OWNER: PRIVATE JETS INC.
ADDRESS: 7200 NW 63RD STREET
BETHANY OK 73008
OFFICE: 405-681-4466
FAX: 405-681-1661

OPERATOR: PRIVATE JETS INC.
ADDRESS: 7200 NW 63RD STREET
BETHANY OK 73008
OFFICE: 405-681-4466
FAX: 405-681-1661

ANALYST: JUSTIN RICE
EMAIL: JRICE@CAMPSYSTEMS.COM

1-866-581-2267 (OFFICE)
+1-631-588-3200 (MAIN)
WWW.CAMPSYSTEMS.COM

800-787-9749 (EFAX-CARDS)
631-980-4222 (EFAX-CARDS)

PLEASE REACH OUT TO YOUR ANALYST TO RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY).

AIRCRAFT

SERIAL/REGNO: 14501007/N317PJ MODEL: EMB-135BJ - LEGACY 600 MANUFACTURER: EMBRAER

CERTIFICATION DATE: 27-AUG-2007

LAST ACTUALS:

11276.3	A/C HRS	as of 26-MAY-2026
6025	AFL	as of 26-MAY-2026
6098	APH	as of 27-APR-2026

APU

SERIAL/PART: SP-E0614882/4504113A MODEL: T-62T-40C14 MANUFACTURER: PRATT & WHITNEY CANADA CORP.

INSTALLED ON: 10-FEB-2017

2952.1	APU HRS	8094.9 A/C HRS
2686	APUS	

LAST ACTUALS:

6098	APU HRS	as of 27-APR-2026
5571	APUS	as of 27-APR-2026

ENGINE NO. 1

SERIAL/PART: CAE312988/23074862 MODEL: AE 3007A1E MANUFACTURER: ROLLS-ROYCE DERBY PLC

INSTALLED ON: 25-SEP-2007

0	ENG. HRS	0 A/C HRS
0	ENC	

LAST ACTUALS:

11172.1	ENG. HRS	as of 26-MAY-2026
5953	ENC	as of 26-MAY-2026

ENGINE NO. 2

SERIAL/PART: CAE312989/23074862 MODEL: AE 3007A1E MANUFACTURER: ROLLS-ROYCE DERBY PLC

INSTALLED ON: 25-SEP-2007

0	ENG. HRS	0 A/C HRS
0	ENC	

LAST ACTUALS:

11172.1	ENG. HRS	as of 26-MAY-2026
5953	ENC	as of 26-MAY-2026

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 00 - INFORMATION									
A135-160301		APU - REVIEW T-62T-40C14 EM REV 13							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS	
	HRS								
	APUS								
PROC. REF: RCF A135PROC. REF: RCF A135									
E135-160422		REVIEW EMBRAER 135 (LEGACY 600/650) SMRD-1533, TR 11-2 DATED APRIL 22/16 AND MPG-1483, TR 11-3 DATED APRIL 22/16 - REQUIREMENT CHANGE FORM							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS	
	HRS								
	AFL								
PROC. REF: RCF E135PROC. REF: RCF E135									
E135-160829		REVIEW EMBRAER 135 - LEGACY 600/650 (E135) MISCELLANOUS CORRECTIONS REQUIREMENT SUMMARY CHANGE FORM							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS	
	HRS								
	AFL								
PROC. REF: RCF E135PROC. REF: RCF E135									
E135-200623		REVIEW EMBRAER LEGACY 600/650 MPG AND SMRD TR 14-2 DATED JUNE 23, 2020							Service ATA:00
	MOS/MSC	27-Aug-07	-					REQUIREMENT CHANGE FORMS	
	HRS	0							
	AFL	0							
PROC. REF: RCF 00PROC. REF: RCF 00									
E135-210629-MPG-SMRD		REVIEW LEGACY 600/650 MAINTENANCE PLANNING GIUDE (MPG) AND SCHEDULED MAINTENANCE REQUIREMENTS DOCUMENT (SMRD) REVISION 15, DATED 29 JUNE, 2021							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS	
	HRS								
	AFL								
PROC. REF: RCF 00PROC. REF: RCF 00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 00 - INFORMATION									
E135-220517-CAMP ADJUSTMENT		REVIEW CAMP ADJUSTMENT FORM DATED MAY 17/2022 FOR EMB-135BJ - LEGACY 600/650							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS	
	HRS								
	AFL								
PROC. REF: RCF 00PROC. REF: RCF 00									
E135-220823-CAMP ADJUSTMENT		REVIEW CAMP ADJUSTMENT FORM DATED AUG 23/2022 FOR EMB-135BJ - LEGACY 600/650							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS	
	HRS								
	AFL								
PROC. REF: RCF 00PROC. REF: RCF 00									
E135-220908-CAMP ADJUSTMENT		REVIEW CAMP ADJUSTMENT FORM DATED SEP 08/2022 FOR EMB-135BJ - LEGACY 600/650							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS	
	HRS								
	AFL								
PROC. REF: RCF 00PROC. REF: RCF 00									
E135-230313-MPG-SMRD		REVIEW LEGACY 600/650 MAINTENANCE PLANNING GIUDE (MPG) AND SCHEDULED MAINTENANCE REQUIREMENTS DOCUMENT (SMRD) REVISION 16, DATED MAR 13/2023							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS	
	HRS								
	AFL								
PROC. REF: RCF 00, RCF 00PROC. REF: RCF 00, RCF 00									
E135-230404-TR		REVIEW LEGACY 600/650 MAINTENANCE PLANNING GIUDE (MPG) TEMPORARY REVISION 16-1, DATED 04 APRIL, 2023							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS	
	HRS								
	AFL								
PROC. REF: RCF -PROC. REF: RCF -									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 00 - INFORMATION									
E135-230411-TR		REVIEW LEGACY 600/650 SCHEDULED MAINTENANCE REQUIREMENTS DOCUMENT (SMRD) TEMPORARY REVISION 16-1, DATED 11 APRIL, 2023							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS	
	HRS								
	AFL								
PROC. REF: RCF --PROC. REF: RCF --									
E135-230425-CAMP ADJUSTMENT		REVIEW CAMP ADJUSTMENT FORM DATED APR 25/2023 FOR EMB-135BJ - LEGACY 600/650							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS	
	HRS								
	AFL								
E307-160420		NO. 1 ENGINE - REVIEW AE3007A MM REV 78							Service ATA:00
	MOS/MSC	29-Aug-16	-					REQUIREMENT CHANGE FORMS	
	HRS	7760.1							
	ENC	4148							
PROC. REF: RCF E307PROC. REF: RCF E307									
E307-160420		NO. 2 ENGINE - REVIEW AE3007A MM REV 78							Service ATA:00
	MOS/MSC	29-Aug-16	-					REQUIREMENT CHANGE FORMS	
	HRS	7760.1							
	ENC	4148							
PROC. REF: RCF E307PROC. REF: RCF E307									
E307-160720		NO. 1 ENGINE - REVIEW AE3700A MM REV 79							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS	
	HRS								
	ENC								
PROC. REF: RCF E307PROC. REF: RCF E307									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 00 - INFORMATION									
E307-160720		NO. 2 ENGINE - REVIEW AE3700A MM REV 79							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS	
	HRS								
	ENC								
PROC. REF: RCF E307PROC. REF: RCF E307									
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
05-LU06		LOW UTILIZATION-LU6							Package ATA:05
	MOS/MSC	14-Jan-21	N/A	Adj -15d					
	HRS	9507.9							
	AFL	5060							
									PKG:5001
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
05-LU12		LOW UTILIZATION-LU12							Package ATA:05
	MOS	17-Oct-25	12 (+15d/-15d)	Adj -62d	16-Aug-26	31-Aug-26	82 d (+15)	LOW UTILIZATION	
	HRS	10913.9	500 (+20/-20)		11413.9	11433.9	137.6 (+20)		
	AFL	5820							
									PKG:5002
PROC. REF: SMRD SECTION IIPROC. REF: SMRD SECTION II									
05-LU24		LOW UTILIZATION-LU24							Package ATA:05
	MOS	17-Oct-25	24 (+15d/-15d)	Adj -80d	29-Jul-27	13-Aug-27	429 d (+15)	LOW UTILIZATION	
	HRS	10913.9	1000 (+20/-20)		11913.9	11933.9	637.6 (+20)		
	AFL	5820							
									PKG:5004
PROC. REF: SMRD SECTION IIPROC. REF: SMRD SECTION II									
05-LU24T96		THRESHOLD 96 MOS LOW UTILIZATION-LU24							Package ATA:05
	MOS	17-Oct-25	24 (+15d/-15d)	Adj -80d	29-Jul-27	13-Aug-27	429 d (+15)	LOW UTILIZATION	
	HRS	10913.9	1000 (+20/-20)		11913.9	11933.9	637.6 (+20)		
	AFL	5820							
									PKG:5007
PROC. REF: SMRD SECTION IIPROC. REF: SMRD SECTION II									

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
05-LU48		LOW UTILIZATION-LU48						Package	ATA:05
	MOS	29-Jun-23	48 (+15d/-15d)		29-Jun-27	14-Jul-27	399 d (+15)	LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)		12161.5	12181.5	885.2 (+20)		
	AFL	5401	1000 (+20/-20)		6401	6421	376 (+20)		
									PKG:5008
PROC. REF: SMRD SECTION IIPROC. REF: SMRD SECTION II									
05-LU48T96		THRESHOLD 96 MOS LOW UTILIZATION-LU48						Package	ATA:05
	MOS	29-Jun-23	48 (+15d/-15d)		29-Jun-27	14-Jul-27	399 d (+15)	LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)		12161.5	12181.5	885.2 (+20)		
	AFL	5401	1000 (+20/-20)		6401	6421	376 (+20)		
									PKG:5009
PROC. REF: SMRD SECTION IIPROC. REF: SMRD SECTION II									
05-LU48T192		THRESHOLD 192 MOS LOW UTILIZATION-LU48						Package	ATA:05
	MOS	29-Jun-23	48 (+15d/-15d)		29-Jun-27	14-Jul-27	399 d (+15)	LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)		12161.5	12181.5	885.2 (+20)		
	AFL	5401	1000 (+20/-20)		6401	6421	376 (+20)		
									PKG:5010
PROC. REF: SMRD SECTION IIPROC. REF: SMRD SECTION II									
05-LU48T288		THRESHOLD 288 MOS LOW UTILIZATION-LU48						Package	ATA:05
	MOS	29-Jun-23	48 (+15d/-15d)		29-Jun-27	14-Jul-27	399 d (+15)	LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)		12161.5	12181.5	885.2 (+20)		
	AFL	5401	1000 (+20/-20)		6401	6421	376 (+20)		
									PKG:5011
PROC. REF: SMRD SECTION IIPROC. REF: SMRD SECTION II									
05-LU72		LOW UTILIZATION-LU72						Package	ATA:05
	MOS	17-Oct-25	72 (+15d/-15d)	Adj -51d	27-Aug-31	11-Sep-31	1919 d (+15)	LOW UTILIZATION	
	HRS	10913.9	3000 (+20/-20)		13913.9	13933.9	2637.6 (+20)		
	AFL	5820	1500 (+20/-20)		7320	7340	1295 (+20)		
									PKG:5012
PROC. REF: SMRD SECTION IIPROC. REF: SMRD SECTION II									

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
05-LU96		LOW UTILIZATION-LU96						Package	ATA:05
	MOS	29-Jun-23	96 (+15d/-15d)		29-Jun-31	14-Jul-31	1860 d (+15)	LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)		14161.5	14181.5	2885.2 (+20)		
	AFL	5401	2000 (+20/-20)		7401	7421	1376 (+20)		
									PKG:5016
PROC. REF: SMRD SECTION IIPROC. REF: SMRD SECTION II									
05-LU96T192		THRESHOLD 192 MOS LOW UTILIZATION-LU96						Package	ATA:05
	MOS	29-Jun-23	96 (+15d/-15d)		29-Jun-31	14-Jul-31	1860 d (+15)	LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)		14161.5	14181.5	2885.2 (+20)		
	AFL	5401	2000 (+20/-20)		7401	7421	1376 (+20)		
									PKG:5017
PROC. REF: SMRD SECTION IIPROC. REF: SMRD SECTION II									
05-LU96T288		THRESHOLD 288 MOS LOW UTILIZATION-LU96						Package	ATA:05
	MOS	27-Aug-07	T:288 (+15d/-15d)		27-Aug-31	11-Sep-31	1919 d (+15)	LOW UTILIZATION	
	HRS	0	T:12000 (+20/-20)		12000	12020	723.7 (+20)		
	AFL	0	T:6000 (+20/-20)	Adj 60	6060	6080	35 (+20)		
									PKG:5018
PROC. REF: SMRD SECTION IIPROC. REF: SMRD SECTION II									
05-LU144		LOW UTILIZATION-LU144						Package	ATA:05
	MOS	06-Jul-19	144 (+15d/-15d)	Adj 52d	27-Aug-31	11-Sep-31	1919 d (+15)	LOW UTILIZATION	
	HRS	9057.4	6000 (+20/-20)		15057.4	15077.4	3781.1 (+20)		
	AFL	4853	3000 (+20/-20)		7853	7873	1828 (+20)		
									PKG:5024
PROC. REF: SMRD SECTION IIPROC. REF: SMRD SECTION II									
05-LU144T288		THRESHOLD 288 MOS LOW UTILIZATION-LU144						Package	ATA:05
	MOS	27-Aug-07	T:288 (+15d/-15d)		27-Aug-31	11-Sep-31	1919 d (+15)	LOW UTILIZATION	
	HRS	0	T:12000 (+20/-20)		12000	12020	723.7 (+20)		
	AFL	0	T:6000 (+20/-20)	Adj 60	6060	6080	35 (+20)		
									PKG:5025
PROC. REF: SMRD SECTION IIPROC. REF: SMRD SECTION II									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
05-LU192		LOW UTILIZATION-LU192						Package	ATA:05
	MOS	02-Jul-15	192 (+15d/-15d)	Adj 56d	27-Aug-31	11-Sep-31	1919 d (+15)	LOW UTILIZATION	
	HRS	7460.3	8000 (+20/-20)		15460.3	15480.3	4184 (+20)		
	AFL	3992	4000 (+20/-20)		7992	8012	1967 (+20)		
									PKG:5032
PROC. REF: SMRD SECTION IIPROC. REF: SMRD SECTION II									
05-LU288		LOW UTILIZATION-LU288						Package	ATA:05
	MOS	27-Aug-07	288 (+15d/-15d)		27-Aug-31	11-Sep-31	1919 d (+15)	LOW UTILIZATION	
	HRS	0	12000 (+20/-20)		12000	12020	723.7 (+20)		
	AFL	0	6000 (+20/-20)	Adj 60	6060	6080	35 (+20)		
									PKG:5140
PROC. REF: SMRD SECTION IIPROC. REF: SMRD SECTION II									
05-00-CUS-1000 U		PERFORM ANNUAL AVIONICS RAMP CHECK						Service	ATA:05
	MOS	17-Oct-25	12		17-Oct-26		144 d	CUSTOMER CODE	
	HRS	10913.9							
	AFL	5820							
05-00-CUS-1004 U		RENEW AIRCRAFT REGISTRATION						Service	ATA:05
	MOS	25-Jan-24	36 (+1m/-2m)		25-Jan-27	25-Feb-27	244 d (+31)		
	HRS								
	AFL								
05-00-CUS-1005 U		RENEW ELT REGISTRATION						Service	ATA:05
	MOS	13-Jan-25	24		14-Jan-27 (M)		233 d		
	HRS	10663.7							
	AFL	5675							
			Expiry Date: : 14-Jan-27						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
05-50-01-200-801	LIGHTNING STRIKE - GENERAL INSPECTION							Service	ATA:05
	MOS/MSC	27-Aug-07	A/R						
	HRS	0							
	AFL	0							
PROC. REF: AMM 05-50-01	PROC. REF: AMM 05-50-01								
05-50-01-200-802	FORWARD FUSELAGE AND NOSE LANDINGGEAR - DETAILED INSPECTION							Service	ATA:05
	MOS/MSC	27-Aug-07	A/R						
	HRS	0							
	AFL	0							
PROC. REF: AMM 05-50-01	PROC. REF: AMM 05-50-01								
05-50-01-200-803	CENTER FUSELAGE MAIN LANDINGGEARS AND WING STUB - INSPECTION							Service	ATA:05
	MOS/MSC	27-Aug-07	A/R						
	HRS	0							
	AFL	0							
PROC. REF: AMM 05-50-01	PROC. REF: AMM 05-50-01								
05-50-01-200-804	WINGS - DETAILED INSPECTION							Service	ATA:05
	MOS/MSC	27-Aug-07	A/R						
	HRS	0							
	AFL	0							
PROC. REF: AMM 05-50-01	PROC. REF: AMM 05-50-01								
05-50-01-200-805	ENGINE NACELLE - DETAILED INSPECTION							Service	ATA:05
	MOS/MSC	27-Aug-07	A/R						
	HRS	0							
	AFL	0							
PROC. REF: AMM 05-50-01	PROC. REF: AMM 05-50-01								
05-50-01-200-806	REAR FUSELAGE AND EMPENNAGE -DETAILED INSPECTION							Service	ATA:05
	MOS/MSC	27-Aug-07	A/R						
	HRS	0							
	AFL	0							
PROC. REF: AMM 05-50-01	PROC. REF: AMM 05-50-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
05-50-02-200-801		OVERWEIGHT LANDING OR HARDLANDING						Service	ATA:05
	MOS/MSC	27-Aug-07	A/R						
	HRS	0							
	AFL	0							
PROC. REF: AMM 05-50-02	PROC. REF: AMM 05-50-02								
05-50-03-200-801		HIGH DRAG/SIDE LOAD LANDING CONDITION						Service	ATA:05
	MOS/MSC	27-Aug-07	A/R						
	HRS	0							
	AFL	0							
PROC. REF: AMM 05-50-03	PROC. REF: AMM 05-50-03								
05-50-04-200-801		OVERSPEED INSPECTION						Service	ATA:05
	MOS/MSC	27-Aug-07	A/R						
	HRS	0							
	AFL	0							
PROC. REF: AMM 05-50-04	PROC. REF: AMM 05-50-04								
05-50-04-200-802		ON-GROUND GALE-FORCE WINDS						Service	ATA:05
	MOS/MSC	27-Aug-07	A/R						
	HRS	0							
	AFL	0							
PROC. REF: AMM 05-50-04	PROC. REF: AMM 05-50-04								
05-50-04-200-803		SEVERE TURBULENCE OR BUFFETINGCONDITION						Service	ATA:05
	MOS/MSC	27-Aug-07	A/R						
	HRS	0							
	AFL	0							
PROC. REF: AMM 05-50-04	PROC. REF: AMM 05-50-04								
05-50-05-200-801		HIGH-LOAD-FACTOR FLIGHT CONDITION						Service	ATA:05
	MOS/MSC	27-Aug-07	A/R						
	HRS	0							
	AFL	0							
PROC. REF: AMM 05-50-05	PROC. REF: AMM 05-50-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
05-50-06-200-801		LANDING GEAR DOWN OVERSPEED							Service ATA:05
	MOS/MSC	27-Aug-07	A/R						
	HRS	0							
	AFL	0							
PROC. REF: AMM 05-50-06	PROC. REF: AMM 05-50-06								
05-50-07-200-801		MAXIMUM FLAP EXTENDED SPEED							Service ATA:05
	MOS/MSC	27-Aug-07	A/R						
	HRS	0							
	AFL	0							
PROC. REF: AMM 05-50-07	PROC. REF: AMM 05-50-07								
05-50-08-200-801		BIRD STRIKE AND HAILSTORM							Service ATA:05
	MOS/MSC	27-Aug-07	A/R						
	HRS	0							
	AFL	0							
PROC. REF: AMM 05-50-08	PROC. REF: AMM 05-50-08								
05-50-09-200-801		ENGINE FIRE WARNING							Service ATA:05
	MOS/MSC	27-Aug-07	A/R						
	HRS	0							
	AFL	0							
PROC. REF: AMM 05-50-09	PROC. REF: AMM 05-50-09								
05-50-10-200-801		ICING OR SNOWING INSPECTION							Service ATA:05
	MOS/MSC	27-Aug-07	A/R						
	HRS	0							
	AFL	0							
PROC. REF: AMM 05-50-10	PROC. REF: AMM 05-50-10								
05-50-11-200-801		APU FIRE WARNING							Service ATA:05
	MOS/MSC	27-Aug-07	A/R						
	HRS	0							
	AFL	0							
PROC. REF: AMM 05-50-11	PROC. REF: AMM 05-50-11								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
05-50-12-100-801		TOILET OVERSERVICING - CLEANING						Service	ATA:05
	MOS/MSC	27-Aug-07	A/R						
	HRS	0							
	AFL	0							
PROC. REF: AMM 05-50-12	PROC. REF: AMM 05-50-12								
05-50-12-200-801		TOILET OVERSERVICING - INSPECTION						Service	ATA:05
	MOS/MSC	27-Aug-07	A/R						
	HRS	0							
	AFL	0							
PROC. REF: AMM 05-50-12	PROC. REF: AMM 05-50-12								
05-50-13-700-801		AIRCRAFT RECONFIGURATION - CHECK						Service	ATA:05
	MOS/MSC	27-Aug-07	A/R						
	HRS	0							
	AFL	0							
PROC. REF: AMM 05-50-13	PROC. REF: AMM 05-50-13								
05-50-14-200-801		OVERHEAT WHEELS						Service	ATA:05
	MOS/MSC	27-Aug-07	A/R						
	HRS	0							
	AFL	0							
PROC. REF: AMM 05-50-14	PROC. REF: AMM 05-50-14								
05-50-15-200-801		LANDING-GEAR TIRE TREAD FAILURE -EXTENDED LANDING GEAR						Service	ATA:05
	MOS/MSC	27-Aug-07	A/R						
	HRS	0							
	AFL	0							
PROC. REF: AMM 05-50-15	PROC. REF: AMM 05-50-15								
05-50-15-200-802		LANDING-GEAR TIRE TREAD FAILURE -RETRACTED LANDING GEAR						Service	ATA:05
	MOS/MSC	27-Aug-07	A/R						
	HRS	0							
	AFL	0							
PROC. REF: AMM 05-50-15	PROC. REF: AMM 05-50-15								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
05-50-16-200-801	HIGH ENERGY STOP - INSPECTION							Service	ATA:05
	MOS/MSC	27-Aug-07	A/R						
	HRS	0							
	AFL	0							
PROC. REF: AMM 05-50-16	PROC. REF: AMM 05-50-16								
05-50-18-200-801	VOLCANIC ASH CONDITION							Service	ATA:05
	MOS/MSC	27-Aug-07	A/R						
	HRS	0							
	AFL	0							
PROC. REF: AMM 05-50-18	PROC. REF: AMM 05-50-18								
05-50-19-960-801	APU FUEL INLET FILTER - INSPECTION							Service	ATA:05
	MOS/MSC	27-Aug-07	A/R						
	HRS	0							
	AFL	0							
PROC. REF: AMM 05-50-19	PROC. REF: AMM 05-50-19								
05-50-20-200-801	FORWARD POCKET DOOR RESETTING -INSPECTION							Service	ATA:05
	MOS/MSC	27-Aug-07	A/R						
	HRS	0							
	AFL	0							
PROC. REF: AMM 05-50-20	PROC. REF: AMM 05-50-20								
05-50-23-200-801	BRAKE USE DURING TOWBARLESSTOWING OPERATION							Service	ATA:05
	MOS/MSC	27-Aug-07	A/R						
	HRS	0							
	AFL	0							
PROC. REF: AMM 05-50-23	PROC. REF: AMM 05-50-23								
05-50-24-200-801	LH/RH STATIC PORTS VICINITY - INSPECTION							Service	ATA:05
	MOS/MSC	27-Aug-07	A/R						
	HRS	0							
	AFL	0							
PROC. REF: AMM 05-50-24	PROC. REF: AMM 05-50-24								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
05-50-32-200-801		OVERSTEERING - GENERAL VISUAL INSPECTION							Service ATA:05
	MOS/MSC	27-Aug-07	A/R						
	HRS	0							
	AFL	0							
PROC. REF: AMM 05-50-32PROC. REF: AMM 05-50-32									
055013		NO. 1 ENGINE - FLUSH THE ENGINE AFTER A FIRE-EXTINGUISHING AGENT DISCHARGE							Service ATA:05
	MOS/MSC	25-Sep-07	A/R						
	HRS	0							
	ENC	0							
PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00									
055013		NO. 2 ENGINE - FLUSH THE ENGINE AFTER A FIRE-EXTINGUISHING AGENT DISCHARGE							Service ATA:05
	MOS/MSC	25-Sep-07	A/R						
	HRS	0							
	ENC	0							
PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00									
MRA-003344 U		PERFORM INSPECTION FOR THE ROSEN LCD CABIN BULKHEAD MONITORS							Service ATA:05
	MOS	10-Dec-24	72		10-Dec-30		1659 d	CUSTOMER CODE	
	HRS	10605.1							
	AFL	5653							
ATA 08 - LEVELING AND WEIGHING									
08051910 U		WEIGHT AND BALANCE AIRCRAFT							Service ATA:08
	MOS	28-May-25	36		28-May-28		733 d		
	HRS	10795.9							
	AFL	5750							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 10 - PARKING, MOORING, STORE AND RET TO SERV									
10-10-02-500-801-A [U]		PERFORM AIRCRAFT PROLONGED PARKING							Service ATA:10
	MOS/MSC		A/R						
	HRS								
	AFL								
10-10-02-500-802-A [U]		PERFORM AIRCRAFT RETURN TO SERVICE AFTER PROLONGED PARKING							Service ATA:10
	MOS/MSC		A/R						
	HRS								
	AFL								
ATA 12 - SERVICING									
12-13-01-610-001-A00		SERVICE (REPLENISH) HYDRAULIC SYSTEM RESERVOIR							Service ATA:12
	MOS/MSC	12-May-25	O/C						
	HRS	10787.2							
	AFL	5746							
PROC. REF: AMM 12-13-01PROC. REF: AMM 12-13-01									
ATA 20 - STANDARD PRACTICES - AIRFRAME									
20-00-00-140-002-A00		RESTORE (CLEANING) CENTER FUSELAGE III LOWER SIDE INCLUDING WIRING, LINES AND OMEGA BEAMS (ZONES: 151, 152, 153, 154, 155, 156, 157).NOTE: EWIS (L650 ONLY)							Service ATA:20
	MOS/MSC	25-Sep-07	N/A					SYSTEM	
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: AMM 05-40-01PROC. REF: AMM 05-40-01									
20-00-00-140-003-A00		RESTORE (CLEANING) CENTER FUSELAGE IV LOWER SIDE INCLUDING WIRING, LINES AND OMEGA BEAMS (ZONES: 161, 162).NOTE: EWIS (L650 ONLY)							Service ATA:20
	MOS/MSC	25-Sep-07	N/A					SYSTEM	
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: AMM 05-40-02PROC. REF: AMM 05-40-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 20 - STANDARD PRACTICES - AIRFRAME									
20-00-00-140-004-A00		RESTORE (CLEANING) CENTER FUSELAGE IV UPPER AND LATERAL SIDE INCLUDING ELT UNIT (ZONES: 262, 263, 264).NOTE: EWIS. (L650 ONLY)						Service	ATA:20
	MOS/MSC	25-Sep-07	N/A				SYSTEM		
	HRS	0							
	AFL	0							
									PKG:6032
PROC. REF: AMM 05-40-03PROC. REF: AMM 05-40-03									
20-00-00-140-005-A00 S		RESTORE (CLEANING) REAR FUSELAGE I LOWER SIDE, INCLUDING WIRING AND LINES (ZONES: 171, 172).NOTE: EWIS .(L650 ONLY)						Service	ATA:20
	MOS/MSC	25-Sep-07	N/A				SYSTEM		
	HRS	0							
	AFL	0							
									PKG:5016,6032
PROC. REF: AMM 05-40-04PROC. REF: AMM 05-40-04									
20-00-00-140-006-A00 S		RESTORE (CLEANING) REAR FUSELAGE I LATERAL SIDE, INCLUDING ELECTRONIC REAR COMPARTMENT WIRING (ZONES: 271, 272).NOTE: EWIS.(L650 ONLY)						Service	ATA:20
	MOS/MSC	25-Sep-07	N/A				SYSTEM		
	HRS	0							
	AFL	0							
									PKG:5016,6032
PROC. REF: AMM 05-40-05PROC. REF: AMM 05-40-05									
20-00-00-140-007-A00		RESTORE (CLEANING) CENTER FUSELAGE II LOWER SIDE INCLUDING WIRING, LINES AND OMEGA BEAMS (ZONES: 141, 142). NOTE: EWIS (L650 ONLY)						Service	ATA:20
	MOS/MSC	25-Sep-07	N/A				SYSTEM		
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: AMM 05-40-10PROC. REF: AMM 05-40-10									
20-00-00-140-008-A00		RESTORE (CLEANING) CENTER FUSELAGE I LOWER SIDE INCLUDING WIRING, LINES AND OMEGA BEAMS (ZONES: 131, 132). NOTE: EWIS (L650 ONLY)						Service	ATA:20
	MOS/MSC	25-Sep-07	N/A				SYSTEM		
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: AMM 05-40-14PROC. REF: AMM 05-40-14									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 20 - STANDARD PRACTICES - AIRFRAME									
20-00-00-140-009-A00	RESTORE (CLEANING) NLG & FWD ELECTRONIC COMPARTMENTS, FWDPRESSURE BULKHEAD UPPER SIDE (ZONES: 113, 114,213, 214, 215, 216).NOTE: EWIS.(L650 ONLY)							Service	ATA:20
	MOS/MSC	25-Sep-07	N/A				SYSTEM		
	HRS	0							
	AFL	0							
									PKG:6032
PROC. REF: AMM 05-40-11PROC. REF: AMM 05-40-11									
20-00-00-140-010-A00	RESTORE (CLEANING) COCKPIT LATERAL SIDE AND FWD PRESSURE BULKHEAD UPPER SIDE (ZONES: 221, 222, 223, 224). NOTE: EWIS (L650 ONLY)							Service	ATA:20
	MOS/MSC	25-Sep-07	N/A				SYSTEM		
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: AMM 05-40-13PROC. REF: AMM 05-40-13									
20-00-00-140-011-A00	RESTORE (CLEANING) COCKPIT LOWER SIDE AND FWD PRESSURE BULKHEAD LOWER SIDE (ZONES: 121, 122, 123, 124) NOTE: EWIS (L650 ONLY)							Service	ATA:20
	MOS/MSC	25-Sep-07	N/A				SYSTEM		
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: AMM 05-40-12PROC. REF: AMM 05-40-12									
20-00-00-212-002-A00	INSPECT (GENERAL VISUAL) CENTER FUSELAGE III LOWER SIDE - EWIS COMPONENTS OF APU AND ENGINES GENERATORS POWER CABLES, HYDRAULIC PUMPS POWER CABLES AND WIRING BUNDLES (ZONES: 151, 152, 153,154, 155, 156, 157).NOTE: EWIS (L650 ONLY)							Service	ATA:20
	MOS/MSC	25-Sep-07	N/A				SYSTEM		
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: AMM 05-40-01PROC. REF: AMM 05-40-01									
20-00-00-212-003-A00	INSPECT (GENERAL VISUAL) CENTER FUSELAGE IV LOWER SIDE - EWIS COMPONENTS OF APU AND ENGINES GENERATORS POWER CABLES, HYDRAULIC PUMPS POWER CABLES AND WIRING BUNDLES (ZONES: 161, 162). NOTE: EWIS (L650 ONLY)							Service	ATA:20
	MOS/MSC	25-Sep-07	N/A				SYSTEM		
	HRS	0							
	AFL	0							
									PKG:6016

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 20 - STANDARD PRACTICES - AIRFRAME									
PROC. REF: AMM 05-40-02PROC. REF: AMM 05-40-02									
20-00-00-212-007-A00	INSPECT (GENERAL VISUAL) REAR FUSELAGE I, PRESSURE BULKHEAD PRESSURIZED AREA SIDE - EWIS COMPONENTS OF APU POWER CABLES AND WIRING BUNDLES (ZONES: 275, 276NOTE: EWIS).(L650 ONLY)								Service ATA:20
	MOS/MSC	25-Sep-07	N/A					SYSTEM	
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: AMM 05-40-07PROC. REF: AMM 05-40-07									
20-00-00-212-008-A00	INSPECT (GENERAL VISUAL) REAR FUSELAGE II, STRUCTURAL AREA AFT OF REAR PRESSURE BULKHEAD - EWIS COMPONENTS OF POWER CABLES AND WIRING BUNDLES (ZONES: 311, 312).NOTE: EWIS (L650 ONLY)								Service ATA:20
	MOS/MSC	25-Sep-07	N/A					SYSTEM	
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: AMM 05-40-08PROC. REF: AMM 05-40-08									
20-00-00-212-011-A00	INSPECT (GENERAL VISUAL) FWD AUXILIARY FUEL TANK FAIRINGS, VENTRAL FUEL TANK FAIRINGS AND WING-TO- FUSELAGE ATTACHMENT FAIRINGS - EWIS COMPONENTS OF WIRING BUNDLES (ZONES: 191, 193, 194, 195, 196,1924 AND 1932)NOTE: EWIS (L650 ONLY)								Service ATA:20
	MOS/MSC	25-Sep-07	N/A					SYSTEM	
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: AMM 05-40-09PROC. REF: AMM 05-40-09									
20-00-00-212-012-A00	INSPECT (GENERAL VISUAL) NLG ELECTRONIC COMPARTMENT - EWIS COMPONENTS OF WIRING BUNDLES (ZONES: 113, 114).NOTE: EWIS.(L650 ONLY)								Service ATA:20
	MOS/MSC	25-Sep-07	N/A					SYSTEM	
	HRS	0							
	AFL	0							
									PKG:6032
PROC. REF: AMM 05-40-11PROC. REF: AMM 05-40-11									

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 20 - STANDARD PRACTICES - AIRFRAME									
20-00-00-212-013-A00	INSPECT (GENERAL VISUAL) ENGINE PYLON - EWIS COMPONENTS OF ENGINES GENERATORS POWER CABLES AND WIRING BUNDLES (ZONES: 414, 424). NOTE: EWIS (L650 ONLY)							Service	ATA:20
	MOS/MSC	25-Sep-07	N/A				SYSTEM		
	HRS	0							
	AFL	0							
PROC. REF: AMM 05-40-15	PROC. REF: AMM 05-40-15								
20-00-00-212-014-A00	INSPECT (GENERAL VISUAL) ENGINES - EWIS COMPONENTS OF ENGINES GENERATORS POWER CABLES (ZONES: 415, 425).NOTE: EWIS (L650 ONLY)							Service	ATA:20
	MOS/MSC	25-Sep-07	N/A				SYSTEM		
	HRS	0							
	AFL	0							
PROC. REF: AMM 05-40-18	PROC. REF: AMM 05-40-18								
20-00-00-212-015-A00	INSPECT (GENERAL VISUAL) WING LEADING EDGE - EWIS COMPONENTS OF WIRING BUNDLES (ZONES: 511, 512,513, 611, 612, 613). NOTE: EWIS (L650 ONLY)							Service	ATA:20
	MOS/MSC	25-Sep-07	N/A				SYSTEM		
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: AMM 24-00-02	PROC. REF: AMM 24-00-02								
20-00-00-212-016-A00	INSPECT (GENERAL VISUAL) EWIS COMPONENTS OFTRAILING EDGE HARNESS (ZONES: 532, 5711, 5721,5731, 5732, 632, 6711, 6721, 6731, 6732).NOTE: EWIS (L650 ONLY)							Service	ATA:20
	MOS/MSC	25-Sep-07	N/A				SYSTEM		
	HRS	0							
	AFL	0							
PROC. REF: AMM 24-00-03	PROC. REF: AMM 24-00-03								
20-00-00-212-017-A00	INSPECT (GENERAL VISUAL) WING STUB HARNESS - EWIS COMPONENTS OF WIRING BUNDLES (ZONE 192).NOTE: EWIS (L650 ONLY)							Service	ATA:20
	MOS/MSC	25-Sep-07	N/A				SYSTEM		
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: AMM 24-00-04	PROC. REF: AMM 24-00-04								

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 20 - STANDARD PRACTICES - AIRFRAME									
20-00-00-212-018-A00 S	INSPECT (GENERAL VISUAL) REAR FUSELAGE I LOWER SIDE- EWIS COMPONENTS OF APU AND ENGINES GENERATORS POWER CABLES, HYDRAULIC PUMPS POWER CABLES AND WIRING BUNDLES (ZONES: 171, 172). NOTE: EWIS (L650 ONLY)								Service ATA:20
	MOS/MSC	25-Sep-07	N/A					SYSTEM	
	HRS	0							
	AFL	0							
									PKG:5016,6032
PROC. REF: AMM 05-40-04PROC. REF: AMM 05-40-04									
20-00-00-212-019-A00 S	INSPECT (GENERAL VISUAL) REAR FUSELAGE I LATERAL SIDE- EWIS COMPONENTS OF ENGINES GENERATORS POWER CABLES AND WIRING BUNDLES (ZONES: 271, 272). NOTE: EWIS (L650 ONLY)								Service ATA:20
	MOS/MSC	25-Sep-07	N/A					SYSTEM	
	HRS	0							
	AFL	0							
									PKG:5016,6032
PROC. REF: AMM 05-40-05PROC. REF: AMM 05-40-05									
20-00-00-220-001-A00	INSPECT (DETAILED INSPECTION) EWIS COMPONENTS OFWING TANK UNIT HARNESS (ZONES: 155, 156, 157,531, 631, 541, 641).NOTE: EWIS (L650 ONLY)								Service ATA:20
	MOS/MSC	25-Sep-07	N/A					SYSTEM	
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: AMM 28-41-03PROC. REF: AMM 28-41-03									
20-00-00-220-003-A00	INSPECT (DETAILED INSPECTION) ELECTRIC FUEL PUMPCONNECTOR (ZONES: 155, 156, 157, 531, 631).NOTE: EWIS (L650 ONLY)								Service ATA:20
	MOS/MSC	25-Sep-07	N/A					SYSTEM	
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: AMM 28-21-01PROC. REF: AMM 28-21-01									
20-00-00-220-006-A00	INSPECT (DETAILED INSPECTION) VENTRAL FUEL TANK - EWIS COMPONENTS OF VENTRAL TANK UNIT HARNESS (ZONE: 1972).NOTE: (L650 ONLY)								Service ATA:20
	MOS/MSC	25-Sep-07	N/A					SYSTEM	
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: AMM 28-41-06PROC. REF: AMM 28-41-06									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 20 - STANDARD PRACTICES - AIRFRAME									
20-00-00-220-008-A00		INSPECT (DETAILED INSPECTION) WING MIDDLE SECTION - EWIS COMPONENTS OF VENT VALVE HARNESS INSIDE THE CONDUIT (ZONES: 541, 641).NOTE: EWIS (L650 ONLY)							Service ATA:20
	MOS/MSC	25-Sep-07	N/A					SYSTEM	
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: AMM 28-23-04PROC. REF: AMM 28-23-04									
20-00-00-220-009-A00		INSPECT (DETAILED INSPECTION) FWD ELECTRONIC COMPARTMENT/ FWD PRESSURE BULKHEAD UPPER SIDE - EWIS COMPONENTS OF WIRING BUNDLES (ZONES: 213,214, 215, 216).NOTE: EWIS.(L650 ONLY)							Service ATA:20
	MOS/MSC	25-Sep-07	N/A					SYSTEM	
	HRS	0							
	AFL	0							
									PKG:6032
PROC. REF: AMM 05-40-11, AMM 05-40-11PROC. REF: AMM 05-40-11, AMM 05-40-11									
20-00-00-220-010-A00		INSPECT (DETAILED INSPECTION) COCKPIT LOWER SIDE - EWIS COMPONENTS OF POWER CABLES AND WIRING BUNDLES (ZONES: 123, 124).NOTE: EWIS (L650 ONLY)							Service ATA:20
	MOS/MSC	25-Sep-07	N/A					SYSTEM	
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: AMM 05-40-12PROC. REF: AMM 05-40-12									
20-00-00-220-011-A00		INSPECT (DETAILED INSPECTION) COCKPIT LATERAL SIDE - EWIS COMPONENTS OF POWER CABLES AND BACK SIDE OF THE RELAY SUPPORT PANEL (ZONES: 223, 224), (ZONES: 223, 224).NOTE: EWIS (L650 ONLY)							Service ATA:20
	MOS/MSC	25-Sep-07	N/A					SYSTEM	
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: AMM 05-40-13PROC. REF: AMM 05-40-13									
20-00-00-220-012-A00		INSPECT (DETAILED INSPECTION) CENTER FUSELAGE I LOWER SIDE - EWIS COMPONENTS OF APU AND ENGINES GENERATORS POWER CABLES, HYDRAULIC PUMPS POWER CABLES AND WIRING BUNDLES (ZONES: 131, 132). NOTE: EWIS (L650 ONLY)							Service ATA:20
	MOS/MSC	25-Sep-07	N/A					SYSTEM	
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: AMM 05-40-14PROC. REF: AMM 05-40-14									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 20 - STANDARD PRACTICES - AIRFRAME									
20-00-00-220-013-A00	INSPECT (DETAILED INSPECTION) CENTER FUSELAGE II LOWER SIDE - EWIS COMPONENTS OF APU AND ENGINES GENERATORS POWER CABLES, HYDRAULIC PUMPS POWER CABLES AND WIRING BUNDLES (ZONES: 141, 142). NOTE: EWIS (L650 ONLY)							Service	ATA:20
	MOS/MSC	25-Sep-07	N/A				SYSTEM		
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: AMM 05-40-10PROC. REF: AMM 05-40-10									
20-00-00-220-014-A00	INSPECT (DETAILED INSPECTION) AFT FUEL TANK - EWIS COMPONENTS OF AFT FUEL TANK UNITS HARNESS (ZONES271, 272)NOTE: EWIS (L650 ONLY)							Service	ATA:20
	MOS/MSC	25-Sep-07	N/A				SYSTEM		
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: AMM 28-46-02PROC. REF: AMM 28-46-02									
20-00-00-220-015-A00	INSPECT (DETAILED INSPECTION) FUEL PUMP ELECTRICALHARNESS (ZONES 155, 156, 157).NOTE: EWIS (L650 ONLY)							Service	ATA:20
	MOS/MSC	25-Sep-07	N/A				SYSTEM		
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: AMM 28-21-01PROC. REF: AMM 28-21-01									
20-00-00-220-017-A00	INSPECT (DETAILED INSPECTION) EWIS COMPONENTS OFFWD FUEL TANK UNIT HARNESS (ZONE 197).NOTE: EWIS (L650 ONLY)							Service	ATA:20
	MOS/MSC	25-Sep-07	N/A				SYSTEM		
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: AMM 28-46-04PROC. REF: AMM 28-46-04									
20-00-00-220-019-A00	INSPECT (DETAILED INSPECTION) EWIS COMPONENTS OFW1642 INTRINSICALLY SAFE HARNESS (ZONES 123, 124,131, 132, 141, 142, 151, 152, 153, 154, 161, 162,171, 172, 271).NOTE: EWIS (L650 ONLY)							Service	ATA:20
	MOS/MSC	25-Sep-07	N/A				SYSTEM		
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: AMM 28-41-00PROC. REF: AMM 28-41-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
21-20-00-710-001-A00 S	OPERATIONALLY CHECK CONDITIONED AIR DISTRIBUTION SYSTEM							Service	ATA:21
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: AMM 21-20-00PROC. REF: AMM 21-20-00									
21-21-00-720-001-A00 S	FUNCTIONALLY CHECK DISPLAY VENTILATION SYSTEM							Service	ATA:21
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 21-21-00PROC. REF: AMM 21-21-00									
21-25-01-211-001-A00 S	VISUALLY CHECK FLAP OF RAM AIR VALVE							Service	ATA:21
	MOS	17-Oct-25	24 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	1000 (+20/-20)						
	AFL	5820							
									PKG:5004
PROC. REF: AMM 21-25-01PROC. REF: AMM 21-25-01									
21-25-01-710-001-A00 S	OPERATIONALLY CHECK RAM AIR VALVE							Service	ATA:21
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 21-25-01PROC. REF: AMM 21-25-01									
21-26-00-710-001-A00 S	OPERATIONALLY CHECK ELECTRONIC COMPARTMENT VENTILATION SYSTEM							Service	ATA:21
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 21-26-00PROC. REF: AMM 21-26-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
21-26-08-960-001-A01	DISCARD EXHAUST HOSES OF THE ELECTRONIC BAY COMPARTMENT							Service	ATA:21
	MOS	15-Aug-13	180 (+30d/-30d)		15-Aug-28	14-Sep-28	812 d (+30)	SYSTEM	
	HRS	6643.4							
	AFL	3572							
PROC. REF: AMM 21-26-08PROC. REF: AMM 21-26-08									
21-27-00-710-001-A00 S	OPERATIONAL CHECK BAGGAGE COMPARTMENT VENTILATION SYSTEM (INCLUDING HIGH AND LOW SPEED OF FAN)							Service	ATA:21
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008
PROC. REF: AMM 21-27-00PROC. REF: AMM 21-27-00									
21-27-02-640-001-A00 S	LUBRICATE BAGGAGE COMPARTMENT CHECK VALVES							Service	ATA:21
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 21-27-02PROC. REF: AMM 21-27-02									
21-27-02-710-001-A00 S	OPERATIONALLY CHECK BAGGAGE COMPARTMENT CHECK VALVE (MANUAL CHECK FOR FREE MOVEMENT AND CORRECTED SEATING)							Service	ATA:21
	MOS	17-Oct-25	24 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	1000 (+20/-20)						
	AFL	5820							
									PKG:5004
PROC. REF: AMM 21-27-02PROC. REF: AMM 21-27-02									
21-31-00-710-001-A00 S	OPERATIONALLY CHECK PRESSURIZATION CONTROL SYSTEM IN MANUAL MODE							Service	ATA:21
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: AMM 21-31-00PROC. REF: AMM 21-31-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
21-31-00-720-002-A00 S	FUNCTIONALLY CHECK OUTFLOW VALVES PRESSURE RELIEF DEVICES							Service	ATA:21
	MOS	06-Jul-19	144 (+15d/-15d)					LOW UTILIZATION	
	HRS	9057.4	6000 (+20/-20)						
	AFL	4853	3000 (+20/-20)						
									PKG:5024,6020
PROC. REF: AMM 21-31-00, AMM 21-31-00PROC. REF: AMM 21-31-00, AMM 21-31-00									
21-31-00-720-005-A00 S	FUNCTIONALLY CHECK LINE FOR LEAKAGE							Service	ATA:21
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: AMM 21-31-00PROC. REF: AMM 21-31-00									
21-31-03-140-001-A00 S	RESTORE (CLEANING) ELECTROPNEUMATIC OUTFLOW VALVE (NON-SMOKING FLIGHTS)							Service	ATA:21
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008
PROC. REF: AMM 21-31-03PROC. REF: AMM 21-31-03									
21-31-03-140-001-A01 S	RESTORE (CLEANING) ELECTROPNEUMATIC OUTFLOW VALVE (SMOKING FLIGHTS)							Service	ATA:21
	MOS	17-Oct-25	24 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	1000 (+20/-20)						
	AFL	5820							
									PKG:5004
PROC. REF: AMM 21-31-03PROC. REF: AMM 21-31-03									
21-31-04-140-001-A00 S	RESTORE (CLEANING) PNEUMATIC OUTFLOW VALVE (NON-SMOKING FLIGHTS)							Service	ATA:21
	MOS	17-Oct-25	24 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	1000 (+20/-20)						
	AFL	5820							
									PKG:5004
PROC. REF: AMM 21-31-04PROC. REF: AMM 21-31-04									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
21-31-04-140-001-A01	RESTORE (CLEANING) PNEUMATIC OUTFLOW VALVE (SMOKING FLIGHTS)								Service ATA:21
	MOS/MSC	18-Aug-18	N/A						
	HRS	8725.1							
	AFL	4681							
PROC. REF: AMM 21-31-04PROC. REF: AMM 21-31-04									
21-31-08-960-001-A00	DISCARD AIR FILTER ELEMENT (NON-SMOKING FLIGHTS)								Service ATA:21
	MOS	17-Mar-22						SYSTEM	
	HRS	9824.2	3200		13024.2		1747.9		
	AFL	5235							
PROC. REF: AMM 21-31-08PROC. REF: AMM 21-31-08									
21-31-08-960-001-A01	DISCARD AIR FILTER ELEMENT (SMOKING FLIGHTS)								Service ATA:21
	MOS/MSC	27-Aug-07	N/A						
	HRS	0							
	AFL	0							
PROC. REF: AMM 21-31-08PROC. REF: AMM 21-31-08									
21-32-01-720-001-A00	FUNCTIONALLY CHECK CABIN PRESSURE ACQUISITION MODULE (CPAM) POST-MOD. S.B.145LEG-00-0007 OR WITH AN EQUIVALENT MODIFICATION FACTORY-INCORPORATED								Service ATA:21
	MOS/MSC	19-Aug-15	N/A					SYSTEM	
	HRS	7460.3							
	AFL	3992							
									PKG:6032
PROC. REF: AMM 21-32-01PROC. REF: AMM 21-32-01									
21-51-00-710-001-A00 S	OPERATIONALLY CHECK COOLING PACK SYSTEM TO VERIFY ECS OFF SIGNAL								Service ATA:21
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 21-51-00PROC. REF: AMM 21-51-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
21-51-00-720-001-A00 S	FUNCTIONALLY CHECK COOLING PACK SYSTEM							Service	ATA:21
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: AMM 21-51-00, AMM 21-51-00PROC. REF: AMM 21-51-00, AMM 21-51-00									
21-51-00-720-003-A00 S	FUNCTIONALLY CHECK PACK DUCT OVERTEMPERATURE PROTECTION							Service	ATA:21
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 21-51-09PROC. REF: AMM 21-51-09									
21-51-01-130-001-A00 S	RESTORE (CLEANING) PACK VALVE FILTER USING ULTRASONIC METHOD							Service	ATA:21
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008
PROC. REF: AMM 21-51-01PROC. REF: AMM 21-51-01									
21-51-02-170-001-A00 S	RESTORE (CLEANING) DUAL HEAT EXCHANGER AND VISUALLY CHECK CONDITION OF CORE.							Service	ATA:21
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6016
PROC. REF: AMM 21-51-02PROC. REF: AMM 21-51-02									
21-51-02-170-002-A00 S	RESTORE (CLEANING) DUAL HEAT EXCHANGER - ON THE AIRCRAFT							Service	ATA:21
	MOS	17-Oct-25	24 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	1000 (+20/-20)						
	AFL	5820							
									PKG:5004
PROC. REF: AMM 21-51-02PROC. REF: AMM 21-51-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
21-51-10-710-001-A00 S	OPERATIONALLY CHECK PACK LEAK SWITCH							Service	ATA:21
	MOS	17-Oct-25	72 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	3000 (+20/-20)						
	AFL	5820	1500 (+20/-20)						
									PKG:5012,6020
PROC. REF: AMM 21-51-10PROC. REF: AMM 21-51-10									
21-51-13-211-001-A00 S	VISUALLY CHECK WATER SPRAY NOZZLES NOTE: EMB-RECOMM							Service	ATA:21
	MOS	17-Oct-25	12 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	500 (+20/-20)						
	AFL	5820							
									PKG:5002
PROC. REF: AMM 21-51-13PROC. REF: AMM 21-51-13									
21-60-00-710-001-A00 S	OPERATIONALLY CHECK TEMPERATURE CONTROL							Service	ATA:21
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: AMM 21-60-00PROC. REF: AMM 21-60-00									
21-60-08-960-001-A00 S	DISCARD TORQUE-MOTOR DUAL-VALVE FILTER							Service	ATA:21
	MOS	14-Jul-15	192 (+15d/-15d)					LOW UTILIZATION	
	HRS	7460.3	8000 (+20/-20)						
	AFL	3992	4000 (+20/-20)						
									PKG:5032,6032
PROC. REF: AMM 21-60-08PROC. REF: AMM 21-60-08									
21-71-01-900-001-A00 S	RESTORE (CLEANING) NO. 1 OZONE/OXYGEN CONVERTER - BLEED SYSTEM							Service	ATA:21
PN:60A523-101	MOS	06-Jul-19	144 (+15d/-15d)					LOW UTILIZATION	
SN:0306-1352	HRS	9057.4	6000 (+20/-20)						
	AFL	4853	3000 (+20/-20)						
									PKG:5024,6020
PROC. REF: AMM 21-70-01PROC. REF: AMM 21-70-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
21-71-01-900-001-A00 S		RESTORE (CLEANING) NO. 2 OZONE/OXYGEN CONVERTER - BLEED SYSTEM							Service ATA:21
PN:60A523-101	MOS	06-Jul-19	144 (+15d/-15d)					LOW UTILIZATION	
SN:011/0338	HRS	9057.4	6000 (+20/-20)						
	AFL	4853	3000 (+20/-20)						
									PKG:5024,6020
PROC. REF: AMM 21-70-01PROC. REF: AMM 21-70-01									
212104-0101		GASPER ASSY-GASPER,AIR CONDITIONING SYS VALVE							Component ATA:21
PN:145-22301-401	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:0000141365	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-23-01PROC. REF: AMM 21-23-01									
212104-0102		LEFT ASSY-GASPER,AIR CONDITIONING SYS VALVE							Component ATA:21
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-23-01PROC. REF: AMM 21-23-01									
212104-0103		RIGHT ASSY-GASPER,AIR CONDITIONING SYS VALVE							Component ATA:21
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-23-01PROC. REF: AMM 21-23-01									
212200-0101		FWD VALVE -DISTRIBUTION,AIR COND SYS,PAX CABIN ASSEMBLY							Component ATA:21
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-22-01PROC. REF: AMM 21-22-01									
212200-0102		AFT VALVE -DISTRIBUTION,AIR COND SYS,PAX CABIN ASSEMBLY							Component ATA:21
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-22-01PROC. REF: AMM 21-22-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
212200-0201	C FLOOR VALVE ASSY							Component	ATA:21
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
212201-0101	C FLOOR VALVE ASSY							Component	ATA:21
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
212300-0101	LEFT RECIRCULATION & GASPER FAN							Component	ATA:21
PN:AE1115A00	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:05148	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-23-03, AMM 21-24-01PROC. REF: AMM 21-23-03, AMM 21-24-01									
212300-0102	GASPER RECIRCULATION & GASPER FAN							Component	ATA:21
PN:AE1115A00	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:05220	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-23-03, AMM 21-24-01PROC. REF: AMM 21-23-03, AMM 21-24-01									
212300-0103	RIGHT RECIRCULATION & GASPER FAN							Component	ATA:21
PN:AE1115A00	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:05222	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-23-03, AMM 21-24-01PROC. REF: AMM 21-23-03, AMM 21-24-01									
212401-0101	LH RECIRCULATION FAN AFT MUFFLER							Component	ATA:21
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-24-02PROC. REF: AMM 21-24-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
212401-0102	RH RECIRCULATION FAN AFT MUFFLER							Component	ATA:21
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-24-02	PROC. REF: AMM 21-24-02								
212500-0101	LEFT ELECTROMECHANICAL LINEAR-FLAPPER VALVE,APU ACTUATOR							Component	ATA:21
PN:SYLC51836-1	MOS/MSC	06-Jul-19	O/C	TSR 3					
SN:060506	HRS	9057.4		TSN 4240, TSR 0					
	AFL	4853		TSN 2002, TSR 0					
PROC. REF: AMM 21-25-03	PROC. REF: AMM 21-25-03								
212500-0102	RIGHT ELECTROMECHANICAL LINEAR-FLAPPER VALVE,APU ACTUATOR							Component	ATA:21
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-25-03	PROC. REF: AMM 21-25-03								
212600-0101	LEFT ACTUATOR LINEAR -ELECTROMECHANICAL,CONTROL GUST LOCK ASSEMBLY							Component	ATA:21
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-26-09	PROC. REF: AMM 21-26-09								
212600-0102	RIGHT ACTUATOR LINEAR -ELECTROMECHANICAL,CONTROL GUST LOCK ASSEMBLY							Component	ATA:21
PN:SYLC53229-3	MOS/MSC	10-Jan-12	O/C						
SN:051101	HRS	5287.4							
	AFL	2805							
PROC. REF: AMM 21-26-09	PROC. REF: AMM 21-26-09								
212600-0103	LH FWR ELECTRONIC COMPARTIMENT FAN							Component	ATA:21
PN:526484	MOS/MSC	26-Jan-15	O/C	TSO 0					
SN:I07181667	HRS	7281.6		TSO 0					
	AFL	3897		TSO 0					
PROC. REF: AMM 21-26-02	PROC. REF: AMM 21-26-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
212600-0104	RH FWR ELECTRONIC COMPARTIMENT FAN							Component	ATA:21
PN:526484	MOS/MSC	26-Jan-15	O/C	TSO 0					
SN:I98289255	HRS	7281.6		TSO 0					
	AFL	3897		TSO 0					
PROC. REF: AMM 21-26-02PROC. REF: AMM 21-26-02									
212600-0201	LH REAR ELECTRONIC COMPARTIMENT FAN							Component	ATA:21
PN:526484	MOS/MSC	27-Jan-13	O/C	TSO 9					
SN:I01101819	HRS	6442.2		TSO 0					
	AFL	3468		TSO 0					
PROC. REF: AMM 21-26-02PROC. REF: AMM 21-26-02									
212600-0202	RH REAR ELECTRONIC COMPARTIMENT FAN							Component	ATA:21
PN:526484	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:106442692	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-26-02PROC. REF: AMM 21-26-02									
212603-0101	NO. 1 NOSE 28 VDC/12 VDC,FAN,ELECTRONIC EQUIPMENT EQUIPMENT,FWD FUSLG INVERTER							Component	ATA:21
PN:524864	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:E07018279	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-26-03PROC. REF: AMM 21-26-03									
212603-0102	NO. 2 NOSE 28 VDC/12 VDC,FAN,ELECTRONIC EQUIPMENT EQUIPMENT,FWD FUSLG INVERTER							Component	ATA:21
PN:524864	MOS/MSC	26-Jan-15	O/C	TSN 0					
SN:E11467053	HRS	7281.6		TSN 0					
	AFL	3897		TSN 0					
PROC. REF: AMM 21-26-03PROC. REF: AMM 21-26-03									
212603-0103	NO. 3 NOSE 28 VDC/12 VDC,FAN,ELECTRONIC EQUIPMENT EQUIPMENT,FWD FUSLG INVERTER							Component	ATA:21
PN:524864	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:E07018281	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-26-03PROC. REF: AMM 21-26-03									

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
212603-0104	NOSE 28 VDC/12 VDC,FAN,ELECTRONIC EQUIPMENT EQUIPMENT,FWD FUSLG INVERTER							Component	ATA:21
PN:524864	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:E07018282	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-26-03PROC. REF: AMM 21-26-03									
212603-0201	FWD COMPARTMENT EXT POWER SUPPLY SUPPLY							Component	ATA:21
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
212701-0101	CLASS C, BAGGAGE COMPARTMENT FAN							Component	ATA:21
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-27-01PROC. REF: AMM 21-27-01									
212703-0101	CARGO CP PRESSURIZATION EQUILIZATION VALVE ASSEMBLY							Component	ATA:21
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-27-03PROC. REF: AMM 21-27-03									
213000-0201	LEFT REGULATING-PRESSURE/DEICING,PNEUMATIC SYS VALVE							Component	ATA:21
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
213000-0202	RIGHT REGULATING-PRESSURE/DEICING,PNEUMATIC SYS VALVE							Component	ATA:21
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
213100-0101		PRESS SYS - REAR FUSLG 1,41 KFT PNEUMATIC VALVE						Component	ATA:21
PN:2113A020101	MOS/MSC	17-Feb-22	O/C	TSR 10					
SN:05045	HRS	9806.1		TSR 0					
	AFL	5216		TSR 0					
PROC. REF: AMM 21-31-04PROC. REF: AMM 21-31-04									
213100-0102		PRESS SYS - REAR FUSLG 1,41 KFT, 10V ELECTRO PNEUMATIC VALVE						Component	ATA:21
PN:2112A010101	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:05066	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-31-04PROC. REF: AMM 21-31-04									
213101-0101		CSL CENT DIGITAL CONTROLLER-PRESSURIZATION,COCKPIT UNIT						Component	ATA:21
PN:91132A010101	MOS/MSC	28-Jul-21	O/C						
SN:05162	HRS	9631.4							
	AFL	5130							
PROC. REF: AMM 21-31-01PROC. REF: AMM 21-31-01									
213102-0101		CSL CENT CONTROL-MANUAL PRESSURE REGULATOR 41 KFT,CTL CSL,COCKPIT UNLT						Component	ATA:21
PN:2114A010101	MOS/MSC	19-Feb-21	O/C	TSN 0					
SN:05302	HRS	9508.9		TSN 0					
	AFL	5061		TSN 0					
PROC. REF: AMM 21-31-02PROC. REF: AMM 21-31-02									
213107-0201		LH REAR STATIC-HEATED,PRESSURIZATION SYS,28VDC PORT						Component	ATA:21
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-31-07PROC. REF: AMM 21-31-07									
213107-0202		RH REAR STATIC-HEATED,PRESSURIZATION SYS,28VDC PORT						Component	ATA:21
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-31-07PROC. REF: AMM 21-31-07									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
213201-0101	CABIN PRESSURE - RH LATERAL CONSOLE, DATA ACQUISITION MODULE							Component	ATA:21
PN:2014AB1	MOS/MSC	21-Jan-22	O/C	TSR 2					
SN:1406	HRS	9789.3		TSR 0					
	AFL	5205		TSR 0					
PROC. REF: AMM 21-32-01PROC. REF: AMM 21-32-01									
215100-0101	LH PACK ENVIRONMENTAL CONTROL UNIT							Component	ATA:21
PN:816626-2	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:2007030073	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
215100-0102	RH PACK ENVIRONMENTAL CONTROL- ECU, AIR CONDITIONING SYS UNIT							Component	ATA:21
PN:816636-2	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:2007020129	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
215101-0101	LH PIL CHECK-BLEED SYS,REAR FUSLG I/II VALVE							Component	ATA:21
PN:816604-2	MOS/MSC	05-Mar-18	O/C	TSR 0					
SN:2006100487	HRS	8509.4		TSR 0					
	AFL	4566		TSR 0					
PROC. REF: AMM 21-51-01PROC. REF: AMM 21-51-01									
215101-0102	RH PIL CHECK-BLEED SYS,REAR FUSLG I/II VALVE							Component	ATA:21
PN:816604-2	MOS/MSC	05-Mar-18	O/C	TSR 18					
SN:2008020786	HRS	8509.4		TSR 537.8					
	AFL	4566		TSR 287					
PROC. REF: AMM 21-51-01PROC. REF: AMM 21-51-01									
215102-0101	LH HEAT EXCHANGER UNIT							Component	ATA:21
PN:816630-1	MOS/MSC	29-Jun-23	O/C	TSO 0					
SN:2011031697	HRS	10161.5		TSO 0					
	AFL	5401		TSO 0					
PROC. REF: AMM 21-51-02PROC. REF: AMM 21-51-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
215102-0102		RH HEAT EXCHANGER UNIT						Component	ATA:21
PN:816630-2	MOS/MSC	29-Jun-23	O/C	TSO 0					
SN:2011120010	HRS	10161.5		TSO 0					
	AFL	5401		TSO 0					
PROC. REF: AMM 21-51-02PROC. REF: AMM 21-51-02									
215106-0201		LH ENG PACK,AIR CONDITIONING SYS - OVERPRESSURE SWITCH						Component	ATA:21
PN:782100-11	MOS/MSC	16-Jun-12	O/C	TSN 0					
SN:3171	HRS	5893.2		TSN 0					
	AFL	3135		TSN 0					
PROC. REF: AMM 21-51-06PROC. REF: AMM 21-51-06									
215106-0202		RH ENG PACK, AIR CONDITIONING SYS - OVERPRESSURE SWITCH						Component	ATA:21
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-51-06PROC. REF: AMM 21-51-06									
216001-7000 U		RH DUAL TEMP CONTROL VALVE						Component	ATA:21
PN:C143123-6	MOS/MSC	09-Apr-13	O/C					CUSTOMER CODE	
SN:01022238	HRS	6519.2		TSN 14949.8, TSO 36.93, TSR 0					
	AFL	3507		TSN 13415, TSR 0					
216002-0101		PAX AMBIENT TEMPERATURE,ECU,A/C SYS SENSOR						Component	ATA:21
PN:815289-2	MOS/MSC	31-Aug-18	O/C	TSN 3					
SN:21035	HRS	8737.9		TSN 0					
	AFL	4686		TSN 0					
PROC. REF: AMM 21-60-02PROC. REF: AMM 21-60-02									
216002-0102		CREW CAB AMBIENT TEMPERATURE,ECU,A/C SYS SENSOR						Component	ATA:21
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-60-02PROC. REF: AMM 21-60-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
216004-0101		LEFT TEMPERATURE ASSY-DIGITAL,AIR CONDITIONING SYS CONTROLLER						Component	ATA:21
PN:C142398-4-006	MOS/MSC	04-Aug-10	O/C	TSN 0					
SN:07043238	HRS	3628.6		TSN 0					
	AFL	1907		TSN 0					
PROC. REF: AMM 21-60-04	PROC. REF: AMM 21-60-04								
216004-0102		RIGHT TEMPERATURE ASSY-DIGITAL,AIR CONDITIONING SYS CONTROLLER						Component	ATA:21
PN:C142398-4-006	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:07023204	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-60-04	PROC. REF: AMM 21-60-04								
216005-0101		MANUAL, AIR COND SYS, RH CONSOLE, TEMPERATURE CONTROL MODULE						Component	ATA:21
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-60-05	PROC. REF: AMM 21-60-05								
216006-0101		BOX - PAX TEMPERATURE CONTROLLER,MM SYS ASSEMBLY						Component	ATA:21
PN:990-8000-004	MOS/MSC	12-Sep-18	O/C	TSN 1					
SN:11040062146	HRS	8754.1		TSN 0					
	AFL	4698		TSN 0					
PROC. REF: AMM 21-60-06	PROC. REF: AMM 21-60-06								
217001-0101		NO. 1 OZONE/OXYGEN CONVERTER - BLEED SYSTEM						Component	ATA:21
PN:60A523-101	MOS/MSC	27-Jun-19	O/C	TSR 0					
SN:0306-1352	HRS	9057.4		TSR 0					
	AFL	4853		TSR 0					
PROC. REF: AMM 21-70-01	PROC. REF: AMM 21-70-01								
217001-0102		NO. 2 OZONE/OXYGEN CONVERTER - BLEED SYSTEM						Component	ATA:21
PN:60A523-101	MOS/MSC	27-Jun-19	O/C	TSR 0					
SN:011/0338	HRS	9057.4		TSR 0					
	AFL	4853		TSR 0					
PROC. REF: AMM 21-70-01	PROC. REF: AMM 21-70-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 22 - AUTO FLIGHT									
22-11-00-720-003-A00	FUNCTIONALLY CHECK CATEGORY II MONITORING FUNCTION NOTE: ONLY FOR CAT II OPERATION								Service ATA:22
	MOS/MSC	01-Sep-17	O/C						
	HRS	8284.1							
	AFL	4446							
PROC. REF: AMM 22-11-00PROC. REF: AMM 22-11-00									
22-11-00-720-004-A00 S	FUNCTIONALLY CHECK AFCS ALTITUDE HOLD MODE AND ALTITUDE PRE-SELECT MODE NOTE: ONLY FOR RVSM OPERATION								Service ATA:22
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 22-11-00PROC. REF: AMM 22-11-00									
221001-0101	CSL CENT AUTOPILOT PC400, INSTRUMENT PANEL CONTROLLER UNIT								Component ATA:22
PN:7003897-925	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:07013614	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 22-11-02PROC. REF: AMM 22-11-02									
221002-0101	CSL CENT GC 550, GUIDANCE AUTOPILOT SYS, GLARESHIELD CONTROL PANEL								Component ATA:22
PN:7021170-953	MOS/MSC	10-Dec-24	O/C						
SN:04031380	HRS	10605.1							
	AFL	5653							
PROC. REF: AMM 22-11-01PROC. REF: AMM 22-11-01									
221003-0101	FORWARD FUSELAGE,AUTO PILOT, AILERON SERVO								Component ATA:22
PN:145-20449-407	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 22-11-03PROC. REF: AMM 22-11-03									
221003-0201	RUDDER ELECTROMECHANICAL ASSY-FLIGHT CONTROL,AUTO PILOT ACTUATOR								Component ATA:22
PN:4006719-906 MOD N	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:0612H515	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 22-11-05PROC. REF: AMM 22-11-05									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 22 - AUTO FLIGHT									
221003-0202		ELEVATOR ELECTROMECHANICAL ASSY-FLIGHT CONTROL,AUTO PILOT ACTUATOR						Component	ATA:22
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 22-11-04	PROC. REF: AMM 22-11-04								
221003-0203		AILERON ELECTROMECHANICAL ASSY-FLIGHT CONTROL,AUTO PILOT ACTUATOR						Component	ATA:22
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 22-11-03	PROC. REF: AMM 22-11-03								
221004-0101		FORWARD ASSY-ELEVATOR, AUTO PILOT, HORIZONTAL TAIL SERVO						Component	ATA:22
PN:145-20454-409	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 22-11-04	PROC. REF: AMM 22-11-04								
221005-0101		REAR ASSY-RUDDER, AUTO PILOT, VERTICAL TAIL SERVO						Component	ATA:22
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 22-11-05	PROC. REF: AMM 22-11-05								
ATA 23 - COMMUNICATIONS									
23-15-03-212-001-A00		INSPECT (GENERAL VISUAL) OF SATCOM ANTENNA PART NUMBER 10101-00 NOTE: EMB RECOMM						Service	ATA:23
	MOS/MSC	03-Jul-15	N/A						
	HRS	7460.3							
	AFL	3992							
PROC. REF: AMM 23-15-03	PROC. REF: AMM 23-15-03								
23-35-21-710-001-A00 S		OPERATIONALLY CHECK ENTERTAINMENT CABINET FANS						Service	ATA:23
	MOS	29-Jun-23	48 (+15d/-15d)				LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 23-35-21	PROC. REF: AMM 23-35-21								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
23-60-00-720-001-A00 S	FUNCTIONALLY CHECK STATIC DISCHARGER								Service ATA:23
	MOS	17-Oct-25	72 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	3000 (+20/-20)						
	AFL	5820	1500 (+20/-20)						
									PKG:5012,6020
PROC. REF: AMM 23-60-00PROC. REF: AMM 23-60-00									
23-71-00-710-001-A00	OPERATIONALLY CHECK VOICE RECORDER 4 CHANNELS AND AREA MICROPHONE								Service ATA:23
	MOS	29-Jun-23	48 (+30d/-30d)	Adj 7d	06-Jul-27	05-Aug-27	406 d (+30)	SYSTEM	
	HRS	10161.5	4000		14161.5		2885.2		
	AFL	5401							
PROC. REF: AMM 23-71-00PROC. REF: AMM 23-71-00									
23-71-02-960-001-A00	DISCARD CVR UNDERWATER LOCATOR BEACON BATTERY NOTE: ULB BATTERY CHANGE IN ACCORDANCE WITH MANUFACTURER'S DATAPLATE EXPIRATION DATE								Service ATA:23
PN:PN	MOS/MSC	01-Jun-22	DUE		31-Mar-29 (M)		1040 d	SYSTEM	
SN:UNKNOWN	HRS	9892.8							
	AFL	5264							
PROC. REF: AMM 23-71-02PROC. REF: AMM 23-71-02									
230000-0702 U	CONFIGURATION MODULE AIRCELL								Component ATA:23
PN:PI4126	MOS/MSC	19-Sep-13	O/C					CUSTOMER CODE	
SN:1412612592	HRS								
	AFL								
230190-701 U	XM RADIO ANTENNA								Component ATA:23
PN:CI420-1	MOS/MSC	01-Mar-19	O/C	TSN 0					
SN:109639	HRS	8966		TSN 0					
	AFL	4791		TSN 0					
231102-0101	REAR I KRX1053 HF COMM W/SELCAL COMPATIBILITY TRANSCEIVER								Component ATA:23
PN:064-01073-0102	MOS/MSC	31-Aug-17	O/C	TSN 21					
SN:KRX1053-5635	HRS	8284.1		TSN 0					
	AFL	4446		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
PROC. REF: AMM 23-11-02PROC. REF: AMM 23-11-02									
231102-0102		REAR I KRX1053 HF COMM W/SELCAL COMPATIBILITY TRANSCEIVER						Component	ATA:23
PN:064-01073-0101	MOS/MSC	16-Mar-08	O/C	TSN 0					
SN:2528	HRS	694		TSN 0					
	AFL	358		TSN 0					
PROC. REF: AMM 23-11-02PROC. REF: AMM 23-11-02									
231103-0101		NO. 1 REAR POWER- KPA 1052 AMPLIFIER						Component	ATA:23
PN:064-01072-0101	MOS/MSC		O/C						
SN:2125	HRS								
	AFL	0							
PROC. REF: AMM 23-11-03PROC. REF: AMM 23-11-03									
231103-0102		NO. 2 REAR I POWER- KPA 1052 AMPLIFIER						Component	ATA:23
PN:064-01072-0101	MOS/MSC		O/C						
SN:2142	HRS								
	AFL	0							
PROC. REF: AMM 23-11-03PROC. REF: AMM 23-11-03									
231104-0101		NO. 1 REAR I HF ANTENNA COUPLER - KAC1052, KHF1050 SYSTEM						Component	ATA:23
PN:064-01074-0101	MOS/MSC	01-Oct-08	O/C						
SN:1720	HRS	1356.7							
	AFL	721							
PROC. REF: AMM 23-11-04PROC. REF: AMM 23-11-04									
231104-0102		NO. 2 REAR I HF ANTENNA COUPLER - KAC1052, KHF1050 SYSTEM						Component	ATA:23
PN:064-01074-0101	MOS/MSC		O/C						
SN:2177	HRS								
	AFL	0							
PROC. REF: AMM 23-11-04PROC. REF: AMM 23-11-04									
231111-0101		REAR COMPARTMENT BRIDGING AMPLIFIER - KA 158 AMPLIFIER						Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
PROC. REF: AMM 23-11-11PROC. REF: AMM 23-11-11									
231112-0101		REAR COMPARTMENT KA 594 BUS ADAPTER, HF SYSTEM ADAPTER						Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-11-12PROC. REF: AMM 23-11-12									
231113-0101		REAR COMPARTMENT CAPACITOR,DUAL-EXTERNAL,KA 162,HN CONNECTOR,HF RADIO SYSTEM CAPACITOR						Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-11-13PROC. REF: AMM 23-11-13									
231114-0101		PILOT MODULE -KHF1 SYSTEM,MAIN PANEL,COCKPIT ASSEMBLY						Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 31-11-01PROC. REF: AMM 31-11-01									
231114-0102		COPILOT MODULE -KHF1 SYSTEM,MAIN PANEL,COCKPIT ASSEMBLY						Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 31-11-01PROC. REF: AMM 31-11-01									
231201-0101		NO.1 NOSE VHF-COMM RCZ833K,RADIO NAV/COMM SYS ACCESSORIES UNIT						Component	ATA:23
PN:7510733-666	MOS/MSC	19-Aug-15	O/C						
SN:0608A868	HRS	7460.3							
	AFL	3992							
PROC. REF: AMM 23-00-01PROC. REF: AMM 23-00-01									
231201-0101A U		RECERTIFY NO.1 NOSE VHF-COMM RCZ833K,RADIO NAV/COMM SYS ACCESSORIES UNIT PER FAR 91.413						Service	ATA:23
PN:7510733-666	MOS	14-Jul-25	24 (+30d/-30d)		14-Jul-27	13-Aug-27	414 d (+30)	FAR	
SN:0608A868	HRS	10838.8							
	AFL	5775							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
PROC. REF: FAR FAR 91.413PROC. REF: FAR FAR 91.413									
231201-0102		NO.2 NOSE VHF-COMM RCZ833K,RADIO NAV/COMM SYS ACCESSORIES UNIT							Component ATA:23
PN:7510733-666	MOS/MSC	19-Aug-15	O/C	TSR 34					
SN:0812C389	HRS	7460.3		TSR 1018.1					
	AFL	3992		TSR 524					
PROC. REF: AMM 23-00-01PROC. REF: AMM 23-00-01									
231201-0102A U		RECERTIFY NO.2 NOSE VHF-COMM RCZ833K,RADIO NAV/COMM SYS ACCESSORIES UNIT PER FAR 91.413							Service ATA:23
PN:7510733-666	MOS	14-Jul-25	24 (+30d/-30d)		14-Jul-27	13-Aug-27	414 d (+30)	FAR	
SN:0812C389	HRS	10838.8							
	AFL	5775							
PROC. REF: FAR FAR 91.413PROC. REF: FAR FAR 91.413									
231201-0201		NOSE VHF-COMMUNICATION UNIT,RADIO NAV/COMM SYS BOX							Component ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-00-01PROC. REF: AMM 23-00-01									
231204-0201		VHF 1 VHF ANTENNA							Component ATA:23
PN:16-21B MOD.1	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-12-04PROC. REF: AMM 23-12-04									
231204-0202		VHF 2 VHF ANTENNA							Component ATA:23
PN:16-21B MOD.1	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-12-04PROC. REF: AMM 23-12-04									
231204-0203		VHF 3 VHF ANTENNA							Component ATA:23
PN:S65-8280-41	MOS/MSC	20-Feb-20	O/C	TSN 0					
SN:322-6611	HRS	9313.5		TSN 0					
	AFL	4970		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty

ATA 23 - COMMUNICATIONS

PROC. REF: AMM 23-12-04PROC. REF: AMM 23-12-04

231501-0101	REAR FUS UNIT,TRANSCEPTOR-IRIDIUM TELEPHONE SYSTEM							Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

231501-0102	REAR FUS UNIT,TRANSCEPTOR-IRIDIUM TELEPHONE SYSTEM							Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

231503-0101	FLITEFONE, SATELLITE COMMUNICATION SYS ANTENNA							Component	ATA:23
PN:015-10306-001	MOS/MSC	14-Oct-15	O/C	TSN 2					
SN:11775	HRS	7523.8		TSN 0					
	AFL	4025		TSN 0					
PROC. REF: AMM 23-15-03PROC. REF: AMM 23-15-03									

231503-0102	FLITEFONE, SATELLITE COMMUNICATION SYS ANTENNA							Component	ATA:23
PN:015-10306-001	MOS/MSC	14-Oct-15	O/C	TSN 2					
SN:8391	HRS	7523.8		TSN 0					
	AFL	4025		TSN 0					
PROC. REF: AMM 23-15-03PROC. REF: AMM 23-15-03									

231505-0101	INMARSAT/IRIDIUM COSITE INTERFERENCE UNIT							Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

231507-0101	IRIDIUM FILTER UNIT							Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
231510-0101		TRANSCEIVER ,PAX BOARD TELEPHONE MANAGEMENT, AEROCON UNIT						Component	ATA:23
PN:P12023 REV.U	MOS/MSC	04-Dec-13	O/C	TSR 0					
SN:1202312020	HRS			TSR 0					
	AFL			TSR 0					
PROC. REF: AMM 23-15-10PROC. REF: AMM 23-15-10									
231521-0101		SATCOM DATA SDU-7300/SATCOM SYS UNIT						Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-15-21PROC. REF: AMM 23-15-21									
231521-0201		REAR COMPARTMENT HIGH SPEED DATA TERMINAL, INTERNET, TERMINAL						Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-15-21PROC. REF: AMM 23-15-21									
231522-0101		HIGH POWER AMPLIFIER-AERO HPA-7400/SATCOM SYS UNIT						Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-15-22PROC. REF: AMM 23-15-22									
231523-0101		REAR FUS ACCESS POINT-WASP,WIRELESS,HSD SYS UNIT						Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-15-23PROC. REF: AMM 23-15-23									
231524-0101		REAR DIPLEXER/AMPLIFIER- DAU 7050 SYS HSD IRIDIUM UNIT						Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty

ATA 23 - COMMUNICATIONS

PROC. REF: AMM 23-15-24PROC. REF: AMM 23-15-24

231525-0101		HIGH GAIN-HGA 7000,SATCOM SYS ANTENNA						Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					

PROC. REF: AMM 23-15-26PROC. REF: AMM 23-15-26

231525-0102		BAGGAGE COMPARTMENT CAP ANTENNA, BI ANTENNA						Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					

PROC. REF: AMM 23-15-25PROC. REF: AMM 23-15-25

231528-0101		BOARD TELEPHONE UNIT MANAGEMENT,ICS UNIT						Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

232101-0101		HHCSL DECODER, SELECTIVE CALLING SYS, RADIOCOMM UNIT						Component	ATA:23
PN:2800-0012-102	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:7015001	HRS	0		TSN 0					
	AFL	0		TSN 0					

PROC. REF: AMM 23-21-01PROC. REF: AMM 23-21-01

232102-0101		CREW CAB SELCAL HF+VHF 2 MODULE						Component	ATA:23
PN:145-46569-405	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:0000159263	HRS	0		TSN 0					
	AFL	0		TSN 0					

PROC. REF: AMM 23-21-02PROC. REF: AMM 23-21-02

232401-0101		NOSE CMU950, ARINC SYS, MANAGEMENT CONTROL UNIT						Component	ATA:23
PN:965-0758-006	MOS/MSC	20-Feb-20	O/C						
SN:CMUMK2-08202	HRS	9313.5							
	AFL	4970							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
PROC. REF: AMM 23-24-01PROC. REF: AMM 23-24-01									
232401-0201		CMU BATTERY						Component	ATA:23
PN:PN-UNKNOWN	MOS/MSC	28-Jan-19	O/C						
SN:UNKNOWN	HRS	8932.1							
	AFL	4776							
PROC. REF: AMM 23-24-01PROC. REF: AMM 23-24-01									
232403-0101		NOSE IM 950,5V,CMU SYS,FWD ELEK COMPT, AIRCRAFT PERSONALITY MODULE						Component	ATA:23
PN:964-0465-001	MOS/MSC	20-Feb-20	O/C						
SN:APM-01883	HRS	9313.5							
	AFL	4970							
PROC. REF: AMM 23-24-03PROC. REF: AMM 23-24-03									
233000-0904 U		1 TERRESTRIAL MODEM ANTENNA						Component	ATA:23
PN:P18350-001	MOS/MSC	19-Feb-20	O/C	TSN 0				CUSTOMER CODE	
SN:1835005874	HRS	9310.8		TSN 0					
	AFL	4969		TSN 0					
233000-0904 U		2 TERRESTRIAL MODEM ANTENNA						Component	ATA:23
PN:P18350-001	MOS/MSC	19-Feb-20	O/C	TSN 0				CUSTOMER CODE	
SN:1835005828	HRS	9310.8		TSN 0					
	AFL	4969		TSN 0					
233000-0905 U		AXXESS CABIN ROUTER						Component	ATA:23
PN:PN	MOS/MSC	19-Feb-20	O/C						
SN:NOT INSTALLED	HRS	9310.8							
	AFL	4969							
233000-0906 U		GOGO BIZ 4G TRANSCEIVER						Component	ATA:23
PN:P34110-002	MOS/MSC	15-Aug-24	O/C						
SN:341100024435E	HRS	10541.4							
	AFL	5613							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
233000-0907 U		AXXESS CONFIGURATION MODULE						Component	ATA:23
PN:P14126	MOS/MSC	19-Feb-20	O/C	TSN 0					
SN:1412625133	HRS	9310.8		TSN 0					
	AFL	4969		TSN 0					
233000-0908 U		NO. 1 4G ANTENNA						Component	ATA:23
PN:P35500	MOS/MSC	19-Feb-20	O/C	TSN 0					
SN:3550002857	HRS	9310.8		TSN 0					
	AFL	4969		TSN 0					
233000-0908 U		NO. 2 4G ANTENNA						Component	ATA:23
PN:P35500	MOS/MSC	19-Feb-20	O/C	TSN 0					
SN:3550002858	HRS	9310.8		TSN 0					
	AFL	4969		TSN 0					
233000-0909 U		NO. 1 REMOTE ANTENNA						Component	ATA:23
PN:P16917-001	MOS/MSC	19-Feb-20	O/C	TSN 0					
SN:16917001112003	HRS	9310.8		TSN 0					
	AFL	4969		TSN 0					
233000-0909 U		NO. 2 REMOTE ANTENNA						Component	ATA:23
PN:P16917-001	MOS/MSC	19-Feb-20	O/C	TSN 0					
SN:1691700111991	HRS	9310.8		TSN 0					
	AFL	4969		TSN 0					
233000-0909 U		NO. 3 REMOTE ANTENNA						Component	ATA:23
PN:P16917-001	MOS/MSC	19-Feb-20	O/C	TSN 0					
SN:1691700111988	HRS	9310.8		TSN 0					
	AFL	4969		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
233000-0909 U		NO. 4 REMOTE ANTENNA						Component	ATA:23
PN:P16917-001	MOS/MSC	19-Feb-20	O/C	TSN 0					
SN:1691700111984	HRS	9310.8		TSN 0					
	AFL	4969		TSN 0					
233000-0909 U		NO. 5 REMOTE ANTENNA						Component	ATA:23
PN:P16917-001	MOS/MSC	19-Feb-20	O/C	TSN 0					
SN:1691700111992	HRS	9310.8		TSN 0					
	AFL	4969		TSN 0					
233000-0909 U		NO. 6 REMOTE ANTENNA						Component	ATA:23
PN:P16917-001	MOS/MSC	19-Feb-20	O/C	TSN 0					
SN:1691700111989	HRS	9310.8		TSN 0					
	AFL	4969		TSN 0					
233000-0910 U		AUDIO STORAGE UNIT						Component	ATA:23
PN:630A-000	MOS/MSC	20-Feb-20	O/C	TSN 0					
SN:P200400	HRS	9313.5		TSN 0					
	AFL	4970		TSN 0					
233000-0911 U		SATELLITE DATA UNIT						Component	ATA:23
PN:DL-150-00	MOS/MSC	20-Feb-20	O/C	TSN 0					
SN:60155	HRS	9313.5		TSN 0					
	AFL	4970		TSN 0					
233000-0912 U		IRIDIUM ANTENNA						Component	ATA:23
PN:S67-1575-409	MOS/MSC	20-Feb-20	O/C	TSN 0					
SN:904-2378	HRS	9313.5		TSN 0					
	AFL	4970		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
233000-0913 U		VDR ASSEMBLY (TR-866B) MODULE						Component	ATA:23
PN:7026201-815	MOS/MSC	20-Feb-20	O/C	TSN 0					
SN:1912G649	HRS	9313.5		TSN 0					
	AFL	4970		TSN 0					
233101-0101		PASSENGER WARNING SYSTEM AMPLIFIER						Component	ATA:23
PN:5482-1	MOS/MSC	15-Nov-17	O/C	TSR 10					
SN:1265	HRS	8381.4		TSR 0					
	AFL	4500		TSR 0					
PROC. REF: AMM 23-31-01PROC. REF: AMM 23-31-01									
233102-0101		OVERH P MODULE -ICU ASSEMBLY						Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-31-02PROC. REF: AMM 23-31-02									
233104-0101		ELECTRICAL COMPARTMENT SERVICE PANEL, AFT LH, CEILING SPEAKER						Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
233104-0102		ELECTRICAL COMPARTMENT SERVICE PANEL, AFT LH, CEILING SPEAKER						Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
233104-0103		ELECTRICAL COMPARTMENT SERVICE PANEL, AFT LH, CEILING SPEAKER						Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
233104-0104	ELECTRICAL COMPARTMENT SERVICE PANEL, AFT LH, CEILING SPEAKER							Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
233104-0105	ELECTRICAL COMPARTMENT SERVICE PANEL, AFT LH, CEILING SPEAKER							Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
233104-0106	ELECTRICAL COMPARTMENT SERVICE PANEL, AFT LH, CEILING SPEAKER							Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
233501-0101	DIGITAL INTERFACE-ENTERTAINMENT,AIRSHOW,PAX CABIN UNIT							Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-35-01PROC. REF: AMM 23-35-01									
233504-0101	AUDIO/VIDEO SYS, PAX ENTERTAINMENT CABINET VIDEO CASSETTE PLAYER							Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-35-04PROC. REF: AMM 23-35-04									
233505-0101	DIGITAL VIDEO DISC -AUDIO/VIDEO SYS, PAX ENTERTAINMENT CABINET ASSEMBLY							Component	ATA:23
PN:996-4720-001	MOS/MSC	01-Sep-17	O/C	TSR 0					
SN:11090063542	HRS	8284.1		TSR 0					
	AFL	4446		TSR 0					
PROC. REF: AMM 23-35-05PROC. REF: AMM 23-35-05									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
233505-0102	DIGITAL VIDEO DISC -AUDIO/VIDEO SYS,PAX ENTERTAINMENT CABINET ASSEMBLY							Component	ATA:23
PN:996-4718-001	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:07030037332	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-35-05	PROC. REF: AMM 23-35-05								
233506-0101	BASE, RECEPTACLE - HORIZONTAL UNIT							Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 24-40-01	PROC. REF: AMM 24-40-01								
233506-0102	BASE, RECEPTACLE - HORIZONTAL UNIT							Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 24-40-01	PROC. REF: AMM 24-40-01								
233506-0103	BASE, RECEPTACLE - HORIZONTAL UNIT							Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 24-40-01	PROC. REF: AMM 24-40-01								
233506-0104	BASE, RECEPTACLE - HORIZONTAL UNIT							Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 24-40-01	PROC. REF: AMM 24-40-01								
233506-0105	BASE, RECEPTACLE - HORIZONTAL UNIT							Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 24-40-01	PROC. REF: AMM 24-40-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
233506-0106	BASE, RECEPTACLE - HORIZONTAL UNIT							Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 24-40-01PROC. REF: AMM 24-40-01									
233506-0107	BASE, RECEPTACLE - HORIZONTAL UNIT							Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 24-40-01PROC. REF: AMM 24-40-01									
233506-0108	BASE, RECEPTACLE - HORIZONTAL UNIT							Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 24-40-01PROC. REF: AMM 24-40-01									
233513-0101	AUDIO,AMPLIFIER-IFE/PA,DC,DA-420PDC UNIT							Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-35-13PROC. REF: AMM 23-35-13									
233515-0101	FORWARD AUDIO ASSY-M1021,AIRSHOW SYS AMPLIFIER							Component	ATA:23
PN:990-4132-002	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:06050027269	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-35-13PROC. REF: AMM 23-35-13									
233515-0102	FORWARD AUDIO ASSY-M1021,AIRSHOW SYS AMPLIFIER							Component	ATA:23
PN:990-4132-002	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:06100032705	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-35-13PROC. REF: AMM 23-35-13									

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
233531-0101	MEDIA, INTERFACE UNIT							Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-35-31PROC. REF: AMM 23-35-31									
233532-0101	JETMAP COCKPIT CONTROL PANEL							Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
233601-0101	UTILITY I/O - CABIN, CONTROLLER UNIT							Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-36-01PROC. REF: AMM 23-36-01									
233602-0101	CABIN, INTERFACE UNIT							Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-36-02PROC. REF: AMM 23-36-02									
233602-0102	CABIN, INTERFACE UNIT							Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-36-02PROC. REF: AMM 23-36-02									
233603-0101	UNIT,ACCESS POINT - WIRELESS, AVCMS UNIT							Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-36-03PROC. REF: AMM 23-36-03									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
233604-0101		TOUCHSCREEN,PANEL-GALLEY,8.9" UNIT						Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-36-04PROC. REF: AMM 23-36-04									
233605-0101		SELECT 100, PASSENGER, CONTROL UNIT						Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-36-05PROC. REF: AMM 23-36-05									
233607-0101		SELECT200, PASSENGER, CONTROL UNIT						Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-36-05PROC. REF: AMM 23-36-05									
233607-0102		SELECT200, PASSENGER, CONTROL UNIT						Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-36-05PROC. REF: AMM 23-36-05									
233607-0103		SELECT200, PASSENGER, CONTROL UNIT						Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-36-05PROC. REF: AMM 23-36-05									
233607-0104		SELECT200, PASSENGER, CONTROL UNIT						Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-36-05PROC. REF: AMM 23-36-05									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
233607-0105	SELECT200, PASSENGER, CONTROL UNIT							Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-36-05PROC. REF: AMM 23-36-05									
233607-0106	SELECT200, PASSENGER, CONTROL UNIT							Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-36-05PROC. REF: AMM 23-36-05									
233607-0107	SELECT200, PASSENGER, CONTROL UNIT							Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-36-05PROC. REF: AMM 23-36-05									
233607-0108	SELECT200, PASSENGER, CONTROL UNIT							Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-36-05PROC. REF: AMM 23-36-05									
233607-0109	SELECT200, PASSENGER, CONTROL UNIT							Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-36-05PROC. REF: AMM 23-36-05									
233607-0110	SELECT200, PASSENGER, CONTROL UNIT							Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-36-05PROC. REF: AMM 23-36-05									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
233609-0101	PERSONAL MONITOR, VIDEO, 9 INCHES D UNIT							Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
233609-0102	PERSONAL MONITOR, VIDEO, 9 INCHES D UNIT							Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
233609-0103	PERSONAL MONITOR, VIDEO, 9 INCHES D UNIT							Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
233609-0104	PERSONAL MONITOR, VIDEO, 9 INCHES D UNIT							Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
233609-0105	PERSONAL MONITOR, VIDEO, 9 INCHES D UNIT							Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
233609-0106	PERSONAL MONITOR, VIDEO, 9 INCHES D UNIT							Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
233609-0107	PERSONAL MONITOR, VIDEO, 9 INCHES D UNIT							Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
233609-0108	PERSONAL MONITOR, VIDEO, 9 INCHES D UNIT							Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
233801-0101	BLU-RAY,PLAYER UNIT							Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-38-01PROC. REF: AMM 23-38-01									
233801-0102	BLU-RAY,PLAYER UNIT							Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-38-01PROC. REF: AMM 23-38-01									
233802-0101	HIGH DEFINITION, AUDIO/VIDEO, INPUT UNIT							Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-38-02PROC. REF: AMM 23-38-02									
233802-0102	HIGH DEFINITION, AUDIO/VIDEO, INPUT UNIT							Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-38-02PROC. REF: AMM 23-38-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
233803-0101	IPOD,DOCKING,STATION-PAX,CABIN UNIT							Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-38-03PROC. REF: AMM 23-38-03									
233803-0102	IPOD,DOCKING,STATION-PAX,CABIN UNIT							Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-38-03PROC. REF: AMM 23-38-03									
233804-0101	AUX. PANELS (1 USB, RCA, HDMI, RJ45 UNIT							Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-38-04PROC. REF: AMM 23-38-04									
233804-0102	AUX. PANELS (1 USB, RCA, HDMI, RJ45 UNIT							Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-38-04PROC. REF: AMM 23-38-04									
233805-0101	SCALAR BOX - HIGH DEFINITION VIDEO UNIT							Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
233806-0101	HD 24" WIDESCREEN MONITOR UNIT							Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
234101-0101	ATTEND 1 INTERPHONE-FLIGHT ATTENDANT/PAX CABIN UNIT							Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
235101-0101	NO.1 CREW CAB AUDIO -AV-850 PANEL							Component	ATA:23
PN:7511001-975	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:0702B797	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-51-01PROC. REF: AMM 23-51-01									
235101-0102	NO. 2 CREW CAB AUDIO -AV-850 PANEL							Component	ATA:23
PN:7511001-975	MOS/MSC	11-Sep-19	O/C	TSR 0					
SN:0608B230	HRS	9134.8		TSR 0					
	AFL	4897		TSR 0					
PROC. REF: AMM 23-51-01PROC. REF: AMM 23-51-01									
235101-0103	NO. 3 CREW CAB AUDIO -AV-850 PANEL							Component	ATA:23
PN:7511001-975	MOS/MSC	17-Aug-15	O/C	TSR 7					
SN:0809D201	HRS	7460.3		TSN 1080.53, TSR 0					
	AFL	3992		TSN 741, TSR 0					
PROC. REF: AMM 23-51-01PROC. REF: AMM 23-51-01									
235103-0201	PILOT DYNAMIC-COCKPIT MICROPHONE							Component	ATA:23
PN:602-3375	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:0701010	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-51-03PROC. REF: AMM 23-51-03									
235103-0202	COPILOT DYNAMIC-COCKPIT MICROPHONE							Component	ATA:23
PN:602-3375	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:0701995	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-51-03PROC. REF: AMM 23-51-03									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
235107-0101		CREW CAB MODULE -OBSERVER JACKS PANEL ASSEMBLY						Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-51-06	PROC. REF: AMM 23-51-06								
237101-0101		SSCVR, RADIO/NAV SYS, COCKPIT VOICE RECORDER						Component	ATA:23
PN:1606-00-01	MOS/MSC	28-Apr-20	O/C						
SN:1279	HRS	9356.2							
	AFL	4984							
PROC. REF: AMM 23-71-01	PROC. REF: AMM 23-71-01								
237101-0201		CVR UNDERWATER LOCATOR BEACON						Component	ATA:23
PN:DK120/90	MOS/MSC	01-Jun-22	O/C	TSN 5					
SN:AT176706	HRS	9892.8		TSN 0					
	AFL	5264		TSN 0					
PROC. REF: AMM 23-71-02	PROC. REF: AMM 23-71-02								
237101-0301		COCKPIT VOICE RECORDER (CVR) UNDERWATER LOCATOR BEACON (ULB) BATTERY						Component	ATA:23
PN:PN	MOS/MSC	01-Jun-22	H/T	TSN 5					
SN:UNKNOWN	HRS	9892.8		TSN 0					
	AFL	5264		TSN 0					
PROC. REF: GENERIC NO REF	PROC. REF: GENERIC NO REF								
237102-0101		OVERH P RADIO/NAVIGATION SYS, CVR CONTROL PANEL						Component	ATA:23
PN:1641-110-01	MOS/MSC	20-Feb-20	O/C						
SN:0924	HRS	9313.5							
	AFL	4970							
PROC. REF: AMM 23-71-02	PROC. REF: AMM 23-71-02								
237103-0101		CREW CAB CVR,RADIO/NAV SYS MICROPHONE						Component	ATA:23
PN:16301-01	MOS/MSC	20-Feb-20	O/C						
SN:6750	HRS	9313.5							
	AFL	4970							
PROC. REF: AMM 23-71-03	PROC. REF: AMM 23-71-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
237104-0101		CVR IMPACT SWITCH						Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-71-04PROC. REF: AMM 23-71-04									
237106-0101		RECORDER INDEPENDENT POWER SUPPLY						Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-71-06PROC. REF: AMM 23-71-06									
238101-0101		CSL CENT RADIO MANAGEMENT RM-855, COMM SYS, W/HF CONTROL UNIT						Component	ATA:23
PN:7013270-977	MOS/MSC	24-Feb-16	O/C						
SN:09127222	HRS	7661.9							
	AFL	4095							
PROC. REF: AMM 23-81-01PROC. REF: AMM 23-81-01									
238101-0102		CSL CENT RADIO MANAGEMENT RM-855, COMM SYS, W/HF CONTROL UNIT						Component	ATA:23
PN:7013270-977	MOS/MSC	04-Jan-23	O/C	TSR 8					
SN:98081160	HRS	10066.9		TSR 0					
	AFL	5346		TSR 0					
PROC. REF: AMM 23-81-01PROC. REF: AMM 23-81-01									
239101-0101		BASE STATION - CORDLESS HANDSET UNIT						Component	ATA:23
PN:P12857-101	MOS/MSC	01-Sep-17	O/C	TSN 0					
SN:1285740347	HRS	8284.1		TSN 0					
	AFL	4446		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
ATA 24 - ELECTRICAL POWER									
24-31-00-710-001-A00 S		OPERATIONALLY CHECK MAIN GENERATION SWITCHING CIRCUIT						Service	ATA:24
	MOS	29-Jun-23	96 (+15d/-15d)				LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6016
PROC. REF: AMM 24-31-00PROC. REF: AMM 24-31-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 24 - ELECTRICAL POWER									
24-31-00-710-002-A00 S	OPERATIONALLY CHECK MAIN GENERATION OVERCURRENT PROTECTION CIRCUIT							Service	ATA:24
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6016
PROC. REF: AMM 24-31-00PROC. REF: AMM 24-31-00									
24-31-01-900-001-A00	RESTORE (OVERHAUL) LH INBOARD (NO.3) MAIN GENERATOR PART NUMBER 30086-010 NOTE: FROM THE MANUFACTURE DATE OR LAST RESTORATION. NOTE: IF INSTALLED							Service	ATA:24
PN:30086-011	MOS/MSC	09-Apr-26	N/A						
SN:Y10505	HRS	11166.4							
	AFL	5961							
PROC. REF: AMM 24-31-01PROC. REF: AMM 24-31-01									
24-31-01-900-001-A00	RESTORE (OVERHAUL) LH OUTBOARD (NO.1) MAIN GENERATOR PART NUMBER 30086-010 NOTE: FROM THE MANUFACTURE DATE OR LAST RESTORATION. NOTE: IF INSTALLED							Service	ATA:24
PN:30086-011	MOS/MSC		N/A						
SN:Y10441	HRS								
	AFL								
PROC. REF: AMM 24-31-01PROC. REF: AMM 24-31-01									
24-31-01-900-001-A00	RESTORE (OVERHAUL) RH INBOARD (NO.2) MAIN GENERATOR PART NUMBER 30086-010 NOTE: FROM THE MANUFACTURE DATE OR LAST RESTORATION. NOTE: IF INSTALLED							Service	ATA:24
PN:30086-011	MOS/MSC	27-Jan-25	N/A						
SN:YOO96	HRS	10679.6							
	AFL	5685							
PROC. REF: AMM 24-31-01PROC. REF: AMM 24-31-01									
24-31-01-900-001-A00	RESTORE (OVERHAUL) RH OUTBOARD (NO.4) MAIN GENERATOR PART NUMBER 30086-010 NOTE: FROM THE MANUFACTURE DATE OR LAST RESTORATION. NOTE: IF INSTALLED							Service	ATA:24
PN:30086-011	MOS/MSC	18-Jul-24	N/A						
SN:99398	HRS	10519.2							
	AFL	5604							
PROC. REF: AMM 24-31-01PROC. REF: AMM 24-31-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 24 - ELECTRICAL POWER									
24-31-01-900-001-A01		RESTORE (OVERHAUL) LH INBOARD (NO.3) MAIN GENERATOR PART NUMBER 30086-011 NOTE: FROM THE MANUFACTURE DATE OR LAST RESTORATION. NOTE: IF INSTALLED.							Service ATA:24
PN:30086-011	MOS	09-Apr-26	60		09-Apr-31		1779 d	SYSTEM	
SN:Y10505	HRS	11166.4	3600		14766.4		3490.1		
	AFL	5961							
PROC. REF: AMM 24-31-01PROC. REF: AMM 24-31-01									
24-31-01-900-001-A01		RESTORE (OVERHAUL) RH INBOARD (NO.2) MAIN GENERATOR PART NUMBER 30086-011 NOTE: FROM THE MANUFACTURE DATE OR LAST RESTORATION. NOTE: IF INSTALLED.							Service ATA:24
PN:30086-011	MOS	27-Jan-25	60		27-Jan-30		1342 d	SYSTEM	
SN:YOO96	HRS	10679.6	3600		14279.6		3003.3		
	AFL	5685							
PROC. REF: AMM 24-31-01PROC. REF: AMM 24-31-01									
24-31-01-900-001-A01		RESTORE (OVERHAUL) LH OUTBOARD (NO.1) MAIN GENERATOR PART NUMBER 30086-011 NOTE: FROM THE MANUFACTURE DATE OR LAST RESTORATION. NOTE: IF INSTALLED.							Service ATA:24
PN:30086-011	MOS	14-Jun-21	60		14-Jun-26		19 d	SYSTEM	
SN:Y10441	HRS	9586.9	3600		13186.9		1910.6		
	AFL	5110							
PROC. REF: AMM 24-31-01PROC. REF: AMM 24-31-01									
24-31-01-900-001-A01		RESTORE (OVERHAUL) RH OUTBOARD (NO.4) MAIN GENERATOR PART NUMBER 30086-011 NOTE: FROM THE MANUFACTURE DATE OR LAST RESTORATION. NOTE: IF INSTALLED.							Service ATA:24
PN:30086-011	MOS	18-Jul-24	60		18-Jul-29		1149 d	SYSTEM	
SN:99398	HRS	10519.2	3600		14119.2		2842.9		
	AFL	5604							
PROC. REF: AMM 24-31-01PROC. REF: AMM 24-31-01									
24-34-01-220-001-A00		INSPECT (DETAILED INSPECTION) APU STARTER/GENERATOR BRUSHES							Service ATA:24
PN:23080-013A	MOS	24-Mar-25						SYSTEM	
SN:P1511	HRS	10758.2							
	AFL	5733							
	APH	5790	400		6190		92		
PROC. REF: AMM 24-34-01PROC. REF: AMM 24-34-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 24 - ELECTRICAL POWER									
24-34-01-900-001-A00	APU - RESTORE (OVERHAUL) APU STARTER/GENERATOR								Service ATA:24
	MOS	24-Mar-25	48		24-Mar-29		1033 d		
	HRS	5790	1200		6990		892		
	APUS	5060							
PROC. REF: AMM 24-34-01PROC. REF: AMM 24-34-01									
24-34-01-900-001-A00	RESTORE (OVERHAUL) APU STARTER/GENERATOR								Service ATA:24
PN:23080-013A	MOS	24-Mar-25	48		24-Mar-29		1033 d	SYSTEM	
SN:P1511	HRS	10758.2							
	AFL	5733							
	APH	5790	1200		6990		892		
PROC. REF: AMM 24-34-01PROC. REF: AMM 24-34-01									
24-34-01-960-001-A00	APU - DISCARD APU STARTER/GENERATOR BRUSHES								Service ATA:24
	MOS/MSC	11-Mar-17	N/A						
	HRS	2952.1							
	APUS	2686							
PROC. REF: AMM 24-34-01PROC. REF: AMM 24-34-01									
24-35-01-720-001-A00	FUNCTIONALLY CHECK BACK-UP BATTERY - NOSE EMERGENCY-ELECTRICAL EQUIPMENT								Service ATA:24
PN:501-1228-04	MOS	16-Feb-26	6 (+15d/-15d)		16-Aug-26	31-Aug-26	82 d (+15)		
SN:80329	HRS	11064.1							
	AFL	5912							
PROC. REF: AMM 24-35-01PROC. REF: AMM 24-35-01									
24-35-01-900-001-A00	RESTORE (REPLACEMENT) OF NOSE EMERGENCY-ELECTRICAL EQUIPMENT, BACK-UP BATTERY								Service ATA:24
PN:501-1228-04	MOS	17-Oct-25	12		17-Oct-26		144 d	SYSTEM	
SN:80329	HRS	10913.9							
	AFL	5820							
			Restoration Date:: 17-Oct-25						
PROC. REF: AMM 24-35-01PROC. REF: AMM 24-35-01									
24-36-01-610-001-A00	SERVICE (REPLENISH) NO.1 NOSE MARATHON MAIN BATTERYNOTE: IF INSTALLED								Service ATA:24
PN:442CH1	MOS/MSC		N/A						
SN:A03650	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 24 - ELECTRICAL POWER									
PROC. REF: AMM 24-36-01PROC. REF: AMM 24-36-01									
24-36-01-610-001-A00	SERVICE (REPLENISH) NO.2 NOSE MARATHON MAIN BATTERYNOTE: IF INSTALLED								Service ATA:24
PN:442CH1	MOS/MSC		N/A						
SN:T06718	HRS								
	AFL								
PROC. REF: AMM 24-36-01PROC. REF: AMM 24-36-01									
24-36-01-900-001-A00	SERVICE (OVERHAUL) NO.1 NOSE SAFT MAIN BATTERYNOTE: IF INSTALLED								Service ATA:24
PN:442CH1	MOS	17-Oct-25	12		17-Oct-26		144 d	RESTORE	
SN:A03650	HRS	10913.9	1000		11913.9		637.6		
	AFL	5820							
PROC. REF: AMM 24-36-01PROC. REF: AMM 24-36-01									
24-36-01-900-001-A00	SERVICE (OVERHAUL) NO.2 NOSE SAFT MAIN BATTERYNOTE: IF INSTALLED								Service ATA:24
PN:442CH1	MOS	17-Oct-25	12		17-Oct-26		144 d	RESTORE	
SN:T06718	HRS	10913.9	1000		11913.9		637.6		
	AFL	5820							
PROC. REF: AMM 24-36-01PROC. REF: AMM 24-36-01									
24-60-00-710-001-A00 S	OPERATIONALLY CHECK ELECTRICAL EMERGENCY TRANSFER CIRCUIT								Service ATA:24
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6016
PROC. REF: AMM 24-60-00PROC. REF: AMM 24-60-00									
24-60-00-710-002-A00 S	OPERATIONALLY CHECK ELECTRICAL EMERGENCY ABNORMAL ALARM								Service ATA:24
	MOS/MSC	17-Oct-25	O/C						
	HRS	10913.9							
	AFL	5820							
									PKG:5002
PROC. REF: AMM 24-60-00PROC. REF: AMM 24-60-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 24 - ELECTRICAL POWER									
240000-0101		OVERH P MODULE -CONTROL,ELECTRIC SYS,OVER HEAD PANEL ASSEMBLY						Component	ATA:24
PN:135-14918-401	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:0000147353	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 24-00-01PROC. REF: AMM 24-00-01									
242103-0101		PAX STATIC ASSY, FUSLG CTL I INVERTER						Component	ATA:24
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
242104-0101		OVERH P MODULE -ILLUMINATED PANEL,IFE/PC POWER,COCKPIT ASSEMBLY						Component	ATA:24
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
243101-0201		LH OUTBOARD (NO.1) GENERATOR POWER UNIT						Component	ATA:24
PN:30086-011	MOS/MSC	14-Jun-21	O/C	TSO 9					
SN:Y10441	HRS	9586.9		TSO 0					
	AFL	5110		TSO 0					
PROC. REF: AMM 24-31-01PROC. REF: AMM 24-31-01									
243101-0202		LH INBOARD (NO.3) GENERATOR POWER UNIT						Component	ATA:24
PN:30086-011	MOS/MSC	09-Apr-26	O/C	TSO 0					
SN:Y10505	HRS	11166.4		TSO 0					
	AFL	5961		TSO 0					
PROC. REF: AMM 24-31-01PROC. REF: AMM 24-31-01									
243101-0203		RH INBOARD (NO.2) GENERATOR POWER UNIT						Component	ATA:24
PN:30086-011	MOS/MSC	27-Jan-25	O/C	TSO 0					
SN:YOO96	HRS	10679.6		TSO 0					
	AFL	5685		TSO 0					
PROC. REF: AMM 24-31-01PROC. REF: AMM 24-31-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 24 - ELECTRICAL POWER									
243101-0204	RH OUTBOARD (NO.4) GENERATOR POWER UNIT							Component	ATA:24
PN:30086-011	MOS/MSC	18-Jul-24	O/C	TSO 0					
SN:99398	HRS	10519.2		TSO 0					
	AFL	5604		TSO 0					
PROC. REF: AMM 24-31-01PROC. REF: AMM 24-31-01									
243102-0201	LH CSL (GCU 1) GENERATOR CONTROL-ELECTRICAL EOUIPMENT,CONSOLE,COCKPIT UNIT							Component	ATA:24
PN:51545-002A	MOS/MSC	26-Jan-23	O/C						
SN:P1747	HRS	10069.5							
	AFL	5348							
PROC. REF: AMM 24-31-02PROC. REF: AMM 24-31-02									
243102-0202	LH CSL (GCU 3) GENERATOR CONTROL-ELECTRICAL EOUIPMENT,CONSOLE,COCKPIT UNIT							Component	ATA:24
PN:51545-002A	MOS/MSC	26-Jan-23	O/C						
SN:P1766	HRS	10069.5							
	AFL	5348							
PROC. REF: AMM 24-31-02PROC. REF: AMM 24-31-02									
243102-0203	RH CSL (GCU 2) GENERATOR CONTROL-ELECTRICAL EOUIPMENT,CONSOLE,COCKPIT UNIT							Component	ATA:24
PN:51545-002A	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 24-31-02PROC. REF: AMM 24-31-02									
243102-0204	RH CSL (GCU 4) GENERATOR CONTROL-ELECTRICAL EOUIPMENT,CONSOLE,COCKPIT UNIT							Component	ATA:24
PN:51545-002A	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 24-31-02PROC. REF: AMM 24-31-02									
243401-0101	APU STARTER GENERATOR-400A/28VDC,APU UNIT							Component	ATA:24
PN:23080-013A	MOS/MSC	27-Mar-25	O/C	TSO 0					
SN:P1511	HRS	10758.2		TSO 0					
	AFL	5733		TSO 0					
PROC. REF: AMM 24-34-01, AMM 24-34-01PROC. REF: AMM 24-34-01, AMM 24-34-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 24 - ELECTRICAL POWER									
243402-0101		CREW CAB GCU - GENERATOR CONTROL UNIT						Component	ATA:24
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 24-34-02PROC. REF: AMM 24-34-02									
243501-0101		NOSE EMERGENCY-ELECTRICAL EQUIPMENT, BACK-UP BATTERY						Component	ATA:24
PN:501-1228-04	MOS/MSC	11-Jan-23	O/C	TSR 0					
SN:80329	HRS	10066.9		TSR 0					
	AFL	5346		TSR 0					
PROC. REF: AMM 24-35-01PROC. REF: AMM 24-35-01									
243502-0101		NOSE MODULE -RELAY BOX,BATTERY BACKUP,ELECTRONIC COMPARTMENT ASSEMBLY						Component	ATA:24
PN:135-08601-401	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:0000139930	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 24-35-02PROC. REF: AMM 24-35-02									
243601-0101		NO.1 NOSE 44AH, NI-CD BATTERY						Component	ATA:24
PN:442CH1	MOS/MSC	29-Jun-23	O/C	TSO 0					
SN:A03650	HRS	10161.5		TSO 0					
	AFL	5401		TSO 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
243601-0102		NO.2 NOSE 44AH, NI-CD BATTERY						Component	ATA:24
PN:442CH1	MOS/MSC	29-Jun-23	O/C	TSO 0					
SN:T06718	HRS	10161.5		TSO 0					
	AFL	5401		TSO 0					
PROC. REF: AMM 24-36-01PROC. REF: AMM 24-36-01									
243602-0101		NOSE BATTERY 1 RELAY BOX- ASSEMBLY						Component	ATA:24
PN:145-31116-405	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:0000146833	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 24-36-02PROC. REF: AMM 24-36-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 24 - ELECTRICAL POWER									
243602-0102		NOSE BATTERY 2 RELAY BOX- ASSEMBLY						Component	ATA:24
PN:145-31118-407	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:0000138185	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 24-36-03PROC. REF: AMM 24-36-03									
246005-0101		LEFT DC DISTRIBUTION BOX						Component	ATA:24
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 24-65-00PROC. REF: AMM 24-65-00									
246005-0102		RIGHT DC DISTRIBUTION BOX						Component	ATA:24
PN:135-18756-403	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:0000173484	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 24-65-01PROC. REF: AMM 24-65-01									
ATA 25 - EQUIPMENT/FURNISHINGS									
25-11-01-140-001-A00 S		RESTORE (CLEANING) FLIGHT CREW SEATS LOCKING SYSTEM						Service	ATA:25
	MOS	17-Oct-25	12 (+15d/-15d)				LOW UTILIZATION		
	HRS	10913.9	500 (+20/-20)						
	AFL	5820							
									PKG:5002
PROC. REF: AMM 25-11-01PROC. REF: AMM 25-11-01									
25-11-01-220-001-A00 S		INSPECT (DETAILED INSPECTION) COCKPIT SEATS FOR SECURITY OF ATTACHMENT TO THE TRACK, INCLUDING RESTRAINT SYSTEM (SEAT BELT).						Service	ATA:25
	MOS	29-Jun-23	48 (+15d/-15d)				LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 25-11-01PROC. REF: AMM 25-11-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
25-21-00-212-001-A00 S	INSPECT (GENERAL VISUAL) PASSENGER CABIN SEATS (FABRIC, COVER, SAFETY BELT, SEAT MOVEMENT AND ATTACHMENTS TO TRACK)							Service	ATA:25
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 25-21-05PROC. REF: AMM 25-21-05									
25-21-00-220-002-A00 S	INSPECT (DETAILED INSPECTION) FLIGHT ATTENDANT SEATS HARNESS, INERTIAL REEL FOR CONDITION AND THE SEAT BOTTOM FOR FREEDOM OF MOVEMENT AND RETURNING BACK TO UPRIGHT POSITION. (NOTE: IF INSTALLED)							Service	ATA:25
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 25-21-02PROC. REF: AMM 25-21-02									
25-26-00-212-001-A00 S	INSPECT (GENERAL VISUAL) CREDENZA, CLOSETS AND ENTERTAINMENT CABINET FOR INTEGRITY AND SECURITY.							Service	ATA:25
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 25-26-00PROC. REF: AMM 25-26-00									
25-27-02-211-001-A00 S	VISUALLY CHECK LAVATORY/BAGGAGE DOOR SEALING FOR CONDITION, INTEGRITY AND SECURITY.							Service	ATA:25
	MOS	17-Oct-25	12 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	500 (+20/-20)						
	AFL	5820							
									PKG:5002
PROC. REF: AMM 25-27-02PROC. REF: AMM 25-27-02									
25-30-06-212-001-A00 S	INSPECT (GENERAL VISUAL) FORWARD GALLEY STRUCTURE LOWER ATTACHMENT POINTS (ON THE TRACKS).							Service	ATA:25
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 25-30-01PROC. REF: AMM 25-30-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
25-40-04-212-001-A00 S	INSPECT (GENERAL VISUAL) LAVATORY STRUCTURE LOWER ATTACHMENT POINTS.							Service	ATA:25
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 25-40-01PROC. REF: AMM 25-40-01									
25-60-01-212-001-A00	INSPECT (GENERAL VISUAL) FIRST AID KIT FOR CONDITION AND VALIDATION.							Service	ATA:25
PN:AFAK 1.0	MOS/MSC	17-Oct-25	DUE		31-Oct-26 (M)		158 d	SYSTEM	
SN:110220005	HRS	10913.9							
	AFL	5820							
			Expiry Date: : 31-Oct-26						
PROC. REF: AMM 25-60-01PROC. REF: AMM 25-60-01									
25-60-02-900-001-ALL	RESTORE ATTEND 1 EMERGENCY EQUIPMENT LIFE JACKET (25-60-02-900-001-A00/A01/A02/A03/A04/A05)							Service	ATA:25
PN:P01074-201	MOS/MSC	31-Oct-20	DUE		01-Aug-30 (M)		1528 d	VENDOR RECOMMENDATION	
SN:20080790056	HRS	9463.7							
	AFL	5043							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
25-60-02-900-001-ALL	RESTORE COPILOT EMERGENCY EQUIPMENT LIFE JACKET (25-60-02-900-001-A00/A01/A02/A03/A04/A05)							Service	ATA:25
PN:P01074-201	MOS/MSC	31-Oct-20	DUE		01-Aug-30 (M)		1528 d	VENDOR RECOMMENDATION	
SN:20080790054	HRS	9463.7							
	AFL	5043							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
25-60-02-900-001-ALL	RESTORE OBSERVER EMERGENCY EQUIPMENT LIFE JACKET (25-60-02-900-001-A00/A01/A02/A03/A04/A05)							Service	ATA:25
PN:P01074-201	MOS/MSC	31-Oct-20	DUE		01-Aug-30 (M)		1528 d	VENDOR RECOMMENDATION	
SN:20080790055	HRS	9463.7							
	AFL	5043							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
25-60-02-900-001-ALL	RESTORE PAX 1 EMERGENCY EQUIPMENT LIFE JACKET (25-60-02-900-001-A00/A01/A02/A03/A04/A05)								Service ATA:25
PN:P01074-201	MOS/MSC	31-Oct-20	DUE		01-Aug-30 (M)		1528 d	VENDOR RECOMMENDATION	
SN:20080790057	HRS	9463.7							
	AFL	5043							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
25-60-02-900-001-ALL	RESTORE PAX 10 EMERGENCY EQUIPMENT LIFE JACKET (25-60-02-900-001-A00/A01/A02/A03/A04/A05)								Service ATA:25
PN:P01074-201	MOS/MSC	31-Oct-20	DUE		01-Aug-30 (M)		1528 d	VENDOR RECOMMENDATION	
SN:20080790107	HRS	9463.7							
	AFL	5043							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
25-60-02-900-001-ALL	RESTORE PAX 11 EMERGENCY EQUIPMENT LIFE JACKET (25-60-02-900-001-A00/A01/A02/A03/A04/A05)								Service ATA:25
PN:63600-105	MOS/MSC	09-Jun-17	DUE		09-Jun-27 (M)		379 d	VENDOR RECOMMENDATION	
SN:L2190735	HRS								
	AFL								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
25-60-02-900-001-ALL	RESTORE PAX 12 EMERGENCY EQUIPMENT LIFE JACKET (25-60-02-900-001-A00/A01/A02/A03/A04/A05)								Service ATA:25
PN:63600-105	MOS/MSC	09-Jun-17	DUE		09-Jun-27 (M)		379 d	VENDOR RECOMMENDATION	
SN:L2190733	HRS								
	AFL								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
25-60-02-900-001-ALL	RESTORE PAX 13 EMERGENCY EQUIPMENT LIFE JACKET (25-60-02-900-001-A00/A01/A02/A03/A04/A05)								Service ATA:25
PN:63600-105	MOS/MSC	13-Feb-20	DUE		30-Nov-29 (M)		1284 d	VENDOR RECOMMENDATION	
SN:L4939550	HRS	9310.8							
	AFL	4969							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
25-60-02-900-001-ALL	RESTORE PAX 2 EMERGENCY EQUIPMENT LIFE JACKET (25-60-02-900-001-A00/A01/A02/A03/A04/A05)								Service ATA:25
PN:P01074-201	MOS/MSC	31-Oct-20	DUE		01-Aug-30 (M)		1528 d	VENDOR RECOMMENDATION	
SN:20080790058	HRS	9463.7							
	AFL	5043							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
25-60-02-900-001-ALL	RESTORE PAX 3 EMERGENCY EQUIPMENT LIFE JACKET (25-60-02-900-001-A00/A01/A02/A03/A04/A05)								Service ATA:25
PN:P01074-201	MOS/MSC	31-Oct-20	DUE		01-Aug-30 (M)		1528 d	VENDOR RECOMMENDATION	
SN:20080790059	HRS	9463.7							
	AFL	5043							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
25-60-02-900-001-ALL	RESTORE PAX 4 EMERGENCY EQUIPMENT LIFE JACKET (25-60-02-900-001-A00/A01/A02/A03/A04/A05)								Service ATA:25
PN:P01074-201	MOS/MSC	31-Oct-20	DUE		01-Aug-30 (M)		1528 d	VENDOR RECOMMENDATION	
SN:20080790101	HRS	9463.7							
	AFL	5043							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
25-60-02-900-001-ALL	RESTORE PAX 5 EMERGENCY EQUIPMENT LIFE JACKET (25-60-02-900-001-A00/A01/A02/A03/A04/A05)								Service ATA:25
PN:P01074-201	MOS/MSC	31-Oct-20	DUE		01-Aug-30 (M)		1528 d	VENDOR RECOMMENDATION	
SN:20080790102	HRS	9463.7							
	AFL	5043							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
25-60-02-900-001-ALL	RESTORE PAX 6 EMERGENCY EQUIPMENT LIFE JACKET (25-60-02-900-001-A00/A01/A02/A03/A04/A05)								Service ATA:25
PN:P01074-201	MOS/MSC	31-Oct-20	DUE		01-Aug-30 (M)		1528 d	VENDOR RECOMMENDATION	
SN:20080790103	HRS	9463.7							
	AFL	5043							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
25-60-02-900-001-ALL	RESTORE PAX 7 EMERGENCY EQUIPMENT LIFE JACKET (25-60-02-900-001-A00/A01/A02/A03/A04/A05)								Service ATA:25
PN:P01074-201	MOS/MSC	31-Oct-20	DUE		01-Aug-30 (M)		1528 d	VENDOR RECOMMENDATION	
SN:20080790104	HRS	9463.7							
	AFL	5043							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
25-60-02-900-001-ALL	RESTORE PAX 8 EMERGENCY EQUIPMENT LIFE JACKET (25-60-02-900-001-A00/A01/A02/A03/A04/A05)								Service ATA:25
PN:P01074-201	MOS/MSC	31-Oct-20	DUE		01-Aug-30 (M)		1528 d	VENDOR RECOMMENDATION	
SN:20080790105	HRS	9463.7							
	AFL	5043							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
25-60-02-900-001-ALL	RESTORE PAX 9 EMERGENCY EQUIPMENT LIFE JACKET (25-60-02-900-001-A00/A01/A02/A03/A04/A05)								Service ATA:25
PN:P01074-201	MOS/MSC	31-Oct-20	DUE		01-Aug-30 (M)		1528 d	VENDOR RECOMMENDATION	
SN:20080790106	HRS	9463.7							
	AFL	5043							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
25-60-02-900-001-ALL	RESTORE PILOT EMERGENCY EQUIPMENT LIFE JACKET (25-60-02-900-001-A00/A01/A02/A03/A04/A05)								Service ATA:25
PN:P01074-201	MOS/MSC	31-Oct-20	DUE		01-Aug-30 (M)		1528 d	VENDOR RECOMMENDATION	
SN:20080790053	HRS	9463.7							
	AFL	5043							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
25-60-04-212-001-A00 S	INSPECT (GENERAL VISUAL) COCKPIT ESCAPE ROPE(ZONES 225/226)								Service ATA:25
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 25-60-07PROC. REF: AMM 25-60-07									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
25-60-05-212-001-A00 S	INSPECT (GENERAL VISUAL) OF LIFELINE FOR INTEGRITY AND GENERAL CONDITIONS (ZONE 252) (IF INSTALLED)							Service	ATA:25
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 25-60-03PROC. REF: AMM 25-60-03									
25-61-00-212-001-A00	INSPECT (GENERAL VISUAL) EMERGENCY LOCATOR TRANSMITTER FOR CONDITION PROPER INSTALLATION BATTERY CORROSION AND LEAKAGE							Service	ATA:25
	MOS	17-Oct-25	12 (+15d/-15d)		17-Oct-26	01-Nov-26	144 d (+15)	SYSTEM	
	HRS	10913.9							
	AFL	5820							
PROC. REF: AMM 25-61-00, FAR FAR 91.207PROC. REF: AMM 25-61-00, FAR FAR 91.207									
25-61-00-710-001-A00	OPERATIONAL CHECK EMERGENCY LOCATOR TRANSMITTER SYSTEM - PROPER OPERATION- CRASH SWITCH OPERATION							Service	ATA:25
	MOS	17-Oct-25	12 (+15d/-15d)		17-Oct-26	01-Nov-26	144 d (+15)	SYSTEM	
	HRS	10913.9							
	AFL	5820							
PROC. REF: AMM 25-61-00, AMM 25-61-00, AMM 25-61-00, FAR FAR 91.207PROC. REF: AMM 25-61-00, AMM 25-61-00, AMM 25-61-00, FAR FAR 91.207									
25-62-03-801 U	DISCARD NO. 1 LIFE RAFT EMERGENCY LOCATOR TRANSMITTER (ELT) BEACON BATTERY							Service	ATA:25
PN:K2-01-0003-001	MOS/MSC	30-Mar-22	DUE		01-Jan-28 (M)		585 d		
SN:UNKNOWN	HRS	9837							
	AFL	5241							
25-63-00-710-001-A00	OPERATIONALLY CHECK PORTABLE EMERGENCY LOCATOR TRANSMITTER SYSTEM NOTE: IF INSTALLED							Service	ATA:25
	MOS/MSC	30-Aug-12	N/A						
	HRS	6158.5							
	AFL	3279							
PROC. REF: AMM 25-63-02PROC. REF: AMM 25-63-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
25-63-01-900-001-A01		RESTORE (OVERHAUL) WINSLOW (VACUUM PACKED) NO.2 LIFE RAFT ASSEMBLYNOTE: FROM THE MANUFACTURE DATE OR LAST RESTORATION.NOTE: IF INSTALLED.							Service ATA:25
PN:R0103A105	MOS	10-Jan-24	36		10-Jan-27		229 d	SYSTEM	
SN:TQ09158	HRS	10396.8							
	AFL	5532							
			Manufacture Date:: 10-Jan-24						
PROC. REF: AMM 25-60-02, AMM 25-60-05PROC. REF: AMM 25-60-02, AMM 25-60-05									
25-63-01-900-001-A01		RESTORE (OVERHAUL) WINSLOW (VACUUM PACKED) NO.1 LIFE RAFT ASSEMBLYNOTE: FROM THE MANUFACTURE DATE OR LAST RESTORATION.NOTE: IF INSTALLED.							Service ATA:25
PN:PN	MOS/MSC	27-Mar-25	N/A						
SN:UNKNOWN	HRS	10758.2							
	AFL	5733							
PROC. REF: AMM 25-60-02, AMM 25-60-05PROC. REF: AMM 25-60-02, AMM 25-60-05									
25-63-02-960-001-A00		DISCARD PORTABLE ELT BATTERY ELTA PN: 05N62123 NOTE: PORTABLE ELT BATTERY CHANGE IN ACCORDANCE WITH MANUFACTURER'S DATA PLATE EXPIRATION DATE OR IN ACCORDANCE WITH LOCAL REGULATORY AUTHORITY REQUIREMENTS							Service ATA:25
	MOS/MSC	30-Aug-12	O/C						
	HRS	6158.5							
	AFL	3279							
PROC. REF: AMM 25-63-03PROC. REF: AMM 25-63-03									
251101-0101		PILOT ASSY-PILOT SEAT							Component ATA:25
PN:1471611-05	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:06T2116	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 25-11-01PROC. REF: AMM 25-11-01									
251101-0102		COPILOT ASSY-CO-PILOT SEAT							Component ATA:25
PN:1471610-05	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:06T3595	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 25-11-01PROC. REF: AMM 25-11-01									

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
251102-0101	OBSERVER ASSEMBLY SEAT							Component	ATA:25
PN:7222001-101	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:104607	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 25-11-02	PROC. REF: AMM 25-11-02								
252102-0101	FLIGHT ATTENDANT SEAT ASSY							Component	ATA:25
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 25-21-02	PROC. REF: AMM 25-21-02								
253103-0101	GALLEY CABINET ELECTRICAL OVEN							Component	ATA:25
PN:400-1191-01-R	MOS/MSC	24-Feb-16	O/C	TSR 0					
SN:05-08-37415	HRS	7661.9		TSR 0					
	AFL	4095		TSR 0					
PROC. REF: AMM 25-31-03	PROC. REF: AMM 25-31-03								
253104-0101	GALLEY CABINET MICROWAVE OVEN							Component	ATA:25
PN:400-1860-01	MOS/MSC	22-Jan-14	O/C	TSR 5					
SN:06-11-39938	HRS	6836.5		TSR 0					
	AFL	3679		TSR 0					
PROC. REF: AMM 25-31-04	PROC. REF: AMM 25-31-04								
253105-0101	GALLEY ELECTRICAL COFFEE MAKER							Component	ATA:25
PN:400-1749-10	MOS/MSC	01-Sep-17	O/C	TSR 0					
SN:07-03-40593	HRS	8284.1		TSR 0					
	AFL	4446		TSR 0					
PROC. REF: AMM 25-31-05	PROC. REF: AMM 25-31-05								
253109-0101	GALLEY UNIT, REFRIGERATOR UNIT							Component	ATA:25
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM NO REF	PROC. REF: AMM NO REF								

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
253110-0701 U		GALLEY SWITCHING PANEL						Component	ATA:25
PN:990-9105-015	MOS/MSC	25-Apr-17	O/C	TSR 1					
SN:06070030259	HRS	8136.8		TSR 0					
	AFL	4367		TSR 0					
253205-0101		OVEN REAR CABINET ,GALLEY CONTROL PANEL						Component	ATA:25
PN:400-1377-01	MOS/MSC	19-Sep-13	O/C	TSN 0					
SN:07-04-40940	HRS	6680.2		TSN 0					
	AFL	3597		TSN 0					
PROC. REF: AMM 25-31-03PROC. REF: AMM 25-31-03									
255006-0101		BAGGAGE COMPARTMENT REAR BULKHEAD PANEL ASSY						Component	ATA:25
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
256001-0101		FIRST AID KIT						Component	ATA:25
PN:AFAK 1.0	MOS/MSC	08-Sep-25	O/C	TSO 0					
SN:110220005	HRS	10880		TSO 0					
	AFL	5803		TSO 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
256001-0701 U		DEFIBRILLATOR AND AED PREP KIT						Component	ATA:25
PN:AED FRX	MOS/MSC	29-Jan-25	DUE	TSN 77, TSR 24	30-Nov-26 (M)		188 d		
SN:B12K-00297	HRS	10685.3		TSN 1947.4, TSR 615.8					
	AFL	5688		TSN 1002, TSR 340					
			Expiry Date: : 30-Nov-26						
256002-0101		PILOT EMERGENCY EQUIPMENT LIFE JACKET						Component	ATA:25
PN:P01074-201	MOS/MSC	31-Oct-20	O/C	TSN 0					
SN:20080790053	HRS	9463.7		TSN 0					
	AFL	5043		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
256002-0102	COPILOT EMERGENCY EQUIPMENT LIFE JACKET							Component	ATA:25
PN:P01074-201	MOS/MSC	31-Oct-20	O/C	TSN 0					
SN:20080790054	HRS	9463.7		TSN 0					
	AFL	5043		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
256002-0103	OBSERVER EMERGENCY EQUIPMENT LIFE JACKET							Component	ATA:25
PN:P01074-201	MOS/MSC	31-Oct-20	O/C	TSN 0					
SN:20080790055	HRS	9463.7		TSN 0					
	AFL	5043		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
256002-0104	ATTEND 1 EMERGENCY EQUIPMENT LIFE JACKET							Component	ATA:25
PN:P01074-201	MOS/MSC	31-Oct-20	O/C	TSN 0					
SN:20080790056	HRS	9463.7		TSN 0					
	AFL	5043		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
256002-7101	PAX 1 EMERGENCY EQUIPMENT LIFE JACKET							Component	ATA:25
PN:P01074-201	MOS/MSC	31-Oct-20	O/C	TSN 0					
SN:20080790057	HRS	9463.7		TSN 0					
	AFL	5043		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
256002-7102	PAX 2 EMERGENCY EQUIPMENT LIFE JACKET							Component	ATA:25
PN:P01074-201	MOS/MSC	31-Oct-20	O/C	TSN 0					
SN:20080790058	HRS	9463.7		TSN 0					
	AFL	5043		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
256002-7103	PAX 3 EMERGENCY EQUIPMENT LIFE JACKET							Component	ATA:25
PN:P01074-201	MOS/MSC	31-Oct-20	O/C	TSN 0					
SN:20080790059	HRS	9463.7		TSN 0					
	AFL	5043		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
256002-7104	PAX 4 EMERGENCY EQUIPMENT LIFE JACKET							Component	ATA:25
PN:P01074-201	MOS/MSC	31-Oct-20	O/C	TSN 0					
SN:20080790101	HRS	9463.7		TSN 0					
	AFL	5043		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
256002-7105	PAX 5 EMERGENCY EQUIPMENT LIFE JACKET							Component	ATA:25
PN:P01074-201	MOS/MSC	31-Oct-20	O/C	TSN 0					
SN:20080790102	HRS	9463.7		TSN 0					
	AFL	5043		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
256002-7106	PAX 6 EMERGENCY EQUIPMENT LIFE JACKET							Component	ATA:25
PN:P01074-201	MOS/MSC	31-Oct-20	O/C	TSN 0					
SN:20080790103	HRS	9463.7		TSN 0					
	AFL	5043		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
256002-7107	PAX 7 EMERGENCY EQUIPMENT LIFE JACKET							Component	ATA:25
PN:P01074-201	MOS/MSC	31-Oct-20	O/C	TSN 0					
SN:20080790104	HRS	9463.7		TSN 0					
	AFL	5043		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
256002-7108	PAX 8 EMERGENCY EQUIPMENT LIFE JACKET							Component	ATA:25
PN:P01074-201	MOS/MSC	31-Oct-20	O/C	TSN 0					
SN:20080790105	HRS	9463.7		TSN 0					
	AFL	5043		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
256002-7109	PAX 9 EMERGENCY EQUIPMENT LIFE JACKET							Component	ATA:25
PN:P01074-201	MOS/MSC	31-Oct-20	O/C	TSN 0					
SN:20080790106	HRS	9463.7		TSN 0					
	AFL	5043		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
256002-7110	PAX 10 EMERGENCY EQUIPMENT LIFE JACKET							Component	ATA:25
PN:P01074-201	MOS/MSC	31-Oct-20	O/C	TSN 0					
SN:20080790107	HRS	9463.7		TSN 0					
	AFL	5043		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
256002-7111	PAX 11 EMERGENCY EQUIPMENT LIFE JACKET							Component	ATA:25
PN:63600-105	MOS/MSC	04-Jan-19	O/C						
SN:L2190735	HRS	8912.5							
	AFL	4764							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
256002-7112	PAX 12 EMERGENCY EQUIPMENT LIFE JACKET							Component	ATA:25
PN:63600-105	MOS/MSC	04-Jan-19	O/C						
SN:L2190733	HRS	8912.5							
	AFL	4764							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
256002-7113	PAX 13 EMERGENCY EQUIPMENT LIFE JACKET							Component	ATA:25
PN:63600-105	MOS/MSC	13-Feb-20	O/C	TSN 3					
SN:L4939550	HRS	9310.8		TSN 0					
	AFL	4969		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
256003-7101	NO. 1 LIFE RAFT							Component	ATA:25
PN:PN	MOS/MSC	27-Mar-25	O/C						
SN:UNKNOWN	HRS	10758.2							
	AFL	5733							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
256003-7102	NO. 2 LIFE RAFT							Component	ATA:25
PN:R0103A105	MOS/MSC	10-Jan-24	O/C						
SN:TQ09158	HRS	10396.8							
	AFL	5532							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
256100-0101		CREW CAB MODULE -ELT ASSEMBLY							Component ATA:25
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 25-61-01PROC. REF: AMM 25-61-01									
256104-0101		ELT - RADIO/NAVIGATION SYS, EMERGENCY LOCATOR TRANSMITTER							Component ATA:25
PN:ELT97A2560000000	MOS/MSC	18-Jan-21	O/C	TSN 211					
SN:3582	HRS	9506.9							
	AFL	5061							
PROC. REF: AMM 25-61-01PROC. REF: AMM 25-61-01									
256104-0101D		DISCARD EMERGENCY LOCATOR TRANSMITTER (ELT) BATTERY (NOTE: IN ACCORDANCE WITH MANUFACTURERS DATAPLATE EXPIRATION DATE OR LOCAL REGULATORY AUTHORITY REQUIREMENTS).							Service ATA:25
PN:PN-UNKNOWN	MOS/MSC	16-Aug-24	DUE		31-Aug-29 (M)		1193 d	SYSTEM	
SN:UNKNOWN	HRS	10541.4							
	AFL	5613							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
256104-0102		EMERGENCY LOCATOR TRANSMITTER (ELT) BATTERY							Component ATA:25
PN:PN-UNKNOWN	MOS/MSC	18-Jan-21	C/C						
SN:UNKNOWN	HRS	9506.9							
	AFL	5061							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
256203-0701 U		NO. 1 LIFE RAFT EMERGENCY LOCATOR TRANSMITTER (ELT) BEACON							Component ATA:25
PN:P3-03-0041-101	MOS/MSC	19-Feb-21	O/C						
SN:141467	HRS	9508.9							
	AFL	5061							
256203-0702 U		NO. 2 LIFE RAFT EMERGENCY LOCATOR TRANSMITTER (ELT) BEACON							Component ATA:25
PN:PN	MOS/MSC	10-Jan-24	O/C						
SN:UNKNOWN	HRS	10396.8							
	AFL	5532							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
256203-0801 U		NO. 1 LIFE RAFT EMERGENCY LOCATOR TRANSMITTER (ELT) BEACON BATTERY						Component	ATA:25
PN:K2-01-0003-001	MOS/MSC	30-Mar-22	H/T	TSN 0					
SN:UNKNOWN	HRS	9837		TSN 0					
	AFL	5241		TSN 0					
256203-0802 U		NO. 2 LIFE RAFT EMERGENCY LOCATOR TRANSMITTER (ELT) BEACON BATTERY						Component	ATA:25
PN:PN	MOS/MSC	19-Feb-21	H/T	TSN 0					
SN:UNKNOWN	HRS	9508.9		TSN 0					
	AFL	5061		TSN 0					
259001-0101		COCKPIT TOUCH SCREEN, REMOTE - TSU9600 UNIT						Component	ATA:25
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
259500-0201		REAR ELT ANTENNA						Component	ATA:25
PN:S65-1231	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:160-1046	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 25-61-03PROC. REF: AMM 25-61-03									
259502-7302		ASSY- AFT DIVAN SEAT						Component	ATA:25
PN:2523.714.01-13	MOS/MSC	14-Aug-13	O/C						
SN:070322-11	HRS	6643.4							
	AFL	3572							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
259502-7304		NO.1 DOUBLE, SERIES 200 SEAT						Component	ATA:25
PN:2524.551.01-501A	MOS/MSC	14-Aug-13	O/C						
SN:070322-07	HRS	6643.4							
	AFL	3572							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
259502-7305		NO. 2 DOUBLE, SERIES 200 SEAT						Component	ATA:25
PN:2524.551.01-505B	MOS/MSC	14-Aug-13	O/C						
SN:070322-08	HRS	6643.4							
	AFL	3572							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
259502-7306		FWD DIVAN SEAT						Component	ATA:25
PN:2523.714.01-11	MOS/MSC	14-Aug-13	O/C						
SN:070322-09	HRS	6643.4							
	AFL	3572							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
259502-7307		MID DIVAN SEAT						Component	ATA:25
PN:2523.714.01-12	MOS/MSC	14-Aug-13	O/C						
SN:070322-10	HRS	6643.4							
	AFL	3572							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
259502-7308		SINGLE SERIES 200 SEAT						Component	ATA:25
PN:2524.550.01-501A	MOS/MSC	14-Aug-13	O/C						
SN:070322-01	HRS	6643.4							
	AFL	3572							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
259502-7309		SINGLE SERIES 200 SEAT						Component	ATA:25
PN:2524.550.01-509B	MOS/MSC	14-Aug-13	O/C						
SN:070322-03	HRS	6643.4							
	AFL	3572							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
259502-7310		SINGLE SERIES 200 SEAT						Component	ATA:25
PN:2524.550.01-502B	MOS/MSC	14-Aug-13	O/C						
SN:070322-02	HRS	6643.4							
	AFL	3572							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
259502-7311		SINGLE SERIES 200 SEAT						Component	ATA:25
PN:2524.550.01-515A	MOS/MSC	14-Aug-13	O/C						
SN:070322-04	HRS	6643.4							
	AFL	3572							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
259502-7312		SINGLE SERIES 200 SEAT						Component	ATA:25
PN:2524.550.01-503A	MOS/MSC	14-Aug-13	O/C						
SN:070322-05	HRS	6643.4							
	AFL	3572							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
259502-7313		SINGLE SERIES 200 SEAT						Component	ATA:25
PN:2524.550.01-501B	MOS/MSC	14-Aug-13	O/C						
SN:070322-06	HRS	6643.4							
	AFL	3572							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
261401-0101		LAVATORY SMOKE DETECTOR						Component	ATA:25
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 26-14-01PROC. REF: AMM 26-14-01									
ATA 26 - FIRE PROTECTION									
26-14-00-710-001-A00 S		OPERATIONALLY CHECK LAVATORY SMOKE DETECTOR (ACTUATING THE SMOKE SENSOR WITH SMOKE) NOTE: IF INSTALLED						Service	ATA:26
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 26 - FIRE PROTECTION									
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6020
PROC. REF: AMM 26-14-01PROC. REF: AMM 26-14-01									
26-14-01-960-001-A00	DISCARD JAMCO LAVATORY SMOKE DETECTOR (IF INSTALLED)								Service ATA:26
	MOS/MSC	25-Sep-07	N/A						
	HRS	0							
	AFL	0							
PROC. REF: AMM 26-14-01PROC. REF: AMM 26-14-01									
26-15-01-140-001-A00 S	RESTORE (CLEANING) BAGGAGE SMOKE DETECTOR CLEANING OF BAGGAGE SMOKE DETECTORS								Service ATA:26
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 26-15-01PROC. REF: AMM 26-15-01									
26-21-00-720-001-A00	FUNCTIONALLY CHECK ENGINE FIRE EXTINGUISHING SYSTEM								Service ATA:26
	MOS	17-Oct-25	36		17-Oct-28		875 d	SYSTEM	
	HRS	10913.9							
	AFL	5820							
PROC. REF: AMM 26-21-00PROC. REF: AMM 26-21-00									
26-21-02-720-001-A00	FUNCTIONALLY CHECK (HYDROSTATIC TEST) LH ENGINE FIRE EXTINGUISHER BOTTLE								Service ATA:26
PN:33600057-5	MOS/MSC	06-Jul-22	O/C						
SN:57143D1	HRS								
	AFL								
			HydroCheck Date: : 06-Jul-22						
PROC. REF: AMM 26-21-02PROC. REF: AMM 26-21-02									
26-21-02-720-001-A00	FUNCTIONALLY CHECK (HYDROSTATIC TEST) RH ENGINE FIRE EXTINGUISHER BOTTLE								Service ATA:26
PN:33600057-5	MOS/MSC	16-Jun-21	O/C						
SN:74313D1	HRS								
	AFL								
			HydroCheck Date: : 16-Jun-21						
PROC. REF: AMM 26-21-02PROC. REF: AMM 26-21-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 26 - FIRE PROTECTION									
26-21-03-720-001-A00	FUNCTIONALLY CHECK L/H ENGINE FIRE EXTINGUISHING BOTTLE PRESSURE SWITCH-NOTE: IF INSTALLED.								Service ATA:26
	MOS	14-Jul-22	60		14-Jul-27		414 d	SYSTEM	
	HRS	9915.8							
	AFL	5271							
PROC. REF: AMM 26-21-03	PROC. REF: AMM 26-21-03								
26-21-03-720-001-A00	FUNCTIONALLY CHECK R/H ENGINE FIRE EXTINGUISHING BOTTLE PRESSURE SWITCH -NOTE: IF INSTALLED.								Service ATA:26
	MOS	29-Jul-21	60		29-Jul-26		64 d	SYSTEM	
	HRS	9631.4							
	AFL	5130							
PROC. REF: AMM 26-21-03	PROC. REF: AMM 26-21-03								
26-21-04-960-001-A00	DISCARD (SERVICE LIFE) NO. 1 LH ENGINE FIRE EXTINGUISHER BOTTLE (A) CARTRIDGE								Service ATA:26
PN:M30903920	MOS	06-Jul-22	72		06-Jul-28		772 d	SERVICE LIFE LIMIT	
SN:08165	HRS								
	AFL								
			Installation Date: : 06-Jul-22						
PROC. REF: AMM 26-21-04	PROC. REF: AMM 26-21-04								
26-21-04-960-001-A00	DISCARD (SERVICE LIFE) NO. 1 RH ENGINE FIRE EXTINGUISHER BOTTLE (B) CARTRIDGE								Service ATA:26
PN:30903920	MOS	18-Jul-21	72		18-Jul-27		418 d	SERVICE LIFE LIMIT	
SN:ESD20H218-001	HRS								
	AFL								
			Installation Date: : 18-Jul-21						
PROC. REF: AMM 26-21-04	PROC. REF: AMM 26-21-04								
26-21-04-960-001-A00	DISCARD (SERVICE LIFE) NO. 2 LH ENGINE FIRE EXTINGUISHER BOTTLE (A) CARTRIDGE								Service ATA:26
PN:M30903920	MOS	06-Jul-22	72		06-Jul-28		772 d	SERVICE LIFE LIMIT	
SN:08093	HRS								
	AFL								
			Installation Date: : 06-Jul-22						
PROC. REF: AMM 26-21-04	PROC. REF: AMM 26-21-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 26 - FIRE PROTECTION									
26-21-04-960-001-A00	DISCARD (SERVICE LIFE) NO. 2 RH ENGINE FIRE EXTINGUISHER BOTTLE (B) CARTRIDGE								Service ATA:26
PN:30903920	MOS	18-Jul-21	72		18-Jul-27		418 d	SERVICE LIFE LIMIT	
SN:ESD20H218-001	HRS								
	AFL								
			Installation Date: : 18-Jul-21						
PROC. REF: AMM 26-21-04PROC. REF: AMM 26-21-04									
26-21-04-960-001-A00-M	DISCARD (LIFE LIMIT) NO. 1 LH ENGINE FIRE EXTINGUISHER BOTTLE (A) CARTRIDGE								Service ATA:26
PN:M30903920	MOS	01-Feb-22	108		01-Feb-31		1712 d	LIFE LIMIT	
SN:08165	HRS								
	AFL								
			Manufacture Date:: 01-Feb-22						
PROC. REF: AMM 26-21-04PROC. REF: AMM 26-21-04									
26-21-04-960-001-A00-M	DISCARD (LIFE LIMIT) NO. 1 RH ENGINE FIRE EXTINGUISHER BOTTLE (B) CARTRIDGE								Service ATA:26
PN:30903920	MOS	01-Jun-21	108		01-Jun-30		1467 d	LIFE LIMIT	
SN:ESD20H218-001	HRS								
	AFL								
			Manufacture Date:: 01-Jun-21						
PROC. REF: AMM 26-21-04PROC. REF: AMM 26-21-04									
26-21-04-960-001-A00-M	DISCARD (LIFE LIMIT) NO. 2 LH ENGINE FIRE EXTINGUISHER BOTTLE (A) CARTRIDGE								Service ATA:26
PN:M30903920	MOS	01-Feb-22	108		01-Feb-31		1712 d	LIFE LIMIT	
SN:08093	HRS								
	AFL								
			Manufacture Date:: 01-Feb-22						
PROC. REF: AMM 26-21-04PROC. REF: AMM 26-21-04									
26-21-04-960-001-A00-M	DISCARD (LIFE LIMIT) NO. 2 RH ENGINE FIRE EXTINGUISHER BOTTLE (B) CARTRIDGE								Service ATA:26
PN:30903920	MOS	01-Jun-21	108		01-Jun-30		1467 d	LIFE LIMIT	
SN:ESD20H218-001	HRS								
	AFL								
			Manufacture Date:: 01-Jun-21						
PROC. REF: AMM 26-21-04PROC. REF: AMM 26-21-04									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 26 - FIRE PROTECTION									
26-21-05-720-001-A00		FUNCTIONALLY CHECK ENGINE FIRE EXTINGUISHING TWO-WAY "TEE" CHECK VALVES							Service ATA:26
	MOS	16-Aug-24	72		16-Aug-30		1543 d	SYSTEM	
	HRS	10541.4	8000		18541.4		7265.1		
	AFL	5613							
PROC. REF: AMM 26-21-05	PROC. REF: AMM 26-21-05								
26-22-00-720-001-A00		FUNCTIONALLY CHECK APU FIRE-EXTINGUISHING SYSTEM (BETWEEN SWITCH AND BOTTLE CONNECTOR) AND VERIFY APU ISOLATION BY APU FUEL SHUTOFF VALVE ACTUATION.							Service ATA:26
	MOS	17-Oct-25	36		17-Oct-28		875 d	SYSTEM	
	HRS	10913.9							
	AFL	5820							
PROC. REF: AMM 26-22-00	PROC. REF: AMM 26-22-00								
26-22-01-720-001-A00		FUNCTIONALLY CHECK (HYDROSTATIC TEST) APU FIRE EXTINGUISHER,REAR APU BOTTLE							Service ATA:26
PN:30100050-5	MOS/MSC	01-Apr-20	O/C						
SN:95144A1	HRS								
	AFL								
			HydroCheck Date: : 01-Apr-20						
PROC. REF: AMM 26-22-01	PROC. REF: AMM 26-22-01								
26-22-02-720-001-A00		FUNCTIONALLY CHECK APU FIRE EXTINGUISHING BOTTLE PRESSURE SWITCH							Service ATA:26
	MOS	29-Jul-21	60		29-Jul-26		64 d	SYSTEM	
	HRS	9631.4							
	AFL	5130							
PROC. REF: AMM 26-22-02	PROC. REF: AMM 26-22-02								
26-22-03-960-001-A00		DISCARD APU FIRE EXTINGUISHING BOTTLE CARTRIDGE (SERVICE LIFE)							Service ATA:26
PN:30903920	MOS	23-Jul-21	72		23-Jul-27		423 d	SERVICE LIFE LIMIT	
SN:ESD19D208-001	HRS								
	AFL								
			Installation Date: : 23-Jul-21						
PROC. REF: AMM 26-22-03	PROC. REF: AMM 26-22-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 26 - FIRE PROTECTION									
26-22-03-960-001-A00-M		DISCARD APU FIRE EXTINGUISHING BOTTLE CARTRIDGE (LIFE LIMIT)							Service ATA:26
PN:30903920	MOS	01-Jul-20	108		01-Jul-29		1132 d	LIFE LIMIT	
SN:ESD19D208-001	HRS								
	AFL								
			Manufacture Date:: 01-Jul-20						
PROC. REF: AMM 26-22-03PROC. REF: AMM 26-22-03									
26-23-00-720-001-A00 S		FUNCTIONALLY CHECK BAGGAGE-COMPARTMENT FIRE EXTINGUISHING SYSTEM (COVERING THE PRESSURE SWITCH, CARTRIDGE, BAGG FIRE EXTING.SWITCH AND ELECTRICAL HARDWARE).							Service ATA:26
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 26-23-00PROC. REF: AMM 26-23-00									
26-23-01-720-001-A00		FUNCTIONALLY CHECK (HYDROSTATIC TEST) OF NO.1 BAGGAGE FIRE EXTINGUISHING BOTTLES (HIGH RATE)							Service ATA:26
PN:33700027-1	MOS/MSC	10-Dec-24	O/C						
SN:4206D1	HRS	10605.1							
	AFL	5653							
			HydroCheck Date: : 30-Sep-21						
PROC. REF: AMM 26-23-01PROC. REF: AMM 26-23-01									
26-23-01-720-001-A00		FUNCTIONALLY CHECK (HYDROSTATIC TEST) OF NO.2 BAGGAGE FIRE EXTINGUISHING BOTTLES (METERING)							Service ATA:26
PN:34600073-3	MOS/MSC	01-Dec-16	O/C						
SN:27095F1	HRS								
	AFL								
			HydroCheck Date: : 01-Dec-16						
PROC. REF: AMM 26-23-01PROC. REF: AMM 26-23-01									
26-23-01-720-002-A00		FUNCTIONALLY CHECK NO. 1 BAGGAGE COMPARTMENT FIREEXTINGUISHING BOTTLE (HIGH RATE) FOR WEIGHT NOTE: FROM THE MANUFACTURE DATE OR LAST TASK ACCOMPLISHMENT							Service ATA:26
PN:33700027-1	MOS	10-Dec-24	60 (+30d/-30d)		10-Dec-29	09-Jan-30	1294 d (+30)	SYSTEM	
SN:4206D1	HRS	10605.1							
	AFL	5653							
			WeightCheck Date : : 10-Dec-24						
PROC. REF: AMM 26-23-01PROC. REF: AMM 26-23-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 26 - FIRE PROTECTION									
26-23-01-720-002-A00		FUNCTIONALLY CHECK NO. 2 BAGGAGE COMPARTMENT FIREEXTINGUISHING BOTTLE (METERING) FOR WEIGHT							Service ATA:26
PN:34600073-3	MOS	10-Jan-23	60 (+30d/-30d)		10-Jan-28	09-Feb-28	594 d (+30)	SYSTEM	
SN:27095F1	HRS								
	AFL								
			WeightCheck Date : : 10-Jan-23						
PROC. REF: AMM 26-23-01PROC. REF: AMM 26-23-01									
26-23-02-960-001-A00		DISCARD BAGGAGE COMPARTMENT HIGH RATE FIRE EXTINGUISHER BOTTLE CARTRIDGE (SERVICE LIFE) NOTE: 180 MO FROM DATE OFMANUFACTURING OR 120 MO FROM DATE OF INSTALLATION, WHICHEVER OCCURS FIRST.							Service ATA:26
PN:30903870	MOS	10-Dec-24	120		10-Dec-34		3120 d	SERVICE LIFE LIMIT	
SN:0544BC	HRS	10605.1							
	AFL	5653							
			Installation Date: : 10-Dec-24						
PROC. REF: AMM 26-23-02PROC. REF: AMM 26-23-02									
26-23-02-960-001-A00		DISCARD BAGGAGE COMPARTMENT METERING FIRE EXTINGUISHER BOTTLE CARTRIDGE (SERVICE LIFE) NOTE: 180 MO FROM DATE OFMANUFACTURING OR 120 MO FROM DATE OF INSTALLATION, WHICHEVER OCCURS FIRST.							Service ATA:26
PN:30903870	MOS	24-Jul-21	120		24-Jul-31		1885 d	SERVICE LIFE LIMIT	
SN:1342AJ	HRS								
	AFL								
			Installation Date: : 24-Jul-21						
PROC. REF: AMM 26-23-02PROC. REF: AMM 26-23-02									
26-23-02-960-001-A00-M		DISCARD BAGGAGE COMPARTMENT HIGH RATE FIRE EXTINGUISHER BOTTLE CARTRIDGE (LIFE LIMIT)							Service ATA:26
PN:30903870	MOS	10-Dec-24	180		30-Nov-36		3841 d	LIFE LIMIT	
SN:0544BC	HRS	10605.1							
	AFL	5653							
			Manufacture Date:: 30-Nov-21						
PROC. REF: AMM 26-23-02PROC. REF: AMM 26-23-02									
26-23-02-960-001-A00-M		DISCARD BAGGAGE COMPARTMENT METERING FIRE EXTINGUISHER BOTTLE CARTRIDGE (LIFE LIMIT)							Service ATA:26
PN:30903870	MOS	17-Jan-17	180		17-Jan-32		2062 d	LIFE LIMIT	
SN:1342AJ	HRS	8039.6							
	AFL	4314							
			Manufacture Date:: 17-Jan-17						
PROC. REF: AMM 26-23-02PROC. REF: AMM 26-23-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 26 - FIRE PROTECTION									
26-23-04-720-001-A00 S	FUNCTIONALLY CHECK BAGGAGE FIRE EXTINGUISHING TWO-WAY "TEE" CHECK VALVE							Service	ATA:26
	MOS	17-Oct-25	72 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	3000 (+20/-20)						
	AFL	5820	1500 (+20/-20)						
									PKG:5012,6020
PROC. REF: AMM 26-23-04PROC. REF: AMM 26-23-04									
26-23-05-212-001-A00 S	INSPECT (GENERAL VISUAL) DISCHARGE PIPING FOR CRACKS, BENT AND LOOSEFITTINGS, AND NOZZLES FOR DAMAGE.INSPECT (GENERAL VISUAL) DISCHARGE PIPING FOR CRACKS, BENT AND LOOSEFITTINGS, AND NOZZLES FOR DAMAGE.							Service	ATA:26
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: AMM 05-20-44PROC. REF: AMM 05-20-44									
26-24-00-720-001-A00	FUNCTIONALLY CHECK OF COCKPIT PORTABLE FIRE EXTINGUISHING BOTTLE FOR WEIGHT (SEE PLACARD ATTACHED TO THE BOTTLE) NOTE: FROM THE MANUFACTURE DATE OR LAST TASK ACCOMPLISHMENT.							Service	ATA:26
PN:RT-A1200	MOS	17-Oct-25	12		17-Oct-26		144 d	SYSTEM	
SN:Y-502093	HRS	10913.9							
	AFL	5820							
PROC. REF: AMM 26-24-00PROC. REF: AMM 26-24-00									
26-24-00-720-001-A00	FUNCTIONALLY CHECK OF FORWARD PORTABLE FIRE EXTINGUISHING BOTTLE FOR WEIGHT (SEE PLACARD ATTACHED TO THE BOTTLE) NOTE: FROM THE MANUFACTURE DATE OR LAST TASK ACCOMPLISHMENT.							Service	ATA:26
PN:BA21741SR-5	MOS	17-Oct-25	12		17-Oct-26		144 d	SYSTEM	
SN:104464	HRS	10913.9							
	AFL	5820							
PROC. REF: AMM 26-24-00PROC. REF: AMM 26-24-00									
26-24-00-960-001-A00	DISCARD FORWARD PORTABLE FIRE EXTINGUISHER P/N BA21741 SERIESNOTE: FROM THE MANUFACTURE DATE							Service	ATA:26
	MOS		120		01-Jul-27 (M)		401 d	LIFE LIMIT	
	HRS								
	AFL								
PROC. REF: AMM 26-24-01PROC. REF: AMM 26-24-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 26 - FIRE PROTECTION									
26-24-00-960-001-A01		DISCARD COCKPIT PORTABLE FIRE EXTINGUISHER P/N RT A1200 OR P3APP003000-SERIES.NOTE: FROM THE MANUFACTURE DATENOTE: IF INSTALLED							Service ATA:26
PN:RT-A1200	MOS	06-Jul-19	144		01-Mar-31 (M)		1740 d	LIFE LIMIT	
SN:Y-502093	HRS	9057.4							
	AFL	4853							
PROC. REF: AMM 26-24-01PROC. REF: AMM 26-24-01									
26-24-CUS-0101 U		VISUAL INSPECTION COCKPIT PORTABLE FIRE EXTINGUISHER BOTTLE							Service ATA:26
PN:RT-A1200	MOS	15-Oct-24	0					CUSTOMER CODE	
SN:Y-502093	HRS	10578.1							
	AFL	5634							
26-25-01-720-001-A00		FUNCTIONALLY CHECK GALLEY FIRE EXTINGUISHING BOTTLE FOR WEIGHT P/N BA22557-1/ BA22653-1							Service ATA:26
PN:BA24320F-1	MOS/MSC	30-May-19	N/A						
SN:58391	HRS								
	AFL								
			WeightCheck Date : : 30-May-19						
PROC. REF: AMM 26-25-01PROC. REF: AMM 26-25-01									
26-25-01-720-001-A00		FUNCTIONALLY CHECK LAVATORY FIRE EXTINGUISHING BOTTLE FOR WEIGHT P/N BA22557-1/ BA22653-1							Service ATA:26
PN:BA22557-1	MOS	17-Oct-25	12		17-Oct-26		144 d	SYSTEM	
SN:69193	HRS	10913.9							
	AFL	5820							
			WeightCheck Date : : 17-Oct-25						
PROC. REF: AMM 26-25-01PROC. REF: AMM 26-25-01									
26-25-01-720-001-A01		FUNCTIONALLY CHECK GALLEY FIRE EXTINGUISHING BOTTLE FOR WEIGHT P/N BA24320F-1 / BA24320H-1NOTE: FROM THE MANUFACTURE DATE OR LAST TASK ACCOMPLISHMENT.							Service ATA:26
PN:BA24320F-1	MOS	10-Dec-24	60		10-Dec-29		1294 d		
SN:58391	HRS	10605.1							
	AFL	5653							
PROC. REF: AMM 26-25-01PROC. REF: AMM 26-25-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 26 - FIRE PROTECTION									
26-25-01-720-001-A01	FUNCTIONALLY CHECK LAVATORY FIRE EXTINGUISHING BOTTLE FOR WEIGHT P/N BA24320F-1 / BA24320H-1NOTE: FROM THE MANUFACTURE DATE OR LAST TASK ACCOMPLISHMENT.							Service	ATA:26
	MOS/MSC	27-Aug-07	N/A						
	HRS	0							
	AFL	0							
PROC. REF: AMM 26-25-01PROC. REF: AMM 26-25-01									
260000-0101	OVERH P FIRE EXTINGUISHING APU/BAGG MODULE							Component	ATA:26
PN:145-34156-401	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:0000122878	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
261101-0101	LH ENGINE ACC FIRE DETECTOR							Component	ATA:26
PN:3601-133-500/230C-9.0M	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:236171	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 26-11-01PROC. REF: AMM 26-11-01									
261101-0102	RH ENGINE ACC FIRE DETECTOR							Component	ATA:26
PN:3601-133-500/230C-9.0M	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:236183	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 26-11-01PROC. REF: AMM 26-11-01									
261102-0101	LH ENGINE PYLON FIRE DETECTOR							Component	ATA:26
PN:3601-134-480/220C-2.7M	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:235805	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 26-11-02PROC. REF: AMM 26-11-02									

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 26 - FIRE PROTECTION									
261102-0102	RH ENGINE PYLON FIRE DETECTOR							Component	ATA:26
PN:3601-134-480/220C-2.7M	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:235807	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 26-11-02	PROC. REF: AMM 26-11-02								
261103-0101	LH CSL CONTROL-FIRE PROTECTION SYS, CONSOLE, COCKPIT MODULE							Component	ATA:26
PN:902081	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 26-11-03	PROC. REF: AMM 26-11-03								
261103-0102	RH CSL CONTROL-FIRE PROTECTION SYS, CONSOLE, COCKPIT MODULE							Component	ATA:26
PN:902081	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 26-11-03	PROC. REF: AMM 26-11-03								
261103-0103	LH CSL CONTROL-FIRE PROTECTION SYS,CONSOLE,COCKPIT MODULE							Component	ATA:26
PN:902081	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 26-11-03	PROC. REF: AMM 26-11-03								
261201-0101	APU APU FIRE DETECTOR							Component	ATA:26
PN:3601-135-470/200C-3.5M	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:235600	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 26-12-01	PROC. REF: AMM 26-12-01								
261500-0101	BAGGAGE COMPARTMENT CEILING SMOKE DETECTOR							Component	ATA:26
PN:473597-13	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 26-15-01	PROC. REF: AMM 26-15-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 26 - FIRE PROTECTION									
261500-0102		BAGGAGE BULKHEAD SMOKE DETECTOR						Component	ATA:26
PN:473597-13	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 26-15-01PROC. REF: AMM 26-15-01									
262101-0101		PILOT FIRE EXTINGUISHING,ENGINE OVERHEAD PANEL,PAX CABIN HANDLE						Component	ATA:26
PN:1-7054-3	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:1656	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 26-21-01PROC. REF: AMM 26-21-01									
262101-0102		COPILOT FIRE EXTINGUISHING,ENGINE 2-OVERHEAD PANEL HANDLE						Component	ATA:26
PN:2-7054-3	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:1674	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 26-21-01PROC. REF: AMM 26-21-01									
262102-0101		LH ENGINE FIRE EXTINGUISHER BOTTLE (A)						Component	ATA:26
PN:33600057-5	MOS/MSC	14-Jul-22	O/C	TSO 0					
SN:57143D1	HRS	9915.8		TSO 0					
	AFL	5271		TSO 0					
PROC. REF: AMM 26-21-02PROC. REF: AMM 26-21-02									
262102-0102		RH ENGINE FIRE EXTINGUISHER BOTTLE (B)						Component	ATA:26
PN:33600057-5	MOS/MSC	20-Jul-21	O/C	TSN 122, TSO 1					
SN:74313D1	HRS	9631.4		TSO 0					
	AFL	5130		TSO 0					
PROC. REF: AMM 26-21-02PROC. REF: AMM 26-21-02									
262104-0101		NO. 1 LH ENGINE FIRE EXTINGUISHER BOTTLE (A) CARTRIDGE						Component	ATA:26
PN:M30903920	MOS/MSC	14-Jul-22	H/T	TSN 0					
SN:08165	HRS	9915.8		TSN 0					
	AFL	5271		TSN 0					
			Manufacture Date:: 01-Feb-22						
PROC. REF: AMM 26-21-04PROC. REF: AMM 26-21-04									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 26 - FIRE PROTECTION									
262104-0102		NO. 2 LH ENGINE FIRE EXTINGUISHER BOTTLE (A) CARTRIDGE						Component	ATA:26
PN:M30903920	MOS/MSC	14-Jul-22	H/T	TSN 0					
SN:08093	HRS	9915.8		TSN 0					
	AFL	5271		TSN 0					
			Manufacture Date:: 01-Feb-22						
PROC. REF: AMM 26-21-04PROC. REF: AMM 26-21-04									
262104-0201		NO. 1 RH ENGINE FIRE EXTINGUISHER BOTTLE (B) CARTRIDGE						Component	ATA:26
PN:30903920	MOS/MSC	18-Jul-21	H/T	TSN 1					
SN:ESD20H218-001	HRS	9631.4		TSN 0					
	AFL	5130		TSN 0					
			Manufacture Date:: 01-Jun-21						
PROC. REF: AMM 26-21-04PROC. REF: AMM 26-21-04									
262104-0202		NO. 2 RH ENGINE FIRE EXTINGUISHER BOTTLE (B) CARTRIDGE						Component	ATA:26
PN:30903920	MOS/MSC	18-Jul-21	H/T	TSN 1					
SN:ESD20H218-001	HRS	9631.4		TSN 0					
	AFL	5130		TSN 0					
			Manufacture Date:: 01-Jun-21						
PROC. REF: AMM 26-21-04PROC. REF: AMM 26-21-04									
262201-0101		APU FIRE EXTINGUISHER,REAR APU BOTTLE						Component	ATA:26
PN:30100050-5	MOS/MSC	23-Jul-21	O/C	TSN 1					
SN:95144A1	HRS	9631.4		TSN 0					
	AFL	5130		TSN 0					
PROC. REF: AMM 26-22-01PROC. REF: AMM 26-22-01									
262202-0201		APU FIRE EXTINGUISHER BOTTLE CARTRIDGE						Component	ATA:26
PN:30903920	MOS/MSC	23-Jul-21	H/T	TSN 12					
SN:ESD19D208-001	HRS	9631.4		TSN 0					
	AFL	5130		TSN 0					
			Manufacture Date:: 01-Jul-20						
PROC. REF: AMM 26-22-03PROC. REF: AMM 26-22-03									

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 26 - FIRE PROTECTION									
262301-0101		NO.1 BAGGAGE COMPARTMENT HIGH RATE FIRE EXTINGUISHER BOTTLE						Component	ATA:26
PN:33700027-1	MOS/MSC	10-Dec-24	O/C	TSO 0					
SN:4206D1	HRS	10605.1		TSO 0					
	AFL	5653		TSO 0					
PROC. REF: AMM 26-23-01PROC. REF: AMM 26-23-01									
262301-0102		NO.2 BAGGAGE COMPARTMENT METERING FIRE EXTINGUISHER BOTTLE						Component	ATA:26
PN:34600073-3	MOS/MSC	10-Jan-23	O/C	TSN 203, TSO 72					
SN:27095F1	HRS	10066.9		TSO 2027.3					
	AFL	5346		TSO 1032					
PROC. REF: AMM 26-23-01PROC. REF: AMM 26-23-01									
262302-0201		BAGGAGE COMPARTMENT HIGH RATE FIRE EXTINGUISHER BOTTLE CARTRIDGE						Component	ATA:26
PN:30903870	MOS/MSC	10-Dec-24	H/T						
SN:0544BC	HRS	10605.1							
	AFL	5653							
PROC. REF: AMM 26-23-02PROC. REF: AMM 26-23-02									
262302-0202		BAGGAGE COMPARTMENT METERING FIRE EXTINGUISHER BOTTLE CARTRIDGE						Component	ATA:26
PN:30903870	MOS/MSC	26-Jul-21	H/T	TSN 10					
SN:1342AJ	HRS	9631.4		TSN 0					
	AFL	5130		TSN 0					
PROC. REF: AMM 26-23-02PROC. REF: AMM 26-23-02									
262400-0101		COCKPIT PORTABLE FIRE EXTINGUISHER BOTTLE						Component	ATA:26
PN:RT-A1200	MOS/MSC	06-Jul-19	H/T	TSN 1					
SN:Y-502093	HRS	9057.4		TSN 0					
	AFL	4853		TSN 0					
PROC. REF: AMM 26-24-01PROC. REF: AMM 26-24-01									
262400-0102		FORWARD PORTABLE FIRE EXTINGUISHER (PAX CABIN) BOTTLE						Component	ATA:26
PN:BA21741SR-5	MOS/MSC	01-Sep-17	H/T	TSN 2					
SN:104464	HRS	8284.1		TSN 0					
	AFL	4446		TSN 0					
PROC. REF: AMM 26-24-01PROC. REF: AMM 26-24-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 26 - FIRE PROTECTION									
262500-0101		LAVATORY FIRE EXTINGUISHER WASTE DISPOSAL ASSEMBLY						Component	ATA:26
PN:BA22557-1	MOS/MSC	22-Jul-15	O/C	TSN 1					
SN:69193	HRS	7460.3		TSN 0					
	AFL	3992		TSN 0					
PROC. REF: AMM 26-25-01PROC. REF: AMM 26-25-01									
262500-0102		GALLEY FIRE EXTINGUISHER WASTE DISPOSAL ASSEMBLY						Component	ATA:26
PN:BA24320F-1	MOS/MSC	01-Jul-14	O/C						
SN:58391	HRS	7031.5							
	AFL	3775							
PROC. REF: AMM 26-25-01PROC. REF: AMM 26-25-01									
264100-0101		LH WING FUEL QUANTITY TRANSMITTER						Component	ATA:26
PN:028-936-003	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:2348B	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
ATA 27 - FLIGHT CONTROLS									
27-11-00-220-001-A00 S		INSPECT (DETAILED INSPECTION) AILERON PRIMARY MECHANICAL CONTROL FROM CONTROL WHEEL TO AILERON PCAS, CHECKING CABLES, PULLEYS, NRUS, QUADRANTS, DISCONNECT SYSTEM, AND MECHANICAL LINKS						Service	ATA:27
	MOS	29-Jun-23	48 (+15d/-15d)				LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 27-11-00PROC. REF: AMM 27-11-00									
27-11-00-640-001-A00 S		LUBRICATE CONTROL WHEEL CHAIN						Service	ATA:27
	MOS	29-Jun-23	48 (+15d/-15d)				LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 27-11-00PROC. REF: AMM 27-11-00									

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
27-11-00-720-001-A00 S	FUNCTIONALLY CHECK AILERON PRIMARY MECHANICAL CONTROL BACKLASH								Service ATA:27
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5009
PROC. REF: AMM 27-11-00PROC. REF: AMM 27-11-00									
27-11-01-720-001-A00	FUNCTIONALLY CHECK TENSION OF AILERON CONTROL CABLES								Service ATA:27
	MOS	26-Jan-24	48 (+30d/-30d)	Adj 18d	13-Feb-28	14-Mar-28	628 d (+30)	LOW UTILIZATION	
	HRS	10402.1	2000		12402.1		1125.8		
	AFL	5534	1000		6534		509		
PROC. REF: AMM 27-11-01PROC. REF: AMM 27-11-01									
27-12-00-720-001-A00 S	FUNCTIONALLY CHECK AILERON HYDRAULIC ACTUATION								Service ATA:27
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: AMM 27-12-00PROC. REF: AMM 27-12-00									
27-12-00-720-003-A01 S	FUNCTIONALLY CHECK EXTERNAL LEAKAGE OF AILERON HYDRAULIC ACTUATOR (CMR)								Service ATA:27
	MOS	17-Oct-25	24 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	1000 (+20/-20)						
	AFL	5820							
									PKG:5004
PROC. REF: AMM 27-12-00PROC. REF: AMM 27-12-00									
27-12-00-720-003-A02	FUNCTIONALLY CHECK EXTERNAL LEAKAGE OF AILERON HYDRAULIC ACTUATOR (CMR)								Service ATA:27
	MOS/MSC	27-Aug-07	N/A						
	HRS	0							
	AFL	0							
PROC. REF: AMM 27-12-00PROC. REF: AMM 27-12-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
27-12-01-212-001-A00 S	INSPECT (GENERAL VISUAL) AILERON PCA HOSES							Service	ATA:27
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 27-12-01PROC. REF: AMM 27-12-01									
27-12-01-212-002-A01 S	INSPECT (GENERAL VISUAL) AILERON PCA ROD ENDS/FITTING LUGS FOR INTEGRITY AND GENERAL CONDITION (CMR)							Service	ATA:27
	MOS	17-Oct-25	24 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	1000 (+20/-20)						
	AFL	5820							
									PKG:5004
PROC. REF: AMM 27-12-01PROC. REF: AMM 27-12-01									
27-12-01-212-002-A02	INSPECT (GENERAL VISUAL) AILERON PCA ROD ENDS/FITTING LUGS FOR INTEGRITY AND GENERAL CONDITION (CMR)							Service	ATA:27
	MOS/MSC	27-Aug-07	N/A						
	HRS	0							
	AFL	0							
PROC. REF: AMM 27-12-01PROC. REF: AMM 27-12-01									
27-12-01-720-001-A01 S	FUNCTIONALLY CHECK AILERON-ACTUATOR DAMPING COMPONENTS AND MONITORING DEVICES (CMR)							Service	ATA:27
	MOS	17-Oct-25	12 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	500 (+20/-20)						
	AFL	5820							
									PKG:5002
PROC. REF: AMM 27-12-01PROC. REF: AMM 27-12-01									
27-12-01-720-001-A02	FUNCTIONALLY CHECK AILERON-ACTUATOR DAMPING COMPONENTS AND MONITORING DEVICES (CMR)							Service	ATA:27
	MOS/MSC	27-Aug-07	N/A						
	HRS	0							
	AFL	0							
PROC. REF: AMM 27-12-01PROC. REF: AMM 27-12-01									
27-12-01-720-002-A00	FUNCTIONALLY CHECK AILERON ACTUATOR FORCE FIGHT (CMR)							Service	ATA:27
	MOS/MSC	27-Aug-07	N/A						
	HRS	0							
	AFL	0							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
PROC. REF: AMM 27-12-01PROC. REF: AMM 27-12-01									
27-12-01-720-002-A01 S	FUNCTIONALLY CHECK AILERON ACTUATOR FORCE FIGHT (FOR AIRCRAFT UNDER ANAC/FAA CERTIFICATIONS)							Service	ATA:27
	MOS	17-Oct-25	24 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	1000 (+20/-20)						
	AFL	5820							
									PKG:5004
PROC. REF: AMM 27-12-01PROC. REF: AMM 27-12-01									
27-12-03-212-001-A00 S	VISUALLY CHECK AILERON DAMPER ROD ENDS/FITTING LUGS FOR INTEGRITY AND GENERAL CONDITION (CMR)							Service	ATA:27
	MOS	17-Oct-25	12 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	500 (+20/-20)						
	AFL	5820							
									PKG:5002
PROC. REF: AMM 27-12-03PROC. REF: AMM 27-12-03									
27-12-03-720-001-A00 S	FUNCTIONALLY CHECK AILERON DAMPER DAMPING FORCE (CMR)							Service	ATA:27
	MOS	17-Oct-25	24 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	1000 (+20/-20)						
	AFL	5820							
									PKG:5004
PROC. REF: AMM 27-12-03PROC. REF: AMM 27-12-03									
27-12-03-720-002-A00 S	FUNCTIONALLY CHECK EXTERNAL LEAKAGE OF AILERON DAMPER (CMR)							Service	ATA:27
	MOS	17-Oct-25	24 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	1000 (+20/-20)						
	AFL	5820							
									PKG:5004
PROC. REF: AMM 27-12-03PROC. REF: AMM 27-12-03									
27-13-00-710-001-A00 S	OPERATIONALLY CHECK AILERON SOLENOID-MANIFOLD-SHUTOFF FUNCTION							Service	ATA:27
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 27-13-00PROC. REF: AMM 27-13-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
27-14-00-720-001-A00 S	FUNCTIONALLY CHECK ROLL TRIM							Service	ATA:27
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 27-14-00PROC. REF: AMM 27-14-00									
27-15-00-710-001-A00 S	OPERATIONALLY CHECK AILERON DISCONNECT SYSTEM							Service	ATA:27
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016
PROC. REF: AMM 27-15-00PROC. REF: AMM 27-15-00									
27-15-02-640-001-A00 S	LUBRICATE AILERON DISCONNECT SYSTEM (NOTE: THE PLATE MECHANISM IS BENCH LUBRICATED)							Service	ATA:27
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: AMM 27-15-02PROC. REF: AMM 27-15-02									
27-21-00-710-001-A00	OPERATIONALLY CHECK RUDDER MOVABLE PRIMARY STOP MECHANISM							Service	ATA:27
	MOS/MSC	27-Aug-07	N/A						
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: AMM 27-21-00PROC. REF: AMM 27-21-00									
27-21-01-220-001-A00 S	INSPECT (DETAILED INSPECTION) RUDDER PRIMARY MECHANICAL CONTROL CHECKING CABLES, PULLEYS AND QUADRANTS							Service	ATA:27
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 27-21-01PROC. REF: AMM 27-21-01									

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
27-21-01-720-001-A00	FUNCTIONALLY CHECK TENSION OF RUDDER CONTROL CABLES								Service ATA:27
	MOS	26-Jan-24	48 (+30d/-30d)	Adj 18d	13-Feb-28	14-Mar-28	628 d (+30)	LOW UTILIZATION	
	HRS	10402.1	2000		12402.1		1125.8		
	AFL	5534	1000		6534		509		
PROC. REF: AMM 27-21-01PROC. REF: AMM 27-21-01									
27-21-02-220-001-A00 S	INSPECT (DETAILED INSPECTION) RUDDER MAIN CONTROL FEEDBACK PATH, PCU LINKAGE AND MOUNTING POINTS, RUDDER ACTUATOR ATTACHMENTS, HINGES AND CONNECTING RODS								Service ATA:27
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 27-21-02PROC. REF: AMM 27-21-02									
27-22-00-720-001-A00 S	FUNCTIONALLY CHECK RUDDER BACKLASH								Service ATA:27
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 27-22-00PROC. REF: AMM 27-22-00									
27-22-00-720-002-A00	FUNCTIONALLY CHECK RUDDER HYDRAULIC DAMPING								Service ATA:27
	MOS/MSC	19-Aug-15	N/A						
	HRS	7460.3							
	AFL	3992							
PROC. REF: AMM 27-22-00PROC. REF: AMM 27-22-00									
27-22-01-720-001-A00 S	FUNCTIONALLY CHECK RUDDER POWER CONTROL UNIT/ACTUATORS DIFFERENTIAL PRESSURE								Service ATA:27
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 27-22-01PROC. REF: AMM 27-22-01									

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
27-22-02-212-001-A00 S	INSPECT (GENERAL VISUAL) RUDDER ACTUATORS								Service ATA:27
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 27-22-02PROC. REF: AMM 27-22-02									
27-23-00-710-002-A00	OPERATIONALLY CHECK ALERTING LIGHT OF THE RUDDER MOVABLE PRIMARY STOP								Service ATA:27
	MOS/MSC	23-Jul-15	N/A						
	HRS	7460.3							
	AFL	3992							
PROC. REF: AMM 27-23-00PROC. REF: AMM 27-23-00									
27-25-00-710-001-A00 S	OPERATIONALLY CHECK RUDDER PEDALS AUTO SHUTOFF AND RUDDER MANUAL SHUTOFF FUNCTIONS (CMR)								Service ATA:27
	MOS	17-Oct-25	24 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	1000 (+20/-20)						
	AFL	5820							
									PKG:5004
PROC. REF: AMM 27-25-00PROC. REF: AMM 27-25-00									
27-31-00-720-001-A00 S	FUNCTIONALLY CHECK ELEVATOR PRIMARY MECHANICAL CONTROL BACKLASH								Service ATA:27
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 27-31-00PROC. REF: AMM 27-31-00									
27-31-01-220-001-A00 S	INSPECT (DETAILED INSPECTION) ELEVATOR CONTROL CABLES								Service ATA:27
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 27-31-01PROC. REF: AMM 27-31-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
27-31-01-720-001-A00	FUNCTIONALLY CHECK TENSION OF THE ELEVATOR CONTROL CABLES								Service ATA:27
	MOS	26-Jan-24	48 (+30d/-30d)	Adj 18d	13-Feb-28	14-Mar-28	628 d (+30)	LOW UTILIZATION	
	HRS	10402.1	2000		12402.1		1125.8		
	AFL	5534	1000		6534		509		
PROC. REF: AMM 27-31-01PROC. REF: AMM 27-31-01									
27-31-04-710-001-A00 S	OPERATIONALLY CHECK SPRING AND SERVO TABS								Service ATA:27
	MOS	17-Oct-25	12 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	500 (+20/-20)						
	AFL	5820							
									PKG:5002
PROC. REF: AMM 27-31-04PROC. REF: AMM 27-31-04									
27-31-05-220-001-A00 S	INSPECT (DETAILED INSPECTION) SERVO TAB FAIL-SAFE ACTUATION LINK (CMR)								Service ATA:27
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 27-31-05PROC. REF: AMM 27-31-05									
27-31-05-220-002-A00 S	INSPECT (DETAILED INSPECTION) SPRING TAB ATTACHMENT LINK								Service ATA:27
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 27-31-05PROC. REF: AMM 27-31-05									
27-35-00-640-001-A00 S	LUBRICATE ELEVATOR DISCONNECT SYSTEM (NOTE: THE PLATE MECHANISM IS BENCH LUBRICATED).								Service ATA:27
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: AMM 27-35-00PROC. REF: AMM 27-35-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
27-35-00-710-001-A00 S	OPERATIONALLY CHECK ELEVATOR DISCONNECT SYSTEM							Service	ATA:27
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016
PROC. REF: AMM 27-35-00PROC. REF: AMM 27-35-00									
27-36-00-710-001-A00 S	OPERATIONALLY CHECK STALL PROTECTION SYSTEM							Service	ATA:27
	MOS	17-Oct-25	12 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	500 (+20/-20)						
	AFL	5820							
									PKG:5002
PROC. REF: AMM 27-36-00PROC. REF: AMM 27-36-00									
27-36-00-720-001-A00 S	FUNCTIONALLY CHECK ICE/SPS SPEEDS INTERFACE CIRCUIT							Service	ATA:27
	MOS	17-Oct-25	12 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	500 (+20/-20)						
	AFL	5820							
									PKG:5002
PROC. REF: AMM 27-36-00PROC. REF: AMM 27-36-00									
27-40-00-710-002-A00 S	OPERATIONALLY CHECK BACKUP SYS CUTOUT PUSHBUTTON, MAIN SYS CUTOUT SWITCH, AND QUICK DISCONNECT SWITCH							Service	ATA:27
	MOS/MSC	29-Jun-23	O/C						
	HRS	10161.5							
	AFL	5401							
									PKG:5008
PROC. REF: AMM 27-40-00PROC. REF: AMM 27-40-00									
27-40-00-710-003-A00	OPERATIONALLY CHECK LOCKOUT LOGIC OF HORIZONTAL STABILIZER CONTROL UNIT POST-MOD SB 145LEG-27-0016 OR WITH AN EQUIVALENT MODIFICATION FACTORY-INCORPORATED.							Service	ATA:27
	MOS/MSC	16-Aug-24	O/C						
	HRS	10541.4							
	AFL	5613							
PROC. REF: AMM 27-40-00PROC. REF: AMM 27-40-00									

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
27-40-00-720-001-A00 S	FUNCTIONALLY CHECK HORIZONTAL STABILIZER BACKLASH							Service	ATA:27
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 27-40-00PROC. REF: AMM 27-40-00									
27-40-02-220-001-A00 S	INSPECT (DETAILED INSPECTION) HORIZONTAL STABILIZER ACTUATOR INTEGRITY AND ATTACHMENTS							Service	ATA:27
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 27-40-02PROC. REF: AMM 27-40-02									
27-40-02-610-001-A00 S	SERVICE (REPLENISH) HORIZONTAL STABILIZER ACTUATOR AND CHECK FOR LEAKAGE.							Service	ATA:27
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008
PROC. REF: AMM 27-40-02PROC. REF: AMM 27-40-02									
27-51-00-212-001-A00 S	INSPECT (GENERAL VISUAL) FLAP MECHANICAL LINE							Service	ATA:27
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 27-51-00PROC. REF: AMM 27-51-00									
27-51-00-220-001-A00 S	INSPECT (DETAILED INSPECTION) FLAP FLEXIBLE SHAFT							Service	ATA:27
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 27-51-00PROC. REF: AMM 27-51-00									

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
27-51-00-610-001-A00	SERVICE (LUBRICATE) FLAP SCREWJACK ACTUATORS GEARBOX (PRE-MOD SB 145LEG-27-0026) (L600 ONLY)							Service	ATA:27
	MOS/MSC	15-Aug-13	N/A	Adj 12d					
	HRS	6643.4							
	AFL	3572							
									PKG:6016
PROC. REF: AMM 27-51-00PROC. REF: AMM 27-51-00									
27-51-00-610-001-A01 S	SERVICE (LUBRICATE) FLAP SCREWJACK ACTUATORS GEARBOX (POST-MOD SB 145LEG-27-0026 OR WITH AN EQUIVALENT MODIFICATION FACTORY INCORPORATED)							Service	ATA:27
	MOS	17-Oct-25	72 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	3000 (+20/-20)						
	AFL	5820	1500 (+20/-20)						
									PKG:5012,6020
PROC. REF: AMM 27-51-00PROC. REF: AMM 27-51-00									
27-51-00-640-001-A00 S	SERVICE (LUBRICATE) FLAP SCREWJACK ACTUATOR (FSAS)							Service	ATA:27
	MOS	17-Oct-25	12 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	500 (+20/-20)						
	AFL	5820							
									PKG:5002
PROC. REF: AMM 27-51-00PROC. REF: AMM 27-51-00									
27-51-01-720-001-A00 S	FUNCTIONALLY CHECK FLAP TRANSMISSION BRAKE HOLDING CAPABILITY							Service	ATA:27
	MOS	17-Oct-25	24 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	1000 (+20/-20)						
	AFL	5820							
									PKG:5004
PROC. REF: AMM 27-51-01PROC. REF: AMM 27-51-01									
27-51-15-220-001-A00 S	INSPECT (DETAILED INSPECTION) FLAP ROLLERS FOR STRUCTURAL INTEGRITY							Service	ATA:27
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: AMM 27-51-15PROC. REF: AMM 27-51-15									

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
27-51-17-720-001-A00 S	FUNCTIONAL CHECK MTB FLAP DRIVE MOTOR UNIT(FDMU) HOLDING CAPABILITY							Service	ATA:27
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 27-51-17PROC. REF: AMM 27-51-17									
27-53-00-710-001-A00 S	OPERATIONALLY CHECK FLAP FAIL MESSAGE							Service	ATA:27
	MOS	17-Oct-25	12 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	500 (+20/-20)						
	AFL	5820							
									PKG:5002
PROC. REF: AMM 27-53-00PROC. REF: AMM 27-53-00									
27-53-00-710-002-A00 S	OPERATIONALLY CHECK "TAKEOFF FLAPS" AURAL WARNING AND NO TAKEOFF CONFIGURATION VISUAL WARNING							Service	ATA:27
	MOS	17-Oct-25	12 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	500 (+20/-20)						
	AFL	5820							
									PKG:5002
PROC. REF: AMM 27-53-00PROC. REF: AMM 27-53-00									
27-62-00-720-001-A00 S	FUNCTIONALLY CHECK GROUND SPOILER/SPEED BRAKE VALVES, CONTROL CIRCUIT, AND RELATED MESSAGES (CMR)							Service	ATA:27
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: AMM 27-62-00PROC. REF: AMM 27-62-00									
27-63-01-710-001-A00 S	OPERATIONALLY CHECK SPOILER SYSTEM							Service	ATA:27
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 27-63-01PROC. REF: AMM 27-63-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
27-71-00-220-001-A00 S	INSPECT (DETAILED INSPECTION) ELECTROMECHANICAL GUST LOCK MECHANISM							Service	ATA:27
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 27-71-00PROC. REF: AMM 27-71-00									
27-71-00-710-004-A00 S	OPERATIONALLY CHECK ELECTROMECHANICAL GUST LOCK SOLENOID FUNCTION							Service	ATA:27
	MOS	17-Oct-25	12 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	500 (+20/-20)						
	AFL	5820							
									PKG:5002
PROC. REF: AMM 27-71-00PROC. REF: AMM 27-71-00									
270000-0101	CENTRAL CONSOLE, TRIM CONTROL MODULE							Component	ATA:27
PN:145-34177-407	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:0000143331	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
270000-0201	OVERHEAD PANEL, FLIGHT CONTROL MODULE							Component	ATA:27
PN:145-21333-403	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:0000140025	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
270101-0101	RUDDER VII BALANCING ASSEMBLY							Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
271100-0101	DISCONNECTION ASSY - AILERON, FUSELAGE FORWARD DEVICE							Component	ATA:27
PN:145-37755-409	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:0000133996	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-15-00PROC. REF: AMM 27-15-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
271100-0201		FWD FUS TUBE,TORQUE ASSY ASSEMBLY						Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
271100-0202		FWD FUS TORQUE TUBE ASSY ASSEMBLY						Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
271102-0301		LH WING AILERON ASSEMBLY						Component	ATA:27
PN:135-03290-407	MOS/MSC	06-Jul-19	O/C	TSR 0					
SN:0000127949	HRS	9057.4		TSR 0					
	AFL	4853		TSR 0					
PROC. REF: AMM 27-10-00PROC. REF: AMM 27-10-00									
271102-0302		RH WING AILERON ASSEMBLY						Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-10-00PROC. REF: AMM 27-10-00									
271103-0201		LEFT AILERON CONTROL CABLE ASSY						Component	ATA:27
PN:PN	MOS/MSC	06-Jul-19	O/C	TSN 0					
SN:UNKNOWN	HRS	9057.4		TSN 0					
	AFL	4853		TSN 0					
PROC. REF: AMM 27-11-01PROC. REF: AMM 27-11-01									
271103-0202		RIGHT AILERON CONTROL CABLE ASSY						Component	ATA:27
PN:PN	MOS/MSC	06-Jul-19	O/C	TSN 0					
SN:UNKNOWN	HRS	9057.4		TSN 0					
	AFL	4853		TSN 0					
PROC. REF: AMM 27-11-01PROC. REF: AMM 27-11-01									

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
271103-0301		LH PIL AILERON FORCE,COCKPIT SENSOR						Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
271103-0302		LH COPIL AILERON FORCE,COCKPIT SENSOR						Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
271103-0303		RH PIL AILERON FORCE,COCKPIT SENSOR						Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
271103-0304		RH COPIL AILERON FORCE,COCKPIT SENSOR						Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
271200-0101		LH WING NEUTRAL RECOVERY-AILERON CONTROL UNIT						Component	ATA:27
PN:373600-1001	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:2052	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-11-07PROC. REF: AMM 27-11-07									
271200-0102		RH WING NEUTRAL RECOVERY-AILERON CONTROL UNIT						Component	ATA:27
PN:373600-1001	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:1993	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-11-07PROC. REF: AMM 27-11-07									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
271200-0301	LH REAR MANIFOLD -HYDRAULIC, AILERON SOLENOID ASSEMBLY							Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-12-02PROC. REF: AMM 27-12-02									
271200-0302	RH REAR MANIFOLD -HYDRAULIC, AILERON SOLENOID ASSEMBLY							Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-12-02PROC. REF: AMM 27-12-02									
271200-0401	LH WING DAMPER ASSEMBLY							Component	ATA:27
PN:41012130-104	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:1299	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
271200-0402	RH WING DAMPER ASSEMBLY							Component	ATA:27
PN:41012130-104	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:1298	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
271200-0501	LH WING HYDRAULIC-AILERON ACTUATOR							Component	ATA:27
PN:418800-1007	MOS/MSC	27-Aug-14	O/C	TSR 0					
SN:2483AB	HRS	7112.9		TSR 0					
	AFL	3811		TSR 0					
PROC. REF: AMM 27-12-01, AMM 27-12-04PROC. REF: AMM 27-12-01, AMM 27-12-04									
271200-0502	RH WING HYDRAULIC-AILERON ACTUATOR							Component	ATA:27
PN:418800-1007	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:2488A	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-12-01, AMM 27-12-04PROC. REF: AMM 27-12-01, AMM 27-12-04									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
271400-0101		FORWARD ELECTROMECHANICAL ACTUATOR						Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-71-01PROC. REF: AMM 27-71-01									
271400-0102		RUDDER ELECTROMECHANICAL ACTUATOR						Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-71-01PROC. REF: AMM 27-71-01									
271400-0201		FORWARD FEEL-POSITION, AILERON TRIM TAB UNIT						Component	ATA:27
PN:367000-1005	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:1045	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-14-00PROC. REF: AMM 27-14-00									
271500-0101		CREW CAB MODULE -AILERON DISCONNECTION,CENTRAL CONSOLE ASSEMBLY						Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-15-00PROC. REF: AMM 27-15-00									
272100-0201		ASSY ACTUATOR						Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
272100-0202		ASSY ACTUATOR						Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
272100-0301	PROF COP ELEVATOR/RUDDER FORCE,COCKPIT SENSOR							Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
272100-0302	PROF PIL ELEVATOR/RUDDER FORCE,COCKPIT SENSOR							Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
272100-0303	RUD COP ELEVATOR/RUDDER FORCE,COCKPIT SENSOR							Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
272100-0304	RUD PIL ELEVATOR/RUDDER FORCE,COCKPIT SENSOR							Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
272100-0401	ROD ASSEMBLY							Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-21-08PROC. REF: AMM 27-21-08									
272100-0402	ROD ASSEMBLY							Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-21-08PROC. REF: AMM 27-21-08									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
272100-0501		PILOT PEDAL ASSEMBLY						Component	ATA:27
PN:145-27402-405	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:0000131839	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-21-07	PROC. REF: AMM 27-21-07								
272100-0502		COPILOT PEDAL ASSEMBLY						Component	ATA:27
PN:145-27402-407	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:0000131840	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-21-07	PROC. REF: AMM 27-21-07								
272101-0101		LH PIL ACTUATOR LINEAR -ROTARY ELECTROMECHANICAL, CONTROL RUDDER ASSEMBLY						Component	ATA:27
PN:6203	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:2936	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-21-01	PROC. REF: AMM 27-21-01								
272101-0102		RH COPIL ACTUATOR LINEAR -ROTARY ELECTROMECHANICAL, CONTROL RUDDER ASSEMBLY						Component	ATA:27
PN:6203	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:2935	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-21-01	PROC. REF: AMM 27-21-01								
272101-0201		RUDDER CONTROL CABLE ASSEMBLY						Component	ATA:27
PN:PN	MOS/MSC	06-Jul-19	O/C	TSN 0					
SN:UNKNOWN	HRS	9057.4		TSN 0					
	AFL	4853		TSN 0					
PROC. REF: AMM 27-21-01	PROC. REF: AMM 27-21-01								
272102-0101		RUDDER II -PIN ASSEMBLY						Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-20-02	PROC. REF: AMM 27-20-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
272103-0101		STRUCTURE ASSY ASSEMBLY						Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
272200-0101		RUDDER SYS - POWER CONTROL UNIT ASSEMBLY						Component	ATA:27
PN:360300-1001	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:1047	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-22-03PROC. REF: AMM 27-22-03									
272200-0201		HYDRAULIC SYS, FIN RUDDER HYDROMECHANIC ACTUATOR ASSEMBLY						Component	ATA:27
PN:360340-1005	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-22-02PROC. REF: AMM 27-22-02									
272200-0202		HYDRAULIC SYS, FIN RUDDER HYDROMECHANIC ACTUATOR ASSEMBLY						Component	ATA:27
PN:360340-1005	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-22-02PROC. REF: AMM 27-22-02									
272200-0301		UPPER FORWARD TAIL HYDRAULIC SYS BLEED VALVE						Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-22-07PROC. REF: AMM 27-22-07									
272200-0302		UPPER AFT TAIL HYDRAULIC SYS BLEED VALVE						Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-22-07PROC. REF: AMM 27-22-07									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
272200-0303	LOWER FORWARD TAIL HYDRAULIC SYS BLEED VALVE							Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-22-07PROC. REF: AMM 27-22-07									
272200-0304	LOWER AFT TAIL HYDRAULIC SYS BLEED VALVE							Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-22-07PROC. REF: AMM 27-22-07									
272200-0401	MID PAX DOOR SYS, THREE WAY/TWO POSITIONS, SOLENOID VALVE							Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-22-05PROC. REF: AMM 27-22-05									
272200-0402	PAX DOOR SYS, THREE WAY/TWO POSITIONS, SOLENOID VALVE							Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-22-05PROC. REF: AMM 27-22-05									
272200-0403	PAX DOOR SYS, THREE WAY/TWO POSITIONS, SOLENOID VALVE							Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-22-05PROC. REF: AMM 27-22-05									
272300-0101	SERVO CONTROL, RUDDER PRESSURE SENSOR UNIT							Component	ATA:27
PN:15H0048PH	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:0827	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-23-04PROC. REF: AMM 27-23-04									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
272300-0102		SERVO CONTROL, RUDDER PRESSURE SENSOR UNIT						Component	ATA:27
PN:15H0048PH	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:0825	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-23-04PROC. REF: AMM 27-23-04									
273100-0101		ELEVATOR CONTROL, FUSELAGE FWD, DISCONNECTION ASSY DEVICE						Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-35-00PROC. REF: AMM 27-35-00									
273100-0201		PILOT YOKE EQUIPPED CONTROLLER						Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-11-08PROC. REF: AMM 27-11-08									
273100-0202		COPILOT YOKE EQUIPPED CONTROLLER						Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-11-08PROC. REF: AMM 27-11-08									
273100-0301		ROD ASSEMBLY						Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
273100-0302		ROD ASSEMBLY						Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
273100-0401	C FLOOR TUBE ASSY							Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
273100-0402	C FLOOR TUBE ASSY							Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
273101-0101	ELEVATOR CONTROL CABLE ASSEMBLY							Component	ATA:27
PN:PN	MOS/MSC	06-Jul-19	O/C	TSN 0					
SN:UNKNOWN	HRS	9057.4		TSN 0					
	AFL	4853		TSN 0					
PROC. REF: AMM 27-31-01PROC. REF: AMM 27-31-01									
273102-0101	LEFT ELEVATOR -HORIZONTAL TAIL ASSEMBLY							Component	ATA:27
PN:145-50845-423	MOS/MSC	13-May-14	O/C	TSN 0					
SN:0000809800	HRS	6988.9		TSN 0					
	AFL	3750		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
273102-0102	RIGHT ELEVATOR -HORIZONTAL TAIL ASSEMBLY							Component	ATA:27
PN:145-50845-416	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:0000133435	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
273103-0101	LEFT ELEVATOR CABLE TENSION REGULATOR							Component	ATA:27
PN:0501020-03	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:1175	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-31-01PROC. REF: AMM 27-31-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
273103-0102	RIGHT ELEVATOR CABLE TENSION REGULATOR							Component	ATA:27
PN:0501020-01	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:1174	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-31-01	PROC. REF: AMM 27-31-01								
273500-0101	CREW CAB MODULE -ELEVATOR DISCONNECTION,CENTRAL CONSOLE ASSEMBLY							Component	ATA:27
PN:145-22175-401	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:0000137134	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-35-00	PROC. REF: AMM 27-35-00								
273601-0101	LEFT ANGLE OF ATTACK SENSOR							Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-36-01	PROC. REF: AMM 27-36-01								
273601-0102	RIGHT ANGLE OF ATTACK SENSOR							Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-36-01	PROC. REF: AMM 27-36-01								
273602-0201	PILOT STICK SHAKER ACTUATOR							Component	ATA:27
PN:0050N1	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:2901	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-36-03	PROC. REF: AMM 27-36-03								
273602-0202	COPILOT STICK SHAKER ACTUATOR							Component	ATA:27
PN:0050N1	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:2915	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-36-03	PROC. REF: AMM 27-36-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
273603-0101	C FLOOR DATA PROCESSING-STALL PROTECTION CONTROL SYS COMPUTER							Component	ATA:27
PN:0020BN7	MOS/MSC	10-Feb-10	O/C						
SN:1207	HRS	2977.3							
	AFL	1557							
PROC. REF: AMM 27-36-05	PROC. REF: AMM 27-36-05								
273604-0101	FORWARD LINEAR ASSY-ELECTROMECHANICAL, STICK PUSHER ACTUATOR							Component	ATA:27
PN:6235-1	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:1880	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-36-04	PROC. REF: AMM 27-36-04								
273605-0101	CSL CENT MODULE -STALL PROTECTION/FMS ASSEMBLY							Component	ATA:27
PN:145-34172-407	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:0000139918	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-36-05	PROC. REF: AMM 27-36-05								
274000-0101	STABILIZER -HORIZONTAL EMPENAGE ASSEMBLY							Component	ATA:27
PN:362200-1015	MOS/MSC	11-Aug-25	O/C						
SN:0824	HRS	10856.2							
	AFL	5786							
PROC. REF: AMM 27-40-02	PROC. REF: AMM 27-40-02								
274100-0101	ACTUATOR, ELECTROMECHANICAL -HORIZONTAL STABILIZER ASSEMBLY							Component	ATA:27
PN:362200-1015	MOS/MSC	15-Aug-13	O/C						
SN:0614	HRS	6643.4							
	AFL	3572							
PROC. REF: AMM 27-40-02	PROC. REF: AMM 27-40-02								
274302-0101	REAR CONTROL HORIZONTAL STABILIZER UNIT							Component	ATA:27
PN:362100-1013	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:4742	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-40-01	PROC. REF: AMM 27-40-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
275000-0101	L/H WING FLAP I ASSY,LEFT,SEALING ASSEMBLY							Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
275000-0102	R/H WING FLAP I ASSY,RIGHT,SEALING ASSEMBLY							Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
275000-0103	L/H WING FLAP II ASSY,LEFT,SEALING ASSEMBLY							Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
275000-0104	R/H WING FLAP II ASSY,RIGHT,SEALING ASSEMBLY							Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
275100-0102	LH WING FLEXIBLE ASSY-SEGMENT 2, FLAP CONTROL SHAFT							Component	ATA:27
PN:363400-1021	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:03194	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-51-05PROC. REF: AMM 27-51-05									
275100-0103	RH WING FLEXIBLE ASSY-SEGMENT 2, FLAP CONTROL SHAFT							Component	ATA:27
PN:363400-1021	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-51-05PROC. REF: AMM 27-51-05									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
275100-0106	INBOARD FLAP ASSY ASSEMBLY							Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-50-00PROC. REF: AMM 27-50-00									
275100-0107	INBOARD FLAP ASSY ASSEMBLY							Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-50-00PROC. REF: AMM 27-50-00									
275100-0108	OUTBOARD FLAP ASSY ASSEMBLY							Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-50-00PROC. REF: AMM 27-50-00									
275100-0109	OUTBOARD FLAP ASSY ASSEMBLY							Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-50-00PROC. REF: AMM 27-50-00									
275100-0409	RH WING FLAP SCREWJACK ACTUATOR							Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-51-09, AMM 27-51-10PROC. REF: AMM 27-51-09, AMM 27-51-10									
275100-0410	RH WING FLAP SCREWJACK ACTUATOR							Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-51-09, AMM 27-51-10PROC. REF: AMM 27-51-09, AMM 27-51-10									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
275100-0411	RH WING FLAP SCREWJACK ACTUATOR							Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-51-09, AMM 27-51-10	PROC. REF: AMM 27-51-09, AMM 27-51-10								
275100-0412	RH WING FLAP SCREWJACK ACTUATOR							Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-51-09, AMM 27-51-10	PROC. REF: AMM 27-51-09, AMM 27-51-10								
275100-0413	LH WING FLAP SCREWJACK ACTUATOR							Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-51-09, AMM 27-51-10	PROC. REF: AMM 27-51-09, AMM 27-51-10								
275100-0414	LH WING FLAP SCREWJACK ACTUATOR							Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-51-09, AMM 27-51-10	PROC. REF: AMM 27-51-09, AMM 27-51-10								
275100-0415	LH WING FLAP SCREWJACK ACTUATOR							Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-51-09, AMM 27-51-10	PROC. REF: AMM 27-51-09, AMM 27-51-10								
275100-0416	LH WING FLAP SCREWJACK ACTUATOR							Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-51-09, AMM 27-51-10	PROC. REF: AMM 27-51-09, AMM 27-51-10								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
275100-0503		LH WING BRAKE TRANSMISSION FLAP						Component	ATA:27
PN:363500-1003	MOS/MSC	05-Aug-15	O/C						
SN:LA-628	HRS	7460.3		TSN 32934.97					
	AFL	3992		TSN 30844					
PROC. REF: AMM 27-51-01PROC. REF: AMM 27-51-01									
275100-0504		RH WING BRAKE TRANSMISSION FLAP						Component	ATA:27
PN:363500-1003	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:03198	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-51-01PROC. REF: AMM 27-51-01									
275100-0701		LH WING FLAP FLEXIBLE 4 E 5 SHAFT						Component	ATA:27
PN:363400-1025	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:05824	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-51-07, AMM 27-51-08PROC. REF: AMM 27-51-07, AMM 27-51-08									
275100-0702		RH WING FLAP FLEXIBLE 4 E 5 SHAFT						Component	ATA:27
PN:363400-1025	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-51-07, AMM 27-51-08PROC. REF: AMM 27-51-07, AMM 27-51-08									
275100-0703		LH WING FLAP FLEXIBLE 4 E 5 SHAFT						Component	ATA:27
PN:363400-1025	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-51-07, AMM 27-51-08PROC. REF: AMM 27-51-07, AMM 27-51-08									
275100-0704		RH WING FLAP FLEXIBLE 4 E 5 SHAFT						Component	ATA:27
PN:363400-1025	MOS/MSC	27-Jul-15	O/C						
SN:07353	HRS	7460.3							
	AFL	3992							
PROC. REF: AMM 27-51-07, AMM 27-51-08PROC. REF: AMM 27-51-07, AMM 27-51-08									

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
275100-0705	LH WING FLAP FLEXIBLE 3 SHAFT							Component	ATA:27
PN:363400-1023	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:03199	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-51-06PROC. REF: AMM 27-51-06									
275100-0706	RH WING FLAP FLEXIBLE 3 SHAFT							Component	ATA:27
PN:363400-1023	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-51-06PROC. REF: AMM 27-51-06									
275100-0801	LH WING ANGLE-ACTUATOR, INTERNAL CENTRAL FLAP ROOT, WING ADAPTER							Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
275100-0802	RH WING ANGLE-ACTUATOR, INTERNAL CENTRAL FLAP ROOT, WING ADAPTER							Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
275100-0803	LH WING ANGLE-ACTUATOR, EXTERNAL FLAP ROOT, WING ADAPTER							Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
275100-0804	RH WING ANGLE-ACTUATOR, EXTERNAL FLAP ROOT, WING ADAPTER							Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
275100-0901	LH WING SENSOR -VELOCITY, FLAP ASSEMBLY							Component	ATA:27
PN:363350-1003	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:05950	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-51-12PROC. REF: AMM 27-51-12									
275100-0902	RH WING SENSOR -VELOCITY, FLAP ASSEMBLY							Component	ATA:27
PN:363350-1003	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:05915	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-51-12PROC. REF: AMM 27-51-12									
275100-1001	LH WING ASSY, FLAP CONTROL ACTUATOR							Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-51-09, AMM 27-51-10, AMM 27-51-09, AMM 27-51-10PROC. REF: AMM 27-51-09, AMM 27-51-10, AMM 27-51-09, AMM 27-51-10									
275100-1002	RH WING ASSY, FLAP CONTROL ACTUATOR							Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-51-09, AMM 27-51-10, AMM 27-51-09, AMM 27-51-10PROC. REF: AMM 27-51-09, AMM 27-51-10, AMM 27-51-09, AMM 27-51-10									
275100-1003	LH WING ASSY, FLAP CONTROL ACTUATOR							Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-51-09, AMM 27-51-10, AMM 27-51-09, AMM 27-51-10PROC. REF: AMM 27-51-09, AMM 27-51-10, AMM 27-51-09, AMM 27-51-10									
275100-1004	RH WING ASSY, FLAP CONTROL ACTUATOR							Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-51-09, AMM 27-51-10, AMM 27-51-09, AMM 27-51-10PROC. REF: AMM 27-51-09, AMM 27-51-10, AMM 27-51-09, AMM 27-51-10									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
275100-1005		LH WING ASSY, FLAP CONTROL ACTUATOR						Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-51-09, AMM 27-51-10, AMM 27-51-09, AMM 27-51-10PROC. REF: AMM 27-51-09, AMM 27-51-10, AMM 27-51-09, AMM 27-51-10									
275100-1006		RH WING ASSY, FLAP CONTROL ACTUATOR						Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-51-09, AMM 27-51-10, AMM 27-51-09, AMM 27-51-10PROC. REF: AMM 27-51-09, AMM 27-51-10, AMM 27-51-09, AMM 27-51-10									
275100-1007		LH WING ASSY, FLAP CONTROL ACTUATOR						Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-51-09, AMM 27-51-10, AMM 27-51-09, AMM 27-51-10PROC. REF: AMM 27-51-09, AMM 27-51-10, AMM 27-51-09, AMM 27-51-10									
275100-1008		RH WING ASSY, FLAP CONTROL ACTUATOR						Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-51-09, AMM 27-51-10, AMM 27-51-09, AMM 27-51-10PROC. REF: AMM 27-51-09, AMM 27-51-10, AMM 27-51-09, AMM 27-51-10									
275100-1101		LH FLAP - INBOARD, WING HALF ASSEMBLY						Component	ATA:27
PN:135-03288-403	MOS/MSC	19-Aug-15	O/C	TSN 96					
SN:0000137761	HRS	7460.3		TSN 7460.3					
	AFL	3992		TSN 3992					
PROC. REF: AMM 27-50-00PROC. REF: AMM 27-50-00									
275100-1102		RH FLAP - INBOARD, WING HALF ASSEMBLY						Component	ATA:27
PN:135-03288-404	MOS/MSC	19-Aug-15	O/C	TSR 0					
SN:0000137750	HRS	7460.3		TSR 0					
	AFL	3992		TSR 0					
PROC. REF: AMM 27-50-00PROC. REF: AMM 27-50-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
275100-1103	LH FLAP - OUTBOARD, WING HALF ASSEMBLY							Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-50-00PROC. REF: AMM 27-50-00									
275100-1104	RH FLAP - OUTBOARD, WING HALF ASSEMBLY							Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-50-00PROC. REF: AMM 27-50-00									
275300-0101	W STUB POWER-DRIVE, FLAP ACTUATOR UNIT							Component	ATA:27
PN:363200-1003	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:01249	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-53-04PROC. REF: AMM 27-53-04									
275300-0201	LH WING FLAP FLEXIBLE 1 SHAFT							Component	ATA:27
PN:363400-1019	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:03050	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-51-04PROC. REF: AMM 27-51-04									
275300-0202	RH WING FLAP FLEXIBLE 1 SHAFT							Component	ATA:27
PN:363400-1019	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-51-04PROC. REF: AMM 27-51-04									
275302-0101	WING/FUSLG FAIRING, FLAP CONTROL UNIT							Component	ATA:27
PN:363100-1011	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:5378	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-53-02PROC. REF: AMM 27-53-02									

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
275303-0101	FLAP SYS, CSL CENT, SELECTOR LEVER							Component	ATA:27
PN:363110-1009	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:1142	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-53-03	PROC. REF: AMM 27-53-03								
276000-0101	LH WING GROUND SPOILER PANEL ASSEMBLY							Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-62-05	PROC. REF: AMM 27-62-05								
276000-0102	RH WING GROUND SPOILER PANEL ASSEMBLY							Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-62-05	PROC. REF: AMM 27-62-05								
276000-0201	LH WING SPEED BRAKE PANEL							Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-62-06	PROC. REF: AMM 27-62-06								
276000-0202	RH WING SPEED BRAKE PANEL							Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-62-06	PROC. REF: AMM 27-62-06								
276201-0101	LH WING GROUND SPOILER, HYDROMECHANICAL ACTUATOR ASSEMBLY							Component	ATA:27
PN:360440-1011	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-62-01	PROC. REF: AMM 27-62-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
276201-0102	RH WING GROUND SPOILER, HYDROMECHANICAL ACTUATOR ASSEMBLY							Component	ATA:27
PN:360440-1011	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-62-01PROC. REF: AMM 27-62-01									
276201-0201	W STUB ELECTROVALVE-SPOILER, HYDRAULIC SYSTEM							Component	ATA:27
PN:360450-1001	MOS/MSC	01-Sep-17	O/C						
SN:1136	HRS	8284.1							
	AFL	4446							
PROC. REF: AMM 27-62-03PROC. REF: AMM 27-62-03									
276201-0301	W STUB RESTRICTOR, HYDRAULIC SYS, SSTEEL VALVE							Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-22-06PROC. REF: AMM 27-22-06									
276203-0101	LH WING HYDROMECHANICAL SPEED BRAKE ACTUATOR							Component	ATA:27
PN:360540-1011	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-62-02PROC. REF: AMM 27-62-02									
276203-0102	RH WING HYDROMECHANICAL SPEED BRAKE ACTUATOR							Component	ATA:27
PN:360540-1011	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-62-02PROC. REF: AMM 27-62-02									
276203-0201	W STUB BRAKE AERODYNAMIC VALVE							Component	ATA:27
PN:360550-1003	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:1088	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
276207-0101	MID PRESSURE REDUCER, HYDRAULIC SYS, WING STUB VALVE							Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-62-07PROC. REF: AMM 27-62-07									
276301-0101	LH WING SPOILER INBOARD PROXIMITY SWITCH							Component	ATA:27
PN:80-057-01	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-63-04PROC. REF: AMM 27-63-04									
276301-0102	RH WING SPOILER INBOARD PROXIMITY SWITCH							Component	ATA:27
PN:8-527-01	MOS/MSC	09-Feb-11	O/C	TSN 0					
SN:18077	HRS	4234		TSN 0					
	AFL	2237		TSN 0					
PROC. REF: AMM 27-63-04PROC. REF: AMM 27-63-04									
276301-0103	LH WING SPOILER OUTBOARD PROXIMITY SWITCH							Component	ATA:27
PN:80-057-01	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-63-04PROC. REF: AMM 27-63-04									
276301-0104	RH WING SPOILER OUTBOARD PROXIMITY SWITCH							Component	ATA:27
PN:80-057-01	MOS/MSC	26-Dec-10	O/C						
SN:26368	HRS	4048.8							
	AFL	2138							
PROC. REF: AMM 27-63-04PROC. REF: AMM 27-63-04									
276301-0105	LH WING SPOILER CENTER PROXIMITY SWITCH							Component	ATA:27
PN:80-057-01	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-63-04PROC. REF: AMM 27-63-04									

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
276302-0101		SPEED BRAKE CONTROL, CENTRAL CONSOLE, LEVER ASSEMBLY						Component	ATA:27
PN:999-1003	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:1086	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-63-03	PROC. REF: AMM 27-63-03								
276303-0101		CSL CENT SPOILER CONTROL, EQUIPPED UNIT						Component	ATA:27
PN:145-33022-411	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:124793	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-63-02	PROC. REF: AMM 27-63-02								
277100-0101		ELECTROMECHANICAL,CONTROLS LOCKING ACTUATOR ASSEMBLY						Component	ATA:27
PN:SYLC-53058	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:070316	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-71-01	PROC. REF: AMM 27-71-01								
277100-0201		LEFT CARTRIDGE ASSY-GUST LOCK SYS SPRING						Component	ATA:27
PN:KPD4235	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:KC2261	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-71-03	PROC. REF: AMM 27-71-03								
277100-0202		RIGHT CARTRIDGE ASSY-GUST LOCK SYS SPRING						Component	ATA:27
PN:KPD4235	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:KC2227	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-71-03	PROC. REF: AMM 27-71-03								
ATA 28 - FUEL									
28-10-00-220-001-A00		INSPECT (DETAILED INSPECTION) OF FUEL TANKS (WINGS AND WING STUB) FOR PRESENCE OF MICROORGANISM (L600 ONLY) NOTE 1:IF MODERATE OR HEAVY CONTAMINATION IS FOUND, FWD AND AFT FUEL TANKS MUST BE INSPECTED.NOTE 2: IF ENGINE FUEL FILTER ELEMENT HAS BEEN REPLACED THE TASK 73-1100-960-001-A00 MUST BE SIGNED OFF NOTE 3: EMB-RECOMMENDED						Service	ATA:28
	MOS	17-Oct-25	12 (+15d/-15d)		17-Oct-26	01-Nov-26	144 d (+15)		
	HRS	10913.9							
	AFL	5820							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
PROC. REF: AMM 28-11-00PROC. REF: AMM 28-11-00									
28-10-00-220-001-A01	INSPECT (DETAILED INSPECTION) OF FUEL TANKS (WINGS, WING STUB AND VENTRAL) FOR PRESENCE OF MICROORGANISM (L650 ONLY) NOTE 1: IF MODERATE OR HEAVY CONTAMINATION IS FOUND, FWD AND AFT FUEL TANKS MUST BE INSPECTED.NOTE 2: IF ENGINE FUEL FILTER ELEMENT HAS BEEN REPLACED, THE TASK 73-11-00-960-001-A00 MUST BE SIGNED OFFNOTE 3: EMB-RECOMMENDED								Service	ATA:28
	MOS/MSC	27-Aug-07	N/A						
	HRS	0							
	AFL	0							
PROC. REF: AMM 28-11-00PROC. REF: AMM 28-11-00									
28-11-00-280-001-A00	INSPECT (SPECIAL INSPECTION) FOR PRESENCE OF MICROORGANISMS IN THE FUEL TANKS. NOTE: THIS TASK IS NOT APPLICABLE IF THE OPERATOR DECIDES TO COMPLY WITH TASK 28-11-00-280-001-A01. NOTE: EMB-RECOMMENDED								Service	ATA:28
	MOS	16-Feb-26	6 (+15d/-15d)		16-Aug-26	31-Aug-26	82 d (+15)		
	HRS	11064.1							
	AFL	5912							
PROC. REF: AMM 28-11-00PROC. REF: AMM 28-11-00									
28-11-00-280-001-A01	INSPECT (SPECIAL INSPECTION) FOR PRESENCE OF MICRO ORGANISMS IN THE FUEL TANKS NOTE1: THIS TASK IS NOT APPLICABLE IF THE OPERATOR DECIDES TO COMPLY WITH TASK 28-11-00-280-001-A00								Service	ATA:28
	MOS	17-Oct-25	12 (+15d/-15d)		17-Oct-26	01-Nov-26	144 d (+15)		
	HRS	10913.9							
	AFL	5820							
PROC. REF: AMM 28-11-00PROC. REF: AMM 28-11-00									
28-11-00-720-001-A00 S	FUNCTIONALLY CHECK CRITICAL BONDING INTEGRITY OF SELECTED CONDUITS INSIDE THE WING TANK, FUEL PUMP AND FQIS CONNECTORS AT TANK WALL BY CONDUCTIVITY MEASUREMENTS. (L600 ONLY)								Service	ATA:28
	MOS	27-Aug-07	288 (+15d/-15d)					LOW UTILIZATION	
	HRS	0	12000 (+20/-20)						
	AFL	0	6000 (+20/-20)						
									PKG:5140
PROC. REF: AMM 28-11-00PROC. REF: AMM 28-11-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
28-11-00-720-002-A01		FUNCTIONALLY CHECK CRITICAL BONDING INTEGRITY OF SELECTED CONDUITS INSIDE THE WING TANK, FUEL PUMP CONNECTORS AT TANK WALL BY CONDUCTIVITY MEASUREMENTS. NOTE: APPLICABLE TO FUEL PUMPS WITH TANK WALL HERMETIC CONNECTOR (L650 ONLY)							Service ATA:28
	MOS/MSC	27-Aug-07	N/A						
	HRS	0							
	AFL	0							
PROC. REF: AMM 28-11-00PROC. REF: AMM 28-11-00									
28-11-00-720-003-A01		FUNCTIONALLY CHECK CRITICAL BONDING INTEGRITY OF SELECTED CONDUITS INSIDE THEWING TANK, FQIS CONNECTORS AT TANK WALL BY CONDUCTIVITY MEASUREMENTS (L650 ONLY)							Service ATA:28
	MOS/MSC	27-Aug-07	N/A						
	HRS	0							
	AFL	0							
PROC. REF: AMM 28-11-00PROC. REF: AMM 28-11-00									
28-11-04-710-001-A00 S		OPERATIONALLY CHECK FLAP VALVES (RIBS 1 AND 7) (MANUAL CHECK FOR FREE MOVEMENT AND SEALING CONDITION) NOTE: CHECK DURING INTERNAL TANK INSPECTION.							Service ATA:28
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: AMM 28-11-04PROC. REF: AMM 28-11-04									
28-12-01-710-001-A00 S		OPERATIONAL CHECK VENT FLOAT VALVES (MANUAL CHECK) (NOTE: CHECK DURING INTERNAL TANK INSPECTION).							Service ATA:28
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01									
28-12-04-710-001-A00 S		OPERATIONALLY CHECK FLAP VALVES (MANUAL CHECK FOR FREE MOVEMENT AND SEALING CONDITION). NOTE: CHECK DURING INTERNAL TANK INPECTION.							Service ATA:28
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: AMM 28-12-04PROC. REF: AMM 28-12-04									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
28-12-05-211-001-A00 S	VISUALLY CHECK FLAME ARRESTOR FOR HONEY COMB CLOGGING, AND ATTACHING PARTS FOR SECURITY.							Service	ATA:28
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 28-12-05PROC. REF: AMM 28-12-05									
28-12-05-710-001-A00 S	OPERATIONAL CHECK FLAME ARRESTOR IN/OUT FLOW VALVES FOR FREEDOM MOVEMENT.							Service	ATA:28
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 28-12-05PROC. REF: AMM 28-12-05									
28-13-00-220-001-A00 S	INSPECT (DETAILED INSPECTION) OF AFT FUEL TANKS							Service	ATA:28
	MOS	17-Oct-25	24 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	1000 (+20/-20)						
	AFL	5820							
									PKG:5007,6008
PROC. REF: AMM 28-13-02PROC. REF: AMM 28-13-02									
28-13-01-720-001-A00 S	FUNCTIONALLY CHECK AFT FUEL TANKS							Service	ATA:28
	MOS	17-Oct-25	24 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	1000 (+20/-20)						
	AFL	5820							
									PKG:5007
PROC. REF: AMM 28-13-01PROC. REF: AMM 28-13-01									
28-13-01-720-002-A00 S	FUNCTIONALLY CHECK AFT FUEL TANK CRITICAL BONDING INTEGRITY OF FUEL PUMP, FQGS AND LOW LEVEL SW CONNECTORS AT TANK WALL BY CONDUCTIVITY MEASUREMENTS.(L600 ONLY)							Service	ATA:28
	MOS	27-Aug-07	288 (+15d/-15d)					LOW UTILIZATION	
	HRS	0	12000 (+20/-20)						
	AFL	0	6000 (+20/-20)						
									PKG:5140
PROC. REF: AMM 28-13-01PROC. REF: AMM 28-13-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
28-13-01-720-003-A01	FUNCTIONALLY CHECK AFT FUEL TANK CRITICAL BONDING INTEGRITY OF FUEL PUMP CONNECTORS AT TANK WALL BY CONDUCTIVITY MEASUREMENTS(NOTE: APPLICABLE TO FUEL PUMPS WITH TANK WALL HERMETIC CONNECTOR) (L650 ONLY)							Service	ATA:28
	MOS/MSC	27-Aug-07	N/A						
	HRS	0							
	AFL	0							
PROC. REF: AMM 28-13-01PROC. REF: AMM 28-13-01									
28-13-01-720-004-A01	FUNCTIONALLY CHECK AFT FUEL TANK CRITICAL BONDING INTEGRITY OF FQGS CONNECTORS AT TANK WALL BY CONDUCTIVITY MEASUREMENTS(L650 ONLY)							Service	ATA:28
	MOS/MSC	27-Aug-07	N/A						
	HRS	0							
	AFL	0							
PROC. REF: AMM 28-13-01PROC. REF: AMM 28-13-01									
28-14-00-710-001-A00 S	OPERATIONALLY CHECK AFT FUEL TANK POSITIVE RELIEF SYSTEM							Service	ATA:28
	MOS	17-Oct-25	12 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	500 (+20/-20)						
	AFL	5820							
									PKG:5002
PROC. REF: AMM 28-14-00PROC. REF: AMM 28-14-00									
28-14-01-710-001-A00 S	OPERATIONAL CHECK AFT FUEL TANK FLOAT VENT VALVES PRE-MOD SB 145LEG-28-0019.(L600 ONLY)							Service	ATA:28
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: AMM 28-14-10PROC. REF: AMM 28-14-10									
28-14-04-720-001-A00 S	FUNCTIONALLY CHECK AFT FUEL TANKS POSITIVE RELIEF VALVE							Service	ATA:28
	MOS	17-Oct-25	24 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	1000 (+20/-20)						
	AFL	5820							
									PKG:5004
PROC. REF: AMM 28-14-13PROC. REF: AMM 28-14-13									

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
28-14-05-720-001-A00 S	FUNCTIONALLY CHECK AFT FUEL TANKS NEGATIVE RELIEF VALVE							Service	ATA:28
	MOS	17-Oct-25	24 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	1000 (+20/-20)						
	AFL	5820							
									PKG:5004
PROC. REF: AMM 28-14-14PROC. REF: AMM 28-14-14									
28-14-06-960-001-A00 S	DISCARD AFT-FUEL-TANK AIR FILTER							Service	ATA:28
	MOS	17-Oct-25	12 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	500 (+20/-20)						
	AFL	5820							
									PKG:5002
PROC. REF: AMM 28-14-15PROC. REF: AMM 28-14-15									
28-14-07-220-001-A00 S	INSPECT (DETAILED INSPECTION) OF AFT FUEL TANKS FLAME ARRESTORS. NOTE: FLAME ARRESTORS INSTALLED IN THE SKIN OF THE FUSELAGE AND FLAME ARRESTORS INSTALLED CLOSE TO CONTAINER BOX, IF INSTALLED.							Service	ATA:28
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 28-14-09PROC. REF: AMM 28-14-09									
28-14-08-710-001-A00	OPERATIONALLY CHECK 3/4 ZERO LEAKAGE CHECK VALVES. NOTE: CMR/ANAC-FAA-EASA. (CMR)							Service	ATA:28
	MOS	17-Oct-25	48 (+15d/-15d)		17-Oct-29	01-Nov-29	1240 d (+15)	LOW UTILIZATION	
	HRS	10913.9	1000		11913.9		637.6		
	AFL	5820							
									PKG:6003
PROC. REF: AMM 28-14-17PROC. REF: AMM 28-14-17									
28-14-09-710-001-A00 S	OPERATIONALLY CHECK 3/8 ZERO LEAKAGE CHECK VALVES. (CMR)							Service	ATA:28
	MOS	17-Oct-25	12 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	500 (+20/-20)						
	AFL	5820							
									PKG:5002
PROC. REF: AMM 28-14-17PROC. REF: AMM 28-14-17									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
28-14-10-710-001-A00 S	OPERATIONALLY CHECK AFT FUEL TANKS PRESSURIZATION VENT PLUMBING SHROUD (CMR)							Service	ATA:28
	MOS	17-Oct-25	24 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	1000 (+20/-20)						
	AFL	5820							
									PKG:5004
PROC. REF: AMM 28-13-01, AMM 28-13-01PROC. REF: AMM 28-13-01, AMM 28-13-01									
28-15-03-710-001-A00 S	OPERATIONALLY CHECK FORWARD FUEL TANKS FLAP VALVES							Service	ATA:28
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: AMM 28-15-03PROC. REF: AMM 28-15-03									
28-15-04-720-001-A00 S	FUNCTIONALLY CHECK FWD FUEL TANK CRITICAL BONDING INTEGRITY OF FUEL PUMP, FQGS AND LOW LEVEL SW CONNECTORS AT TANK WALL BY CONDUCTIVITY MEASUREMENTS.(L600 ONLY)							Service	ATA:28
	MOS	27-Aug-07	288 (+15d/-15d)					LOW UTILIZATION	
	HRS	0	12000 (+20/-20)						
	AFL	0	6000 (+20/-20)						
									PKG:5140
PROC. REF: AMM 28-15-04PROC. REF: AMM 28-15-04									
28-15-04-720-002-A01	FUNCTIONALLY CHECK FWD FUEL TANK CRITICAL BONDING INTEGRITY OF FUEL PUMPCONNECTORS AT TANK WALL BY CONDUCTIVITY MEASUREMENTS(NOTE: APPLICABLE TO FUEL PUMPS WITH TANK WALL HERMETIC CONNECTOR)(L650 ONLY)							Service	ATA:28
	MOS/MSC	27-Aug-07	N/A						
	HRS	0							
	AFL	0							
PROC. REF: AMM 28-15-04PROC. REF: AMM 28-15-04									
28-15-04-720-003-A01	FUNCTIONALLY CHECK FWD FUEL TANK CRITICAL BONDING INTEGRITY OF FQGS CONNECTORS AT TANK WALL BY CONDUCTIVITY MEASUREMENTS(L650 ONLY)							Service	ATA:28
	MOS/MSC	27-Aug-07	N/A						
	HRS	0							
	AFL	0							
PROC. REF: AMM 28-15-04PROC. REF: AMM 28-15-04									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
28-16-00-710-001-A00 S	OPERATIONALLY CHECK FUEL TANKS VENT OPEN CAUTION SYSTEM.							Service	ATA:28
	MOS	17-Oct-25	12 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	500 (+20/-20)						
	AFL	5820							
									PKG:5002
PROC. REF: AMM 28-16-00PROC. REF: AMM 28-16-00									
28-16-01-710-001-A00 S	OPERATIONALLY CHECK FORWARD FUEL TANKS FLOAT VALVES (MANUALLY CHECKED).							Service	ATA:28
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: AMM 28-16-01PROC. REF: AMM 28-16-01									
28-16-04-710-001-A00 S	OPERATIONALLY CHECK FORWARD FUEL TANKS AUTOMATIC FLOAT DRAIN VALVES.							Service	ATA:28
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: AMM 28-16-04PROC. REF: AMM 28-16-04									
28-16-05-220-001-A00 S	INSPECT (DETAILED INSPECTION) OF FORWARD FUEL TANK FLAME ARRESTORS.NOTE: FLAME ARRESTORS INSTALLED ON NACA AIR DUCT AND FLAME ARRESTORS INSTALLED ON REFUEL/OVERFILL VENTILATION LINE, IF INSTALLED.							Service	ATA:28
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 28-16-05PROC. REF: AMM 28-16-05									
28-17-01-720-002-A01	FUNCTIONALLY CHECK VENTRAL TANK CRITICAL BONDING INTEGRITY OF FUEL PUMP CONNECTORS AT TANK WALL BY CONDUCTIVITY MEASUREMENTS NOTE: APPLICABLE TO FUEL PUMPS WITH TANK WALL HERMETIC CONNECTOR (L650 ONLY)							Service	ATA:28
	MOS/MSC	27-Aug-07	N/A						
	HRS	0							
	AFL	0							
PROC. REF: AMM 28-17-01PROC. REF: AMM 28-17-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
28-17-01-720-003-A01	FUNCTIONALLY CHECK VENTRAL TANK CRITICAL BONDING INTEGRITY OF FQGS CONNECTORS AT TANK WALL BY CONDUCTIVITY MEASUREMENTS (L650 ONLY)							Service	ATA:28
	MOS/MSC	27-Aug-07	N/A						
	HRS	0							
	AFL	0							
PROC. REF: AMM 28-17-01PROC. REF: AMM 28-17-01									
28-17-03-710-001-A00	OPERATIONALLY CHECK VENTRAL FUEL TANK FLAP VALVES (L650 ONLY)							Service	ATA:28
	MOS/MSC	27-Aug-07	N/A						
	HRS	0							
	AFL	0							
									PKG:6032
PROC. REF: AMM 28-17-05PROC. REF: AMM 28-17-05									
28-17-04-710-001-A00	OPERATIONALLY CHECK VENTRAL FUEL TANK BAFFLE VALVES (L650 ONLY)							Service	ATA:28
	MOS/MSC	27-Aug-07	N/A						
	HRS	0							
	AFL	0							
									PKG:6032
PROC. REF: AMM 28-17-05PROC. REF: AMM 28-17-05									
28-18-01-710-001-A00	OPERATIONALLY CHECK VENTRAL FUEL TANK FLOAT VENT VALVES (L650 ONLY)							Service	ATA:28
	MOS/MSC	27-Aug-07	N/A						
	HRS	0							
	AFL	0							
									PKG:6032
PROC. REF: AMM 28-18-01PROC. REF: AMM 28-18-01									
28-18-03-710-001-A00	OPERATIONALLY CHECK VENTRAL FUEL TANK FLOAT ACTUATED DRAIN VALVE (L650 ONLY)							Service	ATA:28
	MOS/MSC	27-Aug-07	N/A						
	HRS	0							
	AFL	0							
									PKG:6032
PROC. REF: AMM 28-18-04PROC. REF: AMM 28-18-04									

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
28-21-01-220-001-A00 S	INSPECT (DETAILED INSPECTION) WING ELECTRIC FUEL PUMP CONNECTOR (L600 ONLY)							Service	ATA:28
	MOS	10-Jul-15	192 (+15d/-15d)					LOW UTILIZATION	
	HRS	7460.3	8000 (+20/-20)						
	AFL	3992	4000 (+20/-20)						
									PKG:5032,6032
PROC. REF: AMM 28-21-01PROC. REF: AMM 28-21-01									
28-21-03-720-001-A00 S	FUNCTIONALLY CHECK RELIEF VALVE NOTE: BENCH TEST							Service	ATA:28
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: AMM 28-21-03PROC. REF: AMM 28-21-03									
28-21-04-710-001-A00 S	OPERATIONALLY CHECK FUEL CROSSFEED VALVE							Service	ATA:28
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 28-21-04PROC. REF: AMM 28-21-04									
28-21-10-710-001-A00 S	OPERATIONALLY CHECK FUEL FEED LINE SHROUD							Service	ATA:28
	MOS	17-Oct-25	72 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	3000 (+20/-20)						
	AFL	5820	1500 (+20/-20)						
									PKG:5012,6020
PROC. REF: AMM 28-21-10PROC. REF: AMM 28-21-10									
28-22-03-710-001-A00 S	OPERATIONALLY CHECK APU FUEL FEED LINE SHROUD							Service	ATA:28
	MOS	17-Oct-25	72 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	3000 (+20/-20)						
	AFL	5820	1500 (+20/-20)						
									PKG:5012,6020
PROC. REF: AMM 28-22-03PROC. REF: AMM 28-22-03									

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
28-23-03-220-001-A00 S	INSPECT (DETAILED INSPECTION) PILOT VALVE HARNESS INSIDE THE CONDUIT.(L600 ONLY)							Service	ATA:28
	MOS	27-Aug-07	288 (+15d/-15d)					LOW UTILIZATION	
	HRS	0	12000 (+20/-20)						
	AFL	0	6000 (+20/-20)						
									PKG:5140
PROC. REF: AMM 28-23-03PROC. REF: AMM 28-23-03									
28-23-04-220-001-A00 S	INSPECT (DETAILED INSPECTION) VENT VALVE HARNESS INSIDE THE CONDUIT (L600 ONLY)							Service	ATA:28
	MOS	27-Aug-07	288 (+15d/-15d)					LOW UTILIZATION	
	HRS	0	12000 (+20/-20)						
	AFL	0	6000 (+20/-20)						
									PKG:5140
PROC. REF: AMM 28-23-04PROC. REF: AMM 28-23-04									
28-23-04-220-001-A01	INSPECT (DETAILED INSPECTION) VENT VALVE HARNESS INSIDE THE CONDUIT (L650 ONLY)							Service	ATA:28
	MOS/MSC	27-Aug-07	N/A						
	HRS	0							
	AFL	0							
									PKG:6032
PROC. REF: AMM 28-23-04PROC. REF: AMM 28-23-04									
28-26-00-710-001-A00 S	OPERATIONALLY CHECK OF FWD PUMP AND CIRCUITRY							Service	ATA:28
	MOS	17-Oct-25	24 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	1000 (+20/-20)						
	AFL	5820							
									PKG:5004
PROC. REF: AMM 28-26-00PROC. REF: AMM 28-26-00									
28-26-00-720-001-A00 S	FUNCTIONALLY CHECK AFT/FWD TRANSFER FUEL TANKS TRANSFER CHECK RELIEF VALVES							Service	ATA:28
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: AMM 28-26-00PROC. REF: AMM 28-26-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
28-26-16-710-001-A00 S	OPERATIONALLY CHECK FUEL TRANSFER LINE SHROUD.							Service	ATA:28
	MOS	17-Oct-25	72 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	3000 (+20/-20)						
	AFL	5820	1500 (+20/-20)						
									PKG:5012,6020
PROC. REF: AMM 28-13-01PROC. REF: AMM 28-13-01									
28-26-18-710-001-A00 S	OPERATIONALLY CHECK AFT TANK ELECTRICAL ISOLATING SHUT-OFF VALVE AND CIRCUITRY							Service	ATA:28
	MOS	17-Oct-25	12 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	500 (+20/-20)						
	AFL	5820							
									PKG:5002
PROC. REF: AMM 28-26-18PROC. REF: AMM 28-26-18									
28-26-21-710-001-A00 S	OPERATIONALLY CHECK FORWARD TANKS LOW LEVEL SWITCH (L600 ONLY)							Service	ATA:28
	MOS	17-Oct-25	24 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	1000 (+20/-20)						
	AFL	5820							
									PKG:5004
PROC. REF: AMM 28-26-21PROC. REF: AMM 28-26-21									
28-26-21-710-001-A01	OPERATIONALLY CHECK FORWARD TANKS LOW LEVEL SENSOR (L650 ONLY)							Service	ATA:28
	MOS/MSC	25-Sep-07	N/A					SYSTEM	
	HRS	0							
	AFL	0							
PROC. REF: AMM 28-26-21PROC. REF: AMM 28-26-21									
28-26-22-710-001-A00 S	OPERATIONALLY CHECK AFT TANKS LOW LEVEL SWITCH (L600 ONLY)							Service	ATA:28
	MOS	17-Oct-25	24 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	1000 (+20/-20)						
	AFL	5820							
									PKG:5004
PROC. REF: AMM 28-26-22PROC. REF: AMM 28-26-22									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
28-26-22-710-001-A01	OPERATIONALLY CHECK AFT TANKS LOW LEVEL SENSOR (L650 ONLY)							Service	ATA:28
	MOS/MSC	25-Sep-07	N/A					SYSTEM	
	HRS	0							
	AFL	0							
PROC. REF: AMM 28-26-22PROC. REF: AMM 28-26-22									
28-26-24-710-001-A00 S	OPERATIONALLY CHECK AFT TANKS TRANSFER CHECK VALVE							Service	ATA:28
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: AMM 28-26-23PROC. REF: AMM 28-26-23									
28-41-00-220-001-A01	INSPECT (DETAILED INSPECTION) W1642 INTRINSICALLY SAFE HARNESSES FOR SLEEVE INTEGRITY(L650 ONLY)							Service	ATA:28
	MOS/MSC	27-Aug-07	N/A						
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: AMM 28-41-00PROC. REF: AMM 28-41-00									
28-41-00-710-001-A00 S	OPERATIONALLY CHECK ELECTRICAL FUEL QUANTITY INDICATING SYSTEM (FUEL LOW LEVEL LOGIC) (L600 ONLY)							Service	ATA:28
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 28-41-00PROC. REF: AMM 28-41-00									
28-41-01-720-001-A01 S	FUNCTIONALLY CHECK THE SAFE LIFE FEATURES OF THE FUEL CONDITIONING UNIT (FCU). - INITIAL FUNCTIONAL CHECK, - EXTERNAL VISUAL INSPECTION, - INTERNAL VISUAL INSPECTION, -FUNCTIONAL CHECK OF THE SAFE LIFE FEATURE, - FINAL FUNCTIONAL CHECK. (L600 ONLY)							Service	ATA:28
	MOS	06-Jul-15	192 (+15d/-15d)					LOW UTILIZATION	
	HRS	7460.3	8000 (+20/-20)						
	AFL	3992	4000 (+20/-20)						
									PKG:5032,6032
PROC. REF: AMM 28-41-01PROC. REF: AMM 28-41-01									

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
28-41-03-220-001-A00 S	INSPECT (DETAILED INSPECTION) FQIS HARNESS FOR CLAMP AND WIRE JACKET INTEGRITY (L600 ONLY)							Service	ATA:28
	MOS	27-Aug-07	288 (+15d/-15d)					LOW UTILIZATION	
	HRS	0	12000 (+20/-20)						
	AFL	0	6000 (+20/-20)						
									PKG:5140
PROC. REF: AMM 28-41-03PROC. REF: AMM 28-41-03									
28-41-03-220-001-A01	INSPECT (DETAILED INSPECTION) FQIS HARNESS FOR CLAMP AND WIRE JACKET INTEGRITY. (L650 ONLY)							Service	ATA:28
	MOS/MSC	27-Aug-07	N/A						
	HRS	0							
	AFL	0							
									PKG:6032
PROC. REF: AMM 28-41-03PROC. REF: AMM 28-41-03									
28-41-07-220-001-A01	INSPECT (DETAILED INSPECTION) VENTRAL TANK INTERNAL INSPECTION: FQGS HARNESS FOR CLAMP AND WIRE JACKET INTEGRITY. (L650 ONLY)							Service	ATA:28
	MOS/MSC	27-Aug-07	N/A						
	HRS	0							
	AFL	0							
									PKG:6032
PROC. REF: AMM 28-41-06PROC. REF: AMM 28-41-06									
28-43-00-720-001-A00 S	FUNCTIONALLY CHECK FUEL TEMPERATURE INDICATION SYSTEM							Service	ATA:28
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: AMM 28-43-00PROC. REF: AMM 28-43-00									
28-44-00-720-001-A00 S	FUNCTIONALLY CHECK FUEL LOW LEVEL WARNING SYSTEM NOTE: CHECK DURING INTERNAL TANK INSPECTION							Service	ATA:28
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: AMM 28-44-00PROC. REF: AMM 28-44-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
28-45-00-710-001-A00 S	OPERATIONALLY CHECK FUEL LOW PRESSURE WARNING SYSTEM							Service	ATA:28
	MOS	17-Oct-25	24 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	1000 (+20/-20)						
	AFL	5820							
									PKG:5004
PROC. REF: AMM 28-45-00PROC. REF: AMM 28-45-00									
28-46-00-710-001-A00 S	OPERATIONAL CHECK "FUSELAGE FUEL IMB" WARNING SYSTEM (L600 ONLY)							Service	ATA:28
	MOS	17-Oct-25	12 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	500 (+20/-20)						
	AFL	5820							
									PKG:5002
PROC. REF: AMM 28-46-00PROC. REF: AMM 28-46-00									
28-46-00-710-001-A01	OPERATIONALLY CHECK "FUSELAGE FUEL IMB" AND"FUEL XFER CRITICAL" CAUTION SYSTEM (L650 ONLY)							Service	ATA:28
	MOS/MSC	25-Sep-07	N/A					SYSTEM	
	HRS	0							
	AFL	0							
PROC. REF: AMM 28-46-00PROC. REF: AMM 28-46-00									
28-46-00-720-001-A00 S	FUNCTIONALLY CHECK "CHECK ACFT LOAD OR FUEL XFER CRITICAL" WARNING SYSTEM (L600 ONLY)							Service	ATA:28
	MOS	17-Oct-25	24 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	1000 (+20/-20)						
	AFL	5820							
									PKG:5004
PROC. REF: AMM 28-46-00PROC. REF: AMM 28-46-00									
28-46-00-720-002-A00 S	FUNCTIONALLY CHECK OF AUXILIARY TANKS PROBES AND FCU							Service	ATA:28
	MOS	17-Oct-25	24 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	1000 (+20/-20)						
	AFL	5820							
									PKG:5004
PROC. REF: AMM 28-46-00PROC. REF: AMM 28-46-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
28-46-02-220-001-A00 S	INSPECT (DETAILED INSPECTION) AFT FUEL TANK INTERNAL INSPECTION: FQGS HARNESS AND LOW LEVEL SW HARNESS FOR CLAMP AND WIRE JACKET INTEGRITY.(L600 ONLY)							Service	ATA:28
	MOS	27-Aug-07	288 (+15d/-15d)					LOW UTILIZATION	
	HRS	0	12000 (+20/-20)						
	AFL	0	6000 (+20/-20)						
									PKG:5140
PROC. REF: AMM 28-46-02PROC. REF: AMM 28-46-02									
28-46-02-220-001-A01	INSPECT (DETAILED INSPECTION) AFT FUEL TANK: FQGS HARNESS FOR CLAMP AND WIRE JACKET INTEGRITY.(L650 ONLY)							Service	ATA:28
	MOS/MSC	27-Aug-07	N/A						
	HRS	0							
	AFL	0							
									PKG:6032
PROC. REF: AMM 28-46-02PROC. REF: AMM 28-46-02									
28-46-04-220-001-A00 S	INSPECT (DETAILED INSPECTION) FWD FUEL TANK INTERNAL INSPECTION: FQGS HARNESS AND LOW LEVEL SW HARNESS FOR CLAMP AND WIRE JACKET INTEGRITY.(L600 ONLY)							Service	ATA:28
	MOS	27-Aug-07	288 (+15d/-15d)					LOW UTILIZATION	
	HRS	0	12000 (+20/-20)						
	AFL	0	6000 (+20/-20)						
									PKG:5140
PROC. REF: AMM 28-46-04PROC. REF: AMM 28-46-04									
28-46-04-220-001-A01	INSPECT (DETAILED INSPECTION) FWD FUEL TANK INTERNAL INSPECTION: FQGS HARNESS FOR CLAMP AND WIRE JACKET INTEGRITY. (L650 ONLY)							Service	ATA:28
	MOS/MSC	27-Aug-07	N/A						
	HRS	0							
	AFL	0							
									PKG:6032
PROC. REF: AMM 28-46-04PROC. REF: AMM 28-46-04									
28-46-05-720-001-A01 S	FUNCTIONALLY CHECK THE SAFE LIFE FEATURES OF THE AUXILIARY FUEL CONDITIONING UNIT (AFCU). - INITIAL FUNCTIONAL CHECK, - EXTERNAL VISUAL INSPECTION, - INTERNAL VISUAL INSPECTION, -FUNCTIONAL CHECK OF THE SAFE LIFE FEATURE, - FINAL FUNCTIONAL CHECK (L600 ONLY)							Service	ATA:28
	MOS	06-Jul-15	192 (+15d/-15d)					LOW UTILIZATION	
	HRS	7460.3	8000 (+20/-20)						
	AFL	3992	4000 (+20/-20)						
									PKG:5032,6032
PROC. REF: AMM 28-46-05PROC. REF: AMM 28-46-05									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
28-50-01-220-001-A00 S	INSPECT (DETAILED INSPECTION) FUEL PUMP ELECTRICAL HARNESS NOTE: THIS TASK COMPLIES WITH FUEL TANK IGNITION SOURCES PREVENTION (SFAR-88)(L600 ONLY)							Service	ATA:28
	MOS	31-Jul-15	192 (+15d/-15d)					LOW UTILIZATION	
	HRS	7460.3	8000 (+20/-20)						
	AFL	3992	4000 (+20/-20)						
									PKG:5032,6032
PROC. REF: AMM 28-21-01, AMM 28-26-08PROC. REF: AMM 28-21-01, AMM 28-26-08									
28-50-01-220-001-A01	DETAILED INSPECTION FUEL PUMP ELECTRICAL HARNESS AND CONNECTORS NOTE: APPLICABLE TO FUEL PUMPS WITH TANK WALL HERMETIC CONNECTOR (L650 ONLY)							Service	ATA:28
	MOS/MSC	27-Aug-07	N/A						
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: AMM 28-21-01, AMM 28-26-08, AMM 28-26-01PROC. REF: AMM 28-21-01, AMM 28-26-08, AMM 28-26-01									
28-50-01-220-001-A02	INSPECT (DETAILED INSPECTION) FUEL PUMP ELECTRICAL HARNESS CHA (CABLE HARNESS ASSEMBLY) END FITTING (L650 ONLY)							Service	ATA:28
	MOS/MSC	27-Aug-07	N/A						
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: AMM 28-21-01PROC. REF: AMM 28-21-01									
28-50-01-720-001-A00	FUNCTIONALLY CHECK FUEL PUMP ELECTRICAL HARNESS FOR LEAKAGE NOTE: APPLICABLE TO AIRCRAFT WITH FUEL PUMP HARNESSWITH CORRUGATED CONDUIT.ZONE: 155/156 157/197 271/272 1972 (L650 ONLY)							Service	ATA:28
	MOS/MSC	27-Aug-07	N/A						
	HRS	0							
	AFL	0							
									PKG:6032
PROC. REF: AMM 28-21-01PROC. REF: AMM 28-21-01									
28-50-02-220-001-A00 S	INSPECT (DETAILED INSPECTION) WING FUEL TANK UNIT NOTE: THIS TASK COMPLIES WITH FUEL TANK IGNITION SOURCES PREVENTION (SFAR-88).(L600 ONLY)							Service	ATA:28
	MOS	10-Jul-15	192 (+15d/-15d)					LOW UTILIZATION	
	HRS	7460.3	8000 (+20/-20)						
	AFL	3992	4000 (+20/-20)						
									PKG:5032,6032

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
PROC. REF: AMM 28-41-02PROC. REF: AMM 28-41-02									
28-50-02-220-001-A01	INSPECT (DETAILED INSPECTION) WING FUEL TANK UNITS (L650 ONLY)							Service	ATA:28
	MOS/MSC	27-Aug-07	N/A						
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: AMM 28-41-02PROC. REF: AMM 28-41-02									
28-50-03-220-002-A00 S	INSPECT (DETAILED INSPECTION) FWD FUEL TANK UNIT NOTE: THIS TASK COMPLIES WITH FUEL TANK IGNITION SOURCES PREVENTION (SFAR-88) (L600 ONLY)							Service	ATA:28
	MOS	10-Jul-15	192 (+15d/-15d)				LOW UTILIZATION		
	HRS	7460.3	8000 (+20/-20)						
	AFL	3992	4000 (+20/-20)						
									PKG:5032,6032
PROC. REF: AMM 28-46-03PROC. REF: AMM 28-46-03									
28-50-03-220-002-A01	INSPECT (DETAILED INSPECTION) FWD FUEL TANK UNITS (L650 ONLY)							Service	ATA:28
	MOS/MSC	27-Aug-07	N/A						
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: AMM 28-46-03PROC. REF: AMM 28-46-03									
28-50-04-212-001-A00 S	INSPECT (GENERAL VISUAL) WING STUB HARNESS NOTE: THIS TASK COMPLIES WITH FUEL TANK IGNITION SOURCES PREVENTION (SFAR-88) (L600 ONLY)							Service	ATA:28
	MOS	10-Jul-15	192 (+15d/-15d)				LOW UTILIZATION		
	HRS	7460.3	8000 (+20/-20)						
	AFL	3992	4000 (+20/-20)						
									PKG:5032,6032
PROC. REF: AMM 24-00-04PROC. REF: AMM 24-00-04									
28-50-04-212-001-A01	INSPECT (GENERAL VISUAL) WING STUB HARNESS (L650 ONLY)							Service	ATA:28
	MOS/MSC	27-Aug-07	N/A						
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: AMM 24-00-04PROC. REF: AMM 24-00-04									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
28-50-05-212-001-A00 S	INSPECT (GENERAL VISUAL) TRAILING EDGE HARNESS NOTE: THIS TASK COMPLIES WITH FUEL TANK IGNITION SOURCES PREVENTION (SFAR-88) (L600 ONLY)							Service	ATA:28
	MOS	10-Jul-15	192 (+15d/-15d)				LOW UTILIZATION		
	HRS	7460.3	8000 (+20/-20)						
	AFL	3992	4000 (+20/-20)						
									PKG:5032,6032
PROC. REF: AMM 24-00-03PROC. REF: AMM 24-00-03									
28-50-05-212-001-A01	INSPECT (GENERAL VISUAL) TRAILING EDGE HARNESS (L650 ONLY)							Service	ATA:28
	MOS/MSC	27-Aug-07	N/A						
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: AMM 24-00-03PROC. REF: AMM 24-00-03									
28-50-06-212-001-A00 S	INSPECT (GENERAL VISUAL) LEADING EDGE HARNESS NOTE: THIS TASK COMPLIES WITH FUEL TANK IGNITION SOURCES PREVENTION (SFAR-88) (L600 ONLY)							Service	ATA:28
	MOS	10-Jul-15	192 (+15d/-15d)				LOW UTILIZATION		
	HRS	7460.3	8000 (+20/-20)						
	AFL	3992	4000 (+20/-20)						
									PKG:5032,6032
PROC. REF: AMM 24-00-02PROC. REF: AMM 24-00-02									
28-50-06-212-001-A01	INSPECT (GENERAL VISUAL) LEADING EDGE HARNESS (L650 ONLY)							Service	ATA:28
	MOS/MSC	27-Aug-07	N/A						
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: AMM 24-00-02PROC. REF: AMM 24-00-02									
28-50-07-220-001-A00 S	INSPECT (DETAILED INSPECTION) AFT FUEL TANK UNITS NOTE: THIS TASK COMPLIES WITH FUEL TANK IGNITION SOURCES PREVENTION (SFAR-88) (L600 ONLY)							Service	ATA:28
	MOS	31-Jul-15	192 (+15d/-15d)				LOW UTILIZATION		
	HRS	7460.3	8000 (+20/-20)						
	AFL	3992	4000 (+20/-20)						
									PKG:5032,6032
PROC. REF: AMM 28-46-01PROC. REF: AMM 28-46-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
28-50-07-220-001-A01	INSPECT (DETAILED INSPECTION) AFT FUEL TANK UNITS (L650 ONLY)							Service	ATA:28
	MOS/MSC	27-Aug-07	N/A						
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: AMM 28-46-01PROC. REF: AMM 28-46-01									
28-50-08-212-001-A00	INSPECT (GENERAL VISUAL) VENTRAL FUEL TANK EXTERNAL HARNESS(L650 ONLY)							Service	ATA:28
	MOS/MSC	27-Aug-07	N/A						
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: AMM 28-27-01PROC. REF: AMM 28-27-01									
28-50-08-220-001-A00	INSPECT (DETAILED INSPECTION) VENTRAL FUEL TANK UNITS (L650 ONLY)							Service	ATA:28
	MOS/MSC	27-Aug-07	N/A						
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: AMM 28-41-05PROC. REF: AMM 28-41-05									
28-50-09-212-001-A00	INSPECT (GENERAL VISUAL) FWD FUEL TANK EXTERNAL HARNESS(L650 ONLY)							Service	ATA:28
	MOS/MSC	27-Aug-07	N/A						
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: AMM 28-26-01PROC. REF: AMM 28-26-01									
28-50-10-212-001-A00	INSPECT (GENERAL VISUAL) AFT FUEL TANK EXTERNAL HARNESS(L650 ONLY)							Service	ATA:28
	MOS/MSC	27-Aug-07	N/A						
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: AMM 28-26-08PROC. REF: AMM 28-26-08									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
281200-0101	LH WING FLOAT VENT VALVE							Component	ATA:28
PN:2930015-102	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01									
281200-0102	LH WING FLOAT VENT VALVE							Component	ATA:28
PN:2930015-102	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01									
281200-0103	RH WING FLOAT VENT VALVE							Component	ATA:28
PN:2930015-102	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01									
281200-0104	RH WING FLOAT VENT VALVE							Component	ATA:28
PN:2930015-102	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01									
281200-0105	FWR TK FLOAT VENT VALVE							Component	ATA:28
PN:2930015-102	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01									
281200-0106	FWR TK FLOAT VENT VALVE							Component	ATA:28
PN:2930015-102	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
281200-0107	FWR TK FLOAT VENT VALVE							Component	ATA:28
PN:2930015-102	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-12-01	PROC. REF: AMM 28-12-01								
281200-0108	FWR TK FLOAT VENT VALVE							Component	ATA:28
PN:2930015-102	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-12-01	PROC. REF: AMM 28-12-01								
281205-0201	LH WING FLAME ARRESTOR							Component	ATA:28
PN:130-0045-01	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:2358	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-12-05	PROC. REF: AMM 28-12-05								
281205-0202	RH WING FLAME ARRESTOR							Component	ATA:28
PN:130-0045-01	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:2359	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-12-05	PROC. REF: AMM 28-12-05								
281300-0101	LH REAR FUEL TANK ASSEMBLY							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-13-01	PROC. REF: AMM 28-13-01								
281300-0102	RH REAR FUEL TANK ASSEMBLY							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-13-01	PROC. REF: AMM 28-13-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
281300-0103		FORWARD FUEL TANK ASSEMBLY						Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-15-04PROC. REF: AMM 28-15-04									
281301-0101		REAR LH ALL RUBBER FUEL TANK						Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-13-01PROC. REF: AMM 28-13-01									
281301-0102		REAR RH ALL RUBBER FUEL TANK						Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-13-01PROC. REF: AMM 28-13-01									
281302-0701 U		LH AFT FUEL TANK BLADDER VALVE						Component	ATA:28
PN:RAHE40371	MOS/MSC	19-Aug-16	O/C	TSN 0					
SN:384	HRS	7460.3		TSN 0					
	AFL	3992		TSN 0					
281302-0702 U		RH AFT FUEL TANK BLADDER VALVE						Component	ATA:28
PN:RAHE40371	MOS/MSC	19-Aug-16	O/C	TSN 0					
SN:393	HRS	7460.3		TSN 0					
	AFL	3992		TSN 0					
281400-0101		REAR TK CHECK-TYPE BUTTERFLY,INTERNAL TANK,FUEL SYSTEM VALVE						Component	ATA:28
PN:2000034-102	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
281400-0102	REAR TK CHECK-TYPE BUTTERFLY,INTERNAL TANK,FUEL SYSTEM VALVE							Component	ATA:28
PN:2000034-102	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-21-03PROC. REF: AMM 28-21-03									
281400-0103	REAR TK CHECK-TYPE BUTTERFLY,INTERNAL TANK,FUEL SYSTEM VALVE							Component	ATA:28
PN:2000034-102	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-21-03PROC. REF: AMM 28-21-03									
281400-0104	REAR TK CHECK-TYPE BUTTERFLY,INTERNAL TANK,FUEL SYSTEM VALVE							Component	ATA:28
PN:2000034-102	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-21-03PROC. REF: AMM 28-21-03									
281400-0105	REAR TK CHECK-TYPE BUTTERFLY,INTERNAL TANK,FUEL SYSTEM VALVE							Component	ATA:28
PN:2000034-102	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-21-03PROC. REF: AMM 28-21-03									
281400-0106	REAR TK CHECK-TYPE BUTTERFLY,INTERNAL TANK,FUEL SYSTEM VALVE							Component	ATA:28
PN:2000034-102	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-21-03PROC. REF: AMM 28-21-03									
281400-0201	REAR TK VALVE CHECK-FUEL TANK, FUSELAGE ASSEMBLY							Component	ATA:28
PN:869A-12BT	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
281400-0202	REAR TK VALVE CHECK-FUEL TANK, FUSELAGE ASSEMBLY							Component	ATA:28
PN:869A-12BT	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
281400-0203	REAR TK VALVE CHECK-FUEL TANK, FUSELAGE ASSEMBLY							Component	ATA:28
PN:869A-12BT	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
281400-0204	REAR TK VALVE CHECK-FUEL TANK, FUSELAGE ASSEMBLY							Component	ATA:28
PN:869A-12BT	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
281400-0301	REAR SEAT SHUTOFF ASSY-FUEL SYS VALVE							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-23-02PROC. REF: AMM 28-23-02									
281400-0302	FWDSEAT SHUTOFF ASSY-FUEL SYS VALVE							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-23-02PROC. REF: AMM 28-23-02									
281400-0303	X FEED SHUTOFF ASSY-FUEL SYS VALVE							Component	ATA:28
PN:2930003-103	MOS/MSC	11-Dec-12	O/C	TSO 0					
SN:6301	HRS	6440.4		TSO 0					
	AFL	3467		TSO 0					
PROC. REF: AMM 28-23-02PROC. REF: AMM 28-23-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
281400-0304	REAR TK CROSSFEED SHUTOFF ASSY-FUEL SYS VALVE							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-21-04	PROC. REF: AMM 28-21-04								
281400-0305	FWRTK SHUTOFF ASSY-FUEL SYS VALVE							Component	ATA:28
PN:2930003-104	MOS/MSC	15-Aug-13	O/C						
SN:4641	HRS	6643.4							
	AFL	3572							
PROC. REF: AMM 28-23-02	PROC. REF: AMM 28-23-02								
281400-0306	W STUB SHUTOFF ASSY-FUEL SYS VALVE							Component	ATA:28
PN:2930003-103	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:6833	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-23-02	PROC. REF: AMM 28-23-02								
281400-0307	STUB SHUTOFF ASSY-FUEL SYS VALVE							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-23-02	PROC. REF: AMM 28-23-02								
281400-0308	APU SHUTOFF ASSY-FUEL SYS VALVE							Component	ATA:28
PN:293003-105	MOS/MSC	06-Jul-19	O/C	TSR 0					
SN:7335M	HRS	9057.4		TSR 0					
	AFL	4853		TSR 0					
PROC. REF: AMM 28-23-02	PROC. REF: AMM 28-23-02								
281400-0309	LH ENG SHUTOFF ASSY-FUEL SYS VALVE							Component	ATA:28
PN:2930003-104	MOS/MSC	12-Dec-12	O/C						
SN:6291	HRS	6440.4							
	AFL	3467							
PROC. REF: AMM 28-23-02	PROC. REF: AMM 28-23-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
281400-0310		RH ENG SHUTOFF ASSY-FUEL SYS VALVE						Component	ATA:28
PN:2930003-104	MOS/MSC	19-Aug-15	O/C	TSR 0					
SN:6584	HRS	7460.3		TSR 0					
	AFL	3992		TSR 0					
PROC. REF: AMM 28-23-02	PROC. REF: AMM 28-23-02								
281400-0311		LEFT REAR TK ENGINE SHUTOFF ASSY-FUEL SYS VALVE						Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-21-05	PROC. REF: AMM 28-21-05								
281400-0312		RIGHT REAR TK ENGINE SHUTOFF ASSY-FUEL SYS VALVE						Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-21-05	PROC. REF: AMM 28-21-05								
281400-0313		FWR TK SHUTOFF ASSY-FUEL SYS VALVE						Component	ATA:28
PN:2930003-104	MOS/MSC	15-Aug-13	O/C						
SN:6995	HRS	6643.4							
	AFL	3572							
PROC. REF: AMM 28-23-02	PROC. REF: AMM 28-23-02								
281400-0314		REAR TK SHUTOFF VALVE ASSY						Component	ATA:28
PN:2930003-104	MOS/MSC	15-Aug-13	O/C						
SN:4283	HRS	6643.4							
	AFL	3572							
PROC. REF: AMM 28-23-02	PROC. REF: AMM 28-23-02								
281400-0316		STUB SHUTOFF ASSY-FUEL SYS VALVE						Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-23-02	PROC. REF: AMM 28-23-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
281400-0401	REAR TK ASSY,RELIEF LINE-INT TNK,AL SENSOR							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
281400-0402	REAR TK ASSY,RELIEF LINE-INT TNK,AL SENSOR							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
281400-0501	FWR TK DRAIN-FUEL SYS VALVE							Component	ATA:28
PN:2990076-102	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-11-02PROC. REF: AMM 28-11-02									
281400-0502	FWR TK DRAIN-FUEL SYS VALVE							Component	ATA:28
PN:2990076-102	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-11-02PROC. REF: AMM 28-11-02									
281400-0503	REAR TK DRAIN-FUEL SYS VALVE							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-11-02PROC. REF: AMM 28-11-02									
281400-0504	REAR TK DRAIN-FUEL SYS VALVE							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-11-02PROC. REF: AMM 28-11-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
281400-0505	LEFT FUSELAGE TANK DRAIN-FUEL SYS VALVE							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-11-02PROC. REF: AMM 28-11-02									
281400-0506	RIGHT FUSELAGE TANK DRAIN-FUEL SYS VALVE							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-11-02PROC. REF: AMM 28-11-02									
281400-0507	VENTRAL TANK NO.1 DRAIN-FUEL SYS VALVE							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-11-02PROC. REF: AMM 28-11-02									
281400-0508	VENTRAL TANK NO.2 DRAIN-FUEL SYS VALVE							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-11-02PROC. REF: AMM 28-11-02									
281400-0509	VENTRAL TANK NO.3 VENTRAL TANK VALVE							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
281400-0601	REAR TK RELIEF-INTERNAL TANK,FUEL SYSTEM VALVE							Component	ATA:28
PN:2000062-103	MOS/MSC	25-Jun-19	O/C	TSN 32					
SN:2367	HRS	9057.4		TSN 773.3					
	AFL	4853		TSN 407					
PROC. REF: AMM 28-14-13, AMM 28-14-14PROC. REF: AMM 28-14-13, AMM 28-14-14									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
281400-0602		REAR TK RELIEF-INTERNAL TANK,FUEL SYSTEM VALVE						Component	ATA:28
PN:2000062-103	MOS/MSC	25-Jun-19	O/C	TSN 32					
SN:2355	HRS	9057.4		TSN 773.3					
	AFL	4853		TSN 407					
PROC. REF: AMM 28-14-13, AMM 28-14-14PROC. REF: AMM 28-14-13, AMM 28-14-14									
281400-0603		L/H AFT TANK DIFFERENTIAL PRESSURE SWITCH						Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-21-03PROC. REF: AMM 28-21-03									
281400-0604		R/H AFT TANK DIFFERENTIAL PRESSURE SWITCH						Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
281400-0701		LH REAR FUEL TANK RELIEF VALVE						Component	ATA:28
PN:2000031-102	MOS/MSC	29-Jun-23	O/C						
SN:0567	HRS	10161.5							
	AFL	5401							
PROC. REF: AMM 28-14-13, AMM 28-14-14PROC. REF: AMM 28-14-13, AMM 28-14-14									
281400-0702		RH REAR FUEL TANK RELIEF VALVE						Component	ATA:28
PN:2000031-102	MOS/MSC	29-Jun-23	O/C						
SN:0568	HRS	10161.5							
	AFL	5401							
PROC. REF: AMM 28-14-13, AMM 28-14-14PROC. REF: AMM 28-14-13, AMM 28-14-14									
281400-0801		FWR TK ARRESTOR-FLAME,VENT LINE						Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-16-05PROC. REF: AMM 28-16-05									

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
281400-0802		FWR TK ARRESTOR-FLAME,VENT LINE						Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-16-05PROC. REF: AMM 28-16-05									
281400-0803		REAR TK ARRESTOR-FLAME,VENT LINE						Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-16-05PROC. REF: AMM 28-16-05									
281400-0804		REAR TK ARRESTOR-FLAME,VENT LINE						Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-16-05PROC. REF: AMM 28-16-05									
281400-0901		LH WING CHECK-TYPE BUTTERFLY,INTERNAL TANK,FUEL SYSTEM VALVE						Component	ATA:28
PN:2000034-102	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
281400-0902		RH WING CHECK-TYPE BUTTERFLY,INTERNAL TANK,FUEL SYSTEM VALVE						Component	ATA:28
PN:2000034-102	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
281400-0903		LH WING CHECK-TYPE BUTTERFLY,INTERNAL TANK,FUEL SYSTEM VALVE						Component	ATA:28
PN:2000034-102	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-21-03PROC. REF: AMM 28-21-03									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
281400-0904	RH WING CHECK-TYPE BUTTERFLY,INTERNAL TANK,FUEL SYSTEM VALVE							Component	ATA:28
PN:2000034-102	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-21-03PROC. REF: AMM 28-21-03									
281501-0101	REAR TK ELECTRICAL-FUEL SYSTEM, INTERNAL PUMP							Component	ATA:28
PN:1C7-25	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-21-01PROC. REF: AMM 28-21-01									
281501-0102	REAR TK ELECTRICAL-FUEL SYSTEM, INTERNAL PUMP							Component	ATA:28
PN:1C7-25	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-21-01PROC. REF: AMM 28-21-01									
281501-0103	FWR TK ELECTRICAL-FUEL SYSTEM, INTERNAL PUMP							Component	ATA:28
PN:1C7-25	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-21-01PROC. REF: AMM 28-21-01									
281501-0104	FWR TK ELECTRICAL-FUEL SYSTEM,INTERNAL PUMP							Component	ATA:28
PN:1C7-25	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-21-01PROC. REF: AMM 28-21-01									
281501-0105	FWR TK ELECTRICAL-FUEL SYSTEM,INTERNAL PUMP							Component	ATA:28
PN:1C7-25	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-21-01PROC. REF: AMM 28-21-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
281501-0106		FWR TK ELECTRICAL-FUEL SYSTEM,INTERNAL PUMP						Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-21-01PROC. REF: AMM 28-21-01									
281501-0107		LEFT VENTRAL TANK ELECTRICAL PUMP						Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-24-12PROC. REF: AMM 28-24-12									
281501-0108		RIGHT VENTRAL TANK ELECTRICAL PUMP						Component	ATA:28
PN:1C7-25	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-24-12PROC. REF: AMM 28-24-12									
281501-0201		FWR TK PRESSURE SWITCH						Component	ATA:28
PN:F7-337-2	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-23-05PROC. REF: AMM 28-23-05									
281501-0202		FWR TK PRESSURE SWITCH						Component	ATA:28
PN:F7-337-2	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-23-05PROC. REF: AMM 28-23-05									
281501-0203		FWR TK PRESSURE SWITCH						Component	ATA:28
PN:F7-337-2	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-23-05PROC. REF: AMM 28-23-05									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
281501-0204	FWR TK PRESSURE SWITCH							Component	ATA:28
PN:F7-337-2	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-23-05PROC. REF: AMM 28-23-05									
281501-0205	REAR TK PRESSURE SWITCH							Component	ATA:28
PN:F7-337-2	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-23-05PROC. REF: AMM 28-23-05									
281501-0206	REAR TK PRESSURE SWITCH							Component	ATA:28
PN:F7-337-2	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-23-05PROC. REF: AMM 28-23-05									
281501-0301	FWR TK INTERNAL, SOLENOID ASSY-REFUELLING VALVE							Component	ATA:28
PN:2990059-102	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-24-10PROC. REF: AMM 28-24-10									
281501-0302	FWR TK INTERNAL, SOLENOID ASSY-REFUELLING VALVE							Component	ATA:28
PN:2990059-102	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-24-10PROC. REF: AMM 28-24-10									
281501-0303	FWR TK INTERNAL, SOLENOID ASSY-REFUELLING VALVE							Component	ATA:28
PN:2990059-102	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-24-10PROC. REF: AMM 28-24-10									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
281501-0304		FWR TK INTERNAL, SOLENOID ASSY-REFUELLING VALVE						Component	ATA:28
PN:2990059-102	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-24-10PROC. REF: AMM 28-24-10									
281501-0305		REAR TK INTERNAL, SOLENOID ASSY-REFUELLING VALVE						Component	ATA:28
PN:2990059-102	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-24-10PROC. REF: AMM 28-24-10									
281501-0306		REAR TK INTERNAL, SOLENOID ASSY-REFUELLING VALVE						Component	ATA:28
PN:2990059-102	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-24-10PROC. REF: AMM 28-24-10									
281501-0307		REAR TK INTERNAL, SOLENOID ASSY-REFUELLING VALVE						Component	ATA:28
PN:2990059-102	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-24-10PROC. REF: AMM 28-24-10									
281501-0308		REAR TK INTERNAL, SOLENOID ASSY-REFUELLING VALVE						Component	ATA:28
PN:2990059-102	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-24-10PROC. REF: AMM 28-24-10									
281501-0401		FWR TK FUEL SYS - SHUTOFF VALVE						Component	ATA:28
PN:2000038-102	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-23-02PROC. REF: AMM 28-23-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
281501-0402		FWR TK FUEL SYS - SHUTOFF VALVE						Component	ATA:28
PN:2000038-102	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-23-02PROC. REF: AMM 28-23-02									
281501-0403		REAR TK FUEL SYS - SHUTOFF VALVE						Component	ATA:28
PN:2000038-102	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-23-02PROC. REF: AMM 28-23-02									
281501-0404		REAR TK FUEL SYS - SHUTOFF VALVE						Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-23-02PROC. REF: AMM 28-23-02									
281501-0501		FWR TK RELIEF-INTERNAL TANK,FUEL SYSTEM VALVE						Component	ATA:28
PN:2000062-101	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
281501-0502		FWR TK RELIEF-INTERNAL TANK,FUEL SYSTEM VALVE						Component	ATA:28
PN:2000062-101	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
281501-0503		LEFT RELIEF-INTERNAL TANK,FUEL SYSTEM VALVE						Component	ATA:28
PN:2000062-101	MOS/MSC	06-Jul-15	O/C						
SN:0581	HRS	7460.3							
	AFL	3992							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
281501-0504		RIGHT RELIEF-INTERNAL TANK,FUEL SYSTEM VALVE						Component	ATA:28
PN:2000062-101	MOS/MSC	06-Jul-15	O/C						
SN:0928	HRS	7460.3							
	AFL	3992							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
281501-0505		MID RELIEF-INTERNAL TANK,FUEL SYSTEM VALVE						Component	ATA:28
PN:2000062-101	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
281501-0601		FWR TK CHECK-TYPE THERMOSTATIC EXPANSION,TANK,FUEL SYS VALVE						Component	ATA:28
PN:2020035-101	MOS/MSC	29-Jun-23	O/C						
SN:0296	HRS	10161.5							
	AFL	5401							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
281501-0602		FWR TK CHECK-TYPE THERMOSTATIC EXPANSION,TANK,FUEL SYS VALVE						Component	ATA:28
PN:2020035-101	MOS/MSC	29-Jun-23	O/C						
SN:0318	HRS	10161.5							
	AFL	5401							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
281501-0603		FWR TK CHECK-TYPE THERMOSTATIC EXPANSION,TANK,FUEL SYS VALVE						Component	ATA:28
PN:2020035-101	MOS/MSC	29-Jun-23	O/C	TSN 0					
SN:1668	HRS	10161.5		TSN 0					
	AFL	5401		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
281501-0604		FWR TK CHECK-TYPE THERMOSTATIC EXPANSION,TANK,FUEL SYS VALVE						Component	ATA:28
PN:2020035-101	MOS/MSC	29-Jun-23	O/C						
SN:0675	HRS	10161.5							
	AFL	5401							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
281501-0701	F UND TK EQUIPPED FORWARD UNDERBELLY TANK TANK							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
281701-0101	VENT TK EQUIPPED VENTRAL TANK TANK							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM NO REFPROC. REF: AMM NO REF									
281701-0102	VENT TK EQUIPPED VENTRAL TANK TANK							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM NO REFPROC. REF: AMM NO REF									
281801-0101	FORWARD LEFT VENTRAL TANK FLOAT VENT VALVE							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM NO REFPROC. REF: AMM NO REF									
281801-0102	FORWARD RIGHT VENTRAL TANK FLOAT VENT VALVE							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM NO REFPROC. REF: AMM NO REF									
281801-0103	AFT LEFT VENTRAL TANK FLOAT VENT VALVE							Component	ATA:28
PN:2930015-102	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM NO REFPROC. REF: AMM NO REF									

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
281801-0104	AFT RIGHT VENTRAL TANK FLOAT VENT VALVE							Component	ATA:28
PN:2930015-102	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM NO REFPROC. REF: AMM NO REF									
281805-0101	LEFT FLAME ARRESTOR							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-12-05PROC. REF: AMM 28-12-05									
281805-0102	RIGHT FLAME ARRESTOR							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-12-05PROC. REF: AMM 28-12-05									
282004-0101	MODULE ASSY MODULE							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
282100-0101	REAR TK BALL-FUEL SYS VALVE							Component	ATA:28
PN:869A-12TT	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:07-0320603	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
282100-0102	REAR TK BALL-FUEL SYS VALVE							Component	ATA:28
PN:869A-12TT	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:07-0320592	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
282100-0201	LH WING EJECTOR-FUEL SYSTEM,COMPLETION PUMP							Component	ATA:28
PN:2010031-101	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:0375	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-21-02PROC. REF: AMM 28-21-02									
282100-0202	RH WING EJECTOR-FUEL SYSTEM,COMPLETION PUMP							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-21-02PROC. REF: AMM 28-21-02									
282100-0301	LH WING ELECTRICAL-FUEL SYSTEM,TANK,REAR FUSELAGE PUMP							Component	ATA:28
PN:2C7-4	MOS/MSC	19-Oct-11	O/C	TSN 0					
SN:6BF26	HRS	4959.3		TSN 0					
	AFL	2629		TSN 0					
PROC. REF: AMM 28-21-01PROC. REF: AMM 28-21-01									
282100-0302	LH WING ELECTRICAL-FUEL SYSTEM,TANK,REAR FUSELAGE PUMP							Component	ATA:28
PN:2C7-4	MOS/MSC	25-Oct-23	O/C	TSO 0					
SN:4AP102	HRS	10280.2		TSO 0					
	AFL	5473		TSO 0					
PROC. REF: AMM 28-21-01PROC. REF: AMM 28-21-01									
282100-0303	LH WING ELECTRICAL-FUEL SYSTEM,TANK,REAR FUSELAGE PUMP							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-21-01PROC. REF: AMM 28-21-01									
282100-0304	RH WING ELECTRICAL-FUEL SYSTEM,TANK,REAR FUSELAGE PUMP							Component	ATA:28
PN:2C7-4	MOS/MSC	29-Jul-21	O/C	TSR 9					
SN:10AY472	HRS	9631.4		TSN 5922, TSR 0					
	AFL	5130		TSN 2307, TSR 0					
PROC. REF: AMM 28-21-01PROC. REF: AMM 28-21-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
282100-0305		RH WING ELECTRICAL-FUEL SYSTEM,TANK,REAR FUSELAGE PUMP						Component	ATA:28
PN:2C7-4	MOS/MSC	19-Jan-26	O/C	TSO 0					
SN:7BA213	HRS	11060.9		TSO 0					
	AFL	5907		TSO 0					
PROC. REF: AMM 28-21-01PROC. REF: AMM 28-21-01									
282100-0306		RH WING ELECTRICAL-FUEL SYSTEM,TANK,REAR FUSELAGE PUMP						Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-21-01PROC. REF: AMM 28-21-01									
282100-0401		W STUB FUEL SYSTEM CHECK VALVE						Component	ATA:28
PN:2930006-101	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:2110	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
282100-0402		W STUB FUEL SYSTEM CHECK VALVE						Component	ATA:28
PN:2930006-101	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:2177	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
282100-0501		LH STUB POPPET-RELIEF, FUEL SYS, WING STUB JUNCTION VALVE						Component	ATA:28
PN:2930005-102	MOS/MSC	29-Jun-23	O/C						
SN:3665	HRS	10161.5							
	AFL	5401							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
282100-0502		RH STUB POPPET-RELIEF, FUEL SYS, WING STUB JUNCTION VALVE						Component	ATA:28
PN:2930005-102	MOS/MSC	29-Jun-23	O/C						
SN:3673	HRS	10161.5							
	AFL	5401							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
282100-0503	REAR TK POPPET-RELIEF, FUEL SYS, WING STUB JUNCTION VALVE							Component	ATA:28
PN:2930005-102	MOS/MSC	29-Jun-23	O/C						
SN:2306	HRS	10161.5							
	AFL	5401							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
282100-0504	REAR TK POPPET-RELIEF, FUEL SYS, WING STUB JUNCTION VALVE							Component	ATA:28
PN:2930005-102	MOS/MSC	29-Jun-23	O/C						
SN:3666	HRS	10161.5							
	AFL	5401							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
282100-0601	REAR TK PRESSURE,28VDC/25AMPS,ENGINE FUEL SYS SWITCH							Component	ATA:28
PN:21117-1	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
282100-0602	REAR TK PRESSURE,28VDC/25AMPS,ENGINE FUEL SYS SWITCH							Component	ATA:28
PN:21117-1	MOS/MSC	27-Mar-18	O/C	TSN 9					
SN:5821	HRS	8539		TSN 0					
	AFL	4583		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
282100-0703	APU PRESSURE-FUEL SYS,STEEL SWITCH							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-45-02PROC. REF: AMM 28-45-02									
282100-0801	LH WING BALL-FUEL SYS VALVE							Component	ATA:28
PN:869A-12TT	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:07-0320596	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
282100-0802		RH WING BALL-FUEL SYS VALVE						Component	ATA:28
PN:869A-12TT	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:04-0911258	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
282100-0901		LH ENG PRESSURE-FUEL SYS,STEEL SWITCH						Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-45-01PROC. REF: AMM 28-45-01									
282100-0902		RH ENG PRESSURE-FUEL SYS,STEEL SWITCH						Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-45-01PROC. REF: AMM 28-45-01									
282102-0101		OVERH P MODULE -FUEL CONTROL PANEL ASSEMBLY						Component	ATA:28
PN:135-05400-403	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:124562	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-20-04PROC. REF: AMM 28-20-04									
282103-0101		AUXILIARY FUEL SYS RELAY BOX						Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-20-02PROC. REF: AMM 28-20-02									
282103-0201		MODULE 6, W7000 FUEL CTL IV MODULE						Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
282201-0101	APU FUEL SYS - SHUTOFF VALVE							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-23-02	PROC. REF: AMM 28-23-02								
282300-0101	PRESS FUELLING,PRESSURE,AL ADAPTER							Component	ATA:28
PN:2820052-102	MOS/MSC	10-Aug-16	O/C	TSR 16					
SN:1643	HRS	7841.1		TSR 0					
	AFL	4202		TSR 0					
PROC. REF: AMM 28-23-01	PROC. REF: AMM 28-23-01								
282300-0201	LH WING FUEL TANK SHUTOFF VALVE							Component	ATA:28
PN:2810049-101	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:3001	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-23-02	PROC. REF: AMM 28-23-02								
282300-0202	RH WING FUEL TANK SHUTOFF VALVE							Component	ATA:28
PN:2810049-101	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:3000	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-23-02	PROC. REF: AMM 28-23-02								
282300-0301	REAR TK PRESSURE SWITCH							Component	ATA:28
PN:F7-330-2	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-23-05	PROC. REF: AMM 28-23-05								
282300-0302	REAR TK PRESSURE SWITCH							Component	ATA:28
PN:F7-330-2	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-23-05	PROC. REF: AMM 28-23-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
282300-0305		FWR TK PRESSURE SWITCH						Component	ATA:28
PN:F7-330-2	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-23-05PROC. REF: AMM 28-23-05									
282300-0306		FWR TK PRESSURE SWITCH						Component	ATA:28
PN:F7-330-2	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-23-05PROC. REF: AMM 28-23-05									
282300-0307		LH PRESSURE SWITCH						Component	ATA:28
PN:211C119-168	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-23-05PROC. REF: AMM 28-23-05									
282300-0308		RH PRESSURE SWITCH						Component	ATA:28
PN:211C119-168	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-23-05PROC. REF: AMM 28-23-05									
282300-0501		LH WING FUEL TANK RELIEF VALVE						Component	ATA:28
PN:2810050-102	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:3043	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-21-03PROC. REF: AMM 28-21-03									
282300-0502		RH WING FUEL TANK RELIEF VALVE						Component	ATA:28
PN:2810050-102	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:3040	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-21-03PROC. REF: AMM 28-21-03									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
282300-0601		FUEL REPEATER INDICATOR						Component	ATA:28
PN:366-927-001	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-23-08	PROC. REF: AMM 28-23-08								
282300-0701		LH WING PRESSURE SWITCH						Component	ATA:28
PN:F7-330-2	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-23-05	PROC. REF: AMM 28-23-05								
282300-0702		RH WING PRESSURE SWITCH						Component	ATA:28
PN:F7-330-2	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-23-05	PROC. REF: AMM 28-23-05								
282300-0801		LH WING VALVE VENT -RELIEF,FUEL TANK ASSEMBLY						Component	ATA:28
PN:2810051-104	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:4252AA	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-23-04	PROC. REF: AMM 28-23-04								
282300-0802		RH WING VALVE VENT -RELIEF,FUEL TANK ASSEMBLY						Component	ATA:28
PN:2810051-104	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:4161AA	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-23-04	PROC. REF: AMM 28-23-04								
282300-0901		FORWARD RH WING/FUSLG FAIRING - REFUEL/DEFUEL CTRL PANEL ASSEMBLY						Component	ATA:28
PN:135-04756-403	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:143475	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-23-09	PROC. REF: AMM 28-23-09								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
282301-0101		REAR TK VALVE -RELIEF, FUELTANK, WING ASSEMBLY						Component	ATA:28
PN:2990074-102	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-21-03PROC. REF: AMM 28-21-03									
282301-0102		REAR TK VALVE -RELIEF, FUELTANK, WING ASSEMBLY						Component	ATA:28
PN:2990074-102	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-21-03PROC. REF: AMM 28-21-03									
282301-0103		FWR TK VALVE -RELIEF, FUELTANK, WING ASSEMBLY						Component	ATA:28
PN:2990074-102	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-21-03PROC. REF: AMM 28-21-03									
282301-0104		FWR TK VALVE -RELIEF, FUELTANK, WING ASSEMBLY						Component	ATA:28
PN:2990074-102	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-21-03PROC. REF: AMM 28-21-03									
282302-0101		REAR TK REFUEL SHUTOFF VALVE						Component	ATA:28
PN:2990078-102	MOS/MSC	28-Aug-16	O/C						
SN:1208	HRS	7864.3							
	AFL	4220							
PROC. REF: AMM 28-24-11PROC. REF: AMM 28-24-11									
282302-0102		REAR TK REFUEL SHUTOFF VALVE						Component	ATA:28
PN:2990078-102	MOS/MSC	06-Oct-16	O/C						
SN:0334	HRS	7915.2							
	AFL	4246							
PROC. REF: AMM 28-24-11PROC. REF: AMM 28-24-11									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
282302-0103		FWR TK REFUEL SHUTOFF VALVE						Component	ATA:28
PN:2990078-102	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-24-11PROC. REF: AMM 28-24-11									
282302-0104		FWR TK REFUEL SHUTOFF VALVE						Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-24-11PROC. REF: AMM 28-24-11									
282302-0105		LEFT UNDERBELLY TANK SHUTOFF ASSY-FUEL SYS VALVE						Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
282302-0106		RIGHT UNDERBELLY TANK SHUTOFF ASSY-FUEL SYS VALVE						Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
282302-0107		STUB - FUEL SYSTEM - SHUTOFF VALVE ASSEMBLY						Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-23-02PROC. REF: AMM 28-23-02									
282302-0108		STUB - FUEL SYSTEM - SHUTOFF VALVE ASSEMBLY						Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-23-02PROC. REF: AMM 28-23-02									

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
282302-0109	STUB - FUEL SYSTEM - SHUTOFF VALVE ASSEMBLY							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-23-02PROC. REF: AMM 28-23-02									
282304-0101	REAR TK LEVEL, FLOAT TYPE, FUEL SYS,WING SENSOR							Component	ATA:28
PN:005-023-001	MOS/MSC		O/C						
SN:UNKNOWN	HRS								
	AFL	0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
282304-0102	REAR TK LEVEL, FLOAT TYPE, FUEL SYS,WING SENSOR							Component	ATA:28
PN:005-023-001	MOS/MSC		O/C						
SN:UNKNOWN	HRS								
	AFL	0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
282304-0103	FWRTK LEVEL, FLOAT TYPE, FUEL SYS,WING SENSOR							Component	ATA:28
PN:005-023-001	MOS/MSC		O/C						
SN:UNKNOWN	HRS								
	AFL	0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
282304-0104	FWRTK LEVEL, FLOAT TYPE, FUEL SYS,WING SENSOR							Component	ATA:28
PN:005-023-001	MOS/MSC	02-Feb-12	O/C	TSN 0					
SN:1844	HRS	5374		TSN 0					
	AFL	2843		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
282304-0105	LH WING FLOAT TYPE, FUEL SYS LEVEL SENSOR							Component	ATA:28
PN:005-023-001	MOS/MSC		O/C						
SN:UNKNOWN	HRS								
	AFL	0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
282304-0106	RH WING FLOAT TYPE, FUEL SYS LEVEL SENSOR							Component	ATA:28
PN:005-023-001	MOS/MSC		O/C						
SN:UNKNOWN	HRS								
	AFL	0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
282307-0101	DEFUELING SHUTOFF ASSY-FUEL SYS VALVE							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-23-07PROC. REF: AMM 28-23-07									
282309-0101	MODULE ASSY MODULE							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
282311-0101	VENTRAL TANK REFUELING SHUTOFF ASSY-FUEL SYS VALVE							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM NO REFPROC. REF: AMM NO REF									
282313-0101	VENTRAL TANK FUEL SYS - SHUTOFF VALVE							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM NO REFPROC. REF: AMM NO REF									
282318-0101	LH WING HIGH LEVEL FUEL SENSOR							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
282318-0102	RH WING HIGH LEVEL FUEL SENSOR							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
282320-0101	VENTRAL HIGH LEVEL FUEL SENSOR							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM NO REFPROC. REF: AMM NO REF									
282411-0101	LH FWD REFUELING SHUTOFF ASSY-FUEL SYS VALVE							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-24-11PROC. REF: AMM 28-24-11									
282411-0102	RH FWD REFUELING SHUTOFF ASSY-FUEL SYS VALVE							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-24-11PROC. REF: AMM 28-24-11									
282411-0103	LH AFT REFUELING SHUTOFF ASSY-FUEL SYS VALVE							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-24-11PROC. REF: AMM 28-24-11									
282411-0104	RH AFT REFUELING SHUTOFF ASSY-FUEL SYS VALVE							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-24-11PROC. REF: AMM 28-24-11									

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
282412-0101	LEFT FORWARD TANK FUEL SYS - SHUTOFF VALVE							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-24-11PROC. REF: AMM 28-24-11									
282412-0102	RIGHT FORWARD TANK FUEL SYS - SHUTOFF VALVE							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-24-11PROC. REF: AMM 28-24-11									
282412-0103	AFT TANK FUEL SYS - SHUTOFF VALVE							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-24-11PROC. REF: AMM 28-24-11									
282412-0104	FORWARD TANK FUEL SYS SHUTOFF VALVE							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-23-02PROC. REF: AMM 28-23-02									
282414-0101	LEFT FORWARD TANK HIGH LEVEL FUEL SENSOR							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
282414-0102	RIGHT FORWARD TANK HIGH LEVEL FUEL SENSOR							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
282600-0101		REAR FUEL SYS, INTERNAL TANK PRESSURE SWITCH						Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
282600-0102		REAR FUEL SYS, INTERNAL TANK PRESSURE SWITCH						Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
282604-0101		LEFT FORWARD TANK TRANSFER SHUTOFF ASSY-FUEL SYS VALVE						Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-26-04PROC. REF: AMM 28-26-04									
282604-0102		RIGHT FORWARD TANK TRANSFER SHUTOFF ASSY-FUEL SYS VALVE						Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-26-04PROC. REF: AMM 28-26-04									
282610-0101		LEFT AFT TANK TRANSFER SHUTOFF ASSY-FUEL SYS VALVE						Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-26-10PROC. REF: AMM 28-26-10									
282610-0102		RIGHT AFT TANK TRANSFER SHUTOFF ASSY-FUEL SYS VALVE						Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-26-10PROC. REF: AMM 28-26-10									

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
282615-0101	CROSS TRANSFER FUEL SYS - SHUTOFF VALVE							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-26-15	PROC. REF: AMM 28-26-15								
282618-0101	LEFT AFT TANK FUEL ISOLATION ELECTRICAL FUEL SYS - SHUTOFF VALVE							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-26-18	PROC. REF: AMM 28-26-18								
282618-0102	RIGHT AFT TANK FUEL ISOLATION ELECTRICAL FUEL SYS - SHUTOFF VALVE							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-26-18	PROC. REF: AMM 28-26-18								
282621-0101	LEFT FORWARD TANK LOW LEVEL FUEL SENSOR							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-26-21	PROC. REF: AMM 28-26-21								
282621-0102	RIGHT FORWARD TANK LOW LEVEL FUEL SENSOR							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-26-21	PROC. REF: AMM 28-26-21								
282622-0101	LEFT UPPER AFT TANK LOW LEVEL FUEL SENSOR							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-26-22	PROC. REF: AMM 28-26-22								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
282622-0102	LEFT LOWER AFT TANK LOW LEVEL FUEL SENSOR							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-26-22PROC. REF: AMM 28-26-22									
282622-0103	RIGHT UPPER AFT TANK LOW LEVEL FUEL SENSOR							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-26-22PROC. REF: AMM 28-26-22									
282622-0104	RIGHT LOWER AFT TANK LOW LEVEL FUEL SENSOR							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-26-22PROC. REF: AMM 28-26-22									
282702-0101	VENTRAL TANK - TRANSFER PUMP CHECK VALVE							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM NO REFPROC. REF: AMM NO REF									
282702-0102	VENTRAL TANK - TRANSFER PUMP CHECK VALVE							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM NO REFPROC. REF: AMM NO REF									
282704-0101	VENTRAL TANK TRANSFER SHUTOFF ASSY-FUEL SYS VALVE							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM NO REFPROC. REF: AMM NO REF									

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
284100-0201	LH WING FUEL TANK UNIT							Component	ATA:28
PN:028-936-002	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:2382B	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-41-02PROC. REF: AMM 28-41-02									
284100-0202	RH WING FUEL TANK UNIT							Component	ATA:28
PN:028-936-002	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:2381B	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-41-02PROC. REF: AMM 28-41-02									
284100-0203	LH WING FUEL TANK UNIT							Component	ATA:28
PN:028-936-005	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:2318B	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-41-02PROC. REF: AMM 28-41-02									
284100-0204	RH WING FUEL TANK UNIT							Component	ATA:28
PN:028-936-005	MOS/MSC	13-Dec-19	O/C	TSR 8					
SN:1494B	HRS	9243.4		TSR 0					
	AFL	4944		TSR 0					
PROC. REF: AMM 28-41-02PROC. REF: AMM 28-41-02									
284100-0205	LH WING STUB TANK #1B UNIT							Component	ATA:28
PN:028-936-008	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:1797B	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-41-02PROC. REF: AMM 28-41-02									
284100-0206	RH WING STUB TANK #1B UNIT							Component	ATA:28
PN:028-936-008	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:1796B	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-41-02PROC. REF: AMM 28-41-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
284100-0301	LH WING FUEL QUANTITY TRANSMITTER							Component	ATA:28
PN:028-936-004	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:2320B	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
284100-0302	RH WING FUEL QUANTITY TRANSMITTER							Component	ATA:28
PN:028-936-004	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:2318B	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
284100-0303	LH WING TANK FUEL QUANTITY TRANSMITTER							Component	ATA:28
PN:028-936-006	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:2418B	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
284100-0304	RH WING TANK FUEL QUANTITY TRANSMITTER							Component	ATA:28
PN:028-936-006	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:2415B	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
284100-0305	RH WING FUEL QUANTITY TRANSMITTER							Component	ATA:28
PN:028-936-003	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:2347B	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
284100-0401	LH WING FUEL TANK,WING STUB PROBE							Component	ATA:28
PN:028-936-007	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:1691B	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
284100-0402		RH WING FUEL TANK,WING STUB PROBE						Component	ATA:28
PN:028-936-007	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:1697B	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
284100-0501		LH WING LOW LEVEL FUEL TANK SENSOR						Component	ATA:28
PN:057-905-001	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:2510B	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-44-01PROC. REF: AMM 28-44-01									
284100-0502		RH WING LOW LEVEL, FUEL TANK SENSOR						Component	ATA:28
PN:057-905-001	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:2512B	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-44-01PROC. REF: AMM 28-44-01									
284100-0601		CREW CAB SIGNAL CONDITIONING-LEVEL, FUEL SYS UNIT						Component	ATA:28
PN:367-934-002	MOS/MSC	21-Jan-22	O/C	TSR 4					
SN:606	HRS	9789.3		TSN 14438.1, TSR 0					
	AFL	5205		TSR 0					
PROC. REF: AMM 28-41-01PROC. REF: AMM 28-41-01									
284100-0602		CSL CENT SIGNAL CONDITIONING-LEVEL, FUEL SYS UNIT						Component	ATA:28
PN:367-934-006	MOS/MSC	07-Feb-12	O/C						
SN:1362	HRS	5380.8							
	AFL	2849							
PROC. REF: AMM 28-41-01PROC. REF: AMM 28-41-01									
284100-0603		CSL CENT SIGNAL CONDITIONING-LEVEL, FUEL SYS UNIT						Component	ATA:28
PN:367-934-006	MOS/MSC	06-Jul-15	O/C	TSR 9					
SN:1321	HRS	7460.3		TSN 1334, TSR 0					
	AFL	3992		TSN 500, TSR 0					
PROC. REF: AMM 28-41-01PROC. REF: AMM 28-41-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
284101-0101	FWR TK FUEL INDICATOR PROBE							Component	ATA:28
PN:028-065-002	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
284101-0102	FWR TK FUEL INDICATOR PROBE							Component	ATA:28
PN:028-065-002	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
284101-0103	FWR TK FUEL INDICATOR PROBE							Component	ATA:28
PN:028-065-002	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
284101-0104	FWR TK FUEL INDICATOR PROBE							Component	ATA:28
PN:028-065-002	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
284101-0105	FWR TK FUEL INDICATOR PROBE							Component	ATA:28
PN:028-065-001	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
284101-0106	FWR TK FUEL INDICATOR PROBE							Component	ATA:28
PN:028-065-001	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
284101-0107		FWR TK FUEL INDICATOR PROBE						Component	ATA:28
PN:028-065-001	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
284101-0108		FWR TK FUEL INDICATOR PROBE						Component	ATA:28
PN:028-065-001	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
284101-0201		FWR TK HARNESS FORWARD AUXILIARY TANK ASSEMBLY						Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-46-04PROC. REF: AMM 28-46-04									
284101-0202		FWR TK HARNESS FORWARD AUXILIARY TANK ASSEMBLY						Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-46-04PROC. REF: AMM 28-46-04									
284102-0301		FORWARD CONTROL-LEVEL SWITCH, FUEL SYS UNIT						Component	ATA:28
PN:367-340-001	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
284102-0302		FORWARD CONTROL-LEVEL SWITCH, FUEL SYS UNIT						Component	ATA:28
PN:367-340-001	MOS/MSC	21-Aug-09	O/C	TSR 0					
SN:1401	HRS	2411.7		TSR 0					
	AFL	1277		TSR 0					
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
284102-0401	LH WING WING TANK FUEL QUANTITY SENSOR							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
284102-0402	RH WING WING TANK FUEL QUANTITY SENSOR							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
284102-0403	LH WING WING TANK FUEL QUANTITY SENSOR							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
284102-0404	RH WING WING TANK FUEL QUANTITY SENSOR							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
284102-0405	LH WING WING TANK FUEL QUANTITY SENSOR							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
284102-0406	RH WING WING TANK FUEL QUANTITY SENSOR							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
284102-0407	LH WING WING TANK FUEL QUANTITY SENSOR							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
284102-0408	RH WING WING TANK FUEL QUANTITY SENSOR							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
284102-0409	LH WING WING TANK FUEL QUANTITY SENSOR							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
284102-0410	RH WING WING TANK FUEL QUANTITY SENSOR							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
284102-0411	LH WING WING TANK FUEL QUANTITY SENSOR							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
284102-0412	RH WING WING TANK FUEL QUANTITY SENSOR							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
284103-0101	TANK UNIT HARNESS ASSEMBLY							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-41-03PROC. REF: AMM 28-41-03									
284103-0102	RH WING TANK UNIT HARNESS ASSEMBLY							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-41-03PROC. REF: AMM 28-41-03									
284105-0101	LEFT VENTRAL TANL UNIT SENSOR							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									
284105-0102	RIGHT VENTRAL TANL UNIT SENSOR							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									
284105-0103	VENTRAL TANL UNIT SENSOR							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									
284105-0104	VENTRAL TANL UNIT SENSOR							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
284105-0105	VENTRAL TANL UNIT SENSOR							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
284105-0106	VENTRAL TANL UNIT FUEL QUANTITY SENSOR							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
284212-0105	F UND T - FUEL SYSTEM - SHUTOFF VALVE ASSEMBLY							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-24-11	PROC. REF: AMM 28-24-11								
284212-0106	F UND T - FUEL SYSTEM - SHUTOFF VALVE ASSEMBLY							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-24-11	PROC. REF: AMM 28-24-11								
284401-0101	FWR TK LEVEL, FLOAT TYPE, FUEL SYS, WING SENSOR							Component	ATA:28
PN:005-022-001	MOS/MSC		O/C						
SN:UNKNOWN	HRS								
	AFL	0							
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
284401-0102	FWR TK LEVEL, FLOAT TYPE, FUEL SYS, WING SENSOR							Component	ATA:28
PN:005-022-001	MOS/MSC		O/C						
SN:UNKNOWN	HRS								
	AFL	0							
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
284600-0101	LEFT LOWER AUX TANK PRIMARY (TANK UNIT) PROBE							Component	ATA:28
PN:028-065-003	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
284600-0102	LEFT LOWER AUX TANK MONITOR (TANK UNIT) PROBE							Component	ATA:28
PN:028-065-003	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
284600-0103	RIGHT LOWER AUX TANK PRIMARY (TANK UNIT) PROBE							Component	ATA:28
PN:028-065-003	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
284600-0104	RIGHT LOWER AUX TANK MONITOR (TANK UNIT) PROBE							Component	ATA:28
PN:028-065-003	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
284600-0201	LEFT UPPER AUX TANK PRIMARY (TANK UNIT) PROBE							Component	ATA:28
PN:028-065-004	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
284600-0202	LEFT UPPER AUX TANK MONITOR (TANK UNIT) PROBE							Component	ATA:28
PN:028-065-004	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
284600-0203	RIGHT UPPER AUX TANK PRIMARY (TANK UNIT) PROBE							Component	ATA:28
PN:028-065-004	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
284600-0204	RIGHT UPPER AUX TANK MONITOR (TANK UNIT) PROBE							Component	ATA:28
PN:028-065-004	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
284601-0101	LEFT INBOARD AFT TANK UNIT FUEL QUANTITY SENSOR							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
284601-0102	LEFT OUTBOARD AFT TANK UNIT FUEL QUANTITY SENSOR							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
284601-0103	RIGHT INBOARD AFT TANK UNIT FUEL QUANTITY SENSOR							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
284601-0104	RIGHT OUTBOARD AFT TANK UNIT FUEL QUANTITY SENSOR							Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
284603-0101		LEFT FORWARD FUEL QUANTITY - FORWARD TANK SENSOR						Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
284603-0102		LEFT AFT FUEL QUANTITY - FORWARD TANK SENSOR						Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
284603-0103		RIGHT FORWARD FUEL QUANTITY - FORWARD TANK SENSOR						Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
284603-0104		RIGHT AFT FUEL QUANTITY - FORWARD TANK SENSOR						Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
284700-0101		REAR TK LEVEL, FLOAT TYPE, FUEL SYS, WING SENSOR						Component	ATA:28
PN:005-022-002	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
284701-0101		REAR TK LEVEL, FLOAT TYPE, FUEL SYS, WING SENSOR						Component	ATA:28
PN:005-022-002	MOS/MSC		O/C						
SN:UNKNOWN	HRS								
	AFL	0							
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 29 - HYDRAULIC POWER									
29-10-00-280-001-A00 S	INSPECT (SPECIAL INSPECTION) HYDRAULIC FLUID - ANALYSIS							Service	ATA:29
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 29-10-00PROC. REF: AMM 29-10-00									
29-10-00-710-001-A00 S	OPERATIONALLY CHECK ELECTRIC MOTOR-DRIVEN PUMP INPUT SIGNALS							Service	ATA:29
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 29-10-00PROC. REF: AMM 29-10-00									
29-10-00-790-001-A00 S	FUNCTIONALLY CHECK INTERNAL LEAKAGE OF HYDRAULIC POWER SYSTEM							Service	ATA:29
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: AMM 29-10-00PROC. REF: AMM 29-10-00									
29-10-01-710-001-A00 S	OPERATIONALLY CHECK SHUTOFF VALVE BY MEANS OF THE HYDRAULIC PANEL SWITCH							Service	ATA:29
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 29-10-01PROC. REF: AMM 29-10-01									
29-10-04-900-001-A00	DISCARD LH RACK DC ELECTRIC MOTOR DRIVEN HYDRAULIC PUMP EMDP BRUSHES							Service	ATA:29
PN:971533	MOS	05-Jul-12						SYSTEM	
SN:MX757308	HRS	5975.6	6000		11975.6		699.3		
	AFL	3181							
PROC. REF: AMM 29-10-04PROC. REF: AMM 29-10-04									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 29 - HYDRAULIC POWER									
29-10-04-900-001-A00		DISCARD RH RACK DC ELECTRIC MOTOR DRIVEN HYDRAULIC PUMP EMPD BRUSHES							Service ATA:29
PN:971533	MOS	05-Jul-12						SYSTEM	
SN:MX673042	HRS	5975.6	6000		11975.6		699.3		
	AFL	3181							
PROC. REF: AMM 29-10-04	PROC. REF: AMM 29-10-04								
29-10-08-211-001-A00 S		VISUALLY CHECK DIFFERENTIAL PRESSURE INDICATOR FOR RED PINS POPPED OUT.							Service ATA:29
	MOS	17-Oct-25	12 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	500 (+20/-20)						
	AFL	5820							
									PKG:5002
PROC. REF: AMM 29-10-08	PROC. REF: AMM 29-10-08								
29-10-10-720-001-A00 S		FUNCTIONALLY CHECK RETURN FILTER BY-PASS VALVE							Service ATA:29
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 29-10-10	PROC. REF: AMM 29-10-10								
29-10-13-720-001-A00 S		FUNCTIONALLY CHECK PRIORITY VALVE							Service ATA:29
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 29-10-13	PROC. REF: AMM 29-10-13								
29-30-03-720-001-A00 S		FUNCTIONALLY CHECK HYDRAULIC FILTERS DIFFERENTIAL PRESSURE INDICATORS							Service ATA:29
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 29-10-10	PROC. REF: AMM 29-10-10								

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 29 - HYDRAULIC POWER									
29-30-05-710-001-A00 S	OPERATIONALLY CHECK HYD SYS OVHT MESSAGE								Service ATA:29
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: AMM 29-30-05PROC. REF: AMM 29-30-05									
291000-0101	RH RACK GENERATOR ASSY ASSEMBLY								Component ATA:29
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									
291001-0101	LH ENG SHUTOFF VALVE								Component ATA:29
PN:2940003-102	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:2130	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 29-10-01PROC. REF: AMM 29-10-01									
291001-0102	RH ENG SHUTOFF VALVE								Component ATA:29
PN:2940003-102	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:2133	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 29-10-01PROC. REF: AMM 29-10-01									
291003-0101	LH ENGINE DRIVEN HYDRAULIC PUMP								Component ATA:29
PN:971808 MOD A	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 29-10-03PROC. REF: AMM 29-10-03									
291003-0102	RH ENGINE DRIVEN HYDRAULIC PUMP								Component ATA:29
PN:971808 MOD B	MOS/MSC	15-Nov-13	O/C	TSN 0					
SN:MX773200	HRS	6756.1		TSN 0					
	AFL	3630		TSN 0					
PROC. REF: AMM 29-10-03PROC. REF: AMM 29-10-03									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 29 - HYDRAULIC POWER									
291004-0201		LH RACK DC ELECTRIC MOTOR DRIVEN HYDRAULIC PUMP						Component	ATA:29
PN:971533	MOS/MSC	05-Jul-12	O/C	TSN 0					
SN:MX757308	HRS	5975.6		TSN 0					
	AFL	3181		TSN 0					
PROC. REF: AMM 29-10-04	PROC. REF: AMM 29-10-04								
291004-0202		RH RACK DC ELECTRIC MOTOR DRIVEN HYDRAULIC PUMP						Component	ATA:29
PN:971533	MOS/MSC	05-Jul-12	O/C						
SN:MX673042	HRS	5975.6							
	AFL	3181							
PROC. REF: AMM 29-10-04	PROC. REF: AMM 29-10-04								
291005-0101		LH RACK HYDRAULIC, GENERATOR UNIT RESERVOIR						Component	ATA:29
PN:368900-1003	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:2057	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 29-10-05	PROC. REF: AMM 29-10-05								
291005-0102		RH RACK HYDRAULIC, GENERATOR UNIT RESERVOIR						Component	ATA:29
PN:368900-1003	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:2056	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 29-10-05	PROC. REF: AMM 29-10-05								
291007-0101		LH RACK FILTER -MANIFOLD, HYDRAULIC SYS ASSEMBLY						Component	ATA:29
PN:368100-1007	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:2041	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 29-10-07	PROC. REF: AMM 29-10-07								
291007-0102		RH RACK FILTER -MANIFOLD, HYDRAULIC SYS ASSEMBLY						Component	ATA:29
PN:368100-1007	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:2038	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 29-10-07	PROC. REF: AMM 29-10-07								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 29 - HYDRAULIC POWER									
291013-0101	W STUB ASSY-PRIORITY, SHUT OFF, HYDRAULIC SYS, LANDING GEAR VALVE							Component	ATA:29
PN:2226-0001-401	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:01150	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 29-10-13	PROC. REF: AMM 29-10-13								
291014-0101	LH RACK CHECK-TYPE RETAINER HYDRAULIC SYSTEM, POWER UNIT VALVE							Component	ATA:29
PN:CV26-63	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:07-0424175	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
291014-0102	RH RACK CHECK-TYPE RETAINER HYDRAULIC SYSTEM, POWER UNIT VALVE							Component	ATA:29
PN:CV26-63	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:07-0424177	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
291015-0101	LEFT CHECK-TYPE RETAINER, ELECTRICAL PUMP, POWER UNIT VALVE							Component	ATA:29
PN:2662A-4EE	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
291015-0102	LEFT CHECK-TYPE RETAINER, ELECTRICAL PUMP, POWER UNIT VALVE							Component	ATA:29
PN:2662A-4EE	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
291015-0103	RIGHT CHECK-TYPE RETAINER, ELECTRICAL PUMP, POWER UNIT VALVE							Component	ATA:29
PN:2662A-4EE	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 29 - HYDRAULIC POWER									
291015-0104	RIGHT CHECK-TYPE RETAINER, ELECTRICAL PUMP, POWER UNIT VALVE							Component	ATA:29
PN:2662A-4EE	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
291016-0101	LEFT CHECK-TYPE RETAINER, HYDRAULIC SYSTEM VALVE							Component	ATA:29
PN:2662T-6EE	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:07-021317	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
291016-0102	MID CHECK-TYPE RETAINER, HYDRAULIC SYSTEM VALVE							Component	ATA:29
PN:1C5444-1	MOS/MSC	07-Feb-08	O/C	TSN 0					
SN:0757	HRS	557.2		TSN 0					
	AFL	275		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
291016-0103	RIGHT CHECK-TYPE RETAINER, HYDRAULIC SYSTEM VALVE							Component	ATA:29
PN:2662T-6EE	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:06-1025308	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
291016-0104	LH RACK VALVE, CHECK, -6, CRES VALVE							Component	ATA:29
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
291016-0105	RH RACK CRES -6 CHECK VALVE							Component	ATA:29
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 29 - HYDRAULIC POWER									
291016-0106		FWD FUS CRES -6 CHECK VALVE						Component	ATA:29
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
291020-0101		L/H ENG. HYDRAULIC PULSATION DAMPENER						Component	ATA:29
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 29-10-20	PROC. REF: AMM 29-10-20								
291020-0102		R/H ENG. HYDRAULIC PULSATION DAMPENER						Component	ATA:29
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 29-10-20	PROC. REF: AMM 29-10-20								
291300-0101		FUS WING GENERATOR ASSY GENERATOR						Component	ATA:29
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
293000-0101		OVERH P MODULE -HYDRAULIC POWER CONTROL ASSEMBLY						Component	ATA:29
PN:145-29739-403	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:0000147594	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
293002-0201		LH RACK PRESSURE-HYDRAULIC SYS TRANSMITTER						Component	ATA:29
PN:APTE-24-1000-5000A	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:7218-6-179	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 29-30-02	PROC. REF: AMM 29-30-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 29 - HYDRAULIC POWER									
293002-0202		RH RACK PRESSURE-HYDRAULIC SYS TRANSMITTER						Component	ATA:29
PN:APTE-24-1000-5000A	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:7218-6-184	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 29-30-02	PROC. REF: AMM 29-30-02								
299001-0101		LH RACK ELECTRIC PUMP ASSEMBLY						Component	ATA:29
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
299001-0102		RH RACK ELECTRIC PUMP ASSEMBLY						Component	ATA:29
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
ATA 30 - ICE AND RAIN PROTECTION									
30-00-00-710-001-A00		OPERATIONALLY CHECK ANTI-ICING SYSTEM MESSAGES						Service	ATA:30
	MOS	18-May-26						SYSTEM	
	HRS	11259.6	100		11359.6		83.3		
	AFL	6018							
PROC. REF: AMM 30-00-00	PROC. REF: AMM 30-00-00								
30-11-00-720-001-A00 S		FUNCTIONALLY CHECK PRESSURE SENSORS OF THE WING THERMAL ANTI-ICING SYSTEM (BENCH TEST). (CMR)						Service	ATA:30
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 30-11-00	PROC. REF: AMM 30-11-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 30 - ICE AND RAIN PROTECTION									
30-11-05-710-001-A00 S	OPERATIONALLY CHECK WING LEAK THERMOSTAT							Service	ATA:30
	MOS	17-Oct-25	72 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	3000 (+20/-20)						
	AFL	5820	1500 (+20/-20)						
									PKG:5012,6020
PROC. REF: AMM 30-11-05PROC. REF: AMM 30-11-05									
30-12-00-710-001-A00 S	OPERATIONALLY CHECK ELECTRICAL HARDWARE OF THE HORIZONTAL STABILIZER THERMAL ANTI-ICING SYSTEM.							Service	ATA:30
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 30-12-00PROC. REF: AMM 30-12-00									
30-12-00-720-001-A00 S	FUNCTIONALLY CHECK PRESSURE SENSORS OF THE HORIZONTAL STABILIZER THERMAL ANTI-ICING SYSTEM (BENCH TEST) (CMR)							Service	ATA:30
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 30-12-00PROC. REF: AMM 30-12-00									
30-12-05-710-001-A00 S	OPERATIONALLY CHECK HORIZONTAL-STABILIZER LEAK THERMOSTAT							Service	ATA:30
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: AMM 30-12-05PROC. REF: AMM 30-12-05									
30-20-00-220-001-A00 S	INSPECT (DETAILED INSPECTION) THERMAL ANTI-ICE (TAI) EXHAUST DUCT FOR CONDITION AND SECURITY OF INSTALLATION.							Service	ATA:30
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 30-20-00PROC. REF: AMM 30-20-00									

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 30 - ICE AND RAIN PROTECTION									
30-20-01-720-001-A00 S	FUNCTIONALLY CHECK ENGINE THERMAL ANTI-ICE (TAI) INTERBULKHEAD ASSEMBLY FOR LEAKAGE							Service	ATA:30
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 30-20-01PROC. REF: AMM 30-20-01									
30-21-00-720-001-A00 S	FUNCTIONALLY CHECK PRESSURE SENSORS OF THE ENGINE THERMAL ANTI-ICING SYSTEM (BENCH TEST) (CMR)							Service	ATA:30
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 30-21-00PROC. REF: AMM 30-21-00									
30-31-00-710-001-A00 S	OPERATIONALLY CHECK PITOT, ANEMOMETRIC STATIC PORT HEATING							Service	ATA:30
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6016
PROC. REF: AMM 30-31-00, FAR FAR 43 APPENDIX E, FAR FAR 91.411 / 91.217PROC. REF: AMM 30-31-00, FAR FAR 43 APPENDIX E, FAR FAR 91.411 / 91.217									
30-31-00-710-002-A00 S	OPERATIONALLY CHECK PRESSURIZATION STATIC PORT HEATING							Service	ATA:30
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6016
PROC. REF: AMM 30-31-00PROC. REF: AMM 30-31-00									
30-31-08-710-001-A00 S	OPERATIONALLY CHECK PITOT LINES HEATER NOTE: IF INSTALLED							Service	ATA:30
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: AMM 30-31-03PROC. REF: AMM 30-31-03									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 30 - ICE AND RAIN PROTECTION									
30-32-00-710-001-A00 S	OPERATIONALLY CHECK AOA SENSOR HEATING							Service	ATA:30
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6016
PROC. REF: AMM 30-32-00PROC. REF: AMM 30-32-00									
30-33-00-710-001-A00 S	OPERATIONALLY CHECK TAT SENSOR HEATING							Service	ATA:30
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6016
PROC. REF: AMM 30-33-00PROC. REF: AMM 30-33-00									
30-41-00-710-001-A00	OPERATIONALLY CHECK WINDSHIELD WIPER SYSTEM							Service	ATA:30
	MOS/MSC	15-Aug-13	O/C						
	HRS	6643.4							
	AFL	3572							
PROC. REF: AMM 30-41-00PROC. REF: AMM 30-41-00									
30-42-00-710-001-A00 S	OPERATIONALLY CHECK WINDSHIELD HEATING							Service	ATA:30
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 30-42-00PROC. REF: AMM 30-42-00									
30-43-01-211-001-A00 S	VISUALLY CHECK RAIN REPELLENT COATING (RRC)							Service	ATA:30
	MOS	17-Oct-25	24 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	1000 (+20/-20)						
	AFL	5820							
									PKG:5004
PROC. REF: AMM 30-41-04PROC. REF: AMM 30-41-04									

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 30 - ICE AND RAIN PROTECTION									
300000-0101		OVERH P ELECTRICAL SYS, ICE PROTECTION MODULE						Component	ATA:30
PN:145-31656-409	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:0000146548	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
301100-0101		W STUB ELECTRONIC, ANTI ICE SYS, WING PRESSURE SWITCH						Component	ATA:30
PN:APS-8-1000	MOS/MSC	10-Nov-11	O/C	TSN 0					
SN:7902-3-54	HRS	5047.1		TSN 0					
	AFL	2682		TSN 0					
PROC. REF: AMM 30-11-03	PROC. REF: AMM 30-11-03								
301100-0301		LH WING WING ANTI ICE PICCOLO BURST MONITORING PRESSURE TRANSDUCER						Component	ATA:30
PN:APS-6-1000	MOS/MSC	13-Jan-14	O/C	TSN 0					
SN:8094-7-1100	HRS	6811.6		TSN 0					
	AFL	3661		TSN 0					
PROC. REF: AMM 30-11-12	PROC. REF: AMM 30-11-12								
301100-0302		RH WING WING ANTI ICE PICCOLO BURST MONITORING PRESSURE TRANSDUCER						Component	ATA:30
PN:APS-6-1000	MOS/MSC	10-Nov-11	O/C	TSN 0					
SN:7720-7-312	HRS	5047.1		TSN 0					
	AFL	2682		TSN 0					
PROC. REF: AMM 30-11-12	PROC. REF: AMM 30-11-12								
301200-0101		AIRFRAME ANTI ICE SYSTEM OVERPRESSURE SWITCH						Component	ATA:30
PN:12949-4	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:2216	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-11-03	PROC. REF: AMM 30-11-03								
301200-0102		LH WING AIRFRAME ANTI ICE SYSTEM OVERPRESSURE SWITCH						Component	ATA:30
PN:12949-4	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:2221	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-11-03	PROC. REF: AMM 30-11-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 30 - ICE AND RAIN PROTECTION									
301200-0103	RH WING AIRFRAME ANTI ICE SYSTEM OVERPRESSURE SWITCH							Component	ATA:30
PN:12949-4	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:2227	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-11-03	PROC. REF: AMM 30-11-03								
301200-0201	PRESSURE-ELECTRONIC, ANTI ICE SYS, WING/STABILIZER HORI SWITCH							Component	ATA:30
PN:APS-7-1000	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-12-03	PROC. REF: AMM 30-12-03								
301200-0202	LEFT PRESSURE-ELECTRONIC, ANTI ICE SYS, WING/STABILIZER HORI SWITCH							Component	ATA:30
PN:APS-7-1000	MOS/MSC	10-Nov-11	O/C	TSN 0					
SN:7816-7-295	HRS	5047.1		TSN 0					
	AFL	2682		TSN 0					
PROC. REF: AMM 30-12-03	PROC. REF: AMM 30-12-03								
301200-0203	PRESSURE-ELECTRONIC, ANTI ICE SYS, WING/STABILIZER HORI SWITCH							Component	ATA:30
PN:APS-7-1000	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-12-03	PROC. REF: AMM 30-12-03								
301200-0204	RIGHT PRESSURE-ELECTRONIC, ANTI ICE SYS, WING/STABILIZER HORI SWITCH							Component	ATA:30
PN:APS-7-1000	MOS/MSC	10-Nov-11	O/C	TSN 0					
SN:7816-7-210	HRS	5047.1		TSN 0					
	AFL	2682		TSN 0					
PROC. REF: AMM 30-12-03	PROC. REF: AMM 30-12-03								
301200-0301	REAR ANTI ICE, STABILIZER VALVE							Component	ATA:30
PN:1000649-2	MOS/MSC	11-Dec-23	O/C	TSO 0					
SN:9912325	HRS	10328.7		TSO 0					
	AFL	5502		TSO 0					
PROC. REF: AMM 30-12-01	PROC. REF: AMM 30-12-01								

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 30 - ICE AND RAIN PROTECTION									
301200-0401	TAIL HORIZONTAL STABILIZER PICCOLO BURST PRESSURE SWITCH							Component	ATA:30
PN:83536-2	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:0997	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-12-06	PROC. REF: AMM 30-12-06								
301300-0101	LH WING SHUTOFF/REGULATOR-AIR PRESSURE, ANTI ICE SYS, AIRFOILS VALVE							Component	ATA:30
PN:1000649-1	MOS/MSC	07-Apr-19	O/C	TSO 9					
SN:9910164	HRS	8973.5		TSN 4288, TSO 0					
	AFL	4805		TSO 0					
PROC. REF: AMM 30-11-01	PROC. REF: AMM 30-11-01								
301300-0102	RH WING SHUTOFF/REGULATOR-AIR PRESSURE, ANTI ICE SYS, AIRFOILS VALVE							Component	ATA:30
PN:1000649-1	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:2007040480	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-11-01	PROC. REF: AMM 30-11-01								
302000-0101	LH ENG PRESSURE-ELECTRONIC, ANTI ICE SYS TRANSDUCER							Component	ATA:30
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-21-06	PROC. REF: AMM 30-21-06								
302000-0102	RH ENG PRESSURE-ELECTRONIC, ANTI ICE SYS TRANSDUCER							Component	ATA:30
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-21-06	PROC. REF: AMM 30-21-06								
302000-0201	LH ENG ANTI ICE, AIR BLEED SYS VALVE							Component	ATA:30
PN:C146009-4	MOS/MSC	18-Jul-09	O/C	TSR 0					
SN:2740	HRS	2297.3		TSR 0					
	AFL	1211		TSR 0					
PROC. REF: AMM 30-21-01	PROC. REF: AMM 30-21-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 30 - ICE AND RAIN PROTECTION									
302000-0202		RH ENG ANTI ICE, AIR BLEED SYS VALVE						Component	ATA:30
PN:C146009-4	MOS/MSC	01-Apr-11	O/C						
SN:2666	HRS	4453.2							
	AFL	2335							
PROC. REF: AMM 30-21-01	PROC. REF: AMM 30-21-01								
304201-0101		WINDSHIELD TEMPERATURE CONTROLLER						Component	ATA:30
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-42-01	PROC. REF: AMM 30-42-01								
304201-0102		WINDSHIELD TEMPERATURE CONTROLLER						Component	ATA:30
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-42-01	PROC. REF: AMM 30-42-01								
308000-0201		LH CSL ICE-FRONT FUSELAGE DETECTOR						Component	ATA:30
PN:0871HT3-1A	MOS/MSC	04-Mar-15	O/C	TSN 28					
SN:02473	HRS	7330.8		TSN 899.7					
	AFL	3928		TSN 465					
PROC. REF: AMM 30-80-01	PROC. REF: AMM 30-80-01								
308000-0202		RH CSL ICE-FRONT FUSELAGE DETECTOR						Component	ATA:30
PN:0871HT3	MOS/MSC	16-Aug-24	O/C						
SN:00939	HRS	10541.4							
	AFL	5613							
PROC. REF: AMM 30-80-01	PROC. REF: AMM 30-80-01								
308002-0101		REAR PROCESSOR-DETECTION, CLEAR ICE, REAR FUSELAGE UNIT						Component	ATA:30
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-80-02	PROC. REF: AMM 30-80-02								

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 30 - ICE AND RAIN PROTECTION									
308003-0101		LH WING ICE DETECTION SENSOR							Component ATA:30
PN:00870-0020-0002	MOS/MSC	01-Mar-17	O/C						
SN:2502	HRS	8086							
	AFL	4338							
PROC. REF: AMM 30-80-03	PROC. REF: AMM 30-80-03								
308003-0102		RH WING ICE DETECTION SENSOR							Component ATA:30
PN:00870-0020-0002	MOS/MSC	01-Mar-17	O/C						
SN:2522	HRS	8086							
	AFL	4338							
PROC. REF: AMM 30-80-03	PROC. REF: AMM 30-80-03								
308003-0201		RIGHT WING CABL 03, W603 CABLE							Component ATA:30
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
308003-0202		LEFT WING CABL 03, W603 CABLE							Component ATA:30
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
ATA 31 - INDICATING/RECORDING SYSTEMS									
31-21-00-710-001-A00		OPERATIONALLY CHECK PILOT DIGITAL CLOCK INFORMATION NOTE: CHECK TOGETHER WITH TASK 31-31-00-720-001-A00.							Service ATA:31
	MOS/MSC	14-Jul-22	O/C						
	HRS	9904.2							
	AFL	5268							
PROC. REF: AMM 31-21-00	PROC. REF: AMM 31-21-00								
31-31-00-720-001-A00		FUNCTIONALLY CHECK REAR FLIGHT DATA SSFDR ELECTRONIC SYSTEM RECORDER							Service ATA:31
PN:980-4700-042	MOS	10-Dec-24	48 (+30d/-30d)		10-Dec-28	09-Jan-29	929 d (+30)	SYSTEM	
SN:SSFDR-13164	HRS	10605.1	4000		14605.1		3328.8		
	AFL	5653							
PROC. REF: AMM 31-31-00, AMM 31-31-00, AMM 31-31-00, AMM 31-31-00	PROC. REF: AMM 31-31-00, AMM 31-31-00, AMM 31-31-00, AMM 31-31-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 31 - INDICATING/RECORDING SYSTEMS									
31-31-02-960-001-A00		DISCARD FDR UNDERWATER LOCATOR BEACON (ULB) BATTERY NOTE: ULB BATTERY CHANGE IN ACCORDANCE WITH MANUFACTURER'S DATAPLATE EXPIRATION DATE						Service	ATA:31
PN:DK120	MOS/MSC	18-Jul-24	DUE		31-Oct-29 (M)		1254 d	SYSTEM	
SN:NT61967	HRS	10519.2							
	AFL	5604							
PROC. REF: AMM 31-31-02PROC. REF: AMM 31-31-02									
311300-0101		LH LIGHT PANEL MODULE						Component	ATA:31
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									
311300-0102		RH LIGHT PANEL MODULE						Component	ATA:31
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									
311700-0101		MODULE MAINTENANCE PANEL ASSEMBLY						Component	ATA:31
PN:135-53624-405	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:0000146486	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 31-17-01PROC. REF: AMM 31-17-01									
311803-0706 U		NO. 6 CABIN SEAT AUDIO CONTROLLER						Component	ATA:31
PN:990-6107-162	MOS/MSC	29-Dec-17	O/C	TSR 0					
SN:06120034180	HRS	8436.1		TSR 0					
	AFL	4528		TSR 0					
311803-0708 U		NO. 8 CABIN SEAT AUDIO CONTROLLER						Component	ATA:31
PN:990-6107-163	MOS/MSC	29-Dec-17	O/C	TSR 0					
SN:06120034179	HRS	8436.1		TSR 0					
	AFL	4528		TSR 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 31 - INDICATING/RECORDING SYSTEMS									
312102-0201		PILOT DIGITAL 2 POL CLOCK						Component	ATA:31
PN:APE4190-040	MOS/MSC	19-Sep-13	O/C	TSN 0					
SN:163	HRS	6680.2		TSN 0					
	AFL	3597		TSN 0					
PROC. REF: AMM 31-21-01	PROC. REF: AMM 31-21-01								
312102-0202		COPILOT DIGITAL 2 POL CLOCK						Component	ATA:31
PN:APE4190-040	MOS/MSC	19-Sep-13	O/C	TSN 0					
SN:164	HRS	6680.2		TSN 0					
	AFL	3597		TSN 0					
PROC. REF: AMM 31-21-01	PROC. REF: AMM 31-21-01								
313101-0101		REAR FLIGHT DATA SSFDR ELECTRONIC SYSTEM RECORDER						Component	ATA:31
PN:980-4700-042	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:SSFDR-13164	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 31-31-01	PROC. REF: AMM 31-31-01								
313101-0201		FDR UNDERWATER LOCATOR BEACON						Component	ATA:31
PN:DK120/90	MOS/MSC	19-Aug-24	O/C	TSN 0					
SN:NT61967	HRS	10541.4		TSN 0					
	AFL	5613		TSN 0					
PROC. REF: AMM 31-31-02	PROC. REF: AMM 31-31-02								
313101-0301		FLIGHT DATA RECORDER (FDR) UNDERWATER LOCATOR BEACON (ULB) BATTERY						Component	ATA:31
PN:DK120	MOS/MSC	18-Jul-24	H/T	TSN 0					
SN:NT61967	HRS	10519.2		TSN 0					
	AFL	5604		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
313102-0101		REAR TRI AXIAL ACCELEROMETER						Component	ATA:31
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 31-31-03	PROC. REF: AMM 31-31-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 31 - INDICATING/RECORDING SYSTEMS									
313105-0101		FDR SYS IMPACT SWITCH						Component	ATA:31
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 31-31-05PROC. REF: AMM 31-31-05									
313106-0101		LH WING ROTARY-VARIABLE INDUCTIVE, 28VDC/50MA TRANSDUCER						Component	ATA:31
PN:D370535	MOS/MSC	19-Jan-21	O/C						
SN:02J00161	HRS	9508.9							
	AFL	5061							
PROC. REF: AMM 31-31-06PROC. REF: AMM 31-31-06									
313106-0102		RH WING ROTARY-VARIABLE INDUCTIVE, 28VDC/50MA TRANSDUCER						Component	ATA:31
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 31-31-06PROC. REF: AMM 31-31-06									
313106-0103		ROTARY-VARIABLE INDUCTIVE, 28VDC/50MA TRANSDUCER						Component	ATA:31
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 31-31-06PROC. REF: AMM 31-31-06									
313106-0104		ROTARY-VARIABLE INDUCTIVE, 28VDC/50MA TRANSDUCER						Component	ATA:31
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 31-31-06PROC. REF: AMM 31-31-06									
313106-0105		TAIL ROTARY-VARIABLE INDUCTIVE, 28VDC/50MA TRANSDUCER						Component	ATA:31
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 31-31-06PROC. REF: AMM 31-31-06									

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 31 - INDICATING/RECORDING SYSTEMS									
313107-0101	REAR FUS AFDAU - AUXILIARY FLIGHT DATA ACQUISITION UNIT							Component	ATA:31
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 31-31-07	PROC. REF: AMM 31-31-07								
313108-0101	C FLOOR CONVERTER-ANALOGIC/DIGITAL,FLIGHT DATA RECORDING SYS UNIT							Component	ATA:31
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 31-31-08	PROC. REF: AMM 31-31-08								
314101-0101	REAR I DATA ACQUISITION DA-800 PH, 9 UNIT							Component	ATA:31
PN:7013348-948	MOS/MSC	30-Dec-22	O/C	TSN 184					
SN:07026460	HRS	10063.9		TSN 10063.9					
	AFL	5344		TSN 5344					
PROC. REF: AMM 31-41-01	PROC. REF: AMM 31-41-01								
314101-0102	C FLOOR DATA ACQUISITION DA-800 PH, 10 UNIT							Component	ATA:31
PN:7013348-948	MOS/MSC	30-Dec-22	O/C	TSN 184					
SN:06096358	HRS	10063.9		TSN 10063.9					
	AFL	5344		TSN 5344					
PROC. REF: AMM 31-41-01	PROC. REF: AMM 31-41-01								
314102-0201	CONTROL-EICAS SYS,MAIN PANEL							Component	ATA:31
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 31-41-02	PROC. REF: AMM 31-41-02								
314104-0101	CREW CAB CONTROL,EGPWS,NAVIGATION SYS,CTL CONSOLE,COCKPIT MODULE							Component	ATA:31
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 31 - INDICATING/RECORDING SYSTEMS									
314104-0102		CSL CENT MODULE MODULE						Component	ATA:31
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
314201-0101		INTEGRATED COMPUTER IC-600 WITH AP CARD						Component	ATA:31
PN:7017000-0101	MOS/MSC	18-Sep-24	O/C						
SN:00093656	HRS	10556							
	AFL	5619							
PROC. REF: AMM 31-42-01	PROC. REF: AMM 31-42-01								
314201-0102		INTEGRATED COMPUTER IC-600 WITHOUT AP CARD						Component	ATA:31
PN:7017000-83414	MOS/MSC	19-Aug-15	O/C	TSN 96					
SN:06117836	HRS	7460.3		TSN 7460.3					
	AFL	3992		TSN 3992					
PROC. REF: AMM 31-42-01	PROC. REF: AMM 31-42-01								
314202-0101		LEFT CONFIGURATION-IC-600 INTEGRATED COMPUTER, COCKPIT MODULE						Component	ATA:31
PN:7025973-03000	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:07024539	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 31-42-02	PROC. REF: AMM 31-42-02								
314202-0102		RIGHT CONFIGURATION-IC-600 INTEGRATED COMPUTER, COCKPIT MODULE						Component	ATA:31
PN:7025973-03000	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:07014519	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 31-42-02	PROC. REF: AMM 31-42-02								
314301-0101		MHE, PAX ENTERTAINMENT SYSTEM, BOX ASSY CONTROLLER						Component	ATA:31
PN:990-6800-004	MOS/MSC	01-Sep-17	O/C						
SN:07100044474	HRS	8284.1							
	AFL	4446							
PROC. REF: AMM 31-43-01	PROC. REF: AMM 31-43-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 31 - INDICATING/RECORDING SYSTEMS									
314302-0101		MHC25R, PAX CABIN CONTROLLER BOX ASSEMBLY						Component	ATA:31
PN:990-6812-001	MOS/MSC	23-May-14	O/C						
SN:05100022475	HRS	7003.7							
	AFL	3758							
PROC. REF: AMM 31-43-02	PROC. REF: AMM 31-43-02								
314303-0101		LAPTOP INETRFACE, PAX MHE AIRSHOW SYS, CONTROL ASSY PANEL						Component	ATA:31
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 31-43-01	PROC. REF: AMM 31-43-01								
314304-0101		MHR/IRS AIRSHOW,PAX ENTERTAINMENT CABINET RECEIVER						Component	ATA:31
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 31-43-04	PROC. REF: AMM 31-43-04								
314305-0101		MHR INFRARED SENSOR CONTROL UNIT						Component	ATA:31
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC, AMM 23-35-17	PROC. REF: NDT GENERIC, AMM 23-35-17								
314306-0101		MHI INTERFACE, ENT CABINET, CONTROL UNIT						Component	ATA:31
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 31-43-06	PROC. REF: AMM 31-43-06								
315101-0101		NOSE ALARM-AUDIO,ELECTRONIC EQUIPAMENT, FWD FUSLG UNIT						Component	ATA:31
PN:80-0694-2-8	MOS/MSC	19-Aug-16	O/C						
SN:2190	HRS	7460.3							
	AFL	3992							
PROC. REF: AMM 31-51-01	PROC. REF: AMM 31-51-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 31 - INDICATING/RECORDING SYSTEMS									
315102-0101		CREW CAB MODULE -CONSOLE,MAIN PANEL,COCKPIT ASSEMBLY						Component	ATA:31
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									
316101-0101		C FLOOR BOX -DIODES,AVIONICS POWER SUPPLY,FLOOR,COCKPIT ASSEMBLY						Component	ATA:31
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 31-61-01PROC. REF: AMM 31-61-01									
ATA 32 - LANDING GEAR									
32-10-00-210-801-L00 S		GENERAL VISUAL INSPECTION EXTERNALLY INSPECT THE MAIN LANDING GEAR COMPONENTS- TRAILING ARM - MLG (SSI 32-10-03).						Service	ATA:32
	MOS	29-Jun-23	96 (+15d/-15d)				LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6016
PROC. REF: NDT 32-10-00PROC. REF: NDT 32-10-00									
32-10-00-210-C01-L00 S		GENERAL VISUAL INSPECTION EXTERNALLY INSPECT THE MAIN LANDING GEAR COMPONENTS- LEG STRUCTURE, EQUIPPED (LEFT) - MLG (SSI 32-10-01).- LEG STRUCTURE, EQUIPPED (RIGHT) - MLG (SSI 32-10-02).- UPPER SECONDARY BRACE STRUT ASSY - MLG (SSI 32 -10-09).- LOWER SECONDARY BRACE STRUT ASSY - MLG (SSI 32-10-10).						Service	ATA:32
	MOS	29-Jun-23	48 (+15d/-15d)				LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: CPM 32-10-00PROC. REF: CPM 32-10-00									
32-10-00-210-C02-L00 S		GENERAL VISUAL INSPECTION EXTERNALLY INSPECT THE MAIN LANDING GEAR COMPONENTS- SHOCK ABSORBER PISTON TUBE ASSY - MLG (SSI 32-10-05).-SHOCK ABSORBER CYLINDER ASSY - MLG (SSI 32-10-06).						Service	ATA:32
	MOS	29-Jun-23	48 (+15d/-15d)				LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: CPM 32-10-00PROC. REF: CPM 32-10-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
32-10-00-220-801-L00 S	DETAILED INSPECTION (EXTERNAL) OF THE MAIN LANDING GEAR COMPONENTS- WHEEL AXLE - MLG (SSI 32-10-04).								Service ATA:32
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008
PROC. REF: NDT 32-10-00PROC. REF: NDT 32-10-00									
32-10-01-900-001-A00	RESTORE (OVERHAUL) LH MLG LEG OLEO STRUT ASSEMBLY								Service ATA:32
PN:2309-3100-405	MOS	01-Jul-19	144 (+60d/-60d)		01-Jul-31	30-Aug-31	1862 d (+60)	SYSTEM	
SN:00080	HRS	9057.4							
	AFL	4853							
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
32-10-01-900-001-A00	RESTORE (OVERHAUL) RH MLG LEG OLEO STRUT ASSEMBLY								Service ATA:32
PN:2309-3100-406	MOS	01-Jul-19	144 (+60d/-60d)		01-Jul-31	30-Aug-31	1862 d (+60)	SYSTEM	
SN:00090	HRS	9057.4							
	AFL	4853							
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
32-10-01-900-002-A00	RESTORE (OVERHAUL) LH MLG TRAILING ARM ASSY								Service ATA:32
	MOS	01-Jul-19	144 (+60d/-60d)		01-Jul-31	30-Aug-31	1862 d (+60)	SYSTEM	
	HRS	9057.4							
	AFL	4853							
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
32-10-01-900-002-A00	RESTORE (OVERHAUL) RH MLG TRAILING ARM ASSY								Service ATA:32
	MOS	01-Jul-19	144 (+60d/-60d)		01-Jul-31	30-Aug-31	1862 d (+60)	SYSTEM	
	HRS	9057.4							
	AFL	4853							
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
32-10-02-610-001-A00 S	SERVICE (REPLENISH) MLG SHOCK ABSORBER								Service ATA:32
	MOS	17-Oct-25	12 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	500 (+20/-20)						
	AFL	5820							
									PKG:5002

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
PROC. REF: AMM 32-10-02PROC. REF: AMM 32-10-02									
32-10-02-900-001-A00		RESTORE (OVERHAUL) LH MLG SHOCK ABSORBER ASSEMBLY							Service ATA:32
PN:2309-2005-007	MOS	01-Jul-19	144 (+60d/-60d)		01-Jul-31	30-Aug-31	1862 d (+60)	SYSTEM	
SN:10041	HRS	9057.4							
	AFL	4853							
PROC. REF: AMM 32-10-02PROC. REF: AMM 32-10-02									
32-10-02-900-001-A00		RESTORE (OVERHAUL) RH MLG SHOCK ABSORBER ASSEMBLY							Service ATA:32
PN:2309-2005-007	MOS	01-Jul-19	144 (+60d/-60d)		01-Jul-31	30-Aug-31	1862 d (+60)	SYSTEM	
SN:10004	HRS	9057.4							
	AFL	4853							
PROC. REF: AMM 32-10-02PROC. REF: AMM 32-10-02									
32-10-03-900-001-A00		RESTORE (OVERHAUL) LH MLG UPPER MAIN SIDE STRUT ASSEMBLY							Service ATA:32
PN:2309-2524-001	MOS	01-Jul-19	144 (+60d/-60d)		01-Jul-31	30-Aug-31	1862 d (+60)	SYSTEM	
SN:1143026/010	HRS	9057.4							
	AFL	4853							
PROC. REF: AMM 32-10-03PROC. REF: AMM 32-10-03									
32-10-03-900-001-A00		RESTORE (OVERHAUL) RH MLG UPPER MAIN SIDE STRUT ASSEMBLY							Service ATA:32
PN:2309-2524-001	MOS	01-Jul-19	144 (+60d/-60d)		01-Jul-31	30-Aug-31	1862 d (+60)	SYSTEM	
SN:1138062/005	HRS	9057.4							
	AFL	4853							
PROC. REF: AMM 32-10-03PROC. REF: AMM 32-10-03									
32-10-03-900-002-A00		RESTORE (OVERHAUL) LH MAIN SIDE ASSY (MLG) STRUT LOWER							Service ATA:32
PN:2309-3500-503	MOS	01-Jul-19	144 (+60d/-60d)		01-Jul-31	30-Aug-31	1862 d (+60)	SYSTEM	
SN:01528	HRS	9057.4							
	AFL	4853							
PROC. REF: AMM 32-10-03PROC. REF: AMM 32-10-03									
32-10-03-900-002-A00		RESTORE (OVERHAUL) RH MAIN SIDE ASSY (MLG) STRUT LOWER							Service ATA:32
PN:2309-3500-503	MOS	01-Jul-19	144 (+60d/-60d)		01-Jul-31	30-Aug-31	1862 d (+60)	SYSTEM	
SN:01491	HRS	9057.4							
	AFL	4853							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
PROC. REF: AMM 32-10-03PROC. REF: AMM 32-10-03									
32-10-04-900-001-A00	RESTORE (OVERHAUL) LH MLG UPPER SECONDARY SIDE STRUT ASSEMBLY								Service ATA:32
PN:2309-2611-003	MOS	01-Jul-19	144 (+60d/-60d)		01-Jul-31	30-Aug-31	1862 d (+60)	SYSTEM	
SN:1156805/007	HRS	9057.4							
	AFL	4853							
PROC. REF: AMM 32-10-04PROC. REF: AMM 32-10-04									
32-10-04-900-001-A00	RESTORE (OVERHAUL) RH MLG UPPER SECONDARY SIDE STRUT ASSEMBLY								Service ATA:32
PN:2309-2611-003	MOS	01-Jul-19	144 (+60d/-60d)		01-Jul-31	30-Aug-31	1862 d (+60)	SYSTEM	
SN:1137253/001	HRS	9057.4							
	AFL	4853							
PROC. REF: AMM 32-10-04PROC. REF: AMM 32-10-04									
32-10-04-900-002-A00	RESTORE (OVERHAUL) LH MLG SECONDARY SIDE STRUT (LOWER) ASSEMBLY								Service ATA:32
PN:2309-2624-001	MOS	01-Jul-19	144 (+60d/-60d)		01-Jul-31	30-Aug-31	1862 d (+60)	SYSTEM	
SN:1162870/012	HRS	9057.4							
	AFL	4853							
PROC. REF: AMM 32-10-04PROC. REF: AMM 32-10-04									
32-10-04-900-002-A00	RESTORE (OVERHAUL) RH MLG SECONDARY SIDE STRUT (LOWER) ASSEMBLY								Service ATA:32
PN:2309-2624-001	MOS	01-Jul-19	144 (+60d/-60d)		01-Jul-31	30-Aug-31	1862 d (+60)	SYSTEM	
SN:1139184/009	HRS	9057.4							
	AFL	4853							
PROC. REF: AMM 32-10-04PROC. REF: AMM 32-10-04									
32-10-05-900-002-A00	RESTORE (OVERHAUL) LH MLG SECONDARY SIDE STRUT NO.1 SPRING CARTRIDGE ASSY								Service ATA:32
	MOS	01-Jul-19	144 (+60d/-60d)		01-Jul-31	30-Aug-31	1862 d (+60)	SYSTEM	
	HRS	9057.4							
	AFL	4853							
PROC. REF: AMM 32-10-05PROC. REF: AMM 32-10-05									
32-10-05-900-002-A00	RESTORE (OVERHAUL) LH MLG SECONDARY SIDE STRUT NO.2 SPRING CARTRIDGE ASSY								Service ATA:32
	MOS	01-Jul-19	144 (+60d/-60d)		01-Jul-31 (M)	30-Aug-31	1862 d (+60)	SYSTEM	
	HRS	9057.4							
	AFL	4853							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
PROC. REF: AMM 32-10-05PROC. REF: AMM 32-10-05									
32-10-05-900-002-A00	RESTORE (OVERHAUL) RH MLG SECONDARY SIDE STRUT NO.1 SPRING CARTRIDGE ASSY								Service ATA:32
	MOS	01-Jul-19	144 (+60d/-60d)		01-Jul-31	30-Aug-31	1862 d (+60)	SYSTEM	
	HRS	9057.4							
	AFL	4853							
PROC. REF: AMM 32-10-05PROC. REF: AMM 32-10-05									
32-10-05-900-002-A00	RESTORE (OVERHAUL) RH MLG SECONDARY SIDE STRUT NO.2 SPRING CARTRIDGE ASSY								Service ATA:32
	MOS	01-Jul-19	144 (+60d/-60d)		01-Jul-31 (M)	30-Aug-31	1862 d (+60)	SYSTEM	
	HRS	9057.4							
	AFL	4853							
PROC. REF: AMM 32-10-05PROC. REF: AMM 32-10-05									
32-20-00-210-801-L00 S	GENERAL VISUAL INSPECTION EXTERNALLY INSPECT THE NOSE LANDING GEAR COMPONENTS - STRUT (MAIN FITTING) - NLG (SSI 32-20-12).- LOWER LOCKING STRUT (SSI 32-20-16).- UPPER DRAG STAY - NLG (SSI 32-20-13).- UPPER LOCKING STAY - NLG (SSI 32-20-15).- TORQUE LINKS - NLG (SSI 32-20-17).								Service ATA:32
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: NDT 32-20-00PROC. REF: NDT 32-20-00									
32-20-00-210-802-L00 S	GENERAL VISUAL INSPECTION (EXTERNAL) INSPECT THE NOSE LANDING GEAR COMPONENTS- SLIDING TUBE - NLG (SSI 32-20-18).								Service ATA:32
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008
PROC. REF: NDT 32-20-00PROC. REF: NDT 32-20-00									
32-20-00-210-C01-L00 S	GENERAL VISUAL INSPECTION (EXTERNAL) INSPECT THE NOSE LANDING GEAR COMPONENTS- LOWER DRAG STAY - NLG (SSI 32-20-14).								Service ATA:32
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: CPM 32-20-00PROC. REF: CPM 32-20-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
32-20-00-220-801-L00 S	DETAILED INSPECTION (EXTERNAL) INSPECT THE NOSE LANDING GEAR COMPONENTS- WHEEL AXLE (SSI 32-20-19).							Service	ATA:32
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008
PROC. REF: NDT 32-20-00PROC. REF: NDT 32-20-00									
32-20-01-610-001-A00 S	SERVICE (REPLENISH) NLG SHOCK ABSORBER							Service	ATA:32
	MOS	17-Oct-25	12 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	500 (+20/-20)						
	AFL	5820							
									PKG:5002
PROC. REF: AMM 32-20-01PROC. REF: AMM 32-20-01									
32-20-01-720-001-A00	FUNCTIONALLY CHECK NLG LEG CENTERING CAM PLAY NOTE: PERFORM AT THE TIME OF NLG SLIDING TUBE ASSY RESTORATION							Service	ATA:32
	MOS/MSC	01-Jul-19	O/C						
	HRS	9057.4							
	AFL	4853							
PROC. REF: AMM 32-20-01PROC. REF: AMM 32-20-01									
32-20-01-900-001-A00	RESTORE (OVERHAUL) NOSE LANDING GEAR (NLG) MAIN FITTING ASSY							Service	ATA:32
	MOS	01-Jul-19	144 (+60d/-60d)		01-Jul-31	30-Aug-31	1862 d (+60)	SYSTEM	
	HRS	9057.4							
	AFL	4853							
PROC. REF: AMM 32-20-01PROC. REF: AMM 32-20-01									
32-20-01-900-002-A00	RESTORE (OVERHAUL) NLG LEG STRUT SLIDING TUBE							Service	ATA:32
PN:2233-0201	MOS	01-Jul-19	144 (+60d/-60d)		01-Jul-31	30-Aug-31	1862 d (+60)	SYSTEM	
SN:1379	HRS	9057.4							
	AFL	4853							
PROC. REF: AMM 32-20-01PROC. REF: AMM 32-20-01									
32-20-01-900-003-A00	RESTORE (OVERHAUL) NLG LEG STRUT STEERING CUFF							Service	ATA:32
PN:1170-2301	MOS	01-Jul-19	144 (+60d/-60d)		01-Jul-31	30-Aug-31	1862 d (+60)	SYSTEM	
SN:L1578	HRS	9057.4							
	AFL	4853							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
PROC. REF: AMM 32-20-01PROC. REF: AMM 32-20-01									
32-20-01-900-004-A00		RESTORE (OVERHAUL) NO.1 NLG LEG STRUT TORQUE LINK							Service ATA:32
PN:1170-0301	MOS	01-Jul-19	144 (+60d/-60d)		01-Jul-31	30-Aug-31	1862 d (+60)	SYSTEM	
SN:L2583	HRS	9057.4							
	AFL	4853							
PROC. REF: AMM 32-20-01PROC. REF: AMM 32-20-01									
32-20-01-900-004-A00		RESTORE (OVERHAUL) NO.2 NLG LEG STRUT TORQUE LINK							Service ATA:32
PN:1170-0301	MOS	01-Jul-19	144 (+60d/-60d)		01-Jul-31	30-Aug-31	1862 d (+60)	SYSTEM	
SN:L2584	HRS	9057.4							
	AFL	4853							
PROC. REF: AMM 32-20-01PROC. REF: AMM 32-20-01									
32-20-02-900-001-A00		RESTORE (OVERHAUL) TOP NLG MAIN DRAG STRUT STAY							Service ATA:32
PN:1172A0600-01	MOS	01-Jul-19	144 (+60d/-60d)		01-Jul-31	30-Aug-31	1862 d (+60)	SYSTEM	
SN:HM1431	HRS	9057.4							
	AFL	4853							
PROC. REF: AMM 32-20-02PROC. REF: AMM 32-20-02									
32-20-02-900-002-A00		RESTORE (OVERHAUL) BOTTOM NLG MAIN DRAG STRUT STAY							Service ATA:32
PN:1172A0200-01	MOS	01-Jul-19	144 (+60d/-60d)		01-Jul-31	30-Aug-31	1862 d (+60)	SYSTEM	
SN:HM39	HRS	9057.4							
	AFL	4853							
PROC. REF: AMM 32-20-02PROC. REF: AMM 32-20-02									
32-20-03-900-001-A00		RESTORE (OVERHAUL) NLG AUXILIARY DRAG STRUT (UPPER) ASSEMBLY							Service ATA:32
PN:1173A0200-01	MOS	01-Jul-19	144 (+60d/-60d)		01-Jul-31	30-Aug-31	1862 d (+60)	SYSTEM	
SN:HM1191	HRS	9057.4							
	AFL	4853							
PROC. REF: AMM 32-20-03PROC. REF: AMM 32-20-03									
32-20-03-900-002-A00		RESTORE (OVERHAUL) NLG AUXILIARY DRAG STRUT (LOWER) ASSEMBLY							Service ATA:32
PN:1173A0100-02	MOS	01-Jul-19	144 (+60d/-60d)		01-Jul-31	30-Aug-31	1862 d (+60)	SYSTEM	
SN:L1327	HRS	9057.4							
	AFL	4853							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
PROC. REF: AMM 32-20-03PROC. REF: AMM 32-20-03									
32-20-04-900-002-A00		RESTORE (OVERHAUL) NLG DOWN LOCK SPRING ASSY							Service ATA:32
	MOS	01-Jul-19	144 (+60d/-60d)		01-Jul-31	30-Aug-31	1862 d (+60)	SYSTEM	
	HRS	9057.4							
	AFL	4853							
PROC. REF: AMM 32-20-04PROC. REF: AMM 32-20-04									
32-32-00-710-001-A00 S		OPERATIONALLY CHECK LANDING GEAR EXTENSION AND RETRACTION (ELECTRICAL) INDICATION AND DOWNLOCK RELAYS BY CHANNELS A AND B (WITH JACKS)							Service ATA:32
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 32-32-00PROC. REF: AMM 32-32-00									
32-32-02-710-001-A00 S		OPERATIONALLY CHECK SOLENOID AND DOWLOCK RELEASE BUTTON OF THE LANDING GEAR CONTROL LEVER.							Service ATA:32
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: AMM 32-32-02PROC. REF: AMM 32-32-02									
32-34-00-640-001-A00 S		LUBRICATE LANDING GEAR (MLG & NLG) AND STEERING SYSTEM							Service ATA:32
	MOS	17-Oct-25	12 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	500 (+20/-20)						
	AFL	5820							
									PKG:5002
PROC. REF: AMM 32-34-00PROC. REF: AMM 32-34-00									
32-34-00-710-001-A00 S		OPERATIONALLY CHECK LANDING GEAR EMERGENCY EXTENSION (OVERRIDE SWITCH)							Service ATA:32
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 32-34-00PROC. REF: AMM 32-34-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
32-34-00-720-001-A01 S	FUNCTIONALLY CHECK LANDING GEAR EMERGENCY EXTENSION							Service	ATA:32
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 32-34-00PROC. REF: AMM 32-34-00									
32-34-03-720-001-A00 S	FUNCTIONALLY CHECK CONDITION AND TENSION OF FREE-FALL CONTROL CABLES							Service	ATA:32
	MOS	17-Oct-25	72 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	3000 (+20/-20)						
	AFL	5820	1500 (+20/-20)						
									PKG:5012,6020
PROC. REF: AMM 32-34-03PROC. REF: AMM 32-34-03									
32-41-00-720-001-A00 S	FUNCTIONALLY CHECK MAIN BRAKE SYSTEM							Service	ATA:32
	MOS	30-Dec-24	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10619.1	2000 (+20/-20)						
	AFL	5659	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 32-41-00PROC. REF: AMM 32-41-00									
32-41-01-710-001-A00 S	OPERATIONALLY CHECK BRAKE-PEDAL POSITION TRANSDUCER							Service	ATA:32
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01									
32-41-07-720-001-A00 S	FUNCTIONALLY CHECK MAIN BRAKE HYDRAULIC FUSES							Service	ATA:32
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 32-41-07PROC. REF: AMM 32-41-07									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
32-41-09-710-001-A00 S	OPERATIONALLY CHECK RETURN-LINE CHECK VALVE OF MAIN BRAKE SYSTEM.							Service	ATA:32
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 32-41-09PROC. REF: AMM 32-41-09									
32-44-00-720-001-A00 S	FUNCTIONALLY CHECK EMERGENCY/PARKING BRAKE SYSTEM							Service	ATA:32
	MOS	30-Dec-24	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10619.1	4000 (+20/-20)						
	AFL	5659	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: AMM 32-44-00PROC. REF: AMM 32-44-00									
32-44-02-720-001-A00 S	FUNCTIONALLY CHECK HYDRAULIC ACCUMULATOR FOR NITROGEN PRE-CHARGE							Service	ATA:32
	MOS	17-Oct-25	12 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	500 (+20/-20)						
	AFL	5820							
									PKG:5002
PROC. REF: AMM 32-44-02PROC. REF: AMM 32-44-02									
32-44-06-720-001-A00 S	FUNCTIONALLY CHECK THERMAL RELIEF VALVE OF THE EMERGENCY/PARKING BRAKE SYSTEM							Service	ATA:32
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: AMM 32-44-06PROC. REF: AMM 32-44-06									
32-44-08-710-001-A00 S	OPERATIONALLY CHECK RETURN-LINE CHECK VALVE OF EMERGENCY/PARKING BRAKE SYSTEM							Service	ATA:32
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 32-44-08PROC. REF: AMM 32-44-08									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
32-44-10-640-001-A00 S	LUBRICATE MECHANICAL HARDWARE (HANDLE) AND ROLLER OF EMERGENCY PARKING BRAKE VALVE							Service	ATA:32
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 32-44-10PROC. REF: AMM 32-44-10									
32-49-02-220-001-A00	INSPECT (DETAILED INSPECTION) LEFT NO. 1 MAIN LANDING GEAR OUTBOARD TIRE MLG WHEEL ASSY - WHEELS SPEED TRANSDUCER CLIP IN THE HUB CAP DRIVE CLIP NOTE: AT EACH TIRE CHANGE							Service	ATA:32
PN:304K63-2	MOS/MSC	11-Aug-25	T/C					SYSTEM	
SN:33485239	HRS	10856.2							
	AFL	5786							
PROC. REF: AMM 32-49-02PROC. REF: AMM 32-49-02									
32-49-02-220-001-A00	INSPECT (DETAILED INSPECTION) LEFT NO. 2 MAIN LANDING GEAR INBOARD TIRE MLG WHEEL ASSY - WHEELS SPEED TRANSDUCER CLIP IN THE HUB CAP DRIVE CLIP NOTE: AT EACH TIRE CHANGE							Service	ATA:32
PN:304K63-2	MOS/MSC	15-Jan-26	T/C					SYSTEM	
SN:51416228	HRS	11060.9							
	AFL	5907							
PROC. REF: AMM 32-49-02PROC. REF: AMM 32-49-02									
32-49-02-220-001-A00	INSPECT (DETAILED INSPECTION) RIGHT NO. 3 MAIN LANDING GEAR INBOARD TIRE MLG WHEEL ASSY - WHEELS SPEED TRANSDUCER CLIP IN THE HUB CAP DRIVE CLIP NOTE: AT EACH TIRE CHANGE							Service	ATA:32
PN:304K63-2	MOS/MSC	15-Jan-26	T/C					SYSTEM	
SN:50236243	HRS	11060.9							
	AFL	5907							
PROC. REF: AMM 32-49-02PROC. REF: AMM 32-49-02									
32-49-02-220-001-A00	INSPECT (DETAILED INSPECTION) RIGHT NO. 4 MAIN LANDING GEAR OUTBOARD TIRE MLG WHEEL ASSY - WHEELS SPEED TRANSDUCER CLIP IN THE HUB CAP DRIVE CLIP NOTE: AT EACH TIRE CHANGE							Service	ATA:32
PN:304K63-2	MOS/MSC	09-Apr-26	T/C					SYSTEM	
SN:51376211	HRS	11166.4							
	AFL	5961							
PROC. REF: AMM 32-49-02PROC. REF: AMM 32-49-02									

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
32-49-03-220-001-A00	INSPECT (DETAILED INSPECTION) OF LEFT NO. 1 BRAKE WEAR INDICATOR. NOTE: AT EACH TIRE CHANGE							Service	ATA:32
PN:304K63-2	MOS/MSC		T/C					SYSTEM	
SN:33485239	HRS								
	AFL								
PROC. REF: AMM 32-49-03PROC. REF: AMM 32-49-03									
32-49-03-220-001-A00	INSPECT (DETAILED INSPECTION) OF LEFT NO. 2 BRAKE WEAR INDICATOR. NOTE: AT EACH TIRE CHANGE							Service	ATA:32
PN:304K63-2	MOS/MSC	15-Jan-26	T/C					SYSTEM	
SN:51416228	HRS	11060.9							
	AFL	5907							
PROC. REF: AMM 32-49-03PROC. REF: AMM 32-49-03									
32-49-03-220-001-A00	INSPECT (DETAILED INSPECTION) OF RIGHT NO. 3 BRAKE WEAR INDICATOR. NOTE: AT EACH TIRE CHANGE							Service	ATA:32
PN:304K63-2	MOS/MSC	15-Jan-26	T/C					SYSTEM	
SN:50236243	HRS	11060.9							
	AFL	5907							
PROC. REF: AMM 32-49-03PROC. REF: AMM 32-49-03									
32-49-03-220-001-A00	INSPECT (DETAILED INSPECTION) OF RIGHT NO. 4 BRAKE WEAR INDICATOR. NOTE: AT EACH TIRE CHANGE							Service	ATA:32
PN:304K63-2	MOS/MSC	09-Apr-26	T/C					SYSTEM	
SN:51376211	HRS	11166.4							
	AFL	5961							
PROC. REF: AMM 32-49-03PROC. REF: AMM 32-49-03									
32-49-07-710-001-A00	OPERATIONALLY CHECK NO. 1 CARBON ASSY-LEG,MAIN LANDING GEAR BRAKE BRAKE SHUTTLE VALVE NOTE: AT EACH BRAKE REPLACEMENT							Service	ATA:32
PN:2-1582OPT5	MOS/MSC	27-Aug-07	C/C					SYSTEM	
SN:2723	HRS	0							
	AFL	0							
PROC. REF: AMM 32-49-07PROC. REF: AMM 32-49-07									
32-49-07-710-001-A00	OPERATIONALLY CHECK NO. 2 CARBON ASSY-LEG,MAIN LANDING GEAR BRAKE BRAKE SHUTTLE VALVE NOTE: AT EACH BRAKE REPLACEMENT							Service	ATA:32
PN:2-1582	MOS/MSC	30-Dec-24	C/C						
SN:2219	HRS	10619.1							
	AFL	5659							
PROC. REF: AMM 32-49-07PROC. REF: AMM 32-49-07									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
32-49-07-710-001-A00		OPERATIONALLY CHECK NO. 3 CARBON ASSY-LEG,MAIN LANDING GEAR BRAKE BRAKE SHUTTLE VALVE NOTE: AT EACH BRAKE REPLACEMENT						Service	ATA:32
PN:2-1582	MOS/MSC	18-Aug-18	C/C						
SN:1968	HRS	8725.1							
	AFL	4681							
PROC. REF: AMM 32-49-07PROC. REF: AMM 32-49-07									
32-49-07-710-001-A00		OPERATIONALLY CHECK NO. 4 CARBON ASSY-LEG,MAIN LANDING GEAR BRAKE BRAKE SHUTTLE VALVE NOTE: AT EACH BRAKE REPLACEMENT						Service	ATA:32
PN:2-1582OPT5	MOS/MSC	27-Aug-07	C/C						
SN:1844	HRS	0							
	AFL	0							
PROC. REF: AMM 32-49-07PROC. REF: AMM 32-49-07									
32-50-00-710-001-A00 S		OPERATIONALLY CHECK NOSE WHEEL STEERING SYSTEM DISENGAGEMENT						Service	ATA:32
	MOS	17-Oct-25	12 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	500 (+20/-20)						
	AFL	5820							
									PKG:5002
PROC. REF: AMM 32-50-00PROC. REF: AMM 32-50-00									
32-50-06-720-001-A00 S		FUNCTIONALLY CHECK 7-DEGREE PROXIMITY SWITCH.						Service	ATA:32
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 32-50-06PROC. REF: AMM 32-50-06									
32-62-00-710-001-A00 S		OPERATIONALLY CHECK LANDING-GEAR WARNING SYSTEM						Service	ATA:32
	MOS	17-Oct-25	12 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	500 (+20/-20)						
	AFL	5820							
									PKG:5002
PROC. REF: AMM 32-62-00PROC. REF: AMM 32-62-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
32-63-00-710-001-A00 S	OPERATIONALLY CHECK AIR/GROUND SYSTEM (CMR)							Service	ATA:32
	MOS	17-Oct-25	12 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	500 (+20/-20)						
	AFL	5820							
									PKG:5002
PROC. REF: AMM 32-63-00PROC. REF: AMM 32-63-00									
32-Z711-213-001-A00 S	EXTERNAL GENERAL VISUAL INSPECTION OF ZONES 113, 114, 115, 116, 711, 713, 714 (L600 ONLY)							Service	ATA:32
	MOS	17-Oct-25	24 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	1000 (+20/-20)						
	AFL	5820							
									PKG:5004
PROC. REF: AMM 05-20-99PROC. REF: AMM 05-20-99									
32-Z711-213-001-A01	GENERAL VISUAL INSPECTION EXTERNAL GENERAL VISUAL INSPECTION (ZONES 113, 114, 115, 116,711, 713, 714) NOTE: EWIS.(L650 ONLY)							Service	ATA:32
	MOS/MSC	25-Sep-07	N/A					ZONAL	
	HRS	0							
	AFL	0							
PROC. REF: AMM 05-20-99PROC. REF: AMM 05-20-99									
32-Z721-213-001-A00 S	EXTERNAL GENERAL VISUAL INSPECTION OF ZONES 721, 731, 722, 732, 532, 632 (L600 ONLY)							Service	ATA:32
	MOS	17-Oct-25	24 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	1000 (+20/-20)						
	AFL	5820							
									PKG:5004
PROC. REF: AMM 05-30-01PROC. REF: AMM 05-30-01									
32-Z721-213-001-A01	GENERAL VISUAL INSPECTION (EXTERNAL) (ZONES 721, 731, 722, 732, 532, 632).NOTE: EWIS. (L650 ONLY)							Service	ATA:32
	MOS/MSC	25-Sep-07	N/A					ZONAL	
	HRS	0							
	AFL	0							
PROC. REF: AMM 05-30-01PROC. REF: AMM 05-30-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
321000-0101	LH MLG LEG OLEO STRUT ASSEMBLY								Component ATA:32
PN:2309-3100-405	MOS/MSC	06-Jul-19	O/C	TSN 143, TSO 0					
SN:00080	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853		TSN 4853, TSO 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
321000-0102	RH MLG LEG OLEO STRUT ASSEMBLY								Component ATA:32
PN:2309-3100-406	MOS/MSC	06-Jul-19	O/C	TSN 143, TSO 0					
SN:00090	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853		TSN 4853, TSO 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
321000-0201	LH STRUT (MLG) LEG								Component ATA:32
PN:2309-3006-505	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT	
SN:1145758/001	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853	60000	TSN 4853	60000		53975		
PROC. REF: AMM 32-10-01	PROC. REF: AMM 32-10-01								
321000-0202	RH STRUT (MLG) LEG								Component ATA:32
PN:2309-3006-506	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT	
SN:1134444/001	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853	60000	TSN 4853	60000		53975		
PROC. REF: AMM 32-10-01	PROC. REF: AMM 32-10-01								
321000-0203	LH STRUT (MLG) - PIVOT								Component ATA:32
PN:2309-2050-003	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT	
SN:1078756/021	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853	60000	TSN 4853	60000		53975		
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
321000-0204	RH STRUT (MLG) - PIVOT								Component ATA:32
PN:2309-2050-003	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT	
SN:1078756/014	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853	60000	TSN 4853	60000		53975		
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
321000-0301		LH NO. 1 TRUNNION (MLG) (LEG STRUT) AXLE							Component ATA:32
PN:2309-3025-001	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT	
SN:1129173/004	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853	60000	TSN 4853	60000		53975		
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
321000-0302		RH NO. 1 TRUNNION (MLG) (LEG STRUT) AXLE							Component ATA:32
PN:2309-3025-001	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT	
SN:1120134/001	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853	60000	TSN 4853	60000		53975		
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
321000-0303		LH NO. 2 TRUNNION (MLG) (LEG STRUT) AXLE							Component ATA:32
PN:2309-3025-001	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT	
SN:1129173/001	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853	60000	TSN 4853	60000		53975		
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
321000-0304		RH NO. 2 TRUNNION (MLG) (LEG STRUT) AXLE							Component ATA:32
PN:2309-3025-001	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT	
SN:1120134/010	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853	60000	TSN 4853	60000		53975		
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
321000-0401		LH ACTUATOR ATTACHMENT (MLG) (LEG STRUT) AXLE							Component ATA:32
PN:2309-2027-005	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:1143020/008	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
321000-0402		RH ACTUATOR ATTACHMENT (MLG) (LEG STRUT) AXLE							Component ATA:32
PN:2309-2027-005	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:1128751/007	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
321001-0101		LH TRAILING (MLG) (LEG STRUT) ARM							Component ATA:32
PN:2309-3009-507	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT	
SN:1138043/002	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853	60000	TSN 4853	60000		53975		
PROC. REF: AMM 32-10-08	PROC. REF: AMM 32-10-08								
321001-0102		RH TRAILING (MLG) (LEG STRUT) ARM							Component ATA:32
PN:2309-3009-507	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT	
SN:1139180/002	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853	60000	TSN 4853	60000		53975		
PROC. REF: AMM 32-10-08	PROC. REF: AMM 32-10-08								
321001-0201		LH TRAILING ARM (MLG) (LEG STRUT) AXLE							Component ATA:32
PN:2309-3055-001	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT	
SN:1150008/005	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853	60000	TSN 4853	60000		53975		
PROC. REF: AMM 32-10-08	PROC. REF: AMM 32-10-08								
321001-0202		RH TRAILING ARM (MLG) (LEG STRUT) AXLE							Component ATA:32
PN:2309-3055-002	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT	
SN:1132809/001	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853	60000	TSN 4853	60000		53975		
PROC. REF: AMM 32-10-08	PROC. REF: AMM 32-10-08								
321002-0101		LH MLG SHOCK ABSORBER ASSEMBLY							Component ATA:32
PN:2309-2005-007	MOS/MSC	06-Jul-19	O/C	TSO 0					
SN:10041	HRS	9057.4		TSN 8793.6, TSO 0					
	AFL	4853		TSN 4716, TSO 0					
PROC. REF: AMM 32-10-02	PROC. REF: AMM 32-10-02								
321002-0102		RH MLG SHOCK ABSORBER ASSEMBLY							Component ATA:32
PN:2309-2005-007	MOS/MSC	06-Jul-19	O/C	TSO 0					
SN:10004	HRS	9057.4		TSO 0					
	AFL	4853		TSO 0					
PROC. REF: AMM 32-10-02	PROC. REF: AMM 32-10-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
321002-0201		LH MLG NO.1 SHOCK ABSORBER ATTACHMENT (LEG STRUT) AXLE							Component ATA:32
PN:2309-2029-001	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT	
SN:1145948/005	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853	60000	TSN 4853	60000		53975		
PROC. REF: AMM 32-10-02PROC. REF: AMM 32-10-02									
321002-0202		RH MLG NO.1 SHOCK ABSORBER ATTACHMENT (LEG STRUT) AXLE							Component ATA:32
PN:2309-2029-001	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT	
SN:1140197/007	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853	60000	TSN 4853	60000		53975		
PROC. REF: AMM 32-10-02PROC. REF: AMM 32-10-02									
321002-0203		LH MLG NO.2 SHOCK ABSORBER ATTACHMENT (LEG STRUT) AXLE							Component ATA:32
PN:2309-2029-001	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT	
SN:1145948/004	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853	60000	TSN 4853	60000		53975		
PROC. REF: AMM 32-10-02PROC. REF: AMM 32-10-02									
321002-0204		RH MLG NO.2 SHOCK ABSORBER ATTACHMENT (LEG STRUT) AXLE							Component ATA:32
PN:2309-2029-001	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT	
SN:1140197/008	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853	60000	TSN 4853	60000		53975		
PROC. REF: AMM 32-10-02PROC. REF: AMM 32-10-02									
321002-0301		LH SHOCK ABSORBER PISTON (MLG) (LEG STRUT) TUBE							Component ATA:32
PN:2309-2058-001	MOS	06-Jul-19		TSO 0				LIFE LIMIT	
SN:1138316/001	HRS	9057.4		TSO 0					
	AFL	4853	60000	TSN 4716	60137		54112		
PROC. REF: AMM 32-10-02PROC. REF: AMM 32-10-02									
321002-0302		RH SHOCK ABSORBER PISTON (MLG) (LEG STRUT) TUBE							Component ATA:32
PN:2309-2058-001	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT	
SN:1129863-002	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853	60000	TSN 4853	60000		53975		
PROC. REF: AMM 32-10-02PROC. REF: AMM 32-10-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
321002-0401		LH SHOCK ABSORBER (MLG) (LEG STRUT) CYLINDER							Component ATA:32
PN:2309-2056-005	MOS	06-Jul-19		TSO 0				LIFE LIMIT	
SN:1139199/001	HRS	9057.4		TSO 0					
	AFL	4853	60000	TSN 4716	60137		54112		
PROC. REF: AMM 32-10-02	PROC. REF: AMM 32-10-02								
321002-0402		RH SHOCK ABSORBER (MLG) (LEG STRUT) CYLINDER							Component ATA:32
PN:2309-2056-005	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT	
SN:1130055-001	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853	60000	TSN 4853	60000		53975		
PROC. REF: AMM 32-10-02	PROC. REF: AMM 32-10-02								
321002-0501		LH SHOCK ABSORBER BEARING (MLG) (LEG STRUT) CAP							Component ATA:32
PN:2309-2082-001	MOS	06-Jul-19		TSO 0				LIFE LIMIT	
SN:1139188/006	HRS	9057.4		TSO 0					
	AFL	4853	60000	TSN 4716	60137		54112		
PROC. REF: AMM 32-10-02	PROC. REF: AMM 32-10-02								
321002-0502		RH SHOCK ABSORBER BEARING (MLG) (LEG STRUT) CAP							Component ATA:32
PN:2309-2082-001	MOS	06-Jul-19		TSN 0				LIFE LIMIT	
SN:1621044/002	HRS	9057.4		TSN 0					
	AFL	4853	60000	TSN 0	64853		58828		
PROC. REF: AMM 32-10-02	PROC. REF: AMM 32-10-02								
321003-0101		LH MAIN SIDE ASSY (MLG) STRUT							Component ATA:32
PN:2309-3500-503	MOS/MSC	06-Jul-19	O/C	TSN 143, TSO 0					
SN:01528	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853		TSN 4853, TSO 0					
PROC. REF: AMM 32-10-03	PROC. REF: AMM 32-10-03								
321003-0102		RH MAIN SIDE ASSY (MLG) STRUT							Component ATA:32
PN:2309-3500-503	MOS/MSC	06-Jul-19	O/C	TSN 143, TSO 0					
SN:01491	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853		TSN 4853, TSO 0					
PROC. REF: AMM 32-10-03	PROC. REF: AMM 32-10-03								

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
321003-0201		LH MLG LEG STRUT - MAIN SIDE STRUT ATTCHEMENT AXLE (PIVOT PIN)						Component	ATA:32
PN:2309-3032-005	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT	
SN:1138094/001	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853	60000	TSN 4853	60000		53975		
PROC. REF: AMM 32-10-10	PROC. REF: AMM 32-10-10								
321003-0202		RH MLG LEG STRUT - MAIN SIDE STRUT ATTCHEMENT AXLE (PIVOT PIN)						Component	ATA:32
PN:2309-3032-005	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT	
SN:1133462-002	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853	60000	TSN 4853	60000		53975		
PROC. REF: AMM 32-10-10	PROC. REF: AMM 32-10-10								
321003-0301		LH MLG UPPER MAIN SIDE STRUT						Component	ATA:32
PN:2309-2524-001	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT	
SN:1143026/010	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853	60000	TSN 4853	60000		53975		
PROC. REF: AMM 32-10-03	PROC. REF: AMM 32-10-03								
321003-0302		RH MLG UPPER MAIN SIDE STRUT						Component	ATA:32
PN:2309-2524-001	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT	
SN:1138062/005	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853	60000	TSN 4853	60000		53975		
PROC. REF: AMM 32-10-03	PROC. REF: AMM 32-10-03								
321003-0401		LH MAIN SIDE STRUT (MLG) (LOWER)						Component	ATA:32
PN:2309-2532-001	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT	
SN:1145946/007	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853	60000	TSN 4853	60000		53975		
PROC. REF: AMM 32-10-03	PROC. REF: AMM 32-10-03								
321003-0402		RH MAIN SIDE STRUT (MLG) (LOWER)						Component	ATA:32
PN:2309-2532-001	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT	
SN:1130597-010	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853	60000	TSN 4853	60000		53975		
PROC. REF: AMM 32-10-03	PROC. REF: AMM 32-10-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
321003-0501		LH MAIN SIDE STRUT (MLG) SHAFT							Component ATA:32
PN:2309-3515-001	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT	
SN:1148030/004	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853	60000	TSN 4853	60000		53975		
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
321003-0502		RH MAIN SIDE STRUT (MLG) SHAFT							Component ATA:32
PN:2309-3515-001	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT	
SN:1126836/004	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853	60000	TSN 4853	60000		53975		
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
321003-0601		LH MAIN SIDE STRUT (MLG) PIVOT PIN							Component ATA:32
PN:2309-3516-001	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT	
SN:1150805/001	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853	60000	TSN 4853	60000		53975		
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
321003-0602		RH MAIN SIDE STRUT (MLG) PIVOT PIN							Component ATA:32
PN:2309-3516-001	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT	
SN:1124611/006	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853	60000	TSN 4853	60000		53975		
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
321003-0701		LH MAIN SIDE STRUT (MLG) CARDAN							Component ATA:32
PN:2309-3530-001	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:1144576/002	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-10-10	PROC. REF: AMM 32-10-10								
321003-0702		RH MAIN SIDE STRUT (MLG) CARDAN							Component ATA:32
PN:2309-3530-001	MOS/MSC	06-Jul-19	O/C	TSN 143, TSO 0					
SN:1119633/002	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853		TSN 4853, TSO 0					
PROC. REF: AMM 32-10-10	PROC. REF: AMM 32-10-10								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
321004-0101		LH LDG ROD -SECONDARY,MAIN LANDING GEAR ASSEMBLY						Component	ATA:32
PN:2309-2600-507	MOS/MSC	06-Jul-19	O/C	TSN 143, TSO 0					
SN:02104	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853		TSN 4853, TSO 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
321004-0102		RH LDG ROD -SECONDARY,MAIN LANDING GEAR ASSEMBLY						Component	ATA:32
PN:2309-2600-507	MOS/MSC	06-Jul-19	O/C	TSN 143, TSO 0					
SN:02066	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853		TSN 4853, TSO 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
321004-0301		LH MLG UPPER SECONDARY SIDE STRUT						Component	ATA:32
PN:2309-2611-003	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT	
SN:1156805/007	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853	60000	TSN 4853	60000		53975		
PROC. REF: AMM 32-10-10	PROC. REF: AMM 32-10-10								
321004-0302		RH MLG UPPER SECONDARY SIDE STRUT						Component	ATA:32
PN:2309-2611-003	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT	
SN:1137253/001	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853	60000	TSN 4853	60000		53975		
PROC. REF: AMM 32-10-10	PROC. REF: AMM 32-10-10								
321004-0401		LH MLG SECONDARY SIDE STRUT (LOWER)						Component	ATA:32
PN:2309-2624-001	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT	
SN:1162870/012	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853	60000	TSN 4853	60000		53975		
PROC. REF: AMM 32-10-04	PROC. REF: AMM 32-10-04								
321004-0402		RH MLG SECONDARY SIDE STRUT (LOWER)						Component	ATA:32
PN:2309-2624-001	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT	
SN:1139184/009	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853	60000	TSN 4853	60000		53975		
PROC. REF: AMM 32-10-04	PROC. REF: AMM 32-10-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
321004-0501		LH MLG SECONDARY SIDE STRUT CARDAN						Component	ATA:32
PN:2309-2618-001	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT	
SN:1122821/058	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853	60000	TSN 4853	60000		53975		
PROC. REF: AMM 32-10-11	PROC. REF: AMM 32-10-11								
321004-0502		RH MLG SECONDARY SIDE STRUT CARDAN						Component	ATA:32
PN:2309-2618-001	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT	
SN:1122821/042	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853	60000	TSN 4853	60000		53975		
PROC. REF: AMM 32-10-11	PROC. REF: AMM 32-10-11								
321004-0601		LH MLG SECONDARY SIDE STRUT AXLE						Component	ATA:32
PN:2309-2621-001	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT	
SN:1136819/005	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853	60000	TSN 4853	60000		53975		
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
321004-0602		RH MLG SECONDARY SIDE STRUT AXLE						Component	ATA:32
PN:2309-2621-001	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT	
SN:1123525/009	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853	60000	TSN 4853	60000		53975		
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
321004-0701		LH MLG SECONDARY SIDE STRUT BOLT						Component	ATA:32
PN:2309-2626-001	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT	
SN:1140062/006	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853	60000	TSN 4853	60000		53975		
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
321004-0702		RH MLG SECONDARY SIDE STRUT BOLT						Component	ATA:32
PN:2309-2626-001	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT	
SN:1124607/049	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853	60000	TSN 4853	60000		53975		
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
321004-0801		LH MLG SECONDARY SIDE STRUT PIVOT PIN						Component	ATA:32
PN:2309-2613-001	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT	
SN:1150116/005	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853	60000	TSN 4853	60000		53975		
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
321004-0802		RH MLG SECONDARY SIDE STRUT PIVOT PIN						Component	ATA:32
PN:2309-2613-001	MOS	06-Jul-19		TSO 0				LIFE LIMIT	
SN:1134738/004	HRS	9057.4		TSO 0					
	AFL	4853	60000	TSN 4853	60000		53975		
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
321004-0901		LH MLG SECONDARY SIDE STRUT NO.1 SPRING						Component	ATA:32
PN:2309-2651-005	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT	
SN:1153614/030	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853	60000	TSN 4853	60000		53975		
PROC. REF: AMM 32-10-05	PROC. REF: AMM 32-10-05								
321004-0902		LH MLG SECONDARY SIDE STRUT NO.2 SPRING						Component	ATA:32
PN:2309-2651-005	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT	
SN:1153614/025	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853	60000	TSN 4853	60000		53975		
PROC. REF: AMM 32-10-05	PROC. REF: AMM 32-10-05								
321004-0903		RH MLG SECONDARY SIDE STRUT NO.1 SPRING						Component	ATA:32
PN:2309-2651-005	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT	
SN:1148690/013	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853	60000	TSN 4853	60000		53975		
PROC. REF: AMM 32-10-05	PROC. REF: AMM 32-10-05								
321004-0904		RH MLG SECONDARY SIDE STRUT NO.2 SPRING						Component	ATA:32
PN:2309-2651-005	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT	
SN:1148690/012	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853	60000	TSN 4853	60000		53975		
PROC. REF: AMM 32-10-05	PROC. REF: AMM 32-10-05								

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
321005-0101		LH WHEEL (MLG) (LEG STRUT) AXLE							Component ATA:32
PN:2309-3040-001	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT	
SN:1138050/002	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853	60000	TSN 4853	60000		53975		
PROC. REF: AMM 32-49-02PROC. REF: AMM 32-49-02									
321005-0102		RH WHEEL (MLG) (LEG STRUT) AXLE							Component ATA:32
PN:2309-3040-001	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT	
SN:1106882/002	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853	60000	TSN 4853	60000		53975		
PROC. REF: AMM 32-49-02PROC. REF: AMM 32-49-02									
321005-0501		LH MLG SECONDARY SIDE STRUT NO.1 SPRING CARTRIDGE ASSY							Component ATA:32
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
321005-0502		LH MLG SECONDARY SIDE STRUT NO.2 SPRING CARTRIDGE ASSY							Component ATA:32
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
321005-0503		RH MLG SECONDARY SIDE STRUT NO.1 SPRING CARTRIDGE ASSY							Component ATA:32
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
321005-0504		RH MLG SECONDARY SIDE STRUT NO.2 SPRING CARTRIDGE ASSY							Component ATA:32
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
321006-0101		LH (MLG) (LEG STRUT) CARDAN JOINT							Component ATA:32
PN:2309-2048-005	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT	
SN:1140614/008	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853	60000	TSN 4853	60000		53975		
PROC. REF: AMM 32-10-10PROC. REF: AMM 32-10-10									
321006-0102		RH (MLG) (LEG STRUT) CARDAN JOINT							Component ATA:32
PN:2309-2048-005	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT	
SN:1121551/003	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853	60000	TSN 4853	60000		53975		
PROC. REF: AMM 32-10-10PROC. REF: AMM 32-10-10									
321007-0101		LH (MLG) LINEAR HYDRAULIC (MANEUVERING ACTUATOR) ACTUATOR							Component ATA:32
PN:2309-3700-503	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:01561	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									
321007-0102		RH (MLG) LINEAR HYDRAULIC (MANEUVERING ACTUATOR) ACTUATOR							Component ATA:32
PN:2309-3700-503	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:01538	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									
321007-0201		LH MANEUVERING ACTUATOR (MLG) CYLINDER							Component ATA:32
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									
321007-0202		RH MANEUVERING ACTUATOR (MLG) CYLINDER							Component ATA:32
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
321007-0301	LH MANEUVERING ACTUATOR (MLG) ROD END							Component	ATA:32
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									
321007-0302	RH MANEUVERING ACTUATOR (MLG) ROD END							Component	ATA:32
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									
321007-0401	LH MANEUVERING ACTUATOR ROD (MLG) PISTON							Component	ATA:32
PN:2309-3710-001	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:1140770/001	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									
321007-0402	RH MANEUVERING ACTUATOR ROD (MLG) PISTON							Component	ATA:32
PN:2309-3710-001	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:1132492/001	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									
321007-0501	LH MANEUVERING ACTUATOR BEARING (MLG) CAP							Component	ATA:32
PN:2309-3712-001	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:1159163/002	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									
321007-0502	RH MANEUVERING ACTUATOR BEARING (MLG) CAP							Component	ATA:32
PN:2309-3712-001	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:1133951/010	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
322000-0101		LEG -NOSE LANDING GEAR ASSEMBLY							Component ATA:32
PN:2233A0000-02	MOS	06-Jul-19		TSN 143, TSO 0				SCRAP	
SN:02303	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853	60000	TSN 4853	60000		53975		
PROC. REF: AMM 32-20-01	PROC. REF: AMM 32-20-01								
322000-0201		NLG LEG STRUT SLIDING TUBE							Component ATA:32
PN:2233-0201	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT	
SN:1379	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853	60000	TSN 4853	60000		53975		
PROC. REF: AMM 32-20-08	PROC. REF: AMM 32-20-08								
322000-0301		NLG LEG STRUT WHEEL AXLE							Component ATA:32
PN:2233-0202	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT	
SN:L219	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853	60000	TSN 4853	60000		53975		
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
322000-0401		NLG LEG STRUT STEERING CUFF							Component ATA:32
PN:1170-2301	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT	
SN:L1578	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853	60000	TSN 4853	60000		53975		
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
322000-0501		NO.1 NLG LEG STRUT TORQUE LINK							Component ATA:32
PN:1170-0301	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT	
SN:L2583	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853	60000	TSN 4853	60000		53975		
PROC. REF: AMM 32-20-10	PROC. REF: AMM 32-20-10								
322000-0502		NO.2 NLG LEG STRUT TORQUE LINK							Component ATA:32
PN:1170-0301	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT	
SN:L2584	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853	60000	TSN 4853	60000		53975		
PROC. REF: AMM 32-20-10	PROC. REF: AMM 32-20-10								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
322000-0601		NO.1 NLG LEG STRUT TORQUE LINK PIN						Component	ATA:32
PN:1170-0001	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT	
SN:L1843	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853	60000	TSN 4853	60000		53975		
PROC. REF: AMM 32-20-10	PROC. REF: AMM 32-20-10								
322000-0602		NO.2 NLG LEG STRUT TORQUE LINK PIN						Component	ATA:32
PN:1170-0001	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT	
SN:L2625	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853	60000	TSN 4853	60000		53975		
PROC. REF: AMM 32-20-10	PROC. REF: AMM 32-20-10								
322000-0701		NLG LEG STRUT TORQUE LINK CENTRAL BOLT						Component	ATA:32
PN:1170-0002	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT	
SN:L1337	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853	60000	TSN 4853	60000		53975		
PROC. REF: AMM 32-20-10	PROC. REF: AMM 32-20-10								
322000-0801		NLG LEG STRUT MAIN FITTING						Component	ATA:32
PN:2233-0103	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT	
SN:L572	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853	60000	TSN 4853	60000		53975		
PROC. REF: AMM 32-20-01	PROC. REF: AMM 32-20-01								
322000-0901		(NLG) MAIN DRAG STRUT ATTACHMENT PIN						Component	ATA:32
PN:1170-0070	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT	
SN:L1490	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853	60000	TSN 4853	60000		53975		
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
322000-1101		NO. 1 NLG LEG STRUT PINTLE PIN						Component	ATA:32
PN:1170-0032	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT	
SN:L3045	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853	60000	TSN 4853	60000		53975		
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
322000-1102		NO. 2 NLG LEG STRUT PINTLE PIN							Component ATA:32
PN:1170-0032	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT	
SN:L3046	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853	60000	TSN 4853	60000		53975		
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									
322000-1201		(NLG) LEG STRUT ACTUATOR ATTACHMENT BOLT PIN							Component ATA:32
PN:1170-0071	MOS	27-Aug-07		TSN 0				LIFE LIMIT	
SN:L1445	HRS	0		TSN 0					
	AFL	0	60000	TSN 0	60000		53975		
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									
322000-1301		NLG LEG STRUT SET - SCREW							Component ATA:32
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									
322000-1302		NLG LEG STRUT SET - SCREW							Component ATA:32
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									
322000-1401		NLG LEG STRUT - RACK							Component ATA:32
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									
322000-1501		NLG LEG STRUT - PINION							Component ATA:32
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
322000-1601	NLG LEG STRUT CYLINDER - HOUSING							Component	ATA:32
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
322000-1602	NLG LEG STRUT CYLINDER - HOUSING							Component	ATA:32
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
322001-0101	TOP NLG MAIN DRAG STRUT STAY							Component	ATA:32
PN:1172A0600-01	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT	
SN:HM1431	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853	60000	TSN 4853	60000		53975		
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
322001-0201	BOTTOM NLG MAIN DRAG STRUT STAY							Component	ATA:32
PN:1172A0200-01	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT	
SN:HM39	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853	60000	TSN 4853	60000		53975		
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
322001-0301	NO.1 NLG MAIN DRAG STRUT PINTLE PIN							Component	ATA:32
PN:1172-0037	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT	
SN:L359	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853	60000	TSN 4853	60000		53975		
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
322001-0302	NO.2 NLG MAIN DRAG STRUT PINTLE PIN							Component	ATA:32
PN:1172-0037	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT	
SN:L358	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853	60000	TSN 4853	60000		53975		
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
322001-0401		NLG MAIN DRAG STRUT HINGE POINT BOLT							Component ATA:32
PN:1172-0001	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT	
SN:HM241	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853	60000	TSN 4853	60000		53975		
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
322001-0501		NLG MAIN DRAG STRUT ACTUATOR ATTACHMENT PIN							Component ATA:32
PN:1172-0066	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:HM075	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
322001-0601		NLG MAIN DRAG STRUT ASSEMBLY							Component ATA:32
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
322002-0101		NLG ROD -MAIN LOCKING,NOSE LANDING GEAR ASSEMBLY							Component ATA:32
PN:1172C0000-02	MOS/MSC	06-Jul-19	O/C	TSN 143, TSO 0					
SN:02086	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853		TSN 4853					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
322003-0101		NLG AUXILIARY DRAG STRUT							Component ATA:32
PN:1173B0000-03	MOS/MSC	06-Jul-19	O/C	TSN 143, TSO 0					
SN:02115	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853		TSN 4853, TSO 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
322004-0101		NLG AUXILIARY DRAG STRUT (UPPER)							Component ATA:32
PN:1173A0200-01	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT	
SN:HM1191	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853	60000	TSN 4853	60000		53975		
PROC. REF: AMM 32-20-09	PROC. REF: AMM 32-20-09								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
322004-0201		NLG AUXILIARY DRAG STRUT (LOWER)							Component ATA:32
PN:1173A0100-02	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT	
SN:L1327	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853	60000	TSN 4853	60000		53975		
PROC. REF: AMM 32-20-09	PROC. REF: AMM 32-20-09								
322004-0301		NO. 1 NLG AUXILIARY DRAG STRUT HINGE POINT BOLT							Component ATA:32
PN:1173-0001	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT	
SN:HM120	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853	60000	TSN 4853	60000		53975		
PROC. REF: AMM 32-20-03	PROC. REF: AMM 32-20-03								
322004-0302		NLG UNLOCKING ACTUATOR BOLT							Component ATA:32
PN:1173-0024	MOS/MSC	06-Jul-19	O/C	TSN 143, TSO 0					
SN:HM01P	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853		TSN 4853, TSO 0					
PROC. REF: AMM 32-20-03	PROC. REF: AMM 32-20-03								
322004-0401		NLG AUXILIARY DRAG STRUT (JOINT ATTACHING PARTS) CARDAN							Component ATA:32
PN:KSL 113608V	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT	
SN:4184-KC1296	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853	60000	TSN 4853	60000		53975		
PROC. REF: AMM 32-20-09	PROC. REF: AMM 32-20-09								
322004-0501		NO. 1 NLG AUXILIARY DRAG STRUT SLEEVE							Component ATA:32
PN:1173-0011	MOS/MSC	06-Jul-19	O/C	TSN 143, TSO 0					
SN:HM01P	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853		TSN 4853, TSO 0					
PROC. REF: AMM 32-20-03	PROC. REF: AMM 32-20-03								
322004-0502		NO. 2 NLG AUXILIARY DRAG STRUT SLEEVE							Component ATA:32
PN:1173-0011	MOS/MSC	06-Jul-19	O/C	TSN 143, TSO 0					
SN:HM01P	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853		TSN 4853, TSO 0					
PROC. REF: AMM 32-20-03	PROC. REF: AMM 32-20-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
322004-0601		NO. 1 NLG AUXILIARY DRAG STRUT DOWNLOCK SPRING							Component ATA:32
PN:1173A0700-01	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT	
SN:064215HM	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853	60000	TSN 4853	60000		53975		
PROC. REF: AMM 32-20-03	PROC. REF: AMM 32-20-03								
322004-0602		NO. 2 NLG AUXILIARY DRAG STRUT DOWNLOCK SPRING							Component ATA:32
PN:1173A0700-01	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT	
SN:064216HM	HRS	9057.4		TSN 9057.4, TSO 0					
	AFL	4853	60000	TSN 4853	60000		53975		
PROC. REF: AMM 32-20-03	PROC. REF: AMM 32-20-03								
322005-0101		NO. 1 NLG - NOSE LANDING GEAR DOOR ASSEMBLY							Component ATA:32
PN:135-18799-401	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:0000127632	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-20-05	PROC. REF: AMM 32-20-05								
322005-0102		NO.2 NLG - NOSE LANDING GEAR DOOR ASSEMBLY							Component ATA:32
PN:135-18799-402	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:0000127641	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-20-05	PROC. REF: AMM 32-20-05								
323201-0101		CSL CENT LANDING GEAR ELECTRONIC UNIT							Component ATA:32
PN:355-022-003	MOS/MSC	17-Jun-11	O/C						
SN:5105	HRS	4739.5							
	AFL	2487							
PROC. REF: AMM 32-32-01	PROC. REF: AMM 32-32-01								
323202-0101		CSL CENT CONTROL,LANDING GEAR,MAIN PANEL LEVER							Component ATA:32
PN:7-45550-3	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:1203	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-32-02	PROC. REF: AMM 32-32-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
323301-0101	MID FREE-FALL SELECTOR VALVE							Component	ATA:32
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-33-01	PROC. REF: AMM 32-33-01								
323302-0101	MID SOLENOID 4 WASYS, 2 POS VALVE							Component	ATA:32
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-33-02	PROC. REF: AMM 32-33-02								
323303-0101	NOSE ACTUATOR, HYDRAULIC -DOOR, NOSE LANDING GEAR ASSEMBLY							Component	ATA:32
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-33-03	PROC. REF: AMM 32-33-03								
323303-0102	NOSE ACTUATOR, HYDRAULIC -DOOR, NOSE LANDING GEAR ASSEMBLY							Component	ATA:32
PN:2118-0100-401	MOS/MSC	13-Mar-15	O/C	TSR 2					
SN:1732	HRS	7353.5		TSR 0					
	AFL			TSR 0					
PROC. REF: AMM 32-33-03	PROC. REF: AMM 32-33-03								
323303-0201	NLG DOOR ACTUATOR							Component	ATA:32
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-33-03	PROC. REF: AMM 32-33-03								
323304-0101	MID SOLENOID 4 WAY, 3 POS, VALVE							Component	ATA:32
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-33-04	PROC. REF: AMM 32-33-04								

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
323305-0101	NLG MANEUVERING ACTUATOR							Component	ATA:32
PN:1300B0000-02	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:02085	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-33-05	PROC. REF: AMM 32-33-05								
323305-0201	NLG MANEUVERING ACTUATOR CYLINDER							Component	ATA:32
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-33-05	PROC. REF: AMM 32-33-05								
323305-0301	NLG MANEUVERING ACTUATOR PISTON ROD							Component	ATA:32
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-33-05	PROC. REF: AMM 32-33-05								
323306-0101	NLG ACTUATOR -HYDRAULIC,UNLOCKING, NLG ASSEMBLY							Component	ATA:32
PN:1175B0000-01	MOS/MSC	27-Aug-07	O/C						
SN:02015	HRS	0							
	AFL	0		TSN 0					
PROC. REF: AMM 32-33-06	PROC. REF: AMM 32-33-06								
323307-0101	NLG BOX UP LOCK -HYDRAULIC SYS,AUXILIARY LANDING GEAR ASSEMBLY							Component	ATA:32
PN:2309-2900-401	MOS/MSC	27-Aug-07	O/C						
SN:03163	HRS	0							
	AFL	0		TSN 0					
PROC. REF: AMM 32-33-07	PROC. REF: AMM 32-33-07								
323307-0102	LH LDG BOX UP LOCK -HYDRAULIC SYS,AUXILIARY LANDING GEAR ASSEMBLY							Component	ATA:32
PN:2309-2900-401	MOS/MSC	27-Aug-07	O/C						
SN:03157	HRS	0							
	AFL	0		TSN 0					
PROC. REF: AMM 32-33-07	PROC. REF: AMM 32-33-07								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
323307-0103		RH LDG BOX UP LOCK -HYDRAULIC SYS,AUXILIARY LANDING GEAR ASSEMBLY						Component	ATA:32
PN:2309-2900-401	MOS/MSC	27-Aug-07	O/C						
SN:03100	HRS	0							
	AFL	0		TSN 0					
PROC. REF: AMM 32-33-07PROC. REF: AMM 32-33-07									
323309-0101		LH LDG UNLOCKING ACTUATOR ASSEMBLY						Component	ATA:32
PN:2309-2800-505	MOS/MSC	27-Aug-07	O/C						
SN:02114	HRS	0							
	AFL	0		TSN 0					
PROC. REF: AMM 32-33-09PROC. REF: AMM 32-33-09									
323309-0102		RH LDG UNLOCKING ACTUATOR ASSEMBLY						Component	ATA:32
PN:2309-2800-505	MOS/MSC	27-Aug-07	O/C						
SN:02085	HRS	0							
	AFL	0		TSN 0					
PROC. REF: AMM 32-33-09PROC. REF: AMM 32-33-09									
323311-0101		MID CHECK ASSY-HYDRAULIC SYS, FWD FUSLG VALVE						Component	ATA:32
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-33-11PROC. REF: AMM 32-33-11									
323311-0102		STUB CHECK ASSY-HYDRAULIC SYS, FWD FUSLG VALVE						Component	ATA:32
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-33-11PROC. REF: AMM 32-33-11									
323311-0103		RH RACK CHECK ASSY-HYDRAULIC SYS, FWD FUSLG VALVE						Component	ATA:32
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-33-11PROC. REF: AMM 32-33-11									

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
323312-0101		MID RESTRICTOR, HYDRAULIC SYS, SSTEEL VALVE						Component	ATA:32
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-33-12PROC. REF: AMM 32-33-12									
323315-0101		MID HYDRAULIC ACCUMULATOR						Component	ATA:32
PN:0860202001	MOS/MSC	19-Sep-13	O/C	TSN 25					
SN:602002-2226NA	HRS	6680.2		TSN 0					
	AFL	3597		TSN 0					
PROC. REF: AMM 32-33-15PROC. REF: AMM 32-33-15									
323315-0701 U		LANDING GEAR HYDRAULIC ACCUMULATOR DRAIN VALVE						Component	ATA:32
PN:HV50-61	MOS/MSC	21-Jan-22	O/C						
SN:80206103	HRS	9789.3							
	AFL	5205							
323316-0101		MID ONE-WAY RESTRICTOR VALVE						Component	ATA:32
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-33-12PROC. REF: AMM 32-33-12									
323319-0101		MID DRAIN-MANUAL, HYDRAULIC SYS, FWD/CTL FUSLG VALVE						Component	ATA:32
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									
323319-0102		HYD SYST DRAIN-MANUAL, HYDRAULIC SYS, FWD/CTL FUSLG VALVE						Component	ATA:32
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
323319-0103		MID DRAIN-MANUAL, HYDRAULIC SYS, FWD/CTL FUSLG VALVE						Component	ATA:32
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
324101-0201		LH PIL PEDAL,RUDDER CONTROL,FWD FUSLG TRANSDUCER						Component	ATA:32
PN:20-017500	MOS/MSC	28-Nov-08	O/C						
SN:764778	HRS	1511.4							
	AFL	802							
PROC. REF: AMM 32-41-01	PROC. REF: AMM 32-41-01								
324101-0202		LH COPIL PEDAL,RUDDER CONTROL,FWD FUSLG TRANSDUCER						Component	ATA:32
PN:20-017500	MOS/MSC	28-Nov-08	O/C						
SN:773635	HRS	1511.4							
	AFL	802							
PROC. REF: AMM 32-41-01	PROC. REF: AMM 32-41-01								
324101-0203		RH PIL PEDAL, RUDDER CONTROL,FWD FUSLG TRANSDUCER						Component	ATA:32
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-01	PROC. REF: AMM 32-41-01								
324101-0204		RH COPIL PEDAL,RUDDER CONTROL,FWD FUSLG TRANSDUCER						Component	ATA:32
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-01	PROC. REF: AMM 32-41-01								
324102-0101		C FLOOR CONTROL ASSY,BS,BRAKE SYS,COCKPIT BOX						Component	ATA:32
PN:142-093 REV A	MOS/MSC	11-Oct-08	O/C						
SN:442	HRS	1392.8							
	AFL	744							
PROC. REF: AMM 32-41-02	PROC. REF: AMM 32-41-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
324103-0101	LEFT NO. 1 WHEEL SPEED OUTBOARD TRANSDUCER							Component	ATA:32
PN:140-197	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-03	PROC. REF: AMM 32-41-03								
324103-0102	LEFT NO. 2 WHEEL SPEED INBOARD TRANSDUCER							Component	ATA:32
PN:140-197	MOS/MSC	08-Oct-08	O/C	TSO 0					
SN:1678	HRS	1378.1		TSO 0					
	AFL	736		TSO 0					
PROC. REF: AMM 32-41-03	PROC. REF: AMM 32-41-03								
324103-0103	RIGHT NO.3 WHEEL SPEED INBOARD TRANSDUCER							Component	ATA:32
PN:140-197	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-03	PROC. REF: AMM 32-41-03								
324103-0104	RIGHT NO.4 WHEEL SPEED OUTBOARD TRANSDUCER							Component	ATA:32
PN:140-197	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-03	PROC. REF: AMM 32-41-03								
324104-0101	LEFT PRESSURE SWITCH							Component	ATA:32
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-04	PROC. REF: AMM 32-41-04								
324104-0102	RIGHT PRESSURE SWITCH							Component	ATA:32
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-04	PROC. REF: AMM 32-41-04								

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
324105-0101	LH WING SHUTOFF,BRAKE VALVE							Component	ATA:32
PN:38-793500	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:2092	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-05	PROC. REF: AMM 32-41-05								
324105-0102	RH WING SHUTOFF,BRAKE VALVE							Component	ATA:32
PN:38-793500	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:2195	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-05	PROC. REF: AMM 32-41-05								
324106-0101	LH WING BRAKE CONTROL VALVE							Component	ATA:32
PN:39-807	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:2256	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-06	PROC. REF: AMM 32-41-06								
324106-0102	RH WING BRAKE CONTROL VALVE							Component	ATA:32
PN:39-807	MOS/MSC	08-Nov-08	O/C						
SN:402	HRS	1467							
	AFL	779							
PROC. REF: AMM 32-41-06	PROC. REF: AMM 32-41-06								
324107-0101	LH WING FUSE							Component	ATA:32
PN:38-791500	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-07	PROC. REF: AMM 32-41-07								
324107-0102	LH WING FUSE							Component	ATA:32
PN:38-791500	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-07	PROC. REF: AMM 32-41-07								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
324107-0201	RH WING FUSE							Component	ATA:32
PN:38-791500	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-07	PROC. REF: AMM 32-41-07								
324107-0202	RH WING FUSE							Component	ATA:32
PN:38-791500	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-07	PROC. REF: AMM 32-41-07								
324108-0201	LH WING PRESSURE-LANDING GEAR TRANSDUCER							Component	ATA:32
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-08	PROC. REF: AMM 32-41-08								
324108-0202	RH WING PRESSURE-LANDING GEAR TRANSDUCER							Component	ATA:32
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-08	PROC. REF: AMM 32-41-08								
324108-0203	LH WING PRESSURE-LANDING GEAR TRANSDUCER							Component	ATA:32
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-08	PROC. REF: AMM 32-41-08								
324108-0204	RH WING PRESSURE-LANDING GEAR TRANSDUCER							Component	ATA:32
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-08	PROC. REF: AMM 32-41-08								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
324109-0101	W STUB CHECK ASSY-HYDRAULIC SYS, FWD FUSLG VALVE							Component	ATA:32
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-09PROC. REF: AMM 32-41-09									
324109-0102	W STUB CHECK ASSY-HYDRAULIC SYS, FWD FUSLG VALVE							Component	ATA:32
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-09PROC. REF: AMM 32-41-09									
324109-0103	MID CHECK ASSY-HYDRAULIC SYS, FWD FUSLG VALVE							Component	ATA:32
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-09PROC. REF: AMM 32-41-09									
324401-0101	HYD SYST EMERGENCY PARKING BRAKE VALVE							Component	ATA:32
PN:9067-40-4	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:1216	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-44-01PROC. REF: AMM 32-44-01									
324402-0101	EMERGENCY PARKING BRAKE HYDRAULIC ACCUMULATOR							Component	ATA:32
PN:088424002	MOS/MSC	03-Nov-07	O/C						
SN:8424-16128	HRS	167.3							
	AFL	85							
PROC. REF: AMM 32-44-02PROC. REF: AMM 32-44-02									
324402-0102	FUS WING ACCUMULATOR, HYDRAULIC, PISTON ACCUMULATOR							Component	ATA:32
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-44-02PROC. REF: AMM 32-44-02									

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
324405-0101	HYD SYST PRESSURE SWITCH							Component	ATA:32
PN:15782-101	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:0600	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-44-05	PROC. REF: AMM 32-44-05								
324406-0101	MID THERMAL RELIEF ASSY, VALVE							Component	ATA:32
PN:2228-0001-005	MOS/MSC	27-Jul-15	O/C	TSR 8					
SN:02430	HRS	7460.3		TSR 0					
	AFL	3992		TSR 0					
PROC. REF: AMM 32-44-06	PROC. REF: AMM 32-44-06								
324406-0102	RH RACK THERMAL RELIEF ASSY, VALVE							Component	ATA:32
PN:2228-0001-005	MOS/MSC	15-Aug-13	O/C	TSN 24					
SN:02537	HRS	6643.4		TSN 1823.3					
	AFL	3572		TSN 1026					
PROC. REF: AMM 32-44-06	PROC. REF: AMM 32-44-06								
324407-0101	LH WING PRESSURE-PARKING BRAKE SYS SWITCH							Component	ATA:32
PN:15851	MOS/MSC	19-Mar-15	O/C	TSN 0					
SN:1666	HRS	7359.8		TSN 0					
	AFL	3939		TSN 0					
PROC. REF: AMM 32-44-07	PROC. REF: AMM 32-44-07								
324701-0201	LH LDG INDICATOR,BRAKE TEMPERATURE SENSOR							Component	ATA:32
PN:0132AEV-3	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-47-01	PROC. REF: AMM 32-47-01								
324701-0202	LH LDG INDICATOR,BRAKE TEMPERATURE SENSOR							Component	ATA:32
PN:0132AEV-3	MOS/MSC	07-Jul-11	O/C	TSN 0					
SN:K1985	HRS	4802.9		TSN 0					
	AFL	2530		TSN 0					
PROC. REF: AMM 32-47-01	PROC. REF: AMM 32-47-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
324701-0203		RH LDG INDICATOR,BRAKE TEMPERATURE SENSOR						Component	ATA:32
PN:0132AEV-3	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-47-01PROC. REF: AMM 32-47-01									
324701-0204		RH LDG INDICATOR,BRAKE TEMPERATURE SENSOR						Component	ATA:32
PN:0132AEV-3	MOS/MSC	25-Mar-11	O/C	TSN 0					
SN:K0535	HRS	4423.8		TSN 0					
	AFL	2322		TSN 0					
PROC. REF: AMM 32-47-01PROC. REF: AMM 32-47-01									
324702-0201		LEFT SIGNAL-BRAKE TEMPERATURE,WING STUB CONDITIONER						Component	ATA:32
PN:0510GW2	MOS/MSC		O/C						
SN:2089	HRS								
	AFL	0							
PROC. REF: AMM 32-47-02PROC. REF: AMM 32-47-02									
324702-0202		RIGHT SIGNAL-BRAKE TEMPERATURE,WING STUB CONDITIONER						Component	ATA:32
PN:0510GW2	MOS/MSC		O/C						
SN:2109	HRS								
	AFL	0							
PROC. REF: AMM 32-47-02PROC. REF: AMM 32-47-02									
324900-0001		LEFT NO.1 MAIN LANDING GEAR OUTBOARD WHEEL AND TIRE ASSEMBLY						Component	ATA:32
PN:2309-2003-403	MOS/MSC	11-Aug-25	O/C						
SN:3642	HRS	10856.2							
	AFL	5786							
PROC. REF: AMM 32-49-01PROC. REF: AMM 32-49-01									
324900-0002		LEFT NO. 2 MAIN LANDING GEAR INBOARD WHEEL AND TIRE ASSEMBLY						Component	ATA:32
PN:2309-2003-401	MOS/MSC	15-Jan-26	O/C						
SN:2445	HRS	11060.9							
	AFL	5907							
PROC. REF: AMM 32-49-01PROC. REF: AMM 32-49-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
324900-0003	RIGHT NO. 3 MAIN LANDING GEAR INBOARD WHEEL AND TIRE ASSEMBLY							Component	ATA:32
PN:2309-2003-401	MOS/MSC	15-Jan-26	O/C						
SN:2861	HRS	11060.9							
	AFL	5907							
PROC. REF: AMM 32-49-01	PROC. REF: AMM 32-49-01								
324900-0004	RIGHT NO. 4 MAIN LANDING GEAR OUTBOARD WHEEL AND TIRE ASSEMBLY							Component	ATA:32
PN:2309-2003-403	MOS/MSC	09-Apr-26	O/C						
SN:2912	HRS	11166.4							
	AFL	5961							
PROC. REF: AMM 32-49-01	PROC. REF: AMM 32-49-01								
324900-0101	LEFT NO. 1 MAIN LANDING GEAR OUTBOARD WHEEL ASSEMBLY							Component	ATA:32
PN:3-1550-1	MOS/MSC	10-Jan-24	O/C						
SN:3642	HRS	10396.8							
	AFL	5532							
PROC. REF: AMM 32-49-02	PROC. REF: AMM 32-49-02								
324900-0102	LEFT NO. 2 MAIN LANDING GEAR INBOARD WHEEL ASSEMBLY							Component	ATA:32
PN:3-1550-1	MOS/MSC	18-Dec-24	O/C						
SN:2061	HRS	10607.9							
	AFL	5654							
PROC. REF: AMM 32-49-02	PROC. REF: AMM 32-49-02								
324900-0103	RIGHT NO. 3 MAIN LANDING GEAR INBOARD WHEEL ASSEMBLY							Component	ATA:32
PN:3-1550-1	MOS/MSC	18-Dec-24	O/C						
SN:2912	HRS	10607.9							
	AFL	5654							
PROC. REF: AMM 32-49-02	PROC. REF: AMM 32-49-02								
324900-0104	RIGHT NO. 4 MAIN LANDING GEAR OUTBOARD WHEEL ASSEMBLY							Component	ATA:32
PN:3-1550-1	MOS/MSC	09-Apr-26	O/C						
SN:2912	HRS	11166.4							
	AFL	5961							
PROC. REF: AMM 32-49-02	PROC. REF: AMM 32-49-02								

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
324900-0201		LEFT NO. 1 MAIN LANDING GEAR OUTBOARD TIRE						Component	ATA:32
PN:304K63-2	MOS/MSC	11-Aug-25	O/C	TSN 0					
SN:33485239	HRS	10856.2		TSN 0					
	AFL	5786		TSN 0					
PROC. REF: AMM 32-49-01PROC. REF: AMM 32-49-01									
324900-0202		LEFT NO. 2 MAIN LANDING GEAR INBOARD TIRE						Component	ATA:32
PN:304K63-2	MOS/MSC	15-Jan-26	O/C	TSN 0					
SN:51416228	HRS	11060.9		TSN 0					
	AFL	5907		TSN 0					
PROC. REF: AMM 32-49-01PROC. REF: AMM 32-49-01									
324900-0203		RIGHT NO. 3 MAIN LANDING GEAR INBOARD TIRE						Component	ATA:32
PN:304K63-2	MOS/MSC	15-Jan-26	O/C	TSN 0					
SN:50236243	HRS	11060.9		TSN 0					
	AFL	5907		TSN 0					
PROC. REF: AMM 32-49-01PROC. REF: AMM 32-49-01									
324900-0204		RIGHT NO. 4 MAIN LANDING GEAR OUTBOARD TIRE						Component	ATA:32
PN:304K63-2	MOS/MSC	09-Apr-26	O/C	TSN 0					
SN:51376211	HRS	11166.4		TSN 0					
	AFL	5961		TSN 0					
PROC. REF: AMM 32-49-01PROC. REF: AMM 32-49-01									
324900-0301		LH NOSE LANDING GEAR WHEEL ASSEMBLY						Component	ATA:32
PN:3-1622	MOS/MSC	12-Jul-23	O/C	TSO 0					
SN:0392	HRS	10167.3		TSO 0					
	AFL	5404		TSO 0					
PROC. REF: AMM 32-49-05PROC. REF: AMM 32-49-05									
324900-0302		RH NOSE LANDING GEAR WHEEL ASSEMBLY						Component	ATA:32
PN:3-1622	MOS/MSC	12-Jul-23	O/C	TSO 0					
SN:0518	HRS	10167.3		TSO 0					
	AFL	5404		TSO 0					
PROC. REF: AMM 32-49-05PROC. REF: AMM 32-49-05									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
324900-0401		LH NOSE LANDING GEAR TIRE						Component	ATA:32
PN:196K02B1	MOS/MSC	11-Aug-25	O/C	TSN 0					
SN:22570432	HRS	10856.2		TSN 0					
	AFL	5786		TSN 0					
PROC. REF: AMM 32-49-04	PROC. REF: AMM 32-49-04								
324900-0402		RH NOSE LANDING GEAR TIRE						Component	ATA:32
PN:196K02B1	MOS/MSC	11-Aug-25	O/C	TSN 0					
SN:22630435	HRS	10856.2		TSN 0					
	AFL	5786		TSN 0					
PROC. REF: AMM 32-49-04	PROC. REF: AMM 32-49-04								
324900-0501		LH NOSE LANDING GEAR WHEEL AND TIRE ASSEMBLY						Component	ATA:32
PN:3-1622	MOS/MSC	11-Aug-25	O/C						
SN:0841	HRS	10856.2							
	AFL	5786							
PROC. REF: AMM 32-49-05	PROC. REF: AMM 32-49-05								
324900-0502		RH NOSE LANDING GEAR WHEEL AND TIRE ASSEMBLY						Component	ATA:32
PN:3-1622	MOS/MSC	11-Aug-25	O/C						
SN:1516	HRS	10856.2							
	AFL	5786							
PROC. REF: AMM 32-49-05	PROC. REF: AMM 32-49-05								
324903-0101		NO. 1 CARBON ASSY-LEG,MAIN LANDING GEAR BRAKE						Component	ATA:32
PN:2-1582OPT5	MOS/MSC	04-Aug-12	O/C	TSN 0					
SN:2723	HRS	6092		TSN 0					
	AFL	3243		TSN 0					
PROC. REF: AMM 32-49-03	PROC. REF: AMM 32-49-03								
324903-0102		NO. 2 CARBON ASSY-LEG,MAIN LANDING GEAR BRAKE						Component	ATA:32
PN:2-1582	MOS/MSC	23-Dec-24	O/C	TSO 0					
SN:2219	HRS	10619.1		TSO 0					
	AFL	5659		TSO 0					
PROC. REF: AMM 32-49-03	PROC. REF: AMM 32-49-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
324903-0103	NO. 3 CARBON ASSY-LEG,MAIN LANDING GEAR BRAKE							Component	ATA:32
PN:2-1582	MOS/MSC	18-Aug-18	O/C	TSO 30					
SN:1968	HRS	8725.1		TSO 0					
	AFL	4681		TSO 0					
PROC. REF: AMM 32-49-03	PROC. REF: AMM 32-49-03								
324903-0104	NO. 4 CARBON ASSY-LEG,MAIN LANDING GEAR BRAKE							Component	ATA:32
PN:2-1582OPT5	MOS/MSC	25-Mar-11	O/C	TSO 0					
SN:1844	HRS	4423.8		TSO 0					
	AFL	2322		TSO 0					
PROC. REF: AMM 32-49-03	PROC. REF: AMM 32-49-03								
325001-0101	CSL CENT BOX CONTROL -STEERING, MANUAL, NOSE LANDING GEAR ASSEMBLY							Component	ATA:32
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-50-01	PROC. REF: AMM 32-50-01								
325003-0101	C FLOOR BOX ELECTRONIC-STEERING CONTROL, NOSE LANDING GEAR ASSEMBLY							Component	ATA:32
PN:308560-1019	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:1579	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-50-03	PROC. REF: AMM 32-50-03								
325004-0101	MID HYDRALIC-STEERING SYS CONTROL, NOSE LDG MODULE							Component	ATA:32
PN:308570-1011	MOS/MSC	01-Feb-19	O/C	TSR 67					
SN:1187	HRS	8932.1		TSR 0					
	AFL	4776		TSR 0					
PROC. REF: AMM 32-50-04	PROC. REF: AMM 32-50-04								
325006-0101	NLG STEERING PROXIMITY SWITCH							Component	ATA:32
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-50-06	PROC. REF: AMM 32-50-06								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
326101-0101	LH MLG UPLOCK 'A' PROXIMITY SWITCH							Component	ATA:32
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-61-01PROC. REF: AMM 32-61-01									
326101-0102	RH MLG UPLOCK 'A' PROXIMITY SWITCH							Component	ATA:32
PN:80-057-01	MOS/MSC	04-Aug-10	O/C	TSN 0					
SN:17781	HRS	3628.6		TSN 0					
	AFL	1907		TSN 0					
PROC. REF: AMM 32-61-01PROC. REF: AMM 32-61-01									
326101-0103	LH MLG UPLOCK 'B' PROXIMITY SWITCH							Component	ATA:32
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-61-01PROC. REF: AMM 32-61-01									
326101-0104	RH MLG UPLOCK 'B' PROXIMITY SWITCH							Component	ATA:32
PN:80-057-01	MOS/MSC	04-Aug-10	O/C	TSN 0					
SN:25626	HRS	3628.6		TSN 0					
	AFL	1907		TSN 0					
PROC. REF: AMM 32-61-01PROC. REF: AMM 32-61-01									
326102-0101	LH MLG DOWNLOCK 'A' PROXIMITY SWITCH							Component	ATA:32
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-61-02PROC. REF: AMM 32-61-02									
326102-0102	RH MLG DOWNLOCK 'A' PROXIMITY SWITCH							Component	ATA:32
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-61-02PROC. REF: AMM 32-61-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
326102-0103		LH MLG DOWNLOCK 'B' PROXIMITY SWITCH						Component	ATA:32
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-61-02	PROC. REF: AMM 32-61-02								
326102-0104		RH MLG DOWNLOCK 'B' PROXIMITY SWITCH						Component	ATA:32
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-61-02	PROC. REF: AMM 32-61-02								
326301-0101		LH MLG WOW #1 PROXIMITY SWITCH						Component	ATA:32
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-63-01	PROC. REF: AMM 32-63-01								
326301-0102		RH MLG WOW #1 PROXIMITY SWITCH						Component	ATA:32
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-63-01	PROC. REF: AMM 32-63-01								
326301-0103		LH MLG WOW #2 PROXIMITY SWITCH						Component	ATA:32
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-63-01	PROC. REF: AMM 32-63-01								
326301-0104		RH MLG WOW #2 PROXIMITY SWITCH						Component	ATA:32
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-63-01	PROC. REF: AMM 32-63-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
326302-0101	NLG WOW PROXIMITY SWITCH							Component	ATA:32
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-63-01	PROC. REF: AMM 32-63-01								
326303-0101	NLG SEQUENCE DOOR PROXIMITY SWITCH							Component	ATA:32
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-63-03	PROC. REF: AMM 32-63-03								
326304-0101	NLG OPEN DOOR PROXIMITY SWITCH							Component	ATA:32
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-63-04	PROC. REF: AMM 32-63-04								
326304-0102	NLG OPEN DOOR PROXIMITY SWITCH							Component	ATA:32
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-63-04	PROC. REF: AMM 32-63-04								
329500-0313	NLG PROXIMITY SWITCH							Component	ATA:32
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-50-06	PROC. REF: AMM 32-50-06								
329500-0314	NLG PROXIMITY SWITCH							Component	ATA:32
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-50-06	PROC. REF: AMM 32-50-06								

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
329500-0315		NLG PROXIMITY SWITCH						Component	ATA:32
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-50-06PROC. REF: AMM 32-50-06									
329500-0316		NLG PROXIMITY SWITCH						Component	ATA:32
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-50-06PROC. REF: AMM 32-50-06									
ATA 33 - LIGHTS									
33-12-00-710-002-A00 S		OPERATIONALLY CHECK COCKPIT PUSHBUTTON LIGHTING						Service	ATA:33
	MOS/MSC	17-Oct-25	N/A						
	HRS	10913.9							
	AFL	5820							
									PKG:5004
PROC. REF: AMM 33-12-00PROC. REF: AMM 33-12-00									
33-47-03-720-001-A00 S		FUNCTIONALLY CHECK INTENSITY OF WHITE STROBE LIGHTING SYSTEM.NOTE: THIS TASK IS APPLICABLE ONLY TO AIRCRAFT UNDER ANAC/FAA CERTIFICATIONS.						Service	ATA:33
	MOS	17-Oct-25	72 (+15d/-15d)				LOW UTILIZATION		
	HRS	10913.9	3000 (+20/-20)						
	AFL	5820	1500 (+20/-20)						
									PKG:5012
PROC. REF: AMM 33-47-03PROC. REF: AMM 33-47-03									
33-50-00-710-001-A00 S		OPERATIONALLY CHECK EMERGENCY LIGHTING SYSTEM						Service	ATA:33
	MOS	17-Oct-25	12 (+15d/-15d)				LOW UTILIZATION		
	HRS	10913.9	500 (+20/-20)						
	AFL	5820							
									PKG:5002
PROC. REF: AMM 33-50-00PROC. REF: AMM 33-50-00									

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 33 - LIGHTS									
33-50-04-720-001-A00		FUNCTIONALLY CHECK NO. 1 DLE EMERGENCY LIGHTING SYSTEM BATTERY POWER SUPPLY NOTE: IF INSTALLED NOTE: FROM THE MANUFACTURE DATE OR LAST TASK ACCOMPLISHMENT.							Service ATA:33
PN:8ES360000-00	MOS	16-Feb-26	6 (+15d/-15d)		16-Aug-26	31-Aug-26	82 d (+15)		
SN:303084	HRS	11064.1							
	AFL	5912							
PROC. REF: AMM 33-50-04	PROC. REF: AMM 33-50-04								
33-50-04-720-001-A00		FUNCTIONALLY CHECK NO. 2 DLE EMERGENCY LIGHTING SYSTEM BATTERY POWER SUPPLY NOTE: IF INSTALLED NOTE: FROM THE MANUFACTURE DATE OR LAST TASK ACCOMPLISHMENT.							Service ATA:33
PN:8ES360000-00	MOS	16-Feb-26	6 (+15d/-15d)		16-Aug-26	31-Aug-26	82 d (+15)		
SN:321029	HRS	11064.1							
	AFL	5912							
PROC. REF: AMM 33-50-04	PROC. REF: AMM 33-50-04								
33-50-04-720-001-A01		FUNCTIONALLY CHECK NO.1 EMERGENCY-NICAD,6VDC,5 AH BATTERY RADIANT OR BRUCE MODEL IF INSTALLED.							Service ATA:33
PN:8ES360000-00	MOS/MSC	01-Jul-24	N/A						
SN:303084	HRS	10503.9							
	AFL	5592							
PROC. REF: AMM 33-50-04	PROC. REF: AMM 33-50-04								
33-50-04-720-001-A01		FUNCTIONALLY CHECK NO.2 EMERGENCY-NICAD,6VDC,5 AH BATTERY RADIANT OR BRUCE MODEL IF INSTALLED.							Service ATA:33
PN:8ES360000-00	MOS/MSC	01-Jul-24	N/A						
SN:321029	HRS	10503.9							
	AFL	5592							
PROC. REF: AMM 33-50-04	PROC. REF: AMM 33-50-04								
33-51-01-720-001-A00 S		FUNCTIONALLY CHECK FLASHLIGHTS RECHARGEABLE BATTERIES (IF INSTALLED)							Service ATA:33
	MOS	17-Oct-25	12 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	500 (+20/-20)						
	AFL	5820							
									PKG:5002
PROC. REF: AMM 33-51-01	PROC. REF: AMM 33-51-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 33 - LIGHTS									
33-51-01-720-001-A01 S	FUNCTIONALLY CHECK FLASHLIGHTS NON-RECHARGEABLE BATTERIES (IF INSTALLED)								Service ATA:33
	MOS	17-Oct-25	12 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	500 (+20/-20)						
	AFL	5820							
									PKG:5002
PROC. REF: AMM 33-51-01PROC. REF: AMM 33-51-01									
33-51-03-960-001-A00	DISCARD NON RECHARGEABLE FLASHLIGHT BATTERY PACK NOTE: IF INSTALLED								Service ATA:33
	MOS	17-Oct-25	24 (+30d/-30d)	Adj -84d	25-Jul-27	24-Aug-27	425 d (+30)	SYSTEM	
	HRS	10913.9							
	AFL	5820							
PROC. REF: AMM 33-51-01PROC. REF: AMM 33-51-01									
330000-0101	OVERH P MODULE -INTERNAL LT CONT ASSEMBLY								Component ATA:33
PN:145-32843-405	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:0000137145	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									
330000-0201	OVERH P MODULE -EXT/CKPT/PAX LT CONTROL ASSEMBLY								Component ATA:33
PN:145-21338-401	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:0000139956	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									
330000-0301	OVERH P CONTROL ASSY-EXTERNAL NAVIGATION LIGHT,COCKPIT MODULE								Component ATA:33
PN:145-21335-401	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:0000140789	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									
330000-0401	OVERH P CONTROL ASSY-OVERHEAD PANEL EXTERNAL LIGHT,LDG,COCKPIT MODULE								Component ATA:33
PN:145-21332-401	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:0000139852	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 33 - LIGHTS									
331100-0101		CREW CAB LIGHT READING,COCKPIT CEILING ASSEMBLY						Component	ATA:33
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-11-04	PROC. REF: AMM 33-11-04								
331100-0102		CREW CAB LIGHT READING,COCKPIT CEILING ASSEMBLY						Component	ATA:33
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-11-04	PROC. REF: AMM 33-11-04								
331100-0103		CREW CAB LIGHT READING,COCKPIT CEILING ASSEMBLY						Component	ATA:33
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-11-04	PROC. REF: AMM 33-11-04								
331202-0101		NOSE DIMMER						Component	ATA:33
PN:1826-1	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-12-01	PROC. REF: AMM 33-12-01								
331202-0102		NOSE DIMMER						Component	ATA:33
PN:1826-1	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-12-01	PROC. REF: AMM 33-12-01								
331202-0103		NOSE DIMMER						Component	ATA:33
PN:1826-1	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-12-01	PROC. REF: AMM 33-12-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 33 - LIGHTS									
331202-0104	NOSE DIMMER							Component	ATA:33
PN:1826-1	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-12-01PROC. REF: AMM 33-12-01									
331202-0105	NOSE DIMMER							Component	ATA:33
PN:1826-1	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-12-01PROC. REF: AMM 33-12-01									
331202-0106	NOSE DIMMER							Component	ATA:33
PN:1826-1	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-12-01PROC. REF: AMM 33-12-01									
331501-0101	CSL CENT PROJECTOR,GLARESHIELD CENTRAL CONSOLE,COCKPIT PANEL							Component	ATA:33
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									
331501-0102	CSL CENT PROJECTOR,GLARESHIELD CENTRAL CONSOLE,COCKPIT PANEL							Component	ATA:33
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									
331501-0103	CSL CENT PROJECTOR,GLARESHIELD CENTRAL CONSOLE,COCKPIT PANEL							Component	ATA:33
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 33 - LIGHTS									
331503-0101	LH CSL LEFT,MAIN PANEL,CTL CONSOLE INVERTER							Component	ATA:33
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-15-02	PROC. REF: AMM 33-15-02								
331503-0102	RH CSL RIGHT,MAIN PANEL,CTL CONSOLE INVERTER							Component	ATA:33
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-15-02	PROC. REF: AMM 33-15-02								
332802-0101	NO. 1 LAVATORY LIGHT BALLAST - LAMP INVERTER							Component	ATA:33
PN:189-720	MOS/MSC	29-Jun-23	O/C	TSN 0					
SN:15382	HRS	10161.5		TSN 0					
	AFL	5401		TSN 0					
PROC. REF: AMM 33-28-02	PROC. REF: AMM 33-28-02								
334502-0101	UPPER LIGHT NAVIGATION,RED STROBE LIGHT ASSEMBLY							Component	ATA:33
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-47-05	PROC. REF: AMM 33-47-05								
334503-0101	CENT FUS POWER,SUPPLY-ELECTRICAL,RED STROBE LIGHT							Component	ATA:33
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-47-02	PROC. REF: AMM 33-47-02								
334702-0101	STROBE LIGHT POWER SUPPLY							Component	ATA:33
PN:60-5096-1	MOS/MSC	11-Jul-10	O/C						
SN:3488	HRS	3539.9							
	AFL	1859							
PROC. REF: AMM 33-47-02	PROC. REF: AMM 33-47-02								

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 33 - LIGHTS									
334702-0201		LH WING STROBE LIGHT POWER SUPPLY						Component	ATA:33
PN:60-5096-1	MOS/MSC	06-Apr-23	O/C						
SN:3543	HRS	10102.6							
	AFL	5373							
PROC. REF: AMM 33-47-02	PROC. REF: AMM 33-47-02								
334702-0202		RH WING STROBE LIGHT POWER SUPPLY						Component	ATA:33
PN:60-5096-1	MOS/MSC	06-Apr-23	O/C	TSR 2					
SN:4014	HRS	10102.6		TSR 0					
	AFL	5373		TSR 0					
PROC. REF: AMM 33-47-02	PROC. REF: AMM 33-47-02								
335002-0101		NO. 1 EMERGENCY LIGHTING SYSTEM POWER SUPPLY ASSEMBLY						Component	ATA:33
PN:3400-22-10	MOS/MSC	16-Feb-26	O/C	TSN 68, TSR 38					
SN:015146	HRS	11064.1		TSN 1556.2, TSR 1005.9					
	AFL	5912		TSN 852, TSR 572					
PROC. REF: AMM 33-50-04	PROC. REF: AMM 33-50-04								
335002-0102		NO. 2 EMERGENCY LIGHTING SYSTEM POWER SUPPLY ASSEMBLY						Component	ATA:33
PN:3400-22-10	MOS/MSC	16-Feb-26	O/C	TSR 38					
SN:001186	HRS	11064.1		TSR 1005.9					
	AFL	5912		TSR 572					
PROC. REF: AMM 33-50-04	PROC. REF: AMM 33-50-04								
335004-0101		NO.1 EMERGENCY-NICAD,6VDC,5 AH BATTERY						Component	ATA:33
PN:8ES360000-00	MOS/MSC	16-Aug-24	O/C						
SN:303084	HRS	10541.4		TSN 37.5					
	AFL	5613		TSN 21					
			Manufacture Date:: 31-Jan-24						
PROC. REF: AMM 33-50-04	PROC. REF: AMM 33-50-04								
335004-0102		NO.2 EMERGENCY-NICAD,6VDC,5 AH BATTERY						Component	ATA:33
PN:8ES360000-00	MOS/MSC	16-Aug-24	O/C						
SN:321029	HRS	10541.4		TSN 37.5					
	AFL	5613		TSN 21					
			Manufacture Date:: 31-Jan-24						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 33 - LIGHTS									
PROC. REF: AMM 33-50-04PROC. REF: AMM 33-50-04									
ATA 34 - NAVIGATION									
34-01-00-720-001-A00		FUNCTIONALLY CHECK INTEGRATED STANDBY INSTRUMENT SYSTEM - ISIS							Service ATA:34
	MOS	29-Jun-23						SYSTEM	
	HRS	10161.5	5000		15161.5		3885.2		
	AFL	5401							
PROC. REF: AMM 34-01-01PROC. REF: AMM 34-01-01									
34-01-CA-200		FUNCTIONALLY CHECK INTEGRATED STANDBY INSTRUMENT SYSTEM - ISIS (PER LOCAL AUTHORITY)							Service ATA:34
	MOS	07-Jul-25	24		07-Jul-27		407 d		
	HRS	10838.8							
	AFL	5775							
PROC. REF: AMM 34-01-01PROC. REF: AMM 34-01-01									
34-13-00-610-001-A00		SERVICE (CLEANING) PITOT AND STATIC SYSTEM							Service ATA:34
	MOS	29-Jun-23	72 (+30d/-30d)		29-Jun-29	29-Jul-29	1130 d (+30)	SYSTEM	
	HRS	10161.5	8000		18161.5		6885.2		
	AFL	5401							
PROC. REF: AMM 34-13-00, FAR FAR 43 APPENDIX E, FAR FAR 91.411 / 91.217PROC. REF: AMM 34-13-00, FAR FAR 43 APPENDIX E, FAR FAR 91.411 / 91.217									
34-13-00-680-001-A00 S		SERVICE (DRAIN) PITOT LINES							Service ATA:34
	MOS	17-Oct-25	12 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	500 (+20/-20)						
	AFL	5820							
									PKG:5002
PROC. REF: AMM 34-13-00, FAR FAR 43 APPENDIX E, FAR FAR 91.411 / 91.217PROC. REF: AMM 34-13-00, FAR FAR 43 APPENDIX E, FAR FAR 91.411 / 91.217									
34-13-00-790-001-A00		FUNCTIONALLY CHECK PITOT-STATIC SYSTEM FOR LEAKAGE							Service ATA:34
	MOS	29-Jun-23						SYSTEM	
	HRS	10161.5	5000		15161.5		3885.2		
	AFL	5401							
PROC. REF: AMM 34-13-00, FAR FAR 43 APPENDIX E, FAR FAR 91.411 / 91.217PROC. REF: AMM 34-13-00, FAR FAR 43 APPENDIX E, FAR FAR 91.411 / 91.217									

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
34-13-04-280-001-A00		INSPECT (SPECIAL INSPECTION) RVSM CRITICAL REGION (SKIN) FOR WAVINESS							Service ATA:34
	MOS	29-Jun-23	48 (+30d/-30d)	Adj 7d	06-Jul-27	05-Aug-27	406 d (+30)		
	HRS	10161.5	5000		15161.5		3885.2		
	AFL	5401							
PROC. REF: AMM 34-13-04	PROC. REF: AMM 34-13-04								
34-13-04-280-002-A00		INSPECT (SPECIAL INSPECTION) STATIC PORT SURROUNDING PLATE FOR FLUSHNESS AND INTEGRITYNOTE: ONLY FOR RVSM OPERATION							Service ATA:34
	MOS	29-Jun-23	48 (+30d/-30d)	Adj 7d	06-Jul-27	05-Aug-27	406 d (+30)		
	HRS	10161.5	5000		15161.5		3885.2		
	AFL	5401							
PROC. REF: AMM 34-13-04	PROC. REF: AMM 34-13-04								
34-13-04-280-003-A00		INSPECT (SPECIAL INSPECTION) OXYGEN SERVICE PANEL FOR FLUSHNESS AND INTEGRITY (PASSENGER GASEOUS OXYGEN SYSTEM ONLY) NOTE: IF INSTALLED							Service ATA:34
	MOS	29-Jun-23	48 (+30d/-30d)	Adj 7d	06-Jul-27	05-Aug-27	406 d (+30)		
	HRS	10161.5	5000		15161.5		3885.2		
	AFL	5401							
PROC. REF: AMM 34-13-04	PROC. REF: AMM 34-13-04								
34-13-CA-201		FUNCTIONALLY CHECK PITOT-STATIC SYSTEM FOR LEAKAGE (PER LOCAL AUTHORITY)							Service ATA:34
	MOS	07-Jul-25	24		07-Jul-27		407 d		
	HRS	10838.8							
	AFL	5775							
PROC. REF: AMM 34-13-00	PROC. REF: AMM 34-13-00								
34-15-00-720-001-A00		FUNCTIONALLY CHECK NO. 1 AIR DATA COMPUTER (ADC) SYSTEM							Service ATA:34
PN:7014700-627	MOS	29-Jun-23						SYSTEM	
SN:07027821	HRS	10161.5	5000		15161.5		3885.2		
	AFL	5401							
PROC. REF: AMM 34-15-00	PROC. REF: AMM 34-15-00								
34-15-00-720-001-A00		FUNCTIONALLY CHECK NO. 2 AIR DATA COMPUTER (ADC) SYSTEM							Service ATA:34
PN:7014700-627	MOS	29-Jun-23						SYSTEM	
SN:07027816	HRS	10161.5	5000		15161.5		3885.2		
	AFL	5401							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
PROC. REF: AMM 34-15-00PROC. REF: AMM 34-15-00									
34-15-CA-200		FUNCTIONALLY CHECK NO. 1 AIR DATA COMPUTER (ADC) SYSTEM (PER LOCAL AUTHORITY)							Service ATA:34
	MOS	07-Jul-25	24		07-Jul-27		407 d		
	HRS	10838.8							
	AFL	5775							
PROC. REF: AMM 34-15-00PROC. REF: AMM 34-15-00									
34-15-CA-200		FUNCTIONALLY CHECK NO. 2 AIR DATA COMPUTER (ADC) SYSTEM (PER LOCAL AUTHORITY)							Service ATA:34
	MOS	07-Jul-25	24		07-Jul-27		407 d		
	HRS	10838.8							
	AFL	5775							
PROC. REF: AMM 34-15-00PROC. REF: AMM 34-15-00									
34-21-03-140-001-A00		RESTORE (CLEANING) AHRS FAN FILTER (NOTE: IF INSTALLED)							Service ATA:34
	MOS/MSC	30-Jun-15	N/A					SYSTEM	
	HRS	7460.3							
	AFL	3992							
PROC. REF: AMM 34-21-03PROC. REF: AMM 34-21-03									
34-25-00-720-001-A00		FUNCTIONALLY CHECK STANDBY COMPASS FOR PROPER COMPENSATION							Service ATA:34
PN:PGA1001WG	MOS/MSC	13-Oct-25	O/C						
SN:702130-02	HRS	10909.4							
	AFL	5818							
PROC. REF: AMM 34-25-00PROC. REF: AMM 34-25-00									
34-27-03-140-001-A00 S		RESTORE (CLEANING) DUAL IRS MOUNTING TRAY FAN FILTER (NOTE: IF INSTALLED).							Service ATA:34
	MOS	17-Oct-25	12 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	500 (+20/-20)						
	AFL	5820							
									PKG:5002
PROC. REF: AMM 34-27-03PROC. REF: AMM 34-27-03									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
34-41-00-710-003-A00 S		OPERATIONALLY CHECK EGPWS/WINDSHEAR							Service ATA:34
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 34-41-00PROC. REF: AMM 34-41-00									
34-52-00-720-001-A00		FUNCTIONALLY CHECK NO. 1 TRANSPONDER SYSTEM							Service ATA:34
	MOS	14-Jul-25	24 (+30d/-30d)	Adj 8d	22-Jul-27	21-Aug-27	422 d (+30)	SYSTEM	
	HRS	10838.8							
	AFL	5775							
PROC. REF: AMM 34-52-00, FAR FAR 91.217 / 91.413PROC. REF: AMM 34-52-00, FAR FAR 91.217 / 91.413									
34-52-00-720-001-A00		FUNCTIONALLY CHECK NO. 2 TRANSPONDER SYSTEM							Service ATA:34
	MOS	14-Jul-25	24 (+30d/-30d)	Adj 8d	22-Jul-27	21-Aug-27	422 d (+30)	SYSTEM	
	HRS	10838.8							
	AFL	5775							
PROC. REF: AMM 34-52-00, FAR FAR 91.217 / 91.413PROC. REF: AMM 34-52-00, FAR FAR 91.217 / 91.413									
34-63-01-720-001-A00		FUNCTIONALLY CHECK ELECTRONIC FLIGHT BAG DISPLAY UNIT (EDU), BATTERY CAPACITY. NOTE: ONLY FOR AIRCRAFT EQUIPPED WITH EFB.							Service ATA:34
	MOS/MSC	03-Jul-15	N/A						
	HRS	7460.3							
	AFL	3992							
PROC. REF: AMM 34-63-02PROC. REF: AMM 34-63-02									
340101-0101		CSL CENT CONTROL-INTEGRATED STANDBY INSTRUMENT SYS UNIT							Component ATA:34
PN:C16221GD04	MOS/MSC		O/C						
SN:C16221008390	HRS								
	AFL	0							
PROC. REF: AMM 34-01-01PROC. REF: AMM 34-01-01									
340101-0101A U		RECERTIFY CSL CENT CONTROL-INTEGRATED STANDBY INSTRUMENT SYS UNIT PER FAR 91.411							Service ATA:34
PN:C16221GD04	MOS	07-Jul-25	24		07-Jul-27		407 d	FAR	
SN:C16221008390	HRS	10838.8							
	AFL	5775							
PROC. REF: FAR FAR 91.411PROC. REF: FAR FAR 91.411									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
341300-0101	LEFT PITOT-ANEMOMETRIC SYSTEM,NICKEL TUBE							Component	ATA:34
PN:0851HU3	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:251171	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-13-01PROC. REF: AMM 34-13-01									
341300-0102	RIGHT PITOT-ANEMOMETRIC SYSTEM,NICKEL TUBE							Component	ATA:34
PN:0851HU3	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:251173	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-13-01PROC. REF: AMM 34-13-01									
341300-0201	FORWARD TUBE,PITOT STATIC-ANEMOMETRIC FWD FUSLG SYSTEM							Component	ATA:34
PN:0856NF	MOS/MSC	02-Apr-19	O/C	TSN 1					
SN:311409	HRS	8972.4		TSN 0					
	AFL	4803		TSN 0					
PROC. REF: AMM 34-13-01PROC. REF: AMM 34-13-01									
341300-0401	LEFT UP PORT,STATIC-HEATED,PRESSURIZATION 28VDC SYSTEM							Component	ATA:34
PN:ST-300-2PTH	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-13-00PROC. REF: AMM 34-13-00									
341300-0402	LEFT LW PORT,STATIC-HEATED,PRESSURIZATION 28VDC SYSTEM							Component	ATA:34
PN:ST-300-2PTH	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-13-00PROC. REF: AMM 34-13-00									
341300-0403	RIGHT UP PORT,STATIC-HEATED,PRESSURIZATION 28VDC SYSTEM							Component	ATA:34
PN:ST-300-2PTH	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-13-00PROC. REF: AMM 34-13-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
341300-0404		RIGHT LW PORT,STATIC-HEATED,PRESSURIZATION 28VDC SYSTEM							Component ATA:34
PN:ST-300-2PTH	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-13-00PROC. REF: AMM 34-13-00									
341501-0101		NO. 1 AIR DATA COMPUTER (ADC)							Component ATA:34
PN:7014700-627	MOS/MSC		O/C						
SN:07027821	HRS								
	AFL	0							
PROC. REF: AMM 34-15-01PROC. REF: AMM 34-15-01									
341501-0101B U		RECERTIFY NO.1 COMPUTER PER FAR 91.411							Service ATA:34
PN:7014700-627	MOS	07-Jul-25	24		07-Jul-27		407 d	FAR	
SN:07027821	HRS	10838.8							
	AFL	5775							
PROC. REF: FAR FAR 91.411PROC. REF: FAR FAR 91.411									
341501-0102		NO. 2 AIR DATA COMPUTER (ADC)							Component ATA:34
PN:7014700-627	MOS/MSC		O/C						
SN:07027816	HRS								
	AFL	0							
PROC. REF: AMM 34-15-01PROC. REF: AMM 34-15-01									
341501-0102B U		RECERTIFY NO.2 COMPUTER PER FAR 91.411							Service ATA:34
PN:7014700-627	MOS	07-Jul-25	24		07-Jul-27		407 d	FAR	
SN:07027816	HRS	10838.8							
	AFL	5775							
PROC. REF: FAR FAR 91.411PROC. REF: FAR FAR 91.411									
341502-0101		NOSE TOTAL TEMPERATURE SENSOR							Component ATA:34
PN:102AU1AF	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-15-03PROC. REF: AMM 34-15-03									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
341502-0102		CREW CAB TOTAL, TEMPERATURE SENSOR						Component	ATA:34
PN:102AU1AF	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-15-03PROC. REF: AMM 34-15-03									
342201-0101		EICAS DISPLAY, EICAS/PFD/MFD SYS, MAIN PANEL UNIT						Component	ATA:34
PN:7014300-901	MOS/MSC	24-Mar-23	O/C	TSN 187					
SN:0703G201	HRS	10087.9		TSN 10087.9					
	AFL	5364		TSN 5364					
PROC. REF: AMM 31-41-02PROC. REF: AMM 31-41-02									
342201-0102		MFD 1 DISPLAY, EICAS/PFD/MFD SYS, MAIN PANEL UNIT						Component	ATA:34
PN:7014300-901	MOS/MSC	28-Feb-09	O/C	TSN 0					
SN:0309C903	HRS	1849.1		TSN 0					
	AFL	966		TSN 0					
PROC. REF: AMM 31-41-02PROC. REF: AMM 31-41-02									
342201-0103		MFD 2 DISPLAY, EICAS/PFD/MFD SYS, MAIN PANEL UNIT						Component	ATA:34
PN:7014300-901	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:0703G202	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 31-41-02PROC. REF: AMM 31-41-02									
342201-0104		PFD 1 DISPLAY, EICAS/PFD/MFD SYS, MAIN PANEL UNIT						Component	ATA:34
PN:7014300-901	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:96101681	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 31-41-02PROC. REF: AMM 31-41-02									
342201-0105		PFD 2 DISPLAY, EICAS/PFD/MFD SYS, MAIN PANEL UNIT						Component	ATA:34
PN:7014300-901	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:0703G205	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 31-41-02PROC. REF: AMM 31-41-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
342202-0101		CONTROL-PFD SYS, MAIN PANEL						Component	ATA:34
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-22-02	PROC. REF: AMM 34-22-02								
342202-0102		CONTROL-PFD SYS, MAIN PANEL						Component	ATA:34
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-22-02	PROC. REF: AMM 34-22-02								
342202-0103		CONTROL-MFD SYS,MAIN PANEL						Component	ATA:34
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-22-02	PROC. REF: AMM 34-22-02								
342202-0104		CONTROL-MFD SYS,MAIN PANEL						Component	ATA:34
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-22-02	PROC. REF: AMM 34-22-02								
342204-0101		CREW CAB MODULE -REVERSIONARY PANEL ASSEMBLY						Component	ATA:34
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-22-03	PROC. REF: AMM 34-22-03								
342204-0102		CREW CAB MODULE -REVERSIONARY PANEL ASSEMBLY						Component	ATA:34
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-22-03	PROC. REF: AMM 34-22-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
342205-0101		CREW CAB CONTROL-DISPLAY,FGC,GLARESHIELD PANEL UNIT						Component	ATA:34
PN:7016986-505	MOS/MSC	21-Jun-10	O/C						
SN:03125221	HRS	3461.1							
	AFL	1818							
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									
342205-0102		CREW CAB CONTROL-DISPLAY,FGC,GLARESHIELD PANEL UNIT						Component	ATA:34
PN:7016986-505	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:07016649	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									
342206-0101		PILOT DEVICE-CONTROL,CURSOR,MC-800 UNIT						Component	ATA:34
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-22-05PROC. REF: AMM 34-22-05									
342206-0102		COPILOT DEVICE-CONTROL,CURSOR,MC-800 UNIT						Component	ATA:34
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-22-05PROC. REF: AMM 34-22-05									
342501-0101		MAGNETIC-NAV SYS - WINDSHIELD MOUNTING BRACKET COMPASS						Component	ATA:34
PN:PGA1001WG	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:702130-02	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-25-01PROC. REF: AMM 34-25-01									
342701-0101		NOSE INERTIAL REFERENCE UNIT						Component	ATA:34
PN:HG2001GD03	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:56015315	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-27-01PROC. REF: AMM 34-27-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
342701-0102		NOSE INERTIAL REFERENCE UNIT						Component	ATA:34
PN:HG2001GD03	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:56015276	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-27-01PROC. REF: AMM 34-27-01									
342703-0101		CREW CAB MODE SELECT UNIT						Component	ATA:34
PN:CG1042AB03	MOS/MSC	06-Nov-14	O/C	TSR 18					
SN:56009073	HRS	7222.5		TSR 0					
	AFL	3865		TSR 0					
342703-0102		CREW CAB MODE SELECT UNIT						Component	ATA:34
PN:CG1042AB03	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:73731029	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-27-02PROC. REF: AMM 34-27-02									
343101-0101		LH RADIO ALTIMETER UNIT						Component	ATA:34
PN:7001840-937	MOS/MSC	03-Jan-12	O/C						
SN:01049215	HRS	5261.9							
	AFL	2792							
PROC. REF: AMM 34-31-01PROC. REF: AMM 34-31-01									
343101-0102		RH RADIO ALTIMETER UNIT						Component	ATA:34
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-31-01PROC. REF: AMM 34-31-01									
343102-0101		NAVIGATION SYSTEM - RADIO ALTIMETER ANTENNA						Component	ATA:34
PN:S67-2002	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-31-02PROC. REF: AMM 34-31-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
343102-0102		NAVIGATION SYSTEM - RADIO ALTIMETER ANTENNA						Component	ATA:34
PN:S67-2002	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-31-02	PROC. REF: AMM 34-31-02								
343102-0201		NAVIGATION SYSTEM - RADIO ALTIMETER ANTENNA						Component	ATA:34
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-31-02	PROC. REF: AMM 34-31-02								
343102-0202		NAVIGATION SYSTEM - RADIO ALTIMETER ANTENNA						Component	ATA:34
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-31-02	PROC. REF: AMM 34-31-02								
343200-0101		NOSE COUPLER						Component	ATA:34
PN:DMB-20-20	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:1823	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
343201-0101		NOSE NAV/ADF/DME,INTEGRATED,NAVIGATION SYS UNIT						Component	ATA:34
PN:7510100-631	MOS/MSC	29-Jun-09	O/C						
SN:97052239	HRS	2226.4							
	AFL	1167							
PROC. REF: AMM 34-32-01	PROC. REF: AMM 34-32-01								
343201-0102		NOSE NAV/ADF/DME,INTEGRATED,NAVIGATION SYS UNIT						Component	ATA:34
PN:7510100-631	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:0701B021	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-32-01	PROC. REF: AMM 34-32-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
343202-0101		CREW CAB CONTROL-EMERGENCY,NAVIGATION/COMMUNICATION SYS UNIT						Component	ATA:34
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									
343203-0101		NOSE DUAL GLIDE SLOPE ANTENNA						Component	ATA:34
PN:S41422-2	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:111-5806	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-32-05PROC. REF: AMM 34-32-05									
343204-0101		LOWER MARKER BEACON ANTENNA						Component	ATA:34
PN:3165-82	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:316582-813	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-32-04PROC. REF: AMM 34-32-04									
343205-0101		REAR VOR-LOC ANTENNA						Component	ATA:34
PN:19-78	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-32-03PROC. REF: AMM 34-32-03									
343205-0102		REAR VOR-LOC ANTENNA						Component	ATA:34
PN:19-78	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-32-03PROC. REF: AMM 34-32-03									
343205-0201		REAR DIVIDER,ANTENNA,VOR/ILS/MB SYS COUPLER						Component	ATA:34
PN:CI120-7	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:143362	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-32-12PROC. REF: AMM 34-32-12									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
344101-0101	L/H CSL EGPWS,NAVIGATION,COCKPIT CONTROL UNIT							Component	ATA:34
PN:965-0976-040-216-216	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:25664	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-41-01	PROC. REF: AMM 34-41-01								
344201-0101	NOSE WEATHER RADAR TRANSCEIVER							Component	ATA:34
PN:7021450-801	MOS/MSC	04-Aug-12	O/C						
SN:08028209	HRS	6092							
	AFL	3243							
PROC. REF: AMM 34-42-01	PROC. REF: AMM 34-42-01								
344202-0101	CSL CENT PANEL CONTROL WEATHER RADAR ASSEMBLY							Component	ATA:34
PN:7008471-407	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-42-02	PROC. REF: AMM 34-42-02								
344202-0102	CSL CENT PANEL CONTROL WEATHER RADAR ASSEMBLY							Component	ATA:34
PN:7008471-407	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-42-02	PROC. REF: AMM 34-42-02								
344301-0101	TCAS PROCESSOR UNIT							Component	ATA:34
PN:7517900-55020	MOS/MSC	07-Aug-13	O/C						
SN:20008822	HRS	6643.4							
	AFL	3572							
PROC. REF: AMM 34-43-01	PROC. REF: AMM 34-43-01								
344302-0101	TCAS ANTENNA							Component	ATA:34
PN:7514081-915	MOS/MSC	05-May-18	O/C						
SN:ANE52939	HRS	8585.1							
	AFL	4609							
PROC. REF: AMM 34-43-03, AMM 34-43-02	PROC. REF: AMM 34-43-03, AMM 34-43-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
344303-0101		BAND 'L' (DME/TDR) ANTENNA						Component	ATA:34
PN:2430-87-00	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-43-03PROC. REF: AMM 34-43-03									
344303-0102		TDR TOP BAND 'L' (DME/TDR) ANTENNA						Component	ATA:34
PN:2430-87-00	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-43-03PROC. REF: AMM 34-43-03									
344303-0103		TDR BOT BAND 'L' (DME/TDR) ANTENNA						Component	ATA:34
PN:2430-87-00	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-43-03PROC. REF: AMM 34-43-03									
344303-0104		DMEL BAND 'L' (DME/TDR) ANTENNA						Component	ATA:34
PN:2430-87-00	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-43-03PROC. REF: AMM 34-43-03									
344303-0105		BAND 'L' (DME/TDR) ANTENNA						Component	ATA:34
PN:2430-87-00	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-43-03PROC. REF: AMM 34-43-03									
345203-0101		NOSE COAXIAL RELAY						Component	ATA:34
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
345203-0102		NOSE COAXIAL RELAY						Component	ATA:34
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
345302-0201		NO. 1 ADF ANTENNA						Component	ATA:34
PN:7510300-901	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:0610B051	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-53-02	PROC. REF: AMM 34-53-02								
345302-0202		NO. 2 ADF ANTENNA						Component	ATA:34
PN:7510300-901	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:0610B052	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-53-02	PROC. REF: AMM 34-53-02								
345401-0101		REAR COMPARTMENT RECEIVER, XM RECEIVER						Component	ATA:34
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-54-01	PROC. REF: AMM 34-54-01								
345402-0101		CENTER FUSELAGE - XM - WEATHER DATA, XMRANT ANTENNA						Component	ATA:34
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-54-02	PROC. REF: AMM 34-54-02								
345601-0101		CENT FUS SENSOR,GPS,RADIO/NAVIGATION SYS (GNSSU) UNIT						Component	ATA:34
PN:HG2021GD04	MOS/MSC	19-Aug-15	O/C	TSR 0					
SN:0629	HRS	7460.3		TSR 0					
	AFL	3992		TSR 0					
PROC. REF: AMM 34-56-01	PROC. REF: AMM 34-56-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
345601-0102		CENT FUS SENSOR,GPS,RADIO/NAVIGATION SYS (GNSSU) UNIT						Component	ATA:34
PN:100-601944-300	MOS/MSC	14-Oct-15	O/C						
SN:0200	HRS	7523.8							
	AFL	4025							
PROC. REF: AMM 34-56-01	PROC. REF: AMM 34-56-01								
345602-0201		GPS 1 GPS ANTENNA						Component	ATA:34
PN:S67-1575-135	MOS/MSC	27-Sep-17	O/C	TSN 12					
SN:818-6999	HRS	8319.4		TSN 0					
	AFL	4456		TSN 0					
PROC. REF: AMM 34-56-02	PROC. REF: AMM 34-56-02								
345602-0202		GPS 2 GPS ANTENNA						Component	ATA:34
PN:S67-1575-135	MOS/MSC	19-Aug-15	O/C	TSN 0					
SN:UNKNOWN	HRS	7460.3		TSN 0					
	AFL	3992		TSN 0					
PROC. REF: AMM 34-56-02	PROC. REF: AMM 34-56-02								
346201-0101		NOSE FMS COMPUTER						Component	ATA:34
PN:7018879-03044	MOS/MSC	24-Feb-16	O/C						
SN:07044534	HRS	7661.9							
	AFL	4095							
PROC. REF: AMM 34-61-01	PROC. REF: AMM 34-61-01								
346201-0102		NOSE FMS COMPUTER						Component	ATA:34
PN:7018879-03044	MOS/MSC	01-Sep-17	O/C	TSR 0					
SN:07124588	HRS	8284.1		TSR 0					
	AFL	4446		TSR 0					
PROC. REF: AMM 34-61-01	PROC. REF: AMM 34-61-01								
346202-0101		CSL CENT CONTROL AND DISPLAY (FMS) UNIT						Component	ATA:34
PN:G7830-03	MOS/MSC	04-May-26	O/C						
SN:48356	HRS	11229.1							
	AFL	6000							
PROC. REF: AMM 34-61-02	PROC. REF: AMM 34-61-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
346202-0102		CSL CENT CONTROL AND DISPLAY (FMS) UNIT						Component	ATA:34
PN:G7830-03	MOS/MSC	20-Feb-20	O/C						
SN:56656	HRS	9313.5							
	AFL	4970							
PROC. REF: AMM 34-61-02	PROC. REF: AMM 34-61-02								
346206-0101		CSL CENT DATA,LOADER-DUAL FMS/GPS SYS,CREW CABIN UNIT						Component	ATA:34
PN:G7226-01	MOS/MSC	05-Feb-14	O/C	TSR 0					
SN:1960	HRS	6867.7		TSR 0					
	AFL	3686		TSR 0					
PROC. REF: AMM 34-61-03	PROC. REF: AMM 34-61-03								
346207-0101		NOSE CONFIGURATION-FMS,NAVIGATION SYS MODULE						Component	ATA:34
PN:7014940-902	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-61-04	PROC. REF: AMM 34-61-04								
346207-0102		NOSE CONFIGURATION-FMS,NAVIGATION SYS MODULE						Component	ATA:34
PN:7014940-902	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-61-04	PROC. REF: AMM 34-61-04								
346301-0101		CENTER CONSOLE LH EXPANSION MODULE(EMU),CMA UNIT						Component	ATA:34
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-63-01	PROC. REF: AMM 34-63-01								
346301-0102		CENTER CONSOLE RH EXPANSION MODULE(EMU),CMA UNIT						Component	ATA:34
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-63-01	PROC. REF: AMM 34-63-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
346302-0103		LH ELECTRONIC DISPLAY, (EDU), CMA UNIT (CKPT, SIDE CONSOLE, FS250)						Component	ATA:34
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-63-01PROC. REF: AMM 34-63-01									
346302-0104		RH ELECTRONIC DISPLAY, (EDU), CMA UNIT (CKPT, SIDE CONSOLE, FS250)						Component	ATA:34
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-63-01PROC. REF: AMM 34-63-01									
349095-0101		EGPWS PCMCIA CARD						Component	ATA:34
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									
FD600CAM-2 U		VISUAL INSPECTION OF ALL COMPONENTS INSTALLED AS PART OF FLIGHT DISPLAY SYSTEMS FD600CAM-2 GLARESHIELD CAMERA						Service	ATA:34
	MOS	07-Jul-25	72		07-Jul-31		1868 d		
	HRS	10838.8							
	AFL	5775							
ATA 35 - OXYGEN									
35-10-00-710-001-A00 S		OPERATIONALLY CHECK CREW/PAX OXYGEN MASKS						Service	ATA:35
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 35-10-00PROC. REF: AMM 35-10-00									
35-10-00-910-001-A00 S		FUNCTIONALLY CHECK LEAK TEST CREW OXYGEN SYSTEM LINES						Service	ATA:35
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 35 - OXYGEN									
PROC. REF: AMM 35-10-00PROC. REF: AMM 35-10-00									
35-10-07-720-001-A00		FUNCTIONALLY CHECK CREW OXYGEN CYLINDER PRESSURE REGULATOR						Service	ATA:35
PN:172270-01	MOS	16-Aug-24	60		16-Aug-29		1178 d	SYSTEM	
SN:2570	HRS	10541.4							
	AFL	5613							
PROC. REF: AMM 35-10-07PROC. REF: AMM 35-10-07									
35-10-07-720-002-A01		FUNCTIONALLY CHECK (HYDROSTATIC TEST) CREWOXYGEN CYLINDER.NOTE: FROM THE MANUFACTURE DATE OR LAST TASK ACCOMPLISHMENT.NOTE: OR IN ACCORDANCE WITH LOCAL REGULATORY AUTHORITY REQUIREMENTS						Service	ATA:35
PN:4441009-050	MOS/MSC	31-Aug-23	O/C						
SN:552902908	HRS	10541.4							
	AFL	5613							
			HydroCheck Date: : 31-Aug-23						
PROC. REF: AMM 35-10-07PROC. REF: AMM 35-10-07									
35-20-00-710-001-A00 S		OPERATIONALLY CHECK PASSENGER GASEOUS OXYGEN-SUBSYSTEM IN MANUAL MODE NOTE: IF INSTALLED						Service	ATA:35
	MOS	17-Oct-25	12 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	500 (+20/-20)						
	AFL	5820							
									PKG:5002
PROC. REF: AMM 35-20-00PROC. REF: AMM 35-20-00									
35-20-00-710-002-A00 S		OPERATIONALLY CHECK GASEOUS OXYGEN LOW PRESSURE INDICATING CIRCUIT.NOTE: IF INSTALLED.						Service	ATA:35
	MOS	17-Oct-25	24 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	1000 (+20/-20)						
	AFL	5820							
									PKG:5004
PROC. REF: AMM 35-11-04PROC. REF: AMM 35-11-04									
35-20-00-720-001-A00 S		FUNCTIONALLY CHECK PASSENGER GASEOUS OXYGEN SUBSYSTEM IN AUTOMATIC MODE(NOTE: IF INSTALLED).						Service	ATA:35
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 35-20-00PROC. REF: AMM 35-20-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 35 - OXYGEN									
35-20-02-211-001-A00 S	VISUALLY CHECK PASSENGER GASEOUS OXYGEN MASK ASSEMBLY (NOTE: IF INSTALLED).							Service	ATA:35
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 35-20-04PROC. REF: AMM 35-20-04									
35-20-04-720-001-A00	FUNCTIONALLY CHECK (HYDROSTATIC TEST) NO. 1 PASSENGER OXYGEN CYLINDER ASSEMBLY NOTE: IF INSTALLED NOTE: FROM THE MANUFACTURE DATE OR LAST TASK ACCOMPLISHMENT.							Service	ATA:35
PN:895-48077	MOS/MSC	06-Jul-21	O/C						
SN:ALT281-35367	HRS								
	AFL								
			HydroCheck Date: : 06-Jul-21						
PROC. REF: AMM 35-20-08PROC. REF: AMM 35-20-08									
35-20-04-720-001-A00	FUNCTIONALLY CHECK (HYDROSTATIC TEST) NO. 2 PASSENGER OXYGEN CYLINDER ASSEMBLY NOTE: IF INSTALLED NOTE: FROM THE MANUFACTURE DATE OR LAST TASK ACCOMPLISHMENT.							Service	ATA:35
PN:895-48015	MOS/MSC	28-Feb-23	O/C						
SN:C08100129	HRS								
	AFL								
			HydroCheck Date: : 28-Feb-23						
PROC. REF: AMM 35-20-08PROC. REF: AMM 35-20-08									
35-20-04-960-001-A00	DISCARD NO.1 PASSENGER GASEOUS OXYGEN CYLINDER							Service	ATA:35
PN:895-48077	MOS	01-May-16	180		01-May-31		1801 d	DISCARD	
SN:ALT281-35367	HRS								
	AFL								
PROC. REF: AMM 35-20-08, AMM 35-20-08PROC. REF: AMM 35-20-08, AMM 35-20-08									
35-20-04-960-001-A00	DISCARD NO.2 PASSENGER GASEOUS OXYGEN CYLINDER							Service	ATA:35
PN:895-48015	MOS	11-Jul-23	180		11-Jul-38		4429 d	DISCARD	
SN:C08100129	HRS	10167.3							
	AFL	5404							
PROC. REF: AMM 35-20-08, AMM 35-20-08PROC. REF: AMM 35-20-08, AMM 35-20-08									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 35 - OXYGEN									
35-20-06-900-001-A00		RESTORE (OVERHAUL) LH GASEOUS OXYGEN ELECTRIC PULSE/LATCHING ON-OFF VALVE NOTE: IF INSTALLED NOTE: FROM THE INSTALLATION DATE							Service ATA:35
PN:P21070	MOS	19-May-22	60 (+30d/-30d)		19-May-27	18-Jun-27	358 d (+30)	SYSTEM	
SN:0239	HRS	9875.7	2000		11875.7		599.4		
	AFL	5259							
PROC. REF: AMM 35-20-10	PROC. REF: AMM 35-20-10								
35-20-06-900-001-A00		RESTORE (OVERHAUL) RH GASEOUS OXYGEN ELECTRIC PULSE/LATCHING ON-OFF VALVE NOTE: IF INSTALLED NOTE: FROM THE INSTALLATION DATE							Service ATA:35
PN:P21070	MOS	01-Jun-22	60 (+30d/-30d)		01-Jun-27	01-Jul-27	371 d (+30)	SYSTEM	
SN:R22020218	HRS	9892.8	2000		11892.8		616.5		
	AFL	5264							
PROC. REF: AMM 35-20-10	PROC. REF: AMM 35-20-10								
35-20-07-900-001-A00		RESTORE (OVERHAUL) LH OXYGEN SEQUENCE REGULATOR NOTE: IF INSTALLED NOTE: FROM THE INSTALLATION DATE							Service ATA:35
PN:P21087	MOS	19-May-22	60 (+30d/-30d)		19-May-27	18-Jun-27	358 d (+30)	SYSTEM	
SN:0262	HRS	9875.7	2000		11875.7		599.4		
	AFL	5259							
PROC. REF: AMM 35-20-11	PROC. REF: AMM 35-20-11								
35-20-07-900-001-A00		RESTORE (OVERHAUL) RH OXYGEN SEQUENCE REGULATOR NOTE: IF INSTALLED NOTE: FROM THE INSTALLATION DATE							Service ATA:35
PN:P21087	MOS	19-May-22	60 (+30d/-30d)		19-May-27	18-Jun-27	358 d (+30)	SYSTEM	
SN:0494	HRS	9875.7	2000		11875.7		599.4		
	AFL	5259							
PROC. REF: AMM 35-20-11	PROC. REF: AMM 35-20-11								
35-20-08-211-001-A00 S		VISUALLY CHECK PASSENGER AND CREW GASEOUS OXYGEN PRESSURE INDICATOR GAUGE AGAINST PRESSURE TRANSDUCER INDICATOR ON MFD (NOTE: IF INSTALLED)							Service ATA:35
	MOS	17-Oct-25	24 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	1000 (+20/-20)						
	AFL	5820							
									PKG:5004
PROC. REF: AMM 35-20-08	PROC. REF: AMM 35-20-08								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 35 - OXYGEN									
35-20-15-790-001-A00 S	FUNCTIONALLY CHECK (LEAK) PASSENGER GASEOUS OXYGEN DISTRIBUTION (HP) LINES NOTE: IF INSTALLED							Service	ATA:35
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 35-20-15PROC. REF: AMM 35-20-15									
35-20-16-790-001-A00 S	FUNCTIONALLY CHECK (LEAK) PASSENGER GASEOUS OXYGEN DISTRIBUTION (LP) LINES NOTE: IF INSTALLED							Service	ATA:35
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 35-20-16PROC. REF: AMM 35-20-16									
35-30-01-211-001-A00	VISUALLY CHECK PORTABLE OXYGEN CYLINDER GAUGE PRESSURE INDICATION							Service	ATA:35
	MOS	16-Feb-26	12 (+15d/-15d)		16-Feb-27	03-Mar-27	266 d (+15)	SYSTEM	
	HRS	11064.1	500		11564.1		287.8		
	AFL	5912							
PROC. REF: AMM 35-30-01PROC. REF: AMM 35-30-01									
35-30-01-720-001-A00	FUNCTIONALLY CHECK PASSENGER CABIN PORTABLE OXYGEN BOTTLE PRESSURE REGULATOR							Service	ATA:35
PN:5500-C1W-BF23A	MOS	10-Dec-24	60		10-Dec-29		1294 d	SYSTEM	
SN:P11041075	HRS	10605.1							
	AFL	5653							
PROC. REF: AMM 35-30-01PROC. REF: AMM 35-30-01									
35-30-01-720-002-A00	FUNCTIONALLY CHECK (HYDROSTATIC TEST) PASSENGER CABIN PORTABLE OXYGEN BOTTLE (NOTE: OR IN ACCORDANCE WITH LOCAL REGULATORY AUTHORITY REQUIREMENTS) NOTE: FROM THE MANUFACTURE DATE OR LAST TASK ACCOMPLISHMEN							Service	ATA:35
PN:5500-C1W-BF23A	MOS/MSC	10-Dec-24	O/C						
SN:P11041075	HRS	10605.1							
	AFL	5653							
			HydroCheck Date: : 31-May-24						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 35 - OXYGEN									
35-30-02-211-001-A00 S		VISUALLY CHECK CONTINUOUS FLOW MASK							Service ATA:35
	MOS	17-Oct-25	24 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	1000 (+20/-20)						
	AFL	5820							
									PKG:5004
PROC. REF: AMM 35-30-02PROC. REF: AMM 35-30-02									
35-30-03-960-001-A00		DISCARD COCKPIT EMERGENCY PROTECTIVE BREATHING EQUIPMENT NOTE: FRON THE MANUFACTURE DATE OR DATA PLATE EXPERITATION DATE							Service ATA:35
PN:PN802300-14	MOS	16-Feb-26	120		20-May-32		2186 d	LIFE LIMIT	
SN:E22050236	HRS	11064.1							
	AFL	5912							
			Manufacture Date:: 20-May-22						
PROC. REF: AMM 35-30-03PROC. REF: AMM 35-30-03									
35-30-03-960-001-A00		DISCARD NO.1 EMERGENCY PROTECTIVE BREATHING EQUIPMENT PBE NOTE: FRON THE MANUFACTURE DATE OR DATA PLATE EXPERITATION DATE							Service ATA:35
PN:802300-14	MOS	27-Mar-25	120		28-May-30		1463 d	LIFE LIMIT	
SN:E22050236	HRS	10758.2							
	AFL	5733							
			Manufacture Date:: 28-May-20						
PROC. REF: AMM 35-30-03PROC. REF: AMM 35-30-03									
351000-0101		PILOT MASK ASSY-STORAGE BOX							Component ATA:35
PN:MXP138-1	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:SE21285	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 35-10-09PROC. REF: AMM 35-10-09									
351000-0102		COPILOT MASK ASSY-STORAGE BOX							Component ATA:35
PN:MXP138-1	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:SE20103	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 35-10-09PROC. REF: AMM 35-10-09									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 35 - OXYGEN									
351000-0201		PILOT OXYGEN ASSY-PRESSURE/DEMAND MASK							Component ATA:35
PN:MC10-16-105	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:121209	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 35-10-10PROC. REF: AMM 35-10-10									
351000-0202		COPILOT OXYGEN ASSY-PRESSURE/DEMAND MASK							Component ATA:35
PN:MC10-16-105	MOS/MSC	07-Jan-15	O/C	TSO 38					
SN:117473	HRS	7277.7		TSO 0					
	AFL	3892		TSO 0					
PROC. REF: AMM 35-10-10PROC. REF: AMM 35-10-10									
351000-0203		OBSERVER OXYGEN ASSY-PRESSURE/DEMAND MASK							Component ATA:35
PN:MC10-16-105	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:121213	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 35-10-10PROC. REF: AMM 35-10-10									
351000-0301		OBSERVER LIDS ASSEMBLY							Component ATA:35
PN:MXP129	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:SE19520	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									
351000-0401		COCKPIT PROTECTIVE BREATHING EQUIPMENT (PBE)							Component ATA:35
PN:PN802300-14	MOS/MSC	16-Feb-26	H/T	TSN 46					
SN:E22050236	HRS	11064.1							
	AFL	5912							
			Manufacture Date:: 05-May-22						
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									
351007-0101		COCKPIT OXYGEN CYLINDER							Component ATA:35
PN:4441009-050	MOS	16-Aug-24	180		29-Feb-28		644 d	LIFE LIMIT	
SN:552902908	HRS	10541.4							
	AFL	5613							
			Manufacture Date:: 28-Feb-13						
PROC. REF: AMM 35-10-07PROC. REF: AMM 35-10-07									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 35 - OXYGEN									
351007-0201	CREW OXYGEN CYLINDER PRESSURE REGULATOR							Component	ATA:35
PN:172270-01	MOS/MSC	06-Jul-19	O/C	TSO 119					
SN:2570	HRS	9057.4							
	AFL	4853							
PROC. REF: AMM 35-10-07	PROC. REF: AMM 35-10-07								
351102-0101	PRESSURE ASSY-OXYGEN SYS TRANSDUCER							Component	ATA:35
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 35-11-02	PROC. REF: AMM 35-11-02								
351102-0102	PRESSURE ASSY-OXYGEN SYS TRANSDUCER							Component	ATA:35
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 35-11-02	PROC. REF: AMM 35-11-02								
352000-0101	CREW CAB MODULE -PASS OXYGEN CONTROL ASSEMBLY							Component	ATA:35
PN:135-06949-409	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:0000123549	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 35-20-00	PROC. REF: AMM 35-20-00								
352000-0201	CONTACTING ELEC SYS,OXYGEN BOX,CHEMICAL GENERATION ALTIMETER							Component	ATA:35
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
352006-0101	LH GASEOUS OXYGEN ELECTRIC PULSE/LATCHING ON-OFF VALVE							Component	ATA:35
PN:P21070	MOS/MSC	19-May-22	O/C	TSO 0					
SN:0239	HRS	9875.7		TSO 0					
	AFL	5259		TSO 0					
PROC. REF: AMM 35-20-10	PROC. REF: AMM 35-20-10								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 35 - OXYGEN									
352006-0102		RH GASEOUS OXYGEN ELECTRIC PULSE/LATCHING ON-OFF VALVE						Component	ATA:35
PN:P21070	MOS/MSC	01-Jun-22	O/C	TSN 2					
SN:R22020218	HRS	9892.8		TSN 0					
	AFL	5264		TSN 0					
PROC. REF: AMM 35-20-10	PROC. REF: AMM 35-20-10								
352007-0101		LH OXYGEN SEQUENCE REGULATOR						Component	ATA:35
PN:P21087	MOS/MSC	19-May-22	O/C	TSO 0					
SN:0262	HRS	9875.7		TSO 0					
	AFL	5259		TSO 0					
PROC. REF: AMM 35-20-11	PROC. REF: AMM 35-20-11								
352007-0102		RH OXYGEN SEQUENCE REGULATOR						Component	ATA:35
PN:P21087	MOS/MSC	19-May-22	O/C	TSO 0					
SN:0494	HRS	9875.7		TSO 0					
	AFL	5259		TSO 0					
PROC. REF: AMM 35-20-11	PROC. REF: AMM 35-20-11								
352008-7101		NO. 1 PASSENGER OXYGEN CYLINDER ASSEMBLY						Component	ATA:35
PN:895-48077	MOS/MSC	07-Jul-21	H/T	TSN 62					
SN:ALT281-35367	HRS	9608.3		TSN 1767.2					
	AFL	5118		TSN 916					
PROC. REF: AMM 35-20-08	PROC. REF: AMM 35-20-08								
352008-7102		NO. 2 PASSENGER OXYGEN CYLINDER ASSEMBLY						Component	ATA:35
PN:895-48015	MOS/MSC	11-Jul-23	H/T	TSN 180, TSO 0					
SN:C08100129	HRS	10167.3		TSO 0					
	AFL	5404		TSO 0					
PROC. REF: AMM 35-20-08	PROC. REF: AMM 35-20-08								
353001-0101		PASSENGER CABIN PORTABLE OXYGEN BOTTLE						Component	ATA:35
PN:5500-C1W-BF23A	MOS/MSC	13-Feb-20	O/C	TSN 109, TSO 55, TSR 1					
SN:P11041075	HRS	9310.8		TSO 1850.5, TSR 0					
	AFL	4969		TSO 977, TSR 0					
PROC. REF: AMM 35-30-01	PROC. REF: AMM 35-30-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 35 - OXYGEN									
353003-0101		NO.1 EMERGENCY PROTECTIVE BREATHING EQUIPMENT PBE							Component ATA:35
PN:802300-14	MOS/MSC	27-Mar-25	H/T						
SN:E22050236	HRS	10758.2							
	AFL	5733							
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									
353003-7101 U		NO.2 EMERGENCY PROTECTIVE BREATHING EQUIPMENT PBE							Component ATA:35
PN:15-40-80	MOS	24-Feb-25	120		31-Aug-32		2289 d	LIFE LIMIT	
SN:120007805	HRS	10723.1		TSN 0					
	AFL	5703		TSN 0					
			Manufacture Date:: 31-Aug-22						
353005-0101		PORTABLE OXYGEN CYLINDER PRESSURE REGULATOR							Component ATA:35
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									
ATA 36 - PNEUMATIC									
36-10-01-130-001-A00 S		RESTORE (CLEANING) CROSS-BLEED VALVE FILTER BY ULTRASONIC METHOD							Service ATA:36
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6016
PROC. REF: AMM 36-10-01PROC. REF: AMM 36-10-01									
36-11-01-220-001-A00 S		INSPECT (DETAILED INSPECTION) ENGINE HIGH STAGE VALVE P/N 816601-1 AND LOW PRESSURE BLEED AIR CHECK VALVE P/N 816603 -3 (IF INSTALLED)							Service ATA:36
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 36-11-01PROC. REF: AMM 36-11-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 36 - PNEUMATIC									
36-11-02-130-001-A00 S	RESTORE (CLEANING) HIGH-STAGE VALVE FILTER BY ULTRASONIC METHOD							Service	ATA:36
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6016
PROC. REF: AMM 36-11-02PROC. REF: AMM 36-11-02									
36-11-03-130-001-A00 S	RESTORE (CLEANING) FAN-AIR VALVE FILTER BY ULTRASONIC METHOD							Service	ATA:36
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6016
PROC. REF: AMM 36-11-03PROC. REF: AMM 36-11-03									
36-11-04-110-001-A00 S	RESTORE (CLEANING) PRE-COOLER BY CHEMICAL METHOD.							Service	ATA:36
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 36-11-04PROC. REF: AMM 36-11-04									
36-11-05-130-001-A00 S	RESTORE (CLEANING) ENGINE BLEED VALVE FILTER BY ULTRASONIC METHOD							Service	ATA:36
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6016
PROC. REF: AMM 36-11-05PROC. REF: AMM 36-11-05									
36-11-11-710-001-A00 S	OPERATIONALLY CHECK THERMOSTAT SHUTOFF VALVE							Service	ATA:36
	MOS	17-Oct-25	24 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	1000 (+20/-20)						
	AFL	5820							
									PKG:5004
PROC. REF: AMM 36-11-08PROC. REF: AMM 36-11-08									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 36 - PNEUMATIC									
36-20-00-710-001-A00 S	OPERATIONALLY CHECK BLEED VALVE INDICATION FUNCTION							Service	ATA:36
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: AMM 36-20-00PROC. REF: AMM 36-20-00									
36-20-00-720-001-A00 S	FUNCTIONALLY CHECK OVERTEMPERATURE WARNING CIRCUIT							Service	ATA:36
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: AMM 36-20-00PROC. REF: AMM 36-20-00									
36-20-02-710-003-A00 S	OPERATIONALLY CHECK THERMAL SWITCH							Service	ATA:36
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 36-20-02PROC. REF: AMM 36-20-02									
36-20-05-710-002-A00 S	OPERATIONALLY CHECK BLEED AUTOMATIC SHUTOFF AND CIRCUITRY.							Service	ATA:36
	MOS	17-Oct-25	12 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	500 (+20/-20)						
	AFL	5820							
									PKG:5002
PROC. REF: AMM 36-20-02PROC. REF: AMM 36-20-02									
361001-0101	APU CROSS-BLEED VALVE							Component	ATA:36
PN:816606-1	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:2007030885	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-10-01PROC. REF: AMM 36-10-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 36 - PNEUMATIC									
361002-0101	RH REAR GROUND CHECK "J"SST VALVE							Component	ATA:36
PN:816605-2	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:1591	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-10-02PROC. REF: AMM 36-10-02									
361101-0104	APU CHECK-BLEED SYS,REAR FUSLG I/II VALVE							Component	ATA:36
PN:816603-3	MOS/MSC	27-Mar-13	O/C	TSN 67					
SN:5738	HRS	6503.7		TSN 6503.7					
	AFL	3500		TSN 3500					
PROC. REF: AMM 36-11-01PROC. REF: AMM 36-11-01									
361101-0201	LH ENG CHECK-BLEED SYS,REAR FUSLG I/II VALVE							Component	ATA:36
PN:816603-3	MOS/MSC	06-Jul-19	O/C	TSO 0					
SN:5461	HRS	9057.4		TSO 0					
	AFL	4853		TSO 0					
PROC. REF: AMM 36-11-01PROC. REF: AMM 36-11-01									
361101-0202	LH ENG CHECK-BLEED SYS,REAR FUSLG I/II VALVE							Component	ATA:36
PN:816603-3	MOS/MSC	16-Jul-15	O/C	TSR 4					
SN:6642	HRS	7460.3		TSR 0					
	AFL	3992		TSR 0					
PROC. REF: AMM 36-11-01PROC. REF: AMM 36-11-01									
361101-0203	RH ENG CHECK-BLEED SYS,REAR FUSLG I/II VALVE							Component	ATA:36
PN:816603-3	MOS/MSC	06-Jul-19	O/C						
SN:UNKNOWN	HRS	9057.4							
	AFL	4853							
PROC. REF: AMM 36-11-01PROC. REF: AMM 36-11-01									
361101-0204	RH ENG CHECK-BLEED SYS,REAR FUSLG I/II VALVE							Component	ATA:36
PN:816603-3	MOS/MSC	06-Jul-19	O/C						
SN:UNKNOWN	HRS	9057.4							
	AFL	4853							
PROC. REF: AMM 36-11-01PROC. REF: AMM 36-11-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 36 - PNEUMATIC									
361102-0101		LH PIL HIGH STAGE VALVE						Component	ATA:36
PN:816601-1	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-11-02PROC. REF: AMM 36-11-02									
361102-0102		RH PIL HIGH STAGE VALVE						Component	ATA:36
PN:816601-1	MOS/MSC	03-Feb-22	O/C						
SN:9808109	HRS	9799							
	AFL	5212							
PROC. REF: AMM 36-11-02PROC. REF: AMM 36-11-02									
361102-0201		LH ENG HIGH STAGE VALVE						Component	ATA:36
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-11-02PROC. REF: AMM 36-11-02									
361102-0202		RH ENG HIGH STAGE VALVE						Component	ATA:36
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-11-02PROC. REF: AMM 36-11-02									
361103-0101		LEFT REGULATION-TYPE BUTTERFLY,AIR,TURBOFAN ENGINE VALVE						Component	ATA:36
PN:816610-2	MOS/MSC	05-Mar-18	O/C	TSN 127					
SN:2007040036	HRS	8509.4		TSN 8509.4					
	AFL	4566		TSN 4566					
PROC. REF: AMM 36-11-03PROC. REF: AMM 36-11-03									
361103-0102		RIGHT REGULATION-TYPE BUTTERFLY,AIR,TURBOFAN ENGINE VALVE						Component	ATA:36
PN:816610-2	MOS/MSC	05-Mar-18	O/C	TSR 77					
SN:200208156	HRS	8509.4		TSR 3593					
	AFL	4566		TSR 1965					
PROC. REF: AMM 36-11-03PROC. REF: AMM 36-11-03									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 36 - PNEUMATIC									
361106-0101		LEFT THERMOSTAT-FAN AIR ,ENGINE CONTROLLER						Component	ATA:36
PN:816624-10	MOS/MSC	05-Mar-18	O/C	TSR 0					
SN:2008061104	HRS	8509.4		TSR 0					
	AFL	4566		TSR 0					
PROC. REF: AMM 36-11-06	PROC. REF: AMM 36-11-06								
361106-0102		RIGHT THERMOSTAT-FAN AIR ,ENGINE CONTROLLER						Component	ATA:36
PN:816624-10	MOS/MSC	05-Mar-18	O/C						
SN:200312138	HRS	8509.4							
	AFL	4566							
PROC. REF: AMM 36-11-06	PROC. REF: AMM 36-11-06								
361106-0103		LEFT THERMOSTAT-FAN AIR ,ENGINE CONTROLLER						Component	ATA:36
PN:816624-9	MOS/MSC	10-Jul-11	O/C						
SN:2005070688	HRS	4802.9							
	AFL	2530							
PROC. REF: AMM 36-11-06	PROC. REF: AMM 36-11-06								
361106-0104		RIGHT THERMOSTAT-FAN AIR ,ENGINE CONTROLLER						Component	ATA:36
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-11-06	PROC. REF: AMM 36-11-06								
361107-0101		LH ENG PRESSURE HIGH STAGE,AIR BLEED SYS,ENGINE SWITCH						Component	ATA:36
PN:782100-8	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:2457	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-11-07	PROC. REF: AMM 36-11-07								
361107-0102		RH ENG PRESSURE HIGH STAGE,AIR BLEED SYS,ENGINE SWITCH						Component	ATA:36
PN:782100-8	MOS/MSC	19-Aug-15	O/C	TSN 0					
SN:4375	HRS	7460.3		TSN 0					
	AFL	3992		TSN 0					
PROC. REF: AMM 36-11-07	PROC. REF: AMM 36-11-07								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 36 - PNEUMATIC									
361201-0101	APU BLEED AIR VALVE							Component	ATA:36
PN:4952829	MOS/MSC	28-Feb-17	O/C						
SN:4033	HRS								
	AFL								
PROC. REF: AMM 36-12-03	PROC. REF: AMM 36-12-03								
361300-0101	LH AIR BLEED SYS, ENGINE PYLON PRE-COOLER							Component	ATA:36
PN:145-30609-401	MOS/MSC	29-Jun-23	O/C	TSO 0					
SN:3478	HRS	10161.5		TSO 0					
	AFL	5401		TSO 0					
PROC. REF: AMM 36-11-04	PROC. REF: AMM 36-11-04								
361300-0102	RH AIR BLEED SYS, ENGINE PYLON PRE-COOLER							Component	ATA:36
PN:145-30609-401	MOS/MSC	29-Jun-23	O/C	TSO 0					
SN:0000623635	HRS	10161.5		TSO 0					
	AFL	5401		TSO 0					
PROC. REF: AMM 36-11-04	PROC. REF: AMM 36-11-04								
361700-0201	BLEED LH SOLENOID-THREE WAY/TWO POSITIONS,BLEED SYS VALVE							Component	ATA:36
PN:5303-21	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
361700-0202	BLEED RH SOLENOID-THREE WAY/TWO POSITIONS,BLEED SYS VALVE							Component	ATA:36
PN:5303-21	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
361700-0203	X BLEED SOLENOID-THREE WAY/TWO POSITIONS,BLEED SYS VALVE							Component	ATA:36
PN:5303-21	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 36 - PNEUMATIC									
361700-0204		X BLEED SOLENOID-THREE WAY/TWO POSITIONS,BLEED SYS,REAR FUSELAGE VALVE						Component	ATA:36
PN:5303-21	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									
362000-0101		OVERHEAD PANEL PNEUMATIC CONTROL MODULE						Component	ATA:36
PN:145-31625-421	MOS/MSC	29-May-13	O/C						
SN:0000504768	HRS	6582.7							
	AFL	3538							
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									
362000-0102		OVERHEAD PANEL MODULE ASSY MODULE						Component	ATA:36
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									
362001-0101		LH PYLON INDICATOR,BRAKE TEMPERATURE SENSOR						Component	ATA:36
PN:0132ADT	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:G4035	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-20-01PROC. REF: AMM 36-20-01									
362001-0102		RH PYLON INDICATOR,BRAKE TEMPERATURE SENSOR						Component	ATA:36
PN:0132ADT	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:G4092	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-20-01PROC. REF: AMM 36-20-01									
362001-0201		LH PACK INDICATOR,BRAKE TEMPERATURE SENSOR						Component	ATA:36
PN:0132ADT	MOS/MSC	05-Mar-18	O/C	TSN 127					
SN:G4036	HRS	8509.4		TSN 8509.4					
	AFL	4566		TSN 4566					
PROC. REF: AMM 36-20-01PROC. REF: AMM 36-20-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 36 - PNEUMATIC									
362001-0202		RH PACK INDICATOR,BRAKE TEMPERATURE SENSOR							Component ATA:36
PN:0132ADT	MOS/MSC	05-Mar-18	O/C	TSN 127					
SN:G4039	HRS	8509.4		TSN 8509.4					
	AFL	4566		TSN 4566					
PROC. REF: AMM 36-20-01PROC. REF: AMM 36-20-01									
ATA 38 - WATER/WASTE									
38-10-00-610-001-A00		RESTORE (CLEANING) STERILIZE POTABLE WATER SYSTEM.							Service ATA:38
	MOS	17-Oct-25	12 (+15d/-15d)		17-Oct-26	01-Nov-26	144 d (+15)	SYSTEM	
	HRS	10913.9							
	AFL	5820							
PROC. REF: AMM 38-10-00PROC. REF: AMM 38-10-00									
38-10-00-710-001-A00 S		OPERATIONALLY CHECK POTABLE WATER HEATER SYSTEM.NOTE: APPLICABLE TO AIRCRAFT EQUIPPED WITH ONE (01) POTABLE WATER SERVICE PANEL.(L600 ONLY)							Service ATA:38
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 38-33-00PROC. REF: AMM 38-33-00									
38-10-03-960-001-A00 S		DISCARD WATER FILTER CARTRIDGE (IF INSTALLED)							Service ATA:38
	MOS	17-Oct-25	24 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	1000 (+20/-20)						
	AFL	5820							
									PKG:5004
PROC. REF: AMM 38-10-12PROC. REF: AMM 38-10-12									
38-10-05-720-001-A00		FUNCTIONALLY CHECK OF MECHANICAL RELIEF VALVE GOODRICH PN 4E3263-1. NOTE: IF INSTALLED. (L600 ONLY)							Service ATA:38
	MOS/MSC	27-Aug-07	N/A						
	HRS	0							
	AFL	0							
PROC. REF: AMM 38-10-01PROC. REF: AMM 38-10-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 38 - WATER/WASTE									
38-10-05-720-001-A01	FUNCTIONALLY CHECK OF MECHANICAL RELIEF VALVE HYDRAFLOW PN VA046-SERIES. NOTE: IF INSTALLED.							Service	ATA:38
	MOS/MSC	27-Aug-07	N/A						
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: AMM 38-10-07PROC. REF: AMM 38-10-07									
38-32-04-960-001-A00 S	DISCARD WASTE DRAIN VALVE O-RING							Service	ATA:38
	MOS	17-Oct-25	12 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	500 (+20/-20)						
	AFL	5820							
									PKG:5002
PROC. REF: AMM 38-32-04PROC. REF: AMM 38-32-04									
38-32-10-960-001-A00 S	DISCARD WASTE DRAIN VALVE CAP SEAL							Service	ATA:38
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 38-32-04PROC. REF: AMM 38-32-04									
38-33-00-710-001-A00 S	OPERATIONALLY CHECK THE WASTE WATER HEATER SYSTEM							Service	ATA:38
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 38-33-00PROC. REF: AMM 38-33-00									
381001-0101	GALLEY WATER TANK ASSEMBLY							Component	ATA:38
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 38-10-01PROC. REF: AMM 38-10-01									

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 38 - WATER/WASTE									
381011-0701 U		WATER LEVEL CONTROLLER							Component ATA:38
PN:32612	MOS/MSC	24-Feb-16	O/C	TSN 0					
SN:1145469	HRS	7661.9		TSN 0					
	AFL	4095		TSN 0					
381015-0702 U		AFT WATER HEATER							Component ATA:38
PN:4E3176-1	MOS/MSC	29-Jun-20	O/C	TSN 0					
SN:N2006517	HRS	9369.6		TSN 0					
	AFL	4994		TSN 0					
381074-7000 U		LAVATORY WATER TANK							Component ATA:38
PN:AR9038-1	MOS/MSC	23-Apr-13	O/C					CUSTOMER CODE	
SN:0115	HRS	6533.4							
	AFL	3513							
383204-0101		LAVATORY WATER DRAIN VALVE							Component ATA:38
PN:0218-0032-1	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:045717	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 38-32-04PROC. REF: AMM 38-32-04									
383204-0102		REAR FUSELAGE WASTE DRAIN VALVE							Component ATA:38
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 38-32-04PROC. REF: AMM 38-32-04									
383250-0701 U		LAVATORY FLUSH SWITCH PANEL							Component ATA:38
PN:990-9105-016	MOS/MSC	23-Nov-15	O/C	TSR 47					
SN:05060019713	HRS	7556		TSR 0					
	AFL	4049		TSR 0					

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 38 - WATER/WASTE									
383301-0701 U		GALLEY SINK WATER DRAIN VALVE ASSY						Component	ATA:38
PN:AR9124-1D626	MOS/MSC	21-Apr-16	O/C	TSN 8					
SN:0009534925	HRS	7713.9		TSN 0					
	AFL	4144		TSN 0					
ATA 45 - CENTRAL MAINT SYSTEM									
454501-0101		CREW CAB CENTRAL MAINTENANCE - CMC COMPUTER						Component	ATA:45
PN:251-116-013-012	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:AC44341	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 45-45-01	PROC. REF: AMM 45-45-01								
ATA 49 - AIRBORNE AUXILIARY POWER									
49-17-00-160-001-A00 S		RESTORE (CLEANING) APU DRAINS POST MOD SB 145LEG-49-0006 OR WITH AN EQUIVALENT MODIFICATION FACTORY INCORPORATED						Service	ATA:49
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 49-19-02	PROC. REF: AMM 49-19-02								
49-31-00-710-001-A01		APU - OPERATIONALLY CHECK THE APU FADEC BITE DISPLAY FOR FAULT MESSAGES FOR APU MODEL T-62T-40C14 (APS500R).(NOTE : IF INSTALLED).						Service	ATA:49
	MOS	16-Feb-26							
	HRS	6017	400		6417		319		
	APUS	5442							
PROC. REF: AMM 49-64-03	PROC. REF: AMM 49-64-03								
49-31-04-960-001-A01		APU - DISCARD APS 500R INLET FUEL FILTER FOR APU MODEL T-62T-40C14 (APS500R) ONLY.(NOTE: IF INSTALLED).						Service	ATA:49
	MOS	14-Jul-22						SYSTEM	
	HRS	5009	1200		6209		111		
	APUS	4337							
PROC. REF: AMM 49-32-15	PROC. REF: AMM 49-32-15								

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 49 - AIRBORNE AUXILIARY POWER									
49-41-03-220-001-A00	APU - INSPECT (DETAILED INSPECTION) IGNITER PLUG								Service ATA:49
	MOS	14-Jul-22						SYSTEM	
	HRS	5009	1200		6209		111		
	APUS	4337							
PROC. REF: AMM 49-44-03	PROC. REF: AMM 49-44-03								
49-62-00-710-001-A00 S	OPERATIONALLY CHECK APU EMERGENCY SHUTDOWN BY USING APU FUEL SHUTOFF SWITCH AND FIRE TEST SWITCH.								Service ATA:49
	MOS	17-Oct-25	72 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	3000 (+20/-20)						
	AFL	5820	1500 (+20/-20)						
									PKG:5012,6020
PROC. REF: AMM 49-62-00	PROC. REF: AMM 49-62-00								
49-91-00-610-001-A00	APU - SERVICE (REPLENISH) CHECK OIL LEVEL AND SERVICE OIL SYSTEM AS REQUIRED								Service ATA:49
	MOS	16-Feb-26						SYSTEM	
	HRS	6017	400		6417		319		
	APUS	5442							
PROC. REF: AMM 49-96-00	PROC. REF: AMM 49-96-00								
49-91-00-680-001-A00	APU - SERVICE (DRAIN) AND REPLACE APU OIL SUPPLY								Service ATA:49
	MOS	17-Oct-25	12		17-Oct-26		144 d	SYSTEM	
	HRS	5934	2000		7934		1836		
	APUS	5309							
PROC. REF: AMM 49-96-00	PROC. REF: AMM 49-96-00								
49-91-01-960-001-A00	APU - DISCARD APU OIL FILTER ELEMENT								Service ATA:49
	MOS	10-Dec-24	24		10-Dec-26		198 d	SYSTEM	
	HRS	5776	2000		7776		1678		
	APUS	5052							
PROC. REF: AMM 49-96-01	PROC. REF: AMM 49-96-01								
490000-0101	OVERH P APU CONTROL MODULE								Component ATA:49
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 26-12-02	PROC. REF: AMM 26-12-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 49 - AIRBORNE AUXILIARY POWER									
491000-0101	APU - AUXILIARY POWER UNIT COWLING							Component	ATA:49
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 49-15-00PROC. REF: AMM 49-15-00									
491010	APU - ELECTRICAL HARNESS							Component	ATA:49
PN:4504230B	MOS/MSC	28-Feb-17	O/C						
SN:1031	HRS	2952.1							
	APUS	2686							
491015	APU - COMBUSTOR ASSEMBLY							Component	ATA:49
PN:4504374B	MOS/MSC	30-Nov-06	O/C	TSN 0					
SN:L06-002	HRS	0		TSN 0					
	APUS	0		TSN 0					
491020	APU - COMBUSTOR LINER							Component	ATA:49
PN:4504383A	MOS/MSC	30-Nov-06	O/C	TSN 0					
SN:H06-005	HRS	0		TSN 0					
	APUS	0		TSN 0					
491025	APU - COMBUSTOR HOUSING							Component	ATA:49
PN:4505387B	MOS/MSC	30-Nov-06	O/C	TSN 0					
SN:L06-002	HRS	0		TSN 0					
	APUS	0		TSN 0					
491030	APU - OUTPUT SHAFT							Component	ATA:49
PN:4505403	MOS/MSC	30-Nov-06	O/C	TSN 0					
SN:V72-W0186	HRS	0		TSN 0					
	APUS	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 49 - AIRBORNE AUXILIARY POWER									
491040		APU - (1 OF 3) STAR GEAR						Component	ATA:49
PN:4505488	MOS/MSC	30-Nov-06	O/C	TSN 0					
SN:V72-W120	HRS	0		TSN 0					
	APUS	0		TSN 0					
491041		APU - (2 OF 3) STAR GEAR						Component	ATA:49
PN:4505488	MOS/MSC	30-Nov-06	O/C	TSN 0					
SN:V72-W125	HRS	0		TSN 0					
	APUS	0		TSN 0					
491042		APU - (3 OF 3) STAR GEAR						Component	ATA:49
PN:4505488	MOS/MSC	30-Nov-06	O/C	TSN 0					
SN:V72-W076	HRS	0		TSN 0					
	APUS	0		TSN 0					
491050		APU - FUEL MANIFOLD ASSEMBLY						Component	ATA:49
PN:4951609	MOS/MSC	30-Nov-06	O/C	TSN 0					
SN:03061359-01	HRS	0		TSN 0					
	APUS	0		TSN 0					
491055		APU - SECONDARY FUEL MANIFOLD						Component	ATA:49
PN:4951610	MOS/MSC	30-Nov-06	O/C	TSN 0					
SN:03146306-01	HRS	0		TSN 0					
	APUS	0		TSN 0					
491060		APU - MAIN FUEL SOLENOID						Component	ATA:49
PN:4952316-2	MOS/MSC	30-Nov-06	O/C	TSN 0					
SN:1671	HRS	0		TSN 0					
	APUS	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 49 - AIRBORNE AUXILIARY POWER									
491101-0101	APU - TURBINE WHEEL ASSEMBLY								Component ATA:49
PN:4504847	MOS/MSC	28-Feb-17	H/T					LIFE LIMIT	
SN:HK713	HRS	2952.1		TSN 13					
	APUS	2686		TSN 5					
491101-0101-A00	APU - DISCARD OF TURBINE WHEEL								Service ATA:49
PN:4504847	MOS	28-Feb-17						LIFE LIMIT	
SN:HK713	HRS	2952.1							
	APUS	2686	15000	TAC 5	17681		12110		
491120-0101	APU - IMPELLER ASSEMBLY								Component ATA:49
PN:4504253	MOS/MSC	28-Feb-17	H/T						
SN:SIF3866	HRS	2952.1		TSN 13					
	APUS	2686		TSN 5					
491120-0101-A00	APU - DISCARD OF THE COMPRESSOR IMPELLER								Service ATA:49
PN:4504253	MOS	28-Feb-17						LIFE LIMIT	
SN:SIF3866	HRS	2952.1							
	APUS	2686	50000	TAC 5	52681		47110		
492000-0101 U	APU - AUXILIARY POWER, T62/T40C14,MOD A UNIT								Component ATA:49
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 49-14-01PROC. REF: AMM 49-14-01									
492010	APU - QUILL SHAFT								Component ATA:49
PN:4504407A	MOS/MSC	30-Nov-06	O/C	TSN 0					
SN:W0387	HRS	0		TSN 0					
	APUS	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 49 - AIRBORNE AUXILIARY POWER									
492015		APU - THRUST BEARING						Component	ATA:49
PN:4502042	MOS/MSC	30-Nov-06	O/C	TSN 0					
SN:2489	HRS	0		TSN 0					
	APUS	0		TSN 0					
492020		APU - TURBINE ASSEMBLY						Component	ATA:49
PN:4504115B	MOS/MSC	28-Feb-17	O/C	TSN 123					
SN:1004	HRS	2952.1		TSN 2952.1, TSR 1.3					
	APUS	2686		TSN 2686, TSR 5					
492025		APU - GEARBOX ASSEMBLY						Component	ATA:49
PN:4504235D	MOS/MSC	28-Feb-17	O/C	TSN 123					
SN:D749	HRS	2952.1		TSN 2952.1					
	APUS	2686		TSN 2686					
492026		APU - GEARBOX HOUSING						Component	ATA:49
PN:4504360C	MOS/MSC	30-Nov-06	O/C	TSN 0					
SN:V4551106D749	HRS	0		TSN 0					
	APUS	0		TSN 0					
492035		APU - ROTOR ASSEMBLY						Component	ATA:49
PN:4504257A	MOS/MSC	30-Nov-06	O/C	TSN 0					
SN:V42-C4599	HRS	0		TSN 0					
	APUS	0		TSN 0					
492040		APU - INTERMEDIATE GEAR						Component	ATA:49
PN:4504313	MOS/MSC	30-Nov-06	O/C	TSN 0					
SN:V24-D0773	HRS	0		TSN 0					
	APUS	0		TSN 0					

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 49 - AIRBORNE AUXILIARY POWER									
492045		APU - RING GEAR						Component	ATA:49
PN:4504328	MOS/MSC	30-Nov-06	O/C	TSN 0					
SN:V24-D0953	HRS	0		TSN 0					
	APUS	0		TSN 0					
492050		APU - CONTAINMENT RING						Component	ATA:49
PN:4504652	MOS/MSC	30-Nov-06	O/C	TSN 0					
SN:D911	HRS	0		TSN 0					
	APUS	0		TSN 0					
492055 U		APU - TURBINE WHEEL						Component	ATA:49
PN:PN	MOS/MSC	30-Nov-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	APUS	0		TSN 0					
492060		APU - TURBINE NOZZLE						Component	ATA:49
PN:4505479	MOS/MSC	30-Nov-06	O/C	TSN 0					
SN:0829	HRS	0		TSN 0					
	APUS	0		TSN 0					
492065		APU - DIFFUSER						Component	ATA:49
PN:4505480	MOS/MSC	30-Nov-06	O/C	TSN 0					
SN:V06-G0006	HRS	0		TSN 0					
	APUS	0		TSN 0					
492070		APU - ANTI-SURGE VALVE						Component	ATA:49
PN:4950899	MOS/MSC	30-Nov-06	O/C	TSN 0					
SN:1939	HRS	0		TSN 0					
	APUS	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 49 - AIRBORNE AUXILIARY POWER									
492075		APU - ROLLER BEARING						Component	ATA:49
PN:4951506	MOS/MSC	30-Nov-06	O/C	TSN 0					
SN:3331-1368	HRS	0		TSN 0					
	APUS	0		TSN 0					
492080		APU - CARBON SEAL						Component	ATA:49
PN:4951586	MOS/MSC	30-Nov-06	O/C	TSN 0					
SN:11460	HRS	0		TSN 0					
	APUS	0		TSN 0					
492081		APU - SEAL MATING RING						Component	ATA:49
PN:4951587	MOS/MSC	30-Nov-06	O/C	TSN 0					
SN:10694	HRS	0		TSN 0					
	APUS	0		TSN 0					
493010		APU - FUEL PUMP						Component	ATA:49
PN:4503140D	MOS/MSC	30-Nov-06	O/C	TSN 0					
SN:3325	HRS	0		TSN 0					
	APUS	0		TSN 0					
493015		APU - FUEL CONTROL ASSEMBLY						Component	ATA:49
PN:4504616A	MOS/MSC	30-Nov-06	O/C	TSN 0					
SN:11-06-62	HRS	0		TSN 0					
	APUS	0		TSN 0					
493025		APU - FLOW DIVIDER						Component	ATA:49
PN:4951486	MOS/MSC	30-Nov-06	O/C	TSN 0					
SN:1087	HRS	0		TSN 0					
	APUS	0		TSN 0					

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 49 - AIRBORNE AUXILIARY POWER									
493030		APU - FUEL CONTROL SERVO VALVE						Component	ATA:49
PN:4951568	MOS/MSC	30-Nov-06	O/C	TSN 0					
SN:1240	HRS	0		TSN 0					
	APUS	0		TSN 0					
493035		APU - LOW OIL PRESSURE SWITCH						Component	ATA:49
PN:4952366	MOS/MSC	30-Nov-06	O/C	TSN 0					
SN:1107	HRS	0		TSN 0					
	APUS	0		TSN 0					
494010		APU - EXCITER						Component	ATA:49
PN:4950745	MOS/MSC	05-Aug-25	O/C	TSN 0					
SN:07059898	HRS	5899		TSN 0					
	APUS	5238		TSN 0					
495010		APU - AIR HOUSING INLET						Component	ATA:49
PN:4504117B	MOS/MSC	30-Nov-06	O/C	TSN 0					
SN:1004	HRS	0		TSN 0					
	APUS	0		TSN 0					
495015		APU - AIR INLET DUCT						Component	ATA:49
PN:4504716	MOS/MSC	30-Nov-06	O/C	TSN 0					
SN:MS1282	HRS	0		TSN 0					
	APUS	0		TSN 0					
495020 U		APU - BLEED AIR VALVE						Component	ATA:49
PN:4952375	MOS/MSC	30-Nov-06	O/C	TSN 0					
SN:2442	HRS	0		TSN 0					
	APUS	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 49 - AIRBORNE AUXILIARY POWER									
495025		APU - HOT SWITCH						Component	ATA:49
PN:4952459-1	MOS/MSC	30-Nov-06	O/C	TSN 0					
SN:479	HRS	2		TSN 0					
	APUS	7		TSN 0					
495201		APU - NO. 1 INJECTOR						Component	ATA:49
PN:4952404	MOS/MSC	30-Nov-06	O/C	TSN 0					
SN:W2662	HRS	2		TSN 0					
	APUS	7		TSN 0					
495202		APU - NO. 2 INJECTOR						Component	ATA:49
PN:4952404	MOS/MSC	30-Nov-06	O/C	TSN 0					
SN:W2670	HRS	2		TSN 0					
	APUS	7		TSN 0					
495203		APU - NO. 3 INJECTOR						Component	ATA:49
PN:4952404	MOS/MSC	30-Nov-06	O/C	TSN 0					
SN:W2641	HRS	2		TSN 0					
	APUS	7		TSN 0					
495204		APU - NO. 4 INJECTOR						Component	ATA:49
PN:4952404	MOS/MSC	30-Nov-06	O/C	TSN 0					
SN:W2674	HRS	2		TSN 0					
	APUS	7		TSN 0					
495205		APU - NO. 5 INJECTOR						Component	ATA:49
PN:4952404	MOS/MSC	30-Nov-06	O/C	TSN 0					
SN:W2635	HRS	2		TSN 0					
	APUS	7		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 49 - AIRBORNE AUXILIARY POWER									
495206		APU - NO. 6 INJECTOR						Component	ATA:49
PN:4952404	MOS/MSC	30-Nov-06	O/C	TSN 0					
SN:W2665	HRS	2		TSN 0					
	APUS	7		TSN 0					
496000-0101		APU - AUXILIARY POWER, FADEC CONTROL UNIT						Component	ATA:49
PN:4504205E	MOS/MSC	16-Nov-09	O/C						
SN:0063	HRS								
	AFL								
PROC. REF: AMM 49-64-03PROC. REF: AMM 49-64-03									
496010		APU - GEAR ASSEMBLY						Component	ATA:49
PN:4503716A	MOS/MSC	30-Nov-06	O/C	TSN 0					
SN:V4350806-W143	HRS	0		TSN 0					
	APUS	0		TSN 0					
496015		APU - DATA MEMORY MODULE						Component	ATA:49
PN:4505576	MOS/MSC	30-Nov-06	O/C	TSN 0					
SN:1494	HRS	0		TSN 0					
	APUS	0		TSN 0					
497010		APU - SPEED SENSOR						Component	ATA:49
PN:4504185C	MOS/MSC	30-Nov-06	O/C	TSN 0					
SN:096669	HRS	0		TSN 0					
	APUS	0		TSN 0					
497020		APU - TEMP/PRESS SENSOR						Component	ATA:49
PN:4504196A	MOS/MSC	30-Nov-06	O/C	TSN 0					
SN:V00-S091639	HRS	0		TSN 0					
	APUS	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 49 - AIRBORNE AUXILIARY POWER									
499010		APU - OIL PUMP GEAR						Component	ATA:49
PN:4504241	MOS/MSC	30-Nov-06	O/C	TSN 0					
SN:V7770406	HRS	0		TSN 0					
	APUS	0		TSN 0					
49APU1		APU						Component	ATA:49
PN:4504113A	MOS/MSC	10-Mar-17	E/C						
SN:SP-E0614882	HRS	8094.9		TSN 2952.1, TSR 1.3					
WC#: 49.APU1	AFL	4346		TSN 2686, TSR 5					
PROC. REF: AMM 49-14-01PROC. REF: AMM 49-14-01									
ATA 52 - DOORS									
52-00-00-211-001-A00 S		VISUALLY CHECK LOCKING RED MARKSNOTE: REPAINT IF NECESSARY						Service	ATA:52
	MOS	29-Jun-23	48 (+15d/-15d)				LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 52-00-00PROC. REF: AMM 52-00-00									
52-10-00-220-801-L00 S		DETAILED INSPECTION (INTERNAL) OF MAIN DOOR COMPONENTS:- MAIN DOOR STOP & BACK UP STRUCTURES (SSI 52-10-03)- MAIN DOOR FOLDING FLAP STOPS (SSI 52-10-04)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR SSI 52-10-04						Service	ATA:52
	MOS	29-Jun-23	48 (+15d/-15d)				LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: NDT 52-10-00, CPM 51-61-00PROC. REF: NDT 52-10-00, CPM 51-61-00									
52-10-00-220-802-L00 S		DETAILED INSPECTION (INTERNAL) OF MAIN DOOR COMPONENTS:- MAIN DOOR FOLDING FLAP STRUCTURE (SSI 52-10-02)- MAIN DOOR-TO-FUSELAGE ATTACHMENT FITTINGS & INTERFACE PARTS (SSI 52-10-05)						Service	ATA:52
	MOS	29-Jun-23	96 (+15d/-15d)				LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 52-10-00PROC. REF: NDT 52-10-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 52 - DOORS									
52-10-00-220-803-L00 S	DETAILED INSPECTION (EXTERNAL) OF MAIN DOOR COMPONENTS:- MAIN DOOR-TO-FUSELAGE ATTACHMENT FITTINGS & INTER-FACE PARTS (SSI 52-10-05)- MAIN DOOR FOLDING FLAP STRUC- TURE (SSI 52-10-02)							Service	ATA:52
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 52-10-00PROC. REF: NDT 52-10-00									
52-10-00-220-804-L00 S	DETAILED INSPECTION (EXTERNAL) OF MAIN DOOR COMPONENTS:- STOP & BACK UP STRUCTURES (SSI 52-10-03)							Service	ATA:52
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6016
PROC. REF: NDT 52-10-00PROC. REF: NDT 52-10-00									
52-10-00-220-807-L00	DETAILED INSPECTION (EXTERNAL) OF MAIN DOOR COMPONENTS:- STRUCTURE (SSI 52-10-01) (L650 ONLY)							Service	ATA:52
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL	
	HRS	0							
	AFL	0							
									PKG:6032
PROC. REF: NDT 52-10-00PROC. REF: NDT 52-10-00									
52-10-00-220-808-L00	DETAILED INSPECTION (INTERNAL) OF MAIN DOOR COMPONENTS:- STRUCTURE (SSI 52-10-01) (L650 ONLY)							Service	ATA:52
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL	
	HRS	0							
	AFL	0							
									PKG:6032
PROC. REF: NDT 52-10-00PROC. REF: NDT 52-10-00									
52-10-00-220-C01-L00 S	DETAILED INSPECTION (EXTERNAL) OF MAIN DOOR COMPONENTS:- STRUCTURE (SSI 52-10-01) (L600 ONLY)							Service	ATA:52
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: CPM 52-10-00PROC. REF: CPM 52-10-00									

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 52 - DOORS									
52-10-00-220-C02-L00 S	DETAILED INSPECTION (INTERNAL) OF MAIN DOOR COMPONENTS:- STRUCTURE (SSI 52-10-01) (L600 ONLY)							Service	ATA:52
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: CPM 52-10-00PROC. REF: CPM 52-10-00									
52-11-00-640-001-A00 S	LUBRICATE STANDARD MAIN DOOR ACTUATING AND LOCKING MECHANISM							Service	ATA:52
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 52-11-00PROC. REF: AMM 52-11-00									
52-11-00-720-005-A00 S	FUNCTIONALLY CHECK STANDARD MAIN DOOR ACTUATING, LATCHING AND LOCKING MECHANISM							Service	ATA:52
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 52-11-00PROC. REF: AMM 52-11-00									
52-12-00-710-001-A00 S	OPERATIONALLY CHECK ALTERNATE OPENING SYSTEM							Service	ATA:52
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 52-12-00PROC. REF: AMM 52-12-00									
52-12-00-720-001-A00 S	FUNCTIONALLY CHECK MAIN DOOR HYDRAULIC ACCUMULATOR NITROGEN CHARGE							Service	ATA:52
	MOS	17-Oct-25	24 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	1000 (+20/-20)						
	AFL	5820							
									PKG:5004
PROC. REF: AMM 52-12-00PROC. REF: AMM 52-12-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 52 - DOORS									
52-14-00-220-001-A00 S	INSPECT (DETAILED INSPECTION) MAIN DOOR DRAINING SYSTEM FOR OBSTRUCTION OR DAMAGE							Service	ATA:52
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 52-14-01PROC. REF: AMM 52-14-01									
52-21-00-220-801-L00 S	DETAILED INSPECTION (EXTERNAL) OF PASSENGER CABIN ESCAPE HATCH COMPONENTS:- ESCAPE HATCH STRUCTURE (SSI 52-21-06)- ESCAPE HATCH WINDOW FRAME (SSI 52-21-07)							Service	ATA:52
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 52-21-00PROC. REF: NDT 52-21-00									
52-21-00-220-802-L00 S	DETAILED INSPECTION (INTERNAL) OF PASSENGER CABIN ESCAPE HATCH COMPONENTS:- ESCAPE HATCH STRUCTURE (SSI 52-21-06)- ESCAPE HATCH WINDOW FRAME (SSI 52-21-07)							Service	ATA:52
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 52-21-00PROC. REF: NDT 52-21-00									
52-21-00-640-001-A00 S	LUBRICATE PASSENGER CABIN ESCAPE HATCH SUPPORT PINS							Service	ATA:52
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 52-21-00PROC. REF: AMM 52-21-00									
52-21-00-710-001-A00 S	OPERATIONALLY CHECK PASSENGER CABIN ESCAPE HATCH MECHANISM							Service	ATA:52
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 52-21-00PROC. REF: AMM 52-21-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 52 - DOORS									
52-22-00-710-001-A00 S	OPERATIONALLY CHECK COCKPIT EMERGENCY EXIT								Service ATA:52
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 56-11-00PROC. REF: AMM 56-11-00									
52-22-01-640-001-A00 S	LUBRICATE COCKPIT EMERGENCY EXIT LOCKING MECHANISM								Service ATA:52
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 56-11-01PROC. REF: AMM 56-11-01									
52-30-00-210-801-L00 S	GENERAL VISUAL INSPECTION (INTERNAL) OF BAGGAGE DOOR COMPONENTS:- BAGGAGE DOOR STRUCTURE (SSI 52-30-08)								Service ATA:52
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 52-30-00PROC. REF: NDT 52-30-00									
52-30-00-210-802-L00	GENERAL VISUAL INSPECTION (EXTERNAL) OF BAGGAGE DOOR COMPONENTS:- BAGGAGE DOOR STRUCTURE (SSI 52-30-08) (L650 ONLY)								Service ATA:52
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL	
	HRS	0							
	AFL	0							
									PKG:6032
PROC. REF: NDT 52-30-00PROC. REF: NDT 52-30-00									
52-30-00-210-C01-L00 S	GENERAL VISUAL INSPECTION (EXTERNAL) OF BAGGAGE DOOR COMPONENTS:- BAGGAGE DOOR STRUCTURE (SSI 52-30-08) (L600 ONLY)								Service ATA:52
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: CPM 52-30-00PROC. REF: CPM 52-30-00									

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 52 - DOORS									
52-30-00-220-801-L00	DETAILED INSPECTION (INTERNAL) OF BAGGAGE DOOR COMPONENTS:- BAGGAGE DOOR STOPS AND FIT- TINGS (SSI 52-30-09)NOTE: APPLICABLE TO AIRCRAFT PRE-MOD. SB145LEG-00-0007 (L600 ONLY)								Service ATA:52
	MOS/MSC	27-Aug-07	N/A					STRUCTURAL	
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: NDT 52-30-00PROC. REF: NDT 52-30-00									
52-30-00-220-801-L01 S	DETAILED INSPECTION (INTERNAL) OF BAGGAGE DOOR COMPONENTS:- BAGGAGE DOOR STOPS AND FITTINGS (SSI 52-30-09)NOTE: APPLICABLE TO AIRCRAFT POST-MOD. SB145LEG-00-0007 OR WITH AN EQUIVALENT MODIFICATION FACTORY INCORPORATED								Service ATA:52
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6016
PROC. REF: NDT 52-30-00PROC. REF: NDT 52-30-00									
52-31-00-640-001-A00 S	LUBRICATE BAGGAGE DOOR GEAR BOX								Service ATA:52
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 52-31-00PROC. REF: AMM 52-31-00									
52-32-00-220-001-A00 S	INSPECT (DETAILED INSPECTION) BAGGAGE DOOR LIFTING AND LOWERING MECHANISM FOR GENERAL CONDITION AND TORSION BAR FOR TORSION								Service ATA:52
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 52-32-00PROC. REF: AMM 52-32-00									
52-42-01-220-001-A00 S	INSPECT (DETAILED INSPECTION) COCKPIT UNDERFLOOR ACCESS HATCH MECHANISM								Service ATA:52
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 52-42-01PROC. REF: AMM 52-42-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 52 - DOORS									
52-44-00-220-801-L00 S	DETAILED INSPECTION (EXTERNAL) OF REAR ELECTRONIC COMPARTMENT DOOR COMPONENTS:- REAR ELECTRONIC COMPARTMENT DOOR STRUCTURE (SSI 52-44-01)							Service	ATA:52
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: NDT 52-44-00PROC. REF: NDT 52-44-00									
52-44-00-220-802-L00 S	DETAILED INSPECTION (INTERNAL) OF REAR ELECTRONIC COMPARTMENT DOOR COMPONENTS:- REAR ELECTRONIC COMPARTMENT DOOR STRUCTURE (SSI 52-44-01)							Service	ATA:52
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: NDT 52-44-00PROC. REF: NDT 52-44-00									
52-44-01-220-001-A00 S	INSPECT (DETAILED INSPECTION) REAR ELECTRONIC COMPARTMENT DOOR MECHANISM							Service	ATA:52
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 52-44-01PROC. REF: AMM 52-44-01									
52-71-00-710-001-A00 S	OPERATIONALLY CHECK FORWARD ELECTRONIC COMPARTMENT DOOR WARNING MESSAGE							Service	ATA:52
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 52-71-00PROC. REF: AMM 52-71-00									
52-72-00-710-001-A00 S	OPERATIONALLY CHECK RIGGING DOOR WARNING MESSAGE							Service	ATA:52
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 52-72-00PROC. REF: AMM 52-72-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 52 - DOORS									
52-73-00-710-001-A00 S	OPERATIONALLY CHECK MAIN DOOR WARNING MESSAGE							Service	ATA:52
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 52-73-00PROC. REF: AMM 52-73-00									
52-73-01-720-001-A00 S	FUNCTIONALLY CHECK MAIN DOOR WARNING MICROSWITCHES							Service	ATA:52
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 52-73-01PROC. REF: AMM 52-73-01									
52-75-00-710-001-A00 S	OPERATIONALLY CHECK EMERGENCY EXIT WARNING MESSAGE							Service	ATA:52
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 52-75-00PROC. REF: AMM 52-75-00									
52-76-00-710-001-A00 S	OPERATIONALLY CHECK BAGGAGE DOOR WARNING MESSAGE							Service	ATA:52
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 52-76-00PROC. REF: AMM 52-76-00									
52-77-00-710-001-A00 S	OPERATIONALLY CHECK REAR ELECTRONIC COMPARTMENT DOOR WARNING MESSAGE							Service	ATA:52
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 52-77-00PROC. REF: AMM 52-77-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 52 - DOORS									
52-Z811-213-001-A00 S	GENERAL VISUAL INSPECTION(EXTERNAL) (ZONE 811)							Service	ATA:52
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 05-30-03PROC. REF: AMM 05-30-03									
52-Z811-214-001-A00 S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONE 811)							Service	ATA:52
	MOS	17-Oct-25	24 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	1000 (+20/-20)						
	AFL	5820							
									PKG:5004
PROC. REF: AMM 05-30-04PROC. REF: AMM 05-30-04									
52-Z812-213-001-A00 S	GENERAL VISUAL INSPECTION(EXTERNAL) (ZONE 812 AND 822)							Service	ATA:52
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: AMM 05-30-05PROC. REF: AMM 05-30-05									
52-Z812-214-001-A00 S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONE 812 AND 822)							Service	ATA:52
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: AMM 05-30-06PROC. REF: AMM 05-30-06									
52-Z813-213-001-A00 S	GENERAL VISUAL INSPECTION(EXTERNAL) (ZONE 813)							Service	ATA:52
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 05-30-07PROC. REF: AMM 05-30-07									

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 52 - DOORS									
52-Z813-214-001-A00 S		GENERAL VISUAL INSPECTION(INTERNAL) (ZONE 813)							Service ATA:52
	MOS	17-Oct-25	24 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	1000 (+20/-20)						
	AFL	5820							
									PKG:5004
PROC. REF: AMM 05-30-08PROC. REF: AMM 05-30-08									
521000-0101		PAX CABIN DOOR							Component ATA:52
PN:135-12294-423	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:0000137963	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 52-10-01PROC. REF: AMM 52-10-01									
521001-0101		FORWARD PANEL, DOOR RELEASE CONTROL MODULE							Component ATA:52
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 52-10-01PROC. REF: AMM 52-10-01									
521100-0101		PAX DOOR DAMPER							Component ATA:52
PN:2119-0001-001	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:00610	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									
521100-0201		BOX LOCK ASSEMBLY							Component ATA:52
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 52-11-06PROC. REF: AMM 52-11-06									
521100-0202		BOX LOCK ASSEMBLY							Component ATA:52
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 52-11-06PROC. REF: AMM 52-11-06									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 52 - DOORS									
521200-0101	MID ACCUMULATOR -HYDRAULIC SYS, ELECTRONIC COMPT ASSEMBLY							Component	ATA:52
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
521200-0201	MID PRESSURE RELIEF VALVE ASSEMBLY							Component	ATA:52
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 52-12-07	PROC. REF: AMM 52-12-07								
521200-0301	MAIN DOOR HYDRAULIC PRESSURE SWITCH							Component	ATA:52
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
521200-0401	LEFT CHECK-TYPE RETAINER, HYDRAULIC SYSTEM VALVE							Component	ATA:52
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
521200-0501	MAIN DOOR - LIFTING AND LOWERING SYSTEM, ACCUMULATOR ISOLATION VALVE							Component	ATA:52
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
521200-0701	LEFT HYDRAULIC ASSY-DRIVING,PAX DOOR ACTUATOR							Component	ATA:52
PN:2106-0500-001	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:01048	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 52 - DOORS									
521200-0702		RIGHT HYDRAULIC ASSY-DRIVING,PAX DOOR ACTUATOR						Component	ATA:52
PN:2106-0500-001	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:01049	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									
522100-0101		RIGHT EMERGENCY DOOR ASSEMBLY						Component	ATA:52
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									
523000-0101		LH REAR CARGO COMPT, DOOR ASSEMBLY						Component	ATA:52
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 52-30-01PROC. REF: AMM 52-30-01									
524100-0101		BATTERY COMPARTMENT,FWD FUSELAGE, DOOR ASSEMBLY						Component	ATA:52
PN:145-37880-401	MOS/MSC	12-Aug-15	O/C	TSR 0					
SN:8975100440	HRS	7460.3		TSR 0					
	AFL	3992		TSR 0					
PROC. REF: AMM 52-41-00PROC. REF: AMM 52-41-00									
524100-0102		HYDRAULIC COMPARTMENT,FWD FUSELAGE, DOOR ASSEMBLY						Component	ATA:52
PN:145-47650-401	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:0000126092	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 52-41-00PROC. REF: AMM 52-41-00									
524200-0101		FORWARD ACCESS ASSY-FWD CONTROL FUSELAGE DOOR						Component	ATA:52
PN:145-29986-405	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:0000126044	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 52-46-00PROC. REF: AMM 52-46-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 52 - DOORS									
524400-0101	RH REAR STATION 00 ACCESS DOOR							Component	ATA:52
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 52-44-01	PROC. REF: AMM 52-44-01								
524400-0102	REAR EQUIPMENT BAY DOOR ASSY DOOR							Component	ATA:52
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
524400-0201	BAGGAGE COMPARTMENT DOOR ASSY							Component	ATA:52
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 52-30-01	PROC. REF: AMM 52-30-01								
528100-0101	LH DOOR -MLG UPPER ASSEMBLY							Component	ATA:52
PN:135-03284-404	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:0000127264	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
528100-0102	RH DOOR -MLG UPPER ASSEMBLY							Component	ATA:52
PN:135-03284-403	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:0000129935	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
528100-0103	LH DOOR -MLG LOWER ASSEMBLY							Component	ATA:52
PN:135-03285-401	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:0000127189	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 52 - DOORS									
528100-0104	RIGHT LW DOOR -MAIN LANDING GEAR,LOWER ASSEMBLY							Component	ATA:52
PN:135-03285-402	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:0000127875	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
528100-0201	LH DOOR ASSY							Component	ATA:52
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-10-06	PROC. REF: AMM 32-10-06								
528100-0202	RH DOOR ASSY							Component	ATA:52
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-10-06	PROC. REF: AMM 32-10-06								
528100-0301	LH LDG DOOR ASSY							Component	ATA:52
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-10-06	PROC. REF: AMM 32-10-06								
528100-0302	RH LDG DOOR ASSY							Component	ATA:52
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-10-06	PROC. REF: AMM 32-10-06								
ATA 53 - FUSELAGE									
53-00-01-220-001-A00 S	INSPECT (DETAILED INSPECTION) FUSELAGE DRAINS FOR OBSTRUCTION OR DAMAGE							Service	ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)				LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 53-00-01	PROC. REF: AMM 53-00-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-00-CUS-001	U	VISUAL INSPECTION XM SATELLITE RADIO INSTALLATION FOR CORROSION, WEAR AND TEAR, ATTACHMENT CONDITION, LOOSE ITEMS, AND THAT THE CONNECTING CABLES AND/OR ASSOCIATED WIRING IS NOT FRAYED, CUT OR PINCHED FOR THAT PARTICULAR COMPONENT AND IMMEDIATE SURROUNDING AREA.							Service ATA:53
	MOS	29-Jun-23	48		29-Jun-27		399 d		
	HRS	10161.5							
	AFL	5401							
53-00-CUS-002	U	SPECIAL INSPECTION XM RADIO ANTENNA INSTALLATIONS FOR THE FATIGUE LIFE EVALUATION AND EACHCRACK GROWTH MODEL OF THE DAMAGE TOLERANCE EVALUATION (DTE).							Service ATA:53
	MOS	15-Aug-13							
	HRS	6643.4							
	AFL	3572	T:10000		13572		7547		
53-00-CUS-003	U	LIFE LIMIT XM RADIO ANTENNA INSTALLATIONS							Service ATA:53
	MOS	15-Aug-13							
	HRS	6643.4							
	AFL	3572	T:20000		23572		17547		
53-00-CUS-004	U	INSPECTION FEED THRU INSTALLATION							Service ATA:53
	MOS	19-Feb-20							
	HRS	9310.8	T:8000		17310.8		6034.5		
	AFL	4969	T:4000		8969		2944		
53-00-CUS-005	U S	VISUAL INSPECTION OF THE MK II+ CMU, TR-866B VDR, AND DL150 LRUS							Service ATA:53
	MOS	29-Jun-23	48						
	HRS	10161.5	2000						
	AFL	5401	1000						
									PKG:5008

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-00-CUS-006 U S		VISUAL INSPECTION OF WIRING INSTALLATION OF THE MK II+ CMU, TR-866B VDR, AND DL150 LRUS						Service	ATA:53
	MOS	29-Jun-23	48						
	HRS	10161.5	2000						
	AFL	5401	1000						
									PKG:5008
53-11-00-210-C01-L00 S		GENERAL VISUAL INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- BULKHEAD 1 STRUCTURE (SSI 53-10-23)- BATTERY COMPARTMENT CUT- OUT STRUCTURE(SSI 53-10-44)- HYDRAULIC COMPARTMENT CUTOUT STRUCTURE (SSI 53-10-45)- LONGERONS (SSI 53-10-46)						Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)				LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: CPM 53-11-00PROC. REF: CPM 53-11-00									
53-11-00-210-C02-L00 S		GENERAL VISUAL INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/BULKHEADS, AND SPLICES (SSI 53-10-07)- FUSELAGE SKIN PANEL AT PRESSURE BULKHEAD(SSI 53-10-15)						Service	ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)				LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5009
PROC. REF: CPM 53-11-00PROC. REF: CPM 53-11-00									
53-11-00-220-801-L00 S		DETAILED INSPECTION (INTERNAL)OF FUSELAGE COMPONENTS:- FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/ BULKHEADS, AND SPLICES (SSI 53-10-07)						Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)				LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 53-11-00PROC. REF: NDT 53-11-00									
53-11-00-220-C01-L00 S		DETAILED INSPECTION (INTERNAL)OF FUSELAGE COMPONENTS:- NOSE LANDING GEAR FITTING, INCLUDING BEARING CAP AND TRUNNION FITTING (SSI 53-10-25)						Service	ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)				LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: CPM 53-11-00PROC. REF: CPM 53-11-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-11-00-220-C02-L00 S	DETAILED INSPECTION (INTERNAL)OF FUSELAGE COMPONENTS:- FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/BULKHEADS, AND SPLICES (SSI 53-10-07)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: CPM 53-11-00PROC. REF: CPM 53-11-00									
53-11-00-220-C03-L00 S	DETAILED INSPECTION (INTERNAL)OF FUSELAGE COMPONENTS:- FUSELAGE SKIN CIRCUMFERENTIAL SPLICE(SSI 53-10-14)- FUSELAGE SKIN PANEL AT PRESSURE BULKHEAD(SSI 53-10-15)- FRAMES (SSI 53-10-43)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: CPM 53-11-00PROC. REF: CPM 53-11-00									
53-11-00-220-C04-L00 S	DETAILED INSPECTION (INTERNAL)OF FUSELAGE COMPONENTS:- FUSELAGE SKIN LONGITUDINAL SPLICE (SSI 53-10-08)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: CPM 53-11-00PROC. REF: CPM 53-11-00									
53-11-00-220-C05-L00 S	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- NOSE LANDING GEAR BAY STRUCTURE (SSI 53-10-24)							Service	ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5009
PROC. REF: CPM 53-11-00PROC. REF: CPM 53-11-00									
53-11-00-220-C06-L00 S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- NOSE LANDING GEAR BAY STRUCTURE (SSI 53-10-24)							Service	ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5009
PROC. REF: CPM 53-11-00PROC. REF: CPM 53-11-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-11-00-250-801-L00 S	SPECIAL DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS BY USING EDDY CURRENT INSPECTION METHOD:- NOSE LANDING GEAR FITTING,INCLUDING BEARING CAP AND TRUNNION FITTING (SSI 53-10-25)							Service	ATA:53
	MOS	27-Aug-07	288 (+15d/-15d)					LOW UTILIZATION	
	HRS	0	12000 (+20/-20)						
	AFL	0	6000 (+20/-20)						
									PKG:5140
PROC. REF: NDT 53-11-00PROC. REF: NDT 53-11-00									
53-11-01-220-001-A00 S	INSPECT (DETAILED INSPECTION) THE PRESENCE OF WATER ON THE RADOME							Service	ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 53-11-01PROC. REF: AMM 53-11-01									
53-11-05-212-001-A00 S	INSPECT (VISUAL INSPECTION) THE RADOME POLYURETHANE FILM							Service	ATA:53
	MOS	17-Oct-25	24 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	1000 (+20/-20)						
	AFL	5820							
									PKG:5004
PROC. REF: AMM 53-11-05PROC. REF: AMM 53-11-05									
53-12-00-210-801-L00 S	GENERAL VISUAL INSPECTION (INTERNAL) OF FUSELAGE COM- PONENTS:- WINDSHIELD PANEL (SSI 53-10-21)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 53-12-00PROC. REF: NDT 53-12-00									
53-12-00-210-802-L00	GENERAL VISUAL INSPECTION(EXTERNAL) OF FUSELAGE COMPONENTS:- WINDSHIELD PANEL (SSI 53-10-21) (L650 ONLY)							Service	ATA:53
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL	
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: NDT 53-12-00PROC. REF: NDT 53-12-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-12-00-210-C01-L00 S	GENERAL VISUAL INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/BULK-HEADS, AND SPLICES (SSI 53-10-07)							Service	ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5009
PROC. REF: CPM 53-12-00PROC. REF: CPM 53-12-00									
53-12-00-210-C02-L00 S	GENERAL VISUAL INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN PANEL AT PRESSURE BULKHEAD(SSI 53-10-15)							Service	ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5009
PROC. REF: CPM 53-12-00PROC. REF: CPM 53-12-00									
53-12-00-210-C04-L00 S	GENERAL VISUAL INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- WINDSHIELD PANEL (SSI 53-10-21) (L600 ONLY)							Service	ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: CPM 53-12-00PROC. REF: CPM 53-12-00									
53-12-00-210-C05-L00 S	GENERAL VISUAL INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- MAINTENANCE DOOR CUTOUT STRUCTURE (SSI 53-10-49)							Service	ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5009
PROC. REF: CPM 53-12-00PROC. REF: CPM 53-12-00									
53-12-00-220-801-L00 S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- WINDSHIELD CUTOUT STRUCTURE (SSI 53-10-17)- COCKPIT WINDOW CUTOUT STRUCTURE (SSI 53-10-18)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 53-12-00PROC. REF: NDT 53-12-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-12-00-220-802-L00 S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- WINDSHIELD CENTER POST AND ITS ATTACHMENT (SSI 53-10-19)							Service	ATA:53
	MOS	12-Jul-15	192 (+15d/-15d)					LOW UTILIZATION	
	HRS	7460.3	8000 (+20/-20)						
	AFL	3992	4000 (+20/-20)						
									PKG:5032,6032
PROC. REF: NDT 53-12-00PROC. REF: NDT 53-12-00									
53-12-00-220-803-L00 S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- WINDSHIELD LATERAL POST AND ITS ATTACHMENT (SSI 53-10-20)- COCKPIT WINDOW REAR POST AND ITS ATTACHMENT (SSI 53-10-22)							Service	ATA:53
	MOS	12-Jul-15	192 (+15d/-15d)					LOW UTILIZATION	
	HRS	7460.3	8000 (+20/-20)						
	AFL	3992	4000 (+20/-20)						
									PKG:5032,6032
PROC. REF: NDT 53-12-00PROC. REF: NDT 53-12-00									
53-12-00-220-804-L00 S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- FORWARD PRESSURE BULKHEAD (SSI 53-10-26)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 53-12-00PROC. REF: NDT 53-12-00									
53-12-00-220-805-L00 S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/ BULKHEADS, AND SPLICES (SSI 53-10-07)- FUSELAGE SKIN LONGITUDINAL SPLICE (SSI 53-10-08)- FUSELAGE SKIN PANEL AT PRESSURE BULKHEAD (SSI 53-10-15)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 53-12-00PROC. REF: NDT 53-12-00									
53-12-00-220-806-L00 S	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- COCKPIT WINDOW CUTOUT STRUCTURE (SSI 53-10-18)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6016
PROC. REF: NDT 53-12-00PROC. REF: NDT 53-12-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-12-00-220-807-L00 S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/ BULKHEADS, AND SPLICES (SSI 53-10-07)- FUSELAGE SKIN LONGITUDINAL SPLICE (SSI 53-10-08)								Service ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 53-12-00PROC. REF: NDT 53-12-00									
53-12-00-220-808-L00 S	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- COCKPIT WINDOW REAR POST AND ITS ATTACHMENT (SSI 53-10-22)								Service ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6016
PROC. REF: NDT 53-12-00PROC. REF: NDT 53-12-00									
53-12-00-220-809-L00 S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- COCKPIT FLOOR BEAMS AND COL- UMNS (SSI 53-10-27)NOTE: APPLICABLE TO AIRCRAFT POST-MOD. S.B.145LEG-00-0007 OR WITH AN EQUIVALENT MODIFICATION FACTORY INCORPORATED								Service ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 53-12-00PROC. REF: NDT 53-12-00									
53-12-00-220-C01-L00 S	DETAILED INSPECTION (INTERNAL)OF FUSELAGE COMPONENTS:- FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/BULKHEADS, AND SPLICES (SSI 53-10-07)								Service ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: CPM 53-12-00PROC. REF: CPM 53-12-00									
53-12-00-220-C02-L00 S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN CIRCUMFERENTIAL SPLICE(SSI 53-10-14)-FRAMES (SSI 53-10-43)								Service ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: CPM 53-12-00PROC. REF: CPM 53-12-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-12-00-220-C03-L00 S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- COCKPIT FLOOR BEAMS AND COLUMNS (SSI 53-10-27)-MAINTENANCE DOOR CUTOUT STRUCTURE (SSI 53-10-49)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: CPM 53-12-00PROC. REF: CPM 53-12-00									
53-12-00-220-C04-L00 S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN PANEL AT PRESSURE BULKHEAD(SSI 53-10-15)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: CPM 53-12-00PROC. REF: CPM 53-12-00									
53-12-00-250-804-L00	SPECIAL DETAILED INSPECTION (INTERNAL) OF FUSELAGE COM- PONENTS BY USING EDDY CUR- RENT INSPECTION METHOD:-WINDSHIELD CENTER POST, INCLUDING ITS ATTACHMENTS AND LOWER FITTING (SSI 53-10-19)NOTE: APPLICABLE TO AIRCRAFT PRE -MOD. S.B.145LEG-00-0007 AND PRE-MOD. S.B.145LEG-53-0021 (L600 ONLY)							Service	ATA:53
	MOS/MSC	27-Aug-07	N/A					STRUCTURAL	
	HRS	0							
	AFL	0							
PROC. REF: NDT 53-12-00PROC. REF: NDT 53-12-00									
53-12-00-250-804-L01	SPECIAL DETAILED INSPECTION (INTERNAL) OF FUSELAGE COM- PONENTS BY USING EDDY CUR- RENT INSPECTION METHOD:-WINDSHIELD CENTER POST, INCLUDING ITS ATTACHMENTS AND LOWER FITTING (SSI 53-10-19)NOTE: APPLICABLE TO AIRCRAFT PRE -MOD. S.B.145LEG-00-0007 AND POST-MOD. S.B. 145LEG-53-0021 OR WITH AN EQUIVALENT MODIFICATION FACTORY INCORPORATED (L600 ONLY)							Service	ATA:53
	MOS/MSC	27-Aug-07	N/A						
	HRS	0							
	AFL	0							
PROC. REF: NDT 53-12-00PROC. REF: NDT 53-12-00									

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-12-00-250-804-L02	SPECIAL DETAILED INSPECTION (INTERNAL) OF FUSELAGE COM- PONENTS BY USING EDDY CUR- RENT INSPECTION METHOD:- WINDSHIELD CENTER POST, INCLUDING ITS ATTACHMENTS AND LOWER FITTING (SSI 53-10-19)NOTE: APPLICABLE TO AIRCRAFT POST-MOD. S.B.145LEG-00-0007 OR WITH AN EQUIVALENT MODIFICATION FACTORY-INCORPORATED AND PRE-MOD. S.B. 145LEG-53-0021 (L600 ONLY)								Service	ATA:53
	MOS/MSC	27-Aug-07	N/A						
	HRS	0							
	AFL	0							
									PKG:6008
PROC. REF: NDT 53-12-00PROC. REF: NDT 53-12-00									
53-12-00-250-804-L03 S	SPECIAL DETAILED INSPECTION (INTERNAL) OF FUSELAGE COM- PONENTS BY USING EDDY CUR- RENT INSPECTION METHOD:- WINDSHIELD CENTER POST, INCLUDING ITS ATTACHMENTS AND LOWER FITTING (SSI 53-10-19)NOTE: APPLICABLE TO AIRCRAFT POST-MOD. S.B.145LEG-00-0007 AND POST-MOD. S.B. 145LEG-53-0021 OR WITH AN EQUIVALENT MODIFICATION FACTORY-INCORPORATED								Service	ATA:53
	MOS	17-Jul-15	192 (+15d/-15d)					LOW UTILIZATION	
	HRS	7460.3	8000 (+20/-20)						
	AFL	3992	4000 (+20/-20)						
									PKG:5032,6032
PROC. REF: NDT 53-12-00PROC. REF: NDT 53-12-00									
53-12-00-250-805-L00	SPECIAL DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENT BY USING EDDY CURRENT INSPECTION METHOD:- WINDSHIELD LATERAL POST AND ITS ATTACHMENT (SSI 53-10-20).NOTE: APPLICABLE TO AIRCRAFT PRE-MOD. S.B.145LEG-00-0007 AND PRE-MOD. S.B. 145LEG-53-0030. (L600 ONLY)								Service	ATA:53
	MOS/MSC	29-Jun-15	N/A						
	HRS	7460.3							
	AFL	3992							
PROC. REF: NDT 53-12-00PROC. REF: NDT 53-12-00									
53-12-00-250-806-L00	SPECIAL DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENT BY USING EDDY CURRENT INSPECTION METHOD:- WINDSHIELD LATERAL POST AND ITS ATTACHMENT (SSI 53-10-20).NOTE: APPLICABLE TO AIRCRAFT POST-MOD. S.B.145LEG-00-0007 OR WITH AN EQUIVALENT MODIFICATION FACTORY-INCORPO- RATED AND PRE-MOD. S.B.145LEG-53-0030.								Service	ATA:53
	MOS/MSC	27-Aug-07	N/A						
	HRS	0							
	AFL	0							
PROC. REF: NDT 53-12-00PROC. REF: NDT 53-12-00									

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-12-00-250-807-L00	SPECIAL DETAILED INSPECTION (INTERNAL) OF FUSELAGE COM- PONENT BY USING EDDY CURRENT INSPECTION METHOD:- WINDSHIELD LATERAL POST AND ITS ATTACHMENT (SSI 53-10-20).NOTE: APPLICABLE TO AIRCRAFT PRE-MOD. S.B.145LEG-00-0007 AND PRE-MOD. S.B.145LEG-53-0030. (L600 ONLY)								Service ATA:53
	MOS/MSC	27-Aug-07	N/A						
	HRS	0							
	AFL	0							
PROC. REF: NDT 53-12-00PROC. REF: NDT 53-12-00									
53-12-00-250-808-L00	SPECIAL DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENT BY USING EDDY CURRENT INSPECTION METHOD:- WINDSHIELD LATERAL POST AND ITS ATTACHMENT (SSI 53-10-20).NOTE: APPLICABLE TO AIRCRAFT POST-MOD. S.B.145LEG-00-0007 OR WITH AN EQUIVALENT MODIFICATION FACTORY-INCORPORATED AND PRE-MOD. S.B.145LEG-53-0030.								Service ATA:53
	MOS/MSC	27-Aug-07	N/A						
	HRS	0							
	AFL	0							
PROC. REF: NDT 53-12-00PROC. REF: NDT 53-12-00									
53-12-00-250-809-L00	SPECIAL DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENT BY USING EDDY CURRENT INSPECTION METHOD:- WINDSHIELD LATERAL POST AND ITS ATTACHMENT (SSI 53-10-20).NOTE: APPLICABLE TO AIRCRAFT PRE-MOD. S.B.145LEG-00-0007 AND POST-MOD. S.B.145LEG-53-0030 OR WITH AN EQUIVALENT MODIFICATION FACTORY-INCORPORATED. (L600 ONLY)								Service ATA:53
	MOS/MSC	27-Aug-07	N/A						
	HRS	0							
	AFL	0							
PROC. REF: NDT 53-12-00PROC. REF: NDT 53-12-00									
53-12-00-250-810-L00 S	SPECIAL DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENT BY USING EDDY CURRENT INSPECTION METHOD:- WINDSHIELD LATERAL POST AND ITS ATTACHMENT (SSI 53-10-20).NOTE: APPLICABLE TO AIRCRAFT POST-MOD. S.B.145LEG-00-0007 OR WITH AN EQUIVALENT MODIFICATION FACTORY-INCORPO- RATED AND POST- MOD. S.B.145LEG-53-0030 OR WITH AN EQUIVALENT MODIFICATION FACTORY INCORPORATED.								Service ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5017
PROC. REF: NDT 53-12-00PROC. REF: NDT 53-12-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-21-00-210-C01-L00 S	GENERAL VISUAL INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- MAIN DOOR ATTACHMENTS FITTINGS AND INTERFACE PARTS(SSI 53-20-04)							Service	ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: CPM 53-21-00PROC. REF: CPM 53-21-00									
53-21-00-210-C02-L00 S	GENERAL VISUAL INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- MAIN DOOR ATTACHMENTS FIT- TINGS AND INTERFACE PARTS (SSI 53-20-04)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: CPM 53-21-00PROC. REF: CPM 53-21-00									
53-21-00-220-801-L00 S	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- PASSENGER DOOR CUTOUT REIN- FORCING STRUCTURES (SSI 53-20-09)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6016
PROC. REF: NDT 53-21-00PROC. REF: NDT 53-21-00									
53-21-00-220-802-L00 S	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- STOPS AND BACKUP STRUC- TURES FOR MAIN DOOR (SSI 53-20-01)							Service	ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: NDT 53-21-00PROC. REF: NDT 53-21-00									
53-21-00-220-803-L00 S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- STOPS AND BACKUP STRUC- TURES FOR MAIN DOOR (SSI 53-20-01)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI							Service	ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: NDT 53-21-00PROC. REF: NDT 53-21-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-21-00-220-804-L00 S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/ BULKHEADS, AND SPLICES (SSI 53-20-07)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 53-21-00PROC. REF: NDT 53-21-00									
53-21-00-220-805-L00 S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- FRAME 15 & 18 LHS SPLICES AT STRINGERS 3L & 16L (SSI 53-20-12) NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 53-21-00PROC. REF: NDT 53-21-00									
53-21-00-220-806-L00	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- PASSENGER CABIN WINDOW FRAME (SSI 53-20-06)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSINOTE: IF INSTALLED IN THE ZONE. (L600 ONLY)							Service	ATA:53
	MOS/MSC	27-Aug-07	N/A					STRUCTURAL	
	HRS	0							
	AFL	0							
									PKG:6032
PROC. REF: NDT 53-21-00PROC. REF: NDT 53-21-00									
53-21-00-220-807-L00 S	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- FRAME 15 & 18 LHS SPLICES AT STRINGERS 3L & 16L (SSI 53-20-12)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6016
PROC. REF: NDT 53-21-00PROC. REF: NDT 53-21-00									
53-21-00-220-808-L00 S	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- PASSENGER CABIN WINDOW FRAME (SSI 53-20-06) NOTE: IF INSTALLED IN THE ZONE. (L600 ONLY)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6016
PROC. REF: NDT 53-21-00PROC. REF: NDT 53-21-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-21-00-220-810-L00 S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- PASSENGER DOOR CUTOUT REINFORCING STRUCTURES (SSI 53-20-09)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI								Service ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 53-21-00PROC. REF: NDT 53-21-00									
53-21-00-220-811-L00 S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN LONGITUDINAL SPLICES AT MAIN DOOR CUTOUT (SSI 53-20-41)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI								Service ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 53-21-00PROC. REF: NDT 53-21-00									
53-21-00-220-812-L00 S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/ BULKHEADS, AND SPLICES (SSI 53-20-07)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI								Service ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: NDT 53-21-00PROC. REF: NDT 53-21-00									
53-21-00-220-813-L00 S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- MACHINED SHEAR CLIP AT FRAMES 23, 33 AND 35 (SSI 53-20-79)								Service ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 53-21-00PROC. REF: NDT 53-21-00									
53-21-00-220-814-L00 S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN LONGITUDINAL SPLICE (SSI 53-20-08)NOTE: DURING THIS INSPEC-TION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR (SSI 53-20-08) (L600 ONLY)								Service ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5009
PROC. REF: NDT 53-21-00PROC. REF: NDT 53-21-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-21-00-220-816-L00 S	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- FORWARD AUXILIARY FUEL TANK FITTING, DOUBLER AND PIN AT FRAMES 23, 33 AND 35 (SSI53-20-82)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 53-21-00PROC. REF: NDT 53-21-00									
53-21-00-220-818-L00 S	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/ BULKHEADS, AND SPLICES (SSI 53-20-07) NOTE: DO NOT REMOVE THE FUEL TANK							Service	ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008
PROC. REF: NDT 53-21-00PROC. REF: NDT 53-21-00									
53-21-00-220-819-L00	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN LONGITUDINAL SPLICE (SSI 53-20-08)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR (SSI 53-20-08). (L650 ONLY)							Service	ATA:53
	MOS/MSC	27-Aug-07	N/A						
	HRS	0							
	AFL	0							
PROC. REF: NDT 53-21-00PROC. REF: NDT 53-21-00									
53-21-00-220-C01-L00 S	GENERAL VISUAL INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- PASSENGER CABIN FLOOR BEAMS AND COLUMNS (SSI 53-20-11)							Service	ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: CPM 53-21-00PROC. REF: CPM 53-21-00									
53-21-02-640-001-A00 S	LUBRICATE MAIN DOOR FRAME ROLLERS							Service	ATA:53
	MOS	17-Oct-25	12 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	500 (+20/-20)						
	AFL	5820							
									PKG:5002
PROC. REF: AMM 53-21-02PROC. REF: AMM 53-21-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-22-00-210-801-L00 S	GENERAL VISUAL INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/BULK-HEADS, AND SPLICES (SSI 53-20-07)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 53-22-00PROC. REF: NDT 53-22-00									
53-22-00-210-802-L00 S	GENERAL VISUAL INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/BULK-HEADS, AND SPLICES (SSI 53-20-07)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 53-22-00PROC. REF: NDT 53-22-00									
53-22-00-210-803-L00 S	GENERAL VISUAL INSPECTION (INTERNAL) OF FUSELAGE COM- PONENTS:- MACHINED SHEAR CLIP AT FRAMES 23, 33 AND 35 (SSI 53-20-79)- MACHINED SHEAR CLIP AT FRAMES 25 AND 31 (SSI 53-20-80)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 53-22-00PROC. REF: NDT 53-22-00									
53-22-00-210-804-L00 S	GENERAL VISUAL INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/BULK-HEADS, AND SPLICES (SSI 53-20-07)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 53-22-00PROC. REF: NDT 53-22-00									
53-22-00-210-805-L00 S	GENERAL VISUAL INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- FORWARD AUXILIARY FUEL TANK (SSI 53-20-81)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 53-22-00PROC. REF: NDT 53-22-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-22-00-210-806-L00 S	GENERAL VISUAL INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- FORWARD AUXILIARY FUEL TANK (SSI 53-20-81)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 53-22-00PROC. REF: NDT 53-22-00									
53-22-00-220-802-L00 S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/ BULKHEADS, AND SPLICES (SSI 53-20-07)- FUSELAGE SKIN CIRCUMFERENTIAL SPLICE (SSI 53-20-14)- FRAMES (SSI 53-20-43)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 53-22-00PROC. REF: NDT 53-22-00									
53-22-00-220-804-L00 S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN LONGITUDINAL SPLICE (SSI 53-20-08)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 53-22-00PROC. REF: NDT 53-22-00									
53-22-00-220-806-L00 S	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- FORWARD AUXILIARY FUEL TANK FITTING, DOUBLER AND PIN AT FRAMES 23, 33 AND 35 (SSI53-20-82)- FORWARD AUXILIARY FUEL TANK FITTING, DOUBLER AND PIN AT FRAMES 25 AND 31 (SSI 53-20 -83)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 53-22-00PROC. REF: NDT 53-22-00									
53-22-00-220-807-L00 S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- PASSENGER CABIN WINDOW FRAME (SSI 53-20-06)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 53-22-00PROC. REF: NDT 53-22-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-22-00-220-808-L00 S	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- MACHINED SHEAR CLIP AT FRAMES 23, 33 AND 35 (SSI 53-20-79)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 53-22-00PROC. REF: NDT 53-22-00									
53-22-00-220-C01-L00 S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- PASSENGER CABIN FLOOR BEAMS AND COLUMNS (SSI 53-20-11)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: CPM 53-22-00PROC. REF: CPM 53-22-00									
53-23-00-210-801-L00 S	GENERAL VISUAL INSPECTION (INTERNAL) OF FUSELAGE COM- PONENTS:- OVERWING FUSELAGE SKIN PANEL (SSI 53-20-16)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 53-23-00PROC. REF: NDT 53-23-00									
53-23-00-210-804-L00 S	GENERAL VISUAL INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- OVERWING FUSELAGE SKIN PANEL (SSI 53-20-16)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 53-23-00PROC. REF: NDT 53-23-00									
53-23-00-210-C02-L00 S	GENERAL VISUAL INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- PASSENGER CABIN WINDOW FRAME (SSI 53-20-06)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: CPM 53-23-00PROC. REF: CPM 53-23-00									

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-23-00-220-801-L00 S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE MACHINED BULKHEAD (SSI 53-20-30)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR ZONES 151/152 AND 153/154							Service	ATA:53
	MOS	27-Aug-07	288 (+15d/-15d)					LOW UTILIZATION	
	HRS	0	12000 (+20/-20)						
	AFL	0	6000 (+20/-20)						
									PKG:5140
PROC. REF: NDT 53-23-00PROC. REF: NDT 53-23-00									
53-23-00-220-802-L00 S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/ BULKHEADS, AND SPLICES (SSI 53-20-07)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 53-23-00PROC. REF: NDT 53-23-00									
53-23-00-220-803-L00 S	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- SKIN AND REINFORCEMENT AROUND ESCAPE HATCH CUTOUT (SSI 53-20-51)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6016
PROC. REF: NDT 53-23-00PROC. REF: NDT 53-23-00									
53-23-00-220-804-L00 S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- FRAMES (SSI 53-20-43)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 53-23-00PROC. REF: NDT 53-23-00									
53-23-00-220-805-L00 S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- FRAMES (SSI 53-20-43)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 53-23-00PROC. REF: NDT 53-23-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-23-00-220-806-L00 S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE MACHINED BULK- HEAD (SSI 53-20-30)- FRAMES (SSI 53-20-43)- SKIN AND REINFORCEMENT AROUND ESCAPE HATCH CUTOUT (SSI 53-20-51)- FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/ BULKHEADS, AND SPLICES (SSI 53-20-07)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR (SSI 53-20-30)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)				LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 53-23-00PROC. REF: NDT 53-23-00									
53-23-00-220-808-L00	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/ BULKHEADS, AND SPLICES (SSI 53-20-07)NOTE: APPLICABLE TO AIRCRAFT PRE-MOD. S.B.145LEG-00-0007 (L600 ONLY)							Service	ATA:53
	MOS/MSC	15-Aug-13	N/A						
	HRS	6643.4							
	AFL	3572							
									PKG:6016
PROC. REF: NDT 53-23-00PROC. REF: NDT 53-23-00									
53-23-00-220-808-L01 S	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/ BULK-HEADS, AND SPLICES (SSI 53-20-07)NOTE: APPLICABLE TO AIRCRAFT POST-MOD. S.B.145LEG-00-0007 OR WITH AN EQUIVALENT MODIFICATION FACTORY-INCORPORATED.							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)				LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 53-23-00PROC. REF: NDT 53-23-00									
53-23-00-220-809-L00	DETAILED INSPECTION (EXTERNAL)OF FUSELAGE COMPONENTS:- FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/ BULKHEADS, AND SPLICES (SSI 53-20-07)NOTE: APPLICABLE TO AIRCRAFT PRE-MOD. S.B.145LEG-00-0007 (L600 ONLY)							Service	ATA:53
	MOS/MSC	15-Aug-13	N/A						
	HRS	6643.4							
	AFL	3572							
									PKG:6016
PROC. REF: NDT 53-23-00PROC. REF: NDT 53-23-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-23-00-220-810-L00		DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- MACHINED FRAME AT VENTRAL FUEL TANK ATTACHMENT POINTS (SSI 53-20-84) (L650 ONLY)							Service ATA:53
	MOS/MSC	27-Aug-07	N/A						
	HRS	0							
	AFL	0							
									PKG:6032
PROC. REF: NDT 53-23-00PROC. REF: NDT 53-23-00									
53-23-00-220-811-L00 S		DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- PASSENGER CABIN FLOOR BEAMS AND COLUMNS (SSI 53-20-11) NOTE: APPLICABLE TO AIRCRAFT PRE-MOD. S.B.145LEG-00-0007. (L600 ONLY)							Service ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 53-23-00PROC. REF: NDT 53-23-00									
53-23-00-220-811-L01 S		DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- PASSENGER CABIN FLOOR BEAMS AND COLUMNS (SSI 53-20-11) NOTE: APPLICABLE TO AIRCRAFT POST-MOD. S.B.145LEG-00-0007 OR WITH AN EQUIVALENT MODIFICATION FACTORY-INCORPORATED.							Service ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 53-23-00PROC. REF: NDT 53-23-00									
53-23-00-220-812-L00		DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/BULKHEADS, AND SPLICES (SSI 53-20-07). (L650 ONLY)							Service ATA:53
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL	
	HRS	0							
	AFL	0							
									PKG:6032
PROC. REF: NDT 53-23-00PROC. REF: NDT 53-23-00									
53-23-00-220-C01-L00 S		DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/BULKHEADS, AND SPLICES (SSI 53-20-07)							Service ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
PROC. REF: CPM 53-23-00PROC. REF: CPM 53-23-00									
53-23-00-220-C03-L00 S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN LONGITUDINAL SPLICE (SSI 53-20-08)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)				LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: CPM 53-23-00PROC. REF: CPM 53-23-00									
53-23-00-220-C04-L00 S	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/BULKHEADS, AND SPLICES (SSI 53-20-07) (L600 ONLY)							Service	ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)				LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: CPM 53-23-00PROC. REF: CPM 53-23-00									
53-23-00-250-801-L00	SPECIAL DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENT BY USING EDDY CURRENT HIGH FREQUENCY INSPECTION METHOD:- PASSENGER CABIN WINDOW FRAME (SSI 53-20-06)NOTE: APPLICABLE TO AIRCRAFT PRE-MOD. S.B.145LEG-00-0007 (L600 ONLY)							Service	ATA:53
	MOS/MSC	27-Aug-07	N/A						
	HRS	0							
	AFL	0							
PROC. REF: NDT 53-23-00PROC. REF: NDT 53-23-00									
53-24-00-210-C01-L00 S	GENERAL VISUAL INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- PASSENGER CABIN WINDOW FRAME (SSI 53-20-06)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)				LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: CPM 53-24-00PROC. REF: CPM 53-24-00									
53-24-00-210-C07-L00	GENERAL VISUAL INSPECTION (EXTERNAL) OF VENTRAL FUEL TANK COMPONENTS - VENTRAL FUEL TANK STRUCTURE (SSI 53-20-85) - FRONTAL SIDE OF VENTRAL FUEL TANK STRUCTURE (SSI 53-20-87) (L650 ONLY)							Service	ATA:53
	MOS/MSC	27-Aug-07	N/A						
	HRS	0							
	AFL	0							
									PKG:6032

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
PROC. REF: CPM 53-24-00PROC. REF: CPM 53-24-00									
53-24-00-220-801-L00 S	DETAILED INSPECTION (INTERNAL)OF FUSELAGE COMPONENTS:- FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/ BULKHEADS, AND SPLICES (SSI 53-20-07)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 53-24-00PROC. REF: NDT 53-24-00									
53-24-00-220-802-L00 S	DETAILED INSPECTION (INTERNAL)OF FUSELAGE COMPONENTS:- FUSELAGE SKIN LONGITUDINAL SPLICE (SSI 53-20-08)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 53-24-00PROC. REF: NDT 53-24-00									
53-24-00-220-803-L00 S	DETAILED INSPECTION (INTERNAL)OF FUSELAGE COMPONENTS:- FUSELAGE SKIN CIRCUMFERENTIAL SPLICE(SSI 53-20-14)- FRAMES (SSI 53-20-43) (L600 ONLY)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016
PROC. REF: NDT 53-24-00PROC. REF: NDT 53-24-00									
53-24-00-220-804-L00 S	DETAILED INSPECTION (INTERNAL)OF FUSELAGE COMPONENTS:- FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/ BULKHEADS, AND SPLICES (SSI 53-20-07)- FUSELAGE SKIN LONGITUDINAL SPLICE (SSI 53-20-08)NOTE: APPLICABLE TO AIRCRAFT PRE-MOD. S.B.145LEG-00-0007 (L600 ONLY)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 53-24-00PROC. REF: NDT 53-24-00									

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-24-00-220-805-L00 S	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/ BULKHEADS, AND SPLICES (SSI 53-20-07) (L600 ONLY)								Service ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: NDT 53-24-00PROC. REF: NDT 53-24-00									
53-24-00-220-813-L00	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- MACHINED FRAME AT VENTRAL FUEL TANK ATTACHMENT POINTS (SSI 53-20-84) (L650 ONLY)								Service ATA:53
	MOS/MSC	27-Aug-07	N/A						
	HRS	0							
	AFL	0							
									PKG:6032
PROC. REF: NDT 53-24-00PROC. REF: NDT 53-24-00									
53-24-00-220-814-L00	DETAILED INSPECTION (EXTERNAL) OF VENTRAL FUEL TANK COMPONENTS:- VENTRAL FUEL TANK ATTACHMENT POINTS, INCLUDING MAIN BOLTS (SSI 53-20-86) (L650 ONLY)								Service ATA:53
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL	
	HRS	0							
	AFL	0							
									PKG:6032
PROC. REF: NDT 53-24-00PROC. REF: NDT 53-24-00									
53-24-00-220-815-L00	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN CIRCUMFEREN- TIAL SPLICE(SSI 53-20-14) FRAMES (SSI 53-20-43) (L650 ONLY)								Service ATA:53
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL	
	HRS	0							
	AFL	0							
									PKG:6032
PROC. REF: NDT 53-24-00PROC. REF: NDT 53-24-00									
53-24-00-220-816-L00	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/ BULKHEADS, AND SPLICES (SSI 53-20-07) (L650 ONLY)								Service ATA:53
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL	
	HRS	0							
	AFL	0							
PROC. REF: NDT 53-24-00PROC. REF: NDT 53-24-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-24-00-220-C01-L00 S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/BULKHEADS, AND SPLICES (SSI 53-20-07)							Service	ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: CPM 53-24-00PROC. REF: CPM 53-24-00									
53-24-00-220-C02-L00 S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- PASSENGER CABIN FLOOR BEAMS AND COLUMNS(SSI 53-20-11)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: CPM 53-24-00PROC. REF: CPM 53-24-00									
53-24-00-220-C03-L00 S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/BULKHEADS, AND SPLICES (SSI53-20-07).NOTE: APPLICABLE TO AIRCRAFT POST-MOD. S.B. 145LEG-00-0007 OR WITH AN EQUIVALENT MODIFICATION FACTORY- INCORPORATED							Service	ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: CPM 53-24-00PROC. REF: CPM 53-24-00									
53-24-00-220-C04-L00	DETAILED INSPECTION (INTERNAL) OF VENTRAL FUEL TANK COMPONENTS:- VENTRAL FUEL TANK STRUCTURE (SSI 53-20-85) (L650 ONLY)							Service	ATA:53
	MOS/MSC	27-Aug-07	N/A						
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: CPM 53-24-00PROC. REF: CPM 53-24-00									
53-24-00-220-C05-L00	DETAILED INSPECTION (INTERNAL) OF VENTRAL FUEL TANK COMPONENTS:- FRONTAL SIDE OF VENTRAL FUEL TANK STRUCTURE (SSI 53-20-87) (L650 ONLY)							Service	ATA:53
	MOS/MSC	27-Aug-07	N/A						
	HRS	0							
	AFL	0							
									PKG:6032
PROC. REF: CPM 53-24-00PROC. REF: CPM 53-24-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty

ATA 53 - FUSELAGE

53-31-00-210-801-L00 S	GENERAL VISUAL INSPECTION (INTERNAL) OF FUSELAGE COM- PONENTS:- REAR AUXILIARY FUEL TANK FITTING AT ATTACHMENTS (SSI 53-30-56)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 53-31-00PROC. REF: NDT 53-31-00									
53-31-00-210-802-L00 S	GENERAL VISUAL INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- BAGGAGE DOOR LATERAL L- SHAPE (SSI 53-30-03)							Service	ATA:53
	MOS	09-Jul-15	192 (+15d/-15d)					LOW UTILIZATION	
	HRS	7460.3	8000 (+20/-20)						
	AFL	3992	4000 (+20/-20)						
									PKG:5032,6032
PROC. REF: NDT 53-31-00PROC. REF: NDT 53-31-00									
53-31-00-210-803-L00 S	GENERAL VISUAL INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- BAGGAGE DOOR CUTOUT STRUCTURE (SSI 53-30-48)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 53-31-00PROC. REF: NDT 53-31-00									
53-31-00-210-804-L00 S	GENERAL VISUAL INSPECTION(INTERNAL) OF FUSELAGE COMPONENTS:- REAR ELECTRONIC COMPARTMENT DOOR CUTOUT STRUCTURE (SSI 53-30-49)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI.NOTE: APPLICABLE TO AIRCRAFT PRE-MOD. S.B.145LEG-00-0007 (L600 ONLY)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 53-31-00PROC. REF: NDT 53-31-00									

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-31-00-210-804-L01 S		GENERAL VISUAL INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- REAR ELECTRONIC COMPARTMENT DOOR CUTOUT STRUCTURE (SSI 53-30-49)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI.NOTE: APPLICABLE TO AIRCRAFT POST-MOD. S.B.145LEG-00-0007 OR WITH AN EQUIVALENT MODIFICATION FACTORY-INCORPORATED (L600 ONLY)						Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)				LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 53-31-00PROC. REF: NDT 53-31-00									
53-31-00-210-810-L00		GENERAL VISUAL INSPECTION(INTERNAL) OF FUSELAGECOMPONENTS:- REAR ELECTRONIC COMPARTMENT DOOR CUTOUT STRUCTURE (SSI 53-30-49)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI. (L650 ONLY)						Service	ATA:53
	MOS/MSC	25-Sep-07	N/A				STRUCTURAL		
	HRS	0							
	AFL	0							
									PKG:6032
PROC. REF: NDT 53-31-00PROC. REF: NDT 53-31-00									
53-31-00-210-811-L00 S		GENERAL VISUAL INSPECTION (INTERNAL) OFFUSELAGE COMPONENTS: FUSELAGE SKIN PANEL AT STRINGERS,FRAMES/BULKHEADS, AND SPLICES (SSI 53-30-07). FUSELAGE SKIN PANEL AT PRESSURE BULKHEAD(53-30- 15). FUSELAGE MACHINED BULKHEAD (53-30-30). FRAMES (53-30-43).NOTE: DURING THIS INSPECTION, THE CPCP BASICTASK SHALL ALSO BE PERFORMED FOR SSI 53-30-07						Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)				LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 53-31-00PROC. REF: NDT 53-31-00									
53-31-00-220-801-L00 S		DETAILED INSPECTION (INTERNAL)OF FUSELAGE COMPONENTS:- BAGGAGE COMPARTMENT FLOOR BEAMS AND COLUMNS (SSI 53-30 -28)						Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)				LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 53-31-00PROC. REF: NDT 53-31-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-31-00-220-802-L00 S	DETAILED INSPECTION (EXTERNAL)OF FUSELAGE COMPONENTS:- FRAME REINFORCEMENT - MACHINED SHEAR CLIP (SSI 53-30-55)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 53-31-00PROC. REF: NDT 53-31-00									
53-31-00-220-805-L00 S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- FRAME REINFORCEMENT - MACHINED SHEAR CLIP (SSI 53-30-55)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 53-31-00PROC. REF: NDT 53-31-00									
53-31-00-220-806-L00 S	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN PANEL AT PRESSURE BULKHEAD (SSI 53-30-15)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 53-31-00PROC. REF: NDT 53-31-00									
53-31-00-220-807-L00 S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN LONGITUDINAL SPLICE (SSI 53-30-08)- FUSELAGE SKIN CIRCUMFERENTIAL SPLICE(SSI 53-30-14)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 53-31-00PROC. REF: NDT 53-31-00									
53-31-00-220-808-L00 S	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- BAGGAGE DOOR CUTOUT STRUCTURE (SSI 53-30-48)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 53-31-00PROC. REF: NDT 53-31-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-31-00-220-809-L00 S	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- REAR ELECTRONIC COMPARTMENT DOOR CUTOUT STRUCTURE (SSI 53-30-49) (L600 ONLY)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)				LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016
PROC. REF: NDT 53-31-00PROC. REF: NDT 53-31-00									
53-31-00-220-810-L00 S	DETAILED INSPECTION (INTERNAL)OF FUSELAGE COMPONENTS:- BULKHEAD-TO-ENGINE PYLON ATTACHMENT(SSI 53-30-35)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR 53-30-35 (L600 ONLY)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)				LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 53-31-00PROC. REF: NDT 53-31-00									
53-31-00-220-811-L00 S	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE MACHINED BULK- HEAD (SSI 53-30-30)							Service	ATA:53
	MOS	24-Jul-15	192 (+15d/-15d)				LOW UTILIZATION		
	HRS	7460.3	8000 (+20/-20)						
	AFL	3992	4000 (+20/-20)						
									PKG:5032,6032
PROC. REF: NDT 53-31-00PROC. REF: NDT 53-31-00									
53-31-00-220-813-L00 S	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/ BULKHEADS, AND SPLICES (SSI 53-30-07)- FUSELAGE SKIN PANEL AT PRES- SURE BULKHEAD(SSI 53-30-15)- FUSELAGE TO VERTICAL STABILIZER SPAR ATTACHMENT FITTING (SSI 53-30-38)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR SSI 53-30-38							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)				LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6016
PROC. REF: NDT 53-31-00PROC. REF: NDT 53-31-00									
53-31-00-220-818-L00	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- REAR ELECTRONIC COMPARTMENT DOOR CUTOUT STRUCTURE (SSI 53-30-49) (L650 ONLY)							Service	ATA:53
	MOS/MSC	25-Sep-07	N/A				STRUCTURAL		
	HRS	0							
	AFL	0							
									PKG:6016

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
PROC. REF: NDT 53-31-00PROC. REF: NDT 53-31-00									
53-31-00-220-819-L00	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- BULKHEAD-TO-ENGINE PYLON ATTACHMENT (SSI 53-30-35)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR SSI 53-30-35 (L650 ONLY)								Service ATA:53
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL	
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: NDT 53-31-00PROC. REF: NDT 53-31-00									
53-31-00-220-820-L00 S	DETAILED INSPECTION (INTERNAL) OF FUSELAGECOMPONENTS: FUSELAGE SKIN PANEL AT STRINGERS,FRAMES/BULKHEADS AND SPLICES (SSI 53-30-36).								Service ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 53-31-00PROC. REF: NDT 53-31-00									
53-31-00-220-821-L00 S	DETAILED INSPECTION (EXTERNAL) OF FUSELAGECOMPONENTS: FUSELAGE SKIN PANEL AT STRINGERS,FRAMES/BULKHEADS, AND SPLICES (SSI 53-30-07). FUSELAGE SKIN PANEL AT PRESSURE BULKHEAD (SSI53-30-15). FUSELAGE MACHINED BULKHEAD (SSI 53-30-30).NOTE: REMOVE BUMPER PLATES, IF INSTALLED								Service ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6016
PROC. REF: NDT 53-31-00PROC. REF: NDT 53-31-00									
53-31-00-220-C01-L00 S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- TOILET WASTE DRAIN VALVE SUPPORT (SSI 53-30-29)- FRAMES (SSI 53-30-43)								Service ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: CPM 53-31-00PROC. REF: CPM 53-31-00									

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-31-00-220-C02-L00 S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/BULK HEADS, AND SPLICES (SSI 53-30-07)							Service	ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: CPM 53-31-00PROC. REF: CPM 53-31-00									
53-31-00-220-C03-L00 S	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN PANEL AT PRESSURE BULKHEAD(SSI 53-30-15)							Service	ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: CPM 53-31-00PROC. REF: CPM 53-31-00									
53-31-00-220-C04-L00 S	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- TOILET WASTE DRAIN VALVE SUPPORT (SSI 53-30-29)							Service	ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: CPM 53-31-00PROC. REF: CPM 53-31-00									
53-31-00-220-C05-L00 S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- FRAMES (SSI 53-30-43)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: CPM 53-31-00PROC. REF: CPM 53-31-00									
53-31-00-250-801-L00	SPECIAL DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENT BY USING EDDY CURRENT HIGH FREQUENCY INSPECTION METHOD:- TOILET WASTE DRAIN VALVE SUPPORT (SSI 53-30-29)NOTE: APPLICABLE TO AIRCRAFT POST-MOD. S.B.145LEG-00-0007 OR WITH AN EQUIVALENT MODIFICATION FACTORY-INCORPORATED.							Service	ATA:53
	MOS/MSC	27-Aug-07	N/A						
	HRS	0							
	AFL	0							
PROC. REF: NDT 53-31-00PROC. REF: NDT 53-31-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-31-00-250-802-L00 S	SPECIAL DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENT BY USING EDDY CURRENT LOW FREQUENCY INSPECTION METHOD:- BAGGAGE DOOR CUTOUT STRUCTURE (SSI 53-30-48)							Service	ATA:53
	MOS	27-Aug-07	T:288 (+15d/-15d)		27-Aug-31 (M)	11-Sep-31	1919 d (+15)	LOW UTILIZATION	
	HRS		T:12000 (+20/-20)		12000 (M)	12020	723.7 (+20)		
	AFL		T:6000 (+20/-20)		6060 (M)	6080	35 (+20)		
									PKG:5018
PROC. REF: NDT 53-31-00PROC. REF: NDT 53-31-00									
53-31-00-250-803-L00 S	SPECIAL DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENT BY USING EDDY CURRENT HIGH FREQUENCY INSPECTION METHOD:- BAGGAGE DOOR CUTOUT STRUCTURE (SSI 53-30-48)							Service	ATA:53
	MOS	27-Aug-07	T:288 (+15d/-15d)		27-Aug-31 (M)	11-Sep-31	1919 d (+15)	LOW UTILIZATION	
	HRS		T:12000 (+20/-20)		12000 (M)	12020	723.7 (+20)		
	AFL		T:6000 (+20/-20)		6060 (M)	6080	35 (+20)		
									PKG:5018
PROC. REF: NDT 53-31-00PROC. REF: NDT 53-31-00									
53-31-00-250-804-L00 S	SPECIAL DETAILED INSPECTION (EXTERNAL) OFFUSELAGE SKIN AT FRAMES 61, 62, AND 63,BY USING THE HIGH FREQUENCY EDDY CURRENTMETHOD: FUSELAGE SKIN PANEL AT STRINGERS,FRAMES/BULKHEADS, AND SPLICES: (SSI 53-30-07)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6016
PROC. REF: NDT 53-31-00PROC. REF: NDT 53-31-00									
53-31-00-250-805-L00 S	SPECIAL DETAILED INSPECTION (INTERNAL) AFT SIDEOF THE REAR PRESSURE BULKHEAD, BY USING THEHIGH FREQUENCY EDDY CURRENT METHOD. REAR PRESSURE BULKHEAD. (SSI 53-30-36)							Service	ATA:53
	MOS	27-Aug-07	T:288 (+15d/-15d)					LOW UTILIZATION	
	HRS	0	T:12000 (+20/-20)						
	AFL	0	T:6000 (+20/-20)						
									PKG:5025
PROC. REF: NDT 53-31-00PROC. REF: NDT 53-31-00									
53-31-00-250-806-L00 S	SPECIAL DETAILED INSPECTION (EXTERNAL) OFFUSELAGE COMPONENT BY USING HIGH FREQUENCYEDDY CURRENT METHOD: SSI 53-30-15 (FUSELAGE SKIN PANEL ATPRESSURE BULKHEAD. SSI 53-30-30 (FUSELAGE MACHINED BULKHEAD)							Service	ATA:53
	MOS	27-Aug-07	T:288 (+15d/-15d)					LOW UTILIZATION	
	HRS	0	T:12000 (+20/-20)						
	AFL	0	T:6000 (+20/-20)						
									PKG:5018

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
PROC. REF: NDT 53-31-00PROC. REF: NDT 53-31-00									
53-32-00-210-801-L00 S	GENERAL VISUAL INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- APU MOUNTING (SSI 53-30-40)								Service ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 53-32-00PROC. REF: NDT 53-32-00									
53-32-00-210-802-L00 S	GENERAL VISUAL INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- TAIL CONE ACCESS DOOR CUT- OUT STRUCTURE(SSI 53-30-50)								Service ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 53-32-00PROC. REF: NDT 53-32-00									
53-32-00-210-C01-L00 S	GENERAL VISUAL INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/BULKHEADS, AND SPLICES (SSI 53-30-07)								Service ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5009
PROC. REF: CPM 53-32-00PROC. REF: CPM 53-32-00									
53-32-00-210-C02-L00 S	GENERAL VISUAL INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/BULKHEADS, AND SPLICES (SSI 53-30-07)- FUSELAGE SKIN LONGITUDINAL SPLICE (SSI 53-30-08)- FUSELAGE SKIN CIRCUMFERENTIAL SPLICE(SSI 53-30-14)- TAIL CONE FRAME AT APU MOUNTING ATTACHMENT (SSI 53-30-39)								Service ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5009
PROC. REF: CPM 53-32-00PROC. REF: CPM 53-32-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-32-00-220-801-L00 S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE TO VERTICAL STABILIZER SPAR ATTACHMENT FITTING (SSI 53-30-38)							Service	ATA:53
	MOS	08-Jul-15	192 (+15d/-15d)					LOW UTILIZATION	
	HRS	7460.3	8000 (+20/-20)						
	AFL	3992	4000 (+20/-20)						
									PKG:5032,6032
PROC. REF: NDT 53-32-00PROC. REF: NDT 53-32-00									
53-32-00-220-802-L00 S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE MACHINED BULKHEAD (SSI 53-30-30)							Service	ATA:53
	MOS	07-Jul-15	192 (+15d/-15d)					LOW UTILIZATION	
	HRS	7460.3	8000 (+20/-20)						
	AFL	3992	4000 (+20/-20)						
									PKG:5032,6032
PROC. REF: NDT 53-32-00PROC. REF: NDT 53-32-00									
53-32-00-220-803-L00 S	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- L PROFILE STRAKE ATTACHMENT (SSI 53-30-53)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 53-32-00PROC. REF: NDT 53-32-00									
53-32-00-220-804-L00 S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- TAIL CONE ACCESS DOOR CUT- OUT STRUCTURE(SSI 53-30-50)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 53-32-00PROC. REF: NDT 53-32-00									
53-32-00-220-C01-L00 S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- REAR PRESSURE BULKHEAD (SSI 53-30-36)							Service	ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: CPM 53-32-00PROC. REF: CPM 53-32-00									

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-32-00-220-C02-L00 S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- FRAMES (SSI 53-30-43)							Service	ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5009
PROC. REF: CPM 53-32-00PROC. REF: CPM 53-32-00									
53-Z111-213-001-A00 S	GENERAL VISUAL INSPECTION(EXTERNAL) (ZONE 111)							Service	ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 05-20-01PROC. REF: AMM 05-20-01									
53-Z111-214-001-A00 S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONE 111)							Service	ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 05-20-01PROC. REF: AMM 05-20-01									
53-Z113-213-001-A00 S	GENERAL VISUAL INSPECTION(EXTERNAL) (ZONE 113, 114)							Service	ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 05-20-03PROC. REF: AMM 05-20-03									
53-Z113-214-001-A00 S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONE 113)							Service	ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 05-20-03PROC. REF: AMM 05-20-03									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-Z114-214-001-A00 S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONE 114) (L600 ONLY)							Service	ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 05-20-03PROC. REF: AMM 05-20-03									
53-Z114-214-001-A01	GENERAL VISUAL INSPECTION(INTERNAL) (ZONE 114)NOTE:EWIS (L650 ONLY)							Service	ATA:53
	MOS/MSC	25-Sep-07	N/A					ZONAL	
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: AMM 05-20-03PROC. REF: AMM 05-20-03									
53-Z123-213-001-A00 S	GENERAL VISUAL INSPECTION(EXTERNAL) (ZONE 123, 124)							Service	ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 05-20-10PROC. REF: AMM 05-20-10									
53-Z123-214-001-A00 S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONE 121, 122, 123 AND 124) (L600 ONLY)							Service	ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 05-20-10PROC. REF: AMM 05-20-10									
53-Z123-214-001-A01	GENERAL VISUAL INSPECTION(INTERNAL) (ZONE 121, 122, 123 AND 124)NOTE:EWIS (L650 ONLY)							Service	ATA:53
	MOS/MSC	25-Sep-07	N/A					ZONAL	
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: AMM 05-20-10PROC. REF: AMM 05-20-10									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-Z131-213-001-A00 S	GENERAL VISUAL INSPECTION(EXTERNAL) (ZONES 131 AND 132)							Service	ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 05-20-17PROC. REF: AMM 05-20-17									
53-Z131-214-001-A00 S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 131 AND 132) (L600 ONLY)							Service	ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 05-20-17PROC. REF: AMM 05-20-17									
53-Z131-214-001-A01	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 131 AND 132)NOTE:EWIS (L650 ONLY)							Service	ATA:53
	MOS/MSC	25-Sep-07	N/A					ZONAL	
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: AMM 05-20-17PROC. REF: AMM 05-20-17									
53-Z141-213-001-A00 S	GENERAL VISUAL INSPECTION(EXTERNAL) (ZONES 141 AND 142)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: AMM 05-20-21PROC. REF: AMM 05-20-21									
53-Z141-214-001-A00 S	GENERAL VISUAL INSPECTION (INTERNAL) (ZONES 141 AND 142). (L600 ONLY)							Service	ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 05-20-21PROC. REF: AMM 05-20-21									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-Z141-214-001-A01	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 141 AND 142)NOTE:EWIS (L650 ONLY)							Service	ATA:53
	MOS/MSC	25-Sep-07	N/A					ZONAL	
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: AMM 05-20-21PROC. REF: AMM 05-20-21									
53-Z151-214-002-A00 S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 151, 152, 153, 154, 155, 156, 157) (L600 ONLY)							Service	ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 05-20-26PROC. REF: AMM 05-20-26									
53-Z151-214-002-A01	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 151, 152, 153, 154, 155, 156, 157)NOTE:EWIS (L650 ONLY)							Service	ATA:53
	MOS/MSC	25-Sep-07	N/A					ZONAL	
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: AMM 05-20-26PROC. REF: AMM 05-20-26									
53-Z155-214-001-A00 S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 155, 156 AND 157) (L600 ONLY)							Service	ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 05-20-28PROC. REF: AMM 05-20-28									
53-Z155-214-001-A01	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 155, 156 AND 157)NOTE:EWIS (L650 ONLY)							Service	ATA:53
	MOS/MSC	25-Sep-07	N/A					ZONAL	
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: AMM 05-20-28PROC. REF: AMM 05-20-28									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-Z161-214-001-A00 S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 161, 162) (L600 ONLY)							Service	ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 05-20-33PROC. REF: AMM 05-20-33									
53-Z161-214-001-A01	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 161, 162)NOTE:EWIS (L650 ONLY)							Service	ATA:53
	MOS/MSC	25-Sep-07	N/A					ZONAL	
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: AMM 05-20-33PROC. REF: AMM 05-20-33									
53-Z171-213-001-A00 S	GENERAL VISUAL INSPECTION (EXTERNAL) (ZONES 171 AND 172)							Service	ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 05-20-38PROC. REF: AMM 05-20-38									
53-Z171-214-001-A00 S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 171 AND 172) (L600 ONLY)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016
PROC. REF: AMM 05-20-38PROC. REF: AMM 05-20-38									
53-Z171-214-001-A01 S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 171 AND 172) NOTE:EWIS (L650 ONLY)							Service	ATA:53
	MOS/MSC	25-Sep-07	N/A					ZONAL	
	HRS	0							
	AFL	0							
									PKG:5016,6032
PROC. REF: AMM 05-20-38PROC. REF: AMM 05-20-38									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-Z191-213-001-A00 S	GENERAL VISUAL INSPECTION (EXTERNAL) (ZONES 191, 192, 193, 194, 195, 196, 197,198, 199, 1921, 1922, 1923, 1971, 1981, 1982, 1991 AND 1992).NOTE: DO NOT REMOVE THE FUEL TANK (L600 ONLY)							Service	ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)				LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 05-20-95PROC. REF: AMM 05-20-95									
53-Z191-213-002-A00	GENERAL VISUAL INSPECTION (EXTERNAL) (ZONES 191, 192, 1921, 1923, 1924, 193, 1932, 194, 195, 196, 197, 1971, 1972, 198, 1981, 1982, 199, 1991 AND 1992). NOTE: DO NOT REMOVE THE FUEL TANK (L650 ONLY)							Service	ATA:53
	MOS/MSC	25-Sep-07	N/A				ZONAL		
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: AMM 05-20-95PROC. REF: AMM 05-20-95									
53-Z191-214-001-A00 S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 191, 192, 193, 194, 195, 196, 198, 199, 1921, 1922, 1923, 1971, 1981, 1982,1991 AND 1992). (L600 ONLY)							Service	ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)				LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 05-20-95PROC. REF: AMM 05-20-95									
53-Z191-214-003-A00	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 191, 192, 1921, 1922, 1923, 1924, 193, 1932, 194, 195, 196, 1971, 198, 1981, 1982, 199, 1991, 1992).NOTE:EWIS (L650 ONLY)							Service	ATA:53
	MOS/MSC	25-Sep-07	N/A				ZONAL		
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: AMM 05-20-95PROC. REF: AMM 05-20-95									
53-Z197-214-001-A00 S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 197) (L600 ONLY)							Service	ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)				LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 05-20-96PROC. REF: AMM 05-20-96									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-Z197-214-001-A01	GENERAL VISUAL INSPECTION(INTERNAL) (ZONE 197) NOTE:EWIS (L650 ONLY)								Service ATA:53
	MOS/MSC	25-Sep-07	N/A					ZONAL	
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: AMM 05-20-96PROC. REF: AMM 05-20-96									
53-Z197-214-002-A00	GENERAL VISUAL INSPECTION(INTERNAL) (ZONE 1972)NOTE:EWIS (L650 ONLY)								Service ATA:53
	MOS/MSC	25-Sep-07	N/A					ZONAL	
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: AMM 05-30-37PROC. REF: AMM 05-30-37									
53-Z213-213-001-A00 S	GENERAL VISUAL INSPECTION(EXTERNAL) (ZONE 213, 214)								Service ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 05-20-06PROC. REF: AMM 05-20-06									
53-Z213-214-001-A00 S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 113, 114, 213, 214, 215, 216) (L600 ONLY)								Service ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 05-20-06PROC. REF: AMM 05-20-06									
53-Z213-214-001-A01	GENERAL VISUAL INSPECTION(INTERNAL) (ZONE 113, 114, 213, 214, 215, 216)NOTE:EWIS (L650 ONLY)								Service ATA:53
	MOS/MSC	25-Sep-07	N/A					ZONAL	
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: AMM 05-20-06PROC. REF: AMM 05-20-06									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-Z223-213-001-A00 S	GENERAL VISUAL INSPECTION(EXTERNAL) (ZONES 223, 224)							Service	ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 05-20-13PROC. REF: AMM 05-20-13									
53-Z223-214-001-A00 S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 221, 222, 223 AND 224) (L600 ONLY)							Service	ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 05-20-13PROC. REF: AMM 05-20-13									
53-Z225-213-001-A00 S	GENERAL VISUAL INSPECTION(EXTERNAL) (ZONES 225 AND 226)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: AMM 05-20-15PROC. REF: AMM 05-20-15									
53-Z225-214-001-A00 S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 225 AND 226)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: AMM 05-20-15PROC. REF: AMM 05-20-15									
53-Z231-213-001-A00	GENERAL VISUAL INSPECTION(EXTERNAL) (ZONES 231 AND 232)NOTE: APPLICABLE TO AIRCRAFT PRE-MOD. SB 145LEG-53-0031.							Service	ATA:53
	MOS/MSC	15-Aug-16	N/A						
	HRS	7841.1							
	AFL	4202							
PROC. REF: AMM 05-20-18PROC. REF: AMM 05-20-18									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-Z231-213-001-A01 S	GENERAL VISUAL INSPECTION(EXTERNAL) (ZONES 231 AND 232)NOTE: APPLICABLE TO AIRCRAFT POST-MOD. SB 145LEG-53-0031 OR WITH AN EQUIVALENT MODIFICATION FACTORY-INCORPORATED.							Service	ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 05-20-18PROC. REF: AMM 05-20-18									
53-Z231-214-001-A00 S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 231 AND 232)							Service	ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 05-20-18PROC. REF: AMM 05-20-18									
53-Z233-213-001-A00 S	GENERAL VISUAL INSPECTION(EXTERNAL) (ZONES 233 AND 234)							Service	ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 05-20-19PROC. REF: AMM 05-20-19									
53-Z233-214-001-A00 S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 233 AND 234)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: AMM 05-20-19PROC. REF: AMM 05-20-19									
53-Z241-213-001-A00 S	GENERAL VISUAL INSPECTION(EXTERNAL) (ZONES 241 AND 242)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: AMM 05-20-23PROC. REF: AMM 05-20-23									

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-Z241-214-001-A00 S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 241 AND 242)							Service	ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 05-20-23PROC. REF: AMM 05-20-23									
53-Z243-213-003-A00 S	GENERAL VISUAL INSPECTION(EXTERNAL) (ZONES 243 AND 244)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: AMM 05-20-25PROC. REF: AMM 05-20-25									
53-Z243-214-001-A00 S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 243 AND 244)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: AMM 05-20-25PROC. REF: AMM 05-20-25									
53-Z251-213-001-A00 S	GENERAL VISUAL INSPECTION(EXTERNAL) (ZONES 251 AND 252)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: AMM 05-20-30PROC. REF: AMM 05-20-30									
53-Z251-214-001-A00 S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 251 AND 252)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: AMM 05-20-30PROC. REF: AMM 05-20-30									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-Z253-213-001-A00 S	GENERAL VISUAL INSPECTION(EXTERNAL) (ZONES 253 AND 254)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: AMM 05-20-31PROC. REF: AMM 05-20-31									
53-Z253-214-001-A00 S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 253 AND 254)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: AMM 05-20-31PROC. REF: AMM 05-20-31									
53-Z261-213-001-A00 S	GENERAL VISUAL INSPECTION(EXTERNAL) (ZONES 261, 262)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: AMM 05-20-35PROC. REF: AMM 05-20-35									
53-Z261-214-001-A00 S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 261, 262)							Service	ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 05-20-35PROC. REF: AMM 05-20-35									
53-Z263-213-002-A00 S	GENERAL VISUAL INSPECTION(EXTERNAL) (ZONES 263 AND 264)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: AMM 05-20-36PROC. REF: AMM 05-20-36									

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-Z263-214-001-A00 S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 263 AND 264) (L600 ONLY)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: AMM 05-20-36PROC. REF: AMM 05-20-36									
53-Z263-214-001-A01	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 263 AND 264)NOTE:EWIS (L650 ONLY)							Service	ATA:53
	MOS/MSC	25-Sep-07	N/A					ZONAL	
	HRS	0							
	AFL	0							
									PKG:6032
PROC. REF: AMM 05-20-36PROC. REF: AMM 05-20-36									
53-Z271-213-001-A00 S	GENERAL VISUAL INSPECTION(EXTERNAL) (ZONES 271, 272)							Service	ATA:53
	MOS	17-Oct-25	24 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	1000 (+20/-20)						
	AFL	5820							
									PKG:5004
PROC. REF: AMM 05-20-40PROC. REF: AMM 05-20-40									
53-Z271-214-001-A00 S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 271, 272) (L600 ONLY)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016
PROC. REF: AMM 05-20-40PROC. REF: AMM 05-20-40									
53-Z271-214-001-A01 S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 271, 272)NOTE:EWIS (L650 ONLY)							Service	ATA:53
	MOS/MSC	25-Sep-07	N/A					ZONAL	
	HRS	0							
	AFL	0							
									PKG:5016,6032
PROC. REF: AMM 05-20-40PROC. REF: AMM 05-20-40									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-Z273-213-002-A00 S	GENERAL VISUAL INSPECTION(EXTERNAL) (ZONES 273 AND 274)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: AMM 05-20-44PROC. REF: AMM 05-20-44									
53-Z273-214-002-A00 S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 273 AND 274) (L600 ONLY)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016
PROC. REF: AMM 05-20-44PROC. REF: AMM 05-20-44									
53-Z273-214-002-A01 S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 273 AND 274)NOTE:EWIS (L650 ONLY)							Service	ATA:53
	MOS/MSC	25-Sep-07	N/A					ZONAL	
	HRS	0							
	AFL	0							
									PKG:5016,6032
PROC. REF: AMM 05-20-44PROC. REF: AMM 05-20-44									
53-Z275-214-001-A00 S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 275 AND 276) (L600 ONLY)							Service	ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 05-20-41PROC. REF: AMM 05-20-41									
53-Z275-214-001-A01	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 275 AND 276)NOTE:EWIS (L650 ONLY)							Service	ATA:53
	MOS/MSC	25-Sep-07	N/A					ZONAL	
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: AMM 05-20-41PROC. REF: AMM 05-20-41									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-Z311-213-001-A00 S	GENERAL VISUAL INSPECTION(EXTERNAL) (ZONES 311 AND 312)							Service	ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 05-20-46PROC. REF: AMM 05-20-46									
53-Z311-214-001-A00 S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 311 AND 312) (L600 ONLY)							Service	ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 05-20-46PROC. REF: AMM 05-20-46									
53-Z311-214-001-A01	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 311 AND 312)NOTE:EWIS (L650 ONLY)							Service	ATA:53
	MOS/MSC	25-Sep-07	N/A					ZONAL	
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: AMM 05-20-46PROC. REF: AMM 05-20-46									
53-Z313-213-001-A00 S	GENERAL VISUAL INSPECTION(EXTERNAL) (ZONE 313)							Service	ATA:53
	MOS	17-Oct-25	24 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	1000 (+20/-20)						
	AFL	5820							
									PKG:5004
PROC. REF: AMM 05-20-47PROC. REF: AMM 05-20-47									
53-Z313-214-001-A00 S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONE 313) (L600 ONLY)							Service	ATA:53
	MOS	17-Oct-25	24 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	1000 (+20/-20)						
	AFL	5820							
									PKG:5004
PROC. REF: AMM 05-20-47PROC. REF: AMM 05-20-47									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-Z313-214-001-A01	GENERAL VISUAL INSPECTION(INTERNAL) (ZONE 313)NOTE:EWIS (L650 ONLY)							Service	ATA:53
	MOS/MSC	25-Sep-07	N/A					ZONAL	
	HRS	0							
	AFL	0							
PROC. REF: AMM 05-20-47PROC. REF: AMM 05-20-47									
53-Z315-213-001-A00 S	GENERAL VISUAL INSPECTION(EXTERNAL) (ZONES 315, 316, 317, 318)							Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: AMM 05-20-45PROC. REF: AMM 05-20-45									
530401-0101	LH FAIRING ASSY							Component	ATA:53
PN:135-12815-407	MOS/MSC	19-Aug-15	O/C	TSR 0					
SN:UNKNOWN	HRS	7460.3		TSR 0					
	AFL	3992		TSR 0					
PROC. REF: AMM 53-04-01PROC. REF: AMM 53-04-01									
530401-0102	RH FAIRING ASSY							Component	ATA:53
PN:135-12835-409	MOS/MSC	19-Aug-15	O/C	TSR 0					
SN:UNKNOWN	HRS	7460.3		TSR 0					
	AFL	3992		TSR 0					
PROC. REF: AMM 53-04-01PROC. REF: AMM 53-04-01									
530401-0103	FUS WING FAIRING ASSY FAIRING ASSY							Component	ATA:53
PN:135-02858-403	MOS/MSC	19-Aug-15	O/C	TSR 0					
SN:UNKNOWN	HRS	7460.3		TSR 0					
	AFL	3992		TSR 0					
PROC. REF: AMM 53-04-01PROC. REF: AMM 53-04-01									
530410-0101	MID FAIRING ASSY							Component	ATA:53
PN:135-08117-403	MOS/MSC	19-Aug-15	O/C	TSR 0					
SN:UNKNOWN	HRS	7460.3		TSR 0					
	AFL	3992		TSR 0					
PROC. REF: AMM 53-04-10PROC. REF: AMM 53-04-10									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
530420-0101	LH FAIRING ASSY							Component	ATA:53
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 53-04-20PROC. REF: AMM 53-04-20									
530420-0102	RH FAIRING ASSY							Component	ATA:53
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 53-04-20PROC. REF: AMM 53-04-20									
530430-0101	FAIRING ASSY							Component	ATA:53
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 53-04-30PROC. REF: AMM 53-04-30									
531400-0101	RADOME ANTENNA							Component	ATA:53
PN:4980-101	MOS/MSC	06-Jul-19	O/C	TSR 0					
SN:1205	HRS	9057.4		TSR 0					
	AFL	4853		TSR 0					
PROC. REF: AMM 53-11-01PROC. REF: AMM 53-11-01									
531500-0101	CENTER FUSELAGE ASSY STRUCTURE							Component	ATA:53
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 53-04-10PROC. REF: AMM 53-04-10									
533200-0101	REAR FUS ACCESS TAIL CONE							Component	ATA:53
PN:120-24234-043	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:0000125482	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 53-32-00PROC. REF: AMM 53-32-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
533210-0101		SILENCER -EXHAUST,APU ASSEMBLY						Component	ATA:53
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 49-81-01PROC. REF: AMM 49-81-01									
533500-0101		TAIL LEADING EDGE,VERTICAL FIN ASSEMBLY						Component	ATA:53
PN:145-35015-417	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:0000133367	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 55-35-00PROC. REF: AMM 55-35-00									
ATA 54 - NACELLES/PYLONS									
54-50-00-210-801-L00 S		GENERAL VISUAL INSPECTION (EXTERNAL) OF PYLON COMPONENTS:- PYLON SKIN (SSI 54-50-04)						Service	ATA:54
	MOS	29-Jun-23	48 (+15d/-15d)				LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: NDT 54-50-00PROC. REF: NDT 54-50-00									
54-50-00-220-802-L00 S		DETAILED INSPECTION (INTERNAL) OF PYLON COMPONENT:- FWD ENGINE MOUNTS (INCLUDING BOLTS) (SSI 54-50-03) (L600 ONLY)						Service	ATA:54
	MOS	29-Jun-23	48 (+15d/-15d)				LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008
PROC. REF: NDT 54-50-00PROC. REF: NDT 54-50-00									
54-50-00-220-803-L00 S		DETAILED INSPECTION (INTERNAL) OF PYLON COMPONENTS:- PYLON SPARS I, II, III AND IV (SSI 54-50-01)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI (L600 ONLY)						Service	ATA:54
	MOS	29-Jun-23	96 (+15d/-15d)				LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6016
PROC. REF: NDT 54-50-00PROC. REF: NDT 54-50-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 54 - NACELLES/PYLONS									
54-50-00-220-804-L00	DETAILED INSPECTION (INTERNAL) OF PYLON COMPONENTS:- PYLON SPARS I, II, III AND IV (SSI 54-50-01)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI. (L650 ONLY)							Service	ATA:54
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL	
	HRS	0							
	AFL	0							
PROC. REF: NDT 54-50-00PROC. REF: NDT 54-50-00									
54-50-00-220-805-L00	DETAILED INSPECTION (INTERNAL) OF PYLON COMPONENT:- FWD ENGINE MOUNTS (INCLUDING BOLTS) (SSI 54-50-03) (L650 ONLY)							Service	ATA:54
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL	
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: NDT 54-50-00PROC. REF: NDT 54-50-00									
54-50-00-220-806-L00 S	DETAILED INSPECTION (INTERNAL) OF PYLON COMPONENT:- AFT ENGINE MOUNTS (INCLUDING BOLTS) (SSI 54-50-07) (L600 ONLY)							Service	ATA:54
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008
PROC. REF: NDT 54-50-00PROC. REF: NDT 54-50-00									
54-50-00-220-807-L00	DETAILED INSPECTION (INTERNAL) OF PYLON COMPONENT:- AFT ENGINE MOUNTS (INCLUDING BOLTS) (SSI 54-50-07) (L650 ONLY)							Service	ATA:54
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL	
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: NDT 54-50-00PROC. REF: NDT 54-50-00									
54-50-00-220-808-L00 S	DETAILED INSPECTION (INTERNAL) OF PYLON COMPONENT:- PYLON YOKES I AND II (SSI 54-50-05) PRIMARY ELEMENT.							Service	ATA:54
	MOS	10-Jul-15	192 (+15d/-15d)					LOW UTILIZATION	
	HRS	7460.3	8000 (+20/-20)						
	AFL	3992	4000 (+20/-20)						
									PKG:5032,6032
PROC. REF: NDT 54-50-00PROC. REF: NDT 54-50-00									

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 54 - NACELLES/PYLONS									
54-50-00-220-809-L00 S	DETAILED INSPECTION (INTERNAL) OF PYLON COMPONENT:- PYLON YOKES I AND II (SSI 54-50-05) SECONDARY ELEMENT.							Service	ATA:54
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5011
PROC. REF: NDT 54-50-00PROC. REF: NDT 54-50-00									
54-50-00-220-C01-L00 S	DETAILED INSPECTION (INTERNAL) OF PYLON COMPONENTS:- PYLON YOKES III AND IV (SSI 54-50-02)							Service	ATA:54
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: CPM 54-50-00PROC. REF: CPM 54-50-00									
54-50-00-220-C02-L00 S	DETAILED INSPECTION (INTERNAL) OF PYLON COMPONENTS:- PYLON YOKES I AND II (SSI 54-50-05)							Service	ATA:54
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: CPM 54-50-00PROC. REF: CPM 54-50-00									
54-50-00-220-C03-L00 S	DETAILED INSPECTION (INTERNAL) OF PYLON COMPONENTS:- PYLON YOKES I AND II UPPER FLANGE (SSI 54-50-06).							Service	ATA:54
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: CPM 54-50-00PROC. REF: CPM 54-50-00									
54-50-00-230-801-L00	SPECIAL DETAILED INSPECTION (INTERNAL) OF PYLON COMPONENTS BY LIQUID PENETRANT INSPECTION METHOD:- FWD ENGINE MOUNTS(INCLUDING BOLTS) (SSI 54-50-03) (L650 ONLY)							Service	ATA:54
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL	
	HRS	0							
	AFL	0							
PROC. REF: NDT 54-50-00PROC. REF: NDT 54-50-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 54 - NACELLES/PYLONS									
54-50-00-250-801-L00 S	SPECIAL DETAILED INSPECTION (INTERNAL) OF PYLON COMPONENTS BY THE EDDY CURRENT METHOD:- PYLON YOKES I AND II (SSI 54-50-05)							Service	ATA:54
	MOS		288 (+15d/-15d)					LOW UTILIZATION	
	HRS		12000 (+20/-20)						
	AFL		6000 (+20/-20)						
									PKG:5140
PROC. REF: NDT 54-50-00PROC. REF: NDT 54-50-00									
54-50-00-250-802-L00	SPECIAL DETAILED INSPECTION (INTERNAL) OF PYLON COMPONENTS BY THE EDDY CURRENT METHOD:- PYLON YOKES I AND II UPPER FLANGE (SSI 54-50-06)NOTE: APPLICABLE TO AIRCRAFT PRE-MOD SB145LEG-54-0001							Service	ATA:54
	MOS/MSC		N/A						
	HRS								
	AFL								
									PKG:6016
PROC. REF: NDT 54-50-00PROC. REF: NDT 54-50-00									
54-50-00-250-802-L01 S	SPECIAL DETAILED INSPECTION (INTERNAL) OF PYLON COMPONENTS BY THE EDDY CURRENT METHOD:- PYLON YOKES I AND II UPPER FLANGE (SSI 54-50-06)NOTE: APPLICABLE TO AIRCRAFT POST-MOD SB145LEG-54-0001 OR WITH AN EQUIVALENT MODIFICATION FACTORY-INCORPORATED.							Service	ATA:54
	MOS	27-Aug-07	192 (+15d/-15d)					LOW UTILIZATION	
	HRS	0	8000 (+20/-20)						
	AFL	0	4000 (+20/-20)						
									PKG:5032,6032
PROC. REF: NDT 54-50-00PROC. REF: NDT 54-50-00									
54-50-00-290-801-L00 S	SPECIAL DETAILED INSPECTION (INTERNAL) OF PYLON COMPO- NENT USING BOROSCOPE:- PYLON SKIN (SSI 54-50-04)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI							Service	ATA:54
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: NDT 54-50-00PROC. REF: NDT 54-50-00									
54-Z414-213-001-A00 S	GENERAL VISUAL INSPECTION(EXTERNAL) (ZONES 414 AND 424)							Service	ATA:54
	MOS	17-Oct-25	24 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	1000 (+20/-20)						
	AFL	5820							
									PKG:5004
PROC. REF: AMM 05-20-72PROC. REF: AMM 05-20-72									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 54 - NACELLES/PYLONS									
54-Z414-214-001-A00 S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 414 AND 424) (L600 ONLY)							Service	ATA:54
	MOS	17-Oct-25	24 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	1000 (+20/-20)						
	AFL	5820							
									PKG:5004
PROC. REF: AMM 05-20-72PROC. REF: AMM 05-20-72									
54-Z414-214-001-A01	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 414 AND 424)NOTE:EWIS (L650 ONLY)							Service	ATA:54
	MOS/MSC	25-Sep-07	N/A					ZONAL	
	HRS	0							
	AFL	0							
PROC. REF: AMM 05-20-72PROC. REF: AMM 05-20-72									
ATA 55 - STABILIZERS									
55-10-00-210-802-L00 S	GENERAL VISUAL INSPECTION (EXTERNAL) OF HORIZONTAL STABILIZER COMPONENTS:- SKIN, FROM RIB STA. YH=350 TO RIB STA. YH=990 - UPPER SURFACE (SSI 55-10-07)							Service	ATA:55
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 55-10-00PROC. REF: NDT 55-10-00									
55-10-00-210-805-L00 S	GENERAL VISUAL INSPECTION (EXTERNAL) OF HORIZONTAL STABILIZER COMPONENTS:- SUPPORT PULLEY CENTRAL STA- BILIZER (SSI 55-10-14)							Service	ATA:55
	MOS	10-Jul-15	192 (+15d/-15d)					LOW UTILIZATION	
	HRS	7460.3	8000 (+20/-20)						
	AFL	3992	4000 (+20/-20)						
									PKG:5032,6032
PROC. REF: NDT 55-10-00PROC. REF: NDT 55-10-00									
55-10-00-210-C01-L00 S	GENERAL VISUAL INSPECTION (EXTERNAL) OF HORIZON- TAL STABILIZER COMPONENTS:- U SHAPE, L SHAPE AND BOX STRUCTURE - ELEVATOR COMMAND (SSI 55-10-22)							Service	ATA:55
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: CPM 55-10-00PROC. REF: CPM 55-10-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 55 - STABILIZERS									
55-10-00-210-C02-L00 S	GENERAL VISUAL INSPECTION (EXTERNAL) OF HORIZON- TAL STABILIZER COMPONENTS:- SUPPORT QUADRANT ASSY, STABILIZER (SSI 55-10-23)							Service	ATA:55
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5009
PROC. REF: CPM 55-10-00PROC. REF: CPM 55-10-00									
55-10-00-220-801-L00 S	DETAILED INSPECTION (EXTERNAL) OF HORIZONTAL STABILIZER COMPONENTS:- ELEVATOR SUPPORT FITTINGS (SSI 55-10-15)							Service	ATA:55
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: NDT 55-10-00PROC. REF: NDT 55-10-00									
55-10-00-220-802-L00 S	DETAILED INSPECTION (EXTERNAL) OF HORIZONTAL STABILIZER COMPONENTS:- FITTING HINGE SUPPORT STABILIZER (SSI 55-10-21)							Service	ATA:55
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 55-10-00PROC. REF: NDT 55-10-00									
55-10-00-220-803-L00 S	DETAILED INSPECTION (INTERNAL)OF HORIZONTAL STABILIZER COMPONENT:- REAR SPAR WEB AND CAP, FROM FIN TO RIB STA. YH=350, INCLUDING CENTER FITTING/SPARATTACHMENT (SSI 55-10-12)							Service	ATA:55
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 55-10-00PROC. REF: NDT 55-10-00									
55-10-00-220-804-L00 S	DETAILED INSPECTION (INTERNAL) OF HORIZONTAL STABILIZER COMPONENTS:- ROOT RIB (SSI 55-10-17)							Service	ATA:55
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016
PROC. REF: NDT 55-10-00PROC. REF: NDT 55-10-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 55 - STABILIZERS									
55-10-00-220-805-L00 S	DETAILED INSPECTION (EXTERNAL) OF HORIZONTAL STABILIZER COMPONENTS:- SKIN, FROM FIN TO STA. YH=350 - LOWER SURFACE (SSI 55-10-06)- SKIN, FROM FIN TO STA. YH=350 - UPPER SURFACE(SSI 55-10-01) (L600 ONLY)								Service ATA:55
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016
PROC. REF: NDT 55-10-00PROC. REF: NDT 55-10-00									
55-10-00-220-806-L00 S	DETAILED INSPECTION (INTERNAL) OF HORIZONTAL STABILIZER COMPONENTS:- SKIN SPLICE AT UPPER AND LOWER SURFACE (SSI 55-10-16)- FRONT/ REAR AUXILIARY SPAR CENTER FITTING (SSI 55-10-19)- REAR SPAR CENTER FITTING (SSI 55-10-18)- FRONT SPAR CENTER FITTINGS (SSI 55-10-20) (L600 ONLY)								Service ATA:55
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5017
PROC. REF: NDT 55-10-00PROC. REF: NDT 55-10-00									
55-10-00-220-808-L00 S	DETAILED INSPECTION (EXTERNAL) OF HORIZONTAL STABILIZER COMPONENTS:- SKIN, FROM RIB STA YH=350 TO RIB YH=990 - UPPER SURFACE (SSI 55-10-02) (L600 ONLY)								Service ATA:55
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016
PROC. REF: NDT 55-10-00PROC. REF: NDT 55-10-00									
55-10-00-220-809-L00 S	DETAILED INSPECTION (INTERNAL) OF HORIZONTAL STABILIZER COMPONENTS:- FRONT AND REAR AUXILIARY SPAR WEBS AND CAPS,INCLUDING CENTER FIT- TING/SPAR ATTACHMENT (SSI 55-10-11) (L600 ONLY)								Service ATA:55
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6016
PROC. REF: NDT 55-10-00PROC. REF: NDT 55-10-00									
55-10-00-220-810-L00 S	DETAILED INSPECTION (EXTERNAL) OF HORIZONTAL STABILIZER COMPONENTS:- SKIN, FROM RIB STA. YH=990 TO RIB STA. YH=2965 - UPPER SURFACE (SSI 55-10-03)								Service ATA:55
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6016

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 55 - STABILIZERS									
PROC. REF: NDT 55-10-00PROC. REF: NDT 55-10-00									
55-10-00-220-811-L00 S	DETAILED INSPECTION (INTERNAL) OF HORIZONTAL STABILIZER COMPONENTS:- RIBS, FROM RIB STA. YH=30 TO RIB STA. YH=990 (SSI 55-10-04)- RIBS, FROM RIB STA. YH=990 TO RIB STA. YH=2965 (SSI 55-10-05)							Service	ATA:55
	MOS	29-Jun-23	96 (+15d/-15d)				LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016
PROC. REF: NDT 55-10-00PROC. REF: NDT 55-10-00									
55-10-00-220-812-L00 S	DETAILED INSPECTION (INTERNAL) OF HORIZONTAL STABILIZER COMPONENTS:- FRONT SPAR WEB AND CAP, FROM RIB STA. YH=350 TO RIB STA. YH=2965 (SSI 55-10-10) (L600 ONLY)							Service	ATA:55
	MOS	29-Jun-23	48 (+15d/-15d)				LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5009
PROC. REF: NDT 55-10-00PROC. REF: NDT 55-10-00									
55-10-00-220-813-L00 S	DETAILED INSPECTION (INTERNAL) OF HORIZONTAL STABILIZER COMPONENTS:- FRONT SPAR WEB AND CAP, FROM FIN TO RIB STA. YH=350, INCLUDING CENTER FITTING /SPAR ATTACHMENT (SSI 55-10-09) (L600 ONLY)							Service	ATA:55
	MOS	29-Jun-23	48 (+15d/-15d)				LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008
PROC. REF: NDT 55-10-00PROC. REF: NDT 55-10-00									
55-10-00-220-814-L00	DETAILED INSPECTION (EXTERNAL) OF HORIZONTAL STABILIZER COMPONENTS:- SKIN, FROM FIN TO STA. YH=350 - LOWER SURFACE (SSI 55-10-06)- SKIN, FROM FIN TO STA. YH=350 - UPPER SURFACE (SSI 55-10-01) (L650 ONLY)							Service	ATA:55
	MOS/MSC	25-Sep-07	N/A				STRUCTURAL		
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: NDT 55-10-00PROC. REF: NDT 55-10-00									

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 55 - STABILIZERS									
55-10-00-220-815-L00	DETAILED INSPECTION (INTERNAL) OF HORIZONTAL STABILIZER COMPONENTS:- SKIN SPLICE AT UPPER AND LOWER SURFACE (SSI 55-10-16)- FRONT/ REAR AUXILIARY SPAR CENTER FITTING (SSI 55-10-19)- REAR SPAR CENTER FITTING(SSI 55-10-18)- FRONT SPAR CENTER FITTINGS(SSI 55-10-20) (L650 ONLY)								Service ATA:55
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL	
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: NDT 55-10-00PROC. REF: NDT 55-10-00									
55-10-00-220-816-L00	DETAILED INSPECTION (EXTERNAL) OF HORIZONTAL STABILIZER COMPONENTS:- SKIN, FROM RIB STA YH=350 TO RIB YH=990 - UPPER SURFACE (SSI 55-10-02) (L650 ONLY)								Service ATA:55
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL	
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: NDT 55-10-00PROC. REF: NDT 55-10-00									
55-10-00-220-817-L00	DETAILED INSPECTION (INTERNAL) OF HORIZONTAL STABILIZER COMPONENTS:- FRONT AND REAR AUXILIARY SPAR WEBS AND CAPS, INCLUDING CENTER FITTING/SPAR ATTACHMENT (SSI 55-10-11) (L650 ONLY)								Service ATA:55
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL	
	HRS	0							
	AFL	0							
									PKG:6032
PROC. REF: NDT 55-10-00PROC. REF: NDT 55-10-00									
55-10-00-220-818-L00	DETAILED INSPECTION (INTERNAL) OF HORIZONTAL STABILIZER COMPONENTS:- FRONT SPAR WEB AND CAP, FROM RIB STA. YH=350 TO RIB STA. YH=2965 (SSI 55-10-10) (L650 ONLY)								Service ATA:55
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL	
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: NDT 55-10-00PROC. REF: NDT 55-10-00									

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 55 - STABILIZERS									
55-10-00-220-C01-L00 S	DETAILED INSPECTION (INTERNAL) OF HORIZONTAL STABILIZER COMPONENTS:- FRONT SPAR WEB AND CAP, FROM FIN TO RIB STA. YH=350, INCLUDING CEN- TER FITTING/ SPAR ATTACHMENT (SSI 55-10-09)- REAR SPAR WEB & CAP, FROM RIB STA. YH=350 TO RIB STA. YH=2965, INCLUD- ING FITTING HINGE STABILIZER ATTACH TO ELEVATOR (SSI 55-10-13)							Service	ATA:55
	MOS	29-Jun-23	48 (+15d/-15d)				LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: CPM 55-10-00PROC. REF: CPM 55-10-00									
55-10-00-220-C02-L00 S	DETAILED INSPECTION (EXTERNAL) OF HORIZONTAL STA- BILIZER COMPONENTS:- SKIN, FROM RIB STA. YH=990 TO RIB STA. YH=2965- LOWER SURFACE (SSI 55-10-08)							Service	ATA:55
	MOS	29-Jun-23	48 (+15d/-15d)				LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: CPM 55-10-00PROC. REF: CPM 55-10-00									
55-10-00-220-C03-L00 S	DETAILED INSPECTION (INTERNAL) OF HORIZONTAL STABILIZER COMPONENTS:- PIN, INTERNAL AND EXTERNAL HINGE, STABILIZER (SSI 55-10-24)							Service	ATA:55
	MOS	29-Jun-23	48 (+15d/-15d)				LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: CPM 55-10-00PROC. REF: CPM 55-10-00									
55-10-00-240-801-L00 S	SPECIAL DETAILED INSPECTION (EXTERNAL) OF HORIZONTAL STABILIZER COMPONENTS BY THE MAGNETIC PARTICLE INSPECTION METHOD:- PIN, INTERNAL AND EXTERNAL HINGE, STABILIZER(SSI 55-10-24)							Service	ATA:55
	MOS	27-Aug-07	288 (+15d/-15d)				LOW UTILIZATION		
	HRS	0	12000 (+20/-20)						
	AFL	0	6000 (+20/-20)						
									PKG:5140
PROC. REF: NDT 55-10-00PROC. REF: NDT 55-10-00									
55-10-00-250-805-L00 S	SPECIAL DETAILED INSPECTION (EXTERNAL) OF HORIZONTAL STABILIZER COMPONENTS BY THE EDDY CURRENT INSPECTION METHOD:- SKIN, FROM FIN TO STA. YH=350 - UPPER SURFACE (SSI 55-10-01) (L600 ONLY)							Service	ATA:55
	MOS	06-Jul-19	144 (+15d/-15d)				LOW UTILIZATION		
	HRS	9057.4	6000 (+20/-20)						
	AFL	4853	3000 (+20/-20)						
									PKG:5024

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 55 - STABILIZERS									
PROC. REF: NDT 55-10-00PROC. REF: NDT 55-10-00									
55-10-00-250-806-L00 S	SPECIAL DETAILED INSPECTION (EXTERNAL) OF HORIZONTAL STABILIZER COMPONENTS BY THE EDDY CURRENT INSPECTION METHOD:- SKIN, FROM RIB TO STA. YH=350 TO RIB YH=990 -UPPER SURFACE (SSI 55-10-02) (L600 ONLY)							Service	ATA:55
	MOS	11-Aug-15	192 (+15d/-15d)					LOW UTILIZATION	
	HRS	7460.3	8000 (+20/-20)						
	AFL	3992	4000 (+20/-20)						
									PKG:5032,6032
PROC. REF: NDT 55-10-00PROC. REF: NDT 55-10-00									
55-10-00-250-807-L00 S	SPECIAL DETAILED INSPECTION (EXTERNAL) OF HORIZONTAL STABILIZER COMPONENTS BY THE EDDY CURRENT INSPECTION METHOD:- SKIN, FROM FIN TO STA. YH=350 - LOWER SURFACE (SSI 55-10-06) (L600 ONLY)							Service	ATA:55
	MOS	06-Jul-19	144 (+15d/-15d)					LOW UTILIZATION	
	HRS	9057.4	6000 (+20/-20)						
	AFL	4853	3000 (+20/-20)						
									PKG:5024
PROC. REF: NDT 55-10-00PROC. REF: NDT 55-10-00									
55-10-00-250-808-L00 S	SPECIAL DETAILED INSPECTION (EXTERNAL) OF HORIZONTAL STABILIZER COMPONENTS BY USING EDDY CURRENT LOW FREQUENCY INSPECTION METHOD:- FRONT SPAR WEB AND CAP, FROM FIN TO RIB STA. YH=350,INCLUDING CENTER FITTING/SPAR ATTACHMENT (SSI 55-10-09). (L600 ONLY)							Service	ATA:55
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5010,6008
PROC. REF: NDT 55-10-00PROC. REF: NDT 55-10-00									
55-10-00-250-809-L00 S	SPECIAL DETAILED INSPECTION (EXTERNAL) OF HORIZONTAL STABILIZER COMPONENTS BY USING EDDY CURRENT LOW FREQUENCY INSPECTION METHOD:- FRONT AND REAR AUXILIARY SPAR WEBS AND CAPS,INCLUDING CENTER FIT- TING/SPAR ATTACHMENT (SSI 55-10-11) (L600 ONLY)							Service	ATA:55
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5010,6008
PROC. REF: NDT 55-10-00PROC. REF: NDT 55-10-00									

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 55 - STABILIZERS									
55-10-00-250-810-L00 S	SPECIAL DETAILED INSPECTION (EXTERNAL) OF HORIZONTAL STABILIZER COMPONENTS BY USING EDDY CURRENT LOW FREQUENCY INSPECTION METHOD:- REAR SPAR WEB AND CAP, FROM FIN TO RIB STA. YH=350,INCLUDING CENTER FITTING/SPAR ATTACHMENT (SSI 55-10-12) (L600 ONLY)								Service ATA:55
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5010,6008
PROC. REF: NDT 55-10-00PROC. REF: NDT 55-10-00									
55-20-00-210-801-L00 S	GENERAL VISUAL INSPECTION (INTERNAL) OF ELEVATOR COMPONENTS:- ELEVATOR HORN MASS BALANCE WEIGHTS AND ATTACHMENTS (SSI 55-20-90)								Service ATA:55
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008
PROC. REF: NDT 55-20-00PROC. REF: NDT 55-20-00									
55-20-00-210-C01-L00 S	GENERAL VISUAL INSPECTION (EXTERNAL) OF ELEVATOR COMPONENTS:- SKIN, BETWEEN ROOT AND STA. YH=160(SSI 55-20-26)-SKIN, BETWEEN STA. YH=160 AND STA. YH=3320 (SSI 55-20-28)								Service ATA:55
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5009
PROC. REF: CPM 55-20-00PROC. REF: CPM 55-20-00									
55-20-00-210-C02-L00 S	GENERAL VISUAL INSPECTION (INTERNAL) OF ELEVATOR COMPONENTS:- SPARS BETWEEN ROOT AND STA. YH=160(SSI 55-20-25)-SPARS, BETWEEN STA. YH=160 AND STA. YH=3320 (SSI 55-20-27)								Service ATA:55
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: CPM 55-20-00PROC. REF: CPM 55-20-00									
55-20-00-210-C03-L00 S	GENERAL VISUAL INSPECTION (EXTERNAL) OF ELEVATOR COMPONENTS:- TAB (SSI 55-20-37)								Service ATA:55
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: CPM 55-20-00PROC. REF: CPM 55-20-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 55 - STABILIZERS									
55-20-00-220-801-L00 S	DETAILED INSPECTION (INTERNAL) OF ELEVATOR COMPONENTS:- TORQUE TUBE FITTINGS (SSI 55-20-34)- TAB WHEEL DRIVE SUPPORT FITTINGS (SSI 55-20-35)								Service ATA:55
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 55-20-00PROC. REF: NDT 55-20-00									
55-20-00-220-802-L00 S	DETAILED INSPECTION (EXTERNAL) OF ELEVATOR COMPONENTS:- TAB HINGE FITTINGS (SSI 55-20-36)								Service ATA:55
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 55-20-00PROC. REF: NDT 55-20-00									
55-20-00-220-C01-L00 S	DETAILED INSPECTION (INTERNAL) OF ELEVATOR COMPONENTS:- RIBS, BETWEEN ROOT AND STA. YH=160(SSI 55-20-29)- RIBS, BETWEEN STA. YH=160 AND STA. YH=983.4 (SSI 55-20-30)- RIBS, BETWEEN STA. YH=3001 AND STA. YH=3320 (SSI 55-20-33)								Service ATA:55
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: CPM 55-20-00PROC. REF: CPM 55-20-00									
55-20-00-290-C01-L00 S	DETAILED INSPECTION (INTERNAL) OF ELEVATOR COMPONENTS USING A BOROSCOPE:- RIBS, BETWEEN STA. YH=983,4 AND STA. YH=1898 (SSI 55-20-31)- RIBS, BETWEEN STA. YH=1898 AND STA. YH=3001 (SSI 55-20-32)								Service ATA:55
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: CPM 55-20-00PROC. REF: CPM 55-20-00									

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 55 - STABILIZERS									
55-30-00-210-802-L00 S	GENERAL VISUAL INSPECTION(INTERNAL) OF VERTICAL STABILIZER COMPONENTS:- SPAR 2 (WEB AND CAP),FROM FUSELAGE CONTOUR LINE TO TIP RIB STA. ZV=3015 (SSI 55-30-67)- SPAR 1 (WEB AND CAP),FROM FUSELAGE CONTOUR LINE TO TIP RIB (SSI 55-30-68) (L600 ONLY)								Service ATA:55
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 55-30-00PROC. REF: NDT 55-30-00									
55-30-00-210-C01-L00 S	GENERAL VISUAL INSPECTION (EXTERNAL) OF VERTICAL STABILIZER COMPONENTS:- SKIN AT WINDOWS FROM FUSELAGE TO STA. ZV=1169 (SSI 55-30-44)								Service ATA:55
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5009
PROC. REF: CPM 55-30-00PROC. REF: CPM 55-30-00									
55-30-00-210-C02-L00 S	GENERAL VISUAL INSPECTION (EXTERNAL) OF VERTICAL STABILIZER COMPONENTS:- SKIN AT SPAR 3, AUXILIARY SPAR 52%, AND STRINGERS46.5% & 57.65%, BETWEEN FUSELAGE & RIB STA. ZV=1169 (SSI 55-30-39)- SKIN AT SPAR 3, AUXILIARY SPAR 52%, AND STRINGERS46.5% & 57.65%, BETWEEN RIBS STA. ZV=1169 & STA. ZV=2799 (SSI 55-30-41)- SKIN AT SPAR 3, AUXILIARY SPAR 52%, AND STRINGERS 46.5% & 57.65%, BETWEEN RIB STA. ZV=2799 & HORIZONTAL STABILIZER (SSI 55-30-43)- SKIN AT WINDOWS BETWEEN STA. ZV=1169 & STA. ZV=2799 (SSI 55-30-45)- SKIN AT RIBS, BETWEEN STA.ZV=1169 AND STA. ZV=2799 (SSI 55 -30-48)- SKIN AT RIBS, BETWEEN STA. ZV=2799 AND HORIZONTAL STABILIZER (SSI 55-30-49)								Service ATA:55
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: CPM 55-30-00PROC. REF: CPM 55-30-00									
55-30-00-210-C03-L00 S	GENERAL VISUAL INSPECTION (EXTERNAL) OF VERTICAL STABILIZER COMPONENTS:- SKIN AT RIBS FROM FUSE- LAGE TO STA. ZV=1169 (SSI 55-30-47)								Service ATA:55
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5009
PROC. REF: CPM 55-30-00PROC. REF: CPM 55-30-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 55 - STABILIZERS									
55-30-00-210-C04-L00 S	GENERAL VISUAL INSPECTION (INTERNAL) OF VERTICAL STABILIZER COMPONENTS:- RIBS (STA. ZV=3461, ZV=2538, ZV=1677,ZV=1550.5, ZV=1430.5, ZV=1423, ZV=1302, ZV=1169 AND ZV=915) (SSI 55-30-73)								Service ATA:55
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5009
PROC. REF: CPM 55-30-00PROC. REF: CPM 55-30-00									
55-30-00-210-C05-L00 S	GENERAL VISUAL INSPECTION (EXTERNAL) OF VERTICAL STABILIZER COMPONENTS:- SKIN AT SPARS 1, 2, AUXIL- IARY SPAR 41% AND STRINGERS 20% & 35.5% BETWEEN FUSELAGE & RIB STA. ZV=1169 (SSI 55-30-38)- SKIN AT SPARS 1, 2, AUXIL- IARY SPAR 41% AND STRING- ERS 20% & 35.5% BETWEEN RIBS STA. ZV=1169 & STA. ZV=2799 (SSI 55-30-40)- SKIN AT SPARS 1, 2, AUXILIARY SPAR 41% ANDSTRINGERS 20% & 35.5% BETWEEN RIB STA. ZV=2799 & HORIZONTAL STABILIZER (SSI 55-30-42)- SKIN AT WINDOWS BETWEEN STA. ZV=2799AND HORIZONTAL STABILIZER (SSI 55-30-46)								Service ATA:55
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5009
PROC. REF: CPM 55-30-00PROC. REF: CPM 55-30-00									
55-30-00-220-801-L00 S	DETAILED INSPECTION (INTERNAL) OF VERTICAL STABILIZER COMPONENTS:- TIP RIB (SSI 55-30-69)								Service ATA:55
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 55-30-00PROC. REF: NDT 55-30-00									
55-30-00-220-802-L00 S	DETAILED INSPECTION (INTERNAL) OF VERTICAL STABILIZER COMPONENTS:- FIN-TO-FUSELAGE ATTACHMENT FITTING TO SPAR 1 (SSI 55-30-58)- FIN-TO-FUSELAGE ATTACHMENT FITTING TO BULKHEAD 77 (SSI 55-30-59) (L600 ONLY)								Service ATA:55
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 55-30-00PROC. REF: NDT 55-30-00									
55-30-00-220-804-L00 S	DETAILED INSPECTION (INTERNAL) OF VERTICAL STABILIZER COMPONENTS:- FITTING HINGE SUPPORT (SSI 55-30-76) (L600 ONLY)								Service ATA:55
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 55 - STABILIZERS									
PROC. REF: NDT 55-30-00PROC. REF: NDT 55-30-00									
55-30-00-220-805-L00 S	DETAILED INSPECTION (INTERNAL) OF VERTICAL STABILIZER COMPONENTS:- FIN-TO-FUSELAGE ATTACH- MENT FITTING TO SPAR 3 (SSI 55-30-54)- FIN-TO-FUSELAGE ATTACH- MENT FITTING TO BULKHEAD 78 (SSI 55-30-60)- FIN-TO-FUSELAGE ATTACH- MENT FITTING TO BULKHEAD 79 (SSI 55-30-61)- FIN-TO-FUSELAGE ATTACH- MENT FITTING TO BULKHEAD 80 (SSI 55-30-62)- SPAR 41% (WEB AND CAP), FROM STA. ZV=1550.5, INCLUDING ATTACHMENT BOLTS (SSI 55-30-66) (L600 ONLY)							Service	ATA:55
	MOS	29-Jun-23	96 (+15d/-15d)				LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 55-30-00PROC. REF: NDT 55-30-00									
55-30-00-220-806-L00 S	DETAILED INSPECTION (INTERNAL) OF VERTICAL STABILIZER COMPONENTS:- FIN-TO-FUSELAGE ATTACH- MENT FITTING TO AUXILIARY SPAR 52% (SSI 55-30-55)- FIN-TO-FUSELAGE ATTACH- MENT FITTING TO AUXILIARY SPAR 41% (SSI 55-30-56)- SPAR 3 (WEB AND CAP), FROM FUSELAGE CONTOUR LINE TO TIP RIB, INCLUDINGATTACHMENT BOLTS (SSI 55-30-63)- SPAR 52% (WEB AND CAP),FROM FUSELAGE CONTOUR LINE TO TIP RIB, INCLUDING ATTACHMENT BOLTS (SSI 55-30-64)- SPAR 41% (WEB AND CAP), FROM STA. ZV=2538 TO TIP RIB, INCLUDING ATTACHMENT BOLTS (SSI 55-30-65)- FIN-TO-HORIZONTAL STABILIZER SUPPORT ACTUATORS, INCLUDING BOLT (SSI 55-30-75)- ACTUATOR SUPPORT FITTINGS (RUDDER) (SSI 55-30-79)- PCU SUPPORT FITTINGS (SSI 55-30-80) (L600 ONLY)							Service	ATA:55
	MOS	27-Aug-07	288 (+15d/-15d)				LOW UTILIZATION		
	HRS	0	12000 (+20/-20)						
	AFL	0	6000 (+20/-20)						
									PKG:5140
PROC. REF: NDT 55-30-00PROC. REF: NDT 55-30-00									
55-30-00-220-807-L00 S	DETAILED INSPECTION (INTERNAL) OF VERTICAL STABILIZER COMPONENTS:- FIN-TO-FUSELAGE ATTACH- MENT FITTING TO SPAR 2 (SSI 55-30-57) (L600 ONLY)							Service	ATA:55
	MOS	27-Aug-07	288 (+15d/-15d)				LOW UTILIZATION		
	HRS	0	12000 (+20/-20)						
	AFL	0	6000 (+20/-20)						
									PKG:5140
PROC. REF: NDT 55-30-00PROC. REF: NDT 55-30-00									
55-30-00-220-808-L00	DETAILED INSPECTION (INTERNAL) OF VERTICAL STABILIZER COMPONENTS:- SPAR 2 (WEB AND CAP), FROM FUSELAGE CONTOUR LINE TO TIP RIB STA. ZV=3015 (SSI55-30-67)- SPAR 1 (WEB AND CAP), FROM FUSELAGE CONTOUR LINE TO TIP RIB (SSI 55-30-68) (L650 ONLY)							Service	ATA:55
	MOS/MSC	25-Sep-07	N/A				STRUCTURAL		
	HRS	0							
	AFL	0							
									PKG:6032

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 55 - STABILIZERS									
PROC. REF: NDT 55-30-00PROC. REF: NDT 55-30-00									
55-30-00-220-809-L00	DETAILED INSPECTION (INTERNAL) OF VERTICAL STABILIZER COMPONENTS:- FIN-TO-FUSELAGE ATTACHMENT FITTING TO SPAR 1 (SSI 55-30-58)- FIN-TO-FUSELAGE ATTACHMENT FITTING TO BULKHEAD 77 (SSI 55-30-59) (L650 ONLY)								Service ATA:55
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL	
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: NDT 55-30-00PROC. REF: NDT 55-30-00									
55-30-00-220-810-L00	DETAILED INSPECTION (INTERNAL) OF VERTICAL STABILIZER COMPONENTS:- FITTING HINGE SUPPORT (SSI 55-30-76) (L650 ONLY)								Service ATA:55
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL	
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: NDT 55-30-00PROC. REF: NDT 55-30-00									
55-30-00-220-811-L00	DETAILED INSPECTION (INTERNAL) OF VERTICAL STABILIZER COMPONENTS:- FIN-TO-FUSELAGE ATTACHMENT FITTING TO SPAR 3 (SSI 55-30-54)- FIN-TO-FUSELAGE ATTACHMENT FITTING TO BULKHEAD 78 (SSI 55-30-60)- FIN-TO-FUSELAGE ATTACHMENT FITTING TO BULKHEAD 79 (SSI 55-30-61)- FIN-TO-FUSELAGE ATTACHMENT FITTING TO BULKHEAD 80 (SSI 55-30-62)- SPAR 41% (WEB AND CAP), FROM STA. ZV=1550.5,INCLUDING ATTACHMENT BOLTS (SSI 55-30-66) (L650 ONLY)								Service ATA:55
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL	
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: NDT 55-30-00PROC. REF: NDT 55-30-00									
55-30-00-220-812-L00	DETAILED INSPECTION (INTERNAL) OF VERTICAL STABILIZER COMPONENTS:- FIN-TO-FUSELAGE ATTACHMENT FITTING TO AUXILIARY SPAR 52% (SSI 55-30-55)- FIN-TO-FUSELAGE ATTACH- MENT FITTING TO AUXILIARY SPAR 41% (SSI 55-30-56)- SPAR 3 (WEB AND CAP), FROM FUSELAGE CONTOUR LINE TO TIP RIB, INCLUDING ATTACH- MENT BOLTS (SSI 55-30-63)- SPAR 52% (WEB AND CAP), FROM FUSELAGE CONTOUR LINE TO TIP RIB, INCLUDING ATTACH- MENT BOLTS (SSI 55-30- 64)- SPAR 41% (WEB AND CAP), FROM STA. ZV=2538 TO TIP RIB, INCLUDING ATTACHMENT BOLTS (SSI 55-30-65)- FIN-TO-HORIZONTAL STABILIZER SUPPORT ACTUATORS, INCLUD- ING BOLT (SSI 55-30-75)- ACTUATOR SUPPORT FITTINGS (RUDDER) (SSI 55-30-79)- PCU SUPPORT FITTINGS (SSI 55-30-80) (L650 ONLY)								Service ATA:55
	MOS/MSC	27-Aug-07	N/A						
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: NDT 55-30-00PROC. REF: NDT 55-30-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 55 - STABILIZERS									
55-30-00-220-813-L00	DETAILED INSPECTION (INTERNAL) OF VERTICAL STABILIZER COMPONENTS:- FIN-TO-FUSELAGE ATTACHMENT FITTING TO SPAR 2 (SSI 55-30-57) (L650 ONLY)								Service ATA:55
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL	
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: NDT 55-30-00PROC. REF: NDT 55-30-00									
55-30-00-220-C01-L00 S	DETAILED INSPECTION (INTERNAL) OF VERTICAL STABILIZER COMPONENTS:- ROOT RIB, INCLUDING BOLTS (SSI 55-30-70)- RIBS OF ACTUATOR AREA (STA. ZV=1932 AND ZV=2277) (SSI 55-30-72)								Service ATA:55
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5009
PROC. REF: CPM 55-30-00PROC. REF: CPM 55-30-00									
55-30-00-220-C02-L00 S	DETAILED INSPECTION (INTERNAL) OF VERTICAL STABILIZER COMPONENTS:- RIBS OF HORIZONTAL STABILIZER ACTUATORS (STA. ZV=3145, ZV=3015 AND ZV=2799) (SSI 55-30-71)- REAR SPAR ACTUATOR SUPPORT FITTING (ELEVA- TOR) (SSI 55-30-77)								Service ATA:55
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: CPM 55-30-00PROC. REF: CPM 55-30-00									
55-30-00-220-C03-L00 S	DETAILED INSPECTION (INTERNAL) OF VERTICAL STABILIZER COMPONENTS:- SPAR 1 - TIP RIB ATTACH- MENT (SSI 55-30-53)								Service ATA:55
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: CPM 55-30-00PROC. REF: CPM 55-30-00									
55-30-00-220-C04-L00 S	DETAILED INSPECTION (EXTERNAL) OF VERTICAL STABILIZER COMPONENTS:- RUDDER HINGE FITTINGS (SSI 55-30-78)								Service ATA:55
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: CPM 55-30-00PROC. REF: CPM 55-30-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 55 - STABILIZERS									
55-30-00-220-C05-L00 S	DETAILED INSPECTION (INTERNAL) OF VERTICAL STABILIZER COMPONENTS:- FIN-TO-HORIZONTAL STABILIZER ATTACHMENT FITTING TO SPAR 3 (SSI 55-30-50)- FIN-TO-HORIZONTAL STABILIZER ATTACHMENT FITTING TO AUXILIARY SPAR 52% (SSI 55-30-51) - FIN-TO-HORIZONTAL STABILIZER ATTACHMENT FITTING TO AUXILIARY SPAR 41% (SSI 55-30-52)							Service	ATA:55
	MOS	29-Jun-23	48 (+15d/-15d)				LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: CPM 55-30-00PROC. REF: CPM 55-30-00									
55-30-00-250-801-L00 S	SPECIAL DETAILED INSPECTION (EXTERNAL) OF VERTICAL STABILIZER COMPONENTS BY THE EDDY CURRENT INSPECTION METHOD:- FITTING HINGE SUPPORT (SSI 55-30-76)							Service	ATA:55
	MOS	27-Aug-07	288 (+15d/-15d)				LOW UTILIZATION		
	HRS	0	12000 (+20/-20)						
	AFL	0	6000 (+20/-20)						
									PKG:5140
PROC. REF: NDT 55-30-00PROC. REF: NDT 55-30-00									
55-30-00-290-801-L00 S	SPECIAL DETAILED INSPECTION(EXTERNAL) OF VERTICAL STABILIZERCOMPONENTS USING BOROSCOPE. TRAILING EDGE RIBS (SSI 55-30-74).							Service	ATA:55
	MOS	29-Jun-23	96 (+15d/-15d)				LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 55-30-00PROC. REF: NDT 55-30-00									
55-40-00-210-C01-L00 S	GENERAL VISUAL INSPECTION (EXTERNAL) OF RUDDER COMPONENTS:- FRONT SPAR - SKIN ATTACHMENT (RUDDER I)(SSI 55-40-81)- REAR SPAR - SKIN ATTACHMENT (RUDDER I)(SSI 55-40-82)- LT & RT SKIN - SPAR CAP ATTACHMENT (RUDDER I)(SSI 55-40-83)- RIBS - SKIN ATTACHMENT (RUDDER I) (SSI 55-40-84)- HINGES - RUDDER I (SSI 55-40-85)							Service	ATA:55
	MOS	29-Jun-23	48 (+15d/-15d)				LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: CPM 55-40-00PROC. REF: CPM 55-40-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 55 - STABILIZERS									
55-40-00-210-C02-L00 S	GENERAL VISUAL INSPECTION (EXTERNAL) OF RUDDER COMPONENTS:- SPAR - SKIN ATTACHMENT (RUDDER II) (SSI 55- 40- 86)- LT & RT SKIN - SPAR CAP ATTACHMENT (RUDDER II) (SSI 55-40-87)- RIBS - SKIN ATTACHMENT (RUDDER II) (SSI 55-40-88)- HINGES - RUDDER II (SSI 55-40-89)								Service ATA:55
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: CPM 55-40-00PROC. REF: CPM 55-40-00									
55-40-00-220-C01-L00 S	DETAILED INSPECTION (INTERNAL) OF RUDDER COMPONENTS:- FRONT SPAR - SKIN ATTACH- MENT (RUDDER I)(SSI 55-40-81)- REAR SPAR - SKIN ATTACH- MENT (RUDDER I)(SSI 55-40-82)- LT & RT SKIN - SPAR CAP ATTACHMENT (RUDDER I)(SSI 55-40-83)- RIBS - SKIN ATTACHMENT (RUDDER I) (SSI 55-40-84)- HINGES - RUDDER I (SSI 55-40-85)								Service ATA:55
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: CPM 55-40-00PROC. REF: CPM 55-40-00									
55-40-00-220-C02-L00 S	DETAILED INSPECTION (INTERNAL) OF RUDDER COMPONENTS:- SPAR - SKIN ATTACHMENT (RUDDER II) (SSI 55-40-86)- LT & RT SKIN - SPAR CAP ATTACHMENT (RUDDER II) (SSI 55-40-87)- RIBS - SKIN ATTACHMENT (RUDDER II) (SSI 55-40-88)- HINGES - RUDDER II (SSI 55-40-89)								Service ATA:55
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: CPM 55-40-00PROC. REF: CPM 55-40-00									
55-Z321-213-001-A00 S	GENERAL VISUAL INSPECTION(EXTERNAL) (ZONES 321, 322, 323)								Service ATA:55
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 05-20-65PROC. REF: AMM 05-20-65									
55-Z321-214-001-A00 S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 321, 322, 323, 337)								Service ATA:55
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 55 - STABILIZERS									
PROC. REF: AMM 05-20-65PROC. REF: AMM 05-20-65									
55-Z324-213-001-A00 S	GENERAL VISUAL INSPECTION(EXTERNAL) (ZONES 324, 325)							Service	ATA:55
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 05-20-58PROC. REF: AMM 05-20-58									
55-Z324-214-001-A00 S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 324, 325) (L600 ONLY)							Service	ATA:55
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 05-20-58PROC. REF: AMM 05-20-58									
55-Z324-214-001-A01	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 324, 325)NOTE:EWIS (L650 ONLY)							Service	ATA:55
	MOS/MSC	25-Sep-07	N/A					ZONAL	
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: AMM 05-20-58PROC. REF: AMM 05-20-58									
55-Z326-213-001-A00 S	GENERAL VISUAL INSPECTION(EXTERNAL) (ZONES 326, 327)							Service	ATA:55
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 05-20-48PROC. REF: AMM 05-20-48									
55-Z326-214-001-A00 S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 326, 327)							Service	ATA:55
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 05-20-48PROC. REF: AMM 05-20-48									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 55 - STABILIZERS									
55-Z333-213-001-A00 S	GENERAL VISUAL INSPECTION(EXTERNAL) (ZONES 331, 332, 333, 334)							Service	ATA:55
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 05-20-52PROC. REF: AMM 05-20-52									
55-Z333-214-001-A00 S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 331, 332, 333, 334)							Service	ATA:55
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 05-20-52PROC. REF: AMM 05-20-52									
55-Z335-213-001-A00 S	GENERAL VISUAL INSPECTION(EXTERNAL) (ZONE 335, 336)							Service	ATA:55
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 05-20-62PROC. REF: AMM 05-20-62									
55-Z335-214-001-A00 S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONE 335, 336)							Service	ATA:55
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 05-20-62PROC. REF: AMM 05-20-62									
551500-0101	LEFT LEADING EDGE HORIZ STABILIZER ASSEMBLY							Component	ATA:55
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 55-15-00PROC. REF: AMM 55-15-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 55 - STABILIZERS									
551500-0102	RIGHT LEADING EDGE HORIZ STABILIZER ASSEMBLY							Component	ATA:55
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 55-15-00PROC. REF: AMM 55-15-00									
551500-0103	LEADING EDGE ASSY ASSEMBLY							Component	ATA:55
PN:145-03435-413	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:0000134776	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 55-15-00, AMM 55-35-00PROC. REF: AMM 55-15-00, AMM 55-35-00									
551500-0104	LEADING EDGE ASSY ASSEMBLY							Component	ATA:55
PN:145-03435-414	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:0000160169	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 55-15-00, AMM 55-35-00PROC. REF: AMM 55-15-00, AMM 55-35-00									
551500-0201	LH FAIRING ASSY							Component	ATA:55
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 55-13-01PROC. REF: AMM 55-13-01									
551500-0202	RH FAIRING ASSY							Component	ATA:55
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 55-13-01PROC. REF: AMM 55-13-01									
551500-0301	LH FAIRING ASSY							Component	ATA:55
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 55-14-00PROC. REF: AMM 55-14-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 55 - STABILIZERS									
551500-0302	RH FAIRING ASSY							Component	ATA:55
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 55-14-00	PROC. REF: AMM 55-14-00								
553400-0101	REAR FUS DORSAL FIN ASSY							Component	ATA:55
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 55-34-00	PROC. REF: AMM 55-34-00								
553600-0101	FRONT FIXED FAIRING ASSY							Component	ATA:55
PN:145-21643-421	MOS/MSC	19-Aug-15	O/C	TSN 96, TSR 0					
SN:0000127727	HRS	7460.3		TSN 7460.3, TSR 0					
	AFL	3992		TSN 3992, TSR 0					
PROC. REF: AMM 55-36-02	PROC. REF: AMM 55-36-02								
553600-0102	REAR FIXED FAIRING ASSY							Component	ATA:55
PN:145-21646-403	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:0000130993	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 55-36-02	PROC. REF: AMM 55-36-02								
553600-0103	FRONT MOVING FAIRING ASSY							Component	ATA:55
PN:145-21644-401	MOS/MSC	19-Aug-15	O/C	TSN 96, TSR 0					
SN:0000126684	HRS	7460.3		TSN 7460.3, TSR 0					
	AFL	3992		TSN 3992, TSR 0					
PROC. REF: AMM 55-36-00	PROC. REF: AMM 55-36-00								
553600-0104	REAR MOVING FAIRING ASSY							Component	ATA:55
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 55-36-00	PROC. REF: AMM 55-36-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 56 - WINDOWS									
56-10-01-220-001-A00 S	INSPECT (DETAILED INSPECTION) THE WINDSHIELD HUMP SEAL								Service ATA:56
	MOS	17-Oct-25	12 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	500 (+20/-20)						
	AFL	5820							
									PKG:5002
PROC. REF: AMM 56-10-01PROC. REF: AMM 56-10-01									
56-10-01-720-001-A00	FUNCTIONALLY CHECK TORQUE OF WINDSHIELDATTACHING BOLTSNOTE: APPLICABLE TO AIRCRAFT PRE-MOD. SB145LEG-56-0001 (L600 ONLY)								Service ATA:56
	MOS/MSC	15-Aug-13	N/A	Adj 12d				EMB-RECOMM	
	HRS	6643.4							
	AFL	3572							
PROC. REF: AMM 56-10-01PROC. REF: AMM 56-10-01									
56-10-01-720-001-A01	FUNCTIONALLY CHECK TORQUE OF WINDSHIELD ATTACHING BOLTS - FRONTAL WINDSHIELD ASSY, (LH)								Service ATA:56
PN:NP-151311-19	MOS	25-Aug-22						EMB-RECOMM	
SN:20118H0238	HRS	9956.8	10000		19956.8		8680.5		
	AFL	5293							
PROC. REF: AMM 56-10-01PROC. REF: AMM 56-10-01									
56-10-01-720-001-A01	FUNCTIONALLY CHECK TORQUE OF WINDSHIELD ATTACHING BOLTS - FRONTAL WINDSHIELD ASSY, (RH)								Service ATA:56
PN:NP-151311-20	MOS	25-Aug-22						EMB-RECOMM	
SN:20084H7588	HRS	9956.8	10000		19956.8		8680.5		
	AFL	5293							
PROC. REF: AMM 56-10-01PROC. REF: AMM 56-10-01									
56-10-01-CUS-0701 U	PERFORM PERMANENT REPAIR OF RH WINDOW HUMPSEAL								Service ATA:56
	MOS/MSC	01-Mar-19	-						
	HRS	8966							
	AFL	4791							
56-10-01-CUS-0702 U	GENERAL VISUAL INSPECTION OF RH WINDOW HUMPSEAL TEMPORARY REPAIR FOR TAPE INTEGRITY								Service ATA:56
	DAYS/MSC	01-Mar-19	-						
	HRS	8966							
	AFL	4791							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 56 - WINDOWS									
561000-0101		LEFT ELECTRICALLY HEATED, WITH RRC - FRONTAL WINDSHIELD ASSY, (LH)						Component	ATA:56
PN:NP-151311-19	MOS/MSC	25-Aug-22	O/C	TSN 0					
SN:20118H0238	HRS	9956.8		TSN 0					
	AFL	5293		TSN 0					
PROC. REF: AMM 56-10-01PROC. REF: AMM 56-10-01									
561000-0102		RIGHT ELECTRICALLY HEATED, WITH RRC - FRONTAL WINDSHIELD ASSY, (RH)						Component	ATA:56
PN:NP-151311-20	MOS/MSC	25-Aug-22	O/C	TSN 0					
SN:20084H7588	HRS	9956.8		TSN 0					
	AFL	5293		TSN 0					
PROC. REF: AMM 56-10-01PROC. REF: AMM 56-10-01									
561100-0101		PILOT FITTING -MECHANISM,STORM WINDOW ASSEMBLY						Component	ATA:56
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									
561100-0102		COPILOT FITTING -MECHANISM,STORM WINDOW ASSEMBLY						Component	ATA:56
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									
ATA 57 - WINGS									
57-01-00-220-C01-L00 S		DETAILED INSPECTION (INTERNAL) OF WING STUB COMPONENTS:- WING STUB - LOWER SKIN - RIB 2A ATTACHMENT(SSI 57-01-15)- WING STUB - SPAR 2 - BRACKETS RIBS 2A ATTACHMENTS (SSI 57-01-17)- WING STUB - SPAR 1 - BRACKETS RIBS 2A ATTACHMENTS (SSI 57-01-16)						Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)				LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: CPM 57-01-00PROC. REF: CPM 57-01-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-01-00-220-C02-L00 S	DETAILED INSPECTION (INTERNAL) OF WING STUB COMPONENTS:- WING STUB - RIB 2A SKIN SUPPORTS AND THEIRATTACHMENTS TO WEB, LOWER FLANGE, AND FWD & AFT WEB SUPPORTS (SSI 57-01-18)- WING STUB - UPPER SKIN - RIB 2A ATTACHMENTS(SSI 57-01-19)								Service ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: CPM 57-01-00PROC. REF: CPM 57-01-00									
57-01-00-220-C03-L00 S	DETAILED INSPECTION (EXTERNAL) OF WING STUB COMPONENTS:- WING STUB - LOWER SKIN - RIB 2A ATTACHMENT(SSI 57-01-15)								Service ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: CPM 57-01-00PROC. REF: CPM 57-01-00									
57-01-00-220-C04-L00 S	DETAILED INSPECTION (EXTERNAL) OF WING STUB COMPONENTS:- WING STUB - UPPER SKIN - RIB 2A ATTACHMENTS(SSI 57-01-19)								Service ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: CPM 57-01-00PROC. REF: CPM 57-01-00									
57-10-00-210-801-L00 S	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING STUB COMPONENTS:- SPAR 2 - BRACKETS AND RIB 2A WEB ATTACHMENTS (SSI 57-10-27)								Service ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 57-10-00PROC. REF: NDT 57-10-00									
57-10-00-210-C01-L00 S	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING STUB COMPONENTS:- UPPER SKIN - TIRE COMPARTMENT COMPOSITE PANEL (SSI 57-10-14)								Service ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: CPM 57-10-00PROC. REF: CPM 57-10-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-10-00-220-801-L00 S	DETAILED INSPECTION (EXTERNAL) OF WING STUB COMPONENTS:- SPAR 1 - AUXILIARY CAPATTACHMENTS & AUXILIARY CAP SPLICE AT WING ATTACHMENTS (SSI 57-10-05)- LOWER SKIN - RIBS 1, 2 & 3 ATTACHMENTS AND TIRE COMPARTMENT WALL ATTACHMENTS (SSI 57-10-02)- SPAR 1 - LOWER SKIN ATTACHMENTS (SSI 57-10-03)NOTE: DURING THIS INSPECTION, THE CPCP BASICTASK SHALL ALSO BE PERFORMED FOR THESE SSIS							Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)				LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: NDT 57-10-00PROC. REF: NDT 57-10-00									
57-10-00-220-802-L00 S	DETAILED INSPECTION (INTERNAL) OF WING STUB COMPONENTS:- SPAR 2 - BRACKETS AND RIB 2A WEB ATTACHMENTS (SSI 57-10-27)- SPAR 1 - LOWER SKIN ATTACHMENTS (SSI 57-10-03)- SPAR 1 - AUXILIARY CAP ATTACHMENTS & AUXILIARY CAP SPLICE AT WING ATTACH- MENTS (SSI 57-10-05) (L600 ONLY)							Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)				LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: NDT 57-10-00PROC. REF: NDT 57-10-00									
57-10-00-220-803-L00 S	DETAILED INSPECTION (INTERNAL) OF WING STUB COMPONENTS:- LOWER SKIN - RIBS 1, 2 & 3 ATTACHMENTS AND TIRE COMPARTMENT WALL ATTACHMENTS(SSI 57-10-02)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI							Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)				LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: NDT 57-10-00PROC. REF: NDT 57-10-00									
57-10-00-220-804-L00 S	DETAILED INSPECTION (EXTERNAL) OF WING STUB COMPONENTS:- LOWER SKIN - SPANWISE SPLICE AT SPAR 2, ACCESS HOLES, STRINGERS, INTEGRAL MILLED PANELS & SPANWISE SPLICE OF INTEGRAL PANEL (SSI 57-10-01)- SPAR 2 - LOWER SKIN ATTACHMENTS (SSI 57-10-06)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI'S (L600 ONLY)							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)				LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016
PROC. REF: NDT 57-10-00PROC. REF: NDT 57-10-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-10-00-220-805-L00 S		DETAILED INSPECTION (INTERNAL) OF WING STUB COMPONENTS:- LOWER SKIN - SPANWISE SPLICE AT SPAR 2, ACCESS HOLES, STRINGERS, INTEGRAL MILLED PANELS & SPANWISE SPLICE OF INTEGRAL PANEL (SSI 57-10-01)- SPAR 2 - LOWER SKIN ATTACH- MENTS (SSI 57-10-06)- SPAR 2 - AUXILIARY CAP ATTACHMENTS AND AUXILIARYCAP SPLICE AT WING ATTACH- MENTS (SSI 57-10-08) NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI¿S 57-10-06 AND 57-10-08 (L600 ONLY)						Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)				LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016
PROC. REF: NDT 57-10-00PROC. REF: NDT 57-10-00									
57-10-00-220-806-L00		DETAILED INSPECTION (INTERNAL) OF WING STUB COMPONENTS:- SPAR 2 - BRACKETS AND RIB 2A WEB ATTACHMENTS (SSI 57-10-27)- SPAR 1 - LOWER SKIN ATTACH- MENTS (SSI 57-10-03)- SPAR 1 - AUXILIARY CAP ATTACHMENTS & AUXILIARYCAP SPLICE AT WING ATTACH- MENTS (SSI 57-10-05) (L650 ONLY)						Service	ATA:57
	MOS/MSC	25-Sep-07	N/A				STRUCTURAL		
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: NDT 57-10-00PROC. REF: NDT 57-10-00									
57-10-00-220-807-L00		DETAILED INSPECTION (EXTERNAL) OF WING STUB COMPONENTS:- LOWER SKIN - SPANWISE SPLICE AT SPAR 2, ACCESS HOLES, STRINGERS, INTEGRAL MILLED PANELS & SPANWISE SPLICE OF INTEGRAL PANEL (SSI 57-10-01)- SPAR 2 - LOWER SKIN ATTACH- MENTS (SSI 57-10- 06)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI¿S (L650 ONLY)						Service	ATA:57
	MOS/MSC	25-Sep-07	N/A				STRUCTURAL		
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: NDT 57-10-00PROC. REF: NDT 57-10-00									
57-10-00-220-808-L00		DETAILED INSPECTION (INTERNAL) OF WING STUB COMPONENTS:- LOWER SKIN - SPANWISE SPLICE AT SPAR 2, ACCESS HOLES, STRINGERS, INTEGRAL MILLED PANELS & SPANWISE SPLICE OF INTEGRAL PANEL (SSI 57-10-01)- SPAR 2 - LOWER SKIN ATTACH- MENTS (SSI 57-10-06)- SPAR 2 - AUXILIARY CAP ATTACHMENTS AND AUXILIARY CAP SPLICE AT WING ATTACH- MENTS (SSI 57-10-08) NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI¿S 57-10-06 AND 57-10-08 (L650 ONLY)						Service	ATA:57
	MOS/MSC	25-Sep-07	N/A				STRUCTURAL		
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: NDT 57-10-00PROC. REF: NDT 57-10-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-10-00-220-C01-L00 S	DETAILED INSPECTION (INTERNAL) OF WING STUB COMPONENTS:- SPAR 1 - BRACKETS, RIBS 1 AND 3 ATTACHMENTS(SSI 57-10-04)- SPAR 2 - CENTER BRACKETS & RIB 2 ATTACHMENTS AND RIBS 1 & 3 WEB ATTACHMENTS (SSI 57-10-07)							Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: CPM 57-10-00PROC. REF: CPM 57-10-00									
57-10-00-220-C02-L00 S	DETAILED INSPECTION (EXTERNAL) OF WING STUB COMPONENTS:- UPPER SKIN - RIB 1 ATTACHMENTS AND SPANWISE SPLICE OF INTEGRAL PANEL (SSI 57-10-13)							Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: CPM 57-10-00PROC. REF: CPM 57-10-00									
57-10-00-220-C03-L00 S	DETAILED INSPECTION (EXTERNAL) OF WING STUB COMPONENTS:- RIB 4 - LOWER FLANGE AND WEB (SSI 57-10-11)							Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: CPM 57-10-00PROC. REF: CPM 57-10-00									
57-10-00-220-C04-L00 S	DETAILED INSPECTION (EXTERNAL) OF WING STUB COMPONENTS:- SPAR 3 - LOWER SKIN ATTACHMENTS (SSI 57-10-09)							Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: CPM 57-10-00PROC. REF: CPM 57-10-00									
57-10-00-220-C05-L00 S	DETAILED INSPECTION (INTERNAL) OF WING STUB COMPONENTS:- SPAR 3 - LOWER SKIN ATTACHMENTS (SSI 57-10-09)- UPPER SKIN - TIRE COMPARTMENT COMPOSITE PANEL (SSI 57-10-14)							Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: CPM 57-10-00PROC. REF: CPM 57-10-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-10-00-220-C06-L00 S	DETAILED INSPECTION (INTERNAL) OF WING STUB COMPONENTS:- UPPER SKIN - RIB 1 ATTACH- MENTS AND SPANWISE SPLICE OF INTEGRAL PANEL (SSI 57-10-13)							Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: CPM 57-10-00PROC. REF: CPM 57-10-00									
57-10-00-220-C07-L00 S	DETAILED INSPECTION (INTERNAL) OF WING STUB COMPONENTS:- RIB 4 - LOWER FLANGE AND WEB (SSI 57-10-11)- RIB 2 - LONGITUDINAL STRINGER- TO- WEB ATTACHMENTS (SSI 57-10-12)							Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: CPM 57-10-00PROC. REF: CPM 57-10-00									
57-10-00-220-C08-L00 S	DETAILED INSPECTION (INTERNAL) OF WING STUB COMPONENTS:- SPAR 3 - CENTER BRACKET AND RIB 2 ATTACHMENTS (SSI 57-10-10)							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: CPM 57-10-00PROC. REF: CPM 57-10-00									
57-10-00-250-803-L00 S	SPECIAL DETAILED INSPECTION (INTERNAL) OF WING STUB COMPONENTS BY THE EDDY CURRENT METHOD:- LOWER SKIN - SPANWISE SPLICE AT SPAR 2, ACCESS HOLES, STRINGERS, INTEGRAL MILLED PANELS & SPANWISE SPLICE OF INTEGRAL PANEL (SSI 57-10-01) (L600 ONLY)							Service	ATA:57
	MOS	27-Aug-07	T:288 (+15d/-15d)					LOW UTILIZATION	
	HRS	0	T:12000 (+20/-20)						
	AFL	0	T:6000 (+20/-20)						
									PKG:5025
PROC. REF: NDT 57-10-00PROC. REF: NDT 57-10-00									

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-11-00-220-801-L00 S	DETAILED INSPECTION (EXTERNAL) OF WING STUB COMPONENTS:- LOWER SKIN - REAR FITTING-TO- SKIN ATTACHMENTS AND SPARS 1 & 2 - STUB- TO- WING ATTACHMENTS (SSI 57-11-17)- FUSELAGE BULKHEAD AT FRAME 50 AND ITS ATTACH- MENTS TO FRAME 50 (SSI 57-11-25)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THESE SSIS							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)				LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 57-11-00PROC. REF: NDT 57-11-00									
57-11-00-220-802-L00 S	DETAILED INSPECTION (INTERNAL) OF WING STUB COMPONENTS:- LOWER SKIN - REAR FITTING-TO- SKIN ATTACHMENTS AND SPARS 1 & 2 - STUB-TO-WING ATTACHMENTS (SSI 57-11-17)- FUSELAGE BULKHEAD AT FRAME 50 AND ITS ATTACHMENTS TO FRAME 50 (SSI 57-11-25)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR SSI 57-11-25							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)				LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 57-11-00PROC. REF: NDT 57-11-00									
57-11-00-220-803-L00 S	DETAILED INSPECTION (EXTERNAL) OF WING STUB COMPONENTS:- SPAR 1 - LOWER FRONT FITTINGATTACHMENTS AND SPAR 2 - LOWER REAR FITTING ATTACH- MENTS (SSI 57-11-18)- SPAR 2 - TITANIUM FITTING ATTACHMENTS AND FUSELAGE BULKHEAD AT FRAME 46 (SSI 57-11-20)- SPAR 3 - FUSELAGE BULKHEAD ATTACHMENTS AT FRAME 50, L- SHAPE FUSELAGE FRAME 50 ATTACHMENTS & FUSELAGE STRINGERS ATTACH- MENTS (SSI 57-11-21)- SPAR 1 - TITANIUM FITTING ATTACHMENTS, FUSELAGE BULKHEAD ATTACHMENTS AT FRAME 40, L SHAPE FUSE- LAGE FRAME 40 ATTACHMENTS& FUSELAGE STRINGERS (SSI 57-11-19)NOTE: DURING THIS INSPECTION, THE CPCPBASIC TASK SHALL ALSO BE PERFORMED FOR SSIS 57-11-18 AND 57-11-20 (L600 ONLY)							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)				LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 57-11-00PROC. REF: NDT 57-11-00									
57-11-00-220-805-L00 S	DETAILED INSPECTION (INTERNAL) OF WING STUB COMPONENTS:- SPAR 1 - TITANIUM FITTING ATTACHMENTS, FUSELAGE BULKHEAD ATTACHMENTS AT FRAME 40, L SHAPE FUSELAGE FRAME 40 ATTACHMENTS & FUSELAGE STRINGERS ATTACHMENTS (SSI 57-11-19)- SPAR 3 - FUSELAGE BULKHEAD ATTACHMENTS AT FRAME 50, SHALL L- SHAPE FUSELAGE FRAME 50 ATTACHMENTS & FUSELAGE STRINGERS ATTACHMENTS (SSI 57-11-21)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR SSI 57-11-21							Service	ATA:57
	MOS	07-Jul-15	192 (+15d/-15d)				LOW UTILIZATION		
	HRS	7460.3	8000 (+20/-20)						
	AFL	3992	4000 (+20/-20)						
									PKG:5032,6032
PROC. REF: NDT 57-11-00PROC. REF: NDT 57-11-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-11-00-220-806-L00 S	DETAILED INSPECTION (INTERNAL) OF WING STUB COMPONENTS:- SPAR 1 - LOWER FRONT FITTING ATTACHMENTS AND SPAR 2 - LOWER REAR FITTING ATTACHMENTS (SSI 57-11-18)- SPAR 2 - TITANIUM FITTING ATTACHMENTS AND FUSELAGE BULKHEAD AT FRAME 46 (SSI 57-11-20) (L600 ONLY)								Service ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 57-11-00PROC. REF: NDT 57-11-00									
57-11-00-220-807-L00 S	DETAILED INSPECTION (EXTERNAL) OF WING STUB COMPONENTS:- SPAR 3 AND RIB 4 - ROD-END LINK (SSI 57-11-22)- FUSELAGE BULKHEAD AT FRAME 40 AND ITS ATTACHMENTS TO FRAME (SSI 57-11-23)- FUSELAGE BULKHEAD ATTACHMENT TO FRAME 46 (SSI 57-11-24)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THESE SSIS (L600 ONLY)								Service ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 57-11-00PROC. REF: NDT 57-11-00									
57-11-00-220-808-L00 S	DETAILED INSPECTION (INTERNAL) OF WING STUB COMPONENTS:- FUSELAGE BULKHEAD AT FRAME 40 AND ITS ATTACHMENTS TO FRAME 40 (SSI 57-11-23)- FUSELAGE BULKHEAD ATTACH- MENT TO FRAME 46 (SSI 57-11-24)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR SSI 57-11-24 (L600 ONLY)								Service ATA:57
	MOS	27-Aug-07	192 (+15d/-15d)					LOW UTILIZATION	
	HRS	0	8000 (+20/-20)						
	AFL	0	4000 (+20/-20)						
									PKG:5032
PROC. REF: NDT 57-11-00PROC. REF: NDT 57-11-00									
57-11-00-220-809-L00	DETAILED INSPECTION (EXTERNAL)OF WING STUB COMPONENTS:- SPAR 1 - LOWER FRONT FITTING ATTACHMENTS AND SPAR 2 - LOWER REAR FITTING ATTACHMENTS (SSI 57-11-18)- SPAR 2 - TITANIUM FITTING ATTACHMENTS AND FUSELAGE BULKHEAD AT FRAME 46 (SSI 57-11-20)- SPAR 3 - FUSELAGE BULKHEAD ATTACHMENTS AT FRAME 50, L- SHAPE FUSELAGE FRAME 50 ATTACHMENTS & FUSELAGE STRINGERS ATTACHMENTS (SSI 57-11-21)- SPAR 1 - TITANIUM FITTING ATTACHMENTS, FUSELAGE BULKHEAD ATTACHMENTS AT FRAME 40, L SHAPE FUSELAGE FRAME 40 ATTACHMENTS & FUSELAGE STRINGERS (SSI 57-11-19)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR SSIS 57-11-18 AND 57-11-20 (L650 ONLY)								Service ATA:57
	MOS/MSC	27-Aug-07	N/A						
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: NDT 57-11-00PROC. REF: NDT 57-11-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-11-00-220-810-L00	DETAILED INSPECTION (INTERNAL) OF WING STUB COMPONENTS:- SPAR 1 - LOWER FRONT FITTING ATTACHMENTS AND SPAR 2 - LOWER REAR FITTING ATTACHMENTS (SSI 57-11-18)- SPAR 2 - TITANIUM FITTING ATTACHMENTS AND FUSELAGE BULKHEAD AT FRAME 46 (SSI 57-11-20) (L650 ONLY)								Service ATA:57
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL	
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: NDT 57-11-00PROC. REF: NDT 57-11-00									
57-11-00-220-811-L00	DETAILED INSPECTION (EXTERNAL) OF WING STUB COMPONENTS:- SPAR 3 AND RIB 4 - ROD-END LINK (SSI 57-11-22)- FUSELAGE BULKHEAD AT FRAME 40 AND ITSATTACHMENTS TO FRAME (SSI 57-11-23)- FUSELAGE BULKHEAD ATTACHMENT TO FRAME 46 (SSI 57-11-24)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THESE SSIS (L650 ONLY)								Service ATA:57
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL	
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: NDT 57-11-00PROC. REF: NDT 57-11-00									
57-11-00-220-812-L00	DETAILED INSPECTION (INTERNAL) OF WING STUB COMPONENTS:- FUSELAGE BULKHEAD AT FRAME 40 AND ITSATTACHMENTS TO FRAME 40 (SSI 57-11-23)- FUSELAGE BULKHEAD ATTACHMENT TO FRAME 46 (SSI 57-11-24)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR SSI 57-11-24 (L650 ONLY)								Service ATA:57
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL	
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: NDT 57-11-00PROC. REF: NDT 57-11-00									
57-11-00-250-801-L00 S	SPECIAL DETAILED INSPECTION (INTERNAL) OF WING STUB COMPONENTS BY THE EDDY CURRENT INSPECTION METHOD:- LOWER SKIN - REAR FITTING-TO- SKIN ATTACHMENTS AND SPARS 1 & 2 - STUB-TO-WING ATTACHMENTS (SSI 57-11-17)								Service ATA:57
	MOS	27-Aug-07	288 (+15d/-15d)					LOW UTILIZATION	
	HRS	0	12000 (+20/-20)						
	AFL	0	6000 (+20/-20)						
									PKG:5140
PROC. REF: NDT 57-11-00PROC. REF: NDT 57-11-00									

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-21-00-210-801-L00 S	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS:- LOWER SKIN/SPAR ATTACH- MENTS (SSI 57-21-36)							Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008
PROC. REF: NDT 57-21-00PROC. REF: NDT 57-21-00									
57-21-00-210-806-L00 S	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS:- UPPER SKIN/SPAR ATTACH- MENT (SSI 57-21-37) (L600 ONLY)							Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008
PROC. REF: NDT 57-21-00PROC. REF: NDT 57-21-00									
57-21-00-210-809-L00 S	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS:- LOWER SKIN ACCESS HOLES (SSI 57-21-32)							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 57-21-00PROC. REF: NDT 57-21-00									
57-21-00-210-812-L00 S	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS:- LOWER SKIN PANEL SPANWISE JOINT (SSI 57-21-30)- UPPER SKIN PANEL SPANWISE JOINT (SSI 57-21-31)- UPPER SKIN/SPAR ATTACHMENT (SSI 57-21-37)							Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008
PROC. REF: NDT 57-21-00PROC. REF: NDT 57-21-00									
57-21-00-210-813-L00 S	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS:- LOWER SKIN PANEL CHORD- WISE JOINT (SSI 57-21-29)- LOWER SKIN PANEL SPANWISE JOINT (SSI 57-21-30)							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 57-21-00PROC. REF: NDT 57-21-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-21-00-210-814-L00 S	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS:- LOWER SKIN ACCESS HOLES (SSI 57-21-32)							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 57-21-00PROC. REF: NDT 57-21-00									
57-21-00-210-815-L00 S	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS:- LOWER SKIN PANEL SPANWISE JOINT (SSI 57-21-30)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 57-21-00PROC. REF: NDT 57-21-00									
57-21-00-210-816-L00 S	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS:- LOWER SKIN PANEL CHORD- WISE JOINT (SSI 57-21-29)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 57-21-00PROC. REF: NDT 57-21-00									
57-21-00-210-821-L00 S	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS:- LOWER SKIN/ SPAR ATTACH- MENTS (SSI 57-21-36)							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6016
PROC. REF: NDT 57-21-00PROC. REF: NDT 57-21-00									
57-21-00-210-822-L00 S	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS:- LOWER SKIN PANEL SPANWISE JOINT (SSI 57-21-30)							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 57-21-00PROC. REF: NDT 57-21-00									

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-21-00-210-823-L00 S	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS:- SKIN PANELS (SSI 57-21-26)							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 57-21-00PROC. REF: NDT 57-21-00									
57-21-00-210-824-L00 S	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS:- UPPER SKIN PANEL AT SPANWISE JOINT (SSI 57-21-31)							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 57-21-00PROC. REF: NDT 57-21-00									
57-21-00-210-825-L00	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS:- UPPER SKIN/SPAR ATTACHMENT (SSI 57-21-37) (L650 ONLY)							Service	ATA:57
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL	
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: NDT 57-21-00PROC. REF: NDT 57-21-00									
57-21-00-210-826-L00 S	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS:- LOWER SKIN ACCESS HOLES (SSI 57-21-32)							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6016
PROC. REF: NDT 57-21-00PROC. REF: NDT 57-21-00									
57-21-00-210-C01-L00 S	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS: - LOWER VENT HOLE (SSI 57-21-33) - GRAVITY FUEL HOLE (SSI 57-21-35)							Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5009
PROC. REF: CPM 57-21-00PROC. REF: CPM 57-21-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-21-00-210-C02-L00 S	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS:- UPPER SKIN/ SPAR ATTACHMENT (SSI 57-21-37)							Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5009
PROC. REF: CPM 57-21-00PROC. REF: CPM 57-21-00									
57-21-00-210-C04-L00 S	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS:- UPPER SKIN PANEL SPAN- WISE JOINT (SSI 57-21-31)							Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: CPM 57-21-00PROC. REF: CPM 57-21-00									
57-21-00-210-C06-L00 S	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS:- UPPER SKIN/ SPAR STUB ATTACHMENT (SSI 57-21-39)							Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: CPM 57-21-00PROC. REF: CPM 57-21-00									
57-21-00-210-C08-L00 S	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS:- SKIN PANELS (SSI 57-21-26)- UPPER SKIN PANEL SPAN- WISE JOINT (SSI 57-21-31)- UPPER SKIN/ SPAR ATTACH- MENT (SSI 57-21-37)							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: CPM 57-21-00PROC. REF: CPM 57-21-00									
57-21-00-210-C09-L00 S	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS:- LOWER SKIN ACCESS HOLES (SSI 57-21-32)							Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5009
PROC. REF: CPM 57-21-00PROC. REF: CPM 57-21-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-21-00-210-C10-L00 S	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS:- LOWER SKIN/ WING STUB ATTACHMENT (SSI 57-21-38)							Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: CPM 57-21-00PROC. REF: CPM 57-21-00									
57-21-00-210-C11-L00 S	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS:- GRAVITY FUEL HOLE (SSI 57-21-35)							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: CPM 57-21-00PROC. REF: CPM 57-21-00									
57-21-00-210-C13-L00 S	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS:- UPPER SKIN/ WING STUB ATTACHMENT (SSI 57-21-39)							Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: CPM 57-21-00PROC. REF: CPM 57-21-00									
57-21-00-210-C14-L00 S	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS:- SKIN PANELS (SSI 57-21-26)- UPPER SKIN PANEL SPAN- WISE JOINT (SSI 57-21-31) (L600 ONLY)							Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: CPM 57-21-00PROC. REF: CPM 57-21-00									
57-21-00-210-C15-L00 S	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS:- UPPER SKIN/ SPAR ATTACHMENT (SSI 57-21-37)							Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: CPM 57-21-00PROC. REF: CPM 57-21-00									

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-21-00-210-C16-L00 S	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS:- LOWER SKIN PANEL SPAN- WISE JOINT (SSI 57-21-30)							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: CPM 57-21-00PROC. REF: CPM 57-21-00									
57-21-00-210-C17-L00 S	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS:- LOWER SKIN/WING STUB ATTACHMENT (SSI 57-21-38)							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: CPM 57-21-00PROC. REF: CPM 57-21-00									
57-21-00-210-C18-L00 S	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS:- LOWER SKIN PANEL SPAN- WISE JOINT (SSI 57-21-30) (L600 ONLY)							Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: CPM 57-21-00PROC. REF: CPM 57-21-00									
57-21-00-220-801-L00 S	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS:- SKIN PANELS (SSI 57-21-26)							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6016
PROC. REF: NDT 57-21-00PROC. REF: NDT 57-21-00									
57-21-00-220-802-L00 S	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS:- LOWER SKIN ACCESS HOLES (SSI 57-21-32)							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6016
PROC. REF: NDT 57-21-00PROC. REF: NDT 57-21-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-21-00-220-803-L00 S	DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS:- LOWER SKIN/SPAR ATTACH- MENTS (SSI 57-21-36)							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6016
PROC. REF: NDT 57-21-00PROC. REF: NDT 57-21-00									
57-21-00-220-804-L00 S	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS:- ACTUATOR ACCESS HOLES (SSI 57-21-34)- LOWER SKIN/SPAR ATTACH - MENTS (SSI 57-21-36)							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6016
PROC. REF: NDT 57-21-00PROC. REF: NDT 57-21-00									
57-21-00-220-805-L00 S	DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS:- ACTUATOR ACCESS HOLES (SSI 57-21-34)							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 57-21-00PROC. REF: NDT 57-21-00									
57-21-00-220-806-L00 S	DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS:- LOWER SKIN ACCESS HOLES (SSI 57-21-32)							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 57-21-00PROC. REF: NDT 57-21-00									
57-21-00-220-807-L00 S	DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS:- UPPER SKIN / SPAR ATTACH- MENT (SSI 57-21-37)- SKIN PANELS (SSI 57-21-26)							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 57-21-00PROC. REF: NDT 57-21-00									

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-21-00-220-808-L00	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS - SKIN PANELS (SSI 57-21-26) (L650 ONLY)								Service ATA:57
	MOS/MSC	27-Aug-07	N/A						
	HRS	0							
	AFL	0							
PROC. REF: NDT 57-21-00PROC. REF: NDT 57-21-00									
57-21-00-220-C01-L00 S	DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS:- LOWER VENT HOLE (SSI 57-21-33)								Service ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: CPM 57-21-00PROC. REF: CPM 57-21-00									
57-21-00-220-C02-L00	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS:- SKIN PANELS (SSI 57-21-26)- UPPER SKIN PANEL SPAN- WISE JOINT (SSI 57-21-31) (L650 ONLY)								Service ATA:57
	MOS/MSC	25-Sep-07	N/A						
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: CPM 57-21-00PROC. REF: CPM 57-21-00									
57-21-00-220-C03-L00	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS:- LOWER SKIN PANEL SPAN- WISE JOINT (SSI 57-21-30) (L650 ONLY)								Service ATA:57
	MOS/MSC	25-Sep-07	N/A						
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: CPM 57-21-00PROC. REF: CPM 57-21-00									
57-21-00-220-C04-L00	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS: - LOWER VENT HOLE (SSI 57-21-33) (L650 ONLY)								Service ATA:57
	MOS/MSC	27-Aug-07	N/A						
	HRS	0							
	AFL	0							
PROC. REF: CPM 57-21-00PROC. REF: CPM 57-21-00									

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-21-00-250-802-L00 S	SPECIAL DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS BY USING EDDY CURRENT LOW FREQUENCY INSPECTION METHOD:- LOWER SKIN PANEL CHORD- WISE JOINT (SSI 57-21-29). (L600 ONLY)								Service ATA:57
	MOS	11-Aug-15	192 (+15d/-15d)					LOW UTILIZATION	
	HRS	7460.3	8000 (+20/-20)						
	AFL	3992	4000 (+20/-20)						
									PKG:5032,6032
PROC. REF: NDT 57-21-00PROC. REF: NDT 57-21-00									
57-21-00-250-803-L00	SPECIAL DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS BY USING EDDY CURRENT LOW FREQUENCY INSPECTION METHOD:- LOWER SKIN PANEL CHORDWISE JOINT (SSI 57-21-29) (L650 ONLY)								Service ATA:57
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL	
	HRS	0							
	AFL	0							
PROC. REF: NDT 57-21-00PROC. REF: NDT 57-21-00									
57-21-00-250-804-L00	SPECIAL DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS BY USING EDDY CURRENT INSPECTION METHOD:- LOWER SKIN/SPAR ATTACHMENTS (SSI 57-21-36) (L650 ONLY)								Service ATA:57
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL	
	HRS	0							
	AFL	0							
PROC. REF: NDT 57-21-00PROC. REF: NDT 57-21-00									
57-21-00-250-805-L00	SPECIAL DETAIL INSPECTION (EXTERNAL) OF WING COMPONENTS BY USING EDDY CURRENT LOW FREQUENCY INSPECTION METHOD: - LOWER SKIN PANEL CHORDWISE JOINT (SSI 57-21-29) (L650 ONLY)								Service ATA:57
	MOS/MSC	27-Aug-07	N/A						
	HRS	0							
	AFL	0							
PROC. REF: NDT 57-21-00PROC. REF: NDT 57-21-00									
57-22-00-210-801-L00 S	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS:- SPAR 1/ WING STUB ATTACH- MENT (SSI 57-22-44)								Service ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 57-22-00PROC. REF: NDT 57-22-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-22-00-210-802-L00 S	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS:- SPAR 1 CAP (SSI 57-22-41)							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 57-22-00PROC. REF: NDT 57-22-00									
57-22-00-210-803-L00 S	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS:- SPAR 1/ LEADING EDGE ATTACH- MENTS (SSI 57-22-43) (L600 ONLY)							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6016
PROC. REF: NDT 57-22-00PROC. REF: NDT 57-22-00									
57-22-00-210-804-L00 S	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS:- SPAR 1/ LEADING EDGE ATTACHMENTS (SSI 57-22-43)							Service	ATA:57
	MOS	02-Jul-15	192 (+15d/-15d)					LOW UTILIZATION	
	HRS	7460.3	8000 (+20/-20)						
	AFL	3992	4000 (+20/-20)						
									PKG:5032,6032
PROC. REF: NDT 57-22-00PROC. REF: NDT 57-22-00									
57-22-00-210-805-L00 S	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS:- SPAR 1 CAP (SSI 57-22-41)							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 57-22-00PROC. REF: NDT 57-22-00									
57-22-00-210-806-L00 S	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS:- SPAR 1/ LEADING EDGE ATTACHMENTS (SSI 57-22-43)							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 57-22-00PROC. REF: NDT 57-22-00									

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-22-00-210-807-L00	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS:- SPAR 1/WING STUB ATTACHMENT (SSI 57-22-44) (L650 ONLY)							Service	ATA:57
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL	
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: NDT 57-22-00PROC. REF: NDT 57-22-00									
57-22-00-210-C01-L00 S	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS:- SPAR 1/ LEADING EDGE ATTACHMENTS (SSI 57-22-43)							Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: CPM 57-22-00PROC. REF: CPM 57-22-00									
57-22-00-220-801-L00 S	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS:- SPAR 1/ WEB AND STIFFENERS (SSI 57-22-40)							Service	ATA:57
	MOS	02-Jul-15	192 (+15d/-15d)					LOW UTILIZATION	
	HRS	7460.3	8000 (+20/-20)						
	AFL	3992	4000 (+20/-20)						
									PKG:5032,6032
PROC. REF: NDT 57-22-00PROC. REF: NDT 57-22-00									
57-22-00-220-802-L00 S	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS:- SPAR 1/ WEB AND STIFFENERS (SSI 57-22-40)- SPAR 1, WEB CUTOUTS (SSI 57-22-42)							Service	ATA:57
	MOS	02-Jul-15	192 (+15d/-15d)					LOW UTILIZATION	
	HRS	7460.3	8000 (+20/-20)						
	AFL	3992	4000 (+20/-20)						
									PKG:5032,6032
PROC. REF: NDT 57-22-00PROC. REF: NDT 57-22-00									
57-22-00-220-803-L00 S	DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS:- SPAR 1, WEB CUTOUTS (SSI 57-22-42)							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 57-22-00PROC. REF: NDT 57-22-00									

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-22-00-220-804-L00 S	DETAILED INSPECTION (INTERNAL) OF WINGLET COMPONENTS:- FRONT SPAR - WINGLET (SSI 57-22-45)							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 57-22-00PROC. REF: NDT 57-22-00									
57-22-00-220-805-L00 S	DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS:- SPAR 1, WEB AND STIFFENERS (SSI 57-22-40)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 57-22-00PROC. REF: NDT 57-22-00									
57-22-00-220-806-L00 S	DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS:- SPAR 1, WEB AND STIFFEN- ERS (SSI 57-22-40)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 57-22-00PROC. REF: NDT 57-22-00									
57-22-00-220-807-L00	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS:- SPAR 1/ LEADING EDGE ATTACHMENTS (SSI 57-22-43) (L650 ONLY)							Service	ATA:57
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL	
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: NDT 57-22-00PROC. REF: NDT 57-22-00									
57-23-00-210-801-L00 S	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS:- SPAR 2 CAP (SSI 57-23-46) (L600 ONLY)							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 57-23-00PROC. REF: NDT 57-23-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-23-00-210-802-L00 S	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS:- SPAR 2/ WING STUB ATTACH- MENTS (SSI 57-23-48) (L600 ONLY)							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6016
PROC. REF: NDT 57-23-00PROC. REF: NDT 57-23-00									
57-23-00-210-803-L00 S	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS:- SPAR 2/ WING STUB ATTACH- MENTS (SSI 57-23-48) (L600 ONLY)							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6016
PROC. REF: NDT 57-23-00PROC. REF: NDT 57-23-00									
57-23-00-210-804-L00	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS:- SPAR 2 CAP (SSI 57-23-46) (L650 ONLY)							Service	ATA:57
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL	
	HRS	0							
	AFL	0							
									PKG:6032
PROC. REF: NDT 57-23-00PROC. REF: NDT 57-23-00									
57-23-00-210-805-L00	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS:- SPAR 2/ WING STUB ATTACHMENTS (SSI 57-23-48) (L650 ONLY)							Service	ATA:57
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL	
	HRS	0							
	AFL	0							
									PKG:6032
PROC. REF: NDT 57-23-00PROC. REF: NDT 57-23-00									
57-23-00-210-806-L00	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS:- SPAR 2/ WING STUB ATTACHMENTS (SSI 57-23-48) (L650 ONLY)							Service	ATA:57
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL	
	HRS	0							
	AFL	0							
									PKG:6032
PROC. REF: NDT 57-23-00PROC. REF: NDT 57-23-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-23-00-220-801-L00 S	DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS:- SPAR 2, WEB AND STIFFENERS (SSI 57-23-45)							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 57-23-00PROC. REF: NDT 57-23-00									
57-23-00-220-803-L00	DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS:- REAR SPAR - WINGLET (SSI 57-23-49) (L650 ONLY)							Service	ATA:57
	MOS/MSC	09-Jul-15	N/A						
	HRS	7460.3							
	AFL	3992							
									PKG:6032
PROC. REF: NDT 57-23-00PROC. REF: NDT 57-23-00									
57-23-00-220-804-L00 S	DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS:- SPAR 2, WEB CUTOUTS (SSI 57-23-47)							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 57-23-00PROC. REF: NDT 57-23-00									
57-23-00-220-805-L00 S	DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS:- SPAR 2, WEB CUTOUTS (SSI 57-23-47)							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 57-23-00PROC. REF: NDT 57-23-00									
57-23-00-220-C01-L00 S	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS:- SPAR 2, WEB AND STIFFEN- ERS (SSI 57-23-45)- SPAR 2, WEB CUTOUTS (SSI 57-23-47)							Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: CPM 57-23-00PROC. REF: CPM 57-23-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-23-00-290-801-L00 S	SPECIAL DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS USING BOROSCOPE:- REAR SPAR - WINGLET (SSI 57-23-49) (L600 ONLY)							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 57-23-00PROC. REF: NDT 57-23-00									
57-24-00-210-801-L00 S	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS:- SPAR 3, CAP (SSI 57-24-50)							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 57-24-00PROC. REF: NDT 57-24-00									
57-24-00-210-802-L00 S	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS:- SPAR 3, WING STUB ATTACH- MENT (SSI 57-24-52) (L600 ONLY)							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6016
PROC. REF: NDT 57-24-00PROC. REF: NDT 57-24-00									
57-24-00-210-C01-L00 S	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS:- SPAR 3, WEB AND STIFFEN- ERS (SSI 57-24-49)- SPAR 3, WEB CUTOUTS (SSI 57-24-51)							Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: CPM 57-24-00PROC. REF: CPM 57-24-00									
57-24-00-210-C02-L00 S	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS:- SPAR 3, WEB AND STIFFEN- ERS (SSI 57-24-49)- SPAR 3, WEB CUTOUTS (SSI 57-24-51)							Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: CPM 57-24-00PROC. REF: CPM 57-24-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-24-00-220-801-L00	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS:- SPAR 3, WING STUB ATTACHMENT (SSI 57-24-52) (L650 ONLY)							Service	ATA:57
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL	
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: NDT 57-24-00PROC. REF: NDT 57-24-00									
57-25-00-210-C01-L00 S	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS:- RIBS, MAIN BOX (SSI 57-25-53)- LOWER SKIN/ RIB ATTACHMENT (SSI 57-25-54)- UPPER SKIN/ RIB ATTACHMENT (SSI 57-25-55)							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: CPM 57-25-00PROC. REF: CPM 57-25-00									
57-25-00-210-C02-L00 S	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS:- LOWER SKIN/ RIB ATTACHMENT (SSI 57-25-54)- UPPER SKIN/ RIB ATTACHMENT (SSI 57-25-55)							Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: CPM 57-25-00PROC. REF: CPM 57-25-00									
57-25-00-290-801-L00 S	SPECIAL DETAILED INSPECTION (INTERNAL) OF WINGLET COM- PONENTS USING BOROSCOPE:- RIB 25 - WINGLET (SSI 57-25-56)							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 57-25-00PROC. REF: NDT 57-25-00									
57-26-00-220-801-L00 S	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS:- FWD & AFT SIDE BRACE FITTINGS, MLG (SSI 57-26-56)							Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: NDT 57-26-00PROC. REF: NDT 57-26-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-26-00-220-C01-L00 S	DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS:- FWD & AFT SIDE BRACE FIT- TINGS MLG (SSI 57-26-56)- BEARING CAP (SSI 57-26-94)- TRUNNION FITTING (SSI 57-26-95)								Service ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: CPM 57-26-00PROC. REF: CPM 57-26-00									
57-26-00-250-802-L00 S	SPECIAL DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS BY THE EDDY CURRENT INSPECTION METHOD:- BEARING CAP - MLG (SSI 57-26-94) (L600 ONLY)								Service ATA:57
	MOS	27-Aug-07	288 (+15d/-15d)					LOW UTILIZATION	
	HRS	0	12000 (+20/-20)						
	AFL	0	6000 (+20/-20)						
									PKG:5140
PROC. REF: NDT 57-26-00PROC. REF: NDT 57-26-00									
57-26-00-250-803-L00 S	SPECIAL DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS BY THE EDDY CURRENT INSPECTION METHOD:- FWD & AFT SIDE BRACE FIT- TINGS, MLG (SSI 57-26-56)								Service ATA:57
	MOS	27-Aug-07	288 (+15d/-15d)					LOW UTILIZATION	
	HRS	0	12000 (+20/-20)						
	AFL	0	6000 (+20/-20)						
									PKG:5140
PROC. REF: NDT 57-26-00PROC. REF: NDT 57-26-00									
57-26-00-250-804-L00 S	SPECIAL DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS BY THE EDDY CURRENT INSPECTION METHOD:- TRUNNION FITTINGS (SSI 57-26-95)								Service ATA:57
	MOS	27-Aug-07	288 (+15d/-15d)					LOW UTILIZATION	
	HRS	0	12000 (+20/-20)						
	AFL	0	6000 (+20/-20)						
									PKG:5140
PROC. REF: NDT 57-26-00PROC. REF: NDT 57-26-00									
57-26-00-250-805-L00	SPECIAL DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS BY THE EDDY CURRENT INSPECTION METHOD:- BEARING CAP - MLG (SSI 57-26-94) (L650 ONLY)								Service ATA:57
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL	
	HRS	0							
	AFL	0							
									PKG:6032
PROC. REF: NDT 57-26-00PROC. REF: NDT 57-26-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-28-00-210-801-L00 S	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS:- SPAR ATTACHMENT, TORQUE BOX (SSI 57-28-57)							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 57-28-00PROC. REF: NDT 57-28-00									
57-28-00-210-804-L00 S	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS:- SPAR 3 ATTACHMENT, TORQUE BOX (SSI 57-28-63)- OUTBOARD FLAP CENTER TRACK ATTACHMENT(SSI 57-28-68) (L600 ONLY)							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 57-28-00PROC. REF: NDT 57-28-00									
57-28-00-210-806-L00 S	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS:- SPAR 3 ATTACHMENT, TORQUE BOX 2 (SSI 57-28-63)							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 57-28-00PROC. REF: NDT 57-28-00									
57-28-00-210-807-L00 S	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS:- ATTACHMENT LUGS AILERON(SSI 57-28-66)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI (L600 ONLY)							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016
PROC. REF: NDT 57-28-00PROC. REF: NDT 57-28-00									
57-28-00-210-808-L00 S	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS:- UPPER SKIN, TORQUE BOX (SSI 57-28-61)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 57-28-00PROC. REF: NDT 57-28-00									

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-28-00-210-809-L00	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS:- SPAR ATTACHMENT, TORQUE BOX (SSI 57-28-57) (L650 ONLY)								Service ATA:57
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL	
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: NDT 57-28-00PROC. REF: NDT 57-28-00									
57-28-00-210-810-L00	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS: - SPAR 3 ATTACHMENT, TORQUE BOX (SSI 57-28-63) (L650 ONLY)								Service ATA:57
	MOS/MSC	27-Aug-07	N/A						
	HRS	0							
	AFL	0							
PROC. REF: NDT 57-28-00PROC. REF: NDT 57-28-00									
57-28-00-210-C01-L00 S	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS:- LOWER SKIN, TORQUE BOX (SSI 57-28-58) (L600 ONLY)								Service ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: CPM 57-28-00PROC. REF: CPM 57-28-00									
57-28-00-210-C02-L00 S	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS:- SPAR ATTACHMENT, TORQUE BOX (SSI 57-28-57) (L600 ONLY)								Service ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: CPM 57-28-00PROC. REF: CPM 57-28-00									
57-28-00-210-C03-L00 S	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS:- UPPER SKIN, TORQUE BOX (SSI 57-28-61)								Service ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5009
PROC. REF: CPM 57-28-00PROC. REF: CPM 57-28-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-28-00-210-C04-L00 S	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS:- FLAP ACTUATOR ATTACHMENT FITTINGS (SSI 57-28-67)							Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5009
PROC. REF: CPM 57-28-00PROC. REF: CPM 57-28-00									
57-28-00-210-C05-L00 S	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS:- SPAR ATTACHMENT, TORQUE BOX (SSI 57-28-57)							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: CPM 57-28-00PROC. REF: CPM 57-28-00									
57-28-00-210-C07-L00 S	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS:- LOWER SKIN, TORQUE BOX (SSI 57-28-58)							Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: CPM 57-28-00PROC. REF: CPM 57-28-00									
57-28-00-210-C09-L00 S	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS:- UPPER SKIN, TORQUE BOX (SSI 57-28-61)							Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5009
PROC. REF: CPM 57-28-00PROC. REF: CPM 57-28-00									
57-28-00-210-C10-L00 S	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS:- SPAR ATTACHMENT, TORQUE BOX (SSI 57-28-57)							Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5009
PROC. REF: CPM 57-28-00PROC. REF: CPM 57-28-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-28-00-220-801-L00 S	DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS:- SPAR ATTACHMENT, TORQUE BOX (SSI 57-28-57)							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 57-28-00PROC. REF: NDT 57-28-00									
57-28-00-220-804-L00 S	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS:- CENTER TRACK AND RIB 15 TRAILING EDGE(SSI 57-28-69)							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6016
PROC. REF: NDT 57-28-00PROC. REF: NDT 57-28-00									
57-28-00-220-805-L00 S	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS:- TRACKS/ RIBS ATTACHMENT, TORQUE BOX(SSI 57-28-62)							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 57-28-00PROC. REF: NDT 57-28-00									
57-28-00-220-806-L00	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS:- SPAR 3 ATTACHMENT, TORQUE BOX (SSI 57-28-63)- OUTBOARD FLAP CENTER TRACK ATTACHMENT (SSI 57-28-68) (L650 ONLY)							Service	ATA:57
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL	
	HRS	0							
	AFL	0							
									PKG:6032
PROC. REF: NDT 57-28-00PROC. REF: NDT 57-28-00									
57-28-00-220-807-L00	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS:- ATTACHMENT LUGS AILERON (SSI 57-28-66)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI. (L650 ONLY)							Service	ATA:57
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL	
	HRS	0							
	AFL	0							
									PKG:6032
PROC. REF: NDT 57-28-00PROC. REF: NDT 57-28-00									

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-28-00-220-808-L00	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS:- RIBS, TORQUE BOX (SSI 57-28-60) (L650 ONLY)								Service ATA:57
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL	
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: NDT 57-28-00PROC. REF: NDT 57-28-00									
57-28-00-220-809-L00	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS:- RIBS, TORQUE BOX 3 (SSI 57-28-64)- TRACKS/ RIB ATTACHMENT, TORQUE BOX 3 (SSI 57-28-65) (L650 ONLY)								Service ATA:57
	MOS/MSC	25-Sep-07	N/A						
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: NDT 57-28-00PROC. REF: NDT 57-28-00									
57-28-00-220-C01-L00 S	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS:- SPAR ATTACHMENT, TORQUE BOX (SSI 57-28-57)								Service ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: CPM 57-28-00PROC. REF: CPM 57-28-00									
57-28-00-220-C02-L00 S	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS:- FLAP TRACK, TORQUE BOX (SSI 57-28-59)								Service ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5009
PROC. REF: CPM 57-28-00PROC. REF: CPM 57-28-00									
57-28-00-220-C03-L00 S	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS:- RIBS, TORQUE BOX 3 (SSI 57-28-64)- TRACKS/ RIB ATTACHMENT, TORQUE BOX 3(SSI 57-28-65) (L600 ONLY)								Service ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: CPM 57-28-00PROC. REF: CPM 57-28-00									

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-28-00-220-C04-L00 S	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS:- ATTACHMENT ACTUATOR LUGS, INBOARD/ OUTBOARD SPOILERS (SSI 57-28-70)							Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: CPM 57-28-00PROC. REF: CPM 57-28-00									
57-28-00-220-C05-L00 S	DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS:- TRACKS/ RIBS ATTACHMENT, TORQUE BOX(SSI 57-28-62)							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: CPM 57-28-00PROC. REF: CPM 57-28-00									
57-28-00-220-C06-L00 S	DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS:- RIBS, TORQUE BOX 3 (SSI 57-28-64)- TRACKS/ RIB ATTACHMENT, TORQUE BOX 3(SSI 57-28-65)							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: CPM 57-28-00PROC. REF: CPM 57-28-00									
57-28-00-220-C07-L00 S	DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS:- RIBS, TORQUE BOX 3 (SSI 57-28-60)							Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5009
PROC. REF: CPM 57-28-00PROC. REF: CPM 57-28-00									
57-28-00-220-C08-L00 S	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS:- RIBS, TORQUE BOX (SSI 57-28-60)							Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5009
PROC. REF: CPM 57-28-00PROC. REF: CPM 57-28-00									

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-28-00-220-C09-L00 S	DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS:- RIBS, TORQUE BOX (SSI 57-28-60)							Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: CPM 57-28-00PROC. REF: CPM 57-28-00									
57-28-00-220-C10-L00 S	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS:- RIBS, TORQUE BOX (SSI 57-28-60) (L600 ONLY)							Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: CPM 57-28-00PROC. REF: CPM 57-28-00									
57-28-00-220-C11-L00	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS:- LOWER SKIN, TORQUE BOX (SSI 57-28-58) (L650 ONLY)							Service	ATA:57
	MOS/MSC	25-Sep-07	N/A						
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: CPM 57-28-00PROC. REF: CPM 57-28-00									
57-28-00-250-801-L00 S	SPECIAL DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS BY THE EDDY CURRENT INSPECTION METHOD:- SPAR ATTACHMENT, TORQUE BOX (SSI 57-28-57)							Service	ATA:57
	MOS	27-Aug-07	288 (+15d/-15d)					LOW UTILIZATION	
	HRS	0	12000 (+20/-20)						
	AFL	0	6000 (+20/-20)						
									PKG:5140
PROC. REF: NDT 57-28-00PROC. REF: NDT 57-28-00									
57-28-00-250-802-L00 S	SPECIAL DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS BY THE EDDY CURRENT INSPECTION METHOD:- RIBS, TORQUE BOX (SSI 57-28-60)							Service	ATA:57
	MOS	27-Aug-07	288 (+15d/-15d)					LOW UTILIZATION	
	HRS	0	12000 (+20/-20)						
	AFL	0	6000 (+20/-20)						
									PKG:5140
PROC. REF: NDT 57-28-00PROC. REF: NDT 57-28-00									

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-28-00-250-803-L00 S	SPECIAL DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS BY THE EDDY CURRENT INSPECTION METHOD:- ATTACHMENT, TORQUE BOX (SSI 57-28-57)						SPAR		Service ATA:57
	MOS	27-Aug-07	288 (+15d/-15d)					LOW UTILIZATION	
	HRS	0	12000 (+20/-20)						
	AFL	0	6000 (+20/-20)						
									PKG:5140
PROC. REF: NDT 57-28-00PROC. REF: NDT 57-28-00									
57-28-00-250-804-L00 S	SPECIAL DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS BY THE EDDY CURRENT INSPECTION METHOD:- BOX (SSI 57-28-60)						RIBS, TORQUE		Service ATA:57
	MOS	27-Aug-07	288 (+15d/-15d)					LOW UTILIZATION	
	HRS	0	12000 (+20/-20)						
	AFL	0	6000 (+20/-20)						
									PKG:5140
PROC. REF: NDT 57-28-00PROC. REF: NDT 57-28-00									
57-28-00-250-805-L00 S	SPECIAL DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS BY THE EDDY CURRENT INSPECTION METHOD:- TORQUE BOX (SSI 57-28-59)						FLAP TRACK,		Service ATA:57
	MOS	27-Aug-07	288 (+15d/-15d)					LOW UTILIZATION	
	HRS	0	12000 (+20/-20)						
	AFL	0	6000 (+20/-20)						
									PKG:5140
PROC. REF: NDT 57-28-00PROC. REF: NDT 57-28-00									
57-29-00-220-801-L00 S	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS:- SKIN/ RIB ATTACHMENT, MLGB (SSI 57-29-72)								Service ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6016
PROC. REF: NDT 57-29-00PROC. REF: NDT 57-29-00									
57-29-00-220-802-L00 S	DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS:- RIBS, MAIN LANDING GEAR BAY (SSI 57-29-71)- SKIN/ RIB ATTACHMENT, MLGB (SSI 57-29-72)								Service ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6016
PROC. REF: NDT 57-29-00PROC. REF: NDT 57-29-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-41-00-210-801-L00	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING LEAD- ING EDGE COMPONENTS:- WING LEADING EDGE 1 SKIN (SSI 57-41-94) (L650 ONLY)							Service	ATA:57
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL	
	HRS	0							
	AFL	0							
									PKG:6032
PROC. REF: NDT 57-41-00PROC. REF: NDT 57-41-00									
57-41-00-210-C01-L00 S	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING LEADING EDGE COMPONENTS:- WING LEADING EDGE 1 SKIN (SSI 57-41-94) (L600 ONLY)							Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: CPM 57-41-00PROC. REF: CPM 57-41-00									
57-41-00-220-801-L00 S	DETAILED INSPECTION (INTERNAL) OF WING LEADING EDGE COMPONENTS:- MACHINED RIB FLANGE (SSI 57-41-98)							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 57-41-00PROC. REF: NDT 57-41-00									
57-42-00-210-801-L00	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING LEAD- ING EDGE COMPONENTS:- WING LEADING EDGE 2 SKIN (SSI 57-42-95) (L650 ONLY)							Service	ATA:57
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL	
	HRS	0							
	AFL	0							
									PKG:6032
PROC. REF: NDT 57-42-00PROC. REF: NDT 57-42-00									
57-42-00-210-C01-L00 S	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING LEADING EDGE COMPONENTS:- WING LEADING EDGE 2 SKIN (SSI 57-42-95) (L600 ONLY)							Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: CPM 57-42-00PROC. REF: CPM 57-42-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-42-00-220-801-L00 S	DETAILED INSPECTION (INTERNAL) OF WING LEADING EDGE COMPONENTS:- MACHINED RIB FLANGE (SSI 57-42-98)							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 57-42-00PROC. REF: NDT 57-42-00									
57-42-00-220-802-L00 S	DETAILED INSPECTION (EXTERNAL) OF WING LEADING EDGE COMPONENTS:- WING LEADING EDGE 2 BOTTOM SKIN AT CONNECTIONSTO LOWER REAR GIRDER & WING LOWER SPAR CAP (SSI 57-42-97)							Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: NDT 57-42-00PROC. REF: NDT 57-42-00									
57-43-00-210-801-L00	GENERAL VISUAL INSPECTION (EXTERNAL) OF LEADING EDGE COMPONENTS:- WING LEADING EDGE 3 SKIN (SSI 57-43-96) (L650 ONLY)							Service	ATA:57
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL	
	HRS	0							
	AFL	0							
									PKG:6032
PROC. REF: NDT 57-43-00PROC. REF: NDT 57-43-00									
57-43-00-210-C01-L00 S	GENERAL VISUAL INSPECTION (EXTERNAL) OF LEADING EDGE COMPONENTS:- WING LEADING EDGE 3 SKIN (SSI 57-43-96) (L600 ONLY)							Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: CPM 57-43-00PROC. REF: CPM 57-43-00									
57-43-00-220-801-L00 S	DETAILED INSPECTION (INTERNAL) OF WING LEADING EDGE COMPONENTS:- MACHINED RIB FLANGE (SSI 57-43-98)							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 57-43-00PROC. REF: NDT 57-43-00									

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-50-00-220-803-L00 S	DETAILED INSPECTION (EXTERNAL) OF FLAP COMPONENTS:- ROLLER ATTACHMENT, FLAPS (SSI 57-50-76)							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 57-50-00PROC. REF: NDT 57-50-00									
57-50-00-220-804-L00 S	DETAILED INSPECTION (EXTERNAL) OF FLAP COMPONENTS:- TRACKS, FLAPS (SSI 57-50-80)							Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: NDT 57-50-00PROC. REF: NDT 57-50-00									
57-50-00-220-805-L00 S	DETAILED INSPECTION (EXTERNAL) OF FLAPCOMPONENTS: FLAP ROOT-SPAR FITTING (SSI 57-50-74). INBOARD FLAP FITTING TIP SPAR (SSI 57-52-73). OUTBOARD FLAP TIP SPAR FITTING (SSI 57-53-83).							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 57-50-00PROC. REF: NDT 57-50-00									
57-50-00-220-806-L00 S	DETAILED INSPECTION (EXTERNAL) OF FLAPCOMPONENTS: INBOARD FLAP RIBS/SKIN ATTACHMENT (SSI57-52-79). INBOARD FLAP VANE INBOARD/OUTBOARD FITTINGS(SSI 57-52-81). OUTBOARD FLAP RIBS/SKIN ATTACHMENT (SSI57-53-86). OUTBOARD FLAP VANE INBOARD/OUTBOARDFITTINGS (SSI 57-53-88).							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6016
PROC. REF: NDT 57-50-00PROC. REF: NDT 57-50-00									
57-50-00-220-C01-L00 S	DETAILED INSPECTION (EXTERNAL) OF FLAP COMPONENTS:- TRACKS/ RIB ATTACHMENT, FLAPS (SSI 57-50-77)							Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5009
PROC. REF: CPM 57-50-00PROC. REF: CPM 57-50-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-50-00-250-801-L00 S	SPECIAL DETAILED INSPECTION (EXTERNAL) OF FLAP COMPONENTS BY THE EDDY CURRENT INSPECTION METHOD:- ROLLER ATTACHMENT, FLAPS (SSI 57-50-76)							Service	ATA:57
	MOS	27-Aug-07	288 (+15d/-15d)					LOW UTILIZATION	
	HRS	0	12000 (+20/-20)						
	AFL	0	6000 (+20/-20)						
									PKG:5140
PROC. REF: NDT 57-50-00PROC. REF: NDT 57-50-00									
57-50-00-250-802-L00 S	SPECIAL DETAILED INSPECTION (EXTERNAL) OF FLAP COMPONENTS BY THE EDDY CURRENT INSPECTION METHOD:- TRACKS, FLAPS (SSI 57-50-80) (L600 ONLY)							Service	ATA:57
	MOS	27-Aug-07	288 (+15d/-15d)					LOW UTILIZATION	
	HRS	0	12000 (+20/-20)						
	AFL	0	6000 (+20/-20)						
									PKG:5140
PROC. REF: NDT 57-50-00PROC. REF: NDT 57-50-00									
57-50-00-250-803-L00	SPECIAL DETAILED INSPECTION (EXTERNAL) OF FLAP COMPONENTS BY THE EDDY CURRENT INSPECTION METHOD:- TRACKS, FLAPS (SSI 57-50-80) (L650 ONLY)							Service	ATA:57
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL	
	HRS	0							
	AFL	0							
PROC. REF: NDT 57-50-00PROC. REF: NDT 57-50-00									
57-50-00-290-801-L00 S	SPECIAL DETAILED INSPECTION (INTERNAL) OF FLAPCOMPONENTS BY BORESCOPE INSPECTION METHOD: STRUCTURAL SIGNIFICANT ITEM: SSI 57-50-74 - FLAPROOTSPAR FITTING. STRUCTURAL SIGNIFICANT ITEM: SSI 57-52-73 -INBOARD FLAP TIP SPAR FITTING. STRUCTURAL SIGNIFICANT ITEM: SSI 57-53-83 -OUTBOARD FLAP TIP SPAR FITTING.							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 57-50-00PROC. REF: NDT 57-50-00									
57-52-00-210-803-L00 S	GENERAL VISUAL INSPECTION (EXTERNAL) OF FLAP COMPONENTS:- VANE CENTER FITTING, INBOARD FLAP (SSI 57-52-78) (L600 ONLY)							Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008
PROC. REF: NDT 57-52-00PROC. REF: NDT 57-52-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-52-00-210-804-L00 S	GENERAL VISUAL INSPECTION (EXTERNAL) OF FLAP COMPONENTS:- PIN AND ACTUATOR LUGS, INBOARD FLAP (SSI 57-52-75) (L600 ONLY)							Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5009,6008
PROC. REF: NDT 57-52-00PROC. REF: NDT 57-52-00									
57-52-00-210-805-L00	GENERAL VISUAL INSPECTION (EXTERNAL) OF FLAP COMPONENTS:- PIN AND ACTUATOR LUGS, INBOARD FLAP (SSI 57-52-75) (L650 ONLY)							Service	ATA:57
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL	
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: NDT 57-52-00PROC. REF: NDT 57-52-00									
57-52-00-220-803-L00	DETAILED INSPECTION (EXTERNAL) OF FLAP COMPONENTS:- VANE CENTER FITTING, INBOARD FLAP (SSI 57-52-78) (L650 ONLY)							Service	ATA:57
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL	
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: NDT 57-52-00PROC. REF: NDT 57-52-00									
57-53-00-210-801-L00 S	GENERAL VISUAL INSPECTION (EXTERNAL) OF FLAP COMPONENTS:- VANE CENTER FITTING, OUTBOARD FLAP (SSI 57-53-85) (L600 ONLY)							Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008
PROC. REF: NDT 57-53-00PROC. REF: NDT 57-53-00									
57-53-00-210-803-L00 S	GENERAL VISUAL INSPECTION (INTERNAL) OF FLAP COMPONENTS:- CENTER RIBS ATTACHMENT, OUTBOARD FLAP (SSI 57-53-87)							Service	ATA:57
	MOS	27-Aug-07	288 (+15d/-15d)					LOW UTILIZATION	
	HRS	0	12000 (+20/-20)						
	AFL	0	6000 (+20/-20)						
									PKG:5140
PROC. REF: NDT 57-53-00PROC. REF: NDT 57-53-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-53-00-210-806-L00 S	GENERAL VISUAL INSPECTION(EXTERNAL) OF FLAP COMPONENTS:- PIN AND ACTUATOR LUGS, OUTBOARD FLAP(SSI 57-53-84) (L600 ONLY)							Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5009,6008
PROC. REF: NDT 57-53-00PROC. REF: NDT 57-53-00									
57-53-00-210-807-L00	GENERAL VISUAL INSPECTION(EXTERNAL) OF FLAP COMPONENTS:- PIN AND ACTUATOR LUGS, OUT- BOARD FLAP (SSI 57-53-84) (L650 ONLY)							Service	ATA:57
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL	
	HRS	0							
	AFL	0							
									PKG:6032
PROC. REF: NDT 57-53-00PROC. REF: NDT 57-53-00									
57-53-00-210-C01-L00 S	GENERAL VISUAL INSPECTION (EXTERNAL) OF FLAP COMPONENTS:- CENTER RIBS ATTACHMENT, OUTBOARD FLAP(SSI 57-53-87) (L600 ONLY)							Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5009
PROC. REF: CPM 57-53-00PROC. REF: CPM 57-53-00									
57-53-00-220-803-L00	DETAILED INSPECTION (EXTERNAL) OF FLAP COMPONENTS:- VANE CENTER FITTING, OUTBOARD FLAP (SSI 57-53-85) (L650 ONLY)							Service	ATA:57
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL	
	HRS	0							
	AFL	0							
									PKG:6032
PROC. REF: NDT 57-53-00PROC. REF: NDT 57-53-00									
57-53-00-220-C01-L00	DETAILED INSPECTION (EXTERNAL) OF FLAP COMPONENTS:- CENTER RIBS ATTACHMENT, OUTBOARD FLAP (SSI 57-53-87) (L650 ONLY)							Service	ATA:57
	MOS/MSC	25-Sep-07	N/A						
	HRS	0							
	AFL	0							
PROC. REF: CPM 57-53-00PROC. REF: CPM 57-53-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-61-00-210-801-L00 S	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS:- HINGES ATTACHMENT, AILERON (SSI 57-61-89)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI (L600 ONLY)							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: NDT 57-61-00PROC. REF: NDT 57-61-00									
57-61-00-210-C01-L00 S	GENERAL VISUAL INSPECTION (EXTERNAL) OF AILERON COMPONENTS:- SPAR CAP, AILERON (SSI 57-61-91)							Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5009
PROC. REF: CPM 57-61-00PROC. REF: CPM 57-61-00									
57-61-00-220-801-L00 S	DETAILED INSPECTION (EXTERNAL) OF AILERON COMPONENTS:- ACTUATOR ATTACHMENT, AILERON (SSI 57-61-90)							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6016
PROC. REF: NDT 57-61-00PROC. REF: NDT 57-61-00									
57-61-00-220-802-L00 S	DETAILED INSPECTION (INTERNAL) OF AILERON COMPONENTS:- ACTUATOR ATTACHMENT, AILERON (SSI 57-61-90)							Service	ATA:57
	MOS	03-Jul-15	192 (+15d/-15d)					LOW UTILIZATION	
	HRS	7460.3	8000 (+20/-20)						
	AFL	3992	4000 (+20/-20)						
									PKG:5032,6032
PROC. REF: NDT 57-61-00PROC. REF: NDT 57-61-00									
57-61-00-220-804-L00 S	DETAILED INSPECTION (INTERNAL) OF AILERON COMPONENTS:- AILERON ACTUATOR FITTINGS (SSI 57-61-12)							Service	ATA:57
	MOS/MSC	03-Jul-15	N/A						
	HRS	7460.3							
	AFL	3992							
									PKG:5032,6032
PROC. REF: NDT 57-61-00PROC. REF: NDT 57-61-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-61-00-220-805-L00	DETAILED INSPECTION (EXTER-NAL) OF WING COMPONENTS:- HINGES ATTACHMENT, AILERON (SSI 57-61-89)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI. (L650 ONLY)								Service ATA:57
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL	
	HRS	0							
	AFL	0							
									PKG:6032
PROC. REF: NDT 57-61-00PROC. REF: NDT 57-61-00									
57-70-00-210-C01-L00 S	GENERAL VISUAL INSPECTION (EXTERNAL) OF SPOILER COMPONENTS:- HINGES ATTACHMENT, SPOILERS (SSI 57-70-92)- ACTUATOR ATTACHMENT, SPOILERS (SSI 57-70-93)								Service ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: CPM 57-70-00PROC. REF: CPM 57-70-00									
57-Z511-213-001-A00 S	GENERAL VISUAL INSPECTION(EXTERNAL) (ZONES 511, 611, 512, 612, 513 AND 613)								Service ATA:57
	MOS	17-Oct-25	24 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	1000 (+20/-20)						
	AFL	5820							
									PKG:5004
PROC. REF: AMM 05-20-76PROC. REF: AMM 05-20-76									
57-Z511-214-001-A00 S	GENERAL VISUAL INSPECTION(INTERNAL) (L600 ONLY) (ZONES 511, 611, 512, 612, 513 AND 613)								Service ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 05-20-76PROC. REF: AMM 05-20-76									
57-Z511-214-001-A01	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 511, 611, 512, 612, 513 AND 613)NOTE:EWIS (L650 ONLY)								Service ATA:57
	MOS/MSC	25-Sep-07	N/A					ZONAL	
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: AMM 05-20-76PROC. REF: AMM 05-20-76									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-Z531-213-001-A00 S	GENERAL VISUAL INSPECTION(EXTERNAL) (ZONES 531, 631)							Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 05-20-82PROC. REF: AMM 05-20-82									
57-Z531-214-001-A00 S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 531, 631) (L600 ONLY)							Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 05-20-82PROC. REF: AMM 05-20-82									
57-Z531-214-001-A01	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 531, 631)NOTE:EWIS (L650 ONLY)							Service	ATA:57
	MOS/MSC	25-Sep-07	N/A					ZONAL	
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: AMM 05-20-82PROC. REF: AMM 05-20-82									
57-Z532-213-001-A00 S	GENERAL VISUAL INSPECTION(EXTERNAL) (ZONES 532 AND 632)							Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 05-20-84PROC. REF: AMM 05-20-84									
57-Z532-214-001-A00 S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 532 AND 632) (L600 ONLY)							Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 05-20-84PROC. REF: AMM 05-20-84									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-Z532-214-001-A01	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 532 AND 632)NOTE:EWIS (L650 ONLY)							Service	ATA:57
	MOS/MSC	25-Sep-07	N/A					ZONAL	
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: AMM 05-20-84PROC. REF: AMM 05-20-84									
57-Z541-213-001-A00 S	GENERAL VISUAL INSPECTION(EXTERNAL) (ZONES 541 AND 641)							Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 05-20-86PROC. REF: AMM 05-20-86									
57-Z541-214-001-A00 S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 541 AND 641) (L600 ONLY)							Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 05-20-86PROC. REF: AMM 05-20-86									
57-Z541-214-001-A01	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 541 AND 641)NOTE:EWIS (L650 ONLY)							Service	ATA:57
	MOS/MSC	25-Sep-07	N/A					ZONAL	
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: AMM 05-20-86PROC. REF: AMM 05-20-86									
57-Z551-213-002-A00 S	GENERAL VISUAL INSPECTION(EXTERNAL) (ZONES 551, 561, 651, 661)							Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 05-20-88PROC. REF: AMM 05-20-88									

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-Z551-214-002-A00 S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 551, 561, 651, 661) (L600 ONLY)							Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 05-20-88PROC. REF: AMM 05-20-88									
57-Z551-214-002-A01	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 551, 561, 651, 661)NOTE:EWIS (L650 ONLY)							Service	ATA:57
	MOS/MSC	25-Sep-07	N/A					ZONAL	
	HRS	0							
	AFL	0							
									PKG:6016
PROC. REF: AMM 05-20-88PROC. REF: AMM 05-20-88									
57-Z571-213-001-A00 S	GENERAL VISUAL INSPECTION(EXTERNAL) (ZONES 571, 671, 5711, 6711, 5712, 6712, 5713, 6713)							Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 05-20-90PROC. REF: AMM 05-20-90									
57-Z571-214-001-A00 S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 571, 671, 5711, 6711, 5712, 6712, 5713, 6713) (L600 ONLY)							Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 05-20-90PROC. REF: AMM 05-20-90									
57-Z571-214-001-A01	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 571, 671, 5711, 6711, 5712, 6712, 5713, 6713)NOTE:EWIS (L650 ONLY)							Service	ATA:57
	MOS/MSC	25-Sep-07	N/A					ZONAL	
	HRS	0							
	AFL	0							
PROC. REF: AMM 05-20-90PROC. REF: AMM 05-20-90									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-Z572-213-001-A00 S	GENERAL VISUAL INSPECTION(EXTERNAL) (ZONES 572, 672, 5721, 6721, 5722, 6722)							Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 05-20-92PROC. REF: AMM 05-20-92									
57-Z572-214-001-A00 S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 572, 672, 5721, 6721, 5722, 6722) (L600 ONLY)							Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 05-20-92PROC. REF: AMM 05-20-92									
57-Z572-214-001-A01	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 572, 672, 5721, 6721, 5722, 6722).NOTE:EWIS (L650 ONLY)							Service	ATA:57
	MOS/MSC	25-Sep-07	N/A					ZONAL	
	HRS	0							
	AFL	0							
PROC. REF: AMM 05-20-92PROC. REF: AMM 05-20-92									
57-Z573-213-001-A00 S	GENERAL VISUAL INSPECTION(EXTERNAL) (ZONES 573, 673, 5731, 6731, 5732, 6732)							Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 05-20-94PROC. REF: AMM 05-20-94									
57-Z573-214-001-A00 S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 573, 673, 5731, 6731, 5732, 6732) (L600 ONLY)							Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 05-20-94PROC. REF: AMM 05-20-94									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-Z573-214-001-A01	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 573, 673, 5731, 6731, 5732, 6732)NOTE:EWIS (L650 ONLY)							Service	ATA:57
	MOS/MSC	25-Sep-07	N/A					ZONAL	
	HRS	0							
	AFL	0							
PROC. REF: AMM 05-20-94PROC. REF: AMM 05-20-94									
574000-0201	LH WING LEADING EDGE WING ASSEMBLY							Component	ATA:57
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 57-41-00, AMM 57-42-00, AMM 57-43-00PROC. REF: AMM 57-41-00, AMM 57-42-00, AMM 57-43-00									
574000-0202	LH WING LEADING EDGE WING ASSEMBLY							Component	ATA:57
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 57-41-00, AMM 57-42-00, AMM 57-43-00PROC. REF: AMM 57-41-00, AMM 57-42-00, AMM 57-43-00									
574000-0203	LH WING LEADING EDGE WING ASSEMBLY							Component	ATA:57
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 57-41-00, AMM 57-42-00, AMM 57-43-00PROC. REF: AMM 57-41-00, AMM 57-42-00, AMM 57-43-00									
574000-0204	RH WING LEADING EDGE WING ASSEMBLY							Component	ATA:57
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 57-41-00, AMM 57-42-00, AMM 57-43-00PROC. REF: AMM 57-41-00, AMM 57-42-00, AMM 57-43-00									
574000-0205	RH WING LEADING EDGE WING ASSEMBLY							Component	ATA:57
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 57-41-00, AMM 57-42-00, AMM 57-43-00PROC. REF: AMM 57-41-00, AMM 57-42-00, AMM 57-43-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
574000-0206	RH WING LEADING EDGE WING ASSEMBLY							Component	ATA:57
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 57-41-00, AMM 57-42-00, AMM 57-43-00PROC. REF: AMM 57-41-00, AMM 57-42-00, AMM 57-43-00									
575300-0101	WING FLAP ASSY ASSEMBLY							Component	ATA:57
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-50-00PROC. REF: AMM 27-50-00									
575300-0102	WING FLAP ASSY ASSEMBLY							Component	ATA:57
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-50-00PROC. REF: AMM 27-50-00									
575600-0101	LH WING SHROUD ASSY							Component	ATA:57
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									
575600-0102	RH WING SHROUD ASSY							Component	ATA:57
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									
575600-0201	LH WING SHROUD ASSY							Component	ATA:57
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
575600-0202	RH WING SHROUD ASSY							Component	ATA:57
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
575600-0301	LH MOBILE SHROUD ASSY							Component	ATA:57
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
575600-0302	RH MOBILE SHROUD ASSY							Component	ATA:57
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
576600-0101	LHUP SHROUD ASSY							Component	ATA:57
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
576600-0102	RHUP SHROUD ASSY							Component	ATA:57
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								
576600-0201	LH WING FIXED SHROUD ASSY							Component	ATA:57
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERIC	PROC. REF: NDT GENERIC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
576600-0202	RH WING FIXED SHROUD ASSY							Component	ATA:57
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									
576602-0101	LH WING SHROUD ASSY							Component	ATA:57
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									
576602-0102	RH WING SHROUD ASSY							Component	ATA:57
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									
576604-0101	LH WING FIXED SHROUD ASSY							Component	ATA:57
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									
576604-0102	RH WING FIXED SHROUD ASSY							Component	ATA:57
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									
ATA 71 - POWER PLANT									
71-10-00-211-001-A00 S	VISUALLY CHECK COWLINGSEALS							Service	ATA:71
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 71-10-00PROC. REF: AMM 71-10-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 71 - POWER PLANT									
71-10-00-220-001-A00 S	INSPECT (DETAILED INSPECTION) COWLING INBOARD/ OUTBOARD ATTACHMENT AND SURROUNDING STRUCTURE							Service	ATA:71
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 71-10-00PROC. REF: AMM 71-10-00									
71-20-00-220-001-A00 S	INSPECT (DETAILED INSPECTION) ENGINE MOUNTING ASSY							Service	ATA:71
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
71-60-01-211-001-A00 S	VISUALLY CHECK AIR INTAKEATTACHMENT							Service	ATA:71
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 71-60-01PROC. REF: AMM 71-60-01									
71-60-01-211-002-A00 S	VISUALLY CHECK AIR INTAKE REAR BULKHEAD AND FIRE SHIELD							Service	ATA:71
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 71-60-01PROC. REF: AMM 71-60-01									
71-Z411-213-001-A00 S	GENERAL VISUAL INSPECTION(EXTERNAL) (ZONES 411, 412, 413, 421, 422, 423)							Service	ATA:71
	MOS	17-Oct-25	24 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	1000 (+20/-20)						
	AFL	5820							
									PKG:5004
PROC. REF: AMM 05-20-70PROC. REF: AMM 05-20-70									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 71 - POWER PLANT									
71-Z411-214-001-A00 S	GENERAL VISUAL INSPECTION (INTERNAL) (ZONES 411, 412, 413, 415, 421, 422, 423 AND 425) (L600 ONLY)							Service	ATA:71
	MOS	17-Oct-25	24 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	1000 (+20/-20)						
	AFL	5820							
									PKG:5004
PROC. REF: AMM 05-20-70PROC. REF: AMM 05-20-70									
71-Z411-214-001-A01	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 411, 412, 413, 415, 421, 422, 423 AND 425)NOTE:EWIS (L650 ONLY)							Service	ATA:71
	MOS/MSC	25-Sep-07	N/A					ZONAL	
	HRS	0							
	AFL	0							
PROC. REF: AMM 05-20-70PROC. REF: AMM 05-20-70									
711000-0101	LEFT UP COWLING -NACELLE ASSEMBLY							Component	ATA:71
PN:145-76830-401	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:1028	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 71-11-01PROC. REF: AMM 71-11-01									
711000-0102	RIGHT UP COWLING -NACELLE ASSEMBLY							Component	ATA:71
PN:145-76830-402	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:1031	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 71-11-01PROC. REF: AMM 71-11-01									
711000-0103	LEFT LW ENGINE COWLING ASSEMBLY							Component	ATA:71
PN:135-04972-405	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:0000137717	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 71-12-01PROC. REF: AMM 71-12-01									
711000-0104	RIGHT LW ENGINE COWLING ASSEMBLY							Component	ATA:71
PN:135-04974-405	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:0000137712	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 71-12-01PROC. REF: AMM 71-12-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 71 - POWER PLANT									
711000-0201		LH ENG STRUCTURE -APRON, COWLING ASSEMBLY						Component	ATA:71
PN:145-77030-401	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:1017	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 71-13-01	PROC. REF: AMM 71-13-01								
711000-0202		RH ENG STRUCTURE -APRON, COWLING ASSEMBLY						Component	ATA:71
PN:145-77030-402	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:1013	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 71-13-01	PROC. REF: AMM 71-13-01								
711000-0301		LHLW COWLING ASSEMBLY						Component	ATA:71
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 71-12-01	PROC. REF: AMM 71-12-01								
711000-0302		RHLW COWLING ASSEMBLY						Component	ATA:71
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 71-12-01	PROC. REF: AMM 71-12-01								
712000-0201		LH ENG AFT SHOCKMOUNT ASSEMBLY						Component	ATA:71
PN:LM-223-SA7	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 71-20-00	PROC. REF: AMM 71-20-00								
712000-0202		RH ENG AFT SHOCKMOUNT ASSEMBLY						Component	ATA:71
PN:LM-223-SA7	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 71-20-00	PROC. REF: AMM 71-20-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 71 - POWER PLANT									
712000-0203	LH ENG AFT SHOCKMOUNT ASSEMBLY							Component	ATA:71
PN:LM-223-SA7	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
712000-0204	RH ENG AFT SHOCKMOUNT ASSEMBLY							Component	ATA:71
PN:LM-223-SA7	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
712000-0301	LH ENG FORWARD FLUIDLASTIC NL TUN ISOLATOR							Component	ATA:71
PN:LM-223-SA5-1	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									
712000-0302	RH ENG FORWARD FLUIDLASTIC NL TUN ISOLATOR							Component	ATA:71
PN:LM-223-SA5-1	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									
712000-0303	LH ENG FORWARD FLUIDLASTIC NL TUN ISOLATOR							Component	ATA:71
PN:LM-223-SA5-1	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									
712000-0304	RH ENG FORWARD FLUIDLASTIC NL TUN ISOLATOR							Component	ATA:71
PN:LM-223-SA5-1	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 71 - POWER PLANT									
716000-0101	LH ENGINE AIR INLET MODULE							Component	ATA:71
PN:135-04892-407	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:NC2048	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 71-60-01	PROC. REF: AMM 71-60-01								
716000-0102	RH ENGINE AIR INLET MODULE							Component	ATA:71
PN:135-04892-407	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:NC2050	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 71-60-01	PROC. REF: AMM 71-60-01								
71EN1	NO. 1 ENGINE							Component	ATA:71
PN:23074862	MOS/MSC	30-Aug-11	E/C						
SN:CAE312988	HRS	4825.2		TSN 4721, TSR 0					
WC#: 71.EN1	AFL	2549		TSN 2477, TSR 0					
PROC. REF: AMM 71-00-00	PROC. REF: AMM 71-00-00								
71EN2	NO. 2 ENGINE							Component	ATA:71
PN:23074862	MOS/MSC	30-Aug-11	E/C						
SN:CAE312989	HRS	4825.2		TSN 4721, TSR 0					
WC#: 71.EN2	AFL	2549		TSN 2477, TSR 0					
PROC. REF: AMM 71-00-00	PROC. REF: AMM 71-00-00								
ATA 72 - ENGINE									
72-00-00-970-001-A00	NO. 1 ENGINE - ENGINE TREND DOWNLOAD/ANALYSIS							Service	ATA:72
	MOS/MSC	15-Oct-24	N/A						
	HRS	10473.9							
	ENC	5562							
PROC. REF: GENERIC NO REF, AMM 72-00-00	PROC. REF: GENERIC NO REF, AMM 72-00-00								
72-00-00-970-001-A00	NO. 2 ENGINE - ENGINE TREND DOWNLOAD/ANALYSIS							Service	ATA:72
	MOS/MSC	15-Oct-24	N/A						
	HRS	10473.9							
	ENC	5562							
PROC. REF: GENERIC NO REF, AMM 72-00-00	PROC. REF: GENERIC NO REF, AMM 72-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
72-00-CUS-0701 U		NO. 1 ENGINE - PERFORM ENGINE RUN							Service ATA:72
	DAYS/MSC	23-Apr-20	A/R						
	HRS	9252							
	ENC	4912							
72-00-CUS-0701 U		NO. 2 ENGINE - PERFORM ENGINE RUN							Service ATA:72
	DAYS/MSC	23-Apr-20	A/R						
	HRS	9252							
	ENC	4912							
72-20-00-212-001-A00		INSPECT (GENERAL VISUAL) ENGINE AIR INTAKE							Service ATA:72
	MOS	31-Dec-25						SYSTEM	
	HRS	11048.3	500		11548.3		272		
	AFL	5890							
PROC. REF: AMM 72-25-02PROC. REF: AMM 72-25-02									
72-20-00-212-001-A00		NO. 1 ENGINE - INSPECT (GENERAL VISUAL) ENGINE AIR INTAKE							Service ATA:72
	MOS	31-Dec-25						SYSTEM	
	HRS	10944.1	500		(11444.1) 11548.3		272		
	ENC	5818							
PROC. REF: GENERIC NO REF, AMM 72-25-02PROC. REF: GENERIC NO REF, AMM 72-25-02									
72-20-00-212-001-A00		NO. 2 ENGINE - INSPECT (GENERAL VISUAL) ENGINE AIR INTAKE							Service ATA:72
	MOS	31-Dec-25						SYSTEM	
	HRS	10944.1	500		(11444.1) 11548.3		272		
	ENC	5818							
PROC. REF: GENERIC NO REF, AMM 72-25-02PROC. REF: GENERIC NO REF, AMM 72-25-02									
72-21-01-220-001-A00		NO. 1 ENGINE - INSPECT (DETAILED INSPECTION) FAN BLADES							Service ATA:72
	MOS	17-Jan-17						SYSTEM	
	HRS	7935.4	5000		(12935.4) 13039.6		1763.3		
	ENC	4242							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
PROC. REF: AMM 72-21-01, MM 72-21-15PROC. REF: AMM 72-21-01, MM 72-21-15									
72-21-01-220-001-A00	NO. 2 ENGINE - INSPECT (DETAILED INSPECTION) FAN BLADES								Service ATA:72
	MOS	17-Jan-17						SYSTEM	
	HRS	7935.4	5000		(12935.4) 13039.6		1763.3		
	ENC	4242							
PROC. REF: AMM 72-21-01, MM 72-21-15PROC. REF: AMM 72-21-01, MM 72-21-15									
72-21-20-220-002-A00	NO. 1 ENGINE - INSPECT (DETAILED INSPECTION) FAN SPINNER P/N 23054034, 23064250 OR 23065046 ONLY								Service ATA:72
PN:23087826	MOS/MSC	19-Aug-15	N/A						
SN:FF378408	HRS	7356.1							
	ENC	3920							
PROC. REF: AMM 72-31-01, MM 72-21-20, MM 72-21-20, MM 72-21-20, MM 72-21-20PROC. REF: AMM 72-31-01, MM 72-21-20, MM 72-21-20, MM 72-21-20, MM 72-21-20									
72-21-20-220-002-A00	NO. 2 ENGINE - INSPECT (DETAILED INSPECTION) FAN SPINNER P/N 23054034, 23064250 OR 23065046 ONLY								Service ATA:72
PN:23087826	MOS/MSC	06-Jul-15	N/A						
SN:FF378411	HRS	7356.1							
	ENC	3920							
PROC. REF: AMM 72-31-01, MM 72-21-20, MM 72-21-20, MM 72-21-20, MM 72-21-20PROC. REF: AMM 72-31-01, MM 72-21-20, MM 72-21-20, MM 72-21-20, MM 72-21-20									
72-62-01-212-001-A00	NO. 1 ENGINE - INSPECT (GENERAL VISUAL) GEARBOX RETENTION CABLES								Service ATA:72
	MOS/MSC	25-Sep-07	N/A						
	HRS	0							
	ENC	0							
PROC. REF: AMM 72-63-03, MM 72-63-10PROC. REF: AMM 72-63-03, MM 72-63-10									
72-62-01-212-001-A00	NO. 2 ENGINE - INSPECT (GENERAL VISUAL) GEARBOX RETENTION CABLES								Service ATA:72
	MOS/MSC	25-Sep-07	N/A						
	HRS	0							
	ENC	0							
PROC. REF: AMM 72-63-03, MM 72-63-10PROC. REF: AMM 72-63-03, MM 72-63-10									

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
72-63-01-710-001-A00	NO. 1 ENGINE - OPERATIONALLY CHECK STARTER DRAIN ADAPTER POST-MOD. SB AE3007A-72-253 AND PRE-MOD SB AE3007A-72-330.								Service ATA:72
	MOS/MSC	25-Sep-07	N/A					SYSTEM	
	HRS	0							
	ENC	0							
PROC. REF: AMM 72-63-02, MM 72-63-10PROC. REF: AMM 72-63-02, MM 72-63-10									
72-63-01-710-001-A00	NO. 2 ENGINE - OPERATIONALLY CHECK STARTER DRAIN ADAPTER POST-MOD. SB AE3007A-72-253 AND PRE-MOD SB AE3007A-72-330.								Service ATA:72
	MOS/MSC	25-Sep-07	N/A					SYSTEM	
	HRS	0							
	ENC	0							
PROC. REF: AMM 72-63-02, MM 72-63-10PROC. REF: AMM 72-63-02, MM 72-63-10									
720000-0101	RH ENG TURBOFAN,WT/FADEC,WT/SENSOR UNIT								Component ATA:72
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 73-22-01PROC. REF: AMM 73-22-01									
720000-0102	LH ENG TURBOFAN,WT/FADEC,WT/SENSOR UNIT								Component ATA:72
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 73-22-01PROC. REF: AMM 73-22-01									
720000-0103	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF ACCESSORY DRIVES SECTION(MPG EQUIVALENT TASKS 71-Z411-214-001-A00 AND 71-Z411-214-001-A01)								Service ATA:72
	MOS	14-Jul-22							
	HRS	9811.6	10000		(19811.6) 19915.8		8639.5		
	ENC	5199							
PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
720000-0103		NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF ACCESSORY DRIVES SECTION(MPG EQUIVALENT TASKS 71-Z411-214-001-A00 AND 71-Z411-214-001-A01)							Service ATA:72
	MOS	14-Jul-22							
	HRS	9811.6	10000		(19811.6) 19915.8		8639.5		
	ENC	5199							
PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00									
720000-0104		NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF BYPASS SECTION (MPG EQUIVALENT TASKS 71-Z411-214-001-A00 AND 71-Z411-214-001-A01)							Service ATA:72
	MOS	14-Jul-22							
	HRS	9811.6	10000		(19811.6) 19915.8		8639.5		
	ENC	5199							
PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00									
720000-0104		NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF BYPASS SECTION (MPG EQUIVALENT TASKS 71-Z411-214-001-A00 AND 71-Z411-214-001-A01)							Service ATA:72
	MOS	14-Jul-22							
	HRS	9811.6	10000		(19811.6) 19915.8		8639.5		
	ENC	5199							
PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00									
720000-0106		NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF FUEL SYSTEM DISTRIBUTION (TUBES AND HOSES) (MPG EQUIVALENT TASKS 71-Z411-214-001-A00 AND 71-Z411-214-001-A01)							Service ATA:72
	MOS	14-Jul-22							
	HRS	9811.6	10000		(19811.6) 19915.8		8639.5		
	ENC	5199							
PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00									
720000-0106		NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF FUEL SYSTEM DISTRIBUTION (TUBES AND HOSES) (MPG EQUIVALENT TASKS 71-Z411-214-001-A00 AND 71-Z411-214-001-A01)							Service ATA:72
	MOS	14-Jul-22							
	HRS	9811.6	10000		(19811.6) 19915.8		8639.5		
	ENC	5199							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00									
720000-0108		NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF POWER CONTROL SECTION (HARNESSES) (MPG EQUIVALENT TASKS 71-Z411-214-001-A00 AND 71-Z411-214-001-A01)						Service	ATA:72
	MOS	14-Jul-22							
	HRS	9811.6	10000		(19811.6) 19915.8		8639.5		
	ENC	5199							
PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00									
720000-0108		NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF POWER CONTROL SECTION (HARNESSES) (MPG EQUIVALENT TASKS 71-Z411-214-001-A00 AND 71-Z411-214-001-A01)						Service	ATA:72
	MOS	14-Jul-22							
	HRS	9811.6	10000		(19811.6) 19915.8		8639.5		
	ENC	5199							
PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00									
720000-0109		NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF TURBINE-INTERSTAGE THERMOCOUPLE (A) HARNESS (MPG EQUIVALENT TASKS 71-Z411-214-001-A00 AND 71-Z411-214-001-A01)						Service	ATA:72
	MOS	14-Jul-22							
	HRS	9811.6	10000		(19811.6) 19915.8		8639.5		
	ENC	5199							
PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00									
720000-0109		NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF TURBINE-INTERSTAGE THERMOCOUPLE (A) HARNESS (MPG EQUIVALENT TASKS 71-Z411-214-001-A00 AND 71-Z411-214-001-A01)						Service	ATA:72
	MOS	14-Jul-22							
	HRS	9811.6	10000		(19811.6) 19915.8		8639.5		
	ENC	5199							
PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
720000-0110		NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF TURBINE-INTERSTAGE THERMOCOUPLE (B) HARNESS (MPG EQUIVALENT TASKS 71-Z411-214-001-A00 AND 71-Z411-214-001-A01)							Service ATA:72
	MOS	14-Jul-22							
	HRS	9811.6	10000		(19811.6) 19915.8		8639.5		
	ENC	5199							
PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00									
720000-0110		NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF TURBINE-INTERSTAGE THERMOCOUPLE (B) HARNESS (MPG EQUIVALENT TASKS 71-Z411-214-001-A00 AND 71-Z411-214-001-A01)							Service ATA:72
	MOS	14-Jul-22							
	HRS	9811.6	10000		(19811.6) 19915.8		8639.5		
	ENC	5199							
PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00									
720000-0111		NO. 1 ENGINE - PERFORM SPECIAL PROCEDURES ON THE ENGINE							Service ATA:72
	MOS/MSC	25-Sep-07	N/A						
	HRS	0							
	ENC	0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
720000-0111		NO. 2 ENGINE - PERFORM SPECIAL PROCEDURES ON THE ENGINE							Service ATA:72
	MOS/MSC	25-Sep-07	N/A						
	HRS	0							
	ENC	0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
720010-0101		NO. 1 ENGINE - MANIFOLD ASSEMBLY							Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 73-13-02, MM 73-13-10, MM 73-13-10, MM 73-13-10, MM 73-13-10, MM 73-13-10, MM 73-13-10, MM 73-13-10PROC. REF: AMM 73-13-02, MM 73-13-10, MM 73-13-10, MM 73-13-10, MM 73-13-10, MM 73-13-10, MM 73-13-10, MM 73-13-10, MM 73-13-10									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
720010-0101	NO. 2 ENGINE - MANIFOLD ASSEMBLY							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 73-13-02, MM 73-13-10, MM 73-13-10, MM 73-13-10, MM 73-13-10, MM 73-13-10, MM 73-13-10, MM 73-13-10, MM 73-13-10PROC. REF: AMM 73-13-02, MM 73-13-10, MM 73-13-10, MM 73-13-10, MM 73-13-10, MM 73-13-10, MM 73-13-10, MM 73-13-10, MM 73-13-10									
720038-0101	NO. 1 ENGINE - ACCESSORY DRIVE GEARBOX MODULE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-63-10, MM 72-63-10PROC. REF: MM 72-63-10, MM 72-63-10									
720038-0101	NO. 2 ENGINE - ACCESSORY DRIVE GEARBOX MODULE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-63-10, MM 72-63-10PROC. REF: MM 72-63-10, MM 72-63-10									
720039-0101	NO. 1 ENGINE - ACCESSORY DRIVE GEARBOX							Component	ATA:72
PN:23079389	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:2869	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 72-61-01, MM 72-63-10, MM 72-63-10PROC. REF: AMM 72-61-01, MM 72-63-10, MM 72-63-10									
720039-0101	NO. 2 ENGINE - ACCESSORY DRIVE GEARBOX							Component	ATA:72
PN:23079389	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:2468	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 72-61-01, MM 72-63-10, MM 72-63-10PROC. REF: AMM 72-61-01, MM 72-63-10, MM 72-63-10									
721000-0101	NO. 1 ENGINE - FAN ROTOR ASSEMBLY							Component	ATA:72
PN:23075474	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:MW50802	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
721000-0101	NO. 2 ENGINE - FAN ROTOR ASSEMBLY							Component	ATA:72
PN:23075474	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:MW50853	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
721003-0101	NO. 1 ENGINE - INSPECT ENGINE AT 100 CYCLES							Service	ATA:72
	MOS/MSC	25-Sep-07	A/R						
	HRS	0							
	ENC	0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
721003-0101	NO. 2 ENGINE - INSPECT ENGINE AT 100 CYCLES							Service	ATA:72
	MOS/MSC	25-Sep-07	A/R						
	HRS	0							
	ENC	0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
722100-0101	NO. 1 ENGINE - FAN WHEEL							Component	ATA:72
PN:23058865	MOS	25-Sep-07		TSN 0				LIFE LIMIT	
SN:MW50802	HRS	0		TSN 0					
	ENC	0	20000	TSN 0	(20000) 20072		14047		
PROC. REF: MM 72-21-10, MM 72-21-10, BULLETINSPROC. REF: MM 72-21-10, MM 72-21-10, BULLETINS									
722100-0101	NO. 2 ENGINE - FAN WHEEL							Component	ATA:72
PN:23058865	MOS	25-Sep-07		TSN 0				LIFE LIMIT	
SN:MW50853	HRS	0		TSN 0					
	ENC	0	20000	TSN 0	(20000) 20072		14047		
PROC. REF: MM 72-21-10, MM 72-21-10, BULLETINSPROC. REF: MM 72-21-10, MM 72-21-10, BULLETINS									
722100-0102	NO. 1 ENGINE - FAN DRIVE SHAFT							Component	ATA:72
PN:23074382	MOS	25-Sep-07		TSN 0				LIFE LIMIT	
SN:GV246257	HRS	0		TSN 0					
	ENC	0	20000	TSN 0	(20000) 20072		14047		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
PROC. REF: MM 72-25-40, MM 72-25-40PROC. REF: MM 72-25-40, MM 72-25-40									
722100-0102		NO. 2 ENGINE - FAN DRIVE SHAFT							Component ATA:72
PN:23074382	MOS	25-Sep-07		TSN 0				LIFE LIMIT	
SN:GV246248	HRS	0		TSN 0					
	ENC	0	20000	TSN 0	(20000) 20072		14047		
PROC. REF: MM 72-25-40, MM 72-25-40PROC. REF: MM 72-25-40, MM 72-25-40									
722101-0101		NO. 1 ENGINE - FORWARD FAN BLADE RETAINER							Component ATA:72
PN:23062491	MOS	25-Sep-07		TSN 0				LIFE LIMIT	
SN:HK120747	HRS	0		TSN 0					
	ENC	0	20000	TSN 0	(20000) 20072		14047		
PROC. REF: MM 72-21-30, MM 72-21-30PROC. REF: MM 72-21-30, MM 72-21-30									
722101-0101		NO. 2 ENGINE - FORWARD FAN BLADE RETAINER							Component ATA:72
PN:23062491	MOS	25-Sep-07		TSN 0				LIFE LIMIT	
SN:HK120751	HRS	0		TSN 0					
	ENC	0	20000	TSN 0	(20000) 20072		14047		
PROC. REF: MM 72-21-30, MM 72-21-30PROC. REF: MM 72-21-30, MM 72-21-30									
722102-0101		NO. 1 ENGINE - FAN SUPPORT BEARING HOUSING ASSEMBLY							Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
722102-0101		NO. 2 ENGINE - FAN SUPPORT BEARING HOUSING ASSEMBLY							Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
722103-0101	NO. 1 ENGINE - CLEAN AND DO THE DETAILED INSPECTION OF THE FAN BLADES							Service	ATA:72
	MOS/MSC	25-Sep-07	N/A						
	HRS	0							
	ENC	0							
PROC. REF: AMM 72-21-01, MM 72-21-03, MM 72-21-03PROC. REF: AMM 72-21-01, MM 72-21-03, MM 72-21-03									
722103-0101	NO. 2 ENGINE - CLEAN AND DO THE DETAILED INSPECTION OF THE FAN BLADES							Service	ATA:72
	MOS/MSC	25-Sep-07	N/A						
	HRS	0							
	ENC	0							
PROC. REF: AMM 72-21-01, MM 72-21-03, MM 72-21-03PROC. REF: AMM 72-21-01, MM 72-21-03, MM 72-21-03									
722104-0101	NO. 1 ENGINE - FAN SPINNER ASSEMBLY							Component	ATA:72
PN:23087826	MOS/MSC	08-Sep-10	O/C	TSN 0					
SN:FF378408	HRS	3738.1		TSN 0					
	ENC	1964		TSN 0					
PROC. REF: AMM 72-31-01, MM 72-21-20, MM 72-21-20PROC. REF: AMM 72-31-01, MM 72-21-20, MM 72-21-20									
722104-0101	NO. 2 ENGINE - FAN SPINNER ASSEMBLY							Component	ATA:72
PN:23087826	MOS/MSC	09-Sep-10	O/C	TSN 0					
SN:FF378411	HRS	3738.1		TSN 0					
	ENC	1964		TSN 0					
PROC. REF: AMM 72-31-01, MM 72-21-20, MM 72-21-20PROC. REF: AMM 72-31-01, MM 72-21-20, MM 72-21-20									
722105-0101	NO. 1 ENGINE - FRONT FRAME ASSEMBLY							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
722105-0101	NO. 2 ENGINE - FRONT FRAME ASSEMBLY							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
722107-0101	NO. 1 ENGINE - FAN CASE ASSEMBLY							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-25-30PROC. REF: MM 72-25-30									
722107-0101	NO. 2 ENGINE - FAN CASE ASSEMBLY							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-25-30PROC. REF: MM 72-25-30									
722108-0101	NO. 1 ENGINE - NO. 1 FAN BYPASS VANE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-25-10, MM 72-25-10PROC. REF: MM 72-25-10, MM 72-25-10									
722108-0101	NO. 2 ENGINE - NO. 1 FAN BYPASS VANE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-25-10, MM 72-25-10PROC. REF: MM 72-25-10, MM 72-25-10									
722108-0102	NO. 1 ENGINE - NO. 2 FAN BYPASS VANE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-25-10, MM 72-25-10PROC. REF: MM 72-25-10, MM 72-25-10									
722108-0102	NO. 2 ENGINE - NO. 2 FAN BYPASS VANE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-25-10, MM 72-25-10PROC. REF: MM 72-25-10, MM 72-25-10									

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
722108-0103	NO. 1 ENGINE - NO. 3 FAN BYPASS VANE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-25-10, MM 72-25-10PROC. REF: MM 72-25-10, MM 72-25-10									
722108-0103	NO. 2 ENGINE - NO. 3 FAN BYPASS VANE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-25-10, MM 72-25-10PROC. REF: MM 72-25-10, MM 72-25-10									
722108-0104	NO. 1 ENGINE - NO. 4 FAN BYPASS VANE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-25-10, MM 72-25-10PROC. REF: MM 72-25-10, MM 72-25-10									
722108-0104	NO. 2 ENGINE - NO. 4 FAN BYPASS VANE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-25-10, MM 72-25-10PROC. REF: MM 72-25-10, MM 72-25-10									
722108-0105	NO. 1 ENGINE - NO. 5 FAN BYPASS VANE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-25-10, MM 72-25-10PROC. REF: MM 72-25-10, MM 72-25-10									
722108-0105	NO. 2 ENGINE - NO. 5 FAN BYPASS VANE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-25-10, MM 72-25-10PROC. REF: MM 72-25-10, MM 72-25-10									

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
722108-0106	NO. 1 ENGINE - NO. 6 FAN BYPASS VANE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-25-10, MM 72-25-10PROC. REF: MM 72-25-10, MM 72-25-10									
722108-0106	NO. 2 ENGINE - NO. 6 FAN BYPASS VANE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-25-10, MM 72-25-10PROC. REF: MM 72-25-10, MM 72-25-10									
722108-0107	NO. 1 ENGINE - NO. 7 FAN BYPASS VANE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-25-10, MM 72-25-10PROC. REF: MM 72-25-10, MM 72-25-10									
722108-0107	NO. 2 ENGINE - NO. 7 FAN BYPASS VANE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-25-10, MM 72-25-10PROC. REF: MM 72-25-10, MM 72-25-10									
722108-0108	NO. 1 ENGINE - NO. 8 FAN BYPASS VANE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-25-10, MM 72-25-10PROC. REF: MM 72-25-10, MM 72-25-10									
722108-0108	NO. 2 ENGINE - NO. 8 FAN BYPASS VANE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-25-10, MM 72-25-10PROC. REF: MM 72-25-10, MM 72-25-10									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
722108-0109	NO. 1 ENGINE - NO. 9 FAN BYPASS VANE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-25-10, MM 72-25-10PROC. REF: MM 72-25-10, MM 72-25-10									
722108-0109	NO. 2 ENGINE - NO. 9 FAN BYPASS VANE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-25-10, MM 72-25-10PROC. REF: MM 72-25-10, MM 72-25-10									
722108-0110	NO. 1 ENGINE - NO. 10 FAN BYPASS VANE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-25-10, MM 72-25-10PROC. REF: MM 72-25-10, MM 72-25-10									
722108-0110	NO. 2 ENGINE - NO. 10 FAN BYPASS VANE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-25-10, MM 72-25-10PROC. REF: MM 72-25-10, MM 72-25-10									
722108-0111	NO. 1 ENGINE - NO. 11 FAN BYPASS VANE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-25-10, MM 72-25-10PROC. REF: MM 72-25-10, MM 72-25-10									
722108-0111	NO. 2 ENGINE - NO. 11 FAN BYPASS VANE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-25-10, MM 72-25-10PROC. REF: MM 72-25-10, MM 72-25-10									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
722108-0112	NO. 1 ENGINE - NO. 12 FAN BYPASS VANE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-25-10, MM 72-25-10PROC. REF: MM 72-25-10, MM 72-25-10									
722108-0112	NO. 2 ENGINE - NO. 12 FAN BYPASS VANE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-25-10, MM 72-25-10PROC. REF: MM 72-25-10, MM 72-25-10									
722108-0113	NO. 1 ENGINE - NO. 13 FAN BYPASS VANE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-25-10, MM 72-25-10PROC. REF: MM 72-25-10, MM 72-25-10									
722108-0113	NO. 2 ENGINE - NO. 13 FAN BYPASS VANE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-25-10, MM 72-25-10PROC. REF: MM 72-25-10, MM 72-25-10									
722108-0114	NO. 1 ENGINE - NO. 14 FAN BYPASS VANE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-25-10, MM 72-25-10PROC. REF: MM 72-25-10, MM 72-25-10									
722108-0114	NO. 2 ENGINE - NO. 14 FAN BYPASS VANE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-25-10, MM 72-25-10PROC. REF: MM 72-25-10, MM 72-25-10									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
722108-0115	NO. 1 ENGINE - NO. 15 FAN BYPASS VANE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-25-10, MM 72-25-10PROC. REF: MM 72-25-10, MM 72-25-10									
722108-0115	NO. 2 ENGINE - NO. 15 FAN BYPASS VANE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-25-10, MM 72-25-10PROC. REF: MM 72-25-10, MM 72-25-10									
722108-0116	NO. 1 ENGINE - NO. 16 FAN BYPASS VANE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-25-10, MM 72-25-10PROC. REF: MM 72-25-10, MM 72-25-10									
722108-0116	NO. 2 ENGINE - NO. 16 FAN BYPASS VANE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-25-10, MM 72-25-10PROC. REF: MM 72-25-10, MM 72-25-10									
722108-0117	NO. 1 ENGINE - NO. 17 FAN BYPASS VANE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-25-10, MM 72-25-10PROC. REF: MM 72-25-10, MM 72-25-10									
722108-0117	NO. 2 ENGINE - NO. 17 FAN BYPASS VANE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-25-10, MM 72-25-10PROC. REF: MM 72-25-10, MM 72-25-10									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
722108-0118	NO. 1 ENGINE - NO. 18 FAN BYPASS VANE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-25-10, MM 72-25-10PROC. REF: MM 72-25-10, MM 72-25-10									
722108-0118	NO. 2 ENGINE - NO. 18 FAN BYPASS VANE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-25-10, MM 72-25-10PROC. REF: MM 72-25-10, MM 72-25-10									
722108-0119	NO. 1 ENGINE - NO. 19 FAN BYPASS VANE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-25-10, MM 72-25-10PROC. REF: MM 72-25-10, MM 72-25-10									
722108-0119	NO. 2 ENGINE - NO. 19 FAN BYPASS VANE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-25-10, MM 72-25-10PROC. REF: MM 72-25-10, MM 72-25-10									
722108-0120	NO. 1 ENGINE - NO. 20 FAN BYPASS VANE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-25-10, MM 72-25-10PROC. REF: MM 72-25-10, MM 72-25-10									
722108-0120	NO. 2 ENGINE - NO. 20 FAN BYPASS VANE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-25-10, MM 72-25-10PROC. REF: MM 72-25-10, MM 72-25-10									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
722108-0121	NO. 1 ENGINE - NO. 21 FAN BYPASS VANE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-25-10, MM 72-25-10PROC. REF: MM 72-25-10, MM 72-25-10									
722108-0121	NO. 2 ENGINE - NO. 21 FAN BYPASS VANE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-25-10, MM 72-25-10PROC. REF: MM 72-25-10, MM 72-25-10									
722108-0122	NO. 1 ENGINE - NO. 22 FAN BYPASS VANE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-25-10, MM 72-25-10PROC. REF: MM 72-25-10, MM 72-25-10									
722108-0122	NO. 2 ENGINE - NO. 22 FAN BYPASS VANE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-25-10, MM 72-25-10PROC. REF: MM 72-25-10, MM 72-25-10									
722108-0123	NO. 1 ENGINE - NO. 23 FAN BYPASS VANE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-25-10, MM 72-25-10PROC. REF: MM 72-25-10, MM 72-25-10									
722108-0123	NO. 2 ENGINE - NO. 23 FAN BYPASS VANE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-25-10, MM 72-25-10PROC. REF: MM 72-25-10, MM 72-25-10									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
722108-0124	NO. 1 ENGINE - NO. 24 FAN BYPASS VANE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-25-10, MM 72-25-10PROC. REF: MM 72-25-10, MM 72-25-10									
722108-0124	NO. 2 ENGINE - NO. 24 FAN BYPASS VANE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-25-10, MM 72-25-10PROC. REF: MM 72-25-10, MM 72-25-10									
722108-0125	NO. 1 ENGINE - NO. 25 FAN BYPASS VANE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-25-10, MM 72-25-10PROC. REF: MM 72-25-10, MM 72-25-10									
722108-0125	NO. 2 ENGINE - NO. 25 FAN BYPASS VANE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-25-10, MM 72-25-10PROC. REF: MM 72-25-10, MM 72-25-10									
722108-0126	NO. 1 ENGINE - NO. 26 FAN BYPASS VANE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-25-10, MM 72-25-10PROC. REF: MM 72-25-10, MM 72-25-10									
722108-0126	NO. 2 ENGINE - NO. 26 FAN BYPASS VANE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-25-10, MM 72-25-10PROC. REF: MM 72-25-10, MM 72-25-10									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
722108-0127	NO. 1 ENGINE - NO. 27 FAN BYPASS VANE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-25-10, MM 72-25-10PROC. REF: MM 72-25-10, MM 72-25-10									
722108-0127	NO. 2 ENGINE - NO. 27 FAN BYPASS VANE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-25-10, MM 72-25-10PROC. REF: MM 72-25-10, MM 72-25-10									
722108-0128	NO. 1 ENGINE - NO. 28 FAN BYPASS VANE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-25-10, MM 72-25-10PROC. REF: MM 72-25-10, MM 72-25-10									
722108-0128	NO. 2 ENGINE - NO. 28 FAN BYPASS VANE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-25-10, MM 72-25-10PROC. REF: MM 72-25-10, MM 72-25-10									
722108-0129	NO. 1 ENGINE - NO. 29 FAN BYPASS VANE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-25-10, MM 72-25-10PROC. REF: MM 72-25-10, MM 72-25-10									
722108-0129	NO. 2 ENGINE - NO. 29 FAN BYPASS VANE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-25-10, MM 72-25-10PROC. REF: MM 72-25-10, MM 72-25-10									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
722108-0130	NO. 1 ENGINE - NO. 30 FAN BYPASS VANE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-25-10, MM 72-25-10PROC. REF: MM 72-25-10, MM 72-25-10									
722108-0130	NO. 2 ENGINE - NO. 30 FAN BYPASS VANE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-25-10, MM 72-25-10PROC. REF: MM 72-25-10, MM 72-25-10									
722109-0101	NO. 1 ENGINE - SEG CARBON FAN SEAL ASSEMBLY							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
722109-0101	NO. 2 ENGINE - SEG CARBON FAN SEAL ASSEMBLY							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
722111-0101	NO. 1 ENGINE - SPANNER NUT							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-21-05, MM 72-21-05PROC. REF: MM 72-21-05, MM 72-21-05									
722111-0101	NO. 2 ENGINE - SPANNER NUT							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-21-05, MM 72-21-05PROC. REF: MM 72-21-05, MM 72-21-05									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
722112-0101	NO. 1 ENGINE - BEARING SELF-LOCKING NUT							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
722112-0101	NO. 2 ENGINE - BEARING SELF-LOCKING NUT							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
722113-0101	NO. 1 ENGINE - ROLLER BEARING							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
722113-0101	NO. 2 ENGINE - ROLLER BEARING							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
722114-0101	NO. 1 ENGINE - NO. 1 FAN BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15									
722114-0101	NO. 2 ENGINE - NO. 1 FAN BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
722114-0102	NO. 1 ENGINE - NO. 2 FAN BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15	PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15								
722114-0102	NO. 2 ENGINE - NO. 2 FAN BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15	PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15								
722114-0103	NO. 1 ENGINE - NO. 3 FAN BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15	PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15								
722114-0103	NO. 2 ENGINE - NO. 3 FAN BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15	PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15								
722114-0104	NO. 1 ENGINE - NO. 4 FAN BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15	PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15								
722114-0104	NO. 2 ENGINE - NO. 4 FAN BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15	PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
722114-0105	NO. 1 ENGINE - NO. 5 FAN BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15									
722114-0105	NO. 2 ENGINE - NO. 5 FAN BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15									
722114-0106	NO. 1 ENGINE - NO. 6 FAN BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15									
722114-0106	NO. 2 ENGINE - NO. 6 FAN BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15									
722114-0107	NO. 1 ENGINE - NO. 7 FAN BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15									
722114-0107	NO. 2 ENGINE - NO. 7 FAN BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
722114-0108	NO. 1 ENGINE - NO. 8 FAN BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15	PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15								
722114-0108	NO. 2 ENGINE - NO. 8 FAN BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15	PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15								
722114-0109	NO. 1 ENGINE - NO. 9 FAN BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15	PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15								
722114-0109	NO. 2 ENGINE - NO. 9 FAN BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15	PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15								
722114-0110	NO. 1 ENGINE - NO. 10 FAN BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15	PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15								
722114-0110	NO. 2 ENGINE - NO. 10 FAN BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15	PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
722114-0111	NO. 1 ENGINE - NO. 11 FAN BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15									
722114-0111	NO. 2 ENGINE - NO. 11 FAN BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15									
722114-0112	NO. 1 ENGINE - NO. 12 FAN BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15									
722114-0112	NO. 2 ENGINE - NO. 12 FAN BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15									
722114-0113	NO. 1 ENGINE - NO. 13 FAN BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-21-15, MM 72-21-15PROC. REF: MM 72-21-15, MM 72-21-15									
722114-0113	NO. 2 ENGINE - NO. 13 FAN BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-21-15, MM 72-21-15PROC. REF: MM 72-21-15, MM 72-21-15									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
722114-0114	NO. 1 ENGINE - NO. 14 FAN BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-21-15, MM 72-21-15	PROC. REF: MM 72-21-15, MM 72-21-15								
722114-0114	NO. 2 ENGINE - NO. 14 FAN BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-21-15, MM 72-21-15	PROC. REF: MM 72-21-15, MM 72-21-15								
722114-0115	NO. 1 ENGINE - NO. 15 FAN BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-21-15, MM 72-21-15	PROC. REF: MM 72-21-15, MM 72-21-15								
722114-0115	NO. 2 ENGINE - NO. 15 FAN BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-21-15, MM 72-21-15	PROC. REF: MM 72-21-15, MM 72-21-15								
722114-0116	NO. 1 ENGINE - NO. 16 FAN BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15	PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15								
722114-0116	NO. 2 ENGINE - NO. 16 FAN BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15	PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
722114-0117	NO. 1 ENGINE - NO. 17 FAN BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15	PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15								
722114-0117	NO. 2 ENGINE - NO. 17 FAN BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15	PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15								
722114-0118	NO. 1 ENGINE - NO. 18 FAN BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15	PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15								
722114-0118	NO. 2 ENGINE - NO. 18 FAN BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15	PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15								
722114-0119	NO. 1 ENGINE - NO. 19 FAN BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15	PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15								
722114-0119	NO. 2 ENGINE - NO. 19 FAN BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15	PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
722114-0120	NO. 1 ENGINE - NO. 20 FAN BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15	PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15								
722114-0120	NO. 2 ENGINE - NO. 20 FAN BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15	PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15								
722114-0121	NO. 1 ENGINE - NO. 21 FAN BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15	PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15								
722114-0121	NO. 2 ENGINE - NO. 21 FAN BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15	PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15								
722114-0122	NO. 1 ENGINE - NO. 22 FAN BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15	PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15								
722114-0122	NO. 2 ENGINE - NO. 22 FAN BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15	PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
722114-0123	NO. 1 ENGINE - NO. 23 FAN BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15	PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15								
722114-0123	NO. 2 ENGINE - NO. 23 FAN BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15	PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15								
722114-0124	NO. 1 ENGINE - NO. 24 FAN BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15	PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15								
722114-0124	NO. 2 ENGINE - NO. 24 FAN BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15	PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15								
722120-0101	NO. 1 ENGINE - DETAILED INSPECTION OF THE FAN SPINNER							Service	ATA:72
	MOS/MSC	25-Sep-07	N/R						
	HRS	0							
	ENC	0							
PROC. REF: AMM 72-31-01, MM 72-21-20, MM 72-21-20, MM 72-21-20, MM 72-21-20	PROC. REF: AMM 72-31-01, MM 72-21-20, MM 72-21-20, MM 72-21-20, MM 72-21-20								
722120-0101	NO. 2 ENGINE - DETAILED INSPECTION OF THE FAN SPINNER							Service	ATA:72
	MOS/MSC	25-Sep-07	N/R						
	HRS	0							
	ENC	0							
PROC. REF: AMM 72-31-01, MM 72-21-20, MM 72-21-20, MM 72-21-20, MM 72-21-20	PROC. REF: AMM 72-31-01, MM 72-21-20, MM 72-21-20, MM 72-21-20, MM 72-21-20								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
722500-0101	NO. 1 ENGINE - BEVEL PINION - RADIAL DRIVE GEARSHAFT							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
722500-0101	NO. 2 ENGINE - BEVEL PINION - RADIAL DRIVE GEARSHAFT							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
722501-0101	NO. 1 ENGINE - FRONT SUMP BEVEL GEAR							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
722501-0101	NO. 2 ENGINE - FRONT SUMP BEVEL GEAR							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
722502-0101	NO. 1 ENGINE - FRONT SUMP HOUSING ASSEMBLY							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
722502-0101	NO. 2 ENGINE - FRONT SUMP HOUSING ASSEMBLY							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
722503-0101		NO. 1 ENGINE - MID-SPAN ROLLER BEARING						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-25-35, MM 72-25-35PROC. REF: MM 72-25-35, MM 72-25-35									
722503-0101		NO. 2 ENGINE - MID-SPAN ROLLER BEARING						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-25-35, MM 72-25-35PROC. REF: MM 72-25-35, MM 72-25-35									
722504-0101		NO. 1 ENGINE - HORIZONTAL QUILL SHAFT						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
722504-0101		NO. 2 ENGINE - HORIZONTAL QUILL SHAFT						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
722506-0101		NO. 1 ENGINE - NO. 4 CARBON-TANDEM SEAL ASSEMBLY						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
722506-0101		NO. 2 ENGINE - NO. 4 CARBON-TANDEM SEAL ASSEMBLY						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
722508-0101	NO. 1 ENGINE - 80 X 100 X 11 MM ROLLER BEARING							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
722508-0101	NO. 2 ENGINE - 80 X 100 X 11 MM ROLLER BEARING							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
722509-0101	NO. 1 ENGINE - 87 X 108 X 11 BALL BEARING							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
722509-0101	NO. 2 ENGINE - 87 X 108 X 11 BALL BEARING							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
722510-0101	NO. 1 ENGINE - FLANGED ROLLER BEARING							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
722510-0101	NO. 2 ENGINE - FLANGED ROLLER BEARING							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
722511-0101		NO. 1 ENGINE - ROLLER BEARING						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
722511-0101		NO. 2 ENGINE - ROLLER BEARING						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
722512-0101		NO. 1 ENGINE - RADIAL DRIVE GEARSHAFT ASSEMBLY						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
722512-0101		NO. 2 ENGINE - RADIAL DRIVE GEARSHAFT ASSEMBLY						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
722513-0101		NO. 1 ENGINE - CONRAD BEARING						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
722513-0101		NO. 2 ENGINE - CONRAD BEARING						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
722514-0101	NO. 1 ENGINE - NO. 1 POWER TURBINE (LPT) BALL BEARING							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
722514-0101	NO. 2 ENGINE - NO. 1 POWER TURBINE (LPT) BALL BEARING							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723000-0101	NO. 1 ENGINE - COMPRESSOR ROTOR ASSEMBLY							Component	ATA:72
PN:23075618	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:A21726	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723000-0101	NO. 2 ENGINE - COMPRESSOR ROTOR ASSEMBLY							Component	ATA:72
PN:23075618	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:A21727	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723017-0101	NO. 1 ENGINE - COMP/TURBINE SHAFT							Component	ATA:72
PN:23073165	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:L314125	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723017-0101	NO. 2 ENGINE - COMP/TURBINE SHAFT							Component	ATA:72
PN:23073165	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:L314133	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
723018-0101	NO. 1 ENGINE - COMPRESSOR STUB SHAFT							Component	ATA:72
PN:23077677	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:GV256851	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723018-0101	NO. 2 ENGINE - COMPRESSOR STUB SHAFT							Component	ATA:72
PN:23077677	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:GV256859	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723019-0101	NO. 1 ENGINE - COMPRESSOR TIE BOLT							Component	ATA:72
PN:23076018	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:L316484	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723019-0101	NO. 2 ENGINE - COMPRESSOR TIE BOLT							Component	ATA:72
PN:23076018	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:L316500	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723020-0101	NO. 1 ENGINE - 9TH STAGE COMPRESSOR CASE							Component	ATA:72
PN:23077726	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:JB42245	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723020-0101	NO. 2 ENGINE - 9TH STAGE COMPRESSOR CASE							Component	ATA:72
PN:23077726	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:JB42246	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
723500-0101		NO. 1 ENGINE - 1ST STAGE COMPRESSOR WHEEL							Component ATA:72
PN:23065041	MOS	25-Sep-07		TSN 0				LIFE LIMIT	
SN:L317342	HRS	0		TSN 0					
	ENC	0	20000	TSN 0	(20000) 20072		14047		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723500-0101		NO. 2 ENGINE - 1ST STAGE COMPRESSOR WHEEL							Component ATA:72
PN:23065041	MOS	25-Sep-07		TSN 0				LIFE LIMIT	
SN:L317309	HRS	0		TSN 0					
	ENC	0	20000	TSN 0	(20000) 20072		14047		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723500-0102		NO. 1 ENGINE - 2ND STAGE COMPRESSOR WHEEL							Component ATA:72
PN:23050752	MOS	25-Sep-07		TSN 0				LIFE LIMIT	
SN:L308271	HRS	0		TSN 0					
	ENC	0	15200	TSN 0	(15200) 15272		9247		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723500-0102		NO. 2 ENGINE - 2ND STAGE COMPRESSOR WHEEL							Component ATA:72
PN:23050752	MOS	25-Sep-07		TSN 0				LIFE LIMIT	
SN:L308272	HRS	0		TSN 0					
	ENC	0	15200	TSN 0	(15200) 15272		9247		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723500-0103		NO. 1 ENGINE - 3RD STAGE COMPRESSOR WHEEL							Component ATA:72
PN:23065303	MOS	25-Sep-07		TSN 0				LIFE LIMIT	
SN:L310095	HRS	0		TSN 0					
	ENC	0	13300	TSN 0	(13300) 13372		7347		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
723500-0103		NO. 2 ENGINE - 3RD STAGE COMPRESSOR WHEEL							Component ATA:72
PN:23065303	MOS	25-Sep-07		TSN 0				LIFE LIMIT	
SN:L310107	HRS	0		TSN 0					
	ENC	0	13300	TSN 0	(13300) 13372		7347		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723500-0104		NO. 1 ENGINE - 4TH STAGE COMPRESSOR WHEEL							Component ATA:72
PN:23071259	MOS	25-Sep-07		TSN 0				LIFE LIMIT	
SN:L296792	HRS	0		TSN 0					
	ENC	0	20000	TSN 0	(20000) 20072		14047		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723500-0104		NO. 2 ENGINE - 4TH STAGE COMPRESSOR WHEEL							Component ATA:72
PN:23071259	MOS	25-Sep-07		TSN 0				LIFE LIMIT	
SN:L296731	HRS	0		TSN 0					
	ENC	0	20000	TSN 0	(20000) 20072		14047		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723500-0105		NO. 1 ENGINE - 5TH STAGE COMPRESSOR WHEEL							Component ATA:72
PN:23071260	MOS	25-Sep-07		TSN 0				LIFE LIMIT	
SN:L312877	HRS	0		TSN 0					
	ENC	0	20000	TSN 0	(20000) 20072		14047		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723500-0105		NO. 2 ENGINE - 5TH STAGE COMPRESSOR WHEEL							Component ATA:72
PN:23071260	MOS	25-Sep-07		TSN 0				LIFE LIMIT	
SN:L312854	HRS	0		TSN 0					
	ENC	0	20000	TSN 0	(20000) 20072		14047		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
723500-0106		NO. 1 ENGINE - 6TH STAGE COMPRESSOR WHEEL							Component ATA:72
PN:23074717	MOS	25-Sep-07		TSN 0				LIFE LIMIT	
SN:L275159	HRS	0		TSN 0					
	ENC	0	20000	TSN 0	(20000) 20072		14047		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723500-0106		NO. 2 ENGINE - 6TH STAGE COMPRESSOR WHEEL							Component ATA:72
PN:23074717	MOS	25-Sep-07		TSN 0				LIFE LIMIT	
SN:L275144	HRS	0		TSN 0					
	ENC	0	20000	TSN 0	(20000) 20072		14047		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723500-0107		NO. 1 ENGINE - 7TH STAGE COMPRESSOR WHEEL							Component ATA:72
PN:23074217	MOS	25-Sep-07		TSN 0				LIFE LIMIT	
SN:L299189	HRS	0		TSN 0					
	ENC	0	20000	TSN 0	(20000) 20072		14047		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723500-0107		NO. 2 ENGINE - 7TH STAGE COMPRESSOR WHEEL							Component ATA:72
PN:23074217	MOS	25-Sep-07		TSN 0				LIFE LIMIT	
SN:L299210	HRS	0		TSN 0					
	ENC	0	20000	TSN 0	(20000) 20072		14047		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723500-0108		NO. 1 ENGINE - 8TH STAGE COMPRESSOR WHEEL							Component ATA:72
PN:23074721	MOS	25-Sep-07		TSN 0				LIFE LIMIT	
SN:L305178	HRS	0		TSN 0					
	ENC	0	20000	TSN 0	(20000) 20072		14047		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
723500-0108		NO. 2 ENGINE - 8TH STAGE COMPRESSOR WHEEL							Component ATA:72
PN:23074721	MOS	25-Sep-07		TSN 0				LIFE LIMIT	
SN:L305092	HRS	0		TSN 0					
	ENC	0	20000	TSN 0	(20000) 20072		14047		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723500-0109		NO. 1 ENGINE - 9TH STAGE COMPRESSOR WHEEL							Component ATA:72
PN:23074722	MOS	25-Sep-07		TSN 0				LIFE LIMIT	
SN:L310539	HRS	0		TSN 0					
	ENC	0	20000	TSN 0	(20000) 20072		14047		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723500-0109		NO. 2 ENGINE - 9TH STAGE COMPRESSOR WHEEL							Component ATA:72
PN:23074722	MOS	25-Sep-07		TSN 0				LIFE LIMIT	
SN:L310527	HRS	0		TSN 0					
	ENC	0	20000	TSN 0	(20000) 20072		14047		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723500-0110		NO. 1 ENGINE - 10TH STAGE COMPRESSOR WHEEL							Component ATA:72
PN:23074723	MOS	25-Sep-07		TSN 0				LIFE LIMIT	
SN:L309565	HRS	0		TSN 0					
	ENC	0	20000	TSN 0	(20000) 20072		14047		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723500-0110		NO. 2 ENGINE - 10TH STAGE COMPRESSOR WHEEL							Component ATA:72
PN:23074723	MOS	25-Sep-07		TSN 0				LIFE LIMIT	
SN:L309575	HRS	0		TSN 0					
	ENC	0	20000	TSN 0	(20000) 20072		14047		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
723500-0111		NO. 1 ENGINE - 11TH STAGE COMPRESSOR WHEEL							Component ATA:72
PN:23074724	MOS	25-Sep-07		TSN 0				LIFE LIMIT	
SN:L308976	HRS	0		TSN 0					
	ENC	0	20000	TSN 0	(20000) 20072		14047		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723500-0111		NO. 2 ENGINE - 11TH STAGE COMPRESSOR WHEEL							Component ATA:72
PN:23074724	MOS	25-Sep-07		TSN 0				LIFE LIMIT	
SN:L308972	HRS	0		TSN 0					
	ENC	0	20000	TSN 0	(20000) 20072		14047		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723500-0112		NO. 1 ENGINE - 12TH STAGE COMPRESSOR WHEEL							Component ATA:72
PN:23074725	MOS	25-Sep-07		TSN 0				LIFE LIMIT	
SN:L295437	HRS	0		TSN 0					
	ENC	0	20000	TSN 0	(20000) 20072		14047		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723500-0112		NO. 2 ENGINE - 12TH STAGE COMPRESSOR WHEEL							Component ATA:72
PN:23074725	MOS	25-Sep-07		TSN 0				LIFE LIMIT	
SN:L295434	HRS	0		TSN 0					
	ENC	0	20000	TSN 0	(20000) 20072		14047		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723500-0113		NO. 1 ENGINE - 13TH STAGE COMPRESSOR WHEEL							Component ATA:72
PN:23074213	MOS	25-Sep-07		TSN 0				LIFE LIMIT	
SN:L313172	HRS	0		TSN 0					
	ENC	0	20000	TSN 0	(20000) 20072		14047		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
723500-0113		NO. 2 ENGINE - 13TH STAGE COMPRESSOR WHEEL							Component ATA:72
PN:23074213	MOS	25-Sep-07		TSN 0				LIFE LIMIT	
SN:L313180	HRS	0		TSN 0					
	ENC	0	20000	TSN 0	(20000) 20072		14047		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723500-0114		NO. 1 ENGINE - 14TH STAGE COMPRESSOR WHEEL							Component ATA:72
PN:23074214	MOS	25-Sep-07		TSN 0				LIFE LIMIT	
SN:L308693	HRS	0		TSN 0					
	ENC	0	20000	TSN 0	(20000) 20072		14047		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723500-0114		NO. 2 ENGINE - 14TH STAGE COMPRESSOR WHEEL							Component ATA:72
PN:23074214	MOS	25-Sep-07		TSN 0				LIFE LIMIT	
SN:L308696	HRS	0		TSN 0					
	ENC	0	20000	TSN 0	(20000) 20072		14047		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723500-0120		NO. 1 ENGINE - COMPRESSOR SHAFT CONE ASSEMBLY							Component ATA:72
PN:23076016	MOS	25-Sep-07		TSN 0				LIFE LIMIT	
SN:L311723	HRS	0		TSN 0					
	ENC	0	20000	TSN 0	(20000) 20072		14047		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723500-0120		NO. 2 ENGINE - COMPRESSOR SHAFT CONE ASSEMBLY							Component ATA:72
PN:23076016	MOS	25-Sep-07		TSN 0				LIFE LIMIT	
SN:L311743	HRS	0		TSN 0					
	ENC	0	20000	TSN 0	(20000) 20072		14047		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
723700-0101		NO. 1 ENGINE - COMPRESSOR CASE ASSEMBLY						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723700-0101		NO. 2 ENGINE - COMPRESSOR CASE ASSEMBLY						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723705-0101		NO. 1 ENGINE - COMPRESSOR DIFFUSER						Component	ATA:72
PN:23079071	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:NY217133	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723705-0101		NO. 2 ENGINE - COMPRESSOR DIFFUSER						Component	ATA:72
PN:23079071	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:NY216909	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723707-0101		NO. 1 ENGINE - SPLIT BALL BEARING						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723707-0101		NO. 2 ENGINE - SPLIT BALL BEARING						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
723902-0101		NO. 1 ENGINE - NO. 6 CARBON CENTER SUMP SEAL ASSEMBLY						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723902-0101		NO. 2 ENGINE - NO. 6 CARBON CENTER SUMP SEAL ASSEMBLY						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723903-0101		NO. 1 ENGINE - NO. 5 CARBON CENTER SUMP SEAL ASSEMBLY						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723903-0101		NO. 2 ENGINE - NO. 5 CARBON CENTER SUMP SEAL ASSEMBLY						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723904-0101		NO. 1 ENGINE - CENTER SUMP HOUSING ASSEMBLY						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723904-0101		NO. 2 ENGINE - CENTER SUMP HOUSING ASSEMBLY						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
724500-0101	NO. 1 ENGINE - COMBUSTION LINER ASSEMBLY							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
724500-0101	NO. 2 ENGINE - COMBUSTION LINER ASSEMBLY							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725000-0101	NO. 1 ENGINE - HPT ROTOR ASSEMBLY							Component	ATA:72
PN:23074650	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:A72794	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725000-0101	NO. 2 ENGINE - HPT ROTOR ASSEMBLY							Component	ATA:72
PN:23074650	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:A72795	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725010-0101	NO. 1 ENGINE - ROTOR ASSY-LPT ROTOR ASSEMBLY							Component	ATA:72
PN:23074088	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:A82774	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725010-0101	NO. 2 ENGINE - ROTOR ASSY-LPT ROTOR ASSEMBLY							Component	ATA:72
PN:23074088	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:A82776	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
725181-0101	NO. 1 ENGINE - NO. 1 HP TURBINE 2ND STAGE VANE ASSEMBLY							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725181-0101	NO. 2 ENGINE - NO. 1 HP TURBINE 2ND STAGE VANE ASSEMBLY							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725181-0102	NO. 1 ENGINE - NO. 2 HP TURBINE 2ND STAGE VANE ASSEMBLY							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725181-0102	NO. 2 ENGINE - NO. 2 HP TURBINE 2ND STAGE VANE ASSEMBLY							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725181-0103	NO. 1 ENGINE - NO. 3 HP TURBINE 2ND STAGE VANE ASSEMBLY							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725181-0103	NO. 2 ENGINE - NO. 3 HP TURBINE 2ND STAGE VANE ASSEMBLY							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
725181-0104	NO. 1 ENGINE - NO. 4 HP TURBINE 2ND STAGE VANE ASSEMBLY							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725181-0104	NO. 2 ENGINE - NO. 4 HP TURBINE 2ND STAGE VANE ASSEMBLY							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725181-0105	NO. 1 ENGINE - NO. 5 HP TURBINE 2ND STAGE VANE ASSEMBLY							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725181-0105	NO. 2 ENGINE - NO. 5 HP TURBINE 2ND STAGE VANE ASSEMBLY							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725181-0106	NO. 1 ENGINE - NO. 6 HP TURBINE 2ND STAGE VANE ASSEMBLY							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725181-0106	NO. 2 ENGINE - NO. 6 HP TURBINE 2ND STAGE VANE ASSEMBLY							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
725181-0107		NO. 1 ENGINE - NO. 7 HP TURBINE 2ND STAGE VANE ASSEMBLY						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725181-0107		NO. 2 ENGINE - NO. 7 HP TURBINE 2ND STAGE VANE ASSEMBLY						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725181-0108		NO. 1 ENGINE - NO. 8 HP TURBINE 2ND STAGE VANE ASSEMBLY						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725181-0108		NO. 2 ENGINE - NO. 8 HP TURBINE 2ND STAGE VANE ASSEMBLY						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725181-0109		NO. 1 ENGINE - NO. 9 HP TURBINE 2ND STAGE VANE ASSEMBLY						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725181-0109		NO. 2 ENGINE - NO. 9 HP TURBINE 2ND STAGE VANE ASSEMBLY						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
725181-0110	NO. 1 ENGINE - NO. 10 HP TURBINE 2ND STAGE VANE ASSEMBLY							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725181-0110	NO. 2 ENGINE - NO. 10 HP TURBINE 2ND STAGE VANE ASSEMBLY							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725181-0111	NO. 1 ENGINE - NO. 11 HP TURBINE 2ND STAGE VANE ASSEMBLY							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725181-0111	NO. 2 ENGINE - NO. 11 HP TURBINE 2ND STAGE VANE ASSEMBLY							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725181-0112	NO. 1 ENGINE - NO. 12 HP TURBINE 2ND STAGE VANE ASSEMBLY							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725181-0112	NO. 2 ENGINE - NO. 12 HP TURBINE 2ND STAGE VANE ASSEMBLY							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
725181-0113	NO. 1 ENGINE - NO. 13 HP TURBINE 2ND STAGE VANE ASSEMBLY							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725181-0113	NO. 2 ENGINE - NO. 13 HP TURBINE 2ND STAGE VANE ASSEMBLY							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725181-0114	NO. 1 ENGINE - NO. 14 HP TURBINE 2ND STAGE VANE ASSEMBLY							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725181-0114	NO. 2 ENGINE - NO. 14 HP TURBINE 2ND STAGE VANE ASSEMBLY							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725181-0115	NO. 1 ENGINE - NO. 15 HP TURBINE 2ND STAGE VANE ASSEMBLY							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725181-0115	NO. 2 ENGINE - NO. 15 HP TURBINE 2ND STAGE VANE ASSEMBLY							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
725181-0116	NO. 1 ENGINE - NO. 16 HP TURBINE 2ND STAGE VANE ASSEMBLY							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725181-0116	NO. 2 ENGINE - NO. 16 HP TURBINE 2ND STAGE VANE ASSEMBLY							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725200-0101	NO. 1 ENGINE - 1ST STAGE GAS-GENERATOR TURBINE OR HP TURBINE WHEEL							Component	ATA:72
PN:23079946	MOS	25-Sep-07		TSN 0				LIFE LIMIT	
SN:MW51866	HRS	0		TSN 0					
	ENC	0	35000	TSN 0	(35000) 35072		29047		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725200-0101	NO. 2 ENGINE - 1ST STAGE GAS-GENERATOR TURBINE OR HP TURBINE WHEEL							Component	ATA:72
PN:23079946	MOS	25-Sep-07		TSN 0				LIFE LIMIT	
SN:MW51868	HRS	0		TSN 0					
	ENC	0	35000	TSN 0	(35000) 35072		29047		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725200-0102	NO. 1 ENGINE - 2ND STAGE GAS-GENERATOR-TURBINE OR HIGH-PRESSURE-TURBINE WHEEL							Component	ATA:72
PN:23084781	MOS	25-Sep-07		TSN 0				LIFE LIMIT	
SN:MW51939	HRS	0		TSN 0					
	ENC	0	20000	TSN 0	(20000) 20072		14047		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
725200-0102		NO. 2 ENGINE - 2ND STAGE GAS-GENERATOR-TURBINE OR HIGH-PRESSURE-TURBINE WHEEL							Component ATA:72
PN:23084781	MOS	25-Sep-07		TSN 0				LIFE LIMIT	
SN:MW51964	HRS	0		TSN 0					
	ENC	0	20000	TSN 0	(20000) 20072		14047		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725200-0105		NO. 1 ENGINE - 1ST TO 2ND STAGE TURBINE SPACER							Component ATA:72
PN:23076778	MOS	25-Sep-07		TSN 0				LIFE LIMIT	
SN:TW516137	HRS	0		TSN 0					
	ENC	0	30000	TSN 0	(30000) 30072		24047		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725200-0105		NO. 2 ENGINE - 1ST TO 2ND STAGE TURBINE SPACER							Component ATA:72
PN:23076778	MOS	25-Sep-07		TSN 0				LIFE LIMIT	
SN:TW516070	HRS	0		TSN 0					
	ENC	0	30000	TSN 0	(30000) 30072		24047		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725281-0101		NO. 1 ENGINE - STAGE 1 TURBINE WHEEL RING SEAL							Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725281-0101		NO. 2 ENGINE - STAGE 1 TURBINE WHEEL RING SEAL							Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0101		NO. 1 ENGINE - NO. 1 HP TURBINE 2ND STAGE BLADE							Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0101	NO. 2 ENGINE - NO. 1 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0102	NO. 1 ENGINE - NO. 2 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0102	NO. 2 ENGINE - NO. 2 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0103	NO. 1 ENGINE - NO. 3 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0103	NO. 2 ENGINE - NO. 3 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0104	NO. 1 ENGINE - NO. 4 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0104	NO. 2 ENGINE - NO. 4 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0105	NO. 1 ENGINE - NO. 5 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0105	NO. 2 ENGINE - NO. 5 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0106	NO. 1 ENGINE - NO. 6 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0106	NO. 2 ENGINE - NO. 6 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0107	NO. 1 ENGINE - NO. 7 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0107	NO. 2 ENGINE - NO. 7 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0108	NO. 1 ENGINE - NO. 8 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0108	NO. 2 ENGINE - NO. 8 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0109	NO. 1 ENGINE - NO. 9 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0109	NO. 2 ENGINE - NO. 9 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0110	NO. 1 ENGINE - NO. 10 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0110	NO. 2 ENGINE - NO. 10 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0111	NO. 1 ENGINE - NO. 11 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0111	NO. 2 ENGINE - NO. 11 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0112	NO. 1 ENGINE - NO. 12 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0112	NO. 2 ENGINE - NO. 12 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0113	NO. 1 ENGINE - NO. 13 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0113	NO. 2 ENGINE - NO. 13 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0114	NO. 1 ENGINE - NO. 14 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0114	NO. 2 ENGINE - NO. 14 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0115	NO. 1 ENGINE - NO. 15 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0115	NO. 2 ENGINE - NO. 15 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0116	NO. 1 ENGINE - NO. 16 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0116		NO. 2 ENGINE - NO. 16 HP TURBINE 2ND STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0117		NO. 1 ENGINE - NO. 17 HP TURBINE 2ND STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0117		NO. 2 ENGINE - NO. 17 HP TURBINE 2ND STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0118		NO. 1 ENGINE - NO. 18 HP TURBINE 2ND STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0118		NO. 2 ENGINE - NO. 18 HP TURBINE 2ND STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0119		NO. 1 ENGINE - NO. 19 HP TURBINE 2ND STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0119	NO. 2 ENGINE - NO. 19 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0120	NO. 1 ENGINE - NO. 20 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0120	NO. 2 ENGINE - NO. 20 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0121	NO. 1 ENGINE - NO. 21 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0121	NO. 2 ENGINE - NO. 21 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0122	NO. 1 ENGINE - NO. 22 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0122	NO. 2 ENGINE - NO. 22 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0123	NO. 1 ENGINE - NO. 23 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0123	NO. 2 ENGINE - NO. 23 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0124	NO. 1 ENGINE - NO. 24 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0124	NO. 2 ENGINE - NO. 24 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0125	NO. 1 ENGINE - NO. 25 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0125		NO. 2 ENGINE - NO. 25 HP TURBINE 2ND STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0126		NO. 1 ENGINE - NO. 26 HP TURBINE 2ND STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0126		NO. 2 ENGINE - NO. 26 HP TURBINE 2ND STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0127		NO. 1 ENGINE - NO. 27 HP TURBINE 2ND STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0127		NO. 2 ENGINE - NO. 27 HP TURBINE 2ND STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0128		NO. 1 ENGINE - NO. 28 HP TURBINE 2ND STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0128	NO. 2 ENGINE - NO. 28 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0129	NO. 1 ENGINE - NO. 29 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0129	NO. 2 ENGINE - NO. 29 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0130	NO. 1 ENGINE - NO. 30 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0130	NO. 2 ENGINE - NO. 30 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0131	NO. 1 ENGINE - NO. 31 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0131	NO. 2 ENGINE - NO. 31 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0132	NO. 1 ENGINE - NO. 32 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0132	NO. 2 ENGINE - NO. 32 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0133	NO. 1 ENGINE - NO. 33 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0133	NO. 2 ENGINE - NO. 33 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0134	NO. 1 ENGINE - NO. 34 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0134	NO. 2 ENGINE - NO. 34 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0135	NO. 1 ENGINE - NO. 35 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0135	NO. 2 ENGINE - NO. 35 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0136	NO. 1 ENGINE - NO. 36 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0136	NO. 2 ENGINE - NO. 36 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0137	NO. 1 ENGINE - NO. 37 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0137		NO. 2 ENGINE - NO. 37 HP TURBINE 2ND STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0138		NO. 1 ENGINE - NO. 38 HP TURBINE 2ND STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0138		NO. 2 ENGINE - NO. 38 HP TURBINE 2ND STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0139		NO. 1 ENGINE - NO. 39 HP TURBINE 2ND STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0139		NO. 2 ENGINE - NO. 39 HP TURBINE 2ND STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0140		NO. 1 ENGINE - NO. 40 HP TURBINE 2ND STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0140	NO. 2 ENGINE - NO. 40 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0141	NO. 1 ENGINE - NO. 41 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0141	NO. 2 ENGINE - NO. 41 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0142	NO. 1 ENGINE - NO. 42 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0142	NO. 2 ENGINE - NO. 42 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0143	NO. 1 ENGINE - NO. 43 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0143	NO. 2 ENGINE - NO. 43 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0144	NO. 1 ENGINE - NO. 44 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0144	NO. 2 ENGINE - NO. 44 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0145	NO. 1 ENGINE - NO. 45 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0145	NO. 2 ENGINE - NO. 45 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0146	NO. 1 ENGINE - NO. 46 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0146		NO. 2 ENGINE - NO. 46 HP TURBINE 2ND STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0147		NO. 1 ENGINE - NO. 47 HP TURBINE 2ND STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0147		NO. 2 ENGINE - NO. 47 HP TURBINE 2ND STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0148		NO. 1 ENGINE - NO. 48 HP TURBINE 2ND STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0148		NO. 2 ENGINE - NO. 48 HP TURBINE 2ND STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0149		NO. 1 ENGINE - NO. 49 HP TURBINE 2ND STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0149	NO. 2 ENGINE - NO. 49 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0150	NO. 1 ENGINE - NO. 50 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0150	NO. 2 ENGINE - NO. 50 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0151	NO. 1 ENGINE - NO. 51 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0151	NO. 2 ENGINE - NO. 51 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0152	NO. 1 ENGINE - NO. 52 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0152	NO. 2 ENGINE - NO. 52 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0153	NO. 1 ENGINE - NO. 53 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0153	NO. 2 ENGINE - NO. 53 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0154	NO. 1 ENGINE - NO. 54 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0154	NO. 2 ENGINE - NO. 54 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0155	NO. 1 ENGINE - NO. 55 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0155		NO. 2 ENGINE - NO. 55 HP TURBINE 2ND STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0156		NO. 1 ENGINE - NO. 56 HP TURBINE 2ND STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0156		NO. 2 ENGINE - NO. 56 HP TURBINE 2ND STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0157		NO. 1 ENGINE - NO. 57 HP TURBINE 2ND STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0157		NO. 2 ENGINE - NO. 57 HP TURBINE 2ND STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0158		NO. 1 ENGINE - NO. 58 HP TURBINE 2ND STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0158	NO. 2 ENGINE - NO. 58 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0159	NO. 1 ENGINE - NO. 59 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0159	NO. 2 ENGINE - NO. 59 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0160	NO. 1 ENGINE - NO. 60 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0160	NO. 2 ENGINE - NO. 60 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0161	NO. 1 ENGINE - NO. 61 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0161	NO. 2 ENGINE - NO. 61 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0162	NO. 1 ENGINE - NO. 62 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0162	NO. 2 ENGINE - NO. 62 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0163	NO. 1 ENGINE - NO. 63 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0163	NO. 2 ENGINE - NO. 63 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0164	NO. 1 ENGINE - NO. 64 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0164	NO. 2 ENGINE - NO. 64 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0165	NO. 1 ENGINE - NO. 65 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0165	NO. 2 ENGINE - NO. 65 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0166	NO. 1 ENGINE - NO. 66 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0166	NO. 2 ENGINE - NO. 66 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0167	NO. 1 ENGINE - NO. 67 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0167	NO. 2 ENGINE - NO. 67 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0168	NO. 1 ENGINE - NO. 68 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0168	NO. 2 ENGINE - NO. 68 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0169	NO. 1 ENGINE - NO. 69 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0169	NO. 2 ENGINE - NO. 69 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0170	NO. 1 ENGINE - NO. 70 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0170		NO. 2 ENGINE - NO. 70 HP TURBINE 2ND STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0171		NO. 1 ENGINE - NO. 71 HP TURBINE 2ND STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0171		NO. 2 ENGINE - NO. 71 HP TURBINE 2ND STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0172		NO. 1 ENGINE - NO. 72 HP TURBINE 2ND STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0172		NO. 2 ENGINE - NO. 72 HP TURBINE 2ND STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0173		NO. 1 ENGINE - NO. 73 HP TURBINE 2ND STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0173	NO. 2 ENGINE - NO. 73 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0174	NO. 1 ENGINE - NO. 74 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0174	NO. 2 ENGINE - NO. 74 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0175	NO. 1 ENGINE - NO. 75 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0175	NO. 2 ENGINE - NO. 75 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0176	NO. 1 ENGINE - NO. 76 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0176	NO. 2 ENGINE - NO. 76 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0201	NO. 1 ENGINE - HPT 2ND STAGE (BLADED) WHEEL ASSEMBLY							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725282-0201	NO. 2 ENGINE - HPT 2ND STAGE (BLADED) WHEEL ASSEMBLY							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725283-0101	NO. 1 ENGINE - STAGE 2 TURBINE BLADES							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725283-0101	NO. 2 ENGINE - STAGE 2 TURBINE BLADES							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0101	NO. 1 ENGINE - NO. 1 HP TURBINE 1ST STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0101	NO. 2 ENGINE - NO. 1 HP TURBINE 1ST STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0102	NO. 1 ENGINE - NO. 2 HP TURBINE 1ST STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0102	NO. 2 ENGINE - NO. 2 HP TURBINE 1ST STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0103	NO. 1 ENGINE - NO. 3 HP TURBINE 1ST STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0103	NO. 2 ENGINE - NO. 3 HP TURBINE 1ST STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0104	NO. 1 ENGINE - NO. 4 HP TURBINE 1ST STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0104	NO. 2 ENGINE - NO. 4 HP TURBINE 1ST STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0105	NO. 1 ENGINE - NO. 5 HP TURBINE 1ST STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0105	NO. 2 ENGINE - NO. 5 HP TURBINE 1ST STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0106	NO. 1 ENGINE - NO. 6 HP TURBINE 1ST STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0106	NO. 2 ENGINE - NO. 6 HP TURBINE 1ST STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0107	NO. 1 ENGINE - NO. 7 HP TURBINE 1ST STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0107		NO. 2 ENGINE - NO. 7 HP TURBINE 1ST STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0108		NO. 1 ENGINE - NO. 8 HP TURBINE 1ST STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0108		NO. 2 ENGINE - NO. 8 HP TURBINE 1ST STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0109		NO. 1 ENGINE - NO. 9 HP TURBINE 1ST STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0109		NO. 2 ENGINE - NO. 9 HP TURBINE 1ST STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0110		NO. 1 ENGINE - NO. 10 HP TURBINE 1ST STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0110		NO. 2 ENGINE - NO. 10 HP TURBINE 1ST STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0111		NO. 1 ENGINE - NO. 11 HP TURBINE 1ST STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0111		NO. 2 ENGINE - NO. 11 HP TURBINE 1ST STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0112		NO. 1 ENGINE - NO. 12 HP TURBINE 1ST STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0112		NO. 2 ENGINE - NO. 12 HP TURBINE 1ST STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0113		NO. 1 ENGINE - NO. 13 HP TURBINE 1ST STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0113	NO. 2 ENGINE - NO. 13 HP TURBINE 1ST STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0114	NO. 1 ENGINE - NO. 14 HP TURBINE 1ST STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0114	NO. 2 ENGINE - NO. 14 HP TURBINE 1ST STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0115	NO. 1 ENGINE - NO. 15 HP TURBINE 1ST STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0115	NO. 2 ENGINE - NO. 15 HP TURBINE 1ST STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0116	NO. 1 ENGINE - NO. 16 HP TURBINE 1ST STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0116		NO. 2 ENGINE - NO. 16 HP TURBINE 1ST STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0117		NO. 1 ENGINE - NO. 17 HP TURBINE 1ST STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0117		NO. 2 ENGINE - NO. 17 HP TURBINE 1ST STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0118		NO. 1 ENGINE - NO. 18 HP TURBINE 1ST STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0118		NO. 2 ENGINE - NO. 18 HP TURBINE 1ST STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0119		NO. 1 ENGINE - NO. 19 HP TURBINE 1ST STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0119	NO. 2 ENGINE - NO. 19 HP TURBINE 1ST STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0120	NO. 1 ENGINE - NO. 20 HP TURBINE 1ST STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0120	NO. 2 ENGINE - NO. 20 HP TURBINE 1ST STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0121	NO. 1 ENGINE - NO. 21 HP TURBINE 1ST STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0121	NO. 2 ENGINE - NO. 21 HP TURBINE 1ST STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0122	NO. 1 ENGINE - NO. 22 HP TURBINE 1ST STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0122	NO. 2 ENGINE - NO. 22 HP TURBINE 1ST STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0123	NO. 1 ENGINE - NO. 23 HP TURBINE 1ST STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0123	NO. 2 ENGINE - NO. 23 HP TURBINE 1ST STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0124	NO. 1 ENGINE - NO. 24 HP TURBINE 1ST STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0124	NO. 2 ENGINE - NO. 24 HP TURBINE 1ST STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0125	NO. 1 ENGINE - NO. 25 HP TURBINE 1ST STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0125		NO. 2 ENGINE - NO. 25 HP TURBINE 1ST STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0126		NO. 1 ENGINE - NO. 26 HP TURBINE 1ST STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0126		NO. 2 ENGINE - NO. 26 HP TURBINE 1ST STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0127		NO. 1 ENGINE - NO. 27 HP TURBINE 1ST STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0127		NO. 2 ENGINE - NO. 27 HP TURBINE 1ST STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0128		NO. 1 ENGINE - NO. 28 HP TURBINE 1ST STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0128		NO. 2 ENGINE - NO. 28 HP TURBINE 1ST STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0129		NO. 1 ENGINE - NO. 29 HP TURBINE 1ST STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0129		NO. 2 ENGINE - NO. 29 HP TURBINE 1ST STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0130		NO. 1 ENGINE - NO. 30 HP TURBINE 1ST STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0130		NO. 2 ENGINE - NO. 30 HP TURBINE 1ST STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0131		NO. 1 ENGINE - NO. 31 HP TURBINE 1ST STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0131	NO. 2 ENGINE - NO. 31 HP TURBINE 1ST STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0132	NO. 1 ENGINE - NO. 32 HP TURBINE 1ST STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0132	NO. 2 ENGINE - NO. 32 HP TURBINE 1ST STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0133	NO. 1 ENGINE - NO. 33 HP TURBINE 1ST STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0133	NO. 2 ENGINE - NO. 33 HP TURBINE 1ST STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0134	NO. 1 ENGINE - NO. 34 HP TURBINE 1ST STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0134	NO. 2 ENGINE - NO. 34 HP TURBINE 1ST STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0135	NO. 1 ENGINE - NO. 35 HP TURBINE 1ST STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0135	NO. 2 ENGINE - NO. 35 HP TURBINE 1ST STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0136	NO. 1 ENGINE - NO. 36 HP TURBINE 1ST STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0136	NO. 2 ENGINE - NO. 36 HP TURBINE 1ST STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0137	NO. 1 ENGINE - NO. 37 HP TURBINE 1ST STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0137	NO. 2 ENGINE - NO. 37 HP TURBINE 1ST STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0138	NO. 1 ENGINE - NO. 38 HP TURBINE 1ST STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0138	NO. 2 ENGINE - NO. 38 HP TURBINE 1ST STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0139	NO. 1 ENGINE - NO. 39 HP TURBINE 1ST STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0139	NO. 2 ENGINE - NO. 39 HP TURBINE 1ST STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0140	NO. 1 ENGINE - NO. 40 HP TURBINE 1ST STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0140		NO. 2 ENGINE - NO. 40 HP TURBINE 1ST STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0141		NO. 1 ENGINE - NO. 41 HP TURBINE 1ST STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0141		NO. 2 ENGINE - NO. 41 HP TURBINE 1ST STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0142		NO. 1 ENGINE - NO. 42 HP TURBINE 1ST STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0142		NO. 2 ENGINE - NO. 42 HP TURBINE 1ST STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0143		NO. 1 ENGINE - NO. 43 HP TURBINE 1ST STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0143	NO. 2 ENGINE - NO. 43 HP TURBINE 1ST STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0144	NO. 1 ENGINE - NO. 44 HP TURBINE 1ST STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0144	NO. 2 ENGINE - NO. 44 HP TURBINE 1ST STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0145	NO. 1 ENGINE - NO. 45 HP TURBINE 1ST STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0145	NO. 2 ENGINE - NO. 45 HP TURBINE 1ST STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0146	NO. 1 ENGINE - NO. 46 HP TURBINE 1ST STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0146	NO. 2 ENGINE - NO. 46 HP TURBINE 1ST STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0147	NO. 1 ENGINE - NO. 47 HP TURBINE 1ST STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0147	NO. 2 ENGINE - NO. 47 HP TURBINE 1ST STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0148	NO. 1 ENGINE - NO. 48 HP TURBINE 1ST STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0148	NO. 2 ENGINE - NO. 48 HP TURBINE 1ST STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0149	NO. 1 ENGINE - NO. 49 HP TURBINE 1ST STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0149	NO. 2 ENGINE - NO. 49 HP TURBINE 1ST STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0150	NO. 1 ENGINE - NO. 50 HP TURBINE 1ST STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0150	NO. 2 ENGINE - NO. 50 HP TURBINE 1ST STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0151	NO. 1 ENGINE - NO. 51 HP TURBINE 1ST STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0151	NO. 2 ENGINE - NO. 51 HP TURBINE 1ST STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0152	NO. 1 ENGINE - NO. 52 HP TURBINE 1ST STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0152		NO. 2 ENGINE - NO. 52 HP TURBINE 1ST STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0153		NO. 1 ENGINE - NO. 53 HP TURBINE 1ST STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0153		NO. 2 ENGINE - NO. 53 HP TURBINE 1ST STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0154		NO. 1 ENGINE - NO. 54 HP TURBINE 1ST STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0154		NO. 2 ENGINE - NO. 54 HP TURBINE 1ST STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0155		NO. 1 ENGINE - NO. 55 HP TURBINE 1ST STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0155		NO. 2 ENGINE - NO. 55 HP TURBINE 1ST STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0156		NO. 1 ENGINE - NO. 56 HP TURBINE 1ST STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0156		NO. 2 ENGINE - NO. 56 HP TURBINE 1ST STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0157		NO. 1 ENGINE - NO. 57 HP TURBINE 1ST STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0157		NO. 2 ENGINE - NO. 57 HP TURBINE 1ST STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0158		NO. 1 ENGINE - NO. 58 HP TURBINE 1ST STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0158	NO. 2 ENGINE - NO. 58 HP TURBINE 1ST STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0201	NO. 1 ENGINE - HPT 1ST STAGE (BLADED) WHEEL ASSEMBLY							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725284-0201	NO. 2 ENGINE - HPT 1ST STAGE (BLADED) WHEEL ASSEMBLY							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725285-0101	NO. 1 ENGINE - 1ST STAGE HPT BLADES							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725285-0101	NO. 2 ENGINE - 1ST STAGE HPT BLADES							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725289-0101	NO. 1 ENGINE - AIR DISTRIBUTION RING							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725289-0101		NO. 2 ENGINE - AIR DISTRIBUTION RING						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725700-0101		NO. 1 ENGINE - LPT TURBINE ASSEMBLY						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725700-0101		NO. 2 ENGINE - LPT TURBINE ASSEMBLY						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725702-0101		NO. 1 ENGINE - LPT CASE ASSEMBLY						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725702-0101		NO. 2 ENGINE - LPT CASE ASSEMBLY						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725703-0101		NO. 1 ENGINE - LP TURBINE STAGE 1 VANE RING						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725703-0101	NO. 2 ENGINE - LP TURBINE STAGE 1 VANE RING							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725707-0101	NO. 1 ENGINE - INTERSHAFT CARBON SEAL							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725707-0101	NO. 2 ENGINE - INTERSHAFT CARBON SEAL							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725800-0101	NO. 1 ENGINE - 1ST STAGE LOW PRESSURE TURBINE WHEEL							Component	ATA:72
PN:23076801	MOS	25-Sep-07		TSN 0				LIFE LIMIT	
SN:MW49192	HRS	0		TSN 0					
	ENC	0	35000	TSN 0	(35000) 35072		29047		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725800-0101	NO. 2 ENGINE - 1ST STAGE LOW PRESSURE TURBINE WHEEL							Component	ATA:72
PN:23076801	MOS	25-Sep-07		TSN 0				LIFE LIMIT	
SN:MW49120	HRS	0		TSN 0					
	ENC	0	35000	TSN 0	(35000) 35072		29047		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
725800-0102		NO. 1 ENGINE - 2ND STAGE LOW PRESSURE TURBINE WHEEL							Component ATA:72
PN:23079220	MOS	25-Sep-07		TSN 0				LIFE LIMIT	
SN:MW48763	HRS	0		TSN 0					
	ENC	0	35000	TSN 0	(35000) 35072		29047		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725800-0102		NO. 2 ENGINE - 2ND STAGE LOW PRESSURE TURBINE WHEEL							Component ATA:72
PN:23079220	MOS	25-Sep-07		TSN 0				LIFE LIMIT	
SN:MW48782	HRS	0		TSN 0					
	ENC	0	35000	TSN 0	(35000) 35072		29047		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725800-0103		NO. 1 ENGINE - 3RD STAGE LOW PRESSURE TURBINE WHEEL							Component ATA:72
PN:23079224	MOS	25-Sep-07		TSN 0				LIFE LIMIT	
SN:MW48959	HRS	0		TSN 0					
	ENC	0	35000	TSN 0	(35000) 35072		29047		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725800-0103		NO. 2 ENGINE - 3RD STAGE LOW PRESSURE TURBINE WHEEL							Component ATA:72
PN:23079224	MOS	25-Sep-07		TSN 0				LIFE LIMIT	
SN:MW48958	HRS	0		TSN 0					
	ENC	0	35000	TSN 0	(35000) 35072		29047		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725800-0104		NO. 1 ENGINE - LOW PRESSURE TURBINE INTERSTAGE AFT SPACER							Component ATA:72
PN:23054049	MOS	25-Sep-07		TSN 0				LIFE LIMIT	
SN:TW516290	HRS	0		TSN 0					
	ENC	0	35000	TSN 0	(35000) 35072		29047		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
725800-0104		NO. 2 ENGINE - LOW PRESSURE TURBINE INTERSTAGE AFT SPACER						Component	ATA:72
PN:23054049	MOS	25-Sep-07		TSN 0				LIFE LIMIT	
SN:TW516291	HRS	0		TSN 0					
	ENC	0	35000	TSN 0	(35000) 35072		29047		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725800-0105		NO. 1 ENGINE - LOW PRESSURE TURBINE INTERSTAGE FORWARD SPACER						Component	ATA:72
PN:23054049	MOS	25-Sep-07		TSN 0				LIFE LIMIT	
SN:TW514752	HRS	0		TSN 0					
	ENC	0	35000	TSN 0	(35000) 35072		29047		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725800-0105		NO. 2 ENGINE - LOW PRESSURE TURBINE INTERSTAGE FORWARD SPACER						Component	ATA:72
PN:23054049	MOS	25-Sep-07		TSN 0				LIFE LIMIT	
SN:TW516323	HRS	0		TSN 0					
	ENC	0	35000	TSN 0	(35000) 35072		29047		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725800-0106		NO. 1 ENGINE - LP TURBINE ROTOR LOW PRESSURE TURBINE FORWARD SHAFT						Component	ATA:72
PN:23074538	MOS	25-Sep-07		TSN 0				LIFE LIMIT	
SN:GV253002	HRS	0		TSN 0					
	ENC	0	35000	TSN 0	(35000) 35072		29047		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725800-0106		NO. 2 ENGINE - LP TURBINE ROTOR LOW PRESSURE TURBINE FORWARD SHAFT						Component	ATA:72
PN:23074538	MOS	25-Sep-07		TSN 0				LIFE LIMIT	
SN:GV257987	HRS	0		TSN 0					
	ENC	0	35000	TSN 0	(35000) 35072		29047		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
725800-0201	NO. 1 ENGINE - BALL BEARING							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725800-0201	NO. 2 ENGINE - BALL BEARING							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725802-0101	NO. 1 ENGINE - REAR LPT SHAFT							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725802-0101	NO. 2 ENGINE - REAR LPT SHAFT							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725883-0101	NO. 1 ENGINE - LPT-1 ROTATING SEAL							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725883-0101	NO. 2 ENGINE - LPT-1 ROTATING SEAL							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
725884-0101	NO. 1 ENGINE - LPT WHEEL ASSEMBLY							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725884-0101	NO. 2 ENGINE - LPT WHEEL ASSEMBLY							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725885-0101	NO. 1 ENGINE - LPT (BLADED) WHEEL ASSEMBLY							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725885-0101	NO. 2 ENGINE - LPT (BLADED) WHEEL ASSEMBLY							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725886-0101	NO. 1 ENGINE - LPT STAGE 1 (BLADED) WHEEL ASSEMBLY							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725886-0101	NO. 2 ENGINE - LPT STAGE 1 (BLADED) WHEEL ASSEMBLY							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
725900-0101		NO. 1 ENGINE - NO. 7 CARBON SEAL ASSEMBLY						Component	ATA:72
PN:23061737	MOS/MSC	01-Sep-17	O/C						
SN:NSN	HRS	8179.9							
	ENC	4374							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725900-0101		NO. 2 ENGINE - NO. 7 CARBON SEAL ASSEMBLY						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725910-0101		NO. 1 ENGINE - ROLLER BEARING						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725910-0101		NO. 2 ENGINE - ROLLER BEARING						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
726303-0101		NO. 1 ENGINE - RADIAL DRIVE QUILL SHAFT						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
726303-0101		NO. 2 ENGINE - RADIAL DRIVE QUILL SHAFT						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
727100-0101	NO. 1 ENGINE - RIGHT COMPRESSOR INNER DUCT ASSEMBLY							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-71-10, MM 72-71-10, MM 72-71-10, MM 72-71-10, MM 72-71-10, MM 72-71-10PROC. REF: MM 72-71-10, MM 72-71-10, MM 72-71-10, MM 72-71-10, MM 72-71-10, MM 72-71-10									
727100-0101	NO. 2 ENGINE - RIGHT COMPRESSOR INNER DUCT ASSEMBLY							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-71-10, MM 72-71-10, MM 72-71-10, MM 72-71-10, MM 72-71-10, MM 72-71-10PROC. REF: MM 72-71-10, MM 72-71-10, MM 72-71-10, MM 72-71-10, MM 72-71-10, MM 72-71-10									
727101-0101	NO. 1 ENGINE - LEFT COMPRESSOR INNER DUCT ASSEMBLY							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-71-10, MM 72-71-10, MM 72-71-10, MM 72-71-10, MM 72-71-10, MM 72-71-10PROC. REF: MM 72-71-10, MM 72-71-10, MM 72-71-10, MM 72-71-10, MM 72-71-10, MM 72-71-10									
727101-0101	NO. 2 ENGINE - LEFT COMPRESSOR INNER DUCT ASSEMBLY							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-71-10, MM 72-71-10, MM 72-71-10, MM 72-71-10, MM 72-71-10, MM 72-71-10PROC. REF: MM 72-71-10, MM 72-71-10, MM 72-71-10, MM 72-71-10, MM 72-71-10, MM 72-71-10									
727102-0101	NO. 1 ENGINE - LOWER COMPRESSOR INNER DUCT ASSEMBLY							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-71-10, MM 72-71-10, MM 72-71-10, MM 72-71-10, MM 72-71-10, MM 72-71-10PROC. REF: MM 72-71-10, MM 72-71-10, MM 72-71-10, MM 72-71-10, MM 72-71-10, MM 72-71-10									
727102-0101	NO. 2 ENGINE - LOWER COMPRESSOR INNER DUCT ASSEMBLY							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-71-10, MM 72-71-10, MM 72-71-10, MM 72-71-10, MM 72-71-10, MM 72-71-10PROC. REF: MM 72-71-10, MM 72-71-10, MM 72-71-10, MM 72-71-10, MM 72-71-10, MM 72-71-10									

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
727300-0101	NO. 1 ENGINE - OUTER BYPASS DUCT ASSEMBLY								Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
727300-0101	NO. 2 ENGINE - OUTER BYPASS DUCT ASSEMBLY								Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
727302-0101	NO. 1 ENGINE - BYPASS SUPPORT ASSEMBLY								Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-73-09, MM 72-73-09PROC. REF: MM 72-73-09, MM 72-73-09									
727302-0101	NO. 2 ENGINE - BYPASS SUPPORT ASSEMBLY								Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 72-73-09, MM 72-73-09PROC. REF: MM 72-73-09, MM 72-73-09									
ATA 73 - ENGINE FUEL AND CONTROL									
73-11-00-960-001-A00	NO. 1 ENGINE - DISCARD OF ENGINE FUEL FILTER ELEMENT								Service ATA:73
	MOS	13-Apr-22						SYSTEM	
	HRS	9739.4	2000 (+20/-20)		(11739.4) 11843.6	11759.4	567.3 (+20)		
	ENC	5173							
PROC. REF: GENERIC NO REF, AMM 73-11-01, AMM 73-11-00PROC. REF: GENERIC NO REF, AMM 73-11-01, AMM 73-11-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 73 - ENGINE FUEL AND CONTROL									
73-11-00-960-001-A00	NO. 2 ENGINE - DISCARD OF ENGINE FUEL FILTER ELEMENT							Service	ATA:73
	MOS	13-Apr-22						SYSTEM	
	HRS	9739.4	2000 (+20/-20)		(11739.4) 11843.6	11759.4	567.3 (+20)		
	ENC	5173							
PROC. REF: GENERIC NO REF, AMM 73-11-01, AMM 73-11-00PROC. REF: GENERIC NO REF, AMM 73-11-01, AMM 73-11-00									
73-11-10-130-001-A00	NO. 1 ENGINE - RESTORE (CLEANING) FUEL NOZZLES EXCEPT P/N 23075904, 23077006, 23087207, OR 23090046							Service	ATA:73
PN:23087207	MOS/MSC		N/A						
SN:UNKNOWN	HRS								
	ENC								
PROC. REF: AMM 73-11-10, MM 73-11-10, MM 73-11-10PROC. REF: AMM 73-11-10, MM 73-11-10, MM 73-11-10									
73-11-10-130-001-A00	NO. 2 ENGINE - RESTORE (CLEANING) FUEL NOZZLES EXCEPT P/N 23075904, 23077006, 23087207, OR 23090046							Service	ATA:73
PN:23087207	MOS/MSC		N/A						
SN:UNKNOWN	HRS								
	ENC								
PROC. REF: AMM 73-11-10, MM 73-11-10, MM 73-11-10PROC. REF: AMM 73-11-10, MM 73-11-10, MM 73-11-10									
73-11-10-130-001-A01	NO. 1 ENGINE - RESTORE (CLEANING) FUEL NOZZLES P/N 23075904, 23077006, 23087207, OR 23090046 ONLY							Service	ATA:73
PN:23087207	MOS	14-Jul-22						SYSTEM	
SN:UNKNOWN	HRS	9811.6	10000		(19811.6) 19915.8		8639.5		
	ENC	5199							
PROC. REF: AMM 73-11-10, MM 73-11-10, MM 73-11-10PROC. REF: AMM 73-11-10, MM 73-11-10, MM 73-11-10									
73-11-10-130-001-A01	NO. 2 ENGINE - RESTORE (CLEANING) FUEL NOZZLES P/N 23075904, 23077006, 23087207, OR 23090046 ONLY							Service	ATA:73
PN:23087207	MOS	14-Jul-22						SYSTEM	
SN:UNKNOWN	HRS	9811.6	10000		(19811.6) 19915.8		8639.5		
	ENC	5199							
PROC. REF: AMM 73-11-10, MM 73-11-10, MM 73-11-10PROC. REF: AMM 73-11-10, MM 73-11-10, MM 73-11-10									

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 73 - ENGINE FUEL AND CONTROL									
73-21-00-211-001-A00	NO. 1 ENGINE - VISUALLY CHECK FUEL PUMP AND METERING UNIT FOR FUEL LEAKAGE								Service ATA:73
	MOS	16-Feb-26						SYSTEM	
	HRS	10959.9	1000		(11959.9) 12064.1		787.8		
	ENC	5840							
PROC. REF: AMM 73-21-00, MM 72-00-00PROC. REF: AMM 73-21-00, MM 72-00-00									
73-21-00-211-001-A00	NO. 2 ENGINE - VISUALLY CHECK FUEL PUMP AND METERING UNIT FOR FUEL LEAKAGE								Service ATA:73
	MOS	16-Feb-26						SYSTEM	
	HRS	10959.9	1000		(11959.9) 12064.1		787.8		
	ENC	5840							
PROC. REF: AMM 73-21-00, MM 72-00-00PROC. REF: AMM 73-21-00, MM 72-00-00									
73-21-06-720-001-A00	NO. 1 ENGINE - FUNCTIONALLY CHECK FUEL FILTER IMPENDING BYPASS INDICATOR SYSTEM								Service ATA:73
	MOS	18-Aug-18						SYSTEM	
	HRS	8620.9	3000		(11620.9) 11725.1		448.8		
	ENC	4609							
PROC. REF: AMM 73-21-06, MM 73-37-10PROC. REF: AMM 73-21-06, MM 73-37-10									
73-21-06-720-001-A00	NO. 2 ENGINE - FUNCTIONALLY CHECK FUEL FILTER IMPENDING BYPASS INDICATOR SYSTEM								Service ATA:73
	MOS	18-Aug-18						SYSTEM	
	HRS	8620.9	3000		(11620.9) 11725.1		448.8		
	ENC	4609							
PROC. REF: AMM 73-21-06, MM 73-37-10PROC. REF: AMM 73-21-06, MM 73-37-10									
73-22-01-720-003-A00	FUNCTIONALLY CHECK MULTIFUNCTION DISPLAY FOR ENG1(2) LT FAULT AND ENG1(2) SCHED MAINT REPAIR MAINTENANCE MESSAGES								Service ATA:73
	MOS	09-Apr-26	12		09-Apr-27		318 d		
	HRS	11166.4	250	Adj -2.5	11413.9		137.6		
	AFL	5961							
PROC. REF: AMM 73-22-01PROC. REF: AMM 73-22-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 73 - ENGINE FUEL AND CONTROL									
73-30-04-220-001-A00	NO. 1 ENGINE - INSPECT (DETAILED INSPECTION) THE FADEC ANTI- VIBRATION MOUNTS							Service	ATA:73
	MOS	17-Jan-17							
	HRS	7935.4	5000		(12935.4) 13039.6		1763.3		
	ENC	4242							
PROC. REF: AMM 73-30-04, MM 73-25-10, MM 73-25-10, MM 73-25-10PROC. REF: AMM 73-30-04, MM 73-25-10, MM 73-25-10, MM 73-25-10									
73-30-04-220-001-A00	NO. 2 ENGINE - INSPECT (DETAILED INSPECTION) THE FADEC ANTI- VIBRATION MOUNTS							Service	ATA:73
	MOS	17-Jan-17							
	HRS	7935.4	5000		(12935.4) 13039.6		1763.3		
	ENC	4242							
PROC. REF: AMM 73-30-04, MM 73-25-10, MM 73-25-10, MM 73-25-10PROC. REF: AMM 73-30-04, MM 73-25-10, MM 73-25-10, MM 73-25-10									
731101-0101	NO. 1 ENGINE - NO. 1 FUEL NOZZLE ASSEMBLY							Component	ATA:73
PN:23087207	MOS/MSC	14-Jul-22	O/C	TSO 0					
SN:VN1BCK0522	HRS	9811.6		TSO 0					
	ENC	5199		TSO 0					
PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10									
731101-0101	NO. 2 ENGINE - NO. 1 FUEL NOZZLE ASSEMBLY							Component	ATA:73
PN:23087207	MOS/MSC	14-Jul-22	O/C	TSO 0					
SN:VN1BCE0573	HRS	9811.6		TSO 0					
	ENC	5199		TSO 0					
PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10									
731101-0102	NO. 1 ENGINE - NO. 2 FUEL NOZZLE ASSEMBLY							Component	ATA:73
PN:23087207	MOS/MSC	14-Jul-22	O/C	TSO 0					
SN:VN1BCK0523	HRS	9811.6		TSO 0					
	ENC	5199		TSO 0					
PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10									
731101-0102	NO. 2 ENGINE - NO. 2 FUEL NOZZLE ASSEMBLY							Component	ATA:73
PN:23087207	MOS/MSC	14-Jul-22	O/C	TSO 0					
SN:VN1BCE0574	HRS	9811.6		TSO 0					
	ENC	5199		TSO 0					
PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 73 - ENGINE FUEL AND CONTROL									
731101-0103	NO. 1 ENGINE - NO. 3 FUEL NOZZLE ASSEMBLY							Component	ATA:73
PN:23087207	MOS/MSC	14-Jul-22	O/C	TSO 0					
SN:VN1BCK0524	HRS	9811.6		TSO 0					
	ENC	5199		TSO 0					
PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10									
731101-0103	NO. 2 ENGINE - NO. 3 FUEL NOZZLE ASSEMBLY							Component	ATA:73
PN:23087207	MOS/MSC	14-Jul-22	O/C	TSO 0					
SN:VN1BCE0575	HRS	9811.6		TSO 0					
	ENC	5199		TSO 0					
PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10									
731101-0104	NO. 1 ENGINE - NO. 4 FUEL NOZZLE ASSEMBLY							Component	ATA:73
PN:23087207	MOS/MSC	14-Jul-22	O/C	TSO 0					
SN:VN1BCK0529	HRS	9811.6		TSO 0					
	ENC	5199		TSO 0					
PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10									
731101-0104	NO. 2 ENGINE - NO. 4 FUEL NOZZLE ASSEMBLY							Component	ATA:73
PN:23087207	MOS/MSC	14-Jul-22	O/C	TSO 0					
SN:VN1BCE0581	HRS	9811.6		TSO 0					
	ENC	5199		TSO 0					
PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10									
731101-0105	NO. 1 ENGINE - NO. 5 FUEL NOZZLE ASSEMBLY							Component	ATA:73
PN:23087207	MOS/MSC	14-Jul-22	O/C	TSO 0					
SN:VN1BCK0765	HRS	9811.6		TSO 0					
	ENC	5199		TSO 0					
PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10									
731101-0105	NO. 2 ENGINE - NO. 5 FUEL NOZZLE ASSEMBLY							Component	ATA:73
PN:23087207	MOS/MSC	14-Jul-22	O/C	TSO 0					
SN:VN1BCE0584	HRS	9811.6		TSO 0					
	ENC	5199		TSO 0					
PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 73 - ENGINE FUEL AND CONTROL									
731101-0106	NO. 1 ENGINE - NO. 6 FUEL NOZZLE ASSEMBLY							Component	ATA:73
PN:23087207	MOS/MSC	14-Jul-22	O/C	TSO 0					
SN:VN1BCK0768	HRS	9811.6		TSO 0					
	ENC	5199		TSO 0					
PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10	PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10								
731101-0106	NO. 2 ENGINE - NO. 6 FUEL NOZZLE ASSEMBLY							Component	ATA:73
PN:23087207	MOS/MSC	14-Jul-22	O/C	TSO 0					
SN:VN1BCD1026	HRS	9811.6		TSO 0					
	ENC	5199		TSO 0					
PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10	PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10								
731101-0107	NO. 1 ENGINE - NO. 7 FUEL NOZZLE ASSEMBLY							Component	ATA:73
PN:23087207	MOS/MSC	14-Jul-22	O/C	TSO 0					
SN:VN1BCK0769	HRS	9811.6		TSO 0					
	ENC	5199		TSO 0					
PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10	PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10								
731101-0107	NO. 2 ENGINE - NO. 7 FUEL NOZZLE ASSEMBLY							Component	ATA:73
PN:23087207	MOS/MSC	14-Jul-22	O/C	TSO 0					
SN:VN1BCD1027	HRS	9811.6		TSO 0					
	ENC	5199		TSO 0					
PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10	PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10								
731101-0108	NO. 1 ENGINE - NO. 8 FUEL NOZZLE ASSEMBLY							Component	ATA:73
PN:23087207	MOS/MSC	14-Jul-22	O/C	TSO 0					
SN:VN1BCK0770	HRS	9811.6		TSO 0					
	ENC	5199		TSO 0					
PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10	PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10								
731101-0108	NO. 2 ENGINE - NO. 8 FUEL NOZZLE ASSEMBLY							Component	ATA:73
PN:23087207	MOS/MSC	14-Jul-22	O/C	TSO 0					
SN:VN1BCD1028	HRS	9811.6		TSO 0					
	ENC	5199		TSO 0					
PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10	PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10								

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 73 - ENGINE FUEL AND CONTROL									
731101-0109	NO. 1 ENGINE - NO. 9 FUEL NOZZLE ASSEMBLY							Component	ATA:73
PN:23087207	MOS/MSC	14-Jul-22	O/C	TSO 0					
SN:VN1BCK0771	HRS	9811.6		TSO 0					
	ENC	5199		TSO 0					
PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10	PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10								
731101-0109	NO. 2 ENGINE - NO. 9 FUEL NOZZLE ASSEMBLY							Component	ATA:73
PN:23087207	MOS/MSC	14-Jul-22	O/C	TSO 0					
SN:VN1BCD1029	HRS	9811.6		TSO 0					
	ENC	5199		TSO 0					
PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10	PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10								
731101-0110	NO. 1 ENGINE - NO. 10 FUEL NOZZLE ASSEMBLY							Component	ATA:73
PN:23087207	MOS/MSC	14-Jul-22	O/C	TSO 0					
SN:VN1BCK0777	HRS	9811.6		TSO 0					
	ENC	5199		TSO 0					
PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10	PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10								
731101-0110	NO. 2 ENGINE - NO. 10 FUEL NOZZLE ASSEMBLY							Component	ATA:73
PN:23087207	MOS/MSC	14-Jul-22	O/C	TSO 0					
SN:VN1BCD1032	HRS	9811.6		TSO 0					
	ENC	5199		TSO 0					
PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10	PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10								
731101-0111	NO. 1 ENGINE - NO. 11 FUEL NOZZLE ASSEMBLY							Component	ATA:73
PN:23087207	MOS/MSC	14-Jul-22	O/C	TSO 0					
SN:VN1BCK0779	HRS	9811.6		TSO 0					
	ENC	5199		TSO 0					
PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10	PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10								
731101-0111	NO. 2 ENGINE - NO. 11 FUEL NOZZLE ASSEMBLY							Component	ATA:73
PN:23087207	MOS/MSC	14-Jul-22	O/C	TSO 0					
SN:VN1BCD1033	HRS	9811.6		TSO 0					
	ENC	5199		TSO 0					
PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10	PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 73 - ENGINE FUEL AND CONTROL									
731101-0112	NO. 1 ENGINE - NO. 12 FUEL NOZZLE ASSEMBLY							Component	ATA:73
PN:23087207	MOS/MSC	14-Jul-22	O/C	TSO 0					
SN:VN1BCK0780	HRS	9811.6		TSO 0					
	ENC	5199		TSO 0					
PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10	PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10								
731101-0112	NO. 2 ENGINE - NO. 12 FUEL NOZZLE ASSEMBLY							Component	ATA:73
PN:23087207	MOS/MSC	14-Jul-22	O/C	TSO 0					
SN:VN1BCD1035	HRS	9811.6		TSO 0					
	ENC	5199		TSO 0					
PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10	PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10								
731101-0113	NO. 1 ENGINE - NO. 13 FUEL NOZZLE ASSEMBLY							Component	ATA:73
PN:23087207	MOS/MSC	14-Jul-22	O/C	TSO 0					
SN:VN1BCK0781	HRS	9811.6		TSO 0					
	ENC	5199		TSO 0					
PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10	PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10								
731101-0113	NO. 2 ENGINE - NO. 13 FUEL NOZZLE ASSEMBLY							Component	ATA:73
PN:23087207	MOS/MSC	14-Jul-22	O/C	TSO 0					
SN:VN1BCD1036	HRS	9811.6		TSO 0					
	ENC	5199		TSO 0					
PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10	PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10								
731101-0114	NO. 1 ENGINE - NO. 14 FUEL NOZZLE ASSEMBLY							Component	ATA:73
PN:23087207	MOS/MSC	14-Jul-22	O/C	TSO 0					
SN:VN1BCK0782	HRS	9811.6		TSO 0					
	ENC	5199		TSO 0					
PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10	PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10								
731101-0114	NO. 2 ENGINE - NO. 14 FUEL NOZZLE ASSEMBLY							Component	ATA:73
PN:23087207	MOS/MSC	14-Jul-22	O/C	TSO 0					
SN:VN1BCD1037	HRS	9811.6		TSO 0					
	ENC	5199		TSO 0					
PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10	PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 73 - ENGINE FUEL AND CONTROL									
731101-0115	NO. 1 ENGINE - NO. 15 FUEL NOZZLE ASSEMBLY							Component	ATA:73
PN:23087207	MOS/MSC	14-Jul-22	O/C	TSO 0					
SN:VN1BCK0783	HRS	9811.6		TSO 0					
	ENC	5199		TSO 0					
PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10	PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10								
731101-0115	NO. 2 ENGINE - NO. 15 FUEL NOZZLE ASSEMBLY							Component	ATA:73
PN:23087207	MOS/MSC	14-Jul-22	O/C	TSO 0					
SN:VN1BCD1042	HRS	9811.6		TSO 0					
	ENC	5199		TSO 0					
PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10	PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10								
731101-0116	NO. 1 ENGINE - NO. 16 FUEL NOZZLE ASSEMBLY							Component	ATA:73
PN:23087207	MOS/MSC	14-Jul-22	O/C	TSO 0					
SN:VN1BCK0784	HRS	9811.6		TSO 0					
	ENC	5199		TSO 0					
PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10	PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10								
731101-0116	NO. 2 ENGINE - NO. 16 FUEL NOZZLE ASSEMBLY							Component	ATA:73
PN:23087207	MOS/MSC	14-Jul-22	O/C	TSO 0					
SN:VN1BCD1043	HRS	9811.6		TSO 0					
	ENC	5199		TSO 0					
PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10	PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10								
731101-0201	NO. 1 ENGINE - FUEL NOZZLE ASSEMBLY							Component	ATA:73
PN:23087207	MOS/MSC	14-Jul-22	O/C						
SN:UNKNOWN	HRS	9811.6							
	ENC	5199							
PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10	PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10								
731101-0201	NO. 2 ENGINE - FUEL NOZZLE ASSEMBLY							Component	ATA:73
PN:23087207	MOS/MSC	14-Jul-22	O/C						
SN:UNKNOWN	HRS	9811.6							
	ENC	5199							
PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10	PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 73 - ENGINE FUEL AND CONTROL									
732101-0101	NO. 1 ENGINE - METERING UNIT AND FUEL PUMP							Component	ATA:73
PN:23077658	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:SCP06-034	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 73-21-01, MM 73-21-10, MM 73-21-10PROC. REF: AMM 73-21-01, MM 73-21-10, MM 73-21-10									
732101-0101	NO. 2 ENGINE - METERING UNIT AND FUEL PUMP							Component	ATA:73
PN:23077658	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:SCP07-034	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 73-21-01, MM 73-21-10, MM 73-21-10PROC. REF: AMM 73-21-01, MM 73-21-10, MM 73-21-10									
732200-0101	LEFT ENGINE PRESSURE DERIVATION SENSOR							Component	ATA:73
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									
732200-0102	LEFT ENGINE PRESSURE DERIVATION SENSOR							Component	ATA:73
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									
732200-0103	RIGHT ENGINE PRESSURE DERIVATION SENSOR							Component	ATA:73
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									
732200-0104	RIGHT ENGINE PRESSURE DERIVATION SENSOR							Component	ATA:73
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 73 - ENGINE FUEL AND CONTROL									
732200-0201		REAR FUS PRESSURE TRANSDUCER - ENGINE SYSTEM TRANSDUCER						Component	ATA:73
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									
732201-0201 U		L ENG 1A FADEC, BASIC, ELECTRICAL CONTROL UNIT						Component	ATA:73
PN:23078837	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 73-22-01PROC. REF: AMM 73-22-01									
732201-0202 U		L ENG 1B FADEC, BASIC, ELECTRICAL CONTROL UNIT						Component	ATA:73
PN:23078837	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 73-22-01PROC. REF: AMM 73-22-01									
732201-0203 U		R ENG 2A FADEC, BASIC, ELECTRICAL CONTROL UNIT						Component	ATA:73
PN:23078837	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 73-22-01PROC. REF: AMM 73-22-01									
732201-0204 U		R ENG 2B FADEC, BASIC, ELECTRICAL CONTROL UNIT						Component	ATA:73
PN:23078837	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 73-22-01PROC. REF: AMM 73-22-01									
732501-0101		NO. 1 ENGINE - NO. 1 FADEC						Component	ATA:73
PN:23093341	MOS/MSC	22-Oct-21	O/C						
SN:BX162257	HRS	9600							
	ENC	5089							
PROC. REF: AMM 73-22-01, MM 73-25-10, MM 73-25-10PROC. REF: AMM 73-22-01, MM 73-25-10, MM 73-25-10									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 73 - ENGINE FUEL AND CONTROL									
732501-0101		NO. 2 ENGINE - NO. 1 FADEC						Component	ATA:73
PN:23093341	MOS/MSC	22-Oct-21	O/C						
SN:BX162259	HRS	9600							
	ENC	5089							
PROC. REF: AMM 73-22-01, MM 73-25-10, MM 73-25-10		PROC. REF: AMM 73-22-01, MM 73-25-10, MM 73-25-10							
732503-0101		NO. 1 ENGINE - NO. 2 FADEC						Component	ATA:73
PN:23093341	MOS/MSC	22-Oct-21	O/C						
SN:BX162278	HRS	9600							
	ENC	5089							
PROC. REF: AMM 73-22-01, MM 73-25-10, MM 73-25-10		PROC. REF: AMM 73-22-01, MM 73-25-10, MM 73-25-10							
732503-0101		NO. 2 ENGINE - NO. 2 FADEC						Component	ATA:73
PN:23093341	MOS/MSC	22-Oct-21	O/C						
SN:BX162246	HRS	9600							
	ENC	5089							
PROC. REF: AMM 73-22-01, MM 73-25-10, MM 73-25-10		PROC. REF: AMM 73-22-01, MM 73-25-10, MM 73-25-10							
732510-0201		NO. 1 ENGINE - INSPECTION OF FADEC FAULT						Service	ATA:73
	MOS/MSC	25-Sep-07	A/R						
	HRS	0							
	ENC	0							
PROC. REF: MM 73-25-10		PROC. REF: MM 73-25-10							
732510-0201		NO. 2 ENGINE - INSPECTION OF FADEC FAULT						Service	ATA:73
	MOS/MSC	25-Sep-07	A/R						
	HRS	0							
	ENC	0							
PROC. REF: MM 73-25-10		PROC. REF: MM 73-25-10							
733001-0101		NO. 1 ENGINE - FUEL FLOWMETER						Component	ATA:73
PN:23052613	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:JQ-12321	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 73-31-01, MM 73-35-10, MM 73-35-10		PROC. REF: AMM 73-31-01, MM 73-35-10, MM 73-35-10							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 73 - ENGINE FUEL AND CONTROL									
733001-0101	NO. 2 ENGINE - FUEL FLOWMETER							Component	ATA:73
PN:23052613	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:JQ-12299	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 73-31-01, MM 73-35-10, MM 73-35-10PROC. REF: AMM 73-31-01, MM 73-35-10, MM 73-35-10									
733100-0101	NO. 1 ENGINE - FUEL TEMPERATURE SENSOR							Component	ATA:73
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 73-32-01, MM 73-31-10, MM 73-31-10PROC. REF: AMM 73-32-01, MM 73-31-10, MM 73-31-10									
733100-0101	NO. 2 ENGINE - FUEL TEMPERATURE SENSOR							Component	ATA:73
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 73-32-01, MM 73-31-10, MM 73-31-10PROC. REF: AMM 73-32-01, MM 73-31-10, MM 73-31-10									
ATA 74 - IGNITION									
74-21-01-960-001-A00	NO. 1 ENGINE - DISCARD THE IGNITERS							Service	ATA:74
	MOS	17-Jan-17						SYSTEM	
	HRS	7935.4	4000		(11935.4) 12039.6		763.3		
	ENC	4242							
PROC. REF: AMM 74-21-01, MM 74-21-10, MM 74-21-10, MM 74-21-10, MM 74-21-10PROC. REF: AMM 74-21-01, MM 74-21-10, MM 74-21-10, MM 74-21-10, MM 74-21-10									
74-21-01-960-001-A00	NO. 2 ENGINE - DISCARD THE IGNITERS							Service	ATA:74
	MOS	17-Jan-17						SYSTEM	
	HRS	7935.4	4000		(11935.4) 12039.6		763.3		
	ENC	4242							
PROC. REF: AMM 74-21-01, MM 74-21-10, MM 74-21-10, MM 74-21-10, MM 74-21-10PROC. REF: AMM 74-21-01, MM 74-21-10, MM 74-21-10, MM 74-21-10, MM 74-21-10									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 74 - IGNITION									
741102-0101	NO. 1 ENGINE - PMA ROTOR							Component	ATA:74
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 74-11-10, MM 74-11-10PROC. REF: MM 74-11-10, MM 74-11-10									
741102-0101	NO. 2 ENGINE - PMA ROTOR							Component	ATA:74
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 74-11-10, MM 74-11-10PROC. REF: MM 74-11-10, MM 74-11-10									
741103-0101	NO. 1 ENGINE - (PMA) ALTERNATOR STATOR							Component	ATA:74
PN:23075489	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UN11285	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 74-11-15, MM 74-11-15PROC. REF: MM 74-11-15, MM 74-11-15									
741103-0101	NO. 2 ENGINE - (PMA) ALTERNATOR STATOR							Component	ATA:74
PN:23075489	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UN11296	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 74-11-15, MM 74-11-15PROC. REF: MM 74-11-15, MM 74-11-15									
741301-0101	NO. 1 ENGINE - LEFT EXCITOR IGNITION							Component	ATA:74
PN:23077617	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UY06404681	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 74-13-01, MM 74-13-10, MM 74-13-10PROC. REF: AMM 74-13-01, MM 74-13-10, MM 74-13-10									
741301-0101	NO. 2 ENGINE - LEFT EXCITOR IGNITION							Component	ATA:74
PN:23077617	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UY06404672	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 74-13-01, MM 74-13-10, MM 74-13-10PROC. REF: AMM 74-13-01, MM 74-13-10, MM 74-13-10									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 74 - IGNITION									
741303-0101		NO. 1 ENGINE - RIGHT EXCITOR IGNITION						Component	ATA:74
PN:23077617	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UY06485105	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 74-13-01, MM 74-13-10, MM 74-13-10PROC. REF: AMM 74-13-01, MM 74-13-10, MM 74-13-10									
741303-0101		NO. 2 ENGINE - RIGHT EXCITOR IGNITION						Component	ATA:74
PN:23077617	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UY06344426	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 74-13-01, MM 74-13-10, MM 74-13-10PROC. REF: AMM 74-13-01, MM 74-13-10, MM 74-13-10									
742101-0101		NO. 1 ENGINE - TOP IGNITOR						Component	ATA:74
PN:23062672	MOS/MSC	17-Jan-17	O/C	TSN 0					
SN:JH1600694	HRS	7935.4		TSN 0					
	ENC	4242		TSN 0					
PROC. REF: AMM 74-21-01, MM 74-21-10, MM 74-21-10PROC. REF: AMM 74-21-01, MM 74-21-10, MM 74-21-10									
742101-0101		NO. 2 ENGINE - TOP IGNITOR						Component	ATA:74
PN:23062672	MOS/MSC	17-Jan-17	O/C	TSN 0					
SN:JH1601674	HRS	7935.4		TSN 0					
	ENC	4242		TSN 0					
PROC. REF: AMM 74-21-01, MM 74-21-10, MM 74-21-10PROC. REF: AMM 74-21-01, MM 74-21-10, MM 74-21-10									
742103-0101		NO. 1 ENGINE - BOTTOM IGNITOR						Component	ATA:74
PN:23062672	MOS/MSC	17-Jan-17	O/C	TSN 0					
SN:JH1601513	HRS	7935.4		TSN 0					
	ENC	4242		TSN 0					
PROC. REF: AMM 74-21-01, MM 74-13-10, MM 74-21-10PROC. REF: AMM 74-21-01, MM 74-13-10, MM 74-21-10									
742103-0101		NO. 2 ENGINE - BOTTOM IGNITOR						Component	ATA:74
PN:23062672	MOS/MSC	17-Jan-17	O/C	TSN 0					
SN:JH1601492	HRS	7935.4		TSN 0					
	ENC	4242		TSN 0					
PROC. REF: AMM 74-21-01, MM 74-13-10, MM 74-21-10PROC. REF: AMM 74-21-01, MM 74-13-10, MM 74-21-10									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 74 - IGNITION									
742105-0101		NO. 1 ENGINE - SPARK IGNITER (A) LEAD ASSEMBLY						Component	ATA:74
PN:23054367	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UM06477887	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 74-21-02, MM 74-21-15, MM 74-21-15PROC. REF: AMM 74-21-02, MM 74-21-15, MM 74-21-15									
742105-0101		NO. 2 ENGINE - SPARK IGNITER (A) LEAD ASSEMBLY						Component	ATA:74
PN:23054367	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UM06477892	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 74-21-02, MM 74-21-15, MM 74-21-15PROC. REF: AMM 74-21-02, MM 74-21-15, MM 74-21-15									
742107-0101		NO. 1 ENGINE - SPARK IGNITER (B) LEAD ASSEMBLY						Component	ATA:74
PN:23054368	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UM06417221	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 74-21-02, MM 74-21-20, MM 74-21-20PROC. REF: AMM 74-21-02, MM 74-21-20, MM 74-21-20									
742107-0101		NO. 2 ENGINE - SPARK IGNITER (B) LEAD ASSEMBLY						Component	ATA:74
PN:23054368	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UM06417225	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 74-21-02, MM 74-21-20, MM 74-21-20PROC. REF: AMM 74-21-02, MM 74-21-20, MM 74-21-20									
ATA 75 - AIR									
752509-0101		NO. 1 ENGINE - RTD TOTAL TEMP SENSOR						Component	ATA:75
PN:23059750	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:RTAN269	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
752509-0101		NO. 2 ENGINE - RTD TOTAL TEMP SENSOR						Component	ATA:75
PN:23059750	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:RTAN274	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 75 - AIR									
753101-0101	NO. 1 ENGINE - BLEED AIR-COMPR ACCEL VALVE ASSEMBLY							Component	ATA:75
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 75-31-02, MM 75-31-15, MM 75-31-15PROC. REF: AMM 75-31-02, MM 75-31-15, MM 75-31-15									
753101-0101	NO. 2 ENGINE - BLEED AIR-COMPR ACCEL VALVE ASSEMBLY							Component	ATA:75
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 75-31-02, MM 75-31-15, MM 75-31-15PROC. REF: AMM 75-31-02, MM 75-31-15, MM 75-31-15									
753302-0101	NO. 1 ENGINE - INT LUDT HYDRAULIC ACTUATOR ASSEMBLY							Component	ATA:75
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
753302-0101	NO. 2 ENGINE - INT LUDT HYDRAULIC ACTUATOR ASSEMBLY							Component	ATA:75
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
754301-0101	NO. 1 ENGINE - NO. 1 P2.5 PRESSURE TRANSDUCER SENSOR							Component	ATA:75
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 75-43-10, MM 75-43-10PROC. REF: MM 75-43-10, MM 75-43-10									
754301-0101	NO. 2 ENGINE - NO. 1 P2.5 PRESSURE TRANSDUCER SENSOR							Component	ATA:75
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 75-43-10, MM 75-43-10PROC. REF: MM 75-43-10, MM 75-43-10									

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 75 - AIR									
754302-0101	NO. 1 ENGINE - NO. 2 P2.5 PRESSURE TRANSDUCER SENSOR							Component	ATA:75
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 75-43-10, MM 75-43-10PROC. REF: MM 75-43-10, MM 75-43-10									
754302-0101	NO. 2 ENGINE - NO. 2 P2.5 PRESSURE TRANSDUCER SENSOR							Component	ATA:75
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 75-43-10, MM 75-43-10PROC. REF: MM 75-43-10, MM 75-43-10									
754303-0101	NO. 1 ENGINE - NO. 1 P2 PRESSURE TRANSDUCER SENSOR							Component	ATA:75
PN:23055446	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:QW400480S	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 75-43-10, MM 75-43-10PROC. REF: MM 75-43-10, MM 75-43-10									
754303-0101	NO. 2 ENGINE - NO. 1 P2 PRESSURE TRANSDUCER SENSOR							Component	ATA:75
PN:23055446	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:QW440459S	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 75-43-10, MM 75-43-10PROC. REF: MM 75-43-10, MM 75-43-10									
754303-0102	NO. 1 ENGINE - NO. 2 P2 PRESSURE TRANSDUCER SENSOR							Component	ATA:75
PN:23055446	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:QW400473S	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 75-43-10, MM 75-43-10PROC. REF: MM 75-43-10, MM 75-43-10									
754303-0102	NO. 2 ENGINE - NO. 2 P2 PRESSURE TRANSDUCER SENSOR							Component	ATA:75
PN:23055446	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:QW400458S	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 75-43-10, MM 75-43-10PROC. REF: MM 75-43-10, MM 75-43-10									

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 75 - AIR									
754310-0101		NO. 1 ENGINE - INSPECT THE COMPRESSOR-INLET-PRESSURE-SENSOR (P2.5 SENSOR)							Service ATA:75
	MOS/MSC	25-Sep-07	N/R						
	HRS	0							
	ENC	0							
PROC. REF: MM 75-43-10PROC. REF: MM 75-43-10									
754310-0101		NO. 2 ENGINE - INSPECT THE COMPRESSOR-INLET-PRESSURE-SENSOR (P2.5 SENSOR)							Service ATA:75
	MOS/MSC	25-Sep-07	N/R						
	HRS	0							
	ENC	0							
PROC. REF: MM 75-43-10PROC. REF: MM 75-43-10									
ATA 76 - ENGINE CONTROLS									
76-11-04-720-001-A00 S		FUNCTIONALLY CHECK FRICTION LOCK ASSEMBLY FOR PRE-LOAD VALUE.							Service ATA:76
	MOS/MSC	17-Oct-25	N/A						
	HRS	10913.9							
	AFL	5820							
									PKG:5004
PROC. REF: AMM 76-11-04PROC. REF: AMM 76-11-04									
76-12-00-710-001-A00 S		OPERATIONAL CHECK WOW INPUT SIGNAL TO FADEC							Service ATA:76
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: AMM 76-12-00PROC. REF: AMM 76-12-00									
76-12-01-212-001-A00 S		GENERAL VISUAL INSPECTION RESOLVERS ATTACHMENTS TO THE THRUST LEVERS.(NOTE: CHECK TOGETHER WITH TASK 78-33-00-720-001-A00)							Service ATA:76
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: AMM 76-12-01PROC. REF: AMM 76-12-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 76 - ENGINE CONTROLS									
76-13-03-710-001-A00 S	OPERATIONAL CHECK IDLE LOCKOUT MICROSWITCH							Service	ATA:76
	MOS	17-Oct-25	12 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	500 (+20/-20)						
	AFL	5820							
									PKG:5002
PROC. REF: AMM 76-13-03PROC. REF: AMM 76-13-03									
76-20-00-710-001-A00 S	OPERATIONAL CHECK EMERGENCY SHUTDOWN SYSTEM.							Service	ATA:76
	MOS	17-Oct-25	24 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	1000 (+20/-20)						
	AFL	5820							
									PKG:5004
PROC. REF: AMM 76-20-00PROC. REF: AMM 76-20-00									
761000-0101	CREW CAB CONTROL BOX,-THRUST REVERSER/GUST LOCK,ENGINE,CTL CONSOL ASSEMBLY							Component	ATA:76
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 76-11-02PROC. REF: AMM 76-11-02									
761000-0201	C FLOOR BOX -POWER SUPPLY DIODE ASSEMBLY							Component	ATA:76
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 76-12-03PROC. REF: AMM 76-12-03									
761000-0301	CENTER PEDESTAL QUADRANT ASSY-ENGINE CENTRAL,MAIN CONSOLE,COCKPIT QUADRANT							Component	ATA:76
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									
761100-0101	NO. 1 ENGINE - INT ENGINE (B) HARNESS ASSEMBLY							Component	ATA:76
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 76-11-15, MM 76-11-15PROC. REF: MM 76-11-15, MM 76-11-15									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 76 - ENGINE CONTROLS									
761100-0101	NO. 2 ENGINE - INT ENGINE (B) HARNESS ASSEMBLY							Component	ATA:76
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 76-11-15, MM 76-11-15					PROC. REF: MM 76-11-15, MM 76-11-15				
761101-0101	NO. 1 ENGINE - ENGINE CONTROL WIRING HARNESS							Component	ATA:76
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 76-11-10, MM 76-11-10, MM 76-11-15, MM 76-11-15					PROC. REF: MM 76-11-10, MM 76-11-10, MM 76-11-15, MM 76-11-15				
761101-0101	NO. 2 ENGINE - ENGINE CONTROL WIRING HARNESS							Component	ATA:76
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 76-11-10, MM 76-11-10, MM 76-11-15, MM 76-11-15					PROC. REF: MM 76-11-10, MM 76-11-10, MM 76-11-15, MM 76-11-15				
761102-0101	NO. 1 ENGINE - EXT ENGINE WIRING HARNESS ASSEMBLY							Component	ATA:76
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 76-11-20, MM 76-11-20, MM 76-11-20, MM 76-11-20, MM 76-11-25, MM 76-11-25, MM 76-11-25, MM 76-11-25					PROC. REF: MM 76-11-20, MM 76-11-20, MM 76-11-20, MM 76-11-20, MM 76-11-25, MM 76-11-25, MM 76-11-25, MM 76-11-25				
761102-0101	NO. 2 ENGINE - EXT ENGINE WIRING HARNESS ASSEMBLY							Component	ATA:76
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 76-11-20, MM 76-11-20, MM 76-11-20, MM 76-11-20, MM 76-11-25, MM 76-11-25, MM 76-11-25, MM 76-11-25					PROC. REF: MM 76-11-20, MM 76-11-20, MM 76-11-20, MM 76-11-20, MM 76-11-25, MM 76-11-25, MM 76-11-25, MM 76-11-25				
761103-0101	NO. 1 ENGINE - INT ENGINE (A) HARNESS ASSEMBLY							Component	ATA:76
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 76-11-10, MM 76-11-10					PROC. REF: MM 76-11-10, MM 76-11-10				

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 76 - ENGINE CONTROLS									
761103-0101		NO. 2 ENGINE - INT ENGINE (A) HARNESS ASSEMBLY						Component	ATA:76
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 76-11-10, MM 76-11-10		PROC. REF: MM 76-11-10, MM 76-11-10							
761200-0101		OVERH P CONTROL ASSY-POWER PLANT CONTROL,COCKPIT MODULE						Component	ATA:76
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 76-12-04		PROC. REF: AMM 76-12-04							
761200-0201		CREW CAB THRUST RATING SELECTION MODULE						Component	ATA:76
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 76-12-02		PROC. REF: AMM 76-12-02							
761301-0101		NO. 1 ENGINE - EXT-ENGINE INDICATING HARNESS ASSEMBLY						Component	ATA:76
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 76-13-15, MM 76-13-15, MM 76-13-15, MM 76-13-15		PROC. REF: MM 76-13-15, MM 76-13-15, MM 76-13-15, MM 76-13-15							
761301-0101		NO. 2 ENGINE - EXT-ENGINE INDICATING HARNESS ASSEMBLY						Component	ATA:76
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 76-13-15, MM 76-13-15, MM 76-13-15, MM 76-13-15		PROC. REF: MM 76-13-15, MM 76-13-15, MM 76-13-15, MM 76-13-15							
761302-0101		NO. 1 ENGINE - INT-ENG INDICATING HARNESS ASSEMBLY						Component	ATA:76
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 76-13-10, MM 76-13-10		PROC. REF: MM 76-13-10, MM 76-13-10							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 76 - ENGINE CONTROLS									
761302-0101	NO. 2 ENGINE - INT-ENG INDICATING HARNESS ASSEMBLY							Component	ATA:76
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 76-13-10, MM 76-13-10PROC. REF: MM 76-13-10, MM 76-13-10									
ATA 77 - ENGINE INDICATING									
771100-0101	NO. 1 ENGINE - NO. 1 GAS PRODUCER SENSOR							Component	ATA:77
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 77-11-10, MM 77-11-10PROC. REF: MM 77-11-10, MM 77-11-10									
771100-0101	NO. 2 ENGINE - NO. 1 GAS PRODUCER SENSOR							Component	ATA:77
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 77-11-10, MM 77-11-10PROC. REF: MM 77-11-10, MM 77-11-10									
771101-0101	NO. 1 ENGINE - NO. 2 GAS PRODUCER SENSOR							Component	ATA:77
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 77-11-10, MM 77-11-10PROC. REF: MM 77-11-10, MM 77-11-10									
771101-0101	NO. 2 ENGINE - NO. 2 GAS PRODUCER SENSOR							Component	ATA:77
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 77-11-10, MM 77-11-10PROC. REF: MM 77-11-10, MM 77-11-10									
771103-0101	NO. 1 ENGINE - NO. 1 FAN SPEED PICKUP SENSOR							Component	ATA:77
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 77-11-02, MM 77-11-15, MM 77-11-15PROC. REF: AMM 77-11-02, MM 77-11-15, MM 77-11-15									

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 77 - ENGINE INDICATING									
771103-0101	NO. 2 ENGINE - NO. 1 FAN SPEED PICKUP SENSOR							Component	ATA:77
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 77-11-02, MM 77-11-15, MM 77-11-15	PROC. REF: AMM 77-11-02, MM 77-11-15, MM 77-11-15								
771105-0101	NO. 1 ENGINE - NO. 2 FAN SPEED PICKUP SENSOR							Component	ATA:77
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 77-11-02, MM 77-11-15, MM 77-11-15	PROC. REF: AMM 77-11-02, MM 77-11-15, MM 77-11-15								
771105-0101	NO. 2 ENGINE - NO. 2 FAN SPEED PICKUP SENSOR							Component	ATA:77
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 77-11-02, MM 77-11-15, MM 77-11-15	PROC. REF: AMM 77-11-02, MM 77-11-15, MM 77-11-15								
772101-0101	NO. 1 ENGINE - NO. 1 TURBINE THERMOCOUPLE							Component	ATA:77
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10	PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10								
772101-0101	NO. 2 ENGINE - NO. 1 TURBINE THERMOCOUPLE							Component	ATA:77
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10	PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10								
772101-0102	NO. 1 ENGINE - NO. 2 TURBINE THERMOCOUPLE							Component	ATA:77
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10	PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 77 - ENGINE INDICATING									
772101-0102	NO. 2 ENGINE - NO. 2 TURBINE THERMOCOUPLE							Component	ATA:77
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10									
772101-0103	NO. 1 ENGINE - NO. 3 TURBINE THERMOCOUPLE							Component	ATA:77
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10									
772101-0103	NO. 2 ENGINE - NO. 3 TURBINE THERMOCOUPLE							Component	ATA:77
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10									
772101-0104	NO. 1 ENGINE - NO. 4 TURBINE THERMOCOUPLE							Component	ATA:77
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10									
772101-0104	NO. 2 ENGINE - NO. 4 TURBINE THERMOCOUPLE							Component	ATA:77
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10									
772101-0105	NO. 1 ENGINE - NO. 5 TURBINE THERMOCOUPLE							Component	ATA:77
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10									

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 77 - ENGINE INDICATING									
772101-0105	NO. 2 ENGINE - NO. 5 TURBINE THERMOCOUPLE							Component	ATA:77
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10									
772101-0106	NO. 1 ENGINE - NO. 6 TURBINE THERMOCOUPLE							Component	ATA:77
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10									
772101-0106	NO. 2 ENGINE - NO. 6 TURBINE THERMOCOUPLE							Component	ATA:77
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10									
772101-0107	NO. 1 ENGINE - NO. 7 TURBINE THERMOCOUPLE							Component	ATA:77
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10									
772101-0107	NO. 2 ENGINE - NO. 7 TURBINE THERMOCOUPLE							Component	ATA:77
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10									
772101-0108	NO. 1 ENGINE - NO. 8 TURBINE THERMOCOUPLE							Component	ATA:77
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 77 - ENGINE INDICATING									
772101-0108	NO. 2 ENGINE - NO. 8 TURBINE THERMOCOUPLE							Component	ATA:77
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10									
772101-0109	NO. 1 ENGINE - NO. 9 TURBINE THERMOCOUPLE							Component	ATA:77
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10									
772101-0109	NO. 2 ENGINE - NO. 9 TURBINE THERMOCOUPLE							Component	ATA:77
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10									
772101-0110	NO. 1 ENGINE - NO. 10 TURBINE THERMOCOUPLE							Component	ATA:77
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10									
772101-0110	NO. 2 ENGINE - NO. 10 TURBINE THERMOCOUPLE							Component	ATA:77
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10									
772101-0111	NO. 1 ENGINE - NO. 11 TURBINE THERMOCOUPLE							Component	ATA:77
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 77 - ENGINE INDICATING									
772101-0111	NO. 2 ENGINE - NO. 11 TURBINE THERMOCOUPLE							Component	ATA:77
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10									
772101-0112	NO. 1 ENGINE - NO. 12 TURBINE THERMOCOUPLE							Component	ATA:77
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10									
772101-0112	NO. 2 ENGINE - NO. 12 TURBINE THERMOCOUPLE							Component	ATA:77
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10									
772101-0113	NO. 1 ENGINE - NO. 13 TURBINE THERMOCOUPLE							Component	ATA:77
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10									
772101-0113	NO. 2 ENGINE - NO. 13 TURBINE THERMOCOUPLE							Component	ATA:77
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10									
772101-0114	NO. 1 ENGINE - NO. 14 TURBINE THERMOCOUPLE							Component	ATA:77
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 77 - ENGINE INDICATING									
772101-0114	NO. 2 ENGINE - NO. 14 TURBINE THERMOCOUPLE							Component	ATA:77
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10									
772101-0115	NO. 1 ENGINE - NO. 15 TURBINE THERMOCOUPLE							Component	ATA:77
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10									
772101-0115	NO. 2 ENGINE - NO. 15 TURBINE THERMOCOUPLE							Component	ATA:77
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10									
772101-0116	NO. 1 ENGINE - NO. 16 TURBINE THERMOCOUPLE							Component	ATA:77
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10									
772101-0116	NO. 2 ENGINE - NO. 16 TURBINE THERMOCOUPLE							Component	ATA:77
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10									
772101-0201	NO. 1 ENGINE - TURBINE (1-16) THERMOCOUPLE							Component	ATA:77
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 77 - ENGINE INDICATING									
772101-0201		NO. 2 ENGINE - TURBINE (1-16) THERMOCOUPLE						Component	ATA:77
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10									
772102-0101		NO. 1 ENGINE - T/C WIRING HARNESS						Component	ATA:77
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 77-21-02, MM 77-21-15, MM 77-21-15, MM 77-21-20, MM 77-21-20PROC. REF: AMM 77-21-02, MM 77-21-15, MM 77-21-15, MM 77-21-20, MM 77-21-20									
772102-0101		NO. 2 ENGINE - T/C WIRING HARNESS						Component	ATA:77
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 77-21-02, MM 77-21-15, MM 77-21-15, MM 77-21-20, MM 77-21-20PROC. REF: AMM 77-21-02, MM 77-21-15, MM 77-21-15, MM 77-21-20, MM 77-21-20									
772103-0101		NO. 1 ENGINE - T/C WIRING ASSEMBLY						Component	ATA:77
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 77-21-02, MM 77-21-15, MM 77-21-15, MM 77-21-20, MM 77-21-20PROC. REF: AMM 77-21-02, MM 77-21-15, MM 77-21-15, MM 77-21-20, MM 77-21-20									
772103-0101		NO. 2 ENGINE - T/C WIRING ASSEMBLY						Component	ATA:77
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 77-21-02, MM 77-21-15, MM 77-21-15, MM 77-21-20, MM 77-21-20PROC. REF: AMM 77-21-02, MM 77-21-15, MM 77-21-15, MM 77-21-20, MM 77-21-20									
774000-0101		REAR VIBRATION MONITORING-ENGINE,EVMU,REAR FUSLG I UNIT						Component	ATA:77
PN:241-244-013-002	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:AC25773	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 77-41-03PROC. REF: AMM 77-41-03									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 77 - ENGINE INDICATING									
774102-0101		NO. 1 ENGINE - ACCELEROMETER VIBRATION SENSOR							Component ATA:77
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
774102-0101		NO. 2 ENGINE - ACCELEROMETER VIBRATION SENSOR							Component ATA:77
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
774102-0102		NO. 1 ENGINE - ACCELEROMETER VIBRATION SENSOR							Component ATA:77
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
774102-0102		NO. 2 ENGINE - ACCELEROMETER VIBRATION SENSOR							Component ATA:77
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
ATA 78 - EXHAUST									
78-10-01-212-002-A00		INSPECT (GENERAL VISUAL) PLAIN EXHAUST ASSY FOR DAMAGE, FAILURE OR IRREGULARITIES.(NOTE : NOT APPLICABLE TO AIRCRAFT WITH THRUST REVERSERS INSTALLED).							Service ATA:78
	MOS/MSC	15-Aug-13	N/A					SYSTEM	
	HRS	6643.4							
	AFL	3572							
									PKG:6020
PROC. REF: AMM 78-10-01PROC. REF: AMM 78-10-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 78 - EXHAUST									
78-31-00-220-001-A00 S	INSPECT (DETAILED INSPECTION) THRUST REVERSER STRUCTURE							Service	ATA:78
	MOS	17-Oct-25	72 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	3000 (+20/-20)						
	AFL	5820	1500 (+20/-20)						
									PKG:5012,6020
PROC. REF: AMM 78-31-00PROC. REF: AMM 78-31-00									
78-32-00-211-001-A00 S	VISUAL CHECK THRUST REVERSER 1RY AND 3RY LOCKS							Service	ATA:78
	MOS	17-Oct-25	12 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	500 (+20/-20)						
	AFL	5820							
									PKG:5002
PROC. REF: AMM 78-32-00PROC. REF: AMM 78-32-00									
78-32-00-710-001-A00 S	OPERATIONAL CHECK THRUST REVERSER (TR) SECONDARY (2RY) AND TERTIARY (3RY) LOCKS							Service	ATA:78
	MOS	17-Oct-25	12 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	500 (+20/-20)						
	AFL	5820							
									PKG:5002
PROC. REF: AMM 78-32-00PROC. REF: AMM 78-32-00									
78-33-00-710-001-A00 S	OPERATIONAL CHECK AIR/GROUND INPUT SIGNAL TO THRUST REVERSER (TR) SYSTEM (CMR)							Service	ATA:78
	MOS	17-Oct-25	12 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	500 (+20/-20)						
	AFL	5820							
									PKG:5002
PROC. REF: AMM 78-33-00PROC. REF: AMM 78-33-00									
78-33-00-710-002-A00 S	OPERATIONAL CHECK WHEEL-SPEED INPUT SIGNAL TO THE THRUST REVERSER SYSTEM (CMR)							Service	ATA:78
	MOS	17-Oct-25	12 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	500 (+20/-20)						
	AFL	5820							
									PKG:5002
PROC. REF: AMM 78-33-00PROC. REF: AMM 78-33-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 78 - EXHAUST									
78-33-00-720-001-A00 S	FUNCTIONAL CHECK THRUST-REVERSER (TR) CONTROL-LEVER MICROSWITCHES							Service	ATA:78
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	4000 (+20/-20)						
	AFL	5401	2000 (+20/-20)						
									PKG:5016,6032
PROC. REF: AMM 78-33-00PROC. REF: AMM 78-33-00									
78-33-01-710-001-A00 S	OPERATIONAL CHECK THRUST REVERSER ISOLATION CONTROL UNIT (ICU) (CMR)							Service	ATA:78
	MOS	17-Oct-25	12 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	500 (+20/-20)						
	AFL	5820							
									PKG:5002
PROC. REF: AMM 78-33-01PROC. REF: AMM 78-33-01									
78-34-00-710-001-A00 S	OPERATIONAL CHECK THRUST-REVERSER (TR) INDICATING SYSTEM (CMR)							Service	ATA:78
	MOS	17-Oct-25	72 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	3000 (+20/-20)						
	AFL	5820	1500 (+20/-20)						
									PKG:5012,6020
PROC. REF: AMM 78-34-00PROC. REF: AMM 78-34-00									
78-34-01-720-001-A00	FUNCTIONAL CHECK STOW/TRANSIT THRUST REVERSER MICROSWITCHES FOR INSULATION PRE-MOD S.B. 145LEG-78-0006. (ELECTRICAL TEST).(L600 ONLY)							Service	ATA:78
	MOS/MSC	27-Aug-07	N/A						
	HRS	0							
	AFL	0							
PROC. REF: AMM 78-34-01PROC. REF: AMM 78-34-01									
78-Z416-213-001-A00 S	GENERAL VISUAL INSPECTION THRUST REVERSER MODULE (EXTERNAL) (ZONES 416 AND 426)							Service	ATA:78
	MOS	17-Oct-25	24 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	1000 (+20/-20)						
	AFL	5820							
									PKG:5004
PROC. REF: AMM 05-20-74PROC. REF: AMM 05-20-74									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 78 - EXHAUST									
78-Z416-213-001-A01	GENERAL VISUAL INSPECTION (EXTERNAL) (ZONES 416 AND 426).NOTE: FOR AIRCRAFT WITHOUT THRUST REVERSERS ONLY.							Service	ATA:78
	MOS/MSC		N/A						
	HRS								
	AFL								
									PKG:6016
PROC. REF: AMM 05-30-41PROC. REF: AMM 05-30-41									
78-Z416-214-001-A00 S	GENERAL VISUAL INSPECTION THRUST REVERSER MODULE (INTERNAL) (ZONES 416 AND 426) (L600 ONLY)							Service	ATA:78
	MOS	17-Oct-25	24 (+15d/-15d)				LOW UTILIZATION		
	HRS	10913.9	1000 (+20/-20)						
	AFL	5820							
									PKG:5004
PROC. REF: AMM 05-20-74PROC. REF: AMM 05-20-74									
78-Z416-214-001-A01	GENERAL VISUAL INSPECTION (INTERNAL) (ZONES 416 AND 426).NOTE: FOR AIRCRAFT WITHOUT THRUST REVERSERS ONLY.							Service	ATA:78
	MOS/MSC		N/A						
	HRS								
	AFL								
									PKG:6016
PROC. REF: AMM 05-30-41PROC. REF: AMM 05-30-41									
78-Z416-214-001-A02	GENERAL VISUAL INSPECTION THRUST REVERSER MODULE (INTERNAL) (ZONES 416 AND 426).NOTE: EWIS. (L650 ONLY)							Service	ATA:78
	MOS/MSC	25-Sep-07	N/A				ZONAL		
	HRS	0							
	AFL	0							
PROC. REF: AMM 05-20-74PROC. REF: AMM 05-20-74									
783000-0201	LH ENG THRUST REVERSER ASSEMBLY							Component	ATA:78
PN:145-79600-407	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:TR1838	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 78-31-01PROC. REF: AMM 78-31-01									
783000-0202	RH ENG THRUST REVERSER ASSEMBLY							Component	ATA:78
PN:145-79600-407	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:TR1863	HRS	0		TSN 0					
	AFL	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 78 - EXHAUST									
PROC. REF: AMM 78-31-01PROC. REF: AMM 78-31-01									
783101-0101	LEFT UPPER THRUST REVERSER DOOR							Component	ATA:78
PN:145-79603-403	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UPD1837	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 78-31-02PROC. REF: AMM 78-31-02									
783101-0102	LEFT LOWER THRUST REVERSER DOOR							Component	ATA:78
PN:145-79604-403	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:LPD1838	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 78-31-03PROC. REF: AMM 78-31-03									
783101-0103	RIGHT UPPER THRUST REVERSER DOOR							Component	ATA:78
PN:145-79603-403	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UPD1863	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 78-31-02PROC. REF: AMM 78-31-02									
783101-0104	RIGHT LOWER THRUST REVERSER DOOR							Component	ATA:78
PN:145-79604-403	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:LPD1863	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 78-31-03PROC. REF: AMM 78-31-03									
783201-0101	LEFT UPPER PIVOT DOOR ACTUATOR							Component	ATA:78
PN:TY2039-14A	MOS	27-Aug-07		TSN 0				LIFE LIMIT	
SN:3910	HRS	0		TSN 0					
	AFL	0	60250	TSN 0	60250		54225		
PROC. REF: AMM 78-32-01PROC. REF: AMM 78-32-01									
783201-0102	LEFT LOWER PIVOT DOOR ACTUATOR							Component	ATA:78
PN:TY2039-14A	MOS	27-Aug-07		TSN 0				LIFE LIMIT	
SN:3909	HRS	0		TSN 0					
	AFL	0	60250	TSN 0	60250		54225		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 78 - EXHAUST									
PROC. REF: AMM 78-32-01PROC. REF: AMM 78-32-01									
783201-0103		RIGHT UPPER PIVOT DOOR ACTUATOR						Component	ATA:78
PN:TY2039-14A	MOS	27-Aug-07		TSN 0				LIFE LIMIT	
SN:3948	HRS	0		TSN 0					
	AFL	0	60250	TSN 0	60250		54225		
PROC. REF: AMM 78-32-01PROC. REF: AMM 78-32-01									
783201-0104		RIGHT LOWER PIVOT DOOR ACTUATOR						Component	ATA:78
PN:TY2039-14A	MOS	27-Aug-07		TSN 0				LIFE LIMIT	
SN:3961	HRS	0		TSN 0					
	AFL	0	60250	TSN 0	60250		54225		
PROC. REF: AMM 78-32-01PROC. REF: AMM 78-32-01									
783202-0101		LEFT 90 DEG PRIMARY DOOR LOCK ACTUATOR						Component	ATA:78
PN:TY2038-02A	MOS	27-Aug-07		TSN 0				LIFE LIMIT	
SN:61016	HRS	0		TSN 0					
	AFL	0	60250	TSN 0	60250		54225		
PROC. REF: AMM 78-32-02PROC. REF: AMM 78-32-02									
783202-0102		LEFT 270 DEG PRIMARY DOOR LOCK ACTUATOR						Component	ATA:78
PN:TY2038-02A	MOS	27-Aug-07		TSN 0				LIFE LIMIT	
SN:61017	HRS	0		TSN 0					
	AFL	0	60250	TSN 0	60250		54225		
PROC. REF: AMM 78-32-02PROC. REF: AMM 78-32-02									
783202-0103		RIGHT 90 DEG PRIMARY DOOR LOCK ACTUATOR						Component	ATA:78
PN:TY2038-02A	MOS	27-Aug-07		TSN 0				LIFE LIMIT	
SN:61066	HRS	0		TSN 0					
	AFL	0	60250	TSN 0	60250		54225		
PROC. REF: AMM 78-32-02PROC. REF: AMM 78-32-02									
783202-0104		RIGHT 270 DEG PRIMARY DOOR LOCK ACTUATOR						Component	ATA:78
PN:TY2038-02A	MOS	27-Aug-07		TSN 0				LIFE LIMIT	
SN:61067	HRS	0		TSN 0					
	AFL	0	60250	TSN 0	60250		54225		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 78 - EXHAUST									
PROC. REF: AMM 78-32-02PROC. REF: AMM 78-32-02									
783205-0101		LEFT UPPER TERTIARY LOCK						Component	ATA:78
PN:TY2560-01A	MOS	27-Aug-07		TSN 0				LIFE LIMIT	
SN:03203	HRS	0		TSN 0					
	AFL	0	61500	TSN 0	61500		55475		
PROC. REF: AMM 78-32-05PROC. REF: AMM 78-32-05									
783205-0102		LEFT LOWER TERTIARY LOCK						Component	ATA:78
PN:TY2560-01A	MOS	27-Aug-07		TSN 0				LIFE LIMIT	
SN:03204	HRS	0		TSN 0					
	AFL	0	61500	TSN 0	61500		55475		
PROC. REF: AMM 78-32-05PROC. REF: AMM 78-32-05									
783205-0103		RIGHT UPPER TERTIARY LOCK						Component	ATA:78
PN:TY2560-01A	MOS	27-Aug-07		TSN 0				LIFE LIMIT	
SN:03313	HRS	0		TSN 0					
	AFL	0	61500	TSN 0	61500		55475		
PROC. REF: AMM 78-32-05PROC. REF: AMM 78-32-05									
783205-0104		RIGHT LOWER TERTIARY LOCK						Component	ATA:78
PN:TY2560-01A	MOS	27-Aug-07		TSN 0				LIFE LIMIT	
SN:03314	HRS	0		TSN 0					
	AFL	0	61500	TSN 0	61500		55475		
PROC. REF: AMM 78-32-05PROC. REF: AMM 78-32-05									
783301-0101		LH REAR ISOLATION ASSY-THRUST REVERSER VALVE						Component	ATA:78
PN:TY2041-03A	MOS	27-Aug-07		TSN 0				LIFE LIMIT	
SN:1936	HRS	0		TSN 0					
	AFL	0	60250	TSN 0	60250		54225		
PROC. REF: AMM 78-33-01PROC. REF: AMM 78-33-01									
783301-0102		RH REAR ISOLATION ASSY-THRUST REVERSER VALVE						Component	ATA:78
PN:TY2041-03A	MOS	27-Aug-07		TSN 0				LIFE LIMIT	
SN:1937	HRS	0		TSN 0					
	AFL	0	60250	TSN 0	60250		54225		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 78 - EXHAUST									
PROC. REF: AMM 78-33-01PROC. REF: AMM 78-33-01									
783305-0101		LEFT DIRECTIONAL CONTROL UNIT							Component ATA:78
PN:TY2040-01A	MOS	27-Aug-07		TSN 0				LIFE LIMIT	
SN:1944	HRS	0		TSN 0					
	AFL	0	60250	TSN 0	60250		54225		
PROC. REF: AMM 78-33-05PROC. REF: AMM 78-33-05									
783305-0102		RIGHT DIRECTIONAL CONTROL UNIT							Component ATA:78
PN:TY2040-01A	MOS	27-Aug-07		TSN 0				LIFE LIMIT	
SN:1971	HRS	0		TSN 0					
	AFL	0	60250	TSN 0	60250		54225		
PROC. REF: AMM 78-33-05PROC. REF: AMM 78-33-05									
783305-0201		LEFT LOCK SEQUENCER							Component ATA:78
PN:TY2047-03B	MOS	27-Aug-07		TSN 0				LIFE LIMIT	
SN:1921	HRS	0		TSN 0					
	AFL	0	60250	TSN 0	60250		54225		
PROC. REF: AMM 78-33-06PROC. REF: AMM 78-33-06									
783305-0202		RIGHT LOCK SEQUENCER							Component ATA:78
PN:TY2047-03B	MOS	27-Aug-07		TSN 0				LIFE LIMIT	
SN:1948	HRS	0		TSN 0					
	AFL	0	60250	TSN 0	60250		54225		
PROC. REF: AMM 78-33-06PROC. REF: AMM 78-33-06									
783402-0101		LEFT HAND UPPER DEPLOY SWITCH SWITCH							Component ATA:78
PN:83-990-173	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:00561	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 78-34-02PROC. REF: AMM 78-34-02									
783402-0102		LEFT HAND LOWER DEPLOY SWITCH							Component ATA:78
PN:83-990-174	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:00564	HRS	0		TSN 0					
	AFL	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty

ATA 78 - EXHAUST

PROC. REF: AMM 78-34-02PROC. REF: AMM 78-34-02

783402-0103	RIGHT HAND UPPER DEPLOY SWITCH							Component	ATA:78
PN:83-990-173	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:00596	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 78-34-02PROC. REF: AMM 78-34-02									
783402-0104	RIGHT HAND LOWER DEPLOY SWITCH							Component	ATA:78
PN:83-990-174	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:00603	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 78-34-02PROC. REF: AMM 78-34-02									
789000-0101	LEFT UPPER LEFT THRUST REVERSER STOW SWITCH							Component	ATA:78
PN:83-990-168	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:11614	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 78-34-01PROC. REF: AMM 78-34-01									
789000-0102	LEFT LOWER LEFT THRUST REVERSER STOW SWITCH							Component	ATA:78
PN:83-990-168	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:11623	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 78-34-01PROC. REF: AMM 78-34-01									
789000-0103	RIGHT UPPER LEFT THRUST REVERSER STOW SWITCH							Component	ATA:78
PN:83-990-168	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:11621	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 78-34-01PROC. REF: AMM 78-34-01									
789000-0104	RIGHT LOWER LEFT THRUST REVERSER STOW SWITCH							Component	ATA:78
PN:83-990-168	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:11622	HRS	0		TSN 0					
	AFL	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 78 - EXHAUST									
PROC. REF: AMM 78-34-01PROC. REF: AMM 78-34-01									
789000-0105	LEFT UPPER RIGHT THRUST REVERSER STOW SWITCH							Component	ATA:78
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 78-34-01PROC. REF: AMM 78-34-01									
789000-0106	LEFT LOWER RIGHT THRUST REVERSER STOW SWITCH							Component	ATA:78
PN:83-990-168	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:12018	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 78-34-01PROC. REF: AMM 78-34-01									
789000-0107	RIGHT UPPER RIGHT THRUST REVERSER STOW SWITCH							Component	ATA:78
PN:83-990-168	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:11979	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 78-34-01PROC. REF: AMM 78-34-01									
789000-0108	RIGHT LOWER RIGHT THRUST REVERSER STOW SWITCH							Component	ATA:78
PN:83-990-168	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:12017	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 78-34-01PROC. REF: AMM 78-34-01									
789000-0201	UPPER LEFT THRUST REVERSER TRANSIT SWITCH							Component	ATA:78
PN:83-990-168	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:11613	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 78-34-01PROC. REF: AMM 78-34-01									
789000-0202	LOWER LEFT THRUST REVERSER TRANSIT SWITCH							Component	ATA:78
PN:83-990-168	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:11619	HRS	0		TSN 0					
	AFL	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty

ATA 78 - EXHAUST

PROC. REF: AMM 78-34-01PROC. REF: AMM 78-34-01

789000-0203		UPPER RIGHT THRUST REVERSER TRANSIT SWITCH						Component	ATA:78
PN:83-990-168	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:11973	HRS	0		TSN 0					
	AFL	0		TSN 0					

PROC. REF: AMM 78-34-01PROC. REF: AMM 78-34-01

789000-0204		LOWER RIGHT THRUST REVERSER TRANSIT SWITCH						Component	ATA:78
PN:83-990-168	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:12008	HRS	0		TSN 0					
	AFL	0		TSN 0					

PROC. REF: AMM 78-34-01PROC. REF: AMM 78-34-01

ATA 79 - OIL

79-23-01-960-002-A00 S		DISCARD OIL FILTER						Service	ATA:79
	MOS	17-Oct-25	24 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	1000 (+20/-20)						
	AFL	5820							

PKG:5004

PROC. REF: AMM 79-23-01PROC. REF: AMM 79-23-01

79-27-00-211-001-A00		NO. 1 ENGINE - VISUALLY CHECK OIL PLUMBING						Service	ATA:79
	MOS/MSC	14-Jul-22	O/C						
	HRS	9811.6							
	ENC	5199							

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

79-27-00-211-001-A00		NO. 2 ENGINE - VISUALLY CHECK OIL PLUMBING						Service	ATA:79
	MOS/MSC	14-Jul-22	O/C						
	HRS	9811.6							
	ENC	5199							

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 79 - OIL									
79-27-00-212-001-A00	NO. 1 ENGINE - INSPECT (GENERAL VISUAL) OIL PLUMBING							Service	ATA:79
	MOS	25-Sep-07							
	HRS	0	10000		(19811.6) 19915.8 (M)		8639.5		
	ENC	0							
PROC. REF: GENERIC NO REF, AMM 79-27-00PROC. REF: GENERIC NO REF, AMM 79-27-00									
79-27-00-212-001-A00	NO. 2 ENGINE - INSPECT (GENERAL VISUAL) OIL PLUMBING							Service	ATA:79
	MOS	25-Sep-07							
	HRS	0	10000		(19811.6) 19915.8 (M)		8639.5		
	ENC	0							
PROC. REF: GENERIC NO REF, AMM 79-27-00PROC. REF: GENERIC NO REF, AMM 79-27-00									
79-34-00-212-001-A00	INSPECT (GENERAL VISUAL) OF MULTI-FUNCTION DISPLAY FOR ENG 1(2) OIL DEBRIS ENGINE AE3007A1P MAINTENANCE MESSAGE NOTE: IF INSTALLED (L600 ONLY)							Service	ATA:79
	MOS/MSC	15-Aug-13	N/A						
	HRS	6643.4							
	AFL	3572							
PROC. REF: AMM 79-34-00PROC. REF: AMM 79-34-00									
79-34-00-212-001-A01	INSPECT (GENERAL VISUAL) MFD FOR ENG 1(2) OIL DEBRIS FOR ENGINE AE3007A1E OR AE3007A2 MAINTENANCE MESSAGE (NOTE: IF INSTALLED).							Service	ATA:79
	DAYS	18-May-26	30		17-Jun-26		22 d		
	HRS	11259.6	70	Adj -23.2	11306.4		30.1		
	AFL	6018							
PROC. REF: AMM 79-34-00PROC. REF: AMM 79-34-00									
79-34-01-720-001-A00	NO. 1 ENGINE - FUNCTIONALLY CHECK INDICATING MAGNETIC PLUG ASSEMBLY							Service	ATA:79
	MOS	17-Feb-17							
	HRS	7961.8	10000		(17961.8) 18066		6789.7		
	ENC	4253							
PROC. REF: AMM 79-34-01, MM 79-37-10PROC. REF: AMM 79-34-01, MM 79-37-10									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 79 - OIL									
79-34-01-720-001-A00	NO. 2 ENGINE - FUNCTIONALLY CHECK INDICATING MAGNETIC PLUG ASSEMBLY							Service	ATA:79
	MOS	17-Feb-17							
	HRS	7961.8	10000		(17961.8) 18066		6789.7		
	ENC	4253							
PROC. REF: AMM 79-34-01, MM 79-37-10PROC. REF: AMM 79-34-01, MM 79-37-10									
79-37-00-720-001-A00	NO. 1 ENGINE - FUNCTIONALLY CHECK OIL FILTER IMPEDING BYPASS INDICATING SYSTEM							Service	ATA:79
	MOS	17-Feb-17							
	HRS	7961.8	10000		(17961.8) 18066		6789.7		
	ENC	4253							
PROC. REF: AMM 79-37-00, MM 79-37-15PROC. REF: AMM 79-37-00, MM 79-37-15									
79-37-00-720-001-A00	NO. 2 ENGINE - FUNCTIONALLY CHECK OIL FILTER IMPEDING BYPASS INDICATING SYSTEM							Service	ATA:79
	MOS	10-Jul-20							
	HRS	9265.4	10000		(19265.4) 19369.6		8093.3		
	ENC	4922							
PROC. REF: AMM 79-37-00, MM 79-37-15PROC. REF: AMM 79-37-00, MM 79-37-15									
790010-0101	NO. 1 ENGINE - CHANGE THE OIL							Service	ATA:79
	MOS/MSC	25-Sep-07	A/R						
	HRS	0							
	ENC	0							
PROC. REF: MM 12-10-79PROC. REF: MM 12-10-79									
790010-0101	NO. 2 ENGINE - CHANGE THE OIL							Service	ATA:79
	MOS/MSC	25-Sep-07	A/R						
	HRS	0							
	ENC	0							
PROC. REF: MM 12-10-79PROC. REF: MM 12-10-79									
791101-0101	NO. 1 ENGINE - OIL TANK ASSEMBLY							Component	ATA:79
PN:23070328	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:RJ15141	HRS	0		TSN 0					
	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 79 - OIL									
PROC. REF: AMM 79-11-01, MM 79-11-10, MM 79-11-10PROC. REF: AMM 79-11-01, MM 79-11-10, MM 79-11-10									
791101-0101	NO. 2 ENGINE - OIL TANK ASSEMBLY							Component	ATA:79
PN:23070328	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:RJ15135	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 79-11-01, MM 79-11-10, MM 79-11-10PROC. REF: AMM 79-11-01, MM 79-11-10, MM 79-11-10									
792101-0101	NO. 1 ENGINE - LUBE/SCAVENGE PUMP ASSEMBLY							Component	ATA:79
PN:23079382	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:NL-3020	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 79-21-10, MM 79-21-10PROC. REF: MM 79-21-10, MM 79-21-10									
792101-0101	NO. 2 ENGINE - LUBE/SCAVENGE PUMP ASSEMBLY							Component	ATA:79
PN:23079382	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:NL-3021	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: MM 79-21-10, MM 79-21-10PROC. REF: MM 79-21-10, MM 79-21-10									
792103-0101	NO. 1 ENGINE - OIL PRESS/TEMP SENSOR							Component	ATA:79
PN:23073715	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:QW7496V	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 79-32-01, MM 79-31-10, MM 79-31-10PROC. REF: AMM 79-32-01, MM 79-31-10, MM 79-31-10									
792103-0101	NO. 2 ENGINE - OIL PRESS/TEMP SENSOR							Component	ATA:79
PN:23073715	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:QW7493V	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 79-32-01, MM 79-31-10, MM 79-31-10PROC. REF: AMM 79-32-01, MM 79-31-10, MM 79-31-10									
792301-0101	NO. 1 ENGINE - OIL FILTER ASSEMBLY							Component	ATA:79
PN:23087914	MOS/MSC	20-Mar-20	O/C	TSN 0					
SN:WQ739D	HRS	9243.7		TSN 0					
	ENC	4910		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 79 - OIL									
PROC. REF: AMM 79-21-01, MM 79-23-10, MM 79-23-10PROC. REF: AMM 79-21-01, MM 79-23-10, MM 79-23-10									
792301-0101	NO. 2 ENGINE - OIL FILTER ASSEMBLY							Component	ATA:79
PN:23087914	MOS/MSC	19-Sep-13	O/C	TSN 0					
SN:WQ419D	HRS	6680.2		TSN 0					
	ENC	3597		TSN 0					
PROC. REF: AMM 79-21-01, MM 79-23-10, MM 79-23-10PROC. REF: AMM 79-21-01, MM 79-23-10, MM 79-23-10									
792501-0101	NO. 1 ENGINE - OIL AIR COOLED COOLER							Component	ATA:79
PN:23075194	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:VR2974	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 79-25-01, MM 79-25-10, MM 79-25-10PROC. REF: AMM 79-25-01, MM 79-25-10, MM 79-25-10									
792501-0101	NO. 2 ENGINE - OIL AIR COOLED COOLER							Component	ATA:79
PN:23075194	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:VR2967	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 79-25-01, MM 79-25-10, MM 79-25-10PROC. REF: AMM 79-25-01, MM 79-25-10, MM 79-25-10									
792503-0101	NO. 1 ENGINE - OIL FUEL COOLED COOLER							Component	ATA:79
PN:23077047	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:VR3135	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 79-25-02, MM 79-25-15, MM 79-25-15PROC. REF: AMM 79-25-02, MM 79-25-15, MM 79-25-15									
792503-0101	NO. 2 ENGINE - OIL FUEL COOLED COOLER							Component	ATA:79
PN:23077047	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:VR3137	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 79-25-02, MM 79-25-15, MM 79-25-15PROC. REF: AMM 79-25-02, MM 79-25-15, MM 79-25-15									
792507-0101	NO. 1 ENGINE - NO. 1 P2.5 TRANSDUCER							Component	ATA:79
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 79 - OIL									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
792507-0101		NO. 2 ENGINE - NO. 1 P2.5 TRANSDUCER						Component	ATA:79
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
792508-0101		NO. 1 ENGINE - NO. 2 P2.5 TRANSDUCER						Component	ATA:79
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
792508-0101		NO. 2 ENGINE - NO. 2 P2.5 TRANSDUCER						Component	ATA:79
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
793000-0101		NO. 1 ENGINE - INSPECT OIL CONTAMINATION (MPG EQUIVALENT TASKS: 79-34-00-212-001-A00 AND 79-34-00-212-001-A01)						Service	ATA:79
	MOS/MSC	25-Sep-07	-						
	HRS	0							
	ENC	0							
PROC. REF: MM 79-30-00PROC. REF: MM 79-30-00									
793000-0101		NO. 2 ENGINE - INSPECT OIL CONTAMINATION (MPG EQUIVALENT TASKS: 79-34-00-212-001-A00 AND 79-34-00-212-001-A01)						Service	ATA:79
	MOS/MSC	25-Sep-07	-						
	HRS	0							
	ENC	0							
PROC. REF: MM 79-30-00PROC. REF: MM 79-30-00									
793005-0101 U		NO. 1 ENGINE -						Service	ATA:79
	MOS/MSC	25-Sep-07	N/A						
	HRS	0							
	ENC	0							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 79 - OIL									
PROC. REF: AMM 79-11-01PROC. REF: AMM 79-11-01									
793005-0101 U		NO. 2 ENGINE -						Service	ATA:79
	MOS/MSC	25-Sep-07	N/A						
	HRS	0							
	ENC	0							
PROC. REF: AMM 79-11-01PROC. REF: AMM 79-11-01									
793301-0101		NO. 1 ENGINE - LOW OIL PRESSURE SWITCH						Component	ATA:79
PN:23078098	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:KB11053	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 49-64-02, MM 79-33-10, MM 79-33-10PROC. REF: AMM 49-64-02, MM 79-33-10, MM 79-33-10									
793301-0101		NO. 2 ENGINE - LOW OIL PRESSURE SWITCH						Component	ATA:79
PN:23078098	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:KB11047	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 49-64-02, MM 79-33-10, MM 79-33-10PROC. REF: AMM 49-64-02, MM 79-33-10, MM 79-33-10									
793704-0101		NO. 1 ENGINE - MAGNETIC-INDICATE PLUG						Component	ATA:79
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 79-34-01, MM 79-37-10, MM 79-37-10PROC. REF: AMM 79-34-01, MM 79-37-10, MM 79-37-10									
793704-0101		NO. 2 ENGINE - MAGNETIC-INDICATE PLUG						Component	ATA:79
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: AMM 79-34-01, MM 79-37-10, MM 79-37-10PROC. REF: AMM 79-34-01, MM 79-37-10, MM 79-37-10									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 11276.3 AFL: 6025 As Of: 26-May-2026

26-May-2026 01:42 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 80 - STARTING									
80-10-01-720-001-A00 S	FUNCTIONALLY CHECK AIR TURBINE STARTER (ATS) INCLUDING OIL SERVICING.							Service	ATA:80
	MOS	17-Oct-25	12 (+15d/-15d)					LOW UTILIZATION	
	HRS	10913.9	500 (+20/-20)						
	AFL	5820							
									PKG:5002
PROC. REF: AMM 80-10-01PROC. REF: AMM 80-10-01									
80-10-02-160-001-A00 S	SERVICE (CLEANING) START CONTROL VALVE FILTER							Service	ATA:80
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION	
	HRS	10161.5	2000 (+20/-20)						
	AFL	5401	1000 (+20/-20)						
									PKG:5008,6016
PROC. REF: AMM 80-10-02PROC. REF: AMM 80-10-02									
801100-0101	LH ENG PNEUMATIC STARTER UNIT							Component	ATA:80
PN:3505910-6	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:2578	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									
801100-0102	RH ENG PNEUMATIC STARTER UNIT							Component	ATA:80
PN:3505910-6	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:2576	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									
801100-0201	LH ENG BUTTERFLY TYPE,STARTER SYS SHUTOFF VALVE							Component	ATA:80
PN:3215358-2	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:2313	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									
801100-0202	RH ENG BUTTERFLY TYPE,STARTER SYS SHUTOFF VALVE							Component	ATA:80
PN:3215358-2	MOS/MSC	27-Aug-07	O/C	TSN 0					
SN:2312	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: NDT GENERICPROC. REF: NDT GENERIC									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS