

OWNER: FIRE ROCK LLC
 ADDRESS: 7200 NW 63RD STREET
 BETHANY OK 73008
 OFFICE:
 FAX:

OPERATOR: PRIVATE JETS INC.
 ADDRESS: 7200 NW 63RD STREET
 BETHANY OK 73008
 OFFICE: 405-681-4466
 FAX: 405-681-1661

ANALYST: LEARJET ANALYST 1
 EMAIL: ESMITH@CAMPSYSTEMS.COM

+1-316-462-2407 (DIRECT)
 +1-631-588-3200 (MAIN)
 WWW.CAMPSYSTEMS.COM

800-787-9749 (EFAX-CARDS)
 631-980-4222 (EFAX-CARDS)

PLEASE REACH OUT TO YOUR ANALYST TO
 RECORD CHANGES TO ADDRESS, LAST ACTUALS
 (IF ANY).

AIRCRAFT	SERIAL/REGNO: 45-2027/N116PJ	MODEL: LEARJET 40XR	MANUFACTURER: BOMBARDIER AVIATION
----------	------------------------------	---------------------	-----------------------------------

CERTIFICATION DATE: 10-MAY-2005

LAST ACTUALS:
 9515.7 A/C HRS as of 11-NOV-2024
 7576 AFL as of 11-NOV-2024
 3089.7 ACH as of 15-NOV-2024

ENGINE NO. 1	SERIAL/PART: P-116596C/3060084-1	MODEL: TFE731-20BR-1B	MANUFACTURER: HONEYWELL
--------------	----------------------------------	-----------------------	-------------------------

INSTALLED ON: 17-FEB-2005
 0 ENG. HRS 0 A/C HRS
 0 ENC

LAST ACTUALS:
 9431.7 ENG. HRS as of 11-NOV-2024
 7542 ENC as of 11-NOV-2024

ENGINE NO. 2	SERIAL/PART: P-116597C/3060084-1	MODEL: TFE731-20BR-1B	MANUFACTURER: HONEYWELL
--------------	----------------------------------	-----------------------	-------------------------

INSTALLED ON: 17-FEB-2005
 0 ENG. HRS 0 A/C HRS
 0 ENC

LAST ACTUALS:
 9431.7 ENG. HRS as of 11-NOV-2024
 7542 ENC as of 11-NOV-2024

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 00 - INFORMATION										
CI40-150721	REVIEW CONCORDE EMERGENCY BATTERY CMM 5-0167 REVISION E									Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS		
	HRS									
	AFL									
					PROC. REF: RCF C140					
CI40-160527	REVIEW LEARJET 40 AMM REVISION 34									Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS		
	HRS									
	AFL									
					PROC. REF: RCF C140					
CI40-160603	REVIEW LEARJET 40 AMM TR 4-28									Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS		
	HRS									
	AFL									
					PROC. REF: RCF C140					
CI40-160613	REVIEW LEARJET 40 AMM TR 5-77									Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS		
	HRS									
	AFL									
					PROC. REF: RCF C140					
CI40-161207B	REVIEW LEARJET 40 AMM REVISION 35									Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS		
	HRS									
	AFL									
					PROC. REF: RCF C140					
CI40-181109B	REVIEW LEARJET 40/40XR AMM REVISION 39									Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS		
	HRS									
	AFL									
					PROC. REF: RCF C140					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 00 - INFORMATION										
CI40-190429A	REVIEW LEARJET 40/40XR AMM REV 40									Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS		
	HRS									
	AFL									
	PROC. REF: RCF C140									
CI40-200529	REVIEW AUDIT SUMMARY CHANGE FORM									Service ATA:00
	MOS/MSC	EFF	-					AUDIT SUMMARY CHANGE FORM		
	HRS									
	AFL									
	PROC. REF: RCF C140									
CI40-210120	REVIEW LEARJET 40/40XR AUDIT SUMMARY CHANGE FORM									Service ATA:00
	MOS/MSC	EFF	-					AUDIT SUMMARY CHANGE FORM		
	HRS									
	AFL									
	PROC. REF: RCF C140									
EC04-180802	NO. 1 ENGINE - REVIEW TFE731-20/-40/-60 (CIMMS) LMM TR 5-17									Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS		
	HRS									
	ENC									
	PROC. REF: RCF EC04-180802									
EC04-180802	NO. 2 ENGINE - REVIEW TFE731-20/-40/-60 (CIMMS) LMM TR 5-17									Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS		
	HRS									
	ENC									
	PROC. REF: RCF EC04-180802									
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS										
051101	PERFORM PHASE A1-300 HOUR CHECKS									Package ATA:05
	MOS	25-Jan-24	12 (+14d/-14d)		25-Jan-25	08-Feb-25	71 d (+14)			
	HRS	9265.8	300 (+25/-25)		9565.8	9590.8	50.1 (+25)			
	AFL	7395								
	PROC. REF: AMM 05-11-01									
										PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS										
051102	PERFORM PHASE A2-300 HOUR CHECKS									Package ATA:05
	MOS	25-Jan-24	12 (+14d/-14d)		25-Jan-25	08-Feb-25	71 d (+14)			
	HRS	9265.8	300 (+25/-25)		9565.8	9590.8	50.1 (+25)			
	AFL	7395								
					PROC. REF: AMM 05-11-02					PKG:2
051103	PERFORM PHASE A3-300 HOUR CHECKS									Package ATA:05
	MOS	25-Jan-24	12 (+14d/-14d)		25-Jan-25	08-Feb-25	71 d (+14)			
	HRS	9265.8	300 (+25/-25)		9565.8	9590.8	50.1 (+25)			
	AFL	7395								
					PROC. REF: AMM 05-11-03					PKG:3
051104	PERFORM PHASE A4-300 HOUR CHECKS									Package ATA:05
	MOS	25-Jan-24	12 (+14d/-14d)		25-Jan-25	08-Feb-25	71 d (+14)			
	HRS	9265.8	300 (+25/-25)		9565.8	9590.8	50.1 (+25)			
	AFL	7395								
					PROC. REF: AMM 05-11-04					PKG:4
051105	PERFORM PHASE A5-300 HOUR CHECKS									Package ATA:05
	MOS	25-Jan-24	12 (+14d/-14d)		25-Jan-25	08-Feb-25	71 d (+14)			
	HRS	9265.8	300 (+25/-25)		9565.8	9590.8	50.1 (+25)			
	AFL	7395								
					PROC. REF: AMM 05-11-05					PKG:5
051106	PERFORM PHASE A6-300 HOUR CHECKS									Package ATA:05
	MOS	25-Jan-24	12 (+14d/-14d)		25-Jan-25	08-Feb-25	71 d (+14)			
	HRS	9265.8	300 (+25/-25)		9565.8	9590.8	50.1 (+25)			
	AFL	7395								
					PROC. REF: AMM 05-11-06					PKG:6
051201	PERFORM PHASE B1-600 HOUR CHECKS									Package ATA:05
	MOS	25-Jan-24	24 (+14d/-14d)		25-Jan-26	08-Feb-26	436 d (+14)			
	HRS	9265.8	600 (+25/-25)		9865.8	9890.8	350.1 (+25)			
	AFL	7395								
					PROC. REF: AMM 05-12-01					PKG:7
051202	PERFORM PHASE B2-600 HOUR CHECKS									Package ATA:05
	MOS	25-Jan-24	24 (+14d/-14d)		25-Jan-26	08-Feb-26	436 d (+14)			
	HRS	9265.8	600 (+25/-25)		9865.8	9890.8	350.1 (+25)			
	AFL	7395								
					PROC. REF: AMM 05-12-02					PKG:8

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS										
051203	PERFORM PHASE B3-600 HOUR CHECKS									Package ATA:05
	MOS	25-Jan-24	24 (+14d/-14d)		25-Jan-26	08-Feb-26	436 d (+14)			
	HRS	9265.8	600 (+25/-25)		9865.8	9890.8	350.1 (+25)			
	AFL	7395								
					PROC. REF: AMM 05-12-03					PKG:9
051204	PERFORM PHASE B4-600 HOUR CHECKS									Package ATA:05
	MOS	25-Jan-24	24 (+14d/-14d)		25-Jan-26	08-Feb-26	436 d (+14)			
	HRS	9265.8	600 (+25/-25)		9865.8	9890.8	350.1 (+25)			
	AFL	7395								
					PROC. REF: AMM 05-12-04					PKG:10
051205	PERFORM PHASE B5-600 HOUR CHECKS									Package ATA:05
	MOS	25-Jan-24	24 (+14d/-14d)		25-Jan-26	08-Feb-26	436 d (+14)			
	HRS	9265.8	600 (+25/-25)		9865.8	9890.8	350.1 (+25)			
	AFL	7395								
					PROC. REF: AMM 05-12-05					PKG:11
051206	PERFORM PHASE B6-600 HOUR CHECKS									Package ATA:05
	MOS	25-Jan-24	24 (+14d/-14d)		25-Jan-26	08-Feb-26	436 d (+14)			
	HRS	9265.8	600 (+25/-25)		9865.8	9890.8	350.1 (+25)			
	AFL	7395								
					PROC. REF: AMM 05-12-06					PKG:12
051301	PERFORM PHASE C1-1200 HOUR CHECKS									Package ATA:05
	MOS	11-Mar-22	48 (+14d/-14d)		11-Mar-26	25-Mar-26	481 d (+14)			
	HRS	8721.2	1200 (+25/-25)		9921.2	9946.2	405.5 (+25)			
	AFL	7006								
					PROC. REF: AMM 05-13-01					PKG:13
051302	PERFORM PHASE C2-1200 HOUR CHECKS									Package ATA:05
	MOS	11-Mar-22	48 (+14d/-14d)		11-Mar-26	25-Mar-26	481 d (+14)			
	HRS	8721.2	1200 (+25/-25)		9921.2	9946.2	405.5 (+25)			
	AFL	7006								
					PROC. REF: AMM 05-13-02					PKG:14
051303	PERFORM PHASE C3-1200 HOUR CHECKS									Package ATA:05
	MOS	11-Mar-22	48 (+14d/-14d)		11-Mar-26	25-Mar-26	481 d (+14)			
	HRS	8721.2	1200 (+25/-25)		9921.2	9946.2	405.5 (+25)			
	AFL	7006								
					PROC. REF: AMM 05-13-03					PKG:15

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS										
051304	PERFORM PHASE C4-1200 HOUR CHECKS									Package ATA:05
	MOS	11-Mar-22	48 (+14d/-14d)		11-Mar-26	25-Mar-26	481 d (+14)			
	HRS	8721.2	1200 (+25/-25)		9921.2	9946.2	405.5 (+25)			
	AFL	7006								
	PROC. REF: AMM 05-13-04									PKG:16
051305	PERFORM PHASE C5-1200 HOUR CHECKS									Package ATA:05
	MOS	11-Mar-22	48 (+14d/-14d)		11-Mar-26	25-Mar-26	481 d (+14)			
	HRS	8721.2	1200 (+25/-25)		9921.2	9946.2	405.5 (+25)			
	AFL	7006								
	PROC. REF: AMM 05-13-05									PKG:17
051306	PERFORM PHASE C6-1200 HOUR CHECKS									Package ATA:05
	MOS	11-Mar-22	48 (+14d/-14d)		11-Mar-26	25-Mar-26	481 d (+14)			
	HRS	8721.2	1200 (+25/-25)		9921.2	9946.2	405.5 (+25)			
	AFL	7006								
	PROC. REF: AMM 05-13-06									PKG:18
051401	PERFORM PHASE D1-2400 HOUR CHECKS									Package ATA:05
	MOS	10-May-23	96 (+14d/-14d)	Adj -105d	25-Jan-31	08-Feb-31	2262 d (+14)			
	HRS	9071.3	2400 (+25/-25)	Adj -2.03	11469.27	11494.27	1953.6 (+25)			
	AFL	7252								
	PROC. REF: AMM 05-14-01									PKG:19
051402	PERFORM PHASE D2-2400 HOUR CHECKS									Package ATA:05
	MOS	10-May-23	96 (+14d/-14d)	Adj -105d	25-Jan-31	08-Feb-31	2262 d (+14)			
	HRS	9071.3	2400 (+25/-25)	Adj -2.03	11469.27	11494.27	1953.6 (+25)			
	AFL	7252								
	PROC. REF: AMM 05-14-02									PKG:20
051403	PERFORM PHASE D3-2400 HOUR CHECKS									Package ATA:05
	MOS	10-May-23	96 (+14d/-14d)	Adj -105d	25-Jan-31	08-Feb-31	2262 d (+14)			
	HRS	9071.3	2400 (+25/-25)		11471.3	11496.3	1955.6 (+25)			
	AFL	7252								
	PROC. REF: AMM 05-14-03									PKG:21
051404	PERFORM PHASE D4-2400 HOUR CHECKS									Package ATA:05
	MOS	10-May-23	96 (+14d/-14d)	Adj -105d	25-Jan-31	08-Feb-31	2262 d (+14)			
	HRS	9071.3	2400 (+25/-25)	Adj -2.03	11469.27	11494.27	1953.6 (+25)			
	AFL	7252								
	PROC. REF: AMM 05-14-04									PKG:22

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS										
051405	PERFORM PHASE D5-2400 HOUR CHECKS									Package ATA:05
	MOS	10-May-23	96 (+14d/-14d)	Adj -105d	25-Jan-31	08-Feb-31	2262 d (+14)			
	HRS	9071.3	2400 (+25/-25)	Adj -2.03	11469.27	11494.27	1953.6 (+25)			
	AFL	7252								
	PROC. REF: AMM 05-14-05									PKG:23
051406	PERFORM PHASE D6-2400 HOUR CHECKS									Package ATA:05
	MOS	10-May-23	96 (+14d/-14d)	Adj -105d	25-Jan-31	08-Feb-31	2262 d (+14)			
	HRS	9071.3	2400 (+25/-25)	Adj -2.03	11469.27	11494.27	1953.6 (+25)			
	AFL	7252								
	PROC. REF: AMM 05-14-06									PKG:24
051500	PERFORM 4800 HOUR CHECKS									Package ATA:05
	MOS	10-May-23								
	HRS	9071.3	4800 (+25/-25)		13871.3	13896.3	4355.6 (+25)			
	AFL	7252								
	PROC. REF: AMM 05-15-00									PKG:25
051600	PERFORM 9600 HOUR CHECKS									Package ATA:05
	MOS	10-May-05								
	HRS	0	9600		9600		84.3			
	AFL									
	PROC. REF: AMM 05-16-00									PKG:26
051700	PERFORM MAJOR LANDING GEAR INSPECTION									Package ATA:05
	MOS	10-May-05								
	HRS	0								
	AFL	0	10000		10000		2424			
	PROC. REF: AMM 05-17-00									PKG:27
057110	NO. 1 ENGINE - 150 TO 250 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS									Package ATA:05
	MOS	16-Oct-24								
	HRS	9408.6	250 (-100)		(9658.6) 9742.6		226.9			
	ENC	7526								
	PROC. REF: LMM 72-00-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS											
057110			NO. 2 ENGINE - 150 TO 250 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							Package	ATA:05
	MOS	16-Oct-24									
	HRS	9408.6	250 (-100)		(9658.6) 9742.6		226.9				
	ENC	7526									
PROC. REF: LMM 72-00-00											
057120			NO. 1 ENGINE - 300 TO 440 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							Package	ATA:05
	MOS/MSC	25-Jan-05	N/A								
	HRS	0									
	ENC	0									
PROC. REF: LMM 72-00-00											
057120			NO. 2 ENGINE - 300 TO 440 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							Package	ATA:05
	MOS/MSC	26-Jan-05	N/A								
	HRS	0									
	ENC	0									
PROC. REF: LMM 72-00-00											
057130			NO. 1 ENGINE - 500 TO 650 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							Package	ATA:05
	MOS	10-May-23									
	HRS	8987.3	600 (+50/-100)		(9587.3) 9671.3	9637.3	155.6 (+50)				
	ENC	7218									
PROC. REF: LMM 72-00-00											
057130			NO. 2 ENGINE - 500 TO 650 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							Package	ATA:05
	MOS	10-May-23									
	HRS	8987.3	600 (+50/-100)		(9587.3) 9671.3	9637.3	155.6 (+50)				
	ENC	7218									
PROC. REF: LMM 72-00-00											
057140			NO. 1 ENGINE - 500 TO 850 HOUR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							Package	ATA:05
	MOS	03-Jan-24									
	HRS	9174	850 (-350)		(10024) 10108		592.3				
	ENC	7357									
PROC. REF: LMM 72-00-00											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS											
057140			NO. 2 ENGINE - 500 TO 850 HOUR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS								Package ATA:05
	MOS	03-Jan-24									
	HRS	9174	850 (-350)		(10024) 10108		592.3				
	ENC	7357									
PROC. REF: LMM 72-00-00											
057150			NO. 1 ENGINE - 1000 TO 1300 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS								Package ATA:05
	MOS	03-Sep-21									
	HRS	8351.1	1200 (+100/-200)		(9551.1) 9635.1	9651.1	119.4 (+100)				
	ENC	6753									
PROC. REF: LMM 72-00-00											
057150			NO. 2 ENGINE - 1000 TO 1300 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS								Package ATA:05
	MOS	03-Sep-21									
	HRS	8351.1	1200 (+100/-200)		(9551.1) 9635.1	9651.1	119.4 (+100)				
	ENC	6753									
PROC. REF: LMM 72-00-00											
057160			NO. 1 ENGINE - 1500 TO 1650 HOUR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS								Package ATA:05
	MOS	03-Jan-24									
	HRS	9174	1600 (+50/-100)		(10774) 10858	10824	1342.3 (+50)				
	ENC	7357									
PROC. REF: LMM 72-00-00											
057160			NO. 2 ENGINE - 1500 TO 1650 HOUR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS								Package ATA:05
	MOS	03-Jan-24									
	HRS	9174	1600 (+50/-100)		(10774) 10858	10824	1342.3 (+50)				
	ENC	7357									
PROC. REF: LMM 72-00-00											
05REGISTRATION ^U			RENEW AIRCRAFT REGISTRATION								Service ATA:05
	MOS/MSC	13-Aug-16	A/R						CUSTOMER OPERATIONS REQUIREMENT		
	HRS	6857.7									
	AFL	5573									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS										
5-50-00-EV	PERFORM ENGINE VIBRATION TEST AND INSPECTION									Service ATA:05
	MOS/MSC		A/R							
	HRS									
	AFL									
PROC. REF: AMM 05-50-00										
5-50-00-FD	INSPECTION FOREIGN OBJECT DAMAGE									Service ATA:05
	MOS/MSC		O/C					O/C - ON CONDITION		
	HRS									
	AFL									
PROC. REF: AMM 05-50-00										
ATA 08 - LEVELING AND WEIGHING										
080000	WEIGHT AND BALANCE									Service ATA:08
	MOS	16-Oct-24	36 (+14d/-14d)	Adj -16d	30-Sep-27	14-Oct-27	1049 d (+14)			
	HRS	9492.6								
	AFL	7560								
PROC. REF: AMM 08-10-00, FAR 135.185										
ATA 11 - PLACARDS AND MARKINGS										
G1130000 ^S	CHECK BRIGHTNESS LEVEL OF ALL SELF-LUMINOUS PLACARDS									Service ATA:11
	MOS	11-Mar-22	48 (+14d/-14d)							
	HRS	8721.2	1200 (+25/-25)							
	AFL	7006								
PROC. REF: AMM 11-30-00										PKG:13
ATA 12 - SERVICING										
5-19-00-Q1221064	FLAP ACTUATOR JOINT (P/N 145673-1) - APPLY CORROSION PREVENTIVE COMPOUND (CPC)									Service ATA:12
	MOS/MSC	25-Jan-15	-					N/A BY PART NUMBER		
	HRS									
	AFL									
PROC. REF: AMM 12-21-03										
5-19-00-U1210004	FLAP FLEXIBLE TRANSMISSION SHAFTS - HAND LUBRICATE									Service ATA:12
	MOS	25-Jan-15								
	HRS	6669.27	4800 (+25/-25)		11469.27	11494.27	1953.6 (+25)			
	AFL	5419								
PROC. REF: AMM 12-21-03										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 12 - SERVICING											
AB1210060 ^S			MAIN LANDING GEAR UP-LOCK ACTUATOR - LUBRICATE						Service	ATA:12	
	MOS	25-Jan-24	12								
	HRS	9265.8	300								
	AFL	7395									
						PROC. REF: AMM 12-21-01				PKG:5	
O1210002 ^S			FLAP ACTUATORS - CHECK OIL LEVEL.						Service	ATA:12	
	MOS	25-Jan-24	24 (+14d/-14d)								
	HRS	9265.8	600 (+25/-25)								
	AFL	7395									
						PROC. REF: AMM 12-21-03				PKG:10	
Y1210000 ^S			NOSE LANDING GEAR SHOCK STRUT - CHECK FOR PROPER FLUID LEVEL AND INFLATION PRESSURE.						Service	ATA:12	
	MOS	25-Jan-24	12 (+14d/-14d)								
	HRS	9265.8	300 (+25/-25)								
	AFL	7395									
						PROC. REF: AMM 12-10-02				PKG:5	
Y1210001 ^S			MAIN LANDING GEAR SHOCK STRUTS - CHECK FOR PROPER FLUID LEVEL AND INFLATION PRESSURE						Service	ATA:12	
	MOS	25-Jan-24	12 (+14d/-14d)								
	HRS	9265.8	300 (+25/-25)								
	AFL	7395									
						PROC. REF: AMM 12-10-03				PKG:5	
Y1210003 ^S			LUBRICATE FLAP ACTUATOR BALLNUT						Service	ATA:12	
	MOS	25-Jan-24	12 (+14d/-14d)								
	HRS	9265.8	300 (+25/-25)								
	AFL	7395									
						PROC. REF: AMM 12-21-03				PKG:4	
Y1210005 ^S			LUBRICATE NOSE LANDING GEAR TRUNNION PIN						Service	ATA:12	
	MOS	25-Jan-24	12 (+14d/-14d)								
	HRS	9265.8	300 (+25/-25)								
	AFL	7395									
						PROC. REF: AMM 12-21-01				PKG:5	
Y1210006 ^S			LUBRICATE NOSE LANDING GEAR ACTUATOR ATTACH FITTING						Service	ATA:12	
	MOS	25-Jan-24	12 (+14d/-14d)								
	HRS	9265.8	300 (+25/-25)								
	AFL	7395									
						PROC. REF: AMM 12-21-01				PKG:5	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 12 - SERVICING											
Y1210007 ^S			CHECK NOSE AND MAIN TIRES FOR PROPER INFLATION.						Service	ATA:12	
	MOS	25-Jan-24	12 (+14d/-14d)								
	HRS	9265.8	300 (+25/-25)								
	AFL	7395									
					PROC. REF: AMM 12-10-04					PKG:5	
Y1210009 ^S			LUBRICATE NOSE GEAR DOOR HINGE						Service	ATA:12	
	MOS	25-Jan-24	12 (+14d/-14d)								
	HRS	9265.8	300 (+25/-25)								
	AFL	7395									
					PROC. REF: AMM 12-21-02					PKG:1	
Y1210011 ^S			LUBRICATE MAIN LANDING GEAR ACTUATOR JOINTS						Service	ATA:12	
	MOS	25-Jan-24	12 (+14d/-14d)								
	HRS	9265.8	300 (+25/-25)								
	AFL	7395									
					PROC. REF: AMM 12-21-01					PKG:5	
Y1210012 ^S			LUBRICATE MAIN LANDING GEAR AXLE BEAM/PISTON JOINTS						Service	ATA:12	
	MOS	25-Jan-24	12 (+14d/-14d)								
	HRS	9265.8	300 (+25/-25)								
	AFL	7395									
					PROC. REF: AMM 12-21-01					PKG:5	
Y1210013 ^S			LUBRICATE MAIN LANDING GEAR TORQUE LINKS						Service	ATA:12	
	MOS	25-Jan-24	12 (+14d/-14d)								
	HRS	9265.8	300 (+25/-25)								
	AFL	7395									
					PROC. REF: AMM 12-21-01					PKG:5	
Y1210014 ^S			LUBRICATE MAIN GEAR DOOR HINGE						Service	ATA:12	
	MOS	25-Jan-24	12 (+14d/-14d)								
	HRS	9265.8	300 (+25/-25)								
	AFL	7395									
					PROC. REF: AMM 12-21-02					PKG:5	
Y1210016 ^S			LUBRICATE PASSENGER/CREW DOOR HINGE						Service	ATA:12	
	MOS	25-Jan-24	12 (+14d/-14d)								
	HRS	9265.8	300 (+25/-25)								
	AFL	7395									
					PROC. REF: AMM 12-21-02					PKG:6	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 12 - SERVICING										
Y1210017 ^S	LUBRICATE PASSENGER/CREW DOOR PINS									Service ATA:12
	MOS	25-Jan-24	12 (+14d/-14d)							
	HRS	9265.8	300 (+25/-25)							
	AFL	7395								
					PROC. REF: AMM 12-21-02					PKG:6
Y1210018 ^S	LUBRICATE PASSENGER/CREW DOOR TENSION BOLTS									Service ATA:12
	MOS	25-Jan-24	12 (+14d/-14d)							
	HRS	9265.8	300 (+25/-25)							
	AFL	7395								
					PROC. REF: AMM 12-21-02					PKG:6
Y1210019 ^S	LUBRICATE EMERGENCY EXIT DOOR LATCHING MECHANISM									Service ATA:12
	MOS	25-Jan-24	12 (+14d/-14d)							
	HRS	9265.8	300 (+25/-25)							
	AFL	7395								
					PROC. REF: AMM 12-21-02					PKG:6
Y1210020 ^S	LUBRICATE EMERGENCY EXIT DOOR PINS									Service ATA:12
	MOS	25-Jan-24	12 (+14d/-14d)							
	HRS	9265.8	300 (+25/-25)							
	AFL	7395								
					PROC. REF: AMM 12-21-02					PKG:6
Y1210021 ^S	LUBRICATE BAGGAGE COMPARTMENT DOOR LATCH PINS									Service ATA:12
	MOS	25-Jan-24	12 (+14d/-14d)							
	HRS	9265.8	300 (+25/-25)							
	AFL	7395								
					PROC. REF: AMM 12-21-02					PKG:6
Y1210022 ^S	LUBRICATE BAGGAGE COMPARTMENT DOOR HINGE									Service ATA:12
	MOS	25-Jan-24	12 (+14d/-14d)							
	HRS	9265.8	300 (+25/-25)							
	AFL	7395								
					PROC. REF: AMM 12-21-02					PKG:6
Y1210023 ^S	LUBRICATE OXYGEN SYSTEM SERVICING DOOR HINGE									Service ATA:12
	MOS	25-Jan-24	12 (+14d/-14d)							
	HRS	9265.8	300 (+25/-25)							
	AFL	7395								
					PROC. REF: AMM 12-21-02					PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 12 - SERVICING											
Y1210024 ^S			LUBRICATE TOILET SERVICING DOOR HINGE						Service	ATA:12	
	MOS	25-Jan-24	12 (+14d/-14d)								
	HRS	9265.8	300 (+25/-25)								
	AFL	7395									
					PROC. REF: AMM 12-21-02					PKG:4	
Y1210025 ^S			LUBRICATE PRESSURE REFUELING DOOR HINGE						Service	ATA:12	
	MOS	25-Jan-24	12 (+14d/-14d)								
	HRS	9265.8	300 (+25/-25)								
	AFL	7395									
					PROC. REF: AMM 12-21-02					PKG:2	
Y1210026 ^S			LUBRICATE FUSELAGE FUEL FILLER DOOR HINGE						Service	ATA:12	
	MOS	25-Jan-24	12 (+14d/-14d)								
	HRS	9265.8	300 (+25/-25)								
	AFL	7395									
					PROC. REF: AMM 12-21-02					PKG:2	
Y1210027 ^S			LUBRICATE TAILCONE ACCESS DOOR PINS						Service	ATA:12	
	MOS	25-Jan-24	12 (+14d/-14d)								
	HRS	9265.8	300 (+25/-25)								
	AFL	7395									
					PROC. REF: AMM 12-21-02					PKG:6	
Y1210028 ^S			LUBRICATE TAILCONE ACCESS DOOR HINGE						Service	ATA:12	
	MOS	25-Jan-24	12 (+14d/-14d)								
	HRS	9265.8	300 (+25/-25)								
	AFL	7395									
					PROC. REF: AMM 12-21-02					PKG:6	
Y1210029 ^S			LUBRICATE MAIN LANDING GEAR TRUNNION PIN						Service	ATA:12	
	MOS	25-Jan-24	12 (+14d/-14d)								
	HRS	9265.8	300 (+25/-25)								
	AFL	7395									
					PROC. REF: AMM 12-21-01					PKG:5	
Y1221037 ^S			FLAPS - LUBRICATE ROLLING SURFACES OF MAIN AND NOSE ROLLER TRACKS.						Service	ATA:12	
	MOS	25-Jan-24	12 (+14d/-14d)								
	HRS	9265.8	300 (+25/-25)								
	AFL	7395									
					PROC. REF: AMM 12-21-03					PKG:4	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 12 - SERVICING											
Y1221042 ^S		LUBRICATE HORIZONTAL STABILIZER UPPER AND LOWER TORQUE LINKS								Service	ATA:12
	MOS	25-Jan-24	24 (+14d/-14d)								
	HRS	9265.8	600 (+25/-25)								
	AFL	7395									
PROC. REF: AMM 12-21-03										PKG:9	
Y1227000 ^S		LUBRICATE EMERGENCY PARK BRAKE HANDLE SHAFT								Service	ATA:12
	MOS	25-Jan-24	12 (+14d/-14d)								
	HRS	9265.8	300 (+25/-25)								
	AFL	7395									
PROC. REF: AMM 12-27-00										PKG:1	
ATA 21 - AIR CONDITIONING											
212011		NO. 1 EMERGENCY PRESSURIZATION CHECK VALVE								Component	ATA:21
PN:6621000000-043	MOS/MSC	10-May-05	O/C	TSN 0							
SN:2581	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 21-20-03											
212012		NO.2 EMERGENCY PRESSURIZATION CHECK VALVE								Component	ATA:21
PN:6621000000-043	MOS/MSC	10-May-05	O/C	TSN 0							
SN:2588	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 21-20-03											
212810		ASSY, AVIONICS COOLING FAN MOUNT								Component	ATA:21
PN:4521208521-009	MOS/MSC	10-May-05	O/C	TSN 0							
SN:A00318352C	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 21-21-01											
213000		CABIN PRESSURE CONTROLLER								Component	ATA:21
PN:6621300000-029	MOS/MSC	10-May-05	O/C	TSN 0							
SN:50-H0130	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 21-30-03											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 21 - AIR CONDITIONING											
213001		LEFT EMERGENCY PRESSURE SHUTOFF VALVE								Component	ATA:21
PN:3291224-1	MOS/MSC	08-Apr-22	O/C								
SN:710	HRS	8768									
	AFL	7041									
PROC. REF: AMM 21-31-01											
213002		RIGHT EMERGENCY PRESSURE SHUTOFF VALVE								Component	ATA:21
PN:3291224-1	MOS/MSC	08-Apr-22	O/C								
SN:717	HRS	8768									
	AFL	7041									
PROC. REF: AMM 21-31-01											
213031		PRIMARY OUTFLOW VALVE								Component	ATA:21
PN:103858-1	MOS/MSC	10-May-05	O/C	TSN 0							
SN:104-A0334	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 21-30-01											
213032		SECONDARY OUTFLOW VALVE								Component	ATA:21
PN:103858-2	MOS/MSC	03-Jun-13	O/C								
SN:86-B0004	HRS	5513.02									
	AFL	4486									
PROC. REF: AMM 21-30-02											
213055		EMERGENCY PRESSURE ANEROID SWITCH								Component	ATA:21
PN:E45C-47	MOS/MSC	10-May-05	O/C	TSN 0							
SN:4978	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
213105		TAILCONE CHECK CABIN PRESS VALVE								Component	ATA:21
PN:130158-3-1	MOS/MSC	10-May-05	O/C	TSN 0							
SN:94-A0631	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
215004		WATER SEPARATOR ASSEMBLY								Component	ATA:21
PN:2341168-1	MOS/MSC	10-May-05	O/C	TSN 0							
SN:408	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 21-50-03											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 21 - AIR CONDITIONING										
215005 (KEITH PRODUCTS) PALLET AIR CONDITIONING COMPRESSOR ASSEMBLY										Component ATA:21
PN:45-0550-1	MOS/MSC	10-May-05	O/C	TSN 0						
SN:K11576	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
215007 (R-134) AIR CONDITIONING COMPRESSOR DRIVE MOTOR										Component ATA:21
PN:ES61110-4	MOS	25-Jan-15		TSO 0						
SN:083	HRS	6669.27		TSO 0						
	AFL	5419		TSO 0						
	ACH	2522.3	1200 (+25/-25)	TSO 0	3722.3	3747.3	632.6 (+25)			
PROC. REF: AMM 21-51-02										
215007A (R-134) AIR CONDITIONING COMPRESSOR DRIVE MOTOR BRUSHES - PERFORM WEAR INSPECTION (IRN L2150054)										Service ATA:21
PN:ES61110-4	MOS	19-Feb-21								
SN:083	HRS	8188.7								
	AFL	6601								
	ACH	2906.2	600 (+25/-25)		3506.2	3531.2	416.5 (+25)			
PROC. REF: AMM 21-51-00										
215019 (KEITH PRODUCTS) AIR CONDITIONING CONDENSOR ASSEMBLY										Component ATA:21
PN:45-0350-1	MOS/MSC	10-May-05	O/C	TSN 0						
SN:K11695	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-51-04										
215024 (KEITH PRODUCTS) AIR CONDITIONING MAINTENANCE PANEL										Component ATA:21
PN:45-1756-1	MOS/MSC	10-May-05	O/C	TSN 0						
SN:L11366	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
215030 ENVIRONMENTAL CONTROL UNIT										Component ATA:21
PN:6621000000-081	MOS/MSC	10-May-05	O/C	TSN 0						
SN:075C-0108	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-50-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 21 - AIR CONDITIONING										
215051 (KEITH PRODUCTS) AIR CONDITIONER ASSEMBLY LOAD SHED										Component ATA:21
PN:45-0755-1	MOS/MSC	10-May-05	O/C	TSN 0						
SN:K11240	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-51-12										
215052 FWD (KEITH PRODUCTS) AIR CONDITIONING ASSEMBLY EVAPORATOR										Component ATA:21
PN:45-0250-2	MOS/MSC	10-May-05	O/C	TSN 0						
SN:K11474	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
215053 AFT AIR CONDITIONING ASSEMBLY(KEITH PRODUCTS) EVAPORATOR										Component ATA:21
PN:45-0263-1	MOS/MSC	10-May-05	O/C	TSN 0						
SN:K11450	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
215054 AUX (KEITH PRODUCTS) HEATER ASSEMBLY										Component ATA:21
PN:45-0264-1	MOS/MSC	10-May-05	O/C	TSN 0						
SN:K11500	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-51-13										
215055 FWD EVAPORATOR ASSEMBLY MOTOR										Component ATA:21
PN:ES61136-2	MOS/MSC	10-May-05	O/C	TSN 0						
SN:0920	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
215056 AFT EVAPORATOR ASSEMBLY MOTOR										Component ATA:21
PN:ES61136-2	MOS/MSC	10-May-05	O/C	TSN 0						
SN:0908	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
216001 INTEGRATED ECS TEMP CONTROLLER										Component ATA:21
PN:1151830-3	MOS/MSC	10-May-05	O/C	TSN 0						
SN:1151830-00681	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-60-10										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 21 - AIR CONDITIONING										
216013	COCKPIT TEMPERATURE CONTROL VALVE									Component ATA:21
PN:662100000-047	MOS/MSC	10-May-05	O/C	TSN 0						
SN:735	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-60-05										
216014	CABIN TEMPERATURE CONTROL VALVE									Component ATA:21
PN:3291222-1	MOS/MSC	31-Dec-19	O/C							
SN:964	HRS	7795								
	AFL	6296								
PROC. REF: AMM 21-60-04										
5-19-00-Y2130065	LEAKAGE TEST CABIN PRESSURIZATION SYSTEM (IRN W2130065)									Service ATA:21
	MOS	03-Nov-22								
	HRS	8950.9	1200 (+25/-25)		10150.9	10175.9	635.2 (+25)			
	AFL	7175								
PROC. REF: AMM 21-30-00										
5-19-01-Y2141002	REPLACE WATER SEPARATOR COALESCER BAG (IRN Y2141002)									Service ATA:21
	MOS/MSC	04-Aug-05	-							
	HRS	31.7								
	AFL	22								
PROC. REF: GENERIC NO REF										
J2160008 ^S	TEMPERATURE CONTROL SYSTEM - INSPECT AND CLEAN CABIN AND COCKPIT TEMPERATURE CONTROL VALVE SERVO AIR FILTERS.									Service ATA:21
	MOS	25-Jan-24	24 (+14d/-14d)							
	HRS	9265.8	600 (+25/-25)							
	AFL	7395								
PROC. REF: AMM 21-60-11										
L2150056 ^S	** AUXILIARY HEAT SYSTEM - PERFORM FUNCTIONAL TEST. (AWL**)									Service ATA:21
	MOS	25-Jan-24	24 (+14d/-14d)					AIRWORTHINESS		
	HRS	9265.8	600 (+25/-25)							
	AFL	7395								
PROC. REF: AMM 21-51-00										
L2150057 ^S	** AUXILIARY HEAT SYSTEM - PERFORM AUXILIARY HEATER ELECTRICAL AND TEMPERATURE TEST (AWL**)									Service ATA:21
	MOS	11-Mar-22	48 (+14d/-14d)					AIRWORTHINESS		
	HRS	8721.2	1200 (+25/-25)							
	AFL	7006								
PROC. REF: AMM 21-51-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 21 - AIR CONDITIONING										
O2130000^S PRIMARY AND SECONDARY OUTFLOW VALVES - PERFORM INSPECTION. Service ATA:21										
	MOS	11-Mar-22	48 (+14d/-14d)							
	HRS	8721.2	1200 (+25/-25)							
	AFL	7006								
PROC. REF: AMM 21-30-01, AMM 21-30-02										PKG:13
O2130001^S REPLACE OUTFLOW VALVE AIR FILTER - REMOVE AND REPLACE. Service ATA:21										
	MOS	10-May-23	96 (+14d/-14d)							
	HRS	9071.3	2400 (+25/-25)							
	AFL	7252								
PROC. REF: AMM 21-30-04										PKG:19
O2130002^S ** PRESSURIZATION CONTROL SYSTEM - PERFORM FUNCTIONAL TEST. (AWL **) Service ATA:21										
	MOS	11-Mar-22	48 (+14d/-14d)					AIRWORTHINESS		
	HRS	8721.2	1200 (+25/-25)							
	AFL	7006								
PROC. REF: AMM 21-30-00										PKG:13
Y2130003^S PRESSURIZATION CONTROL SYSTEM - PERFORM OPERATIONAL CHECK Service ATA:21										
	MOS	25-Jan-24	24 (+14d/-14d)							
	HRS	9265.8	600 (+25/-25)							
	AFL	7395								
PROC. REF: AMM 21-30-00										PKG:7
Y2140000^S AIR CYCLE MACHINE HEAT EXCHANGER INLET - PERFORM VISUAL INSPECTION Service ATA:21										
	MOS	11-Mar-22	48 (+14d/-14d)							
	HRS	8721.2	1200 (+25/-25)							
	AFL	7006								
PROC. REF: GENERIC NO REF										PKG:14
Y2141000^S ENVIRONMENTAL CONTROL UNIT - PERFORM VISUAL INSPECTION Service ATA:21										
	MOS	11-Mar-22	48 (+14d/-14d)							
	HRS	8721.2	1200 (+25/-25)							
	AFL	7006								
PROC. REF: GENERIC NO REF										PKG:14
Y2141001^S WATER SEPARATOR COALESCER BAG - PERFORM VISUAL INSPECTION. CLEAN IF NECESSARY. Service ATA:21										
	MOS	25-Jan-24	12 (+14d/-14d)							
	HRS	9265.8	300 (+25/-25)							
	AFL	7395								
PROC. REF: AMM 21-50-03										PKG:2

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 21 - AIR CONDITIONING										
Y2142000^S PERFORM BAGGAGE COMPARTMENT HEATING SYSTEM - FUNCTIONAL TEST Service ATA:21										
	MOS	10-May-23	96 (+14d/-14d)							
	HRS	9071.3	2400 (+25/-25)							
	AFL	7252								
PROC. REF: AMM 21-40-00										PKG:20
Y2145000^S ECS PLENUM ASSEMBLY CHECK VALVES - PERFORM VISUAL INSPECTION. VERIFY FREEDOM OF MOVEMENT OF BUTTERFLY ASSEMBLY. Service ATA:21										
	MOS	11-Mar-22	48 (+14d/-14d)							
	HRS	8721.2	1200 (+25/-25)							
	AFL	7006								
PROC. REF: AMM 21-20-09										PKG:14
Y2150058^S PERFORM VISUAL INSPECTION OF THE AIR CONDITIONING SYSTEM COMPONENTS, INCLUDING COMPRESSOR MOTOR BELT FOR WEAR AND PROPER V-BELT TENSION, CONDENSER COILS FOR CLEANLINESS AND HOSES FOR CHAFING AND WEAR. IF OIL LEAKS ARE VISIBLE AND/OR REFRIGERANT DUMPED, CHECK COMPRESSOR OIL LEVEL (SOME LEAKAGE IS ALLOWABLE AROUND THE SHAFT.) Service ATA:21										
	MOS	11-Mar-22	48 (+14d/-14d)							
	HRS	8721.2	1200 (+25/-25)							
	AFL	7006								
PROC. REF: GENERIC NO REF										PKG:14
Y2150059^S AIR CONDITIONING SYSTEM - PERFORM LOAD SHED ASSEMBLY CHECK Service ATA:21										
	MOS	11-Mar-22	48 (+14d/-14d)							
	HRS	8721.2	1200 (+25/-25)							
	AFL	7006								
PROC. REF: AMM 21-51-00										PKG:14
ATA 22 - AUTO FLIGHT										
221001 AUTOPILOT FLIGHT GUIDANCE CONTROLLER Component ATA:22										
PN:7021170-901	MOS/MSC	06-Apr-11	O/C							
SN:97100248	HRS	4134.42								
	AFL	3382								
PROC. REF: AMM 22-10-01										
221041 AUTOPILOT ROLL SERVO Component ATA:22										
PN:4006719-948	MOS/MSC	13-Dec-21	O/C							
SN:97019207	HRS	8647.8								
	AFL	6960								
PROC. REF: AMM 22-10-04										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 22 - AUTO FLIGHT										
221045	AILERON SERVO BRACKET									Component ATA:22
PN:4005842	MOS/MSC	10-May-05	O/C	TSN 0						
SN:04107574	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 22-10-05										
221051	AUTOPILOT PITCH SERVO									Component ATA:22
PN:4006719-908	MOS/MSC	10-May-05	O/C	TSN 0						
SN:04078769	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 22-10-02										
221055	PITCH SERVO BRACKET									Component ATA:22
PN:4005842	MOS/MSC	10-May-05	O/C	TSN 0						
SN:04067332	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 22-10-03										
221061	AUTOPILOT YAW SERVO									Component ATA:22
PN:7012919-904	MOS/MSC	10-May-05	O/C	TSN 0						
SN:01100509	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 22-10-06										
221065	SERVO, YAW BRACKET									Component ATA:22
PN:7012098-902	MOS/MSC	10-May-05	O/C	TSN 0						
SN:04080540	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 22-10-07										
225001	YAW INTERFACE UNIT									Component ATA:22
PN:4522108501-011	MOS/MSC	10-May-05	O/C	TSN 0						
SN:MRP306891-01	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 22-50-01										
A2210033 ^S	** AUTOPILOT SYSTEM - PERFORM AUTOPILOT DISCONNECT TONE TEST. (AWL**)									Service ATA:22
	MOS	25-Jan-24	24 (+14d/-14d)					AIRWORTHINESS		
	HRS	9265.8	600 (+25/-25)							
	AFL	7395								
PROC. REF: AMM 22-10-00										
										PKG: 7

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 22 - AUTO FLIGHT											
G2210030 ^S		PITCH SERVO CABLES - PERFORM CABLE TENSION CHECK							Service	ATA:22	
	MOS	11-Mar-22	48 (+14d/-14d)								
	HRS	8721.2	1200 (+25/-25)								
	AFL	7006									
							PROC. REF: AMM 22-10-03			PKG:14	
G2210031 ^S		ROLL SERVO CABLES - PERFORM CABLE TENSION CHECK							Service	ATA:22	
	MOS	11-Mar-22	48 (+14d/-14d)								
	HRS	8721.2	1200 (+25/-25)								
	AFL	7006									
							PROC. REF: AMM 22-10-05			PKG:13	
G2210032 ^S		YAW SERVO CABLES - PERFORM CABLE TENSION CHECK							Service	ATA:22	
	MOS	11-Mar-22	48 (+14d/-14d)								
	HRS	8721.2	1200 (+25/-25)								
	AFL	7006									
							PROC. REF: AMM 22-10-07			PKG:14	
ATA 23 - COMMUNICATIONS											
230013		ANTENNA SPLITTER							Component	ATA:23	
PN:DMH21-1	MOS/MSC	10-May-05	O/C	TSN 0							
SN:30072	HRS	0		TSN 0							
	AFL	0		TSN 0							
							PROC. REF: AMM 34-30-03				
231011		NO. 1 POWER AMPLIFIER/HF ANTENNA COUPLER							Component	ATA:23	
PN:064-1017-01	MOS/MSC	08-Apr-13	O/C								
SN:16738	HRS	5470.47									
	AFL	4452									
							PROC. REF: GENERIC NO REF				
231021		NO. 1 INTEGRATED COMM/ATC UNIT							Component	ATA:23	
PN:7517400-932	MOS/MSC	21-Mar-23	O/C								
SN:98112319	HRS										
	AFL										
							PROC. REF: GENERIC NO REF				
231021A		RECERTIFY NO. 1 INTEGRATED COMM/ATC UNIT TRANSPONDER - FAR 91.413							Service	ATA:23	
	MOS	21-Mar-23	24		21-Mar-25		126 d				
	HRS										
	AFL										
							PROC. REF: GENERIC NO REF, FAR SUBPART E				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 23 - COMMUNICATIONS										
231022	NO. 2 INTEGRATED COMM/ATC UNIT									Component ATA:23
PN:7517400-932	MOS/MSC	21-Mar-23	O/C							
SN:05028807	HRS									
	AFL									
PROC. REF: GENERIC NO REF										
231022A	RECERTIFY NO. 2 INTEGRATED COMM/ATC UNIT TRANSPONDER - FAR 91.413									Service ATA:23
	MOS	21-Mar-23	24		21-Mar-25		126 d			
	HRS									
	AFL									
PROC. REF: GENERIC NO REF, FAR SUBPART E										
231023	NO.1 STRAP BOARD NAV									Component ATA:23
PN:4523180820-2027-001	MOS/MSC	10-May-05	O/C	TSN 0						
SN:A00587725-01	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-11-03										
231024	NO.2 STRAP BOARD NAV									Component ATA:23
PN:4523180820-2017-005	MOS/MSC	10-May-05	O/C	TSN 0						
SN:A00587764-1	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-11-03										
231029	HF RECEIVER/EXCITER									Component ATA:23
PN:064-1015-01	MOS/MSC	01-Feb-15	O/C							
SN:32609	HRS	6678.12								
	AFL	5426								
PROC. REF: GENERIC NO REF										
231033	UPPER VHF ANTENNA									Component ATA:23
PN:DMC60-17-1	MOS/MSC	27-Oct-11	O/C							
SN:16307	HRS	4469.73								
	AFL	3671								
PROC. REF: AMM 23-11-02										
231034	LOWER VHF ANTENNA									Component ATA:23
PN:DMC60-17-1	MOS/MSC	27-Oct-11	O/C							
SN:16308	HRS	4469.73								
	AFL	3671								
PROC. REF: AMM 23-11-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 23 - COMMUNICATIONS											
231035		NO.1 STRAP BOARD COMM							Component	ATA:23	
PN:4523180820-2017-003	MOS/MSC	10-May-05	O/C	TSN 0							
SN:A00587707-01	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 23-11-03											
231036		NO.2 STRAP BOARD COMM							Component	ATA:23	
PN:4523180820-2017-007	MOS/MSC	10-May-05	O/C	TSN 0							
SN:A00587782-01	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 23-11-03											
231045		NO. 1 HF CONTROL							Component	ATA:23	
PN:064-1016-03	MOS/MSC	25-Jan-12	O/C								
SN:11177	HRS	4667.67									
	AFL	3815									
PROC. REF: GENERIC NO REF											
231505 ^U		IRIDIUM SATCOM PHONE BASE UNIT CORDLESS							Component	ATA:23	
PN:9L8810A-B	MOS/MSC	03-Apr-11	O/C								
SN:250211	HRS	4129.55									
	AFL	3376									
231510 ^U		IRIDIUM SATCOM TRANSCEIVER							Component	ATA:23	
PN:500617-2	MOS/MSC	18-Jul-05	O/C	TSN 0							
SN:5231	HRS	18.9		TSN 0							
	AFL	15		TSN 0							
231510A ^U		GENERAL VISUAL INSPECTION MOUNTING AND RETAINING HARDWARE. CHECK FOR SECURITY OF ATTACHMENT AND OTHER DEFECTS							Service	ATA:23	
PN:500617-2	MOS	11-Mar-22	48		11-Mar-26		481 d				
SN:5231	HRS	8721.2	1200		9921.2		405.5				
	AFL	7006									
231515 ^U		IRIDIUM SATCOM ANTENNA							Component	ATA:23	
PN:C1490-1	MOS/MSC	18-Jul-05	O/C	TSN 0							
SN:5033798	HRS	18.9		TSN 0							
	AFL	15		TSN 0							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 23 - COMMUNICATIONS											
231515A ^U		GENERAL VISUAL INSPECTION IRIDIUM SATCOM ANTENNA MOUNTAINING AND RETAINING HARDWARE. CHECK FOR SECURITY OF ATTACHMENT AND OTHER DEFECTS							Service	ATA:23	
PN:C1490-1	MOS	11-Mar-22	48		11-Mar-26		481 d				
SN:5033798	HRS	8721.2	1200		9921.2		405.5				
	AFL	7006									
<hr/>											
233014		1-R CABIN STEREO SPEAKER							Component	ATA:23	
PN:6623308507-001	MOS/MSC	18-Jul-05	O/C	TSN 0							
SN:040500488	HRS	18.9		TSN 0							
	AFL	15		TSN 0							
PROC. REF: AMM 23-30-01											
<hr/>											
233015		2-R CABIN STEREO SPEAKER							Component	ATA:23	
PN:6623308507-001	MOS/MSC	18-Jul-05	O/C	TSN 0							
SN:040500589	HRS	18.9		TSN 0							
	AFL	15		TSN 0							
PROC. REF: AMM 23-30-01											
<hr/>											
233016		2-L CABIN STEREO SPEAKER							Component	ATA:23	
PN:6623308507-001	MOS/MSC	18-Jul-05	O/C	TSN 0							
SN:040500490	HRS	18.9		TSN 0							
	AFL	15		TSN 0							
PROC. REF: AMM 23-30-01											
<hr/>											
233017		1-L CABIN STEREO SPEAKER							Component	ATA:23	
PN:6623308507-001	MOS/MSC	18-Jul-05	O/C	TSN 0							
SN:040500481	HRS	18.9		TSN 0							
	AFL	15		TSN 0							
PROC. REF: AMM 23-30-01											
<hr/>											
233025		SUB WOOFER SPEAKER							Component	ATA:23	
PN:EN-646-W	MOS/MSC	10-May-05	O/C	TSN 0							
SN:040500044	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 23-30-01											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 23 - COMMUNICATIONS											
233043		PA AMPLIFIER								Component	ATA:23
PN:PA-7501-01-1	MOS/MSC	10-May-05	O/C	TSN 0							
SN:060400501	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 23-30-02											
235001		PILOT AUDIO CONTROL UNIT								Component	ATA:23
PN:7511001-937	MOS/MSC	03-Sep-14	O/C								
SN:05019873	HRS	6427.53									
	AFL	5233									
PROC. REF: AMM 23-50-01											
235002		COPILOT AUDIO CONTROL UNIT								Component	ATA:23
PN:4523558501-003	MOS/MSC	03-Sep-14	O/C								
SN:05064203	HRS	6427.53									
	AFL	5233									
PROC. REF: AMM 23-50-01											
237001		COCKPIT VOICE RECORDER								Component	ATA:23
PN:980-6020-011	MOS/MSC	10-May-05	O/C	TSN 0							
SN:CVR30-04088	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 23-70-01											
237002		CD CHANGER								Component	ATA:23
PN:MCD-102-RU-3	MOS/MSC	18-Jul-05	O/C	TSN 0							
SN:030500239	HRS	18.9		TSN 0							
	AFL	15		TSN 0							
PROC. REF: GENERIC NO REF											
237005		CVR UNDERWATER LOCATOR BEACON								Component	ATA:23
PN:DK120	MOS/MSC	08-Mar-24	O/C	TSN 24							
SN:AT169093	HRS	9292.2		TSN 571							
	AFL	7418		TSN 412							
PROC. REF: AMM 25-61-01											
237005A		CLEAN CVR UNDERWATER LOCATOR BEACON SWITCH, AND PERFORM OPERATIONAL CHECK AND TEST OF ULB BATTERY (AA2560000)								Service	ATA:23
PN:DK120	MOS	08-Mar-24	24 (+14d/-14d)	Adj 3d	11-Mar-26	25-Mar-26	481 d (+14)				
SN:AT169093	HRS	9292.2									
	AFL	7418									
PROC. REF: AMM 25-61-01											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 23 - COMMUNICATIONS											
237005B		REPLACE CVR UNDERWATER LOCATOR BEACON BATTERY (D2566001)								Service	ATA:23
PN:DK120	MOS/MSC	11-Mar-22	DUE		30-Jun-28 (M)		1323 d	LIFE LIMIT			
SN:AT169093	HRS	8721.2									
	AFL	7006									
PROC. REF: GENERIC NO REF											
237005C		RECERTIFY CVR UNDERWATER LOCATOR BEACON								Service	ATA:23
PN:DK120	MOS	08-Mar-24	216 (+14d/-14d)		08-Mar-42		22-Mar-42	6322 d (+14)			
SN:AT169093	HRS	9292.2									
	AFL	7418									
PROC. REF: GENERIC NO REF											
237019		COCKPIT AREA MICROPHONE								Component	ATA:23
PN:980-6113-001	MOS/MSC	10-May-05	O/C	TSN 0							
SN:03374	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
237034		CVR PRE-AMPLIFIER								Component	ATA:23
PN:980-6118-001	MOS/MSC	10-May-05	O/C	TSN 0							
SN:CAMP-RAMP-00554	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 23-70-03											
238001		NO. 1 RADIO MANAGEMENT UNIT								Component	ATA:23
PN:7013270-985	MOS/MSC	04-Dec-19	O/C								
SN:01130471	HRS	7762.1									
	AFL	6271									
PROC. REF: AMM 23-80-01											
238002		NO. 2 RADIO MANAGEMENT UNIT								Component	ATA:23
PN:7013270-965	MOS/MSC	04-Dec-19	O/C								
SN:04124627	HRS	7762.1									
	AFL	6271									
PROC. REF: AMM 23-80-01											
238025		CLEARANCE DELIVERY UNIT								Component	ATA:23
PN:7513000-835	MOS/MSC	10-May-05	O/C	TSN 0							
SN:04112863	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 23-82-01											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 23 - COMMUNICATIONS											
A2300000 ^S		** COMMUNICATIONS SYSTEMS - PERFORM OPERATIONAL CHECK. (AWL**)								Service	ATA:23
	MOS	25-Jan-24	24 (+14d/-14d)					AIRWORTHINESS			
	HRS	9265.8	600 (+25/-25)								
	AFL	7395									
PROC. REF: AMM 23-00-00										PKG:7	
NC23155001-SMM ^U		DETAILED VISUAL INSPECTION IRIDIUM SATCOM ANTENNA SKIN CUTOUT AND DOUBLER								Service	ATA:23
	MOS	10-May-05									
	HRS	0									
	AFL	0	T:10000		10000		2424				
NC23155001-SMM-A ^U		FUNCTIONAL TEST IRIDIUM SATELITE COMMUNICATIONS PHONE SYSTEM								Service	ATA:23
	MOS	25-Jan-24	24		25-Jan-26		436 d				
	HRS	9265.8	600		9865.8		350.1				
	AFL	7395									
NC23155001-SMM-B ^U		PERFORM A GENERAL VISUAL INSPECTION OF THE TRANSCEIVER MOUNTING AND RETAINING HARDWARE. CHECK FOR SECURITY OF ATTACHMENT AND OTHER DEFECTS								Service	ATA:23
	MOS	22-Apr-24	48		22-Apr-28		1254 d				
	HRS	9368.9	1200		10568.9		1053.2				
	AFL	7476									
NC23155001-SMM-C ^U		PERFORM A GENERAL VISUAL INSPECTION OF THE COCKPIT PHONE MOUNTING AND RETAINING HARDWARE. CHECK FOR SECURITY OF ATTACHMENT AND OTHER DEFECTS.								Service	ATA:23
	MOS	22-Apr-24	48		22-Apr-28		1254 d				
	HRS	9368.9	1200		10568.9		1053.2				
	AFL	7476									
NC23155001-SMM-D ^U		PERFORM A GENERAL VISUAL INSPECTION OF THE CABIN HANDSET AND BASE UNIT, AND RETAINING HARDWARE. CHECK FOR SECURITY OF ATTACHMENT AND OTHER DEFECTS.								Service	ATA:23
	MOS	22-Apr-24	48		22-Apr-28		1254 d				
	HRS	9368.9	1200		10568.9		1053.2				
	AFL	7476									
NC23155001-SMM-E ^U		PERFORM A GENERAL VISUAL INSPECTION OF THE ANTENNA AND RETAINING HARDWARE. CHECK FOR SECURITY OF ATTACHMENT AND OTHER DEFECTS.								Service	ATA:23
	MOS	22-Apr-24	48		22-Apr-28		1254 d				
	HRS	9368.9	1200		10568.9		1053.2				
	AFL	7476									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 23 - COMMUNICATIONS											
NC23155001-SMM-F ^U		GENERAL VISUAL INSPECTION IRIDIUM SATELITE COMMUNICATIONS PHONE SYSTEM CONNECTORS AND WIRING FOR CHAFING, DAMAGE, SECURITY OF ATTACHMENT, AND OTHER DEFECTS							Service	ATA:23	
	MOS	22-Apr-24	48		22-Apr-28		1254 d				
	HRS	9368.9	1200		10568.9		1053.2				
	AFL	7476									
V2312003 ^S		HF ANTENNA- PERFORM VISUAL INSPECTION. CHECK FOR PROPER TENSION ON HF ANTENNA WIRE							Service	ATA:23	
	MOS	11-Mar-22	48 (+14d/-14d)								
	HRS	8721.2	1200 (+25/-25)								
	AFL	7006									
PROC. REF: AMM 23-12-04										PKG:14	
Y2360020 ^S		AIRCRAFT STATIC DISCHARGERS - PERFORM FUNCTIONAL TEST							Service	ATA:23	
	MOS	10-May-23	96 (+14d/-14d)								
	HRS	9071.3	2400 (+25/-25)								
	AFL	7252									
PROC. REF: AMM 23-60-00										PKG:20	
Y2360023 ^S		AIRCRAFT STATIC DISCHARGERS - PERFORM FUNCTIONAL TEST							Service	ATA:23	
	MOS	10-May-23	96 (+14d/-14d)								
	HRS	9071.3	2400 (+25/-25)								
	AFL	7252									
PROC. REF: AMM 23-60-00										PKG:22	
ATA 24 - ELECTRICAL POWER											
240101		PILOT CIRCUIT BREAKER PANEL							Component	ATA:24	
PN:4531180817-2027-001	MOS/MSC	10-May-05	O/C	TSN 0							
SN:A00587710-01	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 24-60-01											
240102		COPILOT CIRCUIT BREAKER PANEL							Component	ATA:24	
PN:4531180818-2027-001	MOS/MSC	10-May-05	O/C	TSN 0							
SN:A0058776-01	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 24-60-01											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 24 - ELECTRICAL POWER										
242001	NO. 1 AC 5KVA ALTERNATOR									Component ATA:24
PN:90278-2	MOS/MSC	27-May-24	O/C	TSO 0						
SN:1185	HRS	9381.4		TSO 0						
	AFL	7483		TSO 0						
PROC. REF: AMM 24-20-01										
242001A	NO. 1 AC 5KVA ALTERNATOR ** REPLACE BEARINGS (IRN F2420000) (AWL**)									Service ATA:24
PN:90278-2	MOS	27-May-24						LIFE LIMIT		
SN:1185	HRS	9381.4	1200 (+25/-25)		10581.4	10606.4	1065.7 (+25)			
	AFL	7483								
PROC. REF: AMM 24-20-01										
242002	NO. 2 AC 5KVA ALTERNATOR									Component ATA:24
PN:90278-2	MOS/MSC	06-May-24	O/C							
SN:1293	HRS	9381.4								
	AFL	7483								
PROC. REF: AMM 24-20-01										
242002A	NO. 2 AC 5KVA ALTERNATOR ** REPLACE BEARINGS (IRN F2420000) (AWL**)									Service ATA:24
PN:90278-2	MOS	06-May-24		TAC 13				LIFE LIMIT		
SN:1293	HRS	9381.4	1200 (+25/-25)	TAC 310.1	10271.3	10296.3	755.6 (+25)			
	AFL	7483		TAC 231						
PROC. REF: AMM 24-20-01										
242050	BREAKER, REMOTE CIRCUIT									Component ATA:24
PN:SM600BA25N1	MOS/MSC	18-Jul-05	O/C	TSN 0						
SN:91298	HRS	18.9		TSN 0						
	AFL	15		TSN 0						
PROC. REF: GENERIC NO REF										
242054	AFT BREAKER, OPTIONAL CIRCUIT									Component ATA:24
PN:4533488524-017	MOS/MSC	10-May-05	O/C	TSN 0						
SN:A00588396	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
242055	OPTIONAL BREAKER PANEL CIRCUIT									Component ATA:24
PN:4524088502-029	MOS/MSC	18-Jul-05	O/C	TSN 0						
SN:A00612021	HRS	18.9		TSN 0						
	AFL	15		TSN 0						
PROC. REF: AMM 24-60-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 24 - ELECTRICAL POWER											
242081		1200 VA, 115VAC , 60HZ INVERTER								Component	ATA:24
PN:2D1200-1A-1011	MOS/MSC	10-May-05	O/C	TSN 0							
SN:GB001040	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
243001		NO. 1 STARTER/GENERATOR (IRN P2430003)								Component	ATA:24
PN:23280-067	MOS	09-Jan-23		TSO 0				OVERHAUL			
SN:P1263/CA	HRS	9039.2	1200 (+25/-25)	TSO 0, Adj -14.3	10224.9	10249.9	709.2 (+25)				
	AFL	7232		TSO 0							
PROC. REF: AMM 24-30-01											
243001A		REPLACE NO. 1 STARTER/GENERATOR (IRN P2430003) BEARING (IRN P2430007)								Service	ATA:24
PN:23280-067	MOS/MSC	09-Jan-23	N/A								
SN:P1263/CA	HRS	9039.2									
	AFL	7232									
PROC. REF: AMM 24-30-01											
243002		NO. 2 STARTER/GENERATOR (IRN P2430003)								Component	ATA:24
PN:23280-067	MOS	10-May-23		TSO 0				OVERHAUL			
SN:P1391/CA	HRS	9071.3	1200 (+25/-25)	TSO 0, Adj -2.03	10269.27	10294.27	753.6 (+25)				
	AFL	7252		TSO 0							
PROC. REF: AMM 24-30-01											
243002A		REPLACE NO. 2 STARTER/GENERATOR (IRN P2430003) BEARING (IRN P2430007)								Service	ATA:24
PN:23280-067	MOS/MSC	10-May-23	N/A								
SN:P1391/CA	HRS	9071.3									
	AFL	7252									
PROC. REF: AMM 24-30-01											
243037		EMERGENCY BATTERY (P/N RG-443), (IF INSTALLED) -REPLACE (IRN AB2431063).								Component	ATA:24
PN:RG-443	MOS	16-Oct-24	60 (+14d/-14d)	TSN 13	16-Sep-28	30-Sep-28	1401 d (+14)	REPLACE			
SN:41333981	HRS	9492.6	5000 (+25/-25)	TSN 311	14181.6	14206.6	4665.9 (+25)				
	AFL	7560		TSN 234							
PROC. REF: AMM 24-32-01, CMM 24-30-67											
243037A		CAPACITY CHECK EMERGENCY BATTERY (IRN O2431002, IRN AB2431062)								Service	ATA:24
PN:RG-443	MOS	16-Oct-24	12 (+14d/-14d)	Adj -21d	25-Sep-25	09-Oct-25	314 d (+14)				
SN:41333981	HRS	9492.6	1000 (+25/-25)		10492.6	10517.6	976.9 (+25)				
	AFL	7560									
PROC. REF: GENERIC NO REF, CMM 24-30-67											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 24 - ELECTRICAL POWER											
243043		NO. 1 MAIN AIRCRAFT BATTERY								Component	ATA:24
PN:RG-380E/44L	MOS	16-Oct-24	48 (+1m/-1m)	TSN 31	16-Mar-26	16-Apr-26	486 d (+31)				
SN:41199883	HRS	9492.6		TSN 771.4							
	AFL	7560		TSN 554							
PROC. REF: AMM 24-31-01, AMM 24-31-06, CMM 24-30-71											
243043B		CAPACITY CHECK NO. 1 MAIN AIRCRAFT BATTERY (IRN O1222000 NI-CAD/IRN T1222004 38 AMP HOUR LEAD-ACID/T1222007 28 AMP HOUR LEAD ACID)								Service	ATA:24
PN:RG-380E/44L	MOS	16-Oct-24	6 (+1m/-1m)	Adj -39d	08-Mar-25	08-Apr-25	113 d (+31)				
SN:41199883	HRS	9492.6									
	AFL	7560									
PROC. REF: AMM 12-22-00, CMM 24-30-71											
243044		NO. 2 MAIN AIRCRAFT BATTERY								Component	ATA:24
PN:RG-380E/44L	MOS	16-Oct-24	48 (+1m/-1m)	TSN 31	16-Mar-26	16-Apr-26	486 d (+31)				
SN:41199145	HRS	9492.6		TSN 771.4							
	AFL	7560		TSN 554							
PROC. REF: AMM 24-31-01, AMM 24-31-06, CMM 24-30-71											
243044B		CAPACITY CHECK NO. 2 MAIN AIRCRAFT BATTERY (IRN O1222000 NI-CAD/IRN T1222004 38 AMP HOUR LEAD-ACID/T1222007 28 AMP HOUR LEAD ACID)								Service	ATA:24
PN:RG-380E/44L	MOS	16-Oct-24	6 (+1m/-1m)	Adj -39d	08-Mar-25	08-Apr-25	113 d (+31)				
SN:41199145	HRS	9492.6									
	AFL	7560									
PROC. REF: AMM 12-22-00, CMM 24-30-71											
246001		LH FWD PWR DISTRIBUTION PANEL								Component	ATA:24
PN:650GC02Y03	MOS/MSC	10-May-05	O/C	TSN 0							
SN:364	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 24-60-02											
246002		RH FWD PWR DISTRIBUTION PANEL								Component	ATA:24
PN:655GC02Y03	MOS/MSC	10-May-05	O/C	TSN 0							
SN:358	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 24-60-02											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 24 - ELECTRICAL POWER										
246003	LH AFT PWR DISTRIBUTION PANEL									Component ATA:24
PN:660GC02Y07	MOS/MSC	03-Jun-13	O/C							
SN:211	HRS	5513.02								
	AFL	4486								
PROC. REF: AMM 24-60-03										
246004	RIGHT AFT PWR DISTRIBUTION PANEL									Component ATA:24
PN:700GC02Y07	MOS/MSC	14-Nov-09	O/C							
SN:142	HRS	3056.47								
	AFL	2526								
PROC. REF: AMM 24-60-03										
5-19-00-Y2431005	PERFORM BATTERY CONNECTOR TOLERANCE CHECK.									Service ATA:24
	MOS	03-Jan-24								
	HRS	9258	300 (+25/-25)	9558	9583	42.3 (+25)				
	AFL	7391								
PROC. REF: AMM 24-31-00										
AC2460002 ^S	REMOVE ATTACHING PARTS SECURING CIRCUIT BREAKER PANEL TO STRUCTURE. CHECK FOR LOOSE CIRCUIT BREAKER TERMINALS, LOOSE WIRE TERMINALS, CORRODED TERMINALS OR BUSS BARS, AND EVIDENCE OF WIRE INSULATION DAMAGE.									Service ATA:24
	MOS	10-May-23	96 (+14d/-14d)							
	HRS	9071.3	2400 (+25/-25)							
	AFL	7252								
PROC. REF: GENERIC NO REF										
PKG:19										
B2450002 ^S	** ELECTRICAL SYSTEM CONTROL - PERFORM OPERATIONAL CHECK (AWL**)									Service ATA:24
	MOS	11-Mar-22	48 (+14d/-14d)	AIRWORTHINESS						
	HRS	8721.2	1200 (+25/-25)							
	AFL	7006								
PROC. REF: AMM 24-00-00										
PKG:13										
H2450001 ^S	** AUXILIARY POWER SUPPLIES - PERFORM FUNCTIONAL TEST (AWL**)									Service ATA:24
	MOS	25-Jan-24	24 (+14d/-14d)	AIRWORTHINESS						
	HRS	9265.8	600 (+25/-25)							
	AFL	7395								
PROC. REF: AMM 24-00-00										
PKG:7										
H2450023 ^S	** EMER BATT LOW AND GEN AMPS HIGH INDICATION - PERFORM OPERATIONAL CHECK (AWL**)									Service ATA:24
	MOS	25-Jan-24	24 (+14d/-14d)	AIRWORTHINESS						
	HRS	9265.8	600 (+25/-25)							
	AFL	7395								
PROC. REF: AMM 24-00-00										
PKG:7										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 24 - ELECTRICAL POWER											
Q2460001 ^S			** POWER DISTRIBUTION SYSTEM - PERFORM SQUAT SWITCH CHECK (AWL**)							Service	ATA:24
	MOS	11-Mar-22	48 (+14d/-14d)					AIRWORTHINESS			
	HRS	8721.2	1200 (+25/-25)								
	AFL	7006									
					PROC. REF: AMM 24-60-00					PKG:17	
R2431003 ^S			** BATTERY WARNING SYSTEM - PERFORM FUNCTIONAL TEST. (EFFECTIVE ON AIRCRAFT WITH NI-CAD BATTERIES INSTALLED.) (AWL**)							Service	ATA:24
	MOS	10-May-23	96 (+14d/-14d)					AIRWORTHINESS			
	HRS	9071.3	2400 (+25/-25)								
	AFL	7252									
					PROC. REF: AMM 24-31-00					PKG:19	
W2450000 ^S			** GENERATOR FAIL INDICATION - PERFORM OPERATIONALCHECK. (AWL**)							Service	ATA:24
	MOS	25-Jan-24	24 (+14d/-14d)					AIRWORTHINESS			
	HRS	9265.8	600 (+25/-25)								
	AFL	7395									
					PROC. REF: AMM 24-00-00					PKG:7	
Y2400001 ^S			SWITCH AND CIRCUIT BREAKER PANELS - PERFORM VISUAL INSPECTION							Service	ATA:24
	MOS	11-Mar-22	48 (+14d/-14d)								
	HRS	8721.2	1200 (+25/-25)								
	AFL	7006									
					PROC. REF: GENERIC NO REF					PKG:13	
Y2400002 ^S			ELECTRICAL WIRING - PERFORM VISUAL INSPECTION FOR ROUTING, SECURITY, CLEARANCES, CHAFING, AND ELECTRICAL COMPONENTS FOR SECURITY AND GENERAL CONDITION.							Service	ATA:24
	MOS	25-Jan-24	24 (+14d/-14d)								
	HRS	9265.8	600 (+25/-25)								
	AFL	7395									
					PROC. REF: GENERIC NO REF					PKG:7	
Y2400025 ^S			ELECTRICAL WIRING - PERFORM VISUAL INSPECTION FOR ROUTING, SECURITY, CLEARANCES, CHAFING, AND ELECTRICAL COMPONENTS FOR SECURITY AND GENERAL CONDITION.							Service	ATA:24
	MOS	25-Jan-24	24 (+14d/-14d)								
	HRS	9265.8	600 (+25/-25)								
	AFL	7395									
					PROC. REF: GENERIC NO REF					PKG:8	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 24 - ELECTRICAL POWER										
Y2430005 ^S STARTER/GENERATOR - PERFORM GROUNDING LUG BONDING CHECK Service ATA:24										
	MOS	25-Jan-24	24 (+14d/-14d)							
	HRS	9265.8	600 (+25/-25)							
	AFL	7395								
PROC. REF: AMM 24-30-01										PKG:9
Y2430006 ^S STARTER/GENERATOR - PERFORM VISUAL INSPECTION OF GROUNDING LUGS. Service ATA:24										
	MOS	25-Jan-24	24 (+14d/-14d)							
	HRS	9265.8	600 (+25/-25)							
	AFL	7395								
PROC. REF: GENERIC NO REF										PKG:9
Y2431000 ^S BATTERY, GENERATOR, AND BUS-TIE CABLES - PERFORM VISUAL INSPECTION. Service ATA:24										
	MOS	10-May-23	96 (+14d/-14d)							
	HRS	9071.3	2400 (+25/-25)							
	AFL	7252								
PROC. REF: GENERIC NO REF										PKG:20
Y2431001 ^S EMERGENCY BATTERY CABLES - PERFORM VISUAL INSPECTION. Service ATA:24										
	MOS	25-Jan-24	24 (+14d/-14d)							
	HRS	9265.8	600 (+25/-25)							
	AFL	7395								
PROC. REF: GENERIC NO REF										PKG:7
Y2460000 ^S DC BUS ISOLATION - PERFORM OPERATIONAL CHECK Service ATA:24										
	MOS	11-Mar-22	48 (+14d/-14d)							
	HRS	8721.2	1200 (+25/-25)							
	AFL	7006								
PROC. REF: AMM 24-60-00										PKG:13
ATA 25 - EQUIPMENT/FURNISHINGS										
251001 PILOT CREW SEAT Component ATA:25										
PN:4525103038-007	MOS/MSC	10-May-05	O/C	TSN 0						
SN:654	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-10-50										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 25 - EQUIPMENT/FURNISHINGS											
251002		COPILOT CREW SEAT								Component	ATA:25
PN:4525103038-008	MOS/MSC	10-May-05	O/C	TSN 0							
SN:635	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 25-10-50											
256061		PILOT LIFE VEST								Component	ATA:25
PN:63600-101	MOS/MSC	03-Mar-20	O/C	TSN 0	03-Mar-30 (M)		1934 d				
SN:L4686058	HRS	7896.6		TSN 0							
	AFL	6371		TSN 0							
PROC. REF: CMM 25-60-05, AMM 25-60-01											
256061A		INSPECT PILOT LIFE VEST (E2561002)								Service	ATA:25
PN:63600-101	MOS	03-Mar-20	60		03-Mar-25		108 d				
SN:L4686058	HRS	7896.6									
	AFL	6371									
PROC. REF: CMM 25-60-05, AMM 25-60-01											
256062		COPILOT LIFE VEST								Component	ATA:25
PN:63600-101	MOS/MSC	03-Mar-20	O/C	TSN 0	03-Mar-30 (M)		1934 d				
SN:L4686058	HRS	7896.6		TSN 0							
	AFL	6371		TSN 0							
PROC. REF: CMM 25-60-05, AMM 25-60-01											
256062A		INSPECT COPILOT LIFE VEST (E2561002)								Service	ATA:25
PN:63600-101	MOS	03-Mar-20	60		03-Mar-25		108 d				
SN:L4686058	HRS	7896.6									
	AFL	6371									
PROC. REF: CMM 25-60-05, AMM 25-60-01											
256063		NO. 1 LIFE VEST								Component	ATA:25
PN:63600-101	MOS/MSC	03-Mar-20	O/C	TSN 0	03-Mar-30 (M)		1934 d				
SN:L4686059	HRS	7896.6		TSN 0							
	AFL	6371		TSN 0							
PROC. REF: CMM 25-60-05, AMM 25-60-01											
256063A		INSPECT NO. 1 LIFE VEST (E2561002)								Service	ATA:25
PN:63600-101	MOS	03-Mar-20	60		03-Mar-25		108 d				
SN:L4686059	HRS	7896.6									
	AFL	6371									
PROC. REF: CMM 25-60-05, AMM 25-60-01											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 25 - EQUIPMENT/FURNISHINGS											
256064		NO. 2 LIFE VEST								Component	ATA:25
PN:636300-101	MOS/MSC	03-Mar-20	O/C	TSN 0	03-Mar-30 (M)		1934 d				
SN:L4686056	HRS	7896.6		TSN 0							
	AFL	6371		TSN 0							
PROC. REF: CMM 25-60-05, AMM 25-60-01											
256064A		INSPECT NO. 2 LIFE VEST (E2561002)								Service	ATA:25
PN:636300-101	MOS	03-Mar-20	60		03-Mar-25		108 d				
SN:L4686056	HRS	7896.6									
	AFL	6371									
PROC. REF: CMM 25-60-05, AMM 25-60-01											
256065		NO. 3 LIFE VEST								Component	ATA:25
PN:63600-101	MOS/MSC	03-Mar-20	O/C	TSN 0	03-Mar-30 (M)		1934 d				
SN:L4586052	HRS	7896.6		TSN 0							
	AFL	6371		TSN 0							
PROC. REF: CMM 25-60-05, AMM 25-60-01											
256065A		INSPECT NO. 3 LIFE VEST (E2561002)								Service	ATA:25
PN:63600-101	MOS	03-Mar-20	60		03-Mar-25		108 d				
SN:L4586052	HRS	7896.6									
	AFL	6371									
PROC. REF: CMM 25-60-05, AMM 25-60-01											
256066		NO. 4 LIFE VEST								Component	ATA:25
PN:63600-101	MOS/MSC	03-Mar-20	O/C	TSN 0	03-Mar-30 (M)		1934 d				
SN:L4686051	HRS	7896.6		TSN 0							
	AFL	6371		TSN 0							
PROC. REF: CMM 25-60-05, AMM 25-60-01											
256066A		INSPECT NO. 4 LIFE VEST (E2561002)								Service	ATA:25
PN:63600-101	MOS	03-Mar-20	60		03-Mar-25		108 d				
SN:L4686051	HRS	7896.6									
	AFL	6371									
PROC. REF: CMM 25-60-05, AMM 25-60-01											
256067		NO. 5 LIFE VEST								Component	ATA:25
PN:63600-101	MOS/MSC	03-Mar-20	O/C		25-Jan-25 (M)		71 d				
SN:L527314	HRS	7896.6									
	AFL	6371									
PROC. REF: CMM 25-60-05, AMM 25-60-01											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 25 - EQUIPMENT/FURNISHINGS											
256067A		INSPECT NO. 5 LIFE VEST (E2561002)								Service	ATA:25
PN:63600-101	MOS	03-Mar-20	60		03-Mar-25		108 d				
SN:L527314	HRS	7896.6									
	AFL	6371									
PROC. REF: CMM 25-60-05, AMM 25-60-01											
256068		NO. 6 LIFE VEST								Component	ATA:25
PN:63600-101	MOS/MSC	03-Mar-20	O/C	TSN 0	03-Mar-30 (M)		1934 d				
SN:L4686053	HRS	7896.6		TSN 0							
	AFL	6371		TSN 0							
PROC. REF: CMM 25-60-05, AMM 25-60-01											
256068A		INSPECT NO. 6 LIFE VEST (E2561002)								Service	ATA:25
PN:63600-101	MOS	03-Mar-20	60		03-Mar-25		108 d				
SN:L4686053	HRS	7896.6									
	AFL	6371									
PROC. REF: CMM 25-60-05, AMM 25-60-01											
256071		LAVATORY LIFE VEST								Component	ATA:25
PN:63600-101	MOS/MSC	03-Mar-20	O/C	TSN 0	03-Mar-30 (M)		1934 d				
SN:L4686050	HRS	7896.6		TSN 0							
	AFL	6371		TSN 0							
PROC. REF: CMM 25-60-05, AMM 25-60-01											
256071A		INSPECT LAVATORY LIFE VEST (E2561002)								Service	ATA:25
PN:63600-101	MOS	03-Mar-20	60 (+14d/-14d)		03-Mar-25	17-Mar-25	108 d (+14)				
SN:L4686050	HRS	7896.6									
	AFL	6371									
PROC. REF: CMM 25-60-05, AMM 25-60-01											
256076		FIRST AID KIT								Component	ATA:25
PN:PN	MOS/MSC	13-Oct-17	O/C	TSN 0							
SN:UNKNOWN	HRS	7059.3		TSN 0							
	AFL	5738		TSN 0							
PROC. REF: GENERIC NO REF											
256076A		VISUAL INSPECTION FIRST AID KIT PER MANUFACTURERS INSTRUCTIONS								Service	ATA:25
PN:PN	MOS	16-Oct-24	12 (+14d/-14d)		16-Oct-25	30-Oct-25	335 d (+14)				
SN:UNKNOWN	HRS	9492.6									
	AFL	7560									
PROC. REF: GENERIC CUSTOM											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
256109 EMERGENCY LOCATOR TRANSMITTER BEACON										Component ATA:25
PN:453-5000-366	MOS/MSC	25-Jan-24	O/C							
SN:10213	HRS	9265.8								
	AFL	7395								
PROC. REF: AMM 25-62-01										
256109A FUNCTIONAL TEST EMERGENCY LOCATOR TRANSMITTER BEACON SYSTEM										Service ATA:25
PN:453-5000-366	MOS	25-Jan-24	12 (+14d/-14d)		25-Jan-25	08-Feb-25	71 d (+14)			
SN:10213	HRS	9265.8								
	AFL	7395								
PROC. REF: AMM 25-62-00, FAR FAR 91.207										
256109B INSPECT EMERGENCY LOCATOR TRANSMITTER (ELT) BATTERY										Service ATA:25
PN:552-0133	MOS	22-Apr-24	12 (+14d/-14d)		22-Apr-25	06-May-25	158 d (+14)			
SN:1005120-034	HRS	9368.9								
	AFL	7476								
PROC. REF: AMM 25-62-00										
256109C REPLACE EMERGENCY LOCATOR TRANSMITTER (ELT) BATTERY										Service ATA:25
PN:552-0133	MOS/MSC	22-Apr-24	DUE		23-Feb-29 (M)		1561 d			
SN:1005120-034	HRS	9368.9								
	AFL	7476								
PROC. REF: AMM 25-62-01, FAR FAR 91.207										
256109D REPLACE EMERGENCY LOCATOR TRANSMITTER BEACON REMOTE SWITCH BATTERY (IF INSTALLED)										Service ATA:25
PN:453-5000-366	MOS/MSC	10-May-23	A/R							
SN:10213	HRS	9071.3								
	AFL	7252								
PROC. REF: GENERIC NO REF, FAR FAR 91.207										
256111 EMERGENCY LOCATOR TRANSMITTER (ELT) BATTERY										Component ATA:25
PN:552-0133	MOS/MSC	22-Apr-24	O/C	TSN 0						
SN:1005120-034	HRS	9368.9		TSN 0						
	AFL	7476		TSN 0						
PROC. REF: GENERIC NO REF										
256115 ELT ANTENNA										Component ATA:25
PN:110-337	MOS/MSC	10-May-05	O/C	TSN 0						
SN:4030477	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-62-03										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
258010	AIRSHOW FLT DECK CONTROLLER									Component ATA:25
PN:922000-2	MOS/MSC	04-Jan-15	O/C							
SN:G02041804	HRS	6640								
	AFL	5400								
PROC. REF: GENERIC NO REF										
5-19-01-N2561004	DORNE AND MARGOLIN ELT REMOTE CONTROL BATTERY P/N U264-1 (IRN N2561004)									Service ATA:25
	MOS/MSC	10-May-05	N/A							
	HRS	0								
	AFL	0								
PROC. REF: GENERIC NO REF										
T2550000 ^S	AVIONICS EQUIPMENT AND WIRING LOCATED IN FORWARD RH AVIONICS CABINET - PERFORM GENERAL VISUAL INSPECTION.									Service ATA:25
	MOS	10-May-23								
	HRS	9071.3	4800 (+25/-25)							
	AFL	7252								
PROC. REF: GENERIC NO REF										
Y2510000 ^S	GLARESHIELD, HEADLINER, AND TRIM STRIPS - PERFORM VISUAL INSPECTION									Service ATA:25
	MOS	25-Jan-24	12 (+14d/-14d)							
	HRS	9265.8	300 (+25/-25)							
	AFL	7395								
PROC. REF: GENERIC NO REF										
Y2510001 ^S	CREW SEATS AND SEAT BELTS - PERFORM VISUAL INSPECTION									Service ATA:25
	MOS	25-Jan-24	12 (+14d/-14d)							
	HRS	9265.8	300 (+25/-25)							
	AFL	7395								
PROC. REF: GENERIC NO REF										
Y2520000 ^S	CABIN - PERFORM VISUAL INSPECTION OF THE FOLLOWING:A. CABIN SEATS AND SEAT BELTS. ENSURE THAT THE SEATS FUNCTION CORRECTLY AND LOCK IN PLACE.B. STOWAGE CABINETSC. HEADLINERD. SIDE PANELSE. RUG									Service ATA:25
	MOS	25-Jan-24	12 (+14d/-14d)							
	HRS	9265.8	300 (+25/-25)							
	AFL	7395								
PROC. REF: GENERIC NO REF										
Y2540000 ^S	PERFORM ALL LAVATORY PAPER AND LINEN WASTE RECEPTACLE ACCESS DOORS AND DISPOSAL DOORS FOR PROPER OPERATION, FIT, SEALING, LATCHING, AND LEGIBILITY OF PLACARD.									Service ATA:25
	MOS	25-Jan-24	24 (+14d/-14d)							
	HRS	9265.8	600 (+25/-25)							
	AFL	7395								
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 26 - FIRE PROTECTION											
261057		NO. 1 FIRE DETECT CONTROL UNIT								Component	ATA:26
PN:877-01032	MOS/MSC	19-Apr-11	O/C								
SN:0403-208	HRS	4171.45									
	AFL	3411									
PROC. REF: AMM 26-11-01											
261058		NO. 2 FIRE DETECT CONTROL UNIT								Component	ATA:26
PN:35009-39	MOS/MSC	04-Mar-08	O/C								
SN:1763	HRS	1982.37									
	AFL	1615									
PROC. REF: AMM 26-11-01											
261521		LH LEAK DETECTION UNIT								Component	ATA:26
PN:6626100000-003	MOS/MSC	10-May-05	O/C	TSN 0							
SN:1029	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 26-12-01											
261522		RH LEAK DETECTION UNIT								Component	ATA:26
PN:6626100000-003	MOS/MSC	10-May-05	O/C	TSN 0							
SN:1035	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 26-12-01											
261570		ANTI-ICE LEAK DETECTION UNIT								Component	ATA:26
PN:6626100000-003	MOS/MSC	19-Apr-11	O/C								
SN:1706	HRS	4171.45									
	AFL	3411									
PROC. REF: AMM 26-12-01											
262001		NO. 1/LEFT/LOWER FIRE EXTINGUISHER BOTTLE								Component	ATA:26
PN:33100021-1	MOS/MSC	16-Oct-24	O/C	TSO 0							
SN:51536B1	HRS	9492.6		TSO 0							
	AFL	7560		TSO 0							
PROC. REF: AMM 26-21-01											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 26 - FIRE PROTECTION											
262001A		NO. 1/LEFT/LOWER FIRE EXTINGUISHER BOTTLE - HYDROSTATIC TEST (Q2620006)							Service		ATA:26
PN:33100021-1	MOS	16-Oct-24	60 (+14d/-14d)		16-Oct-29	30-Oct-29	1796 d (+14)				
SN:51536B1	HRS	9492.6									
	AFL	7560									
PROC. REF: AMM 26-21-01											
262002		NO. 2/RIGHT/UPPER FIRE EXTINGUISHER BOTTLE							Component		ATA:26
PN:33100021-1	MOS/MSC	16-Oct-24	O/C	TSO 0							
SN:50847B1	HRS	9492.6		TSO 0							
	AFL	7560		TSO 0							
PROC. REF: AMM 26-21-01											
262002A		NO. 2/RIGHT/UPPER FIRE EXTINGUISHER BOTTLE - HYDROSTATIC TEST (Q2620006)							Service		ATA:26
PN:33100021-1	MOS	16-Oct-24	60 (+14d/-14d)		16-Oct-29	30-Oct-29	1796 d (+14)				
SN:50847B1	HRS	9492.6									
	AFL	7560									
PROC. REF: AMM 26-21-01											
262013		NO. 1/LEFT/LOWER FIRE EXTINGUISHER, LEFT SQUIB							Component		ATA:26
PN:30903856	MOS	16-Oct-24	180 (+14d/-14d)	TSN 0	16-Oct-39	30-Oct-39	5448 d (+14)	LIFE LIMIT			
SN:03212	HRS	9492.6		TSN 0							
	AFL	7560		TSN 0							
PROC. REF: AMM 26-21-02											
262013A		NO. 1/LEFT/LOWER FIRE EXTINGUISHER, LEFT SQUIB SERVICE LIFE LIMIT							Service		ATA:26
PN:30903856	MOS	16-Oct-24	120 (+14d/-14d)		16-Oct-34	30-Oct-34	3622 d (+14)	SERVICE LIFE LIMIT			
SN:03212	HRS	9492.6									
	AFL	7560									
PROC. REF: AMM 26-21-02											
262014		NO. 1/LEFT/LOWER FIRE EXTINGUISHER, RIGHT SQUIB							Component		ATA:26
PN:30903859	MOS	16-Oct-24	180 (+14d/-14d)	TSN 0	16-Oct-39	30-Oct-39	5448 d (+14)				
SN:02315	HRS	9492.6		TSN 0							
	AFL	7560		TSN 0							
PROC. REF: AMM 26-21-02											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 26 - FIRE PROTECTION											
262014A		NO. 1/LEFT/LOWER FIRE EXTINGUISHER, RIGHT SQUIB SERVICE LIFE LIMIT								Service	ATA:26
PN:30903859	MOS	16-Oct-24	120 (+14d/-14d)		16-Oct-34	30-Oct-34	3622 d (+14)	SERVICE LIFE LIMIT			
SN:02315	HRS	9492.6									
	AFL	7560									
PROC. REF: AMM 26-21-02											
262015		NO. 2/RIGHT/UPPER FIRE EXTINGUISHER, LEFT SQUIB								Component	ATA:26
PN:30903856	MOS	16-Oct-24	180 (+14d/-14d)	TSN 0	16-Oct-39	30-Oct-39	5448 d (+14)				
SN:03214	HRS	9492.6		TSN 0							
	AFL	7560		TSN 0							
PROC. REF: AMM 26-21-02											
262015A		NO. 2/RIGHT/UPPER FIRE EXTINGUISHER, LEFT SQUIB SERVICE LIFE LIMIT (D2620007)								Service	ATA:26
PN:30903856	MOS	16-Oct-24	120 (+14d/-14d)		16-Oct-34	30-Oct-34	3622 d (+14)	SERVICE LIFE LIMIT			
SN:03214	HRS	9492.6									
	AFL	7560									
PROC. REF: AMM 26-21-02											
262016		NO. 2/RIGHT/UPPER FIRE EXTINGUISHER, RIGHT SQUIB								Component	ATA:26
PN:30903859	MOS	16-Oct-24	180 (+14d/-14d)	TSN 0	16-Oct-39	30-Oct-39	5448 d (+14)	LIFE LIMIT			
SN:02286	HRS	9492.6		TSN 0							
	AFL	7560		TSN 0							
PROC. REF: AMM 26-21-02											
262016A		NO. 2/RIGHT/UPPER FIRE EXTINGUISHER, RIGHT SQUIB SERVICE LIFE LIMIT								Service	ATA:26
PN:30903859	MOS	16-Oct-24	120 (+14d/-14d)		16-Oct-34	30-Oct-34	3622 d (+14)				
SN:02286	HRS	9492.6									
	AFL	7560									
PROC. REF: AMM 26-21-02											
262041		PILOT PORTABLE FIRE EXTINGUISHER								Component	ATA:26
PN:A344	MOS/MSC	13-Oct-17	O/C	TSN 0							
SN:D-00364181	HRS	7059.3		TSN 0							
	AFL	5738		TSN 0							
PROC. REF: GENERIC NO REF											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 26 - FIRE PROTECTION											
262041B		HYDROSTATIC TEST PILOT PORTABLE FIRE EXTINGUISHER (Q2510003)							Service	ATA:26	
PN:A344	MOS	13-Oct-17	144 (+14d/-14d)		13-Oct-29	27-Oct-29	1793 d (+14)				
SN:D-00364181	HRS	7059.3									
	AFL	5738									
PROC. REF: AMM 26-23-00											
262042		COPILOT PORTABLE FIRE EXTINGUISHER							Component	ATA:26	
PN:A344	MOS/MSC	13-Oct-17	O/C	TSN 0							
SN:D-00363453	HRS	7059.3		TSN 0							
	AFL	5738		TSN 0							
PROC. REF: GENERIC NO REF											
262042B		HYDROSTATIC TEST COPILOT PORTABLE FIRE EXTINGUISHER (Q2510003)							Service	ATA:26	
PN:A344	MOS	13-Oct-17	144 (+14d/-14d)		13-Oct-29	27-Oct-29	1793 d (+14)				
SN:D-00363453	HRS	7059.3									
	AFL	5738									
PROC. REF: AMM 26-23-00											
262051		CABIN PORTABLE FIRE EXTINGUISHER							Component	ATA:26	
PN:C352	MOS/MSC	13-Oct-17	O/C	TSN 0							
SN:E-09392938	HRS	7059.3		TSN 0							
	AFL	5738		TSN 0							
PROC. REF: GENERIC NO REF											
262051B		HYDROSTATIC TEST CABIN PORTABLE FIRE EXTINGUISHER (Q2510003)							Service	ATA:26	
PN:C352	MOS	13-Oct-17	144 (+14d/-14d)		13-Oct-29	27-Oct-29	1793 d (+14)				
SN:E-09392938	HRS	7059.3									
	AFL	5738									
PROC. REF: AMM 26-23-00											
5-19-00-Q2610001-LEFT		NO. 1 ENGINE HOT SECTION FIRE DETECTOR ELEMENT - PERFORM VISUAL INSPECTION (IRN O2610001)							Service	ATA:26	
	MOS	14-Mar-14									
	HRS	5991.87	3500 (+100/-100)		9491.87	9591.87	TOL (+76.2)				
	AFL	4884									
PROC. REF: GENERIC NO REF											
5-19-00-Q2610001-RIGHT		NO. 2 ENGINE HOT SECTION FIRE DETECTOR ELEMENT - PERFORM VISUAL INSPECTION (IRN O2610001)							Service	ATA:26	
	MOS	12-Mar-14									
	HRS	5991.87	3500 (+100/-100)		9491.87	9591.87	TOL (+76.2)				
	AFL	4884									
PROC. REF: GENERIC NO REF											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 26 - FIRE PROTECTION										
J2620000 ^S	** ENGINE FIRE EXTINGUISHING SYSTEM FIRE SWITCH - PERFORM FUNCTIONAL TEST (AWL**)									Service ATA:26
	MOS	10-May-23						AIRWORTHINESS		
	HRS	9071.3	4800 (+25/-25)							
	AFL	7252								
PROC. REF: AMM 26-21-00										PKG:25
T2620001 ^S	** FIREWALL SHUTOFF VALVES - PERFORM OPERATIONAL CHECK (AWL**)									Service ATA:26
	MOS	11-Mar-22	48 (+14d/-14d)					AIRWORTHINESS		
	HRS	8721.2	1200 (+25/-25)							
	AFL	7006								
PROC. REF: AMM 26-21-00										PKG:13
Y2610000 ^S	FIREWALL AND ACCESSORY COMPARTMENT FIRE DETECTOR ELEMENTS - PERFORM VISUAL INSPECTION.									Service ATA:26
	MOS	25-Jan-24	24 (+14d/-14d)							
	HRS	9265.8	600 (+25/-25)							
	AFL	7395								
PROC. REF: GENERIC NO REF										PKG:9
Y2620002 ^S	ENGINE FIRE EXTINGUISHER CONTAINERS - PERFORM VISUAL INSPECTION. CHECK CONTAINERS FOR CONDITION, CARTRIDGES AND CARTRIDGE WIRING FOR SECURITY AND CONDITION, CONTAINER PRESSURE GAGES FOR PROPER PRESSURES, AND PLUMBING FOR SECURITY AND CONDITION.									Service ATA:26
	MOS	25-Jan-24	12 (+14d/-14d)							
	HRS	9265.8	300 (+25/-25)							
	AFL	7395								
PROC. REF: GENERIC NO REF										PKG:2
Y2620005 ^S	ENGINE FIRE EXTINGUISHING SYSTEM - PERFORM OPERATIONAL CHECK									Service ATA:26
	MOS	10-May-23	96 (+14d/-14d)							
	HRS	9071.3	2400 (+25/-25)							
	AFL	7252								
PROC. REF: AMM 26-21-00										PKG:19
Y2620009 ^S	INSPECT PORTABLE HAND HELD FIRE EXTINGUISHERS FOR CONDITION AND DATE OF MANUFACTURE. CHECK OPERATING PRESSURE AND WEIGHT PER MAINTENANCE INSTRUCTIONS ON FIRE EXTINGUISHER BOTTLE.									Service ATA:26
	MOS	25-Jan-24	12 (+14d/-14d)							
	HRS	9265.8	300 (+25/-25)							
	AFL	7395								
PROC. REF: AMM 26-23-00										PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 26 - FIRE PROTECTION											
Z2620021 ^S			NO. 1 ENGINE FIRE EXTINGUISHER CONTAINER PLUMBING - PERFORM DETAILED INSPECTION						Service	ATA:26	
	MOS		25-Jan-24		12						
	HRS		9265.8		300						
	AFL		7395								
PROC. REF: AMM 26-21-00										PKG:2	
Z2620021 ^S			NO. 2 ENGINE FIRE EXTINGUISHER CONTAINER PLUMBING - PERFORM DETAILED INSPECTION						Service	ATA:26	
	MOS		25-Jan-24		12						
	HRS		9265.8		300						
	AFL		7395								
PROC. REF: AMM 26-21-00										PKG:2	
ATA 27 - FLIGHT CONTROLS											
270308 ^U			TRIM SWITCH PANEL						Component	ATA:27	
PN:4522208501-018	MOS/MSC		10-May-05	O/C	TSN 0						
SN:A00346119-01	HRS		0		TSN 0						
	AFL		0		TSN 0						
271095			PILOT ANGLE OF ATTACK INDICATOR						Component	ATA:27	
PN:C-38805-1	MOS/MSC		10-May-05	O/C	TSN 0						
SN:83042	HRS		0		TSN 0						
	AFL		0		TSN 0						
PROC. REF: GENERIC NO REF											
271096			COPILOT ANGLE OF ATTACK INDICATOR						Component	ATA:27	
PN:C-38805-1	MOS/MSC		10-May-05	O/C	TSN 0						
SN:83044	HRS		0		TSN 0						
	AFL		0		TSN 0						
PROC. REF: GENERIC NO REF											
271560			AILERON TRIM ACTUATOR						Component	ATA:27	
PN:6627108000-001	MOS/MSC		10-May-05	O/C	TSN 0						
SN:0363	HRS		0		TSN 0						
	AFL		0		TSN 0						
PROC. REF: AMM 27-10-09											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
272031 PILOT RUDDER PEDAL ADJUST ACTUATOR										Component ATA:27
PN:6627208001-001	MOS/MSC	10-May-05	O/C	TSN 0						
SN:0783	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-20-05										
272032 COPILOT RUDDER PEDAL ADJUST ACTUATOR										Component ATA:27
PN:6627208001-001	MOS/MSC	10-May-05	O/C	TSN 0						
SN:0785	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-20-05										
272550 RUDDER TRIM ACTUATOR										Component ATA:27
PN:4323322	MOS/MSC	10-May-05	O/C	TSN 0						
SN:0310	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-20-03										
273063 PILOT STICK SHAKER										Component ATA:27
PN:6627308500-009	MOS/MSC	10-May-05	O/C	TSN 0						
SN:1423	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-31-03										
273064 COPILOT STICK SHAKER										Component ATA:27
PN:6627308500-009	MOS/MSC	10-May-05	O/C	TSN 0						
SN:1412	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-31-03										
273075 LH ANGLE OF ATTACK TRANSMITTER										Component ATA:27
PN:6627308500-001	MOS/MSC	26-Oct-06	O/C							
SN:860	HRS	945.68								
	AFL	753								
PROC. REF: AMM 27-31-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
273076 RH ANGLE OF ATTACK TRANSMITTER										Component ATA:27
PN:6627308500-001	MOS/MSC	10-May-05	O/C	TSN 0						
SN:895	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-31-01										
273087 STALL WARNING COMPUTER										Component ATA:27
PN:C-38806-2	MOS/MSC	10-May-05	O/C	TSN 0						
SN:450	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-31-02										
274011 HORIZONTAL STABILIZER ACTUATOR										Component ATA:27
PN:6627401000-009	MOS/MSC	11-Mar-22	O/C	TSO 30						
SN:B0285	HRS	8721.2		TSO 1025.6						
	AFL	7006		TSO 773						
PROC. REF: AMM 27-40-02										
274011A HORIZONTAL STABILIZER ACTUATOR * PERFORM INSPECTION (IRN T2740002 FOR P/N 6627401000-007 OR IRN P2740032 FOR P/N 6627401000-009)										Service ATA:27
PN:6627401000-009	MOS	11-Mar-22								
SN:B0285	HRS	8721.2	1200		9921.2		405.5			
	AFL	7006								
PROC. REF: GENERIC NO REF										
274011B HORIZONTAL STABILIZER ACTUATOR * PERFORM DETAILED STRUCTURAL INSPECTION (IRN N2740025 FOR P/N 6627401000-007 OR IRN P2740033 FOR P/N 6627401000-009) (AWL*)										Service ATA:27
PN:6627401000-009	MOS	11-Mar-22						AIRWORTHINESS		
SN:B0285	HRS	8721.2	2400		11121.2		1605.5			
	AFL	7006								
PROC. REF: GENERIC NO REF										
274041 FWD INTERFACE UNIT										Component ATA:27
PN:4527408503-027	MOS/MSC	03-Jun-13	O/C							
SN:MRP642750	HRS	5513.02								
	AFL	4486								
PROC. REF: AMM 27-40-04										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
274051 HORIZONTAL STAB ACTUATOR CONTROL UNIT										Component ATA:27
PN:6627401000-003	MOS/MSC	11-Mar-22	O/C							
SN:D0581	HRS	8721.2								
	AFL	7006								
PROC. REF: AMM 27-40-03										
274164 TRIM-IN-MOTION DETECTOR										Component ATA:27
PN:1625-1-1	MOS/MSC	10-May-05	O/C	TSN 0						
SN:205050274	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-41-01										
275014 LH FLAP DRIVE RVDT										Component ATA:27
PN:C144489-2	MOS/MSC	10-May-05	O/C	TSN 0						
SN:A0654	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-50-03										
275015 RH FLAP DRIVE RVDT										Component ATA:27
PN:C144489-2	MOS/MSC	10-May-05	O/C	TSN 0						
SN:A0659	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-50-03										
275021 LH IB FLAP ACTUATOR										Component ATA:27
PN:C144487-4	MOS/MSC	14-Mar-19	O/C							
SN:1935	HRS	7551								
	AFL									
PROC. REF: AMM 27-50-06										
275022 RH IB FLAP ACTUATOR										Component ATA:27
PN:C144487-4	MOS/MSC	25-Jan-15	O/C							
SN:1204	HRS	6669.27								
	AFL	5419								
PROC. REF: AMM 27-50-06										
275023 LH OB FLAP ACTUATOR										Component ATA:27
PN:6627503000-033	MOS/MSC	25-Jan-15	O/C							
SN:1229	HRS	6669.27								
	AFL	5419								
PROC. REF: AMM 27-50-06										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 27 - FLIGHT CONTROLS											
275024		RH OB FLAP ACTUATOR								Component	ATA:27
PN:C144488-4	MOS/MSC	25-Jan-15	O/C								
SN:2059	HRS	6669.27									
	AFL	5419									
PROC. REF: AMM 27-50-06											
275040		FLAP CONTROL UNIT								Component	ATA:27
PN:C144486-3-003	MOS/MSC	02-Oct-23	O/C								
SN:1663	HRS	9194.3									
	AFL	7332									
PROC. REF: AMM 27-50-05											
275055		FLAP LEVER MODULE ASSY								Component	ATA:27
PN:69013-15	MOS/MSC	02-Aug-05	O/C								
SN:029	HRS	31.7									
	AFL	22									
PROC. REF: GENERIC NO REF											
275057		FLAP DRIVE POWER UNIT								Component	ATA:27
PN:C144483-3	MOS/MSC	27-Jul-12	O/C								
SN:1278X	HRS	4975.13									
	AFL	4047									
PROC. REF: AMM 27-50-08											
275069		FLAP POSITION INDICATOR								Component	ATA:27
PN:C145159-1	MOS/MSC	10-May-05	O/C	TSN 0							
SN:1429	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 27-50-07											
276001		LH SPOILER ACTUATOR								Component	ATA:27
PN:6627602001-007	MOS/MSC	25-May-06	O/C								
SN:DAW521-01	HRS	578.27									
	AFL	440									
PROC. REF: AMM 27-60-04											
276002		RH SPOILER ACTUATOR								Component	ATA:27
PN:P455A0001-03	MOS/MSC	25-May-06	O/C								
SN:DAW022-95	HRS	578.27									
	AFL	440									
PROC. REF: AMM 27-60-04											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 27 - FLIGHT CONTROLS											
2760085 ^S		SPOILER LEVER ARM - PERFORM DETAILED VISUAL INSPECTION TO ENSURE SPOILER LEVER ARM IS PROPERLY SEATED AND SECURED ON SPOILER RVDT SHAFT							Service	ATA:27	
	MOS	25-Jan-24	36 (+14d/-14d)								
	HRS	9265.8	600 (+25/-25)								
	AFL	7395									
PROC. REF: AMM 27-60-05										PKG:10	
276013		SPOILER SHUTOFF VALVE							Component	ATA:27	
PN:6627602002-005	MOS/MSC	10-May-05	O/C	TSN 0							
SN:0052T	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 27-60-07											
276014		SPOILER CONTROL LEVER MODULE							Component	ATA:27	
PN:69014-7	MOS/MSC	10-May-05	O/C	TSN 0							
SN:339	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 27-60-03											
276049		LH SPOILER RVDT							Component	ATA:27	
PN:4527603007-001	MOS/MSC	01-Dec-05	O/C								
SN:A0650	HRS										
	AFL										
PROC. REF: AMM 27-60-05											
276050		RH SPOILER RVDT							Component	ATA:27	
PN:4527603007-001	MOS/MSC	01-Dec-05	O/C								
SN:A0651	HRS										
	AFL										
PROC. REF: AMM 27-60-05											
276073		SPOILERON COMPUTER							Component	ATA:27	
PN:402800-07-01	MOS/MSC	10-May-23	O/C								
SN:00823	HRS	9071.3									
	AFL	7252									
PROC. REF: AMM 27-60-02											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
276076	CONTROL WHEEL RVDT									Component ATA:27
PN:3G4-211A	MOS/MSC	10-May-05	O/C	TSN 0						
SN:0335/0441	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-60-06										
5-19-00-D2740003	** HORIZONTAL STABILIZER ACTUATOR SECONDARY TRIM - PERFORM FUNCTIONAL TEST (IRN D2740003) (AWL**)									Service ATA:27
	MOS	25-Jan-24						AIRWORTHINESS		
	HRS	9265.8	600 (+25/-25)		9865.8	9890.8	350.1 (+25)			
	AFL	7395								
PROC. REF: AMM 27-40-02										
5-19-00-D2740004	** HORIZONTAL STABILIZER ACTUATOR PRIMARY TRIM - PERFORM FUNCTIONAL TEST (IRN D2740004) (AWL**)									Service ATA:27
	MOS	25-Jan-24						AIRWORTHINESS		
	HRS	9265.8	600 (+25/-25)		9865.8	9890.8	350.1 (+25)			
	AFL	7395								
PROC. REF: AMM 27-40-02										
5-19-00-K2700007	* AILERON CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED VISUAL INSPECTION (IRN K2700007) (AWL*)									Service ATA:27
	MOS	10-May-23						AIRWORTHINESS		
	HRS	9071.3	4800		13871.3		4355.6			
	AFL	7252								
PROC. REF: AMM 27-00-00										
5-19-00-K2700007-LEFT ^U S	DETAILED VISUAL INSPECTION LEFT * AILERON CONTROL SYSTEM PRIMARY CABLES (K2700007)									Service ATA:27
	MOS	27-Oct-11						AIRWORTHINESS		
	HRS	4469.73	4800							
	AFL	3671								
5-19-00-K2700007-RIGHT ^U S	DETAILED VISUAL INSPECTION RIGHT * AILERON CONTROL SYSTEM PRIMARY CABLES (K2700007)									Service ATA:27
	MOS	27-Oct-11						AIRWORTHINESS		
	HRS	4469.73	4800							
	AFL	3671								
5-19-00-K2700008	* ELEVATOR CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED VISUAL INSPECTION (IRN K2700008) (AWL*)									Service ATA:27
	MOS	10-May-23						AIRWORTHINESS		
	HRS	9071.3	4800		13871.3		4355.6			
	AFL	7252								
PROC. REF: AMM 27-00-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
5-19-00-K2700009	* RUDDER CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED VISUAL INSPECTION (IRN K2700009) (AWL*)									Service ATA:27
MOS	10-May-23							AIRWORTHINESS		
HRS	9071.3		4800		13871.3		4355.6			
AFL	7252									
PROC. REF: AMM 27-00-00										
5-19-00-K2700010	* ELEVATOR CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED INSPECTION (IRN K2700010) (AWL*)									Service ATA:27
MOS	10-May-23							AIRWORTHINESS		
HRS	9071.3		4800		13871.3		4355.6			
AFL	7252									
PROC. REF: AMM 27-00-00										
5-19-00-K2700012	* RUDDER CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED VISUAL INSPECTION (IRN K2700012) (AWL*)									Service ATA:27
MOS	10-May-23							AIRWORTHINESS		
HRS	9071.3		4800		13871.3		4355.6			
AFL	7252									
PROC. REF: AMM 27-00-00										
5-19-00-K2700014	* AILERON CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED VISUAL INSPECTION (IRN K2700014) (AWL*)									Service ATA:27
MOS	10-May-23							AIRWORTHINESS		
HRS	9071.3		4800		13871.3		4355.6			
AFL	7252									
PROC. REF: AMM 27-00-00										
5-19-00-N2720030	RUDDER TORQUE TUBE AND SPINDLE - PERFORM DETAILED VISUAL INSPECTION (IRN N2720030)									Service ATA:27
MOS	22-Apr-24		72 (+14d/-14d)	Adj -9d	13-Apr-30		27-Apr-30	1975 d (+14)		
HRS	9368.9									
AFL	7476									
PROC. REF: AMM 27-20-01										
5-19-00-S2750057	* FLAP ACTUATOR BALLNUT SLEEVE - PERFORM FLOURESCENT PENETRANT INSPECTION (FLAP ACTUATOR ASSEMBLY LEARJET P/N 6627503000-009, 6627503000-011, 6627503000-021, 6627503000-023, 6627503000-025 AND 6627503000-027, MICROTECNICA P/N C144487-1, C144488-1, C144487-2, C144488-2, C144487-3 AND C144488-3) (AWL*)									Service ATA:27
MOS/MS			-					N/A BY PART NUMBER		
HRS										
AFL										
PROC. REF: NDT PART 8/27-50-01, NDT PART 8/27-50-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
5-19-00-W2750056					* FLAP ACTUATOR JOINT (P/N 145673-1) - PERFORM DETAILED VISUAL INSPECTION. APPLY CORROSION PREVENTIVE COMPOUND (CPC) TO JOINT. (AWL*)				Service	ATA:27
	MOS/MSC	25-Jan-15	N/A					N/A BY PART NUMBER		
	HRS									
	AFL									
PROC. REF: AMM 27-50-06										
5-19-01-AA2760021-LEFT					LEFT SPOILER HYDRAULIC PRESSURE SWIVEL - REPLACE				Service	ATA:27
	MOS	11-Mar-22								
	HRS	8721.2	1200 (+25/-25)		9921.2	9946.2	405.5 (+25)			
	AFL	7006								
PROC. REF: GENERIC NO REF										
5-19-01-AA2760021-LEFT					LEFT SPOILER HYDRAULIC RETURN SWIVEL - REPLACE				Service	ATA:27
	MOS	11-Mar-22								
	HRS	8721.2	1200 (+25/-25)		9921.2	9946.2	405.5 (+25)			
	AFL	7006								
PROC. REF: GENERIC NO REF										
5-19-01-AA2760021-RIGHT					RIGHT SPOILER HYDRAULIC PRESSURE SWIVEL - REPLACE				Service	ATA:27
	MOS	11-Mar-22								
	HRS	8721.2	1200 (+25/-25)		9921.2	9946.2	405.5 (+25)			
	AFL	7006								
PROC. REF: GENERIC NO REF										
5-19-01-AA2760021-RIGHT					RIGHT SPOILER HYDRAULIC RETURN SWIVEL - REPLACE				Service	ATA:27
	MOS	11-Mar-22								
	HRS	8721.2	1200 (+25/-25)		9921.2	9946.2	405.5 (+25)			
	AFL	7006								
PROC. REF: GENERIC NO REF										
5-19-01-R2710041					REPLACE *AILERON SPINDLE (4527102103-001) (AWL*)				Service	ATA:27
	MOS/MSC	10-May-05	N/A					N/A EQUIPMENT NOT INSTALLED		
	HRS	0								
	AFL	0								
PROC. REF: AMM 27-10-07										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
5-19-01-W2750055	* REPLACE FLAP ACTUATOR JOINT (P/N 145673-1) (Q2750055) (AWL*)									Component ATA:27
PN:PN	MOS/MSC	25-Jan-15	N/A	TSN 0				NOT APPLICABLE		
SN:UNKNOWN	HRS			TSN 0						
	AFL			TSN 0						
PROC. REF: AMM 27-50-06										
A2711001 ^S	** AILERON TRIM TAB CONTROL SYSTEM - PERFORM OPERATIONAL CHECK. (AWL**)									Service ATA:27
	MOS	25-Jan-24	24 (+14d/-14d)					AIRWORTHINESS		
	HRS	9265.8	600 (+25/-25)							
	AFL	7395								
PROC. REF: AMM 27-10-04										
A2721001 ^S	** RUDDER TRIM SYSTEM - PERFORM OPERATIONAL CHECK. (AWL**)									Service ATA:27
	MOS	25-Jan-24	24 (+14d/-14d)					AIRWORTHINESS		
	HRS	9265.8	600 (+25/-25)							
	AFL	7395								
PROC. REF: AMM 27-20-00										
A2731002 ^S	** ELEVATOR DISCONNECT SYSTEM - PERFORM OPERATIONAL CHECK. (AWL**)									Service ATA:27
	MOS	25-Jan-24	24 (+14d/-14d)					AIRWORTHINESS		
	HRS	9265.8	600 (+25/-25)							
	AFL	7395								
PROC. REF: AMM 27-30-00										
A2760001 ^S	** SPOILER ACTUATOR CHECK VALVE - PERFORM OPERATIONAL CHECK (AWL**)									Service ATA:27
	MOS	25-Jan-24	24 (+14d/-14d)					AIRWORTHINESS		
	HRS	9265.8	600 (+25/-25)							
	AFL	7395								
PROC. REF: AMM 27-60-04										
A2760002 ^S	** SPOILER SYSTEM - PERFORM SPOILER AUTHORITY WITH FLAPS CHECK (AWL**)									Service ATA:27
	MOS	25-Jan-24	24 (+14d/-14d)					AIRWORTHINESS		
	HRS	9265.8	600 (+25/-25)							
	AFL	7395								
PROC. REF: AMM 27-60-10										
AA2700000 ^S	AILERON CONTROL CABLE SYSTEM - WITH COCKPIT AND CABIN FLOORBOARDS REMOVED, PERFORM VISUAL INSPECTION OF ACCESSIBLE CABLES									Service ATA:27
	MOS	25-Jan-24	24 (+14d/-14d)							
	HRS	9265.8	600 (+25/-25)							
	AFL	7395								
PROC. REF: AMM 27-00-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 27 - FLIGHT CONTROLS											
AA2700001 ^S			RUDDER CONTROL CABLE SYSTEM - WITH COCKPIT AND CABIN FLOORBOARDS REMOVED, PERFORM VISUAL INSPECTION OF ACCESSIBLE CABLES						Service	ATA:27	
	MOS	25-Jan-24	24 (+14d/-14d)								
	HRS	9265.8	600 (+25/-25)								
	AFL	7395									
					PROC. REF: AMM 27-00-00					PKG:7	
AA2700002 ^S			ELEVATOR CONTROL CABLE SYSTEM - WITH COCKPIT AND CABIN FLOORBOARDS REMOVED, PERFORM VISUAL INSPECTION OF ACCESSIBLE CABLES						Service	ATA:27	
	MOS	25-Jan-24	24 (+14d/-14d)								
	HRS	9265.8	600 (+25/-25)								
	AFL	7395									
					PROC. REF: AMM 27-00-00					PKG:7	
G2710003 ^S			AILERON CONTROL SYSTEM CABLES (LOCATED IN WING AREA) - PERFORM CABLE TENSION CHECK						Service	ATA:27	
	MOS	11-Mar-22	48 (+14d/-14d)								
	HRS	8721.2	1200 (+25/-25)								
	AFL	7006									
					PROC. REF: AMM 27-10-00					PKG:16	
G2710004 ^S			AILERON CONTROL SYSTEM CABLES (LOCATED IN FUSELAGE AREA) - PERFORM CABLE TENSION CHECK						Service	ATA:27	
	MOS	11-Mar-22	48 (+14d/-14d)								
	HRS	8721.2	1200 (+25/-25)								
	AFL	7006									
					PROC. REF: AMM 27-10-00					PKG:13	
G2720003 ^S			RUDDER CONTROL CABLES - PERFORM TENSION CHECK						Service	ATA:27	
	MOS	11-Mar-22	48 (+14d/-14d)								
	HRS	8721.2	1200 (+25/-25)								
	AFL	7006									
					PROC. REF: AMM 27-20-00					PKG:14	
G2720004 ^S			RUDDER PEDALS, PEDAL PUSHRODS, ADJUSTMENT ACTUATOR, AND SECTORS - PERFORM VISUAL INSPECTION. CHECK DURING FULL TRAVEL OF RUDDER						Service	ATA:27	
	MOS	11-Mar-22	48 (+14d/-14d)								
	HRS	8721.2	1200 (+25/-25)								
	AFL	7006									
					PROC. REF: GENERIC NO REF					PKG:13	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
G2730003 ^S	ELEVATOR CONTROL CABLES - PERFORM TENSION CHECK									Service ATA:27
	MOS	11-Mar-22	48 (+14d/-14d)							
	HRS	8721.2	1200 (+25/-25)							
	AFL	7006								
PROC. REF: AMM 27-30-00										PKG:14
V2712000 ^S	** ROLL DISCONNECT SWITCHES - PERFORM OPERATIONAL CHECK (AWL**)									Service ATA:27
	MOS	25-Jan-24	24 (+14d/-14d)					AIRWORTHINESS		
	HRS	9265.8	600 (+25/-25)							
	AFL	7395								
PROC. REF: AMM 27-60-09										PKG:7
W2731001 ^S	** PITCH TRIM - PERFORM OPERATIONAL CHECK OF ELEVATOR OVERRIDE ACTUATOR (AWL**)									Service ATA:27
	MOS	25-Jan-24	24 (+14d/-14d)					AIRWORTHINESS		
	HRS	9265.8	600 (+25/-25)							
	AFL	7395								
PROC. REF: AMM 27-30-14										PKG:8
Y2700003 ^S	AILERON CONTROL CABLE SYSTEM - PERFORM VISUAL INSPECTION OF CABLES WITHIN WING									Service ATA:27
	MOS	25-Jan-24	24 (+14d/-14d)							
	HRS	9265.8	600 (+25/-25)							
	AFL	7395								
PROC. REF: AMM 27-00-00										PKG:10
Y2700004 ^S	RUDDER CONTROL CABLE SYSTEM - PERFORM VISUAL INSPECTION OF ACCESSIBLE UPPER AND LOWER CABLES									Service ATA:27
	MOS	25-Jan-24	24 (+14d/-14d)							
	HRS	9265.8	600 (+25/-25)							
	AFL	7395								
PROC. REF: AMM 27-00-00										PKG:8
Y2700005 ^S	ELEVATOR CONTROL CABLE SYSTEM - PERFORM VISUAL INSPECTION OF ACCESSIBLE UPPER AND LOWER CABLES									Service ATA:27
	MOS	25-Jan-24	24 (+14d/-14d)							
	HRS	9265.8	600 (+25/-25)							
	AFL	7395								
PROC. REF: AMM 27-00-00										PKG:8
Y2700006 ^S	RUDDER AND ELEVATOR CONTROL CABLES AND ASSOCIATED PULLEYS, LOCATED IN AFT PRESSURE BULKHEAD SUPPORT CHANNEL - PERFORM VISUAL INSPECTION									Service ATA:27
	MOS	25-Jan-24	24 (+14d/-14d)							
	HRS	9265.8	600 (+25/-25)							
	AFL	7395								
PROC. REF: AMM 27-00-00										PKG:9

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
Y2710000^S AILERONS, AILERON TRIM TAB AND VISIBLE PORTION OF RODS - PERFORM VISUAL INSPECTION. Service ATA:27										
	MOS	25-Jan-24	24 (+14d/-14d)							
	HRS	9265.8	600 (+25/-25)							
	AFL	7395								
PROC. REF: GENERIC NO REF										PKG:10
Y2710001^S AILERON BALANCE WEIGHT INSTALLATION AND SUPPORTING STRUCTURE - PERFORM VISUAL INSPECTION. Service ATA:27										
	MOS	11-Mar-22	48 (+14d/-14d)							
	HRS	8721.2	1200 (+25/-25)							
	AFL	7006								
PROC. REF: GENERIC NO REF										PKG:16
Y2710002^S AILERON CONTROL SYSTEM - PERFORM OPERATIONAL CHECK Service ATA:27										
	MOS	11-Mar-22	48 (+14d/-14d)							
	HRS	8721.2	1200 (+25/-25)							
	AFL	7006								
PROC. REF: AMM 27-10-00										PKG:16
Y2710048^S AILERON TRIM TAB INSTALLATION - PERFORM FREE PLAY CHECK Service ATA:27										
	MOS	10-May-23	96 (+14d/-14d)							
	HRS	9071.3	2400 (+25/-25)							
	AFL	7252								
PROC. REF: AMM 27-10-04										PKG:22
Y2720000^S RUDDER - PERFORM VISUAL INSPECTION. Service ATA:27										
	MOS	25-Jan-24	12 (+14d/-14d)							
	HRS	9265.8	300 (+25/-25)							
	AFL	7395								
PROC. REF: GENERIC NO REF										PKG:2
Y2720001^S RUDDER BALANCE WEIGHT INSTALLATION AND SUPPORTING STRUCTURE - PERFORM VISUAL INSPECTION Service ATA:27										
	MOS	11-Mar-22	48 (+14d/-14d)							
	HRS	8721.2	1200 (+28/-28)							
	AFL	7006								
PROC. REF: GENERIC NO REF										PKG:14
Y2720002^S RUDDER CONTROL SYSTEM - PERFORM OPERATIONAL CHECK Service ATA:27										
	MOS	11-Mar-22	48 (+14d/-14d)							
	HRS	8721.2	1200 (+25/-25)							
	AFL	7006								
PROC. REF: AMM 27-20-00										PKG:14

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
Y2721000 ^S	RUDDER TRIM TAB AND VISIBLE RODS - PERFORM VISUAL INSPECTION.								Service	ATA:27
	MOS	25-Jan-24	12 (+14d/-14d)							
	HRS	9265.8	300 (+25/-25)							
	AFL	7395								
	PROC. REF: GENERIC NO REF									PKG:2
Y2730000 ^S	CONTROL COLUMNS - PERFORM VISUAL INSPECTION. PAY PARTICULAR ATTENTION TO AILERON CONTROL WHEEL CABLE DRUM AND BOTTOM CROSSOVER PULLEYS								Service	ATA:27
	MOS	11-Mar-22	48 (+14d/-14d)							
	HRS	8721.2	1200 (+25/-25)							
	AFL	7006								
	PROC. REF: GENERIC NO REF									PKG:13
Y2730001 ^S	ELEVATORS - PERFORM VISUAL INSPECTION								Service	ATA:27
	MOS	25-Jan-24	12 (+14d/-14d)							
	HRS	9265.8	300 (+25/-25)							
	AFL	7395								
	PROC. REF: GENERIC NO REF									PKG:2
Y2730002 ^S	ELEVATOR CONTROL SYSTEM - PERFORM OPERATIONAL CHECK								Service	ATA:27
	MOS	11-Mar-22	48 (+14d/-14d)							
	HRS	8721.2	1200 (+25/-25)							
	AFL	7006								
	PROC. REF: AMM 27-30-00									PKG:14
Y2730004 ^S	CONTROL COLUMNS - PERFORM INSPECTION. INSPECT CABLE, PULLEYS, BEARINGS, AND ELECTRICAL WIRING								Service	ATA:27
	MOS	10-May-23	96 (+14d/-14d)							
	HRS	9071.3	2400 (+25/-25)							
	AFL	7252								
	PROC. REF: AMM 27-00-00									PKG:19
Y2730007 ^S	AFT ELEVATOR DISCONNECT - PERFORM DETAILED VISUAL INSPECTION.								Service	ATA:27
	MOS	10-May-23	96 (+14d/-14d)							
	HRS	9071.3	2400 (+25/-25)							
	AFL	7252								
	PROC. REF: GENERIC NO REF									PKG:20
Y2740000 ^S	PRIMARY PITCH TRIM SYSTEM - PERFORM OPERATIONAL CHECK								Service	ATA:27
	MOS	11-Mar-22	48 (+14d/-14d)							
	HRS	8721.2	1200 (+25/-25)							
	AFL	7006								
	PROC. REF: AMM 27-40-00									PKG:14

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
Y2740001^S SECONDARY PITCH TRIM SYSTEM - PERFORM OPERATIONAL CHECK Service ATA:27										
	MOS	11-Mar-22	48 (+14d/-14d)							
	HRS	8721.2	1200 (+25/-25)							
	AFL	7006								
PROC. REF: AMM 27-40-00										PKG:14
Y2750000^S FLAP DRIVE INSTALLATION - PERFORM VISUAL INSPECTION WITH FLAPS LOWERED. Service ATA:27										
	MOS	25-Jan-24	24 (+14d/-14d)							
	HRS	9265.8	600 (+25/-25)							
	AFL	7395								
PROC. REF: GENERIC NO REF										PKG:10
Y2750001^S FLAPS - PERFORM VISUAL INSPECTION Service ATA:27										
	MOS	25-Jan-24	12 (+14d/-14d)							
	HRS	9265.8	300 (+25/-25)							
	AFL	7395								
PROC. REF: GENERIC NO REF										PKG:4
Y2750053^S FLAP DRIVE ACTUATORS - PERFORM A VISUAL INSPECTION OF THE ACTUATOR ATTACHMENT, PAYING PARTICULAR ATTENTION TO THE GIMBAL PIN RETAINING RINGS. Service ATA:27										
	MOS	25-Jan-24	24 (+14d/-14d)							
	HRS	9265.8	600 (+25/-25)							
	AFL	7395								
PROC. REF: GENERIC NO REF										PKG:10
Y2760000^S SPOILER AND SPOILER ACTUATOR - PERFORM VISUAL INSPECTION WITH FLAPS LOWERED AND ACCESS PANELS OPENED. Service ATA:27										
	MOS	25-Jan-24	24 (+14d/-14d)							
	HRS	9265.8	600 (+25/-25)							
	AFL	7395								
PROC. REF: GENERIC NO REF										PKG:10
ATA 28 - FUEL										
281001 L/H BAY 1 FUEL, EJECTOR SCAVENGE PUMP Component ATA:28										
PN:6628200302-001V0685	MOS/MSC	10-May-05	O/C	TSN 0						
SN:44040004	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-12-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 28 - FUEL											
281002		R/H BAY 1 FUEL, EJECTOR SCAVENGE PUMP							Component	ATA:28	
PN:6628200302-001V0685	MOS/MSC	10-May-05	O/C	TSN 0							
SN:44040012	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-12-01											
281003		L/H BAY 3 FUEL, EJECTOR SCAVENGE PUMP							Component	ATA:28	
PN:6628200302-001V0685	MOS/MSC	10-May-05	O/C	TSN 0							
SN:44040026	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-12-01											
281004		R/H BAY 3 FUEL, EJECTOR SCAVENGE PUMP							Component	ATA:28	
PN:6628200302-001V0685	MOS/MSC	10-May-05	O/C	TSN 0							
SN:44040011	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-12-01											
281005		L/H BAY 2 FWD FUEL, EJECTOR SCAVENGE PUMP							Component	ATA:28	
PN:6628200302-001V0685	MOS/MSC	10-May-05	O/C	TSN 0							
SN:44040008	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-12-01											
281006		R/H BAY 2 FWD FUEL, EJECTOR SCAVENGE PUMP							Component	ATA:28	
PN:6628200302-001V0685	MOS/MSC	10-May-05	O/C	TSN 0							
SN:44040010	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-12-01											
281007		L/H BAY 2 AFT FUEL, EJECTOR SCAVENGE PUMP							Component	ATA:28	
PN:6628200302-001V0685	MOS/MSC	10-May-05	O/C	TSN 0							
SN:44040025	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-12-01											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
281008	R/H BAY 2 AFT FUEL, EJECTOR SCAVENGE PUMP									Component ATA:28
PN:6628200302-001V0685	MOS/MSC	10-May-05	O/C	TSN 0						
SN:44040020	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-12-01										
281009	L/H BAY 9 FUEL, EJECTOR SCAVENGE PUMP									Component ATA:28
PN:6628200302-001V0685	MOS/MSC	10-May-05	O/C	TSN 0						
SN:44040005	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-12-01										
281010	R/H BAY 9 FUEL, EJECTOR SCAVENGE PUMP									Component ATA:28
PN:6628200302-001V0685	MOS/MSC	10-May-05	O/C	TSN 0						
SN:44040003	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-12-01										
281031	FUSELAGE FUEL CELL									Component ATA:28
PN:6628100103-003	MOS/MSC	10-May-05	O/C	TSN 0						
SN:332	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-10-02										
281512	RH MOTORIZED SHUT OFF VALVE									Component ATA:28
PN:6628200101-003	MOS/MSC	10-May-05	O/C	TSN 0						
SN:1102	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
282001	L/H NO. 1 MOTORIZED SHUT OFF VALVE									Component ATA:28
PN:6628200101-003	MOS/MSC	10-May-05	O/C	TSN 0						
SN:1097	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
282003	L/H NO. 2 MOTORIZED SHUT OFF VALVE									Component ATA:28
PN:6628200101-003	MOS/MSC	10-May-05	O/C	TSN 0						
SN:1099	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
282011	SHUTOFF - REFUEL VALVE									Component ATA:28
PN:6628200102-003	MOS/MSC	10-May-05	O/C	TSN 0						
SN:46041020	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-20-10										
282013	CENTER DEFUEL SHUT OFF VALVE									Component ATA:28
PN:91816-EM9102-2	MOS/MSC	10-May-05	O/C	TSN 0						
SN:1074	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-20-07										
282033	RH MAIN EJECTOR PUMP									Component ATA:28
PN:6628200301-001	MOS/MSC	10-May-05	O/C	TSN 0						
SN:36040168	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-20-01										
282041	CONTROL - REFUELING PANEL									Component ATA:28
PN:452840800V5-001	MOS/MSC	10-May-05	O/C	TSN 0						
SN:04120826BA	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-20-14										
282043	L-1 FUEL SUPPLY CHECK VALVE									Component ATA:28
PN:7628200101-001	MOS/MSC	10-May-05	O/C	TSN 0						
SN:M0146CV1104	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-20-03										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
282044	R-2 FUEL SUPPLY CHECK VALVE									Component ATA:28
PN:7628200101-001	MOS/MSC	10-May-05	O/C	TSN 0						
SN:M0189CV0904	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-20-03										
282045	R-1 FUEL SUPPLY CHECK VALVE									Component ATA:28
PN:7628200101-001	MOS/MSC	10-May-05	O/C	TSN 0						
SN:M0158CV1084	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-20-03										
282046	L-2 FUEL SUPPLY CHECK VALVE									Component ATA:28
PN:7628200101-001	MOS/MSC	10-May-05	O/C	TSN 0						
SN:M0148CV1104	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-20-03										
282051	LH MOTIVE FLOW CHECK VALVE									Component ATA:28
PN:6628200106-003	MOS/MSC	10-May-05	O/C	TSN 0						
SN:38040216	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-20-05										
282052	RH MOTIVE FLOW CHECK VALVE									Component ATA:28
PN:6628200106-003	MOS/MSC	10-May-05	O/C	TSN 0						
SN:31040894	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-20-05										
282063	PRE-CHECK SPPR VALVE									Component ATA:28
PN:6628200116-001	MOS/MSC	14-May-15	O/C	TSN 0						
SN:44120253	HRS	6708.1		TSN 0						
	AFL	5450		TSN 0						
PROC. REF: AMM 28-20-12										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
282064	PILOT SPPR VALVE									Component ATA:28
PN:61087-2	MOS/MSC	10-May-05	O/C	TSN 0						
SN:320	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-20-11										
282087	LH STANDBY FUEL PUMP									Component ATA:28
PN:6628200303-003	MOS/MSC	10-May-05	O/C	TSN 0						
SN:12AV74	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-20-02										
282088	RH STANDBY FUEL PUMP									Component ATA:28
PN:6628200303-003	MOS/MSC	10-May-05	O/C	TSN 0						
SN:12AV75	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-20-02										
282113	LH FUEL TRANSFER VALVE									Component ATA:28
PN:7628200104-001	MOS/MSC	10-May-05	O/C	TSN 0						
SN:M0144CV1104	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-12-03										
282114	RH FUEL TRANSFER VALVE									Component ATA:28
PN:7628200104-001	MOS/MSC	10-May-05	O/C	TSN 0						
SN:M0145CV1104	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-12-03										
284001	C1 FUEL PROBE ASSEMBLY									Component ATA:28
PN:6628408000-001	MOS/MSC	10-May-05	O/C	TSN 0						
SN:0709	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-05										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
284002	C2 FUEL PROBE ASSEMBLY									Component ATA:28
PN:6628408000-027	MOS/MSC	22-Feb-06	O/C							
SN:0663	HRS	386.77								
	AFL	298								
PROC. REF: AMM 28-40-05										
284003	C3 FUEL PROBE ASSEMBLY									Component ATA:28
PN:6628408000-005	MOS/MSC	10-May-05	O/C	TSN 0						
SN:0688	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-05										
284004	C4 FUEL PROBE ASSEMBLY									Component ATA:28
PN:6628408000-007	MOS/MSC	10-May-05	O/C	TSN 0						
SN:0796	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-05										
284005	C5 FUEL PROBE ASSEMBLY									Component ATA:28
PN:6628408000-009	MOS/MSC	10-May-05	O/C	TSN 0						
SN:1041	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-05										
284006	C6 FUEL PROBE ASSEMBLY									Component ATA:28
PN:6628408000-011	MOS/MSC	10-May-05	O/C	TSN 0						
SN:1349	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-05										
284008	C8 FUEL PROBE ASSEMBLY									Component ATA:28
PN:6628408000-001	MOS/MSC	10-May-05	O/C	TSN 0						
SN:0727	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-05										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
284009	C9 FUEL PROBE ASSEMBLY									Component ATA:28
PN:6628408000-027	MOS/MSC	22-Feb-06	O/C							
SN:7240	HRS	386.77								
	AFL	298								
PROC. REF: AMM 28-40-05										
284010	C10 FUEL PROBE ASSEMBLY									Component ATA:28
PN:6628408000-005	MOS/MSC	10-May-05	O/C	TSN 0						
SN:0710	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-05										
284011	C11 FUEL PROBE ASSEMBLY									Component ATA:28
PN:6628408000-019	MOS/MSC	10-May-05	O/C	TSN 0						
SN:811	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-05										
284012	C12 FUEL PROBE ASSEMBLY									Component ATA:28
PN:6628408000-009	MOS/MSC	10-May-05	O/C	TSN 0						
SN:1039	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-05										
284013	C13 FUEL PROBE ASSEMBLY									Component ATA:28
PN:6628408000-011	MOS/MSC	10-May-05	O/C	TSN 0						
SN:1352	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-05										
284014	C14 FUEL PROBE ASSEMBLY									Component ATA:28
PN:6628408000-011	MOS/MSC	10-May-05	O/C	TSN 0						
SN:1351	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-05										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
284015	C15 FUEL PROBE ASSEMBLY									Component ATA:28
PN:6628408000-021	MOS/MSC	10-May-05	O/C	TSN 0						
SN:0677	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-05										
284016	C16 FUEL PROBE ASSEMBLY									Component ATA:28
PN:6628408000-011	MOS/MSC	10-May-05	O/C	TSN 0						
SN:1356	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-05										
284017	C17 FUEL PROBE ASSEMBLY									Component ATA:28
PN:6628408000-021	MOS/MSC	10-May-05	O/C	TSN 0						
SN:0676	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-05										
284033	FUSELAGE FUEL PROBE									Component ATA:28
PN:6628408000-019	MOS/MSC	10-May-05	O/C	TSN 0						
SN:811	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-05										
284045	FUEL QUANTITY SIGNAL CONDITIONER									Component ATA:28
PN:10551B08Y09	MOS/MSC	07-Dec-13	O/C							
SN:B0676	HRS	5894.57								
	AFL	4812								
PROC. REF: AMM 28-40-05										
5-19-00-D2820013	PERFORM INITIAL CLEANING AND LEAK CHECK OF LOW PRESSURE FUEL FILTERS (IRN D2820013)									Service ATA:28
	MOS/MSC	04-Aug-05	-							
	HRS	31.7								
	AFL	22								
PROC. REF: AMM 28-20-15										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
F2840003^S ** FUEL QUANTITY SIGNAL CONDITIONER - PERFORM FUNCTIONAL TEST TO VERIFY WEIGHT-ON-WHEELS (WOW) INPUTS (AWL**) Service ATA:28										
	MOS	11-Mar-22	48 (+14d/-14d)					AIRWORTHINESS		
	HRS	8721.2	1200 (+25/-25)							
	AFL	7006								
PROC. REF: AMM 28-40-00										PKG:14
Y2810001^S WING TANKS - REMOVE FUEL TANK ACCESS PANELS AND PERFORM VISUAL INSPECTION Service ATA:28										
	MOS	25-Jan-24	24 (+14d/-14d)							
	HRS	9265.8	600 (+25/-25)							
	AFL	7395								
PROC. REF: GENERIC NO REF										PKG:10
Y2810002^S WING TANKS - REMOVE FUEL TANK ACCESS PANELS AND PERFORM VISUAL INSPECTION. Service ATA:28										
	MOS	10-May-23	96 (+14d/-14d)							
	HRS	9071.3	2400 (+25/-25)							
	AFL	7252								
PROC. REF: GENERIC NO REF										PKG:22
Y2820000^S LOW PRESSURE FUEL FILTER - REMOVE AND INSPECT FOR CONTAMINATION. CLEAN IF NECESSARY Service ATA:28										
	MOS	25-Jan-24	24 (+14d/-14d)							
	HRS	9265.8	600 (+25/-25)							
	AFL	7395								
PROC. REF: AMM 28-20-15										PKG:10
ATA 29 - HYDRAULIC POWER										
291013 HYDRAULIC FUEL SHUTOFF VALVE Component ATA:29										
PN:6600355-2	MOS/MSC	10-May-05	O/C	TSN 0						
SN:04-1019160	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 29-10-05										
291033 PRESSURE CONTROL MODULE BOX Component ATA:29										
PN:ZVM11-2	MOS/MSC	10-May-05	O/C	TSN 0						
SN:04-101135	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 29-10-06										
291034 RESERVOIR FLOAT SENSOR Component ATA:29										
PN:3L14F-17	MOS/MSC	10-May-05	O/C	TSN 0						
SN:497	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 29-30-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 29 - HYDRAULIC POWER										
291045 LH ENGINE DRIVEN HYDRAULIC PUMP Component ATA:29										
PN:6629101000-001	MOS/MSC	10-May-05	O/C	TSN 0						
SN:MX683284A	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 29-10-01										
291046 RH ENGINE DRIVEN HYDRAULIC PUMP Component ATA:29										
PN:6629101000-001	MOS/MSC	10-May-05	O/C	TSN 0						
SN:MX683286A	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 29-10-01										
291057 MAIN HYDRAULIC SYSTEM ACCUMULATOR Component ATA:29										
PN:88746-1	MOS/MSC	10-May-05	O/C	TSN 0						
SN:313	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 29-10-04										
291059 MAIN HYDRAULIC FILTER MANIFOLD ASSEMBLY Component ATA:29										
PN:2247H000-004	MOS/MSC	27-Mar-15	O/C	TSR 0						
SN:1583	HRS	6705.27		TSR 0						
	AFL	5447		TSR 0						
PROC. REF: AMM 29-10-03										
291069 THERMAL SHUTOFF VALVE Component ATA:29										
PN:98050	MOS/MSC	10-May-05	O/C	TSN 0						
SN:0513	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 29-10-07										
292011 AUXILIARY HYDRAULIC PUMP ASSEMBLY Component ATA:29										
PN:6629201000-013	MOS/MSC	29-May-14	O/C							
SN:K0304	HRS									
	AFL									
PROC. REF: AMM 29-20-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 29 - HYDRAULIC POWER										
293011	HYDRAULIC PRESSURE TRANSDUCER									Component ATA:29
PN:7629301001-001	MOS/MSC	10-May-05	O/C	TSN 0						
SN:7052-2-50	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 29-30-04										
293012	PRESSURE TRANSDUCER									Component ATA:29
PN:7629301001-001	MOS/MSC	10-May-05	O/C	TSN 0						
SN:7052-2-48	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 29-30-04										
293021	HYDRAULIC GROUND SERVICE CONTROL BOX									Component ATA:29
PN:4529308000V9-001	MOS/MSC	10-May-05	O/C	TSN 0						
SN:A5050	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 29-30-01										
5-19-01-D2910017	REPLACE MAIN HYDRAULIC FILTER MANIFOLD ELEMENTS (IRN D2910017)									Service ATA:29
	MOS/MSC	04-Aug-05	-							
	HRS	31.7								
	AFL	22								
PROC. REF: AMM 29-10-03										
5-19-01-D2910018	REPLACE MAIN HYDRAULIC FILTER MANIFOLD ELEMENTS (IRN D2910018)									Service ATA:29
	MOS	25-Jan-24								
	HRS	9265.8	300 (+25/-25)		9565.8	9590.8	50.1 (+25)			
	AFL	7395								
PROC. REF: AMM 29-10-03										
5-19-01-O2910005	REPLACE AUXILIARY HYDRAULIC FILTER MANIFOLD ELEMENTS (IRN O2910005)									Service ATA:29
	MOS	10-May-23								
	HRS	9071.3	2400 (+25/-25)	Adj -2.03	11469.27	11494.27	1953.6 (+25)			
	AFL	7252								
PROC. REF: AMM 29-20-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 29 - HYDRAULIC POWER										
T2910026^S RELIEF FUNCTION OF THE HYDRAULIC RESERVOIR PRESSURIZATION CONTROL MODULE - PERFORM FUNCTIONALTEST										
	MOS	11-Mar-22	48 (+14d/-14d)						Service	ATA:29
	HRS	8721.2	1200 (+25/-25)							
	AFL	7006								
PROC. REF: AMM 29-10-06										PKG:14
Y2910001^S HYDRAULIC COMPONENTS AND ASSOCIATED PLUMBING (AFT OF FUSELAGE FUEL CELL, FS 495 TO FS 512) - PERFORM VISUAL INSPECTION										
	MOS	11-Mar-22	48 (+14d/-14d)						Service	ATA:29
	HRS	8721.2	1200 (+25/-25)							
	AFL	7006								
PROC. REF: GENERIC NO REF										PKG:14
Y2910002^S HYDRAULIC COMPONENTS AND ASSOCIATED PLUMBING (WHEEL WELL AND FORWARD AREA OF REAR SPAR) - PERFORM VISUAL INSPECTION.										
	MOS	11-Mar-22	48 (+14d/-14d)						Service	ATA:29
	HRS	8721.2	1200 (+25/-25)							
	AFL	7006								
PROC. REF: GENERIC NO REF										PKG:17
Y2910003^S HYDRAULIC COMPONENTS AND ASSOCIATED PLUMBING (AFT AREA OF REAR SPAR) - PERFORM VISUAL INSPECTION										
	MOS	10-May-23	96 (+14d/-14d)						Service	ATA:29
	HRS	9071.3	2400 (+25/-25)							
	AFL	7252								
PROC. REF: GENERIC NO REF										PKG:19
Y2920001^S AUXILIARY HYDRAULIC SYSTEM - PERFORM OPERATIONAL CHECK										
	MOS	11-Mar-22	48 (+14d/-14d)						Service	ATA:29
	HRS	8721.2	1200 (+25/-25)							
	AFL	7006								
PROC. REF: AMM 29-20-00										PKG:13
ATA 30 - ICE AND RAIN PROTECTION										
301063 LH PRESS REG/MOD SHUTOFF VALVE										
PN:6621000000-087	MOS/MSC	10-May-05	O/C	TSN 0					Component	ATA:30
SN:839	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 30-10-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 30 - ICE AND RAIN PROTECTION										
301064	RH PRESS REG/MOD SHUTOFF VALVE									Component ATA:30
PN:662100000-087	MOS/MSC	10-May-05	O/C	TSN 0						
SN:845	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 30-10-01										
304021	WINDSHIELD ANTI-ICE CONTROLLER									Component ATA:30
PN:90825-9	MOS/MSC	30-Jun-17	O/C							
SN:267	HRS	7012.8								
	AFL	5698								
PROC. REF: AMM 30-40-01										
308006	ICE DETECT PROBE									Component ATA:30
PN:0871HN2	MOS/MSC	10-May-05	O/C	TSN 0						
SN:0329	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 30-80-01										
5-19-00-AC3010006	** ANTI-ICE MANIFOLD ASSEMBLY - PERFORM BORESCOPE INSPECTION (AWL)**									Service ATA:30
	MOS	03-Nov-22						AIRWORTHINESS		
	HRS	8950.9	600 (+25/-25)		9550.9	9575.9	35.2 (+25)			
	AFL	7175								
PROC. REF: AMM 30-10-07										
5-19-00-Z3020005-LEFT	LEFT * ENGINE INLET ANTI-ICE TUBE ASSEMBLY FROM THE AFT INLET BULKHEAD CONNECTION POINT FORWARD TO SPRAY RING CONNECTION, PERFORM DETAILED VISUAL/BORESCOPE INSPECTION OF THE WELDS INSIDE AND OUTSIDE OF THE TUBE AT BOTH FORWARD AND AFT ENDS. (AWL*)									Service ATA:30
	MOS	22-Apr-24						AIRWORTHINESS		
	HRS	9368.9	250		9618.9		103.2			
	AFL	7476								
PROC. REF: AMM 30-20-00										
5-19-00-Z3020005-RIGHT	RIGHT * ENGINE INLET ANTI-ICE TUBE ASSEMBLY FROM THE AFT INLET BULKHEAD CONNECTION POINT FORWARD TO SPRAY RING CONNECTION, PERFORM DETAILED VISUAL/BORESCOPE INSPECTION OF THE WELDS INSIDE AND OUTSIDE OF THE TUBE AT BOTH FORWARD AND AFT ENDS. (AWL*)									Service ATA:30
	MOS	22-Apr-24						AIRWORTHINESS		
	HRS	9368.9	250		9618.9		103.2			
	AFL	7476								
PROC. REF: AMM 30-20-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 30 - ICE AND RAIN PROTECTION										
5-19-00-Z3020006-LEFT	LEFT ENGINE INLET ANTI-ICE TUBE ASSEMBLY FROM THE AFT INLET BULKHEAD CONNECTION POINT FORWARD TO SPRAY RING CONNECTION, PERFORM DETAILED VISUAL/BORESCOPE INSPECTION OF THE WELDS INSIDE AND OUTSIDE OF THE TUBE AT BOTH FORWARD AND AFT ENDS.								Service	ATA:30
	MOS/MSC	10-May-05	N/A							
	HRS	0								
	AFL	0								
PROC. REF: AMM 30-20-00										
5-19-00-Z3020006-RIGHT	RIGHT ENGINE INLET ANTI-ICE TUBE ASSEMBLY FROM THE AFT INLET BULKHEAD CONNECTION POINT FORWARD TO SPRAY RING CONNECTION, PERFORM DETAILED VISUAL/BORESCOPE INSPECTION OF THE WELDS INSIDE AND OUTSIDE OF THE TUBE AT BOTH FORWARD AND AFT ENDS								Service	ATA:30
	MOS/MSC	10-May-05	N/A							
	HRS	0								
	AFL	0								
PROC. REF: AMM 30-20-00										
A3020000 ^S	** NACELLE ANTI-ICE SYSTEM - PERFORM FUNCTIONAL TEST (AWL**)								Service	ATA:30
	MOS	11-Mar-22	48 (+14d/-14d)	AIRWORTHINESS						
	HRS	8721.2	1200 (+25/-25)							
	AFL	7006								
PROC. REF: AMM 30-20-00										
A3030000 ^S	** PITOT-STATIC HEAT SYSTEM - PERFORM OPERATIONAL CHECK (AWL**)								Service	ATA:30
	MOS	10-May-23	96 (+14d/-14d)	AIRWORTHINESS						
	HRS	9071.3	2400 (+25/-25)							
	AFL	7252								
PROC. REF: AMM 30-30-00										
H3010000 ^S	** WING/STAB ANTI-ICE SWITCH - PERFORM OPERATIONAL CHECK (AWL**)								Service	ATA:30
	MOS	25-Jan-24	24 (+14d/-14d)	AIRWORTHINESS						
	HRS	9265.8	600 (+25/-25)							
	AFL	7395								
PROC. REF: AMM 30-10-00										
T3040000 ^S	** PERFORM FUNCTIONAL TEST OF THE WINDSHIELD ANTI-ICE SYSTEM. (AWL**)								Service	ATA:30
	MOS	25-Jan-24	24 (+14d/-14d)	AIRWORTHINESS						
	HRS	9265.8	600 (+25/-25)							
	AFL	7395								
PROC. REF: AMM 30-40-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 30 - ICE AND RAIN PROTECTION											
Y3010007 ^S		WING ANTI-ICE PICCOLO TUBE - PERFORM DETAILED VISUAL INSPECTION FOR CRACKS AT W.S. 43 AND W.S. 176.							Service	ATA:30	
	MOS	25-Jan-24	24 (+14d/-14d)								
	HRS	9265.8	600 (+25/-25)								
	AFL	7395									
PROC. REF: GENERIC NO REF										PKG:10	
Y3080000 ^S		ICE DETECTION SYSTEM - PERFORM FUNCTIONAL TEST							Service	ATA:30	
	MOS	11-Mar-22	48 (+14d/-14d)								
	HRS	8721.2	1200 (+25/-25)								
	AFL	7006									
PROC. REF: AMM 30-80-00										PKG:13	
ATA 31 - INDICATING/RECORDING SYSTEMS											
311607		CENTER SWITCH PANEL							Component	ATA:31	
PN:M4525188576-041-641	MOS/MSC	10-May-05	O/C	TSN 0							
SN:MAN147556	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 31-11-03											
311805		ENGINE FUEL CONTROL PANEL							Component	ATA:31	
PN:4576108500-025	MOS/MSC	16-May-22	O/C								
SN:A00381795-01	HRS	8777.4									
	AFL	7052									
PROC. REF: AMM 31-11-05											
312001		PILOT CLOCK							Component	ATA:31	
PN:M850	MOS/MSC	24-Sep-21	O/C	TSN 0							
SN:A8274	HRS	8457.7		TSN 0							
	AFL	6804		TSN 0							
PROC. REF: AMM 31-21-01											
312002		COPILOT CLOCK							Component	ATA:31	
PN:M850-5V-LA	MOS/MSC	29-Nov-14	O/C								
SN:A3472	HRS	6566.75									
	AFL	5343									
PROC. REF: AMM 31-21-01											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 31 - INDICATING/RECORDING SYSTEMS										
312011 REPLACE PILOT DIGITAL CLOCK BATTERY Component ATA:31										
PN:DURACELL N	MOS	22-Apr-24	12 (+14d/-14d)	TSN 0	22-Apr-25	06-May-25	158 d (+14)			
SN:UNKNOWN	HRS	9368.9		TSN 0						
	AFL	7476		TSN 0						
PROC. REF: AMM 31-21-02										
312012 REPLACE COPILOT DIGITAL CLOCK BATTERY Component ATA:31										
PN:DURACELL N	MOS	22-Apr-24	12 (+14d/-14d)	TSN 0	22-Apr-25	06-May-25	158 d (+14)			
SN:UNKNOWN	HRS	9368.9		TSN 0						
	AFL	7476		TSN 0						
PROC. REF: AMM 31-21-02										
314001 SELCAL DECODER Component ATA:31										
PN:1200006-102	MOS/MSC	18-Jul-05	O/C	TSN 0						
SN:1675	HRS	18.9		TSN 0						
	AFL	15		TSN 0						
PROC. REF: GENERIC NO REF										
314011 NO. 1 DATA ACQUISITION UNIT Component ATA:31										
PN:7013348-938	MOS/MSC	26-Jul-24	O/C							
SN:01084576	HRS	9450.9								
	AFL	7531								
PROC. REF: AMM 31-42-01										
314012 NO. 2 DATA ACQUISITION UNIT Component ATA:31										
PN:7013348-938	MOS/MSC	26-Jul-24	O/C							
SN:06056251	HRS	9450.9								
	AFL	7531								
PROC. REF: AMM 31-42-01										
314023 NO. 1 IC-600 INTEGRATED AVIONICS COMPUTER Component ATA:31										
PN:7017000-82222	MOS/MSC	30-Mar-22	O/C							
SN:06077657	HRS	8750.5								
	AFL	7031								
PROC. REF: AMM 31-41-01										
314024 NO. 2 IC-600 INTEGRATED AVIONICS COMPUTER Component ATA:31										
PN:7017000-82222	MOS/MSC	10-May-05	O/C	TSN 0						
SN:00012987	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-41-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 31 - INDICATING/RECORDING SYSTEMS										
314051	LH IM-600 MEMORY MODULE									Component ATA:31
PN:7025973-04214	MOS/MSC	01-Dec-05	O/C	TSN 0						
SN:05013483	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-41-02										
314052	RH IM-600 MEMORY MODULE									Component ATA:31
PN:7025973-04214	MOS/MSC	01-Dec-05	O/C	TSN 0						
SN:05013484	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-41-02										
315001	CREW WARNING PANEL									Component ATA:31
PN:90-42801-8	MOS/MSC	10-May-05	O/C	TSN 0						
SN:387	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-51-01										
316025	PILOT EFIS DISPLAY CONTROLLER									Component ATA:31
PN:7016986-733	MOS/MSC	10-May-05	O/C	TSN 0						
SN:05015778	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-60-02										
316026	COPILOT EFIS DISPLAY CONTROLLER									Component ATA:31
PN:7016986-733	MOS/MSC	10-May-05	O/C	TSN 0						
SN:05015779	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-60-02										
B310000 ^S	** INDICATING/RECORDING SYSTEM - PERFORM OPERATIONAL CHECK (AWL**)									Service ATA:31
	MOS	25-Jan-24	24 (+14d/-14d)					AIRWORTHINESS		
	HRS	9265.8	600 (+25/-25)							
	AFL	7395								
PROC. REF: AMM 31-00-00										
PKG:7										
ATA 32 - LANDING GEAR										
320041	* LEFT UPPER MAIN LANDING GEAR LINK PIN (IRN N3220101) (AWL*)									Component ATA:32
PN:200-0214-101	MOS	14-Dec-05		TSN 0				LIFE LIMIT		
SN:NSN	HRS	2600.03		TSN 0						
	AFL	2143	10000	TSN 2143	10000		2424			
PROC. REF: AMM 32-10-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
320042	* RIGHT UPPER MAIN LANDING GEAR LINK PIN (IRN N3220101) (AWL*)									Component ATA:32
PN:200-0214-101	MOS	14-Dec-05		TSN 0				LIFE LIMIT		
SN:NSN	HRS	2600.03		TSN 0						
	AFL	2143	10000	TSN 2143	10000		2424			
PROC. REF: AMM 32-10-01										
320043	* LEFT LOWER MAIN LANDING GEAR LINK PIN (IRN N3220101) (AWL*)									Component ATA:32
PN:200-0204-001	MOS	14-Dec-05		TSN 0				LIFE LIMIT		
SN:NSN	HRS	2600.03		TSN 0						
	AFL	2143	10000	TSN 2143	10000		2424			
PROC. REF: AMM 32-10-01										
320044	* RIGHT LOWER MAIN LANDING GEAR LINK PIN (IRN N3220101) (AWL*)									Component ATA:32
PN:200-0204-001	MOS	14-Dec-05		TSN 0				LIFE LIMIT		
SN:NSN	HRS	2600.03		TSN 0						
	AFL	2143	10000	TSN 2143	10000		2424			
PROC. REF: AMM 32-10-01										
320051	LEFT * MAIN LANDING GEAR PISTON PIN (IRN N3220102) (AWL*)									Component ATA:32
PN:200-0215-101	MOS	14-Dec-05		TSN 0				LIFE LIMIT		
SN:NSN	HRS	2600.03		TSN 0						
	AFL	2143	10000	TSN 2143	10000		2424			
PROC. REF: AMM 32-10-01										
320052	RIGHT * MAIN LANDING GEAR PISTON PIN (IRN N3220102) (AWL*)									Component ATA:32
PN:200-0215-101	MOS	14-Dec-05		TSN 0				LIFE LIMIT		
SN:NSN	HRS	2600.03		TSN 0						
	AFL	2143	10000	TSN 2143	10000		2424			
PROC. REF: AMM 32-10-01										
320061	* LEFT MAIN LANDING GEAR ACTUATOR PISTON (IRN N3220103). (AWL*)									Component ATA:32
PN:200-0301-103	MOS	15-Nov-10		TSN 0				LIFE LIMIT		
SN:NSN	HRS	0		TSN 0						
	AFL	0	17000	TSN 0	17000		9424			
PROC. REF: AMM 32-31-01										
320062	* RIGHT MAIN LANDING GEAR ACTUATOR PISTON (IRN N3220103). (AWL*)									Component ATA:32
PN:200-0301-103	MOS	15-Nov-10		TSN 0				LIFE LIMIT		
SN:NSN	HRS	0		TSN 0						
	AFL	0	17000	TSN 0	17000		9424			
PROC. REF: AMM 32-31-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
320071	* LEFT MAIN LANDING GEAR ACTUATOR CYLINDER (IRN N3220104) (AWL*)									Component ATA:32
PN:200-0302-101	MOS	15-Nov-10		TSN 0				LIFE LIMIT		
SN:NSN	HRS	0		TSN 0						
	AFL	0	17000	TSN 0	17000		9424			
PROC. REF: AMM 32-31-01										
320072	* RIGHT MAIN LANDING GEAR ACTUATOR CYLINDER (IRN N3220104) (AWL*)									Component ATA:32
PN:200-0302-101	MOS	15-Nov-10		TSN 0				LIFE LIMIT		
SN:NSN	HRS	0		TSN 0						
	AFL	0	17000	TSN 0	17000		9424			
PROC. REF: AMM 32-31-01										
320081	* LEFT MAIN LANDING GEAR ACTUATOR END CAP (IRN T3220105) (AWL*)									Component ATA:32
PN:200-0303-001	MOS	25-Jan-15						LIFE LIMIT		
SN:H2466	HRS	6669.27								
	AFL	5419	2387	TSN 0	7806		230			
PROC. REF: AMM 32-31-01										
320082	* RIGHT MAIN LANDING GEAR ACTUATOR END CAP (IRN T3220105) (AWL*)									Component ATA:32
PN:200-0303-001	MOS	25-Jan-15						LIFE LIMIT		
SN:H2458	HRS	6669.27								
	AFL	5419	2387	TSN 0	7806		230			
PROC. REF: AMM 32-31-01										
320091	* LEFT MAIN LANDING GEAR ACTUATOR HOUSING (IRN N3220106) (AWL*)									Component ATA:32
PN:200-0304-001	MOS	15-Nov-10		TSN 0				LIFE LIMIT		
SN:NSN	HRS	0		TSN 0						
	AFL	0	17000	TSN 0	17000		9424			
PROC. REF: AMM 32-31-01										
320092	* RIGHT MAIN LANDING GEAR ACTUATOR HOUSING (IRN N3220106) (AWL*)									Component ATA:32
PN:200-0304-001	MOS	15-Nov-10		TSN 0				LIFE LIMIT		
SN:NSN	HRS	0		TSN 0						
	AFL	0	17000	TSN 0	17000		9424			
PROC. REF: AMM 32-31-01										
321001	* LEFT MAIN LANDING GEAR STRUT ASSEMBLY (IRN N3220012) (AWL*)									Component ATA:32
PN:200-0200-011	MOS	10-May-23		TSN 216				LIFE LIMIT		
SN:H0319	HRS	9071.3		TSN 9071.3						
	AFL	7252	10000	TSN 7252	10000		2424			
PROC. REF: AMM 32-10-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
321001A LEFT MAIN LANDING GEAR STRUT ASSEMBLY - SPECIAL DETAILED INSPECTION (IRN AA3220018) Service ATA:32										
PN:200-0200-011	MOS	10-May-23	96 (+14d/-14d)		10-May-31	24-May-31	2367 d (+14)			
SN:H0319	HRS	9071.3								
	AFL	7252	6600 (+25/-25)		13852	13877	6276 (+25)			
PROC. REF: GENERIC NO REF										
321002 * RIGHT MAIN LANDING GEAR STRUT ASSEMBLY (IRN N3220012) (AWL*) Component ATA:32										
PN:200-0200-012	MOS	10-May-23		TSN 216				LIFE LIMIT		
SN:H1323	HRS	9071.3		TSN 9071.3						
	AFL	7252	10000	TSN 7252	10000		2424			
PROC. REF: AMM 32-10-01										
321002A RIGHT MAIN LANDING GEAR STRUT ASSEMBLY - SPECIAL DETAILED INSPECTION (IRN AA3220018) Service ATA:32										
PN:200-0200-012	MOS	10-May-23	96 (+14d/-14d)		10-May-31	24-May-31	2367 d (+14)			
SN:H1323	HRS	9071.3								
	AFL	7252	6600 (+25/-25)		13852	13877	6276 (+25)			
PROC. REF: GENERIC NO REF										
321011 * REPLACE LEFT MAIN LANDING GEAR SHOCK STRUT CYLINDER (IRN N3220116) (AWL*) Component ATA:32										
PN:200-0201-005	MOS	14-Dec-05		TSN 0				LIFE LIMIT		
SN:NSN	HRS	0		TSN 0						
	AFL	0	10000	TSN 0	10000		2424			
PROC. REF: AMM 32-10-01										
321012 * REPLACE RIGHT MAIN LANDING GEAR SHOCK STRUT CYLINDER (IRN N3220116) (AWL*) Component ATA:32										
PN:200-0201-006	MOS	14-Dec-05		TSN 0				LIFE LIMIT		
SN:NSN	HRS	0		TSN 0						
	AFL	0	10000	TSN 0	10000		2424			
PROC. REF: AMM 32-10-01										
321025 LEFT * MAIN LANDING GEAR SIDE STAY ACTUATOR UPPER PIN (P/N 200-0325). (IRN T3220014). (AWL*) Component ATA:32										
PN:200-0325-101	MOS	13-Apr-18	96	TSN 0	13-Apr-26		514 d	LIFE LIMIT		
SN:H3127	HRS	7237.4		TSN 0						
	AFL	5866		TSN 0						
PROC. REF: AMM 32-31-01										
321025A * LEFT UPPER MAIN LANDING GEAR SIDE-STAY ACTUATOR PINS - PERFORM MAGNETIC PARTICLE INSPECTION (IRN T3220024) (AWL*) Service ATA:32										
PN:200-0325-101	MOS	11-Aug-21	48		11-Aug-25		269 d	AIRWORTHINESS		
SN:H3127	HRS	8435.1								
	AFL	6787								
PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
321025B * LEFT UPPER MAIN LANDING GEAR SIDE-STAY ACTUATOR PINS - PERFORM DETAILED VISUAL INSPECTION (IRN T3220135) (AWL*) Service ATA:32										
PN:200-0325-101	MOS	11-Aug-21	48		11-Aug-25		269 d	AIRWORTHINESS		
SN:H3127	HRS	8435.1								
	AFL	6787								
PROC. REF: GENERIC NO REF										
321026 RIGHT * MAIN LANDING GEAR SIDE STAY ACTUATOR UPPER PIN (P/N 200-0325). (IRN T3220014) (AWL*) Component ATA:32										
PN:200-0325-101	MOS	13-Apr-18	96	TSN 0	13-Apr-26		514 d	LIFE LIMIT		
SN:H3070	HRS	7237.4		TSN 0						
	AFL	5866		TSN 0						
PROC. REF: AMM 32-31-01										
321026A * RIGHT UPPER MAIN LANDING GEAR SIDE-STAY ACTUATOR PINS - PERFORM MAGNETIC PARTICLE INSPECTION (IRN T3220024) (AWL*) Service ATA:32										
PN:200-0325-101	MOS	11-Aug-21	48		11-Aug-25		269 d	AIRWORTHINESS		
SN:H3070	HRS	8435.1								
	AFL	6787								
PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01										
321026B * RIGHT UPPER MAIN LANDING GEAR SIDE-STAY ACTUATOR PINS - PERFORM DETAILED VISUAL INSPECTION (IRN T3220135) (AWL*) Service ATA:32										
PN:200-0325-101	MOS	11-Aug-21	48		11-Aug-25		269 d	AIRWORTHINESS		
SN:H3070	HRS	8435.1								
	AFL	6787								
PROC. REF: GENERIC NO REF										
321037 LEFT * MAIN LANDING GEAR SIDE STAY ACTUATOR LOWER PIN (P/N 200-0217). (IRN T3220038) (AWL*) Component ATA:32										
PN:200-0217-101	MOS	13-Apr-18	96	TSN 0	13-Apr-26		514 d	LIFE LIMIT		
SN:H3497	HRS	7237.4		TSN 0						
	AFL	5866		TSN 0						
PROC. REF: AMM 32-31-01										
321037A * LEFT LOWER MAIN LANDING GEAR SIDE-STAY ACTUATOR PINS - PERFORM MAGNETIC PARTICLE INSPECTION (IRN T3220024) (AWL*) Service ATA:32										
PN:200-0217-101	MOS	11-Aug-21	48		11-Aug-25		269 d	AIRWORTHINESS		
SN:H3497	HRS	8435.1								
	AFL	6787								
PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01										

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
321037B * LEFT LOWER MAIN LANDING GEAR SIDE-STAY ACTUATOR PINS - PERFORM DETAILED VISUAL INSPECTION (IRN T3220135) (AWL*) Service ATA:32										
PN:200-0217-101	MOS	11-Aug-21	48		11-Aug-25		269 d	AIRWORTHINESS		
SN:H3497	HRS	8435.1								
	AFL	6787								
PROC. REF: GENERIC NO REF										
321038 RIGHT * MAIN LANDING GEAR SIDE STAY ACTUATOR LOWER PIN (P/N 200-0217). (IRN T3220038) (AWL*) Component ATA:32										
PN:200-0217-101	MOS	13-Apr-18	96	TSN 0	13-Apr-26		514 d	LIFE LIMIT		
SN:H3369	HRS	7237.4		TSN 0						
	AFL	5866		TSN 0						
PROC. REF: AMM 32-31-01										
321038A * RIGHT LOWER MAIN LANDING GEAR SIDE-STAY ACTUATOR PINS - PERFORM MAGNETIC PARTICLE INSPECTION (IRN T3220024) (AWL*) Service ATA:32										
PN:200-0217-101	MOS	11-Aug-21	48		11-Aug-25		269 d	AIRWORTHINESS		
SN:H3369	HRS	8435.1								
	AFL	6787								
PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01										
321038B * RIGHT LOWER MAIN LANDING GEAR SIDE-STAY ACTUATOR PINS - PERFORM DETAILED VISUAL INSPECTION (IRN T3220135) (AWL*) Service ATA:32										
PN:200-0217-101	MOS	11-Aug-21	48		11-Aug-25		269 d	AIRWORTHINESS		
SN:H3369	HRS	8435.1								
	AFL	6787								
PROC. REF: GENERIC NO REF										
321049 LEFT * MAIN LANDING GEAR AXLE BEAM (IRN N3220036) (AWL*) Component ATA:32										
PN:200-0203-001	MOS	14-Dec-05						LIFE LIMIT		
SN:H0726	HRS	2600.03								
	AFL	2143	10000	TSN 2143	10000		2424			
PROC. REF: AMM 32-10-01										
321050 RIGHT * MAIN LANDING GEAR AXLE BEAM (IRN N3220036) (AWL*) Component ATA:32										
PN:200-0203-001	MOS	14-Dec-05						LIFE LIMIT		
SN:H0722	HRS	2600.03								
	AFL	2143	10000	TSN 2143	10000		2424			
PROC. REF: AMM 32-10-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
321085 L/H FWD MAIN LANDING GEAR TRUNNION BREAKOUT BLK ASSEMBLY Component ATA:32										
PN:4532103011-009	MOS/MSC	10-May-05	O/C	TSN 0						
SN:CYC064	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
321086 R/H FWD MAIN LANDING GEAR TRUNNION BREAKOUT BLK ASSEMBLY Component ATA:32										
PN:4532103011-010	MOS/MSC	10-May-05	O/C	TSN 0						
SN:CYC061	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
321087 LH AFT MAIN LANDING GEAR TRUNNION BREAKOUT BLK ASSEMBLY Component ATA:32										
PN:4532103021-007	MOS/MSC	10-May-05	O/C	TSN 0						
SN:CYC053	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
321088 RIGHT AFT MAIN LANDING GEAR TRUNNION BREAKOUT BLK ASSEMBLY Component ATA:32										
PN:4532103021-008	MOS/MSC	10-May-05	O/C	TSN 0						
SN:CYC049	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
321101 LEFT FORWARD * MAIN LANDING GEAR TRUNNION PIN (IRN N3220023) (AWL*) Component ATA:32										
PN:200-0212-103	MOS	10-May-05		TSN 0				LIFE LIMIT		
SN:H0895	HRS	0		TSN 0						
	AFL	0	10000	TSN 0	10000		2424			
PROC. REF: AMM 32-10-01										
321102 RIGHT FORWARD * MAIN LANDING GEAR TRUNNION PIN (IRN N3220023) (AWL*) Component ATA:32										
PN:200-0212-103	MOS	10-May-05		TSN 0				LIFE LIMIT		
SN:H0894	HRS	0		TSN 0						
	AFL	0	10000	TSN 0	10000		2424			
PROC. REF: AMM 32-10-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
321103 LEFT AFT * MAIN LANDING GEAR TRUNNION PIN (IRN N3220023) (AWL*) Component ATA:32										
PN:200-0213-103	MOS		10-May-05		TSN 0			LIFE LIMIT		
SN:H0676	HRS		0		TSN 0					
	AFL		0	10000	TSN 0	10000	2424			
PROC. REF: AMM 32-10-01										
321104 RIGHT AFT * MAIN LANDING GEAR TRUNNION PIN (IRN N3220023) (AWL*) Component ATA:32										
PN:200-0213-103	MOS		10-May-05		TSN 0			LIFE LIMIT		
SN:H0684	HRS		0		TSN 0					
	AFL		0	10000	TSN 0	10000	2424			
PROC. REF: AMM 32-10-01										
321111 LEFT FORWARD LOWER * MAIN LANDING GEAR TRUNNION SHEAR PIN (AWL*) Component ATA:32										
PN:4532103201-001	MOS		26-Oct-14					LIFE LIMIT		
SN:1174	HRS		6496.17							
	AFL		5289	5000	TSN 0	10289	2713			
PROC. REF: AMM 57-10-05										
321112 RIGHT FORWARD LOWER * MAIN LANDING GEAR TRUNNION SHEAR PIN (AWL*) Component ATA:32										
PN:4532103201-001	MOS		26-Oct-14					LIFE LIMIT		
SN:CMI1418	HRS		6496.17							
	AFL		5289	5000	TSN 0	10289	2713			
PROC. REF: AMM 57-10-05										
321113 LEFT FORWARD UPPER * MAIN LANDING GEAR TRUNNION SHEAR PIN (AWL*) Component ATA:32										
PN:4532103201-001	MOS		26-Oct-14					LIFE LIMIT		
SN:CMI1440	HRS		6496.17							
	AFL		5289	5000	TSN 0	10289	2713			
PROC. REF: AMM 57-10-05										
321114 RIGHT FORWARD UPPER * MAIN LANDING GEAR TRUNNION SHEAR PIN (AWL*) Component ATA:32										
PN:4532103201-001	MOS		26-Oct-14					LIFE LIMIT		
SN:CMI1433	HRS		6496.17							
	AFL		5289	5000	TSN 0	10289	2713			
PROC. REF: AMM 57-10-05										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
321117 LEFT AFT UPPER * MAIN LANDING GEAR TRUNNION SHEAR PIN (AWL*) Component ATA:32										
PN:4532103202-001	MOS	11-Mar-22		TSN 0				LIFE LIMIT		
SN:CMI1350	HRS	8721.2		TSN 0						
	AFL	7006	1800	TSN 0	8806		1230			
PROC. REF: AMM 57-10-05										
321118 RIGHT AFT UPPER * MAIN LANDING GEAR TRUNNION SHEAR PIN (AWL*) Component ATA:32										
PN:4532103202-001	MOS	11-Mar-22		TSN 0				LIFE LIMIT		
SN:CMI1263	HRS	8721.2		TSN 0						
	AFL	7006	1800	TSN 0	8806		1230			
PROC. REF: AMM 57-10-05										
321119 LEFT AFT LOWER * MAIN LANDING GEAR TRUNNION SHEAR PIN (AWL*) Component ATA:32										
PN:4532103203-001	MOS	11-Mar-22		TSN 0				LIFE LIMIT		
SN:CMI1501	HRS	8721.2		TSN 0						
	AFL	7006	1800	TSN 0	8806		1230			
PROC. REF: AMM 57-10-05										
321120 RIGHT AFT LOWER * MAIN LANDING GEAR TRUNNION SHEAR PIN (AWL*) Component ATA:32										
PN:4532103203-001	MOS	11-Mar-22		TSN 0				LIFE LIMIT		
SN:CMI1509	HRS	8721.2		TSN 0						
	AFL	7006	1800	TSN 0	8806		1230			
PROC. REF: AMM 57-10-05										
321215 LEFT * MAIN LANDING GEAR SHOCK STRUT PISTON (IRN N3220035) (AWL*) Component ATA:32										
PN:200-0202-101	MOS	10-May-05		TSN 0				LIFE LIMIT		
SN:H0236	HRS	0		TSN 0						
	AFL	0	10000	TSN 0	10000		2424			
PROC. REF: AMM 32-10-01										
321216 RIGHT * MAIN LANDING GEAR SHOCK STRUT PISTON (IRN N3220035) (AWL*) Component ATA:32										
PN:200-0202-101	MOS	10-May-05		TSN 0				LIFE LIMIT		
SN:H0819	HRS	0		TSN 0						
	AFL	0	10000	TSN 0	10000		2424			
PROC. REF: AMM 32-10-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
321227 * LEFT MAIN LANDING GEAR SHOCK STRUT LINK (IRN N3220037) (AWL*) Component ATA:32										
PN:200-0204-101	MOS		10-May-05		TSN 0			LIFE LIMIT		
SN:H0705	HRS		0		TSN 0					
	AFL		0	10000	TSN 0	10000	2424			
PROC. REF: AMM 32-10-01										
321228 * RIGHT MAIN LANDING GEAR SHOCK STRUT LINK (IRN N3220037) (AWL*) Component ATA:32										
PN:200-0204-101	MOS		10-May-05		TSN 0			LIFE LIMIT		
SN:H0671	HRS		0		TSN 0					
	AFL		0	10000	TSN 0	10000	2424			
PROC. REF: AMM 32-10-01										
322001 * NOSE LANDING GEAR STRUT ASSEMBLY (IRN O3220009) (AWL*) Component ATA:32										
PN:4532240001-817	MOS		27-May-24					LIFE LIMIT		
SN:398	HRS		9381.4		TSN 9381.4					
	AFL		7483	20000	TSN 7483	20000	12424			
PROC. REF: AMM 32-20-01										
322002 NOSE LANDING GEAR CYLINDER Component ATA:32										
PN:2342102	MOS/MSC		10-May-05	O/C	TSN 0					
SN:T363	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: GENERIC NO REF										
322003 NOSE LANDING GEAR PISTON Component ATA:32										
PN:2342104	MOS/MSC		10-May-05	O/C	TSN 0					
SN:F042	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: GENERIC NO REF										
322004 NOSE LANDING GEAR ASSEMBLY BRACKET Component ATA:32										
PN:2342111	MOS/MSC		10-May-05	O/C	TSN 0					
SN:R224	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: GENERIC NO REF										
322005 NOSE LANDING GEAR FORK Component ATA:32										
PN:2342116	MOS/MSC		10-May-05	O/C	TSN 0					
SN:R378	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
322011	* NOSE LANDING GEAR ACTUATOR (P/N 6632201000) (IRN 03220010) (AWL*)									Component ATA:32
PN:6632201000-005	MOS	10-May-05		TSN 0				LIFE LIMIT		
SN:EFS378	HRS	0		TSN 0						
	AFL	0	20000	TSN 0	20000		12424			
PROC. REF: AMM 32-32-01										
3220147	LEFT FORWARD LOWER * MAIN LANDING GEAR TRUNNION SHEAR PINS - PERFORM VISUAL INPECTION FOR PIN MIGRATION (AWL*)									Service ATA:32
	MOS	11-Mar-22								
	HRS	8721.2								
	AFL	7006	600		7606		30			
PROC. REF: AMM 57-10-05										
322061	* NOSE LANDING GEAR TRUNNION AXLE (IRN 03220029) (AWL*)									Component ATA:32
PN:2342110-003	MOS	10-May-05		TSN 0				LIFE LIMIT		
SN:384	HRS	0		TSN 0						
	AFL	0	20000	TSN 0	20000		12424			
PROC. REF: AMM 32-20-01										
322071	LEFT * NOSE LANDING GEAR TRUNNION PIN (IRN 03220028) (AWL*)									Component ATA:32
PN:2342108-003	MOS	10-May-05		TSN 0				LIFE LIMIT		
SN:E020	HRS	0		TSN 0						
	AFL	0	20000	TSN 0	20000		12424			
PROC. REF: AMM 32-20-01										
322072	RIGHT * NOSE LANDING GEAR TRUNNION PIN (IRN 03220028) (AWL*)									Component ATA:32
PN:2342108-003	MOS	10-May-05		TSN 0				LIFE LIMIT		
SN:E005	HRS	0		TSN 0						
	AFL	0	20000	TSN 0	20000		12424			
PROC. REF: AMM 32-20-01										
322095	LEFT NOSE LANDING GEAR DOOR									Component ATA:32
PN:4552800001-007	MOS/MSC	10-May-05	O/C	TSN 0						
SN:0315	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 52-81-01										

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
322096	RIGHT NOSE LANDING GEAR DOOR									Component ATA:32
PN:4552800002-007	MOS/MSC	10-May-05	O/C	TSN 0						
SN:0311	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 52-81-01										
322121	NOSE LANDING GEAR UPLOCK MECHANISM									Component ATA:32
PN:2269H000-003	MOS/MSC	01-Dec-06	O/C							
SN:0064	HRS	1017.73								
	AFL	815								
PROC. REF: AMM 32-32-02										
323001	LEFT * MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY (AWL*)									Component ATA:32
PN:200-0300-003	MOS							LIFE LIMIT		
SN:H0361	HRS									
	AFL	0	17000	TSN 3247	16892 (M)		9316			
	ACH									
PROC. REF: AMM 32-31-01										
323002	RIGHT * MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY (AWL*)									Component ATA:32
PN:200-0300-006	MOS	16-Oct-24		TSN 64				LIFE LIMIT		
SN:H1714	HRS	9492.6		TSN 3148.6						
	AFL	7560	17000	TSN 2384	22176		14600			
PROC. REF: AMM 32-31-01										
323013	LEFT INBOARD MAIN LANDING GEAR DOOR ACTUATOR									Component ATA:32
PN:7469-1	MOS/MSC	13-Mar-14	O/C							
SN:0194	HRS	6040.72								
	AFL	4913								
PROC. REF: AMM 32-31-02										
323014	RIGHT INBOARD MAIN LANDING GEAR DOOR ACTUATOR									Component ATA:32
PN:7469-1	MOS/MSC	27-May-24	O/C	TSO 0						
SN:0673	HRS	9381.4		TSO 0						
	AFL	7483		TSO 0						
PROC. REF: AMM 32-31-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
323110 * NOSE LANDING GEAR ACTUATOR UPPER PIN (AWL*) Component ATA:32										
PN:4532302043-007	MOS	18-Jul-05		TSN 0				LIFE LIMIT		
SN:251	HRS	18.9		TSN 0						
	AFL	15	20000	TSN 0	20015		12439			
PROC. REF: AMM 32-32-01										
323206 LEFT UPLOCK ACTUATOR ASSEMBLY Component ATA:32										
PN:3000H000-005	MOS/MSC		O/C							
SN:0248	HRS									
	AFL	0								
PROC. REF: AMM 32-31-04										
323240 RIGHT UPLOCK ACTUATOR ASSEMBLY Component ATA:32										
PN:6632303004-006	MOS/MSC	10-May-05	O/C	TSN 0						
SN:1654	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-31-04										
323735 MAIN LANDING GEAR VALVE Component ATA:32										
PN:6632302001-003	MOS/MSC	10-May-05	O/C	TSN 0						
SN:1343	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
324001 LEFT INBOARD MAIN LANDING GEAR WHEEL Component ATA:32										
PN:3-1545-1	MOS/MSC	16-Oct-23	O/C							
SN:1334	HRS	9196.4								
	AFL	7334								
PROC. REF: AMM 32-40-02										
324002 LEFT OUTBOARD MAIN LANDING GEAR WHEEL Component ATA:32										
PN:3-1545-1	MOS/MSC	16-Oct-23	O/C							
SN:3516	HRS	9196.4								
	AFL	7334								
PROC. REF: AMM 32-40-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 32 - LANDING GEAR											
324003		RIGHT INBOARD MAIN LANDING GEAR WHEEL							Component	ATA:32	
PN:3-1545-1	MOS/MSC	27-May-24	O/C								
SN:0612	HRS	9381.4									
	AFL	7483									
PROC. REF: AMM 32-40-02											
324004		RIGHT OUTBOARD MAIN LANDING GEAR WHEEL							Component	ATA:32	
PN:3-1545-1	MOS/MSC	27-May-24	O/C								
SN:2694	HRS	9381.4									
	AFL	7483									
PROC. REF: AMM 32-40-02											
324005		NOSE GEAR ASSEMBLY WHEEL							Component	ATA:32	
PN:5010694	MOS/MSC	27-May-24	O/C								
SN:00-9103	HRS	9381.4									
	AFL	7483									
PROC. REF: AMM 32-40-01											
324021		LEFT INBOARD MAIN LANDING GEAR TIRE							Component	ATA:32	
PN:226K08-4	MOS/MSC	26-Jul-24	O/C	TSN 0							
SN:33450489	HRS	9450.9		TSN 0							
	AFL	7531		TSN 0							
PROC. REF: AMM 32-40-02											
324022		LEFT OUTBOARD MAIN LANDING GEAR TIRE							Component	ATA:32	
PN:226K08-4	MOS/MSC	26-Jul-24	O/C	TSN 0							
SN:31750546	HRS	9450.9		TSN 0							
	AFL	7531		TSN 0							
PROC. REF: AMM 32-40-02											
324023		RIGHT INBOARD MAIN LANDING GEAR TIRE							Component	ATA:32	
PN:226K08-4	MOS/MSC	27-May-24	O/C	TSN 0							
SN:33380478	HRS	9381.4		TSN 0							
	AFL	7483		TSN 0							
PROC. REF: AMM 32-40-02											
324024		RIGHT OUTBOARD MAIN LANDING GEAR TIRE							Component	ATA:32	
PN:226K08-4	MOS/MSC	27-May-24	O/C	TSN 0							
SN:33460488	HRS	9381.4		TSN 0							
	AFL	7483		TSN 0							
PROC. REF: AMM 32-40-02											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
324025 NOSE TIRE										Component ATA:32
PN:031-613-8	MOS/MSC	27-May-24	O/C	TSN 0						
SN:2293T00389	HRS	9381.4		TSN 0						
	AFL	7483		TSN 0						
PROC. REF: AMM 32-40-01										
324041 LEFT OUTBOARD MAIN LANDING GEAR BRAKE										Component ATA:32
PN:2-1579-2	MOS/MSC	22-Sep-16	O/C	TSO 0						
SN:0131	HRS	6857.7		TSO 0						
	AFL	553		TSO 0						
PROC. REF: AMM 32-41-01										
324042 LEFT INBOARD MAIN LANDING GEAR BRAKE										Component ATA:32
PN:2-1579-2	MOS/MSC	22-Sep-16	O/C	TSO 0						
SN:1999	HRS	6857.7		TSO 0						
	AFL	5573		TSO 0						
PROC. REF: AMM 32-41-01										
324043 RIGHT INBOARD MAIN LANDING GEAR BRAKE										Component ATA:32
PN:2-1579-2	MOS/MSC	22-Sep-16	O/C	TSO 0						
SN:1221	HRS	6857.7		TSO 0						
	AFL	5573		TSO 0						
PROC. REF: AMM 32-41-01										
324044 RIGHT OUTBOARD MAIN LANDING GEAR BRAKE										Component ATA:32
PN:2-1579-2	MOS/MSC	10-May-23	O/C	TSO 0						
SN:0825	HRS	9071.3		TSO 0						
	AFL	7252		TSO 0						
PROC. REF: AMM 32-41-01										
324061 LEFT ANTI-SKID CONTROL VALVE										Component ATA:32
PN:39-787	MOS/MSC	29-Jul-22	O/C							
SN:1257	HRS	8833.8								
	AFL	7089								
PROC. REF: AMM 32-41-07										
324062 RIGHT ANTI-SKID CONTROL VALVE										Component ATA:32
PN:39-787	MOS/MSC	25-Jan-22	O/C							
SN:802	HRS	8706.9								
	AFL	6996								
PROC. REF: AMM 32-41-07										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
324201 LEFT INBOARD BRAKE SHUTTLE VALVE										Component ATA:32
PN:7632401002-003	MOS/MSC	10-May-05	O/C	TSN 0						
SN:1288	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-42-04										
324202 LEFT OUTBOARD BRAKE SHUTTLE VALVE										Component ATA:32
PN:7632401002-003	MOS/MSC	10-May-05	O/C	TSN 0						
SN:1285	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-42-04										
324203 RIGHT INBOARD BRAKE SHUTTLE VALVE										Component ATA:32
PN:7632401002-003	MOS/MSC	10-May-05	O/C	TSN 0						
SN:1284	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-42-04										
324204 RIGHT OUTBOARD BRAKE SHUTTLE VALVE										Component ATA:32
PN:7632401002-003	MOS/MSC	10-May-05	O/C	TSN 0						
SN:1289	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-42-04										
324205^U BRAKE SHUTTLE MODULE										Component ATA:32
PN:6632401003-001	MOS/MSC	09-Jan-23	O/C	TSO 0						
SN:040	HRS	9039.2		TSO 0						
	AFL	7232		TSO 0						
PROC. REF: AMM 32-41-02										
324305 BRAKE CONTROL UNIT										Component ATA:32
PN:42-933-3	MOS/MSC	28-Aug-23	O/C							
SN:719A	HRS	9158.1								
	AFL	7309								
PROC. REF: AMM 32-41-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 32 - LANDING GEAR											
324805		BRAKE ACCUMULATOR								Component	ATA:32
PN:4532403040-005	MOS/MSC	10-May-05	O/C	TSN 0							
SN:353	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 32-42-02											
324868 ^U		EMERGENCY PARK BRAKE VALVE								Component	ATA:32
PN:6632401002-011	MOS/MSC	02-Aug-09	O/C								
SN:025	HRS	2839.98									
	AFL	2341									
325011		NOSE STEERING WHEEL ACTUATOR								Component	ATA:32
PN:JR5208C	MOS/MSC	10-May-05	O/C	TSN 0							
SN:A0343	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 32-50-02											
325021		NOSE STEERING WHEEL GEARBOX								Component	ATA:32
PN:2W3201D	MOS/MSC	10-May-05	O/C	TSN 0							
SN:C0336	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 32-50-03											
325031		NOSE STEERING WHEEL COMPUTER								Component	ATA:32
PN:498000-03-01	MOS/MSC	10-May-05	O/C	TSN 0							
SN:00336	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 32-50-01											
325041		RIGHT NWS RVDT								Component	ATA:32
PN:19710/3A1279A	MOS/MSC	10-May-05	O/C	TSN 0							
SN:0681	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
325042		LEFT NWS RVDT								Component	ATA:32
PN:19710/3A1279A	MOS/MSC	10-May-05	O/C	TSN 0							
SN:0643	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
5-19-00-AA3220111-LEFT	LEFT MAIN LANDING GEAR SIDE-STAY ACTUATOR - DISASSEMBLE ACTUATOR AND PERFORM DETAILED VISUAL INSPECTION. (IRN AA3220111)								Service	ATA:32
MOS	03-Sep-21	96 (+14d/-14d)	Adj -92d	03-Jun-29	17-Jun-29	1661 d (+14)				
HRS	8435.1									
AFL	6787	10000 (+25/-25)		16787	16812	9211 (+25)				
PROC. REF: GENERIC NO REF										
5-19-00-AA3220111-RIGHT	RIGHT MAIN LANDING GEAR SIDE-STAY ACTUATOR - DISASSEMBLE ACTUATOR AND PERFORM DETAILED VISUAL INSPECTION. (IRN AA3220111)								Service	ATA:32
MOS	03-Sep-21	96 (+14d/-14d)	Adj -92d	03-Jun-29	17-Jun-29	1661 d (+14)				
HRS	8435.1									
AFL	6787	10000 (+25/-25)		16787	16812	9211 (+25)				
PROC. REF: GENERIC NO REF										
5-19-00-L3220020-LEFT	* MAIN LANDING GEAR TRUNNION FITTINGS ON MID AND REAR SPAR - PERFORM EDDY CURRENT INSPECTION (IRN L3220020) (AWL*)								Service	ATA:32
MOS	10-May-05							AIRWORTHINESS		
HRS	0									
AFL	0	T:10000		10000		2424				
PROC. REF: NDT PART 6/32-11-00										
5-19-00-L3220020-RIGHT	* MAIN LANDING GEAR TRUNNION FITTINGS ON MID AND REAR SPAR - PERFORM EDDY CURRENT INSPECTION (IRN L3220020) (AWL*)								Service	ATA:32
MOS	10-May-05							AIRWORTHINESS		
HRS	0									
AFL	0	T:10000		10000		2424				
PROC. REF: NDT PART 6/32-11-00										
5-19-00-P3220146	MAIN LANDING GEAR * SHOCK STRUT CYLINDER (P/N 200-0201-109 AND 200-0201-110) PERFORM ULTRASONIC INSPECTION OF THE FORGING PARTING LINE								Service	ATA:32
MOS	10-May-23							AIRWORTHINESS		
HRS	9071.3									
AFL	7252	600		7852		276				
PROC. REF: NDT PART 4/32-10-01										
5-19-00-P3231020-LEFT	MAIN LANDING GEAR DOOR ACTUATOR GIMBAL ASSEMBLY - PERFORM EDDY CURRENT INSPECTION (IRN P3231020)								Service	ATA:32
MOS/MS	10-May-05	N/A								
HRS	0									
AFL	0									
PROC. REF: NDT PART 6/32-13-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
5-19-00-P3231020-RIGHT	MAIN LANDING GEAR DOOR ACTUATOR GIMBAL ASSEMBLY - PERFORM EDDY CURRENT INSPECTION (IRN P3231020)									Service ATA:32
	MOS/MSC	10-May-05	N/A							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 6/32-13-00										
5-19-00-P3231021-LEFT	MAIN LANDING GEAR DOOR ACTUATOR GIMBAL SHAFT - PERFORM FLUORESCENT PENETRANT INSPECTION - (IRN P3231021)									Service ATA:32
	MOS/MSC	10-May-05	N/A							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 8/32-13-02										
5-19-00-P3231021-RIGHT	MAIN LANDING GEAR DOOR ACTUATOR GIMBAL SHAFT - PERFORM FLUORESCENT PENETRANT INSPECTION - (IRN P3231021)									Service ATA:32
	MOS/MSC	10-May-05	N/A							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 8/32-13-02										
5-19-00-T3220007	* MAIN LANDING GEAR AXLES - PERFORM MAIN LANDING GEAR AXLE BEAM ASSEMBLY (P/N 200-203-001) BORESCOPE INSPECTION (IRN T3220007) (AWL*)									Service ATA:32
	MOS	11-Aug-21	48		11-Aug-25		269 d			
	HRS	8435.1								
	AFL	6787								
PROC. REF: NDT PART 8/32-10-03, AMM 32-10-01										
5-19-00-V3220022-LEFT	MAIN LANDING GEAR TRUNNION PINS - PERFORM MAGNETIC PARTICLE INSPECTION.									Service ATA:32
	MOS	03-Sep-21	96 (+14d/-14d)	Adj -92d	03-Jun-29	17-Jun-29	1661 d (+14)			
	HRS	8435.1								
	AFL	6787								
PROC. REF: NDT PART 7/32-10-07, NDT PART 7/32-10-08										
5-19-00-V3220022-RIGHT	MAIN LANDING GEAR TRUNNION PINS - PERFORM MAGNETIC PARTICLE INSPECTION.									Service ATA:32
	MOS	03-Sep-21	96 (+25d/-25d)	Adj -92d	03-Jun-29	28-Jun-29	1661 d (+25)			
	HRS	8435.1								
	AFL	6787								
PROC. REF: NDT PART 7/32-10-07, NDT PART 7/32-10-08										
5-19-00-W3231022-LEFT	LEFT MAIN LANDING GEAR INBOARD DOOR GIMBAL BRACKET (P/N 4532103150-001) - PERFORM EDDY CURRENT INSPECTION.									Service ATA:32
	MOS/MSC	10-May-05	N/A							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 6/32-13-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 32 - LANDING GEAR											
5-19-00-W3231022-RIGHT			RIGHT MAIN LANDING GEAR INBOARD DOOR GIMBAL BRACKET (P/N 4532103150-001) - PERFORM EDDY CURRENT INSPECTION.							Service	ATA:32
	MOS/MSC	10-May-05	N/A								
	HRS	0									
	AFL	0									
PROC. REF: NDT PART 6/32-13-01											
5-19-01-L3231024			* REPLACE MAIN LANDING GEAR INBOARD DOOR ACTUATOR CAP SCREWS (P/N 7469-1) (AWL*)							Service	ATA:32
	MOS	03-Sep-21	LIFE LIMIT								
	HRS	8435.1	2400	10835.1			1319.4				
	AFL	6787									
PROC. REF: AMM 32-31-02											
5-19-01-N3220012-L			REPLACE * MAIN LANDING GEAR STRUT ASSEMBLY (P/N 6632101000) (N3220012) (AWL*)							Service	ATA:32
	MOS	10-May-05	LIFE LIMIT								
	HRS	0									
	AFL	0	10000	10000			2424				
PROC. REF: AMM 32-10-01											
5-19-01-N3220012-R			REPLACE * MAIN LANDING GEAR STRUT ASSEMBLY (P/N 6632101000) (N3220012) (AWL*)							Service	ATA:32
	MOS	10-May-05	LIFE LIMIT								
	HRS	0									
	AFL	0	10000	10000			2424				
PROC. REF: AMM 32-10-01											
5-19-01-N3220023			REPLACE * MAIN LANDING GEAR TRUNNION PINS (P/N 200-0212, 200-0213) (N3220023) (AWL*)							Service	ATA:32
	MOS	10-May-05	LIFE LIMIT								
	HRS	0									
	AFL	0	10000	10000			2424				
PROC. REF: AMM 32-10-01											
5-19-01-N3220035-L			REPLACE * MAIN LANDING GEAR SHOCK STRUT PISTON (N3220035) (AWL*)							Service	ATA:32
	MOS	14-Dec-05	LIFE LIMIT								
	HRS	0									
	AFL	0	10000	10000			2424				
PROC. REF: NDT PART 7/32-10-03, AMM 32-10-01											
5-19-01-N3220035-R			REPLACE * MAIN LANDING GEAR SHOCK STRUT PISTON (N3220035) (AWL*)							Service	ATA:32
	MOS	14-Dec-05	LIFE LIMIT								
	HRS	0									
	AFL	0	10000	10000			2424				
PROC. REF: NDT PART 7/32-10-03, AMM 32-10-01											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
5-19-01-N3220036-L	* REPLACE LEFT MAIN LANDING GEAR AXLE BEAM (IRN N3220036) (AWL*)									Service ATA:32
	MOS	14-Dec-05						LIFE LIMIT		
	HRS	0								
	AFL	0	10000		10000		2424			
PROC. REF: AMM 32-10-01										
5-19-01-N3220036-R	* REPLACE RIGHT MAIN LANDING GEAR AXLE BEAM (IRN N3220036) (AWL*)									Service ATA:32
	MOS	14-Dec-05						LIFE LIMIT		
	HRS	0								
	AFL	0	10000		10000		2424			
PROC. REF: AMM 32-10-01										
5-19-01-N3220037-L	* REPLACE LEFT MAIN LANDING GEAR SHOCK STRUT LINK (IRN N3220037) (AWL*)									Service ATA:32
	MOS	14-Dec-05						LIFE LIMIT		
	HRS	0								
	AFL	0	10000		10000		2424			
PROC. REF: AMM 32-10-01										
5-19-01-N3220037-R	* REPLACE RIGHT MAIN LANDING GEAR SHOCK STRUT LINK (IRN N3220037) (AWL*)									Service ATA:32
	MOS	14-Dec-05						LIFE LIMIT		
	HRS	0								
	AFL	0	10000		10000		2424			
PROC. REF: AMM 32-10-01										
5-19-01-N3220041	REPLACE * MAIN LANDING GEAR FORWARD TRUNNION SHEAR PINS (P/N 4532103015, 4532103132) (IRN N3220041) (AWL*)									Service ATA:32
	MOS/MSC	10-May-05	N/A							
	HRS	0								
	AFL	0								
PROC. REF: AMM 57-10-05										
5-19-01-N3220042	REPLACE * MAIN LANDING GEAR AFT TRUNNION UPPER SHEAR PIN (P/N 4532103025, 4532103133) (IRN N3220042) (AWL*)									Service ATA:32
	MOS/MSC	26-Oct-14	N/A							
	HRS	6496.17								
	AFL	5289								
PROC. REF: AMM 57-10-05										
5-19-01-N3220043	REPLACE * MAIN LANDING GEAR AFT TRUNNION LOWER SHEAR PIN (P/N 4532103026, 4532103134) (IRN N3220043) (AWL*)									Service ATA:32
	MOS/MSC	26-Oct-14	N/A							
	HRS	6496.17								
	AFL	5289								
PROC. REF: AMM 57-10-05										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
5-19-01-N3220101	REPLACE * MAIN LANDING GEAR LINK PIN (P/N 200-0214) (IRN N3220101) (AWL*)									Service ATA:32
	MOS	14-Dec-05						LIFE LIMIT		
	HRS	0								
	AFL	0	10000		10000		2424			
	PROC. REF: AMM 32-10-01									
5-19-01-N3220102	* REPLACE MAIN LANDING GEAR PISTON PIN (IRN N3220102) (AWL*)									Service ATA:32
	MOS	14-Dec-05						LIFE LIMIT		
	HRS	0								
	AFL	0	10000		10000		2424			
	PROC. REF: NDT PART 7/32-10-04, AMM 32-10-01									
5-19-01-N3220116	REPLACE * MAIN LANDING GEAR SHOCK STRUT CYLINDER (P/N 200-0201-109, -110) (N3220116) (AWL*)									Service ATA:32
	MOS	14-Dec-05						LIFE LIMIT		
	HRS	0								
	AFL	0	10000		10000		2424			
	PROC. REF: GENERIC NO REF									
5-19-01-N3220126	REPLACE * MAIN LANDING GEAR SIDE-STAY ACTUATOR FITTING (N3220126) (AWL*)									Service ATA:32
	MOS	10-May-05						LIFE LIMIT		
	HRS	0								
	AFL	0	20000		20000		12424			
	PROC. REF: AMM 32-31-01									
5-19-01-N3220139	REPLACE * MAIN LANDING GEAR FORWARD TRUNNION SHEAR PIN (P/N 4532103201) (N3220139) (AWL*)									Service ATA:32
	MOS							LIFE LIMIT		
	HRS									
	AFL	0	5000		10289 (M)		2713			
	PROC. REF: AMM 57-10-05									
5-19-01-N3220140	REPLACE * MAIN LANDING GEAR AFT TRUNNION UPPER SHEAR PIN (P/N 4532103202) (N3220140) (AWL*)									Service ATA:32
	MOS/MSC	10-May-05	N/A							
	HRS	0								
	AFL	0								
	PROC. REF: AMM 57-10-05									
5-19-01-N3220141	REPLACE * MAIN LANDING GEAR AFT TRUNNION LOWER SHEAR PIN (P/N 4532103203) (N3220141) (AWL*)									Service ATA:32
	MOS/MSC	10-May-05	N/A							
	HRS	0								
	AFL	0								
	PROC. REF: AMM 57-10-05									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
A3230001 ^S	** LANDING GEAR - PERFORM EMERGENCY GEAR EXTENSIONFUNCTIONAL TEST (AWL**)									Service ATA:32
	MOS	25-Jan-24	24 (+14d/-14d)					AIRWORTHINESS		
	HRS	9265.8	600 (+25/-25)							
	AFL	7395								
						PROC. REF: AMM 32-33-00	PKG:11			
A3240005 ^S	** BRAKE HYDRAULIC FUSES - PERFORM FUNCTIONAL TEST (AWL**)									Service ATA:32
	MOS	11-Mar-22	48 (+14d/-14d)					AIRWORTHINESS		
	HRS	8721.2	1200 (+25/-25)							
	AFL	7006								
						PROC. REF: AMM 32-41-09	PKG:17			
A3240006 ^S	** BRAKE SHUTTLE MODULE - PERFORM FUNCTIONAL TEST (AWL**)									Service ATA:32
	MOS	11-Mar-22	48 (+14d/-14d)					AIRWORTHINESS		
	HRS	8721.2	1200 (+25/-25)							
	AFL	7006								
						PROC. REF: AMM 32-41-04	PKG:17			
A3240007 ^S	**BRAKE SHUTTLE VALVES - PERFORM FUNCTIONAL TEST (AWL**)									Service ATA:32
	MOS	10-May-23	96 (+14d/-14d)					AIRWORTHINESS		
	HRS	9071.3	2400 (+25/-25)							
	AFL	7252								
						PROC. REF: AMM 32-42-04	PKG:23			
A3240009 ^S	** BRAKE PRESSURE TRANSDUCERS - PERFORM FUNCTIONAL TEST (AWL**)									Service ATA:32
	MOS	10-May-23						AIRWORTHINESS		
	HRS	9071.3	4800 (+25/-25)							
	AFL	7252								
						PROC. REF: AMM 32-41-08	PKG:25			
AB3220016 ^S	NOSE LANDING GEAR STRUT ASSEMBLY - PERFORM SPECIAL DETAILED INSPECTION.									Service ATA:32
	MOS	10-May-05								
	HRS	0								
	AFL	0	10000 (+25/-25)							
						PROC. REF: GENERIC NO REF	PKG:27			
H3220017 ^S	NOSE LANDING GEAR TRUNNION AXLE - PERFORM VISUAL INSPECTION. IF CORROSION IS FOUND, REMOVE AXLE FROM CYLINDER AND PERFORM FLUORESCENT PENETRANT INSPECTION OF LUG AREA AND MAGNETIC PARTICLE INSPECTION OF AXLE. IF CORROSION IS NOT FOUND, CONDUCT FLUORESCENT PENETRANT INSPECTION OF AXLE PORTION THAT IS EXPOSED FROM CYLINDER									Service ATA:32
	MOS	10-May-05								
	HRS	0								
	AFL	0	10000 (+25/-25)							
						PROC. REF: GENERIC NO REF	PKG:27			

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
L3220019 ^S					NOSE LANDING GEAR ACTUATOR ATTACHMENT PIN - REMOVE PIN AND PERFORM MAGNETIC PARTICLE INSPECTION.				Service	ATA:32
	MOS	10-May-05								
	HRS	0								
	AFL	0	10000 (+25/-25)							
					PROC. REF: NDT PART 7/32-30-02					PKG:27
L3220109 ^S					NOSE LANDING GEAR ACTUATOR ASSEMBLY - DISASSEMBLE ACTUATOR AND PERFORM DETAILED VISUAL INSPECTION				Service	ATA:32
	MOS	10-May-05								
	HRS	0								
	AFL	0	10000 (+25/-25)							
					PROC. REF: GENERIC NO REF					PKG:27
V3240004 ^S					** EMERGENCY/PARKING BRAKE SWITCH - VERIFY THAT "EMERGENCY/PARKING BRAKE" MESSAGE ILLUMINATES ON EICAS WHEN PARKING BRAKE IS SET AND THROTTLES ARE MOVED ABOVE MCR DETENT (AWL**)				Service	ATA:32
	MOS	25-Jan-24	24 (+14d/-14d)					AIRWORTHINESS		
	HRS	9265.8	600 (+25/-25)							
	AFL	7395								
					PROC. REF: AMM 32-42-01					PKG:11
V3240008 ^S					** EMERGENCY/PARKING BRAKE CONTROL SYSTEM - PERFORM FUNCTIONAL TEST (AWL**)				Service	ATA:32
	MOS	25-Jan-24	24 (+14d/-14d)					AIRWORTHINESS		
	HRS	9265.8	600 (+25/-25)							
	AFL	7395								
					PROC. REF: AMM 32-42-02					PKG:11
Y3220000 ^S					NOSE LANDING GEAR ASSEMBLY - PERFORM VISUAL INSPECTION.				Service	ATA:32
	MOS	25-Jan-24	24 (+14d/-14d)							
	HRS	9265.8	600 (+25/-25)							
	AFL	7395								
					PROC. REF: GENERIC NO REF					PKG:11
Y3220001 ^S					MAIN LANDING GEAR ASSEMBLY - PERFORM VISUAL INSPECTION. INSPECTION TO INCLUDE ACTUATOR, FASTENERS, SUPPORT STRUCTURE, AND SQUAT SWITCHES.				Service	ATA:32
	MOS	25-Jan-24	24 (+14d/-14d)							
	HRS	9265.8	600 (+25/-25)							
	AFL	7395								
					PROC. REF: GENERIC NO REF					PKG:11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
Y3220002 ^S	NOSE LANDING GEAR ACTUATOR PRESSURE AND RETURN LINES - PERFORM VISUAL INSPECTION. LOWER ACTUATOR DUST BOOT TO INSPECT LINES.								Service	ATA:32
	MOS	25-Jan-24	24 (+14d/-14d)							
	HRS	9265.8	600 (+25/-25)							
	AFL	7395								
PROC. REF: GENERIC NO REF										PKG:11
Y3220003 ^S	NOSE GEAR SHOCK STRUT - REMOVE AND REPLACE RETAINERRING LOCKSCREW								Service	ATA:32
	MOS	25-Jan-24	24 (+14d/-14d)							
	HRS	9265.8	600 (+25/-25)							
	AFL	7395								
PROC. REF: GENERIC NO REF										PKG:11
Y3220004 ^S	MAIN LANDING GEAR ACTUATOR AND GEAR INBOARD DOOR ACTUATOR ATTACH POINTS - PERFORM VISUAL INSPECTION.								Service	ATA:32
	MOS	25-Jan-24	24 (+14d/-14d)							
	HRS	9265.8	600 (+25/-25)							
	AFL	7395								
PROC. REF: GENERIC NO REF										PKG:11
Y3220006 ^S	LANDING GEAR ELECTRICAL WIRING - PERFORM VISUAL INSPECTION (THAT PORTION VISIBLE INSIDE WHEEL/WELL).								Service	ATA:32
	MOS	25-Jan-24	24 (+14d/-14d)							
	HRS	9265.8	600 (+25/-25)							
	AFL	7395								
PROC. REF: GENERIC NO REF										PKG:11
Y3220008 ^S	NOSE LANDING GEAR AXLE - REMOVE NOSE LANDING GEAR WHEEL AND PERFORM INSPECTION. INSPECT BOTHINSIDE AND OUTSIDE OF AXLE								Service	ATA:32
	MOS	11-Mar-22	48 (+14d/-14d)							
	HRS	8721.2	1200 (+25/-25)							
	AFL	7006								
PROC. REF: AMM 32-40-01										PKG:17
Y3220124 ^S	NOSE LANDING GEAR - PERFORM DETAILED VISUAL INSPECTION OF THE NOSE LANDING GEAR UPLOCK ROLLER BRACKET								Service	ATA:32
	MOS	25-Jan-24	24 (+14d/-14d)							
	HRS	9265.8	600 (+25/-25)							
	AFL	7395								
PROC. REF: GENERIC NO REF										PKG:11
Y3230002 ^S	MAIN LANDING GEAR FREE FALL ROLLER - PERFORM VISUAL INSPECTION. PAY PARTICULAR ATTENTION TO BINDING OF ROLLERS.								Service	ATA:32
	MOS	25-Jan-24	12 (+14d/-14d)							
	HRS	9265.8	300 (+25/-25)							
	AFL	7395								
PROC. REF: GENERIC NO REF										PKG:5

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
Y3231023 ^S PERFORM MAIN LANDING GEAR INBOARD DOOR ACTUATOR (P/N 7469) END CAP SCREWS - DETAILED INSPECTION Service ATA:32										
	MOS	25-Jan-24	12 (+14d/-14d)							
	HRS	9265.8	300 (+25/-25)							
	AFL	7395								
PROC. REF: AMM 32-31-02										PKG:5
Y3240000 ^S NOSE AND MAIN TIRES - PERFORM VISUAL INSPECTION Service ATA:32										
	MOS	25-Jan-24	12 (+14d/-14d)							
	HRS	9265.8	300 (+25/-25)							
	AFL	7395								
PROC. REF: AMM 12-10-04										PKG:5
Y3240001 ^S BRAKE LINES - PERFORM VISUAL INSPECTION. INSPECT ALL BRAKE LINES VISIBLE IN WHEEL WELLS AND ON STRUTS. Service ATA:32										
	MOS	25-Jan-24	24 (+14d/-14d)							
	HRS	9265.8	600 (+25/-25)							
	AFL	7395								
PROC. REF: GENERIC NO REF										PKG:11
Y3240002 ^S BRAKE ASSEMBLIES - PERFORM VISUAL INSPECTION WITH PARKING BRAKE SET. WORN BRAKES ARE VISUALLY INDICATED WHEN THE WEAR INDICATOR PINS BECOME EVEN WITH THE OUTER SURFACE OF THE WEAR INDICATOR SLEEVE Service ATA:32										
	MOS	25-Jan-24	12 (+14d/-14d)							
	HRS	9265.8	300 (+25/-25)							
	AFL	7395								
PROC. REF: AMM 32-41-01										PKG:5
Y3240003 ^S BRAKE CONTROL SYSTEM LINEAR VARIABLE DIFFERENTIAL TRANSFORMER (LVDT) - PERFORM VISUAL INSPECTION. Service ATA:32										
	MOS	11-Mar-22	48 (+14d/-14d)							
	HRS	8721.2	1200 (+25/-25)							
	AFL	7006								
PROC. REF: GENERIC NO REF										PKG:13
Y3260005 ^S LUBRICATE NOSE LANDING GEAR SQUAT SWITCH ROTATING DISK ASSEMBLY Service ATA:32										
	MOS	25-Jan-24	12 (+14d/-14d)							
	HRS	9265.8	300 (+25/-25)							
	AFL	7395								
PROC. REF: AMM 12-21-01										PKG:5
ATA 33 - LIGHTS										
330000 MODIFIED PULSE CONTROLLER Component ATA:33										
PN:2401S	MOS/MSC	18-Jul-05	O/C	TSN 0						
SN:AR00716	HRS	18.9		TSN 0						
	AFL	15		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 33 - LIGHTS										
331001 NO. 1 LIGHTING CONTROL UNIT										Component ATA:33
PN:RDC4-1	MOS/MSC	10-May-05	O/C	TSN 0						
SN:0642	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-10-06										
331002 NO.2 LIGHTING CONTROL UNIT										Component ATA:33
PN:RDC4-1	MOS/MSC	10-May-05	O/C	TSN 0						
SN:0643	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-10-06										
331005 CENTER DIODE SWITCH RELAY BOX ASSEMBLY										Component ATA:33
PN:4533108520-005	MOS/MSC	10-May-05	O/C	TSN 0						
SN:A00319688-01	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-10-08										
331010 DIMMER CONTROL BOX										Component ATA:33
PN:LT-48(G)	MOS/MSC	10-May-05	O/C	TSN 0						
SN:1679	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-10-10										
331020 LIGHTING INVERTER SUPPLY										Component ATA:33
PN:6900135-001	MOS/MSC	10-May-05	O/C	TSN 0						
SN:467	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-10-04										
331029 CENTER PANEL OVERLAY ASSEMBLY SWITCH										Component ATA:33
PN:7676108500-007	MOS/MSC	01-Sep-13	O/C							
SN:854/L16683	HRS	5692.87								
	AFL	4644								
PROC. REF: GENERIC NO REF										
331030 COCKPIT LIGHTING CONTROL MODULE										Component ATA:33
PN:SP-45-54	MOS/MSC	16-Feb-09	O/C							
SN:110600688	HRS	2629.47								
	AFL	2166								
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 33 - LIGHTS										
332006	NO.4 LIGHT CONTROL UNIT SWITCH									Component ATA:33
PN:SP-45-33	MOS/MSC	10-May-05	O/C	TSN 0						
SN:060500543	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
332404	ENTRY WAY SWITCH PANEL									Component ATA:33
PN:SP-45-32	MOS/MSC	18-Jul-05	O/C	TSN 0						
SN:050500814	HRS	18.9		TSN 0						
	AFL	15		TSN 0						
PROC. REF: GENERIC NO REF										
334332	UPPER ANTI-COLLISION LIGHT									Component ATA:33
PN:GE16386-12-1	MOS/MSC	18-Jul-05	O/C	TSN 0						
SN:AF2952	HRS	18.9		TSN 0						
	AFL	15		TSN 0						
PROC. REF: AMM 33-40-01										
334333	LOWER ANTI-COLLISION LIGHT									Component ATA:33
PN:GE16386-12-1	MOS/MSC	18-Jul-05	O/C	TSN 0						
SN:AF2957	HRS	18.9		TSN 0						
	AFL	15		TSN 0						
PROC. REF: AMM 33-40-01										
335020	ELS ACTIVATION MODULE									Component ATA:33
PN:4533508501V5-001	MOS/MSC	18-Jul-05	O/C	TSN 0						
SN:A00440271-01	HRS	18.9		TSN 0						
	AFL	15		TSN 0						
PROC. REF: AMM 33-50-01										
336001	PILOT LIGHTED CHART HOLDER									Component ATA:33
PN:10-62-01	MOS/MSC	13-Nov-13	O/C							
SN:6751	HRS	5854.77								
	AFL	4776								
PROC. REF: GENERIC NO REF										
336002	COPILOT LIGHTED CHART HOLDER									Component ATA:33
PN:10-62-01	MOS/MSC	13-Nov-13	O/C							
SN:6714	HRS	5854.77								
	AFL	4776								
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 33 - LIGHTS											
Y3310000 ^S		PERFORM FLIGHT COMPARTMENT LIGHTING - OPERATION OF THE FOLLOWING: A. MAP LIGHTS. B. INSTRUMENT PANEL FLUORESCENT LIGHTS. C. INSTRUMENT/INDICATOR LIGHTS. D. LIGHT DIMMING SWITCHES. E. CREW WARNING PANEL. F. PANEL OVERLAYS.							Service	ATA:33	
	MOS	25-Jan-24	12 (+14d/-14d)								
	HRS	9265.8	300 (+25/-25)								
	AFL	7395									
PROC. REF: AMM 33-10-00										PKG:1	
Y3340000 ^S		EXTERIOR LIGHTING SYSTEMS - PERFORM OPERATION OF THE FOLLOWING: A. TAXI LIGHTS.B. ANTI-COLLISION BEACONS.C. NAVIGATION LIGHTS.D. STROBE LIGHTS.E. LANDING/RECOGNITION LIGHTS.F. WING ICE INSPECTION LIGHTS.G. EMERGENCY DOOR EGRESS LIGHTS.							Service	ATA:33	
	MOS	25-Jan-24	12 (+14d/-14d)								
	HRS	9265.8	300 (+25/-25)								
	AFL	7395									
PROC. REF: AMM 33-40-00, AMM 33-41-00										PKG:2	
Y3350003 ^S		EMERGENCY LIGHTING SYSTEM - PERFORM OPERATIONAL CHECK							Service	ATA:33	
	MOS	11-Mar-22	48 (+14d/-14d)								
	HRS	8721.2	1200 (+25/-25)								
	AFL	7006									
PROC. REF: AMM 33-50-00										PKG:14	
ATA 34 - NAVIGATION											
340001		RECERTIFY LEFT PITOT STATIC SYSTEM							Service	ATA:34	
	MOS	21-Mar-23	24		21-Mar-25		126 d				
	HRS										
	AFL										
PROC. REF: AMM 34-11-00, FAR SUBPART E											
340005		RECERTIFY RIGHT PITOT STATIC SYSTEM							Service	ATA:34	
	MOS	21-Mar-23	24		21-Mar-25		126 d				
	HRS										
	AFL										
PROC. REF: AMM 34-11-00, FAR SUBPART E											
341001		NO. 1 AIR DATA COMPUTER							Component	ATA:34	
	PN:7030700-71704	MOS/MS	28-Oct-13	O/C							
	SN:04010049	HRS	5825.12								
	AFL	4749									
PROC. REF: GENERIC NO REF											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 34 - NAVIGATION											
341001A		RECERTIFY NO. 1 AIR DATA COMPUTER								Service	ATA:34
PN:7030700-71704	MOS	21-Mar-23	24		21-Mar-25		126 d				
SN:04010049	HRS										
	AFL										
PROC. REF: GENERIC NO REF, FAR SUBPART E											
341002		NO. 2 AIR DATA COMPUTER								Component	ATA:34
PN:7030700-71704	MOS/MSC	04-Dec-19	O/C								
SN:05010297	HRS	7762.1									
	AFL	6271									
PROC. REF: GENERIC NO REF											
341002A		RECERTIFY NO. 2 AIR DATA COMPUTER								Service	ATA:34
PN:7030700-71704	MOS	21-Mar-23	24		21-Mar-25		126 d				
SN:05010297	HRS										
	AFL										
PROC. REF: GENERIC NO REF, FAR SUBPART E											
341013		STANDBY AIRSPEED INDICATOR								Component	ATA:34
PN:6634208002-003	MOS/MSC	08-Dec-21	O/C	TSO 5							
SN:271917	HRS	8647.8		TSO 0							
	AFL	6960		TSO 0							
PROC. REF: AMM 34-18-01											
341025		STANDBY ALTIMETER								Component	ATA:34
PN:3A43.42.51F.05.1.GM	MOS/MSC	27-Mar-15	O/C								
SN:1049907	HRS	6705.27									
	AFL	5447									
PROC. REF: AMM 34-15-01											
341025A		RECERTIFY STANDBY ALTIMETER								Service	ATA:34
PN:3A43.42.51F.05.1.GM	MOS	21-Mar-23	24		21-Mar-25		126 d				
SN:1049907	HRS										
	AFL										
PROC. REF: GENERIC NO REF, FAR SUBPART E											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
341037 LEFT PRIMARY PITOT/STATIC PROBE (P/N 0856TJ1 OR 6634100000-001) Component ATA:34										
PN:6634100000-001	MOS	03-Jan-24						LIFE LIMIT		
SN:297570	HRS	9258	15000 (+25/-25)	TSN 4839.9	19418.1	19443.1	9902.4 (+25)			
	AFL	7391		TSN 3532						
PROC. REF: AMM 34-11-01										
341038 RIGHT PRIMARY PITOT/STATIC PROBE (P/N 0856TJ2 OR 6634100000-003) Component ATA:34										
PN:6634100000-003	MOS	10-May-05		TSN 0				LIFE LIMIT		
SN:228303	HRS	0	15000 (+25/-25)	TSN 0	15000	15025	5484.3 (+25)			
	AFL	0		TSN 0						
PROC. REF: AMM 34-11-01										
341049 STANDBY PITOT/STATIC PROBE Component ATA:34										
PN:6634100000-005	MOS/MSC	15-Jul-19	O/C							
SN:255416	HRS	7629.8								
	AFL	6170								
PROC. REF: AMM 34-11-01										
341061 RADAR ALTIMETER RECEIVER Component ATA:34										
PN:7001840-936	MOS/MSC	10-May-05	O/C	TSN 0						
SN:05018748	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
341073 FWD RADAR ALTIMETER ANTENNA Component ATA:34										
PN:S67-2002-4	MOS/MSC	10-May-05	O/C	TSN 0						
SN:11976	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
341074 AFT RADAR ALTIMETER ANTENNA Component ATA:34										
PN:S67-2002-4	MOS/MSC	10-May-05	O/C	TSN 0						
SN:552-12301	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
341085	TAT SENSOR PROBE									Component ATA:34
PN:102AU1AG	MOS/MSC	10-May-05	O/C	TSN 0						
SN:A56616	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-17-02										
342001	NO. 1 ATTITUDE HEADING REFERENCE COMPUTER									Component ATA:34
PN:142185-1102	MOS/MSC	05-Jul-23	O/C							
SN:1298	HRS	9121.8								
	AFL	7284								
PROC. REF: GENERIC NO REF										
342002	NO. 2 ATTITUDE HEADING REFERENCE COMPUTER									Component ATA:34
PN:142185-1102	MOS/MSC	07-Jul-23	O/C							
SN:1219	HRS	9121.8								
	AFL	7284								
PROC. REF: GENERIC NO REF										
342003	LEFT AHRS FAN									Component ATA:34
PN:26012423-105	MOS/MSC	22-Feb-14	O/C							
SN:NSN	HRS	6022.57								
	AFL	4903								
PROC. REF: GENERIC NO REF										
342004	RIGHT AHRS FAN									Component ATA:34
PN:140691-0000	MOS/MSC	10-May-05	O/C	TSN 0						
SN:2732	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
342037	LEFT FLUX VALVE									Component ATA:34
PN:7010133	MOS/MSC	22-Feb-14	O/C							
SN:85074657	HRS	6022.57								
	AFL	4903								
PROC. REF: AMM 34-26-02										
342038	RIGHT FLUX VALVE									Component ATA:34
PN:7010133	MOS/MSC	10-May-05	O/C	TSN 0						
SN:01025838	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-26-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 34 - NAVIGATION											
342049		NO. 1 DISPLAY, DU870 UNIT								Component	ATA:34
PN:7014300-901	MOS/MSC	16-Feb-18	O/C								
SN:0201A982	HRS	7180.4									
	AFL	5824									
PROC. REF: GENERIC NO REF											
342050		NO. 2 DISPLAY, DU870 UNIT								Component	ATA:34
PN:7014300-901	MOS/MSC	05-Nov-19	O/C	TSO 0							
SN:98113978	HRS	7762.1		TSO 0							
	AFL	6271		TSO 0							
PROC. REF: GENERIC NO REF											
342051		NO. 3 DISPLAY, DU870 UNIT								Component	ATA:34
PN:7014300-901	MOS/MSC	18-Jul-05	O/C	TSN 0							
SN:0505E648	HRS	18.9		TSN 0							
	AFL	15		TSN 0							
PROC. REF: GENERIC NO REF											
342052		NO. 4 DISPLAY, DU870 UNIT								Component	ATA:34
PN:7014300-901	MOS/MSC	29-Aug-14	O/C								
SN:0608F718	HRS	6419.93									
	AFL	5227									
PROC. REF: GENERIC NO REF											
342075		STANDBY ATTITUDE INDICATOR								Component	ATA:34
PN:501-1648-02	MOS/MSC	16-May-22	O/C								
SN:1573	HRS	8777.4									
	AFL	7052									
PROC. REF: AMM 34-23-01											
342087		STANDBY COMPASS								Component	ATA:34
PN:PAI-700-5V	MOS/MSC	10-May-05	O/C	TSN 0							
SN:54257	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 34-21-01											
344011		WEATHER RADAR ANTENNA								Component	ATA:34
PN:7021450-601	MOS/MSC	15-Jul-11	O/C								
SN:08038292	HRS	4321.27									
	AFL	3541									
PROC. REF: AMM 34-42-01											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
344012	WEATHER RADAR CONTROLLER									Component ATA:34
PN:7008471-667	MOS/MSC	10-May-05	O/C	TSN 0						
SN:04128107	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-42-02										
344111	UPPER TCAS ANTENNA									Component ATA:34
PN:7514081-913	MOS/MSC	13-Nov-08	O/C							
SN:ANE21122	HRS	2476.37								
	AFL	2046								
PROC. REF: AMM 34-43-02										
344112	LOWER TCAS ANTENNA									Component ATA:34
PN:7514081-913	MOS/MSC	09-Jul-11	O/C							
SN:ANE34705	HRS	4311.47								
	AFL	3530								
PROC. REF: AMM 34-43-02										
344143	TCAS PROCESSOR									Component ATA:34
PN:7517900-55012	MOS/MSC	27-Mar-15	O/C							
SN:20008090	HRS	6705.27								
	AFL	5447								
PROC. REF: AMM 34-43-01										
345001	NO. 1 INTEGRATED NAVIGATION UNIT									Component ATA:34
PN:7510100-633	MOS/MSC	24-Sep-21	O/C							
SN:01035165	HRS	8457.7								
	AFL	6804								
PROC. REF: GENERIC NO REF										
345002	NO. 2 INTEGRATED NAVIGATION UNIT									Component ATA:34
PN:7510100-633	MOS/MSC	04-Nov-21	O/C	TSR 21						
SN:02086727	HRS	8563.6		TSR 0						
	AFL	6885		TSR 0						
PROC. REF: GENERIC NO REF										
345013	NO. 1 ADF ANTENNA									Component ATA:34
PN:7510300-901	MOS/MSC	22-Jul-11	O/C							
SN:1101H620	HRS	4335.18								
	AFL	3554								
PROC. REF: AMM 34-57-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
345014 NO. 2 ADF ANTENNA										Component ATA:34
PN:7510300-901	MOS/MSC	10-May-05	O/C	TSN 0						
SN:04118782	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-57-01										
345025 ENHANCED GROUND PROXIMITY WARNING COMPUTER										Component ATA:34
PN:965-0976-040-208-208	MOS/MSC	10-May-05	O/C	TSN 0						
SN:20041	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-45-01										
345037 UPPER ATC ANTENNA										Component ATA:34
PN:DMN150-2-2	MOS/MSC	18-Jul-05	O/C	TSN 0						
SN:102434	HRS	18.9		TSN 0						
	AFL	15		TSN 0						
PROC. REF: AMM 34-56-01										
345038 LOWER ATC ANTENNA										Component ATA:34
PN:DMN150-2-2	MOS/MSC	10-May-05	O/C	TSN 0						
SN:88828	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-56-01										
345049 NO. 1 DME ANTENNA										Component ATA:34
PN:DMN150-2-2	MOS/MSC	10-May-05	O/C	TSN 0						
SN:88829	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-55-01										
345050 NO. 2 DME ANTENNA										Component ATA:34
PN:DMN150-9-2	MOS/MSC	10-May-05	O/C	TSN 0						
SN:7063	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-55-01										
345061 MARKER BEACON ANTENNA										Component ATA:34
PN:DMN27-3	MOS/MSC	10-May-05	O/C	TSN 0						
SN:14914	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-30-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
345083 LEFT VOR/LOCALIZER ANTENNA										Component ATA:34
PN:DMN4-17-1/N	MOS/MSC	10-May-05	O/C	TSN 0						
SN:20783	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
345084 RIGHT VOR/LOCALIZER ANTENNA										Component ATA:34
PN:DMN4-17-1/N	MOS/MSC	10-May-05	O/C	TSN 0						
SN:20784	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
345085 PHASING, VHF/NAV COUPLER										Component ATA:34
PN:DMN4-17-2	MOS/MSC	10-May-05	O/C	TSN 0						
SN:19012	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-51-03										
345605 NO.1 ATC ANTENNA										Component ATA:34
PN:DMN150-2-2	MOS/MSC	10-May-05	O/C	TSN 0						
SN:89515	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-56-01										
345606 NO.2 ATC ANTENNA										Component ATA:34
PN:DMN150-2-2	MOS/MSC	10-May-05	O/C	TSN 0						
SN:88839	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-56-01										
346001 PILOT CONTROL DISPLAY, FLIGHT MANAGEMENT CDU										Component ATA:34
PN:2017-41-201	MOS/MSC	27-Jul-23	O/C							
SN:1506	HRS	9146.9								
	AFL	7300								
PROC. REF: AMM 34-60-01										
346021 FMS DATA TRANSFER UNIT										Component ATA:34
PN:1406-01-1	MOS/MSC	10-May-05	O/C	TSN 0						
SN:3285	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-60-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
346025	NO.1 FMS CONFIG MODULE									Component ATA:34
PN:10171	MOS/MSC	10-May-05	O/C	TSN 0						
SN:4112	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
347510	NO. 1 GPS ANTENNA									Component ATA:34
PN:10706	MOS/MSC	10-May-05	O/C	TSN 0						
SN:9447	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-53-01										
347511	NO. 2 GPS ANTENNA									Component ATA:34
PN:10706	MOS/MSC	18-Jul-05	O/C	TSN 0						
SN:9934	HRS	18.9		TSN 0						
	AFL	15		TSN 0						
PROC. REF: AMM 34-53-01										
5-19-02-RVSM-L3411062	PERFORM PITOT/STATIC PROBE - DETAILED VISUAL INSPECTION. (IRN L3411062)									Service ATA:34
	MOS	21-Mar-23	24 (+14d/-14d)		21-Mar-25		04-Apr-25	126 d (+14)		
	HRS									
	AFL									
PROC. REF: AMM 34-11-01										
5-19-02-RVSM-M3411052	VERIFY PITCH, ROLL, AND YAW ALIGNMENT ON PRIMARY PITOT-STATIC PROBES (IRN M3411052)									Service ATA:34
	MOS	21-Mar-23	24 (+14d/-14d)		21-Mar-25		04-Apr-25	126 d (+14)		
	HRS									
	AFL									
PROC. REF: AMM 34-11-01										
5-19-02-RVSM-U3411060	FUNCTIONAL TEST AIR DATA SYSTEM									Service ATA:34
	MOS	21-Mar-23	24 (+14d/-14d)		21-Mar-25		04-Apr-25	126 d (+14)		
	HRS									
	AFL									
PROC. REF: AMM 34-17-00										
A3400000 ^S	** NAVIGATION SYSTEMS - PERFORM OPERATIONAL CHECK (AWL)**									Service ATA:34
	MOS	25-Jan-24	24 (+14d/-14d)					AIRWORTHINESS		
	HRS	9265.8	600 (+25/-25)							
	AFL	7395								
PROC. REF: AMM 34-00-00										
										PKG:7

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 34 - NAVIGATION											
Y3411000 ^S		PITOT-STATIC PROBE - PERFORM VISUAL INSPECTION. ENSURE DRAIN HOLES ARE CLEAR OF OBSTRUCTIONS							Service	ATA:34	
	MOS	25-Jan-24	24 (+14d/-14d)								
	HRS	9265.8	600 (+25/-25)								
	AFL	7395									
						PROC. REF: AMM 34-11-01					
Y3440000 ^S		RADOME STRUCTURE AND ANTENNA INSTALLATION - PERFORM VISUAL INSPECTION.							Service	ATA:34	
	MOS	11-Mar-22	48 (+14d/-14d)								
	HRS	8721.2	1200 (+25/-25)								
	AFL	7006									
						PROC. REF: GENERIC NO REF					
ATA 35 - OXYGEN											
350001		OXYGEN REGULATOR & CYLINDER (IRN O3510007)							Component	ATA:35	
PN:806385-13	MOS	08-May-20	180 (+14d/-14d)	TSN 0	08-May-35	22-May-35	3826 d (+14)	LIFE LIMIT			
SN:ALT372-8282	HRS	7922.3		TSN 0							
	AFL	6385		TSN 0							
						PROC. REF: AMM 35-00-01					
350001A		** PERFORM ICC HYDROSTATIC TEST ON CYLINDER (PER DOT EXEMPTION E8162) AND FUNCTIONALLY TEST OXYGEN CYLINDER LOW PRESSURE RELIEF VALVE. (IRN Q3510005 OR Q3510018) (AWL)**							Service	ATA:35	
PN:806385-13	MOS	08-May-20	60 (+14d/-14d)		08-May-25	22-May-25	174 d (+14)				
SN:ALT372-8282	HRS	7922.3	5000 (+25/-25)		12922.3	12947.3	3406.6 (+25)				
	AFL	6385									
						PROC. REF: GENERIC NO REF					
350001B		** OXYGEN CYLINDER AND REMOTE OXYGEN FILL VALVES - PERFORM PERIODIC CHECK. (IRN N3510013) (AWL)**							Service	ATA:35	
	MOS	27-May-24									
	HRS	9381.4	1500 (+25/-25)		10881.4	10906.4	1365.7 (+25)				
	AFL	7483									
						PROC. REF: AMM 35-00-01					
350230		OXYGEN INDICATOR							Component	ATA:35	
PN:P24090	MOS/MSC	18-Jul-05	O/C	TSN 0							
SN:017	HRS	18.9		TSN 0							
	AFL	15		TSN 0							
						PROC. REF: AMM 35-00-05					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 35 - OXYGEN										
351001	PILOT OXYGEN MASK									Component ATA:35
PN:MC10-15-166	MOS/MSC	05-Aug-24	O/C							
SN:77506	HRS	9460.2								
	AFL	7535								
PROC. REF: AMM 35-10-01										
351001A	OVERHAUL PILOT OXYGEN MASK (IRN 5-19-00-O3510006)									Service ATA:35
PN:MC10-15-166	MOS	14-Mar-19	72 (+14d/-14d)		14-Mar-25	28-Mar-25	119 d (+14)			
SN:77506	HRS									
	AFL									
OverHaul Date:: 14-Mar-19 PROC. REF: GENERIC NO REF										
351002	COPILOT OXYGEN MASK									Component ATA:35
PN:MC10-15-166	MOS/MSC	18-Oct-24	O/C	TSO 0						
SN:77842	HRS	9492.6		TSO 0						
	AFL	7560		TSO 0						
PROC. REF: AMM 35-10-01										
351002A	OVERHAUL COPILOT OXYGEN MASK (IRN 5-19-00-O3510006)									Service ATA:35
PN:MC10-15-166	MOS	18-Oct-24	72 (+14d/-14d)		18-Oct-30	01-Nov-30	2163 d (+14)			
SN:77842	HRS	9492.6								
	AFL	7560								
OverHaul Date:: 18-Oct-24 PROC. REF: GENERIC NO REF										
352002	ALTITUDE COMPENSATING REGULATOR									Component ATA:35
PN:PN	MOS/MSC	10-May-05	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 35-20-06										
352015	OXYGEN CONTROL VALVE									Component ATA:35
PN:P21081	MOS/MSC	10-May-05	O/C	TSN 0						
SN:0358	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 35-20-01										
5-19-00-N3510019	** PERFORM PERIODIC CHECK OF THE OXYGEN CYLINDER AND REMOTE FILL VALVES (IRN N3510019) (AWL**)									Service ATA:35
	MOS	23-Mar-21								
	HRS	8242.3	1500 (+25/-25)		9742.3	9767.3	226.6 (+25)			
	AFL	6636								
PROC. REF: AMM 35-00-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 35 - OXYGEN										
5-19-00-Q3510018	PERFORM ** ICC HYDROSTATIC TEST ON CYLINDER (PER DOT EXEMPTION E8162) AND FUNCTIONALLY TEST OXYGEN CYLINDER LOW PRESSURE RELIEF VALVE. (EFFECTIVE ON AIRCRAFT EQUIPPED WITH INCREASED CAPACITY OXYGEN SYSTEM.) (AWL **)								Service	ATA:35
	MOS	08-May-20	60 (+14d/-14d)		08-May-25	22-May-25	174 d (+14)			
	HRS	7922.3	5000 (+25/-25)		12922.3	12947.3	3406.6 (+25)			
	AFL	6385								
PROC. REF: GENERIC NO REF										
5-19-00-Q3510023	OXYGEN CYLINDER REGULATOR - PERFORM OVERHAUL.								Service	ATA:35
	MOS	08-May-20	60 (+14d/-14d)		08-May-25	22-May-25	174 d (+14)			
	HRS	7922.3	5000 (+25/-25)		12922.3	12947.3	3406.6 (+25)			
	AFL	6385								
PROC. REF: GENERIC NO REF										
O3510003 ^S	** CABIN LOW PRESSURE OXYGEN DISTRIBUTION FLEX HOSES - PERFORM FUNCTIONAL TEST. (AWL**)								Service	ATA:35
	MOS	25-Jan-24	24 (+14d/-14d)					AIRWORTHINESS		
	HRS	9265.8	600 (+25/-25)							
	AFL	7395								
PROC. REF: AMM 35-20-00										PKG:7
S3510014 ^S	** OXYGEN SYSTEM ALTITUDE COMPENSATING REGULATOR - PERFORM FUNCTIONAL TEST. (AWL**)								Service	ATA:35
	MOS	25-Jan-24	24 (+14d/-14d)					AIRWORTHINESS		
	HRS	9265.8	600 (+25/-25)							
	AFL	7395								
PROC. REF: AMM 35-20-00										PKG:7
Y3510000 ^S	OXYGEN CYLINDER INSTALLATION - PERFORM VISUAL INSPECTION. CHECK PLUMBING FOR ROUTING, SECURITY, AND CONDITION.								Service	ATA:35
	MOS	11-Mar-22	48 (+14d/-14d)							
	HRS	8721.2	1200 (+25/-25)							
	AFL	7006								
PROC. REF: AMM 35-00-01										PKG:13
Y3510017 ^S	OXYGEN CYLINDER INSTALLATION - PERFORM VISUAL INSPECTION. CHECK PLUMBING FOR ROUTING, SECURITY, AND CONDITION.								Service	ATA:35
	MOS	25-Jan-24	24 (+14d/-14d)							
	HRS	9265.8	600 (+25/-25)							
	AFL	7395								
PROC. REF: AMM 35-00-01										PKG:7
ATA 36 - PNEUMATIC										
361031	ECS CONTROLLER								Component	ATA:36
PN:6636108500-003	MOS/MSC	13-Sep-22	O/C							
SN:366MF	HRS	8895.7								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 36 - PNEUMATIC										
	AFL	7135								
PROC. REF: AMM 36-10-01										
361041	NO. 1 HIGH PRESSURE SWITCH									Component ATA:36
PN:642019-3	MOS/MSC	10-May-05	O/C	TSN 0						
SN:0765	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 36-10-06										
361042	NO. 2 HIGH PRESSURE SWITCH									Component ATA:36
PN:642019-3	MOS/MSC	10-May-05	O/C	TSN 0						
SN:0750	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 36-10-06										
361053	NO. 1 ECS SHUT-OFF (L37) VALVE									Component ATA:36
PN:6621000000-061	MOS/MSC	10-May-05	O/C	TSN 0						
SN:729	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 36-10-03										
361054	NO. 2 ECS SHUT-OFF (L38) VALVE									Component ATA:36
PN:6621000000-061	MOS/MSC	10-May-05	O/C	TSN 0						
SN:731	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 36-10-03										
361065	LEFT TAILCONE HIGH PRESSURE SHUT-OFF VALVE									Component ATA:36
PN:6621000000-092	MOS/MSC	30-Aug-13	O/C							
SN:771	HRS	5687.42								
	AFL	4640								
PROC. REF: AMM 36-10-02										
361066	RIGHT TAILCONE HIGH PRESSURE SHUT-OFF VALVE									Component ATA:36
PN:3291216-2	MOS/MSC	26-May-22	O/C							
SN:1274C	HRS	8787.3								
	AFL	7061								
PROC. REF: AMM 36-10-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 36 - PNEUMATIC										
361160	LEFT OZONE CONVERTER									Component ATA:36
PN:53A405-4	MOS/MSC	15-Mar-18	O/C	TSO 0						
SN:0497-1008	HRS	7205.4		TSO 0						
	AFL	5847		TSO 0						
PROC. REF: AMM 21-20-12										
361160A	TEST LEFT OZONE CONVERTER EFFICIENCY (Y2140001)									Service ATA:36
PN:53A405-4	MOS	15-Mar-18								
SN:0497-1008	HRS	7205.4	3600 (+25/-25)		10805.4	10830.4	1289.7 (+25)			
	AFL	5847								
PROC. REF: GENERIC NO REF										
361161	RIGHT OZONE CONVERTER									Component ATA:36
PN:53A405-4	MOS/MSC	15-Mar-18	O/C	TSO 0						
SN:0504-1015	HRS	7205.4		TSO 0						
	AFL	5847		TSO 0						
PROC. REF: AMM 21-20-12										
361161A	TEST RIGHT OZONE CONVERTER EFFICIENCY (Y2140001)									Service ATA:36
PN:53A405-4	MOS	15-Mar-18								
SN:0504-1015	HRS	7205.4	3600 (+25/-25)		10805.4	10830.4	1289.7 (+25)			
	AFL	5847								
PROC. REF: GENERIC NO REF										
361215	LEFT HIGH PRESSURE BLEED AIR MANIFOLD ASSEMBLY									Component ATA:36
PN:LJ01212-001	MOS/MSC	10-May-05	O/C	TSN 0						
SN:281204-002	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 36-10-07										
361216	RIGHT HIGH PRESSURE BLEED AIR MANIFOLD ASSEMBLY									Component ATA:36
PN:LJ01317-002	MOS/MSC	03-Sep-21	O/C							
SN:180102-006	HRS	8435.1		TSN 4839.9						
	AFL	6787		TSN 3532						
PROC. REF: AMM 36-10-07										
361337	LEFT SERVO AIR CHECK VALVE									Component ATA:36
PN:6608295-3	MOS/MSC	11-Jun-08	O/C							
SN:2677	HRS	2192.67								
	AFL	1781								
PROC. REF: AMM 36-15-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 36 - PNEUMATIC										
361337A	REPLACE LEFT SERVO AIR CHECK VALVE (K3610012)									Service ATA:36
PN:6608295-3	MOS/MS	11-Jun-08	O/C							
SN:2677	HRS	2192.67								
	AFL	1781								
PROC. REF: AMM 36-15-02										
361357	RIGHT SERVO AIR CHECK VALVE									Component ATA:36
PN:6608295-3	MOS/MS	11-Jun-08	O/C							
SN:2194	HRS	2192.67								
	AFL	1781								
PROC. REF: AMM 36-15-02										
361357A	REPLACE RIGHT SERVO AIR CHECK VALVE (K3610012)									Service ATA:36
PN:6608295-3	MOS/MS	11-Jun-08	O/C							
SN:2194	HRS	2192.67								
	AFL	1781								
PROC. REF: AMM 36-15-02										
5-19-00-P3610048	PERFORM VISUAL INSPECTION HIGH PRESSURE BLEED AIR MANIFOLD ASSEMBLY									Service ATA:36
	MOS	07-Feb-14								
	HRS	5991.87	3500 (+100/-100)	9491.87	9591.87	TOL (+76.2)				
	AFL	4884								
PROC. REF: GENERIC NO REF										
A3610000 ^S	** BLEED AIR SYSTEM - PERFORM FUNCTIONAL TEST (AWL**)									Service ATA:36
	MOS	25-Jan-24	24 (+14d/-14d)	AIRWORTHINESS						
	HRS	9265.8	600 (+25/-25)							
	AFL	7395								
PROC. REF: AMM 36-10-00										
A3610001 ^S	** PYLON OVERHEAT THERMOSTAT AND ELECTRICAL SYSTEM - PERFORM FUNCTIONAL TEST (AWL**)									Service ATA:36
	MOS	25-Jan-24	24 (+14d/-14d)	AIRWORTHINESS						
	HRS	9265.8	600 (+25/-25)							
	AFL	7395								
PROC. REF: AMM 36-20-01										
U3610075 ^S	BORESCOPE INSPECTION ECS BLEED AIR "Y" MANIFOLD (P/N 12945-054-019, 12945-054-025, 12945-054-031, 129-054-037, 12945-054V1-001, 12945-054V2-001, 12945-054V6-001, 4536102027-001)									Service ATA:36
	MOS	10-May-23								
	HRS	9071.3	4800 (+25/-25)							
	AFL	7252								
PROC. REF: AMM 36-10-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 36 - PNEUMATIC										
W3510002^S ** OXYGEN SYSTEM - PERFORM OPERATIONAL CHECK (AWL**) Service ATA:36										
	MOS	25-Jan-24	24 (+14d/-14d)					AIRWORTHINESS		
	HRS	9265.8	600 (+25/-25)							
	AFL	7395								
PROC. REF: AMM 35-00-00										PKG:7
Y3510001^S CREW SEAT OXYGEN HOSES - PERFORM VISUAL INSPECTION. PAY PARTICULAR ATTENTION TO AREA WHERE OXYGEN HOSES ENTER CREW SEATS ABOVE COCKPIT FLOOR Service ATA:36										
	MOS	25-Jan-24	12 (+14d/-14d)							
	HRS	9265.8	300 (+25/-25)							
	AFL	7395								
PROC. REF: GENERIC NO REF										PKG:1
Y3610061^S HIGH PRESSURE BLEED AIR SHUT-OFF VALVE IN-LINE FILTER - PERFORM CLEANING PROCEDURES Service ATA:36										
	MOS	25-Jan-24	24 (+14d/-14d)							
	HRS	9265.8	600 (+25/-25)							
	AFL	7395								
PROC. REF: AMM 36-10-02										PKG:8
ATA 38 - WATER/WASTE										
382016 LAVATORY HOT WATER TANK Component ATA:38										
PN:AR9061-1	MOS/MSC	02-Aug-05	O/C							
SN:0028	HRS	31.7		TSR 0						
	AFL	22		TSR 0						
PROC. REF: GENERIC NO REF										
383001 TOILET ASSEMBLY Component ATA:38										
PN:663830300-005	MOS/MSC	05-Jul-18	O/C							
SN:U2395	HRS	7338.4								
	AFL	5941								
PROC. REF: AMM 38-30-01										
383014 TOILET TIMER Component ATA:38										
PN:7638303002-009	MOS/MSC	18-Jul-05	O/C	TSN 0						
SN:T3891	HRS	18.9		TSN 0						
	AFL	15		TSN 0						
PROC. REF: AMM 38-30-02										
ATA 52 - DOORS										
5-19-02-RVSM-M5240004 INSPECT AVIONIC ACCESS DOOR GAP AND MISMATCH (IRN M5240004) Service ATA:52										
	MOS	21-Mar-23	24 (+14d/-14d)		21-Mar-25	04-Apr-25	126 d (+14)			
	HRS									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 52 - DOORS										
AFL										
PROC. REF: AMM 52-40-01										
521001	UPPER CABIN ASSEMBLY DOOR									Component ATA:52
PN:4552101000-003	MOS/MSC	10-May-05	O/C	TSN 0						
SN:W295	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
521002	LOWER CABIN ASSEMBLY DOOR									Component ATA:52
PN:4552100300-001	MOS/MSC	10-May-05	O/C	TSN 0						
SN:W281	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
5210053	CABIN DOOR HANDLE - REPLACE									Service ATA:52
	MOS	03-Sep-21	144 (+14d/-14d)	Adj -126d	30-Apr-33	14-May-33	3088 d (+14)			
	HRS	8435.1								
	AFL	6787	6000 (+25/-25)		12787	12812	5211 (+25)			
PROC. REF: GENERIC NO REF										
521301	LEFT INBOARD MAIN GEAR DOOR									Component ATA:52
PN:4552803004-003	MOS/MSC	10-May-05	O/C	TSN 0						
SN:665478900295	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 52-80-01										
521302	RIGHT INBOARD MAIN GEAR DOOR									Component ATA:52
PN:4552803004-004	MOS/MSC	10-May-05	O/C	TSN 0						
SN:665480800295	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 52-80-01										
521303	LEFT OUTBOARD MAIN GEAR DOOR									Component ATA:52
PN:4552803003-003	MOS/MSC	10-May-05	O/C	TSN 0						
SN:223824400295	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 52-80-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 52 - DOORS										
521304										Component ATA:52
PN:4552803003-004	MOS/MSC	27-Mar-15	O/C							
SN:939663300517	HRS	6705.27								
	AFL	5447								
PROC. REF: AMM 52-80-01										
522001										Component ATA:52
PN:4552200076V36-001	MOS/MSC	10-May-05	O/C	TSN 0						
SN:L2027	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 52-20-01										
523001										Component ATA:52
PN:12045-557V1-001X01	MOS/MSC	10-May-05	O/C	TSN 0						
SN:0315	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
524001										Component ATA:52
PN:4552405151-009	MOS/MSC	10-May-05	O/C	TSN 0						
SN:0315	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 52-40-02										
A5210009 ^S										Service ATA:52
* EMERGENCY EXIT DOOR RETAINERS - PERFORM VISUAL INSPECTION. INSPECT DOOR STOP FITTINGS ON EMERGENCY EXIT DOOR FRAMES IN FLANGE RADII. (FS 374 AND 394) (AWL*)										
	MOS	10-May-05						AIRWORTHINESS		
	HRS	0	9600							
	AFL	0								
PROC. REF: GENERIC NO REF										
A5210012 ^S										Service ATA:52
* LOWER PASSENGER DOOR HINGE - PERFORM VISUAL INSPECTION. INSPECT PIANO HINGE LUGS AND FASTENERS (AWL*)										
	MOS	10-May-05						AIRWORTHINESS		
	HRS	0	9600							
	AFL	0								
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 52 - DOORS										
A5210014 ^S					* UPPER PASSENGER DOOR TENSION FITTINGS - VISUAL INSPECTION. INSPECT THE FOLLOWING:A. TENSION STUDS AT RETAINING FLANGES.B. RADII AROUND FLANGE PERIPHERY (AWL*)				Service	ATA:52
	MOS	10-May-05						AIRWORTHINESS		
	HRS	0	9600							
	AFL	0								
					PROC. REF: GENERIC NO REF					PKG:26
AA5210055 ^S					CABIN DOOR HANDLE RAMP ROLLER WHEEL - LUBRICATION				Service	ATA:52
	MOS	11-Mar-22	48							
	HRS	8721.2	1200							
	AFL	7006								
					PROC. REF: AMM 12-21-02					PKG:18
D5210015 ^S					* EMERGENCY EXIT DOOR - PERFORM VISUAL INSPECTION. PAY PARTICULAR ATTENTION TO FLANGES AND FASTENER HOLES OF DOOR STOP FITTINGS (AWL*)				Service	ATA:52
	MOS	10-May-23						AIRWORTHINESS		
	HRS	9071.3	4800							
	AFL	7252								
					PROC. REF: GENERIC NO REF					PKG:25
E5210013 ^S					* UPPER AND LOWER PASSENGER DOOR LATCH ARMS AND DOOR ATTACHMENTS - PERFORM VISUAL INSPECTION (AWL*)				Service	ATA:52
	MOS	10-May-23						AIRWORTHINESS		
	HRS	9071.3	4800							
	AFL	7252								
					PROC. REF: GENERIC NO REF					PKG:25
F5210016 ^S					* UPPER PASSENGER DOOR HINGE - PERFORM VISUAL INSPECTION. INSPECT UPPER SURFACE OF HINGE FINGERSAT BASE OF LUG (AWL*)				Service	ATA:52
	MOS	10-May-05						AIRWORTHINESS		
	HRS	0	9600							
	AFL	0								
					PROC. REF: GENERIC NO REF					PKG:26
N5210010 ^S					* LOWER PASSENGER DOOR TENSION BOLTS, BOLT RETAINERS, TENSION FITTINGS, AND DOOR ATTACHMENTS - PERFORM VISUAL INSPECTION (AWL*)				Service	ATA:52
	MOS	10-May-23	96					AIRWORTHINESS		
	HRS	9071.3	2400							
	AFL	7252								
					PROC. REF: GENERIC NO REF					PKG:24

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 52 - DOORS											
N5210011 ^S			* UPPER AND LOWER PASSENGER DOOR LATCH PINS - PERFORM VISUAL INSPECTION. INSPECT BOLTS AND DOOR END RIB STRUCTURE AT LOCK PINS. (AWL*)						Service	ATA:52	
	MOS	10-May-23	96					AIRWORTHINESS			
	HRS	9071.3	2400								
	AFL	7252									
PROC. REF: GENERIC NO REF										PKG:24	
N5210017 ^S			* UPPER PASSENGER DOOR TENSION BOLTS, BOLT RETAINERS, TENSION FITTINGS, AND DOOR ATTACHMENTS - PERFORM VISUAL INSPECTION. (AWL*)						Service	ATA:52	
	MOS	10-May-23	96					AIRWORTHINESS			
	HRS	9071.3	2400								
	AFL	7252									
PROC. REF: GENERIC NO REF										PKG:24	
T5210003 ^S			EXTERNAL LOWER PASSENGER/CREW DOOR CABLES - PERFORM VISUAL INSPECTION OF VISIBLE PORTION OF CABLES AND HANDLE AREA.						Service	ATA:52	
	MOS	11-Mar-22	48 (+14d/-14d)								
	HRS	8721.2	1200 (+25/-25)								
	AFL	7006									
PROC. REF: GENERIC NO REF										PKG:18	
Y5210000 ^S			AVIONICS COMPARTMENT ACCESS DOORS AND SEALS - PERFORM VISUAL INSPECTION.						Service	ATA:52	
	MOS	11-Mar-22	48 (+14d/-14d)								
	HRS	8721.2	1200 (+25/-25)								
	AFL	7006									
PROC. REF: GENERIC NO REF										PKG:13	
Y5210001 ^S			TAILCONE ACCESS DOOR AND SEAL - PERFORM VISUAL INSPECTION OF DOOR, SEALS, AND LATCHES.						Service	ATA:52	
	MOS	25-Jan-24	24 (+14d/-14d)								
	HRS	9265.8	600 (+25/-25)								
	AFL	7395									
PROC. REF: GENERIC NO REF										PKG:12	
Y5210002 ^S			BAGGAGE COMPARTMENT DOOR - PERFORM VISUAL INSPECTION OF DOORS, SEALS, AND LATCHES.						Service	ATA:52	
	MOS	25-Jan-24	24 (+14d/-14d)								
	HRS	9265.8	600 (+25/-25)								
	AFL	7395									
PROC. REF: GENERIC NO REF										PKG:12	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 52 - DOORS											
Y5210004 ^S			UPPER AND LOWER PASSENGER/CREW DOOR - PERFORM VISUAL INSPECTION OF DOOR STRUCTURE, TENSION FITTINGS, AND HINGE AREA FOR CRACKS AND CORROSION.						Service	ATA:52	
	MOS	11-Mar-22	48 (+14d/-14d)								
	HRS	8721.2	1200 (+25/-25)								
	AFL	7006									
					PROC. REF: GENERIC NO REF					PKG:18	
Y5210005 ^S			INTERNAL LOWER PASSENGER/CREW DOOR CABLES - PERFORM VISUAL INSPECTION. REMOVE STEP SKIN TO GAIN ACCESS TO CABLES.						Service	ATA:52	
	MOS	11-Mar-22	48 (+14d/-14d)								
	HRS	8721.2	1200 (+25/-25)								
	AFL	7006									
					PROC. REF: GENERIC NO REF					PKG:18	
Y5210006 ^S			UPPER PASSENGER/CREW DOOR VENT DOOR SPRINGS - PERFORM VISUAL INSPECTION.						Service	ATA:52	
	MOS	25-Jan-24	24 (+14d/-14d)								
	HRS	9265.8	600 (+25/-25)								
	AFL	7395									
					PROC. REF: GENERIC NO REF					PKG:12	
Y5210008 ^S			PERFORM EMERGENCY EXIT DOOR INTERNAL AND EXTERNAL HANDLE LATCHING MECHANISM - PERFORM OPERATIONAL CHECK						Service	ATA:52	
	MOS	25-Jan-24	24 (+14d/-14d)								
	HRS	9265.8	600 (+25/-25)								
	AFL	7395									
					PROC. REF: AMM 52-20-07					PKG:12	
Y5240000 ^S			OXYGEN SYSTEM SERVICING DOOR AND LATCHES - PERFORM VISUAL INSPECTION FOR CONDITION AND SECURITY. CHECK DECAL FOR CONDITION AND LEGIBILITY.						Service	ATA:52	
	MOS	11-Mar-22	48 (+14d/-14d)								
	HRS	8721.2	1200 (+25/-25)								
	AFL	7006									
					PROC. REF: GENERIC NO REF					PKG:13	
Y5240003 ^S			SINGLE POINT REFUELING ACCESS DOOR - PERFORM VISUAL INSPECTION.						Service	ATA:52	
	MOS	11-Mar-22	48 (+14d/-14d)								
	HRS	8721.2	1200 (+25/-25)								
	AFL	7006									
					PROC. REF: GENERIC NO REF					PKG:14	
ATA 53 - FUSELAGE											
5-19-00-H5323032			* EXTERIOR CABIN WINDOW COAMING (UNPAINTED) - PERFORM EDDY CURRENT INSPECTION (H5323032) (AWL*)						Service	ATA:53	
	MOS	20-Nov-23	24		20-Nov-25		370 d	AIRWORTHINESS			
	HRS	9228.3	2400		11628.3		2112.6				
	AFL	7360									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty		
ATA 53 - FUSELAGE												
PROC. REF: NDT PART 6/56-20-01												
5-19-00-H5323092			*EXTERIOR CABIN WINDOW COAMING (PAINTED) - PERFORM EDDY CURRENT INSPECTION (IRN H5323092) (AWL*)								Service	ATA:53
	MOS/MSC	10-May-05	N/A									
	HRS	0										
	AFL	0										
PROC. REF: NDT PART 6/56-20-01												
5-19-00-T5323166			* EXTERNAL SKIN CUT-OUTS/PENETRATIONS (PRESSURE CABIN) - PERFORM DETAILED VISUAL INSPECTION. INSPECT SKIN AND DOUBLERS AT ANTENNAS, ELECTRICAL COMPONENTS, AND ACCESS PANELS. (EXCLUDING PITOT/ STATIC PROBES, AOA STALL VANES, AND WING INSPECTION LIGHT) (AWL*)								Service	ATA:53
	MOS	01-May-17	144		01-May-29		1628 d	MANDATORY				
	HRS	6994.7	9600		16594.7		7079					
	AFL	5681										
PROC. REF: GENERIC NO REF												
5-19-00-V5323168			* LOWER COUPE RAIL RADIUS/WINDSCREEN RETAINER ATTACH - PERFORM EDDY CURRENT INSPECTION (P/N 4553130001-802 THRU 4553130001-809) (AWL*)								Service	ATA:53
	MOS	10-Sep-12						AIRWORTHINESS				
	HRS	5091.27	5000		10091.27		575.6					
	AFL	4149										
PROC. REF: NDT PART 6/53-30-23, NDT PART 6/53-30-24												
5-19-01-U5323167-LEFT			* LEFT COUPE RAIL (4553002003V7000-001). REPLACE (AWL*)								Component	ATA:53
PN:PN	MOS/MSC	10-May-05	N/A	TSN 0				NOT APPLICABLE				
SN:UNKNOWN	HRS	0		TSN 0								
	AFL	0		TSN 0								
PROC. REF: GENERIC NO REF												
5-19-01-U5323167-RIGHT			*RIGHT COUPE RAIL (4553002003V7001-002). REPLACE (AWL*)								Component	ATA:53
PN:PN	MOS/MSC	10-May-05	N/A	TSN 0				NOT APPLICABLE				
SN:UNKNOWN	HRS	0		TSN 0								
	AFL	0		TSN 0								
PROC. REF: GENERIC NO REF												
5-19-02-RVSM-M5313001			PERFORM PITOT-STATIC PROBE ZONE SKIN CONTOUR CHECK (IRN M5313001)								Service	ATA:53
	MOS	21-Mar-23	24 (+14d/-14d)		21-Mar-25	04-Apr-25	126 d (+14)					
	HRS											
	AFL											
PROC. REF: AMM 53-00-01												

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
530001	ASSEMBLY FUSELAGE									Component ATA:53
PN:455300010-001	MOS/MSC	10-May-05	O/C	TSN 0						
SN:L2027	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
535001	RADOME									Component ATA:53
PN:6634408000-005	MOS/MSC	30-Jul-13	O/C							
SN:0254	HRS	5607.75								
	AFL	4568								
PROC. REF: AMM 53-50-01										
535601	LEFT DELTA FIN									Component ATA:53
PN:4555501000-015	MOS/MSC	10-May-05	O/C	TSN 0						
SN:S7549/A0070	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 53-56-01										
535602	RIGHT DELTA FIN									Component ATA:53
PN:4555501000-016	MOS/MSC	10-May-05	O/C	TSN 0						
SN:S7549/A0070	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 53-56-01										
A5310005 ^S	* FUSELAGE FUEL CELL CANTED BULKHEAD (FS 495) - PERFORM VISUAL INSPECTION, PAYING PARTICULAR ATTENTION TO MAIN CROSSMEMBER. INSPECT FLANGES AND ATTACHMENTS FOR CRACKING (AWL*)									Service ATA:53
	MOS	10-May-23						AIRWORTHINESS		
	HRS	9071.3	4800							
	AFL	7252								
PROC. REF: GENERIC NO REF										PKG:25
A5310007 ^S	* AFT PRESSURE BULKHEAD BOTTOM SHEAR DIAPHRAGM - PERFORM DETAILED VISUAL INSPECTION. INSPECT BULKHEAD POST ATTACHMENT FASTENER HOLES AND CONTROL CABLE SLOT (AWL*)									Service ATA:53
	MOS	10-May-05						AIRWORTHINESS		
	HRS	0	9600							
	AFL	0								
PROC. REF: GENERIC NO REF										PKG:26

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 53 - FUSELAGE											
A5323023 ^S			* DRAG LINK ATTACHMENT LUG - PERFORM VISUAL INSPECTION (AWL*)							Service	ATA:53
	MOS	10-May-23						AIRWORTHINESS			
	HRS	9071.3	4800								
	AFL	7252									
PROC. REF: GENERIC NO REF										PKG:25	
A5360001 ^S			WITH DELTA FINS REMOVED, VISUALLY INSPECT THE FOLLOWING:A. DELTA FIN AFT SPAR.B. DELTA FIN SUPPORT ANGLE.C. INSPECT STIFFENERS CONNECTING TO ATTACH FITTINGS							Service	ATA:53
	MOS	10-May-05									
	HRS	0	9600 (+25/-25)								
	AFL	0									
PROC. REF: GENERIC NO REF										PKG:26	
E5310001 ^S			* LONGERON, INTERNAL (BETWEEN FS 384 AND FS 433) - PERFORM VISUAL INSPECTION (AWL*)							Service	ATA:53
	MOS	10-May-05						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
PROC. REF: GENERIC NO REF										PKG:26	
E5310017 ^S			* AFT PRESSURE BULKHEAD BOTTOM CROSSBREED (FS 457) - PERFORM DETAILED VISUAL INSPECTION. INSPECT TEE-SECTION AT FS 457 FLANGE AT ATTACHMENT TO PRESSURE FLOOR (AWL*)							Service	ATA:53
	MOS	10-May-05						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
PROC. REF: GENERIC NO REF										PKG:26	
E5310018 ^S			* AFT PRESSURE BULKHEAD PANEL FACING SHEETS (FS 457) - PERFORM VISUAL INSPECTION. INSPECT BOTH FRONT AND AFT OF FACING SHEETS (AWL*)							Service	ATA:53
	MOS	10-May-05						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
PROC. REF: GENERIC NO REF										PKG:26	
E5323050 ^S			* AFT POST/WINDSHIELD RETAINER ATTACHMENT - WITH HEADLINER REMOVED, PERFORM EDDY CURRENT INSPECTION (AWL*)							Service	ATA:53
	MOS	10-May-23						AIRWORTHINESS			
	HRS	9071.3	4800								
	AFL	7252									
PROC. REF: NDT PART 6/53-30-04										PKG:25	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
E5323068 ^S					* STRINGER 1 RH BETWEEN FS 533 AND FS 543 - PERFORM VISUAL INSPECTION. INSPECT STRINGER 1 FLANGE AND SKIN ALONG STRINGER 1 BETWEEN FS 533 AND FS 543 (AWL*)				Service	ATA:53
	MOS	10-May-05						AIRWORTHINESS		
	HRS	0	9600							
	AFL	0								
					PROC. REF: GENERIC NO REF					PKG:26
E5323073 ^S					* FUSELAGE BOTTOM SKIN PANEL - PERFORM VISUAL INSPECTION. INSPECT CORNER RADIUS AT JUNCTION OF EXTERNAL LONGERON AND MID SPAR FRAME (FS 435) (AWL*)				Service	ATA:53
	MOS	10-May-05						AIRWORTHINESS		
	HRS	0	9600							
	AFL	0								
					PROC. REF: GENERIC NO REF					PKG:26
E5323074 ^S					* AUXILIARY SKIN PANEL - PERFORM VISUAL INSPECTION. INSPECT CORNER RADIUS AT JUNCTION OF KEEL BEAM AND REAR SPAR FRAME (FS 466) (AWL*)				Service	ATA:53
	MOS	10-May-05						AIRWORTHINESS		
	HRS	0	9600							
	AFL	0								
					PROC. REF: GENERIC NO REF					PKG:26
E5350000 ^S					* BOTTOM KEELBEAM END PADS (FS 384 - FS 486) - PERFORM VISUAL INSPECTION. INSPECT END PADS AROUND BOLT HOLES AND IN RADII AT FS 433. (AWL*)				Service	ATA:53
	MOS	10-May-05						AIRWORTHINESS		
	HRS	0	9600							
	AFL	0								
					PROC. REF: GENERIC NO REF					PKG:26
F5323081 ^S					* TIE-ROD FORK ENDS (TITANIUM, P/N R24889) - PERFORM FLUORESCENT PENETRANT INSPECTION (AWL*)				Service	ATA:53
	MOS	10-May-05						AIRWORTHINESS		
	HRS	0	9600							
	AFL	0								
					PROC. REF: NDT PART 8/53-10-01					PKG:26
F5331021 ^S					* FORWARD CANTED BULKHEAD (FS 630) - PERFORM VISUAL INSPECTION. INSPECT AT FRONT SPAR ATTACHMENT FASTENERS (AWL*)				Service	ATA:53
	MOS	10-May-23						AIRWORTHINESS		
	HRS	9071.3	4800							
	AFL	7252								
					PROC. REF: GENERIC NO REF					PKG:25

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 53 - FUSELAGE											
F5331022 ^S			* MID CANTED BULKHEAD (FS 657) - PERFORM VISUAL INSPECTION AT MID SPAR UPPER ATTACHMENT FASTENERS (AWL*)						Service	ATA:53	
	MOS	10-May-05						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
PROC. REF: GENERIC NO REF										PKG:26	
F5331023 ^S			* AFT CANTED BULKHEAD (FS 682) - PERFORM VISUAL INSPECTION. INSPECT AT REAR SPAR ATTACHMENT FASTENERS (AWL*)						Service	ATA:53	
	MOS	10-May-05						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
PROC. REF: GENERIC NO REF										PKG:26	
F5331024 ^S			* VERTICAL STABILIZER FRONT ROOT BULKHEAD ATTACHMENT (FS 630) - PERFORM VISUAL INSPECTION. INSPECT FRONT SPAR ROOT BULKHEAD ATTACHMENT AT FASTENER HOLES (AWL*)						Service	ATA:53	
	MOS	10-May-05						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
PROC. REF: GENERIC NO REF										PKG:26	
F5331025 ^S			* VERTICAL STABILIZER MID SPAR ROOT BULKHEAD ATTACHMENT (FS 657) - PERFORM VISUAL INSPECTION. INSPECT MID SPAR ROOT BULKHEAD ATTACHMENT AT FASTENER HOLES (AWL*)						Service	ATA:53	
	MOS	10-May-05						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
PROC. REF: GENERIC NO REF										PKG:26	
F5331026 ^S			* VERTICAL STABILIZER REAR SPAR ROOT BULKHEAD ATTACHMENT (FS 682) - PERFORM VISUAL INSPECTION.INSPECT REAR SPAR ROOT BULKHEAD ATTACHMENT ATFASTENER HOLES (AWL*)						Service	ATA:53	
	MOS	10-May-05						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
PROC. REF: GENERIC NO REF										PKG:26	
J5310019 ^S			* FLIGHT DECK LONGERON (FS 174 - FS 220.51) - PERFORM VISUAL INSPECTION. INSPECT FLIGHT DECK LONGERON STIFFENERS, WEBS, AND CUTOUTS (AWL*)						Service	ATA:53	
	MOS	10-May-05						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
PROC. REF: GENERIC NO REF										PKG:26	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 53 - FUSELAGE											
J5323093 ^S			* NOSE LANDING GEAR AFT WHEELBOX CLOSING STRUCTURE (FS 174 TO FS 186) - PERFORM VISUAL INSPECTION. INSPECT THE FOLLOWING:A. PANEL.B. CHANNEL STIFFENERS.C. SUPPORT ANGLE.D. ANGLE STIFFENER.E. ZEE STIFFENER. (AWL*)							Service	ATA:53
	MOS	10-May-05						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
PROC. REF: GENERIC NO REF										PKG:26	
J5323094 ^S			* FORWARD/AFT WHEELBOX JOINT (FS 174) - PERFORM VISUAL INSPECTION. INSPECT SPLICE STRAP AFT OF FORWARD PRESSURE BULKHEAD AT INTERSECTION OF ATTACHMENT ANGLE AND FLIGHT DECK LONGERON (AWL*)							Service	ATA:53
	MOS	10-May-05						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
PROC. REF: GENERIC NO REF										PKG:26	
J5323095 ^S			* UPPER AND LOWER PASSENGER/CREW DOOR SKIN CUTOUT CORNERS (F.S. 249 - F.S. 281) - PERFORM EDDY CURRENT INSPECTION. INSPECT SKIN AT CORNERS OF PASSENGER/CREW DOOR CUTOUT (AWL*)							Service	ATA:53
	MOS	10-May-23	96					AIRWORTHINESS			
	HRS	9071.3	2400								
	AFL	7252									
PROC. REF: NDT PART 6/53-30-02										PKG:19	
J5323101 ^S			* FRAME ATTACHMENTS TO UPPER AND LOWER COUPE RAILS (FS 195 TO FS 228) - PERFORM VISUAL INSPECTION. INSPECT THE FOLLOWING:A. FRAME ATTACHMENTS TO LOWER COUPE RAILS AT FS 195, FS 206, FS 221, AND FS 229.B. FRAME ATTACHMENTS TO UPPER COUPE RAILS AT FS 221 AND FS 229.C. GUSSETS AT FASTENER HOLES. (AWL*)							Service	ATA:53
	MOS	10-May-05						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
PROC. REF: NDT PART 6/53-30-03										PKG:26	
J5323102 ^S			* TIE-ROD ASSEMBLY (FS 186) (TITANIUM ENDS) - PERFORM VISUAL INSPECTION. INSPECT TIE-ROD ENDS, TIE-ROD TUBES, AND TIE-ROD BOLTS. (AWL*)							Service	ATA:53
	MOS	10-May-05						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
PROC. REF: GENERIC NO REF										PKG:26	
L5311002 ^S			* NOSE LANDING GEAR ACTUATOR ATTACHMENT ON FORWARD PRESSURE BULKHEAD - PERFORM EDDY CURRENT INSPECTION. INSPECT ACTUATOR ATTACHMENT BRACKET LUGS, RADII, AND FASTENER HOLES (AWL*)							Service	ATA:53
	MOS	10-May-05						AIRWORTHINESS			
	HRS	0									
	AFL	0	10000								
PROC. REF: NDT PART 6/32-12-00										PKG:27	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
L5311004 ^S					* NOSE LANDING GEAR TRUNNION FITTINGS - PERFORM VISUAL INSPECTION OF THE TRUNNION FITTINGS AND ATTACHMENT BOLTS (AWL*)				Service	ATA:53
	MOS		10-May-05					AIRWORTHINESS		
	HRS		0							
	AFL		0	10000						
PROC. REF: GENERIC NO REF										PKG:27
L5311005 ^S					PERFORM * NOSE LANDING GEAR TRUNNION FITTINGS AND SUPPORT STRUCTURE - PERFORM EDDY CURRENT INSPECTION OF THE TRUNNION SUPPORT STRUCTURE AT THE FORWARD PRESSURE BULKHEAD FLANGE (AWL*)				Service	ATA:53
	MOS		10-May-05					AIRWORTHINESS		
	HRS		0							
	AFL		0	10000						
PROC. REF: NDT PART 6/32-12-05										PKG:27
M5323021 ^S					* EXTERNAL LONGERON, FASTENER LOCATIONS, AND AREA AROUND WING ATTACHMENTS - PERFORM VISUAL INSPECTION. INSPECT LONGERON BETWEEN FS 398 AND FS 486, STRINGER 13 LHS & RHS (AWL*)				Service	ATA:53
	MOS		10-May-05					AIRWORTHINESS		
	HRS		0	9600						
	AFL		0							
PROC. REF: GENERIC NO REF										PKG:26
M5323034 ^S					* UPPER AND LOWER COUPE RAIL AND CENTER POST/WINDSHIELD RETAINER ATTACHMENT - PERFORM EDDY CURRENT INSPECTION. (AWL*)				Service	ATA:53
	MOS		10-May-05					AIRWORTHINESS		
	HRS		0	9600						
	AFL		0							
PROC. REF: NDT PART 6/53-30-03										PKG:26
N5314000 ^S					* EMERGENCY EXIT DOOR SKIN CUTOUT CORNERS AND DOUBLERS (FS 370 TO FS 398) - PERFORM EDDY CURRENT INSPECTION. (AWL*)				Service	ATA:53
	MOS		10-May-23	96				AIRWORTHINESS		
	HRS		9071.3	2400						
	AFL		7252							
PROC. REF: NDT PART 6/53-30-01										PKG:19
P5310003 ^S					* AFT PRESSURE BULKHEAD SUPPORT POST (FS 457) - PERFORM EDDY CURRENT INSPECTION (AWL*)				Service	ATA:53
	MOS		10-May-05					AIRWORTHINESS		
	HRS		0	9600						
	AFL		0							
PROC. REF: NDT PART 6/53-30-18										PKG:26

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 53 - FUSELAGE											
P5310004 ^S			* AFT PRESSURE BULKHEAD FRAME PERIPHERY - PERFORM EDDY CURRENT INSPECTION. (AWL*)							Service	ATA:53
	MOS	10-May-23						AIRWORTHINESS			
	HRS	9071.3	4800								
	AFL	7252									
PROC. REF: NDT PART 6/53-30-21										PKG:25	
P5310006 ^S			* FORWARD PRESSURE BULKHEAD - PERFORM EDDY CURRENT INSPECTION. (AWL*)							Service	ATA:53
	MOS	10-May-05						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
PROC. REF: NDT PART 6/53-30-07										PKG:26	
P5320001 ^S			* FUSELAGE PRESSURE FLOOR STEP (FS 433 - FS 457) - PERFORM EDDY CURRENT INSPECTION. (AWL*)							Service	ATA:53
	MOS	10-May-05						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
PROC. REF: NDT PART 6/53-20-01										PKG:26	
P5323024 ^S			* FUSELAGE SKIN CUT-OUTS ABOVE FUEL CELL - PERFORM EDDY CURRENT INSPECTION. (AWL*)							Service	ATA:53
	MOS	10-May-23						AIRWORTHINESS			
	HRS	9071.3	4800								
	AFL	7252									
PROC. REF: NDT PART 6/53-30-12										PKG:25	
P5323027 ^S			* FUSELAGE FRAME AT FS 412 - PERFORM EDDY CURRENT INSPECTION. (AWL*)							Service	ATA:53
	MOS	10-May-23						AIRWORTHINESS			
	HRS	9071.3	4800								
	AFL	7252									
PROC. REF: NDT PART 6/53-30-20										PKG:25	
P5323029 ^S			* MACHINED SPAR FRAMES SYSTEMS CUTOUTS (FS 398, FS 412, FS 432, FS 466) - PERFORM EDDY CURRENT INSPECTION. (AWL*)							Service	ATA:53
	MOS	10-May-23						AIRWORTHINESS			
	HRS	9071.3	4800								
	AFL	7252									
PROC. REF: NDT PART 6/53-30-15										PKG:25	
P5323033 ^S			* FUSELAGE SKIN AT EMERGENCY DOOR EGRESS-LIGHT AND WING INSPECTION LIGHT - PERFORM EDDY CURRENT INSPECTION. (AWL*)							Service	ATA:53
	MOS	10-May-05						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
PROC. REF: NDT PART 6/53-40-02										PKG:26	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
P5323037 ^S					* WINDSHIELD COUPE RAIL TIE ROD BRACKET - PERFORM EDDY CURRENT INSPECTION. (AWL*)				Service	ATA:53
	MOS	10-May-05						AIRWORTHINESS		
	HRS	0	9600							
	AFL	0								
					PROC. REF: NDT PART 6/53-30-09					PKG:26
P5323038 ^S					* WINDSHIELD CENTERPOST TO UPPER COUPE RAIL JOINT ATTACHMENT - PERFORM EDDY CURRENT INSPECTION (AWL*)				Service	ATA:53
	MOS	10-May-23						AIRWORTHINESS		
	HRS	9071.3	4800							
	AFL	7252								
					PROC. REF: NDT PART 6/53-30-22					PKG:25
P5323047 ^S					* PRESSURE CABIN FUSELAGE CROWN SKIN - PERFORM EDDY CURRENT INSPECTION (AWL*)				Service	ATA:53
	MOS	10-May-23	96					AIRWORTHINESS		
	HRS	9071.3	2400							
	AFL	7252								
					PROC. REF: NDT PART 6/53-10-04					PKG:19
P5323049 ^S					* FUSELAGE SKIN AT UPPER AND LOWER COUPE RAIL RUN-OUT JOINTS - PERFORM EDDY CURRENT INSPECTION. (AWL*)				Service	ATA:53
	MOS	10-May-05						AIRWORTHINESS		
	HRS	0	9600							
	AFL	0								
					PROC. REF: NDT PART 6/53-30-11					PKG:26
P5323057 ^S					* PRESSURE CABIN SKIN AT FUSELAGE STATION 451 - PERFORM EDDY CURRENT INSPECTION (AWL*)				Service	ATA:53
	MOS	10-May-23	96					AIRWORTHINESS		
	HRS	9071.3	2400							
	AFL	7252								
					PROC. REF: NDT PART 6/53-30-06					PKG:19
P5323058 ^S					* FUSELAGE SKIN AT F.S. 504 - PERFORM EDDY CURRENT INSPECTION. (AWL*)				Service	ATA:53
	MOS	10-May-23						AIRWORTHINESS		
	HRS	9071.3	4800							
	AFL	7252								
					PROC. REF: NDT PART 6/53-30-13					PKG:25
P5323069 ^S					* CIRCUMFERENTIAL SKIN JOINT AT FORWARD PRESSURE BULKHEAD - PERFORM EDDY CURRENT INSPECTION. (AWL*)				Service	ATA:53
	MOS	10-May-05						AIRWORTHINESS		
	HRS	0	9600							
	AFL	0								
					PROC. REF: NDT PART 6/53-30-08					PKG:26

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 53 - FUSELAGE											
P5323164 ^S			* FUSELAGE SKIN AND DOUBLER AROUND ECS DUCT CUTOUT - PERFORM EDDY CURRENT INSPECTION. (AWL*)							Service	ATA:53
	MOS	10-May-05						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
PROC. REF: NDT PART 6/53-40-01										PKG:26	
P5323165 ^S			* WINDSHIELD CENTER POST TO LOWER COUPE RAIL JOINT ATTACHMENT - PERFORM EDDY CURRENT INSPECTION (AWL*)							Service	ATA:53
	MOS	10-May-05						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
PROC. REF: NDT PART 6/53-30-10										PKG:26	
P5360006 ^S			DELTA FIN ATTACH BOLT - PERFORM LIQUID PENETRANT INSPECTION.							Service	ATA:53
	MOS	10-May-05									
	HRS	0	9600 (+25/-25)								
	AFL	0									
PROC. REF: NDT PART 8/53-10-02										PKG:26	
Q5310023 ^S			FORWARD AND AFT FUEL CELL BAY STRUCTURE, ANGLE REINFORCEMENT, STRINGER 1, LH & RH - PERFORM DETAILED VISUAL INSPECTION OF HI-LITE COLLARS.							Service	ATA:53
	MOS	10-May-05									
	HRS	0	9600 (+25/-25)								
	AFL	0									
PROC. REF: AMM RSIP-HST79-104-2										PKG:26	
Q5310025 ^S			AFT FUSELAGE KEELBEAM LONGERON (LH & RH, BL 5.15, FS 466.30 - 495.12) AND AFT FUSELAGE KEELBEAM LOWER FRAME (FS 466.30, BL 9.55 LH THRU BL 9.55 RH) - PERFORM DETAILED VISUAL INSPECTION OF HI-LITE COLLARS.							Service	ATA:53
	MOS	10-May-05									
	HRS	0	9600 (+25/-25)								
	AFL	0									
PROC. REF: AMM RSIP-HST79-104-3										PKG:26	
Q5323048 ^S			* FUSELAGE (PRESSURE CABIN) - PERFORM EDDY CURRENT INSPECTION. INSPECT PRESSURE CABIN SKIN (LONGITUDINAL SKIN CRACKING). (AWL*)							Service	ATA:53
	MOS	10-May-23						AIRWORTHINESS			
	HRS	9071.3	4800								
	AFL	7252									
PROC. REF: NDT PART 6/53-30-05										PKG:25	

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 53 - FUSELAGE											
Q5323099 ^S			* LONGITUDINAL JOINTS INSIDE PRESSURE CABIN (FS 244 - FS 457) AND SKIN WITHIN ONE STRINGER BAY OF JOINT - PERFORM EDDY CURRENT INSPECTION. INSPECT SKIN FASTENER HOLES ALONG JOINTS AT STRINGER 10 LH AND RH AND STRINGER 2 RH AND STRINGER 18 RH (AWL*)						Service	ATA:53	
	MOS	10-May-23						AIRWORTHINESS			
	HRS	9071.3	4800								
	AFL	7252									
PROC. REF: NDT PART 6/53-30-05										PKG:25	
Q5323103 ^S			* STRINGER TO FRAME JOINTS (FS 186 TO FS 237) - PERFORM EDDY CURRENT INSPECTION. INSPECT SKIN, STRINGERS, AND FRAMES AT JOINTS. (AWL*)						Service	ATA:53	
	MOS	10-May-05						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
PROC. REF: NDT PART 6/53-30-05										PKG:26	
T5310027 ^S			* AFT PRESSURE BULKHEAD TOP MOUNTING STRUCTURE - PERFORM EDDY CURRENT INSPECTION (AWL*)						Service	ATA:53	
	MOS	10-May-05						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
PROC. REF: NDT PART 6/53-30-17										PKG:26	
T5321089 ^S			SEAT RAILS - PERFORM DETAILED INSPECTION OF SEAT RAIL (TRACK) SHEAR WEBS FOR CRACKING.						Service	ATA:53	
	MOS	25-Jan-24	24 (+14d/-14d)								
	HRS	9265.8	600 (+25/-25)								
	AFL	7395									
PROC. REF: AMM 53-20-01										PKG:7	
T5323028 ^S			* FUSELAGE TO WING ATTACH FITTINGS - PERFORM EDDY CURRENT INSPECTION. (AWL*)						Service	ATA:53	
	MOS	10-May-23						AIRWORTHINESS			
	HRS	9071.3	4800								
	AFL	7252									
PROC. REF: NDT PART 6/53-30-16										PKG:25	
V5323169 ^S			*FUSELAGE SKIN AT STRINGER AND FRAME LOCATIONS FS230.84 TO FS244.00 - PERFORM EDDY CURRENT INSPECTION. (EFFECTIVE ON AIRCRAFT 45-2006 ONLY) (AWL*)						Service	ATA:53	
	MOS/MSC	10-May-23	N/A					AIRWORTHINESS			
	HRS	9071.3									
	AFL	7252									
PROC. REF: GENERIC NO REF										PKG:25	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 53 - FUSELAGE											
V5323170 ^S			*FUSELAGE SKIN AT STRINGER AND FRAME LOCATIONS FS349.12 TO FS377.54 - PERFORM EDDY CURRENT INSPECTION. (EFFECTIVE ON AIRCRAFT 45-2006 ONLY) (AWL*)						Service	ATA:53	
	MOS/MSC	10-May-23	N/A					AIRWORTHINESS			
	HRS	9071.3									
	AFL	7252									
					PROC. REF: GENERIC NO REF					PKG:25	
V5323171 ^S			*STRINGER 10 AT FUSELAGE STATION FS345.39 TO 378.38 - PERFORM X-RAY INSPECTION. (EFFECTIVE ON AIRCRAFT 45-2006 ONLY) (AWL*)						Service	ATA:53	
	MOS/MSC	10-May-23	N/A					AIRWORTHINESS			
	HRS	9071.3									
	AFL	7252									
					PROC. REF: GENERIC NO REF					PKG:25	
Y5311001 ^S			NOSE LANDING GEAR ACTUATOR ATTACH FITTING AND SURROUNDING STRUCTURE - PERFORM VISUAL INSPECTION.						Service	ATA:53	
	MOS	11-Mar-22	48 (+14d/-14d)								
	HRS	8721.2	1200 (+25/-25)								
	AFL	7006									
					PROC. REF: GENERIC NO REF					PKG:17	
Y5311003 ^S			NOSE LANDING GEAR TRUNNION FITTING AND SURROUNDING STRUCTURE - PERFORM VISUAL INSPECTION.						Service	ATA:53	
	MOS	11-Mar-22	48 (+14d/-14d)								
	HRS	8721.2	1200 (+25/-25)								
	AFL	7006									
					PROC. REF: GENERIC NO REF					PKG:17	
Y5320000 ^S			CENTER PEDESTAL - PERFORM VISUAL INSPECTION						Service	ATA:53	
	MOS	25-Jan-24	12 (+14d/-14d)								
	HRS	9265.8	300 (+25/-25)								
	AFL	7395									
					PROC. REF: GENERIC NO REF					PKG:1	
Y5321010 ^S			PERFORM FLOORBOARDS AROUND GALLEY, LAVATORY, AND WATER TANK - PERFORM VISUAL INSPECTION. NOTE: IF EVIDENCE OF SPILLAGE IS VISIBLE, PERFORM INSPECTION ON THE GALLEY AND LAVATORY AREAS FOR SPILLS AND CORROSION.						Service	ATA:53	
	MOS	25-Jan-24	12 (+14d/-14d)								
	HRS	9265.8	300 (+25/-25)								
	AFL	7395									
					PROC. REF: AMM 53-20-01					PKG:1	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 53 - FUSELAGE											
Y5321011 ^S			TAILCONE BAGGAGE COMPARTMENT - PERFORM VISUAL INSPECTION.						Service	ATA:53	
	MOS	25-Jan-24	24	(+14d/-14d)							
	HRS	9265.8	600	(+25/-25)							
	AFL	7395									
				PROC. REF: GENERIC NO REF							PKG:8
Y5321088 ^S			SEAT RAILS - REMOVE FLOORBOARD 230AL AND PERFORM VISUAL INSPECTION OF SEAT RAILS. NOTE: IF CORROSION IS DETECTED, REMOVE ALL FLOORBOARDS AND INSPECT ALL SEAT RAILS.						Service	ATA:53	
	MOS	11-Mar-22	48	(+14d/-14d)							
	HRS	8721.2	1200	(+25/-25)							
	AFL	7006									
				PROC. REF: GENERIC NO REF							PKG:13
Y5323031 ^S			EXTERIOR CABIN WINDOW COAMINGS AND SURROUNDING FUSELAGE SKIN - PERFORM VISUAL INSPECTION USING 10X MAGNIFICATION AND ADEQUATE LIGHTING.						Service	ATA:53	
	MOS	11-Mar-22	48	(+14d/-14d)							
	HRS	8721.2	1200	(+25/-25)							
	AFL	7006									
				PROC. REF: GENERIC NO REF							PKG:13
Y5323105 ^S			EXTERNAL FUSELAGE (PRESSURE CABIN) - PERFORM VISUAL INSPECTION OF ALL CABIN SKINS FROM F.S. 124 TO F.S.458. PAY PARTICULAR ATTENTION TO ALL CUTOUTS AND SKIN JOINTS. NO FAIRING ACCESS REQUIRED.						Service	ATA:53	
	MOS	11-Mar-22	48	(+14d/-14d)							
	HRS	8721.2	1200	(+25/-25)							
	AFL	7006									
				PROC. REF: GENERIC NO REF							PKG:13
Y5340007 ^S			WING ATTACH FITTINGS - PERFORM VISUAL INSPECTION.						Service	ATA:53	
	MOS	10-May-23	96	(+14d/-14d)							
	HRS	9071.3	2400	(+25/-25)							
	AFL	7252									
				PROC. REF: GENERIC NO REF							PKG:19
Y5360000 ^S			DELTA FINS - PERFORM VISUAL INSPECTION.						Service	ATA:53	
	MOS	25-Jan-24	24	(+14d/-14d)							
	HRS	9265.8	600	(+25/-25)							
	AFL	7395									
				PROC. REF: GENERIC NO REF							PKG:8

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 54 - NACELLES/PYLONS										
5-19-00-Q5450013-LEFT ^U	LEFT FORWARD ENGINE BEAM AND BEAM FITTING - PERFORM VISUAL INSPECTION, PAYING PARTICULAR ATTENTION TO THE FOLLOWING:A. UPPER CAPPING PLATE AT FASTENER HOLES, AND CHANNEL FLANGE AT FASTENER HOLESB. BOLT HOLES, ESPECIALLY UPPER BOLT HOLE ON AFT FLANGE(IRN Q5450013)								Service	ATA:54
	MOS/MSC	10-May-05	N/A							
	HRS	0								
	AFL	0								
PROC. REF: GENERIC NO REF										
5-19-00-Q5450013-RIGHT ^U	RIGHT FORWARD ENGINE BEAM AND BEAM FITTING - PERFORM VISUAL INSPECTION, PAYING PARTICULAR ATTENTION TO THE FOLLOWING:A. UPPER CAPPING PLATE AT FASTENER HOLES, AND CHANNEL FLANGE AT FASTENER HOLESB. BOLT HOLES, ESPECIALLY UPPER BOLT HOLE ON AFT FLANGE(IRN Q5450013)								Service	ATA:54
	MOS/MSC	10-May-05	N/A							
	HRS	0								
	AFL	0								
PROC. REF: GENERIC NO REF										
5-19-01-A5450022-LEFT	REPLACE * AFT ENGINE MOUNT TO END FITTING ATTACH BOLT (IRN A5450022) (AWL*)								Service	ATA:54
	MOS	10-May-05						LIFE LIMIT		
	HRS	0	9600		9600		84.3			
	AFL	0								
PROC. REF: AMM 71-20-00										
5-19-01-A5450022-RIGHT	REPLACE * AFT ENGINE MOUNT TO END FITTING ATTACH BOLT (IRN A5450022) (AWL*)								Service	ATA:54
	MOS	10-May-05						LIFE LIMIT		
	HRS	0	9600		9600		84.3			
	AFL	0								
PROC. REF: AMM 71-20-00										
5-19-01-P5450020-LEFT	REPLACE * AFT ENGINE BEAM TO FRAME ATTACHMENT BOLT (P5450020) (AWL*)								Service	ATA:54
	MOS	10-May-05						LIFE LIMIT		
	HRS	0	9600		9600		84.3			
	AFL	0								
PROC. REF: NDT PART 8/54-30-01										
5-19-01-P5450020-RIGHT	REPLACE * AFT ENGINE BEAM TO FRAME ATTACHMENT BOLT (P5450020) (AWL*)								Service	ATA:54
	MOS	10-May-05						LIFE LIMIT		
	HRS	0	9600		9600		84.3			
	AFL	0								
PROC. REF: NDT PART 8/54-30-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 54 - NACELLES/PYLONS										
5-19-01-P5450023-LEFT	REPLACE * ENGINE TO AFT ENGINE MOUNT ATTACH BOLT (IRN P5450023) (AWL*)									Service ATA:54
MOS	10-May-05							LIFE LIMIT		
HRS	0	9600			9600	84.3				
AFL	0									
PROC. REF: NDT PART 8/54-30-02										
5-19-01-P5450023-RIGHT	REPLACE * ENGINE TO AFT ENGINE MOUNT ATTACH BOLT (IRN P5450023) (AWL*)									Service ATA:54
MOS	10-May-05							LIFE LIMIT		
HRS	0	9600			9600	84.3				
AFL	0									
PROC. REF: NDT PART 8/54-30-02										
5450054	LEFT FORWARD ENGINE BEAM AND BEAM FITTING - PERFORM VISUAL INSPECTION, PAYING PARTICULAR ATTENTION TO THE FOLLOWING: A. UPPER CAPPING PLATE AT FASTENER HOLES, AND CHANNEL FLANGE AT FASTENER HOLES B. BOLT HOLES, ESPECIALLY UPPER BOLT HOLE ON AFT FLANGE									Service ATA:54
MOS	07-Feb-14									
HRS	5991.87	7000 (+100/-100)			12991.87	13091.87	3476.2 (+100)			
AFL	4884									
PROC. REF: AMM 05-10-00										
5450054	RIGHT FORWARD ENGINE BEAM AND BEAM FITTING - PERFORM VISUAL INSPECTION, PAYING PARTICULAR ATTENTION TO THE FOLLOWING:A. UPPER CAPPING PLATE AT FASTENER HOLES, AND CHANNEL FLANGE AT FASTENER HOLESB. BOLT HOLES, ESPECIALLY UPPER BOLT HOLE ON AFT FLANGE									Service ATA:54
MOS	07-Feb-14									
HRS	5991.87	7000 (+100/-100)			12991.87	13091.87	3476.2 (+100)			
AFL	4884									
PROC. REF: AMM 05-10-00										
A5450026 ^S	* ENGINE DRAG STRUT - PERFORM EDDY CURRENT INSPECTION (AWL*)									Service ATA:54
MOS	10-May-23							AIRWORTHINESS		
HRS	9071.3	4800								
AFL	7252									
PROC. REF: NDT PART 6/54-50-01										
E5450029 ^S	* AFT ENGINE BEAM - PERFORM VISUAL INSPECTION. INSPECT UPPER CAPPING PLATE, AROUND FASTENER HOLES IN THE CAPPING PLATE, AND CHANNEL FLANGE (AWL*)									Service ATA:54
MOS	10-May-23							AIRWORTHINESS		
HRS	9071.3	4800								
AFL	7252									
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 54 - NACELLES/PYLONS										
F5450019 ^S					* AFT ENGINE BEAM ATTACHMENT TO FRAMES - PERFORM VISUAL INSPECTION. INSPECT AFT ENGINE BEAM ATTACHMENT TO FRAMES (AWL*)				Service	ATA:54
	MOS		10-May-23					AIRWORTHINESS		
	HRS		9071.3		4800					
	AFL		7252							
PROC. REF: GENERIC NO REF										PKG:25
H5450012 ^S					* FRAMES 39/40 (FS 512/518) AT ENGINE BEAM ATTACHMENT - PERFORM EDDY CURRENT INSPECTION. INSPECT OUTER FLANGE AND FRAME WEB AT ENGINE BEAM ATTACHMENT (AWL*)				Service	ATA:54
	MOS		10-May-23					AIRWORTHINESS		
	HRS		9071.3		4800					
	AFL		7252							
PROC. REF: NDT PART 6/54-50-03										PKG:25
M5450015 ^S					* FORWARD ENGINE BEAM, SPAR CAP, AND WEB - PERFORM EDDY CURRENT INSPECTION. (AWL*)				Service	ATA:54
	MOS		10-May-23					AIRWORTHINESS		
	HRS		9071.3		4800					
	AFL		7252							
PROC. REF: NDT PART 6/54-50-05										PKG:25
M5450018 ^S					*FORWARD ENGINE MOUNT ATTACHMENT BOLTS - PERFORM FLUORESCENT LIQUID PENETRANT INSPECTION (AWL*)				Service	ATA:54
	MOS		10-May-23					AIRWORTHINESS		
	HRS		9071.3		4800					
	AFL		7252							
PROC. REF: NDT PART 8/71-20-01										PKG:25
P5450011 ^S					* DRAG STRUT ATTACHMENT FITTINGS - PERFORM EDDY CURRENT INSPECTION. (AWL*)				Service	ATA:54
	MOS		10-May-23					AIRWORTHINESS		
	HRS		9071.3		4800					
	AFL		7252							
PROC. REF: NDT PART 6/53-10-03										PKG:25
P5450016 ^S					*FORWARD ENGINE BEAM END FITTING - PERFORM EDDY CURRENT INSPECTION. (AWL*)				Service	ATA:54
	MOS		10-May-23					AIRWORTHINESS		
	HRS		9071.3		4800					
	AFL		7252							
PROC. REF: NDT PART 6/54-50-02										PKG:25
P5450017 ^S					* FORWARD ENGINE BEAM TO FRAME ATTACH BOLTS - PERFORM LIQUID PENETRANT INSPECTION (AWL*)				Service	ATA:54
	MOS		10-May-23					AIRWORTHINESS		
	HRS		9071.3		4800					
	AFL		7252							
PROC. REF: NDT PART 8/53-40-01										PKG:25

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 54 - NACELLES/PYLONS											
P5450021 ^S			* ENGINE AFT ISOLATOR MOUNT FITTINGS - PERFORM LIQUID PENETRANT INSPECTION. (AWL*)							Service	ATA:54
	MOS	10-May-23						AIRWORTHINESS			
	HRS	9071.3	4800								
	AFL	7252									
PROC. REF: NDT PART 8/71-20-03										PKG:25	
P5450024 ^S			* FUSELAGE FRAMES AT FS 543.55 AND 546.15 TO AFT BEAM ATTACHMENT - PERFORM EDDY CURRENT INSPECTION (AWL*)							Service	ATA:54
	MOS	10-May-23						AIRWORTHINESS			
	HRS	9071.3	4800								
	AFL	7252									
PROC. REF: NDT PART 6/53-30-14										PKG:25	
P5450025 ^S			* FORWARD ENGINE BEAM AND FRAMES AT ATTACH HOLES - PERFORM EDDY CURRENT INSPECTION (AWL*)							Service	ATA:54
	MOS	10-May-23						AIRWORTHINESS			
	HRS	9071.3	4800								
	AFL	7252									
PROC. REF: NDT PART 6/54-50-03										PKG:25	
P5450030 ^S			* AFT ENGINE BEAM END FITTING - PERFORM EDDY CURRENT INSPECTION (AWL*)							Service	ATA:54
	MOS	10-May-23						AIRWORTHINESS			
	HRS	9071.3	4800								
	AFL	7252									
PROC. REF: NDT PART 6/54-50-04										PKG:25	
Y5410002 ^S			PYLONS - PERFORM VISUAL INSPECTION. INSPECT HILITE COLLARS COMMON TO MAIN ENGINE BEAM EXTERNAL TO FUSELAGE							Service	ATA:54
	MOS	11-Mar-22	48 (+14d/-14d)								
	HRS	8721.2	1200 (+25/-25)								
	AFL	7006									
PROC. REF: AMM 54-00-01										PKG:14	
ATA 55 - STABILIZERS											
5-19-00-M5510010			* HORIZONTAL STABILIZER AFT ROOT RIB - PERFORM EDDY CURRENT INSPECTION. INSPECT AFT ROOT RIB INTERNAL BETWEEN MID SPAR AND AFT SPAR AND UPPER AND LOWER SKINS EXTERNAL AT ATTACHMENT FASTNERS. (IRN M5510010) (AWL*)							Service	ATA:55
	MOS	03-Nov-22						AIRWORTHINESS			
	HRS	8950.9	1200		10150.9		635.2				
	AFL	7175									
PROC. REF: NDT PART 6/55-10-03											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 55 - STABILIZERS										
5-19-00-M5540022	RUDDER TORQUE TUBE - PERFORM BORESCOPE INSPECTION									Service ATA:55
	MOS/MSC	11-May-05	N/A							
	HRS	4185.15								
	AFL	3428								
PROC. REF: GENERIC NO REF										
5-19-00-W5510091	* HORIZONTAL STABILIZER HINGE PRIMARY AND SECONDARY PIVOT PIN INSTALLATION AND ATTACHING HARDWARE - PERFORM DETAILED VISUAL INSPECTION (IRN W5510091) (AWL*)									Service ATA:55
	MOS	03-Nov-22						AIRWORTHINESS		
	HRS	8950.9	625		9575.9		60.2			
	AFL	7175								
PROC. REF: AMM 55-10-00										
5510034	HORIZONTAL STABILIZER PRIMARY AND SECONDARY BOLTS AND BUSHINGS - PERFORM DETAILED INSPECTION									Service ATA:55
	MOS	14-Mar-19								
	HRS	7551	4800 (+25/-25)		12351	12376	2835.3 (+25)			
	AFL									
PROC. REF: AMM 55-10-00										
551200	HORIZONTAL STABILIZER									Component ATA:55
PN:4555101002-027	MOS/MSC	10-May-23	O/C		TSN 216					
SN:S7549A0056	HRS	9071.3			TSN 9071.3					
	AFL	7252			TSN 7252					
PROC. REF: AMM 27-40-01										
552031	LEFT ELEVATOR									Component ATA:55
PN:4555201001V7003-001	MOS/MSC	10-May-23	O/C		TSN 216					
SN:S7549A0059	HRS	9071.3			TSN 9071.3					
	AFL	7252			TSN 7252					
PROC. REF: AMM 55-20-00										
552032	RIGHT ELEVATOR									Component ATA:55
PN:4555201001V7003-002	MOS/MSC	10-May-23	O/C		TSN 216					
SN:S7549A0059	HRS	9071.3			TSN 9071.3					
	AFL	7252			TSN 7252					
PROC. REF: AMM 55-20-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 55 - STABILIZERS										
553001	VERTICAL ASSEMBLY, TAILCONE STABILIZER									Component ATA:55
PN:4555301001-001	MOS/MSC	10-May-05	O/C	TSN 0						
SN:A0055	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
554005	ASSEMBLY RUDDER									Component ATA:55
PN:4555401000-017	MOS/MSC	10-May-23	O/C	TSN 216						
SN:S7549A0063	HRS	9071.3		TSN 9071.3						
	AFL	7252		TSN 7252						
PROC. REF: AMM 27-20-01										
A5510014 ^S	* VERTICAL STABILIZER PIVOT FITTING BOTTOM PLATE - PERFORM DETAILED VISUAL INSPECTION. INSPECT AFT PORTION OF BOTTOM PLATE THROUGH LIGHTENING HOLE IN TOP PLATE, FORWARD PORTION OF BOTTOM PLATE THROUGH TOP PLATE CUTOUTS, AND BOTTOM OF OUTSIDE EXPOSED SURFACE OF PIVOT FITTING (AWL*)									Service ATA:55
	MOS	10-May-05						AIRWORTHINESS		
	HRS	0	9600							
	AFL	0								
PROC. REF: GENERIC NO REF										
A5510021 ^S	* HORIZONTAL MID SPAR FROM CANTED RIB #2 TO CANTED RIB #3 - PERFORM DETAILED VISUAL INSPECTION (AWL*)									Service ATA:55
	MOS	10-May-05						AIRWORTHINESS		PKG:26
	HRS	0	9600							
	AFL	0								
PROC. REF: GENERIC NO REF										
A5540000 ^S	* RUDDER ROOT RIB CAP (FS 698) - PERFORM VISUAL INSPECTION. INSPECT AROUND FASTENER HOLES AND LIGHTENING HOLES (AWL*)									Service ATA:55
	MOS	10-May-05						AIRWORTHINESS		PKG:26
	HRS	0	9600							
	AFL	0								
PROC. REF: GENERIC NO REF										
E5510074 ^S	* HORIZONTAL STABILIZER REAR SPAR FROM CANTED RIB #2 TO CANTED RIB #3 - PERFORM VISUAL INSPECTION. INSPECT REAR SPAR CAP AND FASTENERS (AWL*)									Service ATA:55
	MOS	10-May-05						AIRWORTHINESS		PKG:26
	HRS	0	9600							
	AFL	0								
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 55 - STABILIZERS											
E5510075 ^S			* HORIZONTAL STABILIZER OUTBOARD SPARS AND SKINS OUTBOARD OF CANTED RIB #3 - PERFORM VISUAL INSPECTION. INSPECT SPAR CAPS AND FASTENERS. (AWL*)						INSPECT	Service	ATA:55
	MOS		10-May-05					AIRWORTHINESS			
	HRS		0		9600						
	AFL		0								
PROC. REF: GENERIC NO REF										PKG:26	
E5510076 ^S			* HORIZONTAL STABILIZER FRONT SPAR FROM CANTED RIB #2 TO CANTED RIB #3 - PERFORM VISUAL INSPECTION. INSPECT FRONT SPAR CAP AND FASTENERS (AWL*)						INSPECT FRONT	Service	ATA:55
	MOS		10-May-05					AIRWORTHINESS			
	HRS		0		9600						
	AFL		0								
PROC. REF: GENERIC NO REF										PKG:26	
E5520003 ^S			* ELEVATOR FRONT SPAR - PERFORM VISUAL INSPECTION. INSPECT SPAR CAP AT FASTENER HOLES (AWL*)						INSPECT SPAR CAP AT FASTENER HOLES (AWL*)	Service	ATA:55
	MOS		10-May-05					AIRWORTHINESS			
	HRS		0		9600						
	AFL		0								
PROC. REF: GENERIC NO REF										PKG:26	
E5520004 ^S			* ELEVATOR RIB #1 CAP - PERFORM VISUAL INSPECTION OF RIB #1 CAP CROSS SECTION AND RIB CAP FLANGES AT TORQUE TUBE. (AWL*)						INSPECT RIB #1 CAP CROSS SECTION AND RIB CAP FLANGES AT TORQUE TUBE. (AWL*)	Service	ATA:55
	MOS		10-May-05					AIRWORTHINESS			
	HRS		0		9600						
	AFL		0								
PROC. REF: GENERIC NO REF										PKG:26	
G5510000 ^S			* HORIZONTAL STABILIZER ACTUATOR ATTACHMENT FITTINGS - PERFORM EDDY CURRENT INSPECTION (AWL*)						INSPECT ATTACHMENT FITTINGS - PERFORM EDDY CURRENT INSPECTION (AWL*)	Service	ATA:55
	MOS		10-May-23					AIRWORTHINESS			
	HRS		9071.3		4800						
	AFL		7252								
PROC. REF: NDT PART 6/55-10-01										PKG:25	
G5510023 ^S			* HORIZONTAL STABILIZER ACTUATOR VERTICAL TAIL ATTACHMENT - PERFORM EDDY CURRENT INSPECTION (AWL*)						INSPECT VERTICAL TAIL ATTACHMENT - PERFORM EDDY CURRENT INSPECTION (AWL*)	Service	ATA:55
	MOS		10-May-23					AIRWORTHINESS			
	HRS		9071.3		4800						
	AFL		7252								
PROC. REF: NDT PART 6/55-30-01										PKG:25	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 55 - STABILIZERS											
H5510033 ^S			* HORIZONTAL STABILIZER ACTUATOR ATTACHMENT BOLTS - PERFORM LIQUID PENETRANT INSPECTION (AWL*)							Service	ATA:55
	MOS	10-May-23						AIRWORTHINESS			
	HRS	9071.3	4800								
	AFL	7252									
PROC. REF: NDT PART 8/27-40-01										PKG:25	
N5510005 ^S			* HORIZONTAL STABILIZER REAR SPAR CAP - PERFORM EDDY CURRENT INSPECTION. INSPECT REAR SPAR CAP AND WEB AT CENTER SPLICE. (AWL*)							Service	ATA:55
	MOS	10-May-23	96					AIRWORTHINESS			
	HRS	9071.3	2400								
	AFL	7252									
PROC. REF: NDT PART 6/55-10-05										PKG:20	
N5510015 ^S			* VERTICAL STABILIZER PIVOT FITTING TOP PLATE - PERFORM EDDY CURRENT INSPECTION. (AWL*)							Service	ATA:55
	MOS	10-May-23	96					AIRWORTHINESS			
	HRS	9071.3	2400								
	AFL	7252									
PROC. REF: NDT PART 6/55-30-02										PKG:20	
N5510016 ^S			* VERTICAL STABILIZER PIVOT FITTING TOWER SECTION FORWARD RADIUS - PERFORM EDDY CURRENT INSPECTION.INSPECT PIVOT FITTING AT TOWER SECTION RADIUS,PIVOT FITTING AND TOP PLATE AROUND ADJACENT FASTENERS,AND PIVOT FITTING SIDES AT TOWER SECTION RADIUS. (AWL*)							Service	ATA:55
	MOS	10-May-23	96					AIRWORTHINESS			
	HRS	9071.3	2400								
	AFL	7252									
PROC. REF: NDT PART 6/55-30-03										PKG:20	
N5510069 ^S			* HORIZONTAL STABILIZER MID SPAR FLANGE ROOT RIB ATTACHMENT - PERFORM EDDY CURRENT INSPECTION. (AWL*)							Service	ATA:55
	MOS	10-May-23	96					AIRWORTHINESS			
	HRS	9071.3	2400								
	AFL	7252									
PROC. REF: NDT PART 6/55-10-02										PKG:20	
N5510082 ^S			* HORIZONTAL STABILIZER REAR SPAR FLANGE ROOT RIB ATTACHMENT -PERFORM EDDY CURRENT INSPECTION. (AWL*)							Service	ATA:55
	MOS	10-May-23	96					AIRWORTHINESS			
	HRS	9071.3	2400								
	AFL	7252									
PROC. REF: NDT PART 6/55-10-04										PKG:20	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 55 - STABILIZERS											
P5510006 ^S			* VERTICAL STABILIZER FRONT SPAR AND MID SPAR - PERFORM RADIOGRAPHIC INSPECTION (AWL*)							Service	ATA:55
	MOS	10-May-05						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
PROC. REF: NDT PART 2/55-30-01										PKG:26	
P5510008 ^S			* HORIZONTAL STABILIZER PRIMARY AND SECONDARY ATTACH BOLTS - PERFORM MAGNETIC PARTICLE INSPECTION (AWL*)							Service	ATA:55
	MOS	10-May-05						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
PROC. REF: NDT PART 7/55-30-02, NDT PART 7/55-30-03										PKG:26	
P5510009 ^S			* HORIZONTAL STABILIZER MID SPAR CAP B.L. 0.0 TO B.L. 4.0 - PERFORM X-RAY INSPECTION (AWL*)							Service	ATA:55
	MOS	10-May-23	96					AIRWORTHINESS			
	HRS	9071.3	2400								
	AFL	7252									
PROC. REF: NDT PART 2/55-10-03										PKG:20	
P5510011 ^S			* HORIZONTAL STABILIZER MID-SPAR AND REAR-SPAR UPPER FLANGE AT ROOT RIB - PERFORM RADIOGRAPHIC INSPECTION (AWL*)							Service	ATA:55
	MOS	10-May-05						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
PROC. REF: NDT PART 2/55-10-01										PKG:26	
P5510017 ^S			* VERTICAL STABILIZER PIVOT FITTING TOWER SECTION - PERFORM EDDY CURRENT INSPECTION (AWL*)							Service	ATA:55
	MOS	10-May-23	96					AIRWORTHINESS			
	HRS	9071.3	2400								
	AFL	7252									
PROC. REF: NDT PART 6/55-30-05										PKG:20	
P5510018 ^S			* VERTICAL STABILIZER PIVOT FITTING LUGS - PERFORM EDDY CURRENT INSPECTION (AWL*)							Service	ATA:55
	MOS	10-May-05						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
PROC. REF: NDT PART 6/55-30-04										PKG:26	
P5510019 ^S			* ELEVATOR HINGES ON HORIZONTAL STABILIZER - PERFORM EDDY CURRENT INSPECTION (AWL*)							Service	ATA:55
	MOS	10-May-05						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
PROC. REF: NDT PART 6/55-20-02										PKG:26	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 55 - STABILIZERS											
P5510020 ^S			* HORIZONTAL MID-SPAR UPPER CAP - PERFORM EDDY CURRENT INSPECTION (AWL*)								Service ATA:55
	MOS	10-May-05						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
					PROC. REF: NDT PART 6/55-10-07					PKG:26	
P5510024 ^S			* ELEVATOR CONTROL HORN - PERFORM EDDY CURRENT INSPECTION (AWL*)								Service ATA:55
	MOS	10-May-05						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
					PROC. REF: NDT PART 6/55-20-01					PKG:26	
P5510070 ^S			* HORIZONTAL STABILIZER FRONT SPAR - PERFORM RADIOGRAPHIC INSPECTION (AWL*)								Service ATA:55
	MOS	10-May-05						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
					PROC. REF: NDT PART 2/55-10-02					PKG:26	
P5510073 ^S			* HORIZONTAL REAR SPAR UPPER CAP - PERFORM EDDY CURRENT INSPECTION (AWL*)								Service ATA:55
	MOS	10-May-05						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
					PROC. REF: NDT PART 6/55-10-07					PKG:26	
P5510092 ^S			* HORIZONTAL STABILIZER UPPER-SPAR-SPLICE DOUBLER - PERFORM EDDY CURRENT INSPECTION (AWL*)								Service ATA:55
	MOS	10-May-23	96					AIRWORTHINESS			
	HRS	9071.3	2400								
	AFL	7252									
					PROC. REF: NDT PART 6/55-10-06					PKG:26	
P5520001 ^S			* ELEVATOR HINGE ATTACH BOLT - PERFORM MAGNETIC PARTICLE INSPECTION (AWL*)								Service ATA:55
	MOS	10-May-05						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
					PROC. REF: NDT PART 7/27-30-01					PKG:26	
P5520021 ^S			* ELEVATOR HINGE FITTINGS - PERFORM EDDY CURRENT INSPECTION (AWL*)								Service ATA:55
	MOS	10-May-05						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
					PROC. REF: NDT PART 6/55-30-07					PKG:26	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 55 - STABILIZERS											
P5520022 ^S			* ELEVATOR HINGE PRIMARY AND SECONDARY ATTACH BOLTS - PERFORM LIQUID PENETRANT INSPECTION (AWL*)							Service	ATA:55
	MOS	10-May-05						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
PROC. REF: NDT PART 8/27-30-01, NDT PART 8/27-30-02										PKG:26	
P5540001 ^S			* RUDDER SPAR - PERFORM DETAILED VISUAL INSPECTION. INSPECT SPAR CAPS AND FASTENERS (AWL*)							Service	ATA:55
	MOS	10-May-05						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
PROC. REF: GENERIC NO REF										PKG:26	
P5540002 ^S			* RUDDER ATTACH BOLT - PERFORM LIQUID PENETRANT INSPECTION (AWL*)							Service	ATA:55
	MOS	10-May-05						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
PROC. REF: NDT PART 8/55-30-02										PKG:26	
Q5510007 ^S			* VERTICAL STABILIZER SKIN AND AFT LOWER SPAR CAP - PERFORM EDDY CURRENT INSPECTION (AWL*)							Service	ATA:55
	MOS	10-May-05						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
PROC. REF: NDT PART 6/55-30-06										PKG:26	
Q5530011 ^S			* VERTICAL STABILIZER SKIN AND UPPER AFT SPAR CAP - PERFORM EDDY CURRENT INSPECTION (AWL*)							Service	ATA:55
	MOS	10-May-23	96					AIRWORTHINESS			
	HRS	9071.3	2400								
	AFL	7252									
PROC. REF: NDT PART 6/55-30-06										PKG:26	
T5510004 ^S			* RUDDER HINGE FITTINGS - PERFORM VISUAL INSPECTION. CONTROL SURFACE REMOVAL NOT REQUIRED. (AWL*)							Service	ATA:55
	MOS	10-May-05						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
PROC. REF: GENERIC NO REF										PKG:26	
Y5510001 ^S			HORIZONTAL STABILIZER - PERFORM EXTERNAL VISUAL INSPECTION.							Service	ATA:55
	MOS	11-Mar-22	48 (+14d/-14d)								
	HRS	8721.2	1200 (+25/-25)								
	AFL	7006									
PROC. REF: GENERIC NO REF										PKG:14	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 55 - STABILIZERS											
Y5510002 ^S		ELEVATOR HINGES ON HORIZONTAL STABILIZER - PERFORM VISUAL INSPECTION. INSPECT HINGE LUGS ON HORIZONTAL TAIL SIDE OF JOINT. INSPECT HILITE COLLARS AT BL 0.0 AND OUTBOARD ELEVATOR HINGE							Service	ATA:55	
	MOS	11-Mar-22	48 (+14d/-14d)								
	HRS	8721.2	1200 (+25/-25)								
	AFL	7006									
PROC. REF: GENERIC NO REF										PKG:14	
Y5510003 ^S		VERTICAL STABILIZER PIVOT FITTING - PERFORM VISUAL INSPECTION. INSPECT HILITE COLLARS COMMON TO THE PIVOT FITTING (MID SPAR, AFT SPAR, TOP PLATE, AND UP/DOWN SPRING BRACKET).							Service	ATA:55	
	MOS	11-Mar-22	48 (+14d/-14d)								
	HRS	8721.2	1200 (+25/-25)								
	AFL	7006									
PROC. REF: GENERIC NO REF										PKG:14	
Y5510093 ^S		HORIZONTAL STABILIZER - PERFORM VISUAL INSPECTION OF HILITE COLLARS IN THE FOLLOWING AREAS: - FORWARD SPAR TO BL 0.0 RIB.- CENTER SPAR TO BL 0.0 RIB.- CENTER SPAR SPLICE PLATE.- AFT SPAR SPLICE PLATE.- ROOT RIBS AT BL 3.70 (RIGHT AND LEFT).- UPPER DOUBLER SPAR SPLICE, BL 0.0.- HSTA UPPER ATTACH FITTING STRUCTURE.							Service	ATA:55	
	MOS	11-Mar-22	48 (+14d/-14d)								
	HRS	8721.2	1200 (+25/-25)								
	AFL	7006									
PROC. REF: AMM 55-00-01										PKG:14	
Y5510094 ^S		LOWER BRACKET, HORIZONTAL STABILIZER TRIM ACTUATOR - PERFORM BORESCOPE INSPECTION OF HILITE COLLARS COMMON TO RIB # 6 AND MID SPAR							Service	ATA:55	
	MOS	11-Mar-22	48 (+14d/-14d)								
	HRS	8721.2	1200 (+25/-25)								
	AFL	7006									
PROC. REF: AMM 55-10-00										PKG:14	
Y5540012 ^S		RUDDER TORQUE TUBE - LOOSEN TORQUE TUBE BONDING CLAMP AND PERFORM DETAILED VISUAL INSPECTION OF AREA AROUND BONDING CLAMP FOR CORROSION. NOTE: PERFORM BONDING CHECK OF CLAMP AND BONDING JUMPERS AFTER REINSTALLATION OF CLAMP.							Service	ATA:55	
	MOS	25-Jan-24	12 (+14d/-14d)								
	HRS	9265.8	300 (+25/-25)								
	AFL	7395									
PROC. REF: AMM 27-20-01										PKG:2	
ATA 56 - WINDOWS											
5-19-00-W5600002		** WINDSHIELD - PERFORM RAIN REMOVAL COATING EFFECTIVENESS TEST (AWL**)							Service	ATA:56	
	MOS	25-Jan-24	12 (+14d/-14d)		25-Jan-25	08-Feb-25	71 d (+14)	AIRWORTHINESS			
	HRS	9265.8									
	AFL	7395									
PROC. REF: AMM 56-10-01, AMM 56-10-01											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 56 - WINDOWS										
561001	LEFT WINDSHIELD									Component ATA:56
PN:6656100001-001	MOS/MSC	28-Aug-23	O/C							
SN:1653	HRS	9158.1								
	AFL	7309								
PROC. REF: AMM 56-10-01, AMM 56-10-01										
561001A	* LEFT WINDSHIELD - PERFORM ULTRASONIC INSPECTION OF THE STRUCTURAL PLIES (IRN N5600003) (AWL*)									Service ATA:56
	MOS	11-Aug-22								
	HRS	8836.8	4800		13636.8		4121.1			
	AFL	7093								
PROC. REF: NDT PART 4/56-10-01										
561001B	* LEFT WINDSHIELD - PERFORM BOLT HOLE INSPECTION (IRN N5600012) (AWL*)									Service ATA:56
	MOS/MSC	28-Aug-23	N/A							
	HRS	9158.1								
	AFL	7309								
PROC. REF: AMM 56-10-01										
561002	RIGHT WINDSHIELD									Component ATA:56
PN:173600-24	MOS/MSC	16-Oct-24	O/C							
SN:2310	HRS	9492.6								
	AFL	7560								
PROC. REF: AMM 56-10-01, AMM 56-10-01										
561002A	* RIGHT WINDSHIELD - PERFORM ULTRASONIC INSPECTION OF THE STRUCTURAL PLIES (IRN N5600003) (AWL*)									Service ATA:56
	MOS/MSC	11-Aug-22	N/A							
	HRS	8836.8								
	AFL	7093								
PROC. REF: NDT PART 4/56-10-01										
561002B	* RIGHT WINDSHIELD - PERFORM BOLT HOLE INSPECTION (IRN N5600012) (AWL*)									Service ATA:56
	MOS	11-Aug-22								
	HRS	8836.8	4800		13636.8		4121.1			
	AFL	7093								
PROC. REF: AMM 56-10-01										
L5600010 ^S	* CABIN WINDOWS (INCLUDING THE EMERGENCY EXIT WINDOW) - PERFORM DETAILED VISUAL INSPECTION (AWL*)									Service ATA:56
	MOS	10-May-23						AIRWORTHINESS		
	HRS	9071.3	4800							
	AFL	7252								
PROC. REF: GENERIC NO REF										

PKG:25

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 56 - WINDOWS											
Y5600000 ^S			WINDSHIELDS - PERFORM VISUAL INSPECTION (INTERIOR AND EXTERIOR).						Service	ATA:56	
	MOS	25-Jan-24	12 (+14d/-14d)								
	HRS	9265.8	300 (+25/-25)								
	AFL	7395									
PROC. REF: GENERIC NO REF										PKG:1	
Y5600001 ^S			CABIN WINDOWS - PERFORM VISUAL INSPECTION.						Service	ATA:56	
	MOS	25-Jan-24	24 (+14d/-14d)								
	HRS	9265.8	600 (+25/-25)								
	AFL	7395									
PROC. REF: GENERIC NO REF										PKG:7	
Y5600013 ^S			WINDSHIELDS - PERFORM VISUAL INSPECTION OF THE AERODYNAMIC SEAL. NOTE: IF REPAIRS TO THE SEAL ARE NEEDED, REFER TO 56-10-01						Service	ATA:56	
	MOS	25-Jan-24	12 (+14d/-14d)								
	HRS	9265.8	300 (+25/-25)								
	AFL	7395									
PROC. REF: AMM 56-10-01, AMM 56-10-01										PKG:1	
ATA 57 - WINGS											
5-19-00-E5750051			* FLAP MAIN TRACK ROLLERS - PERFORM VISUAL INSPECTION WITH FLAPS REMOVED (IRN E5750051) (AWL*)						Service	ATA:57	
	MOS	10-May-05						AIRWORTHINESS			
	HRS	0	T:10000	10000			484.3				
	AFL	0									
PROC. REF: AMM 27-50-01											
5-19-00-E5750052			* FLAP NOSE ROLLERS - PERFORM VISUAL INSPECTION WITH THE FLAPS REMOVED (IRN E5750052) (AWL*)						Service	ATA:57	
	MOS	25-Jan-24						AIRWORTHINESS			
	HRS	9265.8	600	9865.8			350.1				
	AFL	7395									
PROC. REF: GENERIC NO REF											
5-19-00-N5710002			* WING BOX MID SPAR LOWER CAP, OUTBOARD OF JOINT AT WS 137 BETWEEN RIBS 7 AND 8 - PERFORM DIRECTED VISUAL INSPECTION. INSPECT MID SPAR LOWER CAP AND LOWER SKIN PANELS. (IRN N5710002) (AWL*)						Service	ATA:57	
	MOS	10-May-05						AIRWORTHINESS			
	HRS	0	T:9600	9600			84.3				
	AFL	0									
PROC. REF: GENERIC NO REF											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 57 - WINGS											
5-19-00-N5710008			* WING BOX MID SPAR LOWER CAP - PERFORM ULTRASONIC INSPECTION. INSPECT MID SPAR LOWER CAP AND LOWER SKIN PANELS BETWEEN WS 99 & WS 137 (IRN N5710008) (AWL*)							Service	ATA:57
	MOS	10-May-05						AIRWORTHINESS			
	HRS	0	T:9600		9600		84.3				
	AFL	0									
PROC. REF: NDT PART 4/57-30-03											
5-19-00-N5710009			* WING BOX MID SPAR LOWER CAP JOINT AT WS 137 - PERFORM XRAY INSPECTION. INSPECT MID SPAR CENTER/OUTER JOINT (IRN N5710009) (AWL*)							Service	ATA:57
	MOS	10-May-05						AIRWORTHINESS			
	HRS	0	T:9600		9600		84.3				
	AFL	0									
PROC. REF: NDT PART 2/57-10-02											
5-19-00-N5710010			* WING BOX REAR SPAR LOWER CAP INBOARD OF JOINT AT WS 81 - PERFORM ULTRASONIC INSPECTION. INSPECT REAR SPAR LOWER CAP BETWEEN SKIN TERMINATION AT WS 48 AND CLOSING RIB AT WS 60 (IRN N5710010) (AWL*)							Service	ATA:57
	MOS	10-May-05						AIRWORTHINESS			
	HRS	0	T:9600		9600		84.3				
	AFL	0									
PROC. REF: NDT PART 4/57-30-01											
5-19-00-N5710012			* WING BOX REAR SPAR LOWER CAP OUTBOARD OF JOINT AT WS 81 TO RIB 6 - PERFORM DETAILED VISUAL INSPECTION. INSPECT OUTER REAR SPAR LOWER CAP AND AFT LOWER SKIN PANEL OUTBOARD OF REAR SPLICE AT WS 90. (IRN N5710012) (AWL*)							Service	ATA:57
	MOS	10-May-05						AIRWORTHINESS			
	HRS	0	T:9600		9600		84.3				
	AFL	0									
PROC. REF: GENERIC NO REF											
5-19-00-N5710013			* WING BOX REAR SPAR LOWER CAP SKIN TERMINATION AT MS 48 - PERFORM EDDY CURRENT INSPECTION. INSPECT REAR SPAR LOWER CAP BETWEEN WS33 AND WS48. (AWL*)							Service	ATA:57
	MOS	10-May-05						AIRWORTHINESS			
	HRS	0	T:10000		10000		484.3				
	AFL	0									
PROC. REF: NDT PART 6/57-20-04											
5-19-00-N5710026			* WING BOX MID SPAR LOWER CAP - PERFORM NDI INSPECTION. INSPECT MID SPAR LOWER CAP OUTBOARD OF ROOT RIB AT WS 33 TO WS 99. (IRN N5710026) (AWL*)							Service	ATA:57
	MOS	10-May-05						AIRWORTHINESS			
	HRS	0	T:10000		10000		484.3				
	AFL	0									
PROC. REF: NDT PART 4/57-30-03											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 57 - WINGS											
5-19-00-N5710123			* WING BOX MID SPAR LOWER CAP - PERFORM EDDY CURRENT INSPECTION AT TRUNNION FITTING (IRN N5710123) (AWL*)							Service	ATA:57
	MOS	10-May-05						AIRWORTHINESS			
	HRS	0	T:9600		9600		84.3				
	AFL	0									
PROC. REF: NDT PART 6/57-10-01											
5-19-00-N5710174			* WING BOX REAR SPAR LOWER CAP SKIN TERMINATION AT MS 48 - PERFORM ULTRASONIC INSPECTION. INSPECT REAR SPAR LOWER CAP BETWEEN WS 33 AND WS 48 (AWL*)							Service	ATA:57
	MOS	10-May-05									
	HRS	0	T:10000		10000		484.3				
	AFL	0									
PROC. REF: NDT PART 4/57-30-04											
5-19-00-P5710172			* WING BOX MID SPAR LOWER CAP - PERFORM ULTRASONIC INSPECTION AT TRUNNION FITTING (AWL*)							Service	ATA:57
	MOS	10-May-05						AIRWORTHINESS			
	HRS	0	T:9600		9600		84.3				
	AFL	0									
PROC. REF: NDT PART 4/57-10-00											
5-19-01-A5760004-LEFT			LEFT * AILERON BOLTS * REPLACE LEFT AILERON BOLTS (IRN A5760004) (AWL*)							Service	ATA:57
	MOS	10-May-05									
	HRS	0	9600		9600		84.3				
	AFL	0									
PROC. REF: AMM 27-10-02											
5-19-01-A5760004-RIGHT			RIGHT * AILERON BOLTS * REPLACE RIGHT AILERON BOLTS (IRN A5760004) (AWL*)							Service	ATA:57
	MOS	10-May-05									
	HRS	0	9600		9600		84.3				
	AFL	0									
PROC. REF: AMM 27-10-02											
570001			WING ASSEMBLY							Component	ATA:57
PN:4557000004-001	MOS/MSC	10-May-05	O/C		TSN 0						
SN:144043600295	HRS	0			TSN 0						
	AFL	0			TSN 0						
PROC. REF: AMM 57-10-00											

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
571010	* REPLACE LEFT MAIN LANDING GEAR SIDE-STAY ACTUATOR FITTING (IRN N3220126) (AWL*)									Component ATA:57
PN:4532103041-009	MOS	22-Apr-08		TSN 0						
SN:NSN	HRS	2112.67		TSN 0						
	AFL	1713	20000	TSN 0	21713		14137			
PROC. REF: AMM 32-31-01										
571011	* REPLACE RIGHT MAIN LANDING GEAR SIDE-STAY ACTUATOR FITTING (IRN N3220126) (AWL*)									Component ATA:57
PN:4532103041-009	MOS	22-Apr-08		TSN 0						
SN:NSN	HRS	2112.67		TSN 0						
	AFL	1713	20000	TSN 0	21713		14137			
PROC. REF: AMM 32-31-01										
5710190	* LEFT WING CENTER SECTION (PANELS 510AC, 510BC, 510BL AND 610BR REMOVED AND PANELS 510AL, 610AR, 720BL, AND 730BR LOWERED) - PERFORM VISUAL INSPECTION. INSPECT STRUCTURE FOR CORROSION OR DETERIORATION OF PROTECTIVE TREATMENT.									Service ATA:57
	MOS	19-Feb-20	96 (+14d/-14d)	Adj 6d	25-Feb-28	10-Mar-28	1197 d (+14)			
	HRS	7875.4								
	AFL	6355								
PROC. REF: AMM 57-10-00										
5710190	* RIGHT WING CENTER SECTION (PANELS 510AC, 510BC, 510BL AND 610BR REMOVED AND PANELS 510AL, 610AR, 720BL, AND 730BR LOWERED) - PERFORM VISUAL INSPECTION. INSPECT STRUCTURE FOR CORROSION OR DETERIORATION OF PROTECTIVE TREATMENT.									Service ATA:57
	MOS	19-Feb-20	96 (+14d/-14d)	Adj 6d	25-Feb-28	10-Mar-28	1197 d (+14)			
	HRS	7875.4								
	AFL	6355								
PROC. REF: AMM 57-10-00										
573001	LEFT WINGLET ASSEMBLY									Component ATA:57
PN:4557300006-001/00	MOS/MSC	10-May-05	O/C	TSN 0						
SN:675845000295	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 57-30-01										
573002	RIGHT WINGLET ASSEMBLY									Component ATA:57
PN:4557300006-002/00	MOS/MSC	10-May-05	O/C	TSN 0						
SN:675547300295	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 57-30-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
574011	LEFT INBOARD LEADING EDGE ACCESS SECTION									Component ATA:57
PN:4557400005-037	MOS/MSC	10-May-05	O/C	TSN 0						
SN:675656500295	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 57-40-01										
574013	RIGHT INBOARD LEADING EDGE ACCESS SECTION									Component ATA:57
PN:4557400005-038	MOS/MSC	10-May-05	O/C	TSN 0						
SN:277549200295	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 57-40-01										
574039	LEFT OUTBOARD LEADING EDGE ACCESS SECTION									Component ATA:57
PN:4557400005-045	MOS/MSC	10-May-05	O/C	TSN 0						
SN:675673200295	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 57-40-01										
574041	RIGHT OUTBOARD LEADING EDGE ACCESS SECTION									Component ATA:57
PN:4557400005-044	MOS/MSC	10-May-05	O/C	TSN 0						
SN:220291600295	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 57-40-01										
574042	LEFT INBOARD LEADING EDGE									Component ATA:57
PN:4557400005-039	MOS/MSC	10-May-05	O/C	TSN 0						
SN:675658100295	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 57-40-01										
574043	RIGHT INBOARD LEADING EDGE									Component ATA:57
PN:4557400005-040	MOS/MSC	10-May-05	O/C	TSN 0						
SN:675660000295	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 57-40-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
574044	LEFT CENTER LEADING EDGE									Component ATA:57
PN:4557400005-041	MOS/MSC	10-May-05	O/C	TSN 0						
SN:675664700295	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 57-40-01										
574045	RIGHT CENTER LEADING EDGE									Component ATA:57
PN:4557400005-042	MOS/MSC	10-May-05	O/C	TSN 0						
SN:418499400295	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 57-40-01										
574046	LEFT OUTBOARD LEADING EDGE									Component ATA:57
PN:4557400005-043	MOS/MSC	10-May-05	O/C	TSN 0						
SN:473401600295	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 57-40-01										
574047	RIGHT OUTBOARD LEADING EDGE									Component ATA:57
PN:4557400005-046	MOS/MSC	10-May-05	O/C	TSN 0						
SN:219958200295	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 57-40-01										
575002	RIGHT FLAP ASSEMBLY									Component ATA:57
PN:4557500006-008	MOS/MSC	10-May-23	O/C	TSN 216						
SN:676081600295	HRS	9071.3		TSN 9071.3						
	AFL	7252		TSN 7252						
PROC. REF: AMM 57-50-01										
576001	LEFT AILERON ASSEMBLY									Component ATA:57
PN:4557600003-001	MOS/MSC	10-May-23	O/C	TSN 216						
SN:698914500299	HRS	9071.3		TSN 9071.3						
	AFL	7252		TSN 7252						
Special Properties: RII ITEM PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 57 - WINGS											
576002	RIGHT AILERON ASSEMBLY									Component ATA:57	
PN:4557600003-002	MOS/MSC	10-May-23	O/C	TSN 216							
SN:701682900299	HRS	9071.3	TSN 9071.3								
	AFL	7252	TSN 7252								
Special Properties: RII ITEM				PROC. REF: GENERIC NO REF							
577001	LEFT SPOILER ASSEMBLY									Component ATA:57	
PN:4557700003-021	MOS/MSC	10-May-23	O/C	TSN 216							
SN:0342	HRS	9071.3	TSN 9071.3								
	AFL	7252	TSN 7252								
				PROC. REF: AMM 57-70-01							
577002	RIGHT SPOILER ASSEMBLY									Component ATA:57	
PN:4557700003-022	MOS/MSC	10-May-23	O/C	TSN 216							
SN:0349	HRS	9071.3	TSN 9071.3								
	AFL	7252	TSN 7252								
				PROC. REF: AMM 57-70-01							
E5710005 ^S	* WING CENTER SECTION SPAR UPPER CAPS - PERFORM VISUAL INSPECTION. INSPECT FRONT, MID, AND REAR SPAR UPPER CAPS FROM CENTERLINE TO SKIN TERMINATION ATWS 33 (AWL*)									Service ATA:57	
	MOS	10-May-05								AIRWORTHINESS	
	HRS	0	9600								
	AFL	0									
				PROC. REF: GENERIC NO REF							PKG:26
E5710019 ^S	* WING BOX, UPPER SKIN, SKIN/STRINGER AND SPAR CAPS - PERFORM VISUAL INSPECTION. INSPECT UPPER WING SPAR CAPS, SKIN PANEL, AND STRINGERS OF OUTER WING. (AWL*)									Service ATA:57	
	MOS	10-May-05								AIRWORTHINESS	
	HRS	0	9600								
	AFL	0									
				PROC. REF: GENERIC NO REF							PKG:26
E5710020 ^S	* WING BOX RIBS - PERFORM VISUAL INSPECTION. INSPECT ALL WING BOX RIBS EXCEPT CLOSING RIB BETWEEN FRONT AND MID SPARS AND CLOSING RIB BETWEEN MID AND REAR SPAR (AWL*)									Service ATA:57	
	MOS	10-May-05								AIRWORTHINESS	
	HRS	0	9600								
	AFL	0									
				PROC. REF: GENERIC NO REF							PKG:26

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
E5760006 ^S					* AILERON BASIC STRUCTURE - PERFORM VISUAL INSPECTION. (AWL*)				Service	ATA:57
	MOS	10-May-05						AIRWORTHINESS		
	HRS	0	9600							
	AFL	0								
					PROC. REF: GENERIC NO REF					PKG:26
L5710124 ^S					* AILERON DRIVE SUPPORT - PERFORM ULTRASONIC INSPECTION. (AWL*)				Service	ATA:57
	MOS	10-May-23						AIRWORTHINESS		
	HRS	9071.3	4800							
	AFL	7252								
					PROC. REF: NDT PART 4/27-10-01					PKG:25
N5710004 ^S					* WING CENTER SECTION REAR SPAR - PERFORM EDDY CURRENT INSPECTION. INSPECT REAR SPAR LOWER CAP FROM CENTERLINE TO WS 33. (AWL*)				Service	ATA:57
	MOS	10-May-23						AIRWORTHINESS		
	HRS	9071.3	4800							
	AFL	7252								
					PROC. REF: NDT PART 6/57-20-02					PKG:25
N5710006 ^S					* WING CENTER SECTION FORWARD AND AFT RIBS AT WS 6 AND FORWARD RIBS AT WS 17 - PERFORM EDDY CURRENT INSPECTION. (AWL*)				Service	ATA:57
	MOS	10-May-23						AIRWORTHINESS		
	HRS	9071.3	4800							
	AFL	7252								
					PROC. REF: NDT PART 6/57-10-06					PKG:25
N5710011 ^S					* WING BOX REAR SPAR LOWER CAP JOINT AT WS 81 - PERFORM X-RAY INSPECTION. (AWL*)				Service	ATA:57
	MOS	10-May-23	96					AIRWORTHINESS		
	HRS	9071.3	2400							
	AFL	7252								
					PROC. REF: NDT PART 2/57-10-03					PKG:22
N5710014 ^S					* WING BOX REAR SPAR FLAP TRACK CUTOUTS - PERFORM EDDY CURRENT INSPECTION. INSPECT FLAP TRACK CUTOUTS AT WS 65, WS 126, AND WS 184 ON REAR SPAR. (AWL*)				Service	ATA:57
	MOS	10-May-23						AIRWORTHINESS		
	HRS	9071.3	4800							
	AFL	7252								
					PROC. REF: NDT PART 6/57-20-01					PKG:25

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 57 - WINGS											
N5710016 ^S			* WING BOX BASIC SKIN/STRINGER, LOWER SKIN - PERFORM VISUAL INSPECTION. INSPECT OUTBOARD WING FORWARD AND AFT LOWER SKIN PANELS AND STRINGERS (AWL*)						Service	ATA:57	
	MOS	10-May-23						AIRWORTHINESS			
	HRS	9071.3	4800								
	AFL	7252									
					PROC. REF: GENERIC NO REF						PKG:25
N5710017 ^S			* WING BOX BASIC SKIN/STRINGER AT STRINGER RUN-OUT, LOWER SKIN - PERFORM VISUAL INSPECTION. INSPECT STRINGER RUN-OUTS IN FORWARD AND AFT LOWER SKIN PANELS. (AWL*)						Service	ATA:57	
	MOS	10-May-05						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
					PROC. REF: GENERIC NO REF						PKG:26
N5710021 ^S			* CENTER SECTION MID SPAR LOWER CAP - PERFORM EDDY CURRENT INSPECTION. (AWL*)						Service	ATA:57	
	MOS	10-May-23	96					AIRWORTHINESS			
	HRS	9071.3	2400								
	AFL	7252									
					PROC. REF: NDT PART 6/57-10-02						PKG:22
N5710022 ^S			* CENTER SECTION MID SPAR CENTERLINE JOINT - PERFORM EDDY CURRENT INSPECTION. (AWL*)						Service	ATA:57	
	MOS	10-May-23	96					AIRWORTHINESS			
	HRS	9071.3	2400								
	AFL	7252									
					PROC. REF: NDT PART 6/57-10-08, NDT PART 6/57-10-10						PKG:22
N5710023 ^S			* CENTER SECTION FRONT SPAR LOWER CAP - PERFORM EDDY CURRENT INSPECTION. (AWL*)						Service	ATA:57	
	MOS	10-May-23	96					AIRWORTHINESS			
	HRS	9071.3	2400								
	AFL	7252									
					PROC. REF: NDT PART 6/57-10-03						PKG:22
N5710028 ^S			* WING BOX MID SPAR LOWER CAP, SKIN TERMINATION AT WS 33 - BOLT HOLE - PERFORM EDDY CURRENT INSPECTION. INSPECT MID SPAR LOWER CAP UNDERNEATH ROOT RIB (WS 33) AT POINT OF SKIN TERMINATION. (AWL*)						Service	ATA:57	
	MOS	10-May-23						AIRWORTHINESS			
	HRS	9071.3	4800								
	AFL	7252									
					PROC. REF: NDT PART 6/57-10-11						PKG:25

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 57 - WINGS											
N5710031 ^S			PERFORM * WING BOX SKIN ACCESS COVER HOLES - EDDY CURRENT INSPECTION. INSPECT ACCESS HOLES IN FORWARD AND AFT LOWER SKIN PANELS. (AWL*)						Service	ATA:57	
	MOS	10-May-23						AIRWORTHINESS			
	HRS	9071.3	4800								
	AFL	7252									
					PROC. REF: NDT PART 6/57-30-01						PKG:25
N5710037 ^S			* WING BOX FRONT SPAR LOWER CAP - PERFORM VISUAL INSPECTION. INSPECT FRONT SPAR LOWER CAP AND LOWER FORWARD SKIN OUTBOARD OF MID-SPAR STATION (MS) 55. (AWL*)						Service	ATA:57	
	MOS	10-May-23	96					AIRWORTHINESS			
	HRS	9071.3	2400								
	AFL	7252									
					PROC. REF: GENERIC NO REF						PKG:22
N5710084 ^S			SPOILER, CENTER HINGE SPOILER SIDE - PERFORM NDI INSPECTION						Service	ATA:57	
	MOS	10-May-23	96 (+14d/-14d)								
	HRS	9071.3	2400 (+25/-25)								
	AFL	7252									
					PROC. REF: NDT PART 6/57-40-01						PKG:22
N5710121 ^S			* WING BOX MID SPAR, OUTBOARD OF RIB 8 - PERFORM VISUAL INSPECTION AT WS 156 AND OUTBOARD TO WS 260 (AWL*)						Service	ATA:57	
	MOS	10-May-23						AIRWORTHINESS			
	HRS	9071.3	4800								
	AFL	7252									
					PROC. REF: GENERIC NO REF						PKG:25
N5710122 ^S			* WING BOX REAR SPAR, OUTBOARD OF RIB 6 - PERFORM VISUAL INSPECTION AT WS 118 AND OUTBOARD TO WS 260. (AWL*)						Service	ATA:57	
	MOS	10-May-23						AIRWORTHINESS			
	HRS	9071.3	4800								
	AFL	7252									
					PROC. REF: GENERIC NO REF						PKG:25
N5710137 ^S			* MID SPAR AT RIB 2 NEAR WS 48 - PERFORM BOLT HOLE EDDY CURRENT INSPECTION. (AWL*)						Service	ATA:57	
	MOS	10-May-23						AIRWORTHINESS			
	HRS	9071.3	4800								
	AFL	7252									
					PROC. REF: NDT PART 6/57-10-11A						PKG:25
N5710138 ^S			* MID SPAR AT RIB 3 NEAR WS 60 - PERFORM BOLT HOLE EDDY CURRENT INSPECTION. (AWL*)						Service	ATA:57	
	MOS	10-May-23						AIRWORTHINESS			
	HRS	9071.3	4800								
	AFL	7252									
					PROC. REF: NDT PART 6/57-10-11A						PKG:25

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
N5710139 ^S					* FORWARD FLANGE FASTENERS AT REAR SPAR BETWEEN WS 52 AND WS 60 - PERFORM BOLT HOLE EDDY CURRENT INSPECTION. (AWL*)				Service	ATA:57
	MOS	10-May-23	96					AIRWORTHINESS		
	HRS	9071.3	2400							
	AFL	7252								
					PROC. REF: NDT PART 6/57-20-03					PKG:22
N5710176 ^S					* WING MID-SPAR (CENTER SECTION) LOWER CAP AND CENTER-JOINT FITTING - PERFORM ULTRASONIC INSPECTION. (AWL*)				Service	ATA:57
	MOS	10-May-23	96					AIRWORTHINESS		
	HRS	9071.3	2400							
	AFL	7252								
					PROC. REF: NDT PART 4/57-30-05					PKG:22
N5750005 ^S					* FLAP MAIN TRACK HINGE FITTINGS, TRACK, AND FLAP BOX SIDES - PERFORM VISUAL INSPECTION. INSPECT MAIN TRACK HINGE FITTINGS ON TRACK AND FLAP BOX SIDES. (AWL*)				Service	ATA:57
	MOS	10-May-23	96					AIRWORTHINESS		
	HRS	9071.3	2400							
	AFL	7252								
					PROC. REF: GENERIC NO REF					PKG:22
P5710001 ^S					* WING DRAG LINK ATTACH FITTING - PERFORM MAGNETIC PARTICLE INSPECTION (AWL*)				Service	ATA:57
	MOS	10-May-23	96					AIRWORTHINESS		
	HRS	9071.3	2400							
	AFL	7252								
					PROC. REF: NDT PART 7/57-30-02					PKG:22
P5710007 ^S					* WING TO FUSELAGE ATTACH FITTINGS AND LINKS - PERFORM EDDY CURRENT INSPECTION (AWL*)				Service	ATA:57
	MOS	10-May-23						AIRWORTHINESS		
	HRS	9071.3	4800							
	AFL	7252								
					PROC. REF: NDT PART 6/57-10-12					PKG:25
P5710015 ^S					* WING REAR SPAR AT AILERON HINGE - PERFORM EDDY CURRENT INSPECTION (AWL*)				Service	ATA:57
	MOS	10-May-23						AIRWORTHINESS		
	HRS	9071.3	4800							
	AFL	7252								
					PROC. REF: NDT PART 6/57-10-20					PKG:25
P5710018 ^S					* WING LOWER SKIN AT MID-SPAR SPAN-WISE JOINT - PERFORM EDDY CURRENT INSPECTION (AWL*)				Service	ATA:57
	MOS	10-May-05						AIRWORTHINESS		
	HRS	0	9600							
	AFL	0								
					PROC. REF: NDT PART 6/57-10-09					PKG:26

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 57 - WINGS											
P5710024 ^S			* WING REAR-SPAR SIDE-STAY-FITTING SUPPORT STRUCTURE - PERFORM EDDY CURRENT INSPECTION (AWL*)							Service	ATA:57
	MOS	10-May-23						AIRWORTHINESS			
	HRS	9071.3	4800								
	AFL	7252									
						PROC. REF: NDT PART 6/57-20-06					
PKG:25											
P5710025 ^S			* WING FRONT SPAR LOWER CAP FROM WS 33.0 TO WS 60.0 - PERFORM RADIOGRAPHIC INSPECTION (AWL*)							Service	ATA:57
	MOS	10-May-23	96					AIRWORTHINESS			
	HRS	9071.3	2400								
	AFL	7252									
						PROC. REF: NDT PART 2/57-10-01					
PKG:22											
P5710029 ^S			* WING MID-SPAR VERTICAL WEB - PERFORM EDDY CURRENT INSPECTION (AWL*)							Service	ATA:57
	MOS	10-May-05						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
						PROC. REF: NDT PART 6/57-10-07					
PKG:26											
P5710030 ^S			* WING REAR SPAR VERTICAL WEB - PERFORM EDDY CURRENT INSPECTION (AWL*)							Service	ATA:57
	MOS	10-May-05						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
						PROC. REF: NDT PART 6/57-20-05					
PKG:26											
P5710032 ^S			* WING RIB UPPER-AFT-FLANGE FILLET RADIUS AT WS 33.0 - PERFORM ULTRASONIC INSPECTION (AWL*)							Service	ATA:57
	MOS	10-May-23						AIRWORTHINESS			
	HRS	9071.3	4800								
	AFL	7252									
						PROC. REF: NDT PART 4/57-30-02					
PKG:25											
P5710033 ^S			* WING ACCESS HOLE IN CLOSING RIB BETWEEN MID SPAR AND REAR SPAR - PERFORM EDDY CURRENT INSPECTION (AWL*)							Service	ATA:57
	MOS	10-May-23						AIRWORTHINESS			
	HRS	9071.3	4800								
	AFL	7252									
						PROC. REF: NDT PART 6/57-10-05					
PKG:25											
P5710034 ^S			* WING BOX JOINT TO WINGLET - PERFORM EDDY CURRENT INSPECTION (AWL*)							Service	ATA:57
	MOS	10-May-23						AIRWORTHINESS			
	HRS	9071.3	4800								
	AFL	7252									
						PROC. REF: NDT PART 6/57-10-13					
PKG:25											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 57 - WINGS											
P5710035 ^S			* WING LOWER SKIN AT DRAIN HOLE - PERFORM EDDY CURRENT INSPECTION (AWL*)							Service	ATA:57
	MOS	10-May-23						AIRWORTHINESS			
	HRS	9071.3	4800								
	AFL	7252									
PROC. REF: NDT PART 6/57-30-02										PKG:25	
P5710083 ^S			* FLAP BOX BASIC STRUCTURE - PERFORM EDDY CURRENT INSPECTION (AWL*)							Service	ATA:57
	MOS	10-May-23						AIRWORTHINESS			
	HRS	9071.3	4800								
	AFL	7252									
PROC. REF: NDT PART 6/57-40-02										PKG:25	
P5710085 ^S			SPOILER UPPER SKIN - PERFORM EDDY CURRENT INSPECTION							Service	ATA:57
	MOS	10-May-23									
	HRS	9071.3	4800 (+25/-25)								
	AFL	7252									
PROC. REF: NDT PART 6/57-10-16										PKG:25	
P5710086 ^S			SPOILER BOLTS AND HINGE PINS - PERFORM MAGNETIC PARTICLE INSPECTION							Service	ATA:57
	MOS	10-May-23									
	HRS	9071.3	4800 (+25/-25)								
	AFL	7252									
PROC. REF: NDT PART 7/27-10-01										PKG:25	
P5710181 ^S			* WING DRAG LINK TUBE - PERFORM MAGNETIC PARTICLE INSPECTION (AWL*)							Service	ATA:57
	MOS	10-May-23	96					AIRWORTHINESS			
	HRS	9071.3	2400								
	AFL	7252									
PROC. REF: NDT PART 7/57-30-01										PKG:22	
P5710182 ^S			* WING DRAG LINK ATTACH BOLTS - PERFORM LIQUID PENETRANT INSPECTION (AWL*)							Service	ATA:57
	MOS	10-May-23	96					AIRWORTHINESS			
	HRS	9071.3	2400								
	AFL	7252									
PROC. REF: NDT PART 8/57-10-01										PKG:22	
P5710183 ^S			* WING DRAG-LINK CLEVIS - PERFORM MAGNETIC PARTICLE INSPECTION (AWL*)							Service	ATA:57
	MOS	10-May-23	96					AIRWORTHINESS			
	HRS	9071.3	2400								
	AFL	7252									
PROC. REF: NDT PART 7/57-10-01										PKG:22	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 57 - WINGS											
P5710184 ^S			* WING ATTACH BOLTS - PERFORM FLUORESCENT PENETRANT INSPECTION (AWL*)							Service	ATA:57
	MOS	10-May-23						AIRWORTHINESS			
	HRS	9071.3	4800								
	AFL	7252									
PROC. REF: NDT PART 8/57-10-02										PKG:25	
P5710185 ^S			* WING ATTACH LINKS - PERFORM MAGNETIC PARTICLE INSPECTION (AWL*)							Service	ATA:57
	MOS	10-May-23						AIRWORTHINESS			
	HRS	9071.3	4800								
	AFL	7252									
PROC. REF: NDT PART 7/57-10-03										PKG:25	
P5710186 ^S			* WING ATTACH FITTINGS AT MID SPAR AND REAR SPAR - PERFORM MAGNETIC PARTICLE INSPECTION (AWL*)							Service	ATA:57
	MOS	10-May-23						AIRWORTHINESS			
	HRS	9071.3	4800								
	AFL	7252									
PROC. REF: NDT PART 7/57-10-02										PKG:25	
P5750002 ^S			* FLAP FRONT-SPAR CUTOUTS - PERFORM EDDY CURRENT INSPECTION (AWL*)							Service	ATA:57
	MOS	10-May-23	96					AIRWORTHINESS			
	HRS	9071.3	2400								
	AFL	7252									
PROC. REF: NDT PART 6/57-10-15										PKG:22	
P5750003 ^S			* FLAP NOSE-ROLLER RIBS - PERFORM EDDY CURRENT INSPECTION (AWL*)							Service	ATA:57
	MOS	10-May-23						AIRWORTHINESS			
	HRS	9071.3	4800								
	AFL	7252									
PROC. REF: NDT PART 6/57-10-14										PKG:25	
P5750004 ^S			* FLAP ACTUATOR SUPPORT RIBS - PERFORM EDDY CURRENT INSPECTION (AWL*)							Service	ATA:57
	MOS	10-May-05						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
PROC. REF: NDT PART 6/57-10-21										PKG:26	
P5750048 ^S			* FLAP TRACKS - PERFORM MAGNETIC PARTICLE INSPECTION (AWL*)							Service	ATA:57
	MOS	10-May-05						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
PROC. REF: NDT PART 7/57-71-01										PKG:26	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 57 - WINGS											
P5750049 ^S			* FLAP NOSE ROLLER TRACKS - PERFORM MAGNETIC PARTICLE INSPECTION WITH FLAPS REMOVED (AWL*)								Service ATA:57
	MOS	10-May-05						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
					PROC. REF: NDT PART 7/57-10-04					PKG:26	
P5750053 ^S			* FLAP TRACK SUPPORT RIBS - PERFORM EDDY CURRENT INSPECTION (AWL*)								Service ATA:57
	MOS	10-May-05						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
					PROC. REF: NDT PART 6/57-10-17					PKG:26	
P5750068 ^S			* FLAP FRONT-SPAR RIB SUPPORT STRUCTURE - PERFORM EDDY CURRENT INSPECTION (AWL*)								Service ATA:57
	MOS	10-May-23						AIRWORTHINESS			
	HRS	9071.3	4800								
	AFL	7252									
					PROC. REF: NDT PART 6/57-10-26					PKG:25	
P5760000 ^S			* AILERON ACTUATOR HINGE FITTING - PERFORM EDDY CURRENT INSPECTION (AWL*)								Service ATA:57
	MOS	10-May-05						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
					PROC. REF: NDT PART 6/57-10-25					PKG:26	
P5760001 ^S			* AILERON SKIN -PERFORM EDDY CURRENT INSPECTION (AWL*)								Service ATA:57
	MOS	10-May-05						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
					PROC. REF: NDT PART 6/57-10-19					PKG:26	
P5760002 ^S			* AILERON BALANCE TAB HINGE FITTINGS - PERFORM EDDY CURRENT INSPECTION (AWL*)								Service ATA:57
	MOS	10-May-23	96					AIRWORTHINESS			
	HRS	9071.3	2400								
	AFL	7252									
					PROC. REF: GENERIC NO REF					PKG:22	
P5760003 ^S			* AILERON TRIM AND BALANCE TAB FRONT SPARS - PERFORM RADIOGRAPHIC INSPECTION (AWL*)								Service ATA:57
	MOS	10-May-23						AIRWORTHINESS			
	HRS	9071.3	4800								
	AFL	7252									
					PROC. REF: NDT PART 2/57-60-01					PKG:25	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 57 - WINGS											
P5760005 ^S			* AILERON HINGE LUGS AND FITTINGS - PERFORM EDDY CURRENT INSPECTION (AWL*)							Service	ATA:57
	MOS	10-May-05						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
PROC. REF: NDT PART 6/57-10-24										PKG:26	
P5760014 ^S			* AILERON HINGE SUPPORT STRUCTURE - PERFORM EDDY CURRENT INSPECTION (AWL*)							Service	ATA:57
	MOS	10-May-05						AIRWORTHINESS			
	HRS	0	9600								
	AFL	0									
PROC. REF: NDT PART 6/57-10-23										PKG:26	
P5770000 ^S			SPOILER HINGE ASSEMBLIES AND ACTUATOR FITTING - PERFORM EDDY CURRENT INSPECTION							Service	ATA:57
	MOS	10-May-23									
	HRS	9071.3	4800 (+25/-25)								
	AFL	7252									
PROC. REF: NDT PART 6/57-10-22										PKG:25	
V5710039 ^S			WINGLET SKIN - PERFORM EDDY CURRENT INSPECTION.							Service	ATA:57
	MOS	10-May-23						AIRWORTHINESS			
	HRS	9071.3	4800 (+25/-25)								
	AFL	7252									
PROC. REF: GENERIC NO REF										PKG:25	
Y5700001 ^S			WINGLET - PERFORM VISUAL INSPECTION							Service	ATA:57
	MOS	25-Jan-24	12 (+14d/-14d)								
	HRS	9265.8	300 (+25/-25)								
	AFL	7395									
PROC. REF: GENERIC NO REF										PKG:4	
Y5710000 ^S			WING - PERFORM EXTERNAL VISUAL INSPECTION FROM BL 0.00 TO WS 260.							Service	ATA:57
	MOS	11-Mar-22	48 (+14d/-14d)								
	HRS	8721.2	1200 (+25/-25)								
	AFL	7006									
PROC. REF: GENERIC NO REF										PKG:16	
Y5710180 ^S			EXTERNAL LOWER WING SKIN - PERFORM VISUAL INSPECTION.							Service	ATA:57
	MOS	25-Jan-24	24 (+14d/-14d)								
	HRS	9265.8	600 (+25/-25)								
	AFL	7395									
PROC. REF: GENERIC NO REF										PKG:10	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
Y5730013 ^S	AILERON BRUSH SEALS - PERFORM DETAILED INSPECTION									Service ATA:57
	MOS	25-Jan-24	12 (+14d/-14d)							
	HRS	9265.8	300 (+25/-25)							
	AFL	7395								
PROC. REF: AMM 57-60-01										PKG:4
Y5750067 ^S	FLAP BRACKETS (P/N A159019-1 AND A159022-1) - PERFORM DETAILED VISUAL INSPECTION.									Service ATA:57
	MOS	10-May-23	96 (+14d/-14d)							
	HRS	9071.3	2400 (+25/-25)							
	AFL	7252								
PROC. REF: GENERIC NO REF										PKG:22
Y5750069 ^S	FLAPS - PERFORM VISUAL INSPECTION OF FLAP NOSE ROLLERS, FLAP TRACKS, FLAP NOSE ROLLER TRACKS, AND FLAP MAIN TRACK ROLLERS									Service ATA:57
	MOS	25-Jan-24	12 (+14d/-14d)							
	HRS	9265.8	300 (+25/-25)							
	AFL	7395								
PROC. REF: GENERIC NO REF										PKG:4
Y5750071 ^S	FLAPS - WITH FLAPS REMOVED, PERFORM DETAILED VISUAL INSPECTION OF FLAP NOSE ROLLERS, FLAP TRACKS, FLAP NOSE ROLLER TRACKS, AND FLAP MAIN TRACK ROLLERS.									Service ATA:57
	MOS	11-Mar-22	48 (+14d/-14d)							
	HRS	8721.2	1200 (+25/-25)							
	AFL	7006								
PROC. REF: GENERIC NO REF										PKG:16
ATA 71 - POWER PLANT										
5-19-00-Q7110004-LEFT	NO. 1 ENGINE INLET - PERFORM TAP TEST									Service ATA:71
	MOS	10-May-23								
	HRS	9071.3	3500 (+100/-100)		12571.3	12671.3	3055.6 (+100)			
	AFL	7252								
PROC. REF: AMM 71-10-01										
5-19-00-Q7110004-RIGHT	NO. 2 ENGINE INLET - PERFORM TAP TEST									Service ATA:71
	MOS	10-May-23								
	HRS	9071.3	3500 (+100/-100)		12571.3	12671.3	3055.6 (+100)			
	AFL	7252								
PROC. REF: AMM 71-10-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 71 - POWER PLANT										
5-19-00-R7100032	LEFT ENGINE NACELLE TUBES - PERFORM DETAILED VISUAL INSPECTION									Service ATA:71
	MOS/MSC		-					NOT APPLICABLE		
	HRS									
	AFL									
PROC. REF: AMM 71-10-03										
5-19-01-V7120074L	*REPLACE LEFT AFT ENGINE MOUNT BOLT (P/N 4571408525-001) (IRN V7120074) (AWL*)									Service ATA:71
	MOS/MSC	10-May-05	E/C					AIRWORTHINESS		
	HRS	0								
	AFL	0								
PROC. REF: AMM 71-20-00										
5-19-01-V7120074R	*REPLACE RIGHT AFT ENGINE MOUNT BOLT (P/N 4571408525-001) (IRN V7120074) (AWL*)									Service ATA:71
	MOS/MSC	10-May-05	E/C					AIRWORTHINESS		
	HRS	0								
	AFL	0								
PROC. REF: AMM 71-20-00										
710100	NO. 1 ENGINE - MAIN ENGINE WIRING HARNESS ASSEMBLY									Component ATA:71
PN:PN	MOS/MSC	25-Jan-05	O/C		TSN 0					
SN:UNKNOWN	HRS	0			TSN 0					
	ENC	0			TSN 0					
PROC. REF: LMM 72-00-02, LMM 72-00-02										
710100	NO. 2 ENGINE - MAIN ENGINE WIRING HARNESS ASSEMBLY									Component ATA:71
PN:PN	MOS/MSC	26-Jan-05	O/C		TSN 0					
SN:UNKNOWN	HRS	0			TSN 0					
	ENC	0			TSN 0					
PROC. REF: LMM 72-00-02, LMM 72-00-02										
710130 ^S	NO. 1 ENGINE - INSPECT TAILPIPE/LPT3 ROTOR ASSEMBLY-VISUALLY INSPECT FOR FOREIGN OBJECT DAMAGE, THERMAL DISTRESS, AND LEAKS.									Service ATA:71
	MOS	03-Jan-24								
	HRS	9174	850 (-350)							
	ENC	7357								
PROC. REF: LMM 72-00-00										
710130 ^S	NO. 2 ENGINE - INSPECT TAILPIPE/LPT3 ROTOR ASSEMBLY-VISUALLY INSPECT FOR FOREIGN OBJECT DAMAGE, THERMAL DISTRESS, AND LEAKS.									Service ATA:71
	MOS	03-Jan-24								
	HRS	9174	850 (-350)							
	ENC	7357								
PROC. REF: LMM 72-00-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 71 - POWER PLANT											
710140 ^S			NO. 1 ENGINE - INSPECT INLET/FAN AREA - INSPECT FOR FOREIGN OBJECT DAMAGE AND LEAKAGE (REFER TO PARAGRAPH 4.B)							Service	ATA:71
	MOS		03-Jan-24								
	HRS		9174		850 (-350)						
	ENC		7357								
PROC. REF: LMM 72-00-00, LMM 72-00-00										PKG:0	
710140 ^S			NO. 2 ENGINE - INSPECT INLET/FAN AREA - INSPECT FOR FOREIGN OBJECT DAMAGE AND LEAKAGE (REFER TO PARAGRAPH 4.B)							Service	ATA:71
	MOS		03-Jan-24								
	HRS		9174		850 (-350)						
	ENC		7357								
PROC. REF: LMM 72-00-00, LMM 72-00-00										PKG:0	
711001			NO. 1 ENGINE FORWARD MOUNT							Component	ATA:71
PN:4571200011-003	MOS/MSC		07-Dec-09	O/C							
SN:CDF1248	HRS		3096.38								
	AFL		2562								
PROC. REF: AMM 71-20-00											
711002			NO. 2 ENGINE FORWARD MOUNT							Component	ATA:71
PN:4571200011-003	MOS/MSC		10-May-05	O/C	TSN 0						
SN:CDF660	HRS		0		TSN 0						
	AFL		0		TSN 0						
PROC. REF: AMM 71-20-00											
7120004 ^S			REPLACE NO. 1 ENGINE AFT ENGINE MOUNT ISOLATOR HOUSING							Component	ATA:71
PN:PN	MOS		10-May-05		TSN 0			LIFE LIMIT			
SN:UNKNOWN	HRS		0		15000 (+25/-25)	TSN 0					
	AFL		0		TSN 0						
PROC. REF: AMM 71-20-00											
7120004			REPLACE NO. 1 ENGINE ALL ENGINE MOUNT ISOLATOR HOUSINGS							Component	ATA:71
	MOS		10-May-05					LIFE LIMIT			
	HRS		0		15000 (+25/-25)	15000	15025	5484.3 (+25)			
	AFL		0								
PROC. REF: AMM 71-20-00											
7120004 ^S			REPLACE NO. 1 ENGINE FORWARD LOWER ENGINE MOUNT ISOLATOR HOUSING							Component	ATA:71
PN:PN	MOS		10-May-05		TSN 0			LIFE LIMIT			
SN:UNKNOWN	HRS		0		15000 (+25/-25)	TSN 0					
	AFL		0		TSN 0						
PROC. REF: AMM 71-20-00											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 71 - POWER PLANT										
7120004 ^S REPLACE NO. 1 ENGINE FORWARD UPPER ENGINE MOUNT ISOLATOR HOUSING Component ATA:71										
PN:PN	MOS	10-May-05		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0	15000 (+25/-25)	TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										
7120004 ^S REPLACE NO. 2 ENGINE AFT ENGINE MOUNT ISOLATOR HOUSING Component ATA:71										
PN:PN	MOS	10-May-05		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0	15000 (+25/-25)	TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										
7120004 REPLACE NO. 2 ENGINE ALL ENGINE MOUNT ISOLATOR HOUSINGS Component ATA:71										
	MOS	10-May-05						LIFE LIMIT		
	HRS	0	15000 (+25/-25)		15000	15025	5484.3 (+25)			
	AFL	0								
PROC. REF: AMM 71-20-00										
7120004 ^S REPLACE NO. 2 ENGINE FORWARD LOWER ENGINE MOUNT ISOLATOR HOUSING Component ATA:71										
PN:PN	MOS	10-May-05		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0	15000 (+25/-25)	TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										
7120004 ^S REPLACE NO. 2 ENGINE FORWARD UPPER ENGINE MOUNT ISOLATOR HOUSING Component ATA:71										
PN:PN	MOS	10-May-05		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0	15000 (+25/-25)	TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										
7120005 ^S REPLACE NO. 1 ENGINE AFT ENGINE MOUNT ISOLATOR FORWARD BONDED MOUNTING Component ATA:71										
PN:PN	MOS	10-May-05		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0	5000 (+100/-100)	TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										
7120005 REPLACE NO. 1 ENGINE ALL ENGINE MOUNT ISOLATOR BONDED MOUNTING Component ATA:71										
	MOS/MS	10-May-05	N/A							
	HRS	0								
	AFL	0								
PROC. REF: AMM 71-20-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 71 - POWER PLANT										
7120005 ^S REPLACE NO. 1 ENGINE FORWARD LOWER ENGINE MOUNT ISOLATOR BONDED MOUNTING Component ATA:71										
PN:PN	MOS	10-May-05		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0	5000 (+100/-100)	TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										
7120005 ^S REPLACE NO. 1 ENGINE FORWARD UPPER ENGINE MOUNT ISOLATOR BONDED MOUNTING Component ATA:71										
PN:PN	MOS	10-May-05		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0	5000 (+100/-100)	TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										
7120005 ^S REPLACE NO. 2 ENGINE AFT ENGINE MOUNT ISOLATOR BONDED MOUNTING Component ATA:71										
PN:PN	MOS	10-May-05		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0	5000 (+100/-100)	TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										
7120005 REPLACE NO. 2 ENGINE ALL ENGINE MOUNT ISOLATOR BONDED MOUNTING Component ATA:71										
	MOS/MSC	10-May-05	N/A							
	HRS	0								
	AFL	0								
PROC. REF: AMM 71-20-00										
7120005 ^S REPLACE NO. 2 ENGINE FORWARD LOWER ENGINE MOUNT ISOLATOR BONDED MOUNTING Component ATA:71										
PN:PN	MOS	10-May-05		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0	5000 (+100/-100)	TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										
7120005 ^S REPLACE NO. 2 ENGINE FORWARD UPPER ENGINE MOUNT ISOLATOR BONDED MOUNTING Component ATA:71										
PN:PN	MOS	10-May-05		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0	5000 (+100/-100)	TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										
7120006 ^S REPLACE NO. 1 ENGINE AFT ENGINE MOUNT ISOLATOR FORWARD BONDED MOUNTING Component ATA:71										
PN:PN	MOS	10-May-05		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0	3500 (+100/-100)	TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 71 - POWER PLANT										
7120006 REPLACE NO. 1 ENGINE ALL ENGINE MOUNT ISOLATOR FORWARD BONDED MOUNTING Component ATA:71										
PN:PN	MOS	10-May-05		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0	3500 (+100/-100)	TSN 0	9491.87 (M)	9591.87	TOL (+76.2)			
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										
7120006 ^S REPLACE NO. 1 ENGINE FORWARD LOWER ENGINE MOUNT ISOLATOR BONDED MOUNTING Component ATA:71										
PN:PN	MOS	10-May-05		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0	3500 (+100/-100)	TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										
7120006 ^S REPLACE NO. 1 ENGINE FORWARD UPPER ENGINE MOUNT ISOLATOR BONDED MOUNTING Component ATA:71										
PN:PN	MOS	10-May-05		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0	3500 (+100/-100)	TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										
7120006 ^S REPLACE NO. 2 ENGINE AFT ENGINE MOUNT ISOLATOR BONDED MOUNTING Component ATA:71										
PN:PN	MOS	10-May-05		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0	3500 (+100/-100)	TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										
7120006 REPLACE NO. 2 ENGINE ALL ENGINE MOUNT ISOLATOR FORWARD BONDED MOUNTING Component ATA:71										
PN:PN	MOS	10-May-05		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0	3500 (+100/-100)	TSN 0	9491.87 (M)	9591.87	TOL (+76.2)			
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										
7120006 ^S REPLACE NO. 2 ENGINE FORWARD LOWER ENGINE MOUNT ISOLATOR BONDED MOUNTING Component ATA:71										
PN:PN	MOS	10-May-05		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0	3500 (+100/-100)	TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										
7120006 ^S REPLACE NO. 2 ENGINE FORWARD UPPER ENGINE MOUNT ISOLATOR BONDED MOUNTING Component ATA:71										
PN:PN	MOS	10-May-05		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0	3500 (+100/-100)	TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 71 - POWER PLANT										
712005	NO. 1 ENGINE AFT MOUNT ISOLATOR ASSEMBLY									Component ATA:71
PN:LM-833-SA18	MOS/MSC	07-Feb-14	O/C							
SN:LK2048	HRS	5991.87								
	AFL	4884								
PROC. REF: AMM 71-20-00										
712006	NO. 2 ENGINE AFT MOUNT ISOLATOR ASSEMBLY									Component ATA:71
PN:LM-833-SA18	MOS/MSC	07-Feb-14	O/C							
SN:LK2064	HRS	5991.87								
	AFL	4884								
PROC. REF: AMM 71-20-00										
7120069 ^S	NO. 1 ENGINE AFT ISOLATOR - PERFORM VISUAL INSPECTION OF ISOLATOR AND ASSOCIATED PARTS									Service ATA:71
	MOS/MSC	10-May-05	N/A							
	HRS	0								
	AFL	0								
PROC. REF: AMM 71-20-00										
7120069	NO. 1 ENGINE ALL ISOLATORS - PERFORM VISUAL INSPECTION OF ISOLATORS AND ASSOCIATED PARTS									Service ATA:71
	MOS/MSC	14-Mar-14	N/A							
	HRS	5991.87								
	AFL	4884								
PROC. REF: AMM 71-20-00										
7120069 ^S	NO. 1 ENGINE FORWARD UPPER ISOLATOR - PERFORM VISUAL INSPECTION OF ISOLATOR AND ASSOCIATED PARTS									Service ATA:71
	MOS/MSC	10-May-05	N/A							
	HRS	0								
	AFL	0								
PROC. REF: AMM 71-20-00										
7120069 ^S	NO. 2 ENGINE AFT ISOLATOR - PERFORM VISUAL INSPECTION OF ISOLATOR AND ASSOCIATED PARTS									Service ATA:71
	MOS/MSC	10-May-05	N/A							
	HRS	0								
	AFL	0								
PROC. REF: AMM 71-20-00										
7120069	NO. 2 ENGINE ALL ISOLATORS - PERFORM VISUAL INSPECTION OF ISOLATORS AND ASSOCIATED PARTS									Service ATA:71
	MOS/MSC	12-Mar-14	N/A							
	HRS	5991.87								
	AFL	4884								
PROC. REF: AMM 71-20-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 71 - POWER PLANT										
7120069 ^S	NO. 2 ENGINE FORWARD LOWER ISOLATOR - PERFORM VISUAL INSPECTION OF ISOLATOR AND ASSOCIATED PARTS									Service ATA:71
	MOS/MSC	10-May-05	N/A							
	HRS	0								
	AFL	0								
PROC. REF: AMM 71-20-00										
7120069 ^S	NO. 2 ENGINE FORWARD UPPER ISOLATOR - PERFORM VISUAL INSPECTION OF ISOLATOR AND ASSOCIATED PARTS									Service ATA:71
	MOS/MSC	10-May-05	N/A							
	HRS	0								
	AFL	0								
PROC. REF: AMM 71-20-00										
7120070 ^S	REPLACE NO. 1 ENGINE AFT ENGINE MOUNT ISOLATOR BONDED MOUNTING									Component ATA:71
PN:PN	MOS/MSC	10-May-05	N/A	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										
7120070	REPLACE NO. 1 ENGINE ALL ENGINE MOUNT ISOLATOR BONDED MOUNTING									Component ATA:71
PN:PN	MOS/MSC		N/A							
SN:UNKNOWN	HRS									
	AFL	0								
PROC. REF: AMM 71-20-00										
7120070 ^S	REPLACE NO. 1 ENGINE FORWARD LOWER ENGINE MOUNT ISOLATOR BONDED MOUNTING									Component ATA:71
PN:PN	MOS/MSC	10-May-05	N/A	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										
7120070 ^S	REPLACE NO. 1 ENGINE FORWARD UPPER ENGINE MOUNT ISOLATOR BONDED MOUNTING									Component ATA:71
PN:PN	MOS/MSC	10-May-05	N/A	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										
7120070 ^S	REPLACE NO. 2 ENGINE AFT ENGINE MOUNT ISOLATOR BONDED MOUNTING									Component ATA:71
PN:PN	MOS/MSC	10-May-05	N/A	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 71 - POWER PLANT										
7120070	REPLACE NO. 2 ENGINE ALL ENGINE MOUNT ISOLATOR BONDED MOUNTING									Component ATA:71
PN:PN	MOS/MSC		N/A							
SN:UNKNOWN	HRS									
	AFL	0								
PROC. REF: AMM 71-20-00										
7120070 ^S	REPLACE NO. 2 ENGINE FORWARD LOWER ENGINE MOUNT ISOLATOR BONDED MOUNTING									Component ATA:71
PN:PN	MOS/MSC	10-May-05	N/A	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										
7120070 ^S	REPLACE NO. 2 ENGINE FORWARD UPPER ENGINE MOUNT ISOLATOR BONDED MOUNTING									Component ATA:71
PN:PN	MOS/MSC	10-May-05	N/A	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										
7120073 ^S	NO. 1 ENGINE AFT ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS									Service ATA:71
	MOS/MSC	10-May-05	N/A							
	HRS	0								
	AFL	0								
PROC. REF: AMM 71-20-00										
7120073	NO. 1 ENGINE ALL ISOLATORS - PERFORM INSPECTION OF ISOLATORS AND ASSOCIATED PARTS									Service ATA:71
	MOS/MSC	07-Feb-14	N/A							
	HRS	5991.87								
	AFL	4884								
PROC. REF: AMM 71-20-00										
7120073 ^S	NO. 1 ENGINE FORWARD LOWER ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS									Service ATA:71
	MOS/MSC	10-May-05	N/A							
	HRS	0								
	AFL	0								
PROC. REF: AMM 71-20-00										
7120073 ^S	NO. 1 ENGINE FORWARD UPPER ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS									Service ATA:71
	MOS/MSC	10-May-05	N/A							
	HRS	0								
	AFL	0								
PROC. REF: AMM 71-20-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 71 - POWER PLANT											
7120073 ^S			NO. 2 ENGINE AFT ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS						Service	ATA:71	
	MOS/MSC	10-May-05	N/A								
	HRS	0									
	AFL	0									
PROC. REF: AMM 71-20-00											
7120073			NO. 2 ENGINE ALL ISOLATORS - PERFORM INSPECTION OF ISOLATORS AND ASSOCIATED PARTS						Service	ATA:71	
	MOS/MSC	07-Feb-14	N/A								
	HRS	5991.87									
	AFL	4884									
PROC. REF: AMM 71-20-00											
7120073 ^S			NO. 2 ENGINE FORWARD LOWER ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS						Service	ATA:71	
	MOS/MSC	10-May-05	N/A								
	HRS	0									
	AFL	0									
PROC. REF: AMM 71-20-00											
7120073 ^S			NO. 2 ENGINE FORWARD UPPER ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS						Service	ATA:71	
	MOS/MSC	10-May-05	N/A								
	HRS	0									
	AFL	0									
PROC. REF: AMM 71-20-00											
714010 ^S			NO. 1 ENGINE - CHECK ELECTRICAL WIRES AND CONNECTIONS - VISUALLY INSPECT FOR SECURITY AND DAMAGE						Service	ATA:71	
	MOS	03-Jan-24									
	HRS	9174	850 (-350)								
	ENC	7357									
PROC. REF: LMM 72-00-00											
714010 ^S			NO. 2 ENGINE - CHECK ELECTRICAL WIRES AND CONNECTIONS - VISUALLY INSPECT FOR SECURITY AND DAMAGE						Service	ATA:71	
	MOS	03-Jan-24									
	HRS	9174	850 (-350)								
	ENC	7357									
PROC. REF: LMM 72-00-00											
715010 ^S			NO. 1 ENGINE - CHECK PLUMBING LINES AND CONNECTIONS - VISUALLY INSPECT FOR SECURITY, LOOSE OR BROKEN CLAMPS OR BRACKETS, LEAKS, CRACKS, CUTS, OR RUBBING						Service	ATA:71	
	MOS	03-Jan-24									
	HRS	9174	850 (-350)								
	ENC	7357									
PROC. REF: LMM 72-00-00											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 71 - POWER PLANT										
715010 ^S NO. 2 ENGINE - CHECK PLUMBING LINES AND CONNECTIONS - VISUALLY INSPECT FOR SECURITY, LOOSE OR BROKEN CLAMPS OR BRACKETS, LEAKS, CRACKS, CUTS, OR RUBBING Service ATA:71										
	MOS	03-Jan-24								
	HRS	9174	850 (-350)							
	ENC	7357								
PROC. REF: LMM 72-00-00										PKG:0
71EN1 NO. 1 ENGINE Component ATA:71										
PN:3060084-1	MOS/MSC		E/C							
SN:P-116596C	HRS									
WC#: 71.EN1	AFL									
PROC. REF: AMM 71-00-01										
71EN2 NO. 2 ENGINE Component ATA:71										
PN:3060084-1	MOS/MSC		E/C							
SN:P-116597C	HRS									
WC#: 71.EN2	AFL									
PROC. REF: AMM 71-00-01										
P7120001 ^S * FORWARD ENGINE MOUNT - PERFORM EDDY CURRENT INSPECTION (AWL*) Service ATA:71										
	MOS	10-May-23						AIRWORTHINESS		
	HRS	9071.3	4800							
	AFL	7252								
PROC. REF: NDT PART 6/71-10-01										PKG:25
Y7100002 ^S LOWER ENGINE COWLING - VISUALLY INSPECT LATCH CHANNELS FOR CHAFING. Service ATA:71										
	MOS	25-Jan-24	24 (+14d/-14d)							
	HRS	9265.8	600 (+25/-25)							
	AFL	7395								
PROC. REF: GENERIC NO REF										PKG:9
Y7110000 ^S ENGINE NACELLE - PERFORM VISUAL INSPECTION. INSPECT INLET BULKHEAD, STRUCTURE, PLUMBING, SKIN SPOT WELDS, ANTI-ICE OUTLET SCREEN, AND FASTENERS FOR SECURITY, CRACKS, AND GENERAL CONDITION. Service ATA:71										
	MOS	25-Jan-24	24 (+14d/-14d)							
	HRS	9265.8	600 (+25/-25)							
	AFL	7395								
PROC. REF: GENERIC NO REF										PKG:9
Y7110001 ^S ENGINE INLET LIP AND DUCT - PERFORM VISUAL INSPECTION. Service ATA:71										
	MOS	25-Jan-24	24 (+14d/-14d)							
	HRS	9265.8	600 (+25/-25)							
	AFL	7395								
PROC. REF: GENERIC NO REF										PKG:9

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 71 - POWER PLANT										
Y7110002 ^S	ENGINE STARTER/GENERATOR INLET AND EXHAUST DUCT AND SEALS - PERFORM VISUAL INSPECTION.									Service ATA:71
	MOS	25-Jan-24	24 (+14d/-14d)							
	HRS	9265.8	600 (+25/-25)							
	AFL	7395								
PROC. REF: GENERIC NO REF										PKG:9
Y7110003 ^S	ENGINE ALTERNATOR EXHAUST DUCT AND SEALS - PERFORM VISUAL INSPECTION.									Service ATA:71
	MOS	25-Jan-24	24 (+14d/-14d)							
	HRS	9265.8	600 (+25/-25)							
	AFL	7395								
PROC. REF: GENERIC NO REF										PKG:9
Y7120000 ^S	FORWARD ENGINE MOUNTS - PERFORM VISUAL INSPECTION									Service ATA:71
	MOS	25-Jan-24	12 (+14d/-14d)							
	HRS	9265.8	300 (+25/-25)							
	AFL	7395								
PROC. REF: GENERIC NO REF										PKG:3
ATA 72 - ENGINE										
72-AS-720005	NO. 1 ENGINE - INSPECT MAJOR PERIODIC PER MANUFACTURERS INSTRUCTIONS									Service ATA:72
	MOS	14-Mar-14								
	HRS	5991.87	3500 (+100)		(9491.87) 9575.87	9591.87	60.2 (+100)			
	ENC	4884								
PROC. REF: LMM 72-00-00										
72-AS-720005	NO. 2 ENGINE - INSPECT MAJOR PERIODIC PER MANUFACTURERS INSTRUCTIONS									Service ATA:72
	MOS	12-Mar-14								
	HRS	5991.87	3500 (+100)		(9491.87) 9575.87	9591.87	60.2 (+100)			
	ENC	4884								
PROC. REF: LMM 72-00-00										
72-AS-720006 ^S	NO. 1 ENGINE - INSPECT COMB CHAMBER PLENUM CASE INSP PER MANUFACTURERS INSTRUCTIONS									Service ATA:72
	MOS	25-Jan-05								
	HRS	0	3500 (+100/-100)							
	ENC	0								
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 72 - ENGINE											
72-AS-720006 ^S			NO. 2 ENGINE - INSPECT COMB CHAMBER PLENUM CASE INSP PER MANUFACTURERS INSTRUCTIONS							Service	ATA:72
	MOS	26-Jan-05									
	HRS	0	3500 (+100/-100)								
	ENC	0									
PROC. REF: GENERIC NO REF											
72-AS-720007			NO. 1 ENGINE - INSPECT COMPRESSOR ZONE PER MANUFACTURERS INSTRUCTIONS							Service	ATA:72
	MOS	14-Mar-14									
	HRS	5991.87	7000 (+200)		(12991.87) 13075.87	13191.87	3560.2 (+200)				
	ENC	4884									
PROC. REF: LMM 72-00-00											
72-AS-720007			NO. 2 ENGINE - INSPECT COMPRESSOR ZONE PER MANUFACTURERS INSTRUCTIONS							Service	ATA:72
	MOS	12-Mar-14									
	HRS	5991.87	7000 (+200)		(12991.87) 13075.87	13191.87	3560.2 (+200)				
	ENC	4884									
PROC. REF: LMM 72-00-00											
72-AS-720008 ^S			NO. 1 ENGINE - INSPECT AGB PER MANUFACTURERS INSTRUCTIONS							Service	ATA:72
	MOS	25-Jan-05									
	HRS	0	7000 (+200/-200)								
	ENC	0									
PROC. REF: GENERIC NO REF, LMM 72-60-02											
72-AS-720008 ^S			NO. 2 ENGINE - INSPECT AGB PER MANUFACTURERS INSTRUCTIONS							Service	ATA:72
	MOS	26-Jan-05									
	HRS	0	7000 (+200/-200)								
	ENC	0									
PROC. REF: GENERIC NO REF, LMM 72-60-02											
72-AS-720010			NO. 1 ENGINE - ANALYSIS OIL AND FILTER (BASELINE/SPECIAL REQUIREMENT) (SOAP)							Service	ATA:72
	MOS/MSC	18-Jul-05	A/R								
	HRS	13.7									
	ENC	11									
PROC. REF: LMM 72-00-00											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 72 - ENGINE											
72-AS-720010			NO. 2 ENGINE - ANALYSIS OIL AND FILTER (BASELINE/SPECIAL REQUIREMENT) (SOAP)						Service	ATA:72	
	MOS/MSC	18-Jul-05	A/R								
	HRS	13.7									
	ENC	11									
PROC. REF: LMM 72-00-00											
72-AS-720011			NO. 1 ENGINE - REPLACE FUEL FILTER ELEMENT (25-HR INITIAL)						Service	ATA:72	
	MOS/MSC	18-Jul-05	A/R								
	HRS	13.7									
	ENC	11									
PROC. REF: LMM 73-21-02											
72-AS-720011			NO. 2 ENGINE - REPLACE FUEL FILTER ELEMENT (25-HR INITIAL)						Service	ATA:72	
	MOS/MSC	18-Jul-05	A/R								
	HRS	13.7									
	ENC	11									
PROC. REF: LMM 73-21-02											
720110			NO. 1 ENGINE - ACCESSORY GEARBOX						Component	ATA:72	
PN:3060827-2	MOS/MSC	25-Jan-05	O/C	TSN 0							
SN:S-2066	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: LMM 72-60-02											
720110			NO. 2 ENGINE - ACCESSORY GEARBOX						Component	ATA:72	
PN:3060827-2	MOS/MSC	26-Jan-05	O/C	TSN 0							
SN:S-2062	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: LMM 72-60-02											
723010 ^S			NO. 1 ENGINE - CHECK CARBON SEAL HEALTH						Service	ATA:72	
	MOS	03-Jan-24									
	HRS	9174	1600 (+50/-100)								
	ENC	7357									
PROC. REF: LMM 72-00-00											
723010 ^S			NO. 2 ENGINE - CHECK CARBON SEAL HEALTH						Service	ATA:72	
	MOS	03-Jan-24									
	HRS	9174	1600 (+50/-100)								
	ENC	7357									
PROC. REF: LMM 72-00-00											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725007	NO. 1 ENGINE - HIGH PRESSURE TURBINE (HPT) NOZZLE ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	25-Jan-05	A/R	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
WC#: 72.500	ENC	0	TSN 0							
PROC. REF: LMM 72-50-07										
725007	NO. 2 ENGINE - HIGH PRESSURE TURBINE (HPT) NOZZLE ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	26-Jan-05	A/R	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
WC#: 72.500	ENC	0	TSN 0							
PROC. REF: LMM 72-50-07										
725010	NO. 1 ENGINE - 1ST-STAGE LOW PRESSURE TURBINE (LPT) DISC									Component ATA:72
PN:3060625-1	MOS	25-Jan-05	TSN 0							LIFE LIMIT
SN:040322901930	HRS	0	TSN 0							
ENC	0	12000	TSN 0	(12000) 12034	4458					
PROC. REF: LMM 72-50-04										
725010	NO. 2 ENGINE - 1ST-STAGE LOW PRESSURE TURBINE (LPT) DISC									Component ATA:72
PN:3060625-1	MOS	26-Jan-05	TSN 0							LIFE LIMIT
SN:040322901934	HRS	0	TSN 0							
ENC	0	12000	TSN 0	(12000) 12034	4458					
PROC. REF: LMM 72-50-04										
725020	NO. 1 ENGINE - 2ND-STAGE LOW PRESSURE TURBINE (LPT) DISC									Component ATA:72
PN:3060611-1	MOS	25-Jan-05	TSN 0							LIFE LIMIT
SN:040322901467	HRS	0	TSN 0							
ENC	0	12000	TSN 0	(12000) 12034	4458					
PROC. REF: LMM 72-50-04										
725020	NO. 2 ENGINE - 2ND-STAGE LOW PRESSURE TURBINE (LPT) DISC									Component ATA:72
PN:3060611-1	MOS	26-Jan-05	TSN 0							LIFE LIMIT
SN:040322900200	HRS	0	TSN 0							
ENC	0	12000	TSN 0	(12000) 12034	4458					
PROC. REF: LMM 72-50-04										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725030	NO. 1 ENGINE - 3RD-STAGE LOW PRESSURE TURBINE (LPT) DISC									Component ATA:72
PN:3060671-2	MOS	25-Jan-05		TSN 0				LIFE LIMIT		
SN:040322902116	HRS	0		TSN 0						
	ENC	0	12000	TSN 0	(12000) 12034		4458			
PROC. REF: LMM 72-50-04										
725030	NO. 2 ENGINE - 3RD-STAGE LOW PRESSURE TURBINE (LPT) DISC									Component ATA:72
PN:3060671-2	MOS	26-Jan-05		TSN 0				LIFE LIMIT		
SN:040322902117	HRS	0		TSN 0						
	ENC	0	12000	TSN 0	(12000) 12034		4458			
PROC. REF: LMM 72-50-04										
725040	NO. 1 ENGINE - HIGH PRESSURE TURBINE (HPT) DISC									Component ATA:72
PN:3060841-1	MOS							LIFE LIMIT		
SN:051217200048	HRS									
	ENC	0	10000	TSN 2500	(10062) 10096 (M)		2520			
PROC. REF: LMM 72-50-07										
725040	NO. 2 ENGINE - HIGH PRESSURE TURBINE (HPT) DISC									Component ATA:72
PN:3060841-1	MOS							LIFE LIMIT		
SN:051217200081	HRS									
	ENC	0	10000	TSN 2500	(10062) 10096 (M)		2520			
PROC. REF: LMM 72-50-07										
725045	NO. 1 ENGINE - HIGH PRESSURE TURBINE (HPT) ASSY									Component ATA:72
PN:PN	MOS/MSC	25-Jan-05	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
725045	NO. 2 ENGINE - HIGH PRESSURE TURBINE (HPT) ASSY									Component ATA:72
PN:PN	MOS/MSC	26-Jan-05	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 72 - ENGINE											
725050		NO. 1 ENGINE - FAN DISC								Component	ATA:72
PN:3060287-2	MOS		25-Jan-05		TSN 0			LIFE LIMIT			
SN:030322902310	HRS		0		TSN 0						
	ENC		0	20000	TSN 0	(20000) 20034	12458				
PROC. REF: GENERIC NO REF											
725050		NO. 2 ENGINE - FAN DISC								Component	ATA:72
PN:3060287-2	MOS		26-Jan-05		TSN 0			LIFE LIMIT			
SN:040322900791	HRS		0		TSN 0						
	ENC		0	20000	TSN 0	(20000) 20034	12458				
PROC. REF: GENERIC NO REF											
725060		NO. 1 ENGINE - 1ST-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC								Component	ATA:72
PN:3060372-1	MOS		25-Jan-05		TSN 0			LIFE LIMIT			
SN:040306003327	HRS		0		TSN 0						
	ENC		0	10000	TSN 0	(10000) 10034	2458				
PROC. REF: LMM 72-30-04											
725060		NO. 2 ENGINE - 1ST-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC								Component	ATA:72
PN:3060372-1	MOS		26-Jan-05		TSN 0			LIFE LIMIT			
SN:040316003325	HRS		0		TSN 0						
	ENC		0	10000	TSN 0	(10000) 10034	2458				
PROC. REF: LMM 72-30-04											
725070		NO. 1 ENGINE - 2ND-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC								Component	ATA:72
PN:3060373-1	MOS		25-Jan-05		TSN 0			LIFE LIMIT			
SN:040316002582	HRS		0		TSN 0						
	ENC		0	10000	TSN 0	(10000) 10034	2458				
PROC. REF: LMM 72-30-04											
725070		NO. 2 ENGINE - 2ND-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC								Component	ATA:72
PN:3060373-1	MOS		26-Jan-05		TSN 0			LIFE LIMIT			
SN:040316002571	HRS		0		TSN 0						
	ENC		0	10000	TSN 0	(10000) 10034	2458				
PROC. REF: LMM 72-30-04											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725080	NO. 1 ENGINE - 3RD-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC									Component ATA:72
PN:3060374-1	MOS		25-Jan-05		TSN 0			LIFE LIMIT		
SN:040316002226	HRS		0		TSN 0					
	ENC		0	20000	TSN 0	(20000) 20034	12458			
PROC. REF: LMM 72-30-04										
725080	NO. 2 ENGINE - 3RD-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC									Component ATA:72
PN:3060374-1	MOS		26-Jan-05		TSN 0			LIFE LIMIT		
SN:040316002225	HRS		0		TSN 0					
	ENC		0	20000	TSN 0	(20000) 20034	12458			
PROC. REF: LMM 72-30-04										
725090	NO. 1 ENGINE - 4TH-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC									Component ATA:72
PN:3075326-5	MOS		25-Jan-05		TSN 0			LIFE LIMIT		
SN:040350107662	HRS		0		TSN 0					
	ENC		0	20000	TSN 0	(20000) 20034	12458			
PROC. REF: LMM 72-30-04										
725090	NO. 2 ENGINE - 4TH-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC									Component ATA:72
PN:3075326-5	MOS		26-Jan-05		TSN 0			LIFE LIMIT		
SN:040350107603	HRS		0		TSN 0					
	ENC		0	20000	TSN 0	(20000) 20034	12458			
PROC. REF: LMM 72-30-04										
725110	NO. 1 ENGINE - LOW PRESSURE COMPRESSOR TIE ROD									Component ATA:72
PN:3074744-1	MOS/MSC		25-Jan-05	O/C	TSN 0					
SN:04P22935	HRS		0		TSN 0					
	ENC		0		TSN 0					
PROC. REF: LMM 72-30-10, LMM 72-30-10, LMM 72-30-10										
725110	NO. 2 ENGINE - LOW PRESSURE COMPRESSOR TIE ROD									Component ATA:72
PN:3074744-1	MOS/MSC		26-Jan-05	O/C	TSN 0					
SN:04P22921	HRS		0		TSN 0					
	ENC		0		TSN 0					
PROC. REF: LMM 72-30-10, LMM 72-30-10, LMM 72-30-10										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 72 - ENGINE											
725120		NO. 1 ENGINE - HIGH PRESSURE COMPRESSOR ROTOR IMPELLER								Component	ATA:72
PN:3060371-1	MOS			TSN 0				LIFE LIMIT			
SN:13-182449-10175	HRS			TSN 0							
	ENC	0	8000	TSN 0	(12884) 12918 (M)		5342				
PROC. REF: LMM 72-50-06											
725120		NO. 2 ENGINE - HIGH PRESSURE COMPRESSOR ROTOR IMPELLER								Component	ATA:72
PN:3060371-1	MOS			TSN 0				LIFE LIMIT			
SN:13-182449-09492	HRS			TSN 0							
	ENC	0	8000	TSN 0	(12884) 12918 (M)		5342				
PROC. REF: LMM 72-50-06											
725130		NO. 1 ENGINE - FAN SPINNER								Component	ATA:72
PN:3060156-2	MOS	25-Jan-05		TSN 0				LIFE LIMIT			
SN:042784300293	HRS	0		TSN 0							
	ENC	0	20000	TSN 0	(20000) 20034		12458				
PROC. REF: LMM 72-70-01											
725130		NO. 2 ENGINE - FAN SPINNER								Component	ATA:72
PN:3060156-2	MOS	26-Jan-05		TSN 0				LIFE LIMIT			
SN:042784300283	HRS	0		TSN 0							
	ENC	0	20000	TSN 0	(20000) 20034		12458				
PROC. REF: LMM 72-70-01											
725140		NO. 1 ENGINE - FAN DRIVE SHAFT								Component	ATA:72
PN:3060180-2	MOS/MSC	25-Jan-05	O/C	TSN 0							
SN:041366303699	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: GENERIC NO REF											
725140		NO. 2 ENGINE - FAN DRIVE SHAFT								Component	ATA:72
PN:3067021-1	MOS/MSC	26-Jan-05	O/C	TSN 0							
SN:010339000673	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: GENERIC NO REF											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725160 NO. 1 ENGINE - FORWARD ROTOR HIGH PRESSURE SEAL Component ATA:72										
PN:3060698-1	MOS			TSN 0				LIFE LIMIT		
SN:13-162246-00058	HRS			TSN 0						
	ENC	0	7000	TSN 0	(11884) 11918 (M)		4342			
PROC. REF: LMM 72-70-03										
725160 NO. 2 ENGINE - FORWARD ROTOR HIGH PRESSURE SEAL Component ATA:72										
PN:3060698-1	MOS			TSN 0				LIFE LIMIT		
SN:12-162053-47102	HRS			TSN 0						
	ENC	0	7000	TSN 0	(11884) 11918 (M)		4342			
PROC. REF: LMM 72-70-03										
725170 NO. 1 ENGINE - HIGH PRESSURE SHOULDERED SHAFT Component ATA:72										
PN:3060366-3	MOS/MSC	25-Jan-05	O/C	TSN 0						
SN:04P26318	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725170 NO. 2 ENGINE - HIGH PRESSURE SHOULDERED SHAFT Component ATA:72										
PN:3060366-3	MOS/MSC	26-Jan-05	O/C	TSN 0						
SN:04P25139	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725180 NO. 1 ENGINE - COMBUSTION PLENUM CASE Component ATA:72										
PN:3060534-4	MOS/MSC	25-Jan-05	O/C	TSN 0						
SN:04P23220	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-40-04, LMM 72-40-04										
725180 NO. 2 ENGINE - COMBUSTION PLENUM CASE Component ATA:72										
PN:3060534-4	MOS/MSC	26-Jan-05	O/C	TSN 0						
SN:04P24170	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-40-04, LMM 72-40-04										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725210	NO. 1 ENGINE - HIGH PRESSURE TURBINE FORWARD SEAL PLATE									Component ATA:72
PN:3060514-1	MOS		25-Jan-05		TSN 0			LIFE LIMIT		
SN:040322903211	HRS		0		TSN 0					
	ENC		0	10000	TSN 0	(10000) 10034	2458			
PROC. REF: GENERIC NO REF										
725210	NO. 2 ENGINE - HIGH PRESSURE TURBINE FORWARD SEAL PLATE									Component ATA:72
PN:3060514-1	MOS		26-Jan-05		TSN 0			LIFE LIMIT		
SN:040322903212	HRS		0		TSN 0					
	ENC		0	10000	TSN 0	(10000) 10034	2458			
PROC. REF: GENERIC NO REF										
725220	NO. 1 ENGINE - TURBINE INTERSTAGE TRANSITION DUCT									Component ATA:72
PN:3060694-6	MOS/MSC		25-Jan-05	O/C	TSN 0					
SN:02P01802	HRS		0		TSN 0					
	ENC		0		TSN 0					
PROC. REF: GENERIC NO REF										
725220	NO. 2 ENGINE - TURBINE INTERSTAGE TRANSITION DUCT									Component ATA:72
PN:3060694-6	MOS/MSC		26-Jan-05	O/C	TSN 0					
SN:00P27570	HRS		0		TSN 0					
	ENC		0		TSN 0					
PROC. REF: GENERIC NO REF										
725230	NO. 1 ENGINE - LOW PRESSURE TURBINE (LPT) 1 NOZZLE SEAL SUPPORT									Component ATA:72
PN:3060693-1	MOS/MSC		25-Jan-05	O/C	TSN 0					
SN:01P15821	HRS		0		TSN 0					
	ENC		0		TSN 0					
PROC. REF: LMM 72-50-04										
725230	NO. 2 ENGINE - LOW PRESSURE TURBINE (LPT) 1 NOZZLE SEAL SUPPORT									Component ATA:72
PN:3060693-1	MOS/MSC		26-Jan-05	O/C	TSN 0					
SN:950740420408	HRS		0		TSN 0					
	ENC		0		TSN 0					
PROC. REF: LMM 72-50-04										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725240	NO. 1 ENGINE - LOW PRESSURE TURBINE (LPT) 1 NOZZLE ASSEMBLY									Component ATA:72
PN:3060666-7	MOS/MSC	25-Jan-05	O/C	TSN 0						
SN:08P11075	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-50-04										
725240	NO. 2 ENGINE - LOW PRESSURE TURBINE (LPT) 1 NOZZLE ASSEMBLY									Component ATA:72
PN:3060666-7	MOS/MSC	26-Jan-05	O/C	TSN 0						
SN:950740418475	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-50-04										
725250	NO. 1 ENGINE - FORWARD SHAFT HIGH PRESSURE TURBINE (HPT) COUPLING									Component ATA:72
PN:3060502-2	MOS/MSC	25-Jan-05	O/C	TSN 0						
SN:05P00427	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725250	NO. 2 ENGINE - FORWARD SHAFT HIGH PRESSURE TURBINE (HPT) COUPLING									Component ATA:72
PN:3060502-2	MOS/MSC	26-Jan-05	O/C	TSN 0						
SN:04P25580	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725260	NO. 1 ENGINE - AFT HIGH PRESSURE TURBINE (HPT) SHAFT COUPLING									Component ATA:72
PN:3060599-2	MOS/MSC	25-Jan-05	O/C	TSN 0						
SN:04P26086	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725260	NO. 2 ENGINE - AFT HIGH PRESSURE TURBINE (HPT) SHAFT COUPLING									Component ATA:72
PN:3060599-2	MOS/MSC	26-Jan-05	O/C	TSN 0						
SN:04P25408	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725270	NO. 1 ENGINE - NOZZLE LOW PRESSURE TURBINE (LPT) (A5) SEAL									Component ATA:72
PN:3073765-12	MOS/MSC	25-Jan-05	O/C	TSN 0						
SN:01P15394	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725270	NO. 2 ENGINE - NOZZLE LOW PRESSURE TURBINE (LPT) (A5) SEAL									Component ATA:72
PN:3073765-12	MOS/MSC	26-Jan-05	O/C	TSN 0						
SN:95074042151	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
726005	NO. 1 ENGINE - TRANSFER GEARBOX ASSEMBLY									Component ATA:72
PN:3070093-16	MOS/MSC	25-Jan-05	O/C	TSN 0						
SN:04P11300	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-60-03										
726005	NO. 2 ENGINE - TRANSFER GEARBOX ASSEMBLY									Component ATA:72
PN:3070093-16	MOS/MSC	26-Jan-05	O/C	TSN 0						
SN:04P11302	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-60-03										
727006	NO. 1 ENGINE - LOWER FAN DUCT ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	25-Jan-05	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-70-05										
727006	NO. 2 ENGINE - LOWER FAN DUCT ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	26-Jan-05	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-70-05										
727010 ^S	NO. 1 ENGINE - INSPECT BYPASS STATOR VANE ASSEMBLY.									Service ATA:72
	MOS	03-Sep-21								
	HRS	8351.1	1200 (+100/-200)							
	ENC	6753								
PROC. REF: GENERIC NO REF, LMM 72-70-04, LMM 72-70-04, LMM 72-70-04										
727010 ^S	NO. 2 ENGINE - INSPECT BYPASS STATOR VANE ASSEMBLY.									Service ATA:72
	MOS	03-Sep-21								
	HRS	8351.1	1200 (+100/-200)							
	ENC	6753								
PROC. REF: GENERIC NO REF, LMM 72-70-04, LMM 72-70-04, LMM 72-70-04										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 73 - ENGINE FUEL AND CONTROL										
730110 NO. 1 ENGINE - FUEL CONTROL UNIT										Component ATA:73
PN:3070800-47	MOS/MSC	06-Oct-20	O/C	TSR 0						
SN:16117	HRS	7987.5		TSR 0						
	ENC	6473		TSR 0						
PROC. REF: LMM 73-20-01										
730110 NO. 2 ENGINE - FUEL CONTROL UNIT										Component ATA:73
PN:3070800-37	MOS/MSC	26-Jan-05	O/C	TSN 0						
SN:16768	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 73-20-01										
730120^S NO. 1 ENGINE - REPLACE FUEL FILTER ELEMENT										Service ATA:73
	MOS	10-May-23								
	HRS	8987.3	600							
	ENC	7218								
PROC. REF: LMM 73-21-02, LMM 73-21-02										PKG:0
730120^S NO. 2 ENGINE - REPLACE FUEL FILTER ELEMENT										Service ATA:73
	MOS	10-May-23								
	HRS	8987.3	600							
	ENC	7218								
PROC. REF: LMM 73-21-02, LMM 73-21-02										PKG:0
730130 NO. 1 ENGINE - ENGINE FUEL PUMP ASSEMBLY										Component ATA:73
PN:3060760-4	MOS/MSC	25-Jan-05	O/C	TSN 0						
SN:1682	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 73-20-01, LMM 73-20-01, LMM 73-20-01										
730130 NO. 2 ENGINE - ENGINE FUEL PUMP ASSEMBLY										Component ATA:73
PN:3060760-4	MOS/MSC	26-Jan-05	O/C	TSN 0						
SN:1660	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 73-20-01, LMM 73-20-01, LMM 73-20-01										
731001 NO. 1 ENGINE - MOTIVE FLOW FUEL PUMP ASSEMBLY										Component ATA:73
PN:3060759-1	MOS/MSC	25-Jan-05	O/C	TSN 0						
SN:0985	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 73-21-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 73 - ENGINE FUEL AND CONTROL										
731001	NO. 2 ENGINE - MOTIVE FLOW FUEL PUMP ASSEMBLY									Component ATA:73
PN:3060759-1	MOS/MSC	26-Jan-05	O/C	TSN 0						
SN:1658	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 73-21-02										
731110	NO. 1 ENGINE - PRESSURE LIMITER (PCD) VALVE									Component ATA:73
PN:3070685-11	MOS/MSC	25-Jan-05	O/C	TSN 0						
SN:16227	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 73-20-01										
731110	NO. 2 ENGINE - PRESSURE LIMITER (PCD) VALVE									Component ATA:73
PN:3070685-11	MOS/MSC	26-Jan-05	O/C	TSN 0						
SN:16255	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 73-20-01										
731120	NO. 1 ENGINE - FUEL FLOW DIVIDER/DRAIN VALVE									Component ATA:73
PN:394476-2	MOS/MSC	25-Jan-05	O/C	TSN 0						
SN:1819	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
731120	NO. 2 ENGINE - FUEL FLOW DIVIDER/DRAIN VALVE									Component ATA:73
PN:394476-2	MOS/MSC	26-Jan-05	O/C	TSN 0						
SN:1181	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
732120 ^S	NO. 1 ENGINE - INSPECT MOTIVE FLOW FUEL PUMP DRIVE SPLINE									Service ATA:73
	MOS	10-May-23								
	HRS	8987.3	600 (+50/-100)							
	ENC	7218								
PROC. REF: LMM 72-00-00, LMM 73-21-04										
732120 ^S	NO. 2 ENGINE - INSPECT MOTIVE FLOW FUEL PUMP DRIVE SPLINE									Service ATA:73
	MOS	10-May-23								
	HRS	8987.3	600 (+50/-100)							
	ENC	7218								
PROC. REF: LMM 72-00-00, LMM 73-21-04										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 73 - ENGINE FUEL AND CONTROL										
733013	DUAL FUEL FLOW (DFFC) CONVERTER									Component ATA:73
PN:6673308500-003	MOS/MSC	13-Dec-09	O/C							
SN:V01030738BA	HRS	3104.17								
	AFL	2569								
PROC. REF: AMM 73-31-02										
734012	RIGHT FUEL TEMPERATURE BULB									Component ATA:73
PN:MS28034-3	MOS/MSC	01-Dec-06	O/C							
SN:133624	HRS	1017.73								
	AFL	815								
PROC. REF: AMM 73-31-03										
ATA 74 - IGNITION										
740140 ^S	NO. 1 ENGINE - REMOVE AND INSPECT 5 O'CLOCK IGNITER PLUG AND LEAD									Service ATA:74
	MOS	03-Jan-24								
	HRS	9174	1600 (+50/-100)							
	ENC	7357								
PROC. REF: LMM 74-00-01, LMM 74-00-01										
740140 ^S	NO. 2 ENGINE - REMOVE AND INSPECT 5 O'CLOCK IGNITER PLUG AND LEAD									Service ATA:74
	MOS	03-Jan-24								
	HRS	9174	1600 (+50/-100)							
	ENC	7357								
PROC. REF: LMM 74-00-01, LMM 74-00-01										
740160 ^S	NO. 1 ENGINE - REMOVE AND INSPECT 7 O'CLOCK IGNITER PLUG AND LEAD									Service ATA:74
	MOS	03-Jan-24								
	HRS	9174	1600 (+50/-100)							
	ENC	7357								
PROC. REF: LMM 74-00-01										
740160 ^S	NO. 2 ENGINE - REMOVE AND INSPECT 7 O'CLOCK IGNITER PLUG AND LEAD									Service ATA:74
	MOS	03-Jan-24								
	HRS	9174	1600 (+50/-100)							
	ENC	7357								
PROC. REF: LMM 74-00-01										
ATA 76 - ENGINE CONTROLS										
761210	THROTTLE CONTROL MODULE									Component ATA:76
PN:69011-17	MOS/MSC	24-Sep-21	O/C							
SN:607	HRS	8457.7								
	AFL	6804								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	-----	----------

ATA 76 - ENGINE CONTROLS

PROC. REF: GENERIC NO REF

761320		NO. 1 ENGINE - SOLENOID CONTROLLER VALVE					Component	ATA:76
PN:10696-6-1	MOS/MSC	25-Jan-05	O/C	TSN 0				
SN:11660	HRS	0		TSN 0				
	ENC	0		TSN 0				

PROC. REF: LMM 76-10-01, LMM 76-10-01, LMM 76-10-01

761320		NO. 2 ENGINE - SOLENOID CONTROLLER VALVE					Component	ATA:76
PN:10969-6-1	MOS/MSC	26-Jan-05	O/C	TSN 0				
SN:11657	HRS	0		TSN 0				
	ENC	0		TSN 0				

PROC. REF: LMM 76-10-01, LMM 76-10-01, LMM 76-10-01

761330		NO. 1 ENGINE - ENGINE (DEEC) COMPUTER					Component	ATA:76
PN:2118882-1008	MOS/MSC	25-Jan-05	O/C	TSN 0				
SN:124-AW0049	HRS	0		TSN 0				
	ENC	0		TSN 0				

PROC. REF: LMM 76-10-02, LMM 76-10-02, LMM 76-10-02

761330		NO. 2 ENGINE - ENGINE (DEEC) COMPUTER					Component	ATA:76
PN:2118882-1008	MOS/MSC	26-Jan-05	O/C	TSN 0				
SN:124-AW0054	HRS	0		TSN 0				
	ENC	0		TSN 0				

PROC. REF: LMM 76-10-02, LMM 76-10-02, LMM 76-10-02

761330A		NO. 1 ENGINE - DOWNLOAD ENGINE (DEEC) COMPUTER ECTM					Service	ATA:76
PN:2118882-1008	MOS/MSC	03-Oct-19	A/R					
SN:124-AW0049	HRS	7680.1						
	ENC	6230						

PROC. REF: MSC CAMP EHM ADENDUM, LMM 76-10-02, LMM 72-00-00

761330A		NO. 2 ENGINE - DOWNLOAD ENGINE (DEEC) COMPUTER ECTM					Service	ATA:76
PN:2118882-1008	MOS/MSC	03-Oct-19	A/R					
SN:124-AW0054	HRS	7680.1						
	ENC	6230						

PROC. REF: MSC CAMP EHM ADENDUM, LMM 76-10-02, LMM 72-00-00

Y7600000 ⁹		ENGINE DEEC WIRE HARNESS SHIELD OVERBRAIDS AND SHIELD TERMINATIONS - PERFORM VISUAL INSPECTION.					Service	ATA:76
	MOS	11-Mar-22	48 (+14d/-14d)					
	HRS	8721.2	1200 (+25/-25)					
	AFL	7006						

PROC. REF: GENERIC NO REF

PKG:15

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 76 - ENGINE CONTROLS										
Y7600001^S THRUST LEVER CONTROL MODULE - PERFORM FUNCTIONAL TEST Service ATA:76										
	MOS	11-Mar-22	48 (+14d/-14d)							
	HRS	8721.2	1200 (+25/-25)							
	AFL	7006								
PROC. REF: AMM 76-10-02										PKG:13
Y7610007^S ENGINE CONTROL CABLES - PERFORM VISUAL INSPECTION OF FORWARD AND AFT CABLE CONNECTION. Service ATA:76										
	MOS	11-Mar-22	48 (+14d/-14d)							
	HRS	8721.2	1200 (+25/-25)							
	AFL	7006								
PROC. REF: GENERIC NO REF										PKG:14
ATA 77 - ENGINE INDICATING										
774001 ENGINE VIBRATION MONITOR BOX Component ATA:77										
PN:241-241-000-501	MOS/MSC	25-Jan-15	O/C							
SN:0173	HRS	6669.27								
	AFL	5419								
PROC. REF: AMM 77-41-01										
Y7741000^S ENGINE VIBRATION MONITORING SYSTEM - PERFORM FUNCTIONAL TEST. Service ATA:77										
	MOS	10-May-23	96 (+14d/-14d)							
	HRS	9071.3	2400 (+25/-25)							
	AFL	7252								
PROC. REF: AMM 77-41-00										PKG:21
ATA 78 - EXHAUST										
783001 LEFT LOWER THRUST REVERSER Component ATA:78										
PN:PN	MOS/MSC	10-May-05	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 78-31-00										
783001 LEFT UPPER THRUST REVERSER Component ATA:78										
PN:LJ7830101-5	MOS/MSC	10-May-05	O/C	TSN 0						
SN:A30040305	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 78-31-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 78 - EXHAUST										
783002	RIGHT LOWER THRUST REVERSER									Component ATA:78
PN:PN	MOS/MSC	10-May-05	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 78-31-00										
783002	RIGHT UPPER THRUST REVERSER									Component ATA:78
PN:LJ7830101-6	MOS/MSC	10-May-23	O/C							
SN:A30040305	HRS	9071.3								
	AFL	7252								
PROC. REF: AMM 78-31-00										
783031	NO. 1 ASSEMBLY, THRUST REVERSER CONTROL BOX									Component ATA:78
PN:LJ7836704-17	MOS/MSC	26-Jul-24	O/C							
SN:OBTE30584	HRS	9450.9								
	AFL	7531								
PROC. REF: GENERIC NO REF										
783032	NO. 2 ASSEMBLY, THRUST REVERSER CONTROL BOX									Component ATA:78
PN:6678300000-003	MOS/MSC	28-Mar-11	O/C							
SN:OBTE30547	HRS	4114.93								
	AFL	3365								
PROC. REF: GENERIC NO REF										
783101	LEFT THRUST REVERSER ISOLATION VALVE									Component ATA:78
PN:LJ7835200-5	MOS/MSC	25-Jan-22	O/C	TSO 0						
SN:0590	HRS	8706.9		TSO 0						
	AFL	6996		TSO 0						
PROC. REF: AMM 78-30-02										
783102	RIGHT THRUST REVERSER ISOLATION VALVE									Component ATA:78
PN:71556-8	MOS/MSC	15-Dec-09	O/C							
SN:0814	HRS	3106.15								
	AFL	2571								
PROC. REF: AMM 78-30-02										
D7830078 ^S	** THRUST REVERSER SYSTEM THROTTLE RETARD ACTUATOR - PERFORM OPERATIONAL CHECK (AWL**)									Service ATA:78
	MOS	10-May-23	96 (+14d/-14d)					AIRWORTHINESS		
	HRS	9071.3	2400 (+25/-25)							
	AFL	7252								
PROC. REF: AMM 78-32-40										
PKG:21										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 78 - EXHAUST											
H7830081 ^S			THRUST REVERSERS - REMOVE LINK ROD ASSEMBLIES AND PERFORM MAGNETIC PARTICLE INSPECTION						Service	ATA:78	
	MOS	10-May-23	96 (+14d/-14d)								
	HRS	9071.3	2400 (+25/-25)								
	AFL	7252									
			PROC. REF: NDT PART 7/78-30-01								PKG:21
H7830082 ^S			THRUST REVERSERS - REMOVE THRUST REVERSER DOOR ASSEMBLIES AND PERFORM EDDY CURRENT INSPECTION OF PIVOT FITTING AND DOOR HINGES						Service	ATA:78	
	MOS	10-May-23	96 (+14d/-14d)								
	HRS	9071.3	2400 (+25/-25)								
	AFL	7252									
			PROC. REF: NDT PART 6/78-30-02, NDT PART 6/78-30-03								PKG:21
Y7830000 ^S			EXHAUST NOZZLE - PERFORM VISUAL INSPECTION.						Service	ATA:78	
	MOS	10-May-23	96 (+14d/-14d)								
	HRS	9071.3	2400 (+25/-25)								
	AFL	7252									
			PROC. REF: GENERIC NO REF								PKG:21
Y7830001 ^S			THRUST REVERSER INNER FAN DUCT ASSEMBLY -PERFORM VISUAL INSPECTION. INSPECT FROM EXHAUST END ONLY.						Service	ATA:78	
	MOS	11-Mar-22	48 (+14d/-14d)								
	HRS	8721.2	1200 (+25/-25)								
	AFL	7006									
			PROC. REF: GENERIC NO REF								PKG:15
Y7830002 ^S			THRUST REVERSER DOOR AND HINGE FITTINGS - PERFORM VISUAL INSPECTION.						Service	ATA:78	
	MOS	11-Mar-22	48 (+14d/-14d)								
	HRS	8721.2	1200 (+25/-25)								
	AFL	7006									
			PROC. REF: GENERIC NO REF								PKG:15
Y7830003 ^S			THRUST REVERSER PRIMARY ACTUATOR AND LATCH ASSEMBLY - PERFORM VISUAL INSPECTION.						Service	ATA:78	
	MOS	11-Mar-22	48 (+14d/-14d)								
	HRS	8721.2	1200 (+25/-25)								
	AFL	7006									
			PROC. REF: GENERIC NO REF								PKG:15
Y7830004 ^S			THRUST REVERSER HYDRAULIC CONTROL VALVE (HCV), THROTTLE RETARD ACTUATOR, AND ASSOCIATED PLUMBING - PERFORM VISUAL INSPECTION.						Service	ATA:78	
	MOS	11-Mar-22	48 (+14d/-14d)								
	HRS	8721.2	1200 (+25/-25)								
	AFL	7006									
			PROC. REF: GENERIC NO REF								PKG:15

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 78 - EXHAUST										
Y7830005^S THRUST REVERSER DOOR SEALS AND RETAINERS - PERFORM VISUAL INSPECTION. Service ATA:78										
	MOS	11-Mar-22	48 (+14d/-14d)							
	HRS	8721.2	1200 (+25/-25)							
	AFL	7006								
PROC. REF: GENERIC NO REF										PKG:15
Y7830006^S THRUST REVERSER WIRE HARNESS - PERFORM VISUAL INSPECTION. Service ATA:78										
	MOS	11-Mar-22	48 (+14d/-14d)							
	HRS	8721.2	1200 (+25/-25)							
	AFL	7006								
PROC. REF: GENERIC NO REF										PKG:15
ATA 79 - OIL										
790110 NO. 1 ENGINE - OIL PUMP Component ATA:79										
PN:3060785-3	MOS/MSC	25-Jan-05	O/C	TSN 0						
SN:061405700706	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 79-20-03										
790110 NO. 2 ENGINE - OIL PUMP Component ATA:79										
PN:3060785-3	MOS/MSC	26-Jan-05	O/C	TSN 0						
SN:081405700019	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 79-20-03										
790130^S NO. 1 ENGINE - ANALYSIS OIL AND FILTER (SOAP) Service ATA:79										
	MOS	16-Oct-24								
	HRS	9408.6	150 (+100)							
	ENC	7526								
PROC. REF: LMM 72-00-00										PKG:0
790130^S NO. 2 ENGINE - ANALYSIS OIL AND FILTER (SOAP) Service ATA:79										
	MOS	16-Oct-24								
	HRS	9408.6	150 (+100)							
	ENC	7526								
PROC. REF: LMM 72-00-00										PKG:0
790140^S NO. 1 ENGINE - PERFORM OIL CHANGE Service ATA:79										
	MOS	03-Sep-21								
	HRS	8351.1	1200 (+100/-200)							
	ENC	6753								
PROC. REF: LMM 72-00-00										PKG:0

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 79 - OIL											
790140 ^S		NO. 2 ENGINE - PERFORM OIL CHANGE								Service	ATA:79
	MOS	03-Sep-21									
	HRS	8351.1	1200 (+100/-200)								
	ENC	6753									
PROC. REF: LMM 72-00-00										PKG:0	
790150 ^S		NO. 1 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION AND PERFORM RESISTANCE CHECK								Service	ATA:79
	MOS	10-May-23									
	HRS	8987.3	600 (+50/-100)								
	ENC	7218									
PROC. REF: LMM 79-10-01, LMM 79-10-01										PKG:0	
790150 ^S		NO. 2 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION AND PERFORM RESISTANCE CHECK								Service	ATA:79
	MOS	10-May-23									
	HRS	8987.3	600 (+50/-100)								
	ENC	7218									
PROC. REF: LMM 79-10-01, LMM 79-10-01										PKG:0	
790160 ^S		NO. 1 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION								Service	ATA:79
	MOS	16-Oct-24									
	HRS	9408.6	150 (+100)								
	ENC	7526									
PROC. REF: LMM 79-10-01, LMM 79-10-01										PKG:0	
790160 ^S		NO. 2 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION								Service	ATA:79
	MOS	16-Oct-24									
	HRS	9408.6	150 (+100)								
	ENC	7526									
PROC. REF: LMM 79-10-01, LMM 79-10-01										PKG:0	
792008		NO. 1 ENGINE - OIL FLOW REDUCTION VALVE								Component	ATA:79
PN:3060769-1	MOS/MSC	25-Jan-05	O/C	TSN 0							
SN:040645103627	HRS	0									
	ENC	0									
PROC. REF: LMM 79-20-08											
792008		NO. 2 ENGINE - OIL FLOW REDUCTION VALVE								Component	ATA:79
PN:3060769-1	MOS/MSC	26-Jan-05	O/C	TSN 0							
SN:040645103617	HRS	0									
	ENC	0									
PROC. REF: LMM 79-20-08											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 79 - OIL										
792260	NO. 1 ENGINE - OIL TEMPERATURE CONTROL VALVE									Component ATA:79
PN:158465-6	MOS/MSC	25-Jan-05	O/C	TSN 0						
SN:11615	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 79-30-01										
792260	NO. 2 ENGINE - OIL TEMPERATURE CONTROL VALVE									Component ATA:79
PN:158465-6	MOS/MSC	26-Jan-05	O/C	TSN 0						
SN:11614	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 79-30-01										
793064	NO. 1 ENGINE - TEMP BULB									Component ATA:79
PN:MS28034-3	MOS/MSC	25-Jan-05	O/C	TSN 0						
SN:H8987	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
793064	NO. 2 ENGINE - TEMP BULB									Component ATA:79
PN:MS28034-3	MOS/MSC	26-Jan-05	O/C	TSN 0						
SN:J5959	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
793315 ^S	NO. 1 ENGINE - CHECK OIL FILTER BYPASS VALVE CIRCUIT/THERMAL LOCKOUT SWITCH									Service ATA:79
	MOS	03-Sep-21								
	HRS	8351.1	1200 (+100/-200)							
	ENC	6753								
PROC. REF: LMM 79-30-01										
793315 ^S	NO. 2 ENGINE - CHECK OIL FILTER BYPASS VALVE CIRCUIT/THERMAL LOCKOUT SWITCH									Service ATA:79
	MOS	03-Sep-21								
	HRS	8351.1	1200 (+100/-200)							
	ENC	6753								
PROC. REF: LMM 79-30-01										
793320	NO. 1 ENGINE - FUEL HEATER / OIL COOLER ASSEMBLY									Component ATA:79
PN:3060709-4	MOS/MSC	25-Jan-05	O/C	TSN 0						
SN:1897	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 79-20-07										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9515.7 AFL: 7576 As Of: 11-Nov-2024

15-Nov-2024 12:16 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 79 - OIL										
793320	NO. 2 ENGINE - FUEL HEATER / OIL COOLER ASSEMBLY									Component ATA:79
PN:3060709-4	MOS/MSC	26-Jan-05	O/C	TSN 0						
SN:1895	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: LMM 79-20-07										