

Status Report

EMB-135BJ - LEGACY
600

S/N 14501007 N317PJ

OWNER: PRIVATE JETS INC.
ADDRESS: 7200 NW 63RD STREET
BETHANY OK 73008
OFFICE: 405-681-4466
FAX: 405-681-1661

OPERATOR: PRIVATE JETS INC.
ADDRESS: 7200 NW 63RD STREET
BETHANY OK 73008
OFFICE: 405-681-4466
FAX: 405-681-1661

ANALYST: ADRIAN SABOU
EMAIL: ASABOU@CAMPSYSTEMS.COM

+1-514-448-1151 (DIRECT)
+1-631-588-3200 (MAIN)
WWW.CAMPSYSTEMS.COM

800-787-9749 (EFAX-CARDS)
631-980-4222 (EFAX-CARDS)

PLEASE REACH OUT TO YOUR ANALYST TO
RECORD CHANGES TO ADDRESS, LAST ACTUALS
(IF ANY).

AIRCRAFT	SERIAL/REGNO: 14501007/N317PJ	MODEL: EMB-135BJ - LEGACY 600	MANUFACTURER: EMBRAER
-----------------	-------------------------------	-------------------------------	-----------------------

CERTIFICATION DATE: 27-AUG-2007

LAST ACTUALS:
10595.6 A/C HRS as of 11-NOV-2024
5649 AFL as of 11-NOV-2024
5758 APH as of 22-OCT-2024

APU	SERIAL/PART: SP-E0614882/4504113A	MODEL: T-62T-40C14	MANUFACTURER: PRATT & WHITNEY CANADA CORP.
------------	-----------------------------------	--------------------	--

INSTALLED ON: 10-FEB-2017
2952.1 APU HRS 8094.9 A/C HRS
2686 APUS

LAST ACTUALS:
5758 APU HRS as of 22-OCT-2024
5023 APUS as of 22-OCT-2024

ENGINE NO. 1	SERIAL/PART: CAE312988/23074862	MODEL: AE 3007A1E	MANUFACTURER: ROLLS-ROYCE DERBY PLC
---------------------	---------------------------------	-------------------	-------------------------------------

INSTALLED ON: 25-SEP-2007
0 ENG. HRS 0 A/C HRS
0 ENC

LAST ACTUALS:
10491.4 ENG. HRS as of 11-NOV-2024
5577 ENC as of 11-NOV-2024

ENGINE NO. 2	SERIAL/PART: CAE312989/23074862	MODEL: AE 3007A1E	MANUFACTURER: ROLLS-ROYCE DERBY PLC
---------------------	---------------------------------	-------------------	-------------------------------------

INSTALLED ON: 25-SEP-2007
0 ENG. HRS 0 A/C HRS
0 ENC

LAST ACTUALS:
10491.4 ENG. HRS as of 11-NOV-2024
5577 ENC as of 11-NOV-2024



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 00 - INFORMATION										
A135-160301	APU - REVIEW T-62T-40C14 EM REV 13									Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS		
	HRS									
	APUS									
PROC. REF: RCF A135										
E135-160422	REVIEW EMBRAER 135 (LEGACY 600/650) SMRD-1533, TR 11-2 DATED APRIL 22/16 AND MPG-1483, TR 11-3 DATED APRIL 22/16 - REQUIREMENT CHANGE FORM									Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS		
	HRS									
	AFL									
PROC. REF: RCF E135										
E135-160829	REVIEW EMBRAER 135 - LEGACY 600/650 (E135) MISCELLANOUS CORRECTIONS REQUIREMENT SUMMARY CHANGE FORM									Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS		
	HRS									
	AFL									
PROC. REF: RCF E135										
E135-200623	REVIEW EMBRAER LEGACY 600/650 MPG AND SMRD TR 14-2 DATED JUNE 23, 2020									Service ATA:00
	MOS/MSC	27-Aug-07	-					REQUIREMENT CHANGE FORMS		
	HRS	0								
	AFL	0								
PROC. REF: RCF 00										
E135-210629-MPG-SMRD	REVIEW LEGACY 600/650 MAINTENANCE PLANNING GIUDE (MPG) AND SCHEDULED MAINTENANCE REQUIREMENTS DOCUMENT (SMRD) REVISION 15, DATED 29 JUNE, 2021									Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS		
	HRS									
	AFL									
PROC. REF: RCF 00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 00 - INFORMATION										
E135-220517-CAMP ADJUSTMENT					REVIEW CAMP ADJUSTMENT FORM DATED MAY 17/2022 FOR EMB-135BJ - LEGACY 600/650					Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS		
	HRS									
	AFL									
					PROC. REF: RCF 00					
E135-220823-CAMP ADJUSTMENT					REVIEW CAMP ADJUSTMENT FORM DATED AUG 23/2022 FOR EMB-135BJ - LEGACY 600/650					Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS		
	HRS									
	AFL									
					PROC. REF: RCF 00					
E135-220908-CAMP ADJUSTMENT					REVIEW CAMP ADJUSTMENT FORM DATED SEP 08/2022 FOR EMB-135BJ - LEGACY 600/650					Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS		
	HRS									
	AFL									
					PROC. REF: RCF 00					
E135-230313-MPG-SMRD					REVIEW LEGACY 600/650 MAINTENANCE PLANNING GIUDE (MPG) AND SCHEDULED MAINTENANCE REQUIREMENTS DOCUMENT (SMRD) REVISION 16, DATED MAR 13/2023					Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS		
	HRS									
	AFL									
					PROC. REF: RCF 00, RCF 00					
E135-230404-TR					REVIEW LEGACY 600/650 MAINTENANCE PLANNING GIUDE (MPG) TEMPORARY REVISION 16-1, DATED 04 APRIL, 2023					Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS		
	HRS									
	AFL									
					PROC. REF: RCF -					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 00 - INFORMATION										
E135-230411-TR	REVIEW LEGACY 600/650 SCHEDULED MAINTENANCE REQUIREMENTS DOCUMENT (SMRD) TEMPORARY REVISION 16-1, DATED 11 APRIL, 2023								Service	ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS		
	HRS									
	AFL									
					PROC. REF: RCF --					
E135-230425-CAMP ADJUSTMENT	REVIEW CAMP ADJUSTMENT FORM DATED APR 25/2023 FOR EMB-135BJ - LEGACY 600/650								Service	ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS		
	HRS									
	AFL									
					PROC. REF: RCF 00					
E307-160420	NO. 1 ENGINE - REVIEW AE3007A MM REV 78								Service	ATA:00
	MOS/MSC	29-Aug-16	-					REQUIREMENT CHANGE FORMS		
	HRS	7760.1								
	ENC	4148								
					PROC. REF: RCF E307					
E307-160420	NO. 2 ENGINE - REVIEW AE3007A MM REV 78								Service	ATA:00
	MOS/MSC	29-Aug-16	-					REQUIREMENT CHANGE FORMS		
	HRS	7760.1								
	ENC	4148								
					PROC. REF: RCF E307					
E307-160720	NO. 1 ENGINE - REVIEW AE3700A MM REV 79								Service	ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS		
	HRS									
	ENC									
					PROC. REF: RCF E307					
E307-160720	NO. 2 ENGINE - REVIEW AE3700A MM REV 79								Service	ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS		
	HRS									
	ENC									
					PROC. REF: RCF E307					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS										
05-LU06	LOW UTILIZATION-LU6									Package ATA:05
	MOS/MSC	14-Jan-21	N/A	Adj -15d						
	HRS	9507.9								
	AFL	5060								
	PROC. REF: GENERIC NO REF									PKG:5001
05-LU12	LOW UTILIZATION-LU12									Package ATA:05
	MOS	16-Aug-24	12 (+15d/-15d)	Adj -18d	29-Jul-25	13-Aug-25	256 d (+15)	LOW UTILIZATION		
	HRS	10541.4	500 (+20/-20)		11041.4		11061.4	445.8 (+20)		
	AFL	5613								
	PROC. REF: SMRD SECTION II									PKG:5002
05-LU24	LOW UTILIZATION-LU24									Package ATA:05
	MOS	29-Jun-23	24 (+15d/-15d)		29-Jun-25	14-Jul-25	226 d (+15)	LOW UTILIZATION		
	HRS	10161.5	1000 (+20/-20)		11161.5		11181.5	565.9 (+20)		
	AFL	5401								
	PROC. REF: SMRD SECTION II									PKG:5004
05-LU24T96	THRESHOLD 96 MOS LOW UTILIZATION-LU24									Package ATA:05
	MOS	29-Jun-23	24 (+15d/-15d)		29-Jun-25	14-Jul-25	226 d (+15)	LOW UTILIZATION		
	HRS	10161.5	1000 (+20/-20)		11161.5		11181.5	565.9 (+20)		
	AFL	5401								
	PROC. REF: SMRD SECTION II									PKG:5007
05-LU48	LOW UTILIZATION-LU48									Package ATA:05
	MOS	29-Jun-23	48 (+15d/-15d)		29-Jun-27	14-Jul-27	956 d (+15)	LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)		12161.5		12181.5	1565.9 (+20)		
	AFL	5401	1000 (+20/-20)		6401		6421	752 (+20)		
	PROC. REF: SMRD SECTION II									PKG:5008
05-LU48T96	THRESHOLD 96 MOS LOW UTILIZATION-LU48									Package ATA:05
	MOS	29-Jun-23	48 (+15d/-15d)		29-Jun-27	14-Jul-27	956 d (+15)	LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)		12161.5		12181.5	1565.9 (+20)		
	AFL	5401	1000 (+20/-20)		6401		6421	752 (+20)		
	PROC. REF: SMRD SECTION II									PKG:5009

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS										
05-LU48T192	THRESHOLD 192 MOS LOW UTILIZATION-LU48									Package ATA:05
	MOS	29-Jun-23	48 (+15d/-15d)		29-Jun-27	14-Jul-27	956 d (+15)	LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)		12161.5	12181.5	1565.9 (+20)			
	AFL	5401	1000 (+20/-20)		6401	6421	752 (+20)			
PROC. REF: SMRD SECTION II										PKG:5010
05-LU48T288	THRESHOLD 288 MOS LOW UTILIZATION-LU48									Package ATA:05
	MOS	29-Jun-23	48 (+15d/-15d)		29-Jun-27	14-Jul-27	956 d (+15)	LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)		12161.5	12181.5	1565.9 (+20)			
	AFL	5401	1000 (+20/-20)		6401	6421	752 (+20)			
PROC. REF: SMRD SECTION II										PKG:5011
05-LU72	LOW UTILIZATION-LU72									Package ATA:05
	MOS	06-Jul-19	72 (+15d/-15d)	Adj 52d	27-Aug-25	11-Sep-25	285 d (+15)	LOW UTILIZATION		
	HRS	9057.4	3000 (+20/-20)		12057.4	12077.4	1461.8 (+20)			
	AFL	4853	1500 (+20/-20)		6353	6373	704 (+20)			
PROC. REF: SMRD SECTION II										PKG:5012
05-LU96	LOW UTILIZATION-LU96									Package ATA:05
	MOS	29-Jun-23	96 (+15d/-15d)		29-Jun-31	14-Jul-31	2417 d (+15)	LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)		14161.5	14181.5	3565.9 (+20)			
	AFL	5401	2000 (+20/-20)		7401	7421	1752 (+20)			
PROC. REF: SMRD SECTION II										PKG:5016
05-LU96T192	THRESHOLD 192 MOS LOW UTILIZATION-LU96									Package ATA:05
	MOS	29-Jun-23	96 (+15d/-15d)		29-Jun-31	14-Jul-31	2417 d (+15)	LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)		14161.5	14181.5	3565.9 (+20)			
	AFL	5401	2000 (+20/-20)		7401	7421	1752 (+20)			
PROC. REF: SMRD SECTION II										PKG:5017
05-LU96T288	THRESHOLD 288 MOS LOW UTILIZATION-LU96									Package ATA:05
	MOS	27-Aug-07	T:288 (+15d/-15d)		27-Aug-31	11-Sep-31	2476 d (+15)	LOW UTILIZATION		
	HRS	0	T:12000 (+20/-20)		12000	12020	1404.4 (+20)			
	AFL	0	T:6000 (+20/-20)		6000	6020	351 (+20)			
PROC. REF: SMRD SECTION II										PKG:5018

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS										
05-LU144	LOW UTILIZATION-LU144									Package ATA:05
	MOS	06-Jul-19	144 (+15d/-15d)	Adj 52d	27-Aug-31	11-Sep-31	2476 d (+15)	LOW UTILIZATION		
	HRS	9057.4	6000 (+20/-20)		15057.4	15077.4	4461.8 (+20)			
	AFL	4853	3000 (+20/-20)		7853	7873	2204 (+20)			
PROC. REF: SMRD SECTION II										PKG:5024
05-LU144T288	THRESHOLD 288 MOS LOW UTILIZATION-LU144									Package ATA:05
	MOS	27-Aug-07	T:288 (+15d/-15d)		27-Aug-31	11-Sep-31	2476 d (+15)	LOW UTILIZATION		
	HRS	0	T:12000 (+20/-20)		12000	12020	1404.4 (+20)			
	AFL	0	T:6000 (+20/-20)		6000	6020	351 (+20)			
PROC. REF: SMRD SECTION II										PKG:5025
05-LU192	LOW UTILIZATION-LU192									Package ATA:05
	MOS	02-Jul-15	192 (+15d/-15d)	Adj 56d	27-Aug-31	11-Sep-31	2476 d (+15)	LOW UTILIZATION		
	HRS	7460.3	8000 (+20/-20)		15460.3	15480.3	4864.7 (+20)			
	AFL	3992	4000 (+20/-20)		7992	8012	2343 (+20)			
PROC. REF: SMRD SECTION II										PKG:5032
05-LU288	LOW UTILIZATION-LU288									Package ATA:05
	MOS	27-Aug-07	288 (+15d/-15d)		27-Aug-31	11-Sep-31	2476 d (+15)	LOW UTILIZATION		
	HRS	0	12000 (+20/-20)		12000	12020	1404.4 (+20)			
	AFL	0	6000 (+20/-20)		6000	6020	351 (+20)			
PROC. REF: SMRD SECTION II										PKG:5140
05-00-CUS-1000 ^U	PERFORM ANNUAL AVIONICS RAMP CHECK									Service ATA:05
	MOS	16-Aug-24	12		16-Aug-25		274 d	CUSTOMER CODE		
	HRS	10541.4								
	AFL	5613								
05-00-CUS-1004 ^U	RENEW AIRCRAFT REGISTRATION									Service ATA:05
	MOS	25-Jan-24	36 (+1m/-2m)		25-Jan-27	25-Feb-27	801 d (+31)			
	HRS									
	AFL									
05-00-CUS-1005 ^U	RENEW ELT REGISTRATION									Service ATA:05
	MOS	11-Jan-23	24		11-Jan-25 (M)		57 d			
	HRS	10066.9								
	AFL	5346								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS											
05-50-01-200-801		LIGHTNING STRIKE - GENERAL INSPECTION								Service	ATA:05
	MOS/MSC	27-Aug-07	A/R								
	HRS	0									
	AFL	0									
PROC. REF: AMM 05-50-01											
05-50-01-200-802		FORWARD FUSELAGE AND NOSE LANDINGGEAR - DETAILED INSPECTION								Service	ATA:05
	MOS/MSC	27-Aug-07	A/R								
	HRS	0									
	AFL	0									
PROC. REF: AMM 05-50-01											
05-50-01-200-803		CENTER FUSELAGE MAIN LANDINGGEARS AND WING STUB - INSPECTION								Service	ATA:05
	MOS/MSC	27-Aug-07	A/R								
	HRS	0									
	AFL	0									
PROC. REF: AMM 05-50-01											
05-50-01-200-804		WINGS - DETAILED INSPECTION								Service	ATA:05
	MOS/MSC	27-Aug-07	A/R								
	HRS	0									
	AFL	0									
PROC. REF: AMM 05-50-01											
05-50-01-200-805		ENGINE NACELLE - DETAILED INSPECTION								Service	ATA:05
	MOS/MSC	27-Aug-07	A/R								
	HRS	0									
	AFL	0									
PROC. REF: AMM 05-50-01											
05-50-01-200-806		REAR FUSELAGE AND EMPENNAGE -DETAILED INSPECTION								Service	ATA:05
	MOS/MSC	27-Aug-07	A/R								
	HRS	0									
	AFL	0									
PROC. REF: AMM 05-50-01											
05-50-02-200-801		OVERWEIGHT LANDING OR HARDLANDING								Service	ATA:05
	MOS/MSC	27-Aug-07	A/R								
	HRS	0									
	AFL	0									
PROC. REF: AMM 05-50-02											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS											
05-50-03-200-801		HIGH DRAG/SIDE LOAD LANDING CONDITION							Service	ATA:05	
	MOS/MSC	27-Aug-07	A/R								
	HRS	0									
	AFL	0									
PROC. REF: AMM 05-50-03											
05-50-04-200-801		OVERSPEED INSPECTION							Service	ATA:05	
	MOS/MSC	27-Aug-07	A/R								
	HRS	0									
	AFL	0									
PROC. REF: AMM 05-50-04											
05-50-04-200-802		ON-GROUND GALE-FORCE WINDS							Service	ATA:05	
	MOS/MSC	27-Aug-07	A/R								
	HRS	0									
	AFL	0									
PROC. REF: AMM 05-50-04											
05-50-04-200-803		SEVERE TURBULENCE OR BUFFETINGCONDITION							Service	ATA:05	
	MOS/MSC	27-Aug-07	A/R								
	HRS	0									
	AFL	0									
PROC. REF: AMM 05-50-04											
05-50-05-200-801		HIGH-LOAD-FACTOR FLIGHT CONDITION							Service	ATA:05	
	MOS/MSC	27-Aug-07	A/R								
	HRS	0									
	AFL	0									
PROC. REF: AMM 05-50-05											
05-50-06-200-801		LANDING GEAR DOWN OVERSPEED							Service	ATA:05	
	MOS/MSC	27-Aug-07	A/R								
	HRS	0									
	AFL	0									
PROC. REF: AMM 05-50-06											
05-50-07-200-801		MAXIMUM FLAP EXTENDED SPEED							Service	ATA:05	
	MOS/MSC	27-Aug-07	A/R								
	HRS	0									
	AFL	0									
PROC. REF: AMM 05-50-07											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS											
05-50-08-200-801		BIRD STRIKE AND HAILSTORM							Service	ATA:05	
	MOS/MSC	27-Aug-07	A/R								
	HRS	0									
	AFL	0									
PROC. REF: AMM 05-50-08											
05-50-09-200-801		ENGINE FIRE WARNING							Service	ATA:05	
	MOS/MSC	27-Aug-07	A/R								
	HRS	0									
	AFL	0									
PROC. REF: AMM 05-50-09											
05-50-10-200-801		ICING OR SNOWING INSPECTION							Service	ATA:05	
	MOS/MSC	27-Aug-07	A/R								
	HRS	0									
	AFL	0									
PROC. REF: AMM 05-50-10											
05-50-11-200-801		APU FIRE WARNING							Service	ATA:05	
	MOS/MSC	27-Aug-07	A/R								
	HRS	0									
	AFL	0									
PROC. REF: AMM 05-50-11											
05-50-12-100-801		TOILET OVERSERVICING - CLEANING							Service	ATA:05	
	MOS/MSC	27-Aug-07	A/R								
	HRS	0									
	AFL	0									
PROC. REF: AMM 05-50-12											
05-50-12-200-801		TOILET OVERSERVICING - INSPECTION							Service	ATA:05	
	MOS/MSC	27-Aug-07	A/R								
	HRS	0									
	AFL	0									
PROC. REF: AMM 05-50-12											
05-50-13-700-801		AIRCRAFT RECONFIGURATION - CHECK							Service	ATA:05	
	MOS/MSC	27-Aug-07	A/R								
	HRS	0									
	AFL	0									
PROC. REF: AMM 05-50-13											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS											
05-50-14-200-801		OVERHEAT WHEELS								Service	ATA:05
	MOS/MSC	27-Aug-07	A/R								
	HRS	0									
	AFL	0									
PROC. REF: AMM 05-50-14											
05-50-15-200-801		LANDING-GEAR TIRE TREAD FAILURE -EXTENDED LANDING GEAR								Service	ATA:05
	MOS/MSC	27-Aug-07	A/R								
	HRS	0									
	AFL	0									
PROC. REF: AMM 05-50-15											
05-50-15-200-802		LANDING-GEAR TIRE TREAD FAILURE -RETRACTED LANDING GEAR								Service	ATA:05
	MOS/MSC	27-Aug-07	A/R								
	HRS	0									
	AFL	0									
PROC. REF: AMM 05-50-15											
05-50-16-200-801		HIGH ENERGY STOP - INSPECTION								Service	ATA:05
	MOS/MSC	27-Aug-07	A/R								
	HRS	0									
	AFL	0									
PROC. REF: AMM 05-50-16											
05-50-18-200-801		VOLCANIC ASH CONDITION								Service	ATA:05
	MOS/MSC	27-Aug-07	A/R								
	HRS	0									
	AFL	0									
PROC. REF: AMM 05-50-18											
05-50-19-960-801		APU FUEL INLET FILTER - INSPECTION								Service	ATA:05
	MOS/MSC	27-Aug-07	A/R								
	HRS	0									
	AFL	0									
PROC. REF: AMM 05-50-19											
05-50-20-200-801		FORWARD POCKET DOOR RESETTING -INSPECTION								Service	ATA:05
	MOS/MSC	27-Aug-07	A/R								
	HRS	0									
	AFL	0									
PROC. REF: AMM 05-50-20											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS										
05-50-23-200-801	BRAKE USE DURING TOWBARLESSTOWING OPERATION									Service ATA:05
	MOS/MSC	27-Aug-07	A/R							
	HRS	0								
	AFL	0								
PROC. REF: AMM 05-50-23										
05-50-24-200-801	LH/RH STATIC PORTS VICINITY - INSPECTION									Service ATA:05
	MOS/MSC	27-Aug-07	A/R							
	HRS	0								
	AFL	0								
PROC. REF: AMM 05-50-24										
05-50-32-200-801	OVERSTEERING - GENERAL VISUAL INSPECTION									Service ATA:05
	MOS/MSC	27-Aug-07	A/R							
	HRS	0								
	AFL	0								
PROC. REF: AMM 05-50-32										
055013	NO. 1 ENGINE - FLUSH THE ENGINE AFTER A FIRE-EXTINGUISHING AGENT DISCHARGE									Service ATA:05
	MOS/MSC	25-Sep-07	A/R							
	HRS	0								
	ENC	0								
PROC. REF: MM 05-50-00										
055013	NO. 2 ENGINE - FLUSH THE ENGINE AFTER A FIRE-EXTINGUISHING AGENT DISCHARGE									Service ATA:05
	MOS/MSC	25-Sep-07	A/R							
	HRS	0								
	ENC	0								
PROC. REF: MM 05-50-00										
MRA-003344 ^U	PERFORM INSPECTION FOR THE ROSEN LCD CABIN BULKHEAD MONITORS									Service ATA:05
	MOS	04-Jan-19	72		04-Jan-25		50 d	CUSTOMER CODE		
	HRS	8912.5								
	AFL	4764								
ATA 08 - LEVELING AND WEIGHING										
08051910 ^U	WEIGHT AND BALANCE AIRCRAFT									Service ATA:08
	MOS	17-May-22	36		17-May-25		183 d			
	HRS	9875.7								
	AFL	5259								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 10 - PARKING, MOORING, STORE AND RET TO SERV										
10-10-02-500-801-A ^U	PERFORM AIRCRAFT PROLONGED PARKING									Service ATA:10
	MOS/MSC		A/R							
	HRS									
	AFL									
10-10-02-500-802-A ^U	PERFORM AIRCRAFT RETURN TO SERVICE AFTER PROLONGED PARKING									Service ATA:10
	MOS/MSC		A/R							
	HRS									
	AFL									
ATA 12 - SERVICING										
12-13-01-610-001-A00	SERVICE (REPLENISH) HYDRAULIC SYSTEM RESERVOIR									Service ATA:12
	MOS	16-Aug-24						SYSTEM		
	HRS	10541.4	250		10791.4		195.8			
	AFL	5613								
	PROC. REF: AMM 12-13-01									
ATA 20 - STANDARD PRACTICES - AIRFRAME										
20-00-00-140-002-A00	RESTORE (CLEANING) CENTER FUSELAGE III LOWER SIDE INCLUDING WIRING, LINES AND OMEGA BEAMS (ZONES: 151, 152, 153, 154, 155, 156, 157).NOTE: EWIS (L650 ONLY)									Service ATA:20
	MOS/MSC	25-Sep-07	N/A					SYSTEM		
	HRS	0								
	AFL	0								
	PROC. REF: AMM 05-40-01									PKG:6016
20-00-00-140-003-A00	RESTORE (CLEANING) CENTER FUSELAGE IV LOWER SIDE INCLUDING WIRING, LINES AND OMEGA BEAMS (ZONES: 161, 162).NOTE: EWIS (L650 ONLY)									Service ATA:20
	MOS/MSC	25-Sep-07	N/A					SYSTEM		
	HRS	0								
	AFL	0								
	PROC. REF: AMM 05-40-02									PKG:6016
20-00-00-140-004-A00	RESTORE (CLEANING) CENTER FUSELAGE IV UPPER AND LATERAL SIDE INCLUDING ELT UNIT (ZONES: 262, 263, 264).NOTE: EWIS (L650 ONLY)									Service ATA:20
	MOS/MSC	25-Sep-07	N/A					SYSTEM		
	HRS	0								
	AFL	0								
	PROC. REF: AMM 05-40-03									PKG:6032

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 20 - STANDARD PRACTICES - AIRFRAME										
20-00-00-140-005-A00	RESTORE (CLEANING) REAR FUSELAGE I LOWER SIDE, INCLUDING WIRING AND LINES (ZONES: 171, 172).NOTE: EWIS (L650 ONLY)									Service ATA:20
	MOS/MSC	25-Sep-07	N/A					SYSTEM		
	HRS	0								
	AFL	0								
					PROC. REF: AMM 05-40-04					PKG:6016
20-00-00-140-006-A00	RESTORE (CLEANING) REAR FUSELAGE I LATERAL SIDE, INCLUDING ELECTRONIC REAR COMPARTMENT WIRING (ZONES: 271, 272).NOTE: EWIS.(L650 ONLY)									Service ATA:20
	MOS/MSC	25-Sep-07	N/A					SYSTEM		
	HRS	0								
	AFL	0								
					PROC. REF: AMM 05-40-05					PKG:6016
20-00-00-140-007-A00	RESTORE (CLEANING) CENTER FUSELAGE II LOWER SIDE INCLUDING WIRING, LINES AND OMEGA BEAMS (ZONES: 141, 142). NOTE: EWIS (L650 ONLY)									Service ATA:20
	MOS/MSC	25-Sep-07	N/A					SYSTEM		
	HRS	0								
	AFL	0								
					PROC. REF: AMM 05-40-10					PKG:6016
20-00-00-140-008-A00	RESTORE (CLEANING) CENTER FUSELAGE I LOWER SIDE INCLUDING WIRING, LINES AND OMEGA BEAMS (ZONES: 131, 132). NOTE: EWIS (L650 ONLY)									Service ATA:20
	MOS/MSC	25-Sep-07	N/A					SYSTEM		
	HRS	0								
	AFL	0								
					PROC. REF: AMM 05-40-14					PKG:6016
20-00-00-140-009-A00	RESTORE (CLEANING) NLG & FWD ELECTRONIC COMPARTMENTS, FWDPRESSURE BULKHEAD UPPER SIDE (ZONES: 113, 114,213, 214, 215, 216).NOTE: EWIS.(L650 ONLY)									Service ATA:20
	MOS/MSC	25-Sep-07	N/A					SYSTEM		
	HRS	0								
	AFL	0								
					PROC. REF: AMM 05-40-11					PKG:6032
20-00-00-140-010-A00	RESTORE (CLEANING) COCKPIT LATERAL SIDE AND FWD PRESSURE BULKHEAD UPPER SIDE (ZONES: 221, 222, 223, 224). NOTE: EWIS (L650 ONLY)									Service ATA:20
	MOS/MSC	25-Sep-07	N/A					SYSTEM		
	HRS	0								
	AFL	0								
					PROC. REF: AMM 05-40-13					PKG:6016

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 20 - STANDARD PRACTICES - AIRFRAME										
20-00-00-140-011-A00	RESTORE (CLEANING) COCKPIT LOWER SIDE AND FWD PRESSURE BULKHEAD LOWER SIDE (ZONES: 121, 122, 123, 124) NOTE: EWIS (L650 ONLY)									Service ATA:20
	MOS/MSC	25-Sep-07	N/A					SYSTEM		
	HRS	0								
	AFL	0								
					PROC. REF: AMM 05-40-12					PKG:6016
20-00-00-212-002-A00	INSPECT (GENERAL VISUAL) CENTER FUSELAGE III LOWER SIDE - EWIS COMPONENTS OF APU AND ENGINES GENERATORS POWER CABLES, HYDRAULIC PUMPS POWER CABLES AND WIRING BUNDLES (ZONES: 151, 152, 153,154, 155, 156, 157).NOTE: EWIS (L650 ONLY)									Service ATA:20
	MOS/MSC	25-Sep-07	N/A					SYSTEM		
	HRS	0								
	AFL	0								
					PROC. REF: AMM 05-40-01					PKG:6016
20-00-00-212-003-A00	INSPECT (GENERAL VISUAL) CENTER FUSELAGE IV LOWER SIDE - EWIS COMPONENTS OF APU AND ENGINES GENERATORS POWER CABLES, HYDRAULIC PUMPS POWER CABLES AND WIRING BUNDLES (ZONES: 161, 162). NOTE: EWIS (L650 ONLY)									Service ATA:20
	MOS/MSC	25-Sep-07	N/A					SYSTEM		
	HRS	0								
	AFL	0								
					PROC. REF: AMM 05-40-02					PKG:6016
20-00-00-212-007-A00	INSPECT (GENERAL VISUAL) REAR FUSELAGE I, PRESSURE BULKHEAD PRESSURIZED AREA SIDE - EWIS COMPONENTS OF APU POWER CABLES AND WIRING BUNDLES (ZONES: 275, 276NOTE: EWIS).(L650 ONLY)									Service ATA:20
	MOS/MSC	25-Sep-07	N/A					SYSTEM		
	HRS	0								
	AFL	0								
					PROC. REF: AMM 05-40-07					PKG:6016
20-00-00-212-008-A00	INSPECT (GENERAL VISUAL) REAR FUSELAGE II, STRUCTURAL AREA AFT OF REAR PRESSURE BULKHEAD - EWIS COMPONENTS OF POWER CABLES AND WIRING BUNDLES (ZONES: 311, 312).NOTE: EWIS (L650 ONLY)									Service ATA:20
	MOS/MSC	25-Sep-07	N/A					SYSTEM		
	HRS	0								
	AFL	0								
					PROC. REF: AMM 05-40-08					PKG:6016
20-00-00-212-011-A00	INSPECT (GENERAL VISUAL) FWD AUXILIARY FUEL TANK FAIRINGS, VENTRAL FUEL TANK FAIRINGS AND WING-TO- FUSELAGE ATTACHMENT FAIRINGS - EWIS COMPONENTS OF WIRING BUNDLES (ZONES: 191, 193, 194, 195, 196,1924 AND 1932)NOTE: EWIS (L650 ONLY)									Service ATA:20
	MOS/MSC	25-Sep-07	N/A					SYSTEM		
	HRS	0								
	AFL	0								
					PROC. REF: AMM 05-40-09					PKG:6016

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 20 - STANDARD PRACTICES - AIRFRAME										
20-00-00-212-012-A00	INSPECT (GENERAL VISUAL) NLG ELECTRONIC COMPARTMENT - EWIS COMPONENTS OF WIRING BUNDLES (ZONES: 113, 114).NOTE: EWIS.(L650 ONLY)									Service ATA:20
	MOS/MSC	25-Sep-07	N/A					SYSTEM		
	HRS	0								
	AFL	0								
					PROC. REF: AMM 05-40-11					PKG:6032
20-00-00-212-013-A00	INSPECT (GENERAL VISUAL) ENGINE PYLON - EWIS COMPONENTS OF ENGINES GENERATORS POWER CABLES AND WIRING BUNDLES (ZONES: 414, 424). NOTE: EWIS (L650 ONLY)									Service ATA:20
	MOS/MSC	25-Sep-07	N/A					SYSTEM		
	HRS	0								
	AFL	0								
					PROC. REF: AMM 05-40-15					
20-00-00-212-014-A00	INSPECT (GENERAL VISUAL) ENGINES - EWIS COMPONENTS OF ENGINES GENERATORS POWER CABLES (ZONES: 415, 425).NOTE: EWIS (L650 ONLY)									Service ATA:20
	MOS/MSC	25-Sep-07	N/A					SYSTEM		
	HRS	0								
	AFL	0								
					PROC. REF: AMM 05-40-18					
20-00-00-212-015-A00	INSPECT (GENERAL VISUAL) WING LEADING EDGE - EWIS COMPONENTS OF WIRING BUNDLES (ZONES: 511, 512,513, 611, 612, 613).NOTE: EWIS (L650 ONLY)									Service ATA:20
	MOS/MSC	25-Sep-07	N/A					SYSTEM		
	HRS	0								
	AFL	0								
					PROC. REF: AMM 24-00-02					PKG:6016
20-00-00-212-016-A00	INSPECT (GENERAL VISUAL) EWIS COMPONENTS OFTRAILING EDGE HARNESS (ZONES: 532, 5711, 5721,5731, 5732, 632, 6711, 6721, 6731, 6732).NOTE: EWIS (L650 ONLY)									Service ATA:20
	MOS/MSC	25-Sep-07	N/A					SYSTEM		
	HRS	0								
	AFL	0								
					PROC. REF: AMM 24-00-03					
20-00-00-212-017-A00	INSPECT (GENERAL VISUAL) WING STUB HARNESS - EWIS COMPONENTS OF WIRING BUNDLES (ZONE 192).NOTE: EWIS (L650 ONLY)									Service ATA:20
	MOS/MSC	25-Sep-07	N/A					SYSTEM		
	HRS	0								
	AFL	0								
					PROC. REF: AMM 24-00-04					PKG:6016

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 20 - STANDARD PRACTICES - AIRFRAME										
20-00-00-212-018-A00	INSPECT (GENERAL VISUAL) REAR FUSELAGE I LOWER SIDE- EWIS COMPONENTS OF APU AND ENGINES GENERATORS POWER CABLES, HYDRAULIC PUMPS POWER CABLES AND WIRING BUNDLES (ZONES: 171, 172). NOTE: EWIS (L650 ONLY)								Service	ATA:20
	MOS/MSC	25-Sep-07	N/A					SYSTEM		
	HRS	0								
	AFL	0								
	PROC. REF: AMM 05-40-04									PKG:6016
20-00-00-212-019-A00	INSPECT (GENERAL VISUAL) REAR FUSELAGE I LATERAL SIDE- EWIS COMPONENTS OF ENGINES GENERATORS POWER CABLES AND WIRING BUNDLES (ZONES: 271, 272). NOTE: EWIS (L650 ONLY)								Service	ATA:20
	MOS/MSC	25-Sep-07	N/A					SYSTEM		
	HRS	0								
	AFL	0								
	PROC. REF: AMM 05-40-05									PKG:6016
20-00-00-220-001-A00	INSPECT (DETAILED INSPECTION) EWIS COMPONENTS OF WING TANK UNIT HARNESS (ZONES: 155, 156, 157, 531, 631, 541, 641).NOTE: EWIS (L650 ONLY)								Service	ATA:20
	MOS/MSC	25-Sep-07	N/A					SYSTEM		
	HRS	0								
	AFL	0								
	PROC. REF: AMM 28-41-03									PKG:6016
20-00-00-220-003-A00	INSPECT (DETAILED INSPECTION) ELECTRIC FUEL PUMP CONNECTOR (ZONES: 155, 156, 157, 531, 631).NOTE: EWIS (L650 ONLY)								Service	ATA:20
	MOS/MSC	25-Sep-07	N/A					SYSTEM		
	HRS	0								
	AFL	0								
	PROC. REF: AMM 28-21-01									PKG:6016
20-00-00-220-006-A00	INSPECT (DETAILED INSPECTION) VENTRAL FUEL TANK - EWIS COMPONENTS OF VENTRAL TANK UNIT HARNESS (ZONE: 1972).NOTE: (L650 ONLY)								Service	ATA:20
	MOS/MSC	25-Sep-07	N/A					SYSTEM		
	HRS	0								
	AFL	0								
	PROC. REF: AMM 28-41-06									PKG:6016
20-00-00-220-008-A00	INSPECT (DETAILED INSPECTION) WING MIDDLE SECTION - EWIS COMPONENTS OF VENT VALVE HARNESS INSIDE THE CONDUIT (ZONES: 541, 641).NOTE: EWIS (L650 ONLY)								Service	ATA:20
	MOS/MSC	25-Sep-07	N/A					SYSTEM		
	HRS	0								
	AFL	0								
	PROC. REF: AMM 28-23-04									PKG:6016

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 20 - STANDARD PRACTICES - AIRFRAME										
20-00-00-220-009-A00	INSPECT (DETAILED INSPECTION) FWD ELECTRONIC COMPARTMENT/ FWD PRESSURE BULKHEAD UPPER SIDE - EWIS COMPONENTS OF WIRING BUNDLES (ZONES: 213,214, 215, 216).NOTE: EWIS.(L650 ONLY)									Service ATA:20
	MOS/MSC	25-Sep-07	N/A					SYSTEM		
	HRS	0								
	AFL	0								
	PROC. REF: AMM 05-40-11, AMM 05-40-11									PKG:6032
20-00-00-220-010-A00	INSPECT (DETAILED INSPECTION) COCKPIT LOWER SIDE - EWIS COMPONENTS OF POWER CABLES AND WIRING BUNDLES (ZONES: 123, 124).NOTE: EWIS (L650 ONLY)									Service ATA:20
	MOS/MSC	25-Sep-07	N/A					SYSTEM		
	HRS	0								
	AFL	0								
	PROC. REF: AMM 05-40-12									PKG:6016
20-00-00-220-011-A00	INSPECT (DETAILED INSPECTION) COCKPIT LATERAL SIDE - EWIS COMPONENTS OF POWER CABLES AND BACK SIDE OF THE RELAY SUPPORT PANEL (ZONES: 223, 224), (ZONES: 223, 224).NOTE: EWIS (L650 ONLY)									Service ATA:20
	MOS/MSC	25-Sep-07	N/A					SYSTEM		
	HRS	0								
	AFL	0								
	PROC. REF: AMM 05-40-13									PKG:6016
20-00-00-220-012-A00	INSPECT (DETAILED INSPECTION) CENTER FUSELAGE I LOWER SIDE - EWIS COMPONENTS OF APU AND ENGINES GENERATORS POWER CABLES, HYDRAULIC PUMPS POWER CABLES AND WIRING BUNDLES (ZONES: 131, 132). NOTE: EWIS (L650 ONLY)									Service ATA:20
	MOS/MSC	25-Sep-07	N/A					SYSTEM		
	HRS	0								
	AFL	0								
	PROC. REF: AMM 05-40-14									PKG:6016
20-00-00-220-013-A00	INSPECT (DETAILED INSPECTION) CENTER FUSELAGE II LOWER SIDE - EWIS COMPONENTS OF APU AND ENGINES GENERATORS POWER CABLES, HYDRAULIC PUMPS POWER CABLES AND WIRING BUNDLES (ZONES: 141, 142). NOTE: EWIS (L650 ONLY)									Service ATA:20
	MOS/MSC	25-Sep-07	N/A					SYSTEM		
	HRS	0								
	AFL	0								
	PROC. REF: AMM 05-40-10									PKG:6016
20-00-00-220-014-A00	INSPECT (DETAILED INSPECTION) AFT FUEL TANK - EWIS COMPONENTS OF AFT FUEL TANK UNITS HARNESS (ZONES271, 272)NOTE: EWIS (L650 ONLY)									Service ATA:20
	MOS/MSC	25-Sep-07	N/A					SYSTEM		
	HRS	0								
	AFL	0								
	PROC. REF: AMM 28-46-02									PKG:6016

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 20 - STANDARD PRACTICES - AIRFRAME										
20-00-00-220-015-A00 INSPECT (DETAILED INSPECTION) FUEL PUMP ELECTRICALHARNES (ZONES 155, 156, 157).NOTE: EWIS (L650 ONLY) Service ATA:20										
	MOS/MSC	25-Sep-07	N/A					SYSTEM		
	HRS	0								
	AFL	0								
PROC. REF: AMM 28-21-01										PKG:6016
20-00-00-220-017-A00 INSPECT (DETAILED INSPECTION) EWIS COMPONENTS OFFWD FUEL TANK UNIT HARNES (ZONE 197).NOTE: EWIS (L650 ONLY) Service ATA:20										
	MOS/MSC	25-Sep-07	N/A					SYSTEM		
	HRS	0								
	AFL	0								
PROC. REF: AMM 28-46-04										PKG:6016
20-00-00-220-019-A00 INSPECT (DETAILED INSPECTION) EWIS COMPONENTS OFW1642 INTRINSICALLY SAFE HARNES (ZONES 123, 124,131, 132, 141, 142, 151, 152, 153, 154, 161, 162,171, 172, 271).NOTE: EWIS (L650 ONLY) Service ATA:20										
	MOS/MSC	25-Sep-07	N/A					SYSTEM		
	HRS	0								
	AFL	0								
PROC. REF: AMM 28-41-00										PKG:6016
ATA 21 - AIR CONDITIONING										
21-20-00-710-001-A00 ^S OPERATIONALLY CHECK CONDITIONED AIR DISTRIBUTION SYSTEM Service ATA:21										
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
PROC. REF: AMM 21-20-00										PKG:5016,6032
21-21-00-720-001-A00 ^S FUNCTIONALLY CHECK DISPLAY VENTILATION SYSTEM Service ATA:21										
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
PROC. REF: AMM 21-21-00										PKG:5008,6016
21-25-01-211-001-A00 ^S VISUALLY CHECK FLAP OF RAM AIR VALVE Service ATA:21										
	MOS	29-Jun-23	24 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	1000 (+20/-20)							
	AFL	5401								
PROC. REF: AMM 21-25-01										PKG:5004

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 21 - AIR CONDITIONING										
21-25-01-710-001-A00 ^S	OPERATIONALLY CHECK RAM AIR VALVE									Service ATA:21
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
	PROC. REF: AMM 21-25-01									PKG:5008,6016
21-26-00-710-001-A00 ^S	OPERATIONALLY CHECK ELECTRONIC COMPARTMENT VENTILATION SYSTEM									Service ATA:21
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
	PROC. REF: AMM 21-26-00									PKG:5008,6016
21-26-08-960-001-A01	DISCARD EXHAUST HOSES OF THE ELECTRONIC BAY COMPARTMENT									Service ATA:21
	MOS	15-Aug-13	180 (+30d/-30d)		15-Aug-28	14-Sep-28	1369 d (+30)	SYSTEM		
	HRS	6643.4								
	AFL	3572								
	PROC. REF: AMM 21-26-08									
21-27-00-710-001-A00 ^S	OPERATIONAL CHECK BAGGAGE COMPARTMENT VENTILATION SYSTEM (INCLUDING HIGH AND LOW SPEED OF FAN)									Service ATA:21
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
	PROC. REF: AMM 21-27-00									PKG:5008
21-27-02-640-001-A00 ^S	LUBRICATE BAGGAGE COMPARTMENT CHECK VALVES									Service ATA:21
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
	PROC. REF: AMM 21-27-02									PKG:5008,6016
21-27-02-710-001-A00 ^S	OPERATIONALLY CHECK BAGGAGE COMPARTMENT CHECK VALVE (MANUAL CHECK FOR FREE MOVEMENT AND CORRECTED SEATING)									Service ATA:21
	MOS	29-Jun-23	24 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	1000 (+20/-20)							
	AFL	5401								
	PROC. REF: AMM 21-27-02									PKG:5004
21-31-00-710-001-A00 ^S	OPERATIONALLY CHECK PRESSURIZATION CONTROL SYSTEM IN MANUAL MODE									Service ATA:21
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
	PROC. REF: AMM 21-31-00									PKG:5016,6032

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 21 - AIR CONDITIONING										
21-31-00-720-002-A00 ^S	FUNCTIONALLY CHECK OUTFLOW VALVES PRESSURE RELIEF DEVICES									Service ATA:21
	MOS	06-Jul-19	144 (+15d/-15d)					LOW UTILIZATION		
	HRS	9057.4	6000 (+20/-20)							
	AFL	4853	3000 (+20/-20)							
	PROC. REF: AMM 21-31-00, AMM 21-31-00									PKG:5024,6020
21-31-00-720-005-A00 ^S	FUNCTIONALLY CHECK LINE FOR LEAKAGE									Service ATA:21
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
	PROC. REF: AMM 21-31-00									PKG:5016,6032
21-31-03-140-001-A00 ^S	RESTORE (CLEANING) ELECTROPNEUMATIC OUTFLOW VALVE (NON-SMOKING FLIGHTS)									Service ATA:21
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
	PROC. REF: AMM 21-31-03									PKG:5008
21-31-03-140-001-A01 ^S	RESTORE (CLEANING) ELECTROPNEUMATIC OUTFLOW VALVE (SMOKING FLIGHTS)									Service ATA:21
	MOS	29-Jun-23	24 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	1000 (+20/-20)							
	AFL	5401								
	PROC. REF: AMM 21-31-03									PKG:5004
21-31-04-140-001-A00 ^S	RESTORE (CLEANING) PNEUMATIC OUTFLOW VALVE (NON-SMOKING FLIGHTS)									Service ATA:21
	MOS	29-Jun-23	24 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	1000 (+20/-20)							
	AFL	5401								
	PROC. REF: AMM 21-31-04									PKG:5004
21-31-04-140-001-A01	RESTORE (CLEANING) PNEUMATIC OUTFLOW VALVE (SMOKING FLIGHTS)									Service ATA:21
	MOS/MS	18-Aug-18	N/A							
	HRS	8725.1								
	AFL	4681								
	PROC. REF: AMM 21-31-04									
21-31-08-960-001-A00	DISCARD AIR FILTER ELEMENT (NON-SMOKING FLIGHTS)									Service ATA:21
	MOS	17-Mar-22						SYSTEM		
	HRS	9824.2	3200		13024.2		2428.6			
	AFL	5235								
	PROC. REF: AMM 21-31-08									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 21 - AIR CONDITIONING										
21-31-08-960-001-A01	DISCARD AIR FILTER ELEMENT (SMOKING FLIGHTS)									Service ATA:21
	MOS/MSC	27-Aug-07	N/A							
	HRS	0								
	AFL	0								
PROC. REF: AMM 21-31-08										
21-32-01-720-001-A00	FUNCTIONALLY CHECK CABIN PRESSURE ACQUISITION MODULE (CPAM) POST-MOD. S.B.145LEG-00-0007 OR WITH AN EQUIVALENT MODIFICATION FACTORY-INCORPORATED									Service ATA:21
	MOS/MSC	19-Aug-15	N/A					SYSTEM		
	HRS	7460.3								
	AFL	3992								
PROC. REF: AMM 21-32-01										
21-51-00-710-001-A00 ^S	OPERATIONALLY CHECK COOLING PACK SYSTEM TO VERIFY ECS OFF SIGNAL									Service ATA:21
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
PROC. REF: AMM 21-51-00										
21-51-00-720-001-A00 ^S	FUNCTIONALLY CHECK COOLING PACK SYSTEM									Service ATA:21
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
PROC. REF: AMM 21-51-00, AMM 21-51-00										
21-51-00-720-003-A00 ^S	FUNCTIONALLY CHECK PACK DUCT OVERTEMPERATURE PROTECTION									Service ATA:21
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
PROC. REF: AMM 21-51-09										
21-51-01-130-001-A00 ^S	RESTORE (CLEANING) PACK VALVE FILTER USING ULTRASONIC METHOD									Service ATA:21
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
PROC. REF: AMM 21-51-01										
21-51-02-170-001-A00 ^S	RESTORE (CLEANING) DUAL HEAT EXCHANGER AND VISUALLY CHECK CONDITION OF CORE.									Service ATA:21
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
PROC. REF: AMM 21-51-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 21 - AIR CONDITIONING										
21-51-02-170-002-A00^S RESTORE (CLEANING) DUAL HEAT EXCHANGER - ON THE AIRCRAFT										
	MOS	29-Jun-23	24 (+15d/-15d)					LOW UTILIZATION		Service ATA:21
	HRS	10161.5	1000 (+20/-20)							
	AFL	5401								
					PROC. REF: AMM 21-51-02					PKG:5004
21-51-10-710-001-A00^S OPERATIONALLY CHECK PACK LEAK SWITCH										
	MOS	06-Jul-19	72 (+15d/-15d)					LOW UTILIZATION		Service ATA:21
	HRS	9057.4	3000 (+20/-20)							
	AFL	4853	1500 (+20/-20)							
					PROC. REF: AMM 21-51-10					PKG:5012,6020
21-51-13-211-001-A00^S VISUALLY CHECK WATER SPRAY NOZZLES NOTE: EMB-RECOMM										
	MOS	16-Aug-24	12 (+15d/-15d)					LOW UTILIZATION		Service ATA:21
	HRS	10541.4	500 (+20/-20)							
	AFL	5613								
					PROC. REF: AMM 21-51-13					PKG:5002
21-60-00-710-001-A00^S OPERATIONALLY CHECK TEMPERATURE CONTROL										
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		Service ATA:21
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
					PROC. REF: AMM 21-60-00					PKG:5016,6032
21-60-08-960-001-A00^S DISCARD TORQUE-MOTOR DUAL-VALVE FILTER										
	MOS	14-Jul-15	192 (+15d/-15d)					LOW UTILIZATION		Service ATA:21
	HRS	7460.3	8000 (+20/-20)							
	AFL	3992	4000 (+20/-20)							
					PROC. REF: AMM 21-60-08					PKG:5032,6032
21-71-01-900-001-A00^S RESTORE (CLEANING) NO. 1 OZONE/OXYGEN CONVERTER - BLEED SYSTEM										
PN:60A523-101	MOS	06-Jul-19	144 (+15d/-15d)					LOW UTILIZATION		Service ATA:21
SN:0306-1352	HRS	9057.4	6000 (+20/-20)							
	AFL	4853	3000 (+20/-20)							
					PROC. REF: AMM 21-70-01					PKG:5024,6020
21-71-01-900-001-A00^S RESTORE (CLEANING) NO. 2 OZONE/OXYGEN CONVERTER - BLEED SYSTEM										
PN:60A523-101	MOS	06-Jul-19	144 (+15d/-15d)					LOW UTILIZATION		Service ATA:21
SN:011/0338	HRS	9057.4	6000 (+20/-20)							
	AFL	4853	3000 (+20/-20)							
					PROC. REF: AMM 21-70-01					PKG:5024,6020

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 21 - AIR CONDITIONING										
212104-0101 GASPER ASSY-GASPER,AIR CONDITIONING SYS VALVE Component ATA:21										
PN:145-22301-401	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:0000141365	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-23-01										
212104-0102 LEFT ASSY-GASPER,AIR CONDITIONING SYS VALVE Component ATA:21										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-23-01										
212104-0103 RIGHT ASSY-GASPER,AIR CONDITIONING SYS VALVE Component ATA:21										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-23-01										
212200-0101 FWD VALVE -DISTRIBUTION,AIR COND SYS,PAX CABIN ASSEMBLY Component ATA:21										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-22-01										
212200-0102 AFT VALVE -DISTRIBUTION,AIR COND SYS,PAX CABIN ASSEMBLY Component ATA:21										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-22-01										
212200-0201 C FLOOR VALVE ASSY Component ATA:21										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
212201-0101 C FLOOR VALVE ASSY Component ATA:21										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 21 - AIR CONDITIONING										
212300-0101 LEFT RECIRCULATION & GASPER FAN Component ATA:21										
PN:AE1115A00	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:05148	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: AMM 21-23-03, AMM 21-24-01										
212300-0102 GASPER RECIRCULATION & GASPER FAN Component ATA:21										
PN:AE1115A00	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:05220	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: AMM 21-23-03, AMM 21-24-01										
212300-0103 RIGHT RECIRCULATION & GASPER FAN Component ATA:21										
PN:AE1115A00	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:05222	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: AMM 21-23-03, AMM 21-24-01										
212401-0101 LH RECIRCULATION FAN AFT MUFFLER Component ATA:21										
PN:PN	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: AMM 21-24-02										
212401-0102 RH RECIRCULATION FAN AFT MUFFLER Component ATA:21										
PN:PN	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: AMM 21-24-02										
212500-0101 LEFT ELECTROMECHANICAL LINEAR-FLAPPER VALVE,APU ACTUATOR Component ATA:21										
PN:SYLC51836-1	MOS/MSC		06-Jul-19	O/C	TSR 3					
SN:060506	HRS		9057.4		TSN 4240, TSR 0					
	AFL		4853		TSN 2002, TSR 0					
PROC. REF: AMM 21-25-03										
212500-0102 RIGHT ELECTROMECHANICAL LINEAR-FLAPPER VALVE,APU ACTUATOR Component ATA:21										
PN:PN	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: AMM 21-25-03										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 21 - AIR CONDITIONING										
212600-0101 LEFT ACTUATOR LINEAR -ELECTROMECHANICAL,CONTROL GUST LOCK ASSEMBLY Component ATA:21										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-26-09										
212600-0102 RIGHT ACTUATOR LINEAR -ELECTROMECHANICAL,CONTROL GUST LOCK ASSEMBLY Component ATA:21										
PN:SYLC53229-3	MOS/MSC	10-Jan-12	O/C							
SN:051101	HRS	5287.4								
	AFL	2805								
PROC. REF: AMM 21-26-09										
212600-0103 LH FWR ELECTRONIC COMPARTMENT FAN Component ATA:21										
PN:526484	MOS/MSC	26-Jan-15	O/C	TSO 0						
SN:107181667	HRS	7281.6		TSO 0						
	AFL	3897		TSO 0						
PROC. REF: AMM 21-26-02										
212600-0104 RH FWR ELECTRONIC COMPARTMENT FAN Component ATA:21										
PN:526484	MOS/MSC	26-Jan-15	O/C	TSO 0						
SN:198289255	HRS	7281.6		TSO 0						
	AFL	3897		TSO 0						
PROC. REF: AMM 21-26-02										
212600-0201 LH REAR ELECTRONIC COMPARTMENT FAN Component ATA:21										
PN:526484	MOS/MSC	27-Jan-13	O/C	TSO 9						
SN:101101819	HRS	6442.2		TSO 0						
	AFL	3468		TSO 0						
PROC. REF: AMM 21-26-02										
212600-0202 RH REAR ELECTRONIC COMPARTMENT FAN Component ATA:21										
PN:526484	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:106442692	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-26-02										
212603-0101 NO. 1 NOSE 28 VDC/12 VDC,FAN,ELECTRONIC EQUIPMENT EQUIPMENT,FWD FUSL G INVERTER Component ATA:21										
PN:524864	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:E07018279	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-26-03										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 21 - AIR CONDITIONING										
212603-0102 NO. 2 NOSE 28 VDC/12 VDC,FAN,ELECTRONIC EQUIPMENT EQUIPMENT,FWD FUSL G INVERTER Component ATA:21										
PN:524864	MOS/MSC	26-Jan-15	O/C	TSN 0						
SN:E11467053	HRS	7281.6		TSN 0						
	AFL	3897		TSN 0						
PROC. REF: AMM 21-26-03										
212603-0103 NO. 3 NOSE 28 VDC/12 VDC,FAN,ELECTRONIC EQUIPMENT EQUIPMENT,FWD FUSL G INVERTER Component ATA:21										
PN:524864	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:E07018281	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-26-03										
212603-0104 NOSE 28 VDC/12 VDC,FAN,ELECTRONIC EQUIPMENT EQUIPMENT,FWD FUSL G INVERTER Component ATA:21										
PN:524864	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:E07018282	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-26-03										
212603-0201 FWD COMPARTMENT EXT POWER SUPPLY SUPPLY Component ATA:21										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
212701-0101 CLASS C, BAGGAGE COMPARTMENT FAN Component ATA:21										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-27-01										
212703-0101 CARGO CP PRESSURIZATION EQUILIZATION VALVE ASSEMBLY Component ATA:21										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-27-03										
213000-0201 LEFT REGULATING-PRESSURE/DEICING,PNEUMATIC SYS VALVE Component ATA:21										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 21 - AIR CONDITIONING											
213000-0202		RIGHT REGULATING-PRESSURE/DEICING,PNEUMATIC SYS VALVE							Component	ATA:21	
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
213100-0101		PRESS SYS - REAR FUSLG 1,41 KFT PNEUMATIC VALVE							Component	ATA:21	
PN:2113A020101	MOS/MSC	17-Feb-22	O/C	TSR 10							
SN:05045	HRS	9806.1		TSR 0							
	AFL	5216		TSR 0							
PROC. REF: AMM 21-31-04											
213100-0102		PRESS SYS - REAR FUSLG 1,41 KFT, 10V ELECTRO PNEUMATIC VALVE							Component	ATA:21	
PN:2112A010101	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:05066	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 21-31-04											
213101-0101		CSL CENT DIGITAL CONTROLLER-PRESSURIZATION,COCKPIT UNIT							Component	ATA:21	
PN:91132A010101	MOS/MSC	28-Jul-21	O/C	TSN 0							
SN:05162	HRS	9631.4		TSN 0							
	AFL	5130		TSN 0							
PROC. REF: AMM 21-31-01											
213102-0101		CSL CENT CONTROL-MANUAL PRESSURE REGULATOR 41 KFT,CTL CSL,COCKPIT UNLT							Component	ATA:21	
PN:2114A010101	MOS/MSC	19-Feb-21	O/C	TSN 0							
SN:05302	HRS	9508.9		TSN 0							
	AFL	5061		TSN 0							
PROC. REF: AMM 21-31-02											
213107-0201		LH REAR STATIC-HEATED,PRESSURIZATION SYS,28VDC PORT							Component	ATA:21	
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 21-31-07											
213107-0202		RH REAR STATIC-HEATED,PRESSURIZATION SYS,28VDC PORT							Component	ATA:21	
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 21-31-07											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 21 - AIR CONDITIONING											
213201-0101		CABIN PRESSURE - RH LATERAL CONSOLE, DATA ACQUISITION MODULE							Component	ATA:21	
PN:2014AB1	MOS/MSC	21-Jan-22	O/C	TSR 2							
SN:1406	HRS	9789.3		TSR 0							
	AFL	5205		TSR 0							
PROC. REF: AMM 21-32-01											
215100-0101		LH PACK ENVIRONMENTAL CONTROL UNIT							Component	ATA:21	
PN:816626-2	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:2007030073	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
215100-0102		RH PACK ENVIRONMENTAL CONTROL- ECU, AIR CONDITIONING SYS UNIT							Component	ATA:21	
PN:816636-2	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:2007020129	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
215101-0101		LH PIL CHECK-BLEED SYS,REAR FUSLG I/II VALVE							Component	ATA:21	
PN:816604-2	MOS/MSC	05-Mar-18	O/C	TSR 0							
SN:2006100487	HRS	8509.4		TSR 0							
	AFL	4566		TSR 0							
PROC. REF: AMM 21-51-01											
215101-0102		RH PIL CHECK-BLEED SYS,REAR FUSLG I/II VALVE							Component	ATA:21	
PN:816604-2	MOS/MSC	05-Mar-18	O/C	TSR 18							
SN:2008020786	HRS	8509.4		TSR 537.8							
	AFL	4566		TSR 287							
PROC. REF: AMM 21-51-01											
215102-0101		LH HEAT EXCHANGER UNIT							Component	ATA:21	
PN:816630-1	MOS/MSC	29-Jun-23	O/C	TSO 0							
SN:2011031697	HRS	10161.5		TSO 0							
	AFL	5401		TSO 0							
PROC. REF: AMM 21-51-02											
215102-0102		RH HEAT EXCHANGER UNIT							Component	ATA:21	
PN:816630-2	MOS/MSC	29-Jun-23	O/C	TSO 0							
SN:2011120010	HRS	10161.5		TSO 0							
	AFL	5401		TSO 0							
PROC. REF: AMM 21-51-02											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 21 - AIR CONDITIONING											
215106-0201		LH ENG PACK,AIR CONDITIONING SYS - OVERPRESSURE SWITCH								Component	ATA:21
PN:782100-11	MOS/MSC	16-Jun-12	O/C	TSN 0							
SN:3171	HRS	5893.2	TSN 0								
	AFL	3135	TSN 0								
PROC. REF: AMM 21-51-06											
215106-0202		RH ENG PACK, AIR CONDITIONING SYS - OVERPRESSURE SWITCH								Component	ATA:21
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 21-51-06											
216001-7000 ^U		RH DUAL TEMP CONTROL VALVE								Component	ATA:21
PN:C143123-6	MOS/MSC	09-Apr-13	O/C	CUSTOMER CODE							
SN:01022238	HRS	6519.2	TSN 14949.8, TSO 36.93, TSR 0								
	AFL	3507	TSN 13415, TSR 0								
216002-0101		PAX AMBIENT TEMPERATURE,ECU,A/C SYS SENSOR								Component	ATA:21
PN:815289-2	MOS/MSC	31-Aug-18	O/C	TSN 3							
SN:21035	HRS	8737.9	TSN 0								
	AFL	4686	TSN 0								
PROC. REF: AMM 21-60-02											
216002-0102		CREW CAB AMBIENT TEMPERATURE,ECU,A/C SYS SENSOR								Component	ATA:21
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 21-60-02											
216004-0101		LEFT TEMPERATURE ASSY-DIGITAL,AIR CONDITIONING SYS CONTROLLER								Component	ATA:21
PN:C142398-4-006	MOS/MSC	04-Aug-10	O/C	TSN 0							
SN:07043238	HRS	3628.6	TSN 0								
	AFL	1907	TSN 0								
PROC. REF: AMM 21-60-04											
216004-0102		RIGHT TEMPERATURE ASSY-DIGITAL,AIR CONDITIONING SYS CONTROLLER								Component	ATA:21
PN:C142398-4-006	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:07023204	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 21-60-04											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 21 - AIR CONDITIONING											
216005-0101		MANUAL, AIR COND SYS, RH CONSOLE, TEMPERATURE CONTROL MODULE							Component	ATA:21	
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 21-60-05											
216006-0101		BOX - PAX TEMPERATURE CONTROLLER,MM SYS ASSEMBLY							Component	ATA:21	
PN:990-8000-004	MOS/MSC	12-Sep-18	O/C	TSN 1							
SN:11040062146	HRS	8754.1		TSN 0							
	AFL	4698		TSN 0							
PROC. REF: AMM 21-60-06											
217001-0101		NO. 1 OZONE/OXYGEN CONVERTER - BLEED SYSTEM							Component	ATA:21	
PN:60A523-101	MOS/MSC	27-Jun-19	O/C	TSR 0							
SN:0306-1352	HRS	9057.4		TSR 0							
	AFL	4853		TSR 0							
PROC. REF: AMM 21-70-01											
217001-0102		NO. 2 OZONE/OXYGEN CONVERTER - BLEED SYSTEM							Component	ATA:21	
PN:60A523-101	MOS/MSC	27-Jun-19	O/C	TSR 0							
SN:011/0338	HRS	9057.4		TSR 0							
	AFL	4853		TSR 0							
PROC. REF: AMM 21-70-01											
ATA 22 - AUTO FLIGHT											
22-11-00-720-003-A00		FUNCTIONALLY CHECK CATEGORY II MONITORING FUNCTION NOTE: ONLY FOR CAT II OPERATION							Service	ATA:22	
	MOS/MSC	01-Sep-17	O/C								
	HRS	8284.1									
	AFL	4446									
PROC. REF: AMM 22-11-00											
22-11-00-720-004-A00 ^S		FUNCTIONALLY CHECK AFCS ALTITUDE HOLD MODE AND ALTITUDE PRE-SELECT MODE NOTE: ONLY FOR RVSM OPERATION							Service	ATA:22	
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	2000 (+20/-20)								
	AFL	5401	1000 (+20/-20)								
PROC. REF: AMM 22-11-00											
PKG:5008,6016											
221001-0101		CSL CENT AUTOPILOT PC400, INSTRUMENT PANEL CONTROLLER UNIT							Component	ATA:22	
PN:7003897-925	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:07013614	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 22-11-02											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 22 - AUTO FLIGHT											
221002-0101		CSL CENT GC 550, GUIDANCE AUTOPILOT SYS, GLARESHIELD CONTROL PANEL							Component	ATA:22	
PN:7021170-951	MOS/MSC	15-Oct-24	O/C								
SN:03061300	HRS	10578.1									
	AFL	5634									
PROC. REF: AMM 22-11-01											
221003-0101		FORWARD FUSELAGE,AUTO PILOT, AILERON SERVO							Component	ATA:22	
PN:145-20449-407	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 22-11-03											
221003-0201		RUDDER ELECTROMECHANICAL ASSY-FLIGHT CONTROL,AUTO PILOT ACTUATOR							Component	ATA:22	
PN:4006719-906 MOD N	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:0612H515	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 22-11-05											
221003-0202		ELEVATOR ELECTROMECHANICAL ASSY-FLIGHT CONTROL,AUTO PILOT ACTUATOR							Component	ATA:22	
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 22-11-04											
221003-0203		AILERON ELECTROMECHANICAL ASSY-FLIGHT CONTROL,AUTO PILOT ACTUATOR							Component	ATA:22	
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 22-11-03											
221004-0101		FORWARD ASSY-ELEVATOR, AUTO PILOT, HORIZONTAL TAIL SERVO							Component	ATA:22	
PN:145-20454-409	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 22-11-04											
221005-0101		REAR ASSY-RUDDER, AUTO PILOT, VERTICAL TAIL SERVO							Component	ATA:22	
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 22-11-05											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 23 - COMMUNICATIONS										
23-15-03-212-001-A00 INSPECT (GENERAL VISUAL) OF SATCOM ANTENNA PART NUMBER 10101-00 NOTE: EMB RECOMM Service ATA:23										
	MOS/MSC	03-Jul-15	N/A							
	HRS	7460.3								
	AFL	3992								
PROC. REF: AMM 23-15-03										
23-35-21-710-001-A00 ^S OPERATIONALLY CHECK ENTERTAINMENT CABINET FANS Service ATA:23										
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
PROC. REF: AMM 23-35-21										
PKG:5008,6016										
23-60-00-720-001-A00 ^S FUNCTIONALLY CHECK STATIC DISCHARGER Service ATA:23										
	MOS	06-Jul-19	72 (+15d/-15d)					LOW UTILIZATION		
	HRS	9057.4	3000 (+20/-20)							
	AFL	4853	1500 (+20/-20)							
PROC. REF: AMM 23-60-00										
PKG:5012,6020										
23-71-00-710-001-A00 OPERATIONALLY CHECK VOICE RECORDER 4 CHANNELS AND AREA MICROPHONE Service ATA:23										
	MOS	29-Jun-23	48 (+30d/-30d)	Adj 7d	06-Jul-27	05-Aug-27	963 d (+30)	SYSTEM		
	HRS	10161.5	4000		14161.5		3565.9			
	AFL	5401								
PROC. REF: AMM 23-71-00										
23-71-02-960-001-A00 DISCARD CVR UNDERWATER LOCATOR BEACON BATTERY NOTE: ULB BATTERY CHANGE IN ACCORDANCE WITH MANUFACTURER'S DATAPLATE EXPIRATION DATE Service ATA:23										
PN:PN	MOS/MSC	01-Jun-22	DUE		31-Mar-29 (M)		1597 d	SYSTEM		
SN:UNKNOWN	HRS	9892.8								
	AFL	5264								
PROC. REF: AMM 23-71-02										
230000-0702 ^U CONFIGURATION MODULE AIRCELL Component ATA:23										
PN:PI4126	MOS/MSC	19-Sep-13	O/C					CUSTOMER CODE		
SN:1412612592	HRS									
	AFL									
230190-701 ^U XM RADIO ANTENNA Component ATA:23										
PN:C1420-1	MOS/MSC	01-Mar-19	O/C	TSN 0						
SN:109639	HRS	8966		TSN 0						
	AFL	4791		TSN 0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 23 - COMMUNICATIONS										
231102-0101 REAR I KRX1053 HF COMM W/SELCAL COMPATIBILITY TRANSCEIVER Component ATA:23										
PN:064-01073-0102	MOS/MSC	31-Aug-17	O/C	TSN 21						
SN:KRX1053-5635	HRS	8284.1		TSN 0						
	AFL	4446		TSN 0						
PROC. REF: AMM 23-11-02										
231102-0102 REAR I KRX1053 HF COMM W/SELCAL COMPATIBILITY TRANSCEIVER Component ATA:23										
PN:064-01073-0101	MOS/MSC	16-Mar-08	O/C	TSN 0						
SN:2528	HRS	694		TSN 0						
	AFL	358		TSN 0						
PROC. REF: AMM 23-11-02										
231103-0101 NO. 1 REAR POWER- KPA 1052 AMPLIFIER Component ATA:23										
PN:064-01072-0101	MOS/MSC		O/C							
SN:2125	HRS									
	AFL	0								
PROC. REF: AMM 23-11-03										
231103-0102 NO. 2 REAR I POWER- KPA 1052 AMPLIFIER Component ATA:23										
PN:064-01072-0101	MOS/MSC		O/C							
SN:2142	HRS									
	AFL	0								
PROC. REF: AMM 23-11-03										
231104-0101 NO. 1 REAR I HF ANTENNA COUPLER - KAC1052, KHF1050 SYSTEM Component ATA:23										
PN:064-01074-0101	MOS/MSC	01-Oct-08	O/C							
SN:1720	HRS	1356.7								
	AFL	721								
PROC. REF: AMM 23-11-04										
231104-0102 NO. 2 REAR I HF ANTENNA COUPLER - KAC1052, KHF1050 SYSTEM Component ATA:23										
PN:064-01074-0101	MOS/MSC		O/C							
SN:2177	HRS									
	AFL	0								
PROC. REF: AMM 23-11-04										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 23 - COMMUNICATIONS										
231111-0101 REAR COMPARTMENT BRIDGING AMPLIFIER - KA 158 AMPLIFIER Component ATA:23										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-11-11										
231112-0101 REAR COMPARTMENT KA 594 BUS ADAPTER, HF SYSTEM ADAPTER Component ATA:23										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-11-12										
231113-0101 REAR COMPARTMENT CAPACITOR,DUAL-EXTERNAL,KA 162,HN CONNECTOR,HF RADIO SYSTEM CAPACITOR Component ATA:23										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-11-13										
231114-0101 PILOT MODULE -KHF1 SYSTEM,MAIN PANEL,COCKPIT ASSEMBLY Component ATA:23										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-11-01										
231114-0102 COPILOT MODULE -KHF1 SYSTEM,MAIN PANEL,COCKPIT ASSEMBLY Component ATA:23										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-11-01										
231201-0101 NO.1 NOSE VHF-COMM RCZ833K,RADIO NAV/COMM SYS ACCESSORIES UNIT Component ATA:23										
PN:7510733-666	MOS/MSC	19-Aug-15	O/C							
SN:0608A868	HRS	7460.3								
	AFL	3992								
PROC. REF: AMM 23-00-01										
231201-0101A^U RECERTIFY NO.1 NOSE VHF-COMM RCZ833K,RADIO NAV/COMM SYS ACCESSORIES UNIT PER FAR 91.413 Service ATA:23										
PN:7510733-666	MOS	29-Jun-23	24 (+30d/-30d)		29-Jun-25	29-Jul-25	226 d (+30)	FAR		
SN:0608A868	HRS	10161.5								
	AFL	5401								
PROC. REF: FAR FAR 91.413										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 23 - COMMUNICATIONS										
231201-0102 NO.2 NOSE VHF-COMM RCZ833K,RADIO NAV/COMM SYS ACCESSORIES UNIT Component ATA:23										
PN:7510733-666	MOS/MSC	19-Aug-15	O/C	TSR 34						
SN:0812C389	HRS	7460.3		TSR 1018.1						
	AFL	3992		TSR 524						
PROC. REF: AMM 23-00-01										
231201-0102A^U RECERTIFY NO.2 NOSE VHF-COMM RCZ833K,RADIO NAV/COMM SYS ACCESSORIES UNIT PER FAR 91.413 Service ATA:23										
PN:7510733-666	MOS	29-Jun-23	24 (+30d/-30d)		29-Jun-25		29-Jul-25	226 d (+30)	FAR	
SN:0812C389	HRS	10161.5								
	AFL	5401								
PROC. REF: FAR FAR 91.413										
231201-0201 NOSE VHF-COMMUNICATION UNIT,RADIO NAV/COMM SYS BOX Component ATA:23										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-00-01										
231204-0201 VHF 1 VHF ANTENNA Component ATA:23										
PN:16-21B MOD.1	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-12-04										
231204-0202 VHF 2 VHF ANTENNA Component ATA:23										
PN:16-21B MOD.1	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-12-04										
231204-0203 VHF 3 VHF ANTENNA Component ATA:23										
PN:S65-8280-41	MOS/MSC	20-Feb-20	O/C	TSN 0						
SN:322-6611	HRS	9313.5		TSN 0						
	AFL	4970		TSN 0						
PROC. REF: AMM 23-12-04										
231501-0101 REAR FUS UNIT,TRANSCPTOR-IRIDIUM TELEPHONE SYSTEM Component ATA:23										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 23 - COMMUNICATIONS										
231501-0102 REAR FUS UNIT, TRANSCEPTOR-IRIDIUM TELEPHONE SYSTEM Component ATA:23										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
231503-0101 FLITEPHONE, SATELLITE COMMUNICATION SYS ANTENNA Component ATA:23										
PN:015-10306-001	MOS/MSC	14-Oct-15	O/C	TSN 2						
SN:11775	HRS	7523.8		TSN 0						
	AFL	4025		TSN 0						
PROC. REF: AMM 23-15-03										
231503-0102 FLITEPHONE, SATELLITE COMMUNICATION SYS ANTENNA Component ATA:23										
PN:015-10306-001	MOS/MSC	14-Oct-15	O/C	TSN 2						
SN:8391	HRS	7523.8		TSN 0						
	AFL	4025		TSN 0						
PROC. REF: AMM 23-15-03										
231505-0101 INMARSAT/IRIDIUM COSITE INTERFERENCE UNIT Component ATA:23										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
231507-0101 IRIDIUM FILTER UNIT Component ATA:23										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
231510-0101 TRANSCEIVER ,PAX BOARD TELEPHONE MANAGEMENT, AEROCON UNIT Component ATA:23										
PN:P12023 REV.U	MOS/MSC	04-Dec-13	O/C	TSR 0						
SN:1202312020	HRS			TSR 0						
	AFL			TSR 0						
PROC. REF: AMM 23-15-10										
231521-0101 SATCOM DATA SDU-7300/SATCOM SYS UNIT Component ATA:23										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-15-21										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 23 - COMMUNICATIONS										
231521-0201 REAR COMPARTMENT HIGH SPEED DATA TERMINAL, INTERNET, TERMINAL										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						Component ATA:23
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-15-21										
231522-0101 HIGH POWER AMPLIFIER-AERO HPA-7400/SATCOM SYS UNIT										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						Component ATA:23
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-15-22										
231523-0101 REAR FUS ACCESS POINT-WASP,WIRELESS,HSD SYS UNIT										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						Component ATA:23
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-15-23										
231524-0101 REAR DIPLEXER/AMPLIFIER- DAU 7050 SYS HSD IRIDIUM UNIT										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						Component ATA:23
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-15-24										
231525-0101 HIGH GAIN-HGA 7000,SATCOM SYS ANTENNA										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						Component ATA:23
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-15-26										
231525-0102 BAGGAGE COMPARTMENT CAP ANTENNA, BI ANTENNA										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						Component ATA:23
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-15-25										
231528-0101 BOARD TELEPHONE UNIT MANAGEMENT,ICS UNIT										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						Component ATA:23
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 23 - COMMUNICATIONS										
232101-0101 HHCSL DECODER, SELECTIVE CALLING SYS, RADIOCOMM UNIT Component ATA:23										
PN:2800-0012-102	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:7015001	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-21-01										
232102-0101 CREW CAB SELCAL HF+VHF 2 MODULE Component ATA:23										
PN:145-46569-405	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:0000159263	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-21-02										
232401-0101 NOSE CMU950, ARINC SYS, MANAGEMENT CONTROL UNIT Component ATA:23										
PN:965-0758-006	MOS/MSC	20-Feb-20	O/C							
SN:CMUMK2-08202	HRS	9313.5								
	AFL	4970								
PROC. REF: AMM 23-24-01										
232401-0201 CMU BATTERY Component ATA:23										
PN:PN-UNKNOWN	MOS/MSC	28-Jan-19	O/C							
SN:UNKNOWN	HRS	8932.1								
	AFL	4776								
PROC. REF: AMM 23-24-01										
232403-0101 NOSE IM 950,5V,CMU SYS,FWD ELEK COMPT, AIRCRAFT PERSONALITY MODULE Component ATA:23										
PN:964-0465-001	MOS/MSC	20-Feb-20	O/C							
SN:APM-01883	HRS	9313.5								
	AFL	4970								
PROC. REF: AMM 23-24-03										
233000-0904^U 1 TERRESTRIAL MODEM ANTENNA Component ATA:23										
PN:P18350-001	MOS/MSC	19-Feb-20	O/C	TSN 0				CUSTOMER CODE		
SN:1835005874	HRS	9310.8		TSN 0						
	AFL	4969		TSN 0						
233000-0904^U 2 TERRESTRIAL MODEM ANTENNA Component ATA:23										
PN:P18350-001	MOS/MSC	19-Feb-20	O/C	TSN 0				CUSTOMER CODE		
SN:1835005828	HRS	9310.8		TSN 0						
	AFL	4969		TSN 0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 23 - COMMUNICATIONS											
233000-0905 ^U		AXXESS CABIN ROUTER								Component	ATA:23
PN:PN	MOS/MSC	19-Feb-20	O/C								
SN:NOT INSTALLED	HRS	9310.8									
	AFL	4969									
233000-0906 ^U		GOGO BIZ 4G TRANSCEIVER								Component	ATA:23
PN:P34110-002	MOS/MSC	15-Aug-24	O/C								
SN:341100024435E	HRS	10541.4									
	AFL	5613									
233000-0907 ^U		AXXESS CONFIGURATION MODULE								Component	ATA:23
PN:P14126	MOS/MSC	19-Feb-20	O/C	TSN 0							
SN:1412625133	HRS	9310.8		TSN 0							
	AFL	4969		TSN 0							
233000-0908 ^U		NO. 1 4G ANTENNA								Component	ATA:23
PN:P35500	MOS/MSC	19-Feb-20	O/C	TSN 0							
SN:3550002857	HRS	9310.8		TSN 0							
	AFL	4969		TSN 0							
233000-0908 ^U		NO. 2 4G ANTENNA								Component	ATA:23
PN:P35500	MOS/MSC	19-Feb-20	O/C	TSN 0							
SN:3550002858	HRS	9310.8		TSN 0							
	AFL	4969		TSN 0							
233000-0909 ^U		NO. 1 REMOTE ANTENNA								Component	ATA:23
PN:P16917-001	MOS/MSC	19-Feb-20	O/C	TSN 0							
SN:1691700111200 3	HRS	9310.8		TSN 0							
	AFL	4969		TSN 0							
233000-0909 ^U		NO. 2 REMOTE ANTENNA								Component	ATA:23
PN:P16917-001	MOS/MSC	19-Feb-20	O/C	TSN 0							
SN:1691700111991	HRS	9310.8		TSN 0							
	AFL	4969		TSN 0							
233000-0909 ^U		NO. 3 REMOTE ANTENNA								Component	ATA:23
PN:P16917-001	MOS/MSC	19-Feb-20	O/C	TSN 0							
SN:1691700111988	HRS	9310.8		TSN 0							
	AFL	4969		TSN 0							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 23 - COMMUNICATIONS											
233000-0909 ^U		NO. 4 REMOTE ANTENNA								Component	ATA:23
PN:P16917-001	MOS/MSC	19-Feb-20	O/C	TSN 0							
SN:1691700111984	HRS	9310.8		TSN 0							
	AFL	4969		TSN 0							
233000-0909 ^U		NO. 5 REMOTE ANTENNA								Component	ATA:23
PN:P16917-001	MOS/MSC	19-Feb-20	O/C	TSN 0							
SN:1691700111992	HRS	9310.8		TSN 0							
	AFL	4969		TSN 0							
233000-0909 ^U		NO. 6 REMOTE ANTENNA								Component	ATA:23
PN:P16917-001	MOS/MSC	19-Feb-20	O/C	TSN 0							
SN:1691700111989	HRS	9310.8		TSN 0							
	AFL	4969		TSN 0							
233000-0910 ^U		AUDIO STORAGE UNIT								Component	ATA:23
PN:630A-000	MOS/MSC	20-Feb-20	O/C	TSN 0							
SN:P200400	HRS	9313.5		TSN 0							
	AFL	4970		TSN 0							
233000-0911 ^U		SATELLITE DATA UNIT								Component	ATA:23
PN:DL-150-00	MOS/MSC	20-Feb-20	O/C	TSN 0							
SN:60155	HRS	9313.5		TSN 0							
	AFL	4970		TSN 0							
233000-0912 ^U		IRIDIUM ANTENNA								Component	ATA:23
PN:S67-1575-409	MOS/MSC	20-Feb-20	O/C	TSN 0							
SN:904-2378	HRS	9313.5		TSN 0							
	AFL	4970		TSN 0							
233000-0913 ^U		VDR ASSEMBLY (TR-866B) MODULE								Component	ATA:23
PN:7026201-815	MOS/MSC	20-Feb-20	O/C	TSN 0							
SN:1912G649	HRS	9313.5		TSN 0							
	AFL	4970		TSN 0							
233101-0101		PASSENGER WARNING SYSTEM AMPLIFIER								Component	ATA:23
PN:5482-1	MOS/MSC	15-Nov-17	O/C	TSR 10							
SN:1265	HRS	8381.4		TSR 0							
	AFL	4500		TSR 0							
PROC. REF: AMM 23-31-01											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 23 - COMMUNICATIONS										
233102-0101	OVERH P MODULE -ICU ASSEMBLY									Component ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 23-31-02										
233104-0101	ELECTRICAL COMPARTMENT SERVICE PANEL, AFT LH, CEILING SPEAKER									Component ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: GENERIC NO REF										
233104-0102	ELECTRICAL COMPARTMENT SERVICE PANEL, AFT LH, CEILING SPEAKER									Component ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: GENERIC NO REF										
233104-0103	ELECTRICAL COMPARTMENT SERVICE PANEL, AFT LH, CEILING SPEAKER									Component ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: GENERIC NO REF										
233104-0104	ELECTRICAL COMPARTMENT SERVICE PANEL, AFT LH, CEILING SPEAKER									Component ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: GENERIC NO REF										
233104-0105	ELECTRICAL COMPARTMENT SERVICE PANEL, AFT LH, CEILING SPEAKER									Component ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: GENERIC NO REF										
233104-0106	ELECTRICAL COMPARTMENT SERVICE PANEL, AFT LH, CEILING SPEAKER									Component ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 23 - COMMUNICATIONS											
233501-0101		DIGITAL INTERFACE-ENTERTAINMENT,AIRSHOW,PAX CABIN UNIT								Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 23-35-01											
233504-0101		AUDIO/VIDEO SYS, PAX ENTERTAINMENT CABINET VIDEO CASSETTE PLAYER								Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 23-35-04											
233505-0101		DIGITAL VIDEO DISC -AUDIO/VIDEO SYS, PAX ENTERTAINMENT CABINET ASSEMBLY								Component	ATA:23
PN:996-4720-001	MOS/MSC	01-Sep-17	O/C	TSR 0							
SN:11090063542	HRS	8284.1		TSR 0							
	AFL	4446		TSR 0							
PROC. REF: AMM 23-35-05											
233505-0102		DIGITAL VIDEO DISC -AUDIO/VIDEO SYS,PAX ENTERTAINMENT CABINET ASSEMBLY								Component	ATA:23
PN:996-4718-001	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:07030037332	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 23-35-05											
233506-0101		BASE, RECEPTACLE - HORIZONTAL UNIT								Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 24-40-01											
233506-0102		BASE, RECEPTACLE - HORIZONTAL UNIT								Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 24-40-01											
233506-0103		BASE, RECEPTACLE - HORIZONTAL UNIT								Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 24-40-01											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 23 - COMMUNICATIONS										
233506-0104	BASE, RECEPTACLE - HORIZONTAL UNIT									Component ATA:23
PN:PN	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: AMM 24-40-01										
233506-0105	BASE, RECEPTACLE - HORIZONTAL UNIT									Component ATA:23
PN:PN	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: AMM 24-40-01										
233506-0106	BASE, RECEPTACLE - HORIZONTAL UNIT									Component ATA:23
PN:PN	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: AMM 24-40-01										
233506-0107	BASE, RECEPTACLE - HORIZONTAL UNIT									Component ATA:23
PN:PN	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: AMM 24-40-01										
233506-0108	BASE, RECEPTACLE - HORIZONTAL UNIT									Component ATA:23
PN:PN	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: AMM 24-40-01										
233513-0101	AUDIO,AMPLIFIER-IFE/PA,DC,DA-420PDC UNIT									Component ATA:23
PN:PN	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: AMM 23-35-13										
233515-0101	FORWARD AUDIO ASSY-M1021,AIRSHOW SYS AMPLIFIER									Component ATA:23
PN:990-4132-002	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:06050027269	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: AMM 23-35-13										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 23 - COMMUNICATIONS										
233515-0102 FORWARD AUDIO ASSY-M1021,AIRSHOW SYS AMPLIFIER Component ATA:23										
PN:990-4132-002	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:06100032705	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-35-13										
233531-0101 MEDIA, INTERFACE UNIT Component ATA:23										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-35-31										
233532-0101 JETMAP COCKPIT CONTROL PANEL Component ATA:23										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
233601-0101 UTILITY I/O - CABIN, CONTROLLER UNIT Component ATA:23										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-36-01										
233602-0101 CABIN, INTERFACE UNIT Component ATA:23										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-36-02										
233602-0102 CABIN, INTERFACE UNIT Component ATA:23										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-36-02										
233603-0101 UNIT,ACCESS POINT - WIRELESS, AVCMS UNIT Component ATA:23										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-36-03										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of:
11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 23 - COMMUNICATIONS										
233604-0101 TOUCHSCREEN,PANEL-GALLEY,8.9" UNIT Component ATA:23										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-36-04										
233605-0101 SELECT 100, PASSENGER, CONTROL UNIT Component ATA:23										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-36-05										
233607-0101 SELECT200, PASSENGER, CONTROL UNIT Component ATA:23										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-36-05										
233607-0102 SELECT200, PASSENGER, CONTROL UNIT Component ATA:23										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-36-05										
233607-0103 SELECT200, PASSENGER, CONTROL UNIT Component ATA:23										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-36-05										
233607-0104 SELECT200, PASSENGER, CONTROL UNIT Component ATA:23										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-36-05										
233607-0105 SELECT200, PASSENGER, CONTROL UNIT Component ATA:23										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-36-05										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 23 - COMMUNICATIONS										
233607-0106 SELECT200, PASSENGER, CONTROL UNIT Component ATA:23										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-36-05										
233607-0107 SELECT200, PASSENGER, CONTROL UNIT Component ATA:23										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-36-05										
233607-0108 SELECT200, PASSENGER, CONTROL UNIT Component ATA:23										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-36-05										
233607-0109 SELECT200, PASSENGER, CONTROL UNIT Component ATA:23										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-36-05										
233607-0110 SELECT200, PASSENGER, CONTROL UNIT Component ATA:23										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-36-05										
233609-0101 PERSONAL MONITOR, VIDEO, 9 INCHES D UNIT Component ATA:23										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
233609-0102 PERSONAL MONITOR, VIDEO, 9 INCHES D UNIT Component ATA:23										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 23 - COMMUNICATIONS										
233609-0103	PERSONAL MONITOR, VIDEO, 9 INCHES D UNIT									Component ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
233609-0104	PERSONAL MONITOR, VIDEO, 9 INCHES D UNIT									Component ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
233609-0105	PERSONAL MONITOR, VIDEO, 9 INCHES D UNIT									Component ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
233609-0106	PERSONAL MONITOR, VIDEO, 9 INCHES D UNIT									Component ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
233609-0107	PERSONAL MONITOR, VIDEO, 9 INCHES D UNIT									Component ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
233609-0108	PERSONAL MONITOR, VIDEO, 9 INCHES D UNIT									Component ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
233801-0101	BLU-RAY,PLAYER UNIT									Component ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-38-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 23 - COMMUNICATIONS											
233801-0102		BLU-RAY,PLAYER UNIT								Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 23-38-01											
233802-0101		HIGH DEFINITION, AUDIO/VIDEO, INPUT UNIT								Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 23-38-02											
233802-0102		HIGH DEFINITION, AUDIO/VIDEO, INPUT UNIT								Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 23-38-02											
233803-0101		IPOD,DOCKING,STATION-PAX,CABIN UNIT								Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 23-38-03											
233803-0102		IPOD,DOCKING,STATION-PAX,CABIN UNIT								Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 23-38-03											
233804-0101		AUX. PANELS (1 USB, RCA, HDMI, RJ45 UNIT								Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 23-38-04											
233804-0102		AUX. PANELS (1 USB, RCA, HDMI, RJ45 UNIT								Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 23-38-04											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 23 - COMMUNICATIONS											
233805-0101		SCALAR BOX - HIGH DEFINITION VIDEO UNIT								Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: GENERIC NO REF											
233806-0101		HD 24" WIDESCREEN MONITOR UNIT								Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: GENERIC NO REF											
234101-0101		ATTEND 1 INTERPHONE-FLIGHT ATTENDANT/PAX CABIN UNIT								Component	ATA:23
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: GENERIC NO REF											
235101-0101		NO.1 CREW CAB AUDIO -AV-850 PANEL								Component	ATA:23
PN:7511001-975	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:0702B797	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 23-51-01											
235101-0102		NO. 2 CREW CAB AUDIO -AV-850 PANEL								Component	ATA:23
PN:7511001-975	MOS/MSC	11-Sep-19	O/C	TSR 0							
SN:0608B230	HRS	9134.8	TSR 0								
	AFL	4897	TSR 0								
PROC. REF: AMM 23-51-01											
235101-0103		NO. 3 CREW CAB AUDIO -AV-850 PANEL								Component	ATA:23
PN:7511001-975	MOS/MSC	17-Aug-15	O/C	TSR 7							
SN:0809D201	HRS	7460.3	TSN 1080.53, TSR 0								
	AFL	3992	TSN 741, TSR 0								
PROC. REF: AMM 23-51-01											
235103-0201		PILOT DYNAMIC-COCKPIT MICROPHONE								Component	ATA:23
PN:602-3375	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:0701010	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 23-51-03											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 23 - COMMUNICATIONS										
235103-0202 COPILOT DYNAMIC-COCKPIT MICROPHONE Component ATA:23										
PN:602-3375	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:0701995	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: AMM 23-51-03										
235107-0101 CREW CAB MODULE -OBSERVER JACKS PANEL ASSEMBLY Component ATA:23										
PN:PN	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: AMM 23-51-06										
237101-0101 SSCVR, RADIO/NAV SYS, COCKPIT VOICE RECORDER Component ATA:23										
PN:1606-00-01	MOS/MSC		28-Apr-20	O/C						
SN:1279	HRS		9356.2							
	AFL		4984							
PROC. REF: AMM 23-71-01										
237101-0201 CVR UNDERWATER LOCATOR BEACON Component ATA:23										
PN:DK120/90	MOS/MSC		01-Jun-22	O/C	TSN 5					
SN:AT176706	HRS		9892.8		TSN 0					
	AFL		5264		TSN 0					
PROC. REF: AMM 23-71-02										
237101-0301 COCKPIT VOICE RECORDER (CVR) UNDERWATER LOCATOR BEACON (ULB) BATTERY Component ATA:23										
PN:PN	MOS/MSC		01-Jun-22	H/T	TSN 5					
SN:UNKNOWN	HRS		9892.8		TSN 0					
	AFL		5264		TSN 0					
PROC. REF: GENERIC NO REF										
237102-0101 OVERH P RADIO/NAVIGATION SYS, CVR CONTROL PANEL Component ATA:23										
PN:1641-110-01	MOS/MSC		20-Feb-20	O/C						
SN:0924	HRS		9313.5							
	AFL		4970							
PROC. REF: AMM 23-71-02										
237103-0101 CREW CAB CVR,RADIO/NAV SYS MICROPHONE Component ATA:23										
PN:16301-01	MOS/MSC		20-Feb-20	O/C						
SN:6750	HRS		9313.5							
	AFL		4970							
PROC. REF: AMM 23-71-03										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 23 - COMMUNICATIONS										
237104-0101 REAR IMPACT SWITCH Component ATA:23										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-71-04										
237104-0102 REAR IMPACT SWITCH Component ATA:23										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-71-04										
237106-0101 RECORDER INDEPENDENT POWER SUPPLY Component ATA:23										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-71-06										
238101-0101 CSL CENT RADIO MANAGEMENT RM-855, COMM SYS, W/HF CONTROL UNIT Component ATA:23										
PN:7013270-977	MOS/MSC	24-Feb-16	O/C							
SN:09127222	HRS	7661.9								
	AFL	4095								
PROC. REF: AMM 23-81-01										
238101-0102 CSL CENT RADIO MANAGEMENT RM-855, COMM SYS, W/HF CONTROL UNIT Component ATA:23										
PN:7013270-977	MOS/MSC	04-Jan-23	O/C	TSR 8						
SN:98081160	HRS	10066.9		TSR 0						
	AFL	5346		TSR 0						
PROC. REF: AMM 23-81-01										
239101-0101 BASE STATION - CORDLESS HANDSET UNIT Component ATA:23										
PN:P12857-101	MOS/MSC	01-Sep-17	O/C	TSN 0						
SN:1285740347	HRS	8284.1		TSN 0						
	AFL	4446		TSN 0						
PROC. REF: GENERIC NO REF										
ATA 24 - ELECTRICAL POWER										
24-31-00-710-001-A00^S OPERATIONALLY CHECK MAIN GENERATION SWITCHING CIRCUIT Service ATA:24										
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
PROC. REF: AMM 24-31-00										
PKG:5016,6016										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 24 - ELECTRICAL POWER										
24-31-00-710-002-A00 ^S OPERATIONALLY CHECK MAIN GENERATION OVERCURRENT PROTECTION CIRCUIT Service ATA:24										
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
PROC. REF: AMM 24-31-00										PKG:5016,6016
24-31-01-900-001-A00 RESTORE (OVERHAUL) LH INBOARD (NO.3) MAIN GENERATOR PART NUMBER 30086-010 NOTE: FROM THE MANUFACTURE DATE OR LAST RESTORATION. NOTE: IF INSTALLED Service ATA:24										
PN:30086-011	MOS/MSC		N/A							
SN:P2610	HRS									
	AFL									
PROC. REF: AMM 24-31-01										
24-31-01-900-001-A00 RESTORE (OVERHAUL) LH OUTBOARD (NO.1) MAIN GENERATOR PART NUMBER 30086-010 NOTE: FROM THE MANUFACTURE DATE OR LAST RESTORATION. NOTE: IF INSTALLED Service ATA:24										
PN:30086-011	MOS/MSC		N/A							
SN:Y10441	HRS									
	AFL									
PROC. REF: AMM 24-31-01										
24-31-01-900-001-A00 RESTORE (OVERHAUL) RH INBOARD (NO.2) MAIN GENERATOR PART NUMBER 30086-010 NOTE: FROM THE MANUFACTURE DATE OR LAST RESTORATION. NOTE: IF INSTALLED Service ATA:24										
PN:30086-011	MOS/MSC	18-Jul-24	N/A							
SN:P1182	HRS	10519.2								
	AFL	5604								
PROC. REF: AMM 24-31-01										
24-31-01-900-001-A00 RESTORE (OVERHAUL) RH OUTBOARD (NO.4) MAIN GENERATOR PART NUMBER 30086-010 NOTE: FROM THE MANUFACTURE DATE OR LAST RESTORATION. NOTE: IF INSTALLED Service ATA:24										
PN:30086-011	MOS/MSC	18-Jul-24	N/A							
SN:99398	HRS	10519.2								
	AFL	5604								
PROC. REF: AMM 24-31-01										
24-31-01-900-001-A01 RESTORE (OVERHAUL) LH INBOARD (NO.3) MAIN GENERATOR PART NUMBER 30086-011 NOTE: FROM THE MANUFACTURE DATE OR LAST RESTORATION. NOTE: IF INSTALLED. Service ATA:24										
PN:30086-011	MOS	08-Feb-23	60		08-Feb-28		1180 d	SYSTEM		
SN:P2610	HRS	10071.3	3600		13671.3		3075.7			
	AFL	5350								
PROC. REF: AMM 24-31-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 24 - ELECTRICAL POWER										
24-31-01-900-001-A01 RESTORE (OVERHAUL) RH INBOARD (NO.2) MAIN GENERATOR PART NUMBER 30086-011 NOTE: FROM THE MANUFACTURE DATE OR LAST RESTORATION. NOTE: IF INSTALLED. Service ATA:24										
PN:30086-011	MOS	18-Jul-24	60		18-Jul-29		1706 d	SYSTEM		
SN:P1182	HRS	10519.2	3600		14119.2		3523.6			
	AFL	5604								
PROC. REF: AMM 24-31-01										
24-31-01-900-001-A01 RESTORE (OVERHAUL) LH OUTBOARD (NO.1) MAIN GENERATOR PART NUMBER 30086-011 NOTE: FROM THE MANUFACTURE DATE OR LAST RESTORATION. NOTE: IF INSTALLED. Service ATA:24										
PN:30086-011	MOS	14-Jun-21	60		14-Jun-26		576 d	SYSTEM		
SN:Y10441	HRS	9586.9	3600		13186.9		2591.3			
	AFL	5110								
PROC. REF: AMM 24-31-01										
24-31-01-900-001-A01 RESTORE (OVERHAUL) RH OUTBOARD (NO.4) MAIN GENERATOR PART NUMBER 30086-011 NOTE: FROM THE MANUFACTURE DATE OR LAST RESTORATION. NOTE: IF INSTALLED. Service ATA:24										
PN:30086-011	MOS	18-Jul-24	60		18-Jul-29		1706 d	SYSTEM		
SN:99398	HRS	10519.2	3600		14119.2		3523.6			
	AFL	5604								
PROC. REF: AMM 24-31-01										
24-34-01-220-001-A00 INSPECT (DETAILED INSPECTION) APU STARTER/GENERATOR BRUSHES Service ATA:24										
PN:23080-013A	MOS	16-Aug-24						SYSTEM		
SN:P1172	HRS	10541.4								
	AFL	5613								
	APH	5722	400		6122		364			
PROC. REF: AMM 24-34-01										
24-34-01-900-001-A00 APU - RESTORE (OVERHAUL) APU STARTER/GENERATOR Service ATA:24										
	MOS	19-May-22	48		19-May-26		550 d			
	HRS	4938	1200		6138		380			
	APUS	4287								
PROC. REF: AMM 24-34-01										
24-34-01-900-001-A00 RESTORE (OVERHAUL) APU STARTER/GENERATOR Service ATA:24										
PN:23080-013A	MOS	19-May-22	48		19-May-26		550 d	SYSTEM		
SN:P1172	HRS	9875.7								
	AFL	5259								
	APH	4938	1200		6138		380			
PROC. REF: AMM 24-34-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 24 - ELECTRICAL POWER										
24-34-01-960-001-A00 APU - DISCARD APU STARTER/GENERATOR BRUSHES Service ATA:24										
	MOS/MSC		11-Mar-17	N/A						
	HRS		2952.1							
	APUS		2686							
PROC. REF: AMM 24-34-01										
24-35-01-720-001-A00 NOSE EMERGENCY-ELECTRICAL EQUIPMENT, BACK-UP BATTERY FUNCTIONALLY CHECK NOSE EMERGENCY-ELECTRICAL EQUIPMENT, BACK-UP BATTERY NOTE: FROM THE MANUFACTURE DATE OR LAST TASK ACCOMPLISHMENT Service ATA:24										
PN:501-1228-04	MOS		18-Jul-24	6 (+15d/-15d)	18-Jan-25	02-Feb-25	64 d (+15)			
SN:80329	HRS		10519.2							
	AFL		5604							
PROC. REF: AMM 24-35-01										
24-35-01-900-001-A00 RESTORE (REPLACEMENT) OF NOSE EMERGENCY-ELECTRICAL EQUIPMENT, BACK-UP BATTERY Service ATA:24										
PN:501-1228-04	MOS		10-Jan-24	12	10-Jan-25		56 d	SYSTEM		
SN:80329	HRS									
	AFL									
Restoration Date:: 10-Jan-24 PROC. REF: AMM 24-35-01										
24-36-01-610-001-A00 SERVICE (REPLENISH) NO.1 NOSE MARATHON MAIN BATTERYNOTE: IF INSTALLED Service ATA:24										
PN:442CH1	MOS/MSC			N/A						
SN:A03650	HRS									
	AFL									
PROC. REF: AMM 24-36-01										
24-36-01-610-001-A00 SERVICE (REPLENISH) NO.2 NOSE MARATHON MAIN BATTERYNOTE: IF INSTALLED Service ATA:24										
PN:442CH1	MOS/MSC			N/A						
SN:T06718	HRS									
	AFL									
PROC. REF: AMM 24-36-01										
24-36-01-900-001-A00 SERVICE (OVERHAUL) NO.1 NOSE SAFT MAIN BATTERYNOTE: IF INSTALLED Service ATA:24										
PN:442CH1	MOS		16-Aug-24	12	16-Aug-25		274 d	RESTORE		
SN:A03650	HRS		10541.4	1000	11541.4		945.8			
	AFL		5613							
PROC. REF: AMM 24-36-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 24 - ELECTRICAL POWER										
24-36-01-900-001-A00 SERVICE (OVERHAUL) NO.2 NOSE SAFT MAIN BATTERYNOTE: IF INSTALLED										Service ATA:24
PN:442CH1	MOS	16-Aug-24	12		16-Aug-25		274 d	RESTORE		
SN:T06718	HRS	10541.4	1000		11541.4		945.8			
	AFL	5613								
PROC. REF: AMM 24-36-01										
24-60-00-710-001-A00 ^S OPERATIONALLY CHECK ELECTRICAL EMERGENCY TRANSFER CIRCUIT										Service ATA:24
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
PROC. REF: AMM 24-60-00										
24-60-00-710-002-A00 ^S OPERATIONALLY CHECK ELECTRICAL EMERGENCY ABNORMAL ALARM										Service ATA:24
	MOS	16-Aug-24	12 (+15d/-15d)					LOW UTILIZATION		
	HRS	10541.4	500 (+20/-20)							
	AFL	5613								
PROC. REF: AMM 24-60-00										
240000-0101 OVERH P MODULE -CONTROL,ELECTRIC SYS,OVER HEAD PANEL ASSEMBLY										Component ATA:24
PN:135-14918-401	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:0000147353	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 24-00-01										
242103-0101 PAX STATIC ASSY, FUSLG CTL I INVERTER										Component ATA:24
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
242104-0101 OVERH P MODULE -ILLUMINATED PANEL,IFE/PC POWER,COCKPIT ASSEMBLY										Component ATA:24
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
243101-0201 LH OUTBOARD (NO.1) GENERATOR POWER UNIT										Component ATA:24
PN:30086-011	MOS/MSC	14-Jun-21	O/C	TSO 9						
SN:Y10441	HRS	9586.9		TSO 0						
	AFL	5110		TSO 0						
PROC. REF: AMM 24-31-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 24 - ELECTRICAL POWER										
243101-0202 LH INBOARD (NO.3) GENERATOR POWER UNIT Component ATA:24										
PN:30086-011	MOS/MSC	08-Feb-23	O/C	TSO 1						
SN:P2610	HRS	10071.3		TSO 0						
	AFL	5350		TSO 0						
PROC. REF: AMM 24-31-01										
243101-0203 RH INBOARD (NO.2) GENERATOR POWER UNIT Component ATA:24										
PN:30086-011	MOS/MSC	18-Jul-24	O/C	TSO 0						
SN:P1182	HRS	10519.2		TSO 0						
	AFL	5604		TSO 0						
PROC. REF: AMM 24-31-01										
243101-0204 RH OUTBOARD (NO.4) GENERATOR POWER UNIT Component ATA:24										
PN:30086-011	MOS/MSC	18-Jul-24	O/C	TSO 0						
SN:99398	HRS	10519.2		TSO 0						
	AFL	5604		TSO 0						
PROC. REF: AMM 24-31-01										
243102-0201 LH CSL (GCU 1) GENERATOR CONTROL-ELECTRICAL EQUIPMENT,CONSOLE,COCKPIT UNIT Component ATA:24										
PN:51545-002A	MOS/MSC	26-Jan-23	O/C							
SN:P1747	HRS	10069.5								
	AFL	5348								
PROC. REF: AMM 24-31-02										
243102-0202 LH CSL (GCU 3) GENERATOR CONTROL-ELECTRICAL EQUIPMENT,CONSOLE,COCKPIT UNIT Component ATA:24										
PN:51545-002A	MOS/MSC	26-Jan-23	O/C							
SN:P1766	HRS	10069.5								
	AFL	5348								
PROC. REF: AMM 24-31-02										
243102-0203 RH CSL (GCU 2) GENERATOR CONTROL-ELECTRICAL EQUIPMENT,CONSOLE,COCKPIT UNIT Component ATA:24										
PN:51545-002A	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 24-31-02										
243102-0204 RH CSL (GCU 4) GENERATOR CONTROL-ELECTRICAL EQUIPMENT,CONSOLE,COCKPIT UNIT Component ATA:24										
PN:51545-002A	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 24-31-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 24 - ELECTRICAL POWER										
243401-0101 APU STARTER GENERATOR-400A/28VDC,APU UNIT Component ATA:24										
PN:23080-013A	MOS/MSC	19-May-22	O/C	TSO 0						
SN:P1172	HRS	9875.7		TSO 0						
	AFL	5259		TSO 0						
PROC. REF: AMM 24-34-01, AMM 24-34-01										
243402-0101 CREW CAB GCU - GENERATOR CONTROL UNIT Component ATA:24										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 24-34-02										
243501-0101 NOSE EMERGENCY-ELECTRICAL EQUIPMENT, BACK-UP BATTERY Component ATA:24										
PN:501-1228-04	MOS/MSC	11-Jan-23	O/C	TSR 0						
SN:80329	HRS	10066.9		TSR 0						
	AFL	5346		TSR 0						
PROC. REF: AMM 24-35-01										
243502-0101 NOSE MODULE -RELAY BOX,BATTERY BACKUP,ELECTRONIC COMPARTMENT ASSEMBLY Component ATA:24										
PN:135-08601-401	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:0000139930	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 24-35-02										
243601-0101 NO.1 NOSE 44AH, NI-CD BATTERY Component ATA:24										
PN:442CH1	MOS/MSC	29-Jun-23	O/C	TSO 0						
SN:A03650	HRS	10161.5		TSO 0						
	AFL	5401		TSO 0						
PROC. REF: GENERIC NO REF										
243601-0102 NO.2 NOSE 44AH, NI-CD BATTERY Component ATA:24										
PN:442CH1	MOS/MSC	29-Jun-23	O/C	TSO 0						
SN:T06718	HRS	10161.5		TSO 0						
	AFL	5401		TSO 0						
PROC. REF: AMM 24-36-01										
243602-0101 NOSE BATTERY 1 RELAY BOX- ASSEMBLY Component ATA:24										
PN:145-31116-405	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:0000146833	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 24-36-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 24 - ELECTRICAL POWER											
243602-0102		NOSE BATTERY 2 RELAY BOX- ASSEMBLY							Component	ATA:24	
PN:145-31118-407	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:0000138185	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 24-36-03											
246005-0101		LEFT DC DISTRIBUTION BOX							Component	ATA:24	
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 24-65-00											
246005-0102		RIGHT DC DISTRIBUTION BOX							Component	ATA:24	
PN:135-18756-403	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:0000173484	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 24-65-01											
ATA 25 - EQUIPMENT/FURNISHINGS											
25-11-01-140-001-A00 ^S		RESTORE (CLEANING) FLIGHT CREW SEATS LOCKING SYSTEM							Service	ATA:25	
	MOS	16-Aug-24	12 (+15d/-15d)			LOW UTILIZATION					
	HRS	10541.4	500 (+20/-20)								
	AFL	5613									
PROC. REF: AMM 25-11-01											
25-11-01-220-001-A00 ^S		INSPECT (DETAILED INSPECTION) COCKPIT SEATS FOR SECURITY OF ATTACHMENT TO THE TRACK, INCLUDING RESTRAINT SYSTEM (SEAT BELT).							Service	ATA:25	
	MOS	29-Jun-23	48 (+15d/-15d)			LOW UTILIZATION					
	HRS	10161.5	2000 (+20/-20)								
	AFL	5401	1000 (+20/-20)								
PROC. REF: AMM 25-11-01											
25-21-00-212-001-A00 ^S		INSPECT (GENERAL VISUAL) PASSENGER CABIN SEATS (FABRIC, COVER, SAFETY BELT, SEAT MOVEMENT AND ATTACHMENTS TO TRACK)							Service	ATA:25	
	MOS	29-Jun-23	48 (+15d/-15d)			LOW UTILIZATION					
	HRS	10161.5	2000 (+20/-20)								
	AFL	5401	1000 (+20/-20)								
PROC. REF: AMM 25-21-05											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 25 - EQUIPMENT/FURNISHINGS											
25-21-00-220-002-A00 ^S		INSPECT (DETAILED INSPECTION) FLIGHT ATTENDANT SEATS HARNESS, INERTIAL REEL FOR CONDITION AND THE SEAT BOTTOM FOR FREEDOM OF MOVEMENT AND RETURNING BACK TO UPRIGHT POSITION. (NOTE: IF INSTALLED)							Service	ATA:25	
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	2000 (+20/-20)								
	AFL	5401	1000 (+20/-20)								
PROC. REF: AMM 25-21-02										PKG:5008,6016	
25-26-00-212-001-A00 ^S		INSPECT (GENERAL VISUAL) CREDENZA, CLOSETS AND ENTERTAINMENT CABINET FOR INTEGRITY AND SECURITY.							Service	ATA:25	
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	2000 (+20/-20)								
	AFL	5401	1000 (+20/-20)								
PROC. REF: AMM 25-26-00										PKG:5008,6016	
25-27-02-211-001-A00 ^S		VISUALLY CHECK LAVATORY/BAGGAGE DOOR SEALING FOR CONDITION, INTEGRITY AND SECURITY.							Service	ATA:25	
	MOS	16-Aug-24	12 (+15d/-15d)					LOW UTILIZATION			
	HRS	10541.4	500 (+20/-20)								
	AFL	5613									
PROC. REF: AMM 25-27-02										PKG:5002	
25-30-06-212-001-A00 ^S		INSPECT (GENERAL VISUAL) FORWARD GALLEY STRUCTURE LOWER ATTACHMENT POINTS (ON THE TRACKS).							Service	ATA:25	
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	2000 (+20/-20)								
	AFL	5401	1000 (+20/-20)								
PROC. REF: AMM 25-30-01										PKG:5008,6016	
25-40-04-212-001-A00 ^S		INSPECT (GENERAL VISUAL) LAVATORY STRUCTURE LOWER ATTACHMENT POINTS.							Service	ATA:25	
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	2000 (+20/-20)								
	AFL	5401	1000 (+20/-20)								
PROC. REF: AMM 25-40-01										PKG:5008,6016	
25-60-01-212-001-A00		INSPECT (GENERAL VISUAL) FIRST AID KIT FOR CONDITION AND VALIDATION.							Service	ATA:25	
PN:AFAK 1.0	MOS/MS	16-Aug-24	DUE		31-Aug-25 (M)		289 d	SYSTEM			
SN:110220005	HRS	10541.4									
	AFL	5613									
PROC. REF: AMM 25-60-01											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
25-60-02-900-001-ALL RESTORE ATTEND 1 EMERGENCY EQUIPMENT LIFE JACKET (25-60-02-900-001-A00/A01/A02/A03/A04/A05) Service ATA:25										
PN:P01074-201	MOS/MSC	31-Oct-20	DUE		01-Aug-30 (M)		2085 d	VENDOR RECOMMENDATION		
SN:20080790056	HRS	9463.7								
	AFL	5043								
PROC. REF: GENERIC NO REF										
25-60-02-900-001-ALL RESTORE COPILOT EMERGENCY EQUIPMENT LIFE JACKET (25-60-02-900-001-A00/A01/A02/A03/A04/A05) Service ATA:25										
PN:P01074-201	MOS/MSC	31-Oct-20	DUE		01-Aug-30 (M)		2085 d	VENDOR RECOMMENDATION		
SN:20080790054	HRS	9463.7								
	AFL	5043								
PROC. REF: GENERIC NO REF										
25-60-02-900-001-ALL RESTORE OBSERVER EMERGENCY EQUIPMENT LIFE JACKET (25-60-02-900-001-A00/A01/A02/A03/A04/A05) Service ATA:25										
PN:P01074-201	MOS/MSC	31-Oct-20	DUE		01-Aug-30 (M)		2085 d	VENDOR RECOMMENDATION		
SN:20080790055	HRS	9463.7								
	AFL	5043								
PROC. REF: GENERIC NO REF										
25-60-02-900-001-ALL RESTORE PAX 1 EMERGENCY EQUIPMENT LIFE JACKET (25-60-02-900-001-A00/A01/A02/A03/A04/A05) Service ATA:25										
PN:P01074-201	MOS/MSC	31-Oct-20	DUE		01-Aug-30 (M)		2085 d	VENDOR RECOMMENDATION		
SN:20080790057	HRS	9463.7								
	AFL	5043								
PROC. REF: GENERIC NO REF										
25-60-02-900-001-ALL RESTORE PAX 10 EMERGENCY EQUIPMENT LIFE JACKET (25-60-02-900-001-A00/A01/A02/A03/A04/A05) Service ATA:25										
PN:P01074-201	MOS/MSC	31-Oct-20	DUE		01-Aug-30 (M)		2085 d	VENDOR RECOMMENDATION		
SN:20080790107	HRS	9463.7								
	AFL	5043								
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
25-60-02-900-001-ALL RESTORE PAX 11 EMERGENCY EQUIPMENT LIFE JACKET (25-60-02-900-001-A00/A01/A02/A03/A04/A05) Service ATA:25										
PN:63600-105	MOS/MSC	09-Jun-17	DUE		09-Jun-27 (M)		936 d	VENDOR RECOMMENDATION		
SN:L2190735	HRS									
	AFL									
PROC. REF: GENERIC NO REF										
25-60-02-900-001-ALL RESTORE PAX 12 EMERGENCY EQUIPMENT LIFE JACKET (25-60-02-900-001-A00/A01/A02/A03/A04/A05) Service ATA:25										
PN:63600-105	MOS/MSC	09-Jun-17	DUE		09-Jun-27 (M)		936 d	VENDOR RECOMMENDATION		
SN:L2190733	HRS									
	AFL									
PROC. REF: GENERIC NO REF										
25-60-02-900-001-ALL RESTORE PAX 13 EMERGENCY EQUIPMENT LIFE JACKET (25-60-02-900-001-A00/A01/A02/A03/A04/A05) Service ATA:25										
PN:63600-105	MOS/MSC	13-Feb-20	DUE		30-Nov-29 (M)		1841 d	VENDOR RECOMMENDATION		
SN:L4939550	HRS	9310.8								
	AFL	4969								
PROC. REF: GENERIC NO REF										
25-60-02-900-001-ALL RESTORE PAX 2 EMERGENCY EQUIPMENT LIFE JACKET (25-60-02-900-001-A00/A01/A02/A03/A04/A05) Service ATA:25										
PN:P01074-201	MOS/MSC	31-Oct-20	DUE		01-Aug-30 (M)		2085 d	VENDOR RECOMMENDATION		
SN:20080790058	HRS	9463.7								
	AFL	5043								
PROC. REF: GENERIC NO REF										
25-60-02-900-001-ALL RESTORE PAX 3 EMERGENCY EQUIPMENT LIFE JACKET (25-60-02-900-001-A00/A01/A02/A03/A04/A05) Service ATA:25										
PN:P01074-201	MOS/MSC	31-Oct-20	DUE		01-Aug-30 (M)		2085 d	VENDOR RECOMMENDATION		
SN:20080790059	HRS	9463.7								
	AFL	5043								
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
25-60-02-900-001-ALL RESTORE PAX 4 EMERGENCY EQUIPMENT LIFE JACKET (25-60-02-900-001-A00/A01/A02/A03/A04/A05) Service ATA:25										
PN:P01074-201	MOS/MSC	31-Oct-20	DUE		01-Aug-30 (M)		2085 d	VENDOR RECOMMENDATION		
SN:20080790101	HRS	9463.7								
	AFL	5043								
PROC. REF: GENERIC NO REF										
25-60-02-900-001-ALL RESTORE PAX 5 EMERGENCY EQUIPMENT LIFE JACKET (25-60-02-900-001-A00/A01/A02/A03/A04/A05) Service ATA:25										
PN:P01074-201	MOS/MSC	31-Oct-20	DUE		01-Aug-30 (M)		2085 d	VENDOR RECOMMENDATION		
SN:20080790102	HRS	9463.7								
	AFL	5043								
PROC. REF: GENERIC NO REF										
25-60-02-900-001-ALL RESTORE PAX 6 EMERGENCY EQUIPMENT LIFE JACKET (25-60-02-900-001-A00/A01/A02/A03/A04/A05) Service ATA:25										
PN:P01074-201	MOS/MSC	31-Oct-20	DUE		01-Aug-30 (M)		2085 d	VENDOR RECOMMENDATION		
SN:20080790103	HRS	9463.7								
	AFL	5043								
PROC. REF: GENERIC NO REF										
25-60-02-900-001-ALL RESTORE PAX 7 EMERGENCY EQUIPMENT LIFE JACKET (25-60-02-900-001-A00/A01/A02/A03/A04/A05) Service ATA:25										
PN:P01074-201	MOS/MSC	31-Oct-20	DUE		01-Aug-30 (M)		2085 d	VENDOR RECOMMENDATION		
SN:20080790104	HRS	9463.7								
	AFL	5043								
PROC. REF: GENERIC NO REF										
25-60-02-900-001-ALL RESTORE PAX 8 EMERGENCY EQUIPMENT LIFE JACKET (25-60-02-900-001-A00/A01/A02/A03/A04/A05) Service ATA:25										
PN:P01074-201	MOS/MSC	31-Oct-20	DUE		01-Aug-30 (M)		2085 d	VENDOR RECOMMENDATION		
SN:20080790105	HRS	9463.7								
	AFL	5043								
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
25-60-02-900-001-ALL RESTORE PAX 9 EMERGENCY EQUIPMENT LIFE JACKET (25-60-02-900-001-A00/A01/A02/A03/A04/A05) Service ATA:25										
PN:P01074-201	MOS/MSC	31-Oct-20	DUE		01-Aug-30 (M)		2085 d	VENDOR RECOMMENDATION		
SN:20080790106	HRS	9463.7								
	AFL	5043								
PROC. REF: GENERIC NO REF										
25-60-02-900-001-ALL RESTORE PILOT EMERGENCY EQUIPMENT LIFE JACKET (25-60-02-900-001-A00/A01/A02/A03/A04/A05) Service ATA:25										
PN:P01074-201	MOS/MSC	31-Oct-20	DUE		01-Aug-30 (M)		2085 d	VENDOR RECOMMENDATION		
SN:20080790053	HRS	9463.7								
	AFL	5043								
PROC. REF: GENERIC NO REF										
25-60-04-212-001-A00 ^S INSPECT (GENERAL VISUAL) COCKPIT ESCAPE ROPE(ZONES 225/226) Service ATA:25										
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
PROC. REF: AMM 25-60-07										
25-60-05-212-001-A00 ^S INSPECT (GENERAL VISUAL) OF LIFELINE FOR INTEGRITY AND GENERAL CONDITIONS (ZONE 252) (IF INSTALLED) Service ATA:25										
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
PROC. REF: AMM 25-60-03										
25-61-00-212-001-A00 INSPECT (GENERAL VISUAL) EMERGENCY LOCATOR TRANSMITTER FOR CONDITION PROPER INSTALLATION BATTERY CORROSION AND LEAKAGE Service ATA:25										
	MOS	16-Aug-24	12 (+15d/-15d)		16-Aug-25	31-Aug-25	274 d (+15)	SYSTEM		
	HRS	10541.4								
	AFL	5613								
PROC. REF: AMM 25-61-00, FAR FAR 91.207										
25-61-00-710-001-A00 OPERATIONAL CHECK EMERGENCY LOCATOR TRANSMITTER SYSTEM - PROPER OPERATION- CRASH SWITCH OPERATION Service ATA:25										
	MOS	18-Jul-24	12 (+15d/-15d)	Adj 13d	31-Jul-25	15-Aug-25	258 d (+15)	SYSTEM		
	HRS	10519.2								
	AFL	5604								
PROC. REF: AMM 25-61-00, AMM 25-61-00, AMM 25-61-00, FAR FAR 91.207										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
25-62-03-701 ^U RENEW NO. 1 LIFE RAFT EMERGENCY LOCATOR TRANSMITTER (ELT) BEACON REGISTRATION Service ATA:25										
	MOS	08-Feb-23	24		08-Feb-25		85 d			
	HRS	10071.3								
	AFL	5350								
25-62-03-702 ^U RENEW NO. 2 LIFE RAFT EMERGENCY LOCATOR TRANSMITTER (ELT) BEACON REGISTRATION Service ATA:25										
	MOS	08-Feb-23	24		08-Feb-25		85 d			
	HRS	10071.3								
	AFL	5350								
25-62-03-801 ^U DISCARD NO. 1 LIFE RAFT EMERGENCY LOCATOR TRANSMITTER (ELT) BEACON BATTERY Service ATA:25										
PN:K2-01-0003-001	MOS/MSC	30-Mar-22	DUE		01-Jan-28 (M)		1142 d			
SN:UNKNOWN	HRS	9837								
	AFL	5241								
25-62-03-802 ^U DISCARD NO. 2 LIFE RAFT EMERGENCY LOCATOR TRANSMITTER (ELT) BEACON BATTERY Service ATA:25										
PN:PN	MOS/MSC	10-Jan-24	DUE		31-Jan-25 (M)		77 d			
SN:UNKNOWN	HRS	10396.8								
	AFL	5532								
25-63-00-710-001-A00 OPERATIONALLY CHECK PORTABLE EMERGENCY LOCATOR TRANSMITTER SYSTEM NOTE: IF INSTALLED Service ATA:25										
	MOS/MSC	30-Aug-12	N/A							
	HRS	6158.5								
	AFL	3279								
PROC. REF: AMM 25-63-02										
25-63-01-900-001-A01 RESTORE (OVERHAUL) WINSLOW (VACUUM PACKED) NO.2 LIFE RAFT ASSEMBLYNOTE: FROM THE MANUFACTURE DATE OR LAST RESTORATION.NOTE: IF INSTALLED. Service ATA:25										
PN:R0103A105	MOS	10-Jan-24	36		10-Jan-27		786 d	SYSTEM		
SN:TQ09158	HRS	10396.8								
	AFL	5532								
Manufacture Date:: 10-Jan-24 PROC. REF: AMM 25-60-02, AMM 25-60-05										
25-63-01-900-001-A01 RESTORE (OVERHAUL) WINSLOW (VACUUM PACKED) NO.1 LIFE RAFT ASSEMBLYNOTE: FROM THE MANUFACTURE DATE OR LAST RESTORATION.NOTE: IF INSTALLED. Service ATA:25										
PN:69FASA-631-1-702	MOS	30-Mar-22	36		30-Mar-25		135 d	SYSTEM		
SN:64L-01766	HRS	9837								
	AFL	5241								
Manufacture Date:: 30-Mar-22 PROC. REF: AMM 25-60-02, AMM 25-60-05										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
25-63-02-960-001-A00	DISCARD PORTABLE ELT BATTERY ELTA PN: 05N62123 NOTE: PORTABLE ELT BATTERY CHANGE IN ACCORDANCE WITH MANUFACTURER'S DATA PLATE EXPIRATION DATE OR IN ACCORDANCE WITH LOCAL REGULATORY AUTHORITY REQUIREMENTS								Service	ATA:25
	MOS/MSC	30-Aug-12	O/C							
	HRS	6158.5								
	AFL	3279								
PROC. REF: AMM 25-63-03										
251101-0101	PILOT ASSY-PILOT SEAT								Component	ATA:25
PN:1471611-05	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:06T2116	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-11-01										
251101-0102	COPILOT ASSY-CO-PILOT SEAT								Component	ATA:25
PN:1471610-05	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:06T3595	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-11-01										
251102-0101	OBSERVER ASSEMBLY SEAT								Component	ATA:25
PN:7222001-101	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:104607	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-11-02										
252102-0101	FLIGHT ATTENDANT SEAT ASSY								Component	ATA:25
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-21-02										
253103-0101	GALLEY CABINET ELECTRICAL OVEN								Component	ATA:25
PN:400-1191-01-R	MOS/MSC	24-Feb-16	O/C	TSR 0						
SN:05-08-37415	HRS	7661.9		TSR 0						
	AFL	4095		TSR 0						
PROC. REF: AMM 25-31-03										
253104-0101	GALLEY CABINET MICROWAVE OVEN								Component	ATA:25
PN:400-1860-01	MOS/MSC	22-Jan-14	O/C	TSR 5						
SN:06-11-39938	HRS	6836.5		TSR 0						
	AFL	3679		TSR 0						
PROC. REF: AMM 25-31-04										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 25 - EQUIPMENT/FURNISHINGS											
253105-0101		GALLEY ELECTRICAL COFFEE MAKER								Component	ATA:25
PN:400-1749-10	MOS/MSC	01-Sep-17	O/C	TSR 0							
SN:07-03-40593	HRS	8284.1		TSR 0							
	AFL	4446		TSR 0							
PROC. REF: AMM 25-31-05											
253109-0101		GALLEY UNIT, REFRIGERATOR UNIT								Component	ATA:25
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM NO REF											
253110-0701^U		GALLEY SWITCHING PANEL								Component	ATA:25
PN:990-9105-015	MOS/MSC	25-Apr-17	O/C	TSR 1							
SN:06070030259	HRS	8136.8		TSR 0							
	AFL	4367		TSR 0							
253205-0101		OVEN REAR CABINET ,GALLEY CONTROL PANEL								Component	ATA:25
PN:400-1377-01	MOS/MSC	19-Sep-13	O/C	TSN 0							
SN:07-04-40940	HRS	6680.2		TSN 0							
	AFL	3597		TSN 0							
PROC. REF: AMM 25-31-03											
255006-0101		BAGGAGE COMPARTMENT REAR BULKHEAD PANEL ASSY								Component	ATA:25
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
256001-0101		FIRST AID KIT								Component	ATA:25
PN:AFAK 1.0	MOS/MSC	01-Jul-24	O/C	TSO 0							
SN:110220005	HRS	10503.9		TSO 0							
	AFL	5592		TSO 0							
PROC. REF: GENERIC NO REF											
256001-0701^U		DEFIBRILLATOR AND AED PREP KIT								Component	ATA:25
PN:AED FRX	MOS/MSC	26-Jan-23	DUE	TSN 53, TSR 0	31-Jan-25 (M)		77 d				
SN:B12K-00297	HRS	10069.5		TSN 1331.6, TSR 0							
	AFL	5348		TSN 662, TSR 0							
Expiry Date: : 31-Jan-25											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 25 - EQUIPMENT/FURNISHINGS											
256002-0101		PILOT EMERGENCY EQUIPMENT LIFE JACKET							Component	ATA:25	
PN:P01074-201	MOS/MSC	31-Oct-20	O/C	TSN 0							
SN:20080790053	HRS	9463.7		TSN 0							
	AFL	5043		TSN 0							
PROC. REF: GENERIC NO REF											
256002-0102		COPILOT EMERGENCY EQUIPMENT LIFE JACKET							Component	ATA:25	
PN:P01074-201	MOS/MSC	31-Oct-20	O/C	TSN 0							
SN:20080790054	HRS	9463.7		TSN 0							
	AFL	5043		TSN 0							
PROC. REF: GENERIC NO REF											
256002-0103		OBSERVER EMERGENCY EQUIPMENT LIFE JACKET							Component	ATA:25	
PN:P01074-201	MOS/MSC	31-Oct-20	O/C	TSN 0							
SN:20080790055	HRS	9463.7		TSN 0							
	AFL	5043		TSN 0							
PROC. REF: GENERIC NO REF											
256002-0104		ATTEND 1 EMERGENCY EQUIPMENT LIFE JACKET							Component	ATA:25	
PN:P01074-201	MOS/MSC	31-Oct-20	O/C	TSN 0							
SN:20080790056	HRS	9463.7		TSN 0							
	AFL	5043		TSN 0							
PROC. REF: GENERIC NO REF											
256002-7101		PAX 1 EMERGENCY EQUIPMENT LIFE JACKET							Component	ATA:25	
PN:P01074-201	MOS/MSC	31-Oct-20	O/C	TSN 0							
SN:20080790057	HRS	9463.7		TSN 0							
	AFL	5043		TSN 0							
PROC. REF: GENERIC NO REF											
256002-7102		PAX 2 EMERGENCY EQUIPMENT LIFE JACKET							Component	ATA:25	
PN:P01074-201	MOS/MSC	31-Oct-20	O/C	TSN 0							
SN:20080790058	HRS	9463.7		TSN 0							
	AFL	5043		TSN 0							
PROC. REF: GENERIC NO REF											
256002-7103		PAX 3 EMERGENCY EQUIPMENT LIFE JACKET							Component	ATA:25	
PN:P01074-201	MOS/MSC	31-Oct-20	O/C	TSN 0							
SN:20080790059	HRS	9463.7		TSN 0							
	AFL	5043		TSN 0							
PROC. REF: GENERIC NO REF											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 25 - EQUIPMENT/FURNISHINGS											
256002-7104		PAX 4 EMERGENCY EQUIPMENT LIFE JACKET								Component	ATA:25
PN:P01074-201	MOS/MSC	31-Oct-20	O/C	TSN 0							
SN:20080790101	HRS	9463.7		TSN 0							
	AFL	5043		TSN 0							
PROC. REF: GENERIC NO REF											
256002-7105		PAX 5 EMERGENCY EQUIPMENT LIFE JACKET								Component	ATA:25
PN:P01074-201	MOS/MSC	31-Oct-20	O/C	TSN 0							
SN:20080790102	HRS	9463.7		TSN 0							
	AFL	5043		TSN 0							
PROC. REF: GENERIC NO REF											
256002-7106		PAX 6 EMERGENCY EQUIPMENT LIFE JACKET								Component	ATA:25
PN:P01074-201	MOS/MSC	31-Oct-20	O/C	TSN 0							
SN:20080790103	HRS	9463.7		TSN 0							
	AFL	5043		TSN 0							
PROC. REF: GENERIC NO REF											
256002-7107		PAX 7 EMERGENCY EQUIPMENT LIFE JACKET								Component	ATA:25
PN:P01074-201	MOS/MSC	31-Oct-20	O/C	TSN 0							
SN:20080790104	HRS	9463.7		TSN 0							
	AFL	5043		TSN 0							
PROC. REF: GENERIC NO REF											
256002-7108		PAX 8 EMERGENCY EQUIPMENT LIFE JACKET								Component	ATA:25
PN:P01074-201	MOS/MSC	31-Oct-20	O/C	TSN 0							
SN:20080790105	HRS	9463.7		TSN 0							
	AFL	5043		TSN 0							
PROC. REF: GENERIC NO REF											
256002-7109		PAX 9 EMERGENCY EQUIPMENT LIFE JACKET								Component	ATA:25
PN:P01074-201	MOS/MSC	31-Oct-20	O/C	TSN 0							
SN:20080790106	HRS	9463.7		TSN 0							
	AFL	5043		TSN 0							
PROC. REF: GENERIC NO REF											
256002-7110		PAX 10 EMERGENCY EQUIPMENT LIFE JACKET								Component	ATA:25
PN:P01074-201	MOS/MSC	31-Oct-20	O/C	TSN 0							
SN:20080790107	HRS	9463.7		TSN 0							
	AFL	5043		TSN 0							
PROC. REF: GENERIC NO REF											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
256002-7111	PAX 11 EMERGENCY EQUIPMENT LIFE JACKET									Component ATA:25
PN:63600-105	MOS/MSC	04-Jan-19	O/C							
SN:L2190735	HRS	8912.5								
	AFL	4764								
PROC. REF: GENERIC NO REF										
256002-7112	PAX 12 EMERGENCY EQUIPMENT LIFE JACKET									Component ATA:25
PN:63600-105	MOS/MSC	04-Jan-19	O/C							
SN:L2190733	HRS	8912.5								
	AFL	4764								
PROC. REF: GENERIC NO REF										
256002-7113	PAX 13 EMERGENCY EQUIPMENT LIFE JACKET									Component ATA:25
PN:63600-105	MOS/MSC	13-Feb-20	O/C	TSN 3						
SN:L4939550	HRS	9310.8		TSN 0						
	AFL	4969		TSN 0						
PROC. REF: GENERIC NO REF										
256003-7101	NO. 1 LIFE RAFT									Component ATA:25
PN:69FASA-631-1-702	MOS/MSC	30-Mar-22	O/C	TSO 0						
SN:64L-01766	HRS	9837		TSO 0						
	AFL	5241		TSO 0						
PROC. REF: GENERIC NO REF										
256003-7102	NO. 2 LIFE RAFT									Component ATA:25
PN:R0103A105	MOS/MSC	10-Jan-24	O/C							
SN:TQ09158	HRS	10396.8								
	AFL	5532								
PROC. REF: GENERIC NO REF										
256100-0101	CREW CAB MODULE -ELT ASSEMBLY									Component ATA:25
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-61-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 25 - EQUIPMENT/FURNISHINGS											
256104-0101		ELT - RADIO/NAVIGATION SYS, EMERGENCY LOCATOR TRANSMITTER							Component	ATA:25	
PN:ELT97A256000000	MOS/MSC	18-Jan-21	O/C	TSN 211							
SN:3582	HRS	9506.9									
	AFL	5061									
PROC. REF: AMM 25-61-01											
256104-0101D		DISCARD EMERGENCY LOCATOR TRANSMITTER (ELT) BATTERY (NOTE: IN ACCORDANCE WITH MANUFACTURERS DATAPLATE EXPIRATION DATE OR LOCAL REGULATORY AUTHORITY REQUIREMENTS).							Service	ATA:25	
PN:PN-UNKNOWN	MOS/MSC	16-Aug-24	DUE	31-Aug-29 (M)			1750 d	SYSTEM			
SN:UNKNOWN	HRS	10541.4									
	AFL	5613									
PROC. REF: GENERIC NO REF											
256104-0102		EMERGENCY LOCATOR TRANSMITTER (ELT) BATTERY							Component	ATA:25	
PN:PN-UNKNOWN	MOS/MSC	18-Jan-21	C/C								
SN:UNKNOWN	HRS	9506.9									
	AFL	5061									
PROC. REF: GENERIC NO REF											
256203-0701 ^U		NO. 1 LIFE RAFT EMERGENCY LOCATOR TRANSMITTER (ELT) BEACON							Component	ATA:25	
PN:P3-03-0041-101	MOS/MSC	19-Feb-21	O/C								
SN:141467	HRS	9508.9									
	AFL	5061									
256203-0702 ^U		NO. 2 LIFE RAFT EMERGENCY LOCATOR TRANSMITTER (ELT) BEACON							Component	ATA:25	
PN:PN	MOS/MSC	10-Jan-24	O/C								
SN:UNKNOWN	HRS	10396.8									
	AFL	5532									
256203-0801 ^U		NO. 1 LIFE RAFT EMERGENCY LOCATOR TRANSMITTER (ELT) BEACON BATTERY							Component	ATA:25	
PN:K2-01-0003-001	MOS/MSC	30-Mar-22	H/T	TSN 0							
SN:UNKNOWN	HRS	9837		TSN 0							
	AFL	5241		TSN 0							
256203-0802 ^U		NO. 2 LIFE RAFT EMERGENCY LOCATOR TRANSMITTER (ELT) BEACON BATTERY							Component	ATA:25	
PN:PN	MOS/MSC	19-Feb-21	H/T	TSN 0							
SN:UNKNOWN	HRS	9508.9		TSN 0							
	AFL	5061		TSN 0							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
259001-0101	COCKPIT TOUCH SCREEN, REMOTE - TSU9600 UNIT									Component ATA:25
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: GENERIC NO REF										
259500-0201	REAR ELT ANTENNA									Component ATA:25
PN:S65-1231	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:160-1046	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 25-61-03										
259502-7302	ASSY- AFT DIVAN SEAT									Component ATA:25
PN:2523.714.01-13	MOS/MSC	14-Aug-13	O/C	TSN 0						
SN:070322-11	HRS	6643.4	TSN 0							
	AFL	3572	TSN 0							
PROC. REF: GENERIC NO REF										
259502-7304	NO.1 DOUBLE, SERIES 200 SEAT									Component ATA:25
PN:2524.551.01-501A	MOS/MSC	14-Aug-13	O/C	TSN 0						
SN:070322-07	HRS	6643.4	TSN 0							
	AFL	3572	TSN 0							
PROC. REF: GENERIC NO REF										
259502-7305	NO. 2 DOUBLE, SERIES 200 SEAT									Component ATA:25
PN:2524.551.01-505B	MOS/MSC	14-Aug-13	O/C	TSN 0						
SN:070322-08	HRS	6643.4	TSN 0							
	AFL	3572	TSN 0							
PROC. REF: GENERIC NO REF										
259502-7306	FWD DIVAN SEAT									Component ATA:25
PN:2523.714.01-11	MOS/MSC	14-Aug-13	O/C	TSN 0						
SN:070322-09	HRS	6643.4	TSN 0							
	AFL	3572	TSN 0							
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
259502-7307	MID DIVAN SEAT									Component ATA:25
PN:2523.714.01-12	MOS/MSC		14-Aug-13	O/C						
SN:070322-10	HRS		6643.4							
	AFL		3572							
PROC. REF: GENERIC NO REF										
259502-7308	SINGLE SERIES 200 SEAT									Component ATA:25
PN:2524.550.01-501A	MOS/MSC		14-Aug-13	O/C						
SN:070322-01	HRS		6643.4							
	AFL		3572							
PROC. REF: GENERIC NO REF										
259502-7309	SINGLE SERIES 200 SEAT									Component ATA:25
PN:2524.550.01-509B	MOS/MSC		14-Aug-13	O/C						
SN:070322-03	HRS		6643.4							
	AFL		3572							
PROC. REF: GENERIC NO REF										
259502-7310	SINGLE SERIES 200 SEAT									Component ATA:25
PN:2524.550.01-502B	MOS/MSC		14-Aug-13	O/C						
SN:070322-02	HRS		6643.4							
	AFL		3572							
PROC. REF: GENERIC NO REF										
259502-7311	SINGLE SERIES 200 SEAT									Component ATA:25
PN:2524.550.01-515A	MOS/MSC		14-Aug-13	O/C						
SN:070322-04	HRS		6643.4							
	AFL		3572							
PROC. REF: GENERIC NO REF										
259502-7312	SINGLE SERIES 200 SEAT									Component ATA:25
PN:2524.550.01-503A	MOS/MSC		14-Aug-13	O/C						
SN:070322-05	HRS		6643.4							
	AFL		3572							
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 25 - EQUIPMENT/FURNISHINGS											
259502-7313		SINGLE SERIES 200 SEAT								Component	ATA:25
PN:2524.550.01-501B	MOS/MSC	14-Aug-13	O/C								
SN:070322-06	HRS	6643.4									
	AFL	3572									
PROC. REF: GENERIC NO REF											
261401-0101		LAVATORY SMOKE DETECTOR								Component	ATA:25
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 26-14-01											
ATA 26 - FIRE PROTECTION											
26-14-00-710-001-A00 ^S		OPERATIONALLY CHECK LAVATORY SMOKE DETECTOR (ACTUATING THE SMOKE SENSOR WITH SMOKE) NOTE: IF INSTALLED								Service	ATA:26
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	4000 (+20/-20)								
	AFL	5401	2000 (+20/-20)								
PROC. REF: AMM 26-14-01											
26-14-01-960-001-A00		DISCARD JAMCO LAVATORY SMOKE DETECTOR (IF INSTALLED)								Service	ATA:26
	MOS/MSC	25-Sep-07	N/A								
	HRS	0									
	AFL	0									
PROC. REF: AMM 26-14-01											
26-15-01-140-001-A00 ^S		RESTORE (CLEANING) BAGGAGE SMOKE DETECTOR CLEANING OF BAGGAGE SMOKE DETECTORS								Service	ATA:26
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	2000 (+20/-20)								
	AFL	5401	1000 (+20/-20)								
PROC. REF: AMM 26-15-01											
26-21-00-720-001-A00		FUNCTIONALLY CHECK ENGINE FIRE EXTINGUISHING SYSTEM								Service	ATA:26
	MOS	14-Jul-22	36		14-Jul-25		241 d	SYSTEM			
	HRS	9915.8									
	AFL	5271									
PROC. REF: AMM 26-21-00											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 26 - FIRE PROTECTION										
26-21-02-720-001-A00 FUNCTIONALLY CHECK (HYDROSTATIC TEST) LH ENGINE FIRE EXTINGUISHER BOTTLE										
PN:33600057-5	MOS/MSC	06-Jul-22	O/C							Service ATA:26
SN:57143D1	HRS									
	AFL									
			HydroCheck Date: : 06-Jul-22	PROC. REF: AMM 26-21-02						
26-21-02-720-001-A00 FUNCTIONALLY CHECK (HYDROSTATIC TEST) RH ENGINE FIRE EXTINGUISHER BOTTLE										
PN:33600057-5	MOS/MSC	16-Jun-21	O/C							Service ATA:26
SN:74313D1	HRS									
	AFL									
			HydroCheck Date: : 16-Jun-21	PROC. REF: AMM 26-21-02						
26-21-03-720-001-A00 FUNCTIONALLY CHECK L/H ENGINE FIRE EXTINGUISHING BOTTLE PRESSURE SWITCH-NOTE: IF INSTALLED.										
	MOS	14-Jul-22	60		14-Jul-27		971 d	SYSTEM		Service ATA:26
	HRS	9915.8								
	AFL	5271								
			PROC. REF: AMM 26-21-03							
26-21-03-720-001-A00 FUNCTIONALLY CHECK R/H ENGINE FIRE EXTINGUISHING BOTTLE PRESSURE SWITCH -NOTE: IF INSTALLED.										
	MOS	29-Jul-21	60		29-Jul-26		621 d	SYSTEM		Service ATA:26
	HRS	9631.4								
	AFL	5130								
			PROC. REF: AMM 26-21-03							
26-21-04-960-001-A00 DISCARD (SERVICE LIFE) NO. 1 LH ENGINE FIRE EXTINGUISHER BOTTLE (A) CARTRIDGE										
PN:M30903920	MOS	06-Jul-22	72		06-Jul-28		1329 d	SERVICE LIFE LIMIT		Service ATA:26
SN:08165	HRS									
	AFL									
			Installation Date: : 06-Jul-22	PROC. REF: AMM 26-21-04						
26-21-04-960-001-A00 DISCARD (SERVICE LIFE) NO. 1 RH ENGINE FIRE EXTINGUISHER BOTTLE (B) CARTRIDGE										
PN:30903920	MOS	18-Jul-21	72		18-Jul-27		975 d	SERVICE LIFE LIMIT		Service ATA:26
SN:ESD20H218-001	HRS									
	AFL									
			Installation Date: : 18-Jul-21	PROC. REF: AMM 26-21-04						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 26 - FIRE PROTECTION										
26-21-04-960-001-A00 DISCARD (SERVICE LIFE) NO. 2 LH ENGINE FIRE EXTINGUISHER BOTTLE (A) CARTRIDGE Service ATA:26										
PN:M30903920	MOS	06-Jul-22	72		06-Jul-28		1329 d	SERVICE LIFE LIMIT		
SN:08093	HRS									
	AFL									
			Installation Date: : 06-Jul-22		PROC. REF: AMM 26-21-04					
26-21-04-960-001-A00 DISCARD (SERVICE LIFE) NO. 2 RH ENGINE FIRE EXTINGUISHER BOTTLE (B) CARTRIDGE Service ATA:26										
PN:30903920	MOS	18-Jul-21	72		18-Jul-27		975 d	SERVICE LIFE LIMIT		
SN:ESD20H218-001	HRS									
	AFL									
			Installation Date: : 18-Jul-21		PROC. REF: AMM 26-21-04					
26-21-04-960-001-A00-M DISCARD (LIFE LIMIT) NO. 1 LH ENGINE FIRE EXTINGUISHER BOTTLE (A) CARTRIDGE Service ATA:26										
PN:M30903920	MOS	01-Feb-22	108		01-Feb-31		2269 d	LIFE LIMIT		
SN:08165	HRS									
	AFL									
			Manufacture Date:: 01-Feb-22		PROC. REF: AMM 26-21-04					
26-21-04-960-001-A00-M DISCARD (LIFE LIMIT) NO. 1 RH ENGINE FIRE EXTINGUISHER BOTTLE (B) CARTRIDGE Service ATA:26										
PN:30903920	MOS	01-Jun-21	108		01-Jun-30		2024 d	LIFE LIMIT		
SN:ESD20H218-001	HRS									
	AFL									
			Manufacture Date:: 01-Jun-21		PROC. REF: AMM 26-21-04					
26-21-04-960-001-A00-M DISCARD (LIFE LIMIT) NO. 2 LH ENGINE FIRE EXTINGUISHER BOTTLE (A) CARTRIDGE Service ATA:26										
PN:M30903920	MOS	01-Feb-22	108		01-Feb-31		2269 d	LIFE LIMIT		
SN:08093	HRS									
	AFL									
			Manufacture Date:: 01-Feb-22		PROC. REF: AMM 26-21-04					
26-21-04-960-001-A00-M DISCARD (LIFE LIMIT) NO. 2 RH ENGINE FIRE EXTINGUISHER BOTTLE (B) CARTRIDGE Service ATA:26										
PN:30903920	MOS	01-Jun-21	108		01-Jun-30		2024 d	LIFE LIMIT		
SN:ESD20H218-001	HRS									
	AFL									
			Manufacture Date:: 01-Jun-21		PROC. REF: AMM 26-21-04					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 26 - FIRE PROTECTION										
26-21-05-720-001-A00 FUNCTIONALLY CHECK ENGINE FIRE EXTINGUISHING TWO-WAY "TEE" CHECK VALVES										
	MOS	16-Aug-24	72		16-Aug-30		2100 d	SYSTEM		Service ATA:26
	HRS	10541.4	8000		18541.4		7945.8			
	AFL	5613								
PROC. REF: AMM 26-21-05										
26-22-00-720-001-A00 FUNCTIONALLY CHECK APU FIRE-EXTINGUISHING SYSTEM (BETWEEN SWITCH AND BOTTLE CONNECTOR) AND VERIFY APU ISOLATION BY APU FUEL SHUTOFF VALVE ACTUATION.										
	MOS	14-Jul-22	36		14-Jul-25		241 d	SYSTEM		Service ATA:26
	HRS	9915.8								
	AFL	5271								
PROC. REF: AMM 26-22-00										
26-22-01-720-001-A00 FUNCTIONALLY CHECK (HYDROSTATIC TEST) APU FIRE EXTINGUISHER,REAR APU BOTTLE										
PN:30100050-5	MOS/MSC	01-Apr-20	O/C							Service ATA:26
SN:95144A1	HRS									
	AFL									
HydroCheck Date: : 01-Apr-20 PROC. REF: AMM 26-22-01										
26-22-02-720-001-A00 FUNCTIONALLY CHECK APU FIRE EXTINGUISHING BOTTLE PRESSURE SWITCH										
	MOS	29-Jul-21	60		29-Jul-26		621 d	SYSTEM		Service ATA:26
	HRS	9631.4								
	AFL	5130								
PROC. REF: AMM 26-22-02										
26-22-03-960-001-A00 DISCARD APU FIRE EXTINGUISHING BOTTLE CARTRIDGE (SERVICE LIFE)										
PN:30903920	MOS	23-Jul-21	72		23-Jul-27		980 d	SERVICE LIFE LIMIT		Service ATA:26
SN:ESD19D208-001	HRS									
	AFL									
Installation Date: : 23-Jul-21 PROC. REF: AMM 26-22-03										
26-22-03-960-001-A00-M DISCARD APU FIRE EXTINGUISHING BOTTLE CARTRIDGE (LIFE LIMIT)										
PN:30903920	MOS	01-Jul-20	108		01-Jul-29		1689 d	LIFE LIMIT		Service ATA:26
SN:ESD19D208-001	HRS									
	AFL									
Manufacture Date:: 01-Jul-20 PROC. REF: AMM 26-22-03										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 26 - FIRE PROTECTION											
26-23-00-720-001-A00 ^S		FUNCTIONALLY CHECK BAGGAGE-COMPARTMENT FIRE EXTINGUISHING SYSTEM (COVERING THE PRESSURE SWITCH, CARTRIDGE, BAGG FIRE EXTING.SWITCH AND ELECTRICAL HARDWARE).							Service	ATA:26	
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	2000 (+20/-20)								
	AFL	5401	1000 (+20/-20)								
						PROC. REF: AMM 26-23-00					PKG:5008,6016
26-23-01-720-001-A00		FUNCTIONALLY CHECK (HYDROSTATIC TEST) OF NO.1 BAGGAGE FIRE EXTINGUISHING BOTTLES (HIGH RATE)							Service	ATA:26	
PN:33700027-1	MOS/MSC	24-Jan-20	O/C		01-Jan-25 (M)		47 d				
SN:64533D1	HRS										
	AFL										
						PROC. REF: AMM 26-23-01					
26-23-01-720-001-A00		FUNCTIONALLY CHECK (HYDROSTATIC TEST) OF NO.2 BAGGAGE FIRE EXTINGUISHING BOTTLES (METERING)							Service	ATA:26	
PN:34600073-3	MOS/MSC	01-Dec-16	O/C								
SN:27095F1	HRS										
	AFL										
						HydroCheck Date: : 01-Dec-16					PROC. REF: AMM 26-23-01
26-23-01-720-002-A00		FUNCTIONALLY CHECK NO. 1 BAGGAGE COMPARTMENT FIREEXTINGUISHING BOTTLE (HIGH RATE) FOR WEIGHT NOTE: FROM THE MANUFACTURE DATE OR LAST TASK ACCOMPLISHMENT							Service	ATA:26	
PN:33700027-1	MOS	15-Jan-20	60 (+30d/-30d)		15-Jan-25	14-Feb-25	61 d (+30)	SYSTEM			
SN:64533D1	HRS										
	AFL										
						WeightCheck Date : : 15-Jan-20					PROC. REF: AMM 26-23-01
26-23-01-720-002-A00		FUNCTIONALLY CHECK NO. 2 BAGGAGE COMPARTMENT FIREEXTINGUISHING BOTTLE (METERING) FOR WEIGHT							Service	ATA:26	
PN:34600073-3	MOS	10-Jan-23	60 (+30d/-30d)		10-Jan-28	09-Feb-28	1151 d (+30)	SYSTEM			
SN:27095F1	HRS										
	AFL										
						WeightCheck Date : : 10-Jan-23					PROC. REF: AMM 26-23-01
26-23-02-960-001-A00		DISCARD BAGGAGE COMPARTMENT HIGH RATE FIRE EXTINGUISHER BOTTLE CARTRIDGE (SERVICE LIFE) NOTE: 180 MO FROM DATE OFMANUFACTURING OR 120 MO FROM DATE OF INSTALLATION, WHICHEVER OCCURS FIRST.							Service	ATA:26	
PN:M30903870	MOS	24-Jan-20	120		24-Jan-30		1896 d	SERVICE LIFE LIMIT			
SN:11860	HRS										
	AFL										
						Installation Date: : 24-Jan-20					PROC. REF: AMM 26-23-02

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 26 - FIRE PROTECTION											
26-23-02-960-001-A00		DISCARD BAGGAGE COMPARTMENT METERING FIRE EXTINGUISHER BOTTLE CARTRIDGE (SERVICE LIFE) NOTE: 180 MO FROM DATE OFMANUFACTURING OR 120 MO FROM DATE OF INSTALLATION, WHICHEVER OCCURS FIRST.							Service	ATA:26	
PN:30903870	MOS	24-Jul-21	120		24-Jul-31		2442 d	SERVICE LIFE LIMIT			
SN:1342AJ	HRS										
	AFL										
		Installation Date: : 24-Jul-21		PROC. REF: AMM 26-23-02							
26-23-02-960-001-A00-M		DISCARD BAGGAGE COMPARTMENT HIGH RATE FIRE EXTINGUISHER BOTTLE CARTRIDGE (LIFE LIMIT)							Service	ATA:26	
PN:M30903870	MOS	31-Jul-15	180		31-Jul-30		2084 d	LIFE LIMIT			
SN:11860	HRS	7460									
	AFL	3992									
		Manufacture Date:: 31-Jul-15		PROC. REF: AMM 26-23-02							
26-23-02-960-001-A00-M		DISCARD BAGGAGE COMPARTMENT METERING FIRE EXTINGUISHER BOTTLE CARTRIDGE (LIFE LIMIT)							Service	ATA:26	
PN:30903870	MOS	17-Jan-17	180		17-Jan-32		2619 d	LIFE LIMIT			
SN:1342AJ	HRS	8039.6									
	AFL	4314									
		Manufacture Date:: 17-Jan-17		PROC. REF: AMM 26-23-02							
26-23-04-720-001-A00 ^S		FUNCTIONALLY CHECK BAGGAGE FIRE EXTINGUISHING TWO-WAY "TEE" CHECK VALVE							Service	ATA:26	
	MOS	06-Jul-19	72 (+15d/-15d)					LOW UTILIZATION			
	HRS	9057.4	3000 (+20/-20)								
	AFL	4853	1500 (+20/-20)								
		PROC. REF: AMM 26-23-04								PKG:5012,6020	
26-23-05-212-001-A00 ^S		INSPECT (GENERAL VISUAL) DISCHARGE PIPING FOR CRACKS, BENT AND LOOSEFITTINGS, AND NOZZLES FOR DAMAGE.INSPECT (GENERAL VISUAL) DISCHARGE PIPING FOR CRACKS, BENT AND LOOSEFITTINGS, AND NOZZLES FOR DAMAGE.							Service	ATA:26	
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	4000 (+20/-20)								
	AFL	5401	2000 (+20/-20)								
		PROC. REF: AMM 05-20-44								PKG:5016,6032	
26-24-00-720-001-A00		FUNCTIONALLY CHECK OF COCKPIT PORTABLE FIRE EXTINGUISHING BOTTLE FOR WEIGHT (SEE PLACARD ATTACHED TO THE BOTTLE) NOTE: FROM THE MANUFACTURE DATE OR LAST TASK ACCOMPLISHMENT.							Service	ATA:26	
PN:RT-A1200	MOS	16-Aug-24	12		16-Aug-25		274 d	SYSTEM			
SN:Y-502093	HRS	10541.4									
	AFL	5613									
		PROC. REF: AMM 26-24-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 26 - FIRE PROTECTION											
26-24-00-720-001-A00		FUNCTIONALLY CHECK OF FORWARD PORTABLE FIRE EXTINGUISHING BOTTLE FOR WEIGHT (SEE PLACARD ATTACHED TO THE BOTTLE) NOTE: FROM THE MANUFACTURE DATE OR LAST TASK ACCOMPLISHMENT.							Service	ATA:26	
PN:BA21741SR-5	MOS	16-Aug-24	12		16-Aug-25		274 d	SYSTEM			
SN:104464	HRS	10541.4									
	AFL	5613									
PROC. REF: AMM 26-24-00											
26-24-00-960-001-A00		DISCARD FORWARD PORTABLE FIRE EXTINGUISHER P/N BA21741 SERIESNOTE: FROM THE MANUFACTURE DATE							Service	ATA:26	
	MOS		120		01-Jul-27 (M)		958 d	LIFE LIMIT			
	HRS										
	AFL										
PROC. REF: AMM 26-24-01											
26-24-00-960-001-A01		DISCARD COCKPIT PORTABLE FIRE EXTINGUISHER P/N RT A1200 OR P3APP003000-SERIES.NOTE: FROM THE MANUFACTURE DATENOTE: IF INSTALLED							Service	ATA:26	
PN:RT-A1200	MOS	06-Jul-19	144		01-Mar-31 (M)		2297 d	LIFE LIMIT			
SN:Y-502093	HRS	9057.4									
	AFL	4853									
PROC. REF: AMM 26-24-01											
26-24-CUS-0101 ^U		VISUAL INSPECTION COCKPIT PORTABLE FIRE EXTINGUISHER BOTTLE							Service	ATA:26	
PN:RT-A1200	MOS	15-Oct-24	1		15-Nov-24		0 d	CUSTOMER CODE			
SN:Y-502093	HRS	10578.1									
	AFL	5634									
26-24-CUS-0102 ^U		VISUAL INSPECTION FORWARD PORTABLE FIRE EXTINGUISHER (PAX CABIN) BOTTLE							Service	ATA:26	
PN:BA21741SR-5	MOS	15-Oct-24	1		15-Nov-24		0 d	CUSTOMER CODE			
SN:104464	HRS	10578.1									
	AFL	5634									
26-25-01-720-001-A00		FUNCTIONALLY CHECK GALLEY FIRE EXTINGUISHING BOTTLE FOR WEIGHT P/N BA22557-1/ BA22653-1							Service	ATA:26	
PN:BA24320F-1	MOS/MSC	30-May-19	N/A								
SN:58391	HRS										
	AFL										
			WeightCheck Date : : 30-May-19		PROC. REF: AMM 26-25-01						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 26 - FIRE PROTECTION										
26-25-01-720-001-A00 FUNCTIONALLY CHECK LAVATORY FIRE EXTINGUISHING BOTTLE FOR WEIGHT P/N BA22557-1/ BA22653-1										
PN:BA22557-1	MOS	16-Aug-24	12		16-Aug-25		274 d	SYSTEM		Service ATA:26
SN:69193	HRS	10541.4								
	AFL	5613								
WeightCheck Date : : 16-Aug-24 PROC. REF: AMM 26-25-01										
26-25-01-720-001-A01 FUNCTIONALLY CHECK GALLEY FIRE EXTINGUISHING BOTTLE FOR WEIGHT P/N BA24320F-1 / BA24320H-1NOTE: FROM THE MANUFACTURE DATE OR LAST TASK ACCOMPLISHMENT.										
PN:BA24320F-1	MOS	06-Feb-20	60		06-Feb-25		83 d			Service ATA:26
SN:58391	HRS									
	AFL									
PROC. REF: AMM 26-25-01										
26-25-01-720-001-A01 FUNCTIONALLY CHECK LAVATORY FIRE EXTINGUISHING BOTTLE FOR WEIGHT P/N BA24320F-1 / BA24320H-1NOTE: FROM THE MANUFACTURE DATE OR LAST TASK ACCOMPLISHMENT.										
	MOS/MSC	27-Aug-07	N/A							Service ATA:26
	HRS	0								
	AFL	0								
PROC. REF: AMM 26-25-01										
260000-0101 OVERH P FIRE EXTINGUISHING APU/BAGG MODULE										
PN:145-34156-401	MOS/MSC	27-Aug-07	O/C	TSN 0						Component ATA:26
SN:0000122878	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
261101-0101 LH ENGINE ACC FIRE DETECTOR										
PN:3601-133-500/230C-9.0M	MOS/MSC	27-Aug-07	O/C	TSN 0						Component ATA:26
SN:236171	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 26-11-01										
261101-0102 RH ENGINE ACC FIRE DETECTOR										
PN:3601-133-500/230C-9.0M	MOS/MSC	27-Aug-07	O/C	TSN 0						Component ATA:26
SN:236183	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 26-11-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 26 - FIRE PROTECTION										
261102-0101 LH ENGINE PYLON FIRE DETECTOR Component ATA:26										
PN:3601-134-480/220C-2.7M	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:235805	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 26-11-02										
261102-0102 RH ENGINE PYLON FIRE DETECTOR Component ATA:26										
PN:3601-134-480/220C-2.7M	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:235807	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 26-11-02										
261103-0101 LH CSL CONTROL-FIRE PROTECTION SYS, CONSOLE, COCKPIT MODULE Component ATA:26										
PN:902081	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 26-11-03										
261103-0102 RH CSL CONTROL-FIRE PROTECTION SYS, CONSOLE, COCKPIT MODULE Component ATA:26										
PN:902081	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 26-11-03										
261103-0103 LH CSL CONTROL-FIRE PROTECTION SYS, CONSOLE, COCKPIT MODULE Component ATA:26										
PN:902081	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 26-11-03										
261201-0101 APU APU FIRE DETECTOR Component ATA:26										
PN:3601-135-470/200C-3.5M	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:235600	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 26-12-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 26 - FIRE PROTECTION											
261500-0101		BAGGAGE COMPARTMENT CEILING SMOKE DETECTOR								Component	ATA:26
PN:473597-13	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 26-15-01											
261500-0102		BAGGAGE BULKHEAD SMOKE DETECTOR								Component	ATA:26
PN:473597-13	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 26-15-01											
262101-0101		PILOT FIRE EXTINGUISHING,ENGINE OVERHEAD PANEL,PAX CABIN HANDLE								Component	ATA:26
PN:1-7054-3	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:1656	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 26-21-01											
262101-0102		COPILOT FIRE EXTINGUISHING,ENGINE 2-OVERHEAD PANEL HANDLE								Component	ATA:26
PN:2-7054-3	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:1674	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 26-21-01											
262102-0101		LH ENGINE FIRE EXTINGUISHER BOTTLE (A)								Component	ATA:26
PN:33600057-5	MOS/MSC	14-Jul-22	O/C	TSO 0							
SN:57143D1	HRS	9915.8		TSO 0							
	AFL	5271		TSO 0							
PROC. REF: AMM 26-21-02											
262102-0102		RH ENGINE FIRE EXTINGUISHER BOTTLE (B)								Component	ATA:26
PN:33600057-5	MOS/MSC	20-Jul-21	O/C	TSN 122, TSO 1							
SN:74313D1	HRS	9631.4		TSO 0							
	AFL	5130		TSO 0							
PROC. REF: AMM 26-21-02											
262104-0101		NO. 1 LH ENGINE FIRE EXTINGUISHER BOTTLE (A) CARTRIDGE								Component	ATA:26
PN:M30903920	MOS/MSC	14-Jul-22	H/T	TSN 0							
SN:08165	HRS	9915.8		TSN 0							
	AFL	5271		TSN 0							
		Manufacture Date:: 01-Feb-22		PROC. REF: AMM 26-21-04							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 26 - FIRE PROTECTION											
262104-0102		NO. 2 LH ENGINE FIRE EXTINGUISHER BOTTLE (A) CARTRIDGE								Component	ATA:26
PN:M30903920	MOS/MSC	14-Jul-22	H/T	TSN 0							
SN:08093	HRS	9915.8		TSN 0							
	AFL	5271		TSN 0							
			Manufacture Date:: 01-Feb-22	PROC. REF: AMM 26-21-04							
262104-0201		NO. 1 RH ENGINE FIRE EXTINGUISHER BOTTLE (B) CARTRIDGE								Component	ATA:26
PN:30903920	MOS/MSC	18-Jul-21	H/T	TSN 1							
SN:ESD20H218-001	HRS	9631.4		TSN 0							
	AFL	5130		TSN 0							
			Manufacture Date:: 01-Jun-21	PROC. REF: AMM 26-21-04							
262104-0202		NO. 2 RH ENGINE FIRE EXTINGUISHER BOTTLE (B) CARTRIDGE								Component	ATA:26
PN:30903920	MOS/MSC	18-Jul-21	H/T	TSN 1							
SN:ESD20H218-001	HRS	9631.4		TSN 0							
	AFL	5130		TSN 0							
			Manufacture Date:: 01-Jun-21	PROC. REF: AMM 26-21-04							
262201-0101		APU FIRE EXTINGUISHER,REAR APU BOTTLE								Component	ATA:26
PN:30100050-5	MOS/MSC	23-Jul-21	O/C	TSN 1							
SN:95144A1	HRS	9631.4		TSN 0							
	AFL	5130		TSN 0							
			PROC. REF: AMM 26-22-01								
262202-0201		APU FIRE EXTINGUISHER BOTTLE CARTRIDGE								Component	ATA:26
PN:30903920	MOS/MSC	23-Jul-21	H/T	TSN 12							
SN:ESD19D208-001	HRS	9631.4		TSN 0							
	AFL	5130		TSN 0							
			Manufacture Date:: 01-Jul-20	PROC. REF: AMM 26-22-03							
262301-0101		NO.1 BAGGAGE COMPARTMENT HIGH RATE FIRE EXTINGUISHER BOTTLE								Component	ATA:26
PN:33700027-1	MOS/MSC	13-Feb-20	O/C	TSN 136, TSO 1							
SN:64533D1	HRS	9310.8		TSO 0							
	AFL	4969		TSO 0							
			PROC. REF: AMM 26-23-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 26 - FIRE PROTECTION										
262301-0102 NO.2 BAGGAGE COMPARTMENT METERING FIRE EXTINGUISHER BOTTLE Component ATA:26										
PN:34600073-3	MOS/MSC	10-Jan-23	O/C	TSN 203, TSO 72						
SN:27095F1	HRS	10066.9	TSO 2027.3							
	AFL	5346	TSO 1032							
PROC. REF: AMM 26-23-01										
262302-0201 BAGGAGE COMPARTMENT HIGH RATE FIRE EXTINGUISHER BOTTLE CARTRIDGE Component ATA:26										
PN:M30903870	MOS/MSC	13-Feb-20	H/T	TSN 0						
SN:11860	HRS	9310.8								
	AFL	4969								
PROC. REF: AMM 26-23-02										
262302-0202 BAGGAGE COMPARTMENT METERING FIRE EXTINGUISHER BOTTLE CARTRIDGE Component ATA:26										
PN:30903870	MOS/MSC	26-Jul-21	H/T	TSN 10						
SN:1342AJ	HRS	9631.4	TSN 0							
	AFL	5130	TSN 0							
PROC. REF: AMM 26-23-02										
262400-0101 COCKPIT PORTABLE FIRE EXTINGUISHER BOTTLE Component ATA:26										
PN:RT-A1200	MOS/MSC	06-Jul-19	H/T	TSN 1						
SN:Y-502093	HRS	9057.4	TSN 0							
	AFL	4853	TSN 0							
PROC. REF: AMM 26-24-01										
262400-0102 FORWARD PORTABLE FIRE EXTINGUISHER (PAX CABIN) BOTTLE Component ATA:26										
PN:BA21741SR-5	MOS/MSC	01-Sep-17	H/T	TSN 2						
SN:104464	HRS	8284.1	TSN 0							
	AFL	4446	TSN 0							
PROC. REF: AMM 26-24-01										
262500-0101 LAVATORY FIRE EXTINGUISHER WASTE DISPOSAL ASSEMBLY Component ATA:26										
PN:BA22557-1	MOS/MSC	22-Jul-15	O/C	TSN 1						
SN:69193	HRS	7460.3	TSN 0							
	AFL	3992	TSN 0							
PROC. REF: AMM 26-25-01										
262500-0102 GALLEY FIRE EXTINGUISHER WASTE DISPOSAL ASSEMBLY Component ATA:26										
PN:BA24320F-1	MOS/MSC	01-Jul-14	O/C							
SN:58391	HRS	7031.5								
	AFL	3775								
PROC. REF: AMM 26-25-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 26 - FIRE PROTECTION											
264100-0101		LH WING FUEL QUANTITY TRANSMITTER								Component	ATA:26
PN:028-936-003	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:2348B	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: GENERIC NO REF											
ATA 27 - FLIGHT CONTROLS											
27-11-00-220-001-A00 ^S		INSPECT (DETAILED INSPECTION) AILERON PRIMARY MECHANICAL CONTROL FROM CONTROL WHEEL TO AILERON PCAS, CHECKING CABLES, PULLEYS, NRUS, QUADRANTS, DISCONNECT SYSTEM, AND MECHANICAL LINKS								Service	ATA:27
	MOS	29-Jun-23	48 (+15d/-15d)			LOW UTILIZATION					
	HRS	10161.5	2000 (+20/-20)								
	AFL	5401	1000 (+20/-20)								
PROC. REF: AMM 27-11-00										PKG:5008,6016	
27-11-00-640-001-A00 ^S		LUBRICATE CONTROL WHEEL CHAIN								Service	ATA:27
	MOS	29-Jun-23	48 (+15d/-15d)			LOW UTILIZATION					
	HRS	10161.5	2000 (+20/-20)								
	AFL	5401	1000 (+20/-20)								
PROC. REF: AMM 27-11-00										PKG:5008,6016	
27-11-00-720-001-A00 ^S		FUNCTIONALLY CHECK AILERON PRIMARY MECHANICAL CONTROL BACKLASH								Service	ATA:27
	MOS	29-Jun-23	48 (+15d/-15d)			LOW UTILIZATION					
	HRS	10161.5	2000 (+20/-20)								
	AFL	5401	1000 (+20/-20)								
PROC. REF: AMM 27-11-00										PKG:5009	
27-11-01-720-001-A00		FUNCTIONALLY CHECK TENSION OF AILERON CONTROL CABLES								Service	ATA:27
	MOS	26-Jan-24	48 (+30d/-30d)	Adj 18d	13-Feb-28	14-Mar-28	1185 d (+30)	LOW UTILIZATION			
	HRS	10402.1	2000	12402.1		1806.5					
	AFL	5534	1000	6534		885					
PROC. REF: AMM 27-11-01											
27-12-00-720-001-A00 ^S		FUNCTIONALLY CHECK AILERON HYDRAULIC ACTUATION								Service	ATA:27
	MOS	29-Jun-23	96 (+15d/-15d)			LOW UTILIZATION					
	HRS	10161.5	4000 (+20/-20)								
	AFL	5401	2000 (+20/-20)								
PROC. REF: AMM 27-12-00										PKG:5016,6032	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-12-00-720-003-A01 ^S	FUNCTIONALLY CHECK EXTERNAL LEAKAGE OF AILERON HYDRAULIC ACTUATOR (CMR)								Service	ATA:27
	MOS	29-Jun-23	24 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	1000 (+20/-20)							
	AFL	5401								
					PROC. REF: AMM 27-12-00					PKG:5004
27-12-00-720-003-A02	FUNCTIONALLY CHECK EXTERNAL LEAKAGE OF AILERON HYDRAULIC ACTUATOR (CMR)								Service	ATA:27
	MOS/MSC	27-Aug-07	N/A							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-12-00					
27-12-01-212-001-A00 ^S	INSPECT (GENERAL VISUAL) AILERON PCA HOSES								Service	ATA:27
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: AMM 27-12-01					PKG:5008,6016
27-12-01-212-002-A01 ^S	INSPECT (GENERAL VISUAL) AILERON PCA ROD ENDS/FITTING LUGS FOR INTEGRITY AND GENERAL CONDITION (CMR)								Service	ATA:27
	MOS	29-Jun-23	24 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	1000 (+20/-20)							
	AFL	5401								
					PROC. REF: AMM 27-12-01					PKG:5004
27-12-01-212-002-A02	INSPECT (GENERAL VISUAL) AILERON PCA ROD ENDS/FITTING LUGS FOR INTEGRITY AND GENERAL CONDITION (CMR)								Service	ATA:27
	MOS/MSC	27-Aug-07	N/A							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-12-01					
27-12-01-720-001-A01 ^S	FUNCTIONALLY CHECK AILERON-ACTUATOR DAMPING COMPONENTS AND MONITORING DEVICES (CMR)								Service	ATA:27
	MOS	16-Aug-24	12 (+15d/-15d)					LOW UTILIZATION		
	HRS	10541.4	500 (+20/-20)							
	AFL	5613								
					PROC. REF: AMM 27-12-01					PKG:5002
27-12-01-720-001-A02	FUNCTIONALLY CHECK AILERON-ACTUATOR DAMPING COMPONENTS AND MONITORING DEVICES (CMR)								Service	ATA:27
	MOS/MSC	27-Aug-07	N/A							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-12-01					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-12-01-720-002-A00	FUNCTIONALLY CHECK AILERON ACTUATOR FORCE FIGHT (CMR)									Service ATA:27
	MOS/MSC	27-Aug-07	N/A							
	HRS	0								
	AFL	0								
PROC. REF: AMM 27-12-01										
27-12-01-720-002-A01 ^S	FUNCTIONALLY CHECK AILERON ACTUATOR FORCE FIGHT (FOR AIRCRAFT UNDER ANAC/FAA CERTIFICATIONS)									Service ATA:27
	MOS	29-Jun-23	24 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	1000 (+20/-20)							
	AFL	5401								
PROC. REF: AMM 27-12-01										
PKG:5004										
27-12-03-212-001-A00 ^S	VISUALLY CHECK AILERON DAMPER ROD ENDS/FITTING LUGS FOR INTEGRITY AND GENERAL CONDITION (CMR)									Service ATA:27
	MOS	16-Aug-24	12 (+15d/-15d)					LOW UTILIZATION		
	HRS	10541.4	500 (+20/-20)							
	AFL	5613								
PROC. REF: AMM 27-12-03										
PKG:5002										
27-12-03-720-001-A00 ^S	FUNCTIONALLY CHECK AILERON DAMPER DAMPING FORCE (CMR)									Service ATA:27
	MOS	29-Jun-23	24 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	1000 (+20/-20)							
	AFL	5401								
PROC. REF: AMM 27-12-03										
PKG:5004										
27-12-03-720-002-A00 ^S	FUNCTIONALLY CHECK EXTERNAL LEAKAGE OF AILERON DAMPER (CMR)									Service ATA:27
	MOS	29-Jun-23	24 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	1000 (+20/-20)							
	AFL	5401								
PROC. REF: AMM 27-12-03										
PKG:5004										
27-13-00-710-001-A00 ^S	OPERATIONALLY CHECK AILERON SOLENOID-MANIFOLD-SHUTOFF FUNCTION									Service ATA:27
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
PROC. REF: AMM 27-13-00										
PKG:5008,6016										
27-14-00-720-001-A00 ^S	FUNCTIONALLY CHECK ROLL TRIM									Service ATA:27
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
PROC. REF: AMM 27-14-00										
PKG:5008,6016										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-15-00-710-001-A00 ^S	OPERATIONALLY CHECK AILERON DISCONNECT SYSTEM									Service ATA:27
	MOS	29-Jun-23	24 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	1000 (+20/-20)							
	AFL	5401								
					PROC. REF: AMM 27-15-00					PKG:5004
27-15-02-640-001-A00 ^S	LUBRICATE AILERON DISCONNECT SYSTEM (NOTE: THE PLATE MECHANISM IS BENCH LUBRICATED)									Service ATA:27
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
					PROC. REF: AMM 27-15-02					PKG:5016,6032
27-21-00-710-001-A00	OPERATIONALLY CHECK RUDDER MOVABLE PRIMARY STOP MECHANISM									Service ATA:27
	MOS/MS	27-Aug-07	N/A							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-21-00					PKG:6016
27-21-01-220-001-A00 ^S	INSPECT (DETAILED INSPECTION) RUDDER PRIMARY MECHANICAL CONTROL CHECKING CABLES, PULLEYS AND QUADRANTS									Service ATA:27
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: AMM 27-21-01					PKG:5008,6016
27-21-01-720-001-A00	FUNCTIONALLY CHECK TENSION OF RUDDER CONTROL CABLES									Service ATA:27
	MOS	26-Jan-24	48 (+30d/-30d)	Adj 18d	13-Feb-28	14-Mar-28	1185 d (+30)	LOW UTILIZATION		
	HRS	10402.1	2000		12402.1		1806.5			
	AFL	5534	1000		6534		885			
					PROC. REF: AMM 27-21-01					
27-21-02-220-001-A00 ^S	INSPECT (DETAILED INSPECTION) RUDDER MAIN CONTROL FEEDBACK PATH, PCU LINKAGE AND MOUNTING POINTS, RUDDER ACTUATOR ATTACHMENTS, HINGES AND CONNECTING RODS									Service ATA:27
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: AMM 27-21-02					PKG:5008,6016

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-22-00-720-001-A00^S FUNCTIONALLY CHECK RUDDER BACKLASH										
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		Service ATA:27
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
	PROC. REF: AMM 27-22-00									PKG:5008,6016
27-22-00-720-002-A00 FUNCTIONALLY CHECK RUDDER HYDRAULIC DAMPING										
	MOS/MSC	19-Aug-15	N/A							Service ATA:27
	HRS	7460.3								
	AFL	3992								
	PROC. REF: AMM 27-22-00									
27-22-01-720-001-A00^S FUNCTIONALLY CHECK RUDDER POWER CONTROL UNIT/ACTUATORS DIFFERENTIAL PRESSURE										
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		Service ATA:27
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
	PROC. REF: AMM 27-22-01									PKG:5008,6016
27-22-02-212-001-A00^S INSPECT (GENERAL VISUAL) RUDDER ACTUATORS										
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		Service ATA:27
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
	PROC. REF: AMM 27-22-02									PKG:5008,6016
27-23-00-710-002-A00 OPERATIONALLY CHECK ALERTING LIGHT OF THE RUDDER MOVABLE PRIMARY STOP										
	MOS/MSC	23-Jul-15	N/A							Service ATA:27
	HRS	7460.3								
	AFL	3992								
	PROC. REF: AMM 27-23-00									
27-25-00-710-001-A00^S OPERATIONALLY CHECK RUDDER PEDALS AUTO SHUTOFF AND RUDDER MANUAL SHUTOFF FUNCTIONS (CMR)										
	MOS	29-Jun-23	24 (+15d/-15d)					LOW UTILIZATION		Service ATA:27
	HRS	10161.5	1000 (+20/-20)							
	AFL	5401								
	PROC. REF: AMM 27-25-00									PKG:5004
27-31-00-720-001-A00^S FUNCTIONALLY CHECK ELEVATOR PRIMARY MECHANICAL CONTROL BACKLASH										
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		Service ATA:27
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
	PROC. REF: AMM 27-31-00									PKG:5008,6016

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-31-01-220-001-A00 ^S	INSPECT (DETAILED INSPECTION) ELEVATOR CONTROL CABLES									Service ATA:27
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
	PROC. REF: AMM 27-31-01									PKG:5008,6016
27-31-01-720-001-A00	FUNCTIONALLY CHECK TENSION OF THE ELEVATOR CONTROL CABLES									Service ATA:27
	MOS	26-Jan-24	48 (+30d/-30d)	Adj 18d	13-Feb-28	14-Mar-28	1185 d (+30)	LOW UTILIZATION		
	HRS	10402.1	2000		12402.1		1806.5			
	AFL	5534	1000		6534		885			
	PROC. REF: AMM 27-31-01									
27-31-04-710-001-A00 ^S	OPERATIONALLY CHECK SPRING AND SERVO TABS									Service ATA:27
	MOS	16-Aug-24	12 (+15d/-15d)					LOW UTILIZATION		
	HRS	10541.4	500 (+20/-20)							
	AFL	5613								
	PROC. REF: AMM 27-31-04									PKG:5002
27-31-05-220-001-A00 ^S	INSPECT (DETAILED INSPECTION) SERVO TAB FAIL-SAFE ACTUATION LINK (CMR)									Service ATA:27
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
	PROC. REF: AMM 27-31-05									PKG:5008,6016
27-31-05-220-002-A00 ^S	INSPECT (DETAILED INSPECTION) SPRING TAB ATTACHMENT LINK									Service ATA:27
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
	PROC. REF: AMM 27-31-05									PKG:5008,6016
27-35-00-640-001-A00 ^S	LUBRICATE ELEVATOR DISCONNECT SYSTEM (NOTE: THE PLATE MECHANISM IS BENCH LUBRICATED).									Service ATA:27
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
	PROC. REF: AMM 27-35-00									PKG:5016,6032
27-35-00-710-001-A00 ^S	OPERATIONALLY CHECK ELEVATOR DISCONNECT SYSTEM									Service ATA:27
	MOS	29-Jun-23	24 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	1000 (+20/-20)							
	AFL	5401								
	PROC. REF: AMM 27-35-00									PKG:5004

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-36-00-710-001-A00 ^S OPERATIONALLY CHECK STALL PROTECTION SYSTEM Service ATA:27										
	MOS	16-Aug-24	12 (+15d/-15d)					LOW UTILIZATION		
	HRS	10541.4	500 (+20/-20)							
	AFL	5613								
					PROC. REF: AMM 27-36-00					PKG:5002
27-36-00-720-001-A00 ^S FUNCTIONALLY CHECK ICE/SPS SPEEDS INTERFACE CIRCUIT Service ATA:27										
	MOS	16-Aug-24	12 (+15d/-15d)					LOW UTILIZATION		
	HRS	10541.4	500 (+20/-20)							
	AFL	5613								
					PROC. REF: AMM 27-36-00					PKG:5002
27-40-00-710-002-A00 ^S OPERATIONALLY CHECK BACKUP SYS CUTOFF PUSHBUTTON, MAIN SYS CUTOFF SWITCH, AND QUICK DISCONNECT SWITCH Service ATA:27										
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: AMM 27-40-00					PKG:5008,6016
27-40-00-710-003-A00 ^S OPERATIONALLY CHECK LOCKOUT LOGIC OF HORIZONTAL STABILIZER CONTROL UNIT POST-MOD SB 145LEG-27-0016 OR WITH AN EQUIVALENT MODIFICATION FACTORY-INCORPORATED. Service ATA:27										
	MOS	16-Aug-24	12 (+15d/-15d)					LOW UTILIZATION		
	HRS	10541.4	500 (+20/-20)							
	AFL	5613								
					PROC. REF: AMM 27-40-00					PKG:5002
27-40-00-720-001-A00 ^S FUNCTIONALLY CHECK HORIZONTAL STABILIZER BACKLASH Service ATA:27										
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: AMM 27-40-00					PKG:5008,6016
27-40-02-220-001-A00 ^S INSPECT (DETAILED INSPECTION) HORIZONTAL STABILIZER ACTUATOR INTEGRITY AND ATTACHMENTS Service ATA:27										
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: AMM 27-40-02					PKG:5008,6016
27-40-02-610-001-A00 ^S SERVICE (REPLENISH) HORIZONTAL STABILIZER ACTUATOR AND CHECK FOR LEAKAGE. Service ATA:27										
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: AMM 27-40-02					PKG:5008

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-51-00-212-001-A00 ^S	INSPECT (GENERAL VISUAL) FLAP MECHANICAL LINE									Service ATA:27
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
	PROC. REF: AMM 27-51-00									PKG:5008,6016
27-51-00-220-001-A00 ^S	INSPECT (DETAILED INSPECTION) FLAP FLEXIBLE SHAFT									Service ATA:27
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
	PROC. REF: AMM 27-51-00									PKG:5008,6016
27-51-00-610-001-A00	SERVICE (LUBRICATE) FLAP SCREWJACK ACTUATORS GEARBOX (PRE-MOD SB 145LEG-27-0026) (L600 ONLY)									Service ATA:27
	MOS/MSC	15-Aug-13	N/A	Adj 12d						
	HRS	6643.4								
	AFL	3572								
	PROC. REF: AMM 27-51-00									PKG:6016
27-51-00-610-001-A01 ^S	SERVICE (LUBRICATE) FLAP SCREWJACK ACTUATORS GEARBOX (POST-MOD SB 145LEG-27-0026 OR WITH AN EQUIVALENT MODIFICATION FACTORY INCORPORATED)									Service ATA:27
	MOS	06-Jul-19	72 (+15d/-15d)					LOW UTILIZATION		
	HRS	9057.4	3000 (+20/-20)							
	AFL	4853	1500 (+20/-20)							
	PROC. REF: AMM 27-51-00									PKG:5012,6020
27-51-00-640-001-A00 ^S	SERVICE (LUBRICATE) FLAP SCREWJACK ACTUATOR (FSAS)									Service ATA:27
	MOS	16-Aug-24	12 (+15d/-15d)					LOW UTILIZATION		
	HRS	10541.4	500 (+20/-20)							
	AFL	5613								
	PROC. REF: AMM 27-51-00									PKG:5002
27-51-01-720-001-A00 ^S	FUNCTIONALLY CHECK FLAP TRANSMISSION BRAKE HOLDING CAPABILITY									Service ATA:27
	MOS	29-Jun-23	24 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	1000 (+20/-20)							
	AFL	5401								
	PROC. REF: AMM 27-51-01									PKG:5004
27-51-15-220-001-A00 ^S	INSPECT (DETAILED INSPECTION) FLAP ROLLERS FOR STRUCTURAL INTEGRITY									Service ATA:27
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
	PROC. REF: AMM 27-51-15									PKG:5016,6032

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-51-17-720-001-A00^S FUNCTIONAL CHECK MTB FLAP DRIVE MOTOR UNIT(FDMU) HOLDING CAPABILITY										
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		Service ATA:27
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: AMM 27-51-17					PKG:5008,6016
27-53-00-710-001-A00^S OPERATIONALLY CHECK FLAP FAIL MESSAGE										
	MOS	16-Aug-24	12 (+15d/-15d)					LOW UTILIZATION		Service ATA:27
	HRS	10541.4	500 (+20/-20)							
	AFL	5613								
					PROC. REF: AMM 27-53-00					PKG:5002
27-53-00-710-002-A00^S OPERATIONALLY CHECK "TAKEOFF FLAPS" AURAL WARNING AND NO TAKEOFF CONFIGURATION VISUAL WARNING										
	MOS	16-Aug-24	12 (+15d/-15d)					LOW UTILIZATION		Service ATA:27
	HRS	10541.4	500 (+20/-20)							
	AFL	5613								
					PROC. REF: AMM 27-53-00					PKG:5002
27-62-00-720-001-A00^S FUNCTIONALLY CHECK GROUND SPOILER/SPEED BRAKE VALVES, CONTROL CIRCUIT, AND RELATED MESSAGES (CMR)										
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		Service ATA:27
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
					PROC. REF: AMM 27-62-00					PKG:5016,6032
27-63-01-710-001-A00^S OPERATIONALLY CHECK SPOILER SYSTEM										
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		Service ATA:27
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: AMM 27-63-01					PKG:5008,6016
27-71-00-220-001-A00^S INSPECT (DETAILED INSPECTION) ELECTROMECHANICAL GUST LOCK MECHANISM										
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		Service ATA:27
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: AMM 27-71-00					PKG:5008,6016
27-71-00-710-004-A00^S OPERATIONALLY CHECK ELECTROMECHANICAL GUST LOCK SOLENOID FUNCTION										
	MOS	16-Aug-24	12 (+15d/-15d)					LOW UTILIZATION		Service ATA:27
	HRS	10541.4	500 (+20/-20)							
	AFL	5613								
					PROC. REF: AMM 27-71-00					PKG:5002

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
270000-0101 CENTRAL CONSOLE, TRIM CONTROL MODULE Component ATA:27										
PN:145-34177-407	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:0000143331	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
270000-0201 OVERHEAD PANEL, FLIGHT CONTROL MODULE Component ATA:27										
PN:145-21333-403	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:0000140025	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
270101-0101 RUDDER VII BALANCING ASSEMBLY Component ATA:27										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
271100-0101 DISCONNECTION ASSY - AILERON, FUSELAGE FORWARD DEVICE Component ATA:27										
PN:145-37755-409	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:0000133996	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-15-00										
271100-0201 FWD FUS TUBE,TORQUE ASSY ASSEMBLY Component ATA:27										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
271100-0202 FWD FUS TORQUE TUBE ASSY ASSEMBLY Component ATA:27										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
271102-0301 LH WING AILERON ASSEMBLY Component ATA:27										
PN:135-03290-407	MOS/MSC	06-Jul-19	O/C	TSR 0						
SN:0000127949	HRS	9057.4		TSR 0						
	AFL	4853		TSR 0						
PROC. REF: AMM 27-10-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 27 - FLIGHT CONTROLS											
271102-0302		RH WING AILERON ASSEMBLY								Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 27-10-00											
271103-0201		LEFT AILERON CONTROL CABLE ASSY								Component	ATA:27
PN:PN	MOS/MSC	06-Jul-19	O/C	TSN 0							
SN:UNKNOWN	HRS	9057.4	TSN 0								
	AFL	4853	TSN 0								
PROC. REF: AMM 27-11-01											
271103-0202		RIGHT AILERON CONTROL CABLE ASSY								Component	ATA:27
PN:PN	MOS/MSC	06-Jul-19	O/C	TSN 0							
SN:UNKNOWN	HRS	9057.4	TSN 0								
	AFL	4853	TSN 0								
PROC. REF: AMM 27-11-01											
271103-0301		LH PIL AILERON FORCE,COCKPIT SENSOR								Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: GENERIC NO REF											
271103-0302		LH COPIL AILERON FORCE,COCKPIT SENSOR								Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: GENERIC NO REF											
271103-0303		RH PIL AILERON FORCE,COCKPIT SENSOR								Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: GENERIC NO REF											
271103-0304		RH COPIL AILERON FORCE,COCKPIT SENSOR								Component	ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: GENERIC NO REF											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
271200-0101 LH WING NEUTRAL RECOVERY-AILERON CONTROL UNIT Component ATA:27										
PN:373600-1001	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:2052	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-11-07										
271200-0102 RH WING NEUTRAL RECOVERY-AILERON CONTROL UNIT Component ATA:27										
PN:373600-1001	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:1993	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-11-07										
271200-0301 LH REAR MANIFOLD -HYDRAULIC, AILERON SOLENOID ASSEMBLY Component ATA:27										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-12-02										
271200-0302 RH REAR MANIFOLD -HYDRAULIC, AILERON SOLENOID ASSEMBLY Component ATA:27										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-12-02										
271200-0401 LH WING DAMPER ASSEMBLY Component ATA:27										
PN:41012130-104	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:1299	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
271200-0402 RH WING DAMPER ASSEMBLY Component ATA:27										
PN:41012130-104	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:1298	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
271200-0501 LH WING HYDRAULIC-AILERON ACTUATOR Component ATA:27										
PN:418800-1007	MOS/MSC	27-Aug-14	O/C	TSR 0						
SN:2483AB	HRS	7112.9		TSR 0						
	AFL	3811		TSR 0						
PROC. REF: AMM 27-12-01, AMM 27-12-04										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
271200-0502 RH WING HYDRAULIC-AILERON ACTUATOR Component ATA:27										
PN:418800-1007	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:2488A	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: AMM 27-12-01, AMM 27-12-04										
271400-0101 FORWARD ELECTROMECHANICAL ACTUATOR Component ATA:27										
PN:PN	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: AMM 27-71-01										
271400-0102 RUDDER ELECTROMECHANICAL ACTUATOR Component ATA:27										
PN:PN	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: AMM 27-71-01										
271400-0201 FORWARD FEEL-POSITION, AILERON TRIM TAB UNIT Component ATA:27										
PN:367000-1005	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:1045	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: AMM 27-14-00										
271500-0101 CREW CAB MODULE -AILERON DISCONNECTION,CENTRAL CONSOLE ASSEMBLY Component ATA:27										
PN:PN	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: AMM 27-15-00										
272100-0201 ASSY ACTUATOR Component ATA:27										
PN:PN	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: GENERIC NO REF										
272100-0202 ASSY ACTUATOR Component ATA:27										
PN:PN	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
272100-0301 PROF COP ELEVATOR/RUDDER FORCE,COCKPIT SENSOR Component ATA:27										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
272100-0302 PROF PIL ELEVATOR/RUDDER FORCE,COCKPIT SENSOR Component ATA:27										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
272100-0303 RUD COP ELEVATOR/RUDDER FORCE,COCKPIT SENSOR Component ATA:27										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
272100-0304 RUD PIL ELEVATOR/RUDDER FORCE,COCKPIT SENSOR Component ATA:27										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
272100-0401 ROD ASSEMBLY Component ATA:27										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-21-08										
272100-0402 ROD ASSEMBLY Component ATA:27										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-21-08										
272100-0501 PILOT PEDAL ASSEMBLY Component ATA:27										
PN:145-27402-405	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:0000131839	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-21-07										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
272100-0502 COPILOT PEDAL ASSEMBLY Component ATA:27										
PN:145-27402-407	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:0000131840	HRS	0			TSN 0					
	AFL	0			TSN 0					
PROC. REF: AMM 27-21-07										
272101-0101 LH PIL ACTUATOR LINEAR -ROTARY ELECTROMECHANICAL, CONTROL RUDDER ASSEMBLY Component ATA:27										
PN:6203	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:2936	HRS	0			TSN 0					
	AFL	0			TSN 0					
PROC. REF: AMM 27-21-01										
272101-0102 RH COPIL ACTUATOR LINEAR -ROTARY ELECTROMECHANICAL, CONTROL RUDDER ASSEMBLY Component ATA:27										
PN:6203	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:2935	HRS	0			TSN 0					
	AFL	0			TSN 0					
PROC. REF: AMM 27-21-01										
272101-0201 RUDDER CONTROL CABLE ASSEMBLY Component ATA:27										
PN:PN	MOS/MSC		06-Jul-19	O/C	TSN 0					
SN:UNKNOWN	HRS	9057.4			TSN 0					
	AFL	4853			TSN 0					
PROC. REF: AMM 27-21-01										
272102-0101 RUDDER II -PIN ASSEMBLY Component ATA:27										
PN:PN	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0			TSN 0					
	AFL	0			TSN 0					
PROC. REF: AMM 27-20-02										
272103-0101 STRUCTURE ASSY ASSEMBLY Component ATA:27										
PN:PN	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS	0			TSN 0					
	AFL	0			TSN 0					
PROC. REF: GENERIC NO REF										
272200-0101 RUDDER SYS - POWER CONTROL UNIT ASSEMBLY Component ATA:27										
PN:360300-1001	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:1047	HRS	0			TSN 0					
	AFL	0			TSN 0					
PROC. REF: AMM 27-22-03										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
272200-0201 HYDRAULIC SYS, FIN RUDDER HYDROMECHANIC ACTUATOR ASSEMBLY Component ATA:27										
PN:360340-1005	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-22-02										
272200-0202 HYDRAULIC SYS, FIN RUDDER HYDROMECHANIC ACTUATOR ASSEMBLY Component ATA:27										
PN:360340-1005	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-22-02										
272200-0301 UPPER FORWARD TAIL HYDRAULIC SYS BLEED VALVE Component ATA:27										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-22-07										
272200-0302 UPPER AFT TAIL HYDRAULIC SYS BLEED VALVE Component ATA:27										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-22-07										
272200-0303 LOWER FORWARD TAIL HYDRAULIC SYS BLEED VALVE Component ATA:27										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-22-07										
272200-0304 LOWER AFT TAIL HYDRAULIC SYS BLEED VALVE Component ATA:27										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-22-07										
272200-0401 MID PAX DOOR SYS, THREE WAY/TWO POSITIONS, SOLENOID VALVE Component ATA:27										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-22-05										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
272200-0402 PAX DOOR SYS, THREE WAY/TWO POSITIONS, SOLENOID VALVE Component ATA:27										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-22-05										
272200-0403 PAX DOOR SYS, THREE WAY/TWO POSITIONS, SOLENOID VALVE Component ATA:27										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-22-05										
272300-0101 SERVO CONTROL, RUDDER PRESSURE SENSOR UNIT Component ATA:27										
PN:15H0048PH	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:0827	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-23-04										
272300-0102 SERVO CONTROL, RUDDER PRESSURE SENSOR UNIT Component ATA:27										
PN:15H0048PH	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:0825	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-23-04										
273100-0101 ELEVATOR CONTROL, FUSELAGE FWD, DISCONNECTION ASSY DEVICE Component ATA:27										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-35-00										
273100-0201 PILOT YOKE EQUIPPED CONTROLLER Component ATA:27										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-11-08										
273100-0202 COPILOT YOKE EQUIPPED CONTROLLER Component ATA:27										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-11-08										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
273100-0301 ROD ASSEMBLY										Component ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
273100-0302 ROD ASSEMBLY										Component ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
273100-0401 C FLOOR TUBE ASSY										Component ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
273100-0402 C FLOOR TUBE ASSY										Component ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
273101-0101 ELEVATOR CONTROL CABLE ASSEMBLY										Component ATA:27
PN:PN	MOS/MSC	06-Jul-19	O/C	TSN 0						
SN:UNKNOWN	HRS	9057.4		TSN 0						
	AFL	4853		TSN 0						
PROC. REF: AMM 27-31-01										
273102-0101 LEFT ELEVATOR -HORIZONTAL TAIL ASSEMBLY										Component ATA:27
PN:145-50845-423	MOS/MSC	13-May-14	O/C	TSN 0						
SN:0000809800	HRS	6988.9		TSN 0						
	AFL	3750		TSN 0						
PROC. REF: GENERIC NO REF										
273102-0102 RIGHT ELEVATOR -HORIZONTAL TAIL ASSEMBLY										Component ATA:27
PN:145-50845-416	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:0000133435	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
273103-0101 LEFT ELEVATOR CABLE TENSION REGULATOR Component ATA:27										
PN:0501020-03	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:1175	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-31-01										
273103-0102 RIGHT ELEVATOR CABLE TENSION REGULATOR Component ATA:27										
PN:0501020-01	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:1174	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-31-01										
273500-0101 CREW CAB MODULE -ELEVATOR DISCONNECTION,CENTRAL CONSOLE ASSEMBLY Component ATA:27										
PN:145-22175-401	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:0000137134	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-35-00										
273601-0101 LEFT ANGLE OF ATTACK SENSOR Component ATA:27										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-36-01										
273601-0102 RIGHT ANGLE OF ATTACK SENSOR Component ATA:27										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-36-01										
273602-0201 PILOT STICK SHAKER ACTUATOR Component ATA:27										
PN:0050N1	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:2901	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-36-03										
273602-0202 COPILOT STICK SHAKER ACTUATOR Component ATA:27										
PN:0050N1	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:2915	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-36-03										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
273603-0101 C FLOOR DATA PROCESSING-STALL PROTECTION CONTROL SYS COMPUTER Component ATA:27										
PN:0020BN7	MOS/MSC	10-Feb-10	O/C							
SN:1207	HRS	2977.3								
	AFL	1557								
PROC. REF: AMM 27-36-05										
273604-0101 FORWARD LINEAR ASSY-ELECTROMECHANICAL, STICK PUSHER ACTUATOR Component ATA:27										
PN:6235-1	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:1880	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-36-04										
273605-0101 CSL CENT MODULE -STALL PROTECTION/FMS ASSEMBLY Component ATA:27										
PN:145-34172-407	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:0000139918	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-36-05										
274000-0101 STABILIZER -HORIZONTAL EMPENAGE ASSEMBLY Component ATA:27										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-40-02										
274100-0101 ACTUATOR, ELECTROMECHANICAL -HORIZONTAL STABILIZER ASSEMBLY Component ATA:27										
PN:362200-1015	MOS/MSC	15-Aug-13	O/C							
SN:0614	HRS	6643.4								
	AFL	3572								
PROC. REF: AMM 27-40-02										
274302-0101 REAR CONTROL HORIZONTAL STABILIZER UNIT Component ATA:27										
PN:362100-1013	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:4742	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-40-01										
275000-0101 L/H WING FLAP I ASSY,LEFT,SEALING ASSEMBLY Component ATA:27										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
275000-0102 R/H WING FLAP I ASSY,RIGHT,SEALING ASSEMBLY Component ATA:27										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
275000-0103 L/H WING FLAP II ASSY,LEFT,SEALING ASSEMBLY Component ATA:27										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
275000-0104 R/H WING FLAP II ASSY,RIGHT,SEALING ASSEMBLY Component ATA:27										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
275100-0102 LH WING FLEXIBLE ASSY-SEGMENT 2, FLAP CONTROL SHAFT Component ATA:27										
PN:363400-1021	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:03194	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-51-05										
275100-0103 RH WING FLEXIBLE ASSY-SEGMENT 2, FLAP CONTROL SHAFT Component ATA:27										
PN:363400-1021	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-51-05										
275100-0106 INBOARD FLAP ASSY ASSEMBLY Component ATA:27										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-50-00										
275100-0107 INBOARD FLAP ASSY ASSEMBLY Component ATA:27										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-50-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
275100-0108 OUTBOARD FLAP ASSY ASSEMBLY										Component ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-50-00										
275100-0109 OUTBOARD FLAP ASSY ASSEMBLY										Component ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-50-00										
275100-0409 RH WING FLAP SCREWJACK ACTUATOR										Component ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-51-09, AMM 27-51-10										
275100-0410 RH WING FLAP SCREWJACK ACTUATOR										Component ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-51-09, AMM 27-51-10										
275100-0411 RH WING FLAP SCREWJACK ACTUATOR										Component ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-51-09, AMM 27-51-10										
275100-0412 RH WING FLAP SCREWJACK ACTUATOR										Component ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-51-09, AMM 27-51-10										
275100-0413 LH WING FLAP SCREWJACK ACTUATOR										Component ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-51-09, AMM 27-51-10										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
275100-0414 LH WING FLAP SCREWJACK ACTUATOR Component ATA:27										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-51-09, AMM 27-51-10										
275100-0415 LH WING FLAP SCREWJACK ACTUATOR Component ATA:27										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-51-09, AMM 27-51-10										
275100-0416 LH WING FLAP SCREWJACK ACTUATOR Component ATA:27										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-51-09, AMM 27-51-10										
275100-0503 LH WING BRAKE TRANSMISSION FLAP Component ATA:27										
PN:363500-1003	MOS/MSC	05-Aug-15	O/C							
SN:LA-628	HRS	7460.3		TSN 32934.97						
	AFL	3992		TSN 30844						
PROC. REF: AMM 27-51-01										
275100-0504 RH WING BRAKE TRANSMISSION FLAP Component ATA:27										
PN:363500-1003	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:03198	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-51-01										
275100-0701 LH WING FLAP FLEXIBLE 4 E 5 SHAFT Component ATA:27										
PN:363400-1025	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:05824	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-51-07, AMM 27-51-08										
275100-0702 RH WING FLAP FLEXIBLE 4 E 5 SHAFT Component ATA:27										
PN:363400-1025	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-51-07, AMM 27-51-08										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
275100-0703 LH WING FLAP FLEXIBLE 4 E 5 SHAFT										Component ATA:27
PN:363400-1025	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-51-07, AMM 27-51-08										
275100-0704 RH WING FLAP FLEXIBLE 4 E 5 SHAFT										Component ATA:27
PN:363400-1025	MOS/MSC	27-Jul-15	O/C							
SN:07353	HRS	7460.3								
	AFL	3992								
PROC. REF: AMM 27-51-07, AMM 27-51-08										
275100-0705 LH WING FLAP FLEXIBLE 3 SHAFT										Component ATA:27
PN:363400-1023	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:03199	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-51-06										
275100-0706 RH WING FLAP FLEXIBLE 3 SHAFT										Component ATA:27
PN:363400-1023	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-51-06										
275100-0801 LH WING ANGLE-ACTUATOR, INTERNAL CENTRAL FLAP ROOT, WING ADAPTER										Component ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
275100-0802 RH WING ANGLE-ACTUATOR, INTERNAL CENTRAL FLAP ROOT, WING ADAPTER										Component ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
275100-0803 LH WING ANGLE-ACTUATOR, EXTERNAL FLAP ROOT, WING ADAPTER										Component ATA:27
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
275100-0804 RH WING ANGLE-ACTUATOR, EXTERNAL FLAP ROOT, WING ADAPTER Component ATA:27										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
275100-0901 LH WING SENSOR -VELOCITY, FLAP ASSEMBLY Component ATA:27										
PN:363350-1003	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:05950	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-51-12										
275100-0902 RH WING SENSOR -VELOCITY, FLAP ASSEMBLY Component ATA:27										
PN:363350-1003	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:05915	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-51-12										
275100-1001 LH WING ASSY, FLAP CONTROL ACTUATOR Component ATA:27										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-51-09, AMM 27-51-10, AMM 27-51-09, AMM 27-51-10										
275100-1002 RH WING ASSY, FLAP CONTROL ACTUATOR Component ATA:27										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-51-09, AMM 27-51-10, AMM 27-51-09, AMM 27-51-10										
275100-1003 LH WING ASSY, FLAP CONTROL ACTUATOR Component ATA:27										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-51-09, AMM 27-51-10, AMM 27-51-09, AMM 27-51-10										
275100-1004 RH WING ASSY, FLAP CONTROL ACTUATOR Component ATA:27										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-51-09, AMM 27-51-10, AMM 27-51-09, AMM 27-51-10										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 27 - FLIGHT CONTROLS											
275100-1005		LH WING ASSY, FLAP CONTROL ACTUATOR							Component	ATA:27	
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 27-51-09, AMM 27-51-10, AMM 27-51-09, AMM 27-51-10											
275100-1006		RH WING ASSY, FLAP CONTROL ACTUATOR							Component	ATA:27	
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 27-51-09, AMM 27-51-10, AMM 27-51-09, AMM 27-51-10											
275100-1007		LH WING ASSY, FLAP CONTROL ACTUATOR							Component	ATA:27	
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 27-51-09, AMM 27-51-10, AMM 27-51-09, AMM 27-51-10											
275100-1008		RH WING ASSY, FLAP CONTROL ACTUATOR							Component	ATA:27	
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 27-51-09, AMM 27-51-10, AMM 27-51-09, AMM 27-51-10											
275100-1101		LH FLAP - INBOARD, WING HALF ASSEMBLY							Component	ATA:27	
PN:135-03288-403	MOS/MSC	19-Aug-15	O/C	TSN 96							
SN:0000137761	HRS	7460.3		TSN 7460.3							
	AFL	3992		TSN 3992							
PROC. REF: AMM 27-50-00											
275100-1102		RH FLAP - INBOARD, WING HALF ASSEMBLY							Component	ATA:27	
PN:135-03288-404	MOS/MSC	19-Aug-15	O/C	TSR 0							
SN:0000137750	HRS	7460.3		TSR 0							
	AFL	3992		TSR 0							
PROC. REF: AMM 27-50-00											
275100-1103		LH FLAP - OUTBOARD, WING HALF ASSEMBLY							Component	ATA:27	
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 27-50-00											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
275100-1104 RH FLAP - OUTBOARD, WING HALF ASSEMBLY Component ATA:27										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-50-00										
275300-0101 W STUB POWER-DRIVE, FLAP ACTUATOR UNIT Component ATA:27										
PN:363200-1003	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:01249	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-53-04										
275300-0201 LH WING FLAP FLEXIBLE 1 SHAFT Component ATA:27										
PN:363400-1019	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:03050	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-51-04										
275300-0202 RH WING FLAP FLEXIBLE 1 SHAFT Component ATA:27										
PN:363400-1019	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-51-04										
275302-0101 WING/FUSLG FAIRING, FLAP CONTROL UNIT Component ATA:27										
PN:363100-1011	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:5378	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-53-02										
275303-0101 FLAP SYS, CSL CENT, SELECTOR LEVER Component ATA:27										
PN:363110-1009	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:1142	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-53-03										
276000-0101 LH WING GROUND SPOILER PANEL ASSEMBLY Component ATA:27										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-62-05										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
276000-0102 RH WING GROUND SPOILER PANEL ASSEMBLY Component ATA:27										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-62-05										
276000-0201 LH WING SPEED BRAKE PANEL Component ATA:27										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-62-06										
276000-0202 RH WING SPEED BRAKE PANEL Component ATA:27										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-62-06										
276201-0101 LH WING GROUND SPOILER, HYDROMECHANICAL ACTUATOR ASSEMBLY Component ATA:27										
PN:360440-1011	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-62-01										
276201-0102 RH WING GROUND SPOILER, HYDROMECHANICAL ACTUATOR ASSEMBLY Component ATA:27										
PN:360440-1011	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-62-01										
276201-0201 W STUB ELECTROVALVE-SPOILER, HYDRAULIC SYSTEM Component ATA:27										
PN:360450-1001	MOS/MSC	01-Sep-17	O/C							
SN:1136	HRS	8284.1								
	AFL	4446								
PROC. REF: AMM 27-62-03										
276201-0301 W STUB RESTRICTOR, HYDRAULIC SYS, SSTEEL VALVE Component ATA:27										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-22-06										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
276203-0101 LH WING HYDROMECHANICAL SPEED BRAKE ACTUATOR Component ATA:27										
PN:360540-1011	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-62-02										
276203-0102 RH WING HYDROMECHANICAL SPEED BRAKE ACTUATOR Component ATA:27										
PN:360540-1011	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-62-02										
276203-0201 W STUB BRAKE AERODYNAMIC VALVE Component ATA:27										
PN:360550-1003	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:1088	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
276207-0101 MID PRESSURE REDUCER, HYDRAULIC SYS, WING STUB VALVE Component ATA:27										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-62-07										
276301-0101 LH WING SPOILER INBOARD PROXIMITY SWITCH Component ATA:27										
PN:80-057-01	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-63-04										
276301-0102 RH WING SPOILER INBOARD PROXIMITY SWITCH Component ATA:27										
PN:8-527-01	MOS/MSC	09-Feb-11	O/C	TSN 0						
SN:18077	HRS	4234		TSN 0						
	AFL	2237		TSN 0						
PROC. REF: AMM 27-63-04										
276301-0103 LH WING SPOILER OUTBOARD PROXIMITY SWITCH Component ATA:27										
PN:80-057-01	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-63-04										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
276301-0104 RH WING SPOILER OUTBOARD PROXIMITY SWITCH Component ATA:27										
PN:80-057-01	MOS/MSC	26-Dec-10	O/C							
SN:26368	HRS	4048.8								
	AFL	2138								
PROC. REF: AMM 27-63-04										
276301-0105 LH WING SPOILER CENTER PROXIMITY SWITCH Component ATA:27										
PN:80-057-01	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-63-04										
276302-0101 SPEED BRAKE CONTROL, CENTRAL CONSOLE, LEVER ASSEMBLY Component ATA:27										
PN:999-1003	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:1086	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-63-03										
276303-0101 CSL CENT SPOILER CONTROL, EQUIPPED UNIT Component ATA:27										
PN:145-33022-411	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:124793	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-63-02										
277100-0101 ELECTROMECHANICAL,CONTROLS LOCKING ACTUATOR ASSEMBLY Component ATA:27										
PN:SYLC-53058	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:070316	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-71-01										
277100-0201 LEFT CARTRIDGE ASSY-GUST LOCK SYS SPRING Component ATA:27										
PN:KPD4235	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:KC2261	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-71-03										
277100-0202 RIGHT CARTRIDGE ASSY-GUST LOCK SYS SPRING Component ATA:27										
PN:KPD4235	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:KC2227	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-71-03										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
28-10-00-220-001-A00	INSPECT (DETAILED INSPECTION) OF FUEL TANKS (WINGS AND WING STUB) FOR PRESENCE OF MICROORGANISM (L600 ONLY) NOTE 1: IF MODERATE OR HEAVY CONTAMINATION IS FOUND, FWD AND AFT FUEL TANKS MUST BE INSPECTED. NOTE 2: IF ENGINE FUEL FILTER ELEMENT HAS BEEN REPLACED THE TASK 73-1100-960-001-A00 MUST BE SIGNED OFF NOTE 3: EMB-RECOMMENDED								Service	ATA:28
	MOS	18-Jul-24	12 (+15d/-15d)	Adj -4d	14-Jul-25	29-Jul-25	241 d (+15)			
	HRS	10519.2								
	AFL	5604								
PROC. REF: AMM 28-11-00										
28-10-00-220-001-A01	INSPECT (DETAILED INSPECTION) OF FUEL TANKS (WINGS, WING STUB AND VENTRAL) FOR PRESENCE OF MICROORGANISM (L650 ONLY) NOTE 1: IF MODERATE OR HEAVY CONTAMINATION IS FOUND, FWD AND AFT FUEL TANKS MUST BE INSPECTED. NOTE 2: IF ENGINE FUEL FILTER ELEMENT HAS BEEN REPLACED, THE TASK 73-11-00-960-001-A00 MUST BE SIGNED OFF NOTE 3: EMB-RECOMMENDED								Service	ATA:28
	MOS/MSC	27-Aug-07	N/A							
	HRS	0								
	AFL	0								
PROC. REF: AMM 28-11-00										
28-11-00-280-001-A00	INSPECT (SPECIAL INSPECTION) FOR PRESENCE OF MICRO ORGANISMS IN THE FUEL TANKS. NOTE: THIS TASK IS NOT APPLICABLE IF THE OPERATOR DECIDES TO COMPLY WITH TASK 28-11-00-280-001-A01. NOTE: EMB-RECOMMENDED								Service	ATA:28
	MOS	16-Aug-24	6 (+15d/-15d)		16-Feb-25	03-Mar-25	93 d (+15)			
	HRS	10541.4								
	AFL	5613								
PROC. REF: AMM 28-11-00										
28-11-00-280-001-A01	INSPECT (SPECIAL INSPECTION) FOR PRESENCE OF MICRO ORGANISMS IN THE FUEL TANKS NOTE1: THIS TASK IS NOT APPLICABLE IF THE OPERATOR DECIDES TO COMPLY WITH TASK 28-11-00-280-001-A00								Service	ATA:28
	MOS	18-Jul-24	12 (+15d/-15d)	Adj -4d	14-Jul-25	29-Jul-25	241 d (+15)			
	HRS	10519.2								
	AFL	5604								
PROC. REF: AMM 28-11-00										
28-11-00-720-001-A00 ^S	FUNCTIONALLY CHECK CRITICAL BONDING INTEGRITY OF SELECTED CONDUITS INSIDE THE WING TANK, FUEL PUMP AND FQIS CONNECTORS AT TANK WALL BY CONDUCTIVITY MEASUREMENTS. (L600 ONLY)								Service	ATA:28
	MOS	27-Aug-07	288 (+15d/-15d)					LOW UTILIZATION		
	HRS	0	12000 (+20/-20)							
	AFL	0	6000 (+20/-20)							
PROC. REF: AMM 28-11-00										PKG:5140

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 28 - FUEL											
28-11-00-720-002-A01			FUNCTIONALLY CHECK CRITICAL BONDING INTEGRITY OF SELECTED CONDUITS INSIDE THE WING TANK, FUEL PUMP CONNECTORS AT TANK WALL BY CONDUCTIVITY MEASUREMENTS. NOTE: APPLICABLE TO FUEL PUMPS WITH TANK WALL HERMETIC CONNECTOR (L650 ONLY)						Service	ATA:28	
	MOS/MSC	27-Aug-07	N/A								
	HRS	0									
	AFL	0									
PROC. REF: AMM 28-11-00											
28-11-00-720-003-A01			FUNCTIONALLY CHECK CRITICAL BONDING INTEGRITY OF SELECTED CONDUITS INSIDE THE WING TANK, FOIS CONNECTORS AT TANK WALL BY CONDUCTIVITY MEASUREMENTS (L650 ONLY)						Service	ATA:28	
	MOS/MSC	27-Aug-07	N/A								
	HRS	0									
	AFL	0									
PROC. REF: AMM 28-11-00											
28-11-04-710-001-A00 ^S			OPERATIONALLY CHECK FLAP VALVES (RIBS 1 AND 7) (MANUAL CHECK FOR FREE MOVEMENT AND SEALING CONDITION) NOTE: CHECK DURING INTERNAL TANK INSPECTION.						Service	ATA:28	
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	4000 (+20/-20)								
	AFL	5401	2000 (+20/-20)								
PROC. REF: AMM 28-11-04											
PKG:5016,6032											
28-12-01-710-001-A00 ^S			OPERATIONAL CHECK VENT FLOAT VALVES (MANUAL CHECK) (NOTE: CHECK DURING INTERNAL TANK INSPECTION).						Service	ATA:28	
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	4000 (+20/-20)								
	AFL	5401	2000 (+20/-20)								
PROC. REF: AMM 28-12-01											
PKG:5016,6032											
28-12-04-710-001-A00 ^S			OPERATIONALLY CHECK FLAP VALVES (MANUAL CHECK FOR FREE MOVEMENT AND SEALING CONDITION). NOTE: CHECK DURING INTERNAL TANK INSPECTION.						Service	ATA:28	
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	4000 (+20/-20)								
	AFL	5401	2000 (+20/-20)								
PROC. REF: AMM 28-12-04											
PKG:5016,6032											
28-12-05-211-001-A00 ^S			VISUALLY CHECK FLAME ARRESTOR FOR HONEY COMB CLOGGING, AND ATTACHING PARTS FOR SECURITY.						Service	ATA:28	
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	2000 (+20/-20)								
	AFL	5401	1000 (+20/-20)								
PROC. REF: AMM 28-12-05											
PKG:5008,6016											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
28-12-05-710-001-A00 ^S	OPERATIONAL CHECK FLAME ARRESTOR IN/OUT FLOW VALVES FOR FREEDOM MOVEMENT.								Service	ATA:28
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: AMM 28-12-05					PKG:5008,6016
28-13-00-220-001-A00 ^S	INSPECT (DETAILED INSPECTION) OF AFT FUEL TANKS								Service	ATA:28
	MOS	29-Jun-23	24 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	1000 (+20/-20)							
	AFL	5401								
					PROC. REF: AMM 28-13-02					PKG:5007,6008
28-13-01-720-001-A00 ^S	FUNCTIONALLY CHECK AFT FUEL TANKS								Service	ATA:28
	MOS	29-Jun-23	24 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	1000 (+20/-20)							
	AFL	5401								
					PROC. REF: AMM 28-13-01					PKG:5007
28-13-01-720-002-A00 ^S	FUNCTIONALLY CHECK AFT FUEL TANK CRITICAL BONDING INTEGRITY OF FUEL PUMP, FQGS AND LOW LEVEL SW CONNECTORS AT TANK WALL BY CONDUCTIVITY MEASUREMENTS.(L600 ONLY)								Service	ATA:28
	MOS	27-Aug-07	288 (+15d/-15d)					LOW UTILIZATION		
	HRS	0	12000 (+20/-20)							
	AFL	0	6000 (+20/-20)							
					PROC. REF: AMM 28-13-01					PKG:5140
28-13-01-720-003-A01	FUNCTIONALLY CHECK AFT FUEL TANK CRITICAL BONDING INTEGRITY OF FUEL PUMP CONNECTORS AT TANK WALL BY CONDUCTIVITY MEASUREMENTS(NOTE: APPLICABLE TO FUEL PUMPS WITH TANK WALL HERMETIC CONNECTOR) (L650 ONLY)								Service	ATA:28
	MOS/MSC	27-Aug-07	N/A							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 28-13-01					
28-13-01-720-004-A01	FUNCTIONALLY CHECK AFT FUEL TANK CRITICAL BONDING INTEGRITY OF FQGS CONNECTORS AT TANK WALL BY CONDUCTIVITY MEASUREMENTS(L650 ONLY)								Service	ATA:28
	MOS/MSC	27-Aug-07	N/A							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 28-13-01					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
28-14-00-710-001-A00 ^S	OPERATIONALLY CHECK AFT FUEL TANK POSITIVE RELIEF SYSTEM									Service ATA:28
	MOS	16-Aug-24	12 (+15d/-15d)					LOW UTILIZATION		
	HRS	10541.4	500 (+20/-20)							
	AFL	5613								
					PROC. REF: AMM 28-14-00					PKG:5002
28-14-01-710-001-A00 ^S	OPERATIONAL CHECK AFT FUEL TANK FLOAT VENT VALVES PRE-MOD SB 145LEG-28-0019.(L600 ONLY)									Service ATA:28
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
					PROC. REF: AMM 28-14-10					PKG:5016,6032
28-14-04-720-001-A00 ^S	FUNCTIONALLY CHECK AFT FUEL TANKS POSITIVE RELIEF VALVE									Service ATA:28
	MOS	29-Jun-23	24 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	1000 (+20/-20)							
	AFL	5401								
					PROC. REF: AMM 28-14-13					PKG:5004
28-14-05-720-001-A00 ^S	FUNCTIONALLY CHECK AFT FUEL TANKS NEGATIVE RELIEF VALVE									Service ATA:28
	MOS	29-Jun-23	24 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	1000 (+20/-20)							
	AFL	5401								
					PROC. REF: AMM 28-14-14					PKG:5004
28-14-06-960-001-A00 ^S	DISCARD AFT-FUEL-TANK AIR FILTER									Service ATA:28
	MOS	16-Aug-24	12 (+15d/-15d)					LOW UTILIZATION		
	HRS	10541.4	500 (+20/-20)							
	AFL	5613								
					PROC. REF: AMM 28-14-15					PKG:5002
28-14-07-220-001-A00 ^S	INSPECT (DETAILED INSPECTION) OF AFT FUEL TANKS FLAME ARRESTORS. NOTE: FLAME ARRESTORS INSTALLED IN THE SKIN OF THE FUSELAGE AND FLAME ARRESTORS INSTALLED CLOSE TO CONTAINER BOX, IF INSTALLED.									Service ATA:28
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: AMM 28-14-09					PKG:5008,6016
28-14-08-710-001-A00	OPERATIONALLY CHECK 3/4 ZERO LEAKAGE CHECK VALVES. NOTE: CMR/ANAC-FAA-EASA. (CMR)									Service ATA:28
	MOS	14-Jul-22	48 (+15d/-15d)		14-Jul-26	29-Jul-26	606 d (+15)	LOW UTILIZATION		
	HRS	9915.8	1000		10915.8		320.2			
	AFL	5271								
					PROC. REF: AMM 28-14-17					PKG:6003

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
28-14-09-710-001-A00 ^S	OPERATIONALLY CHECK 3/8 ZERO LEAKAGE CHECK VALVES. (CMR)									Service ATA:28
	MOS	16-Aug-24	12 (+15d/-15d)					LOW UTILIZATION		
	HRS	10541.4	500 (+20/-20)							
	AFL	5613								
PROC. REF: AMM 28-14-17										PKG:5002
28-14-10-710-001-A00 ^S	OPERATIONALLY CHECK AFT FUEL TANKS PRESSURIZATION VENT PLUMBING SHROUD (CMR)									Service ATA:28
	MOS	29-Jun-23	24 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	1000 (+20/-20)							
	AFL	5401								
PROC. REF: AMM 28-13-01, AMM 28-13-01										PKG:5004
28-15-03-710-001-A00 ^S	OPERATIONALLY CHECK FORWARD FUEL TANKS FLAP VALVES									Service ATA:28
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
PROC. REF: AMM 28-15-03										PKG:5016,6032
28-15-04-720-001-A00 ^S	FUNCTIONALLY CHECK FWD FUEL TANK CRITICAL BONDING INTEGRITY OF FUEL PUMP, FQGS AND LOW LEVEL SW CONNECTORS AT TANK WALL BY CONDUCTIVITY MEASUREMENTS.(L600 ONLY)									Service ATA:28
	MOS	27-Aug-07	288 (+15d/-15d)					LOW UTILIZATION		
	HRS	0	12000 (+20/-20)							
	AFL	0	6000 (+20/-20)							
PROC. REF: AMM 28-15-04										PKG:5140
28-15-04-720-002-A01	FUNCTIONALLY CHECK FWD FUEL TANK CRITICAL BONDING INTEGRITY OF FUEL PUMPCONNECTORS AT TANK WALL BY CONDUCTIVITY MEASUREMENTS(NOTE: APPLICABLE TO FUEL PUMPS WITH TANK WALL HERMETIC CONNECTOR)(L650 ONLY)									Service ATA:28
	MOS/MSC	27-Aug-07	N/A							
	HRS	0								
	AFL	0								
PROC. REF: AMM 28-15-04										
28-15-04-720-003-A01	FUNCTIONALLY CHECK FWD FUEL TANK CRITICAL BONDING INTEGRITY OF FQGS CONNECTORS AT TANK WALL BY CONDUCTIVITY MEASUREMENTS(L650 ONLY)									Service ATA:28
	MOS/MSC	27-Aug-07	N/A							
	HRS	0								
	AFL	0								
PROC. REF: AMM 28-15-04										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
28-16-00-710-001-A00 ^S	OPERATIONALLY CHECK FUEL TANKS VENT OPEN CAUTION SYSTEM.									Service ATA:28
	MOS	16-Aug-24	12 (+15d/-15d)					LOW UTILIZATION		
	HRS	10541.4	500 (+20/-20)							
	AFL	5613								
	PROC. REF: AMM 28-16-00									PKG:5002
28-16-01-710-001-A00 ^S	OPERATIONALLY CHECK FORWARD FUEL TANKS FLOAT VALVES (MANUALLY CHECKED).									Service ATA:28
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
	PROC. REF: AMM 28-16-01									PKG:5016,6032
28-16-04-710-001-A00 ^S	OPERATIONALLY CHECK FORWARD FUEL TANKS AUTOMATIC FLOAT DRAIN VALVES.									Service ATA:28
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
	PROC. REF: AMM 28-16-04									PKG:5016,6032
28-16-05-220-001-A00 ^S	INSPECT (DETAILED INSPECTION) OF FORWARD FUEL TANK FLAME ARRESTORS.NOTE: FLAME ARRESTORS INSTALLED ON NACA AIR DUCT AND FLAME ARRESTORS INSTALLED ON REFUEL/OVERFILL VENTILATION LINE, IF INSTALLED.									Service ATA:28
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
	PROC. REF: AMM 28-16-05									PKG:5008,6016
28-17-01-720-002-A01	FUNCTIONALLY CHECK VENTRAL TANK CRITICAL BONDING INTEGRITY OF FUEL PUMP CONNECTORS AT TANK WALL BY CONDUCTIVITY MEASUREMENTS NOTE: APPLICABLE TO FUEL PUMPS WITH TANK WALL HERMETIC CONNECTOR (L650 ONLY)									Service ATA:28
	MOS/MSC	27-Aug-07	N/A							
	HRS	0								
	AFL	0								
	PROC. REF: AMM 28-17-01									
28-17-01-720-003-A01	FUNCTIONALLY CHECK VENTRAL TANK CRITICAL BONDING INTEGRITY OF FOGS CONNECTORS AT TANK WALL BY CONDUCTIVITY MEASUREMENTS (L650 ONLY)									Service ATA:28
	MOS/MSC	27-Aug-07	N/A							
	HRS	0								
	AFL	0								
	PROC. REF: AMM 28-17-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
28-17-03-710-001-A00	OPERATIONALLY CHECK VENTRAL FUEL TANK FLAP VALVES (L650 ONLY)									Service ATA:28
	MOS/MSC	27-Aug-07	N/A							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 28-17-05					PKG:6032
28-17-04-710-001-A00	OPERATIONALLY CHECK VENTRAL FUEL TANK BAFFLE VALVES (L650 ONLY)									Service ATA:28
	MOS/MSC	27-Aug-07	N/A							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 28-17-05					PKG:6032
28-18-01-710-001-A00	OPERATIONALLY CHECK VENTRAL FUEL TANK FLOAT VENT VALVES (L650 ONLY)									Service ATA:28
	MOS/MSC	27-Aug-07	N/A							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 28-18-01					PKG:6032
28-18-03-710-001-A00	OPERATIONALLY CHECK VENTRAL FUEL TANK FLOAT ACTUATED DRAIN VALVE (L650 ONLY)									Service ATA:28
	MOS/MSC	27-Aug-07	N/A							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 28-18-04					PKG:6032
28-21-01-220-001-A00 ^S	INSPECT (DETAILED INSPECTION) WING ELECTRIC FUEL PUMP CONNECTOR									Service ATA:28
	MOS	10-Jul-15	192 (+15d/-15d)					LOW UTILIZATION		
	HRS	7460.3	8000 (+20/-20)							
	AFL	3992	4000 (+20/-20)							
					PROC. REF: AMM 28-21-01					PKG:5032,6032
28-21-03-720-001-A00 ^S	FUNCTIONALLY CHECK RELIEF VALVE NOTE: BENCH TEST									Service ATA:28
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
					PROC. REF: AMM 28-21-03					PKG:5016,6032
28-21-04-710-001-A00 ^S	OPERATIONALLY CHECK FUEL CROSSFEED VALVE									Service ATA:28
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: AMM 28-21-04					PKG:5008,6016

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
28-21-10-710-001-A00 ^S	OPERATIONALLY CHECK FUEL FEED LINE SHROUD									Service ATA:28
	MOS	06-Jul-19	72 (+15d/-15d)					LOW UTILIZATION		
	HRS	9057.4	3000 (+20/-20)							
	AFL	4853	1500 (+20/-20)							
	PROC. REF: AMM 28-21-10									PKG:5012,6020
28-22-03-710-001-A00 ^S	OPERATIONALLY CHECK APU FUEL FEED LINE SHROUD									Service ATA:28
	MOS	06-Jul-19	72 (+15d/-15d)					LOW UTILIZATION		
	HRS	9057.4	3000 (+20/-20)							
	AFL	4853	1500 (+20/-20)							
	PROC. REF: AMM 28-22-03									PKG:5012,6020
28-23-03-220-001-A00 ^S	INSPECT (DETAILED INSPECTION) PILOT VALVE HARNESS INSIDE THE CONDUIT.(L600 ONLY)									Service ATA:28
	MOS	27-Aug-07	288 (+15d/-15d)					LOW UTILIZATION		
	HRS	0	12000 (+20/-20)							
	AFL	0	6000 (+20/-20)							
	PROC. REF: AMM 28-23-03									PKG:5140
28-23-04-220-001-A00 ^S	INSPECT (DETAILED INSPECTION) VENT VALVE HARNESS INSIDE THE CONDUIT (L600 ONLY)									Service ATA:28
	MOS	27-Aug-07	288 (+15d/-15d)					LOW UTILIZATION		
	HRS	0	12000 (+20/-20)							
	AFL	0	6000 (+20/-20)							
	PROC. REF: AMM 28-23-04									PKG:5140
28-23-04-220-001-A01	INSPECT (DETAILED INSPECTION) VENT VALVE HARNESS INSIDE THE CONDUIT (L650 ONLY)									Service ATA:28
	MOS/MS	27-Aug-07	N/A							
	HRS	0								
	AFL	0								
	PROC. REF: AMM 28-23-04									PKG:6032
28-26-00-710-001-A00 ^S	OPERATIONALLY CHECK OF FWD PUMP AND CIRCUITRY									Service ATA:28
	MOS	29-Jun-23	24 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	1000 (+20/-20)							
	AFL	5401								
	PROC. REF: AMM 28-26-00									PKG:5004
28-26-00-720-001-A00 ^S	FUNCTIONALLY CHECK AFT/FWD TRANSFER FUEL TANKS TRANSFER CHECK RELIEF VALVES									Service ATA:28
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
	PROC. REF: AMM 28-26-00									PKG:5016,6032

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
28-26-16-710-001-A00 ^S	OPERATIONALLY CHECK FUEL TRANSFER LINE SHROUD.									Service ATA:28
	MOS	06-Jul-19	72 (+15d/-15d)					LOW UTILIZATION		
	HRS	9057.4	3000 (+20/-20)							
	AFL	4853	1500 (+20/-20)							
	PROC. REF: AMM 28-13-01									PKG:5012,6020
28-26-18-710-001-A00 ^S	OPERATIONALLY CHECK AFT TANK ELECTRICAL ISOLATING SHUT-OFF VALVE AND CIRCUITRY									Service ATA:28
	MOS	16-Aug-24	12 (+15d/-15d)					LOW UTILIZATION		
	HRS	10541.4	500 (+20/-20)							
	AFL	5613								
	PROC. REF: AMM 28-26-18									PKG:5002
28-26-21-710-001-A00 ^S	OPERATIONALLY CHECK FORWARD TANKS LOW LEVEL SWITCH (L600 ONLY)									Service ATA:28
	MOS	29-Jun-23	24 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	1000 (+20/-20)							
	AFL	5401								
	PROC. REF: AMM 28-26-21									PKG:5004
28-26-21-710-001-A01	OPERATIONALLY CHECK FORWARD TANKS LOW LEVEL SENSOR (L650 ONLY)									Service ATA:28
	MOS/MSC	25-Sep-07	N/A					SYSTEM		
	HRS	0								
	AFL	0								
	PROC. REF: AMM 28-26-21									
28-26-22-710-001-A00 ^S	OPERATIONALLY CHECK AFT TANKS LOW LEVEL SWITCH (L600 ONLY)									Service ATA:28
	MOS	29-Jun-23	24 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	1000 (+20/-20)							
	AFL	5401								
	PROC. REF: AMM 28-26-22									PKG:5004
28-26-22-710-001-A01	OPERATIONALLY CHECK AFT TANKS LOW LEVEL SENSOR (L650 ONLY)									Service ATA:28
	MOS/MSC	25-Sep-07	N/A					SYSTEM		
	HRS	0								
	AFL	0								
	PROC. REF: AMM 28-26-22									
28-26-24-710-001-A00 ^S	OPERATIONALLY CHECK AFT TANKS TRANSFER CHECK VALVE									Service ATA:28
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
	PROC. REF: AMM 28-26-23									PKG:5016,6032

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
28-41-00-220-001-A01	INSPECT (DETAILED INSPECTION) W1642 INTRINSICALLY SAFE HARNESSSES FOR SLEEVE INTEGRITY(L650 ONLY)									Service ATA:28
	MOS/MSC	27-Aug-07	N/A							
	HRS	0								
	AFL	0								
PROC. REF: AMM 28-41-00										PKG:6016
28-41-00-710-001-A00 ^S	OPERATIONALLY CHECK ELECTRICAL FUEL QUANTITY INDICATING SYSTEM (FUEL LOW LEVEL LOGIC) (L600 ONLY)									Service ATA:28
	MOS	29-Jun-23	48 (+15d/-15d)	LOW UTILIZATION						
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
PROC. REF: AMM 28-41-00										PKG:5008,6016
28-41-01-720-001-A01 ^S	FUNCTIONALLY CHECK THE SAFE LIFE FEATURES OF THE FUEL CONDITIONING UNIT (FCU). - INITIAL FUNCTIONAL CHECK, - EXTERNAL VISUAL INSPECTION, - INTERNAL VISUAL INSPECTION, -FUNCTIONAL CHECK OF THE SAFE LIFE FEATURE, - FINAL FUNCTIONAL CHECK. (L600 ONLY)									Service ATA:28
	MOS	06-Jul-15	192 (+15d/-15d)	LOW UTILIZATION						
	HRS	7460.3	8000 (+20/-20)							
	AFL	3992	4000 (+20/-20)							
PROC. REF: AMM 28-41-01										PKG:5032,6032
28-41-03-220-001-A00 ^S	INSPECT (DETAILED INSPECTION) FQIS HARNESS FOR CLAMP AND WIRE JACKET INTEGRITY (L600 ONLY)									Service ATA:28
	MOS	27-Aug-07	288 (+15d/-15d)	LOW UTILIZATION						
	HRS	0	12000 (+20/-20)							
	AFL	0	6000 (+20/-20)							
PROC. REF: AMM 28-41-03										PKG:5140
28-41-03-220-001-A01	INSPECT (DETAILED INSPECTION) FQIS HARNESS FOR CLAMP AND WIRE JACKET INTEGRITY. (L650 ONLY)									Service ATA:28
	MOS/MSC	27-Aug-07	N/A							
	HRS	0								
	AFL	0								
PROC. REF: AMM 28-41-03										PKG:6032
28-41-07-220-001-A01	INSPECT (DETAILED INSPECTION) VENTRAL TANK INTERNAL INSPECTION: FQGS HARNESS FOR CLAMP AND WIRE JACKET INTEGRITY. (L650 ONLY)									Service ATA:28
	MOS/MSC	27-Aug-07	N/A							
	HRS	0								
	AFL	0								
PROC. REF: AMM 28-41-06										PKG:6032

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
28-43-00-720-001-A00 ^S	FUNCTIONALLY CHECK FUEL TEMPERATURE INDICATION SYSTEM									Service ATA:28
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
	PROC. REF: AMM 28-43-00									PKG:5016,6032
28-44-00-720-001-A00 ^S	FUNCTIONALLY CHECK FUEL LOW LEVEL WARNING SYSTEM NOTE: CHECK DURING INTERNAL TANK INSPECTION									Service ATA:28
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
	PROC. REF: AMM 28-44-00									PKG:5016,6032
28-45-00-710-001-A00 ^S	OPERATIONALLY CHECK FUEL LOW PRESSURE WARNING SYSTEM									Service ATA:28
	MOS	29-Jun-23	24 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	1000 (+20/-20)							
	AFL	5401								
	PROC. REF: AMM 28-45-00									PKG:5004
28-46-00-710-001-A00 ^S	OPERATIONAL CHECK "FUSELAGE FUEL IMB" WARNING SYSTEM (L600 ONLY)									Service ATA:28
	MOS	16-Aug-24	12 (+15d/-15d)					LOW UTILIZATION		
	HRS	10541.4	500 (+20/-20)							
	AFL	5613								
	PROC. REF: AMM 28-46-00									PKG:5002
28-46-00-710-001-A01	OPERATIONALLY CHECK "FUSELAGE FUEL IMB" AND "FUEL XFER CRITICAL" CAUTION SYSTEM (L650 ONLY)									Service ATA:28
	MOS/MS	25-Sep-07	N/A					SYSTEM		
	HRS	0								
	AFL	0								
	PROC. REF: AMM 28-46-00									
28-46-00-720-001-A00 ^S	FUNCTIONALLY CHECK "CHECK ACFT LOAD OR FUEL XFER CRITICAL" WARNING SYSTEM (L600 ONLY)									Service ATA:28
	MOS	29-Jun-23	24 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	1000 (+20/-20)							
	AFL	5401								
	PROC. REF: AMM 28-46-00									PKG:5004
28-46-00-720-002-A00 ^S	FUNCTIONALLY CHECK OF AUXILIARY TANKS PROBES AND FCU									Service ATA:28
	MOS	29-Jun-23	24 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	1000 (+20/-20)							
	AFL	5401								
	PROC. REF: AMM 28-46-00									PKG:5004

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
28-46-02-220-001-A00 ^S	INSPECT (DETAILED INSPECTION) AFT FUEL TANK INTERNAL INSPECTION: FQGS HARNESS AND LOW LEVEL SW HARNESS FOR CLAMP AND WIRE JACKET INTEGRITY.(L600 ONLY)								Service	ATA:28
MOS	27-Aug-07	288 (+15d/-15d)	LOW UTILIZATION							
HRS	0	12000 (+20/-20)								
AFL	0	6000 (+20/-20)								
PROC. REF: AMM 28-46-02										PKG:5140
28-46-02-220-001-A01	INSPECT (DETAILED INSPECTION) AFT FUEL TANK: FQGS HARNESS FOR CLAMP AND WIRE JACKET INTEGRITY.(L650 ONLY)								Service	ATA:28
MOS/MSC	27-Aug-07	N/A								
HRS	0									
AFL	0									
PROC. REF: AMM 28-46-02										PKG:6032
28-46-04-220-001-A00 ^S	INSPECT (DETAILED INSPECTION) FWD FUEL TANK INTERNAL INSPECTION: FQGS HARNESS AND LOW LEVEL SW HARNESS FOR CLAMP AND WIRE JACKET INTEGRITY.(L600 ONLY)								Service	ATA:28
MOS	27-Aug-07	288 (+15d/-15d)	LOW UTILIZATION							
HRS	0	12000 (+20/-20)								
AFL	0	6000 (+20/-20)								
PROC. REF: AMM 28-46-04										PKG:5140
28-46-04-220-001-A01	INSPECT (DETAILED INSPECTION) FWD FUEL TANK INTERNAL INSPECTION: FQGS HARNESS FOR CLAMP AND WIRE JACKET INTEGRITY.(L650 ONLY)								Service	ATA:28
MOS/MSC	27-Aug-07	N/A								
HRS	0									
AFL	0									
PROC. REF: AMM 28-46-04										PKG:6032
28-46-05-720-001-A01 ^S	FUNCTIONALLY CHECK THE SAFE LIFE FEATURES OF THE AUXILIARY FUEL CONDITIONING UNIT (AFCU). - INITIAL FUNCTIONAL CHECK, - EXTERNAL VISUAL INSPECTION, - INTERNAL VISUAL INSPECTION, -FUNCTIONAL CHECK OF THE SAFE LIFE FEATURE, - FINAL FUNCTIONAL CHECK (L600 ONLY)								Service	ATA:28
MOS	06-Jul-15	192 (+15d/-15d)	LOW UTILIZATION							
HRS	7460.3	8000 (+20/-20)								
AFL	3992	4000 (+20/-20)								
PROC. REF: AMM 28-46-05										PKG:5032,6032
28-50-01-220-001-A00 ^S	INSPECT (DETAILED INSPECTION) FUEL PUMP ELECTRICAL HARNESS NOTE: THIS TASK COMPLIES WITH FUEL TANK IGNITION SOURCES PREVENTION (SFAR-88)(L600 ONLY)								Service	ATA:28
MOS	31-Jul-15	192 (+15d/-15d)	LOW UTILIZATION							
HRS	7460.3	8000 (+20/-20)								
AFL	3992	4000 (+20/-20)								
PROC. REF: AMM 28-21-01, AMM 28-26-08										PKG:5032,6032

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
28-50-01-220-001-A01	DETAILED INSPECTION FUEL PUMP ELECTRICAL HARNESS AND CONNECTORS NOTE: APPLICABLE TO FUEL PUMPS WITH TANK WALL HERMETIC CONNECTOR (L650 ONLY)									Service ATA:28
	MOS/MSC	27-Aug-07	N/A							
	HRS	0								
	AFL	0								
PROC. REF: AMM 28-21-01, AMM 28-26-08, AMM 28-26-01										PKG:6016
28-50-01-220-001-A02	INSPECT (DETAILED INSPECTION) FUEL PUMP ELECTRICAL HARNESS CHA (CABLE HARNESS ASSEMBLY) END FITTING (L650 ONLY)									Service ATA:28
	MOS/MSC	27-Aug-07	N/A							
	HRS	0								
	AFL	0								
PROC. REF: AMM 28-21-01										PKG:6016
28-50-01-720-001-A00	FUNCTIONALLY CHECK FUEL PUMP ELECTRICAL HARNESS FOR LEAKAGE NOTE: APPLICABLE TO AIRCRAFT WITH FUEL PUMP HARNESSWITH CORRUGATED CONDUIT.ZONE: 155/156 157/197 271/272 1972 (L650 ONLY)									Service ATA:28
	MOS/MSC	27-Aug-07	N/A							
	HRS	0								
	AFL	0								
PROC. REF: AMM 28-21-01										PKG:6032
28-50-02-220-001-A00 ^S	INSPECT (DETAILED INSPECTION) WING FUEL TANK UNIT NOTE: THIS TASK COMPLIES WITH FUEL TANK IGNITION SOURCES PREVENTION (SFAR-88).(L600 ONLY)									Service ATA:28
	MOS	10-Jul-15	192 (+15d/-15d)					LOW UTILIZATION		
	HRS	7460.3	8000 (+20/-20)							
	AFL	3992	4000 (+20/-20)							
PROC. REF: AMM 28-41-02										PKG:5032,6032
28-50-02-220-001-A01	INSPECT (DETAILED INSPECTION) WING FUEL TANK UNITS (L650 ONLY)									Service ATA:28
	MOS/MSC	27-Aug-07	N/A							
	HRS	0								
	AFL	0								
PROC. REF: AMM 28-41-02										PKG:6016
28-50-03-220-002-A00 ^S	INSPECT (DETAILED INSPECTION) FWD FUEL TANK UNIT NOTE: THIS TASK COMPLIES WITH FUEL TANK IGNITION SOURCES PREVENTION (SFAR-88) (L600 ONLY)									Service ATA:28
	MOS	10-Jul-15	192 (+15d/-15d)					LOW UTILIZATION		
	HRS	7460.3	8000 (+20/-20)							
	AFL	3992	4000 (+20/-20)							
PROC. REF: AMM 28-46-03										PKG:5032,6032

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
28-50-03-220-002-A01	INSPECT (DETAILED INSPECTION) FWD FUEL TANK UNITS (L650 ONLY)									Service ATA:28
	MOS/MSC	27-Aug-07	N/A							
	HRS	0								
	AFL	0								
	PROC. REF: AMM 28-46-03									PKG:6016
28-50-04-212-001-A00 ^S	INSPECT (GENERAL VISUAL) WING STUB HARNESS NOTE: THIS TASK COMPLIES WITH FUEL TANK IGNITION SOURCES PREVENTION (SFAR-88) (L600 ONLY)									Service ATA:28
	MOS	10-Jul-15	192 (+15d/-15d)					LOW UTILIZATION		
	HRS	7460.3	8000 (+20/-20)							
	AFL	3992	4000 (+20/-20)							
	PROC. REF: AMM 24-00-04									PKG:5032,6032
28-50-04-212-001-A01	INSPECT (GENERAL VISUAL) WING STUB HARNESS (L650 ONLY)									Service ATA:28
	MOS/MSC	27-Aug-07	N/A							
	HRS	0								
	AFL	0								
	PROC. REF: AMM 24-00-04									PKG:6016
28-50-05-212-001-A00 ^S	INSPECT (GENERAL VISUAL) TRAILING EDGE HARNESS NOTE: THIS TASK COMPLIES WITH FUEL TANK IGNITION SOURCES PREVENTION (SFAR-88) (L600 ONLY)									Service ATA:28
	MOS	10-Jul-15	192 (+15d/-15d)					LOW UTILIZATION		
	HRS	7460.3	8000 (+20/-20)							
	AFL	3992	4000 (+20/-20)							
	PROC. REF: AMM 24-00-03									PKG:5032,6032
28-50-05-212-001-A01	INSPECT (GENERAL VISUAL) TRAILING EDGE HARNESS (L650 ONLY)									Service ATA:28
	MOS/MSC	27-Aug-07	N/A							
	HRS	0								
	AFL	0								
	PROC. REF: AMM 24-00-03									PKG:6016
28-50-06-212-001-A00 ^S	INSPECT (GENERAL VISUAL) LEADING EDGE HARNESS NOTE: THIS TASK COMPLIES WITH FUEL TANK IGNITION SOURCES PREVENTION (SFAR-88) (L600 ONLY)									Service ATA:28
	MOS	10-Jul-15	192 (+15d/-15d)					LOW UTILIZATION		
	HRS	7460.3	8000 (+20/-20)							
	AFL	3992	4000 (+20/-20)							
	PROC. REF: AMM 24-00-02									PKG:5032,6032

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 28 - FUEL											
28-50-06-212-001-A01			INSPECT (GENERAL VISUAL) LEADING EDGE HARNESS (L650 ONLY)						Service	ATA:28	
	MOS/MSC	27-Aug-07	N/A								
	HRS	0									
	AFL	0									
					PROC. REF: AMM 24-00-02					PKG:6016	
28-50-07-220-001-A00 ^S			INSPECT (DETAILED INSPECTION) AFT FUEL TANK UNITS NOTE: THIS TASK COMPLIES WITH FUEL TANK IGNITION SOURCES PREVENTION (SFAR-88) (L600 ONLY)						Service	ATA:28	
	MOS	31-Jul-15	192 (+15d/-15d)					LOW UTILIZATION			
	HRS	7460.3	8000 (+20/-20)								
	AFL	3992	4000 (+20/-20)								
					PROC. REF: AMM 28-46-01					PKG:5032,6032	
28-50-07-220-001-A01			INSPECT (DETAILED INSPECTION) AFT FUEL TANK UNITS (L650 ONLY)						Service	ATA:28	
	MOS/MSC	27-Aug-07	N/A								
	HRS	0									
	AFL	0									
					PROC. REF: AMM 28-46-01					PKG:6016	
28-50-08-212-001-A00			INSPECT (GENERAL VISUAL) VENTRAL FUEL TANK EXTERNAL HARNESS(L650 ONLY)						Service	ATA:28	
	MOS/MSC	27-Aug-07	N/A								
	HRS	0									
	AFL	0									
					PROC. REF: AMM 28-27-01					PKG:6016	
28-50-08-220-001-A00			INSPECT (DETAILED INSPECTION) VENTRAL FUEL TANK UNITS (L650 ONLY)						Service	ATA:28	
	MOS/MSC	27-Aug-07	N/A								
	HRS	0									
	AFL	0									
					PROC. REF: AMM 28-41-05					PKG:6016	
28-50-09-212-001-A00			INSPECT (GENERAL VISUAL) FWD FUEL TANK EXTERNAL HARNESS(L650 ONLY)						Service	ATA:28	
	MOS/MSC	27-Aug-07	N/A								
	HRS	0									
	AFL	0									
					PROC. REF: AMM 28-26-01					PKG:6016	
28-50-10-212-001-A00			INSPECT (GENERAL VISUAL) AFT FUEL TANK EXTERNAL HARNESS(L650 ONLY)						Service	ATA:28	
	MOS/MSC	27-Aug-07	N/A								
	HRS	0									
	AFL	0									
					PROC. REF: AMM 28-26-08					PKG:6016	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 28 - FUEL											
281200-0101		LH WING FLOAT VENT VALVE								Component	ATA:28
PN:2930015-102	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-12-01											
281200-0102		LH WING FLOAT VENT VALVE								Component	ATA:28
PN:2930015-102	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-12-01											
281200-0103		RH WING FLOAT VENT VALVE								Component	ATA:28
PN:2930015-102	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-12-01											
281200-0104		RH WING FLOAT VENT VALVE								Component	ATA:28
PN:2930015-102	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-12-01											
281200-0105		FWR TK FLOAT VENT VALVE								Component	ATA:28
PN:2930015-102	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-12-01											
281200-0106		FWR TK FLOAT VENT VALVE								Component	ATA:28
PN:2930015-102	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-12-01											
281200-0107		FWR TK FLOAT VENT VALVE								Component	ATA:28
PN:2930015-102	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-12-01											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 28 - FUEL											
281200-0108		FWR TK FLOAT VENT VALVE								Component	ATA:28
PN:2930015-102	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-12-01											
281205-0201		LH WING FLAME ARRESTOR								Component	ATA:28
PN:130-0045-01	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:2358	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-12-05											
281205-0202		RH WING FLAME ARRESTOR								Component	ATA:28
PN:130-0045-01	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:2359	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-12-05											
281300-0101		LH REAR FUEL TANK ASSEMBLY								Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-13-01											
281300-0102		RH REAR FUEL TANK ASSEMBLY								Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-13-01											
281300-0103		FORWARD FUEL TANK ASSEMBLY								Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-15-04											
281301-0101		REAR LH ALL RUBBER FUEL TANK								Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-13-01											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 28 - FUEL											
281301-0102		REAR RH ALL RUBBER FUEL TANK								Component	ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 28-13-01											
281302-0701 ^U		LH AFT FUEL TANK BLADDER VALVE								Component	ATA:28
PN:RAHE40371	MOS/MSC	19-Aug-16	O/C	TSN 0							
SN:384	HRS	7460.3	TSN 0								
	AFL	3992	TSN 0								
281302-0702 ^U		RH AFT FUEL TANK BLADDER VALVE								Component	ATA:28
PN:RAHE40371	MOS/MSC	19-Aug-16	O/C	TSN 0							
SN:393	HRS	7460.3	TSN 0								
	AFL	3992	TSN 0								
281400-0101		REAR TK CHECK-TYPE BUTTERFLY,INTERNAL TANK,FUEL SYSTEM VALVE								Component	ATA:28
PN:2000034-102	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
281400-0102		REAR TK CHECK-TYPE BUTTERFLY,INTERNAL TANK,FUEL SYSTEM VALVE								Component	ATA:28
PN:2000034-102	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 28-21-03											
281400-0103		REAR TK CHECK-TYPE BUTTERFLY,INTERNAL TANK,FUEL SYSTEM VALVE								Component	ATA:28
PN:2000034-102	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 28-21-03											
281400-0104		REAR TK CHECK-TYPE BUTTERFLY,INTERNAL TANK,FUEL SYSTEM VALVE								Component	ATA:28
PN:2000034-102	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 28-21-03											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 28 - FUEL											
281400-0105		REAR TK CHECK-TYPE BUTTERFLY,INTERNAL TANK,FUEL SYSTEM VALVE							Component	ATA:28	
PN:2000034-102	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-21-03											
281400-0106		REAR TK CHECK-TYPE BUTTERFLY,INTERNAL TANK,FUEL SYSTEM VALVE							Component	ATA:28	
PN:2000034-102	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-21-03											
281400-0201		REAR TK VALVE CHECK-FUEL TANK, FUSELAGE ASSEMBLY							Component	ATA:28	
PN:869A-12BT	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
281400-0202		REAR TK VALVE CHECK-FUEL TANK, FUSELAGE ASSEMBLY							Component	ATA:28	
PN:869A-12BT	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
281400-0203		REAR TK VALVE CHECK-FUEL TANK, FUSELAGE ASSEMBLY							Component	ATA:28	
PN:869A-12BT	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
281400-0204		REAR TK VALVE CHECK-FUEL TANK, FUSELAGE ASSEMBLY							Component	ATA:28	
PN:869A-12BT	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
281400-0301		REAR SEAT SHUTOFF ASSY-FUEL SYS VALVE							Component	ATA:28	
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-23-02											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 28 - FUEL											
281400-0302		FWDSEAT SHUTOFF ASSY-FUEL SYS VALVE							Component	ATA:28	
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 28-23-02											
281400-0303		X FEED SHUTOFF ASSY-FUEL SYS VALVE							Component	ATA:28	
PN:2930003-103	MOS/MSC	11-Dec-12	O/C	TSO 0							
SN:6301	HRS	6440.4	TSO 0								
	AFL	3467	TSO 0								
PROC. REF: AMM 28-23-02											
281400-0304		REAR TK CROSSFEED SHUTOFF ASSY-FUEL SYS VALVE							Component	ATA:28	
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 28-21-04											
281400-0305		FWRTK SHUTOFF ASSY-FUEL SYS VALVE							Component	ATA:28	
PN:2930003-104	MOS/MSC	15-Aug-13	O/C	TSN 0							
SN:4641	HRS	6643.4	TSN 0								
	AFL	3572	TSN 0								
PROC. REF: AMM 28-23-02											
281400-0306		W STUB SHUTOFF ASSY-FUEL SYS VALVE							Component	ATA:28	
PN:2930003-103	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:6833	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 28-23-02											
281400-0307		STUB SHUTOFF ASSY-FUEL SYS VALVE							Component	ATA:28	
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 28-23-02											
281400-0308		APU SHUTOFF ASSY-FUEL SYS VALVE							Component	ATA:28	
PN:2930003-105	MOS/MSC	06-Jul-19	O/C	TSR 0							
SN:7335M	HRS	9057.4	TSR 0								
	AFL	4853	TSR 0								
PROC. REF: AMM 28-23-02											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 28 - FUEL											
281400-0309		LH ENG SHUTOFF ASSY-FUEL SYS VALVE							Component	ATA:28	
PN:2930003-104	MOS/MSC	12-Dec-12	O/C								
SN:6291	HRS	6440.4									
	AFL	3467									
PROC. REF: AMM 28-23-02											
281400-0310		RH ENG SHUTOFF ASSY-FUEL SYS VALVE							Component	ATA:28	
PN:2930003-104	MOS/MSC	19-Aug-15	O/C	TSR 0							
SN:6584	HRS	7460.3		TSR 0							
	AFL	3992		TSR 0							
PROC. REF: AMM 28-23-02											
281400-0311		LEFT REAR TK ENGINE SHUTOFF ASSY-FUEL SYS VALVE							Component	ATA:28	
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-21-05											
281400-0312		RIGHT REAR TK ENGINE SHUTOFF ASSY-FUEL SYS VALVE							Component	ATA:28	
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-21-05											
281400-0313		FWR TK SHUTOFF ASSY-FUEL SYS VALVE							Component	ATA:28	
PN:2930003-104	MOS/MSC	15-Aug-13	O/C								
SN:6995	HRS	6643.4									
	AFL	3572									
PROC. REF: AMM 28-23-02											
281400-0314		REAR TK SHUTOFF VALVE ASSY							Component	ATA:28	
PN:2930003-104	MOS/MSC	15-Aug-13	O/C								
SN:4283	HRS	6643.4									
	AFL	3572									
PROC. REF: AMM 28-23-02											
281400-0316		STUB SHUTOFF ASSY-FUEL SYS VALVE							Component	ATA:28	
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-23-02											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
281400-0401	REAR TK ASSY,RELIEF LINE-INT TNK,AL SENSOR									Component ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
281400-0402	REAR TK ASSY,RELIEF LINE-INT TNK,AL SENSOR									Component ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
281400-0501	FWR TK DRAIN-FUEL SYS VALVE									Component ATA:28
PN:2990076-102	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-11-02										
281400-0502	FWR TK DRAIN-FUEL SYS VALVE									Component ATA:28
PN:2990076-102	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-11-02										
281400-0503	REAR TK DRAIN-FUEL SYS VALVE									Component ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-11-02										
281400-0504	REAR TK DRAIN-FUEL SYS VALVE									Component ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-11-02										
281400-0505	LEFT FUSELAGE TANK DRAIN-FUEL SYS VALVE									Component ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-11-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
281400-0506	RIGHT FUSELAGE TANK DRAIN-FUEL SYS VALVE									Component ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-11-02										
281400-0507	VENTRAL TANK NO.1 DRAIN-FUEL SYS VALVE									Component ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-11-02										
281400-0508	VENTRAL TANK NO.2 DRAIN-FUEL SYS VALVE									Component ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-11-02										
281400-0509	VENTRAL TANK NO.3 VENTRAL TANK VALVE									Component ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
281400-0601	REAR TK RELIEF-INTERNAL TANK,FUEL SYSTEM VALVE									Component ATA:28
PN:2000062-103	MOS/MSC	25-Jun-19	O/C	TSN 32						
SN:2367	HRS	9057.4		TSN 773.3						
	AFL	4853		TSN 407						
PROC. REF: AMM 28-14-13, AMM 28-14-14										
281400-0602	REAR TK RELIEF-INTERNAL TANK,FUEL SYSTEM VALVE									Component ATA:28
PN:2000062-103	MOS/MSC	25-Jun-19	O/C	TSN 32						
SN:2355	HRS	9057.4		TSN 773.3						
	AFL	4853		TSN 407						
PROC. REF: AMM 28-14-13, AMM 28-14-14										
281400-0603	L/H AFT TANK DIFFERENTIAL PRESSURE SWITCH									Component ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-21-03										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of:
11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 28 - FUEL											
281400-0604		R/H AFT TANK DIFFERENTIAL PRESSURE SWITCH							Component	ATA:28	
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
281400-0701		LH REAR FUEL TANK RELIEF VALVE							Component	ATA:28	
PN:2000031-102	MOS/MSC	29-Jun-23	O/C								
SN:0567	HRS	10161.5									
	AFL	5401									
PROC. REF: AMM 28-14-13, AMM 28-14-14											
281400-0702		RH REAR FUEL TANK RELIEF VALVE							Component	ATA:28	
PN:2000031-102	MOS/MSC	29-Jun-23	O/C								
SN:0568	HRS	10161.5									
	AFL	5401									
PROC. REF: AMM 28-14-13, AMM 28-14-14											
281400-0801		FWR TK ARRESTOR-FLAME,VENT LINE							Component	ATA:28	
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-16-05											
281400-0802		FWR TK ARRESTOR-FLAME,VENT LINE							Component	ATA:28	
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-16-05											
281400-0803		REAR TK ARRESTOR-FLAME,VENT LINE							Component	ATA:28	
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-16-05											
281400-0804		REAR TK ARRESTOR-FLAME,VENT LINE							Component	ATA:28	
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-16-05											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
281400-0901	LH WING CHECK-TYPE BUTTERFLY,INTERNAL TANK,FUEL SYSTEM VALVE									Component ATA:28
PN:2000034-102	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
281400-0902	RH WING CHECK-TYPE BUTTERFLY,INTERNAL TANK,FUEL SYSTEM VALVE									Component ATA:28
PN:2000034-102	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
281400-0903	LH WING CHECK-TYPE BUTTERFLY,INTERNAL TANK,FUEL SYSTEM VALVE									Component ATA:28
PN:2000034-102	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-21-03										
281400-0904	RH WING CHECK-TYPE BUTTERFLY,INTERNAL TANK,FUEL SYSTEM VALVE									Component ATA:28
PN:2000034-102	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-21-03										
281501-0101	REAR TK ELECTRICAL-FUEL SYSTEM, INTERNAL PUMP									Component ATA:28
PN:1C7-25	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-21-01										
281501-0102	REAR TK ELECTRICAL-FUEL SYSTEM, INTERNAL PUMP									Component ATA:28
PN:1C7-25	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-21-01										
281501-0103	FWR TK ELECTRICAL-FUEL SYSTEM, INTERNAL PUMP									Component ATA:28
PN:1C7-25	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-21-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
281501-0104 FWR TK ELECTRICAL-FUEL SYSTEM,INTERNAL PUMP Component ATA:28										
PN:1C7-25	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-21-01										
281501-0105 FWR TK ELECTRICAL-FUEL SYSTEM,INTERNAL PUMP Component ATA:28										
PN:1C7-25	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-21-01										
281501-0106 FWR TK ELECTRICAL-FUEL SYSTEM,INTERNAL PUMP Component ATA:28										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-21-01										
281501-0107 LEFT VENTRAL TANK ELECTRICAL PUMP Component ATA:28										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-24-12										
281501-0108 RIGHT VENTRAL TANK ELECTRICAL PUMP Component ATA:28										
PN:1C7-25	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-24-12										
281501-0201 FWR TK PRESSURE SWITCH Component ATA:28										
PN:F7-337-2	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-23-05										
281501-0202 FWR TK PRESSURE SWITCH Component ATA:28										
PN:F7-337-2	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-23-05										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
281501-0203 FWR TK PRESSURE SWITCH Component ATA:28										
PN:F7-337-2	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: AMM 28-23-05										
281501-0204 FWR TK PRESSURE SWITCH Component ATA:28										
PN:F7-337-2	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: AMM 28-23-05										
281501-0205 REAR TK PRESSURE SWITCH Component ATA:28										
PN:F7-337-2	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: AMM 28-23-05										
281501-0206 REAR TK PRESSURE SWITCH Component ATA:28										
PN:F7-337-2	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: AMM 28-23-05										
281501-0301 FWR TK INTERNAL, SOLENOID ASSY-REFUELLING VALVE Component ATA:28										
PN:2990059-102	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: AMM 28-24-10										
281501-0302 FWR TK INTERNAL, SOLENOID ASSY-REFUELLING VALVE Component ATA:28										
PN:2990059-102	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: AMM 28-24-10										
281501-0303 FWR TK INTERNAL, SOLENOID ASSY-REFUELLING VALVE Component ATA:28										
PN:2990059-102	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: AMM 28-24-10										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 28 - FUEL											
281501-0304		FWR TK INTERNAL, SOLENOID ASSY-REFUELLING VALVE							Component	ATA:28	
PN:2990059-102	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 28-24-10											
281501-0305		REAR TK INTERNAL, SOLENOID ASSY-REFUELLING VALVE							Component	ATA:28	
PN:2990059-102	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 28-24-10											
281501-0306		REAR TK INTERNAL, SOLENOID ASSY-REFUELLING VALVE							Component	ATA:28	
PN:2990059-102	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 28-24-10											
281501-0307		REAR TK INTERNAL, SOLENOID ASSY-REFUELLING VALVE							Component	ATA:28	
PN:2990059-102	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 28-24-10											
281501-0308		REAR TK INTERNAL, SOLENOID ASSY-REFUELLING VALVE							Component	ATA:28	
PN:2990059-102	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 28-24-10											
281501-0401		FWR TK FUEL SYS - SHUTOFF VALVE							Component	ATA:28	
PN:2000038-102	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 28-23-02											
281501-0402		FWR TK FUEL SYS - SHUTOFF VALVE							Component	ATA:28	
PN:2000038-102	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 28-23-02											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 28 - FUEL											
281501-0403		REAR TK FUEL SYS - SHUTOFF VALVE							Component	ATA:28	
PN:2000038-102	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 28-23-02											
281501-0404		REAR TK FUEL SYS - SHUTOFF VALVE							Component	ATA:28	
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 28-23-02											
281501-0501		FWR TK RELIEF-INTERNAL TANK,FUEL SYSTEM VALVE							Component	ATA:28	
PN:2000062-101	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: GENERIC NO REF											
281501-0502		FWR TK RELIEF-INTERNAL TANK,FUEL SYSTEM VALVE							Component	ATA:28	
PN:2000062-101	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: GENERIC NO REF											
281501-0503		LEFT RELIEF-INTERNAL TANK,FUEL SYSTEM VALVE							Component	ATA:28	
PN:2000062-101	MOS/MSC	06-Jul-15	O/C								
SN:0581	HRS	7460.3									
	AFL	3992									
PROC. REF: GENERIC NO REF											
281501-0504		RIGHT RELIEF-INTERNAL TANK,FUEL SYSTEM VALVE							Component	ATA:28	
PN:2000062-101	MOS/MSC	06-Jul-15	O/C								
SN:0928	HRS	7460.3									
	AFL	3992									
PROC. REF: GENERIC NO REF											
281501-0505		MID RELIEF-INTERNAL TANK,FUEL SYSTEM VALVE							Component	ATA:28	
PN:2000062-101	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: GENERIC NO REF											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
281501-0601	FWR TK CHECK-TYPE THERMOSTATIC EXPANSION,TANK,FUEL SYS VALVE									Component ATA:28
PN:2020035-101	MOS/MSC		29-Jun-23	O/C						
SN:0296	HRS		10161.5							
	AFL		5401							
PROC. REF: GENERIC NO REF										
281501-0602	FWR TK CHECK-TYPE THERMOSTATIC EXPANSION,TANK,FUEL SYS VALVE									Component ATA:28
PN:2020035-101	MOS/MSC		29-Jun-23	O/C						
SN:0318	HRS		10161.5							
	AFL		5401							
PROC. REF: GENERIC NO REF										
281501-0603	FWR TK CHECK-TYPE THERMOSTATIC EXPANSION,TANK,FUEL SYS VALVE									Component ATA:28
PN:2020035-101	MOS/MSC		29-Jun-23	O/C	TSN 0					
SN:1668	HRS		10161.5		TSN 0					
	AFL		5401		TSN 0					
PROC. REF: GENERIC NO REF										
281501-0604	FWR TK CHECK-TYPE THERMOSTATIC EXPANSION,TANK,FUEL SYS VALVE									Component ATA:28
PN:2020035-101	MOS/MSC		29-Jun-23	O/C						
SN:0675	HRS		10161.5							
	AFL		5401							
PROC. REF: GENERIC NO REF										
281501-0701	F UND TK EQUIPPED FORWARD UNDERBELLY TANK TANK									Component ATA:28
PN:PN	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: GENERIC NO REF										
281701-0101	VENT TK EQUIPPED VENTRAL TANK TANK									Component ATA:28
PN:PN	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: AMM NO REF										
281701-0102	VENT TK EQUIPPED VENTRAL TANK TANK									Component ATA:28
PN:PN	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: AMM NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
281801-0101 FORWARD LEFT VENTRAL TANK FLOAT VENT VALVE Component ATA:28										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM NO REF										
281801-0102 FORWARD RIGHT VENTRAL TANK FLOAT VENT VALVE Component ATA:28										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM NO REF										
281801-0103 AFT LEFT VENTRAL TANK FLOAT VENT VALVE Component ATA:28										
PN:2930015-102	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM NO REF										
281801-0104 AFT RIGHT VENTRAL TANK FLOAT VENT VALVE Component ATA:28										
PN:2930015-102	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM NO REF										
281805-0101 LEFT FLAME ARRESTOR Component ATA:28										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-12-05										
281805-0102 RIGHT FLAME ARRESTOR Component ATA:28										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-12-05										
282004-0101 MODULE ASSY MODULE Component ATA:28										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
282100-0101 REAR TK BALL-FUEL SYS VALVE										Component ATA:28
PN:869A-12TT	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:07-0320603	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
282100-0102 REAR TK BALL-FUEL SYS VALVE										Component ATA:28
PN:869A-12TT	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:07-0320592	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
282100-0201 LH WING EJECTOR-FUEL SYSTEM,COMPLETION PUMP										Component ATA:28
PN:2010031-101	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:0375	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-21-02										
282100-0202 RH WING EJECTOR-FUEL SYSTEM,COMPLETION PUMP										Component ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-21-02										
282100-0301 LH WING ELECTRICAL-FUEL SYSTEM,TANK,REAR FUSELAGE PUMP										Component ATA:28
PN:2C7-4	MOS/MSC	19-Oct-11	O/C	TSN 0						
SN:6BF26	HRS	4959.3		TSN 0						
	AFL	2629		TSN 0						
PROC. REF: AMM 28-21-01										
282100-0302 LH WING ELECTRICAL-FUEL SYSTEM,TANK,REAR FUSELAGE PUMP										Component ATA:28
PN:2C7-4	MOS/MSC	25-Oct-23	O/C	TSO 0						
SN:4AP102	HRS	10280.2		TSO 0						
	AFL	5473		TSO 0						
PROC. REF: AMM 28-21-01										
282100-0303 LH WING ELECTRICAL-FUEL SYSTEM,TANK,REAR FUSELAGE PUMP										Component ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-21-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
282100-0304 RH WING ELECTRICAL-FUEL SYSTEM,TANK,REAR FUSELAGE PUMP Component ATA:28										
PN:2C7-4	MOS/MSC	29-Jul-21	O/C	TSR 9						
SN:10AY472	HRS	9631.4		TSN 5922, TSR 0						
	AFL	5130		TSN 2307, TSR 0						
PROC. REF: AMM 28-21-01										
282100-0305 RH WING ELECTRICAL-FUEL SYSTEM,TANK,REAR FUSELAGE PUMP Component ATA:28										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-21-01										
282100-0306 RH WING ELECTRICAL-FUEL SYSTEM,TANK,REAR FUSELAGE PUMP Component ATA:28										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-21-01										
282100-0401 W STUB FUEL SYSTEM CHECK VALVE Component ATA:28										
PN:2930006-101	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:2110	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
282100-0402 W STUB FUEL SYSTEM CHECK VALVE Component ATA:28										
PN:2930006-101	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:2177	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
282100-0501 LH STUB POPPET-RELIEF, FUEL SYS, WING STUB JUNCTION VALVE Component ATA:28										
PN:2930005-102	MOS/MSC	29-Jun-23	O/C							
SN:3665	HRS	10161.5								
	AFL	5401								
PROC. REF: GENERIC NO REF										
282100-0502 RH STUB POPPET-RELIEF, FUEL SYS, WING STUB JUNCTION VALVE Component ATA:28										
PN:2930005-102	MOS/MSC	29-Jun-23	O/C							
SN:3673	HRS	10161.5								
	AFL	5401								
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 28 - FUEL											
282100-0503		REAR TK POPPET-RELIEF, FUEL SYS, WING STUB JUNCTION VALVE							Component	ATA:28	
PN:2930005-102	MOS/MSC	29-Jun-23	O/C								
SN:2306	HRS	10161.5									
	AFL	5401									
PROC. REF: GENERIC NO REF											
282100-0504		REAR TK POPPET-RELIEF, FUEL SYS, WING STUB JUNCTION VALVE							Component	ATA:28	
PN:2930005-102	MOS/MSC	29-Jun-23	O/C								
SN:3666	HRS	10161.5									
	AFL	5401									
PROC. REF: GENERIC NO REF											
282100-0601		REAR TK PRESSURE,28VDC/25AMPS,ENGINE FUEL SYS SWITCH							Component	ATA:28	
PN:21117-1	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
282100-0602		REAR TK PRESSURE,28VDC/25AMPS,ENGINE FUEL SYS SWITCH							Component	ATA:28	
PN:21117-1	MOS/MSC	27-Mar-18	O/C	TSN 9							
SN:5821	HRS	8539		TSN 0							
	AFL	4583		TSN 0							
PROC. REF: GENERIC NO REF											
282100-0703		APU PRESSURE-FUEL SYS,STEEL SWITCH							Component	ATA:28	
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-45-02											
282100-0801		LH WING BALL-FUEL SYS VALVE							Component	ATA:28	
PN:869A-12TT	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:07-0320596	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
282100-0802		RH WING BALL-FUEL SYS VALVE							Component	ATA:28	
PN:869A-12TT	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:04-0911258	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 28 - FUEL											
282100-0901		LH ENG PRESSURE-FUEL SYS,STEEL SWITCH							Component	ATA:28	
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 28-45-01											
282100-0902		RH ENG PRESSURE-FUEL SYS,STEEL SWITCH							Component	ATA:28	
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 28-45-01											
282102-0101		OVERH P MODULE -FUEL CONTROL PANEL ASSEMBLY							Component	ATA:28	
PN:135-05400-403	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:124562	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 28-20-04											
282103-0101		AUXILIARY FUEL SYS RELAY BOX							Component	ATA:28	
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 28-20-02											
282103-0201		MODULE 6, W7000 FUEL CTL IV MODULE							Component	ATA:28	
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: GENERIC NO REF											
282201-0101		APU FUEL SYS - SHUTOFF VALVE							Component	ATA:28	
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 28-23-02											
282300-0101		PRESS FUELLING,PRESSURE,AL ADAPTER							Component	ATA:28	
PN:2820052-102	MOS/MSC	10-Aug-16	O/C	TSR 16							
SN:1643	HRS	7841.1	TSR 0								
	AFL	4202	TSR 0								
PROC. REF: AMM 28-23-01											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 28 - FUEL											
282300-0201		LH WING FUEL TANK SHUTOFF VALVE								Component	ATA:28
PN:2810049-101	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:3001	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-23-02											
282300-0202		RH WING FUEL TANK SHUTOFF VALVE								Component	ATA:28
PN:2810049-101	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:3000	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-23-02											
282300-0301		REAR TK PRESSURE SWITCH								Component	ATA:28
PN:F7-330-2	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-23-05											
282300-0302		REAR TK PRESSURE SWITCH								Component	ATA:28
PN:F7-330-2	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-23-05											
282300-0305		FWR TK PRESSURE SWITCH								Component	ATA:28
PN:F7-330-2	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-23-05											
282300-0306		FWR TK PRESSURE SWITCH								Component	ATA:28
PN:F7-330-2	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-23-05											
282300-0307		LH PRESSURE SWITCH								Component	ATA:28
PN:211C119-168	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-23-05											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 28 - FUEL											
282300-0308		RH PRESSURE SWITCH								Component	ATA:28
PN:211C119-168	MOS/MSC		27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS		0		TSN 0						
	AFL		0		TSN 0						
PROC. REF: AMM 28-23-05											
282300-0501		LH WING FUEL TANK RELIEF VALVE								Component	ATA:28
PN:2810050-102	MOS/MSC		27-Aug-07	O/C	TSN 0						
SN:3043	HRS		0		TSN 0						
	AFL		0		TSN 0						
PROC. REF: AMM 28-21-03											
282300-0502		RH WING FUEL TANK RELIEF VALVE								Component	ATA:28
PN:2810050-102	MOS/MSC		27-Aug-07	O/C	TSN 0						
SN:3040	HRS		0		TSN 0						
	AFL		0		TSN 0						
PROC. REF: AMM 28-21-03											
282300-0601		FUEL REPEATER INDICATOR								Component	ATA:28
PN:366-927-001	MOS/MSC		27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS		0		TSN 0						
	AFL		0		TSN 0						
PROC. REF: AMM 28-23-08											
282300-0701		LH WING PRESSURE SWITCH								Component	ATA:28
PN:F7-330-2	MOS/MSC		27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS		0		TSN 0						
	AFL		0		TSN 0						
PROC. REF: AMM 28-23-05											
282300-0702		RH WING PRESSURE SWITCH								Component	ATA:28
PN:F7-330-2	MOS/MSC		27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS		0		TSN 0						
	AFL		0		TSN 0						
PROC. REF: AMM 28-23-05											
282300-0801		LH WING VALVE VENT -RELIEF,FUEL TANK ASSEMBLY								Component	ATA:28
PN:2810051-104	MOS/MSC		27-Aug-07	O/C	TSN 0						
SN:4252AA	HRS		0		TSN 0						
	AFL		0		TSN 0						
PROC. REF: AMM 28-23-04											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 28 - FUEL											
282300-0802		RH WING VALVE VENT -RELIEF,FUEL TANK ASSEMBLY							Component	ATA:28	
PN:2810051-104	MOS/MSC		27-Aug-07	O/C	TSN 0						
SN:4161AA	HRS		0		TSN 0						
	AFL		0		TSN 0						
PROC. REF: AMM 28-23-04											
282300-0901		FORWARD RH WING/FUSLG FAIRING - REFUEL/DEFUEL CTRL PANEL ASSEMBLY							Component	ATA:28	
PN:135-04756-403	MOS/MSC		27-Aug-07	O/C	TSN 0						
SN:143475	HRS		0		TSN 0						
	AFL		0		TSN 0						
PROC. REF: AMM 28-23-09											
282301-0101		REAR TK VALVE -RELIEF, FUEL TANK, WING ASSEMBLY							Component	ATA:28	
PN:2990074-102	MOS/MSC		27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS		0		TSN 0						
	AFL		0		TSN 0						
PROC. REF: AMM 28-21-03											
282301-0102		REAR TK VALVE -RELIEF, FUEL TANK, WING ASSEMBLY							Component	ATA:28	
PN:2990074-102	MOS/MSC		27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS		0		TSN 0						
	AFL		0		TSN 0						
PROC. REF: AMM 28-21-03											
282301-0103		FWR TK VALVE -RELIEF, FUEL TANK, WING ASSEMBLY							Component	ATA:28	
PN:2990074-102	MOS/MSC		27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS		0		TSN 0						
	AFL		0		TSN 0						
PROC. REF: AMM 28-21-03											
282301-0104		FWR TK VALVE -RELIEF, FUEL TANK, WING ASSEMBLY							Component	ATA:28	
PN:2990074-102	MOS/MSC		27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS		0		TSN 0						
	AFL		0		TSN 0						
PROC. REF: AMM 28-21-03											
282302-0101		REAR TK REFUEL SHUTOFF VALVE							Component	ATA:28	
PN:2990078-102	MOS/MSC		28-Aug-16	O/C							
SN:1208	HRS		7864.3								
	AFL		4220								
PROC. REF: AMM 28-24-11											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 28 - FUEL											
282302-0102		REAR TK REFUEL SHUTOFF VALVE							Component	ATA:28	
PN:2990078-102	MOS/MSC	06-Oct-16	O/C								
SN:0334	HRS	7915.2									
	AFL	4246									
PROC. REF: AMM 28-24-11											
282302-0103		FWR TK REFUEL SHUTOFF VALVE							Component	ATA:28	
PN:2990078-102	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-24-11											
282302-0104		FWR TK REFUEL SHUTOFF VALVE							Component	ATA:28	
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-24-11											
282302-0105		LEFT UNDERBELLY TANK SHUTOFF ASSY-FUEL SYS VALVE							Component	ATA:28	
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
282302-0106		RIGHT UNDERBELLY TANK SHUTOFF ASSY-FUEL SYS VALVE							Component	ATA:28	
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
282302-0107		STUB - FUEL SYSTEM - SHUTOFF VALVE ASSEMBLY							Component	ATA:28	
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-23-02											
282302-0108		STUB - FUEL SYSTEM - SHUTOFF VALVE ASSEMBLY							Component	ATA:28	
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-23-02											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
282302-0109	STUB - FUEL SYSTEM - SHUTOFF VALVE ASSEMBLY									Component ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 28-23-02										
282304-0101	REAR TK LEVEL, FLOAT TYPE, FUEL SYS,WING SENSOR									Component ATA:28
PN:005-023-001	MOS/MSC	O/C								
SN:UNKNOWN	HRS									
	AFL	0								
PROC. REF: GENERIC NO REF										
282304-0102	REAR TK LEVEL, FLOAT TYPE, FUEL SYS,WING SENSOR									Component ATA:28
PN:005-023-001	MOS/MSC	O/C								
SN:UNKNOWN	HRS									
	AFL	0								
PROC. REF: GENERIC NO REF										
282304-0103	FWRTK LEVEL, FLOAT TYPE, FUEL SYS,WING SENSOR									Component ATA:28
PN:005-023-001	MOS/MSC	O/C								
SN:UNKNOWN	HRS									
	AFL	0								
PROC. REF: GENERIC NO REF										
282304-0104	FWRTK LEVEL, FLOAT TYPE, FUEL SYS,WING SENSOR									Component ATA:28
PN:005-023-001	MOS/MSC	02-Feb-12	O/C	TSN 0						
SN:1844	HRS	5374	TSN 0							
	AFL	2843	TSN 0							
PROC. REF: GENERIC NO REF										
282304-0105	LH WING FLOAT TYPE, FUEL SYS LEVEL SENSOR									Component ATA:28
PN:005-023-001	MOS/MSC	O/C								
SN:UNKNOWN	HRS									
	AFL	0								
PROC. REF: GENERIC NO REF										
282304-0106	RH WING FLOAT TYPE, FUEL SYS LEVEL SENSOR									Component ATA:28
PN:005-023-001	MOS/MSC	O/C								
SN:UNKNOWN	HRS									
	AFL	0								
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
282307-0101	DEFUELING SHUTOFF ASSY-FUEL SYS VALVE									Component ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 28-23-07										
282309-0101	MODULE ASSY MODULE									Component ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: GENERIC NO REF										
282311-0101	VENTRAL TANK REFUELING SHUTOFF ASSY-FUEL SYS VALVE									Component ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM NO REF										
282313-0101	VENTRAL TANK FUEL SYS - SHUTOFF VALVE									Component ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM NO REF										
282318-0101	LH WING HIGH LEVEL FUEL SENSOR									Component ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: GENERIC NO REF										
282318-0102	RH WING HIGH LEVEL FUEL SENSOR									Component ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: GENERIC NO REF										
282320-0101	VENTRAL HIGH LEVEL FUEL SENSOR									Component ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of:
11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 28 - FUEL											
282411-0101		LH FWD REFUELING SHUTOFF ASSY-FUEL SYS VALVE							Component	ATA:28	
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-24-11											
282411-0102		RH FWD REFUELING SHUTOFF ASSY-FUEL SYS VALVE							Component	ATA:28	
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-24-11											
282411-0103		LH AFT REFUELING SHUTOFF ASSY-FUEL SYS VALVE							Component	ATA:28	
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-24-11											
282411-0104		RH AFT REFUELING SHUTOFF ASSY-FUEL SYS VALVE							Component	ATA:28	
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-24-11											
282412-0101		LEFT FORWARD TANK FUEL SYS - SHUTOFF VALVE							Component	ATA:28	
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-24-11											
282412-0102		RIGHT FORWARD TANK FUEL SYS - SHUTOFF VALVE							Component	ATA:28	
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-24-11											
282412-0103		AFT TANK FUEL SYS - SHUTOFF VALVE							Component	ATA:28	
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-24-11											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
282412-0104 FORWARD TANK FUEL SYS SHUTOFF VALVE Component ATA:28										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-23-02										
282414-0101 LEFT FORWARD TANK HIGH LEVEL FUEL SENSOR Component ATA:28										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
282414-0102 RIGHT FORWARD TANK HIGH LEVEL FUEL SENSOR Component ATA:28										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
282600-0101 REAR FUEL SYS, INTERNAL TANK PRESSURE SWITCH Component ATA:28										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
282600-0102 REAR FUEL SYS, INTERNAL TANK PRESSURE SWITCH Component ATA:28										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
282604-0101 LEFT FORWARD TANK TRANSFER SHUTOFF ASSY-FUEL SYS VALVE Component ATA:28										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-26-04										
282604-0102 RIGHT FORWARD TANK TRANSFER SHUTOFF ASSY-FUEL SYS VALVE Component ATA:28										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-26-04										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
282610-0101 LEFT AFT TANK TRANSFER SHUTOFF ASSY-FUEL SYS VALVE Component ATA:28										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-26-10										
282610-0102 RIGHT AFT TANK TRANSFER SHUTOFF ASSY-FUEL SYS VALVE Component ATA:28										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-26-10										
282615-0101 CROSS TRANSFER FUEL SYS - SHUTOFF VALVE Component ATA:28										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-26-15										
282618-0101 LEFT AFT TANK FUEL ISOLATION ELECTRICAL FUEL SYS - SHUTOFF VALVE Component ATA:28										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-26-18										
282618-0102 RIGHT AFT TANK FUEL ISOLATION ELECTRICAL FUEL SYS - SHUTOFF VALVE Component ATA:28										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-26-18										
282621-0101 LEFT FORWARD TANK LOW LEVEL FUEL SENSOR Component ATA:28										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-26-21										
282621-0102 RIGHT FORWARD TANK LOW LEVEL FUEL SENSOR Component ATA:28										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-26-21										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
282622-0101	LEFT UPPER AFT TANK LOW LEVEL FUEL SENSOR									Component ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 28-26-22										
282622-0102	LEFT LOWER AFT TANK LOW LEVEL FUEL SENSOR									Component ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 28-26-22										
282622-0103	RIGHT UPPER AFT TANK LOW LEVEL FUEL SENSOR									Component ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 28-26-22										
282622-0104	RIGHT LOWER AFT TANK LOW LEVEL FUEL SENSOR									Component ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 28-26-22										
282702-0101	VENTRAL TANK - TRANSFER PUMP CHECK VALVE									Component ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM NO REF										
282702-0102	VENTRAL TANK - TRANSFER PUMP CHECK VALVE									Component ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM NO REF										
282704-0101	VENTRAL TANK TRANSFER SHUTOFF ASSY-FUEL SYS VALVE									Component ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 28 - FUEL											
284100-0201		LH WING FUEL TANK UNIT								Component	ATA:28
PN:028-936-002	MOS/MSC		27-Aug-07	O/C	TSN 0						
SN:2382B	HRS		0		TSN 0						
	AFL		0		TSN 0						
PROC. REF: AMM 28-41-02											
284100-0202		RH WING FUEL TANK UNIT								Component	ATA:28
PN:028-936-002	MOS/MSC		27-Aug-07	O/C	TSN 0						
SN:2381B	HRS		0		TSN 0						
	AFL		0		TSN 0						
PROC. REF: AMM 28-41-02											
284100-0203		LH WING FUEL TANK UNIT								Component	ATA:28
PN:028-936-005	MOS/MSC		27-Aug-07	O/C	TSN 0						
SN:2318B	HRS		0		TSN 0						
	AFL		0		TSN 0						
PROC. REF: AMM 28-41-02											
284100-0204		RH WING FUEL TANK UNIT								Component	ATA:28
PN:028-936-005	MOS/MSC		13-Dec-19	O/C	TSR 8						
SN:1494B	HRS		9243.4		TSR 0						
	AFL		4944		TSR 0						
PROC. REF: AMM 28-41-02											
284100-0205		LH WING STUB TANK #1B UNIT								Component	ATA:28
PN:028-936-008	MOS/MSC		27-Aug-07	O/C	TSN 0						
SN:1797B	HRS		0		TSN 0						
	AFL		0		TSN 0						
PROC. REF: AMM 28-41-02											
284100-0206		RH WING STUB TANK #1B UNIT								Component	ATA:28
PN:028-936-008	MOS/MSC		27-Aug-07	O/C	TSN 0						
SN:1796B	HRS		0		TSN 0						
	AFL		0		TSN 0						
PROC. REF: AMM 28-41-02											
284100-0301		LH WING FUEL QUANTITY TRANSMITTER								Component	ATA:28
PN:028-936-004	MOS/MSC		27-Aug-07	O/C	TSN 0						
SN:2320B	HRS		0		TSN 0						
	AFL		0		TSN 0						
PROC. REF: GENERIC NO REF											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of:
11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 28 - FUEL											
284100-0302		RH WING FUEL QUANTITY TRANSMITTER								Component	ATA:28
PN:028-936-004	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:2318B	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
284100-0303		LH WING TANK FUEL QUANTITY TRANSMITTER								Component	ATA:28
PN:028-936-006	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:2418B	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
284100-0304		RH WING TANK FUEL QUANTITY TRANSMITTER								Component	ATA:28
PN:028-936-006	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:2415B	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
284100-0305		RH WING FUEL QUANTITY TRANSMITTER								Component	ATA:28
PN:028-936-003	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:2347B	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
284100-0401		LH WING FUEL TANK,WING STUB PROBE								Component	ATA:28
PN:028-936-007	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:1691B	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
284100-0402		RH WING FUEL TANK,WING STUB PROBE								Component	ATA:28
PN:028-936-007	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:1697B	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
284100-0501		LH WING LOW LEVEL FUEL TANK SENSOR								Component	ATA:28
PN:057-905-001	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:2510B	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-44-01											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 28 - FUEL											
284100-0502		RH WING LOW LEVEL, FUEL TANK SENSOR							Component	ATA:28	
PN:057-905-001	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:2512B	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 28-44-01											
284100-0601		CREW CAB SIGNAL CONDITIONING-LEVEL, FUEL SYS UNIT							Component	ATA:28	
PN:367-934-002	MOS/MSC	21-Jan-22	O/C	TSR 4							
SN:606	HRS	9789.3		TSN 14438.1, TSR 0							
	AFL	5205		TSR 0							
PROC. REF: AMM 28-41-01											
284100-0602		CSL CENT SIGNAL CONDITIONING-LEVEL, FUEL SYS UNIT							Component	ATA:28	
PN:367-934-006	MOS/MSC	07-Feb-12	O/C								
SN:1362	HRS	5380.8									
	AFL	2849									
PROC. REF: AMM 28-41-01											
284100-0603		CSL CENT SIGNAL CONDITIONING-LEVEL, FUEL SYS UNIT							Component	ATA:28	
PN:367-934-006	MOS/MSC	06-Jul-15	O/C	TSR 9							
SN:1321	HRS	7460.3		TSN 1334, TSR 0							
	AFL	3992		TSN 500, TSR 0							
PROC. REF: AMM 28-41-01											
284101-0101		FWR TK FUEL INDICATOR PROBE							Component	ATA:28	
PN:028-065-002	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
284101-0102		FWR TK FUEL INDICATOR PROBE							Component	ATA:28	
PN:028-065-002	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
284101-0103		FWR TK FUEL INDICATOR PROBE							Component	ATA:28	
PN:028-065-002	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 28 - FUEL											
284101-0104		FWR TK FUEL INDICATOR PROBE								Component	ATA:28
PN:028-065-002	MOS/MSC		27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS		0		TSN 0						
	AFL		0		TSN 0						
PROC. REF: GENERIC NO REF											
284101-0105		FWR TK FUEL INDICATOR PROBE								Component	ATA:28
PN:028-065-001	MOS/MSC		27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS		0		TSN 0						
	AFL		0		TSN 0						
PROC. REF: GENERIC NO REF											
284101-0106		FWR TK FUEL INDICATOR PROBE								Component	ATA:28
PN:028-065-001	MOS/MSC		27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS		0		TSN 0						
	AFL		0		TSN 0						
PROC. REF: GENERIC NO REF											
284101-0107		FWR TK FUEL INDICATOR PROBE								Component	ATA:28
PN:028-065-001	MOS/MSC		27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS		0		TSN 0						
	AFL		0		TSN 0						
PROC. REF: GENERIC NO REF											
284101-0108		FWR TK FUEL INDICATOR PROBE								Component	ATA:28
PN:028-065-001	MOS/MSC		27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS		0		TSN 0						
	AFL		0		TSN 0						
PROC. REF: GENERIC NO REF											
284101-0201		FWR TK HARNESS FORWARD AUXILIARY TANK ASSEMBLY								Component	ATA:28
PN:PN	MOS/MSC		27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS		0		TSN 0						
	AFL		0		TSN 0						
PROC. REF: AMM 28-46-04											
284101-0202		FWR TK HARNESS FORWARD AUXILIARY TANK ASSEMBLY								Component	ATA:28
PN:PN	MOS/MSC		27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS		0		TSN 0						
	AFL		0		TSN 0						
PROC. REF: AMM 28-46-04											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 28 - FUEL											
284102-0301		FORWARD CONTROL-LEVEL SWITCH, FUEL SYS UNIT							Component	ATA:28	
PN:367-340-001	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: GENERIC NO REF											
284102-0302		FORWARD CONTROL-LEVEL SWITCH, FUEL SYS UNIT							Component	ATA:28	
PN:367-340-001	MOS/MSC	21-Aug-09	O/C	TSR 0							
SN:1401	HRS	2411.7		TSR 0							
	AFL	1277		TSR 0							
PROC. REF: NDT GENERIC											
284102-0401		LH WING WING TANK FUEL QUANTITY SENSOR							Component	ATA:28	
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: NDT GENERIC											
284102-0402		RH WING WING TANK FUEL QUANTITY SENSOR							Component	ATA:28	
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: NDT GENERIC											
284102-0403		LH WING WING TANK FUEL QUANTITY SENSOR							Component	ATA:28	
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: NDT GENERIC											
284102-0404		RH WING WING TANK FUEL QUANTITY SENSOR							Component	ATA:28	
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: NDT GENERIC											
284102-0405		LH WING WING TANK FUEL QUANTITY SENSOR							Component	ATA:28	
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: NDT GENERIC											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of:
11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
284102-0406	RH WING WING TANK FUEL QUANTITY SENSOR									Component ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										
284102-0407	LH WING WING TANK FUEL QUANTITY SENSOR									Component ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										
284102-0408	RH WING WING TANK FUEL QUANTITY SENSOR									Component ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										
284102-0409	LH WING WING TANK FUEL QUANTITY SENSOR									Component ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										
284102-0410	RH WING WING TANK FUEL QUANTITY SENSOR									Component ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										
284102-0411	LH WING WING TANK FUEL QUANTITY SENSOR									Component ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										
284102-0412	RH WING WING TANK FUEL QUANTITY SENSOR									Component ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
284103-0101	TANK UNIT HARNESS ASSEMBLY									Component ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-41-03										
284103-0102	RH WING TANK UNIT HARNESS ASSEMBLY									Component ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-41-03										
284105-0101	LEFT VENTRAL TANL UNIT SENSOR									Component ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										
284105-0102	RIGHT VENTRAL TANL UNIT SENSOR									Component ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										
284105-0103	VENTRAL TANL UNIT SENSOR									Component ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										
284105-0104	VENTRAL TANL UNIT SENSOR									Component ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										
284105-0105	VENTRAL TANL UNIT SENSOR									Component ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
284105-0106	VENTRAL TANL UNIT FUEL QUANTITY SENSOR									Component ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										
284212-0105	F UND T - FUEL SYSTEM - SHUTOFF VALVE ASSEMBLY									Component ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-24-11										
284212-0106	F UND T - FUEL SYSTEM - SHUTOFF VALVE ASSEMBLY									Component ATA:28
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-24-11										
284401-0101	FWR TK LEVEL, FLOAT TYPE, FUEL SYS, WING SENSOR									Component ATA:28
PN:005-022-001	MOS/MSC		O/C							
SN:UNKNOWN	HRS									
	AFL	0								
PROC. REF: NDT GENERIC										
284401-0102	FWR TK LEVEL, FLOAT TYPE, FUEL SYS, WING SENSOR									Component ATA:28
PN:005-022-001	MOS/MSC		O/C							
SN:UNKNOWN	HRS									
	AFL	0								
PROC. REF: NDT GENERIC										
284600-0101	LEFT LOWER AUX TANK PRIMARY (TANK UNIT) PROBE									Component ATA:28
PN:028-065-003	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										
284600-0102	LEFT LOWER AUX TANK MONITOR (TANK UNIT) PROBE									Component ATA:28
PN:028-065-003	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
284600-0103 RIGHT LOWER AUX TANK PRIMARY (TANK UNIT) PROBE Component ATA:28										
PN:028-065-003	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										
284600-0104 RIGHT LOWER AUX TANK MONITOR (TANK UNIT) PROBE Component ATA:28										
PN:028-065-003	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										
284600-0201 LEFT UPPER AUX TANK PRIMARY (TANK UNIT) PROBE Component ATA:28										
PN:028-065-004	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										
284600-0202 LEFT UPPER AUX TANK MONITOR (TANK UNIT) PROBE Component ATA:28										
PN:028-065-004	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										
284600-0203 RIGHT UPPER AUX TANK PRIMARY (TANK UNIT) PROBE Component ATA:28										
PN:028-065-004	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										
284600-0204 RIGHT UPPER AUX TANK MONITOR (TANK UNIT) PROBE Component ATA:28										
PN:028-065-004	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										
284601-0101 LEFT INBOARD AFT TANK UNIT FUEL QUANTITY SENSOR Component ATA:28										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
284601-0102 LEFT OUTBOARD AFT TANK UNIT FUEL QUANTITY SENSOR Component ATA:28										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										
284601-0103 RIGHT INBOARD AFT TANK UNIT FUEL QUANTITY SENSOR Component ATA:28										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										
284601-0104 RIGHT OUTBOARD AFT TANK UNIT FUEL QUANTITY SENSOR Component ATA:28										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										
284603-0101 LEFT FORWARD FUEL QUANTITY - FORWARD TANK SENSOR Component ATA:28										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										
284603-0102 LEFT AFT FUEL QUANTITY - FORWARD TANK SENSOR Component ATA:28										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										
284603-0103 RIGHT FORWARD FUEL QUANTITY - FORWARD TANK SENSOR Component ATA:28										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										
284603-0104 RIGHT AFT FUEL QUANTITY - FORWARD TANK SENSOR Component ATA:28										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 28 - FUEL											
284700-0101		REAR TK LEVEL, FLOAT TYPE, FUEL SYS, WING SENSOR							Component	ATA:28	
PN:005-022-002	MOS/MSC		27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS		0		TSN 0						
	AFL		0		TSN 0						
PROC. REF: NDT GENERIC											
284701-0101		REAR TK LEVEL, FLOAT TYPE, FUEL SYS, WING SENSOR							Component	ATA:28	
PN:005-022-002	MOS/MSC			O/C							
SN:UNKNOWN	HRS										
	AFL		0								
PROC. REF: NDT GENERIC											
ATA 29 - HYDRAULIC POWER											
29-10-00-280-001-A00 ^S		INSPECT (SPECIAL INSPECTION) HYDRAULIC FLUID - ANALYSIS							Service	ATA:29	
	MOS		29-Jun-23		48 (+15d/-15d)			LOW UTILIZATION			
	HRS		10161.5		2000 (+20/-20)						
	AFL		5401		1000 (+20/-20)						
PROC. REF: AMM 29-10-00											
PKG:5008,6016											
29-10-00-710-001-A00 ^S		OPERATIONALLY CHECK ELECTRIC MOTOR-DRIVEN PUMP INPUT SIGNALS							Service	ATA:29	
	MOS		29-Jun-23		48 (+15d/-15d)			LOW UTILIZATION			
	HRS		10161.5		2000 (+20/-20)						
	AFL		5401		1000 (+20/-20)						
PROC. REF: AMM 29-10-00											
PKG:5008,6016											
29-10-00-790-001-A00 ^S		FUNCTIONALLY CHECK INTERNAL LEAKAGE OF HYDRAULIC POWER SYSTEM							Service	ATA:29	
	MOS		29-Jun-23		96 (+15d/-15d)			LOW UTILIZATION			
	HRS		10161.5		4000 (+20/-20)						
	AFL		5401		2000 (+20/-20)						
PROC. REF: AMM 29-10-00											
PKG:5016,6032											
29-10-01-710-001-A00 ^S		OPERATIONALLY CHECK SHUTOFF VALVE BY MEANS OF THE HYDRAULIC PANEL SWITCH							Service	ATA:29	
	MOS		29-Jun-23		48 (+15d/-15d)			LOW UTILIZATION			
	HRS		10161.5		2000 (+20/-20)						
	AFL		5401		1000 (+20/-20)						
PROC. REF: AMM 29-10-01											
PKG:5008,6016											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 29 - HYDRAULIC POWER										
29-10-04-900-001-A00 DISCARD LH RACK DC ELECTRIC MOTOR DRIVEN HYDRAULIC PUMP EMDP BRUSHES										
PN:971533	MOS	05-Jul-12						SYSTEM		Service ATA:29
SN:MX757308	HRS	5975.6	6000		11975.6		1380			
	AFL	3181								
PROC. REF: AMM 29-10-04										
29-10-04-900-001-A00 DISCARD RH RACK DC ELECTRIC MOTOR DRIVEN HYDRAULIC PUMP EMPD BRUSHES										
PN:971533	MOS	05-Jul-12						SYSTEM		Service ATA:29
SN:MX673042	HRS	5975.6	6000		11975.6		1380			
	AFL	3181								
PROC. REF: AMM 29-10-04										
29-10-08-211-001-A00^S VISUALLY CHECK DIFFERENTIAL PRESSURE INDICATOR FOR RED PINS POPPED OUT.										
	MOS	16-Aug-24	12 (+15d/-15d)					LOW UTILIZATION		Service ATA:29
	HRS	10541.4	500 (+20/-20)							
	AFL	5613								
PROC. REF: AMM 29-10-08										
29-10-10-720-001-A00^S FUNCTIONALLY CHECK RETURN FILTER BY-PASS VALVE										
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		Service ATA:29
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
PROC. REF: AMM 29-10-10										
29-10-13-720-001-A00^S FUNCTIONALLY CHECK PRIORITY VALVE										
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		Service ATA:29
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
PROC. REF: AMM 29-10-13										
29-30-03-720-001-A00^S FUNCTIONALLY CHECK HYDRAULIC FILTERS DIFFERENTIAL PRESSURE INDICATORS										
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		Service ATA:29
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
PROC. REF: AMM 29-10-10										
29-30-05-710-001-A00^S OPERATIONALLY CHECK HYD SYS OVHT MESSAGE										
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		Service ATA:29
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
PROC. REF: AMM 29-30-05										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 29 - HYDRAULIC POWER											
291000-0101		RH RACK GENERATOR ASSY ASSEMBLY								Component	ATA:29
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: NDT GENERIC											
291001-0101		LH ENG SHUTOFF VALVE								Component	ATA:29
PN:2940003-102	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:2130	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 29-10-01											
291001-0102		RH ENG SHUTOFF VALVE								Component	ATA:29
PN:2940003-102	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:2133	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 29-10-01											
291003-0101		LH ENGINE DRIVEN HYDRAULIC PUMP								Component	ATA:29
PN:971808 MOD A	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 29-10-03											
291003-0102		RH ENGINE DRIVEN HYDRAULIC PUMP								Component	ATA:29
PN:971808 MOD B	MOS/MSC	15-Nov-13	O/C	TSN 0							
SN:MX773200	HRS	6756.1	TSN 0								
	AFL	3630	TSN 0								
PROC. REF: AMM 29-10-03											
291004-0201		LH RACK DC ELECTRIC MOTOR DRIVEN HYDRAULIC PUMP								Component	ATA:29
PN:971533	MOS/MSC	05-Jul-12	O/C	TSN 0							
SN:MX757308	HRS	5975.6	TSN 0								
	AFL	3181	TSN 0								
PROC. REF: AMM 29-10-04											
291004-0202		RH RACK DC ELECTRIC MOTOR DRIVEN HYDRAULIC PUMP								Component	ATA:29
PN:971533	MOS/MSC	05-Jul-12	O/C	TSN 0							
SN:MX673042	HRS	5975.6	TSN 0								
	AFL	3181	TSN 0								
PROC. REF: AMM 29-10-04											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 29 - HYDRAULIC POWER										
291005-0101 LH RACK HYDRAULIC, GENERATOR UNIT RESERVOIR Component ATA:29										
PN:368900-1003	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:2057	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: AMM 29-10-05										
291005-0102 RH RACK HYDRAULIC, GENERATOR UNIT RESERVOIR Component ATA:29										
PN:368900-1003	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:2056	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: AMM 29-10-05										
291007-0101 LH RACK FILTER -MANIFOLD, HYDRAULIC SYS ASSEMBLY Component ATA:29										
PN:368100-1007	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:2041	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: AMM 29-10-07										
291007-0102 RH RACK FILTER -MANIFOLD, HYDRAULIC SYS ASSEMBLY Component ATA:29										
PN:368100-1007	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:2038	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: AMM 29-10-07										
291013-0101 W STUB ASSY-PRIORITY, SHUT OFF, HYDRAULIC SYS, LANDING GEAR VALVE Component ATA:29										
PN:2226-0001-401	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:01150	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: AMM 29-10-13										
291014-0101 LH RACK CHECK-TYPE RETAINER HYDRAULIC SYSTEM, POWER UNIT VALVE Component ATA:29										
PN:CV26-63	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:07-0424175	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: NDT GENERIC										
291014-0102 RH RACK CHECK-TYPE RETAINER HYDRAULIC SYSTEM, POWER UNIT VALVE Component ATA:29										
PN:CV26-63	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:07-0424177	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: NDT GENERIC										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 29 - HYDRAULIC POWER										
291015-0101 LEFT CHECK-TYPE RETAINER, ELECTRICAL PUMP, POWER UNIT VALVE Component ATA:29										
PN:2662A-4EE	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										
291015-0102 LEFT CHECK-TYPE RETAINER, ELECTRICAL PUMP, POWER UNIT VALVE Component ATA:29										
PN:2662A-4EE	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										
291015-0103 RIGHT CHECK-TYPE RETAINER, ELECTRICAL PUMP, POWER UNIT VALVE Component ATA:29										
PN:2662A-4EE	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										
291015-0104 RIGHT CHECK-TYPE RETAINER, ELECTRICAL PUMP, POWER UNIT VALVE Component ATA:29										
PN:2662A-4EE	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										
291016-0101 LEFT CHECK-TYPE RETAINER, HYDRAULIC SYSTEM VALVE Component ATA:29										
PN:2662T-6EE	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:07-021317	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										
291016-0102 MID CHECK-TYPE RETAINER, HYDRAULIC SYSTEM VALVE Component ATA:29										
PN:1C5444-1	MOS/MSC	07-Feb-08	O/C	TSN 0						
SN:0757	HRS	557.2		TSN 0						
	AFL	275		TSN 0						
PROC. REF: NDT GENERIC										
291016-0103 RIGHT CHECK-TYPE RETAINER, HYDRAULIC SYSTEM VALVE Component ATA:29										
PN:2662T-6EE	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:06-1025308	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 29 - HYDRAULIC POWER										
291016-0104 LH RACK VALVE, CHECK, -6, CRES VALVE Component ATA:29										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										
291016-0105 RH RACK CRES -6 CHECK VALVE Component ATA:29										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										
291016-0106 FWD FUS CRES -6 CHECK VALVE Component ATA:29										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										
291020-0101 L/H ENG. HYDRAULIC PULSATION DAMPENER Component ATA:29										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 29-10-20										
291020-0102 R/H ENG. HYDRAULIC PULSATION DAMPENER Component ATA:29										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 29-10-20										
291300-0101 FUS WING GENERATOR ASSY GENERATOR Component ATA:29										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										
293000-0101 OVERH P MODULE -HYDRAULIC POWER CONTROL ASSEMBLY Component ATA:29										
PN:145-29739-403	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:0000147594	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 29 - HYDRAULIC POWER											
293002-0201		LH RACK PRESSURE-HYDRAULIC SYS TRANSMITTER							Component	ATA:29	
PN:APTE-24-1000-5000A	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:7218-6-179	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 29-30-02											
293002-0202		RH RACK PRESSURE-HYDRAULIC SYS TRANSMITTER							Component	ATA:29	
PN:APTE-24-1000-5000A	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:7218-6-184	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 29-30-02											
299001-0101		LH RACK ELECTRIC PUMP ASSEMBLY							Component	ATA:29	
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: NDT GENERIC											
299001-0102		RH RACK ELECTRIC PUMP ASSEMBLY							Component	ATA:29	
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: NDT GENERIC											
ATA 30 - ICE AND RAIN PROTECTION											
30-00-00-710-001-A00		OPERATIONALLY CHECK ANTI-ICING SYSTEM MESSAGES							Service	ATA:30	
	MOS	15-Oct-24						SYSTEM			
	HRS	10578.1	100		10678.1		82.5				
	AFL	5634									
PROC. REF: AMM 30-00-00											
30-11-00-720-001-A00 ^S		FUNCTIONALLY CHECK PRESSURE SENSORS OF THE WING THERMAL ANTI-ICING SYSTEM (BENCH TEST). (CMR)							Service	ATA:30	
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	2000 (+20/-20)								
	AFL	5401	1000 (+20/-20)								
PROC. REF: AMM 30-11-00											
PKG:5008,6016											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 30 - ICE AND RAIN PROTECTION										
30-11-05-710-001-A00^S OPERATIONALLY CHECK WING LEAK THERMOSTAT										
	MOS	06-Jul-19	72 (+15d/-15d)					LOW UTILIZATION		Service ATA:30
	HRS	9057.4	3000 (+20/-20)							
	AFL	4853	1500 (+20/-20)							
					PROC. REF: AMM 30-11-05					PKG:5012,6020
30-12-00-710-001-A00^S OPERATIONALLY CHECK ELECTRICAL HARDWARE OF THE HORIZONTAL STABILIZER THERMAL ANTI-ICING SYSTEM.										
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		Service ATA:30
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: AMM 30-12-00					PKG:5008,6016
30-12-00-720-001-A00^S FUNCTIONALLY CHECK PRESSURE SENSORS OF THE HORIZONTAL STABILIZER THERMAL ANTI-ICING SYSTEM (BENCH TEST) (CMR)										
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		Service ATA:30
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: AMM 30-12-00					PKG:5008,6016
30-12-05-710-001-A00^S OPERATIONALLY CHECK HORIZONTAL-STABILIZER LEAK THERMOSTAT										
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		Service ATA:30
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
					PROC. REF: AMM 30-12-05					PKG:5016,6032
30-20-00-220-001-A00^S INSPECT (DETAILED INSPECTION) THERMAL ANTI-ICE (TAI) EXHAUST DUCT FOR CONDITION AND SECURITY OF INSTALLATION.										
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		Service ATA:30
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: AMM 30-20-00					PKG:5008,6016
30-20-01-720-001-A00^S FUNCTIONALLY CHECK ENGINE THERMAL ANTI-ICE (TAI) INTERBULKHEAD ASSEMBLY FOR LEAKAGE										
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		Service ATA:30
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: AMM 30-20-01					PKG:5008,6016
30-21-00-720-001-A00^S FUNCTIONALLY CHECK PRESSURE SENSORS OF THE ENGINE THERMAL ANTI-ICING SYSTEM (BENCH TEST) (CMR)										
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		Service ATA:30
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: AMM 30-21-00					PKG:5008,6016

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 30 - ICE AND RAIN PROTECTION										
30-31-00-710-001-A00^S OPERATIONALLY CHECK PITOT, ANEMOMETRIC STATIC PORT HEATING										
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		Service ATA:30
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
	PROC. REF: AMM 30-31-00, FAR FAR 43 APPENDIX E, FAR FAR 91.411 / 91.217									PKG:5016,6016
30-31-00-710-002-A00^S OPERATIONALLY CHECK PRESSURIZATION STATIC PORT HEATING										
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		Service ATA:30
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
	PROC. REF: AMM 30-31-00									PKG:5016,6016
30-31-08-710-001-A00^S OPERATIONALLY CHECK PITOT LINES HEATER NOTE: IF INSTALLED										
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		Service ATA:30
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
	PROC. REF: AMM 30-31-03									PKG:5016,6032
30-32-00-710-001-A00^S OPERATIONALLY CHECK AOA SENSOR HEATING										
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		Service ATA:30
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
	PROC. REF: AMM 30-32-00									PKG:5016,6016
30-33-00-710-001-A00^S OPERATIONALLY CHECK TAT SENSOR HEATING										
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		Service ATA:30
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
	PROC. REF: AMM 30-33-00									PKG:5016,6016
30-41-00-710-001-A00 OPERATIONALLY CHECK WINDSHIELD WIPER SYSTEM										
	MOS/MS	15-Aug-13	O/C							Service ATA:30
	HRS	6643.4								
	AFL	3572								
	PROC. REF: AMM 30-41-00									
30-42-00-710-001-A00^S OPERATIONALLY CHECK WINDSHIELD HEATING										
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		Service ATA:30
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
	PROC. REF: AMM 30-42-00									PKG:5008,6016

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 30 - ICE AND RAIN PROTECTION										
30-43-01-211-001-A00^S VISUALLY CHECK RAIN REPELLENT COATING (RRC) Service ATA:30										
	MOS	29-Jun-23	24 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	1000 (+20/-20)							
	AFL	5401								
PROC. REF: AMM 30-41-04										PKG:5004
300000-0101 OVERH P ELECTRICAL SYS, ICE PROTECTION MODULE Component ATA:30										
PN:145-31656-409	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:0000146548	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										
301100-0101 W STUB ELECTRONIC, ANTI ICE SYS, WING PRESSURE SWITCH Component ATA:30										
PN:APS-8-1000	MOS/MSC	10-Nov-11	O/C	TSN 0						
SN:7902-3-54	HRS	5047.1		TSN 0						
	AFL	2682		TSN 0						
PROC. REF: AMM 30-11-03										
301100-0301 LH WING WING ANTI ICE PICCOLO BURST MONITORING PRESSURE TRANSDUCER Component ATA:30										
PN:APS-6-1000	MOS/MSC	13-Jan-14	O/C	TSN 0						
SN:8094-7-1100	HRS	6811.6		TSN 0						
	AFL	3661		TSN 0						
PROC. REF: AMM 30-11-12										
301100-0302 RH WING WING ANTI ICE PICCOLO BURST MONITORING PRESSURE TRANSDUCER Component ATA:30										
PN:APS-6-1000	MOS/MSC	10-Nov-11	O/C	TSN 0						
SN:7720-7-312	HRS	5047.1		TSN 0						
	AFL	2682		TSN 0						
PROC. REF: AMM 30-11-12										
301200-0101 AIRFRAME ANTI ICE SYSTEM OVERPRESSURE SWITCH Component ATA:30										
PN:12949-4	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:2216	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 30-11-03										
301200-0102 LH WING AIRFRAME ANTI ICE SYSTEM OVERPRESSURE SWITCH Component ATA:30										
PN:12949-4	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:2221	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 30-11-03										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 30 - ICE AND RAIN PROTECTION										
301200-0103 RH WING AIRFRAME ANTI ICE SYSTEM OVERPRESSURE SWITCH Component ATA:30										
PN:12949-4	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:2227	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 30-11-03										
301200-0201 PRESSURE-ELECTRONIC, ANTI ICE SYS, WING/STABILIZER HORI SWITCH Component ATA:30										
PN:APS-7-1000	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 30-12-03										
301200-0202 LEFT PRESSURE-ELECTRONIC, ANTI ICE SYS, WING/STABILIZER HORI SWITCH Component ATA:30										
PN:APS-7-1000	MOS/MSC	10-Nov-11	O/C	TSN 0						
SN:7816-7-295	HRS	5047.1		TSN 0						
	AFL	2682		TSN 0						
PROC. REF: AMM 30-12-03										
301200-0203 PRESSURE-ELECTRONIC, ANTI ICE SYS, WING/STABILIZER HORI SWITCH Component ATA:30										
PN:APS-7-1000	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 30-12-03										
301200-0204 RIGHT PRESSURE-ELECTRONIC, ANTI ICE SYS, WING/STABILIZER HORI SWITCH Component ATA:30										
PN:APS-7-1000	MOS/MSC	10-Nov-11	O/C	TSN 0						
SN:7816-7-210	HRS	5047.1		TSN 0						
	AFL	2682		TSN 0						
PROC. REF: AMM 30-12-03										
301200-0301 REAR ANTI ICE, STABILIZER VALVE Component ATA:30										
PN:1000649-2	MOS/MSC	11-Dec-23	O/C	TSO 0						
SN:9912325	HRS	10328.7		TSO 0						
	AFL	5502		TSO 0						
PROC. REF: AMM 30-12-01										
301200-0401 TAIL HORIZONTAL STABILIZER PICCOLO BURST PRESSURE SWITCH Component ATA:30										
PN:83536-2	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:0997	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 30-12-06										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 30 - ICE AND RAIN PROTECTION										
301300-0101 LH WING SHUTOFF/REGULATOR-AIR PRESSURE, ANTI ICE SYS, AIRFOILS VALVE Component ATA:30										
PN:1000649-1	MOS/MSC	07-Apr-19	O/C	TSO 9						
SN:9910164	HRS	8973.5		TSN 4288, TSO 0						
	AFL	4805		TSO 0						
PROC. REF: AMM 30-11-01										
301300-0102 RH WING SHUTOFF/REGULATOR-AIR PRESSURE, ANTI ICE SYS, AIRFOILS VALVE Component ATA:30										
PN:1000649-1	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:2007040480	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 30-11-01										
302000-0101 LH ENG PRESSURE-ELECTRONIC, ANTI ICE SYS TRANSDUCER Component ATA:30										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 30-21-06										
302000-0102 RH ENG PRESSURE-ELECTRONIC, ANTI ICE SYS TRANSDUCER Component ATA:30										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 30-21-06										
302000-0201 LH ENG ANTI ICE, AIR BLEED SYS VALVE Component ATA:30										
PN:C146009-4	MOS/MSC	18-Jul-09	O/C	TSR 0						
SN:2740	HRS	2297.3		TSR 0						
	AFL	1211		TSR 0						
PROC. REF: AMM 30-21-01										
302000-0202 RH ENG ANTI ICE, AIR BLEED SYS VALVE Component ATA:30										
PN:C146009-4	MOS/MSC	01-Apr-11	O/C							
SN:2666	HRS	4453.2								
	AFL	2335								
PROC. REF: AMM 30-21-01										
304201-0101 WINDSHIELD TEMPERATURE CONTROLLER Component ATA:30										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 30-42-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 30 - ICE AND RAIN PROTECTION										
304201-0102 WINDSHIELD TEMPERATURE CONTROLLER Component ATA:30										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 30-42-01										
308000-0201 LH CSL ICE-FRONT FUSELAGE DETECTOR Component ATA:30										
PN:0871HT3-1A	MOS/MSC	04-Mar-15	O/C	TSN 28						
SN:02473	HRS	7330.8		TSN 899.7						
	AFL	3928		TSN 465						
PROC. REF: AMM 30-80-01										
308000-0202 RH CSL ICE-FRONT FUSELAGE DETECTOR Component ATA:30										
PN:0871HT3	MOS/MSC	16-Aug-24	O/C							
SN:00939	HRS	10541.4								
	AFL	5613								
PROC. REF: AMM 30-80-01										
308002-0101 REAR PROCESSOR-DETECTION, CLEAR ICE, REAR FUSELAGE UNIT Component ATA:30										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 30-80-02										
308003-0101 LH WING ICE DETECTION SENSOR Component ATA:30										
PN:00870-0020-0002	MOS/MSC	01-Mar-17	O/C							
SN:2502	HRS	8086								
	AFL	4338								
PROC. REF: AMM 30-80-03										
308003-0102 RH WING ICE DETECTION SENSOR Component ATA:30										
PN:00870-0020-0002	MOS/MSC	01-Mar-17	O/C							
SN:2522	HRS	8086								
	AFL	4338								
PROC. REF: AMM 30-80-03										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 30 - ICE AND RAIN PROTECTION											
308003-0201		RIGHT WING CABL 03, W603 CABLE								Component	ATA:30
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: NDT GENERIC											
308003-0202		LEFT WING CABL 03, W603 CABLE								Component	ATA:30
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: NDT GENERIC											
ATA 31 - INDICATING/RECORDING SYSTEMS											
31-21-00-710-001-A00		OPERATIONALLY CHECK PILOT DIGITAL CLOCK INFORMATION NOTE: CHECK TOGETHER WITH TASK 31-31-00-720-001-A00.								Service	ATA:31
	MOS	14-Jul-22	48 (+30d/-30d)	14-Jul-26	13-Aug-26	606 d (+30)	SYSTEM				
	HRS	9904.2	4000	13904.2			3308.6				
	AFL	5268									
PROC. REF: AMM 31-21-00											
31-31-00-720-001-A00		FUNCTIONALLY CHECK REAR FLIGHT DATA SSFDR ELECTRONIC SYSTEM RECORDER								Service	ATA:31
PN:980-4700-042	MOS	11-Jan-21	48 (+30d/-30d)	11-Jan-25	10-Feb-25	57 d (+30)	SYSTEM				
SN:SSFDR-13164	HRS	9507.9	4000	13507.9			2912.3				
	AFL	5060									
PROC. REF: AMM 31-31-00, AMM 31-31-00, AMM 31-31-00, AMM 31-31-00											
31-31-02-960-001-A00		DISCARD FDR UNDERWATER LOCATOR BEACON (ULB) BATTERY NOTE: ULB BATTERY CHANGE IN ACCORDANCE WITH MANUFACTURER'S DATAPLATE EXPIRATION DATE								Service	ATA:31
PN:DK120	MOS/MSC	18-Jul-24	DUE	31-Oct-29 (M)			1811 d	SYSTEM			
SN:NT61967	HRS	10519.2									
	AFL	5604									
PROC. REF: AMM 31-31-02											
311300-0101		LH LIGHT PANEL MODULE								Component	ATA:31
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: NDT GENERIC											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 31 - INDICATING/RECORDING SYSTEMS											
311300-0102		RH LIGHT PANEL MODULE								Component	ATA:31
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: NDT GENERIC											
311700-0101		MODULE MAINTENANCE PANEL ASSEMBLY								Component	ATA:31
PN:135-53624-405	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:0000146486	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 31-17-01											
311803-0706 ^U		NO. 6 CABIN SEAT AUDIO CONTROLLER								Component	ATA:31
PN:990-6107-162	MOS/MSC	29-Dec-17	O/C	TSR 0							
SN:06120034180	HRS	8436.1		TSR 0							
	AFL	4528		TSR 0							
311803-0708 ^U		NO. 8 CABIN SEAT AUDIO CONTROLLER								Component	ATA:31
PN:990-6107-163	MOS/MSC	29-Dec-17	O/C	TSR 0							
SN:06120034179	HRS	8436.1		TSR 0							
	AFL	4528		TSR 0							
312102-0201		PILOT DIGITAL 2 POL CLOCK								Component	ATA:31
PN:APE4190-040	MOS/MSC	19-Sep-13	O/C	TSN 0							
SN:163	HRS	6680.2		TSN 0							
	AFL	3597		TSN 0							
PROC. REF: AMM 31-21-01											
312102-0202		COPILOT DIGITAL 2 POL CLOCK								Component	ATA:31
PN:APE4190-040	MOS/MSC	19-Sep-13	O/C	TSN 0							
SN:164	HRS	6680.2		TSN 0							
	AFL	3597		TSN 0							
PROC. REF: AMM 31-21-01											
313101-0101		REAR FLIGHT DATA SSFDR ELECTRONIC SYSTEM RECORDER								Component	ATA:31
PN:980-4700-042	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:SSFDR-13164	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 31-31-01											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 31 - INDICATING/RECORDING SYSTEMS										
313101-0201 FDR UNDERWATER LOCATOR BEACON Component ATA:31										
PN:DK120/90	MOS/MSC	19-Aug-24	O/C	TSN 0						
SN:NT61967	HRS	10541.4		TSN 0						
	AFL	5613		TSN 0						
PROC. REF: AMM 31-31-02										
313101-0301 FLIGHT DATA RECORDER (FDR) UNDERWATER LOCATOR BEACON (ULB) BATTERY Component ATA:31										
PN:DK120	MOS/MSC	18-Jul-24	H/T	TSN 0						
SN:NT61967	HRS	10519.2		TSN 0						
	AFL	5604		TSN 0						
PROC. REF: NDT GENERIC										
313102-0101 REAR TRI AXIAL ACCELEROMETER Component ATA:31										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-31-03										
313106-0101 LH WING ROTARY-VARIABLE INDUCTIVE, 28VDC/50MA TRANSDUCER Component ATA:31										
PN:D370535	MOS/MSC	19-Jan-21	O/C							
SN:02J00161	HRS	9508.9								
	AFL	5061								
PROC. REF: AMM 31-31-06										
313106-0102 RH WING ROTARY-VARIABLE INDUCTIVE, 28VDC/50MA TRANSDUCER Component ATA:31										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-31-06										
313106-0103 ROTARY-VARIABLE INDUCTIVE, 28VDC/50MA TRANSDUCER Component ATA:31										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-31-06										
313106-0104 ROTARY-VARIABLE INDUCTIVE, 28VDC/50MA TRANSDUCER Component ATA:31										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-31-06										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 31 - INDICATING/RECORDING SYSTEMS										
313106-0105 TAIL ROTARY-VARIABLE INDUCTIVE, 28VDC/50MA TRANSDUCER Component ATA:31										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-31-06										
313107-0101 REAR FUS AFDAU - AUXILIARY FLIGHT DATA ACQUISITION UNIT Component ATA:31										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-31-07										
313108-0101 C FLOOR CONVERTER-ANALOGIC/DIGITAL,FLIGHT DATA RECORDING SYS UNIT Component ATA:31										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-31-08										
314101-0101 REAR I DATA ACQUISITION DA-800 PH, 9 UNIT Component ATA:31										
PN:7013348-948	MOS/MSC	30-Dec-22	O/C	TSN 184						
SN:07026460	HRS	10063.9		TSN 10063.9						
	AFL	5344		TSN 5344						
PROC. REF: AMM 31-41-01										
314101-0102 C FLOOR DATA ACQUISITION DA-800 PH, 10 UNIT Component ATA:31										
PN:7013348-948	MOS/MSC	30-Dec-22	O/C	TSN 184						
SN:06096358	HRS	10063.9		TSN 10063.9						
	AFL	5344		TSN 5344						
PROC. REF: AMM 31-41-01										
314102-0201 CONTROL-EICAS SYS,MAIN PANEL Component ATA:31										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-41-02										
314104-0101 CREW CAB CONTROL,EGPWS,NAVIGATION SYS,CTL CONSOLE,COCKPIT MODULE Component ATA:31										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 31 - INDICATING/RECORDING SYSTEMS										
314104-0102 CSL CENT MODULE MODULE Component ATA:31										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										
314201-0101 INTEGRATED COMPUTER IC-600 WITH AP CARD Component ATA:31										
PN:7017000-0101	MOS/MSC	18-Sep-24	O/C							
SN:00093656	HRS	10556								
	AFL	5619								
PROC. REF: AMM 31-42-01										
314201-0102 INTEGRATED COMPUTER IC-600 WITHOUT AP CARD Component ATA:31										
PN:7017000-83414	MOS/MSC	19-Aug-15	O/C	TSN 96						
SN:06117836	HRS	7460.3		TSN 7460.3						
	AFL	3992		TSN 3992						
PROC. REF: AMM 31-42-01										
314202-0101 LEFT CONFIGURATION-IC-600 INTEGRATED COMPUTER, COCKPIT MODULE Component ATA:31										
PN:7025973-03000	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:07024539	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-42-02										
314202-0102 RIGHT CONFIGURATION-IC-600 INTEGRATED COMPUTER, COCKPIT MODULE Component ATA:31										
PN:7025973-03000	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:07014519	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-42-02										
314301-0101 MHE, PAX ENTERTAINMENT SYSTEM, BOX ASSY CONTROLLER Component ATA:31										
PN:990-6800-004	MOS/MSC	01-Sep-17	O/C							
SN:07100044474	HRS	8284.1								
	AFL	4446								
PROC. REF: AMM 31-43-01										
314302-0101 MHC25R, PAX CABIN CONTROLLER BOX ASSEMBLY Component ATA:31										
PN:990-6812-001	MOS/MSC	23-May-14	O/C							
SN:05100022475	HRS	7003.7								
	AFL	3758								
PROC. REF: AMM 31-43-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 31 - INDICATING/RECORDING SYSTEMS											
314303-0101		LAPTOP INETRFACE, PAX MHE AIRSHOW SYS, CONTROL ASSY PANEL							Component	ATA:31	
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 31-43-01											
314304-0101		MHR/IRS AIRSHOW,PAX ENTERTAINMENT CABINET RECEIVER							Component	ATA:31	
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 31-43-04											
314305-0101		MHR INFRARED SENSOR CONTROL UNIT							Component	ATA:31	
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: NDT GENERIC, AMM 23-35-17											
314306-0101		MHI INTERFACE, ENT CABINET, CONTROL UNIT							Component	ATA:31	
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 31-43-06											
315101-0101		NOSE ALARM-AUDIO,ELECTRONIC EQUIPAMENT, FWD FUSLG UNIT							Component	ATA:31	
PN:80-0694-2-8	MOS/MSC	19-Aug-16	O/C								
SN:2190	HRS	7460.3									
	AFL	3992									
PROC. REF: AMM 31-51-01											
315102-0101		CREW CAB MODULE -CONSOLE,MAIN PANEL,COCKPIT ASSEMBLY							Component	ATA:31	
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: NDT GENERIC											
316101-0101		C FLOOR BOX -DIODES,AVIONICS POWER SUPPLY,FLOOR,COCKPIT ASSEMBLY							Component	ATA:31	
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 31-61-01											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
32-10-00-210-801-L00 ^S GENERAL VISUAL INSPECTION EXTERNALLY INSPECT THE MAIN LANDING GEAR COMPONENTS- TRAILING ARM - MLG (SSI 32-10-03).										
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		Service ATA:32
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
					PROC. REF: NDT 32-10-00					PKG:5016,6016
32-10-00-210-C01-L00 ^S GENERAL VISUAL INSPECTION EXTERNALLY INSPECT THE MAIN LANDING GEAR COMPONENTS- LEG STRUCTURE, EQUIPPED (LEFT) - MLG (SSI 32-10-01).- LEG STRUCTURE, EQUIPPED (RIGHT) - MLG (SSI 32-10-02).- UPPER SECONDARY BRACE STRUT ASSY - MLG (SSI 32-10-09).- LOWER SECONDARY BRACE STRUT ASSY - MLG (SSI 32-10-10).										
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		Service ATA:32
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: CPM 32-10-00					PKG:5008,6016
32-10-00-210-C02-L00 ^S GENERAL VISUAL INSPECTION EXTERNALLY INSPECT THE MAIN LANDING GEAR COMPONENTS- SHOCK ABSORBER PISTON TUBE ASSY - MLG (SSI 32-10-05).-SHOCK ABSORBER CYLINDER ASSY - MLG (SSI 32-10-06).										
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		Service ATA:32
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: CPM 32-10-00					PKG:5008,6016
32-10-00-220-801-L00 ^S DETAILED INSPECTION (EXTERNAL) OF THE MAIN LANDING GEAR COMPONENTS- WHEEL AXLE - MLG (SSI 32-10-04).										
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		Service ATA:32
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: NDT 32-10-00					PKG:5008
32-10-01-900-001-A00 RESTORE (OVERHAUL) LH MLG LEG OLEO STRUT ASSEMBLY										
PN:2309-3100-405	MOS	01-Jul-19	144 (+60d/-60d)		01-Jul-31	30-Aug-31	2419 d (+60)	SYSTEM		Service ATA:32
SN:00080	HRS	9057.4								
	AFL	4853								
					PROC. REF: AMM 32-10-01					
32-10-01-900-001-A00 RESTORE (OVERHAUL) RH MLG LEG OLEO STRUT ASSEMBLY										
PN:2309-3100-406	MOS	01-Jul-19	144 (+60d/-60d)		01-Jul-31	30-Aug-31	2419 d (+60)	SYSTEM		Service ATA:32
SN:00090	HRS	9057.4								
	AFL	4853								
					PROC. REF: AMM 32-10-01					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
32-10-01-900-002-A00 RESTORE (OVERHAUL) LH MLG TRAILING ARM ASSY Service ATA:32										
	MOS	01-Jul-19	144 (+60d/-60d)		01-Jul-31	30-Aug-31	2419 d (+60)	SYSTEM		
	HRS	9057.4								
	AFL	4853								
PROC. REF: AMM 32-10-01										
32-10-01-900-002-A00 RESTORE (OVERHAUL) RH MLG TRAILING ARM ASSY Service ATA:32										
	MOS	01-Jul-19	144 (+60d/-60d)		01-Jul-31	30-Aug-31	2419 d (+60)	SYSTEM		
	HRS	9057.4								
	AFL	4853								
PROC. REF: AMM 32-10-01										
32-10-02-610-001-A00 ^S SERVICE (REPLENISH) MLG SHOCK ABSORBER Service ATA:32										
	MOS	16-Aug-24	12 (+15d/-15d)					LOW UTILIZATION		
	HRS	10541.4	500 (+20/-20)							
	AFL	5613								
PROC. REF: AMM 32-10-02										
32-10-02-900-001-A00 RESTORE (OVERHAUL) LH MLG SHOCK ABSORBER ASSEMBLY Service ATA:32										
PN:2309-2005-007	MOS	01-Jul-19	144 (+60d/-60d)		01-Jul-31	30-Aug-31	2419 d (+60)	SYSTEM		
SN:10041	HRS	9057.4								
	AFL	4853								
PROC. REF: AMM 32-10-02										
32-10-02-900-001-A00 RESTORE (OVERHAUL) RH MLG SHOCK ABSORBER ASSEMBLY Service ATA:32										
PN:2309-2005-007	MOS	01-Jul-19	144 (+60d/-60d)		01-Jul-31	30-Aug-31	2419 d (+60)	SYSTEM		
SN:10004	HRS	9057.4								
	AFL	4853								
PROC. REF: AMM 32-10-02										
32-10-03-900-001-A00 RESTORE (OVERHAUL) LH MLG UPPER MAIN SIDE STRUT ASSEMBLY Service ATA:32										
PN:2309-2524-001	MOS	01-Jul-19	144 (+60d/-60d)		01-Jul-31	30-Aug-31	2419 d (+60)	SYSTEM		
SN:1143026/010	HRS	9057.4								
	AFL	4853								
PROC. REF: AMM 32-10-03										
32-10-03-900-001-A00 RESTORE (OVERHAUL) RH MLG UPPER MAIN SIDE STRUT ASSEMBLY Service ATA:32										
PN:2309-2524-001	MOS	01-Jul-19	144 (+60d/-60d)		01-Jul-31	30-Aug-31	2419 d (+60)	SYSTEM		
SN:1138062/005	HRS	9057.4								
	AFL	4853								
PROC. REF: AMM 32-10-03										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
32-10-03-900-002-A00 RESTORE (OVERHAUL) LH MAIN SIDE ASSY (MLG) STRUT LOWER										
PN:2309-3500-503	MOS	01-Jul-19	144 (+60d/-60d)		01-Jul-31	30-Aug-31	2419 d (+60)	SYSTEM		Service ATA:32
SN:01528	HRS	9057.4								
	AFL	4853								
PROC. REF: AMM 32-10-03										
32-10-03-900-002-A00 RESTORE (OVERHAUL) RH MAIN SIDE ASSY (MLG) STRUT LOWER										
PN:2309-3500-503	MOS	01-Jul-19	144 (+60d/-60d)		01-Jul-31	30-Aug-31	2419 d (+60)	SYSTEM		Service ATA:32
SN:01491	HRS	9057.4								
	AFL	4853								
PROC. REF: AMM 32-10-03										
32-10-04-900-001-A00 RESTORE (OVERHAUL) LH MLG UPPER SECONDARY SIDE STRUT ASSEMBLY										
PN:2309-2611-003	MOS	01-Jul-19	144 (+60d/-60d)		01-Jul-31	30-Aug-31	2419 d (+60)	SYSTEM		Service ATA:32
SN:1156805/007	HRS	9057.4								
	AFL	4853								
PROC. REF: AMM 32-10-04										
32-10-04-900-001-A00 RESTORE (OVERHAUL) RH MLG UPPER SECONDARY SIDE STRUT ASSEMBLY										
PN:2309-2611-003	MOS	01-Jul-19	144 (+60d/-60d)		01-Jul-31	30-Aug-31	2419 d (+60)	SYSTEM		Service ATA:32
SN:1137253/001	HRS	9057.4								
	AFL	4853								
PROC. REF: AMM 32-10-04										
32-10-04-900-002-A00 RESTORE (OVERHAUL) LH MLG SECONDARY SIDE STRUT (LOWER) ASSEMBLY										
PN:2309-2624-001	MOS	01-Jul-19	144 (+60d/-60d)		01-Jul-31	30-Aug-31	2419 d (+60)	SYSTEM		Service ATA:32
SN:1162870/012	HRS	9057.4								
	AFL	4853								
PROC. REF: AMM 32-10-04										
32-10-04-900-002-A00 RESTORE (OVERHAUL) RH MLG SECONDARY SIDE STRUT (LOWER) ASSEMBLY										
PN:2309-2624-001	MOS	01-Jul-19	144 (+60d/-60d)		01-Jul-31	30-Aug-31	2419 d (+60)	SYSTEM		Service ATA:32
SN:1139184/009	HRS	9057.4								
	AFL	4853								
PROC. REF: AMM 32-10-04										
32-10-05-900-002-A00 RESTORE (OVERHAUL) LH MLG SECONDARY SIDE STRUT NO.1 SPRING CARTRIDGE ASSY										
	MOS	01-Jul-19	144 (+60d/-60d)		01-Jul-31	30-Aug-31	2419 d (+60)	SYSTEM		Service ATA:32
	HRS	9057.4								
	AFL	4853								
PROC. REF: AMM 32-10-05										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 32 - LANDING GEAR											
32-10-05-900-002-A00		RESTORE (OVERHAUL)	LH MLG SECONDARY SIDE STRUT NO.2 SPRING CARTRIDGE ASSY						Service	ATA:32	
	MOS	01-Jul-19	144 (+60d/-60d)		01-Jul-31 (M)	30-Aug-31	2419 d (+60)	SYSTEM			
	HRS	9057.4									
	AFL	4853									
					PROC. REF: AMM 32-10-05						
32-10-05-900-002-A00		RESTORE (OVERHAUL)	RH MLG SECONDARY SIDE STRUT NO.1 SPRING CARTRIDGE ASSY						Service	ATA:32	
	MOS	01-Jul-19	144 (+60d/-60d)		01-Jul-31	30-Aug-31	2419 d (+60)	SYSTEM			
	HRS	9057.4									
	AFL	4853									
					PROC. REF: AMM 32-10-05						
32-10-05-900-002-A00		RESTORE (OVERHAUL)	RH MLG SECONDARY SIDE STRUT NO.2 SPRING CARTRIDGE ASSY						Service	ATA:32	
	MOS	01-Jul-19	144 (+60d/-60d)		01-Jul-31 (M)	30-Aug-31	2419 d (+60)	SYSTEM			
	HRS	9057.4									
	AFL	4853									
					PROC. REF: AMM 32-10-05						
32-20-00-210-801-L00 ^S		GENERAL VISUAL INSPECTION EXTERNALLY INSPECT THE NOSE LANDING GEAR COMPONENTS - STRUT (MAIN FITTING) - NLG (SSI 32-20-12).- LOWER LOCKING STRUT (SSI 32-20-16).- UPPER DRAG STAY - NLG (SSI 32-20-13).- UPPER LOCKING STAY - NLG (SSI 32-20-15).- TORQUE LINKS - NLG (SSI 32-20-17).							Service	ATA:32	
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	2000 (+20/-20)								
	AFL	5401	1000 (+20/-20)								
					PROC. REF: NDT 32-20-00					PKG:5008,6016	
32-20-00-210-802-L00 ^S		GENERAL VISUAL INSPECTION (EXTERNAL) INSPECT THE NOSE LANDING GEAR COMPONENTS- SLIDING TUBE - NLG (SSI 32-20-18).							Service	ATA:32	
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	2000 (+20/-20)								
	AFL	5401	1000 (+20/-20)								
					PROC. REF: NDT 32-20-00					PKG:5008	
32-20-00-210-C01-L00 ^S		GENERAL VISUAL INSPECTION (EXTERNAL) INSPECT THE NOSE LANDING GEAR COMPONENTS- LOWER DRAG STAY - NLG (SSI 32-20-14).							Service	ATA:32	
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	2000 (+20/-20)								
	AFL	5401	1000 (+20/-20)								
					PROC. REF: CPM 32-20-00					PKG:5008,6016	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
32-20-00-220-801-L00^S DETAILED INSPECTION (EXTERNAL) INSPECT THE NOSE LANDING GEAR COMPONENTS- WHEEL AXLE (SSI 32-20-19).										
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		Service ATA:32
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: NDT 32-20-00					PKG:5008
32-20-01-610-001-A00^S SERVICE (REPLENISH) NLG SHOCK ABSORBER										
	MOS	16-Aug-24	12 (+15d/-15d)					LOW UTILIZATION		Service ATA:32
	HRS	10541.4	500 (+20/-20)							
	AFL	5613								
					PROC. REF: AMM 32-20-01					PKG:5002
32-20-01-720-001-A00 FUNCTIONALLY CHECK NLG LEG CENTERING CAM PLAY NOTE: PERFORM AT THE TIME OF NLG SLIDING TUBE ASSY RESTORATION										
	MOS/MS	01-Jul-19	O/C							Service ATA:32
	HRS	9057.4								
	AFL	4853								
					PROC. REF: AMM 32-20-01					
32-20-01-900-001-A00 RESTORE (OVERHAUL) NOSE LANDING GEAR (NLG) MAIN FITTING ASSY										
	MOS	01-Jul-19	144 (+60d/-60d)		01-Jul-31	30-Aug-31	2419 d (+60)	SYSTEM		Service ATA:32
	HRS	9057.4								
	AFL	4853								
					PROC. REF: AMM 32-20-01					
32-20-01-900-002-A00 RESTORE (OVERHAUL) NLG LEG STRUT SLIDING TUBE										
PN:2233-0201	MOS	01-Jul-19	144 (+60d/-60d)		01-Jul-31	30-Aug-31	2419 d (+60)	SYSTEM		Service ATA:32
SN:1379	HRS	9057.4								
	AFL	4853								
					PROC. REF: AMM 32-20-01					
32-20-01-900-003-A00 RESTORE (OVERHAUL) NLG LEG STRUT STEERING CUFF										
PN:1170-2301	MOS	01-Jul-19	144 (+60d/-60d)		01-Jul-31	30-Aug-31	2419 d (+60)	SYSTEM		Service ATA:32
SN:L1578	HRS	9057.4								
	AFL	4853								
					PROC. REF: AMM 32-20-01					
32-20-01-900-004-A00 RESTORE (OVERHAUL) NO.1 NLG LEG STRUT TORQUE LINK										
PN:1170-0301	MOS	01-Jul-19	144 (+60d/-60d)		01-Jul-31	30-Aug-31	2419 d (+60)	SYSTEM		Service ATA:32
SN:L2583	HRS	9057.4								
	AFL	4853								
					PROC. REF: AMM 32-20-01					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of:
11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
32-20-01-900-004-A00 RESTORE (OVERHAUL) NO.2 NLG LEG STRUT TORQUE LINK										
PN:1170-0301	MOS	01-Jul-19	144 (+60d/-60d)		01-Jul-31	30-Aug-31	2419 d (+60)	SYSTEM		Service ATA:32
SN:L2584	HRS	9057.4								
	AFL	4853								
PROC. REF: AMM 32-20-01										
32-20-02-900-001-A00 RESTORE (OVERHAUL) TOP NLG MAIN DRAG STRUT STAY										
PN:1172A0600-01	MOS	01-Jul-19	144 (+60d/-60d)		01-Jul-31	30-Aug-31	2419 d (+60)	SYSTEM		Service ATA:32
SN:HM1431	HRS	9057.4								
	AFL	4853								
PROC. REF: AMM 32-20-02										
32-20-02-900-002-A00 RESTORE (OVERHAUL) BOTTOM NLG MAIN DRAG STRUT STAY										
PN:1172A0200-01	MOS	01-Jul-19	144 (+60d/-60d)		01-Jul-31	30-Aug-31	2419 d (+60)	SYSTEM		Service ATA:32
SN:HM39	HRS	9057.4								
	AFL	4853								
PROC. REF: AMM 32-20-02										
32-20-03-900-001-A00 RESTORE (OVERHAUL) NLG AUXILIARY DRAG STRUT (UPPER) ASSEMBLY										
PN:1173A0200-01	MOS	01-Jul-19	144 (+60d/-60d)		01-Jul-31	30-Aug-31	2419 d (+60)	SYSTEM		Service ATA:32
SN:HM1191	HRS	9057.4								
	AFL	4853								
PROC. REF: AMM 32-20-03										
32-20-03-900-002-A00 RESTORE (OVERHAUL) NLG AUXILIARY DRAG STRUT (LOWER) ASSEMBLY										
PN:1173A0100-02	MOS	01-Jul-19	144 (+60d/-60d)		01-Jul-31	30-Aug-31	2419 d (+60)	SYSTEM		Service ATA:32
SN:L1327	HRS	9057.4								
	AFL	4853								
PROC. REF: AMM 32-20-03										
32-20-04-900-002-A00 RESTORE (OVERHAUL) NLG DOWN LOCK SPRING ASSY										
	MOS	01-Jul-19	144 (+60d/-60d)		01-Jul-31	30-Aug-31	2419 d (+60)	SYSTEM		Service ATA:32
	HRS	9057.4								
	AFL	4853								
PROC. REF: AMM 32-20-04										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 32 - LANDING GEAR											
32-32-00-710-001-A00 ^S		OPERATIONALLY CHECK LANDING GEAR EXTENSION AND RETRACTION (ELECTRICAL) INDICATION AND DOWNLOCK RELAYS BY CHANNELS A AND B (WITH JACKS)							Service	ATA:32	
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	2000 (+20/-20)								
	AFL	5401	1000 (+20/-20)								
PROC. REF: AMM 32-32-00										PKG:5008,6016	
32-32-02-710-001-A00 ^S		OPERATIONALLY CHECK SOLENOID AND DOWLOCK RELEASE BUTTON OF THE LANDING GEAR CONTROL LEVER.							Service	ATA:32	
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	4000 (+20/-20)								
	AFL	5401	2000 (+20/-20)								
PROC. REF: AMM 32-32-02										PKG:5016,6032	
32-34-00-640-001-A00 ^S		LUBRICATE LANDING GEAR (MLG & NLG) AND STEERING SYSTEM							Service	ATA:32	
	MOS	16-Aug-24	12 (+15d/-15d)					LOW UTILIZATION			
	HRS	10541.4	500 (+20/-20)								
	AFL	5613									
PROC. REF: AMM 32-34-00										PKG:5002	
32-34-00-710-001-A00 ^S		OPERATIONALLY CHECK LANDING GEAR EMERGENCY EXTENSION (OVERRIDE SWITCH)							Service	ATA:32	
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	2000 (+20/-20)								
	AFL	5401	1000 (+20/-20)								
PROC. REF: AMM 32-34-00										PKG:5008,6016	
32-34-00-720-001-A01 ^S		FUNCTIONALLY CHECK LANDING GEAR EMERGENCY EXTENSION							Service	ATA:32	
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	2000 (+20/-20)								
	AFL	5401	1000 (+20/-20)								
PROC. REF: AMM 32-34-00										PKG:5008,6016	
32-34-03-720-001-A00 ^S		FUNCTIONALLY CHECK CONDITION AND TENSION OF FREE-FALL CONTROL CABLES							Service	ATA:32	
	MOS	06-Jul-19	72 (+15d/-15d)					LOW UTILIZATION			
	HRS	9057.4	3000 (+20/-20)								
	AFL	4853	1500 (+20/-20)								
PROC. REF: AMM 32-34-03										PKG:5012,6020	
32-41-00-720-001-A00 ^S		FUNCTIONALLY CHECK MAIN BRAKE SYSTEM							Service	ATA:32	
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	2000 (+20/-20)								
	AFL	5401	1000 (+20/-20)								
PROC. REF: AMM 32-41-00										PKG:5008,6016	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
32-41-01-710-001-A00 ^S	OPERATIONALLY CHECK BRAKE-PEDAL POSITION TRANSDUCER									Service ATA:32
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
					PROC. REF: AMM 32-41-01					PKG:5016,6032
32-41-07-720-001-A00 ^S	FUNCTIONALLY CHECK MAIN BRAKE HYDRAULIC FUSES									Service ATA:32
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: AMM 32-41-07					PKG:5008,6016
32-41-09-710-001-A00 ^S	OPERATIONALLY CHECK RETURN-LINE CHECK VALVE OF MAIN BRAKE SYSTEM.									Service ATA:32
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: AMM 32-41-09					PKG:5008,6016
32-44-00-720-001-A00 ^S	FUNCTIONALLY CHECK EMERGENCY/PARKING BRAKE SYSTEM									Service ATA:32
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
					PROC. REF: AMM 32-44-00					PKG:5016,6032
32-44-02-720-001-A00 ^S	FUNCTIONALLY CHECK HYDRAULIC ACCUMULATOR FOR NITROGEN PRE-CHARGE									Service ATA:32
	MOS	16-Aug-24	12 (+15d/-15d)					LOW UTILIZATION		
	HRS	10541.4	500 (+20/-20)							
	AFL	5613								
					PROC. REF: AMM 32-44-02					PKG:5002
32-44-06-720-001-A00 ^S	FUNCTIONALLY CHECK THERMAL RELIEF VALVE OF THE EMERGENCY/PARKING BRAKE SYSTEM									Service ATA:32
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
					PROC. REF: AMM 32-44-06					PKG:5016,6032
32-44-08-710-001-A00 ^S	OPERATIONALLY CHECK RETURN-LINE CHECK VALVE OF EMERGENCY/PARKING BRAKE SYSTEM									Service ATA:32
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: AMM 32-44-08					PKG:5008,6016

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
32-44-10-640-001-A00 ^S LUBRICATE MECHANICAL HARDWARE (HANDLE) AND ROLLER OF EMERGENCY PARKING BRAKE VALVE Service ATA:32										
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
PROC. REF: AMM 32-44-10										PKG:5008,6016
32-49-02-220-001-A00 INSPECT (DETAILED INSPECTION) LEFT NO. 1 MAIN LANDING GEAR OUTBOARD TIRE MLG WHEEL ASSY - WHEELS SPEED TRANSDUCER CLIP IN THE HUB CAP DRIVE CLIP NOTE: AT EACH TIRE CHANGE Service ATA:32										
PN:304K63-2	MOS/MSC	10-Jan-24	T/C					SYSTEM		
SN:32735231	HRS	10396.8								
	AFL	5532								
PROC. REF: AMM 32-49-02										
32-49-02-220-001-A00 INSPECT (DETAILED INSPECTION) LEFT NO. 2 MAIN LANDING GEAR INBOARD TIRE MLG WHEEL ASSY - WHEELS SPEED TRANSDUCER CLIP IN THE HUB CAP DRIVE CLIP NOTE: AT EACH TIRE CHANGE Service ATA:32										
PN:304K63-2	MOS/MSC	01-Mar-22	T/C					SYSTEM		
SN:11570308	HRS	9819.3								
	AFL	5227								
PROC. REF: AMM 32-49-02										
32-49-02-220-001-A00 INSPECT (DETAILED INSPECTION) RIGHT NO. 3 MAIN LANDING GEAR INBOARD TIRE MLG WHEEL ASSY - WHEELS SPEED TRANSDUCER CLIP IN THE HUB CAP DRIVE CLIP NOTE: AT EACH TIRE CHANGE Service ATA:32										
PN:304K63-2	MOS/MSC	16-Oct-23	T/C					SYSTEM		
SN:20200999	HRS	10259.3								
	AFL	5461								
PROC. REF: AMM 32-49-02										
32-49-02-220-001-A00 INSPECT (DETAILED INSPECTION) RIGHT NO. 4 MAIN LANDING GEAR OUTBOARD TIRE MLG WHEEL ASSY - WHEELS SPEED TRANSDUCER CLIP IN THE HUB CAP DRIVE CLIP NOTE: AT EACH TIRE CHANGE Service ATA:32										
PN:304K63-2	MOS/MSC	16-Oct-23	T/C					SYSTEM		
SN:23400868	HRS	10259.3								
	AFL	5461								
PROC. REF: AMM 32-49-02										
32-49-03-220-001-A00 INSPECT (DETAILED INSPECTION) OF LEFT NO. 1 BRAKE WEAR INDICATOR. NOTE: AT EACH TIRE CHANGE Service ATA:32										
PN:304K63-2	MOS/MSC	10-Jan-24	T/C					SYSTEM		
SN:32735231	HRS	10396.8								
	AFL	5532								
PROC. REF: AMM 32-49-03										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
32-49-03-220-001-A00 INSPECT (DETAILED INSPECTION) OF LEFT NO. 2 BRAKE WEAR INDICATOR. NOTE: AT EACH TIRE CHANGE Service ATA:32										
PN:304K63-2	MOS/MSC	01-Mar-22	T/C					SYSTEM		
SN:11570308	HRS	9819.3								
	AFL	5227								
PROC. REF: AMM 32-49-03										
32-49-03-220-001-A00 INSPECT (DETAILED INSPECTION) OF RIGHT NO. 3 BRAKE WEAR INDICATOR. NOTE: AT EACH TIRE CHANGE Service ATA:32										
PN:304K63-2	MOS/MSC	16-Oct-23	T/C					SYSTEM		
SN:20200999	HRS	10259.3								
	AFL	5461								
PROC. REF: AMM 32-49-03										
32-49-03-220-001-A00 INSPECT (DETAILED INSPECTION) OF RIGHT NO. 4 BRAKE WEAR INDICATOR. NOTE: AT EACH TIRE CHANGE Service ATA:32										
PN:304K63-2	MOS/MSC	16-Oct-23	T/C					SYSTEM		
SN:23400868	HRS	10259.3								
	AFL	5461								
PROC. REF: AMM 32-49-03										
32-49-07-710-001-A00 OPERATIONALLY CHECK NO. 1 CARBON ASSY-LEG,MAIN LANDING GEAR BRAKE BRAKE SHUTTLE VALVE NOTE: AT EACH BRAKE REPLACEMENT Service ATA:32										
PN:2-1582OPT5	MOS/MSC	27-Aug-07	C/C					SYSTEM		
SN:2723	HRS	0								
	AFL	0								
PROC. REF: AMM 32-49-07										
32-49-07-710-001-A00 OPERATIONALLY CHECK NO. 2 CARBON ASSY-LEG,MAIN LANDING GEAR BRAKE BRAKE SHUTTLE VALVE NOTE: AT EACH BRAKE REPLACEMENT Service ATA:32										
PN:2-1582OPT5	MOS/MSC	27-Aug-07	C/C							
SN:1464	HRS	0								
	AFL	0								
PROC. REF: AMM 32-49-07										
32-49-07-710-001-A00 OPERATIONALLY CHECK NO. 3 CARBON ASSY-LEG,MAIN LANDING GEAR BRAKE BRAKE SHUTTLE VALVE NOTE: AT EACH BRAKE REPLACEMENT Service ATA:32										
PN:2-1582	MOS/MSC	18-Aug-18	C/C							
SN:1968	HRS	8725.1								
	AFL	4681								
PROC. REF: AMM 32-49-07										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 32 - LANDING GEAR											
32-49-07-710-001-A00		OPERATIONALLY CHECK NO. 4 CARBON ASSY-LEG,MAIN LANDING GEAR BRAKE BRAKE SHUTTLE VALVE NOTE: AT EACH BRAKE REPLACEMENT							Service	ATA:32	
PN:2-1582OPT5	MOS/MSC	27-Aug-07	C/C								
SN:1844	HRS	0									
	AFL	0									
PROC. REF: AMM 32-49-07											
32-50-00-710-001-A00 ^S		OPERATIONALLY CHECK NOSE WHEEL STEERING SYSTEM DISENGAGEMENT							Service	ATA:32	
	MOS	16-Aug-24	12 (+15d/-15d)					LOW UTILIZATION			
	HRS	10541.4	500 (+20/-20)								
	AFL	5613									
PROC. REF: AMM 32-50-00											
PKG:5002											
32-50-06-720-001-A00 ^S		FUNCTIONALLY CHECK 7-DEGREE PROXIMITY SWITCH.							Service	ATA:32	
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	2000 (+20/-20)								
	AFL	5401	1000 (+20/-20)								
PROC. REF: AMM 32-50-06											
PKG:5008,6016											
32-62-00-710-001-A00 ^S		OPERATIONALLY CHECK LANDING-GEAR WARNING SYSTEM							Service	ATA:32	
	MOS	16-Aug-24	12 (+15d/-15d)					LOW UTILIZATION			
	HRS	10541.4	500 (+20/-20)								
	AFL	5613									
PROC. REF: AMM 32-62-00											
PKG:5002											
32-63-00-710-001-A00 ^S		OPERATIONALLY CHECK AIR/GROUND SYSTEM (CMR)							Service	ATA:32	
	MOS	16-Aug-24	12 (+15d/-15d)					LOW UTILIZATION			
	HRS	10541.4	500 (+20/-20)								
	AFL	5613									
PROC. REF: AMM 32-63-00											
PKG:5002											
32-Z711-213-001-A00 ^S		EXTERNAL GENERAL VISUAL INSPECTION OF ZONES 113, 114, 115, 116, 711, 713, 714 (L600 ONLY)							Service	ATA:32	
	MOS	29-Jun-23	24 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	1000 (+20/-20)								
	AFL	5401									
PROC. REF: AMM 05-20-99											
PKG:5004											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
32-Z711-213-001-A01	GENERAL VISUAL INSPECTION EXTERNAL GENERAL VISUAL INSPECTION (ZONES 113, 114, 115, 116,711, 713, 714) NOTE: EWIS.(L650 ONLY)									Service ATA:32
	MOS/MSC	25-Sep-07	N/A					ZONAL		
	HRS	0								
	AFL	0								
PROC. REF: AMM 05-20-99										
32-Z721-213-001-A00 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF ZONES 721, 731, 722, 732, 532, 632 (L600 ONLY)									Service ATA:32
	MOS	29-Jun-23	24 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	1000 (+20/-20)							
	AFL	5401								
PROC. REF: AMM 05-30-01										
32-Z721-213-001-A01	GENERAL VISUAL INSPECTION EXTERNAL GENERAL VISUAL INSPECTION (ZONES 721, 731, 722, 732,532, 632). NOTE: EWIS.(L650 ONLY)									Service ATA:32
	MOS/MSC	25-Sep-07	N/A					ZONAL		
	HRS	0								
	AFL	0								
PROC. REF: AMM 05-30-01										
321000-0101	LH MLG LEG OLEO STRUT ASSEMBLY									Component ATA:32
PN:2309-3100-405	MOS/MSC	06-Jul-19	O/C		TSN 143, TSO 0					
SN:00080	HRS	9057.4			TSN 9057.4, TSO 0					
	AFL	4853			TSN 4853, TSO 0					
PROC. REF: NDT GENERIC										
321000-0102	RH MLG LEG OLEO STRUT ASSEMBLY									Component ATA:32
PN:2309-3100-406	MOS/MSC	06-Jul-19	O/C		TSN 143, TSO 0					
SN:00090	HRS	9057.4			TSN 9057.4, TSO 0					
	AFL	4853			TSN 4853, TSO 0					
PROC. REF: NDT GENERIC										
321000-0201	LH STRUT (MLG) LEG									Component ATA:32
PN:2309-3006-505	MOS	06-Jul-19			TSN 143, TSO 0			LIFE LIMIT		
SN:1145758/001	HRS	9057.4			TSN 9057.4, TSO 0					
	AFL	4853	60000		TSN 4853	60000	54351			
PROC. REF: AMM 32-10-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 32 - LANDING GEAR											
321000-0202		RH STRUT (MLG) LEG								Component	ATA:32
PN:2309-3006-506	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT			
SN:1134444/001	HRS	9057.4		TSN 9057.4, TSO 0							
	AFL	4853	60000	TSN 4853	60000		54351				
PROC. REF: AMM 32-10-01											
321000-0203		LH STRUT (MLG) - PIVOT								Component	ATA:32
PN:2309-2050-003	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT			
SN:1078756/021	HRS	9057.4		TSN 9057.4, TSO 0							
	AFL	4853	60000	TSN 4853	60000		54351				
PROC. REF: NDT GENERIC											
321000-0204		RH STRUT (MLG) - PIVOT								Component	ATA:32
PN:2309-2050-003	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT			
SN:1078756/014	HRS	9057.4		TSN 9057.4, TSO 0							
	AFL	4853	60000	TSN 4853	60000		54351				
PROC. REF: NDT GENERIC											
321000-0301		LH NO. 1 TRUNNION (MLG) (LEG STRUT) AXLE								Component	ATA:32
PN:2309-3025-001	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT			
SN:1129173/004	HRS	9057.4		TSN 9057.4, TSO 0							
	AFL	4853	60000	TSN 4853	60000		54351				
PROC. REF: NDT GENERIC											
321000-0302		RH NO. 1 TRUNNION (MLG) (LEG STRUT) AXLE								Component	ATA:32
PN:2309-3025-001	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT			
SN:1120134/001	HRS	9057.4		TSN 9057.4, TSO 0							
	AFL	4853	60000	TSN 4853	60000		54351				
PROC. REF: NDT GENERIC											
321000-0303		LH NO. 2 TRUNNION (MLG) (LEG STRUT) AXLE								Component	ATA:32
PN:2309-3025-001	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT			
SN:1129173/001	HRS	9057.4		TSN 9057.4, TSO 0							
	AFL	4853	60000	TSN 4853	60000		54351				
PROC. REF: NDT GENERIC											
321000-0304		RH NO. 2 TRUNNION (MLG) (LEG STRUT) AXLE								Component	ATA:32
PN:2309-3025-001	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT			
SN:1120134/010	HRS	9057.4		TSN 9057.4, TSO 0							
	AFL	4853	60000	TSN 4853	60000		54351				
PROC. REF: NDT GENERIC											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
321000-0401 LH ACTUATOR ATTACHMENT (MLG) (LEG STRUT) AXLE Component ATA:32										
PN:2309-2027-005	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:1143020/008	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: NDT GENERIC										
321000-0402 RH ACTUATOR ATTACHMENT (MLG) (LEG STRUT) AXLE Component ATA:32										
PN:2309-2027-005	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:1128751/007	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: NDT GENERIC										
321001-0101 LH TRAILING (MLG) (LEG STRUT) ARM Component ATA:32										
PN:2309-3009-507	MOS		06-Jul-19		TSN 143, TSO 0			LIFE LIMIT		
SN:1138043/002	HRS		9057.4		TSN 9057.4, TSO 0					
	AFL		4853	60000	TSN 4853	60000	54351			
PROC. REF: AMM 32-10-08										
321001-0102 RH TRAILING (MLG) (LEG STRUT) ARM Component ATA:32										
PN:2309-3009-507	MOS		06-Jul-19		TSN 143, TSO 0			LIFE LIMIT		
SN:1139180/002	HRS		9057.4		TSN 9057.4, TSO 0					
	AFL		4853	60000	TSN 4853	60000	54351			
PROC. REF: AMM 32-10-08										
321001-0201 LH TRAILING ARM (MLG) (LEG STRUT) AXLE Component ATA:32										
PN:2309-3055-001	MOS		06-Jul-19		TSN 143, TSO 0			LIFE LIMIT		
SN:1150008/005	HRS		9057.4		TSN 9057.4, TSO 0					
	AFL		4853	60000	TSN 4853	60000	54351			
PROC. REF: AMM 32-10-08										
321001-0202 RH TRAILING ARM (MLG) (LEG STRUT) AXLE Component ATA:32										
PN:2309-3055-002	MOS		06-Jul-19		TSN 143, TSO 0			LIFE LIMIT		
SN:1132809/001	HRS		9057.4		TSN 9057.4, TSO 0					
	AFL		4853	60000	TSN 4853	60000	54351			
PROC. REF: AMM 32-10-08										
321002-0101 LH MLG SHOCK ABSORBER ASSEMBLY Component ATA:32										
PN:2309-2005-007	MOS/MSC		06-Jul-19	O/C	TSO 0					
SN:10041	HRS		9057.4		TSN 8793.6, TSO 0					
	AFL		4853		TSN 4716, TSO 0					
PROC. REF: AMM 32-10-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
321002-0102 RH MLG SHOCK ABSORBER ASSEMBLY Component ATA:32										
PN:2309-2005-007	MOS/MSC	06-Jul-19	O/C	TSO 0						
SN:10004	HRS	9057.4		TSO 0						
	AFL	4853		TSO 0						
PROC. REF: AMM 32-10-02										
321002-0201 LH MLG NO.1 SHOCK ABSORBER ATTACHMENT (LEG STRUT) AXLE Component ATA:32										
PN:2309-2029-001	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT		
SN:1145948/005	HRS	9057.4		TSN 9057.4, TSO 0						
	AFL	4853	60000	TSN 4853	60000		54351			
PROC. REF: AMM 32-10-02										
321002-0202 RH MLG NO.1 SHOCK ABSORBER ATTACHMENT (LEG STRUT) AXLE Component ATA:32										
PN:2309-2029-001	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT		
SN:1140197/007	HRS	9057.4		TSN 9057.4, TSO 0						
	AFL	4853	60000	TSN 4853	60000		54351			
PROC. REF: AMM 32-10-02										
321002-0203 LH MLG NO.2 SHOCK ABSORBER ATTACHMENT (LEG STRUT) AXLE Component ATA:32										
PN:2309-2029-001	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT		
SN:1145948/004	HRS	9057.4		TSN 9057.4, TSO 0						
	AFL	4853	60000	TSN 4853	60000		54351			
PROC. REF: AMM 32-10-02										
321002-0204 RH MLG NO.2 SHOCK ABSORBER ATTACHMENT (LEG STRUT) AXLE Component ATA:32										
PN:2309-2029-001	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT		
SN:1140197/008	HRS	9057.4		TSN 9057.4, TSO 0						
	AFL	4853	60000	TSN 4853	60000		54351			
PROC. REF: AMM 32-10-02										
321002-0301 LH SHOCK ABSORBER PISTON (MLG) (LEG STRUT) TUBE Component ATA:32										
PN:2309-2058-001	MOS	06-Jul-19		TSO 0				LIFE LIMIT		
SN:1138316/001	HRS	9057.4		TSO 0						
	AFL	4853	60000	TSN 4716	60137		54488			
PROC. REF: AMM 32-10-02										
321002-0302 RH SHOCK ABSORBER PISTON (MLG) (LEG STRUT) TUBE Component ATA:32										
PN:2309-2058-001	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT		
SN:1129863-002	HRS	9057.4		TSN 9057.4, TSO 0						
	AFL	4853	60000	TSN 4853	60000		54351			
PROC. REF: AMM 32-10-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 32 - LANDING GEAR											
321002-0401		LH SHOCK ABSORBER (MLG) (LEG STRUT) CYLINDER							Component	ATA:32	
PN:2309-2056-005	MOS	06-Jul-19		TSO 0				LIFE LIMIT			
SN:1139199/001	HRS	9057.4		TSO 0							
	AFL	4853	60000	TSN 4716	60137		54488				
PROC. REF: AMM 32-10-02											
321002-0402		RH SHOCK ABSORBER (MLG) (LEG STRUT) CYLINDER							Component	ATA:32	
PN:2309-2056-005	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT			
SN:1130055-001	HRS	9057.4		TSN 9057.4, TSO 0							
	AFL	4853	60000	TSN 4853	60000		54351				
PROC. REF: AMM 32-10-02											
321002-0501		LH SHOCK ABSORBER BEARING (MLG) (LEG STRUT) CAP							Component	ATA:32	
PN:2309-2082-001	MOS	06-Jul-19		TSO 0				LIFE LIMIT			
SN:1139188/006	HRS	9057.4		TSO 0							
	AFL	4853	60000	TSN 4716	60137		54488				
PROC. REF: AMM 32-10-02											
321002-0502		RH SHOCK ABSORBER BEARING (MLG) (LEG STRUT) CAP							Component	ATA:32	
PN:2309-2082-001	MOS	06-Jul-19		TSN 0				LIFE LIMIT			
SN:1621044/002	HRS	9057.4		TSN 0							
	AFL	4853	60000	TSN 0	64853		59204				
PROC. REF: AMM 32-10-02											
321003-0101		LH MAIN SIDE ASSY (MLG) STRUT							Component	ATA:32	
PN:2309-3500-503	MOS/MSC	06-Jul-19	O/C	TSN 143, TSO 0							
SN:01528	HRS	9057.4		TSN 9057.4, TSO 0							
	AFL	4853		TSN 4853, TSO 0							
PROC. REF: AMM 32-10-03											
321003-0102		RH MAIN SIDE ASSY (MLG) STRUT							Component	ATA:32	
PN:2309-3500-503	MOS/MSC	06-Jul-19	O/C	TSN 143, TSO 0							
SN:01491	HRS	9057.4		TSN 9057.4, TSO 0							
	AFL	4853		TSN 4853, TSO 0							
PROC. REF: AMM 32-10-03											
321003-0201		LH MLG LEG STRUT - MAIN SIDE STRUT ATTACHEMENT AXLE (PIVOT PIN)							Component	ATA:32	
PN:2309-3032-005	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT			
SN:1138094/001	HRS	9057.4		TSN 9057.4, TSO 0							
	AFL	4853	60000	TSN 4853	60000		54351				
PROC. REF: AMM 32-10-10											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
321003-0202 RH MLG LEG STRUT - MAIN SIDE STRUT ATTACHEMENT AXLE (PIVOT PIN) Component ATA:32										
PN:2309-3032-005	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT		
SN:1133462-002	HRS	9057.4		TSN 9057.4, TSO 0						
	AFL	4853	60000	TSN 4853	60000		54351			
PROC. REF: AMM 32-10-10										
321003-0301 LH MLG UPPER MAIN SIDE STRUT Component ATA:32										
PN:2309-2524-001	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT		
SN:1143026/010	HRS	9057.4		TSN 9057.4, TSO 0						
	AFL	4853	60000	TSN 4853	60000		54351			
PROC. REF: AMM 32-10-03										
321003-0302 RH MLG UPPER MAIN SIDE STRUT Component ATA:32										
PN:2309-2524-001	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT		
SN:1138062/005	HRS	9057.4		TSN 9057.4, TSO 0						
	AFL	4853	60000	TSN 4853	60000		54351			
PROC. REF: AMM 32-10-03										
321003-0401 LH MAIN SIDE STRUT (MLG) (LOWER) Component ATA:32										
PN:2309-2532-001	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT		
SN:1145946/007	HRS	9057.4		TSN 9057.4, TSO 0						
	AFL	4853	60000	TSN 4853	60000		54351			
PROC. REF: AMM 32-10-03										
321003-0402 RH MAIN SIDE STRUT (MLG) (LOWER) Component ATA:32										
PN:2309-2532-001	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT		
SN:1130597-010	HRS	9057.4		TSN 9057.4, TSO 0						
	AFL	4853	60000	TSN 4853	60000		54351			
PROC. REF: AMM 32-10-03										
321003-0501 LH MAIN SIDE STRUT (MLG) SHAFT Component ATA:32										
PN:2309-3515-001	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT		
SN:1148030/004	HRS	9057.4		TSN 9057.4, TSO 0						
	AFL	4853	60000	TSN 4853	60000		54351			
PROC. REF: NDT GENERIC										
321003-0502 RH MAIN SIDE STRUT (MLG) SHAFT Component ATA:32										
PN:2309-3515-001	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT		
SN:1126836/004	HRS	9057.4		TSN 9057.4, TSO 0						
	AFL	4853	60000	TSN 4853	60000		54351			
PROC. REF: NDT GENERIC										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
321003-0601 LH MAIN SIDE STRUT (MLG) PIVOT PIN Component ATA:32										
PN:2309-3516-001	MOS	06-Jul-19			TSN 143, TSO 0			LIFE LIMIT		
SN:1150805/001	HRS	9057.4			TSN 9057.4, TSO 0					
	AFL	4853	60000		TSN 4853	60000	54351			
PROC. REF: NDT GENERIC										
321003-0602 RH MAIN SIDE STRUT (MLG) PIVOT PIN Component ATA:32										
PN:2309-3516-001	MOS	06-Jul-19			TSN 143, TSO 0			LIFE LIMIT		
SN:1124611/006	HRS	9057.4			TSN 9057.4, TSO 0					
	AFL	4853	60000		TSN 4853	60000	54351			
PROC. REF: NDT GENERIC										
321003-0701 LH MAIN SIDE STRUT (MLG) CARDAN Component ATA:32										
PN:2309-3530-001	MOS/MSC	27-Aug-07	O/C		TSN 0					
SN:1144576/002	HRS	0			TSN 0					
	AFL	0			TSN 0					
PROC. REF: AMM 32-10-10										
321003-0702 RH MAIN SIDE STRUT (MLG) CARDAN Component ATA:32										
PN:2309-3530-001	MOS/MSC	06-Jul-19	O/C		TSN 143, TSO 0					
SN:1119633/002	HRS	9057.4			TSN 9057.4, TSO 0					
	AFL	4853			TSN 4853, TSO 0					
PROC. REF: AMM 32-10-10										
321004-0101 LH LDG ROD -SECONDARY,MAIN LANDING GEAR ASSEMBLY Component ATA:32										
PN:2309-2600-507	MOS/MSC	06-Jul-19	O/C		TSN 143, TSO 0					
SN:02104	HRS	9057.4			TSN 9057.4, TSO 0					
	AFL	4853			TSN 4853, TSO 0					
PROC. REF: NDT GENERIC										
321004-0102 RH LDG ROD -SECONDARY,MAIN LANDING GEAR ASSEMBLY Component ATA:32										
PN:2309-2600-507	MOS/MSC	06-Jul-19	O/C		TSN 143, TSO 0					
SN:02066	HRS	9057.4			TSN 9057.4, TSO 0					
	AFL	4853			TSN 4853, TSO 0					
PROC. REF: NDT GENERIC										
321004-0301 LH MLG UPPER SECONDARY SIDE STRUT Component ATA:32										
PN:2309-2611-003	MOS	06-Jul-19			TSN 143, TSO 0			LIFE LIMIT		
SN:1156805/007	HRS	9057.4			TSN 9057.4, TSO 0					
	AFL	4853	60000		TSN 4853	60000	54351			
PROC. REF: AMM 32-10-10										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 32 - LANDING GEAR											
321004-0302		RH MLG UPPER SECONDARY SIDE STRUT								Component	ATA:32
PN:2309-2611-003	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT			
SN:1137253/001	HRS	9057.4		TSN 9057.4, TSO 0							
	AFL	4853	60000	TSN 4853	60000		54351				
PROC. REF: AMM 32-10-10											
321004-0401		LH MLG SECONDARY SIDE STRUT (LOWER)								Component	ATA:32
PN:2309-2624-001	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT			
SN:1162870/012	HRS	9057.4		TSN 9057.4, TSO 0							
	AFL	4853	60000	TSN 4853	60000		54351				
PROC. REF: AMM 32-10-04											
321004-0402		RH MLG SECONDARY SIDE STRUT (LOWER)								Component	ATA:32
PN:2309-2624-001	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT			
SN:1139184/009	HRS	9057.4		TSN 9057.4, TSO 0							
	AFL	4853	60000	TSN 4853	60000		54351				
PROC. REF: AMM 32-10-04											
321004-0501		LH MLG SECONDARY SIDE STRUT CARDAN								Component	ATA:32
PN:2309-2618-001	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT			
SN:1122821/058	HRS	9057.4		TSN 9057.4, TSO 0							
	AFL	4853	60000	TSN 4853	60000		54351				
PROC. REF: AMM 32-10-11											
321004-0502		RH MLG SECONDARY SIDE STRUT CARDAN								Component	ATA:32
PN:2309-2618-001	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT			
SN:1122821/042	HRS	9057.4		TSN 9057.4, TSO 0							
	AFL	4853	60000	TSN 4853	60000		54351				
PROC. REF: AMM 32-10-11											
321004-0601		LH MLG SECONDARY SIDE STRUT AXLE								Component	ATA:32
PN:2309-2621-001	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT			
SN:1136819/005	HRS	9057.4		TSN 9057.4, TSO 0							
	AFL	4853	60000	TSN 4853	60000		54351				
PROC. REF: NDT GENERIC											
321004-0602		RH MLG SECONDARY SIDE STRUT AXLE								Component	ATA:32
PN:2309-2621-001	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT			
SN:1123525/009	HRS	9057.4		TSN 9057.4, TSO 0							
	AFL	4853	60000	TSN 4853	60000		54351				
PROC. REF: NDT GENERIC											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
321004-0701 LH MLG SECONDARY SIDE STRUT BOLT Component ATA:32										
PN:2309-2626-001	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT		
SN:1140062/006	HRS	9057.4		TSN 9057.4, TSO 0						
	AFL	4853	60000	TSN 4853	60000		54351			
PROC. REF: NDT GENERIC										
321004-0702 RH MLG SECONDARY SIDE STRUT BOLT Component ATA:32										
PN:2309-2626-001	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT		
SN:1124607/049	HRS	9057.4		TSN 9057.4, TSO 0						
	AFL	4853	60000	TSN 4853	60000		54351			
PROC. REF: NDT GENERIC										
321004-0801 LH MLG SECONDARY SIDE STRUT PIVOT PIN Component ATA:32										
PN:2309-2613-001	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT		
SN:1150116/005	HRS	9057.4		TSN 9057.4, TSO 0						
	AFL	4853	60000	TSN 4853	60000		54351			
PROC. REF: NDT GENERIC										
321004-0802 RH MLG SECONDARY SIDE STRUT PIVOT PIN Component ATA:32										
PN:2309-2613-001	MOS	06-Jul-19		TSO 0				LIFE LIMIT		
SN:1134738/004	HRS	9057.4		TSO 0						
	AFL	4853	60000	TSN 4853	60000		54351			
PROC. REF: NDT GENERIC										
321004-0901 LH MLG SECONDARY SIDE STRUT NO.1 SPRING Component ATA:32										
PN:2309-2651-005	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT		
SN:1153614/030	HRS	9057.4		TSN 9057.4, TSO 0						
	AFL	4853	60000	TSN 4853	60000		54351			
PROC. REF: AMM 32-10-05										
321004-0902 LH MLG SECONDARY SIDE STRUT NO.2 SPRING Component ATA:32										
PN:2309-2651-005	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT		
SN:1153614/025	HRS	9057.4		TSN 9057.4, TSO 0						
	AFL	4853	60000	TSN 4853	60000		54351			
PROC. REF: AMM 32-10-05										
321004-0903 RH MLG SECONDARY SIDE STRUT NO.1 SPRING Component ATA:32										
PN:2309-2651-005	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT		
SN:1148690/013	HRS	9057.4		TSN 9057.4, TSO 0						
	AFL	4853	60000	TSN 4853	60000		54351			
PROC. REF: AMM 32-10-05										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
321004-0904 RH MLG SECONDARY SIDE STRUT NO.2 SPRING Component ATA:32										
PN:2309-2651-005	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT		
SN:1148690/012	HRS	9057.4		TSN 9057.4, TSO 0						
	AFL	4853	60000	TSN 4853	60000		54351			
PROC. REF: AMM 32-10-05										
321005-0101 LH WHEEL (MLG) (LEG STRUT) AXLE Component ATA:32										
PN:2309-3040-001	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT		
SN:1138050/002	HRS	9057.4		TSN 9057.4, TSO 0						
	AFL	4853	60000	TSN 4853	60000		54351			
PROC. REF: AMM 32-49-02										
321005-0102 RH WHEEL (MLG) (LEG STRUT) AXLE Component ATA:32										
PN:2309-3040-001	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT		
SN:1106882/002	HRS	9057.4		TSN 9057.4, TSO 0						
	AFL	4853	60000	TSN 4853	60000		54351			
PROC. REF: AMM 32-49-02										
321005-0501 LH MLG SECONDARY SIDE STRUT NO.1 SPRING CARTRIDGE ASSY Component ATA:32										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
321005-0502 LH MLG SECONDARY SIDE STRUT NO.2 SPRING CARTRIDGE ASSY Component ATA:32										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
321005-0503 RH MLG SECONDARY SIDE STRUT NO.1 SPRING CARTRIDGE ASSY Component ATA:32										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
321005-0504 RH MLG SECONDARY SIDE STRUT NO.2 SPRING CARTRIDGE ASSY Component ATA:32										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
321006-0101 LH (MLG) (LEG STRUT) CARDAN JOINT Component ATA:32										
PN:2309-2048-005	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT		
SN:1140614/008	HRS	9057.4		TSN 9057.4, TSO 0						
	AFL	4853	60000	TSN 4853	60000		54351			
PROC. REF: AMM 32-10-10										
321006-0102 RH (MLG) (LEG STRUT) CARDAN JOINT Component ATA:32										
PN:2309-2048-005	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT		
SN:1121551/003	HRS	9057.4		TSN 9057.4, TSO 0						
	AFL	4853	60000	TSN 4853	60000		54351			
PROC. REF: AMM 32-10-10										
321007-0101 LH (MLG) LINEAR HYDRAULIC (MANEUVERING ACTUATOR) ACTUATOR Component ATA:32										
PN:2309-3700-503	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:01561	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										
321007-0102 RH (MLG) LINEAR HYDRAULIC (MANEUVERING ACTUATOR) ACTUATOR Component ATA:32										
PN:2309-3700-503	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:01538	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										
321007-0201 LH MANEUVERING ACTUATOR (MLG) CYLINDER Component ATA:32										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										
321007-0202 RH MANEUVERING ACTUATOR (MLG) CYLINDER Component ATA:32										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										
321007-0301 LH MANEUVERING ACTUATOR (MLG) ROD END Component ATA:32										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
321007-0302 RH MANEUVERING ACTUATOR (MLG) ROD END Component ATA:32										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										
321007-0401 LH MANEUVERING ACTUATOR ROD (MLG) PISTON Component ATA:32										
PN:2309-3710-001	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:1140770/001	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										
321007-0402 RH MANEUVERING ACTUATOR ROD (MLG) PISTON Component ATA:32										
PN:2309-3710-001	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:1132492/001	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										
321007-0501 LH MANEUVERING ACTUATOR BEARING (MLG) CAP Component ATA:32										
PN:2309-3712-001	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:1159163/002	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										
321007-0502 RH MANEUVERING ACTUATOR BEARING (MLG) CAP Component ATA:32										
PN:2309-3712-001	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:1133951/010	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										
322000-0101 LEG -NOSE LANDING GEAR ASSEMBLY Component ATA:32										
PN:2233A0000-02	MOS	06-Jul-19		TSN 143, TSO 0				SCRAP		
SN:02303	HRS	9057.4		TSN 9057.4, TSO 0						
	AFL	4853	60000	TSN 4853	60000		54351			
PROC. REF: AMM 32-20-01										
322000-0201 NLG LEG STRUT SLIDING TUBE Component ATA:32										
PN:2233-0201	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT		
SN:1379	HRS	9057.4		TSN 9057.4, TSO 0						
	AFL	4853	60000	TSN 4853	60000		54351			
PROC. REF: AMM 32-20-08										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
322000-0301 NLG LEG STRUT WHEEL AXLE Component ATA:32										
PN:2233-0202	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT		
SN:L219	HRS	9057.4		TSN 9057.4, TSO 0						
	AFL	4853	60000	TSN 4853	60000		54351			
PROC. REF: NDT GENERIC										
322000-0401 NLG LEG STRUT STEERING CUFF Component ATA:32										
PN:1170-2301	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT		
SN:L1578	HRS	9057.4		TSN 9057.4, TSO 0						
	AFL	4853	60000	TSN 4853	60000		54351			
PROC. REF: NDT GENERIC										
322000-0501 NO.1 NLG LEG STRUT TORQUE LINK Component ATA:32										
PN:1170-0301	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT		
SN:L2583	HRS	9057.4		TSN 9057.4, TSO 0						
	AFL	4853	60000	TSN 4853	60000		54351			
PROC. REF: AMM 32-20-10										
322000-0502 NO.2 NLG LEG STRUT TORQUE LINK Component ATA:32										
PN:1170-0301	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT		
SN:L2584	HRS	9057.4		TSN 9057.4, TSO 0						
	AFL	4853	60000	TSN 4853	60000		54351			
PROC. REF: AMM 32-20-10										
322000-0601 NO.1 NLG LEG STRUT TORQUE LINK PIN Component ATA:32										
PN:1170-0001	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT		
SN:L1843	HRS	9057.4		TSN 9057.4, TSO 0						
	AFL	4853	60000	TSN 4853	60000		54351			
PROC. REF: AMM 32-20-10										
322000-0602 NO.2 NLG LEG STRUT TORQUE LINK PIN Component ATA:32										
PN:1170-0001	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT		
SN:L2625	HRS	9057.4		TSN 9057.4, TSO 0						
	AFL	4853	60000	TSN 4853	60000		54351			
PROC. REF: AMM 32-20-10										
322000-0701 NLG LEG STRUT TORQUE LINK CENTRAL BOLT Component ATA:32										
PN:1170-0002	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT		
SN:L1337	HRS	9057.4		TSN 9057.4, TSO 0						
	AFL	4853	60000	TSN 4853	60000		54351			
PROC. REF: AMM 32-20-10										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
322000-0801 NLG LEG STRUT MAIN FITTING Component ATA:32										
PN:2233-0103	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT		
SN:L572	HRS	9057.4		TSN 9057.4, TSO 0						
	AFL	4853	60000	TSN 4853	60000		54351			
PROC. REF: AMM 32-20-01										
322000-0901 (NLG) MAIN DRAG STRUT ATTACHMENT PIN Component ATA:32										
PN:1170-0070	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT		
SN:L1490	HRS	9057.4		TSN 9057.4, TSO 0						
	AFL	4853	60000	TSN 4853	60000		54351			
PROC. REF: NDT GENERIC										
322000-1101 NO. 1 NLG LEG STRUT PINTLE PIN Component ATA:32										
PN:1170-0032	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT		
SN:L3045	HRS	9057.4		TSN 9057.4, TSO 0						
	AFL	4853	60000	TSN 4853	60000		54351			
PROC. REF: NDT GENERIC										
322000-1102 NO. 2 NLG LEG STRUT PINTLE PIN Component ATA:32										
PN:1170-0032	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT		
SN:L3046	HRS	9057.4		TSN 9057.4, TSO 0						
	AFL	4853	60000	TSN 4853	60000		54351			
PROC. REF: NDT GENERIC										
322000-1201 (NLG) LEG STRUT ACTUATOR ATTACHMENT BOLT PIN Component ATA:32										
PN:1170-0071	MOS	27-Aug-07		TSN 0				LIFE LIMIT		
SN:L1445	HRS	0		TSN 0						
	AFL	0	60000	TSN 0	60000		54351			
PROC. REF: NDT GENERIC										
322000-1301 NLG LEG STRUT SET - SCREW Component ATA:32										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										
322000-1302 NLG LEG STRUT SET - SCREW Component ATA:32										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 32 - LANDING GEAR											
322000-1401		NLG LEG STRUT - RACK								Component	ATA:32
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: NDT GENERIC											
322000-1501		NLG LEG STRUT - PINION								Component	ATA:32
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: NDT GENERIC											
322000-1601		NLG LEG STRUT CYLINDER - HOUSING								Component	ATA:32
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: NDT GENERIC											
322000-1602		NLG LEG STRUT CYLINDER - HOUSING								Component	ATA:32
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: NDT GENERIC											
322001-0101		TOP NLG MAIN DRAG STRUT STAY								Component	ATA:32
PN:1172A0600-01	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT			
SN:HM1431	HRS	9057.4		TSN 9057.4, TSO 0							
	AFL	4853	60000	TSN 4853	60000		54351				
PROC. REF: NDT GENERIC											
322001-0201		BOTTOM NLG MAIN DRAG STRUT STAY								Component	ATA:32
PN:1172A0200-01	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT			
SN:HM39	HRS	9057.4		TSN 9057.4, TSO 0							
	AFL	4853	60000	TSN 4853	60000		54351				
PROC. REF: NDT GENERIC											
322001-0301		NO.1 NLG MAIN DRAG STRUT PINTLE PIN								Component	ATA:32
PN:1172-0037	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT			
SN:L359	HRS	9057.4		TSN 9057.4, TSO 0							
	AFL	4853	60000	TSN 4853	60000		54351				
PROC. REF: NDT GENERIC											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
322001-0302 NO.2 NLG MAIN DRAG STRUT PINTLE PIN Component ATA:32										
PN:1172-0037	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT		
SN:L358	HRS	9057.4		TSN 9057.4, TSO 0						
	AFL	4853	60000	TSN 4853	60000		54351			
PROC. REF: NDT GENERIC										
322001-0401 NLG MAIN DRAG STRUT HINGE POINT BOLT Component ATA:32										
PN:1172-0001	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT		
SN:HM241	HRS	9057.4		TSN 9057.4, TSO 0						
	AFL	4853	60000	TSN 4853	60000		54351			
PROC. REF: NDT GENERIC										
322001-0501 NLG MAIN DRAG STRUT ACTUATOR ATTACHMENT PIN Component ATA:32										
PN:1172-0066	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:HMO75	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										
322001-0601 NLG MAIN DRAG STRUT ASSEMBLY Component ATA:32										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										
322002-0101 NLG ROD -MAIN LOCKING,NOSE LANDING GEAR ASSEMBLY Component ATA:32										
PN:1172C0000-02	MOS/MSC	06-Jul-19	O/C	TSN 143, TSO 0						
SN:02086	HRS	9057.4		TSN 9057.4, TSO 0						
	AFL	4853		TSN 4853						
PROC. REF: NDT GENERIC										
322003-0101 NLG AUXILIARY DRAG STRUT Component ATA:32										
PN:1173B0000-03	MOS/MSC	06-Jul-19	O/C	TSN 143, TSO 0						
SN:02115	HRS	9057.4		TSN 9057.4, TSO 0						
	AFL	4853		TSN 4853, TSO 0						
PROC. REF: NDT GENERIC										
322004-0101 NLG AUXILIARY DRAG STRUT (UPPER) Component ATA:32										
PN:1173A0200-01	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT		
SN:HM1191	HRS	9057.4		TSN 9057.4, TSO 0						
	AFL	4853	60000	TSN 4853	60000		54351			
PROC. REF: AMM 32-20-09										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 32 - LANDING GEAR											
322004-0201		NLG AUXILIARY DRAG STRUT (LOWER)								Component	ATA:32
PN:1173A0100-02	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT			
SN:L1327	HRS	9057.4		TSN 9057.4, TSO 0							
	AFL	4853	60000	TSN 4853	60000		54351				
PROC. REF: AMM 32-20-09											
322004-0301		NO. 1 NLG AUXILIARY DRAG STRUT HINGE POINT BOLT								Component	ATA:32
PN:1173-0001	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT			
SN:HM120	HRS	9057.4		TSN 9057.4, TSO 0							
	AFL	4853	60000	TSN 4853	60000		54351				
PROC. REF: AMM 32-20-03											
322004-0302		NLG UNLOCKING ACTUATOR BOLT								Component	ATA:32
PN:1173-0024	MOS/MSC	06-Jul-19	O/C	TSN 143, TSO 0							
SN:HM01P	HRS	9057.4		TSN 9057.4, TSO 0							
	AFL	4853		TSN 4853, TSO 0							
PROC. REF: AMM 32-20-03											
322004-0401		NLG AUXILIARY DRAG STRUT (JOINT ATTACHING PARTS) CARDAN								Component	ATA:32
PN:KSL 113608V	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT			
SN:4184-KC1296	HRS	9057.4		TSN 9057.4, TSO 0							
	AFL	4853	60000	TSN 4853	60000		54351				
PROC. REF: AMM 32-20-09											
322004-0501		NO. 1 NLG AUXILIARY DRAG STRUT SLEEVE								Component	ATA:32
PN:1173-0011	MOS/MSC	06-Jul-19	O/C	TSN 143, TSO 0							
SN:HM01P	HRS	9057.4		TSN 9057.4, TSO 0							
	AFL	4853		TSN 4853, TSO 0							
PROC. REF: AMM 32-20-03											
322004-0502		NO. 2 NLG AUXILIARY DRAG STRUT SLEEVE								Component	ATA:32
PN:1173-0011	MOS/MSC	06-Jul-19	O/C	TSN 143, TSO 0							
SN:HM01P	HRS	9057.4		TSN 9057.4, TSO 0							
	AFL	4853		TSN 4853, TSO 0							
PROC. REF: AMM 32-20-03											
322004-0601		NO. 1 NLG AUXILIARY DRAG STRUT DOWNLOCK SPRING								Component	ATA:32
PN:1173A0700-01	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT			
SN:064215HM	HRS	9057.4		TSN 9057.4, TSO 0							
	AFL	4853	60000	TSN 4853	60000		54351				
PROC. REF: AMM 32-20-03											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
322004-0602 NO. 2 NLG AUXILIARY DRAG STRUT DOWNLOCK SPRING Component ATA:32										
PN:1173A0700-01	MOS	06-Jul-19		TSN 143, TSO 0				LIFE LIMIT		
SN:064216HM	HRS	9057.4		TSN 9057.4, TSO 0						
	AFL	4853	60000	TSN 4853	60000		54351			
PROC. REF: AMM 32-20-03										
322005-0101 NO. 1 NLG - NOSE LANDING GEAR DOOR ASSEMBLY Component ATA:32										
PN:135-18799-401	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:0000127632	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-20-05										
322005-0102 NO.2 NLG - NOSE LANDING GEAR DOOR ASSEMBLY Component ATA:32										
PN:135-18799-402	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:0000127641	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-20-05										
323201-0101 CSL CENT LANDING GEAR ELECTRONIC UNIT Component ATA:32										
PN:355-022-003	MOS/MSC	17-Jun-11	O/C							
SN:5105	HRS	4739.5								
	AFL	2487								
PROC. REF: AMM 32-32-01										
323202-0101 CSL CENT CONTROL, LANDING GEAR, MAIN PANEL LEVER Component ATA:32										
PN:7-45550-3	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:1203	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-32-02										
323301-0101 MID FREE-FALL SELECTOR VALVE Component ATA:32										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-33-01										
323302-0101 MID SOLENOID 4 WASYS, 2 POS VALVE Component ATA:32										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-33-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
323303-0101 NOSE ACTUATOR, HYDRAULIC -DOOR, NOSE LANDING GEAR ASSEMBLY Component ATA:32										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-33-03										
323303-0102 NOSE ACTUATOR, HYDRAULIC -DOOR, NOSE LANDING GEAR ASSEMBLY Component ATA:32										
PN:2118-0100-401	MOS/MSC	13-Mar-15	O/C	TSR 2						
SN:1732	HRS	7353.5		TSR 0						
	AFL			TSR 0						
PROC. REF: AMM 32-33-03										
323303-0201 NLG DOOR ACTUATOR Component ATA:32										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-33-03										
323304-0101 MID SOLENOID 4 WAY, 3 POS, VALVE Component ATA:32										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-33-04										
323305-0101 NLG MANEUVERING ACTUATOR Component ATA:32										
PN:1300B0000-02	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:02085	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-33-05										
323305-0201 NLG MANEUVERING ACTUATOR CYLINDER Component ATA:32										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-33-05										
323305-0301 NLG MANEUVERING ACTUATOR PISTON ROD Component ATA:32										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-33-05										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
323306-0101 NLG ACTUATOR -HYDRAULIC,UNLOCKING, NLG ASSEMBLY Component ATA:32										
PN:1175B0000-01	MOS/MSC		27-Aug-07	O/C						
SN:02015	HRS		0							
	AFL		0		TSN 0					
PROC. REF: AMM 32-33-06										
323307-0101 NLG BOX UP LOCK -HYDRAULIC SYS,AUXILIARY LANDING GEAR ASSEMBLY Component ATA:32										
PN:2309-2900-401	MOS/MSC		27-Aug-07	O/C						
SN:03163	HRS		0							
	AFL		0		TSN 0					
PROC. REF: AMM 32-33-07										
323307-0102 LH LDG BOX UP LOCK -HYDRAULIC SYS,AUXILIARY LANDING GEAR ASSEMBLY Component ATA:32										
PN:2309-2900-401	MOS/MSC		27-Aug-07	O/C						
SN:03157	HRS		0							
	AFL		0		TSN 0					
PROC. REF: AMM 32-33-07										
323307-0103 RH LDG BOX UP LOCK -HYDRAULIC SYS,AUXILIARY LANDING GEAR ASSEMBLY Component ATA:32										
PN:2309-2900-401	MOS/MSC		27-Aug-07	O/C						
SN:03100	HRS		0							
	AFL		0		TSN 0					
PROC. REF: AMM 32-33-07										
323309-0101 LH LDG UNLOCKING ACTUATOR ASSEMBLY Component ATA:32										
PN:2309-2800-505	MOS/MSC		27-Aug-07	O/C						
SN:02114	HRS		0							
	AFL		0		TSN 0					
PROC. REF: AMM 32-33-09										
323309-0102 RH LDG UNLOCKING ACTUATOR ASSEMBLY Component ATA:32										
PN:2309-2800-505	MOS/MSC		27-Aug-07	O/C						
SN:02085	HRS		0							
	AFL		0		TSN 0					
PROC. REF: AMM 32-33-09										
323311-0101 MID CHECK ASSY-HYDRAULIC SYS, FWD FUSLG VALVE Component ATA:32										
PN:PN	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: AMM 32-33-11										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
323311-0102 STUB CHECK ASSY-HYDRAULIC SYS, FWD FUSLG VALVE Component ATA:32										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-33-11										
323311-0103 RH RACK CHECK ASSY-HYDRAULIC SYS, FWD FUSLG VALVE Component ATA:32										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-33-11										
323312-0101 MID RESTRICTOR, HYDRAULIC SYS, SSTEEL VALVE Component ATA:32										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-33-12										
323315-0101 MID HYDRAULIC ACCUMULATOR Component ATA:32										
PN:0860202001	MOS/MSC	19-Sep-13	O/C	TSN 25						
SN:602002-2226NAHRS		6680.2		TSN 0						
	AFL	3597		TSN 0						
PROC. REF: AMM 32-33-15										
323315-0701^U LANDING GEAR HYDRAULIC ACCUMULATOR DRAIN VALVE Component ATA:32										
PN:HV50-61	MOS/MSC	21-Jan-22	O/C							
SN:80206103	HRS	9789.3								
	AFL	5205								
323316-0101 MID ONE-WAY RESTRICTOR VALVE Component ATA:32										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-33-12										
323319-0101 MID DRAIN-MANUAL, HYDRAULIC SYS, FWD/CTL FUSLG VALVE Component ATA:32										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
323319-0102 HYD SYST DRAIN-MANUAL, HYDRAULIC SYS, FWD/CTL FUSLG VALVE Component ATA:32										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										
323319-0103 MID DRAIN-MANUAL, HYDRAULIC SYS, FWD/CTL FUSLG VALVE Component ATA:32										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										
324101-0201 LH PIL PEDAL, RUDDER CONTROL, FWD FUSLG TRANSDUCER Component ATA:32										
PN:20-017500	MOS/MSC	28-Nov-08	O/C							
SN:764778	HRS	1511.4								
	AFL	802								
PROC. REF: AMM 32-41-01										
324101-0202 LH COPIL PEDAL, RUDDER CONTROL, FWD FUSLG TRANSDUCER Component ATA:32										
PN:20-017500	MOS/MSC	28-Nov-08	O/C							
SN:773635	HRS	1511.4								
	AFL	802								
PROC. REF: AMM 32-41-01										
324101-0203 RH PIL PEDAL, RUDDER CONTROL, FWD FUSLG TRANSDUCER Component ATA:32										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-41-01										
324101-0204 RH COPIL PEDAL, RUDDER CONTROL, FWD FUSLG TRANSDUCER Component ATA:32										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-41-01										
324102-0101 C FLOOR CONTROL ASSY, BS, BRAKE SYS, COCKPIT BOX Component ATA:32										
PN:142-093 REV A	MOS/MSC	11-Oct-08	O/C							
SN:442	HRS	1392.8								
	AFL	744								
PROC. REF: AMM 32-41-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
324103-0101 LEFT NO. 1 WHEEL SPEED OUTBOARD TRANSDUCER Component ATA:32										
PN:140-197	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-41-03										
324103-0102 LEFT NO. 2 WHEEL SPEED INBOARD TRANSDUCER Component ATA:32										
PN:140-197	MOS/MSC	08-Oct-08	O/C	TSO 0						
SN:1678	HRS	1378.1		TSO 0						
	AFL	736		TSO 0						
PROC. REF: AMM 32-41-03										
324103-0103 RIGHT NO.3 WHEEL SPEED INBOARD TRANSDUCER Component ATA:32										
PN:140-197	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-41-03										
324103-0104 RIGHT NO.4 WHEEL SPEED OUTBOARD TRANSDUCER Component ATA:32										
PN:140-197	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-41-03										
324104-0101 LEFT PRESSURE SWITCH Component ATA:32										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-41-04										
324104-0102 RIGHT PRESSURE SWITCH Component ATA:32										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-41-04										
324105-0101 LH WING SHUTOFF,BRAKE VALVE Component ATA:32										
PN:38-793500	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:2092	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-41-05										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
324105-0102 RH WING SHUTOFF,BRAKE VALVE Component ATA:32										
PN:38-793500	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:2195	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-41-05										
324106-0101 LH WING BRAKE CONTROL VALVE Component ATA:32										
PN:39-807	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:2256	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-41-06										
324106-0102 RH WING BRAKE CONTROL VALVE Component ATA:32										
PN:39-807	MOS/MSC	08-Nov-08	O/C							
SN:402	HRS	1467								
	AFL	779								
PROC. REF: AMM 32-41-06										
324107-0101 LH WING FUSE Component ATA:32										
PN:38-791500	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-41-07										
324107-0102 LH WING FUSE Component ATA:32										
PN:38-791500	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-41-07										
324107-0201 RH WING FUSE Component ATA:32										
PN:38-791500	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-41-07										
324107-0202 RH WING FUSE Component ATA:32										
PN:38-791500	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-41-07										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
324108-0201 LH WING PRESSURE-LANDING GEAR TRANSDUCER Component ATA:32										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-41-08										
324108-0202 RH WING PRESSURE-LANDING GEAR TRANSDUCER Component ATA:32										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-41-08										
324108-0203 LH WING PRESSURE-LANDING GEAR TRANSDUCER Component ATA:32										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-41-08										
324108-0204 RH WING PRESSURE-LANDING GEAR TRANSDUCER Component ATA:32										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-41-08										
324109-0101 W STUB CHECK ASSY-HYDRAULIC SYS, FWD FUSLG VALVE Component ATA:32										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-41-09										
324109-0102 W STUB CHECK ASSY-HYDRAULIC SYS, FWD FUSLG VALVE Component ATA:32										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-41-09										
324109-0103 MID CHECK ASSY-HYDRAULIC SYS, FWD FUSLG VALVE Component ATA:32										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-41-09										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
324401-0101 HYD SYST EMERGENCY PARKING BRAKE VALVE Component ATA:32										
PN:9067-40-4	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:1216	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: AMM 32-44-01										
324402-0101 EMERGENCY PARKING BRAKE HYDRAULIC ACCUMULATOR Component ATA:32										
PN:088424002	MOS/MSC		03-Nov-07	O/C						
SN:8424-16128	HRS		167.3							
	AFL		85							
PROC. REF: AMM 32-44-02										
324402-0102 FUS WING ACCUMULATOR, HYDRAULIC, PISTON ACCUMULATOR Component ATA:32										
PN:PN	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: AMM 32-44-02										
324405-0101 HYD SYST PRESSURE SWITCH Component ATA:32										
PN:15782-101	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:0600	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: AMM 32-44-05										
324406-0101 MID THERMAL RELIEF ASSY, VALVE Component ATA:32										
PN:2228-0001-005	MOS/MSC		27-Jul-15	O/C	TSR 8					
SN:02430	HRS		7460.3		TSR 0					
	AFL		3992		TSR 0					
PROC. REF: AMM 32-44-06										
324406-0102 RH RACK THERMAL RELIEF ASSY, VALVE Component ATA:32										
PN:2228-0001-005	MOS/MSC		15-Aug-13	O/C	TSN 24					
SN:02537	HRS		6643.4		TSN 1823.3					
	AFL		3572		TSN 1026					
PROC. REF: AMM 32-44-06										
324407-0101 LH WING PRESSURE-PARKING BRAKE SYS SWITCH Component ATA:32										
PN:15851	MOS/MSC		19-Mar-15	O/C	TSN 0					
SN:1666	HRS		7359.8		TSN 0					
	AFL		3939		TSN 0					
PROC. REF: AMM 32-44-07										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 32 - LANDING GEAR											
324701-0201		LH LDG INDICATOR,BRAKE TEMPERATURE SENSOR							Component	ATA:32	
PN:0132AEV-3	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 32-47-01											
324701-0202		LH LDG INDICATOR,BRAKE TEMPERATURE SENSOR							Component	ATA:32	
PN:0132AEV-3	MOS/MSC	07-Jul-11	O/C	TSN 0							
SN:K1985	HRS	4802.9	TSN 0								
	AFL	2530	TSN 0								
PROC. REF: AMM 32-47-01											
324701-0203		RH LDG INDICATOR,BRAKE TEMPERATURE SENSOR							Component	ATA:32	
PN:0132AEV-3	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 32-47-01											
324701-0204		RH LDG INDICATOR,BRAKE TEMPERATURE SENSOR							Component	ATA:32	
PN:0132AEV-3	MOS/MSC	25-Mar-11	O/C	TSN 0							
SN:K0535	HRS	4423.8	TSN 0								
	AFL	2322	TSN 0								
PROC. REF: AMM 32-47-01											
324702-0201		LEFT SIGNAL-BRAKE TEMPERATURE,WING STUB CONDITIONER							Component	ATA:32	
PN:0510GW2	MOS/MSC	O/C									
SN:2089	HRS										
	AFL	0									
PROC. REF: AMM 32-47-02											
324702-0202		RIGHT SIGNAL-BRAKE TEMPERATURE,WING STUB CONDITIONER							Component	ATA:32	
PN:0510GW2	MOS/MSC	O/C									
SN:2109	HRS										
	AFL	0									
PROC. REF: AMM 32-47-02											
324900-0001		LEFT NO.1 MAIN LANDING GEAR OUTBOARD WHEEL AND TIRE ASSEMBLY							Component	ATA:32	
PN:2309-2003-403	MOS/MSC	10-Jan-24	O/C								
SN:3642	HRS	10396.8									
	AFL	5532									
PROC. REF: AMM 32-49-01											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
324900-0002 LEFT NO. 2 MAIN LANDING GEAR INBOARD WHEEL AND TIRE ASSEMBLY Component ATA:32										
PN:2309-2003-401	MOS/MSC	01-Mar-22	O/C	TSR 0						
SN:3268	HRS	9819.3		TSR 0						
	AFL	5227		TSR 0						
PROC. REF: AMM 32-49-01										
324900-0003 RIGHT NO. 3 MAIN LANDING GEAR INBOARD WHEEL AND TIRE ASSEMBLY Component ATA:32										
PN:2309-2003-401	MOS/MSC	16-Oct-23	O/C							
SN:3302	HRS	10259.3								
	AFL	5461								
PROC. REF: AMM 32-49-01										
324900-0004 RIGHT NO. 4 MAIN LANDING GEAR OUTBOARD WHEEL AND TIRE ASSEMBLY Component ATA:32										
PN:2309-2003-403	MOS/MSC	16-Oct-23	O/C	TSR 19						
SN:3337	HRS	10259.3		TSR 440						
	AFL	5461		TSR 234						
PROC. REF: AMM 32-49-01										
324900-0101 LEFT NO. 1 MAIN LANDING GEAR OUTBOARD WHEEL ASSEMBLY Component ATA:32										
PN:3-1550-1	MOS/MSC	10-Jan-24	O/C							
SN:3642	HRS	10396.8								
	AFL	5532								
PROC. REF: AMM 32-49-02										
324900-0102 LEFT NO. 2 MAIN LANDING GEAR INBOARD WHEEL ASSEMBLY Component ATA:32										
PN:3-1550-1	MOS/MSC	01-Mar-22	O/C	TSR 0						
SN:3268	HRS	9819.3		TSR 0						
	AFL	5227		TSR 0						
PROC. REF: AMM 32-49-02										
324900-0103 RIGHT NO. 3 MAIN LANDING GEAR INBOARD WHEEL ASSEMBLY Component ATA:32										
PN:3-1550-1	MOS/MSC	16-Oct-23	O/C	TSR 17						
SN:3302	HRS	10259.3		TSR 383.6						
	AFL	5461		TSR 202						
PROC. REF: AMM 32-49-02										
324900-0104 RIGHT NO. 4 MAIN LANDING GEAR OUTBOARD WHEEL ASSEMBLY Component ATA:32										
PN:3-1550-1	MOS/MSC	16-Oct-23	O/C	TSR 19						
SN:3337	HRS	10259.3		TSR 440						
	AFL	5461		TSR 234						
PROC. REF: AMM 32-49-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
324900-0201 LEFT NO. 1 MAIN LANDING GEAR OUTBOARD TIRE Component ATA:32										
PN:304K63-2	MOS/MSC	10-Jan-24	O/C	TSN 0						
SN:32735231	HRS	10396.8		TSN 0						
	AFL	5532		TSN 0						
PROC. REF: AMM 32-49-01										
324900-0202 LEFT NO. 2 MAIN LANDING GEAR INBOARD TIRE Component ATA:32										
PN:304K63-2	MOS/MSC	01-Mar-22	O/C	TSN 0						
SN:11570308	HRS	9819.3		TSN 0						
	AFL	5227		TSN 0						
PROC. REF: AMM 32-49-01										
324900-0203 RIGHT NO. 3 MAIN LANDING GEAR INBOARD TIRE Component ATA:32										
PN:304K63-2	MOS/MSC	16-Oct-23	O/C	TSN 0						
SN:20200999	HRS	10259.3		TSN 0						
	AFL	5461		TSN 0						
PROC. REF: AMM 32-49-01										
324900-0204 RIGHT NO. 4 MAIN LANDING GEAR OUTBOARD TIRE Component ATA:32										
PN:304K63-2	MOS/MSC	16-Oct-23	O/C	TSN 0						
SN:23400868	HRS	10259.3		TSN 0						
	AFL	5461		TSN 0						
PROC. REF: AMM 32-49-01										
324900-0301 L/H WHEEL NLG ASSEMBLY Component ATA:32										
PN:3-1622	MOS/MSC	12-Jul-23	O/C	TSO 0						
SN:0392	HRS	10167.3		TSO 0						
	AFL	5404		TSO 0						
PROC. REF: AMM 32-49-05										
324900-0302 R/H WHEEL NLG ASSEMBLY Component ATA:32										
PN:3-1622	MOS/MSC	12-Jul-23	O/C	TSO 0						
SN:0518	HRS	10167.3		TSO 0						
	AFL	5404		TSO 0						
PROC. REF: AMM 32-49-05										
324900-0401 WHEEL NLG (LH) TIRE Component ATA:32										
PN:196K02B1	MOS/MSC	12-Jul-23	O/C	TSN 0						
SN:20580131	HRS	10167.3		TSN 0						
	AFL	5404		TSN 0						
PROC. REF: AMM 32-49-04										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
324900-0402 WHEEL NLG (RH) TIRE Component ATA:32										
PN:196K02B1	MOS/MSC	12-Jul-23	O/C	TSN 0						
SN:20570447	HRS	10167.3		TSN 0						
	AFL	5404		TSN 0						
PROC. REF: AMM 32-49-04										
324903-0101 NO. 1 CARBON ASSY-LEG,MAIN LANDING GEAR BRAKE Component ATA:32										
PN:2-1582OPT5	MOS/MSC	04-Aug-12	O/C	TSN 0						
SN:2723	HRS	6092		TSN 0						
	AFL	3243		TSN 0						
PROC. REF: AMM 32-49-03										
324903-0102 NO. 2 CARBON ASSY-LEG,MAIN LANDING GEAR BRAKE Component ATA:32										
PN:2-1582OPT5	MOS/MSC	06-Oct-12	O/C							
SN:1464	HRS	6307								
	AFL	3377								
PROC. REF: AMM 32-49-03										
324903-0103 NO. 3 CARBON ASSY-LEG,MAIN LANDING GEAR BRAKE Component ATA:32										
PN:2-1582	MOS/MSC	18-Aug-18	O/C	TSO 30						
SN:1968	HRS	8725.1		TSO 0						
	AFL	4681		TSO 0						
PROC. REF: AMM 32-49-03										
324903-0104 NO. 4 CARBON ASSY-LEG,MAIN LANDING GEAR BRAKE Component ATA:32										
PN:2-1582OPT5	MOS/MSC	25-Mar-11	O/C	TSO 0						
SN:1844	HRS	4423.8		TSO 0						
	AFL	2322		TSO 0						
PROC. REF: AMM 32-49-03										
325001-0101 CSL CENT BOX CONTROL -STEERING, MANUAL, NOSE LANDING GEAR ASSEMBLY Component ATA:32										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-50-01										
325003-0101 C FLOOR BOX ELECTRONIC-STEERING CONTROL, NOSE LANDING GEAR ASSEMBLY Component ATA:32										
PN:308560-1019	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:1579	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-50-03										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
325004-0101 MID HYDRALIC-STEERING SYS CONTROL, NOSE LDG MODULE Component ATA:32										
PN:308570-1011	MOS/MSC	01-Feb-19	O/C	TSR 67						
SN:1187	HRS	8932.1		TSR 0						
	AFL	4776		TSR 0						
PROC. REF: AMM 32-50-04										
325006-0101 NLG STEERING PROXIMITY SWITCH Component ATA:32										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-50-06										
326101-0101 LH MLG UPLOCK 'A' PROXIMITY SWITCH Component ATA:32										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-61-01										
326101-0102 RH MLG UPLOCK 'A' PROXIMITY SWITCH Component ATA:32										
PN:80-057-01	MOS/MSC	04-Aug-10	O/C	TSN 0						
SN:17781	HRS	3628.6		TSN 0						
	AFL	1907		TSN 0						
PROC. REF: AMM 32-61-01										
326101-0103 LH MLG UPLOCK 'B' PROXIMITY SWITCH Component ATA:32										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-61-01										
326101-0104 RH MLG UPLOCK 'B' PROXIMITY SWITCH Component ATA:32										
PN:80-057-01	MOS/MSC	04-Aug-10	O/C	TSN 0						
SN:25626	HRS	3628.6		TSN 0						
	AFL	1907		TSN 0						
PROC. REF: AMM 32-61-01										
326102-0101 LH MLG DOWNLOCK 'A' PROXIMITY SWITCH Component ATA:32										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-61-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
326102-0102 RH MLG DOWNLOCK 'A' PROXIMITY SWITCH Component ATA:32										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-61-02										
326102-0103 LH MLG DOWNLOCK 'B' PROXIMITY SWITCH Component ATA:32										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-61-02										
326102-0104 RH MLG DOWNLOCK 'B' PROXIMITY SWITCH Component ATA:32										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-61-02										
326301-0101 LH MLG WOW #1 PROXIMITY SWITCH Component ATA:32										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-63-01										
326301-0102 RH MLG WOW #1 PROXIMITY SWITCH Component ATA:32										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-63-01										
326301-0103 LH MLG WOW #2 PROXIMITY SWITCH Component ATA:32										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-63-01										
326301-0104 RH MLG WOW #2 PROXIMITY SWITCH Component ATA:32										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-63-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
326302-0101 NLG WOW PROXIMITY SWITCH Component ATA:32										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-63-01										
326303-0101 NLG SEQUENCE DOOR PROXIMITY SWITCH Component ATA:32										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-63-03										
326304-0101 NLG OPEN DOOR PROXIMITY SWITCH Component ATA:32										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-63-04										
326304-0102 NLG OPEN DOOR PROXIMITY SWITCH Component ATA:32										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-63-04										
329500-0313 NLG PROXIMITY SWITCH Component ATA:32										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-50-06										
329500-0314 NLG PROXIMITY SWITCH Component ATA:32										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-50-06										
329500-0315 NLG PROXIMITY SWITCH Component ATA:32										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-50-06										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 32 - LANDING GEAR											
329500-0316		NLG PROXIMITY SWITCH								Component	ATA:32
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 32-50-06											
ATA 33 - LIGHTS											
33-12-00-710-002-A00 ^S		OPERATIONALLY CHECK COCKPIT PUSHBUTTON LIGHTING								Service	ATA:33
	MOS/MSC	29-Jun-23	N/A								
	HRS	10161.5									
	AFL	5401									
PROC. REF: AMM 33-12-00											
PKG:5004											
33-47-03-720-001-A00 ^S		FUNCTIONALLY CHECK INTENSITY OF WHITE STROBE LIGHTING SYSTEM.NOTE: THIS TASK IS APPLICABLE ONLY TO AIRCRAFT UNDER ANAC/FAA CERTIFICATIONS.								Service	ATA:33
	MOS	06-Jul-19	72 (+15d/-15d)	LOW UTILIZATION							
	HRS	9057.4	3000 (+20/-20)								
	AFL	4853	1500 (+20/-20)								
PROC. REF: AMM 33-47-03											
PKG:5012											
33-50-00-710-001-A00 ^S		OPERATIONALLY CHECK EMERGENCY LIGHTING SYSTEM								Service	ATA:33
	MOS	16-Aug-24	12 (+15d/-15d)	LOW UTILIZATION							
	HRS	10541.4	500 (+20/-20)								
	AFL	5613									
PROC. REF: AMM 33-50-00											
PKG:5002											
33-50-04-720-001-A00		FUNCTIONALLY CHECK NO. 1 DLE EMERGENCY LIGHTING SYSTEM BATTERY POWER SUPPLY NOTE: IF INSTALLED NOTE: FROM THE MANUFACTURE DATE OR LAST TASK ACCOMPLISHMENT.								Service	ATA:33
PN:8ES360000-00	MOS	16-Aug-24	6 (+15d/-15d)	16-Feb-25	03-Mar-25	93 d (+15)					
SN:303084	HRS	10541.4									
	AFL	5613									
PROC. REF: AMM 33-50-04											
33-50-04-720-001-A00		FUNCTIONALLY CHECK NO. 2 DLE EMERGENCY LIGHTING SYSTEM BATTERY POWER SUPPLY NOTE: IF INSTALLED NOTE: FROM THE MANUFACTURE DATE OR LAST TASK ACCOMPLISHMENT.								Service	ATA:33
PN:8ES360000-00	MOS	16-Aug-24	6 (+15d/-15d)	16-Feb-25	03-Mar-25	93 d (+15)					
SN:321029	HRS	10541.4									
	AFL	5613									
PROC. REF: AMM 33-50-04											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 33 - LIGHTS										
33-50-04-720-001-A01 FUNCTIONALLY CHECK NO.1 EMERGENCY-NICAD,6VDC,5 AH BATTERY RADIANT OR BRUCE MODEL IF INSTALLED.										Service ATA:33
PN:8ES360000-00	MOS/MSC	01-Jul-24	N/A							
SN:303084	HRS	10503.9								
	AFL	5592								
PROC. REF: AMM 33-50-04										
33-50-04-720-001-A01 FUNCTIONALLY CHECK NO.2 EMERGENCY-NICAD,6VDC,5 AH BATTERY RADIANT OR BRUCE MODEL IF INSTALLED.										Service ATA:33
PN:8ES360000-00	MOS/MSC	01-Jul-24	N/A							
SN:321029	HRS	10503.9								
	AFL	5592								
PROC. REF: AMM 33-50-04										
33-51-01-720-001-A00 ^S FUNCTIONALLY CHECK FLASHLIGHTS RECHARGEABLE BATTERIES (IF INSTALLED)										Service ATA:33
	MOS	16-Aug-24	12 (+15d/-15d)					LOW UTILIZATION		
	HRS	10541.4	500 (+20/-20)							
	AFL	5613								
PROC. REF: AMM 33-51-01										PKG:5002
33-51-01-720-001-A01 ^S FUNCTIONALLY CHECK FLASHLIGHTS NON-RECHARGEABLE BATTERIES (IF INSTALLED)										Service ATA:33
	MOS	16-Aug-24	12 (+15d/-15d)					LOW UTILIZATION		
	HRS	10541.4	500 (+20/-20)							
	AFL	5613								
PROC. REF: AMM 33-51-01										PKG:5002
33-51-03-960-001-A00 DISCARD NON RECHARGEABLE FLASHLIGHT BATTERY PACK NOTE: IF INSTALLED										Service ATA:33
	MOS	29-Jun-23	24 (+30d/-30d)	Adj 26d	25-Jul-25	24-Aug-25	252 d (+30)	SYSTEM		
	HRS	10161.5								
	AFL	5401								
PROC. REF: AMM 33-51-01										
330000-0101 OVERH P MODULE -INTERNAL LT CONT ASSEMBLY										Component ATA:33
PN:145-32843-405	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:0000137145	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										
330000-0201 OVERH P MODULE -EXT/CKPT/PAX LT CONTROL ASSEMBLY										Component ATA:33
PN:145-21338-401	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:0000139956	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 33 - LIGHTS										
330000-0301 OVERH P CONTROL ASSY-EXTERNAL NAVIGATION LIGHT,COCKPIT MODULE										Component ATA:33
PN:145-21335-401	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:0000140789	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										
330000-0401 OVERH P CONTROL ASSY-OVERHEAD PANEL EXTERNAL LIGHT,LDG,COCKPIT MODULE										Component ATA:33
PN:145-21332-401	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:0000139852	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										
331100-0101 CREW CAB LIGHT READING,COCKPIT CEILING ASSEMBLY										Component ATA:33
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-11-04										
331100-0102 CREW CAB LIGHT READING,COCKPIT CEILING ASSEMBLY										Component ATA:33
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-11-04										
331100-0103 CREW CAB LIGHT READING,COCKPIT CEILING ASSEMBLY										Component ATA:33
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-11-04										
331202-0101 NOSE DIMMER										Component ATA:33
PN:1826-1	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-12-01										
331202-0102 NOSE DIMMER										Component ATA:33
PN:1826-1	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-12-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 33 - LIGHTS											
331202-0103		NOSE DIMMER								Component	ATA:33
PN:1826-1	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 33-12-01											
331202-0104		NOSE DIMMER								Component	ATA:33
PN:1826-1	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 33-12-01											
331202-0105		NOSE DIMMER								Component	ATA:33
PN:1826-1	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 33-12-01											
331202-0106		NOSE DIMMER								Component	ATA:33
PN:1826-1	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 33-12-01											
331501-0101		CSL CENT PROJECTOR, GLARESHIELD CENTRAL CONSOLE, COCKPIT PANEL								Component	ATA:33
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: NDT GENERIC											
331501-0102		CSL CENT PROJECTOR, GLARESHIELD CENTRAL CONSOLE, COCKPIT PANEL								Component	ATA:33
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: NDT GENERIC											
331501-0103		CSL CENT PROJECTOR, GLARESHIELD CENTRAL CONSOLE, COCKPIT PANEL								Component	ATA:33
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: NDT GENERIC											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 33 - LIGHTS										
331503-0101 LH CSL LEFT,MAIN PANEL,CTL CONSOLE INVERTER Component ATA:33										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-15-02										
331503-0102 RH CSL RIGHT,MAIN PANEL,CTL CONSOLE INVERTER Component ATA:33										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-15-02										
332802-0101 NO. 1 LAVATORY LIGHT BALLAST - LAMP INVERTER Component ATA:33										
PN:189-720	MOS/MSC	29-Jun-23	O/C	TSN 0						
SN:15382	HRS	10161.5		TSN 0						
	AFL	5401		TSN 0						
PROC. REF: AMM 33-28-02										
334502-0101 UPPER LIGHT NAVIGATION,RED STROBE LIGHT ASSEMBLY Component ATA:33										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-47-05										
334503-0101 CENT FUS POWER,SUPPLY-ELECTRICAL,RED STROBE LIGHT Component ATA:33										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-47-02										
334702-0101 STROBE LIGHT POWER SUPPLY Component ATA:33										
PN:60-5096-1	MOS/MSC	11-Jul-10	O/C							
SN:3488	HRS	3539.9								
	AFL	1859								
PROC. REF: AMM 33-47-02										
334702-0201 LH WING STROBE LIGHT POWER SUPPLY Component ATA:33										
PN:60-5096-1	MOS/MSC	06-Apr-23	O/C							
SN:3543	HRS	10102.6								
	AFL	5373								
PROC. REF: AMM 33-47-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 33 - LIGHTS											
334702-0202		RH WING STROBE LIGHT POWER SUPPLY								Component	ATA:33
PN:60-5096-1	MOS/MSC	06-Apr-23	O/C	TSR 2							
SN:4014	HRS	10102.6		TSR 0							
	AFL	5373		TSR 0							
PROC. REF: AMM 33-47-02											
335002-0101		NO. 1 EMERGENCY LIGHTING SYSTEM POWER SUPPLY ASSEMBLY								Component	ATA:33
PN:3400-22-10	MOS/MSC	16-Aug-24	O/C	TSN 50, TSR 20							
SN:015146	HRS	10541.4		TSN 1033.5, TSR 483.2							
	AFL	5613		TSN 553, TSR 273							
PROC. REF: AMM 33-50-04											
335002-0102		NO. 2 EMERGENCY LIGHTING SYSTEM POWER SUPPLY ASSEMBLY								Component	ATA:33
PN:3400-22-10	MOS/MSC	16-Aug-24	O/C	TSR 20							
SN:001186	HRS	10541.4		TSR 483.2							
	AFL	5613		TSR 273							
PROC. REF: AMM 33-50-04											
335004-0101		NO.1 EMERGENCY-NICAD,6VDC,5 AH BATTERY								Component	ATA:33
PN:8ES360000-00	MOS/MSC	16-Aug-24	O/C								
SN:303084	HRS	10541.4		TSN 37.5							
	AFL	5613		TSN 21							
Manufacture Date:: 31-Jan-24 PROC. REF: AMM 33-50-04											
335004-0102		NO.2 EMERGENCY-NICAD,6VDC,5 AH BATTERY								Component	ATA:33
PN:8ES360000-00	MOS/MSC	16-Aug-24	O/C								
SN:321029	HRS	10541.4		TSN 37.5							
	AFL	5613		TSN 21							
Manufacture Date:: 31-Jan-24 PROC. REF: AMM 33-50-04											
ATA 34 - NAVIGATION											
34-01-00-720-001-A00		FUNCTIONALLY CHECK INTEGRATED STANDBY INSTRUMENT SYSTEM - ISIS								Service	ATA:34
	MOS	29-Jun-23						SYSTEM			
	HRS	10161.5	5000		15161.5		4565.9				
	AFL	5401									
PROC. REF: AMM 34-01-01											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
34-01-CA-200	FUNCTIONALLY CHECK INTEGRATED STANDBY INSTRUMENT SYSTEM - ISIS (PER LOCAL AUTHORITY)									Service ATA:34
	MOS	29-Jun-23	24		29-Jun-25		226 d			
	HRS	10161.5								
	AFL	5401								
PROC. REF: AMM 34-01-01										
34-13-00-610-001-A00	SERVICE (CLEANING) PITOT AND STATIC SYSTEM									Service ATA:34
	MOS	29-Jun-23	72 (+30d/-30d)		29-Jun-29	29-Jul-29	1687 d (+30)	SYSTEM		
	HRS	10161.5	8000		18161.5		7565.9			
	AFL	5401								
PROC. REF: AMM 34-13-00, FAR FAR 43 APPENDIX E, FAR FAR 91.411 / 91.217										
34-13-00-680-001-A00 ^S	SERVICE (DRAIN) PITOT LINES									Service ATA:34
	MOS	16-Aug-24	12 (+15d/-15d)					LOW UTILIZATION		
	HRS	10541.4	500 (+20/-20)							
	AFL	5613								
PROC. REF: AMM 34-13-00, FAR FAR 43 APPENDIX E, FAR FAR 91.411 / 91.217										PKG:5002
34-13-00-790-001-A00	FUNCTIONALLY CHECK PITOT-STATIC SYSTEM FOR LEAKAGE									Service ATA:34
	MOS	29-Jun-23						SYSTEM		
	HRS	10161.5	5000		15161.5		4565.9			
	AFL	5401								
PROC. REF: AMM 34-13-00, FAR FAR 43 APPENDIX E, FAR FAR 91.411 / 91.217										
34-13-04-280-001-A00	INSPECT (SPECIAL INSPECTION) RVSM CRITICAL REGION (SKIN) FOR WAVINESS									Service ATA:34
	MOS	29-Jun-23	48 (+30d/-30d)	Adj 7d	06-Jul-27	05-Aug-27	963 d (+30)			
	HRS	10161.5	5000		15161.5		4565.9			
	AFL	5401								
PROC. REF: AMM 34-13-04										
34-13-04-280-002-A00	INSPECT (SPECIAL INSPECTION) STATIC PORT SURROUNDING PLATE FOR FLUSHNESS AND INTEGRITYNOTE: ONLY FOR RVSM OPERATION									Service ATA:34
	MOS	29-Jun-23	48 (+30d/-30d)	Adj 7d	06-Jul-27	05-Aug-27	963 d (+30)			
	HRS	10161.5	5000		15161.5		4565.9			
	AFL	5401								
PROC. REF: AMM 34-13-04										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 34 - NAVIGATION											
34-13-04-280-003-A00		INSPECT (SPECIAL INSPECTION) OXYGEN SERVICE PANEL FOR FLUSHNESS AND INTEGRITY (PASSENGER GASEOUS OXYGEN SYSTEM ONLY) NOTE: IF INSTALLED							Service	ATA:34	
	MOS	29-Jun-23	48 (+30d/-30d)	Adj 7d	06-Jul-27	05-Aug-27	963 d (+30)				
	HRS	10161.5	5000		15161.5		4565.9				
	AFL	5401									
PROC. REF: AMM 34-13-04											
34-13-CA-201		FUNCTIONALLY CHECK PITOT-STATIC SYSTEM FOR LEAKAGE (PER LOCAL AUTHORITY)							Service	ATA:34	
	MOS	29-Jun-23	24		29-Jun-25		226 d				
	HRS	10161.5									
	AFL	5401									
PROC. REF: AMM 34-13-00											
34-15-00-720-001-A00		FUNCTIONALLY CHECK NO. 1 AIR DATA COMPUTER (ADC) SYSTEM							Service	ATA:34	
PN:7014700-627	MOS	29-Jun-23						SYSTEM			
SN:07027821	HRS	10161.5	5000		15161.5		4565.9				
	AFL	5401									
PROC. REF: AMM 34-15-00											
34-15-00-720-001-A00		FUNCTIONALLY CHECK NO. 2 AIR DATA COMPUTER (ADC) SYSTEM							Service	ATA:34	
PN:7014700-627	MOS	29-Jun-23						SYSTEM			
SN:07027816	HRS	10161.5	5000		15161.5		4565.9				
	AFL	5401									
PROC. REF: AMM 34-15-00											
34-15-CA-200		FUNCTIONALLY CHECK NO. 1 AIR DATA COMPUTER (ADC) SYSTEM (PER LOCAL AUTHORITY)							Service	ATA:34	
	MOS	29-Jun-23	24		29-Jun-25		226 d				
	HRS	10161.5									
	AFL	5401									
PROC. REF: AMM 34-15-00											
34-15-CA-200		FUNCTIONALLY CHECK NO. 2 AIR DATA COMPUTER (ADC) SYSTEM (PER LOCAL AUTHORITY)							Service	ATA:34	
	MOS	29-Jun-23	24		29-Jun-25		226 d				
	HRS	10161.5									
	AFL	5401									
PROC. REF: AMM 34-15-00											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
34-21-03-140-001-A00 RESTORE (CLEANING) AHRS FAN FILTER (NOTE: IF INSTALLED) Service ATA:34										
	MOS/MSC	30-Jun-15	N/A					SYSTEM		
	HRS	7460.3								
	AFL	3992								
PROC. REF: AMM 34-21-03										
34-25-00-720-001-A00 FUNCTIONALLY CHECK STANDBY COMPASS FOR PROPER COMPENSATION Service ATA:34										
PN:PGA1001WG	MOS	29-Jun-23	24 (+30d/-30d)	Adj 7d	06-Jul-25	05-Aug-25	233 d (+30)	SYSTEM		
SN:702130-02	HRS	10161.5								
	AFL	5401								
PROC. REF: AMM 34-25-00										
34-27-03-140-001-A00 ^S RESTORE (CLEANING) DUAL IRS MOUNTING TRAY FAN FILTER (NOTE: IF INSTALLED). Service ATA:34										
	MOS	16-Aug-24	12 (+15d/-15d)					LOW UTILIZATION		
	HRS	10541.4	500 (+20/-20)							
	AFL	5613								
PROC. REF: AMM 34-27-03										
34-41-00-710-003-A00 ^S OPERATIONALLY CHECK EGPWS/WINDSHEAR Service ATA:34										
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
PROC. REF: AMM 34-41-00										
34-52-00-720-001-A00 FUNCTIONALLY CHECK NO. 1 TRANSPONDER SYSTEM Service ATA:34										
	MOS	29-Jun-23	24 (+30d/-30d)	Adj 23d	22-Jul-25	21-Aug-25	249 d (+30)	SYSTEM		
	HRS	10161.5								
	AFL	5401								
PROC. REF: AMM 34-52-00, FAR FAR 91.217 / 91.413										
34-52-00-720-001-A00 FUNCTIONALLY CHECK NO. 2 TRANSPONDER SYSTEM Service ATA:34										
	MOS	29-Jun-23	24 (+30d/-30d)	Adj 23d	22-Jul-25	21-Aug-25	249 d (+30)	SYSTEM		
	HRS	10161.5								
	AFL	5401								
PROC. REF: AMM 34-52-00, FAR FAR 91.217 / 91.413										
34-61-00-470-801A ^U PERFORM NAVIGATION DATABASE UPDATE Service ATA:34										
	DAYS/MSC	15-Oct-24	DUE		27-Nov-24 (M)		12 d	CUSTOMER CODE		
	HRS	10578.1								
	AFL	5634								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
34-63-01-720-001-A00	FUNCTIONALLY CHECK ELECTRONIC FLIGHT BAG DISPLAY UNIT (EDU), BATTERY CAPACITY. NOTE: ONLY FOR AIRCRAFT EQUIPPED WITH EFB.									Service ATA:34
	MOS/MSC	03-Jul-15	N/A							
	HRS	7460.3								
	AFL	3992								
PROC. REF: AMM 34-63-02										
340101-0101	CSL CENT CONTROL-INTEGRATED STANDBY INSTRUMENT SYS UNIT									Component ATA:34
PN:C16221GD04	MOS/MSC		O/C							
SN:C16221008390	HRS									
	AFL	0								
PROC. REF: AMM 34-01-01										
340101-0101A ^U	RECERTIFY CSL CENT CONTROL-INTEGRATED STANDBY INSTRUMENT SYS UNIT PER FAR 91.411									Service ATA:34
PN:C16221GD04	MOS	29-Jun-23	24		29-Jun-25		226 d	FAR		
SN:C16221008390	HRS	10161.5								
	AFL	5401								
PROC. REF: FAR FAR 91.411										
341300-0101	LEFT PITOT-ANEMOMETRIC SYSTEM,NICKEL TUBE									Component ATA:34
PN:0851HU3	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:251171	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-13-01										
341300-0102	RIGHT PITOT-ANEMOMETRIC SYSTEM,NICKEL TUBE									Component ATA:34
PN:0851HU3	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:251173	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-13-01										
341300-0201	FORWARD TUBE,PITOT STATIC-ANEMOMETRIC FWD FUSLG SYSTEM									Component ATA:34
PN:0856NF	MOS/MSC	02-Apr-19	O/C	TSN 1						
SN:311409	HRS	8972.4		TSN 0						
	AFL	4803		TSN 0						
PROC. REF: AMM 34-13-01										
341300-0401	LEFT UP PORT,STATIC-HEATED,PRESSURIZATION 28VDC SYSTEM									Component ATA:34
PN:ST-300-2PTH	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-13-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 34 - NAVIGATION											
341300-0402		LEFT LW PORT,STATIC-HEATED,PRESSURIZATION 28VDC SYSTEM							Component	ATA:34	
PN:ST-300-2PTH	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 34-13-00											
341300-0403		RIGHT UP PORT,STATIC-HEATED,PRESSURIZATION 28VDC SYSTEM							Component	ATA:34	
PN:ST-300-2PTH	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 34-13-00											
341300-0404		RIGHT LW PORT,STATIC-HEATED,PRESSURIZATION 28VDC SYSTEM							Component	ATA:34	
PN:ST-300-2PTH	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 34-13-00											
341501-0101		NO. 1 AIR DATA COMPUTER (ADC)							Component	ATA:34	
PN:7014700-627	MOS/MSC	O/C									
SN:07027821	HRS										
	AFL	0									
PROC. REF: AMM 34-15-01											
341501-0101B ^U		RECERTIFY NO.1 COMPUTER PER FAR 91.411							Service	ATA:34	
PN:7014700-627	MOS	29-Jun-23	24	29-Jun-25		226 d	FAR				
SN:07027821	HRS	10161.5									
	AFL	5401									
PROC. REF: FAR FAR 91.411											
341501-0102		NO. 2 AIR DATA COMPUTER (ADC)							Component	ATA:34	
PN:7014700-627	MOS/MSC	O/C									
SN:07027816	HRS										
	AFL	0									
PROC. REF: AMM 34-15-01											
341501-0102B ^U		RECERTIFY NO.2 COMPUTER PER FAR 91.411							Service	ATA:34	
PN:7014700-627	MOS	29-Jun-23	24	29-Jun-25		226 d	FAR				
SN:07027816	HRS	10161.5									
	AFL	5401									
PROC. REF: FAR FAR 91.411											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
341502-0101 NOSE TOTAL TEMPERATURE SENSOR Component ATA:34										
PN:102AU1AF	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: AMM 34-15-03										
341502-0102 CREW CAB TOTAL, TEMPERATURE SENSOR Component ATA:34										
PN:102AU1AF	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: AMM 34-15-03										
342201-0101 EICAS DISPLAY, EICAS/PFD/MFD SYS, MAIN PANEL UNIT Component ATA:34										
PN:7014300-901	MOS/MSC		24-Mar-23	O/C	TSN 187					
SN:0703G201	HRS		10087.9		TSN 10087.9					
	AFL		5364		TSN 5364					
PROC. REF: AMM 31-41-02										
342201-0102 MFD 1 DISPLAY, EICAS/PFD/MFD SYS, MAIN PANEL UNIT Component ATA:34										
PN:7014300-901	MOS/MSC		28-Feb-09	O/C	TSN 0					
SN:0309C903	HRS		1849.1		TSN 0					
	AFL		966		TSN 0					
PROC. REF: AMM 31-41-02										
342201-0103 MFD 2 DISPLAY, EICAS/PFD/MFD SYS, MAIN PANEL UNIT Component ATA:34										
PN:7014300-901	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:0703G202	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: AMM 31-41-02										
342201-0104 PFD 1 DISPLAY, EICAS/PFD/MFD SYS, MAIN PANEL UNIT Component ATA:34										
PN:7014300-901	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:96101681	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: AMM 31-41-02										
342201-0105 PFD 2 DISPLAY, EICAS/PFD/MFD SYS, MAIN PANEL UNIT Component ATA:34										
PN:7014300-901	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:0703G205	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: AMM 31-41-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 34 - NAVIGATION											
342202-0101		CONTROL-PFD SYS, MAIN PANEL								Component	ATA:34
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 34-22-02											
342202-0102		CONTROL-PFD SYS, MAIN PANEL								Component	ATA:34
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 34-22-02											
342202-0103		CONTROL-MFD SYS,MAIN PANEL								Component	ATA:34
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 34-22-02											
342202-0104		CONTROL-MFD SYS,MAIN PANEL								Component	ATA:34
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 34-22-02											
342204-0101		CREW CAB MODULE -REVERSIONARY PANEL ASSEMBLY								Component	ATA:34
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 34-22-03											
342204-0102		CREW CAB MODULE -REVERSIONARY PANEL ASSEMBLY								Component	ATA:34
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 34-22-03											
342205-0101		CREW CAB CONTROL-DISPLAY,FGC,GLARESHIELD PANEL UNIT								Component	ATA:34
PN:7016986-505	MOS/MSC	21-Jun-10	O/C								
SN:03125221	HRS	3461.1									
	AFL	1818									
PROC. REF: NDT GENERIC											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 34 - NAVIGATION											
342205-0102		CREW CAB CONTROL-DISPLAY,FGC,GLARESHIELD PANEL UNIT							Component	ATA:34	
PN:7016986-505	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:07016649	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: NDT GENERIC											
342206-0101		PILOT DEVICE-CONTROL,CURSOR,MC-800 UNIT							Component	ATA:34	
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 34-22-05											
342206-0102		COPILOT DEVICE-CONTROL,CURSOR,MC-800 UNIT							Component	ATA:34	
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 34-22-05											
342501-0101		MAGNETIC-NAV SYS - WINDSHIELD MOUNTING BRACKET COMPASS							Component	ATA:34	
PN:PGA1001WG	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:702130-02	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 34-25-01											
342701-0101		NOSE INERTIAL REFERENCE UNIT							Component	ATA:34	
PN:HG2001GD03	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:56015315	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 34-27-01											
342701-0102		NOSE INERTIAL REFERENCE UNIT							Component	ATA:34	
PN:HG2001GD03	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:56015276	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 34-27-01											
342703-0101		CREW CAB MODE SELECT UNIT							Component	ATA:34	
PN:CG1042AB03	MOS/MSC	06-Nov-14	O/C	TSR 18							
SN:56009073	HRS	7222.5		TSR 0							
	AFL	3865		TSR 0							
PROC. REF: AMM 34-27-02											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
342703-0102 CREW CAB MODE SELECT UNIT Component ATA:34										
PN:CG1042AB03	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:73731029	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-27-02										
343101-0101 LH RADIO ALTIMETER UNIT Component ATA:34										
PN:7001840-937	MOS/MSC	03-Jan-12	O/C							
SN:01049215	HRS	5261.9								
	AFL	2792								
PROC. REF: AMM 34-31-01										
343101-0102 RH RADIO ALTIMETER UNIT Component ATA:34										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-31-01										
343102-0101 NAVIGATION SYSTEM - RADIO ALTIMETER ANTENNA Component ATA:34										
PN:S67-2002	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-31-02										
343102-0102 NAVIGATION SYSTEM - RADIO ALTIMETER ANTENNA Component ATA:34										
PN:S67-2002	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-31-02										
343102-0201 NAVIGATION SYSTEM - RADIO ALTIMETER ANTENNA Component ATA:34										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-31-02										
343102-0202 NAVIGATION SYSTEM - RADIO ALTIMETER ANTENNA Component ATA:34										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-31-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
343200-0101 NOSE COUPLER Component ATA:34										
PN:DMB-20-20	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:1823	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: NDT GENERIC										
343201-0101 NOSE NAV/ADF/DME,INTEGRATED,NAVIGATION SYS UNIT Component ATA:34										
PN:7510100-631	MOS/MSC		29-Jun-09	O/C						
SN:97052239	HRS		2226.4							
	AFL		1167							
PROC. REF: AMM 34-32-01										
343201-0102 NOSE NAV/ADF/DME,INTEGRATED,NAVIGATION SYS UNIT Component ATA:34										
PN:7510100-631	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:0701B021	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: AMM 34-32-01										
343202-0101 CREW CAB CONTROL-EMERGENCY,NAVIGATION/COMMUNICATION SYS UNIT Component ATA:34										
PN:PN	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: NDT GENERIC										
343203-0101 NOSE DUAL GLIDE SLOPE ANTENNA Component ATA:34										
PN:S41422-2	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:111-5806	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: AMM 34-32-05										
343204-0101 LOWER MARKER BEACON ANTENNA Component ATA:34										
PN:3165-82	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:316582-813	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: AMM 34-32-04										
343205-0101 REAR VOR-LOC ANTENNA Component ATA:34										
PN:19-78	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: AMM 34-32-03										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 34 - NAVIGATION											
343205-0102		REAR VOR-LOC ANTENNA								Component	ATA:34
PN:19-78	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 34-32-03											
343205-0201		REAR DIVIDER,ANTENNA,VOR/ILS/MB SYS COUPLER								Component	ATA:34
PN:C1120-7	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:143362	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 34-32-12											
344101-0101		L/H CSL EGPWS,NAVIGATION,COCKPIT CONTROL UNIT								Component	ATA:34
PN:965-0976-040-216-216	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:25664	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 34-41-01											
344201-0101		NOSE WEATHER RADAR TRANSCEIVER								Component	ATA:34
PN:7021450-801	MOS/MSC	04-Aug-12	O/C	TSN 0							
SN:08028209	HRS	6092	TSN 0								
	AFL	3243	TSN 0								
PROC. REF: AMM 34-42-01											
344202-0101		CSL CENT PANEL CONTROL WEATHER RADAR ASSEMBLY								Component	ATA:34
PN:7008471-407	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 34-42-02											
344202-0102		CSL CENT PANEL CONTROL WEATHER RADAR ASSEMBLY								Component	ATA:34
PN:7008471-407	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 34-42-02											
344301-0101		TCAS PROCESSOR UNIT								Component	ATA:34
PN:7517900-55020	MOS/MSC	07-Aug-13	O/C	TSN 0							
SN:20008822	HRS	6643.4	TSN 0								
	AFL	3572	TSN 0								
PROC. REF: AMM 34-43-01											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 34 - NAVIGATION											
344302-0101		TCAS ANTENNA								Component	ATA:34
PN:7514081-915	MOS/MSC	05-May-18	O/C								
SN:ANE52939	HRS	8585.1									
	AFL	4609									
PROC. REF: AMM 34-43-03, AMM 34-43-02											
344303-0101		BAND 'L' (DME/TDR) ANTENNA								Component	ATA:34
PN:2430-87-00	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 34-43-03											
344303-0102		TDR TOP BAND 'L' (DME/TDR) ANTENNA								Component	ATA:34
PN:2430-87-00	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 34-43-03											
344303-0103		TDR BOT BAND 'L' (DME/TDR) ANTENNA								Component	ATA:34
PN:2430-87-00	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 34-43-03											
344303-0104		DMEL BAND 'L' (DME/TDR) ANTENNA								Component	ATA:34
PN:2430-87-00	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 34-43-03											
344303-0105		BAND 'L' (DME/TDR) ANTENNA								Component	ATA:34
PN:2430-87-00	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 34-43-03											
345203-0101		NOSE COAXIAL RELAY								Component	ATA:34
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: NDT GENERIC											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 34 - NAVIGATION											
345203-0102		NOSE COAXIAL RELAY								Component	ATA:34
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: NDT GENERIC											
345302-0201		NO. 1 ADF ANTENNA								Component	ATA:34
PN:7510300-901	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:0610B051	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 34-53-02											
345302-0202		NO. 2 ADF ANTENNA								Component	ATA:34
PN:7510300-901	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:0610B052	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 34-53-02											
345401-0101		REAR COMPARTMENT RECEIVER, XM RECEIVER								Component	ATA:34
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 34-54-01											
345402-0101		CENTER FUSELAGE - XM - WEATHER DATA, XMRANT ANTENNA								Component	ATA:34
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 34-54-02											
345601-0101		CENT FUS SENSOR,GPS,RADIO/NAVIGATION SYS (GNSSU) UNIT								Component	ATA:34
PN:HG2021GD04	MOS/MSC	19-Aug-15	O/C	TSR 0							
SN:0629	HRS	7460.3		TSR 0							
	AFL	3992		TSR 0							
PROC. REF: AMM 34-56-01											
345601-0102		CENT FUS SENSOR,GPS,RADIO/NAVIGATION SYS (GNSSU) UNIT								Component	ATA:34
PN:100-601944-300	MOS/MSC	14-Oct-15	O/C								
SN:0200	HRS	7523.8									
	AFL	4025									
PROC. REF: AMM 34-56-01											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 34 - NAVIGATION											
345602-0201		GPS 1 GPS ANTENNA								Component	ATA:34
PN:S67-1575-135	MOS/MSC		27-Sep-17	O/C	TSN 12						
SN:818-6999	HRS		8319.4		TSN 0						
	AFL		4456		TSN 0						
PROC. REF: AMM 34-56-02											
345602-0202		GPS 2 GPS ANTENNA								Component	ATA:34
PN:S67-1575-135	MOS/MSC		19-Aug-15	O/C	TSN 0						
SN:UNKNOWN	HRS		7460.3		TSN 0						
	AFL		3992		TSN 0						
PROC. REF: AMM 34-56-02											
346201-0101		NOSE FMS COMPUTER								Component	ATA:34
PN:7018879-03044	MOS/MSC		24-Feb-16	O/C							
SN:07044534	HRS		7661.9								
	AFL		4095								
PROC. REF: AMM 34-61-01											
346201-0102		NOSE FMS COMPUTER								Component	ATA:34
PN:7018879-03044	MOS/MSC		01-Sep-17	O/C	TSR 0						
SN:07124588	HRS		8284.1		TSR 0						
	AFL		4446		TSR 0						
PROC. REF: AMM 34-61-01											
346202-0101		CSL CENT CONTROL AND DISPLAY (FMS) UNIT								Component	ATA:34
PN:G7830-03	MOS/MSC		20-Feb-20	O/C							
SN:56657	HRS		9313.5								
	AFL		4970								
PROC. REF: AMM 34-61-02											
346202-0102		CSL CENT CONTROL AND DISPLAY (FMS) UNIT								Component	ATA:34
PN:G7830-03	MOS/MSC		20-Feb-20	O/C							
SN:56656	HRS		9313.5								
	AFL		4970								
PROC. REF: AMM 34-61-02											
346206-0101		CSL CENT DATA,LOADER-DUAL FMS/GPS SYS,CREW CABIN UNIT								Component	ATA:34
PN:G7226-01	MOS/MSC		05-Feb-14	O/C	TSR 0						
SN:1960	HRS		6867.7		TSR 0						
	AFL		3686		TSR 0						
PROC. REF: AMM 34-61-03											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 34 - NAVIGATION											
346207-0101		NOSE CONFIGURATION-FMS,NAVIGATION SYS MODULE								Component	ATA:34
PN:7014940-902	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 34-61-04											
346207-0102		NOSE CONFIGURATION-FMS,NAVIGATION SYS MODULE								Component	ATA:34
PN:7014940-902	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 34-61-04											
346301-0101		CENTER CONSOLE LH EXPANSION MODULE(EMU),CMA UNIT								Component	ATA:34
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 34-63-01											
346301-0102		CENTER CONSOLE RH EXPANSION MODULE(EMU),CMA UNIT								Component	ATA:34
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 34-63-01											
346302-0103		LH ELECTRONIC DISPLAY, (EDU), CMA UNIT (CKPT, SIDE CONSOLE, FS250)								Component	ATA:34
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 34-63-01											
346302-0104		RH ELECTRONIC DISPLAY, (EDU), CMA UNIT (CKPT, SIDE CONSOLE, FS250)								Component	ATA:34
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 34-63-01											
349095-0101		EGPWS PCMCIA CARD								Component	ATA:34
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: NDT GENERIC											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
FD600CAM-2 ^U VISUAL INSPECTION OF ALL COMPONENTS INSTALLED AS PART OF FLIGHT DISPLAY SYSTEMS FD600CAM-2 GLARESHIELD CAMERA Service ATA:34										
	MOS	06-Jul-19	72		06-Jul-25		233 d			
	HRS	9057.4								
	AFL	4853								
ATA 35 - OXYGEN										
35-10-00-710-001-A00 ^S OPERATIONALLY CHECK CREW/PAX OXYGEN MASKS Service ATA:35										
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
PROC. REF: AMM 35-10-00										PKG:5008,6016
35-10-00-910-001-A00 ^S FUNCTIONALLY CHECK LEAK TEST CREW OXYGEN SYSTEM LINES Service ATA:35										
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
PROC. REF: AMM 35-10-00										PKG:5008
35-10-07-720-001-A00 FUNCTIONALLY CHECK CREW OXYGEN CYLINDER PRESSURE REGULATOR Service ATA:35										
PN:172270-01	MOS	16-Aug-24	60		16-Aug-29		1735 d	SYSTEM		
SN:2570	HRS	10541.4								
	AFL	5613								
PROC. REF: AMM 35-10-07										
35-10-07-720-002-A01 FUNCTIONALLY CHECK (HYDROSTATIC TEST) CREWOXYGEN CYLINDER.NOTE: FROM THE MANUFACTURE DATE OR LAST TASK ACCOMPLISHMENT.NOTE: OR IN ACCORDANCE WITH LOCAL REGULATORY AUTHORITY REQUIREMENTS Service ATA:35										
PN:4441009-050	MOS/MS	31-Aug-23	O/C							
SN:552902908	HRS	10541.4								
	AFL	5613								
HydroCheck Date: : 31-Aug-23 PROC. REF: AMM 35-10-07										
35-20-00-710-001-A00 ^S OPERATIONALLY CHECK PASSENGER GASEOUS OXYGEN-SUBSYSTEM IN MANUAL MODE NOTE: IF INSTALLED Service ATA:35										
	MOS	16-Aug-24	12 (+15d/-15d)					LOW UTILIZATION		
	HRS	10541.4	500 (+20/-20)							
	AFL	5613								
PROC. REF: AMM 35-20-00										PKG:5002

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 35 - OXYGEN										
35-20-00-710-002-A00 ^S OPERATIONALLY CHECK GASEOUS OXYGEN LOW PRESSURE INDICATING CIRCUIT.NOTE: IF INSTALLED.										
	MOS	29-Jun-23	24 (+15d/-15d)					LOW UTILIZATION		Service ATA:35
	HRS	10161.5	1000 (+20/-20)							
	AFL	5401								
PROC. REF: AMM 35-11-04										PKG:5004
35-20-00-720-001-A00 ^S FUNCTIONALLY CHECK PASSENGER GASEOUS OXYGEN SUBSYSTEM IN AUTOMATIC MODE(NOTE: IF INSTALLED).										
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		Service ATA:35
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
PROC. REF: AMM 35-20-00										PKG:5008,6016
35-20-02-211-001-A00 ^S VISUALLY CHECK PASSENGER GASEOUS OXYGEN MASK ASSEMBLY (NOTE: IF INSTALLED).										
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		Service ATA:35
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
PROC. REF: AMM 35-20-04										PKG:5008,6016
35-20-04-720-001-A00 FUNCTIONALLY CHECK (HYDROSTATIC TEST) NO. 1 PASSENGER OXYGEN CYLINDER ASSEMBLY NOTE: IF INSTALLED NOTE: FROM THE MANUFACTURE DATE OR LAST TASK ACCOMPLISHMENT.										
PN:895-48077	MOS/MSC	06-Jul-21	O/C							Service ATA:35
SN:ALT281-35367	HRS									
	AFL									
HydroCheck Date: : 06-Jul-21 PROC. REF: AMM 35-20-08										
35-20-04-720-001-A00 FUNCTIONALLY CHECK (HYDROSTATIC TEST) NO. 2 PASSENGER OXYGEN CYLINDER ASSEMBLY NOTE: IF INSTALLED NOTE: FROM THE MANUFACTURE DATE OR LAST TASK ACCOMPLISHMENT.										
PN:895-48015	MOS/MSC	28-Feb-23	O/C							Service ATA:35
SN:C08100129	HRS									
	AFL									
HydroCheck Date: : 28-Feb-23 PROC. REF: AMM 35-20-08										
35-20-04-960-001-A00 DISCARD NO.1 PASSENGER GASEOUS OXYGEN CYLINDER										
PN:895-48077	MOS	01-May-16	180		01-May-31		2358 d	DISCARD		Service ATA:35
SN:ALT281-35367	HRS									
	AFL									
PROC. REF: AMM 35-20-08, AMM 35-20-08										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 35 - OXYGEN											
35-20-04-960-001-A00		DISCARD NO.2 PASSENGER GASEOUS OXYGEN CYLINDER								Service	ATA:35
PN:895-48015	MOS	11-Jul-23	180		11-Jul-38		4986 d	DISCARD			
SN:C08100129	HRS	10167.3									
	AFL	5404									
PROC. REF: AMM 35-20-08, AMM 35-20-08											
35-20-06-900-001-A00		RESTORE (OVERHAUL) LH GASEOUS OXYGEN ELECTRIC PULSE/LATCHING ON-OFF VALVE NOTE: IF INSTALLED NOTE: FROM THE INSTALLATION DATE								Service	ATA:35
PN:P21070	MOS	19-May-22	60 (+30d/-30d)		19-May-27	18-Jun-27	915 d (+30)	SYSTEM			
SN:0239	HRS	9875.7	2000		11875.7		1280.1				
	AFL	5259									
PROC. REF: AMM 35-20-10											
35-20-06-900-001-A00		RESTORE (OVERHAUL) RH GASEOUS OXYGEN ELECTRIC PULSE/LATCHING ON-OFF VALVE NOTE: IF INSTALLED NOTE: FROM THE INSTALLATION DATE								Service	ATA:35
PN:P21070	MOS	01-Jun-22	60 (+30d/-30d)		01-Jun-27	01-Jul-27	928 d (+30)	SYSTEM			
SN:R22020218	HRS	9892.8	2000		11892.8		1297.2				
	AFL	5264									
PROC. REF: AMM 35-20-10											
35-20-07-900-001-A00		RESTORE (OVERHAUL) LH OXYGEN SEQUENCE REGULATOR NOTE: IF INSTALLED NOTE: FROM THE INSTALLATION DATE								Service	ATA:35
PN:P21087	MOS	19-May-22	60 (+30d/-30d)		19-May-27	18-Jun-27	915 d (+30)	SYSTEM			
SN:0262	HRS	9875.7	2000		11875.7		1280.1				
	AFL	5259									
PROC. REF: AMM 35-20-11											
35-20-07-900-001-A00		RESTORE (OVERHAUL) RH OXYGEN SEQUENCE REGULATOR NOTE: IF INSTALLED NOTE: FROM THE INSTALLATION DATE								Service	ATA:35
PN:P21087	MOS	19-May-22	60 (+30d/-30d)		19-May-27	18-Jun-27	915 d (+30)	SYSTEM			
SN:0494	HRS	9875.7	2000		11875.7		1280.1				
	AFL	5259									
PROC. REF: AMM 35-20-11											
35-20-08-211-001-A00 ^S		VISUALLY CHECK PASSENGER AND CREW GASEOUS OXYGEN PRESSURE INDICATOR GAUGE AGAINST PRESSURE TRANSDUCER INDICATOR ON MFD (NOTE: IF INSTALLED)								Service	ATA:35
	MOS	29-Jun-23	24 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	1000 (+20/-20)								
	AFL	5401									
PROC. REF: AMM 35-20-08										PKG:5004	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 35 - OXYGEN										
35-20-15-790-001-A00 ^S FUNCTIONALLY CHECK (LEAK) PASSENGER GASEOUS OXYGEN DISTRIBUTION (HP) LINES NOTE: IF INSTALLED Service ATA:35										
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
PROC. REF: AMM 35-20-15										PKG:5008,6016
35-20-16-790-001-A00 ^S FUNCTIONALLY CHECK (LEAK) PASSENGER GASEOUS OXYGEN DISTRIBUTION (LP) LINES NOTE: IF INSTALLED Service ATA:35										
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
PROC. REF: AMM 35-20-16										PKG:5008,6016
35-30-01-211-001-A00 VISUALLY CHECK PORTABLE OXYGEN CYLINDER GAUGE PRESSURE INDICATION Service ATA:35										
	MOS	16-Aug-24	12 (+15d/-15d)	Adj -18d	29-Jul-25	13-Aug-25	256 d (+15)	SYSTEM		
	HRS	10541.4	500		11041.4		445.8			
	AFL	5613								
PROC. REF: AMM 35-30-01										
35-30-01-720-001-A00 FUNCTIONALLY CHECK PASSENGER CABIN PORTABLE OXYGEN BOTTLE PRESSURE REGULATOR Service ATA:35										
PN:5500-C1W-BF23A	MOS	29-Jan-20	60		29-Jan-25		75 d	SYSTEM		
SN:P11041075	HRS									
	AFL									
PROC. REF: AMM 35-30-01										
35-30-01-720-002-A00 FUNCTIONALLY CHECK (HYDROSTATIC TEST) PASSENGER CABIN PORTABLE OXYGEN BOTTLE (NOTE: OR IN ACCORDANCE WITH LOCAL REGULATORY AUTHORITY REQUIREMENTS) NOTE: FROM THE MANUFACTURE DATE OR LAST TASK ACCOMPLISHMEN Service ATA:35										
PN:5500-C1W-BF23A	MOS/MSC	29-Jan-20	O/C							
SN:P11041075	HRS									
	AFL									
HydroCheck Date: : 29-Jan-20										
35-30-02-211-001-A00 ^S VISUALLY CHECK CONTINUOUS FLOW MASK Service ATA:35										
	MOS	29-Jun-23	24 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	1000 (+20/-20)							
	AFL	5401								
PROC. REF: AMM 35-30-02										PKG:5004

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 35 - OXYGEN											
35-30-03-960-001-A00		DISCARD COCKPIT EMERGENCY PROTECTIVE BREATHING EQUIPMENT NOTE: FROM THE MANUFACTURE DATE OR DATA PLATE EXPERITATION DATE							Service	ATA:35	
PN:PN	MOS	01-Jun-16	120		01-Jun-26		563 d	LIFE LIMIT			
SN:UNKNOWN	HRS										
	AFL										
			Manufacture Date:: 01-Jun-16		PROC. REF: AMM 35-30-03						
35-30-03-960-001-A00		DISCARD NO.1 EMERGENCY PROTECTIVE BREATHING EQUIPMENT PBE NOTE: FROM THE MANUFACTURE DATE OR DATA PLATE EXPERITATION DATE							Service	ATA:35	
PN:802300-14	MOS	15-Aug-16	120		01-Apr-25 (M)		137 d	LIFE LIMIT			
SN:E15040250	HRS	7841.1									
	AFL	4202									
					PROC. REF: AMM 35-30-03						
351000-0101		PILOT MASK ASSY-STORAGE BOX							Component	ATA:35	
PN:MXP138-1	MOS/MSC	27-Aug-07	O/C		TSN 0						
SN:SE21285	HRS	0			TSN 0						
	AFL	0			TSN 0						
					PROC. REF: AMM 35-10-09						
351000-0102		COPILOT MASK ASSY-STORAGE BOX							Component	ATA:35	
PN:MXP138-1	MOS/MSC	27-Aug-07	O/C		TSN 0						
SN:SE20103	HRS	0			TSN 0						
	AFL	0			TSN 0						
					PROC. REF: AMM 35-10-09						
351000-0201		PILOT OXYGEN ASSY-PRESSURE/DEMAND MASK							Component	ATA:35	
PN:MC10-16-105	MOS/MSC	27-Aug-07	O/C		TSN 0						
SN:121209	HRS	0			TSN 0						
	AFL	0			TSN 0						
					PROC. REF: AMM 35-10-10						
351000-0202		COPILOT OXYGEN ASSY-PRESSURE/DEMAND MASK							Component	ATA:35	
PN:MC10-16-105	MOS/MSC	07-Jan-15	O/C		TSO 38						
SN:117473	HRS	7277.7			TSO 0						
	AFL	3892			TSO 0						
					PROC. REF: AMM 35-10-10						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 35 - OXYGEN										
351000-0203 OBSERVER OXYGEN ASSY-PRESSURE/DEMAND MASK Component ATA:35										
PN:MC10-16-105	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:121213	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: AMM 35-10-10										
351000-0301 OBSERVER LIDS ASSEMBLY Component ATA:35										
PN:MXP129	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:SE19520	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: NDT GENERIC										
351000-0401 COCKPIT PROTECTIVE BREATHING EQUIPMENT (PBE) Component ATA:35										
PN:PN	MOS/MSC		04-Jan-19	H/T						
SN:UNKNOWN	HRS		8912.5							
	AFL		4764							
Manufacture Date:: 01-Jun-16 PROC. REF: NDT GENERIC										
351007-0101 COCKPIT OXYGEN CYLINDER Component ATA:35										
PN:4441009-050	MOS		16-Aug-24	180	29-Feb-28		1201 d	LIFE LIMIT		
SN:552902908	HRS		10541.4							
	AFL		5613							
Manufacture Date:: 28-Feb-13 PROC. REF: AMM 35-10-07										
351007-0201 CREW OXYGEN CYLINDER PRESSURE REGULATOR Component ATA:35										
PN:172270-01	MOS/MSC		06-Jul-19	O/C	TSO 119					
SN:2570	HRS		9057.4							
	AFL		4853							
PROC. REF: AMM 35-10-07										
351102-0101 PRESSURE ASSY-OXYGEN SYS TRANSDUCER Component ATA:35										
PN:PN	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: AMM 35-11-02										
351102-0102 PRESSURE ASSY-OXYGEN SYS TRANSDUCER Component ATA:35										
PN:PN	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: AMM 35-11-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 35 - OXYGEN											
352000-0101		CREW CAB MODULE -PASS OXYGEN CONTROL ASSEMBLY							Component	ATA:35	
PN:135-06949-409	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:0000123549	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 35-20-00											
352000-0201		CONTACTING ELEC SYS,OXYGEN BOX,CHEMICAL GENERATION ALTIMETER							Component	ATA:35	
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: NDT GENERIC											
352006-0101		LH GASEOUS OXYGEN ELECTRIC PULSE/LATCHING ON-OFF VALVE							Component	ATA:35	
PN:P21070	MOS/MSC	19-May-22	O/C	TSO 0							
SN:0239	HRS	9875.7		TSO 0							
	AFL	5259		TSO 0							
PROC. REF: AMM 35-20-10											
352006-0102		RH GASEOUS OXYGEN ELECTRIC PULSE/LATCHING ON-OFF VALVE							Component	ATA:35	
PN:P21070	MOS/MSC	01-Jun-22	O/C	TSN 2							
SN:R22020218	HRS	9892.8		TSN 0							
	AFL	5264		TSN 0							
PROC. REF: AMM 35-20-10											
352007-0101		LH OXYGEN SEQUENCE REGULATOR							Component	ATA:35	
PN:P21087	MOS/MSC	19-May-22	O/C	TSO 0							
SN:0262	HRS	9875.7		TSO 0							
	AFL	5259		TSO 0							
PROC. REF: AMM 35-20-11											
352007-0102		RH OXYGEN SEQUENCE REGULATOR							Component	ATA:35	
PN:P21087	MOS/MSC	19-May-22	O/C	TSO 0							
SN:0494	HRS	9875.7		TSO 0							
	AFL	5259		TSO 0							
PROC. REF: AMM 35-20-11											
352008-7101		NO. 1 PASSENGER OXYGEN CYLINDER ASSEMBLY							Component	ATA:35	
PN:895-48077	MOS/MSC	07-Jul-21	H/T	TSN 62							
SN:ALT281-35367	HRS	9608.3		TSN 1767.2							
	AFL	5118		TSN 916							
PROC. REF: AMM 35-20-08											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 35 - OXYGEN											
352008-7102		NO. 2 PASSENGER OXYGEN CYLINDER ASSEMBLY							Component	ATA:35	
PN:895-48015	MOS/MSC	11-Jul-23	H/T	TSN 180, TSO 0							
SN:C08100129	HRS	10167.3	TSO 0								
	AFL	5404	TSO 0								
PROC. REF: AMM 35-20-08											
353001-0101		PASSENGER CABIN PORTABLE OXYGEN BOTTLE							Component	ATA:35	
PN:5500-C1W-BF23A	MOS/MSC	13-Feb-20	O/C	TSN 109, TSO 55, TSR 1							
SN:P11041075	HRS	9310.8	TSO 1850.5, TSR 0								
	AFL	4969	TSO 977, TSR 0								
PROC. REF: AMM 35-30-01											
353003-0101		NO.1 EMERGENCY PROTECTIVE BREATHING EQUIPMENT PBE							Component	ATA:35	
PN:802300-14	MOS/MSC	15-Aug-16	H/T	TSN 0							
SN:E15040250	HRS	7841.1	TSN 0								
	AFL	4202	TSN 0								
PROC. REF: NDT GENERIC											
353003-7101 ^U		NO.2 EMERGENCY PROTECTIVE BREATHING EQUIPMENT PBE							Component	ATA:35	
PN:802300-14	MOS	01-Sep-17	120	01-Jun-26 (M)			563 d	LIFE LIMIT			
SN:E16060647	HRS	8284.1	TSN 0								
	AFL	4446	TSN 0								
Manufacture Date:: 01-Jun-16											
353005-0101		PORTABLE OXYGEN CYLINDER PRESSURE REGULATOR							Component	ATA:35	
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: NDT GENERIC											
ATA 36 - PNEUMATIC											
36-10-01-130-001-A00 ^S		RESTORE (CLEANING) CROSS-BLEED VALVE FILTER BY ULTRASONIC METHOD							Service	ATA:36	
	MOS	29-Jun-23	96 (+15d/-15d)	LOW UTILIZATION							
	HRS	10161.5	4000 (+20/-20)								
	AFL	5401	2000 (+20/-20)								
PROC. REF: AMM 36-10-01											
										PKG:5016,6016	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 36 - PNEUMATIC											
36-11-01-220-001-A00 ^S	INSPECT (DETAILED INSPECTION) ENGINE HIGH STAGE VALVE P/N 816601-1 AND LOW PRESSURE BLEED AIR CHECK VALVE P/N 816603 -3 (IF INSTALLED)							Service	ATA:36		
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	2000 (+20/-20)								
	AFL	5401	1000 (+20/-20)								
					PROC. REF: AMM 36-11-01					PKG:5008,6016	
36-11-02-130-001-A00 ^S	RESTORE (CLEANING) HIGH-STAGE VALVE FILTER BY ULTRASONIC METHOD							Service	ATA:36		
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	4000 (+20/-20)								
	AFL	5401	2000 (+20/-20)								
					PROC. REF: AMM 36-11-02					PKG:5016,6016	
36-11-03-130-001-A00 ^S	RESTORE (CLEANING) FAN-AIR VALVE FILTER BY ULTRASONIC METHOD							Service	ATA:36		
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	4000 (+20/-20)								
	AFL	5401	2000 (+20/-20)								
					PROC. REF: AMM 36-11-03					PKG:5016,6016	
36-11-04-110-001-A00 ^S	RESTORE (CLEANING) PRE-COOLER BY CHEMICAL METHOD.							Service	ATA:36		
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	2000 (+20/-20)								
	AFL	5401	1000 (+20/-20)								
					PROC. REF: AMM 36-11-04					PKG:5008,6016	
36-11-05-130-001-A00 ^S	RESTORE (CLEANING) ENGINE BLEED VALVE FILTER BY ULTRASONIC METHOD							Service	ATA:36		
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	4000 (+20/-20)								
	AFL	5401	2000 (+20/-20)								
					PROC. REF: AMM 36-11-05					PKG:5016,6016	
36-11-11-710-001-A00 ^S	OPERATIONALLY CHECK THERMOSTAT SHUTOFF VALVE							Service	ATA:36		
	MOS	29-Jun-23	24 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	1000 (+20/-20)								
	AFL	5401									
					PROC. REF: AMM 36-11-08					PKG:5004	
36-20-00-710-001-A00 ^S	OPERATIONALLY CHECK BLEED VALVE INDICATION FUNCTION							Service	ATA:36		
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	4000 (+20/-20)								
	AFL	5401	2000 (+20/-20)								
					PROC. REF: AMM 36-20-00					PKG:5016,6032	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 36 - PNEUMATIC										
36-20-00-720-001-A00^S FUNCTIONALLY CHECK OVERTEMPERATURE WARNING CIRCUIT										
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		Service ATA:36
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
					PROC. REF: AMM 36-20-00					PKG:5016,6032
36-20-02-710-003-A00^S OPERATIONALLY CHECK THERMAL SWITCH										
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		Service ATA:36
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: AMM 36-20-02					PKG:5008,6016
36-20-05-710-002-A00^S OPERATIONALLY CHECK BLEED AUTOMATIC SHUTOFF AND CIRCUITRY.										
	MOS	16-Aug-24	12 (+15d/-15d)					LOW UTILIZATION		Service ATA:36
	HRS	10541.4	500 (+20/-20)							
	AFL	5613								
					PROC. REF: AMM 36-20-02					PKG:5002
361001-0101 APU CROSS-BLEED VALVE										
PN:816606-1	MOS/MSC	27-Aug-07	O/C	TSN 0						Component ATA:36
SN:2007030885	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 36-10-01					
361002-0101 RH REAR GROUND CHECK "J" SST VALVE										
PN:816605-2	MOS/MSC	27-Aug-07	O/C	TSN 0						Component ATA:36
SN:1591	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 36-10-02					
361101-0104 APU CHECK-BLEED SYS,REAR FUSLG I/II VALVE										
PN:816603-3	MOS/MSC	27-Mar-13	O/C	TSN 67						Component ATA:36
SN:5738	HRS	6503.7		TSN 6503.7						
	AFL	3500		TSN 3500						
					PROC. REF: AMM 36-11-01					
361101-0201 LH ENG CHECK-BLEED SYS,REAR FUSLG I/II VALVE										
PN:816603-3	MOS/MSC	06-Jul-19	O/C	TSO 0						Component ATA:36
SN:5461	HRS	9057.4		TSO 0						
	AFL	4853		TSO 0						
					PROC. REF: AMM 36-11-01					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 36 - PNEUMATIC										
361101-0202 LH ENG CHECK-BLEED SYS,REAR FUSLG I/II VALVE Component ATA:36										
PN:816603-3	MOS/MSC	16-Jul-15	O/C	TSR 4						
SN:6642	HRS	7460.3		TSR 0						
	AFL	3992		TSR 0						
PROC. REF: AMM 36-11-01										
361101-0203 RH ENG CHECK-BLEED SYS,REAR FUSLG I/II VALVE Component ATA:36										
PN:816603-3	MOS/MSC	06-Jul-19	O/C							
SN:UNKNOWN	HRS	9057.4								
	AFL	4853								
PROC. REF: AMM 36-11-01										
361101-0204 RH ENG CHECK-BLEED SYS,REAR FUSLG I/II VALVE Component ATA:36										
PN:816603-3	MOS/MSC	06-Jul-19	O/C							
SN:UNKNOWN	HRS	9057.4								
	AFL	4853								
PROC. REF: AMM 36-11-01										
361102-0101 LH PIL HIGH STAGE VALVE Component ATA:36										
PN:816601-1	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 36-11-02										
361102-0102 RH PIL HIGH STAGE VALVE Component ATA:36										
PN:816601-1	MOS/MSC	03-Feb-22	O/C							
SN:9808109	HRS	9799								
	AFL	5212								
PROC. REF: AMM 36-11-02										
361102-0201 LH ENG HIGH STAGE VALVE Component ATA:36										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 36-11-02										
361102-0202 RH ENG HIGH STAGE VALVE Component ATA:36										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 36-11-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 36 - PNEUMATIC										
361103-0101 LEFT REGULATION-TYPE BUTTERFLY,AIR,TURBOFAN ENGINE VALVE Component ATA:36										
PN:816610-2	MOS/MSC	05-Mar-18	O/C	TSN 127						
SN:2007040036	HRS	8509.4		TSN 8509.4						
	AFL	4566		TSN 4566						
PROC. REF: AMM 36-11-03										
361103-0102 RIGHT REGULATION-TYPE BUTTERFLY,AIR,TURBOFAN ENGINE VALVE Component ATA:36										
PN:816610-2	MOS/MSC	05-Mar-18	O/C	TSR 77						
SN:200208156	HRS	8509.4		TSR 3593						
	AFL	4566		TSR 1965						
PROC. REF: AMM 36-11-03										
361106-0101 LEFT THERMOSTAT-FAN AIR ,ENGINE CONTROLLER Component ATA:36										
PN:816624-10	MOS/MSC	05-Mar-18	O/C	TSR 0						
SN:2008061104	HRS	8509.4		TSR 0						
	AFL	4566		TSR 0						
PROC. REF: AMM 36-11-06										
361106-0102 RIGHT THERMOSTAT-FAN AIR ,ENGINE CONTROLLER Component ATA:36										
PN:816624-10	MOS/MSC	05-Mar-18	O/C							
SN:200312138	HRS	8509.4								
	AFL	4566								
PROC. REF: AMM 36-11-06										
361106-0103 LEFT THERMOSTAT-FAN AIR ,ENGINE CONTROLLER Component ATA:36										
PN:816624-9	MOS/MSC	10-Jul-11	O/C							
SN:2005070688	HRS	4802.9								
	AFL	2530								
PROC. REF: AMM 36-11-06										
361106-0104 RIGHT THERMOSTAT-FAN AIR ,ENGINE CONTROLLER Component ATA:36										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 36-11-06										
361107-0101 LH ENG PRESSURE HIGH STAGE,AIR BLEED SYS,ENGINE SWITCH Component ATA:36										
PN:782100-8	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:2457	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 36-11-07										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 36 - PNEUMATIC										
361107-0102 RH ENG PRESSURE HIGH STAGE,AIR BLEED SYS,ENGINE SWITCH Component ATA:36										
PN:782100-8	MOS/MSC	19-Aug-15	O/C	TSN 0						
SN:4375	HRS	7460.3		TSN 0						
	AFL	3992		TSN 0						
PROC. REF: AMM 36-11-07										
361201-0101 APU BLEED AIR VALVE Component ATA:36										
PN:4952829	MOS/MSC	28-Feb-17	O/C							
SN:4033	HRS									
	AFL									
PROC. REF: AMM 36-12-03										
361300-0101 LH AIR BLEED SYS, ENGINE PYLON PRE-COOLER Component ATA:36										
PN:145-30609-401	MOS/MSC	29-Jun-23	O/C	TSO 0						
SN:3478	HRS	10161.5		TSO 0						
	AFL	5401		TSO 0						
PROC. REF: AMM 36-11-04										
361300-0102 RH AIR BLEED SYS, ENGINE PYLON PRE-COOLER Component ATA:36										
PN:145-30609-401	MOS/MSC	29-Jun-23	O/C	TSO 0						
SN:0000623635	HRS	10161.5		TSO 0						
	AFL	5401		TSO 0						
PROC. REF: AMM 36-11-04										
361700-0201 BLEED LH SOLENOID-THREE WAY/TWO POSITIONS,BLEED SYS VALVE Component ATA:36										
PN:5303-21	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										
361700-0202 BLEED RH SOLENOID-THREE WAY/TWO POSITIONS,BLEED SYS VALVE Component ATA:36										
PN:5303-21	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										
361700-0203 X BLEED SOLENOID-THREE WAY/TWO POSITIONS,BLEED SYS VALVE Component ATA:36										
PN:5303-21	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 36 - PNEUMATIC										
361700-0204 X BLEED SOLENOID-THREE WAY/TWO POSITIONS,BLEED SYS,REAR FUSELAGE VALVE Component ATA:36										
PN:5303-21	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										
362000-0101 OVERHEAD PANEL PNEUMATIC CONTROL MODULE Component ATA:36										
PN:145-31625-421	MOS/MSC	29-May-13	O/C							
SN:0000504768	HRS	6582.7								
	AFL	3538								
PROC. REF: NDT GENERIC										
362000-0102 OVERHEAD PANEL MODULE ASSY MODULE Component ATA:36										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										
362001-0101 LH PYLON INDICATOR,BRAKE TEMPERATURE SENSOR Component ATA:36										
PN:0132ADT	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:G4035	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 36-20-01										
362001-0102 RH PYLON INDICATOR,BRAKE TEMPERATURE SENSOR Component ATA:36										
PN:0132ADT	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:G4092	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 36-20-01										
362001-0201 LH PACK INDICATOR,BRAKE TEMPERATURE SENSOR Component ATA:36										
PN:0132ADT	MOS/MSC	05-Mar-18	O/C	TSN 127						
SN:G4036	HRS	8509.4		TSN 8509.4						
	AFL	4566		TSN 4566						
PROC. REF: AMM 36-20-01										
362001-0202 RH PACK INDICATOR,BRAKE TEMPERATURE SENSOR Component ATA:36										
PN:0132ADT	MOS/MSC	05-Mar-18	O/C	TSN 127						
SN:G4039	HRS	8509.4		TSN 8509.4						
	AFL	4566		TSN 4566						
PROC. REF: AMM 36-20-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 38 - WATER/WASTE										
38-10-00-610-001-A00	RESTORE (CLEANING) STERILIZE POTABLE WATER SYSTEM.									Service ATA:38
	MOS	10-Jan-24	12 (+15d/-15d)		10-Jan-25	25-Jan-25	56 d (+15)	SYSTEM		
	HRS	10396.8								
	AFL	5532								
PROC. REF: AMM 38-10-00										
38-10-00-710-001-A00 ^S	OPERATIONALLY CHECK POTABLE WATER HEATER SYSTEM.NOTE: APPLICABLE TO AIRCRAFT EQUIPPED WITH ONE (01) POTABLE WATER SERVICE PANEL.(L600 ONLY)									Service ATA:38
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
PROC. REF: AMM 38-33-00										
38-10-03-960-001-A00 ^S	DISCARD WATER FILTER CARTRIDGE (IF INSTALLED)									Service ATA:38
	MOS	29-Jun-23	24 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	1000 (+20/-20)							
	AFL	5401								
PROC. REF: AMM 38-10-12										
38-10-05-720-001-A00	FUNCTIONALLY CHECK OF MECHANICAL RELIEF VALVE GOODRICH PN 4E3263-1. NOTE: IF INSTALLED. (L600 ONLY)									Service ATA:38
	MOS/MS	27-Aug-07	N/A							
	HRS	0								
	AFL	0								
PROC. REF: AMM 38-10-01										
38-10-05-720-001-A01	FUNCTIONALLY CHECK OF MECHANICAL RELIEF VALVE HYDRAFLOW PN VA046-SERIES. NOTE: IF INSTALLED.									Service ATA:38
	MOS/MS	27-Aug-07	N/A							
	HRS	0								
	AFL	0								
PROC. REF: AMM 38-10-07										
38-32-04-960-001-A00 ^S	DISCARD WASTE DRAIN VALVE O-RING									Service ATA:38
	MOS	16-Aug-24	12 (+15d/-15d)					LOW UTILIZATION		
	HRS	10541.4	500 (+20/-20)							
	AFL	5613								
PROC. REF: AMM 38-32-04										
38-32-10-960-001-A00 ^S	DISCARD WASTE DRAIN VALVE CAP SEAL									Service ATA:38
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
PROC. REF: AMM 38-32-04										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 38 - WATER/WASTE											
38-33-00-710-001-A00 ^S		OPERATIONALLY CHECK THE WASTE WATER HEATER SYSTEM							Service	ATA:38	
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	2000 (+20/-20)								
	AFL	5401	1000 (+20/-20)								
						PROC. REF: AMM 38-33-00					
381001-0101		GALLEY WATER TANK ASSEMBLY							Component	ATA:38	
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
						PROC. REF: AMM 38-10-01					
381011-0701 ^U		WATER LEVEL CONTROLLER							Component	ATA:38	
PN:32612	MOS/MSC	24-Feb-16	O/C	TSN 0							
SN:1145469	HRS	7661.9		TSN 0							
	AFL	4095		TSN 0							
381015-0702 ^U		AFT WATER HEATER							Component	ATA:38	
PN:4E3176-1	MOS/MSC	29-Jun-20	O/C	TSN 0							
SN:N2006517	HRS	9369.6		TSN 0							
	AFL	4994		TSN 0							
381074-7000 ^U		LAVATORY WATER TANK							Component	ATA:38	
PN:AR9038-1	MOS/MSC	23-Apr-13	O/C					CUSTOMER CODE			
SN:0115	HRS	6533.4									
	AFL	3513									
383204-0101		LAVATORY WATER DRAIN VALVE							Component	ATA:38	
PN:0218-0032-1	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:045717	HRS	0		TSN 0							
	AFL	0		TSN 0							
						PROC. REF: AMM 38-32-04					
383204-0102		REAR FUSELAGE WASTE DRAIN VALVE							Component	ATA:38	
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
						PROC. REF: AMM 38-32-04					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 38 - WATER/WASTE											
383250-0701 ^U		LAVATORY FLUSH SWITCH PANEL							Component	ATA:38	
PN:990-9105-016	MOS/MSC	23-Nov-15	O/C	TSR 47							
SN:05060019713	HRS	7556	TSR 0								
	AFL	4049	TSR 0								
383301-0701 ^U		GALLEY SINK WATER DRAIN VALVE ASSY							Component	ATA:38	
PN:AR9124-1D626	MOS/MSC	21-Apr-16	O/C	TSN 8							
SN:0009534925	HRS	7713.9	TSN 0								
	AFL	4144	TSN 0								
ATA 45 - CENTRAL MAINT SYSTEM											
454501-0101		CREW CAB CENTRAL MAINTENANCE - CMC COMPUTER							Component	ATA:45	
PN:251-116-013-012	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:AC44341	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 45-45-01											
ATA 49 - AIRBORNE AUXILIARY POWER											
49-17-00-160-001-A00 ^S		RESTORE (CLEANING) APU DRAINS POST MOD SB 145LEG-49-0006 OR WITH AN EQUIVALENT MODIFICATION FACTORY INCORPORATED							Service	ATA:49	
	MOS	29-Jun-23	48 (+15d/-15d)			LOW UTILIZATION					
	HRS	10161.5	2000 (+20/-20)								
	AFL	5401	1000 (+20/-20)								
PROC. REF: AMM 49-19-02											
49-31-00-710-001-A01		APU - OPERATIONALLY CHECK THE APU FADEC BITE DISPLAY FOR FAULT MESSAGES FOR APU MODEL T-62T-40C14 (APS500R).(NOTE : IF INSTALLED).							Service	ATA:49	
	MOS	16-Aug-24									
	HRS	5722	400	6122	364						
	APUS	4970									
PROC. REF: AMM 49-64-03											
49-31-04-960-001-A01		APU - DISCARD APS 500R INLET FUEL FILTER FOR APU MODEL T-62T-40C14 (APS500R) ONLY.(NOTE: IF INSTALLED).							Service	ATA:49	
	MOS	14-Jul-22			SYSTEM						
	HRS	5009	1200	6209	451						
	APUS	4337									
PROC. REF: AMM 49-32-15											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 49 - AIRBORNE AUXILIARY POWER										
49-41-03-220-001-A00	APU - INSPECT (DETAILED INSPECTION) IGNITER PLUG									Service ATA:49
	MOS	14-Jul-22						SYSTEM		
	HRS	5009	1200		6209		451			
	APUS	4337								
PROC. REF: AMM 49-44-03										
49-62-00-710-001-A00 ^S	OPERATIONALLY CHECK APU EMERGENCY SHUTDOWN BY USING APU FUEL SHUTOFF SWITCH AND FIRE TEST SWITCH.									Service ATA:49
	MOS	06-Jul-19	72 (+15d/-15d)					LOW UTILIZATION		
	HRS	9057.4	3000 (+20/-20)							
	AFL	4853	1500 (+20/-20)							
PROC. REF: AMM 49-62-00										
PKG:5012,6020										
49-91-00-610-001-A00	APU - SERVICE (REPLENISH) CHECK OIL LEVEL AND SERVICE OIL SYSTEM AS REQUIRED									Service ATA:49
	MOS	16-Aug-24						SYSTEM		
	HRS	5722	400		6122		364			
	APUS	4970								
PROC. REF: AMM 49-96-00										
49-91-00-680-001-A00	APU - SERVICE (DRAIN) AND REPLACE APU OIL SUPPLY									Service ATA:49
	MOS	10-Jan-24	12		10-Jan-25		56 d	SYSTEM		
	HRS	5605	2000		7605		1847			
	APUS	4834								
PROC. REF: AMM 49-96-00										
49-91-01-960-001-A00	APU - DISCARD APU OIL FILTER ELEMENT									Service ATA:49
	MOS	11-Jan-23	24		11-Jan-25		57 d	SYSTEM		
	HRS	5210	2000		7210		1452			
	APUS	4477								
PROC. REF: AMM 49-96-01										
490000-0101	OVERH P APU CONTROL MODULE									Component ATA:49
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 26-12-02										
491000-0101	APU - AUXILIARY POWER UNIT COWLING									Component ATA:49
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 49-15-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 49 - AIRBORNE AUXILIARY POWER										
491010 APU - ELECTRICAL HARNESS Component ATA:49										
PN:4504230B	MOS/MSC	28-Feb-17	O/C							
SN:1031	HRS	2952.1								
	APUS	2686								
491015 APU - COMBUSTOR ASSEMBLY Component ATA:49										
PN:4504374B	MOS/MSC	30-Nov-06	O/C	TSN 0						
SN:L06-002	HRS	0		TSN 0						
	APUS	0		TSN 0						
491020 APU - COMBUSTOR LINER Component ATA:49										
PN:4504383A	MOS/MSC	30-Nov-06	O/C	TSN 0						
SN:H06-005	HRS	0		TSN 0						
	APUS	0		TSN 0						
491025 APU - COMBUSTOR HOUSING Component ATA:49										
PN:4505387B	MOS/MSC	30-Nov-06	O/C	TSN 0						
SN:L06-002	HRS	0		TSN 0						
	APUS	0		TSN 0						
491030 APU - OUTPUT SHAFT Component ATA:49										
PN:4505403	MOS/MSC	30-Nov-06	O/C	TSN 0						
SN:V72-W0186	HRS	0		TSN 0						
	APUS	0		TSN 0						
491040 APU - (1 OF 3) STAR GEAR Component ATA:49										
PN:4505488	MOS/MSC	30-Nov-06	O/C	TSN 0						
SN:V72-W120	HRS	0		TSN 0						
	APUS	0		TSN 0						
491041 APU - (2 OF 3) STAR GEAR Component ATA:49										
PN:4505488	MOS/MSC	30-Nov-06	O/C	TSN 0						
SN:V72-W125	HRS	0		TSN 0						
	APUS	0		TSN 0						
491042 APU - (3 OF 3) STAR GEAR Component ATA:49										
PN:4505488	MOS/MSC	30-Nov-06	O/C	TSN 0						
SN:V72-W076	HRS	0		TSN 0						
	APUS	0		TSN 0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 49 - AIRBORNE AUXILIARY POWER										
491050 APU - FUEL MANIFOLD ASSEMBLY Component ATA:49										
PN:4951609	MOS/MSC	30-Nov-06	O/C	TSN 0						
SN:03061359-01	HRS	0		TSN 0						
	APUS	0		TSN 0						
491055 APU - SECONDARY FUEL MANIFOLD Component ATA:49										
PN:4951610	MOS/MSC	30-Nov-06	O/C	TSN 0						
SN:03146306-01	HRS	0		TSN 0						
	APUS	0		TSN 0						
491060 APU - MAIN FUEL SOLENOID Component ATA:49										
PN:4952316-2	MOS/MSC	30-Nov-06	O/C	TSN 0						
SN:1671	HRS	0		TSN 0						
	APUS	0		TSN 0						
491101-0101 APU - TURBINE WHEEL ASSEMBLY Component ATA:49										
PN:4504847	MOS/MSC	28-Feb-17	H/T					LIFE LIMIT		
SN:HK713	HRS	2952.1		TSN 13						
	APUS	2686		TSN 5						
491101-0101-A00 APU - DISCARD OF TURBINE WHEEL Service ATA:49										
PN:4504847	MOS	28-Feb-17								
SN:HK713	HRS	2952.1								
	APUS	2686	15000	TAC 5	17681		12658			
491120-0101 APU - IMPELLER ASSEMBLY Component ATA:49										
PN:4504253	MOS/MSC	28-Feb-17	H/T							
SN:SIF3866	HRS	2952.1		TSN 13						
	APUS	2686		TSN 5						
491120-0101-A00 APU - DISCARD OF THE COMPRESSOR IMPELLER Service ATA:49										
PN:4504253	MOS	28-Feb-17						LIFE LIMIT		
SN:SIF3866	HRS	2952.1								
	APUS	2686	50000	TAC 5	52681		47658			
492000-0101^U APU - AUXILIARY POWER, T62/T40C14,MOD A UNIT Component ATA:49										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						

PROC. REF: AMM 49-14-01

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 49 - AIRBORNE AUXILIARY POWER											
492010		APU - QUILL SHAFT								Component	ATA:49
PN:4504407A	MOS/MSC	30-Nov-06	O/C	TSN 0							
SN:W0387	HRS	0		TSN 0							
	APUS	0		TSN 0							
492015		APU - THRUST BEARING								Component	ATA:49
PN:4502042	MOS/MSC	30-Nov-06	O/C	TSN 0							
SN:2489	HRS	0		TSN 0							
	APUS	0		TSN 0							
492020		APU - TURBINE ASSEMBLY								Component	ATA:49
PN:4504115B	MOS/MSC	28-Feb-17	O/C	TSN 123							
SN:1004	HRS	2952.1		TSN 2952.1, TSR 1.3							
	APUS	2686		TSN 2686, TSR 5							
492025		APU - GEARBOX ASSEMBLY								Component	ATA:49
PN:4504235D	MOS/MSC	28-Feb-17	O/C	TSN 123							
SN:D749	HRS	2952.1		TSN 2952.1							
	APUS	2686		TSN 2686							
492026		APU - GEARBOX HOUSING								Component	ATA:49
PN:4504360C	MOS/MSC	30-Nov-06	O/C	TSN 0							
SN:V4551106D749	HRS	0		TSN 0							
	APUS	0		TSN 0							
492035		APU - ROTOR ASSEMBLY								Component	ATA:49
PN:4504257A	MOS/MSC	30-Nov-06	O/C	TSN 0							
SN:V42-C4599	HRS	0		TSN 0							
	APUS	0		TSN 0							
492040		APU - INTERMEDIATE GEAR								Component	ATA:49
PN:4504313	MOS/MSC	30-Nov-06	O/C	TSN 0							
SN:V24-D0773	HRS	0		TSN 0							
	APUS	0		TSN 0							
492045		APU - RING GEAR								Component	ATA:49
PN:4504328	MOS/MSC	30-Nov-06	O/C	TSN 0							
SN:V24-D0953	HRS	0		TSN 0							
	APUS	0		TSN 0							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 49 - AIRBORNE AUXILIARY POWER										
492050 APU - CONTAINMENT RING Component ATA:49										
PN:4504652	MOS/MSC	30-Nov-06	O/C	TSN 0						
SN:D911	HRS	0		TSN 0						
	APUS	0		TSN 0						
492055^U APU - TURBINE WHEEL Component ATA:49										
PN:PN	MOS/MSC	30-Nov-06	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	APUS	0		TSN 0						
492060 APU - TURBINE NOZZLE Component ATA:49										
PN:4505479	MOS/MSC	30-Nov-06	O/C	TSN 0						
SN:0829	HRS	0		TSN 0						
	APUS	0		TSN 0						
492065 APU - DIFFUSER Component ATA:49										
PN:4505480	MOS/MSC	30-Nov-06	O/C	TSN 0						
SN:V06-G0006	HRS	0		TSN 0						
	APUS	0		TSN 0						
492070 APU - ANTI-SURGE VALVE Component ATA:49										
PN:4950899	MOS/MSC	30-Nov-06	O/C	TSN 0						
SN:1939	HRS	0		TSN 0						
	APUS	0		TSN 0						
492075 APU - ROLLER BEARING Component ATA:49										
PN:4951506	MOS/MSC	30-Nov-06	O/C	TSN 0						
SN:3331-1368	HRS	0		TSN 0						
	APUS	0		TSN 0						
492080 APU - CARBON SEAL Component ATA:49										
PN:4951586	MOS/MSC	30-Nov-06	O/C	TSN 0						
SN:11460	HRS	0		TSN 0						
	APUS	0		TSN 0						
492081 APU - SEAL MATING RING Component ATA:49										
PN:4951587	MOS/MSC	30-Nov-06	O/C	TSN 0						
SN:10694	HRS	0		TSN 0						
	APUS	0		TSN 0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 49 - AIRBORNE AUXILIARY POWER										
493010 APU - FUEL PUMP Component ATA:49										
PN:4503140D	MOS/MSC	30-Nov-06	O/C	TSN 0						
SN:3325	HRS	0		TSN 0						
	APUS	0		TSN 0						
493015 APU - FUEL CONTROL ASSEMBLY Component ATA:49										
PN:4504616A	MOS/MSC	30-Nov-06	O/C	TSN 0						
SN:11-06-62	HRS	0		TSN 0						
	APUS	0		TSN 0						
493025 APU - FLOW DIVIDER Component ATA:49										
PN:4951486	MOS/MSC	30-Nov-06	O/C	TSN 0						
SN:1087	HRS	0		TSN 0						
	APUS	0		TSN 0						
493030 APU - FUEL CONTROL SERVO VALVE Component ATA:49										
PN:4951568	MOS/MSC	30-Nov-06	O/C	TSN 0						
SN:1240	HRS	0		TSN 0						
	APUS	0		TSN 0						
493035 APU - LOW OIL PRESSURE SWITCH Component ATA:49										
PN:4952366	MOS/MSC	30-Nov-06	O/C	TSN 0						
SN:1107	HRS	0		TSN 0						
	APUS	0		TSN 0						
494010 APU - EXCITER Component ATA:49										
PN:4950745	MOS/MSC	30-Nov-06	O/C	TSN 0						
SN:06087833	HRS	0		TSN 0						
	APUS	0		TSN 0						
495010 APU - AIR HOUSING INLET Component ATA:49										
PN:4504117B	MOS/MSC	30-Nov-06	O/C	TSN 0						
SN:1004	HRS	0		TSN 0						
	APUS	0		TSN 0						
495015 APU - AIR INLET DUCT Component ATA:49										
PN:4504716	MOS/MSC	30-Nov-06	O/C	TSN 0						
SN:MS1282	HRS	0		TSN 0						
	APUS	0		TSN 0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 49 - AIRBORNE AUXILIARY POWER										
495020^U APU - BLEED AIR VALVE Component ATA:49										
PN:4952375	MOS/MSC		30-Nov-06	O/C	TSN 0					
SN:2442	HRS		0		TSN 0					
	APUS		0		TSN 0					
495025 APU - HOT SWITCH Component ATA:49										
PN:4952459-1	MOS/MSC		30-Nov-06	O/C	TSN 0					
SN:479	HRS		2		TSN 0					
	APUS		7		TSN 0					
495201 APU - NO. 1 INJECTOR Component ATA:49										
PN:4952404	MOS/MSC		30-Nov-06	O/C	TSN 0					
SN:W2662	HRS		2		TSN 0					
	APUS		7		TSN 0					
495202 APU - NO. 2 INJECTOR Component ATA:49										
PN:4952404	MOS/MSC		30-Nov-06	O/C	TSN 0					
SN:W2670	HRS		2		TSN 0					
	APUS		7		TSN 0					
495203 APU - NO. 3 INJECTOR Component ATA:49										
PN:4952404	MOS/MSC		30-Nov-06	O/C	TSN 0					
SN:W2641	HRS		2		TSN 0					
	APUS		7		TSN 0					
495204 APU - NO. 4 INJECTOR Component ATA:49										
PN:4952404	MOS/MSC		30-Nov-06	O/C	TSN 0					
SN:W2674	HRS		2		TSN 0					
	APUS		7		TSN 0					
495205 APU - NO. 5 INJECTOR Component ATA:49										
PN:4952404	MOS/MSC		30-Nov-06	O/C	TSN 0					
SN:W2635	HRS		2		TSN 0					
	APUS		7		TSN 0					
495206 APU - NO. 6 INJECTOR Component ATA:49										
PN:4952404	MOS/MSC		30-Nov-06	O/C	TSN 0					
SN:W2665	HRS		2		TSN 0					
	APUS		7		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 49 - AIRBORNE AUXILIARY POWER										
496000-0101 APU - AUXILIARY POWER, FADEC CONTROL UNIT Component ATA:49										
PN:4504205E	MOS/MSC	16-Nov-09	O/C							
SN:0063	HRS									
	AFL									
PROC. REF: AMM 49-64-03										
496010 APU - GEAR ASSEMBLY Component ATA:49										
PN:4503716A	MOS/MSC	30-Nov-06	O/C	TSN 0						
SN:V4350806-W143	HRS	0		TSN 0						
	APUS	0		TSN 0						
496015 APU - DATA MEMORY MODULE Component ATA:49										
PN:4505576	MOS/MSC	30-Nov-06	O/C	TSN 0						
SN:1494	HRS	0		TSN 0						
	APUS	0		TSN 0						
497010 APU - SPEED SENSOR Component ATA:49										
PN:4504185C	MOS/MSC	30-Nov-06	O/C	TSN 0						
SN:096669	HRS	0		TSN 0						
	APUS	0		TSN 0						
497020 APU - TEMP/PRESS SENSOR Component ATA:49										
PN:4504196A	MOS/MSC	30-Nov-06	O/C	TSN 0						
SN:V00-S091639	HRS	0		TSN 0						
	APUS	0		TSN 0						
499010 APU - OIL PUMP GEAR Component ATA:49										
PN:4504241	MOS/MSC	30-Nov-06	O/C	TSN 0						
SN:V7770406	HRS	0		TSN 0						
	APUS	0		TSN 0						
49APU1 APU Component ATA:49										
PN:4504113A	MOS/MSC	10-Mar-17	E/C							
SN:SP-E0614882	HRS	8094.9		TSN 2952.1, TSR 1.3						
WC#: 49.APU1	AFL	4346		TSN 2686, TSR 5						
PROC. REF: AMM 49-14-01										
ATA 52 - DOORS										
52-00-00-211-001-A00^S VISUALLY CHECK LOCKING RED MARKSNOTE: REPAINT IF NECESSARY Service ATA:52										
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 52 - DOORS										
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
PROC. REF: AMM 52-00-00										PKG:5008,6016
52-10-00-220-801-L00 ^S	DETAILED INSPECTION (INTERNAL) OF MAIN DOOR COMPONENTS:- MAIN DOOR STOP & BACK UP STRUCTURES (SSI 52-10-03)- MAIN DOOR FOLDING FLAP STOPS (SSI 52-10-04)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR SSI 52-10-04								Service	ATA:52
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
PROC. REF: NDT 52-10-00, CPM 51-61-00										PKG:5008,6016
52-10-00-220-802-L00 ^S	DETAILED INSPECTION (INTERNAL) OF MAIN DOOR COMPONENTS:- MAIN DOOR FOLDING FLAP STRUCTURE (SSI 52-10-02)- MAIN DOOR-TO-FUSELAGE ATTACHMENT FITTINGS & INTERFACE PARTS (SSI 52-10-05)								Service	ATA:52
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
PROC. REF: NDT 52-10-00										PKG:5016,6032
52-10-00-220-803-L00 ^S	DETAILED INSPECTION (EXTERNAL) OF MAIN DOOR COMPONENTS:- MAIN DOOR-TO-FUSELAGE ATTACHMENT FITTINGS & INTER-FACE PARTS (SSI 52-10-05)- MAIN DOOR FOLDING FLAP STRUCTURE (SSI 52-10-02)								Service	ATA:52
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
PROC. REF: NDT 52-10-00										PKG:5016,6032
52-10-00-220-804-L00 ^S	DETAILED INSPECTION (EXTERNAL) OF MAIN DOOR COMPONENTS:- STOP & BACK UP STRUCTURES (SSI 52-10-03)								Service	ATA:52
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
PROC. REF: NDT 52-10-00										PKG:5016,6016
52-10-00-220-807-L00	DETAILED INSPECTION (EXTERNAL) OF MAIN DOOR COMPONENTS:- STRUCTURE (SSI 52-10-01) (L650 ONLY)								Service	ATA:52
	MOS/MS	25-Sep-07	N/A					STRUCTURAL		
	HRS	0								
	AFL	0								
PROC. REF: NDT 52-10-00										PKG:6032
52-10-00-220-808-L00	DETAILED INSPECTION (INTERNAL) OF MAIN DOOR COMPONENTS:- STRUCTURE (SSI 52-10-01) (L650 ONLY)								Service	ATA:52
	MOS/MS	25-Sep-07	N/A					STRUCTURAL		
	HRS	0								
	AFL	0								
PROC. REF: NDT 52-10-00										PKG:6032

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 52 - DOORS										
52-10-00-220-C01-L00 ^S	DETAILED INSPECTION (EXTERNAL) OF MAIN DOOR COMPONENTS:- STRUCTURE (SSI 52-10-01) (L600 ONLY)									Service ATA:52
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: CPM 52-10-00					PKG:5008,6016
52-10-00-220-C02-L00 ^S	DETAILED INSPECTION (INTERNAL) OF MAIN DOOR COMPONENTS:- STRUCTURE (SSI 52-10-01) (L600 ONLY)									Service ATA:52
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: CPM 52-10-00					PKG:5008,6016
52-11-00-640-001-A00 ^S	LUBRICATE STANDARD MAIN DOOR ACTUATING AND LOCKING MECHANISM									Service ATA:52
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: AMM 52-11-00					PKG:5008,6016
52-11-00-720-005-A00 ^S	FUNCTIONALLY CHECK STANDARD MAIN DOOR ACTUATING, LATCHING AND LOCKING MECHANISM									Service ATA:52
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: AMM 52-11-00					PKG:5008,6016
52-12-00-710-001-A00 ^S	OPERATIONALLY CHECK ALTERNATE OPENING SYSTEM									Service ATA:52
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: AMM 52-12-00					PKG:5008,6016
52-12-00-720-001-A00 ^S	FUNCTIONALLY CHECK MAIN DOOR HYDRAULIC ACCUMULATOR NITROGEN CHARGE									Service ATA:52
	MOS	29-Jun-23	24 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	1000 (+20/-20)							
	AFL	5401								
					PROC. REF: AMM 52-12-00					PKG:5004
52-14-00-220-001-A00 ^S	INSPECT (DETAILED INSPECTION) MAIN DOOR DRAINING SYSTEM FOR OBSTRUCTION OR DAMAGE									Service ATA:52
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: AMM 52-14-01					PKG:5008,6016

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 52 - DOORS										
52-21-00-220-801-L00 ^S	DETAILED INSPECTION (EXTERNAL) OF PASSENGER CABIN ESCAPE HATCH COMPONENTS:- ESCAPE HATCH STRUCTURE (SSI 52-21-06)- ESCAPE HATCH WINDOW FRAME (SSI 52-21-07)								Service	ATA:52
MOS	29-Jun-23		96 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		4000 (+20/-20)							
AFL	5401		2000 (+20/-20)							
PROC. REF: NDT 52-21-00										PKG:5016,6032
52-21-00-220-802-L00 ^S	DETAILED INSPECTION (INTERNAL) OF PASSENGER CABIN ESCAPE HATCH COMPONENTS:- ESCAPE HATCH STRUCTURE (SSI 52-21-06)- ESCAPE HATCH WINDOW FRAME (SSI 52-21-07)								Service	ATA:52
MOS	29-Jun-23		96 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		4000 (+20/-20)							
AFL	5401		2000 (+20/-20)							
PROC. REF: NDT 52-21-00										PKG:5016,6032
52-21-00-640-001-A00 ^S	LUBRICATE PASSENGER CABIN ESCAPE HATCH SUPPORT PINS								Service	ATA:52
MOS	29-Jun-23		48 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		2000 (+20/-20)							
AFL	5401		1000 (+20/-20)							
PROC. REF: AMM 52-21-00										PKG:5008,6016
52-21-00-710-001-A00 ^S	OPERATIONALLY CHECK PASSENGER CABIN ESCAPE HATCH MECHANISM								Service	ATA:52
MOS	29-Jun-23		48 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		2000 (+20/-20)							
AFL	5401		1000 (+20/-20)							
PROC. REF: AMM 52-21-00										PKG:5008,6016
52-22-00-710-001-A00 ^S	OPERATIONALLY CHECK COCKPIT EMERGENCY EXIT								Service	ATA:52
MOS	29-Jun-23		48 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		2000 (+20/-20)							
AFL	5401		1000 (+20/-20)							
PROC. REF: AMM 56-11-00										PKG:5008,6016
52-22-01-640-001-A00 ^S	LUBRICATE COCKPIT EMERGENCY EXIT LOCKING MECHANISM								Service	ATA:52
MOS	29-Jun-23		48 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		2000 (+20/-20)							
AFL	5401		1000 (+20/-20)							
PROC. REF: AMM 56-11-01										PKG:5008,6016

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 52 - DOORS										
52-30-00-210-801-L00 ^S	GENERAL VISUAL INSPECTION (INTERNAL) OF BAGGAGE DOOR COMPONENTS:- BAGGAGE DOOR STRUCTURE (SSI 52-30-08)								Service	ATA:52
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
					PROC. REF: NDT 52-30-00					PKG:5016,6032
52-30-00-210-802-L00	GENERAL VISUAL INSPECTION (EXTERNAL) OF BAGGAGE DOOR COMPONENTS:- BAGGAGE DOOR STRUCTURE (SSI 52-30-08) (L650 ONLY)								Service	ATA:52
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL		
	HRS	0								
	AFL	0								
					PROC. REF: NDT 52-30-00					PKG:6032
52-30-00-210-C01-L00 ^S	GENERAL VISUAL INSPECTION (EXTERNAL) OF BAGGAGE DOOR COMPONENTS:- BAGGAGE DOOR STRUCTURE (SSI 52-30-08) (L600 ONLY)								Service	ATA:52
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: CPM 52-30-00					PKG:5008,6016
52-30-00-220-801-L00	DETAILED INSPECTION (INTERNAL) OF BAGGAGE DOOR COMPONENTS:- BAGGAGE DOOR STOPS AND FIT- TINGS (SSI 52-30-09)NOTE: APPLICABLE TO AIRCRAFT PRE-MOD. SB145LEG-00-0007 (L600 ONLY)								Service	ATA:52
	MOS/MSC	27-Aug-07	N/A					STRUCTURAL		
	HRS	0								
	AFL	0								
					PROC. REF: NDT 52-30-00					PKG:6016
52-30-00-220-801-L01 ^S	DETAILED INSPECTION (INTERNAL) OF BAGGAGE DOOR COMPONENTS:- BAGGAGE DOOR STOPS AND FITTINGS (SSI 52-30-09)NOTE: APPLICABLE TO AIRCRAFT POST-MOD. SB145LEG-00-0007 OR WITH AN EQUIVALENT MODIFICATION FACTORY INCORPORATED								Service	ATA:52
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
					PROC. REF: NDT 52-30-00					PKG:5016,6016
52-31-00-640-001-A00 ^S	LUBRICATE BAGGAGE DOOR GEAR BOX								Service	ATA:52
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: AMM 52-31-00					PKG:5008,6016

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 52 - DOORS										
52-32-00-220-001-A00 ^S	INSPECT (DETAILED INSPECTION) BAGGAGE DOOR LIFTING AND LOWERING MECHANISM FOR GENERAL CONDITION AND TORSION BAR FOR TORSION								Service	ATA:52
MOS	29-Jun-23	48 (+15d/-15d)						LOW UTILIZATION		
HRS	10161.5	2000 (+20/-20)								
AFL	5401	1000 (+20/-20)								
PROC. REF: AMM 52-32-00										PKG:5008,6016
52-42-01-220-001-A00 ^S	INSPECT (DETAILED INSPECTION) COCKPIT UNDERFLOOR ACCESS HATCH MECHANISM								Service	ATA:52
MOS	29-Jun-23	48 (+15d/-15d)						LOW UTILIZATION		
HRS	10161.5	2000 (+20/-20)								
AFL	5401	1000 (+20/-20)								
PROC. REF: AMM 52-42-01										PKG:5008,6016
52-44-00-220-801-L00 ^S	DETAILED INSPECTION (EXTERNAL) OF REAR ELECTRONIC COMPARTMENT DOOR COMPONENTS:- REAR ELECTRONIC COMPARTMENT DOOR STRUCTURE (SSI 52-44-01)								Service	ATA:52
MOS	29-Jun-23	48 (+15d/-15d)						LOW UTILIZATION		
HRS	10161.5	2000 (+20/-20)								
AFL	5401	1000 (+20/-20)								
PROC. REF: NDT 52-44-00										PKG:5008,6016
52-44-00-220-802-L00 ^S	DETAILED INSPECTION (INTERNAL) OF REAR ELECTRONIC COMPARTMENT DOOR COMPONENTS:- REAR ELECTRONIC COMPARTMENT DOOR STRUCTURE (SSI 52-44-01)								Service	ATA:52
MOS	29-Jun-23	48 (+15d/-15d)						LOW UTILIZATION		
HRS	10161.5	2000 (+20/-20)								
AFL	5401	1000 (+20/-20)								
PROC. REF: NDT 52-44-00										PKG:5008,6016
52-44-01-220-001-A00 ^S	INSPECT (DETAILED INSPECTION) REAR ELECTRONIC COMPARTMENT DOOR MECHANISM								Service	ATA:52
MOS	29-Jun-23	48 (+15d/-15d)						LOW UTILIZATION		
HRS	10161.5	2000 (+20/-20)								
AFL	5401	1000 (+20/-20)								
PROC. REF: AMM 52-44-01										PKG:5008,6016
52-71-00-710-001-A00 ^S	OPERATIONALLY CHECK FORWARD ELECTRONIC COMPARTMENT DOOR WARNING MESSAGE								Service	ATA:52
MOS	29-Jun-23	48 (+15d/-15d)						LOW UTILIZATION		
HRS	10161.5	2000 (+20/-20)								
AFL	5401	1000 (+20/-20)								
PROC. REF: AMM 52-71-00										PKG:5008,6016

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 52 - DOORS										
52-72-00-710-001-A00 ^S	OPERATIONALLY CHECK RIGGING DOOR WARNING MESSAGE									Service ATA:52
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: AMM 52-72-00					PKG:5008,6016
52-73-00-710-001-A00 ^S	OPERATIONALLY CHECK MAIN DOOR WARNING MESSAGE									Service ATA:52
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: AMM 52-73-00					PKG:5008,6016
52-73-01-720-001-A00 ^S	FUNCTIONALLY CHECK MAIN DOOR WARNING MICROSWITCHES									Service ATA:52
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: AMM 52-73-01					PKG:5008,6016
52-75-00-710-001-A00 ^S	OPERATIONALLY CHECK EMERGENCY EXIT WARNING MESSAGE									Service ATA:52
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: AMM 52-75-00					PKG:5008,6016
52-76-00-710-001-A00 ^S	OPERATIONALLY CHECK BAGGAGE DOOR WARNING MESSAGE									Service ATA:52
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: AMM 52-76-00					PKG:5008,6016
52-77-00-710-001-A00 ^S	OPERATIONALLY CHECK REAR ELECTRONIC COMPARTMENT DOOR WARNING MESSAGE									Service ATA:52
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: AMM 52-77-00					PKG:5008,6016
52-Z811-213-001-A00 ^S	GENERAL VISUAL INSPECTION(EXTERNAL) (ZONE 811)									Service ATA:52
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: AMM 05-30-03					PKG:5008,6016

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 52 - DOORS										
52-Z811-214-001-A00 ^S GENERAL VISUAL INSPECTION(INTERNAL) (ZONE 811) Service ATA:52										
	MOS	29-Jun-23	24 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	1000 (+20/-20)							
	AFL	5401								
PROC. REF: AMM 05-30-04										PKG:5004
52-Z812-213-001-A00 ^S GENERAL VISUAL INSPECTION(EXTERNAL) (ZONE 812 AND 822) Service ATA:52										
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
PROC. REF: AMM 05-30-05										PKG:5016,6032
52-Z812-214-001-A00 ^S GENERAL VISUAL INSPECTION(INTERNAL) (ZONE 812 AND 822) Service ATA:52										
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
PROC. REF: AMM 05-30-06										PKG:5016,6032
52-Z813-213-001-A00 ^S GENERAL VISUAL INSPECTION(EXTERNAL) (ZONE 813) Service ATA:52										
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
PROC. REF: AMM 05-30-07										PKG:5008,6016
52-Z813-214-001-A00 ^S GENERAL VISUAL INSPECTION(INTERNAL) (ZONE 813) Service ATA:52										
	MOS	29-Jun-23	24 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	1000 (+20/-20)							
	AFL	5401								
PROC. REF: AMM 05-30-08										PKG:5004
521000-0101 PAX CABIN DOOR Component ATA:52										
PN:135-12294-423	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:0000137963	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 52-10-01										
521001-0101 FORWARD PANEL, DOOR RELEASE CONTROL MODULE Component ATA:52										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 52-10-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of:
11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 52 - DOORS										
521100-0101	PAX DOOR DAMPER									Component ATA:52
PN:2119-0001-001	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:00610	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: NDT GENERIC										
521100-0201	BOX LOCK ASSEMBLY									Component ATA:52
PN:PN	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: AMM 52-11-06										
521100-0202	BOX LOCK ASSEMBLY									Component ATA:52
PN:PN	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: AMM 52-11-06										
521200-0101	MID ACCUMULATOR -HYDRAULIC SYS, ELECTRONIC COMPT ASSEMBLY									Component ATA:52
PN:PN	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: NDT GENERIC										
521200-0201	MID PRESSURE RELIEF VALVE ASSEMBLY									Component ATA:52
PN:PN	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: AMM 52-12-07										
521200-0301	MAIN DOOR HYDRAULIC PRESSURE SWITCH									Component ATA:52
PN:PN	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: NDT GENERIC										
521200-0401	LEFT CHECK-TYPE RETAINER, HYDRAULIC SYSTEM VALVE									Component ATA:52
PN:PN	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: NDT GENERIC										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 52 - DOORS										
521200-0501	MAIN DOOR - LIFTING AND LOWERING SYSTEM, ACCUMULATOR ISOLATION VALVE									Component ATA:52
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: NDT GENERIC										
521200-0701	LEFT HYDRAULIC ASSY-DRIVING,PAX DOOR ACTUATOR									Component ATA:52
PN:2106-0500-001	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:01048	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: NDT GENERIC										
521200-0702	RIGHT HYDRAULIC ASSY-DRIVING,PAX DOOR ACTUATOR									Component ATA:52
PN:2106-0500-001	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:01049	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: NDT GENERIC										
522100-0101	RIGHT EMERGENCY DOOR ASSEMBLY									Component ATA:52
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: NDT GENERIC										
523000-0101	LH REAR CARGO COMPT, DOOR ASSEMBLY									Component ATA:52
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 52-30-01										
524100-0101	BATTERY COMPARTMENT,FWD FUSELAGE, DOOR ASSEMBLY									Component ATA:52
PN:145-37880-401	MOS/MSC	12-Aug-15	O/C	TSR 0						
SN:8975100440	HRS	7460.3	TSR 0							
	AFL	3992	TSR 0							
PROC. REF: AMM 52-41-00										
524100-0102	HYDRAULIC COMPARTMENT,FWD FUSELAGE, DOOR ASSEMBLY									Component ATA:52
PN:145-47650-401	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:0000126092	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 52-41-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 52 - DOORS										
524200-0101	FORWARD ACCESS ASSY-FWD CONTROL FUSELAGE DOOR									Component ATA:52
PN:145-29986-405	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:0000126044	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 52-46-00										
524400-0101	RH REAR STATION 00 ACCESS DOOR									Component ATA:52
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 52-44-01										
524400-0102	REAR EQUIPMENT BAY DOOR ASSY DOOR									Component ATA:52
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										
524400-0201	BAGGAGE COMPARTMENT DOOR ASSY									Component ATA:52
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 52-30-01										
528100-0101	LH DOOR -MLG UPPER ASSEMBLY									Component ATA:52
PN:135-03284-404	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:0000127264	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										
528100-0102	RH DOOR -MLG UPPER ASSEMBLY									Component ATA:52
PN:135-03284-403	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:0000129935	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										
528100-0103	LH DOOR -MLG LOWER ASSEMBLY									Component ATA:52
PN:135-03285-401	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:0000127189	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 52 - DOORS										
528100-0104	RIGHT LW DOOR -MAIN LANDING GEAR,LOWER ASSEMBLY									Component ATA:52
PN:135-03285-402	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:0000127875	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										
528100-0201	LH DOOR ASSY									Component ATA:52
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-10-06										
528100-0202	RH DOOR ASSY									Component ATA:52
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-10-06										
528100-0301	LH LDG DOOR ASSY									Component ATA:52
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-10-06										
528100-0302	RH LDG DOOR ASSY									Component ATA:52
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-10-06										
ATA 53 - FUSELAGE										
53-00-01-220-001-A00 ^S	INSPECT (DETAILED INSPECTION) FUSELAGE DRAINS FOR OBSTRUCTION OR DAMAGE									Service ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
PROC. REF: AMM 53-00-01										
										PKG:5008,6016

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 53 - FUSELAGE											
53-00-CUS-001 ^U			VISUAL INSPECTION XM SATELLITE RADIO INSTALLATION FOR CORROSION, WEAR AND TEAR, ATTACHMENT CONDITION, LOOSE ITEMS, AND THAT THE CONNECTING CABLES AND/OR ASSOCIATED WIRING IS NOT FRAYED, CUT OR PINCHED FOR THAT PARTICULAR COMPONENT AND IMMEDIATE SURROUNDING AREA.						Service	ATA:53	
	MOS	29-Jun-23	48		29-Jun-27		956 d				
	HRS	10161.5									
	AFL	5401									
53-00-CUS-002 ^U			SPECIAL INSPECTION XM RADIO ANTENNA INSTALLATIONS FOR THE FATIGUE LIFE EVALUATION AND EACHCRACK GROWTH MODEL OF THE DAMAGE TOLERANCE EVALUATION (DTE).						Service	ATA:53	
	MOS	15-Aug-13									
	HRS	6643.4									
	AFL	3572	T:10000		13572		7923				
53-00-CUS-003 ^U			LIFE LIMIT XM RADIO ANTENNA INSTALLATIONS						Service	ATA:53	
	MOS	15-Aug-13									
	HRS	6643.4									
	AFL	3572	T:20000		23572		17923				
53-00-CUS-004 ^U			INSPECTION FEED THRU INSTALLATION						Service	ATA:53	
	MOS	19-Feb-20									
	HRS	9310.8	T:8000		17310.8		6715.2				
	AFL	4969	T:4000		8969		3320				
53-00-CUS-005 ^{U S}			VISUAL INSPECTION OF THE MK II+ CMU, TR-866B VDR, AND DL150 LRUS						Service	ATA:53	
	MOS	29-Jun-23	48								
	HRS	10161.5	2000								
	AFL	5401	1000								
										PKG:5008	
53-00-CUS-006 ^{U S}			VISUAL INSPECTION OF WIRING INSTALLATION OF THE MK II+ CMU, TR-866B VDR, AND DL150 LRUS						Service	ATA:53	
	MOS	29-Jun-23	48								
	HRS	10161.5	2000								
	AFL	5401	1000								
										PKG:5008	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
53-11-00-210-C01-L00 ^S	GENERAL VISUAL INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- BULKHEAD 1 STRUCTURE (SSI 53-10-23)- BATTERY COMPARTMENT CUT- OUT STRUCTURE(SS I 53-10-44)- HYDRAULIC COMPARTMENT CUTOUT STRUCTURE (SSI 53-10-45)- LONGERONS (SSI 53-10-46)								Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
	PROC. REF: CPM 53-11-00									PKG:5016,6032
53-11-00-210-C02-L00 ^S	GENERAL VISUAL INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/BULKHEADS, AND SPLICES (SSI 53-10-07)- FUSELAGE SKIN PANEL AT PRESSURE BULKHEAD(SS I 53-10-15)								Service	ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
	PROC. REF: CPM 53-11-00									PKG:5009
53-11-00-220-801-L00 ^S	DETAILED INSPECTION (INTERNAL)OF FUSELAGE COMPONENTS:- FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/ BULKHEADS, AND SPLICES (SSI 53-10-07)								Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
	PROC. REF: NDT 53-11-00									PKG:5016,6032
53-11-00-220-C01-L00 ^S	DETAILED INSPECTION (INTERNAL)OF FUSELAGE COMPONENTS:- NOSE LANDING GEAR FITTING, INCLUDING BEARING CAP AND TRUNNION FITTING (SSI 53-10-25)								Service	ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
	PROC. REF: CPM 53-11-00									PKG:5008,6016
53-11-00-220-C02-L00 ^S	DETAILED INSPECTION (INTERNAL)OF FUSELAGE COMPONENTS:- FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/BULKHEADS, AND SPLICES (SSI 53-10-07)								Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
	PROC. REF: CPM 53-11-00									PKG:5016,6032
53-11-00-220-C03-L00 ^S	DETAILED INSPECTION (INTERNAL)OF FUSELAGE COMPONENTS:- FUSELAGE SKIN CIRCUMFERENTIAL SPLICE(SS I 53-10-14)- FUSELAGE SKIN PANEL AT PRESSURE BULKHEAD(SS I 53-10-15)- FRAMES (SSI 53-10-43)								Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
	PROC. REF: CPM 53-11-00									PKG:5016,6032

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
53-11-00-220-C04-L00 ^S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN LONGITUDINAL SPLICE (SSI 53-10-08)								Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
					PROC. REF: CPM 53-11-00					PKG:5016,6032
53-11-00-220-C05-L00 ^S	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- NOSE LANDING GEAR BAY STRUCTURE (SSI 53-10-24)								Service	ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: CPM 53-11-00					PKG:5009
53-11-00-220-C06-L00 ^S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- NOSE LANDING GEAR BAY STRUCTURE (SSI 53-10-24)								Service	ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: CPM 53-11-00					PKG:5009
53-11-00-250-801-L00 ^S	SPECIAL DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS BY USING EDDY CURRENT INSPECTION METHOD:- NOSE LANDING GEAR FITTING, INCLUDING BEARING CAP AND TRUNNION FITTING (SSI 53-10-25)								Service	ATA:53
	MOS	27-Aug-07	288 (+15d/-15d)					LOW UTILIZATION		
	HRS	0	12000 (+20/-20)							
	AFL	0	6000 (+20/-20)							
					PROC. REF: NDT 53-11-00					PKG:5140
53-11-01-220-001-A00 ^S	INSPECT (DETAILED INSPECTION) THE PRESENCE OF WATER ON THE RADOME								Service	ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: AMM 53-11-01					PKG:5008,6016
53-11-05-212-001-A00 ^S	INSPECT (VISUAL INSPECTION) THE RADOME POLYURETHANE FILM								Service	ATA:53
	MOS	29-Jun-23	24 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	1000 (+20/-20)							
	AFL	5401								
					PROC. REF: AMM 53-11-05					PKG:5004
53-12-00-210-801-L00 ^S	GENERAL VISUAL INSPECTION (INTERNAL) OF FUSELAGE COM- PONENTS:- WINDSHIELD PANEL (SSI 53-10-21)								Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
					PROC. REF: NDT 53-12-00					PKG:5016,6032

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
53-12-00-210-802-L00	GENERAL VISUAL INSPECTION(EXTERNAL) OF FUSELAGE COMPONENTS:- WINDSHIELD PANEL (SSI 53-10-21) (L650 ONLY)								Service	ATA:53
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL		
	HRS	0								
	AFL	0								
PROC. REF: NDT 53-12-00										PKG:6016
53-12-00-210-C01-L00 ^S	GENERAL VISUAL INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/BULK-HEADS, AND SPLICES (SSI 53-10-07)								Service	ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
PROC. REF: CPM 53-12-00										PKG:5009
53-12-00-210-C02-L00 ^S	GENERAL VISUAL INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN PANEL AT PRESSURE BULKHEAD(SSI 53-10-15)								Service	ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
PROC. REF: CPM 53-12-00										PKG:5009
53-12-00-210-C04-L00 ^S	GENERAL VISUAL INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- WINDSHIELD PANEL (SSI 53-10-21) (L600 ONLY)								Service	ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
PROC. REF: CPM 53-12-00										PKG:5008,6016
53-12-00-210-C05-L00 ^S	GENERAL VISUAL INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- MAINTENANCE DOOR CUTOUT STRUCTURE (SSI 53-10-49)								Service	ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
PROC. REF: CPM 53-12-00										PKG:5009
53-12-00-220-801-L00 ^S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- WINDSHIELD CUTOUT STRUCTURE (SSI 53-10-17)- COCKPIT WINDOW CUTOUT STRUCTURE (SSI 53-10-18)								Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
PROC. REF: NDT 53-12-00										PKG:5016,6032

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
53-12-00-220-802-L00 ^S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- WINDSHIELD CENTER POST AND ITS ATTACHMENT (SSI 53-10-19)								Service	ATA:53
	MOS	12-Jul-15	192 (+15d/-15d)					LOW UTILIZATION		
	HRS	7460.3	8000 (+20/-20)							
	AFL	3992	4000 (+20/-20)							
					PROC. REF: NDT 53-12-00					PKG:5032,6032
53-12-00-220-803-L00 ^S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- WINDSHIELD LATERAL POST AND ITS ATTACHMENT (SSI 53-10-20)- COCKPIT WINDOW REAR POST AND ITS ATTACHMENT (SSI 53-10-22)								Service	ATA:53
	MOS	12-Jul-15	192 (+15d/-15d)					LOW UTILIZATION		
	HRS	7460.3	8000 (+20/-20)							
	AFL	3992	4000 (+20/-20)							
					PROC. REF: NDT 53-12-00					PKG:5032,6032
53-12-00-220-804-L00 ^S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- FORWARD PRESSURE BULKHEAD (SSI 53-10-26)								Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
					PROC. REF: NDT 53-12-00					PKG:5016,6032
53-12-00-220-805-L00 ^S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/ BULKHEADS, AND SPLICES (SSI 53-10-07)- FUSELAGE SKIN LONGITUDINAL SPLICE (SSI 53-10-08)- FUSELAGE SKIN PANEL AT PRESSURE BULKHEAD (SSI 53-10-15)								Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
					PROC. REF: NDT 53-12-00					PKG:5016,6032
53-12-00-220-806-L00 ^S	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- COCKPIT WINDOW CUTOUT STRUCTURE (SSI 53-10-18)								Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
					PROC. REF: NDT 53-12-00					PKG:5016,6016
53-12-00-220-807-L00 ^S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/ BULKHEADS, AND SPLICES (SSI 53-10-07)- FUSELAGE SKIN LONGITUDINAL SPLICE (SSI 53-10-08)								Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
					PROC. REF: NDT 53-12-00					PKG:5016,6032

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 53 - FUSELAGE											
53-12-00-220-808-L00 ^S			DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- COCKPIT WINDOW REAR POST AND ITS ATTACHMENT (SSI 53-10-22)						Service	ATA:53	
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	4000 (+20/-20)								
	AFL	5401	2000 (+20/-20)								
					PROC. REF: NDT 53-12-00					PKG:5016,6016	
53-12-00-220-809-L00 ^S			DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- COCKPIT FLOOR BEAMS AND COL-UMNS (SSI 53-10-27)NOTE: APPLICABLE TO AIRCRAFT POST-MOD. S.B.145LEG-00-0007 OR WITH AN EQUIVALENT MODIFICATION FACTORY INCORPORATED						Service	ATA:53	
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	4000 (+20/-20)								
	AFL	5401	2000 (+20/-20)								
					PROC. REF: NDT 53-12-00					PKG:5016,6032	
53-12-00-220-C01-L00 ^S			DETAILED INSPECTION (INTERNAL)OF FUSELAGE COMPONENTS:- FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/BULKHEADS, AND SPLICES (SSI 53-10-07)						Service	ATA:53	
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	4000 (+20/-20)								
	AFL	5401	2000 (+20/-20)								
					PROC. REF: CPM 53-12-00					PKG:5016,6032	
53-12-00-220-C02-L00 ^S			DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN CIRCUMFERENTIAL SPLICE(SS I 53-10-14)-FRAMES (SSI 53-10-43)						Service	ATA:53	
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	4000 (+20/-20)								
	AFL	5401	2000 (+20/-20)								
					PROC. REF: CPM 53-12-00					PKG:5016,6032	
53-12-00-220-C03-L00 ^S			DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- COCKPIT FLOOR BEAMS AND COLUMNS (SSI 53-10-27)-MAINTENANCE DOOR CUTOUT STRUCTURE (SSI 53-10-49)						Service	ATA:53	
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	4000 (+20/-20)								
	AFL	5401	2000 (+20/-20)								
					PROC. REF: CPM 53-12-00					PKG:5016,6032	
53-12-00-220-C04-L00 ^S			DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN PANEL AT PRESSURE BULKHEAD(SS I 53-10-15)						Service	ATA:53	
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	4000 (+20/-20)								
	AFL	5401	2000 (+20/-20)								
					PROC. REF: CPM 53-12-00					PKG:5016,6032	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
53-12-00-250-804-L00	SPECIAL DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS BY USING EDDY CURRENT INSPECTION METHOD:- WINDSHIELD CENTER POST, INCLUDING ITS ATTACHMENTS AND LOWER FITTING (SSI 53-10-19)NOTE: APPLICABLE TO AIRCRAFT PRE-MOD. S.B.145LEG-00-0007 AND PRE-MOD. S.B.145LEG-53-0021 (L600 ONLY)								Service	ATA:53
	MOS/MSC	27-Aug-07	N/A					STRUCTURAL		
	HRS	0								
	AFL	0								
PROC. REF: NDT 53-12-00										
53-12-00-250-804-L01	SPECIAL DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS BY USING EDDY CURRENT INSPECTION METHOD:- WINDSHIELD CENTER POST, INCLUDING ITS ATTACHMENTS AND LOWER FITTING (SSI 53-10-19)NOTE: APPLICABLE TO AIRCRAFT PRE-MOD. S.B.145LEG-00-0007 AND POST-MOD. S.B. 145LEG-53-0021 OR WITH AN EQUIVALENT MODIFICATION FACTORY INCORPORATED (L600 ONLY)								Service	ATA:53
	MOS/MSC	27-Aug-07	N/A							
	HRS	0								
	AFL	0								
PROC. REF: NDT 53-12-00										
53-12-00-250-804-L02	SPECIAL DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS BY USING EDDY CURRENT INSPECTION METHOD:- WINDSHIELD CENTER POST, INCLUDING ITS ATTACHMENTS AND LOWER FITTING (SSI 53-10-19)NOTE: APPLICABLE TO AIRCRAFT POST-MOD. S.B.145LEG-00-0007 OR WITH AN EQUIVALENT MODIFICATION FACTORY-INCORPORATED AND PRE-MOD. S.B. 145LEG-53-0021 (L600 ONLY)								Service	ATA:53
	MOS/MSC	27-Aug-07	N/A							
	HRS	0								
	AFL	0								
PROC. REF: NDT 53-12-00										PKG:6008
53-12-00-250-804-L03 ^S	SPECIAL DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS BY USING EDDY CURRENT INSPECTION METHOD:- WINDSHIELD CENTER POST, INCLUDING ITS ATTACHMENTS AND LOWER FITTING (SSI 53-10-19)NOTE: APPLICABLE TO AIRCRAFT POST-MOD. S.B.145LEG-00-0007 AND POST-MOD. S.B. 145LEG-53-0021 OR WITH AN EQUIVALENT MODIFICATION FACTORY-INCORPORATED								Service	ATA:53
	MOS	17-Jul-15	192 (+15d/-15d)					LOW UTILIZATION		
	HRS	7460.3	8000 (+20/-20)							
	AFL	3992	4000 (+20/-20)							
PROC. REF: NDT 53-12-00										PKG:5032,6032
53-12-00-250-805-L00	SPECIAL DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENT BY USING EDDY CURRENT INSPECTION METHOD:- WINDSHIELD LATERAL POST AND ITS ATTACHMENT (SSI 53-10-20).NOTE: APPLICABLE TO AIRCRAFT PRE-MOD. S.B.145LEG-00-0007 AND PRE-MOD. S.B. 145LEG-53-0030. (L600 ONLY)								Service	ATA:53
	MOS/MSC	29-Jun-15	N/A							
	HRS	7460.3								
	AFL	3992								
PROC. REF: NDT 53-12-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 53 - FUSELAGE											
53-12-00-250-806-L00			SPECIAL DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENT BY USING EDDY CURRENT INSPECTION METHOD:- WINDSHIELD LATERAL POST AND ITS ATTACHMENT (SSI 53-10-20).NOTE: APPLICABLE TO AIRCRAFT POST-MOD. S.B.145LEG-00-0007 OR WITH AN EQUIVALENT MODIFICATION FACTORY-INCORPORATED AND PRE-MOD. S.B.145LEG-53-0030.						Service	ATA:53	
	MOS/MSC	27-Aug-07	N/A								
	HRS	0									
	AFL	0									
PROC. REF: NDT 53-12-00											
53-12-00-250-807-L00			SPECIAL DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENT BY USING EDDY CURRENT INSPECTION METHOD:- WINDSHIELD LATERAL POST AND ITS ATTACHMENT (SSI 53-10-20).NOTE: APPLICABLE TO AIRCRAFT PRE-MOD. S.B.145LEG-00-0007 AND PRE-MOD. S.B.145LEG-53-0030. (L600 ONLY)						Service	ATA:53	
	MOS/MSC	27-Aug-07	N/A								
	HRS	0									
	AFL	0									
PROC. REF: NDT 53-12-00											
53-12-00-250-808-L00			SPECIAL DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENT BY USING EDDY CURRENT INSPECTION METHOD:- WINDSHIELD LATERAL POST AND ITS ATTACHMENT (SSI 53-10-20).NOTE: APPLICABLE TO AIRCRAFT POST-MOD. S.B.145LEG-00-0007 OR WITH AN EQUIVALENT MODIFICATION FACTORY-INCORPORATED AND PRE-MOD. S.B.145LEG-53-0030.						Service	ATA:53	
	MOS/MSC	27-Aug-07	N/A								
	HRS	0									
	AFL	0									
PROC. REF: NDT 53-12-00											
53-12-00-250-809-L00			SPECIAL DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENT BY USING EDDY CURRENT INSPECTION METHOD:- WINDSHIELD LATERAL POST AND ITS ATTACHMENT (SSI 53-10-20).NOTE: APPLICABLE TO AIRCRAFT PRE-MOD. S.B.145LEG-00-0007 AND POST-MOD. S.B.145LEG-53-0030 OR WITH AN EQUIVALENT MODIFICATION FACTORY-INCORPORATED. (L600 ONLY)						Service	ATA:53	
	MOS/MSC	27-Aug-07	N/A								
	HRS	0									
	AFL	0									
PROC. REF: NDT 53-12-00											
53-12-00-250-810-L00 ^S			SPECIAL DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENT BY USING EDDY CURRENT INSPECTION METHOD:- WINDSHIELD LATERAL POST AND ITS ATTACHMENT (SSI 53-10-20).NOTE: APPLICABLE TO AIRCRAFT POST-MOD. S.B.145LEG-00-0007 OR WITH AN EQUIVALENT MODIFICATION FACTORY-INCORPORATED AND POST-MOD. S.B.145LEG-53-0030 OR WITH AN EQUIVALENT MODIFICATION FACTORY INCORPORATED.						Service	ATA:53	
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	4000 (+20/-20)								
	AFL	5401	2000 (+20/-20)								
PROC. REF: NDT 53-12-00											
										PKG:5017	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
53-21-00-210-C01-L00 ^S	GENERAL VISUAL INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- MAIN DOOR ATTACHMENTS FITTINGS AND INTERFACE PARTS(SS1 53-20-04)								Service	ATA:53
MOS	29-Jun-23	48 (+15d/-15d)						LOW UTILIZATION		
HRS	10161.5	2000 (+20/-20)								
AFL	5401	1000 (+20/-20)								
PROC. REF: CPM 53-21-00										PKG:5008,6016
53-21-00-210-C02-L00 ^S	GENERAL VISUAL INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- MAIN DOOR ATTACHMENTS FITTINGS AND INTERFACE PARTS (SSI 53-20-04)								Service	ATA:53
MOS	29-Jun-23	96 (+15d/-15d)						LOW UTILIZATION		
HRS	10161.5	4000 (+20/-20)								
AFL	5401	2000 (+20/-20)								
PROC. REF: CPM 53-21-00										PKG:5016,6032
53-21-00-220-801-L00 ^S	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- PASSENGER DOOR CUTOUT REINFORCING STRUCTURES (SSI 53-20-09)								Service	ATA:53
MOS	29-Jun-23	96 (+15d/-15d)						LOW UTILIZATION		
HRS	10161.5	4000 (+20/-20)								
AFL	5401	2000 (+20/-20)								
PROC. REF: NDT 53-21-00										PKG:5016,6016
53-21-00-220-802-L00 ^S	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- STOPS AND BACKUP STRUCTURES FOR MAIN DOOR (SSI 53-20-01)								Service	ATA:53
MOS	29-Jun-23	48 (+15d/-15d)						LOW UTILIZATION		
HRS	10161.5	2000 (+20/-20)								
AFL	5401	1000 (+20/-20)								
PROC. REF: NDT 53-21-00										PKG:5008,6016
53-21-00-220-803-L00 ^S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- STOPS AND BACKUP STRUCTURES FOR MAIN DOOR (SSI 53-20-01)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI								Service	ATA:53
MOS	29-Jun-23	48 (+15d/-15d)						LOW UTILIZATION		
HRS	10161.5	2000 (+20/-20)								
AFL	5401	1000 (+20/-20)								
PROC. REF: NDT 53-21-00										PKG:5008,6016
53-21-00-220-804-L00 ^S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/ BULKHEADS, AND SPLICES (SSI 53-20-07)								Service	ATA:53
MOS	29-Jun-23	96 (+15d/-15d)						LOW UTILIZATION		
HRS	10161.5	4000 (+20/-20)								
AFL	5401	2000 (+20/-20)								
PROC. REF: NDT 53-21-00										PKG:5016,6032

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
53-21-00-220-805-L00 ^S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- FRAME 15 & 18 LHS SPLICES AT STRINGERS 3L & 16L (SSI 53-20-12) NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI								Service	ATA:53
MOS	29-Jun-23		96 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		4000 (+20/-20)							
AFL	5401		2000 (+20/-20)							
PROC. REF: NDT 53-21-00										PKG:5016,6032
53-21-00-220-806-L00	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- PASSENGER CABIN WINDOW FRAME (SSI 53-20-06)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSINOTE: IF INSTALLED IN THE ZONE. (L600 ONLY)								Service	ATA:53
MOS/MS	27-Aug-07		N/A					STRUCTURAL		
HRS	0									
AFL	0									
PROC. REF: NDT 53-21-00										PKG:6032
53-21-00-220-807-L00 ^S	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- FRAME 15 & 18 LHS SPLICES AT STRINGERS 3L & 16L (SSI 53-20-12)								Service	ATA:53
MOS	29-Jun-23		96 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		4000 (+20/-20)							
AFL	5401		2000 (+20/-20)							
PROC. REF: NDT 53-21-00										PKG:5016,6016
53-21-00-220-808-L00 ^S	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- PASSENGER CABIN WINDOW FRAME (SSI 53-20-06) NOTE: IF INSTALLED IN THE ZONE. (L600 ONLY)								Service	ATA:53
MOS	29-Jun-23		96 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		4000 (+20/-20)							
AFL	5401		2000 (+20/-20)							
PROC. REF: NDT 53-21-00										PKG:5016,6016
53-21-00-220-810-L00 ^S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- PASSENGER DOOR CUTOUT REINFORCING STRUCTURES (SSI 53-20-09)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI								Service	ATA:53
MOS	29-Jun-23		96 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		4000 (+20/-20)							
AFL	5401		2000 (+20/-20)							
PROC. REF: NDT 53-21-00										PKG:5016,6032
53-21-00-220-811-L00 ^S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN LONGITUDINAL SPLICES AT MAIN DOOR CUTOUT (SSI 53-20-41)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI								Service	ATA:53
MOS	29-Jun-23		96 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		4000 (+20/-20)							
AFL	5401		2000 (+20/-20)							
PROC. REF: NDT 53-21-00										PKG:5016,6032

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
53-21-00-220-812-L00 ^S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/ BULKHEADS, AND SPLICES (SSI 53-20-07)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI								Service	ATA:53
MOS	29-Jun-23		48 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		2000 (+20/-20)							
AFL	5401		1000 (+20/-20)							
PROC. REF: NDT 53-21-00										PKG:5008,6016
53-21-00-220-813-L00 ^S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- MACHINED SHEAR CLIP AT FRAMES 23, 33 AND 35 (SSI 53-20-79)								Service	ATA:53
MOS	29-Jun-23		96 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		4000 (+20/-20)							
AFL	5401		2000 (+20/-20)							
PROC. REF: NDT 53-21-00										PKG:5016,6032
53-21-00-220-814-L00 ^S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN LONGITUDINAL SPLICE (SSI 53-20-08)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR (SSI 53-20-08) (L600 ONLY)								Service	ATA:53
MOS	29-Jun-23		48 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		2000 (+20/-20)							
AFL	5401		1000 (+20/-20)							
PROC. REF: NDT 53-21-00										PKG:5009
53-21-00-220-816-L00 ^S	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- FORWARD AUXILIARY FUEL TANK FITTING, DOUBLER AND PIN AT FRAMES 23, 33 AND 35 (SSI53-20-82)								Service	ATA:53
MOS	29-Jun-23		96 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		4000 (+20/-20)							
AFL	5401		2000 (+20/-20)							
PROC. REF: NDT 53-21-00										PKG:5016,6032
53-21-00-220-818-L00 ^S	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/ BULKHEADS, AND SPLICES (SSI 53-20-07) NOTE: DO NOT REMOVE THE FUEL TANK								Service	ATA:53
MOS	29-Jun-23		48 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		2000 (+20/-20)							
AFL	5401		1000 (+20/-20)							
PROC. REF: NDT 53-21-00										PKG:5008
53-21-00-220-819-L00	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN LONGITUDINAL SPLICE (SSI 53-20-08)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR (SSI 53-20-08). (L650 ONLY)								Service	ATA:53
MOS/MS	27-Aug-07		N/A							
HRS	0									
AFL	0									
PROC. REF: NDT 53-21-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 53 - FUSELAGE											
53-21-00-220-C01-L00 ^S			GENERAL VISUAL INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- PASSENGER CABIN FLOOR BEAMS AND COLUMNS (SSI 53-20-11)						Service	ATA:53	
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	2000 (+20/-20)								
	AFL	5401	1000 (+20/-20)								
					PROC. REF: CPM 53-21-00					PKG:5008,6016	
53-21-02-640-001-A00 ^S			LUBRICATE MAIN DOOR FRAME ROLLERS						Service	ATA:53	
	MOS	16-Aug-24	12 (+15d/-15d)					LOW UTILIZATION			
	HRS	10541.4	500 (+20/-20)								
	AFL	5613									
					PROC. REF: AMM 53-21-02					PKG:5002	
53-22-00-210-801-L00 ^S			GENERAL VISUAL INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/BULK-HEADS, AND SPLICES (SSI 53-20-07)						Service	ATA:53	
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	4000 (+20/-20)								
	AFL	5401	2000 (+20/-20)								
					PROC. REF: NDT 53-22-00					PKG:5016,6032	
53-22-00-210-802-L00 ^S			GENERAL VISUAL INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/BULK-HEADS, AND SPLICES (SSI 53-20-07)						Service	ATA:53	
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	4000 (+20/-20)								
	AFL	5401	2000 (+20/-20)								
					PROC. REF: NDT 53-22-00					PKG:5016,6032	
53-22-00-210-803-L00 ^S			GENERAL VISUAL INSPECTION (INTERNAL) OF FUSELAGE COM- PONENTS:- MACHINED SHEAR CLIP AT FRAMES 23, 33 AND 35 (SSI 53-20-79)- MACHINED SHEAR CLIP AT FRAMES 25 AND 31 (SSI 53-20-80)						Service	ATA:53	
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	4000 (+20/-20)								
	AFL	5401	2000 (+20/-20)								
					PROC. REF: NDT 53-22-00					PKG:5016,6032	
53-22-00-210-804-L00 ^S			GENERAL VISUAL INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/BULK-HEADS, AND SPLICES (SSI 53-20-07)						Service	ATA:53	
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	4000 (+20/-20)								
	AFL	5401	2000 (+20/-20)								
					PROC. REF: NDT 53-22-00					PKG:5016,6032	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
53-22-00-210-805-L00 ^S	GENERAL VISUAL INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- FORWARD AUXILIARY FUEL TANK (SSI 53-20-81)								Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
	PROC. REF: NDT 53-22-00									PKG:5016,6032
53-22-00-210-806-L00 ^S	GENERAL VISUAL INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- FORWARD AUXILIARY FUEL TANK (SSI 53-20-81)								Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
	PROC. REF: NDT 53-22-00									PKG:5016,6032
53-22-00-220-802-L00 ^S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/ BULKHEADS, AND SPLICES (SSI 53-20-07)- FUSELAGE SKIN CIRCUMFERENTIAL SPLICE (SSI 53-20-14)- FRAMES (SSI 53-20-43)								Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
	PROC. REF: NDT 53-22-00									PKG:5016,6032
53-22-00-220-804-L00 ^S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN LONGITUDINAL SPLICE (SSI 53-20-08)								Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
	PROC. REF: NDT 53-22-00									PKG:5016,6032
53-22-00-220-806-L00 ^S	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- FORWARD AUXILIARY FUEL TANK FITTING, DOUBLER AND PIN AT FRAMES 23, 33 AND 35 (SSI53-20-82)- FORWARD AUXILIARY FUEL TANK FITTING, DOUBLER AND PIN AT FRAMES 25 AND 31 (SSI 53-20-83)								Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
	PROC. REF: NDT 53-22-00									PKG:5016,6032
53-22-00-220-807-L00 ^S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- PASSENGER CABIN WINDOW FRAME (SSI 53-20-06)								Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
	PROC. REF: NDT 53-22-00									PKG:5016,6032

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
53-22-00-220-808-L00 ^S	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- MACHINED SHEAR CLIP AT FRAMES 23, 33 AND 35 (SSI 53-20-79)								Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
	PROC. REF: NDT 53-22-00									PKG:5016,6032
53-22-00-220-C01-L00 ^S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- PASSENGER CABIN FLOOR BEAMS AND COLUMNS (SSI 53-20-11)								Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
	PROC. REF: CPM 53-22-00									PKG:5016,6032
53-23-00-210-801-L00 ^S	GENERAL VISUAL INSPECTION (INTERNAL) OF FUSELAGE COM- PONENTS:- OVERWING FUSELAGE SKIN PANEL (SSI 53-20-16)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI								Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
	PROC. REF: NDT 53-23-00									PKG:5016,6032
53-23-00-210-804-L00 ^S	GENERAL VISUAL INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- OVERWING FUSELAGE SKIN PANEL (SSI 53-20-16)								Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
	PROC. REF: NDT 53-23-00									PKG:5016,6032
53-23-00-210-C02-L00 ^S	GENERAL VISUAL INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- PASSENGER CABIN WINDOW FRAME (SSI 53-20-06)								Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
	PROC. REF: CPM 53-23-00									PKG:5016,6032
53-23-00-220-801-L00 ^S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE MACHINED BULKHEAD (SSI 53-20-30)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR ZONES 151/152 AND 153/154								Service	ATA:53
	MOS	27-Aug-07	288 (+15d/-15d)					LOW UTILIZATION		
	HRS	0	12000 (+20/-20)							
	AFL	0	6000 (+20/-20)							
	PROC. REF: NDT 53-23-00									PKG:5140

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
53-23-00-220-802-L00 ^S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/ BULKHEADS, AND SPLICES (SSI 53-20-07)								Service	ATA:53
MOS	29-Jun-23		96 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		4000 (+20/-20)							
AFL	5401		2000 (+20/-20)							
PROC. REF: NDT 53-23-00										PKG:5016,6032
53-23-00-220-803-L00 ^S	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- SKIN AND REINFORCEMENT AROUND ESCAPE HATCH CUTOUT (SSI 53-20-51)								Service	ATA:53
MOS	29-Jun-23		96 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		4000 (+20/-20)							
AFL	5401		2000 (+20/-20)							
PROC. REF: NDT 53-23-00										PKG:5016,6016
53-23-00-220-804-L00 ^S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- FRAMES (SSI 53-20-43)								Service	ATA:53
MOS	29-Jun-23		96 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		4000 (+20/-20)							
AFL	5401		2000 (+20/-20)							
PROC. REF: NDT 53-23-00										PKG:5016,6032
53-23-00-220-805-L00 ^S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- FRAMES (SSI 53-20-43)								Service	ATA:53
MOS	29-Jun-23		96 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		4000 (+20/-20)							
AFL	5401		2000 (+20/-20)							
PROC. REF: NDT 53-23-00										PKG:5016,6032
53-23-00-220-806-L00 ^S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE MACHINED BULK- HEAD (SSI 53-20-30)- FRAMES (SSI 53-20-43)- SKIN AND REINFORCEMENT AROUND ESCAPE HATCH CUTOUT (SSI 53-20-51)- FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/ BULKHEADS, AND SPLICES (SSI 53-20-07)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR (SSI 53-20-30)								Service	ATA:53
MOS	29-Jun-23		96 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		4000 (+20/-20)							
AFL	5401		2000 (+20/-20)							
PROC. REF: NDT 53-23-00										PKG:5016,6032
53-23-00-220-808-L00	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/ BULKHEADS, AND SPLICES (SSI 53-20-07)NOTE: APPLICABLE TO AIRCRAFT PRE-MOD. S.B.145LEG-00-0007 (L600 ONLY)								Service	ATA:53
MOS/MSC	15-Aug-13		N/A							
HRS	6643.4									
AFL	3572									
PROC. REF: NDT 53-23-00										PKG:6016

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
53-23-00-220-808-L01 ^S	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/ BULK-HEADS, AND SPLICES (SSI 53-20-07)NOTE: APPLICABLE TO AIRCRAFT POST-MOD. S.B.145LEG-00-0007 OR WITH AN EQUIVALENT MODIFICATION FACTORY-INCORPORATED.								Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
PROC. REF: NDT 53-23-00										PKG:5016,6032
53-23-00-220-809-L00	DETAILED INSPECTION (EXTERNAL)OF FUSELAGE COMPONENTS:- FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/ BULKHEADS, AND SPLICES (SSI 53-20-07)NOTE: APPLICABLE TO AIRCRAFT PRE-MOD. S.B.145LEG-00-0007 (L600 ONLY)								Service	ATA:53
	MOS/MSC	15-Aug-13	N/A							
	HRS	6643.4								
	AFL	3572								
PROC. REF: NDT 53-23-00										PKG:6016
53-23-00-220-810-L00	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- MACHINED FRAME AT VENTRAL FUEL TANK ATTACHMENT POINTS (SSI 53-20-84) (L650 ONLY)								Service	ATA:53
	MOS/MSC	27-Aug-07	N/A							
	HRS	0								
	AFL	0								
PROC. REF: NDT 53-23-00										PKG:6032
53-23-00-220-811-L00 ^S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- PASSENGER CABIN FLOOR BEAMS AND COLUMNS (SSI 53-20-11) NOTE: APPLICABLE TO AIRCRAFT PRE-MOD. S.B.145LEG-00-0007. (L600 ONLY)								Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
PROC. REF: NDT 53-23-00										PKG:5016,6032
53-23-00-220-811-L01 ^S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- PASSENGER CABIN FLOOR BEAMS AND COLUMNS (SSI 53-20-11) NOTE: APPLICABLE TO AIRCRAFT POST-MOD. S.B.145LEG-00-0007 OR WITH AN EQUIVALENT MODIFICATION FACTORY-INCORPORATED.								Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
PROC. REF: NDT 53-23-00										PKG:5016,6032
53-23-00-220-812-L00	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/BULKHEADS, AND SPLICES (SSI 53-20-07). (L650 ONLY)								Service	ATA:53
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL		
	HRS	0								
	AFL	0								
PROC. REF: NDT 53-23-00										PKG:6032

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
53-23-00-220-C01-L00 ^S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/BULKHEADS, AND SPLICES (SSI 53-20-07)								Service	ATA:53
MOS	29-Jun-23		48 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		2000 (+20/-20)							
AFL	5401		1000 (+20/-20)							
PROC. REF: CPM 53-23-00										PKG:5008,6016
53-23-00-220-C03-L00 ^S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN LONGITUDINAL SPLICE (SSI 53-20-08)								Service	ATA:53
MOS	29-Jun-23		96 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		4000 (+20/-20)							
AFL	5401		2000 (+20/-20)							
PROC. REF: CPM 53-23-00										PKG:5016,6032
53-23-00-220-C04-L00 ^S	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/BULKHEADS, AND SPLICES (SSI 53-20-07) (L600 ONLY)								Service	ATA:53
MOS	29-Jun-23		48 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		2000 (+20/-20)							
AFL	5401		1000 (+20/-20)							
PROC. REF: CPM 53-23-00										PKG:5008,6016
53-23-00-250-801-L00	SPECIAL DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENT BY USING EDDY CURRENT HIGH FREQUENCY INSPECTION METHOD:- PASSENGER CABIN WINDOW FRAME (SSI 53-20-06)NOTE: APPLICABLE TO AIRCRAFT PRE-MOD. S.B.145LEG-00-0007 (L600 ONLY)								Service	ATA:53
MOS/MSC	27-Aug-07		N/A							
HRS	0									
AFL	0									
PROC. REF: NDT 53-23-00										
53-24-00-210-C01-L00 ^S	GENERAL VISUAL INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- PASSENGER CABIN WINDOW FRAME (SSI 53-20-06)								Service	ATA:53
MOS	29-Jun-23		96 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		4000 (+20/-20)							
AFL	5401		2000 (+20/-20)							
PROC. REF: CPM 53-24-00										PKG:5016,6032
53-24-00-210-C07-L00	GENERAL VISUAL INSPECTION (EXTERNAL) OF VENTRAL FUEL TANK COMPONENTS - VENTRAL FUEL TANK STRUCTURE (SSI 53-20-85) - FRONTAL SIDE OF VENTRAL FUEL TANK STRUCTURE (SSI 53-20-87) (L650 ONLY)								Service	ATA:53
MOS/MSC	27-Aug-07		N/A							
HRS	0									
AFL	0									
PROC. REF: CPM 53-24-00										PKG:6032

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
53-24-00-220-801-L00 ^S	DETAILED INSPECTION (INTERNAL)OF FUSELAGE COMPONENTS:- FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/ BULKHEADS, AND SPLICES (SSI 53-20-07)								Service	ATA:53
MOS	29-Jun-23		96 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		4000 (+20/-20)							
AFL	5401		2000 (+20/-20)							
PROC. REF: NDT 53-24-00										PKG:5016,6032
53-24-00-220-802-L00 ^S	DETAILED INSPECTION (INTERNAL)OF FUSELAGE COMPONENTS:- FUSELAGE SKIN LONGITUDINAL SPLICE (SSI 53-20-08)								Service	ATA:53
MOS	29-Jun-23		96 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		4000 (+20/-20)							
AFL	5401		2000 (+20/-20)							
PROC. REF: NDT 53-24-00										PKG:5016,6032
53-24-00-220-803-L00 ^S	DETAILED INSPECTION (INTERNAL)OF FUSELAGE COMPONENTS:- FUSELAGE SKIN CIRCUMFERENTIAL SPLICE(SSS 53-20-14)- FRAMES (SSI 53-20-43) (L600 ONLY)								Service	ATA:53
MOS	29-Jun-23		96 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		4000 (+20/-20)							
AFL	5401		2000 (+20/-20)							
PROC. REF: NDT 53-24-00										PKG:5016
53-24-00-220-804-L00 ^S	DETAILED INSPECTION (INTERNAL)OF FUSELAGE COMPONENTS:- FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/ BULKHEADS, AND SPLICES (SSI 53-20-07)- FUSELAGE SKIN LONGITUDINAL SPLICE (SSI 53-20-08)NOTE: APPLICABLE TO AIRCRAFT PRE-MOD. S.B.145LEG-00-0007 (L600 ONLY)								Service	ATA:53
MOS	29-Jun-23		96 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		4000 (+20/-20)							
AFL	5401		2000 (+20/-20)							
PROC. REF: NDT 53-24-00										PKG:5016,6032
53-24-00-220-805-L00 ^S	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/ BULKHEADS, AND SPLICES (SSI 53-20-07) (L600 ONLY)								Service	ATA:53
MOS	29-Jun-23		48 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		2000 (+20/-20)							
AFL	5401		1000 (+20/-20)							
PROC. REF: NDT 53-24-00										PKG:5008,6016
53-24-00-220-813-L00	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- MACHINED FRAME AT VENTRAL FUEL TANK ATTACHMENT POINTS (SSI 53-20-84) (L650 ONLY)								Service	ATA:53
MOS/MSC	27-Aug-07		N/A							
HRS	0									
AFL	0									
PROC. REF: NDT 53-24-00										PKG:6032

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 53 - FUSELAGE											
53-24-00-220-814-L00			DETAILED INSPECTION (EXTERNAL) OF VENTRAL FUEL TANK COMPONENTS:- VENTRAL FUEL TANK ATTACHMENT POINTS, INCLUDING MAIN BOLTS (SSI 53-20-86) (L650 ONLY)						Service	ATA:53	
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL			
	HRS	0									
	AFL	0									
					PROC. REF: NDT 53-24-00					PKG:6032	
53-24-00-220-815-L00			DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN CIRCUMFEREN- TIAL SPLICE(SS I 53-20-14) FRAMES (SSI 53-20-43) (L650 ONLY)						Service	ATA:53	
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL			
	HRS	0									
	AFL	0									
					PROC. REF: NDT 53-24-00					PKG:6032	
53-24-00-220-816-L00			DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/ BULKHEADS, AND SPLICES (SSI 53-20-07) (L650 ONLY)						Service	ATA:53	
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL			
	HRS	0									
	AFL	0									
					PROC. REF: NDT 53-24-00						
53-24-00-220-C01-L00 ^S			DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/BULKHEADS, AND SPLICES (SSI 53-20-07)						Service	ATA:53	
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	2000 (+20/-20)								
	AFL	5401	1000 (+20/-20)								
					PROC. REF: CPM 53-24-00					PKG:5008,6016	
53-24-00-220-C02-L00 ^S			DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- PASSENGER CABIN FLOOR BEAMS AND COLUMNS(SS I 53-20-11)						Service	ATA:53	
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	4000 (+20/-20)								
	AFL	5401	2000 (+20/-20)								
					PROC. REF: CPM 53-24-00					PKG:5016,6032	
53-24-00-220-C03-L00 ^S			DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/BULKHEADS, AND SPLICES (SSI53-20-07).NOTE: APPLICABLE TO AIRCRAFT POST-MOD. S.B. 145LEG-00-0007 OR WITH AN EQUIVALENT MODIFICATION FACTORY- INCORPORATED						Service	ATA:53	
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	2000 (+20/-20)								
	AFL	5401	1000 (+20/-20)								
					PROC. REF: CPM 53-24-00					PKG:5008,6016	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 53 - FUSELAGE											
53-24-00-220-C04-L00			DETAILED INSPECTION (INTERNAL) OF VENTRAL FUEL TANK COMPONENTS:- VENTRAL FUEL TANK STRUCTURE (SSI 53-20-85) (L650 ONLY)						Service	ATA:53	
	MOS/MSC	27-Aug-07	N/A								
	HRS	0									
	AFL	0									
					PROC. REF: CPM 53-24-00					PKG:6016	
53-24-00-220-C05-L00			DETAILED INSPECTION (INTERNAL) OF VENTRAL FUEL TANK COMPONENTS:- FRONTAL SIDE OF VENTRAL FUEL TANK STRUCTURE (SSI 53-20-87) (L650 ONLY)						Service	ATA:53	
	MOS/MSC	27-Aug-07	N/A								
	HRS	0									
	AFL	0									
					PROC. REF: CPM 53-24-00					PKG:6032	
53-31-00-210-801-L00 ^S			GENERAL VISUAL INSPECTION (INTERNAL) OF FUSELAGE COM- PONENTS:- REAR AUXILIARY FUEL TANK FITTING AT ATTACHMENTS (SSI 53-30-56)						Service	ATA:53	
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	4000 (+20/-20)								
	AFL	5401	2000 (+20/-20)								
					PROC. REF: NDT 53-31-00					PKG:5016,6032	
53-31-00-210-802-L00 ^S			GENERAL VISUAL INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- BAGGAGE DOOR LATERAL L- SHAPE (SSI 53-30-03)						Service	ATA:53	
	MOS	09-Jul-15	192 (+15d/-15d)					LOW UTILIZATION			
	HRS	7460.3	8000 (+20/-20)								
	AFL	3992	4000 (+20/-20)								
					PROC. REF: NDT 53-31-00					PKG:5032,6032	
53-31-00-210-803-L00 ^S			GENERAL VISUAL INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- BAGGAGE DOOR CUTOUT STRUCTURE (SSI 53-30-48)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI						Service	ATA:53	
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	4000 (+20/-20)								
	AFL	5401	2000 (+20/-20)								
					PROC. REF: NDT 53-31-00					PKG:5016,6032	
53-31-00-210-804-L00 ^S			GENERAL VISUAL INSPECTION(INTERNAL) OF FUSELAGE COMPONENTS:- REAR ELECTRONIC COMPARTMENT DOOR CUTOUT STRUCTURE (SSI 53-30-49)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI.NOTE: APPLICABLE TO AIRCRAFT PRE-MOD. S.B.145LEG-00-0007 (L600 ONLY)						Service	ATA:53	
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	4000 (+20/-20)								
	AFL	5401	2000 (+20/-20)								
					PROC. REF: NDT 53-31-00					PKG:5016,6032	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
53-31-00-210-804-L01 ^S			GENERAL VISUAL INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- REAR ELECTRONIC COMPARTMENT DOOR CUTOUT STRUCTURE (SSI 53-30-49)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI.NOTE: APPLICABLE TO AIRCRAFT POST-MOD. S.B.145LEG-00-0007 OR WITH AN EQUIVALENT MODIFICATION FACTORY-INCORPORATED (L650 ONLY)						Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
					PROC. REF: NDT 53-31-00					PKG:5016,6032
53-31-00-210-810-L00			GENERAL VISUAL INSPECTION(INTERNAL) OF FUSELAGECOMPONENTS:- REAR ELECTRONIC COMPARTMENT DOOR CUTOUT STRUCTURE (SSI 53-30-49)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI. (L650 ONLY)						Service	ATA:53
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL		
	HRS	0								
	AFL	0								
					PROC. REF: NDT 53-31-00					PKG:6032
53-31-00-210-811-L00 ^S			GENERAL VISUAL INSPECTION (INTERNAL) OFFUSELAGE COMPONENTS: FUSELAGE SKIN PANEL AT STRINGERS,FRAMES/BULKHEADS, AND SPLICES (SSI 53-30-07). FUSELAGE SKIN PANEL AT PRESSURE BULKHEAD(53-30- 15). FUSELAGE MACHINED BULKHEAD (53-30-30). FRAMES (53-30-43).NOTE: DURING THIS INSPECTION, THE CPCP BASICTASK SHALL ALSO BE PERFORMED FOR SSI 53-30-07						Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
					PROC. REF: NDT 53-31-00					PKG:5016,6032
53-31-00-220-801-L00 ^S			DETAILED INSPECTION (INTERNAL)OF FUSELAGE COMPONENTS:- BAGGAGE COMPARTMENT FLOOR BEAMS AND COLUMNS (SSI 53-30-28)						Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
					PROC. REF: NDT 53-31-00					PKG:5016,6032
53-31-00-220-802-L00 ^S			DETAILED INSPECTION (EXTERNAL)OF FUSELAGE COMPONENTS:- FRAME REINFORCEMENT - MACHINED SHEAR CLIP (SSI 53-30-55)						Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
					PROC. REF: NDT 53-31-00					PKG:5016,6032

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
53-31-00-220-805-L00 ^S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- FRAME REINFORCEMENT - MACHINED SHEAR CLIP (SSI 53-30-55)								Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
					PROC. REF: NDT 53-31-00					PKG:5016,6032
53-31-00-220-806-L00 ^S	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN PANEL AT PRESSURE BULKHEAD (SSI 53-30-15)								Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
					PROC. REF: NDT 53-31-00					PKG:5016,6032
53-31-00-220-807-L00 ^S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN LONGITUDINAL SPLICE (SSI 53-30-08)- FUSELAGE SKIN CIRCUMFERENTIAL SPLICE(SS I 53-30-14)								Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
					PROC. REF: NDT 53-31-00					PKG:5016,6032
53-31-00-220-808-L00 ^S	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- BAGGAGE DOOR CUTOUT STRUCTURE (SSI 53-30-48)								Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
					PROC. REF: NDT 53-31-00					PKG:5016,6032
53-31-00-220-809-L00 ^S	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- REAR ELECTRONIC COMPARTMENT DOOR CUTOUT STRUCTURE (SSI 53-30-49) (L600 ONLY)								Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
					PROC. REF: NDT 53-31-00					PKG:5016
53-31-00-220-810-L00 ^S	DETAILED INSPECTION (INTERNAL)OF FUSELAGE COMPONENTS:- BULKHEAD-TO-ENGINE PYLON ATTACHMENT(SS I 53-30-35)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR 53-30-35 (L600 ONLY)								Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
					PROC. REF: NDT 53-31-00					PKG:5016,6032

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
53-31-00-220-811-L00 ^S	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE MACHINED BULK- HEAD (SSI 53-30-30)								Service	ATA:53
	MOS	24-Jul-15	192 (+15d/-15d)					LOW UTILIZATION		
	HRS	7460.3	8000 (+20/-20)							
	AFL	3992	4000 (+20/-20)							
					PROC. REF: NDT 53-31-00					PKG:5032,6032
53-31-00-220-813-L00 ^S	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/ BULKHEADS, AND SPLICES (SSI 53-30-07)- FUSELAGE SKIN PANEL AT PRES- SURE BULKHEAD(SS1 53-30-15)- FUSELAGE TO VERTICAL STABILIZER SPAR ATTACHMENT FITTING (SSI 53-30-38)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR SSI 53-30-38								Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
					PROC. REF: NDT 53-31-00					PKG:5016,6016
53-31-00-220-818-L00	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- REAR ELECTRONIC COMPARTMENT DOOR CUTOUT STRUCTURE (SSI 53-30-49) (L650 ONLY)								Service	ATA:53
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL		
	HRS	0								
	AFL	0								
					PROC. REF: NDT 53-31-00					PKG:6016
53-31-00-220-819-L00	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- BULKHEAD-TO-ENGINE PYLON ATTACHMENT (SSI 53-30-35)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR SSI 53-30-35 (L650 ONLY)								Service	ATA:53
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL		
	HRS	0								
	AFL	0								
					PROC. REF: NDT 53-31-00					PKG:6016
53-31-00-220-820-L00 ^S	DETAILED INSPECTION (INTERNAL) OF FUSELAGECOMPONENTS: FUSELAGE SKIN PANEL AT STRINGERS,FRAMES/BULKHEADS AND SPLICES (SSI 53-30-36).								Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
					PROC. REF: NDT 53-31-00					PKG:5016,6032
53-31-00-220-821-L00 ^S	DETAILED INSPECTION (EXTERNAL) OF FUSELAGECOMPONENTS: FUSELAGE SKIN PANEL AT STRINGERS,FRAMES/BULKHEADS, AND SPLICES (SSI 53-30-07). FUSELAGE SKIN PANEL AT PRESSURE BULKHEAD (SSI53-30-15). FUSELAGE MACHINED BULKHEAD (SSI 53-30-30).NOTE: REMOVE BUMPER PLATES, IF INSTALLED								Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
					PROC. REF: NDT 53-31-00					PKG:5016,6016

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
53-31-00-220-C01-L00 ^S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- TOILET WASTE DRAIN VALVE SUPPORT (SSI 53-30-29)- FRAMES (SSI 53-30-43)								Service	ATA:53
MOS	29-Jun-23		48 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		2000 (+20/-20)							
AFL	5401		1000 (+20/-20)							
PROC. REF: CPM 53-31-00										PKG:5008,6016
53-31-00-220-C02-L00 ^S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/BULK HEADS, AND SPLICES (SSI 53-30-07)								Service	ATA:53
MOS	29-Jun-23		48 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		2000 (+20/-20)							
AFL	5401		1000 (+20/-20)							
PROC. REF: CPM 53-31-00										PKG:5008,6016
53-31-00-220-C03-L00 ^S	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN PANEL AT PRESSURE BULKHEAD(SS I 53-30-15)								Service	ATA:53
MOS	29-Jun-23		48 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		2000 (+20/-20)							
AFL	5401		1000 (+20/-20)							
PROC. REF: CPM 53-31-00										PKG:5008,6016
53-31-00-220-C04-L00 ^S	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- TOILET WASTE DRAIN VALVE SUPPORT (SSI 53-30-29)								Service	ATA:53
MOS	29-Jun-23		48 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		2000 (+20/-20)							
AFL	5401		1000 (+20/-20)							
PROC. REF: CPM 53-31-00										PKG:5008,6016
53-31-00-220-C05-L00 ^S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- FRAMES (SSI 53-30-43)								Service	ATA:53
MOS	29-Jun-23		96 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		4000 (+20/-20)							
AFL	5401		2000 (+20/-20)							
PROC. REF: CPM 53-31-00										PKG:5016,6032
53-31-00-250-801-L00	SPECIAL DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENT BY USING EDDY CURRENT HIGH FREQUENCY INSPECTION METHOD:- TOILET WASTE DRAIN VALVE SUPPORT (SSI 53-30-29)NOTE: APPLICABLE TO AIRCRAFT POST-MOD. S.B.145LEG-00-0007 OR WITH AN EQUIVALENT MODIFICATION FACTORY-INCORPORATED.								Service	ATA:53
MOS/MSC	27-Aug-07		N/A							
HRS	0									
AFL	0									
PROC. REF: NDT 53-31-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
53-31-00-250-802-L00 ^S	SPECIAL DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENT BY USING EDDY CURRENT LOW FREQUENCY INSPECTION METHOD:- BAGGAGE DOOR CUTOUT STRUCTURE (SSI 53-30-48)								Service	ATA:53
MOS	27-Aug-07		T:288 (+15d/-15d)		27-Aug-31 (M)		11-Sep-31	2476 d (+15)	LOW UTILIZATION	
HRS			T:12000 (+20/-20)		12000 (M)		12020	1404.4 (+20)		
AFL			T:6000 (+20/-20)		6000 (M)		6020	351 (+20)		
PROC. REF: NDT 53-31-00										PKG:5018
53-31-00-250-803-L00 ^S	SPECIAL DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENT BY USING EDDY CURRENT HIGH FREQUENCY INSPECTION METHOD:- BAGGAGE DOOR CUTOUT STRUCTURE (SSI 53-30-48)								Service	ATA:53
MOS	27-Aug-07		T:288 (+15d/-15d)		27-Aug-31 (M)		11-Sep-31	2476 d (+15)	LOW UTILIZATION	
HRS			T:12000 (+20/-20)		12000 (M)		12020	1404.4 (+20)		
AFL			T:6000 (+20/-20)		6000 (M)		6020	351 (+20)		
PROC. REF: NDT 53-31-00										PKG:5018
53-31-00-250-804-L00 ^S	SPECIAL DETAILED INSPECTION (EXTERNAL) OFFUSELAGE SKIN AT FRAMES 61, 62, AND 63,BY USING THE HIGH FREQUENCY EDDY CURRENTMETHOD: FUSELAGE SKIN PANEL AT STRINGERS,FRAMES/BULKHEADS, AND SPLICES: (SSI 53-30-07)								Service	ATA:53
MOS	29-Jun-23		96 (+15d/-15d)						LOW UTILIZATION	
HRS	10161.5		4000 (+20/-20)							
AFL	5401		2000 (+20/-20)							
PROC. REF: NDT 53-31-00										PKG:5016,6016
53-31-00-250-805-L00 ^S	SPECIAL DETAILED INSPECTION (INTERNAL) AFT SIDEOF THE REAR PRESSURE BULKHEAD, BY USING THEHIGH FREQUENCY EDDY CURRENT METHOD. REAR PRESSURE BULKHEAD. (SSI 53-30-36)								Service	ATA:53
MOS	27-Aug-07		T:288 (+15d/-15d)						LOW UTILIZATION	
HRS	0		T:12000 (+20/-20)							
AFL	0		T:6000 (+20/-20)							
PROC. REF: NDT 53-31-00										PKG:5025
53-31-00-250-806-L00 ^S	SPECIAL DETAILED INSPECTION (EXTERNAL) OFFUSELAGE COMPONENT BY USING HIGH FREQUENCYEDDY CURRENT METHOD: SSI 53-30-15 (FUSELAGE SKIN PANEL ATPRESSURE BULKHEAD. SSI 53-30-30 (FUSELAGE MACHINED BULKHEAD)								Service	ATA:53
MOS	27-Aug-07		T:288 (+15d/-15d)						LOW UTILIZATION	
HRS	0		T:12000 (+20/-20)							
AFL	0		T:6000 (+20/-20)							
PROC. REF: NDT 53-31-00										PKG:5018
53-32-00-210-801-L00 ^S	GENERAL VISUAL INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- APU MOUNTING (SSI 53-30-40)								Service	ATA:53
MOS	29-Jun-23		96 (+15d/-15d)						LOW UTILIZATION	
HRS	10161.5		4000 (+20/-20)							
AFL	5401		2000 (+20/-20)							
PROC. REF: NDT 53-32-00										PKG:5016,6032

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
53-32-00-210-802-L00 ^S	GENERAL VISUAL INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- TAIL CONE ACCESS DOOR CUT- OUT STRUCTURE(SS1 53-30-50)								Service	ATA:53
MOS	29-Jun-23	96 (+15d/-15d)						LOW UTILIZATION		
HRS	10161.5	4000 (+20/-20)								
AFL	5401	2000 (+20/-20)								
PROC. REF: NDT 53-32-00								PKG:5016,6032		
53-32-00-210-C01-L00 ^S	GENERAL VISUAL INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/BULKHEADS, AND SPLICES (SSI 53-30-07)								Service	ATA:53
MOS	29-Jun-23	48 (+15d/-15d)						LOW UTILIZATION		
HRS	10161.5	2000 (+20/-20)								
AFL	5401	1000 (+20/-20)								
PROC. REF: CPM 53-32-00								PKG:5009		
53-32-00-210-C02-L00 ^S	GENERAL VISUAL INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/BULKHEADS, AND SPLICES (SSI 53-30-07)- FUSELAGE SKIN LONGITUDINAL SPLICE (SSI 53-30-08)- FUSELAGE SKIN CIRCUMFERENTIAL SPLICE(SS1 53-30-14)- TAIL CONE FRAME AT APU MOUNTING ATTACHMENT (SSI 53-30-39)								Service	ATA:53
MOS	29-Jun-23	48 (+15d/-15d)						LOW UTILIZATION		
HRS	10161.5	2000 (+20/-20)								
AFL	5401	1000 (+20/-20)								
PROC. REF: CPM 53-32-00								PKG:5009		
53-32-00-220-801-L00 ^S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE TO VERTICAL STABILIZER SPAR ATTACHMENT FITTING (SSI 53-30-38)								Service	ATA:53
MOS	08-Jul-15	192 (+15d/-15d)						LOW UTILIZATION		
HRS	7460.3	8000 (+20/-20)								
AFL	3992	4000 (+20/-20)								
PROC. REF: NDT 53-32-00								PKG:5032,6032		
53-32-00-220-802-L00 ^S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- FUSELAGE MACHINED BULKHEAD (SSI 53-30-30)								Service	ATA:53
MOS	07-Jul-15	192 (+15d/-15d)						LOW UTILIZATION		
HRS	7460.3	8000 (+20/-20)								
AFL	3992	4000 (+20/-20)								
PROC. REF: NDT 53-32-00								PKG:5032,6032		
53-32-00-220-803-L00 ^S	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS:- L PROFILE STRAKE ATTACHMENT (SSI 53-30-53)								Service	ATA:53
MOS	29-Jun-23	96 (+15d/-15d)						LOW UTILIZATION		
HRS	10161.5	4000 (+20/-20)								
AFL	5401	2000 (+20/-20)								
PROC. REF: NDT 53-32-00								PKG:5016,6032		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
53-32-00-220-L00 ^S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- TAIL CONE ACCESS DOOR CUT- OUT STRUCTURE(SS1 53-30-50)								Service	ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
					PROC. REF: NDT 53-32-00					PKG:5016,6032
53-32-00-220-C01-L00 ^S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- REAR PRESSURE BULKHEAD (SSI 53-30-36)								Service	ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: CPM 53-32-00					PKG:5008,6016
53-32-00-220-C02-L00 ^S	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS:- FRAMES (SSI 53-30-43)								Service	ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: CPM 53-32-00					PKG:5009
53-Z111-213-001-A00 ^S	GENERAL VISUAL INSPECTION(EXTERNAL) (ZONE 111)								Service	ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: AMM 05-20-01					PKG:5008,6016
53-Z111-214-001-A00 ^S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONE 111)								Service	ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: AMM 05-20-01					PKG:5008,6016
53-Z113-213-001-A00 ^S	GENERAL VISUAL INSPECTION(EXTERNAL) (ZONE 113, 114)								Service	ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: AMM 05-20-03					PKG:5008,6016
53-Z113-214-001-A00 ^S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONE 113)								Service	ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: AMM 05-20-03					PKG:5008,6016

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
53-Z114-214-001-A00 ^S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONE 114) (L600 ONLY)									Service ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
	PROC. REF: AMM 05-20-03									PKG:5008,6016
53-Z114-214-001-A01	GENERAL VISUAL INSPECTION(INTERNAL) (ZONE 114)NOTE:EWIS (L650 ONLY)									Service ATA:53
	MOS/MSC	25-Sep-07	N/A					ZONAL		
	HRS	0								
	AFL	0								
	PROC. REF: AMM 05-20-03									PKG:6016
53-Z123-213-001-A00 ^S	GENERAL VISUAL INSPECTION(EXTERNAL) (ZONE 123, 124)									Service ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
	PROC. REF: AMM 05-20-10									PKG:5008,6016
53-Z123-214-001-A00 ^S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONE 121, 122, 123 AND 124) (L600 ONLY)									Service ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
	PROC. REF: AMM 05-20-10									PKG:5008,6016
53-Z123-214-001-A01	GENERAL VISUAL INSPECTION(INTERNAL) (ZONE 121, 122, 123 AND 124)NOTE:EWIS (L650 ONLY)									Service ATA:53
	MOS/MSC	25-Sep-07	N/A					ZONAL		
	HRS	0								
	AFL	0								
	PROC. REF: AMM 05-20-10									PKG:6016
53-Z131-213-001-A00 ^S	GENERAL VISUAL INSPECTION(EXTERNAL) (ZONES 131 AND 132)									Service ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
	PROC. REF: AMM 05-20-17									PKG:5008,6016
53-Z131-214-001-A00 ^S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 131 AND 132) (L600 ONLY)									Service ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
	PROC. REF: AMM 05-20-17									PKG:5008,6016

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
53-Z131-214-001-A01	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 131 AND 132)NOTE:EWIS (L650 ONLY)									Service ATA:53
	MOS/MSC	25-Sep-07	N/A					ZONAL		
	HRS	0								
	AFL	0								
	PROC. REF: AMM 05-20-17									PKG:6016
53-Z141-213-001-A00 ^S	GENERAL VISUAL INSPECTION(EXTERNAL) (ZONES 141 AND 142)									Service ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
	PROC. REF: AMM 05-20-21									PKG:5016,6032
53-Z141-214-001-A00 ^S	GENERAL VISUAL INSPECTION (INTERNAL) (ZONES 141 AND 142). (L600 ONLY)									Service ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
	PROC. REF: AMM 05-20-21									PKG:5008,6016
53-Z141-214-001-A01	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 141 AND 142)NOTE:EWIS (L650 ONLY)									Service ATA:53
	MOS/MSC	25-Sep-07	N/A					ZONAL		
	HRS	0								
	AFL	0								
	PROC. REF: AMM 05-20-21									PKG:6016
53-Z151-214-002-A00 ^S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 151, 152, 153, 154, 155, 156, 157) (L600 ONLY)									Service ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
	PROC. REF: AMM 05-20-26									PKG:5008,6016
53-Z151-214-002-A01	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 151, 152, 153, 154, 155, 156, 157)NOTE:EWIS (L650 ONLY)									Service ATA:53
	MOS/MSC	25-Sep-07	N/A					ZONAL		
	HRS	0								
	AFL	0								
	PROC. REF: AMM 05-20-26									PKG:6016
53-Z155-214-001-A00 ^S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 155, 156 AND 157) (L600 ONLY)									Service ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
	PROC. REF: AMM 05-20-28									PKG:5008,6016

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
53-Z155-214-001-A01	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 155, 156 AND 157)NOTE:EWIS (L650 ONLY)									Service ATA:53
	MOS/MSC	25-Sep-07	N/A					ZONAL		
	HRS	0								
	AFL	0								
	PROC. REF: AMM 05-20-28									PKG:6016
53-Z161-214-001-A00 ^S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 161, 162) (L600 ONLY)									Service ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
	PROC. REF: AMM 05-20-33									PKG:5008,6016
53-Z161-214-001-A01	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 161, 162)NOTE:EWIS (L650 ONLY)									Service ATA:53
	MOS/MSC	25-Sep-07	N/A					ZONAL		
	HRS	0								
	AFL	0								
	PROC. REF: AMM 05-20-33									PKG:6016
53-Z171-213-001-A00 ^S	GENERAL VISUAL INSPECTION (EXTERNAL) (ZONES 171 AND 172)									Service ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
	PROC. REF: AMM 05-20-38									PKG:5008,6016
53-Z171-214-001-A00 ^S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 171 AND 172) (L600 ONLY)									Service ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
	PROC. REF: AMM 05-20-38									PKG:5008,6016
53-Z171-214-001-A01	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 171 AND 172) NOTE:EWIS (L650 ONLY)									Service ATA:53
	MOS/MSC	25-Sep-07	N/A					ZONAL		
	HRS	0								
	AFL	0								
	PROC. REF: AMM 05-20-38									PKG:6016
53-Z191-213-001-A00 ^S	GENERAL VISUAL INSPECTION (EXTERNAL) (ZONES 191, 192, 193, 194, 195, 196, 197,198, 199, 1921, 1922, 1923, 1971, 1981, 1982, 1991 AND 1992).NOTE: DO NOT REMOVE THE FUEL TANK (L600 ONLY)									Service ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
	PROC. REF: AMM 05-20-95									PKG:5008,6016

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
53-Z191-213-002-A00	GENERAL VISUAL INSPECTION (EXTERNAL) (ZONES 191, 192, 1921, 1923, 1924, 193, 1932, 194, 195, 196, 197, 1971, 1972, 198, 1981, 1982, 199, 1991 AND 1992). NOTE: DO NOT REMOVE THE FUEL TANK (L650 ONLY)								Service	ATA:53
	MOS/MSC	25-Sep-07	N/A					ZONAL		
	HRS	0								
	AFL	0								
	PROC. REF: AMM 05-20-95									PKG:6016
53-Z191-214-001-A00 ^S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 191, 192, 193, 194, 195, 196, 198, 199, 1921, 1922, 1923, 1971, 1981, 1982,1991 AND 1992). (L600 ONLY)								Service	ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
	PROC. REF: AMM 05-20-95									PKG:5008,6016
53-Z191-214-003-A00	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 191, 192, 1921, 1922, 1923, 1924, 193, 1932, 194, 195, 196, 1971, 198, 1981, 1982, 199, 1991, 1992).NOTE:EWIS (L650 ONLY)								Service	ATA:53
	MOS/MSC	25-Sep-07	N/A					ZONAL		
	HRS	0								
	AFL	0								
	PROC. REF: AMM 05-20-95									PKG:6016
53-Z197-214-001-A00 ^S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 197) (L600 ONLY)								Service	ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
	PROC. REF: AMM 05-20-96									PKG:5008,6016
53-Z197-214-001-A01	GENERAL VISUAL INSPECTION(INTERNAL) (ZONE 197) NOTE:EWIS (L650 ONLY)								Service	ATA:53
	MOS/MSC	25-Sep-07	N/A					ZONAL		
	HRS	0								
	AFL	0								
	PROC. REF: AMM 05-20-96									PKG:6016
53-Z197-214-002-A00	GENERAL VISUAL INSPECTION(INTERNAL) (ZONE 1972)NOTE:EWIS (L650 ONLY)								Service	ATA:53
	MOS/MSC	25-Sep-07	N/A					ZONAL		
	HRS	0								
	AFL	0								
	PROC. REF: AMM 05-30-37									PKG:6016

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 53 - FUSELAGE											
53-Z213-213-001-A00 ^S	GENERAL VISUAL INSPECTION(EXTERNAL) (ZONE 213, 214)								Service	ATA:53	
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	2000 (+20/-20)								
	AFL	5401	1000 (+20/-20)								
	PROC. REF: AMM 05-20-06									PKG:5008,6016	
53-Z213-214-001-A00 ^S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 113, 114, 213, 214, 215, 216) (L600 ONLY)								Service	ATA:53	
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	2000 (+20/-20)								
	AFL	5401	1000 (+20/-20)								
	PROC. REF: AMM 05-20-06									PKG:5008,6016	
53-Z213-214-001-A01	GENERAL VISUAL INSPECTION(INTERNAL) (ZONE 113, 114, 213, 214, 215, 216)NOTE:EWIS (L650 ONLY)								Service	ATA:53	
	MOS/MS	25-Sep-07	N/A					ZONAL			
	HRS	0									
	AFL	0									
	PROC. REF: AMM 05-20-06									PKG:6016	
53-Z223-213-001-A00 ^S	GENERAL VISUAL INSPECTION(EXTERNAL) (ZONES 223, 224)								Service	ATA:53	
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	2000 (+20/-20)								
	AFL	5401	1000 (+20/-20)								
	PROC. REF: AMM 05-20-13									PKG:5008,6016	
53-Z223-214-001-A00 ^S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 221, 222, 223 AND 224) (L600 ONLY)								Service	ATA:53	
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	2000 (+20/-20)								
	AFL	5401	1000 (+20/-20)								
	PROC. REF: AMM 05-20-13									PKG:5008,6016	
53-Z225-213-001-A00 ^S	GENERAL VISUAL INSPECTION(EXTERNAL) (ZONES 225 AND 226)								Service	ATA:53	
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	4000 (+20/-20)								
	AFL	5401	2000 (+20/-20)								
	PROC. REF: AMM 05-20-15									PKG:5016,6032	
53-Z225-214-001-A00 ^S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 225 AND 226)								Service	ATA:53	
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	4000 (+20/-20)								
	AFL	5401	2000 (+20/-20)								
	PROC. REF: AMM 05-20-15									PKG:5016,6032	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
53-Z231-213-001-A00	GENERAL VISUAL INSPECTION(EXTERNAL) (ZONES 231 AND 232)NOTE: APPLICABLE TO AIRCRAFT PRE-MOD. SB 145LEG-53-0031.									Service ATA:53
	MOS/MSC	15-Aug-16	N/A							
	HRS	7841.1								
	AFL	4202								
PROC. REF: AMM 05-20-18										
53-Z231-213-001-A01 ^S	GENERAL VISUAL INSPECTION(EXTERNAL) (ZONES 231 AND 232)NOTE: APPLICABLE TO AIRCRAFT POST-MOD. SB 145LEG-53-0031 OR WITH AN EQUIVALENT MODIFICATION FACTORY-INCORPORATED.									Service ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
PROC. REF: AMM 05-20-18										
53-Z231-214-001-A00 ^S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 231 AND 232)									Service ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
PROC. REF: AMM 05-20-18										
53-Z233-213-001-A00 ^S	GENERAL VISUAL INSPECTION(EXTERNAL) (ZONES 233 AND 234)									Service ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
PROC. REF: AMM 05-20-19										
53-Z233-214-001-A00 ^S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 233 AND 234)									Service ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
PROC. REF: AMM 05-20-19										
53-Z241-213-001-A00 ^S	GENERAL VISUAL INSPECTION(EXTERNAL) (ZONES 241 AND 242)									Service ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
PROC. REF: AMM 05-20-23										
53-Z241-214-001-A00 ^S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 241 AND 242)									Service ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
PROC. REF: AMM 05-20-23										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
53-Z243-213-003-A00 ^S	GENERAL VISUAL INSPECTION(EXTERNAL) (ZONES 243 AND 244)									Service ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
					PROC. REF: AMM 05-20-25					PKG:5016,6032
53-Z243-214-001-A00 ^S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 243 AND 244)									Service ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
					PROC. REF: AMM 05-20-25					PKG:5016,6032
53-Z251-213-001-A00 ^S	GENERAL VISUAL INSPECTION(EXTERNAL) (ZONES 251 AND 252)									Service ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
					PROC. REF: AMM 05-20-30					PKG:5016,6032
53-Z251-214-001-A00 ^S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 251 AND 252)									Service ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
					PROC. REF: AMM 05-20-30					PKG:5016,6032
53-Z253-213-001-A00 ^S	GENERAL VISUAL INSPECTION(EXTERNAL) (ZONES 253 AND 254)									Service ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
					PROC. REF: AMM 05-20-31					PKG:5016,6032
53-Z253-214-001-A00 ^S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 253 AND 254)									Service ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
					PROC. REF: AMM 05-20-31					PKG:5016,6032
53-Z261-213-001-A00 ^S	GENERAL VISUAL INSPECTION(EXTERNAL) (ZONES 261, 262)									Service ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
					PROC. REF: AMM 05-20-35					PKG:5016,6032

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
53-Z261-214-001-A00 ^S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 261, 262)									Service ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
	PROC. REF: AMM 05-20-35									PKG:5008,6016
53-Z263-213-002-A00 ^S	GENERAL VISUAL INSPECTION(EXTERNAL) (ZONES 263 AND 264)									Service ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
	PROC. REF: AMM 05-20-36									PKG:5016,6032
53-Z263-214-001-A00 ^S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 263 AND 264) (L600 ONLY)									Service ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
	PROC. REF: AMM 05-20-36									PKG:5016,6032
53-Z263-214-001-A01	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 263 AND 264)NOTE:EWIS (L650 ONLY)									Service ATA:53
	MOS/MSC	25-Sep-07	N/A					ZONAL		
	HRS	0								
	AFL	0								
	PROC. REF: AMM 05-20-36									PKG:6032
53-Z271-213-001-A00 ^S	GENERAL VISUAL INSPECTION(EXTERNAL) (ZONES 271, 272)									Service ATA:53
	MOS	29-Jun-23	24 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	1000 (+20/-20)							
	AFL	5401								
	PROC. REF: AMM 05-20-40									PKG:5004
53-Z271-214-001-A00 ^S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 271, 272) (L600 ONLY)									Service ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
	PROC. REF: AMM 05-20-40									PKG:5008,6016
53-Z271-214-001-A01	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 271, 272)NOTE:EWIS (L650 ONLY)									Service ATA:53
	MOS/MSC	25-Sep-07	N/A					ZONAL		
	HRS	0								
	AFL	0								
	PROC. REF: AMM 05-20-40									PKG:6016

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
53-Z273-213-002-A00 ^S	GENERAL VISUAL INSPECTION(EXTERNAL) (ZONES 273 AND 274)									Service ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
	PROC. REF: AMM 05-20-44									PKG:5016,6032
53-Z273-214-002-A00 ^S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 273 AND 274) (L600 ONLY)									Service ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
	PROC. REF: AMM 05-20-44									PKG:5008,6016
53-Z273-214-002-A01	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 273 AND 274)NOTE:EWIS (L650 ONLY)									Service ATA:53
	MOS/MSC	25-Sep-07	N/A					ZONAL		
	HRS	0								
	AFL	0								
	PROC. REF: AMM 05-20-44									PKG:6016
53-Z275-214-001-A00 ^S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 275 AND 276) (L600 ONLY)									Service ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
	PROC. REF: AMM 05-20-41									PKG:5008,6016
53-Z275-214-001-A01	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 275 AND 276)NOTE:EWIS (L650 ONLY)									Service ATA:53
	MOS/MSC	25-Sep-07	N/A					ZONAL		
	HRS	0								
	AFL	0								
	PROC. REF: AMM 05-20-41									PKG:6016
53-Z311-213-001-A00 ^S	GENERAL VISUAL INSPECTION(EXTERNAL) (ZONES 311 AND 312)									Service ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
	PROC. REF: AMM 05-20-46									PKG:5008,6016
53-Z311-214-001-A00 ^S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 311 AND 312) (L600 ONLY)									Service ATA:53
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
	PROC. REF: AMM 05-20-46									PKG:5008,6016

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
53-Z311-214-001-A01	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 311 AND 312)NOTE:EWIS (L650 ONLY)									Service ATA:53
	MOS/MSC	25-Sep-07	N/A					ZONAL		
	HRS	0								
	AFL	0								
	PROC. REF: AMM 05-20-46									PKG:6016
53-Z313-213-001-A00 ^S	GENERAL VISUAL INSPECTION(EXTERNAL) (ZONE 313)									Service ATA:53
	MOS	29-Jun-23	24 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	1000 (+20/-20)							
	AFL	5401								
	PROC. REF: AMM 05-20-47									PKG:5004
53-Z313-214-001-A00 ^S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONE 313) (L600 ONLY)									Service ATA:53
	MOS	29-Jun-23	24 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	1000 (+20/-20)							
	AFL	5401								
	PROC. REF: AMM 05-20-47									PKG:5004
53-Z313-214-001-A01	GENERAL VISUAL INSPECTION(INTERNAL) (ZONE 313)NOTE:EWIS (L650 ONLY)									Service ATA:53
	MOS/MSC	25-Sep-07	N/A					ZONAL		
	HRS	0								
	AFL	0								
	PROC. REF: AMM 05-20-47									PKG:5016,6032
53-Z315-213-001-A00 ^S	GENERAL VISUAL INSPECTION(EXTERNAL) (ZONES 315, 316, 317, 318)									Service ATA:53
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
	PROC. REF: AMM 05-20-45									PKG:5016,6032
530401-0101	LH FAIRING ASSY									Component ATA:53
PN:135-12815-407	MOS/MSC	19-Aug-15	O/C	TSR 0						
SN:UNKNOWN	HRS	7460.3		TSR 0						
	AFL	3992		TSR 0						
	PROC. REF: AMM 53-04-01									
530401-0102	RH FAIRING ASSY									Component ATA:53
PN:135-12835-409	MOS/MSC	19-Aug-15	O/C	TSR 0						
SN:UNKNOWN	HRS	7460.3		TSR 0						
	AFL	3992		TSR 0						
	PROC. REF: AMM 53-04-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
530401-0103 FUS WING FAIRING ASSY FAIRING ASSY										Component ATA:53
PN:135-02858-403	MOS/MSC	19-Aug-15	O/C	TSR 0						
SN:UNKNOWN	HRS	7460.3		TSR 0						
	AFL	3992		TSR 0						
PROC. REF: AMM 53-04-01										
530410-0101 MID FAIRING ASSY										Component ATA:53
PN:135-08117-403	MOS/MSC	19-Aug-15	O/C	TSR 0						
SN:UNKNOWN	HRS	7460.3		TSR 0						
	AFL	3992		TSR 0						
PROC. REF: AMM 53-04-10										
530420-0101 LH FAIRING ASSY										Component ATA:53
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 53-04-20										
530420-0102 RH FAIRING ASSY										Component ATA:53
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 53-04-20										
530430-0101 FAIRING ASSY										Component ATA:53
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 53-04-30										
531400-0101 RADOME ANTENNA										Component ATA:53
PN:4980-101	MOS/MSC	06-Jul-19	O/C	TSR 0						
SN:1205	HRS	9057.4		TSR 0						
	AFL	4853		TSR 0						
PROC. REF: AMM 53-11-01										
531500-0101 CENTER FUSELAGE ASSY STRUCTURE										Component ATA:53
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 53-04-10										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
533200-0101	REAR FUS ACCESS TAIL CONE									Component ATA:53
PN:120-24234-043	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:0000125482	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: AMM 53-32-00										
533210-0101	SILENCER -EXHAUST,APU ASSEMBLY									Component ATA:53
PN:PN	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: AMM 49-81-01										
533500-0101	TAIL LEADING EDGE,VERTICAL FIN ASSEMBLY									Component ATA:53
PN:145-35015-417	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:0000133367	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: AMM 55-35-00										
ATA 54 - NACELLES/PYLONS										
54-50-00-210-801-L00 ^S	GENERAL VISUAL INSPECTION (EXTERNAL) OF PYLON COMPONENTS:- PYLON SKIN (SSI 54-50-04)									Service ATA:54
	MOS		29-Jun-23		48 (+15d/-15d)			LOW UTILIZATION		
	HRS		10161.5		2000 (+20/-20)					
	AFL		5401		1000 (+20/-20)					
PROC. REF: NDT 54-50-00										
54-50-00-220-802-L00 ^S	DETAILED INSPECTION (INTERNAL) OF PYLON COMPONENT:- FWD ENGINE MOUNTS (INCLUDING BOLTS) (SSI 54-50-03) (L600 ONLY)									Service ATA:54
	MOS		29-Jun-23		48 (+15d/-15d)			LOW UTILIZATION		
	HRS		10161.5		2000 (+20/-20)					
	AFL		5401		1000 (+20/-20)					
PROC. REF: NDT 54-50-00										
54-50-00-220-803-L00 ^S	DETAILED INSPECTION (INTERNAL) OF PYLON COMPONENTS:- PYLON SPARS I, II, III AND IV (SSI 54-50-01)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI (L600 ONLY)									Service ATA:54
	MOS		29-Jun-23		96 (+15d/-15d)			LOW UTILIZATION		
	HRS		10161.5		4000 (+20/-20)					
	AFL		5401		2000 (+20/-20)					
PROC. REF: NDT 54-50-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 54 - NACELLES/PYLONS										
54-50-00-220-804-L00	DETAILED INSPECTION (INTERNAL) OF PYLON COMPONENTS:- PYLON SPARS I, II, III AND IV (SSI 54-50-01)NOTE: DURING THIS INSPECTION, THE C/PCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI. (L650 ONLY)								Service	ATA:54
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL		
	HRS	0								
	AFL	0								
PROC. REF: NDT 54-50-00										
54-50-00-220-805-L00	DETAILED INSPECTION (INTERNAL) OF PYLON COMPONENT:- FWD ENGINE MOUNTS (INCLUDING BOLTS) (SSI 54-50-03) (L650 ONLY)								Service	ATA:54
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL		
	HRS	0								
	AFL	0								
PROC. REF: NDT 54-50-00										PKG:6016
54-50-00-220-806-L00 ^S	DETAILED INSPECTION (INTERNAL) OF PYLON COMPONENT:- AFT ENGINE MOUNTS (INCLUDING BOLTS) (SSI 54-50-07) (L600 ONLY)								Service	ATA:54
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
PROC. REF: NDT 54-50-00										PKG:5008
54-50-00-220-807-L00	DETAILED INSPECTION (INTERNAL) OF PYLON COMPONENT:- AFT ENGINE MOUNTS (INCLUDING BOLTS) (SSI 54-50-07) (L650 ONLY)								Service	ATA:54
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL		
	HRS	0								
	AFL	0								
PROC. REF: NDT 54-50-00										PKG:6016
54-50-00-220-808-L00 ^S	DETAILED INSPECTION (INTERNAL) OF PYLON COMPONENT:- PYLON YOKES I AND II (SSI 54-50-05) PRIMARY ELEMENT.								Service	ATA:54
	MOS	10-Jul-15	192 (+15d/-15d)					LOW UTILIZATION		
	HRS	7460.3	8000 (+20/-20)							
	AFL	3992	4000 (+20/-20)							
PROC. REF: NDT 54-50-00										PKG:5032,6032
54-50-00-220-809-L00 ^S	DETAILED INSPECTION (INTERNAL) OF PYLON COMPONENT:- PYLON YOKES I AND II (SSI 54-50-05) SECONDARY ELEMENT.								Service	ATA:54
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
PROC. REF: NDT 54-50-00										PKG:5011
54-50-00-220-C01-L00 ^S	DETAILED INSPECTION (INTERNAL) OF PYLON COMPONENTS:- PYLON YOKES III AND IV (SSI 54-50-02)								Service	ATA:54
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
PROC. REF: CPM 54-50-00										PKG:5008,6016

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 54 - NACELLES/PYLONS										
54-50-00-220-C02-L00 ^S	DETAILED INSPECTION (INTERNAL) OF PYLON COMPONENTS:- PYLON YOKES I AND II (SSI 54-50-05)								Service	ATA:54
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: CPM 54-50-00					PKG:5008,6016
54-50-00-220-C03-L00 ^S	DETAILED INSPECTION (INTERNAL) OF PYLON COMPONENTS:- PYLON YOKES I AND II UPPER FLANGE (SSI 54-50-06).								Service	ATA:54
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: CPM 54-50-00					PKG:5008,6016
54-50-00-230-801-L00	SPECIAL DETAILED INSPECTION (INTERNAL) OF PYLON COMPONENTS BY LIQUID PENETRANT INSPECTION METHOD:- FWD ENGINE MOUNTS(INCLUDING BOLTS) (SSI 54-50-03) (L650 ONLY)								Service	ATA:54
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL		
	HRS	0								
	AFL	0								
					PROC. REF: NDT 54-50-00					
54-50-00-250-801-L00 ^S	SPECIAL DETAILED INSPECTION (INTERNAL) OF PYLON COMPONENTS BY THE EDDY CURRENT METHOD:- PYLON YOKES I AND II (SSI 54-50-05)								Service	ATA:54
	MOS		288 (+15d/-15d)					LOW UTILIZATION		
	HRS		12000 (+20/-20)							
	AFL		6000 (+20/-20)							
					PROC. REF: NDT 54-50-00					PKG:5140
54-50-00-250-802-L00	SPECIAL DETAILED INSPECTION (INTERNAL) OF PYLON COMPONENTS BY THE EDDY CURRENT METHOD:- PYLON YOKES I AND II UPPER FLANGE (SSI 54-50-06)NOTE: APPLICABLE TO AIRCRAFT PRE-MOD SB145LEG-54-0001								Service	ATA:54
	MOS/MSC		N/A							
	HRS									
	AFL									
					PROC. REF: NDT 54-50-00					PKG:6016
54-50-00-250-802-L01 ^S	SPECIAL DETAILED INSPECTION (INTERNAL) OF PYLON COMPONENTS BY THE EDDY CURRENT METHOD:- PYLON YOKES I AND II UPPER FLANGE (SSI 54-50-06)NOTE: APPLICABLE TO AIRCRAFT POST-MOD SB145LEG-54-0001 OR WITH AN EQUIVALENT MODIFICATION FACTORY-INCORPORATED.								Service	ATA:54
	MOS	27-Aug-07	192 (+15d/-15d)					LOW UTILIZATION		
	HRS	0	8000 (+20/-20)							
	AFL	0	4000 (+20/-20)							
					PROC. REF: NDT 54-50-00					PKG:5032,6032

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 54 - NACELLES/PYLONS										
54-50-00-290-801-L00 ^S	SPECIAL DETAILED INSPECTION (INTERNAL) OF PYLON COMPO- NENT USING BOROSCOPE:- PYLON SKIN (SSI 54-50-04)NOTE: DURING THIS INSPECTION, THE C/PCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI								Service	ATA:54
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: NDT 54-50-00					PKG:5008,6016
54-Z414-213-001-A00 ^S	GENERAL VISUAL INSPECTION(EXTERNAL) (ZONES 414 AND 424)								Service	ATA:54
	MOS	29-Jun-23	24 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	1000 (+20/-20)							
	AFL	5401								
					PROC. REF: AMM 05-20-72					PKG:5004
54-Z414-214-001-A00 ^S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 414 AND 424) (L600 ONLY)								Service	ATA:54
	MOS	29-Jun-23	24 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	1000 (+20/-20)							
	AFL	5401								
					PROC. REF: AMM 05-20-72					PKG:5004
54-Z414-214-001-A01	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 414 AND 424)NOTE:EWIS (L650 ONLY)								Service	ATA:54
	MOS/MSC	25-Sep-07	N/A					ZONAL		
	HRS	0								
	AFL	0								
					PROC. REF: AMM 05-20-72					
ATA 55 - STABILIZERS										
55-10-00-210-802-L00 ^S	GENERAL VISUAL INSPECTION (EXTERNAL) OF HORIZONTAL STABILIZER COMPONENTS:- SKIN, FROM RIB STA. YH=350 TO RIB STA. YH=990 - UPPER SURFACE (SSI 55-10-07)								Service	ATA:55
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
					PROC. REF: NDT 55-10-00					PKG:5016,6032
55-10-00-210-805-L00 ^S	GENERAL VISUAL INSPECTION (EXTERNAL) OF HORIZONTAL STABILIZER COMPONENTS:- SUPPORT PULLEY CENTRAL STA- BILIZER (SSI 55-10-14)								Service	ATA:55
	MOS	10-Jul-15	192 (+15d/-15d)					LOW UTILIZATION		
	HRS	7460.3	8000 (+20/-20)							
	AFL	3992	4000 (+20/-20)							
					PROC. REF: NDT 55-10-00					PKG:5032,6032

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 55 - STABILIZERS										
55-10-00-210-C01-L00 ^S	GENERAL VISUAL INSPECTION (EXTERNAL) OF HORIZONTAL STABILIZER COMPONENTS:- U SHAPE, L SHAPE AND BOX STRUCTURE - ELEVATOR COMMAND (SSI 55-10-22)								Service	ATA:55
MOS	29-Jun-23		48 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		2000 (+20/-20)							
AFL	5401		1000 (+20/-20)							
PROC. REF: CPM 55-10-00										PKG:5008,6016
55-10-00-210-C02-L00 ^S	GENERAL VISUAL INSPECTION (EXTERNAL) OF HORIZONTAL STABILIZER COMPONENTS:- SUPPORT QUADRANT ASSY, STABILIZER (SSI 55-10-23)								Service	ATA:55
MOS	29-Jun-23		48 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		2000 (+20/-20)							
AFL	5401		1000 (+20/-20)							
PROC. REF: CPM 55-10-00										PKG:5009
55-10-00-220-801-L00 ^S	DETAILED INSPECTION (EXTERNAL) OF HORIZONTAL STABILIZER COMPONENTS:- ELEVATOR SUPPORT FITTINGS (SSI 55-10-15)								Service	ATA:55
MOS	29-Jun-23		48 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		2000 (+20/-20)							
AFL	5401		1000 (+20/-20)							
PROC. REF: NDT 55-10-00										PKG:5008,6016
55-10-00-220-802-L00 ^S	DETAILED INSPECTION (EXTERNAL) OF HORIZONTAL STABILIZER COMPONENTS:- FITTING HINGE SUPPORT STABILIZER (SSI 55-10-21)								Service	ATA:55
MOS	29-Jun-23		96 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		4000 (+20/-20)							
AFL	5401		2000 (+20/-20)							
PROC. REF: NDT 55-10-00										PKG:5016,6032
55-10-00-220-803-L00 ^S	DETAILED INSPECTION (INTERNAL) OF HORIZONTAL STABILIZER COMPONENT:- REAR SPAR WEB AND CAP, FROM FIN TO RIB STA. YH=350, INCLUDING CENTER FITTING/SPAR ATTACHMENT (SSI 55-10-12)								Service	ATA:55
MOS	29-Jun-23		96 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		4000 (+20/-20)							
AFL	5401		2000 (+20/-20)							
PROC. REF: NDT 55-10-00										PKG:5016,6032
55-10-00-220-804-L00 ^S	DETAILED INSPECTION (INTERNAL) OF HORIZONTAL STABILIZER COMPONENTS:- ROOT RIB (SSI 55-10-17)								Service	ATA:55
MOS	29-Jun-23		96 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		4000 (+20/-20)							
AFL	5401		2000 (+20/-20)							
PROC. REF: NDT 55-10-00										PKG:5016

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 55 - STABILIZERS										
55-10-00-220-805-L00 ^S	DETAILED INSPECTION (EXTERNAL) OF HORIZONTAL STABILIZER COMPONENTS:- SKIN, FROM FIN TO STA. YH=350 - LOWER SURFACE (SSI 55-10-06)- SKIN, FROM FIN TO STA. YH=350 - UPPER SURFACE(SS I 55-10-01) (L600 ONLY)								Service	ATA:55
MOS	29-Jun-23		96 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		4000 (+20/-20)							
AFL	5401		2000 (+20/-20)							
PROC. REF: NDT 55-10-00										PKG:5016
55-10-00-220-806-L00 ^S	DETAILED INSPECTION (INTERNAL) OF HORIZONTAL STABILIZER COMPONENTS:- SKIN SPLICE AT UPPER AND LOWER SURFACE (SSI 55-10-16)- FRONT/ REAR AUXILIARY SPAR CENTER FITTING (SSI 55-10-19)- REAR SPAR CENTER FITTING (SSI 55-10-18)- FRONT SPAR CENTER FITTINGS (SSI 55-10-20) (L600 ONLY)								Service	ATA:55
MOS	29-Jun-23		96 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		4000 (+20/-20)							
AFL	5401		2000 (+20/-20)							
PROC. REF: NDT 55-10-00										PKG:5017
55-10-00-220-808-L00 ^S	DETAILED INSPECTION (EXTERNAL) OF HORIZONTAL STABILIZER COMPONENTS:- SKIN, FROM RIB STA YH=350 TO RIB YH=990 - UPPER SURFACE (SSI 55-10-02) (L600 ONLY)								Service	ATA:55
MOS	29-Jun-23		96 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		4000 (+20/-20)							
AFL	5401		2000 (+20/-20)							
PROC. REF: NDT 55-10-00										PKG:5016
55-10-00-220-809-L00 ^S	DETAILED INSPECTION (INTERNAL) OF HORIZONTAL STABILIZER COMPONENTS:- FRONT AND REAR AUXILIARY SPAR WEBS AND CAPS,INCLUDING CENTER FIT- TING/SPAR ATTACHMENT (SSI 55-10-11) (L600 ONLY)								Service	ATA:55
MOS	29-Jun-23		96 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		4000 (+20/-20)							
AFL	5401		2000 (+20/-20)							
PROC. REF: NDT 55-10-00										PKG:5016,6016
55-10-00-220-810-L00 ^S	DETAILED INSPECTION (EXTERNAL) OF HORIZONTAL STABILIZER COMPONENTS:- SKIN, FROM RIB STA. YH=990 TO RIB STA. YH=2965 - UPPER SURFACE (SSI 55-10-03)								Service	ATA:55
MOS	29-Jun-23		96 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		4000 (+20/-20)							
AFL	5401		2000 (+20/-20)							
PROC. REF: NDT 55-10-00										PKG:5016,6016
55-10-00-220-811-L00 ^S	DETAILED INSPECTION (INTERNAL) OF HORIZONTAL STABILIZER COMPONENTS:- RIBS, FROM RIB STA. YH=30 TO RIB STA. YH=990 (SSI 55-10-04)- RIBS, FROM RIB STA. YH=990 TO RIB STA. YH=2965 (SSI 55-10-05)								Service	ATA:55
MOS	29-Jun-23		96 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		4000 (+20/-20)							
AFL	5401		2000 (+20/-20)							
PROC. REF: NDT 55-10-00										PKG:5016

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 55 - STABILIZERS											
55-10-00-220-812-L00 ^S			DETAILED INSPECTION (INTERNAL) OF HORIZONTAL STABILIZER COMPONENTS:- FRONT SPAR WEB AND CAP, FROM RIB STA. YH=350 TO RIB STA. YH=2965 (SSI 55-10-10) (L600 ONLY)						Service	ATA:55	
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	2000 (+20/-20)								
	AFL	5401	1000 (+20/-20)								
					PROC. REF: NDT 55-10-00					PKG:5009	
55-10-00-220-813-L00 ^S			DETAILED INSPECTION (INTERNAL) OF HORIZONTAL STABILIZER COMPONENTS:- FRONT SPAR WEB AND CAP, FROM FIN TO RIB STA. YH=350, INCLUDING CENTER FITTING /SPAR ATTACHMENT (SSI 55-10-09) (L600 ONLY)						Service	ATA:55	
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	2000 (+20/-20)								
	AFL	5401	1000 (+20/-20)								
					PROC. REF: NDT 55-10-00					PKG:5008	
55-10-00-220-814-L00			DETAILED INSPECTION (EXTERNAL) OF HORIZONTAL STABILIZER COMPONENTS:- SKIN, FROM FIN TO STA. YH=350 - LOWER SURFACE (SSI 55-10-06)- SKIN, FROM FIN TO STA. YH=350 - UPPER SURFACE (SSI 55-10-01) (L650 ONLY)						Service	ATA:55	
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL			
	HRS	0									
	AFL	0									
					PROC. REF: NDT 55-10-00					PKG:6016	
55-10-00-220-815-L00			DETAILED INSPECTION (INTERNAL) OF HORIZONTAL STABILIZER COMPONENTS:- SKIN SPLICE AT UPPER AND LOWER SURFACE (SSI 55-10-16)- FRONT/ REAR AUXILIARY SPAR CENTER FITTING (SSI 55-10-19)- REAR SPAR CENTER FITTING(SSSI 55-10-18)- FRONT SPAR CENTER FITTINGS(SSSI 55-10-20) (L650 ONLY)						Service	ATA:55	
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL			
	HRS	0									
	AFL	0									
					PROC. REF: NDT 55-10-00					PKG:6016	
55-10-00-220-816-L00			DETAILED INSPECTION (EXTERNAL) OF HORIZONTAL STABILIZER COMPONENTS:- SKIN, FROM RIB STA YH=350 TO RIB YH=990 - UPPER SURFACE (SSI 55-10-02) (L650 ONLY)						Service	ATA:55	
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL			
	HRS	0									
	AFL	0									
					PROC. REF: NDT 55-10-00					PKG:6016	
55-10-00-220-817-L00			DETAILED INSPECTION (INTERNAL) OF HORIZONTAL STABILIZER COMPONENTS:- FRONT AND REAR AUXILIARY SPAR WEBS AND CAPS, INCLUDING CENTER FITTING/SPAR ATTACHMENT (SSI 55-10-11) (L650 ONLY)						Service	ATA:55	
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL			
	HRS	0									
	AFL	0									
					PROC. REF: NDT 55-10-00					PKG:6032	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 55 - STABILIZERS											
55-10-00-220-818-L00	DETAILED INSPECTION (INTERNAL) OF HORIZONTAL STABILIZER COMPONENTS:- FRONT SPAR WEB AND CAP, FROM RIB STA. YH=350 TO RIB STA. YH=2965 (SSI 55-10-10) (L650 ONLY)								Service	ATA:55	
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL			
	HRS	0									
	AFL	0									
PROC. REF: NDT 55-10-00										PKG:6016	
55-10-00-220-C01-L00 ^S	DETAILED INSPECTION (INTERNAL) OF HORIZONTAL STABILIZER COMPONENTS:- FRONT SPAR WEB AND CAP, FROM FIN TO RIB STA. YH=350, INCLUDING CEN- TER FITTING/ SPAR ATTACHMENT (SSI 55-10-09)- REAR SPAR WEB & CAP, FROM RIB STA. YH=350 TO RIB STA. YH=2965, INCLUD- ING FITTING HINGE STABILIZER ATTACH TO ELEVATOR (SSI 55-10-13)								Service	ATA:55	
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	2000 (+20/-20)								
	AFL	5401	1000 (+20/-20)								
PROC. REF: CPM 55-10-00										PKG:5008,6016	
55-10-00-220-C02-L00 ^S	DETAILED INSPECTION (EXTERNAL) OF HORIZONTAL STA- BILIZER COMPONENTS:- SKIN, FROM RIB STA. YH=990 TO RIB STA. YH=2965- LOWER SURFACE (SSI 55-10-08)								Service	ATA:55	
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	2000 (+20/-20)								
	AFL	5401	1000 (+20/-20)								
PROC. REF: CPM 55-10-00										PKG:5008,6016	
55-10-00-220-C03-L00 ^S	DETAILED INSPECTION (INTERNAL) OF HORIZONTAL STABILIZER COMPONENTS:- PIN, INTERNAL AND EXTERNAL HINGE, STABILIZER (SSI 55-10-24)								Service	ATA:55	
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	2000 (+20/-20)								
	AFL	5401	1000 (+20/-20)								
PROC. REF: CPM 55-10-00										PKG:5008,6016	
55-10-00-240-801-L00 ^S	SPECIAL DETAILED INSPECTION (EXTERNAL) OF HORIZONTAL STABILIZER COMPONENTS BY THE MAGNETIC PARTICLE INSPECTION METHOD:- PIN, INTERNAL AND EXTERNAL HINGE, STABILIZER(SS I 55-10-24)								Service	ATA:55	
	MOS	27-Aug-07	288 (+15d/-15d)					LOW UTILIZATION			
	HRS	0	12000 (+20/-20)								
	AFL	0	6000 (+20/-20)								
PROC. REF: NDT 55-10-00										PKG:5140	
55-10-00-250-805-L00 ^S	SPECIAL DETAILED INSPECTION (EXTERNAL) OF HORIZONTAL STABILIZER COMPONENTS BY THE EDDY CURRENT INSPECTION METHOD:- SKIN, FROM FIN TO STA. YH=350 - UPPER SURFACE (SSI 55-10-01) (L600 ONLY)								Service	ATA:55	
	MOS	06-Jul-19	144 (+15d/-15d)					LOW UTILIZATION			
	HRS	9057.4	6000 (+20/-20)								
	AFL	4853	3000 (+20/-20)								
PROC. REF: NDT 55-10-00										PKG:5024	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 55 - STABILIZERS											
55-10-00-250-806-L00 ^S			SPECIAL DETAILED INSPECTION (EXTERNAL) OF HORIZONTAL STABILIZER COMPONENTS BY THE EDDY CURRENT INSPECTION METHOD:- SKIN, FROM RIB TO STA. YH=350 TO RIB YH=990 -UPPER SURFACE (SSI 55-10-02) (L600 ONLY)						Service	ATA:55	
	MOS	11-Aug-15	192 (+15d/-15d)					LOW UTILIZATION			
	HRS	7460.3	8000 (+20/-20)								
	AFL	3992	4000 (+20/-20)								
					PROC. REF: NDT 55-10-00					PKG:5032,6032	
55-10-00-250-807-L00 ^S			SPECIAL DETAILED INSPECTION (EXTERNAL) OF HORIZONTAL STABILIZER COMPONENTS BY THE EDDY CURRENT INSPECTION METHOD:- SKIN, FROM FIN TO STA. YH=350 - LOWER SURFACE (SSI 55-10-06) (L600 ONLY)						Service	ATA:55	
	MOS	06-Jul-19	144 (+15d/-15d)					LOW UTILIZATION			
	HRS	9057.4	6000 (+20/-20)								
	AFL	4853	3000 (+20/-20)								
					PROC. REF: NDT 55-10-00					PKG:5024	
55-10-00-250-808-L00 ^S			SPECIAL DETAILED INSPECTION (EXTERNAL) OF HORIZONTAL STABILIZER COMPONENTS BY USING EDDY CURRENT LOW FREQUENCY INSPECTION METHOD:- FRONT SPAR WEB AND CAP, FROM FIN TO RIB STA. YH=350,INCLUDING CENTER FITTING/SPAR ATTACHMENT (SSI 55-10-09). (L600 ONLY)						Service	ATA:55	
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	2000 (+20/-20)								
	AFL	5401	1000 (+20/-20)								
					PROC. REF: NDT 55-10-00					PKG:5010,6008	
55-10-00-250-809-L00 ^S			SPECIAL DETAILED INSPECTION (EXTERNAL) OF HORIZONTAL STABILIZER COMPONENTS BY USING EDDY CURRENT LOW FREQUENCY INSPECTION METHOD:- FRONT AND REAR AUXILIARY SPAR WEBS AND CAPS,INCLUDING CENTER FITTING/SPAR ATTACHMENT (SSI 55-10-11) (L600 ONLY)						Service	ATA:55	
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	2000 (+20/-20)								
	AFL	5401	1000 (+20/-20)								
					PROC. REF: NDT 55-10-00					PKG:5010,6008	
55-10-00-250-810-L00 ^S			SPECIAL DETAILED INSPECTION (EXTERNAL) OF HORIZONTAL STABILIZER COMPONENTS BY USING EDDY CURRENT LOW FREQUENCY INSPECTION METHOD:- REAR SPAR WEB AND CAP, FROM FIN TO RIB STA. YH=350,INCLUDING CENTER FITTING/SPAR ATTACHMENT (SSI 55-10-12) (L600 ONLY)						Service	ATA:55	
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	2000 (+20/-20)								
	AFL	5401	1000 (+20/-20)								
					PROC. REF: NDT 55-10-00					PKG:5010,6008	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 55 - STABILIZERS										
55-20-00-210-801-L00 ^S	GENERAL VISUAL INSPECTION (INTERNAL) OF ELEVATOR COMPONENTS:- ELEVATOR HORN MASS BALANCE WEIGHTS AND ATTACHMENTS (SSI 55-20-90)								Service	ATA:55
MOS	29-Jun-23		48 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		2000 (+20/-20)							
AFL	5401		1000 (+20/-20)							
PROC. REF: NDT 55-20-00										PKG:5008
55-20-00-210-C01-L00 ^S	GENERAL VISUAL INSPECTION (EXTERNAL) OF ELEVATOR COMPONENTS:- SKIN, BETWEEN ROOT AND STA. YH=160(SS I 55-20-26)- SKIN, BETWEEN STA. YH=160 AND STA. YH=3320 (SSI 55-20-28)								Service	ATA:55
MOS	29-Jun-23		48 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		2000 (+20/-20)							
AFL	5401		1000 (+20/-20)							
PROC. REF: CPM 55-20-00										PKG:5009
55-20-00-210-C02-L00 ^S	GENERAL VISUAL INSPECTION (INTERNAL) OF ELEVATOR COMPONENTS:- SPARS BETWEEN ROOT AND STA. YH=160(SS I 55-20-25)- SPARS, BETWEEN STA. YH=160 AND STA. YH=3320 (SSI 55-20-27)								Service	ATA:55
MOS	29-Jun-23		96 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		4000 (+20/-20)							
AFL	5401		2000 (+20/-20)							
PROC. REF: CPM 55-20-00										PKG:5016,6032
55-20-00-210-C03-L00 ^S	GENERAL VISUAL INSPECTION (EXTERNAL) OF ELEVATOR COMPONENTS:- TAB (SSI 55-20-37)								Service	ATA:55
MOS	29-Jun-23		48 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		2000 (+20/-20)							
AFL	5401		1000 (+20/-20)							
PROC. REF: CPM 55-20-00										PKG:5008,6016
55-20-00-220-801-L00 ^S	DETAILED INSPECTION (INTERNAL) OF ELEVATOR COMPONENTS:- TORQUE TUBE FITTINGS (SSI 55-20-34)- TAB WHEEL DRIVE SUPPORT FITTINGS (SSI 55-20-35)								Service	ATA:55
MOS	29-Jun-23		96 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		4000 (+20/-20)							
AFL	5401		2000 (+20/-20)							
PROC. REF: NDT 55-20-00										PKG:5016,6032
55-20-00-220-802-L00 ^S	DETAILED INSPECTION (EXTERNAL) OF ELEVATOR COMPONENTS:- TAB HINGE FITTINGS (SSI 55-20-36)								Service	ATA:55
MOS	29-Jun-23		96 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		4000 (+20/-20)							
AFL	5401		2000 (+20/-20)							
PROC. REF: NDT 55-20-00										PKG:5016,6032

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 55 - STABILIZERS											
55-20-00-220-C01-L00 ^S			DETAILED INSPECTION (INTERNAL) OF ELEVATOR COMPONENTS:- RIBS, BETWEEN ROOT AND STA. YH=160(SS1 55-20-29)- RIBS, BETWEEN STA. YH=160 AND STA. YH=983.4 (SSI 55-20-30)- RIBS, BETWEEN STA. YH=3001 AND STA. YH=3320 (SSI 55-20-33)						Service	ATA:55	
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	4000 (+20/-20)								
	AFL	5401	2000 (+20/-20)								
					PROC. REF: CPM 55-20-00					PKG:5016,6032	
55-20-00-290-C01-L00 ^S			DETAILED INSPECTION (INTERNAL) OF ELEVATOR COMPONENTS USING A BOROSCOPE:- RIBS, BETWEEN STA. YH=983,4 AND STA. YH=1898 (SSI 55-20-31)- RIBS, BETWEEN STA. YH=1898 AND STA. YH=3001 (SSI 55-20-32)						Service	ATA:55	
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	2000 (+20/-20)								
	AFL	5401	1000 (+20/-20)								
					PROC. REF: CPM 55-20-00					PKG:5008,6016	
55-30-00-210-802-L00 ^S			GENERAL VISUAL INSPECTION(INTERNAL) OF VERTICAL STABILIZER COMPONENTS:- SPAR 2 (WEB AND CAP),FROM FUSELAGE CONTOUR LINE TO TIP RIB STA. ZV=3015 (SSI 55-30-67)- SPAR 1 (WEB AND CAP),FROM FUSELAGE CONTOUR LINE TO TIP RIB (SSI 55-30-68) (L600 ONLY)						Service	ATA:55	
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	4000 (+20/-20)								
	AFL	5401	2000 (+20/-20)								
					PROC. REF: NDT 55-30-00					PKG:5016,6032	
55-30-00-210-C01-L00 ^S			GENERAL VISUAL INSPECTION (EXTERNAL) OF VERTICAL STABILIZER COMPONENTS:- SKIN AT WINDOWS FROM FUSELAGE TO STA. ZV=1169 (SSI 55-30-44)						Service	ATA:55	
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	2000 (+20/-20)								
	AFL	5401	1000 (+20/-20)								
					PROC. REF: CPM 55-30-00					PKG:5009	
55-30-00-210-C02-L00 ^S			GENERAL VISUAL INSPECTION (EXTERNAL) OF VERTICAL STABILIZER COMPONENTS:- SKIN AT SPAR 3, AUXILIARY SPAR 52%, AND STRINGERS46.5% & 57.65%, BETWEEN FUSELAGE & RIB STA. ZV=1169 (SSI 55-30-39)- SKIN AT SPAR 3, AUXILIARY SPAR 52%, AND STRINGERS46.5% & 57.65%, BETWEEN RIBS STA. ZV=1169 & STA. ZV=2799 (SSI 55-30-41)- SKIN AT SPAR 3, AUXILIARY SPAR 52%, AND STRINGERS 46.5% & 57.65%, BETWEEN RIB STA. ZV=2799 & HORIZONTAL STABILIZER (SSI 55-30-43)- SKIN AT WINDOWS BETWEEN STA. ZV=1169 & STA. ZV=2799 (SSI 55-30-45)- SKIN AT RIBS, BETWEEN STA.ZV=1169 AND STA. ZV=2799 (SSI 55-30-48)- SKIN AT RIBS, BETWEEN STA. ZV=2799 AND HORIZONTAL STABILIZER (SSI 55-30-49)						Service	ATA:55	
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	2000 (+20/-20)								
	AFL	5401	1000 (+20/-20)								
					PROC. REF: CPM 55-30-00					PKG:5008,6016	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 55 - STABILIZERS											
55-30-00-210-C03-L00 ^S			GENERAL VISUAL INSPECTION (EXTERNAL) OF VERTICAL STABILIZER COMPONENTS:- SKIN AT RIBS FROM FUSE- LAGE TO STA. ZV=1169 (SSI 55-30-47)						Service	ATA:55	
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	2000 (+20/-20)								
	AFL	5401	1000 (+20/-20)								
					PROC. REF: CPM 55-30-00					PKG:5009	
55-30-00-210-C04-L00 ^S			GENERAL VISUAL INSPECTION (INTERNAL) OF VERTICAL STABILIZER COMPONENTS:- RIBS (STA. ZV=3461, ZV=2538, ZV=1677,ZV=1550.5, ZV=1430.5, ZV=1423, ZV=1302, ZV=1169 AND ZV=915) (SSI 55-30-73)						Service	ATA:55	
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	2000 (+20/-20)								
	AFL	5401	1000 (+20/-20)								
					PROC. REF: CPM 55-30-00					PKG:5009	
55-30-00-210-C05-L00 ^S			GENERAL VISUAL INSPECTION (EXTERNAL) OF VERTICAL STABILIZER COMPONENTS:- SKIN AT SPARS 1, 2, AUXIL- IARY SPAR 41% AND STRINGERS 20% & 35.5% BETWEEN FUSELAGE & RIB STA. ZV=1169 (SSI 55-30-38)- SKIN AT SPARS 1, 2, AUXIL- IARY SPAR 41% AND STRING- ERS 20% & 35.5% BETWEEN RIBS STA. ZV=1169 & STA. ZV=2799 (SSI 55-30-40)- SKIN AT SPARS 1, 2, AUXILIARY SPAR 41% ANDSTRINGERS 20% & 35.5% BETWEEN RIB STA. ZV=2799 & HORIZONTAL STABILIZER (SSI 55-30-42)- SKIN AT WINDOWS BETWEEN STA. ZV=2799AND HORIZONTAL STABILIZER (SSI 55-30-46)						Service	ATA:55	
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	2000 (+20/-20)								
	AFL	5401	1000 (+20/-20)								
					PROC. REF: CPM 55-30-00					PKG:5009	
55-30-00-220-801-L00 ^S			DETAILED INSPECTION (INTERNAL) OF VERTICAL STABILIZER COMPONENTS:- TIP RIB (SSI 55-30-69)						Service	ATA:55	
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	4000 (+20/-20)								
	AFL	5401	2000 (+20/-20)								
					PROC. REF: NDT 55-30-00					PKG:5016,6032	
55-30-00-220-802-L00 ^S			DETAILED INSPECTION (INTERNAL) OF VERTICAL STABILIZER COMPONENTS:- FIN-TO-FUSELAGE ATTACHMENT FITTING TO SPAR 1 (SSI 55-30-58)- FIN-TO-FUSELAGE ATTACHMENT FITTING TO BULKHEAD 77 (SSI 55-30-59) (L600 ONLY)						Service	ATA:55	
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	4000 (+20/-20)								
	AFL	5401	2000 (+20/-20)								
					PROC. REF: NDT 55-30-00					PKG:5016,6032	
55-30-00-220-804-L00 ^S			DETAILED INSPECTION (INTERNAL) OF VERTICAL STABILIZER COMPONENTS:- FITTING HINGE SUPPORT (SSI 55-30-76) (L600 ONLY)						Service	ATA:55	
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	4000 (+20/-20)								
	AFL	5401	2000 (+20/-20)								
					PROC. REF: NDT 55-30-00					PKG:5016,6032	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 55 - STABILIZERS										
55-30-00-220-805-L00 ^S			DETAILED INSPECTION (INTERNAL) OF VERTICAL STABILIZER COMPONENTS:- FIN-TO-FUSELAGE ATTACH- MENT FITTING TO SPAR 3 (SSI 55-30-54)- FIN-TO-FUSELAGE ATTACH- MENT FITTING TO BULKHEAD 78 (SSI 55-30-60)- FIN-TO-FUSELAGE ATTACH- MENT FITTING TO BULKHEAD 79 (SSI 55-30-61)- FIN-TO-FUSELAGE ATTACH- MENT FITTING TO BULKHEAD 80 (SSI 55-30-62)- SPAR 41% (WEB AND CAP), FROM STA. ZV=1550.5, INCLUDING ATTACHMENT BOLTS (SSI 55-30-66) (L600 ONLY)						Service	ATA:55
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
					PROC. REF: NDT 55-30-00					PKG:5016,6032
55-30-00-220-806-L00 ^S			DETAILED INSPECTION (INTERNAL) OF VERTICAL STABILIZER COMPONENTS:- FIN-TO-FUSELAGE ATTACH- MENT FITTING TO AUXILIARY SPAR 52% (SSI 55-30-55)- FIN-TO-FUSELAGE ATTACH- MENT FITTING TO AUXILIARY SPAR 41% (SSI 55-30-56)- SPAR 3 (WEB AND CAP), FROM FUSELAGE CONTOUR LINE TO TIP RIB, INCLUDING ATTACHMENT BOLTS (SSI 55-30-63)- SPAR 52% (WEB AND CAP), FROM FUSELAGE CONTOUR LINE TO TIP RIB, INCLUDING ATTACHMENT BOLTS (SSI 55-30-64)- SPAR 41% (WEB AND CAP), FROM STA. ZV=2538 TO TIP RIB, INCLUDING ATTACHMENT BOLTS (SSI 55-30-65)- FIN-TO-HORIZONTAL STABILIZER SUPPORT ACTUATORS, INCLUDING BOLT (SSI 55-30-75)- ACTUATOR SUPPORT FITTINGS (RUDDER) (SSI 55-30-79)- PCU SUPPORT FITTINGS (SSI 55-30-80) (L600 ONLY)						Service	ATA:55
	MOS	27-Aug-07	288 (+15d/-15d)					LOW UTILIZATION		
	HRS	0	12000 (+20/-20)							
	AFL	0	6000 (+20/-20)							
					PROC. REF: NDT 55-30-00					PKG:5140
55-30-00-220-807-L00 ^S			DETAILED INSPECTION (INTERNAL) OF VERTICAL STABILIZER COMPONENTS:- FIN-TO-FUSELAGE ATTACH- MENT FITTING TO SPAR 2 (SSI 55-30-57) (L600 ONLY)						Service	ATA:55
	MOS	27-Aug-07	288 (+15d/-15d)					LOW UTILIZATION		
	HRS	0	12000 (+20/-20)							
	AFL	0	6000 (+20/-20)							
					PROC. REF: NDT 55-30-00					PKG:5140
55-30-00-220-808-L00			DETAILED INSPECTION (INTERNAL) OF VERTICAL STABILIZER COMPONENTS:- SPAR 2 (WEB AND CAP), FROM FUSELAGE CONTOUR LINE TO TIP RIB STA. ZV=3015 (SSI55-30-67)- SPAR 1 (WEB AND CAP), FROM FUSELAGE CONTOUR LINE TO TIP RIB (SSI 55-30-68) (L650 ONLY)						Service	ATA:55
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL		
	HRS	0								
	AFL	0								
					PROC. REF: NDT 55-30-00					PKG:6032
55-30-00-220-809-L00			DETAILED INSPECTION (INTERNAL) OF VERTICAL STABILIZER COMPONENTS:- FIN-TO-FUSELAGE ATTACHMENT FITTING TO SPAR 1 (SSI 55-30-58)- FIN-TO-FUSELAGE ATTACHMENT FITTING TO BULKHEAD 77 (SSI 55-30-59) (L650 ONLY)						Service	ATA:55
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL		
	HRS	0								
	AFL	0								
					PROC. REF: NDT 55-30-00					PKG:6016

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 55 - STABILIZERS										
55-30-00-220-810-L00	DETAILED INSPECTION (INTERNAL) OF VERTICAL STABILIZER COMPONENTS:- FITTING HINGE SUPPORT (SSI 55-30-76) (L650 ONLY)								Service	ATA:55
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL		
	HRS	0								
	AFL	0								
PROC. REF: NDT 55-30-00										PKG:6016
55-30-00-220-811-L00	DETAILED INSPECTION (INTERNAL) OF VERTICAL STABILIZER COMPONENTS:- FIN-TO-FUSELAGE ATTACHMENT FITTING TO SPAR 3 (SSI 55-30-54)- FIN-TO-FUSELAGE ATTACHMENT FITTING TO BULKHEAD 78 (SSI 55-30-60)- FIN-TO-FUSELAGE ATTACHMENT FITTING TO BULKHEAD 79 (SSI 55-30-61)- FIN-TO-FUSELAGE ATTACHMENT FITTING TO BULKHEAD 80 (SSI 55-30-62)- SPAR 41% (WEB AND CAP), FROM STA. ZV=1550.5,INCLUDING ATTACHMENT BOLTS (SSI 55-30-66) (L650 ONLY)								Service	ATA:55
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL		
	HRS	0								
	AFL	0								
PROC. REF: NDT 55-30-00										PKG:6016
55-30-00-220-812-L00	DETAILED INSPECTION (INTERNAL) OF VERTICAL STABILIZER COMPONENTS:- FIN-TO-FUSELAGE ATTACHMENT FITTING TO AUXILIARY SPAR 52% (SSI 55-30-55)- FIN-TO-FUSELAGE ATTACHMENT FITTING TO AUXILIARY SPAR 41% (SSI 55-30-56)- SPAR 3 (WEB AND CAP), FROM FUSELAGE CONTOUR LINE TO TIP RIB, INCLUDING ATTACHMENT BOLTS (SSI 55-30-63)- SPAR 52% (WEB AND CAP), FROM FUSELAGE CONTOUR LINE TO TIP RIB, INCLUDING ATTACHMENT BOLTS (SSI 55-30-64)- SPAR 41% (WEB AND CAP), FROM STA. ZV=2538 TO TIP RIB, INCLUDING ATTACHMENT BOLTS (SSI 55-30-65)- FIN-TO-HORIZONTAL STABILIZER SUPPORT ACTUATORS, INCLUDING BOLT (SSI 55-30-75)- ACTUATOR SUPPORT FITTINGS (RUDDER) (SSI 55-30-79)- PCU SUPPORT FITTINGS (SSI 55-30-80) (L650 ONLY)								Service	ATA:55
	MOS/MSC	27-Aug-07	N/A							
	HRS	0								
	AFL	0								
PROC. REF: NDT 55-30-00										PKG:6016
55-30-00-220-813-L00	DETAILED INSPECTION (INTERNAL) OF VERTICAL STABILIZER COMPONENTS:- FIN-TO-FUSELAGE ATTACHMENT FITTING TO SPAR 2 (SSI 55-30-57) (L650 ONLY)								Service	ATA:55
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL		
	HRS	0								
	AFL	0								
PROC. REF: NDT 55-30-00										PKG:6016
55-30-00-220-C01-L00 ^S	DETAILED INSPECTION (INTERNAL) OF VERTICAL STABILIZER COMPONENTS:- ROOT RIB, INCLUDING BOLTS (SSI 55-30-70)- RIBS OF ACTUATOR AREA (STA. ZV=1932 AND ZV=2277) (SSI 55-30-72)								Service	ATA:55
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
PROC. REF: CPM 55-30-00										PKG:5009

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 55 - STABILIZERS										
55-30-00-220-C02-L00 ^S	DETAILED INSPECTION (INTERNAL) OF VERTICAL STABILIZER COMPONENTS:- RIBS OF HORIZONTAL STABILIZER ACTUATORS (STA. ZV=3145, ZV=3015 AND ZV=2799) (SSI 55-30-71)- REAR SPAR ACTUATOR SUPPORT FITTING (ELEVATOR) (SSI 55-30-77)								Service	ATA:55
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
	PROC. REF: CPM 55-30-00									PKG:5016,6032
55-30-00-220-C03-L00 ^S	DETAILED INSPECTION (INTERNAL) OF VERTICAL STABILIZER COMPONENTS:- SPAR 1 - TIP RIB ATTACHMENT (SSI 55-30-53)								Service	ATA:55
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
	PROC. REF: CPM 55-30-00									PKG:5016,6032
55-30-00-220-C04-L00 ^S	DETAILED INSPECTION (EXTERNAL) OF VERTICAL STABILIZER COMPONENTS:- RUDDER HINGE FITTINGS (SSI 55-30-78)								Service	ATA:55
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
	PROC. REF: CPM 55-30-00									PKG:5008,6016
55-30-00-220-C05-L00 ^S	DETAILED INSPECTION (INTERNAL) OF VERTICAL STABILIZER COMPONENTS:- FIN-TO-HORIZONTAL STABILIZER ATTACHMENT FITTING TO SPAR 3 (SSI 55-30-50)- FIN-TO-HORIZONTAL STABILIZER ATTACHMENT FITTING TO AUXILIARY SPAR 52% (SSI 55-30-51) - FIN-TO-HORIZONTAL STABILIZER ATTACHMENT FITTING TO AUXILIARY SPAR 41% (SSI 55-30-52)								Service	ATA:55
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
	PROC. REF: CPM 55-30-00									PKG:5008,6016
55-30-00-250-801-L00 ^S	SPECIAL DETAILED INSPECTION (EXTERNAL) OF VERTICAL STABILIZER COMPONENTS BY THE EDDY CURRENT INSPECTION METHOD:- FITTING HINGE SUPPORT (SSI 55-30-76)								Service	ATA:55
	MOS	27-Aug-07	288 (+15d/-15d)					LOW UTILIZATION		
	HRS	0	12000 (+20/-20)							
	AFL	0	6000 (+20/-20)							
	PROC. REF: NDT 55-30-00									PKG:5140
55-30-00-290-801-L00 ^S	SPECIAL DETAILED INSPECTION(EXTERNAL) OF VERTICAL STABILIZERCOMPONENTS USING BOROSCOPE. TRAILING EDGE RIBS (SSI 55-30-74).								Service	ATA:55
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
	PROC. REF: NDT 55-30-00									PKG:5016,6032

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 55 - STABILIZERS										
55-40-00-210-C01-L00 ^S	GENERAL VISUAL INSPECTION (EXTERNAL) OF RUDDER COMPONENTS:- FRONT SPAR - SKIN ATTACHMENT (RUDDER I)(SSI 55-40-81)- REAR SPAR - SKIN ATTACHMENT (RUDDER I)(SSI 55-40-82)- LT & RT SKIN - SPAR CAP ATTACHMENT (RUDDER I)(SSI 55-40-83)- RIBS - SKIN ATTACHMENT (RUDDER I) (SSI 55-40-84)- HINGES - RUDDER I (SSI 55-40-85)								Service	ATA:55
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
PROC. REF: CPM 55-40-00										PKG:5008,6016
55-40-00-210-C02-L00 ^S	GENERAL VISUAL INSPECTION (EXTERNAL) OF RUDDER COMPONENTS:- SPAR - SKIN ATTACHMENT (RUDDER II) (SSI 55- 40- 86)- LT & RT SKIN - SPAR CAP ATTACHMENT (RUDDER II) (SSI 55-40-87)- RIBS - SKIN ATTACHMENT (RUDDER II) (SSI 55-40-88)- HINGES - RUDDER II (SSI 55-40-89)								Service	ATA:55
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
PROC. REF: CPM 55-40-00										PKG:5008,6016
55-40-00-220-C01-L00 ^S	DETAILED INSPECTION (INTERNAL) OF RUDDER COMPONENTS:- FRONT SPAR - SKIN ATTACH- MENT (RUDDER I)(SSI 55-40-81)- REAR SPAR - SKIN ATTACH- MENT (RUDDER I)(SSI 55-40-82)- LT & RT SKIN - SPAR CAP ATTACHMENT (RUDDER I)(SSI 55-40-83)- RIBS - SKIN ATTACHMENT (RUDDER I) (SSI 55-40-84)- HINGES - RUDDER I (SSI 55-40-85)								Service	ATA:55
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
PROC. REF: CPM 55-40-00										PKG:5008,6016
55-40-00-220-C02-L00 ^S	DETAILED INSPECTION (INTERNAL) OF RUDDER COMPONENTS:- SPAR - SKIN ATTACHMENT (RUDDER II) (SSI 55-40-86)- LT & RT SKIN - SPAR CAP ATTACHMENT (RUDDER II) (SSI 55-40-87)- RIBS - SKIN ATTACHMENT (RUDDER II) (SSI 55-40-88)- HINGES - RUDDER II (SSI 55-40-89)								Service	ATA:55
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
PROC. REF: CPM 55-40-00										PKG:5008,6016
55-Z321-213-001-A00 ^S	GENERAL VISUAL INSPECTION(EXTERNAL) (ZONES 321, 322, 323)								Service	ATA:55
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
PROC. REF: AMM 05-20-65										PKG:5008,6016

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 55 - STABILIZERS										
55-Z321-214-001-A00 ^S	GENERAL VISUAL INSPECTION	(INTERNAL)	(ZONES 321, 322, 323, 337)							Service ATA:55
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: AMM 05-20-65					PKG:5008,6016
55-Z324-213-001-A00 ^S	GENERAL VISUAL INSPECTION	(EXTERNAL)	(ZONES 324, 325)							Service ATA:55
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: AMM 05-20-58					PKG:5008,6016
55-Z324-214-001-A00 ^S	GENERAL VISUAL INSPECTION	(INTERNAL)	(ZONES 324, 325) (L600 ONLY)							Service ATA:55
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: AMM 05-20-58					PKG:5008,6016
55-Z324-214-001-A01	GENERAL VISUAL INSPECTION	(INTERNAL)	(ZONES 324, 325) NOTE:EWIS (L650 ONLY)							Service ATA:55
	MOS/MS	25-Sep-07	N/A					ZONAL		
	HRS	0								
	AFL	0								
					PROC. REF: AMM 05-20-58					PKG:6016
55-Z326-213-001-A00 ^S	GENERAL VISUAL INSPECTION	(EXTERNAL)	(ZONES 326, 327)							Service ATA:55
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: AMM 05-20-48					PKG:5008,6016
55-Z326-214-001-A00 ^S	GENERAL VISUAL INSPECTION	(INTERNAL)	(ZONES 326, 327)							Service ATA:55
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: AMM 05-20-48					PKG:5008,6016
55-Z333-213-001-A00 ^S	GENERAL VISUAL INSPECTION	(EXTERNAL)	(ZONES 331, 332, 333, 334)							Service ATA:55
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: AMM 05-20-52					PKG:5008,6016

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 55 - STABILIZERS										
55-Z333-214-001-A00 ^S GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 331, 332, 333, 334) Service ATA:55										
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
PROC. REF: AMM 05-20-52										PKG:5008,6016
55-Z335-213-001-A00 ^S GENERAL VISUAL INSPECTION(EXTERNAL) (ZONE 335, 336) Service ATA:55										
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
PROC. REF: AMM 05-20-62										PKG:5008,6016
55-Z335-214-001-A00 ^S GENERAL VISUAL INSPECTION(INTERNAL) (ZONE 335, 336) Service ATA:55										
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
PROC. REF: AMM 05-20-62										PKG:5008,6016
551500-0101 LEFT LEADING EDGE HORIZ STABILIZER ASSEMBLY Component ATA:55										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 55-15-00										
551500-0102 RIGHT LEADING EDGE HORIZ STABILIZER ASSEMBLY Component ATA:55										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 55-15-00										
551500-0103 LEADING EDGE ASSY ASSEMBLY Component ATA:55										
PN:145-03435-413	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:0000134776	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 55-15-00, AMM 55-35-00										
551500-0104 LEADING EDGE ASSY ASSEMBLY Component ATA:55										
PN:145-03435-414	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:0000160169	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 55-15-00, AMM 55-35-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 55 - STABILIZERS											
551500-0201		LH FAIRING ASSY								Component	ATA:55
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 55-13-01											
551500-0202		RH FAIRING ASSY								Component	ATA:55
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 55-13-01											
551500-0301		LH FAIRING ASSY								Component	ATA:55
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 55-14-00											
551500-0302		RH FAIRING ASSY								Component	ATA:55
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 55-14-00											
553400-0101		REAR FUS DORSAL FIN ASSY								Component	ATA:55
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 55-34-00											
553600-0101		FRONT FIXED FAIRING ASSY								Component	ATA:55
PN:145-21643-421	MOS/MSC	19-Aug-15	O/C	TSN 96, TSR 0							
SN:0000127727	HRS	7460.3		TSN 7460.3, TSR 0							
	AFL	3992		TSN 3992, TSR 0							
PROC. REF: AMM 55-36-02											
553600-0102		REAR FIXED FAIRING ASSY								Component	ATA:55
PN:145-21646-403	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:0000130993	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 55-36-02											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 55 - STABILIZERS											
553600-0103		FRONT MOVING FAIRING ASSY								Component	ATA:55
PN:145-21644-401	MOS/MSC	19-Aug-15	O/C	TSN 96, TSR 0							
SN:0000126684	HRS	7460.3	TSN 7460.3, TSR 0								
	AFL	3992	TSN 3992, TSR 0								
PROC. REF: AMM 55-36-00											
553600-0104		REAR MOVING FAIRING ASSY								Component	ATA:55
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	AFL	0	TSN 0								
PROC. REF: AMM 55-36-00											
ATA 56 - WINDOWS											
56-10-01-220-001-A00 ^S		INSPECT (DETAILED INSPECTION) THE WINDSHIELD HUMP SEAL								Service	ATA:56
	MOS	16-Aug-24	12 (+15d/-15d)	LOW UTILIZATION							
	HRS	10541.4	500 (+20/-20)								
	AFL	5613									
PROC. REF: AMM 56-10-01											
56-10-01-720-001-A00		FUNCTIONALLY CHECK TORQUE OF WINDSHIELD ATTACHING BOLTS NOTE: APPLICABLE TO AIRCRAFT PRE-MOD. SB145LEG-56-0001 (L600 ONLY)								Service	ATA:56
	MOS/MSC	15-Aug-13	N/A	Adj 12d	EMB-RECOMM						
	HRS	6643.4									
	AFL	3572									
PROC. REF: AMM 56-10-01											
56-10-01-720-001-A01		FUNCTIONALLY CHECK TORQUE OF WINDSHIELD ATTACHING BOLTS - FRONTAL WINDSHIELD ASSY, (LH)								Service	ATA:56
PN:NP-151311-19	MOS	25-Aug-22	EMB-RECOMM								
SN:20118H0238	HRS	9956.8	10000	19956.8	9361.2						
	AFL	5293									
PROC. REF: AMM 56-10-01											
56-10-01-720-001-A01		FUNCTIONALLY CHECK TORQUE OF WINDSHIELD ATTACHING BOLTS - FRONTAL WINDSHIELD ASSY, (RH)								Service	ATA:56
PN:NP-151311-20	MOS	25-Aug-22	EMB-RECOMM								
SN:20084H7588	HRS	9956.8	10000	19956.8	9361.2						
	AFL	5293									
PROC. REF: AMM 56-10-01											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 56 - WINDOWS										
56-10-01-CUS-0701^U PERFORM PERMANENT REPAIR OF RH WINDOW HUMPSEAL										
	MOS/MSC		01-Mar-19	-						Service ATA:56
	HRS		8966							
	AFL		4791							
56-10-01-CUS-0702^U GENERAL VISUAL INSPECTION OF RH WINDOW HUMPSEAL TEMPORARY REPAIR FOR TAPE INTEGRITY										
	DAYS/MSC		01-Mar-19	-						Service ATA:56
	HRS		8966							
	AFL		4791							
561000-0101 LEFT ELECTRICALLY HEATED, WITH RRC - FRONTAL WINDSHIELD ASSY, (LH)										
PN:NP-151311-19	MOS/MSC		25-Aug-22	O/C	TSN 0					Component ATA:56
SN:20118H0238	HRS		9956.8		TSN 0					
	AFL		5293		TSN 0					
PROC. REF: AMM 56-10-01										
561000-0102 RIGHT ELECTRICALLY HEATED, WITH RRC - FRONTAL WINDSHIELD ASSY, (RH)										
PN:NP-151311-20	MOS/MSC		25-Aug-22	O/C	TSN 0					Component ATA:56
SN:20084H7588	HRS		9956.8		TSN 0					
	AFL		5293		TSN 0					
PROC. REF: AMM 56-10-01										
561100-0101 PILOT FITTING -MECHANISM,STORM WINDOW ASSEMBLY										
PN:PN	MOS/MSC		27-Aug-07	O/C	TSN 0					Component ATA:56
SN:UNKNOWN	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: NDT GENERIC										
561100-0102 COPILOT FITTING -MECHANISM,STORM WINDOW ASSEMBLY										
PN:PN	MOS/MSC		27-Aug-07	O/C	TSN 0					Component ATA:56
SN:UNKNOWN	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: NDT GENERIC										
ATA 57 - WINGS										
57-01-00-220-C01-L00^S DETAILED INSPECTION (INTERNAL) OF WING STUB COMPONENTS:- WING STUB - LOWER SKIN - RIB 2A ATTACHMENT(SS1 57-01-15)- WING STUB - SPAR 2 - BRACKETS RIBS 2A ATTACHMENTS (SSI 57-01-17)- WING STUB - SPAR 1 - BRACKETS RIBS 2A ATTACHMENTS (SSI 57-01-16)										
	MOS		29-Jun-23	96 (+15d/-15d)				LOW UTILIZATION		Service ATA:57
	HRS		10161.5	4000 (+20/-20)						
	AFL		5401	2000 (+20/-20)						
PROC. REF: CPM 57-01-00										PKG:5016,6032

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 57 - WINGS											
57-01-00-220-C02-L00 ^S			DETAILED INSPECTION (INTERNAL) OF WING STUB COMPONENTS:- WING STUB - RIB 2A SKIN SUPPORTS AND THEIR ATTACHMENTS TO WEB, LOWER FLANGE, AND FWD & AFT WEB SUPPORTS (SSI 57-01-18)- WING STUB - UPPER SKIN - RIB 2A ATTACHMENTS (SSI 57-01-19)							Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	2000 (+20/-20)								
	AFL	5401	1000 (+20/-20)								
					PROC. REF: CPM 57-01-00					PKG:5008,6016	
57-01-00-220-C03-L00 ^S			DETAILED INSPECTION (EXTERNAL) OF WING STUB COMPONENTS:- WING STUB - LOWER SKIN - RIB 2A ATTACHMENT (SSI 57-01-15)							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	4000 (+20/-20)								
	AFL	5401	2000 (+20/-20)								
					PROC. REF: CPM 57-01-00					PKG:5016,6032	
57-01-00-220-C04-L00 ^S			DETAILED INSPECTION (EXTERNAL) OF WING STUB COMPONENTS:- WING STUB - UPPER SKIN - RIB 2A ATTACHMENTS (SSI 57-01-19)							Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	2000 (+20/-20)								
	AFL	5401	1000 (+20/-20)								
					PROC. REF: CPM 57-01-00					PKG:5008,6016	
57-10-00-210-801-L00 ^S			GENERAL VISUAL INSPECTION (EXTERNAL) OF WING STUB COMPONENTS:- SPAR 2 - BRACKETS AND RIB 2A WEB ATTACHMENTS (SSI 57-10-27)							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	4000 (+20/-20)								
	AFL	5401	2000 (+20/-20)								
					PROC. REF: NDT 57-10-00					PKG:5016,6032	
57-10-00-210-C01-L00 ^S			GENERAL VISUAL INSPECTION (EXTERNAL) OF WING STUB COMPONENTS:- UPPER SKIN - TIRE COMPARTMENT COMPOSITE PANEL (SSI 57-10-14)							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	4000 (+20/-20)								
	AFL	5401	2000 (+20/-20)								
					PROC. REF: CPM 57-10-00					PKG:5016,6032	
57-10-00-220-801-L00 ^S			DETAILED INSPECTION (EXTERNAL) OF WING STUB COMPONENTS:- SPAR 1 - AUXILIARY CAP ATTACHMENTS & AUXILIARY CAP SPLICE AT WING ATTACHMENTS (SSI 57-10-05)- LOWER SKIN - RIBS 1, 2 & 3 ATTACHMENTS AND TIRE COMPARTMENT WALL ATTACHMENTS (SSI 57-10-02)- SPAR 1 - LOWER SKIN ATTACHMENTS (SSI 57-10-03) NOTE: DURING THIS INSPECTION, THE C/PC BASIC TASK SHALL ALSO BE PERFORMED FOR THESE SSIS							Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	2000 (+20/-20)								
	AFL	5401	1000 (+20/-20)								
					PROC. REF: NDT 57-10-00					PKG:5008,6016	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 57 - WINGS											
57-10-00-220-802-L00 ^S			DETAILED INSPECTION (INTERNAL) OF WING STUB COMPONENTS:- SPAR 2 - BRACKETS AND RIB 2A WEB ATTACHMENTS (SSI 57-10-27)- SPAR 1 - LOWER SKIN ATTACHMENTS (SSI 57-10-03)- SPAR 1 - AUXILIARY CAP ATTACHMENTS & AUXILIARY CAP SPLICE AT WING ATTACHMENTS (SSI 57-10-05) (L600 ONLY)						Service	ATA:57	
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	2000 (+20/-20)								
	AFL	5401	1000 (+20/-20)								
					PROC. REF: NDT 57-10-00					PKG:5008,6016	
57-10-00-220-803-L00 ^S			DETAILED INSPECTION (INTERNAL) OF WING STUB COMPONENTS:- LOWER SKIN - RIBS 1, 2 & 3 ATTACHMENTS AND TIRE COMPARTMENT WALL ATTACHMENTS(SS I 57-10-02)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI						Service	ATA:57	
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	2000 (+20/-20)								
	AFL	5401	1000 (+20/-20)								
					PROC. REF: NDT 57-10-00					PKG:5008,6016	
57-10-00-220-804-L00 ^S			DETAILED INSPECTION (EXTERNAL) OF WING STUB COMPONENTS:- LOWER SKIN - SPANWISE SPLICE AT SPAR 2, ACCESS HOLES, STRINGERS, INTEGRAL MILLED PANELS & SPANWISE SPLICE OF INTEGRAL PANEL (SSI 57-10-01)- SPAR 2 - LOWER SKIN ATTACHMENTS (SSI 57-10-06)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI'S (L600 ONLY)						Service	ATA:57	
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	4000 (+20/-20)								
	AFL	5401	2000 (+20/-20)								
					PROC. REF: NDT 57-10-00					PKG:5016	
57-10-00-220-805-L00 ^S			DETAILED INSPECTION (INTERNAL) OF WING STUB COMPONENTS:- LOWER SKIN - SPANWISE SPLICE AT SPAR 2, ACCESS HOLES, STRINGERS, INTEGRAL MILLED PANELS & SPANWISE SPLICE OF INTEGRAL PANEL (SSI 57-10-01)- SPAR 2 - LOWER SKIN ATTACHMENTS (SSI 57-10-06)- SPAR 2 - AUXILIARY CAP ATTACHMENTS AND AUXILIARYCAP SPLICE AT WING ATTACHMENTS (SSI 57-10-08) NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI'S 57-10-06 AND 57-10-08 (L600 ONLY)						Service	ATA:57	
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	4000 (+20/-20)								
	AFL	5401	2000 (+20/-20)								
					PROC. REF: NDT 57-10-00					PKG:5016	
57-10-00-220-806-L00			DETAILED INSPECTION (INTERNAL) OF WING STUB COMPONENTS:- SPAR 2 - BRACKETS AND RIB 2A WEB ATTACHMENTS (SSI 57-10-27)- SPAR 1 - LOWER SKIN ATTACHMENTS (SSI 57-10-03)- SPAR 1 - AUXILIARY CAP ATTACHMENTS & AUXILIARYCAP SPLICE AT WING ATTACHMENTS (SSI 57-10-05) (L650 ONLY)						Service	ATA:57	
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL			
	HRS	0									
	AFL	0									
					PROC. REF: NDT 57-10-00					PKG:6016	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
57-10-00-220-807-L00								DETAILED INSPECTION (EXTERNAL) OF WING STUB COMPONENTS:- LOWER SKIN - SPANWISE SPLICE AT SPAR 2, ACCESS HOLES, STRINGERS, INTEGRAL MILLED PANELS & SPANWISE SPLICE OF INTEGRAL PANEL (SSI 57-10-01)- SPAR 2 - LOWER SKIN ATTACHMENTS (SSI 57-10- 06)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI ₂ S (L650 ONLY)	Service	ATA:57
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL		
	HRS	0								
	AFL	0								
PROC. REF: NDT 57-10-00										PKG:6016
57-10-00-220-808-L00								DETAILED INSPECTION (INTERNAL) OF WING STUB COMPONENTS:- LOWER SKIN - SPANWISE SPLICE AT SPAR 2, ACCESS HOLES, STRINGERS, INTEGRAL MILLED PANELS & SPANWISE SPLICE OF INTEGRAL PANEL (SSI 57-10-01)- SPAR 2 - LOWER SKIN ATTACHMENTS (SSI 57-10-06)- SPAR 2 - AUXILIARY CAP ATTACHMENTS AND AUXILIARY CAP SPLICE AT WING ATTACHMENTS (SSI 57-10-08) NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI ₂ S 57-10-06 AND 57-10-08 (L650 ONLY)	Service	ATA:57
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL		
	HRS	0								
	AFL	0								
PROC. REF: NDT 57-10-00										PKG:6016
57-10-00-220-C01-L00 ^S								DETAILED INSPECTION (INTERNAL) OF WING STUB COMPONENTS:- SPAR 1 - BRACKETS, RIBS 1 AND 3 ATTACHMENTS(SS I 57-10-04)- SPAR 2 - CENTER BRACKETS & RIB 2 ATTACHMENTS AND RIBS 1 & 3 WEB ATTACHMENTS (SSI 57-10-07)	Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
PROC. REF: CPM 57-10-00										PKG:5008,6016
57-10-00-220-C02-L00 ^S								DETAILED INSPECTION (EXTERNAL) OF WING STUB COMPONENTS:- UPPER SKIN - RIB 1 ATTACHMENTS AND SPANWISE SPLICE OF INTEGRAL PANEL (SSI 57-10-13)	Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
PROC. REF: CPM 57-10-00										PKG:5008,6016
57-10-00-220-C03-L00 ^S								DETAILED INSPECTION (EXTERNAL) OF WING STUB COMPONENTS:- RIB 4 - LOWER FLANGE AND WEB (SSI 57-10-11)	Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
PROC. REF: CPM 57-10-00										PKG:5008,6016

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
57-10-00-220-C04-L00 ^S	DETAILED INSPECTION (EXTERNAL) OF WING STUB COMPONENTS:- SPAR 3 - LOWER SKIN ATTACHMENTS (SSI 57-10-09)								Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
	PROC. REF: CPM 57-10-00									PKG:5008,6016
57-10-00-220-C05-L00 ^S	DETAILED INSPECTION (INTERNAL) OF WING STUB COMPONENTS:- SPAR 3 - LOWER SKIN ATTACHMENTS (SSI 57-10-09)- UPPER SKIN - TIRE COMPARTMENT COMPOSITE PANEL (SSI 57-10-14)								Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
	PROC. REF: CPM 57-10-00									PKG:5008,6016
57-10-00-220-C06-L00 ^S	DETAILED INSPECTION (INTERNAL) OF WING STUB COMPONENTS:- UPPER SKIN - RIB 1 ATTACHMENTS AND SPANWISE SPLICE OF INTEGRAL PANEL (SSI 57-10-13)								Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
	PROC. REF: CPM 57-10-00									PKG:5008,6016
57-10-00-220-C07-L00 ^S	DETAILED INSPECTION (INTERNAL) OF WING STUB COMPONENTS:- RIB 4 - LOWER FLANGE AND WEB (SSI 57-10-11)- RIB 2 - LONGITUDINAL STRINGER- TO- WEB ATTACHMENTS (SSI 57-10-12)								Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
	PROC. REF: CPM 57-10-00									PKG:5008,6016
57-10-00-220-C08-L00 ^S	DETAILED INSPECTION (INTERNAL) OF WING STUB COMPONENTS:- SPAR 3 - CENTER BRACKET AND RIB 2 ATTACHMENTS (SSI 57-10-10)								Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
	PROC. REF: CPM 57-10-00									PKG:5016,6032
57-10-00-250-803-L00 ^S	SPECIAL DETAILED INSPECTION (INTERNAL) OF WING STUB COMPONENTS BY THE ULTRA- SONIC INSPECTION METHOD:- LOWER SKIN - SPANWISE SPLICE AT SPAR 2, ACCESS HOLES, STRINGERS, INTEGRAL MILLED PANELS & SPANWISE SPLICE OF INTEGRAL PANEL (SSI 57-10-01) (L600 ONLY)								Service	ATA:57
	MOS	27-Aug-07	T:288 (+15d/-15d)					LOW UTILIZATION		
	HRS	0	T:12000 (+20/-20)							
	AFL	0	T:6000 (+20/-20)							
	PROC. REF: NDT 57-10-00									PKG:5025

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 57 - WINGS											
57-11-00-220-801-L00 ^S			DETAILED INSPECTION (EXTERNAL) OF WING STUB COMPONENTS:- LOWER SKIN - REAR FITTING-TO- SKIN ATTACHMENTS AND SPARS 1 & 2 - STUB- TO- WING ATTACHMENTS (SSI 57-11-17)- FUSELAGE BULKHEAD AT FRAME 50 AND ITS ATTACH- MENTS TO FRAME 50 (SSI 57-11-25)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THESE SSIS						Service	ATA:57	
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	4000 (+20/-20)								
	AFL	5401	2000 (+20/-20)								
					PROC. REF: NDT 57-11-00					PKG:5016,6032	
57-11-00-220-802-L00 ^S			DETAILED INSPECTION (INTERNAL) OF WING STUB COMPONENTS:- LOWER SKIN - REAR FITTING-TO- SKIN ATTACHMENTS AND SPARS 1 & 2 - STUB-TO-WING ATTACHMENTS (SSI 57-11-17)- FUSELAGE BULKHEAD AT FRAME 50 AND ITS ATTACHMENTS TO FRAME 50 (SSI 57-11-25)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR SSI 57-11-25						Service	ATA:57	
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	4000 (+20/-20)								
	AFL	5401	2000 (+20/-20)								
					PROC. REF: NDT 57-11-00					PKG:5016,6032	
57-11-00-220-803-L00 ^S			DETAILED INSPECTION (EXTERNAL) OF WING STUB COMPONENTS:- SPAR 1 - LOWER FRONT FITTINGATTACHMENTS AND SPAR 2 - LOWER REAR FITTING ATTACH- MENTS (SSI 57-11-18)- SPAR 2 - TITANIUM FITTING ATTACHMENTS AND FUSELAGE BULKHEAD AT FRAME 46 (SSI 57-11-20)- SPAR 3 - FUSELAGE BULKHEAD ATTACHMENTS AT FRAME 50, L- SHAPE FUSELAGE FRAME 50 ATTACHMENTS & FUSELAGE STRINGERS ATTACH- MENTS (SSI 57-11-21)- SPAR 1 - TITANIUM FITTING ATTACHMENTS, FUSELAGE BULKHEAD ATTACHMENTS AT FRAME 40, L SHAPE FUSE- LAGE FRAME 40 ATTACHMENTS& FUSELAGE STRINGERS (SSI 57-11-19)NOTE: DURING THIS INSPECTION, THE CPCPBASIC TASK SHALL ALSO BE PERFORMED FOR SSIS 57-11-18 AND 57-11-20 (L600 ONLY)						Service	ATA:57	
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	4000 (+20/-20)								
	AFL	5401	2000 (+20/-20)								
					PROC. REF: NDT 57-11-00					PKG:5016,6032	
57-11-00-220-805-L00 ^S			DETAILED INSPECTION (INTERNAL) OF WING STUB COMPONENTS:- SPAR 1 - TITANIUM FITTING ATTACHMENTS, FUSELAGE BULKHEAD ATTACHMENTS AT FRAME 40, L SHAPE FUSELAGE FRAME 40 ATTACHMENTS & FUSELAGE STRINGERS ATTACHMENTS (SSI 57-11-19)- SPAR 3 - FUSELAGE BULKHEAD ATTACHMENTS AT FRAME 50, SHALL L- SHAPE FUSELAGE FRAME 50 ATTACHMENTS & FUSELAGE STRINGERS ATTACHMENTS (SSI 57-11-21)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR SSI 57-11-21						Service	ATA:57	
	MOS	07-Jul-15	192 (+15d/-15d)					LOW UTILIZATION			
	HRS	7460.3	8000 (+20/-20)								
	AFL	3992	4000 (+20/-20)								
					PROC. REF: NDT 57-11-00					PKG:5032,6032	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 57 - WINGS											
57-11-00-220-806-L00 ^S			DETAILED INSPECTION (INTERNAL) OF WING STUB COMPONENTS:- SPAR 1 - LOWER FRONT FITTING ATTACHMENTS AND SPAR 2 - LOWER REAR FITTING ATTACHMENTS (SSI 57-11-18)- SPAR 2 - TITANIUM FITTING ATTACHMENTS AND FUSELAGE BULKHEAD AT FRAME 46 (SSI 57-11-20) (L600 ONLY)							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	4000 (+20/-20)								
	AFL	5401	2000 (+20/-20)								
					PROC. REF: NDT 57-11-00					PKG:5016,6032	
57-11-00-220-807-L00 ^S			DETAILED INSPECTION (EXTERNAL) OF WING STUB COMPONENTS:- SPAR 3 AND RIB 4 - ROD-END LINK (SSI 57-11-22)- FUSELAGE BULKHEAD AT FRAME 40 AND ITS ATTACHMENTS TO FRAME (SSI 57-11-23)- FUSELAGE BULKHEAD ATTACHMENT TO FRAME 46 (SSI 57-11-24)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THESE SSIS (L600 ONLY)							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	4000 (+20/-20)								
	AFL	5401	2000 (+20/-20)								
					PROC. REF: NDT 57-11-00					PKG:5016,6032	
57-11-00-220-808-L00 ^S			DETAILED INSPECTION (INTERNAL) OF WING STUB COMPONENTS:- FUSELAGE BULKHEAD AT FRAME 40 AND ITS ATTACHMENTS TO FRAME 40 (SSI 57-11-23)- FUSELAGE BULKHEAD ATTACHMENT TO FRAME 46 (SSI 57-11-24)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR SSI 57-11-24 (L600 ONLY)							Service	ATA:57
	MOS	27-Aug-07	192 (+15d/-15d)					LOW UTILIZATION			
	HRS	0	8000 (+20/-20)								
	AFL	0	4000 (+20/-20)								
					PROC. REF: NDT 57-11-00					PKG:5032	
57-11-00-220-809-L00			DETAILED INSPECTION (EXTERNAL)OF WING STUB COMPONENTS:- SPAR 1 - LOWER FRONT FITTING ATTACHMENTS AND SPAR 2 - LOWER REAR FITTING ATTACHMENTS (SSI 57-11-18)- SPAR 2 - TITANIUM FITTING ATTACHMENTS AND FUSELAGE BULKHEAD AT FRAME 46 (SSI 57-11-20)- SPAR 3 - FUSELAGE BULKHEAD ATTACHMENTS AT FRAME 50, L- SHAPE FUSELAGE FRAME 50 ATTACHMENTS & FUSELAGE STRINGERS ATTACHMENTS (SSI 57-11-21)- SPAR 1 - TITANIUM FITTING ATTACHMENTS, FUSELAGE BULKHEAD ATTACHMENTS AT FRAME 40, L SHAPE FUSELAGE FRAME 40 ATTACHMENTS & FUSELAGE STRINGERS (SSI 57-11-19)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR SSIS 57-11-18 AND 57-11-20 (L650 ONLY)							Service	ATA:57
	MOS/MSC	27-Aug-07	N/A								
	HRS	0									
	AFL	0									
					PROC. REF: NDT 57-11-00					PKG:6016	
57-11-00-220-810-L00			DETAILED INSPECTION (INTERNAL) OF WING STUB COMPONENTS:- SPAR 1 - LOWER FRONT FITTING ATTACHMENTS AND SPAR 2 - LOWER REAR FITTING ATTACHMENTS (SSI 57-11-18)- SPAR 2 - TITANIUM FITTING ATTACHMENTS AND FUSELAGE BULKHEAD AT FRAME 46 (SSI 57-11-20) (L650 ONLY)							Service	ATA:57
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL			
	HRS	0									
	AFL	0									
					PROC. REF: NDT 57-11-00					PKG:6016	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 57 - WINGS											
57-11-00-220-811-L00			DETAILED INSPECTION (EXTERNAL) OF WING STUB COMPONENTS:- SPAR 3 AND RIB 4 - ROD-END LINK (SSI 57-11-22)- FUSELAGE BULKHEAD AT FRAME 40 AND ITS ATTACHMENTS TO FRAME (SSI 57-11-23)- FUSELAGE BULKHEAD ATTACHMENT TO FRAME 46 (SSI 57-11-24)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THESE SSIS (L650 ONLY)						Service	ATA:57	
	MOS/MS	25-Sep-07	N/A					STRUCTURAL			
	HRS	0									
	AFL	0									
					PROC. REF: NDT 57-11-00					PKG:6016	
57-11-00-220-812-L00			DETAILED INSPECTION (INTERNAL) OF WING STUB COMPONENTS:- FUSELAGE BULKHEAD AT FRAME 40 AND ITS ATTACHMENTS TO FRAME 40 (SSI 57-11-23)- FUSELAGE BULKHEAD ATTACHMENT TO FRAME 46 (SSI 57-11-24)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR SSI 57-11-24 (L650 ONLY)						Service	ATA:57	
	MOS/MS	25-Sep-07	N/A					STRUCTURAL			
	HRS	0									
	AFL	0									
					PROC. REF: NDT 57-11-00					PKG:6016	
57-11-00-250-801-L00 ^S			SPECIAL DETAILED INSPECTION (INTERNAL) OF WING STUB COMPONENTS BY THE EDDY CURRENT INSPECTION METHOD:- LOWER SKIN - REAR FITTING-TO- SKIN ATTACHMENTS AND SPARS 1 & 2 - STUB-TO-WING ATTACHMENTS (SSI 57-11-17)						Service	ATA:57	
	MOS	27-Aug-07	288 (+15d/-15d)					LOW UTILIZATION			
	HRS	0	12000 (+20/-20)								
	AFL	0	6000 (+20/-20)								
					PROC. REF: NDT 57-11-00					PKG:5140	
57-21-00-210-801-L00 ^S			GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS:- LOWER SKIN/SPAR ATTACH- MENTS (SSI 57-21-36)						Service	ATA:57	
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	2000 (+20/-20)								
	AFL	5401	1000 (+20/-20)								
					PROC. REF: NDT 57-21-00					PKG:5008	
57-21-00-210-806-L00 ^S			GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS:- UPPER SKIN/SPAR ATTACH- MENT (SSI 57-21-37) (L600 ONLY)						Service	ATA:57	
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	2000 (+20/-20)								
	AFL	5401	1000 (+20/-20)								
					PROC. REF: NDT 57-21-00					PKG:5008	
57-21-00-210-809-L00 ^S			GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS:- LOWER SKIN ACCESS HOLES (SSI 57-21-32)						Service	ATA:57	
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	4000 (+20/-20)								
	AFL	5401	2000 (+20/-20)								
					PROC. REF: NDT 57-21-00					PKG:5016,6032	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
57-21-00-210-812-L00 ^S	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS:- LOWER SKIN PANEL SPANWISE JOINT (SSI 57-21-30)- UPPER SKIN PANEL SPANWISE JOINT (SSI 57-21-31)- UPPER SKIN/SPAR ATTACHMENT (SSI 57-21-37)								Service	ATA:57
MOS	29-Jun-23		48 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		2000 (+20/-20)							
AFL	5401		1000 (+20/-20)							
PROC. REF: NDT 57-21-00										PKG:5008
57-21-00-210-813-L00 ^S	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS:- LOWER SKIN PANEL CHORD- WISE JOINT (SSI 57-21-29)- LOWER SKIN PANEL SPANWISE JOINT (SSI 57-21-30)								Service	ATA:57
MOS	29-Jun-23		96 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		4000 (+20/-20)							
AFL	5401		2000 (+20/-20)							
PROC. REF: NDT 57-21-00										PKG:5016,6032
57-21-00-210-814-L00 ^S	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS:- LOWER SKIN ACCESS HOLES (SSI 57-21-32)								Service	ATA:57
MOS	29-Jun-23		96 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		4000 (+20/-20)							
AFL	5401		2000 (+20/-20)							
PROC. REF: NDT 57-21-00										PKG:5016,6032
57-21-00-210-815-L00 ^S	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS:- LOWER SKIN PANEL SPANWISE JOINT (SSI 57-21-30)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI								Service	ATA:57
MOS	29-Jun-23		96 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		4000 (+20/-20)							
AFL	5401		2000 (+20/-20)							
PROC. REF: NDT 57-21-00										PKG:5016,6032
57-21-00-210-816-L00 ^S	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS:- LOWER SKIN PANEL CHORD- WISE JOINT (SSI 57-21-29)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI								Service	ATA:57
MOS	29-Jun-23		96 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		4000 (+20/-20)							
AFL	5401		2000 (+20/-20)							
PROC. REF: NDT 57-21-00										PKG:5016,6032
57-21-00-210-821-L00 ^S	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS:- LOWER SKIN/ SPAR ATTACH- MENTS (SSI 57-21-36)								Service	ATA:57
MOS	29-Jun-23		96 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		4000 (+20/-20)							
AFL	5401		2000 (+20/-20)							
PROC. REF: NDT 57-21-00										PKG:5016,6016

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
57-21-00-210-822-L00 ^S	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS:- LOWER SKIN PANEL SPANWISE JOINT (SSI 57-21-30)									Service ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
	PROC. REF: NDT 57-21-00									PKG:5016,6032
57-21-00-210-823-L00 ^S	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS:- SKIN PANELS (SSI 57-21-26)									Service ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
	PROC. REF: NDT 57-21-00									PKG:5016,6032
57-21-00-210-824-L00 ^S	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS:- UPPER SKIN PANEL AT SPANWISE JOINT (SSI 57-21-31)									Service ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
	PROC. REF: NDT 57-21-00									PKG:5016,6032
57-21-00-210-825-L00	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS:- UPPER SKIN/SPAR ATTACHMENT (SSI 57-21-37) (L650 ONLY)									Service ATA:57
	MOS/MS	25-Sep-07	N/A					STRUCTURAL		
	HRS	0								
	AFL	0								
	PROC. REF: NDT 57-21-00									PKG:6016
57-21-00-210-826-L00 ^S	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS:- LOWER SKIN ACCESS HOLES (SSI 57-21-32)									Service ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
	PROC. REF: NDT 57-21-00									PKG:5016,6016
57-21-00-210-C01-L00 ^S	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS: - LOWER VENT HOLE (SSI 57-21-33) - GRAVITY FUEL HOLE (SSI 57-21-35)									Service ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
	PROC. REF: CPM 57-21-00									PKG:5009
57-21-00-210-C02-L00 ^S	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS:- UPPER SKIN/ SPAR ATTACHMENT (SSI 57-21-37)									Service ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
	PROC. REF: CPM 57-21-00									PKG:5009

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
57-21-00-210-C04-L00 ^S	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS:- UPPER SKIN PANEL SPAN- WISE JOINT (SSI 57-21-31)								Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: CPM 57-21-00					PKG:5008,6016
57-21-00-210-C06-L00 ^S	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS:- UPPER SKIN/ SPAR STUB ATTACHMENT (SSI 57-21-39)								Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: CPM 57-21-00					PKG:5008,6016
57-21-00-210-C08-L00 ^S	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS:- SKIN PANELS (SSI 57-21-26)- UPPER SKIN PANEL SPAN- WISE JOINT (SSI 57-21-31)- UPPER SKIN/ SPAR ATTACH- MENT (SSI 57-21-37)								Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
					PROC. REF: CPM 57-21-00					PKG:5016,6032
57-21-00-210-C09-L00 ^S	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS:- LOWER SKIN ACCESS HOLES (SSI 57-21-32)								Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: CPM 57-21-00					PKG:5009
57-21-00-210-C10-L00 ^S	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS:- LOWER SKIN/ WING STUB ATTACHMENT (SSI 57-21-38)								Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: CPM 57-21-00					PKG:5008,6016
57-21-00-210-C11-L00 ^S	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS:- GRAVITY FUEL HOLE (SSI 57-21-35)								Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
					PROC. REF: CPM 57-21-00					PKG:5016,6032
57-21-00-210-C13-L00 ^S	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS:- UPPER SKIN/ WING STUB ATTACHMENT (SSI 57-21-39)								Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: CPM 57-21-00					PKG:5008,6016

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
57-21-00-210-C14-L00 ^S	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS:- SKIN PANELS (SSI 57-21-26)- UPPER SKIN PANEL SPAN- WISE JOINT (SSI 57-21-31) (L600 ONLY)								Service	ATA:57
MOS	29-Jun-23		48 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		2000 (+20/-20)							
AFL	5401		1000 (+20/-20)							
PROC. REF: CPM 57-21-00										PKG:5008,6016
57-21-00-210-C15-L00 ^S	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS:- UPPER SKIN/ SPAR ATTACHMENT (SSI 57-21-37)								Service	ATA:57
MOS	29-Jun-23		48 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		2000 (+20/-20)							
AFL	5401		1000 (+20/-20)							
PROC. REF: CPM 57-21-00										PKG:5008,6016
57-21-00-210-C16-L00 ^S	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS:- LOWER SKIN PANEL SPAN- WISE JOINT (SSI 57-21-30)								Service	ATA:57
MOS	29-Jun-23		96 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		4000 (+20/-20)							
AFL	5401		2000 (+20/-20)							
PROC. REF: CPM 57-21-00										PKG:5016,6032
57-21-00-210-C17-L00 ^S	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS:- LOWER SKIN/WING STUB ATTACHMENT (SSI 57-21-38)								Service	ATA:57
MOS	29-Jun-23		96 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		4000 (+20/-20)							
AFL	5401		2000 (+20/-20)							
PROC. REF: CPM 57-21-00										PKG:5016,6032
57-21-00-210-C18-L00 ^S	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS:- LOWER SKIN PANEL SPAN- WISE JOINT (SSI 57-21-30) (L600 ONLY)								Service	ATA:57
MOS	29-Jun-23		48 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		2000 (+20/-20)							
AFL	5401		1000 (+20/-20)							
PROC. REF: CPM 57-21-00										PKG:5008,6016
57-21-00-220-801-L00 ^S	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS:- SKIN PANELS (SSI 57-21-26)								Service	ATA:57
MOS	29-Jun-23		96 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		4000 (+20/-20)							
AFL	5401		2000 (+20/-20)							
PROC. REF: NDT 57-21-00										PKG:5016,6016

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
57-21-00-220-802-L00 ^S	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS:- LOWER SKIN ACCESS HOLES (SSI 57-21-32)								Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
					PROC. REF: NDT 57-21-00					PKG:5016,6016
57-21-00-220-803-L00 ^S	DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS:- LOWER SKIN/SPAR ATTACH- MENTS (SSI 57-21-36)								Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
					PROC. REF: NDT 57-21-00					PKG:5016,6016
57-21-00-220-804-L00 ^S	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS:- ACTUATOR ACCESS HOLES (SSI 57-21-34)- LOWER SKIN/SPAR ATTACH - MENTS (SSI 57-21-36)								Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
					PROC. REF: NDT 57-21-00					PKG:5016,6016
57-21-00-220-805-L00 ^S	DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS:- ACTUATOR ACCESS HOLES (SSI 57-21-34)								Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
					PROC. REF: NDT 57-21-00					PKG:5016,6032
57-21-00-220-806-L00 ^S	DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS:- LOWER SKIN ACCESS HOLES (SSI 57-21-32)								Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
					PROC. REF: NDT 57-21-00					PKG:5016,6032
57-21-00-220-807-L00 ^S	DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS:- UPPER SKIN / SPAR ATTACH- MENT (SSI 57-21-37)- SKIN PANELS (SSI 57-21-26)								Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
					PROC. REF: NDT 57-21-00					PKG:5016,6032

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
57-21-00-220-808-L00	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS - SKIN PANELS (SSI 57-21-26) (L650 ONLY)									Service ATA:57
	MOS/MSC	27-Aug-07	N/A							
	HRS	0								
	AFL	0								
PROC. REF: NDT 57-21-00										
57-21-00-220-C01-L00 ^S	DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS:- LOWER VENT HOLE (SSI 57-21-33)									Service ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
PROC. REF: CPM 57-21-00										
PKG:5016,6032										
57-21-00-220-C02-L00	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS:- SKIN PANELS (SSI 57-21-26)- UPPER SKIN PANEL SPAN- WISE JOINT (SSI 57-21-31) (L650 ONLY)									Service ATA:57
	MOS/MSC	25-Sep-07	N/A							
	HRS	0								
	AFL	0								
PROC. REF: CPM 57-21-00										
PKG:6016										
57-21-00-220-C03-L00	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS:- LOWER SKIN PANEL SPAN- WISE JOINT (SSI 57-21-30) (L650 ONLY)									Service ATA:57
	MOS/MSC	25-Sep-07	N/A							
	HRS	0								
	AFL	0								
PROC. REF: CPM 57-21-00										
PKG:6016										
57-21-00-220-C04-L00	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS: - LOWER VENT HOLE (SSI 57-21-33) (L650 ONLY)									Service ATA:57
	MOS/MSC	27-Aug-07	N/A							
	HRS	0								
	AFL	0								
PROC. REF: CPM 57-21-00										
57-21-00-250-802-L00 ^S	SPECIAL DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS BY USING EDDY CURRENT LOW FREQUENCY INSPECTION METHOD:- LOWER SKIN PANEL CHORD- WISE JOINT (SSI 57-21-29). (L600 ONLY)									Service ATA:57
	MOS	11-Aug-15	192 (+15d/-15d)					LOW UTILIZATION		
	HRS	7460.3	8000 (+20/-20)							
	AFL	3992	4000 (+20/-20)							
PROC. REF: NDT 57-21-00										
PKG:5032,6032										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
57-21-00-250-803-L00	SPECIAL DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS BY USING EDDY CURRENT LOW FREQUENCY INSPECTION METHOD:- LOWER SKIN PANEL CHORDWISE JOINT (SSI 57-21-29) (L650 ONLY)								Service	ATA:57
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL		
	HRS	0								
	AFL	0								
PROC. REF: NDT 57-21-00										
57-21-00-250-804-L00	SPECIAL DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS BY USING EDDY CURRENT INSPECTION METHOD:- LOWER SKIN/SPAR ATTACHMENTS (SSI 57-21-36) (L650 ONLY)								Service	ATA:57
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL		
	HRS	0								
	AFL	0								
PROC. REF: NDT 57-21-00										
57-21-00-250-805-L00	SPECIAL DETAIL INSPECTION (EXTERNAL) OF WING COMPONENTS BY USING EDDY CURRENT LOW FREQUENCY INSPECTION METHOD: - LOWER SKIN PANEL CHORDWISE JOINT (SSI 57-21-29) (L650 ONLY)								Service	ATA:57
	MOS/MSC	27-Aug-07	N/A							
	HRS	0								
	AFL	0								
PROC. REF: NDT 57-21-00										
57-22-00-210-801-L00 ^S	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS:- SPAR 1/ WING STUB ATTACH- MENT (SSI 57-22-44)								Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
PROC. REF: NDT 57-22-00										
										PKG:5016,6032
57-22-00-210-802-L00 ^S	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS:- SPAR 1 CAP (SSI 57-22-41)								Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
PROC. REF: NDT 57-22-00										
										PKG:5016,6032
57-22-00-210-803-L00 ^S	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS:- SPAR 1/ LEADING EDGE ATTACH- MENTS (SSI 57-22-43) (L600 ONLY)								Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
PROC. REF: NDT 57-22-00										
										PKG:5016,6016

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
57-22-00-210-804-L00 ^S	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS:- SPAR 1/ LEADING EDGE ATTACHMENTS (SSI 57-22-43)									Service ATA:57
	MOS	02-Jul-15	192 (+15d/-15d)					LOW UTILIZATION		
	HRS	7460.3	8000 (+20/-20)							
	AFL	3992	4000 (+20/-20)							
					PROC. REF: NDT 57-22-00					PKG:5032,6032
57-22-00-210-805-L00 ^S	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS:- SPAR 1 CAP (SSI 57-22-41)									Service ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
					PROC. REF: NDT 57-22-00					PKG:5016,6032
57-22-00-210-806-L00 ^S	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS:- SPAR 1/ LEADING EDGE ATTACHMENTS (SSI 57-22-43)									Service ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
					PROC. REF: NDT 57-22-00					PKG:5016,6032
57-22-00-210-807-L00	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS:- SPAR 1/WING STUB ATTACHMENT (SSI 57-22-44) (L650 ONLY)									Service ATA:57
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL		
	HRS	0								
	AFL	0								
					PROC. REF: NDT 57-22-00					PKG:6016
57-22-00-210-C01-L00 ^S	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS:- SPAR 1/ LEADING EDGE ATTACHMENTS (SSI 57-22-43)									Service ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: CPM 57-22-00					PKG:5008,6016
57-22-00-220-801-L00 ^S	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS:- SPAR 1/ WEB AND STIFFENERS (SSI 57-22-40)									Service ATA:57
	MOS	02-Jul-15	192 (+15d/-15d)					LOW UTILIZATION		
	HRS	7460.3	8000 (+20/-20)							
	AFL	3992	4000 (+20/-20)							
					PROC. REF: NDT 57-22-00					PKG:5032,6032
57-22-00-220-802-L00 ^S	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS:- SPAR 1/ WEB AND STIFFENERS (SSI 57-22-40)- SPAR 1, WEB CUTOUTS (SSI 57-22-42)									Service ATA:57
	MOS	02-Jul-15	192 (+15d/-15d)					LOW UTILIZATION		
	HRS	7460.3	8000 (+20/-20)							
	AFL	3992	4000 (+20/-20)							
					PROC. REF: NDT 57-22-00					PKG:5032,6032

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
57-22-00-220-803-L00 ^S	DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS:- SPAR 1, WEB CUTOUTS (SSI 57-22-42)								Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
	PROC. REF: NDT 57-22-00									PKG:5016,6032
57-22-00-220-804-L00 ^S	DETAILED INSPECTION (INTERNAL) OF WINGLET COMPONENTS:- FRONT SPAR - WINGLET (SSI 57-22-45)								Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
	PROC. REF: NDT 57-22-00									PKG:5016,6032
57-22-00-220-805-L00 ^S	DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS:- SPAR 1, WEB AND STIFFENERS (SSI 57-22-40)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI								Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
	PROC. REF: NDT 57-22-00									PKG:5016,6032
57-22-00-220-806-L00 ^S	DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS:- SPAR 1, WEB AND STIFFENERS (SSI 57-22-40)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI								Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
	PROC. REF: NDT 57-22-00									PKG:5016,6032
57-22-00-220-807-L00	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS:- SPAR 1/ LEADING EDGE ATTACHMENTS (SSI 57-22-43) (L650 ONLY)								Service	ATA:57
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL		
	HRS	0								
	AFL	0								
	PROC. REF: NDT 57-22-00									PKG:6016
57-23-00-210-801-L00 ^S	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS:- SPAR 2 CAP (SSI 57-23-46) (L600 ONLY)								Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
	PROC. REF: NDT 57-23-00									PKG:5016,6032

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 57 - WINGS											
57-23-00-210-802-L00 ^S	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS:- SPAR 2/ WING STUB ATTACH- MENTS (SSI 57-23-48) (L600 ONLY)							Service	ATA:57		
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	4000 (+20/-20)								
	AFL	5401	2000 (+20/-20)								
					PROC. REF: NDT 57-23-00					PKG:5016,6016	
57-23-00-210-803-L00 ^S	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS:- SPAR 2/ WING STUB ATTACH- MENTS (SSI 57-23-48) (L600 ONLY)							Service	ATA:57		
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	4000 (+20/-20)								
	AFL	5401	2000 (+20/-20)								
					PROC. REF: NDT 57-23-00					PKG:5016,6016	
57-23-00-210-804-L00	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS:- SPAR 2 CAP (SSI 57-23-46) (L650 ONLY)							Service	ATA:57		
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL			
	HRS	0									
	AFL	0									
					PROC. REF: NDT 57-23-00					PKG:6032	
57-23-00-210-805-L00	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS:- SPAR 2/ WING STUB ATTACHMENTS (SSI 57-23-48) (L650 ONLY)							Service	ATA:57		
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL			
	HRS	0									
	AFL	0									
					PROC. REF: NDT 57-23-00					PKG:6032	
57-23-00-210-806-L00	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS:- SPAR 2/ WING STUB ATTACHMENTS (SSI 57-23-48) (L650 ONLY)							Service	ATA:57		
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL			
	HRS	0									
	AFL	0									
					PROC. REF: NDT 57-23-00					PKG:6032	
57-23-00-220-801-L00 ^S	DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS:- SPAR 2, WEB AND STIFFENERS (SSI 57-23-45)							Service	ATA:57		
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	4000 (+20/-20)								
	AFL	5401	2000 (+20/-20)								
					PROC. REF: NDT 57-23-00					PKG:5016,6032	
57-23-00-220-803-L00	DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS:- REAR SPAR - WINGLET (SSI 57-23-49) (L650 ONLY)							Service	ATA:57		
	MOS/MSC	09-Jul-15	N/A								
	HRS	7460.3									
	AFL	3992									
					PROC. REF: NDT 57-23-00					PKG:6032	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 57 - WINGS											
57-23-00-220-804-L00 ^S			DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS:- SPAR 2, WEB CUTOUTS (SSI 57-23-47)							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	4000 (+20/-20)								
	AFL	5401	2000 (+20/-20)								
					PROC. REF: NDT 57-23-00					PKG:5016,6032	
57-23-00-220-805-L00 ^S			DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS:- SPAR 2, WEB CUTOUTS (SSI 57-23-47)							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	4000 (+20/-20)								
	AFL	5401	2000 (+20/-20)								
					PROC. REF: NDT 57-23-00					PKG:5016,6032	
57-23-00-220-C01-L00 ^S			DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS:- SPAR 2, WEB AND STIFFEN- ERS (SSI 57-23-45)- SPAR 2, WEB CUTOUTS (SSI 57-23-47)							Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	2000 (+20/-20)								
	AFL	5401	1000 (+20/-20)								
					PROC. REF: CPM 57-23-00					PKG:5008,6016	
57-23-00-290-801-L00 ^S			SPECIAL DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS USING BOROSCOPE:- REAR SPAR - WINGLET (SSI 57-23-49) (L600 ONLY)							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	4000 (+20/-20)								
	AFL	5401	2000 (+20/-20)								
					PROC. REF: NDT 57-23-00					PKG:5016,6032	
57-24-00-210-801-L00 ^S			GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS:- SPAR 3, CAP (SSI 57-24-50)							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	4000 (+20/-20)								
	AFL	5401	2000 (+20/-20)								
					PROC. REF: NDT 57-24-00					PKG:5016,6032	
57-24-00-210-802-L00 ^S			GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS:- SPAR 3, WING STUB ATTACH- MENT (SSI 57-24-52) (L600 ONLY)							Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	4000 (+20/-20)								
	AFL	5401	2000 (+20/-20)								
					PROC. REF: NDT 57-24-00					PKG:5016,6016	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
57-24-00-210-C01-L00 ^S	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS:- SPAR 3, WEB AND STIFFEN- ERS (SSI 57-24-49)- SPAR 3, WEB CUTOUTS (SSI 57-24-51)								Service	ATA:57
MOS	29-Jun-23		48 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		2000 (+20/-20)							
AFL	5401		1000 (+20/-20)							
PROC. REF: CPM 57-24-00										PKG:5008,6016
57-24-00-210-C02-L00 ^S	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS:- SPAR 3, WEB AND STIFFEN- ERS (SSI 57-24-49)- SPAR 3, WEB CUTOUTS (SSI 57-24-51)								Service	ATA:57
MOS	29-Jun-23		48 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		2000 (+20/-20)							
AFL	5401		1000 (+20/-20)							
PROC. REF: CPM 57-24-00										PKG:5008,6016
57-24-00-220-801-L00	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS:- SPAR 3, WING STUB ATTACHMENT (SSI 57-24-52) (L650 ONLY)								Service	ATA:57
MOS/MS	25-Sep-07		N/A					STRUCTURAL		
HRS	0									
AFL	0									
PROC. REF: NDT 57-24-00										PKG:6016
57-25-00-210-C01-L00 ^S	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS:- RIBS, MAIN BOX (SSI 57-25-53)- LOWER SKIN/ RIB ATTACHMENT (SSI 57-25-54)- UPPER SKIN/ RIB ATTACHMENT (SSI 57-25-55)								Service	ATA:57
MOS	29-Jun-23		96 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		4000 (+20/-20)							
AFL	5401		2000 (+20/-20)							
PROC. REF: CPM 57-25-00										PKG:5016,6032
57-25-00-210-C02-L00 ^S	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS:- LOWER SKIN/ RIB ATTACHMENT (SSI 57-25-54)- UPPER SKIN/ RIB ATTACHMENT (SSI 57-25-55)								Service	ATA:57
MOS	29-Jun-23		48 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		2000 (+20/-20)							
AFL	5401		1000 (+20/-20)							
PROC. REF: CPM 57-25-00										PKG:5008,6016
57-25-00-290-801-L00 ^S	SPECIAL DETAILED INSPECTION (INTERNAL) OF WINGLET COM- PONENTS USING BOROSCOPE:- RIB 25 - WINGLET (SSI 57-25-56)								Service	ATA:57
MOS	29-Jun-23		96 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		4000 (+20/-20)							
AFL	5401		2000 (+20/-20)							
PROC. REF: NDT 57-25-00										PKG:5016,6032

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 57 - WINGS											
57-26-00-220-801-L00 ^S			DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS:- FWD & AFT SIDE BRACE FITTINGS, MLG (SSI 57-26-56)							Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	2000 (+20/-20)								
	AFL	5401	1000 (+20/-20)								
					PROC. REF: NDT 57-26-00					PKG:5008,6016	
57-26-00-220-C01-L00 ^S			DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS:- FWD & AFT SIDE BRACE FITTINGS MLG (SSI 57-26-56)- BEARING CAP (SSI 57-26-94)- TRUNNION FITTING (SSI 57-26-95)							Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	2000 (+20/-20)								
	AFL	5401	1000 (+20/-20)								
					PROC. REF: CPM 57-26-00					PKG:5008,6016	
57-26-00-250-802-L00 ^S			SPECIAL DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS BY THE EDDY CURRENT INSPECTION METHOD:- BEARING CAP - MLG (SSI 57-26-94) (L600 ONLY)							Service	ATA:57
	MOS	27-Aug-07	288 (+15d/-15d)					LOW UTILIZATION			
	HRS	0	12000 (+20/-20)								
	AFL	0	6000 (+20/-20)								
					PROC. REF: NDT 57-26-00					PKG:5140	
57-26-00-250-803-L00 ^S			SPECIAL DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS BY THE EDDY CURRENT INSPECTION METHOD:- FWD & AFT SIDE BRACE FITTINGS, MLG (SSI 57-26-56)							Service	ATA:57
	MOS	27-Aug-07	288 (+15d/-15d)					LOW UTILIZATION			
	HRS	0	12000 (+20/-20)								
	AFL	0	6000 (+20/-20)								
					PROC. REF: NDT 57-26-00					PKG:5140	
57-26-00-250-804-L00 ^S			SPECIAL DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS BY THE EDDY CURRENT INSPECTION METHOD:- TRUNNION FITTINGS (SSI 57-26-95)							Service	ATA:57
	MOS	27-Aug-07	288 (+15d/-15d)					LOW UTILIZATION			
	HRS	0	12000 (+20/-20)								
	AFL	0	6000 (+20/-20)								
					PROC. REF: NDT 57-26-00					PKG:5140	
57-26-00-250-805-L00			SPECIAL DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS BY THE EDDY CURRENT INSPECTION METHOD:- BEARING CAP - MLG (SSI 57-26-94) (L650 ONLY)							Service	ATA:57
	MOS/MS	25-Sep-07	N/A					STRUCTURAL			
	HRS	0									
	AFL	0									
					PROC. REF: NDT 57-26-00					PKG:6032	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
57-28-00-210-801-L00 ^S	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS:- SPAR ATTACHMENT, TORQUE BOX (SSI 57-28-57)								Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
					PROC. REF: NDT 57-28-00					PKG:5016,6032
57-28-00-210-804-L00 ^S	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS:- SPAR 3 ATTACHMENT, TORQUE BOX (SSI 57-28-63)- OUTBOARD FLAP CENTER TRACK ATTACHMENT(SS I 57-28-68) (L600 ONLY)								Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
					PROC. REF: NDT 57-28-00					PKG:5016,6032
57-28-00-210-806-L00 ^S	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS:- SPAR 3 ATTACHMENT, TORQUE BOX 2 (SSI 57-28-63)								Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
					PROC. REF: NDT 57-28-00					PKG:5016,6032
57-28-00-210-807-L00 ^S	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS:- ATTACHMENT LUGS AILERON(SS I 57-28-66)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI (L600 ONLY)								Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
					PROC. REF: NDT 57-28-00					PKG:5016
57-28-00-210-808-L00 ^S	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS:- UPPER SKIN, TORQUE BOX (SSI 57-28-61)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI								Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
					PROC. REF: NDT 57-28-00					PKG:5016,6032
57-28-00-210-809-L00	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS:- SPAR ATTACHMENT, TORQUE BOX (SSI 57-28-57) (L650 ONLY)								Service	ATA:57
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL		
	HRS	0								
	AFL	0								
					PROC. REF: NDT 57-28-00					PKG:6016

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
57-28-00-210-810-L00	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS: - SPAR 3 ATTACHMENT, TORQUE BOX (SSI 57-28-63) (L650 ONLY)								Service	ATA:57
	MOS/MSC	27-Aug-07	N/A							
	HRS	0								
	AFL	0								
PROC. REF: NDT 57-28-00										
57-28-00-210-C01-L00 ^S	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS:- LOWER SKIN, TORQUE BOX (SSI 57-28-58) (L600 ONLY)								Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
PROC. REF: CPM 57-28-00										
PKG:5008,6016										
57-28-00-210-C02-L00 ^S	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS:- SPAR ATTACHMENT, TORQUE BOX (SSI 57-28-57) (L600 ONLY)								Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
PROC. REF: CPM 57-28-00										
PKG:5008,6016										
57-28-00-210-C03-L00 ^S	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS:- UPPER SKIN, TORQUE BOX (SSI 57-28-61)								Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
PROC. REF: CPM 57-28-00										
PKG:5009										
57-28-00-210-C04-L00 ^S	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS:- FLAP ACTUATOR ATTACHMENT FITTINGS (SSI 57-28-67)								Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
PROC. REF: CPM 57-28-00										
PKG:5009										
57-28-00-210-C05-L00 ^S	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS:- SPAR ATTACHMENT, TORQUE BOX (SSI 57-28-57)								Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
PROC. REF: CPM 57-28-00										
PKG:5016,6032										
57-28-00-210-C07-L00 ^S	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS:- LOWER SKIN, TORQUE BOX (SSI 57-28-58)								Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
PROC. REF: CPM 57-28-00										
PKG:5008,6016										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
57-28-00-210-C09-L00 ^S	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS:- UPPER SKIN, TORQUE BOX (SSI 57-28-61)								Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: CPM 57-28-00					PKG:5009
57-28-00-210-C10-L00 ^S	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS:- SPAR ATTACHMENT, TORQUE BOX (SSI 57-28-57)								Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: CPM 57-28-00					PKG:5009
57-28-00-220-801-L00 ^S	DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS:- SPAR ATTACHMENT, TORQUE BOX (SSI 57-28-57)								Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
					PROC. REF: NDT 57-28-00					PKG:5016,6032
57-28-00-220-804-L00 ^S	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS:- CENTER TRACK AND RIB 15 TRAILING EDGE(SS I 57-28-69)								Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
					PROC. REF: NDT 57-28-00					PKG:5016,6016
57-28-00-220-805-L00 ^S	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS:- TRACKS/ RIBS ATTACHMENT, TORQUE BOX(SS I 57-28-62)								Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
					PROC. REF: NDT 57-28-00					PKG:5016,6032
57-28-00-220-806-L00	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS:- SPAR 3 ATTACHMENT, TORQUE BOX (SSI 57-28-63)- OUTBOARD FLAP CENTER TRACK ATTACHMENT (SSI 57-28-68) (L650 ONLY)								Service	ATA:57
	MOS/MS C	25-Sep-07	N/A					STRUCTURAL		
	HRS	0								
	AFL	0								
					PROC. REF: NDT 57-28-00					PKG:6032

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
57-28-00-220-807-L00	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS:- ATTACHMENT LUGS AILERON (SSI 57-28-66)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI. (L650 ONLY)								Service	ATA:57
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL		
	HRS	0								
	AFL	0								
					PROC. REF: NDT 57-28-00					PKG:6032
57-28-00-220-808-L00	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS:- RIBS, TORQUE BOX (SSI 57-28-60) (L650 ONLY)								Service	ATA:57
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL		
	HRS	0								
	AFL	0								
					PROC. REF: NDT 57-28-00					PKG:6016
57-28-00-220-809-L00	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS:- RIBS, TORQUE BOX 3 (SSI 57-28-64)- TRACKS/ RIB ATTACHMENT, TORQUE BOX 3 (SSI 57-28-65) (L650 ONLY)								Service	ATA:57
	MOS/MSC	25-Sep-07	N/A							
	HRS	0								
	AFL	0								
					PROC. REF: NDT 57-28-00					PKG:6016
57-28-00-220-C01-L00 ^S	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS:- SPAR ATTACHMENT, TORQUE BOX (SSI 57-28-57)								Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: CPM 57-28-00					PKG:5008,6016
57-28-00-220-C02-L00 ^S	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS:- FLAP TRACK, TORQUE BOX (SSI 57-28-59)								Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: CPM 57-28-00					PKG:5009
57-28-00-220-C03-L00 ^S	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS:- RIBS, TORQUE BOX 3 (SSI 57-28-64)- TRACKS/ RIB ATTACHMENT, TORQUE BOX 3(SSI 57-28-65) (L600 ONLY)								Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: CPM 57-28-00					PKG:5008,6016

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
57-28-00-220-C04-L00 ^S	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS:- ATTACHMENT ACTUATOR LUGS, INBOARD/ OUTBOARD SPOILERS (SSI 57-28-70)								Service	ATA:57
MOS	29-Jun-23		48 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		2000 (+20/-20)							
AFL	5401		1000 (+20/-20)							
PROC. REF: CPM 57-28-00										PKG:5008,6016
57-28-00-220-C05-L00 ^S	DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS:- TRACKS/ RIBS ATTACHMENT, TORQUE BOX(SSI 57-28-62)								Service	ATA:57
MOS	29-Jun-23		96 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		4000 (+20/-20)							
AFL	5401		2000 (+20/-20)							
PROC. REF: CPM 57-28-00										PKG:5016,6032
57-28-00-220-C06-L00 ^S	DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS:- RIBS, TORQUE BOX 3 (SSI 57-28-64)- TRACKS/ RIB ATTACHMENT, TORQUE BOX 3(SSI 57-28-65)								Service	ATA:57
MOS	29-Jun-23		96 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		4000 (+20/-20)							
AFL	5401		2000 (+20/-20)							
PROC. REF: CPM 57-28-00										PKG:5016,6032
57-28-00-220-C07-L00 ^S	DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS:- RIBS, TORQUE BOX 3 (SSI 57-28-60)								Service	ATA:57
MOS	29-Jun-23		48 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		2000 (+20/-20)							
AFL	5401		1000 (+20/-20)							
PROC. REF: CPM 57-28-00										PKG:5009
57-28-00-220-C08-L00 ^S	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS:- RIBS, TORQUE BOX (SSI 57-28-60)								Service	ATA:57
MOS	29-Jun-23		48 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		2000 (+20/-20)							
AFL	5401		1000 (+20/-20)							
PROC. REF: CPM 57-28-00										PKG:5009
57-28-00-220-C09-L00 ^S	DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS:- RIBS, TORQUE BOX (SSI 57-28-60)								Service	ATA:57
MOS	29-Jun-23		48 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		2000 (+20/-20)							
AFL	5401		1000 (+20/-20)							
PROC. REF: CPM 57-28-00										PKG:5008,6016

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
57-28-00-220-C10-L00 ^S	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS:- RIBS, TORQUE BOX (SSI 57-28-60) (L600 ONLY)								Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
	PROC. REF: CPM 57-28-00									PKG:5008,6016
57-28-00-220-C11-L00	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS:- LOWER SKIN, TORQUE BOX (SSI 57-28-58) (L650 ONLY)								Service	ATA:57
	MOS/MSC	25-Sep-07	N/A							
	HRS	0								
	AFL	0								
	PROC. REF: CPM 57-28-00									PKG:6016
57-28-00-250-801-L00 ^S	SPECIAL DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS BY THE EDDY CURRENT INSPECTION METHOD:- SPAR ATTACHMENT, TORQUE BOX (SSI 57-28-57)								Service	ATA:57
	MOS	27-Aug-07	288 (+15d/-15d)					LOW UTILIZATION		
	HRS	0	12000 (+20/-20)							
	AFL	0	6000 (+20/-20)							
	PROC. REF: NDT 57-28-00									PKG:5140
57-28-00-250-802-L00 ^S	SPECIAL DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS BY THE EDDY CURRENT INSPECTION METHOD:- RIBS, TORQUE BOX (SSI 57-28-60)								Service	ATA:57
	MOS	27-Aug-07	288 (+15d/-15d)					LOW UTILIZATION		
	HRS	0	12000 (+20/-20)							
	AFL	0	6000 (+20/-20)							
	PROC. REF: NDT 57-28-00									PKG:5140
57-28-00-250-803-L00 ^S	SPECIAL DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS BY THE EDDY CURRENT INSPECTION METHOD:- SPAR ATTACHMENT, TORQUE BOX (SSI 57-28-57)								Service	ATA:57
	MOS	27-Aug-07	288 (+15d/-15d)					LOW UTILIZATION		
	HRS	0	12000 (+20/-20)							
	AFL	0	6000 (+20/-20)							
	PROC. REF: NDT 57-28-00									PKG:5140
57-28-00-250-804-L00 ^S	SPECIAL DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS BY THE EDDY CURRENT INSPECTION METHOD:- RIBS, TORQUE BOX (SSI 57-28-60)								Service	ATA:57
	MOS	27-Aug-07	288 (+15d/-15d)					LOW UTILIZATION		
	HRS	0	12000 (+20/-20)							
	AFL	0	6000 (+20/-20)							
	PROC. REF: NDT 57-28-00									PKG:5140

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
57-28-00-250-805-L00 ^S	SPECIAL DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS BY THE EDDY CURRENT INSPECTION METHOD:- FLAP TRACK, TORQUE BOX (SSI 57-28-59)								Service	ATA:57
MOS	27-Aug-07		288 (+15d/-15d)					LOW UTILIZATION		
HRS	0		12000 (+20/-20)							
AFL	0		6000 (+20/-20)							
PROC. REF: NDT 57-28-00										PKG:5140
57-29-00-220-801-L00 ^S	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS:- SKIN/ RIB ATTACHMENT, MLGB (SSI 57-29-72)								Service	ATA:57
MOS	29-Jun-23		96 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		4000 (+20/-20)							
AFL	5401		2000 (+20/-20)							
PROC. REF: NDT 57-29-00										PKG:5016,6016
57-29-00-220-802-L00 ^S	DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS:- RIBS, MAIN LANDING GEAR BAY (SSI 57-29-71)- SKIN/ RIB ATTACHMENT, MLGB (SSI 57-29-72)								Service	ATA:57
MOS	29-Jun-23		96 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		4000 (+20/-20)							
AFL	5401		2000 (+20/-20)							
PROC. REF: NDT 57-29-00										PKG:5016,6016
57-41-00-210-801-L00	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING LEAD- ING EDGE COMPONENTS:- WING LEADING EDGE 1 SKIN (SSI 57-41-94) (L650 ONLY)								Service	ATA:57
MOS/MS	25-Sep-07		N/A					STRUCTURAL		
HRS	0									
AFL	0									
PROC. REF: NDT 57-41-00										PKG:6032
57-41-00-210-C01-L00 ^S	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING LEADING EDGE COMPONENTS:- WING LEADING EDGE 1 SKIN (SSI 57-41-94) (L600 ONLY)								Service	ATA:57
MOS	29-Jun-23		48 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		2000 (+20/-20)							
AFL	5401		1000 (+20/-20)							
PROC. REF: CPM 57-41-00										PKG:5008,6016
57-41-00-220-801-L00 ^S	DETAILED INSPECTION (INTERNAL) OF WING LEADING EDGE COMPONENTS:- MACHINED RIB FLANGE (SSI 57-41-98)								Service	ATA:57
MOS	29-Jun-23		96 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		4000 (+20/-20)							
AFL	5401		2000 (+20/-20)							
PROC. REF: NDT 57-41-00										PKG:5016,6032

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
57-42-00-210-801-L00	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING LEAD- ING EDGE COMPONENTS:- WING LEADING EDGE 2 SKIN (SSI 57-42-95) (L650 ONLY)									Service ATA:57
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL		
	HRS	0								
	AFL	0								
					PROC. REF: NDT 57-42-00					PKG:6032
57-42-00-210-C01-L00 ^S	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING LEADING EDGE COMPONENTS:- WING LEADING EDGE 2 SKIN (SSI 57-42-95) (L600 ONLY)									Service ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: CPM 57-42-00					PKG:5008,6016
57-42-00-220-801-L00 ^S	DETAILED INSPECTION (INTERNAL) OF WING LEADING EDGE COMPONENTS:- MACHINED RIB FLANGE (SSI 57-42-98)									Service ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
					PROC. REF: NDT 57-42-00					PKG:5016,6032
57-42-00-220-802-L00 ^S	DETAILED INSPECTION (EXTERNAL) OF WING LEADING EDGE COMPONENTS:- WING LEADING EDGE 2 BOTTOM SKIN AT CONNECTIONSTO LOWER REAR GIRDER & WING LOWER SPAR CAP (SSI 57-42-97)									Service ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: NDT 57-42-00					PKG:5008,6016
57-43-00-210-801-L00	GENERAL VISUAL INSPECTION (EXTERNAL) OF LEADING EDGE COMPONENTS:- WING LEADING EDGE 3 SKIN (SSI 57-43-96) (L650 ONLY)									Service ATA:57
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL		
	HRS	0								
	AFL	0								
					PROC. REF: NDT 57-43-00					PKG:6032
57-43-00-210-C01-L00 ^S	GENERAL VISUAL INSPECTION (EXTERNAL) OF LEADING EDGE COMPONENTS:- WING LEADING EDGE 3 SKIN (SSI 57-43-96) (L600 ONLY)									Service ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: CPM 57-43-00					PKG:5008,6016

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
57-43-00-220-801-L00 ^S	DETAILED INSPECTION (INTERNAL) OF WING LEADING EDGE COMPONENTS:- MACHINED RIB FLANGE (SSI 57-43-98)								Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
	PROC. REF: NDT 57-43-00									PKG:5016,6032
57-50-00-220-803-L00 ^S	DETAILED INSPECTION (EXTERNAL) OF FLAP COMPONENTS:- ROLLER ATTACHMENT, FLAPS (SSI 57-50-76)								Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
	PROC. REF: NDT 57-50-00									PKG:5016,6032
57-50-00-220-804-L00 ^S	DETAILED INSPECTION (EXTERNAL) OF FLAP COMPONENTS:- TRACKS, FLAPS (SSI 57-50-80)								Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
	PROC. REF: NDT 57-50-00									PKG:5008,6016
57-50-00-220-805-L00 ^S	DETAILED INSPECTION (EXTERNAL) OF FLAPCOMPONENTS: FLAP ROOT-SPAR FITTING (SSI 57-50-74). INBOARD FLAP FITTING TIP SPAR (SSI 57-52-73). OUTBOARD FLAP TIP SPAR FITTING (SSI 57-53-83).								Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
	PROC. REF: NDT 57-50-00									PKG:5016,6032
57-50-00-220-806-L00 ^S	DETAILED INSPECTION (EXTERNAL) OF FLAPCOMPONENTS: INBOARD FLAP RIBS/SKIN ATTACHMENT (SSI57-52-79). INBOARD FLAP VANE INBOARD/OUTBOARD FITTINGS(SSI 57-52-81). OUTBOARD FLAP RIBS/SKIN ATTACHMENT (SSI57-53-86). OUTBOARD FLAP VANE INBOARD/OUTBOARDFITTINGS (SSI 57-53-88).								Service	ATA:57
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	4000 (+20/-20)							
	AFL	5401	2000 (+20/-20)							
	PROC. REF: NDT 57-50-00									PKG:5016,6016
57-50-00-220-C01-L00 ^S	DETAILED INSPECTION (EXTERNAL) OF FLAP COMPONENTS:- TRACKS/ RIB ATTACHMENT, FLAPS (SSI 57-50-77)								Service	ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
	PROC. REF: CPM 57-50-00									PKG:5009

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
57-50-00-250-801-L00 ^S	SPECIAL DETAILED INSPECTION (EXTERNAL) OF FLAP COMPONENTS BY THE EDDY CURRENT INSPECTION METHOD:- ROLLER ATTACHMENT, FLAPS (SSI 57-50-76)								Service	ATA:57
MOS	27-Aug-07	288 (+15d/-15d)	LOW UTILIZATION							
HRS	0	12000 (+20/-20)								
AFL	0	6000 (+20/-20)								
PROC. REF: NDT 57-50-00										PKG:5140
57-50-00-250-802-L00 ^S	SPECIAL DETAILED INSPECTION (EXTERNAL) OF FLAP COMPONENTS BY THE EDDY CURRENT INSPECTION METHOD:- TRACKS, FLAPS (SSI 57-50-80) (L600 ONLY)								Service	ATA:57
MOS	27-Aug-07	288 (+15d/-15d)	LOW UTILIZATION							
HRS	0	12000 (+20/-20)								
AFL	0	6000 (+20/-20)								
PROC. REF: NDT 57-50-00										PKG:5140
57-50-00-250-803-L00	SPECIAL DETAILED INSPECTION (EXTERNAL) OF FLAP COMPONENTS BY THE EDDY CURRENT INSPECTION METHOD:- TRACKS, FLAPS (SSI 57-50-80) (L650 ONLY)								Service	ATA:57
MOS/MSC	25-Sep-07	N/A	STRUCTURAL							
HRS	0									
AFL	0									
PROC. REF: NDT 57-50-00										
57-50-00-290-801-L00 ^S	SPECIAL DETAILED INSPECTION (INTERNAL) OF FLAPCOMPONENTS BY BORESCOPE INSPECTION METHOD: STRUCTURAL SIGNIFICANT ITEM: SSI 57-50-74 - FLAPROOTSPAR FITTING. STRUCTURAL SIGNIFICANT ITEM: SSI 57-52-73 -INBOARD FLAP TIP SPAR FITTING. STRUCTURAL SIGNIFICANT ITEM: SSI 57-53-83 -OUTBOARD FLAP TIP SPAR FITTING.								Service	ATA:57
MOS	29-Jun-23	96 (+15d/-15d)	LOW UTILIZATION							
HRS	10161.5	4000 (+20/-20)								
AFL	5401	2000 (+20/-20)								
PROC. REF: NDT 57-50-00										PKG:5016,6032
57-52-00-210-803-L00 ^S	GENERAL VISUAL INSPECTION (EXTERNAL) OF FLAP COMPONENTS:- VANE CENTER FITTING, INBOARD FLAP (SSI 57-52-78) (L600 ONLY)								Service	ATA:57
MOS	29-Jun-23	48 (+15d/-15d)	LOW UTILIZATION							
HRS	10161.5	2000 (+20/-20)								
AFL	5401	1000 (+20/-20)								
PROC. REF: NDT 57-52-00										PKG:5008
57-52-00-210-804-L00 ^S	GENERAL VISUAL INSPECTION (EXTERNAL) OF FLAP COMPONENTS:- PIN AND ACTUATOR LUGS, INBOARD FLAP (SSI 57-52-75) (L600 ONLY)								Service	ATA:57
MOS	29-Jun-23	48 (+15d/-15d)	LOW UTILIZATION							
HRS	10161.5	2000 (+20/-20)								
AFL	5401	1000 (+20/-20)								
PROC. REF: NDT 57-52-00										PKG:5009,6008

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
57-52-00-210-805-L00	GENERAL VISUAL INSPECTION (EXTERNAL) OF FLAP COMPONENTS:- PIN AND ACTUATOR LUGS, INBOARD FLAP (SSI 57-52-75) (L650 ONLY)									Service ATA:57
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL		
	HRS	0								
	AFL	0								
	PROC. REF: NDT 57-52-00									PKG:6016
57-52-00-220-803-L00	DETAILED INSPECTION (EXTERNAL) OF FLAP COMPONENTS:- VANE CENTER FITTING, INBOARD FLAP (SSI 57-52-78) (L650 ONLY)									Service ATA:57
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL		
	HRS	0								
	AFL	0								
	PROC. REF: NDT 57-52-00									PKG:6016
57-53-00-210-801-L00 ^S	GENERAL VISUAL INSPECTION (EXTERNAL) OF FLAP COMPONENTS:- VANE CENTER FITTING, OUTBOARD FLAP (SSI 57-53-85) (L600 ONLY)									Service ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
	PROC. REF: NDT 57-53-00									PKG:5008
57-53-00-210-803-L00 ^S	GENERAL VISUAL INSPECTION (INTERNAL) OF FLAP COMPONENTS:- CENTER RIBS ATTACHMENT, OUTBOARD FLAP (SSI 57-53-87) ONLY)									Service ATA:57
	MOS	27-Aug-07	288 (+15d/-15d)					LOW UTILIZATION		
	HRS	0	12000 (+20/-20)							
	AFL	0	6000 (+20/-20)							
	PROC. REF: NDT 57-53-00									PKG:5140
57-53-00-210-806-L00 ^S	GENERAL VISUAL INSPECTION(EXTERNAL) OF FLAP COMPONENTS:- PIN AND ACTUATOR LUGS, OUTBOARD FLAP(SS I 57-53-84) (L600 ONLY)									Service ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
	PROC. REF: NDT 57-53-00									PKG:5009,6008
57-53-00-210-807-L00	GENERAL VISUAL INSPECTION(EXTERNAL) OF FLAP COMPONENTS:- PIN AND ACTUATOR LUGS, OUT- BOARD FLAP (SSI 57-53-84) (L650 ONLY)									Service ATA:57
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL		
	HRS	0								
	AFL	0								
	PROC. REF: NDT 57-53-00									PKG:6032

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
57-53-00-210-C01-L00 ^S	GENERAL VISUAL INSPECTION (EXTERNAL) OF FLAP COMPONENTS:- CENTER RIBS ATTACHMENT, OUTBOARD FLAP(SS1 57-53-87) (L600 ONLY)								Service	ATA:57
MOS	29-Jun-23		48 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		2000 (+20/-20)							
AFL	5401		1000 (+20/-20)							
PROC. REF: CPM 57-53-00										PKG:5009
57-53-00-220-803-L00	DETAILED INSPECTION (EXTERNAL) OF FLAP COMPONENTS:- VANE CENTER FITTING, OUTBOARD FLAP (SSI 57-53-85) (L650 ONLY)								Service	ATA:57
MOS/MSC	25-Sep-07		N/A					STRUCTURAL		
HRS	0									
AFL	0									
PROC. REF: NDT 57-53-00										PKG:6032
57-53-00-220-C01-L00	DETAILED INSPECTION (EXTERNAL) OF FLAP COMPONENTS:- CENTER RIBS ATTACHMENT, OUTBOARD FLAP (SSI 57-53-87) (L650 ONLY)								Service	ATA:57
MOS/MSC	25-Sep-07		N/A							
HRS	0									
AFL	0									
PROC. REF: CPM 57-53-00										
57-61-00-210-801-L00 ^S	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS:- HINGES ATTACHMENT, AILERON (SSI 57-61-89)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI (L600 ONLY)								Service	ATA:57
MOS	29-Jun-23		96 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		4000 (+20/-20)							
AFL	5401		2000 (+20/-20)							
PROC. REF: NDT 57-61-00										PKG:5016,6032
57-61-00-210-C01-L00 ^S	GENERAL VISUAL INSPECTION (EXTERNAL) OF AILERON COMPONENTS:- SPAR CAP, AILERON (SSI 57-61-91)								Service	ATA:57
MOS	29-Jun-23		48 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		2000 (+20/-20)							
AFL	5401		1000 (+20/-20)							
PROC. REF: CPM 57-61-00										PKG:5009
57-61-00-220-801-L00 ^S	DETAILED INSPECTION (EXTERNAL) OF AILERON COMPONENTS:- ACTUATOR ATTACHMENT, AILERON (SSI 57-61-90)								Service	ATA:57
MOS	29-Jun-23		96 (+15d/-15d)					LOW UTILIZATION		
HRS	10161.5		4000 (+20/-20)							
AFL	5401		2000 (+20/-20)							
PROC. REF: NDT 57-61-00										PKG:5016,6016

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 57 - WINGS											
57-61-00-220-802-L00 ^S	DETAILED INSPECTION (INTERNAL) OF AILERON COMPONENTS:- ACTUATOR ATTACHMENT, AILERON (SSI 57-61-90)								Service	ATA:57	
	MOS	03-Jul-15	192 (+15d/-15d)					LOW UTILIZATION			
	HRS	7460.3	8000 (+20/-20)								
	AFL	3992	4000 (+20/-20)								
	PROC. REF: NDT 57-61-00									PKG:5032,6032	
57-61-00-220-804-L00 ^S	DETAILED INSPECTION (INTERNAL) OF AILERON COMPONENTS:- AILERON ACTUATOR FITTINGS (SSI 57-61-12)								Service	ATA:57	
	MOS/MSC	03-Jul-15	N/A								
	HRS	7460.3									
	AFL	3992									
	PROC. REF: NDT 57-61-00									PKG:5032,6032	
57-61-00-220-805-L00	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS:- HINGES ATTACHMENT, AILERON (SSI 57-61-89)NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI. (L650 ONLY)								Service	ATA:57	
	MOS/MSC	25-Sep-07	N/A					STRUCTURAL			
	HRS	0									
	AFL	0									
	PROC. REF: NDT 57-61-00									PKG:6032	
57-70-00-210-C01-L00 ^S	GENERAL VISUAL INSPECTION (EXTERNAL) OF SPOILER COMPONENTS:- HINGES ATTACHMENT, SPOILERS (SSI 57-70-92)- ACTUATOR ATTACHMENT, SPOILERS (SSI 57-70-93)								Service	ATA:57	
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	2000 (+20/-20)								
	AFL	5401	1000 (+20/-20)								
	PROC. REF: CPM 57-70-00									PKG:5008,6016	
57-Z511-213-001-A00 ^S	GENERAL VISUAL INSPECTION(EXTERNAL) (ZONES 511, 611, 512, 612, 513 AND 613)								Service	ATA:57	
	MOS	29-Jun-23	24 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	1000 (+20/-20)								
	AFL	5401									
	PROC. REF: AMM 05-20-76									PKG:5004	
57-Z511-214-001-A00 ^S	GENERAL VISUAL INSPECTION(INTERNAL) (L600 ONLY) (ZONES 511, 611, 512, 612, 513 AND 613)								Service	ATA:57	
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	2000 (+20/-20)								
	AFL	5401	1000 (+20/-20)								
	PROC. REF: AMM 05-20-76									PKG:5008,6016	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
57-Z511-214-001-A01	GENERAL	VISUAL	INSPECTION	(INTERNAL)	(ZONES 511, 611, 512, 612, 513 AND 613)	NOTE:EWIS (L650 ONLY)				Service ATA:57
	MOS/MSC	25-Sep-07	N/A					ZONAL		
	HRS	0								
	AFL	0								
					PROC. REF: AMM 05-20-76					PKG:6016
57-Z531-213-001-A00 ^S	GENERAL	VISUAL	INSPECTION	(EXTERNAL)	(ZONES 531, 631)					Service ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: AMM 05-20-82					PKG:5008,6016
57-Z531-214-001-A00 ^S	GENERAL	VISUAL	INSPECTION	(INTERNAL)	(ZONES 531, 631)	(L600 ONLY)				Service ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: AMM 05-20-82					PKG:5008,6016
57-Z531-214-001-A01	GENERAL	VISUAL	INSPECTION	(INTERNAL)	(ZONES 531, 631)	NOTE:EWIS (L650 ONLY)				Service ATA:57
	MOS/MSC	25-Sep-07	N/A					ZONAL		
	HRS	0								
	AFL	0								
					PROC. REF: AMM 05-20-82					PKG:6016
57-Z532-213-001-A00 ^S	GENERAL	VISUAL	INSPECTION	(EXTERNAL)	(ZONES 532 AND 632)					Service ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: AMM 05-20-84					PKG:5008,6016
57-Z532-214-001-A00 ^S	GENERAL	VISUAL	INSPECTION	(INTERNAL)	(ZONES 532 AND 632)	(L600 ONLY)				Service ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: AMM 05-20-84					PKG:5008,6016
57-Z532-214-001-A01	GENERAL	VISUAL	INSPECTION	(INTERNAL)	(ZONES 532 AND 632)	NOTE:EWIS (L650 ONLY)				Service ATA:57
	MOS/MSC	25-Sep-07	N/A					ZONAL		
	HRS	0								
	AFL	0								
					PROC. REF: AMM 05-20-84					PKG:6016

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
57-Z541-213-001-A00 ^S	GENERAL VISUAL INSPECTION(EXTERNAL) (ZONES 541 AND 641)									Service ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: AMM 05-20-86					PKG:5008,6016
57-Z541-214-001-A00 ^S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 541 AND 641) (L600 ONLY)									Service ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: AMM 05-20-86					PKG:5008,6016
57-Z541-214-001-A01	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 541 AND 641)NOTE:EWIS (L650 ONLY)									Service ATA:57
	MOS/MSC	25-Sep-07	N/A					ZONAL		
	HRS	0								
	AFL	0								
					PROC. REF: AMM 05-20-86					PKG:6016
57-Z551-213-002-A00 ^S	GENERAL VISUAL INSPECTION(EXTERNAL) (ZONES 551, 561, 651, 661)									Service ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: AMM 05-20-88					PKG:5008,6016
57-Z551-214-002-A00 ^S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 551, 561, 651, 661) (L600 ONLY)									Service ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: AMM 05-20-88					PKG:5008,6016
57-Z551-214-002-A01	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 551, 561, 651, 661)NOTE:EWIS (L650 ONLY)									Service ATA:57
	MOS/MSC	25-Sep-07	N/A					ZONAL		
	HRS	0								
	AFL	0								
					PROC. REF: AMM 05-20-88					PKG:6016
57-Z571-213-001-A00 ^S	GENERAL VISUAL INSPECTION(EXTERNAL) (ZONES 571, 671, 5711, 6711, 5712, 6712, 5713, 6713)									Service ATA:57
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
					PROC. REF: AMM 05-20-90					PKG:5008,6016

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 57 - WINGS											
57-Z571-214-001-A00 ^S	GENERAL VISUAL INSPECTION	(INTERNAL)	(ZONES 571, 671, 5711, 6711, 5712, 6712, 5713, 6713) (L600 ONLY)					Service	ATA:57		
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	2000 (+20/-20)								
	AFL	5401	1000 (+20/-20)								
					PROC. REF: AMM 05-20-90					PKG:5008,6016	
57-Z571-214-001-A01	GENERAL VISUAL INSPECTION	(INTERNAL)	(ZONES 571, 671, 5711, 6711, 5712, 6712, 5713, 6713)NOTE:EWIS (L650 ONLY)					Service	ATA:57		
	MOS/MSC	25-Sep-07	N/A					ZONAL			
	HRS	0									
	AFL	0									
					PROC. REF: AMM 05-20-90						
57-Z572-213-001-A00 ^S	GENERAL VISUAL INSPECTION	(EXTERNAL)	(ZONES 572, 672, 5721, 6721, 5722, 6722)					Service	ATA:57		
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	2000 (+20/-20)								
	AFL	5401	1000 (+20/-20)								
					PROC. REF: AMM 05-20-92					PKG:5008,6016	
57-Z572-214-001-A00 ^S	GENERAL VISUAL INSPECTION	(INTERNAL)	(ZONES 572, 672, 5721, 6721, 5722, 6722) (L600 ONLY)					Service	ATA:57		
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	2000 (+20/-20)								
	AFL	5401	1000 (+20/-20)								
					PROC. REF: AMM 05-20-92					PKG:5008,6016	
57-Z572-214-001-A01	GENERAL VISUAL INSPECTION	(INTERNAL)	(ZONES 572, 672, 5721, 6721, 5722, 6722).NOTE:EWIS (L650 ONLY)					Service	ATA:57		
	MOS/MSC	25-Sep-07	N/A					ZONAL			
	HRS	0									
	AFL	0									
					PROC. REF: AMM 05-20-92						
57-Z573-213-001-A00 ^S	GENERAL VISUAL INSPECTION	(EXTERNAL)	(ZONES 573, 673, 5731, 6731, 5732, 6732)					Service	ATA:57		
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	2000 (+20/-20)								
	AFL	5401	1000 (+20/-20)								
					PROC. REF: AMM 05-20-94					PKG:5008,6016	
57-Z573-214-001-A00 ^S	GENERAL VISUAL INSPECTION	(INTERNAL)	(ZONES 573, 673, 5731, 6731, 5732, 6732) (L600 ONLY)					Service	ATA:57		
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	2000 (+20/-20)								
	AFL	5401	1000 (+20/-20)								
					PROC. REF: AMM 05-20-94					PKG:5008,6016	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
57-Z573-214-001-A01	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 573, 673, 5731, 6731, 5732, 6732)NOTE:EWIS (L650 ONLY)									Service ATA:57
	MOS/MSC	25-Sep-07	N/A					ZONAL		
	HRS	0								
	AFL	0								
PROC. REF: AMM 05-20-94										
574000-0201	LH WING LEADING EDGE WING ASSEMBLY									Component ATA:57
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 57-41-00, AMM 57-42-00, AMM 57-43-00										
574000-0202	LH WING LEADING EDGE WING ASSEMBLY									Component ATA:57
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 57-41-00, AMM 57-42-00, AMM 57-43-00										
574000-0203	LH WING LEADING EDGE WING ASSEMBLY									Component ATA:57
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 57-41-00, AMM 57-42-00, AMM 57-43-00										
574000-0204	RH WING LEADING EDGE WING ASSEMBLY									Component ATA:57
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 57-41-00, AMM 57-42-00, AMM 57-43-00										
574000-0205	RH WING LEADING EDGE WING ASSEMBLY									Component ATA:57
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 57-41-00, AMM 57-42-00, AMM 57-43-00										
574000-0206	RH WING LEADING EDGE WING ASSEMBLY									Component ATA:57
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 57-41-00, AMM 57-42-00, AMM 57-43-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
575300-0101	WING FLAP ASSY ASSEMBLY									Component ATA:57
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-50-00										
575300-0102	WING FLAP ASSY ASSEMBLY									Component ATA:57
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-50-00										
575600-0101	LH WING SHROUD ASSY									Component ATA:57
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										
575600-0102	RH WING SHROUD ASSY									Component ATA:57
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										
575600-0201	LH WING SHROUD ASSY									Component ATA:57
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										
575600-0202	RH WING SHROUD ASSY									Component ATA:57
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										
575600-0301	LH MOBILE SHROUD ASSY									Component ATA:57
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of:
11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
575600-0302	RH MOBILE SHROUD ASSY									Component ATA:57
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: NDT GENERIC										
576600-0101	LHUP SHROUD ASSY									Component ATA:57
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: NDT GENERIC										
576600-0102	RHUP SHROUD ASSY									Component ATA:57
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: NDT GENERIC										
576600-0201	LH WING FIXED SHROUD ASSY									Component ATA:57
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: NDT GENERIC										
576600-0202	RH WING FIXED SHROUD ASSY									Component ATA:57
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: NDT GENERIC										
576602-0101	LH WING SHROUD ASSY									Component ATA:57
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: NDT GENERIC										
576602-0102	RH WING SHROUD ASSY									Component ATA:57
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: NDT GENERIC										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
576604-0101	LH WING FIXED SHROUD ASSY									Component ATA:57
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: NDT GENERIC										
576604-0102	RH WING FIXED SHROUD ASSY									Component ATA:57
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: NDT GENERIC										
ATA 71 - POWER PLANT										
71-10-00-211-001-A00 ^S	VISUALLY CHECK COWLINGSEALS									Service ATA:71
	MOS	29-Jun-23	48 (+15d/-15d)	LOW UTILIZATION						
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
PROC. REF: AMM 71-10-00										
71-10-00-220-001-A00 ^S	INSPECT (DETAILED INSPECTION) COWLING INBOARD/ OUTBOARD ATTACHMENT AND SURROUNDING STRUCTURE									Service ATA:71
	MOS	29-Jun-23	48 (+15d/-15d)	LOW UTILIZATION						
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
PROC. REF: AMM 71-10-00										
71-20-00-220-001-A00 ^S	INSPECT (DETAILED INSPECTION) ENGINE MOUNTING ASSY									Service ATA:71
	MOS	29-Jun-23	48 (+15d/-15d)	LOW UTILIZATION						
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
PROC. REF: AMM 71-20-00										
71-60-01-211-001-A00 ^S	VISUALLY CHECK AIR INTAKEATTACHMENT									Service ATA:71
	MOS	29-Jun-23	48 (+15d/-15d)	LOW UTILIZATION						
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
PROC. REF: AMM 71-60-01										
71-60-01-211-002-A00 ^S	VISUALLY CHECK AIR INTAKE REAR BULKHEAD AND FIRE SHIELD									Service ATA:71
	MOS	29-Jun-23	48 (+15d/-15d)	LOW UTILIZATION						
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
PROC. REF: AMM 71-60-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 71 - POWER PLANT										
71-Z411-213-001-A00 ^S	GENERAL VISUAL INSPECTION(EXTERNAL) (ZONES 411, 412, 413, 421, 422, 423)									Service ATA:71
	MOS	29-Jun-23	24 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	1000 (+20/-20)							
	AFL	5401								
PROC. REF: AMM 05-20-70										PKG:5004
71-Z411-214-001-A00 ^S	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 411, 412, 413, 421, 422, 423 AND 425) (L600 ONLY)									Service ATA:71
	MOS	29-Jun-23	24 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	1000 (+20/-20)							
	AFL	5401								
PROC. REF: AMM 05-20-70										PKG:5004
71-Z411-214-001-A01	GENERAL VISUAL INSPECTION(INTERNAL) (ZONES 411, 412, 413, 415, 421, 422, 423 AND 425)NOTE:EWIS (L650 ONLY)									Service ATA:71
	MOS/MSC	25-Sep-07	N/A					ZONAL		
	HRS	0								
	AFL	0								
PROC. REF: AMM 05-20-70										
711000-0101	LEFT UP COWLING -NACELLE ASSEMBLY									Component ATA:71
PN:145-76830-401	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:1028	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-11-01										
711000-0102	RIGHT UP COWLING -NACELLE ASSEMBLY									Component ATA:71
PN:145-76830-402	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:1031	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-11-01										
711000-0103	LEFT LW ENGINE COWLING ASSEMBLY									Component ATA:71
PN:135-04972-405	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:0000137717	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-12-01										
711000-0104	RIGHT LW ENGINE COWLING ASSEMBLY									Component ATA:71
PN:135-04974-405	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:0000137712	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-12-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 71 - POWER PLANT										
711000-0201 LH ENG STRUCTURE -APRON, COWLING ASSEMBLY Component ATA:71										
PN:145-77030-401	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:1017	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-13-01										
711000-0202 RH ENG STRUCTURE -APRON, COWLING ASSEMBLY Component ATA:71										
PN:145-77030-402	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:1013	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-13-01										
711000-0301 LHLW COWLING ASSEMBLY Component ATA:71										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-12-01										
711000-0302 RHLW COWLING ASSEMBLY Component ATA:71										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-12-01										
712000-0201 LH ENG AFT SHOCKMOUNT ASSEMBLY Component ATA:71										
PN:LM-223-SA7	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										
712000-0202 RH ENG AFT SHOCKMOUNT ASSEMBLY Component ATA:71										
PN:LM-223-SA7	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										
712000-0203 LH ENG AFT SHOCKMOUNT ASSEMBLY Component ATA:71										
PN:LM-223-SA7	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 71 - POWER PLANT											
712000-0204		RH ENG AFT SHOCKMOUNT ASSEMBLY								Component	ATA:71
PN:LM-223-SA7	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 71-20-00											
712000-0301		LH ENG FORWARD FLUIDLASTIC NL TUN ISOLATOR								Component	ATA:71
PN:LM-223-SA5-1	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: NDT GENERIC											
712000-0302		RH ENG FORWARD FLUIDLASTIC NL TUN ISOLATOR								Component	ATA:71
PN:LM-223-SA5-1	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: NDT GENERIC											
712000-0303		LH ENG FORWARD FLUIDLASTIC NL TUN ISOLATOR								Component	ATA:71
PN:LM-223-SA5-1	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: NDT GENERIC											
712000-0304		RH ENG FORWARD FLUIDLASTIC NL TUN ISOLATOR								Component	ATA:71
PN:LM-223-SA5-1	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: NDT GENERIC											
716000-0101		LH ENGINE AIR INLET MODULE								Component	ATA:71
PN:135-04892-407	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:NC2048	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 71-60-01											
716000-0102		RH ENGINE AIR INLET MODULE								Component	ATA:71
PN:135-04892-407	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:NC2050	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 71-60-01											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 71 - POWER PLANT											
71EN1		NO. 1 ENGINE								Component	ATA:71
PN:23074862	MOS/MSC	30-Aug-11	E/C								
SN:CAE312988	HRS	4825.2			TSN 4721, TSR 0						
WC#: 71.EN1	AFL	2549			TSN 2477, TSR 0						
PROC. REF: AMM 71-00-00											
71EN2		NO. 2 ENGINE								Component	ATA:71
PN:23074862	MOS/MSC	30-Aug-11	E/C								
SN:CAE312989	HRS	4825.2			TSN 4721, TSR 0						
WC#: 71.EN2	AFL	2549			TSN 2477, TSR 0						
PROC. REF: AMM 71-00-00											
ATA 72 - ENGINE											
72-00-00-970-001-A00		NO. 1 ENGINE - ENGINE TREND DOWNLOAD/ANALYSIS								Service	ATA:72
	MOS/MSC	15-Oct-24	N/A								
	HRS	10473.9									
	ENC	5562									
PROC. REF: MM NO REF, AMM 72-00-00											
72-00-00-970-001-A00		NO. 2 ENGINE - ENGINE TREND DOWNLOAD/ANALYSIS								Service	ATA:72
	MOS/MSC	15-Oct-24	N/A								
	HRS	10473.9									
	ENC	5562									
PROC. REF: MM NO REF, AMM 72-00-00											
72-00-CUS-0701^U		NO. 1 ENGINE - PERFORM ENGINE RUN								Service	ATA:72
	DAYS/MSC	23-Apr-20	A/R								
	HRS	9252									
	ENC	4912									
72-00-CUS-0701^U		NO. 2 ENGINE - PERFORM ENGINE RUN								Service	ATA:72
	DAYS/MSC	23-Apr-20	A/R								
	HRS	9252									
	ENC	4912									
72-20-00-212-001-A00		INSPECT (GENERAL VISUAL) ENGINE AIR INTAKE								Service	ATA:72
	MOS	16-Aug-24						SYSTEM			
	HRS	10541.4	500		11041.4		445.8				
	AFL	5613									
PROC. REF: AMM 72-25-02											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
72-20-00-212-001-A00 NO. 1 ENGINE - INSPECT (GENERAL VISUAL) ENGINE AIR INTAKE Service ATA:72										
	MOS		16-Aug-24					SYSTEM		
	HRS		10437.2	500	(10937.2) 11041.4		445.8			
	ENC		5541							
PROC. REF: AMM 72-25-02, MM 72-00-00										
72-20-00-212-001-A00 NO. 2 ENGINE - INSPECT (GENERAL VISUAL) ENGINE AIR INTAKE Service ATA:72										
	MOS		16-Aug-24					SYSTEM		
	HRS		10437.2	500	(10937.2) 11041.4		445.8			
	ENC		5541							
PROC. REF: AMM 72-25-02, MM 72-00-00										
72-21-01-220-001-A00 NO. 1 ENGINE - INSPECT (DETAILED INSPECTION) FAN BLADES Service ATA:72										
	MOS		17-Jan-17					SYSTEM		
	HRS		7935.4	4000	(11935.4) 12039.6		1444			
	ENC		4242							
PROC. REF: AMM 72-21-01, MM 72-21-15										
72-21-01-220-001-A00 NO. 2 ENGINE - INSPECT (DETAILED INSPECTION) FAN BLADES Service ATA:72										
	MOS		17-Jan-17					SYSTEM		
	HRS		7935.4	4000	(11935.4) 12039.6		1444			
	ENC		4242							
PROC. REF: AMM 72-21-01, MM 72-21-15										
72-21-20-220-002-A00 NO. 1 ENGINE - INSPECT (DETAILED INSPECTION) FAN SPINNER P/N 23054034, 23064250 OR 23065046 ONLY Service ATA:72										
PN:23087826	MOS/MSC		19-Aug-15	N/A						
SN:FF378408	HRS		7356.1							
	ENC		3920							
PROC. REF: MM NO REF, AMM 72-31-01										
72-21-20-220-002-A00 NO. 2 ENGINE - INSPECT (DETAILED INSPECTION) FAN SPINNER P/N 23054034, 23064250 OR 23065046 ONLY Service ATA:72										
PN:23087826	MOS/MSC		06-Jul-15	N/A						
SN:FF378411	HRS		7356.1							
	ENC		3920							
PROC. REF: MM NO REF, AMM 72-31-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
72-62-01-212-001-A00	NO. 1 ENGINE - INSPECT (GENERAL VISUAL) GEARBOX RETENTION CABLES									Service ATA:72
	MOS/MSC	25-Sep-07	N/A							
	HRS	0								
	ENC	0								
PROC. REF: AMM 72-63-03, MM 72-63-10										
72-62-01-212-001-A00	NO. 2 ENGINE - INSPECT (GENERAL VISUAL) GEARBOX RETENTION CABLES									Service ATA:72
	MOS/MSC	25-Sep-07	N/A							
	HRS	0								
	ENC	0								
PROC. REF: AMM 72-63-03, MM 72-63-10										
72-63-01-710-001-A00	NO. 1 ENGINE - OPERATIONALLY CHECK STARTER DRAIN ADAPTER POST-MOD. SB AE3007A-72-253 AND PRE-MOD SB AE3007A-72-330.									Service ATA:72
	MOS/MSC	25-Sep-07	N/A					SYSTEM		
	HRS	0								
	ENC	0								
PROC. REF: AMM 72-63-02, MM 72-63-10										
72-63-01-710-001-A00	NO. 2 ENGINE - OPERATIONALLY CHECK STARTER DRAIN ADAPTER POST-MOD. SB AE3007A-72-253 AND PRE-MOD SB AE3007A-72-330.									Service ATA:72
	MOS/MSC	25-Sep-07	N/A					SYSTEM		
	HRS	0								
	ENC	0								
PROC. REF: AMM 72-63-02, MM 72-63-10										
720000-0101	RH ENG TURBOFAN,WT/FADEC,WT/SENSOR UNIT									Component ATA:72
PN:PN	MOS/MSC	27-Aug-07	O/C		TSN 0					
SN:UNKNOWN	HRS	0			TSN 0					
	AFL	0			TSN 0					
PROC. REF: AMM 73-22-01										
720000-0102	LH ENG TURBOFAN,WT/FADEC,WT/SENSOR UNIT									Component ATA:72
PN:PN	MOS/MSC	27-Aug-07	O/C		TSN 0					
SN:UNKNOWN	HRS	0			TSN 0					
	AFL	0			TSN 0					
PROC. REF: AMM 73-22-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
720000-0103		NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF ACCESSORY DRIVES SECTION(MPG EQUIVALENT TASKS 71-Z411-214-001-A00 AND 71-Z411-214-001-A01)							Service	ATA:72
	MOS	14-Jul-22								
	HRS	9811.6	10000		(19811.6) 19915.8		9320.2			
	ENC	5199								
PROC. REF: MM 72-00-00										
720000-0103		NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF ACCESSORY DRIVES SECTION(MPG EQUIVALENT TASKS 71-Z411-214-001-A00 AND 71-Z411-214-001-A01)							Service	ATA:72
	MOS	14-Jul-22								
	HRS	9811.6	10000		(19811.6) 19915.8		9320.2			
	ENC	5199								
PROC. REF: MM 72-00-00										
720000-0104		NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF BYPASS SECTION (MPG EQUIVALENT TASKS 71-Z411-214-001-A00 AND 71-Z411-214-001-A01)							Service	ATA:72
	MOS	14-Jul-22								
	HRS	9811.6	10000		(19811.6) 19915.8		9320.2			
	ENC	5199								
PROC. REF: MM 72-00-00										
720000-0104		NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF BYPASS SECTION (MPG EQUIVALENT TASKS 71-Z411-214-001-A00 AND 71-Z411-214-001-A01)							Service	ATA:72
	MOS	14-Jul-22								
	HRS	9811.6	10000		(19811.6) 19915.8		9320.2			
	ENC	5199								
PROC. REF: MM 72-00-00										
720000-0106		NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF FUEL SYSTEM DISTRIBUTION (TUBES AND HOSES) (MPG EQUIVALENT TASKS 71-Z411-214-001-A00 AND 71-Z411-214-001-A01)							Service	ATA:72
	MOS	14-Jul-22								
	HRS	9811.6	10000		(19811.6) 19915.8		9320.2			
	ENC	5199								
PROC. REF: MM 72-00-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
720000-0106		NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF FUEL SYSTEM DISTRIBUTION (TUBES AND HOSES) (MPG EQUIVALENT TASKS 71-Z411-214-001-A00 AND 71-Z411-214-001-A01)							Service	ATA:72
	MOS	14-Jul-22								
	HRS	9811.6	10000		(19811.6) 19915.8		9320.2			
	ENC	5199								
PROC. REF: MM 72-00-00										
720000-0108		NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF POWER CONTROL SECTION (HARNESSES) (MPG EQUIVALENT TASKS 71-Z411-214-001-A00 AND 71-Z411-214-001-A01)							Service	ATA:72
	MOS	14-Jul-22								
	HRS	9811.6	10000		(19811.6) 19915.8		9320.2			
	ENC	5199								
PROC. REF: MM 72-00-00										
720000-0108		NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF POWER CONTROL SECTION (HARNESSES) (MPG EQUIVALENT TASKS 71-Z411-214-001-A00 AND 71-Z411-214-001-A01)							Service	ATA:72
	MOS	14-Jul-22								
	HRS	9811.6	10000		(19811.6) 19915.8		9320.2			
	ENC	5199								
PROC. REF: MM 72-00-00										
720000-0109		NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF TURBINE-INTERSTAGE THERMOCOUPLE (A) HARNESS (MPG EQUIVALENT TASKS 71-Z411-214-001-A00 AND 71-Z411-214-001-A01)							Service	ATA:72
	MOS	14-Jul-22								
	HRS	9811.6	10000		(19811.6) 19915.8		9320.2			
	ENC	5199								
PROC. REF: MM 72-00-00										
720000-0109		NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF TURBINE-INTERSTAGE THERMOCOUPLE (A) HARNESS (MPG EQUIVALENT TASKS 71-Z411-214-001-A00 AND 71-Z411-214-001-A01)							Service	ATA:72
	MOS	14-Jul-22								
	HRS	9811.6	10000		(19811.6) 19915.8		9320.2			
	ENC	5199								
PROC. REF: MM 72-00-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
720000-0110		NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF TURBINE-INTERSTAGE THERMOCOUPLE (B) HARNESS (MPG EQUIVALENT TASKS 71-Z411-214-001-A00 AND 71-Z411-214-001-A01)							Service	ATA:72
	MOS	14-Jul-22								
	HRS	9811.6	10000		(19811.6) 19915.8		9320.2			
	ENC	5199								
PROC. REF: MM 72-00-00										
720000-0110		NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF TURBINE-INTERSTAGE THERMOCOUPLE (B) HARNESS (MPG EQUIVALENT TASKS 71-Z411-214-001-A00 AND 71-Z411-214-001-A01)							Service	ATA:72
	MOS	14-Jul-22								
	HRS	9811.6	10000		(19811.6) 19915.8		9320.2			
	ENC	5199								
PROC. REF: MM 72-00-00										
720000-0111		NO. 1 ENGINE - PERFORM SPECIAL PROCEDURES ON THE ENGINE							Service	ATA:72
	MOS/MSC	25-Sep-07	N/A							
	HRS	0								
	ENC	0								
PROC. REF: GENERIC NO REF										
720000-0111		NO. 2 ENGINE - PERFORM SPECIAL PROCEDURES ON THE ENGINE							Service	ATA:72
	MOS/MSC	25-Sep-07	N/A							
	HRS	0								
	ENC	0								
PROC. REF: GENERIC NO REF										
720010-0101		NO. 1 ENGINE - MANIFOLD ASSEMBLY							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C		TSN 0					
SN:UNKNOWN	HRS	0			TSN 0					
	ENC	0			TSN 0					
PROC. REF: AMM 73-13-02, MM 73-13-10, MM 73-13-10, MM 73-13-10, MM 73-13-10, MM 73-13-10, MM 73-13-10, MM 73-13-10, MM 73-13-10, MM 73-13-10										
720010-0101		NO. 2 ENGINE - MANIFOLD ASSEMBLY							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C		TSN 0					
SN:UNKNOWN	HRS	0			TSN 0					
	ENC	0			TSN 0					
PROC. REF: AMM 73-13-02, MM 73-13-10, MM 73-13-10, MM 73-13-10, MM 73-13-10, MM 73-13-10, MM 73-13-10, MM 73-13-10, MM 73-13-10, MM 73-13-10										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
720038-0101			NO. 1 ENGINE - ACCESSORY DRIVE GEARBOX MODULE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 72-63-10, MM 72-63-10										
720038-0101			NO. 2 ENGINE - ACCESSORY DRIVE GEARBOX MODULE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 72-63-10, MM 72-63-10										
720039-0101			NO. 1 ENGINE - ACCESSORY DRIVE GEARBOX						Component	ATA:72
PN:23079389	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:2869	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 72-61-01, MM 72-63-10, MM 72-63-10										
720039-0101			NO. 2 ENGINE - ACCESSORY DRIVE GEARBOX						Component	ATA:72
PN:23079389	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:2468	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 72-61-01, MM 72-63-10, MM 72-63-10										
721000-0101			NO. 1 ENGINE - FAN ROTOR ASSEMBLY						Component	ATA:72
PN:23075474	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:MW50802	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
721000-0101			NO. 2 ENGINE - FAN ROTOR ASSEMBLY						Component	ATA:72
PN:23075474	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:MW50853	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
721003-0101			NO. 1 ENGINE - INSPECT ENGINE AT 100 CYCLES						Service	ATA:72
	MOS/MSC	25-Sep-07	A/R							
	HRS	0								
	ENC	0								
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 72 - ENGINE											
721003-0101			NO. 2 ENGINE - INSPECT ENGINE AT 100 CYCLES								Service ATA:72
	MOS/MSC	25-Sep-07	A/R								
	HRS	0									
	ENC	0									
PROC. REF: GENERIC NO REF											
722100-0101			NO. 1 ENGINE - FAN WHEEL								Component ATA:72
PN:23058865	MOS	25-Sep-07		TSN 0				LIFE LIMIT			
SN:MW50802	HRS	0		TSN 0							
	ENC	0	20000	TSN 0	(20000) 20072		14423				
PROC. REF: MM 72-21-10, MM 72-21-10, BULLETINS											
722100-0101			NO. 2 ENGINE - FAN WHEEL								Component ATA:72
PN:23058865	MOS	25-Sep-07		TSN 0				LIFE LIMIT			
SN:MW50853	HRS	0		TSN 0							
	ENC	0	20000	TSN 0	(20000) 20072		14423				
PROC. REF: MM 72-21-10, MM 72-21-10, BULLETINS											
722100-0102			NO. 1 ENGINE - FAN DRIVE SHAFT								Component ATA:72
PN:23074382	MOS	25-Sep-07		TSN 0				LIFE LIMIT			
SN:GV246257	HRS	0		TSN 0							
	ENC	0	20000	TSN 0	(20000) 20072		14423				
PROC. REF: MM 72-25-40, MM 72-25-40											
722100-0102			NO. 2 ENGINE - FAN DRIVE SHAFT								Component ATA:72
PN:23074382	MOS	25-Sep-07		TSN 0				LIFE LIMIT			
SN:GV246248	HRS	0		TSN 0							
	ENC	0	20000	TSN 0	(20000) 20072		14423				
PROC. REF: MM 72-25-40, MM 72-25-40											
722101-0101			NO. 1 ENGINE - FORWARD FAN BLADE RETAINER								Component ATA:72
PN:23062491	MOS	25-Sep-07		TSN 0				LIFE LIMIT			
SN:HK120747	HRS	0		TSN 0							
	ENC	0	20000	TSN 0	(20000) 20072		14423				
PROC. REF: MM 72-21-30, MM 72-21-30											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of:
11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
722101-0101 NO. 2 ENGINE - FORWARD FAN BLADE RETAINER Component ATA:72										
PN:23062491	MOS		25-Sep-07	TSN 0				LIFE LIMIT		
SN:HK120751	HRS		0	TSN 0						
	ENC		0	20000	TSN 0	(20000) 20072	14423			
PROC. REF: MM 72-21-30, MM 72-21-30										
722102-0101 NO. 1 ENGINE - FAN SUPPORT BEARING HOUSING ASSEMBLY Component ATA:72										
PN:PN	MOS/MSC		25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS		0	TSN 0						
	ENC		0	TSN 0						
PROC. REF: GENERIC NO REF										
722102-0101 NO. 2 ENGINE - FAN SUPPORT BEARING HOUSING ASSEMBLY Component ATA:72										
PN:PN	MOS/MSC		25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS		0	TSN 0						
	ENC		0	TSN 0						
PROC. REF: GENERIC NO REF										
722103-0101 NO. 1 ENGINE - CLEAN AND DO THE DETAILED INSPECTION OF THE FAN BLADES Service ATA:72										
	MOS/MSC		25-Sep-07	N/A						
	HRS		0							
	ENC		0							
PROC. REF: MM NO REF, AMM 72-21-01										
722103-0101 NO. 2 ENGINE - CLEAN AND DO THE DETAILED INSPECTION OF THE FAN BLADES Service ATA:72										
	MOS/MSC		25-Sep-07	N/A						
	HRS		0							
	ENC		0							
PROC. REF: MM NO REF, AMM 72-21-01										
722104-0101 NO. 1 ENGINE - FAN SPINNER ASSEMBLY Component ATA:72										
PN:23087826	MOS/MSC		08-Sep-10	O/C	TSN 0					
SN:FF378408	HRS		3738.1	TSN 0						
	ENC		1964	TSN 0						
PROC. REF: AMM 72-31-01, MM 72-21-20, MM 72-21-20										
722104-0101 NO. 2 ENGINE - FAN SPINNER ASSEMBLY Component ATA:72										
PN:23087826	MOS/MSC		09-Sep-10	O/C	TSN 0					
SN:FF378411	HRS		3738.1	TSN 0						
	ENC		1964	TSN 0						
PROC. REF: AMM 72-31-01, MM 72-21-20, MM 72-21-20										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
722105-0101 NO. 1 ENGINE - FRONT FRAME ASSEMBLY Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
722105-0101 NO. 2 ENGINE - FRONT FRAME ASSEMBLY Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
722107-0101 NO. 1 ENGINE - FAN CASE ASSEMBLY Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 72-25-30, MM 72-25-30										
722107-0101 NO. 2 ENGINE - FAN CASE ASSEMBLY Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 72-25-30, MM 72-25-30										
722108-0101 NO. 1 ENGINE - NO. 1 FAN BYPASS VANE Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 72-25-10, MM 72-25-10										
722108-0101 NO. 2 ENGINE - NO. 1 FAN BYPASS VANE Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 72-25-10, MM 72-25-10										
722108-0102 NO. 1 ENGINE - NO. 2 FAN BYPASS VANE Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 72-25-10, MM 72-25-10										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
722108-0102	NO. 2 ENGINE - NO. 2 FAN BYPASS VANE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: MM 72-25-10, MM 72-25-10										
722108-0103	NO. 1 ENGINE - NO. 3 FAN BYPASS VANE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: MM 72-25-10, MM 72-25-10										
722108-0103	NO. 2 ENGINE - NO. 3 FAN BYPASS VANE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: MM 72-25-10, MM 72-25-10										
722108-0104	NO. 1 ENGINE - NO. 4 FAN BYPASS VANE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: MM 72-25-10, MM 72-25-10										
722108-0104	NO. 2 ENGINE - NO. 4 FAN BYPASS VANE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: MM 72-25-10, MM 72-25-10										
722108-0105	NO. 1 ENGINE - NO. 5 FAN BYPASS VANE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: MM 72-25-10, MM 72-25-10										
722108-0105	NO. 2 ENGINE - NO. 5 FAN BYPASS VANE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: MM 72-25-10, MM 72-25-10										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
722108-0106 NO. 1 ENGINE - NO. 6 FAN BYPASS VANE Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 72-25-10, MM 72-25-10										
722108-0106 NO. 2 ENGINE - NO. 6 FAN BYPASS VANE Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 72-25-10, MM 72-25-10										
722108-0107 NO. 1 ENGINE - NO. 7 FAN BYPASS VANE Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 72-25-10, MM 72-25-10										
722108-0107 NO. 2 ENGINE - NO. 7 FAN BYPASS VANE Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 72-25-10, MM 72-25-10										
722108-0108 NO. 1 ENGINE - NO. 8 FAN BYPASS VANE Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 72-25-10, MM 72-25-10										
722108-0108 NO. 2 ENGINE - NO. 8 FAN BYPASS VANE Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 72-25-10, MM 72-25-10										
722108-0109 NO. 1 ENGINE - NO. 9 FAN BYPASS VANE Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 72-25-10, MM 72-25-10										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
722108-0109	NO. 2 ENGINE - NO. 9 FAN BYPASS VANE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: MM 72-25-10, MM 72-25-10										
722108-0110	NO. 1 ENGINE - NO. 10 FAN BYPASS VANE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: MM 72-25-10, MM 72-25-10										
722108-0110	NO. 2 ENGINE - NO. 10 FAN BYPASS VANE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: MM 72-25-10, MM 72-25-10										
722108-0111	NO. 1 ENGINE - NO. 11 FAN BYPASS VANE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: MM 72-25-10, MM 72-25-10										
722108-0111	NO. 2 ENGINE - NO. 11 FAN BYPASS VANE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: MM 72-25-10, MM 72-25-10										
722108-0112	NO. 1 ENGINE - NO. 12 FAN BYPASS VANE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: MM 72-25-10, MM 72-25-10										
722108-0112	NO. 2 ENGINE - NO. 12 FAN BYPASS VANE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: MM 72-25-10, MM 72-25-10										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
722108-0113 NO. 1 ENGINE - NO. 13 FAN BYPASS VANE Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 72-25-10, MM 72-25-10										
722108-0113 NO. 2 ENGINE - NO. 13 FAN BYPASS VANE Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 72-25-10, MM 72-25-10										
722108-0114 NO. 1 ENGINE - NO. 14 FAN BYPASS VANE Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 72-25-10, MM 72-25-10										
722108-0114 NO. 2 ENGINE - NO. 14 FAN BYPASS VANE Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 72-25-10, MM 72-25-10										
722108-0115 NO. 1 ENGINE - NO. 15 FAN BYPASS VANE Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 72-25-10, MM 72-25-10										
722108-0115 NO. 2 ENGINE - NO. 15 FAN BYPASS VANE Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 72-25-10, MM 72-25-10										
722108-0116 NO. 1 ENGINE - NO. 16 FAN BYPASS VANE Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 72-25-10, MM 72-25-10										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
722108-0116	NO. 2 ENGINE - NO. 16 FAN BYPASS VANE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: MM 72-25-10, MM 72-25-10										
722108-0117	NO. 1 ENGINE - NO. 17 FAN BYPASS VANE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: MM 72-25-10, MM 72-25-10										
722108-0117	NO. 2 ENGINE - NO. 17 FAN BYPASS VANE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: MM 72-25-10, MM 72-25-10										
722108-0118	NO. 1 ENGINE - NO. 18 FAN BYPASS VANE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: MM 72-25-10, MM 72-25-10										
722108-0118	NO. 2 ENGINE - NO. 18 FAN BYPASS VANE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: MM 72-25-10, MM 72-25-10										
722108-0119	NO. 1 ENGINE - NO. 19 FAN BYPASS VANE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: MM 72-25-10, MM 72-25-10										
722108-0119	NO. 2 ENGINE - NO. 19 FAN BYPASS VANE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: MM 72-25-10, MM 72-25-10										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
722108-0120 NO. 1 ENGINE - NO. 20 FAN BYPASS VANE Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 72-25-10, MM 72-25-10										
722108-0120 NO. 2 ENGINE - NO. 20 FAN BYPASS VANE Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 72-25-10, MM 72-25-10										
722108-0121 NO. 1 ENGINE - NO. 21 FAN BYPASS VANE Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 72-25-10, MM 72-25-10										
722108-0121 NO. 2 ENGINE - NO. 21 FAN BYPASS VANE Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 72-25-10, MM 72-25-10										
722108-0122 NO. 1 ENGINE - NO. 22 FAN BYPASS VANE Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 72-25-10, MM 72-25-10										
722108-0122 NO. 2 ENGINE - NO. 22 FAN BYPASS VANE Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 72-25-10, MM 72-25-10										
722108-0123 NO. 1 ENGINE - NO. 23 FAN BYPASS VANE Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 72-25-10, MM 72-25-10										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
722108-0123	NO. 2 ENGINE - NO. 23 FAN BYPASS VANE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 72-25-10, MM 72-25-10										
722108-0124	NO. 1 ENGINE - NO. 24 FAN BYPASS VANE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 72-25-10, MM 72-25-10										
722108-0124	NO. 2 ENGINE - NO. 24 FAN BYPASS VANE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 72-25-10, MM 72-25-10										
722108-0125	NO. 1 ENGINE - NO. 25 FAN BYPASS VANE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 72-25-10, MM 72-25-10										
722108-0125	NO. 2 ENGINE - NO. 25 FAN BYPASS VANE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 72-25-10, MM 72-25-10										
722108-0126	NO. 1 ENGINE - NO. 26 FAN BYPASS VANE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 72-25-10, MM 72-25-10										
722108-0126	NO. 2 ENGINE - NO. 26 FAN BYPASS VANE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 72-25-10, MM 72-25-10										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
722108-0127 NO. 1 ENGINE - NO. 27 FAN BYPASS VANE Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 72-25-10, MM 72-25-10										
722108-0127 NO. 2 ENGINE - NO. 27 FAN BYPASS VANE Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 72-25-10, MM 72-25-10										
722108-0128 NO. 1 ENGINE - NO. 28 FAN BYPASS VANE Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 72-25-10, MM 72-25-10										
722108-0128 NO. 2 ENGINE - NO. 28 FAN BYPASS VANE Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 72-25-10, MM 72-25-10										
722108-0129 NO. 1 ENGINE - NO. 29 FAN BYPASS VANE Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 72-25-10, MM 72-25-10										
722108-0129 NO. 2 ENGINE - NO. 29 FAN BYPASS VANE Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 72-25-10, MM 72-25-10										
722108-0130 NO. 1 ENGINE - NO. 30 FAN BYPASS VANE Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 72-25-10, MM 72-25-10										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
722108-0130	NO. 2 ENGINE - NO. 30 FAN BYPASS VANE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 72-25-10, MM 72-25-10										
722109-0101	NO. 1 ENGINE - SEG CARBON FAN SEAL ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
722109-0101	NO. 2 ENGINE - SEG CARBON FAN SEAL ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
722111-0101	NO. 1 ENGINE - SPANNER NUT									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 72-21-05, MM 72-21-05										
722111-0101	NO. 2 ENGINE - SPANNER NUT									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 72-21-05, MM 72-21-05										
722112-0101	NO. 1 ENGINE - BEARING SELF-LOCKING NUT									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
722112-0101	NO. 2 ENGINE - BEARING SELF-LOCKING NUT									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 72 - ENGINE											
722113-0101		NO. 1 ENGINE - ROLLER BEARING								Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: GENERIC NO REF											
722113-0101		NO. 2 ENGINE - ROLLER BEARING								Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: GENERIC NO REF											
722114-0101		NO. 1 ENGINE - NO. 1 FAN BLADE								Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15											
722114-0101		NO. 2 ENGINE - NO. 1 FAN BLADE								Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15											
722114-0102		NO. 1 ENGINE - NO. 2 FAN BLADE								Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15											
722114-0102		NO. 2 ENGINE - NO. 2 FAN BLADE								Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15											
722114-0103		NO. 1 ENGINE - NO. 3 FAN BLADE								Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 72 - ENGINE											
722114-0103		NO. 2 ENGINE - NO. 3 FAN BLADE								Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15											
722114-0104		NO. 1 ENGINE - NO. 4 FAN BLADE								Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15											
722114-0104		NO. 2 ENGINE - NO. 4 FAN BLADE								Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15											
722114-0105		NO. 1 ENGINE - NO. 5 FAN BLADE								Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15											
722114-0105		NO. 2 ENGINE - NO. 5 FAN BLADE								Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15											
722114-0106		NO. 1 ENGINE - NO. 6 FAN BLADE								Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15											
722114-0106		NO. 2 ENGINE - NO. 6 FAN BLADE								Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
722114-0107 NO. 1 ENGINE - NO. 7 FAN BLADE Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15										
722114-0107 NO. 2 ENGINE - NO. 7 FAN BLADE Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15										
722114-0108 NO. 1 ENGINE - NO. 8 FAN BLADE Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15										
722114-0108 NO. 2 ENGINE - NO. 8 FAN BLADE Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15										
722114-0109 NO. 1 ENGINE - NO. 9 FAN BLADE Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15										
722114-0109 NO. 2 ENGINE - NO. 9 FAN BLADE Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15										
722114-0110 NO. 1 ENGINE - NO. 10 FAN BLADE Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
722114-0110	NO. 2 ENGINE - NO. 10 FAN BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15										
722114-0111	NO. 1 ENGINE - NO. 11 FAN BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15										
722114-0111	NO. 2 ENGINE - NO. 11 FAN BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15										
722114-0112	NO. 1 ENGINE - NO. 12 FAN BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15										
722114-0112	NO. 2 ENGINE - NO. 12 FAN BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15										
722114-0113	NO. 1 ENGINE - NO. 13 FAN BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: MM 72-21-15, MM 72-21-15										
722114-0113	NO. 2 ENGINE - NO. 13 FAN BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: MM 72-21-15, MM 72-21-15										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
722114-0114	NO. 1 ENGINE - NO. 14 FAN BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: MM 72-21-15, MM 72-21-15										
722114-0114	NO. 2 ENGINE - NO. 14 FAN BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: MM 72-21-15, MM 72-21-15										
722114-0115	NO. 1 ENGINE - NO. 15 FAN BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: MM 72-21-15, MM 72-21-15										
722114-0115	NO. 2 ENGINE - NO. 15 FAN BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: MM 72-21-15, MM 72-21-15										
722114-0116	NO. 1 ENGINE - NO. 16 FAN BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15										
722114-0116	NO. 2 ENGINE - NO. 16 FAN BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15										
722114-0117	NO. 1 ENGINE - NO. 17 FAN BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
722114-0117	NO. 2 ENGINE - NO. 17 FAN BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15										
722114-0118	NO. 1 ENGINE - NO. 18 FAN BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15										
722114-0118	NO. 2 ENGINE - NO. 18 FAN BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15										
722114-0119	NO. 1 ENGINE - NO. 19 FAN BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15										
722114-0119	NO. 2 ENGINE - NO. 19 FAN BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15										
722114-0120	NO. 1 ENGINE - NO. 20 FAN BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15										
722114-0120	NO. 2 ENGINE - NO. 20 FAN BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
722114-0121 NO. 1 ENGINE - NO. 21 FAN BLADE Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15										
722114-0121 NO. 2 ENGINE - NO. 21 FAN BLADE Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15										
722114-0122 NO. 1 ENGINE - NO. 22 FAN BLADE Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15										
722114-0122 NO. 2 ENGINE - NO. 22 FAN BLADE Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15										
722114-0123 NO. 1 ENGINE - NO. 23 FAN BLADE Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15										
722114-0123 NO. 2 ENGINE - NO. 23 FAN BLADE Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15										
722114-0124 NO. 1 ENGINE - NO. 24 FAN BLADE Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
722114-0124	NO. 2 ENGINE - NO. 24 FAN BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: AMM 72-31-02, MM 72-21-15, MM 72-21-15										
722120-0101	NO. 1 ENGINE - DETAILED INSPECTION OF THE FAN SPINNER									Service ATA:72
	MOS/MSC	25-Sep-07	N/R							
	HRS	0								
	ENC	0								
PROC. REF: AMM 72-31-01, MM 72-21-20										
722120-0101	NO. 2 ENGINE - DETAILED INSPECTION OF THE FAN SPINNER									Service ATA:72
	MOS/MSC	25-Sep-07	N/R							
	HRS	0								
	ENC	0								
PROC. REF: AMM 72-31-01, MM 72-21-20										
722500-0101	NO. 1 ENGINE - BEVEL PINION - RADIAL DRIVE GEARSHAFT									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
722500-0101	NO. 2 ENGINE - BEVEL PINION - RADIAL DRIVE GEARSHAFT									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
722501-0101	NO. 1 ENGINE - FRONT SUMP BEVEL GEAR									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
722501-0101	NO. 2 ENGINE - FRONT SUMP BEVEL GEAR									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
722502-0101 NO. 1 ENGINE - FRONT SUMP HOUSING ASSEMBLY Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
722502-0101 NO. 2 ENGINE - FRONT SUMP HOUSING ASSEMBLY Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
722503-0101 NO. 1 ENGINE - MID-SPAN ROLLER BEARING Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 72-25-35, MM 72-25-35										
722503-0101 NO. 2 ENGINE - MID-SPAN ROLLER BEARING Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 72-25-35, MM 72-25-35										
722504-0101 NO. 1 ENGINE - HORIZONTAL QUILL SHAFT Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
722504-0101 NO. 2 ENGINE - HORIZONTAL QUILL SHAFT Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
722506-0101 NO. 1 ENGINE - NO. 4 CARBON-TANDEM SEAL ASSEMBLY Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
722506-0101	NO. 2 ENGINE - NO. 4 CARBON-TANDEM SEAL ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
722508-0101	NO. 1 ENGINE - 80 X 100 X 11 MM ROLLER BEARING									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
722508-0101	NO. 2 ENGINE - 80 X 100 X 11 MM ROLLER BEARING									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
722509-0101	NO. 1 ENGINE - 87 X 108 X 11 BALL BEARING									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
722509-0101	NO. 2 ENGINE - 87 X 108 X 11 BALL BEARING									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
722510-0101	NO. 1 ENGINE - FLANGED ROLLER BEARING									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
722510-0101	NO. 2 ENGINE - FLANGED ROLLER BEARING									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
722511-0101 NO. 1 ENGINE - ROLLER BEARING Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
722511-0101 NO. 2 ENGINE - ROLLER BEARING Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
722512-0101 NO. 1 ENGINE - RADIAL DRIVE GEARSHAFT ASSEMBLY Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
722512-0101 NO. 2 ENGINE - RADIAL DRIVE GEARSHAFT ASSEMBLY Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
722513-0101 NO. 1 ENGINE - CONRAD BEARING Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
722513-0101 NO. 2 ENGINE - CONRAD BEARING Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
722514-0101 NO. 1 ENGINE - NO. 1 POWER TURBINE (LPT) BALL BEARING Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
722514-0101	NO. 2 ENGINE - NO. 1 POWER TURBINE (LPT) BALL BEARING									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
723000-0101	NO. 1 ENGINE - COMPRESSOR ROTOR ASSEMBLY									Component ATA:72
PN:23075618	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:A21726	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
723000-0101	NO. 2 ENGINE - COMPRESSOR ROTOR ASSEMBLY									Component ATA:72
PN:23075618	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:A21727	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
723017-0101	NO. 1 ENGINE - COMP/TURBINE SHAFT									Component ATA:72
PN:23073165	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:L314125	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
723017-0101	NO. 2 ENGINE - COMP/TURBINE SHAFT									Component ATA:72
PN:23073165	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:L314133	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
723018-0101	NO. 1 ENGINE - COMPRESSOR STUB SHAFT									Component ATA:72
PN:23077677	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:GV256851	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
723018-0101	NO. 2 ENGINE - COMPRESSOR STUB SHAFT									Component ATA:72
PN:23077677	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:GV256859	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 72 - ENGINE											
723019-0101		NO. 1 ENGINE - COMPRESSOR TIE BOLT								Component	ATA:72
PN:23076018	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:L316484	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: GENERIC NO REF											
723019-0101		NO. 2 ENGINE - COMPRESSOR TIE BOLT								Component	ATA:72
PN:23076018	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:L316500	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: GENERIC NO REF											
723020-0101		NO. 1 ENGINE - 9TH STAGE COMPRESSOR CASE								Component	ATA:72
PN:23077726	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:JB42245	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: GENERIC NO REF											
723020-0101		NO. 2 ENGINE - 9TH STAGE COMPRESSOR CASE								Component	ATA:72
PN:23077726	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:JB42246	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: GENERIC NO REF											
723500-0101		NO. 1 ENGINE - 1ST STAGE COMPRESSOR WHEEL								Component	ATA:72
PN:23065041	MOS	25-Sep-07		TSN 0				LIFE LIMIT			
SN:L317342	HRS	0		TSN 0							
	ENC	0	20000	TSN 0	(20000) 20072		14423				
PROC. REF: GENERIC NO REF											
723500-0101		NO. 2 ENGINE - 1ST STAGE COMPRESSOR WHEEL								Component	ATA:72
PN:23065041	MOS	25-Sep-07		TSN 0				LIFE LIMIT			
SN:L317309	HRS	0		TSN 0							
	ENC	0	20000	TSN 0	(20000) 20072		14423				
PROC. REF: GENERIC NO REF											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
723500-0102	NO. 1 ENGINE - 2ND STAGE COMPRESSOR WHEEL									Component ATA:72
PN:23050752	MOS		25-Sep-07	TSN 0				LIFE LIMIT		
SN:L308271	HRS		0	TSN 0						
	ENC	0	15200	TSN 0	(15200) 15272		9623			
PROC. REF: GENERIC NO REF										
723500-0102	NO. 2 ENGINE - 2ND STAGE COMPRESSOR WHEEL									Component ATA:72
PN:23050752	MOS		25-Sep-07	TSN 0				LIFE LIMIT		
SN:L308272	HRS		0	TSN 0						
	ENC	0	15200	TSN 0	(15200) 15272		9623			
PROC. REF: GENERIC NO REF										
723500-0103	NO. 1 ENGINE - 3RD STAGE COMPRESSOR WHEEL									Component ATA:72
PN:23065303	MOS		25-Sep-07	TSN 0				LIFE LIMIT		
SN:L310095	HRS		0	TSN 0						
	ENC	0	13300	TSN 0	(13300) 13372		7723			
PROC. REF: GENERIC NO REF										
723500-0103	NO. 2 ENGINE - 3RD STAGE COMPRESSOR WHEEL									Component ATA:72
PN:23065303	MOS		25-Sep-07	TSN 0				LIFE LIMIT		
SN:L310107	HRS		0	TSN 0						
	ENC	0	13300	TSN 0	(13300) 13372		7723			
PROC. REF: GENERIC NO REF										
723500-0104	NO. 1 ENGINE - 4TH STAGE COMPRESSOR WHEEL									Component ATA:72
PN:23071259	MOS		25-Sep-07	TSN 0				LIFE LIMIT		
SN:L296792	HRS		0	TSN 0						
	ENC	0	20000	TSN 0	(20000) 20072		14423			
PROC. REF: GENERIC NO REF										
723500-0104	NO. 2 ENGINE - 4TH STAGE COMPRESSOR WHEEL									Component ATA:72
PN:23071259	MOS		25-Sep-07	TSN 0				LIFE LIMIT		
SN:L296731	HRS		0	TSN 0						
	ENC	0	20000	TSN 0	(20000) 20072		14423			
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
723500-0105 NO. 1 ENGINE - 5TH STAGE COMPRESSOR WHEEL Component ATA:72										
PN:23071260	MOS		25-Sep-07	TSN 0				LIFE LIMIT		
SN:L312877	HRS		0	TSN 0						
	ENC	0	20000	TSN 0	(20000) 20072		14423			
PROC. REF: GENERIC NO REF										
723500-0105 NO. 2 ENGINE - 5TH STAGE COMPRESSOR WHEEL Component ATA:72										
PN:23071260	MOS		25-Sep-07	TSN 0				LIFE LIMIT		
SN:L312854	HRS		0	TSN 0						
	ENC	0	20000	TSN 0	(20000) 20072		14423			
PROC. REF: GENERIC NO REF										
723500-0106 NO. 1 ENGINE - 6TH STAGE COMPRESSOR WHEEL Component ATA:72										
PN:23074717	MOS		25-Sep-07	TSN 0				LIFE LIMIT		
SN:L275159	HRS		0	TSN 0						
	ENC	0	20000	TSN 0	(20000) 20072		14423			
PROC. REF: GENERIC NO REF										
723500-0106 NO. 2 ENGINE - 6TH STAGE COMPRESSOR WHEEL Component ATA:72										
PN:23074717	MOS		25-Sep-07	TSN 0				LIFE LIMIT		
SN:L275144	HRS		0	TSN 0						
	ENC	0	20000	TSN 0	(20000) 20072		14423			
PROC. REF: GENERIC NO REF										
723500-0107 NO. 1 ENGINE - 7TH STAGE COMPRESSOR WHEEL Component ATA:72										
PN:23074217	MOS		25-Sep-07	TSN 0				LIFE LIMIT		
SN:L299189	HRS		0	TSN 0						
	ENC	0	20000	TSN 0	(20000) 20072		14423			
PROC. REF: GENERIC NO REF										
723500-0107 NO. 2 ENGINE - 7TH STAGE COMPRESSOR WHEEL Component ATA:72										
PN:23074217	MOS		25-Sep-07	TSN 0				LIFE LIMIT		
SN:L299210	HRS		0	TSN 0						
	ENC	0	20000	TSN 0	(20000) 20072		14423			
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
723500-0108 NO. 1 ENGINE - 8TH STAGE COMPRESSOR WHEEL Component ATA:72										
PN:23074721	MOS		25-Sep-07	TSN 0				LIFE LIMIT		
SN:L305178	HRS		0	TSN 0						
	ENC	0	20000	TSN 0	(20000) 20072		14423			
PROC. REF: GENERIC NO REF										
723500-0108 NO. 2 ENGINE - 8TH STAGE COMPRESSOR WHEEL Component ATA:72										
PN:23074721	MOS		25-Sep-07	TSN 0				LIFE LIMIT		
SN:L305092	HRS		0	TSN 0						
	ENC	0	20000	TSN 0	(20000) 20072		14423			
PROC. REF: GENERIC NO REF										
723500-0109 NO. 1 ENGINE - 9TH STAGE COMPRESSOR WHEEL Component ATA:72										
PN:23074722	MOS		25-Sep-07	TSN 0				LIFE LIMIT		
SN:L310539	HRS		0	TSN 0						
	ENC	0	20000	TSN 0	(20000) 20072		14423			
PROC. REF: GENERIC NO REF										
723500-0109 NO. 2 ENGINE - 9TH STAGE COMPRESSOR WHEEL Component ATA:72										
PN:23074722	MOS		25-Sep-07	TSN 0				LIFE LIMIT		
SN:L310527	HRS		0	TSN 0						
	ENC	0	20000	TSN 0	(20000) 20072		14423			
PROC. REF: GENERIC NO REF										
723500-0110 NO. 1 ENGINE - 10TH STAGE COMPRESSOR WHEEL Component ATA:72										
PN:23074723	MOS		25-Sep-07	TSN 0				LIFE LIMIT		
SN:L309565	HRS		0	TSN 0						
	ENC	0	20000	TSN 0	(20000) 20072		14423			
PROC. REF: GENERIC NO REF										
723500-0110 NO. 2 ENGINE - 10TH STAGE COMPRESSOR WHEEL Component ATA:72										
PN:23074723	MOS		25-Sep-07	TSN 0				LIFE LIMIT		
SN:L309575	HRS		0	TSN 0						
	ENC	0	20000	TSN 0	(20000) 20072		14423			
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
723500-0111 NO. 1 ENGINE - 11TH STAGE COMPRESSOR WHEEL Component ATA:72										
PN:23074724	MOS		25-Sep-07	TSN 0				LIFE LIMIT		
SN:L308976	HRS		0	TSN 0						
	ENC	0	20000	TSN 0	(20000) 20072		14423			
PROC. REF: GENERIC NO REF										
723500-0111 NO. 2 ENGINE - 11TH STAGE COMPRESSOR WHEEL Component ATA:72										
PN:23074724	MOS		25-Sep-07	TSN 0				LIFE LIMIT		
SN:L308972	HRS		0	TSN 0						
	ENC	0	20000	TSN 0	(20000) 20072		14423			
PROC. REF: GENERIC NO REF										
723500-0112 NO. 1 ENGINE - 12TH STAGE COMPRESSOR WHEEL Component ATA:72										
PN:23074725	MOS		25-Sep-07	TSN 0				LIFE LIMIT		
SN:L295437	HRS		0	TSN 0						
	ENC	0	20000	TSN 0	(20000) 20072		14423			
PROC. REF: GENERIC NO REF										
723500-0112 NO. 2 ENGINE - 12TH STAGE COMPRESSOR WHEEL Component ATA:72										
PN:23074725	MOS		25-Sep-07	TSN 0				LIFE LIMIT		
SN:L295434	HRS		0	TSN 0						
	ENC	0	20000	TSN 0	(20000) 20072		14423			
PROC. REF: GENERIC NO REF										
723500-0113 NO. 1 ENGINE - 13TH STAGE COMPRESSOR WHEEL Component ATA:72										
PN:23074213	MOS		25-Sep-07	TSN 0				LIFE LIMIT		
SN:L313172	HRS		0	TSN 0						
	ENC	0	20000	TSN 0	(20000) 20072		14423			
PROC. REF: GENERIC NO REF										
723500-0113 NO. 2 ENGINE - 13TH STAGE COMPRESSOR WHEEL Component ATA:72										
PN:23074213	MOS		25-Sep-07	TSN 0				LIFE LIMIT		
SN:L313180	HRS		0	TSN 0						
	ENC	0	20000	TSN 0	(20000) 20072		14423			
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of:
11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
723500-0114 NO. 1 ENGINE - 14TH STAGE COMPRESSOR WHEEL Component ATA:72										
PN:23074214	MOS		25-Sep-07	TSN 0				LIFE LIMIT		
SN:L308693	HRS		0	TSN 0						
	ENC	0	20000	TSN 0	(20000) 20072		14423			
PROC. REF: GENERIC NO REF										
723500-0114 NO. 2 ENGINE - 14TH STAGE COMPRESSOR WHEEL Component ATA:72										
PN:23074214	MOS		25-Sep-07	TSN 0				LIFE LIMIT		
SN:L308696	HRS		0	TSN 0						
	ENC	0	20000	TSN 0	(20000) 20072		14423			
PROC. REF: GENERIC NO REF										
723500-0120 NO. 1 ENGINE - COMPRESSOR SHAFT CONE ASSEMBLY Component ATA:72										
PN:23076016	MOS		25-Sep-07	TSN 0				LIFE LIMIT		
SN:L311723	HRS		0	TSN 0						
	ENC	0	20000	TSN 0	(20000) 20072		14423			
PROC. REF: GENERIC NO REF										
723500-0120 NO. 2 ENGINE - COMPRESSOR SHAFT CONE ASSEMBLY Component ATA:72										
PN:23076016	MOS		25-Sep-07	TSN 0				LIFE LIMIT		
SN:L311743	HRS		0	TSN 0						
	ENC	0	20000	TSN 0	(20000) 20072		14423			
PROC. REF: GENERIC NO REF										
723700-0101 NO. 1 ENGINE - COMPRESSOR CASE ASSEMBLY Component ATA:72										
PN:PN	MOS/MSC		25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS		0	TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
723700-0101 NO. 2 ENGINE - COMPRESSOR CASE ASSEMBLY Component ATA:72										
PN:PN	MOS/MSC		25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS		0	TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
723705-0101 NO. 1 ENGINE - COMPRESSOR DIFFUSER Component ATA:72										
PN:23079071	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:NY217133	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
723705-0101 NO. 2 ENGINE - COMPRESSOR DIFFUSER Component ATA:72										
PN:23079071	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:NY216909	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
723707-0101 NO. 1 ENGINE - SPLIT BALL BEARING Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
723707-0101 NO. 2 ENGINE - SPLIT BALL BEARING Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
723902-0101 NO. 1 ENGINE - NO. 6 CARBON CENTER SUMP SEAL ASSEMBLY Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
723902-0101 NO. 2 ENGINE - NO. 6 CARBON CENTER SUMP SEAL ASSEMBLY Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
723903-0101 NO. 1 ENGINE - NO. 5 CARBON CENTER SUMP SEAL ASSEMBLY Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
723903-0101 NO. 2 ENGINE - NO. 5 CARBON CENTER SUMP SEAL ASSEMBLY Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
723904-0101 NO. 1 ENGINE - CENTER SUMP HOUSING ASSEMBLY Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
723904-0101 NO. 2 ENGINE - CENTER SUMP HOUSING ASSEMBLY Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
724500-0101 NO. 1 ENGINE - COMBUSTION LINER ASSEMBLY Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
724500-0101 NO. 2 ENGINE - COMBUSTION LINER ASSEMBLY Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725000-0101 NO. 1 ENGINE - HPT ROTOR ASSEMBLY Component ATA:72										
PN:23074650	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:A72794	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725000-0101 NO. 2 ENGINE - HPT ROTOR ASSEMBLY Component ATA:72										
PN:23074650	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:A72795	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725010-0101 NO. 1 ENGINE - ROTOR ASSY-LPT ROTOR ASSEMBLY Component ATA:72										
PN:23074088	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:A82774	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010-0101 NO. 2 ENGINE - ROTOR ASSY-LPT ROTOR ASSEMBLY Component ATA:72										
PN:23074088	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:A82776	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725181-0101 NO. 1 ENGINE - NO. 1 HP TURBINE 2ND STAGE VANE ASSEMBLY Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725181-0101 NO. 2 ENGINE - NO. 1 HP TURBINE 2ND STAGE VANE ASSEMBLY Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725181-0102 NO. 1 ENGINE - NO. 2 HP TURBINE 2ND STAGE VANE ASSEMBLY Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725181-0102 NO. 2 ENGINE - NO. 2 HP TURBINE 2ND STAGE VANE ASSEMBLY Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725181-0103 NO. 1 ENGINE - NO. 3 HP TURBINE 2ND STAGE VANE ASSEMBLY Component ATA:72										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725181-0103	NO. 2 ENGINE - NO. 3 HP TURBINE 2ND STAGE VANE ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725181-0104	NO. 1 ENGINE - NO. 4 HP TURBINE 2ND STAGE VANE ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725181-0104	NO. 2 ENGINE - NO. 4 HP TURBINE 2ND STAGE VANE ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725181-0105	NO. 1 ENGINE - NO. 5 HP TURBINE 2ND STAGE VANE ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725181-0105	NO. 2 ENGINE - NO. 5 HP TURBINE 2ND STAGE VANE ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725181-0106	NO. 1 ENGINE - NO. 6 HP TURBINE 2ND STAGE VANE ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725181-0106	NO. 2 ENGINE - NO. 6 HP TURBINE 2ND STAGE VANE ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725181-0107	NO. 1 ENGINE - NO. 7 HP TURBINE 2ND STAGE VANE ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725181-0107	NO. 2 ENGINE - NO. 7 HP TURBINE 2ND STAGE VANE ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725181-0108	NO. 1 ENGINE - NO. 8 HP TURBINE 2ND STAGE VANE ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725181-0108	NO. 2 ENGINE - NO. 8 HP TURBINE 2ND STAGE VANE ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725181-0109	NO. 1 ENGINE - NO. 9 HP TURBINE 2ND STAGE VANE ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725181-0109	NO. 2 ENGINE - NO. 9 HP TURBINE 2ND STAGE VANE ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725181-0110	NO. 1 ENGINE - NO. 10 HP TURBINE 2ND STAGE VANE ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725181-0110	NO. 2 ENGINE - NO. 10 HP TURBINE 2ND STAGE VANE ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725181-0111	NO. 1 ENGINE - NO. 11 HP TURBINE 2ND STAGE VANE ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725181-0111	NO. 2 ENGINE - NO. 11 HP TURBINE 2ND STAGE VANE ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725181-0112	NO. 1 ENGINE - NO. 12 HP TURBINE 2ND STAGE VANE ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725181-0112	NO. 2 ENGINE - NO. 12 HP TURBINE 2ND STAGE VANE ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725181-0113	NO. 1 ENGINE - NO. 13 HP TURBINE 2ND STAGE VANE ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725181-0113	NO. 2 ENGINE - NO. 13 HP TURBINE 2ND STAGE VANE ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 72 - ENGINE											
725181-0114		NO. 1 ENGINE - NO. 14 HP TURBINE 2ND STAGE VANE ASSEMBLY								Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: GENERIC NO REF											
725181-0114		NO. 2 ENGINE - NO. 14 HP TURBINE 2ND STAGE VANE ASSEMBLY								Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: GENERIC NO REF											
725181-0115		NO. 1 ENGINE - NO. 15 HP TURBINE 2ND STAGE VANE ASSEMBLY								Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: GENERIC NO REF											
725181-0115		NO. 2 ENGINE - NO. 15 HP TURBINE 2ND STAGE VANE ASSEMBLY								Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: GENERIC NO REF											
725181-0116		NO. 1 ENGINE - NO. 16 HP TURBINE 2ND STAGE VANE ASSEMBLY								Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: GENERIC NO REF											
725181-0116		NO. 2 ENGINE - NO. 16 HP TURBINE 2ND STAGE VANE ASSEMBLY								Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: GENERIC NO REF											
725200-0101		NO. 1 ENGINE - 1ST STAGE GAS-GENERATOR TURBINE OR HP TURBINE WHEEL								Component	ATA:72
PN:23079946	MOS	25-Sep-07		TSN 0				LIFE LIMIT			
SN:MW51866	HRS	0		TSN 0							
	ENC	0	35000	TSN 0	(35000) 35072		29423				
PROC. REF: GENERIC NO REF											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725200-0101 NO. 2 ENGINE - 1ST STAGE GAS-GENERATOR TURBINE OR HP TURBINE WHEEL Component ATA:72										
PN:23079946	MOS		25-Sep-07		TSN 0			LIFE LIMIT		
SN:MW51868	HRS		0		TSN 0					
	ENC	0	35000		TSN 0	(35000) 35072	29423			
PROC. REF: GENERIC NO REF										
725200-0102 NO. 1 ENGINE - 2ND STAGE GAS-GENERATOR TURBINE OR HP TURBINE WHEEL Component ATA:72										
PN:23084781	MOS		25-Sep-07		TSN 0			LIFE LIMIT		
SN:MW51939	HRS		0		TSN 0					
	ENC	0	20000		TSN 0	(20000) 20072	14423			
PROC. REF: GENERIC NO REF										
725200-0102 NO. 2 ENGINE - 2ND STAGE GAS-GENERATOR TURBINE OR HP TURBINE WHEEL Component ATA:72										
PN:23084781	MOS		25-Sep-07		TSN 0			LIFE LIMIT		
SN:MW51964	HRS		0		TSN 0					
	ENC	0	20000		TSN 0	(20000) 20072	14423			
PROC. REF: GENERIC NO REF										
725200-0105 NO. 1 ENGINE - HP TURBINE ROTOR 1ST TO 2ND STAGE TURBINE SPACER Component ATA:72										
PN:23076778	MOS		25-Sep-07		TSN 0			LIFE LIMIT		
SN:TW516137	HRS		0		TSN 0					
	ENC	0	30000		TSN 0	(30000) 30072	24423			
PROC. REF: GENERIC NO REF										
725200-0105 NO. 2 ENGINE - HP TURBINE ROTOR 1ST TO 2ND STAGE TURBINE SPACER Component ATA:72										
PN:23076778	MOS		25-Sep-07		TSN 0			LIFE LIMIT		
SN:TW516070	HRS		0		TSN 0					
	ENC	0	30000		TSN 0	(30000) 30072	24423			
PROC. REF: GENERIC NO REF										
725281-0101 NO. 1 ENGINE - STAGE 1 TURBINE WHEEL RING SEAL Component ATA:72										
PN:PN	MOS/MSC		25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS		0		TSN 0					
	ENC	0			TSN 0					
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725281-0101	NO. 2 ENGINE - STAGE 1 TURBINE WHEEL RING SEAL									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0101	NO. 1 ENGINE - NO. 1 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0101	NO. 2 ENGINE - NO. 1 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0102	NO. 1 ENGINE - NO. 2 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0102	NO. 2 ENGINE - NO. 2 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0103	NO. 1 ENGINE - NO. 3 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0103	NO. 2 ENGINE - NO. 3 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 72 - ENGINE											
725282-0104			NO. 1 ENGINE - NO. 4 HP TURBINE 2ND STAGE BLADE						Component	ATA:72	
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: GENERIC NO REF											
725282-0104			NO. 2 ENGINE - NO. 4 HP TURBINE 2ND STAGE BLADE						Component	ATA:72	
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: GENERIC NO REF											
725282-0105			NO. 1 ENGINE - NO. 5 HP TURBINE 2ND STAGE BLADE						Component	ATA:72	
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: GENERIC NO REF											
725282-0105			NO. 2 ENGINE - NO. 5 HP TURBINE 2ND STAGE BLADE						Component	ATA:72	
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: GENERIC NO REF											
725282-0106			NO. 1 ENGINE - NO. 6 HP TURBINE 2ND STAGE BLADE						Component	ATA:72	
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: GENERIC NO REF											
725282-0106			NO. 2 ENGINE - NO. 6 HP TURBINE 2ND STAGE BLADE						Component	ATA:72	
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: GENERIC NO REF											
725282-0107			NO. 1 ENGINE - NO. 7 HP TURBINE 2ND STAGE BLADE						Component	ATA:72	
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: GENERIC NO REF											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725282-0107	NO. 2 ENGINE - NO. 7 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725282-0108	NO. 1 ENGINE - NO. 8 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725282-0108	NO. 2 ENGINE - NO. 8 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725282-0109	NO. 1 ENGINE - NO. 9 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725282-0109	NO. 2 ENGINE - NO. 9 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725282-0110	NO. 1 ENGINE - NO. 10 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725282-0110	NO. 2 ENGINE - NO. 10 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725282-0111	NO. 1 ENGINE - NO. 11 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0111	NO. 2 ENGINE - NO. 11 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0112	NO. 1 ENGINE - NO. 12 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0112	NO. 2 ENGINE - NO. 12 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0113	NO. 1 ENGINE - NO. 13 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0113	NO. 2 ENGINE - NO. 13 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0114	NO. 1 ENGINE - NO. 14 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725282-0114	NO. 2 ENGINE - NO. 14 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0115	NO. 1 ENGINE - NO. 15 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0115	NO. 2 ENGINE - NO. 15 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0116	NO. 1 ENGINE - NO. 16 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0116	NO. 2 ENGINE - NO. 16 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0117	NO. 1 ENGINE - NO. 17 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0117	NO. 2 ENGINE - NO. 17 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 72 - ENGINE											
725282-0118			NO. 1 ENGINE - NO. 18 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	ENC	0	TSN 0								
PROC. REF: GENERIC NO REF											
725282-0118			NO. 2 ENGINE - NO. 18 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	ENC	0	TSN 0								
PROC. REF: GENERIC NO REF											
725282-0119			NO. 1 ENGINE - NO. 19 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	ENC	0	TSN 0								
PROC. REF: GENERIC NO REF											
725282-0119			NO. 2 ENGINE - NO. 19 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	ENC	0	TSN 0								
PROC. REF: GENERIC NO REF											
725282-0120			NO. 1 ENGINE - NO. 20 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	ENC	0	TSN 0								
PROC. REF: GENERIC NO REF											
725282-0120			NO. 2 ENGINE - NO. 20 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	ENC	0	TSN 0								
PROC. REF: GENERIC NO REF											
725282-0121			NO. 1 ENGINE - NO. 21 HP TURBINE 2ND STAGE BLADE							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	ENC	0	TSN 0								
PROC. REF: GENERIC NO REF											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725282-0121	NO. 2 ENGINE - NO. 21 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0122	NO. 1 ENGINE - NO. 22 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0122	NO. 2 ENGINE - NO. 22 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0123	NO. 1 ENGINE - NO. 23 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0123	NO. 2 ENGINE - NO. 23 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0124	NO. 1 ENGINE - NO. 24 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0124	NO. 2 ENGINE - NO. 24 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725282-0125	NO. 1 ENGINE - NO. 25 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0125	NO. 2 ENGINE - NO. 25 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0126	NO. 1 ENGINE - NO. 26 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0126	NO. 2 ENGINE - NO. 26 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0127	NO. 1 ENGINE - NO. 27 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0127	NO. 2 ENGINE - NO. 27 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0128	NO. 1 ENGINE - NO. 28 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725282-0128	NO. 2 ENGINE - NO. 28 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0129	NO. 1 ENGINE - NO. 29 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0129	NO. 2 ENGINE - NO. 29 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0130	NO. 1 ENGINE - NO. 30 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0130	NO. 2 ENGINE - NO. 30 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0131	NO. 1 ENGINE - NO. 31 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0131	NO. 2 ENGINE - NO. 31 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 72 - ENGINE											
725282-0132		NO. 1 ENGINE - NO. 32 HP TURBINE 2ND STAGE BLADE								Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	ENC	0	TSN 0								
PROC. REF: GENERIC NO REF											
725282-0132		NO. 2 ENGINE - NO. 32 HP TURBINE 2ND STAGE BLADE								Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	ENC	0	TSN 0								
PROC. REF: GENERIC NO REF											
725282-0133		NO. 1 ENGINE - NO. 33 HP TURBINE 2ND STAGE BLADE								Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	ENC	0	TSN 0								
PROC. REF: GENERIC NO REF											
725282-0133		NO. 2 ENGINE - NO. 33 HP TURBINE 2ND STAGE BLADE								Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	ENC	0	TSN 0								
PROC. REF: GENERIC NO REF											
725282-0134		NO. 1 ENGINE - NO. 34 HP TURBINE 2ND STAGE BLADE								Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	ENC	0	TSN 0								
PROC. REF: GENERIC NO REF											
725282-0134		NO. 2 ENGINE - NO. 34 HP TURBINE 2ND STAGE BLADE								Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	ENC	0	TSN 0								
PROC. REF: GENERIC NO REF											
725282-0135		NO. 1 ENGINE - NO. 35 HP TURBINE 2ND STAGE BLADE								Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	ENC	0	TSN 0								
PROC. REF: GENERIC NO REF											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725282-0135	NO. 2 ENGINE - NO. 35 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0136	NO. 1 ENGINE - NO. 36 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0136	NO. 2 ENGINE - NO. 36 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0137	NO. 1 ENGINE - NO. 37 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0137	NO. 2 ENGINE - NO. 37 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0138	NO. 1 ENGINE - NO. 38 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0138	NO. 2 ENGINE - NO. 38 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725282-0139	NO. 1 ENGINE - NO. 39 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0139	NO. 2 ENGINE - NO. 39 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0140	NO. 1 ENGINE - NO. 40 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0140	NO. 2 ENGINE - NO. 40 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0141	NO. 1 ENGINE - NO. 41 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0141	NO. 2 ENGINE - NO. 41 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0142	NO. 1 ENGINE - NO. 42 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725282-0142	NO. 2 ENGINE - NO. 42 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0143	NO. 1 ENGINE - NO. 43 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0143	NO. 2 ENGINE - NO. 43 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0144	NO. 1 ENGINE - NO. 44 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0144	NO. 2 ENGINE - NO. 44 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0145	NO. 1 ENGINE - NO. 45 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0145	NO. 2 ENGINE - NO. 45 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725282-0146	NO. 1 ENGINE - NO. 46 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0146	NO. 2 ENGINE - NO. 46 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0147	NO. 1 ENGINE - NO. 47 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0147	NO. 2 ENGINE - NO. 47 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0148	NO. 1 ENGINE - NO. 48 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0148	NO. 2 ENGINE - NO. 48 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0149	NO. 1 ENGINE - NO. 49 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725282-0149	NO. 2 ENGINE - NO. 49 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0150	NO. 1 ENGINE - NO. 50 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0150	NO. 2 ENGINE - NO. 50 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0151	NO. 1 ENGINE - NO. 51 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0151	NO. 2 ENGINE - NO. 51 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0152	NO. 1 ENGINE - NO. 52 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0152	NO. 2 ENGINE - NO. 52 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725282-0153	NO. 1 ENGINE - NO. 53 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0153	NO. 2 ENGINE - NO. 53 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0154	NO. 1 ENGINE - NO. 54 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0154	NO. 2 ENGINE - NO. 54 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0155	NO. 1 ENGINE - NO. 55 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0155	NO. 2 ENGINE - NO. 55 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0156	NO. 1 ENGINE - NO. 56 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725282-0156	NO. 2 ENGINE - NO. 56 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0157	NO. 1 ENGINE - NO. 57 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0157	NO. 2 ENGINE - NO. 57 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0158	NO. 1 ENGINE - NO. 58 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0158	NO. 2 ENGINE - NO. 58 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0159	NO. 1 ENGINE - NO. 59 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0159	NO. 2 ENGINE - NO. 59 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725282-0160	NO. 1 ENGINE - NO. 60 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0160	NO. 2 ENGINE - NO. 60 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0161	NO. 1 ENGINE - NO. 61 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0161	NO. 2 ENGINE - NO. 61 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0162	NO. 1 ENGINE - NO. 62 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0162	NO. 2 ENGINE - NO. 62 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0163	NO. 1 ENGINE - NO. 63 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725282-0163	NO. 2 ENGINE - NO. 63 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0164	NO. 1 ENGINE - NO. 64 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0164	NO. 2 ENGINE - NO. 64 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0165	NO. 1 ENGINE - NO. 65 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0165	NO. 2 ENGINE - NO. 65 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0166	NO. 1 ENGINE - NO. 66 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0166	NO. 2 ENGINE - NO. 66 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725282-0167	NO. 1 ENGINE - NO. 67 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0167	NO. 2 ENGINE - NO. 67 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0168	NO. 1 ENGINE - NO. 68 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0168	NO. 2 ENGINE - NO. 68 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0169	NO. 1 ENGINE - NO. 69 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0169	NO. 2 ENGINE - NO. 69 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0170	NO. 1 ENGINE - NO. 70 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725282-0170	NO. 2 ENGINE - NO. 70 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0171	NO. 1 ENGINE - NO. 71 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0171	NO. 2 ENGINE - NO. 71 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0172	NO. 1 ENGINE - NO. 72 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0172	NO. 2 ENGINE - NO. 72 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0173	NO. 1 ENGINE - NO. 73 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0173	NO. 2 ENGINE - NO. 73 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725282-0174	NO. 1 ENGINE - NO. 74 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0174	NO. 2 ENGINE - NO. 74 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0175	NO. 1 ENGINE - NO. 75 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0175	NO. 2 ENGINE - NO. 75 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0176	NO. 1 ENGINE - NO. 76 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0176	NO. 2 ENGINE - NO. 76 HP TURBINE 2ND STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725282-0201	NO. 1 ENGINE - HPT 2ND STAGE (BLADED) WHEEL ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 72 - ENGINE											
725282-0201		NO. 2 ENGINE - HPT 2ND STAGE (BLADED) WHEEL ASSEMBLY							Component	ATA:72	
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	ENC	0	TSN 0								
PROC. REF: GENERIC NO REF											
725283-0101		NO. 1 ENGINE - STAGE 2 TURBINE BLADES							Component	ATA:72	
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	ENC	0	TSN 0								
PROC. REF: GENERIC NO REF											
725283-0101		NO. 2 ENGINE - STAGE 2 TURBINE BLADES							Component	ATA:72	
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	ENC	0	TSN 0								
PROC. REF: GENERIC NO REF											
725284-0101		NO. 1 ENGINE - NO. 1 HP TURBINE 1ST STAGE BLADE							Component	ATA:72	
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	ENC	0	TSN 0								
PROC. REF: GENERIC NO REF											
725284-0101		NO. 2 ENGINE - NO. 1 HP TURBINE 1ST STAGE BLADE							Component	ATA:72	
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	ENC	0	TSN 0								
PROC. REF: GENERIC NO REF											
725284-0102		NO. 1 ENGINE - NO. 2 HP TURBINE 1ST STAGE BLADE							Component	ATA:72	
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	ENC	0	TSN 0								
PROC. REF: GENERIC NO REF											
725284-0102		NO. 2 ENGINE - NO. 2 HP TURBINE 1ST STAGE BLADE							Component	ATA:72	
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	ENC	0	TSN 0								
PROC. REF: GENERIC NO REF											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725284-0103	NO. 1 ENGINE - NO. 3 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725284-0103	NO. 2 ENGINE - NO. 3 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725284-0104	NO. 1 ENGINE - NO. 4 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725284-0104	NO. 2 ENGINE - NO. 4 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725284-0105	NO. 1 ENGINE - NO. 5 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725284-0105	NO. 2 ENGINE - NO. 5 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725284-0106	NO. 1 ENGINE - NO. 6 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725284-0106	NO. 2 ENGINE - NO. 6 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725284-0107	NO. 1 ENGINE - NO. 7 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725284-0107	NO. 2 ENGINE - NO. 7 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725284-0108	NO. 1 ENGINE - NO. 8 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725284-0108	NO. 2 ENGINE - NO. 8 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725284-0109	NO. 1 ENGINE - NO. 9 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725284-0109	NO. 2 ENGINE - NO. 9 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725284-0110	NO. 1 ENGINE - NO. 10 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725284-0110	NO. 2 ENGINE - NO. 10 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725284-0111	NO. 1 ENGINE - NO. 11 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725284-0111	NO. 2 ENGINE - NO. 11 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725284-0112	NO. 1 ENGINE - NO. 12 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725284-0112	NO. 2 ENGINE - NO. 12 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725284-0113	NO. 1 ENGINE - NO. 13 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725284-0113	NO. 2 ENGINE - NO. 13 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725284-0114	NO. 1 ENGINE - NO. 14 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725284-0114	NO. 2 ENGINE - NO. 14 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725284-0115	NO. 1 ENGINE - NO. 15 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725284-0115	NO. 2 ENGINE - NO. 15 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725284-0116	NO. 1 ENGINE - NO. 16 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725284-0116	NO. 2 ENGINE - NO. 16 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725284-0117	NO. 1 ENGINE - NO. 17 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725284-0117	NO. 2 ENGINE - NO. 17 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725284-0118	NO. 1 ENGINE - NO. 18 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725284-0118	NO. 2 ENGINE - NO. 18 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725284-0119	NO. 1 ENGINE - NO. 19 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725284-0119	NO. 2 ENGINE - NO. 19 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725284-0120	NO. 1 ENGINE - NO. 20 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725284-0120	NO. 2 ENGINE - NO. 20 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725284-0121	NO. 1 ENGINE - NO. 21 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725284-0121	NO. 2 ENGINE - NO. 21 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725284-0122	NO. 1 ENGINE - NO. 22 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725284-0122	NO. 2 ENGINE - NO. 22 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725284-0123	NO. 1 ENGINE - NO. 23 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725284-0123	NO. 2 ENGINE - NO. 23 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 72 - ENGINE											
725284-0124			NO. 1 ENGINE - NO. 24 HP TURBINE 1ST STAGE BLADE						Component	ATA:72	
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: GENERIC NO REF											
725284-0124			NO. 2 ENGINE - NO. 24 HP TURBINE 1ST STAGE BLADE						Component	ATA:72	
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: GENERIC NO REF											
725284-0125			NO. 1 ENGINE - NO. 25 HP TURBINE 1ST STAGE BLADE						Component	ATA:72	
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: GENERIC NO REF											
725284-0125			NO. 2 ENGINE - NO. 25 HP TURBINE 1ST STAGE BLADE						Component	ATA:72	
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: GENERIC NO REF											
725284-0126			NO. 1 ENGINE - NO. 26 HP TURBINE 1ST STAGE BLADE						Component	ATA:72	
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: GENERIC NO REF											
725284-0126			NO. 2 ENGINE - NO. 26 HP TURBINE 1ST STAGE BLADE						Component	ATA:72	
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: GENERIC NO REF											
725284-0127			NO. 1 ENGINE - NO. 27 HP TURBINE 1ST STAGE BLADE						Component	ATA:72	
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: GENERIC NO REF											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725284-0127	NO. 2 ENGINE - NO. 27 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725284-0128	NO. 1 ENGINE - NO. 28 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725284-0128	NO. 2 ENGINE - NO. 28 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725284-0129	NO. 1 ENGINE - NO. 29 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725284-0129	NO. 2 ENGINE - NO. 29 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725284-0130	NO. 1 ENGINE - NO. 30 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725284-0130	NO. 2 ENGINE - NO. 30 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725284-0131			NO. 1 ENGINE - NO. 31 HP TURBINE 1ST STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725284-0131			NO. 2 ENGINE - NO. 31 HP TURBINE 1ST STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725284-0132			NO. 1 ENGINE - NO. 32 HP TURBINE 1ST STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725284-0132			NO. 2 ENGINE - NO. 32 HP TURBINE 1ST STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725284-0133			NO. 1 ENGINE - NO. 33 HP TURBINE 1ST STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725284-0133			NO. 2 ENGINE - NO. 33 HP TURBINE 1ST STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725284-0134			NO. 1 ENGINE - NO. 34 HP TURBINE 1ST STAGE BLADE						Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 72 - ENGINE											
725284-0134			NO. 2 ENGINE - NO. 34 HP TURBINE 1ST STAGE BLADE						Component	ATA:72	
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: GENERIC NO REF											
725284-0135			NO. 1 ENGINE - NO. 35 HP TURBINE 1ST STAGE BLADE						Component	ATA:72	
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: GENERIC NO REF											
725284-0135			NO. 2 ENGINE - NO. 35 HP TURBINE 1ST STAGE BLADE						Component	ATA:72	
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: GENERIC NO REF											
725284-0136			NO. 1 ENGINE - NO. 36 HP TURBINE 1ST STAGE BLADE						Component	ATA:72	
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: GENERIC NO REF											
725284-0136			NO. 2 ENGINE - NO. 36 HP TURBINE 1ST STAGE BLADE						Component	ATA:72	
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: GENERIC NO REF											
725284-0137			NO. 1 ENGINE - NO. 37 HP TURBINE 1ST STAGE BLADE						Component	ATA:72	
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: GENERIC NO REF											
725284-0137			NO. 2 ENGINE - NO. 37 HP TURBINE 1ST STAGE BLADE						Component	ATA:72	
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: GENERIC NO REF											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 72 - ENGINE											
725284-0138			NO. 1 ENGINE - NO. 38 HP TURBINE 1ST STAGE BLADE						Component	ATA:72	
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: GENERIC NO REF											
725284-0138			NO. 2 ENGINE - NO. 38 HP TURBINE 1ST STAGE BLADE						Component	ATA:72	
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: GENERIC NO REF											
725284-0139			NO. 1 ENGINE - NO. 39 HP TURBINE 1ST STAGE BLADE						Component	ATA:72	
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: GENERIC NO REF											
725284-0139			NO. 2 ENGINE - NO. 39 HP TURBINE 1ST STAGE BLADE						Component	ATA:72	
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: GENERIC NO REF											
725284-0140			NO. 1 ENGINE - NO. 40 HP TURBINE 1ST STAGE BLADE						Component	ATA:72	
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: GENERIC NO REF											
725284-0140			NO. 2 ENGINE - NO. 40 HP TURBINE 1ST STAGE BLADE						Component	ATA:72	
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: GENERIC NO REF											
725284-0141			NO. 1 ENGINE - NO. 41 HP TURBINE 1ST STAGE BLADE						Component	ATA:72	
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: GENERIC NO REF											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725284-0141	NO. 2 ENGINE - NO. 41 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725284-0142	NO. 1 ENGINE - NO. 42 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725284-0142	NO. 2 ENGINE - NO. 42 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725284-0143	NO. 1 ENGINE - NO. 43 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725284-0143	NO. 2 ENGINE - NO. 43 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725284-0144	NO. 1 ENGINE - NO. 44 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725284-0144	NO. 2 ENGINE - NO. 44 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725284-0145	NO. 1 ENGINE - NO. 45 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725284-0145	NO. 2 ENGINE - NO. 45 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725284-0146	NO. 1 ENGINE - NO. 46 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725284-0146	NO. 2 ENGINE - NO. 46 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725284-0147	NO. 1 ENGINE - NO. 47 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725284-0147	NO. 2 ENGINE - NO. 47 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725284-0148	NO. 1 ENGINE - NO. 48 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725284-0148	NO. 2 ENGINE - NO. 48 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725284-0149	NO. 1 ENGINE - NO. 49 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725284-0149	NO. 2 ENGINE - NO. 49 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725284-0150	NO. 1 ENGINE - NO. 50 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725284-0150	NO. 2 ENGINE - NO. 50 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725284-0151	NO. 1 ENGINE - NO. 51 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725284-0151	NO. 2 ENGINE - NO. 51 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 72 - ENGINE											
725284-0152			NO. 1 ENGINE - NO. 52 HP TURBINE 1ST STAGE BLADE						Component	ATA:72	
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: GENERIC NO REF											
725284-0152			NO. 2 ENGINE - NO. 52 HP TURBINE 1ST STAGE BLADE						Component	ATA:72	
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: GENERIC NO REF											
725284-0153			NO. 1 ENGINE - NO. 53 HP TURBINE 1ST STAGE BLADE						Component	ATA:72	
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: GENERIC NO REF											
725284-0153			NO. 2 ENGINE - NO. 53 HP TURBINE 1ST STAGE BLADE						Component	ATA:72	
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: GENERIC NO REF											
725284-0154			NO. 1 ENGINE - NO. 54 HP TURBINE 1ST STAGE BLADE						Component	ATA:72	
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: GENERIC NO REF											
725284-0154			NO. 2 ENGINE - NO. 54 HP TURBINE 1ST STAGE BLADE						Component	ATA:72	
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: GENERIC NO REF											
725284-0155			NO. 1 ENGINE - NO. 55 HP TURBINE 1ST STAGE BLADE						Component	ATA:72	
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: GENERIC NO REF											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725284-0155	NO. 2 ENGINE - NO. 55 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725284-0156	NO. 1 ENGINE - NO. 56 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725284-0156	NO. 2 ENGINE - NO. 56 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725284-0157	NO. 1 ENGINE - NO. 57 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725284-0157	NO. 2 ENGINE - NO. 57 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725284-0158	NO. 1 ENGINE - NO. 58 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725284-0158	NO. 2 ENGINE - NO. 58 HP TURBINE 1ST STAGE BLADE									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725284-0201 NO. 1 ENGINE - HPT 1ST STAGE (BLADED) WHEEL ASSEMBLY										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						Component ATA:72
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725284-0201 NO. 2 ENGINE - HPT 1ST STAGE (BLADED) WHEEL ASSEMBLY										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						Component ATA:72
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725285-0101 NO. 1 ENGINE - 1ST STAGE HPT BLADES										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						Component ATA:72
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725285-0101 NO. 2 ENGINE - 1ST STAGE HPT BLADES										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						Component ATA:72
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725289-0101 NO. 1 ENGINE - AIR DISTRIBUTION RING										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						Component ATA:72
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725289-0101 NO. 2 ENGINE - AIR DISTRIBUTION RING										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						Component ATA:72
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725700-0101 NO. 1 ENGINE - LPT TURBINE ASSEMBLY										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						Component ATA:72
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725700-0101	NO. 2 ENGINE - LPT TURBINE ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725702-0101	NO. 1 ENGINE - LPT CASE ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725702-0101	NO. 2 ENGINE - LPT CASE ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725703-0101	NO. 1 ENGINE - LP TURBINE STAGE 1 VANE RING									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725703-0101	NO. 2 ENGINE - LP TURBINE STAGE 1 VANE RING									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725707-0101	NO. 1 ENGINE - INTERSHAFT CARBON SEAL									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725707-0101	NO. 2 ENGINE - INTERSHAFT CARBON SEAL									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725800-0101 NO. 1 ENGINE - 1ST STAGE LOW PRESSURE TURBINE WHEEL										
PN:23076801	MOS		25-Sep-07		TSN 0			LIFE LIMIT		Component ATA:72
SN:MW49192	HRS		0		TSN 0					
	ENC		0	35000	TSN 0	(35000) 35072	29423			
PROC. REF: GENERIC NO REF										
725800-0101 NO. 2 ENGINE - 1ST STAGE LOW PRESSURE TURBINE WHEEL										
PN:23076801	MOS		25-Sep-07		TSN 0			LIFE LIMIT		Component ATA:72
SN:MW49120	HRS		0		TSN 0					
	ENC		0	35000	TSN 0	(35000) 35072	29423			
PROC. REF: GENERIC NO REF										
725800-0102 NO. 1 ENGINE - 2ND STAGE LOW PRESSURE TURBINE WHEEL										
PN:23079220	MOS		25-Sep-07		TSN 0			LIFE LIMIT		Component ATA:72
SN:MW48763	HRS		0		TSN 0					
	ENC		0	35000	TSN 0	(35000) 35072	29423			
PROC. REF: GENERIC NO REF										
725800-0102 NO. 2 ENGINE - 2ND STAGE LOW PRESSURE TURBINE WHEEL										
PN:23079220	MOS		25-Sep-07		TSN 0			LIFE LIMIT		Component ATA:72
SN:MW48782	HRS		0		TSN 0					
	ENC		0	35000	TSN 0	(35000) 35072	29423			
PROC. REF: GENERIC NO REF										
725800-0103 NO. 1 ENGINE - 3RD STAGE LOW PRESSURE TURBINE WHEEL										
PN:23079224	MOS		25-Sep-07		TSN 0			LIFE LIMIT		Component ATA:72
SN:MW48959	HRS		0		TSN 0					
	ENC		0	35000	TSN 0	(35000) 35072	29423			
PROC. REF: GENERIC NO REF										
725800-0103 NO. 2 ENGINE - 3RD STAGE LOW PRESSURE TURBINE WHEEL										
PN:23079224	MOS		25-Sep-07		TSN 0			LIFE LIMIT		Component ATA:72
SN:MW48958	HRS		0		TSN 0					
	ENC		0	35000	TSN 0	(35000) 35072	29423			
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725800-0104 NO. 1 ENGINE - LOW PRESSURE TURBINE INTERSTAGE AFT SPACER										
PN:23054049	MOS		25-Sep-07		TSN 0			LIFE LIMIT		Component ATA:72
SN:TW516290	HRS		0		TSN 0					
	ENC	0	35000		TSN 0	(35000) 35072	29423			
PROC. REF: GENERIC NO REF										
725800-0104 NO. 2 ENGINE - LOW PRESSURE TURBINE INTERSTAGE AFT SPACER										
PN:23054049	MOS		25-Sep-07		TSN 0			LIFE LIMIT		Component ATA:72
SN:TW516291	HRS		0		TSN 0					
	ENC	0	35000		TSN 0	(35000) 35072	29423			
PROC. REF: GENERIC NO REF										
725800-0105 NO. 1 ENGINE - LOW PRESSURE TURBINE INTERSTAGE FORWARD SPACER										
PN:23054049	MOS		25-Sep-07		TSN 0			LIFE LIMIT		Component ATA:72
SN:TW514752	HRS		0		TSN 0					
	ENC	0	35000		TSN 0	(35000) 35072	29423			
PROC. REF: GENERIC NO REF										
725800-0105 NO. 2 ENGINE - LOW PRESSURE TURBINE INTERSTAGE FORWARD SPACER										
PN:23054049	MOS		25-Sep-07		TSN 0			LIFE LIMIT		Component ATA:72
SN:TW516323	HRS		0		TSN 0					
	ENC	0	35000		TSN 0	(35000) 35072	29423			
PROC. REF: GENERIC NO REF										
725800-0106 NO. 1 ENGINE - LP TURBINE ROTOR LOW PRESSURE TURBINE FORWARD SHAFT										
PN:23074538	MOS		25-Sep-07		TSN 0			LIFE LIMIT		Component ATA:72
SN:GV253002	HRS		0		TSN 0					
	ENC	0	35000		TSN 0	(35000) 35072	29423			
PROC. REF: GENERIC NO REF										
725800-0106 NO. 2 ENGINE - LP TURBINE ROTOR LOW PRESSURE TURBINE FORWARD SHAFT										
PN:23074538	MOS		25-Sep-07		TSN 0			LIFE LIMIT		Component ATA:72
SN:GV257987	HRS		0		TSN 0					
	ENC	0	35000		TSN 0	(35000) 35072	29423			
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 72 - ENGINE											
725800-0201		NO. 1 ENGINE - BALL BEARING								Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: GENERIC NO REF											
725800-0201		NO. 2 ENGINE - BALL BEARING								Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: GENERIC NO REF											
725802-0101		NO. 1 ENGINE - REAR LPT SHAFT								Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: GENERIC NO REF											
725802-0101		NO. 2 ENGINE - REAR LPT SHAFT								Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: GENERIC NO REF											
725883-0101		NO. 1 ENGINE - LPT-1 ROTATING SEAL								Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: GENERIC NO REF											
725883-0101		NO. 2 ENGINE - LPT-1 ROTATING SEAL								Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: GENERIC NO REF											
725884-0101		NO. 1 ENGINE - LPT WHEEL ASSEMBLY								Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: GENERIC NO REF											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725884-0101	NO. 2 ENGINE - LPT WHEEL ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725885-0101	NO. 1 ENGINE - LPT (BLADED) WHEEL ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725885-0101	NO. 2 ENGINE - LPT (BLADED) WHEEL ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725886-0101	NO. 1 ENGINE - LPT STAGE 1 (BLADED) WHEEL ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725886-0101	NO. 2 ENGINE - LPT STAGE 1 (BLADED) WHEEL ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										
725900-0101	NO. 1 ENGINE - NO. 7 CARBON SEAL ASSEMBLY									Component ATA:72
PN:23061737	MOS/MSC	01-Sep-17	O/C	TSN 0						
SN:NSN	HRS	8179.9	TSN 0							
	ENC	4374	TSN 0							
PROC. REF: GENERIC NO REF										
725900-0101	NO. 2 ENGINE - NO. 7 CARBON SEAL ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 72 - ENGINE											
725910-0101		NO. 1 ENGINE - ROLLER BEARING								Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	ENC	0	TSN 0								
PROC. REF: GENERIC NO REF											
725910-0101		NO. 2 ENGINE - ROLLER BEARING								Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	ENC	0	TSN 0								
PROC. REF: GENERIC NO REF											
726303-0101		NO. 1 ENGINE - RADIAL DRIVE QUILL SHAFT								Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	ENC	0	TSN 0								
PROC. REF: GENERIC NO REF											
726303-0101		NO. 2 ENGINE - RADIAL DRIVE QUILL SHAFT								Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	ENC	0	TSN 0								
PROC. REF: GENERIC NO REF											
727100-0101		NO. 1 ENGINE - RIGHT COMPRESSOR INNER DUCT ASSEMBLY								Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	ENC	0	TSN 0								
PROC. REF: MM 72-71-10, MM 72-71-10, MM 72-71-10, MM 72-71-10, MM 72-71-10, MM 72-71-10											
727100-0101		NO. 2 ENGINE - RIGHT COMPRESSOR INNER DUCT ASSEMBLY								Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	ENC	0	TSN 0								
PROC. REF: MM 72-71-10, MM 72-71-10, MM 72-71-10, MM 72-71-10, MM 72-71-10, MM 72-71-10											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 72 - ENGINE											
727101-0101			NO. 1 ENGINE - LEFT COMPRESSOR INNER DUCT ASSEMBLY						Component	ATA:72	
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: MM 72-71-10, MM 72-71-10, MM 72-71-10, MM 72-71-10, MM 72-71-10, MM 72-71-10											
727101-0101			NO. 2 ENGINE - LEFT COMPRESSOR INNER DUCT ASSEMBLY						Component	ATA:72	
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: MM 72-71-10, MM 72-71-10, MM 72-71-10, MM 72-71-10, MM 72-71-10, MM 72-71-10											
727102-0101			NO. 1 ENGINE - LOWER COMPRESSOR INNER DUCT ASSEMBLY						Component	ATA:72	
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: MM 72-71-10, MM 72-71-10, MM 72-71-10, MM 72-71-10, MM 72-71-10, MM 72-71-10											
727102-0101			NO. 2 ENGINE - LOWER COMPRESSOR INNER DUCT ASSEMBLY						Component	ATA:72	
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: MM 72-71-10, MM 72-71-10, MM 72-71-10, MM 72-71-10, MM 72-71-10, MM 72-71-10											
727300-0101			NO. 1 ENGINE - OUTER BYPASS DUCT ASSEMBLY						Component	ATA:72	
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: GENERIC NO REF											
727300-0101			NO. 2 ENGINE - OUTER BYPASS DUCT ASSEMBLY						Component	ATA:72	
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: GENERIC NO REF											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 72 - ENGINE											
727302-0101			NO. 1 ENGINE - BYPASS SUPPORT ASSEMBLY							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	ENC	0	TSN 0								
PROC. REF: MM 72-73-09, MM 72-73-09											
727302-0101			NO. 2 ENGINE - BYPASS SUPPORT ASSEMBLY							Component	ATA:72
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	ENC	0	TSN 0								
PROC. REF: MM 72-73-09, MM 72-73-09											
ATA 73 - ENGINE FUEL AND CONTROL											
73-11-00-960-001-A00			NO. 1 ENGINE - DISCARD OF ENGINE FUEL FILTER ELEMENT							Service	ATA:73
	MOS	13-Apr-22	SYSTEM								
	HRS	9739.4	2000 (+20/-20)	(11739.4)	11759.4	1248 (+20)	11843.6				
	ENC	5173									
PROC. REF: MM NO REF, AMM 73-11-01, AMM 73-11-00											
73-11-00-960-001-A00			NO. 2 ENGINE - DISCARD OF ENGINE FUEL FILTER ELEMENT							Service	ATA:73
	MOS	13-Apr-22	SYSTEM								
	HRS	9739.4	2000 (+20/-20)	(11739.4)	11759.4	1248 (+20)	11843.6				
	ENC	5173									
PROC. REF: MM NO REF, AMM 73-11-01, AMM 73-11-00											
73-11-10-130-001-A00			NO. 1 ENGINE - RESTORE (CLEANING) FUEL NOZZLES EXCEPT P/N 23075904, 23077006, 23087207, OR 23090046							Service	ATA:73
PN:23087207	MOS/MSC	N/A									
SN:UNKNOWN	HRS										
	ENC										
PROC. REF: AMM 73-11-10, MM 73-11-10, MM 73-11-10											
73-11-10-130-001-A00			NO. 2 ENGINE - RESTORE (CLEANING) FUEL NOZZLES EXCEPT P/N 23075904, 23077006, 23087207, OR 23090046							Service	ATA:73
PN:23087207	MOS/MSC	N/A									
SN:UNKNOWN	HRS										
	ENC										
PROC. REF: AMM 73-11-10, MM 73-11-10, MM 73-11-10											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 73 - ENGINE FUEL AND CONTROL										
73-11-10-130-001-A01 NO. 1 ENGINE - RESTORE (CLEANING) FUEL NOZZLES P/N 23075904, 23077006, 23087207, OR 23090046 ONLY										
PN:23087207	MOS	14-Jul-22						SYSTEM		Service ATA:73
SN:UNKNOWN	HRS	9811.6	10000		(19811.6) 19915.8		9320.2			
	ENC	5199								
PROC. REF: AMM 73-11-10, MM 73-11-10, MM 73-11-10										
73-11-10-130-001-A01 NO. 2 ENGINE - RESTORE (CLEANING) FUEL NOZZLES P/N 23075904, 23077006, 23087207, OR 23090046 ONLY										
PN:23087207	MOS	14-Jul-22						SYSTEM		Service ATA:73
SN:UNKNOWN	HRS	9811.6	10000		(19811.6) 19915.8		9320.2			
	ENC	5199								
PROC. REF: AMM 73-11-10, MM 73-11-10, MM 73-11-10										
73-21-00-211-001-A00 NO. 1 ENGINE - VISUALLY CHECK FUEL PUMP AND METERING UNIT FOR FUEL LEAKAGE										
	MOS	29-Jun-23						SYSTEM		Service ATA:73
	HRS	10057.3	1000		(11057.3) 11161.5		565.9			
	ENC	5329								
PROC. REF: AMM 73-21-00, MM 72-00-00										
73-21-00-211-001-A00 NO. 2 ENGINE - VISUALLY CHECK FUEL PUMP AND METERING UNIT FOR FUEL LEAKAGE										
	MOS	29-Jun-23						SYSTEM		Service ATA:73
	HRS	10057.3	1000		(11057.3) 11161.5		565.9			
	ENC	5329								
PROC. REF: AMM 73-21-00, MM 72-00-00										
73-21-06-720-001-A00 NO. 1 ENGINE - FUNCTIONALLY CHECK FUEL FILTER IMPENDING BYPASS INDICATOR SYSTEM										
	MOS	18-Aug-18						SYSTEM		Service ATA:73
	HRS	8620.9	3000		(11620.9) 11725.1		1129.5			
	ENC	4609								
PROC. REF: AMM 73-21-06, MM 73-37-10										
73-21-06-720-001-A00 NO. 2 ENGINE - FUNCTIONALLY CHECK FUEL FILTER IMPENDING BYPASS INDICATOR SYSTEM										
	MOS	18-Aug-18						SYSTEM		Service ATA:73
	HRS	8620.9	3000		(11620.9) 11725.1		1129.5			
	ENC	4609								
PROC. REF: AMM 73-21-06, MM 73-37-10										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 73 - ENGINE FUEL AND CONTROL										
73-22-01-720-003-A00 FUNCTIONALLY CHECK MULTI-FUNCTION DISPLAY FOR ENG() LT FAULT AND ENG() SCHED MAINT REPAIR MAINTENANCE MESSAGES Service ATA:73										
	MOS	16-Aug-24	12		16-Aug-25		274 d			
	HRS	10541.4	250		10791.4		195.8			
	AFL	5613								
PROC. REF: AMM 73-22-01										
73-30-04-220-001-A00 NO. 1 ENGINE - INSPECT (DETAILED INSPECTION) THE FADEC ANTI- VIBRATION MOUNTS Service ATA:73										
	MOS	17-Jan-17								
	HRS	7935.4	5000		(12935.4) 13039.6		2444			
	ENC	4242								
PROC. REF: AMM 73-30-04, MM 73-25-10, MM 73-25-10, MM 73-25-10										
73-30-04-220-001-A00 NO. 2 ENGINE - INSPECT (DETAILED INSPECTION) THE FADEC ANTI- VIBRATION MOUNTS Service ATA:73										
	MOS	17-Jan-17								
	HRS	7935.4	5000		(12935.4) 13039.6		2444			
	ENC	4242								
PROC. REF: AMM 73-30-04, MM 73-25-10, MM 73-25-10, MM 73-25-10										
731101-0101 NO. 1 ENGINE - NO. 1 FUEL NOZZLE ASSEMBLY Component ATA:73										
PN:23087207	MOS/MSC	14-Jul-22	O/C		TSO 0					
SN:VN1BCK0522	HRS	9811.6			TSO 0					
	ENC	5199			TSO 0					
PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10										
731101-0101 NO. 2 ENGINE - NO. 1 FUEL NOZZLE ASSEMBLY Component ATA:73										
PN:23087207	MOS/MSC	14-Jul-22	O/C		TSO 0					
SN:VN1BCE0573	HRS	9811.6			TSO 0					
	ENC	5199			TSO 0					
PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10										
731101-0102 NO. 1 ENGINE - NO. 2 FUEL NOZZLE ASSEMBLY Component ATA:73										
PN:23087207	MOS/MSC	14-Jul-22	O/C		TSO 0					
SN:VN1BCK0523	HRS	9811.6			TSO 0					
	ENC	5199			TSO 0					
PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 73 - ENGINE FUEL AND CONTROL											
731101-0102		NO. 2 ENGINE - NO. 2 FUEL NOZZLE ASSEMBLY								Component	ATA:73
PN:23087207	MOS/MSC	14-Jul-22	O/C	TSO 0							
SN:VN1BCE0574	HRS	9811.6		TSO 0							
	ENC	5199		TSO 0							
PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10											
731101-0103		NO. 1 ENGINE - NO. 3 FUEL NOZZLE ASSEMBLY								Component	ATA:73
PN:23087207	MOS/MSC	14-Jul-22	O/C	TSO 0							
SN:VN1BCK0524	HRS	9811.6		TSO 0							
	ENC	5199		TSO 0							
PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10											
731101-0103		NO. 2 ENGINE - NO. 3 FUEL NOZZLE ASSEMBLY								Component	ATA:73
PN:23087207	MOS/MSC	14-Jul-22	O/C	TSO 0							
SN:VN1BCE0575	HRS	9811.6		TSO 0							
	ENC	5199		TSO 0							
PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10											
731101-0104		NO. 1 ENGINE - NO. 4 FUEL NOZZLE ASSEMBLY								Component	ATA:73
PN:23087207	MOS/MSC	14-Jul-22	O/C	TSO 0							
SN:VN1BCK0529	HRS	9811.6		TSO 0							
	ENC	5199		TSO 0							
PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10											
731101-0104		NO. 2 ENGINE - NO. 4 FUEL NOZZLE ASSEMBLY								Component	ATA:73
PN:23087207	MOS/MSC	14-Jul-22	O/C	TSO 0							
SN:VN1BCE0581	HRS	9811.6		TSO 0							
	ENC	5199		TSO 0							
PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10											
731101-0105		NO. 1 ENGINE - NO. 5 FUEL NOZZLE ASSEMBLY								Component	ATA:73
PN:23087207	MOS/MSC	14-Jul-22	O/C	TSO 0							
SN:VN1BCK0765	HRS	9811.6		TSO 0							
	ENC	5199		TSO 0							
PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10											
731101-0105		NO. 2 ENGINE - NO. 5 FUEL NOZZLE ASSEMBLY								Component	ATA:73
PN:23087207	MOS/MSC	14-Jul-22	O/C	TSO 0							
SN:VN1BCE0584	HRS	9811.6		TSO 0							
	ENC	5199		TSO 0							
PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 73 - ENGINE FUEL AND CONTROL										
731101-0106 NO. 1 ENGINE - NO. 6 FUEL NOZZLE ASSEMBLY Component ATA:73										
PN:23087207	MOS/MSC		14-Jul-22	O/C	TSO 0					
SN:VN1BCK0768	HRS		9811.6		TSO 0					
	ENC		5199		TSO 0					
PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10										
731101-0106 NO. 2 ENGINE - NO. 6 FUEL NOZZLE ASSEMBLY Component ATA:73										
PN:23087207	MOS/MSC		14-Jul-22	O/C	TSO 0					
SN:VN1BCD1026	HRS		9811.6		TSO 0					
	ENC		5199		TSO 0					
PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10										
731101-0107 NO. 1 ENGINE - NO. 7 FUEL NOZZLE ASSEMBLY Component ATA:73										
PN:23087207	MOS/MSC		14-Jul-22	O/C	TSO 0					
SN:VN1BCK0769	HRS		9811.6		TSO 0					
	ENC		5199		TSO 0					
PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10										
731101-0107 NO. 2 ENGINE - NO. 7 FUEL NOZZLE ASSEMBLY Component ATA:73										
PN:23087207	MOS/MSC		14-Jul-22	O/C	TSO 0					
SN:VN1BCD1027	HRS		9811.6		TSO 0					
	ENC		5199		TSO 0					
PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10										
731101-0108 NO. 1 ENGINE - NO. 8 FUEL NOZZLE ASSEMBLY Component ATA:73										
PN:23087207	MOS/MSC		14-Jul-22	O/C	TSO 0					
SN:VN1BCK0770	HRS		9811.6		TSO 0					
	ENC		5199		TSO 0					
PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10										
731101-0108 NO. 2 ENGINE - NO. 8 FUEL NOZZLE ASSEMBLY Component ATA:73										
PN:23087207	MOS/MSC		14-Jul-22	O/C	TSO 0					
SN:VN1BCD1028	HRS		9811.6		TSO 0					
	ENC		5199		TSO 0					
PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10										
731101-0109 NO. 1 ENGINE - NO. 9 FUEL NOZZLE ASSEMBLY Component ATA:73										
PN:23087207	MOS/MSC		14-Jul-22	O/C	TSO 0					
SN:VN1BCK0771	HRS		9811.6		TSO 0					
	ENC		5199		TSO 0					
PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 73 - ENGINE FUEL AND CONTROL											
731101-0109		NO. 2 ENGINE - NO. 9 FUEL NOZZLE ASSEMBLY								Component	ATA:73
PN:23087207	MOS/MSC	14-Jul-22	O/C	TSO 0							
SN:VN1BCD1029	HRS	9811.6		TSO 0							
	ENC	5199		TSO 0							
PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10											
731101-0110		NO. 1 ENGINE - NO. 10 FUEL NOZZLE ASSEMBLY								Component	ATA:73
PN:23087207	MOS/MSC	14-Jul-22	O/C	TSO 0							
SN:VN1BCK0777	HRS	9811.6		TSO 0							
	ENC	5199		TSO 0							
PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10											
731101-0110		NO. 2 ENGINE - NO. 10 FUEL NOZZLE ASSEMBLY								Component	ATA:73
PN:23087207	MOS/MSC	14-Jul-22	O/C	TSO 0							
SN:VN1BCD1032	HRS	9811.6		TSO 0							
	ENC	5199		TSO 0							
PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10											
731101-0111		NO. 1 ENGINE - NO. 11 FUEL NOZZLE ASSEMBLY								Component	ATA:73
PN:23087207	MOS/MSC	14-Jul-22	O/C	TSO 0							
SN:VN1BCK0779	HRS	9811.6		TSO 0							
	ENC	5199		TSO 0							
PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10											
731101-0111		NO. 2 ENGINE - NO. 11 FUEL NOZZLE ASSEMBLY								Component	ATA:73
PN:23087207	MOS/MSC	14-Jul-22	O/C	TSO 0							
SN:VN1BCD1033	HRS	9811.6		TSO 0							
	ENC	5199		TSO 0							
PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10											
731101-0112		NO. 1 ENGINE - NO. 12 FUEL NOZZLE ASSEMBLY								Component	ATA:73
PN:23087207	MOS/MSC	14-Jul-22	O/C	TSO 0							
SN:VN1BCK0780	HRS	9811.6		TSO 0							
	ENC	5199		TSO 0							
PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10											
731101-0112		NO. 2 ENGINE - NO. 12 FUEL NOZZLE ASSEMBLY								Component	ATA:73
PN:23087207	MOS/MSC	14-Jul-22	O/C	TSO 0							
SN:VN1BCD1035	HRS	9811.6		TSO 0							
	ENC	5199		TSO 0							
PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 73 - ENGINE FUEL AND CONTROL											
731101-0113		NO. 1 ENGINE - NO. 13 FUEL NOZZLE ASSEMBLY								Component	ATA:73
PN:23087207	MOS/MSC		14-Jul-22	O/C	TSO 0						
SN:VN1BCK0781	HRS		9811.6		TSO 0						
	ENC		5199		TSO 0						
PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10											
731101-0113		NO. 2 ENGINE - NO. 13 FUEL NOZZLE ASSEMBLY								Component	ATA:73
PN:23087207	MOS/MSC		14-Jul-22	O/C	TSO 0						
SN:VN1BCD1036	HRS		9811.6		TSO 0						
	ENC		5199		TSO 0						
PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10											
731101-0114		NO. 1 ENGINE - NO. 14 FUEL NOZZLE ASSEMBLY								Component	ATA:73
PN:23087207	MOS/MSC		14-Jul-22	O/C	TSO 0						
SN:VN1BCK0782	HRS		9811.6		TSO 0						
	ENC		5199		TSO 0						
PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10											
731101-0114		NO. 2 ENGINE - NO. 14 FUEL NOZZLE ASSEMBLY								Component	ATA:73
PN:23087207	MOS/MSC		14-Jul-22	O/C	TSO 0						
SN:VN1BCD1037	HRS		9811.6		TSO 0						
	ENC		5199		TSO 0						
PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10											
731101-0115		NO. 1 ENGINE - NO. 15 FUEL NOZZLE ASSEMBLY								Component	ATA:73
PN:23087207	MOS/MSC		14-Jul-22	O/C	TSO 0						
SN:VN1BCK0783	HRS		9811.6		TSO 0						
	ENC		5199		TSO 0						
PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10											
731101-0115		NO. 2 ENGINE - NO. 15 FUEL NOZZLE ASSEMBLY								Component	ATA:73
PN:23087207	MOS/MSC		14-Jul-22	O/C	TSO 0						
SN:VN1BCD1042	HRS		9811.6		TSO 0						
	ENC		5199		TSO 0						
PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10											
731101-0116		NO. 1 ENGINE - NO. 16 FUEL NOZZLE ASSEMBLY								Component	ATA:73
PN:23087207	MOS/MSC		14-Jul-22	O/C	TSO 0						
SN:VN1BCK0784	HRS		9811.6		TSO 0						
	ENC		5199		TSO 0						
PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 73 - ENGINE FUEL AND CONTROL										
731101-0116 NO. 2 ENGINE - NO. 16 FUEL NOZZLE ASSEMBLY Component ATA:73										
PN:23087207	MOS/MSC		14-Jul-22	O/C	TSO 0					
SN:VN1BCD1043	HRS		9811.6		TSO 0					
	ENC		5199		TSO 0					
PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10										
731101-0201 NO. 1 ENGINE - FUEL NOZZLE ASSEMBLY Component ATA:73										
PN:23087207	MOS/MSC		14-Jul-22	O/C						
SN:UNKNOWN	HRS		9811.6							
	ENC		5199							
PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10										
731101-0201 NO. 2 ENGINE - FUEL NOZZLE ASSEMBLY Component ATA:73										
PN:23087207	MOS/MSC		14-Jul-22	O/C						
SN:UNKNOWN	HRS		9811.6							
	ENC		5199							
PROC. REF: AMM 73-13-01, MM 73-11-10, MM 73-11-10										
732101-0101 NO. 1 ENGINE - METERING UNIT AND FUEL PUMP Component ATA:73										
PN:23077658	MOS/MSC		25-Sep-07	O/C	TSN 0					
SN:SCP06-034	HRS		0		TSN 0					
	ENC		0		TSN 0					
PROC. REF: AMM 73-21-01, MM 73-21-10, MM 73-21-10										
732101-0101 NO. 2 ENGINE - METERING UNIT AND FUEL PUMP Component ATA:73										
PN:23077658	MOS/MSC		25-Sep-07	O/C	TSN 0					
SN:SCP07-034	HRS		0		TSN 0					
	ENC		0		TSN 0					
PROC. REF: AMM 73-21-01, MM 73-21-10, MM 73-21-10										
732200-0101 LEFT ENGINE PRESSURE DERIVATION SENSOR Component ATA:73										
PN:PN	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: NDT GENERIC										
732200-0102 LEFT ENGINE PRESSURE DERIVATION SENSOR Component ATA:73										
PN:PN	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:UNKNOWN	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: NDT GENERIC										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 73 - ENGINE FUEL AND CONTROL										
732200-0103 RIGHT ENGINE PRESSURE DERIVATION SENSOR Component ATA:73										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										
732200-0104 RIGHT ENGINE PRESSURE DERIVATION SENSOR Component ATA:73										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										
732200-0201 REAR FUS PRESSURE TRANSDUCER - ENGINE SYSTEM TRANSDUCER Component ATA:73										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										
732201-0201^U L ENG 1A FADEC, BASIC, ELECTRICAL CONTROL UNIT Component ATA:73										
PN:23078837	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 73-22-01										
732201-0202^U L ENG 1B FADEC, BASIC, ELECTRICAL CONTROL UNIT Component ATA:73										
PN:23078837	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 73-22-01										
732201-0203^U R ENG 2A FADEC, BASIC, ELECTRICAL CONTROL UNIT Component ATA:73										
PN:23078837	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 73-22-01										
732201-0204^U R ENG 2B FADEC, BASIC, ELECTRICAL CONTROL UNIT Component ATA:73										
PN:23078837	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 73-22-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 73 - ENGINE FUEL AND CONTROL										
732501-0101 NO. 1 ENGINE - NO. 1 FADEC Component ATA:73										
PN:23093341	MOS/MSC		22-Oct-21	O/C						
SN:BX162257	HRS		9600							
	ENC		5089							
PROC. REF: AMM 73-22-01, MM 73-25-10, MM 73-25-10										
732501-0101 NO. 2 ENGINE - NO. 1 FADEC Component ATA:73										
PN:23093341	MOS/MSC		22-Oct-21	O/C						
SN:BX162259	HRS		9600							
	ENC		5089							
PROC. REF: AMM 73-22-01, MM 73-25-10, MM 73-25-10										
732503-0101 NO. 1 ENGINE - NO. 2 FADEC Component ATA:73										
PN:23093341	MOS/MSC		22-Oct-21	O/C						
SN:BX162278	HRS		9600							
	ENC		5089							
PROC. REF: AMM 73-22-01, MM 73-25-10, MM 73-25-10										
732503-0101 NO. 2 ENGINE - NO. 2 FADEC Component ATA:73										
PN:23093341	MOS/MSC		22-Oct-21	O/C						
SN:BX162246	HRS		9600							
	ENC		5089							
PROC. REF: AMM 73-22-01, MM 73-25-10, MM 73-25-10										
732510-0201 NO. 1 ENGINE - INSPECTION OF FADEC FAULT Service ATA:73										
	MOS/MSC		25-Sep-07	A/R						
	HRS		0							
	ENC		0							
PROC. REF: MM 73-25-10										
732510-0201 NO. 2 ENGINE - INSPECTION OF FADEC FAULT Service ATA:73										
	MOS/MSC		25-Sep-07	A/R						
	HRS		0							
	ENC		0							
PROC. REF: MM 73-25-10										
733001-0101 NO. 1 ENGINE - FUEL FLOWMETER Component ATA:73										
PN:23052613	MOS/MSC		25-Sep-07	O/C	TSN 0					
SN:JQ-12321	HRS		0		TSN 0					
	ENC		0		TSN 0					
PROC. REF: AMM 73-31-01, MM 73-35-10, MM 73-35-10										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 73 - ENGINE FUEL AND CONTROL											
733001-0101		NO. 2 ENGINE - FUEL FLOWMETER								Component	ATA:73
PN:23052613	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:JQ-12299	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: AMM 73-31-01, MM 73-35-10, MM 73-35-10											
733100-0101		NO. 1 ENGINE - FUEL TEMPERATURE SENSOR								Component	ATA:73
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: AMM 73-32-01, MM 73-31-10, MM 73-31-10											
733100-0101		NO. 2 ENGINE - FUEL TEMPERATURE SENSOR								Component	ATA:73
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: AMM 73-32-01, MM 73-31-10, MM 73-31-10											
ATA 74 - IGNITION											
74-21-01-960-001-A00		NO. 1 ENGINE - DISCARD THE IGNITERS								Service	ATA:74
	MOS	17-Jan-17						SYSTEM			
	HRS	7935.4	4000		(11935.4)		1444				
					12039.6						
	ENC	4242									
PROC. REF: AMM 74-21-01, MM 74-21-10, MM 74-21-10, MM 74-21-10, MM 74-21-10											
74-21-01-960-001-A00		NO. 2 ENGINE - DISCARD THE IGNITERS								Service	ATA:74
	MOS	17-Jan-17						SYSTEM			
	HRS	7935.4	4000		(11935.4)		1444				
					12039.6						
	ENC	4242									
PROC. REF: AMM 74-21-01, MM 74-21-10, MM 74-21-10, MM 74-21-10, MM 74-21-10											
741102-0101		NO. 1 ENGINE - PMA ROTOR								Component	ATA:74
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: MM 74-11-10, MM 74-11-10											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 74 - IGNITION										
741102-0101 NO. 2 ENGINE - PMA ROTOR Component ATA:74										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 74-11-10, MM 74-11-10										
741103-0101 NO. 1 ENGINE - (PMA) ALTERNATOR STATOR Component ATA:74										
PN:23075489	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UN11285	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 74-11-15, MM 74-11-15										
741103-0101 NO. 2 ENGINE - (PMA) ALTERNATOR STATOR Component ATA:74										
PN:23075489	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UN11296	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 74-11-15, MM 74-11-15										
741301-0101 NO. 1 ENGINE - LEFT EXCITOR IGNITION Component ATA:74										
PN:23077617	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UY06404681	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 74-13-01, MM 74-13-10, MM 74-13-10										
741301-0101 NO. 2 ENGINE - LEFT EXCITOR IGNITION Component ATA:74										
PN:23077617	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UY06404672	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 74-13-01, MM 74-13-10, MM 74-13-10										
741303-0101 NO. 1 ENGINE - RIGHT EXCITOR IGNITION Component ATA:74										
PN:23077617	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UY06485105	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 74-13-01, MM 74-13-10, MM 74-13-10										
741303-0101 NO. 2 ENGINE - RIGHT EXCITOR IGNITION Component ATA:74										
PN:23077617	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UY06344426	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 74-13-01, MM 74-13-10, MM 74-13-10										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 74 - IGNITION											
742101-0101		NO. 1 ENGINE - TOP IGNITOR								Component	ATA:74
PN:23062672	MOS/MSC	17-Jan-17	O/C	TSN 0							
SN:JH1600694	HRS	7935.4		TSN 0							
	ENC	4242		TSN 0							
PROC. REF: AMM 74-21-01, MM 74-21-10, MM 74-21-10											
742101-0101		NO. 2 ENGINE - TOP IGNITOR								Component	ATA:74
PN:23062672	MOS/MSC	17-Jan-17	O/C	TSN 0							
SN:JH1601674	HRS	7935.4		TSN 0							
	ENC	4242		TSN 0							
PROC. REF: AMM 74-21-01, MM 74-21-10, MM 74-21-10											
742103-0101		NO. 1 ENGINE - BOTTOM IGNITOR								Component	ATA:74
PN:23062672	MOS/MSC	17-Jan-17	O/C	TSN 0							
SN:JH1601513	HRS	7935.4		TSN 0							
	ENC	4242		TSN 0							
PROC. REF: AMM 74-21-01, MM 74-13-10, MM 74-21-10											
742103-0101		NO. 2 ENGINE - BOTTOM IGNITOR								Component	ATA:74
PN:23062672	MOS/MSC	17-Jan-17	O/C	TSN 0							
SN:JH1601492	HRS	7935.4		TSN 0							
	ENC	4242		TSN 0							
PROC. REF: AMM 74-21-01, MM 74-13-10, MM 74-21-10											
742105-0101		NO. 1 ENGINE - SPARK IGNITER (A) LEAD ASSEMBLY								Component	ATA:74
PN:23054367	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UM06477887	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: AMM 74-21-02, MM 74-21-15, MM 74-21-15											
742105-0101		NO. 2 ENGINE - SPARK IGNITER (A) LEAD ASSEMBLY								Component	ATA:74
PN:23054367	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UM06477892	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: AMM 74-21-02, MM 74-21-15, MM 74-21-15											
742107-0101		NO. 1 ENGINE - SPARK IGNITER (B) LEAD ASSEMBLY								Component	ATA:74
PN:23054368	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UM06417221	HRS	0		TSN 0							
	ENC	0		TSN 0							
PROC. REF: AMM 74-21-02, MM 74-21-20, MM 74-21-20											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 74 - IGNITION										
742107-0101 NO. 2 ENGINE - SPARK IGNITER (B) LEAD ASSEMBLY Component ATA:74										
PN:23054368	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UM06417225	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 74-21-02, MM 74-21-20, MM 74-21-20										
ATA 75 - AIR										
753101-0101 NO. 1 ENGINE - BLEED AIR-COMPR ACCEL VALVE ASSEMBLY Component ATA:75										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 75-31-02, MM 75-31-15, MM 75-31-15										
753101-0101 NO. 2 ENGINE - BLEED AIR-COMPR ACCEL VALVE ASSEMBLY Component ATA:75										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 75-31-02, MM 75-31-15, MM 75-31-15										
753302-0101 NO. 1 ENGINE - INT LUDT HYDRAULIC ACTUATOR ASSEMBLY Component ATA:75										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
753302-0101 NO. 2 ENGINE - INT LUDT HYDRAULIC ACTUATOR ASSEMBLY Component ATA:75										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
754301-0101 NO. 1 ENGINE - NO. 1 P2.5 PRESSURE TRANSDUCER SENSOR Component ATA:75										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 75-43-10, MM 75-43-10										
754301-0101 NO. 2 ENGINE - NO. 1 P2.5 PRESSURE TRANSDUCER SENSOR Component ATA:75										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 75-43-10, MM 75-43-10										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 75 - AIR											
754302-0101		NO. 1 ENGINE - NO. 2 P2.5 PRESSURE TRANSDUCER SENSOR								Component	ATA:75
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	ENC	0	TSN 0								
PROC. REF: MM 75-43-10, MM 75-43-10											
754302-0101		NO. 2 ENGINE - NO. 2 P2.5 PRESSURE TRANSDUCER SENSOR								Component	ATA:75
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:UNKNOWN	HRS	0	TSN 0								
	ENC	0	TSN 0								
PROC. REF: MM 75-43-10, MM 75-43-10											
754303-0101		NO. 1 ENGINE - NO. 1 P2 PRESSURE TRANSDUCER SENSOR								Component	ATA:75
PN:23055446	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:QW400480S	HRS	0	TSN 0								
	ENC	0	TSN 0								
PROC. REF: MM 75-43-10, MM 75-43-10											
754303-0101		NO. 2 ENGINE - NO. 1 P2 PRESSURE TRANSDUCER SENSOR								Component	ATA:75
PN:23055446	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:QW440459S	HRS	0	TSN 0								
	ENC	0	TSN 0								
PROC. REF: MM 75-43-10, MM 75-43-10											
754303-0102		NO. 1 ENGINE - NO. 2 P2 PRESSURE TRANSDUCER SENSOR								Component	ATA:75
PN:23055446	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:QW400473S	HRS	0	TSN 0								
	ENC	0	TSN 0								
PROC. REF: MM 75-43-10, MM 75-43-10											
754303-0102		NO. 2 ENGINE - NO. 2 P2 PRESSURE TRANSDUCER SENSOR								Component	ATA:75
PN:23055446	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:QW400458S	HRS	0	TSN 0								
	ENC	0	TSN 0								
PROC. REF: MM 75-43-10, MM 75-43-10											
754310-0101		NO. 1 ENGINE - INSPECT THE COMPRESSOR-INLET-PRESSURE-SENSOR (P2.5 SENSOR)								Service	ATA:75
	MOS/MSC	25-Sep-07	N/R								
	HRS	0									
	ENC	0									
PROC. REF: MM 75-43-10											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 75 - AIR											
754310-0101			NO. 2 ENGINE - INSPECT THE COMPRESSOR-INLET-PRESSURE-SENSOR (P2.5 SENSOR)						Service		ATA:75
	MOS/MSC	25-Sep-07	N/R								
	HRS	0									
	ENC	0									
PROC. REF: MM 75-43-10											
ATA 76 - ENGINE CONTROLS											
76-11-04-720-001-A00 ^S			FUNCTIONALLY CHECK FRICTION LOCK ASSEMBLY FOR PRE-LOAD VALUE.						Service		ATA:76
	MOS/MSC	29-Jun-23	N/A								
	HRS	10161.5									
	AFL	5401									
PROC. REF: AMM 76-11-04											
76-12-00-710-001-A00 ^S			OPERATIONAL CHECK WOW INPUT SIGNAL TO FADEC						Service		ATA:76
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	4000 (+20/-20)								
	AFL	5401	2000 (+20/-20)								
PROC. REF: AMM 76-12-00											
76-12-01-212-001-A00 ^S			GENERAL VISUAL INSPECTION RESOLVERS ATTACHMENTS TO THE THRUST LEVERS.(NOTE: CHECK TOGETHER WITH TASK 78-33-00-720 -001-A00)						Service		ATA:76
	MOS	29-Jun-23	96 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	4000 (+20/-20)								
	AFL	5401	2000 (+20/-20)								
PROC. REF: AMM 76-12-01											
76-13-03-710-001-A00 ^S			OPERATIONAL CHECK IDLE LOCKOUT MICROSWITCH						Service		ATA:76
	MOS	16-Aug-24	12 (+15d/-15d)					LOW UTILIZATION			
	HRS	10541.4	500 (+20/-20)								
	AFL	5613									
PROC. REF: AMM 76-13-03											
76-20-00-710-001-A00 ^S			OPERATIONAL CHECK EMERGENCY SHUTDOWN SYSTEM.						Service		ATA:76
	MOS	29-Jun-23	24 (+15d/-15d)					LOW UTILIZATION			
	HRS	10161.5	1000 (+20/-20)								
	AFL	5401									
PROC. REF: AMM 76-20-00											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 76 - ENGINE CONTROLS										
761000-0101 CREW CAB CONTROL BOX,-THRUST REVERSER/GUST LOCK,ENGINE,CTL CONSOL ASSEMBLY Component ATA:76										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 76-11-02										
761000-0201 C FLOOR BOX -POWER SUPPLY DIODE ASSEMBLY Component ATA:76										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 76-12-03										
761000-0301 CENTER PEDESTAL QUADRANT ASSY-ENGINE CENTRAL,MAIN CONSOLE,COCKPIT QUADRANT Component ATA:76										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										
761100-0101 NO. 1 ENGINE - INT ENGINE (B) HARNESS ASSEMBLY Component ATA:76										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 76-11-15, MM 76-11-15										
761100-0101 NO. 2 ENGINE - INT ENGINE (B) HARNESS ASSEMBLY Component ATA:76										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 76-11-15, MM 76-11-15										
761101-0101 NO. 1 ENGINE - ENGINE CONTROL WIRING HARNESS Component ATA:76										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 76-11-10, MM 76-11-10, MM 76-11-15, MM 76-11-15										
761101-0101 NO. 2 ENGINE - ENGINE CONTROL WIRING HARNESS Component ATA:76										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 76-11-10, MM 76-11-10, MM 76-11-15, MM 76-11-15										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 76 - ENGINE CONTROLS										
761102-0101 NO. 1 ENGINE - EXT ENGINE WIRING HARNESS ASSEMBLY Component ATA:76										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 76-11-20, MM 76-11-20, MM 76-11-20, MM 76-11-20, MM 76-11-25, MM 76-11-25, MM 76-11-25, MM 76-11-25										
761102-0101 NO. 2 ENGINE - EXT ENGINE WIRING HARNESS ASSEMBLY Component ATA:76										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 76-11-20, MM 76-11-20, MM 76-11-20, MM 76-11-20, MM 76-11-25, MM 76-11-25, MM 76-11-25, MM 76-11-25										
761103-0101 NO. 1 ENGINE - INT ENGINE (A) HARNESS ASSEMBLY Component ATA:76										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 76-11-10, MM 76-11-10										
761103-0101 NO. 2 ENGINE - INT ENGINE (A) HARNESS ASSEMBLY Component ATA:76										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 76-11-10, MM 76-11-10										
761200-0101 OVERH P CONTROL ASSY-POWER PLANT CONTROL,COCKPIT MODULE Component ATA:76										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 76-12-04										
761200-0201 CREW CAB THRUST RATING SELECTION MODULE Component ATA:76										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 76-12-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 76 - ENGINE CONTROLS										
761301-0101 NO. 1 ENGINE - EXT-ENGINE INDICATING HARNESS ASSEMBLY Component ATA:76										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 76-13-15, MM 76-13-15, MM 76-13-15, MM 76-13-15										
761301-0101 NO. 2 ENGINE - EXT-ENGINE INDICATING HARNESS ASSEMBLY Component ATA:76										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 76-13-15, MM 76-13-15, MM 76-13-15, MM 76-13-15										
761302-0101 NO. 1 ENGINE - INT-ENG INDICATING HARNESS ASSEMBLY Component ATA:76										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 76-13-10, MM 76-13-10										
761302-0101 NO. 2 ENGINE - INT-ENG INDICATING HARNESS ASSEMBLY Component ATA:76										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 76-13-10, MM 76-13-10										
ATA 77 - ENGINE INDICATING										
771100-0101 NO. 1 ENGINE - NO. 1 GAS PRODUCER SENSOR Component ATA:77										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 77-11-10, MM 77-11-10										
771100-0101 NO. 2 ENGINE - NO. 1 GAS PRODUCER SENSOR Component ATA:77										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 77-11-10, MM 77-11-10										
771101-0101 NO. 1 ENGINE - NO. 2 GAS PRODUCER SENSOR Component ATA:77										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 77-11-10, MM 77-11-10										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 77 - ENGINE INDICATING										
771101-0101 NO. 2 ENGINE - NO. 2 GAS PRODUCER SENSOR Component ATA:77										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 77-11-10, MM 77-11-10										
771103-0101 NO. 1 ENGINE - NO. 1 FAN SPEED PICKUP SENSOR Component ATA:77										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 77-11-02, MM 77-11-15, MM 77-11-15										
771103-0101 NO. 2 ENGINE - NO. 1 FAN SPEED PICKUP SENSOR Component ATA:77										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 77-11-02, MM 77-11-15, MM 77-11-15										
771105-0101 NO. 1 ENGINE - NO. 2 FAN SPEED PICKUP SENSOR Component ATA:77										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 77-11-02, MM 77-11-15, MM 77-11-15										
771105-0101 NO. 2 ENGINE - NO. 2 FAN SPEED PICKUP SENSOR Component ATA:77										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 77-11-02, MM 77-11-15, MM 77-11-15										
772101-0101 NO. 1 ENGINE - NO. 1 TURBINE THERMOCOUPLE Component ATA:77										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10										
772101-0101 NO. 2 ENGINE - NO. 1 TURBINE THERMOCOUPLE Component ATA:77										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 77 - ENGINE INDICATING										
772101-0102 NO. 1 ENGINE - NO. 2 TURBINE THERMOCOUPLE Component ATA:77										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10										
772101-0102 NO. 2 ENGINE - NO. 2 TURBINE THERMOCOUPLE Component ATA:77										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10										
772101-0103 NO. 1 ENGINE - NO. 3 TURBINE THERMOCOUPLE Component ATA:77										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10										
772101-0103 NO. 2 ENGINE - NO. 3 TURBINE THERMOCOUPLE Component ATA:77										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10										
772101-0104 NO. 1 ENGINE - NO. 4 TURBINE THERMOCOUPLE Component ATA:77										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10										
772101-0104 NO. 2 ENGINE - NO. 4 TURBINE THERMOCOUPLE Component ATA:77										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10										
772101-0105 NO. 1 ENGINE - NO. 5 TURBINE THERMOCOUPLE Component ATA:77										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 77 - ENGINE INDICATING										
772101-0105 NO. 2 ENGINE - NO. 5 TURBINE THERMOCOUPLE Component ATA:77										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10										
772101-0106 NO. 1 ENGINE - NO. 6 TURBINE THERMOCOUPLE Component ATA:77										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10										
772101-0106 NO. 2 ENGINE - NO. 6 TURBINE THERMOCOUPLE Component ATA:77										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10										
772101-0107 NO. 1 ENGINE - NO. 7 TURBINE THERMOCOUPLE Component ATA:77										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10										
772101-0107 NO. 2 ENGINE - NO. 7 TURBINE THERMOCOUPLE Component ATA:77										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10										
772101-0108 NO. 1 ENGINE - NO. 8 TURBINE THERMOCOUPLE Component ATA:77										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10										
772101-0108 NO. 2 ENGINE - NO. 8 TURBINE THERMOCOUPLE Component ATA:77										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 77 - ENGINE INDICATING										
772101-0109 NO. 1 ENGINE - NO. 9 TURBINE THERMOCOUPLE Component ATA:77										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10										
772101-0109 NO. 2 ENGINE - NO. 9 TURBINE THERMOCOUPLE Component ATA:77										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10										
772101-0110 NO. 1 ENGINE - NO. 10 TURBINE THERMOCOUPLE Component ATA:77										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10										
772101-0110 NO. 2 ENGINE - NO. 10 TURBINE THERMOCOUPLE Component ATA:77										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10										
772101-0111 NO. 1 ENGINE - NO. 11 TURBINE THERMOCOUPLE Component ATA:77										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10										
772101-0111 NO. 2 ENGINE - NO. 11 TURBINE THERMOCOUPLE Component ATA:77										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10										
772101-0112 NO. 1 ENGINE - NO. 12 TURBINE THERMOCOUPLE Component ATA:77										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 77 - ENGINE INDICATING										
772101-0112 NO. 2 ENGINE - NO. 12 TURBINE THERMOCOUPLE Component ATA:77										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10										
772101-0113 NO. 1 ENGINE - NO. 13 TURBINE THERMOCOUPLE Component ATA:77										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10										
772101-0113 NO. 2 ENGINE - NO. 13 TURBINE THERMOCOUPLE Component ATA:77										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10										
772101-0114 NO. 1 ENGINE - NO. 14 TURBINE THERMOCOUPLE Component ATA:77										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10										
772101-0114 NO. 2 ENGINE - NO. 14 TURBINE THERMOCOUPLE Component ATA:77										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10										
772101-0115 NO. 1 ENGINE - NO. 15 TURBINE THERMOCOUPLE Component ATA:77										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10										
772101-0115 NO. 2 ENGINE - NO. 15 TURBINE THERMOCOUPLE Component ATA:77										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 77 - ENGINE INDICATING										
772101-0116 NO. 1 ENGINE - NO. 16 TURBINE THERMOCOUPLE Component ATA:77										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10										
772101-0116 NO. 2 ENGINE - NO. 16 TURBINE THERMOCOUPLE Component ATA:77										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10										
772101-0201 NO. 1 ENGINE - TURBINE (1-16) THERMOCOUPLE Component ATA:77										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10										
772101-0201 NO. 2 ENGINE - TURBINE (1-16) THERMOCOUPLE Component ATA:77										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 77-21-01, MM 77-21-10, MM 77-21-10										
772102-0101 NO. 1 ENGINE - T/C WIRING HARNESS Component ATA:77										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 77-21-02, MM 77-21-15, MM 77-21-15, MM 77-21-20, MM 77-21-20										
772102-0101 NO. 2 ENGINE - T/C WIRING HARNESS Component ATA:77										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 77-21-02, MM 77-21-15, MM 77-21-15, MM 77-21-20, MM 77-21-20										
772103-0101 NO. 1 ENGINE - T/C WIRING ASSEMBLY Component ATA:77										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 77-21-02, MM 77-21-15, MM 77-21-15, MM 77-21-20, MM 77-21-20										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 77 - ENGINE INDICATING										
772103-0101 NO. 2 ENGINE - T/C WIRING ASSEMBLY Component ATA:77										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 77-21-02, MM 77-21-15, MM 77-21-15, MM 77-21-20, MM 77-21-20										
774000-0101 REAR VIBRATION MONITORING-ENGINE,EVMU,REAR FUSLG I UNIT Component ATA:77										
PN:241-244-013-002	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:AC25773	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 77-41-03										
774102-0101 NO. 1 ENGINE - ACCELEROMETER VIBRATION SENSOR Component ATA:77										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
774102-0101 NO. 2 ENGINE - ACCELEROMETER VIBRATION SENSOR Component ATA:77										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
774102-0102 NO. 1 ENGINE - ACCELEROMETER VIBRATION SENSOR Component ATA:77										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
774102-0102 NO. 2 ENGINE - ACCELEROMETER VIBRATION SENSOR Component ATA:77										
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
ATA 78 - EXHAUST										
78-10-01-212-002-A00 INSPECT (GENERAL VISUAL) PLAIN EXHAUST ASSY FOR DAMAGE, FAILURE OR IRREGULARITIES.(NOTE : NOT APPLICABLE TO AIRCRAFT WITH THRUST REVERSERS INSTALLED). Service ATA:78										
	MOS/MSC	15-Aug-13	N/A					SYSTEM		
	HRS	6643.4								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 78 - EXHAUST										
	AFL	3572								
PROC. REF: AMM 78-10-01										PKG:6020
78-31-00-220-001-A00 ^S	INSPECT (DETAILED INSPECTION) THRUST REVERSER STRUCTURE									Service ATA:78
MOS	06-Jul-19	72 (+15d/-15d)						LOW UTILIZATION		
HRS	9057.4	3000 (+20/-20)								
AFL	4853	1500 (+20/-20)								
PROC. REF: AMM 78-31-00										PKG:5012,6020
78-32-00-211-001-A00 ^S	VISUAL CHECK THRUST REVERSER 1RY AND 3RY LOCKS									Service ATA:78
MOS	16-Aug-24	12 (+15d/-15d)						LOW UTILIZATION		
HRS	10541.4	500 (+20/-20)								
AFL	5613									
PROC. REF: AMM 78-32-00										PKG:5002
78-32-00-710-001-A00 ^S	OPERATIONAL CHECK THRUST REVERSER (TR) SECONDARY (2RY) AND TERTIARY (3RY) LOCKS									Service ATA:78
MOS	16-Aug-24	12 (+15d/-15d)						LOW UTILIZATION		
HRS	10541.4	500 (+20/-20)								
AFL	5613									
PROC. REF: AMM 78-32-00										PKG:5002
78-33-00-710-001-A00 ^S	OPERATIONAL CHECK AIR/GROUND INPUT SIGNAL TO THRUST REVERSER (TR) SYSTEM (CMR)									Service ATA:78
MOS	16-Aug-24	12 (+15d/-15d)						LOW UTILIZATION		
HRS	10541.4	500 (+20/-20)								
AFL	5613									
PROC. REF: AMM 78-33-00										PKG:5002
78-33-00-710-002-A00 ^S	OPERATIONAL CHECK WHEEL-SPEED INPUT SIGNAL TO THE THRUST REVERSER SYSTEM (CMR)									Service ATA:78
MOS	16-Aug-24	12 (+15d/-15d)						LOW UTILIZATION		
HRS	10541.4	500 (+20/-20)								
AFL	5613									
PROC. REF: AMM 78-33-00										PKG:5002
78-33-00-720-001-A00 ^S	FUNCTIONAL CHECK THRUST-REVERSER (TR) CONTROL-LEVER MICROSWITCHES									Service ATA:78
MOS	29-Jun-23	96 (+15d/-15d)						LOW UTILIZATION		
HRS	10161.5	4000 (+20/-20)								
AFL	5401	2000 (+20/-20)								
PROC. REF: AMM 78-33-00										PKG:5016,6032

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 78 - EXHAUST										
78-33-01-710-001-A00 ^S	OPERATIONAL CHECK THRUST REVERSER ISOLATION CONTROL UNIT (ICU) (CMR)								Service	ATA:78
	MOS	16-Aug-24	12 (+15d/-15d)					LOW UTILIZATION		
	HRS	10541.4	500 (+20/-20)							
	AFL	5613								
					PROC. REF: AMM 78-33-01					PKG:5002
78-34-00-710-001-A00 ^S	OPERATIONAL CHECK THRUST-REVERSER (TR) INDICATING SYSTEM (CMR)								Service	ATA:78
	MOS	06-Jul-19	72 (+15d/-15d)					LOW UTILIZATION		
	HRS	9057.4	3000 (+20/-20)							
	AFL	4853	1500 (+20/-20)							
					PROC. REF: AMM 78-34-00					PKG:5012,6020
78-34-01-720-001-A00	FUNCTIONAL CHECK STOW/TRANSIT THRUST REVERSER MICROSWITCHES FOR INSULATION PRE-MOD S.B. 145LEG-78-0006. (ELECTRICAL TEST).(L600 ONLY)								Service	ATA:78
	MOS/MSC	27-Aug-07	N/A							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 78-34-01					
78-Z416-213-001-A00 ^S	GENERAL VISUAL INSPECTION THRUST REVERSER MODULE (EXTERNAL) (ZONES 416 AND 426)								Service	ATA:78
	MOS	29-Jun-23	24 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	1000 (+20/-20)							
	AFL	5401								
					PROC. REF: AMM 05-20-74					PKG:5004
78-Z416-213-001-A01	GENERAL VISUAL INSPECTION (EXTERNAL) (ZONES 416 AND 426).NOTE: FOR AIRCRAFT WITHOUT THRUST REVERSERS ONLY.								Service	ATA:78
	MOS/MSC		N/A							
	HRS									
	AFL									
					PROC. REF: AMM 05-30-41					PKG:6016
78-Z416-214-001-A00 ^S	GENERAL VISUAL INSPECTION THRUST REVERSER MODULE (INTERNAL) (ZONES 416 AND 426) (L600 ONLY)								Service	ATA:78
	MOS	29-Jun-23	24 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	1000 (+20/-20)							
	AFL	5401								
					PROC. REF: AMM 05-20-74					PKG:5004
78-Z416-214-001-A01	GENERAL VISUAL INSPECTION (INTERNAL) (ZONES 416 AND 426).NOTE: FOR AIRCRAFT WITHOUT THRUST REVERSERS ONLY.								Service	ATA:78
	MOS/MSC		N/A							
	HRS									
	AFL									
					PROC. REF: AMM 05-30-41					PKG:6016

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 78 - EXHAUST										
78-Z416-214-001-A02 GENERAL VISUAL INSPECTION THRUST REVERSER MODULE (INTERNAL) (ZONES 416 AND 426).NOTE: EWIS. (L650 ONLY) Service ATA:78										
	MOS/MSC	25-Sep-07	N/A					ZONAL		
	HRS	0								
	AFL	0								
PROC. REF: AMM 05-20-74										
783000-0201 LH ENG THRUST REVERSER ASSEMBLY Component ATA:78										
PN:145-79600-407	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:TR1838	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 78-31-01										
783000-0202 RH ENG THRUST REVERSER ASSEMBLY Component ATA:78										
PN:145-79600-407	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:TR1863	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 78-31-01										
783101-0101 LEFT UPPER THRUST REVERSER DOOR Component ATA:78										
PN:145-79603-403	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UPD1837	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 78-31-02										
783101-0102 LEFT LOWER THRUST REVERSER DOOR Component ATA:78										
PN:145-79604-403	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:LPD1838	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 78-31-03										
783101-0103 RIGHT UPPER THRUST REVERSER DOOR Component ATA:78										
PN:145-79603-403	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UPD1863	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 78-31-02										
783101-0104 RIGHT LOWER THRUST REVERSER DOOR Component ATA:78										
PN:145-79604-403	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:LPD1863	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 78-31-03										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 78 - EXHAUST											
783201-0101		LEFT UPPER PIVOT DOOR ACTUATOR								Component	ATA:78
PN:TY2039-14A	MOS	27-Aug-07		TSN 0				LIFE LIMIT			
SN:3910	HRS	0		TSN 0							
	AFL	0	60250	TSN 0	60250		54601				
PROC. REF: AMM 78-32-01											
783201-0102		LEFT LOWER PIVOT DOOR ACTUATOR								Component	ATA:78
PN:TY2039-14A	MOS	27-Aug-07		TSN 0				LIFE LIMIT			
SN:3909	HRS	0		TSN 0							
	AFL	0	60250	TSN 0	60250		54601				
PROC. REF: AMM 78-32-01											
783201-0103		RIGHT UPPER PIVOT DOOR ACTUATOR								Component	ATA:78
PN:TY2039-14A	MOS	27-Aug-07		TSN 0				LIFE LIMIT			
SN:3948	HRS	0		TSN 0							
	AFL	0	60250	TSN 0	60250		54601				
PROC. REF: AMM 78-32-01											
783201-0104		RIGHT LOWER PIVOT DOOR ACTUATOR								Component	ATA:78
PN:TY2039-14A	MOS	27-Aug-07		TSN 0				LIFE LIMIT			
SN:3961	HRS	0		TSN 0							
	AFL	0	60250	TSN 0	60250		54601				
PROC. REF: AMM 78-32-01											
783202-0101		LEFT 90 DEG PRIMARY DOOR LOCK ACTUATOR								Component	ATA:78
PN:TY2038-02A	MOS	27-Aug-07		TSN 0				LIFE LIMIT			
SN:61016	HRS	0		TSN 0							
	AFL	0	60250	TSN 0	60250		54601				
PROC. REF: AMM 78-32-02											
783202-0102		LEFT 270 DEG PRIMARY DOOR LOCK ACTUATOR								Component	ATA:78
PN:TY2038-02A	MOS	27-Aug-07		TSN 0				LIFE LIMIT			
SN:61017	HRS	0		TSN 0							
	AFL	0	60250	TSN 0	60250		54601				
PROC. REF: AMM 78-32-02											
783202-0103		RIGHT 90 DEG PRIMARY DOOR LOCK ACTUATOR								Component	ATA:78
PN:TY2038-02A	MOS	27-Aug-07		TSN 0				LIFE LIMIT			
SN:61066	HRS	0		TSN 0							
	AFL	0	60250	TSN 0	60250		54601				
PROC. REF: AMM 78-32-02											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 78 - EXHAUST											
783202-0104		RIGHT 270 DEG PRIMARY DOOR LOCK ACTUATOR							Component	ATA:78	
PN:TY2038-02A	MOS	27-Aug-07		TSN 0				LIFE LIMIT			
SN:61067	HRS	0		TSN 0							
	AFL	0	60250	TSN 0	60250		54601				
PROC. REF: AMM 78-32-02											
783205-0101		LEFT UPPER TERTIARY LOCK							Component	ATA:78	
PN:TY2560-01A	MOS	27-Aug-07		TSN 0				LIFE LIMIT			
SN:03203	HRS	0		TSN 0							
	AFL	0	61500	TSN 0	61500		55851				
PROC. REF: AMM 78-32-05											
783205-0102		LEFT LOWER TERTIARY LOCK							Component	ATA:78	
PN:TY2560-01A	MOS	27-Aug-07		TSN 0				LIFE LIMIT			
SN:03204	HRS	0		TSN 0							
	AFL	0	61500	TSN 0	61500		55851				
PROC. REF: AMM 78-32-05											
783205-0103		RIGHT UPPER TERTIARY LOCK							Component	ATA:78	
PN:TY2560-01A	MOS	27-Aug-07		TSN 0				LIFE LIMIT			
SN:03313	HRS	0		TSN 0							
	AFL	0	61500	TSN 0	61500		55851				
PROC. REF: AMM 78-32-05											
783205-0104		RIGHT LOWER TERTIARY LOCK							Component	ATA:78	
PN:TY2560-01A	MOS	27-Aug-07		TSN 0				LIFE LIMIT			
SN:03314	HRS	0		TSN 0							
	AFL	0	61500	TSN 0	61500		55851				
PROC. REF: AMM 78-32-05											
783301-0101		LH REAR ISOLATION ASSY-THRUST REVERSER VALVE							Component	ATA:78	
PN:TY2041-03A	MOS	27-Aug-07		TSN 0				LIFE LIMIT			
SN:1936	HRS	0		TSN 0							
	AFL	0	60250	TSN 0	60250		54601				
PROC. REF: AMM 78-33-01											
783301-0102		RH REAR ISOLATION ASSY-THRUST REVERSER VALVE							Component	ATA:78	
PN:TY2041-03A	MOS	27-Aug-07		TSN 0				LIFE LIMIT			
SN:1937	HRS	0		TSN 0							
	AFL	0	60250	TSN 0	60250		54601				
PROC. REF: AMM 78-33-01											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 78 - EXHAUST											
783305-0101		LEFT DIRECTIONAL CONTROL UNIT								Component	ATA:78
PN:TY2040-01A	MOS	27-Aug-07		TSN 0				LIFE LIMIT			
SN:1944	HRS	0		TSN 0							
	AFL	0	60250	TSN 0	60250		54601				
PROC. REF: AMM 78-33-05											
783305-0102		RIGHT DIRECTIONAL CONTROL UNIT								Component	ATA:78
PN:TY2040-01A	MOS	27-Aug-07		TSN 0				LIFE LIMIT			
SN:1971	HRS	0		TSN 0							
	AFL	0	60250	TSN 0	60250		54601				
PROC. REF: AMM 78-33-05											
783305-0201		LEFT LOCK SEQUENCER								Component	ATA:78
PN:TY2047-03B	MOS	27-Aug-07		TSN 0				LIFE LIMIT			
SN:1921	HRS	0		TSN 0							
	AFL	0	60250	TSN 0	60250		54601				
PROC. REF: AMM 78-33-06											
783305-0202		RIGHT LOCK SEQUENCER								Component	ATA:78
PN:TY2047-03B	MOS	27-Aug-07		TSN 0				LIFE LIMIT			
SN:1948	HRS	0		TSN 0							
	AFL	0	60250	TSN 0	60250		54601				
PROC. REF: AMM 78-33-06											
783402-0101		LEFT HAND UPPER DEPLOY SWITCH SWITCH								Component	ATA:78
PN:83-990-173	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:00561	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 78-34-02											
783402-0102		LEFT HAND LOWER DEPLOY SWITCH								Component	ATA:78
PN:83-990-174	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:00564	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 78-34-02											
783402-0103		RIGHT HAND UPPER DEPLOY SWITCH								Component	ATA:78
PN:83-990-173	MOS/MSC	27-Aug-07	O/C	TSN 0							
SN:00596	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 78-34-02											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 78 - EXHAUST										
783402-0104 RIGHT HAND LOWER DEPLOY SWITCH Component ATA:78										
PN:83-990-174	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:00603	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 78-34-02										
789000-0101 LEFT UPPER LEFT THRUST REVERSER STOW SWITCH Component ATA:78										
PN:83-990-168	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:11614	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 78-34-01										
789000-0102 LEFT LOWER LEFT THRUST REVERSER STOW SWITCH Component ATA:78										
PN:83-990-168	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:11623	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 78-34-01										
789000-0103 RIGHT UPPER LEFT THRUST REVERSER STOW SWITCH Component ATA:78										
PN:83-990-168	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:11621	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 78-34-01										
789000-0104 RIGHT LOWER LEFT THRUST REVERSER STOW SWITCH Component ATA:78										
PN:83-990-168	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:11622	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 78-34-01										
789000-0105 LEFT UPPER RIGHT THRUST REVERSER STOW SWITCH Component ATA:78										
PN:PN	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 78-34-01										
789000-0106 LEFT LOWER RIGHT THRUST REVERSER STOW SWITCH Component ATA:78										
PN:83-990-168	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:12018	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 78-34-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 78 - EXHAUST										
789000-0107 RIGHT UPPER RIGHT THRUST REVERSER STOW SWITCH Component ATA:78										
PN:83-990-168	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:11979	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: AMM 78-34-01										
789000-0108 RIGHT LOWER RIGHT THRUST REVERSER STOW SWITCH Component ATA:78										
PN:83-990-168	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:12017	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: AMM 78-34-01										
789000-0201 UPPER LEFT THRUST REVERSER TRANSIT SWITCH Component ATA:78										
PN:83-990-168	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:11613	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: AMM 78-34-01										
789000-0202 LOWER LEFT THRUST REVERSER TRANSIT SWITCH Component ATA:78										
PN:83-990-168	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:11619	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: AMM 78-34-01										
789000-0203 UPPER RIGHT THRUST REVERSER TRANSIT SWITCH Component ATA:78										
PN:83-990-168	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:11973	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: AMM 78-34-01										
789000-0204 LOWER RIGHT THRUST REVERSER TRANSIT SWITCH Component ATA:78										
PN:83-990-168	MOS/MSC		27-Aug-07	O/C	TSN 0					
SN:12008	HRS		0		TSN 0					
	AFL		0		TSN 0					
PROC. REF: AMM 78-34-01										
ATA 79 - OIL										
79-23-01-960-002-A00^S DISCARD OIL FILTER Service ATA:79										
	MOS		29-Jun-23		24 (+15d/-15d)			LOW UTILIZATION		
	HRS		10161.5		1000 (+20/-20)					
	AFL		5401							
PROC. REF: AMM 79-23-01										
PKG:5004										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 79 - OIL										
79-27-00-211-001-A00	NO. 1 ENGINE - VISUALLY CHECK OIL PLUMBING									Service ATA:79
	MOS	14-Jul-22						SYSTEM		
	HRS	9811.6	10000		(19811.6) 19915.8		9320.2			
	ENC	5199								
PROC. REF: AMM 79-27-00, MM 72-00-00										
79-27-00-211-001-A00	NO. 2 ENGINE - VISUALLY CHECK OIL PLUMBING									Service ATA:79
	MOS	14-Jul-22						SYSTEM		
	HRS	9811.6	10000		(19811.6) 19915.8		9320.2			
	ENC	5199								
PROC. REF: AMM 79-27-00, MM 72-00-00										
79-34-00-212-001-A00	INSPECT (GENERAL VISUAL) MFD FOR ENG 1(2) OIL DEBRIS FOR ENGINE AE3007A1P MAINTENANCE MESSAGE (NOTE: IF INSTALLED).									Service ATA:79
	MOS/MSC	15-Aug-13	N/A							
	HRS	6643.4								
	AFL	3572								
PROC. REF: AMM 79-34-00										
79-34-00-212-001-A01	INSPECT (GENERAL VISUAL) MFD FOR ENG 1(2) OIL DEBRIS FOR ENGINE AE3007A1E OR AE3007A2 MAINTENANCE MESSAGE (NOTE: IF INSTALLED).									Service ATA:79
	DAYS	15-Oct-24	30		14-Nov-24		OVD	ROUTINE		
	HRS	10578.1	70		10648.1		52.5			
	AFL	5634								
PROC. REF: AMM 79-34-00										
79-34-01-720-001-A00	NO. 1 ENGINE - FUNCTIONALLY CHECK INDICATING MAGNETIC PLUG ASSEMBLY									Service ATA:79
	MOS	17-Feb-17						SYSTEM		
	HRS	7961.8	8000		(15961.8) 16066		5470.4			
	ENC	4253								
PROC. REF: AMM 79-34-01, MM 79-37-10										
79-34-01-720-001-A00	NO. 2 ENGINE - FUNCTIONALLY CHECK INDICATING MAGNETIC PLUG ASSEMBLY									Service ATA:79
	MOS	17-Feb-17						SYSTEM		
	HRS	7961.8	8000		(15961.8) 16066		5470.4			
	ENC	4253								
PROC. REF: AMM 79-34-01, MM 79-37-10										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 79 - OIL										
79-37-00-720-001-A00		NO. 1 ENGINE - FUNCTIONALLY CHECK OIL FILTER IMPEDING BYPASS INDICATING SYSTEM								Service ATA:79
	MOS	17-Feb-17						SYSTEM		
	HRS	7961.8	10000		(17961.8) 18066		7470.4			
	ENC	4253								
PROC. REF: AMM 79-37-00, MM 79-37-15										
79-37-00-720-001-A00		NO. 2 ENGINE - FUNCTIONALLY CHECK OIL FILTER IMPEDING BYPASS INDICATING SYSTEM								Service ATA:79
	MOS	10-Jul-20						SYSTEM		
	HRS	9265.4	10000		(19265.4) 19369.6		8774			
	ENC	4922								
PROC. REF: AMM 79-37-00, MM 79-37-15										
790010-0101		NO. 1 ENGINE - CHANGE THE OIL								Service ATA:79
	MOS/MSC	25-Sep-07	A/R							
	HRS	0								
	ENC	0								
PROC. REF: MM 12-10-79										
790010-0101		NO. 2 ENGINE - CHANGE THE OIL								Service ATA:79
	MOS/MSC	25-Sep-07	A/R							
	HRS	0								
	ENC	0								
PROC. REF: MM 12-10-79										
791101-0101		NO. 1 ENGINE - OIL TANK ASSEMBLY								Component ATA:79
PN:23070328	MOS/MSC	25-Sep-07	O/C		TSN 0					
SN:RJ15141	HRS	0			TSN 0					
	ENC	0			TSN 0					
PROC. REF: AMM 79-11-01, MM 79-11-10, MM 79-11-10										
791101-0101		NO. 2 ENGINE - OIL TANK ASSEMBLY								Component ATA:79
PN:23070328	MOS/MSC	25-Sep-07	O/C		TSN 0					
SN:RJ15135	HRS	0			TSN 0					
	ENC	0			TSN 0					
PROC. REF: AMM 79-11-01, MM 79-11-10, MM 79-11-10										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 79 - OIL											
792101-0101		NO. 1 ENGINE - LUBE/SCAVENGE PUMP ASSEMBLY							Component	ATA:79	
PN:23079382	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:NL-3020	HRS	0	TSN 0								
	ENC	0	TSN 0								
PROC. REF: MM 79-21-10, MM 79-21-10											
792101-0101		NO. 2 ENGINE - LUBE/SCAVENGE PUMP ASSEMBLY							Component	ATA:79	
PN:23079382	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:NL-3021	HRS	0	TSN 0								
	ENC	0	TSN 0								
PROC. REF: MM 79-21-10, MM 79-21-10											
792103-0101		NO. 1 ENGINE - OIL PRESS/TEMP SENSOR							Component	ATA:79	
PN:23073715	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:QW7496V	HRS	0	TSN 0								
	ENC	0	TSN 0								
PROC. REF: AMM 79-32-01, MM 79-31-10, MM 79-31-10											
792103-0101		NO. 2 ENGINE - OIL PRESS/TEMP SENSOR							Component	ATA:79	
PN:23073715	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:QW7493V	HRS	0	TSN 0								
	ENC	0	TSN 0								
PROC. REF: AMM 79-32-01, MM 79-31-10, MM 79-31-10											
792301-0101		NO. 1 ENGINE - OIL FILTER ASSEMBLY							Component	ATA:79	
PN:23087914	MOS/MSC	20-Mar-20	O/C	TSN 0							
SN:WQ739D	HRS	9243.7	TSN 0								
	ENC	4910	TSN 0								
PROC. REF: AMM 79-21-01, MM 79-23-10, MM 79-23-10											
792301-0101		NO. 2 ENGINE - OIL FILTER ASSEMBLY							Component	ATA:79	
PN:23087914	MOS/MSC	19-Sep-13	O/C	TSN 0							
SN:WQ419D	HRS	6680.2	TSN 0								
	ENC	3597	TSN 0								
PROC. REF: AMM 79-21-01, MM 79-23-10, MM 79-23-10											
792501-0101		NO. 1 ENGINE - OIL AIR COOLED COOLER							Component	ATA:79	
PN:23075194	MOS/MSC	25-Sep-07	O/C	TSN 0							
SN:VR2974	HRS	0	TSN 0								
	ENC	0	TSN 0								
PROC. REF: AMM 79-25-01, MM 79-25-10, MM 79-25-10											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 79 - OIL										
792501-0101	NO. 2 ENGINE - OIL AIR COOLED COOLER									Component ATA:79
PN:23075194	MOS/MSC		25-Sep-07	O/C	TSN 0					
SN:VR2967	HRS		0		TSN 0					
	ENC		0		TSN 0					
PROC. REF: AMM 79-25-01, MM 79-25-10, MM 79-25-10										
792503-0101	NO. 1 ENGINE - OIL FUEL COOLED COOLER									Component ATA:79
PN:23077047	MOS/MSC		25-Sep-07	O/C	TSN 0					
SN:VR3135	HRS		0		TSN 0					
	ENC		0		TSN 0					
PROC. REF: AMM 79-25-02, MM 79-25-15, MM 79-25-15										
792503-0101	NO. 2 ENGINE - OIL FUEL COOLED COOLER									Component ATA:79
PN:23077047	MOS/MSC		25-Sep-07	O/C	TSN 0					
SN:VR3137	HRS		0		TSN 0					
	ENC		0		TSN 0					
PROC. REF: AMM 79-25-02, MM 79-25-15, MM 79-25-15										
792507-0101	NO. 1 ENGINE - NO. 1 P2.5 TRANSDUCER									Component ATA:79
PN:PN	MOS/MSC		25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS		0		TSN 0					
	ENC		0		TSN 0					
PROC. REF: GENERIC NO REF										
792507-0101	NO. 2 ENGINE - NO. 1 P2.5 TRANSDUCER									Component ATA:79
PN:PN	MOS/MSC		25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS		0		TSN 0					
	ENC		0		TSN 0					
PROC. REF: GENERIC NO REF										
792508-0101	NO. 1 ENGINE - NO. 2 P2.5 TRANSDUCER									Component ATA:79
PN:PN	MOS/MSC		25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS		0		TSN 0					
	ENC		0		TSN 0					
PROC. REF: GENERIC NO REF										
792508-0101	NO. 2 ENGINE - NO. 2 P2.5 TRANSDUCER									Component ATA:79
PN:PN	MOS/MSC		25-Sep-07	O/C	TSN 0					
SN:UNKNOWN	HRS		0		TSN 0					
	ENC		0		TSN 0					
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty		
ATA 79 - OIL												
792509-0101			NO. 1 ENGINE - RTD TOTAL TEMP SENSOR								Component	ATA:79
PN:23059750	MOS/MSC	25-Sep-07	O/C	TSN 0								
SN:RTAN269	HRS	0	TSN 0									
	ENC	0	TSN 0									
PROC. REF: GENERIC NO REF												
792509-0101			NO. 2 ENGINE - RTD TOTAL TEMP SENSOR								Component	ATA:79
PN:23059750	MOS/MSC	25-Sep-07	O/C	TSN 0								
SN:RTAN274	HRS	0	TSN 0									
	ENC	0	TSN 0									
PROC. REF: GENERIC NO REF												
793000-0101			NO. 1 ENGINE - INSPECT OIL CONTAMINATION (MPG EQUIVALENT TASKS: 79-34-00-212-001-A00 AND 79-34-00-212-001-A01)								Service	ATA:79
	MOS/MSC	25-Sep-07	-									
	HRS	0										
	ENC	0										
PROC. REF: MM 79-30-00												
793000-0101			NO. 2 ENGINE - INSPECT OIL CONTAMINATION (MPG EQUIVALENT TASKS: 79-34-00-212-001-A00 AND 79-34-00-212-001-A01)								Service	ATA:79
	MOS/MSC	25-Sep-07	-									
	HRS	0										
	ENC	0										
PROC. REF: MM 79-30-00												
793005-0101			NO. 1 ENGINE - GENERAL VISUAL INSPECTION OIL TANK								Service	ATA:79
	MOS/MSC	25-Sep-07	N/A									
	HRS	0										
	ENC	0										
PROC. REF: AMM 79-11-01, MM 3007A-79-009												
793005-0101			NO. 2 ENGINE - GENERAL VISUAL INSPECTION OIL TANK								Service	ATA:79
	MOS/MSC	25-Sep-07	N/A									
	HRS	0										
	ENC	0										
PROC. REF: AMM 79-11-01, MM 3007A-79-009												
793301-0101			NO. 1 ENGINE - LOW OIL PRESSURE SWITCH								Component	ATA:79
PN:23078098	MOS/MSC	25-Sep-07	O/C	TSN 0								
SN:KB11053	HRS	0	TSN 0									
	ENC	0	TSN 0									
PROC. REF: AMM 49-64-02, MM 79-33-10, MM 79-33-10												

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of:
11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 79 - OIL										
793301-0101	NO. 2 ENGINE - LOW OIL PRESSURE SWITCH									Component ATA:79
PN:23078098	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:KB11047	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 49-64-02, MM 79-33-10, MM 79-33-10										
793704-0101	NO. 1 ENGINE - MAGNETIC-INDICATE PLUG									Component ATA:79
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 79-34-01, MM 79-37-10, MM 79-37-10										
793704-0101	NO. 2 ENGINE - MAGNETIC-INDICATE PLUG									Component ATA:79
PN:PN	MOS/MSC	25-Sep-07	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: AMM 79-34-01, MM 79-37-10, MM 79-37-10										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: EMB-135BJ - LEGACY 600 Serial: 14501007 RegNo: N317PJ HRS: 10595.6 AFL: 5649 As Of: 11-Nov-2024

15-Nov-2024 12:17 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 80 - STARTING										
80-10-01-720-001-A00 ^S FUNCTIONALLY CHECK AIR TURBINE STARTER (ATS) INCLUDING OIL SERVICING. Service ATA:80										
	MOS	16-Aug-24	12 (+15d/-15d)					LOW UTILIZATION		
	HRS	10541.4	500 (+20/-20)							
	AFL	5613								
PROC. REF: AMM 80-10-01										PKG:5002
80-10-02-160-001-A00 ^S SERVICE (CLEANING) START CONTROL VALVE FILTER Service ATA:80										
	MOS	29-Jun-23	48 (+15d/-15d)					LOW UTILIZATION		
	HRS	10161.5	2000 (+20/-20)							
	AFL	5401	1000 (+20/-20)							
PROC. REF: AMM 80-10-02										PKG:5008,6016
801100-0101 LH ENG PNEUMATIC STARTER UNIT Component ATA:80										
PN:3505910-6	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:2578	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										
801100-0102 RH ENG PNEUMATIC STARTER UNIT Component ATA:80										
PN:3505910-6	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:2576	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										
801100-0201 LH ENG BUTTERFLY TYPE,STARTER SYS SHUTOFF VALVE Component ATA:80										
PN:3215358-2	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:2313	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										
801100-0202 RH ENG BUTTERFLY TYPE,STARTER SYS SHUTOFF VALVE Component ATA:80										
PN:3215358-2	MOS/MSC	27-Aug-07	O/C	TSN 0						
SN:2312	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: NDT GENERIC										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task