

|                          |                        |                              |                           |                                                                                             |
|--------------------------|------------------------|------------------------------|---------------------------|---------------------------------------------------------------------------------------------|
| OWNER: GHANIMA LLC       |                        | OPERATOR: PRIVATE JETS INC.  |                           |                                                                                             |
| ADDRESS: 155 PLEASANT ST |                        | ADDRESS: 7200 NW 63RD STREET |                           |                                                                                             |
| NORWELL MA 02061         |                        | BETHANY OK 73008             |                           |                                                                                             |
| OFFICE:                  |                        | OFFICE: 405-681-4466         |                           |                                                                                             |
| FAX:                     |                        | FAX: 405-681-1661            |                           |                                                                                             |
| ANALYST:                 | SEAN WELLS             | +1-316-928-7895 (DIRECT)     | 800-787-9749 (EFAX-CARDS) | PLEASE REACH OUT TO YOUR ANALYST TO<br>RECORD CHANGES TO ADDRESS, LAST ACTUALS<br>(IF ANY). |
| EMAIL:                   | SWELLS@CAMPSYSTEMS.COM | +1-631-588-3200 (MAIN)       | 631-980-4222 (EFAX-CARDS) |                                                                                             |
|                          |                        | WWW.CAMPSYSTEMS.COM          |                           |                                                                                             |

|                                 |                               |               |              |                                   |
|---------------------------------|-------------------------------|---------------|--------------|-----------------------------------|
| AIRCRAFT                        | SERIAL / REGNO: 45-145/N942FK | MODEL:        | LEARJET 45XR | MANUFACTURER: BOMBARDIER AVIATION |
| CERTIFICATION DATE: 09-MAR-2001 |                               | LAST ACTUALS: |              |                                   |
|                                 |                               | 9669.1        | A/C HRS      | as of 01-APR-2025                 |
|                                 |                               | 7372          | AFL          | as of 01-APR-2025                 |
|                                 |                               | 2653.1        | ACH          | as of 20-FEB-2025                 |

|                           |                                    |               |                |                                 |
|---------------------------|------------------------------------|---------------|----------------|---------------------------------|
| ENGINE NO. 1              | SERIAL / PART: P-116284C/3060082-2 | MODEL:        | TFE731-20BR-1B | MANUFACTURER: HONEYWELL         |
| INSTALLED ON: 20-JAN-2000 |                                    | LAST ACTUALS: |                |                                 |
| 0                         | ENG. HRS                           | 0             | A/C HRS        | 9595 ENG. HRS as of 01-APR-2025 |
| 0                         | ENC                                |               |                | 7314 ENC as of 01-APR-2025      |

|                           |                                    |               |                |                                   |
|---------------------------|------------------------------------|---------------|----------------|-----------------------------------|
| ENGINE NO. 2              | SERIAL / PART: P-116285C/3060084-2 | MODEL:        | TFE731-20BR-1B | MANUFACTURER: HONEYWELL           |
| INSTALLED ON: 12-AUG-2015 |                                    | LAST ACTUALS: |                |                                   |
| 6622.3                    | ENG. HRS                           | 7535.1        | A/C HRS        | 8756.3 ENG. HRS as of 01-APR-2025 |
| 5602                      | ENC                                |               |                | 7210 ENC as of 01-APR-2025        |

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                | Unit    | C/W                                                | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition                 | Warranty |
|----------------------------------------|---------|----------------------------------------------------|----------|----------|------------------------|-----------|-----------|-----------------------------|----------|
| ATA 00 - INFORMATION                   |         |                                                    |          |          |                        |           |           |                             |          |
| CI45-150721                            |         | REVIEW CONCORDE EMERGENCY BATTERY CMM 5-0167 REV E |          |          |                        |           |           | Service                     | ATA:00   |
|                                        | MOS/MSC | EFF                                                | -        |          |                        |           |           | REQUIREMENT<br>CHANGE FORMS |          |
|                                        | HRS     |                                                    |          |          |                        |           |           |                             |          |
|                                        | AFL     |                                                    |          |          |                        |           |           |                             |          |
| PROC. REF: RCF CI45PROC. REF: RCF CI45 |         |                                                    |          |          |                        |           |           |                             |          |
| CI45-160527                            |         | REVIEW LEARJET AMM REVISION 66                     |          |          |                        |           |           | Service                     | ATA:00   |
|                                        | MOS/MSC | EFF                                                | -        |          |                        |           |           | REQUIREMENT<br>CHANGE FORMS |          |
|                                        | HRS     |                                                    |          |          |                        |           |           |                             |          |
|                                        | AFL     |                                                    |          |          |                        |           |           |                             |          |
| PROC. REF: RCF CI45PROC. REF: RCF CI45 |         |                                                    |          |          |                        |           |           |                             |          |
| CI45-160603                            |         | REVIEW LEARJET 45 AMM TR 4-40                      |          |          |                        |           |           | Service                     | ATA:00   |
|                                        | MOS/MSC | EFF                                                | -        |          |                        |           |           | REQUIREMENT<br>CHANGE FORMS |          |
|                                        | HRS     |                                                    |          |          |                        |           |           |                             |          |
|                                        | AFL     |                                                    |          |          |                        |           |           |                             |          |
| PROC. REF: RCF CI45PROC. REF: RCF CI45 |         |                                                    |          |          |                        |           |           |                             |          |
| CI45-160613                            |         | REVIEW LEARJET 45 AMM TR 5-110                     |          |          |                        |           |           | Service                     | ATA:00   |
|                                        | MOS/MSC | EFF                                                | -        |          |                        |           |           | REQUIREMENT<br>CHANGE FORMS |          |
|                                        | HRS     |                                                    |          |          |                        |           |           |                             |          |
|                                        | AFL     |                                                    |          |          |                        |           |           |                             |          |
| PROC. REF: RCF CI45PROC. REF: RCF CI45 |         |                                                    |          |          |                        |           |           |                             |          |
| CI45-161207B                           |         | REVIEW LEARJET 45 AMM REVISION 67                  |          |          |                        |           |           | Service                     | ATA:00   |
|                                        | MOS/MSC | EFF                                                | -        |          |                        |           |           | REQUIREMENT<br>CHANGE FORMS |          |
|                                        | HRS     |                                                    |          |          |                        |           |           |                             |          |
|                                        | AFL     |                                                    |          |          |                        |           |           |                             |          |
| PROC. REF: RCF CI45PROC. REF: RCF CI45 |         |                                                    |          |          |                        |           |           |                             |          |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C/W   (M)-Manual Due   U-User Task   Ex-Excluded Task

# Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                              | Unit    | C/W                                                         | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition                  | Warranty |
|------------------------------------------------------|---------|-------------------------------------------------------------|----------|----------|------------------------|-----------|-----------|------------------------------|----------|
| ATA 00 - INFORMATION                                 |         |                                                             |          |          |                        |           |           |                              |          |
| CI45-181109B                                         |         | REVIEW LEARJET 45/45XR AMM REVISION 71                      |          |          |                        |           |           | Service                      | ATA:00   |
|                                                      | MOS/MSC | EFF                                                         | -        |          |                        |           |           | REQUIREMENT<br>CHANGE FORMS  |          |
|                                                      | HRS     |                                                             |          |          |                        |           |           |                              |          |
|                                                      | AFL     |                                                             |          |          |                        |           |           |                              |          |
| PROC. REF: RCF CI45PROC. REF: RCF CI45               |         |                                                             |          |          |                        |           |           |                              |          |
| CI45-190429A                                         |         | REVIEW LEARJET 45/45XR AMM REV 72                           |          |          |                        |           |           | Service                      | ATA:00   |
|                                                      | MOS/MSC | EFF                                                         | -        |          |                        |           |           | REQUIREMENT<br>CHANGE FORMS  |          |
|                                                      | HRS     |                                                             |          |          |                        |           |           |                              |          |
|                                                      | AFL     |                                                             |          |          |                        |           |           |                              |          |
| PROC. REF: RCF CI45PROC. REF: RCF CI45               |         |                                                             |          |          |                        |           |           |                              |          |
| CI45-200529                                          |         | REVIEW AUDIT SUMMARY CHANGE FORM                            |          |          |                        |           |           | Service                      | ATA:00   |
|                                                      | MOS/MSC | EFF                                                         | -        |          |                        |           |           | AUDIT SUMMARY<br>CHANGE FORM |          |
|                                                      | HRS     |                                                             |          |          |                        |           |           |                              |          |
|                                                      | AFL     |                                                             |          |          |                        |           |           |                              |          |
| PROC. REF: RCF CI45PROC. REF: RCF CI45               |         |                                                             |          |          |                        |           |           |                              |          |
| CI45-210120                                          |         | REVIEW LEARJET 45/45XR AUDIT SUMMARY CHANGE FORM            |          |          |                        |           |           | Service                      | ATA:00   |
|                                                      | MOS/MSC | 30-Mar-21                                                   | -        |          |                        |           |           | AUDIT SUMMARY<br>CHANGE FORM |          |
|                                                      | HRS     | 8414.4                                                      |          |          |                        |           |           |                              |          |
|                                                      | AFL     | 6463                                                        |          |          |                        |           |           |                              |          |
| PROC. REF: RCF CI45PROC. REF: RCF CI45               |         |                                                             |          |          |                        |           |           |                              |          |
| EC04-180802                                          |         | NO. 1 ENGINE - REVIEW TFE731-20/-40/-60 (CIMMS) LMM TR 5-17 |          |          |                        |           |           | Service                      | ATA:00   |
|                                                      | MOS/MSC | EFF                                                         | -        |          |                        |           |           | REQUIREMENT<br>CHANGE FORMS  |          |
|                                                      | HRS     |                                                             |          |          |                        |           |           |                              |          |
|                                                      | ENC     |                                                             |          |          |                        |           |           |                              |          |
| PROC. REF: RCF EC04-180802PROC. REF: RCF EC04-180802 |         |                                                             |          |          |                        |           |           |                              |          |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C/W   (M)-Manual Due   U-User Task   Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|---------|------|-----|----------|----------|------------------------|-----------|-----------|-------------|----------|
|---------|------|-----|----------|----------|------------------------|-----------|-----------|-------------|----------|

ATA 00 - INFORMATION

|                                                      |                                                             |     |   |  |  |  |  |                             |        |
|------------------------------------------------------|-------------------------------------------------------------|-----|---|--|--|--|--|-----------------------------|--------|
| EC04-180802                                          | NO. 2 ENGINE - REVIEW TFE731-20/-40/-60 (CIMMS) LMM TR 5-17 |     |   |  |  |  |  | Service                     | ATA:00 |
|                                                      | MOS/MSC                                                     | EFF | - |  |  |  |  | REQUIREMENT<br>CHANGE FORMS |        |
|                                                      | HRS                                                         |     |   |  |  |  |  |                             |        |
|                                                      | ENC                                                         |     |   |  |  |  |  |                             |        |
| PROC. REF: RCF EC04-180802PROC. REF: RCF EC04-180802 |                                                             |     |   |  |  |  |  |                             |        |

ATA 05 - TIME LIMITS/MAINTENANCE CHECKS

|                                                                            |                          |           |     |  |           |  |       |         |        |
|----------------------------------------------------------------------------|--------------------------|-----------|-----|--|-----------|--|-------|---------|--------|
| 051101                                                                     | PHASE A1-300 HOUR CHECKS |           |     |  |           |  |       | Package | ATA:05 |
|                                                                            | MOS                      | 02-Aug-24 | 12  |  | 02-Aug-25 |  | 122 d |         |        |
|                                                                            | HRS                      | 9525.7    | 325 |  | 9850.7    |  | 181.6 |         |        |
| WC#: 05.110                                                                | AFL                      | 7276      |     |  |           |  |       |         |        |
|                                                                            |                          |           |     |  |           |  |       |         | PKG:1  |
| PROC. REF: AMM 05-10-00, AMM 05-11-01PROC. REF: AMM 05-10-00, AMM 05-11-01 |                          |           |     |  |           |  |       |         |        |

|                                                                            |                          |           |     |  |           |  |       |         |        |
|----------------------------------------------------------------------------|--------------------------|-----------|-----|--|-----------|--|-------|---------|--------|
| 051102                                                                     | PHASE A2-300 HOUR CHECKS |           |     |  |           |  |       | Package | ATA:05 |
|                                                                            | MOS                      | 02-Aug-24 | 12  |  | 02-Aug-25 |  | 122 d |         |        |
|                                                                            | HRS                      | 9525.7    | 325 |  | 9850.7    |  | 181.6 |         |        |
|                                                                            | AFL                      | 7276      |     |  |           |  |       |         |        |
|                                                                            |                          |           |     |  |           |  |       |         | PKG:2  |
| PROC. REF: AMM 05-10-00, AMM 05-11-02PROC. REF: AMM 05-10-00, AMM 05-11-02 |                          |           |     |  |           |  |       |         |        |

|                                                                            |                          |           |     |  |           |  |       |         |        |
|----------------------------------------------------------------------------|--------------------------|-----------|-----|--|-----------|--|-------|---------|--------|
| 051103                                                                     | PHASE A3-300 HOUR CHECKS |           |     |  |           |  |       | Package | ATA:05 |
|                                                                            | MOS                      | 02-Aug-24 | 12  |  | 02-Aug-25 |  | 122 d |         |        |
|                                                                            | HRS                      | 9525.7    | 325 |  | 9850.7    |  | 181.6 |         |        |
|                                                                            | AFL                      | 7276      |     |  |           |  |       |         |        |
|                                                                            |                          |           |     |  |           |  |       |         | PKG:3  |
| PROC. REF: AMM 05-10-00, AMM 05-11-03PROC. REF: AMM 05-10-00, AMM 05-11-03 |                          |           |     |  |           |  |       |         |        |

|                                                                            |                          |           |     |  |           |  |       |         |        |
|----------------------------------------------------------------------------|--------------------------|-----------|-----|--|-----------|--|-------|---------|--------|
| 051104                                                                     | PHASE A4-300 HOUR CHECKS |           |     |  |           |  |       | Package | ATA:05 |
|                                                                            | MOS                      | 02-Aug-24 | 12  |  | 02-Aug-25 |  | 122 d |         |        |
|                                                                            | HRS                      | 9525.7    | 325 |  | 9850.7    |  | 181.6 |         |        |
|                                                                            | AFL                      | 7276      |     |  |           |  |       |         |        |
|                                                                            |                          |           |     |  |           |  |       |         | PKG:4  |
| PROC. REF: AMM 05-10-00, AMM 05-11-04PROC. REF: AMM 05-10-00, AMM 05-11-04 |                          |           |     |  |           |  |       |         |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                                                    | Unit                     | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------------------------------|--------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 05 - TIME LIMITS/MAINTENANCE CHECKS                                    |                          |           |          |          |                        |           |           |             |          |
| 051105                                                                     | PHASE A5-300 HOUR CHECKS |           |          |          |                        |           |           | Package     | ATA:05   |
|                                                                            | MOS                      | 02-Aug-24 | 12       |          | 02-Aug-25              |           | 122 d     |             |          |
|                                                                            | HRS                      | 9525.7    | 325      |          | 9850.7                 |           | 181.6     |             |          |
|                                                                            | AFL                      | 7276      |          |          |                        |           |           |             |          |
| PROC. REF: AMM 05-10-00, AMM 05-11-05PROC. REF: AMM 05-10-00, AMM 05-11-05 |                          |           |          |          |                        |           |           |             | PKG:5    |
| 051106                                                                     | PHASE A6-300 HOUR CHECKS |           |          |          |                        |           |           | Package     | ATA:05   |
|                                                                            | MOS                      | 02-Aug-24 | 12       |          | 02-Aug-25              |           | 122 d     |             |          |
|                                                                            | HRS                      | 9525.7    | 325      |          | 9850.7                 |           | 181.6     |             |          |
|                                                                            | AFL                      | 7276      |          |          |                        |           |           |             |          |
| PROC. REF: AMM 05-10-00, AMM 05-11-06PROC. REF: AMM 05-10-00, AMM 05-11-06 |                          |           |          |          |                        |           |           |             | PKG:6    |
| 051201                                                                     | PHASE B1 600 HOUR CHECKS |           |          |          |                        |           |           | Package     | ATA:05   |
|                                                                            | MOS                      | 02-Aug-24 | 24       |          | 02-Aug-26              |           | 487 d     |             |          |
|                                                                            | HRS                      | 9525.7    | 625      |          | 10150.7                |           | 481.6     |             |          |
|                                                                            | AFL                      | 7276      |          |          |                        |           |           |             |          |
| PROC. REF: AMM 05-10-00, AMM 05-12-01PROC. REF: AMM 05-10-00, AMM 05-12-01 |                          |           |          |          |                        |           |           |             | PKG:7    |
| 051202                                                                     | PHASE B2 600 HOUR CHECKS |           |          |          |                        |           |           | Package     | ATA:05   |
|                                                                            | MOS                      | 02-Aug-24 | 24       |          | 02-Aug-26              |           | 487 d     |             |          |
|                                                                            | HRS                      | 9525.7    | 625      |          | 10150.7                |           | 481.6     |             |          |
|                                                                            | AFL                      | 7276      |          |          |                        |           |           |             |          |
| PROC. REF: AMM 05-10-00, AMM 05-12-02PROC. REF: AMM 05-10-00, AMM 05-12-02 |                          |           |          |          |                        |           |           |             | PKG:8    |
| 051203                                                                     | PHASE B3 600 HOUR CHECKS |           |          |          |                        |           |           | Package     | ATA:05   |
|                                                                            | MOS                      | 02-Aug-24 | 24       |          | 02-Aug-26              |           | 487 d     |             |          |
|                                                                            | HRS                      | 9525.7    | 625      |          | 10150.7                |           | 481.6     |             |          |
|                                                                            | AFL                      | 7276      |          |          |                        |           |           |             |          |
| PROC. REF: AMM 05-10-00, AMM 05-12-03PROC. REF: AMM 05-10-00, AMM 05-12-03 |                          |           |          |          |                        |           |           |             | PKG:9    |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C/W   (M)-Manual Due   U-User Task   Ex-Excluded Task

# Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 9669.1
AFL: 7372
As Of: 01-Apr-2025
02-Apr-2025 02:58 PM

| PN & SN                                                                    | Unit                      | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------------------------------|---------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 05 - TIME LIMITS/MAINTENANCE CHECKS                                    |                           |           |          |          |                        |           |           |             |          |
| 051204                                                                     | PHASE B4 600 HOUR CHECKS  |           |          |          |                        |           |           | Package     | ATA:05   |
|                                                                            | MOS                       | 02-Aug-24 | 24       |          | 02-Aug-26              |           | 487 d     |             |          |
|                                                                            | HRS                       | 9525.7    | 625      |          | 10150.7                |           | 481.6     |             |          |
|                                                                            | AFL                       | 7276      |          |          |                        |           |           |             |          |
| PROC. REF: AMM 05-10-00, AMM 05-12-04PROC. REF: AMM 05-10-00, AMM 05-12-04 |                           |           |          |          |                        |           |           |             | PKG:10   |
| 051205                                                                     | PHASE B5 600 HOUR CHECKS  |           |          |          |                        |           |           | Package     | ATA:05   |
|                                                                            | MOS                       | 02-Aug-24 | 24       |          | 02-Aug-26              |           | 487 d     |             |          |
|                                                                            | HRS                       | 9525.7    | 625      |          | 10150.7                |           | 481.6     |             |          |
|                                                                            | AFL                       | 7276      |          |          |                        |           |           |             |          |
| PROC. REF: AMM 05-10-00, AMM 05-12-05PROC. REF: AMM 05-10-00, AMM 05-12-05 |                           |           |          |          |                        |           |           |             | PKG:11   |
| 051206                                                                     | PHASE B6 600 HOUR CHECKS  |           |          |          |                        |           |           | Package     | ATA:05   |
|                                                                            | MOS                       | 02-Aug-24 | 24       |          | 02-Aug-26              |           | 487 d     |             |          |
|                                                                            | HRS                       | 9525.7    | 625      |          | 10150.7                |           | 481.6     |             |          |
|                                                                            | AFL                       | 7276      |          |          |                        |           |           |             |          |
| PROC. REF: AMM 05-10-00, AMM 05-12-06PROC. REF: AMM 05-10-00, AMM 05-12-06 |                           |           |          |          |                        |           |           |             | PKG:12   |
| 051301                                                                     | PHASE C1 1200 HOUR CHECKS |           |          |          |                        |           |           | Package     | ATA:05   |
|                                                                            | MOS                       | 22-Jun-23 | 48       |          | 22-Jun-27              |           | 811 d     |             |          |
|                                                                            | HRS                       | 9258.5    | 1200     |          | 10458.5                |           | 789.4     |             |          |
|                                                                            | AFL                       | 7100      |          |          |                        |           |           |             |          |
| PROC. REF: AMM 05-10-00, AMM 05-13-01PROC. REF: AMM 05-10-00, AMM 05-13-01 |                           |           |          |          |                        |           |           |             | PKG:13   |
| 051302                                                                     | PHASE C2 1200 HOUR CHECKS |           |          |          |                        |           |           | Package     | ATA:05   |
|                                                                            | MOS                       | 22-Jun-23 | 48       |          | 22-Jun-27              |           | 811 d     |             |          |
|                                                                            | HRS                       | 9258.5    | 1200     |          | 10458.5                |           | 789.4     |             |          |
|                                                                            | AFL                       | 7100      |          |          |                        |           |           |             |          |
| PROC. REF: AMM 05-10-00, AMM 05-13-02PROC. REF: AMM 05-10-00, AMM 05-13-02 |                           |           |          |          |                        |           |           |             | PKG:14   |

?-Insufficient Information    S-Suppressed Requirement    \*-Estimated Due(New Requirement)    (EFF)-Effective C/W    (M)-Manual Due    U-User Task    Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                                                    | Unit                      | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------------------------------|---------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 05 - TIME LIMITS/MAINTENANCE CHECKS                                    |                           |           |          |          |                        |           |           |             |          |
| 051303                                                                     | PHASE C3 1200 HOUR CHECKS |           |          |          |                        |           |           | Package     | ATA:05   |
|                                                                            | MOS                       | 22-Jun-23 | 48       |          | 22-Jun-27              |           | 811 d     |             |          |
|                                                                            | HRS                       | 9258.5    | 1200     |          | 10458.5                |           | 789.4     |             |          |
|                                                                            | AFL                       | 7100      |          |          |                        |           |           |             |          |
| PROC. REF: AMM 05-10-00, AMM 05-13-03PROC. REF: AMM 05-10-00, AMM 05-13-03 |                           |           |          |          |                        |           |           |             | PKG:15   |
| 051304                                                                     | PHASE C4 1200 HOUR CHECKS |           |          |          |                        |           |           | Package     | ATA:05   |
|                                                                            | MOS                       | 22-Jun-23 | 48       |          | 22-Jun-27              |           | 811 d     |             |          |
|                                                                            | HRS                       | 9258.5    | 1200     |          | 10458.5                |           | 789.4     |             |          |
|                                                                            | AFL                       | 7100      |          |          |                        |           |           |             |          |
| PROC. REF: AMM 05-10-00, AMM 05-13-04PROC. REF: AMM 05-10-00, AMM 05-13-04 |                           |           |          |          |                        |           |           |             | PKG:16   |
| 051305                                                                     | PHASE C5 1200 HOUR CHECKS |           |          |          |                        |           |           | Package     | ATA:05   |
|                                                                            | MOS                       | 22-Jun-23 | 48       |          | 22-Jun-27              |           | 811 d     |             |          |
|                                                                            | HRS                       | 9258.5    | 1200     |          | 10458.5                |           | 789.4     |             |          |
|                                                                            | AFL                       | 7100      |          |          |                        |           |           |             |          |
| PROC. REF: AMM 05-10-00, AMM 05-13-05PROC. REF: AMM 05-10-00, AMM 05-13-05 |                           |           |          |          |                        |           |           |             | PKG:17   |
| 051306                                                                     | PHASE C6 1200 HOUR CHECKS |           |          |          |                        |           |           | Package     | ATA:05   |
|                                                                            | MOS                       | 22-Jun-23 | 48       |          | 22-Jun-27              |           | 811 d     |             |          |
|                                                                            | HRS                       | 9258.5    | 1200     |          | 10458.5                |           | 789.4     |             |          |
|                                                                            | AFL                       | 7100      |          |          |                        |           |           |             |          |
| PROC. REF: AMM 05-10-00, AMM 05-13-06PROC. REF: AMM 05-10-00, AMM 05-13-06 |                           |           |          |          |                        |           |           |             | PKG:18   |
| 051401                                                                     | PHASE D1 2400 HOUR CHECKS |           |          |          |                        |           |           | Package     | ATA:05   |
|                                                                            | MOS                       | 25-Nov-19 | 96       |          | 25-Nov-27              |           | 967 d     |             |          |
|                                                                            | HRS                       | 8177.7    | 2400     |          | 10577.7                |           | 908.6     |             |          |
|                                                                            | AFL                       | 6303      |          |          |                        |           |           |             |          |
| PROC. REF: AMM 05-10-00, AMM 05-14-01PROC. REF: AMM 05-10-00, AMM 05-14-01 |                           |           |          |          |                        |           |           |             | PKG:19   |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C/W   (M)-Manual Due   U-User Task   Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                                                    | Unit                      | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------------------------------|---------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 05 - TIME LIMITS/MAINTENANCE CHECKS                                    |                           |           |          |          |                        |           |           |             |          |
| 051402                                                                     | PHASE D2 2400 HOUR CHECKS |           |          |          |                        |           |           | Package     | ATA:05   |
|                                                                            | MOS                       | 25-Nov-19 | 96       |          | 25-Nov-27              |           | 967 d     |             |          |
|                                                                            | HRS                       | 8177.7    | 2400     |          | 10577.7                |           | 908.6     |             |          |
|                                                                            | AFL                       | 6303      |          |          |                        |           |           |             |          |
| PROC. REF: AMM 05-10-00, AMM 05-14-02PROC. REF: AMM 05-10-00, AMM 05-14-02 |                           |           |          |          |                        |           |           |             | PKG:20   |
| 051403                                                                     | PHASE D3 2400 HOUR CHECKS |           |          |          |                        |           |           | Package     | ATA:05   |
|                                                                            | MOS                       | 25-Nov-19 | 96       |          | 25-Nov-27              |           | 967 d     |             |          |
|                                                                            | HRS                       | 8177.7    | 2400     |          | 10577.7                |           | 908.6     |             |          |
|                                                                            | AFL                       | 6303      |          |          |                        |           |           |             |          |
| PROC. REF: AMM 05-10-00, AMM 05-14-03PROC. REF: AMM 05-10-00, AMM 05-14-03 |                           |           |          |          |                        |           |           |             | PKG:21   |
| 051404                                                                     | PHASE D4 2400 HOUR CHECKS |           |          |          |                        |           |           | Package     | ATA:05   |
|                                                                            | MOS                       | 25-Nov-19 | 96       |          | 25-Nov-27              |           | 967 d     |             |          |
|                                                                            | HRS                       | 8177.7    | 2400     |          | 10577.7                |           | 908.6     |             |          |
|                                                                            | AFL                       | 6303      |          |          |                        |           |           |             |          |
| PROC. REF: AMM 05-10-00, AMM 05-14-04PROC. REF: AMM 05-10-00, AMM 05-14-04 |                           |           |          |          |                        |           |           |             | PKG:22   |
| 051405                                                                     | PHASE D5 2400 HOUR CHECKS |           |          |          |                        |           |           | Package     | ATA:05   |
|                                                                            | MOS                       | 25-Nov-19 | 96       |          | 25-Nov-27              |           | 967 d     |             |          |
|                                                                            | HRS                       | 8177.7    | 2400     |          | 10577.7                |           | 908.6     |             |          |
|                                                                            | AFL                       | 6303      |          |          |                        |           |           |             |          |
| PROC. REF: AMM 05-10-00, AMM 05-14-05PROC. REF: AMM 05-10-00, AMM 05-14-05 |                           |           |          |          |                        |           |           |             | PKG:23   |
| 051406                                                                     | PHASE D6 2400 HOUR CHECKS |           |          |          |                        |           |           | Package     | ATA:05   |
|                                                                            | MOS                       | 25-Nov-19 | 96       |          | 25-Nov-27              |           | 967 d     |             |          |
|                                                                            | HRS                       | 8177.7    | 2400     |          | 10577.7                |           | 908.6     |             |          |
|                                                                            | AFL                       | 6303      |          |          |                        |           |           |             |          |
| PROC. REF: AMM 05-10-00, AMM 05-14-06PROC. REF: AMM 05-10-00, AMM 05-14-06 |                           |           |          |          |                        |           |           |             | PKG:24   |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                                                    | Unit                                                                              | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------------------------------|-----------------------------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 05 - TIME LIMITS/MAINTENANCE CHECKS                                    |                                                                                   |           |          |          |                        |           |           |             |          |
| 051500                                                                     | 4800 HOUR CHECKS                                                                  |           |          |          |                        |           |           | Package     | ATA:05   |
|                                                                            | MOS                                                                               | 22-Jun-23 |          |          |                        |           |           |             |          |
|                                                                            | HRS                                                                               | 9258.5    | 4800     |          | 14058.5                |           | 4389.4    |             |          |
|                                                                            | AFL                                                                               | 7100      |          |          |                        |           |           |             |          |
| PROC. REF: AMM 05-10-00, AMM 05-15-00PROC. REF: AMM 05-10-00, AMM 05-15-00 |                                                                                   |           |          |          |                        |           |           |             | PKG:25   |
| 051600                                                                     | 9600 HOUR CHECKS                                                                  |           |          |          |                        |           |           | Package     | ATA:05   |
|                                                                            | MOS                                                                               | 02-Aug-24 |          |          |                        |           |           |             |          |
|                                                                            | HRS                                                                               | 9525.7    | 9600     |          | 19125.7                |           | 9456.6    |             |          |
|                                                                            | AFL                                                                               | 7276      |          |          |                        |           |           |             |          |
| PROC. REF: AMM 05-10-00, AMM 05-16-00PROC. REF: AMM 05-10-00, AMM 05-16-00 |                                                                                   |           |          |          |                        |           |           |             | PKG:26   |
| 051700                                                                     | MAJOR LANDING GEAR INSPECTION                                                     |           |          |          |                        |           |           | Package     | ATA:05   |
|                                                                            | MOS                                                                               | 09-Mar-01 |          |          |                        |           |           |             |          |
|                                                                            | HRS                                                                               | 0         |          |          |                        |           |           |             |          |
|                                                                            | AFL                                                                               | 0         | 10000    |          | 10000                  |           | 2628      |             |          |
| PROC. REF: AMM 05-10-00, AMM 05-17-00PROC. REF: AMM 05-10-00, AMM 05-17-00 |                                                                                   |           |          |          |                        |           |           |             | PKG:27   |
| 057110                                                                     | NO. 1 ENGINE - 150 TO 250 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS |           |          |          |                        |           |           | Package     | ATA:05   |
|                                                                            | MOS                                                                               | 02-Aug-24 |          |          |                        |           |           |             |          |
|                                                                            | HRS                                                                               | 9451.6    | 250      |          | (9701.6)<br>9775.7     |           | 106.6     |             |          |
|                                                                            | ENC                                                                               | 7218      |          |          |                        |           |           |             |          |
| PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00                             |                                                                                   |           |          |          |                        |           |           |             |          |
| 057110                                                                     | NO. 2 ENGINE - 150 TO 250 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS |           |          |          |                        |           |           | Package     | ATA:05   |
|                                                                            | MOS                                                                               | 02-Aug-24 |          |          |                        |           |           |             |          |
|                                                                            | HRS                                                                               | 8612.9    | 250      |          | (8862.9)<br>9775.7     |           | 106.6     |             |          |
|                                                                            | ENC                                                                               | 7114      |          |          |                        |           |           |             |          |
| PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00                             |                                                                                   |           |          |          |                        |           |           |             |          |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C/W   (M)-Manual Due   U-User Task   Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                        | Unit                                                                                | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |        |
|------------------------------------------------|-------------------------------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|----------|--------|
| ATA 05 - TIME LIMITS/MAINTENANCE CHECKS        |                                                                                     |           |          |          |                        |           |           |             |          |        |
| 057120                                         | NO. 1 ENGINE - 300 TO 440 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS   |           |          |          |                        |           |           |             | Package  | ATA:05 |
|                                                | MOS/MSC                                                                             | 22-Jun-23 | N/A      |          |                        |           |           |             |          |        |
|                                                | HRS                                                                                 | 9184.4    |          |          |                        |           |           |             |          |        |
|                                                | ENC                                                                                 | 7042      |          |          |                        |           |           |             |          |        |
| PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00 |                                                                                     |           |          |          |                        |           |           |             |          |        |
| 057120                                         | NO. 2 ENGINE - 300 TO 440 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS   |           |          |          |                        |           |           |             | Package  | ATA:05 |
|                                                | MOS/MSC                                                                             | 18-Aug-22 | N/A      |          |                        |           |           |             |          |        |
|                                                | HRS                                                                                 | 8169.8    |          |          |                        |           |           |             |          |        |
|                                                | ENC                                                                                 | 6832      |          |          |                        |           |           |             |          |        |
| PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00 |                                                                                     |           |          |          |                        |           |           |             |          |        |
| 057130                                         | NO. 1 ENGINE - 500 TO 650 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS   |           |          |          |                        |           |           |             | Package  | ATA:05 |
|                                                | MOS                                                                                 | 22-Jun-23 |          |          |                        |           |           |             |          |        |
|                                                | HRS                                                                                 | 9184.4    | 600      |          | (9784.4)<br>9858.5     |           | 189.4     |             |          |        |
|                                                | ENC                                                                                 | 7042      |          |          |                        |           |           |             |          |        |
| PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00 |                                                                                     |           |          |          |                        |           |           |             |          |        |
| 057130                                         | NO. 2 ENGINE - 500 TO 650 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS   |           |          |          |                        |           |           |             | Package  | ATA:05 |
|                                                | MOS                                                                                 | 22-Jun-23 |          |          |                        |           |           |             |          |        |
|                                                | HRS                                                                                 | 8345.7    | 600      |          | (8945.7)<br>9858.5     |           | 189.4     |             |          |        |
|                                                | ENC                                                                                 | 6938      |          |          |                        |           |           |             |          |        |
| PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00 |                                                                                     |           |          |          |                        |           |           |             |          |        |
| 057140                                         | NO. 1 ENGINE - 500 TO 850 HOUR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS |           |          |          |                        |           |           |             | Package  | ATA:05 |
|                                                | MOS                                                                                 | 18-Aug-22 |          |          |                        |           |           |             |          |        |
|                                                | HRS                                                                                 | 9008.5    | 800      |          | (9808.5)<br>9882.6     |           | 213.5     |             |          |        |
|                                                | ENC                                                                                 | 6936      |          |          |                        |           |           |             |          |        |
| PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00 |                                                                                     |           |          |          |                        |           |           |             |          |        |

?-Insufficient Information
 S-Suppressed Requirement
 \*-Estimated Due(New Requirement)
 (EFF)-Effective C/W
 (M)-Manual Due
 U-User Task
 Ex-Excluded Task

# Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                        | Unit                                                                                  | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty       |
|------------------------------------------------|---------------------------------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|----------------|
| ATA 05 - TIME LIMITS/MAINTENANCE CHECKS        |                                                                                       |           |          |          |                        |           |           |             |                |
| 057140                                         | NO. 2 ENGINE - 500 TO 850 HOUR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS   |           |          |          |                        |           |           |             | Package ATA:05 |
|                                                | MOS                                                                                   | 18-Aug-22 |          |          |                        |           |           |             |                |
|                                                | HRS                                                                                   | 8169.8    | 800      |          | (8969.8)<br>9882.6     |           | 213.5     |             |                |
|                                                | ENC                                                                                   | 6832      |          |          |                        |           |           |             |                |
| PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00 |                                                                                       |           |          |          |                        |           |           |             |                |
| 057150                                         | NO. 1 ENGINE - 1000 TO 1300 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS   |           |          |          |                        |           |           |             | Package ATA:05 |
|                                                | MOS                                                                                   | 27-Aug-21 |          |          |                        |           |           |             |                |
|                                                | HRS                                                                                   | 8634.1    | 1200     |          | (9834.1)<br>9908.2     |           | 239.1     |             |                |
|                                                | ENC                                                                                   | 6633      |          |          |                        |           |           |             |                |
| PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00 |                                                                                       |           |          |          |                        |           |           |             |                |
| 057150                                         | NO. 2 ENGINE - 1000 TO 1300 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS   |           |          |          |                        |           |           |             | Package ATA:05 |
|                                                | MOS                                                                                   | 27-Aug-21 |          |          |                        |           |           |             |                |
|                                                | HRS                                                                                   | 7795.4    | 1200     |          | (8995.4)<br>9908.2     |           | 239.1     |             |                |
|                                                | ENC                                                                                   | 6529      |          |          |                        |           |           |             |                |
| PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00 |                                                                                       |           |          |          |                        |           |           |             |                |
| 057160                                         | NO. 1 ENGINE - 1500 TO 1650 HOUR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS |           |          |          |                        |           |           |             | Package ATA:05 |
|                                                | MOS                                                                                   | 22-Jun-23 |          |          |                        |           |           |             |                |
|                                                | HRS                                                                                   | 9184.4    | 1600     |          | (10784.4)<br>10858.5   |           | 1189.4    |             |                |
|                                                | ENC                                                                                   | 7042      |          |          |                        |           |           |             |                |
| PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00 |                                                                                       |           |          |          |                        |           |           |             |                |
| 057160                                         | NO. 2 ENGINE - 1500 TO 1650 HOUR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS |           |          |          |                        |           |           |             | Package ATA:05 |
|                                                | MOS                                                                                   | 18-Aug-22 |          |          |                        |           |           |             |                |
|                                                | HRS                                                                                   | 8169.8    | 1600     |          | (9769.8)<br>10682.6    |           | 1013.5    |             |                |
|                                                | ENC                                                                                   | 6832      |          |          |                        |           |           |             |                |
| PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00 |                                                                                       |           |          |          |                        |           |           |             |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                            | Unit    | C/W                                                                        | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------|---------|----------------------------------------------------------------------------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 05 - TIME LIMITS/MAINTENANCE CHECKS            |         |                                                                            |          |          |                        |           |           |             |          |
| 5-50-00-BS                                         |         | INSPECTION BIRD STRIKE                                                     |          |          |                        |           |           | Service     | ATA:05   |
|                                                    | MOS/MSC |                                                                            | A/R      |          |                        |           |           | INSPECT     |          |
|                                                    | HRS     |                                                                            |          |          |                        |           |           |             |          |
|                                                    | AFL     |                                                                            |          |          |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |         |                                                                            |          |          |                        |           |           |             |          |
| 5-50-00-EV                                         |         | PERFORM ENGINE VIBRATION TEST AND INSPECTION                               |          |          |                        |           |           | Service     | ATA:05   |
|                                                    | MOS/MSC |                                                                            | A/R      |          |                        |           |           |             |          |
|                                                    | HRS     |                                                                            |          |          |                        |           |           |             |          |
|                                                    | AFL     |                                                                            |          |          |                        |           |           |             |          |
| PROC. REF: AMM 05-50-00PROC. REF: AMM 05-50-00     |         |                                                                            |          |          |                        |           |           |             |          |
| 5-50-00-FD                                         |         | INSPECTION FOREIGN OBJECT DAMAGE                                           |          |          |                        |           |           | Service     | ATA:05   |
|                                                    | MOS/MSC |                                                                            | O/C      |          |                        |           |           |             |          |
|                                                    | HRS     |                                                                            |          |          |                        |           |           |             |          |
|                                                    | AFL     |                                                                            |          |          |                        |           |           |             |          |
| PROC. REF: AMM 05-50-00PROC. REF: AMM 05-50-00     |         |                                                                            |          |          |                        |           |           |             |          |
| 5-50-00-HL                                         |         | INSPECTION HARD LANDING                                                    |          |          |                        |           |           | Service     | ATA:05   |
|                                                    | MOS/MSC |                                                                            | A/R      |          |                        |           |           | INSPECT     |          |
|                                                    | HRS     |                                                                            |          |          |                        |           |           |             |          |
|                                                    | AFL     |                                                                            |          |          |                        |           |           |             |          |
| PROC. REF: AMM 05-50-00PROC. REF: AMM 05-50-00     |         |                                                                            |          |          |                        |           |           |             |          |
| 5-50-00-LS                                         |         | INSPECTION LIGHTNING STRIKE                                                |          |          |                        |           |           | Service     | ATA:05   |
|                                                    | MOS/MSC | 09-Mar-01                                                                  | A/R      |          |                        |           |           | INSPECT     |          |
|                                                    | HRS     | 0                                                                          |          |          |                        |           |           |             |          |
|                                                    | AFL     | 0                                                                          |          |          |                        |           |           |             |          |
| PROC. REF: AMM 05-50-00PROC. REF: AMM 05-50-00     |         |                                                                            |          |          |                        |           |           |             |          |
| 5-50-00-OW                                         |         | INSPECTION OVERWEIGHT LANDING (WEIGHT IN EXCESS OF MAXIMUM LANDING WEIGHT) |          |          |                        |           |           | Service     | ATA:05   |
|                                                    | MOS/MSC |                                                                            | A/R      |          |                        |           |           | INSPECT     |          |
|                                                    | HRS     |                                                                            |          |          |                        |           |           |             |          |
|                                                    | AFL     |                                                                            |          |          |                        |           |           |             |          |
| PROC. REF: AMM 05-50-00PROC. REF: AMM 05-50-00     |         |                                                                            |          |          |                        |           |           |             |          |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C/W   (M)-Manual Due   U-User Task   Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                                                          | Unit                                                                                                 | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition    | Warranty |
|----------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|----------------|----------|
| ATA 08 - LEVELING AND WEIGHING                                                   |                                                                                                      |           |          |          |                        |           |           |                |          |
| 082000                                                                           | REWEIGH AIRCRAFT                                                                                     |           |          |          |                        |           |           | Service        | ATA:08   |
|                                                                                  | MOS                                                                                                  | 30-Dec-22 | 36       |          | 30-Dec-25              |           | 272 d     |                |          |
|                                                                                  | HRS                                                                                                  | 9186.7    |          |          |                        |           |           |                |          |
|                                                                                  | AFL                                                                                                  | 7047      |          |          |                        |           |           |                |          |
| PROC. REF: AMM 08-10-00, FAR FAR 135.185PROC. REF: AMM 08-10-00, FAR FAR 135.185 |                                                                                                      |           |          |          |                        |           |           |                |          |
| ATA 11 - PLACARDS AND MARKINGS                                                   |                                                                                                      |           |          |          |                        |           |           |                |          |
| 112030 <sup>U</sup>                                                              | INSPECTION INTERNAL AND EXTERNAL PLACARD                                                             |           |          |          |                        |           |           | Service        | ATA:11   |
|                                                                                  | MOS/MSC                                                                                              | 09-Mar-01 | A/R      |          |                        |           |           |                |          |
|                                                                                  | HRS                                                                                                  | 0         |          |          |                        |           |           |                |          |
|                                                                                  | AFL                                                                                                  | 0         |          |          |                        |           |           |                |          |
| ATA 12 - SERVICING                                                               |                                                                                                      |           |          |          |                        |           |           |                |          |
| 5-19-00-Q1221064                                                                 | FLAP ACTUATOR JOINT (P/N 145673-1) - APPLY CORROSION PREVENTIVE COMPOUND (CPC). (REFER TO 12-21-03.) |           |          |          |                        |           |           | Service        | ATA:12   |
|                                                                                  | MOS/MSC                                                                                              | 05-Dec-19 | N/A      | Adj -28d |                        |           |           | NOT APPLICABLE |          |
|                                                                                  | HRS                                                                                                  | 8177.8    |          |          |                        |           |           |                |          |
|                                                                                  | AFL                                                                                                  | 6304      |          |          |                        |           |           |                |          |
| PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03                                   |                                                                                                      |           |          |          |                        |           |           |                |          |
| 5-19-00-U1210004                                                                 | LUBRICATE FLAP FLEXIBLE TRANSMISSION SHAFTS - BY HAND (U1210004)                                     |           |          |          |                        |           |           | Service        | ATA:12   |
|                                                                                  | MOS                                                                                                  | 12-Aug-15 |          |          |                        |           |           |                |          |
|                                                                                  | HRS                                                                                                  | 7535.1    | 4800     |          | 12335.1                |           | 2666      |                |          |
|                                                                                  | AFL                                                                                                  | 5764      |          |          |                        |           |           |                |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                               |                                                                                                      |           |          |          |                        |           |           |                |          |
| AB1210060 <sup>S</sup>                                                           | MAIN LANDING GEAR UP-LOCK ACTUATOR - LUBRICATE                                                       |           |          |          |                        |           |           | Service        | ATA:12   |
|                                                                                  | MOS                                                                                                  | 02-Aug-24 | 12       |          |                        |           |           |                |          |
|                                                                                  | HRS                                                                                                  | 9525.7    | 300      |          |                        |           |           |                |          |
|                                                                                  | AFL                                                                                                  | 7276      |          |          |                        |           |           |                |          |
| PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01                                   |                                                                                                      |           |          |          |                        |           |           |                |          |
| PKG:5                                                                            |                                                                                                      |           |          |          |                        |           |           |                |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR    Serial: 45-145    RegNo: N942FK    HRS: 9669.1    AFL: 7372    As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                        | Unit | C / W                                                                                 | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|------------------------------------------------|------|---------------------------------------------------------------------------------------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 12 - SERVICING                             |      |                                                                                       |          |          |                        |           |           |             |          |
| O1210002 <sup>S</sup>                          |      | FLAP ACTUATORS - CHECK OIL LEVEL.                                                     |          |          |                        |           |           | Service     | ATA:12   |
|                                                | MOS  | 02-Aug-24                                                                             | 24       |          |                        |           |           |             |          |
|                                                | HRS  | 9525.7                                                                                | 600      |          |                        |           |           |             |          |
|                                                | AFL  | 7276                                                                                  |          |          |                        |           |           |             |          |
| PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03 |      |                                                                                       |          |          |                        |           |           |             | PKG:10   |
| Y1210000 <sup>S</sup>                          |      | NOSE LANDING GEAR SHOCK STRUT - CHECK FOR PROPER FLUID LEVEL AND INFLATION PRESSURE.  |          |          |                        |           |           | Service     | ATA:12   |
|                                                | MOS  | 02-Aug-24                                                                             | 12       |          |                        |           |           |             |          |
|                                                | HRS  | 9525.7                                                                                | 300      |          |                        |           |           |             |          |
|                                                | AFL  | 7276                                                                                  |          |          |                        |           |           |             |          |
| PROC. REF: AMM 12-10-02PROC. REF: AMM 12-10-02 |      |                                                                                       |          |          |                        |           |           |             | PKG:5    |
| Y1210001 <sup>S</sup>                          |      | MAIN LANDING GEAR SHOCK STRUTS - CHECK FOR PROPER FLUID LEVEL AND INFLATION PRESSURE. |          |          |                        |           |           | Service     | ATA:12   |
|                                                | MOS  | 02-Aug-24                                                                             | 12       |          |                        |           |           |             |          |
|                                                | HRS  | 9525.7                                                                                | 300      |          |                        |           |           |             |          |
|                                                | AFL  | 7276                                                                                  |          |          |                        |           |           |             |          |
| PROC. REF: AMM 12-10-03PROC. REF: AMM 12-10-03 |      |                                                                                       |          |          |                        |           |           |             | PKG:5    |
| Y1210003 <sup>S</sup>                          |      | FLAP ACTUATOR BALLNUT - LUBRICATE.                                                    |          |          |                        |           |           | Service     | ATA:12   |
|                                                | MOS  | 02-Aug-24                                                                             | 12       |          |                        |           |           |             |          |
|                                                | HRS  | 9525.7                                                                                | 300      |          |                        |           |           |             |          |
|                                                | AFL  | 7276                                                                                  |          |          |                        |           |           |             |          |
| PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03 |      |                                                                                       |          |          |                        |           |           |             | PKG:4    |
| Y1210005 <sup>S</sup>                          |      | NOSE LANDING GEAR TRUNNION PIN - LUBRICATE.                                           |          |          |                        |           |           | Service     | ATA:12   |
|                                                | MOS  | 02-Aug-24                                                                             | 12       |          |                        |           |           |             |          |
|                                                | HRS  | 9525.7                                                                                | 300      |          |                        |           |           |             |          |
|                                                | AFL  | 7276                                                                                  |          |          |                        |           |           |             |          |
| PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01 |      |                                                                                       |          |          |                        |           |           |             | PKG:5    |

?-Insufficient Information    S-Suppressed Requirement    \*-Estimated Due(New Requirement)    (EFF)-Effective C/W    (M)-Manual Due    U-User Task    Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                        | Unit | C / W                                                  | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|------------------------------------------------|------|--------------------------------------------------------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 12 - SERVICING                             |      |                                                        |          |          |                        |           |           |             |          |
| Y1210006 <sup>S</sup>                          |      | NOSE LANDING GEAR ACTUATOR ATTACH FITTING - LUBRICATE. |          |          |                        |           |           | Service     | ATA:12   |
|                                                | MOS  | 02-Aug-24                                              | 12       |          |                        |           |           |             |          |
|                                                | HRS  | 9525.7                                                 | 300      |          |                        |           |           |             |          |
|                                                | AFL  | 7276                                                   |          |          |                        |           |           |             |          |
| PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01 |      |                                                        |          |          |                        |           |           |             | PKG:5    |
| Y1210007 <sup>S</sup>                          |      | NOSE AND MAIN TIRES - CHECK FOR PROPER INFLATION.      |          |          |                        |           |           | Service     | ATA:12   |
|                                                | MOS  | 02-Aug-24                                              | 12       |          |                        |           |           |             |          |
|                                                | HRS  | 9525.7                                                 | 300      |          |                        |           |           |             |          |
|                                                | AFL  | 7276                                                   |          |          |                        |           |           |             |          |
| PROC. REF: AMM 12-10-04PROC. REF: AMM 12-10-04 |      |                                                        |          |          |                        |           |           |             | PKG:5    |
| Y1210009 <sup>S</sup>                          |      | NOSE GEAR DOOR HINGE - LUBRICATE.                      |          |          |                        |           |           | Service     | ATA:12   |
|                                                | MOS  | 02-Aug-24                                              | 12       |          |                        |           |           |             |          |
|                                                | HRS  | 9525.7                                                 | 300      |          |                        |           |           |             |          |
|                                                | AFL  | 7276                                                   |          |          |                        |           |           |             |          |
| PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02 |      |                                                        |          |          |                        |           |           |             | PKG:1    |
| Y1210011 <sup>S</sup>                          |      | MAIN LANDING GEAR ACTUATOR JOINTS - LUBRICATE.         |          |          |                        |           |           | Service     | ATA:12   |
|                                                | MOS  | 02-Aug-24                                              | 12       |          |                        |           |           |             |          |
|                                                | HRS  | 9525.7                                                 | 300      |          |                        |           |           |             |          |
|                                                | AFL  | 7276                                                   |          |          |                        |           |           |             |          |
| PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01 |      |                                                        |          |          |                        |           |           |             | PKG:5    |
| Y1210012 <sup>S</sup>                          |      | MAIN LANDING GEAR AXLE BEAM/PISTON JOINTS - LUBRICATE. |          |          |                        |           |           | Service     | ATA:12   |
|                                                | MOS  | 02-Aug-24                                              | 12       |          |                        |           |           |             |          |
|                                                | HRS  | 9525.7                                                 | 300      |          |                        |           |           |             |          |
|                                                | AFL  | 7276                                                   |          |          |                        |           |           |             |          |
| PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01 |      |                                                        |          |          |                        |           |           |             | PKG:5    |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 9669.1
AFL: 7372
As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                        | Unit         | C / W                                          | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|------------------------------------------------|--------------|------------------------------------------------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 12 - SERVICING                             |              |                                                |          |          |                        |           |           |             |          |
| Y1210013                                       | <sup>S</sup> | MAIN LANDING GEAR TORQUE LINKS - LUBRICATE.    |          |          |                        |           |           | Service     | ATA:12   |
|                                                | MOS          | 02-Aug-24                                      | 12       |          |                        |           |           |             |          |
|                                                | HRS          | 9525.7                                         | 300      |          |                        |           |           |             |          |
|                                                | AFL          | 7276                                           |          |          |                        |           |           |             |          |
| PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01 |              |                                                |          |          |                        |           |           |             | PKG:5    |
| Y1210014                                       | <sup>S</sup> | MAIN GEAR DOOR HINGE - LUBRICATE               |          |          |                        |           |           | Service     | ATA:12   |
|                                                | MOS          | 02-Aug-24                                      | 12       |          |                        |           |           |             |          |
|                                                | HRS          | 9525.7                                         | 300      |          |                        |           |           |             |          |
|                                                | AFL          | 7276                                           |          |          |                        |           |           |             |          |
| PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02 |              |                                                |          |          |                        |           |           |             | PKG:5    |
| Y1210016                                       | <sup>S</sup> | PASSENGER/CREW DOOR HINGE - LUBRICATE          |          |          |                        |           |           | Service     | ATA:12   |
|                                                | MOS          | 02-Aug-24                                      | 12       |          |                        |           |           |             |          |
|                                                | HRS          | 9525.7                                         | 300      |          |                        |           |           |             |          |
|                                                | AFL          | 7276                                           |          |          |                        |           |           |             |          |
| PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02 |              |                                                |          |          |                        |           |           |             | PKG:6    |
| Y1210017                                       | <sup>S</sup> | PASSENGER/CREW DOOR PINS - LUBRICATE           |          |          |                        |           |           | Service     | ATA:12   |
|                                                | MOS          | 02-Aug-24                                      | 12       |          |                        |           |           |             |          |
|                                                | HRS          | 9525.7                                         | 300      |          |                        |           |           |             |          |
|                                                | AFL          | 7276                                           |          |          |                        |           |           |             |          |
| PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02 |              |                                                |          |          |                        |           |           |             | PKG:6    |
| Y1210018                                       | <sup>S</sup> | PASSENGER/CREW DOOR TENSION BOLTS - LUBRICATE. |          |          |                        |           |           | Service     | ATA:12   |
|                                                | MOS          | 02-Aug-24                                      | 12       |          |                        |           |           |             |          |
|                                                | HRS          | 9525.7                                         | 300      |          |                        |           |           |             |          |
|                                                | AFL          | 7276                                           |          |          |                        |           |           |             |          |
| PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02 |              |                                                |          |          |                        |           |           |             | PKG:6    |

? - Insufficient Information
S - Suppressed Requirement
\* - Estimated Due(New Requirement)
(EFF) - Effective C / W
(M) - Manual Due
U - User Task
Ex - Excluded Task



Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                        | Unit         | C/W                                                 | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|------------------------------------------------|--------------|-----------------------------------------------------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 12 - SERVICING                             |              |                                                     |          |          |                        |           |           |             |          |
| Y1210019                                       | <sup>S</sup> | EMERGENCY EXIT DOOR LATCHING MECHANISM - LUBRICATE. |          |          |                        |           |           | Service     | ATA:12   |
|                                                | MOS          | 02-Aug-24                                           | 12       |          |                        |           |           |             |          |
|                                                | HRS          | 9525.7                                              | 300      |          |                        |           |           |             |          |
|                                                | AFL          | 7276                                                |          |          |                        |           |           |             |          |
| PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02 |              |                                                     |          |          |                        |           |           |             | PKG:6    |
| Y1210020                                       | <sup>S</sup> | EMERGENCY EXIT DOOR PINS - LUBRICATE.               |          |          |                        |           |           | Service     | ATA:12   |
|                                                | MOS          | 02-Aug-24                                           | 12       |          |                        |           |           |             |          |
|                                                | HRS          | 9525.7                                              | 300      |          |                        |           |           |             |          |
|                                                | AFL          | 7276                                                |          |          |                        |           |           |             |          |
| PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02 |              |                                                     |          |          |                        |           |           |             | PKG:6    |
| Y1210021                                       | <sup>S</sup> | BAGGAGE COMPARTMENT DOOR LATCH PINS - LUBRICATE.    |          |          |                        |           |           | Service     | ATA:12   |
|                                                | MOS          | 02-Aug-24                                           | 12       |          |                        |           |           |             |          |
|                                                | HRS          | 9525.7                                              | 300      |          |                        |           |           |             |          |
|                                                | AFL          | 7276                                                |          |          |                        |           |           |             |          |
| PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02 |              |                                                     |          |          |                        |           |           |             | PKG:6    |
| Y1210022                                       | <sup>S</sup> | BAGGAGE COMPARTMENT DOOR HINGE - LUBRICATE          |          |          |                        |           |           | Service     | ATA:12   |
|                                                | MOS          | 02-Aug-24                                           | 12       |          |                        |           |           |             |          |
|                                                | HRS          | 9525.7                                              | 300      |          |                        |           |           |             |          |
|                                                | AFL          | 7276                                                |          |          |                        |           |           |             |          |
| PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02 |              |                                                     |          |          |                        |           |           |             | PKG:6    |
| Y1210023                                       | <sup>S</sup> | OXYGEN SYSTEM SERVICING DOOR HINGE - LUBRICATE      |          |          |                        |           |           | Service     | ATA:12   |
|                                                | MOS          | 02-Aug-24                                           | 12       |          |                        |           |           |             |          |
|                                                | HRS          | 9525.7                                              | 300      |          |                        |           |           |             |          |
|                                                | AFL          | 7276                                                |          |          |                        |           |           |             |          |
| PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02 |              |                                                     |          |          |                        |           |           |             | PKG:1    |

?-Insufficient Information

S-Suppressed Requirement

\*-Estimated Due(New Requirement)

(EFF)-Effective C/W

(M)-Manual Due

U-User Task

Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                        | Unit | C / W                                       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|------------------------------------------------|------|---------------------------------------------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 12 - SERVICING                             |      |                                             |          |          |                        |           |           |             |          |
| Y1210024 <sup>S</sup>                          |      | TOILET SERVICING DOOR HINGE - LUBRICATE.    |          |          |                        |           |           | Service     | ATA:12   |
|                                                | MOS  | 02-Aug-24                                   | 12       |          |                        |           |           |             |          |
|                                                | HRS  | 9525.7                                      | 300      |          |                        |           |           |             |          |
|                                                | AFL  | 7276                                        |          |          |                        |           |           |             |          |
| PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02 |      |                                             |          |          |                        |           |           |             | PKG:4    |
| Y1210025 <sup>S</sup>                          |      | PRESSURE REFUELING DOOR HINGE - LUBRICATE.  |          |          |                        |           |           | Service     | ATA:12   |
|                                                | MOS  | 02-Aug-24                                   | 12       |          |                        |           |           |             |          |
|                                                | HRS  | 9525.7                                      | 300      |          |                        |           |           |             |          |
|                                                | AFL  | 7276                                        |          |          |                        |           |           |             |          |
| PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02 |      |                                             |          |          |                        |           |           |             | PKG:2    |
| Y1210026 <sup>S</sup>                          |      | FUSELAGE FUEL FILLER DOOR HINGE - LUBRICATE |          |          |                        |           |           | Service     | ATA:12   |
|                                                | MOS  | 02-Aug-24                                   | 12       |          |                        |           |           |             |          |
|                                                | HRS  | 9525.7                                      | 300      |          |                        |           |           |             |          |
|                                                | AFL  | 7276                                        |          |          |                        |           |           |             |          |
| PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02 |      |                                             |          |          |                        |           |           |             | PKG:2    |
| Y1210027 <sup>S</sup>                          |      | TAILCONE ACCESS DOOR PINS - LUBRICATE       |          |          |                        |           |           | Service     | ATA:12   |
|                                                | MOS  | 02-Aug-24                                   | 12       |          |                        |           |           |             |          |
|                                                | HRS  | 9525.7                                      | 300      |          |                        |           |           |             |          |
|                                                | AFL  | 7276                                        |          |          |                        |           |           |             |          |
| PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02 |      |                                             |          |          |                        |           |           |             | PKG:6    |
| Y1210028 <sup>S</sup>                          |      | TAILCONE ACCESS DOOR HINGE - LUBRICATE.     |          |          |                        |           |           | Service     | ATA:12   |
|                                                | MOS  | 02-Aug-24                                   | 12       |          |                        |           |           |             |          |
|                                                | HRS  | 9525.7                                      | 300      |          |                        |           |           |             |          |
|                                                | AFL  | 7276                                        |          |          |                        |           |           |             |          |
| PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02 |      |                                             |          |          |                        |           |           |             | PKG:6    |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                        | Unit    | C / W                                                             | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|------------------------------------------------|---------|-------------------------------------------------------------------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 12 - SERVICING                             |         |                                                                   |          |          |                        |           |           |             |          |
| Y1210029 <sup>S</sup>                          |         | MAIN LANDING GEAR TRUNNION PIN - LUBRICATE                        |          |          |                        |           |           | Service     | ATA:12   |
|                                                | MOS     | 02-Aug-24                                                         | 12       |          |                        |           |           |             |          |
|                                                | HRS     | 9525.7                                                            | 300      |          |                        |           |           |             |          |
|                                                | AFL     | 7276                                                              |          |          |                        |           |           |             |          |
| PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01 |         |                                                                   |          |          |                        |           |           |             | PKG:5    |
|                                                |         |                                                                   |          |          |                        |           |           |             |          |
| Y1221037 <sup>S</sup>                          |         | FLAPS - LUBRICATE ROLLING SURFACES OF MAIN AND NOSE ROLLER TRACKS |          |          |                        |           |           | Service     | ATA:12   |
|                                                | MOS     | 02-Aug-24                                                         | 12       |          |                        |           |           |             |          |
|                                                | HRS     | 9525.7                                                            | 300      |          |                        |           |           |             |          |
|                                                | AFL     | 7276                                                              |          |          |                        |           |           |             |          |
| PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03 |         |                                                                   |          |          |                        |           |           |             | PKG:4    |
|                                                |         |                                                                   |          |          |                        |           |           |             |          |
| Y1221042 <sup>S</sup>                          |         | HORIZONTAL STABILIZER UPPER AND LOWER TORQUE LINKS - LUBRICATE    |          |          |                        |           |           | Service     | ATA:12   |
|                                                | MOS     | 02-Aug-24                                                         | 24       |          |                        |           |           |             |          |
|                                                | HRS     | 9525.7                                                            | 600      |          |                        |           |           |             |          |
|                                                | AFL     | 7276                                                              |          |          |                        |           |           |             |          |
| PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03 |         |                                                                   |          |          |                        |           |           |             | PKG:9    |
|                                                |         |                                                                   |          |          |                        |           |           |             |          |
| Y1227000 <sup>S</sup>                          |         | EMERGENCY PARK BRAKE HANDLE SHAFT - LUBRICATE                     |          |          |                        |           |           | Service     | ATA:12   |
|                                                | MOS     | 02-Aug-24                                                         | 12       |          |                        |           |           |             |          |
|                                                | HRS     | 9525.7                                                            | 300      |          |                        |           |           |             |          |
|                                                | AFL     | 7276                                                              |          |          |                        |           |           |             |          |
| PROC. REF: AMM 12-27-00PROC. REF: AMM 12-27-00 |         |                                                                   |          |          |                        |           |           |             | PKG:1    |
|                                                |         |                                                                   |          |          |                        |           |           |             |          |
| ATA 21 - AIR CONDITIONING                      |         |                                                                   |          |          |                        |           |           |             |          |
| 211001                                         |         | SERVO AIR PRESSURE REGULATING VALVE                               |          |          |                        |           |           | Component   | ATA:21   |
| PN:PN                                          | MOS/MSC | 09-Mar-01                                                         | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS     | 0                                                                 |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL     | 0                                                                 |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 36-15-01PROC. REF: AMM 36-15-01 |         |                                                                   |          |          |                        |           |           |             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9669.1
 AFL: 7372
 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                        | Unit                                                 | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|------------------------------------------------|------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 21 - AIR CONDITIONING                      |                                                      |           |          |          |                        |           |           |             |                  |
| 211011                                         | LEFT PLENUM CHECK VALVE                              |           |          |          |                        |           |           |             | Component ATA:21 |
| PN:PN                                          | MOS/MSC                                              | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                                  | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                                  | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 21-20-09PROC. REF: AMM 21-20-09 |                                                      |           |          |          |                        |           |           |             |                  |
| 211012                                         | RIGHT PLENUM CHECK VALVE                             |           |          |          |                        |           |           |             | Component ATA:21 |
| PN:PN                                          | MOS/MSC                                              | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                                  | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                                  | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 21-20-09PROC. REF: AMM 21-20-09 |                                                      |           |          |          |                        |           |           |             |                  |
| 211017                                         | LEFT EMERGENCY PRESSURIZATION ISOLATION CHECK VALVE  |           |          |          |                        |           |           |             | Component ATA:21 |
| PN:PN                                          | MOS/MSC                                              | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                                  | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                                  | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 21-20-03PROC. REF: AMM 21-20-03 |                                                      |           |          |          |                        |           |           |             |                  |
| 211018                                         | RIGHT EMERGENCY PRESSURIZATION ISOLATION CHECK VALVE |           |          |          |                        |           |           |             | Component ATA:21 |
| PN:PN                                          | MOS/MSC                                              | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                                  | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                                  | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 21-20-03PROC. REF: AMM 21-20-03 |                                                      |           |          |          |                        |           |           |             |                  |
| 212001                                         | COCKPIT AIR CHECK VALVE                              |           |          |          |                        |           |           |             | Component ATA:21 |
| PN:PN                                          | MOS/MSC                                              | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                                  | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                                  | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 21-20-01PROC. REF: AMM 21-20-01 |                                                      |           |          |          |                        |           |           |             |                  |
| 212007                                         | AFT BLOWER MOTOR                                     |           |          |          |                        |           |           |             | Component ATA:21 |
| PN:PN                                          | MOS/MSC                                              | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                                  | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                                  | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 21-51-09PROC. REF: AMM 21-51-09 |                                                      |           |          |          |                        |           |           |             |                  |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C/W   (M)-Manual Due   U-User Task   Ex-Excluded Task

# Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9669.1
 AFL: 7372
 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                            | Unit                               | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------|------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 21 - AIR CONDITIONING                          |                                    |           |          |          |                        |           |           |             |                  |
| 212008                                             | FORWARD BLOWER MOTOR               |           |          |          |                        |           |           |             | Component ATA:21 |
| PN:PN                                              | MOS/MSC                            | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                    |           |          |          |                        |           |           |             |                  |
| 212011                                             | LINEAR ELECTRO-MECHANICAL ACTUATOR |           |          |          |                        |           |           |             | Component ATA:21 |
| PN:PN                                              | MOS/MSC                            | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                    |           |          |          |                        |           |           |             |                  |
| 212041                                             | LEFT ENGINE OZONE CONVERTER        |           |          |          |                        |           |           |             | Component ATA:21 |
| PN:4520000100-801                                  | MOS/MSC                            | 01-Apr-22 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:2298                                            | HRS                                | 8936.8    |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                | 6867      |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 21-20-12PROC. REF: AMM 21-20-12     |                                    |           |          |          |                        |           |           |             |                  |
| 212041A                                            | TEST LEFT EFFICIENCY. (Y2140001)   |           |          |          |                        |           |           |             | Service ATA:21   |
| PN:4520000100-801                                  | MOS                                | 01-Apr-22 |          |          |                        |           |           |             |                  |
| SN:2298                                            | HRS                                | 8936.8    | 3600     |          | 12536.8                |           | 2867.7    |             |                  |
|                                                    | AFL                                | 6867      |          |          |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                    |           |          |          |                        |           |           |             |                  |
| 212042                                             | RIGHT ENGINE OZONE CONVERTER       |           |          |          |                        |           |           |             | Component ATA:21 |
| PN:4520000100-801                                  | MOS/MSC                            | 01-Apr-22 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:2305                                            | HRS                                | 8936.8    |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                | 6867      |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 21-20-12PROC. REF: AMM 21-20-12     |                                    |           |          |          |                        |           |           |             |                  |
| 212042A                                            | TEST RIGHT EFFICIENCY (Y2140001)   |           |          |          |                        |           |           |             | Service ATA:21   |
| PN:4520000100-801                                  | MOS                                | 01-Apr-22 |          |          |                        |           |           |             |                  |
| SN:2305                                            | HRS                                | 8936.8    | 3600     |          | 12536.8                |           | 2867.7    |             |                  |
|                                                    | AFL                                | 6867      |          |          |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                    |           |          |          |                        |           |           |             |                  |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C/W   (M)-Manual Due   U-User Task   Ex-Excluded Task

# Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9669.1
 AFL: 7372
 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                            | Unit                                               | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------|----------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 21 - AIR CONDITIONING                          |                                                    |           |          |          |                        |           |           |             |                  |
| 212101                                             | NO. 1 THERMAL CONTROL ACTUATOR                     |           |          |          |                        |           |           |             | Component ATA:21 |
| PN:PN                                              | MOS/MSC                                            | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                                | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                                | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                    |           |          |          |                        |           |           |             |                  |
| 212102                                             | NO. 2 THERMAL CONTROL ACTUATOR                     |           |          |          |                        |           |           |             | Component ATA:21 |
| PN:PN                                              | MOS/MSC                                            | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                                | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                                | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                    |           |          |          |                        |           |           |             |                  |
| 212105                                             | LEFT ENVIRONMENTAL CONTROL SYSTEM TRANSITION DUCT  |           |          |          |                        |           |           |             | Component ATA:21 |
| PN:PN                                              | MOS/MSC                                            | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                                | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                                | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                    |           |          |          |                        |           |           |             |                  |
| 212106                                             | RIGHT ENVIRONMENTAL CONTROL SYSTEM TRANSITION DUCT |           |          |          |                        |           |           |             | Component ATA:21 |
| PN:PN                                              | MOS/MSC                                            | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                                | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                                | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                    |           |          |          |                        |           |           |             |                  |
| 212201                                             | LEFT GASPER AIR CHECK VALVE                        |           |          |          |                        |           |           |             | Component ATA:21 |
| PN:PN                                              | MOS/MSC                                            | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                                | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                                | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 21-20-07PROC. REF: AMM 21-20-07     |                                                    |           |          |          |                        |           |           |             |                  |
| 212202                                             | RIGHT GASPER AIR CHECK VALVE                       |           |          |          |                        |           |           |             | Component ATA:21 |
| PN:PN                                              | MOS/MSC                                            | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                                | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                                | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 21-20-07PROC. REF: AMM 21-20-07     |                                                    |           |          |          |                        |           |           |             |                  |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C/W   (M)-Manual Due   U-User Task   Ex-Excluded Task

# Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9669.1
 AFL: 7372
 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                        | Unit                                   | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|------------------------------------------------|----------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 21 - AIR CONDITIONING                      |                                        |           |          |          |                        |           |           |             |                  |
| 212213                                         | LEFT CABIN AIR CHECK VALVE             |           |          |          |                        |           |           |             | Component ATA:21 |
| PN:PN                                          | MOS/MSC                                | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                    | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                    | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 21-20-02PROC. REF: AMM 21-20-02 |                                        |           |          |          |                        |           |           |             |                  |
| 212214                                         | RIGHT CABIN AIR CHECK VALVE            |           |          |          |                        |           |           |             | Component ATA:21 |
| PN:PN                                          | MOS/MSC                                | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                    | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                    | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 21-20-02PROC. REF: AMM 21-20-02 |                                        |           |          |          |                        |           |           |             |                  |
| 212801                                         | AVIONICS COOLING FAN MOUNT             |           |          |          |                        |           |           |             | Component ATA:21 |
| PN:PN                                          | MOS/MSC                                | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                    | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                    | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 21-21-01PROC. REF: AMM 21-21-01 |                                        |           |          |          |                        |           |           |             |                  |
| 213000                                         | CABIN PRESSURE CONTROLLER              |           |          |          |                        |           |           |             | Component ATA:21 |
| PN:6628408000-023<br>(10551B08Y09)             | MOS/MSC                                | 17-Feb-05 | O/C      | TSR 0    |                        |           |           |             |                  |
| SN:0716                                        | HRS                                    | 3300.2    |          | TSR 0    |                        |           |           |             |                  |
|                                                | AFL                                    | 2515      |          | TSR 0    |                        |           |           |             |                  |
| PROC. REF: AMM 21-30-03PROC. REF: AMM 21-30-03 |                                        |           |          |          |                        |           |           |             |                  |
| 213001                                         | LEFT EMERGENCY PRESSURE SHUTOFF VALVE  |           |          |          |                        |           |           |             | Component ATA:21 |
| PN:3291224-1                                   | MOS/MSC                                | 03-Dec-09 | O/C      |          |                        |           |           |             |                  |
| SN:133                                         | HRS                                    | 6212.8    |          |          |                        |           |           |             |                  |
|                                                | AFL                                    | 4758      |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 21-31-01PROC. REF: AMM 21-31-01 |                                        |           |          |          |                        |           |           |             |                  |
| 213002                                         | RIGHT EMERGENCY PRESSURE SHUTOFF VALVE |           |          |          |                        |           |           |             | Component ATA:21 |
| PN:PN                                          | MOS/MSC                                | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                    | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                    | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 21-31-01PROC. REF: AMM 21-31-01 |                                        |           |          |          |                        |           |           |             |                  |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C/W   (M)-Manual Due   U-User Task   Ex-Excluded Task

# Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 9669.1
AFL: 7372
As Of: 01-Apr-2025
02-Apr-2025 02:58 PM

| PN & SN                                            | Unit                              | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------|-----------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 21 - AIR CONDITIONING                          |                                   |           |          |          |                        |           |           |             |                  |
| 213021                                             | JET PUMP EJECTOR                  |           |          |          |                        |           |           |             | Component ATA:21 |
| PN:PN                                              | MOS/MSC                           | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 21-30-06PROC. REF: AMM 21-30-06     |                                   |           |          |          |                        |           |           |             |                  |
| 213031                                             | PRIMARY OUTFLOW VALVE             |           |          |          |                        |           |           |             | Component ATA:21 |
| PN:PN                                              | MOS/MSC                           | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 21-30-01PROC. REF: AMM 21-30-01     |                                   |           |          |          |                        |           |           |             |                  |
| 213032                                             | SECONDARY OUTFLOW VALVE           |           |          |          |                        |           |           |             | Component ATA:21 |
| PN:PN                                              | MOS/MSC                           | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 21-30-02PROC. REF: AMM 21-30-02     |                                   |           |          |          |                        |           |           |             |                  |
| 213055                                             | EMERGENCY PRESSURE ANEROID SWITCH |           |          |          |                        |           |           |             | Component ATA:21 |
| PN:PN                                              | MOS/MSC                           | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                   |           |          |          |                        |           |           |             |                  |
| 213056                                             | ABSOLUTE PRESSURE SWITCH          |           |          |          |                        |           |           |             | Component ATA:21 |
| PN:PN                                              | MOS/MSC                           | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                   |           |          |          |                        |           |           |             |                  |
| 213101                                             | TAILCONE CHECK VALVE              |           |          |          |                        |           |           |             | Component ATA:21 |
| PN:PN                                              | MOS/MSC                           | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                   |           |          |          |                        |           |           |             |                  |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C/W   (M)-Manual Due   U-User Task   Ex-Excluded Task



# Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 9669.1
AFL: 7372
As Of: 01-Apr-2025
02-Apr-2025 02:58 PM

| PN & SN                                            | Unit                             | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------|----------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 21 - AIR CONDITIONING                          |                                  |           |          |          |                        |           |           |             |                  |
| 213110                                             | CABIN PRESSURIZATION CHECK VALVE |           |          |          |                        |           |           |             | Component ATA:21 |
| PN:PN                                              | MOS/MSC                          | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                              | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                              | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 21-30-07PROC. REF: AMM 21-30-07     |                                  |           |          |          |                        |           |           |             |                  |
| 214301                                             | FOOT WARMER (S167) THERMOSTAT    |           |          |          |                        |           |           |             | Component ATA:21 |
| PN:PN                                              | MOS/MSC                          | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                              | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                              | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 21-41-02PROC. REF: AMM 21-41-02     |                                  |           |          |          |                        |           |           |             |                  |
| 214925                                             | LEFT ECS CHECK VALVE             |           |          |          |                        |           |           |             | Component ATA:21 |
| PN:PN                                              | MOS/MSC                          | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                              | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                              | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 36-10-04PROC. REF: AMM 36-10-04     |                                  |           |          |          |                        |           |           |             |                  |
| 214926                                             | RIGHT ECS CHECK VALVE            |           |          |          |                        |           |           |             | Component ATA:21 |
| PN:PN                                              | MOS/MSC                          | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                              | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                              | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 36-10-04PROC. REF: AMM 36-10-04     |                                  |           |          |          |                        |           |           |             |                  |
| 215001                                             | WATER SEPARATOR ASSEMBLY         |           |          |          |                        |           |           |             | Component ATA:21 |
| PN:PN                                              | MOS/MSC                          | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                              | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                              | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 21-50-03PROC. REF: AMM 21-50-03     |                                  |           |          |          |                        |           |           |             |                  |
| 215002                                             | WATER SEPARATOR BYPASS VALVE     |           |          |          |                        |           |           |             | Component ATA:21 |
| PN:PN                                              | MOS/MSC                          | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                              | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                              | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                  |           |          |          |                        |           |           |             |                  |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C/W   (M)-Manual Due   U-User Task   Ex-Excluded Task

# Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9669.1
 AFL: 7372
 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                        | Unit                                          | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|------------------------------------------------|-----------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 21 - AIR CONDITIONING                      |                                               |           |          |          |                        |           |           |             |                  |
| 215010                                         | AIR CYCLE MACHINE PRECOOLER ASSEMBLY          |           |          |          |                        |           |           |             | Component ATA:21 |
| PN:PN                                          | MOS/MSC                                       | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 21-50-08PROC. REF: AMM 21-50-08 |                                               |           |          |          |                        |           |           |             |                  |
| 215013                                         | PACK BI-LEVEL PRESURE REGULATOR SHUTOFF VALVE |           |          |          |                        |           |           |             | Component ATA:21 |
| PN:PN                                          | MOS/MSC                                       | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 21-50-02PROC. REF: AMM 21-50-02 |                                               |           |          |          |                        |           |           |             |                  |
| 215015                                         | AIR CYCLE MACHINE BYPASS CHECK VALVE          |           |          |          |                        |           |           |             | Component ATA:21 |
| PN:PN                                          | MOS/MSC                                       | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 21-50-07PROC. REF: AMM 21-50-07 |                                               |           |          |          |                        |           |           |             |                  |
| 215019                                         | CABIN REFRIGERATION CONDENSER                 |           |          |          |                        |           |           |             | Component ATA:21 |
| PN:PN                                          | MOS/MSC                                       | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 21-51-04PROC. REF: AMM 21-51-04 |                                               |           |          |          |                        |           |           |             |                  |
| 215030                                         | ENVIRONMENTAL CONTROL UNIT                    |           |          |          |                        |           |           |             | Component ATA:21 |
| PN:PN                                          | MOS/MSC                                       | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 21-50-01PROC. REF: AMM 21-50-01 |                                               |           |          |          |                        |           |           |             |                  |
| 215033                                         | AIR CYCLE MACHINE                             |           |          |          |                        |           |           |             | Component ATA:21 |
| PN:PN                                          | MOS/MSC                                       | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 21-50-04PROC. REF: AMM 21-50-04 |                                               |           |          |          |                        |           |           |             |                  |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C/W   (M)-Manual Due   U-User Task   Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                            | Unit                                    | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------|-----------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 21 - AIR CONDITIONING                          |                                         |           |          |          |                        |           |           |             |                  |
| 215036                                             | HEAT, PRIMARY, SECONDARY EXCHANGER      |           |          |          |                        |           |           |             | Component ATA:21 |
| PN:PN                                              | MOS/MSC                                 | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                         |           |          |          |                        |           |           |             |                  |
| 215039                                             | AIR CYCLE MACHINE TURBINE               |           |          |          |                        |           |           |             | Component ATA:21 |
| PN:PN                                              | MOS/MSC                                 | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 21-50-04PROC. REF: AMM 21-50-04     |                                         |           |          |          |                        |           |           |             |                  |
| 215043                                             | AFT EVAPORATOR                          |           |          |          |                        |           |           |             | Component ATA:21 |
| PN:PN                                              | MOS/MSC                                 | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 21-51-09PROC. REF: AMM 21-51-09     |                                         |           |          |          |                        |           |           |             |                  |
| 215044                                             | FORWARD EVAPORATOR                      |           |          |          |                        |           |           |             | Component ATA:21 |
| PN:PN                                              | MOS/MSC                                 | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 21-51-07PROC. REF: AMM 21-51-07     |                                         |           |          |          |                        |           |           |             |                  |
| 215100                                             | AIR CONDITIONING COMPRESSOR             |           |          |          |                        |           |           |             | Component ATA:21 |
| PN:JBS222-1                                        | MOS/MSC                                 | 26-Jul-23 | O/C      | TSO 0    |                        |           |           |             |                  |
| SN:K18869                                          | HRS                                     | 9278      |          | TSO 0    |                        |           |           |             |                  |
|                                                    | AFL                                     | 7111      |          | TSO 0    |                        |           |           |             |                  |
| PROC. REF: AMM 21-51-01PROC. REF: AMM 21-51-01     |                                         |           |          |          |                        |           |           |             |                  |
| 215101                                             | AIR CONDITIONING COMPRESSOR DRIVE MOTOR |           |          |          |                        |           |           |             | Component ATA:21 |
| PN:MB86B-6                                         | MOS/MSC                                 | 31-Jul-23 | O/C      | TSO 0    |                        |           |           |             |                  |
| SN:234                                             | HRS                                     | 9282.8    |          | TSO 0    |                        |           |           |             |                  |
|                                                    | AFL                                     | 7113      |          | TSO 0    |                        |           |           |             |                  |
| PROC. REF: AMM 21-51-02PROC. REF: AMM 21-51-02     |                                         |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 9669.1
AFL: 7372
As Of: 01-Apr-2025
02-Apr-2025 02:58 PM

| PN & SN                                            | Unit    | C/W                                                                                    | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------|---------|----------------------------------------------------------------------------------------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 21 - AIR CONDITIONING                          |         |                                                                                        |          |          |                        |           |           |             |          |
| 215101A                                            |         | AIR CONDITIONING COMPRESSOR DRIVE MOTOR - PERFORM BRUSH WEAR INSPECTION - IRN L2150054 |          |          |                        |           |           | Service     | ATA:21   |
| PN:MB86B-6                                         | MOS     | 31-Jul-23                                                                              |          |          |                        |           |           |             |          |
| SN:234                                             | HRS     | 9282.8                                                                                 |          |          |                        |           |           |             |          |
|                                                    | AFL     | 7113                                                                                   |          |          |                        |           |           |             |          |
|                                                    | ACH     | 2596.2                                                                                 | 600      |          | 3196.2                 |           | 543.1     |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |         |                                                                                        |          |          |                        |           |           |             |          |
| 215101B                                            |         | AIR CONDITIONING COMPRESSOR DRIVE MOTOR - OVERHAUL                                     |          |          |                        |           |           | Service     | ATA:21   |
| PN:MB86B-6                                         | MOS     | 31-Jul-23                                                                              |          |          |                        |           |           | OVERHAUL    |          |
| SN:234                                             | HRS     | 9282.8                                                                                 |          |          |                        |           |           |             |          |
|                                                    | AFL     | 7113                                                                                   |          |          |                        |           |           |             |          |
|                                                    | ACH     | 2596.2                                                                                 | 1200     |          | 3796.2                 |           | 1143.1    |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |         |                                                                                        |          |          |                        |           |           |             |          |
| 216001                                             |         | ENVIRONMENTAL CONTROL SYSTEM - INTEGRATED TEMPERATURE CONTROLLER                       |          |          |                        |           |           | Component   | ATA:21   |
| PN:1151830-3                                       | MOS/MSC | 04-Jan-21                                                                              | O/C      |          |                        |           |           |             |          |
| SN:1151830-00815                                   | HRS     | 8361.7                                                                                 |          |          |                        |           |           |             |          |
|                                                    | AFL     | 6425                                                                                   |          |          |                        |           |           |             |          |
| PROC. REF: AMM 21-60-10PROC. REF: AMM 21-60-10     |         |                                                                                        |          |          |                        |           |           |             |          |
| 216013                                             |         | COCKPIT TEMPERATURE CONTROL VALVE                                                      |          |          |                        |           |           | Component   | ATA:21   |
| PN:PN                                              | MOS/MSC | 09-Mar-01                                                                              | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0                                                                                      |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL     | 0                                                                                      |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 21-60-05PROC. REF: AMM 21-60-05     |         |                                                                                        |          |          |                        |           |           |             |          |
| 216014                                             |         | CABIN TEMPERATURE CONTROL VALVE                                                        |          |          |                        |           |           | Component   | ATA:21   |
| PN:PN                                              | MOS/MSC | 09-Mar-01                                                                              | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0                                                                                      |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL     | 0                                                                                      |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 21-60-04PROC. REF: AMM 21-60-04     |         |                                                                                        |          |          |                        |           |           |             |          |
| 216025                                             |         | COCKPIT TEMPERATURE CONTROL SELECTOR                                                   |          |          |                        |           |           | Component   | ATA:21   |
| PN:PN                                              | MOS/MSC | 09-Mar-01                                                                              | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0                                                                                      |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL     | 0                                                                                      |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 21-60-01PROC. REF: AMM 21-60-01     |         |                                                                                        |          |          |                        |           |           |             |          |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C/W   (M)-Manual Due   U-User Task   Ex-Excluded Task

Status Report

Model: LEARJET 45XR    Serial: 45-145    RegNo: N942FK    HRS: 9669.1    AFL: 7372    As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                            | Unit    | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------|---------|-----------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 21 - AIR CONDITIONING                          |         |           |          |          |                        |           |           |             |          |
| 216026 CABIN TEMPERATURE CONTROL SELECTOR          |         |           |          |          |                        |           |           | Component   | ATA:21   |
| PN:PN                                              | MOS/MSC | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL     | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 21-60-01PROC. REF: AMM 21-60-01     |         |           |          |          |                        |           |           |             |          |
|                                                    |         |           |          |          |                        |           |           |             |          |
| 216036 COCKPIT DUCT OVERHEAT THERMOSTAT            |         |           |          |          |                        |           |           | Component   | ATA:21   |
| PN:PN                                              | MOS/MSC | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL     | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 21-60-09PROC. REF: AMM 21-60-09     |         |           |          |          |                        |           |           |             |          |
|                                                    |         |           |          |          |                        |           |           |             |          |
| 216037 CABIN DUCT OVERHEAT THERMOSTAT              |         |           |          |          |                        |           |           | Component   | ATA:21   |
| PN:PN                                              | MOS/MSC | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL     | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 21-60-08PROC. REF: AMM 21-60-08     |         |           |          |          |                        |           |           |             |          |
|                                                    |         |           |          |          |                        |           |           |             |          |
| 216040 28VDC CABIN TEMPERATURE SENSOR/FAN ASSEMBLY |         |           |          |          |                        |           |           | Component   | ATA:21   |
| PN:PN                                              | MOS/MSC | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL     | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 21-60-03PROC. REF: AMM 21-60-03     |         |           |          |          |                        |           |           |             |          |
|                                                    |         |           |          |          |                        |           |           |             |          |
| 216047 <sup>U</sup> TEMP CONTROL, COCKPIT VALVE    |         |           |          |          |                        |           |           | Component   | ATA:21   |
| PN:PN                                              | MOS/MSC | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                    |         |           |          |          |                        |           |           |             |          |
|                                                    |         |           |          |          |                        |           |           |             |          |
| 216049 CABIN DUCT OVERTEMP LIMITER                 |         |           |          |          |                        |           |           | Component   | ATA:21   |
| PN:PN                                              | MOS/MSC | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL     | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 21-60-06PROC. REF: AMM 21-60-06     |         |           |          |          |                        |           |           |             |          |
|                                                    |         |           |          |          |                        |           |           |             |          |

?-Insufficient Information    S-Suppressed Requirement    \*-Estimated Due(New Requirement)    (EFF)-Effective C/W    (M)-Manual Due    U-User Task    Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                            | Unit                                                                                                                                                         | C / W     | Interval | TSX / Adj. | Next Due (ENG / APU) A / C | Max Limit | Remaining | Disposition   | Warranty |
|----------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|----------|------------|----------------------------|-----------|-----------|---------------|----------|
| ATA 21 - AIR CONDITIONING                          |                                                                                                                                                              |           |          |            |                            |           |           |               |          |
| 216071                                             | LOW LIMIT TEMPERATURE CONTROL VALVE                                                                                                                          |           |          |            |                            |           |           | Component     | ATA:21   |
| PN:PN                                              | MOS/MSC                                                                                                                                                      | 09-Mar-01 | O/C      | TSN 0      |                            |           |           |               |          |
| SN:UNKNOWN                                         | HRS                                                                                                                                                          | 0         |          | TSN 0      |                            |           |           |               |          |
|                                                    | AFL                                                                                                                                                          | 0         |          | TSN 0      |                            |           |           |               |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                                                                                                              |           |          |            |                            |           |           |               |          |
| 216074                                             | SERVO AIR PRESSURE REGULATING VALVE                                                                                                                          |           |          |            |                            |           |           | Component     | ATA:21   |
| PN:PN                                              | MOS/MSC                                                                                                                                                      | 09-Mar-01 | O/C      | TSN 0      |                            |           |           |               |          |
| SN:UNKNOWN                                         | HRS                                                                                                                                                          | 0         |          | TSN 0      |                            |           |           |               |          |
|                                                    | AFL                                                                                                                                                          | 0         |          | TSN 0      |                            |           |           |               |          |
| PROC. REF: AMM 36-15-01PROC. REF: AMM 36-15-01     |                                                                                                                                                              |           |          |            |                            |           |           |               |          |
| 216081                                             | COCKPIT DUCT TEMPERATURE SENSOR                                                                                                                              |           |          |            |                            |           |           | Component     | ATA:21   |
| PN:PN                                              | MOS/MSC                                                                                                                                                      | 09-Mar-01 | O/C      | TSN 0      |                            |           |           |               |          |
| SN:UNKNOWN                                         | HRS                                                                                                                                                          | 0         |          | TSN 0      |                            |           |           |               |          |
|                                                    | AFL                                                                                                                                                          | 0         |          | TSN 0      |                            |           |           |               |          |
| PROC. REF: AMM 21-60-07PROC. REF: AMM 21-60-07     |                                                                                                                                                              |           |          |            |                            |           |           |               |          |
| 216083                                             | COCKPIT TEMPERATURE SENSOR                                                                                                                                   |           |          |            |                            |           |           | Component     | ATA:21   |
| PN:PN                                              | MOS/MSC                                                                                                                                                      | 09-Mar-01 | O/C      | TSN 0      |                            |           |           |               |          |
| SN:UNKNOWN                                         | HRS                                                                                                                                                          | 0         |          | TSN 0      |                            |           |           |               |          |
|                                                    | AFL                                                                                                                                                          | 0         |          | TSN 0      |                            |           |           |               |          |
| PROC. REF: AMM 21-60-02PROC. REF: AMM 21-60-02     |                                                                                                                                                              |           |          |            |                            |           |           |               |          |
| 216084                                             | CABIN LOW LIMIT TEMPERATURE SENSOR                                                                                                                           |           |          |            |                            |           |           | Component     | ATA:21   |
| PN:PN                                              | MOS/MSC                                                                                                                                                      | 09-Mar-01 | O/C      | TSN 0      |                            |           |           |               |          |
| SN:UNKNOWN                                         | HRS                                                                                                                                                          | 0         |          | TSN 0      |                            |           |           |               |          |
|                                                    | AFL                                                                                                                                                          | 0         |          | TSN 0      |                            |           |           |               |          |
| PROC. REF: AMM 21-50-09PROC. REF: AMM 21-50-09     |                                                                                                                                                              |           |          |            |                            |           |           |               |          |
| 5-19-00-L2150054                                   | WEAR INSPECTION - AIR CONDITIONING COMPRESSOR DRIVE MOTOR BRUSHES - PERFORM WEAR INSPECTION (RETURN DRIVE MOTOR TO AUTHORIZED SERVICE FACILITY FOR OVERHAUL) |           |          |            |                            |           |           | Service       | ATA:21   |
|                                                    | MOS/MSC                                                                                                                                                      | 31-Jul-23 | N/A      |            |                            |           |           | NOT INSTALLED |          |
|                                                    | HRS                                                                                                                                                          | 9282.8    |          |            |                            |           |           |               |          |
|                                                    | AFL                                                                                                                                                          | 7113      |          |            |                            |           |           |               |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                                                                                                              |           |          |            |                            |           |           |               |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                            | Unit    | C/W                                                                                                                                                                                                          | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty |
|----------------------------------------------------|---------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|----------|------------------------|-----------|-----------|---------------|----------|
| ATA 21 - AIR CONDITIONING                          |         |                                                                                                                                                                                                              |          |          |                        |           |           |               |          |
| 5-19-00-L2150055                                   |         | OVERHAUL - AIR CONDITIONING COMPRESSOR MOTOR - PERFORM OVERHAUL (RETURN DRIVE MOTOR TO AUTHORIZED SERVICE FACILITY FOR OVERHAUL)                                                                             |          |          |                        |           |           | Service       | ATA:21   |
|                                                    | MOS/MSC | 22-Jun-23                                                                                                                                                                                                    | -        |          |                        |           |           | NOT INSTALLED |          |
|                                                    | HRS     | 9258.5                                                                                                                                                                                                       |          |          |                        |           |           |               |          |
|                                                    | AFL     | 7100                                                                                                                                                                                                         |          |          |                        |           |           |               |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |         |                                                                                                                                                                                                              |          |          |                        |           |           |               |          |
| 5-19-00-Y2130065                                   |         | LEAK TEST CABIN PRESSURIZATION SYSTEM. (IRN # Y2130065).                                                                                                                                                     |          |          |                        |           |           | Service       | ATA:21   |
|                                                    | MOS     | 22-Jun-23                                                                                                                                                                                                    |          |          |                        |           |           |               |          |
|                                                    | HRS     | 9258.5                                                                                                                                                                                                       | 1200     |          | 10458.5                |           | 789.4     |               |          |
|                                                    | AFL     | 7100                                                                                                                                                                                                         |          |          |                        |           |           |               |          |
| PROC. REF: AMM 21-30-00PROC. REF: AMM 21-30-00     |         |                                                                                                                                                                                                              |          |          |                        |           |           |               |          |
| 5-19-01-Y2141002                                   |         | REPLACE WATER SEPARATOR COALESCER BAG. (ZONE/ACCESS 310HL, 310RR IRN # W2141002)                                                                                                                             |          |          |                        |           |           | Service       | ATA:21   |
|                                                    | MOS/MSC | 09-Mar-01                                                                                                                                                                                                    | O/C      |          |                        |           |           |               |          |
|                                                    | HRS     | 0                                                                                                                                                                                                            |          |          |                        |           |           |               |          |
|                                                    | AFL     | 0                                                                                                                                                                                                            |          |          |                        |           |           |               |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |         |                                                                                                                                                                                                              |          |          |                        |           |           |               |          |
| J2160007 <sup>S</sup>                              |         | TEMPERATURE CONTROL SYSTEM - INSPECT AND CLEAN CABIN AND COCKPIT TEMPERATURE CONTROL VALVE SERVO AIR FILTERS. (EFFECTIVE ON AIRCRAFT 45-005 THRU 45-232 POST SB 45-21-16, AND AIRCRAFT 45-233 THRU 45-2000.) |          |          |                        |           |           | Service       | ATA:21   |
|                                                    | MOS     | 02-Aug-24                                                                                                                                                                                                    | 24       |          |                        |           |           |               |          |
|                                                    | HRS     | 9525.7                                                                                                                                                                                                       | 600      |          |                        |           |           |               |          |
|                                                    | AFL     | 7276                                                                                                                                                                                                         |          |          |                        |           |           |               |          |
| PROC. REF: AMM 21-60-11PROC. REF: AMM 21-60-11     |         |                                                                                                                                                                                                              |          |          |                        |           |           |               | PKG:8    |
| O2130001 <sup>S</sup>                              |         | REPLACE OUTFLOW VALVE AIR FILTER - REMOVE AND REPLACE.                                                                                                                                                       |          |          |                        |           |           | Service       | ATA:21   |
|                                                    | MOS     | 25-Nov-19                                                                                                                                                                                                    | 96       |          |                        |           |           |               |          |
|                                                    | HRS     | 8177.7                                                                                                                                                                                                       | 2400     |          |                        |           |           |               |          |
|                                                    | AFL     | 6303                                                                                                                                                                                                         |          |          |                        |           |           |               |          |
| PROC. REF: AMM 21-30-04PROC. REF: AMM 21-30-04     |         |                                                                                                                                                                                                              |          |          |                        |           |           |               | PKG:19   |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN | Unit | C / W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|---------|------|-------|----------|----------|------------------------|-----------|-----------|-------------|----------|
|---------|------|-------|----------|----------|------------------------|-----------|-----------|-------------|----------|

ATA 21 - AIR CONDITIONING

|                                                |              |                                                           |     |  |  |  |  |         |        |
|------------------------------------------------|--------------|-----------------------------------------------------------|-----|--|--|--|--|---------|--------|
| Y2130003                                       | <sup>S</sup> | PRESSURIZATION CONTROL SYSTEM - PERFORM OPERATIONAL CHECK |     |  |  |  |  | Service | ATA:21 |
|                                                | MOS          | 02-Aug-24                                                 | 24  |  |  |  |  |         |        |
|                                                | HRS          | 9525.7                                                    | 600 |  |  |  |  |         |        |
|                                                | AFL          | 7276                                                      |     |  |  |  |  |         |        |
| PROC. REF: AMM 21-30-00PROC. REF: AMM 21-30-00 |              |                                                           |     |  |  |  |  |         |        |

PKG:7

|                                                |              |                                                                                                                                                                                                                                                             |     |  |  |  |  |         |        |
|------------------------------------------------|--------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|--|--|--|--|---------|--------|
| Y2141001                                       | <sup>S</sup> | WATER SEPARATOR COALESCER BAG - PERFORM VISUAL INSPECTION. CLEAN IF NECESSARY. (NOTE: THE SERVICING ACTIVITY MAY REQUIRE A MORE FREQUENT INTERVAL, DEPENDING ON ENVIRONMENTAL AND OPERATIONAL REQUIREMENTS, AND SHOULD BE ADJUSTED BY INDIVIDUAL OPERATORS) |     |  |  |  |  | Service | ATA:21 |
|                                                | MOS          | 02-Aug-24                                                                                                                                                                                                                                                   | 12  |  |  |  |  |         |        |
|                                                | HRS          | 9525.7                                                                                                                                                                                                                                                      | 300 |  |  |  |  |         |        |
|                                                | AFL          | 7276                                                                                                                                                                                                                                                        |     |  |  |  |  |         |        |
| PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00 |              |                                                                                                                                                                                                                                                             |     |  |  |  |  |         |        |

PKG:2

|                                                |              |                                                              |      |  |  |  |  |         |        |
|------------------------------------------------|--------------|--------------------------------------------------------------|------|--|--|--|--|---------|--------|
| Y2142000                                       | <sup>S</sup> | PERFORM BAGGAGE COMPARTMENT HEATING SYSTEM - FUNCTIONAL TEST |      |  |  |  |  | Service | ATA:21 |
|                                                | MOS          | 25-Nov-19                                                    | 96   |  |  |  |  |         |        |
|                                                | HRS          | 8177.7                                                       | 2400 |  |  |  |  |         |        |
|                                                | AFL          | 6303                                                         |      |  |  |  |  |         |        |
| PROC. REF: AMM 21-40-00PROC. REF: AMM 21-40-00 |              |                                                              |      |  |  |  |  |         |        |

PKG:20

ATA 22 - AUTO FLIGHT

|                                                    |         |                                                                           |     |  |  |  |  |         |        |
|----------------------------------------------------|---------|---------------------------------------------------------------------------|-----|--|--|--|--|---------|--------|
| 2210-RVSM                                          |         | FLIGHT CHECK AUTOMATIC ALTITUDE HOLD FUNCTIONAL. RVSM COMPLIANT AIRCRAFT. |     |  |  |  |  | Service | ATA:22 |
|                                                    | MOS/MSC | 09-Mar-01                                                                 | N/R |  |  |  |  |         |        |
|                                                    | HRS     | 0                                                                         |     |  |  |  |  |         |        |
|                                                    | AFL     | 0                                                                         |     |  |  |  |  |         |        |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |         |                                                                           |     |  |  |  |  |         |        |

|                                                |         |                                      |     |  |  |  |  |           |        |
|------------------------------------------------|---------|--------------------------------------|-----|--|--|--|--|-----------|--------|
| 221001                                         |         | AUTOPILOT FLIGHT GUIDANCE CONTROLLER |     |  |  |  |  | Component | ATA:22 |
| PN:7021170-901                                 | MOS/MSC | 25-Jan-19                            | O/C |  |  |  |  |           |        |
| SN:05111601                                    | HRS     | 8026.4                               |     |  |  |  |  |           |        |
|                                                | AFL     | 6168                                 |     |  |  |  |  |           |        |
| PROC. REF: AMM 22-10-01PROC. REF: AMM 22-10-01 |         |                                      |     |  |  |  |  |           |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 45XR    Serial: 45-145    RegNo: N942FK    HRS: 9669.1    AFL: 7372    As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                        | Unit    | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|------------------------------------------------|---------|-----------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 22 - AUTO FLIGHT                           |         |           |          |          |                        |           |           |             |          |
| 221041      AUTOPILOT ROLL SERVO               |         |           |          |          |                        |           |           | Component   | ATA:22   |
| PN:PN 4006719-948                              | MOS/MSC | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL     | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 22-10-04PROC. REF: AMM 22-10-04 |         |           |          |          |                        |           |           |             |          |
|                                                |         |           |          |          |                        |           |           |             |          |
| 221045      AUTOPILOT ROLL SERVO BRACKET       |         |           |          |          |                        |           |           | Component   | ATA:22   |
| PN:PN 4005842                                  | MOS/MSC | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL     | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 22-10-05PROC. REF: AMM 22-10-05 |         |           |          |          |                        |           |           |             |          |
|                                                |         |           |          |          |                        |           |           |             |          |
| 221051      AUTOPILOT PITCH SERVO              |         |           |          |          |                        |           |           | Component   | ATA:22   |
| PN:PN 4006719-908                              | MOS/MSC | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL     | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 22-10-02PROC. REF: AMM 22-10-02 |         |           |          |          |                        |           |           |             |          |
|                                                |         |           |          |          |                        |           |           |             |          |
| 221055      AUTOPILOT PITCH SERVO BRACKET      |         |           |          |          |                        |           |           | Component   | ATA:22   |
| PN:PN 4005842                                  | MOS/MSC | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL     | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 22-10-03PROC. REF: AMM 22-10-03 |         |           |          |          |                        |           |           |             |          |
|                                                |         |           |          |          |                        |           |           |             |          |
| 221061      AUTOPILOT YAW SERVO                |         |           |          |          |                        |           |           | Component   | ATA:22   |
| PN:PN 7012919-903                              | MOS/MSC | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL     | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 22-10-06PROC. REF: AMM 22-10-06 |         |           |          |          |                        |           |           |             |          |
|                                                |         |           |          |          |                        |           |           |             |          |
| 221065      AUTOPILOT YAW SERVO BRACKET        |         |           |          |          |                        |           |           | Component   | ATA:22   |
| PN:PN                                          | MOS/MSC | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL     | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 22-10-07PROC. REF: AMM 22-10-07 |         |           |          |          |                        |           |           |             |          |

?-Insufficient Information    S-Suppressed Requirement    \*-Estimated Due(New Requirement)    (EFF)-Effective C/W    (M)-Manual Due    U-User Task    Ex-Excluded Task

# Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9669.1
 AFL: 7372
 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN | Unit | C / W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|---------|------|-------|----------|----------|------------------------|-----------|-----------|-------------|----------|
|---------|------|-------|----------|----------|------------------------|-----------|-----------|-------------|----------|

## ATA 22 - AUTO FLIGHT

|                                                |                    |           |     |       |  |  |  |           |        |
|------------------------------------------------|--------------------|-----------|-----|-------|--|--|--|-----------|--------|
| 225001                                         | YAW INTERFACE UNIT |           |     |       |  |  |  | Component | ATA:22 |
| PN:PN                                          | MOS/MSC            | 09-Mar-01 | O/C | TSN 0 |  |  |  |           |        |
| SN:UNKNOWN                                     | HRS                | 0         |     | TSN 0 |  |  |  |           |        |
|                                                | AFL                | 0         |     | TSN 0 |  |  |  |           |        |
| PROC. REF: AMM 22-50-01PROC. REF: AMM 22-50-01 |                    |           |     |       |  |  |  |           |        |

|                                                |                                            |           |     |       |  |  |  |           |        |
|------------------------------------------------|--------------------------------------------|-----------|-----|-------|--|--|--|-----------|--------|
| 225031                                         | PILOT RUDDER BOOST SYSTEM YAW FORCE SENSOR |           |     |       |  |  |  | Component | ATA:22 |
| PN:PN                                          | MOS/MSC                                    | 09-Mar-01 | O/C | TSN 0 |  |  |  |           |        |
| SN:UNKNOWN                                     | HRS                                        | 0         |     | TSN 0 |  |  |  |           |        |
|                                                | AFL                                        | 0         |     | TSN 0 |  |  |  |           |        |
| PROC. REF: AMM 22-50-02PROC. REF: AMM 22-50-02 |                                            |           |     |       |  |  |  |           |        |

|                                                |                                              |           |     |       |  |  |  |           |        |
|------------------------------------------------|----------------------------------------------|-----------|-----|-------|--|--|--|-----------|--------|
| 225032                                         | COPILOT RUDDER BOOST SYSTEM YAW FORCE SENSOR |           |     |       |  |  |  | Component | ATA:22 |
| PN:PN                                          | MOS/MSC                                      | 09-Mar-01 | O/C | TSN 0 |  |  |  |           |        |
| SN:UNKNOWN                                     | HRS                                          | 0         |     | TSN 0 |  |  |  |           |        |
|                                                | AFL                                          | 0         |     | TSN 0 |  |  |  |           |        |
| PROC. REF: AMM 22-50-02PROC. REF: AMM 22-50-02 |                                              |           |     |       |  |  |  |           |        |

|                                                |                                                              |           |     |  |  |  |  |               |        |
|------------------------------------------------|--------------------------------------------------------------|-----------|-----|--|--|--|--|---------------|--------|
| A2210033 <sup>S</sup>                          | ** AUTOPILOT SYSTEM - PERFORM AUTOPILOT DISCONNECT TONE TEST |           |     |  |  |  |  | Service       | ATA:22 |
|                                                | MOS                                                          | 02-Aug-24 | 24  |  |  |  |  | AIRWORTHINESS |        |
|                                                | HRS                                                          | 9525.7    | 600 |  |  |  |  |               |        |
|                                                | AFL                                                          | 7276      |     |  |  |  |  |               |        |
| PROC. REF: AMM 22-10-00PROC. REF: AMM 22-10-00 |                                                              |           |     |  |  |  |  |               |        |
|                                                |                                                              |           |     |  |  |  |  |               | PKG:7  |

## ATA 23 - COMMUNICATIONS

|                                                    |                   |           |     |       |  |  |  |           |        |
|----------------------------------------------------|-------------------|-----------|-----|-------|--|--|--|-----------|--------|
| 230001                                             | UNILINK PROCESSOR |           |     |       |  |  |  | Component | ATA:23 |
| PN:PN                                              | MOS/MSC           | 09-Mar-01 | O/C | TSN 0 |  |  |  |           |        |
| SN:UNKNOWN                                         | HRS               | 0         |     | TSN 0 |  |  |  |           |        |
|                                                    | AFL               | 0         |     | TSN 0 |  |  |  |           |        |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                   |           |     |       |  |  |  |           |        |

|                                                    |                      |           |     |       |  |  |  |           |        |
|----------------------------------------------------|----------------------|-----------|-----|-------|--|--|--|-----------|--------|
| 230002                                             | CONFIGURATION MODULE |           |     |       |  |  |  | Component | ATA:23 |
| PN:PN                                              | MOS/MSC              | 09-Mar-01 | O/C | TSN 0 |  |  |  |           |        |
| SN:UNKNOWN                                         | HRS                  | 0         |     | TSN 0 |  |  |  |           |        |
|                                                    | AFL                  | 0         |     | TSN 0 |  |  |  |           |        |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                      |           |     |       |  |  |  |           |        |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C/W   (M)-Manual Due   U-User Task   Ex-Excluded Task

# Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9669.1
 AFL: 7372
 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                                                        | Unit                                      | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|--------------------------------------------------------------------------------|-------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 23 - COMMUNICATIONS                                                        |                                           |           |          |          |                        |           |           |             |          |
| 231011                                                                         | NO. 1 POWER AMPLIFIER/HF ANTENNA COUPLER  |           |          |          |                        |           |           | Component   | ATA:23   |
| PN:064-1017-01                                                                 | MOS/MSC                                   | 12-Feb-08 | O/C      |          |                        |           |           |             |          |
| SN:17280                                                                       | HRS                                       | 5965.9    |          |          |                        |           |           |             |          |
|                                                                                | AFL                                       | 4561      |          |          |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                             |                                           |           |          |          |                        |           |           |             |          |
| 231012                                                                         | NO. 2 POWER AMPLIFIER/HF ANTENNA COUPLER  |           |          |          |                        |           |           | Component   | ATA:23   |
| PN:PN                                                                          | MOS/MSC                                   | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                                                     | HRS                                       | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                                                | AFL                                       | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                             |                                           |           |          |          |                        |           |           |             |          |
| 231021                                                                         | NO. 1 VHF COMMUNICATIONS TRANSCEIVER UNIT |           |          |          |                        |           |           | Component   | ATA:23   |
| PN:7510733-616                                                                 | MOS/MSC                                   | 11-May-18 | O/C      |          |                        |           |           |             |          |
| SN:98093272                                                                    | HRS                                       | 7850.8    |          |          |                        |           |           |             |          |
|                                                                                | AFL                                       | 6024      |          |          |                        |           |           |             |          |
| PROC. REF: AMM 23-11-01PROC. REF: AMM 23-11-01                                 |                                           |           |          |          |                        |           |           |             |          |
| 231021A                                                                        | TEST/INSPECT NO. 1 ATC TRANSPONDER        |           |          |          |                        |           |           | Service     | ATA:23   |
| PN:7510733-616                                                                 | MOS                                       | 10-Aug-24 | 24       |          | 10-Aug-26              |           | 495 d     |             |          |
| SN:98093272                                                                    | HRS                                       |           |          |          |                        |           |           |             |          |
|                                                                                | AFL                                       |           |          |          |                        |           |           |             |          |
| Calibration Date: : 10-Aug-24                                                  |                                           |           |          |          |                        |           |           |             |          |
| PROC. REF: AMM 23-11-00, FAR FAR 91.413PROC. REF: AMM 23-11-00, FAR FAR 91.413 |                                           |           |          |          |                        |           |           |             |          |
| 231022                                                                         | NO. 2 VHF COMMUNICATIONS TRANSCEIVER UNIT |           |          |          |                        |           |           | Component   | ATA:23   |
| PN:7510733-616                                                                 | MOS/MSC                                   | 13-Apr-17 | O/C      |          |                        |           |           |             |          |
| SN:99054063                                                                    | HRS                                       | 7744.3    |          |          |                        |           |           |             |          |
|                                                                                | AFL                                       | 5922      |          |          |                        |           |           |             |          |
| PROC. REF: AMM 23-11-01, FAR FAR 91.413PROC. REF: AMM 23-11-01, FAR FAR 91.413 |                                           |           |          |          |                        |           |           |             |          |
| 231022A                                                                        | TEST/INSPECT NO. 2 ATC TRANSPONDER        |           |          |          |                        |           |           | Service     | ATA:23   |
| PN:7510733-616                                                                 | MOS                                       | 10-Aug-24 | 24       |          | 10-Aug-26              |           | 495 d     |             |          |
| SN:99054063                                                                    | HRS                                       |           |          |          |                        |           |           |             |          |
|                                                                                | AFL                                       |           |          |          |                        |           |           |             |          |
| Calibration Date: : 10-Aug-24                                                  |                                           |           |          |          |                        |           |           |             |          |
| PROC. REF: AMM 23-11-00, FAR FAR 91.413PROC. REF: AMM 23-11-00, FAR FAR 91.413 |                                           |           |          |          |                        |           |           |             |          |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C/W   (M)-Manual Due   U-User Task   Ex-Excluded Task

Status Report

Model: LEARJET 45XR    Serial: 45-145    RegNo: N942FK    HRS: 9669.1    AFL: 7372    As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                            | Unit                                                 | C / W     | Interval | TSX / Adj. | Next Due (ENG / APU) A / C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------|------------------------------------------------------|-----------|----------|------------|----------------------------|-----------|-----------|-------------|----------|
| ATA 23 - COMMUNICATIONS                            |                                                      |           |          |            |                            |           |           |             |          |
| 231030                                             | NO. 1 HF SELECTIVE CALLING (SELCAL) RECEIVER/EXCITER |           |          |            |                            |           |           | Component   | ATA:23   |
| PN:PN                                              | MOS/MSC                                              | 09-Mar-01 | O/C      | TSN 0      |                            |           |           |             |          |
| SN:UNKNOWN                                         | HRS                                                  | 0         |          | TSN 0      |                            |           |           |             |          |
|                                                    | AFL                                                  | 0         |          | TSN 0      |                            |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                      |           |          |            |                            |           |           |             |          |
| 231031                                             | NO. 2 HF SELECTIVE CALLING (SELCAL) RECEIVER/EXCITER |           |          |            |                            |           |           | Component   | ATA:23   |
| PN:PN                                              | MOS/MSC                                              | 09-Mar-01 | O/C      | TSN 0      |                            |           |           |             |          |
| SN:UNKNOWN                                         | HRS                                                  | 0         |          | TSN 0      |                            |           |           |             |          |
|                                                    | AFL                                                  | 0         |          | TSN 0      |                            |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                      |           |          |            |                            |           |           |             |          |
| 231032                                             | HF SELECTIVE CALLING (SELCAL) ANTENNA                |           |          |            |                            |           |           | Component   | ATA:23   |
| PN:PN                                              | MOS/MSC                                              | 09-Mar-01 | O/C      | TSN 0      |                            |           |           |             |          |
| SN:UNKNOWN                                         | HRS                                                  | 0         |          | TSN 0      |                            |           |           |             |          |
|                                                    | AFL                                                  | 0         |          | TSN 0      |                            |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                      |           |          |            |                            |           |           |             |          |
| 231033                                             | UPPER VHF ANTENNA                                    |           |          |            |                            |           |           | Component   | ATA:23   |
| PN:PN                                              | MOS/MSC                                              | 09-Mar-01 | O/C      | TSN 0      |                            |           |           |             |          |
| SN:UNKNOWN                                         | HRS                                                  | 0         |          | TSN 0      |                            |           |           |             |          |
|                                                    | AFL                                                  | 0         |          | TSN 0      |                            |           |           |             |          |
| PROC. REF: AMM 23-11-02PROC. REF: AMM 23-11-02     |                                                      |           |          |            |                            |           |           |             |          |
| 231034                                             | LOWER VHF ANTENNA                                    |           |          |            |                            |           |           | Component   | ATA:23   |
| PN:DMC60-17-1                                      | MOS/MSC                                              | 16-Jul-19 | O/C      | TSN 0      |                            |           |           |             |          |
| SN:18936                                           | HRS                                                  | 8109      |          | TSN 0      |                            |           |           |             |          |
|                                                    | AFL                                                  | 6239      |          | TSN 0      |                            |           |           |             |          |
| PROC. REF: AMM 23-11-02PROC. REF: AMM 23-11-02     |                                                      |           |          |            |                            |           |           |             |          |
| 231045                                             | NO. 1 HF CONTROL (MODEL KCU-951)                     |           |          |            |                            |           |           | Component   | ATA:23   |
| PN:064-1016-03                                     | MOS/MSC                                              | 25-Feb-08 | O/C      |            |                            |           |           |             |          |
| SN:11903                                           | HRS                                                  | 5974.6    |          |            |                            |           |           |             |          |
|                                                    | AFL                                                  | 4566      |          |            |                            |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                      |           |          |            |                            |           |           |             |          |

?-Insufficient Information    S-Suppressed Requirement    \*-Estimated Due(New Requirement)    (EFF)-Effective C / W    (M)-Manual Due    U-User Task    Ex-Excluded Task

# Status Report

Model: LEARJET 45XR  
 Serial: 45-145  
 RegNo: N942FK  
 HRS: 9669.1  
 AFL: 7372  
 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                            | Unit                             | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty            |
|----------------------------------------------------|----------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|---------------------|
| ATA 23 - COMMUNICATIONS                            |                                  |           |          |          |                        |           |           |             |                     |
| 231046                                             | NO. 2 HF CONTROL (MODEL KCU-951) |           |          |          |                        |           |           |             | Component    ATA:23 |
| PN:PN                                              | MOS/MSC                          | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                         | HRS                              | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                    | AFL                              | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                  |           |          |          |                        |           |           |             |                     |
| 231051                                             | NO. 1 HF BRIDGING AMPLIFIER      |           |          |          |                        |           |           |             | Component    ATA:23 |
| PN:PN                                              | MOS/MSC                          | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                         | HRS                              | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                    | AFL                              | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                  |           |          |          |                        |           |           |             |                     |
| 231052                                             | NO. 2 HF BRIDGING AMPLIFIER      |           |          |          |                        |           |           |             | Component    ATA:23 |
| PN:PN                                              | MOS/MSC                          | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                         | HRS                              | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                    | AFL                              | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                  |           |          |          |                        |           |           |             |                     |
| 231090                                             | PILOT HEADSET                    |           |          |          |                        |           |           |             | Component    ATA:23 |
| PN:PN                                              | MOS/MSC                          | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                         | HRS                              | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                    | AFL                              | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                  |           |          |          |                        |           |           |             |                     |
| 231091                                             | COPILOT HEADSET                  |           |          |          |                        |           |           |             | Component    ATA:23 |
| PN:PN                                              | MOS/MSC                          | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                         | HRS                              | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                    | AFL                              | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                  |           |          |          |                        |           |           |             |                     |
| 231300                                             | MAGNASTAR PHONE TRANSCEIVER      |           |          |          |                        |           |           |             | Component    ATA:23 |
| PN:PN                                              | MOS/MSC                          | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                         | HRS                              | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                    | AFL                              | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                  |           |          |          |                        |           |           |             |                     |

?-Insufficient Information    S-Suppressed Requirement    \*-Estimated Due(New Requirement)    (EFF)-Effective C/W    (M)-Manual Due    U-User Task    Ex-Excluded Task

Status Report

Model: LEARJET 45XR    Serial: 45-145    RegNo: N942FK    HRS: 9669.1    AFL: 7372    As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                            | Unit    | C / W                                 | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------|---------|---------------------------------------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 23 - COMMUNICATIONS                            |         |                                       |          |          |                        |           |           |             |          |
| 231301 <sup>U</sup>                                |         | ANTENNA                               |          |          |                        |           |           | Component   | ATA:23   |
| PN:PN                                              | MOS/MSC | 09-Mar-01                             | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0                                     |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL     | 0                                     |          | TSN 0    |                        |           |           |             |          |
|                                                    |         |                                       |          |          |                        |           |           |             |          |
| 231305                                             |         | MAGNASTAR ANTENNA                     |          |          |                        |           |           | Component   | ATA:23   |
| PN:PN                                              | MOS/MSC | 09-Mar-01                             | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0                                     |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL     | 0                                     |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |         |                                       |          |          |                        |           |           |             |          |
|                                                    |         |                                       |          |          |                        |           |           |             |          |
| 231307                                             |         | COCKPIT PHONE                         |          |          |                        |           |           | Component   | ATA:23   |
| PN:PN                                              | MOS/MSC | 09-Mar-01                             | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0                                     |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL     | 0                                     |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |         |                                       |          |          |                        |           |           |             |          |
|                                                    |         |                                       |          |          |                        |           |           |             |          |
| 231308                                             |         | CABIN PHONE                           |          |          |                        |           |           | Component   | ATA:23   |
| PN:PN                                              | MOS/MSC | 09-Mar-01                             | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0                                     |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL     | 0                                     |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |         |                                       |          |          |                        |           |           |             |          |
|                                                    |         |                                       |          |          |                        |           |           |             |          |
| 231310                                             |         | ARTU TRAY                             |          |          |                        |           |           | Component   | ATA:23   |
| PN:PN                                              | MOS/MSC | 09-Mar-01                             | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0                                     |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL     | 0                                     |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |         |                                       |          |          |                        |           |           |             |          |
|                                                    |         |                                       |          |          |                        |           |           |             |          |
| 231313                                             |         | NO. 1 CABIN DISTRIBUTION BUS REPEATER |          |          |                        |           |           | Component   | ATA:23   |
| PN:PN                                              | MOS/MSC | 09-Mar-01                             | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0                                     |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL     | 0                                     |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |         |                                       |          |          |                        |           |           |             |          |

?-Insufficient Information    S-Suppressed Requirement    \*-Estimated Due(New Requirement)    (EFF)-Effective C/W    (M)-Manual Due    U-User Task    Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                            | Unit                                  | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------|---------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 23 - COMMUNICATIONS                            |                                       |           |          |          |                        |           |           |             |                  |
| 231314                                             | NO. 2 CABIN DISTRIBUTION BUS REPEATER |           |          |          |                        |           |           |             | Component ATA:23 |
| PN:PN                                              | MOS/MSC                               | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                   | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                   | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                       |           |          |          |                        |           |           |             |                  |
| 231315                                             | CALL ALERTER SWITCH (CAS)             |           |          |          |                        |           |           |             | Component ATA:23 |
| PN:PN                                              | MOS/MSC                               | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                   | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                   | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                       |           |          |          |                        |           |           |             |                  |
| 231320                                             | NO. 1 CABIN IRIDIUM SATCOM HANDSET    |           |          |          |                        |           |           |             | Component ATA:23 |
| PN:P12248-003                                      | MOS/MSC                               | 12-Feb-08 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                   | 5965.9    |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                   | 4561      |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                       |           |          |          |                        |           |           |             |                  |
| 231321                                             | CABIN IRIDIUM SATCOM PHONE CRADLE     |           |          |          |                        |           |           |             | Component ATA:23 |
| PN:PN                                              | MOS/MSC                               | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                   | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                   | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                       |           |          |          |                        |           |           |             |                  |
| 231322                                             | NO. 2 CABIN IRIDIUM SATCOM HANDSET    |           |          |          |                        |           |           |             | Component ATA:23 |
| PN:P12192-002                                      | MOS/MSC                               | 12-Feb-08 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                   | 5965.9    |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                   | 4561      |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                       |           |          |          |                        |           |           |             |                  |
| 231323                                             | IRIDIUM SATCOM TRANSCEIVER            |           |          |          |                        |           |           |             | Component ATA:23 |
| PN:P12023                                          | MOS/MSC                               | 12-Feb-08 | O/C      |          |                        |           |           |             |                  |
| SN:1202310876                                      | HRS                                   | 5965.9    |          |          |                        |           |           |             |                  |
|                                                    | AFL                                   | 4561      |          |          |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                       |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                            | Unit                                | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------|-------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 23 - COMMUNICATIONS                            |                                     |           |          |          |                        |           |           |             |                  |
| 231325                                             | IRIDIUM SATCOM SONALERT             |           |          |          |                        |           |           |             | Component ATA:23 |
| PN:PN                                              | MOS/MSC                             | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                 | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                 | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                     |           |          |          |                        |           |           |             |                  |
| 231327                                             | COCKPIT IRIDIUM SATCOM PHONE CRADLE |           |          |          |                        |           |           |             | Component ATA:23 |
| PN:PN                                              | MOS/MSC                             | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                 | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                 | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                     |           |          |          |                        |           |           |             |                  |
| 231328                                             | COCKPIT IRIDIUM SATCOM HANDSET      |           |          |          |                        |           |           |             | Component ATA:23 |
| PN:P12192-002                                      | MOS/MSC                             | 12-Feb-08 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                 | 5965.9    |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                 | 4561      |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                     |           |          |          |                        |           |           |             |                  |
| 231330                                             | FORWARD IRIDIUM SATCOM ANTENNA      |           |          |          |                        |           |           |             | Component ATA:23 |
| PN:S67-1575-165                                    | MOS/MSC                             | 12-Feb-08 | O/C      |          |                        |           |           |             |                  |
| SN:449-2303                                        | HRS                                 | 5965.9    |          |          |                        |           |           |             |                  |
|                                                    | AFL                                 | 4561      |          |          |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                     |           |          |          |                        |           |           |             |                  |
| 231335                                             | COCKPIT IRIDIUM SATCOM BASE UNIT    |           |          |          |                        |           |           |             | Component ATA:23 |
| PN:PN                                              | MOS/MSC                             | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                 | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                 | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                     |           |          |          |                        |           |           |             |                  |
| 233001                                             | FORWARD CABIN VIDEO MONITOR         |           |          |          |                        |           |           |             | Component ATA:23 |
| PN:AL-LCD104-04-1                                  | MOS/MSC                             | 06-Aug-06 | O/C      |          |                        |           |           |             |                  |
| SN:120000638                                       | HRS                                 | 4725.85   |          |          |                        |           |           |             |                  |
|                                                    | AFL                                 | 3628      |          |          |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                     |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                            | Unit                            | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------|---------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 23 - COMMUNICATIONS                            |                                 |           |          |          |                        |           |           |             |                  |
| 233002                                             | AFT CABIN VIDEO MONITOR         |           |          |          |                        |           |           |             | Component ATA:23 |
| PN:PN                                              | MOS/MSC                         | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                             | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                             | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                 |           |          |          |                        |           |           |             |                  |
| 233003                                             | AUDIO DISTRIBUTION MODULE       |           |          |          |                        |           |           |             | Component ATA:23 |
| PN:PN                                              | MOS/MSC                         | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                             | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                             | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                 |           |          |          |                        |           |           |             |                  |
| 233005                                             | PUBLIC ADDRESS SYSTEM AMPLIFER  |           |          |          |                        |           |           |             | Component ATA:23 |
| PN:PN                                              | MOS/MSC                         | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                             | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                             | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 23-30-02PROC. REF: AMM 23-30-02     |                                 |           |          |          |                        |           |           |             |                  |
| 233010                                             | INFRARED REMOTE RECEIVER MODULE |           |          |          |                        |           |           |             | Component ATA:23 |
| PN:PN                                              | MOS/MSC                         | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                             | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                             | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                 |           |          |          |                        |           |           |             |                  |
| 233015                                             | AUDIO/VIDEO CONTROLLER          |           |          |          |                        |           |           |             | Component ATA:23 |
| PN:PN                                              | MOS/MSC                         | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                             | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                             | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                 |           |          |          |                        |           |           |             |                  |
| 233053                                             | DVD PLAYER                      |           |          |          |                        |           |           |             | Component ATA:23 |
| PN:PN                                              | MOS/MSC                         | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                             | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                             | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                 |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR    Serial: 45-145    RegNo: N942FK    HRS: 9669.1    AFL: 7372    As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                            | Unit    | C / W                       | Interval | TSX / Adj. | Next Due (ENG / APU) A / C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------|---------|-----------------------------|----------|------------|----------------------------|-----------|-----------|-------------|----------|
| ATA 23 - COMMUNICATIONS                            |         |                             |          |            |                            |           |           |             |          |
| 233054                                             |         | CD PLAYER CHANGER           |          |            |                            |           |           | Component   | ATA:23   |
| PN:MCD-102-RU-3                                    | MOS/MSC | 21-Jun-05                   | O/C      |            |                            |           |           |             |          |
| SN:060101192                                       | HRS     | 3694.5                      |          |            |                            |           |           |             |          |
|                                                    | AFL     | 2785                        |          |            |                            |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |         |                             |          |            |                            |           |           |             |          |
| 233055                                             |         | CD PLAYER CONTROL UNIT      |          |            |                            |           |           | Component   | ATA:23   |
| PN:MCD-102-CH-1                                    | MOS/MSC | 22-May-06                   | O/C      |            |                            |           |           |             |          |
| SN:100000353                                       | HRS     | 4507.7                      |          |            |                            |           |           |             |          |
|                                                    | AFL     | 3441                        |          |            |                            |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |         |                             |          |            |                            |           |           |             |          |
| 233056                                             |         | CASSETTE TAPE PLAYER        |          |            |                            |           |           | Component   | ATA:23   |
| PN:PN                                              | MOS/MSC | 09-Mar-01                   | O/C      | TSN 0      |                            |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0                           |          | TSN 0      |                            |           |           |             |          |
|                                                    | AFL     | 0                           |          | TSN 0      |                            |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |         |                             |          |            |                            |           |           |             |          |
| 233101                                             |         | LEFT FORWARD CABIN SPEAKER  |          |            |                            |           |           | Component   | ATA:23   |
| PN:PN                                              | MOS/MSC | 09-Mar-01                   | O/C      | TSN 0      |                            |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0                           |          | TSN 0      |                            |           |           |             |          |
|                                                    | AFL     | 0                           |          | TSN 0      |                            |           |           |             |          |
| PROC. REF: AMM 23-30-01PROC. REF: AMM 23-30-01     |         |                             |          |            |                            |           |           |             |          |
| 233102                                             |         | RIGHT FORWARD CABIN SPEAKER |          |            |                            |           |           | Component   | ATA:23   |
| PN:PN                                              | MOS/MSC | 09-Mar-01                   | O/C      | TSN 0      |                            |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0                           |          | TSN 0      |                            |           |           |             |          |
|                                                    | AFL     | 0                           |          | TSN 0      |                            |           |           |             |          |
| PROC. REF: AMM 23-30-01PROC. REF: AMM 23-30-01     |         |                             |          |            |                            |           |           |             |          |
| 233103                                             |         | LEFT AFT CABIN SPEAKER      |          |            |                            |           |           | Component   | ATA:23   |
| PN:PN                                              | MOS/MSC | 09-Mar-01                   | O/C      | TSN 0      |                            |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0                           |          | TSN 0      |                            |           |           |             |          |
|                                                    | AFL     | 0                           |          | TSN 0      |                            |           |           |             |          |
| PROC. REF: AMM 23-30-01PROC. REF: AMM 23-30-01     |         |                             |          |            |                            |           |           |             |          |

?-Insufficient Information    S-Suppressed Requirement    \*-Estimated Due(New Requirement)    (EFF)-Effective C / W    (M)-Manual Due    U-User Task    Ex-Excluded Task

# Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9669.1
 AFL: 7372
 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                            | Unit                         | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------|------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 23 - COMMUNICATIONS                            |                              |           |          |          |                        |           |           |             |                  |
| 233104                                             | RIGHT AFT CABIN SPEAKER      |           |          |          |                        |           |           |             | Component ATA:23 |
| PN:PN                                              | MOS/MSC                      | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                          | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                          | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 23-30-01PROC. REF: AMM 23-30-01     |                              |           |          |          |                        |           |           |             |                  |
| 233105                                             | SUBWOOFER SPEAKER            |           |          |          |                        |           |           |             | Component ATA:23 |
| PN:PN                                              | MOS/MSC                      | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                          | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                          | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                              |           |          |          |                        |           |           |             |                  |
| 233201                                             | PASSENGER INTERFACE UNIT     |           |          |          |                        |           |           |             | Component ATA:23 |
| PN:PN                                              | MOS/MSC                      | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                          | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                          | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                              |           |          |          |                        |           |           |             |                  |
| 234000                                             | INTERPHONE JACK BOX ASSEMBLY |           |          |          |                        |           |           |             | Component ATA:23 |
| PN:PN                                              | MOS/MSC                      | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                          | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                          | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                              |           |          |          |                        |           |           |             |                  |
| 235001                                             | NO. 1 AUDIO CONTROL UNIT     |           |          |          |                        |           |           |             | Component ATA:23 |
| PN:PN                                              | MOS/MSC                      | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                          | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                          | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 23-50-01PROC. REF: AMM 23-50-01     |                              |           |          |          |                        |           |           |             |                  |
| 235002                                             | NO. 2 AUDIO CONTROL UNIT     |           |          |          |                        |           |           |             | Component ATA:23 |
| PN:7511001-937                                     | MOS/MSC                      | 12-Sep-22 | O/C      |          |                        |           |           |             |                  |
| SN:04049325                                        | HRS                          | 9101.8    |          |          |                        |           |           |             |                  |
|                                                    | AFL                          | 6994      |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 23-50-01PROC. REF: AMM 23-50-01     |                              |           |          |          |                        |           |           |             |                  |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C/W   (M)-Manual Due   U-User Task   Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                            | Unit    | C / W                      | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------|---------|----------------------------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 23 - COMMUNICATIONS                            |         |                            |          |          |                        |           |           |             |          |
| 235013                                             |         | LEFT COCKPIT SPEAKER       |          |          |                        |           |           | Component   | ATA:23   |
| PN:PN                                              | MOS/MSC | 09-Mar-01                  | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0                          |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL     | 0                          |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 23-50-03PROC. REF: AMM 23-50-03     |         |                            |          |          |                        |           |           |             |          |
| 235014                                             |         | RIGHT COCKPIT SPEAKER      |          |          |                        |           |           | Component   | ATA:23   |
| PN:PN                                              | MOS/MSC | 09-Mar-01                  | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0                          |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL     | 0                          |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 23-50-03PROC. REF: AMM 23-50-03     |         |                            |          |          |                        |           |           |             |          |
| 236001 <sup>U</sup>                                |         | STATIC INVERTER            |          |          |                        |           |           | Component   | ATA:23   |
| PN:PN                                              | MOS/MSC | 09-Mar-01                  | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0                          |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL     | 0                          |          | TSN 0    |                        |           |           |             |          |
|                                                    |         |                            |          |          |                        |           |           |             |          |
| 236005                                             |         | XM RADIO WEATHER RECEIVER  |          |          |                        |           |           | Component   | ATA:23   |
| PN:PN                                              | MOS/MSC | 09-Mar-01                  | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0                          |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL     | 0                          |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |         |                            |          |          |                        |           |           |             |          |
| 236010                                             |         | XM RADIO WEATHER DATA PORT |          |          |                        |           |           | Component   | ATA:23   |
| PN:PN                                              | MOS/MSC | 09-Mar-01                  | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0                          |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL     | 0                          |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |         |                            |          |          |                        |           |           |             |          |
| 236015                                             |         | XM RADIO ANTENNA           |          |          |                        |           |           | Component   | ATA:23   |
| PN:PN                                              | MOS/MSC | 09-Mar-01                  | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0                          |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL     | 0                          |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |         |                            |          |          |                        |           |           |             |          |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C/W   (M)-Manual Due   U-User Task   Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                        | Unit                                                        | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|------------------------------------------------|-------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 23 - COMMUNICATIONS                        |                                                             |           |          |          |                        |           |           |             |                  |
| 236096                                         | NO. 1 NAVIGATION STRAP BOARD                                |           |          |          |                        |           |           |             | Component ATA:23 |
| PN:PN                                          | MOS/MSC                                                     | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                                         | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                                         | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 34-51-05PROC. REF: AMM 34-51-05 |                                                             |           |          |          |                        |           |           |             |                  |
| 236097                                         | NO. 2 NAVIGATION STRAP BOARD                                |           |          |          |                        |           |           |             | Component ATA:23 |
| PN:PN                                          | MOS/MSC                                                     | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                                         | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                                         | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 34-51-05PROC. REF: AMM 34-51-05 |                                                             |           |          |          |                        |           |           |             |                  |
| 236098                                         | NO. 1 COMMUNICATION STRAP BOARD                             |           |          |          |                        |           |           |             | Component ATA:23 |
| PN:PN                                          | MOS/MSC                                                     | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                                         | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                                         | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 23-11-03PROC. REF: AMM 23-11-03 |                                                             |           |          |          |                        |           |           |             |                  |
| 236099                                         | NO. 2 COMMUNICATION STRAP BOARD                             |           |          |          |                        |           |           |             | Component ATA:23 |
| PN:PN                                          | MOS/MSC                                                     | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                                         | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                                         | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 23-11-03PROC. REF: AMM 23-11-03 |                                                             |           |          |          |                        |           |           |             |                  |
| 237001                                         | COCKPIT VOICE RECORDER (CVR)                                |           |          |          |                        |           |           |             | Component ATA:23 |
| PN:PN                                          | MOS/MSC                                                     | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                                         | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                                         | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 23-70-01PROC. REF: AMM 23-70-01 |                                                             |           |          |          |                        |           |           |             |                  |
| 237005                                         | COCKPIT VOICE RECORDER, UNDERWATER LOCATOR BEACON (CVR ULB) |           |          |          |                        |           |           |             | Component ATA:23 |
| PN:DK120                                       | MOS/MSC                                                     | 02-Aug-24 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:NT60040                                     | HRS                                                         | 9525.7    |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                                         | 7276      |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 25-61-01PROC. REF: AMM 25-61-01 |                                                             |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                            | Unit    | C/W                                                                                         | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------|---------|---------------------------------------------------------------------------------------------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 23 - COMMUNICATIONS                            |         |                                                                                             |          |          |                        |           |           |             |          |
| 237005A                                            |         | FUNCTIONAL TEST / CLEAN BEACON SWITCH AND PERFORM TEST OF ULB BATTERY (IRN AA2560000)       |          |          |                        |           |           | Service     | ATA:23   |
| PN:DK120                                           | MOS     | 02-Aug-24                                                                                   | 24       |          | 02-Aug-26              |           | 487 d     |             |          |
| SN:NT60040                                         | HRS     | 9525.7                                                                                      |          |          |                        |           |           |             |          |
|                                                    | AFL     | 7276                                                                                        |          |          |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |         |                                                                                             |          |          |                        |           |           |             |          |
| 237005B                                            |         | REPLACE BATTERY ON OR BEFORE ULB BATTERY REPLACEMENT DATE. (ZONE/ACCESS 300 IRN # D2566001) |          |          |                        |           |           | Service     | ATA:23   |
| PN:DK120                                           | MOS/MSC | 02-Aug-24                                                                                   | DUE      |          | 31-Mar-29 (M)          |           | 1459 d    |             |          |
| SN:NT60040                                         | HRS     | 9525.7                                                                                      |          |          |                        |           |           |             |          |
|                                                    | AFL     | 7276                                                                                        |          |          |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |         |                                                                                             |          |          |                        |           |           |             |          |
| 237005C <sup>U</sup>                               |         | RECERTIFY PER MANUFACTURER'S INSTRUCTIONS                                                   |          |          |                        |           |           | Service     | ATA:23   |
| PN:DK120                                           | MOS     | 02-Aug-24                                                                                   | 216      |          | 02-Aug-42              |           | 6331 d    |             |          |
| SN:NT60040                                         | HRS     | 9525.7                                                                                      |          |          |                        |           |           |             |          |
|                                                    | AFL     | 7276                                                                                        |          |          |                        |           |           |             |          |
|                                                    |         |                                                                                             |          |          |                        |           |           |             |          |
| 237018                                             |         | COCKPIT VOICE RECORDER (CVR) INERTIA SWITCH                                                 |          |          |                        |           |           | Component   | ATA:23   |
| PN:PN                                              | MOS/MSC | 09-Mar-01                                                                                   | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0                                                                                           |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL     | 0                                                                                           |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 23-70-05PROC. REF: AMM 23-70-05     |         |                                                                                             |          |          |                        |           |           |             |          |
| 237019                                             |         | COCKPIT AREA MICROPHONE                                                                     |          |          |                        |           |           | Component   | ATA:23   |
| PN:PN                                              | MOS/MSC | 09-Mar-01                                                                                   | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0                                                                                           |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL     | 0                                                                                           |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |         |                                                                                             |          |          |                        |           |           |             |          |
| 237030                                             |         | PANEL SWITCH                                                                                |          |          |                        |           |           | Component   | ATA:23   |
| PN:PN                                              | MOS/MSC | 09-Mar-01                                                                                   | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0                                                                                           |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL     | 0                                                                                           |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |         |                                                                                             |          |          |                        |           |           |             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                            | Unit    | C / W     | Interval | TSX / Adj. | Next Due (ENG / APU) A / C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------|---------|-----------|----------|------------|----------------------------|-----------|-----------|-------------|----------|
| ATA 23 - COMMUNICATIONS                            |         |           |          |            |                            |           |           |             |          |
| 237031 COCKPIT VOICE RECORDER PRE-AMPLIFIER        |         |           |          |            |                            |           |           | Component   | ATA:23   |
| PN:PN                                              | MOS/MSC | 09-Mar-01 | O/C      | TSN 0      |                            |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0         |          | TSN 0      |                            |           |           |             |          |
|                                                    | AFL     | 0         |          | TSN 0      |                            |           |           |             |          |
| PROC. REF: AMM 23-70-03PROC. REF: AMM 23-70-03     |         |           |          |            |                            |           |           |             |          |
|                                                    |         |           |          |            |                            |           |           |             |          |
| 238001 NO. 1 RADIO MANAGEMENT UNIT (RMU)           |         |           |          |            |                            |           |           | Component   | ATA:23   |
| PN:7013270-985                                     | MOS/MSC | 04-May-18 | O/C      |            |                            |           |           |             |          |
| SN:06125540                                        | HRS     | 7849.4    |          |            |                            |           |           |             |          |
|                                                    | AFL     | 6022      |          |            |                            |           |           |             |          |
| PROC. REF: AMM 23-80-01PROC. REF: AMM 23-80-01     |         |           |          |            |                            |           |           |             |          |
|                                                    |         |           |          |            |                            |           |           |             |          |
| 238002 NO. 2 RADIO MANAGEMENT UNIT (RMU)           |         |           |          |            |                            |           |           | Component   | ATA:23   |
| PN:7013270-985                                     | MOS/MSC | 16-Mar-18 | O/C      |            |                            |           |           |             |          |
| SN:1248264                                         | HRS     | 7800.1    |          |            |                            |           |           |             |          |
|                                                    | AFL     | 5976      |          |            |                            |           |           |             |          |
| PROC. REF: AMM 23-80-01PROC. REF: AMM 23-80-01     |         |           |          |            |                            |           |           |             |          |
|                                                    |         |           |          |            |                            |           |           |             |          |
| 238025 CLEARANCE DELIVERY UNIT                     |         |           |          |            |                            |           |           | Component   | ATA:23   |
| PN:PN                                              | MOS/MSC | 09-Mar-01 | O/C      | TSN 0      |                            |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0         |          | TSN 0      |                            |           |           |             |          |
|                                                    | AFL     | 0         |          | TSN 0      |                            |           |           |             |          |
| PROC. REF: AMM 23-82-01PROC. REF: AMM 23-82-01     |         |           |          |            |                            |           |           |             |          |
|                                                    |         |           |          |            |                            |           |           |             |          |
| 239004 MASTER CONTROL SWITCH                       |         |           |          |            |                            |           |           | Component   | ATA:23   |
| PN:PN                                              | MOS/MSC | 09-Mar-01 | O/C      | TSN 0      |                            |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0         |          | TSN 0      |                            |           |           |             |          |
|                                                    | AFL     | 0         |          | TSN 0      |                            |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |         |           |          |            |                            |           |           |             |          |
|                                                    |         |           |          |            |                            |           |           |             |          |
| 239011 LAVATORY MASTER CONTROL SWITCH              |         |           |          |            |                            |           |           | Component   | ATA:23   |
| PN:8500-000077-6767                                | MOS/MSC | 03-Mar-06 | O/C      |            |                            |           |           |             |          |
| SN:0123                                            | HRS     | 4328.77   |          |            |                            |           |           |             |          |
|                                                    | AFL     | 3297      |          |            |                            |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |         |           |          |            |                            |           |           |             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN | Unit | C / W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|---------|------|-------|----------|----------|------------------------|-----------|-----------|-------------|----------|
|---------|------|-------|----------|----------|------------------------|-----------|-----------|-------------|----------|

ATA 23 - COMMUNICATIONS

|                                                |              |                                                       |     |  |  |  |  |               |        |
|------------------------------------------------|--------------|-------------------------------------------------------|-----|--|--|--|--|---------------|--------|
| A2300000                                       | <sup>S</sup> | ** COMMUNICATIONS SYSTEMS - PERFORM OPERATIONAL CHECK |     |  |  |  |  | Service       | ATA:23 |
|                                                | MOS          | 02-Aug-24                                             | 24  |  |  |  |  | AIRWORTHINESS |        |
|                                                | HRS          | 9525.7                                                | 600 |  |  |  |  |               |        |
|                                                | AFL          | 7276                                                  |     |  |  |  |  |               |        |
| PROC. REF: AMM 23-00-00PROC. REF: AMM 23-00-00 |              |                                                       |     |  |  |  |  |               | PKG:7  |

|                                                |              |                                                       |      |  |  |  |  |         |        |
|------------------------------------------------|--------------|-------------------------------------------------------|------|--|--|--|--|---------|--------|
| Y2360020                                       | <sup>S</sup> | PERFORM AIRCRAFT STATIC DISCHARGERS - FUNCTIONAL TEST |      |  |  |  |  | Service | ATA:23 |
|                                                | MOS          | 25-Nov-19                                             | 96   |  |  |  |  |         |        |
|                                                | HRS          | 8177.7                                                | 2400 |  |  |  |  |         |        |
|                                                | AFL          | 6303                                                  |      |  |  |  |  |         |        |
| PROC. REF: AMM 23-60-00PROC. REF: AMM 23-60-00 |              |                                                       |      |  |  |  |  |         | PKG:20 |

|                                                |              |                                                       |      |  |  |  |  |         |        |
|------------------------------------------------|--------------|-------------------------------------------------------|------|--|--|--|--|---------|--------|
| Y2360023                                       | <sup>S</sup> | PERFORM AIRCRAFT STATIC DISCHARGERS - FUNCTIONAL TEST |      |  |  |  |  | Service | ATA:23 |
|                                                | MOS          | 25-Nov-19                                             | 96   |  |  |  |  |         |        |
|                                                | HRS          | 8177.7                                                | 2400 |  |  |  |  |         |        |
|                                                | AFL          | 6303                                                  |      |  |  |  |  |         |        |
| PROC. REF: AMM 23-60-00PROC. REF: AMM 23-60-00 |              |                                                       |      |  |  |  |  |         | PKG:22 |

ATA 24 - ELECTRICAL POWER

|                                                |                           |           |     |       |  |  |  |           |        |
|------------------------------------------------|---------------------------|-----------|-----|-------|--|--|--|-----------|--------|
| 240109                                         | AFT CIRCUIT BREAKER PANEL |           |     |       |  |  |  | Component | ATA:24 |
| PN:PN                                          | MOS/MSC                   | 09-Mar-01 | O/C | TSN 0 |  |  |  |           |        |
| SN:UNKNOWN                                     | HRS                       | 0         |     | TSN 0 |  |  |  |           |        |
|                                                | AFL                       | 0         |     | TSN 0 |  |  |  |           |        |
| PROC. REF: AMM 24-60-04PROC. REF: AMM 24-60-04 |                           |           |     |       |  |  |  |           |        |

|                                                |                       |           |     |       |  |  |  |           |        |
|------------------------------------------------|-----------------------|-----------|-----|-------|--|--|--|-----------|--------|
| 242001                                         | NO. 1 5KVA ALTERNATOR |           |     |       |  |  |  | Component | ATA:24 |
| PN:90278-2                                     | MOS/MSC               | 14-Feb-24 | O/C | TSO 0 |  |  |  |           |        |
| SN:651                                         | HRS                   | 9467.2    |     | TSO 0 |  |  |  |           |        |
|                                                | AFL                   | 7246      |     | TSO 0 |  |  |  |           |        |
| PROC. REF: AMM 24-20-01PROC. REF: AMM 24-20-01 |                       |           |     |       |  |  |  |           |        |

?-Insufficient Information    S-Suppressed Requirement    \*-Estimated Due(New Requirement)    (EFF)-Effective C/W    (M)-Manual Due    U-User Task    Ex-Excluded Task



# Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 9669.1
AFL: 7372
As Of: 01-Apr-2025
02-Apr-2025 02:58 PM

| PN & SN                                            | Unit                                 | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty         |
|----------------------------------------------------|--------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|---------------|------------------|
| ATA 24 - ELECTRICAL POWER                          |                                      |           |          |          |                        |           |           |               |                  |
| 242001A                                            | REPLACE NO. 1 ** BEARING. (F2420000) |           |          |          |                        |           |           |               | Service ATA:24   |
| PN:90278-2                                         | MOS                                  | 14-Feb-24 |          |          |                        |           |           | AIRWORTHINESS |                  |
| SN:651                                             | HRS                                  | 9467.2    | 1200     |          | 10667.2                |           | 998.1     |               |                  |
|                                                    | AFL                                  | 7246      |          |          |                        |           |           |               |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                      |           |          |          |                        |           |           |               |                  |
| 242002                                             | NO. 2 5KVA ALTERNATOR                |           |          |          |                        |           |           |               | Component ATA:24 |
| PN:90278-2                                         | MOS/MSC                              | 19-May-22 | O/C      | TSO 0    |                        |           |           |               |                  |
| SN:1488                                            | HRS                                  | 8995.3    |          | TSO 0    |                        |           |           |               |                  |
|                                                    | AFL                                  | 6902      |          | TSO 0    |                        |           |           |               |                  |
| PROC. REF: AMM 24-20-01PROC. REF: AMM 24-20-01     |                                      |           |          |          |                        |           |           |               |                  |
| 242002A                                            | REPLACE NO. 2 ** BEARING. (F2420000) |           |          |          |                        |           |           |               | Service ATA:24   |
| PN:90278-2                                         | MOS                                  | 19-May-22 |          |          |                        |           |           | AIRWORTHINESS |                  |
| SN:1488                                            | HRS                                  | 8995.3    | 1200     |          | 10195.3                |           | 526.2     |               |                  |
|                                                    | AFL                                  | 6902      |          |          |                        |           |           |               |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                      |           |          |          |                        |           |           |               |                  |
| 242008                                             | AC/DC VOLT INDICATOR                 |           |          |          |                        |           |           |               | Component ATA:24 |
| PN:PN                                              | MOS/MSC                              | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |               |                  |
| SN:UNKNOWN                                         | HRS                                  | 0         |          | TSN 0    |                        |           |           |               |                  |
|                                                    | AFL                                  | 0         |          | TSN 0    |                        |           |           |               |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                      |           |          |          |                        |           |           |               |                  |
| 242050                                             | NO. 1 REMOTE CONTROL CIRCUIT BREAKER |           |          |          |                        |           |           |               | Component ATA:24 |
| PN:PN                                              | MOS/MSC                              | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |               |                  |
| SN:UNKNOWN                                         | HRS                                  | 0         |          | TSN 0    |                        |           |           |               |                  |
|                                                    | AFL                                  | 0         |          | TSN 0    |                        |           |           |               |                  |
| PROC. REF: AMM 24-60-01PROC. REF: AMM 24-60-01     |                                      |           |          |          |                        |           |           |               |                  |
| 242052                                             | NO. 2 REMOTE CONTROL CIRCUIT BREAKER |           |          |          |                        |           |           |               | Component ATA:24 |
| PN:PN                                              | MOS/MSC                              | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |               |                  |
| SN:UNKNOWN                                         | HRS                                  | 0         |          | TSN 0    |                        |           |           |               |                  |
|                                                    | AFL                                  | 0         |          | TSN 0    |                        |           |           |               |                  |
| PROC. REF: AMM 24-60-01PROC. REF: AMM 24-60-01     |                                      |           |          |          |                        |           |           |               |                  |

?-Insufficient Information    S-Suppressed Requirement    \*-Estimated Due(New Requirement)    (EFF)-Effective C/W    (M)-Manual Due    U-User Task    Ex-Excluded Task

# Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9669.1
 AFL: 7372
 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                            | Unit                                                             | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------|------------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 24 - ELECTRICAL POWER                          |                                                                  |           |          |          |                        |           |           |             |          |
| 242054                                             | NO. 3 REMOTE CONTROL CIRCUIT BREAKER                             |           |          |          |                        |           |           | Component   | ATA:24   |
| PN:PN                                              | MOS/MSC                                                          | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS                                                              | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL                                                              | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 24-60-01PROC. REF: AMM 24-60-01     |                                                                  |           |          |          |                        |           |           |             |          |
| 242081                                             | CABIN ELECTRICAL INVERTER                                        |           |          |          |                        |           |           | Component   | ATA:24   |
| PN:PN                                              | MOS/MSC                                                          | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS                                                              | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL                                                              | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                  |           |          |          |                        |           |           |             |          |
| 242082                                             | TAILCONE ELECTRICAL INVERTER                                     |           |          |          |                        |           |           | Component   | ATA:24   |
| PN:PN                                              | MOS/MSC                                                          | 09-Mar-01 | A/R      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS                                                              | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL                                                              | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                  |           |          |          |                        |           |           |             |          |
| 242083                                             | ELECTRICAL INVERTER                                              |           |          |          |                        |           |           | Component   | ATA:24   |
| PN:SS120(C)                                        | MOS/MSC                                                          | 23-Jul-13 | A/R      |          |                        |           |           |             |          |
| SN:320                                             | HRS                                                              | 7175.4    |          |          |                        |           |           |             |          |
|                                                    | AFL                                                              | 5474      |          |          |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                  |           |          |          |                        |           |           |             |          |
| 243001                                             | NO. 1 STARTER/GENERATOR                                          |           |          |          |                        |           |           | Component   | ATA:24   |
| PN:23280-067                                       | MOS/MSC                                                          | 27-Aug-21 | O/C      | TSO 0    |                        |           |           |             |          |
| SN:Y20436                                          | HRS                                                              | 8708.2    |          | TSO 0    |                        |           |           |             |          |
|                                                    | AFL                                                              | 6691      |          | TSO 0    |                        |           |           |             |          |
| PROC. REF: AMM 24-30-01PROC. REF: AMM 24-30-01     |                                                                  |           |          |          |                        |           |           |             |          |
| 243001A                                            | OVERHAUL NO. 1 STARTER/GENERATOR IRN P2430003. (ZONE/ACCESS 410) |           |          |          |                        |           |           | Service     | ATA:24   |
| PN:23280-067                                       | MOS                                                              | 27-Aug-21 |          |          |                        |           |           | OVERHAUL    |          |
| SN:Y20436                                          | HRS                                                              | 8708.2    | 1200     |          | 9908.2                 |           | 239.1     |             |          |
|                                                    | AFL                                                              | 6691      |          |          |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                  |           |          |          |                        |           |           |             |          |

?-Insufficient Information    S-Suppressed Requirement    \*-Estimated Due(New Requirement)    (EFF)-Effective C/W    (M)-Manual Due    U-User Task    Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                            | Unit    | C/W                                                              | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------|---------|------------------------------------------------------------------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 24 - ELECTRICAL POWER                          |         |                                                                  |          |          |                        |           |           |             |          |
| 243001B                                            |         | REPLACE NO. 1 STARTER/GENERATOR BEARING                          |          |          |                        |           |           | Service     | ATA:24   |
| PN:23280-067                                       | MOS/MSC | 27-Aug-21                                                        | N/A      |          |                        |           |           |             |          |
| SN:Y20436                                          | HRS     | 8708.2                                                           |          |          |                        |           |           |             |          |
|                                                    | AFL     | 6691                                                             |          |          |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |         |                                                                  |          |          |                        |           |           |             |          |
| 243002                                             |         | NO. 2 STARTER/GENERATOR                                          |          |          |                        |           |           | Component   | ATA:24   |
| PN:23280-067                                       | MOS/MSC | 02-Aug-24                                                        | O/C      | TSO 0    |                        |           |           |             |          |
| SN:P1484LA                                         | HRS     | 9525.7                                                           |          | TSO 0    |                        |           |           |             |          |
|                                                    | AFL     | 7276                                                             |          | TSO 0    |                        |           |           |             |          |
| PROC. REF: AMM 24-30-01PROC. REF: AMM 24-30-01     |         |                                                                  |          |          |                        |           |           |             |          |
| 243002A                                            |         | OVERHAUL NO. 2 STARTER/GENERATOR IRN P2430003. (ZONE/ACCESS 410) |          |          |                        |           |           | Service     | ATA:24   |
| PN:23280-067                                       | MOS     | 02-Aug-24                                                        |          |          |                        |           |           | OVERHAUL    |          |
| SN:P1484LA                                         | HRS     | 9525.7                                                           | 1200     |          | 10725.7                |           | 1056.6    |             |          |
|                                                    | AFL     | 7276                                                             |          |          |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |         |                                                                  |          |          |                        |           |           |             |          |
| 243002B                                            |         | REPLACE NO. 2 STARTER/GENERATOR BEARING                          |          |          |                        |           |           | Service     | ATA:24   |
| PN:23280-067                                       | MOS/MSC | 02-Aug-24                                                        | N/A      |          |                        |           |           |             |          |
| SN:P1484LA                                         | HRS     | 9525.7                                                           |          |          |                        |           |           |             |          |
|                                                    | AFL     | 7276                                                             |          |          |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |         |                                                                  |          |          |                        |           |           |             |          |
| 243003                                             |         | APU STARTER/GENERATOR                                            |          |          |                        |           |           | Component   | ATA:24   |
| PN:PN                                              | MOS/MSC | 09-Mar-01                                                        | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0                                                                |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL     | 0                                                                |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 49-40-01PROC. REF: AMM 49-40-01     |         |                                                                  |          |          |                        |           |           |             |          |
| 243005                                             |         | LEFT (GCU) GENERATOR CONTROL UNIT                                |          |          |                        |           |           | Component   | ATA:24   |
| PN:PN                                              | MOS/MSC | 09-Mar-01                                                        | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0                                                                |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL     | 0                                                                |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |         |                                                                  |          |          |                        |           |           |             |          |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C / W   (M)-Manual Due   U-User Task   Ex-Excluded Task

# Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9669.1
 AFL: 7372
 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                                                                                | Unit                                                                                                                                                                     | C/W       | Interval | TSX/Adj.  | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|--------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|----------|-----------|------------------------|-----------|-----------|-------------|----------|
| ATA 24 - ELECTRICAL POWER                                                                              |                                                                                                                                                                          |           |          |           |                        |           |           |             |          |
| 243006                                                                                                 | RIGHT (GCU) GENERATOR CONTROL UNIT                                                                                                                                       |           |          |           |                        |           |           | Component   | ATA:24   |
| PN:PN                                                                                                  | MOS/MSC                                                                                                                                                                  | 09-Mar-01 | O/C      | TSN 0     |                        |           |           |             |          |
| SN:UNKNOWN                                                                                             | HRS                                                                                                                                                                      | 0         |          | TSN 0     |                        |           |           |             |          |
|                                                                                                        | AFL                                                                                                                                                                      | 0         |          | TSN 0     |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                                                     |                                                                                                                                                                          |           |          |           |                        |           |           |             |          |
| 243019                                                                                                 | NO. 1 MAIN SHIP BATTERY                                                                                                                                                  |           |          |           |                        |           |           | Component   | ATA:24   |
| PN:RG-380E/40L                                                                                         | MOS/MSC                                                                                                                                                                  | 02-Aug-24 | O/C      |           |                        |           |           |             |          |
| SN:41180857                                                                                            | HRS                                                                                                                                                                      | 9525.7    |          |           |                        |           |           |             |          |
|                                                                                                        | AFL                                                                                                                                                                      | 7276      |          |           |                        |           |           |             |          |
| PROC. REF: AMM 24-31-01, AMM 24-31-06, CMM 24-30-71PROC. REF: AMM 24-31-01, AMM 24-31-06, CMM 24-30-71 |                                                                                                                                                                          |           |          |           |                        |           |           |             |          |
| 243019A                                                                                                | CHECK/SERVICE NO. 1 MAIN SHIP BATTERY (IRN O1222000 NI-CAD) - CAPACITY CHECK (IRN T1222004 38 AMP HOUR LEAD- ACID) - CAPACITY CHECK (IRN T1222007 28 AMP HOUR LEAD ACID) |           |          |           |                        |           |           | Service     | ATA:24   |
| PN:RG-380E/40L                                                                                         | MOS                                                                                                                                                                      | 03-Feb-25 | 6        | Adj -1d   | 02-Aug-25              |           | 122 d     |             |          |
| SN:41180857                                                                                            | HRS                                                                                                                                                                      | 9605.4    | 500      |           | 10105.4                |           | 436.3     |             |          |
|                                                                                                        | AFL                                                                                                                                                                      | 7333      |          |           |                        |           |           |             |          |
| PROC. REF: AMM 12-22-00, CMM 24-30-71PROC. REF: AMM 12-22-00, CMM 24-30-71                             |                                                                                                                                                                          |           |          |           |                        |           |           |             |          |
| 243020                                                                                                 | NO. 2 MAIN SHIP BATTERY                                                                                                                                                  |           |          |           |                        |           |           | Component   | ATA:24   |
| PN:RG-380E/40L                                                                                         | MOS/MSC                                                                                                                                                                  | 02-Aug-24 | O/C      | TSN 34    |                        |           |           |             |          |
| SN:41180858                                                                                            | HRS                                                                                                                                                                      | 9525.7    |          | TSN 762.4 |                        |           |           |             |          |
|                                                                                                        | AFL                                                                                                                                                                      | 7276      |          | TSN 532   |                        |           |           |             |          |
| PROC. REF: AMM 24-31-01, AMM 24-31-06, CMM 24-30-71PROC. REF: AMM 24-31-01, AMM 24-31-06, CMM 24-30-71 |                                                                                                                                                                          |           |          |           |                        |           |           |             |          |
| 243020A                                                                                                | CHECK/SERVICE NO. 2 MAIN SHIP BATTERY (IRN O1222000 NI-CAD) - CAPACITY CHECK (IRN T1222004 38 AMP HOUR LEAD- ACID) - CAPACITY CHECK (IRN T1222007 28 AMP HOUR LEAD ACID) |           |          |           |                        |           |           | Service     | ATA:24   |
| PN:RG-380E/40L                                                                                         | MOS                                                                                                                                                                      | 03-Feb-25 | 6        | Adj -1d   | 02-Aug-25              |           | 122 d     |             |          |
| SN:41180858                                                                                            | HRS                                                                                                                                                                      | 9605.4    | 500      |           | 10105.4                |           | 436.3     |             |          |
|                                                                                                        | AFL                                                                                                                                                                      | 7333      |          |           |                        |           |           |             |          |
| PROC. REF: AMM 12-22-00, CMM 24-30-71PROC. REF: AMM 12-22-00, CMM 24-30-71                             |                                                                                                                                                                          |           |          |           |                        |           |           |             |          |
| 243037                                                                                                 | EMERGENCY (IRN AB2431063 FOR RG-443) BATTERY                                                                                                                             |           |          |           |                        |           |           | Component   | ATA:24   |
| PN:RG-443                                                                                              | MOS                                                                                                                                                                      | 02-Aug-24 | 60       | TSN 10    | 02-Oct-28              |           | 1279 d    | REPLACE     |          |
| SN:41334011                                                                                            | HRS                                                                                                                                                                      | 9525.7    | 5000     | TSN 191.1 | 14334.6                |           | 4665.5    |             |          |
|                                                                                                        | AFL                                                                                                                                                                      | 7276      |          | TSN 125   |                        |           |           |             |          |
| PROC. REF: AMM 24-32-01, CMM 24-30-67PROC. REF: AMM 24-32-01, CMM 24-30-67                             |                                                                                                                                                                          |           |          |           |                        |           |           |             |          |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C/W   (M)-Manual Due   U-User Task   Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                            | Unit    | C / W                                                                                                                           | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------|---------|---------------------------------------------------------------------------------------------------------------------------------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 24 - ELECTRICAL POWER                          |         |                                                                                                                                 |          |          |                        |           |           |             |          |
| 243037A                                            |         | PERFORM EMERGENCY (IRN AB2431063 FOR RG-443) BATTERY CAPACITY CHECK (P/N 7624308001, IRN O2431002), (P/N RG-443, IRN AB2431062) |          |          |                        |           |           | Service     | ATA:24   |
| PN:RG-443                                          | MOS     | 02-Aug-24                                                                                                                       | 12       |          | 02-Aug-25              |           | 122 d     |             |          |
| SN:41334011                                        | HRS     | 9525.7                                                                                                                          | 1000     |          | 10525.7                |           | 856.6     |             |          |
|                                                    | AFL     | 7276                                                                                                                            |          |          |                        |           |           |             |          |
| PROC. REF: CMM 24-30-67PROC. REF: CMM 24-30-67     |         |                                                                                                                                 |          |          |                        |           |           |             |          |
| 246001                                             |         | LEFT FORWARD POWER DISTRIBUTION PANEL                                                                                           |          |          |                        |           |           | Component   | ATA:24   |
| PN:650GC02Y03                                      | MOS/MSC | 21-Jun-18                                                                                                                       | O/C      |          |                        |           |           |             |          |
| SN:575                                             | HRS     | 7887.8                                                                                                                          |          |          |                        |           |           |             |          |
|                                                    | AFL     | 6051                                                                                                                            |          |          |                        |           |           |             |          |
| PROC. REF: AMM 24-60-02PROC. REF: AMM 24-60-02     |         |                                                                                                                                 |          |          |                        |           |           |             |          |
| 246002                                             |         | RIGHT FORWARD POWER DISTRIBUTION PANEL                                                                                          |          |          |                        |           |           | Component   | ATA:24   |
| PN:PN                                              | MOS/MSC | 09-Mar-01                                                                                                                       | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0                                                                                                                               |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL     | 0                                                                                                                               |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 24-60-02PROC. REF: AMM 24-60-02     |         |                                                                                                                                 |          |          |                        |           |           |             |          |
| 246003                                             |         | LEFT AFT POWER DISTRIBUTION PANEL                                                                                               |          |          |                        |           |           | Component   | ATA:24   |
| PN:660GC02Y07                                      | MOS/MSC | 30-Jan-11                                                                                                                       | O/C      |          |                        |           |           |             |          |
| SN:588                                             | HRS     | 6501.3                                                                                                                          |          |          |                        |           |           |             |          |
|                                                    | AFL     | 4977                                                                                                                            |          |          |                        |           |           |             |          |
| PROC. REF: AMM 24-60-03PROC. REF: AMM 24-60-03     |         |                                                                                                                                 |          |          |                        |           |           |             |          |
| 246004                                             |         | RIGHT AFT POWER DISTRIBUTION PANEL                                                                                              |          |          |                        |           |           | Component   | ATA:24   |
| PN:PN                                              | MOS/MSC | 09-Mar-01                                                                                                                       | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0                                                                                                                               |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL     | 0                                                                                                                               |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 24-60-03PROC. REF: AMM 24-60-03     |         |                                                                                                                                 |          |          |                        |           |           |             |          |
| 246101                                             |         | LEFT GENERATOR CONTROL UNIT PRINTED CIRCUIT BOARD                                                                               |          |          |                        |           |           | Component   | ATA:24   |
| PN:PN                                              | MOS/MSC | 09-Mar-01                                                                                                                       | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0                                                                                                                               |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL     | 0                                                                                                                               |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |         |                                                                                                                                 |          |          |                        |           |           |             |          |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C/W   (M)-Manual Due   U-User Task   Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                            | Unit                                                                                                                                                                                                          | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 24 - ELECTRICAL POWER                          |                                                                                                                                                                                                               |           |          |          |                        |           |           |             |          |
| 246102                                             | LEFT LOGIC PRINTED CIRCUIT BOARD                                                                                                                                                                              |           |          |          |                        |           |           | Component   | ATA:24   |
| PN:PN                                              | MOS/MSC                                                                                                                                                                                                       | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS                                                                                                                                                                                                           | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL                                                                                                                                                                                                           | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                                                                                                                                                               |           |          |          |                        |           |           |             |          |
| 246104                                             | RIGHT GENERATOR CONTROL UNIT PRINTED CIRCUIT BOARD                                                                                                                                                            |           |          |          |                        |           |           | Component   | ATA:24   |
| PN:PN                                              | MOS/MSC                                                                                                                                                                                                       | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS                                                                                                                                                                                                           | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL                                                                                                                                                                                                           | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                                                                                                                                                               |           |          |          |                        |           |           |             |          |
| 246105                                             | RIGHT LOGIC PRINTED CIRCUIT BOARD                                                                                                                                                                             |           |          |          |                        |           |           | Component   | ATA:24   |
| PN:PN                                              | MOS/MSC                                                                                                                                                                                                       | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS                                                                                                                                                                                                           | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL                                                                                                                                                                                                           | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                                                                                                                                                               |           |          |          |                        |           |           |             |          |
| 246106                                             | APU GENERATOR CONTROL UNIT PRINTED CIRCUIT BOARD                                                                                                                                                              |           |          |          |                        |           |           | Component   | ATA:24   |
| PN:PN                                              | MOS/MSC                                                                                                                                                                                                       | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS                                                                                                                                                                                                           | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL                                                                                                                                                                                                           | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                                                                                                                                                               |           |          |          |                        |           |           |             |          |
| 5-19-00-Y2431005                                   | BATTERY CABLES AND RECEPTACLES - PERFORM BATTERY CONNECTOR TOLERANCE CHECK. (REFER TO 24-31-00.). IRN Y2431005                                                                                                |           |          |          |                        |           |           | Service     | ATA:24   |
|                                                    | MOS                                                                                                                                                                                                           | 02-Aug-24 |          |          |                        |           |           |             |          |
|                                                    | HRS                                                                                                                                                                                                           | 9525.7    | 300      |          | 9825.7                 |           | 156.6     |             |          |
|                                                    | AFL                                                                                                                                                                                                           | 7276      |          |          |                        |           |           |             |          |
| PROC. REF: AMM 24-31-00PROC. REF: AMM 24-31-00     |                                                                                                                                                                                                               |           |          |          |                        |           |           |             |          |
| AC2460002 <sup>S</sup>                             | REMOVE ATTACHING PARTS SECURING CIRCUIT BREAKER PANEL TO STRUCTURE. CHECK FOR LOOSE CIRCUIT BREAKER TERMINALS, LOOSE WIRE TERMINALS, CORRODED TERMINALS OR BUSS BARS, AND EVIDENCE OF WIRE INSULATION DAMAGE. |           |          |          |                        |           |           | Service     | ATA:24   |
|                                                    | MOS                                                                                                                                                                                                           | 09-Mar-01 | 96       |          |                        |           |           |             |          |
|                                                    | HRS                                                                                                                                                                                                           | 0         | 2400     |          |                        |           |           |             |          |
|                                                    | AFL                                                                                                                                                                                                           | 0         |          |          |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                                                                                                                                                               |           |          |          |                        |           |           |             |          |

?-Insufficient Information

S-Suppressed Requirement

\*-Estimated Due(New Requirement)

(EFF)-Effective C/W

(M)-Manual Due

U-User Task

Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                        | Unit | C / W                                                                                                                                                  | Interval | TSX / Adj. | Next Due (ENG / APU) A / C | Max Limit | Remaining | Disposition   | Warranty |
|------------------------------------------------|------|--------------------------------------------------------------------------------------------------------------------------------------------------------|----------|------------|----------------------------|-----------|-----------|---------------|----------|
| ATA 24 - ELECTRICAL POWER                      |      |                                                                                                                                                        |          |            |                            |           |           |               |          |
| H2450001 <sup>S</sup>                          |      | ** AUXILIARY POWER SUPPLIES - PERFORM FUNCTIONAL TEST                                                                                                  |          |            |                            |           |           | Service       | ATA:24   |
|                                                | MOS  | 02-Aug-24                                                                                                                                              | 24       |            |                            |           |           | AIRWORTHINESS |          |
|                                                | HRS  | 9525.7                                                                                                                                                 | 600      |            |                            |           |           |               |          |
|                                                | AFL  | 7276                                                                                                                                                   |          |            |                            |           |           |               |          |
| PROC. REF: AMM 24-00-00PROC. REF: AMM 24-00-00 |      |                                                                                                                                                        |          |            |                            |           |           |               | PKG:7    |
| H2450023 <sup>S</sup>                          |      | ** EMER BATT LOW AND GEN AMPS HIGH INDICATION - PERFORM OPERATIONAL CHECK.                                                                             |          |            |                            |           |           | Service       | ATA:24   |
|                                                | MOS  | 02-Aug-24                                                                                                                                              | 24       |            |                            |           |           | AIRWORTHINESS |          |
|                                                | HRS  | 9525.7                                                                                                                                                 | 600      |            |                            |           |           |               |          |
|                                                | AFL  | 7276                                                                                                                                                   |          |            |                            |           |           |               |          |
| PROC. REF: AMM 24-00-00PROC. REF: AMM 24-00-00 |      |                                                                                                                                                        |          |            |                            |           |           |               | PKG:7    |
| W2450000 <sup>S</sup>                          |      | ** GENERATOR FAIL INDICATION - PERFORM OPERATIONAL CHECK                                                                                               |          |            |                            |           |           | Service       | ATA:24   |
|                                                | MOS  | 02-Aug-24                                                                                                                                              | 24       |            |                            |           |           | AIRWORTHINESS |          |
|                                                | HRS  | 9525.7                                                                                                                                                 | 600      |            |                            |           |           |               |          |
|                                                | AFL  | 7276                                                                                                                                                   |          |            |                            |           |           |               |          |
| PROC. REF: AMM 24-00-00PROC. REF: AMM 24-00-00 |      |                                                                                                                                                        |          |            |                            |           |           |               | PKG:7    |
| Y2400002 <sup>S</sup>                          |      | ELECTRICAL WIRING - PERFORM VISUAL INSPECTION FOR ROUTING, SECURITY, CLEARANCES, CHAFING, AND ELECTRICAL COMPONENTS FOR SECURITY AND GENERAL CONDITION |          |            |                            |           |           | Service       | ATA:24   |
|                                                | MOS  | 02-Aug-24                                                                                                                                              | 24       |            |                            |           |           |               |          |
|                                                | HRS  | 9525.7                                                                                                                                                 | 600      |            |                            |           |           |               |          |
|                                                | AFL  | 7276                                                                                                                                                   |          |            |                            |           |           |               |          |
| PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00 |      |                                                                                                                                                        |          |            |                            |           |           |               | PKG:7    |
| Y2400025 <sup>S</sup>                          |      | ELECTRICAL WIRING - PERFORM VISUAL INSPECTION FOR ROUTING, SECURITY, CLEARANCES, CHAFING, AND ELECTRICAL COMPONENTS FOR SECURITY AND GENERAL CONDITION |          |            |                            |           |           | Service       | ATA:24   |
|                                                | MOS  | 02-Aug-24                                                                                                                                              | 24       |            |                            |           |           |               |          |
|                                                | HRS  | 9525.7                                                                                                                                                 | 600      |            |                            |           |           |               |          |
|                                                | AFL  | 7276                                                                                                                                                   |          |            |                            |           |           |               |          |
| PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00 |      |                                                                                                                                                        |          |            |                            |           |           |               | PKG:8    |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C / W   (M)-Manual Due   U-User Task   Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                            | Unit    | C/W                                                                 | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------|---------|---------------------------------------------------------------------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 24 - ELECTRICAL POWER                          |         |                                                                     |          |          |                        |           |           |             |          |
| Y2430005 <sup>S</sup>                              |         | STARTER/GENERATOR - PERFORM GROUNDING LUG BONDING CHECK             |          |          |                        |           |           | Service     | ATA:24   |
|                                                    | MOS     | 02-Aug-24                                                           | 24       |          |                        |           |           |             |          |
|                                                    | HRS     | 9525.7                                                              | 600      |          |                        |           |           |             |          |
|                                                    | AFL     | 7276                                                                |          |          |                        |           |           |             |          |
| PROC. REF: AMM 24-30-01PROC. REF: AMM 24-30-01     |         |                                                                     |          |          |                        |           |           |             | PKG:9    |
| Y2430006 <sup>S</sup>                              |         | STARTER/GENERATOR - PERFORM VISUAL INSPECTION OF GROUNDING LUGS     |          |          |                        |           |           | Service     | ATA:24   |
|                                                    | MOS     | 02-Aug-24                                                           | 24       |          |                        |           |           |             |          |
|                                                    | HRS     | 9525.7                                                              | 600      |          |                        |           |           |             |          |
|                                                    | AFL     | 7276                                                                |          |          |                        |           |           |             |          |
| PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00     |         |                                                                     |          |          |                        |           |           |             | PKG:9    |
| Y2431000 <sup>S</sup>                              |         | PERFORM BATTERY, GENERATOR, AND BUS-TIE CABLES - VISUAL INSPECTION. |          |          |                        |           |           | Service     | ATA:24   |
|                                                    | MOS     | 25-Nov-19                                                           | 96       |          |                        |           |           |             |          |
|                                                    | HRS     | 8177.7                                                              | 2400     |          |                        |           |           |             |          |
|                                                    | AFL     | 6303                                                                |          |          |                        |           |           |             |          |
| PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00     |         |                                                                     |          |          |                        |           |           |             | PKG:20   |
| Y2431001 <sup>S</sup>                              |         | EMERGENCY BATTERY CABLES - PERFORM VISUAL INSPECTION                |          |          |                        |           |           | Service     | ATA:24   |
|                                                    | MOS     | 02-Aug-24                                                           | 24       |          |                        |           |           |             |          |
|                                                    | HRS     | 9525.7                                                              | 600      |          |                        |           |           |             |          |
|                                                    | AFL     | 7276                                                                |          |          |                        |           |           |             |          |
| PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00     |         |                                                                     |          |          |                        |           |           |             | PKG:7    |
| ATA 25 - EQUIPMENT/FURNISHINGS                     |         |                                                                     |          |          |                        |           |           |             |          |
| 250010                                             |         | RELAY MODULE                                                        |          |          |                        |           |           | Component   | ATA:25   |
| PN:PN                                              | MOS/MSC | 09-Mar-01                                                           | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0                                                                   |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL     | 0                                                                   |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |         |                                                                     |          |          |                        |           |           |             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 45XR    Serial: 45-145    RegNo: N942FK    HRS: 9669.1    AFL: 7372    As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                        | Unit    | C/W                                 | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty |
|------------------------------------------------|---------|-------------------------------------|----------|----------|------------------------|-----------|-----------|---------------|----------|
| ATA 25 - EQUIPMENT/FURNISHINGS                 |         |                                     |          |          |                        |           |           |               |          |
| 251003 <sup>U</sup>                            |         | CHECK AIRCRAFT FLIGHT MANUAL STATUS |          |          |                        |           |           | Service       | ATA:25   |
|                                                | MOS/MSC | 09-Mar-01                           | A/R      |          |                        |           |           | CUSTOMER CODE |          |
|                                                | HRS     | 0                                   |          |          |                        |           |           |               |          |
|                                                | AFL     | 0                                   |          |          |                        |           |           |               |          |
|                                                |         |                                     |          |          |                        |           |           |               |          |
| 252000-1                                       |         | NO. 1 PASSENGER SEAT                |          |          |                        |           |           | Component     | ATA:25   |
| PN:PN                                          | MOS/MSC | 09-Mar-01                           | O/C      | TSN 0    |                        |           |           |               |          |
| SN:UNKNOWN                                     | HRS     | 0                                   |          | TSN 0    |                        |           |           |               |          |
|                                                | AFL     | 0                                   |          | TSN 0    |                        |           |           |               |          |
| PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45 |         |                                     |          |          |                        |           |           |               |          |
|                                                |         |                                     |          |          |                        |           |           |               |          |
| 252000-2                                       |         | NO. 2 PASSENGER SEAT                |          |          |                        |           |           | Component     | ATA:25   |
| PN:PN                                          | MOS/MSC | 09-Mar-01                           | O/C      | TSN 0    |                        |           |           |               |          |
| SN:UNKNOWN                                     | HRS     | 0                                   |          | TSN 0    |                        |           |           |               |          |
|                                                | AFL     | 0                                   |          | TSN 0    |                        |           |           |               |          |
| PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45 |         |                                     |          |          |                        |           |           |               |          |
|                                                |         |                                     |          |          |                        |           |           |               |          |
| 252000-3                                       |         | NO. 3 PASSENGER SEAT                |          |          |                        |           |           | Component     | ATA:25   |
| PN:PN                                          | MOS/MSC | 09-Mar-01                           | O/C      | TSN 0    |                        |           |           |               |          |
| SN:UNKNOWN                                     | HRS     | 0                                   |          | TSN 0    |                        |           |           |               |          |
|                                                | AFL     | 0                                   |          | TSN 0    |                        |           |           |               |          |
| PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45 |         |                                     |          |          |                        |           |           |               |          |
|                                                |         |                                     |          |          |                        |           |           |               |          |
| 252000-4                                       |         | NO. 4 PASSENGER SEAT                |          |          |                        |           |           | Component     | ATA:25   |
| PN:PN                                          | MOS/MSC | 09-Mar-01                           | O/C      | TSN 0    |                        |           |           |               |          |
| SN:UNKNOWN                                     | HRS     | 0                                   |          | TSN 0    |                        |           |           |               |          |
|                                                | AFL     | 0                                   |          | TSN 0    |                        |           |           |               |          |
| PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45 |         |                                     |          |          |                        |           |           |               |          |
|                                                |         |                                     |          |          |                        |           |           |               |          |
| 252000-5                                       |         | NO. 5 PASSENGER SEAT                |          |          |                        |           |           | Component     | ATA:25   |
| PN:PN                                          | MOS/MSC | 09-Mar-01                           | O/C      | TSN 0    |                        |           |           |               |          |
| SN:UNKNOWN                                     | HRS     | 0                                   |          | TSN 0    |                        |           |           |               |          |
|                                                | AFL     | 0                                   |          | TSN 0    |                        |           |           |               |          |
| PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45 |         |                                     |          |          |                        |           |           |               |          |
|                                                |         |                                     |          |          |                        |           |           |               |          |

?-Insufficient Information    S-Suppressed Requirement    \*-Estimated Due(New Requirement)    (EFF)-Effective C/W    (M)-Manual Due    U-User Task    Ex-Excluded Task

Status Report

Model: LEARJET 45XR    Serial: 45-145    RegNo: N942FK    HRS: 9669.1    AFL: 7372    As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                            | Unit    | C / W                    | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------|---------|--------------------------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 25 - EQUIPMENT/FURNISHINGS                     |         |                          |          |          |                        |           |           |             |          |
| 252000-6                                           |         | NO. 6 PASSENGER SEAT     |          |          |                        |           |           | Component   | ATA:25   |
| PN:PN                                              | MOS/MSC | 09-Mar-01                | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0                        |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL     | 0                        |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45     |         |                          |          |          |                        |           |           |             |          |
| 252000-7                                           |         | NO. 7 PASSENGER SEAT     |          |          |                        |           |           | Component   | ATA:25   |
| PN:PN                                              | MOS/MSC | 09-Mar-01                | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0                        |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL     | 0                        |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45     |         |                          |          |          |                        |           |           |             |          |
| 252000-8                                           |         | NO. 8 PASSENGER SEAT     |          |          |                        |           |           | Component   | ATA:25   |
| PN:PN                                              | MOS/MSC | 09-Mar-01                | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0                        |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL     | 0                        |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45     |         |                          |          |          |                        |           |           |             |          |
| 252000-9                                           |         | JUMP SEAT                |          |          |                        |           |           | Component   | ATA:25   |
| PN:PN                                              | MOS/MSC | 09-Mar-01                | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0                        |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL     | 0                        |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |         |                          |          |          |                        |           |           |             |          |
| 252001-1                                           |         | NO. 1 PASSENGER SEAT PCU |          |          |                        |           |           | Component   | ATA:25   |
| PN:PN                                              | MOS/MSC | 09-Mar-01                | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0                        |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL     | 0                        |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45     |         |                          |          |          |                        |           |           |             |          |
| 252001-2                                           |         | NO. 2 PASSENGER SEAT PCU |          |          |                        |           |           | Component   | ATA:25   |
| PN:PN                                              | MOS/MSC | 09-Mar-01                | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0                        |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL     | 0                        |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45     |         |                          |          |          |                        |           |           |             |          |

?-Insufficient Information    S-Suppressed Requirement    \*-Estimated Due(New Requirement)    (EFF)-Effective C/W    (M)-Manual Due    U-User Task    Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                        | Unit    | C/W                      | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|------------------------------------------------|---------|--------------------------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 25 - EQUIPMENT/FURNISHINGS                 |         |                          |          |          |                        |           |           |             |          |
| 252001-3                                       |         | NO. 3 PASSENGER SEAT PCU |          |          |                        |           |           | Component   | ATA:25   |
| PN:PN                                          | MOS/MSC | 09-Mar-01                | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS     | 0                        |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL     | 0                        |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45 |         |                          |          |          |                        |           |           |             |          |
| 252001-4                                       |         | NO. 4 PASSENGER SEAT PCU |          |          |                        |           |           | Component   | ATA:25   |
| PN:SP-45-07A                                   | MOS/MSC | 05-Apr-06                | O/C      |          |                        |           |           |             |          |
| SN:020600592                                   | HRS     | 4422.47                  |          |          |                        |           |           |             |          |
|                                                | AFL     | 3369                     |          |          |                        |           |           |             |          |
| PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45 |         |                          |          |          |                        |           |           |             |          |
| 252001-5                                       |         | NO. 5 PASSENGER SEAT PCU |          |          |                        |           |           | Component   | ATA:25   |
| PN:PN                                          | MOS/MSC | 09-Mar-01                | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS     | 0                        |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL     | 0                        |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45 |         |                          |          |          |                        |           |           |             |          |
| 252001-6                                       |         | NO. 6 PASSENGER SEAT PCU |          |          |                        |           |           | Component   | ATA:25   |
| PN:PN                                          | MOS/MSC | 09-Mar-01                | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS     | 0                        |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL     | 0                        |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45 |         |                          |          |          |                        |           |           |             |          |
| 252001-7                                       |         | NO. 7 PASSENGER SEAT PCU |          |          |                        |           |           | Component   | ATA:25   |
| PN:PN                                          | MOS/MSC | 09-Mar-01                | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS     | 0                        |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL     | 0                        |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45 |         |                          |          |          |                        |           |           |             |          |
| 252001-8                                       |         | NO. 8 PASSENGER SEAT PCU |          |          |                        |           |           | Component   | ATA:25   |
| PN:PN                                          | MOS/MSC | 09-Mar-01                | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS     | 0                        |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL     | 0                        |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45 |         |                          |          |          |                        |           |           |             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                            | Unit                           | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------|--------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 25 - EQUIPMENT/FURNISHINGS                     |                                |           |          |          |                        |           |           |             |                  |
| 252001-9                                           | LAVATORY PCU                   |           |          |          |                        |           |           |             | Component ATA:25 |
| PN:PN                                              | MOS/MSC                        | 09-Mar-01 | A/R      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                            | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                            | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                |           |          |          |                        |           |           |             |                  |
| 252005 U                                           | AIRSHOW FLIGHT DECK CONTROLLER |           |          |          |                        |           |           |             | Component ATA:25 |
| PN:PN                                              | MOS/MSC                        | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                            | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                            | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    |                                |           |          |          |                        |           |           |             |                  |
| 252010                                             | AIRSHOW COMPUTER               |           |          |          |                        |           |           |             | Component ATA:25 |
| PN:920040                                          | MOS/MSC                        | 06-Mar-09 | O/C      |          |                        |           |           |             |                  |
| SN:452                                             | HRS                            | 6115.4    |          |          |                        |           |           |             |                  |
|                                                    | AFL                            |           |          |          |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                |           |          |          |                        |           |           |             |                  |
| 252020                                             | CLOSET SWITCH PANEL ASSEMBLY   |           |          |          |                        |           |           |             | Component ATA:25 |
| PN:PN                                              | MOS/MSC                        | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                            | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                            | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                |           |          |          |                        |           |           |             |                  |
| 252090                                             | NO. 1 110 VOLT POWER OUTLET    |           |          |          |                        |           |           |             | Component ATA:25 |
| PN:PN                                              | MOS/MSC                        | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                            | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                            | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                |           |          |          |                        |           |           |             |                  |
| 252091                                             | NO. 2 110 VOLT POWER OUTLET    |           |          |          |                        |           |           |             | Component ATA:25 |
| PN:PN                                              | MOS/MSC                        | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                            | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                            | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9669.1
 AFL: 7372
 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                            | Unit                        | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------|-----------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 25 - EQUIPMENT/FURNISHINGS                     |                             |           |          |          |                        |           |           |             |                  |
| 252092                                             | NO. 3 110 VOLT POWER OUTLET |           |          |          |                        |           |           |             | Component ATA:25 |
| PN:PN                                              | MOS/MSC                     | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                         | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                         | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                             |           |          |          |                        |           |           |             |                  |
| 252095                                             | NO. 4 110 VOLT POWER OUTLET |           |          |          |                        |           |           |             | Component ATA:25 |
| PN:PN                                              | MOS/MSC                     | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                         | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                         | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                             |           |          |          |                        |           |           |             |                  |
| 252097                                             | NO. 1 AC POWER OUTLET       |           |          |          |                        |           |           |             | Component ATA:25 |
| PN:PN                                              | MOS/MSC                     | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                         | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                         | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                             |           |          |          |                        |           |           |             |                  |
| 252098                                             | NO. 2 AC POWER OUTLET       |           |          |          |                        |           |           |             | Component ATA:25 |
| PN:PN                                              | MOS/MSC                     | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                         | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                         | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                             |           |          |          |                        |           |           |             |                  |
| 252099                                             | NO. 3 AC POWER OUTLET       |           |          |          |                        |           |           |             | Component ATA:25 |
| PN:PN                                              | MOS/MSC                     | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                         | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                         | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                             |           |          |          |                        |           |           |             |                  |
| 253001                                             | MICROWAVE OVEN              |           |          |          |                        |           |           |             | Component ATA:25 |
| PN:255A-LH28-115                                   | MOS/MSC                     | 28-Jul-05 | O/C      |          |                        |           |           |             |                  |
| SN:19976                                           | HRS                         | 3775.77   |          |          |                        |           |           |             |                  |
|                                                    | AFL                         | 2849      |          |          |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                             |           |          |          |                        |           |           |             |                  |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C/W   (M)-Manual Due   U-User Task   Ex-Excluded Task

Status Report

Model: LEARJET 45XR    Serial: 45-145    RegNo: N942FK    HRS: 9669.1    AFL: 7372    As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                            | Unit                         | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty            |
|----------------------------------------------------|------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|---------------------|
| ATA 25 - EQUIPMENT/FURNISHINGS                     |                              |           |          |          |                        |           |           |             |                     |
| 253075                                             | NO. 1 HEATED WATER CONTAINER |           |          |          |                        |           |           |             | Component    ATA:25 |
| PN:PN                                              | MOS/MSC                      | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                         | HRS                          | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                    | AFL                          | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                              |           |          |          |                        |           |           |             |                     |
| 253076                                             | NO. 2 HEATED WATER CONTAINER |           |          |          |                        |           |           |             | Component    ATA:25 |
| PN:PN                                              | MOS/MSC                      | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                         | HRS                          | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                    | AFL                          | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                              |           |          |          |                        |           |           |             |                     |
| 253077                                             | HEATED WATER SWITCH          |           |          |          |                        |           |           |             | Component    ATA:25 |
| PN:PN                                              | MOS/MSC                      | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                         | HRS                          | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                    | AFL                          | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                              |           |          |          |                        |           |           |             |                     |
| 253080                                             | GALLEY DRAIN VALVE SOLENOID  |           |          |          |                        |           |           |             | Component    ATA:25 |
| PN:8210G94-24DC                                    | MOS/MSC                      | 03-Jan-06 | O/C      |          |                        |           |           |             |                     |
| SN:T116684                                         | HRS                          | 4160.77   |          |          |                        |           |           |             |                     |
|                                                    | AFL                          | 3151      |          |          |                        |           |           |             |                     |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                              |           |          |          |                        |           |           |             |                     |
| 256001                                             | PILOT CREW SEAT              |           |          |          |                        |           |           |             | Component    ATA:25 |
| PN:PN                                              | MOS/MSC                      | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                         | HRS                          | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                    | AFL                          | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: AMM 25-10-50PROC. REF: AMM 25-10-50     |                              |           |          |          |                        |           |           |             |                     |
| 256002                                             | COPILOT CREW SEAT            |           |          |          |                        |           |           |             | Component    ATA:25 |
| PN:PN                                              | MOS/MSC                      | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                         | HRS                          | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                    | AFL                          | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: AMM 25-10-50PROC. REF: AMM 25-10-50     |                              |           |          |          |                        |           |           |             |                     |

?-Insufficient Information    S-Suppressed Requirement    \*-Estimated Due(New Requirement)    (EFF)-Effective C/W    (M)-Manual Due    U-User Task    Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                                                    | Unit                                                              | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty |
|----------------------------------------------------------------------------|-------------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|---------------|----------|
| ATA 25 - EQUIPMENT/FURNISHINGS                                             |                                                                   |           |          |          |                        |           |           |               |          |
| 256032                                                                     | COPILOT PROTECTIVE BREATHING (PBE). (IRN A3510008) EQUIPMENT UNIT |           |          |          |                        |           |           | Component     | ATA:25   |
| PN:119003                                                                  | MOS/MSC                                                           | 09-Mar-01 | N/A      |          |                        |           |           | NOT INSTALLED |          |
| SN:131371                                                                  | HRS                                                               | 0         |          |          |                        |           |           |               |          |
|                                                                            | AFL                                                               | 0         |          |          |                        |           |           |               |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                                                   |           |          |          |                        |           |           |               |          |
| 256061                                                                     | PILOT LIFE VEST                                                   |           |          |          |                        |           |           | Component     | ATA:25   |
| PN:P01074-101                                                              | MOS/MSC                                                           | 09-Feb-21 | O/C      | TSN 0    |                        |           |           |               |          |
| SN:20100400026                                                             | HRS                                                               | 8401.3    |          | TSN 0    |                        |           |           |               |          |
|                                                                            | AFL                                                               | 6458      |          | TSN 0    |                        |           |           |               |          |
| PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01 |                                                                   |           |          |          |                        |           |           |               |          |
| 256061A                                                                    | INSPECT PILOT LIFE VEST (IRN # E2561002)                          |           |          |          |                        |           |           | Service       | ATA:25   |
| PN:P01074-101                                                              | MOS                                                               | 09-Feb-21 | 60       |          | 09-Feb-26              |           | 313 d     |               |          |
| SN:20100400026                                                             | HRS                                                               |           |          |          |                        |           |           |               |          |
|                                                                            | AFL                                                               |           |          |          |                        |           |           |               |          |
| Inspection Date: : 09-Feb-21                                               |                                                                   |           |          |          |                        |           |           |               |          |
| PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01 |                                                                   |           |          |          |                        |           |           |               |          |
| 256062                                                                     | COPILOT LIFE VEST                                                 |           |          |          |                        |           |           | Component     | ATA:25   |
| PN:P01074-101                                                              | MOS/MSC                                                           | 09-Feb-21 | O/C      | TSN 0    |                        |           |           |               |          |
| SN:20100400085                                                             | HRS                                                               | 8401.3    |          | TSN 0    |                        |           |           |               |          |
|                                                                            | AFL                                                               | 6458      |          | TSN 0    |                        |           |           |               |          |
| PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01 |                                                                   |           |          |          |                        |           |           |               |          |
| 256062A                                                                    | INSPECT COPILOT LIFE VEST (IRN # E2561002)                        |           |          |          |                        |           |           | Service       | ATA:25   |
| PN:P01074-101                                                              | MOS                                                               | 09-Feb-21 | 60       |          | 09-Feb-26              |           | 313 d     |               |          |
| SN:20100400085                                                             | HRS                                                               |           |          |          |                        |           |           |               |          |
|                                                                            | AFL                                                               |           |          |          |                        |           |           |               |          |
| Inspection Date: : 09-Feb-21                                               |                                                                   |           |          |          |                        |           |           |               |          |
| PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01 |                                                                   |           |          |          |                        |           |           |               |          |
| 256063                                                                     | NO. 1 LIFE VEST                                                   |           |          |          |                        |           |           | Component     | ATA:25   |
| PN:P01074-101                                                              | MOS/MSC                                                           | 09-Feb-21 | O/C      | TSN 0    |                        |           |           |               |          |
| SN:20100400200                                                             | HRS                                                               | 8401.3    |          | TSN 0    |                        |           |           |               |          |
|                                                                            | AFL                                                               | 6458      |          | TSN 0    |                        |           |           |               |          |
| PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01 |                                                                   |           |          |          |                        |           |           |               |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9669.1
 AFL: 7372
 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                                                    | Unit                                     | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 25 - EQUIPMENT/FURNISHINGS                                             |                                          |           |          |          |                        |           |           |             |                  |
| 256063A                                                                    | INSPECT NO. 1 LIFE VEST (IRN # E2561002) |           |          |          |                        |           |           |             | Service ATA:25   |
| PN:P01074-101                                                              | MOS                                      | 09-Feb-21 | 60       |          | 09-Feb-26              |           | 313 d     |             |                  |
| SN:20100400200                                                             | HRS                                      |           |          |          |                        |           |           |             |                  |
|                                                                            | AFL                                      |           |          |          |                        |           |           |             |                  |
| Inspection Date: : 09-Feb-21                                               |                                          |           |          |          |                        |           |           |             |                  |
| PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01 |                                          |           |          |          |                        |           |           |             |                  |
| 256064                                                                     | NO. 2 LIFE VEST                          |           |          |          |                        |           |           |             | Component ATA:25 |
| PN:P01074-101                                                              | MOS/MSC                                  | 09-Feb-21 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:20100400323                                                             | HRS                                      | 8401.3    |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                      | 6458      |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01 |                                          |           |          |          |                        |           |           |             |                  |
| 256064A                                                                    | INSPECT NO. 2 LIFE VEST (IRN # E2561002) |           |          |          |                        |           |           |             | Service ATA:25   |
| PN:P01074-101                                                              | MOS                                      | 09-Feb-21 | 60       |          | 09-Feb-26              |           | 313 d     |             |                  |
| SN:20100400323                                                             | HRS                                      |           |          |          |                        |           |           |             |                  |
|                                                                            | AFL                                      |           |          |          |                        |           |           |             |                  |
| Inspection Date: : 09-Feb-21                                               |                                          |           |          |          |                        |           |           |             |                  |
| PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01 |                                          |           |          |          |                        |           |           |             |                  |
| 256065                                                                     | NO. 3 LIFE VEST                          |           |          |          |                        |           |           |             | Component ATA:25 |
| PN:P01074-101                                                              | MOS/MSC                                  | 09-Feb-21 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:20100400333                                                             | HRS                                      | 8401.3    |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                      | 6458      |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01 |                                          |           |          |          |                        |           |           |             |                  |
| 256065A                                                                    | INSPECT NO. 3 LIFE VEST (IRN # E2561002) |           |          |          |                        |           |           |             | Service ATA:25   |
| PN:P01074-101                                                              | MOS                                      | 09-Feb-21 | 60       |          | 09-Feb-26              |           | 313 d     |             |                  |
| SN:20100400333                                                             | HRS                                      |           |          |          |                        |           |           |             |                  |
|                                                                            | AFL                                      |           |          |          |                        |           |           |             |                  |
| Inspection Date: : 09-Feb-21                                               |                                          |           |          |          |                        |           |           |             |                  |
| PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01 |                                          |           |          |          |                        |           |           |             |                  |
| 256066                                                                     | NO. 4 LIFE VEST                          |           |          |          |                        |           |           |             | Component ATA:25 |
| PN:P01074-101                                                              | MOS/MSC                                  | 09-Feb-21 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:20100400338                                                             | HRS                                      | 8401.3    |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                      | 6458      |          | TSN 0    |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                                                    | Unit                                     | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------------------------------|------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 25 - EQUIPMENT/FURNISHINGS                                             |                                          |           |          |          |                        |           |           |             |          |
| PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01 |                                          |           |          |          |                        |           |           |             |          |
|                                                                            |                                          |           |          |          |                        |           |           |             |          |
| 256066A                                                                    | INSPECT NO. 4 LIFE VEST (IRN # E2561002) |           |          |          |                        |           |           | Service     | ATA:25   |
| PN:P01074-101                                                              | MOS                                      | 09-Feb-21 | 60       |          | 09-Feb-26              |           | 313 d     |             |          |
| SN:20100400338                                                             | HRS                                      |           |          |          |                        |           |           |             |          |
|                                                                            | AFL                                      |           |          |          |                        |           |           |             |          |
| Inspection Date: : 09-Feb-21                                               |                                          |           |          |          |                        |           |           |             |          |
| PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01 |                                          |           |          |          |                        |           |           |             |          |
|                                                                            |                                          |           |          |          |                        |           |           |             |          |
| 256067                                                                     | NO. 5 LIFE VEST                          |           |          |          |                        |           |           | Component   | ATA:25   |
| PN:P01074-101                                                              | MOS/MSC                                  | 09-Feb-21 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:20100400422                                                             | HRS                                      | 8401.3    |          | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL                                      | 6458      |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01 |                                          |           |          |          |                        |           |           |             |          |
|                                                                            |                                          |           |          |          |                        |           |           |             |          |
| 256067A                                                                    | INSPECT NO. 5 LIFE VEST (IRN # E2561002) |           |          |          |                        |           |           | Service     | ATA:25   |
| PN:P01074-101                                                              | MOS                                      | 09-Feb-21 | 60       |          | 09-Feb-26              |           | 313 d     |             |          |
| SN:20100400422                                                             | HRS                                      |           |          |          |                        |           |           |             |          |
|                                                                            | AFL                                      |           |          |          |                        |           |           |             |          |
| Inspection Date: : 09-Feb-21                                               |                                          |           |          |          |                        |           |           |             |          |
| PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01 |                                          |           |          |          |                        |           |           |             |          |
|                                                                            |                                          |           |          |          |                        |           |           |             |          |
| 256068                                                                     | NO. 6 LIFE VEST                          |           |          |          |                        |           |           | Component   | ATA:25   |
| PN:P01074-101                                                              | MOS/MSC                                  | 09-Feb-21 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:20100400432                                                             | HRS                                      | 8401.3    |          | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL                                      | 6458      |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01 |                                          |           |          |          |                        |           |           |             |          |
|                                                                            |                                          |           |          |          |                        |           |           |             |          |
| 256068A                                                                    | INSPECT NO. 6 LIFE VEST (IRN # E2561002) |           |          |          |                        |           |           | Service     | ATA:25   |
| PN:P01074-101                                                              | MOS                                      | 09-Feb-21 | 60       |          | 09-Feb-26              |           | 313 d     |             |          |
| SN:20100400432                                                             | HRS                                      |           |          |          |                        |           |           |             |          |
|                                                                            | AFL                                      |           |          |          |                        |           |           |             |          |
| Inspection Date: : 09-Feb-21                                               |                                          |           |          |          |                        |           |           |             |          |
| PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01 |                                          |           |          |          |                        |           |           |             |          |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C/W   (M)-Manual Due   U-User Task   Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|---------|------|-----|----------|----------|------------------------|-----------|-----------|-------------|----------|
|---------|------|-----|----------|----------|------------------------|-----------|-----------|-------------|----------|

ATA 25 - EQUIPMENT/FURNISHINGS

|                                                                            |                 |           |     |       |  |  |  |           |        |
|----------------------------------------------------------------------------|-----------------|-----------|-----|-------|--|--|--|-----------|--------|
| 256069                                                                     | NO. 7 LIFE VEST |           |     |       |  |  |  | Component | ATA:25 |
| PN:P01074-101                                                              | MOS/MSC         | 09-Feb-21 | O/C | TSN 0 |  |  |  |           |        |
| SN:20100400704                                                             | HRS             | 8401.3    |     | TSN 0 |  |  |  |           |        |
|                                                                            | AFL             | 6458      |     | TSN 0 |  |  |  |           |        |
| PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01 |                 |           |     |       |  |  |  |           |        |

|                                                                            |                                          |           |    |  |           |  |       |         |        |
|----------------------------------------------------------------------------|------------------------------------------|-----------|----|--|-----------|--|-------|---------|--------|
| 256069A                                                                    | INSPECT NO. 7 LIFE VEST (IRN # E2561002) |           |    |  |           |  |       | Service | ATA:25 |
| PN:P01074-101                                                              | MOS                                      | 09-Feb-21 | 60 |  | 09-Feb-26 |  | 313 d |         |        |
| SN:20100400704                                                             | HRS                                      |           |    |  |           |  |       |         |        |
|                                                                            | AFL                                      |           |    |  |           |  |       |         |        |
| Inspection Date: : 09-Feb-21                                               |                                          |           |    |  |           |  |       |         |        |
| PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01 |                                          |           |    |  |           |  |       |         |        |

|                                                                            |                 |           |     |       |  |  |  |           |        |
|----------------------------------------------------------------------------|-----------------|-----------|-----|-------|--|--|--|-----------|--------|
| 256070                                                                     | NO. 8 LIFE VEST |           |     |       |  |  |  | Component | ATA:25 |
| PN:P01074-101                                                              | MOS/MSC         | 09-Feb-21 | O/C | TSN 0 |  |  |  |           |        |
| SN:20100400721                                                             | HRS             | 8401.3    |     | TSN 0 |  |  |  |           |        |
|                                                                            | AFL             | 6458      |     | TSN 0 |  |  |  |           |        |
| PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01 |                 |           |     |       |  |  |  |           |        |

|                                                                            |                                          |           |    |  |           |  |       |         |        |
|----------------------------------------------------------------------------|------------------------------------------|-----------|----|--|-----------|--|-------|---------|--------|
| 256070A                                                                    | INSPECT NO. 8 LIFE VEST (IRN # E2561002) |           |    |  |           |  |       | Service | ATA:25 |
| PN:P01074-101                                                              | MOS                                      | 09-Feb-21 | 60 |  | 09-Feb-26 |  | 313 d |         |        |
| SN:20100400721                                                             | HRS                                      |           |    |  |           |  |       |         |        |
|                                                                            | AFL                                      |           |    |  |           |  |       |         |        |
| Inspection Date: : 09-Feb-21                                               |                                          |           |    |  |           |  |       |         |        |
| PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01 |                                          |           |    |  |           |  |       |         |        |

|                                                                                |                    |           |     |       |  |  |  |           |        |
|--------------------------------------------------------------------------------|--------------------|-----------|-----|-------|--|--|--|-----------|--------|
| 256071                                                                         | LAVATORY LIFE VEST |           |     |       |  |  |  | Component | ATA:25 |
| PN:P01074-101                                                                  | MOS/MSC            | 09-Feb-21 | O/C | TSN 0 |  |  |  |           |        |
| SN:20100400737                                                                 | HRS                | 8401.3    |     | TSN 0 |  |  |  |           |        |
|                                                                                | AFL                | 6458      |     | TSN 0 |  |  |  |           |        |
| PROC. REF: GENERIC NO REF, CMM 25-60-05PROC. REF: GENERIC NO REF, CMM 25-60-05 |                    |           |     |       |  |  |  |           |        |

|                              |                                             |           |    |  |           |  |       |         |        |
|------------------------------|---------------------------------------------|-----------|----|--|-----------|--|-------|---------|--------|
| 256071A                      | INSPECT LAVATORY LIFE VEST (IRN # E2561002) |           |    |  |           |  |       | Service | ATA:25 |
| PN:P01074-101                | MOS                                         | 09-Feb-21 | 60 |  | 09-Feb-26 |  | 313 d |         |        |
| SN:20100400737               | HRS                                         |           |    |  |           |  |       |         |        |
|                              | AFL                                         |           |    |  |           |  |       |         |        |
| Inspection Date: : 09-Feb-21 |                                             |           |    |  |           |  |       |         |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|---------|------|-----|----------|----------|------------------------|-----------|-----------|-------------|----------|
|---------|------|-----|----------|----------|------------------------|-----------|-----------|-------------|----------|

ATA 25 - EQUIPMENT/FURNISHINGS

PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01

|                       |         |           |     |       |  |  |  |           |        |
|-----------------------|---------|-----------|-----|-------|--|--|--|-----------|--------|
| 256074                | U       | LIFE RAFT |     |       |  |  |  | Component | ATA:25 |
| PN:1015FAUL-630-1-136 | MOS/MSC | 30-Nov-16 | O/C | TSO 0 |  |  |  |           |        |
| SN:10UL-00997         | HRS     | 7683.1    |     | TSO 0 |  |  |  |           |        |
|                       | AFL     | 5878      |     | TSO 0 |  |  |  |           |        |

|                       |     |                                                            |    |           |  |  |       |         |        |
|-----------------------|-----|------------------------------------------------------------|----|-----------|--|--|-------|---------|--------|
| 256074A               | U   | INSPECT LIFE RAFT LIFE RAFT IAW MANUFACTURERS INSTRUCTIONS |    |           |  |  |       | Service | ATA:25 |
| PN:1015FAUL-630-1-136 | MOS | 02-Aug-24                                                  | 36 | 02-Aug-27 |  |  | 852 d |         |        |
| SN:10UL-00997         | HRS | 9525.7                                                     |    |           |  |  |       |         |        |
|                       | AFL | 7276                                                       |    |           |  |  |       |         |        |

|            |         |           |     |       |  |  |  |           |        |
|------------|---------|-----------|-----|-------|--|--|--|-----------|--------|
| 256075     | U       | LIFE RAFT |     |       |  |  |  | Component | ATA:25 |
| PN:PN      | MOS/MSC | 09-Mar-01 | O/C | TSN 0 |  |  |  |           |        |
| SN:UNKNOWN | HRS     | 0         |     | TSN 0 |  |  |  |           |        |
|            | AFL     | 0         |     | TSN 0 |  |  |  |           |        |

|                                                    |         |               |     |  |  |  |  |           |        |
|----------------------------------------------------|---------|---------------|-----|--|--|--|--|-----------|--------|
| 256076                                             |         | FIRST AID KIT |     |  |  |  |  | Component | ATA:25 |
| PN:MSK70002                                        | MOS/MSC | 14-Jul-07     | O/C |  |  |  |  |           |        |
| SN:0602                                            | HRS     | 5618.1        |     |  |  |  |  |           |        |
|                                                    | AFL     | 4293          |     |  |  |  |  |           |        |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |         |               |     |  |  |  |  |           |        |

|            |         |             |     |       |  |  |  |           |        |
|------------|---------|-------------|-----|-------|--|--|--|-----------|--------|
| 256077     | U       | MEDICAL KIT |     |       |  |  |  | Component | ATA:25 |
| PN:PN      | MOS/MSC | 09-Mar-01   | O/C | TSN 0 |  |  |  |           |        |
| SN:UNKNOWN | HRS     | 0           |     | TSN 0 |  |  |  |           |        |
|            | AFL     | 0           |     | TSN 0 |  |  |  |           |        |

|        |         |                                      |     |  |  |  |  |         |        |
|--------|---------|--------------------------------------|-----|--|--|--|--|---------|--------|
| 256080 |         | INSPECT LIFE VESTS 05-19-00-E2561002 |     |  |  |  |  | Service | ATA:25 |
|        | MOS/MSC | 09-Mar-01                            | A/R |  |  |  |  |         |        |
|        | HRS     | 0                                    |     |  |  |  |  |         |        |
|        | AFL     | 0                                    |     |  |  |  |  |         |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-202502-Apr-2025 02:58 PM

| PN & SN                                                                        | Unit    | C/W                                                                    | Interval | TSX/Adj.   | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|--------------------------------------------------------------------------------|---------|------------------------------------------------------------------------|----------|------------|------------------------|-----------|-----------|-------------|----------|
| ATA 25 - EQUIPMENT/FURNISHINGS                                                 |         |                                                                        |          |            |                        |           |           |             |          |
| PROC. REF: GENERIC NO REF, CMM 25-60-05PROC. REF: GENERIC NO REF, CMM 25-60-05 |         |                                                                        |          |            |                        |           |           |             |          |
|                                                                                |         |                                                                        |          |            |                        |           |           |             |          |
| 256081 U                                                                       |         | PYROTECHNIC SIGNALING FLARE GUN KIT                                    |          |            |                        |           |           | Component   | ATA:25   |
| PN:PN                                                                          | MOS/MSC | 09-Mar-01                                                              | O/C      | TSN 0      | CUSTOMER CODE          |           |           |             |          |
| SN:UNKNOWN                                                                     | HRS     | 0                                                                      |          | TSN 0      |                        |           |           |             |          |
|                                                                                | AFL     | 0                                                                      |          | TSN 0      |                        |           |           |             |          |
|                                                                                |         |                                                                        |          |            |                        |           |           |             |          |
| 256109                                                                         |         | (ELT) EMERGENCY LOCATOR TRANSMITTER                                    |          |            |                        |           |           | Component   | ATA:25   |
| PN:453-5000                                                                    | MOS/MSC | 03-Feb-25                                                              | O/C      | TSN 122    |                        |           |           |             |          |
| SN:210-05727                                                                   | HRS     | 9605.4                                                                 |          | TSN 2171.2 |                        |           |           |             |          |
|                                                                                | AFL     | 7333                                                                   |          | TSN 1646   |                        |           |           |             |          |
| PROC. REF: AMM 25-62-01PROC. REF: AMM 25-62-01                                 |         |                                                                        |          |            |                        |           |           |             |          |
|                                                                                |         |                                                                        |          |            |                        |           |           |             |          |
| 256109A                                                                        |         | FUNCTIONAL TEST (ELT) EMERGENCY LOCATOR TRANSMITTER                    |          |            |                        |           |           | Service     | ATA:25   |
| PN:453-5000                                                                    | MOS     | 03-Feb-25                                                              | 12       |            | 03-Feb-26              |           | 307 d     |             |          |
| SN:210-05727                                                                   | HRS     | 9605.4                                                                 |          |            |                        |           |           |             |          |
|                                                                                | AFL     | 7333                                                                   |          |            |                        |           |           |             |          |
| PROC. REF: AMM 25-62-00, FAR FAR 91.207PROC. REF: AMM 25-62-00, FAR FAR 91.207 |         |                                                                        |          |            |                        |           |           |             |          |
|                                                                                |         |                                                                        |          |            |                        |           |           |             |          |
| 256109B                                                                        |         | INSPECT ELT BATTERIES (IF INSTALLED)                                   |          |            |                        |           |           | Service     | ATA:25   |
| PN:453-5000                                                                    | MOS     | 03-Feb-25                                                              | 12       |            | 03-Feb-26              |           | 307 d     |             |          |
| SN:210-05727                                                                   | HRS     | 9605.4                                                                 |          |            |                        |           |           |             |          |
|                                                                                | AFL     | 7333                                                                   |          |            |                        |           |           |             |          |
| PROC. REF: AMM 25-62-00, FAR FAR 91.207PROC. REF: AMM 25-62-00, FAR FAR 91.207 |         |                                                                        |          |            |                        |           |           |             |          |
|                                                                                |         |                                                                        |          |            |                        |           |           |             |          |
| 256109C                                                                        |         | REPLACE (ELT) EMERGENCY LOCATOR TRANSMITTER ELT BATTERY                |          |            |                        |           |           | Service     | ATA:25   |
| PN:453-5000                                                                    | MOS     | 03-Feb-25                                                              | 72       |            | 03-Feb-31              |           | 2133 d    |             |          |
| SN:210-05727                                                                   | HRS     | 9605.4                                                                 |          |            |                        |           |           |             |          |
|                                                                                | AFL     | 7333                                                                   |          |            |                        |           |           |             |          |
| PROC. REF: AMM 25-62-01, FAR FAR 91.207PROC. REF: AMM 25-62-01, FAR FAR 91.207 |         |                                                                        |          |            |                        |           |           |             |          |
|                                                                                |         |                                                                        |          |            |                        |           |           |             |          |
| 256110                                                                         |         | EMERGENCY LOCATOR TRANSMITTER (ELT)/NAVIGATION INTERFACE UNIT (C406-2) |          |            |                        |           |           | Component   | ATA:25   |
| PN:PN                                                                          | MOS/MSC | 09-Mar-01                                                              | O/C      | TSN 0      |                        |           |           |             |          |
| SN:UNKNOWN                                                                     | HRS     | 0                                                                      |          | TSN 0      |                        |           |           |             |          |
|                                                                                | AFL     | 0                                                                      |          | TSN 0      |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                             |         |                                                                        |          |            |                        |           |           |             |          |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C/W   (M)-Manual Due   U-User Task   Ex-Excluded Task

| PN & SN                                            | Unit                                                    | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------|---------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 25 - EQUIPMENT/FURNISHINGS                     |                                                         |           |          |          |                        |           |           |             |                  |
| 256115                                             | EMERGENCY LOCATOR TRANSMITTER (ELT) ANTENNA             |           |          |          |                        |           |           |             | Component ATA:25 |
| PN:PN                                              | MOS/MSC                                                 | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 25-62-03PROC. REF: AMM 25-62-03     |                                                         |           |          |          |                        |           |           |             |                  |
| 256116                                             | EMERGENCY LOCATOR TRANSMITTER (ELT) REMOTE SWITCH       |           |          |          |                        |           |           |             | Component ATA:25 |
| PN:PN                                              | MOS/MSC                                                 | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 25-62-04PROC. REF: AMM 25-62-04     |                                                         |           |          |          |                        |           |           |             |                  |
| 258001                                             | CABIN AIRSHOW DISPLAY COMPUTER UNIT                     |           |          |          |                        |           |           |             | Component ATA:25 |
| PN:PN                                              | MOS/MSC                                                 | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                         |           |          |          |                        |           |           |             |                  |
| 259072                                             | AUTOMATIC ELECTRONIC DEFIBRILLATOR (AED)                |           |          |          |                        |           |           |             | Component ATA:25 |
| PN:PN                                              | MOS/MSC                                                 | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM NO REFPROC. REF: AMM NO REF         |                                                         |           |          |          |                        |           |           |             |                  |
| 259073                                             | AUTOMATIC ELECTRONIC DEFIBRILLATOR (AED) BATTERIES      |           |          |          |                        |           |           |             | Component ATA:25 |
| PN:PN                                              | MOS/MSC                                                 | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                         |           |          |          |                        |           |           |             |                  |
| 259074                                             | AUTOMATIC ELECTRONIC DEFIBRILLATOR (AED) ELECTRODE PADS |           |          |          |                        |           |           |             | Component ATA:25 |
| PN:PN                                              | MOS/MSC                                                 | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                         |           |          |          |                        |           |           |             |                  |

# Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 9669.1
AFL: 7372
As Of: 01-Apr-2025
02-Apr-2025 02:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|---------|------|-----|----------|----------|------------------------|-----------|-----------|-------------|----------|
|---------|------|-----|----------|----------|------------------------|-----------|-----------|-------------|----------|

## ATA 25 - EQUIPMENT/FURNISHINGS

|                                                |              |                                                                     |     |  |  |  |  |         |        |
|------------------------------------------------|--------------|---------------------------------------------------------------------|-----|--|--|--|--|---------|--------|
| Y2510000                                       | <sup>S</sup> | GLARESHIELD, HEADLINER, AND TRIM STRIPS - PERFORM VISUAL INSPECTION |     |  |  |  |  | Service | ATA:25 |
|                                                | MOS          | 02-Aug-24                                                           | 12  |  |  |  |  |         |        |
|                                                | HRS          | 9525.7                                                              | 300 |  |  |  |  |         |        |
|                                                | AFL          | 7276                                                                |     |  |  |  |  |         |        |
| PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00 |              |                                                                     |     |  |  |  |  |         | PKG:1  |

|                                                |              |                                                       |     |  |  |  |  |         |        |
|------------------------------------------------|--------------|-------------------------------------------------------|-----|--|--|--|--|---------|--------|
| Y2510001                                       | <sup>S</sup> | CREW SEATS AND SEAT BELTS - PERFORM VISUAL INSPECTION |     |  |  |  |  | Service | ATA:25 |
|                                                | MOS          | 02-Aug-24                                             | 12  |  |  |  |  |         |        |
|                                                | HRS          | 9525.7                                                | 300 |  |  |  |  |         |        |
|                                                | AFL          | 7276                                                  |     |  |  |  |  |         |        |
| PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00 |              |                                                       |     |  |  |  |  |         | PKG:1  |

|                                                |              |                                                                                                                                                                                                           |     |  |  |  |  |         |        |
|------------------------------------------------|--------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|--|--|--|--|---------|--------|
| Y2520000                                       | <sup>S</sup> | CABIN - PERFORM VISUAL INSPECTION OF THE FOLLOWING: A. CABIN SEATS AND SEAT BELTS. ENSURE THAT THE SEATS FUNCTION CORRECTLY AND LOCK IN PLACE. B. STOWAGE CABINETS. C. HEADLINER. D. SIDE PANELS. E. RUG. |     |  |  |  |  | Service | ATA:25 |
|                                                | MOS          | 02-Aug-24                                                                                                                                                                                                 | 12  |  |  |  |  |         |        |
|                                                | HRS          | 9525.7                                                                                                                                                                                                    | 300 |  |  |  |  |         |        |
|                                                | AFL          | 7276                                                                                                                                                                                                      |     |  |  |  |  |         |        |
| PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00 |              |                                                                                                                                                                                                           |     |  |  |  |  |         | PKG:1  |

|                                                    |              |                                                                                                                                                        |     |  |  |  |  |         |        |
|----------------------------------------------------|--------------|--------------------------------------------------------------------------------------------------------------------------------------------------------|-----|--|--|--|--|---------|--------|
| Y2540000                                           | <sup>S</sup> | ALL LAVATORY PAPER AND LINEN WASTE RECEPTACLE ACCESS DOORS AND DISPOSAL DOORS FOR PROPER OPERATION, FIT, SEALING, LATCHING, AND LEGIBILITY OF PLACARD. |     |  |  |  |  | Service | ATA:25 |
|                                                    | MOS          | 02-Aug-24                                                                                                                                              | 24  |  |  |  |  |         |        |
|                                                    | HRS          | 9525.7                                                                                                                                                 | 600 |  |  |  |  |         |        |
|                                                    | AFL          | 7276                                                                                                                                                   |     |  |  |  |  |         |        |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |              |                                                                                                                                                        |     |  |  |  |  |         | PKG:7  |

## ATA 26 - FIRE PROTECTION

|            |              |                                          |     |       |  |  |  |           |        |
|------------|--------------|------------------------------------------|-----|-------|--|--|--|-----------|--------|
| 261010     | <sup>U</sup> | LEFT SENSING, ENGINE HOT SECTION ELEMENT |     |       |  |  |  | Component | ATA:26 |
| PN:PN      | MOS/MSC      | 09-Mar-01                                | O/C | TSN 0 |  |  |  |           |        |
| SN:UNKNOWN | HRS          | 0                                        |     | TSN 0 |  |  |  |           |        |
|            | AFL          | 0                                        |     | TSN 0 |  |  |  |           |        |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C/W   (M)-Manual Due   U-User Task   Ex-Excluded Task

| PN & SN | Unit | C / W | Interval | TSX / Adj. | Next Due (ENG / APU) A / C | Max Limit | Remaining | Disposition | Warranty |
|---------|------|-------|----------|------------|----------------------------|-----------|-----------|-------------|----------|
|---------|------|-------|----------|------------|----------------------------|-----------|-----------|-------------|----------|

ATA 26 - FIRE PROTECTION

|            |         |                                           |     |       |  |  |  |           |        |
|------------|---------|-------------------------------------------|-----|-------|--|--|--|-----------|--------|
| 261011     | U       | RIGHT SENSING, ENGINE HOT SECTION ELEMENT |     |       |  |  |  | Component | ATA:26 |
| PN:PN      | MOS/MSC | 09-Mar-01                                 | O/C | TSN 0 |  |  |  |           |        |
| SN:UNKNOWN | HRS     | 0                                         |     | TSN 0 |  |  |  |           |        |
|            | AFL     | 0                                         |     | TSN 0 |  |  |  |           |        |

|                                                |         |                                           |     |       |  |  |  |           |        |
|------------------------------------------------|---------|-------------------------------------------|-----|-------|--|--|--|-----------|--------|
| 261012                                         |         | NO. 1 ENGINE FIREWALL FIRE DETECT ELEMENT |     |       |  |  |  | Component | ATA:26 |
| PN:PN                                          | MOS/MSC | 09-Mar-01                                 | O/C | TSN 0 |  |  |  |           |        |
| SN:UNKNOWN                                     | HRS     | 0                                         |     | TSN 0 |  |  |  |           |        |
|                                                | AFL     | 0                                         |     | TSN 0 |  |  |  |           |        |
| PROC. REF: AMM 26-11-02PROC. REF: AMM 26-11-02 |         |                                           |     |       |  |  |  |           |        |

|                                                |         |                                           |     |       |  |  |  |           |        |
|------------------------------------------------|---------|-------------------------------------------|-----|-------|--|--|--|-----------|--------|
| 261013                                         |         | NO. 2 ENGINE FIREWALL FIRE DETECT ELEMENT |     |       |  |  |  | Component | ATA:26 |
| PN:PN                                          | MOS/MSC | 09-Mar-01                                 | O/C | TSN 0 |  |  |  |           |        |
| SN:UNKNOWN                                     | HRS     | 0                                         |     | TSN 0 |  |  |  |           |        |
|                                                | AFL     | 0                                         |     | TSN 0 |  |  |  |           |        |
| PROC. REF: AMM 26-11-02PROC. REF: AMM 26-11-02 |         |                                           |     |       |  |  |  |           |        |

|                                                |         |                                                    |     |       |  |  |  |           |        |
|------------------------------------------------|---------|----------------------------------------------------|-----|-------|--|--|--|-----------|--------|
| 261014                                         |         | NO. 1 ENGINE ACCESSORY GEARBOX FIRE DETECT ELEMENT |     |       |  |  |  | Component | ATA:26 |
| PN:PN                                          | MOS/MSC | 09-Mar-01                                          | O/C | TSN 0 |  |  |  |           |        |
| SN:UNKNOWN                                     | HRS     | 0                                                  |     | TSN 0 |  |  |  |           |        |
|                                                | AFL     | 0                                                  |     | TSN 0 |  |  |  |           |        |
| PROC. REF: AMM 26-11-02PROC. REF: AMM 26-11-02 |         |                                                    |     |       |  |  |  |           |        |

|                                                |         |                                                    |     |       |  |  |  |           |        |
|------------------------------------------------|---------|----------------------------------------------------|-----|-------|--|--|--|-----------|--------|
| 261015                                         |         | NO. 2 ENGINE ACCESSORY GEARBOX FIRE DETECT ELEMENT |     |       |  |  |  | Component | ATA:26 |
| PN:PN                                          | MOS/MSC | 09-Mar-01                                          | O/C | TSN 0 |  |  |  |           |        |
| SN:UNKNOWN                                     | HRS     | 0                                                  |     | TSN 0 |  |  |  |           |        |
|                                                | AFL     | 0                                                  |     | TSN 0 |  |  |  |           |        |
| PROC. REF: AMM 26-11-02PROC. REF: AMM 26-11-02 |         |                                                    |     |       |  |  |  |           |        |

|                                                |         |                                              |     |       |  |  |  |           |        |
|------------------------------------------------|---------|----------------------------------------------|-----|-------|--|--|--|-----------|--------|
| 261016                                         |         | NO. 1 ENGINE HOT SECTION FIRE DETECT ELEMENT |     |       |  |  |  | Component | ATA:26 |
| PN:PN                                          | MOS/MSC | 09-Mar-01                                    | O/C | TSN 0 |  |  |  |           |        |
| SN:UNKNOWN                                     | HRS     | 0                                            |     | TSN 0 |  |  |  |           |        |
|                                                | AFL     | 0                                            |     | TSN 0 |  |  |  |           |        |
| PROC. REF: AMM 26-11-02PROC. REF: AMM 26-11-02 |         |                                              |     |       |  |  |  |           |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9669.1
 AFL: 7372
 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                        | Unit                                         | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|------------------------------------------------|----------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 26 - FIRE PROTECTION                       |                                              |           |          |          |                        |           |           |             |                  |
| 261017                                         | NO. 2 ENGINE HOT SECTION FIRE DETECT ELEMENT |           |          |          |                        |           |           |             | Component ATA:26 |
| PN:744-12135                                   | MOS/MSC                                      | 12-Aug-15 | O/C      |          |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                          | 7535.1    |          |          |                        |           |           |             |                  |
|                                                | AFL                                          | 5764      |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 26-11-02PROC. REF: AMM 26-11-02 |                                              |           |          |          |                        |           |           |             |                  |
| 261057                                         | NO. 1 FIRE DETECT CONTROL UNIT               |           |          |          |                        |           |           |             | Component ATA:26 |
| PN:PN                                          | MOS/MSC                                      | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 26-11-01PROC. REF: AMM 26-11-01 |                                              |           |          |          |                        |           |           |             |                  |
| 261058                                         | NO. 2 FIRE DETECT CONTROL UNIT               |           |          |          |                        |           |           |             | Component ATA:26 |
| PN:PN                                          | MOS/MSC                                      | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 26-11-01PROC. REF: AMM 26-11-01 |                                              |           |          |          |                        |           |           |             |                  |
| 261069                                         | NO. 1 BLEED AIR LEAK DETECTION UNIT          |           |          |          |                        |           |           |             | Component ATA:26 |
| PN:PN                                          | MOS/MSC                                      | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 26-12-01PROC. REF: AMM 26-12-01 |                                              |           |          |          |                        |           |           |             |                  |
| 261070                                         | NO. 2 BLEED AIR LEAK DETECTION UNIT          |           |          |          |                        |           |           |             | Component ATA:26 |
| PN:6626100000-003                              | MOS/MSC                                      | 18-Apr-12 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:2714                                        | HRS                                          | 6879.9    |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                          | 5240      |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 26-12-01PROC. REF: AMM 26-12-01 |                                              |           |          |          |                        |           |           |             |                  |
| 261071                                         | ANTI-ICE BLEED AIR LEAK DETECTION UNIT       |           |          |          |                        |           |           |             | Component ATA:26 |
| PN:PN                                          | MOS/MSC                                      | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 26-12-01PROC. REF: AMM 26-12-01 |                                              |           |          |          |                        |           |           |             |                  |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C/W   (M)-Manual Due   U-User Task   Ex-Excluded Task



Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                            | Unit    | C / W                                                                    | Interval | TSX / Adj. | Next Due (ENG / APU) A / C | Max Limit | Remaining | Disposition                               | Warranty |
|----------------------------------------------------|---------|--------------------------------------------------------------------------|----------|------------|----------------------------|-----------|-----------|-------------------------------------------|----------|
| ATA 26 - FIRE PROTECTION                           |         |                                                                          |          |            |                            |           |           |                                           |          |
| 261075                                             |         | APU FIRE/OVERHEAT DETECTOR                                               |          |            |                            |           |           | Component                                 | ATA:26   |
| PN:PN                                              | MOS/MSC | 09-Mar-01                                                                | O/C      | TSN 0      |                            |           |           |                                           |          |
| SN:UNKNOWN                                         | HRS     | 0                                                                        |          | TSN 0      |                            |           |           |                                           |          |
|                                                    | AFL     | 0                                                                        |          | TSN 0      |                            |           |           |                                           |          |
| PROC. REF: AMM 26-13-01PROC. REF: AMM 26-13-01     |         |                                                                          |          |            |                            |           |           |                                           |          |
| 262001                                             |         | NO. 1/LEFT/LOWER FIRE EXTINGUISHER BOTTLE                                |          |            |                            |           |           | Component                                 | ATA:26   |
| PN:33100021-1                                      | MOS/MSC | 22-Jun-23                                                                | O/C      | TSO 0      |                            |           |           |                                           |          |
| SN:59578B1                                         | HRS     | 9258.5                                                                   |          | TSO 0      |                            |           |           |                                           |          |
|                                                    | AFL     | 7100                                                                     |          | TSO 0      |                            |           |           |                                           |          |
| PROC. REF: AMM 26-21-01PROC. REF: AMM 26-21-01     |         |                                                                          |          |            |                            |           |           |                                           |          |
| 262001A                                            |         | NO. 1/LEFT/LOWER FIRE EXTINGUISHER BOTTLE - HYDROSTATIC TEST (Q2620006)  |          |            |                            |           |           | Service                                   | ATA:26   |
| PN:33100021-1                                      | MOS     | 31-May-23                                                                | 60       |            | 31-May-28                  |           | 1155 d    | SCHEDULED MAINTENANCE TASKS AND INTERVALS |          |
| SN:59578B1                                         | HRS     |                                                                          |          |            |                            |           |           |                                           |          |
|                                                    | AFL     |                                                                          |          |            |                            |           |           |                                           |          |
| HydroCheck Date: : 31-May-23                       |         |                                                                          |          |            |                            |           |           |                                           |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |         |                                                                          |          |            |                            |           |           |                                           |          |
| 262002                                             |         | NO. 2/RIGHT/UPPER FIRE EXTINGUISHER BOTTLE                               |          |            |                            |           |           | Component                                 | ATA:26   |
| PN:33100021-1                                      | MOS/MSC | 25-Nov-20                                                                | O/C      | TSO 0      |                            |           |           |                                           |          |
| SN:72871B1                                         | HRS     | 8301.3                                                                   |          | TSO 0      |                            |           |           |                                           |          |
|                                                    | AFL     | 6392                                                                     |          | TSO 0      |                            |           |           |                                           |          |
| PROC. REF: AMM 26-21-01PROC. REF: AMM 26-21-01     |         |                                                                          |          |            |                            |           |           |                                           |          |
| 262002A                                            |         | NO. 2/RIGHT/UPPER FIRE EXTINGUISHER BOTTLE - HYDROSTATIC TEST (Q2620006) |          |            |                            |           |           | Service                                   | ATA:26   |
| PN:33100021-1                                      | MOS     | 31-Oct-20                                                                | 60       |            | 31-Oct-25                  |           | 212 d     |                                           |          |
| SN:72871B1                                         | HRS     |                                                                          |          |            |                            |           |           |                                           |          |
|                                                    | AFL     |                                                                          |          |            |                            |           |           |                                           |          |
| HydroCheck Date: : 31-Oct-20                       |         |                                                                          |          |            |                            |           |           |                                           |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |         |                                                                          |          |            |                            |           |           |                                           |          |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C/W   (M)-Manual Due   U-User Task   Ex-Excluded Task

# Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                      | Unit | C/W                                                                                            | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|------------------------------|------|------------------------------------------------------------------------------------------------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 26 - FIRE PROTECTION     |      |                                                                                                |          |          |                        |           |           |             |          |
| 262013 <sup>U</sup>          |      | LEFT NO. 1 ENGINE FIRE EXTINGUISHER SQUIB                                                      |          |          |                        |           |           | Component   | ATA:26   |
| PN:M30903856                 | MOS  | 06-Dec-18                                                                                      | 180      |          | 01-Jul-33              |           | 3012 d    | LIFE LIMIT  |          |
| SN:02254                     | HRS  | 7976.3                                                                                         |          | TSN 0    |                        |           |           |             |          |
|                              | AFL  | 6133                                                                                           |          | TSN 0    |                        |           |           |             |          |
| Manufacture Date:: 01-Jul-18 |      |                                                                                                |          |          |                        |           |           |             |          |
| 262013A <sup>U</sup>         |      | REPLACE LEFT NO. 1 ENGINE FIRE EXTINGUISHER SQUIB (SERVICE LIFE IRN # D2620007 AND D2620008).  |          |          |                        |           |           | Service     | ATA:26   |
| PN:M30903856                 | MOS  | 06-Dec-18                                                                                      | 120      |          | 06-Dec-28              |           | 1344 d    | LIFE LIMIT  |          |
| SN:02254                     | HRS  | 7976.3                                                                                         |          |          |                        |           |           |             |          |
|                              | AFL  | 6133                                                                                           |          |          |                        |           |           |             |          |
| 262014 <sup>U</sup>          |      | RIGHT NO. 1 ENGINE FIRE EXTINGUISHER SQUIB                                                     |          |          |                        |           |           | Component   | ATA:26   |
| PN:M30903859                 | MOS  | 06-Dec-18                                                                                      | 180      |          | 01-Jul-33              |           | 3012 d    | LIFE LIMIT  |          |
| SN:01619                     | HRS  | 7976.3                                                                                         |          | TSN 0    |                        |           |           |             |          |
|                              | AFL  | 6133                                                                                           |          | TSN 0    |                        |           |           |             |          |
| Manufacture Date:: 01-Jul-18 |      |                                                                                                |          |          |                        |           |           |             |          |
| 262014A <sup>U</sup>         |      | REPLACE RIGHT NO. 1 ENGINE FIRE EXTINGUISHER SQUIB (SERVICE LIFE IRN # D2620007 AND D2620008). |          |          |                        |           |           | Service     | ATA:26   |
| PN:M30903859                 | MOS  | 06-Dec-18                                                                                      | 120      |          | 06-Dec-28              |           | 1344 d    | LIFE LIMIT  |          |
| SN:01619                     | HRS  | 7976.3                                                                                         |          |          |                        |           |           |             |          |
|                              | AFL  | 6133                                                                                           |          |          |                        |           |           |             |          |
| 262015 <sup>U</sup>          |      | LEFT NO. 2 ENGINE FIRE EXTINGUISHER SQUIB                                                      |          |          |                        |           |           | Component   | ATA:26   |
| PN:30903856                  | MOS  | 25-Nov-20                                                                                      | 180      |          | 30-Nov-30              |           | 2068 d    | LIFE LIMIT  |          |
| SN:1814TC                    | HRS  | 8301.3                                                                                         |          |          |                        |           |           |             |          |
|                              | AFL  | 6392                                                                                           |          |          |                        |           |           |             |          |
| Manufacture Date:: 30-Nov-15 |      |                                                                                                |          |          |                        |           |           |             |          |
| 262015A <sup>U</sup>         |      | REPLACE LEFT NO. 2 ENGINE FIRE EXTINGUISHER SQUIB (SERVICE LIFE IRN # D2620007 AND D2620008).  |          |          |                        |           |           | Service     | ATA:26   |
| PN:30903856                  | MOS  | 18-Jan-19                                                                                      | 120      |          | 18-Jan-29              |           | 1387 d    | LIFE LIMIT  |          |
| SN:1814TC                    | HRS  |                                                                                                |          |          |                        |           |           |             |          |
|                              | AFL  |                                                                                                |          |          |                        |           |           |             |          |
| Manufacture Date:: 18-Jan-19 |      |                                                                                                |          |          |                        |           |           |             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                            | Unit    | C/W                                                                                            | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty |
|----------------------------------------------------|---------|------------------------------------------------------------------------------------------------|----------|----------|------------------------|-----------|-----------|---------------|----------|
| ATA 26 - FIRE PROTECTION                           |         |                                                                                                |          |          |                        |           |           |               |          |
|                                                    |         |                                                                                                |          |          |                        |           |           |               |          |
| 262016 <sup>U</sup>                                |         | RIGHT NO. 2 ENGINE FIRE EXTINGUISHER SQUIB                                                     |          |          |                        |           |           | Component     | ATA:26   |
| PN:30903859                                        | MOS     | 25-Nov-20                                                                                      | 180      |          | 30-Nov-30              |           | 2068 d    | LIFE LIMIT    |          |
| SN:1119TE                                          | HRS     | 8301.3                                                                                         |          |          |                        |           |           |               |          |
|                                                    | AFL     | 6392                                                                                           |          |          |                        |           |           |               |          |
| Manufacture Date:: 30-Nov-15                       |         |                                                                                                |          |          |                        |           |           |               |          |
|                                                    |         |                                                                                                |          |          |                        |           |           |               |          |
| 262016A <sup>U</sup>                               |         | REPLACE RIGHT NO. 2 ENGINE FIRE EXTINGUISHER SQUIB (SERVICE LIFE IRN # D2620007 AND D2620008). |          |          |                        |           |           | Service       | ATA:26   |
| PN:30903859                                        | MOS     | 07-Nov-18                                                                                      | 120      |          | 07-Nov-28              |           | 1315 d    | LIFE LIMIT    |          |
| SN:1119TE                                          | HRS     |                                                                                                |          |          |                        |           |           |               |          |
|                                                    | AFL     |                                                                                                |          |          |                        |           |           |               |          |
| Manufacture Date:: 07-Nov-18                       |         |                                                                                                |          |          |                        |           |           |               |          |
|                                                    |         |                                                                                                |          |          |                        |           |           |               |          |
| 262040                                             |         | APU FIRE WARNING HORN                                                                          |          |          |                        |           |           | Component     | ATA:26   |
| PN:PN                                              | MOS/MSC | 09-Mar-01                                                                                      | O/C      | TSN 0    |                        |           |           |               |          |
| SN:UNKNOWN                                         | HRS     | 0                                                                                              |          | TSN 0    |                        |           |           |               |          |
|                                                    | AFL     | 0                                                                                              |          | TSN 0    |                        |           |           |               |          |
| PROC. REF: AMM 26-13-02PROC. REF: AMM 26-13-02     |         |                                                                                                |          |          |                        |           |           |               |          |
|                                                    |         |                                                                                                |          |          |                        |           |           |               |          |
| 262041                                             |         | PILOT PORTABLE FIRE EXTINGUISHER                                                               |          |          |                        |           |           | Component     | ATA:26   |
| PN:A344T                                           | MOS/MSC | 07-Dec-12                                                                                      | O/C      |          |                        |           |           |               |          |
| SN:UNKNOWN                                         | HRS     | 7016.8                                                                                         |          |          |                        |           |           |               |          |
|                                                    | AFL     | 5361                                                                                           |          |          |                        |           |           |               |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |         |                                                                                                |          |          |                        |           |           |               |          |
|                                                    |         |                                                                                                |          |          |                        |           |           |               |          |
| 262041D <sup>U</sup>                               |         | INSPECT PILOT PORTABLE FIRE EXTINGUISHER                                                       |          |          |                        |           |           | Service       | ATA:26   |
|                                                    | DAYS    | 24-Mar-25                                                                                      | 30       |          | 23-Apr-25              |           | 21 d      | CUSTOMER CODE |          |
|                                                    | HRS     | 9666.9                                                                                         |          |          |                        |           |           |               |          |
|                                                    | AFL     | 7370                                                                                           |          |          |                        |           |           |               |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                            | Unit                                                                                                                       | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty |
|----------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|---------------|----------|
| ATA 26 - FIRE PROTECTION                           |                                                                                                                            |           |          |          |                        |           |           |               |          |
| 262042                                             | COPILOT PORTABLE FIRE EXTINGUISHER                                                                                         |           |          |          |                        |           |           | Component     | ATA:26   |
| PN:A344                                            | MOS/MSC                                                                                                                    | 18-May-16 | O/C      | TSN 0    |                        |           |           |               |          |
| SN:B10813738                                       | HRS                                                                                                                        | 7623.3    |          | TSN 0    |                        |           |           |               |          |
|                                                    | AFL                                                                                                                        | 5813      |          | TSN 0    |                        |           |           |               |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                                                                            |           |          |          |                        |           |           |               |          |
| 262042A <sup>S</sup>                               | VISUAL INSPECTION AND WEIGHT CHECK COPILOT PORTABLE FIRE EXTINGUISHER CO-PILOT'S PORTABLE FIRE EXTINGUISHER (IRN Y2620009) |           |          |          |                        |           |           | Service       | ATA:26   |
| PN:A344                                            | MOS                                                                                                                        | 02-Aug-24 | 12       |          |                        |           |           |               |          |
| SN:B10813738                                       | HRS                                                                                                                        | 9525.7    | 300      |          |                        |           |           |               |          |
|                                                    | AFL                                                                                                                        | 7276      |          |          |                        |           |           |               |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                                                                            |           |          |          |                        |           |           |               |          |
| 262042B                                            | HYDROSTATIC TEST COPILOT PORTABLE FIRE EXTINGUISHER (IRN # Q2510003).                                                      |           |          |          |                        |           |           | Service       | ATA:26   |
| PN:A344                                            | MOS                                                                                                                        | 01-Feb-16 | 144      |          | 01-Feb-28              |           | 1035 d    |               |          |
| SN:B10813738                                       | HRS                                                                                                                        |           |          |          |                        |           |           |               |          |
|                                                    | AFL                                                                                                                        |           |          |          |                        |           |           |               |          |
| HydroCheck Date: : 01-Feb-16                       |                                                                                                                            |           |          |          |                        |           |           |               |          |
| PROC. REF: AMM 26-23-00PROC. REF: AMM 26-23-00     |                                                                                                                            |           |          |          |                        |           |           |               |          |
| 262042D <sup>U</sup>                               | INSPECT COPILOT PORTABLE FIRE EXTINGUISHER                                                                                 |           |          |          |                        |           |           | Service       | ATA:26   |
|                                                    | DAYS                                                                                                                       | 24-Mar-25 | 30       |          | 23-Apr-25              |           | 21 d      | CUSTOMER CODE |          |
|                                                    | HRS                                                                                                                        | 9666.9    |          |          |                        |           |           |               |          |
|                                                    | AFL                                                                                                                        | 7370      |          |          |                        |           |           |               |          |
| 262051                                             | CABIN PORTABLE FIRE EXTINGUISHER                                                                                           |           |          |          |                        |           |           | Component     | ATA:26   |
| PN:C352                                            | MOS/MSC                                                                                                                    | 28-Dec-22 | O/C      | TSN 0    |                        |           |           |               |          |
| SN:H-20651164                                      | HRS                                                                                                                        | 9186.7    |          | TSN 0    |                        |           |           |               |          |
|                                                    | AFL                                                                                                                        | 7047      |          | TSN 0    |                        |           |           |               |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                                                                            |           |          |          |                        |           |           |               |          |
| 262051D <sup>U</sup>                               | INSPECT CABIN PORTABLE FIRE EXTINGUISHER                                                                                   |           |          |          |                        |           |           | Service       | ATA:26   |
|                                                    | DAYS                                                                                                                       | 24-Mar-25 | 30       |          | 23-Apr-25              |           | 21 d      | CUSTOMER CODE |          |
|                                                    | HRS                                                                                                                        | 9666.9    |          |          |                        |           |           |               |          |
|                                                    | AFL                                                                                                                        | 7370      |          |          |                        |           |           |               |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                        | Unit                                                                                                                                                                                                                                               | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 26 - FIRE PROTECTION                       |                                                                                                                                                                                                                                                    |           |          |          |                        |           |           |             |          |
| 5-19-00-O2610001-LEFT                          | VISUALLY INSPECT NO. 1 ENGINE HOT SECTION FIRE DETECTOR ELEMENT. (ZONE/ACCESS 410 IRN O2610001) DURING MAJOR ENGINE INSPECTION/UNSCHEDULED ENGINE CHANGE                                                                                           |           |          |          |                        |           |           | Service     | ATA:26   |
|                                                | MOS                                                                                                                                                                                                                                                | 21-May-18 |          |          |                        |           |           |             |          |
|                                                | HRS                                                                                                                                                                                                                                                | 7855.7    | 3000     | Adj 1.5  | 10857.2                |           | 1188.1    |             |          |
|                                                | AFL                                                                                                                                                                                                                                                | 6028      |          |          |                        |           |           |             |          |
| PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00 |                                                                                                                                                                                                                                                    |           |          |          |                        |           |           |             |          |
| 5-19-00-O2610001-RIGHT                         | VISUALLY INSPECT NO. 2 ENGINE HOT SECTION FIRE DETECTOR ELEMENT. (ZONE/ACCESS 410 IRN O2610001) DURING MAJOR ENGINE INSPECTION/UNSCHEDULED ENGINE CHANGE                                                                                           |           |          |          |                        |           |           | Service     | ATA:26   |
|                                                | MOS                                                                                                                                                                                                                                                | 12-Aug-15 |          |          |                        |           |           |             |          |
|                                                | HRS                                                                                                                                                                                                                                                | 7535.1    | 3000     | Adj 78.9 | 10614                  |           | 944.9     |             |          |
|                                                | AFL                                                                                                                                                                                                                                                | 5764      |          |          |                        |           |           |             |          |
| PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00 |                                                                                                                                                                                                                                                    |           |          |          |                        |           |           |             |          |
| Y2610000 <sup>S</sup>                          | FIREWALL AND ACCESSORY COMPARTMENT FIRE DETECTOR ELEMENTS - PERFORM VISUAL INSPECTION                                                                                                                                                              |           |          |          |                        |           |           | Service     | ATA:26   |
|                                                | MOS                                                                                                                                                                                                                                                | 02-Aug-24 | 24       |          |                        |           |           |             |          |
|                                                | HRS                                                                                                                                                                                                                                                | 9525.7    | 600      |          |                        |           |           |             |          |
|                                                | AFL                                                                                                                                                                                                                                                | 7276      |          |          |                        |           |           |             |          |
| PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00 |                                                                                                                                                                                                                                                    |           |          |          |                        |           |           |             |          |
| Y2620002 <sup>S</sup>                          | ENGINE FIRE EXTINGUISHER CONTAINERS - PERFORM VISUAL INSPECTION. CHECK CONTAINERS FOR CONDITION,CARTRIDGES AND CARTRIDGE WIRING FOR SECURITY AND CONDITION, CONTAINER PRESSURE GAUGE FOR PROPER PRESSURES, AND PLUMBING FOR SECURITY AND CONDITION |           |          |          |                        |           |           | Service     | ATA:26   |
|                                                | MOS                                                                                                                                                                                                                                                | 02-Aug-24 | 12       |          |                        |           |           |             |          |
|                                                | HRS                                                                                                                                                                                                                                                | 9525.7    | 300      |          |                        |           |           |             |          |
|                                                | AFL                                                                                                                                                                                                                                                | 7276      |          |          |                        |           |           |             |          |
| PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00 |                                                                                                                                                                                                                                                    |           |          |          |                        |           |           |             |          |
| Y2620005 <sup>S</sup>                          | PERFORM ENGINE FIRE EXTINGUISHING SYSTEM - OPERATIONAL CHECK                                                                                                                                                                                       |           |          |          |                        |           |           | Service     | ATA:26   |
|                                                | MOS                                                                                                                                                                                                                                                | 25-Nov-19 | 96       |          |                        |           |           |             |          |
|                                                | HRS                                                                                                                                                                                                                                                | 8177.7    | 2400     |          |                        |           |           |             |          |
|                                                | AFL                                                                                                                                                                                                                                                | 6303      |          |          |                        |           |           |             |          |
| PROC. REF: AMM 26-21-00PROC. REF: AMM 26-21-00 |                                                                                                                                                                                                                                                    |           |          |          |                        |           |           |             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN | Unit | C / W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|---------|------|-------|----------|----------|------------------------|-----------|-----------|-------------|----------|
|---------|------|-------|----------|----------|------------------------|-----------|-----------|-------------|----------|

ATA 26 - FIRE PROTECTION

|                                                    |              |                                                                                                                                                                                    |     |  |  |  |  |         |        |
|----------------------------------------------------|--------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|--|--|--|--|---------|--------|
| Y2620009                                           | <sup>S</sup> | INSPECT PORTABLE HAND HELD FIRE EXTINGUISHERS FOR CONDITION AND DATE OF MANUFACTURE. CHECK OPERATING PRESSURE AND WEIGHT PER MAINTENANCE INSTRUCTIONS ON FIRE EXTINGUISHER BOTTLE. |     |  |  |  |  | Service | ATA:26 |
|                                                    | MOS          | 02-Aug-24                                                                                                                                                                          | 12  |  |  |  |  |         |        |
|                                                    | HRS          | 9525.7                                                                                                                                                                             | 300 |  |  |  |  |         |        |
|                                                    | AFL          | 7276                                                                                                                                                                               |     |  |  |  |  |         |        |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |              |                                                                                                                                                                                    |     |  |  |  |  |         | PKG:1  |

|                                                |              |                                                                                 |     |  |  |  |  |         |        |
|------------------------------------------------|--------------|---------------------------------------------------------------------------------|-----|--|--|--|--|---------|--------|
| Z2620021                                       | <sup>S</sup> | NO. 1 ENGINE FIRE EXTINGUISHER CONTAINER PLUMBING - PERFORM DETAILED INSPECTION |     |  |  |  |  | Service | ATA:26 |
|                                                | MOS          | 02-Aug-24                                                                       | 12  |  |  |  |  |         |        |
|                                                | HRS          | 9525.7                                                                          | 300 |  |  |  |  |         |        |
|                                                | AFL          | 7276                                                                            |     |  |  |  |  |         |        |
| PROC. REF: AMM 26-21-00PROC. REF: AMM 26-21-00 |              |                                                                                 |     |  |  |  |  |         | PKG:2  |

|                                                |              |                                                                                 |     |  |  |  |  |         |        |
|------------------------------------------------|--------------|---------------------------------------------------------------------------------|-----|--|--|--|--|---------|--------|
| Z2620021                                       | <sup>S</sup> | NO. 2 ENGINE FIRE EXTINGUISHER CONTAINER PLUMBING - PERFORM DETAILED INSPECTION |     |  |  |  |  | Service | ATA:26 |
|                                                | MOS          | 02-Aug-24                                                                       | 12  |  |  |  |  |         |        |
|                                                | HRS          | 9525.7                                                                          | 300 |  |  |  |  |         |        |
|                                                | AFL          | 7276                                                                            |     |  |  |  |  |         |        |
| PROC. REF: AMM 26-21-00PROC. REF: AMM 26-21-00 |              |                                                                                 |     |  |  |  |  |         | PKG:2  |

ATA 27 - FLIGHT CONTROLS

|                                                |                   |           |     |       |  |  |  |           |        |
|------------------------------------------------|-------------------|-----------|-----|-------|--|--|--|-----------|--------|
| 270301                                         | TRIM SWITCH PANEL |           |     |       |  |  |  | Component | ATA:27 |
| PN:PN                                          | MOS/MSC           | 09-Mar-01 | O/C | TSN 0 |  |  |  |           |        |
| SN:UNKNOWN                                     | HRS               | 0         |     | TSN 0 |  |  |  |           |        |
|                                                | AFL               | 0         |     | TSN 0 |  |  |  |           |        |
| PROC. REF: AMM 27-00-01PROC. REF: AMM 27-00-01 |                   |           |     |       |  |  |  |           |        |

|                                                |                                             |           |     |       |  |  |  |           |        |
|------------------------------------------------|---------------------------------------------|-----------|-----|-------|--|--|--|-----------|--------|
| 271001                                         | LEFT AILERON CONTROL SYSTEM CROSSOVER CABLE |           |     |       |  |  |  | Component | ATA:27 |
| PN:PN                                          | MOS/MSC                                     | 09-Mar-01 | O/C | TSN 0 |  |  |  |           |        |
| SN:UNKNOWN                                     | HRS                                         | 0         |     | TSN 0 |  |  |  |           |        |
|                                                | AFL                                         | 0         |     | TSN 0 |  |  |  |           |        |
| PROC. REF: AMM 27-10-05PROC. REF: AMM 27-10-05 |                                             |           |     |       |  |  |  |           |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9669.1
 AFL: 7372
 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                        | Unit                                         | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|------------------------------------------------|----------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 27 - FLIGHT CONTROLS                       |                                              |           |          |          |                        |           |           |             |                  |
| 271002                                         | RIGHT AILERON CONTROL SYSTEM CROSSOVER CABLE |           |          |          |                        |           |           |             | Component ATA:27 |
| PN:PN                                          | MOS/MSC                                      | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 27-10-05PROC. REF: AMM 27-10-05 |                                              |           |          |          |                        |           |           |             |                  |
| 271003                                         | LEFT AILERON CONTROL SYSTEM CABLE            |           |          |          |                        |           |           |             | Component ATA:27 |
| PN:PN                                          | MOS/MSC                                      | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 27-10-05PROC. REF: AMM 27-10-05 |                                              |           |          |          |                        |           |           |             |                  |
| 271004                                         | RIGHT AILERON CONTROL SYSTEM CABLE           |           |          |          |                        |           |           |             | Component ATA:27 |
| PN:PN                                          | MOS/MSC                                      | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 27-10-05PROC. REF: AMM 27-10-05 |                                              |           |          |          |                        |           |           |             |                  |
| 271005                                         | AFT AILERON CONTROL SYSTEM CABLE             |           |          |          |                        |           |           |             | Component ATA:27 |
| PN:PN                                          | MOS/MSC                                      | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 27-10-05PROC. REF: AMM 27-10-05 |                                              |           |          |          |                        |           |           |             |                  |
| 271045                                         | LEFT INBOARD AILERON CONTROL CABLE           |           |          |          |                        |           |           |             | Component ATA:27 |
| PN:PN                                          | MOS/MSC                                      | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 27-10-05PROC. REF: AMM 27-10-05 |                                              |           |          |          |                        |           |           |             |                  |
| 271046                                         | RIGHT INBOARD AILERON CONTROL CABLE          |           |          |          |                        |           |           |             | Component ATA:27 |
| PN:PN                                          | MOS/MSC                                      | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 27-10-05PROC. REF: AMM 27-10-05 |                                              |           |          |          |                        |           |           |             |                  |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C/W   (M)-Manual Due   U-User Task   Ex-Excluded Task

# Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9669.1
 AFL: 7372
 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                        | Unit                                         | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|------------------------------------------------|----------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 27 - FLIGHT CONTROLS                       |                                              |           |          |          |                        |           |           |             |                  |
| 271051                                         | LEFT FORWARD OUTBOARD AILERON CONTROL CABLE  |           |          |          |                        |           |           |             | Component ATA:27 |
| PN:PN                                          | MOS/MSC                                      | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 27-10-05PROC. REF: AMM 27-10-05 |                                              |           |          |          |                        |           |           |             |                  |
| 271052                                         | RIGHT FORWARD OUTBOARD AILERON CONTROL CABLE |           |          |          |                        |           |           |             | Component ATA:27 |
| PN:PN                                          | MOS/MSC                                      | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 27-10-05PROC. REF: AMM 27-10-05 |                                              |           |          |          |                        |           |           |             |                  |
| 271053                                         | LEFT AFT OUTBOARD AILERON CONTROL CABLE      |           |          |          |                        |           |           |             | Component ATA:27 |
| PN:PN                                          | MOS/MSC                                      | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 27-10-05PROC. REF: AMM 27-10-05 |                                              |           |          |          |                        |           |           |             |                  |
| 271054                                         | RIGHT AFT OUTBOARD AILERON CONTROL CABLE     |           |          |          |                        |           |           |             | Component ATA:27 |
| PN:PN                                          | MOS/MSC                                      | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 27-10-05PROC. REF: AMM 27-10-05 |                                              |           |          |          |                        |           |           |             |                  |
| 271083                                         | AILERON TRIM TAB ACTUATOR                    |           |          |          |                        |           |           |             | Component ATA:27 |
| PN:PN                                          | MOS/MSC                                      | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 27-10-09PROC. REF: AMM 27-10-09 |                                              |           |          |          |                        |           |           |             |                  |
| 271093 <sup>U</sup>                            | PILOT ANGLE OF ATTACK (AOA) TRANSDUCER       |           |          |          |                        |           |           |             | Component ATA:27 |
| PN:PN                                          | MOS/MSC                                      | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                          | 0         |          | TSN 0    |                        |           |           |             |                  |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C/W   (M)-Manual Due   U-User Task   Ex-Excluded Task



# Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9669.1
 AFL: 7372
 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                            | Unit    | C / W                                      | Interval | TSX / Adj. | Next Due (ENG / APU) A / C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------|---------|--------------------------------------------|----------|------------|----------------------------|-----------|-----------|-------------|----------|
| ATA 27 - FLIGHT CONTROLS                           |         |                                            |          |            |                            |           |           |             |          |
| 271094                                             | U       | COPILOT ANGLE OF ATTACK (AOA) TRANSDUCER   |          |            |                            |           |           | Component   | ATA:27   |
| PN:PN                                              | MOS/MSC | 09-Mar-01                                  | O/C      | TSN 0      |                            |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0                                          |          | TSN 0      |                            |           |           |             |          |
|                                                    | AFL     | 0                                          |          | TSN 0      |                            |           |           |             |          |
|                                                    |         |                                            |          |            |                            |           |           |             |          |
| 271095                                             |         | PILOT ANGLE OF ATTACK INDICATOR (AOA)      |          |            |                            |           |           | Component   | ATA:27   |
| PN:PN                                              | MOS/MSC | 09-Mar-01                                  | O/C      | TSN 0      |                            |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0                                          |          | TSN 0      |                            |           |           |             |          |
|                                                    | AFL     | 0                                          |          | TSN 0      |                            |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |         |                                            |          |            |                            |           |           |             |          |
|                                                    |         |                                            |          |            |                            |           |           |             |          |
| 271096                                             |         | COPILOT ANGLE OF ATTACK INDICATOR (AOA)    |          |            |                            |           |           | Component   | ATA:27   |
| PN:PN                                              | MOS/MSC | 09-Mar-01                                  | O/C      | TSN 0      |                            |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0                                          |          | TSN 0      |                            |           |           |             |          |
|                                                    | AFL     | 0                                          |          | TSN 0      |                            |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |         |                                            |          |            |                            |           |           |             |          |
|                                                    |         |                                            |          |            |                            |           |           |             |          |
| 272001                                             |         | FORWARD UPPER RUDDER CONTROL SYSTEM CABLE  |          |            |                            |           |           | Component   | ATA:27   |
| PN:PN                                              | MOS/MSC | 09-Mar-01                                  | O/C      | TSN 0      |                            |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0                                          |          | TSN 0      |                            |           |           |             |          |
|                                                    | AFL     | 0                                          |          | TSN 0      |                            |           |           |             |          |
| PROC. REF: AMM 27-20-08PROC. REF: AMM 27-20-08     |         |                                            |          |            |                            |           |           |             |          |
|                                                    |         |                                            |          |            |                            |           |           |             |          |
| 272002                                             |         | FORWARD LOWER RUDDER CONTROL SYSTEM CABLE  |          |            |                            |           |           | Component   | ATA:27   |
| PN:PN                                              | MOS/MSC | 09-Mar-01                                  | O/C      | TSN 0      |                            |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0                                          |          | TSN 0      |                            |           |           |             |          |
|                                                    | AFL     | 0                                          |          | TSN 0      |                            |           |           |             |          |
| PROC. REF: AMM 27-20-08PROC. REF: AMM 27-20-08     |         |                                            |          |            |                            |           |           |             |          |
|                                                    |         |                                            |          |            |                            |           |           |             |          |
| 272003                                             |         | LEFT AFT UPPER RUDDER CONTROL SYSTEM CABLE |          |            |                            |           |           | Component   | ATA:27   |
| PN:PN                                              | MOS/MSC | 09-Mar-01                                  | O/C      | TSN 0      |                            |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0                                          |          | TSN 0      |                            |           |           |             |          |
|                                                    | AFL     | 0                                          |          | TSN 0      |                            |           |           |             |          |
| PROC. REF: AMM 27-20-08PROC. REF: AMM 27-20-08     |         |                                            |          |            |                            |           |           |             |          |

?-Insufficient Information    S-Suppressed Requirement    \*-Estimated Due(New Requirement)    (EFF)-Effective C / W    (M)-Manual Due    U-User Task    Ex-Excluded Task

# Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9669.1
 AFL: 7372
 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                        | Unit                                        | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|------------------------------------------------|---------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 27 - FLIGHT CONTROLS                       |                                             |           |          |          |                        |           |           |             |                  |
| 272004                                         | RIGHT AFT UPPER RUDDER CONTROL SYSTEM CABLE |           |          |          |                        |           |           |             | Component ATA:27 |
| PN:PN                                          | MOS/MSC                                     | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                         | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                         | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 27-20-08PROC. REF: AMM 27-20-08 |                                             |           |          |          |                        |           |           |             |                  |
| 272005                                         | LEFT AFT LOWER RUDDER CONTROL SYSTEM CABLE  |           |          |          |                        |           |           |             | Component ATA:27 |
| PN:PN                                          | MOS/MSC                                     | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                         | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                         | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 27-20-08PROC. REF: AMM 27-20-08 |                                             |           |          |          |                        |           |           |             |                  |
| 272006                                         | RIGHT AFT LOWER RUDDER CONTROL SYSTEM CABLE |           |          |          |                        |           |           |             | Component ATA:27 |
| PN:PN                                          | MOS/MSC                                     | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                         | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                         | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 27-20-08PROC. REF: AMM 27-20-08 |                                             |           |          |          |                        |           |           |             |                  |
| 272021                                         | RUDDER TRIM TAB ACTUATOR                    |           |          |          |                        |           |           |             | Component ATA:27 |
| PN:PN                                          | MOS/MSC                                     | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                         | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                         | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 27-20-03PROC. REF: AMM 27-20-03 |                                             |           |          |          |                        |           |           |             |                  |
| 272031                                         | PILOT RUDDER PEDAL ADJUST ACTUATOR          |           |          |          |                        |           |           |             | Component ATA:27 |
| PN:6627208001-003<br>(4389596)                 | MOS/MSC                                     | 17-Feb-05 | O/C      |          |                        |           |           |             |                  |
| SN:0437                                        | HRS                                         | 3300.2    |          |          |                        |           |           |             |                  |
|                                                | AFL                                         | 2515      |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 27-20-05PROC. REF: AMM 27-20-05 |                                             |           |          |          |                        |           |           |             |                  |
| 272032                                         | COPILOT RUDDER PEDAL ADJUST ACTUATOR        |           |          |          |                        |           |           |             | Component ATA:27 |
| PN:6627208001-003<br>(4389596)                 | MOS/MSC                                     | 17-Feb-05 | O/C      |          |                        |           |           |             |                  |
| SN:0431                                        | HRS                                         | 3300.2    |          |          |                        |           |           |             |                  |
|                                                | AFL                                         | 2515      |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 27-20-05PROC. REF: AMM 27-20-05 |                                             |           |          |          |                        |           |           |             |                  |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C/W   (M)-Manual Due   U-User Task   Ex-Excluded Task

# Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9669.1
 AFL: 7372
 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                        | Unit                                          | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|------------------------------------------------|-----------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 27 - FLIGHT CONTROLS                       |                                               |           |          |          |                        |           |           |             |                  |
| 273001                                         | PILOT FORWARD ELEVATOR CONTROL SYSTEM CABLE   |           |          |          |                        |           |           |             | Component ATA:27 |
| PN:PN                                          | MOS/MSC                                       | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 27-30-05PROC. REF: AMM 27-30-05 |                                               |           |          |          |                        |           |           |             |                  |
| 273002                                         | COPILOT FORWARD ELEVATOR CONTROL SYSTEM CABLE |           |          |          |                        |           |           |             | Component ATA:27 |
| PN:PN                                          | MOS/MSC                                       | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 27-30-05PROC. REF: AMM 27-30-05 |                                               |           |          |          |                        |           |           |             |                  |
| 273003                                         | LEFT AFT UPPER ELEVATOR CONTROL SYSTEM CABLE  |           |          |          |                        |           |           |             | Component ATA:27 |
| PN:PN                                          | MOS/MSC                                       | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 27-30-05PROC. REF: AMM 27-30-05 |                                               |           |          |          |                        |           |           |             |                  |
| 273004                                         | RIGHT AFT UPPER ELEVATOR CONTROL SYSTEM CABLE |           |          |          |                        |           |           |             | Component ATA:27 |
| PN:PN                                          | MOS/MSC                                       | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 27-30-05PROC. REF: AMM 27-30-05 |                                               |           |          |          |                        |           |           |             |                  |
| 273005                                         | LEFT AFT LOWER ELEVATOR CONTROL SYSTEM CABLE  |           |          |          |                        |           |           |             | Component ATA:27 |
| PN:PN                                          | MOS/MSC                                       | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 27-30-05PROC. REF: AMM 27-30-05 |                                               |           |          |          |                        |           |           |             |                  |
| 273006                                         | RIGHT AFT LOWER ELEVATOR CONTROL SYSTEM CABLE |           |          |          |                        |           |           |             | Component ATA:27 |
| PN:PN                                          | MOS/MSC                                       | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 27-30-05PROC. REF: AMM 27-30-05 |                                               |           |          |          |                        |           |           |             |                  |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C/W   (M)-Manual Due   U-User Task   Ex-Excluded Task

Status Report

Model: LEARJET 45XR    Serial: 45-145    RegNo: N942FK    HRS: 9669.1    AFL: 7372    As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                        | Unit                                    | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|------------------------------------------------|-----------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 27 - FLIGHT CONTROLS                       |                                         |           |          |          |                        |           |           |             |          |
| 273015                                         | LEFT ANGLE OF ATTACK VANE (AOA)         |           |          |          |                        |           |           | Component   | ATA:27   |
| PN:PN                                          | MOS/MSC                                 | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS                                     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL                                     | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 27-31-04PROC. REF: AMM 27-31-04 |                                         |           |          |          |                        |           |           |             |          |
| 273016                                         | RIGHT ANGLE OF ATTACK VANE (AOA)        |           |          |          |                        |           |           | Component   | ATA:27   |
| PN:PN                                          | MOS/MSC                                 | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS                                     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL                                     | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 27-31-04PROC. REF: AMM 27-31-04 |                                         |           |          |          |                        |           |           |             |          |
| 273022                                         | LEFT ANGLE OF ATTACK TRANSMITTER (AOA)  |           |          |          |                        |           |           | Component   | ATA:27   |
| PN:C-38817-1                                   | MOS/MSC                                 | 11-Dec-23 | O/C      |          |                        |           |           |             |          |
| SN:1333                                        | HRS                                     | 9373.9    |          |          |                        |           |           |             |          |
|                                                | AFL                                     | 7179      |          |          |                        |           |           |             |          |
| PROC. REF: AMM 27-31-01PROC. REF: AMM 27-31-01 |                                         |           |          |          |                        |           |           |             |          |
| 273023                                         | RIGHT ANGLE OF ATTACK TRANSMITTER (AOA) |           |          |          |                        |           |           | Component   | ATA:27   |
| PN:PN                                          | MOS/MSC                                 | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS                                     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL                                     | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 27-31-01PROC. REF: AMM 27-31-01 |                                         |           |          |          |                        |           |           |             |          |
| 273051                                         | ELEVATOR DISCONNECT ACTUATOR            |           |          |          |                        |           |           | Component   | ATA:27   |
| PN:PN                                          | MOS/MSC                                 | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS                                     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL                                     | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 27-30-09PROC. REF: AMM 27-30-09 |                                         |           |          |          |                        |           |           |             |          |
| 273063                                         | PILOT STICK SHAKER                      |           |          |          |                        |           |           | Component   | ATA:27   |
| PN:PN                                          | MOS/MSC                                 | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS                                     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL                                     | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 27-31-03PROC. REF: AMM 27-31-03 |                                         |           |          |          |                        |           |           |             |          |

?-Insufficient Information    S-Suppressed Requirement    \*-Estimated Due(New Requirement)    (EFF)-Effective C/W    (M)-Manual Due    U-User Task    Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                        | Unit                                                                                                      | C / W     | Interval | TSX/Adj.  | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|------------------------------------------------|-----------------------------------------------------------------------------------------------------------|-----------|----------|-----------|------------------------|-----------|-----------|-------------|----------|
| ATA 27 - FLIGHT CONTROLS                       |                                                                                                           |           |          |           |                        |           |           |             |          |
| 273064                                         | COPILOT STICK SHAKER                                                                                      |           |          |           |                        |           |           | Component   | ATA:27   |
| PN:PN                                          | MOS/MSC                                                                                                   | 09-Mar-01 | O/C      | TSN 0     |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS                                                                                                       | 0         |          | TSN 0     |                        |           |           |             |          |
|                                                | AFL                                                                                                       | 0         |          | TSN 0     |                        |           |           |             |          |
| PROC. REF: AMM 27-31-03PROC. REF: AMM 27-31-03 |                                                                                                           |           |          |           |                        |           |           |             |          |
| 273087                                         | STALL WARNING COMPUTER                                                                                    |           |          |           |                        |           |           | Component   | ATA:27   |
| PN:C-38806-2                                   | MOS/MSC                                                                                                   | 14-Feb-24 | O/C      |           |                        |           |           |             |          |
| SN:132                                         | HRS                                                                                                       | 9467.2    |          |           |                        |           |           |             |          |
|                                                | AFL                                                                                                       | 7246      |          |           |                        |           |           |             |          |
| PROC. REF: AMM 27-31-02PROC. REF: AMM 27-31-02 |                                                                                                           |           |          |           |                        |           |           |             |          |
| 273201                                         | ELEVATOR DISCONNECT CURRENT LIMITER                                                                       |           |          |           |                        |           |           | Component   | ATA:27   |
| PN:PN                                          | MOS/MSC                                                                                                   | 09-Mar-01 | O/C      | TSN 0     |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS                                                                                                       | 0         |          | TSN 0     |                        |           |           |             |          |
|                                                | AFL                                                                                                       | 0         |          | TSN 0     |                        |           |           |             |          |
| PROC. REF: AMM 27-30-13PROC. REF: AMM 27-30-13 |                                                                                                           |           |          |           |                        |           |           |             |          |
| 273420                                         | ELEVATOR OVERRIDE ACTUATOR                                                                                |           |          |           |                        |           |           | Component   | ATA:27   |
| PN:PN                                          | MOS/MSC                                                                                                   | 09-Mar-01 | O/C      | TSN 0     |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS                                                                                                       | 0         |          | TSN 0     |                        |           |           |             |          |
|                                                | AFL                                                                                                       | 0         |          | TSN 0     |                        |           |           |             |          |
| PROC. REF: AMM 27-30-14PROC. REF: AMM 27-30-14 |                                                                                                           |           |          |           |                        |           |           |             |          |
| 274011                                         | HORIZONTAL STABILIZER ACTUATOR                                                                            |           |          |           |                        |           |           | Component   | ATA:27   |
| PN:6627401000-009                              | MOS/MSC                                                                                                   | 22-Jun-23 | O/C      | TSO 10    |                        |           |           |             |          |
| SN:B0581                                       | HRS                                                                                                       | 9258.5    |          | TSO 175.9 |                        |           |           |             |          |
|                                                | AFL                                                                                                       | 7100      |          | TSO 106   |                        |           |           |             |          |
| PROC. REF: AMM 27-40-02PROC. REF: AMM 27-40-02 |                                                                                                           |           |          |           |                        |           |           |             |          |
| 274011A                                        | INSPECT HORIZONTAL STABILIZER ACTUATOR * (6627401000-009 - IRN P2740032). (6627401000-007 - IRN T2740002) |           |          |           |                        |           |           | Service     | ATA:27   |
| PN:6627401000-009                              | MOS                                                                                                       | 18-Aug-22 |          |           |                        |           |           |             |          |
| SN:B0581                                       | HRS                                                                                                       | 9082.6    | 1200     |           | 10282.6                |           | 613.5     |             |          |
|                                                | AFL                                                                                                       | 6994      |          |           |                        |           |           |             |          |
| PROC. REF: AMM 27-40-00PROC. REF: AMM 27-40-00 |                                                                                                           |           |          |           |                        |           |           |             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                                                    | Unit    | C / W                                                                                                                                      | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------------------------------|---------|--------------------------------------------------------------------------------------------------------------------------------------------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 27 - FLIGHT CONTROLS                                                   |         |                                                                                                                                            |          |          |                        |           |           |             |          |
| 274011B                                                                    |         | * HORIZONTAL STABILIZER ACTUATOR - PERFORM DETAILED STRUCTURAL INSPECTION (6627401000-009 - IRN P2740033). (6627401000-007 - IRN N2740025) |          |          |                        |           |           | Service     | ATA:27   |
| PN:6627401000-009                                                          | MOS     | 18-Aug-22                                                                                                                                  |          |          |                        |           |           |             |          |
| SN:B0581                                                                   | HRS     | 9082.6                                                                                                                                     | 2400     |          | 11482.6                |           | 1813.5    |             |          |
|                                                                            | AFL     | 6994                                                                                                                                       |          |          |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |         |                                                                                                                                            |          |          |                        |           |           |             |          |
| 274011C                                                                    |         | REPLACE HORIZONTAL STABILIZER ACTUATOR * ACME SCREW (P/N 2A94568008). EFFECTIVE ON AIRCRAFT EQUIPPED WITH (6627401000-007 - IRN N2740023)  |          |          |                        |           |           | Service     | ATA:27   |
| PN:6627401000-009                                                          | MOS/MSC | 18-Aug-22                                                                                                                                  | N/A      |          |                        |           |           |             |          |
| SN:B0581                                                                   | HRS     | 9082.6                                                                                                                                     |          |          |                        |           |           |             |          |
|                                                                            | AFL     | 6994                                                                                                                                       |          |          |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |         |                                                                                                                                            |          |          |                        |           |           |             |          |
| 274011D                                                                    |         | REPLACE HORIZONTAL STABILIZER ACTUATOR * ACME NUT (P/N 2A94567005). (EFFECTIVE ON AIRCRAFT EQUIPPED WITH (6627401000-007 - IRN N2740024)   |          |          |                        |           |           | Service     | ATA:27   |
| PN:6627401000-009                                                          | MOS/MSC | 18-Aug-22                                                                                                                                  | N/A      |          |                        |           |           |             |          |
| SN:B0581                                                                   | HRS     | 9082.6                                                                                                                                     |          |          |                        |           |           |             |          |
|                                                                            | AFL     | 6994                                                                                                                                       |          |          |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |         |                                                                                                                                            |          |          |                        |           |           |             |          |
| 274031                                                                     |         | TRIM-IN-MOTION DETECTOR                                                                                                                    |          |          |                        |           |           | Component   | ATA:27   |
| PN:PN                                                                      | MOS/MSC | 09-Mar-01                                                                                                                                  | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                                                 | HRS     | 0                                                                                                                                          |          | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL     | 0                                                                                                                                          |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 27-41-01PROC. REF: AMM 27-41-01                             |         |                                                                                                                                            |          |          |                        |           |           |             |          |
| 274041                                                                     |         | FORWARD INTERFACE UNIT                                                                                                                     |          |          |                        |           |           | Component   | ATA:27   |
| PN:PN                                                                      | MOS/MSC | 09-Mar-01                                                                                                                                  | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                                                 | HRS     | 0                                                                                                                                          |          | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL     | 0                                                                                                                                          |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 27-40-04PROC. REF: AMM 27-40-04                             |         |                                                                                                                                            |          |          |                        |           |           |             |          |
| 274051                                                                     |         | HORIZONTAL STABILIZER ACTUATOR CONTROL BOX                                                                                                 |          |          |                        |           |           | Component   | ATA:27   |
| PN:PN                                                                      | MOS/MSC | 09-Mar-01                                                                                                                                  | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                                                 | HRS     | 0                                                                                                                                          |          | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL     | 0                                                                                                                                          |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 27-40-02, AMM 27-40-03PROC. REF: AMM 27-40-02, AMM 27-40-03 |         |                                                                                                                                            |          |          |                        |           |           |             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                        | Unit | C / W                                          | Interval  | TSX / Adj. | Next Due (ENG / APU) A / C | Max Limit | Remaining | Disposition | Warranty |
|------------------------------------------------|------|------------------------------------------------|-----------|------------|----------------------------|-----------|-----------|-------------|----------|
| ATA 27 - FLIGHT CONTROLS                       |      |                                                |           |            |                            |           |           |             |          |
| 274052 <sup>U</sup>                            |      | ASSEMBLY, HORIZONTAL STAB ACTUATOR CONTROL BOX |           |            |                            |           |           | Component   | ATA:27   |
| PN:6627401000-003                              |      | MOS/MSC                                        | 28-Jan-07 | O/C        |                            |           |           |             |          |
| SN:D0305                                       |      | HRS                                            | 5192.28   |            |                            |           |           |             |          |
|                                                |      | AFL                                            | 3977      |            |                            |           |           |             |          |
|                                                |      |                                                |           |            |                            |           |           |             |          |
| 275020                                         |      | LEFT FLAP, OUTBOARD ACTUATOR                   |           |            |                            |           |           | Component   | ATA:27   |
| PN:PN                                          |      | MOS/MSC                                        | 09-Mar-01 | O/C        | TSN 0                      |           |           |             |          |
| SN:UNKNOWN                                     |      | HRS                                            | 0         |            | TSN 0                      |           |           |             |          |
|                                                |      | AFL                                            | 0         |            | TSN 0                      |           |           |             |          |
| PROC. REF: AMM 27-50-06PROC. REF: AMM 27-50-06 |      |                                                |           |            |                            |           |           |             |          |
|                                                |      |                                                |           |            |                            |           |           |             |          |
| 275021                                         |      | LEFT FLAP, INBOARD ACTUATOR                    |           |            |                            |           |           | Component   | ATA:27   |
| PN:6627503000-009                              |      | MOS/MSC                                        | 18-Jul-07 | O/C        |                            |           |           |             |          |
| SN:1743                                        |      | HRS                                            | 5671.55   |            |                            |           |           |             |          |
|                                                |      | AFL                                            | 4333      |            |                            |           |           |             |          |
| PROC. REF: AMM 27-50-06PROC. REF: AMM 27-50-06 |      |                                                |           |            |                            |           |           |             |          |
|                                                |      |                                                |           |            |                            |           |           |             |          |
| 275022                                         |      | RIGHT FLAP, INBOARD ACTUATOR                   |           |            |                            |           |           | Component   | ATA:27   |
| PN:PN                                          |      | MOS/MSC                                        | 09-Mar-01 | O/C        | TSN 0                      |           |           |             |          |
| SN:UNKNOWN                                     |      | HRS                                            | 0         |            | TSN 0                      |           |           |             |          |
|                                                |      | AFL                                            | 0         |            | TSN 0                      |           |           |             |          |
| PROC. REF: AMM 27-50-06PROC. REF: AMM 27-50-06 |      |                                                |           |            |                            |           |           |             |          |
|                                                |      |                                                |           |            |                            |           |           |             |          |
| 275023                                         |      | RIGHT FLAP, OUTBOARD ACTUATOR                  |           |            |                            |           |           | Component   | ATA:27   |
| PN:PN                                          |      | MOS/MSC                                        | 09-Mar-01 | O/C        | TSN 0                      |           |           |             |          |
| SN:UNKNOWN                                     |      | HRS                                            | 0         |            | TSN 0                      |           |           |             |          |
|                                                |      | AFL                                            | 0         |            | TSN 0                      |           |           |             |          |
| PROC. REF: AMM 27-50-06PROC. REF: AMM 27-50-06 |      |                                                |           |            |                            |           |           |             |          |
|                                                |      |                                                |           |            |                            |           |           |             |          |
| 275057                                         |      | FLAP DRIVE POWER UNIT                          |           |            |                            |           |           | Component   | ATA:27   |
| PN:6627503000-029                              |      | MOS/MSC                                        | 25-Feb-11 | O/C        |                            |           |           |             |          |
| SN:1461                                        |      | HRS                                            | 6519.3    |            |                            |           |           |             |          |
|                                                |      | AFL                                            | 4991      |            |                            |           |           |             |          |
| PROC. REF: AMM 27-50-08PROC. REF: AMM 27-50-08 |      |                                                |           |            |                            |           |           |             |          |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C / W   (M)-Manual Due   U-User Task   Ex-Excluded Task

# Status Report

Model: LEARJET 45XR    Serial: 45-145    RegNo: N942FK    HRS: 9669.1    AFL: 7372    As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                        | Unit                                                      | C / W     | Interval | TSX / Adj. | Next Due (ENG / APU) A / C | Max Limit | Remaining | Disposition | Warranty            |
|------------------------------------------------|-----------------------------------------------------------|-----------|----------|------------|----------------------------|-----------|-----------|-------------|---------------------|
| ATA 27 - FLIGHT CONTROLS                       |                                                           |           |          |            |                            |           |           |             |                     |
| 275058                                         | FLAP CONTROL UNIT                                         |           |          |            |                            |           |           |             | Component    ATA:27 |
| PN:C144486-3-003                               | MOS/MSC                                                   | 05-Jan-20 | O/C      |            |                            |           |           |             |                     |
| SN:1343                                        | HRS                                                       | 8209.7    |          |            |                            |           |           |             |                     |
|                                                | AFL                                                       | 6328      |          |            |                            |           |           |             |                     |
| PROC. REF: AMM 27-50-05PROC. REF: AMM 27-50-05 |                                                           |           |          |            |                            |           |           |             |                     |
| 275069                                         | FLAP POSITION INDICATOR                                   |           |          |            |                            |           |           |             | Component    ATA:27 |
| PN:C145159-1                                   | MOS/MSC                                                   | 09-Oct-23 | O/C      |            |                            |           |           |             |                     |
| SN:135                                         | HRS                                                       | 9332.6    |          |            |                            |           |           |             |                     |
|                                                | AFL                                                       | 7149      |          |            |                            |           |           |             |                     |
| PROC. REF: AMM 27-50-07PROC. REF: AMM 27-50-07 |                                                           |           |          |            |                            |           |           |             |                     |
| 275080                                         | FLAP CONTROL MODULE                                       |           |          |            |                            |           |           |             | Component    ATA:27 |
| PN:PN                                          | MOS/MSC                                                   | 09-Mar-01 | O/C      | TSN 0      |                            |           |           |             |                     |
| SN:UNKNOWN                                     | HRS                                                       | 0         |          | TSN 0      |                            |           |           |             |                     |
|                                                | AFL                                                       | 0         |          | TSN 0      |                            |           |           |             |                     |
| PROC. REF: AMM 27-50-02PROC. REF: AMM 27-50-02 |                                                           |           |          |            |                            |           |           |             |                     |
| 275081                                         | LEFT FLAP DRIVE ROTARY VARIABLE DIFFERENTIAL TRANSFORMER  |           |          |            |                            |           |           |             | Component    ATA:27 |
| PN:PN                                          | MOS/MSC                                                   | 09-Mar-01 | O/C      | TSN 0      |                            |           |           |             |                     |
| SN:UNKNOWN                                     | HRS                                                       | 0         |          | TSN 0      |                            |           |           |             |                     |
|                                                | AFL                                                       | 0         |          | TSN 0      |                            |           |           |             |                     |
| PROC. REF: AMM 27-50-03PROC. REF: AMM 27-50-03 |                                                           |           |          |            |                            |           |           |             |                     |
| 275082                                         | RIGHT FLAP DRIVE ROTARY VARIABLE DIFFERENTIAL TRANSFORMER |           |          |            |                            |           |           |             | Component    ATA:27 |
| PN:PN                                          | MOS/MSC                                                   | 09-Mar-01 | O/C      | TSN 0      |                            |           |           |             |                     |
| SN:UNKNOWN                                     | HRS                                                       | 0         |          | TSN 0      |                            |           |           |             |                     |
|                                                | AFL                                                       | 0         |          | TSN 0      |                            |           |           |             |                     |
| PROC. REF: AMM 27-50-03PROC. REF: AMM 27-50-03 |                                                           |           |          |            |                            |           |           |             |                     |
| 276001                                         | LEFT SPOILER ACTUATOR                                     |           |          |            |                            |           |           |             | Component    ATA:27 |
| PN:6627602001-007                              | MOS/MSC                                                   | 15-Jun-06 | O/C      |            |                            |           |           |             |                     |
| SN:DWA392-00                                   | HRS                                                       | 4570.25   |          |            |                            |           |           |             |                     |
|                                                | AFL                                                       | 3497      |          |            |                            |           |           |             |                     |
| PROC. REF: AMM 27-60-04PROC. REF: AMM 27-60-04 |                                                           |           |          |            |                            |           |           |             |                     |

?-Insufficient Information    S-Suppressed Requirement    \*-Estimated Due(New Requirement)    (EFF)-Effective C / W    (M)-Manual Due    U-User Task    Ex-Excluded Task



Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                        | Unit                                                                                                                                    | C / W     | Interval | TSX / Adj. | Next Due (ENG / APU) A / C | Max Limit | Remaining | Disposition | Warranty |
|------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------|-----------|----------|------------|----------------------------|-----------|-----------|-------------|----------|
| ATA 27 - FLIGHT CONTROLS                       |                                                                                                                                         |           |          |            |                            |           |           |             |          |
| 276002                                         | RIGHT SPOILER ACTUATOR                                                                                                                  |           |          |            |                            |           |           | Component   | ATA:27   |
| PN:6627602001-007                              | MOS/MSC                                                                                                                                 | 15-Jun-06 | O/C      |            |                            |           |           |             |          |
| SN:DAW398-00                                   | HRS                                                                                                                                     | 4570.25   |          |            |                            |           |           |             |          |
|                                                | AFL                                                                                                                                     | 3497      |          |            |                            |           |           |             |          |
| PROC. REF: AMM 27-60-04PROC. REF: AMM 27-60-04 |                                                                                                                                         |           |          |            |                            |           |           |             |          |
| 276005                                         | SPOILER CONTROL MODULE                                                                                                                  |           |          |            |                            |           |           | Component   | ATA:27   |
| PN:PN                                          | MOS/MSC                                                                                                                                 | 09-Mar-01 | O/C      | TSN 0      |                            |           |           |             |          |
| SN:UNKNOWN                                     | HRS                                                                                                                                     | 0         |          | TSN 0      |                            |           |           |             |          |
|                                                | AFL                                                                                                                                     | 0         |          | TSN 0      |                            |           |           |             |          |
| PROC. REF: AMM 27-60-03PROC. REF: AMM 27-60-03 |                                                                                                                                         |           |          |            |                            |           |           |             |          |
| 2760085 <sup>S</sup>                           | SPOILER LEVER ARM - PERFORM DETAILED VISUAL INSPECTION TO ENSURE SPOILER LEVER ARM IS PROPERLY SEATED AND SECURED ON SPOILER RVDT SHAFT |           |          |            |                            |           |           | Service     | ATA:27   |
|                                                | MOS                                                                                                                                     | 02-Aug-24 | 36       |            |                            |           |           |             |          |
|                                                | HRS                                                                                                                                     | 9525.7    | 600      |            |                            |           |           |             |          |
|                                                | AFL                                                                                                                                     | 7276      |          |            |                            |           |           |             |          |
| PROC. REF: AMM 27-60-05PROC. REF: AMM 27-60-05 |                                                                                                                                         |           |          |            |                            |           |           |             |          |
| 276010                                         | SPOILERON CONTROLLER RESISTOR BOX                                                                                                       |           |          |            |                            |           |           | Component   | ATA:27   |
| PN:PN                                          | MOS/MSC                                                                                                                                 | 09-Mar-01 | O/C      | TSN 0      |                            |           |           |             |          |
| SN:UNKNOWN                                     | HRS                                                                                                                                     | 0         |          | TSN 0      |                            |           |           |             |          |
|                                                | AFL                                                                                                                                     | 0         |          | TSN 0      |                            |           |           |             |          |
| PROC. REF: AMM 27-60-10PROC. REF: AMM 27-60-10 |                                                                                                                                         |           |          |            |                            |           |           |             |          |
| 276013                                         | SPOILER SHUTOFF VALVE                                                                                                                   |           |          |            |                            |           |           | Component   | ATA:27   |
| PN:PN                                          | MOS/MSC                                                                                                                                 | 09-Mar-01 | O/C      | TSN 0      |                            |           |           |             |          |
| SN:UNKNOWN                                     | HRS                                                                                                                                     | 0         |          | TSN 0      |                            |           |           |             |          |
|                                                | AFL                                                                                                                                     | 0         |          | TSN 0      |                            |           |           |             |          |
| PROC. REF: AMM 27-60-07PROC. REF: AMM 27-60-07 |                                                                                                                                         |           |          |            |                            |           |           |             |          |
| 276020                                         | SPOILER LOW PRESSURE SWITCH                                                                                                             |           |          |            |                            |           |           | Component   | ATA:27   |
| PN:6629101004-003                              | MOS/MSC                                                                                                                                 | 11-Jun-16 | O/C      |            |                            |           |           |             |          |
| SN:535                                         | HRS                                                                                                                                     | 7630.1    |          |            |                            |           |           |             |          |
|                                                | AFL                                                                                                                                     | 5823      |          |            |                            |           |           |             |          |
| PROC. REF: AMM 27-60-08PROC. REF: AMM 27-60-08 |                                                                                                                                         |           |          |            |                            |           |           |             |          |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C / W   (M)-Manual Due   U-User Task   Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                        | Unit                                                                                      | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|------------------------------------------------|-------------------------------------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 27 - FLIGHT CONTROLS                       |                                                                                           |           |          |          |                        |           |           |             |          |
| 276031                                         | LEFT SPOILER ROTARY VARIABLE DIFFERENTIAL TRANSFORMER                                     |           |          |          |                        |           |           | Component   | ATA:27   |
| PN:PN                                          | MOS/MSC                                                                                   | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS                                                                                       | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL                                                                                       | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 27-60-05PROC. REF: AMM 27-60-05 |                                                                                           |           |          |          |                        |           |           |             |          |
| 276032                                         | RIGHT SPOILER ROTARY VARIABLE DIFFERENTIAL TRANSFORMER                                    |           |          |          |                        |           |           | Component   | ATA:27   |
| PN:PN                                          | MOS/MSC                                                                                   | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS                                                                                       | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL                                                                                       | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 27-60-05PROC. REF: AMM 27-60-05 |                                                                                           |           |          |          |                        |           |           |             |          |
| 276073                                         | SPOILERON COMPUTER                                                                        |           |          |          |                        |           |           | Component   | ATA:27   |
| PN:6627608500-007                              | MOS/MSC                                                                                   | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:00227                                       | HRS                                                                                       | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL                                                                                       | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 27-60-02PROC. REF: AMM 27-60-02 |                                                                                           |           |          |          |                        |           |           |             |          |
| 276076                                         | CONTROL WHEEL ROTARY VARIABLE DIFFERENTIAL TRANSFORMER                                    |           |          |          |                        |           |           | Component   | ATA:27   |
| PN:PN                                          | MOS/MSC                                                                                   | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS                                                                                       | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL                                                                                       | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 27-60-06PROC. REF: AMM 27-60-06 |                                                                                           |           |          |          |                        |           |           |             |          |
| 5-19-00-D2740003                               | ** HORIZONTAL STABILIZER ACTUATOR SECONDARY TRIM - PERFORM FUNCTIONAL TEST (IRN D2740003) |           |          |          |                        |           |           | Service     | ATA:27   |
|                                                | MOS                                                                                       | 02-Aug-24 |          |          |                        |           |           |             |          |
|                                                | HRS                                                                                       | 9525.7    | 600      |          | 10125.7                |           | 456.6     |             |          |
|                                                | AFL                                                                                       | 7276      |          |          |                        |           |           |             |          |
| PROC. REF: AMM 27-40-02PROC. REF: AMM 27-40-02 |                                                                                           |           |          |          |                        |           |           |             |          |
| 5-19-00-D2740004                               | ** HORIZONTAL STABILIZER ACTUATOR PRIMARY TRIM - PERFORM FUNCTIONAL TEST (IRN D2740004)   |           |          |          |                        |           |           | Service     | ATA:27   |
|                                                | MOS                                                                                       | 02-Aug-24 |          |          |                        |           |           |             |          |
|                                                | HRS                                                                                       | 9525.7    | 600      |          | 10125.7                |           | 456.6     |             |          |
|                                                | AFL                                                                                       | 7276      |          |          |                        |           |           |             |          |
| PROC. REF: AMM 27-40-02PROC. REF: AMM 27-40-02 |                                                                                           |           |          |          |                        |           |           |             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                                                                                | Unit                                                                                                                                                                                                                                                                                                                            | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition    | Warranty |
|--------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|----------------|----------|
| ATA 27 - FLIGHT CONTROLS                                                                               |                                                                                                                                                                                                                                                                                                                                 |           |          |          |                        |           |           |                |          |
| 5-19-00-K2700010                                                                                       | * ELEVATOR CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED VISUAL INSPECTION (IRN K2700010)                                                                                                                                                                                                           |           |          |          |                        |           |           | Service        | ATA:27   |
|                                                                                                        | MOS                                                                                                                                                                                                                                                                                                                             | 22-Jun-23 |          |          |                        |           |           | AIRWORTHINESS  |          |
|                                                                                                        | HRS                                                                                                                                                                                                                                                                                                                             | 9258.5    | 4800     |          | 14058.5                |           | 4389.4    |                |          |
|                                                                                                        | AFL                                                                                                                                                                                                                                                                                                                             | 7100      |          |          |                        |           |           |                |          |
| PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00                                                         |                                                                                                                                                                                                                                                                                                                                 |           |          |          |                        |           |           |                |          |
| 5-19-00-K2700012                                                                                       | * RUDDER CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED VISUAL INSPECTION (IRN K2700012)                                                                                                                                                                                                             |           |          |          |                        |           |           | Service        | ATA:27   |
|                                                                                                        | MOS                                                                                                                                                                                                                                                                                                                             | 22-Jun-23 |          |          |                        |           |           | AIRWORTHINESS  |          |
|                                                                                                        | HRS                                                                                                                                                                                                                                                                                                                             | 9258.5    | 4800     |          | 14058.5                |           | 4389.4    |                |          |
|                                                                                                        | AFL                                                                                                                                                                                                                                                                                                                             | 7100      |          |          |                        |           |           |                |          |
| PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00                                                         |                                                                                                                                                                                                                                                                                                                                 |           |          |          |                        |           |           |                |          |
| 5-19-00-K2700014                                                                                       | DETAILED VISUAL INSPECTION * AILERON CONTROL SYSTEM PRIMARY CABLES (IRN K2700014)                                                                                                                                                                                                                                               |           |          |          |                        |           |           | Service        | ATA:27   |
|                                                                                                        | MOS                                                                                                                                                                                                                                                                                                                             | 22-Jun-23 |          |          |                        |           |           | AIRWORTHINESS  |          |
|                                                                                                        | HRS                                                                                                                                                                                                                                                                                                                             | 9258.5    | 4800     |          | 14058.5                |           | 4389.4    |                |          |
|                                                                                                        | AFL                                                                                                                                                                                                                                                                                                                             | 7100      |          |          |                        |           |           |                |          |
| PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00                                                         |                                                                                                                                                                                                                                                                                                                                 |           |          |          |                        |           |           |                |          |
| 5-19-00-N2720030                                                                                       | RUDDER TORQUE TUBE AND SPINDLE - PERFORM DETAILED VISUAL INSPECTION                                                                                                                                                                                                                                                             |           |          |          |                        |           |           | Service        | ATA:27   |
|                                                                                                        | MOS                                                                                                                                                                                                                                                                                                                             | 25-Nov-19 | 72       |          | 25-Nov-25              |           | 237 d     | AIRWORTHINESS  |          |
|                                                                                                        | HRS                                                                                                                                                                                                                                                                                                                             | 8177.7    |          |          |                        |           |           |                |          |
|                                                                                                        | AFL                                                                                                                                                                                                                                                                                                                             | 6303      |          |          |                        |           |           |                |          |
| PROC. REF: AMM 27-20-01PROC. REF: AMM 27-20-01                                                         |                                                                                                                                                                                                                                                                                                                                 |           |          |          |                        |           |           |                |          |
| 5-19-00-S2750057                                                                                       | * FLAP ACTUATOR BALLNUT SLEEVE (FLAP ACTUATOR ASSEMBLY LEARJET P/N 6627503000-009, 6627503000-011, 6627503000-021, 6627503000-023, 6627503000-025, AND 6627503000-027, FLAP ACTUATOR ASSEMBLY MICROTECNICA P/N C144487-1, C144488-1, C144487-2, C144488-2, C144487-3, AND C144488-3) - PERFORM FLUORESCENT PENETRANT INSPECTION |           |          |          |                        |           |           | Service        | ATA:27   |
|                                                                                                        | MOS/MSC                                                                                                                                                                                                                                                                                                                         | 05-Dec-19 | N/A      |          |                        |           |           | NOT APPLICABLE |          |
|                                                                                                        | HRS                                                                                                                                                                                                                                                                                                                             | 8177.8    |          |          |                        |           |           |                |          |
|                                                                                                        | AFL                                                                                                                                                                                                                                                                                                                             | 6304      |          |          |                        |           |           |                |          |
| PROC. REF: NDT PART 8/27-50-01, NDT PART 8/27-50-02PROC. REF: NDT PART 8/27-50-01, NDT PART 8/27-50-02 |                                                                                                                                                                                                                                                                                                                                 |           |          |          |                        |           |           |                |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                                                    | Unit                                                                                                                                                                                           | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition        | Warranty |
|----------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|--------------------|----------|
| ATA 27 - FLIGHT CONTROLS                                                   |                                                                                                                                                                                                |           |          |          |                        |           |           |                    |          |
| 5-19-00-W2750056                                                           | PERFORM * FLAP ACTUATOR JOINT (P/N 145673-1) - PERFORM DETAILED VISUAL INSPECTION. (REFER TO 27-50-06.) APPLY CORROSION PREVENTIVE COMPOUND (CPC) TO JOINT. (REFER TO 12-21-03.). IRN W2750056 |           |          |          |                        |           |           | Service            | ATA:27   |
|                                                                            | MOS/MSC                                                                                                                                                                                        | 05-Dec-19 | N/A      |          |                        |           |           | N/A BY PART NUMBER |          |
|                                                                            | HRS                                                                                                                                                                                            | 8177.8    |          |          |                        |           |           |                    |          |
|                                                                            | AFL                                                                                                                                                                                            | 6304      |          |          |                        |           |           |                    |          |
| PROC. REF: AMM 12-21-03, AMM 27-50-06PROC. REF: AMM 12-21-03, AMM 27-50-06 |                                                                                                                                                                                                |           |          |          |                        |           |           |                    |          |
| 5-19-01-AA2760021-LEFT                                                     | LEFT SPOILER HYDRAULIC PRESSURE SWIVEL - REPLACE                                                                                                                                               |           |          |          |                        |           |           | Service            | ATA:27   |
|                                                                            | MOS                                                                                                                                                                                            | 22-Jun-23 |          |          |                        |           |           |                    |          |
|                                                                            | HRS                                                                                                                                                                                            | 9258.5    | 1200     |          | 10458.5                |           | 789.4     |                    |          |
|                                                                            | AFL                                                                                                                                                                                            | 7100      |          |          |                        |           |           |                    |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                                                                                                                                                                                |           |          |          |                        |           |           |                    |          |
| 5-19-01-AA2760021-LEFT                                                     | LEFT SPOILER HYDRAULIC RETURN SWIVEL - REPLACE                                                                                                                                                 |           |          |          |                        |           |           | Service            | ATA:27   |
|                                                                            | MOS                                                                                                                                                                                            | 22-Jun-23 |          |          |                        |           |           |                    |          |
|                                                                            | HRS                                                                                                                                                                                            | 9258.5    | 1200     |          | 10458.5                |           | 789.4     |                    |          |
|                                                                            | AFL                                                                                                                                                                                            | 7100      |          |          |                        |           |           |                    |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                                                                                                                                                                                |           |          |          |                        |           |           |                    |          |
| 5-19-01-AA2760021-RIGHT                                                    | RIGHT SPOILER HYDRAULIC PRESSURE SWIVEL - REPLACE                                                                                                                                              |           |          |          |                        |           |           | Service            | ATA:27   |
|                                                                            | MOS                                                                                                                                                                                            | 22-Jun-23 |          |          |                        |           |           |                    |          |
|                                                                            | HRS                                                                                                                                                                                            | 9258.5    | 1200     |          | 10458.5                |           | 789.4     |                    |          |
|                                                                            | AFL                                                                                                                                                                                            | 7100      |          |          |                        |           |           |                    |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                                                                                                                                                                                |           |          |          |                        |           |           |                    |          |
| 5-19-01-AA2760021-RIGHT                                                    | RIGHT SPOILER HYDRAULIC RETURN SWIVEL - REPLACE                                                                                                                                                |           |          |          |                        |           |           | Service            | ATA:27   |
|                                                                            | MOS                                                                                                                                                                                            | 22-Jun-23 |          |          |                        |           |           |                    |          |
|                                                                            | HRS                                                                                                                                                                                            | 9258.5    | 1200     |          | 10458.5                |           | 789.4     |                    |          |
|                                                                            | AFL                                                                                                                                                                                            | 7100      |          |          |                        |           |           |                    |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                                                                                                                                                                                |           |          |          |                        |           |           |                    |          |
| 5-19-01-R2710041                                                           | REPLACE * AILERON SPINDLE (P/N 4527102103-001). (IRN R2710041)                                                                                                                                 |           |          |          |                        |           |           | Service            | ATA:27   |
|                                                                            | MOS                                                                                                                                                                                            | 30-Mar-21 | 120      |          | 30-Mar-31              |           | 2188 d    |                    |          |
|                                                                            | HRS                                                                                                                                                                                            | 8414.4    |          |          |                        |           |           |                    |          |
|                                                                            | AFL                                                                                                                                                                                            | 6463      |          |          |                        |           |           |                    |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                        | Unit    | C/W                                                             | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition    | Warranty |
|------------------------------------------------|---------|-----------------------------------------------------------------|----------|----------|------------------------|-----------|-----------|----------------|----------|
| ATA 27 - FLIGHT CONTROLS                       |         |                                                                 |          |          |                        |           |           |                |          |
| PROC. REF: AMM 27-10-07PROC. REF: AMM 27-10-07 |         |                                                                 |          |          |                        |           |           |                |          |
|                                                |         |                                                                 |          |          |                        |           |           |                |          |
| 5-19-01-W2750055                               |         | * FLAP ACTUATOR JOINT (P/N 145673-1) (IRN W2750055) REPLACEMENT |          |          |                        |           |           | Component      | ATA:27   |
| PN:159174-1                                    | MOS/MSC | 05-Dec-19                                                       | N/A      | TSN 4372 |                        |           |           | NOT APPLICABLE |          |
| SN:UNKNOWN                                     | HRS     | 8177.8                                                          |          |          |                        |           |           |                |          |
|                                                | AFL     | 6304                                                            |          |          |                        |           |           |                |          |
| PROC. REF: AMM 27-50-06PROC. REF: AMM 27-50-06 |         |                                                                 |          |          |                        |           |           |                |          |
|                                                |         |                                                                 |          |          |                        |           |           |                |          |
| A2711001 <sup>S</sup>                          |         | ** AILERON TRIM TAB CONTROL SYSTEM - PERFORM OPERATIONAL CHECK  |          |          |                        |           |           | Service        | ATA:27   |
|                                                | MOS     | 02-Aug-24                                                       | 24       |          |                        |           |           | AIRWORTHINESS  |          |
|                                                | HRS     | 9525.7                                                          | 600      |          |                        |           |           |                |          |
|                                                | AFL     | 7276                                                            |          |          |                        |           |           |                |          |
| PKG:7                                          |         |                                                                 |          |          |                        |           |           |                |          |
| PROC. REF: AMM 27-10-04PROC. REF: AMM 27-10-04 |         |                                                                 |          |          |                        |           |           |                |          |
|                                                |         |                                                                 |          |          |                        |           |           |                |          |
| A2721001 <sup>S</sup>                          |         | ** RUDDER TRIM SYSTEM - PERFORM OPERATIONAL CHECK               |          |          |                        |           |           | Service        | ATA:27   |
|                                                | MOS     | 02-Aug-24                                                       | 24       |          |                        |           |           | AIRWORTHINESS  |          |
|                                                | HRS     | 9525.7                                                          | 600      |          |                        |           |           |                |          |
|                                                | AFL     | 7276                                                            |          |          |                        |           |           |                |          |
| PKG:7                                          |         |                                                                 |          |          |                        |           |           |                |          |
| PROC. REF: AMM 27-20-00PROC. REF: AMM 27-20-00 |         |                                                                 |          |          |                        |           |           |                |          |
|                                                |         |                                                                 |          |          |                        |           |           |                |          |
| A2731002 <sup>S</sup>                          |         | ** ELEVATOR DISCONNECT SYSTEM - PERFORM OPERATIONAL CHECK       |          |          |                        |           |           | Service        | ATA:27   |
|                                                | MOS     | 02-Aug-24                                                       | 24       |          |                        |           |           | AIRWORTHINESS  |          |
|                                                | HRS     | 9525.7                                                          | 600      |          |                        |           |           |                |          |
|                                                | AFL     | 7276                                                            |          |          |                        |           |           |                |          |
| PKG:8                                          |         |                                                                 |          |          |                        |           |           |                |          |
| PROC. REF: AMM 27-30-00PROC. REF: AMM 27-30-00 |         |                                                                 |          |          |                        |           |           |                |          |
|                                                |         |                                                                 |          |          |                        |           |           |                |          |
| A2760001 <sup>S</sup>                          |         | ** SPOILER ACTUATOR CHECK VALVE - PERFORM OPERATIONAL CHECK     |          |          |                        |           |           | Service        | ATA:27   |
|                                                | MOS     | 02-Aug-24                                                       | 24       |          |                        |           |           | AIRWORTHINESS  |          |
|                                                | HRS     | 9525.7                                                          | 600      |          |                        |           |           |                |          |
|                                                | AFL     | 7276                                                            |          |          |                        |           |           |                |          |
| PKG:10                                         |         |                                                                 |          |          |                        |           |           |                |          |
| PROC. REF: AMM 27-60-04PROC. REF: AMM 27-60-04 |         |                                                                 |          |          |                        |           |           |                |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                        | Unit         | C / W                                                                                                                      | Interval | TSX / Adj. | Next Due (ENG / APU) A / C | Max Limit | Remaining | Disposition   | Warranty |
|------------------------------------------------|--------------|----------------------------------------------------------------------------------------------------------------------------|----------|------------|----------------------------|-----------|-----------|---------------|----------|
| ATA 27 - FLIGHT CONTROLS                       |              |                                                                                                                            |          |            |                            |           |           |               |          |
| A2760002                                       | <sup>S</sup> | ** SPOILER SYSTEM - PERFORM SPOILER AUTHORITY WITH FLAPS CHECK                                                             |          |            |                            |           |           | Service       | ATA:27   |
|                                                | MOS          | 02-Aug-24                                                                                                                  | 24       |            |                            |           |           | AIRWORTHINESS |          |
|                                                | HRS          | 9525.7                                                                                                                     | 600      |            |                            |           |           |               |          |
|                                                | AFL          | 7276                                                                                                                       |          |            |                            |           |           |               |          |
| PROC. REF: AMM 27-60-00PROC. REF: AMM 27-60-00 |              |                                                                                                                            |          |            |                            | PKG:10    |           |               |          |
| AA2700000                                      | <sup>S</sup> | AILERON CONTROL CABLE SYSTEM - WITH COCKPIT AND CABIN FLOORBOARDS REMOVED, PERFORM VISUAL INSPECTION OF ACCESSIBLE CABLES  |          |            |                            |           |           | Service       | ATA:27   |
|                                                | MOS          | 02-Aug-24                                                                                                                  | 24       |            |                            |           |           |               |          |
|                                                | HRS          | 9525.7                                                                                                                     | 600      |            |                            |           |           |               |          |
|                                                | AFL          | 7276                                                                                                                       |          |            |                            |           |           |               |          |
| PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00 |              |                                                                                                                            |          |            |                            | PKG:7     |           |               |          |
| AA2700001                                      | <sup>S</sup> | RUDDER CONTROL CABLE SYSTEM - WITH COCKPIT AND CABIN FLOORBOARDS REMOVED, PERFORM VISUAL INSPECTION OF ACCESSIBLE CABLES   |          |            |                            |           |           | Service       | ATA:27   |
|                                                | MOS          | 02-Aug-24                                                                                                                  | 24       |            |                            |           |           |               |          |
|                                                | HRS          | 9525.7                                                                                                                     | 600      |            |                            |           |           |               |          |
|                                                | AFL          | 7276                                                                                                                       |          |            |                            |           |           |               |          |
| PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00 |              |                                                                                                                            |          |            |                            | PKG:7     |           |               |          |
| AA2700002                                      | <sup>S</sup> | ELEVATOR CONTROL CABLE SYSTEM - WITH COCKPIT AND CABIN FLOORBOARDS REMOVED, PERFORM VISUAL INSPECTION OF ACCESSIBLE CABLES |          |            |                            |           |           | Service       | ATA:27   |
|                                                | MOS          | 02-Aug-24                                                                                                                  | 24       |            |                            |           |           |               |          |
|                                                | HRS          | 9525.7                                                                                                                     | 600      |            |                            |           |           |               |          |
|                                                | AFL          | 7276                                                                                                                       |          |            |                            |           |           |               |          |
| PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00 |              |                                                                                                                            |          |            |                            | PKG:7     |           |               |          |
| K2700007                                       |              | * AILERON CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED VISUAL INSPECTION                      |          |            |                            |           |           | Service       | ATA:27   |
|                                                | MOS          | 22-Jun-23                                                                                                                  |          |            |                            |           |           | AIRWORTHINESS |          |
|                                                | HRS          | 9258.5                                                                                                                     | 4800     |            | 14058.5                    |           | 4389.4    |               |          |
|                                                | AFL          | 7100                                                                                                                       |          |            |                            |           |           |               |          |
| PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00 |              |                                                                                                                            |          |            |                            |           |           |               |          |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C / W   (M)-Manual Due   U-User Task   Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                        | Unit                                                                                                   | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty |
|------------------------------------------------|--------------------------------------------------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|---------------|----------|
| ATA 27 - FLIGHT CONTROLS                       |                                                                                                        |           |          |          |                        |           |           |               |          |
| K2700008                                       | * ELEVATOR CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED VISUAL INSPECTION |           |          |          |                        |           |           | Service       | ATA:27   |
|                                                | MOS                                                                                                    | 22-Jun-23 |          |          |                        |           |           | AIRWORTHINESS |          |
|                                                | HRS                                                                                                    | 9258.5    | 4800     |          | 14058.5                |           | 4389.4    |               |          |
|                                                | AFL                                                                                                    | 7100      |          |          |                        |           |           |               |          |
| PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00 |                                                                                                        |           |          |          |                        |           |           |               |          |
| K2700009                                       | * RUDDER CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED VISUAL INSPECTION   |           |          |          |                        |           |           | Service       | ATA:27   |
|                                                | MOS                                                                                                    | 22-Jun-23 |          |          |                        |           |           | AIRWORTHINESS |          |
|                                                | HRS                                                                                                    | 9258.5    | 4800     |          | 14058.5                |           | 4389.4    |               |          |
|                                                | AFL                                                                                                    | 7100      |          |          |                        |           |           |               |          |
| PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00 |                                                                                                        |           |          |          |                        |           |           |               |          |
| V2712000 <sup>S</sup>                          | ** ROLL DISCONNECT SWITCHES - PERFORM OPERATIONAL CHECK.                                               |           |          |          |                        |           |           | Service       | ATA:27   |
|                                                | MOS                                                                                                    | 02-Aug-24 | 24       |          |                        |           |           | AIRWORTHINESS |          |
|                                                | HRS                                                                                                    | 9525.7    | 600      |          |                        |           |           |               |          |
|                                                | AFL                                                                                                    | 7276      |          |          |                        |           |           |               |          |
| PROC. REF: AMM 27-60-09PROC. REF: AMM 27-60-09 |                                                                                                        |           |          |          |                        |           |           |               | PKG:7    |
| W2731001 <sup>S</sup>                          | ** PITCH TRIM - PERFORM OPERATIONAL CHECK OF ELEVATOR OVERRIDE ACTUATOR                                |           |          |          |                        |           |           | Service       | ATA:27   |
|                                                | MOS                                                                                                    | 02-Aug-24 | 24       |          |                        |           |           | AIRWORTHINESS |          |
|                                                | HRS                                                                                                    | 9525.7    | 600      |          |                        |           |           |               |          |
|                                                | AFL                                                                                                    | 7276      |          |          |                        |           |           |               |          |
| PROC. REF: AMM 27-30-14PROC. REF: AMM 27-30-14 |                                                                                                        |           |          |          |                        |           |           |               | PKG:8    |
| Y2700003 <sup>S</sup>                          | AILERON CONTROL CABLE SYSTEM - PERFORM VISUAL INSPECTION OF CABLES WITHIN WING                         |           |          |          |                        |           |           | Service       | ATA:27   |
|                                                | MOS                                                                                                    | 02-Aug-24 | 24       |          |                        |           |           |               |          |
|                                                | HRS                                                                                                    | 9525.7    | 600      |          |                        |           |           |               |          |
|                                                | AFL                                                                                                    | 7276      |          |          |                        |           |           |               |          |
| PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00 |                                                                                                        |           |          |          |                        |           |           |               | PKG:10   |

?-Insufficient Information

S-Suppressed Requirement

\*-Estimated Due(New Requirement)

(EFF)-Effective C/W

(M)-Manual Due

U-User Task

Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-202502-Apr-2025 02:58 PM

| PN & SN                                        | Unit | C/W                                                                                                                                     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|------------------------------------------------|------|-----------------------------------------------------------------------------------------------------------------------------------------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 27 - FLIGHT CONTROLS                       |      |                                                                                                                                         |          |          |                        |           |           |             |          |
| Y2700004 <sup>S</sup>                          |      | RUDDER CONTROL CABLE SYSTEM - PERFORM VISUAL INSPECTION OF ACCESSIBLE UPPER AND LOWER CABLES                                            |          |          |                        |           |           | Service     | ATA:27   |
|                                                | MOS  | 02-Aug-24                                                                                                                               | 24       |          |                        |           |           |             |          |
|                                                | HRS  | 9525.7                                                                                                                                  | 600      |          |                        |           |           |             |          |
|                                                | AFL  | 7276                                                                                                                                    |          |          |                        |           |           |             |          |
| PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00 |      |                                                                                                                                         |          |          |                        |           |           |             | PKG:8    |
| Y2700005 <sup>S</sup>                          |      | ELEVATOR CONTROL CABLE SYSTEM - PERFORM VISUAL INSPECTION OF ACCESSIBLE UPPER AND LOWER CABLES                                          |          |          |                        |           |           | Service     | ATA:27   |
|                                                | MOS  | 02-Aug-24                                                                                                                               | 24       |          |                        |           |           |             |          |
|                                                | HRS  | 9525.7                                                                                                                                  | 600      |          |                        |           |           |             |          |
|                                                | AFL  | 7276                                                                                                                                    |          |          |                        |           |           |             |          |
| PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00 |      |                                                                                                                                         |          |          |                        |           |           |             | PKG:8    |
| Y2700006 <sup>S</sup>                          |      | RUDDER AND ELEVATOR CONTROL CABLES AND ASSOCIATED PULLEYS, LOCATED IN AFT PRESSURE BULKHEAD SUPPORT CHANNEL - PERFORM VISUAL INSPECTION |          |          |                        |           |           | Service     | ATA:27   |
|                                                | MOS  | 02-Aug-24                                                                                                                               | 24       |          |                        |           |           |             |          |
|                                                | HRS  | 9525.7                                                                                                                                  | 600      |          |                        |           |           |             |          |
|                                                | AFL  | 7276                                                                                                                                    |          |          |                        |           |           |             |          |
| PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00 |      |                                                                                                                                         |          |          |                        |           |           |             | PKG:9    |
| Y2710000 <sup>S</sup>                          |      | AILERONS, AILERON TRIM TAB AND VISIBLE PORTION OF RODS - PERFORM VISUAL INSPECTION                                                      |          |          |                        |           |           | Service     | ATA:27   |
|                                                | MOS  | 02-Aug-24                                                                                                                               | 24       |          |                        |           |           |             |          |
|                                                | HRS  | 9525.7                                                                                                                                  | 600      |          |                        |           |           |             |          |
|                                                | AFL  | 7276                                                                                                                                    |          |          |                        |           |           |             |          |
| PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00 |      |                                                                                                                                         |          |          |                        |           |           |             | PKG:10   |
| Y2720000 <sup>S</sup>                          |      | RUDDER - PERFORM VISUAL INSPECTION                                                                                                      |          |          |                        |           |           | Service     | ATA:27   |
|                                                | MOS  | 02-Aug-24                                                                                                                               | 12       |          |                        |           |           |             |          |
|                                                | HRS  | 9525.7                                                                                                                                  | 300      |          |                        |           |           |             |          |
|                                                | AFL  | 7276                                                                                                                                    |          |          |                        |           |           |             |          |
| PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00 |      |                                                                                                                                         |          |          |                        |           |           |             | PKG:2    |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                        | Unit | C / W                                                                                                                                                                                                                                                                   | Interval | TSX / Adj. | Next Due (ENG / APU) A / C | Max Limit | Remaining | Disposition | Warranty |
|------------------------------------------------|------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|------------|----------------------------|-----------|-----------|-------------|----------|
| ATA 27 - FLIGHT CONTROLS                       |      |                                                                                                                                                                                                                                                                         |          |            |                            |           |           |             |          |
| Y2721000 <sup>S</sup>                          |      | RUDDER TRIM TAB AND VISIBLE RODS - PERFORM VISUAL INSPECTION. NOTE: ON AIRCRAFT 45-005 THRU 45-364 NOT MODIFIED BY SB 45-27-34 AND AIRCRAFT 45-005 THRU 45-428 NOT MODIFIED PER SB 45-27-37, REPLACE THE RUDDER TRIM TAB HINGE LOWER COTTER PIN DURING THIS INSPECTION. |          |            |                            |           |           | Service     | ATA:27   |
|                                                | MOS  | 02-Aug-24                                                                                                                                                                                                                                                               | 12       |            |                            |           |           |             |          |
|                                                | HRS  | 9525.7                                                                                                                                                                                                                                                                  | 300      |            |                            |           |           |             |          |
|                                                | AFL  | 7276                                                                                                                                                                                                                                                                    |          |            |                            |           |           |             |          |
| PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00 |      |                                                                                                                                                                                                                                                                         |          |            |                            |           |           |             | PKG:2    |
|                                                |      |                                                                                                                                                                                                                                                                         |          |            |                            |           |           |             |          |
| Y2730001 <sup>S</sup>                          |      | ELEVATORS - PERFORM VISUAL INSPECTION                                                                                                                                                                                                                                   |          |            |                            |           |           | Service     | ATA:27   |
|                                                | MOS  | 02-Aug-24                                                                                                                                                                                                                                                               | 12       |            |                            |           |           |             |          |
|                                                | HRS  | 9525.7                                                                                                                                                                                                                                                                  | 300      |            |                            |           |           |             |          |
|                                                | AFL  | 7276                                                                                                                                                                                                                                                                    |          |            |                            |           |           |             |          |
| PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00 |      |                                                                                                                                                                                                                                                                         |          |            |                            |           |           |             | PKG:2    |
|                                                |      |                                                                                                                                                                                                                                                                         |          |            |                            |           |           |             |          |
| Y2730004 <sup>S</sup>                          |      | PERFORM CONTROL COLUMNS - INSPECTION. INSPECT CABLE, PULLEYS, BEARINGS, AND ELECTRICAL WIRING                                                                                                                                                                           |          |            |                            |           |           | Service     | ATA:27   |
|                                                | MOS  | 25-Nov-19                                                                                                                                                                                                                                                               | 96       |            |                            |           |           |             |          |
|                                                | HRS  | 8177.7                                                                                                                                                                                                                                                                  | 2400     |            |                            |           |           |             |          |
|                                                | AFL  | 6303                                                                                                                                                                                                                                                                    |          |            |                            |           |           |             |          |
| PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00 |      |                                                                                                                                                                                                                                                                         |          |            |                            |           |           |             | PKG:19   |
|                                                |      |                                                                                                                                                                                                                                                                         |          |            |                            |           |           |             |          |
| Y2730007 <sup>S</sup>                          |      | PERFORM AFT ELEVATOR DISCONNECT - DETAILED VISUAL INSPECTION                                                                                                                                                                                                            |          |            |                            |           |           | Service     | ATA:27   |
|                                                | MOS  | 25-Nov-19                                                                                                                                                                                                                                                               | 96       |            |                            |           |           |             |          |
|                                                | HRS  | 8177.7                                                                                                                                                                                                                                                                  | 2400     |            |                            |           |           |             |          |
|                                                | AFL  | 6303                                                                                                                                                                                                                                                                    |          |            |                            |           |           |             |          |
| PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00 |      |                                                                                                                                                                                                                                                                         |          |            |                            |           |           |             | PKG:20   |
|                                                |      |                                                                                                                                                                                                                                                                         |          |            |                            |           |           |             |          |
| Y2750000 <sup>S</sup>                          |      | FLAP DRIVE INSTALLATION - PERFORM VISUAL INSPECTION WITH FLAPS LOWERED                                                                                                                                                                                                  |          |            |                            |           |           | Service     | ATA:27   |
|                                                | MOS  | 02-Aug-24                                                                                                                                                                                                                                                               | 24       |            |                            |           |           |             |          |
|                                                | HRS  | 9525.7                                                                                                                                                                                                                                                                  | 600      |            |                            |           |           |             |          |
|                                                | AFL  | 7276                                                                                                                                                                                                                                                                    |          |            |                            |           |           |             |          |
| PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00 |      |                                                                                                                                                                                                                                                                         |          |            |                            |           |           |             | PKG:10   |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|---------|------|-----|----------|----------|------------------------|-----------|-----------|-------------|----------|
|---------|------|-----|----------|----------|------------------------|-----------|-----------|-------------|----------|

ATA 27 - FLIGHT CONTROLS

|                                                |              |                                   |     |  |  |  |  |         |        |
|------------------------------------------------|--------------|-----------------------------------|-----|--|--|--|--|---------|--------|
| Y2750001                                       | <sup>S</sup> | FLAPS - PERFORM VISUAL INSPECTION |     |  |  |  |  | Service | ATA:27 |
|                                                | MOS          | 02-Aug-24                         | 12  |  |  |  |  |         |        |
|                                                | HRS          | 9525.7                            | 300 |  |  |  |  |         |        |
|                                                | AFL          | 7276                              |     |  |  |  |  |         |        |
| PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00 |              |                                   |     |  |  |  |  |         | PKG:4  |

|                                                |              |                                                                                                                                              |     |  |  |  |  |         |        |
|------------------------------------------------|--------------|----------------------------------------------------------------------------------------------------------------------------------------------|-----|--|--|--|--|---------|--------|
| Y2750053                                       | <sup>S</sup> | FLAP DRIVE ACTUATORS - PERFORM A VISUAL INSPECTION OF THE ACTUATOR ATTACHMENT, PAYING PARTICULAR ATTENTION TO THE GIMBAL PIN RETAINING RINGS |     |  |  |  |  | Service | ATA:27 |
|                                                | MOS          | 02-Aug-24                                                                                                                                    | 24  |  |  |  |  |         |        |
|                                                | HRS          | 9525.7                                                                                                                                       | 600 |  |  |  |  |         |        |
|                                                | AFL          | 7276                                                                                                                                         |     |  |  |  |  |         |        |
| PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00 |              |                                                                                                                                              |     |  |  |  |  |         | PKG:10 |

|                                                |              |                                                                                                      |     |  |  |  |  |         |        |
|------------------------------------------------|--------------|------------------------------------------------------------------------------------------------------|-----|--|--|--|--|---------|--------|
| Y2760000                                       | <sup>S</sup> | SPOILER AND SPOILER ACTUATOR - PERFORM VISUAL INSPECTION WITH FLAPS LOWERED AND ACCESS PANELS OPENED |     |  |  |  |  | Service | ATA:27 |
|                                                | MOS          | 02-Aug-24                                                                                            | 24  |  |  |  |  |         |        |
|                                                | HRS          | 9525.7                                                                                               | 600 |  |  |  |  |         |        |
|                                                | AFL          | 7276                                                                                                 |     |  |  |  |  |         |        |
| PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00 |              |                                                                                                      |     |  |  |  |  |         | PKG:10 |

ATA 28 - FUEL

|                                                |                                        |           |     |       |  |  |  |           |        |
|------------------------------------------------|----------------------------------------|-----------|-----|-------|--|--|--|-----------|--------|
| 281001                                         | LEFT NO. 1 FUEL, EJECTOR SCAVENGE PUMP |           |     |       |  |  |  | Component | ATA:28 |
| PN:PN                                          | MOS/MSC                                | 09-Mar-01 | O/C | TSN 0 |  |  |  |           |        |
| SN:UNKNOWN                                     | HRS                                    | 0         |     | TSN 0 |  |  |  |           |        |
|                                                | AFL                                    | 0         |     | TSN 0 |  |  |  |           |        |
| PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01 |                                        |           |     |       |  |  |  |           |        |

|                                                |                                         |           |     |       |  |  |  |           |        |
|------------------------------------------------|-----------------------------------------|-----------|-----|-------|--|--|--|-----------|--------|
| 281002                                         | RIGHT NO. 1 FUEL, EJECTOR SCAVENGE PUMP |           |     |       |  |  |  | Component | ATA:28 |
| PN:PN                                          | MOS/MSC                                 | 09-Mar-01 | O/C | TSN 0 |  |  |  |           |        |
| SN:UNKNOWN                                     | HRS                                     | 0         |     | TSN 0 |  |  |  |           |        |
|                                                | AFL                                     | 0         |     | TSN 0 |  |  |  |           |        |
| PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01 |                                         |           |     |       |  |  |  |           |        |

?-Insufficient Information
 S-Suppressed Requirement
 \*-Estimated Due(New Requirement)
 (EFF)-Effective C/W
 (M)-Manual Due
 U-User Task
 Ex-Excluded Task

Status Report

Model: LEARJET 45XR    Serial: 45-145    RegNo: N942FK    HRS: 9669.1    AFL: 7372    As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                        | Unit                                    | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty            |
|------------------------------------------------|-----------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|---------------------|
| ATA 28 - FUEL                                  |                                         |           |          |          |                        |           |           |             |                     |
| 281003                                         | LEFT NO. 2 FUEL, EJECTOR SCAVENGE PUMP  |           |          |          |                        |           |           |             | Component    ATA:28 |
| PN:PN                                          | MOS/MSC                                 | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                     | HRS                                     | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                | AFL                                     | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01 |                                         |           |          |          |                        |           |           |             |                     |
| 281004                                         | RIGHT NO. 2 FUEL, EJECTOR SCAVENGE PUMP |           |          |          |                        |           |           |             | Component    ATA:28 |
| PN:PN                                          | MOS/MSC                                 | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                     | HRS                                     | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                | AFL                                     | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01 |                                         |           |          |          |                        |           |           |             |                     |
| 281005                                         | LEFT NO. 3 FUEL, EJECTOR SCAVENGE PUMP  |           |          |          |                        |           |           |             | Component    ATA:28 |
| PN:PN                                          | MOS/MSC                                 | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                     | HRS                                     | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                | AFL                                     | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01 |                                         |           |          |          |                        |           |           |             |                     |
| 281006                                         | RIGHT NO. 3 FUEL, EJECTOR SCAVENGE PUMP |           |          |          |                        |           |           |             | Component    ATA:28 |
| PN:PN                                          | MOS/MSC                                 | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                     | HRS                                     | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                | AFL                                     | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01 |                                         |           |          |          |                        |           |           |             |                     |
| 281007                                         | LEFT NO. 4 FUEL, EJECTOR SCAVENGE PUMP  |           |          |          |                        |           |           |             | Component    ATA:28 |
| PN:PN                                          | MOS/MSC                                 | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                     | HRS                                     | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                | AFL                                     | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01 |                                         |           |          |          |                        |           |           |             |                     |
| 281008                                         | RIGHT NO. 4 FUEL, EJECTOR SCAVENGE PUMP |           |          |          |                        |           |           |             | Component    ATA:28 |
| PN:PN                                          | MOS/MSC                                 | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                     | HRS                                     | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                | AFL                                     | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01 |                                         |           |          |          |                        |           |           |             |                     |

?-Insufficient Information    S-Suppressed Requirement    \*-Estimated Due(New Requirement)    (EFF)-Effective C/W    (M)-Manual Due    U-User Task    Ex-Excluded Task

Status Report

Model: LEARJET 45XR    Serial: 45-145    RegNo: N942FK    HRS: 9669.1    AFL: 7372    As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                            | Unit                                    | C / W     | Interval | TSX / Adj. | Next Due (ENG / APU) A / C | Max Limit | Remaining | Disposition | Warranty            |
|----------------------------------------------------|-----------------------------------------|-----------|----------|------------|----------------------------|-----------|-----------|-------------|---------------------|
| ATA 28 - FUEL                                      |                                         |           |          |            |                            |           |           |             |                     |
| 281009                                             | LEFT NO. 5 FUEL, EJECTOR SCAVENGE PUMP  |           |          |            |                            |           |           |             | Component    ATA:28 |
| PN:PN                                              | MOS/MSC                                 | 09-Mar-01 | O/C      | TSN 0      |                            |           |           |             |                     |
| SN:UNKNOWN                                         | HRS                                     | 0         |          | TSN 0      |                            |           |           |             |                     |
|                                                    | AFL                                     | 0         |          | TSN 0      |                            |           |           |             |                     |
| PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01     |                                         |           |          |            |                            |           |           |             |                     |
| 281010                                             | RIGHT NO. 5 FUEL, EJECTOR SCAVENGE PUMP |           |          |            |                            |           |           |             | Component    ATA:28 |
| PN:PN                                              | MOS/MSC                                 | 09-Mar-01 | O/C      | TSN 0      |                            |           |           |             |                     |
| SN:UNKNOWN                                         | HRS                                     | 0         |          | TSN 0      |                            |           |           |             |                     |
|                                                    | AFL                                     | 0         |          | TSN 0      |                            |           |           |             |                     |
| PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01     |                                         |           |          |            |                            |           |           |             |                     |
| 281031                                             | FUEL, FUSELAGE CELL                     |           |          |            |                            |           |           |             | Component    ATA:28 |
| PN:PN                                              | MOS/MSC                                 | 09-Mar-01 | O/C      | TSN 0      |                            |           |           |             |                     |
| SN:UNKNOWN                                         | HRS                                     | 0         |          | TSN 0      |                            |           |           |             |                     |
|                                                    | AFL                                     | 0         |          | TSN 0      |                            |           |           |             |                     |
| PROC. REF: AMM 28-10-02PROC. REF: AMM 28-10-02     |                                         |           |          |            |                            |           |           |             |                     |
| 281051                                             | FUEL CROSSFLOW SHUTOFF VALVE            |           |          |            |                            |           |           |             | Component    ATA:28 |
| PN:PN                                              | MOS/MSC                                 | 09-Mar-01 | O/C      | TSN 0      |                            |           |           |             |                     |
| SN:UNKNOWN                                         | HRS                                     | 0         |          | TSN 0      |                            |           |           |             |                     |
|                                                    | AFL                                     | 0         |          | TSN 0      |                            |           |           |             |                     |
| PROC. REF: AMM 28-12-02PROC. REF: AMM 28-12-02     |                                         |           |          |            |                            |           |           |             |                     |
| 281401                                             | SURGE TANK FLOAT VALVE                  |           |          |            |                            |           |           |             | Component    ATA:28 |
| PN:PN                                              | MOS/MSC                                 | 09-Mar-01 | O/C      | TSN 0      |                            |           |           |             |                     |
| SN:UNKNOWN                                         | HRS                                     | 0         |          | TSN 0      |                            |           |           |             |                     |
|                                                    | AFL                                     | 0         |          | TSN 0      |                            |           |           |             |                     |
| PROC. REF: AMM 28-11-02PROC. REF: AMM 28-11-02     |                                         |           |          |            |                            |           |           |             |                     |
| 281501                                             | LEFT FLEX FUEL HOSE ASSY                |           |          |            |                            |           |           |             | Component    ATA:28 |
| PN:244224151                                       | MOS/MSC                                 | 26-May-05 | O/C      |            |                            |           |           |             |                     |
| SN:F16806-04                                       | HRS                                     | 3623.3    |          |            |                            |           |           |             |                     |
| WC#: 28.015                                        | AFL                                     | 2739      |          |            |                            |           |           |             |                     |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                         |           |          |            |                            |           |           |             |                     |

?-Insufficient Information    S-Suppressed Requirement    \*-Estimated Due(New Requirement)    (EFF)-Effective C / W    (M)-Manual Due    U-User Task    Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                            | Unit                            | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------|---------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 28 - FUEL                                      |                                 |           |          |          |                        |           |           |             |                  |
| 281502                                             | RIGHT FLEX FUEL HOSE ASSY       |           |          |          |                        |           |           |             | Component ATA:28 |
| PN:PN                                              | MOS/MSC                         | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                             | 0         |          | TSN 0    |                        |           |           |             |                  |
| WC#: 28.015                                        | AFL                             | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                 |           |          |          |                        |           |           |             |                  |
| 281521                                             | LEFT FUEL TRANSFER CHECK VALVE  |           |          |          |                        |           |           |             | Component ATA:28 |
| PN:PN                                              | MOS/MSC                         | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                             | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                             | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 28-12-03PROC. REF: AMM 28-12-03     |                                 |           |          |          |                        |           |           |             |                  |
| 281522                                             | RIGHT FUEL TRANSFER CHECK VALVE |           |          |          |                        |           |           |             | Component ATA:28 |
| PN:PN                                              | MOS/MSC                         | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                             | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                             | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 28-12-03PROC. REF: AMM 28-12-03     |                                 |           |          |          |                        |           |           |             |                  |
| 282001                                             | LEFT FUEL SHUTOFF VALVE         |           |          |          |                        |           |           |             | Component ATA:28 |
| PN:PN                                              | MOS/MSC                         | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                             | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                             | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 28-20-06PROC. REF: AMM 28-20-06     |                                 |           |          |          |                        |           |           |             |                  |
| 282003                                             | RIGHT FUEL SHUTOFF VALVE        |           |          |          |                        |           |           |             | Component ATA:28 |
| PN:PN                                              | MOS/MSC                         | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                             | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                             | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 28-20-06PROC. REF: AMM 28-20-06     |                                 |           |          |          |                        |           |           |             |                  |
| 282011                                             | SHUTOFF - REFUEL VALVE          |           |          |          |                        |           |           |             | Component ATA:28 |
| PN:PN                                              | MOS/MSC                         | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                             | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                             | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 28-20-10PROC. REF: AMM 28-20-10     |                                 |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR    Serial: 45-145    RegNo: N942FK    HRS: 9669.1    AFL: 7372    As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                        | Unit                                            | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|------------------------------------------------|-------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 28 - FUEL                                  |                                                 |           |          |          |                        |           |           |             |          |
| 282031                                         | LEFT NO. 1 FUEL SUPPLY CHECK VALVE              |           |          |          |                        |           |           | Component   | ATA:28   |
| PN:PN                                          | MOS/MSC                                         | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS                                             | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL                                             | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 28-20-03PROC. REF: AMM 28-20-03 |                                                 |           |          |          |                        |           |           |             |          |
| 282032                                         | LEFT NO. 2 FUEL SUPPLY CHECK VALVE              |           |          |          |                        |           |           | Component   | ATA:28   |
| PN:PN                                          | MOS/MSC                                         | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS                                             | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL                                             | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 28-20-03PROC. REF: AMM 28-20-03 |                                                 |           |          |          |                        |           |           |             |          |
| 282033                                         | RIGHT NO. 1 FUEL SUPPLY CHECK VALVE             |           |          |          |                        |           |           | Component   | ATA:28   |
| PN:PN                                          | MOS/MSC                                         | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS                                             | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL                                             | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 28-20-03PROC. REF: AMM 28-20-03 |                                                 |           |          |          |                        |           |           |             |          |
| 282034                                         | RIGHT NO. 2 FUEL SUPPLY CHECK VALVE             |           |          |          |                        |           |           | Component   | ATA:28   |
| PN:PN                                          | MOS/MSC                                         | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS                                             | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL                                             | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 28-20-03PROC. REF: AMM 28-20-03 |                                                 |           |          |          |                        |           |           |             |          |
| 282037                                         | RIGHT FUEL SUPPLY SHUT-OFF (L10) VALVE ASSEMBLY |           |          |          |                        |           |           | Component   | ATA:28   |
| PN:PN                                          | MOS/MSC                                         | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS                                             | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL                                             | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 28-20-06PROC. REF: AMM 28-20-06 |                                                 |           |          |          |                        |           |           |             |          |
| 282038                                         | LEFT FUEL SUPPLY SHUT-OFF (L11) VALVE ASSEMBLY  |           |          |          |                        |           |           | Component   | ATA:28   |
| PN:PN                                          | MOS/MSC                                         | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS                                             | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL                                             | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 28-20-06PROC. REF: AMM 28-20-06 |                                                 |           |          |          |                        |           |           |             |          |

?-Insufficient Information    S-Suppressed Requirement    \*-Estimated Due(New Requirement)    (EFF)-Effective C/W    (M)-Manual Due    U-User Task    Ex-Excluded Task

Status Report

Model: LEARJET 45XR    Serial: 45-145    RegNo: N942FK    HRS: 9669.1    AFL: 7372    As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                        | Unit                                  | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty            |
|------------------------------------------------|---------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|---------------------|
| ATA 28 - FUEL                                  |                                       |           |          |          |                        |           |           |             |                     |
| 282041                                         | CONTROL - REFUELING PANEL             |           |          |          |                        |           |           |             | Component    ATA:28 |
| PN:PN                                          | MOS/MSC                               | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                     | HRS                                   | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                | AFL                                   | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: AMM 28-20-14PROC. REF: AMM 28-20-14 |                                       |           |          |          |                        |           |           |             |                     |
| 282051                                         | LEFT CHECK, MOTIVE FLOW VALVE         |           |          |          |                        |           |           |             | Component    ATA:28 |
| PN:PN                                          | MOS/MSC                               | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                     | HRS                                   | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                | AFL                                   | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: AMM 28-20-05PROC. REF: AMM 28-20-05 |                                       |           |          |          |                        |           |           |             |                     |
| 282052                                         | RIGHT CHECK, MOTIVE FLOW VALVE        |           |          |          |                        |           |           |             | Component    ATA:28 |
| PN:PN                                          | MOS/MSC                               | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                     | HRS                                   | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                | AFL                                   | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: AMM 28-20-05PROC. REF: AMM 28-20-05 |                                       |           |          |          |                        |           |           |             |                     |
| 282063                                         | PRE-CHECK, SPPR VALVE                 |           |          |          |                        |           |           |             | Component    ATA:28 |
| PN:PN                                          | MOS/MSC                               | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                     | HRS                                   | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                | AFL                                   | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: AMM 28-20-12PROC. REF: AMM 28-20-12 |                                       |           |          |          |                        |           |           |             |                     |
| 282064                                         | PILOT, SPPR VALVE                     |           |          |          |                        |           |           |             | Component    ATA:28 |
| PN:PN                                          | MOS/MSC                               | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                     | HRS                                   | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                | AFL                                   | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: AMM 28-20-11PROC. REF: AMM 28-20-11 |                                       |           |          |          |                        |           |           |             |                     |
| 282075                                         | LEFT ASSEMBLY, FUEL MAIN EJECTOR PUMP |           |          |          |                        |           |           |             | Component    ATA:28 |
| PN:PN                                          | MOS/MSC                               | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                     | HRS                                   | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                | AFL                                   | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: AMM 28-20-01PROC. REF: AMM 28-20-01 |                                       |           |          |          |                        |           |           |             |                     |

?-Insufficient Information    S-Suppressed Requirement    \*-Estimated Due(New Requirement)    (EFF)-Effective C/W    (M)-Manual Due    U-User Task    Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                            | Unit                                           | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------|------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 28 - FUEL                                      |                                                |           |          |          |                        |           |           |             |                  |
| 282076                                             | RIGHT ASSEMBLY, FUEL MAIN EJECTOR PUMP         |           |          |          |                        |           |           |             | Component ATA:28 |
| PN:PN                                              | MOS/MSC                                        | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                            | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                            | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 28-20-01PROC. REF: AMM 28-20-01     |                                                |           |          |          |                        |           |           |             |                  |
| 282087                                             | LEFT FUEL, STANDBY PUMP                        |           |          |          |                        |           |           |             | Component ATA:28 |
| PN:PN                                              | MOS/MSC                                        | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                            | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                            | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 28-20-02PROC. REF: AMM 28-20-02     |                                                |           |          |          |                        |           |           |             |                  |
| 282088                                             | RIGHT FUEL, STANDBY PUMP                       |           |          |          |                        |           |           |             | Component ATA:28 |
| PN:PN                                              | MOS/MSC                                        | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                            | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                            | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 28-20-02PROC. REF: AMM 28-20-02     |                                                |           |          |          |                        |           |           |             |                  |
| 282601                                             | DEFUEL (B24) SHUTOFF VALVE                     |           |          |          |                        |           |           |             | Component ATA:28 |
| PN:PN                                              | MOS/MSC                                        | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                            | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                            | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 28-20-07PROC. REF: AMM 28-20-07     |                                                |           |          |          |                        |           |           |             |                  |
| 282602                                             | REFUEL CHECK VALVE                             |           |          |          |                        |           |           |             | Component ATA:28 |
| PN:PN                                              | MOS/MSC                                        | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                            | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                            | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 28-20-09PROC. REF: AMM 28-20-09     |                                                |           |          |          |                        |           |           |             |                  |
| 282603                                             | SINGLE POINT PRESSURE REFUELING (SPPR) ADAPTER |           |          |          |                        |           |           |             | Component ATA:28 |
| PN:PN                                              | MOS/MSC                                        | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                            | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                            | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 45XR    Serial: 45-145    RegNo: N942FK    HRS: 9669.1    AFL: 7372    As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                        | Unit    | C / W                   | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|------------------------------------------------|---------|-------------------------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 28 - FUEL                                  |         |                         |          |          |                        |           |           |             |          |
| 282815                                         |         | APU FUEL SHUTOFF VALVE  |          |          |                        |           |           | Component   | ATA:28   |
| PN:PN                                          | MOS/MSC | 09-Mar-01               | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS     | 0                       |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL     | 0                       |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 28-20-04PROC. REF: AMM 28-20-04 |         |                         |          |          |                        |           |           |             |          |
| 284001                                         |         | ASSEMBLY, FUEL C1 PROBE |          |          |                        |           |           | Component   | ATA:28   |
| PN:PN                                          | MOS/MSC | 09-Mar-01               | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS     | 0                       |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL     | 0                       |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05 |         |                         |          |          |                        |           |           |             |          |
| 284002                                         |         | FUEL C2 PROBE           |          |          |                        |           |           | Component   | ATA:28   |
| PN:10552T03Y00                                 | MOS/MSC | 22-May-06               | O/C      |          |                        |           |           |             |          |
| SN:0117                                        | HRS     | 4507.7                  |          |          |                        |           |           |             |          |
|                                                | AFL     | 3441                    |          |          |                        |           |           |             |          |
| PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05 |         |                         |          |          |                        |           |           |             |          |
| 284003                                         |         | ASSEMBLY, FUEL C3 PROBE |          |          |                        |           |           | Component   | ATA:28   |
| PN:PN                                          | MOS/MSC | 09-Mar-01               | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS     | 0                       |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL     | 0                       |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05 |         |                         |          |          |                        |           |           |             |          |
| 284004                                         |         | ASSEMBLY, FUEL C4 PROBE |          |          |                        |           |           | Component   | ATA:28   |
| PN:PN                                          | MOS/MSC | 09-Mar-01               | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS     | 0                       |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL     | 0                       |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05 |         |                         |          |          |                        |           |           |             |          |
| 284005                                         |         | ASSEMBLY, FUEL C5 PROBE |          |          |                        |           |           | Component   | ATA:28   |
| PN:PN                                          | MOS/MSC | 09-Mar-01               | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS     | 0                       |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL     | 0                       |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05 |         |                         |          |          |                        |           |           |             |          |

?-Insufficient Information    S-Suppressed Requirement    \*-Estimated Due(New Requirement)    (EFF)-Effective C/W    (M)-Manual Due    U-User Task    Ex-Excluded Task

Status Report

Model: LEARJET 45XR    Serial: 45-145    RegNo: N942FK    HRS: 9669.1    AFL: 7372    As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                        | Unit                     | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty            |
|------------------------------------------------|--------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|---------------------|
| ATA 28 - FUEL                                  |                          |           |          |          |                        |           |           |             |                     |
| 284006                                         | ASSEMBLY, FUEL C6 PROBE  |           |          |          |                        |           |           |             | Component    ATA:28 |
| PN:PN                                          | MOS/MSC                  | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                     | HRS                      | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                | AFL                      | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05 |                          |           |          |          |                        |           |           |             |                     |
| 284008                                         | FUEL C8 PROBE            |           |          |          |                        |           |           |             | Component    ATA:28 |
| PN:PN                                          | MOS/MSC                  | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                     | HRS                      | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                | AFL                      | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05 |                          |           |          |          |                        |           |           |             |                     |
| 284009                                         | ASSEMBLY, FUEL C9 PROBE  |           |          |          |                        |           |           |             | Component    ATA:28 |
| PN:10552T03Y00                                 | MOS/MSC                  | 22-May-06 | O/C      |          |                        |           |           |             |                     |
| SN:7262                                        | HRS                      | 4507.7    |          |          |                        |           |           |             |                     |
|                                                | AFL                      | 3441      |          |          |                        |           |           |             |                     |
| PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05 |                          |           |          |          |                        |           |           |             |                     |
| 284010                                         | ASSEMBLY, FUEL C10 PROBE |           |          |          |                        |           |           |             | Component    ATA:28 |
| PN:PN                                          | MOS/MSC                  | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                     | HRS                      | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                | AFL                      | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05 |                          |           |          |          |                        |           |           |             |                     |
| 284011                                         | ASSEMBLY, FUEL C11 PROBE |           |          |          |                        |           |           |             | Component    ATA:28 |
| PN:PN                                          | MOS/MSC                  | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                     | HRS                      | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                | AFL                      | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05 |                          |           |          |          |                        |           |           |             |                     |
| 284012                                         | ASSEMBLY, FUEL C12 PROBE |           |          |          |                        |           |           |             | Component    ATA:28 |
| PN:6628408000-009                              | MOS/MSC                  | 04-Jul-07 | O/C      |          |                        |           |           |             |                     |
| SN:B408                                        | HRS                      | 5595.25   |          |          |                        |           |           |             |                     |
|                                                | AFL                      | 4268      |          |          |                        |           |           |             |                     |
| PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05 |                          |           |          |          |                        |           |           |             |                     |

?-Insufficient Information    S-Suppressed Requirement    \*-Estimated Due(New Requirement)    (EFF)-Effective C/W    (M)-Manual Due    U-User Task    Ex-Excluded Task

Status Report

Model: LEARJET 45XR    Serial: 45-145    RegNo: N942FK    HRS: 9669.1    AFL: 7372    As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                        | Unit                     | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty            |
|------------------------------------------------|--------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|---------------------|
| ATA 28 - FUEL                                  |                          |           |          |          |                        |           |           |             |                     |
| 284013                                         | ASSEMBLY, FUEL C13 PROBE |           |          |          |                        |           |           |             | Component    ATA:28 |
| PN:PN                                          | MOS/MSC                  | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                     | HRS                      | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                | AFL                      | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05 |                          |           |          |          |                        |           |           |             |                     |
| 284014                                         | ASSEMBLY, FUEL C14 PROBE |           |          |          |                        |           |           |             | Component    ATA:28 |
| PN:PN                                          | MOS/MSC                  | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                     | HRS                      | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                | AFL                      | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05 |                          |           |          |          |                        |           |           |             |                     |
| 284015                                         | FUEL C15 PROBE           |           |          |          |                        |           |           |             | Component    ATA:28 |
| PN:PN                                          | MOS/MSC                  | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                     | HRS                      | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                | AFL                      | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05 |                          |           |          |          |                        |           |           |             |                     |
| 284016                                         | ASSEMBLY, FUEL C16 PROBE |           |          |          |                        |           |           |             | Component    ATA:28 |
| PN:PN                                          | MOS/MSC                  | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                     | HRS                      | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                | AFL                      | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05 |                          |           |          |          |                        |           |           |             |                     |
| 284017                                         | FUEL C17 PROBE           |           |          |          |                        |           |           |             | Component    ATA:28 |
| PN:PN                                          | MOS/MSC                  | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                     | HRS                      | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                | AFL                      | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05 |                          |           |          |          |                        |           |           |             |                     |
| 284033                                         | FUSELAGE FUEL PROBE      |           |          |          |                        |           |           |             | Component    ATA:28 |
| PN:PN                                          | MOS/MSC                  | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                     | HRS                      | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                | AFL                      | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05 |                          |           |          |          |                        |           |           |             |                     |

?-Insufficient Information    S-Suppressed Requirement    \*-Estimated Due(New Requirement)    (EFF)-Effective C/W    (M)-Manual Due    U-User Task    Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                        | Unit                                  | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|------------------------------------------------|---------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 28 - FUEL                                  |                                       |           |          |          |                        |           |           |             |                  |
| 284035                                         | NO. 1 FUEL, LOW PRESSURE (S21) SWITCH |           |          |          |                        |           |           |             | Component ATA:28 |
| PN:PN                                          | MOS/MSC                               | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                   | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                   | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 28-40-01PROC. REF: AMM 28-40-01 |                                       |           |          |          |                        |           |           |             |                  |
| 284036                                         | NO. 2 FUEL, LOW PRESSURE (S21) SWITCH |           |          |          |                        |           |           |             | Component ATA:28 |
| PN:PN                                          | MOS/MSC                               | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                   | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                   | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 28-40-01PROC. REF: AMM 28-40-01 |                                       |           |          |          |                        |           |           |             |                  |
| 284041                                         | LEFT FLOAT, FUEL (S19 & S20) SWITCH   |           |          |          |                        |           |           |             | Component ATA:28 |
| PN:PN                                          | MOS/MSC                               | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                   | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                   | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 28-40-02PROC. REF: AMM 28-40-02 |                                       |           |          |          |                        |           |           |             |                  |
| 284042                                         | RIGHT FLOAT, FUEL (S19 & S20) SWITCH  |           |          |          |                        |           |           |             | Component ATA:28 |
| PN:PN                                          | MOS/MSC                               | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                   | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                   | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 28-40-02PROC. REF: AMM 28-40-02 |                                       |           |          |          |                        |           |           |             |                  |
| 284045                                         | FUEL QUANTITY SIGNAL CONDITIONER      |           |          |          |                        |           |           |             | Component ATA:28 |
| PN:6628408000-023                              | MOS/MSC                               | 04-Jun-05 | O/C      |          |                        |           |           |             |                  |
| SN:B0672                                       | HRS                                   | 3648.97   |          |          |                        |           |           |             |                  |
|                                                | AFL                                   | 2757      |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 28-40-04PROC. REF: AMM 28-40-04 |                                       |           |          |          |                        |           |           |             |                  |
| 284047                                         | LEFT FUEL, LOW LEVEL SENSOR           |           |          |          |                        |           |           |             | Component ATA:28 |
| PN:PN                                          | MOS/MSC                               | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                   | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                   | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 28-40-03PROC. REF: AMM 28-40-03 |                                       |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                            | Unit                                                                                                                                         | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty |
|----------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|---------------|----------|
| ATA 28 - FUEL                                      |                                                                                                                                              |           |          |          |                        |           |           |               |          |
| 284048                                             | RIGHT FUEL, LOW LEVEL SENSOR                                                                                                                 |           |          |          |                        |           |           | Component     | ATA:28   |
| PN:PN                                              | MOS/MSC                                                                                                                                      | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |               |          |
| SN:UNKNOWN                                         | HRS                                                                                                                                          | 0         |          | TSN 0    |                        |           |           |               |          |
|                                                    | AFL                                                                                                                                          | 0         |          | TSN 0    |                        |           |           |               |          |
| PROC. REF: AMM 28-40-03PROC. REF: AMM 28-40-03     |                                                                                                                                              |           |          |          |                        |           |           |               |          |
| 5-19-00-D2820013                                   | PERFORM INITIAL CLEANING AND LEAK CHECK OF LOW PRESSURE FUEL FILTERS. (NEW AIRCRAFT 50-FLIGHT HOUR CHECK) (ZONE/ACCESS 510AL IRN # D2820013) |           |          |          |                        |           |           | Service       | ATA:28   |
|                                                    | MOS/MSC                                                                                                                                      | 30-Apr-06 | A/R      |          |                        |           |           |               |          |
|                                                    | HRS                                                                                                                                          |           |          |          |                        |           |           |               |          |
|                                                    | AFL                                                                                                                                          |           |          |          |                        |           |           |               |          |
| PROC. REF: AMM 28-20-15PROC. REF: AMM 28-20-15     |                                                                                                                                              |           |          |          |                        |           |           |               |          |
| 5-19-00-H2840001                                   | * DUAL FUEL FLOW CONVERTOR (DFFC) (P/N 10540B06F07) - PERFORM ACCEPTANCE TEST AND LOW TEMPERATURE SCREENING (IRN H2840001)                   |           |          |          |                        |           |           | Service       | ATA:28   |
|                                                    | MOS/MSC                                                                                                                                      | 09-Mar-01 | N/A      |          |                        |           |           | NOT INSTALLED |          |
|                                                    | HRS                                                                                                                                          | 0         |          |          |                        |           |           |               |          |
|                                                    | AFL                                                                                                                                          | 0         |          |          |                        |           |           |               |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                                                                                              |           |          |          |                        |           |           |               |          |
| Y2810001 <sup>S</sup>                              | WING TANKS - REMOVE FUEL TANK ACCESS PANELS AND PERFORM VISUAL INSPECTION                                                                    |           |          |          |                        |           |           | Service       | ATA:28   |
|                                                    | MOS                                                                                                                                          | 02-Aug-24 | 24       |          |                        |           |           |               |          |
|                                                    | HRS                                                                                                                                          | 9525.7    | 600      |          |                        |           |           |               |          |
|                                                    | AFL                                                                                                                                          | 7276      |          |          |                        |           |           |               |          |
| PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00     |                                                                                                                                              |           |          |          |                        |           |           |               | PKG:10   |
| Y2810002 <sup>S</sup>                              | PERFORM WING TANKS - REMOVE FUEL TANK ACCESS PANELS AND PERFORM VISUAL INSPECTION                                                            |           |          |          |                        |           |           | Service       | ATA:28   |
|                                                    | MOS                                                                                                                                          | 25-Nov-19 | 96       |          |                        |           |           |               |          |
|                                                    | HRS                                                                                                                                          | 8177.7    | 2400     |          |                        |           |           |               |          |
|                                                    | AFL                                                                                                                                          | 6303      |          |          |                        |           |           |               |          |
| PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00     |                                                                                                                                              |           |          |          |                        |           |           |               | PKG:22   |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR    Serial: 45-145    RegNo: N942FK    HRS: 9669.1    AFL: 7372    As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN | Unit | C / W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|---------|------|-------|----------|----------|------------------------|-----------|-----------|-------------|----------|
|---------|------|-------|----------|----------|------------------------|-----------|-----------|-------------|----------|

|                                                |     |                                                                                     |     |  |  |  |  |  |                   |
|------------------------------------------------|-----|-------------------------------------------------------------------------------------|-----|--|--|--|--|--|-------------------|
| ATA 28 - FUEL                                  |     |                                                                                     |     |  |  |  |  |  |                   |
| Y2820000 <sup>S</sup>                          |     | LOW PRESSURE FUEL FILTER - REMOVE AND INSPECT FOR CONTAMINATION. CLEAN IF NECESSARY |     |  |  |  |  |  | Service    ATA:28 |
|                                                | MOS | 02-Aug-24                                                                           | 24  |  |  |  |  |  |                   |
|                                                | HRS | 9525.7                                                                              | 600 |  |  |  |  |  |                   |
|                                                | AFL | 7276                                                                                |     |  |  |  |  |  |                   |
| PROC. REF: AMM 28-20-15PROC. REF: AMM 28-20-15 |     |                                                                                     |     |  |  |  |  |  |                   |
|                                                |     |                                                                                     |     |  |  |  |  |  | PKG:10            |

ATA 29 - HYDRAULIC POWER

|                                                |         |                     |     |       |  |  |  |  |                     |
|------------------------------------------------|---------|---------------------|-----|-------|--|--|--|--|---------------------|
| 291001                                         |         | HYDRAULIC RESERVOIR |     |       |  |  |  |  | Component    ATA:29 |
| PN:PN                                          | MOS/MSC | 09-Mar-01           | O/C | TSN 0 |  |  |  |  |                     |
| SN:UNKNOWN                                     | HRS     | 0                   |     | TSN 0 |  |  |  |  |                     |
|                                                | AFL     | 0                   |     | TSN 0 |  |  |  |  |                     |
| PROC. REF: AMM 29-10-02PROC. REF: AMM 29-10-02 |         |                     |     |       |  |  |  |  |                     |

|                                                |         |                            |     |       |  |  |  |  |                     |
|------------------------------------------------|---------|----------------------------|-----|-------|--|--|--|--|---------------------|
| 291012                                         |         | L8 HYDRAULIC SHUTOFF VALVE |     |       |  |  |  |  | Component    ATA:29 |
| PN:PN                                          | MOS/MSC | 09-Mar-01                  | O/C | TSN 0 |  |  |  |  |                     |
| SN:UNKNOWN                                     | HRS     | 0                          |     | TSN 0 |  |  |  |  |                     |
|                                                | AFL     | 0                          |     | TSN 0 |  |  |  |  |                     |
| PROC. REF: AMM 29-10-05PROC. REF: AMM 29-10-05 |         |                            |     |       |  |  |  |  |                     |

|                                                |         |                            |     |       |  |  |  |  |                     |
|------------------------------------------------|---------|----------------------------|-----|-------|--|--|--|--|---------------------|
| 291013                                         |         | L9 HYDRAULIC SHUTOFF VALVE |     |       |  |  |  |  | Component    ATA:29 |
| PN:PN                                          | MOS/MSC | 09-Mar-01                  | O/C | TSN 0 |  |  |  |  |                     |
| SN:UNKNOWN                                     | HRS     | 0                          |     | TSN 0 |  |  |  |  |                     |
|                                                | AFL     | 0                          |     | TSN 0 |  |  |  |  |                     |
| PROC. REF: AMM 29-10-05PROC. REF: AMM 29-10-05 |         |                            |     |       |  |  |  |  |                     |

|                                                |         |                                         |     |       |  |  |  |  |                     |
|------------------------------------------------|---------|-----------------------------------------|-----|-------|--|--|--|--|---------------------|
| 291033                                         |         | RESERVOIR PRESSURIZATION CONTROL MODULE |     |       |  |  |  |  | Component    ATA:29 |
| PN:PN                                          | MOS/MSC | 09-Mar-01                               | O/C | TSN 0 |  |  |  |  |                     |
| SN:UNKNOWN                                     | HRS     | 0                                       |     | TSN 0 |  |  |  |  |                     |
|                                                | AFL     | 0                                       |     | TSN 0 |  |  |  |  |                     |
| PROC. REF: AMM 29-10-06PROC. REF: AMM 29-10-06 |         |                                         |     |       |  |  |  |  |                     |

|                                                |         |                              |     |       |  |  |  |  |                     |
|------------------------------------------------|---------|------------------------------|-----|-------|--|--|--|--|---------------------|
| 291034                                         |         | RESERVOIR FLUID LEVEL SENSOR |     |       |  |  |  |  | Component    ATA:29 |
| PN:PN                                          | MOS/MSC | 09-Mar-01                    | O/C | TSN 0 |  |  |  |  |                     |
| SN:UNKNOWN                                     | HRS     | 0                            |     | TSN 0 |  |  |  |  |                     |
|                                                | AFL     | 0                            |     | TSN 0 |  |  |  |  |                     |
| PROC. REF: AMM 29-30-02PROC. REF: AMM 29-30-02 |         |                              |     |       |  |  |  |  |                     |

?-Insufficient Information    S-Suppressed Requirement    \*-Estimated Due(New Requirement)    (EFF)-Effective C/W    (M)-Manual Due    U-User Task    Ex-Excluded Task

Status Report

Model: LEARJET 45XR    Serial: 45-145    RegNo: N942FK    HRS: 9669.1    AFL: 7372    As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                        | Unit                                         | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty            |
|------------------------------------------------|----------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|---------------------|
| ATA 29 - HYDRAULIC POWER                       |                                              |           |          |          |                        |           |           |             |                     |
| 291045                                         | NO. 1 HYDRAULIC, ENGINE DRIVEN PUMP          |           |          |          |                        |           |           |             | Component    ATA:29 |
| PN:PN                                          | MOS/MSC                                      | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                     | HRS                                          | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                | AFL                                          | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: AMM 29-10-01PROC. REF: AMM 29-10-01 |                                              |           |          |          |                        |           |           |             |                     |
| 291046                                         | NO. 2 HYDRAULIC, ENGINE DRIVEN PUMP          |           |          |          |                        |           |           |             | Component    ATA:29 |
| PN:PN                                          | MOS/MSC                                      | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                     | HRS                                          | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                | AFL                                          | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: AMM 29-10-01PROC. REF: AMM 29-10-01 |                                              |           |          |          |                        |           |           |             |                     |
| 291051                                         | NO. 1 PRESSURE, MAIN HYDRAULIC SYSTEM SWITCH |           |          |          |                        |           |           |             | Component    ATA:29 |
| PN:6629101004-001                              | MOS/MSC                                      | 11-Jun-16 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:1452                                        | HRS                                          | 7630.1    |          | TSN 0    |                        |           |           |             |                     |
|                                                | AFL                                          | 5823      |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: AMM 29-30-03PROC. REF: AMM 29-30-03 |                                              |           |          |          |                        |           |           |             |                     |
| 291052                                         | NO. 2 PRESSURE, MAIN HYDRAULIC SYSTEM SWITCH |           |          |          |                        |           |           |             | Component    ATA:29 |
| PN:PN                                          | MOS/MSC                                      | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                     | HRS                                          | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                | AFL                                          | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: AMM 29-30-03PROC. REF: AMM 29-30-03 |                                              |           |          |          |                        |           |           |             |                     |
| 291057                                         | MAIN HYDRAULIC SYSTEM ACCUMULATOR            |           |          |          |                        |           |           |             | Component    ATA:29 |
| PN:88746-1                                     | MOS/MSC                                      | 28-Jan-07 | O/C      |          |                        |           |           |             |                     |
| SN:424                                         | HRS                                          | 5192.28   |          |          |                        |           |           |             |                     |
|                                                | AFL                                          | 3977      |          |          |                        |           |           |             |                     |
| PROC. REF: AMM 29-10-04PROC. REF: AMM 29-10-04 |                                              |           |          |          |                        |           |           |             |                     |
| 291059                                         | MAIN HYDRAULIC FILTER MANIFOLD               |           |          |          |                        |           |           |             | Component    ATA:29 |
| PN:PN                                          | MOS/MSC                                      | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                     | HRS                                          | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                | AFL                                          | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: AMM 29-10-03PROC. REF: AMM 29-10-03 |                                              |           |          |          |                        |           |           |             |                     |

?-Insufficient Information    S-Suppressed Requirement    \*-Estimated Due(New Requirement)    (EFF)-Effective C/W    (M)-Manual Due    U-User Task    Ex-Excluded Task

Status Report

Model: LEARJET 45XR    Serial: 45-145    RegNo: N942FK    HRS: 9669.1    AFL: 7372    As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                        | Unit                                              | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty            |
|------------------------------------------------|---------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|---------------------|
| ATA 29 - HYDRAULIC POWER                       |                                                   |           |          |          |                        |           |           |             |                     |
| 291069                                         | THERMAL SHUTOFF VALVE                             |           |          |          |                        |           |           |             | Component    ATA:29 |
| PN:PN                                          | MOS/MSC                                           | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                     | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                | AFL                                               | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: AMM 29-10-07PROC. REF: AMM 29-10-07 |                                                   |           |          |          |                        |           |           |             |                     |
| 292001                                         | AUXILIARY FILTER MANIFOLD ASSEMBLY                |           |          |          |                        |           |           |             | Component    ATA:29 |
| PN:PN                                          | MOS/MSC                                           | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                     | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                | AFL                                               | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: AMM 29-20-02PROC. REF: AMM 29-20-02 |                                                   |           |          |          |                        |           |           |             |                     |
| 292011                                         | AUXILIARY HYDRAULIC PUMP ASSEMBLY                 |           |          |          |                        |           |           |             | Component    ATA:29 |
| PN:48-16-1                                     | MOS/MSC                                           | 27-Feb-23 | O/C      | TSO 0    |                        |           |           |             |                     |
| SN:ELE0600A                                    | HRS                                               | 9186.7    |          | TSO 0    |                        |           |           |             |                     |
|                                                | AFL                                               | 7047      |          | TSO 0    |                        |           |           |             |                     |
| PROC. REF: AMM 29-20-01PROC. REF: AMM 29-20-01 |                                                   |           |          |          |                        |           |           |             |                     |
| 292012                                         | AUXILIARY HYDRAULIC PUMP                          |           |          |          |                        |           |           |             | Component    ATA:29 |
| PN:6629201000-015                              | MOS/MSC                                           | 11-Jun-16 | O/C      |          |                        |           |           |             |                     |
| SN:K0153                                       | HRS                                               | 7630.1    |          |          |                        |           |           |             |                     |
|                                                | AFL                                               | 5823      |          |          |                        |           |           |             |                     |
| PROC. REF: AMM 29-20-01PROC. REF: AMM 29-20-01 |                                                   |           |          |          |                        |           |           |             |                     |
| 292013                                         | AUXILIARY HYDRAULIC PUMP ELECTRIC MOTOR           |           |          |          |                        |           |           |             | Component    ATA:29 |
| PN:6629201000-011                              | MOS/MSC                                           | 11-Jun-16 | O/C      | TSR 0    |                        |           |           |             |                     |
| SN:ELE0/094                                    | HRS                                               | 7630.1    |          | TSR 0    |                        |           |           |             |                     |
|                                                | AFL                                               | 5823      |          | TSR 0    |                        |           |           |             |                     |
| PROC. REF: AMM 29-20-04PROC. REF: AMM 29-20-04 |                                                   |           |          |          |                        |           |           |             |                     |
| 292025                                         | AUXILIARY PRESSURE, HYDRAULIC SYSTEM (S29) SWITCH |           |          |          |                        |           |           |             | Component    ATA:29 |
| PN:6629101004-001                              | MOS/MSC                                           | 11-Jun-16 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:1226                                        | HRS                                               | 7630.1    |          | TSN 0    |                        |           |           |             |                     |
|                                                | AFL                                               | 5823      |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: AMM 29-30-03PROC. REF: AMM 29-30-03 |                                                   |           |          |          |                        |           |           |             |                     |

?-Insufficient Information    S-Suppressed Requirement    \*-Estimated Due(New Requirement)    (EFF)-Effective C/W    (M)-Manual Due    U-User Task    Ex-Excluded Task



# Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9669.1
 AFL: 7372
 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                            | Unit                                                                                        | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------|---------------------------------------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 29 - HYDRAULIC POWER                           |                                                                                             |           |          |          |                        |           |           |             |                  |
| 292401                                             | AUXILIARY HUDRAULIC PRESSURE CHECK VALVE                                                    |           |          |          |                        |           |           |             | Component ATA:29 |
| PN:PN                                              | MOS/MSC                                                                                     | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                                                                         | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                                                                         | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                                             |           |          |          |                        |           |           |             |                  |
| 293001                                             | GROUND SERVICE CONTROL BOX                                                                  |           |          |          |                        |           |           |             | Component ATA:29 |
| PN:PN                                              | MOS/MSC                                                                                     | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                                                                         | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                                                                         | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 29-30-01PROC. REF: AMM 29-30-01     |                                                                                             |           |          |          |                        |           |           |             |                  |
| 293011                                             | HYDRAULIC PRESSURE TRANSDUCER                                                               |           |          |          |                        |           |           |             | Component ATA:29 |
| PN:PN                                              | MOS/MSC                                                                                     | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                                                                         | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                                                                         | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 29-30-04PROC. REF: AMM 29-30-04     |                                                                                             |           |          |          |                        |           |           |             |                  |
| 5-19-01-D2910017                                   | REPLACE MAIN HYDRAULIC FILTER MANIFOLD ELEMENTS (D2910017)                                  |           |          |          |                        |           |           |             | Service ATA:29   |
|                                                    | MOS/MSC                                                                                     | 06-Jul-21 | -        |          |                        |           |           |             |                  |
|                                                    | HRS                                                                                         | 8631.2    |          |          |                        |           |           |             |                  |
|                                                    | AFL                                                                                         | 6618      |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 29-10-03PROC. REF: AMM 29-10-03     |                                                                                             |           |          |          |                        |           |           |             |                  |
| 5-19-01-D2910018                                   | REPLACE MAIN HYDRAULIC FILTER MANIFOLD ELEMENTS (D2910018)                                  |           |          |          |                        |           |           |             | Service ATA:29   |
|                                                    | MOS                                                                                         | 18-Jan-24 |          |          |                        |           |           |             |                  |
|                                                    | HRS                                                                                         | 9429.9    | 300      |          | 9729.9                 |           | 60.8      |             |                  |
|                                                    | AFL                                                                                         | 7217      |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 29-10-03PROC. REF: AMM 29-10-03     |                                                                                             |           |          |          |                        |           |           |             |                  |
| 5-19-01-O2910005                                   | REPLACE AUXILIARY HYDRAULIC FILTER MANIFOLD ELEMENTS. (REFER TO 29-20-02.) (IRN # O2910005) |           |          |          |                        |           |           |             | Service ATA:29   |
|                                                    | MOS                                                                                         | 19-May-22 |          |          |                        |           |           |             |                  |
|                                                    | HRS                                                                                         | 8995.3    | 2400     |          | 11395.3                |           | 1726.2    |             |                  |
|                                                    | AFL                                                                                         | 6902      |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 29-20-02PROC. REF: AMM 29-20-02     |                                                                                             |           |          |          |                        |           |           |             |                  |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C/W   (M)-Manual Due   U-User Task   Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                        | Unit         | C/W                                                                                              | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty       |
|------------------------------------------------|--------------|--------------------------------------------------------------------------------------------------|----------|----------|------------------------|-----------|-----------|-------------|----------------|
| ATA 29 - HYDRAULIC POWER                       |              |                                                                                                  |          |          |                        |           |           |             |                |
| Y2910003                                       | <sup>S</sup> | PERFORM HYDRAULIC COMPONENTS AND ASSOCIATED PLUMBING (AFT AREA OF REAR SPAR) - VISUAL INSPECTION |          |          |                        |           |           |             | Service ATA:29 |
|                                                | MOS          | 25-Nov-19                                                                                        | 96       |          |                        |           |           |             |                |
|                                                | HRS          | 8177.7                                                                                           | 2400     |          |                        |           |           |             |                |
|                                                | AFL          | 6303                                                                                             |          |          |                        |           |           |             |                |
| PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00 |              |                                                                                                  |          |          |                        |           |           |             |                |

PKG:19

|                                                |         |                                                        |     |     |   |  |  |  |                  |
|------------------------------------------------|---------|--------------------------------------------------------|-----|-----|---|--|--|--|------------------|
| ATA 30 - ICE AND RAIN PROTECTION               |         |                                                        |     |     |   |  |  |  |                  |
| 301006                                         |         | RELAY (P40) - ANTI-ICE VERTICAL STABILIZER. PANEL ASSY |     |     |   |  |  |  | Component ATA:30 |
| PN:PN                                          | MOS/MSC | 09-Mar-01                                              | O/C | TSN | 0 |  |  |  |                  |
| SN:UNKNOWN                                     | HRS     | 0                                                      |     | TSN | 0 |  |  |  |                  |
|                                                | AFL     | 0                                                      |     | TSN | 0 |  |  |  |                  |
| PROC. REF: AMM 30-10-06PROC. REF: AMM 30-10-06 |         |                                                        |     |     |   |  |  |  |                  |

|                                                |         |                                                  |     |     |   |  |  |  |                  |
|------------------------------------------------|---------|--------------------------------------------------|-----|-----|---|--|--|--|------------------|
| 301010                                         |         | LEFT HORIZONTAL STABILIZER CONTROL (MT47) SENSOR |     |     |   |  |  |  | Component ATA:30 |
| PN:PN                                          | MOS/MSC | 09-Mar-01                                        | O/C | TSN | 0 |  |  |  |                  |
| SN:UNKNOWN                                     | HRS     | 0                                                |     | TSN | 0 |  |  |  |                  |
|                                                | AFL     | 0                                                |     | TSN | 0 |  |  |  |                  |
| PROC. REF: AMM 30-10-05PROC. REF: AMM 30-10-05 |         |                                                  |     |     |   |  |  |  |                  |

|                                                |         |                                                   |     |  |  |  |  |  |                  |
|------------------------------------------------|---------|---------------------------------------------------|-----|--|--|--|--|--|------------------|
| 301011                                         |         | RIGHT HORIZONTAL STABILIZER CONTROL (MT46) SENSOR |     |  |  |  |  |  | Component ATA:30 |
| PN:6621000000-059                              | MOS/MSC | 03-Jun-06                                         | O/C |  |  |  |  |  |                  |
| SN:UNKNOWN                                     | HRS     | 4546.3                                            |     |  |  |  |  |  |                  |
|                                                | AFL     | 3481                                              |     |  |  |  |  |  |                  |
| PROC. REF: AMM 30-10-05PROC. REF: AMM 30-10-05 |         |                                                   |     |  |  |  |  |  |                  |

|                                                |         |                                           |     |     |   |  |  |  |                  |
|------------------------------------------------|---------|-------------------------------------------|-----|-----|---|--|--|--|------------------|
| 301051                                         |         | LEFT CHECK, ANTI-ICE (2.0 DIAMETER) VALVE |     |     |   |  |  |  | Component ATA:30 |
| PN:PN                                          | MOS/MSC | 09-Mar-01                                 | O/C | TSN | 0 |  |  |  |                  |
| SN:UNKNOWN                                     | HRS     | 0                                         |     | TSN | 0 |  |  |  |                  |
|                                                | AFL     | 0                                         |     | TSN | 0 |  |  |  |                  |
| PROC. REF: AMM 30-10-02PROC. REF: AMM 30-10-02 |         |                                           |     |     |   |  |  |  |                  |

|                                                |         |                                            |     |     |   |  |  |  |                  |
|------------------------------------------------|---------|--------------------------------------------|-----|-----|---|--|--|--|------------------|
| 301052                                         |         | RIGHT CHECK, ANTI-ICE (2.0 DIAMETER) VALVE |     |     |   |  |  |  | Component ATA:30 |
| PN:PN                                          | MOS/MSC | 09-Mar-01                                  | O/C | TSN | 0 |  |  |  |                  |
| SN:UNKNOWN                                     | HRS     | 0                                          |     | TSN | 0 |  |  |  |                  |
|                                                | AFL     | 0                                          |     | TSN | 0 |  |  |  |                  |
| PROC. REF: AMM 30-10-02PROC. REF: AMM 30-10-02 |         |                                            |     |     |   |  |  |  |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                                                    | Unit                                                         | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|--------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 30 - ICE AND RAIN PROTECTION                                           |                                                              |           |          |          |                        |           |           |             |                  |
| 301063                                                                     | LEFT ANTI-ICE PRESSURE REGULATING SHUTOFF (PRSOV L12) VALVE  |           |          |          |                        |           |           |             | Component ATA:30 |
| PN:PN                                                                      | MOS/MSC                                                      | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 30-10-01PROC. REF: AMM 30-10-01                             |                                                              |           |          |          |                        |           |           |             |                  |
| 301064                                                                     | RIGHT ANTI-ICE PRESSURE REGULATING SHUTOFF (PRSOV L13) VALVE |           |          |          |                        |           |           |             | Component ATA:30 |
| PN:PN                                                                      | MOS/MSC                                                      | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 30-10-01PROC. REF: AMM 30-10-01                             |                                                              |           |          |          |                        |           |           |             |                  |
| 301065                                                                     | LEFT SHUTTLE, ANTI-ICE VALVE                                 |           |          |          |                        |           |           |             | Component ATA:30 |
| PN:PN                                                                      | MOS/MSC                                                      | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 49-70-06, AMM 30-10-08PROC. REF: AMM 49-70-06, AMM 30-10-08 |                                                              |           |          |          |                        |           |           |             |                  |
| 301066                                                                     | RIGHT SHUTTLE, ANTI-ICE VALVE                                |           |          |          |                        |           |           |             | Component ATA:30 |
| PN:PN                                                                      | MOS/MSC                                                      | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 30-10-08PROC. REF: AMM 30-10-08                             |                                                              |           |          |          |                        |           |           |             |                  |
| 301240                                                                     | ANTI-ICE MANIFOLD ASSEMBLY                                   |           |          |          |                        |           |           |             | Component ATA:30 |
| PN:PN                                                                      | MOS/MSC                                                      | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 30-10-07PROC. REF: AMM 30-10-07                             |                                                              |           |          |          |                        |           |           |             |                  |
| 302001                                                                     | NO. 1 NACELLE INLET ANTI-ICE SHUTOFF VALVE                   |           |          |          |                        |           |           |             | Component ATA:30 |
| PN:PN                                                                      | MOS/MSC                                                      | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 30-20-01PROC. REF: AMM 30-20-01                             |                                                              |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9669.1
 AFL: 7372
 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                        | Unit                                       | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|------------------------------------------------|--------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 30 - ICE AND RAIN PROTECTION               |                                            |           |          |          |                        |           |           |             |          |
| 302002                                         | NO. 2 NACELLE INLET ANTI-ICE SHUTOFF VALVE |           |          |          |                        |           |           | Component   | ATA:30   |
| PN:PN                                          | MOS/MSC                                    | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS                                        | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL                                        | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 30-20-01PROC. REF: AMM 30-20-01 |                                            |           |          |          |                        |           |           |             |          |
| 302013                                         | NO. 1 NACELLE ANTI-ICE PRESSURE SWITCH     |           |          |          |                        |           |           | Component   | ATA:30   |
| PN:PN                                          | MOS/MSC                                    | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS                                        | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL                                        | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 30-20-02PROC. REF: AMM 30-20-02 |                                            |           |          |          |                        |           |           |             |          |
| 302014                                         | NO. 2 NACELLE ANTI-ICE PRESSURE SWITCH     |           |          |          |                        |           |           | Component   | ATA:30   |
| PN:7600020-1                                   | MOS/MSC                                    | 27-Mar-23 | O/C      |          |                        |           |           |             |          |
| SN:5769TW                                      | HRS                                        | 9209.1    |          |          |                        |           |           |             |          |
|                                                | AFL                                        | 7060      |          |          |                        |           |           |             |          |
| PROC. REF: AMM 30-20-02PROC. REF: AMM 30-20-02 |                                            |           |          |          |                        |           |           |             |          |
| 303501                                         | LEFT NOSE RELAY (P15) BOX                  |           |          |          |                        |           |           | Component   | ATA:30   |
| PN:PN                                          | MOS/MSC                                    | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS                                        | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL                                        | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 30-30-01PROC. REF: AMM 30-30-01 |                                            |           |          |          |                        |           |           |             |          |
| 303510                                         | RIGHT NOSE RELAY (P16) BOX                 |           |          |          |                        |           |           | Component   | ATA:30   |
| PN:PN                                          | MOS/MSC                                    | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS                                        | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL                                        | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 30-30-01PROC. REF: AMM 30-30-01 |                                            |           |          |          |                        |           |           |             |          |
| 304021                                         | WINDSHIELD ANTI-ICE CONTROLLER             |           |          |          |                        |           |           | Component   | ATA:30   |
| PN:PN                                          | MOS/MSC                                    | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS                                        | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL                                        | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 30-40-01PROC. REF: AMM 30-40-01 |                                            |           |          |          |                        |           |           |             |          |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C/W   (M)-Manual Due   U-User Task   Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 9669.1
AFL: 7372
As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                        | Unit                                                                                                     | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|------------------------------------------------|----------------------------------------------------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 30 - ICE AND RAIN PROTECTION               |                                                                                                          |           |          |          |                        |           |           |             |          |
| 304060                                         | NO. 1 WING SURFACE TEMPERATURE (MT42) SENSOR                                                             |           |          |          |                        |           |           | Component   | ATA:30   |
| PN:PN                                          | MOS/MSC                                                                                                  | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS                                                                                                      | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL                                                                                                      | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 30-10-03PROC. REF: AMM 30-10-03 |                                                                                                          |           |          |          |                        |           |           |             |          |
| 304061                                         | NO. 2 WING SURFACE TEMPERATURE (MT43) SENSOR                                                             |           |          |          |                        |           |           | Component   | ATA:30   |
| PN:PN                                          | MOS/MSC                                                                                                  | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS                                                                                                      | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL                                                                                                      | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 30-10-03PROC. REF: AMM 30-10-03 |                                                                                                          |           |          |          |                        |           |           |             |          |
| 304062                                         | NO. 3 WING SURFACE TEMPERATURE (MT44) SENSOR                                                             |           |          |          |                        |           |           | Component   | ATA:30   |
| PN:PN                                          | MOS/MSC                                                                                                  | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS                                                                                                      | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL                                                                                                      | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 30-10-03PROC. REF: AMM 30-10-03 |                                                                                                          |           |          |          |                        |           |           |             |          |
| 304063                                         | NO. 4 WING SURFACE TEMPERATURE (MT45) SENSOR                                                             |           |          |          |                        |           |           | Component   | ATA:30   |
| PN:PN                                          | MOS/MSC                                                                                                  | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS                                                                                                      | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL                                                                                                      | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 30-10-03PROC. REF: AMM 30-10-03 |                                                                                                          |           |          |          |                        |           |           |             |          |
| 308005                                         | ICE DETECTION PROBE                                                                                      |           |          |          |                        |           |           | Component   | ATA:30   |
| PN:PN                                          | MOS/MSC                                                                                                  | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS                                                                                                      | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL                                                                                                      | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 30-80-01PROC. REF: AMM 30-80-01 |                                                                                                          |           |          |          |                        |           |           |             |          |
| 5-19-00-AC3010006                              | BORESCOPE INSPECTION ANTI-ICE MANIFOLD ASSEMBLY. (ZONE/ACCESS 300 **IRN # AC3010006). REFER TO 30-10-07. |           |          |          |                        |           |           | Service     | ATA:30   |
|                                                | MOS                                                                                                      | 22-Jun-23 |          |          |                        |           |           |             |          |
|                                                | HRS                                                                                                      | 9258.5    | 600      |          | 9858.5                 |           | 189.4     |             |          |
|                                                | AFL                                                                                                      | 7100      |          |          |                        |           |           |             |          |
| PROC. REF: AMM 30-10-07PROC. REF: AMM 30-10-07 |                                                                                                          |           |          |          |                        |           |           |             |          |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C/W   (M)-Manual Due   U-User Task   Ex-Excluded Task

# Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                        | Unit                                                                                                                                                                                                                                              | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty |
|------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|---------------|----------|
| ATA 30 - ICE AND RAIN PROTECTION               |                                                                                                                                                                                                                                                   |           |          |          |                        |           |           |               |          |
| 5-19-00-Z3020005-LEFT                          | LEFT * ENGINE INLET ANTI-ICE TUBE ASSEMBLY FROM THE AFT INLET BULKHEAD CONNECTION POINT FORWARD TO SPRAY RING CONNECTION, PERFORM DETAILED VISUAL/BORESCOPE INSPECTION OF THE WELDS INSIDE AND OUTSIDE OF THE TUBE AT BOTH FORWARD AND AFT ENDS.  |           |          |          |                        |           |           | Service       | ATA:30   |
|                                                | MOS                                                                                                                                                                                                                                               | 02-Aug-24 |          |          |                        |           |           | AIRWORTHINESS |          |
|                                                | HRS                                                                                                                                                                                                                                               | 9525.7    | 250      |          | 9775.7                 |           | 106.6     |               |          |
|                                                | AFL                                                                                                                                                                                                                                               | 7276      |          |          |                        |           |           |               |          |
| PROC. REF: AMM 30-20-00PROC. REF: AMM 30-20-00 |                                                                                                                                                                                                                                                   |           |          |          |                        |           |           |               |          |
| 5-19-00-Z3020005-RIGHT                         | RIGHT * ENGINE INLET ANTI-ICE TUBE ASSEMBLY FROM THE AFT INLET BULKHEAD CONNECTION POINT FORWARD TO SPRAY RING CONNECTION, PERFORM DETAILED VISUAL/BORESCOPE INSPECTION OF THE WELDS INSIDE AND OUTSIDE OF THE TUBE AT BOTH FORWARD AND AFT ENDS. |           |          |          |                        |           |           | Service       | ATA:30   |
|                                                | MOS                                                                                                                                                                                                                                               | 02-Aug-24 |          |          |                        |           |           | AIRWORTHINESS |          |
|                                                | HRS                                                                                                                                                                                                                                               | 9525.7    | 250      |          | 9775.7                 |           | 106.6     |               |          |
|                                                | AFL                                                                                                                                                                                                                                               | 7276      |          |          |                        |           |           |               |          |
| PROC. REF: AMM 30-20-00PROC. REF: AMM 30-20-00 |                                                                                                                                                                                                                                                   |           |          |          |                        |           |           |               |          |
| 5-19-00-Z3020006-LEFT                          | LEFT ENGINE INLET ANTI-ICE TUBE ASSEMBLY FROM THE AFT INLET BULKHEAD CONNECTION POINT FORWARD TO SPRAY RING CONNECTION, PERFORM DETAILED VISUAL/BORESCOPE INSPECTION OF THE WELDS INSIDE AND OUTSIDE OF THE TUBE AT BOTH FORWARD AND AFT ENDS     |           |          |          |                        |           |           | Service       | ATA:30   |
|                                                | MOS/MSC                                                                                                                                                                                                                                           | 09-Mar-01 | N/A      |          |                        |           |           |               |          |
|                                                | HRS                                                                                                                                                                                                                                               | 0         |          |          |                        |           |           |               |          |
|                                                | AFL                                                                                                                                                                                                                                               | 0         |          |          |                        |           |           |               |          |
| PROC. REF: AMM 30-20-00PROC. REF: AMM 30-20-00 |                                                                                                                                                                                                                                                   |           |          |          |                        |           |           |               |          |
| 5-19-00-Z3020006-RIGHT                         | RIGHT ENGINE INLET ANTI-ICE TUBE ASSEMBLY FROM THE AFT INLET BULKHEAD CONNECTION POINT FORWARD TO SPRAY RING CONNECTION, PERFORM DETAILED VISUAL/BORESCOPE INSPECTION OF THE WELDS INSIDE AND OUTSIDE OF THE TUBE AT BOTH FORWARD AND AFT ENDS    |           |          |          |                        |           |           | Service       | ATA:30   |
|                                                | MOS/MSC                                                                                                                                                                                                                                           | 09-Mar-01 | N/A      |          |                        |           |           |               |          |
|                                                | HRS                                                                                                                                                                                                                                               | 0         |          |          |                        |           |           |               |          |
|                                                | AFL                                                                                                                                                                                                                                               | 0         |          |          |                        |           |           |               |          |
| PROC. REF: AMM 30-20-00PROC. REF: AMM 30-20-00 |                                                                                                                                                                                                                                                   |           |          |          |                        |           |           |               |          |
| A3030000 <sup>S</sup>                          | PERFORM ** PITOT/STATIC HEAT SYSTEM - OPERATIONAL CHECK                                                                                                                                                                                           |           |          |          |                        |           |           | Service       | ATA:30   |
|                                                | MOS                                                                                                                                                                                                                                               | 25-Nov-19 | 96       |          |                        |           |           | AIRWORTHINESS |          |
|                                                | HRS                                                                                                                                                                                                                                               | 8177.7    | 2400     |          |                        |           |           |               |          |
|                                                | AFL                                                                                                                                                                                                                                               | 6303      |          |          |                        |           |           |               |          |
| PROC. REF: AMM 30-30-00PROC. REF: AMM 30-30-00 |                                                                                                                                                                                                                                                   |           |          |          |                        |           |           |               |          |
| PKG:19                                         |                                                                                                                                                                                                                                                   |           |          |          |                        |           |           |               |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|---------|------|-----|----------|----------|------------------------|-----------|-----------|-------------|----------|
|---------|------|-----|----------|----------|------------------------|-----------|-----------|-------------|----------|

ATA 30 - ICE AND RAIN PROTECTION

|                                                |     |                                                          |     |  |  |  |  |               |        |
|------------------------------------------------|-----|----------------------------------------------------------|-----|--|--|--|--|---------------|--------|
| H3010000                                       | S   | ** WING/STAB ANTI-ICE SWITCH - PERFORM OPERATIONAL CHECK |     |  |  |  |  | Service       | ATA:30 |
|                                                | MOS | 02-Aug-24                                                | 24  |  |  |  |  | AIRWORTHINESS |        |
|                                                | HRS | 9525.7                                                   | 600 |  |  |  |  |               |        |
|                                                | AFL | 7276                                                     |     |  |  |  |  |               |        |
| PROC. REF: AMM 30-10-00PROC. REF: AMM 30-10-00 |     |                                                          |     |  |  |  |  |               | PKG:7  |

|                                                |     |                                                              |     |  |  |  |  |               |        |
|------------------------------------------------|-----|--------------------------------------------------------------|-----|--|--|--|--|---------------|--------|
| T3040000                                       | S   | ** PERFORM FUNCTIONAL TEST OF THE WINDSHIELD ANTI-ICE SYSTEM |     |  |  |  |  | Service       | ATA:30 |
|                                                | MOS | 02-Aug-24                                                    | 24  |  |  |  |  | AIRWORTHINESS |        |
|                                                | HRS | 9525.7                                                       | 600 |  |  |  |  |               |        |
|                                                | AFL | 7276                                                         |     |  |  |  |  |               |        |
| PROC. REF: AMM 30-40-00PROC. REF: AMM 30-40-00 |     |                                                              |     |  |  |  |  |               | PKG:7  |

|                                                    |     |                                                                                                     |     |  |  |  |  |         |        |
|----------------------------------------------------|-----|-----------------------------------------------------------------------------------------------------|-----|--|--|--|--|---------|--------|
| Y3010007                                           | S   | WING ANTI-ICE PICCOLO TUBE - PERFORM DETAILED VISUAL INSPECTION FOR CRACKS AT W.S. 43 AND W.S. 176. |     |  |  |  |  | Service | ATA:30 |
|                                                    | MOS | 02-Aug-24                                                                                           | 24  |  |  |  |  |         |        |
|                                                    | HRS | 9525.7                                                                                              | 600 |  |  |  |  |         |        |
|                                                    | AFL | 7276                                                                                                |     |  |  |  |  |         |        |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |     |                                                                                                     |     |  |  |  |  |         | PKG:10 |

ATA 31 - INDICATING/RECORDING SYSTEMS

|                                                |                                  |           |     |       |  |  |  |           |        |
|------------------------------------------------|----------------------------------|-----------|-----|-------|--|--|--|-----------|--------|
| 311001                                         | PILOT CIRCUIT BREAKER PANEL ASSY |           |     |       |  |  |  | Component | ATA:31 |
| PN:PN                                          | MOS/MSC                          | 09-Mar-01 | O/C | TSN 0 |  |  |  |           |        |
| SN:UNKNOWN                                     | HRS                              | 0         |     | TSN 0 |  |  |  |           |        |
|                                                | AFL                              | 0         |     | TSN 0 |  |  |  |           |        |
| PROC. REF: AMM 24-60-01PROC. REF: AMM 24-60-01 |                                  |           |     |       |  |  |  |           |        |

|                                                |                                    |           |     |       |  |  |  |           |        |
|------------------------------------------------|------------------------------------|-----------|-----|-------|--|--|--|-----------|--------|
| 311005                                         | COPILOT CIRCUIT BREAKER PANEL ASSY |           |     |       |  |  |  | Component | ATA:31 |
| PN:PN                                          | MOS/MSC                            | 09-Mar-01 | O/C | TSN 0 |  |  |  |           |        |
| SN:UNKNOWN                                     | HRS                                | 0         |     | TSN 0 |  |  |  |           |        |
|                                                | AFL                                | 0         |     | TSN 0 |  |  |  |           |        |
| PROC. REF: AMM 24-60-01PROC. REF: AMM 24-60-01 |                                    |           |     |       |  |  |  |           |        |

# Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9669.1
 AFL: 7372
 As Of: 01-Apr-2025
 02-Apr-2025 02:58 PM

| PN & SN                                            | Unit    | C/W       | Interval | TSX/Adj.   | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------|---------|-----------|----------|------------|------------------------|-----------|-----------|-------------|----------|
| ATA 31 - INDICATING/RECORDING SYSTEMS              |         |           |          |            |                        |           |           |             |          |
| 311601GEAR UP/DOWN S47 SWITCH                      |         |           |          |            |                        |           |           | Component   | ATA:31   |
| PN:A3-1295                                         | MOS/MSC | 12-Aug-15 | O/C      |            |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 7535.1    |          |            |                        |           |           |             |          |
|                                                    | AFL     | 5764      |          |            |                        |           |           |             |          |
| PROC. REF: AMM 32-30-02PROC. REF: AMM 32-30-02     |         |           |          |            |                        |           |           |             |          |
| 311805ENGINE FUEL CONTROL (P7) PANEL ASSY          |         |           |          |            |                        |           |           | Component   | ATA:31   |
| PN:4576108500-023                                  | MOS/MSC | 20-Jan-05 | O/C      |            |                        |           |           |             |          |
| SN:MRP645048-01                                    | HRS     | 3272.32   |          |            |                        |           |           |             |          |
|                                                    | AFL     | 2494      |          |            |                        |           |           |             |          |
| PROC. REF: AMM 31-11-05PROC. REF: AMM 31-11-05     |         |           |          |            |                        |           |           |             |          |
| 311806ENGINE/FUEL CONTROL PANEL OVERLAY            |         |           |          |            |                        |           |           | Component   | ATA:31   |
| PN:PN                                              | MOS/MSC | 09-Mar-01 | O/C      | TSN 0      |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0         |          | TSN 0      |                        |           |           |             |          |
|                                                    | AFL     | 0         |          | TSN 0      |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |         |           |          |            |                        |           |           |             |          |
| 311906FORWARD QUADRANT SWITCH PANEL (P6) OVERLAY   |         |           |          |            |                        |           |           | Component   | ATA:31   |
| PN:7631208500-015                                  | MOS/MSC | 12-Aug-15 | O/C      | TSN 173    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 7535.1    |          | TSN 7535.1 |                        |           |           |             |          |
|                                                    | AFL     | 5764      |          | TSN 5764   |                        |           |           |             |          |
| PROC. REF: AMM 31-11-04PROC. REF: AMM 31-11-04     |         |           |          |            |                        |           |           |             |          |
| 311906-1RUDDER BOOST (DS48) SWITCH                 |         |           |          |            |                        |           |           | Component   | ATA:31   |
| PN:PN                                              | MOS/MSC | 09-Mar-01 | O/C      | TSN 0      |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0         |          | TSN 0      |                        |           |           |             |          |
|                                                    | AFL     | 0         |          | TSN 0      |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |         |           |          |            |                        |           |           |             |          |
| 312001PILOT CLOCK                                  |         |           |          |            |                        |           |           | Component   | ATA:31   |
| PN:PN                                              | MOS/MSC | 09-Mar-01 | O/C      | TSN 0      |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0         |          | TSN 0      |                        |           |           |             |          |
|                                                    | AFL     | 0         |          | TSN 0      |                        |           |           |             |          |
| PROC. REF: AMM 31-21-01PROC. REF: AMM 31-21-01     |         |           |          |            |                        |           |           |             |          |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C/W   (M)-Manual Due   U-User Task   Ex-Excluded Task



# Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9669.1
 AFL: 7372
 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                            | Unit                           | C/W       | Interval | TSX/Adj.       | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty         |
|----------------------------------------------------|--------------------------------|-----------|----------|----------------|------------------------|-----------|-----------|---------------|------------------|
| ATA 31 - INDICATING/RECORDING SYSTEMS              |                                |           |          |                |                        |           |           |               |                  |
| 312002                                             | COPILOT CLOCK                  |           |          |                |                        |           |           |               | Component ATA:31 |
| PN:M850-5V-LA                                      | MOS/MSC                        | 14-Dec-10 | O/C      | TSN 0          |                        |           |           |               |                  |
| SN:A5231                                           | HRS                            | 6457.2    |          | TSN 0          |                        |           |           |               |                  |
|                                                    | AFL                            | 4944      |          | TSN 0          |                        |           |           |               |                  |
| PROC. REF: AMM 31-21-01PROC. REF: AMM 31-21-01     |                                |           |          |                |                        |           |           |               |                  |
| 312011                                             | PILOTS DIGITAL CLOCK BATTERY   |           |          |                |                        |           |           |               | Component ATA:31 |
| PN:E90                                             | MOS                            | 03-Feb-25 | 12       | TSN 0, Adj 11d | 14-Feb-26              |           | 318 d     | LIFE LIMIT    |                  |
| SN:NA                                              | HRS                            | 9605.4    |          | TSN 0          |                        |           |           |               |                  |
|                                                    | AFL                            | 7333      |          | TSN 0          |                        |           |           |               |                  |
| PROC. REF: AMM 31-21-02PROC. REF: AMM 31-21-02     |                                |           |          |                |                        |           |           |               |                  |
| 312012                                             | COPILOTS DIGITAL CLOCK BATTERY |           |          |                |                        |           |           |               | Component ATA:31 |
| PN:E90                                             | MOS                            | 03-Feb-25 | 12       | TSN 0, Adj 11d | 14-Feb-26              |           | 318 d     | LIFE LIMIT    |                  |
| SN:NA                                              | HRS                            | 9605.4    |          | TSN 0          |                        |           |           |               |                  |
|                                                    | AFL                            | 7333      |          | TSN 0          |                        |           |           |               |                  |
| PROC. REF: AMM 31-21-02PROC. REF: AMM 31-21-02     |                                |           |          |                |                        |           |           |               |                  |
| 313001                                             | FLIGHT DATA RECORDER           |           |          |                |                        |           |           |               | Component ATA:31 |
| PN:PN                                              | MOS/MSC                        | 09-Mar-01 | O/C      | TSN 0          |                        |           |           |               |                  |
| SN:UNKNOWN                                         | HRS                            | 0         |          | TSN 0          |                        |           |           |               |                  |
|                                                    | AFL                            | 0         |          | TSN 0          |                        |           |           |               |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                |           |          |                |                        |           |           |               |                  |
| 313001A                                            | DOWNLOAD FLIGHT DATA RECORDER  |           |          |                |                        |           |           |               | Service ATA:31   |
| PN:PN                                              | MOS/MSC                        | 09-Mar-01 | N/R      |                |                        |           |           | CUSTOMER CODE |                  |
| SN:UNKNOWN                                         | HRS                            | 0         |          |                |                        |           |           |               |                  |
|                                                    | AFL                            | 0         |          |                |                        |           |           |               |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                |           |          |                |                        |           |           |               |                  |
| 313003                                             | FDR ACCELEROMETER              |           |          |                |                        |           |           |               | Component ATA:31 |
| PN:PN                                              | MOS/MSC                        | 09-Mar-01 | O/C      | TSN 0          |                        |           |           |               |                  |
| SN:UNKNOWN                                         | HRS                            | 0         |          | TSN 0          |                        |           |           |               |                  |
|                                                    | AFL                            | 0         |          | TSN 0          |                        |           |           |               |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                |           |          |                |                        |           |           |               |                  |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C/W   (M)-Manual Due   U-User Task   Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                            | Unit                                        | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------|---------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 31 - INDICATING/RECORDING SYSTEMS              |                                             |           |          |          |                        |           |           |             |                  |
| 313010                                             | HOBBS METER                                 |           |          |          |                        |           |           |             | Component ATA:31 |
| PN:PN                                              | MOS/MSC                                     | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                         | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                         | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                             |           |          |          |                        |           |           |             |                  |
| 313018                                             | INERTIA, FDR SWITCH                         |           |          |          |                        |           |           |             | Component ATA:31 |
| PN:PN                                              | MOS/MSC                                     | 09-Mar-01 | A/R      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                         | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                         | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                             |           |          |          |                        |           |           |             |                  |
| 314001                                             | SELCAL DECODER                              |           |          |          |                        |           |           |             | Component ATA:31 |
| PN:PN                                              | MOS/MSC                                     | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                         | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                         | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                             |           |          |          |                        |           |           |             |                  |
| 314011                                             | NO. 1 DATA ACQUISITION (DAU) UNIT           |           |          |          |                        |           |           |             | Component ATA:31 |
| PN:7013348-931                                     | MOS/MSC                                     | 12-Aug-15 | O/C      |          |                        |           |           |             |                  |
| SN:00013220                                        | HRS                                         | 7535.1    |          |          |                        |           |           |             |                  |
|                                                    | AFL                                         | 5764      |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 31-42-01PROC. REF: AMM 31-42-01     |                                             |           |          |          |                        |           |           |             |                  |
| 314012                                             | NO. 2 DATA ACQUISITION (DAU) UNIT           |           |          |          |                        |           |           |             | Component ATA:31 |
| PN:7013348-931                                     | MOS/MSC                                     | 15-Nov-05 | O/C      |          |                        |           |           |             |                  |
| SN:00063567                                        | HRS                                         | 4035.07   |          |          |                        |           |           |             |                  |
|                                                    | AFL                                         | 3047      |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 31-42-01PROC. REF: AMM 31-42-01     |                                             |           |          |          |                        |           |           |             |                  |
| 314023                                             | NO. 1 INTEGRATED AVIONICS (IC-600) COMPUTER |           |          |          |                        |           |           |             | Component ATA:31 |
| PN:7017000-82222                                   | MOS/MSC                                     | 17-Dec-15 | O/C      |          |                        |           |           |             |                  |
| SN:02065544                                        | HRS                                         | 7546      |          |          |                        |           |           |             |                  |
|                                                    | AFL                                         | 5771      |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 31-41-01PROC. REF: AMM 31-41-01     |                                             |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                        | Unit                                         | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|------------------------------------------------|----------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 31 - INDICATING/RECORDING SYSTEMS          |                                              |           |          |          |                        |           |           |             |          |
| 314024                                         | NO. 2 INTEGRATED AVIONICS (IC-600) COMPUTER  |           |          |          |                        |           |           | Component   | ATA:31   |
| PN:7017000-82222                               | MOS/MSC                                      | 23-Nov-21 | O/C      |          |                        |           |           |             |          |
| SN:98041571                                    | HRS                                          | 8770.6    |          |          |                        |           |           |             |          |
|                                                | AFL                                          | 6752      |          |          |                        |           |           |             |          |
| PROC. REF: AMM 31-41-01PROC. REF: AMM 31-41-01 |                                              |           |          |          |                        |           |           |             |          |
| 314051                                         | NO. 1 CENTRAL COMPUTING IM-600 MEMORY MODULE |           |          |          |                        |           |           | Component   | ATA:31   |
| PN:7025973-04214                               | MOS/MSC                                      | 17-Feb-05 | O/C      |          |                        |           |           |             |          |
| SN:01080971                                    | HRS                                          | 3300.2    |          |          |                        |           |           |             |          |
|                                                | AFL                                          | 2515      |          |          |                        |           |           |             |          |
| PROC. REF: AMM 31-41-02PROC. REF: AMM 31-41-02 |                                              |           |          |          |                        |           |           |             |          |
| 314052                                         | NO. 2 CENTRAL COMPUTING IM-600 MEMORY MODULE |           |          |          |                        |           |           | Component   | ATA:31   |
| PN:7025973-04214                               | MOS/MSC                                      | 17-Feb-05 | O/C      |          |                        |           |           |             |          |
| SN:01080922                                    | HRS                                          | 3300.2    |          |          |                        |           |           |             |          |
|                                                | AFL                                          | 2515      |          |          |                        |           |           |             |          |
| PROC. REF: AMM 31-41-02PROC. REF: AMM 31-41-02 |                                              |           |          |          |                        |           |           |             |          |
| 315001                                         | CREW WARNING PANEL ASSEMBLY                  |           |          |          |                        |           |           | Component   | ATA:31   |
| PN:6631508501-001                              | MOS/MSC                                      | 17-Feb-05 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:357                                         | HRS                                          | 3300.2    |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL                                          | 2515      |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 31-51-01PROC. REF: AMM 31-51-01 |                                              |           |          |          |                        |           |           |             |          |
| 316001                                         | NO. 1 DU870 COMPUTER                         |           |          |          |                        |           |           | Component   | ATA:31   |
| PN:PN                                          | MOS/MSC                                      | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS                                          | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL                                          | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 31-60-01PROC. REF: AMM 31-60-01 |                                              |           |          |          |                        |           |           |             |          |
| 316001-1                                       | PILOT (#1) MFD CONTROLLER BEZEL              |           |          |          |                        |           |           | Component   | ATA:31   |
| PN:PN                                          | MOS/MSC                                      | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS                                          | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL                                          | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 31-60-01PROC. REF: AMM 31-60-01 |                                              |           |          |          |                        |           |           |             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR    Serial: 45-145    RegNo: N942FK    HRS: 9669.1    AFL: 7372    As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                        | Unit                              | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|------------------------------------------------|-----------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 31 - INDICATING/RECORDING SYSTEMS          |                                   |           |          |          |                        |           |           |             |          |
| 316002                                         | NO. 2 DU870 COMPUTER              |           |          |          |                        |           |           | Component   | ATA:31   |
| PN:PN                                          | MOS/MSC                           | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS                               | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL                               | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 31-60-01PROC. REF: AMM 31-60-01 |                                   |           |          |          |                        |           |           |             |          |
| 316002-1                                       | PILOT (#2) MFD CONTROLLER BEZEL   |           |          |          |                        |           |           | Component   | ATA:31   |
| PN:PN                                          | MOS/MSC                           | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS                               | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL                               | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 31-60-01PROC. REF: AMM 31-60-01 |                                   |           |          |          |                        |           |           |             |          |
| 316003                                         | NO. 3 DU870 COMPUTER              |           |          |          |                        |           |           | Component   | ATA:31   |
| PN:7014300-901                                 | MOS/MSC                           | 06-Sep-22 | O/C      | TSO 0    |                        |           |           |             |          |
| SN:0203A703                                    | HRS                               | 9097.5    |          | TSO 0    |                        |           |           |             |          |
|                                                | AFL                               | 6994      |          | TSO 0    |                        |           |           |             |          |
| PROC. REF: AMM 31-60-01PROC. REF: AMM 31-60-01 |                                   |           |          |          |                        |           |           |             |          |
| 316003-1                                       | COPILOT (#3) MFD CONTROLLER BEZEL |           |          |          |                        |           |           | Component   | ATA:31   |
| PN:PN                                          | MOS/MSC                           | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS                               | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL                               | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 31-60-01PROC. REF: AMM 31-60-01 |                                   |           |          |          |                        |           |           |             |          |
| 316004                                         | NO. 4 DU870 COMPUTER              |           |          |          |                        |           |           | Component   | ATA:31   |
| PN:PN                                          | MOS/MSC                           | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS                               | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL                               | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 31-60-01PROC. REF: AMM 31-60-01 |                                   |           |          |          |                        |           |           |             |          |
| 316004-1                                       | COPILOT (#4) MFD CONTROLLER BEZEL |           |          |          |                        |           |           | Component   | ATA:31   |
| PN:PN                                          | MOS/MSC                           | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS                               | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL                               | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 31-60-01PROC. REF: AMM 31-60-01 |                                   |           |          |          |                        |           |           |             |          |

?-Insufficient Information    S-Suppressed Requirement    \*-Estimated Due(New Requirement)    (EFF)-Effective C/W    (M)-Manual Due    U-User Task    Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|---------|------|-----|----------|----------|------------------------|-----------|-----------|-------------|----------|
|---------|------|-----|----------|----------|------------------------|-----------|-----------|-------------|----------|

ATA 31 - INDICATING/RECORDING SYSTEMS

|                                                |                               |           |     |       |  |  |  |           |        |
|------------------------------------------------|-------------------------------|-----------|-----|-------|--|--|--|-----------|--------|
| 316005                                         | PILOT EFIS DISPLAY CONTROLLER |           |     |       |  |  |  | Component | ATA:31 |
| PN:PN                                          | MOS/MSC                       | 09-Mar-01 | O/C | TSN 0 |  |  |  |           |        |
| SN:UNKNOWN                                     | HRS                           | 0         |     | TSN 0 |  |  |  |           |        |
|                                                | AFL                           | 0         |     | TSN 0 |  |  |  |           |        |
| PROC. REF: AMM 31-60-02PROC. REF: AMM 31-60-02 |                               |           |     |       |  |  |  |           |        |

|                                                |                                 |           |     |       |  |  |  |           |        |
|------------------------------------------------|---------------------------------|-----------|-----|-------|--|--|--|-----------|--------|
| 316006                                         | COPILOT EFIS DISPLAY CONTROLLER |           |     |       |  |  |  | Component | ATA:31 |
| PN:PN                                          | MOS/MSC                         | 09-Mar-01 | O/C | TSN 0 |  |  |  |           |        |
| SN:UNKNOWN                                     | HRS                             | 0         |     | TSN 0 |  |  |  |           |        |
|                                                | AFL                             | 0         |     | TSN 0 |  |  |  |           |        |
| PROC. REF: AMM 31-60-02PROC. REF: AMM 31-60-02 |                                 |           |     |       |  |  |  |           |        |

|                                                    |                          |           |     |       |  |  |  |           |        |
|----------------------------------------------------|--------------------------|-----------|-----|-------|--|--|--|-----------|--------|
| 316091                                             | DATA TRANSFER, AFIS UNIT |           |     |       |  |  |  | Component | ATA:31 |
| PN:PN                                              | MOS/MSC                  | 09-Mar-01 | O/C | TSN 0 |  |  |  |           |        |
| SN:UNKNOWN                                         | HRS                      | 0         |     | TSN 0 |  |  |  |           |        |
|                                                    | AFL                      | 0         |     | TSN 0 |  |  |  |           |        |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                          |           |     |       |  |  |  |           |        |

|                                                |                                                            |           |     |  |  |  |  |               |        |
|------------------------------------------------|------------------------------------------------------------|-----------|-----|--|--|--|--|---------------|--------|
| B3100000 <sup>S</sup>                          | ** INDICATING/RECORDING SYSTEM - PERFORM OPERATIONAL CHECK |           |     |  |  |  |  | Service       | ATA:31 |
|                                                | MOS                                                        | 02-Aug-24 | 24  |  |  |  |  | AIRWORTHINESS |        |
|                                                | HRS                                                        | 9525.7    | 600 |  |  |  |  |               |        |
|                                                | AFL                                                        | 7276      |     |  |  |  |  |               |        |
| PROC. REF: AMM 31-00-00PROC. REF: AMM 31-00-00 |                                                            |           |     |  |  |  |  |               |        |
|                                                |                                                            |           |     |  |  |  |  |               | PKG:7  |

ATA 32 - LANDING GEAR

|                                                |                                                                             |           |       |       |       |  |      |            |        |
|------------------------------------------------|-----------------------------------------------------------------------------|-----------|-------|-------|-------|--|------|------------|--------|
| 320041                                         | * REPLACE LEFT UPPER MAIN LANDING GEAR LINK PIN (P/N 200-0214) IRN N3220101 |           |       |       |       |  |      | Component  | ATA:32 |
| PN:PN                                          | MOS                                                                         | 09-Mar-01 |       | TSN 0 |       |  |      | LIFE LIMIT |        |
| SN:UNKNOWN                                     | HRS                                                                         | 0         |       | TSN 0 |       |  |      |            |        |
|                                                | AFL                                                                         | 0         | 10000 | TSN 0 | 10000 |  | 2628 |            |        |
| PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01 |                                                                             |           |       |       |       |  |      |            |        |

|                                                |                                                                                |           |       |       |       |  |      |            |        |
|------------------------------------------------|--------------------------------------------------------------------------------|-----------|-------|-------|-------|--|------|------------|--------|
| 320042                                         | * REPLACE RIGHT UPPER MAIN LANDING GEAR LINK PIN (P/N 200-0214) (IRN N3220101) |           |       |       |       |  |      | Component  | ATA:32 |
| PN:PN                                          | MOS                                                                            | 09-Mar-01 |       | TSN 0 |       |  |      | LIFE LIMIT |        |
| SN:UNKNOWN                                     | HRS                                                                            | 0         |       | TSN 0 |       |  |      |            |        |
|                                                | AFL                                                                            | 0         | 10000 | TSN 0 | 10000 |  | 2628 |            |        |
| PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01 |                                                                                |           |       |       |       |  |      |            |        |

?-Insufficient Information
 S-Suppressed Requirement
 \*-Estimated Due(New Requirement)
 (EFF)-Effective C/W
 (M)-Manual Due
 U-User Task
 Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                        | Unit                                                                                               | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|------------------------------------------------|----------------------------------------------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 32 - LANDING GEAR                          |                                                                                                    |           |          |          |                        |           |           |             |                  |
| 320051                                         | * REPLACE LEFT MAIN LANDING GEAR PISTON PIN (P/N 200-0215). (IRN N3220102)                         |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:PN                                          | MOS                                                                                                | 09-Mar-01 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:UNKNOWN                                     | HRS                                                                                                | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                                                                                | 0         | 10000    | TSN 0    | 10000                  |           | 2628      |             |                  |
| PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01 |                                                                                                    |           |          |          |                        |           |           |             |                  |
| 320052                                         | * REPLACE RIGHT MAIN LANDING GEAR PISTON PIN (P/N 200-0215) (IRN N3220102) ASSEMBLY                |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:PN                                          | MOS                                                                                                | 09-Mar-01 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:UNKNOWN                                     | HRS                                                                                                | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                                                                                | 0         | 10000    | TSN 0    | 10000                  |           | 2628      |             |                  |
| PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01 |                                                                                                    |           |          |          |                        |           |           |             |                  |
| 320061                                         | * REPLACE LEFT MAIN LANDING GEAR ACTUATOR PISTON (P/N 200-0301) (IRN N3220103) (JAA IRN Q3220065)  |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:PN                                          | MOS                                                                                                | 09-Mar-01 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:UNKNOWN                                     | HRS                                                                                                | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                                                                                | 0         | 17000    | TSN 0    | 17000                  |           | 9628      |             |                  |
| PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01 |                                                                                                    |           |          |          |                        |           |           |             |                  |
| 320062                                         | * REPLACE RIGHT MAIN LANDING GEAR ACTUATOR PISTON (P/N 200-0301) (IRN N3220103) (JAA IRN Q3220065) |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:4532101000V72-002                           | MOS                                                                                                | 09-Mar-01 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:H1153                                       | HRS                                                                                                | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                                                                                | 0         | 17000    | TSN 0    | 17000                  |           | 9628      |             |                  |
| PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01 |                                                                                                    |           |          |          |                        |           |           |             |                  |
| 320071                                         | * REPLACE LEFT MAIN LANDING GEAR ACTUATOR CYLINDER (IRN N3220104) (JAA IRN Q3220066)               |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:4532101000V76-001                           | MOS                                                                                                | 09-Mar-01 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:H0155                                       | HRS                                                                                                | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                                                                                | 0         | 17000    | TSN 0    | 17000                  |           | 9628      |             |                  |
| PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01 |                                                                                                    |           |          |          |                        |           |           |             |                  |
| 320072                                         | * REPLACE RIGHT MAIN LANDING GEAR ACTUATOR CYLINDER (IRN N3220104) (JAA IRN Q3220066)              |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:4532101000V72-002                           | MOS                                                                                                | 09-Mar-01 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:H1153                                       | HRS                                                                                                | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                                                                                | 0         | 17000    | TSN 0    | 17000                  |           | 9628      |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                        | Unit                                                                                                | C/W       | Interval | TSX/Adj.          | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|------------------------------------------------|-----------------------------------------------------------------------------------------------------|-----------|----------|-------------------|------------------------|-----------|-----------|-------------|------------------|
| ATA 32 - LANDING GEAR                          |                                                                                                     |           |          |                   |                        |           |           |             |                  |
| PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01 |                                                                                                     |           |          |                   |                        |           |           |             |                  |
| 320081                                         | * REPLACE LEFT MAIN LANDING GEAR END CAP (P/N 200-0303) (IRN T3220105) (JAA IRN T3220067)           |           |          |                   |                        |           |           |             | Component ATA:32 |
| PN:200-0303-001                                | MOS                                                                                                 | 02-Aug-24 |          | TSN 0             |                        |           |           | LIFE LIMIT  |                  |
| SN:UNKNOWN                                     | HRS                                                                                                 | 9525.7    |          | TSN 0             |                        |           |           |             |                  |
|                                                | AFL                                                                                                 | 7276      | 2387     | TSN 0             | 9663                   |           | 2291      |             |                  |
| PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01 |                                                                                                     |           |          |                   |                        |           |           |             |                  |
| 320082                                         | * REPLACE RIGHT MAIN LANDING GEAR END CAP (P/N 200-0303) (IRN T3220105) (JAA IRN T3220067)          |           |          |                   |                        |           |           |             | Component ATA:32 |
| PN:200-0303-001                                | MOS                                                                                                 | 02-Aug-24 |          | TSN 0             |                        |           |           | LIFE LIMIT  |                  |
| SN:UNKNOWN                                     | HRS                                                                                                 | 9525.7    |          | TSN 0             |                        |           |           |             |                  |
|                                                | AFL                                                                                                 | 7276      | 2387     | TSN 0             | 9663                   |           | 2291      |             |                  |
| PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01 |                                                                                                     |           |          |                   |                        |           |           |             |                  |
| 320091                                         | * REPLACE LEFT MAIN LANDING GEAR ACTUATOR HOUSING (P/N 200-0304) (IRN N3220106) (JAA IRN Q3220068)  |           |          |                   |                        |           |           |             | Component ATA:32 |
| PN:200-0304-001                                | MOS                                                                                                 | 19-Dec-10 |          | TSN 0             |                        |           |           | LIFE LIMIT  |                  |
| SN:H1704                                       | HRS                                                                                                 | 6457.2    |          | TSN 0             |                        |           |           |             |                  |
|                                                | AFL                                                                                                 | 4944      | 17000    | TSN 0             | 21944                  |           | 14572     |             |                  |
| PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01 |                                                                                                     |           |          |                   |                        |           |           |             |                  |
| 320092                                         | * REPLACE RIGHT MAIN LANDING GEAR ACTUATOR HOUSING (P/N 200-0304) (IRN N3220106) (JAA IRN Q3220068) |           |          |                   |                        |           |           |             | Component ATA:32 |
| PN:4532101000V72-002                           | MOS                                                                                                 | 09-Mar-01 |          | TSN 0             |                        |           |           | LIFE LIMIT  |                  |
| SN:H1153                                       | HRS                                                                                                 | 0         |          | TSN 0             |                        |           |           |             |                  |
|                                                | AFL                                                                                                 | 0         | 17000    | TSN 0             | 17000                  |           | 9628      |             |                  |
| PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01 |                                                                                                     |           |          |                   |                        |           |           |             |                  |
| 321001                                         | * LEFT MAIN LANDING GEAR STRUT (P/N 6632101000, 200-0200) (IRN N3220012) ASSEMBLY                   |           |          |                   |                        |           |           |             | Component ATA:32 |
| PN:200-0200-013                                | MOS                                                                                                 | 30-Mar-21 |          |                   |                        |           |           | LIFE LIMIT  |                  |
| SN:H0584                                       | HRS                                                                                                 | 8414.4    |          | TSN 2110.4, TSO 0 |                        |           |           |             |                  |
|                                                | AFL                                                                                                 | 6463      | 10000    | TSN 1409, TSO 0   | 15054 (M)              |           | 7682      |             |                  |
| PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01 |                                                                                                     |           |          |                   |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                                                                                                                                                                                                                                                                                                                                            | Unit | C/W                                                                                                                                                                                                                                                                         | Interval | TSX/Adj.   | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|------------|------------------------|-----------|-----------|---------------|----------|
| ATA 32 - LANDING GEAR                                                                                                                                                                                                                                                                                                                                              |      |                                                                                                                                                                                                                                                                             |          |            |                        |           |           |               |          |
| 321001A                                                                                                                                                                                                                                                                                                                                                            |      | PERFORM SPECIAL DETAILED INSPECTION ON LEFT MAIN LANDING GEAR SHOCK STRUTS (IRN AA3220018)                                                                                                                                                                                  |          |            |                        |           |           | Service       | ATA:32   |
|                                                                                                                                                                                                                                                                                                                                                                    | MOS  | 30-Mar-21                                                                                                                                                                                                                                                                   | 96       | Adj -44d   | 14-Feb-29              |           | 1414 d    |               |          |
|                                                                                                                                                                                                                                                                                                                                                                    | HRS  | 8414.4                                                                                                                                                                                                                                                                      |          |            |                        |           |           |               |          |
|                                                                                                                                                                                                                                                                                                                                                                    | AFL  | 6463                                                                                                                                                                                                                                                                        | 6600     |            | 13063                  |           | 5691      |               |          |
| PROC. REF: NDT PART 7/32-10-01, NDT PART 7/32-10-03, NDT PART 7/32-10-04, NDT PART 8/32-10-02, NDT PART 7/32-10-05, NDT PART 7/32-10-06, NDT PART 8/32-10-01, NDT PART 8/32-10-03PROC. REF: NDT PART 7/32-10-01, NDT PART 7/32-10-03, NDT PART 7/32-10-04, NDT PART 8/32-10-02, NDT PART 7/32-10-05, NDT PART 7/32-10-06, NDT PART 8/32-10-01, NDT PART 8/32-10-03 |      |                                                                                                                                                                                                                                                                             |          |            |                        |           |           |               |          |
| 321002                                                                                                                                                                                                                                                                                                                                                             |      | * RIGHT MAIN LANDING GEAR STRUT (P/N 6632101000, 200-0200) (IRN N3220012) ASSEMBLY                                                                                                                                                                                          |          |            |                        |           |           | Component     | ATA:32   |
| PN:200-0200-014                                                                                                                                                                                                                                                                                                                                                    | MOS  | 30-Mar-21                                                                                                                                                                                                                                                                   |          |            |                        |           |           | LIFE LIMIT    |          |
| SN:H1593                                                                                                                                                                                                                                                                                                                                                           | HRS  | 8414.4                                                                                                                                                                                                                                                                      |          | TSN 2110.4 |                        |           |           |               |          |
|                                                                                                                                                                                                                                                                                                                                                                    | AFL  | 6463                                                                                                                                                                                                                                                                        | 10000    | TSN 1409   | 15054                  |           | 7682      |               |          |
| PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01                                                                                                                                                                                                                                                                                                                     |      |                                                                                                                                                                                                                                                                             |          |            |                        |           |           |               |          |
| 321002A                                                                                                                                                                                                                                                                                                                                                            |      | PERFORM SPECIAL DETAILED INSPECTION ON RIGHT MAIN LANDING GEAR SHOCK STRUTS (IRN AA3220018)                                                                                                                                                                                 |          |            |                        |           |           | Service       | ATA:32   |
|                                                                                                                                                                                                                                                                                                                                                                    | MOS  | 30-Mar-21                                                                                                                                                                                                                                                                   | 96       | Adj -44d   | 14-Feb-29              |           | 1414 d    |               |          |
|                                                                                                                                                                                                                                                                                                                                                                    | HRS  | 8414.4                                                                                                                                                                                                                                                                      |          |            |                        |           |           |               |          |
|                                                                                                                                                                                                                                                                                                                                                                    | AFL  | 6463                                                                                                                                                                                                                                                                        | 6600     |            | 13063                  |           | 5691      |               |          |
| PROC. REF: NDT PART 7/32-10-01, NDT PART 7/32-10-03, NDT PART 7/32-10-04, NDT PART 8/32-10-02, NDT PART 7/32-10-05, NDT PART 7/32-10-06, NDT PART 8/32-10-01, NDT PART 8/32-10-03PROC. REF: NDT PART 7/32-10-01, NDT PART 7/32-10-03, NDT PART 7/32-10-04, NDT PART 8/32-10-02, NDT PART 7/32-10-05, NDT PART 7/32-10-06, NDT PART 8/32-10-01, NDT PART 8/32-10-03 |      |                                                                                                                                                                                                                                                                             |          |            |                        |           |           |               |          |
| 321011                                                                                                                                                                                                                                                                                                                                                             |      | * LEFT MAIN LANDING GEAR SHOCK STRUT CYLINDER (IRN'S N3220116, Q3220137, Q3220128)                                                                                                                                                                                          |          |            |                        |           |           | Component     | ATA:32   |
| PN:200-0201-009                                                                                                                                                                                                                                                                                                                                                    | MOS  | 30-Mar-21                                                                                                                                                                                                                                                                   |          |            |                        |           |           | LIFE LIMIT    |          |
| SN:H0727                                                                                                                                                                                                                                                                                                                                                           | HRS  | 8414.4                                                                                                                                                                                                                                                                      |          | TSN 2110.4 |                        |           |           |               |          |
|                                                                                                                                                                                                                                                                                                                                                                    | AFL  | 6463                                                                                                                                                                                                                                                                        | 10000    | TSN 1409   | 15054                  |           | 7682      |               |          |
| PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01                                                                                                                                                                                                                                                                                                                     |      |                                                                                                                                                                                                                                                                             |          |            |                        |           |           |               |          |
| 321011A                                                                                                                                                                                                                                                                                                                                                            |      | ULTRASONIC-INSPECTION * LEFT MAIN LANDING GEAR SHOCK STRUT CYLINDER (IRN'S N3220116, Q3220137, Q3220128) * MLG SHOCK STRUT CYLINDER. PERFORM ULTRASONIC INSPECTION OF THE LOWER SERVICE PORT AND FORGING PARTING LINE. IRN L3220118, M3220136, P3220146, (JAA IRN L3220122) |          |            |                        |           |           | Service       | ATA:32   |
| PN:200-0201-009                                                                                                                                                                                                                                                                                                                                                    | MOS  | 27-Nov-22                                                                                                                                                                                                                                                                   |          |            |                        |           |           | AIRWORTHINESS |          |
| SN:H0727                                                                                                                                                                                                                                                                                                                                                           | HRS  | 9163.6                                                                                                                                                                                                                                                                      |          |            |                        |           |           |               |          |
|                                                                                                                                                                                                                                                                                                                                                                    | AFL  | 7031                                                                                                                                                                                                                                                                        | 600      |            | 7631                   |           | 259       |               |          |
| PROC. REF: NDT PART 4/32-10-01, NDT PART 4/32-10-00PROC. REF: NDT PART 4/32-10-01, NDT PART 4/32-10-00                                                                                                                                                                                                                                                             |      |                                                                                                                                                                                                                                                                             |          |            |                        |           |           |               |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                                                                                | Unit                                                                                                                                                                                                                                                                         | C/W       | Interval | TSX/Adj.   | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty |
|--------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|----------|------------|------------------------|-----------|-----------|---------------|----------|
| ATA 32 - LANDING GEAR                                                                                  |                                                                                                                                                                                                                                                                              |           |          |            |                        |           |           |               |          |
| 321012                                                                                                 | * RIGHT MAIN LANDING GEAR SHOCK STRUT CYLINDER (IRN'S N3220116, Q3220137, Q3220128)                                                                                                                                                                                          |           |          |            |                        |           |           | Component     | ATA:32   |
| PN:200-0201-010                                                                                        | MOS                                                                                                                                                                                                                                                                          | 30-Mar-21 |          |            |                        |           |           | LIFE LIMIT    |          |
| SN:H0755                                                                                               | HRS                                                                                                                                                                                                                                                                          | 8414.4    |          | TSN 2110.4 |                        |           |           |               |          |
|                                                                                                        | AFL                                                                                                                                                                                                                                                                          | 6463      | 10000    | TSN 1409   | 15054                  |           | 7682      |               |          |
| PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01                                                         |                                                                                                                                                                                                                                                                              |           |          |            |                        |           |           |               |          |
| 321012A                                                                                                | ULTRASONIC-INSPECTION * RIGHT MAIN LANDING GEAR SHOCK STRUT CYLINDER (IRN'S N3220116, Q3220137, Q3220128) * MLG SHOCK STRUT CYLINDER. PERFORM ULTRASONIC INSPECTION OF THE LOWER SERVICE PORT AND FORGING PARTING LINE. IRN L3220118, M3220136, P3220146, (JAA IRN L3220122) |           |          |            |                        |           |           | Service       | ATA:32   |
| PN:200-0201-010                                                                                        | MOS                                                                                                                                                                                                                                                                          | 27-Nov-22 |          |            |                        |           |           | AIRWORTHINESS |          |
| SN:H0755                                                                                               | HRS                                                                                                                                                                                                                                                                          | 9163.6    |          |            |                        |           |           |               |          |
|                                                                                                        | AFL                                                                                                                                                                                                                                                                          | 7031      | 600      |            | 7631                   |           | 259       |               |          |
| PROC. REF: NDT PART 4/32-10-01, NDT PART 4/32-10-00PROC. REF: NDT PART 4/32-10-01, NDT PART 4/32-10-00 |                                                                                                                                                                                                                                                                              |           |          |            |                        |           |           |               |          |
| 321025                                                                                                 | * LEFT MAIN LANDING GEAR SIDE-STAY ACTUATOR UPPER PIN (P/N 200-0325) ASSEMBLY                                                                                                                                                                                                |           |          |            |                        |           |           | Component     | ATA:32   |
| PN:200-0325-101                                                                                        | MOS                                                                                                                                                                                                                                                                          | 24-Jun-19 | 96       | TSN 0      | 24-Jun-27              |           | 813 d     | LIFE LIMIT    |          |
| SN:H2409                                                                                               | HRS                                                                                                                                                                                                                                                                          | 8101.1    |          | TSN 0      |                        |           |           |               |          |
|                                                                                                        | AFL                                                                                                                                                                                                                                                                          | 6233      |          | TSN 0      |                        |           |           |               |          |
| PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01                                                         |                                                                                                                                                                                                                                                                              |           |          |            |                        |           |           |               |          |
| 321025A                                                                                                | MAGNETIC PARTICLE INSPECT * LEFT MAIN LANDING GEAR SIDE-STAY ACTUATOR UPPER PIN (P/N 200-0325) ASSEMBLY * (IRN T3220024)                                                                                                                                                     |           |          |            |                        |           |           | Service       | ATA:32   |
| PN:200-0325-101                                                                                        | MOS                                                                                                                                                                                                                                                                          | 22-Jun-23 | 48       |            | 22-Jun-27              |           | 811 d     | AIRWORTHINESS |          |
| SN:H2409                                                                                               | HRS                                                                                                                                                                                                                                                                          | 9258.5    |          |            |                        |           |           |               |          |
|                                                                                                        | AFL                                                                                                                                                                                                                                                                          | 7100      |          |            |                        |           |           |               |          |
| PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01 |                                                                                                                                                                                                                                                                              |           |          |            |                        |           |           |               |          |
| 321025B                                                                                                | DETAILED VISUAL INSPECTION * LEFT MAIN LANDING GEAR SIDE-STAY ACTUATOR UPPER PIN (P/N 200-0325) ASSEMBLY * (IRN T3220135)                                                                                                                                                    |           |          |            |                        |           |           | Service       | ATA:32   |
| PN:200-0325-101                                                                                        | MOS                                                                                                                                                                                                                                                                          | 22-Jun-23 | 48       |            | 22-Jun-27              |           | 811 d     | AIRWORTHINESS |          |
| SN:H2409                                                                                               | HRS                                                                                                                                                                                                                                                                          | 9258.5    |          |            |                        |           |           |               |          |
|                                                                                                        | AFL                                                                                                                                                                                                                                                                          | 7100      |          |            |                        |           |           |               |          |
| PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00                                                         |                                                                                                                                                                                                                                                                              |           |          |            |                        |           |           |               |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                                                                                                            | Unit | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty         |
|------------------------------------------------------------------------------------------------------------------------------------|------|-----------|----------|----------|------------------------|-----------|-----------|---------------|------------------|
| ATA 32 - LANDING GEAR                                                                                                              |      |           |          |          |                        |           |           |               |                  |
| 321026 * RIGHT MAIN LANDING GEAR SIDE STAY ACTUATOR UPPER PIN (P/N 200-0325) ASSEMBLY                                              |      |           |          |          |                        |           |           |               | Component ATA:32 |
| PN:200-0325-101                                                                                                                    | MOS  | 24-Jun-19 | 96       | TSN 0    | 24-Jun-27              |           | 813 d     | LIFE LIMIT    |                  |
| SN:HER08U/5030                                                                                                                     | HRS  | 8101.1    |          | TSN 0    |                        |           |           |               |                  |
|                                                                                                                                    | AFL  | 6233      |          | TSN 0    |                        |           |           |               |                  |
| PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01                                                                                     |      |           |          |          |                        |           |           |               |                  |
| 321026A MAGNETIC PARTICLE INSPECT * RIGHT MAIN LANDING GEAR SIDE STAY ACTUATOR UPPER PIN (P/N 200-0325) ASSEMBLY * (IRN T3220024)  |      |           |          |          |                        |           |           |               | Service ATA:32   |
| PN:200-0325-101                                                                                                                    | MOS  | 22-Jun-23 | 48       |          | 22-Jun-27              |           | 811 d     | AIRWORTHINESS |                  |
| SN:HER08U/5030                                                                                                                     | HRS  | 9258.5    |          |          |                        |           |           |               |                  |
|                                                                                                                                    | AFL  | 7100      |          |          |                        |           |           |               |                  |
| PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01                             |      |           |          |          |                        |           |           |               |                  |
| 321026B DETAILED VISUAL INSPECTION * RIGHT MAIN LANDING GEAR SIDE STAY ACTUATOR UPPER PIN (P/N 200-0325) ASSEMBLY * (IRN T3220135) |      |           |          |          |                        |           |           |               | Service ATA:32   |
| PN:200-0325-101                                                                                                                    | MOS  | 22-Jun-23 | 48       |          | 22-Jun-27              |           | 811 d     | AIRWORTHINESS |                  |
| SN:HER08U/5030                                                                                                                     | HRS  | 9258.5    |          |          |                        |           |           |               |                  |
|                                                                                                                                    | AFL  | 7100      |          |          |                        |           |           |               |                  |
| PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00                                                                                     |      |           |          |          |                        |           |           |               |                  |
| 321037 * LEFT MAIN LANDING GEAR SIDE-STAY ACTUATOR LOWER PIN (P/N 200-0217) ASSEMBLY                                               |      |           |          |          |                        |           |           |               | Component ATA:32 |
| PN:200-0217-101                                                                                                                    | MOS  | 24-Jun-19 | 96       | TSN 0    | 24-Jun-27              |           | 813 d     | LIFE LIMIT    |                  |
| SN:H5000                                                                                                                           | HRS  | 8101.1    |          | TSN 0    |                        |           |           |               |                  |
|                                                                                                                                    | AFL  | 6233      |          | TSN 0    |                        |           |           |               |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                                                                                 |      |           |          |          |                        |           |           |               |                  |
| 321037A MAGNETIC PARTICLE INSPECT * LEFT MAIN LANDING GEAR SIDE-STAY ACTUATOR LOWER PIN (P/N 200-0217) ASSEMBLY * (IRN T3220024)   |      |           |          |          |                        |           |           |               | Service ATA:32   |
| PN:200-0217-101                                                                                                                    | MOS  | 22-Jun-23 | 48       |          | 22-Jun-27              |           | 811 d     | AIRWORTHINESS |                  |
| SN:H5000                                                                                                                           | HRS  | 9258.5    |          |          |                        |           |           |               |                  |
|                                                                                                                                    | AFL  | 7100      |          |          |                        |           |           |               |                  |
| PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01                             |      |           |          |          |                        |           |           |               |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 9669.1
AFL: 7372
As Of: 01-Apr-2025
02-Apr-2025 02:58 PM

| PN & SN                                                                                                | Unit | C/W                                                                                                                        | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty |
|--------------------------------------------------------------------------------------------------------|------|----------------------------------------------------------------------------------------------------------------------------|----------|----------|------------------------|-----------|-----------|---------------|----------|
| ATA 32 - LANDING GEAR                                                                                  |      |                                                                                                                            |          |          |                        |           |           |               |          |
| 321037B                                                                                                |      | DETAILED VISUAL INSPECTION * LEFT MAIN LANDING GEAR SIDE-STAY ACTUATOR LOWER PIN (P/N 200-0217) ASSEMBLY * (IRN T3220135)  |          |          |                        |           |           | Service       | ATA:32   |
| PN:200-0217-101                                                                                        | MOS  | 22-Jun-23                                                                                                                  | 48       |          | 22-Jun-27              |           | 811 d     | AIRWORTHINESS |          |
| SN:H5000                                                                                               | HRS  | 9258.5                                                                                                                     |          |          |                        |           |           |               |          |
|                                                                                                        | AFL  | 7100                                                                                                                       |          |          |                        |           |           |               |          |
| PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00                                                         |      |                                                                                                                            |          |          |                        |           |           |               |          |
| 321038                                                                                                 |      | * RIGHT MAIN LANDING GEAR SIDE-STAY ACTUATOR LOWER PIN (P/N 200-0217) ASSEMBLY                                             |          |          |                        |           |           | Component     | ATA:32   |
| PN:200-0217-101                                                                                        | MOS  | 24-Jun-19                                                                                                                  | 96       | TSN 0    | 24-Jun-27              |           | 813 d     | LIFE LIMIT    |          |
| SN:HER08U5014                                                                                          | HRS  | 8101.1                                                                                                                     |          | TSN 0    |                        |           |           |               |          |
|                                                                                                        | AFL  | 6233                                                                                                                       |          | TSN 0    |                        |           |           |               |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                                                     |      |                                                                                                                            |          |          |                        |           |           |               |          |
| 321038A                                                                                                |      | MAGNETIC PARTICLE INSPECT * RIGHT MAIN LANDING GEAR SIDE-STAY ACTUATOR LOWER PIN (P/N 200-0217) ASSEMBLY * (IRN T3220024)  |          |          |                        |           |           | Service       | ATA:32   |
| PN:200-0217-101                                                                                        | MOS  | 22-Jun-23                                                                                                                  | 48       |          | 22-Jun-27              |           | 811 d     | AIRWORTHINESS |          |
| SN:HER08U5014                                                                                          | HRS  | 9258.5                                                                                                                     |          |          |                        |           |           |               |          |
|                                                                                                        | AFL  | 7100                                                                                                                       |          |          |                        |           |           |               |          |
| PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01 |      |                                                                                                                            |          |          |                        |           |           |               |          |
| 321038B                                                                                                |      | DETAILED VISUAL INSPECTION * RIGHT MAIN LANDING GEAR SIDE-STAY ACTUATOR LOWER PIN (P/N 200-0217) ASSEMBLY * (IRN T3220135) |          |          |                        |           |           | Service       | ATA:32   |
| PN:200-0217-101                                                                                        | MOS  | 22-Jun-23                                                                                                                  | 48       |          | 22-Jun-27              |           | 811 d     | AIRWORTHINESS |          |
| SN:HER08U5014                                                                                          | HRS  | 9258.5                                                                                                                     |          |          |                        |           |           |               |          |
|                                                                                                        | AFL  | 7100                                                                                                                       |          |          |                        |           |           |               |          |
| PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00                                                         |      |                                                                                                                            |          |          |                        |           |           |               |          |
| 321049                                                                                                 |      | * LEFT MAIN LANDING GEAR AXLE BEAM (P/N 200-0203) (N3220036) ASSEMBLY                                                      |          |          |                        |           |           | Component     | ATA:32   |
| PN:200-0203-001                                                                                        | MOS  | 08-Sep-12                                                                                                                  |          |          |                        |           |           | LIFE LIMIT    |          |
| SN:H0331                                                                                               | HRS  | 6989.1                                                                                                                     |          |          |                        |           |           |               |          |
|                                                                                                        | AFL  | 5335                                                                                                                       | 10000    | TSN 5311 | 10024                  |           | 2652      |               |          |
| PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01                                                         |      |                                                                                                                            |          |          |                        |           |           |               |          |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C/W   (M)-Manual Due   U-User Task   Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                            | Unit    | C/W                                                                                                                           | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------|---------|-------------------------------------------------------------------------------------------------------------------------------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 32 - LANDING GEAR                              |         |                                                                                                                               |          |          |                        |           |           |             |          |
| 321049A                                            |         | INSPECTION * LEFT MAIN LANDING GEAR AXLES - PERFORM MAIN LANDING GEAR AXLE BEAM ASSEMBLY BORESCOPE INSPECTION (IRN T3220007)  |          |          |                        |           |           | Service     | ATA:32   |
|                                                    | MOS     | 02-Aug-24                                                                                                                     | 48       |          | 02-Aug-28              |           | 1218 d    |             |          |
|                                                    | HRS     | 9525.7                                                                                                                        |          |          |                        |           |           |             |          |
|                                                    | AFL     | 7276                                                                                                                          |          |          |                        |           |           |             |          |
| PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01     |         |                                                                                                                               |          |          |                        |           |           |             |          |
| 321050                                             |         | * RIGHT MAIN LANDING GEAR AXLE BEAM (P/N 200-0203) (N3220036) ASSEMBLY                                                        |          |          |                        |           |           | Component   | ATA:32   |
| PN:200-0203-001                                    | MOS     | 08-Sep-12                                                                                                                     |          |          |                        |           |           | LIFE LIMIT  |          |
| SN:H0334                                           | HRS     | 6989.1                                                                                                                        |          |          |                        |           |           |             |          |
|                                                    | AFL     | 5335                                                                                                                          | 10000    | TSN 5311 | 10024                  |           | 2652      |             |          |
| PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01     |         |                                                                                                                               |          |          |                        |           |           |             |          |
| 321050A                                            |         | INSPECTION * RIGHT MAIN LANDING GEAR AXLES - PERFORM MAIN LANDING GEAR AXLE BEAM ASSEMBLY BORESCOPE INSPECTION (IRN T3220007) |          |          |                        |           |           | Service     | ATA:32   |
|                                                    | MOS     | 02-Aug-24                                                                                                                     | 48       |          | 02-Aug-28              |           | 1218 d    |             |          |
|                                                    | HRS     | 9525.7                                                                                                                        |          |          |                        |           |           |             |          |
|                                                    | AFL     | 7276                                                                                                                          |          |          |                        |           |           |             |          |
| PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01     |         |                                                                                                                               |          |          |                        |           |           |             |          |
| 321061                                             |         | LEFT MAIN LANDING GEAR SIDE-STAY ACTUATOR PIN                                                                                 |          |          |                        |           |           | Component   | ATA:32   |
| PN:PN                                              | MOS/MSC | 09-Mar-01                                                                                                                     | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0                                                                                                                             |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL     | 0                                                                                                                             |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |         |                                                                                                                               |          |          |                        |           |           |             |          |
| 321062                                             |         | RIGHT MAIN LANDING GEAR SIDE-STAY ACTUATOR PIN                                                                                |          |          |                        |           |           | Component   | ATA:32   |
| PN:PN                                              | MOS/MSC | 09-Mar-01                                                                                                                     | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0                                                                                                                             |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL     | 0                                                                                                                             |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |         |                                                                                                                               |          |          |                        |           |           |             |          |
| 321073                                             |         | LEFT MAIN LANDING GEAR SIDE BRACE ACTUATOR DISPLACEMENT TUBE                                                                  |          |          |                        |           |           | Component   | ATA:32   |
| PN:PN                                              | MOS/MSC | 09-Mar-01                                                                                                                     | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0                                                                                                                             |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL     | 0                                                                                                                             |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |         |                                                                                                                               |          |          |                        |           |           |             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR    Serial: 45-145    RegNo: N942FK    HRS: 9669.1    AFL: 7372    As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                            | Unit                                                                                                    | C / W     | Interval | TSX/Adj.   | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------|---------------------------------------------------------------------------------------------------------|-----------|----------|------------|------------------------|-----------|-----------|-------------|----------|
| ATA 32 - LANDING GEAR                              |                                                                                                         |           |          |            |                        |           |           |             |          |
| 321074                                             | RIGHT MAIN LANDING GEAR SIDE BRACE ACTUATOR DISPLACEMENT TUBE                                           |           |          |            |                        |           |           | Component   | ATA:32   |
| PN:PN                                              | MOS/MSC                                                                                                 | 09-Mar-01 | O/C      | TSN 0      |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS                                                                                                     | 0         |          | TSN 0      |                        |           |           |             |          |
|                                                    | AFL                                                                                                     | 0         |          | TSN 0      |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                                                         |           |          |            |                        |           |           |             |          |
| 321085                                             | LEFT FORWARD TRUNNION ASSEMBLY                                                                          |           |          |            |                        |           |           | Component   | ATA:32   |
| PN:PN                                              | MOS/MSC                                                                                                 | 09-Mar-01 | O/C      | TSN 0      |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS                                                                                                     | 0         |          | TSN 0      |                        |           |           |             |          |
|                                                    | AFL                                                                                                     | 0         |          | TSN 0      |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                                                         |           |          |            |                        |           |           |             |          |
| 321086                                             | RIGHT FORWARD TRUNNION ASSEMBLY                                                                         |           |          |            |                        |           |           | Component   | ATA:32   |
| PN:PN                                              | MOS/MSC                                                                                                 | 09-Mar-01 | O/C      | TSN 0      |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS                                                                                                     | 0         |          | TSN 0      |                        |           |           |             |          |
|                                                    | AFL                                                                                                     | 0         |          | TSN 0      |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                                                         |           |          |            |                        |           |           |             |          |
| 321087                                             | LEFT AFT TRUNNION ASSEMBLY                                                                              |           |          |            |                        |           |           | Component   | ATA:32   |
| PN:PN                                              | MOS/MSC                                                                                                 | 09-Mar-01 | O/C      | TSN 0      |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS                                                                                                     | 0         |          | TSN 0      |                        |           |           |             |          |
|                                                    | AFL                                                                                                     | 0         |          | TSN 0      |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                                                         |           |          |            |                        |           |           |             |          |
| 321088                                             | RIGHT AFT TRUNNION ASSEMBLY                                                                             |           |          |            |                        |           |           | Component   | ATA:32   |
| PN:PN                                              | MOS/MSC                                                                                                 | 09-Mar-01 | O/C      | TSN 0      |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS                                                                                                     | 0         |          | TSN 0      |                        |           |           |             |          |
|                                                    | AFL                                                                                                     | 0         |          | TSN 0      |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                                                         |           |          |            |                        |           |           |             |          |
| 321101                                             | * REPLACE LEFT MAIN LANDING GEAR TRUNNION FORWARD PIN (P/N 200-0212, 200-0213). (IRN N3220023) ASSEMBLY |           |          |            |                        |           |           | Component   | ATA:32   |
| PN:200-0212-103                                    | MOS                                                                                                     | 24-Jul-12 |          |            |                        |           |           | LIFE LIMIT  |          |
| SN:H0501                                           | HRS                                                                                                     | 6961.3    |          | TSN 2110.4 |                        |           |           |             |          |
|                                                    | AFL                                                                                                     | 5311      | 10000    | TSN 1409   | 13902                  |           | 6530      |             |          |
| PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01     |                                                                                                         |           |          |            |                        |           |           |             |          |

?-Insufficient Information    S-Suppressed Requirement    \*-Estimated Due(New Requirement)    (EFF)-Effective C/W    (M)-Manual Due    U-User Task    Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                                                                                | Unit | C / W                                                                                                   | Interval | TSX / Adj. | Next Due (ENG / APU) A / C | Max Limit | Remaining | Disposition | Warranty |
|--------------------------------------------------------------------------------------------------------|------|---------------------------------------------------------------------------------------------------------|----------|------------|----------------------------|-----------|-----------|-------------|----------|
| ATA 32 - LANDING GEAR                                                                                  |      |                                                                                                         |          |            |                            |           |           |             |          |
| 321101A                                                                                                |      | MAGNETIC PARTICLE INSPECT LEFT MAIN LANDING GEAR TRUNNION FORWARD PIN - (IRN V3220022)                  |          |            |                            |           |           | Service     | ATA:32   |
|                                                                                                        | MOS  | 30-Mar-21                                                                                               | 96       | Adj -44d   | 14-Feb-29                  |           | 1414 d    |             |          |
|                                                                                                        | HRS  | 8414.4                                                                                                  |          |            |                            |           |           |             |          |
|                                                                                                        | AFL  | 6463                                                                                                    |          |            |                            |           |           |             |          |
| PROC. REF: NDT PART 7/32-10-07, NDT PART 7/32-10-08PROC. REF: NDT PART 7/32-10-07, NDT PART 7/32-10-08 |      |                                                                                                         |          |            |                            |           |           |             |          |
| 321102                                                                                                 |      | * REPLACE RIGHT MAIN LANDING GEAR TRUNNION FORWARD PIN (P/N 200-0212, 200-0213) (IRN N3220023) ASSEMBLY |          |            |                            |           |           | Component   | ATA:32   |
| PN:200-0212-103                                                                                        | MOS  | 24-Jul-12                                                                                               |          |            |                            |           |           | LIFE LIMIT  |          |
| SN:H0473                                                                                               | HRS  | 6961.3                                                                                                  |          | TSN 2110.4 |                            |           |           |             |          |
|                                                                                                        | AFL  | 5311                                                                                                    | 10000    | TSN 1409   | 13902                      |           | 6530      |             |          |
| PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01                                                         |      |                                                                                                         |          |            |                            |           |           |             |          |
| 321102A                                                                                                |      | MAGNETIC PARTICLE INSPECT RIGHT MAIN LANDING GEAR TRUNNION FORWARD PIN (IRN V3220022)                   |          |            |                            |           |           | Service     | ATA:32   |
|                                                                                                        | MOS  | 30-Mar-21                                                                                               | 96       | Adj -44d   | 14-Feb-29                  |           | 1414 d    |             |          |
|                                                                                                        | HRS  | 8414.4                                                                                                  |          |            |                            |           |           |             |          |
|                                                                                                        | AFL  | 6463                                                                                                    |          |            |                            |           |           |             |          |
| PROC. REF: NDT PART 7/32-10-07, NDT PART 7/32-10-08PROC. REF: NDT PART 7/32-10-07, NDT PART 7/32-10-08 |      |                                                                                                         |          |            |                            |           |           |             |          |
| 321103                                                                                                 |      | * REPLACE LEFT MAIN LANDING GEAR TRUNNION AFT PIN (P/N 200-0212, 200-0213) (IRN N3220023) ASSEMBLY      |          |            |                            |           |           | Component   | ATA:32   |
| PN:200-0213-103                                                                                        | MOS  | 24-Jul-12                                                                                               |          |            |                            |           |           | LIFE LIMIT  |          |
| SN:H0364                                                                                               | HRS  | 6961.3                                                                                                  |          | TSN 2110.4 |                            |           |           |             |          |
|                                                                                                        | AFL  | 5311                                                                                                    | 10000    | TSN 1409   | 13902                      |           | 6530      |             |          |
| PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01                                                         |      |                                                                                                         |          |            |                            |           |           |             |          |
| 321103A                                                                                                |      | MAGNETIC PARTICLE INSPECT LEFT MAIN LANDING GEAR TRUNNION AFT PIN (IRN V3220022)                        |          |            |                            |           |           | Service     | ATA:32   |
|                                                                                                        | MOS  | 30-Mar-21                                                                                               | 96       | Adj -44d   | 14-Feb-29                  |           | 1414 d    |             |          |
|                                                                                                        | HRS  | 8414.4                                                                                                  |          |            |                            |           |           |             |          |
|                                                                                                        | AFL  | 6463                                                                                                    |          |            |                            |           |           |             |          |
| PROC. REF: NDT PART 7/32-10-07, NDT PART 7/32-10-08PROC. REF: NDT PART 7/32-10-07, NDT PART 7/32-10-08 |      |                                                                                                         |          |            |                            |           |           |             |          |
| 321104                                                                                                 |      | * REPLACE RIGHT MAIN LANDING GEAR AFT TRUNNION PIN (P/N 200-0212, 200-0213) (IRN N3220023) ASSEMBLY     |          |            |                            |           |           | Component   | ATA:32   |
| PN:200-0213-103                                                                                        | MOS  | 24-Jul-12                                                                                               |          |            |                            |           |           | LIFE LIMIT  |          |
| SN:H0338                                                                                               | HRS  | 6961.3                                                                                                  |          | TSN 2110.4 |                            |           |           |             |          |
|                                                                                                        | AFL  | 5311                                                                                                    | 10000    | TSN 1409   | 13902                      |           | 6530      |             |          |
| PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01                                                         |      |                                                                                                         |          |            |                            |           |           |             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                                                                                | Unit    | C/W                                                                                                      | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition    | Warranty |
|--------------------------------------------------------------------------------------------------------|---------|----------------------------------------------------------------------------------------------------------|----------|----------|------------------------|-----------|-----------|----------------|----------|
| ATA 32 - LANDING GEAR                                                                                  |         |                                                                                                          |          |          |                        |           |           |                |          |
| 321104A                                                                                                |         | MAGNETIC PARTICLE INSPECT RIGHT MAIN LANDING GEAR AFT TRUNNION PIN (IRN V3220022)                        |          |          |                        |           |           | Service        | ATA:32   |
|                                                                                                        | MOS     | 30-Mar-21                                                                                                | 96       | Adj -44d | 14-Feb-29              |           | 1414 d    |                |          |
|                                                                                                        | HRS     | 8414.4                                                                                                   |          |          |                        |           |           |                |          |
|                                                                                                        | AFL     | 6463                                                                                                     |          |          |                        |           |           |                |          |
| PROC. REF: NDT PART 7/32-10-07, NDT PART 7/32-10-08PROC. REF: NDT PART 7/32-10-07, NDT PART 7/32-10-08 |         |                                                                                                          |          |          |                        |           |           |                |          |
| 321111                                                                                                 |         | LEFT FORWARD LOWER * MAIN LANDING GEAR TRUNNION SHEAR PIN                                                |          |          |                        |           |           | Component      | ATA:32   |
| PN:4532103201-001                                                                                      | MOS     | 15-Dec-10                                                                                                |          | TSN 0    |                        |           |           | LIFE LIMIT     |          |
| SN:CM1882                                                                                              | HRS     | 6457.2                                                                                                   |          | TSN 0    |                        |           |           |                |          |
|                                                                                                        | AFL     | 4944                                                                                                     | 5000     | TSN 0    | 9944                   |           | 2572      |                |          |
| PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05                                                         |         |                                                                                                          |          |          |                        |           |           |                |          |
| 321111A                                                                                                |         | LEFT FORWARD LOWER * MAIN LANDING GEAR TRUNNION SHEAR PIN - PERFORM VISUAL INSPECTION FOR PIN MIGRATION  |          |          |                        |           |           | Service        | ATA:32   |
|                                                                                                        | MOS/MSC |                                                                                                          | N/A      |          |                        |           |           | NOT APPLICABLE |          |
|                                                                                                        | HRS     |                                                                                                          |          |          |                        |           |           |                |          |
|                                                                                                        | AFL     |                                                                                                          |          |          |                        |           |           |                |          |
| PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05                                                         |         |                                                                                                          |          |          |                        |           |           |                |          |
| 321112                                                                                                 |         | RIGHT FORWARD LOWER * MAIN LANDING GEAR TRUNNION SHEAR PIN                                               |          |          |                        |           |           | Component      | ATA:32   |
| PN:4532103201-001                                                                                      | MOS     | 15-Dec-10                                                                                                |          | TSN 0    |                        |           |           | LIFE LIMIT     |          |
| SN:CM11113                                                                                             | HRS     | 6457.2                                                                                                   |          | TSN 0    |                        |           |           |                |          |
|                                                                                                        | AFL     | 4944                                                                                                     | 5000     | TSN 0    | 9944                   |           | 2572      |                |          |
| PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05                                                         |         |                                                                                                          |          |          |                        |           |           |                |          |
| 321112A                                                                                                |         | RIGHT FORWARD LOWER * MAIN LANDING GEAR TRUNNION SHEAR PIN - PERFORM VISUAL INSPECTION FOR PIN MIGRATION |          |          |                        |           |           | Service        | ATA:32   |
|                                                                                                        | MOS/MSC |                                                                                                          | N/A      |          |                        |           |           | NOT APPLICABLE |          |
|                                                                                                        | HRS     |                                                                                                          |          |          |                        |           |           |                |          |
|                                                                                                        | AFL     |                                                                                                          |          |          |                        |           |           |                |          |
| PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05                                                         |         |                                                                                                          |          |          |                        |           |           |                |          |
| 321113                                                                                                 |         | LEFT FORWARD UPPER * MAIN LANDING GEAR TRUNNION SHEAR PIN                                                |          |          |                        |           |           | Component      | ATA:32   |
| PN:4532103201-001                                                                                      | MOS     | 15-Dec-10                                                                                                |          | TSN 0    |                        |           |           | LIFE LIMIT     |          |
| SN:CM1806                                                                                              | HRS     | 6457.2                                                                                                   |          | TSN 0    |                        |           |           |                |          |
|                                                                                                        | AFL     | 4944                                                                                                     | 5000     | TSN 0    | 9944                   |           | 2572      |                |          |
| PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05                                                         |         |                                                                                                          |          |          |                        |           |           |                |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                                                                                          | Unit    | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition    | Warranty         |
|------------------------------------------------------------------------------------------------------------------|---------|-----------|----------|----------|------------------------|-----------|-----------|----------------|------------------|
| ATA 32 - LANDING GEAR                                                                                            |         |           |          |          |                        |           |           |                |                  |
| 321113A LEFT FORWARD UPPER * MAIN LANDING GEAR TRUNNION SHEAR PIN - PERFORM VISUAL INSPECTION FOR PIN MIGRATION  |         |           |          |          |                        |           |           |                | Service ATA:32   |
|                                                                                                                  | MOS/MSC |           | N/A      |          |                        |           |           | NOT APPLICABLE |                  |
|                                                                                                                  | HRS     |           |          |          |                        |           |           |                |                  |
|                                                                                                                  | AFL     |           |          |          |                        |           |           |                |                  |
| PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05                                                                   |         |           |          |          |                        |           |           |                |                  |
| 321114 RIGHT FORWARD UPPER * MAIN LANDING GEAR TRUNNION SHEAR PIN                                                |         |           |          |          |                        |           |           |                | Component ATA:32 |
| PN:4532103201-001                                                                                                | MOS     | 15-Dec-10 |          | TSN 0    |                        |           |           | LIFE LIMIT     |                  |
| SN:CM1710                                                                                                        | HRS     | 6457.2    |          | TSN 0    |                        |           |           |                |                  |
|                                                                                                                  | AFL     | 4944      | 5000     | TSN 0    | 9944                   |           | 2572      |                |                  |
| PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05                                                                   |         |           |          |          |                        |           |           |                |                  |
| 321114A RIGHT FORWARD UPPER * MAIN LANDING GEAR TRUNNION SHEAR PIN - PERFORM VISUAL INSPECTION FOR PIN MIGRATION |         |           |          |          |                        |           |           |                | Service ATA:32   |
|                                                                                                                  | MOS/MSC |           | N/A      |          |                        |           |           | NOT APPLICABLE |                  |
|                                                                                                                  | HRS     |           |          |          |                        |           |           |                |                  |
|                                                                                                                  | AFL     |           |          |          |                        |           |           |                |                  |
| PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05                                                                   |         |           |          |          |                        |           |           |                |                  |
| 321117 LEFT AFT UPPER * MAIN LANDING GEAR TRUNNION SHEAR PIN                                                     |         |           |          |          |                        |           |           |                | Component ATA:32 |
| PN:4532103202-001                                                                                                | MOS     | 18-Dec-10 |          | TSN 0    |                        |           |           | LIFE LIMIT     |                  |
| SN:CM1371                                                                                                        | HRS     | 6457.2    |          | TSN 0    |                        |           |           |                |                  |
|                                                                                                                  | AFL     | 4944      | 5000     | TSN 0    | 9944                   |           | 2572      |                |                  |
| PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05                                                                   |         |           |          |          |                        |           |           |                |                  |
| 321117A LEFT AFT UPPER * MAIN LANDING GEAR TRUNNION SHEAR PIN - PERFORM VISUAL INSPECTION FOR PIN MIGRATION      |         |           |          |          |                        |           |           |                | Service ATA:32   |
|                                                                                                                  | MOS/MSC |           | N/A      |          |                        |           |           | NOT APPLICABLE |                  |
|                                                                                                                  | HRS     |           |          |          |                        |           |           |                |                  |
|                                                                                                                  | AFL     |           |          |          |                        |           |           |                |                  |
| PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05                                                                   |         |           |          |          |                        |           |           |                |                  |
| 321118 RIGHT AFT UPPER * MAIN LANDING GEAR TRUNNION SHEAR PIN                                                    |         |           |          |          |                        |           |           |                | Component ATA:32 |
| PN:4532103202-001                                                                                                | MOS     | 18-Dec-10 |          | TSN 0    |                        |           |           | LIFE LIMIT     |                  |
| SN:CM1363                                                                                                        | HRS     | 6457.2    |          | TSN 0    |                        |           |           |                |                  |
|                                                                                                                  | AFL     | 4944      | 5000     | TSN 0    | 9944                   |           | 2572      |                |                  |
| PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05                                                                   |         |           |          |          |                        |           |           |                |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                            | Unit    | C/W                                                                                                  | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition    | Warranty |
|----------------------------------------------------|---------|------------------------------------------------------------------------------------------------------|----------|----------|------------------------|-----------|-----------|----------------|----------|
| ATA 32 - LANDING GEAR                              |         |                                                                                                      |          |          |                        |           |           |                |          |
| 321118A                                            |         | RIGHT AFT UPPER * MAIN LANDING GEAR TRUNNION SHEAR PIN - PERFORM VISUAL INSPECTION FOR PIN MIGRATION |          |          |                        |           |           | Service        | ATA:32   |
|                                                    | MOS/MSC |                                                                                                      | N/A      |          |                        |           |           | NOT APPLICABLE |          |
|                                                    | HRS     |                                                                                                      |          |          |                        |           |           |                |          |
|                                                    | AFL     |                                                                                                      |          |          |                        |           |           |                |          |
| PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05     |         |                                                                                                      |          |          |                        |           |           |                |          |
| 321119                                             |         | LEFT AFT LOWER * MAIN LANDING GEAR TRUNNION SHEAR PIN                                                |          |          |                        |           |           | Component      | ATA:32   |
| PN:4532103203-001                                  | MOS     | 18-Dec-10                                                                                            |          | TSN 0    |                        |           |           | LIFE LIMIT     |          |
| SN:CM1818                                          | HRS     | 6457.2                                                                                               |          | TSN 0    |                        |           |           |                |          |
|                                                    | AFL     | 4944                                                                                                 | 5000     | TSN 0    | 9944                   |           | 2572      |                |          |
| PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05     |         |                                                                                                      |          |          |                        |           |           |                |          |
| 321119A                                            |         | LEFT AFT LOWER * MAIN LANDING GEAR TRUNNION SHEAR PIN - PERFORM VISUAL INSPECTION FOR PIN MIGRATION  |          |          |                        |           |           | Service        | ATA:32   |
|                                                    | MOS/MSC |                                                                                                      | N/A      |          |                        |           |           | NOT APPLICABLE |          |
|                                                    | HRS     |                                                                                                      |          |          |                        |           |           |                |          |
|                                                    | AFL     |                                                                                                      |          |          |                        |           |           |                |          |
| PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05     |         |                                                                                                      |          |          |                        |           |           |                |          |
| 321120                                             |         | RIGHT AFT LOWER * MAIN LANDING GEAR TRUNNION SHEAR PIN                                               |          |          |                        |           |           | Component      | ATA:32   |
| PN:4532103203-001                                  | MOS     | 18-Dec-10                                                                                            |          | TSN 0    |                        |           |           | LIFE LIMIT     |          |
| SN:CM1759                                          | HRS     | 6457.2                                                                                               |          | TSN 0    |                        |           |           |                |          |
|                                                    | AFL     | 4944                                                                                                 | 5000     | TSN 0    | 9944                   |           | 2572      |                |          |
| PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05     |         |                                                                                                      |          |          |                        |           |           |                |          |
| 321120A                                            |         | RIGHT AFT LOWER * MAIN LANDING GEAR TRUNNION SHEAR PIN - PERFORM VISUAL INSPECTION FOR PIN MIGRATION |          |          |                        |           |           | Service        | ATA:32   |
|                                                    | MOS/MSC |                                                                                                      | N/A      |          |                        |           |           | NOT APPLICABLE |          |
|                                                    | HRS     |                                                                                                      |          |          |                        |           |           |                |          |
|                                                    | AFL     |                                                                                                      |          |          |                        |           |           |                |          |
| PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05     |         |                                                                                                      |          |          |                        |           |           |                |          |
| 321201                                             |         | LEFT MAIN LANDING GEAR OLEO ASSEMBLY                                                                 |          |          |                        |           |           | Component      | ATA:32   |
| PN:PN                                              | MOS/MSC | 09-Mar-01                                                                                            | O/C      | TSN 0    |                        |           |           |                |          |
| SN:UNKNOWN                                         | HRS     | 0                                                                                                    |          | TSN 0    |                        |           |           |                |          |
|                                                    | AFL     | 0                                                                                                    |          | TSN 0    |                        |           |           |                |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |         |                                                                                                      |          |          |                        |           |           |                |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                            | Unit                                                                                        | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------|---------------------------------------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 32 - LANDING GEAR                              |                                                                                             |           |          |          |                        |           |           |             |                  |
| 321202                                             | RIGHT MAIN LANDING GEAR OLEO ASSEMBLY                                                       |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:PN                                              | MOS/MSC                                                                                     | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                                                                         | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                                                                         | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                                             |           |          |          |                        |           |           |             |                  |
| 321215                                             | * REPLACE LEFT MAIN LANDING GEAR SHOCK STRUT PISTON (P/N 200-0202) (IRN N3220035) ASSEMBLY  |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:PN                                              | MOS                                                                                         | 09-Mar-01 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:UNKNOWN                                         | HRS                                                                                         | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                                                                         | 0         | 10000    | TSN 0    | 10000                  |           | 2628      |             |                  |
| PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01     |                                                                                             |           |          |          |                        |           |           |             |                  |
| 321216                                             | * REPLACE RIGHT MAIN LANDING GEAR SHOCK STRUT PISTON (P/N 200-0202) (IRN N3220035) ASSEMBLY |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:PN                                              | MOS                                                                                         | 09-Mar-01 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:UNKNOWN                                         | HRS                                                                                         | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                                                                         | 0         | 10000    | TSN 0    | 10000                  |           | 2628      |             |                  |
| PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01     |                                                                                             |           |          |          |                        |           |           |             |                  |
| 321227                                             | * REPLACE LEFT MAIN LANDING GEAR SHOCK STRUT LINK (P/N 200-0204) (IRN N3220037) ASSEMBLY    |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:PN                                              | MOS                                                                                         | 09-Mar-01 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:UNKNOWN                                         | HRS                                                                                         | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                                                                         | 0         | 10000    | TSN 0    | 10000                  |           | 2628      |             |                  |
| PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01     |                                                                                             |           |          |          |                        |           |           |             |                  |
| 321228                                             | * REPLACE RIGHT MAIN LANDING GEAR SHOCK STRUT LINK (P/N 200-0204) (IRN N3220037) ASSEMBLY   |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:PN                                              | MOS                                                                                         | 09-Mar-01 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:UNKNOWN                                         | HRS                                                                                         | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                                                                         | 0         | 10000    | TSN 0    | 10000                  |           | 2628      |             |                  |
| PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01     |                                                                                             |           |          |          |                        |           |           |             |                  |
| 321301                                             | LEFT MAIN LANDING GEAR OUTBOARD DOOR                                                        |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:PN                                              | MOS/MSC                                                                                     | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                                                                         | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                                                                         | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 52-80-01PROC. REF: AMM 52-80-01     |                                                                                             |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR    Serial: 45-145    RegNo: N942FK    HRS: 9669.1    AFL: 7372    As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                        | Unit                                                                 | C / W     | Interval | TSX/Adj.        | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|------------------------------------------------|----------------------------------------------------------------------|-----------|----------|-----------------|------------------------|-----------|-----------|-------------|----------|
| ATA 32 - LANDING GEAR                          |                                                                      |           |          |                 |                        |           |           |             |          |
| 321302                                         | LEFT MAIN LANDING GEAR INBOARD DOOR                                  |           |          |                 |                        |           |           | Component   | ATA:32   |
| PN:PN                                          | MOS/MSC                                                              | 09-Mar-01 | O/C      | TSN 0           |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS                                                                  | 0         |          | TSN 0           |                        |           |           |             |          |
|                                                | AFL                                                                  | 0         |          | TSN 0           |                        |           |           |             |          |
| PROC. REF: AMM 52-80-01PROC. REF: AMM 52-80-01 |                                                                      |           |          |                 |                        |           |           |             |          |
| 321303                                         | RIGHT MAIN LANDING GEAR INBOARD DOOR                                 |           |          |                 |                        |           |           | Component   | ATA:32   |
| PN:PN                                          | MOS/MSC                                                              | 09-Mar-01 | O/C      | TSN 0           |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS                                                                  | 0         |          | TSN 0           |                        |           |           |             |          |
|                                                | AFL                                                                  | 0         |          | TSN 0           |                        |           |           |             |          |
| PROC. REF: AMM 52-80-01PROC. REF: AMM 52-80-01 |                                                                      |           |          |                 |                        |           |           |             |          |
| 321304                                         | RIGHT MAIN LANDING GEAR OUTBOARD DOOR                                |           |          |                 |                        |           |           | Component   | ATA:32   |
| PN:PN                                          | MOS/MSC                                                              | 09-Mar-01 | O/C      | TSN 0           |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS                                                                  | 0         |          | TSN 0           |                        |           |           |             |          |
|                                                | AFL                                                                  | 0         |          | TSN 0           |                        |           |           |             |          |
| PROC. REF: AMM 52-80-01PROC. REF: AMM 52-80-01 |                                                                      |           |          |                 |                        |           |           |             |          |
| 322001 <sup>S</sup>                            | * REPLACE NOSE LANDING GEAR STRUT ASSEMBLY (O3220009) (JAA E3220069) |           |          |                 |                        |           |           | Component   | ATA:32   |
| PN:4532230001-814                              | MOS                                                                  | 12-Feb-08 |          | TSR 0           |                        |           |           | LIFE LIMIT  |          |
| SN:008                                         | HRS                                                                  | 5965.9    |          | TSR 0           |                        |           |           |             |          |
|                                                | AFL                                                                  | 4561      | 20000    | TSN 4561, TSR 0 |                        |           |           |             |          |
| PROC. REF: AMM 32-20-01PROC. REF: AMM 32-20-01 |                                                                      |           |          |                 |                        |           |           |             |          |
| 322002                                         | NOSE LANDING GEAR CYLINDER                                           |           |          |                 |                        |           |           | Component   | ATA:32   |
| PN:PN                                          | MOS/MSC                                                              | 09-Mar-01 | O/C      | TSN 0           |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS                                                                  | 0         |          | TSN 0           |                        |           |           |             |          |
|                                                | AFL                                                                  | 0         |          | TSN 0           |                        |           |           |             |          |
| PROC. REF: AMM 32-32-01PROC. REF: AMM 32-32-01 |                                                                      |           |          |                 |                        |           |           |             |          |
| 322003                                         | NOSE LANDING GEAR PISTON                                             |           |          |                 |                        |           |           | Component   | ATA:32   |
| PN:PN                                          | MOS/MSC                                                              | 09-Mar-01 | O/C      | TSN 0           |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS                                                                  | 0         |          | TSN 0           |                        |           |           |             |          |
|                                                | AFL                                                                  | 0         |          | TSN 0           |                        |           |           |             |          |
| PROC. REF: AMM 32-32-01PROC. REF: AMM 32-32-01 |                                                                      |           |          |                 |                        |           |           |             |          |

?-Insufficient Information    S-Suppressed Requirement    \*-Estimated Due(New Requirement)    (EFF)-Effective C/W    (M)-Manual Due    U-User Task    Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                                                                                              | Unit    | C / W     | Interval | TSX / Adj. | Next Due (ENG / APU) A / C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------------------------------------------------------------------------|---------|-----------|----------|------------|----------------------------|-----------|-----------|-------------|----------|
| ATA 32 - LANDING GEAR                                                                                                |         |           |          |            |                            |           |           |             |          |
| 322004 NOSE LANDING GEAR ACTUATOR BRACKET                                                                            |         |           |          |            |                            |           |           | Component   | ATA:32   |
| PN:PN                                                                                                                | MOS/MSC | 09-Mar-01 | O/C      | TSN 0      |                            |           |           |             |          |
| SN:UNKNOWN                                                                                                           | HRS     | 0         |          | TSN 0      |                            |           |           |             |          |
|                                                                                                                      | AFL     | 0         |          | TSN 0      |                            |           |           |             |          |
| PROC. REF: AMM 32-32-01PROC. REF: AMM 32-32-01                                                                       |         |           |          |            |                            |           |           |             |          |
| 322005 NOSE LANDING GEAR FORK                                                                                        |         |           |          |            |                            |           |           | Component   | ATA:32   |
| PN:PN                                                                                                                | MOS/MSC | 09-Mar-01 | O/C      | TSN 0      |                            |           |           |             |          |
| SN:UNKNOWN                                                                                                           | HRS     | 0         |          | TSN 0      |                            |           |           |             |          |
|                                                                                                                      | AFL     | 0         |          | TSN 0      |                            |           |           |             |          |
| PROC. REF: AMM 32-32-01PROC. REF: AMM 32-32-01                                                                       |         |           |          |            |                            |           |           |             |          |
| 322011 <sup>S</sup> * REPLACE NOSE LANDING GEAR ACTUATOR (P/N 6632201000) (O3220010) (JAA IRN E3220073) ASSEMBLY     |         |           |          |            |                            |           |           | Component   | ATA:32   |
| PN:6632201000-001                                                                                                    | MOS     | 09-Mar-01 |          | TSN 0      |                            |           |           | LIFE LIMIT  |          |
| SN:EFS210                                                                                                            | HRS     | 0         |          | TSN 0      |                            |           |           |             |          |
|                                                                                                                      | AFL     | 0         | 20000    | TSN 0      |                            |           |           |             |          |
| PROC. REF: AMM 32-32-01PROC. REF: AMM 32-32-01                                                                       |         |           |          |            |                            |           |           |             |          |
| 322041 <sup>U</sup> NOSE LANDING GEAR (P/N 2342110) IRN O3220029 AXLE                                                |         |           |          |            |                            |           |           | Component   | ATA:32   |
| PN:PN                                                                                                                | MOS/MSC | 09-Mar-01 | O/C      | TSN 0      |                            |           |           |             |          |
| SN:UNKNOWN                                                                                                           | HRS     | 0         |          | TSN 0      |                            |           |           |             |          |
|                                                                                                                      | AFL     | 0         |          | TSN 0      |                            |           |           |             |          |
|                                                                                                                      |         |           |          |            |                            |           |           |             |          |
| 322061 <sup>S</sup> * REPLACE NOSE LANDING GEAR TRUNNION AXLE (P/N 2342110) (IRN O3220029 JAA IRN E3220072) ASSEMBLY |         |           |          |            |                            |           |           | Component   | ATA:32   |
| PN:2342110-003                                                                                                       | MOS     | 09-Mar-01 |          | TSN 0      |                            |           |           | LIFE LIMIT  |          |
| SN:R153                                                                                                              | HRS     | 0         |          | TSN 0      |                            |           |           |             |          |
|                                                                                                                      | AFL     | 0         | 20000    | TSN 0      |                            |           |           |             |          |
| PROC. REF: AMM 32-20-01PROC. REF: AMM 32-20-01                                                                       |         |           |          |            |                            |           |           |             |          |
| 322071 <sup>S</sup> * REPLACE LEFT NOSE GEAR TRUNNION PIN (P/N 2342108) (IRN O3220028 JAA IRN E3220071) ASSEMBLY     |         |           |          |            |                            |           |           | Component   | ATA:32   |
| PN:2342108-003                                                                                                       | MOS     | 09-Mar-01 |          | TSN 0      |                            |           |           | LIFE LIMIT  |          |
| SN:L016                                                                                                              | HRS     | 0         |          | TSN 0      |                            |           |           |             |          |
|                                                                                                                      | AFL     | 0         | 20000    | TSN 0      |                            |           |           |             |          |
| PROC. REF: AMM 32-20-01PROC. REF: AMM 32-20-01                                                                       |         |           |          |            |                            |           |           |             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                            | Unit    | C / W                                                                                         | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------|---------|-----------------------------------------------------------------------------------------------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 32 - LANDING GEAR                              |         |                                                                                               |          |          |                        |           |           |             |          |
| 322072 <sup>S</sup>                                |         | * REPLACE RIGHT NOSE GEAR TRUNNION PIN (P/N 2342108) (IRN O3220028 JAA IRN E3220071) ASSEMBLY |          |          |                        |           |           | Component   | ATA:32   |
| PN:2342108-003                                     | MOS     | 09-Mar-01                                                                                     |          | TSN 0    |                        |           |           | LIFE LIMIT  |          |
| SN:L012                                            | HRS     | 0                                                                                             |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL     | 0                                                                                             | 20000    | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 32-20-01PROC. REF: AMM 32-20-01     |         |                                                                                               |          |          |                        |           |           |             |          |
| 322095                                             |         | LEFT NOSE LANDING GEAR DOOR                                                                   |          |          |                        |           |           | Component   | ATA:32   |
| PN:PN                                              | MOS/MSC | 09-Mar-01                                                                                     | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0                                                                                             |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL     | 0                                                                                             |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 52-81-01PROC. REF: AMM 52-81-01     |         |                                                                                               |          |          |                        |           |           |             |          |
| 322096                                             |         | RIGHT NOSE LANDING GEAR DOOR                                                                  |          |          |                        |           |           | Component   | ATA:32   |
| PN:PN                                              | MOS/MSC | 09-Mar-01                                                                                     | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0                                                                                             |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL     | 0                                                                                             |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 52-81-01PROC. REF: AMM 52-81-01     |         |                                                                                               |          |          |                        |           |           |             |          |
| 322111                                             |         | NOSE LANDING GEAR CHASSIS ASSEMBLY                                                            |          |          |                        |           |           | Component   | ATA:32   |
| PN:PN                                              | MOS/MSC | 09-Mar-01                                                                                     | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0                                                                                             |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL     | 0                                                                                             |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |         |                                                                                               |          |          |                        |           |           |             |          |
| 322121                                             |         | NOSE LANDING GEAR UPLOCK MECHANISM                                                            |          |          |                        |           |           | Component   | ATA:32   |
| PN:PN                                              | MOS/MSC | 09-Mar-01                                                                                     | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0                                                                                             |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL     | 0                                                                                             |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 32-32-02PROC. REF: AMM 32-32-02     |         |                                                                                               |          |          |                        |           |           |             |          |
| 323001                                             |         | LEFT * MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY REPLACE                                 |          |          |                        |           |           | Component   | ATA:32   |
| PN:200-0300-003                                    | MOS     | 02-Aug-24                                                                                     |          |          |                        |           |           | LIFE LIMIT  |          |
| SN:H0134                                           | HRS     | 9525.7                                                                                        |          |          |                        |           |           |             |          |
|                                                    | AFL     | 7276                                                                                          | 17000    | TSN 7276 | 17000                  |           | 9628      |             |          |
| Special Properties: RII ITEM                       |         |                                                                                               |          |          |                        |           |           |             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|---------|------|-----|----------|----------|------------------------|-----------|-----------|-------------|----------|
|---------|------|-----|----------|----------|------------------------|-----------|-----------|-------------|----------|

## ATA 32 - LANDING GEAR

|                                                    |                                                                                                                                   |           |       |          |           |  |        |         |        |
|----------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------|-----------|-------|----------|-----------|--|--------|---------|--------|
| 323001A                                            | INSPECT LH MAIN LANDING GEAR SIDE-STAY ACTUATOR - DISASSEMBLE ACTUATOR AND PERFORM DETAILED VISUAL INSPECTION.<br>(IRN AA3220111) |           |       |          |           |  |        | Service | ATA:32 |
|                                                    | MOS                                                                                                                               | 30-Mar-21 | 96    | Adj -44d | 14-Feb-29 |  | 1414 d |         |        |
|                                                    | HRS                                                                                                                               | 8414.4    |       |          |           |  |        |         |        |
|                                                    | AFL                                                                                                                               | 6463      | 10000 |          | 16463     |  | 9091   |         |        |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                                                                                   |           |       |          |           |  |        |         |        |

|                              |                                                                |           |       |          |       |  |      |            |        |
|------------------------------|----------------------------------------------------------------|-----------|-------|----------|-------|--|------|------------|--------|
| 323002                       | RIGHT * MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY REPLACE |           |       |          |       |  |      | Component  | ATA:32 |
| PN:200-0300-004              | MOS                                                            | 02-Aug-24 |       |          |       |  |      | LIFE LIMIT |        |
| SN:H1188                     | HRS                                                            | 9525.7    |       |          |       |  |      |            |        |
|                              | AFL                                                            | 7276      | 17000 | TSN 7276 | 17000 |  | 9628 |            |        |
| Special Properties: RII ITEM |                                                                |           |       |          |       |  |      |            |        |

|                                                    |                                                                                                                                   |           |       |          |           |  |        |         |        |
|----------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------|-----------|-------|----------|-----------|--|--------|---------|--------|
| 323002A                                            | INSPECT RH MAIN LANDING GEAR SIDE-STAY ACTUATOR - DISASSEMBLE ACTUATOR AND PERFORM DETAILED VISUAL INSPECTION.<br>(IRN AA3220111) |           |       |          |           |  |        | Service | ATA:32 |
|                                                    | MOS                                                                                                                               | 30-Mar-21 | 96    | Adj -44d | 14-Feb-29 |  | 1414 d |         |        |
|                                                    | HRS                                                                                                                               | 8414.4    |       |          |           |  |        |         |        |
|                                                    | AFL                                                                                                                               | 6463      | 10000 |          | 16463     |  | 9091   |         |        |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                                                                                   |           |       |          |           |  |        |         |        |

|                                                |                                                    |           |     |       |  |  |  |           |        |
|------------------------------------------------|----------------------------------------------------|-----------|-----|-------|--|--|--|-----------|--------|
| 323037                                         | MAIN LANDING GEAR UPLOCK INBD DOOR, LEFT MECHANISM |           |     |       |  |  |  | Component | ATA:32 |
| PN:PN                                          | MOS/MSC                                            | 09-Mar-01 | O/C | TSN 0 |  |  |  |           |        |
| SN:UNKNOWN                                     | HRS                                                | 0         |     | TSN 0 |  |  |  |           |        |
|                                                | AFL                                                | 0         |     | TSN 0 |  |  |  |           |        |
| PROC. REF: AMM 32-31-04PROC. REF: AMM 32-31-04 |                                                    |           |     |       |  |  |  |           |        |

|                                                |                                                     |           |     |        |  |  |  |           |        |
|------------------------------------------------|-----------------------------------------------------|-----------|-----|--------|--|--|--|-----------|--------|
| 323038                                         | MAIN LANDING GEAR UPLOCK INBD DOOR, RIGHT MECHANISM |           |     |        |  |  |  | Component | ATA:32 |
| PN:6632303004-006                              | MOS/MSC                                             | 08-Sep-12 | O/C | TSR 31 |  |  |  |           |        |
| SN:0117                                        | HRS                                                 | 6989.1    |     | TSR 0  |  |  |  |           |        |
|                                                | AFL                                                 | 5335      |     | TSR 0  |  |  |  |           |        |
| PROC. REF: AMM 32-31-04PROC. REF: AMM 32-31-04 |                                                     |           |     |        |  |  |  |           |        |

|            |                                           |           |     |       |  |  |  |           |        |
|------------|-------------------------------------------|-----------|-----|-------|--|--|--|-----------|--------|
| 323110     | NOSE LANDING GEAR DOWN-LOCK (S139) SWITCH |           |     |       |  |  |  | Component | ATA:32 |
| PN:PN      | MOS/MSC                                   | 09-Mar-01 | O/C | TSN 0 |  |  |  |           |        |
| SN:UNKNOWN | HRS                                       | 0         |     | TSN 0 |  |  |  |           |        |
|            | AFL                                       | 0         |     | TSN 0 |  |  |  |           |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|---------|------|-----|----------|----------|------------------------|-----------|-----------|-------------|----------|
|---------|------|-----|----------|----------|------------------------|-----------|-----------|-------------|----------|

ATA 32 - LANDING GEAR

PROC. REF: AMM 32-60-05PROC. REF: AMM 32-60-05

|                                                |                              |           |     |       |  |  |  |           |        |
|------------------------------------------------|------------------------------|-----------|-----|-------|--|--|--|-----------|--------|
| 323220                                         | DOWN AND LOCKED (S96) SWITCH |           |     |       |  |  |  | Component | ATA:32 |
| PN:PN                                          | MOS/MSC                      | 09-Mar-01 | O/C | TSN 0 |  |  |  |           |        |
| SN:UNKNOWN                                     | HRS                          | 0         |     | TSN 0 |  |  |  |           |        |
|                                                | AFL                          | 0         |     | TSN 0 |  |  |  |           |        |
| PROC. REF: AMM 32-60-02PROC. REF: AMM 32-60-02 |                              |           |     |       |  |  |  |           |        |

|                                                |                               |           |     |       |  |  |  |           |        |
|------------------------------------------------|-------------------------------|-----------|-----|-------|--|--|--|-----------|--------|
| 323221                                         | DOWN AND LOCKED (S100) SWITCH |           |     |       |  |  |  | Component | ATA:32 |
| PN:PN                                          | MOS/MSC                       | 09-Mar-01 | O/C | TSN 0 |  |  |  |           |        |
| SN:UNKNOWN                                     | HRS                           | 0         |     | TSN 0 |  |  |  |           |        |
|                                                | AFL                           | 0         |     | TSN 0 |  |  |  |           |        |
| PROC. REF: AMM 32-60-02PROC. REF: AMM 32-60-02 |                               |           |     |       |  |  |  |           |        |

|                                                |                                                                                                        |           |     |  |  |  |  |           |        |
|------------------------------------------------|--------------------------------------------------------------------------------------------------------|-----------|-----|--|--|--|--|-----------|--------|
| 323301                                         | * REPLACE LEFT MAIN LANDING GEAR INBOARD DOOR ACTUATOR (P/N 7469-1) CAP SCREWS (IRN L3231024) ASSEMBLY |           |     |  |  |  |  | Component | ATA:32 |
| PN:6632303003-003                              | MOS/MSC                                                                                                | 13-Apr-07 | O/C |  |  |  |  |           |        |
| SN:0779                                        | HRS                                                                                                    | 5383.5    |     |  |  |  |  |           |        |
|                                                | AFL                                                                                                    | 4119      |     |  |  |  |  |           |        |
| PROC. REF: AMM 32-31-02PROC. REF: AMM 32-31-02 |                                                                                                        |           |     |  |  |  |  |           |        |

|                                                |                                                                                                         |           |     |                   |  |  |  |           |        |
|------------------------------------------------|---------------------------------------------------------------------------------------------------------|-----------|-----|-------------------|--|--|--|-----------|--------|
| 323302                                         | * REPLACE RIGHT MAIN LANDING GEAR INBOARD DOOR ACTUATOR (P/N 7469-1) CAP SCREWS (IRN L3231024) ASSEMBLY |           |     |                   |  |  |  | Component | ATA:32 |
| PN:7469-1                                      | MOS/MSC                                                                                                 | 25-Jul-12 | O/C | TSN 136, TSR 0    |  |  |  |           |        |
| SN:0004                                        | HRS                                                                                                     | 6961.3    |     | TSN 6961.3, TSR 0 |  |  |  |           |        |
|                                                | AFL                                                                                                     | 5311      |     | TSN 5311, TSR 0   |  |  |  |           |        |
| PROC. REF: AMM 32-31-02PROC. REF: AMM 32-31-02 |                                                                                                         |           |     |                   |  |  |  |           |        |

|                                                |                                   |           |     |       |  |  |  |           |        |
|------------------------------------------------|-----------------------------------|-----------|-----|-------|--|--|--|-----------|--------|
| 323305                                         | LEFT MLG ACTUATOR GIMBAL ASSEMBLY |           |     |       |  |  |  | Component | ATA:32 |
| PN:PN                                          | MOS/MSC                           | 09-Mar-01 | O/C | TSN 0 |  |  |  |           |        |
| SN:UNKNOWN                                     | HRS                               | 0         |     | TSN 0 |  |  |  |           |        |
|                                                | AFL                               | 0         |     | TSN 0 |  |  |  |           |        |
| PROC. REF: AMM 32-31-06PROC. REF: AMM 32-31-06 |                                   |           |     |       |  |  |  |           |        |

|                                                |                                    |           |     |  |  |  |  |           |        |
|------------------------------------------------|------------------------------------|-----------|-----|--|--|--|--|-----------|--------|
| 323306                                         | RIGHT MLG ACTUATOR GIMBAL ASSEMBLY |           |     |  |  |  |  | Component | ATA:32 |
| PN:PN-UNKNOWN                                  | MOS/MSC                            | 25-Jul-10 | O/C |  |  |  |  |           |        |
| SN:UNKNOWN                                     | HRS                                | 6330.6    |     |  |  |  |  |           |        |
|                                                | AFL                                | 4850      |     |  |  |  |  |           |        |
| PROC. REF: AMM 32-31-06PROC. REF: AMM 32-31-06 |                                    |           |     |  |  |  |  |           |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR    Serial: 45-145    RegNo: N942FK    HRS: 9669.1    AFL: 7372    As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                                    | Unit    | C / W     | Interval | TSX / Adj. | Next Due (ENG / APU) A / C | Max Limit | Remaining | Disposition | Warranty |
|------------------------------------------------------------|---------|-----------|----------|------------|----------------------------|-----------|-----------|-------------|----------|
| ATA 32 - LANDING GEAR                                      |         |           |          |            |                            |           |           |             |          |
| 323307      LEFT MLG SHAFT GIMBAL ASSEMBLY                 |         |           |          |            |                            |           |           | Component   | ATA:32   |
| PN:PN                                                      | MOS/MSC | 09-Mar-01 | O/C      | TSN 0      |                            |           |           |             |          |
| SN:UNKNOWN                                                 | HRS     | 0         |          | TSN 0      |                            |           |           |             |          |
|                                                            | AFL     | 0         |          | TSN 0      |                            |           |           |             |          |
| PROC. REF: AMM 32-31-06PROC. REF: AMM 32-31-06             |         |           |          |            |                            |           |           |             |          |
|                                                            |         |           |          |            |                            |           |           |             |          |
| 323308      RIGHT MLG SHAFT GIMBAL ASSEMBLY                |         |           |          |            |                            |           |           | Component   | ATA:32   |
| PN:PN-UNKNOWN                                              | MOS/MSC | 25-Jul-10 | O/C      |            |                            |           |           |             |          |
| SN:UNKNOWN                                                 | HRS     | 6330.6    |          |            |                            |           |           |             |          |
|                                                            | AFL     | 4850      |          |            |                            |           |           |             |          |
| PROC. REF: AMM 32-31-06PROC. REF: AMM 32-31-06             |         |           |          |            |                            |           |           |             |          |
|                                                            |         |           |          |            |                            |           |           |             |          |
| 323309      LEFT MLG INBOARD DOOR GIMBAL BRACKET ASSEMBLY  |         |           |          |            |                            |           |           | Component   | ATA:32   |
| PN:PN                                                      | MOS/MSC | 09-Mar-01 | O/C      | TSN 0      |                            |           |           |             |          |
| SN:UNKNOWN                                                 | HRS     | 0         |          | TSN 0      |                            |           |           |             |          |
|                                                            | AFL     | 0         |          | TSN 0      |                            |           |           |             |          |
| PROC. REF: AMM 32-31-06PROC. REF: AMM 32-31-06             |         |           |          |            |                            |           |           |             |          |
|                                                            |         |           |          |            |                            |           |           |             |          |
| 323310      RIGHT MLG INBOARD DOOR GIMBAL BRACKET ASSEMBLY |         |           |          |            |                            |           |           | Component   | ATA:32   |
| PN:PN                                                      | MOS/MSC | 09-Mar-01 | O/C      | TSN 0      |                            |           |           |             |          |
| SN:UNKNOWN                                                 | HRS     | 0         |          | TSN 0      |                            |           |           |             |          |
|                                                            | AFL     | 0         |          | TSN 0      |                            |           |           |             |          |
| PROC. REF: AMM 32-31-06PROC. REF: AMM 32-31-06             |         |           |          |            |                            |           |           |             |          |
|                                                            |         |           |          |            |                            |           |           |             |          |
| 323735      CONTROL VALVE                                  |         |           |          |            |                            |           |           | Component   | ATA:32   |
| PN:PN                                                      | MOS/MSC | 09-Mar-01 | O/C      | TSN 0      |                            |           |           |             |          |
| SN:UNKNOWN                                                 | HRS     | 0         |          | TSN 0      |                            |           |           |             |          |
|                                                            | AFL     | 0         |          | TSN 0      |                            |           |           |             |          |
| PROC. REF: AMM 32-30-01PROC. REF: AMM 32-30-01             |         |           |          |            |                            |           |           |             |          |
|                                                            |         |           |          |            |                            |           |           |             |          |
| 324001      NO. 1 MAIN LANDING GEAR WHEEL                  |         |           |          |            |                            |           |           | Component   | ATA:32   |
| PN:3-1545-1                                                | MOS/MSC | 21-Feb-25 | O/C      |            |                            |           |           |             |          |
| SN:1194                                                    | HRS     | 9637.3    |          |            |                            |           |           |             |          |
|                                                            | AFL     | 7352      |          |            |                            |           |           |             |          |
| PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02             |         |           |          |            |                            |           |           |             |          |

?-Insufficient Information    S-Suppressed Requirement    \*-Estimated Due(New Requirement)    (EFF)-Effective C/W    (M)-Manual Due    U-User Task    Ex-Excluded Task



Status Report

Model: LEARJET 45XR    Serial: 45-145    RegNo: N942FK    HRS: 9669.1    AFL: 7372    As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                            | Unit    | C / W                                              | Interval | TSX / Adj. | Next Due (ENG / APU) A / C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------|---------|----------------------------------------------------|----------|------------|----------------------------|-----------|-----------|-------------|----------|
| ATA 32 - LANDING GEAR                              |         |                                                    |          |            |                            |           |           |             |          |
| 324001A                                            |         | NON DESTRUCTIVE TEST NO. 1 MAIN LANDING GEAR WHEEL |          |            |                            |           |           | Service     | ATA:32   |
| PN:3-1545-1                                        | MOS/MSC | 21-Feb-25                                          | A/R      |            |                            |           |           |             |          |
| SN:1194                                            | HRS     | 9637.3                                             |          |            |                            |           |           |             |          |
|                                                    | AFL     | 7352                                               |          |            |                            |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |         |                                                    |          |            |                            |           |           |             |          |
| 324002                                             |         | NO. 2 MAIN LANDING GEAR WHEEL                      |          |            |                            |           |           | Component   | ATA:32   |
| PN:3-1545-1                                        | MOS/MSC | 21-Feb-25                                          | O/C      |            |                            |           |           |             |          |
| SN:0809                                            | HRS     | 9637.3                                             |          |            |                            |           |           |             |          |
|                                                    | AFL     | 7352                                               |          |            |                            |           |           |             |          |
| PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02     |         |                                                    |          |            |                            |           |           |             |          |
| 324002A                                            |         | NON DESTRUCTIVE TEST NO. 2 MAIN LANDING GEAR WHEEL |          |            |                            |           |           | Service     | ATA:32   |
| PN:3-1545-1                                        | MOS/MSC | 21-Feb-25                                          | A/R      |            |                            |           |           |             |          |
| SN:0809                                            | HRS     | 9637.3                                             |          |            |                            |           |           |             |          |
|                                                    | AFL     | 7352                                               |          |            |                            |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |         |                                                    |          |            |                            |           |           |             |          |
| 324003                                             |         | NO. 3 MAIN LANDING GEAR WHEEL                      |          |            |                            |           |           | Component   | ATA:32   |
| PN:3-1545-1                                        | MOS/MSC | 21-Feb-25                                          | O/C      |            |                            |           |           |             |          |
| SN:3275                                            | HRS     | 9637.3                                             |          |            |                            |           |           |             |          |
|                                                    | AFL     | 7352                                               |          |            |                            |           |           |             |          |
| PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02     |         |                                                    |          |            |                            |           |           |             |          |
| 324003A                                            |         | NON DESTRUCTIVE TEST NO. 3 MAIN LANDING GEAR WHEEL |          |            |                            |           |           | Service     | ATA:32   |
| PN:3-1545-1                                        | MOS/MSC | 21-Feb-25                                          | A/R      |            |                            |           |           |             |          |
| SN:3275                                            | HRS     | 9637.3                                             |          |            |                            |           |           |             |          |
|                                                    | AFL     | 7352                                               |          |            |                            |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |         |                                                    |          |            |                            |           |           |             |          |
| 324004                                             |         | NO. 4 MAIN LANDING GEAR WHEEL                      |          |            |                            |           |           | Component   | ATA:32   |
| PN:3-1545-1                                        | MOS/MSC | 21-Feb-25                                          | O/C      |            |                            |           |           |             |          |
| SN:0831                                            | HRS     | 9637.3                                             |          |            |                            |           |           |             |          |
|                                                    | AFL     | 7352                                               |          |            |                            |           |           |             |          |
| PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02     |         |                                                    |          |            |                            |           |           |             |          |

?-Insufficient Information    S-Suppressed Requirement    \*-Estimated Due(New Requirement)    (EFF)-Effective C/W    (M)-Manual Due    U-User Task    Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                            | Unit                                               | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------|----------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 32 - LANDING GEAR                              |                                                    |           |          |          |                        |           |           |             |                  |
| 324004A                                            | NON DESTRUCTIVE TEST NO. 4 MAIN LANDING GEAR WHEEL |           |          |          |                        |           |           |             | Service ATA:32   |
| PN:3-1545-1                                        | MOS/MSC                                            | 21-Feb-25 | A/R      |          |                        |           |           |             |                  |
| SN:0831                                            | HRS                                                | 9637.3    |          |          |                        |           |           |             |                  |
|                                                    | AFL                                                | 7352      |          |          |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                    |           |          |          |                        |           |           |             |                  |
| 324005                                             | NOSE GEAR WHEEL ASSEMBLY                           |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:9544207-4                                       | MOS/MSC                                            | 21-Feb-25 | O/C      |          |                        |           |           |             |                  |
| SN:OCT07-2939                                      | HRS                                                | 9637.3    |          |          |                        |           |           |             |                  |
|                                                    | AFL                                                | 7352      |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 32-40-01PROC. REF: AMM 32-40-01     |                                                    |           |          |          |                        |           |           |             |                  |
| 324021                                             | NO. 1 MAIN LANDING GEAR TIRE                       |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:226K08-4                                        | MOS/MSC                                            | 21-Feb-25 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:41910755                                        | HRS                                                | 9637.3    |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                                | 7352      |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02     |                                                    |           |          |          |                        |           |           |             |                  |
| 324022                                             | NO. 2 MAIN LANDING GEAR TIRE                       |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:226K08-4                                        | MOS/MSC                                            | 21-Feb-25 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:41920768                                        | HRS                                                | 9637.3    |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                                | 7352      |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02     |                                                    |           |          |          |                        |           |           |             |                  |
| 324023                                             | NO. 3 MAIN LANDING GEAR TIRE                       |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:226K08-4                                        | MOS/MSC                                            | 21-Feb-25 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:41670649                                        | HRS                                                | 9637.3    |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                                | 7352      |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02     |                                                    |           |          |          |                        |           |           |             |                  |
| 324024                                             | NO. 4 MAIN LANDING GEAR TIRE                       |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:226K08-4                                        | MOS/MSC                                            | 21-Feb-25 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:42950939                                        | HRS                                                | 9637.3    |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                                | 7352      |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02     |                                                    |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                            | Unit                          | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------|-------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 32 - LANDING GEAR                              |                               |           |          |          |                        |           |           |             |                  |
| 324025                                             | NOSE LANDING GEAR TIRE        |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:031-613-8                                       | MOS/MSC                       | 21-Feb-25 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:3005T00435                                      | HRS                           | 9637.3    |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                           | 7352      |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 32-40-01PROC. REF: AMM 32-40-01     |                               |           |          |          |                        |           |           |             |                  |
| 324061                                             | LEFT ANTI-SKID CONTROL VALVE  |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:PN                                              | MOS/MSC                       | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                           | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                           | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 32-41-07PROC. REF: AMM 32-41-07     |                               |           |          |          |                        |           |           |             |                  |
| 324062                                             | RIGHT ANTI-SKID CONTROL VALVE |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:PN                                              | MOS/MSC                       | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                           | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                           | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 32-41-07PROC. REF: AMM 32-41-07     |                               |           |          |          |                        |           |           |             |                  |
| 324066                                             | LEFT ANTI-SKID SHUTOFF VALVE  |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:PN                                              | MOS/MSC                       | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                           | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                           | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                               |           |          |          |                        |           |           |             |                  |
| 324067                                             | RIGHT ANTI-SKID SHUTOFF VALVE |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:PN                                              | MOS/MSC                       | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                           | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                           | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                               |           |          |          |                        |           |           |             |                  |
| 324097                                             | BRAKE CONTROL UNIT            |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:42-933-3                                        | MOS/MSC                       | 03-Jan-06 | O/C      |          |                        |           |           |             |                  |
| SN:150                                             | HRS                           | 4160.77   |          |          |                        |           |           |             |                  |
|                                                    | AFL                           | 3151      |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 32-41-02PROC. REF: AMM 32-41-02     |                               |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                        | Unit                                      | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|------------------------------------------------|-------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 32 - LANDING GEAR                          |                                           |           |          |          |                        |           |           |             |                  |
| 324108                                         | EMERGENCY PARKING BRAKE CHECK VALVE       |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:1C4124                                      | MOS/MSC                                   | 19-Mar-05 | O/C      |          |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                       | 3391.45   |          |          |                        |           |           |             |                  |
|                                                | AFL                                       | 2574      |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 32-42-09PROC. REF: AMM 32-42-09 |                                           |           |          |          |                        |           |           |             |                  |
| 324109                                         | EMERGENCY/PARK BRAKE VALVE                |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:PN                                          | MOS/MSC                                   | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                       | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                       | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 32-42-01PROC. REF: AMM 32-42-01 |                                           |           |          |          |                        |           |           |             |                  |
| 324110                                         | PRESSURE, EMERGENCY/PARK BRAKE TRANSDUCER |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:PN                                          | MOS/MSC                                   | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                       | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                       | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 32-42-03PROC. REF: AMM 32-42-03 |                                           |           |          |          |                        |           |           |             |                  |
| 324111                                         | NO. 1 ASSEMBLY, MAIN LANDING GEAR BRAKE   |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:PN                                          | MOS/MSC                                   | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                       | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                       | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01 |                                           |           |          |          |                        |           |           |             |                  |
| 324112                                         | NO. 2 ASSEMBLY, MAIN LANDING GEAR BRAKE   |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:6632401000-002                              | MOS/MSC                                   | 27-Aug-21 | O/C      |          |                        |           |           |             |                  |
| SN:2262                                        | HRS                                       | 8708.2    |          |          |                        |           |           |             |                  |
|                                                | AFL                                       | 6691      |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01 |                                           |           |          |          |                        |           |           |             |                  |
| 324113                                         | NO. 3 ASSEMBLY, MAIN LANDING GEAR BRAKE   |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:6632401000-002                              | MOS/MSC                                   | 25-Nov-19 | O/C      | TSO 0    |                        |           |           |             |                  |
| SN:1975                                        | HRS                                       | 8177.7    |          | TSO 0    |                        |           |           |             |                  |
|                                                | AFL                                       | 6303      |          | TSO 0    |                        |           |           |             |                  |
| PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01 |                                           |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR    Serial: 45-145    RegNo: N942FK    HRS: 9669.1    AFL: 7372    As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                        | Unit                                    | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty            |
|------------------------------------------------|-----------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|---------------------|
| ATA 32 - LANDING GEAR                          |                                         |           |          |          |                        |           |           |             |                     |
| 324114                                         | NO. 4 ASSEMBLY, MAIN LANDING GEAR BRAKE |           |          |          |                        |           |           |             | Component    ATA:32 |
| PN:2-1579-2                                    | MOS/MSC                                 | 15-Jul-11 | O/C      | TSO 0    |                        |           |           |             |                     |
| SN:0917SB                                      | HRS                                     | 6651.4    |          | TSO 0    |                        |           |           |             |                     |
|                                                | AFL                                     | 5089      |          | TSO 0    |                        |           |           |             |                     |
| PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01 |                                         |           |          |          |                        |           |           |             |                     |
| 324201                                         | NO. 1 BRAKE SHUTTLE VALVE               |           |          |          |                        |           |           |             | Component    ATA:32 |
| PN:PN                                          | MOS/MSC                                 | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                     | HRS                                     | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                | AFL                                     | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: AMM 32-42-04PROC. REF: AMM 32-42-04 |                                         |           |          |          |                        |           |           |             |                     |
| 324202                                         | NO. 2 BRAKE SHUTTLE VALVE               |           |          |          |                        |           |           |             | Component    ATA:32 |
| PN:PN                                          | MOS/MSC                                 | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                     | HRS                                     | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                | AFL                                     | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: AMM 32-42-04PROC. REF: AMM 32-42-04 |                                         |           |          |          |                        |           |           |             |                     |
| 324203                                         | NO. 3 BRAKE SHUTTLE VALVE               |           |          |          |                        |           |           |             | Component    ATA:32 |
| PN:PN                                          | MOS/MSC                                 | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                     | HRS                                     | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                | AFL                                     | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: AMM 32-42-04PROC. REF: AMM 32-42-04 |                                         |           |          |          |                        |           |           |             |                     |
| 324204                                         | NO. 4 BRAKE SHUTTLE VALVE               |           |          |          |                        |           |           |             | Component    ATA:32 |
| PN:PN                                          | MOS/MSC                                 | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                     | HRS                                     | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                | AFL                                     | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: AMM 32-42-04PROC. REF: AMM 32-42-04 |                                         |           |          |          |                        |           |           |             |                     |
| 324205                                         | BRAKE SHUTTLE MODULE                    |           |          |          |                        |           |           |             | Component    ATA:32 |
| PN:PN                                          | MOS/MSC                                 | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                     | HRS                                     | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                | AFL                                     | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: AMM 32-41-04PROC. REF: AMM 32-41-04 |                                         |           |          |          |                        |           |           |             |                     |

?-Insufficient Information    S-Suppressed Requirement    \*-Estimated Due(New Requirement)    (EFF)-Effective C/W    (M)-Manual Due    U-User Task    Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                        | Unit    | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|------------------------------------------------|---------|-----------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 32 - LANDING GEAR                          |         |           |          |          |                        |           |           |             |          |
| 324305 LEFT PILOT BRAKE TRANSDUCER             |         |           |          |          |                        |           |           | Component   | ATA:32   |
| PN:PN                                          | MOS/MSC | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL     | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 32-41-03PROC. REF: AMM 32-41-03 |         |           |          |          |                        |           |           |             |          |
|                                                |         |           |          |          |                        |           |           |             |          |
| 324306 RIGHT PILOT BRAKE TRANSDUCER            |         |           |          |          |                        |           |           | Component   | ATA:32   |
| PN:PN                                          | MOS/MSC | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL     | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 32-41-03PROC. REF: AMM 32-41-03 |         |           |          |          |                        |           |           |             |          |
|                                                |         |           |          |          |                        |           |           |             |          |
| 324610-1 LEFT INBOARD BRAKE SWIVEL             |         |           |          |          |                        |           |           | Component   | ATA:32   |
| PN:PN                                          | MOS/MSC | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL     | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01 |         |           |          |          |                        |           |           |             |          |
|                                                |         |           |          |          |                        |           |           |             |          |
| 324610-2 LEFT OUTBOARD BRAKE SWIVEL            |         |           |          |          |                        |           |           | Component   | ATA:32   |
| PN:PN                                          | MOS/MSC | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL     | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01 |         |           |          |          |                        |           |           |             |          |
|                                                |         |           |          |          |                        |           |           |             |          |
| 324611-1 RIGHT INBOARD BRAKE SWIVEL            |         |           |          |          |                        |           |           | Component   | ATA:32   |
| PN:PN                                          | MOS/MSC | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL     | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01 |         |           |          |          |                        |           |           |             |          |
|                                                |         |           |          |          |                        |           |           |             |          |
| 324611-2 RIGHT OUTBOARD BRAKE SWIVEL           |         |           |          |          |                        |           |           | Component   | ATA:32   |
| PN:PN                                          | MOS/MSC | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL     | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01 |         |           |          |          |                        |           |           |             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR    Serial: 45-145    RegNo: N942FK    HRS: 9669.1    AFL: 7372    As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                        | Unit                                     | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty            |
|------------------------------------------------|------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|---------------------|
| ATA 32 - LANDING GEAR                          |                                          |           |          |          |                        |           |           |             |                     |
| 324701                                         | NO. 1 HYDRAULIC, BRAKE FUSE              |           |          |          |                        |           |           |             | Component    ATA:32 |
| PN:PN                                          | MOS/MSC                                  | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                     | HRS                                      | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                | AFL                                      | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: AMM 32-41-09PROC. REF: AMM 32-41-09 |                                          |           |          |          |                        |           |           |             |                     |
| 324702                                         | NO. 2 HYDRAULIC, BRAKE FUSE              |           |          |          |                        |           |           |             | Component    ATA:32 |
| PN:PN                                          | MOS/MSC                                  | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                     | HRS                                      | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                | AFL                                      | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: AMM 32-41-09PROC. REF: AMM 32-41-09 |                                          |           |          |          |                        |           |           |             |                     |
| 324703                                         | NO. 3 HYDRAULIC, BRAKE FUSE              |           |          |          |                        |           |           |             | Component    ATA:32 |
| PN:PN                                          | MOS/MSC                                  | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                     | HRS                                      | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                | AFL                                      | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: AMM 32-41-09PROC. REF: AMM 32-41-09 |                                          |           |          |          |                        |           |           |             |                     |
| 324704                                         | NO. 4 HYDRAULIC, BRAKE FUSE              |           |          |          |                        |           |           |             | Component    ATA:32 |
| PN:PN                                          | MOS/MSC                                  | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                     | HRS                                      | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                | AFL                                      | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: AMM 32-41-09PROC. REF: AMM 32-41-09 |                                          |           |          |          |                        |           |           |             |                     |
| 324711                                         | NO. 1 WHEEL SPEED - ANTI-SKID TRANSDUCER |           |          |          |                        |           |           |             | Component    ATA:32 |
| PN:140-183                                     | MOS/MSC                                  | 17-Nov-20 | O/C      |          |                        |           |           |             |                     |
| SN:3456                                        | HRS                                      | 8301.3    |          |          |                        |           |           |             |                     |
|                                                | AFL                                      | 6392      |          |          |                        |           |           |             |                     |
| PROC. REF: AMM 32-41-10PROC. REF: AMM 32-41-10 |                                          |           |          |          |                        |           |           |             |                     |
| 324712                                         | NO. 2 WHEEL SPEED - ANTI-SKID TRANSDUCER |           |          |          |                        |           |           |             | Component    ATA:32 |
| PN:PN                                          | MOS/MSC                                  | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                     | HRS                                      | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                | AFL                                      | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: AMM 32-41-10PROC. REF: AMM 32-41-10 |                                          |           |          |          |                        |           |           |             |                     |

?-Insufficient Information    S-Suppressed Requirement    \*-Estimated Due(New Requirement)    (EFF)-Effective C/W    (M)-Manual Due    U-User Task    Ex-Excluded Task

Status Report

Model: LEARJET 45XR    Serial: 45-145    RegNo: N942FK    HRS: 9669.1    AFL: 7372    As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                        | Unit                                      | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty            |
|------------------------------------------------|-------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|---------------------|
| ATA 32 - LANDING GEAR                          |                                           |           |          |          |                        |           |           |             |                     |
| 324713                                         | NO. 3 WHEEL SPEED - ANTI-SKID TRANSDUCER  |           |          |          |                        |           |           |             | Component    ATA:32 |
| PN:PN                                          | MOS/MSC                                   | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                     | HRS                                       | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                | AFL                                       | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: AMM 32-41-10PROC. REF: AMM 32-41-10 |                                           |           |          |          |                        |           |           |             |                     |
| 324714                                         | NO. 4 WHEEL SPEED - ANTI-SKID TRANSDUCER  |           |          |          |                        |           |           |             | Component    ATA:32 |
| PN:PN                                          | MOS/MSC                                   | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                     | HRS                                       | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                | AFL                                       | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: AMM 32-41-10PROC. REF: AMM 32-41-10 |                                           |           |          |          |                        |           |           |             |                     |
| 324721                                         | (MT56) PRESSURE BRAKE TRANSDUCER ASSEMBLY |           |          |          |                        |           |           |             | Component    ATA:32 |
| PN:PN                                          | MOS/MSC                                   | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                     | HRS                                       | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                | AFL                                       | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: AMM 32-41-08PROC. REF: AMM 32-41-08 |                                           |           |          |          |                        |           |           |             |                     |
| 324722                                         | (MT57) PRESSURE BRAKE TRANSDUCER ASSEMBLY |           |          |          |                        |           |           |             | Component    ATA:32 |
| PN:PN                                          | MOS/MSC                                   | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                     | HRS                                       | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                | AFL                                       | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: AMM 32-41-08PROC. REF: AMM 32-41-08 |                                           |           |          |          |                        |           |           |             |                     |
| 324723                                         | (MT58) PRESSURE BRAKE TRANSDUCER ASSEMBLY |           |          |          |                        |           |           |             | Component    ATA:32 |
| PN:PN                                          | MOS/MSC                                   | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                     | HRS                                       | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                | AFL                                       | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: AMM 32-41-08PROC. REF: AMM 32-41-08 |                                           |           |          |          |                        |           |           |             |                     |
| 324724                                         | (MT59) PRESSURE BRAKE TRANSDUCER ASSEMBLY |           |          |          |                        |           |           |             | Component    ATA:32 |
| PN:PN                                          | MOS/MSC                                   | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                     | HRS                                       | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                | AFL                                       | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: AMM 32-41-08PROC. REF: AMM 32-41-08 |                                           |           |          |          |                        |           |           |             |                     |

?-Insufficient Information    S-Suppressed Requirement    \*-Estimated Due(New Requirement)    (EFF)-Effective C/W    (M)-Manual Due    U-User Task    Ex-Excluded Task



Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                        | Unit                                  | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|------------------------------------------------|---------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 32 - LANDING GEAR                          |                                       |           |          |          |                        |           |           |             |                  |
| 324801                                         | EMERGENCY/PARK BRAKE FUSE             |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:PN                                          | MOS/MSC                               | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                   | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                   | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 32-42-07PROC. REF: AMM 32-42-07 |                                       |           |          |          |                        |           |           |             |                  |
| 324805                                         | EMER/PARK BRAKE ACCUMULATOR           |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:PN                                          | MOS/MSC                               | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                   | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                   | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 32-42-02PROC. REF: AMM 32-42-02 |                                       |           |          |          |                        |           |           |             |                  |
| 325007                                         | FILTER, NOSE WHEEL STEERING (P41) BOX |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:PN                                          | MOS/MSC                               | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                   | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                   | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 32-50-06PROC. REF: AMM 32-50-06 |                                       |           |          |          |                        |           |           |             |                  |
| 325011                                         | NOSE WHEEL STEERING SERVO ACTUATOR    |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:JR5208C                                     | MOS/MSC                               | 13-Feb-08 | O/C      | TSR 4    |                        |           |           |             |                  |
| SN:A0437                                       | HRS                                   | 5967.8    |          | TSR 0    |                        |           |           |             |                  |
|                                                | AFL                                   | 4562      |          | TSR 0    |                        |           |           |             |                  |
| PROC. REF: AMM 32-50-02PROC. REF: AMM 32-50-02 |                                       |           |          |          |                        |           |           |             |                  |
| 325021                                         | NOSE WHEEL STEERING GEARBOX           |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:2W3201D                                     | MOS/MSC                               | 29-Oct-06 | O/C      |          |                        |           |           |             |                  |
| SN:C0347                                       | HRS                                   | 4933.32   |          |          |                        |           |           |             |                  |
|                                                | AFL                                   | 3789      |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 32-50-03PROC. REF: AMM 32-50-03 |                                       |           |          |          |                        |           |           |             |                  |
| 325031                                         | NOSE WHEEL STEERING COMPUTER          |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:PN                                          | MOS/MSC                               | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                   | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                   | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 32-50-01PROC. REF: AMM 32-50-01 |                                       |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                            | Unit                                                                      | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------|---------------------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 32 - LANDING GEAR                              |                                                                           |           |          |          |                        |           |           |             |          |
| 325035                                             | NOSE WHEEL STEERING POWER SUPPLY                                          |           |          |          |                        |           |           | Component   | ATA:32   |
| PN:PN                                              | MOS/MSC                                                                   | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS                                                                       | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL                                                                       | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                           |           |          |          |                        |           |           |             |          |
| 325041                                             | LEFT NOSE WHEEL STEERING TRANSDUCER                                       |           |          |          |                        |           |           | Component   | ATA:32   |
| PN:PN                                              | MOS/MSC                                                                   | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS                                                                       | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL                                                                       | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 32-50-04PROC. REF: AMM 32-50-04     |                                                                           |           |          |          |                        |           |           |             |          |
| 325042                                             | RIGHT NOSE WHEEL STEERING TRANSDUCER                                      |           |          |          |                        |           |           | Component   | ATA:32   |
| PN:PN                                              | MOS/MSC                                                                   | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS                                                                       | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL                                                                       | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 32-50-04PROC. REF: AMM 32-50-04     |                                                                           |           |          |          |                        |           |           |             |          |
| 325051 <sup>S</sup>                                | * NOSE LANDING GEAR ACTUATOR UPPER PIN (IRN O3220011 OR JAA IRN E3220070) |           |          |          |                        |           |           | Component   | ATA:32   |
| PN:4532302043-007                                  | MOS                                                                       | 09-Mar-01 |          | TSN 0    |                        |           |           | LIFE LIMIT  |          |
| SN:132                                             | HRS                                                                       | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL                                                                       | 0         | 20000    | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 32-32-01PROC. REF: AMM 32-32-01     |                                                                           |           |          |          |                        |           |           |             |          |
| 326000                                             | NOSE LANDING GEAR WIRE HARNESS                                            |           |          |          |                        |           |           | Component   | ATA:32   |
| PN:PN                                              | MOS/MSC                                                                   | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS                                                                       | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL                                                                       | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                           |           |          |          |                        |           |           |             |          |
| 326104                                             | NOSE LANDING GEAR SQUAT/WOW (S178) SWITCH                                 |           |          |          |                        |           |           | Component   | ATA:32   |
| PN:PN                                              | MOS/MSC                                                                   | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS                                                                       | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL                                                                       | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 32-50-09PROC. REF: AMM 32-50-09     |                                                                           |           |          |          |                        |           |           |             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                        | Unit                                                                                                                                                                                                                              | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 32 - LANDING GEAR                          |                                                                                                                                                                                                                                   |           |          |          |                        |           |           |             |          |
| 326105                                         | NO. 1 MAIN GEAR SQUAT SWITCH                                                                                                                                                                                                      |           |          |          |                        |           |           | Component   | ATA:32   |
| PN:444EN2-R                                    | MOS/MSC                                                                                                                                                                                                                           | 18-Oct-22 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS                                                                                                                                                                                                                               | 9133.2    |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL                                                                                                                                                                                                                               | 7007      |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 32-60-09PROC. REF: AMM 32-60-09 |                                                                                                                                                                                                                                   |           |          |          |                        |           |           |             |          |
| 326106                                         | NO. 2 MAIN GEAR SQUAT SWITCH                                                                                                                                                                                                      |           |          |          |                        |           |           | Component   | ATA:32   |
| PN:PN                                          | MOS/MSC                                                                                                                                                                                                                           | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS                                                                                                                                                                                                                               | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL                                                                                                                                                                                                                               | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 32-60-09PROC. REF: AMM 32-60-09 |                                                                                                                                                                                                                                   |           |          |          |                        |           |           |             |          |
| 326107                                         | NO. 3 MAIN GEAR SQUAT SWITCH                                                                                                                                                                                                      |           |          |          |                        |           |           | Component   | ATA:32   |
| PN:PN                                          | MOS/MSC                                                                                                                                                                                                                           | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS                                                                                                                                                                                                                               | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL                                                                                                                                                                                                                               | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 32-60-09PROC. REF: AMM 32-60-09 |                                                                                                                                                                                                                                   |           |          |          |                        |           |           |             |          |
| 326108                                         | NO. 4 MAIN GEAR SQUAT SWITCH                                                                                                                                                                                                      |           |          |          |                        |           |           | Component   | ATA:32   |
| PN:PN                                          | MOS/MSC                                                                                                                                                                                                                           | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS                                                                                                                                                                                                                               | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL                                                                                                                                                                                                                               | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 32-60-09PROC. REF: AMM 32-60-09 |                                                                                                                                                                                                                                   |           |          |          |                        |           |           |             |          |
| 326115                                         | SQUAT SWITCH P21 RELAY BOX                                                                                                                                                                                                        |           |          |          |                        |           |           | Component   | ATA:32   |
| PN:PN                                          | MOS/MSC                                                                                                                                                                                                                           | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS                                                                                                                                                                                                                               | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL                                                                                                                                                                                                                               | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 32-60-08PROC. REF: AMM 32-60-08 |                                                                                                                                                                                                                                   |           |          |          |                        |           |           |             |          |
| 5-19-00-D3260006                               | LUBRICATE NOSE LANDING GEAR SQUAT SWITCH ROTATING DISK ASSEMBLY. EFFECTIVE ON AIRCRAFT 45-001 THRU 45-071 MODIFIED PER SB 45-32-3 AND AIRCRAFT 45-072 THROUGH 45-114 NOT MODIFIED PER SB 45-32-8. (ZONE/ACCESS 700 IRN # D326006) |           |          |          |                        |           |           | Service     | ATA:32   |
|                                                | MOS/MSC                                                                                                                                                                                                                           | 09-Mar-01 | N/A      |          |                        |           |           |             |          |
|                                                | HRS                                                                                                                                                                                                                               | 0         |          |          |                        |           |           |             |          |
|                                                | AFL                                                                                                                                                                                                                               | 0         |          |          |                        |           |           |             |          |
| PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01 |                                                                                                                                                                                                                                   |           |          |          |                        |           |           |             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                                      | Unit                                                                                                                                                      | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty       |
|--------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|---------------|----------------|
| ATA 32 - LANDING GEAR                                        |                                                                                                                                                           |           |          |          |                        |           |           |               |                |
| 5-19-00-J3220120                                             | * MLG TRUNNION SHEAR PIN BUSHING - PERFORM VISUAL INSPECTION FOR BUSHING MIGRATION (IRN J3220120)                                                         |           |          |          |                        |           |           |               | Service ATA:32 |
|                                                              | MOS/MSC                                                                                                                                                   | 09-Mar-01 | O/C      |          |                        |           |           |               |                |
|                                                              | HRS                                                                                                                                                       | 0         |          |          |                        |           |           |               |                |
|                                                              | AFL                                                                                                                                                       | 0         |          |          |                        |           |           |               |                |
| PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05               |                                                                                                                                                           |           |          |          |                        |           |           |               |                |
| 5-19-00-L3220020                                             | * MAIN LANDING GEAR TRUNNION FITTINGS ON MID AND REAR SPAR - PERFORM EDDY CURRENT INSPECTION. (REFER TO NDI MANUAL [NDI-104]. PART 6, 32-11-00 (L3220020) |           |          |          |                        |           |           |               | Service ATA:32 |
|                                                              | MOS                                                                                                                                                       | 09-Mar-01 |          |          |                        |           |           | AIRWORTHINESS |                |
|                                                              | HRS                                                                                                                                                       | 0         |          |          |                        |           |           |               |                |
|                                                              | AFL                                                                                                                                                       | 0         | T:10000  |          | 10000                  |           | 2628      |               |                |
| PROC. REF: NDT PART 6/32-11-00PROC. REF: NDT PART 6/32-11-00 |                                                                                                                                                           |           |          |          |                        |           |           |               |                |
| 5-19-00-P3231020                                             | MAIN LANDING GEAR DOOR ACTUATOR GIMBAL ASSEMBLY - PERFORM EDDY CURRENT INSPECTION                                                                         |           |          |          |                        |           |           |               | Service ATA:32 |
|                                                              | MOS                                                                                                                                                       | 02-Aug-24 |          |          |                        |           |           |               |                |
|                                                              | HRS                                                                                                                                                       | 9525.7    |          |          |                        |           |           |               |                |
|                                                              | AFL                                                                                                                                                       | 7276      | 300      |          | 7576                   |           | 204       |               |                |
| PROC. REF: NDT PART 6/32-13-00PROC. REF: NDT PART 6/32-13-00 |                                                                                                                                                           |           |          |          |                        |           |           |               |                |
| 5-19-00-P3231021                                             | MAIN LANDING GEAR DOOR ACTUATOR GIMBAL SHAFT - PERFORM FLUORESCENT PENETRANT INSPECTION                                                                   |           |          |          |                        |           |           |               | Service ATA:32 |
|                                                              | MOS                                                                                                                                                       | 02-Aug-24 |          |          |                        |           |           |               |                |
|                                                              | HRS                                                                                                                                                       | 9525.7    |          |          |                        |           |           |               |                |
|                                                              | AFL                                                                                                                                                       | 7276      | 300      |          | 7576                   |           | 204       |               |                |
| PROC. REF: NDT PART 8/32-13-02PROC. REF: NDT PART 8/32-13-02 |                                                                                                                                                           |           |          |          |                        |           |           |               |                |
| 5-19-00-W3231022                                             | MAIN LANDING GEAR INBOARD DOOR GIMBAL BRACKET - PERFORM EDDY CURRENT INSPECTION                                                                           |           |          |          |                        |           |           |               | Service ATA:32 |
|                                                              | MOS                                                                                                                                                       | 02-Aug-24 |          |          |                        |           |           |               |                |
|                                                              | HRS                                                                                                                                                       | 9525.7    |          |          |                        |           |           |               |                |
|                                                              | AFL                                                                                                                                                       | 7276      | 300      |          | 7576                   |           | 204       |               |                |
| PROC. REF: NDT PART 6/32-13-01PROC. REF: NDT PART 6/32-13-01 |                                                                                                                                                           |           |          |          |                        |           |           |               |                |
| 5-19-01-D3220046 <sup>U</sup>                                | REPLACE REPLACE MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY (P/N 200-300-001 & -002). (*IRN D3220046)                                                  |           |          |          |                        |           |           |               | Service ATA:32 |
|                                                              | MOS/MSC                                                                                                                                                   | 09-Mar-01 | N/A      |          |                        |           |           | NOT INSTALLED |                |
|                                                              | HRS                                                                                                                                                       | 0         |          |          |                        |           |           |               |                |
|                                                              | AFL                                                                                                                                                       | 0         |          |          |                        |           |           |               |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                        | Unit                                                                                                                                                                                                                                                                                        | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty |
|------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|---------------|----------|
| ATA 32 - LANDING GEAR                          |                                                                                                                                                                                                                                                                                             |           |          |          |                        |           |           |               |          |
| 5-19-01-F3220045                               | REPLACE NOSE LANDING GEAR ACTUATOR ATTACHMENT FITTING (ZINC COATED)                                                                                                                                                                                                                         |           |          |          |                        |           |           | Service       | ATA:32   |
|                                                | MOS/MSC                                                                                                                                                                                                                                                                                     | 09-Mar-01 | N/A      |          |                        |           |           | NOT INSTALLED |          |
|                                                | HRS                                                                                                                                                                                                                                                                                         | 0         |          |          |                        |           |           |               |          |
|                                                | AFL                                                                                                                                                                                                                                                                                         | 0         |          |          |                        |           |           |               |          |
| PROC. REF: AMM 32-32-01PROC. REF: AMM 32-32-01 |                                                                                                                                                                                                                                                                                             |           |          |          |                        |           |           |               |          |
| 5-19-01-L3231024                               | REPLACE INBOARD LEFT AND RIGHT MAIN LANDING GEAR DOOR ACTUATOR (P/N 7469-1) CAP SCREWS. EFFECTIVE ON AIRCRAFT 45-005 THRU 45-276 MODIFIED PER SB 45-32-19, "MAIN LANDING GEAR DOOR ACTUATOR IMPROVEMENT/SADDLE INSTALLATION" AND 45-277 AND SUBSEQUENT. (ZONE/ACCESS 720/730 *IRN L3231024) |           |          |          |                        |           |           | Service       | ATA:32   |
|                                                | MOS                                                                                                                                                                                                                                                                                         | 19-May-22 |          |          |                        |           |           | AIRWORTHINESS |          |
|                                                | HRS                                                                                                                                                                                                                                                                                         | 8995.3    | 2400     |          | 11395.3                |           | 1726.2    |               |          |
|                                                | AFL                                                                                                                                                                                                                                                                                         | 6902      |          |          |                        |           |           |               |          |
| 5-19-01-N3220041                               | REPLACE MAIN LANDING GEAR FORWARD TRUNNION SHEAR PIN (P/N 4532103015 AND 4532103132). (ZONE/ACCESS 720/730 *IRN N3220041)                                                                                                                                                                   |           |          |          |                        |           |           | Service       | ATA:32   |
|                                                | MOS/MSC                                                                                                                                                                                                                                                                                     | 15-Dec-10 | N/A      |          |                        |           |           |               |          |
|                                                | HRS                                                                                                                                                                                                                                                                                         | 6457.2    |          |          |                        |           |           |               |          |
|                                                | AFL                                                                                                                                                                                                                                                                                         | 4944      |          |          |                        |           |           |               |          |
| 5-19-01-N3220042                               | REPLACE MAIN LANDING GEAR AFT TRUNNION SHEAR PIN (P/N 4532103025 AND 4532103133). (ZONE/ACCESS 720/730 *IRN #N3220042)                                                                                                                                                                      |           |          |          |                        |           |           | Service       | ATA:32   |
|                                                | MOS/MSC                                                                                                                                                                                                                                                                                     | 18-Dec-10 | N/A      |          |                        |           |           |               |          |
|                                                | HRS                                                                                                                                                                                                                                                                                         | 6457.2    |          |          |                        |           |           |               |          |
|                                                | AFL                                                                                                                                                                                                                                                                                         | 4944      |          |          |                        |           |           |               |          |
| 5-19-01-N3220043                               | REPLACE MAIN LANDING GEAR AFT LOWER TRUNNION SHEAR PIN (P/N 4532103026 AND 4532103134). (ZONE/ACCESS 720/730 *IRN N3220043)                                                                                                                                                                 |           |          |          |                        |           |           | Service       | ATA:32   |
|                                                | MOS/MSC                                                                                                                                                                                                                                                                                     | 18-Dec-10 | N/A      |          |                        |           |           |               |          |
|                                                | HRS                                                                                                                                                                                                                                                                                         | 6457.2    |          |          |                        |           |           |               |          |
|                                                | AFL                                                                                                                                                                                                                                                                                         | 4944      |          |          |                        |           |           |               |          |
| 5-19-01-N3220139                               | REPLACE MAIN LANDING GEAR FORWARD TRUNNION SHEAR PIN (P/N 4532103201) (ZONE/ACCESS 720/730) (IRN #N3220139)                                                                                                                                                                                 |           |          |          |                        |           |           | Service       | ATA:32   |
|                                                | MOS                                                                                                                                                                                                                                                                                         | 15-Dec-10 |          |          |                        |           |           | LIFE LIMIT    |          |
|                                                | HRS                                                                                                                                                                                                                                                                                         | 6457.2    |          |          |                        |           |           |               |          |
|                                                | AFL                                                                                                                                                                                                                                                                                         | 4944      | 5000     |          | 9944                   |           | 2572      |               |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN               | Unit | C/W                                                                                                            | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|-----------------------|------|----------------------------------------------------------------------------------------------------------------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 32 - LANDING GEAR |      |                                                                                                                |          |          |                        |           |           |             |          |
| 5-19-01-N3220140      | U    | REPLACE MAIN LANDING GEAR AFT TRUNNION UPPER SHEAR PIN (P/N 4532203202) (ZONE/ACCESS 720/730) (IRN # N3220140) |          |          |                        |           |           | Service     | ATA:32   |
|                       | MOS  | 18-Dec-10                                                                                                      |          |          |                        |           |           | LIFE LIMIT  |          |
|                       | HRS  | 6457.2                                                                                                         |          |          |                        |           |           |             |          |
|                       | AFL  | 4944                                                                                                           | 5000     |          | 9944                   |           | 2572      |             |          |
| 5-19-01-N3220141      | U    | REPLACE MAIN LANDING GEAR AFT TRUNNION LOWER SHEAR PIN (P/N 4532103203) (ZONE/ACCESS 720/730) (IRN # N3220141) |          |          |                        |           |           | Service     | ATA:32   |
|                       | MOS  | 18-Dec-10                                                                                                      |          |          |                        |           |           | LIFE LIMIT  |          |
|                       | HRS  | 6457.2                                                                                                         |          |          |                        |           |           |             |          |
|                       | AFL  | 4944                                                                                                           | 5000     |          | 9944                   |           | 2572      |             |          |
| 5-19-01-O3220009      | U    | REPLACE NOSE LANDING GEAR STRUT ASSEMBLY (P/N 2342100) (ZONE/ACCESS 710 *IRN # O3220009)                       |          |          |                        |           |           | Service     | ATA:32   |
|                       | MOS  | 12-Feb-08                                                                                                      |          |          |                        |           |           | LIFE LIMIT  |          |
|                       | HRS  | 5965.9                                                                                                         |          |          |                        |           |           |             |          |
|                       | AFL  | 4561                                                                                                           | 20000    |          | 24561                  |           | 17189     |             |          |
| 5-19-01-O3220010      | U    | REPLACE NOSE LANDING GEAR ACTUATOR ASSEMBLY (P/N 6632201000) (ZONE/ACCESS 710 *IRN # O3220010)                 |          |          |                        |           |           | Service     | ATA:32   |
|                       | MOS  | 09-Mar-01                                                                                                      |          |          |                        |           |           | LIFE LIMIT  |          |
|                       | HRS  | 0                                                                                                              |          |          |                        |           |           |             |          |
|                       | AFL  | 0                                                                                                              | 20000    |          | 20000                  |           | 12628     |             |          |
| 5-19-01-O3220011      | U    | REPLACE NOSE LANDING GEAR ACTUATOR UPPER PIN (P/N 4532302043) (ZONE/ACCESS 710 *IRN # O3220011)                |          |          |                        |           |           | Service     | ATA:32   |
|                       | MOS  | 09-Mar-01                                                                                                      |          |          |                        |           |           | LIFE LIMIT  |          |
|                       | HRS  | 0                                                                                                              |          |          |                        |           |           |             |          |
|                       | AFL  | 0                                                                                                              | 20000    |          | 20000                  |           | 12628     |             |          |
| 5-19-01-O3220028      | U    | REPLACE NOSE LANDING GEAR TRUNNION PINS (P/N 2342108) (ZONE/ACCESS 710 *IRN # O3220028)                        |          |          |                        |           |           | Service     | ATA:32   |
|                       | MOS  | 09-Mar-01                                                                                                      |          |          |                        |           |           | LIFE LIMIT  |          |
|                       | HRS  | 0                                                                                                              |          |          |                        |           |           |             |          |
|                       | AFL  | 0                                                                                                              | 20000    |          | 20000                  |           | 12628     |             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                        | Unit | C / W                                                                                                                                                                      | Interval | TSX / Adj. | Next Due (ENG / APU) A / C | Max Limit | Remaining | Disposition   | Warranty |
|------------------------------------------------|------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|------------|----------------------------|-----------|-----------|---------------|----------|
| ATA 32 - LANDING GEAR                          |      |                                                                                                                                                                            |          |            |                            |           |           |               |          |
| 5-19-01-O3220029                               | U    | REPLACEMENT NOSE LANDING GEAR TRUNNION AXLE (P/N 2342110). (ZONE/ACCESS 710 *IRN O3220029)                                                                                 |          |            |                            |           |           | Service       | ATA:32   |
|                                                | MOS  | 09-Mar-01                                                                                                                                                                  |          |            |                            |           |           | LIFE LIMIT    |          |
|                                                | HRS  | 0                                                                                                                                                                          |          |            |                            |           |           |               |          |
|                                                | AFL  | 0                                                                                                                                                                          | 20000    |            | 20000                      |           | 12628     |               |          |
|                                                |      |                                                                                                                                                                            |          |            |                            |           |           |               |          |
| A3230001                                       | S    | ** LANDING GEAR - PERFORM EMERGENCY GEAR EXTENSION FUNCTIONAL TEST                                                                                                         |          |            |                            |           |           | Service       | ATA:32   |
|                                                | MOS  | 02-Aug-24                                                                                                                                                                  | 24       |            |                            |           |           | AIRWORTHINESS |          |
|                                                | HRS  | 9525.7                                                                                                                                                                     | 600      |            |                            |           |           |               |          |
|                                                | AFL  | 7276                                                                                                                                                                       |          |            |                            |           |           |               |          |
|                                                |      |                                                                                                                                                                            |          |            |                            |           |           |               |          |
| PROC. REF: AMM 32-33-00PROC. REF: AMM 32-33-00 |      |                                                                                                                                                                            |          |            |                            |           |           |               |          |
|                                                |      |                                                                                                                                                                            |          |            |                            |           |           |               |          |
| A3240007                                       | S    | PERFORM **BRAKE SHUTTLE VALVES - FUNCTIONAL TEST                                                                                                                           |          |            |                            |           |           | Service       | ATA:32   |
|                                                | MOS  | 25-Nov-19                                                                                                                                                                  | 96       |            |                            |           |           | AIRWORTHINESS |          |
|                                                | HRS  | 8177.7                                                                                                                                                                     | 2400     |            |                            |           |           |               |          |
|                                                | AFL  | 6303                                                                                                                                                                       |          |            |                            |           |           |               |          |
|                                                |      |                                                                                                                                                                            |          |            |                            |           |           |               |          |
| PROC. REF: AMM 32-42-04PROC. REF: AMM 32-42-04 |      |                                                                                                                                                                            |          |            |                            |           |           |               |          |
|                                                |      |                                                                                                                                                                            |          |            |                            |           |           |               |          |
| V3240004                                       | S    | ** EMERGENCY/PARKING BRAKE SWITCH - VERIFY THAT "EMERGENCY/PARKING BRAKE" MESSAGE ILLUMINATES ON EICAS WHEN PARKING BRAKE IS SET AND THROTTLES ARE MOVED ABOVE MCR DETENT. |          |            |                            |           |           | Service       | ATA:32   |
|                                                | MOS  | 02-Aug-24                                                                                                                                                                  | 24       |            |                            |           |           | AIRWORTHINESS |          |
|                                                | HRS  | 9525.7                                                                                                                                                                     | 600      |            |                            |           |           |               |          |
|                                                | AFL  | 7276                                                                                                                                                                       |          |            |                            |           |           |               |          |
|                                                |      |                                                                                                                                                                            |          |            |                            |           |           |               |          |
| PROC. REF: AMM 32-42-01PROC. REF: AMM 32-42-01 |      |                                                                                                                                                                            |          |            |                            |           |           |               |          |
|                                                |      |                                                                                                                                                                            |          |            |                            |           |           |               |          |
| V3240008                                       | S    | ** EMERGENCY/PARKING BRAKE CONTROL SYSTEM - PERFORM FUNCTIONAL TEST                                                                                                        |          |            |                            |           |           | Service       | ATA:32   |
|                                                | MOS  | 02-Aug-24                                                                                                                                                                  | 24       |            |                            |           |           | AIRWORTHINESS |          |
|                                                | HRS  | 9525.7                                                                                                                                                                     | 600      |            |                            |           |           |               |          |
|                                                | AFL  | 7276                                                                                                                                                                       |          |            |                            |           |           |               |          |
|                                                |      |                                                                                                                                                                            |          |            |                            |           |           |               |          |
| PROC. REF: AMM 32-42-02PROC. REF: AMM 32-42-02 |      |                                                                                                                                                                            |          |            |                            |           |           |               |          |
|                                                |      |                                                                                                                                                                            |          |            |                            |           |           |               |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                            | Unit         | C / W                                                                                                                                    | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------|--------------|------------------------------------------------------------------------------------------------------------------------------------------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 32 - LANDING GEAR                              |              |                                                                                                                                          |          |          |                        |           |           |             |          |
| Y3220000                                           | <sup>S</sup> | NOSE LANDING GEAR ASSEMBLY - PERFORM VISUAL INSPECTION                                                                                   |          |          |                        |           |           | Service     | ATA:32   |
|                                                    | MOS          | 02-Aug-24                                                                                                                                | 24       |          |                        |           |           |             |          |
|                                                    | HRS          | 9525.7                                                                                                                                   | 600      |          |                        |           |           |             |          |
|                                                    | AFL          | 7276                                                                                                                                     |          |          |                        |           |           |             |          |
| PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00     |              |                                                                                                                                          |          |          |                        |           |           |             | PKG:11   |
| Y3220001                                           | <sup>S</sup> | MAIN LANDING GEAR ASSEMBLY - PERFORM VISUAL INSPECTION. INSPECTION TO INCLUDE ACTUATOR, FASTENERS, SUPPORT STRUCTURE, AND SQUAT SWITCHES |          |          |                        |           |           | Service     | ATA:32   |
|                                                    | MOS          | 02-Aug-24                                                                                                                                | 24       |          |                        |           |           |             |          |
|                                                    | HRS          | 9525.7                                                                                                                                   | 600      |          |                        |           |           |             |          |
|                                                    | AFL          | 7276                                                                                                                                     |          |          |                        |           |           |             |          |
| PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00     |              |                                                                                                                                          |          |          |                        |           |           |             | PKG:11   |
| Y3220002                                           | <sup>S</sup> | NOSE LANDING GEAR ACTUATOR PRESSURE AND RETURN LINES - PERFORM VISUAL INSPECTION. LOWER ACTUATOR DUST BOOT TO INSPECT LINES              |          |          |                        |           |           | Service     | ATA:32   |
|                                                    | MOS          | 02-Aug-24                                                                                                                                | 24       |          |                        |           |           |             |          |
|                                                    | HRS          | 9525.7                                                                                                                                   | 600      |          |                        |           |           |             |          |
|                                                    | AFL          | 7276                                                                                                                                     |          |          |                        |           |           |             |          |
| PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00     |              |                                                                                                                                          |          |          |                        |           |           |             | PKG:11   |
| Y3220003                                           | <sup>S</sup> | NOSE GEAR SHOCK STRUT - REMOVE AND REPLACE RETAINER RING LOCKSCREW                                                                       |          |          |                        |           |           | Service     | ATA:32   |
|                                                    | MOS          | 02-Aug-24                                                                                                                                | 24       |          |                        |           |           |             |          |
|                                                    | HRS          | 9525.7                                                                                                                                   | 600      |          |                        |           |           |             |          |
|                                                    | AFL          | 7276                                                                                                                                     |          |          |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |              |                                                                                                                                          |          |          |                        |           |           |             | PKG:11   |
| Y3220004                                           | <sup>S</sup> | MAIN LANDING GEAR ACTUATOR AND GEAR INBOARD DOOR ACTUATOR ATTACH POINTS - PERFORM VISUAL INSPECTION                                      |          |          |                        |           |           | Service     | ATA:32   |
|                                                    | MOS          | 02-Aug-24                                                                                                                                | 24       |          |                        |           |           |             |          |
|                                                    | HRS          | 9525.7                                                                                                                                   | 600      |          |                        |           |           |             |          |
|                                                    | AFL          | 7276                                                                                                                                     |          |          |                        |           |           |             |          |
| PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00     |              |                                                                                                                                          |          |          |                        |           |           |             | PKG:11   |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                        | Unit         | C / W                                                                                                          | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|------------------------------------------------|--------------|----------------------------------------------------------------------------------------------------------------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 32 - LANDING GEAR                          |              |                                                                                                                |          |          |                        |           |           |             |          |
| Y3220006                                       | <sup>S</sup> | LANDING GEAR ELECTRICAL WIRING - PERFORM VISUAL INSPECTION (THAT PORTION VISIBLE INSIDE WHEEL WELL)            |          |          |                        |           |           | Service     | ATA:32   |
|                                                | MOS          | 02-Aug-24                                                                                                      | 24       |          |                        |           |           |             |          |
|                                                | HRS          | 9525.7                                                                                                         | 600      |          |                        |           |           |             |          |
|                                                | AFL          | 7276                                                                                                           |          |          |                        |           |           |             |          |
| PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00 |              |                                                                                                                |          |          |                        |           |           |             | PKG:11   |
| Y3220124                                       | <sup>S</sup> | NOSE LANDING GEAR - PERFORM DETAILED VISUAL INSPECTION OF THE NOSE LANDING GEAR UPLOCK ROLLER BRACKET          |          |          |                        |           |           | Service     | ATA:32   |
|                                                | MOS          | 02-Aug-24                                                                                                      | 24       |          |                        |           |           |             |          |
|                                                | HRS          | 9525.7                                                                                                         | 600      |          |                        |           |           |             |          |
|                                                | AFL          | 7276                                                                                                           |          |          |                        |           |           |             |          |
| PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00 |              |                                                                                                                |          |          |                        |           |           |             | PKG:11   |
| Y3230002                                       | <sup>S</sup> | MAIN LANDING GEAR FREE FALL ROLLER - PERFORM VISUAL INSPECTION. PAY PARTICULAR ATTENTION TO BINDING OF ROLLERS |          |          |                        |           |           | Service     | ATA:32   |
|                                                | MOS          | 02-Aug-24                                                                                                      | 12       |          |                        |           |           |             |          |
|                                                | HRS          | 9525.7                                                                                                         | 300      |          |                        |           |           |             |          |
|                                                | AFL          | 7276                                                                                                           |          |          |                        |           |           |             |          |
| PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00 |              |                                                                                                                |          |          |                        |           |           |             | PKG:5    |
| Y3240000                                       | <sup>S</sup> | NOSE AND MAIN TIRES - PERFORM VISUAL INSPECTION                                                                |          |          |                        |           |           | Service     | ATA:32   |
|                                                | MOS          | 02-Aug-24                                                                                                      | 12       |          |                        |           |           |             |          |
|                                                | HRS          | 9525.7                                                                                                         | 300      |          |                        |           |           |             |          |
|                                                | AFL          | 7276                                                                                                           |          |          |                        |           |           |             |          |
| PROC. REF: AMM 12-10-04PROC. REF: AMM 12-10-04 |              |                                                                                                                |          |          |                        |           |           |             | PKG:5    |
| Y3240001                                       | <sup>S</sup> | BRAKE LINES - PERFORM VISUAL INSPECTION. INSPECT ALL BRAKE LINES VISIBLE IN WHEEL WELLS AND ON STRUTS          |          |          |                        |           |           | Service     | ATA:32   |
|                                                | MOS          | 02-Aug-24                                                                                                      | 24       |          |                        |           |           |             |          |
|                                                | HRS          | 9525.7                                                                                                         | 600      |          |                        |           |           |             |          |
|                                                | AFL          | 7276                                                                                                           |          |          |                        |           |           |             |          |
| PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00 |              |                                                                                                                |          |          |                        |           |           |             | PKG:11   |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|---------|------|-----|----------|----------|------------------------|-----------|-----------|-------------|----------|
|---------|------|-----|----------|----------|------------------------|-----------|-----------|-------------|----------|

ATA 32 - LANDING GEAR

|                                                |              |                                                                                                                                                                                                      |     |  |  |  |  |         |        |
|------------------------------------------------|--------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|--|--|--|--|---------|--------|
| Y3240002                                       | <sup>S</sup> | BRAKE ASSEMBLIES - PERFORM VISUAL INSPECTION WITH PARKING BRAKE SET. WORN BRAKES ARE VISUALLY INDICATED WHEN THE WEAR INDICATOR PINS BECOME EVEN WITH THE OUTER SURFACE OF THE WEAR INDICATOR SLEEVE |     |  |  |  |  | Service | ATA:32 |
|                                                | MOS          | 02-Aug-24                                                                                                                                                                                            | 12  |  |  |  |  |         |        |
|                                                | HRS          | 9525.7                                                                                                                                                                                               | 300 |  |  |  |  |         |        |
|                                                | AFL          | 7276                                                                                                                                                                                                 |     |  |  |  |  |         |        |
| PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01 |              |                                                                                                                                                                                                      |     |  |  |  |  |         | PKG:5  |

|                                                |              |                                                                                                                                                                  |     |  |  |  |  |         |        |
|------------------------------------------------|--------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|--|--|--|--|---------|--------|
| Y3260005                                       | <sup>S</sup> | NOSE LANDING GEAR SQUAT SWITCH ROTATING DISK ASSEMBLY - LUBRICATE. (EFFECTIVE ON AIRCRAFT 45-001 THRU 45-114 POST SB 45-32-8 AND AIRCRAFT 45-115 AND SUBSEQUENT) |     |  |  |  |  | Service | ATA:32 |
|                                                | MOS          | 02-Aug-24                                                                                                                                                        | 12  |  |  |  |  |         |        |
|                                                | HRS          | 9525.7                                                                                                                                                           | 300 |  |  |  |  |         |        |
|                                                | AFL          | 7276                                                                                                                                                             |     |  |  |  |  |         |        |
| PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01 |              |                                                                                                                                                                  |     |  |  |  |  |         | PKG:5  |

ATA 33 - LIGHTS

|                                                    |         |                           |     |       |  |  |  |           |        |
|----------------------------------------------------|---------|---------------------------|-----|-------|--|--|--|-----------|--------|
| 330000                                             |         | MODIFIED PULSE CONTROLLER |     |       |  |  |  | Component | ATA:33 |
| PN:PN                                              | MOS/MSC | 09-Mar-01                 | O/C | TSN 0 |  |  |  |           |        |
| SN:UNKNOWN                                         | HRS     | 0                         |     | TSN 0 |  |  |  |           |        |
|                                                    | AFL     | 0                         |     | TSN 0 |  |  |  |           |        |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |         |                           |     |       |  |  |  |           |        |

|                                                |         |                             |     |       |  |  |  |           |        |
|------------------------------------------------|---------|-----------------------------|-----|-------|--|--|--|-----------|--------|
| 331001                                         |         | NO. 1 LIGHTING CONTROL UNIT |     |       |  |  |  | Component | ATA:33 |
| PN:PN                                          | MOS/MSC | 09-Mar-01                   | O/C | TSN 0 |  |  |  |           |        |
| SN:UNKNOWN                                     | HRS     | 0                           |     | TSN 0 |  |  |  |           |        |
|                                                | AFL     | 0                           |     | TSN 0 |  |  |  |           |        |
| PROC. REF: AMM 33-10-06PROC. REF: AMM 33-10-06 |         |                             |     |       |  |  |  |           |        |

|                                                |         |                             |     |       |  |  |  |           |        |
|------------------------------------------------|---------|-----------------------------|-----|-------|--|--|--|-----------|--------|
| 331002                                         |         | NO. 2 LIGHTING CONTROL UNIT |     |       |  |  |  | Component | ATA:33 |
| PN:PN                                          | MOS/MSC | 09-Mar-01                   | O/C | TSN 0 |  |  |  |           |        |
| SN:UNKNOWN                                     | HRS     | 0                           |     | TSN 0 |  |  |  |           |        |
|                                                | AFL     | 0                           |     | TSN 0 |  |  |  |           |        |
| PROC. REF: AMM 33-10-06PROC. REF: AMM 33-10-06 |         |                             |     |       |  |  |  |           |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR    Serial: 45-145    RegNo: N942FK    HRS: 9669.1    AFL: 7372    As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                            | Unit                                 | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty            |
|----------------------------------------------------|--------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|---------------------|
| ATA 33 - LIGHTS                                    |                                      |           |          |          |                        |           |           |             |                     |
| 331010                                             | PILOT FORWARD SWITCH PANEL OVERLAY   |           |          |          |                        |           |           |             | Component    ATA:33 |
| PN:PN                                              | MOS/MSC                              | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                         | HRS                                  | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                    | AFL                                  | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: AMM 33-10-05PROC. REF: AMM 33-10-05     |                                      |           |          |          |                        |           |           |             |                     |
| 331011                                             | PILOT SWITCH PANEL ASSY              |           |          |          |                        |           |           |             | Component    ATA:33 |
| PN:PN                                              | MOS/MSC                              | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                         | HRS                                  | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                    | AFL                                  | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                      |           |          |          |                        |           |           |             |                     |
| 331012                                             | COPILOT FORWARD SWITCH PANEL OVERLAY |           |          |          |                        |           |           |             | Component    ATA:33 |
| PN:PN                                              | MOS/MSC                              | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                         | HRS                                  | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                    | AFL                                  | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: AMM 33-10-05PROC. REF: AMM 33-10-05     |                                      |           |          |          |                        |           |           |             |                     |
| 331013                                             | COPILOT FORWARD SWITCH PANEL ASSY    |           |          |          |                        |           |           |             | Component    ATA:33 |
| PN:PN                                              | MOS/MSC                              | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                         | HRS                                  | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                    | AFL                                  | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                      |           |          |          |                        |           |           |             |                     |
| 331015                                             | CENTER SWITCH (P5) PANEL ASSEMBLY    |           |          |          |                        |           |           |             | Component    ATA:33 |
| PN:PN                                              | MOS/MSC                              | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                         | HRS                                  | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                    | AFL                                  | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                      |           |          |          |                        |           |           |             |                     |
| 331016                                             | CENTER SWITCH PANEL (P5) OVERLAY     |           |          |          |                        |           |           |             | Component    ATA:33 |
| PN:PN                                              | MOS/MSC                              | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                         | HRS                                  | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                    | AFL                                  | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: AMM 33-10-05PROC. REF: AMM 33-10-05     |                                      |           |          |          |                        |           |           |             |                     |

?-Insufficient Information    S-Suppressed Requirement    \*-Estimated Due(New Requirement)    (EFF)-Effective C/W    (M)-Manual Due    U-User Task    Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                            | Unit                                      | C / W     | Interval | TSX / Adj. | Next Due (ENG / APU) A / C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------|-------------------------------------------|-----------|----------|------------|----------------------------|-----------|-----------|-------------|------------------|
| ATA 33 - LIGHTS                                    |                                           |           |          |            |                            |           |           |             |                  |
| 331017                                             | THROTTLE QUADRANT OVERLAY PANEL           |           |          |            |                            |           |           |             | Component ATA:33 |
| PN:PN                                              | MOS/MSC                                   | 09-Mar-01 | O/C      | TSN 0      |                            |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                       | 0         |          | TSN 0      |                            |           |           |             |                  |
|                                                    | AFL                                       | 0         |          | TSN 0      |                            |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                           |           |          |            |                            |           |           |             |                  |
| 331018                                             | PILOT AFT CIRCUIT BREAKER PANEL OVERLAY   |           |          |            |                            |           |           |             | Component ATA:33 |
| PN:PN                                              | MOS/MSC                                   | 09-Mar-01 | O/C      | TSN 0      |                            |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                       | 0         |          | TSN 0      |                            |           |           |             |                  |
|                                                    | AFL                                       | 0         |          | TSN 0      |                            |           |           |             |                  |
| PROC. REF: AMM 33-10-05PROC. REF: AMM 33-10-05     |                                           |           |          |            |                            |           |           |             |                  |
| 331019                                             | COPILOT AFT CIRCUIT BREAKER PANEL OVERLAY |           |          |            |                            |           |           |             | Component ATA:33 |
| PN:PN                                              | MOS/MSC                                   | 09-Mar-01 | O/C      | TSN 0      |                            |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                       | 0         |          | TSN 0      |                            |           |           |             |                  |
|                                                    | AFL                                       | 0         |          | TSN 0      |                            |           |           |             |                  |
| PROC. REF: AMM 33-10-05PROC. REF: AMM 33-10-05     |                                           |           |          |            |                            |           |           |             |                  |
| 331020                                             | DIMMER CONTROL BOX                        |           |          |            |                            |           |           |             | Component ATA:33 |
| PN:PN                                              | MOS/MSC                                   | 09-Mar-01 | O/C      | TSN 0      |                            |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                       | 0         |          | TSN 0      |                            |           |           |             |                  |
|                                                    | AFL                                       | 0         |          | TSN 0      |                            |           |           |             |                  |
| PROC. REF: AMM 33-10-10PROC. REF: AMM 33-10-10     |                                           |           |          |            |                            |           |           |             |                  |
| 331023                                             | GLARESHIELD FLOOR FLOODLIGHTS INVERTER    |           |          |            |                            |           |           |             | Component ATA:33 |
| PN:PN                                              | MOS/MSC                                   | 09-Mar-01 | O/C      | TSN 0      |                            |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                       | 0         |          | TSN 0      |                            |           |           |             |                  |
|                                                    | AFL                                       | 0         |          | TSN 0      |                            |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                           |           |          |            |                            |           |           |             |                  |
| 331025                                             | COCKPIT MISC RELAY BOX                    |           |          |            |                            |           |           |             | Component ATA:33 |
| PN:PN                                              | MOS/MSC                                   | 09-Mar-01 | O/C      | TSN 0      |                            |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                       | 0         |          | TSN 0      |                            |           |           |             |                  |
|                                                    | AFL                                       | 0         |          | TSN 0      |                            |           |           |             |                  |
| PROC. REF: AMM 33-10-07PROC. REF: AMM 33-10-07     |                                           |           |          |            |                            |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                            | Unit    | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------|---------|-----------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 33 - LIGHTS                                    |         |           |          |          |                        |           |           |             |          |
| 331030CENTER SWITCH PANEL DIODE (P12) BOX          |         |           |          |          |                        |           |           | Component   | ATA:33   |
| PN:PN                                              | MOS/MSC | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL     | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 33-10-08PROC. REF: AMM 33-10-08     |         |           |          |          |                        |           |           |             |          |
|                                                    |         |           |          |          |                        |           |           |             |          |
| 331033GLARESHIELD FLOODLIGHT POWER SUPPLY          |         |           |          |          |                        |           |           | Component   | ATA:33   |
| PN:PN                                              | MOS/MSC | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL     | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |         |           |          |          |                        |           |           |             |          |
|                                                    |         |           |          |          |                        |           |           |             |          |
| 331040PILOT REVERSION PANEL (DS55) OVERLAY         |         |           |          |          |                        |           |           | Component   | ATA:33   |
| PN:PN                                              | MOS/MSC | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL     | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |         |           |          |          |                        |           |           |             |          |
|                                                    |         |           |          |          |                        |           |           |             |          |
| 331101P35 FUSE PANEL ASSY                          |         |           |          |          |                        |           |           | Component   | ATA:33   |
| PN:4533108552-007                                  | MOS/MSC | 17-Feb-05 | O/C      |          |                        |           |           |             |          |
| SN:MRP644283-001                                   | HRS     | 3300.2    |          |          |                        |           |           |             |          |
|                                                    | AFL     | 2515      |          |          |                        |           |           |             |          |
| PROC. REF: AMM 33-10-09PROC. REF: AMM 33-10-09     |         |           |          |          |                        |           |           |             |          |
|                                                    |         |           |          |          |                        |           |           |             |          |
| 331401-1NO. 1 LEFT INVERTER (PS5009) SUPPLY PWR    |         |           |          |          |                        |           |           | Component   | ATA:33   |
| PN:AL-2000                                         | MOS/MSC | 11-Apr-05 | O/C      |          |                        |           |           |             |          |
| SN:46634                                           | HRS     | 3496.3    |          |          |                        |           |           |             |          |
|                                                    | AFL     | 2649      |          |          |                        |           |           |             |          |
| PROC. REF: AMM 33-20-10PROC. REF: AMM 33-20-10     |         |           |          |          |                        |           |           |             |          |
|                                                    |         |           |          |          |                        |           |           |             |          |
| 331401-10INVERTER SUPPLY PWR                       |         |           |          |          |                        |           |           | Component   | ATA:33   |
| PN:PN                                              | MOS/MSC | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL     | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 33-20-10PROC. REF: AMM 33-20-10     |         |           |          |          |                        |           |           |             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR    Serial: 45-145    RegNo: N942FK    HRS: 9669.1    AFL: 7372    As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                                                | Unit    | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|------------------------------------------------------------------------|---------|-----------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 33 - LIGHTS                                                        |         |           |          |          |                        |           |           |             |          |
| 331401-11                      INVERTER SUPPLY PWR                     |         |           |          |          |                        |           |           | Component   | ATA:33   |
| PN:PN                                                                  | MOS/MSC | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                                             | HRS     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                                        | AFL     | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 33-20-10PROC. REF: AMM 33-20-10                         |         |           |          |          |                        |           |           |             |          |
|                                                                        |         |           |          |          |                        |           |           |             |          |
| 331401-2                      NO. 1 RIGHT INVERTER (PS5003) SUPPLY PWR |         |           |          |          |                        |           |           | Component   | ATA:33   |
| PN:AL-2000                                                             | MOS/MSC | 11-Apr-05 | O/C      |          |                        |           |           |             |          |
| SN:46632                                                               | HRS     | 3496.3    |          |          |                        |           |           |             |          |
|                                                                        | AFL     | 2649      |          |          |                        |           |           |             |          |
| PROC. REF: AMM 33-20-10PROC. REF: AMM 33-20-10                         |         |           |          |          |                        |           |           |             |          |
|                                                                        |         |           |          |          |                        |           |           |             |          |
| 331401-3                      NO. 2 LEFT INVERTER (PS5008) SUPPLY PWR  |         |           |          |          |                        |           |           | Component   | ATA:33   |
| PN:PN                                                                  | MOS/MSC | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                                             | HRS     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                                        | AFL     | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 33-20-10PROC. REF: AMM 33-20-10                         |         |           |          |          |                        |           |           |             |          |
|                                                                        |         |           |          |          |                        |           |           |             |          |
| 331401-4                      NO. 2 RIGHT INVERTER (PS5004) SUPPLY PWR |         |           |          |          |                        |           |           | Component   | ATA:33   |
| PN:PN                                                                  | MOS/MSC | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                                             | HRS     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                                        | AFL     | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 33-20-10PROC. REF: AMM 33-20-10                         |         |           |          |          |                        |           |           |             |          |
|                                                                        |         |           |          |          |                        |           |           |             |          |
| 331401-5                      NO. 3 LEFT INVERTER (PS5007) SUPPLY PWR  |         |           |          |          |                        |           |           | Component   | ATA:33   |
| PN:PN                                                                  | MOS/MSC | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                                             | HRS     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                                        | AFL     | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 33-20-10PROC. REF: AMM 33-20-10                         |         |           |          |          |                        |           |           |             |          |
|                                                                        |         |           |          |          |                        |           |           |             |          |
| 331401-6                      NO. 3 RIGHT INVERTER (PS5005) SUPPLY PWR |         |           |          |          |                        |           |           | Component   | ATA:33   |
| PN:PN                                                                  | MOS/MSC | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                                             | HRS     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                                        | AFL     | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 33-20-10PROC. REF: AMM 33-20-10                         |         |           |          |          |                        |           |           |             |          |
|                                                                        |         |           |          |          |                        |           |           |             |          |

?-Insufficient Information    S-Suppressed Requirement    \*-Estimated Due(New Requirement)    (EFF)-Effective C/W    (M)-Manual Due    U-User Task    Ex-Excluded Task

# Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9669.1
 AFL: 7372
 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                               | Unit    | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|-------------------------------------------------------|---------|-----------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 33 - LIGHTS                                       |         |           |          |          |                        |           |           |             |          |
| 331401-7 NO. 4 LEFT INVERTER (PS5006) SUPPLY PWR      |         |           |          |          |                        |           |           | Component   | ATA:33   |
| PN:PN                                                 | MOS/MSC | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                            | HRS     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                       | AFL     | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 33-20-10PROC. REF: AMM 33-20-10        |         |           |          |          |                        |           |           |             |          |
| 331401-8 NO. 4 RIGHT INVERTER (PS5010) LAV SUPPLY PWR |         |           |          |          |                        |           |           | Component   | ATA:33   |
| PN:PN                                                 | MOS/MSC | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                            | HRS     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                       | AFL     | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 33-20-10PROC. REF: AMM 33-20-10        |         |           |          |          |                        |           |           |             |          |
| 331401-9 NO. 5 LEFT INVERTER (PS5011) LAV SUPPLY PWR  |         |           |          |          |                        |           |           | Component   | ATA:33   |
| PN:PN                                                 | MOS/MSC | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                            | HRS     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                       | AFL     | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 33-20-10PROC. REF: AMM 33-20-10        |         |           |          |          |                        |           |           |             |          |
| 332001 RH FWD LIGHTING CONTROL (A5038) UNIT           |         |           |          |          |                        |           |           | Component   | ATA:33   |
| PN:PN                                                 | MOS/MSC | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                            | HRS     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                       | AFL     | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 33-20-05PROC. REF: AMM 33-20-05        |         |           |          |          |                        |           |           |             |          |
| 332002 RH MID FWD LIGHTING CONTROL (A5039) UNIT       |         |           |          |          |                        |           |           | Component   | ATA:33   |
| PN:PN                                                 | MOS/MSC | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                            | HRS     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                       | AFL     | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 33-20-05PROC. REF: AMM 33-20-05        |         |           |          |          |                        |           |           |             |          |
| 332003 RH MID AFT LIGHTING CONTROL (A5040) UNIT       |         |           |          |          |                        |           |           | Component   | ATA:33   |
| PN:PN                                                 | MOS/MSC | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                            | HRS     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                       | AFL     | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 33-20-05PROC. REF: AMM 33-20-05        |         |           |          |          |                        |           |           |             |          |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C/W   (M)-Manual Due   U-User Task   Ex-Excluded Task

# Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9669.1
 AFL: 7372
 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                        | Unit                                                           | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|------------------------------------------------|----------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 33 - LIGHTS                                |                                                                |           |          |          |                        |           |           |             |          |
| 332004                                         | RH AFT LIGHTING CONTROL (A5041) UNIT                           |           |          |          |                        |           |           | Component   | ATA:33   |
| PN:PN                                          | MOS/MSC                                                        | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS                                                            | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL                                                            | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 33-20-05PROC. REF: AMM 33-20-05 |                                                                |           |          |          |                        |           |           |             |          |
| 332005                                         | L/H FWD LIGHTING CONTROL (A5045) UNIT                          |           |          |          |                        |           |           | Component   | ATA:33   |
| PN:PN                                          | MOS/MSC                                                        | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS                                                            | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL                                                            | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 33-20-05PROC. REF: AMM 33-20-05 |                                                                |           |          |          |                        |           |           |             |          |
| 332006                                         | LH MID FWD LIGHTING CONTROL (A5044) UNIT                       |           |          |          |                        |           |           | Component   | ATA:33   |
| PN:PN                                          | MOS/MSC                                                        | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS                                                            | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL                                                            | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 33-20-05PROC. REF: AMM 33-20-05 |                                                                |           |          |          |                        |           |           |             |          |
| 332007                                         | LH MID AFT LIGHTING CONTROL (A5043) UNIT                       |           |          |          |                        |           |           | Component   | ATA:33   |
| PN:PN                                          | MOS/MSC                                                        | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS                                                            | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL                                                            | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 33-20-05PROC. REF: AMM 33-20-05 |                                                                |           |          |          |                        |           |           |             |          |
| 332008                                         | LH AFT LIGHTING CONTROL (A5042) UNIT                           |           |          |          |                        |           |           | Component   | ATA:33   |
| PN:PN                                          | MOS/MSC                                                        | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS                                                            | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL                                                            | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 33-20-05PROC. REF: AMM 33-20-05 |                                                                |           |          |          |                        |           |           |             |          |
| 332030                                         | LAVATORY NO SMOKING / RETURN TO SEAT SIGN (DS138) CONTROL UNIT |           |          |          |                        |           |           | Component   | ATA:33   |
| PN:PN                                          | MOS/MSC                                                        | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS                                                            | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL                                                            | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 33-20-11PROC. REF: AMM 33-20-11 |                                                                |           |          |          |                        |           |           |             |          |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C/W   (M)-Manual Due   U-User Task   Ex-Excluded Task



Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                        | Unit                            | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|------------------------------------------------|---------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 33 - LIGHTS                                |                                 |           |          |          |                        |           |           |             |                  |
| 332068                                         | COPILOT LIGHTING CONTROL MODULE |           |          |          |                        |           |           |             | Component ATA:33 |
| PN:PN                                          | MOS/MSC                         | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                             | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                             | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 33-20-02PROC. REF: AMM 33-20-02 |                                 |           |          |          |                        |           |           |             |                  |
| 332404                                         | ENTRYWAY CONTROL LIGHT PANEL    |           |          |          |                        |           |           |             | Component ATA:33 |
| PN:PN                                          | MOS/MSC                         | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                             | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                             | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 33-20-01PROC. REF: AMM 33-20-01 |                                 |           |          |          |                        |           |           |             |                  |
| 334011                                         | LANDING/TAXI, LEFT LIGHT        |           |          |          |                        |           |           |             | Component ATA:33 |
| PN:GE4587                                      | MOS/MSC                         | 17-Feb-22 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                             | 8864.4    |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                             | 6822      |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 33-40-04PROC. REF: AMM 33-40-04 |                                 |           |          |          |                        |           |           |             |                  |
| 334012                                         | LANDING/TAXI, RIGHT LIGHT       |           |          |          |                        |           |           |             | Component ATA:33 |
| PN:PN                                          | MOS/MSC                         | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                             | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                             | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 33-40-04PROC. REF: AMM 33-40-04 |                                 |           |          |          |                        |           |           |             |                  |
| 334021                                         | LEFT NAVIGATION (DS37) LIGHT    |           |          |          |                        |           |           |             | Component ATA:33 |
| PN:PN                                          | MOS/MSC                         | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                             | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                             | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 33-40-02PROC. REF: AMM 33-40-02 |                                 |           |          |          |                        |           |           |             |                  |
| 334022                                         | RIGHT NAVIGATION (DS38) LIGHT   |           |          |          |                        |           |           |             | Component ATA:33 |
| PN:PN                                          | MOS/MSC                         | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                             | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                             | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 33-40-02PROC. REF: AMM 33-40-02 |                                 |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9669.1
 AFL: 7372
 As Of: 01-Apr-2025
 02-Apr-2025 02:58 PM

| PN & SN                                            | Unit                                     | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------|------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 33 - LIGHTS                                    |                                          |           |          |          |                        |           |           |             |                  |
| 334023                                             | TAIL NAVIGATION (DS39) LIGHT             |           |          |          |                        |           |           |             | Component ATA:33 |
| PN:PN                                              | MOS/MSC                                  | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                      | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                      | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 33-40-02PROC. REF: AMM 33-40-02     |                                          |           |          |          |                        |           |           |             |                  |
| 334041                                             | COPILOT REVERSION PANEL (DS56) OVERLAY   |           |          |          |                        |           |           |             | Component ATA:33 |
| PN:PN                                              | MOS/MSC                                  | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                      | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                      | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                          |           |          |          |                        |           |           |             |                  |
| 334175                                             | RELAY OPTIONS PANEL ASSY                 |           |          |          |                        |           |           |             | Component ATA:33 |
| PN:PN                                              | MOS/MSC                                  | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                      | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                      | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                          |           |          |          |                        |           |           |             |                  |
| 334332                                             | UPPER ANTI-COLLISION LIGHT               |           |          |          |                        |           |           |             | Component ATA:33 |
| PN:PN                                              | MOS/MSC                                  | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                      | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                      | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 33-40-01PROC. REF: AMM 33-40-01     |                                          |           |          |          |                        |           |           |             |                  |
| 334333                                             | LOWER ANTI-COLLISION LIGHT               |           |          |          |                        |           |           |             | Component ATA:33 |
| PN:GE-16386-12-1                                   | MOS/MSC                                  | 22-Dec-08 | O/C      |          |                        |           |           |             |                  |
| SN:AA2591                                          | HRS                                      | 6088.7    |          |          |                        |           |           |             |                  |
|                                                    | AFL                                      | 4660      |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 33-40-01PROC. REF: AMM 33-40-01     |                                          |           |          |          |                        |           |           |             |                  |
| 335005                                             | FWD ELS ACTIVATION ASSEMBLY (A81) MODULE |           |          |          |                        |           |           |             | Component ATA:33 |
| PN:PN                                              | MOS/MSC                                  | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                      | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                      | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 33-50-01PROC. REF: AMM 33-50-01     |                                          |           |          |          |                        |           |           |             |                  |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C/W   (M)-Manual Due   U-User Task   Ex-Excluded Task

# Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 9669.1
AFL: 7372
As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                            | Unit                                     | C / W     | Interval | TSX / Adj. | Next Due (ENG / APU) A / C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------|------------------------------------------|-----------|----------|------------|----------------------------|-----------|-----------|-------------|------------------|
| ATA 33 - LIGHTS                                    |                                          |           |          |            |                            |           |           |             |                  |
| 335006                                             | AFT ELS ACTIVATION ASSEMBLY (A82) MODULE |           |          |            |                            |           |           |             | Component ATA:33 |
| PN:PN                                              | MOS/MSC                                  | 09-Mar-01 | O/C      | TSN 0      |                            |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                      | 0         |          | TSN 0      |                            |           |           |             |                  |
|                                                    | AFL                                      | 0         |          | TSN 0      |                            |           |           |             |                  |
| PROC. REF: AMM 33-50-01PROC. REF: AMM 33-50-01     |                                          |           |          |            |                            |           |           |             |                  |
| 335505 <sup>U</sup>                                | PILOT FLASHLIGHT                         |           |          |            |                            |           |           |             | Component ATA:33 |
| PN:PN                                              | MOS/MSC                                  | 09-Mar-01 | O/C      | TSN 0      |                            |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                      | 0         |          | TSN 0      |                            |           |           |             |                  |
|                                                    | AFL                                      | 0         |          | TSN 0      |                            |           |           |             |                  |
| 335506 <sup>U</sup>                                | COPILOT FLASHLIGHT                       |           |          |            |                            |           |           |             | Component ATA:33 |
| PN:PN                                              | MOS/MSC                                  | 09-Mar-01 | O/C      | TSN 0      |                            |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                      | 0         |          | TSN 0      |                            |           |           |             |                  |
|                                                    | AFL                                      | 0         |          | TSN 0      |                            |           |           |             |                  |
| 336001                                             | PILOT CHART HOLDER                       |           |          |            |                            |           |           |             | Component ATA:33 |
| PN:PN                                              | MOS/MSC                                  | 09-Mar-01 | O/C      | TSN 0      |                            |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                      | 0         |          | TSN 0      |                            |           |           |             |                  |
|                                                    | AFL                                      | 0         |          | TSN 0      |                            |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                          |           |          |            |                            |           |           |             |                  |
| 336002                                             | COPILOT CHART HOLDER                     |           |          |            |                            |           |           |             | Component ATA:33 |
| PN:10-62-01                                        | MOS/MSC                                  | 17-Feb-05 | O/C      |            |                            |           |           |             |                  |
| SN:3357                                            | HRS                                      | 3300.2    |          |            |                            |           |           |             |                  |
|                                                    | AFL                                      | 2515      |          |            |                            |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                          |           |          |            |                            |           |           |             |                  |
| 336003                                             | PILOT MAP LIGHT                          |           |          |            |                            |           |           |             | Component ATA:33 |
| PN:0204327-001                                     | MOS/MSC                                  | 12-Dec-11 | O/C      | TSN 0      |                            |           |           |             |                  |
| SN:542319                                          | HRS                                      | 6763.5    |          | TSN 0      |                            |           |           |             |                  |
|                                                    | AFL                                      | 5158      |          | TSN 0      |                            |           |           |             |                  |
| PROC. REF: AMM 33-10-01PROC. REF: AMM 33-10-01     |                                          |           |          |            |                            |           |           |             |                  |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C / W   (M)-Manual Due   U-User Task   Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                                                            | Unit                                                                                                                                                                                                                                              | C / W     | Interval | TSX / Adj. | Next Due (ENG / APU) A / C | Max Limit | Remaining | Disposition | Warranty         |
|------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|----------|------------|----------------------------|-----------|-----------|-------------|------------------|
| ATA 33 - LIGHTS                                                                    |                                                                                                                                                                                                                                                   |           |          |            |                            |           |           |             |                  |
| 336004                                                                             | COPILOT MAP LIGHT                                                                                                                                                                                                                                 |           |          |            |                            |           |           |             | Component ATA:33 |
| PN:PN                                                                              | MOS/MSC                                                                                                                                                                                                                                           | 09-Mar-01 | O/C      | TSN 0      |                            |           |           |             |                  |
| SN:UNKNOWN                                                                         | HRS                                                                                                                                                                                                                                               | 0         |          | TSN 0      |                            |           |           |             |                  |
|                                                                                    | AFL                                                                                                                                                                                                                                               | 0         |          | TSN 0      |                            |           |           |             |                  |
| PROC. REF: AMM 33-10-01PROC. REF: AMM 33-10-01                                     |                                                                                                                                                                                                                                                   |           |          |            |                            |           |           |             |                  |
| Y3310000 S                                                                         | FLIGHT COMPARTMENT LIGHTING - PERFORM OPERATION OF THE FOLLOWING: A. MAP LIGHTS. B. INSTRUMENT PANEL FLUORESCENT LIGHTS. C. INSTRUMENT/INDICATOR LIGHTS. D. LIGHT DIMMING SWITCHES. E. CREW WARNING PANEL. F. PANEL OVERLAYS.                     |           |          |            |                            |           |           |             | Service ATA:33   |
|                                                                                    | MOS                                                                                                                                                                                                                                               | 02-Aug-24 | 12       |            |                            |           |           |             |                  |
|                                                                                    | HRS                                                                                                                                                                                                                                               | 9525.7    | 300      |            |                            |           |           |             |                  |
|                                                                                    | AFL                                                                                                                                                                                                                                               | 7276      |          |            |                            |           |           |             |                  |
| PROC. REF: AMM 33-10-00PROC. REF: AMM 33-10-00                                     |                                                                                                                                                                                                                                                   |           |          |            |                            |           |           |             |                  |
| Y3340000 S                                                                         | EXTERIOR LIGHTING SYSTEMS - PERFORM OPERATION OF THE FOLLOWING: A. TAXI LIGHTS. B. ANTI-COLLISION BEACONS. C. NAVIGATION LIGHTS. D. STROBE LIGHTS. E. LANDING/RECOGNITION LIGHTS. F. WING ICE INSPECTION LIGHTS. G. EMERGENCY DOOR EGRESS LIGHTS. |           |          |            |                            |           |           |             | Service ATA:33   |
|                                                                                    | MOS                                                                                                                                                                                                                                               | 02-Aug-24 | 12       |            |                            |           |           |             |                  |
|                                                                                    | HRS                                                                                                                                                                                                                                               | 9525.7    | 300      |            |                            |           |           |             |                  |
|                                                                                    | AFL                                                                                                                                                                                                                                               | 7276      |          |            |                            |           |           |             |                  |
| PROC. REF: AMM 33-40-00, AMM 33-41-00PROC. REF: AMM 33-40-00, AMM 33-41-00         |                                                                                                                                                                                                                                                   |           |          |            |                            |           |           |             |                  |
| Y3350003 S                                                                         | EMERGENCY LIGHTING SYSTEM - PERFORM OPERATIONAL CHECK                                                                                                                                                                                             |           |          |            |                            |           |           |             | Service ATA:33   |
|                                                                                    | MOS                                                                                                                                                                                                                                               | 22-Jun-23 | 48       |            |                            |           |           |             |                  |
|                                                                                    | HRS                                                                                                                                                                                                                                               | 9258.5    | 1200     |            |                            |           |           |             |                  |
|                                                                                    | AFL                                                                                                                                                                                                                                               | 7100      |          |            |                            |           |           |             |                  |
| PROC. REF: AMM 33-50-00PROC. REF: AMM 33-50-00                                     |                                                                                                                                                                                                                                                   |           |          |            |                            |           |           |             |                  |
| ATA 34 - NAVIGATION                                                                |                                                                                                                                                                                                                                                   |           |          |            |                            |           |           |             |                  |
| 34-00-FAR-91.171                                                                   | CHECK VOR EQUIPMENT FOR IFR OPERATIONS FAR 91.171                                                                                                                                                                                                 |           |          |            |                            |           |           |             | Service ATA:34   |
|                                                                                    | MOS/MSC                                                                                                                                                                                                                                           | 09-Mar-01 | O/C      |            |                            |           |           |             |                  |
|                                                                                    | HRS                                                                                                                                                                                                                                               | 0         |          |            |                            |           |           |             |                  |
|                                                                                    | AFL                                                                                                                                                                                                                                               | 0         |          |            |                            |           |           |             |                  |
| PROC. REF: GENERIC NO REF, FAR FAR 91.171PROC. REF: GENERIC NO REF, FAR FAR 91.171 |                                                                                                                                                                                                                                                   |           |          |            |                            |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                                                                                                            | Unit    | C/W                                  | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty |
|------------------------------------------------------------------------------------------------------------------------------------|---------|--------------------------------------|----------|----------|------------------------|-----------|-----------|---------------|----------|
| ATA 34 - NAVIGATION                                                                                                                |         |                                      |          |          |                        |           |           |               |          |
| 340000 <sup>U</sup>                                                                                                                |         | INSPECTION ANNUAL AVIONICS           |          |          |                        |           |           | Service       | ATA:34   |
|                                                                                                                                    | MOS/MSC | 09-Mar-01                            | A/R      |          |                        |           |           | CUSTOMER CODE |          |
|                                                                                                                                    | HRS     | 0                                    |          |          |                        |           |           |               |          |
|                                                                                                                                    | AFL     | 0                                    |          |          |                        |           |           |               |          |
|                                                                                                                                    |         |                                      |          |          |                        |           |           |               |          |
| 341001                                                                                                                             |         | NO. 1 AIR DATA COMPUTER              |          |          |                        |           |           | Component     | ATA:34   |
| PN:7014700-606                                                                                                                     | MOS/MSC | 30-Apr-19                            | O/C      |          |                        |           |           |               |          |
| SN:99072942                                                                                                                        | HRS     | 8080.6                               |          |          |                        |           |           |               |          |
|                                                                                                                                    | AFL     | 6214                                 |          |          |                        |           |           |               |          |
| PROC. REF: AMM 34-17-01PROC. REF: AMM 34-17-01                                                                                     |         |                                      |          |          |                        |           |           |               |          |
|                                                                                                                                    |         |                                      |          |          |                        |           |           |               |          |
| 341001A                                                                                                                            |         | TEST/INSPECT NO. 1 AIR DATA COMPUTER |          |          |                        |           |           | Service       | ATA:34   |
| PN:7014700-606                                                                                                                     | MOS     | 10-Aug-24                            | 24       |          | 10-Aug-26              |           | 495 d     |               |          |
| SN:99072942                                                                                                                        | HRS     |                                      |          |          |                        |           |           |               |          |
|                                                                                                                                    | AFL     |                                      |          |          |                        |           |           |               |          |
| Calibration Date: : 10-Aug-24                                                                                                      |         |                                      |          |          |                        |           |           |               |          |
| PROC. REF: FAR FAR 91.411, AMM 34-17-00, CFR 14 CFR PART 43 APP EPROC. REF: FAR FAR 91.411, AMM 34-17-00, CFR 14 CFR PART 43 APP E |         |                                      |          |          |                        |           |           |               |          |
|                                                                                                                                    |         |                                      |          |          |                        |           |           |               |          |
| 341002                                                                                                                             |         | NO. 2 AIR DATA COMPUTER              |          |          |                        |           |           | Component     | ATA:34   |
| PN:7014700-606                                                                                                                     | MOS/MSC | 09-Mar-01                            | O/C      | TSN 0    |                        |           |           |               |          |
| SN:01014560                                                                                                                        | HRS     | 0                                    |          | TSN 0    |                        |           |           |               |          |
|                                                                                                                                    | AFL     | 0                                    |          | TSN 0    |                        |           |           |               |          |
| PROC. REF: AMM 34-17-01PROC. REF: AMM 34-17-01                                                                                     |         |                                      |          |          |                        |           |           |               |          |
|                                                                                                                                    |         |                                      |          |          |                        |           |           |               |          |
| 341002A                                                                                                                            |         | TEST/INSPECT NO. 2 AIR DATA COMPUTER |          |          |                        |           |           | Service       | ATA:34   |
| PN:7014700-606                                                                                                                     | MOS     | 10-Aug-24                            | 24       |          | 10-Aug-26              |           | 495 d     |               |          |
| SN:01014560                                                                                                                        | HRS     |                                      |          |          |                        |           |           |               |          |
|                                                                                                                                    | AFL     |                                      |          |          |                        |           |           |               |          |
| Calibration Date: : 10-Aug-24                                                                                                      |         |                                      |          |          |                        |           |           |               |          |
| PROC. REF: FAR FAR 91.411, AMM 34-17-00, CFR 14 CFR PART 43 APP EPROC. REF: FAR FAR 91.411, AMM 34-17-00, CFR 14 CFR PART 43 APP E |         |                                      |          |          |                        |           |           |               |          |
|                                                                                                                                    |         |                                      |          |          |                        |           |           |               |          |
| 341013                                                                                                                             |         | STANDBY AIRSPEED INDICATOR           |          |          |                        |           |           | Component     | ATA:34   |
| PN:6634208002-003                                                                                                                  | MOS/MSC | 17-Dec-05                            | O/C      |          |                        |           |           |               |          |
| SN:274205                                                                                                                          | HRS     | 4110.78                              |          |          |                        |           |           |               |          |
|                                                                                                                                    | AFL     | 3119                                 |          |          |                        |           |           |               |          |
| PROC. REF: AMM 34-18-01PROC. REF: AMM 34-18-01                                                                                     |         |                                      |          |          |                        |           |           |               |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                                                                                                                | Unit                                                                              | C/W       | Interval | TSX/Adj.   | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------|-----------|----------|------------|------------------------|-----------|-----------|-------------|------------------|
| ATA 34 - NAVIGATION                                                                                                                    |                                                                                   |           |          |            |                        |           |           |             |                  |
| 341025                                                                                                                                 | STANDBY ALTIMETER                                                                 |           |          |            |                        |           |           |             | Component ATA:34 |
| PN:7634208001-003                                                                                                                      | MOS/MSC                                                                           | 10-Aug-24 | O/C      |            |                        |           |           |             |                  |
| SN:1722323                                                                                                                             | HRS                                                                               |           |          |            |                        |           |           |             |                  |
|                                                                                                                                        | AFL                                                                               |           |          |            |                        |           |           |             |                  |
| PROC. REF: AMM 34-15-01PROC. REF: AMM 34-15-01                                                                                         |                                                                                   |           |          |            |                        |           |           |             |                  |
| 341025A                                                                                                                                | TEST/INSPECT STANDBY ALTIMETER                                                    |           |          |            |                        |           |           |             | Service ATA:34   |
| PN:7634208001-003                                                                                                                      | MOS                                                                               | 10-Aug-24 | 24       |            | 10-Aug-26              |           | 495 d     |             |                  |
| SN:1722323                                                                                                                             | HRS                                                                               |           |          |            |                        |           |           |             |                  |
|                                                                                                                                        | AFL                                                                               |           |          |            |                        |           |           |             |                  |
| Calibration Date: : 10-Aug-24                                                                                                          |                                                                                   |           |          |            |                        |           |           |             |                  |
| PROC. REF: FAR FAR 91.411, AMM 34-15-01, CFR 14 CFR PART 43 APP EPROC. REF: FAR FAR 91.411, AMM 34-15-01, CFR 14 CFR PART 43 APP E     |                                                                                   |           |          |            |                        |           |           |             |                  |
| 341037                                                                                                                                 | LEFT PRIMARY PITOT/STATIC PROBE (P/N 0856TJ1 OR P/N 6634100000-001)               |           |          |            |                        |           |           |             | Component ATA:34 |
| PN:0856TJ1                                                                                                                             | MOS                                                                               | 17-Aug-18 |          | TSN 0      |                        |           |           | LIFE LIMIT  |                  |
| SN:308640                                                                                                                              | HRS                                                                               | 7915.5    | 15000    | TSN 0      | 22915.5                |           | 13246.4   |             |                  |
|                                                                                                                                        | AFL                                                                               | 6079      |          | TSN 0      |                        |           |           |             |                  |
| PROC. REF: AMM 34-11-01PROC. REF: AMM 34-11-01                                                                                         |                                                                                   |           |          |            |                        |           |           |             |                  |
| 341037A                                                                                                                                | TEST/INSPECT LEFT PRIMARY PITOT/STATIC PROBE (P/N 0856TJ1 OR P/N 6634100000-001)  |           |          |            |                        |           |           |             | Service ATA:34   |
| PN:0856TJ1                                                                                                                             | MOS                                                                               | 10-Aug-24 | 24       |            | 10-Aug-26              |           | 495 d     |             |                  |
| SN:308640                                                                                                                              | HRS                                                                               |           |          |            |                        |           |           |             |                  |
|                                                                                                                                        | AFL                                                                               |           |          |            |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REF, FAR FAR 91.411, CFR 14 CFR PART 43 APP EPROC. REF: GENERIC NO REF, FAR FAR 91.411, CFR 14 CFR PART 43 APP E |                                                                                   |           |          |            |                        |           |           |             |                  |
| 341038                                                                                                                                 | RIGHT PRIMARY PITOT/STATIC PROBE (P/N 0856TJ2 OR P/N 6634100000-003)              |           |          |            |                        |           |           |             | Component ATA:34 |
| PN:6634100000-003                                                                                                                      | MOS                                                                               | 09-Dec-24 |          |            |                        |           |           | LIFE LIMIT  |                  |
| SN:276891                                                                                                                              | HRS                                                                               | 9574.3    | 15000    | TSN 7559.6 | 17014.7                |           | 7345.6    |             |                  |
|                                                                                                                                        | AFL                                                                               | 7315      |          | TSN 7118   |                        |           |           |             |                  |
| PROC. REF: AMM 34-11-01PROC. REF: AMM 34-11-01                                                                                         |                                                                                   |           |          |            |                        |           |           |             |                  |
| 341038A                                                                                                                                | TEST/INSPECT RIGHT PRIMARY PITOT/STATIC PROBE (P/N 0856TJ2 OR P/N 6634100000-003) |           |          |            |                        |           |           |             | Service ATA:34   |
| PN:6634100000-003                                                                                                                      | MOS                                                                               | 09-Dec-24 | 24       |            | 09-Dec-26              |           | 616 d     |             |                  |
| SN:276891                                                                                                                              | HRS                                                                               | 9574.3    |          |            |                        |           |           |             |                  |
|                                                                                                                                        | AFL                                                                               | 7315      |          |            |                        |           |           |             |                  |
| PROC. REF: FAR FAR 91.411, AMM 34-11-00, CFR 14 CFR PART 43 APP EPROC. REF: FAR FAR 91.411, AMM 34-11-00, CFR 14 CFR PART 43 APP E     |                                                                                   |           |          |            |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR    Serial: 45-145    RegNo: N942FK    HRS: 9669.1    AFL: 7372    As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                                                                                                            | Unit                                                             | C / W     | Interval | TSX / Adj. | Next Due (ENG / APU) A / C | Max Limit | Remaining | Disposition | Warranty |
|------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------|-----------|----------|------------|----------------------------|-----------|-----------|-------------|----------|
| ATA 34 - NAVIGATION                                                                                                                |                                                                  |           |          |            |                            |           |           |             |          |
| 341049                                                                                                                             | STANDBY PITOT/STATIC PROBE                                       |           |          |            |                            |           |           | Component   | ATA:34   |
| PN:PN                                                                                                                              | MOS/MSC                                                          | 09-Mar-01 | O/C      | TSN 0      |                            |           |           |             |          |
| SN:UNKNOWN                                                                                                                         | HRS                                                              | 0         |          | TSN 0      |                            |           |           |             |          |
|                                                                                                                                    | AFL                                                              | 0         |          | TSN 0      |                            |           |           |             |          |
| PROC. REF: AMM 34-11-01PROC. REF: AMM 34-11-01                                                                                     |                                                                  |           |          |            |                            |           |           |             |          |
| 341049A                                                                                                                            | TEST/INSPECT STANDBY PITOT/STATIC PROBE                          |           |          |            |                            |           |           | Service     | ATA:34   |
|                                                                                                                                    | MOS                                                              | 10-Aug-24 | 24       |            | 10-Aug-26                  |           | 495 d     |             |          |
|                                                                                                                                    | HRS                                                              |           |          |            |                            |           |           |             |          |
|                                                                                                                                    | AFL                                                              |           |          |            |                            |           |           |             |          |
| PROC. REF: FAR FAR 91.411, AMM 34-11-00, CFR 14 CFR PART 43 APP EPROC. REF: FAR FAR 91.411, AMM 34-11-00, CFR 14 CFR PART 43 APP E |                                                                  |           |          |            |                            |           |           |             |          |
| 341061                                                                                                                             | RADAR ALTIMETER RECEIVER                                         |           |          |            |                            |           |           | Component   | ATA:34   |
| PN:7001840-937                                                                                                                     | MOS/MSC                                                          | 18-Oct-24 | O/C      |            |                            |           |           |             |          |
| SN:99118031                                                                                                                        | HRS                                                              | 9555.2    |          |            |                            |           |           |             |          |
|                                                                                                                                    | AFL                                                              | 7301      |          |            |                            |           |           |             |          |
| PROC. REF: AMM 34-14-01PROC. REF: AMM 34-14-01                                                                                     |                                                                  |           |          |            |                            |           |           |             |          |
| 341073                                                                                                                             | FORWARD RADAR ALTIMETER ANTENNA                                  |           |          |            |                            |           |           | Component   | ATA:34   |
| PN:S67-2002-4                                                                                                                      | MOS/MSC                                                          | 14-Jul-07 | O/C      |            |                            |           |           |             |          |
| SN:552-14361                                                                                                                       | HRS                                                              | 5618.1    |          |            |                            |           |           |             |          |
|                                                                                                                                    | AFL                                                              | 4293      |          |            |                            |           |           |             |          |
| PROC. REF: AMM 34-14-02PROC. REF: AMM 34-14-02                                                                                     |                                                                  |           |          |            |                            |           |           |             |          |
| 341074                                                                                                                             | AFT RADAR ALTIMETER ANTENNA                                      |           |          |            |                            |           |           | Component   | ATA:34   |
| PN:S67-2002-4                                                                                                                      | MOS/MSC                                                          | 14-Jul-07 | O/C      |            |                            |           |           |             |          |
| SN:552-13054                                                                                                                       | HRS                                                              | 5618.1    |          |            |                            |           |           |             |          |
|                                                                                                                                    | AFL                                                              | 4293      |          |            |                            |           |           |             |          |
| PROC. REF: AMM 34-14-02PROC. REF: AMM 34-14-02                                                                                     |                                                                  |           |          |            |                            |           |           |             |          |
| 3413-RVSM                                                                                                                          | FLIGHT CHECK ALTITUDE ALERTER FUNCTION. RVSM COMPLIANT AIRCRAFT. |           |          |            |                            |           |           | Service     | ATA:34   |
|                                                                                                                                    | MOS/MSC                                                          | 09-Mar-01 | N/R      |            |                            |           |           |             |          |
|                                                                                                                                    | HRS                                                              | 0         |          |            |                            |           |           |             |          |
|                                                                                                                                    | AFL                                                              | 0         |          |            |                            |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                                                                                 |                                                                  |           |          |            |                            |           |           |             |          |

?-Insufficient Information    S-Suppressed Requirement    \*-Estimated Due(New Requirement)    (EFF)-Effective C / W    (M)-Manual Due    U-User Task    Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                        | Unit                                                 | C / W     | Interval | TSX / Adj. | Next Due (ENG / APU) A / C | Max Limit | Remaining | Disposition | Warranty         |
|------------------------------------------------|------------------------------------------------------|-----------|----------|------------|----------------------------|-----------|-----------|-------------|------------------|
| ATA 34 - NAVIGATION                            |                                                      |           |          |            |                            |           |           |             |                  |
| 341901                                         | (TAT) TOTAL AIR TEMPERATURE PROBE                    |           |          |            |                            |           |           |             | Component ATA:34 |
| PN:PN                                          | MOS/MSC                                              | 09-Mar-01 | O/C      | TSN 0      |                            |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                                  | 0         |          | TSN 0      |                            |           |           |             |                  |
|                                                | AFL                                                  | 0         |          | TSN 0      |                            |           |           |             |                  |
| PROC. REF: AMM 34-17-02PROC. REF: AMM 34-17-02 |                                                      |           |          |            |                            |           |           |             |                  |
| 342001                                         | (AHRs) NO. 1 ATTITUDE HEADING REFERENCE COMPUTER     |           |          |            |                            |           |           |             | Component ATA:34 |
| PN:145130-6000                                 | MOS/MSC                                              | 21-Mar-22 | O/C      |            |                            |           |           |             |                  |
| SN:5001                                        | HRS                                                  | 8909      |          |            |                            |           |           |             |                  |
|                                                | AFL                                                  | 6851      |          |            |                            |           |           |             |                  |
| PROC. REF: AMM 34-26-01PROC. REF: AMM 34-26-01 |                                                      |           |          |            |                            |           |           |             |                  |
| 342002                                         | (AHRs) NO. 2 ATTITUDE HEADING REFERENCE COMPUTER     |           |          |            |                            |           |           |             | Component ATA:34 |
| PN:HG2010AC02                                  | MOS/MSC                                              | 10-Feb-09 | O/C      |            |                            |           |           |             |                  |
| SN:99031032                                    | HRS                                                  | 6104.7    |          |            |                            |           |           |             |                  |
|                                                | AFL                                                  |           |          |            |                            |           |           |             |                  |
| PROC. REF: AMM 34-26-01PROC. REF: AMM 34-26-01 |                                                      |           |          |            |                            |           |           |             |                  |
| 342003                                         | (AHRs) NO. 1 ATTITUDE HEADING REFERENCE COMPUTER FAN |           |          |            |                            |           |           |             | Component ATA:34 |
| PN:PN                                          | MOS/MSC                                              | 09-Mar-01 | O/C      | TSN 0      |                            |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                                  | 0         |          | TSN 0      |                            |           |           |             |                  |
|                                                | AFL                                                  | 0         |          | TSN 0      |                            |           |           |             |                  |
| PROC. REF: AMM 34-26-03PROC. REF: AMM 34-26-03 |                                                      |           |          |            |                            |           |           |             |                  |
| 342004                                         | (AHRs) NO. 2 ATTITUDE HEADING REFERENCE COMPUTER FAN |           |          |            |                            |           |           |             | Component ATA:34 |
| PN:26012423-105                                | MOS/MSC                                              | 10-Aug-12 | O/C      |            |                            |           |           |             |                  |
| SN:10396                                       | HRS                                                  | 6975.7    |          |            |                            |           |           |             |                  |
|                                                | AFL                                                  | 5322      |          |            |                            |           |           |             |                  |
| PROC. REF: AMM 34-26-03PROC. REF: AMM 34-26-03 |                                                      |           |          |            |                            |           |           |             |                  |
| 342037                                         | LEFT FLUX VALVE                                      |           |          |            |                            |           |           |             | Component ATA:34 |
| PN:PN                                          | MOS/MSC                                              | 09-Mar-01 | O/C      | TSN 0      |                            |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                                  | 0         |          | TSN 0      |                            |           |           |             |                  |
|                                                | AFL                                                  | 0         |          | TSN 0      |                            |           |           |             |                  |
| PROC. REF: AMM 34-26-02PROC. REF: AMM 34-26-02 |                                                      |           |          |            |                            |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                            | Unit                                                         | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------|--------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 34 - NAVIGATION                                |                                                              |           |          |          |                        |           |           |             |          |
| 342038                                             | RIGHT FLUX VALVE                                             |           |          |          |                        |           |           | Component   | ATA:34   |
| PN:PN                                              | MOS/MSC                                                      | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS                                                          | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL                                                          | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 34-26-02PROC. REF: AMM 34-26-02     |                                                              |           |          |          |                        |           |           |             |          |
| 342101                                             | DUAL ANGLE OF ATTACK INDICATOR                               |           |          |          |                        |           |           | Component   | ATA:34   |
| PN:PN                                              | MOS/MSC                                                      | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS                                                          | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL                                                          | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                              |           |          |          |                        |           |           |             |          |
| 342103                                             | STANDBY COMPASS                                              |           |          |          |                        |           |           | Component   | ATA:34   |
| PN:PN                                              | MOS/MSC                                                      | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS                                                          | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL                                                          | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 34-21-01PROC. REF: AMM 34-21-01     |                                                              |           |          |          |                        |           |           |             |          |
| 342103A                                            | CALIBRATION CHECK STANDBY COMPASS                            |           |          |          |                        |           |           | Service     | ATA:34   |
| PN:PN                                              | MOS/MSC                                                      | 09-Mar-01 | A/R      |          |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS                                                          | 0         |          |          |                        |           |           |             |          |
|                                                    | AFL                                                          | 0         |          |          |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                              |           |          |          |                        |           |           |             |          |
| 342701                                             | LEFT ATTITUDE HEADING REFERENCE SYSTEM (AHRS) MEMORY MODULE  |           |          |          |                        |           |           | Component   | ATA:34   |
| PN:PN                                              | MOS/MSC                                                      | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS                                                          | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL                                                          | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 34-26-01PROC. REF: AMM 34-26-01     |                                                              |           |          |          |                        |           |           |             |          |
| 342702                                             | RIGHT ATTITUDE HEADING REFERENCE SYSTEM (AHRS) MEMORY MODULE |           |          |          |                        |           |           | Component   | ATA:34   |
| PN:PN                                              | MOS/MSC                                                      | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS                                                          | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL                                                          | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 34-26-01PROC. REF: AMM 34-26-01     |                                                              |           |          |          |                        |           |           |             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                        | Unit                           | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|------------------------------------------------|--------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 34 - NAVIGATION                            |                                |           |          |          |                        |           |           |             |                  |
| 342801                                         | STANDBY ATTITUDE INDICATOR     |           |          |          |                        |           |           |             | Component ATA:34 |
| PN:501-1648-02                                 | MOS/MSC                        | 12-Sep-22 | O/C      |          |                        |           |           |             |                  |
| SN:1338                                        | HRS                            | 9101.8    |          |          |                        |           |           |             |                  |
|                                                | AFL                            | 6994      |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 34-23-01PROC. REF: AMM 34-23-01 |                                |           |          |          |                        |           |           |             |                  |
| 343005                                         | MARKER BEACON ANTENNA          |           |          |          |                        |           |           |             | Component ATA:34 |
| PN:PN                                          | MOS/MSC                        | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                            | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                            | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 34-30-01PROC. REF: AMM 34-30-01 |                                |           |          |          |                        |           |           |             |                  |
| 343008                                         | UPPER GLIDESCOPE (E11) ANTENNA |           |          |          |                        |           |           |             | Component ATA:34 |
| PN:PN                                          | MOS/MSC                        | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                            | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                            | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 34-30-02PROC. REF: AMM 34-30-02 |                                |           |          |          |                        |           |           |             |                  |
| 343009                                         | LOWER GLIDESCOPE (E12) ANTENNA |           |          |          |                        |           |           |             | Component ATA:34 |
| PN:PN                                          | MOS/MSC                        | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                            | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                            | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 34-30-02PROC. REF: AMM 34-30-02 |                                |           |          |          |                        |           |           |             |                  |
| 343030                                         | MARKER BEACON ANTENNA SPLITTER |           |          |          |                        |           |           |             | Component ATA:34 |
| PN:PN                                          | MOS/MSC                        | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                            | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                            | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 34-30-03PROC. REF: AMM 34-30-03 |                                |           |          |          |                        |           |           |             |                  |
| 344111                                         | UPPER TCAS ANTENNA             |           |          |          |                        |           |           |             | Component ATA:34 |
| PN:071-01548-0200                              | MOS/MSC                        | 15-Oct-09 | O/C      |          |                        |           |           |             |                  |
| SN:587-10110                                   | HRS                            | 6191.1    |          |          |                        |           |           |             |                  |
|                                                | AFL                            |           |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 34-43-02PROC. REF: AMM 34-43-02 |                                |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR    Serial: 45-145    RegNo: N942FK    HRS: 9669.1    AFL: 7372    As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                            | Unit                           | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------|--------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 34 - NAVIGATION                                |                                |           |          |          |                        |           |           |             |          |
| 344112                                             | LOWER TCAS ANTENNA             |           |          |          |                        |           |           | Component   | ATA:34   |
| PN:PN                                              | MOS/MSC                        | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS                            | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL                            | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 34-43-02PROC. REF: AMM 34-43-02     |                                |           |          |          |                        |           |           |             |          |
| 344143                                             | TCAS PROCESSOR                 |           |          |          |                        |           |           | Component   | ATA:34   |
| PN:066-01146-1211                                  | MOS/MSC                        | 06-Jan-22 | O/C      |          |                        |           |           |             |          |
| SN:41568                                           | HRS                            | 8821.5    |          |          |                        |           |           |             |          |
|                                                    | AFL                            | 6790      |          |          |                        |           |           |             |          |
| PROC. REF: AMM 34-43-01PROC. REF: AMM 34-43-01     |                                |           |          |          |                        |           |           |             |          |
| 344155                                             | TCAS RELAY BOX ASSEMBLY        |           |          |          |                        |           |           | Component   | ATA:34   |
| PN:PN                                              | MOS/MSC                        | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS                            | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL                            | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 34-43-03PROC. REF: AMM 34-43-03     |                                |           |          |          |                        |           |           |             |          |
| 344167                                             | TCAS CONFIGURATION MODULE      |           |          |          |                        |           |           | Component   | ATA:34   |
| PN:PN                                              | MOS/MSC                        | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS                            | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL                            | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                |           |          |          |                        |           |           |             |          |
| 344171                                             | NO. 1 TCAS UPPER ANTENNA CABLE |           |          |          |                        |           |           | Component   | ATA:34   |
| PN:PN                                              | MOS/MSC                        | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS                            | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL                            | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                |           |          |          |                        |           |           |             |          |
| 344172                                             | NO. 2 TCAS UPPER ANTENNA CABLE |           |          |          |                        |           |           | Component   | ATA:34   |
| PN:PN                                              | MOS/MSC                        | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS                            | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL                            | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                |           |          |          |                        |           |           |             |          |

?-Insufficient Information    S-Suppressed Requirement    \*-Estimated Due(New Requirement)    (EFF)-Effective C/W    (M)-Manual Due    U-User Task    Ex-Excluded Task

Status Report

Model: LEARJET 45XR    Serial: 45-145    RegNo: N942FK    HRS: 9669.1    AFL: 7372    As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                            | Unit                           | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------|--------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 34 - NAVIGATION                                |                                |           |          |          |                        |           |           |             |          |
| 344173                                             | NO. 3 TCAS UPPER ANTENNA CABLE |           |          |          |                        |           |           | Component   | ATA:34   |
| PN:PN                                              | MOS/MSC                        | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS                            | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL                            | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                |           |          |          |                        |           |           |             |          |
| 344174                                             | NO. 4 TCAS UPPER ANTENNA CABLE |           |          |          |                        |           |           | Component   | ATA:34   |
| PN:PN                                              | MOS/MSC                        | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS                            | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL                            | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                |           |          |          |                        |           |           |             |          |
| 344176                                             | UPPER TCAS ADAPTER ASSEMBLY    |           |          |          |                        |           |           | Component   | ATA:34   |
| PN:PN                                              | MOS/MSC                        | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS                            | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL                            | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                |           |          |          |                        |           |           |             |          |
| 344177                                             | LOWER TCAS ADAPTER ASSEMBLY    |           |          |          |                        |           |           | Component   | ATA:34   |
| PN:PN                                              | MOS/MSC                        | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS                            | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL                            | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                |           |          |          |                        |           |           |             |          |
| 344181                                             | NO. 1 TCAS LOWER ANTENNA CABLE |           |          |          |                        |           |           | Component   | ATA:34   |
| PN:PN                                              | MOS/MSC                        | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS                            | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL                            | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                |           |          |          |                        |           |           |             |          |
| 344182                                             | NO. 2 TCAS LOWER ANTENNA CABLE |           |          |          |                        |           |           | Component   | ATA:34   |
| PN:PN                                              | MOS/MSC                        | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS                            | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL                            | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                |           |          |          |                        |           |           |             |          |

?-Insufficient Information    S-Suppressed Requirement    \*-Estimated Due(New Requirement)    (EFF)-Effective C/W    (M)-Manual Due    U-User Task    Ex-Excluded Task

Status Report

Model: LEARJET 45XR    Serial: 45-145    RegNo: N942FK    HRS: 9669.1    AFL: 7372    As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                            | Unit                                       | C / W     | Interval | TSX / Adj. | Next Due (ENG / APU) A / C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------|--------------------------------------------|-----------|----------|------------|----------------------------|-----------|-----------|-------------|----------|
| ATA 34 - NAVIGATION                                |                                            |           |          |            |                            |           |           |             |          |
| 344183                                             | NO. 3 TCAS LOWER ANTENNA CABLE             |           |          |            |                            |           |           | Component   | ATA:34   |
| PN:PN                                              | MOS/MSC                                    | 09-Mar-01 | O/C      | TSN 0      |                            |           |           |             |          |
| SN:UNKNOWN                                         | HRS                                        | 0         |          | TSN 0      |                            |           |           |             |          |
|                                                    | AFL                                        | 0         |          | TSN 0      |                            |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                            |           |          |            |                            |           |           |             |          |
| 344184                                             | NO. 4 TCAS LOWER ANTENNA CABLE             |           |          |            |                            |           |           | Component   | ATA:34   |
| PN:PN                                              | MOS/MSC                                    | 09-Mar-01 | O/C      | TSN 0      |                            |           |           |             |          |
| SN:UNKNOWN                                         | HRS                                        | 0         |          | TSN 0      |                            |           |           |             |          |
|                                                    | AFL                                        | 0         |          | TSN 0      |                            |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                            |           |          |            |                            |           |           |             |          |
| 344205                                             | WEATHER RADAR RECEIVER/TRANSMITTER/ANTENNA |           |          |            |                            |           |           | Component   | ATA:34   |
| PN:7021450-601                                     | MOS/MSC                                    | 11-Aug-09 | O/C      |            |                            |           |           |             |          |
| SN:07067540                                        | HRS                                        | 6169.3    |          |            |                            |           |           |             |          |
|                                                    | AFL                                        | 4725      |          |            |                            |           |           |             |          |
| PROC. REF: AMM 34-42-01PROC. REF: AMM 34-42-01     |                                            |           |          |            |                            |           |           |             |          |
| 344207                                             | WEATHER RADAR TRANSCEIVER                  |           |          |            |                            |           |           | Component   | ATA:34   |
| PN:PN                                              | MOS/MSC                                    | 09-Mar-01 | O/C      | TSN 0      |                            |           |           |             |          |
| SN:UNKNOWN                                         | HRS                                        | 0         |          | TSN 0      |                            |           |           |             |          |
|                                                    | AFL                                        | 0         |          | TSN 0      |                            |           |           |             |          |
| PROC. REF: AMM 34-42-01PROC. REF: AMM 34-42-01     |                                            |           |          |            |                            |           |           |             |          |
| 344209                                             | WEATHER RADAR LIGHTNING SENSOR ANTENNA     |           |          |            |                            |           |           | Component   | ATA:34   |
| PN:PN                                              | MOS/MSC                                    | 09-Mar-01 | O/C      | TSN 0      |                            |           |           |             |          |
| SN:UNKNOWN                                         | HRS                                        | 0         |          | TSN 0      |                            |           |           |             |          |
|                                                    | AFL                                        | 0         |          | TSN 0      |                            |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                            |           |          |            |                            |           |           |             |          |
| 344221                                             | WEATHER RADAR CONTROLLER                   |           |          |            |                            |           |           | Component   | ATA:34   |
| PN:PN                                              | MOS/MSC                                    | 09-Mar-01 | O/C      | TSN 0      |                            |           |           |             |          |
| SN:UNKNOWN                                         | HRS                                        | 0         |          | TSN 0      |                            |           |           |             |          |
|                                                    | AFL                                        | 0         |          | TSN 0      |                            |           |           |             |          |
| PROC. REF: AMM 34-42-02PROC. REF: AMM 34-42-02     |                                            |           |          |            |                            |           |           |             |          |

?-Insufficient Information    S-Suppressed Requirement    \*-Estimated Due(New Requirement)    (EFF)-Effective C / W    (M)-Manual Due    U-User Task    Ex-Excluded Task

Status Report

Model: LEARJET 45XR    Serial: 45-145    RegNo: N942FK    HRS: 9669.1    AFL: 7372    As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                            | Unit                                                  | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------|-------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 34 - NAVIGATION                                |                                                       |           |          |          |                        |           |           |             |          |
| 344223                                             | LIGHTNING DETECTION PROCESSOR                         |           |          |          |                        |           |           | Component   | ATA:34   |
| PN:PN                                              | MOS/MSC                                               | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS                                                   | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL                                                   | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                       |           |          |          |                        |           |           |             |          |
| 344513                                             | TERRAIN AWARENESS WARNING (TAWS) COMPUTER             |           |          |          |                        |           |           | Component   | ATA:34   |
| PN:PN                                              | MOS/MSC                                               | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS                                                   | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL                                                   | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                       |           |          |          |                        |           |           |             |          |
| 344514                                             | TERRAIN AWARENESS WARNING (TAWS) CONFIGURATION MODULE |           |          |          |                        |           |           | Component   | ATA:34   |
| PN:PN                                              | MOS/MSC                                               | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS                                                   | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL                                                   | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                       |           |          |          |                        |           |           |             |          |
| 344515                                             | TAWS RELAY BOX                                        |           |          |          |                        |           |           | Component   | ATA:34   |
| PN:PN                                              | MOS/MSC                                               | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS                                                   | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL                                                   | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                       |           |          |          |                        |           |           |             |          |
| 345001                                             | NO. 1 INTEGRATED NAVIGATION UNIT                      |           |          |          |                        |           |           | Component   | ATA:34   |
| PN:7510100-631                                     | MOS/MSC                                               | 17-Feb-05 | O/C      |          |                        |           |           |             |          |
| SN:01015045                                        | HRS                                                   | 3300.2    |          |          |                        |           |           |             |          |
|                                                    | AFL                                                   | 2515      |          |          |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                       |           |          |          |                        |           |           |             |          |
| 345002                                             | NO. 2 INTEGRATED NAVIGATION UNIT                      |           |          |          |                        |           |           | Component   | ATA:34   |
| PN:7510100-633                                     | MOS/MSC                                               | 17-Feb-05 | O/C      |          |                        |           |           |             |          |
| SN:99124053                                        | HRS                                                   | 3300.2    |          |          |                        |           |           |             |          |
|                                                    | AFL                                                   | 2515      |          |          |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                       |           |          |          |                        |           |           |             |          |

?-Insufficient Information    S-Suppressed Requirement    \*-Estimated Due(New Requirement)    (EFF)-Effective C/W    (M)-Manual Due    U-User Task    Ex-Excluded Task

# Status Report

Model: LEARJET 45XR    Serial: 45-145    RegNo: N942FK    HRS: 9669.1    AFL: 7372    As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                            | Unit                                               | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty            |
|----------------------------------------------------|----------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|---------------------|
| ATA 34 - NAVIGATION                                |                                                    |           |          |          |                        |           |           |             |                     |
| 345011                                             | NO. 1 NAVIGATION RECEIVER MODULE                   |           |          |          |                        |           |           |             | Component    ATA:34 |
| PN:PN                                              | MOS/MSC                                            | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                         | HRS                                                | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                    | AFL                                                | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                    |           |          |          |                        |           |           |             |                     |
| 345012                                             | NO. 2 NAVIGATION RECEIVER MODULE                   |           |          |          |                        |           |           |             | Component    ATA:34 |
| PN:PN                                              | MOS/MSC                                            | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                         | HRS                                                | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                    | AFL                                                | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                    |           |          |          |                        |           |           |             |                     |
| 345013                                             | NO. 1 ADF ANTENNA                                  |           |          |          |                        |           |           |             | Component    ATA:34 |
| PN:PN                                              | MOS/MSC                                            | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                         | HRS                                                | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                    | AFL                                                | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: AMM 34-57-01PROC. REF: AMM 34-57-01     |                                                    |           |          |          |                        |           |           |             |                     |
| 345014                                             | NO. 2 ADF ANTENNA                                  |           |          |          |                        |           |           |             | Component    ATA:34 |
| PN:PN                                              | MOS/MSC                                            | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                         | HRS                                                | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                    | AFL                                                | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: AMM 34-57-01PROC. REF: AMM 34-57-01     |                                                    |           |          |          |                        |           |           |             |                     |
| 345024                                             | GPWS CONTROL PANEL                                 |           |          |          |                        |           |           |             | Component    ATA:34 |
| PN:PN                                              | MOS/MSC                                            | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                         | HRS                                                | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                    | AFL                                                | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                    |           |          |          |                        |           |           |             |                     |
| 345025                                             | ENHANCED GROUND PROXIMITY WARNING (EGPWS) COMPUTER |           |          |          |                        |           |           |             | Component    ATA:34 |
| PN:PN                                              | MOS/MSC                                            | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                         | HRS                                                | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                    | AFL                                                | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: AMM 34-45-01PROC. REF: AMM 34-45-01     |                                                    |           |          |          |                        |           |           |             |                     |

?-Insufficient Information    S-Suppressed Requirement    \*-Estimated Due(New Requirement)    (EFF)-Effective C/W    (M)-Manual Due    U-User Task    Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                            | Unit                        | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------|-----------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 34 - NAVIGATION                                |                             |           |          |          |                        |           |           |             |                  |
| 345037                                             | FORWARD ATC ANTENNA         |           |          |          |                        |           |           |             | Component ATA:34 |
| PN:DMNI50-2-2                                      | MOS/MSC                     | 16-Jul-19 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:143631                                          | HRS                         | 8109      |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                         | 6239      |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                             |           |          |          |                        |           |           |             |                  |
| 345038                                             | AFT ATC ANTENNA             |           |          |          |                        |           |           |             | Component ATA:34 |
| PN:DMNI50-2-2                                      | MOS/MSC                     | 16-Jul-19 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:143620                                          | HRS                         | 8109      |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                         | 6239      |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                             |           |          |          |                        |           |           |             |                  |
| 345049                                             | AFT (NO. 1) DME ANTENNA     |           |          |          |                        |           |           |             | Component ATA:34 |
| PN:DMNI50-2-2                                      | MOS/MSC                     | 16-Jul-19 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:143632                                          | HRS                         | 8109      |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                         | 6239      |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 34-55-01PROC. REF: AMM 34-55-01     |                             |           |          |          |                        |           |           |             |                  |
| 345050                                             | FORWARD (NO. 2) DME ANTENNA |           |          |          |                        |           |           |             | Component ATA:34 |
| PN:DMNI50-9-2                                      | MOS/MSC                     | 16-Jul-19 | O/C      | TSN 10   |                        |           |           |             |                  |
| SN:22086                                           | HRS                         | 8109      |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                         | 6239      |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 34-55-01PROC. REF: AMM 34-55-01     |                             |           |          |          |                        |           |           |             |                  |
| 345083                                             | LEFT VOR/LOCALIZER ANTENNA  |           |          |          |                        |           |           |             | Component ATA:34 |
| PN:DMN4-17-1/N                                     | MOS/MSC                     | 25-Nov-19 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:21995                                           | HRS                         | 8177.7    |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                         | 6303      |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 34-51-02PROC. REF: AMM 34-51-02     |                             |           |          |          |                        |           |           |             |                  |
| 345084                                             | RIGHT VOR/LOCALIZER ANTENNA |           |          |          |                        |           |           |             | Component ATA:34 |
| PN:DMN4-17-1/N                                     | MOS/MSC                     | 25-Nov-19 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:21818                                           | HRS                         | 8177.7    |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                         | 6303      |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 34-51-02PROC. REF: AMM 34-51-02     |                             |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9669.1
 AFL: 7372
 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                            | Unit                                        | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------|---------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 34 - NAVIGATION                                |                                             |           |          |          |                        |           |           |             |                  |
| 345201                                             | NAV VHF (A42) DUPLEXER                      |           |          |          |                        |           |           |             | Component ATA:34 |
| PN:PN                                              | MOS/MSC                                     | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                         | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                         | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 34-51-04PROC. REF: AMM 34-51-04     |                                             |           |          |          |                        |           |           |             |                  |
| 345260                                             | PHASING COUPLER                             |           |          |          |                        |           |           |             | Component ATA:34 |
| PN:PN                                              | MOS/MSC                                     | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                         | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                         | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 34-51-03PROC. REF: AMM 34-51-03     |                                             |           |          |          |                        |           |           |             |                  |
| 345501                                             | DME INDICATOR                               |           |          |          |                        |           |           |             | Component ATA:34 |
| PN:PN                                              | MOS/MSC                                     | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                         | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                         | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                             |           |          |          |                        |           |           |             |                  |
| 345605                                             | LEFT UPPER MODE S ATC ANTENNA               |           |          |          |                        |           |           |             | Component ATA:34 |
| PN:PN                                              | MOS/MSC                                     | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                         | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                         | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                             |           |          |          |                        |           |           |             |                  |
| 345606                                             | RIGHT UPPER MODE S ATC ANTENNA              |           |          |          |                        |           |           |             | Component ATA:34 |
| PN:PN                                              | MOS/MSC                                     | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                         | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                         | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                             |           |          |          |                        |           |           |             |                  |
| 346001                                             | PILOT FLIGHT MANAGEMENT CONTROL DISPLAY CDU |           |          |          |                        |           |           |             | Component ATA:34 |
| PN:3017-41-221                                     | MOS/MSC                                     | 13-Apr-17 | O/C      |          |                        |           |           |             |                  |
| SN:2081                                            | HRS                                         | 7744.3    |          |          |                        |           |           |             |                  |
|                                                    | AFL                                         | 5922      |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 34-60-01PROC. REF: AMM 34-60-01     |                                             |           |          |          |                        |           |           |             |                  |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C/W   (M)-Manual Due   U-User Task   Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                            | Unit                                          | C / W     | Interval | TSX / Adj. | Next Due (ENG / APU) A / C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------|-----------------------------------------------|-----------|----------|------------|----------------------------|-----------|-----------|-------------|----------|
| ATA 34 - NAVIGATION                                |                                               |           |          |            |                            |           |           |             |          |
| 346002                                             | COPILOT FLIGHT MANAGEMENT CONTROL DISPLAY CDU |           |          |            |                            |           |           | Component   | ATA:34   |
| PN:3017-41-221                                     | MOS/MSC                                       | 13-Apr-17 | O/C      |            |                            |           |           |             |          |
| SN:2082                                            | HRS                                           | 7744.3    |          |            |                            |           |           |             |          |
|                                                    | AFL                                           | 5922      |          |            |                            |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                               |           |          |            |                            |           |           |             |          |
| 346021                                             | FMS DATA (DTU) TRANSFER UNIT                  |           |          |            |                            |           |           | Component   | ATA:34   |
| PN:1408-00-1                                       | MOS/MSC                                       | 13-Apr-17 | O/C      |            |                            |           |           |             |          |
| SN:3597                                            | HRS                                           | 7744.3    |          |            |                            |           |           |             |          |
|                                                    | AFL                                           | 5922      |          |            |                            |           |           |             |          |
| PROC. REF: AMM 34-60-02PROC. REF: AMM 34-60-02     |                                               |           |          |            |                            |           |           |             |          |
| 346025                                             | NO. 1 FLIGHT MANAGEMENT CONFIGURATION MODULE  |           |          |            |                            |           |           | Component   | ATA:34   |
| PN:30171                                           | MOS/MSC                                       | 13-Apr-17 | O/C      |            |                            |           |           |             |          |
| SN:2173                                            | HRS                                           | 7744.3    |          |            |                            |           |           |             |          |
|                                                    | AFL                                           | 5922      |          |            |                            |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                               |           |          |            |                            |           |           |             |          |
| 346026                                             | NO. 2 FLIGHT MANAGEMENT CONFIGURATION MODULE  |           |          |            |                            |           |           | Component   | ATA:34   |
| PN:30171                                           | MOS/MSC                                       | 13-Apr-17 | O/C      |            |                            |           |           |             |          |
| SN:2174                                            | HRS                                           | 7744.3    |          |            |                            |           |           |             |          |
|                                                    | AFL                                           | 5922      |          |            |                            |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                               |           |          |            |                            |           |           |             |          |
| 346031                                             | NO. 1 FMS ANTENNA                             |           |          |            |                            |           |           | Component   | ATA:34   |
| PN:PN                                              | MOS/MSC                                       | 09-Mar-01 | O/C      | TSN 0      |                            |           |           |             |          |
| SN:UNKNOWN                                         | HRS                                           | 0         |          | TSN 0      |                            |           |           |             |          |
|                                                    | AFL                                           | 0         |          | TSN 0      |                            |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                               |           |          |            |                            |           |           |             |          |
| 346032                                             | NO. 2 FMS ANTENNA                             |           |          |            |                            |           |           | Component   | ATA:34   |
| PN:PN                                              | MOS/MSC                                       | 09-Mar-01 | O/C      | TSN 0      |                            |           |           |             |          |
| SN:UNKNOWN                                         | HRS                                           | 0         |          | TSN 0      |                            |           |           |             |          |
|                                                    | AFL                                           | 0         |          | TSN 0      |                            |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                               |           |          |            |                            |           |           |             |          |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C/W   (M)-Manual Due   U-User Task   Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                            | Unit    | C/W                                                                                                       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------|---------|-----------------------------------------------------------------------------------------------------------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 34 - NAVIGATION                                |         |                                                                                                           |          |          |                        |           |           |             |                  |
| 346037                                             | U       | NO. 1 FMS CONTROL UNIT                                                                                    |          |          |                        |           |           |             | Component ATA:34 |
| PN:PN                                              | MOS/MSC | 09-Mar-01                                                                                                 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS     | 0                                                                                                         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL     | 0                                                                                                         |          | TSN 0    |                        |           |           |             |                  |
|                                                    |         |                                                                                                           |          |          |                        |           |           |             |                  |
| 346038                                             | U       | NO. 2 FMS CONTROL UNIT                                                                                    |          |          |                        |           |           |             | Component ATA:34 |
| PN:PN                                              | MOS/MSC | 09-Mar-01                                                                                                 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS     | 0                                                                                                         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL     | 0                                                                                                         |          | TSN 0    |                        |           |           |             |                  |
|                                                    |         |                                                                                                           |          |          |                        |           |           |             |                  |
| 346090                                             |         | AFIS DATA MANAGEMENT UNIT                                                                                 |          |          |                        |           |           |             | Component ATA:34 |
| PN:PN                                              | MOS/MSC | 09-Mar-01                                                                                                 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS     | 0                                                                                                         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL     | 0                                                                                                         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |         |                                                                                                           |          |          |                        |           |           |             |                  |
|                                                    |         |                                                                                                           |          |          |                        |           |           |             |                  |
| 347510                                             |         | NO. 1 GPS ANTENNA                                                                                         |          |          |                        |           |           |             | Component ATA:34 |
| PN:10708                                           | MOS/MSC | 13-Apr-17                                                                                                 | O/C      |          |                        |           |           |             |                  |
| SN:9815                                            | HRS     | 7744.3                                                                                                    |          |          |                        |           |           |             |                  |
|                                                    | AFL     | 5922                                                                                                      |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 34-53-01PROC. REF: AMM 34-53-01     |         |                                                                                                           |          |          |                        |           |           |             |                  |
|                                                    |         |                                                                                                           |          |          |                        |           |           |             |                  |
| 347511                                             |         | NO. 2 GPS ANTENNA                                                                                         |          |          |                        |           |           |             | Component ATA:34 |
| PN:10708                                           | MOS/MSC | 13-Apr-17                                                                                                 | O/C      |          |                        |           |           |             |                  |
| SN:9814                                            | HRS     | 7744.3                                                                                                    |          |          |                        |           |           |             |                  |
|                                                    | AFL     | 5922                                                                                                      |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 34-53-01PROC. REF: AMM 34-53-01     |         |                                                                                                           |          |          |                        |           |           |             |                  |
|                                                    |         |                                                                                                           |          |          |                        |           |           |             |                  |
| 5-19-02-RVSM-L3411062                              |         | DETAILED VISUAL INSPECTION OF PITOT-STATIC PROBES RVSM COMPLIANT AIRCRAFT(ZONE/ACCESS 220 IRN # L3411062) |          |          |                        |           |           |             | Service ATA:34   |
|                                                    | MOS     | 10-Aug-24                                                                                                 | 24       | Adj 6d   | 16-Aug-26              |           | 501 d     | RVSM        |                  |
|                                                    | HRS     |                                                                                                           |          |          |                        |           |           |             |                  |
|                                                    | AFL     |                                                                                                           |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 34-11-01PROC. REF: AMM 34-11-01     |         |                                                                                                           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|---------|------|-----|----------|----------|------------------------|-----------|-----------|-------------|----------|
|---------|------|-----|----------|----------|------------------------|-----------|-----------|-------------|----------|

ATA 34 - NAVIGATION

|                                                |                                                                                                                   |           |    |        |           |  |       |         |        |
|------------------------------------------------|-------------------------------------------------------------------------------------------------------------------|-----------|----|--------|-----------|--|-------|---------|--------|
| 5-19-02-RVSM-M3411052                          | VERIFY PITCH, ROLL, AND YAW ALIGNMENT OF THE PRIMARY PITOT-STATIC PROBES RVSM COMPLIANT AIRCRAFT (IRN # M3411052) |           |    |        |           |  |       | Service | ATA:34 |
|                                                | MOS                                                                                                               | 10-Aug-24 | 24 | Adj 6d | 16-Aug-26 |  | 501 d | RVSM    |        |
|                                                | HRS                                                                                                               |           |    |        |           |  |       |         |        |
|                                                | AFL                                                                                                               |           |    |        |           |  |       |         |        |
| PROC. REF: AMM 34-11-01PROC. REF: AMM 34-11-01 |                                                                                                                   |           |    |        |           |  |       |         |        |

|                                                |                                                                                                                                      |           |    |        |           |  |       |         |        |
|------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------|-----------|----|--------|-----------|--|-------|---------|--------|
| 5-19-02-RVSM-U3411060                          | PERFORM FUNCTIONAL TEST - AIR DATA SYSTEM (EFFECTIVE ON AIRCRAFT CERTIFIED & MAINTAINED FOR RVSM) (REFER TO 34-17-00) (IRN U3411060) |           |    |        |           |  |       | Service | ATA:34 |
|                                                | MOS                                                                                                                                  | 10-Aug-24 | 24 | Adj 6d | 16-Aug-26 |  | 501 d | RVSM    |        |
|                                                | HRS                                                                                                                                  |           |    |        |           |  |       |         |        |
|                                                | AFL                                                                                                                                  |           |    |        |           |  |       |         |        |
| PROC. REF: AMM 34-17-00PROC. REF: AMM 34-17-00 |                                                                                                                                      |           |    |        |           |  |       |         |        |

|                                                |                                                   |           |     |  |  |  |  |               |        |
|------------------------------------------------|---------------------------------------------------|-----------|-----|--|--|--|--|---------------|--------|
| A3400000 <sup>S</sup>                          | ** NAVIGATION SYSTEMS - PERFORM OPERATIONAL CHECK |           |     |  |  |  |  | Service       | ATA:34 |
|                                                | MOS                                               | 02-Aug-24 | 24  |  |  |  |  | AIRWORTHINESS |        |
|                                                | HRS                                               | 9525.7    | 600 |  |  |  |  |               |        |
|                                                | AFL                                               | 7276      |     |  |  |  |  |               |        |
| PROC. REF: AMM 34-00-00PROC. REF: AMM 34-00-00 |                                                   |           |     |  |  |  |  |               |        |

PKG:7

|                                                |                                                                                                                                     |           |     |  |  |  |  |         |        |
|------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------|-----------|-----|--|--|--|--|---------|--------|
| V3420000 <sup>S</sup>                          | ATTITUDE HEADING REFERENCE UNIT (AHRU) MOUNTING TRAY FAN FILTER - PERFORM VISUAL INSPECTION. ENSURE FILTER IS FREE OF OBSTRUCTIONS. |           |     |  |  |  |  | Service | ATA:34 |
|                                                | MOS                                                                                                                                 | 02-Aug-24 | 24  |  |  |  |  |         |        |
|                                                | HRS                                                                                                                                 | 9525.7    | 600 |  |  |  |  |         |        |
|                                                | AFL                                                                                                                                 | 7276      |     |  |  |  |  |         |        |
| PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00 |                                                                                                                                     |           |     |  |  |  |  |         |        |

PKG:7

|                                                |                                                                                              |           |     |  |  |  |  |         |        |
|------------------------------------------------|----------------------------------------------------------------------------------------------|-----------|-----|--|--|--|--|---------|--------|
| Y3411000 <sup>S</sup>                          | PITOT-STATIC PROBE - PERFORM VISUAL INSPECTION. ENSURE DRAIN HOLES ARE CLEAR OF OBSTRUCTIONS |           |     |  |  |  |  | Service | ATA:34 |
|                                                | MOS                                                                                          | 02-Aug-24 | 24  |  |  |  |  |         |        |
|                                                | HRS                                                                                          | 9525.7    | 600 |  |  |  |  |         |        |
|                                                | AFL                                                                                          | 7276      |     |  |  |  |  |         |        |
| PROC. REF: AMM 34-11-01PROC. REF: AMM 34-11-01 |                                                                                              |           |     |  |  |  |  |         |        |

PKG:7

ATA 35 - OXYGEN

|              |                 |           |     |        |           |  |        |            |        |
|--------------|-----------------|-----------|-----|--------|-----------|--|--------|------------|--------|
| 350001       | OXYGEN CYLINDER |           |     |        |           |  |        | Component  | ATA:35 |
| PN:806385-14 | MOS             | 28-Aug-23 | 180 | TSN 15 | 28-May-37 |  | 4439 d | LIFE LIMIT |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                                                                                                                               | Unit    | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|-------------------------------------------------------------------------------------------------------------------------------------------------------|---------|-----------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 35 - OXYGEN                                                                                                                                       |         |           |          |          |                        |           |           |             |          |
| SN:C10050116                                                                                                                                          | HRS     | 9307.4    |          |          |                        |           |           |             |          |
|                                                                                                                                                       | AFL     | 7125      |          |          |                        |           |           |             |          |
| PROC. REF: AMM 35-00-01PROC. REF: AMM 35-00-01                                                                                                        |         |           |          |          |                        |           |           |             |          |
| 350001A HYDROSTATIC TEST OXYGEN CYLINDER ** (IRN Q3510005 - STANDARD CAPACITY; Q3510018 - INCREASED CAPACITY) Service ATA:35                          |         |           |          |          |                        |           |           |             |          |
| PN:806385-14                                                                                                                                          | MOS     | 27-Jun-23 | 60       |          | 27-Jun-28              |           | 1182 d    |             |          |
| SN:C10050116                                                                                                                                          | HRS     | 9307.4    | 5000     |          | 14307.4                |           | 4638.3    |             |          |
|                                                                                                                                                       | AFL     | 7125      |          |          |                        |           |           |             |          |
| HydroCheck Date: : 27-Jun-23                                                                                                                          |         |           |          |          |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                                                                                                    |         |           |          |          |                        |           |           |             |          |
| 350001C FUNCTIONAL TEST OXYGEN CYLINDER ** LOW PRESSURE RELIEF VALVE (IRN Q3510005 - STANDARD CAPACITY; Q3510018 - INCREASED CAPACITY) Service ATA:35 |         |           |          |          |                        |           |           |             |          |
| PN:806385-14                                                                                                                                          | MOS     | 28-Aug-23 | 60       |          | 28-Aug-28              |           | 1244 d    |             |          |
| SN:C10050116                                                                                                                                          | HRS     | 9307.4    | 5000     |          | 14307.4                |           | 4638.3    |             |          |
|                                                                                                                                                       | AFL     | 7125      |          |          |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                                                                                                    |         |           |          |          |                        |           |           |             |          |
| 350013 OXYGEN CYLINDER LOW PRESSURE RELIEF VALVE Component ATA:35                                                                                     |         |           |          |          |                        |           |           |             |          |
| PN:PN                                                                                                                                                 | MOS/MSC | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                                                                                                                            | HRS     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                                                                                                                       | AFL     | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                                                                                                    |         |           |          |          |                        |           |           |             |          |
| 350201 TEMP/PRESSURE TRANSDUCER Component ATA:35                                                                                                      |         |           |          |          |                        |           |           |             |          |
| PN:10008789                                                                                                                                           | MOS/MSC | 22-Jun-23 | O/C      |          |                        |           |           |             |          |
| SN:20201184                                                                                                                                           | HRS     | 9258.5    |          |          |                        |           |           |             |          |
|                                                                                                                                                       | AFL     | 7100      |          |          |                        |           |           |             |          |
| PROC. REF: AMM 35-00-03PROC. REF: AMM 35-00-03                                                                                                        |         |           |          |          |                        |           |           |             |          |
| 350225 OXYGEN FILL (POST SB 45-12-1) VALVE Component ATA:35                                                                                           |         |           |          |          |                        |           |           |             |          |
| PN:P21010                                                                                                                                             | MOS/MSC | 16-Jul-19 | O/C      | TSN 51   |                        |           |           |             |          |
| SN:7488                                                                                                                                               | HRS     | 8109      |          | TSN 0    |                        |           |           |             |          |
|                                                                                                                                                       | AFL     | 6239      |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                                                                                                    |         |           |          |          |                        |           |           |             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9669.1
 AFL: 7372
 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                            | Unit                                                                                   | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------|----------------------------------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 35 - OXYGEN                                    |                                                                                        |           |          |          |                        |           |           |             |                  |
| 350230                                             | REMOTE OXYGEN PRESSURE INDICATOR                                                       |           |          |          |                        |           |           |             | Component ATA:35 |
| PN:PN                                              | MOS/MSC                                                                                | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                                                                    | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                                                                    | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 35-00-05PROC. REF: AMM 35-00-05     |                                                                                        |           |          |          |                        |           |           |             |                  |
| 351001                                             | PILOT OXYGEN MASK                                                                      |           |          |          |                        |           |           |             | Component ATA:35 |
| PN:MC10-15-166                                     | MOS/MSC                                                                                | 28-Aug-23 | O/C      | TSO 0    |                        |           |           |             |                  |
| SN:100994                                          | HRS                                                                                    | 9307.4    |          | TSO 0    |                        |           |           |             |                  |
|                                                    | AFL                                                                                    | 7125      |          | TSO 0    |                        |           |           |             |                  |
| PROC. REF: AMM 35-10-01PROC. REF: AMM 35-10-01     |                                                                                        |           |          |          |                        |           |           |             |                  |
| 351001A                                            | OVERHAUL PILOT OXYGEN MASK PER MANUFACTURER'S INSTRUCTIONS (IRN # L3510016/O3510006)   |           |          |          |                        |           |           |             | Service ATA:35   |
| PN:MC10-15-166                                     | MOS                                                                                    | 03-Aug-23 | 72       |          | 03-Aug-29              |           | 1584 d    |             |                  |
| SN:100994                                          | HRS                                                                                    |           |          |          |                        |           |           |             |                  |
|                                                    | AFL                                                                                    |           |          |          |                        |           |           |             |                  |
| OverHaul Date:: 03-Aug-23                          |                                                                                        |           |          |          |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                                        |           |          |          |                        |           |           |             |                  |
| 351002                                             | COPILOT OXYGEN MASK                                                                    |           |          |          |                        |           |           |             | Component ATA:35 |
| PN:MC10-15-166                                     | MOS/MSC                                                                                | 26-Aug-24 | O/C      | TSO 0    |                        |           |           |             |                  |
| SN:111581                                          | HRS                                                                                    | 9529      |          | TSO 0    |                        |           |           |             |                  |
|                                                    | AFL                                                                                    | 7280      |          | TSO 0    |                        |           |           |             |                  |
| PROC. REF: AMM 35-10-01PROC. REF: AMM 35-10-01     |                                                                                        |           |          |          |                        |           |           |             |                  |
| 351002A                                            | OVERHAUL COPILOT OXYGEN MASK PER MANUFACTURER'S INSTRUCTIONS (IRN # L3510016/O3510006) |           |          |          |                        |           |           |             | Service ATA:35   |
| PN:MC10-15-166                                     | MOS                                                                                    | 26-Aug-24 | 72       |          | 28-Jun-30              |           | 1913 d    |             |                  |
| SN:111581                                          | HRS                                                                                    | 9529      |          |          |                        |           |           |             |                  |
|                                                    | AFL                                                                                    | 7280      |          |          |                        |           |           |             |                  |
| OverHaul Date:: 28-Jun-24                          |                                                                                        |           |          |          |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                                        |           |          |          |                        |           |           |             |                  |
| 351005                                             | PILOT CREW OXYGEN OUTLET                                                               |           |          |          |                        |           |           |             | Component ATA:35 |
| PN:DPB181-04                                       | MOS/MSC                                                                                | 24-May-07 | O/C      |          |                        |           |           |             |                  |
| SN:20/06                                           | HRS                                                                                    | 5477.2    |          |          |                        |           |           |             |                  |
|                                                    | AFL                                                                                    | 4173      |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 35-10-01PROC. REF: AMM 35-10-01     |                                                                                        |           |          |          |                        |           |           |             |                  |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C/W   (M)-Manual Due   U-User Task   Ex-Excluded Task

# Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9669.1
 AFL: 7372
 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                        | Unit                                      | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A / C | Max Limit | Remaining | Disposition | Warranty         |
|------------------------------------------------|-------------------------------------------|-----------|----------|----------|--------------------------|-----------|-----------|-------------|------------------|
| ATA 35 - OXYGEN                                |                                           |           |          |          |                          |           |           |             |                  |
| 351006                                         | COPILOT CREW-OXYGEN OUTLET                |           |          |          |                          |           |           |             | Component ATA:35 |
| PN:PN                                          | MOS/MSC                                   | 09-Mar-01 | O/C      | TSN 0    |                          |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                       | 0         |          | TSN 0    |                          |           |           |             |                  |
|                                                | AFL                                       | 0         |          | TSN 0    |                          |           |           |             |                  |
| PROC. REF: AMM 35-10-01PROC. REF: AMM 35-10-01 |                                           |           |          |          |                          |           |           |             |                  |
| 352002                                         | ALTITUDE COMPENSATING REGULATOR           |           |          |          |                          |           |           |             | Component ATA:35 |
| PN:PN                                          | MOS/MSC                                   | 09-Mar-01 | O/C      | TSN 0    |                          |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                       | 0         |          | TSN 0    |                          |           |           |             |                  |
|                                                | AFL                                       | 0         |          | TSN 0    |                          |           |           |             |                  |
| PROC. REF: AMM 35-20-06PROC. REF: AMM 35-20-06 |                                           |           |          |          |                          |           |           |             |                  |
| 352005-1 <sup>U</sup>                          | LEFT NO. 1 PASSENGER OXYGEN ASSEMBLY MASK |           |          |          |                          |           |           |             | Component ATA:35 |
| PN:PN                                          | MOS/MSC                                   | 09-Mar-01 | O/C      | TSN 0    |                          |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                       | 0         |          | TSN 0    |                          |           |           |             |                  |
|                                                | AFL                                       | 0         |          | TSN 0    |                          |           |           |             |                  |
| 352005-10 <sup>U</sup>                         | RIGHT NO.5 PASSENGER OXYGEN ASSEMBLY MASK |           |          |          |                          |           |           |             | Component ATA:35 |
| PN:PN                                          | MOS/MSC                                   | 09-Mar-01 | O/C      | TSN 0    |                          |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                       | 0         |          | TSN 0    |                          |           |           |             |                  |
|                                                | AFL                                       | 0         |          | TSN 0    |                          |           |           |             |                  |
| 352005-11 <sup>U</sup>                         | LAVATORY PASSENGER OXYGEN ASSEMBLY MASK   |           |          |          |                          |           |           |             | Component ATA:35 |
| PN:PN                                          | MOS/MSC                                   | 09-Mar-01 | O/C      | TSN 0    |                          |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                       | 0         |          | TSN 0    |                          |           |           |             |                  |
|                                                | AFL                                       | 0         |          | TSN 0    |                          |           |           |             |                  |
| 352005-12 <sup>U</sup>                         | LAVATORY PASSENGER OXYGEN ASSEMBLY MASK   |           |          |          |                          |           |           |             | Component ATA:35 |
| PN:PN                                          | MOS/MSC                                   | 09-Mar-01 | O/C      | TSN 0    |                          |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                       | 0         |          | TSN 0    |                          |           |           |             |                  |
|                                                | AFL                                       | 0         |          | TSN 0    |                          |           |           |             |                  |

?-Insufficient Information    S-Suppressed Requirement    \*-Estimated Due(New Requirement)    (EFF)-Effective C/W    (M)-Manual Due    U-User Task    Ex-Excluded Task

# Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9669.1
 AFL: 7372
 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN               | Unit    | C/W                                        | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|-----------------------|---------|--------------------------------------------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 35 - OXYGEN       |         |                                            |          |          |                        |           |           |             |                  |
| 352005-2 <sup>U</sup> |         | RIGHT NO. 1 PASSENGER OXYGEN ASSEMBLY MASK |          |          |                        |           |           |             | Component ATA:35 |
| PN:PN                 | MOS/MSC | 09-Mar-01                                  | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN            | HRS     | 0                                          |          | TSN 0    |                        |           |           |             |                  |
|                       | AFL     | 0                                          |          | TSN 0    |                        |           |           |             |                  |
|                       |         |                                            |          |          |                        |           |           |             |                  |
| 352005-3 <sup>U</sup> |         | LEFT NO. 2 PASSENGER OXYGEN ASSEMBLY MASK  |          |          |                        |           |           |             | Component ATA:35 |
| PN:PN                 | MOS/MSC | 09-Mar-01                                  | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN            | HRS     | 0                                          |          | TSN 0    |                        |           |           |             |                  |
|                       | AFL     | 0                                          |          | TSN 0    |                        |           |           |             |                  |
|                       |         |                                            |          |          |                        |           |           |             |                  |
| 352005-4 <sup>U</sup> |         | RIGHT NO. 2 PASSENGER OXYGEN ASSEMBLY MASK |          |          |                        |           |           |             | Component ATA:35 |
| PN:PN                 | MOS/MSC | 09-Mar-01                                  | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN            | HRS     | 0                                          |          | TSN 0    |                        |           |           |             |                  |
|                       | AFL     | 0                                          |          | TSN 0    |                        |           |           |             |                  |
|                       |         |                                            |          |          |                        |           |           |             |                  |
| 352005-5 <sup>U</sup> |         | LEFT NO. 3 PASSENGER OXYGEN ASSEMBLY MASK  |          |          |                        |           |           |             | Component ATA:35 |
| PN:PN                 | MOS/MSC | 09-Mar-01                                  | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN            | HRS     | 0                                          |          | TSN 0    |                        |           |           |             |                  |
|                       | AFL     | 0                                          |          | TSN 0    |                        |           |           |             |                  |
|                       |         |                                            |          |          |                        |           |           |             |                  |
| 352005-6 <sup>U</sup> |         | RIGHT NO.3 PASSENGER OXYGEN ASSEMBLY MASK  |          |          |                        |           |           |             | Component ATA:35 |
| PN:PN                 | MOS/MSC | 09-Mar-01                                  | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN            | HRS     | 0                                          |          | TSN 0    |                        |           |           |             |                  |
|                       | AFL     | 0                                          |          | TSN 0    |                        |           |           |             |                  |
|                       |         |                                            |          |          |                        |           |           |             |                  |
| 352005-7 <sup>U</sup> |         | LEFT NO. 4 PASSENGER OXYGEN ASSEMBLY MASK  |          |          |                        |           |           |             | Component ATA:35 |
| PN:PN                 | MOS/MSC | 09-Mar-01                                  | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN            | HRS     | 0                                          |          | TSN 0    |                        |           |           |             |                  |
|                       | AFL     | 0                                          |          | TSN 0    |                        |           |           |             |                  |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C/W   (M)-Manual Due   U-User Task   Ex-Excluded Task



Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN               | Unit    | C/W                                                         | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|-----------------------|---------|-------------------------------------------------------------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 35 - OXYGEN       |         |                                                             |          |          |                        |           |           |             |          |
| 352005-8 <sup>U</sup> |         | RIGHT NO. 4 PASSENGER OXYGEN ASSEMBLY MASK                  |          |          |                        |           |           | Component   | ATA:35   |
| PN:PN                 | MOS/MSC | 09-Mar-01                                                   | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN            | HRS     | 0                                                           |          | TSN 0    |                        |           |           |             |          |
|                       | AFL     | 0                                                           |          | TSN 0    |                        |           |           |             |          |
|                       |         |                                                             |          |          |                        |           |           |             |          |
| 352005-9 <sup>U</sup> |         | LEFT NO.5 PASSENGER OXYGEN ASSEMBLY MASK                    |          |          |                        |           |           | Component   | ATA:35   |
| PN:PN                 | MOS/MSC | 09-Mar-01                                                   | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN            | HRS     | 0                                                           |          | TSN 0    |                        |           |           |             |          |
|                       | AFL     | 0                                                           |          | TSN 0    |                        |           |           |             |          |
|                       |         |                                                             |          |          |                        |           |           |             |          |
| 352007-1 <sup>U</sup> |         | PASSENGER (#1 LEFT AND RIGHT) DUAL OXYGEN MASK BOX ASSEMBLY |          |          |                        |           |           | Component   | ATA:35   |
| PN:PN                 | MOS/MSC | 09-Mar-01                                                   | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN            | HRS     | 0                                                           |          | TSN 0    |                        |           |           |             |          |
|                       | AFL     | 0                                                           |          | TSN 0    |                        |           |           |             |          |
|                       |         |                                                             |          |          |                        |           |           |             |          |
| 352007-2 <sup>U</sup> |         | PASSENGER (#2 LEFT AND RIGHT) DUAL OXYGEN MASK BOX ASSEMBLY |          |          |                        |           |           | Component   | ATA:35   |
| PN:PN                 | MOS/MSC | 09-Mar-01                                                   | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN            | HRS     | 0                                                           |          | TSN 0    |                        |           |           |             |          |
|                       | AFL     | 0                                                           |          | TSN 0    |                        |           |           |             |          |
|                       |         |                                                             |          |          |                        |           |           |             |          |
| 352007-3 <sup>U</sup> |         | PASSENGER (#3 LEFT AND RIGHT) DUAL OXYGEN MASK BOX ASSEMBLY |          |          |                        |           |           | Component   | ATA:35   |
| PN:PN                 | MOS/MSC | 09-Mar-01                                                   | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN            | HRS     | 0                                                           |          | TSN 0    |                        |           |           |             |          |
|                       | AFL     | 0                                                           |          | TSN 0    |                        |           |           |             |          |
|                       |         |                                                             |          |          |                        |           |           |             |          |
| 352007-4 <sup>U</sup> |         | PASSENGER (#4 LEFT AND RIGHT) DUAL OXYGEN MASK BOX ASSEMBLY |          |          |                        |           |           | Component   | ATA:35   |
| PN:PN                 | MOS/MSC | 09-Mar-01                                                   | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN            | HRS     | 0                                                           |          | TSN 0    |                        |           |           |             |          |
|                       | AFL     | 0                                                           |          | TSN 0    |                        |           |           |             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

| PN & SN                                        | Unit    | C / W                                                       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|------------------------------------------------|---------|-------------------------------------------------------------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 35 - OXYGEN                                |         |                                                             |          |          |                        |           |           |             |          |
| 352007-5 <sup>U</sup>                          |         | PASSENGER (#5 LEFT AND RIGHT) DUAL OXYGEN MASK BOX ASSEMBLY |          |          |                        |           |           | Component   | ATA:35   |
| PN:PN                                          | MOS/MSC | 09-Mar-01                                                   | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS     | 0                                                           |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL     | 0                                                           |          | TSN 0    |                        |           |           |             |          |
|                                                |         |                                                             |          |          |                        |           |           |             |          |
| 352007-6 <sup>U</sup>                          |         | PASSENGER (#6 LEFT AND RIGHT) DUAL OXYGEN MASK BOX ASSEMBLY |          |          |                        |           |           | Component   | ATA:35   |
| PN:PN                                          | MOS/MSC | 09-Mar-01                                                   | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS     | 0                                                           |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL     | 0                                                           |          | TSN 0    |                        |           |           |             |          |
|                                                |         |                                                             |          |          |                        |           |           |             |          |
| 352011                                         |         | OXYGEN CONTROL VALVE                                        |          |          |                        |           |           | Component   | ATA:35   |
| PN:PN                                          | MOS/MSC | 09-Mar-01                                                   | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS     | 0                                                           |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL     | 0                                                           |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 35-20-01PROC. REF: AMM 35-20-01 |         |                                                             |          |          |                        |           |           |             |          |
|                                                |         |                                                             |          |          |                        |           |           |             |          |
| 352025 <sup>U</sup>                            |         | OXYGEN CYLINDER REGULATOR                                   |          |          |                        |           |           | Component   | ATA:35   |
| PN:806370-07                                   | MOS/MSC | 28-Aug-23                                                   | O/C      | TSO 0    |                        |           |           |             |          |
| SN:C10040171                                   | HRS     | 9307.4                                                      |          | TSO 0    |                        |           |           |             |          |
|                                                | AFL     | 7125                                                        |          | TSO 0    |                        |           |           |             |          |
|                                                |         |                                                             |          |          |                        |           |           |             |          |
| 353001                                         |         | PORTABLE OXYGEN CYLINDER                                    |          |          |                        |           |           | Component   | ATA:35   |
| PN:PN                                          | MOS/MSC |                                                             | O/C      |          |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS     |                                                             |          |          |                        |           |           |             |          |
|                                                | AFL     |                                                             |          |          |                        |           |           |             |          |
| PROC. REF: AMM 35-00-01PROC. REF: AMM 35-00-01 |         |                                                             |          |          |                        |           |           |             |          |
|                                                |         |                                                             |          |          |                        |           |           |             |          |
| 355111                                         |         | OXYGEN PRESSURE INDICATOR                                   |          |          |                        |           |           | Component   | ATA:35   |
| PN:PN                                          | MOS/MSC | 09-Mar-01                                                   | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS     | 0                                                           |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL     | 0                                                           |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 35-00-05PROC. REF: AMM 35-00-05 |         |                                                             |          |          |                        |           |           |             |          |

?-Insufficient Information
 S-Suppressed Requirement
 \*-Estimated Due(New Requirement)
 (EFF)-Effective C/W
 (M)-Manual Due
 U-User Task
 Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                            | Unit                                                                                                                                                                                                                                                                                                | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 35 - OXYGEN                                    |                                                                                                                                                                                                                                                                                                     |           |          |          |                        |           |           |             |          |
| 5-19-00-K3500021                                   | ** OXYGEN SYSTEM LOW PRESSURE SUPPLY HOSES - PERFORM OPERATIONAL CHECK. ENSURE THAT HOSES ARE FREE OF OBSTRUCTIONS.                                                                                                                                                                                 |           |          |          |                        |           |           | Service     | ATA:35   |
|                                                    | MOS/MSC                                                                                                                                                                                                                                                                                             | 09-Mar-01 | N/A      |          |                        |           |           |             |          |
|                                                    | HRS                                                                                                                                                                                                                                                                                                 | 0         |          |          |                        |           |           |             |          |
|                                                    | AFL                                                                                                                                                                                                                                                                                                 | 0         |          |          |                        |           |           |             |          |
| PROC. REF: AMM 35-00-00PROC. REF: AMM 35-00-00     |                                                                                                                                                                                                                                                                                                     |           |          |          |                        |           |           |             |          |
| 5-19-00-N3510013                                   | PERFORM ** PERIODIC CHECK OF OXYGEN CYLINDER AND REMOTE OXYGEN FILL VALVES (IRN N3510013)                                                                                                                                                                                                           |           |          |          |                        |           |           | Service     | ATA:35   |
|                                                    | MOS                                                                                                                                                                                                                                                                                                 | 30-Mar-21 |          |          |                        |           |           | INSPECT     |          |
|                                                    | HRS                                                                                                                                                                                                                                                                                                 | 8414.4    | 1500     |          | 9914.4                 |           | 245.3     |             |          |
|                                                    | AFL                                                                                                                                                                                                                                                                                                 | 6463      |          |          |                        |           |           |             |          |
| PROC. REF: AMM 35-00-01PROC. REF: AMM 35-00-01     |                                                                                                                                                                                                                                                                                                     |           |          |          |                        |           |           |             |          |
| 5-19-00-N3510019                                   | PERFORM ** PERIODIC CHECK OF THE OXYGEN CYLINDER AND REMOTE FILL VALVES. EFFECTIVE ON AIRCRAFT EQUIPPED WITH INCREASED CAPACITY OXYGEN SYSTEM. (IRN N3510019)                                                                                                                                       |           |          |          |                        |           |           | Service     | ATA:35   |
|                                                    | MOS/MSC                                                                                                                                                                                                                                                                                             |           | N/A      |          |                        |           |           |             |          |
|                                                    | HRS                                                                                                                                                                                                                                                                                                 |           |          |          |                        |           |           |             |          |
|                                                    | AFL                                                                                                                                                                                                                                                                                                 |           |          |          |                        |           |           |             |          |
| PROC. REF: AMM 35-00-01PROC. REF: AMM 35-00-01     |                                                                                                                                                                                                                                                                                                     |           |          |          |                        |           |           |             |          |
| 5-19-00-Q3510018 U                                 | PERFORM OXYGEN CYLINDER (COMPOSITE) AND LOW PRESSURE RELIEF VALVE - PERFORM ICC HYDROSTATIC TEST ON CYLINDER (PER DOT EXEMPTION E8162) AND FUNCTIONALY TEST OXYGEN CYLINDER LOW PRESSURE RELIEF VALVE. EFFECTIVE ON AIRCRAFT EQUIPPED WITH INCREASED CAPACITY OXYGEN SYSTEM. ZONE 230. IRN Q3510018 |           |          |          |                        |           |           | Service     | ATA:35   |
|                                                    | MOS/MSC                                                                                                                                                                                                                                                                                             |           | N/A      |          |                        |           |           |             |          |
|                                                    | HRS                                                                                                                                                                                                                                                                                                 |           |          |          |                        |           |           |             |          |
|                                                    | AFL                                                                                                                                                                                                                                                                                                 |           |          |          |                        |           |           |             |          |
| 5-19-00-Q3510022                                   | OXYGEN CYLINDER REGULATOR - OVERHAUL                                                                                                                                                                                                                                                                |           |          |          |                        |           |           | Service     | ATA:35   |
|                                                    | MOS                                                                                                                                                                                                                                                                                                 | 22-Jun-23 | 60       |          | 22-Jun-28              |           | 1177 d    |             |          |
|                                                    | HRS                                                                                                                                                                                                                                                                                                 | 9258.5    | 5000     |          | 14258.5                |           | 4589.4    |             |          |
|                                                    | AFL                                                                                                                                                                                                                                                                                                 | 7100      |          |          |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                                                                                                                                                                                                                                                     |           |          |          |                        |           |           |             |          |
| 5-19-00-Q3510023                                   | OXYGEN CYLINDER REGULATOR - OVERHAUL (EFFECTIVE ON AIRCRAFT EQUIPPED WITH INCREASED CAPACITY OXYGEN SYSTEM)                                                                                                                                                                                         |           |          |          |                        |           |           | Service     | ATA:35   |
|                                                    | MOS/MSC                                                                                                                                                                                                                                                                                             |           | N/A      |          |                        |           |           |             |          |
|                                                    | HRS                                                                                                                                                                                                                                                                                                 |           |          |          |                        |           |           |             |          |
|                                                    | AFL                                                                                                                                                                                                                                                                                                 |           |          |          |                        |           |           |             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN | Unit | C / W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|---------|------|-------|----------|----------|------------------------|-----------|-----------|-------------|----------|
|---------|------|-------|----------|----------|------------------------|-----------|-----------|-------------|----------|

ATA 35 - OXYGEN

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

|          |     |                                                                                 |     |  |  |  |  |               |        |
|----------|-----|---------------------------------------------------------------------------------|-----|--|--|--|--|---------------|--------|
| O3510003 | S   | ** CABIN LOW PRESSURE OXYGEN DISTRIBUTION FLEX HOSES - PERFORM FUNCTIONAL TEST. |     |  |  |  |  | Service       | ATA:35 |
|          | MOS | 02-Aug-24                                                                       | 24  |  |  |  |  | AIRWORTHINESS |        |
|          | HRS | 9525.7                                                                          | 600 |  |  |  |  |               |        |
|          | AFL | 7276                                                                            |     |  |  |  |  |               |        |

PROC. REF: AMM 35-20-00PROC. REF: AMM 35-20-00

PKG:7

|          |     |                                              |     |  |  |  |  |               |        |
|----------|-----|----------------------------------------------|-----|--|--|--|--|---------------|--------|
| W3510002 | S   | ** OXYGEN SYSTEM - PERFORM OPERATIONAL CHECK |     |  |  |  |  | Service       | ATA:35 |
|          | MOS | 02-Aug-24                                    | 24  |  |  |  |  | AIRWORTHINESS |        |
|          | HRS | 9525.7                                       | 600 |  |  |  |  |               |        |
|          | AFL | 7276                                         |     |  |  |  |  |               |        |

PROC. REF: AMM 35-00-00PROC. REF: AMM 35-00-00

PKG:7

|          |     |                                                                                                                                              |     |  |  |  |  |         |        |
|----------|-----|----------------------------------------------------------------------------------------------------------------------------------------------|-----|--|--|--|--|---------|--------|
| Y3510001 | S   | CREW SEAT OXYGEN HOSES - PERFORM VISUAL INSPECTION. PAY PARTICULAR ATTENTION TO AREA WHERE OXYGEN HOSES ENTER CREW SEATS ABOVE COCKPIT FLOOR |     |  |  |  |  | Service | ATA:35 |
|          | MOS | 02-Aug-24                                                                                                                                    | 12  |  |  |  |  |         |        |
|          | HRS | 9525.7                                                                                                                                       | 300 |  |  |  |  |         |        |
|          | AFL | 7276                                                                                                                                         |     |  |  |  |  |         |        |

PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00

PKG:1

|          |     |                                                                                                                                                                                       |     |  |  |  |  |         |        |
|----------|-----|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|--|--|--|--|---------|--------|
| Y3510017 | S   | OXYGEN CYLINDER INSTALLATION - PERFORM VISUAL INSPECTION. CHECK PLUMBING FOR ROUTING, SECURITY,AND CONDITION. (EFFECTIVE ON AIRCRAFT EQUIPPED WITH INCREASED CAPACITY OXYGEN SYSTEM.) |     |  |  |  |  | Service | ATA:35 |
|          | MOS | 02-Aug-24                                                                                                                                                                             | 24  |  |  |  |  |         |        |
|          | HRS | 9525.7                                                                                                                                                                                | 600 |  |  |  |  |         |        |
|          | AFL | 7276                                                                                                                                                                                  |     |  |  |  |  |         |        |

PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00

PKG:7

ATA 36 - PNEUMATIC

|            |                                              |           |     |       |  |  |  |           |        |
|------------|----------------------------------------------|-----------|-----|-------|--|--|--|-----------|--------|
| 361001     | LEFT ASSEMBLY, HP TAILCONE OUTBOARD MANIFOLD |           |     |       |  |  |  | Component | ATA:36 |
| PN:PN      | MOS/MSC                                      | 09-Mar-01 | O/C | TSN 0 |  |  |  |           |        |
| SN:UNKNOWN | HRS                                          | 0         |     | TSN 0 |  |  |  |           |        |
|            | AFL                                          | 0         |     | TSN 0 |  |  |  |           |        |

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9669.1
 AFL: 7372
 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                        | Unit                                       | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|------------------------------------------------|--------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 36 - PNEUMATIC                             |                                            |           |          |          |                        |           |           |             |                  |
| 361002                                         | LEFT ASSEMBLY, ANTI-ICE OUTBOARD MANIFOLD  |           |          |          |                        |           |           |             | Component ATA:36 |
| PN:PN                                          | MOS/MSC                                    | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                        | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                        | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 30-10-07PROC. REF: AMM 30-10-07 |                                            |           |          |          |                        |           |           |             |                  |
| 361004                                         | LEFT INBOARD HPBA MANIFOLD ASSEMBLY        |           |          |          |                        |           |           |             | Component ATA:36 |
| PN:PN                                          | MOS/MSC                                    | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                        | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                        | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 36-10-07PROC. REF: AMM 36-10-07 |                                            |           |          |          |                        |           |           |             |                  |
| 361005                                         | RIGHT INBOARD HPBA MANIFOLD ASSEMBLY       |           |          |          |                        |           |           |             | Component ATA:36 |
| PN:PN                                          | MOS/MSC                                    | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                        | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                        | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 36-10-07PROC. REF: AMM 36-10-07 |                                            |           |          |          |                        |           |           |             |                  |
| 361016                                         | RIGHT ASSEMBLY, ANTI-ICE OUTBOARD MANIFOLD |           |          |          |                        |           |           |             | Component ATA:36 |
| PN:PN                                          | MOS/MSC                                    | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                        | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                        | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 30-10-07PROC. REF: AMM 30-10-07 |                                            |           |          |          |                        |           |           |             |                  |
| 361020                                         | LEFT HP OVER-TEMP SWITCH                   |           |          |          |                        |           |           |             | Component ATA:36 |
| PN:PN                                          | MOS/MSC                                    | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                        | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                        | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 36-20-03PROC. REF: AMM 36-20-03 |                                            |           |          |          |                        |           |           |             |                  |
| 361021                                         | RIGHT HP OVER-TEMP SWITCH                  |           |          |          |                        |           |           |             | Component ATA:36 |
| PN:641179-4                                    | MOS/MSC                                    | 06-Jun-05 | O/C      |          |                        |           |           |             |                  |
| SN:0766                                        | HRS                                        | 3654.87   |          |          |                        |           |           |             |                  |
|                                                | AFL                                        | 2759      |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 36-20-03PROC. REF: AMM 36-20-03 |                                            |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                        | Unit                                             | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|------------------------------------------------|--------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 36 - PNEUMATIC                             |                                                  |           |          |          |                        |           |           |             |                  |
| 361031                                         | ECS CONTROLLER                                   |           |          |          |                        |           |           |             | Component ATA:36 |
| PN:PN                                          | MOS/MSC                                          | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                              | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                              | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 36-10-01PROC. REF: AMM 36-10-01 |                                                  |           |          |          |                        |           |           |             |                  |
| 361040                                         | VALVE, APU BLEED AIR CHECK REPLACE               |           |          |          |                        |           |           |             | Component ATA:36 |
| PN:PN                                          | MOS/MSC                                          | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                              | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                              | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 36-10-09PROC. REF: AMM 36-10-09 |                                                  |           |          |          |                        |           |           |             |                  |
| 361050                                         | LOAD CONTROL (SHUTOFF (L5003) VALVE              |           |          |          |                        |           |           |             | Component ATA:36 |
| PN:PN                                          | MOS/MSC                                          | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                              | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                              | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 36-10-10PROC. REF: AMM 36-10-10 |                                                  |           |          |          |                        |           |           |             |                  |
| 361053                                         | NO. 1 ECS SHUTOFF (L37) VALVE                    |           |          |          |                        |           |           |             | Component ATA:36 |
| PN:PN                                          | MOS/MSC                                          | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                              | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                              | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 36-10-03PROC. REF: AMM 36-10-03 |                                                  |           |          |          |                        |           |           |             |                  |
| 361054                                         | NO. 2 ECS SHUTOFF (L38) VALVE                    |           |          |          |                        |           |           |             | Component ATA:36 |
| PN:PN                                          | MOS/MSC                                          | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                              | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                              | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 36-10-03PROC. REF: AMM 36-10-03 |                                                  |           |          |          |                        |           |           |             |                  |
| 361065                                         | LEFT TAILCONE HIGH PRESSURE SHUT-OFF (L39) VALVE |           |          |          |                        |           |           |             | Component ATA:36 |
| PN:3291216-2                                   | MOS/MSC                                          | 09-Jun-05 | O/C      |          |                        |           |           |             |                  |
| SN:736                                         | HRS                                              | 3666.35   |          |          |                        |           |           |             |                  |
|                                                | AFL                                              | 2768      |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 36-10-02PROC. REF: AMM 36-10-02 |                                                  |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR    Serial: 45-145    RegNo: N942FK    HRS: 9669.1    AFL: 7372    As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                            | Unit                                                  | C / W     | Interval | TSX / Adj. | Next Due (ENG / APU) A / C | Max Limit | Remaining | Disposition | Warranty            |
|----------------------------------------------------|-------------------------------------------------------|-----------|----------|------------|----------------------------|-----------|-----------|-------------|---------------------|
| ATA 36 - PNEUMATIC                                 |                                                       |           |          |            |                            |           |           |             |                     |
| 361066                                             | RIGHT TAILCONE HIGH PRESSURE SHUT-OFF (L40) VALVE     |           |          |            |                            |           |           |             | Component    ATA:36 |
| PN:3291216-2                                       | MOS/MSC                                               | 09-Jun-05 | O/C      |            |                            |           |           |             |                     |
| SN:426                                             | HRS                                                   | 3666.35   |          |            |                            |           |           |             |                     |
|                                                    | AFL                                                   | 2768      |          |            |                            |           |           |             |                     |
| PROC. REF: AMM 36-10-02PROC. REF: AMM 36-10-02     |                                                       |           |          |            |                            |           |           |             |                     |
| 361120                                             | NO. 1 PRESSURE (S79) SWITCH                           |           |          |            |                            |           |           |             | Component    ATA:36 |
| PN:PN                                              | MOS/MSC                                               | 09-Mar-01 | O/C      | TSN 0      |                            |           |           |             |                     |
| SN:UNKNOWN                                         | HRS                                                   | 0         |          | TSN 0      |                            |           |           |             |                     |
|                                                    | AFL                                                   | 0         |          | TSN 0      |                            |           |           |             |                     |
| PROC. REF: AMM 36-10-06PROC. REF: AMM 36-10-06     |                                                       |           |          |            |                            |           |           |             |                     |
| 361121                                             | NO. 2 PRESSURE (S88) SWITCH                           |           |          |            |                            |           |           |             | Component    ATA:36 |
| PN:PN                                              | MOS/MSC                                               | 09-Mar-01 | O/C      | TSN 0      |                            |           |           |             |                     |
| SN:UNKNOWN                                         | HRS                                                   | 0         |          | TSN 0      |                            |           |           |             |                     |
|                                                    | AFL                                                   | 0         |          | TSN 0      |                            |           |           |             |                     |
| PROC. REF: AMM 36-10-06PROC. REF: AMM 36-10-06     |                                                       |           |          |            |                            |           |           |             |                     |
| 361125                                             | LEFT PYLON LOW PRESSURE TEMPERATURE SENSOR            |           |          |            |                            |           |           |             | Component    ATA:36 |
| PN:PN                                              | MOS/MSC                                               | 09-Mar-01 | O/C      | TSN 0      |                            |           |           |             |                     |
| SN:UNKNOWN                                         | HRS                                                   | 0         |          | TSN 0      |                            |           |           |             |                     |
|                                                    | AFL                                                   | 0         |          | TSN 0      |                            |           |           |             |                     |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                       |           |          |            |                            |           |           |             |                     |
| 361126                                             | RIGHT PYLON LOW PRESSURE TEMPERATURE SENSOR           |           |          |            |                            |           |           |             | Component    ATA:36 |
| PN:PN                                              | MOS/MSC                                               | 09-Mar-01 | O/C      | TSN 0      |                            |           |           |             |                     |
| SN:UNKNOWN                                         | HRS                                                   | 0         |          | TSN 0      |                            |           |           |             |                     |
|                                                    | AFL                                                   | 0         |          | TSN 0      |                            |           |           |             |                     |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                       |           |          |            |                            |           |           |             |                     |
| 361127                                             | LEFT TAILCONE LOW PRESSURE (2.0 DIAMETER) CHECK VALVE |           |          |            |                            |           |           |             | Component    ATA:36 |
| PN:PN                                              | MOS/MSC                                               | 09-Mar-01 | O/C      | TSN 0      |                            |           |           |             |                     |
| SN:UNKNOWN                                         | HRS                                                   | 0         |          | TSN 0      |                            |           |           |             |                     |
|                                                    | AFL                                                   | 0         |          | TSN 0      |                            |           |           |             |                     |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                       |           |          |            |                            |           |           |             |                     |

?-Insufficient Information    S-Suppressed Requirement    \*-Estimated Due(New Requirement)    (EFF)-Effective C / W    (M)-Manual Due    U-User Task    Ex-Excluded Task

# Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9669.1
 AFL: 7372
 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                            | Unit                                                                                            | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------|-------------------------------------------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 36 - PNEUMATIC                                 |                                                                                                 |           |          |          |                        |           |           |             |                  |
| 361128                                             | RIGHT TAILCONE LOW PRESSURE (2.0 DIAMETER) CHECK VALVE                                          |           |          |          |                        |           |           |             | Component ATA:36 |
| PN:PN                                              | MOS/MSC                                                                                         | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                                                                             | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                                                                             | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                                                 |           |          |          |                        |           |           |             |                  |
| 361215                                             | ASSEMBLY, HP LEFT NACELLE BLEED AIR MANIFOLD                                                    |           |          |          |                        |           |           |             | Component ATA:36 |
| PN:PN                                              | MOS/MSC                                                                                         | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                                                                             | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                                                                             | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 36-10-07PROC. REF: AMM 36-10-07     |                                                                                                 |           |          |          |                        |           |           |             |                  |
| 361215A                                            | BORESCOPE ASSEMBLY, HP LEFT NACELLE BLEED AIR MANIFOLD BRACKET                                  |           |          |          |                        |           |           |             | Service ATA:36   |
| PN:PN                                              | MOS/MSC                                                                                         | 09-Mar-01 | O/C      |          |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                                                                             | 0         |          |          |                        |           |           |             |                  |
|                                                    | AFL                                                                                             | 0         |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 36-10-07PROC. REF: AMM 36-10-07     |                                                                                                 |           |          |          |                        |           |           |             |                  |
| 361216                                             | ASSEMBLY, HP RIGHT NACELLE BLEED AIR MANIFOLD                                                   |           |          |          |                        |           |           |             | Component ATA:36 |
| PN:PN                                              | MOS/MSC                                                                                         | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                                                                             | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                                                                             | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 36-10-07PROC. REF: AMM 36-10-07     |                                                                                                 |           |          |          |                        |           |           |             |                  |
| 361216A                                            | BORESCOPE ASSEMBLY, HP RIGHT NACELLE BLEED AIR MANIFOLD BRACKET                                 |           |          |          |                        |           |           |             | Service ATA:36   |
| PN:PN                                              | MOS/MSC                                                                                         | 09-Mar-01 | O/C      |          |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                                                                             | 0         |          |          |                        |           |           |             |                  |
|                                                    | AFL                                                                                             | 0         |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 36-10-07PROC. REF: AMM 36-10-07     |                                                                                                 |           |          |          |                        |           |           |             |                  |
| 361301                                             | APU SERVO AIR CHECK VALVE. EFFECTIVE ON CHECK VALVE S/N 001 THRU 1486. (IRN # K3610013) REPLACE |           |          |          |                        |           |           |             | Component ATA:36 |
| PN:PN                                              | MOS/MSC                                                                                         | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                                                                             | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                                                                             | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 36-15-02PROC. REF: AMM 36-15-02     |                                                                                                 |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 45XR    Serial: 45-145    RegNo: N942FK    HRS: 9669.1    AFL: 7372    As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                                              | Unit    | C / W     | Interval | TSX / Adj. | Next Due (ENG / APU) A / C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------------------------|---------|-----------|----------|------------|----------------------------|-----------|-----------|-------------|----------|
| ATA 36 - PNEUMATIC                                                   |         |           |          |            |                            |           |           |             |          |
| 361302      LEFT ENGINE SERVO AIR CHECK -    IRN K3610012 VALVE      |         |           |          |            |                            |           |           | Component   | ATA:36   |
| PN:6608295-3                                                         | MOS/MSC | 30-Apr-06 | O/C      |            |                            |           |           |             |          |
| SN:2360                                                              | HRS     | 4466.8    |          |            |                            |           |           |             |          |
|                                                                      | AFL     | 3408      |          |            |                            |           |           |             |          |
| PROC. REF: AMM 36-15-02PROC. REF: AMM 36-15-02                       |         |           |          |            |                            |           |           |             |          |
|                                                                      |         |           |          |            |                            |           |           |             |          |
| 361303      RIGHT ENGINE SERVO AIR CHECK -    IRN K3610012 VALVE     |         |           |          |            |                            |           |           | Component   | ATA:36   |
| PN:6608295-3                                                         | MOS/MSC | 30-Apr-06 | O/C      |            |                            |           |           |             |          |
| SN:2308                                                              | HRS     | 4466.8    |          |            |                            |           |           |             |          |
|                                                                      | AFL     | 3408      |          |            |                            |           |           |             |          |
| PROC. REF: AMM 36-15-02PROC. REF: AMM 36-15-02                       |         |           |          |            |                            |           |           |             |          |
|                                                                      |         |           |          |            |                            |           |           |             |          |
| 362005      LEFT FORWARD TAILCONE OVERHEAT THERMOSTAT (S145) SWITCH  |         |           |          |            |                            |           |           | Component   | ATA:36   |
| PN:PN                                                                | MOS/MSC | 09-Mar-01 | O/C      | TSN 0      |                            |           |           |             |          |
| SN:UNKNOWN                                                           | HRS     | 0         |          | TSN 0      |                            |           |           |             |          |
|                                                                      | AFL     | 0         |          | TSN 0      |                            |           |           |             |          |
| PROC. REF: AMM 36-20-02PROC. REF: AMM 36-20-02                       |         |           |          |            |                            |           |           |             |          |
|                                                                      |         |           |          |            |                            |           |           |             |          |
| 362006      RIGHT FORWARD TAILCONE OVERHEAT THERMOSTAT (S146) SWITCH |         |           |          |            |                            |           |           | Component   | ATA:36   |
| PN:PN                                                                | MOS/MSC | 09-Mar-01 | O/C      | TSN 0      |                            |           |           |             |          |
| SN:UNKNOWN                                                           | HRS     | 0         |          | TSN 0      |                            |           |           |             |          |
|                                                                      | AFL     | 0         |          | TSN 0      |                            |           |           |             |          |
| PROC. REF: AMM 36-20-02PROC. REF: AMM 36-20-02                       |         |           |          |            |                            |           |           |             |          |
|                                                                      |         |           |          |            |                            |           |           |             |          |
| 362007      LEFT AFT TAILCONE OVERHEAT THERMOSTAT (S147) SWITCH      |         |           |          |            |                            |           |           | Component   | ATA:36   |
| PN:PN                                                                | MOS/MSC | 09-Mar-01 | O/C      | TSN 0      |                            |           |           |             |          |
| SN:UNKNOWN                                                           | HRS     | 0         |          | TSN 0      |                            |           |           |             |          |
|                                                                      | AFL     | 0         |          | TSN 0      |                            |           |           |             |          |
| PROC. REF: AMM 36-20-02PROC. REF: AMM 36-20-02                       |         |           |          |            |                            |           |           |             |          |
|                                                                      |         |           |          |            |                            |           |           |             |          |
| 362008      RIGHT AFT TAILCONE OVERHEAT THERMOSTAT (S148) SWITCH     |         |           |          |            |                            |           |           | Component   | ATA:36   |
| PN:PN                                                                | MOS/MSC | 09-Mar-01 | O/C      | TSN 0      |                            |           |           |             |          |
| SN:UNKNOWN                                                           | HRS     | 0         |          | TSN 0      |                            |           |           |             |          |
|                                                                      | AFL     | 0         |          | TSN 0      |                            |           |           |             |          |
| PROC. REF: AMM 36-20-02PROC. REF: AMM 36-20-02                       |         |           |          |            |                            |           |           |             |          |
|                                                                      |         |           |          |            |                            |           |           |             |          |

?-Insufficient Information    S-Suppressed Requirement    \*-Estimated Due(New Requirement)    (EFF)-Effective C / W    (M)-Manual Due    U-User Task    Ex-Excluded Task

# Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 9669.1
AFL: 7372
As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                        | Unit                                                                                                                                                                                                                                                           | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty |
|------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|---------------|----------|
| ATA 36 - PNEUMATIC                             |                                                                                                                                                                                                                                                                |           |          |          |                        |           |           |               |          |
| 5-19-00-D3610002                               | BORESCOPE INSPECTION HP BLEED AIR MANIFOLD ASSEMBLY ATTACH BRACKET ASSEMBLY FOR CRACKS AT WELD.(IRN D3610002)                                                                                                                                                  |           |          |          |                        |           |           | Service       | ATA:36   |
|                                                | MOS/MSC                                                                                                                                                                                                                                                        | 09-Mar-01 | N/A      |          |                        |           |           |               |          |
|                                                | HRS                                                                                                                                                                                                                                                            | 0         |          |          |                        |           |           |               |          |
|                                                | AFL                                                                                                                                                                                                                                                            | 0         |          |          |                        |           |           |               |          |
| PROC. REF: AMM 36-10-07PROC. REF: AMM 36-10-07 |                                                                                                                                                                                                                                                                |           |          |          |                        |           |           |               |          |
| 5-19-00-P3610048                               | PERFORM VISUAL INSPECTION OF HP BLEED MANIFOLD ASSEMBLY (REFER TO 36-10-07.) EFFECTIVE ON AIRCRAFT 45-037 AND SUBSEQUENT, AND PREVIOUS AIRCRAFT MODIFIED PER SB 45-36-2, "PNEUMATIC-REPLACEMENT OF HIGH PRESSURE AIR MANIFOLD ASSEMBLY". (ZONE ACCESS 410/420) |           |          |          |                        |           |           | Service       | ATA:36   |
|                                                | MOS/MSC                                                                                                                                                                                                                                                        | 12-Aug-15 | MPI      |          |                        |           |           |               |          |
|                                                | HRS                                                                                                                                                                                                                                                            | 7535.1    |          |          |                        |           |           |               |          |
|                                                | AFL                                                                                                                                                                                                                                                            | 5764      |          |          |                        |           |           |               |          |
| 5-19-01-K3610012                               | REPLACE ENGINE SERVO AIR CHECK VALVE (6608295-3). (ZONE/ACCESS 310HL, 310JL, 310QR, 310RR IRN # K3610012)                                                                                                                                                      |           |          |          |                        |           |           | Service       | ATA:36   |
|                                                | MOS/MSC                                                                                                                                                                                                                                                        | 30-Apr-06 | A/R      |          |                        |           |           |               |          |
|                                                | HRS                                                                                                                                                                                                                                                            | 4466.8    |          |          |                        |           |           |               |          |
|                                                | AFL                                                                                                                                                                                                                                                            | 3408      |          |          |                        |           |           |               |          |
| 5-19-01-K3610013                               | REPLACE APU SERVO CHECK VALVE (6608295-3). EFFECTIVE ON CHECK VALVE S/N 001 THRU 1486. (ZONE/ACCESS 310HL, 310JL, 310QR, 310RR IRN # K3610013)                                                                                                                 |           |          |          |                        |           |           | Service       | ATA:36   |
|                                                | MOS/MSC                                                                                                                                                                                                                                                        | 09-Mar-01 | N/A      |          |                        |           |           | NOT INSTALLED |          |
|                                                | HRS                                                                                                                                                                                                                                                            | 0         |          |          |                        |           |           |               |          |
|                                                | AFL                                                                                                                                                                                                                                                            | 0         |          |          |                        |           |           |               |          |
| A3610000                                       | ** BLEED AIR SYSTEM - PERFORM FUNCTIONAL TEST                                                                                                                                                                                                                  |           |          |          |                        |           |           | Service       | ATA:36   |
|                                                | MOS                                                                                                                                                                                                                                                            | 02-Aug-24 | 24       |          |                        |           |           | AIRWORTHINESS |          |
|                                                | HRS                                                                                                                                                                                                                                                            | 9525.7    | 600      |          |                        |           |           |               |          |
|                                                | AFL                                                                                                                                                                                                                                                            | 7276      |          |          |                        |           |           |               |          |
| PROC. REF: AMM 36-10-00PROC. REF: AMM 36-10-00 |                                                                                                                                                                                                                                                                |           |          |          |                        |           |           |               |          |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C/W   (M)-Manual Due   U-User Task   Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-202502-Apr-2025 02:58 PM

| PN & SN                                            | Unit                          | C/W                                                                                  | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty |
|----------------------------------------------------|-------------------------------|--------------------------------------------------------------------------------------|----------|----------|------------------------|-----------|-----------|---------------|----------|
| ATA 36 - PNEUMATIC                                 |                               |                                                                                      |          |          |                        |           |           |               |          |
| A3610001                                           | S                             | ** PYLON OVERHEAT THERMOSTAT AND ELECTRICAL SYSTEM - PERFORM FUNCTIONAL TEST         |          |          |                        |           |           | Service       | ATA:36   |
|                                                    | MOS                           | 02-Aug-24                                                                            | 24       |          |                        |           |           | AIRWORTHINESS |          |
|                                                    | HRS                           | 9525.7                                                                               | 600      |          |                        |           |           |               |          |
|                                                    | AFL                           | 7276                                                                                 |          |          |                        |           |           |               |          |
| PROC. REF: AMM 36-20-01PROC. REF: AMM 36-20-01     |                               |                                                                                      |          |          |                        |           |           |               | PKG:8    |
|                                                    |                               |                                                                                      |          |          |                        |           |           |               |          |
| Y3610061                                           | S                             | HIGH PRESSURE BLEED AIR SHUT-OFF VALVE IN-LINE FILTER - PERFORM CLEANING PROCEDURES. |          |          |                        |           |           | Service       | ATA:36   |
|                                                    | MOS                           | 02-Aug-24                                                                            | 24       |          |                        |           |           |               |          |
|                                                    | HRS                           | 9525.7                                                                               | 600      |          |                        |           |           |               |          |
|                                                    | AFL                           | 7276                                                                                 |          |          |                        |           |           |               |          |
| PROC. REF: AMM 36-10-02PROC. REF: AMM 36-10-02     |                               |                                                                                      |          |          |                        |           |           |               | PKG:8    |
|                                                    |                               |                                                                                      |          |          |                        |           |           |               |          |
| ATA 38 - WATER/WASTE                               |                               |                                                                                      |          |          |                        |           |           |               |          |
| 380001                                             | TOILET SERVICE PANEL          |                                                                                      |          |          |                        |           |           | Component     | ATA:38   |
| PN:9600-102                                        | MOS/MSC                       | 09-Apr-06                                                                            | O/C      |          |                        |           |           |               |          |
| SN:SP1116                                          | HRS                           |                                                                                      |          |          |                        |           |           |               |          |
|                                                    | AFL                           |                                                                                      |          |          |                        |           |           |               |          |
| PROC. REF: AMM 38-30-05PROC. REF: AMM 38-30-05     |                               |                                                                                      |          |          |                        |           |           |               |          |
|                                                    |                               |                                                                                      |          |          |                        |           |           |               |          |
| 381009                                             | TOILET HEATED DRAIN MAST ASSY |                                                                                      |          |          |                        |           |           | Component     | ATA:38   |
| PN:PN                                              | MOS/MSC                       | 09-Mar-01                                                                            | O/C      | TSN 0    |                        |           |           |               |          |
| SN:UNKNOWN                                         | HRS                           | 0                                                                                    |          | TSN 0    |                        |           |           |               |          |
|                                                    | AFL                           | 0                                                                                    |          | TSN 0    |                        |           |           |               |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                               |                                                                                      |          |          |                        |           |           |               |          |
|                                                    |                               |                                                                                      |          |          |                        |           |           |               |          |
| 383001                                             | TOILET                        |                                                                                      |          |          |                        |           |           | Component     | ATA:38   |
| PN:PN                                              | MOS/MSC                       | 09-Mar-01                                                                            | O/C      | TSN 0    |                        |           |           |               |          |
| SN:UNKNOWN                                         | HRS                           | 0                                                                                    |          | TSN 0    |                        |           |           |               |          |
|                                                    | AFL                           | 0                                                                                    |          | TSN 0    |                        |           |           |               |          |
| PROC. REF: AMM 38-30-01PROC. REF: AMM 38-30-01     |                               |                                                                                      |          |          |                        |           |           |               |          |
|                                                    |                               |                                                                                      |          |          |                        |           |           |               |          |
| 383002                                             | TOILET TIMER                  |                                                                                      |          |          |                        |           |           | Component     | ATA:38   |
| PN:PN                                              | MOS/MSC                       | 09-Mar-01                                                                            | O/C      | TSN 0    |                        |           |           |               |          |
| SN:UNKNOWN                                         | HRS                           | 0                                                                                    |          | TSN 0    |                        |           |           |               |          |
|                                                    | AFL                           | 0                                                                                    |          | TSN 0    |                        |           |           |               |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|---------|------|-----|----------|----------|------------------------|-----------|-----------|-------------|----------|
|---------|------|-----|----------|----------|------------------------|-----------|-----------|-------------|----------|

ATA 38 - WATER/WASTE

PROC. REF: AMM 38-30-02PROC. REF: AMM 38-30-02

|                                                    |                     |           |     |       |  |  |  |           |        |
|----------------------------------------------------|---------------------|-----------|-----|-------|--|--|--|-----------|--------|
| 383005                                             | WATER TANK ASSEMBLY |           |     |       |  |  |  | Component | ATA:38 |
| PN:PN                                              | MOS/MSC             | 09-Mar-01 | O/C | TSN 0 |  |  |  |           |        |
| SN:UNKNOWN                                         | HRS                 | 0         |     | TSN 0 |  |  |  |           |        |
|                                                    | AFL                 | 0         |     | TSN 0 |  |  |  |           |        |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                     |           |     |       |  |  |  |           |        |

|                                                    |                              |           |     |       |  |  |  |           |        |
|----------------------------------------------------|------------------------------|-----------|-----|-------|--|--|--|-----------|--------|
| 383011                                             | LAVATORY SINK SHUT OFF VALVE |           |     |       |  |  |  | Component | ATA:38 |
| PN:PN                                              | MOS/MSC                      | 09-Mar-01 | O/C | TSN 0 |  |  |  |           |        |
| SN:UNKNOWN                                         | HRS                          | 0         |     | TSN 0 |  |  |  |           |        |
|                                                    | AFL                          | 0         |     | TSN 0 |  |  |  |           |        |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                              |           |     |       |  |  |  |           |        |

|                                                    |             |           |     |  |  |  |  |           |        |
|----------------------------------------------------|-------------|-----------|-----|--|--|--|--|-----------|--------|
| 384025                                             | TOILET PUMP |           |     |  |  |  |  | Component | ATA:38 |
| PN:5250-11A                                        | MOS/MSC     | 12-Aug-15 | O/C |  |  |  |  |           |        |
| SN:P8851                                           | HRS         | 7535.1    |     |  |  |  |  |           |        |
|                                                    | AFL         | 5764      |     |  |  |  |  |           |        |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |             |           |     |  |  |  |  |           |        |

|                                                    |                  |           |     |       |  |  |  |           |        |
|----------------------------------------------------|------------------|-----------|-----|-------|--|--|--|-----------|--------|
| 384051                                             | TOILET MACERATOR |           |     |       |  |  |  | Component | ATA:38 |
| PN:5300-1                                          | MOS/MSC          | 12-Aug-15 | O/C | TSN 0 |  |  |  |           |        |
| SN:M5189                                           | HRS              | 7535.1    |     | TSN 0 |  |  |  |           |        |
|                                                    | AFL              | 5764      |     | TSN 0 |  |  |  |           |        |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                  |           |     |       |  |  |  |           |        |

|                                                    |                         |           |     |       |  |  |  |           |        |
|----------------------------------------------------|-------------------------|-----------|-----|-------|--|--|--|-----------|--------|
| 389050                                             | TOILET CLEAN WATER PUMP |           |     |       |  |  |  | Component | ATA:38 |
| PN:PN                                              | MOS/MSC                 | 09-Mar-01 | O/C | TSN 0 |  |  |  |           |        |
| SN:UNKNOWN                                         | HRS                     | 0         |     | TSN 0 |  |  |  |           |        |
|                                                    | AFL                     | 0         |     | TSN 0 |  |  |  |           |        |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                         |           |     |       |  |  |  |           |        |

ATA 49 - AIRBORNE AUXILIARY POWER

|            |                             |           |     |       |  |  |  |           |        |
|------------|-----------------------------|-----------|-----|-------|--|--|--|-----------|--------|
| 490060     | ELECTRONIC CONTROL, APU ECU |           |     |       |  |  |  | Component | ATA:49 |
| PN:PN      | MOS/MSC                     | 09-Mar-01 | O/C | TSN 0 |  |  |  |           |        |
| SN:UNKNOWN | HRS                         | 0         |     | TSN 0 |  |  |  |           |        |
|            | AFL                         | 0         |     | TSN 0 |  |  |  |           |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                            | Unit    | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------|---------|-----------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 49 - AIRBORNE AUXILIARY POWER                  |         |           |          |          |                        |           |           |             |          |
| PROC. REF: AMM 49-60-04PROC. REF: AMM 49-60-04     |         |           |          |          |                        |           |           |             |          |
|                                                    |         |           |          |          |                        |           |           |             |          |
| 491011MAINTENANCE CONTROL, APU PANEL               |         |           |          |          |                        |           |           | Component   | ATA:49   |
| PN:PN                                              | MOS/MSC | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL     | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 49-60-02PROC. REF: AMM 49-60-02     |         |           |          |          |                        |           |           |             |          |
|                                                    |         |           |          |          |                        |           |           |             |          |
| 491020APU, COCKPIT CONTROL PANEL                   |         |           |          |          |                        |           |           | Component   | ATA:49   |
| PN:PN                                              | MOS/MSC | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL     | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 49-60-01PROC. REF: AMM 49-60-01     |         |           |          |          |                        |           |           |             |          |
|                                                    |         |           |          |          |                        |           |           |             |          |
| 494050IGNITION, APU UNIT                           |         |           |          |          |                        |           |           | Component   | ATA:49   |
| PN:PN                                              | MOS/MSC | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL     | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 49-40-04PROC. REF: AMM 49-40-04     |         |           |          |          |                        |           |           |             |          |
|                                                    |         |           |          |          |                        |           |           |             |          |
| 495001COOLING, TAILCONE APU (B31) FAN              |         |           |          |          |                        |           |           | Component   | ATA:49   |
| PN:PN                                              | MOS/MSC | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL     | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 49-50-01PROC. REF: AMM 49-50-01     |         |           |          |          |                        |           |           |             |          |
|                                                    |         |           |          |          |                        |           |           |             |          |
| 495002TAILCONE ACCESS DOOR COOLING (B30) FAN       |         |           |          |          |                        |           |           | Component   | ATA:49   |
| PN:PN                                              | MOS/MSC | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL     | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |         |           |          |          |                        |           |           |             |          |
|                                                    |         |           |          |          |                        |           |           |             |          |
| 495040APU THERMOSTAT (S175) SWITCH                 |         |           |          |          |                        |           |           | Component   | ATA:49   |
| PN:PN                                              | MOS/MSC | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                    | AFL     | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |         |           |          |          |                        |           |           |             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9669.1
 AFL: 7372
 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                            | Unit                                       | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------|--------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 49 - AIRBORNE AUXILIARY POWER                  |                                            |           |          |          |                        |           |           |             |                  |
| 495041                                             | APU THERMOSTAT (S176) SWITCH               |           |          |          |                        |           |           |             | Component ATA:49 |
| PN:PN                                              | MOS/MSC                                    | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                        | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                        | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                            |           |          |          |                        |           |           |             |                  |
| 495201                                             | STRUT SUPPORT ASSEMBLY                     |           |          |          |                        |           |           |             | Component ATA:49 |
| PN:PN                                              | MOS/MSC                                    | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                        | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                        | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                            |           |          |          |                        |           |           |             |                  |
| 495202                                             | STRUT SUPPORT ASSEMBLY                     |           |          |          |                        |           |           |             | Component ATA:49 |
| PN:PN                                              | MOS/MSC                                    | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                        | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                        | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                            |           |          |          |                        |           |           |             |                  |
| 497001                                             | APU BITE INDICATOR                         |           |          |          |                        |           |           |             | Component ATA:49 |
| PN:PN                                              | MOS/MSC                                    | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                        | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                        | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                            |           |          |          |                        |           |           |             |                  |
| 49APU1                                             | APU                                        |           |          |          |                        |           |           |             | Component ATA:49 |
| PN:PN                                              | MOS/MSC                                    |           | E/C      |          |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                        |           |          |          |                        |           |           |             |                  |
|                                                    | AFL                                        |           |          |          |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                            |           |          |          |                        |           |           |             |                  |
| 5-19-01-AA4900039                                  | APU FUEL LINE (P/N 4549058032-001) REPLACE |           |          |          |                        |           |           |             | Component ATA:49 |
| PN:PN                                              | MOS/MSC                                    | EFF       | N/A      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                        | EFF       |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                        |           |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                            |           |          |          |                        |           |           |             |                  |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C/W   (M)-Manual Due   U-User Task   Ex-Excluded Task

# Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9669.1
 AFL: 7372
 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                                                                                         | Unit    | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|-----------------------------------------------------------------------------------------------------------------|---------|-----------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 52 - DOORS                                                                                                  |         |           |          |          |                        |           |           |             |          |
| 5-19-02-RVSM-M5240004 INSPECT AVIONIC ACCESS DOOR GAP AND MISMATCH FOR RVSM COMPLIANT AIRCRAFT (IRN # M5240004) |         |           |          |          |                        |           |           | Service     | ATA:52   |
|                                                                                                                 | MOS     | 10-Aug-24 | 24       | Adj 6d   | 16-Aug-26              |           | 501 d     | RVSM        |          |
|                                                                                                                 | HRS     |           |          |          |                        |           |           |             |          |
|                                                                                                                 | AFL     |           |          |          |                        |           |           |             |          |
| PROC. REF: AMM 52-40-01PROC. REF: AMM 52-40-01                                                                  |         |           |          |          |                        |           |           |             |          |
| 521001 UPPER CABIN DOOR                                                                                         |         |           |          |          |                        |           |           | Component   | ATA:52   |
| PN:PN                                                                                                           | MOS/MSC | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                                                                                      | HRS     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                                                                                 | AFL     | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 52-10-01PROC. REF: AMM 52-10-01                                                                  |         |           |          |          |                        |           |           |             |          |
| 521002 LOWER CABIN DOOR                                                                                         |         |           |          |          |                        |           |           | Component   | ATA:52   |
| PN:PN                                                                                                           | MOS/MSC | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                                                                                      | HRS     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                                                                                 | AFL     | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 52-10-01PROC. REF: AMM 52-10-01                                                                  |         |           |          |          |                        |           |           |             |          |
| 5210053 CABIN DOOR HANDLE - REPLACE                                                                             |         |           |          |          |                        |           |           | Service     | ATA:52   |
|                                                                                                                 | MOS     | 06-Jul-21 | 144      | Adj -67d | 30-Apr-33              |           | 2950 d    |             |          |
|                                                                                                                 | HRS     | 8631.2    |          |          |                        |           |           |             |          |
|                                                                                                                 | AFL     | 6618      | 6000     |          | 12618                  |           | 5246      |             |          |
| PROC. REF: AMM 52-10-08, AMM 52-10-13PROC. REF: AMM 52-10-08, AMM 52-10-13                                      |         |           |          |          |                        |           |           |             |          |
| 521010 LOWER ENTRY DOOR FORWARD GAS DAMPER ASSEMBLY                                                             |         |           |          |          |                        |           |           | Component   | ATA:52   |
| PN:SP21231-2                                                                                                    | MOS/MSC | 24-Jan-25 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                                                                                      | HRS     | 9595.4    |          | TSN 0    |                        |           |           |             |          |
|                                                                                                                 | AFL     | 7326      |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 52-10-11PROC. REF: AMM 52-10-11                                                                  |         |           |          |          |                        |           |           |             |          |
| 521011 LOWER ENTRY DOOR AFT GAS DAMPER ASSEMBLY                                                                 |         |           |          |          |                        |           |           | Component   | ATA:52   |
| PN:PN                                                                                                           | MOS/MSC | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                                                                                      | HRS     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                                                                                 | AFL     | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 52-10-11PROC. REF: AMM 52-10-11                                                                  |         |           |          |          |                        |           |           |             |          |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C/W   (M)-Manual Due   U-User Task   Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                            | Unit                                              | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------|---------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 52 - DOORS                                     |                                                   |           |          |          |                        |           |           |             |                  |
| 522001                                             | EMERGENCY EXIT DOOR ASSEMBLY                      |           |          |          |                        |           |           |             | Component ATA:52 |
| PN:PN                                              | MOS/MSC                                           | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 52-20-01PROC. REF: AMM 52-20-01     |                                                   |           |          |          |                        |           |           |             |                  |
| 522010                                             | DOOR ASSY                                         |           |          |          |                        |           |           |             | Component ATA:52 |
| PN:PN                                              | MOS/MSC                                           | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 52-20-06PROC. REF: AMM 52-20-06     |                                                   |           |          |          |                        |           |           |             |                  |
| 523001                                             | TAILCONE BAGGAGE DOOR ASSEMBLY                    |           |          |          |                        |           |           |             | Component ATA:52 |
| PN:PN                                              | MOS/MSC                                           | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 524001                                             | TAILCONE ACCESS DOOR                              |           |          |          |                        |           |           |             | Component ATA:52 |
| PN:4552405151-009                                  | MOS/MSC                                           | 17-Feb-05 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:0316                                            | HRS                                               | 3300.2    |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                               | 2515      |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 52-40-02PROC. REF: AMM 52-40-02     |                                                   |           |          |          |                        |           |           |             |                  |
| 524010                                             | SPPR DOOR ASSY                                    |           |          |          |                        |           |           |             | Component ATA:52 |
| PN:PN                                              | MOS/MSC                                           |           | O/C      |          |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                               |           |          |          |                        |           |           |             |                  |
|                                                    | AFL                                               |           |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 52-40-03PROC. REF: AMM 52-40-03     |                                                   |           |          |          |                        |           |           |             |                  |
| AA5210055 <sup>S</sup>                             | CABIN DOOR HANDLE RAMP ROLLER WHEEL - LUBRICATION |           |          |          |                        |           |           |             | Service ATA:52   |
|                                                    | MOS                                               | 22-Jun-23 | 48       |          |                        |           |           |             |                  |
|                                                    | HRS                                               | 9258.5    | 1200     |          |                        |           |           |             |                  |
|                                                    | AFL                                               | 7100      |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02     |                                                   |           |          |          |                        |           |           |             |                  |
| PKG:18                                             |                                                   |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                                      | Unit         | C / W                                                                                           | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty |
|--------------------------------------------------------------|--------------|-------------------------------------------------------------------------------------------------|----------|----------|------------------------|-----------|-----------|---------------|----------|
| ATA 52 - DOORS                                               |              |                                                                                                 |          |          |                        |           |           |               |          |
| Y5210001                                                     | <sup>S</sup> | TAILCONE ACCESS DOOR AND SEAL - PERFORM VISUAL INSPECTION OF DOOR, SEALS, AND LATCHES           |          |          |                        |           |           | Service       | ATA:52   |
|                                                              | MOS          | 02-Aug-24                                                                                       | 24       |          |                        |           |           |               |          |
|                                                              | HRS          | 9525.7                                                                                          | 600      |          |                        |           |           |               |          |
|                                                              | AFL          | 7276                                                                                            |          |          |                        |           |           |               |          |
| PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00               |              |                                                                                                 |          |          |                        |           |           |               | PKG:12   |
| Y5210002                                                     | <sup>S</sup> | BAGGAGE COMPARTMENT DOOR - PERFORM VISUAL INSPECTION OF DOORS, SEALS, AND LATCHES               |          |          |                        |           |           | Service       | ATA:52   |
|                                                              | MOS          | 02-Aug-24                                                                                       | 24       |          |                        |           |           |               |          |
|                                                              | HRS          | 9525.7                                                                                          | 600      |          |                        |           |           |               |          |
|                                                              | AFL          | 7276                                                                                            |          |          |                        |           |           |               |          |
| PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00               |              |                                                                                                 |          |          |                        |           |           |               | PKG:12   |
| Y5210006                                                     | <sup>S</sup> | UPPER PASSENGER/CREW DOOR VENT DOOR SPRINGS - PERFORM VISUAL INSPECTION                         |          |          |                        |           |           | Service       | ATA:52   |
|                                                              | MOS          | 02-Aug-24                                                                                       | 24       |          |                        |           |           |               |          |
|                                                              | HRS          | 9525.7                                                                                          | 600      |          |                        |           |           |               |          |
|                                                              | AFL          | 7276                                                                                            |          |          |                        |           |           |               |          |
| PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00               |              |                                                                                                 |          |          |                        |           |           |               | PKG:12   |
| Y5210008                                                     | <sup>S</sup> | EMERGENCY EXIT DOOR INTERNAL AND EXTERNAL HANDLE LATCHING MECHANISM - PERFORM OPERATIONAL CHECK |          |          |                        |           |           | Service       | ATA:52   |
|                                                              | MOS          | 02-Aug-24                                                                                       | 24       |          |                        |           |           |               |          |
|                                                              | HRS          | 9525.7                                                                                          | 600      |          |                        |           |           |               |          |
|                                                              | AFL          | 7276                                                                                            |          |          |                        |           |           |               |          |
| PROC. REF: AMM 52-20-07PROC. REF: AMM 52-20-07               |              |                                                                                                 |          |          |                        |           |           |               | PKG:12   |
| ATA 53 - FUSELAGE                                            |              |                                                                                                 |          |          |                        |           |           |               |          |
| 5-19-00-H5323032                                             |              | * EXTERIOR CABIN WINDOW COAMINGS (UNPAINTED) - PERFORM EDDY CURRENT INSPECTION (IRN H5323032)   |          |          |                        |           |           | Service       | ATA:53   |
|                                                              | MOS          | 11-Mar-25                                                                                       | 24       |          | 11-Mar-27              |           | 708 d     | AIRWORTHINESS |          |
|                                                              | HRS          | 9645.6                                                                                          | 2400     |          | 12045.6                |           | 2376.5    |               |          |
|                                                              | AFL          | 7359                                                                                            |          |          |                        |           |           |               |          |
| PROC. REF: NDT PART 6/56-20-01PROC. REF: NDT PART 6/56-20-01 |              |                                                                                                 |          |          |                        |           |           |               |          |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C/W   (M)-Manual Due   U-User Task   Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                                                                                | Unit                                                                                                                                                                                                                                                                                             | C/W                                                                                                                                                                                                                                                                                       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty       |
|--------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|----------|------------------------|-----------|-----------|---------------|----------------|
| ATA 53 - FUSELAGE                                                                                      |                                                                                                                                                                                                                                                                                                  |                                                                                                                                                                                                                                                                                           |          |          |                        |           |           |               |                |
| 5-19-00-H5323092                                                                                       | * EXTERIOR CABIN WINDOW COAMINGS (PAINTED) - PERFORM EDDY CURRENT INSPECTION (IRN H5323092)                                                                                                                                                                                                      |                                                                                                                                                                                                                                                                                           |          |          |                        |           |           |               | Service ATA:53 |
|                                                                                                        | MOS/MSC                                                                                                                                                                                                                                                                                          | 30-Apr-06                                                                                                                                                                                                                                                                                 | N/A      |          |                        |           |           |               |                |
|                                                                                                        | HRS                                                                                                                                                                                                                                                                                              | 4466.8                                                                                                                                                                                                                                                                                    |          |          |                        |           |           |               |                |
|                                                                                                        | AFL                                                                                                                                                                                                                                                                                              | 3408                                                                                                                                                                                                                                                                                      |          |          |                        |           |           |               |                |
| PROC. REF: NDT PART 6/56-20-01PROC. REF: NDT PART 6/56-20-01                                           |                                                                                                                                                                                                                                                                                                  |                                                                                                                                                                                                                                                                                           |          |          |                        |           |           |               |                |
| 5-19-00-M5310023                                                                                       | U                                                                                                                                                                                                                                                                                                | DETAILED VISUAL INSPECTION FORWARD AND AFT FUEL CELL BAY STRUCTURE, ANGLE REINFORCEMENT, STRINGER 1, LH & RH HI-LITE COLLARS. EFFECTIVE 45-005 THRU 45-031 NOT MODIFIED PER SB45-53-27. (ZONE/ACCESS 300 IRN M5310023)                                                                    |          |          |                        |           |           |               | Service ATA:53 |
|                                                                                                        | MOS/MSC                                                                                                                                                                                                                                                                                          | 09-Mar-01                                                                                                                                                                                                                                                                                 | N/A      |          |                        |           |           | AIRWORTHINESS |                |
|                                                                                                        | HRS                                                                                                                                                                                                                                                                                              | 0                                                                                                                                                                                                                                                                                         |          |          |                        |           |           |               |                |
| WC#: 53-108                                                                                            | AFL                                                                                                                                                                                                                                                                                              | 0                                                                                                                                                                                                                                                                                         |          |          |                        |           |           |               |                |
| 5-19-00-M5310025                                                                                       | U                                                                                                                                                                                                                                                                                                | DETAILED VISUAL INSPECTION AFT FUSELAGE KEELBEAM LONGERON (LH & RH, BL 5.15, FS 466.30-495.12) AND AFT FUSELAGE KEELBEAM LOWER FRAME (FS 466.30, BL9.55 LH THRU BL 9.55 RH) OF HI-LITE COLLARS. EFFECTIVE 45-005 THRU 45-031 NOT MODIFIED PER SB 45-53-28. (ZONE/ACCESS 200 IRN M5310025) |          |          |                        |           |           |               | Service ATA:53 |
|                                                                                                        | MOS/MSC                                                                                                                                                                                                                                                                                          | 09-Mar-01                                                                                                                                                                                                                                                                                 | N/A      |          |                        |           |           | AIRWORTHINESS |                |
|                                                                                                        | HRS                                                                                                                                                                                                                                                                                              | 0                                                                                                                                                                                                                                                                                         |          |          |                        |           |           |               |                |
| WC#: 53.102                                                                                            | AFL                                                                                                                                                                                                                                                                                              | 0                                                                                                                                                                                                                                                                                         |          |          |                        |           |           |               |                |
| 5-19-00-T5323166                                                                                       | PERFORM * EXTERNAL SKIN CUT-OUTS/PENETRATIONS (PRESSURE CABIN) - PERFORM DETAILED VISUAL INSPECTION. INSPECT SKIN AND DOUBLERS AT ANTENNAS, ELECTRICAL COMPONENTS, AND ACCESS PANELS (EXCLUDING PITOT/STATIC PROBES, AOA STALL VANES AND WING INSPECTION LIGHT. (REFER TO 5-10-00.) IRN T5323166 |                                                                                                                                                                                                                                                                                           |          |          |                        |           |           |               | Service ATA:53 |
|                                                                                                        | MOS                                                                                                                                                                                                                                                                                              | 02-Aug-24                                                                                                                                                                                                                                                                                 | 144      |          | 02-Aug-36              |           | 4140 d    | MANDATORY     |                |
|                                                                                                        | HRS                                                                                                                                                                                                                                                                                              | 9525.7                                                                                                                                                                                                                                                                                    | 9600     |          | 19125.7                |           | 9456.6    |               |                |
|                                                                                                        | AFL                                                                                                                                                                                                                                                                                              | 7276                                                                                                                                                                                                                                                                                      |          |          |                        |           |           |               |                |
| PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00                                                         |                                                                                                                                                                                                                                                                                                  |                                                                                                                                                                                                                                                                                           |          |          |                        |           |           |               |                |
| 5-19-00-V5323168                                                                                       | EDDY CURRENT INSPECTION * LOWER COUPE RAIL RADIUS/WINDSCREEN RETAINER ATTACH (P/N'S 4553130001-802 THRU 4553130001-809)                                                                                                                                                                          |                                                                                                                                                                                                                                                                                           |          |          |                        |           |           |               | Service ATA:53 |
|                                                                                                        | MOS                                                                                                                                                                                                                                                                                              | 22-Jun-23                                                                                                                                                                                                                                                                                 |          |          |                        |           |           | AIRWORTHINESS |                |
|                                                                                                        | HRS                                                                                                                                                                                                                                                                                              | 9258.5                                                                                                                                                                                                                                                                                    | 5000     |          | 14258.5                |           | 4589.4    |               |                |
|                                                                                                        | AFL                                                                                                                                                                                                                                                                                              | 7100                                                                                                                                                                                                                                                                                      |          |          |                        |           |           |               |                |
| PROC. REF: NDT PART 6/53-30-23, NDT PART 6/53-30-24PROC. REF: NDT PART 6/53-30-23, NDT PART 6/53-30-24 |                                                                                                                                                                                                                                                                                                  |                                                                                                                                                                                                                                                                                           |          |          |                        |           |           |               |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 9669.1
AFL: 7372
As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                            | Unit                                                                                                                         | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition    | Warranty |
|----------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|----------------|----------|
| ATA 53 - FUSELAGE                                  |                                                                                                                              |           |          |          |                        |           |           |                |          |
| 5-19-01-U5323167-LEFT                              | * REPLACE LEFT COUPE RAIL (P/N 4553002003V7000-001, 4553002003V7001-002) (IRN U5323167) ASSEMBLY                             |           |          |          |                        |           |           | Component      | ATA:53   |
| PN:PN                                              | MOS/MSC                                                                                                                      |           | N/A      | TSN 0    |                        |           |           | NOT APPLICABLE |          |
| SN:UNKNOWN                                         | HRS                                                                                                                          |           |          | TSN 0    |                        |           |           |                |          |
|                                                    | AFL                                                                                                                          |           |          | TSN 0    |                        |           |           |                |          |
| PROC. REF: AMM 53-10-04PROC. REF: AMM 53-10-04     |                                                                                                                              |           |          |          |                        |           |           |                |          |
| 5-19-01-U5323167-RIGHT                             | * REPLACE RIGHT COUPE RAIL (4553002003V7000-001, 4553002003V7001-002) (IRN U5323167) ASSEMBLY                                |           |          |          |                        |           |           | Component      | ATA:53   |
| PN:PN                                              | MOS/MSC                                                                                                                      |           | N/A      | TSN 0    |                        |           |           | NOT APPLICABLE |          |
| SN:UNKNOWN                                         | HRS                                                                                                                          |           |          | TSN 0    |                        |           |           |                |          |
|                                                    | AFL                                                                                                                          |           |          | TSN 0    |                        |           |           |                |          |
| PROC. REF: AMM 53-10-04PROC. REF: AMM 53-10-04     |                                                                                                                              |           |          |          |                        |           |           |                |          |
| 5-19-02-RVSM-M5313001                              | PERFORM PITOT-STATIC PROBE ZONE SKIN CONTOUR CHECK OF THE FORWARD FUSELAGE SKIN FOR RVSM COMPLIANT AIRCRAFT (IRN # M5313001) |           |          |          |                        |           |           | Service        | ATA:53   |
|                                                    | MOS                                                                                                                          | 10-Aug-24 | 24       | Adj 6d   | 16-Aug-26              |           | 501 d     | RVSM           |          |
|                                                    | HRS                                                                                                                          |           |          |          |                        |           |           |                |          |
|                                                    | AFL                                                                                                                          |           |          |          |                        |           |           |                |          |
| PROC. REF: AMM 53-00-01PROC. REF: AMM 53-00-01     |                                                                                                                              |           |          |          |                        |           |           |                |          |
| 530001                                             | FUSELAGE ASSEMBLY                                                                                                            |           |          |          |                        |           |           | Component      | ATA:53   |
| PN:PN                                              | MOS/MSC                                                                                                                      | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |                |          |
| SN:UNKNOWN                                         | HRS                                                                                                                          | 0         |          | TSN 0    |                        |           |           |                |          |
|                                                    | AFL                                                                                                                          | 0         |          | TSN 0    |                        |           |           |                |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                                                                              |           |          |          |                        |           |           |                |          |
| 535001                                             | RADOME                                                                                                                       |           |          |          |                        |           |           | Component      | ATA:53   |
| PN:6634408000-001                                  | MOS/MSC                                                                                                                      | 12-Dec-11 | O/C      | TSR 0    |                        |           |           |                |          |
| SN:150                                             | HRS                                                                                                                          | 6763.5    |          | TSR 0    |                        |           |           |                |          |
|                                                    | AFL                                                                                                                          | 5158      |          | TSR 0    |                        |           |           |                |          |
| PROC. REF: AMM 53-50-01PROC. REF: AMM 53-50-01     |                                                                                                                              |           |          |          |                        |           |           |                |          |
| 535601                                             | LEFT DELTA FIN                                                                                                               |           |          |          |                        |           |           | Component      | ATA:53   |
| PN:PN                                              | MOS/MSC                                                                                                                      | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |                |          |
| SN:UNKNOWN                                         | HRS                                                                                                                          | 0         |          | TSN 0    |                        |           |           |                |          |
|                                                    | AFL                                                                                                                          | 0         |          | TSN 0    |                        |           |           |                |          |
| PROC. REF: AMM 53-56-01PROC. REF: AMM 53-56-01     |                                                                                                                              |           |          |          |                        |           |           |                |          |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C/W   (M)-Manual Due   U-User Task   Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|---------|------|-----|----------|----------|------------------------|-----------|-----------|-------------|----------|
|---------|------|-----|----------|----------|------------------------|-----------|-----------|-------------|----------|

ATA 53 - FUSELAGE

|                                                |                 |           |     |       |  |  |  |           |        |
|------------------------------------------------|-----------------|-----------|-----|-------|--|--|--|-----------|--------|
| 535602                                         | RIGHT DELTA FIN |           |     |       |  |  |  | Component | ATA:53 |
| PN:PN                                          | MOS/MSC         | 09-Mar-01 | O/C | TSN 0 |  |  |  |           |        |
| SN:UNKNOWN                                     | HRS             | 0         |     | TSN 0 |  |  |  |           |        |
|                                                | AFL             | 0         |     | TSN 0 |  |  |  |           |        |
| PROC. REF: AMM 53-56-01PROC. REF: AMM 53-56-01 |                 |           |     |       |  |  |  |           |        |

|                                                              |                                                                                                                      |           |      |  |  |  |  |               |        |
|--------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------|-----------|------|--|--|--|--|---------------|--------|
| N5314000 <sup>S</sup>                                        | PERFORM * EMERGENCY EXIT DOOR SKIN CUTOUT CORNERS AND DOUBLERS (FS 370 TO FS 398) - PERFORM EDDY CURRENT INSPECTION. |           |      |  |  |  |  | Service       | ATA:53 |
|                                                              | MOS                                                                                                                  | 25-Nov-19 | 96   |  |  |  |  | AIRWORTHINESS |        |
|                                                              | HRS                                                                                                                  | 8177.7    | 2400 |  |  |  |  |               |        |
|                                                              | AFL                                                                                                                  | 6303      |      |  |  |  |  |               |        |
| PROC. REF: NDT PART 6/53-30-01PROC. REF: NDT PART 6/53-30-01 |                                                                                                                      |           |      |  |  |  |  |               | PKG:19 |

|                                                              |                                                                                                                                                                         |           |      |  |  |  |  |               |        |
|--------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|------|--|--|--|--|---------------|--------|
| N5323026 <sup>S</sup>                                        | PERFORM * UPPER AND LOWER PASSENGER/CREW DOOR SKIN CUTOUT CORNERS (F.S. 224 - F.S. 256) -EDDY CURRENT INSPECTION. INSPECT SKIN AT CORNERS OF PASSENGER/CREW DOOR CUTOUT |           |      |  |  |  |  | Service       | ATA:53 |
|                                                              | MOS                                                                                                                                                                     | 25-Nov-19 | 96   |  |  |  |  | AIRWORTHINESS |        |
|                                                              | HRS                                                                                                                                                                     | 8177.7    | 2400 |  |  |  |  |               |        |
|                                                              | AFL                                                                                                                                                                     | 6303      |      |  |  |  |  |               |        |
| PROC. REF: NDT PART 6/53-30-02PROC. REF: NDT PART 6/53-30-02 |                                                                                                                                                                         |           |      |  |  |  |  |               | PKG:19 |

|                                                |                                                                                       |           |     |  |  |  |  |         |        |
|------------------------------------------------|---------------------------------------------------------------------------------------|-----------|-----|--|--|--|--|---------|--------|
| T5321089 <sup>S</sup>                          | SEAT RAILS - PERFORM DETAILED INSPECTION OF SEAT RAIL (TRACK) SHEAR WEBS FOR CRACKING |           |     |  |  |  |  | Service | ATA:53 |
|                                                | MOS                                                                                   | 02-Aug-24 | 24  |  |  |  |  |         |        |
|                                                | HRS                                                                                   | 9525.7    | 600 |  |  |  |  |         |        |
|                                                | AFL                                                                                   | 7276      |     |  |  |  |  |         |        |
| PROC. REF: AMM 53-20-01PROC. REF: AMM 53-20-01 |                                                                                       |           |     |  |  |  |  |         | PKG:7  |

|                                                |                                             |           |     |  |  |  |  |         |        |
|------------------------------------------------|---------------------------------------------|-----------|-----|--|--|--|--|---------|--------|
| Y5320000 <sup>S</sup>                          | CENTER PEDESTAL - PERFORM VISUAL INSPECTION |           |     |  |  |  |  | Service | ATA:53 |
|                                                | MOS                                         | 02-Aug-24 | 12  |  |  |  |  |         |        |
|                                                | HRS                                         | 9525.7    | 300 |  |  |  |  |         |        |
|                                                | AFL                                         | 7276      |     |  |  |  |  |         |        |
| PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00 |                                             |           |     |  |  |  |  |         | PKG:1  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                        | Unit | C / W                                                                                                                                                                                                                                                                                                                                              | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|------------------------------------------------|------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 53 - FUSELAGE                              |      |                                                                                                                                                                                                                                                                                                                                                    |          |          |                        |           |           |             |          |
| Y5321010 <sup>S</sup>                          |      | FLOORBOARDS AROUND GALLEY, LAVATORY, AND WATER TANK - PERFORM VISUAL INSPECTION                                                                                                                                                                                                                                                                    |          |          |                        |           |           | Service     | ATA:53   |
|                                                | MOS  | 02-Aug-24                                                                                                                                                                                                                                                                                                                                          | 12       |          |                        |           |           |             |          |
|                                                | HRS  | 9525.7                                                                                                                                                                                                                                                                                                                                             | 300      |          |                        |           |           |             |          |
|                                                | AFL  | 7276                                                                                                                                                                                                                                                                                                                                               |          |          |                        |           |           |             |          |
| PROC. REF: AMM 53-20-01PROC. REF: AMM 53-20-01 |      |                                                                                                                                                                                                                                                                                                                                                    |          |          |                        |           |           |             | PKG:1    |
|                                                |      |                                                                                                                                                                                                                                                                                                                                                    |          |          |                        |           |           |             |          |
| Y5321011 <sup>S</sup>                          |      | TAILCONE BAGGAGE COMPARTMENT - PERFORM VISUAL INSPECTION                                                                                                                                                                                                                                                                                           |          |          |                        |           |           | Service     | ATA:53   |
|                                                | MOS  | 02-Aug-24                                                                                                                                                                                                                                                                                                                                          | 24       |          |                        |           |           |             |          |
|                                                | HRS  | 9525.7                                                                                                                                                                                                                                                                                                                                             | 600      |          |                        |           |           |             |          |
|                                                | AFL  | 7276                                                                                                                                                                                                                                                                                                                                               |          |          |                        |           |           |             |          |
| PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00 |      |                                                                                                                                                                                                                                                                                                                                                    |          |          |                        |           |           |             | PKG:8    |
|                                                |      |                                                                                                                                                                                                                                                                                                                                                    |          |          |                        |           |           |             |          |
| Y5340007 <sup>S</sup>                          |      | PERFORM WING ATTACH FITTINGS - VISUAL INSPECTION                                                                                                                                                                                                                                                                                                   |          |          |                        |           |           | Service     | ATA:53   |
|                                                | MOS  | 25-Nov-19                                                                                                                                                                                                                                                                                                                                          | 96       |          |                        |           |           |             |          |
|                                                | HRS  | 8177.7                                                                                                                                                                                                                                                                                                                                             | 2400     |          |                        |           |           |             |          |
|                                                | AFL  | 6303                                                                                                                                                                                                                                                                                                                                               |          |          |                        |           |           |             |          |
| PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00 |      |                                                                                                                                                                                                                                                                                                                                                    |          |          |                        |           |           |             | PKG:19   |
|                                                |      |                                                                                                                                                                                                                                                                                                                                                    |          |          |                        |           |           |             |          |
| Y5360000 <sup>S</sup>                          |      | DELTA FINS - PERFORM VISUAL INSPECTION                                                                                                                                                                                                                                                                                                             |          |          |                        |           |           | Service     | ATA:53   |
|                                                | MOS  | 02-Aug-24                                                                                                                                                                                                                                                                                                                                          | 24       |          |                        |           |           |             |          |
|                                                | HRS  | 9525.7                                                                                                                                                                                                                                                                                                                                             | 600      |          |                        |           |           |             |          |
|                                                | AFL  | 7276                                                                                                                                                                                                                                                                                                                                               |          |          |                        |           |           |             |          |
| PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00 |      |                                                                                                                                                                                                                                                                                                                                                    |          |          |                        |           |           |             | PKG:8    |
|                                                |      |                                                                                                                                                                                                                                                                                                                                                    |          |          |                        |           |           |             |          |
| ATA 54 - NACELLES/PYLONS                       |      |                                                                                                                                                                                                                                                                                                                                                    |          |          |                        |           |           |             |          |
| 5-19-00-Q5450013 <sup>U</sup>                  |      | VISUAL INSPECTION FORWARD ENGINE BEAM AND BEAM FITTING - PERFORM INSPECTION, PAYING PARTICULAR ATTENTION OF THE FOLLOWING: A. UPPER CAPPING PLATE AT ASTENER HOLES, AND CHANNEL FLANGE AT FASTENER HOLES. B. BOLT HOLES, ESPECIALLY UPPER BOLT HOLE ON AFT FLANGE. (REFER TO 5-10-00.) EFFECTIVE ON AIRCRAFT WITH 5,000 HOUR CZI MODIFIED ENGINES. |          |          |                        |           |           | Service     | ATA:54   |
|                                                | MOS  | 22-Jun-23                                                                                                                                                                                                                                                                                                                                          |          |          |                        |           |           |             |          |
|                                                | HRS  | 9258.5                                                                                                                                                                                                                                                                                                                                             | 5000     |          | 14258.5                |           | 4589.4    |             |          |
|                                                | AFL  | 7100                                                                                                                                                                                                                                                                                                                                               |          |          |                        |           |           |             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                             | Unit    | C/W                                                                                                                                                                                                                                                            | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining            | Disposition | Warranty |
|-------------------------------------|---------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|----------|------------------------|-----------|----------------------|-------------|----------|
| ATA 54 - NACELLES/PYLONS            |         |                                                                                                                                                                                                                                                                |          |          |                        |           |                      |             |          |
| 5-19-00-Q5450013-LEFT <sup>U</sup>  |         | FORWARD LEFT ENGINE BEAM AND BEAM FITTING - PERFORM VISUAL INSPECTION, PAYING PARTICULAR ATTENTION OF THE FOLLOWING: A. UPPER CAPPING PLATE AT FASTENER HOLES, AND CHANNEL FLANGE AT FASTENER HOLES. B. BOLT HOLES, ESPECIALLY UPPER BOLT HOLE ON AFT FLANGE   |          |          |                        |           |                      | Service     | ATA:54   |
|                                     | MOS/MSC | 09-Mar-01                                                                                                                                                                                                                                                      | N/A      |          |                        |           |                      |             |          |
|                                     | HRS     | 0                                                                                                                                                                                                                                                              |          |          |                        |           |                      |             |          |
|                                     | AFL     | 0                                                                                                                                                                                                                                                              |          |          |                        |           |                      |             |          |
|                                     |         |                                                                                                                                                                                                                                                                |          |          |                        |           |                      |             |          |
| 5-19-00-Q5450013-RIGHT <sup>U</sup> |         | RIGHT FORWARD ENGINE BEAM AND BEAM FITTING - PERFORM VISUAL INSPECTION, PAYING PARTICULAR ATTENTION OF THE FOLLOWING: A. UPPER CAPPING PLATE AT FASTENER HOLES, AND CHANNEL FLANGE AT FASTENER HOLES. B. BOLT HOLES, ESPECIALLY UPPER BOLT HOLE ON AFT FLANGE. |          |          |                        |           |                      | Service     | ATA:54   |
|                                     | MOS/MSC | 09-Mar-01                                                                                                                                                                                                                                                      | N/A      |          |                        |           |                      |             |          |
|                                     | HRS     | 0                                                                                                                                                                                                                                                              |          |          |                        |           |                      |             |          |
|                                     | AFL     | 0                                                                                                                                                                                                                                                              |          |          |                        |           |                      |             |          |
|                                     |         |                                                                                                                                                                                                                                                                |          |          |                        |           |                      |             |          |
| 5-19-01-A5450022 <sup>U</sup>       |         | REPLACEMENT AFT ENGINE MOUNT TO END FITTING ATTACH BOLT. (*IRN # A5450022)                                                                                                                                                                                     |          |          |                        |           |                      | Service     | ATA:54   |
|                                     | MOS     | 26-Jul-23                                                                                                                                                                                                                                                      |          |          |                        |           |                      | LIFE LIMIT  |          |
|                                     | HRS     | 9278                                                                                                                                                                                                                                                           | 9600     | 18878    |                        |           | 9208.9               |             |          |
|                                     | AFL     | 7111                                                                                                                                                                                                                                                           |          |          |                        |           |                      |             |          |
|                                     |         |                                                                                                                                                                                                                                                                |          |          |                        |           |                      |             |          |
| 5-19-01-A5450022-LEFT <sup>U</sup>  |         | LEFT AFT ENGINE MOUNT TO END FITTING ATTACH BOLT. IRN A5450022 CHANGE                                                                                                                                                                                          |          |          |                        |           |                      | Component   | ATA:54   |
| PN:A5450022                         | MOS     | 26-Jul-23                                                                                                                                                                                                                                                      | TSN 0    |          |                        |           |                      | MANDATORY   |          |
| SN:UNKNOWN                          | HRS     | 9278                                                                                                                                                                                                                                                           | 9600     | TSN 0    | 18878                  |           | 9208.9               |             |          |
|                                     | AFL     | 7111                                                                                                                                                                                                                                                           | TSN 0    |          |                        |           |                      |             |          |
|                                     |         |                                                                                                                                                                                                                                                                |          |          |                        |           |                      |             |          |
| 5-19-01-A5450022-RIGHT <sup>U</sup> |         | RIGHT AFT ENGINE MOUNT TO END FITTING ATTACH BOLT. IRN A5450022 CHANGE                                                                                                                                                                                         |          |          |                        |           |                      | Component   | ATA:54   |
| PN:A5450022                         | MOS     | 26-Jul-23                                                                                                                                                                                                                                                      | TSN 0    |          |                        |           |                      | MANDATORY   |          |
| SN:UNKNOWN                          | HRS     | 9278                                                                                                                                                                                                                                                           | 9600     | TSN 0    | 18878                  |           | 9208.9               |             |          |
|                                     | AFL     | 7111                                                                                                                                                                                                                                                           | TSN 0    |          |                        |           |                      |             |          |
|                                     |         |                                                                                                                                                                                                                                                                |          |          |                        |           |                      |             |          |
| 5-19-01-A5450028                    |         | REPLACE AFT ENGINE BEAM ASSEMBLY END FITTINGS (P/N 4553500201-001/-002)                                                                                                                                                                                        |          |          |                        |           |                      | Service     | ATA:54   |
|                                     | MOS/MSC | 09-Mar-01                                                                                                                                                                                                                                                      | N/A      |          |                        |           | N/A BY SERIAL NUMBER |             |          |
|                                     | HRS     | 0                                                                                                                                                                                                                                                              |          |          |                        |           |                      |             |          |
|                                     | AFL     | 0                                                                                                                                                                                                                                                              |          |          |                        |           |                      |             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                                                                                                       | Unit    | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|-------------------------------------------------------------------------------------------------------------------------------|---------|-----------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 54 - NACELLES/PYLONS                                                                                                      |         |           |          |          |                        |           |           |             |          |
| PROC. REF: AMM 53-40-02PROC. REF: AMM 53-40-02                                                                                |         |           |          |          |                        |           |           |             |          |
| 5-19-01-M5450027 REPLACE FORWARD ENGINE BEAM ASSEMBLY END FITTINGS (P/N 4553500101-003/4) Service ATA:54                      |         |           |          |          |                        |           |           |             |          |
|                                                                                                                               | MOS/MSC | 09-Mar-01 | N/A      |          |                        |           |           |             |          |
|                                                                                                                               | HRS     | 0         |          |          |                        |           |           |             |          |
|                                                                                                                               | AFL     | 0         |          |          |                        |           |           |             |          |
| PROC. REF: AMM 53-40-02PROC. REF: AMM 53-40-02                                                                                |         |           |          |          |                        |           |           |             |          |
| 5-19-01-P5450020 <sup>U</sup> REPLACEMENT AFT ENGINE BEAM TO FRAME ATTACHMENT BOLT. IRN P5450020 Service ATA:54               |         |           |          |          |                        |           |           |             |          |
|                                                                                                                               | MOS     | 26-Jul-23 |          |          |                        |           |           | LIFE LIMIT  |          |
|                                                                                                                               | HRS     | 9278      | 9600     |          | 18878                  |           | 9208.9    |             |          |
|                                                                                                                               | AFL     | 7111      |          |          |                        |           |           |             |          |
| 5-19-01-P5450020-LEFT <sup>U</sup> LEFT AFT ENGINE BEAM TO FRAME ATTACHMENT BOLT. IRN P5450020 REPLACE Component ATA:54       |         |           |          |          |                        |           |           |             |          |
| PN:P5450020                                                                                                                   | MOS     | 26-Jul-23 |          | TSN 0    |                        |           |           | MANDATORY   |          |
| SN:UNKNOWN                                                                                                                    | HRS     | 9278      | 9600     | TSN 0    | 18878                  |           | 9208.9    |             |          |
|                                                                                                                               | AFL     | 7111      |          | TSN 0    |                        |           |           |             |          |
| 5-19-01-P5450020-RIGHT <sup>U</sup> RIGHT AFT ENGINE BEAM TO FRAME ATTACHMENT BOLT. IRN P5450020 REPLACEMENT Component ATA:54 |         |           |          |          |                        |           |           |             |          |
| PN:P5450020                                                                                                                   | MOS     | 26-Jul-23 |          | TSN 0    |                        |           |           | MANDATORY   |          |
| SN:UNKNOWN                                                                                                                    | HRS     | 9278      | 9600     | TSN 0    | 18878                  |           | 9208.9    |             |          |
|                                                                                                                               | AFL     | 7111      |          | TSN 0    |                        |           |           |             |          |
| 5-19-01-P5450023 <sup>U</sup> REPLACE ENGINE TO AFT ENGINE MOUNT ATTACH BOLT. IRN P5450023 Service ATA:54                     |         |           |          |          |                        |           |           |             |          |
|                                                                                                                               | MOS     | 26-Jul-23 |          |          |                        |           |           | LIFE LIMIT  |          |
|                                                                                                                               | HRS     | 9278      | 9600     |          | 18878                  |           | 9208.9    |             |          |
|                                                                                                                               | AFL     | 7111      |          |          |                        |           |           |             |          |
| 5-19-01-P5450023-LEFT <sup>U</sup> LEFT ENGINE TO AFT ENGINE MOUNT ATTACH BOLT. IRN P5450023 CHANGE Component ATA:54          |         |           |          |          |                        |           |           |             |          |
| PN:P5450023                                                                                                                   | MOS     | 26-Jul-23 |          | TSN 0    |                        |           |           | MANDATORY   |          |
| SN:UNKNOWN                                                                                                                    | HRS     | 9278      | 9600     | TSN 0    | 18878                  |           | 9208.9    |             |          |
|                                                                                                                               | AFL     | 7111      |          | TSN 0    |                        |           |           |             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                                      | Unit                                                                                                                                                                                                                                                           | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty |
|--------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|---------------|----------|
| ATA 54 - NACELLES/PYLONS                                     |                                                                                                                                                                                                                                                                |           |          |          |                        |           |           |               |          |
| 5-19-01-P5450023-RIGH <sup>U</sup>                           | RIGHT ENGINE TO AFT ENGINE MOUNT ATTACH BOLT. IRN P5450023 CHANGE                                                                                                                                                                                              |           |          |          |                        |           |           | Component     | ATA:54   |
| PN:P5450023                                                  | MOS                                                                                                                                                                                                                                                            | 26-Jul-23 |          | TSN 0    |                        |           |           | MANDATORY     |          |
| SN:UNKNOWN                                                   | HRS                                                                                                                                                                                                                                                            | 9278      | 9600     | TSN 0    | 18878                  |           | 9208.9    |               |          |
|                                                              | AFL                                                                                                                                                                                                                                                            | 7111      |          | TSN 0    |                        |           |           |               |          |
|                                                              |                                                                                                                                                                                                                                                                |           |          |          |                        |           |           |               |          |
| 5450054                                                      | LEFT FORWARD ENGINE BEAM AND BEAM FITTING - PERFORM VISUAL INSPECTION, PAYING PARTICULAR ATTENTION OF THE FOLLOWING: A. UPPER CAPPING PLATE AT FASTENER HOLES, AND CHANNEL FLANGE AT FASTENER HOLES. B. BOLT HOLES, ESPECIALLY UPPER BOLT HOLE ON AFT FLANGE.  |           |          |          |                        |           |           | Service       | ATA:54   |
|                                                              | MOS                                                                                                                                                                                                                                                            | 26-Jul-23 |          |          |                        |           |           |               |          |
|                                                              | HRS                                                                                                                                                                                                                                                            | 9278      | 6000     |          | 15278                  |           | 5608.9    |               |          |
|                                                              | AFL                                                                                                                                                                                                                                                            | 7111      |          |          |                        |           |           |               |          |
| PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00               |                                                                                                                                                                                                                                                                |           |          |          |                        |           |           |               |          |
|                                                              |                                                                                                                                                                                                                                                                |           |          |          |                        |           |           |               |          |
| 5450054                                                      | RIGHT FORWARD ENGINE BEAM AND BEAM FITTING - PERFORM VISUAL INSPECTION, PAYING PARTICULAR ATTENTION OF THE FOLLOWING: A. UPPER CAPPING PLATE AT FASTENER HOLES, AND CHANNEL FLANGE AT FASTENER HOLES. B. BOLT HOLES, ESPECIALLY UPPER BOLT HOLE ON AFT FLANGE. |           |          |          |                        |           |           | Service       | ATA:54   |
|                                                              | MOS                                                                                                                                                                                                                                                            | 26-Jul-23 |          |          |                        |           |           |               |          |
|                                                              | HRS                                                                                                                                                                                                                                                            | 9278      | 6000     |          | 15278                  |           | 5608.9    |               |          |
|                                                              | AFL                                                                                                                                                                                                                                                            | 7111      |          |          |                        |           |           |               |          |
| PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00               |                                                                                                                                                                                                                                                                |           |          |          |                        |           |           |               |          |
|                                                              |                                                                                                                                                                                                                                                                |           |          |          |                        |           |           |               |          |
| ATA 55 - STABILIZERS                                         |                                                                                                                                                                                                                                                                |           |          |          |                        |           |           |               |          |
| 5-19-00-M5510010                                             | EDDY CURRENT INSPECTION * HORIZONTAL STABILIZER AFT ROOT RIB. INSPECT AFT ROOT RIB INTERNAL BETWEEN MID SPAR AND AFT SPAR AND UPPER AND LOWER SKINS EXTERNAL AT ATTACHMENT FASTENERS. (REFER TO NDI MANUAL {NDI-104}, PART 6, 55-10-03.)                       |           |          |          |                        |           |           | Service       | ATA:55   |
|                                                              | MOS                                                                                                                                                                                                                                                            | 18-Aug-22 |          |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                                                                                                                                                            | 9082.6    | 1200     |          | 10282.6                |           | 613.5     |               |          |
|                                                              | AFL                                                                                                                                                                                                                                                            | 6994      |          |          |                        |           |           |               |          |
| PROC. REF: NDT PART 6/55-10-03PROC. REF: NDT PART 6/55-10-03 |                                                                                                                                                                                                                                                                |           |          |          |                        |           |           |               |          |
|                                                              |                                                                                                                                                                                                                                                                |           |          |          |                        |           |           |               |          |
| 5-19-00-M5540022                                             | RUDDER TORQUE TUBE - PERFORM BORESCOPE INSPECTION                                                                                                                                                                                                              |           |          |          |                        |           |           | Service       | ATA:55   |
|                                                              | MOS/MSC                                                                                                                                                                                                                                                        | 09-Mar-01 | N/A      |          |                        |           |           |               |          |
|                                                              | HRS                                                                                                                                                                                                                                                            | 0         |          |          |                        |           |           |               |          |
|                                                              | AFL                                                                                                                                                                                                                                                            | 0         |          |          |                        |           |           |               |          |
| PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00               |                                                                                                                                                                                                                                                                |           |          |          |                        |           |           |               |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                                                        | Unit    | C/W                                                                                                                                                                                      | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty |
|--------------------------------------------------------------------------------|---------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|----------|------------------------|-----------|-----------|---------------|----------|
| ATA 55 - STABILIZERS                                                           |         |                                                                                                                                                                                          |          |          |                        |           |           |               |          |
| 5-19-00-N5510088                                                               | U       | DETAILED VISUAL INSPECTION UPPER VERTICAL STABILIZER, PIVOT FITTING STRUCTURE HI-LITE COLLARS. EFFECTIVE 45-005 THRU 45-031 NOT MODIFIED PER SB 45-55-15. (ZONE/ACCESS 300 IRN N5510088) |          |          |                        |           |           | Service       | ATA:55   |
|                                                                                | MOS/MSC | 30-Apr-06                                                                                                                                                                                | N/A      |          |                        |           |           | AIRWORTHINESS |          |
|                                                                                | HRS     | 4465.95                                                                                                                                                                                  |          |          |                        |           |           |               |          |
| WC#: 55.106                                                                    | AFL     | 3406                                                                                                                                                                                     |          |          |                        |           |           |               |          |
|                                                                                |         |                                                                                                                                                                                          |          |          |                        |           |           |               |          |
| 5-19-00-W5510091                                                               |         | PERFORM * HORIZONTAL STABILIZER HINGE PRIMARY AND SECONDARY PIVOT PIN INSTALLATION AND ATTACHING HARDWARE - PERFORM DETAILED VISUAL INSPECTION. (REFER TO 55-10-00.)                     |          |          |                        |           |           | Service       | ATA:55   |
|                                                                                | MOS     | 02-Aug-24                                                                                                                                                                                |          |          |                        |           |           | MANDATORY     |          |
|                                                                                | HRS     | 9525.7                                                                                                                                                                                   | 625      |          | 10150.7                |           | 481.6     |               |          |
|                                                                                | AFL     | 7276                                                                                                                                                                                     |          |          |                        |           |           |               |          |
| PROC. REF: AMM 05-10-00, AMM 55-10-00PROC. REF: AMM 05-10-00, AMM 55-10-00     |         |                                                                                                                                                                                          |          |          |                        |           |           |               |          |
|                                                                                |         |                                                                                                                                                                                          |          |          |                        |           |           |               |          |
| 5510034                                                                        |         | HORIZONTAL STABILIZER PRIMARY AND SECONDARY BOLTS AND BUSHINGS - PERFORM DETAILED INSPECTION                                                                                             |          |          |                        |           |           | Service       | ATA:55   |
|                                                                                | MOS     | 16-Jul-19                                                                                                                                                                                |          |          |                        |           |           |               |          |
|                                                                                | HRS     | 8109                                                                                                                                                                                     | 4800     |          | 12909                  |           | 3239.9    |               |          |
|                                                                                | AFL     | 6239                                                                                                                                                                                     |          |          |                        |           |           |               |          |
| PROC. REF: AMM 05-10-00, AMM 55-10-00PROC. REF: AMM 05-10-00, AMM 55-10-00     |         |                                                                                                                                                                                          |          |          |                        |           |           |               |          |
|                                                                                |         |                                                                                                                                                                                          |          |          |                        |           |           |               |          |
| 551005                                                                         |         | HORIZONTAL STABILIZER ASSEMBLY                                                                                                                                                           |          |          |                        |           |           | Component     | ATA:55   |
| PN:PN                                                                          | MOS/MSC | 02-Aug-24                                                                                                                                                                                | O/C      |          |                        |           |           |               |          |
| SN:UNKNOWN                                                                     | HRS     | 9525.7                                                                                                                                                                                   |          |          |                        |           |           |               |          |
|                                                                                | AFL     | 7276                                                                                                                                                                                     |          |          |                        |           |           |               |          |
| Special Properties: RII ITEM<br>PROC. REF: AMM 27-40-01PROC. REF: AMM 27-40-01 |         |                                                                                                                                                                                          |          |          |                        |           |           |               |          |
|                                                                                |         |                                                                                                                                                                                          |          |          |                        |           |           |               |          |
| 552031                                                                         |         | LEFT ELEVATOR ASSEMBLY                                                                                                                                                                   |          |          |                        |           |           | Component     | ATA:55   |
| PN:4555201005-011                                                              | MOS/MSC | 02-Aug-24                                                                                                                                                                                | O/C      |          |                        |           |           |               |          |
| SN:UNKNOWN                                                                     | HRS     | 9525.7                                                                                                                                                                                   |          |          |                        |           |           |               |          |
|                                                                                | AFL     | 7276                                                                                                                                                                                     |          |          |                        |           |           |               |          |
| Special Properties: RII ITEM<br>PROC. REF: AMM 27-30-01PROC. REF: AMM 27-30-01 |         |                                                                                                                                                                                          |          |          |                        |           |           |               |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|---------|------|-----|----------|----------|------------------------|-----------|-----------|-------------|----------|
|---------|------|-----|----------|----------|------------------------|-----------|-----------|-------------|----------|

ATA 55 - STABILIZERS

|                                                |                         |           |     |  |  |  |  |           |        |
|------------------------------------------------|-------------------------|-----------|-----|--|--|--|--|-----------|--------|
| 552032                                         | RIGHT ELEVATOR ASSEMBLY |           |     |  |  |  |  | Component | ATA:55 |
| PN:4555201005-012                              | MOS/MSC                 | 02-Aug-24 | O/C |  |  |  |  |           |        |
| SN:UNKNOWN                                     | HRS                     | 9525.7    |     |  |  |  |  |           |        |
|                                                | AFL                     | 7276      |     |  |  |  |  |           |        |
| Special Properties: RII ITEM                   |                         |           |     |  |  |  |  |           |        |
| PROC. REF: AMM 27-30-01PROC. REF: AMM 27-30-01 |                         |           |     |  |  |  |  |           |        |

|                                                    |                                       |           |     |       |  |  |  |           |        |
|----------------------------------------------------|---------------------------------------|-----------|-----|-------|--|--|--|-----------|--------|
| 553000                                             | TAILCONE/VERTICAL STABILIZER ASSEMBLY |           |     |       |  |  |  | Component | ATA:55 |
| PN:PN                                              | MOS/MSC                               | 09-Mar-01 | O/C | TSN 0 |  |  |  |           |        |
| SN:UNKNOWN                                         | HRS                                   | 0         |     | TSN 0 |  |  |  |           |        |
|                                                    | AFL                                   | 0         |     | TSN 0 |  |  |  |           |        |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                       |           |     |       |  |  |  |           |        |

|                                                |                 |           |     |  |  |  |  |           |        |
|------------------------------------------------|-----------------|-----------|-----|--|--|--|--|-----------|--------|
| 554005                                         | RUDDER ASSEMBLY |           |     |  |  |  |  | Component | ATA:55 |
| PN:4555401000-023                              | MOS/MSC         | 02-Aug-24 | O/C |  |  |  |  |           |        |
| SN:UNKNOWN                                     | HRS             | 9525.7    |     |  |  |  |  |           |        |
|                                                | AFL             | 7276      |     |  |  |  |  |           |        |
| Special Properties: RII ITEM                   |                 |           |     |  |  |  |  |           |        |
| PROC. REF: AMM 27-20-01PROC. REF: AMM 27-20-01 |                 |           |     |  |  |  |  |           |        |

|                                                              |                                                                                                                          |           |      |  |  |  |  |               |        |
|--------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------|-----------|------|--|--|--|--|---------------|--------|
| N5510005 <sup>S</sup>                                        | PERFORM * HORIZONTAL STABILIZER REAR SPAR CAP - EDDY CURRENT INSPECTION. INSPECT REAR SPAR CAP AND WEB AT CENTER SPLICE. |           |      |  |  |  |  | Service       | ATA:55 |
|                                                              | MOS                                                                                                                      | 25-Nov-19 | 96   |  |  |  |  | AIRWORTHINESS |        |
|                                                              | HRS                                                                                                                      | 8177.7    | 2400 |  |  |  |  |               |        |
|                                                              | AFL                                                                                                                      | 6303      |      |  |  |  |  |               |        |
|                                                              |                                                                                                                          |           |      |  |  |  |  |               | PKG:20 |
| PROC. REF: NDT PART 6/55-10-05PROC. REF: NDT PART 6/55-10-05 |                                                                                                                          |           |      |  |  |  |  |               |        |

|                                                              |                                                                                  |           |      |  |  |  |  |               |        |
|--------------------------------------------------------------|----------------------------------------------------------------------------------|-----------|------|--|--|--|--|---------------|--------|
| N5510015 <sup>S</sup>                                        | PERFORM * VERTICAL STABILIZER PIVOT FITTING TOP PLATE - EDDY CURRENT INSPECTION. |           |      |  |  |  |  | Service       | ATA:55 |
|                                                              | MOS                                                                              | 25-Nov-19 | 96   |  |  |  |  | AIRWORTHINESS |        |
|                                                              | HRS                                                                              | 8177.7    | 2400 |  |  |  |  |               |        |
|                                                              | AFL                                                                              | 6303      |      |  |  |  |  |               |        |
|                                                              |                                                                                  |           |      |  |  |  |  |               | PKG:20 |
| PROC. REF: NDT PART 6/55-30-02PROC. REF: NDT PART 6/55-30-02 |                                                                                  |           |      |  |  |  |  |               |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|---------|------|-----|----------|----------|------------------------|-----------|-----------|-------------|----------|
|---------|------|-----|----------|----------|------------------------|-----------|-----------|-------------|----------|

ATA 55 - STABILIZERS

|                                                              |              |                                                                                                                                                                                                                                                           |      |  |  |  |  |               |        |
|--------------------------------------------------------------|--------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|--|--|--|--|---------------|--------|
| N5510016                                                     | <sup>S</sup> | PERFORM * VERTICAL STABILIZER PIVOT FITTING TOWER SECTION FORWARD RADIUS - EDDY CURRENT INSPECTION. INSPECT PIVOT FITTING AT TOWER SECTION RADIUS, PIVOT FITTING AND TOP PLATE AROUND ADJACENT FASTENERS, AND PIVOT FITTING SIDES AT TOWER SECTION RADIUS |      |  |  |  |  | Service       | ATA:55 |
|                                                              | MOS          | 25-Nov-19                                                                                                                                                                                                                                                 | 96   |  |  |  |  | AIRWORTHINESS |        |
|                                                              | HRS          | 8177.7                                                                                                                                                                                                                                                    | 2400 |  |  |  |  |               |        |
|                                                              | AFL          | 6303                                                                                                                                                                                                                                                      |      |  |  |  |  |               |        |
|                                                              |              |                                                                                                                                                                                                                                                           |      |  |  |  |  |               | PKG:20 |
| PROC. REF: NDT PART 6/55-30-03PROC. REF: NDT PART 6/55-30-03 |              |                                                                                                                                                                                                                                                           |      |  |  |  |  |               |        |

|                                                              |              |                                                                                               |      |  |  |  |  |               |        |
|--------------------------------------------------------------|--------------|-----------------------------------------------------------------------------------------------|------|--|--|--|--|---------------|--------|
| N5510069                                                     | <sup>S</sup> | PERFORM * HORIZONTAL STABILIZER MID SPAR FLANGE ROOT RIB ATTACHMENT - EDDY CURRENT INSPECTION |      |  |  |  |  | Service       | ATA:55 |
|                                                              | MOS          | 25-Nov-19                                                                                     | 96   |  |  |  |  | AIRWORTHINESS |        |
|                                                              | HRS          | 8177.7                                                                                        | 2400 |  |  |  |  |               |        |
|                                                              | AFL          | 6303                                                                                          |      |  |  |  |  |               |        |
|                                                              |              |                                                                                               |      |  |  |  |  |               | PKG:20 |
| PROC. REF: NDT PART 6/55-10-02PROC. REF: NDT PART 6/55-10-02 |              |                                                                                               |      |  |  |  |  |               |        |

|                                                              |              |                                                                                                |      |  |  |  |  |               |        |
|--------------------------------------------------------------|--------------|------------------------------------------------------------------------------------------------|------|--|--|--|--|---------------|--------|
| N5510082                                                     | <sup>S</sup> | PERFORM * HORIZONTAL STABILIZER REAR SPAR FLANGE ROOT RIB ATTACHMENT - EDDY CURRENT INSPECTION |      |  |  |  |  | Service       | ATA:55 |
|                                                              | MOS          | 25-Nov-19                                                                                      | 96   |  |  |  |  | AIRWORTHINESS |        |
|                                                              | HRS          | 8177.7                                                                                         | 2400 |  |  |  |  |               |        |
|                                                              | AFL          | 6303                                                                                           |      |  |  |  |  |               |        |
|                                                              |              |                                                                                                |      |  |  |  |  |               | PKG:20 |
| PROC. REF: NDT PART 6/55-10-04PROC. REF: NDT PART 6/55-10-04 |              |                                                                                                |      |  |  |  |  |               |        |

ATA 56 - WINDOWS

|                                                                            |                                                                                |           |    |        |           |  |       |               |        |
|----------------------------------------------------------------------------|--------------------------------------------------------------------------------|-----------|----|--------|-----------|--|-------|---------------|--------|
| 5-19-00-W5600002                                                           | ** WINDSHIELD - PERFORM RAIN REMOVAL COATING EFFECTIVENESS TEST (IRN W5600002) |           |    |        |           |  |       | Service       | ATA:56 |
|                                                                            | MOS                                                                            | 21-Feb-25 | 12 | Adj 6d | 27-Feb-26 |  | 331 d | AIRWORTHINESS |        |
|                                                                            | HRS                                                                            | 9637.3    |    |        |           |  |       |               |        |
|                                                                            | AFL                                                                            | 7352      |    |        |           |  |       |               |        |
| PROC. REF: AMM 56-10-01, AMM 56-10-01PROC. REF: AMM 56-10-01, AMM 56-10-01 |                                                                                |           |    |        |           |  |       |               |        |

|                                                                            |                          |           |     |  |  |  |  |           |        |
|----------------------------------------------------------------------------|--------------------------|-----------|-----|--|--|--|--|-----------|--------|
| 561001                                                                     | LEFT WINDSHIELD ASSEMBLY |           |     |  |  |  |  | Component | ATA:56 |
| PN:6656100000-001                                                          | MOS/MSC                  | 02-Aug-24 | O/C |  |  |  |  |           |        |
| SN:1121                                                                    | HRS                      | 9525.7    |     |  |  |  |  |           |        |
|                                                                            | AFL                      | 7276      |     |  |  |  |  |           |        |
| Special Properties: RII ITEM                                               |                          |           |     |  |  |  |  |           |        |
| PROC. REF: AMM 56-10-01, AMM 56-10-01PROC. REF: AMM 56-10-01, AMM 56-10-01 |                          |           |     |  |  |  |  |           |        |

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                                                    | Unit                                                                            | C/W       | Interval | TSX/Adj.   | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty         |
|----------------------------------------------------------------------------|---------------------------------------------------------------------------------|-----------|----------|------------|------------------------|-----------|-----------|---------------|------------------|
| ATA 56 - WINDOWS                                                           |                                                                                 |           |          |            |                        |           |           |               |                  |
| 561001A                                                                    | ULTRASONIC-INSPECTION LEFT WINDSHIELD ASSEMBLY STRUCTURAL PLIES (IRN N5600003)  |           |          |            |                        |           |           |               | Service ATA:56   |
| PN:6656100000-001                                                          | MOS/MSC                                                                         | 02-Aug-24 | N/A      |            |                        |           |           | AIRWORTHINESS |                  |
| SN:1121                                                                    | HRS                                                                             | 9525.7    |          |            |                        |           |           |               |                  |
|                                                                            | AFL                                                                             | 7276      |          |            |                        |           |           |               |                  |
| PROC. REF: NDT PART 4/56-10-01PROC. REF: NDT PART 4/56-10-01               |                                                                                 |           |          |            |                        |           |           |               |                  |
| 561001B                                                                    | PERFORM INSPECTION LEFT WINDSHIELD ASSEMBLY BOLT HOLES (IRN N5600012)           |           |          |            |                        |           |           |               | Service ATA:56   |
| PN:6656100000-001                                                          | MOS                                                                             | 02-Aug-24 |          |            |                        |           |           | AIRWORTHINESS |                  |
| SN:1121                                                                    | HRS                                                                             | 9525.7    | 4800     |            | 14325.7                |           | 4656.6    |               |                  |
|                                                                            | AFL                                                                             | 7276      |          |            |                        |           |           |               |                  |
| PROC. REF: AMM 56-10-01PROC. REF: AMM 56-10-01                             |                                                                                 |           |          |            |                        |           |           |               |                  |
| 561002                                                                     | RIGHT WINDSHIELD ASSEMBLY                                                       |           |          |            |                        |           |           |               | Component ATA:56 |
| PN:6656100001-002                                                          | MOS/MSC                                                                         | 02-Aug-24 | O/C      | TSN 152    |                        |           |           |               |                  |
| SN:1222                                                                    | HRS                                                                             | 9525.7    |          | TSN 2762.2 |                        |           |           |               |                  |
|                                                                            | AFL                                                                             | 7276      |          | TSN 2118   |                        |           |           |               |                  |
| Special Properties: RII ITEM                                               |                                                                                 |           |          |            |                        |           |           |               |                  |
| PROC. REF: AMM 56-10-01, AMM 56-10-01PROC. REF: AMM 56-10-01, AMM 56-10-01 |                                                                                 |           |          |            |                        |           |           |               |                  |
| 561002A                                                                    | ULTRASONIC-INSPECTION RIGHT WINDSHIELD ASSEMBLY STRUCTURAL PLIES (IRN N5600003) |           |          |            |                        |           |           |               | Service ATA:56   |
| PN:6656100001-002                                                          | MOS/MSC                                                                         | 02-Aug-24 | N/A      |            |                        |           |           | AIRWORTHINESS |                  |
| SN:1222                                                                    | HRS                                                                             | 9525.7    |          |            |                        |           |           |               |                  |
|                                                                            | AFL                                                                             | 7276      |          |            |                        |           |           |               |                  |
| PROC. REF: NDT PART 4/56-10-01PROC. REF: NDT PART 4/56-10-01               |                                                                                 |           |          |            |                        |           |           |               |                  |
| 561002B                                                                    | PERFORM INSPECTION RIGHT WINDSHIELD ASSEMBLY BOLT HOLE (IRN N5600012)           |           |          |            |                        |           |           |               | Service ATA:56   |
| PN:6656100001-002                                                          | MOS                                                                             | 02-Aug-24 |          |            |                        |           |           | AIRWORTHINESS |                  |
| SN:1222                                                                    | HRS                                                                             | 9525.7    | 4800     |            | 14325.7                |           | 4656.6    |               |                  |
|                                                                            | AFL                                                                             | 7276      |          |            |                        |           |           |               |                  |
| PROC. REF: AMM 56-10-01PROC. REF: AMM 56-10-01                             |                                                                                 |           |          |            |                        |           |           |               |                  |
| 562010-1                                                                   | LEFT NO.1 WINDOW CABIN                                                          |           |          |            |                        |           |           |               | Component ATA:56 |
| PN:PN                                                                      | MOS/MSC                                                                         | 09-Mar-01 | O/C      | TSN 0      |                        |           |           |               |                  |
| SN:UNKNOWN                                                                 | HRS                                                                             | 0         |          | TSN 0      |                        |           |           |               |                  |
|                                                                            | AFL                                                                             | 0         |          | TSN 0      |                        |           |           |               |                  |
| PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01                             |                                                                                 |           |          |            |                        |           |           |               |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR    Serial: 45-145    RegNo: N942FK    HRS: 9669.1    AFL: 7372    As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                        | Unit    | C / W                            | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|------------------------------------------------|---------|----------------------------------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 56 - WINDOWS                               |         |                                  |          |          |                        |           |           |             |          |
| 562010-10                                      |         | RIGHT NO.5 WINDOW CABIN          |          |          |                        |           |           | Component   | ATA:56   |
| PN:7656202000-015                              | MOS/MSC | 22-Dec-08                        | O/C      | TSN 0    |                        |           |           |             |          |
| SN:4621                                        | HRS     | 6088.5                           |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL     | 4660                             |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01 |         |                                  |          |          |                        |           |           |             |          |
| 562010-11                                      |         | LEFT NO.6 WINDOW CABIN           |          |          |                        |           |           | Component   | ATA:56   |
| PN:PN                                          | MOS/MSC | 09-Mar-01                        | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS     | 0                                |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL     | 0                                |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01 |         |                                  |          |          |                        |           |           |             |          |
| 562010-12                                      |         | RIGHT NO.6 EMERGENCY EXIT WINDOW |          |          |                        |           |           | Component   | ATA:56   |
| PN:7656202000-015                              | MOS/MSC | 19-Dec-10                        | O/C      |          |                        |           |           |             |          |
| SN:5304                                        | HRS     | 6457.2                           |          |          |                        |           |           |             |          |
|                                                | AFL     | 4944                             |          |          |                        |           |           |             |          |
| PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01 |         |                                  |          |          |                        |           |           |             |          |
| 562010-13                                      |         | LEFT NO.7 WINDOW CABIN           |          |          |                        |           |           | Component   | ATA:56   |
| PN:7656202000-015                              | MOS/MSC | 28-Jun-16                        | O/C      | TSN 0    |                        |           |           |             |          |
| SN:6187                                        | HRS     | 7635.4                           |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL     | 5831                             |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01 |         |                                  |          |          |                        |           |           |             |          |
| 562010-14                                      |         | RIGHT NO.7 WINDOW CABIN          |          |          |                        |           |           | Component   | ATA:56   |
| PN:7656202000-015                              | MOS/MSC | 17-Feb-05                        | O/C      |          |                        |           |           |             |          |
| SN:0601                                        | HRS     | 3300.2                           |          |          |                        |           |           |             |          |
|                                                | AFL     | 2515                             |          |          |                        |           |           |             |          |
| PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01 |         |                                  |          |          |                        |           |           |             |          |
| 562010-15                                      |         | LEFT NO.8 WINDOW CABIN           |          |          |                        |           |           | Component   | ATA:56   |
| PN:PN                                          | MOS/MSC | 09-Mar-01                        | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS     | 0                                |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL     | 0                                |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01 |         |                                  |          |          |                        |           |           |             |          |

?-Insufficient Information    S-Suppressed Requirement    \*-Estimated Due(New Requirement)    (EFF)-Effective C/W    (M)-Manual Due    U-User Task    Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                        | Unit                        | C / W     | Interval | TSX / Adj. | Next Due (ENG / APU) A / C | Max Limit | Remaining | Disposition | Warranty         |
|------------------------------------------------|-----------------------------|-----------|----------|------------|----------------------------|-----------|-----------|-------------|------------------|
| ATA 56 - WINDOWS                               |                             |           |          |            |                            |           |           |             |                  |
| 562010-16                                      | EMERGENCY EXIT WINDOW CABIN |           |          |            |                            |           |           |             | Component ATA:56 |
| PN:7656202000-015                              | MOS/MSC                     | 13-Dec-10 | O/C      | TSN 0      |                            |           |           |             |                  |
| SN:5304                                        | HRS                         | 6457.2    |          | TSN 0      |                            |           |           |             |                  |
|                                                | AFL                         | 4944      |          | TSN 0      |                            |           |           |             |                  |
| PROC. REF: AMM 52-20-06PROC. REF: AMM 52-20-06 |                             |           |          |            |                            |           |           |             |                  |
| 562010-2                                       | RIGHT NO.1 WINDOW CABIN     |           |          |            |                            |           |           |             | Component ATA:56 |
| PN:7656202000-015                              | MOS/MSC                     | 21-Jun-05 | O/C      |            |                            |           |           |             |                  |
| SN:1340                                        | HRS                         | 3694.5    |          |            |                            |           |           |             |                  |
|                                                | AFL                         | 2785      |          |            |                            |           |           |             |                  |
| PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01 |                             |           |          |            |                            |           |           |             |                  |
| 562010-3                                       | LEFT NO.2 WINDOW CABIN      |           |          |            |                            |           |           |             | Component ATA:56 |
| PN:7656202000-015                              | MOS/MSC                     | 22-Dec-08 | O/C      | TSN 0      |                            |           |           |             |                  |
| SN:4456                                        | HRS                         | 6088.5    |          | TSN 0      |                            |           |           |             |                  |
|                                                | AFL                         | 4660      |          | TSN 0      |                            |           |           |             |                  |
| PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01 |                             |           |          |            |                            |           |           |             |                  |
| 562010-4                                       | RIGHT NO.2 WINDOW CABIN     |           |          |            |                            |           |           |             | Component ATA:56 |
| PN:7656202000-015                              | MOS/MSC                     | 17-Feb-05 | O/C      |            |                            |           |           |             |                  |
| SN:0847                                        | HRS                         | 3300.2    |          |            |                            |           |           |             |                  |
|                                                | AFL                         | 2515      |          |            |                            |           |           |             |                  |
| PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01 |                             |           |          |            |                            |           |           |             |                  |
| 562010-5                                       | LEFT NO.3 WINDOW CABIN      |           |          |            |                            |           |           |             | Component ATA:56 |
| PN:7656202000-015                              | MOS/MSC                     | 22-Dec-08 | O/C      | TSN 0      |                            |           |           |             |                  |
| SN:4505                                        | HRS                         | 6088.5    |          | TSN 0      |                            |           |           |             |                  |
|                                                | AFL                         | 4660      |          | TSN 0      |                            |           |           |             |                  |
| PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01 |                             |           |          |            |                            |           |           |             |                  |
| 562010-6                                       | RIGHT NO.3 WINDOW CABIN     |           |          |            |                            |           |           |             | Component ATA:56 |
| PN:7656202000-015                              | MOS/MSC                     | 22-Dec-08 | O/C      | TSN 0      |                            |           |           |             |                  |
| SN:4458                                        | HRS                         | 6088.5    |          | TSN 0      |                            |           |           |             |                  |
|                                                | AFL                         | 4660      |          | TSN 0      |                            |           |           |             |                  |
| PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01 |                             |           |          |            |                            |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN | Unit | C / W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|---------|------|-------|----------|----------|------------------------|-----------|-----------|-------------|----------|
|---------|------|-------|----------|----------|------------------------|-----------|-----------|-------------|----------|

ATA 56 - WINDOWS

|                                                |                        |           |     |       |  |  |  |           |        |
|------------------------------------------------|------------------------|-----------|-----|-------|--|--|--|-----------|--------|
| 562010-7                                       | LEFT NO.4 WINDOW CABIN |           |     |       |  |  |  | Component | ATA:56 |
| PN:PN                                          | MOS/MSC                | 09-Mar-01 | O/C | TSN 0 |  |  |  |           |        |
| SN:UNKNOWN                                     | HRS                    | 0         |     | TSN 0 |  |  |  |           |        |
|                                                | AFL                    | 0         |     | TSN 0 |  |  |  |           |        |
| PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01 |                        |           |     |       |  |  |  |           |        |

|                                                |                         |           |     |       |  |  |  |           |        |
|------------------------------------------------|-------------------------|-----------|-----|-------|--|--|--|-----------|--------|
| 562010-8                                       | RIGHT NO.4 WINDOW CABIN |           |     |       |  |  |  | Component | ATA:56 |
| PN:7656202000-015                              | MOS/MSC                 | 17-Dec-10 | O/C | TSN 0 |  |  |  |           |        |
| SN:5310                                        | HRS                     | 6457.2    |     | TSN 0 |  |  |  |           |        |
|                                                | AFL                     | 4944      |     | TSN 0 |  |  |  |           |        |
| PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01 |                         |           |     |       |  |  |  |           |        |

|                                                |                        |           |     |       |  |  |  |           |        |
|------------------------------------------------|------------------------|-----------|-----|-------|--|--|--|-----------|--------|
| 562010-9                                       | LEFT NO.5 WINDOW CABIN |           |     |       |  |  |  | Component | ATA:56 |
| PN:7656202000-015                              | MOS/MSC                | 15-Dec-10 | O/C | TSN 0 |  |  |  |           |        |
| SN:5307                                        | HRS                    | 6457.2    |     | TSN 0 |  |  |  |           |        |
|                                                | AFL                    | 4944      |     | TSN 0 |  |  |  |           |        |
| PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01 |                        |           |     |       |  |  |  |           |        |

|                                                |                                                                 |           |     |  |  |  |  |         |        |
|------------------------------------------------|-----------------------------------------------------------------|-----------|-----|--|--|--|--|---------|--------|
| Y5600000 <sup>S</sup>                          | WINDSHIELDS - PERFORM VISUAL INSPECTION (INTERIOR AND EXTERIOR) |           |     |  |  |  |  | Service | ATA:56 |
|                                                | MOS                                                             | 02-Aug-24 | 12  |  |  |  |  |         |        |
|                                                | HRS                                                             | 9525.7    | 300 |  |  |  |  |         |        |
|                                                | AFL                                                             | 7276      |     |  |  |  |  |         |        |
|                                                |                                                                 |           |     |  |  |  |  |         | PKG:1  |
| PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00 |                                                                 |           |     |  |  |  |  |         |        |

|                                                |                                           |           |     |  |  |  |  |         |        |
|------------------------------------------------|-------------------------------------------|-----------|-----|--|--|--|--|---------|--------|
| Y5600001 <sup>S</sup>                          | CABIN WINDOWS - PERFORM VISUAL INSPECTION |           |     |  |  |  |  | Service | ATA:56 |
|                                                | MOS                                       | 02-Aug-24 | 24  |  |  |  |  |         |        |
|                                                | HRS                                       | 9525.7    | 600 |  |  |  |  |         |        |
|                                                | AFL                                       | 7276      |     |  |  |  |  |         |        |
|                                                |                                           |           |     |  |  |  |  |         | PKG:7  |
| PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00 |                                           |           |     |  |  |  |  |         |        |

|                       |                                                                                                                        |           |     |  |  |  |  |         |        |
|-----------------------|------------------------------------------------------------------------------------------------------------------------|-----------|-----|--|--|--|--|---------|--------|
| Y5600013 <sup>S</sup> | WINDSHIELDS - PERFORM VISUAL INSPECTION OF THE AERODYNAMIC SEAL. IF REPAIRS TO THE SEAL ARE NEEDED, REFER TO 56-10-01. |           |     |  |  |  |  | Service | ATA:56 |
|                       | MOS                                                                                                                    | 02-Aug-24 | 12  |  |  |  |  |         |        |
|                       | HRS                                                                                                                    | 9525.7    | 300 |  |  |  |  |         |        |
|                       | AFL                                                                                                                    | 7276      |     |  |  |  |  |         |        |
|                       |                                                                                                                        |           |     |  |  |  |  |         | PKG:1  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                                                    | Unit                                                                                                                        | C/W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty |
|----------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------|---------|----------|----------|------------------------|-----------|-----------|---------------|----------|
| ATA 56 - WINDOWS                                                           |                                                                                                                             |         |          |          |                        |           |           |               |          |
| PROC. REF: AMM 56-10-01, AMM 56-10-01PROC. REF: AMM 56-10-01, AMM 56-10-01 |                                                                                                                             |         |          |          |                        |           |           |               |          |
| ATA 57 - WINGS                                                             |                                                                                                                             |         |          |          |                        |           |           |               |          |
| 5-19-00-E5750051                                                           | VISUALLY INSPECT * FLAP MAIN TRACK ROLLERS WITH FLAPS REMOVED (IRN E5750051)                                                |         |          |          |                        |           |           | Service       | ATA:57   |
| MOS                                                                        | 09-Mar-01                                                                                                                   |         |          |          |                        |           |           | AIRWORTHINESS |          |
| HRS                                                                        | 0                                                                                                                           | T:10000 |          |          | 10000                  |           | 330.9     |               |          |
| AFL                                                                        | 0                                                                                                                           |         |          |          |                        |           |           |               |          |
| PROC. REF: AMM 05-10-00, AMM 27-50-01PROC. REF: AMM 05-10-00, AMM 27-50-01 |                                                                                                                             |         |          |          |                        |           |           |               |          |
| 5-19-00-E5750052                                                           | VISUALLY INSPECT * FLAP NOSE ROLLERS WITH FLAPS REMOVED (IRN E5750052)                                                      |         |          |          |                        |           |           | Service       | ATA:57   |
| MOS                                                                        | 22-Jun-23                                                                                                                   |         |          |          |                        |           |           | AIRWORTHINESS |          |
| HRS                                                                        | 9258.5                                                                                                                      | 600     |          |          | 9858.5                 |           | 189.4     |               |          |
| AFL                                                                        | 7100                                                                                                                        |         |          |          |                        |           |           |               |          |
| PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00                             |                                                                                                                             |         |          |          |                        |           |           |               |          |
| 5-19-00-N5710002                                                           | VISUALLY INSPECT * WING BOX MID SPAR LOWER CAP, OUTBOARD OF JOINT AT WS 137 BETWEEN RIBS 7 AND 8. N5710002 (PRE SB 45-11-5) |         |          |          |                        |           |           | Service       | ATA:57   |
| MOS                                                                        | 02-Aug-24                                                                                                                   |         |          |          |                        |           |           | AIRWORTHINESS |          |
| HRS                                                                        | 9525.7                                                                                                                      | 3580    |          |          | 13105.7                |           | 3436.6    |               |          |
| AFL                                                                        | 7276                                                                                                                        |         |          |          |                        |           |           |               |          |
| PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00                             |                                                                                                                             |         |          |          |                        |           |           |               |          |
| 5-19-00-N5710008                                                           | NON DESTRUCTIVE INSPECT * WING BOX SPAR LOWER CAP - PERFORM NDI INSPECTION. N5710008 (PRE SB 45-11-5)                       |         |          |          |                        |           |           | Service       | ATA:57   |
| MOS                                                                        | 02-Aug-24                                                                                                                   |         |          |          |                        |           |           | AIRWORTHINESS |          |
| HRS                                                                        | 9525.7                                                                                                                      | 2500    |          |          | 12025.7                |           | 2356.6    |               |          |
| AFL                                                                        | 7276                                                                                                                        |         |          |          |                        |           |           |               |          |
| PROC. REF: NDT PART 4/57-30-03PROC. REF: NDT PART 4/57-30-03               |                                                                                                                             |         |          |          |                        |           |           |               |          |
| 5-19-00-N5710009                                                           | NON DESTRUCTIVE TEST * WING BOX MID SPAR LOWER CAP JOINT AT WS 137 - PERFORM NDI INSPECTION. N5710009 (PRE SB 45-11-5)      |         |          |          |                        |           |           | Service       | ATA:57   |
| MOS                                                                        | 02-Aug-24                                                                                                                   |         |          |          |                        |           |           | AIRWORTHINESS |          |
| HRS                                                                        | 9525.7                                                                                                                      | 4517    |          |          | 14042.7                |           | 4373.6    |               |          |
| AFL                                                                        | 7276                                                                                                                        |         |          |          |                        |           |           |               |          |
| PROC. REF: NDT PART 2/57-10-02PROC. REF: NDT PART 2/57-10-02               |                                                                                                                             |         |          |          |                        |           |           |               |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9669.1
 AFL: 7372
 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                                      | Unit                                                                                                                                                                                                                                                                                                                              | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty |
|--------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|---------------|----------|
| ATA 57 - WINGS                                               |                                                                                                                                                                                                                                                                                                                                   |           |          |          |                        |           |           |               |          |
| 5-19-00-N5710010                                             | NON DESTRUCTIVE INSPECT * WING BOX REAR SPAR LOWER CAP INBOARD OF JOINT WS 81 - PERFORM NDI INSPECTION. N5710010 (PRE SB 45-11-5)                                                                                                                                                                                                 |           |          |          |                        |           |           | Service       | ATA:57   |
|                                                              | MOS                                                                                                                                                                                                                                                                                                                               | 02-Aug-24 |          |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                                                                                                                                                                                                                               | 9525.7    | 960      |          | 10485.7                |           | 816.6     |               |          |
|                                                              | AFL                                                                                                                                                                                                                                                                                                                               | 7276      |          |          |                        |           |           |               |          |
| PROC. REF: NDT PART 4/57-30-01PROC. REF: NDT PART 4/57-30-01 |                                                                                                                                                                                                                                                                                                                                   |           |          |          |                        |           |           |               |          |
| 5-19-00-N5710012                                             | * WING BOX REAR SPAR LOWER CAP OUTBOARD OF JOINT AT WS 81 TO RIB #6 - PERFORM DETAILED VISUAL INSPECTION. INSPECT OUTER REAR SPAR LOWER CAP ANDAFT LOWER SKIN PANEL OUTBOARD OF REAR SPLICE AT WS 90. (REFER TO 5-10-00.) (EFFECTIVE ON AIRCRAFT NOT MODIFIED BY SB 45-11-5, "INCREASE MAXIMUMZERO FUEL WEIGHT (16,500 POUNDS).") |           |          |          |                        |           |           | Service       | ATA:57   |
|                                                              | MOS                                                                                                                                                                                                                                                                                                                               | 02-Aug-24 |          |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                                                                                                                                                                                                                               | 9525.7    | 3443     |          | 12968.7                |           | 3299.6    |               |          |
|                                                              | AFL                                                                                                                                                                                                                                                                                                                               | 7276      |          |          |                        |           |           |               |          |
| PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00               |                                                                                                                                                                                                                                                                                                                                   |           |          |          |                        |           |           |               |          |
| 5-19-00-N5710013                                             | NON DESTRUCTIVE INSPECT * WING BOX REAR SPAR LOWER CAP SKIN TERMINATION AT MS 48 - PERFORM NDI INSPECTION. N5710013 (PRE SB 45-11-5)                                                                                                                                                                                              |           |          |          |                        |           |           | Service       | ATA:57   |
|                                                              | MOS                                                                                                                                                                                                                                                                                                                               | 09-Mar-01 |          |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                                                                                                                                                                                                                               | 0         | T:10000  |          | 10000                  |           | 330.9     |               |          |
|                                                              | AFL                                                                                                                                                                                                                                                                                                                               | 0         |          |          |                        |           |           |               |          |
| PROC. REF: NDT PART 6/57-20-04PROC. REF: NDT PART 6/57-20-04 |                                                                                                                                                                                                                                                                                                                                   |           |          |          |                        |           |           |               |          |
| 5-19-00-N5710026                                             | NON DESTRUCTIVE INSPECT * WING BOX SPAR LOWER CAP - PERFORM NDI INSPECTION. INSPECT MID SPAR LOWER CAP OUTBOARD OF ROOT RIB AT WS 33 TO WS 99. N5710026 (PRE SB 45-11-5)                                                                                                                                                          |           |          |          |                        |           |           | Service       | ATA:57   |
|                                                              | MOS                                                                                                                                                                                                                                                                                                                               |           |          |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                                                                                                                                                                                                                               | 0         | T:10000  |          | 10000                  |           | 330.9     |               |          |
|                                                              | AFL                                                                                                                                                                                                                                                                                                                               |           |          |          |                        |           |           |               |          |
| PROC. REF: NDT PART 4/57-30-03PROC. REF: NDT PART 4/57-30-03 |                                                                                                                                                                                                                                                                                                                                   |           |          |          |                        |           |           |               |          |
| 5-19-00-N5710123                                             | EDDY CURRENT INSPECT * WING BOX MID SPAR LOWER CAP AT TRUNNION FITTING - PERFORM EDDY CURRENT INSPECTION AT TRUNNION FITTING. N5710123 (PRE SB 45-11-5)                                                                                                                                                                           |           |          |          |                        |           |           | Service       | ATA:57   |
|                                                              | MOS                                                                                                                                                                                                                                                                                                                               | 02-Aug-24 |          |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                                                                                                                                                                                                                               | 9525.7    | 2666     |          | 12191.7                |           | 2522.6    |               |          |
|                                                              | AFL                                                                                                                                                                                                                                                                                                                               | 7276      |          |          |                        |           |           |               |          |
| PROC. REF: NDT PART 6/57-10-01PROC. REF: NDT PART 6/57-10-01 |                                                                                                                                                                                                                                                                                                                                   |           |          |          |                        |           |           |               |          |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C/W   (M)-Manual Due   U-User Task   Ex-Excluded Task

## Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                                      | Unit                                                                                                                                                                                                                          | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|--------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 57 - WINGS                                               |                                                                                                                                                                                                                               |           |          |          |                        |           |           |             |          |
| 5-19-00-N5710148                                             | EDDY CURRENT INSPECTION * WING CENTER SECTION REAR SPAR - PERFORM EDDY CURRENT INSPECTION, INSPECT REAR SPAR LOWER CAP FROM CENTERLINE TO WS 33 N5710148 (POST SB 45-11-5)                                                    |           |          |          |                        |           |           | Service     | ATA:57   |
|                                                              | MOS/MSC                                                                                                                                                                                                                       | 09-Mar-01 | N/A      |          |                        |           |           |             |          |
|                                                              | HRS                                                                                                                                                                                                                           | 0         |          |          |                        |           |           |             |          |
|                                                              | AFL                                                                                                                                                                                                                           | 0         |          |          |                        |           |           |             |          |
| PROC. REF: NDT PART 6/57-20-02PROC. REF: NDT PART 6/57-20-02 |                                                                                                                                                                                                                               |           |          |          |                        |           |           |             |          |
| 5-19-00-N5710149                                             | EDDY CURRENT INSPECTION * WING CENTER SECTION FORWARD AND AFT RIBS AT WS6 AND FORWARD RIBS AT WS 17 - PERFORM EDDY CURRENT INSPECTION. N5710149 (POST SB 45-11-5)                                                             |           |          |          |                        |           |           | Service     | ATA:57   |
|                                                              | MOS/MSC                                                                                                                                                                                                                       | 09-Mar-01 | N/A      |          |                        |           |           |             |          |
|                                                              | HRS                                                                                                                                                                                                                           | 0         |          |          |                        |           |           |             |          |
|                                                              | AFL                                                                                                                                                                                                                           | 0         |          |          |                        |           |           |             |          |
| PROC. REF: NDT PART 6/57-10-06PROC. REF: NDT PART 6/57-10-06 |                                                                                                                                                                                                                               |           |          |          |                        |           |           |             |          |
| 5-19-00-N5710150                                             | ULTRASONIC-INSPECTION * WING BOX MID SPAR LOWER CAP - PERFORM ULTRASONIC INSPECTION, INSPECT MID SPAR LOWER CAP AND LOWER SKIN PANELS BETWEEN WS99 AND WS137. N5710150 (POST SB 45-11-5)                                      |           |          |          |                        |           |           | Service     | ATA:57   |
|                                                              | MOS/MSC                                                                                                                                                                                                                       | 09-Mar-01 | N/A      |          |                        |           |           |             |          |
|                                                              | HRS                                                                                                                                                                                                                           | 0         |          |          |                        |           |           |             |          |
|                                                              | AFL                                                                                                                                                                                                                           | 0         |          |          |                        |           |           |             |          |
| PROC. REF: NDT PART 4/57-30-03PROC. REF: NDT PART 4/57-30-03 |                                                                                                                                                                                                                               |           |          |          |                        |           |           |             |          |
| 5-19-00-N5710151                                             | X-RAY INSPECTION * WING BOX MID SPAR LOWER CAP JOINT AT WS137 - PERFORM X-RAY INSPECTION. INSPECT MID SPAR CENTER/OUTER JOINT. N5710151 (POST SB 45-11-5)                                                                     |           |          |          |                        |           |           | Service     | ATA:57   |
|                                                              | MOS/MSC                                                                                                                                                                                                                       | 09-Mar-01 | N/A      |          |                        |           |           |             |          |
|                                                              | HRS                                                                                                                                                                                                                           | 0         |          |          |                        |           |           |             |          |
|                                                              | AFL                                                                                                                                                                                                                           | 0         |          |          |                        |           |           |             |          |
| PROC. REF: NDT PART 2/57-10-02PROC. REF: NDT PART 2/57-10-02 |                                                                                                                                                                                                                               |           |          |          |                        |           |           |             |          |
| 5-19-00-N5710152                                             | ULTRASONIC-INSPECTION * WING BOX REAR SPAR LOWER CAP INBOARD OF JOINT AT WS81 - PERFORM ULTRASONIC INSPECTION, INSPECT REAR SPAR LOWER CAP BETWEEN SKIN TERMINATION AT WS 48 CLOSING RIB AT WS 60. N5710152 (POST SB 45-11-5) |           |          |          |                        |           |           | Service     | ATA:57   |
|                                                              | MOS/MSC                                                                                                                                                                                                                       | 09-Mar-01 | N/A      |          |                        |           |           |             |          |
|                                                              | HRS                                                                                                                                                                                                                           | 0         |          |          |                        |           |           |             |          |
|                                                              | AFL                                                                                                                                                                                                                           | 0         |          |          |                        |           |           |             |          |
| PROC. REF: NDT PART 4/57-30-01PROC. REF: NDT PART 4/57-30-01 |                                                                                                                                                                                                                               |           |          |          |                        |           |           |             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9669.1
 AFL: 7372
 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                                      | Unit                                                                                                                                                                                                                                          | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|--------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 57 - WINGS                                               |                                                                                                                                                                                                                                               |           |          |          |                        |           |           |             |          |
| 5-19-00-N5710153                                             | X-RAY INSPECTION * WING BOX REAR SPAR LOWER CAP JOINT AT WS 81 - PERFORM X-RAY INSPECTION. INSPECT CENTER AND OUTER REAR SPARS, LOWER SPLICE PLATE, AND LOWER SKIN BETWEEN WS 60 AND WS 90. N5710153 (POST SB 45-11-5)                        |           |          |          |                        |           |           | Service     | ATA:57   |
|                                                              | MOS/MSC                                                                                                                                                                                                                                       | 09-Mar-01 | N/A      |          |                        |           |           |             |          |
|                                                              | HRS                                                                                                                                                                                                                                           | 0         |          |          |                        |           |           |             |          |
|                                                              | AFL                                                                                                                                                                                                                                           | 0         |          |          |                        |           |           |             |          |
| PROC. REF: NDT PART 2/57-10-03PROC. REF: NDT PART 2/57-10-03 |                                                                                                                                                                                                                                               |           |          |          |                        |           |           |             |          |
| 5-19-00-N5710155                                             | EDDY CURRENT INSPECTION * WING BOX REAR SPAR LOWER CAP SKIN TERMINATION AT MS 48 - PERFORM EDDY CURRENT INSPECTION. INSPECT REAR SPAR LOWER CAP BETWEEN WS33 AND WS 48. N5710155 (POST SB 45-11-5)                                            |           |          |          |                        |           |           | Service     | ATA:57   |
|                                                              | MOS/MSC                                                                                                                                                                                                                                       | 09-Mar-01 | N/A      |          |                        |           |           |             |          |
|                                                              | HRS                                                                                                                                                                                                                                           | 0         |          |          |                        |           |           |             |          |
|                                                              | AFL                                                                                                                                                                                                                                           | 0         |          |          |                        |           |           |             |          |
| PROC. REF: NDT PART 6/57-20-04PROC. REF: NDT PART 6/57-20-04 |                                                                                                                                                                                                                                               |           |          |          |                        |           |           |             |          |
| 5-19-00-N5710158                                             | EDDY CURRENT INSPECTION * CENTER SECTION FRONT SPAR LOWER CAP - PEFORM EDDY CURRENT INSPECTION. INSPECT CENTER WING FRONT SPAR LOWER CAP BETWEEN SKIN TERMINATIONS (WS31 LEFT TO WS31 RIGHT) N5710158 (POST SB 45-11-5)                       |           |          |          |                        |           |           | Service     | ATA:57   |
|                                                              | MOS/MSC                                                                                                                                                                                                                                       | 09-Mar-01 | N/A      |          |                        |           |           |             |          |
|                                                              | HRS                                                                                                                                                                                                                                           | 0         |          |          |                        |           |           |             |          |
|                                                              | AFL                                                                                                                                                                                                                                           | 0         |          |          |                        |           |           |             |          |
| PROC. REF: NDT PART 6/57-10-03PROC. REF: NDT PART 6/57-10-03 |                                                                                                                                                                                                                                               |           |          |          |                        |           |           |             |          |
| 5-19-00-N5710159                                             | ULTRASONIC-INSPECTION * WING BOX MID SPAR LOWER CAP - PERFORM ULTRASONIC INSPECTION. INSPECT MID SPAR LOWER CAP OUTBOARD OF ROOT RIB AT WS 33 TO WS 99. N5710159 (POST SB 45-11-5)                                                            |           |          |          |                        |           |           | Service     | ATA:57   |
|                                                              | MOS/MSC                                                                                                                                                                                                                                       | 09-Mar-01 | N/A      |          |                        |           |           |             |          |
|                                                              | HRS                                                                                                                                                                                                                                           | 0         |          |          |                        |           |           |             |          |
|                                                              | AFL                                                                                                                                                                                                                                           | 0         |          |          |                        |           |           |             |          |
| PROC. REF: NDT PART 4/57-30-03PROC. REF: NDT PART 4/57-30-03 |                                                                                                                                                                                                                                               |           |          |          |                        |           |           |             |          |
| 5-19-00-N5710160                                             | EDDY CURRENT INSPECTION * WING BOX MID SPAR LOWER CAP, SKIN TERMINATION AT WS 33 - PERFORM BOLT HOLE EDDY CURRENT INSPECTION. INSPECT MID SPAR LOWER CAP UNDERNEATH ROOT RIB (WS 33) AT POINT OF SKIN TERMINATION. N5710160 (POST SB 45-11-5) |           |          |          |                        |           |           | Service     | ATA:57   |
|                                                              | MOS/MSC                                                                                                                                                                                                                                       | 09-Mar-01 | N/A      |          |                        |           |           |             |          |
|                                                              | HRS                                                                                                                                                                                                                                           | 0         |          |          |                        |           |           |             |          |
|                                                              | AFL                                                                                                                                                                                                                                           | 0         |          |          |                        |           |           |             |          |
| PROC. REF: NDT PART 6/57-10-11PROC. REF: NDT PART 6/57-10-11 |                                                                                                                                                                                                                                               |           |          |          |                        |           |           |             |          |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C/W   (M)-Manual Due   U-User Task   Ex-Excluded Task

# Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                                                                                | Unit                                                                                                                                                                                                                                             | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition    | Warranty |
|--------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|----------------|----------|
| ATA 57 - WINGS                                                                                         |                                                                                                                                                                                                                                                  |           |          |          |                        |           |           |                |          |
| 5-19-00-N5710163                                                                                       | EDDY CURRENT INSPECTION * CENTER SECTION MID SPAR CENTERLINE JOINT - PERFORM EDDY CURRENT INSPECTION. INSPECT CENTER MID SPAR (CENTERLINE TO WS 17), LOWER SPLICE PLATE, AND CENTER MID SPAR JOINT FITTING LOWER CAP. N5710163 (POST SB 45-11-5) |           |          |          |                        |           |           | Service        | ATA:57   |
|                                                                                                        | MOS/MSC                                                                                                                                                                                                                                          | 09-Mar-01 | N/A      |          |                        |           |           | NOT APPLICABLE |          |
|                                                                                                        | HRS                                                                                                                                                                                                                                              | 0         |          |          |                        |           |           |                |          |
|                                                                                                        | AFL                                                                                                                                                                                                                                              | 0         |          |          |                        |           |           |                |          |
| PROC. REF: NDT PART 6/57-10-08, NDT PART 6/57-10-10PROC. REF: NDT PART 6/57-10-08, NDT PART 6/57-10-10 |                                                                                                                                                                                                                                                  |           |          |          |                        |           |           |                |          |
| 5-19-00-N5710164                                                                                       | EDDY CURRENT INSPECTION * CENTER SECTION MID SPAR LOWER CAP - PEFORM EDDY CURRENT INSPECTION. INSPECT MID SPAR FROM CENTERLINE SPLICE PLATE TO SKIN TERMINATION AT MS 33. N5710164 (POST SB 45-11-5)                                             |           |          |          |                        |           |           | Service        | ATA:57   |
|                                                                                                        | MOS/MSC                                                                                                                                                                                                                                          | 09-Mar-01 | N/A      |          |                        |           |           |                |          |
|                                                                                                        | HRS                                                                                                                                                                                                                                              | 0         |          |          |                        |           |           |                |          |
|                                                                                                        | AFL                                                                                                                                                                                                                                              | 0         |          |          |                        |           |           |                |          |
| PROC. REF: NDT PART 6/57-10-02PROC. REF: NDT PART 6/57-10-02                                           |                                                                                                                                                                                                                                                  |           |          |          |                        |           |           |                |          |
| 5-19-00-N5710165                                                                                       | EDDY CURRENT INSPECTION * WING BOX REAR SPAR FLAP TRACK CUT-OUTS - PERFORM EDDY CURRENT INSPECTION. INSPECT FLAP TRACK CUT-OUTS AT WS65, WS 126 AND WS184 ON REAR SPAR. N5710165 (POST SB 45-11-5)                                               |           |          |          |                        |           |           | Service        | ATA:57   |
|                                                                                                        | MOS/MSC                                                                                                                                                                                                                                          | 09-Mar-01 | N/A      |          |                        |           |           |                |          |
|                                                                                                        | HRS                                                                                                                                                                                                                                              | 0         |          |          |                        |           |           |                |          |
|                                                                                                        | AFL                                                                                                                                                                                                                                              | 0         |          |          |                        |           |           |                |          |
| PROC. REF: NDT PART 6/57-20-01PROC. REF: NDT PART 6/57-20-01                                           |                                                                                                                                                                                                                                                  |           |          |          |                        |           |           |                |          |
| 5-19-00-N5710168                                                                                       | EDDY CURRENT INSPECTION * WING BOX MID SPAR LOWER CAP - PERFORM EDDY CURRENT INSPECTION AT TRUNNION FITTING. N5710168 (POST SB 45-11-5)                                                                                                          |           |          |          |                        |           |           | Service        | ATA:57   |
|                                                                                                        | MOS/MSC                                                                                                                                                                                                                                          | 09-Mar-01 | N/A      |          |                        |           |           |                |          |
|                                                                                                        | HRS                                                                                                                                                                                                                                              | 0         |          |          |                        |           |           |                |          |
|                                                                                                        | AFL                                                                                                                                                                                                                                              | 0         |          |          |                        |           |           |                |          |
| PROC. REF: NDT PART 6/57-10-01PROC. REF: NDT PART 6/57-10-01                                           |                                                                                                                                                                                                                                                  |           |          |          |                        |           |           |                |          |
| 5-19-00-N5710169                                                                                       | EDDY CURRENT INSPECTION * MID SPAR AT RIB #2 NEAR WS48 - PERFORM BOLT HOLE EDDY CURRENT INSPECTION. N5710169 (POST SB 45-11-5)                                                                                                                   |           |          |          |                        |           |           | Service        | ATA:57   |
|                                                                                                        | MOS/MSC                                                                                                                                                                                                                                          | 09-Mar-01 | N/A      |          |                        |           |           |                |          |
|                                                                                                        | HRS                                                                                                                                                                                                                                              | 0         |          |          |                        |           |           |                |          |
|                                                                                                        | AFL                                                                                                                                                                                                                                              | 0         |          |          |                        |           |           |                |          |
| PROC. REF: NDT PART 6/57-10-11APROC. REF: NDT PART 6/57-10-11A                                         |                                                                                                                                                                                                                                                  |           |          |          |                        |           |           |                |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                                       | Unit                                                                                                                                                                                          | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|---------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 57 - WINGS                                                |                                                                                                                                                                                               |           |          |          |                        |           |           |             |          |
| 5-19-00-N5710170                                              | EDDY CURRENT INSPECTION * MID SPAR AT RIB #3 NEAR WS60 - PERFORM BOLT HOLE EDDY CURRENT INSPECTION. N5710170 (POST SB 45-11-5)                                                                |           |          |          |                        |           |           | Service     | ATA:57   |
|                                                               | MOS/MSC                                                                                                                                                                                       | 09-Mar-01 | N/A      |          |                        |           |           |             |          |
|                                                               | HRS                                                                                                                                                                                           | 0         |          |          |                        |           |           |             |          |
|                                                               | AFL                                                                                                                                                                                           | 0         |          |          |                        |           |           |             |          |
| PROC. REF: NDT PART 6/57-10-11PROC. REF: NDT PART 6/57-10-11A |                                                                                                                                                                                               |           |          |          |                        |           |           |             |          |
| 5-19-00-N5710171                                              | EDDY CURRENT INSPECTION * FORWARD FLANGE FASTENERS AT REAR SPAR BETWEEN WS 52 AND WS 60 - PEROFRM BOLT HOLE EDDY CURRENT INSPECTION. N5710171 (POST SB 45-11-5)                               |           |          |          |                        |           |           | Service     | ATA:57   |
|                                                               | MOS/MSC                                                                                                                                                                                       | 09-Mar-01 | N/A      |          |                        |           |           |             |          |
|                                                               | HRS                                                                                                                                                                                           | 0         |          |          |                        |           |           |             |          |
|                                                               | AFL                                                                                                                                                                                           | 0         |          |          |                        |           |           |             |          |
| PROC. REF: NDT PART 6/57-20-03PROC. REF: NDT PART 6/57-20-03  |                                                                                                                                                                                               |           |          |          |                        |           |           |             |          |
| 5-19-00-N5710172                                              | ULTRASONIC-INSPECTION * WING BOX MID SPAR LOWER CAP - PERFORM ULTRASONIC INSPECTION AT TRUNNION FITTING. N5710172 (PRE SB 45-11-5)                                                            |           |          |          |                        |           |           | Service     | ATA:57   |
|                                                               | MOS                                                                                                                                                                                           | 02-Aug-24 |          |          |                        |           |           |             |          |
|                                                               | HRS                                                                                                                                                                                           | 9525.7    | 2666     |          | 12191.7                |           | 2522.6    |             |          |
|                                                               | AFL                                                                                                                                                                                           | 7276      |          |          |                        |           |           |             |          |
| PROC. REF: NDT PART 4/57-10-00PROC. REF: NDT PART 4/57-10-00  |                                                                                                                                                                                               |           |          |          |                        |           |           |             |          |
| 5-19-00-N5710173                                              | ULTRASONIC-INSPECTION * WING BOX MID SPAR LOWER CAP - PERFORM ULTRASONIC INSPECTION AT TRUNNION FITTING. N5710173 (POST SB 45-11-5)                                                           |           |          |          |                        |           |           | Service     | ATA:57   |
|                                                               | MOS/MSC                                                                                                                                                                                       | 09-Mar-01 | N/A      |          |                        |           |           |             |          |
|                                                               | HRS                                                                                                                                                                                           | 0         |          |          |                        |           |           |             |          |
|                                                               | AFL                                                                                                                                                                                           | 0         |          |          |                        |           |           |             |          |
| PROC. REF: NDT PART 4/57-10-00PROC. REF: NDT PART 4/57-10-00  |                                                                                                                                                                                               |           |          |          |                        |           |           |             |          |
| 5-19-00-N5710174                                              | ULTRASONIC-INSPECTION * WING BOX REAR SPAR LOWER CAP SKIN TERMINATION AT WS 48 - PEFORM ULTRASONIC INSPECTION. INSPECT REAR SPAR LOWER CAP BETWEEN WS 33 AND WS 48. N5710174 (PRE SB 45-11-5) |           |          |          |                        |           |           | Service     | ATA:57   |
|                                                               | MOS                                                                                                                                                                                           | 09-Mar-01 |          |          |                        |           |           |             |          |
|                                                               | HRS                                                                                                                                                                                           | 0         | T:10000  |          | 10000                  |           | 330.9     |             |          |
|                                                               | AFL                                                                                                                                                                                           | 0         |          |          |                        |           |           |             |          |
| PROC. REF: NDT PART 4/57-30-04PROC. REF: NDT PART 4/57-30-04  |                                                                                                                                                                                               |           |          |          |                        |           |           |             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                                      | Unit    | C/W                                                                                                                                                                                                                                | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|--------------------------------------------------------------|---------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 57 - WINGS                                               |         |                                                                                                                                                                                                                                    |          |          |                        |           |           |             |          |
| 5-19-00-N5710175                                             |         | ULTRASONIC-INSPECTION * WING BOX REAR SPAR LOWER CAP SKIN TERMINATION AT MS 48 - PERFORM ULTRASONIC INSPECTION. INSPECT REAR SPAR LOWER CAP BETWEEN WS 33 AND WS 48. N5710175 (POST SB 45-11-5)                                    |          |          |                        |           |           | Service     | ATA:57   |
|                                                              | MOS/MSC | 09-Mar-01                                                                                                                                                                                                                          | N/A      |          |                        |           |           |             |          |
|                                                              | HRS     | 0                                                                                                                                                                                                                                  |          |          |                        |           |           |             |          |
|                                                              | AFL     | 0                                                                                                                                                                                                                                  |          |          |                        |           |           |             |          |
| PROC. REF: NDT PART 4/57-30-04PROC. REF: NDT PART 4/57-30-04 |         |                                                                                                                                                                                                                                    |          |          |                        |           |           |             |          |
| 5-19-00-N5710177                                             |         | ULTRASONIC-INSPECTION * WING MID SPAR (CENTER SECTION) LOWER CAP AND CENTER JOINT FITTING - PERFORM ULTRASONIC INSPECTION. N5710177 (POST SB 45-11-5)                                                                              |          |          |                        |           |           | Service     | ATA:57   |
|                                                              | MOS/MSC | 09-Mar-01                                                                                                                                                                                                                          | N/A      |          |                        |           |           |             |          |
|                                                              | HRS     | 0                                                                                                                                                                                                                                  |          |          |                        |           |           |             |          |
|                                                              | AFL     | 0                                                                                                                                                                                                                                  |          |          |                        |           |           |             |          |
| PROC. REF: NDT PART 4/57-30-05PROC. REF: NDT PART 4/57-30-05 |         |                                                                                                                                                                                                                                    |          |          |                        |           |           |             |          |
| 571001                                                       |         | WING ASSEMBLY                                                                                                                                                                                                                      |          |          |                        |           |           | Component   | ATA:57   |
| PN:PN                                                        | MOS/MSC | 09-Mar-01                                                                                                                                                                                                                          | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                                   | HRS     | 0                                                                                                                                                                                                                                  |          | TSN 0    |                        |           |           |             |          |
|                                                              | AFL     | 0                                                                                                                                                                                                                                  |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 57-10-00PROC. REF: AMM 57-10-00               |         |                                                                                                                                                                                                                                    |          |          |                        |           |           |             |          |
| 571010                                                       |         | * REPLACE LEFT MAIN LANDING GEAR SIDE-STAY ACTUATOR FITTING                                                                                                                                                                        |          |          |                        |           |           | Component   | ATA:57   |
| PN:PN                                                        | MOS     | 09-Mar-01                                                                                                                                                                                                                          |          | TSN 0    |                        |           |           | LIFE LIMIT  |          |
| SN:UNKNOWN                                                   | HRS     | 0                                                                                                                                                                                                                                  |          | TSN 0    |                        |           |           |             |          |
|                                                              | AFL     | 0                                                                                                                                                                                                                                  | 20000    | TSN 0    | 20000                  |           | 12628     |             |          |
| PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01               |         |                                                                                                                                                                                                                                    |          |          |                        |           |           |             |          |
| 571011                                                       |         | * REPLACE RIGHT MAIN LANDING GEAR SIDE-STAY ACTUATOR FITTING                                                                                                                                                                       |          |          |                        |           |           | Component   | ATA:57   |
| PN:PN                                                        | MOS     | 09-Mar-01                                                                                                                                                                                                                          |          | TSN 0    |                        |           |           | LIFE LIMIT  |          |
| SN:UNKNOWN                                                   | HRS     | 0                                                                                                                                                                                                                                  |          | TSN 0    |                        |           |           |             |          |
|                                                              | AFL     | 0                                                                                                                                                                                                                                  | 20000    | TSN 0    | 20000                  |           | 12628     |             |          |
| PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01               |         |                                                                                                                                                                                                                                    |          |          |                        |           |           |             |          |
| 5710190                                                      |         | * LEFT WING CENTER SECTION (PANELS 510AC, 510BC, 510BL AND 610BR REMOVED AND PANELS 510AL, 610AR, 720BL, AND 730BR LOWERED) - PERFORM VISUAL INSPECTION. INSPECT STRUCTURE FOR CORROSION OR DETERIORATION OF PROTECTIVE TREATMENT. |          |          |                        |           |           | Service     | ATA:57   |
|                                                              | MOS     | 31-Mar-20                                                                                                                                                                                                                          | 96       | Adj -34d | 26-Feb-28              |           | 1060 d    |             |          |
|                                                              | HRS     | 8253.8                                                                                                                                                                                                                             |          |          |                        |           |           |             |          |
|                                                              | AFL     | 6353                                                                                                                                                                                                                               |          |          |                        |           |           |             |          |
| PROC. REF: AMM 57-10-00PROC. REF: AMM 57-10-00               |         |                                                                                                                                                                                                                                    |          |          |                        |           |           |             |          |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C/W   (M)-Manual Due   U-User Task   Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|---------|------|-----|----------|----------|------------------------|-----------|-----------|-------------|----------|
|---------|------|-----|----------|----------|------------------------|-----------|-----------|-------------|----------|

ATA 57 - WINGS

|                                                |                                                                                                                                                                                                                                     |           |    |          |           |  |        |         |        |
|------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|----|----------|-----------|--|--------|---------|--------|
| 5710190                                        | * RIGHT WING CENTER SECTION (PANELS 510AC, 510BC, 510BL AND 610BR REMOVED AND PANELS 510AL, 610AR, 720BL, AND 730BR LOWERED) - PERFORM VISUAL INSPECTION. INSPECT STRUCTURE FOR CORROSION OR DETERIORATION OF PROTECTIVE TREATMENT. |           |    |          |           |  |        | Service | ATA:57 |
|                                                | MOS                                                                                                                                                                                                                                 | 31-Mar-20 | 96 | Adj -34d | 26-Feb-28 |  | 1060 d |         |        |
|                                                | HRS                                                                                                                                                                                                                                 | 8253.8    |    |          |           |  |        |         |        |
|                                                | AFL                                                                                                                                                                                                                                 | 6353      |    |          |           |  |        |         |        |
| PROC. REF: AMM 57-10-00PROC. REF: AMM 57-10-00 |                                                                                                                                                                                                                                     |           |    |          |           |  |        |         |        |

|                                                    |                     |           |     |       |  |  |  |           |        |
|----------------------------------------------------|---------------------|-----------|-----|-------|--|--|--|-----------|--------|
| 573001                                             | LEFT WINGLET FILLER |           |     |       |  |  |  | Component | ATA:57 |
| PN:PN                                              | MOS/MSC             | 09-Mar-01 | O/C | TSN 0 |  |  |  |           |        |
| SN:UNKNOWN                                         | HRS                 | 0         |     | TSN 0 |  |  |  |           |        |
|                                                    | AFL                 | 0         |     | TSN 0 |  |  |  |           |        |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                     |           |     |       |  |  |  |           |        |

|                                                    |                      |           |     |       |  |  |  |           |        |
|----------------------------------------------------|----------------------|-----------|-----|-------|--|--|--|-----------|--------|
| 573002                                             | RIGHT WINGLET FILLER |           |     |       |  |  |  | Component | ATA:57 |
| PN:PN                                              | MOS/MSC              | 09-Mar-01 | O/C | TSN 0 |  |  |  |           |        |
| SN:UNKNOWN                                         | HRS                  | 0         |     | TSN 0 |  |  |  |           |        |
|                                                    | AFL                  | 0         |     | TSN 0 |  |  |  |           |        |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                      |           |     |       |  |  |  |           |        |

|                                                |                   |           |     |       |  |  |  |           |        |
|------------------------------------------------|-------------------|-----------|-----|-------|--|--|--|-----------|--------|
| 573090                                         | LEFT WING WINGLET |           |     |       |  |  |  | Component | ATA:57 |
| PN:PN                                          | MOS/MSC           | 09-Mar-01 | O/C | TSN 0 |  |  |  |           |        |
| SN:UNKNOWN                                     | HRS               | 0         |     | TSN 0 |  |  |  |           |        |
|                                                | AFL               | 0         |     | TSN 0 |  |  |  |           |        |
| PROC. REF: AMM 57-30-01PROC. REF: AMM 57-30-01 |                   |           |     |       |  |  |  |           |        |

|                                                |                                    |           |     |       |  |  |  |           |        |
|------------------------------------------------|------------------------------------|-----------|-----|-------|--|--|--|-----------|--------|
| 573091                                         | LEFT WINGLET LEADING EDGE ASSEMBLY |           |     |       |  |  |  | Component | ATA:57 |
| PN:PN                                          | MOS/MSC                            | 09-Mar-01 | O/C | TSN 0 |  |  |  |           |        |
| SN:UNKNOWN                                     | HRS                                | 0         |     | TSN 0 |  |  |  |           |        |
|                                                | AFL                                | 0         |     | TSN 0 |  |  |  |           |        |
| PROC. REF: AMM 57-30-01PROC. REF: AMM 57-30-01 |                                    |           |     |       |  |  |  |           |        |

|                                                |                    |           |     |       |  |  |  |           |        |
|------------------------------------------------|--------------------|-----------|-----|-------|--|--|--|-----------|--------|
| 573092                                         | RIGHT WING WINGLET |           |     |       |  |  |  | Component | ATA:57 |
| PN:PN                                          | MOS/MSC            | 09-Mar-01 | O/C | TSN 0 |  |  |  |           |        |
| SN:UNKNOWN                                     | HRS                | 0         |     | TSN 0 |  |  |  |           |        |
|                                                | AFL                | 0         |     | TSN 0 |  |  |  |           |        |
| PROC. REF: AMM 57-30-01PROC. REF: AMM 57-30-01 |                    |           |     |       |  |  |  |           |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9669.1
 AFL: 7372
 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                        | Unit                                      | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|------------------------------------------------|-------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 57 - WINGS                                 |                                           |           |          |          |                        |           |           |             |                  |
| 573093                                         | RIGHT WINGLET LEADING EDGE ASSEMBLY       |           |          |          |                        |           |           |             | Component ATA:57 |
| PN:PN                                          | MOS/MSC                                   | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                       | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                       | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 57-30-01PROC. REF: AMM 57-30-01 |                                           |           |          |          |                        |           |           |             |                  |
| 574005                                         | LEFT INBOARD LEADING EDGE                 |           |          |          |                        |           |           |             | Component ATA:57 |
| PN:PN                                          | MOS/MSC                                   | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                       | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                       | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 57-40-01PROC. REF: AMM 57-40-01 |                                           |           |          |          |                        |           |           |             |                  |
| 574007                                         | RIGHT INBOARD LEADING EDGE                |           |          |          |                        |           |           |             | Component ATA:57 |
| PN:PN                                          | MOS/MSC                                   | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                       | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                       | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 57-40-01PROC. REF: AMM 57-40-01 |                                           |           |          |          |                        |           |           |             |                  |
| 574011                                         | LEFT INBOARD LEADING EDGE ACCESS SECTION  |           |          |          |                        |           |           |             | Component ATA:57 |
| PN:PN                                          | MOS/MSC                                   | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                       | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                       | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 57-40-01PROC. REF: AMM 57-40-01 |                                           |           |          |          |                        |           |           |             |                  |
| 574013                                         | RIGHT INBOARD LEADING EDGE ACCESS SECTION |           |          |          |                        |           |           |             | Component ATA:57 |
| PN:PN                                          | MOS/MSC                                   | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                       | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                       | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 57-40-01PROC. REF: AMM 57-40-01 |                                           |           |          |          |                        |           |           |             |                  |
| 574033                                         | LEFT CENTER LEADING EDGE                  |           |          |          |                        |           |           |             | Component ATA:57 |
| PN:PN                                          | MOS/MSC                                   | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                       | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                       | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 57-40-01PROC. REF: AMM 57-40-01 |                                           |           |          |          |                        |           |           |             |                  |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C/W   (M)-Manual Due   U-User Task   Ex-Excluded Task



Status Report

Model: LEARJET 45XR    Serial: 45-145    RegNo: N942FK    HRS: 9669.1    AFL: 7372    As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                        | Unit                                       | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty            |
|------------------------------------------------|--------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|---------------------|
| ATA 57 - WINGS                                 |                                            |           |          |          |                        |           |           |             |                     |
| 574035                                         | RIGHT CENTER LEADING EDGE                  |           |          |          |                        |           |           |             | Component    ATA:57 |
| PN:PN                                          | MOS/MSC                                    | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                     | HRS                                        | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                | AFL                                        | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: AMM 57-40-01PROC. REF: AMM 57-40-01 |                                            |           |          |          |                        |           |           |             |                     |
| 574039                                         | LEFT OUTBOARD LEADING EDGE ACCESS SECTION  |           |          |          |                        |           |           |             | Component    ATA:57 |
| PN:PN                                          | MOS/MSC                                    | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                     | HRS                                        | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                | AFL                                        | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: AMM 57-40-01PROC. REF: AMM 57-40-01 |                                            |           |          |          |                        |           |           |             |                     |
| 574041                                         | RIGHT OUTBOARD LEADING EDGE ACCESS SECTION |           |          |          |                        |           |           |             | Component    ATA:57 |
| PN:PN                                          | MOS/MSC                                    | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                     | HRS                                        | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                | AFL                                        | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: AMM 57-40-01PROC. REF: AMM 57-40-01 |                                            |           |          |          |                        |           |           |             |                     |
| 574050                                         | LEFT OUTBOARD LEADING EDGE                 |           |          |          |                        |           |           |             | Component    ATA:57 |
| PN:PN                                          | MOS/MSC                                    | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                     | HRS                                        | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                | AFL                                        | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: AMM 57-40-01PROC. REF: AMM 57-40-01 |                                            |           |          |          |                        |           |           |             |                     |
| 574051                                         | RIGHT OUTBOARD LEADING EDGE                |           |          |          |                        |           |           |             | Component    ATA:57 |
| PN:PN                                          | MOS/MSC                                    | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                     | HRS                                        | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                | AFL                                        | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: AMM 57-40-01PROC. REF: AMM 57-40-01 |                                            |           |          |          |                        |           |           |             |                     |
| 575001                                         | LEFT FLAP ASSEMBLY                         |           |          |          |                        |           |           |             | Component    ATA:57 |
| PN:4557500006-007                              | MOS/MSC                                    | 02-Aug-24 | O/C      |          |                        |           |           |             |                     |
| SN:474598000144                                | HRS                                        | 9525.7    |          |          |                        |           |           |             |                     |
|                                                | AFL                                        | 7276      |          |          |                        |           |           |             |                     |
| Special Properties: RII ITEM                   |                                            |           |          |          |                        |           |           |             |                     |
| PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01 |                                            |           |          |          |                        |           |           |             |                     |

?-Insufficient Information    S-Suppressed Requirement    \*-Estimated Due(New Requirement)    (EFF)-Effective C/W    (M)-Manual Due    U-User Task    Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                        | Unit                                                              | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|------------------------------------------------|-------------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 57 - WINGS                                 |                                                                   |           |          |          |                        |           |           |             |          |
| 575002                                         | RIGHT FLAP ASSEMBLY                                               |           |          |          |                        |           |           | Component   | ATA:57   |
| PN:4557500006-008                              | MOS/MSC                                                           | 02-Aug-24 | O/C      |          |                        |           |           |             |          |
| SN:474600100146                                | HRS                                                               | 9525.7    |          |          |                        |           |           |             |          |
|                                                | AFL                                                               | 7276      |          |          |                        |           |           |             |          |
| Special Properties: RII ITEM                   |                                                                   |           |          |          |                        |           |           |             |          |
| PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01 |                                                                   |           |          |          |                        |           |           |             |          |
| 576001                                         | LEFT AILERON                                                      |           |          |          |                        |           |           | Component   | ATA:57   |
| PN:4557600003-001                              | MOS/MSC                                                           | 02-Aug-24 | O/C      |          |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS                                                               | 9525.7    |          |          |                        |           |           |             |          |
|                                                | AFL                                                               | 7276      |          |          |                        |           |           |             |          |
| Special Properties: RII ITEM                   |                                                                   |           |          |          |                        |           |           |             |          |
| PROC. REF: AMM 27-10-02PROC. REF: AMM 27-10-02 |                                                                   |           |          |          |                        |           |           |             |          |
| 576002                                         | RIGHT AILERON                                                     |           |          |          |                        |           |           | Component   | ATA:57   |
| PN:4557600003-002                              | MOS/MSC                                                           | 02-Aug-24 | O/C      |          |                        |           |           |             |          |
| SN:00145                                       | HRS                                                               | 9525.7    |          |          |                        |           |           |             |          |
|                                                | AFL                                                               | 7276      |          |          |                        |           |           |             |          |
| Special Properties: RII ITEM                   |                                                                   |           |          |          |                        |           |           |             |          |
| PROC. REF: AMM 27-10-02PROC. REF: AMM 27-10-02 |                                                                   |           |          |          |                        |           |           |             |          |
| 576037                                         | REPLACE LEFT AILERON (ZONE/ACCESS 540/640 *IRN # A5760004) BOLTS  |           |          |          |                        |           |           | Component   | ATA:57   |
| PN:PN                                          | MOS                                                               | 02-Aug-24 |          | TSN 0    |                        |           |           | REPLACE     |          |
| SN:UNKNOWN                                     | HRS                                                               | 9525.7    | 9600     | TSN 0    | 19125.7                |           | 9456.6    |             |          |
|                                                | AFL                                                               | 7276      |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 27-10-02PROC. REF: AMM 27-10-02 |                                                                   |           |          |          |                        |           |           |             |          |
| 576038                                         | REPLACE RIGHT AILERON (ZONE/ACCESS 540/640 *IRN # A5760004) BOLTS |           |          |          |                        |           |           | Component   | ATA:57   |
| PN:PN                                          | MOS                                                               | 02-Aug-24 |          | TSN 0    |                        |           |           | REPLACE     |          |
| SN:UNKNOWN                                     | HRS                                                               | 9525.7    | 9600     | TSN 0    | 19125.7                |           | 9456.6    |             |          |
|                                                | AFL                                                               | 7276      |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 27-10-02PROC. REF: AMM 27-10-02 |                                                                   |           |          |          |                        |           |           |             |          |
| 577001                                         | LEFT SPOILER                                                      |           |          |          |                        |           |           | Component   | ATA:57   |
| PN:PN                                          | MOS/MSC                                                           | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                     | HRS                                                               | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                | AFL                                                               | 0         |          | TSN 0    |                        |           |           |             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|---------|------|-----|----------|----------|------------------------|-----------|-----------|-------------|----------|
|---------|------|-----|----------|----------|------------------------|-----------|-----------|-------------|----------|

ATA 57 - WINGS

PROC. REF: AMM 27-60-01PROC. REF: AMM 27-60-01

|                                                |               |           |       |       |  |           |        |
|------------------------------------------------|---------------|-----------|-------|-------|--|-----------|--------|
| 577002                                         | RIGHT SPOILER |           |       |       |  | Component | ATA:57 |
| PN:PN                                          | MOS/MSC       | 09-Mar-01 | O/C   | TSN 0 |  |           |        |
| SN:UNKNOWN                                     | HRS           | 0         | TSN 0 |       |  |           |        |
|                                                | AFL           | 0         | TSN 0 |       |  |           |        |
| PROC. REF: AMM 27-60-01PROC. REF: AMM 27-60-01 |               |           |       |       |  |           |        |

|                                                              |                                                              |           |      |         |        |
|--------------------------------------------------------------|--------------------------------------------------------------|-----------|------|---------|--------|
| N5710084 <sup>S</sup>                                        | PERFORM SPOILER, CENTER HINGE SPOILER SIDE - NDI INSPECTION. |           |      | Service | ATA:57 |
|                                                              | MOS                                                          | 25-Nov-19 | 96   |         |        |
|                                                              | HRS                                                          | 8177.7    | 2400 |         |        |
|                                                              | AFL                                                          | 6303      |      |         |        |
| PROC. REF: NDT PART 6/57-40-01PROC. REF: NDT PART 6/57-40-01 |                                                              |           |      |         | PKG:22 |

|                                                |                                     |           |     |         |        |
|------------------------------------------------|-------------------------------------|-----------|-----|---------|--------|
| Y5700001 <sup>S</sup>                          | WINGLET - PERFORM VISUAL INSPECTION |           |     | Service | ATA:57 |
|                                                | MOS                                 | 02-Aug-24 | 12  |         |        |
|                                                | HRS                                 | 9525.7    | 300 |         |        |
|                                                | AFL                                 | 7276      |     |         |        |
|                                                |                                     |           |     |         | PKG:4  |
| PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00 |                                     |           |     |         |        |

|                                                |                                                       |           |     |         |        |
|------------------------------------------------|-------------------------------------------------------|-----------|-----|---------|--------|
| Y5710180 <sup>S</sup>                          | EXTERNAL LOWER WING SKIN - PERFORM VISUAL INSPECTION. |           |     | Service | ATA:57 |
|                                                | MOS                                                   | 02-Aug-24 | 24  |         |        |
|                                                | HRS                                                   | 9525.7    | 600 |         |        |
|                                                | AFL                                                   | 7276      |     |         |        |
|                                                |                                                       |           |     |         | PKG:10 |
| PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00 |                                                       |           |     |         |        |

|                                                |                                                    |           |     |         |        |
|------------------------------------------------|----------------------------------------------------|-----------|-----|---------|--------|
| Y5730013 <sup>S</sup>                          | AILERON BRUSH SEALS - PERFORM DETAILED INSPECTION. |           |     | Service | ATA:57 |
|                                                | MOS                                                | 02-Aug-24 | 12  |         |        |
|                                                | HRS                                                | 9525.7    | 300 |         |        |
|                                                | AFL                                                | 7276      |     |         |        |
|                                                |                                                    |           |     |         | PKG:4  |
| PROC. REF: AMM 57-60-01PROC. REF: AMM 57-60-01 |                                                    |           |     |         |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9669.1
 AFL: 7372
 As Of: 01-Apr-2025
 02-Apr-2025 02:58 PM

| PN & SN                                        | Unit         | C/W                                                                                                                        | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition    | Warranty       |
|------------------------------------------------|--------------|----------------------------------------------------------------------------------------------------------------------------|----------|----------|------------------------|-----------|-----------|----------------|----------------|
| ATA 57 - WINGS                                 |              |                                                                                                                            |          |          |                        |           |           |                |                |
| Y5750067                                       | <sup>S</sup> | PERFORM FLAP BRACKETS (P/N A159019-1 AND A159022-1) - DETAILED VISUAL INSPECTION.                                          |          |          |                        |           |           |                | Service ATA:57 |
|                                                | MOS          | 25-Nov-19                                                                                                                  | 96       |          |                        |           |           |                |                |
|                                                | HRS          | 8177.7                                                                                                                     | 2400     |          |                        |           |           |                |                |
|                                                | AFL          | 6303                                                                                                                       |          |          |                        |           |           |                |                |
| PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00 |              |                                                                                                                            |          |          |                        |           |           |                |                |
| Y5750069                                       | <sup>S</sup> | FLAPS - PERFORM VISUAL INSPECTION OF FLAP NOSE ROLLERS, FLAP TRACKS, FLAP NOSE ROLLER TRACKS, AND FLAP MAIN TRACK ROLLERS. |          |          |                        |           |           |                | Service ATA:57 |
|                                                | MOS          | 02-Aug-24                                                                                                                  | 12       |          |                        |           |           |                |                |
|                                                | HRS          | 9525.7                                                                                                                     | 300      |          |                        |           |           |                |                |
|                                                | AFL          | 7276                                                                                                                       |          |          |                        |           |           |                |                |
| PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00 |              |                                                                                                                            |          |          |                        |           |           |                |                |
| ATA 71 - POWER PLANT                           |              |                                                                                                                            |          |          |                        |           |           |                |                |
| 5-19-00-Q7110004-LEFT                          |              | TAP TEST NO. 1 ENGINE NACELLE INLET (ZONE/ACCESS 430/440 IRN Q7110004). (REFER TO 71-10-01.)                               |          |          |                        |           |           |                | Service ATA:71 |
|                                                | MOS          | 02-Nov-22                                                                                                                  |          |          |                        |           |           |                |                |
|                                                | HRS          | 9151.6                                                                                                                     | 3000     | Adj 39.5 | 12191.1                |           | 2522      |                |                |
|                                                | AFL          | 7021                                                                                                                       |          |          |                        |           |           |                |                |
| PROC. REF: AMM 71-10-01PROC. REF: AMM 71-10-01 |              |                                                                                                                            |          |          |                        |           |           |                |                |
| 5-19-00-Q7110004-RIGHT                         |              | TAP TEST NO. 2 ENGINE NACELLE INLET (ZONE/ACCESS 430/440 IRN Q7110004). (REFER TO 71-10-01.)                               |          |          |                        |           |           |                | Service ATA:71 |
|                                                | MOS          | 12-Aug-15                                                                                                                  |          |          |                        |           |           |                |                |
|                                                | HRS          | 7535.1                                                                                                                     | 3000     |          | 10535.1                |           | 866       |                |                |
|                                                | AFL          | 5764                                                                                                                       |          |          |                        |           |           |                |                |
| PROC. REF: AMM 71-10-01PROC. REF: AMM 71-10-01 |              |                                                                                                                            |          |          |                        |           |           |                |                |
| 5-19-00-R7100032                               |              | L/H ENGINE NACELLE TUBES - PERFORM DETAILED VISUAL INSPECTION.                                                             |          |          |                        |           |           |                | Service ATA:71 |
|                                                | MOS/MSC      | 10-Nov-11                                                                                                                  | N/A      |          |                        |           |           | NOT APPLICABLE |                |
|                                                | HRS          | 6740.8                                                                                                                     |          |          |                        |           |           |                |                |
|                                                | AFL          | 5145                                                                                                                       |          |          |                        |           |           |                |                |
| PROC. REF: AMM 71-10-03PROC. REF: AMM 71-10-03 |              |                                                                                                                            |          |          |                        |           |           |                |                |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C/W   (M)-Manual Due   U-User Task   Ex-Excluded Task

# Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                                                    | Unit                                                                                 | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty |
|----------------------------------------------------------------------------|--------------------------------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|---------------|----------|
| ATA 71 - POWER PLANT                                                       |                                                                                      |           |          |          |                        |           |           |               |          |
| 5-19-01-V7120074L                                                          | LEFT ENGINE *REPLACE AFT ENGINE MOUNT BOLT (P/N 4571408525-001)(REFER TO 71-00-01.)  |           |          |          |                        |           |           | Component     | ATA:71   |
| PN:4571408525-001                                                          | MOS/MSC                                                                              | 26-Jul-23 | E/C      | TSN 0    |                        |           |           | AIRWORTHINESS |          |
| SN:UNKNOWN                                                                 | HRS                                                                                  | 9278      |          | TSN 0    |                        |           |           |               |          |
|                                                                            | AFL                                                                                  | 7111      |          | TSN 0    |                        |           |           |               |          |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00                             |                                                                                      |           |          |          |                        |           |           |               |          |
| 5-19-01-V7120074R                                                          | RIGHT ENGINE *REPLACE AFT ENGINE MOUNT BOLT (P/N 4571408525-001)(REFER TO 71-00-01.) |           |          |          |                        |           |           | Component     | ATA:71   |
| PN:4571408525-001                                                          | MOS/MSC                                                                              | 26-Jul-23 | E/C      | TSN 0    |                        |           |           | AIRWORTHINESS |          |
| SN:UNKNOWN                                                                 | HRS                                                                                  | 9278      |          | TSN 0    |                        |           |           |               |          |
|                                                                            | AFL                                                                                  | 7111      |          | TSN 0    |                        |           |           |               |          |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00                             |                                                                                      |           |          |          |                        |           |           |               |          |
| 710001 <sup>U</sup>                                                        | NO. 1 ASSEMBLY ENGINE                                                                |           |          |          |                        |           |           | Component     | ATA:71   |
| PN:PN                                                                      | MOS/MSC                                                                              | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |               |          |
| SN:UNKNOWN                                                                 | HRS                                                                                  | 0         |          | TSN 0    |                        |           |           |               |          |
|                                                                            | AFL                                                                                  | 0         |          | TSN 0    |                        |           |           |               |          |
| 710002 <sup>U</sup>                                                        | NO. 2 ASSEMBLY ENGINE                                                                |           |          |          |                        |           |           | Component     | ATA:71   |
| PN:PN                                                                      | MOS/MSC                                                                              | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |               |          |
| SN:UNKNOWN                                                                 | HRS                                                                                  | 0         |          | TSN 0    |                        |           |           |               |          |
|                                                                            | AFL                                                                                  | 0         |          | TSN 0    |                        |           |           |               |          |
| 710100                                                                     | NO. 1 ENGINE - MAIN ENGINE WIRING HARNESS ASSEMBLY                                   |           |          |          |                        |           |           | Component     | ATA:71   |
| PN:PN                                                                      | MOS/MSC                                                                              | 05-Jan-00 | O/C      | TSN 0    |                        |           |           |               |          |
| SN:UNKNOWN                                                                 | HRS                                                                                  | 0         |          | TSN 0    |                        |           |           |               |          |
|                                                                            | ENC                                                                                  | 0         |          | TSN 0    |                        |           |           |               |          |
| PROC. REF: LMM 72-00-02, LMM 72-00-02PROC. REF: LMM 72-00-02, LMM 72-00-02 |                                                                                      |           |          |          |                        |           |           |               |          |
| 710100                                                                     | NO. 2 ENGINE - MAIN ENGINE WIRING HARNESS ASSEMBLY                                   |           |          |          |                        |           |           | Component     | ATA:71   |
| PN:3060757-3                                                               | MOS/MSC                                                                              | 06-Jul-23 | O/C      | TSN 0    |                        |           |           |               |          |
| SN:22-129505-00163                                                         | HRS                                                                                  | 8350.6    |          | TSN 0    |                        |           |           |               |          |
|                                                                            | ENC                                                                                  | 6943      |          | TSN 0    |                        |           |           |               |          |
| PROC. REF: LMM 72-00-02, LMM 72-00-02PROC. REF: LMM 72-00-02, LMM 72-00-02 |                                                                                      |           |          |          |                        |           |           |               |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                                                    | Unit         | C/W                                                                                                                          | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------------------------------|--------------|------------------------------------------------------------------------------------------------------------------------------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 71 - POWER PLANT                                                       |              |                                                                                                                              |          |          |                        |           |           |             |          |
| 710130                                                                     | <sup>S</sup> | NO. 1 ENGINE - INSPECT TAILPIPE/LPT3 ROTOR ASSEMBLY-VISUALLY INSPECT FOR FOREIGN OBJECT DAMAGE, THERMAL DISTRESS, AND LEAKS. |          |          |                        |           |           | Service     | ATA:71   |
|                                                                            | MOS          | 18-Aug-22                                                                                                                    |          |          |                        |           |           |             |          |
|                                                                            | HRS          | 9008.5                                                                                                                       | 800      |          |                        |           |           |             |          |
|                                                                            | ENC          | 6936                                                                                                                         |          |          |                        |           |           |             |          |
| PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00                             |              |                                                                                                                              |          |          |                        |           |           |             | PKG:0    |
| 710130                                                                     | <sup>S</sup> | NO. 2 ENGINE - INSPECT TAILPIPE/LPT3 ROTOR ASSEMBLY-VISUALLY INSPECT FOR FOREIGN OBJECT DAMAGE, THERMAL DISTRESS, AND LEAKS. |          |          |                        |           |           | Service     | ATA:71   |
|                                                                            | MOS          | 18-Aug-22                                                                                                                    |          |          |                        |           |           |             |          |
|                                                                            | HRS          | 8169.8                                                                                                                       | 800      |          |                        |           |           |             |          |
|                                                                            | ENC          | 6832                                                                                                                         |          |          |                        |           |           |             |          |
| PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00                             |              |                                                                                                                              |          |          |                        |           |           |             | PKG:0    |
| 710140                                                                     | <sup>S</sup> | NO. 1 ENGINE - INSPECT INLET/FAN AREA - INSPECT FOR FOREIGN OBJECT DAMAGE AND LEAKAGE (REFER TO PARAGRAPH 4.B)               |          |          |                        |           |           | Service     | ATA:71   |
|                                                                            | MOS          | 18-Aug-22                                                                                                                    |          |          |                        |           |           |             |          |
|                                                                            | HRS          | 9008.5                                                                                                                       | 800      |          |                        |           |           |             |          |
|                                                                            | ENC          | 6936                                                                                                                         |          |          |                        |           |           |             |          |
| PROC. REF: LMM 72-00-00, LMM 72-00-00PROC. REF: LMM 72-00-00, LMM 72-00-00 |              |                                                                                                                              |          |          |                        |           |           |             | PKG:0    |
| 710140                                                                     | <sup>S</sup> | NO. 2 ENGINE - INSPECT INLET/FAN AREA - INSPECT FOR FOREIGN OBJECT DAMAGE AND LEAKAGE (REFER TO PARAGRAPH 4.B)               |          |          |                        |           |           | Service     | ATA:71   |
|                                                                            | MOS          | 18-Aug-22                                                                                                                    |          |          |                        |           |           |             |          |
|                                                                            | HRS          | 8169.8                                                                                                                       | 800      |          |                        |           |           |             |          |
|                                                                            | ENC          | 6832                                                                                                                         |          |          |                        |           |           |             |          |
| PROC. REF: LMM 72-00-00, LMM 72-00-00PROC. REF: LMM 72-00-00, LMM 72-00-00 |              |                                                                                                                              |          |          |                        |           |           |             | PKG:0    |
| 711001                                                                     |              | NO. 1 ENGINE FORWARD MOUNT                                                                                                   |          |          |                        |           |           | Component   | ATA:71   |
| PN:PN                                                                      | MOS/MSC      | 09-Mar-01                                                                                                                    | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                                                 | HRS          | 0                                                                                                                            |          | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL          | 0                                                                                                                            |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00                             |              |                                                                                                                              |          |          |                        |           |           |             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9669.1
 AFL: 7372
 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                        | Unit                                                                                      | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|------------------------------------------------|-------------------------------------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 71 - POWER PLANT                           |                                                                                           |           |          |          |                        |           |           |             |                  |
| 711002                                         | NO. 2 ENGINE FORWARD MOUNT                                                                |           |          |          |                        |           |           |             | Component ATA:71 |
| PN:PN                                          | MOS/MSC                                                                                   | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                                                                       | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                                                                       | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00 |                                                                                           |           |          |          |                        |           |           |             |                  |
| 7120002                                        | NO. 1 ENGINE AFT ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS           |           |          |          |                        |           |           |             | Service ATA:71   |
|                                                | MOS                                                                                       | 26-Jul-23 |          |          |                        |           |           |             |                  |
|                                                | HRS                                                                                       | 9278      | 5000     |          | 14278                  |           | 4608.9    |             |                  |
|                                                | AFL                                                                                       | 7111      |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00 |                                                                                           |           |          |          |                        |           |           |             |                  |
| 7120002                                        | NO. 1 ENGINE ALL ISOLATORS - PERFORM INSPECTION OF ISOLATORS AND ASSOCIATED PARTS         |           |          |          |                        |           |           |             | Service ATA:71   |
|                                                | MOS/MSC                                                                                   | 27-Sep-06 | N/A      |          |                        |           |           |             |                  |
|                                                | HRS                                                                                       | 4857.2    |          |          |                        |           |           |             |                  |
|                                                | AFL                                                                                       | 3730      |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00 |                                                                                           |           |          |          |                        |           |           |             |                  |
| 7120002                                        | NO. 1 ENGINE FORWARD LOWER ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS |           |          |          |                        |           |           |             | Service ATA:71   |
|                                                | MOS                                                                                       | 26-Jul-23 |          |          |                        |           |           |             |                  |
|                                                | HRS                                                                                       | 9278      | 5000     |          | 14278                  |           | 4608.9    |             |                  |
|                                                | AFL                                                                                       | 7111      |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00 |                                                                                           |           |          |          |                        |           |           |             |                  |
| 7120002                                        | NO. 1 ENGINE FORWARD UPPER ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS |           |          |          |                        |           |           |             | Service ATA:71   |
|                                                | MOS                                                                                       | 26-Jul-23 |          |          |                        |           |           |             |                  |
|                                                | HRS                                                                                       | 9278      | 5000     |          | 14278                  |           | 4608.9    |             |                  |
|                                                | AFL                                                                                       | 7111      |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00 |                                                                                           |           |          |          |                        |           |           |             |                  |
| 7120002                                        | NO. 2 ENGINE AFT ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS           |           |          |          |                        |           |           |             | Service ATA:71   |
|                                                | MOS                                                                                       | 26-Jul-23 |          |          |                        |           |           |             |                  |
|                                                | HRS                                                                                       | 9278      | 5000     |          | 14278                  |           | 4608.9    |             |                  |
|                                                | AFL                                                                                       | 7111      |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00 |                                                                                           |           |          |          |                        |           |           |             |                  |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C/W   (M)-Manual Due   U-User Task   Ex-Excluded Task

# Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                        | Unit                                                                                      | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|------------------------------------------------|-------------------------------------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 71 - POWER PLANT                           |                                                                                           |           |          |          |                        |           |           |             |                  |
| 7120002                                        | NO. 2 ENGINE ALL ISOLATORS - PERFORM INSPECTION OF ISOLATORS AND ASSOCIATED PARTS         |           |          |          |                        |           |           |             | Service ATA:71   |
|                                                | MOS/MSC                                                                                   | 27-Sep-06 | N/A      |          |                        |           |           |             |                  |
|                                                | HRS                                                                                       | 4857.2    |          |          |                        |           |           |             |                  |
|                                                | AFL                                                                                       | 3730      |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00 |                                                                                           |           |          |          |                        |           |           |             |                  |
| 7120002                                        | NO. 2 ENGINE FORWARD LOWER ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS |           |          |          |                        |           |           |             | Service ATA:71   |
|                                                | MOS                                                                                       | 26-Jul-23 |          |          |                        |           |           |             |                  |
|                                                | HRS                                                                                       | 9278      | 5000     |          | 14278                  |           | 4608.9    |             |                  |
|                                                | AFL                                                                                       | 7111      |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00 |                                                                                           |           |          |          |                        |           |           |             |                  |
| 7120002                                        | NO. 2 ENGINE FORWARD UPPER ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS |           |          |          |                        |           |           |             | Service ATA:71   |
|                                                | MOS                                                                                       | 26-Jul-23 |          |          |                        |           |           |             |                  |
|                                                | HRS                                                                                       | 9278      | 5000     |          | 14278                  |           | 4608.9    |             |                  |
|                                                | AFL                                                                                       | 7111      |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00 |                                                                                           |           |          |          |                        |           |           |             |                  |
| 7120004                                        | REPLACE ALL FORWARD AND AFT ENGINE MOUNT ISOLATOR HOUSINGS                                |           |          |          |                        |           |           |             | Component ATA:71 |
|                                                | MOS                                                                                       | 09-Mar-01 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
|                                                | HRS                                                                                       | 0         | 15000    | TSN 0    | 15000                  |           | 5330.9    |             |                  |
|                                                | AFL                                                                                       | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00 |                                                                                           |           |          |          |                        |           |           |             |                  |
| 7120004 <sup>S</sup>                           | REPLACE NO. 1 ENGINE AFT ENGINE MOUNT ISOLATOR HOUSING                                    |           |          |          |                        |           |           |             | Component ATA:71 |
| PN:PN                                          | MOS                                                                                       | 09-Mar-01 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:UNKNOWN                                     | HRS                                                                                       | 0         | 15000    | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                                                                       | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00 |                                                                                           |           |          |          |                        |           |           |             |                  |
| 7120004 <sup>S</sup>                           | REPLACE NO. 1 ENGINE FORWARD LOWER ENGINE MOUNT ISOLATOR HOUSING                          |           |          |          |                        |           |           |             | Component ATA:71 |
| PN:PN                                          | MOS                                                                                       | 09-Mar-01 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:UNKNOWN                                     | HRS                                                                                       | 0         | 15000    | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                                                                       | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00 |                                                                                           |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                        | Unit    | C / W                                                                  | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|------------------------------------------------|---------|------------------------------------------------------------------------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 71 - POWER PLANT                           |         |                                                                        |          |          |                        |           |           |             |          |
| 7120004 <sup>S</sup>                           |         | REPLACE NO. 1 ENGINE FORWARD UPPER ENGINE MOUNT ISOLATOR HOUSING       |          |          |                        |           |           | Component   | ATA:71   |
| PN:PN                                          | MOS     | 09-Mar-01                                                              |          | TSN 0    |                        |           |           | LIFE LIMIT  |          |
| SN:UNKNOWN                                     | HRS     | 0                                                                      | 15000    | TSN 0    |                        |           |           |             |          |
|                                                | AFL     | 0                                                                      |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00 |         |                                                                        |          |          |                        |           |           |             |          |
| 7120004 <sup>S</sup>                           |         | REPLACE NO. 2 ENGINE AFT ENGINE MOUNT ISOLATOR HOUSING                 |          |          |                        |           |           | Component   | ATA:71   |
| PN:PN                                          | MOS     | 09-Mar-01                                                              |          | TSN 0    |                        |           |           | LIFE LIMIT  |          |
| SN:UNKNOWN                                     | HRS     | 0                                                                      | 15000    | TSN 0    |                        |           |           |             |          |
|                                                | AFL     | 0                                                                      |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00 |         |                                                                        |          |          |                        |           |           |             |          |
| 7120004 <sup>S</sup>                           |         | REPLACE NO. 2 ENGINE FORWARD LOWER ENGINE MOUNT ISOLATOR HOUSING       |          |          |                        |           |           | Component   | ATA:71   |
| PN:PN                                          | MOS     | 09-Mar-01                                                              |          | TSN 0    |                        |           |           | LIFE LIMIT  |          |
| SN:UNKNOWN                                     | HRS     | 0                                                                      | 15000    | TSN 0    |                        |           |           |             |          |
|                                                | AFL     | 0                                                                      |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00 |         |                                                                        |          |          |                        |           |           |             |          |
| 7120004 <sup>S</sup>                           |         | REPLACE NO. 2 ENGINE FORWARD UPPER ENGINE MOUNT ISOLATOR HOUSING       |          |          |                        |           |           | Component   | ATA:71   |
| PN:PN                                          | MOS     | 09-Mar-01                                                              |          | TSN 0    |                        |           |           | LIFE LIMIT  |          |
| SN:UNKNOWN                                     | HRS     | 0                                                                      | 15000    | TSN 0    |                        |           |           |             |          |
|                                                | AFL     | 0                                                                      |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00 |         |                                                                        |          |          |                        |           |           |             |          |
| 7120005                                        |         | REPLACE NO. 1 ENGINE AFT ENGINE MOUNT ISOLATOR FORWARD BONDED MOUNTING |          |          |                        |           |           | Component   | ATA:71   |
| PN:LM-833-SA18                                 | MOS     | 26-Jul-23                                                              |          | TSN 0    |                        |           |           | LIFE LIMIT  |          |
| SN:LK2888                                      | HRS     | 9278                                                                   | 5000     | TSN 0    | 14278                  |           | 4608.9    |             |          |
|                                                | AFL     | 7111                                                                   |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00 |         |                                                                        |          |          |                        |           |           |             |          |
| 7120005                                        |         | REPLACE NO. 1 ENGINE ALL ENGINE MOUNT ISOLATOR BONDED MOUNTING         |          |          |                        |           |           | Component   | ATA:71   |
|                                                | MOS/MSC | 27-Sep-06                                                              | N/A      |          |                        |           |           |             |          |
|                                                | HRS     | 4857.2                                                                 |          |          |                        |           |           |             |          |
|                                                | AFL     | 3730                                                                   |          |          |                        |           |           |             |          |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00 |         |                                                                        |          |          |                        |           |           |             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                        | Unit                                                                     | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|------------------------------------------------|--------------------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 71 - POWER PLANT                           |                                                                          |           |          |          |                        |           |           |             |                  |
| 7120005                                        | REPLACE NO. 1 ENGINE FORWARD LOWER ENGINE MOUNT ISOLATOR BONDED MOUNTING |           |          |          |                        |           |           |             | Component ATA:71 |
| PN:LM-833-48                                   | MOS                                                                      | 26-Jul-23 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:UNKNOWN                                     | HRS                                                                      | 9278      | 5000     | TSN 0    | 14278                  |           | 4608.9    |             |                  |
|                                                | AFL                                                                      | 7111      |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00 |                                                                          |           |          |          |                        |           |           |             |                  |
| 7120005                                        | REPLACE NO. 1 ENGINE FORWARD UPPER ENGINE MOUNT ISOLATOR BONDED MOUNTING |           |          |          |                        |           |           |             | Component ATA:71 |
| PN:LM-833-48                                   | MOS                                                                      | 26-Jul-23 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:UNKNOWN                                     | HRS                                                                      | 9278      | 5000     | TSN 0    | 14278                  |           | 4608.9    |             |                  |
|                                                | AFL                                                                      | 7111      |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00 |                                                                          |           |          |          |                        |           |           |             |                  |
| 7120005                                        | REPLACE NO. 2 ENGINE AFT ENGINE MOUNT ISOLATOR BONDED MOUNTING           |           |          |          |                        |           |           |             | Component ATA:71 |
| PN:LM-833-SA18                                 | MOS                                                                      | 26-Jul-23 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:LK288                                       | HRS                                                                      | 9278      | 5000     | TSN 0    | 14278                  |           | 4608.9    |             |                  |
|                                                | AFL                                                                      | 7111      |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00 |                                                                          |           |          |          |                        |           |           |             |                  |
| 7120005                                        | REPLACE NO. 2 ENGINE ALL ENGINE MOUNT ISOLATOR BONDED MOUNTING           |           |          |          |                        |           |           |             | Component ATA:71 |
| PN:PN                                          | MOS/MSC                                                                  |           | N/A      |          |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                                                      |           |          |          |                        |           |           |             |                  |
|                                                | AFL                                                                      |           |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00 |                                                                          |           |          |          |                        |           |           |             |                  |
| 7120005                                        | REPLACE NO. 2 ENGINE FORWARD LOWER ENGINE MOUNT ISOLATOR BONDED MOUNTING |           |          |          |                        |           |           |             | Component ATA:71 |
| PN:LM-833-48                                   | MOS                                                                      | 26-Jul-23 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:UNKNOWN                                     | HRS                                                                      | 9278      | 5000     | TSN 0    | 14278                  |           | 4608.9    |             |                  |
|                                                | AFL                                                                      | 7111      |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00 |                                                                          |           |          |          |                        |           |           |             |                  |
| 7120005                                        | REPLACE NO. 2 ENGINE FORWARD UPPER ENGINE MOUNT ISOLATOR BONDED MOUNTING |           |          |          |                        |           |           |             | Component ATA:71 |
| PN:LM-833-48                                   | MOS                                                                      | 26-Jul-23 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:UNKNOWN                                     | HRS                                                                      | 9278      | 5000     | TSN 0    | 14278                  |           | 4608.9    |             |                  |
|                                                | AFL                                                                      | 7111      |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00 |                                                                          |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: LEARJET 45XR   
 Serial: 45-145   
 RegNo: N942FK   
 HRS: 9669.1   
 AFL: 7372   
 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                                                          | Unit    | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------------------------------------|---------|-----------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 71 - POWER PLANT                                                             |         |           |          |          |                        |           |           |             |          |
| 7120006 REPLACE NO. 1 ENGINE AFT ENGINE MOUNT ISOLATOR BONDED MOUNTING           |         |           |          |          |                        |           |           | Component   | ATA:71   |
| PN:PN                                                                            | MOS/MSC | 09-Mar-01 | N/A      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                                                       | HRS     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                                                  | AFL     | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00                                   |         |           |          |          |                        |           |           |             |          |
| 7120006 REPLACE NO. 1 ENGINE ALL ENGINE MOUNT ISOLATOR FORWARD BONDED MOUNTING   |         |           |          |          |                        |           |           | Component   | ATA:71   |
| PN:PN                                                                            | MOS/MSC | 09-Mar-01 | N/A      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                                                       | HRS     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                                                  | AFL     | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00                                   |         |           |          |          |                        |           |           |             |          |
| 7120006 REPLACE NO. 1 ENGINE FORWARD LOWER ENGINE MOUNT ISOLATOR BONDED MOUNTING |         |           |          |          |                        |           |           | Component   | ATA:71   |
| PN:PN                                                                            | MOS/MSC | 09-Mar-01 | N/A      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                                                       | HRS     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                                                  | AFL     | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00                                   |         |           |          |          |                        |           |           |             |          |
| 7120006 REPLACE NO. 1 ENGINE FORWARD UPPER ENGINE MOUNT ISOLATOR BONDED MOUNTING |         |           |          |          |                        |           |           | Component   | ATA:71   |
| PN:PN                                                                            | MOS/MSC | 09-Mar-01 | N/A      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                                                       | HRS     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                                                  | AFL     | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00                                   |         |           |          |          |                        |           |           |             |          |
| 7120006 REPLACE NO. 2 ENGINE AFT ENGINE MOUNT ISOLATOR BONDED MOUNTING           |         |           |          |          |                        |           |           | Component   | ATA:71   |
| PN:PN                                                                            | MOS/MSC | 09-Mar-01 | N/A      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                                                       | HRS     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                                                  | AFL     | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00                                   |         |           |          |          |                        |           |           |             |          |
| 7120006 REPLACE NO. 2 ENGINE ALL ENGINE MOUNT ISOLATOR FORWARD BONDED MOUNTING   |         |           |          |          |                        |           |           | Component   | ATA:71   |
| PN:PN                                                                            | MOS/MSC | 09-Mar-01 | N/A      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                                                       | HRS     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                                                  | AFL     | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00                                   |         |           |          |          |                        |           |           |             |          |

?-Insufficient Information   
 S-Suppressed Requirement   
 \*-Estimated Due(New Requirement)   
 (EFF)-Effective C/W   
 (M)-Manual Due   
 U-User Task   
 Ex-Excluded Task

# Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9669.1
 AFL: 7372
 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                        | Unit                                                                                     | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|------------------------------------------------|------------------------------------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 71 - POWER PLANT                           |                                                                                          |           |          |          |                        |           |           |             |                  |
| 7120006                                        | REPLACE NO. 2 ENGINE FORWARD LOWER ENGINE MOUNT ISOLATOR BONDED MOUNTING                 |           |          |          |                        |           |           |             | Component ATA:71 |
| PN:PN                                          | MOS/MSC                                                                                  | 09-Mar-01 | N/A      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                                                                      | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                                                                      | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00 |                                                                                          |           |          |          |                        |           |           |             |                  |
| 7120006                                        | REPLACE NO. 2 ENGINE FORWARD UPPER ENGINE MOUNT ISOLATOR BONDED MOUNTING                 |           |          |          |                        |           |           |             | Component ATA:71 |
| PN:PN                                          | MOS/MSC                                                                                  | 09-Mar-01 | N/A      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                                                                      | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                                                                      | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00 |                                                                                          |           |          |          |                        |           |           |             |                  |
| 712005                                         | NO. 1 ENGINE AFT MOUNT ISOLATOR ASSEMBLY                                                 |           |          |          |                        |           |           |             | Component ATA:71 |
| PN:PN                                          | MOS/MSC                                                                                  | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                                                                      | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                                                                      | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00 |                                                                                          |           |          |          |                        |           |           |             |                  |
| 712006                                         | NO. 2 ENGINE AFT MOUNT ISOLATOR ASSEMBLY                                                 |           |          |          |                        |           |           |             | Component ATA:71 |
| PN:PN                                          | MOS/MSC                                                                                  | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                                                                      | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                                                                      | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00 |                                                                                          |           |          |          |                        |           |           |             |                  |
| 7120069                                        | NO. 1 ENGINE AFT ISOLATOR - PERFORM VISUAL INSPECTION OF ISOLATOR AND ASSOCIATED PARTS   |           |          |          |                        |           |           |             | Service ATA:71   |
|                                                | MOS                                                                                      | 26-Jul-23 |          |          |                        |           |           |             |                  |
|                                                | HRS                                                                                      | 9278      | 2500     |          | 11778                  |           | 2108.9    |             |                  |
|                                                | AFL                                                                                      | 7111      |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00 |                                                                                          |           |          |          |                        |           |           |             |                  |
| 7120069                                        | NO. 1 ENGINE ALL ISOLATORS - PERFORM VISUAL INSPECTION OF ISOLATORS AND ASSOCIATED PARTS |           |          |          |                        |           |           |             | Service ATA:71   |
|                                                | MOS                                                                                      | 26-Jul-23 |          |          |                        |           |           |             |                  |
|                                                | HRS                                                                                      | 9278      | 3000     |          | 12278                  |           | 2608.9    |             |                  |
|                                                | AFL                                                                                      | 7111      |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00 |                                                                                          |           |          |          |                        |           |           |             |                  |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C/W   (M)-Manual Due   U-User Task   Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                        | Unit                                                                                             | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty       |
|------------------------------------------------|--------------------------------------------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|----------------|
| ATA 71 - POWER PLANT                           |                                                                                                  |           |          |          |                        |           |           |             |                |
| 7120069                                        | NO. 1 ENGINE FORWARD LOWER ISOLATOR - PERFORM VISUAL INSPECTION OF ISOLATOR AND ASSOCIATED PARTS |           |          |          |                        |           |           |             | Service ATA:71 |
|                                                | MOS                                                                                              | 26-Jul-23 |          |          |                        |           |           |             |                |
|                                                | HRS                                                                                              | 9278      | 2500     |          | 11778                  |           | 2108.9    |             |                |
|                                                | AFL                                                                                              | 7111      |          |          |                        |           |           |             |                |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00 |                                                                                                  |           |          |          |                        |           |           |             |                |
| 7120069                                        | NO. 1 ENGINE FORWARD UPPER ISOLATOR - PERFORM VISUAL INSPECTION OF ISOLATOR AND ASSOCIATED PARTS |           |          |          |                        |           |           |             | Service ATA:71 |
|                                                | MOS                                                                                              | 26-Jul-23 |          |          |                        |           |           |             |                |
|                                                | HRS                                                                                              | 9278      | 2500     |          | 11778                  |           | 2108.9    |             |                |
|                                                | AFL                                                                                              | 7111      |          |          |                        |           |           |             |                |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00 |                                                                                                  |           |          |          |                        |           |           |             |                |
| 7120069                                        | NO. 2 ENGINE AFT ISOLATOR - PERFORM VISUAL INSPECTION OF ISOLATOR AND ASSOCIATED PARTS           |           |          |          |                        |           |           |             | Service ATA:71 |
|                                                | MOS                                                                                              | 26-Jul-23 |          |          |                        |           |           |             |                |
|                                                | HRS                                                                                              | 9278      | 2500     |          | 11778                  |           | 2108.9    |             |                |
|                                                | AFL                                                                                              | 7111      |          |          |                        |           |           |             |                |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00 |                                                                                                  |           |          |          |                        |           |           |             |                |
| 7120069                                        | NO. 2 ENGINE ALL ISOLATORS - PERFORM VISUAL INSPECTION OF ISOLATORS AND ASSOCIATED PARTS         |           |          |          |                        |           |           |             | Service ATA:71 |
|                                                | MOS                                                                                              | 26-Jul-23 |          |          |                        |           |           |             |                |
|                                                | HRS                                                                                              | 9278      | 3000     |          | 12278                  |           | 2608.9    |             |                |
|                                                | AFL                                                                                              | 7111      |          |          |                        |           |           |             |                |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00 |                                                                                                  |           |          |          |                        |           |           |             |                |
| 7120069                                        | NO. 2 ENGINE FORWARD LOWER ISOLATOR - PERFORM VISUAL INSPECTION OF ISOLATOR AND ASSOCIATED PARTS |           |          |          |                        |           |           |             | Service ATA:71 |
|                                                | MOS                                                                                              | 26-Jul-23 |          |          |                        |           |           |             |                |
|                                                | HRS                                                                                              | 9278      | 2500     |          | 11778                  |           | 2108.9    |             |                |
|                                                | AFL                                                                                              | 7111      |          |          |                        |           |           |             |                |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00 |                                                                                                  |           |          |          |                        |           |           |             |                |
| 7120069                                        | NO. 2 ENGINE FORWARD UPPER ISOLATOR - PERFORM VISUAL INSPECTION OF ISOLATOR AND ASSOCIATED PARTS |           |          |          |                        |           |           |             | Service ATA:71 |
|                                                | MOS                                                                                              | 26-Jul-23 |          |          |                        |           |           |             |                |
|                                                | HRS                                                                                              | 9278      | 2500     |          | 11778                  |           | 2108.9    |             |                |
|                                                | AFL                                                                                              | 7111      |          |          |                        |           |           |             |                |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00 |                                                                                                  |           |          |          |                        |           |           |             |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9669.1
 AFL: 7372
 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                        | Unit                                                                     | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|------------------------------------------------|--------------------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 71 - POWER PLANT                           |                                                                          |           |          |          |                        |           |           |             |                  |
| 712007                                         | NO. 1 ENGINE FORWARD UPPER MOUNT ISOLATOR ASSEMBLY                       |           |          |          |                        |           |           |             | Component ATA:71 |
| PN:PN                                          | MOS/MSC                                                                  | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                                                      | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                                                      | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00 |                                                                          |           |          |          |                        |           |           |             |                  |
| 7120070                                        | REPLACE NO. 1 ENGINE AFT ENGINE MOUNT ISOLATOR BONDED MOUNTING           |           |          |          |                        |           |           |             | Component ATA:71 |
| PN:LM-833-48                                   | MOS                                                                      | 26-Jul-23 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:UNKNOWN                                     | HRS                                                                      | 9278      | 6000     | TSN 0    | 15278                  |           | 5608.9    |             |                  |
|                                                | AFL                                                                      | 7111      |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00 |                                                                          |           |          |          |                        |           |           |             |                  |
| 7120070                                        | REPLACE NO. 1 ENGINE ALL ENGINE MOUNT ISOLATOR BONDED MOUNTING           |           |          |          |                        |           |           |             | Component ATA:71 |
| PN:PN                                          | MOS                                                                      | 26-Jul-23 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:UNKNOWN                                     | HRS                                                                      | 9278      | 6000     | TSN 0    | 15278                  |           | 5608.9    |             |                  |
|                                                | AFL                                                                      | 7111      |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00 |                                                                          |           |          |          |                        |           |           |             |                  |
| 7120070                                        | REPLACE NO. 1 ENGINE FORWARD LOWER ENGINE MOUNT ISOLATOR BONDED MOUNTING |           |          |          |                        |           |           |             | Component ATA:71 |
| PN:LM-833-48                                   | MOS                                                                      | 26-Jul-23 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:UNKNOWN                                     | HRS                                                                      | 9278      | 6000     | TSN 0    | 15278                  |           | 5608.9    |             |                  |
|                                                | AFL                                                                      | 7111      |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00 |                                                                          |           |          |          |                        |           |           |             |                  |
| 7120070                                        | REPLACE NO. 1 ENGINE FORWARD UPPER ENGINE MOUNT ISOLATOR BONDED MOUNTING |           |          |          |                        |           |           |             | Component ATA:71 |
| PN:LM-833-48                                   | MOS                                                                      | 26-Jul-23 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:UNKNOWN                                     | HRS                                                                      | 9278      | 6000     | TSN 0    | 15278                  |           | 5608.9    |             |                  |
|                                                | AFL                                                                      | 7111      |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00 |                                                                          |           |          |          |                        |           |           |             |                  |
| 7120070                                        | REPLACE NO. 2 ENGINE AFT ENGINE MOUNT ISOLATOR BONDED MOUNTING           |           |          |          |                        |           |           |             | Component ATA:71 |
| PN:LM-833-SA18                                 | MOS                                                                      | 26-Jul-23 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:LK2904                                      | HRS                                                                      | 9278      | 6000     | TSN 0    | 15278                  |           | 5608.9    |             |                  |
|                                                | AFL                                                                      | 7111      |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00 |                                                                          |           |          |          |                        |           |           |             |                  |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C/W   (M)-Manual Due   U-User Task   Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                        | Unit                                                                                      | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|------------------------------------------------|-------------------------------------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 71 - POWER PLANT                           |                                                                                           |           |          |          |                        |           |           |             |                  |
| 7120070                                        | REPLACE NO. 2 ENGINE ALL ENGINE MOUNT ISOLATOR BONDED MOUNTING                            |           |          |          |                        |           |           |             | Component ATA:71 |
| PN:PN                                          | MOS                                                                                       | 26-Jul-23 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:UNKNOWN                                     | HRS                                                                                       | 9278      | 6000     | TSN 0    | 15278                  |           | 5608.9    |             |                  |
|                                                | AFL                                                                                       | 7111      |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00 |                                                                                           |           |          |          |                        |           |           |             |                  |
| 7120070                                        | REPLACE NO. 2 ENGINE FORWARD LOWER ENGINE MOUNT ISOLATOR BONDED MOUNTING                  |           |          |          |                        |           |           |             | Component ATA:71 |
| PN:LM-833-48                                   | MOS                                                                                       | 26-Jul-23 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:UNKNOWN                                     | HRS                                                                                       | 9278      | 6000     | TSN 0    | 15278                  |           | 5608.9    |             |                  |
|                                                | AFL                                                                                       | 7111      |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00 |                                                                                           |           |          |          |                        |           |           |             |                  |
| 7120070                                        | REPLACE NO. 2 ENGINE FORWARD UPPER ENGINE MOUNT ISOLATOR BONDED MOUNTING                  |           |          |          |                        |           |           |             | Component ATA:71 |
| PN:LM-833-48                                   | MOS                                                                                       | 26-Jul-23 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:UNKNOWN                                     | HRS                                                                                       | 9278      | 6000     | TSN 0    | 15278                  |           | 5608.9    |             |                  |
|                                                | AFL                                                                                       | 7111      |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00 |                                                                                           |           |          |          |                        |           |           |             |                  |
| 7120073                                        | NO. 1 ENGINE AFT ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS           |           |          |          |                        |           |           |             | Service ATA:71   |
|                                                | MOS                                                                                       | 26-Jul-23 |          |          |                        |           |           |             |                  |
|                                                | HRS                                                                                       | 9278      | 6000     |          | 15278                  |           | 5608.9    |             |                  |
|                                                | AFL                                                                                       | 7111      |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00 |                                                                                           |           |          |          |                        |           |           |             |                  |
| 7120073                                        | NO. 1 ENGINE ALL ISOLATORS - PERFORM INSPECTION OF ISOLATORS AND ASSOCIATED PARTS         |           |          |          |                        |           |           |             | Service ATA:71   |
|                                                | MOS                                                                                       | 26-Jul-23 |          |          |                        |           |           |             |                  |
|                                                | HRS                                                                                       | 9278      | 6000     |          | 15278                  |           | 5608.9    |             |                  |
|                                                | AFL                                                                                       | 7111      |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00 |                                                                                           |           |          |          |                        |           |           |             |                  |
| 7120073                                        | NO. 1 ENGINE FORWARD LOWER ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS |           |          |          |                        |           |           |             | Service ATA:71   |
|                                                | MOS                                                                                       | 26-Jul-23 |          |          |                        |           |           |             |                  |
|                                                | HRS                                                                                       | 9278      | 6000     |          | 15278                  |           | 5608.9    |             |                  |
|                                                | AFL                                                                                       | 7111      |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00 |                                                                                           |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9669.1
 AFL: 7372
 As Of: 01-Apr-2025
 02-Apr-2025 02:58 PM

| PN & SN                                        | Unit                                                                                                          | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty       |
|------------------------------------------------|---------------------------------------------------------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|----------------|
| ATA 71 - POWER PLANT                           |                                                                                                               |           |          |          |                        |           |           |             |                |
| 7120073                                        | NO. 1 ENGINE FORWARD UPPER ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS                     |           |          |          |                        |           |           |             | Service ATA:71 |
|                                                | MOS                                                                                                           | 26-Jul-23 |          |          |                        |           |           |             |                |
|                                                | HRS                                                                                                           | 9278      | 6000     |          | 15278                  |           | 5608.9    |             |                |
|                                                | AFL                                                                                                           | 7111      |          |          |                        |           |           |             |                |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00 |                                                                                                               |           |          |          |                        |           |           |             |                |
| 7120073                                        | NO. 2 ENGINE AFT ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS                               |           |          |          |                        |           |           |             | Service ATA:71 |
|                                                | MOS                                                                                                           | 26-Jul-23 |          |          |                        |           |           |             |                |
|                                                | HRS                                                                                                           | 9278      | 6000     |          | 15278                  |           | 5608.9    |             |                |
|                                                | AFL                                                                                                           | 7111      |          |          |                        |           |           |             |                |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00 |                                                                                                               |           |          |          |                        |           |           |             |                |
| 7120073                                        | NO. 2 ENGINE ALL ISOLATORS - PERFORM INSPECTION OF ISOLATORS AND ASSOCIATED PARTS                             |           |          |          |                        |           |           |             | Service ATA:71 |
|                                                | MOS                                                                                                           | 26-Jul-23 |          |          |                        |           |           |             |                |
|                                                | HRS                                                                                                           | 9278      | 6000     |          | 15278                  |           | 5608.9    |             |                |
|                                                | AFL                                                                                                           | 7111      |          |          |                        |           |           |             |                |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00 |                                                                                                               |           |          |          |                        |           |           |             |                |
| 7120073                                        | NO. 2 ENGINE FORWARD LOWER ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS                     |           |          |          |                        |           |           |             | Service ATA:71 |
|                                                | MOS                                                                                                           | 26-Jul-23 |          |          |                        |           |           |             |                |
|                                                | HRS                                                                                                           | 9278      | 6000     |          | 15278                  |           | 5608.9    |             |                |
|                                                | AFL                                                                                                           | 7111      |          |          |                        |           |           |             |                |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00 |                                                                                                               |           |          |          |                        |           |           |             |                |
| 7120073                                        | NO. 2 ENGINE FORWARD UPPER ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS                     |           |          |          |                        |           |           |             | Service ATA:71 |
|                                                | MOS                                                                                                           | 26-Jul-23 |          |          |                        |           |           |             |                |
|                                                | HRS                                                                                                           | 9278      | 6000     |          | 15278                  |           | 5608.9    |             |                |
|                                                | AFL                                                                                                           | 7111      |          |          |                        |           |           |             |                |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00 |                                                                                                               |           |          |          |                        |           |           |             |                |
| 7120075                                        | NO. 1 AFT ENGINE MOUNT ISOLATORS - PERFORM DETAILED INSPECTION OF AFT ISOLATOR ASSEMBLY AND ASSOCIATED PARTS. |           |          |          |                        |           |           |             | Service ATA:71 |
|                                                | MOS/MSC                                                                                                       | 26-Jul-23 | MPI      |          |                        |           |           |             |                |
|                                                | HRS                                                                                                           | 9278      | 3600     |          | 12878                  |           | 3208.9    |             |                |
|                                                | AFL                                                                                                           | 7111      |          |          |                        |           |           |             |                |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00 |                                                                                                               |           |          |          |                        |           |           |             |                |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C/W   (M)-Manual Due   U-User Task   Ex-Excluded Task



Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                                                                                                                                                                                                                                                                                    | Unit                                                                                                          | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 71 - POWER PLANT                                                                                                                                                                                                                                                                                       |                                                                                                               |           |          |          |                        |           |           |             |                  |
| 7120075                                                                                                                                                                                                                                                                                                    | NO. 2 AFT ENGINE MOUNT ISOLATORS - PERFORM DETAILED INSPECTION OF AFT ISOLATOR ASSEMBLY AND ASSOCIATED PARTS. |           |          |          |                        |           |           |             | Service ATA:71   |
|                                                                                                                                                                                                                                                                                                            | MOS/MSC                                                                                                       | 26-Jul-23 | MPI      |          |                        |           |           |             |                  |
|                                                                                                                                                                                                                                                                                                            | HRS                                                                                                           | 9278      | 3600     |          | 12878                  |           | 3208.9    |             |                  |
|                                                                                                                                                                                                                                                                                                            | AFL                                                                                                           | 7111      |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00                                                                                                                                                                                                                                                             |                                                                                                               |           |          |          |                        |           |           |             |                  |
| 712008                                                                                                                                                                                                                                                                                                     | NO. 2 ENGINE FORWARD UPPER MOUNT ISOLATOR ASSEMBLY                                                            |           |          |          |                        |           |           |             | Component ATA:71 |
| PN:LM833-SA20-5                                                                                                                                                                                                                                                                                            | MOS/MSC                                                                                                       | 26-Sep-06 | O/C      |          |                        |           |           |             |                  |
| SN:LK3128                                                                                                                                                                                                                                                                                                  | HRS                                                                                                           | 4857.22   |          |          |                        |           |           |             |                  |
|                                                                                                                                                                                                                                                                                                            | AFL                                                                                                           | 3730      |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00                                                                                                                                                                                                                                                             |                                                                                                               |           |          |          |                        |           |           |             |                  |
| 712009                                                                                                                                                                                                                                                                                                     | NO. 1 ENGINE FORWARD LOWER MOUNT ISOLATOR ASSEMBLY                                                            |           |          |          |                        |           |           |             | Component ATA:71 |
| PN:PN                                                                                                                                                                                                                                                                                                      | MOS/MSC                                                                                                       | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                                                                                                                                                                                                                                                 | HRS                                                                                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                                                                                                                                                                                                                                                            | AFL                                                                                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00                                                                                                                                                                                                                                                             |                                                                                                               |           |          |          |                        |           |           |             |                  |
| 712010                                                                                                                                                                                                                                                                                                     | NO. 2 ENGINE FORWARD LOWER MOUNT ISOLATOR ASSEMBLY                                                            |           |          |          |                        |           |           |             | Component ATA:71 |
| PN:KM833-SA20-5                                                                                                                                                                                                                                                                                            | MOS/MSC                                                                                                       | 26-Sep-06 | O/C      |          |                        |           |           |             |                  |
| SN:LK3185                                                                                                                                                                                                                                                                                                  | HRS                                                                                                           | 4857.22   |          |          |                        |           |           |             |                  |
|                                                                                                                                                                                                                                                                                                            | AFL                                                                                                           | 3730      |          |          |                        |           |           |             |                  |
| PROC. REF: NDT PART 7/32-10-08, NDT PART 7/32-10-03, NDT PART 7/32-10-04, NDT PART 8/32-10-02, NDT PART 8/54-30-01, NDT PART 8/54-30-02, AMM 71-20-00PROC. REF: NDT PART 7/32-10-08, NDT PART 7/32-10-03, NDT PART 7/32-10-04, NDT PART 8/32-10-02, NDT PART 8/54-30-01, NDT PART 8/54-30-02, AMM 71-20-00 |                                                                                                               |           |          |          |                        |           |           |             |                  |
| 712045                                                                                                                                                                                                                                                                                                     | NO. 1 ENGINE AFT MOUNT                                                                                        |           |          |          |                        |           |           |             | Component ATA:71 |
| PN:PN                                                                                                                                                                                                                                                                                                      | MOS/MSC                                                                                                       | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                                                                                                                                                                                                                                                 | HRS                                                                                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                                                                                                                                                                                                                                                            | AFL                                                                                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00                                                                                                                                                                                                                                                             |                                                                                                               |           |          |          |                        |           |           |             |                  |
| 712046                                                                                                                                                                                                                                                                                                     | NO. 2 ENGINE AFT MOUNT                                                                                        |           |          |          |                        |           |           |             | Component ATA:71 |
| PN:PN                                                                                                                                                                                                                                                                                                      | MOS/MSC                                                                                                       | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                                                                                                                                                                                                                                                 | HRS                                                                                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                                                                                                                                                                                                                                                            | AFL                                                                                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00                                                                                                                                                                                                                                                             |                                                                                                               |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                        | Unit    | C/W                                                                                                                                                      | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|------------------------------------------------|---------|----------------------------------------------------------------------------------------------------------------------------------------------------------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 71 - POWER PLANT                           |         |                                                                                                                                                          |          |          |                        |           |           |             |          |
| 714010 <sup>S</sup>                            |         | NO. 1 ENGINE - CHECK ELECTRICAL WIRES AND CONNECTIONS - VISUALLY INSPECT FOR SECURITY AND DAMAGE                                                         |          |          |                        |           |           | Service     | ATA:71   |
|                                                | MOS     | 18-Aug-22                                                                                                                                                |          |          |                        |           |           |             |          |
|                                                | HRS     | 9008.5                                                                                                                                                   | 800      |          |                        |           |           |             |          |
|                                                | ENC     | 6936                                                                                                                                                     |          |          |                        |           |           |             |          |
| PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00 |         |                                                                                                                                                          |          |          |                        |           |           |             | PKG:0    |
| 714010 <sup>S</sup>                            |         | NO. 2 ENGINE - CHECK ELECTRICAL WIRES AND CONNECTIONS - VISUALLY INSPECT FOR SECURITY AND DAMAGE                                                         |          |          |                        |           |           | Service     | ATA:71   |
|                                                | MOS     | 18-Aug-22                                                                                                                                                |          |          |                        |           |           |             |          |
|                                                | HRS     | 8169.8                                                                                                                                                   | 800      |          |                        |           |           |             |          |
|                                                | ENC     | 6832                                                                                                                                                     |          |          |                        |           |           |             |          |
| PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00 |         |                                                                                                                                                          |          |          |                        |           |           |             | PKG:0    |
| 715010 <sup>S</sup>                            |         | NO. 1 ENGINE - CHECK PLUMBING LINES AND CONNECTIONS - VISUALLY INSPECT FOR SECURITY, LOOSE OR BROKEN CLAMPS OR BRACKETS, LEAKS, CRACKS, CUTS, OR RUBBING |          |          |                        |           |           | Service     | ATA:71   |
|                                                | MOS     | 18-Aug-22                                                                                                                                                |          |          |                        |           |           |             |          |
|                                                | HRS     | 9008.5                                                                                                                                                   | 800      |          |                        |           |           |             |          |
|                                                | ENC     | 6936                                                                                                                                                     |          |          |                        |           |           |             |          |
| PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00 |         |                                                                                                                                                          |          |          |                        |           |           |             | PKG:0    |
| 715010 <sup>S</sup>                            |         | NO. 2 ENGINE - CHECK PLUMBING LINES AND CONNECTIONS - VISUALLY INSPECT FOR SECURITY, LOOSE OR BROKEN CLAMPS OR BRACKETS, LEAKS, CRACKS, CUTS, OR RUBBING |          |          |                        |           |           | Service     | ATA:71   |
|                                                | MOS     | 18-Aug-22                                                                                                                                                |          |          |                        |           |           |             |          |
|                                                | HRS     | 8169.8                                                                                                                                                   | 800      |          |                        |           |           |             |          |
|                                                | ENC     | 6832                                                                                                                                                     |          |          |                        |           |           |             |          |
| PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00 |         |                                                                                                                                                          |          |          |                        |           |           |             | PKG:0    |
| 716005                                         |         | NO. 1 ENGINE INLET NACELLE                                                                                                                               |          |          |                        |           |           | Component   | ATA:71   |
| PN:4572290001-801                              | MOS/MSC | 16-Jul-19                                                                                                                                                | O/C      |          |                        |           |           |             |          |
| SN:145LH                                       | HRS     | 8109                                                                                                                                                     |          |          |                        |           |           |             |          |
|                                                | AFL     | 6239                                                                                                                                                     |          |          |                        |           |           |             |          |
| PROC. REF: AMM 71-10-01PROC. REF: AMM 71-10-01 |         |                                                                                                                                                          |          |          |                        |           |           |             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                        | Unit                                                                                                                                                                                         | C/W       | Interval | TSX/Adj.   | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|----------|------------|------------------------|-----------|-----------|-------------|------------------|
| ATA 71 - POWER PLANT                           |                                                                                                                                                                                              |           |          |            |                        |           |           |             |                  |
| 716006                                         | NO. 2 ENGINE INLET NACELLE                                                                                                                                                                   |           |          |            |                        |           |           |             | Component ATA:71 |
| PN:2652000V24-003                              | MOS/MSC                                                                                                                                                                                      | 02-Dec-09 | O/C      | TSR 0      |                        |           |           |             |                  |
| SN:114RH                                       | HRS                                                                                                                                                                                          | 6213.6    |          | TSR 0      |                        |           |           |             |                  |
|                                                | AFL                                                                                                                                                                                          | 4758      |          | TSR 0      |                        |           |           |             |                  |
| PROC. REF: AMM 71-10-01PROC. REF: AMM 71-10-01 |                                                                                                                                                                                              |           |          |            |                        |           |           |             |                  |
| 71EN1                                          | NO. 1 ENGINE                                                                                                                                                                                 |           |          |            |                        |           |           |             | Component ATA:71 |
| PN:3060082-2                                   | MOS/MSC                                                                                                                                                                                      |           | E/C      |            |                        |           |           |             |                  |
| SN:P-116284C                                   | HRS                                                                                                                                                                                          |           |          |            |                        |           |           |             |                  |
|                                                | AFL                                                                                                                                                                                          |           |          |            |                        |           |           |             |                  |
| PROC. REF: AMM 71-00-01PROC. REF: AMM 71-00-01 |                                                                                                                                                                                              |           |          |            |                        |           |           |             |                  |
| 71EN2                                          | NO. 2 ENGINE                                                                                                                                                                                 |           |          |            |                        |           |           |             | Component ATA:71 |
| PN:3060084-2                                   | MOS/MSC                                                                                                                                                                                      | 12-Aug-15 | E/C      |            |                        |           |           |             |                  |
| SN:P-116285C                                   | HRS                                                                                                                                                                                          | 7535.1    |          | TSN 6622.3 |                        |           |           |             |                  |
|                                                | AFL                                                                                                                                                                                          | 5764      |          |            |                        |           |           |             |                  |
| PROC. REF: AMM 71-00-01PROC. REF: AMM 71-00-01 |                                                                                                                                                                                              |           |          |            |                        |           |           |             |                  |
| Y7100002 <sup>S</sup>                          | LOWER ENGINE COWLING - VISUALLY INSPECT LATCH CHANNELS FOR CHAFING.                                                                                                                          |           |          |            |                        |           |           |             | Service ATA:71   |
|                                                | MOS                                                                                                                                                                                          | 02-Aug-24 | 24       |            |                        |           |           |             |                  |
|                                                | HRS                                                                                                                                                                                          | 9525.7    | 600      |            |                        |           |           |             |                  |
|                                                | AFL                                                                                                                                                                                          | 7276      |          |            |                        |           |           |             |                  |
| PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00 |                                                                                                                                                                                              |           |          |            |                        |           |           |             | PKG:9            |
| Y7110000 <sup>S</sup>                          | ENGINE NACELLE - PERFORM VISUAL INSPECTION. INSPECT INLET BULKHEAD, STRUCTURE, PLUMBING, SKIN SPOT WELDS, ANTI-ICE OUTLET SCREEN, AND FASTENERS FOR SECURITY, CRACKS, AND GENERAL CONDITION. |           |          |            |                        |           |           |             | Service ATA:71   |
|                                                | MOS                                                                                                                                                                                          | 02-Aug-24 | 24       |            |                        |           |           |             |                  |
|                                                | HRS                                                                                                                                                                                          | 9525.7    | 600      |            |                        |           |           |             |                  |
|                                                | AFL                                                                                                                                                                                          | 7276      |          |            |                        |           |           |             |                  |
| PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00 |                                                                                                                                                                                              |           |          |            |                        |           |           |             | PKG:9            |
| Y7110001 <sup>S</sup>                          | ENGINE INLET LIP AND DUCT - PERFORM VISUAL INSPECTION.                                                                                                                                       |           |          |            |                        |           |           |             | Service ATA:71   |
|                                                | MOS                                                                                                                                                                                          | 02-Aug-24 | 24       |            |                        |           |           |             |                  |
|                                                | HRS                                                                                                                                                                                          | 9525.7    | 600      |            |                        |           |           |             |                  |
|                                                | AFL                                                                                                                                                                                          | 7276      |          |            |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|---------|------|-----|----------|----------|------------------------|-----------|-----------|-------------|----------|
|---------|------|-----|----------|----------|------------------------|-----------|-----------|-------------|----------|

ATA 71 - POWER PLANT

PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00

|          |     |                                                                                        |     |  |  |  |  |         |        |
|----------|-----|----------------------------------------------------------------------------------------|-----|--|--|--|--|---------|--------|
| Y7110002 | S   | ENGINE STARTER/GENERATOR INLET AND EXHAUST DUCT AND SEALS - PERFORM VISUAL INSPECTION. |     |  |  |  |  | Service | ATA:71 |
|          | MOS | 02-Aug-24                                                                              | 24  |  |  |  |  |         |        |
|          | HRS | 9525.7                                                                                 | 600 |  |  |  |  |         |        |
|          | AFL | 7276                                                                                   |     |  |  |  |  |         |        |

PKG:9

PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00

|          |     |                                                                       |     |  |  |  |  |         |        |
|----------|-----|-----------------------------------------------------------------------|-----|--|--|--|--|---------|--------|
| Y7110003 | S   | ENGINE ALTERNATOR EXHAUST DUCT AND SEALS - PERFORM VISUAL INSPECTION. |     |  |  |  |  | Service | ATA:71 |
|          | MOS | 02-Aug-24                                                             | 24  |  |  |  |  |         |        |
|          | HRS | 9525.7                                                                | 600 |  |  |  |  |         |        |
|          | AFL | 7276                                                                  |     |  |  |  |  |         |        |

PKG:9

PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00

|          |     |                                                    |     |  |  |  |  |         |        |
|----------|-----|----------------------------------------------------|-----|--|--|--|--|---------|--------|
| Y7120000 | S   | FORWARD ENGINE MOUNTS - PERFORM VISUAL INSPECTION. |     |  |  |  |  | Service | ATA:71 |
|          | MOS | 02-Aug-24                                          | 12  |  |  |  |  |         |        |
|          | HRS | 9525.7                                             | 300 |  |  |  |  |         |        |
|          | AFL | 7276                                               |     |  |  |  |  |         |        |

PKG:3

PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00

ATA 72 - ENGINE

|              |                                                                      |           |      |  |                      |  |         |        |
|--------------|----------------------------------------------------------------------|-----------|------|--|----------------------|--|---------|--------|
| 72-AS-720005 | NO. 1 ENGINE - INSPECT MAJOR PERIODIC PER MANUFACTURERS INSTRUCTIONS |           |      |  |                      |  | Service | ATA:72 |
|              | MOS                                                                  | 06-Dec-17 |      |  |                      |  |         |        |
|              | HRS                                                                  | 7696.2    | 3000 |  | (10696.2)<br>10770.3 |  | 1101.2  |        |
|              | ENC                                                                  | 5895      |      |  |                      |  |         |        |

PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00

|              |                                                                      |           |      |  |                     |  |         |        |
|--------------|----------------------------------------------------------------------|-----------|------|--|---------------------|--|---------|--------|
| 72-AS-720005 | NO. 2 ENGINE - INSPECT MAJOR PERIODIC PER MANUFACTURERS INSTRUCTIONS |           |      |  |                     |  | Service | ATA:72 |
|              | MOS                                                                  | 20-Jul-15 |      |  |                     |  |         |        |
|              | HRS                                                                  | 6622.3    | 3000 |  | (9622.3)<br>10535.1 |  | 866     |        |
|              | ENC                                                                  | 5602      |      |  |                     |  |         |        |

PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                            | Unit | C/W                                                                                 | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------|------|-------------------------------------------------------------------------------------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 72 - ENGINE                                    |      |                                                                                     |          |          |                        |           |           |             |          |
| 72-AS-720006 <sup>S</sup>                          |      | NO. 1 ENGINE - INSPECT COMB CHAMBER PLENUM CASE INSP PER MANUFACTURERS INSTRUCTIONS |          |          |                        |           |           | Service     | ATA:72   |
|                                                    | MOS  | 06-Dec-17                                                                           |          |          |                        |           |           |             |          |
|                                                    | HRS  | 7696.2                                                                              | 3000     |          |                        |           |           |             |          |
|                                                    | ENC  | 5895                                                                                |          |          |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |      |                                                                                     |          |          |                        |           |           |             |          |
|                                                    |      |                                                                                     |          |          |                        |           |           |             |          |
| 72-AS-720006 <sup>S</sup>                          |      | NO. 2 ENGINE - INSPECT COMB CHAMBER PLENUM CASE INSP PER MANUFACTURERS INSTRUCTIONS |          |          |                        |           |           | Service     | ATA:72   |
|                                                    | MOS  | 20-Jul-15                                                                           |          |          |                        |           |           |             |          |
|                                                    | HRS  | 6622.3                                                                              | 3000     |          |                        |           |           |             |          |
|                                                    | ENC  | 5602                                                                                |          |          |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |      |                                                                                     |          |          |                        |           |           |             |          |
|                                                    |      |                                                                                     |          |          |                        |           |           |             |          |
| 72-AS-720007                                       |      | NO. 1 ENGINE - INSPECT COMPRESSOR ZONE PER MANUFACTURERS INSTRUCTIONS               |          |          |                        |           |           | Service     | ATA:72   |
|                                                    | MOS  | 30-Oct-06                                                                           |          |          |                        |           |           |             |          |
|                                                    | HRS  | 4857.2                                                                              | 6000     |          | (10857.2)<br>10931.3   |           | 1262.2    |             |          |
|                                                    | ENC  | 3730                                                                                |          |          |                        |           |           |             |          |
| PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00     |      |                                                                                     |          |          |                        |           |           |             |          |
|                                                    |      |                                                                                     |          |          |                        |           |           |             |          |
| 72-AS-720007                                       |      | NO. 2 ENGINE - INSPECT COMPRESSOR ZONE PER MANUFACTURERS INSTRUCTIONS               |          |          |                        |           |           | Service     | ATA:72   |
|                                                    | MOS  | 28-Jun-06                                                                           |          |          |                        |           |           |             |          |
|                                                    | HRS  | 3701.2                                                                              | 6000     |          | (9701.2)<br>10614      |           | 944.9     |             |          |
|                                                    | ENC  | 2811                                                                                |          |          |                        |           |           |             |          |
| PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00     |      |                                                                                     |          |          |                        |           |           |             |          |
|                                                    |      |                                                                                     |          |          |                        |           |           |             |          |
| 72-AS-720008 <sup>S</sup>                          |      | NO. 1 ENGINE - INSPECT 0 AGB PER MANUFACTURERS INSTRUCTIONS                         |          |          |                        |           |           | Service     | ATA:72   |
|                                                    | MOS  | 25-Oct-06                                                                           |          |          |                        |           |           |             |          |
|                                                    | HRS  | 4857.2                                                                              | 6000     |          |                        |           |           |             |          |
|                                                    | ENC  | 3730                                                                                |          |          |                        |           |           |             |          |
| PROC. REF: LMM 72-60-02PROC. REF: LMM 72-60-02     |      |                                                                                     |          |          |                        |           |           |             |          |
|                                                    |      |                                                                                     |          |          |                        |           |           |             |          |
| 72-AS-720008 <sup>S</sup>                          |      | NO. 2 ENGINE - INSPECT 0 AGB PER MANUFACTURERS INSTRUCTIONS                         |          |          |                        |           |           | Service     | ATA:72   |
|                                                    | MOS  | 05-Jun-06                                                                           |          |          |                        |           |           |             |          |
|                                                    | HRS  | 3701.2                                                                              | 6000     |          |                        |           |           |             |          |
|                                                    | ENC  | 3369                                                                                |          |          |                        |           |           |             |          |
| PROC. REF: LMM 72-60-02PROC. REF: LMM 72-60-02     |      |                                                                                     |          |          |                        |           |           |             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                                                    | Unit    | C/W                                                                          | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------------------------------|---------|------------------------------------------------------------------------------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 72 - ENGINE                                                            |         |                                                                              |          |          |                        |           |           |             |          |
| 72-AS-720010                                                               |         | NO. 1 ENGINE - ANALYSIS OIL AND FILTER (BASELINE/SPECIAL REQUIREMENT) (SOAP) |          |          |                        |           |           | Service     | ATA:72   |
|                                                                            | MOS/MSC | 05-Jan-00                                                                    | A/R      |          |                        |           |           |             |          |
|                                                                            | HRS     | 0                                                                            |          |          |                        |           |           |             |          |
|                                                                            | ENC     | 0                                                                            |          |          |                        |           |           |             |          |
| PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00                             |         |                                                                              |          |          |                        |           |           |             |          |
| 72-AS-720010                                                               |         | NO. 2 ENGINE - ANALYSIS OIL AND FILTER (BASELINE/SPECIAL REQUIREMENT) (SOAP) |          |          |                        |           |           | Service     | ATA:72   |
|                                                                            | MOS/MSC | 20-Jan-16                                                                    | A/R      |          |                        |           |           |             |          |
|                                                                            | HRS     | 6674                                                                         |          |          |                        |           |           |             |          |
|                                                                            | ENC     | 5628                                                                         |          |          |                        |           |           |             |          |
| PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00                             |         |                                                                              |          |          |                        |           |           |             |          |
| 72-AS-720011                                                               |         | NO. 1 ENGINE - REPLACE FUEL FILTER ELEMENT (25-HR INITIAL)                   |          |          |                        |           |           | Service     | ATA:72   |
|                                                                            | MOS/MSC | 05-Jan-00                                                                    | A/R      |          |                        |           |           |             |          |
|                                                                            | HRS     | 0                                                                            |          |          |                        |           |           |             |          |
|                                                                            | ENC     | 0                                                                            |          |          |                        |           |           |             |          |
| PROC. REF: LMM 73-21-02PROC. REF: LMM 73-21-02                             |         |                                                                              |          |          |                        |           |           |             |          |
| 72-AS-720011                                                               |         | NO. 2 ENGINE - REPLACE FUEL FILTER ELEMENT (25-HR INITIAL)                   |          |          |                        |           |           | Service     | ATA:72   |
|                                                                            | MOS/MSC | 15-Jan-00                                                                    | A/R      |          |                        |           |           |             |          |
|                                                                            | HRS     | 0                                                                            |          |          |                        |           |           |             |          |
|                                                                            | ENC     | 0                                                                            |          |          |                        |           |           |             |          |
| PROC. REF: LMM 73-21-02PROC. REF: LMM 73-21-02                             |         |                                                                              |          |          |                        |           |           |             |          |
| 720110                                                                     |         | NO. 1 ENGINE - ACCESSORY GEARBOX                                             |          |          |                        |           |           | Component   | ATA:72   |
| PN:3060827-2                                                               | MOS/MSC | 25-Oct-06                                                                    | O/C      |          |                        |           |           |             |          |
| SN:S986                                                                    | HRS     | 4857.2                                                                       |          |          |                        |           |           |             |          |
|                                                                            | ENC     | 3730                                                                         |          |          |                        |           |           |             |          |
| PROC. REF: LMM 72-60-02, LMM 72-60-02PROC. REF: LMM 72-60-02, LMM 72-60-02 |         |                                                                              |          |          |                        |           |           |             |          |
| 720110                                                                     |         | NO. 2 ENGINE - ACCESSORY GEARBOX                                             |          |          |                        |           |           | Component   | ATA:72   |
| PN:PN                                                                      | MOS/MSC | 15-Jan-00                                                                    | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                                                 | HRS     | 0                                                                            |          | TSN 0    |                        |           |           |             |          |
|                                                                            | ENC     | 0                                                                            |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: LMM 72-60-02, LMM 72-60-02PROC. REF: LMM 72-60-02, LMM 72-60-02 |         |                                                                              |          |          |                        |           |           |             |          |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C/W   (M)-Manual Due   U-User Task   Ex-Excluded Task

| PN & SN                                            | Unit                                      | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------|-------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 72 - ENGINE                                    |                                           |           |          |          |                        |           |           |             |                  |
| 720244                                             | NO. 1 ENGINE - NO. 6 CARBON SEAL ASSEMBLY |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:PN                                              | MOS/MSC                                   | 05-Jan-00 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                       | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                       | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                           |           |          |          |                        |           |           |             |                  |
| 720244                                             | NO. 2 ENGINE - NO. 6 CARBON SEAL ASSEMBLY |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3071383-2                                       | MOS/MSC                                   | 20-Jul-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:13-150211-00260                                 | HRS                                       | 6622.3    |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                       | 5602      |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                           |           |          |          |                        |           |           |             |                  |
| 720245                                             | NO. 1 ENGINE - NO. 6 BEARING ASSEMBLY     |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:PN                                              | MOS/MSC                                   | 05-Jan-00 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                       | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                       | 0         |          | TSN 0    |                        |           |           |             |                  |
| 720245                                             | NO. 2 ENGINE - NO. 6 BEARING ASSEMBLY     |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:PN                                              | MOS/MSC                                   | 15-Jan-00 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                       | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                       | 0         |          | TSN 0    |                        |           |           |             |                  |
| 722001                                             | NO. 1 ENGINE - FAN INLET HOUSING ASSEMBLY |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:PN                                              | MOS/MSC                                   | 05-Jan-00 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                       | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                       | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                           |           |          |          |                        |           |           |             |                  |
| 722001                                             | NO. 2 ENGINE - FAN INLET HOUSING ASSEMBLY |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:PN                                              | MOS/MSC                                   | 15-Jan-00 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                       | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                       | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                           |           |          |          |                        |           |           |             |                  |

?-Insufficient Information
 S-Suppressed Requirement
 \*-Estimated Due(New Requirement)
 (EFF)-Effective C/W
 (M)-Manual Due
 U-User Task
 Ex-Excluded Task

# Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9669.1
 AFL: 7372
 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                                                    | Unit                                      | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|-------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 72 - ENGINE                                                            |                                           |           |          |          |                        |           |           |             |                  |
| 723002                                                                     | NO. 1 ENGINE - NO. 3 CARBON SEAL ASSEMBLY |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3060150-3                                                               | MOS/MSC                                   | 25-Oct-06 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:061936801086                                                            | HRS                                       | 4857.2    |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | ENC                                       | 3730      |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: LMM 72-30-01, LMM 72-30-01PROC. REF: LMM 72-30-01, LMM 72-30-01 |                                           |           |          |          |                        |           |           |             |                  |
| 723002                                                                     | NO. 2 ENGINE - NO. 3 CARBON SEAL ASSEMBLY |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3060150-3                                                               | MOS/MSC                                   | 05-Jun-06 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:061936800093                                                            | HRS                                       | 3701.2    |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | ENC                                       | 3369      |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: LMM 72-30-01, LMM 72-30-01PROC. REF: LMM 72-30-01, LMM 72-30-01 |                                           |           |          |          |                        |           |           |             |                  |
| 723010 <sup>S</sup>                                                        | NO. 1 ENGINE - CHECK CARBON SEAL HEALTH   |           |          |          |                        |           |           |             | Service ATA:72   |
|                                                                            | MOS                                       | 22-Jun-23 |          |          |                        |           |           |             |                  |
|                                                                            | HRS                                       | 9184.4    | 1600     |          |                        |           |           |             |                  |
|                                                                            | ENC                                       | 7042      |          |          |                        |           |           |             |                  |
| PROC. REF: LMM 72-00-00, LMM 72-00-00PROC. REF: LMM 72-00-00, LMM 72-00-00 |                                           |           |          |          |                        |           |           |             |                  |
| 723010 <sup>S</sup>                                                        | NO. 2 ENGINE - CHECK CARBON SEAL HEALTH   |           |          |          |                        |           |           |             | Service ATA:72   |
|                                                                            | MOS                                       | 18-Aug-22 |          |          |                        |           |           |             |                  |
|                                                                            | HRS                                       | 8169.8    | 1600     |          |                        |           |           |             |                  |
|                                                                            | ENC                                       | 6832      |          |          |                        |           |           |             |                  |
| PROC. REF: LMM 72-00-00, LMM 72-00-00PROC. REF: LMM 72-00-00, LMM 72-00-00 |                                           |           |          |          |                        |           |           |             |                  |
| 723011                                                                     | NO. 1 ENGINE - NO. 4 CARBON SEAL RUNNER   |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3075639-2                                                               | MOS/MSC                                   | 25-Oct-06 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:062141803634                                                            | HRS                                       | 4857.2    |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | ENC                                       | 3730      |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                           |           |          |          |                        |           |           |             |                  |
| 723011                                                                     | NO. 2 ENGINE - NO. 4 CARBON SEAL RUNNER   |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3075639-2                                                               | MOS/MSC                                   | 05-Jun-06 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:052141802327                                                            | HRS                                       | 3701.2    |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | ENC                                       | 3369      |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                           |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9669.1
 AFL: 7372
 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                            | Unit                                      | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------|-------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 72 - ENGINE                                    |                                           |           |          |          |                        |           |           |             |                  |
| 723012                                             | NO. 1 ENGINE - NO. 4 CARBON SEAL ASSEMBLY |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3074573-2                                       | MOS/MSC                                   | 25-Oct-06 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:060515861210                                    | HRS                                       | 4857.2    |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                       | 3730      |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                           |           |          |          |                        |           |           |             |                  |
| 723012                                             | NO. 2 ENGINE - NO. 4 CARBON SEAL ASSEMBLY |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3074573-2                                       | MOS/MSC                                   | 05-Jun-06 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:060515847790                                    | HRS                                       | 3701.2    |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                       | 3369      |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                           |           |          |          |                        |           |           |             |                  |
| 723013                                             | NO. 1 ENGINE - NO. 5 CARBON SEAL RUNNER   |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3075633-2                                       | MOS/MSC                                   | 25-Oct-06 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:062141802473                                    | HRS                                       | 4857.2    |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                       | 3730      |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                           |           |          |          |                        |           |           |             |                  |
| 723013                                             | NO. 2 ENGINE - NO. 5 CARBON SEAL RUNNER   |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3075633-2                                       | MOS/MSC                                   | 05-Jun-06 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:052141806990                                    | HRS                                       | 3701.2    |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                       | 3369      |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                           |           |          |          |                        |           |           |             |                  |
| 723014                                             | NO. 1 ENGINE - NO. 5 CARBON SEAL ASSEMBLY |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3074574-2                                       | MOS/MSC                                   | 25-Oct-06 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:060515859035                                    | HRS                                       | 4857.2    |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                       | 3730      |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                           |           |          |          |                        |           |           |             |                  |
| 723014                                             | NO. 2 ENGINE - NO. 5 CARBON SEAL ASSEMBLY |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3074574-2                                       | MOS/MSC                                   | 05-Jun-06 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:060515849488                                    | HRS                                       | 3701.2    |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                       | 3369      |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                           |           |          |          |                        |           |           |             |                  |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C/W   (M)-Manual Due   U-User Task   Ex-Excluded Task

# Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 9669.1
AFL: 7372
As Of: 01-Apr-2025
02-Apr-2025 02:58 PM

| PN & SN                                                                    | Unit                                                       | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 72 - ENGINE                                                            |                                                            |           |          |          |                        |           |           |             |                  |
| 723081                                                                     | NO. 1 ENGINE - ROTATING, AIR 2ND STAGE SEAL                |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:PN                                                                      | MOS/MSC                                                    | 05-Jan-00 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                                        | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | ENC                                                        | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                                            |           |          |          |                        |           |           |             |                  |
| 723081                                                                     | NO. 2 ENGINE - ROTATING, AIR 2ND STAGE SEAL                |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:PN                                                                      | MOS/MSC                                                    | 15-Jan-00 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                                        | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | ENC                                                        | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                                            |           |          |          |                        |           |           |             |                  |
| 725007                                                                     | NO. 1 ENGINE - HIGH PRESSURE TURBINE (HPT) NOZZLE ASSEMBLY |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3060840-3                                                               | MOS/MSC                                                    | 25-Oct-06 | A/R      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                                        | 4857.2    |          | TSN 0    |                        |           |           |             |                  |
| WC#: 72.500                                                                | ENC                                                        | 3730      |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: LMM 72-50-07, LMM 72-50-07PROC. REF: LMM 72-50-07, LMM 72-50-07 |                                                            |           |          |          |                        |           |           |             |                  |
| 725007                                                                     | NO. 2 ENGINE - HIGH PRESSURE TURBINE (HPT) NOZZLE ASSEMBLY |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:PN                                                                      | MOS/MSC                                                    | 15-Jan-00 | A/R      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                                        | 0         |          | TSN 0    |                        |           |           |             |                  |
| WC#: 72.500                                                                | ENC                                                        | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: LMM 72-50-07, LMM 72-50-07PROC. REF: LMM 72-50-07, LMM 72-50-07 |                                                            |           |          |          |                        |           |           |             |                  |
| 725010                                                                     | NO. 1 ENGINE - 1ST-STAGE LOW PRESSURE TURBINE (LPT) DISC   |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3060129-7                                                               | MOS                                                        | 25-Oct-06 |          |          |                        |           |           | LIFE LIMIT  |                  |
| SN:00P21077                                                                | HRS                                                        | 4857.2    |          |          |                        |           |           |             |                  |
|                                                                            | ENC                                                        | 3730      | 12000    | TSN 3730 | (12000)<br>12058       |           | 4686      |             |                  |
| PROC. REF: LMM 72-50-04, LMM 72-50-04PROC. REF: LMM 72-50-04, LMM 72-50-04 |                                                            |           |          |          |                        |           |           |             |                  |
| 725010                                                                     | NO. 2 ENGINE - 1ST-STAGE LOW PRESSURE TURBINE (LPT) DISC   |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3060625-1                                                               | MOS                                                        | 15-Jan-00 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:990322904089                                                            | HRS                                                        | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | ENC                                                        | 0         | 12000    | TSN 0    | (12000)<br>12162       |           | 4790      |             |                  |
| PROC. REF: LMM 72-50-04, LMM 72-50-04PROC. REF: LMM 72-50-04, LMM 72-50-04 |                                                            |           |          |          |                        |           |           |             |                  |

?-Insufficient Information
S-Suppressed Requirement
\*-Estimated Due(New Requirement)
(EFF)-Effective C/W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                                                    | Unit                                                     | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|----------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 72 - ENGINE                                                            |                                                          |           |          |          |                        |           |           |             |                  |
| 725020                                                                     | NO. 1 ENGINE - 2ND-STAGE LOW PRESSURE TURBINE (LPT) DISC |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3060611-1                                                               | MOS                                                      | 05-Jan-00 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:000322903502                                                            | HRS                                                      | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | ENC                                                      | 0         | 12000    | TSN 0    | (12000)<br>12058       |           | 4686      |             |                  |
| PROC. REF: LMM 72-50-04, LMM 72-50-04PROC. REF: LMM 72-50-04, LMM 72-50-04 |                                                          |           |          |          |                        |           |           |             |                  |
| 725020                                                                     | NO. 2 ENGINE - 2ND-STAGE LOW PRESSURE TURBINE (LPT) DISC |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3060611-1                                                               | MOS                                                      | 15-Jan-00 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:000322903437                                                            | HRS                                                      | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | ENC                                                      | 0         | 12000    | TSN 0    | (12000)<br>12162       |           | 4790      |             |                  |
| PROC. REF: LMM 72-50-04, LMM 72-50-04PROC. REF: LMM 72-50-04, LMM 72-50-04 |                                                          |           |          |          |                        |           |           |             |                  |
| 725030                                                                     | NO. 1 ENGINE - 3RD-STAGE LOW PRESSURE TURBINE (LPT) DISC |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3060671-2                                                               | MOS                                                      | 05-Jan-00 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:000322900149                                                            | HRS                                                      | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | ENC                                                      | 0         | 12000    | TSN 0    | (12000)<br>12058       |           | 4686      |             |                  |
| PROC. REF: LMM 72-50-04, LMM 72-50-04PROC. REF: LMM 72-50-04, LMM 72-50-04 |                                                          |           |          |          |                        |           |           |             |                  |
| 725030                                                                     | NO. 2 ENGINE - 3RD-STAGE LOW PRESSURE TURBINE (LPT) DISC |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3060671-2                                                               | MOS                                                      | 15-Jan-00 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:000322900152                                                            | HRS                                                      | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | ENC                                                      | 0         | 12000    | TSN 0    | (12000)<br>12162       |           | 4790      |             |                  |
| PROC. REF: LMM 72-50-04, LMM 72-50-04PROC. REF: LMM 72-50-04, LMM 72-50-04 |                                                          |           |          |          |                        |           |           |             |                  |
| 725040                                                                     | NO. 1 ENGINE - HIGH PRESSURE TURBINE (HPT) DISC          |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3060555-5                                                               | MOS                                                      | 25-Oct-06 |          |          |                        |           |           | LIFE LIMIT  |                  |
| SN:061217200024                                                            | HRS                                                      | 4857.2    |          |          |                        |           |           |             |                  |
|                                                                            | ENC                                                      | 3730      | 10000    | TSN 0    | (13730)<br>13788       |           | 6416      |             |                  |
| PROC. REF: LMM 72-50-07, LMM 72-50-07PROC. REF: LMM 72-50-07, LMM 72-50-07 |                                                          |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN | Unit | C / W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|---------|------|-------|----------|----------|------------------------|-----------|-----------|-------------|----------|
|---------|------|-------|----------|----------|------------------------|-----------|-----------|-------------|----------|

|                                                                            |                                                 |           |       |            |                  |  |      |            |        |
|----------------------------------------------------------------------------|-------------------------------------------------|-----------|-------|------------|------------------|--|------|------------|--------|
| ATA 72 - ENGINE                                                            |                                                 |           |       |            |                  |  |      |            |        |
| 725040                                                                     | NO. 2 ENGINE - HIGH PRESSURE TURBINE (HPT) DISC |           |       |            |                  |  |      | Component  | ATA:72 |
| PN:3060841-1                                                               | MOS                                             | 20-Jul-15 |       |            |                  |  |      | LIFE LIMIT |        |
| SN:041217200360                                                            | HRS                                             | 6622.3    |       | TSN 4043.4 |                  |  |      |            |        |
|                                                                            | ENC                                             | 5602      | 10000 | TSN 3645   | (11957)<br>12119 |  | 4747 |            |        |
| PROC. REF: LMM 72-50-07, LMM 72-50-07PROC. REF: LMM 72-50-07, LMM 72-50-07 |                                                 |           |       |            |                  |  |      |            |        |

|            |                                                 |           |     |       |  |  |  |           |        |
|------------|-------------------------------------------------|-----------|-----|-------|--|--|--|-----------|--------|
| 725045     | NO. 1 ENGINE - HIGH PRESSURE TURBINE (HPT) ASSY |           |     |       |  |  |  | Component | ATA:72 |
| PN:PN      | MOS/MSC                                         | 05-Jan-00 | O/C | TSN 0 |  |  |  |           |        |
| SN:UNKNOWN | HRS                                             | 0         |     | TSN 0 |  |  |  |           |        |
|            | ENC                                             | 0         |     | TSN 0 |  |  |  |           |        |

|            |                                                 |           |     |       |  |  |  |           |        |
|------------|-------------------------------------------------|-----------|-----|-------|--|--|--|-----------|--------|
| 725045     | NO. 2 ENGINE - HIGH PRESSURE TURBINE (HPT) ASSY |           |     |       |  |  |  | Component | ATA:72 |
| PN:PN      | MOS/MSC                                         | 15-Jan-00 | O/C | TSN 0 |  |  |  |           |        |
| SN:UNKNOWN | HRS                                             | 0         |     | TSN 0 |  |  |  |           |        |
|            | ENC                                             | 0         |     | TSN 0 |  |  |  |           |        |

|                                                    |                         |           |       |       |                  |  |       |            |        |
|----------------------------------------------------|-------------------------|-----------|-------|-------|------------------|--|-------|------------|--------|
| 725050                                             | NO. 1 ENGINE - FAN DISC |           |       |       |                  |  |       | Component  | ATA:72 |
| PN:3060287-2                                       | MOS                     | 05-Jan-00 |       | TSN 0 |                  |  |       | LIFE LIMIT |        |
| SN:030322901250                                    | HRS                     | 0         |       | TSN 0 |                  |  |       |            |        |
|                                                    | ENC                     | 0         | 20000 | TSN 0 | (20000)<br>20058 |  | 12686 |            |        |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                         |           |       |       |                  |  |       |            |        |

|                                                    |                         |           |       |       |                  |  |       |            |        |
|----------------------------------------------------|-------------------------|-----------|-------|-------|------------------|--|-------|------------|--------|
| 725050                                             | NO. 2 ENGINE - FAN DISC |           |       |       |                  |  |       | Component  | ATA:72 |
| PN:3060287-2                                       | MOS                     | 15-Jan-00 |       | TSN 0 |                  |  |       | LIFE LIMIT |        |
| SN:010322905809                                    | HRS                     | 0         |       | TSN 0 |                  |  |       |            |        |
|                                                    | ENC                     | 0         | 20000 | TSN 0 | (20000)<br>20162 |  | 12790 |            |        |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                         |           |       |       |                  |  |       |            |        |

|                 |                                                             |           |       |       |                  |  |      |            |        |
|-----------------|-------------------------------------------------------------|-----------|-------|-------|------------------|--|------|------------|--------|
| 725060          | NO. 1 ENGINE - 1ST-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC |           |       |       |                  |  |      | Component  | ATA:72 |
| PN:3060372-1    | MOS                                                         | 05-Jan-00 |       | TSN 0 |                  |  |      | LIFE LIMIT |        |
| SN:000316002316 | HRS                                                         | 0         |       | TSN 0 |                  |  |      |            |        |
|                 | ENC                                                         | 0         | 10000 | TSN 0 | (10000)<br>10058 |  | 2686 |            |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|---------|------|-----|----------|----------|------------------------|-----------|-----------|-------------|----------|
|---------|------|-----|----------|----------|------------------------|-----------|-----------|-------------|----------|

ATA 72 - ENGINE

PROC. REF: LMM 72-30-04PROC. REF: LMM 72-30-04

| 725060                                         | NO. 2 ENGINE - 1ST-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC |           |       |       |                  |  |      | Component  | ATA:72 |
|------------------------------------------------|-------------------------------------------------------------|-----------|-------|-------|------------------|--|------|------------|--------|
| PN:3060372-1                                   | MOS                                                         | 15-Jan-00 |       | TSN 0 |                  |  |      | LIFE LIMIT |        |
| SN:000316002319                                | HRS                                                         | 0         |       | TSN 0 |                  |  |      |            |        |
|                                                | ENC                                                         | 0         | 10000 | TSN 0 | (10000)<br>10162 |  | 2790 |            |        |
| PROC. REF: LMM 72-30-04PROC. REF: LMM 72-30-04 |                                                             |           |       |       |                  |  |      |            |        |

| 725070                                         | NO. 1 ENGINE - 2ND-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC |           |       |          |                  |  |      | Component  | ATA:72 |
|------------------------------------------------|-------------------------------------------------------------|-----------|-------|----------|------------------|--|------|------------|--------|
| PN:3060608-3                                   | MOS                                                         | 25-Oct-06 |       |          |                  |  |      | LIFE LIMIT |        |
| SN:000322903502                                | HRS                                                         | 4857.2    |       |          |                  |  |      |            |        |
|                                                | ENC                                                         | 3730      | 10000 | TSN 3730 | (10000)<br>10058 |  | 2686 |            |        |
| PROC. REF: LMM 72-30-04PROC. REF: LMM 72-30-04 |                                                             |           |       |          |                  |  |      |            |        |

| 725070                                         | NO. 2 ENGINE - 2ND-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC |           |       |       |                  |  |      | Component  | ATA:72 |
|------------------------------------------------|-------------------------------------------------------------|-----------|-------|-------|------------------|--|------|------------|--------|
| PN:3060373-1                                   | MOS                                                         | 15-Jan-00 |       | TSN 0 |                  |  |      | LIFE LIMIT |        |
| SN:000316001852                                | HRS                                                         | 0         |       | TSN 0 |                  |  |      |            |        |
|                                                | ENC                                                         | 0         | 10000 | TSN 0 | (10000)<br>10162 |  | 2790 |            |        |
| PROC. REF: LMM 72-30-04PROC. REF: LMM 72-30-04 |                                                             |           |       |       |                  |  |      |            |        |

| 725071                                                                     | NO. 1 ENGINE - COMBUSTION LINER |           |     |       |  |  |  | Component | ATA:72 |
|----------------------------------------------------------------------------|---------------------------------|-----------|-----|-------|--|--|--|-----------|--------|
| PN:3060766-1                                                               | MOS/MSC                         | 28-Nov-17 | O/C | TSO 0 |  |  |  |           |        |
| SN:08P16345                                                                | HRS                             | 7696.2    |     | TSO 0 |  |  |  |           |        |
|                                                                            | ENC                             | 5895      |     | TSO 0 |  |  |  |           |        |
| PROC. REF: LMM 72-40-03, LMM 72-40-03PROC. REF: LMM 72-40-03, LMM 72-40-03 |                                 |           |     |       |  |  |  |           |        |

| 725071                                                                     | NO. 2 ENGINE - COMBUSTION LINER |           |     |       |  |  |  | Component | ATA:72 |
|----------------------------------------------------------------------------|---------------------------------|-----------|-----|-------|--|--|--|-----------|--------|
| PN:3060766-1                                                               | MOS/MSC                         | 20-Jul-15 | O/C | TSO 0 |  |  |  |           |        |
| SN:06P00417                                                                | HRS                             | 6622.3    |     | TSO 0 |  |  |  |           |        |
|                                                                            | ENC                             | 5602      |     | TSO 0 |  |  |  |           |        |
| PROC. REF: LMM 72-40-03, LMM 72-40-03PROC. REF: LMM 72-40-03, LMM 72-40-03 |                                 |           |     |       |  |  |  |           |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                                                    | Unit    | C/W                                                         | Interval | TSX/Adj.        | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------------------------------|---------|-------------------------------------------------------------|----------|-----------------|------------------------|-----------|-----------|-------------|----------|
| ATA 72 - ENGINE                                                            |         |                                                             |          |                 |                        |           |           |             |          |
| 725080                                                                     |         | NO. 1 ENGINE - 3RD-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC |          |                 |                        |           |           | Component   | ATA:72   |
| PN:3060374-1                                                               | MOS     | 05-Jan-00                                                   |          | TSN 0           |                        |           |           | LIFE LIMIT  |          |
| SN:000316002539                                                            | HRS     | 0                                                           |          | TSN 0           |                        |           |           |             |          |
|                                                                            | ENC     | 0                                                           | 10000    | TSN 0           | (10000)<br>10058       |           | 2686      |             |          |
| PROC. REF: LMM 72-30-04PROC. REF: LMM 72-30-04                             |         |                                                             |          |                 |                        |           |           |             |          |
| 725080                                                                     |         | NO. 2 ENGINE - 3RD-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC |          |                 |                        |           |           | Component   | ATA:72   |
| PN:3072417-12                                                              | MOS     | 05-Jun-06                                                   |          | TSR 0           |                        |           |           | LIFE LIMIT  |          |
| SN:000316002937                                                            | HRS     | 3701.2                                                      |          | TSR 0           |                        |           |           |             |          |
|                                                                            | ENC     | 3369                                                        | 10000    | TSN 3369, TSR 0 | (10000)<br>10162       |           | 2790      |             |          |
| PROC. REF: LMM 72-30-04PROC. REF: LMM 72-30-04                             |         |                                                             |          |                 |                        |           |           |             |          |
| 725081                                                                     |         | NO. 1 ENGINE - OUTER TRANSITION LINER                       |          |                 |                        |           |           | Component   | ATA:72   |
| PN:PN                                                                      | MOS/MSC | 05-Jan-00                                                   | O/C      | TSN 0           |                        |           |           |             |          |
| SN:UNKNOWN                                                                 | HRS     | 0                                                           |          | TSN 0           |                        |           |           |             |          |
|                                                                            | ENC     | 0                                                           |          | TSN 0           |                        |           |           |             |          |
| PROC. REF: LMM 72-40-03, LMM 72-40-03PROC. REF: LMM 72-40-03, LMM 72-40-03 |         |                                                             |          |                 |                        |           |           |             |          |
| 725081                                                                     |         | NO. 2 ENGINE - OUTER TRANSITION LINER                       |          |                 |                        |           |           | Component   | ATA:72   |
| PN:PN                                                                      | MOS/MSC | 15-Jan-00                                                   | O/C      | TSN 0           |                        |           |           |             |          |
| SN:UNKNOWN                                                                 | HRS     | 0                                                           |          | TSN 0           |                        |           |           |             |          |
|                                                                            | ENC     | 0                                                           |          | TSN 0           |                        |           |           |             |          |
| PROC. REF: LMM 72-40-03, LMM 72-40-03PROC. REF: LMM 72-40-03, LMM 72-40-03 |         |                                                             |          |                 |                        |           |           |             |          |
| 725090                                                                     |         | NO. 1 ENGINE - 4TH-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC |          |                 |                        |           |           | Component   | ATA:72   |
| PN:3075326-5                                                               | MOS     | 05-Jan-00                                                   |          | TSN 0           |                        |           |           | LIFE LIMIT  |          |
| SN:001365107764                                                            | HRS     | 0                                                           |          | TSN 0           |                        |           |           |             |          |
|                                                                            | ENC     | 0                                                           | 20000    | TSN 0           | (20000)<br>20058       |           | 12686     |             |          |
| PROC. REF: LMM 72-30-04PROC. REF: LMM 72-30-04                             |         |                                                             |          |                 |                        |           |           |             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                                                    | Unit                                                        | C / W     | Interval | TSX / Adj. | Next Due (ENG / APU) A / C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|-------------------------------------------------------------|-----------|----------|------------|----------------------------|-----------|-----------|-------------|------------------|
| ATA 72 - ENGINE                                                            |                                                             |           |          |            |                            |           |           |             |                  |
| 725090                                                                     | NO. 2 ENGINE - 4TH-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC |           |          |            |                            |           |           |             | Component ATA:72 |
| PN:3075351-12                                                              | MOS                                                         | 05-Jun-06 |          |            |                            |           |           | LIFE LIMIT  |                  |
| SN:050350107807                                                            | HRS                                                         | 3701.2    |          |            |                            |           |           |             |                  |
|                                                                            | ENC                                                         | 3369      | 20000    | TSN 0      | (23369)<br>23531           |           | 16159     |             |                  |
| PROC. REF: LMM 72-30-04PROC. REF: LMM 72-30-04                             |                                                             |           |          |            |                            |           |           |             |                  |
| 725110                                                                     | NO. 1 ENGINE - LOW PRESSURE COMPRESSOR TIE ROD              |           |          |            |                            |           |           |             | Component ATA:72 |
| PN:PN                                                                      | MOS/MSC                                                     | 05-Jan-00 | O/C      | TSN 0      |                            |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                                         | 0         |          | TSN 0      |                            |           |           |             |                  |
|                                                                            | ENC                                                         | 0         |          | TSN 0      |                            |           |           |             |                  |
| PROC. REF: LMM 72-30-10, LMM 72-30-10PROC. REF: LMM 72-30-10, LMM 72-30-10 |                                                             |           |          |            |                            |           |           |             |                  |
| 725110                                                                     | NO. 2 ENGINE - LOW PRESSURE COMPRESSOR TIE ROD              |           |          |            |                            |           |           |             | Component ATA:72 |
| PN:PN                                                                      | MOS/MSC                                                     | 15-Jan-00 | O/C      | TSN 0      |                            |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                                         | 0         |          | TSN 0      |                            |           |           |             |                  |
|                                                                            | ENC                                                         | 0         |          | TSN 0      |                            |           |           |             |                  |
| PROC. REF: LMM 72-30-10, LMM 72-30-10PROC. REF: LMM 72-30-10, LMM 72-30-10 |                                                             |           |          |            |                            |           |           |             |                  |
| 725120                                                                     | NO. 1 ENGINE - HIGH PRESSURE COMPRESSOR ROTOR IMPELLER      |           |          |            |                            |           |           |             | Component ATA:72 |
| PN:3060371-1                                                               | MOS                                                         | 05-Jan-00 |          | TSN 0      |                            |           |           | LIFE LIMIT  |                  |
| SN:005332200378                                                            | HRS                                                         | 0         |          | TSN 0      |                            |           |           |             |                  |
|                                                                            | ENC                                                         | 0         | 8000     | TSN 0      | (8000)<br>8058             |           | 686       |             |                  |
| PROC. REF: LMM 72-50-06, LMM 72-50-06PROC. REF: LMM 72-50-06, LMM 72-50-06 |                                                             |           |          |            |                            |           |           |             |                  |
| 725120                                                                     | NO. 2 ENGINE - HIGH PRESSURE COMPRESSOR ROTOR IMPELLER      |           |          |            |                            |           |           |             | Component ATA:72 |
| PN:3060371-1                                                               | MOS                                                         | 05-Jun-06 |          |            |                            |           |           | LIFE LIMIT  |                  |
| SN:060322902406                                                            | HRS                                                         | 3701.2    |          |            |                            |           |           |             |                  |
|                                                                            | ENC                                                         | 3369      | 8000     | TSN 0      | (11369)<br>11531           |           | 4159      |             |                  |
| PROC. REF: LMM 72-50-06, LMM 72-50-06PROC. REF: LMM 72-50-06, LMM 72-50-06 |                                                             |           |          |            |                            |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                                                    | Unit    | C / W                                           | Interval | TSX / Adj. | Next Due (ENG / APU) A / C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------------------------------|---------|-------------------------------------------------|----------|------------|----------------------------|-----------|-----------|-------------|----------|
| ATA 72 - ENGINE                                                            |         |                                                 |          |            |                            |           |           |             |          |
| 725130                                                                     |         | NO. 1 ENGINE - FAN SPINNER                      |          |            |                            |           |           | Component   | ATA:72   |
| PN:3060156-2                                                               | MOS     | 05-Jan-00                                       |          | TSN 0      |                            |           |           | LIFE LIMIT  |          |
| SN:002428000312                                                            | HRS     | 0                                               |          | TSN 0      |                            |           |           |             |          |
|                                                                            | ENC     | 0                                               | 20000    | TSN 0      | (20000)<br>20058           |           | 12686     |             |          |
| PROC. REF: LMM 72-70-01, LMM 72-70-01PROC. REF: LMM 72-70-01, LMM 72-70-01 |         |                                                 |          |            |                            |           |           |             |          |
| 725130                                                                     |         | NO. 2 ENGINE - FAN SPINNER                      |          |            |                            |           |           | Component   | ATA:72   |
| PN:3060156-2                                                               | MOS     | 15-Jan-00                                       |          | TSN 0      |                            |           |           | LIFE LIMIT  |          |
| SN:002428000311                                                            | HRS     | 0                                               |          | TSN 0      |                            |           |           |             |          |
|                                                                            | ENC     | 0                                               | 20000    | TSN 0      | (20000)<br>20162           |           | 12790     |             |          |
| PROC. REF: LMM 72-70-01, LMM 72-70-01PROC. REF: LMM 72-70-01, LMM 72-70-01 |         |                                                 |          |            |                            |           |           |             |          |
| 725140                                                                     |         | NO. 1 ENGINE - FAN DRIVE SHAFT                  |          |            |                            |           |           | Component   | ATA:72   |
| PN:PN                                                                      | MOS/MSC | 05-Jan-00                                       | O/C      | TSN 0      |                            |           |           |             |          |
| SN:UNKNOWN                                                                 | HRS     | 0                                               |          | TSN 0      |                            |           |           |             |          |
|                                                                            | ENC     | 0                                               |          | TSN 0      |                            |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |         |                                                 |          |            |                            |           |           |             |          |
| 725140                                                                     |         | NO. 2 ENGINE - FAN DRIVE SHAFT                  |          |            |                            |           |           | Component   | ATA:72   |
| PN:3067021-1                                                               | MOS/MSC | 23-May-07                                       | O/C      |            |                            |           |           |             |          |
| SN:970339000246                                                            | HRS     | 4564.4                                          |          |            |                            |           |           |             |          |
|                                                                            | ENC     | 4010                                            |          |            |                            |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |         |                                                 |          |            |                            |           |           |             |          |
| 725160                                                                     |         | NO. 1 ENGINE - FORWARD ROTOR HIGH PRESSURE SEAL |          |            |                            |           |           | Component   | ATA:72   |
| PN:3060698-1                                                               | MOS     | 28-Nov-17                                       |          | TSN 0      |                            |           |           | LIFE LIMIT  |          |
| SN:16-162246-03040                                                         | HRS     | 7696.2                                          |          | TSN 0      |                            |           |           |             |          |
|                                                                            | ENC     | 5895                                            | 7000     | TSN 0      | (12895)<br>12953           |           | 5581      |             |          |
| PROC. REF: LMM 72-70-03, LMM 72-70-03PROC. REF: LMM 72-70-03, LMM 72-70-03 |         |                                                 |          |            |                            |           |           |             |          |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C / W   (M)-Manual Due   U-User Task   Ex-Excluded Task



Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                                                    | Unit                                                    | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|---------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 72 - ENGINE                                                            |                                                         |           |          |          |                        |           |           |             |                  |
| 725160                                                                     | NO. 2 ENGINE - FORWARD ROTOR HIGH PRESSURE SEAL         |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3060698-1                                                               | MOS                                                     | 20-Jul-15 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:14-162246-04706                                                         | HRS                                                     | 6622.3    |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | ENC                                                     | 5602      | 7000     | TSN 0    | (12602)<br>12764       |           | 5392      |             |                  |
| PROC. REF: LMM 72-70-03, LMM 72-70-03PROC. REF: LMM 72-70-03, LMM 72-70-03 |                                                         |           |          |          |                        |           |           |             |                  |
| 725170                                                                     | NO. 1 ENGINE - HIGH PRESSURE SHOULDERED SHAFT           |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:PN                                                                      | MOS/MSC                                                 | 05-Jan-00 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | ENC                                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                                         |           |          |          |                        |           |           |             |                  |
| 725170                                                                     | NO. 2 ENGINE - HIGH PRESSURE SHOULDERED SHAFT           |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:PN                                                                      | MOS/MSC                                                 | 15-Jan-00 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | ENC                                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                                         |           |          |          |                        |           |           |             |                  |
| 725180                                                                     | NO. 1 ENGINE - COMBUSTION PLENUM CASE                   |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:PN                                                                      | MOS/MSC                                                 | 05-Jan-00 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | ENC                                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: LMM 72-40-04, LMM 72-40-04PROC. REF: LMM 72-40-04, LMM 72-40-04 |                                                         |           |          |          |                        |           |           |             |                  |
| 725180                                                                     | NO. 2 ENGINE - COMBUSTION PLENUM CASE                   |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3060534-4                                                               | MOS/MSC                                                 | 15-Jan-00 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:00P24979                                                                | HRS                                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | ENC                                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: LMM 72-40-04, LMM 72-40-04PROC. REF: LMM 72-40-04, LMM 72-40-04 |                                                         |           |          |          |                        |           |           |             |                  |
| 725210                                                                     | NO. 1 ENGINE - HIGH PRESSURE TURBINE FORWARD SEAL PLATE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3060514-1                                                               | MOS                                                     | 05-Jan-00 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:000322905164                                                            | HRS                                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | ENC                                                     | 0         | 10000    | TSN 0    | (10000)<br>10058       |           | 2686      |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                                         |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                                                    | Unit                                                            | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|-----------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 72 - ENGINE                                                            |                                                                 |           |          |          |                        |           |           |             |                  |
| 725210                                                                     | NO. 2 ENGINE - HIGH PRESSURE TURBINE FORWARD SEAL PLATE         |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3060514-1                                                               | MOS                                                             | 15-Jan-00 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:000322905162                                                            | HRS                                                             | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | ENC                                                             | 0         | 10000    | TSN 0    | (10000)<br>10162       |           | 2790      |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                                                 |           |          |          |                        |           |           |             |                  |
| 725220                                                                     | NO. 1 ENGINE - TURBINE INTERSTAGE TRANSITION DUCT               |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3060694-6                                                               | MOS/MSC                                                         | 25-Oct-06 | O/C      |          |                        |           |           |             |                  |
| SN:97P23086                                                                | HRS                                                             | 4857.2    |          |          |                        |           |           |             |                  |
|                                                                            | ENC                                                             | 3730      |          |          |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                                                 |           |          |          |                        |           |           |             |                  |
| 725220                                                                     | NO. 2 ENGINE - TURBINE INTERSTAGE TRANSITION DUCT               |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3060694-6                                                               | MOS/MSC                                                         | 20-Jul-15 | O/C      | TSO 0    |                        |           |           |             |                  |
| SN:02P01906                                                                | HRS                                                             | 6622.3    |          | TSO 0    |                        |           |           |             |                  |
|                                                                            | ENC                                                             | 5602      |          | TSO 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                                                 |           |          |          |                        |           |           |             |                  |
| 725230                                                                     | NO. 1 ENGINE - LOW PRESSURE TURBINE (LPT) 1 NOZZLE SEAL SUPPORT |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:PN                                                                      | MOS/MSC                                                         | 05-Jan-00 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                                             | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | ENC                                                             | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: LMM 72-50-04, LMM 72-50-04PROC. REF: LMM 72-50-04, LMM 72-50-04 |                                                                 |           |          |          |                        |           |           |             |                  |
| 725230                                                                     | NO. 2 ENGINE - LOW PRESSURE TURBINE (LPT) 1 NOZZLE SEAL SUPPORT |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3060693-1                                                               | MOS/MSC                                                         | 15-Jan-00 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:00P28158                                                                | HRS                                                             | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | ENC                                                             | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: LMM 72-50-04, LMM 72-50-04PROC. REF: LMM 72-50-04, LMM 72-50-04 |                                                                 |           |          |          |                        |           |           |             |                  |
| 725240                                                                     | NO. 1 ENGINE - LOW PRESSURE TURBINE (LPT) 1 NOZZLE ASSEMBLY     |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:PN                                                                      | MOS/MSC                                                         | 05-Jan-00 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                                             | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | ENC                                                             | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: LMM 72-50-04, LMM 72-50-04PROC. REF: LMM 72-50-04, LMM 72-50-04 |                                                                 |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                                                    | Unit                                                              | C / W     | Interval | TSX / Adj. | Next Due (ENG / APU) A / C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|-------------------------------------------------------------------|-----------|----------|------------|----------------------------|-----------|-----------|-------------|------------------|
| ATA 72 - ENGINE                                                            |                                                                   |           |          |            |                            |           |           |             |                  |
| 725240                                                                     | NO. 2 ENGINE - LOW PRESSURE TURBINE (LPT) 1 NOZZLE ASSEMBLY       |           |          |            |                            |           |           |             | Component ATA:72 |
| PN:3060666-7                                                               | MOS/MSC                                                           | 15-Jan-00 | O/C      | TSN 0      |                            |           |           |             |                  |
| SN:00P29069                                                                | HRS                                                               | 0         |          | TSN 0      |                            |           |           |             |                  |
|                                                                            | ENC                                                               | 0         |          | TSN 0      |                            |           |           |             |                  |
| PROC. REF: LMM 72-50-04, LMM 72-50-04PROC. REF: LMM 72-50-04, LMM 72-50-04 |                                                                   |           |          |            |                            |           |           |             |                  |
| 725250                                                                     | NO. 1 ENGINE - FORWARD SHAFT HIGH PRESSURE TURBINE (HPT) COUPLING |           |          |            |                            |           |           |             | Component ATA:72 |
| PN:PN                                                                      | MOS/MSC                                                           | 05-Jan-00 | O/C      | TSN 0      |                            |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                                               | 0         |          | TSN 0      |                            |           |           |             |                  |
|                                                                            | ENC                                                               | 0         |          | TSN 0      |                            |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                                                   |           |          |            |                            |           |           |             |                  |
| 725250                                                                     | NO. 2 ENGINE - FORWARD SHAFT HIGH PRESSURE TURBINE (HPT) COUPLING |           |          |            |                            |           |           |             | Component ATA:72 |
| PN:3060502-2                                                               | MOS/MSC                                                           | 15-Jan-00 | O/C      | TSN 0      |                            |           |           |             |                  |
| SN:00P26421                                                                | HRS                                                               | 0         |          | TSN 0      |                            |           |           |             |                  |
|                                                                            | ENC                                                               | 0         |          | TSN 0      |                            |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                                                   |           |          |            |                            |           |           |             |                  |
| 725260                                                                     | NO. 1 ENGINE - AFT HIGH PRESSURE TURBINE (HPT) SHAFT COUPLING     |           |          |            |                            |           |           |             | Component ATA:72 |
| PN:PN                                                                      | MOS/MSC                                                           | 05-Jan-00 | O/C      | TSN 0      |                            |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                                               | 0         |          | TSN 0      |                            |           |           |             |                  |
|                                                                            | ENC                                                               | 0         |          | TSN 0      |                            |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                                                   |           |          |            |                            |           |           |             |                  |
| 725260                                                                     | NO. 2 ENGINE - AFT HIGH PRESSURE TURBINE (HPT) SHAFT COUPLING     |           |          |            |                            |           |           |             | Component ATA:72 |
| PN:3060599-2                                                               | MOS/MSC                                                           | 15-Jan-00 | O/C      | TSN 0      |                            |           |           |             |                  |
| SN:00P28573                                                                | HRS                                                               | 0         |          | TSN 0      |                            |           |           |             |                  |
|                                                                            | ENC                                                               | 0         |          | TSN 0      |                            |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                                                   |           |          |            |                            |           |           |             |                  |
| 725270                                                                     | NO. 1 ENGINE - NOZZLE LOW PRESSURE TURBINE (LPT) (A5) SEAL        |           |          |            |                            |           |           |             | Component ATA:72 |
| PN:PN                                                                      | MOS/MSC                                                           | 05-Jan-00 | O/C      | TSN 0      |                            |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                                               | 0         |          | TSN 0      |                            |           |           |             |                  |
|                                                                            | ENC                                                               | 0         |          | TSN 0      |                            |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                                                   |           |          |            |                            |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                                                    | Unit                                                       | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 72 - ENGINE                                                            |                                                            |           |          |          |                        |           |           |             |                  |
| 725270                                                                     | NO. 2 ENGINE - NOZZLE LOW PRESSURE TURBINE (LPT) (A5) SEAL |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3073765-12                                                              | MOS/MSC                                                    | 15-Jan-00 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:00P29032                                                                | HRS                                                        | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | ENC                                                        | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                                            |           |          |          |                        |           |           |             |                  |
| 726005                                                                     | NO. 1 ENGINE - TRANSFER GEARBOX ASSEMBLY                   |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3070093-16                                                              | MOS/MSC                                                    | 25-Oct-06 | O/C      |          |                        |           |           |             |                  |
| SN:P10020                                                                  | HRS                                                        | 4857.2    |          |          |                        |           |           |             |                  |
|                                                                            | ENC                                                        | 3730      |          |          |                        |           |           |             |                  |
| PROC. REF: LMM 72-60-03, LMM 72-60-03PROC. REF: LMM 72-60-03, LMM 72-60-03 |                                                            |           |          |          |                        |           |           |             |                  |
| 726005                                                                     | NO. 2 ENGINE - TRANSFER GEARBOX ASSEMBLY                   |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:PN                                                                      | MOS/MSC                                                    | 15-Jan-00 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                                        | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | ENC                                                        | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: LMM 72-60-03, LMM 72-60-03PROC. REF: LMM 72-60-03, LMM 72-60-03 |                                                            |           |          |          |                        |           |           |             |                  |
| 726010                                                                     | NO. 1 ENGINE - FORWARD OIL PUMP SPUR ANNULAR BALL BEARING  |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:PN                                                                      | MOS/MSC                                                    | 05-Jan-00 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                                        | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | ENC                                                        | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00                             |                                                            |           |          |          |                        |           |           |             |                  |
| 726010                                                                     | NO. 2 ENGINE - FORWARD OIL PUMP SPUR ANNULAR BALL BEARING  |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:PN                                                                      | MOS/MSC                                                    | 15-Jan-00 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                                        | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | ENC                                                        | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00                             |                                                            |           |          |          |                        |           |           |             |                  |
| 726011                                                                     | NO. 1 ENGINE - AFT OIL PUMP SPUR ANNULAR BALL BEARING      |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:PN                                                                      | MOS/MSC                                                    | 05-Jan-00 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                                        | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | ENC                                                        | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                                            |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR    Serial: 45-145    RegNo: N942FK    HRS: 9669.1    AFL: 7372    As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                            | Unit                                                          | C / W     | Interval | TSX / Adj. | Next Due (ENG / APU) A / C | Max Limit | Remaining | Disposition | Warranty            |
|----------------------------------------------------|---------------------------------------------------------------|-----------|----------|------------|----------------------------|-----------|-----------|-------------|---------------------|
| ATA 72 - ENGINE                                    |                                                               |           |          |            |                            |           |           |             |                     |
| 726011                                             | NO. 2 ENGINE - AFT OIL PUMP SPUR ANNULAR BALL BEARING         |           |          |            |                            |           |           |             | Component    ATA:72 |
| PN:PN                                              | MOS/MSC                                                       | 15-Jan-00 | O/C      | TSN 0      |                            |           |           |             |                     |
| SN:UNKNOWN                                         | HRS                                                           | 0         |          | TSN 0      |                            |           |           |             |                     |
|                                                    | ENC                                                           | 0         |          | TSN 0      |                            |           |           |             |                     |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                               |           |          |            |                            |           |           |             |                     |
| 726012                                             | NO. 1 ENGINE - FORWARD ALTERNATOR SPU ANNULAR BALL BEARING    |           |          |            |                            |           |           |             | Component    ATA:72 |
| PN:PN                                              | MOS/MSC                                                       | 05-Jan-00 | O/C      | TSN 0      |                            |           |           |             |                     |
| SN:UNKNOWN                                         | HRS                                                           | 0         |          | TSN 0      |                            |           |           |             |                     |
|                                                    | ENC                                                           | 0         |          | TSN 0      |                            |           |           |             |                     |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                               |           |          |            |                            |           |           |             |                     |
| 726012                                             | NO. 2 ENGINE - FORWARD ALTERNATOR SPU ANNULAR BALL BEARING    |           |          |            |                            |           |           |             | Component    ATA:72 |
| PN:PN                                              | MOS/MSC                                                       | 15-Jan-00 | O/C      | TSN 0      |                            |           |           |             |                     |
| SN:UNKNOWN                                         | HRS                                                           | 0         |          | TSN 0      |                            |           |           |             |                     |
|                                                    | ENC                                                           | 0         |          | TSN 0      |                            |           |           |             |                     |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                               |           |          |            |                            |           |           |             |                     |
| 726013                                             | NO. 1 ENGINE - AFT ALTERNATOR SPU ANNULAR BEARING             |           |          |            |                            |           |           |             | Component    ATA:72 |
| PN:PN                                              | MOS/MSC                                                       | 05-Jan-00 | O/C      | TSN 0      |                            |           |           |             |                     |
| SN:UNKNOWN                                         | HRS                                                           | 0         |          | TSN 0      |                            |           |           |             |                     |
|                                                    | ENC                                                           | 0         |          | TSN 0      |                            |           |           |             |                     |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                               |           |          |            |                            |           |           |             |                     |
| 726013                                             | NO. 2 ENGINE - AFT ALTERNATOR SPU ANNULAR BEARING             |           |          |            |                            |           |           |             | Component    ATA:72 |
| PN:PN                                              | MOS/MSC                                                       | 15-Jan-00 | O/C      | TSN 0      |                            |           |           |             |                     |
| SN:UNKNOWN                                         | HRS                                                           | 0         |          | TSN 0      |                            |           |           |             |                     |
|                                                    | ENC                                                           | 0         |          | TSN 0      |                            |           |           |             |                     |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                               |           |          |            |                            |           |           |             |                     |
| 726014                                             | NO. 1 ENGINE - FORWARD AIR-OIL SEPARATOR ANNULAR BALL BEARING |           |          |            |                            |           |           |             | Component    ATA:72 |
| PN:PN                                              | MOS/MSC                                                       | 05-Jan-00 | O/C      | TSN 0      |                            |           |           |             |                     |
| SN:UNKNOWN                                         | HRS                                                           | 0         |          | TSN 0      |                            |           |           |             |                     |
|                                                    | ENC                                                           | 0         |          | TSN 0      |                            |           |           |             |                     |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                               |           |          |            |                            |           |           |             |                     |

?-Insufficient Information    S-Suppressed Requirement    \*-Estimated Due(New Requirement)    (EFF)-Effective C / W    (M)-Manual Due    U-User Task    Ex-Excluded Task

Status Report

Model: LEARJET 45XR    Serial: 45-145    RegNo: N942FK    HRS: 9669.1    AFL: 7372    As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                            | Unit    | C/W                                                               | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------|---------|-------------------------------------------------------------------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 72 - ENGINE                                    |         |                                                                   |          |          |                        |           |           |             |          |
| 726014                                             |         | NO. 2 ENGINE - FORWARD AIR-OIL SEPARATOR ANNULAR BALL BEARING     |          |          |                        |           |           | Component   | ATA:72   |
| PN:PN                                              | MOS/MSC | 15-Jan-00                                                         | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0                                                                 |          | TSN 0    |                        |           |           |             |          |
|                                                    | ENC     | 0                                                                 |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |         |                                                                   |          |          |                        |           |           |             |          |
|                                                    |         |                                                                   |          |          |                        |           |           |             |          |
| 726015                                             |         | NO. 1 ENGINE - AFT AIR-OIL SEPARATOR ANNULAR BALL BEARING         |          |          |                        |           |           | Component   | ATA:72   |
| PN:PN                                              | MOS/MSC | 05-Jan-00                                                         | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0                                                                 |          | TSN 0    |                        |           |           |             |          |
|                                                    | ENC     | 0                                                                 |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |         |                                                                   |          |          |                        |           |           |             |          |
|                                                    |         |                                                                   |          |          |                        |           |           |             |          |
| 726015                                             |         | NO. 2 ENGINE - AFT AIR-OIL SEPARATOR ANNULAR BALL BEARING         |          |          |                        |           |           | Component   | ATA:72   |
| PN:PN                                              | MOS/MSC | 15-Jan-00                                                         | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0                                                                 |          | TSN 0    |                        |           |           |             |          |
|                                                    | ENC     | 0                                                                 |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |         |                                                                   |          |          |                        |           |           |             |          |
|                                                    |         |                                                                   |          |          |                        |           |           |             |          |
| 726016                                             |         | NO. 1 ENGINE - FORWARD STARTER/GENERATOR SPU ANNULAR BALL BEARING |          |          |                        |           |           | Component   | ATA:72   |
| PN:PN                                              | MOS/MSC | 05-Jan-00                                                         | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0                                                                 |          | TSN 0    |                        |           |           |             |          |
|                                                    | ENC     | 0                                                                 |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |         |                                                                   |          |          |                        |           |           |             |          |
|                                                    |         |                                                                   |          |          |                        |           |           |             |          |
| 726016                                             |         | NO. 2 ENGINE - FORWARD STARTER/GENERATOR SPU ANNULAR BALL BEARING |          |          |                        |           |           | Component   | ATA:72   |
| PN:PN                                              | MOS/MSC | 15-Jan-00                                                         | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0                                                                 |          | TSN 0    |                        |           |           |             |          |
|                                                    | ENC     | 0                                                                 |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |         |                                                                   |          |          |                        |           |           |             |          |
|                                                    |         |                                                                   |          |          |                        |           |           |             |          |
| 726017                                             |         | NO. 1 ENGINE - AFT STARTER/GENERATOR SPU ANNULAR BEARING          |          |          |                        |           |           | Component   | ATA:72   |
| PN:PN                                              | MOS/MSC | 05-Jan-00                                                         | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                         | HRS     | 0                                                                 |          | TSN 0    |                        |           |           |             |          |
|                                                    | ENC     | 0                                                                 |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |         |                                                                   |          |          |                        |           |           |             |          |

?-Insufficient Information    S-Suppressed Requirement    \*-Estimated Due(New Requirement)    (EFF)-Effective C/W    (M)-Manual Due    U-User Task    Ex-Excluded Task

Status Report

Model: LEARJET 45XR    Serial: 45-145    RegNo: N942FK    HRS: 9669.1    AFL: 7372    As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                                                    | Unit                                                     | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty            |
|----------------------------------------------------------------------------|----------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|---------------------|
| ATA 72 - ENGINE                                                            |                                                          |           |          |          |                        |           |           |             |                     |
| 726017                                                                     | NO. 2 ENGINE - AFT STARTER/GENERATOR SPU ANNULAR BEARING |           |          |          |                        |           |           |             | Component    ATA:72 |
| PN:PN                                                                      | MOS/MSC                                                  | 15-Jan-00 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                                                 | HRS                                                      | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                                            | ENC                                                      | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                                          |           |          |          |                        |           |           |             |                     |
| 727001                                                                     | NO. 1 ENGINE - BYPASS FAN STATOR                         |           |          |          |                        |           |           |             | Component    ATA:72 |
| PN:PN                                                                      | MOS/MSC                                                  | 05-Jan-00 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                                                 | HRS                                                      | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                                            | ENC                                                      | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: LMM 72-70-04, LMM 72-70-04PROC. REF: LMM 72-70-04, LMM 72-70-04 |                                                          |           |          |          |                        |           |           |             |                     |
| 727001                                                                     | NO. 2 ENGINE - BYPASS FAN STATOR                         |           |          |          |                        |           |           |             | Component    ATA:72 |
| PN:PN                                                                      | MOS/MSC                                                  | 15-Jan-00 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                                                 | HRS                                                      | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                                            | ENC                                                      | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: LMM 72-70-04, LMM 72-70-04PROC. REF: LMM 72-70-04, LMM 72-70-04 |                                                          |           |          |          |                        |           |           |             |                     |
| 727005                                                                     | NO. 1 ENGINE - UPPER FAN DUCT ASSEMBLY                   |           |          |          |                        |           |           |             | Component    ATA:72 |
| PN:PN                                                                      | MOS/MSC                                                  | 05-Jan-00 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                                                 | HRS                                                      | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                                            | ENC                                                      | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: LMM 72-70-05, LMM 72-70-05PROC. REF: LMM 72-70-05, LMM 72-70-05 |                                                          |           |          |          |                        |           |           |             |                     |
| 727005                                                                     | NO. 2 ENGINE - UPPER FAN DUCT ASSEMBLY                   |           |          |          |                        |           |           |             | Component    ATA:72 |
| PN:PN                                                                      | MOS/MSC                                                  | 15-Jan-00 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                                                 | HRS                                                      | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                                            | ENC                                                      | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: LMM 72-70-05, LMM 72-70-05PROC. REF: LMM 72-70-05, LMM 72-70-05 |                                                          |           |          |          |                        |           |           |             |                     |
| 727006                                                                     | NO. 1 ENGINE - LOWER FAN DUCT ASSEMBLY                   |           |          |          |                        |           |           |             | Component    ATA:72 |
| PN:PN                                                                      | MOS/MSC                                                  | 05-Jan-00 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                                                 | HRS                                                      | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                                            | ENC                                                      | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: LMM 72-70-05, LMM 72-70-05PROC. REF: LMM 72-70-05, LMM 72-70-05 |                                                          |           |          |          |                        |           |           |             |                     |

?-Insufficient Information    S-Suppressed Requirement    \*-Estimated Due(New Requirement)    (EFF)-Effective C/W    (M)-Manual Due    U-User Task    Ex-Excluded Task

# Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9669.1
 AFL: 7372
 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                                                                                | Unit                                                | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|--------------------------------------------------------------------------------------------------------|-----------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 72 - ENGINE                                                                                        |                                                     |           |          |          |                        |           |           |             |                  |
| 727006                                                                                                 | NO. 2 ENGINE - LOWER FAN DUCT ASSEMBLY              |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:PN                                                                                                  | MOS/MSC                                             | 15-Jan-00 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                                             | HRS                                                 | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                                                        | ENC                                                 | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: LMM 72-70-05, LMM 72-70-05PROC. REF: LMM 72-70-05, LMM 72-70-05                             |                                                     |           |          |          |                        |           |           |             |                  |
| 727010 <sup>S</sup>                                                                                    | NO. 1 ENGINE - INSPECT BYPASS STATOR VANE ASSEMBLY. |           |          |          |                        |           |           |             | Service ATA:72   |
|                                                                                                        | MOS                                                 | 27-Aug-21 |          |          |                        |           |           |             |                  |
|                                                                                                        | HRS                                                 | 8634.1    | 1200     |          |                        |           |           |             |                  |
|                                                                                                        | ENC                                                 | 6633      |          |          |                        |           |           |             |                  |
| PROC. REF: LMM 72-70-04, LMM 72-70-04, LMM 72-70-04PROC. REF: LMM 72-70-04, LMM 72-70-04, LMM 72-70-04 |                                                     |           |          |          |                        |           |           |             |                  |
| 727010 <sup>S</sup>                                                                                    | NO. 2 ENGINE - INSPECT BYPASS STATOR VANE ASSEMBLY. |           |          |          |                        |           |           |             | Service ATA:72   |
|                                                                                                        | MOS                                                 | 27-Aug-21 |          |          |                        |           |           |             |                  |
|                                                                                                        | HRS                                                 | 7795.4    | 1200     |          |                        |           |           |             |                  |
|                                                                                                        | ENC                                                 | 6529      |          |          |                        |           |           |             |                  |
| PROC. REF: LMM 72-70-04, LMM 72-70-04, LMM 72-70-04PROC. REF: LMM 72-70-04, LMM 72-70-04, LMM 72-70-04 |                                                     |           |          |          |                        |           |           |             |                  |
| 727101                                                                                                 | NO. 1 ENGINE - NO. 1 CARBON SEAL ASSEMBLY           |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3060457-1                                                                                           | MOS/MSC                                             | 28-Nov-17 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:17-152826-59105                                                                                     | HRS                                                 | 7696.2    |          | TSN 0    |                        |           |           |             |                  |
|                                                                                                        | ENC                                                 | 5895      |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                                                     |                                                     |           |          |          |                        |           |           |             |                  |
| 727101                                                                                                 | NO. 2 ENGINE - NO. 1 CARBON SEAL ASSEMBLY           |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3060457-1                                                                                           | MOS/MSC                                             | 20-Jul-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:14-152826-73404                                                                                     | HRS                                                 | 6622.3    |          | TSN 0    |                        |           |           |             |                  |
|                                                                                                        | ENC                                                 | 5602      |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                                                     |                                                     |           |          |          |                        |           |           |             |                  |
| 727102                                                                                                 | NO. 1 ENGINE - NO. 1 CARBON SEAL RUNNER             |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:PN                                                                                                  | MOS/MSC                                             | 05-Jan-00 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                                             | HRS                                                 | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                                                        | ENC                                                 | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                                                     |                                                     |           |          |          |                        |           |           |             |                  |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C/W   (M)-Manual Due   U-User Task   Ex-Excluded Task



Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                                                    | Unit                                    | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|-----------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 72 - ENGINE                                                            |                                         |           |          |          |                        |           |           |             |                  |
| 727102                                                                     | NO. 2 ENGINE - NO. 1 CARBON SEAL RUNNER |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3075657-1                                                               | MOS/MSC                                 | 20-Jul-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:14-162397-04157                                                         | HRS                                     | 6622.3    |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | ENC                                     | 5602      |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                         |           |          |          |                        |           |           |             |                  |
| 727103                                                                     | NO. 1 ENGINE - NO. 1 BEARING ASSEMBLY   |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:PN                                                                      | MOS/MSC                                 | 05-Jan-00 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | ENC                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                         |           |          |          |                        |           |           |             |                  |
| 727103                                                                     | NO. 2 ENGINE - NO. 1 BEARING ASSEMBLY   |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:PN                                                                      | MOS/MSC                                 | 15-Jan-00 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | ENC                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                         |           |          |          |                        |           |           |             |                  |
| 727105                                                                     | NO. 1 ENGINE - HELICAL RING GEAR        |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:PN                                                                      | MOS/MSC                                 | 05-Jan-00 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | ENC                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                         |           |          |          |                        |           |           |             |                  |
| 727105                                                                     | NO. 2 ENGINE - HELICAL RING GEAR        |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:PN                                                                      | MOS/MSC                                 | 15-Jan-00 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | ENC                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                         |           |          |          |                        |           |           |             |                  |
| 727203                                                                     | NO. 1 ENGINE - NO. 3 BALL BEARING       |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:PN                                                                      | MOS/MSC                                 | 05-Jan-00 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | ENC                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: LMM 72-30-01, LMM 72-30-01PROC. REF: LMM 72-30-01, LMM 72-30-01 |                                         |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9669.1
 AFL: 7372
 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                                                    | Unit    | C / W                                     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------------------------------|---------|-------------------------------------------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 72 - ENGINE                                                            |         |                                           |          |          |                        |           |           |             |          |
| 727203                                                                     |         | NO. 2 ENGINE - NO. 3 BALL BEARING         |          |          |                        |           |           | Component   | ATA:72   |
| PN:PN                                                                      | MOS/MSC | 15-Jan-00                                 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                                                 | HRS     | 0                                         |          | TSN 0    |                        |           |           |             |          |
|                                                                            | ENC     | 0                                         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: LMM 72-30-01, LMM 72-30-01PROC. REF: LMM 72-30-01, LMM 72-30-01 |         |                                           |          |          |                        |           |           |             |          |
| 727210                                                                     |         | NO. 1 ENGINE - PLANET HOUSING ASSEMBLY    |          |          |                        |           |           | Component   | ATA:72   |
| PN:PN                                                                      | MOS/MSC | 05-Jan-00                                 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                                                 | HRS     | 0                                         |          | TSN 0    |                        |           |           |             |          |
|                                                                            | ENC     | 0                                         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: LMM 72-72-03, LMM 72-72-03PROC. REF: LMM 72-72-03, LMM 72-72-03 |         |                                           |          |          |                        |           |           |             |          |
| 727210                                                                     |         | NO. 2 ENGINE - PLANET HOUSING ASSEMBLY    |          |          |                        |           |           | Component   | ATA:72   |
| PN:PN                                                                      | MOS/MSC | 15-Jan-00                                 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                                                 | HRS     | 0                                         |          | TSN 0    |                        |           |           |             |          |
|                                                                            | ENC     | 0                                         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: LMM 72-72-03, LMM 72-72-03PROC. REF: LMM 72-72-03, LMM 72-72-03 |         |                                           |          |          |                        |           |           |             |          |
| 727210-1                                                                   |         | NO. 1 ENGINE - NO. 1 PLANET GEAR ASSEMBLY |          |          |                        |           |           | Component   | ATA:72   |
| PN:PN                                                                      | MOS/MSC | 05-Jan-00                                 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                                                 | HRS     | 0                                         |          | TSN 0    |                        |           |           |             |          |
|                                                                            | ENC     | 0                                         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: LMM 72-72-03, LMM 72-72-03PROC. REF: LMM 72-72-03, LMM 72-72-03 |         |                                           |          |          |                        |           |           |             |          |
| 727210-1                                                                   |         | NO. 2 ENGINE - NO. 1 PLANET GEAR ASSEMBLY |          |          |                        |           |           | Component   | ATA:72   |
| PN:PN                                                                      | MOS/MSC | 15-Jan-00                                 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                                                 | HRS     | 0                                         |          | TSN 0    |                        |           |           |             |          |
|                                                                            | ENC     | 0                                         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: LMM 72-72-03, LMM 72-72-03PROC. REF: LMM 72-72-03, LMM 72-72-03 |         |                                           |          |          |                        |           |           |             |          |
| 727210-2                                                                   |         | NO. 1 ENGINE - NO. 2 PLANET GEAR ASSEMBLY |          |          |                        |           |           | Component   | ATA:72   |
| PN:PN                                                                      | MOS/MSC | 05-Jan-00                                 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                                                 | HRS     | 0                                         |          | TSN 0    |                        |           |           |             |          |
|                                                                            | ENC     | 0                                         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: LMM 72-72-03, LMM 72-72-03PROC. REF: LMM 72-72-03, LMM 72-72-03 |         |                                           |          |          |                        |           |           |             |          |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C/W   (M)-Manual Due   U-User Task   Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                                                    | Unit    | C/W                                       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------------------------------|---------|-------------------------------------------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 72 - ENGINE                                                            |         |                                           |          |          |                        |           |           |             |          |
| 727210-2                                                                   |         | NO. 2 ENGINE - NO. 2 PLANET GEAR ASSEMBLY |          |          |                        |           |           | Component   | ATA:72   |
| PN:PN                                                                      | MOS/MSC | 15-Jan-00                                 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                                                 | HRS     | 0                                         |          | TSN 0    |                        |           |           |             |          |
|                                                                            | ENC     | 0                                         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: LMM 72-72-03, LMM 72-72-03PROC. REF: LMM 72-72-03, LMM 72-72-03 |         |                                           |          |          |                        |           |           |             |          |
|                                                                            |         |                                           |          |          |                        |           |           |             |          |
| 727210-3                                                                   |         | NO. 1 ENGINE - NO. 3 PLANET GEAR ASSEMBLY |          |          |                        |           |           | Component   | ATA:72   |
| PN:PN                                                                      | MOS/MSC | 05-Jan-00                                 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                                                 | HRS     | 0                                         |          | TSN 0    |                        |           |           |             |          |
|                                                                            | ENC     | 0                                         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: LMM 72-72-03, LMM 72-72-03PROC. REF: LMM 72-72-03, LMM 72-72-03 |         |                                           |          |          |                        |           |           |             |          |
|                                                                            |         |                                           |          |          |                        |           |           |             |          |
| 727210-3                                                                   |         | NO. 2 ENGINE - NO. 3 PLANET GEAR ASSEMBLY |          |          |                        |           |           | Component   | ATA:72   |
| PN:PN                                                                      | MOS/MSC | 15-Jan-00                                 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                                                 | HRS     | 0                                         |          | TSN 0    |                        |           |           |             |          |
|                                                                            | ENC     | 0                                         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: LMM 72-72-03, LMM 72-72-03PROC. REF: LMM 72-72-03, LMM 72-72-03 |         |                                           |          |          |                        |           |           |             |          |
|                                                                            |         |                                           |          |          |                        |           |           |             |          |
| 727210-4                                                                   |         | NO. 1 ENGINE - NO. 4 PLANET GEAR ASSEMBLY |          |          |                        |           |           | Component   | ATA:72   |
| PN:PN                                                                      | MOS/MSC | 05-Jan-00                                 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                                                 | HRS     | 0                                         |          | TSN 0    |                        |           |           |             |          |
|                                                                            | ENC     | 0                                         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: LMM 72-72-03, LMM 72-72-03PROC. REF: LMM 72-72-03, LMM 72-72-03 |         |                                           |          |          |                        |           |           |             |          |
|                                                                            |         |                                           |          |          |                        |           |           |             |          |
| 727210-4                                                                   |         | NO. 2 ENGINE - NO. 4 PLANET GEAR ASSEMBLY |          |          |                        |           |           | Component   | ATA:72   |
| PN:PN                                                                      | MOS/MSC | 15-Jan-00                                 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                                                 | HRS     | 0                                         |          | TSN 0    |                        |           |           |             |          |
|                                                                            | ENC     | 0                                         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: LMM 72-72-03, LMM 72-72-03PROC. REF: LMM 72-72-03, LMM 72-72-03 |         |                                           |          |          |                        |           |           |             |          |
|                                                                            |         |                                           |          |          |                        |           |           |             |          |
| 727210-5                                                                   |         | NO. 1 ENGINE - NO. 5 PLANET GEAR ASSEMBLY |          |          |                        |           |           | Component   | ATA:72   |
| PN:PN                                                                      | MOS/MSC | 05-Jan-00                                 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                                                 | HRS     | 0                                         |          | TSN 0    |                        |           |           |             |          |
|                                                                            | ENC     | 0                                         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: LMM 72-72-03, LMM 72-72-03PROC. REF: LMM 72-72-03, LMM 72-72-03 |         |                                           |          |          |                        |           |           |             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9669.1
 AFL: 7372
 As Of: 01-Apr-2025
 02-Apr-2025 02:58 PM

| PN & SN                                                                    | Unit                                       | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|--------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 72 - ENGINE                                                            |                                            |           |          |          |                        |           |           |             |                  |
| 727210-5                                                                   | NO. 2 ENGINE - NO. 5 PLANET GEAR ASSEMBLY  |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:PN                                                                      | MOS/MSC                                    | 15-Jan-00 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                        | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | ENC                                        | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: LMM 72-72-03, LMM 72-72-03PROC. REF: LMM 72-72-03, LMM 72-72-03 |                                            |           |          |          |                        |           |           |             |                  |
| ATA 73 - ENGINE FUEL AND CONTROL                                           |                                            |           |          |          |                        |           |           |             |                  |
| 730110                                                                     | NO. 1 ENGINE - FUEL CONTROL UNIT           |           |          |          |                        |           |           |             | Component ATA:73 |
| PN:3070800-37                                                              | MOS/MSC                                    | 25-Oct-06 | O/C      |          |                        |           |           |             |                  |
| SN:16529                                                                   | HRS                                        | 4857.2    |          |          |                        |           |           |             |                  |
|                                                                            | ENC                                        | 3730      |          |          |                        |           |           |             |                  |
| PROC. REF: LMM 73-20-01, LMM 73-20-01PROC. REF: LMM 73-20-01, LMM 73-20-01 |                                            |           |          |          |                        |           |           |             |                  |
| 730110                                                                     | NO. 2 ENGINE - FUEL CONTROL UNIT           |           |          |          |                        |           |           |             | Component ATA:73 |
| PN:3070800-47                                                              | MOS/MSC                                    | 27-Feb-23 | O/C      | TSO 0    |                        |           |           |             |                  |
| SN:19179                                                                   | HRS                                        | 8273.9    |          | TSO 0    |                        |           |           |             |                  |
|                                                                            | ENC                                        | 6885      |          | TSO 0    |                        |           |           |             |                  |
| PROC. REF: LMM 73-20-01, LMM 73-20-01PROC. REF: LMM 73-20-01, LMM 73-20-01 |                                            |           |          |          |                        |           |           |             |                  |
| 730120 <sup>S</sup>                                                        | NO. 1 ENGINE - REPLACE FUEL FILTER ELEMENT |           |          |          |                        |           |           |             | Service ATA:73   |
|                                                                            | MOS                                        | 22-Jun-23 |          |          |                        |           |           |             |                  |
|                                                                            | HRS                                        | 9184.4    | 600      |          |                        |           |           |             |                  |
|                                                                            | ENC                                        | 7042      |          |          |                        |           |           |             |                  |
| PROC. REF: LMM 73-21-02, LMM 73-21-02PROC. REF: LMM 73-21-02, LMM 73-21-02 |                                            |           |          |          |                        |           |           |             |                  |
| 730120 <sup>S</sup>                                                        | NO. 2 ENGINE - REPLACE FUEL FILTER ELEMENT |           |          |          |                        |           |           |             | Service ATA:73   |
|                                                                            | MOS                                        | 22-Jun-23 |          |          |                        |           |           |             |                  |
|                                                                            | HRS                                        | 8345.7    | 600      |          |                        |           |           |             |                  |
|                                                                            | ENC                                        | 6938      |          |          |                        |           |           |             |                  |
| PROC. REF: LMM 73-21-02, LMM 73-21-02PROC. REF: LMM 73-21-02, LMM 73-21-02 |                                            |           |          |          |                        |           |           |             |                  |
| 730130                                                                     | NO. 1 ENGINE - ENGINE FUEL PUMP ASSEMBLY   |           |          |          |                        |           |           |             | Component ATA:73 |
| PN:3060760-3                                                               | MOS/MSC                                    | 25-Oct-06 | O/C      |          |                        |           |           |             |                  |
| SN:0942                                                                    | HRS                                        | 4857.2    |          |          |                        |           |           |             |                  |
|                                                                            | ENC                                        | 3730      |          |          |                        |           |           |             |                  |

?-Insufficient Information    S-Suppressed Requirement    \*-Estimated Due(New Requirement)    (EFF)-Effective C/W    (M)-Manual Due    U-User Task    Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                                                                                                            | Unit    | C/W                                                 | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |  |  |  |  |  |  |
|------------------------------------------------------------------------------------------------------------------------------------|---------|-----------------------------------------------------|----------|----------|------------------------|-----------|-----------|-------------|----------|--|--|--|--|--|--|
| ATA 73 - ENGINE FUEL AND CONTROL                                                                                                   |         |                                                     |          |          |                        |           |           |             |          |  |  |  |  |  |  |
| PROC. REF: LMM 73-20-01, LMM 73-20-01, LMM 73-20-01, LMM 73-20-01PROC. REF: LMM 73-20-01, LMM 73-20-01, LMM 73-20-01, LMM 73-20-01 |         |                                                     |          |          |                        |           |           |             |          |  |  |  |  |  |  |
|                                                                                                                                    |         |                                                     |          |          |                        |           |           |             |          |  |  |  |  |  |  |
| 730130                                                                                                                             |         | NO. 2 ENGINE - ENGINE FUEL PUMP ASSEMBLY            |          |          |                        |           |           | Component   | ATA:73   |  |  |  |  |  |  |
| PN:PN                                                                                                                              | MOS/MSC | 15-Jan-00                                           | O/C      | TSN 0    |                        |           |           |             |          |  |  |  |  |  |  |
| SN:UNKNOWN                                                                                                                         | HRS     | 0                                                   | TSN 0    |          |                        |           |           |             |          |  |  |  |  |  |  |
|                                                                                                                                    | ENC     | 0                                                   | TSN 0    |          |                        |           |           |             |          |  |  |  |  |  |  |
| PROC. REF: LMM 73-20-01, LMM 73-20-01, LMM 73-20-01, LMM 73-20-01PROC. REF: LMM 73-20-01, LMM 73-20-01, LMM 73-20-01, LMM 73-20-01 |         |                                                     |          |          |                        |           |           |             |          |  |  |  |  |  |  |
|                                                                                                                                    |         |                                                     |          |          |                        |           |           |             |          |  |  |  |  |  |  |
| 731001                                                                                                                             |         | NO. 1 ENGINE - MOTIVE FLOW FUEL PUMP ASSEMBLY       |          |          |                        |           |           | Component   | ATA:73   |  |  |  |  |  |  |
| PN:3060759-1                                                                                                                       | MOS/MSC | 25-Oct-06                                           | O/C      |          |                        |           |           |             |          |  |  |  |  |  |  |
| SN:0457                                                                                                                            | HRS     | 4857.2                                              |          |          |                        |           |           |             |          |  |  |  |  |  |  |
|                                                                                                                                    | ENC     | 3730                                                |          |          |                        |           |           |             |          |  |  |  |  |  |  |
| PROC. REF: LMM 73-21-02PROC. REF: LMM 73-21-02                                                                                     |         |                                                     |          |          |                        |           |           |             |          |  |  |  |  |  |  |
|                                                                                                                                    |         |                                                     |          |          |                        |           |           |             |          |  |  |  |  |  |  |
| 731001                                                                                                                             |         | NO. 2 ENGINE - MOTIVE FLOW FUEL PUMP ASSEMBLY       |          |          |                        |           |           | Component   | ATA:73   |  |  |  |  |  |  |
| PN:3060759-1                                                                                                                       | MOS/MSC | 18-Dec-13                                           | O/C      | TSO 0    |                        |           |           |             |          |  |  |  |  |  |  |
| SN:0671                                                                                                                            | HRS     | 6312.5                                              | TSO 0    |          |                        |           |           |             |          |  |  |  |  |  |  |
|                                                                                                                                    | ENC     | 5360                                                | TSO 0    |          |                        |           |           |             |          |  |  |  |  |  |  |
| PROC. REF: LMM 73-21-02PROC. REF: LMM 73-21-02                                                                                     |         |                                                     |          |          |                        |           |           |             |          |  |  |  |  |  |  |
|                                                                                                                                    |         |                                                     |          |          |                        |           |           |             |          |  |  |  |  |  |  |
| 731005-1                                                                                                                           |         | NO. 1 ENGINE - NO. 1 FUEL MANIFOLD NOZZLE ASSEMBLY  |          |          |                        |           |           | Component   | ATA:73   |  |  |  |  |  |  |
| PN:3060540-2                                                                                                                       | MOS/MSC | 25-Oct-06                                           | O/C      |          |                        |           |           |             |          |  |  |  |  |  |  |
| SN:97-01371-430                                                                                                                    | HRS     | 4857.2                                              |          |          |                        |           |           |             |          |  |  |  |  |  |  |
|                                                                                                                                    | ENC     | 3730                                                |          |          |                        |           |           |             |          |  |  |  |  |  |  |
| PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01                                                         |         |                                                     |          |          |                        |           |           |             |          |  |  |  |  |  |  |
|                                                                                                                                    |         |                                                     |          |          |                        |           |           |             |          |  |  |  |  |  |  |
| 731005-1                                                                                                                           |         | NO. 2 ENGINE - NO. 1 FUEL MANIFOLD NOZZLE ASSEMBLY  |          |          |                        |           |           | Component   | ATA:73   |  |  |  |  |  |  |
| PN:3060540-2                                                                                                                       | MOS/MSC | 20-Jul-15                                           | O/C      | TSO 0    |                        |           |           |             |          |  |  |  |  |  |  |
| SN:020137100424                                                                                                                    | HRS     | 6622.3                                              | TSO 0    |          |                        |           |           |             |          |  |  |  |  |  |  |
|                                                                                                                                    | ENC     | 5602                                                | TSO 0    |          |                        |           |           |             |          |  |  |  |  |  |  |
| PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01                                                         |         |                                                     |          |          |                        |           |           |             |          |  |  |  |  |  |  |
|                                                                                                                                    |         |                                                     |          |          |                        |           |           |             |          |  |  |  |  |  |  |
| 731005-10                                                                                                                          |         | NO. 1 ENGINE - NO. 10 FUEL MANIFOLD NOZZLE ASSEMBLY |          |          |                        |           |           | Component   | ATA:73   |  |  |  |  |  |  |
| PN:3060540-2                                                                                                                       | MOS/MSC | 25-Oct-06                                           | O/C      |          |                        |           |           |             |          |  |  |  |  |  |  |
| SN:97-01371-1025                                                                                                                   | HRS     | 4857.2                                              |          |          |                        |           |           |             |          |  |  |  |  |  |  |
|                                                                                                                                    | ENC     | 3730                                                |          |          |                        |           |           |             |          |  |  |  |  |  |  |
| PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01                                                         |         |                                                     |          |          |                        |           |           |             |          |  |  |  |  |  |  |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C/W   (M)-Manual Due   U-User Task   Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                                                    | Unit    | C/W                                                 | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------------------------------|---------|-----------------------------------------------------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 73 - ENGINE FUEL AND CONTROL                                           |         |                                                     |          |          |                        |           |           |             |          |
| 731005-10                                                                  |         | NO. 2 ENGINE - NO. 10 FUEL MANIFOLD NOZZLE ASSEMBLY |          |          |                        |           |           | Component   | ATA:73   |
| PN:3060540-2                                                               | MOS/MSC | 20-Jul-15                                           | O/C      | TSO 0    |                        |           |           |             |          |
| SN:052923401375                                                            | HRS     | 6622.3                                              | TSO 0    |          |                        |           |           |             |          |
|                                                                            | ENC     | 5602                                                | TSO 0    |          |                        |           |           |             |          |
| PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01 |         |                                                     |          |          |                        |           |           |             |          |
| 731005-11                                                                  |         | NO. 1 ENGINE - NO. 11 FUEL MANIFOLD NOZZLE ASSEMBLY |          |          |                        |           |           | Component   | ATA:73   |
| PN:3060540-2                                                               | MOS/MSC | 25-Oct-06                                           | O/C      |          |                        |           |           |             |          |
| SN:990137101056                                                            | HRS     | 4857.2                                              |          |          |                        |           |           |             |          |
|                                                                            | ENC     | 3730                                                |          |          |                        |           |           |             |          |
| PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01 |         |                                                     |          |          |                        |           |           |             |          |
| 731005-11                                                                  |         | NO. 2 ENGINE - NO. 11 FUEL MANIFOLD NOZZLE ASSEMBLY |          |          |                        |           |           | Component   | ATA:73   |
| PN:3060540-2                                                               | MOS/MSC | 20-Jul-15                                           | O/C      | TSO 0    |                        |           |           |             |          |
| SN:010137103143                                                            | HRS     | 6622.3                                              | TSO 0    |          |                        |           |           |             |          |
|                                                                            | ENC     | 5602                                                | TSO 0    |          |                        |           |           |             |          |
| PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01 |         |                                                     |          |          |                        |           |           |             |          |
| 731005-12                                                                  |         | NO. 1 ENGINE - NO. 12 FUEL MANIFOLD NOZZLE ASSEMBLY |          |          |                        |           |           | Component   | ATA:73   |
| PN:3060540-2                                                               | MOS/MSC | 25-Oct-06                                           | O/C      |          |                        |           |           |             |          |
| SN:97-01371-400                                                            | HRS     | 4857.2                                              |          |          |                        |           |           |             |          |
|                                                                            | ENC     | 3730                                                |          |          |                        |           |           |             |          |
| PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01 |         |                                                     |          |          |                        |           |           |             |          |
| 731005-12                                                                  |         | NO. 2 ENGINE - NO. 12 FUEL MANIFOLD NOZZLE ASSEMBLY |          |          |                        |           |           | Component   | ATA:73   |
| PN:3060540-2                                                               | MOS/MSC | 20-Jul-15                                           | O/C      | TSO 0    |                        |           |           |             |          |
| SN:052923401374                                                            | HRS     | 6622.3                                              | TSO 0    |          |                        |           |           |             |          |
|                                                                            | ENC     | 5602                                                | TSO 0    |          |                        |           |           |             |          |
| PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01 |         |                                                     |          |          |                        |           |           |             |          |
| 731005-2                                                                   |         | NO. 1 ENGINE - NO. 2 FUEL MANIFOLD NOZZLE ASSEMBLY  |          |          |                        |           |           | Component   | ATA:73   |
| PN:3060540-2                                                               | MOS/MSC | 25-Oct-06                                           | O/C      |          |                        |           |           |             |          |
| SN:010137102472                                                            | HRS     | 4857.2                                              |          |          |                        |           |           |             |          |
|                                                                            | ENC     | 3730                                                |          |          |                        |           |           |             |          |
| PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01 |         |                                                     |          |          |                        |           |           |             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR    Serial: 45-145    RegNo: N942FK    HRS: 9669.1    AFL: 7372    As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                                                    | Unit    | C/W                                                | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------------------------------|---------|----------------------------------------------------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 73 - ENGINE FUEL AND CONTROL                                           |         |                                                    |          |          |                        |           |           |             |          |
| 731005-2                                                                   |         | NO. 2 ENGINE - NO. 2 FUEL MANIFOLD NOZZLE ASSEMBLY |          |          |                        |           |           | Component   | ATA:73   |
| PN:3060540-2                                                               | MOS/MSC | 20-Jul-15                                          | O/C      | TSO 0    |                        |           |           |             |          |
| SN:052923401378                                                            | HRS     | 6622.3                                             |          | TSO 0    |                        |           |           |             |          |
|                                                                            | ENC     | 5602                                               |          | TSO 0    |                        |           |           |             |          |
| PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01 |         |                                                    |          |          |                        |           |           |             |          |
| 731005-3                                                                   |         | NO. 1 ENGINE - NO. 3 FUEL MANIFOLD NOZZLE ASSEMBLY |          |          |                        |           |           | Component   | ATA:73   |
| PN:3060540-2                                                               | MOS/MSC | 25-Oct-06                                          | O/C      |          |                        |           |           |             |          |
| SN:97-01371-398                                                            | HRS     | 4857.2                                             |          |          |                        |           |           |             |          |
|                                                                            | ENC     | 3730                                               |          |          |                        |           |           |             |          |
| PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01 |         |                                                    |          |          |                        |           |           |             |          |
| 731005-3                                                                   |         | NO. 2 ENGINE - NO. 3 FUEL MANIFOLD NOZZLE ASSEMBLY |          |          |                        |           |           | Component   | ATA:73   |
| PN:3060540-2                                                               | MOS/MSC | 20-Jul-15                                          | O/C      | TSO 0    |                        |           |           |             |          |
| SN:032923401169                                                            | HRS     | 6622.3                                             |          | TSO 0    |                        |           |           |             |          |
|                                                                            | ENC     | 5602                                               |          | TSO 0    |                        |           |           |             |          |
| PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01 |         |                                                    |          |          |                        |           |           |             |          |
| 731005-4                                                                   |         | NO. 1 ENGINE - NO. 4 FUEL MANIFOLD NOZZLE ASSEMBLY |          |          |                        |           |           | Component   | ATA:73   |
| PN:3060540-2                                                               | MOS/MSC | 25-Oct-06                                          | O/C      |          |                        |           |           |             |          |
| SN:97-01371-572                                                            | HRS     | 4857.2                                             |          |          |                        |           |           |             |          |
|                                                                            | ENC     | 3730                                               |          |          |                        |           |           |             |          |
| PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01 |         |                                                    |          |          |                        |           |           |             |          |
| 731005-4                                                                   |         | NO. 2 ENGINE - NO. 4 FUEL MANIFOLD NOZZLE ASSEMBLY |          |          |                        |           |           | Component   | ATA:73   |
| PN:3060540-2                                                               | MOS/MSC | 20-Jul-15                                          | O/C      | TSO 0    |                        |           |           |             |          |
| SN:032923401065                                                            | HRS     | 6622.3                                             |          | TSO 0    |                        |           |           |             |          |
|                                                                            | ENC     | 5602                                               |          | TSO 0    |                        |           |           |             |          |
| PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01 |         |                                                    |          |          |                        |           |           |             |          |
| 731005-5                                                                   |         | NO. 1 ENGINE - NO. 5 FUEL MANIFOLD NOZZLE ASSEMBLY |          |          |                        |           |           | Component   | ATA:73   |
| PN:3060540-2                                                               | MOS/MSC | 25-Oct-06                                          | O/C      |          |                        |           |           |             |          |
| SN:990137101033                                                            | HRS     | 4857.2                                             |          |          |                        |           |           |             |          |
|                                                                            | ENC     | 3730                                               |          |          |                        |           |           |             |          |
| PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01 |         |                                                    |          |          |                        |           |           |             |          |

?-Insufficient Information    S-Suppressed Requirement    \*-Estimated Due(New Requirement)    (EFF)-Effective C/W    (M)-Manual Due    U-User Task    Ex-Excluded Task

Status Report

Model: LEARJET 45XR    Serial: 45-145    RegNo: N942FK    HRS: 9669.1    AFL: 7372    As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                                                    | Unit    | C/W                                                | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------------------------------|---------|----------------------------------------------------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 73 - ENGINE FUEL AND CONTROL                                           |         |                                                    |          |          |                        |           |           |             |          |
| 731005-5                                                                   |         | NO. 2 ENGINE - NO. 5 FUEL MANIFOLD NOZZLE ASSEMBLY |          |          |                        |           |           | Component   | ATA:73   |
| PN:3060540-2                                                               | MOS/MSC | 20-Jul-15                                          | O/C      | TSO 0    |                        |           |           |             |          |
| SN:072923400480                                                            | HRS     | 6622.3                                             | TSO 0    |          |                        |           |           |             |          |
|                                                                            | ENC     | 5602                                               | TSO 0    |          |                        |           |           |             |          |
| PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01 |         |                                                    |          |          |                        |           |           |             |          |
| 731005-6                                                                   |         | NO. 1 ENGINE - NO. 6 FUEL MANIFOLD NOZZLE ASSEMBLY |          |          |                        |           |           | Component   | ATA:73   |
| PN:3060540-2                                                               | MOS/MSC | 25-Oct-06                                          | O/C      |          |                        |           |           |             |          |
| SN:990137101059                                                            | HRS     | 4857.2                                             |          |          |                        |           |           |             |          |
|                                                                            | ENC     | 3730                                               |          |          |                        |           |           |             |          |
| PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01 |         |                                                    |          |          |                        |           |           |             |          |
| 731005-6                                                                   |         | NO. 2 ENGINE - NO. 6 FUEL MANIFOLD NOZZLE ASSEMBLY |          |          |                        |           |           | Component   | ATA:73   |
| PN:3060540-2                                                               | MOS/MSC | 20-Jul-15                                          | O/C      | TSO 0    |                        |           |           |             |          |
| SN:052923400974                                                            | HRS     | 6622.3                                             | TSO 0    |          |                        |           |           |             |          |
|                                                                            | ENC     | 5602                                               | TSO 0    |          |                        |           |           |             |          |
| PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01 |         |                                                    |          |          |                        |           |           |             |          |
| 731005-7                                                                   |         | NO. 1 ENGINE - NO. 7 FUEL MANIFOLD NOZZLE ASSEMBLY |          |          |                        |           |           | Component   | ATA:73   |
| PN:3060540-2                                                               | MOS/MSC | 25-Oct-06                                          | O/C      |          |                        |           |           |             |          |
| SN:97-01371-542                                                            | HRS     | 4857.2                                             |          |          |                        |           |           |             |          |
|                                                                            | ENC     | 3730                                               |          |          |                        |           |           |             |          |
| PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01 |         |                                                    |          |          |                        |           |           |             |          |
| 731005-7                                                                   |         | NO. 2 ENGINE - NO. 7 FUEL MANIFOLD NOZZLE ASSEMBLY |          |          |                        |           |           | Component   | ATA:73   |
| PN:3060540-2                                                               | MOS/MSC | 20-Jul-15                                          | O/C      | TSO 0    |                        |           |           |             |          |
| SN:052623401379                                                            | HRS     | 6622.3                                             | TSO 0    |          |                        |           |           |             |          |
|                                                                            | ENC     | 5602                                               | TSO 0    |          |                        |           |           |             |          |
| PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01 |         |                                                    |          |          |                        |           |           |             |          |
| 731005-8                                                                   |         | NO. 1 ENGINE - NO. 8 FUEL MANIFOLD NOZZLE ASSEMBLY |          |          |                        |           |           | Component   | ATA:73   |
| PN:3060540-2                                                               | MOS/MSC | 25-Oct-06                                          | O/C      |          |                        |           |           |             |          |
| SN:022923401439                                                            | HRS     | 4857.2                                             |          |          |                        |           |           |             |          |
|                                                                            | ENC     | 3730                                               |          |          |                        |           |           |             |          |
| PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01 |         |                                                    |          |          |                        |           |           |             |          |

?-Insufficient Information    S-Suppressed Requirement    \*-Estimated Due(New Requirement)    (EFF)-Effective C/W    (M)-Manual Due    U-User Task    Ex-Excluded Task



Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                                                    | Unit    | C/W                                                      | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------------------------------|---------|----------------------------------------------------------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 73 - ENGINE FUEL AND CONTROL                                           |         |                                                          |          |          |                        |           |           |             |          |
| 731005-8                                                                   |         | NO. 2 ENGINE - NO. 8 FUEL MANIFOLD NOZZLE ASSEMBLY       |          |          |                        |           |           | Component   | ATA:73   |
| PN:3060540-2                                                               | MOS/MSC | 20-Jul-15                                                | O/C      | TSO 0    |                        |           |           |             |          |
| SN:052923401376                                                            | HRS     | 6622.3                                                   | TSO 0    |          |                        |           |           |             |          |
|                                                                            | ENC     | 5602                                                     | TSO 0    |          |                        |           |           |             |          |
| PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01 |         |                                                          |          |          |                        |           |           |             |          |
| 731005-9                                                                   |         | NO. 1 ENGINE - NO. 9 FUEL MANIFOLD NOZZLE ASSEMBLY       |          |          |                        |           |           | Component   | ATA:73   |
| PN:3060540-2                                                               | MOS/MSC | 25-Oct-06                                                | O/C      |          |                        |           |           |             |          |
| SN:97-01371-562                                                            | HRS     | 4857.2                                                   |          |          |                        |           |           |             |          |
|                                                                            | ENC     | 3730                                                     |          |          |                        |           |           |             |          |
| PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01 |         |                                                          |          |          |                        |           |           |             |          |
| 731005-9                                                                   |         | NO. 2 ENGINE - NO. 9 FUEL MANIFOLD NOZZLE ASSEMBLY       |          |          |                        |           |           | Component   | ATA:73   |
| PN:3060540-2                                                               | MOS/MSC | 20-Jul-15                                                | O/C      | TSO 0    |                        |           |           |             |          |
| SN:000137102869                                                            | HRS     | 6622.3                                                   | TSO 0    |          |                        |           |           |             |          |
|                                                                            | ENC     | 5602                                                     | TSO 0    |          |                        |           |           |             |          |
| PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01 |         |                                                          |          |          |                        |           |           |             |          |
| 731015                                                                     |         | NO. 1 ENGINE - FUEL PUMP PRESSURE DIFFERENTIAL INDICATOR |          |          |                        |           |           | Component   | ATA:73   |
| PN:PN                                                                      | MOS/MSC | 05-Jan-00                                                | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                                                 | HRS     | 0                                                        | TSN 0    |          |                        |           |           |             |          |
|                                                                            | ENC     | 0                                                        | TSN 0    |          |                        |           |           |             |          |
| PROC. REF: LMM 73-20-01, LMM 73-20-01PROC. REF: LMM 73-20-01, LMM 73-20-01 |         |                                                          |          |          |                        |           |           |             |          |
| 731015                                                                     |         | NO. 2 ENGINE - FUEL PUMP PRESSURE DIFFERENTIAL INDICATOR |          |          |                        |           |           | Component   | ATA:73   |
| PN:PN                                                                      | MOS/MSC | 15-Jan-00                                                | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                                                 | HRS     | 0                                                        | TSN 0    |          |                        |           |           |             |          |
|                                                                            | ENC     | 0                                                        | TSN 0    |          |                        |           |           |             |          |
| PROC. REF: LMM 73-20-01, LMM 73-20-01PROC. REF: LMM 73-20-01, LMM 73-20-01 |         |                                                          |          |          |                        |           |           |             |          |
| 731110                                                                     |         | NO. 1 ENGINE - PRESSURE LIMITER (PCD) VALVE              |          |          |                        |           |           | Component   | ATA:73   |
| PN:PN                                                                      | MOS/MSC | 05-Jan-00                                                | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                                                 | HRS     | 0                                                        | TSN 0    |          |                        |           |           |             |          |
|                                                                            | ENC     | 0                                                        | TSN 0    |          |                        |           |           |             |          |
| PROC. REF: LMM 73-20-01, LMM 73-20-01PROC. REF: LMM 73-20-01, LMM 73-20-01 |         |                                                          |          |          |                        |           |           |             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                                                    | Unit                                                      | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|-----------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 73 - ENGINE FUEL AND CONTROL                                           |                                                           |           |          |          |                        |           |           |             |                  |
| 731110                                                                     | NO. 2 ENGINE - PRESSURE LIMITER (PCD) VALVE               |           |          |          |                        |           |           |             | Component ATA:73 |
| PN:PN                                                                      | MOS/MSC                                                   | 15-Jan-00 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                                       | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | ENC                                                       | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: LMM 73-20-01, LMM 73-20-01PROC. REF: LMM 73-20-01, LMM 73-20-01 |                                                           |           |          |          |                        |           |           |             |                  |
| 731120                                                                     | NO. 1 ENGINE - FUEL FLOW DIVIDER/DRAIN VALVE              |           |          |          |                        |           |           |             | Component ATA:73 |
| PN:PN                                                                      | MOS/MSC                                                   | 05-Jan-00 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                                       | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | ENC                                                       | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                                           |           |          |          |                        |           |           |             |                  |
| 731120                                                                     | NO. 2 ENGINE - FUEL FLOW DIVIDER/DRAIN VALVE              |           |          |          |                        |           |           |             | Component ATA:73 |
| PN:PN                                                                      | MOS/MSC                                                   | 15-Jan-00 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                                       | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | ENC                                                       | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                                           |           |          |          |                        |           |           |             |                  |
| 732102                                                                     | NO. 1 ENGINE - RELIEF VALVE                               |           |          |          |                        |           |           |             | Component ATA:73 |
| PN:PN                                                                      | MOS/MSC                                                   | 05-Jan-00 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                                       | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | ENC                                                       | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                                           |           |          |          |                        |           |           |             |                  |
| 732102                                                                     | NO. 2 ENGINE - RELIEF VALVE                               |           |          |          |                        |           |           |             | Component ATA:73 |
| PN:PN                                                                      | MOS/MSC                                                   | 15-Jan-00 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                                       | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | ENC                                                       | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                                           |           |          |          |                        |           |           |             |                  |
| 732120 <sup>S</sup>                                                        | NO. 1 ENGINE - INSPECT MOTIVE FLOW FUEL PUMP DRIVE SPLINE |           |          |          |                        |           |           |             | Service ATA:73   |
|                                                                            | MOS                                                       | 22-Jun-23 |          |          |                        |           |           |             |                  |
|                                                                            | HRS                                                       | 9184.4    | 600      |          |                        |           |           |             |                  |
|                                                                            | ENC                                                       | 7042      |          |          |                        |           |           |             |                  |
| PROC. REF: LMM 72-00-00, LMM 73-21-04PROC. REF: LMM 72-00-00, LMM 73-21-04 |                                                           |           |          |          |                        |           |           |             |                  |
|                                                                            |                                                           |           |          |          |                        |           |           |             | PKG:0            |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 9669.1
AFL: 7372
As Of: 01-Apr-2025
02-Apr-2025 02:58 PM

| PN & SN                                                                    | Unit    | C/W                                                       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------------------------------|---------|-----------------------------------------------------------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 73 - ENGINE FUEL AND CONTROL                                           |         |                                                           |          |          |                        |           |           |             |          |
| 732120 <sup>S</sup>                                                        |         | NO. 2 ENGINE - INSPECT MOTIVE FLOW FUEL PUMP DRIVE SPLINE |          |          |                        |           |           | Service     | ATA:73   |
|                                                                            | MOS     | 22-Jun-23                                                 |          |          |                        |           |           |             |          |
|                                                                            | HRS     | 8345.7                                                    | 600      |          |                        |           |           |             |          |
|                                                                            | ENC     | 6938                                                      |          |          |                        |           |           |             |          |
| PROC. REF: LMM 72-00-00, LMM 73-21-04PROC. REF: LMM 72-00-00, LMM 73-21-04 |         |                                                           |          |          |                        |           |           |             |          |
| 733001                                                                     |         | NO. 1 ENGINE FUEL FLOW TRANSDUCER                         |          |          |                        |           |           | Component   | ATA:73   |
| PN:PN                                                                      | MOS/MSC | 09-Mar-01                                                 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                                                 | HRS     | 0                                                         |          | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL     | 0                                                         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 73-31-01PROC. REF: AMM 73-31-01                             |         |                                                           |          |          |                        |           |           |             |          |
| 733002                                                                     |         | NO. 2 ENGINE FUEL FLOW TRANSDUCER                         |          |          |                        |           |           | Component   | ATA:73   |
| PN:PN                                                                      | MOS/MSC | 09-Mar-01                                                 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                                                 | HRS     | 0                                                         |          | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL     | 0                                                         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 73-31-01PROC. REF: AMM 73-31-01                             |         |                                                           |          |          |                        |           |           |             |          |
| 733013                                                                     |         | DUAL FUEL FLOW (DFFC) CONVERTER                           |          |          |                        |           |           | Component   | ATA:73   |
| PN:PN                                                                      | MOS/MSC | 09-Mar-01                                                 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                                                 | HRS     | 0                                                         |          | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL     | 0                                                         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 73-31-02PROC. REF: AMM 73-31-02                             |         |                                                           |          |          |                        |           |           |             |          |
| 733031                                                                     |         | LEFT ENGINE FUEL TEMPERATURE BULB                         |          |          |                        |           |           | Component   | ATA:73   |
| PN:PN                                                                      | MOS/MSC | 09-Mar-01                                                 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                                                 | HRS     | 0                                                         |          | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL     | 0                                                         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 73-31-03PROC. REF: AMM 73-31-03                             |         |                                                           |          |          |                        |           |           |             |          |
| 733032                                                                     |         | RIGHT ENGINE FUEL TEMPERATURE BULB                        |          |          |                        |           |           | Component   | ATA:73   |
| PN:PN                                                                      | MOS/MSC | 09-Mar-01                                                 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                                                 | HRS     | 0                                                         |          | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL     | 0                                                         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 73-31-03PROC. REF: AMM 73-31-03                             |         |                                                           |          |          |                        |           |           |             |          |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C/W   (M)-Manual Due   U-User Task   Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN | Unit | C / W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|---------|------|-------|----------|----------|------------------------|-----------|-----------|-------------|----------|
|---------|------|-------|----------|----------|------------------------|-----------|-----------|-------------|----------|

ATA 74 - IGNITION

|                                                                            |                              |           |     |       |  |  |  |           |        |
|----------------------------------------------------------------------------|------------------------------|-----------|-----|-------|--|--|--|-----------|--------|
| 740110                                                                     | NO. 1 ENGINE - IGNITION UNIT |           |     |       |  |  |  | Component | ATA:74 |
| PN:PN                                                                      | MOS/MSC                      | 05-Jan-00 | O/C | TSN 0 |  |  |  |           |        |
| SN:UNKNOWN                                                                 | HRS                          | 0         |     | TSN 0 |  |  |  |           |        |
|                                                                            | ENC                          | 0         |     | TSN 0 |  |  |  |           |        |
| PROC. REF: LMM 74-00-01, LMM 74-00-01PROC. REF: LMM 74-00-01, LMM 74-00-01 |                              |           |     |       |  |  |  |           |        |

|                                                                            |                              |           |     |       |  |  |  |           |        |
|----------------------------------------------------------------------------|------------------------------|-----------|-----|-------|--|--|--|-----------|--------|
| 740110                                                                     | NO. 2 ENGINE - IGNITION UNIT |           |     |       |  |  |  | Component | ATA:74 |
| PN:PN                                                                      | MOS/MSC                      | 15-Jan-00 | O/C | TSN 0 |  |  |  |           |        |
| SN:UNKNOWN                                                                 | HRS                          | 0         |     | TSN 0 |  |  |  |           |        |
|                                                                            | ENC                          | 0         |     | TSN 0 |  |  |  |           |        |
| PROC. REF: LMM 74-00-01, LMM 74-00-01PROC. REF: LMM 74-00-01, LMM 74-00-01 |                              |           |     |       |  |  |  |           |        |

|                                                                            |                                                     |           |     |       |  |  |  |           |        |
|----------------------------------------------------------------------------|-----------------------------------------------------|-----------|-----|-------|--|--|--|-----------|--------|
| 740130                                                                     | NO. 1 ENGINE - 5 O'CLOCK IGNITER (#1 POSITION) PLUG |           |     |       |  |  |  | Component | ATA:74 |
| PN:3074541-4                                                               | MOS/MSC                                             | 28-Nov-17 | O/C | TSN 0 |  |  |  |           |        |
| SN:UNKNOWN                                                                 | HRS                                                 | 7696.2    |     | TSN 0 |  |  |  |           |        |
|                                                                            | ENC                                                 | 5895      |     | TSN 0 |  |  |  |           |        |
| PROC. REF: LMM 74-00-01, LMM 74-00-01PROC. REF: LMM 74-00-01, LMM 74-00-01 |                                                     |           |     |       |  |  |  |           |        |

|                                                                            |                                                     |           |     |       |  |  |  |           |        |
|----------------------------------------------------------------------------|-----------------------------------------------------|-----------|-----|-------|--|--|--|-----------|--------|
| 740130                                                                     | NO. 2 ENGINE - 5 O'CLOCK IGNITER (#1 POSITION) PLUG |           |     |       |  |  |  | Component | ATA:74 |
| PN:3074541-4                                                               | MOS/MSC                                             | 18-Aug-22 | O/C | TSN 0 |  |  |  |           |        |
| SN:UNKNOWN                                                                 | HRS                                                 | 8169.8    |     | TSN 0 |  |  |  |           |        |
|                                                                            | ENC                                                 | 6832      |     | TSN 0 |  |  |  |           |        |
| PROC. REF: LMM 74-00-01, LMM 74-00-01PROC. REF: LMM 74-00-01, LMM 74-00-01 |                                                     |           |     |       |  |  |  |           |        |

|                     |                                                                   |           |      |  |  |  |  |         |        |
|---------------------|-------------------------------------------------------------------|-----------|------|--|--|--|--|---------|--------|
| 740140 <sup>S</sup> | NO. 1 ENGINE - REMOVE AND INSPECT 5 O'CLOCK IGNITER PLUG AND LEAD |           |      |  |  |  |  | Service | ATA:74 |
|                     | MOS                                                               | 22-Jun-23 |      |  |  |  |  |         |        |
|                     | HRS                                                               | 9184.4    | 1600 |  |  |  |  |         |        |
|                     | ENC                                                               | 7042      |      |  |  |  |  |         |        |
|                     |                                                                   |           |      |  |  |  |  | PKG:0   |        |

|                     |                                                                   |           |      |  |  |  |  |         |        |
|---------------------|-------------------------------------------------------------------|-----------|------|--|--|--|--|---------|--------|
| 740140 <sup>S</sup> | NO. 2 ENGINE - REMOVE AND INSPECT 5 O'CLOCK IGNITER PLUG AND LEAD |           |      |  |  |  |  | Service | ATA:74 |
|                     | MOS                                                               | 18-Aug-22 |      |  |  |  |  |         |        |
|                     | HRS                                                               | 8169.8    | 1600 |  |  |  |  |         |        |
|                     | ENC                                                               | 6832      |      |  |  |  |  |         |        |
|                     |                                                                   |           |      |  |  |  |  | PKG:0   |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN | Unit | C / W | Interval | TSX / Adj. | Next Due (ENG / APU) A / C | Max Limit | Remaining | Disposition | Warranty |
|---------|------|-------|----------|------------|----------------------------|-----------|-----------|-------------|----------|
|---------|------|-------|----------|------------|----------------------------|-----------|-----------|-------------|----------|

ATA 74 - IGNITION

|                                                                            |                                                     |           |     |       |  |  |  |           |        |
|----------------------------------------------------------------------------|-----------------------------------------------------|-----------|-----|-------|--|--|--|-----------|--------|
| 740150                                                                     | NO. 1 ENGINE - 7 O'CLOCK IGNITER (#2 POSITION) PLUG |           |     |       |  |  |  | Component | ATA:74 |
| PN:3074541-4                                                               | MOS/MSC                                             | 28-Nov-17 | O/C | TSN 0 |  |  |  |           |        |
| SN:UNKNOWN                                                                 | HRS                                                 | 7696.2    |     | TSN 0 |  |  |  |           |        |
|                                                                            | ENC                                                 | 5895      |     | TSN 0 |  |  |  |           |        |
| PROC. REF: LMM 74-00-01, LMM 74-00-01PROC. REF: LMM 74-00-01, LMM 74-00-01 |                                                     |           |     |       |  |  |  |           |        |

|                                                                            |                                                     |           |     |       |  |  |  |           |        |
|----------------------------------------------------------------------------|-----------------------------------------------------|-----------|-----|-------|--|--|--|-----------|--------|
| 740150                                                                     | NO. 2 ENGINE - 7 O'CLOCK IGNITER (#2 POSITION) PLUG |           |     |       |  |  |  | Component | ATA:74 |
| PN:3074541-4                                                               | MOS/MSC                                             | 18-Aug-22 | O/C | TSN 0 |  |  |  |           |        |
| SN:UNKNOWN                                                                 | HRS                                                 | 8169.8    |     | TSN 0 |  |  |  |           |        |
|                                                                            | ENC                                                 | 6832      |     | TSN 0 |  |  |  |           |        |
| PROC. REF: LMM 74-00-01, LMM 74-00-01PROC. REF: LMM 74-00-01, LMM 74-00-01 |                                                     |           |     |       |  |  |  |           |        |

|                                                |                                                                   |           |      |  |  |  |  |         |        |
|------------------------------------------------|-------------------------------------------------------------------|-----------|------|--|--|--|--|---------|--------|
| 740160 <sup>S</sup>                            | NO. 1 ENGINE - REMOVE AND INSPECT 7 O'CLOCK IGNITER PLUG AND LEAD |           |      |  |  |  |  | Service | ATA:74 |
|                                                | MOS                                                               | 22-Jun-23 |      |  |  |  |  |         |        |
|                                                | HRS                                                               | 9184.4    | 1600 |  |  |  |  |         |        |
|                                                | ENC                                                               | 7042      |      |  |  |  |  |         |        |
| PROC. REF: LMM 74-00-01PROC. REF: LMM 74-00-01 |                                                                   |           |      |  |  |  |  | PKG:0   |        |

|                                                |                                                                   |           |      |  |  |  |  |         |        |
|------------------------------------------------|-------------------------------------------------------------------|-----------|------|--|--|--|--|---------|--------|
| 740160 <sup>S</sup>                            | NO. 2 ENGINE - REMOVE AND INSPECT 7 O'CLOCK IGNITER PLUG AND LEAD |           |      |  |  |  |  | Service | ATA:74 |
|                                                | MOS                                                               | 18-Aug-22 |      |  |  |  |  |         |        |
|                                                | HRS                                                               | 8169.8    | 1600 |  |  |  |  |         |        |
|                                                | ENC                                                               | 6832      |      |  |  |  |  |         |        |
| PROC. REF: LMM 74-00-01PROC. REF: LMM 74-00-01 |                                                                   |           |      |  |  |  |  | PKG:0   |        |

|                                                                            |                                                       |           |     |       |  |  |  |           |        |
|----------------------------------------------------------------------------|-------------------------------------------------------|-----------|-----|-------|--|--|--|-----------|--------|
| 742011                                                                     | NO. 1 ENGINE - NO. 1 IGNITION (IPC 20 REFERENCE) LEAD |           |     |       |  |  |  | Component | ATA:74 |
| PN:3060722-11                                                              | MOS/MSC                                               | 22-Jun-23 | O/C | TSN 0 |  |  |  |           |        |
| SN:S23100003                                                               | HRS                                                   | 9184.4    |     | TSN 0 |  |  |  |           |        |
|                                                                            | ENC                                                   | 7042      |     | TSN 0 |  |  |  |           |        |
| PROC. REF: LMM 74-00-01, LMM 74-00-01PROC. REF: LMM 74-00-01, LMM 74-00-01 |                                                       |           |     |       |  |  |  |           |        |

|                                                                            |                                                       |           |     |       |  |  |  |           |        |
|----------------------------------------------------------------------------|-------------------------------------------------------|-----------|-----|-------|--|--|--|-----------|--------|
| 742011                                                                     | NO. 2 ENGINE - NO. 1 IGNITION (IPC 20 REFERENCE) LEAD |           |     |       |  |  |  | Component | ATA:74 |
| PN:9043913                                                                 | MOS/MSC                                               | 20-Jul-15 | O/C | TSN 0 |  |  |  |           |        |
| SN:UNKNOWN                                                                 | HRS                                                   | 6622.3    |     | TSN 0 |  |  |  |           |        |
|                                                                            | ENC                                                   | 5602      |     | TSN 0 |  |  |  |           |        |
| PROC. REF: LMM 74-00-01, LMM 74-00-01PROC. REF: LMM 74-00-01, LMM 74-00-01 |                                                       |           |     |       |  |  |  |           |        |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C / W   (M)-Manual Due   U-User Task   Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                                                    | Unit                                                  | C / W     | Interval | TSX / Adj. | Next Due (ENG / APU) A / C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|-------------------------------------------------------|-----------|----------|------------|----------------------------|-----------|-----------|-------------|------------------|
| ATA 74 - IGNITION                                                          |                                                       |           |          |            |                            |           |           |             |                  |
| 742012                                                                     | NO. 1 ENGINE - NO. 2 IGNITION (IPC 25 REFERENCE) LEAD |           |          |            |                            |           |           |             | Component ATA:74 |
| PN:3060722-12                                                              | MOS/MSC                                               | 22-Jun-23 | O/C      | TSN 0      |                            |           |           |             |                  |
| SN:S22500007                                                               | HRS                                                   | 9184.4    |          | TSN 0      |                            |           |           |             |                  |
|                                                                            | ENC                                                   | 7042      |          | TSN 0      |                            |           |           |             |                  |
| PROC. REF: LMM 74-00-01, LMM 74-00-01PROC. REF: LMM 74-00-01, LMM 74-00-01 |                                                       |           |          |            |                            |           |           |             |                  |
| 742012                                                                     | NO. 2 ENGINE - NO. 2 IGNITION (IPC 25 REFERENCE) LEAD |           |          |            |                            |           |           |             | Component ATA:74 |
| PN:9043913                                                                 | MOS/MSC                                               | 20-Jul-15 | O/C      | TSN 0      |                            |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                                   | 6622.3    |          | TSN 0      |                            |           |           |             |                  |
|                                                                            | ENC                                                   | 5602      |          | TSN 0      |                            |           |           |             |                  |
| PROC. REF: LMM 74-00-01, LMM 74-00-01PROC. REF: LMM 74-00-01, LMM 74-00-01 |                                                       |           |          |            |                            |           |           |             |                  |
| 743001                                                                     | TAIL CONE RELAY (P13) PANEL                           |           |          |            |                            |           |           |             | Component ATA:74 |
| PN:PN                                                                      | MOS/MSC                                               | 09-Mar-01 | O/C      | TSN 0      |                            |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                                   | 0         |          | TSN 0      |                            |           |           |             |                  |
|                                                                            | AFL                                                   | 0         |          | TSN 0      |                            |           |           |             |                  |
| PROC. REF: AMM 74-30-01PROC. REF: AMM 74-30-01                             |                                                       |           |          |            |                            |           |           |             |                  |
| 743001-1                                                                   | EMERGENCY LIGHTING (P-51) RELAY                       |           |          |            |                            |           |           |             | Component ATA:74 |
| PN:PN                                                                      | MOS/MSC                                               | 09-Mar-01 | O/C      | TSN 0      |                            |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                                   | 0         |          | TSN 0      |                            |           |           |             |                  |
|                                                                            | AFL                                                   | 0         |          | TSN 0      |                            |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                                       |           |          |            |                            |           |           |             |                  |
| 743005-1                                                                   | K22 RELAY                                             |           |          |            |                            |           |           |             | Component ATA:74 |
| PN:PN                                                                      | MOS/MSC                                               | 09-Mar-01 | O/C      | TSN 0      |                            |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                                   | 0         |          | TSN 0      |                            |           |           |             |                  |
|                                                                            | AFL                                                   | 0         |          | TSN 0      |                            |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                                       |           |          |            |                            |           |           |             |                  |
| 743005-2                                                                   | K61 RELAY                                             |           |          |            |                            |           |           |             | Component ATA:74 |
| PN:PN                                                                      | MOS/MSC                                               | 09-Mar-01 | O/C      | TSN 0      |                            |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                                   | 0         |          | TSN 0      |                            |           |           |             |                  |
|                                                                            | AFL                                                   | 0         |          | TSN 0      |                            |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                                       |           |          |            |                            |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                                                                                                            | Unit                                                 | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 75 - AIR                                                                                                                       |                                                      |           |          |          |                        |           |           |             |                  |
| 754210                                                                                                                             | NO. 1 ENGINE - INLET PRESSURE AND TEMPERATURE SENSOR |           |          |          |                        |           |           |             | Component ATA:75 |
| PN:PN                                                                                                                              | MOS/MSC                                              | 05-Jan-00 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                                                                         | HRS                                                  | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                                                                                    | ENC                                                  | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: LMM 75-40-01, LMM 75-40-01, LMM 75-40-01, LMM 75-40-01PROC. REF: LMM 75-40-01, LMM 75-40-01, LMM 75-40-01, LMM 75-40-01 |                                                      |           |          |          |                        |           |           |             |                  |
| 754210                                                                                                                             | NO. 2 ENGINE - INLET PRESSURE AND TEMPERATURE SENSOR |           |          |          |                        |           |           |             | Component ATA:75 |
| PN:PN                                                                                                                              | MOS/MSC                                              | 15-Jan-00 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                                                                         | HRS                                                  | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                                                                                    | ENC                                                  | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: LMM 75-40-01, LMM 75-40-01, LMM 75-40-01, LMM 75-40-01PROC. REF: LMM 75-40-01, LMM 75-40-01, LMM 75-40-01, LMM 75-40-01 |                                                      |           |          |          |                        |           |           |             |                  |
| ATA 76 - ENGINE CONTROLS                                                                                                           |                                                      |           |          |          |                        |           |           |             |                  |
| 761013                                                                                                                             | THROTTLE CONTROL MODULE                              |           |          |          |                        |           |           |             | Component ATA:76 |
| PN:69011-17                                                                                                                        | MOS/MSC                                              | 16-Jul-20 | O/C      |          |                        |           |           |             |                  |
| SN:640                                                                                                                             | HRS                                                  | 8284.1    |          |          |                        |           |           |             |                  |
|                                                                                                                                    | AFL                                                  | 6376      |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 76-10-02PROC. REF: AMM 76-10-02                                                                                     |                                                      |           |          |          |                        |           |           |             |                  |
| 761201                                                                                                                             | AFT LEFT THROTTLE CABLE                              |           |          |          |                        |           |           |             | Component ATA:76 |
| PN:71825-6                                                                                                                         | MOS/MSC                                              | 12-Oct-12 | O/C      |          |                        |           |           |             |                  |
| SN:UNKNOWN                                                                                                                         | HRS                                                  | 6996.3    |          |          |                        |           |           |             |                  |
|                                                                                                                                    | AFL                                                  | 5340      |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 76-10-01PROC. REF: AMM 76-10-01                                                                                     |                                                      |           |          |          |                        |           |           |             |                  |
| 761202                                                                                                                             | AFT RIGHT THROTTLE CABLE                             |           |          |          |                        |           |           |             | Component ATA:76 |
| PN:PN                                                                                                                              | MOS/MSC                                              | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                                                                         | HRS                                                  | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                                                                                    | AFL                                                  | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 76-10-01PROC. REF: AMM 76-10-01                                                                                     |                                                      |           |          |          |                        |           |           |             |                  |
| 761203                                                                                                                             | LEFT FORWARD THROTTLE CABLE                          |           |          |          |                        |           |           |             | Component ATA:76 |
| PN:71845-10                                                                                                                        | MOS/MSC                                              | 12-Oct-12 | O/C      |          |                        |           |           |             |                  |
| SN:UNKNOWN                                                                                                                         | HRS                                                  | 6996.3    |          |          |                        |           |           |             |                  |
|                                                                                                                                    | AFL                                                  | 5340      |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 76-10-01PROC. REF: AMM 76-10-01                                                                                     |                                                      |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                                                                                                            | Unit                                     | C / W     | Interval | TSX / Adj. | Next Due (ENG / APU) A / C | Max Limit | Remaining | Disposition | Warranty         |
|------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------|-----------|----------|------------|----------------------------|-----------|-----------|-------------|------------------|
| ATA 76 - ENGINE CONTROLS                                                                                                           |                                          |           |          |            |                            |           |           |             |                  |
| 761204                                                                                                                             | RIGHT FORWARD THROTTLE CABLE             |           |          |            |                            |           |           |             | Component ATA:76 |
| PN:PN                                                                                                                              | MOS/MSC                                  | 09-Mar-01 | O/C      | TSN 0      |                            |           |           |             |                  |
| SN:UNKNOWN                                                                                                                         | HRS                                      | 0         |          | TSN 0      |                            |           |           |             |                  |
|                                                                                                                                    | AFL                                      | 0         |          | TSN 0      |                            |           |           |             |                  |
| PROC. REF: AMM 76-10-01PROC. REF: AMM 76-10-01                                                                                     |                                          |           |          |            |                            |           |           |             |                  |
| 761310                                                                                                                             | NO. 1 ENGINE - SURGE BLEED VALVE         |           |          |            |                            |           |           |             | Component ATA:76 |
| PN:PN                                                                                                                              | MOS/MSC                                  | 05-Jan-00 | O/C      | TSN 0      |                            |           |           |             |                  |
| SN:UNKNOWN                                                                                                                         | HRS                                      | 0         |          | TSN 0      |                            |           |           |             |                  |
|                                                                                                                                    | ENC                                      | 0         |          | TSN 0      |                            |           |           |             |                  |
| PROC. REF: LMM 76-10-01, LMM 76-10-01, LMM 76-10-01, LMM 76-10-01PROC. REF: LMM 76-10-01, LMM 76-10-01, LMM 76-10-01, LMM 76-10-01 |                                          |           |          |            |                            |           |           |             |                  |
| 761310                                                                                                                             | NO. 2 ENGINE - SURGE BLEED VALVE         |           |          |            |                            |           |           |             | Component ATA:76 |
| PN:978812-6-1                                                                                                                      | MOS/MSC                                  | 20-Jul-15 | O/C      | TSO 0      |                            |           |           |             |                  |
| SN:10962                                                                                                                           | HRS                                      | 6622.3    |          | TSO 0      |                            |           |           |             |                  |
|                                                                                                                                    | ENC                                      | 5602      |          | TSO 0      |                            |           |           |             |                  |
| PROC. REF: LMM 76-10-01, LMM 76-10-01, LMM 76-10-01, LMM 76-10-01PROC. REF: LMM 76-10-01, LMM 76-10-01, LMM 76-10-01, LMM 76-10-01 |                                          |           |          |            |                            |           |           |             |                  |
| 761320                                                                                                                             | NO. 1 ENGINE - SOLENOID CONTROLLER VALVE |           |          |            |                            |           |           |             | Component ATA:76 |
| PN:PN                                                                                                                              | MOS/MSC                                  | 05-Jan-00 | O/C      | TSN 0      |                            |           |           |             |                  |
| SN:UNKNOWN                                                                                                                         | HRS                                      | 0         |          | TSN 0      |                            |           |           |             |                  |
|                                                                                                                                    | ENC                                      | 0         |          | TSN 0      |                            |           |           |             |                  |
| PROC. REF: LMM 76-10-01, LMM 76-10-01, LMM 76-10-01, LMM 76-10-01PROC. REF: LMM 76-10-01, LMM 76-10-01, LMM 76-10-01, LMM 76-10-01 |                                          |           |          |            |                            |           |           |             |                  |
| 761320                                                                                                                             | NO. 2 ENGINE - SOLENOID CONTROLLER VALVE |           |          |            |                            |           |           |             | Component ATA:76 |
| PN:PN                                                                                                                              | MOS/MSC                                  | 15-Jan-00 | O/C      | TSN 0      |                            |           |           |             |                  |
| SN:UNKNOWN                                                                                                                         | HRS                                      | 0         |          | TSN 0      |                            |           |           |             |                  |
|                                                                                                                                    | ENC                                      | 0         |          | TSN 0      |                            |           |           |             |                  |
| PROC. REF: LMM 76-10-01, LMM 76-10-01, LMM 76-10-01, LMM 76-10-01PROC. REF: LMM 76-10-01, LMM 76-10-01, LMM 76-10-01, LMM 76-10-01 |                                          |           |          |            |                            |           |           |             |                  |
| 761330                                                                                                                             | NO. 1 ENGINE - ENGINE (DEEC) COMPUTER    |           |          |            |                            |           |           |             | Component ATA:76 |
| PN:2118882-1008                                                                                                                    | MOS/MSC                                  | 25-Oct-06 | O/C      |            |                            |           |           |             |                  |
| SN:15-AW0059                                                                                                                       | HRS                                      | 4857.2    |          |            |                            |           |           |             |                  |
|                                                                                                                                    | ENC                                      | 3730      |          |            |                            |           |           |             |                  |
| PROC. REF: LMM 76-10-02, LMM 76-10-02, LMM 76-10-02, LMM 76-10-02PROC. REF: LMM 76-10-02, LMM 76-10-02, LMM 76-10-02, LMM 76-10-02 |                                          |           |          |            |                            |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN | Unit | C / W | Interval | TSX / Adj. | Next Due (ENG / APU) A / C | Max Limit | Remaining | Disposition | Warranty |
|---------|------|-------|----------|------------|----------------------------|-----------|-----------|-------------|----------|
|---------|------|-------|----------|------------|----------------------------|-----------|-----------|-------------|----------|

ATA 76 - ENGINE CONTROLS

|                                                                                                                                    |                                       |           |     |  |  |  |  |           |        |
|------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------|-----------|-----|--|--|--|--|-----------|--------|
| 761330                                                                                                                             | NO. 2 ENGINE - ENGINE (DEEC) COMPUTER |           |     |  |  |  |  | Component | ATA:76 |
| PN:2118882-1008                                                                                                                    | MOS/MSC                               | 27-Jun-06 | O/C |  |  |  |  |           |        |
| SN:124-AW0057                                                                                                                      | HRS                                   | 4614      |     |  |  |  |  |           |        |
|                                                                                                                                    | ENC                                   | 3532      |     |  |  |  |  |           |        |
| PROC. REF: LMM 76-10-02, LMM 76-10-02, LMM 76-10-02, LMM 76-10-02PROC. REF: LMM 76-10-02, LMM 76-10-02, LMM 76-10-02, LMM 76-10-02 |                                       |           |     |  |  |  |  |           |        |

|                                                                |                                                     |           |    |  |                |  |    |               |        |
|----------------------------------------------------------------|-----------------------------------------------------|-----------|----|--|----------------|--|----|---------------|--------|
| 761330A                                                        | NO. 1 ENGINE - DOWNLOAD ENGINE (DEEC) COMPUTER ECTM |           |    |  |                |  |    | Service       | ATA:76 |
| PN:2118882-1008                                                | MOS                                                 | 21-Feb-25 |    |  |                |  |    | CUSTOMER CODE |        |
| SN:15-AW0059                                                   | HRS                                                 | 9563.2    |    |  |                |  |    |               |        |
|                                                                | ENC                                                 | 7294      | 40 |  | (7334)<br>7392 |  | 20 |               |        |
| PROC. REF: MSC CAMP EHM ADENDUMPROC. REF: MSC CAMP EHM ADENDUM |                                                     |           |    |  |                |  |    |               |        |

|                                                                |                                                     |           |    |  |                |  |    |               |        |
|----------------------------------------------------------------|-----------------------------------------------------|-----------|----|--|----------------|--|----|---------------|--------|
| 761330A                                                        | NO. 2 ENGINE - DOWNLOAD ENGINE (DEEC) COMPUTER ECTM |           |    |  |                |  |    | Service       | ATA:76 |
| PN:2118882-1008                                                | MOS                                                 | 21-Feb-25 |    |  |                |  |    | CUSTOMER CODE |        |
| SN:124-AW0057                                                  | HRS                                                 | 8724.5    |    |  |                |  |    |               |        |
|                                                                | ENC                                                 | 7190      | 40 |  | (7230)<br>7392 |  | 20 |               |        |
| PROC. REF: MSC CAMP EHM ADENDUMPROC. REF: MSC CAMP EHM ADENDUM |                                                     |           |    |  |                |  |    |               |        |

ATA 77 - ENGINE INDICATING

|                  |         |                                                                                                                                                                                        |     |  |  |  |  |         |        |
|------------------|---------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|--|--|--|--|---------|--------|
| 5-19-00-F7720002 | U       | PERFORM ENGINE TEMPERATURE INDICATING SYSTEM - PERFORM ITT MARGIN CHECK. (EFFECTIVE ON AIRCRAFT 45-080 THRU 45-169 NOT MODIFIED BY SB 45-22-4.) (ZONE/ACCESS 410/420 **IRN # F7720002) |     |  |  |  |  | Service | ATA:77 |
|                  | MOS/MSC | 09-Mar-01                                                                                                                                                                              | N/A |  |  |  |  |         |        |
|                  | HRS     | 0                                                                                                                                                                                      |     |  |  |  |  |         |        |
|                  | AFL     | 0                                                                                                                                                                                      |     |  |  |  |  |         |        |

|                  |         |                                                                                                                                                                                               |     |  |  |  |  |         |        |
|------------------|---------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|--|--|--|--|---------|--------|
| 5-19-00-F7720003 | U       | PERFORM ENGINE TEMPERATURE INDICATING SYSTEM - PERFORM HARDWARE VALIDATION CHECK. (EFFECTIVE ON AIRCRAFT 45-080 THRU 45-169 NOT MODIFIED BY SB 45-22-4.) (ZONE/ACCESS 410/420 IRN # F7720003) |     |  |  |  |  | Service | ATA:77 |
|                  | MOS/MSC | 09-Mar-01                                                                                                                                                                                     | N/A |  |  |  |  |         |        |
|                  | HRS     | 0                                                                                                                                                                                             |     |  |  |  |  |         |        |
|                  | AFL     | 0                                                                                                                                                                                             |     |  |  |  |  |         |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                                                                                                            | Unit                          | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|------------------------------------------------------------------------------------------------------------------------------------|-------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 77 - ENGINE INDICATING                                                                                                         |                               |           |          |          |                        |           |           |             |                  |
| 770101                                                                                                                             | NO. 1 ENGINE - N1 MONOPOLE    |           |          |          |                        |           |           |             | Component ATA:77 |
| PN:PN                                                                                                                              | MOS/MSC                       | 05-Jan-00 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                                                                         | HRS                           | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                                                                                    | ENC                           | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: LMM 77-10-02PROC. REF: LMM 77-10-02                                                                                     |                               |           |          |          |                        |           |           |             |                  |
| 770101                                                                                                                             | NO. 2 ENGINE - N1 MONOPOLE    |           |          |          |                        |           |           |             | Component ATA:77 |
| PN:PN                                                                                                                              | MOS/MSC                       | 15-Jan-00 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                                                                         | HRS                           | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                                                                                    | ENC                           | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: LMM 77-10-02PROC. REF: LMM 77-10-02                                                                                     |                               |           |          |          |                        |           |           |             |                  |
| 771210                                                                                                                             | NO. 1 ENGINE - N1 COMPENSATOR |           |          |          |                        |           |           |             | Component ATA:77 |
| PN:PN                                                                                                                              | MOS/MSC                       | 05-Jan-00 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                                                                         | HRS                           | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                                                                                    | ENC                           | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: LMM 77-10-03, LMM 77-10-03, LMM 77-10-03, LMM 77-10-03PROC. REF: LMM 77-10-03, LMM 77-10-03, LMM 77-10-03, LMM 77-10-03 |                               |           |          |          |                        |           |           |             |                  |
| 771210                                                                                                                             | NO. 2 ENGINE - N1 COMPENSATOR |           |          |          |                        |           |           |             | Component ATA:77 |
| PN:3060735-7                                                                                                                       | MOS/MSC                       | 05-Jun-06 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:011309700526                                                                                                                    | HRS                           | 3701.2    |          | TSN 0    |                        |           |           |             |                  |
|                                                                                                                                    | ENC                           | 3369      |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: LMM 77-10-03, LMM 77-10-03, LMM 77-10-03, LMM 77-10-03PROC. REF: LMM 77-10-03, LMM 77-10-03, LMM 77-10-03, LMM 77-10-03 |                               |           |          |          |                        |           |           |             |                  |
| 771220                                                                                                                             | NO. 1 ENGINE - N2 MONOPOLE    |           |          |          |                        |           |           |             | Component ATA:77 |
| PN:PN                                                                                                                              | MOS/MSC                       | 05-Jan-00 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                                                                         | HRS                           | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                                                                                    | ENC                           | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: LMM 77-10-05, LMM 77-10-05, LMM 77-10-05, LMM 77-10-05PROC. REF: LMM 77-10-05, LMM 77-10-05, LMM 77-10-05, LMM 77-10-05 |                               |           |          |          |                        |           |           |             |                  |
| 771220                                                                                                                             | NO. 2 ENGINE - N2 MONOPOLE    |           |          |          |                        |           |           |             | Component ATA:77 |
| PN:PN                                                                                                                              | MOS/MSC                       | 15-Jan-00 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                                                                         | HRS                           | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                                                                                    | ENC                           | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: LMM 77-10-05, LMM 77-10-05, LMM 77-10-05, LMM 77-10-05PROC. REF: LMM 77-10-05, LMM 77-10-05, LMM 77-10-05, LMM 77-10-05 |                               |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                                                                                                            | Unit                                 | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 77 - ENGINE INDICATING                                                                                                         |                                      |           |          |          |                        |           |           |             |                  |
| 772210                                                                                                                             | NO. 1 ENGINE - ITT HARNESS ASSEMBLY  |           |          |          |                        |           |           |             | Component ATA:77 |
| PN:3060730-1                                                                                                                       | MOS/MSC                              | 28-Nov-17 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:1716901702429                                                                                                                   | HRS                                  | 7696.2    |          | TSN 0    |                        |           |           |             |                  |
|                                                                                                                                    | ENC                                  | 5895      |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: LMM 77-20-01, LMM 77-20-01, LMM 77-20-01, LMM 77-20-01PROC. REF: LMM 77-20-01, LMM 77-20-01, LMM 77-20-01, LMM 77-20-01 |                                      |           |          |          |                        |           |           |             |                  |
| 772210                                                                                                                             | NO. 2 ENGINE - ITT HARNESS ASSEMBLY  |           |          |          |                        |           |           |             | Component ATA:77 |
| PN:3060763-1                                                                                                                       | MOS/MSC                              | 20-Jul-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:1516901702268                                                                                                                   | HRS                                  | 6622.3    |          | TSN 0    |                        |           |           |             |                  |
|                                                                                                                                    | ENC                                  | 5602      |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: LMM 77-20-01, LMM 77-20-01, LMM 77-20-01, LMM 77-20-01PROC. REF: LMM 77-20-01, LMM 77-20-01, LMM 77-20-01, LMM 77-20-01 |                                      |           |          |          |                        |           |           |             |                  |
| 774001                                                                                                                             | ENGINE VIBRATION MONITOR BOX         |           |          |          |                        |           |           |             | Component ATA:77 |
| PN:PN                                                                                                                              | MOS/MSC                              | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                                                                         | HRS                                  | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                                                                                    | AFL                                  | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 77-41-01PROC. REF: AMM 77-41-01                                                                                     |                                      |           |          |          |                        |           |           |             |                  |
| 774010                                                                                                                             | P36 RELAY BOX                        |           |          |          |                        |           |           |             | Component ATA:77 |
| PN:PN                                                                                                                              | MOS/MSC                              | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                                                                         | HRS                                  | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                                                                                    | AFL                                  | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 77-41-03PROC. REF: AMM 77-41-03                                                                                     |                                      |           |          |          |                        |           |           |             |                  |
| 774011                                                                                                                             | LEFT ENGINE VIBRATION ACCELEROMETER  |           |          |          |                        |           |           |             | Component ATA:77 |
| PN:PN                                                                                                                              | MOS/MSC                              | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                                                                         | HRS                                  | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                                                                                    | AFL                                  | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 77-41-02PROC. REF: AMM 77-41-02                                                                                     |                                      |           |          |          |                        |           |           |             |                  |
| 774012                                                                                                                             | RIGHT ENGINE VIBRATION ACCELEROMETER |           |          |          |                        |           |           |             | Component ATA:77 |
| PN:PN                                                                                                                              | MOS/MSC                              | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                                                                         | HRS                                  | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                                                                                    | AFL                                  | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 77-41-02PROC. REF: AMM 77-41-02                                                                                     |                                      |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN | Unit | C / W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|---------|------|-------|----------|----------|------------------------|-----------|-----------|-------------|----------|
|---------|------|-------|----------|----------|------------------------|-----------|-----------|-------------|----------|

ATA 77 - ENGINE INDICATING

|                                                |     |                                                               |      |  |  |  |  |         |        |
|------------------------------------------------|-----|---------------------------------------------------------------|------|--|--|--|--|---------|--------|
| Y7741000                                       | S   | PERFORM ENGINE VIBRATION MONITORING SYSTEM - FUNCTIONAL TEST. |      |  |  |  |  | Service | ATA:77 |
|                                                | MOS | 25-Nov-19                                                     | 96   |  |  |  |  |         |        |
|                                                | HRS | 8177.7                                                        | 2400 |  |  |  |  |         |        |
|                                                | AFL | 6303                                                          |      |  |  |  |  |         |        |
| PROC. REF: AMM 77-41-00PROC. REF: AMM 77-41-00 |     |                                                               |      |  |  |  |  |         | PKG:21 |

ATA 78 - EXHAUST

|                                                              |                                                                                                                         |           |     |         |        |
|--------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------|-----------|-----|---------|--------|
| 5-19-00-R7830007                                             | PERFORM - THRUST REVERSER - PERFORM CONDUCTIVITY CHECK OF RH THRUST REVERSER DOOR SKIN AND COWL ADJACENT TO APU EXHAUST |           |     | Service | ATA:78 |
|                                                              | MOS/MSC                                                                                                                 | 09-Mar-01 | N/A |         |        |
|                                                              | HRS                                                                                                                     | 0         |     |         |        |
|                                                              | AFL                                                                                                                     | 0         |     |         |        |
| PROC. REF: NDT PART 6/78-30-01PROC. REF: NDT PART 6/78-30-01 |                                                                                                                         |           |     |         |        |

|                                                |                            |           |     |  |           |        |
|------------------------------------------------|----------------------------|-----------|-----|--|-----------|--------|
| 783001                                         | LEFT LOWER THRUST REVERSER |           |     |  | Component | ATA:78 |
| PN:LJ7830101-5                                 | MOS/MSC                    | 26-Jul-23 | O/C |  |           |        |
| SN:00046                                       | HRS                        | 9278      |     |  |           |        |
|                                                | AFL                        | 7111      |     |  |           |        |
| Special Properties: RII ITEM                   |                            |           |     |  |           |        |
| PROC. REF: AMM 78-31-00PROC. REF: AMM 78-31-00 |                            |           |     |  |           |        |

| 783002                                         |  |         |           | RIGHT LOWER THRUST REVERSER |  |  |  | Component | ATA:78 |
|------------------------------------------------|--|---------|-----------|-----------------------------|--|--|--|-----------|--------|
| PN:LJ7830101-6                                 |  | MOS/MSC | 26-Jul-23 | O/C                         |  |  |  |           |        |
| SN:00052                                       |  | HRS     | 9278      |                             |  |  |  |           |        |
|                                                |  | AFL     | 7111      |                             |  |  |  |           |        |
| Special Properties: RII ITEM                   |  |         |           |                             |  |  |  |           |        |
| PROC. REF: AMM 78-31-00PROC. REF: AMM 78-31-00 |  |         |           |                             |  |  |  |           |        |

|                                                    |                                               |           |     |       |  |           |        |
|----------------------------------------------------|-----------------------------------------------|-----------|-----|-------|--|-----------|--------|
| 783025                                             | TRANSFORMER/RECTIFIER ELECTRONIC CONTROL UNIT |           |     |       |  | Component | ATA:78 |
| PN:PN                                              | MOS/MSC                                       | 09-Mar-01 | O/C | TSN 0 |  |           |        |
| SN:UNKNOWN                                         | HRS                                           | 0         |     | TSN 0 |  |           |        |
|                                                    | AFL                                           | 0         |     | TSN 0 |  |           |        |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                               |           |     |       |  |           |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR    Serial: 45-145    RegNo: N942FK    HRS: 9669.1    AFL: 7372    As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                        | Unit                                    | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty            |
|------------------------------------------------|-----------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|---------------------|
| ATA 78 - EXHAUST                               |                                         |           |          |          |                        |           |           |             |                     |
| 783037                                         | NO. 1 GPM HYDRAULIC CONTROL VALVE       |           |          |          |                        |           |           |             | Component    ATA:78 |
| PN:PN                                          | MOS/MSC                                 | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                     | HRS                                     | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                | AFL                                     | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: AMM 78-32-10PROC. REF: AMM 78-32-10 |                                         |           |          |          |                        |           |           |             |                     |
| 783038                                         | NO. 2 GPM HYDRAULIC CONTROL VALVE       |           |          |          |                        |           |           |             | Component    ATA:78 |
| PN:PN                                          | MOS/MSC                                 | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                     | HRS                                     | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                | AFL                                     | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: AMM 78-32-10PROC. REF: AMM 78-32-10 |                                         |           |          |          |                        |           |           |             |                     |
| 783051                                         | LEFT OUTBOARD THRUST REVERSER ACTUATOR  |           |          |          |                        |           |           |             | Component    ATA:78 |
| PN:LJ7833100-3                                 | MOS/MSC                                 | 26-Jan-14 | O/C      | TSO 0    |                        |           |           |             |                     |
| SN:A30040652                                   | HRS                                     | 7249.8    |          | TSO 0    |                        |           |           |             |                     |
|                                                | AFL                                     | 5528      |          | TSO 0    |                        |           |           |             |                     |
| PROC. REF: AMM 78-32-20PROC. REF: AMM 78-32-20 |                                         |           |          |          |                        |           |           |             |                     |
| 783052                                         | LEFT INBOARD THRUST REVERSER ACTUATOR   |           |          |          |                        |           |           |             | Component    ATA:78 |
| PN:PN                                          | MOS/MSC                                 | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                     | HRS                                     | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                | AFL                                     | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: AMM 78-32-20PROC. REF: AMM 78-32-20 |                                         |           |          |          |                        |           |           |             |                     |
| 783053                                         | RIGHT INBOARD THRUST REVERSER ACTUATOR  |           |          |          |                        |           |           |             | Component    ATA:78 |
| PN:PN                                          | MOS/MSC                                 | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                     |
| SN:UNKNOWN                                     | HRS                                     | 0         |          | TSN 0    |                        |           |           |             |                     |
|                                                | AFL                                     | 0         |          | TSN 0    |                        |           |           |             |                     |
| PROC. REF: AMM 78-32-20PROC. REF: AMM 78-32-20 |                                         |           |          |          |                        |           |           |             |                     |
| 783054                                         | RIGHT OUTBOARD THRUST REVERSER ACTUATOR |           |          |          |                        |           |           |             | Component    ATA:78 |
| PN:LJ7833100-4                                 | MOS/MSC                                 | 12-Dec-11 | O/C      | TSO 0    |                        |           |           |             |                     |
| SN:A30040459                                   | HRS                                     | 6763.5    |          | TSO 0    |                        |           |           |             |                     |
|                                                | AFL                                     | 5158      |          | TSO 0    |                        |           |           |             |                     |
| PROC. REF: AMM 78-32-20PROC. REF: AMM 78-32-20 |                                         |           |          |          |                        |           |           |             |                     |

?-Insufficient Information    S-Suppressed Requirement    \*-Estimated Due(New Requirement)    (EFF)-Effective C/W    (M)-Manual Due    U-User Task    Ex-Excluded Task

# Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9669.1
 AFL: 7372
 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                        | Unit                                            | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|------------------------------------------------|-------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 78 - EXHAUST                               |                                                 |           |          |          |                        |           |           |             |                  |
| 783061                                         | NO. 1 CONTROL, THRUST REVERSER HYDRAULIC VALVE  |           |          |          |                        |           |           |             | Component ATA:78 |
| PN:PN                                          | MOS/MSC                                         | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                             | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                             | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 78-32-10PROC. REF: AMM 78-32-10 |                                                 |           |          |          |                        |           |           |             |                  |
| 783062                                         | NO. 2 CONTROL, THRUST REVERSER HYDRAULIC VALVE  |           |          |          |                        |           |           |             | Component ATA:78 |
| PN:PN                                          | MOS/MSC                                         | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                             | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                             | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 78-32-10PROC. REF: AMM 78-32-10 |                                                 |           |          |          |                        |           |           |             |                  |
| 783101                                         | LEFT THRUST REVERSER HYDRAULIC ISOLATION VALVE  |           |          |          |                        |           |           |             | Component ATA:78 |
| PN:PN                                          | MOS/MSC                                         | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                             | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                             | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 78-30-02PROC. REF: AMM 78-30-02 |                                                 |           |          |          |                        |           |           |             |                  |
| 783102                                         | RIGHT THRUST REVERSER HYDRAULIC ISOLATION VALVE |           |          |          |                        |           |           |             | Component ATA:78 |
| PN:PN                                          | MOS/MSC                                         | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                             | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                             | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 78-30-02PROC. REF: AMM 78-30-02 |                                                 |           |          |          |                        |           |           |             |                  |
| 783150                                         | LEFT HAND INBOARD LATCHBOX ACTUATOR             |           |          |          |                        |           |           |             | Component ATA:78 |
| PN:PN                                          | MOS/MSC                                         | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                             | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                             | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 78-32-30PROC. REF: AMM 78-32-30 |                                                 |           |          |          |                        |           |           |             |                  |
| 783151                                         | RIGHT HAND INBOARD LATCHBOX ACTUATOR            |           |          |          |                        |           |           |             | Component ATA:78 |
| PN:PN                                          | MOS/MSC                                         | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                             | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                | AFL                                             | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 78-32-30PROC. REF: AMM 78-32-30 |                                                 |           |          |          |                        |           |           |             |                  |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C/W   (M)-Manual Due   U-User Task   Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                            | Unit                                  | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------|---------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 78 - EXHAUST                                   |                                       |           |          |          |                        |           |           |             |                  |
| 783210                                             | LEFT THRUST REVERSER CONTROL VALVE    |           |          |          |                        |           |           |             | Component ATA:78 |
| PN:PN                                              | MOS/MSC                               | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                   | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                   | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                       |           |          |          |                        |           |           |             |                  |
| 783211                                             | RIGHT THRUST REVERSER CONTROL VALVE   |           |          |          |                        |           |           |             | Component ATA:78 |
| PN:PN                                              | MOS/MSC                               | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                   | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                   | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                       |           |          |          |                        |           |           |             |                  |
| 783220                                             | NO. 1 ENGINE THROTTLE RETARD ACTUATOR |           |          |          |                        |           |           |             | Component ATA:78 |
| PN:PN                                              | MOS/MSC                               | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                   | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                   | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 78-32-40PROC. REF: AMM 78-32-40     |                                       |           |          |          |                        |           |           |             |                  |
| 783221                                             | NO. 2 ENGINE THROTTLE RETARD ACTUATOR |           |          |          |                        |           |           |             | Component ATA:78 |
| PN:PN                                              | MOS/MSC                               | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                   | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                   | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 78-32-40PROC. REF: AMM 78-32-40     |                                       |           |          |          |                        |           |           |             |                  |
| 783301                                             | LEFT THRUST REVERSER CONTROL BOX      |           |          |          |                        |           |           |             | Component ATA:78 |
| PN:LJ7836706-3                                     | MOS/MSC                               | 23-Aug-22 | O/C      |          |                        |           |           |             |                  |
| SN:00046                                           | HRS                                   | 9089.4    |          |          |                        |           |           |             |                  |
|                                                    | AFL                                   | 6994      |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 78-33-10PROC. REF: AMM 78-33-10     |                                       |           |          |          |                        |           |           |             |                  |
| 783302                                             | RIGHT THRUST REVERSER CONTROL BOX     |           |          |          |                        |           |           |             | Component ATA:78 |
| PN:LJ7836706-3                                     | MOS/MSC                               | 18-Jun-07 | O/C      |          |                        |           |           |             |                  |
| SN:00059                                           | HRS                                   | 5562.1    |          |          |                        |           |           |             |                  |
|                                                    | AFL                                   | 4242      |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 78-33-10PROC. REF: AMM 78-33-10     |                                       |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR    Serial: 45-145    RegNo: N942FK    HRS: 9669.1    AFL: 7372    As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                        | Unit                                                                           | C / W     | Interval | TSX / Adj. | Next Due (ENG / APU) A / C | Max Limit | Remaining | Disposition   | Warranty |
|------------------------------------------------|--------------------------------------------------------------------------------|-----------|----------|------------|----------------------------|-----------|-----------|---------------|----------|
| ATA 78 - EXHAUST                               |                                                                                |           |          |            |                            |           |           |               |          |
| 783320                                         | LEFT OUTBOARD THRUST REVERSER WIRE HARNESS                                     |           |          |            |                            |           |           | Component     | ATA:78   |
| PN:PN                                          | MOS/MSC                                                                        | 09-Mar-01 | C/C      | TSN 0      |                            |           |           |               |          |
| SN:UNKNOWN                                     | HRS                                                                            | 0         |          | TSN 0      |                            |           |           |               |          |
|                                                | AFL                                                                            | 0         |          | TSN 0      |                            |           |           |               |          |
| PROC. REF: AMM 78-33-20PROC. REF: AMM 78-33-20 |                                                                                |           |          |            |                            |           |           |               |          |
| 783321                                         | LEFT INBOARD THRUST REVERSER WIRE HARNESS                                      |           |          |            |                            |           |           | Component     | ATA:78   |
| PN:PN                                          | MOS/MSC                                                                        | 09-Mar-01 | C/C      | TSN 0      |                            |           |           |               |          |
| SN:UNKNOWN                                     | HRS                                                                            | 0         |          | TSN 0      |                            |           |           |               |          |
|                                                | AFL                                                                            | 0         |          | TSN 0      |                            |           |           |               |          |
| PROC. REF: AMM 78-33-20PROC. REF: AMM 78-33-20 |                                                                                |           |          |            |                            |           |           |               |          |
| 783322                                         | RIGHT INBOARD THRUST REVERSER WIRE HARNESS                                     |           |          |            |                            |           |           | Component     | ATA:78   |
| PN:PN                                          | MOS/MSC                                                                        | 09-Mar-01 | C/C      | TSN 0      |                            |           |           |               |          |
| SN:UNKNOWN                                     | HRS                                                                            | 0         |          | TSN 0      |                            |           |           |               |          |
|                                                | AFL                                                                            | 0         |          | TSN 0      |                            |           |           |               |          |
| PROC. REF: AMM 78-33-20PROC. REF: AMM 78-33-20 |                                                                                |           |          |            |                            |           |           |               |          |
| 783323                                         | RIGHT OUTBOARD THRUST REVERSER WIRE HARNESS                                    |           |          |            |                            |           |           | Component     | ATA:78   |
| PN:PN                                          | MOS/MSC                                                                        | 09-Mar-01 | C/C      | TSN 0      |                            |           |           |               |          |
| SN:UNKNOWN                                     | HRS                                                                            | 0         |          | TSN 0      |                            |           |           |               |          |
|                                                | AFL                                                                            | 0         |          | TSN 0      |                            |           |           |               |          |
| PROC. REF: AMM 78-33-20PROC. REF: AMM 78-33-20 |                                                                                |           |          |            |                            |           |           |               |          |
| D7830078 <sup>S</sup>                          | PERFORM ** THRUST REVERSER SYSTEM THROTTLE RETARD ACTUATOR - OPERATIONAL CHECK |           |          |            |                            |           |           | Service       | ATA:78   |
|                                                | MOS                                                                            | 25-Nov-19 | 96       |            |                            |           |           | AIRWORTHINESS |          |
|                                                | HRS                                                                            | 8177.7    | 2400     |            |                            |           |           |               |          |
|                                                | AFL                                                                            | 6303      |          |            |                            |           |           |               |          |
| PROC. REF: AMM 78-32-40PROC. REF: AMM 78-32-40 |                                                                                |           |          |            |                            |           |           |               |          |
| Y7830000 <sup>S</sup>                          | PERFORM EXHAUST NOZZLE - VISUAL INSPECTION                                     |           |          |            |                            |           |           | Service       | ATA:78   |
|                                                | MOS                                                                            | 25-Nov-19 | 96       |            |                            |           |           |               |          |
|                                                | HRS                                                                            | 8177.7    | 2400     |            |                            |           |           |               |          |
|                                                | AFL                                                                            | 6303      |          |            |                            |           |           |               |          |
| PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00 |                                                                                |           |          |            |                            |           |           |               |          |

?-Insufficient Information    S-Suppressed Requirement    \*-Estimated Due(New Requirement)    (EFF)-Effective C / W    (M)-Manual Due    U-User Task    Ex-Excluded Task



Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN | Unit | C / W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|---------|------|-------|----------|----------|------------------------|-----------|-----------|-------------|----------|
|---------|------|-------|----------|----------|------------------------|-----------|-----------|-------------|----------|

ATA 79 - OIL

|                                                                            |                         |           |     |       |  |  |  |           |        |
|----------------------------------------------------------------------------|-------------------------|-----------|-----|-------|--|--|--|-----------|--------|
| 790110                                                                     | NO. 1 ENGINE - OIL PUMP |           |     |       |  |  |  | Component | ATA:79 |
| PN:3060785-2                                                               | MOS/MSC                 | 25-Oct-06 | O/C | TSN 0 |  |  |  |           |        |
| SN:061405700614                                                            | HRS                     | 4857.2    |     | TSN 0 |  |  |  |           |        |
|                                                                            | ENC                     | 3730      |     | TSN 0 |  |  |  |           |        |
| PROC. REF: LMM 79-20-03, LMM 79-20-03PROC. REF: LMM 79-20-03, LMM 79-20-03 |                         |           |     |       |  |  |  |           |        |

|                                                                            |                         |           |     |       |  |  |  |           |        |
|----------------------------------------------------------------------------|-------------------------|-----------|-----|-------|--|--|--|-----------|--------|
| 790110                                                                     | NO. 2 ENGINE - OIL PUMP |           |     |       |  |  |  | Component | ATA:79 |
| PN:3060785-2                                                               | MOS/MSC                 | 05-Jun-06 | O/C | TSN 0 |  |  |  |           |        |
| SN:061405700076                                                            | HRS                     | 3701.2    |     | TSN 0 |  |  |  |           |        |
|                                                                            | ENC                     | 3369      |     | TSN 0 |  |  |  |           |        |
| PROC. REF: LMM 79-20-03, LMM 79-20-03PROC. REF: LMM 79-20-03, LMM 79-20-03 |                         |           |     |       |  |  |  |           |        |

|                                                |                                               |           |     |  |  |  |  |         |        |
|------------------------------------------------|-----------------------------------------------|-----------|-----|--|--|--|--|---------|--------|
| 790130 <sup>S</sup>                            | NO. 1 ENGINE - ANALYSIS OIL AND FILTER (SOAP) |           |     |  |  |  |  | Service | ATA:79 |
|                                                | MOS                                           | 02-Aug-24 |     |  |  |  |  |         |        |
|                                                | HRS                                           | 9451.6    | 150 |  |  |  |  |         |        |
|                                                | ENC                                           | 7218      |     |  |  |  |  |         |        |
| PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00 |                                               |           |     |  |  |  |  | PKG:0   |        |

|                                                |                                               |           |     |  |  |  |  |         |        |
|------------------------------------------------|-----------------------------------------------|-----------|-----|--|--|--|--|---------|--------|
| 790130 <sup>S</sup>                            | NO. 2 ENGINE - ANALYSIS OIL AND FILTER (SOAP) |           |     |  |  |  |  | Service | ATA:79 |
|                                                | MOS                                           | 02-Aug-24 |     |  |  |  |  |         |        |
|                                                | HRS                                           | 8612.9    | 150 |  |  |  |  |         |        |
|                                                | ENC                                           | 7114      |     |  |  |  |  |         |        |
| PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00 |                                               |           |     |  |  |  |  | PKG:0   |        |

|                                                |                                   |           |      |  |  |  |  |         |        |
|------------------------------------------------|-----------------------------------|-----------|------|--|--|--|--|---------|--------|
| 790140 <sup>S</sup>                            | NO. 1 ENGINE - PERFORM OIL CHANGE |           |      |  |  |  |  | Service | ATA:79 |
|                                                | MOS                               | 27-Aug-21 |      |  |  |  |  |         |        |
|                                                | HRS                               | 8634.1    | 1200 |  |  |  |  |         |        |
|                                                | ENC                               | 6633      |      |  |  |  |  |         |        |
| PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00 |                                   |           |      |  |  |  |  | PKG:0   |        |

|                     |                                   |           |      |  |  |  |  |         |        |
|---------------------|-----------------------------------|-----------|------|--|--|--|--|---------|--------|
| 790140 <sup>S</sup> | NO. 2 ENGINE - PERFORM OIL CHANGE |           |      |  |  |  |  | Service | ATA:79 |
|                     | MOS                               | 27-Aug-21 |      |  |  |  |  |         |        |
|                     | HRS                               | 7795.4    | 1200 |  |  |  |  |         |        |
|                     | ENC                               | 6529      |      |  |  |  |  |         |        |
|                     |                                   |           |      |  |  |  |  | PKG:0   |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR    Serial: 45-145    RegNo: N942FK    HRS: 9669.1    AFL: 7372    As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                                                    | Unit   | C / W                                                                               | Interval | TSX / Adj. | Next Due (ENG / APU) A / C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------------------------------|--------|-------------------------------------------------------------------------------------|----------|------------|----------------------------|-----------|-----------|-------------|----------|
| ATA 79 - OIL                                                               |        |                                                                                     |          |            |                            |           |           |             |          |
| PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00                             |        |                                                                                     |          |            |                            |           |           |             |          |
|                                                                            |        |                                                                                     |          |            |                            |           |           |             |          |
| 790150 <sup>S</sup>                                                        |        | NO. 1 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION AND PERFORM RESISTANCE CHECK |          |            |                            |           |           | Service     | ATA:79   |
|                                                                            | MOS    | 22-Jun-23                                                                           |          |            |                            |           |           |             |          |
|                                                                            | HRS    | 9184.4                                                                              | 600      |            |                            |           |           |             |          |
|                                                                            | ENC    | 7042                                                                                |          |            |                            |           |           |             |          |
|                                                                            |        |                                                                                     |          |            |                            |           |           |             | PKG:0    |
| PROC. REF: LMM 79-10-01PROC. REF: LMM 79-10-01                             |        |                                                                                     |          |            |                            |           |           |             |          |
|                                                                            |        |                                                                                     |          |            |                            |           |           |             |          |
| 790150 <sup>S</sup>                                                        |        | NO. 2 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION AND PERFORM RESISTANCE CHECK |          |            |                            |           |           | Service     | ATA:79   |
|                                                                            | MOS    | 22-Jun-23                                                                           |          |            |                            |           |           |             |          |
|                                                                            | HRS    | 8345.7                                                                              | 600      |            |                            |           |           |             |          |
|                                                                            | ENC    | 6938                                                                                |          |            |                            |           |           |             |          |
|                                                                            |        |                                                                                     |          |            |                            |           |           |             | PKG:0    |
| PROC. REF: LMM 79-10-01PROC. REF: LMM 79-10-01                             |        |                                                                                     |          |            |                            |           |           |             |          |
|                                                                            |        |                                                                                     |          |            |                            |           |           |             |          |
| 790160 <sup>S</sup>                                                        |        | NO. 1 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION                              |          |            |                            |           |           | Service     | ATA:79   |
|                                                                            | MOS    | 02-Aug-24                                                                           |          |            |                            |           |           |             |          |
|                                                                            | HRS    | 9451.6                                                                              | 150      |            |                            |           |           |             |          |
|                                                                            | ENC    | 7218                                                                                |          |            |                            |           |           |             |          |
|                                                                            |        |                                                                                     |          |            |                            |           |           |             | PKG:0    |
| PROC. REF: LMM 79-10-01PROC. REF: LMM 79-10-01                             |        |                                                                                     |          |            |                            |           |           |             |          |
|                                                                            |        |                                                                                     |          |            |                            |           |           |             |          |
| 790160 <sup>S</sup>                                                        |        | NO. 2 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION                              |          |            |                            |           |           | Service     | ATA:79   |
|                                                                            | MOS    | 02-Aug-24                                                                           |          |            |                            |           |           |             |          |
|                                                                            | HRS    | 8612.9                                                                              | 150      |            |                            |           |           |             |          |
|                                                                            | ENC    | 7114                                                                                |          |            |                            |           |           |             |          |
|                                                                            |        |                                                                                     |          |            |                            |           |           |             | PKG:0    |
| PROC. REF: LMM 79-10-01PROC. REF: LMM 79-10-01                             |        |                                                                                     |          |            |                            |           |           |             |          |
|                                                                            |        |                                                                                     |          |            |                            |           |           |             |          |
| 791001                                                                     |        | NO. 1 ENGINE - ENGINE OIL CHIP DETECTOR                                             |          |            |                            |           |           | Component   | ATA:79   |
| PN:277-5501-9002                                                           | MOS/MS | 18-May-13                                                                           | O/C      |            |                            |           |           |             |          |
| SN:N/A                                                                     | HRS    | 7075.3                                                                              |          |            |                            |           |           |             |          |
|                                                                            | ENC    | 5383                                                                                |          |            |                            |           |           |             |          |
| PROC. REF: LMM 79-10-01, LMM 79-10-01PROC. REF: LMM 79-10-01, LMM 79-10-01 |        |                                                                                     |          |            |                            |           |           |             |          |

?-Insufficient Information    S-Suppressed Requirement    \*-Estimated Due(New Requirement)    (EFF)-Effective C / W    (M)-Manual Due    U-User Task    Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                                                    | Unit                                     | C / W     | Interval | TSX / Adj. | Next Due (ENG / APU) A / C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|------------------------------------------|-----------|----------|------------|----------------------------|-----------|-----------|-------------|------------------|
| ATA 79 - OIL                                                               |                                          |           |          |            |                            |           |           |             |                  |
| 791001                                                                     | NO. 2 ENGINE - ENGINE OIL CHIP DETECTOR  |           |          |            |                            |           |           |             | Component ATA:79 |
| PN:277-5501-9004                                                           | MOS/MSC                                  | 18-May-13 | O/C      |            |                            |           |           |             |                  |
| SN:N/A                                                                     | HRS                                      | 6239      |          |            |                            |           |           |             |                  |
|                                                                            | ENC                                      | 5281      |          |            |                            |           |           |             |                  |
| PROC. REF: LMM 79-10-01, LMM 79-10-01PROC. REF: LMM 79-10-01, LMM 79-10-01 |                                          |           |          |            |                            |           |           |             |                  |
| 792008                                                                     | NO. 1 ENGINE - OIL FLOW REDUCTION VALVE  |           |          |            |                            |           |           |             | Component ATA:79 |
| PN:PN                                                                      | MOS/MSC                                  | 05-Jan-00 | O/C      | TSN 0      |                            |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                      | 0         |          | TSN 0      |                            |           |           |             |                  |
|                                                                            | ENC                                      | 0         |          | TSN 0      |                            |           |           |             |                  |
| PROC. REF: LMM 79-20-08, LMM 79-20-08PROC. REF: LMM 79-20-08, LMM 79-20-08 |                                          |           |          |            |                            |           |           |             |                  |
| 792008                                                                     | NO. 2 ENGINE - OIL FLOW REDUCTION VALVE  |           |          |            |                            |           |           |             | Component ATA:79 |
| PN:PN                                                                      | MOS/MSC                                  | 15-Jan-00 | O/C      | TSN 0      |                            |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                      | 0         |          | TSN 0      |                            |           |           |             |                  |
|                                                                            | ENC                                      | 0         |          | TSN 0      |                            |           |           |             |                  |
| PROC. REF: LMM 79-20-08, LMM 79-20-08PROC. REF: LMM 79-20-08, LMM 79-20-08 |                                          |           |          |            |                            |           |           |             |                  |
| 792011                                                                     | NO. 1 ENGINE - FUEL/OIL VALVE            |           |          |            |                            |           |           |             | Component ATA:79 |
| PN:PN                                                                      | MOS/MSC                                  | 05-Jan-00 | O/C      | TSN 0      |                            |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                      | 0         |          | TSN 0      |                            |           |           |             |                  |
|                                                                            | ENC                                      | 0         |          | TSN 0      |                            |           |           |             |                  |
| 792011                                                                     | NO. 2 ENGINE - FUEL/OIL VALVE            |           |          |            |                            |           |           |             | Component ATA:79 |
| PN:PN                                                                      | MOS/MSC                                  | 15-Jan-00 | O/C      | TSN 0      |                            |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                      | 0         |          | TSN 0      |                            |           |           |             |                  |
|                                                                            | ENC                                      | 0         |          | TSN 0      |                            |           |           |             |                  |
| 792012                                                                     | NO. 1 ENGINE - OIL TEMPERATURE REGULATOR |           |          |            |                            |           |           |             | Component ATA:79 |
| PN:PN                                                                      | MOS/MSC                                  | 05-Jan-00 | O/C      | TSN 0      |                            |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                      | 0         |          | TSN 0      |                            |           |           |             |                  |
|                                                                            | ENC                                      | 0         |          | TSN 0      |                            |           |           |             |                  |
| PROC. REF: LMM 79-20-03, LMM 79-20-03PROC. REF: LMM 79-20-03, LMM 79-20-03 |                                          |           |          |            |                            |           |           |             |                  |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C / W   (M)-Manual Due   U-User Task   Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                                                    | Unit                                          | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|-----------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 79 - OIL                                                               |                                               |           |          |          |                        |           |           |             |                  |
| 792012                                                                     | NO. 2 ENGINE - OIL TEMPERATURE REGULATOR      |           |          |          |                        |           |           |             | Component ATA:79 |
| PN:PN                                                                      | MOS/MSC                                       | 15-Jan-00 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | ENC                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: LMM 79-20-03, LMM 79-20-03PROC. REF: LMM 79-20-03, LMM 79-20-03 |                                               |           |          |          |                        |           |           |             |                  |
| 792037                                                                     | NO. 1 OIL PRESSURE SWITCH                     |           |          |          |                        |           |           |             | Component ATA:79 |
| PN:PN                                                                      | MOS/MSC                                       | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 79-30-02PROC. REF: AMM 79-30-02                             |                                               |           |          |          |                        |           |           |             |                  |
| 792038                                                                     | NO. 2 OIL PRESSURE SWITCH                     |           |          |          |                        |           |           |             | Component ATA:79 |
| PN:PN                                                                      | MOS/MSC                                       | 09-Mar-01 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 79-30-02PROC. REF: AMM 79-30-02                             |                                               |           |          |          |                        |           |           |             |                  |
| 792220                                                                     | NO. 1 ENGINE - UPPER OIL COOLER ASSEMBLY      |           |          |          |                        |           |           |             | Component ATA:79 |
| PN:PN                                                                      | MOS/MSC                                       | 05-Jan-00 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | ENC                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
| 792220                                                                     | NO. 2 ENGINE - UPPER OIL COOLER ASSEMBLY      |           |          |          |                        |           |           |             | Component ATA:79 |
| PN:160554-5                                                                | MOS/MSC                                       | 05-Jun-06 | O/C      |          |                        |           |           |             |                  |
| SN:76-247                                                                  | HRS                                           | 3701.2    |          |          |                        |           |           |             |                  |
|                                                                            | ENC                                           | 3369      |          |          |                        |           |           |             |                  |
| 792230                                                                     | NO. 1 ENGINE - LOWER LEFT OIL COOLER ASSEMBLY |           |          |          |                        |           |           |             | Component ATA:79 |
| PN:PN                                                                      | MOS/MSC                                       | 05-Jan-00 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | ENC                                           | 0         |          | TSN 0    |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9669.1
 AFL: 7372
 As Of: 01-Apr-2025
 02-Apr-2025 02:58 PM

| PN & SN                                                                    | Unit                                           | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 79 - OIL                                                               |                                                |           |          |          |                        |           |           |             |                  |
| 792230                                                                     | NO. 2 ENGINE - LOWER LEFT OIL COOLER ASSEMBLY  |           |          |          |                        |           |           |             | Component ATA:79 |
| PN:160552-3                                                                | MOS/MSC                                        | 05-Jun-06 | O/C      |          |                        |           |           |             |                  |
| SN:47-274                                                                  | HRS                                            | 3701.2    |          |          |                        |           |           |             |                  |
|                                                                            | ENC                                            | 3369      |          |          |                        |           |           |             |                  |
| 792240                                                                     | NO. 1 ENGINE - LOWER RIGHT OIL COOLER ASSEMBLY |           |          |          |                        |           |           |             | Component ATA:79 |
| PN:PN                                                                      | MOS/MSC                                        | 05-Jan-00 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                            | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | ENC                                            | 0         |          | TSN 0    |                        |           |           |             |                  |
| 792240                                                                     | NO. 2 ENGINE - LOWER RIGHT OIL COOLER ASSEMBLY |           |          |          |                        |           |           |             | Component ATA:79 |
| PN:160554-6                                                                | MOS/MSC                                        | 05-Jun-06 | O/C      |          |                        |           |           |             |                  |
| SN:1068                                                                    | HRS                                            | 3701.2    |          |          |                        |           |           |             |                  |
|                                                                            | ENC                                            | 3369      |          |          |                        |           |           |             |                  |
| 792250                                                                     | NO. 1 ENGINE - PRESSURE BREATHER VALVE         |           |          |          |                        |           |           |             | Component ATA:79 |
| PN:PN                                                                      | MOS/MSC                                        | 05-Jan-00 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                            | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | ENC                                            | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: LMM 79-20-02, LMM 79-20-02PROC. REF: LMM 79-20-02, LMM 79-20-02 |                                                |           |          |          |                        |           |           |             |                  |
| 792250                                                                     | NO. 2 ENGINE - PRESSURE BREATHER VALVE         |           |          |          |                        |           |           |             | Component ATA:79 |
| PN:3075323-3                                                               | MOS/MSC                                        | 16-Feb-11 | O/C      |          |                        |           |           |             |                  |
| SN:000814506520                                                            | HRS                                            | 5602      |          |          |                        |           |           |             |                  |
|                                                                            | ENC                                            | 4823      |          |          |                        |           |           |             |                  |
| PROC. REF: LMM 79-20-02, LMM 79-20-02PROC. REF: LMM 79-20-02, LMM 79-20-02 |                                                |           |          |          |                        |           |           |             |                  |
| 792260                                                                     | NO. 1 ENGINE - OIL TEMPERATURE CONTROL VALVE   |           |          |          |                        |           |           |             | Component ATA:79 |
| PN:PN                                                                      | MOS/MSC                                        | 05-Jan-00 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                            | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | ENC                                            | 0         |          | TSN 0    |                        |           |           |             |                  |

?-Insufficient Information    S-Suppressed Requirement    \*-Estimated Due(New Requirement)    (EFF)-Effective C/W    (M)-Manual Due    U-User Task    Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025 02-Apr-2025 02:58 PM

| PN & SN                                        | Unit                                         | C / W     | Interval | TSX / Adj. | Next Due (ENG / APU) A / C | Max Limit | Remaining | Disposition | Warranty         |
|------------------------------------------------|----------------------------------------------|-----------|----------|------------|----------------------------|-----------|-----------|-------------|------------------|
| ATA 79 - OIL                                   |                                              |           |          |            |                            |           |           |             |                  |
| 792260                                         | NO. 2 ENGINE - OIL TEMPERATURE CONTROL VALVE |           |          |            |                            |           |           |             | Component ATA:79 |
| PN:PN                                          | MOS/MSC                                      | 15-Jan-00 | O/C      | TSN 0      |                            |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                          | 0         |          | TSN 0      |                            |           |           |             |                  |
|                                                | ENC                                          | 0         |          | TSN 0      |                            |           |           |             |                  |
|                                                |                                              |           |          |            |                            |           |           |             |                  |
| 793001                                         | NO. 1 ENGINE OIL PRESSURE TRANSDUCER         |           |          |            |                            |           |           |             | Component ATA:79 |
| PN:PN                                          | MOS/MSC                                      | 09-Mar-01 | O/C      | TSN 0      |                            |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                          | 0         |          | TSN 0      |                            |           |           |             |                  |
|                                                | AFL                                          | 0         |          | TSN 0      |                            |           |           |             |                  |
| PROC. REF: AMM 79-30-01PROC. REF: AMM 79-30-01 |                                              |           |          |            |                            |           |           |             |                  |
|                                                |                                              |           |          |            |                            |           |           |             |                  |
| 793002                                         | NO. 2 ENGINE OIL PRESSURE TRANSDUCER         |           |          |            |                            |           |           |             | Component ATA:79 |
| PN:PN                                          | MOS/MSC                                      | 09-Mar-01 | O/C      | TSN 0      |                            |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                          | 0         |          | TSN 0      |                            |           |           |             |                  |
|                                                | AFL                                          | 0         |          | TSN 0      |                            |           |           |             |                  |
| PROC. REF: AMM 79-30-01PROC. REF: AMM 79-30-01 |                                              |           |          |            |                            |           |           |             |                  |
|                                                |                                              |           |          |            |                            |           |           |             |                  |
| 793011                                         | LEFT TEMPERATURE OIL BULB                    |           |          |            |                            |           |           |             | Component ATA:79 |
| PN:PN                                          | MOS/MSC                                      | 09-Mar-01 | O/C      | TSN 0      |                            |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                          | 0         |          | TSN 0      |                            |           |           |             |                  |
|                                                | AFL                                          | 0         |          | TSN 0      |                            |           |           |             |                  |
| PROC. REF: AMM 79-30-03PROC. REF: AMM 79-30-03 |                                              |           |          |            |                            |           |           |             |                  |
|                                                |                                              |           |          |            |                            |           |           |             |                  |
| 793012                                         | RIGHT TEMPERATURE OIL BULB                   |           |          |            |                            |           |           |             | Component ATA:79 |
| PN:PN                                          | MOS/MSC                                      | 09-Mar-01 | O/C      | TSN 0      |                            |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                          | 0         |          | TSN 0      |                            |           |           |             |                  |
|                                                | AFL                                          | 0         |          | TSN 0      |                            |           |           |             |                  |
| PROC. REF: AMM 79-30-03PROC. REF: AMM 79-30-03 |                                              |           |          |            |                            |           |           |             |                  |
|                                                |                                              |           |          |            |                            |           |           |             |                  |
| 793013                                         | APU TEMPERATURE OIL BULB                     |           |          |            |                            |           |           |             | Component ATA:79 |
| PN:PN                                          | MOS/MSC                                      | 09-Mar-01 | O/C      | TSN 0      |                            |           |           |             |                  |
| SN:UNKNOWN                                     | HRS                                          | 0         |          | TSN 0      |                            |           |           |             |                  |
|                                                | AFL                                          | 0         |          | TSN 0      |                            |           |           |             |                  |
| PROC. REF: AMM 79-30-03PROC. REF: AMM 79-30-03 |                                              |           |          |            |                            |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN | Unit | C / W | Interval | TSX / Adj. | Next Due (ENG / APU) A / C | Max Limit | Remaining | Disposition | Warranty |
|---------|------|-------|----------|------------|----------------------------|-----------|-----------|-------------|----------|
|---------|------|-------|----------|------------|----------------------------|-----------|-----------|-------------|----------|

ATA 79 - OIL

|                                                    |                          |           |     |       |  |  |  |           |        |
|----------------------------------------------------|--------------------------|-----------|-----|-------|--|--|--|-----------|--------|
| 793064                                             | NO. 1 ENGINE - TEMP BULB |           |     |       |  |  |  | Component | ATA:79 |
| PN:PN                                              | MOS/MSC                  | 05-Jan-00 | O/C | TSN 0 |  |  |  |           |        |
| SN:UNKNOWN                                         | HRS                      | 0         |     | TSN 0 |  |  |  |           |        |
|                                                    | ENC                      | 0         |     | TSN 0 |  |  |  |           |        |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                          |           |     |       |  |  |  |           |        |

|                                                    |                          |           |     |       |  |  |  |           |        |
|----------------------------------------------------|--------------------------|-----------|-----|-------|--|--|--|-----------|--------|
| 793064                                             | NO. 2 ENGINE - TEMP BULB |           |     |       |  |  |  | Component | ATA:79 |
| PN:PN                                              | MOS/MSC                  | 15-Jan-00 | O/C | TSN 0 |  |  |  |           |        |
| SN:UNKNOWN                                         | HRS                      | 0         |     | TSN 0 |  |  |  |           |        |
|                                                    | ENC                      | 0         |     | TSN 0 |  |  |  |           |        |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                          |           |     |       |  |  |  |           |        |

|                 |                                        |           |     |       |  |  |  |           |        |
|-----------------|----------------------------------------|-----------|-----|-------|--|--|--|-----------|--------|
| 793310          | NO. 1 ENGINE - OIL FILTER BYPASS VALVE |           |     |       |  |  |  | Component | ATA:79 |
| PN:3060782-2    | MOS/MSC                                | 25-Oct-06 | O/C | TSN 0 |  |  |  |           |        |
| SN:060645105349 | HRS                                    | 4857.2    |     | TSN 0 |  |  |  |           |        |
|                 | ENC                                    | 3730      |     | TSN 0 |  |  |  |           |        |

|              |                                        |           |     |       |  |  |  |           |        |
|--------------|----------------------------------------|-----------|-----|-------|--|--|--|-----------|--------|
| 793310       | NO. 2 ENGINE - OIL FILTER BYPASS VALVE |           |     |       |  |  |  | Component | ATA:79 |
| PN:3060782-2 | MOS/MSC                                | 25-Nov-20 | O/C | TSO 0 |  |  |  |           |        |
| SN:K15538    | HRS                                    | 7388.5    |     | TSO 0 |  |  |  |           |        |
|              | ENC                                    | 6230      |     | TSO 0 |  |  |  |           |        |

|                     |                                                                             |           |     |  |  |  |  |         |        |
|---------------------|-----------------------------------------------------------------------------|-----------|-----|--|--|--|--|---------|--------|
| 793315 <sup>S</sup> | NO. 1 ENGINE - CHECK OIL FILTER BYPASS VALVE CIRCUIT/THERMAL LOCKOUT SWITCH |           |     |  |  |  |  | Service | ATA:79 |
|                     | MOS                                                                         | 22-Jun-23 |     |  |  |  |  |         |        |
|                     | HRS                                                                         | 9184.4    | 600 |  |  |  |  |         |        |
|                     | ENC                                                                         | 7042      |     |  |  |  |  |         |        |
|                     |                                                                             |           |     |  |  |  |  |         | PKG:0  |

|                     |                                                                             |           |     |  |  |  |  |         |        |
|---------------------|-----------------------------------------------------------------------------|-----------|-----|--|--|--|--|---------|--------|
| 793315 <sup>S</sup> | NO. 2 ENGINE - CHECK OIL FILTER BYPASS VALVE CIRCUIT/THERMAL LOCKOUT SWITCH |           |     |  |  |  |  | Service | ATA:79 |
|                     | MOS                                                                         | 22-Jun-23 |     |  |  |  |  |         |        |
|                     | HRS                                                                         | 8345.7    | 600 |  |  |  |  |         |        |
|                     | ENC                                                                         | 6938      |     |  |  |  |  |         |        |
|                     |                                                                             |           |     |  |  |  |  |         | PKG:0  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9669.1 AFL: 7372 As Of: 01-Apr-2025

02-Apr-2025 02:58 PM

| PN & SN                                                                    | Unit                                             | C / W     | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|--------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 79 - OIL                                                               |                                                  |           |          |          |                        |           |           |             |                  |
| 793320                                                                     | NO. 1 ENGINE - FUEL HEATER / OIL COOLER ASSEMBLY |           |          |          |                        |           |           |             | Component ATA:79 |
| PN:160506-4                                                                | MOS/MSC                                          | 30-Nov-16 | O/C      | TSO 4    |                        |           |           |             |                  |
| SN:47-486                                                                  | HRS                                              | 7607.6    |          | TSO 0    |                        |           |           |             |                  |
|                                                                            | ENC                                              | 5820      |          | TSO 0    |                        |           |           |             |                  |
| PROC. REF: LMM 79-20-07, LMM 79-20-07PROC. REF: LMM 79-20-07, LMM 79-20-07 |                                                  |           |          |          |                        |           |           |             |                  |
| 793320                                                                     | NO. 2 ENGINE - FUEL HEATER / OIL COOLER ASSEMBLY |           |          |          |                        |           |           |             | Component ATA:79 |
| PN:3060709-4                                                               | MOS/MSC                                          | 05-Jun-06 | O/C      |          |                        |           |           |             |                  |
| SN:16-240                                                                  | HRS                                              | 3701.2    |          |          |                        |           |           |             |                  |
|                                                                            | ENC                                              | 3369      |          |          |                        |           |           |             |                  |
| PROC. REF: LMM 79-20-07, LMM 79-20-07PROC. REF: LMM 79-20-07, LMM 79-20-07 |                                                  |           |          |          |                        |           |           |             |                  |
| ATA 85 - FUEL CELL SYSTEMS                                                 |                                                  |           |          |          |                        |           |           |             |                  |
| 859000                                                                     | SUBMIT LOGBOOK ENTRIES FOR ELOGBOOK              |           |          |          |                        |           |           |             | Service ATA:85   |
|                                                                            | MOS/MSC                                          | 09-Mar-01 | A/R      |          |                        |           |           |             |                  |
|                                                                            | HRS                                              | 0         |          |          |                        |           |           |             |                  |
|                                                                            | AFL                                              | 0         |          |          |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                                  |           |          |          |                        |           |           |             |                  |