

OWNER: PRIVATE JETS INC.
 ADDRESS: 7220 NW 63TH ST
 BETHANY OK 73008
 OFFICE:
 FAX:

OPERATOR: PRIVATE JETS INC.
 ADDRESS: 7220 NW 63TH ST
 BETHANY OK 73008
 OFFICE:
 FAX:

ANALYST: SEAN WELLS
 EMAIL: SWELLS@CAMPSYSTEMS.COM

+1-316-928-7895 (DIRECT)
 +1-631-588-3200 (MAIN)
 WWW.CAMPSYSTEMS.COM

800-787-9749 (EFAX-CARDS)
 631-980-4222 (EFAX-CARDS)

PLEASE REACH OUT TO YOUR ANALYST TO
 RECORD CHANGES TO ADDRESS, LAST ACTUALS
 (IF ANY).

AIRCRAFT	SERIAL/REGNO: 45-145/N942FK	MODEL: LEARJET 45XR	MANUFACTURER: BOMBARDIER AVIATION
----------	-----------------------------	---------------------	-----------------------------------

CERTIFICATION DATE: 09-MAR-2001

LAST ACTUALS:
 10023.1 A/C HRS as of 09-FEB-2026
 7616 AFL as of 09-FEB-2026
 2691.6 ACH as of 27-OCT-2025

ENGINE NO. 1	SERIAL/PART: P-116284C/3060082-2	MODEL: TFE731-20BR-1B	MANUFACTURER: HONEYWELL
--------------	----------------------------------	-----------------------	-------------------------

INSTALLED ON: 20-JAN-2000
 0 ENG. HRS 0 A/C HRS
 0 ENC

LAST ACTUALS:
 9949 ENG. HRS as of 09-FEB-2026
 7558 ENC as of 09-FEB-2026

ENGINE NO. 2	SERIAL/PART: P-116285C/3060084-2	MODEL: TFE731-20BR-1B	MANUFACTURER: HONEYWELL
--------------	----------------------------------	-----------------------	-------------------------

INSTALLED ON: 12-AUG-2015
 6622.3 ENG. HRS 7535.1 A/C HRS
 5602 ENC

LAST ACTUALS:
 9110.3 ENG. HRS as of 09-FEB-2026
 7454 ENC as of 09-FEB-2026

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 00 - INFORMATION										
CI45-150721	REVIEW CONCORDE EMERGENCY BATTERY CMM 5-0167 REV E								Service	ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS		
	HRS									
	AFL									
PROC. REF: RCF CI45PROC. REF: RCF CI45										
CI45-160527	REVIEW LEARJET AMM REVISION 66								Service	ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS		
	HRS									
	AFL									
PROC. REF: RCF CI45PROC. REF: RCF CI45										
CI45-160603	REVIEW LEARJET 45 AMM TR 4-40								Service	ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS		
	HRS									
	AFL									
PROC. REF: RCF CI45PROC. REF: RCF CI45										
CI45-160613	REVIEW LEARJET 45 AMM TR 5-110								Service	ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS		
	HRS									
	AFL									
PROC. REF: RCF CI45PROC. REF: RCF CI45										
CI45-161207B	REVIEW LEARJET 45 AMM REVISION 67								Service	ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS		
	HRS									
	AFL									
PROC. REF: RCF CI45PROC. REF: RCF CI45										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 00 - INFORMATION										
CI45-181109B	REVIEW LEARJET 45/45XR AMM REVISION 71								Service	ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS		
	HRS									
	AFL									
PROC. REF: RCF C145PROC. REF: RCF C145										
CI45-190429A	REVIEW LEARJET 45/45XR AMM REV 72								Service	ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS		
	HRS									
	AFL									
PROC. REF: RCF C145PROC. REF: RCF C145										
CI45-200529	REVIEW AUDIT SUMMARY CHANGE FORM								Service	ATA:00
	MOS/MSC	EFF	-					AUDIT SUMMARY CHANGE FORM		
	HRS									
	AFL									
PROC. REF: RCF C145PROC. REF: RCF C145										
CI45-210120	REVIEW LEARJET 45/45XR AUDIT SUMMARY CHANGE FORM								Service	ATA:00
	MOS/MSC	30-Mar-21	-					AUDIT SUMMARY CHANGE FORM		
	HRS	8414.4								
	AFL	6463								
PROC. REF: RCF C145PROC. REF: RCF C145										
CI45-260206	REVIEW ATTACHED AUDIT SUMMARY CHANGE FORM								Service	ATA:00
	MOS/MSC	EBT	-				NEW REQMT	AUDIT SUMMARY CHANGE FORM		
	HRS									
	AFL									
PROC. REF: RCF C145PROC. REF: RCF C145										

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 00 - INFORMATION

EC04-180802	NO. 1 ENGINE - REVIEW TFE731-20/-40/-60 (CIMMS) LMM TR 5-17							Service	ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS	
	HRS								
	ENC								
PROC. REF: RCF EC04-180802PROC. REF: RCF EC04-180802									

EC04-180802	NO. 2 ENGINE - REVIEW TFE731-20/-40/-60 (CIMMS) LMM TR 5-17							Service	ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS	
	HRS								
	ENC								
PROC. REF: RCF EC04-180802PROC. REF: RCF EC04-180802									

ATA 05 - TIME LIMITS/MAINTENANCE CHECKS

051101	PHASE A1-300 HOUR CHECKS							Package	ATA:05
	MOS	21-Aug-25	12		21-Aug-26		190 d		
	HRS	9809.8	300		10109.8		86.7		
WC#: 05.110	AFL	7471							
PROC. REF: AMM 05-10-00, AMM 05-11-01PROC. REF: AMM 05-10-00, AMM 05-11-01									

PKG:1

051102	PHASE A2-300 HOUR CHECKS							Package	ATA:05
	MOS	21-Aug-25	12		21-Aug-26		190 d		
	HRS	9809.8	300		10109.8		86.7		
	AFL	7471							
PROC. REF: AMM 05-10-00, AMM 05-11-02PROC. REF: AMM 05-10-00, AMM 05-11-02									

PKG:2

051103	PHASE A3-300 HOUR CHECKS							Package	ATA:05
	MOS	21-Aug-25	12		21-Aug-26		190 d		
	HRS	9809.8	300		10109.8		86.7		
	AFL	7471							
PROC. REF: AMM 05-10-00, AMM 05-11-03PROC. REF: AMM 05-10-00, AMM 05-11-03									

PKG:3

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS										
051104	PHASE A4-300 HOUR CHECKS								Package	ATA:05
	MOS	21-Aug-25	12		21-Aug-26		190 d			
	HRS	9809.8	300		10109.8		86.7			
	AFL	7471								
PROC. REF: AMM 05-10-00, AMM 05-11-04 PROC. REF: AMM 05-10-00, AMM 05-11-04										
051105	PHASE A5-300 HOUR CHECKS								Package	ATA:05
	MOS	21-Aug-25	12		21-Aug-26		190 d			
	HRS	9809.8	300		10109.8		86.7			
	AFL	7471								
PROC. REF: AMM 05-10-00, AMM 05-11-05 PROC. REF: AMM 05-10-00, AMM 05-11-05										
051106	PHASE A6-300 HOUR CHECKS								Package	ATA:05
	MOS	21-Aug-25	12		21-Aug-26		190 d			
	HRS	9809.8	300		10109.8		86.7			
	AFL	7471								
PROC. REF: AMM 05-10-00, AMM 05-11-06 PROC. REF: AMM 05-10-00, AMM 05-11-06										
051201	PHASE B1 600 HOUR CHECKS								Package	ATA:05
	MOS	02-Aug-24	24		02-Aug-26		171 d			
	HRS	9525.7	600		10125.7		102.6			
	AFL	7276								
PROC. REF: AMM 05-12-01, AMM 05-10-00 PROC. REF: AMM 05-12-01, AMM 05-10-00										
051202	PHASE B2 600 HOUR CHECKS								Package	ATA:05
	MOS	02-Aug-24	24		02-Aug-26		171 d			
	HRS	9525.7	600		10125.7		102.6			
	AFL	7276								
PROC. REF: AMM 05-12-02, AMM 05-10-00 PROC. REF: AMM 05-12-02, AMM 05-10-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS										
051203	PHASE B3 600 HOUR CHECKS								Package	ATA:05
	MOS	02-Aug-24	24		02-Aug-26		171 d			
	HRS	9525.7	600		10125.7		102.6			
	AFL	7276								
PROC. REF: AMM 05-12-03, AMM 05-10-00PROC. REF: AMM 05-12-03, AMM 05-10-00										
PKG:9										
051204	PHASE B4 600 HOUR CHECKS								Package	ATA:05
	MOS	02-Aug-24	24		02-Aug-26		171 d			
	HRS	9525.7	600		10125.7		102.6			
	AFL	7276								
PROC. REF: AMM 05-12-04, AMM 05-10-00PROC. REF: AMM 05-12-04, AMM 05-10-00										
PKG:10										
051205	PHASE B5 600 HOUR CHECKS								Package	ATA:05
	MOS	02-Aug-24	24		02-Aug-26		171 d			
	HRS	9525.7	600		10125.7		102.6			
	AFL	7276								
PROC. REF: AMM 05-12-05, AMM 05-10-00PROC. REF: AMM 05-12-05, AMM 05-10-00										
PKG:11										
051206	PHASE B6 600 HOUR CHECKS								Package	ATA:05
	MOS	02-Aug-24	24		02-Aug-26		171 d			
	HRS	9525.7	600		10125.7		102.6			
	AFL	7276								
PROC. REF: AMM 05-12-06, AMM 05-10-00PROC. REF: AMM 05-12-06, AMM 05-10-00										
PKG:12										
051301	PHASE C1 1200 HOUR CHECKS								Package	ATA:05
	MOS	22-Jun-23	48		22-Jun-27		495 d			
	HRS	9258.5	1200		10458.5		435.4			
	AFL	7100								
PROC. REF: AMM 05-13-01, AMM 05-10-00PROC. REF: AMM 05-13-01, AMM 05-10-00										
PKG:13										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS										
051302	PHASE C2 1200 HOUR CHECKS								Package	ATA:05
	MOS	22-Jun-23	48		22-Jun-27		495 d			
	HRS	9258.5	1200		10458.5		435.4			
	AFL	7100								
PKG:14										
PROC. REF: AMM 05-13-02, AMM 05-10-00PROC. REF: AMM 05-13-02, AMM 05-10-00										
051303	PHASE C3 1200 HOUR CHECKS								Package	ATA:05
	MOS	22-Jun-23	48		22-Jun-27		495 d			
	HRS	9258.5	1200		10458.5		435.4			
	AFL	7100								
PKG:15										
PROC. REF: AMM 05-13-03, AMM 05-10-00PROC. REF: AMM 05-13-03, AMM 05-10-00										
051304	PHASE C4 1200 HOUR CHECKS								Package	ATA:05
	MOS	22-Jun-23	48		22-Jun-27		495 d			
	HRS	9258.5	1200		10458.5		435.4			
	AFL	7100								
PKG:16										
PROC. REF: AMM 05-13-04, AMM 05-10-00PROC. REF: AMM 05-13-04, AMM 05-10-00										
051305	PHASE C5 1200 HOUR CHECKS								Package	ATA:05
	MOS	22-Jun-23	48		22-Jun-27		495 d			
	HRS	9258.5	1200		10458.5		435.4			
	AFL	7100								
PKG:17										
PROC. REF: AMM 05-13-05, AMM 05-10-00PROC. REF: AMM 05-13-05, AMM 05-10-00										
051306	PHASE C6 1200 HOUR CHECKS								Package	ATA:05
	MOS	22-Jun-23	48		22-Jun-27		495 d			
	HRS	9258.5	1200		10458.5		435.4			
	AFL	7100								
PKG:18										
PROC. REF: AMM 05-13-06, AMM 05-10-00PROC. REF: AMM 05-13-06, AMM 05-10-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS										
051401	PHASE D1 2400 HOUR CHECKS								Package	ATA:05
	MOS	25-Nov-19	96		25-Nov-27		651 d			
	HRS	8177.7	2400		10577.7		554.6			
	AFL	6303								
PKG:19										
PROC. REF: AMM 05-14-01, AMM 05-10-00PROC. REF: AMM 05-14-01, AMM 05-10-00										
051402	PHASE D2 2400 HOUR CHECKS								Package	ATA:05
	MOS	25-Nov-19	96		25-Nov-27		651 d			
	HRS	8177.7	2400		10577.7		554.6			
	AFL	6303								
PKG:20										
PROC. REF: AMM 05-14-02, AMM 05-10-00PROC. REF: AMM 05-14-02, AMM 05-10-00										
051403	PHASE D3 2400 HOUR CHECKS								Package	ATA:05
	MOS	25-Nov-19	96		25-Nov-27		651 d			
	HRS	8177.7	2400		10577.7		554.6			
	AFL	6303								
PKG:21										
PROC. REF: AMM 05-14-03, AMM 05-10-00PROC. REF: AMM 05-14-03, AMM 05-10-00										
051404	PHASE D4 2400 HOUR CHECKS								Package	ATA:05
	MOS	25-Nov-19	96		25-Nov-27		651 d			
	HRS	8177.7	2400		10577.7		554.6			
	AFL	6303								
PKG:22										
PROC. REF: AMM 05-14-04, AMM 05-10-00PROC. REF: AMM 05-14-04, AMM 05-10-00										
051405	PHASE D5 2400 HOUR CHECKS								Package	ATA:05
	MOS	25-Nov-19	96		25-Nov-27		651 d			
	HRS	8177.7	2400		10577.7		554.6			
	AFL	6303								
PKG:23										
PROC. REF: AMM 05-14-05, AMM 05-10-00PROC. REF: AMM 05-14-05, AMM 05-10-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS										
051406	PHASE D6 2400 HOUR CHECKS								Package	ATA:05
	MOS	25-Nov-19	96		25-Nov-27		651 d			
	HRS	8177.7	2400		10577.7		554.6			
	AFL	6303								
PROC. REF: AMM 05-14-06, AMM 05-10-00 PROC. REF: AMM 05-14-06, AMM 05-10-00										
051500	4800 HOUR CHECKS								Package	ATA:05
	MOS	22-Jun-23								
	HRS	9258.5	4800		14058.5		4035.4			
	AFL	7100								
PROC. REF: AMM 05-15-00, AMM 05-10-00 PROC. REF: AMM 05-15-00, AMM 05-10-00										
051600	9600 HOUR CHECKS								Package	ATA:05
	MOS	02-Aug-24								
	HRS	9525.7	9600		19125.7		9102.6			
	AFL	7276								
PROC. REF: AMM 05-16-00, AMM 05-10-00 PROC. REF: AMM 05-16-00, AMM 05-10-00										
051700	MAJOR LANDING GEAR INSPECTION								Package	ATA:05
	MOS	09-Mar-01								
	HRS	0								
	AFL	0	10000		10000		2384			
PROC. REF: AMM 05-17-00, AMM 05-10-00 PROC. REF: AMM 05-17-00, AMM 05-10-00										
057110	NO. 1 ENGINE - 150 TO 250 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS								Package	ATA:05
	MOS	28-Jul-25								
	HRS	9706.3	250		(9956.3) 10030.4		7.3			
	ENC	7396								
PROC. REF: LMM 72-00-00 PROC. REF: LMM 72-00-00										

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty		
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS											
057110			NO. 2 ENGINE - 150 TO 250 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							Package	ATA:05
	MOS	28-Jul-25									
	HRS	8867.6	250		(9117.6) 10030.4		7.3				
	ENC	7292									
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00											
057120			NO. 1 ENGINE - 300 TO 440 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							Package	ATA:05
	MOS/MSC	22-Jun-23	N/A								
	HRS	9184.4									
	ENC	7042									
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00											
057120			NO. 2 ENGINE - 300 TO 440 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							Package	ATA:05
	MOS/MSC	18-Aug-22	N/A								
	HRS	8169.8									
	ENC	6832									
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00											
057130			NO. 1 ENGINE - 500 TO 650 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							Package	ATA:05
	MOS	21-Aug-25									
	HRS	9735.7	600		(10335.7) 10409.8		386.7				
	ENC	7413									
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00											
057130			NO. 2 ENGINE - 500 TO 650 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							Package	ATA:05
	MOS	21-Aug-25									
	HRS	8897	600		(9497) 10409.8		386.7				
	ENC	7309									
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS										
057140		NO. 1 ENGINE - 500 TO 850 HOUR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							Package	ATA:05
	MOS	21-Aug-25								
	HRS	9735.7	800		(10535.7) 10609.8		586.7			
	ENC	7413								
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00										
057140		NO. 2 ENGINE - 500 TO 850 HOUR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							Package	ATA:05
	MOS	21-Aug-25								
	HRS	8897	800		(9697) 10609.8		586.7			
	ENC	7309								
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00										
057150		NO. 1 ENGINE - 1000 TO 1300 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							Package	ATA:05
	MOS	27-Oct-25								
	HRS	9832.1	1200		(11032.1) 11106.2		1083.1			
	ENC	7480								
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00										
057150		NO. 2 ENGINE - 1000 TO 1300 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							Package	ATA:05
	MOS	27-Oct-25								
	HRS	8993.4	1200		(10193.4) 11106.2		1083.1			
	ENC	7376								
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00										
057160		NO. 1 ENGINE - 1500 TO 1650 HOUR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							Package	ATA:05
	MOS	22-Jun-23								
	HRS	9184.4	1600		(10784.4) 10858.5		835.4			
	ENC	7042								
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS										
057160		NO. 2 ENGINE - 1500 TO 1650 HOUR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							Package	ATA:05
	MOS	18-Aug-22								
	HRS	8169.8	1600		(9769.8) 10682.6		659.5			
	ENC	6832								
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00										
5-50-00-02		PERFORM UNSCHEDULED MAINTENANCE CHECK - OVERWEIGHT LANDING (WEIGHT IN EXCESS OF MAXIMUM LANDING WEIGHT)							Service	ATA:05
	MOS/MSC		A/R							
	HRS									
	AFL									
PROC. REF: AMM 05-50-00PROC. REF: AMM 05-50-00										
5-50-00-03		PERFORM UNSCHEDULED MAINTENANCE CHECK - HARD LANDING							Service	ATA:05
	MOS/MSC		A/R							
	HRS									
	AFL									
PROC. REF: AMM 05-50-00PROC. REF: AMM 05-50-00										
5-50-00-09		PERFORM UNSCHEDULED MAINTENANCE CHECK - LIGHTNING STRIKE INSPECTION							Service	ATA:05
	MOS/MSC	09-Mar-01	A/R							
	HRS	0								
	AFL	0								
PROC. REF: AMM 05-50-00PROC. REF: AMM 05-50-00										
5-50-00-18		PERFORM UNSCHEDULED MAINTENANCE CHECK - FOREIGN OBJECT DAMAGE							Service	ATA:05
	MOS/MSC		O/C							
	HRS									
	AFL									
PROC. REF: AMM 05-50-00PROC. REF: AMM 05-50-00										
5-50-00-18.1		PERFORM UNSCHEDULED MAINTENANCE CHECK - FOREIGN OBJECT DAMAGE (BIRD STRIKE)							Service	ATA:05
	MOS/MSC		A/R							
	HRS									
	AFL									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS										
5-50-00-19	PERFORM UNSCHEDULED MAINTENANCE CHECK - ENGINE VIBRATION INDICATION								Service	ATA:05
	MOS/MSC		A/R							
	HRS									
	AFL									
PROC. REF: AMM 05-50-00PROC. REF: AMM 05-50-00										
ATA 08 - LEVELING AND WEIGHING										
082000	WEIGH AIRCRAFT								Service	ATA:08
	MOS	30-Dec-22	36		RTS					
	HRS	9186.7								
	AFL	7047								
PROC. REF: AMM 08-10-00, FAR FAR 135.185PROC. REF: AMM 08-10-00, FAR FAR 135.185										
ATA 11 - PLACARDS AND MARKINGS										
G1130000 ^S	CHECK BRIGHTNESS LEVEL OF ALL SELF-LUMINOUS PLACARDS								Service	ATA:11
	MOS	09-Mar-01	48							
	HRS	0	1200							
	AFL	0								
PROC. REF: AMM 11-30-00PROC. REF: AMM 11-30-00										
ATA 12 - SERVICING										
AB1210060 ^S	MAIN LANDING GEAR UPLOCK ACTUATOR - LUBRICATE								Service	ATA:12
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01										
O1210002 ^S	FLAP ACTUATORS - CHECK OIL LEVEL								Service	ATA:12
	MOS	02-Aug-24	24							
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 12 - SERVICING									
Q1221064 LEFT INBOARD FLAP ACTUATOR JOINT - APPLY CORROSION PREVENTIVE COMPOUND (CPC) Service ATA:12									
	MOS/MSC	05-Dec-19	N/A						
	HRS	8177.8							
	AFL	6304							
PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03									
Q1221064 LEFT OUTBOARD FLAP ACTUATOR JOINT - APPLY CORROSION PREVENTIVE COMPOUND (CPC) Service ATA:12									
	MOS/MSC	05-Dec-19	N/A						
	HRS	8177.8							
	AFL	6304							
PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03									
Q1221064 RIGHT INBOARD FLAP ACTUATOR JOINT - APPLY CORROSION PREVENTIVE COMPOUND (CPC) Service ATA:12									
	MOS/MSC	05-Dec-19	N/A						
	HRS	8177.8							
	AFL	6304							
PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03									
Q1221064 RIGHT OUTBOARD FLAP ACTUATOR JOINT - APPLY CORROSION PREVENTIVE COMPOUND (CPC) Service ATA:12									
	MOS/MSC	05-Dec-19	N/A						
	HRS	8177.8							
	AFL	6304							
PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03									
T1222004 NO. 1 MAIN BATTERY - LEAD-ACID BATTERIES - PERFORM BATTERY CAPACITY CHECK Service ATA:12									
PN:RG-380E/40L	MOS	21-Aug-25	6		21-Feb-26		9 d		
SN:41180857	HRS	9809.8	500		10309.8		286.7		
	AFL	7471							
PROC. REF: AMM 12-22-00, CMM 24-30-71PROC. REF: AMM 12-22-00, CMM 24-30-71									
T1222004 NO. 2 MAIN BATTERY - LEAD-ACID BATTERIES - PERFORM BATTERY CAPACITY CHECK Service ATA:12									
PN:RG-380E/40L	MOS	21-Aug-25	6		21-Feb-26		9 d		
SN:41180858	HRS	9809.8	500		10309.8		286.7		
	AFL	7471							
PROC. REF: AMM 12-22-00, CMM 24-30-71PROC. REF: AMM 12-22-00, CMM 24-30-71									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 12 - SERVICING										
U1210004	FLAP FLEXIBLE TRANSMISSION SHAFTS - HAND LUBRICATE								Service	ATA:12
	MOS	12-Aug-15								
	HRS	7535.1	4800		12335.1		2312			
	AFL	5764								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
Y1210000 ^S	NOSE LANDING GEAR SHOCK STRUT - CHECK FOR PROPER FLUID LEVEL AND INFLATION PRESSURE								Service	ATA:12
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 12-10-02PROC. REF: AMM 12-10-02										
Y1210001 ^S	MAIN LANDING GEAR SHOCK STRUTS - CHECK FOR PROPER FLUID LEVEL AND INFLATION PRESSURE								Service	ATA:12
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 12-10-03PROC. REF: AMM 12-10-03										
Y1210003 ^S	FLAP ACTUATOR BALLNUT - LUBRICATE								Service	ATA:12
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03										
Y1210005 ^S	NOSE LANDING GEAR TRUNNION PIN - LUBRICATE								Service	ATA:12
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 12 - SERVICING										
Y1210006	^S	NOSE LANDING GEAR ACTUATOR ATTACH FITTING - LUBRICATE						Service	ATA:12	
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01										
Y1210007	^S	NOSE AND MAIN TIRES - CHECK FOR PROPER INFLATION						Service	ATA:12	
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 12-10-04PROC. REF: AMM 12-10-04										
Y1210009	^S	NOSE GEAR DOOR HINGE - LUBRICATE						Service	ATA:12	
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02										
Y1210011	^S	MAIN LANDING GEAR ACTUATOR JOINTS - LUBRICATE						Service	ATA:12	
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01										
Y1210012	^S	MAIN LANDING GEAR AXLE BEAM/PISTON JOINTS - LUBRICATE						Service	ATA:12	
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 12 - SERVICING										
Y1210013 ^S			MAIN LANDING GEAR TORQUE LINKS - LUBRICATE						Service	ATA:12
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01										
Y1210014 ^S			MAIN LANDING GEAR DOOR HINGE - LUBRICATE						Service	ATA:12
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02										
Y1210016 ^S			PASSENGER/CREW DOOR HINGE - LUBRICATE						Service	ATA:12
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02										
Y1210017 ^S			PASSENGER/CREW DOOR PINS - LUBRICATE						Service	ATA:12
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02										
Y1210018 ^S			PASSENGER/CREW DOOR TENSION BOLTS - LUBRICATE						Service	ATA:12
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 12 - SERVICING										
Y1210019 ^S	EMERGENCY EXIT DOOR LATCHING MECHANISM - LUBRICATE								Service	ATA:12
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02										
Y1210020 ^S	EMERGENCY EXIT DOOR PINS - LUBRICATE								Service	ATA:12
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02										
Y1210021 ^S	BAGGAGE COMPARTMENT DOOR LATCH PINS - LUBRICATE								Service	ATA:12
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02										
Y1210022 ^S	BAGGAGE COMPARTMENT DOOR HINGE - LUBRICATE								Service	ATA:12
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02										
Y1210023 ^S	OXYGEN SYSTEM SERVICING DOOR HINGE - LUBRICATE								Service	ATA:12
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 12 - SERVICING										
Y1210024 ^S			TOILET SERVICING DOOR HINGE - LUBRICATE						Service	ATA:12
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02										
Y1210025 ^S			PRESSURE REFUELING STATION DOOR HINGE - LUBRICATE						Service	ATA:12
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02										
Y1210026 ^S			FUSELAGE FUEL FILLER DOOR HINGE - LUBRICATE						Service	ATA:12
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02										
Y1210027 ^S			TAILCONE ACCESS DOOR PINS - LUBRICATE						Service	ATA:12
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02										
Y1210028 ^S			TAILCONE ACCESS DOOR HINGE - LUBRICATE						Service	ATA:12
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 12 - SERVICING									
Y1210029^S MAIN LANDING GEAR TRUNNION PIN - LUBRICATE Service ATA:12									
	MOS	21-Aug-25	12						
	HRS	9809.8	300						
	AFL	7471							
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01									
Y1221037^S FLAPS - LUBRICATE ROLLING SURFACES OF MAIN AND NOSE ROLLER TRACKS Service ATA:12									
	MOS	21-Aug-25	12						
	HRS	9809.8	300						
	AFL	7471							
PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03									
Y1221042^S HORIZONTAL STABILIZER UPPER AND LOWER TORQUE LINKS - LUBRICATE Service ATA:12									
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03									
Y1227000^S EMERGENCY PARK BRAKE HANDLE SHAFT - LUBRICATE Service ATA:12									
	MOS	21-Aug-25	12						
	HRS	9809.8	300						
	AFL	7471							
PROC. REF: AMM 12-27-00PROC. REF: AMM 12-27-00									
ATA 21 - AIR CONDITIONING									
211001 SERVO AIR PRESSURE REGULATING VALVE Component ATA:21									
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-15-01PROC. REF: AMM 36-15-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 21 - AIR CONDITIONING										
211011		LEFT PLENUM CHECK VALVE						Component		ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-20-09PROC. REF: AMM 21-20-09										
211012		RIGHT PLENUM CHECK VALVE						Component		ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-20-09PROC. REF: AMM 21-20-09										
211017		LEFT EMERGENCY PRESSURIZATION ISOLATION CHECK VALVE						Component		ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-20-03PROC. REF: AMM 21-20-03										
211018		RIGHT EMERGENCY PRESSURIZATION ISOLATION CHECK VALVE						Component		ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-20-03PROC. REF: AMM 21-20-03										
212001		COCKPIT AIR CHECK VALVE						Component		ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-20-01PROC. REF: AMM 21-20-01										
212007		AFT BLOWER MOTOR						Component		ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-51-09PROC. REF: AMM 21-51-09										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
212008 FORWARD BLOWER MOTOR									Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
212011 LINEAR ELECTRO-MECHANICAL ACTUATOR									Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
212041 NO. 1 ENGINE OZONE CONVERTER									Component ATA:21
PN:4520000100-801	MOS/MSC	01-Apr-22	O/C	TSN 0					
SN:2298	HRS	8936.8		TSN 0					
	AFL	6867		TSN 0					
PROC. REF: AMM 21-20-12PROC. REF: AMM 21-20-12									
212101 NO. 1 THERMAL CONTROL ACTUATOR									Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
212102 NO. 2 THERMAL CONTROL ACTUATOR									Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
212105 LEFT ENVIRONMENTAL CONTROL SYSTEM TRANSITION DUCT									Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
212106 RIGHT ENVIRONMENTAL CONTROL SYSTEM TRANSITION DUCT									Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
212201 LEFT GASPER AIR CHECK VALVE									Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-20-07PROC. REF: AMM 21-20-07									
212202 RIGHT GASPER AIR CHECK VALVE									Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-20-07PROC. REF: AMM 21-20-07									
212213 LEFT CABIN AIR CHECK VALVE									Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-20-02PROC. REF: AMM 21-20-02									
212214 RIGHT CABIN AIR CHECK VALVE									Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-20-02PROC. REF: AMM 21-20-02									
212801 AVIONICS COOLING FAN MOUNT									Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-21-01PROC. REF: AMM 21-21-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 21 - AIR CONDITIONING										
213000		CABIN PRESSURE CONTROLLER						Component		ATA:21
PN:6628408000-023 (10551B08Y09)	MOS/MSC	17-Feb-05	O/C	TSR 0						
SN:0716	HRS	3300.2		TSR 0						
	AFL	2515		TSR 0						
PROC. REF: AMM 21-30-03PROC. REF: AMM 21-30-03										
213001		LEFT EMERGENCY PRESSURE SHUTOFF VALVE						Component		ATA:21
PN:3291224-1	MOS/MSC	03-Dec-09	O/C							
SN:133	HRS	6212.8								
	AFL	4758								
PROC. REF: AMM 21-31-01PROC. REF: AMM 21-31-01										
213002		RIGHT EMERGENCY PRESSURE SHUTOFF VALVE						Component		ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-31-01PROC. REF: AMM 21-31-01										
213021		JET PUMP EJECTOR						Component		ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-30-06PROC. REF: AMM 21-30-06										
213031		PRIMARY OUTFLOW VALVE						Component		ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-30-01PROC. REF: AMM 21-30-01										
213032		SECONDARY OUTFLOW VALVE						Component		ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-30-02PROC. REF: AMM 21-30-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
213055 EMERGENCY PRESSURE ANEROID SWITCH									Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
213056 ABSOLUTE PRESSURE SWITCH									Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
213101 TAILCONE CHECK VALVE									Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
213110 CABIN PRESSURIZATION CHECK VALVE									Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-30-07PROC. REF: AMM 21-30-07									
214301 FOOT WARMER THERMOSTAT (S167)									Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-41-02PROC. REF: AMM 21-41-02									
214925 LEFT ECS CHECK VALVE									Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-10-04PROC. REF: AMM 36-10-04									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 21 - AIR CONDITIONING										
214926		RIGHT ECS CHECK VALVE						Component	ATA:21	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 36-10-04PROC. REF: AMM 36-10-04										
215001		WATER SEPARATOR ASSEMBLY						Component	ATA:21	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 21-50-03PROC. REF: AMM 21-50-03										
215002		WATER SEPARATOR BYPASS VALVE						Component	ATA:21	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
215010		AIR CYCLE MACHINE PRECOOLER ASSEMBLY						Component	ATA:21	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 21-50-08PROC. REF: AMM 21-50-08										
215013		PACK BI-LEVEL PRESURE REGULATOR SHUTOFF VALVE						Component	ATA:21	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 21-50-02PROC. REF: AMM 21-50-02										
215015		AIR CYCLE MACHINE BYPASS CHECK VALVE						Component	ATA:21	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 21-50-07PROC. REF: AMM 21-50-07										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
215019 CABIN REFRIGERATION CONDENSER								Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-51-04PROC. REF: AMM 21-51-04									
215030 ENVIRONMENTAL CONTROL UNIT									
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-50-01PROC. REF: AMM 21-50-01									
215033 AIR CYCLE MACHINE									
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-50-04PROC. REF: AMM 21-50-04									
215036 PRIMARY, SECONDARY HEAT EXCHANGER									
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
215039 AIR CYCLE MACHINE TURBINE									
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-50-04PROC. REF: AMM 21-50-04									
215043 AFT EVAPORATOR									
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-51-09PROC. REF: AMM 21-51-09									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 21 - AIR CONDITIONING										
215044		FORWARD EVAPORATOR						Component	ATA:21	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-51-07PROC. REF: AMM 21-51-07										
215100		AIR CONDITIONING COMPRESSOR						Component	ATA:21	
PN:JBS222-1	MOS/MSC	26-Jul-23	O/C	TSO 0						
SN:K18869	HRS	9278		TSO 0						
	AFL	7111		TSO 0						
PROC. REF: AMM 21-51-01PROC. REF: AMM 21-51-01										
215101		AIR CONDITIONING COMPRESSOR DRIVE MOTOR						Component	ATA:21	
PN:MB86B-6	MOS/MSC	31-Jul-23	O/C	TSO 0						
SN:234	HRS	9282.8		TSO 0						
	AFL	7113		TSO 0						
PROC. REF: AMM 21-51-02PROC. REF: AMM 21-51-02										
216001		ENVIRONMENTAL CONTROL SYSTEM - INTEGRATED TEMPERATURE CONTROLLER						Component	ATA:21	
PN:1151830-3	MOS/MSC	04-Jan-21	O/C							
SN:1151830-00815	HRS	8361.7								
	AFL	6425								
PROC. REF: AMM 21-60-10PROC. REF: AMM 21-60-10										
216014		COCKPIT TEMPERATURE CONTROL VALVE						Component	ATA:21	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-60-05PROC. REF: AMM 21-60-05										
216015		CABIN TEMPERATURE CONTROL VALVE						Component	ATA:21	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-60-04PROC. REF: AMM 21-60-04										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 21 - AIR CONDITIONING										
216025 COCKPIT TEMPERATURE CONTROL SELECTOR									Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-60-01PROC. REF: AMM 21-60-01										
216026 CABIN TEMPERATURE CONTROL SELECTOR									Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-60-01PROC. REF: AMM 21-60-01										
216036 COCKPIT DUCT OVERHEAT THERMOSTAT									Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-60-09PROC. REF: AMM 21-60-09										
216037 CABIN DUCT OVERHEAT THERMOSTAT									Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-60-08PROC. REF: AMM 21-60-08										
216040 28VDC CABIN TEMPERATURE SENSOR/FAN ASSEMBLY									Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-60-03PROC. REF: AMM 21-60-03										
216049 CABIN DUCT OVERTEMP LIMITER									Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-60-06PROC. REF: AMM 21-60-06										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 21 - AIR CONDITIONING										
216071	LOW LIMIT TEMPERATURE CONTROL VALVE								Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
<hr/>										
216074	SERVO AIR PRESSURE REGULATING VALVE								Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 36-15-01PROC. REF: AMM 36-15-01										
<hr/>										
216081	COCKPIT DUCT TEMPERATURE SENSOR								Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 21-60-07PROC. REF: AMM 21-60-07										
<hr/>										
216083	COCKPIT TEMPERATURE SENSOR								Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 21-60-02PROC. REF: AMM 21-60-02										
<hr/>										
216084	CABIN LOW LIMIT TEMPERATURE SENSOR								Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 21-50-09PROC. REF: AMM 21-50-09										
<hr/>										
5-19-00-L2150054	WEAR INSPECTION - AIR CONDITIONING COMPRESSOR DRIVE MOTOR BRUSHES - PERFORM WEAR INSPECTION (RETURN DRIVE MOTOR TO AUTHORIZED SERVICE FACILITY FOR OVERHAUL)								Service	ATA:21
	MOS/MSC	31-Jul-23	N/A	NOT INSTALLED						
	HRS	9282.8								
	AFL	7113								

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
5-19-00-L2150055 OVERHAUL - AIR CONDITIONING COMPRESSOR MOTOR - PERFORM OVERHAUL (RETURN DRIVE MOTOR TO AUTHORIZED SERVICE FACILITY FOR OVERHAUL) Service ATA:21									
	MOS/MSC	22-Jun-23	-					NOT INSTALLED	
	HRS	9258.5							
	AFL	7100							
<hr/>									
J2160007 ^S TEMPERATURE CONTROL SYSTEM - INSPECT AND CLEAN CABIN AND COCKPIT TEMPERATURE CONTROL VALVE SERVO AIR FILTERS Service ATA:21									
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
<hr/>									
PROC. REF: AMM 21-60-11PROC. REF: AMM 21-60-11									
<hr/>									
L2150054 AIR CONDITIONING COMPRESSOR DRIVE MOTOR BRUSHES - PERFORM WEAR INSPECTION Service ATA:21									
PN:MB86B-6	MOS	31-Jul-23							
SN:234	HRS	9282.8							
	AFL	7113							
	ACH	2596.2	600		3196.2		504.6		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
<hr/>									
L2150055 AIR CONDITIONING COMPRESSOR DRIVE MOTOR - PERFORM OVERHAUL Service ATA:21									
PN:MB86B-6	MOS	31-Jul-23							
SN:234	HRS	9282.8							
	AFL	7113							
	ACH	2596.2	1200		3796.2		1104.6		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
<hr/>									
L2150057 ^S ** AUXILIARY HEAT SYSTEM - PERFORM AUXILIARY HEATER ELECTRICAL AND TEMPERATURE SWITCH TEST Service ATA:21									
	MOS	09-Mar-01	48					AIRWORTHINESS	
	HRS	0	1200						
	AFL	0							
<hr/>									
PROC. REF: AMM 21-51-00PROC. REF: AMM 21-51-00									
<hr/>									

PKG:8

PKG:14

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
Q2130000^S PRIMARY AND SECONDARY OUTFLOW VALVES - PERFORM INSPECTION Service ATA:21									
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 21-30-01, AMM 21-30-02PROC. REF: AMM 21-30-01, AMM 21-30-02									
Q2130001^S OUTFLOW VALVE AIR FILTER - REMOVE AND REPLACE Service ATA:21									
	MOS	25-Nov-19	96						
	HRS	8177.7	2400						
	AFL	6303							
PROC. REF: AMM 21-30-04PROC. REF: AMM 21-30-04									
Q2130002^S ** PRESSURIZATION CONTROL SYSTEM - PERFORM FUNCTIONAL TEST. (AWL**) Service ATA:21									
	MOS	09-Mar-01	48					AIRWORTHINESS	
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 21-30-00PROC. REF: AMM 21-30-00									
Y2130003^S PRESSURIZATION CONTROL SYSTEM - PERFORM OPERATIONAL CHECK Service ATA:21									
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 21-30-00PROC. REF: AMM 21-30-00									
Y2130065 CABIN PRESSURIZATION SYSTEM - PERFORM CABIN LEAKAGE TEST Service ATA:21									
	MOS	22-Jun-23							
	HRS	9258.5	1200		10458.5		435.4		
	AFL	7100							
PROC. REF: AMM 21-30-00PROC. REF: AMM 21-30-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 21 - AIR CONDITIONING										
Y2140000 ^S	AIR CYCLE MACHINE HEAT EXCHANGER INLET - PERFORM VISUAL INSPECTION								Service	ATA:21
	MOS	09-Mar-01	48							
	HRS	0	1200							
	AFL	0								
PKG:14										
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
Y2140001	NO. 1 ENGINE OZONE CONVERTER - PERFORM CLEANING AND EFFICIENCY TEST								Service	ATA:21
PN:4520000100-801	MOS	01-Apr-22								
SN:2298	HRS	8936.8	3600		12536.8		2513.7			
	AFL	6867								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
Y2140001	NO. 2 ENGINE OZONE CONVERTER - PERFORM CLEANING AND EFFICIENCY TEST								Service	ATA:21
PN:4520000100-801	MOS	01-Apr-22								
SN:2305	HRS	8936.8	3600		12536.8		2513.7			
	AFL	6867								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
Y2141000 ^S	ENVIRONMENTAL CONTROL UNIT - PERFORM VISUAL INSPECTION								Service	ATA:21
	MOS	09-Mar-01	48							
	HRS	0	1200							
	AFL	0								
PKG:14										
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
Y2141001 ^S	WATER SEPARATOR COALESCER BAG - PERFORM VISUAL INSPECTION. CLEAN IF NECESSARY.								Service	ATA:21
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PKG:2										
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
Y2141002	WATER SEPARATOR COALESCER BAG - REPLACE								Service	ATA:21
	MOS/MSC	09-Mar-01	O/C							
	HRS	0								
	AFL	0								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 21 - AIR CONDITIONING

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

Y2142000 ^S	BAGGAGE COMPARTMENT HEATING SYSTEM - PERFORM FUNCTIONAL TEST							Service	ATA:21
	MOS	25-Nov-19	96						
	HRS	8177.7	2400						
	AFL	6303							

PKG:20

PROC. REF: AMM 21-40-00PROC. REF: AMM 21-40-00

Y2145000 ^S	ECS PLENUM ASSEMBLY CHECK VALVES - PERFORM VISUAL INSPECTION. VERIFY FREEDOM OF MOVEMENT OF BUTTERFLY ASSEMBLY.							Service	ATA:21
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							

PKG:14

PROC. REF: AMM 21-20-03, AMM 21-20-09PROC. REF: AMM 21-20-03, AMM 21-20-09

Y2150058 ^S	PERFORM VISUAL INSPECTION OF AIR CONDITIONING SYSTEM COMPONENTS, INCLUDING COMPRESSOR MOTOR BELT FOR WEAR AND PROPER V-BELT TENSION, CONDENSER COILS FOR CLEANLINESS AND HOSES FOR CHAFING AND WEAR. IF OIL LEAKS ARE VISIBLE AND/OR REFRIGERANT DUMPED, CHECK COMPRESSOR OIL LEVEL. SOME LEAKAGE IS ALLOWABLE AROUND SHAFT.							Service	ATA:21
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							

PKG:14

PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00

Y2150059 ^S	AIR CONDITIONING SYSTEM - PERFORM LOAD SHED ASSEMBLY CHECK							Service	ATA:21
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							

PKG:14

PROC. REF: AMM 21-51-00PROC. REF: AMM 21-51-00

ATA 22 - AUTO FLIGHT

2210-RVSM	FLIGHT CHECK AUTOMATIC ALTITUDE HOLD FUNCTIONAL. RVSM COMPLIANT AIRCRAFT.							Service	ATA:22
	MOS/MSC	09-Mar-01	N/R						
	HRS	0							
	AFL	0							

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 22 - AUTO FLIGHT										
221001		AUTOPILOT FLIGHT GUIDANCE CONTROLLER						Component	ATA:22	
PN:7021170-901	MOS/MSC	25-Jan-19	O/C							
SN:05111601	HRS	8026.4								
	AFL	6168								
PROC. REF: AMM 22-10-01PROC. REF: AMM 22-10-01										
221041		AUTOPILOT ROLL SERVO						Component	ATA:22	
PN:PN 4006719-948	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 22-10-04PROC. REF: AMM 22-10-04										
221045		AUTOPILOT ROLL SERVO BRACKET						Component	ATA:22	
PN:PN 4005842	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 22-10-05PROC. REF: AMM 22-10-05										
221051		AUTOPILOT PITCH SERVO						Component	ATA:22	
PN:PN 4006719-908	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 22-10-02PROC. REF: AMM 22-10-02										
221055		AUTOPILOT PITCH SERVO BRACKET						Component	ATA:22	
PN:PN 4005842	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 22-10-03PROC. REF: AMM 22-10-03										
221061		AUTOPILOT YAW SERVO						Component	ATA:22	
PN:PN 7012919-903	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 22-10-06PROC. REF: AMM 22-10-06										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 22 - AUTO FLIGHT										
221065		AUTOPILOT YAW SERVO BRACKET						Component	ATA:22	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 22-10-07PROC. REF: AMM 22-10-07										
225001		YAW INTERFACE UNIT						Component	ATA:22	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 22-50-01PROC. REF: AMM 22-50-01										
225031		PILOT RUDDER BOOST SYSTEM YAW FORCE SENSOR						Component	ATA:22	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 22-50-02PROC. REF: AMM 22-50-02										
225032		COPILOT RUDDER BOOST SYSTEM YAW FORCE SENSOR						Component	ATA:22	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 22-50-02PROC. REF: AMM 22-50-02										
A2210033 ^S		** AUTOPILOT SYSTEM - PERFORM AUTOPILOT DISCONNECT TONE TEST						Service	ATA:22	
	MOS	02-Aug-24	24			AIRWORTHINESS				
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 22-10-00PROC. REF: AMM 22-10-00										
G2210030 ^S		PITCH SERVO CABLES - PERFORM CABLE TENSION CHECK						Service	ATA:22	
	MOS	09-Mar-01	48							
	HRS	0	1200							
	AFL	0								
PROC. REF: AMM 22-10-03PROC. REF: AMM 22-10-03										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 22 - AUTO FLIGHT

G2210031 ^S		ROLL SERVO CABLES - PERFORM CABLE TENSION CHECK						Service	ATA:22
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PKG:13									
PROC. REF: AMM 22-10-05PROC. REF: AMM 22-10-05									

G2210032 ^S		YAW SERVO CABLES - PERFORM CABLE TENSION CHECK						Service	ATA:22
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PKG:14									
PROC. REF: AMM 22-10-07PROC. REF: AMM 22-10-07									

ATA 23 - COMMUNICATIONS

230001		UNILINK PROCESSOR					Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN	0			
SN:UNKNOWN	HRS	0		TSN	0			
	AFL	0		TSN	0			
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

230002		CONFIGURATION MODULE					Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN	0			
SN:UNKNOWN	HRS	0		TSN	0			
	AFL	0		TSN	0			
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

231011		NO. 1 POWER AMPLIFIER/HF ANTENNA COUPLER					Component	ATA:23
PN:064-1017-01	MOS/MSC	12-Feb-08	O/C					
SN:17280	HRS	5965.9						
	AFL	4561						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

231012		NO. 2 POWER AMPLIFIER/HF ANTENNA COUPLER					Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN	0			
SN:UNKNOWN	HRS	0		TSN	0			
	AFL	0		TSN	0			

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 23 - COMMUNICATIONS

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

231021	NO. 1 VHF COMMUNICATIONS TRANSCEIVER UNIT							Component	ATA:23
PN:7510733-616	MOS/MSC	11-May-18	O/C						
SN:98093272	HRS	7850.8							
	AFL	6024							
PROC. REF: AMM 23-11-01PROC. REF: AMM 23-11-01									

231021A	TEST/INSPECT NO. 1 ATC TRANSPONDER							Service	ATA:23
PN:7510733-616	MOS	10-Aug-24	24		10-Aug-26		179 d		
SN:98093272	HRS								
	AFL								
Calibration Date: : 10-Aug-24									
PROC. REF: AMM 23-11-00, FAR FAR 91.413PROC. REF: AMM 23-11-00, FAR FAR 91.413									

231022	NO. 2 VHF COMMUNICATIONS TRANSCEIVER UNIT							Component	ATA:23
PN:7510733-616	MOS/MSC	13-Apr-17	O/C						
SN:99054063	HRS	7744.3							
	AFL	5922							
PROC. REF: AMM 23-11-01, FAR FAR 91.413PROC. REF: AMM 23-11-01, FAR FAR 91.413									

231022A	TEST/INSPECT NO. 2 ATC TRANSPONDER							Service	ATA:23
PN:7510733-616	MOS	10-Aug-24	24		10-Aug-26		179 d		
SN:99054063	HRS								
	AFL								
Calibration Date: : 10-Aug-24									
PROC. REF: AMM 23-11-00, FAR FAR 91.413PROC. REF: AMM 23-11-00, FAR FAR 91.413									

231030	NO. 1 HF SELECTIVE CALLING (SELCAL) RECEIVER/EXCITER							Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 23 - COMMUNICATIONS										
231031	NO. 2 HF SELECTIVE CALLING (SELCAL) RECEIVER/EXCITER								Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
231032	HF SELECTIVE CALLING (SELCAL) ANTENNA								Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
231033	UPPER VHF ANTENNA								Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-11-02PROC. REF: AMM 23-11-02										
231034	LOWER VHF ANTENNA								Component	ATA:23
PN:DMC60-17-1	MOS/MSC	16-Jul-19	O/C	TSN 0						
SN:18936	HRS	8109		TSN 0						
	AFL	6239		TSN 0						
PROC. REF: AMM 23-11-02PROC. REF: AMM 23-11-02										
231045	NO. 1 HF CONTROL (MODEL KCU-951)								Component	ATA:23
PN:064-1016-03	MOS/MSC	25-Feb-08	O/C							
SN:11903	HRS	5974.6								
	AFL	4566								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
231046	NO. 2 HF CONTROL (MODEL KCU-951)								Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 23 - COMMUNICATIONS										
231051	NO. 1 HF BRIDGING AMPLIFIER								Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
<hr/>										
231052	NO. 2 HF BRIDGING AMPLIFIER								Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
<hr/>										
231090	PILOT HEADSET								Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
<hr/>										
231091	COPILOT HEADSET								Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
<hr/>										
231300	MAGNASTAR PHONE TRANSCEIVER								Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
<hr/>										
231305	MAGNASTAR ANTENNA								Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 23 - COMMUNICATIONS										
231307		COCKPIT PHONE						Component		ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
231308		CABIN PHONE						Component		ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
231310		ARTU TRAY						Component		ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
231313		NO. 1 CABIN DISTRIBUTION BUS REPEATER						Component		ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
231314		NO. 2 CABIN DISTRIBUTION BUS REPEATER						Component		ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
231315		CALL ALERTER SWITCH (CAS)						Component		ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 23 - COMMUNICATIONS										
231320		NO. 1 CABIN IRIDIUM SATCOM HANDSET						Component	ATA:23	
PN:P12248-003	MOS/MSC	12-Feb-08	O/C	TSN 0						
SN:UNKNOWN	HRS	5965.9		TSN 0						
	AFL	4561		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
231321		NO. 2 CABIN IRIDIUM SATCOM HANDSET						Component	ATA:23	
PN:P12192-002	MOS/MSC	12-Feb-08	O/C	TSN 0						
SN:UNKNOWN	HRS	5965.9		TSN 0						
	AFL	4561		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
231322		CABIN IRIDIUM SATCOM PHONE CRADLE						Component	ATA:23	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
231323		IRIDIUM SATCOM TRANSCEIVER						Component	ATA:23	
PN:P12023	MOS/MSC	12-Feb-08	O/C							
SN:1202310876	HRS	5965.9								
	AFL	4561								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
231325		IRIDIUM SATCOM SONALERT						Component	ATA:23	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
231327		COCKPIT IRIDIUM SATCOM PHONE CRADLE						Component	ATA:23	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 23 - COMMUNICATIONS										
231328		COCKPIT IRIDIUM SATCOM HANDSET						Component	ATA:23	
PN:P12192-002	MOS/MSC	12-Feb-08	O/C	TSN 0						
SN:UNKNOWN	HRS	5965.9		TSN 0						
	AFL	4561		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
231330		FORWARD IRIDIUM SATCOM ANTENNA						Component	ATA:23	
PN:S67-1575-165	MOS/MSC	12-Feb-08	O/C							
SN:449-2303	HRS	5965.9								
	AFL	4561								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
231335		COCKPIT IRIDIUM SATCOM BASE UNIT						Component	ATA:23	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
233001		FORWARD CABIN VIDEO MONITOR						Component	ATA:23	
PN:AL-LCD104-04-1	MOS/MSC	06-Aug-06	O/C							
SN:120000638	HRS	4725.85								
	AFL	3628								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
233002		AFT CABIN VIDEO MONITOR						Component	ATA:23	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
233003		AUDIO DISTRIBUTION MODULE						Component	ATA:23	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 23 - COMMUNICATIONS										
233005		PUBLIC ADDRESS SYSTEM AMPLIFER						Component	ATA:23	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 23-30-02PROC. REF: AMM 23-30-02										
233010		INFRARED REMOTE RECEIVER MODULE						Component	ATA:23	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
233015		AUDIO/VIDEO CONTROLLER						Component	ATA:23	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
233053		DVD PLAYER						Component	ATA:23	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
233054		CD PLAYER CHANGER						Component	ATA:23	
PN:MCD-102-RU-3	MOS/MSC	21-Jun-05	O/C							
SN:060101192	HRS	3694.5								
	AFL	2785								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
233055		CD PLAYER CONTROL UNIT						Component	ATA:23	
PN:MCD-102-CH-1	MOS/MSC	22-May-06	O/C							
SN:100000353	HRS	4507.7								
	AFL	3441								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 23 - COMMUNICATIONS										
233056	CASSETTE TAPE PLAYER								Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
<hr/>										
233101	LEFT FORWARD CABIN SPEAKER								Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-30-01PROC. REF: AMM 23-30-01										
<hr/>										
233102	RIGHT FORWARD CABIN SPEAKER								Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-30-01PROC. REF: AMM 23-30-01										
<hr/>										
233103	LEFT AFT CABIN SPEAKER								Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-30-01PROC. REF: AMM 23-30-01										
<hr/>										
233104	RIGHT AFT CABIN SPEAKER								Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-30-01PROC. REF: AMM 23-30-01										
<hr/>										
233105	SUBWOOFER SPEAKER								Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 23 - COMMUNICATIONS										
233201	PASSENGER INTERFACE UNIT								Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
<hr/>										
234000	INTERPHONE JACK BOX ASSEMBLY								Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
<hr/>										
235001	NO. 1 AUDIO CONTROL UNIT								Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-50-01PROC. REF: AMM 23-50-01										
<hr/>										
235002	NO. 2 AUDIO CONTROL UNIT								Component	ATA:23
PN:7511001-937	MOS/MSC	12-Sep-22	O/C							
SN:04049325	HRS	9101.8								
	AFL	6994								
PROC. REF: AMM 23-50-01PROC. REF: AMM 23-50-01										
<hr/>										
235013	LEFT COCKPIT SPEAKER								Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-50-03PROC. REF: AMM 23-50-03										
<hr/>										
235014	RIGHT COCKPIT SPEAKER								Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-50-03PROC. REF: AMM 23-50-03										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 23 - COMMUNICATIONS										
236005		XM RADIO WEATHER RECEIVER						Component	ATA:23	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
236010		XM RADIO WEATHER DATA PORT						Component	ATA:23	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
236015		XM RADIO ANTENNA						Component	ATA:23	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
236096		NO. 1 NAVIGATION STRAP BOARD						Component	ATA:23	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 34-51-05PROC. REF: AMM 34-51-05										
236097		NO. 2 NAVIGATION STRAP BOARD						Component	ATA:23	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 34-51-05PROC. REF: AMM 34-51-05										
236098		NO. 1 COMMUNICATION STRAP BOARD						Component	ATA:23	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 23-11-03PROC. REF: AMM 23-11-03										

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 23 - COMMUNICATIONS										
236099		NO. 2 COMMUNICATION STRAP BOARD						Component	ATA:23	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-11-03PROC. REF: AMM 23-11-03										
237001		COCKPIT VOICE RECORDER (CVR)						Component	ATA:23	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-70-01PROC. REF: AMM 23-70-01										
237005		COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON (CVR ULB)						Component	ATA:23	
PN:DK120	MOS/MSC	02-Aug-24	O/C	TSN 0						
SN:NT60040	HRS	9525.7		TSN 0						
	AFL	7276		TSN 0						
PROC. REF: AMM 25-61-01PROC. REF: AMM 25-61-01										
237018		COCKPIT VOICE RECORDER (CVR) INERTIA SWITCH						Component	ATA:23	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-70-05PROC. REF: AMM 23-70-05										
237019		COCKPIT AREA MICROPHONE						Component	ATA:23	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
237030		PANEL SWITCH						Component	ATA:23	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 23 - COMMUNICATIONS										
237031		COCKPIT VOICE RECORDER PRE-AMPLIFIER						Component	ATA:23	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 23-70-03PROC. REF: AMM 23-70-03										
238001		NO. 1 RADIO MANAGEMENT UNIT (RMU)						Component	ATA:23	
PN:7013270-985	MOS/MSC	04-May-18	O/C							
SN:06125540	HRS	7849.4								
	AFL	6022								
PROC. REF: AMM 23-80-01PROC. REF: AMM 23-80-01										
238002		NO. 2 RADIO MANAGEMENT UNIT (RMU)						Component	ATA:23	
PN:7013270-985	MOS/MSC	16-Mar-18	O/C							
SN:1248264	HRS	7800.1								
	AFL	5976								
PROC. REF: AMM 23-80-01PROC. REF: AMM 23-80-01										
238025		CLEARANCE DELIVERY UNIT						Component	ATA:23	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 23-82-01PROC. REF: AMM 23-82-01										
239004		MASTER CONTROL SWITCH						Component	ATA:23	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
239011		LAVATORY MASTER CONTROL SWITCH						Component	ATA:23	
PN:8500-000077-6767	MOS/MSC	03-Mar-06	O/C							
SN:0123	HRS	4328.77								
	AFL	3297								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 23 - COMMUNICATIONS

A2300000 ^S		** COMMUNICATION SYSTEMS - PERFORM OPERATIONAL CHECK						Service	ATA:23
	MOS	02-Aug-24	24					AIRWORTHINESS	
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 23-00-00PROC. REF: AMM 23-00-00									

PKG:7

V2312003 ^S		HF ANTENNA - PERFORM VISUAL INSPECTION. CHECK FOR PROPER TENSION OF HF ANTENNA WIRE.						Service	ATA:23
	MOS	12-Aug-15	48						
	HRS	7535.1	1200						
	AFL	5764							
PROC. REF: AMM 23-12-04PROC. REF: AMM 23-12-04									

PKG:14

Y2360020 ^S		AIRCRAFT STATIC DISCHARGERS - PERFORM FUNCTIONAL TEST						Service	ATA:23
	MOS	25-Nov-19	96						
	HRS	8177.7	2400						
	AFL	6303							
PROC. REF: AMM 23-60-00PROC. REF: AMM 23-60-00									

PKG:20

Y2360023 ^S		AIRCRAFT STATIC DISCHARGERS - PERFORM FUNCTIONAL TEST						Service	ATA:23
	MOS	25-Nov-19	96						
	HRS	8177.7	2400						
	AFL	6303							
PROC. REF: AMM 23-60-00PROC. REF: AMM 23-60-00									

PKG:22

ATA 24 - ELECTRICAL POWER

240109		AFT CIRCUIT BREAKER PANEL						Component	ATA:24
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN	0				
SN:UNKNOWN	HRS	0		TSN	0				
	AFL	0		TSN	0				
PROC. REF: AMM 24-60-04PROC. REF: AMM 24-60-04									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 24 - ELECTRICAL POWER										
242000		NO. 1 ALTERNATOR						Component	ATA:24	
PN:90278-2	MOS/MSC	14-Feb-24	O/C	TSO 0						
SN:651	HRS	9467.2		TSO 0						
	AFL	7246		TSO 0						
PROC. REF: AMM 24-20-01PROC. REF: AMM 24-20-01										
242001		NO. 2 ALTERNATOR						Component	ATA:24	
PN:90278-2	MOS/MSC	19-May-22	O/C	TSO 0						
SN:1488	HRS	8995.3		TSO 0						
	AFL	6902		TSO 0						
PROC. REF: AMM 24-20-01PROC. REF: AMM 24-20-01										
242008		AC/DC VOLT INDICATOR						Component	ATA:24	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
242050		NO. 1 REMOTE CONTROL CIRCUIT BREAKER						Component	ATA:24	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 24-60-01PROC. REF: AMM 24-60-01										
242052		NO. 2 REMOTE CONTROL CIRCUIT BREAKER						Component	ATA:24	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 24-60-01PROC. REF: AMM 24-60-01										
242054		NO. 3 REMOTE CONTROL CIRCUIT BREAKER						Component	ATA:24	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 24-60-01PROC. REF: AMM 24-60-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 24 - ELECTRICAL POWER										
242081	CABIN ELECTRICAL INVERTER								Component	ATA:24
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
242082	TAILCONE ELECTRICAL INVERTER								Component	ATA:24
PN:PN	MOS/MSC	09-Mar-01	A/R	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
242083	ELECTRICAL INVERTER								Component	ATA:24
PN:SS120(C)	MOS/MSC	23-Jul-13	A/R							
SN:320	HRS	7175.4								
	AFL	5474								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
243001	NO. 1 STARTER/GENERATOR								Component	ATA:24
PN:23280-067	MOS/MSC	27-Oct-25	O/C	TSO 0						
SN:Y01027	HRS	9906.2		TSO 0						
	AFL	7538		TSO 0						
PROC. REF: AMM 24-30-01PROC. REF: AMM 24-30-01										
243002	NO. 2 STARTER/GENERATOR								Component	ATA:24
PN:23280-067	MOS/MSC	02-Aug-24	O/C	TSO 0						
SN:P1484LA	HRS	9525.7		TSO 0						
	AFL	7276		TSO 0						
PROC. REF: AMM 24-30-01PROC. REF: AMM 24-30-01										
243003	APU STARTER/GENERATOR								Component	ATA:24
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 49-40-01PROC. REF: AMM 49-40-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 24 - ELECTRICAL POWER									
243005 LEFT GENERATOR CONTROL UNIT (GCU)									Component ATA:24
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
243006 RIGHT GENERATOR CONTROL UNIT (GCU)									Component ATA:24
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
243019 NO. 1 MAIN BATTERY									Component ATA:24
PN:RG-380E/40L	MOS/MSC	02-Aug-24	O/C						
SN:41180857	HRS	9525.7							
	AFL	7276							
PROC. REF: AMM 24-31-01, AMM 24-31-06, CMM 24-30-71PROC. REF: AMM 24-31-01, AMM 24-31-06, CMM 24-30-71									
243020 NO. 2 MAIN BATTERY									Component ATA:24
PN:RG-380E/40L	MOS/MSC	02-Aug-24	O/C	TSN 34					
SN:41180858	HRS	9525.7		TSN 762.4					
	AFL	7276		TSN 532					
PROC. REF: AMM 24-31-01, AMM 24-31-06, CMM 24-30-71PROC. REF: AMM 24-31-01, AMM 24-31-06, CMM 24-30-71									
243037 EMERGENCY BATTERY									Component ATA:24
PN:RG-443	MOS/MSC	27-Oct-25	H/T	TSN 0					
SN:41475046	HRS	9906.2		TSN 0					
	AFL	7538		TSN 0					
PROC. REF: AMM 24-32-01, CMM 24-30-67PROC. REF: AMM 24-32-01, CMM 24-30-67									
246001 LEFT FORWARD POWER DISTRIBUTION PANEL									Component ATA:24
PN:650GC02Y03	MOS/MSC	21-Jun-18	O/C						
SN:575	HRS	7887.8							
	AFL	6051							
PROC. REF: AMM 24-60-02PROC. REF: AMM 24-60-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 24 - ELECTRICAL POWER									
246002 RIGHT FORWARD POWER DISTRIBUTION PANEL									Component ATA:24
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 24-60-02PROC. REF: AMM 24-60-02									
246003 LEFT AFT POWER DISTRIBUTION PANEL									Component ATA:24
PN:660GC02Y07	MOS/MSC	30-Jan-11	O/C						
SN:588	HRS	6501.3							
	AFL	4977							
PROC. REF: AMM 24-60-03PROC. REF: AMM 24-60-03									
246004 RIGHT AFT POWER DISTRIBUTION PANEL									Component ATA:24
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 24-60-03PROC. REF: AMM 24-60-03									
246101 LEFT GENERATOR CONTROL UNIT PRINTED CIRCUIT BOARD									Component ATA:24
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
246102 LEFT LOGIC PRINTED CIRCUIT BOARD									Component ATA:24
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
246104 RIGHT GENERATOR CONTROL UNIT PRINTED CIRCUIT BOARD									Component ATA:24
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 24 - ELECTRICAL POWER										
246105	RIGHT LOGIC PRINTED CIRCUIT BOARD								Component	ATA:24
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
246106	APU GENERATOR CONTROL UNIT PRINTED CIRCUIT BOARD								Component	ATA:24
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
AB2431062	EMERGENCY BATTERY - PERFORM CAPACITY CHECK								Service	ATA:24
PN:RG-443	MOS	27-Oct-25	12	27-Oct-26		257 d				
SN:41475046	HRS	9906.2	1000	10906.2		883.1				
	AFL	7538								
AB2431063	EMERGENCY BATTERY - REPLACE								Service	ATA:24
PN:RG-443	MOS	27-Oct-25	48	27-Oct-29		1353 d		LIFE LIMIT		
SN:41475046	HRS	9906.2								
	AFL	7538								
AC2460002 ^S	REMOVE ATTACHING PARTS SECURING CIRCUIT BREAKER PANEL TO STRUCTURE. CHECK FOR LOOSE CIRCUIT BREAKER TERMINALS, LOOSE WIRE TERMINALS, CORRODED TERMINALS OR BUS BARS, AND EVIDENCE OF WIRE INSULATION DAMAGE.								Service	ATA:24
	MOS	09-Mar-01	96							
	HRS	0	2400							
	AFL	0								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
B2450002 ^S	** ELECTRICAL SYSTEM CONTROL - PERFORM OPERATIONAL CHECK								Service	ATA:24
	MOS	09-Mar-01	48			AIRWORTHINESS				
	HRS	0	1200							
	AFL	0								
PROC. REF: AMM 24-00-00PROC. REF: AMM 24-00-00										

PKG:19

PKG:13

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 24 - ELECTRICAL POWER

F2420000 ** NO. 1 ALTERNATOR - PERFORM BEARING REPLACEMENT Service ATA:24									
PN:90278-2	MOS		14-Feb-24					AIRWORTHINESS	
SN:651	HRS		9467.2	1200			644.1		
	AFL		7246						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

F2420000 ** NO. 2 ALTERNATOR - PERFORM BEARING REPLACEMENT Service ATA:24									
PN:90278-2	MOS		19-May-22					AIRWORTHINESS	
SN:1488	HRS		8995.3	1200			172.2		
	AFL		6902						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

H2450001 ^S ** AUXILIARY POWER SUPPLIES - PERFORM FUNCTIONAL TEST Service ATA:24									
	MOS		02-Aug-24	24				AIRWORTHINESS	
	HRS		9525.7	600					
	AFL		7276						
PROC. REF: AMM 24-00-00PROC. REF: AMM 24-00-00									

PKG:7

H2450023 ^S ** EMER BATT LOW AND GEN AMPS HIGH INDICATION - PERFORM OPERATIONAL CHECK Service ATA:24									
	MOS		02-Aug-24	24				AIRWORTHINESS	
	HRS		9525.7	600					
	AFL		7276						
PROC. REF: AMM 24-00-00PROC. REF: AMM 24-00-00									

PKG:7

O2431002 EMERGENCY BATTERY - PERFORM CAPACITY CHECK Service ATA:24									
PN:RG-443	MOS/MSC		27-Oct-25	N/A					
SN:41475046	HRS		9906.2						
	AFL		7538						
PROC. REF: CMM 24-30-67PROC. REF: CMM 24-30-67									

P2430003 NO. 1 STARTER/GENERATOR - PERFORM OVERHAUL Service ATA:24									
PN:23280-067	MOS		27-Oct-25						
SN:Y01027	HRS		9906.2	1200			1083.1		
	AFL		7538						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 24 - ELECTRICAL POWER

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

P2430003	NO. 2 STARTER/GENERATOR - PERFORM OVERHAUL							Service	ATA:24
-----------------	---	--	--	--	--	--	--	----------------	---------------

PN:23280-067	MOS	02-Aug-24							
--------------	-----	-----------	--	--	--	--	--	--	--

SN:P1484LA	HRS	9525.7	1200		10725.7		702.6		
------------	-----	--------	------	--	---------	--	-------	--	--

	AFL	7276							
--	-----	------	--	--	--	--	--	--	--

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

P2430007	NO. 1 STARTER/GENERATOR - REPLACE BEARINGS							Service	ATA:24
-----------------	---	--	--	--	--	--	--	----------------	---------------

PN:23280-067	MOS/MSC	27-Oct-25	N/A						
--------------	---------	-----------	-----	--	--	--	--	--	--

SN:Y01027	HRS	9906.2							
-----------	-----	--------	--	--	--	--	--	--	--

	AFL	7538							
--	-----	------	--	--	--	--	--	--	--

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

P2430007	NO. 2 STARTER/GENERATOR - REPLACE BEARINGS							Service	ATA:24
-----------------	---	--	--	--	--	--	--	----------------	---------------

PN:23280-067	MOS/MSC	02-Aug-24	N/A						
--------------	---------	-----------	-----	--	--	--	--	--	--

SN:P1484LA	HRS	9525.7							
------------	-----	--------	--	--	--	--	--	--	--

	AFL	7276							
--	-----	------	--	--	--	--	--	--	--

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

Q2460001 ^S	** POWER DISTRIBUTION SYSTEM - PERFORM SQUAT SWITCH CHECK							Service	ATA:24
------------------------------	--	--	--	--	--	--	--	----------------	---------------

	MOS	09-Mar-01	48					AIRWORTHINESS	
--	-----	-----------	----	--	--	--	--	----------------------	--

	HRS	0	1200						
--	-----	---	------	--	--	--	--	--	--

	AFL	0							
--	-----	---	--	--	--	--	--	--	--

PKG:17

PROC. REF: AMM 24-60-00PROC. REF: AMM 24-60-00

R2431003 ^S	** BATTERY WARNING SYSTEM - PERFORM FUNCTIONAL TEST							Service	ATA:24
------------------------------	--	--	--	--	--	--	--	----------------	---------------

	MOS	09-Mar-01	96					AIRWORTHINESS	
--	-----	-----------	----	--	--	--	--	----------------------	--

	HRS	0	2400						
--	-----	---	------	--	--	--	--	--	--

	AFL	0							
--	-----	---	--	--	--	--	--	--	--

PKG:19

PROC. REF: AMM 24-31-00PROC. REF: AMM 24-31-00

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 24 - ELECTRICAL POWER										
W2450000 ^S			** GENERATOR FAIL INDICATION - PERFORM OPERATIONAL CHECK						Service	ATA:24
	MOS	02-Aug-24	24					AIRWORTHINESS		
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 24-00-00PROC. REF: AMM 24-00-00										
ATA 24 - ELECTRICAL POWER										
Y2400001 ^S			SWITCH AND CIRCUIT BREAKER PANELS - PERFORM VISUAL INSPECTION						Service	ATA:24
	MOS	09-Mar-01	48							
	HRS	0	1200							
	AFL	0								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
ATA 24 - ELECTRICAL POWER										
Y2400002 ^S			ELECTRICAL WIRING - PERFORM VISUAL INSPECTION FOR ROUTING, SECURITY, CLEARANCES, CHAFING, AND ELECTRICAL COMPONENTS FOR SECURITY AND GENERAL CONDITION.						Service	ATA:24
	MOS	02-Aug-24	24							
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
ATA 24 - ELECTRICAL POWER										
Y2400025 ^S			ELECTRICAL WIRING - PERFORM VISUAL INSPECTION FOR ROUTING, SECURITY, CLEARANCES, CHAFING, AND ELECTRICAL COMPONENTS FOR SECURITY AND GENERAL CONDITION.						Service	ATA:24
	MOS	02-Aug-24	24							
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
ATA 24 - ELECTRICAL POWER										
Y2430005 ^S			STARTER/GENERATOR - PERFORM GROUNDING LUG BONDING CHECK						Service	ATA:24
	MOS	02-Aug-24	24							
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 24-30-01PROC. REF: AMM 24-30-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 24 - ELECTRICAL POWER

Y2430006 ^S	STARTER/GENERATOR - PERFORM VISUAL INSPECTION OF GROUNDING LUGS							Service	ATA:24
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PKG:9									
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									

Y2431000 ^S	BATTERY, GENERATOR, AND BUS-TIE CABLES - PERFORM VISUAL INSPECTION							Service	ATA:24
	MOS	25-Nov-19	96						
	HRS	8177.7	2400						
	AFL	6303							
PKG:20									
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									

Y2431001 ^S	EMERGENCY BATTERY CABLES - PERFORM VISUAL INSPECTION							Service	ATA:24
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PKG:7									
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									

Y2431005	BATTERY CABLES AND RECEPTACLES - PERFORM BATTERY CONNECTOR TOLERANCE CHECK							Service	ATA:24
	MOS	21-Aug-25							
	HRS	9809.8	300		10109.8		86.7		
	AFL	7471							
PROC. REF: AMM 24-31-00PROC. REF: AMM 24-31-00									

Y2460000 ^S	DC BUS ISOLATION - PERFORM OPERATIONAL CHECK							Service	ATA:24
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PKG:13									
PROC. REF: AMM 24-60-00PROC. REF: AMM 24-60-00									

ATA 25 - EQUIPMENT/FURNISHINGS

250010	RELAY MODULE							Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
252000 JUMP SEAT Component ATA:25									
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
252000 NO. 1 PASSENGER SEAT Component ATA:25									
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45									
252000 NO. 2 PASSENGER SEAT Component ATA:25									
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45									
252000 NO. 3 PASSENGER SEAT Component ATA:25									
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45									
252000 NO. 4 PASSENGER SEAT Component ATA:25									
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 25 - EQUIPMENT/FURNISHINGS										
252000	NO. 5 PASSENGER SEAT								Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45										
252000	NO. 6 PASSENGER SEAT								Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45										
252000	NO. 7 PASSENGER SEAT								Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45										
252000	NO. 8 PASSENGER SEAT								Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45										
252001	LAVATORY PCU								Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	A/R	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
252001	NO. 1 PASSENGER SEAT PCU								Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 25 - EQUIPMENT/FURNISHINGS										
252001	NO. 2 PASSENGER SEAT PCU								Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45										
252001	NO. 3 PASSENGER SEAT PCU								Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45										
252001	NO. 4 PASSENGER SEAT PCU								Component	ATA:25
PN:SP-45-07A	MOS/MSC	05-Apr-06	O/C							
SN:020600592	HRS	4422.47								
	AFL	3369								
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45										
252001	NO. 5 PASSENGER SEAT PCU								Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45										
252001	NO. 6 PASSENGER SEAT PCU								Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45										
252001	NO. 7 PASSENGER SEAT PCU								Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 25 - EQUIPMENT/FURNISHINGS										
252001	NO. 8 PASSENGER SEAT PCU								Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45										
252010	AIRSHOW COMPUTER								Component	ATA:25
PN:920040	MOS/MSC	06-Mar-09	O/C							
SN:452	HRS	6115.4								
	AFL									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
252020	CLOSET SWITCH PANEL ASSEMBLY								Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
252090	NO. 1 110 VOLT POWER OUTLET								Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
252091	NO. 2 110 VOLT POWER OUTLET								Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
252092	NO. 3 110 VOLT POWER OUTLET								Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 25 - EQUIPMENT/FURNISHINGS										
252095	NO. 4 110 VOLT POWER OUTLET								Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
<hr/>										
252097	NO. 1 AC POWER OUTLET								Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
<hr/>										
252098	NO. 2 AC POWER OUTLET								Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
<hr/>										
252099	NO. 3 AC POWER OUTLET								Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
<hr/>										
253001	MICROWAVE OVEN								Component	ATA:25
PN:255A-LH28-115	MOS/MSC	28-Jul-05	O/C							
SN:19976	HRS	3775.77								
	AFL	2849								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
<hr/>										
253075	NO. 1 HEATED WATER CONTAINER								Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 25 - EQUIPMENT/FURNISHINGS										
253076		NO. 2 HEATED WATER CONTAINER						Component	ATA:25	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
253077		HEATED WATER SWITCH						Component	ATA:25	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
253080		GALLEY DRAIN VALVE SOLENOID						Component	ATA:25	
PN:8210G94-24DC	MOS/MSC	03-Jan-06	O/C							
SN:T116684	HRS	4160.77								
	AFL	3151								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
256001		PILOT CREW SEAT						Component	ATA:25	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-10-50PROC. REF: AMM 25-10-50										
256002		COPILOT CREW SEAT						Component	ATA:25	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-10-50PROC. REF: AMM 25-10-50										
256061		PILOTS LIFE VEST						Component	ATA:25	
PN:P01074-101	MOS/MSC	09-Feb-21	O/C	TSN 0						
SN:20100400026	HRS	8401.3		TSN 0						
	AFL	6458		TSN 0						
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 25 - EQUIPMENT/FURNISHINGS										
256062		COPILOTS LIFE VEST						Component	ATA:25	
PN:P01074-101	MOS/MSC	09-Feb-21	O/C	TSN 0						
SN:20100400085	HRS	8401.3		TSN 0						
	AFL	6458		TSN 0						
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01										
256063		NO. 1 PASSENGER LIFE VEST						Component	ATA:25	
PN:P01074-101	MOS/MSC	09-Feb-21	O/C	TSN 0						
SN:20100400200	HRS	8401.3		TSN 0						
	AFL	6458		TSN 0						
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01										
256064		NO. 2 PASSENGER LIFE VEST						Component	ATA:25	
PN:P01074-101	MOS/MSC	09-Feb-21	O/C	TSN 0						
SN:20100400323	HRS	8401.3		TSN 0						
	AFL	6458		TSN 0						
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01										
256065		NO. 3 PASSENGER LIFE VEST						Component	ATA:25	
PN:P01074-101	MOS/MSC	09-Feb-21	O/C	TSN 0						
SN:20100400333	HRS	8401.3		TSN 0						
	AFL	6458		TSN 0						
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01										
256066		NO. 4 PASSENGER LIFE VEST						Component	ATA:25	
PN:P01074-101	MOS/MSC	09-Feb-21	O/C	TSN 0						
SN:20100400338	HRS	8401.3		TSN 0						
	AFL	6458		TSN 0						
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01										
256067		NO. 5 PASSENGER LIFE VEST						Component	ATA:25	
PN:P01074-101	MOS/MSC	09-Feb-21	O/C	TSN 0						
SN:20100400422	HRS	8401.3		TSN 0						
	AFL	6458		TSN 0						
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 25 - EQUIPMENT/FURNISHINGS										
256068	NO. 6 PASSENGER LIFE VEST								Component	ATA:25
PN:P01074-101	MOS/MSC	09-Feb-21	O/C	TSN 0						
SN:20100400432	HRS	8401.3		TSN 0						
	AFL	6458		TSN 0						
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01										
256069	NO. 7 PASSENGER LIFE VEST								Component	ATA:25
PN:P01074-101	MOS/MSC	09-Feb-21	O/C	TSN 0						
SN:20100400704	HRS	8401.3		TSN 0						
	AFL	6458		TSN 0						
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01										
256070	NO. 8 PASSENGER LIFE VEST								Component	ATA:25
PN:P01074-101	MOS/MSC	09-Feb-21	O/C	TSN 0						
SN:20100400721	HRS	8401.3		TSN 0						
	AFL	6458		TSN 0						
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01										
256071	LAVATORY LIFE VEST								Component	ATA:25
PN:P01074-101	MOS/MSC	09-Feb-21	O/C	TSN 0						
SN:20100400737	HRS	8401.3		TSN 0						
	AFL	6458		TSN 0						
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01										
256076	FIRST AID KIT								Component	ATA:25
PN:MSK70002	MOS/MSC	14-Jul-07	O/C							
SN:0602	HRS	5618.1								
	AFL	4293								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
256080	INSPECT LIFE VESTS								Service	ATA:25
	MOS/MSC	09-Mar-01	A/R							
	HRS	0								
	AFL	0								
PROC. REF: GENERIC NO REF, CMM 25-60-05PROC. REF: GENERIC NO REF, CMM 25-60-05										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
256109 (ELT) EMERGENCY LOCATOR TRANSMITTER									Component ATA:25
PN:453-5000	MOS/MSC	03-Feb-25	O/C	TSN 122					
SN:210-05727	HRS	9605.4		TSN 2171.2					
	AFL	7333		TSN 1646					
PROC. REF: AMM 25-62-01PROC. REF: AMM 25-62-01									
256109A (ELT) EMERGENCY LOCATOR TRANSMITTER - PERFORM NATIONALY REQUIRED FUNCTIONAL TEST									Service ATA:25
PN:453-5000	MOS	03-Feb-25	12		03-Feb-26		OVD		
SN:210-05727	HRS	9605.4							
	AFL	7333							
PROC. REF: AMM 25-62-00, FAR FAR 91.207PROC. REF: AMM 25-62-00, FAR FAR 91.207									
256109B (ELT) EMERGENCY LOCATOR TRANSMITTER - INSPECT ELT BATTERIES									Service ATA:25
PN:453-5000	MOS	03-Feb-25	12		03-Feb-26		OVD		
SN:210-05727	HRS	9605.4							
	AFL	7333							
PROC. REF: AMM 25-62-00, FAR FAR 91.207PROC. REF: AMM 25-62-00, FAR FAR 91.207									
256109C (ELT) EMERGENCY LOCATOR TRANSMITTER BATTERY - REPLACE									Service ATA:25
PN:453-5000	MOS	03-Feb-25	72		03-Feb-31		1817 d	LIFE LIMIT	
SN:210-05727	HRS	9605.4							
	AFL	7333							
PROC. REF: AMM 25-62-01, FAR FAR 91.207PROC. REF: AMM 25-62-01, FAR FAR 91.207									
256110 EMERGENCY LOCATOR TRANSMITTER (ELT)/NAVIGATION INTERFACE UNIT (C406-2)									Component ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
256115 EMERGENCY LOCATOR TRANSMITTER (ELT) ANTENNA									Component ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 25-62-03PROC. REF: AMM 25-62-03									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 25 - EQUIPMENT/FURNISHINGS										
256116		EMERGENCY LOCATOR TRANSMITTER (ELT) REMOTE SWITCH						Component	ATA:25	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-62-04PROC. REF: AMM 25-62-04										
258001		CABIN AIRSHOW DISPLAY COMPUTER UNIT						Component	ATA:25	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
259072		AUTOMATIC ELECTRONIC DEFIBRILLATOR (AED)						Component	ATA:25	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
259073		AUTOMATIC ELECTRONIC DEFIBRILLATOR (AED) BATTERIES						Component	ATA:25	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
259074		AUTOMATIC ELECTRONIC DEFIBRILLATOR (AED) ELECTRODE PADS						Component	ATA:25	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
AA2560000		COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON - CLEAN BEACON SWITCH, PERFORM FUNCTIONAL TEST OF BEACON, AND PERFORM TEST OF ULB BATTERY						Service	ATA:25	
PN:DK120	MOS	02-Aug-24	24	02-Aug-26			171 d			
SN:NT60040	HRS	9525.7								
	AFL	7276								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 25 - EQUIPMENT/FURNISHINGS

D2566001 COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON - REPLACE Service ATA:25									
PN:DK120	MOS/MSC	02-Aug-24	DUE		31-Mar-29 (M)		1143 d		
SN:NT60040	HRS	9525.7							
	AFL	7276							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

E2561002 COPILOTS LIFE VEST - PERFORM INSPECTION OF LIFE VESTS Service ATA:25									
PN:P01074-101	MOS	09-Feb-21	60		09-Feb-26		OVD		
SN:20100400085	HRS								
	AFL								
Inspection Date: : 09-Feb-21									
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01									

E2561002 LAVATORY LIFE VEST - PERFORM INSPECTION OF LIFE VESTS Service ATA:25									
PN:P01074-101	MOS	09-Feb-21	60		09-Feb-26		OVD		
SN:20100400737	HRS								
	AFL								
Inspection Date: : 09-Feb-21									
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01									

E2561002 NO. 1 PASSENGER LIFE VEST - PERFORM INSPECTION OF LIFE VESTS Service ATA:25									
PN:P01074-101	MOS	09-Feb-21	60		09-Feb-26		OVD		
SN:20100400200	HRS								
	AFL								
Inspection Date: : 09-Feb-21									
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01									

E2561002 NO. 2 PASSENGER LIFE VEST - PERFORM INSPECTION OF LIFE VESTS Service ATA:25									
PN:P01074-101	MOS	09-Feb-21	60		09-Feb-26		OVD		
SN:20100400323	HRS								
	AFL								
Inspection Date: : 09-Feb-21									
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
E2561002 NO. 3 PASSENGER LIFE VEST - PERFORM INSPECTION OF LIFE VESTS									Service ATA:25
PN:P01074-101	MOS	09-Feb-21	60		09-Feb-26		OVD		
SN:20100400333	HRS								
	AFL								
Inspection Date: : 09-Feb-21									
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01									
E2561002 NO. 4 PASSENGER LIFE VEST - PERFORM INSPECTION OF LIFE VESTS									Service ATA:25
PN:P01074-101	MOS	09-Feb-21	60		09-Feb-26		OVD		
SN:20100400338	HRS								
	AFL								
Inspection Date: : 09-Feb-21									
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01									
E2561002 NO. 5 PASSENGER LIFE VEST - PERFORM INSPECTION OF LIFE VESTS									Service ATA:25
PN:P01074-101	MOS	09-Feb-21	60		09-Feb-26		OVD		
SN:20100400422	HRS								
	AFL								
Inspection Date: : 09-Feb-21									
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01									
E2561002 NO. 6 PASSENGER LIFE VEST - PERFORM INSPECTION OF LIFE VESTS									Service ATA:25
PN:P01074-101	MOS	09-Feb-21	60		09-Feb-26		OVD		
SN:20100400432	HRS								
	AFL								
Inspection Date: : 09-Feb-21									
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01									
E2561002 NO. 7 PASSENGER LIFE VEST - PERFORM INSPECTION OF LIFE VESTS									Service ATA:25
PN:P01074-101	MOS	09-Feb-21	60		09-Feb-26		OVD		
SN:20100400704	HRS								
	AFL								
Inspection Date: : 09-Feb-21									
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01									

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 25 - EQUIPMENT/FURNISHINGS										
E2561002		NO. 8 PASSENGER LIFE VEST - PERFORM INSPECTION OF LIFE VESTS						Service	ATA:25	
PN:P01074-101	MOS	09-Feb-21	60		09-Feb-26		OVD			
SN:20100400721	HRS									
	AFL									
Inspection Date: : 09-Feb-21										
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01										
E2561002		PILOTS LIFE VEST - PERFORM INSPECTION OF LIFE VESTS						Service	ATA:25	
PN:P01074-101	MOS	09-Feb-21	60		09-Feb-26		OVD			
SN:20100400026	HRS									
	AFL									
Inspection Date: : 09-Feb-21										
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01										
Y2510000 ^S		GLARESHIELD, HEADLINER, AND TRIM STRIPS - PERFORM VISUAL INSPECTION						Service	ATA:25	
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PKG:1										
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
Y2510001 ^S		CREW SEATS AND SEAT BELTS - PERFORM VISUAL INSPECTION						Service	ATA:25	
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PKG:1										
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
Y2520000 ^S		CABIN - PERFORM VISUAL INSPECTION OF THE FOLLOWING: A. CABIN SEATS AND SEAT BELTS. ENSURE THAT THE SEATS FUNCTION CORRECTLY AND LOCK IN PLACE. B. STOWAGE CABINETS. C. HEADLINER. D. SIDE PANELS. E. RUG.						Service	ATA:25	
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PKG:1										
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 25 - EQUIPMENT/FURNISHINGS

Y2540000	^S	ALL LAVATORY PAPER AND LINEN WASTE RECEPTACLE ACCESS DOORS AND DISPOSAL DOORS FOR PROPER OPERATION, FIT, SEALING, LATCHING, AND LEGIBILITY OF PLACARD.						Service	ATA:25
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

PKG:7

Y2540009	^S	AVIONICS EQUIPMENT AND WIRING LOCATED IN LAVATORY AREA - PERFORM GENERAL VISUAL INSPECTION						Service	ATA:25
	MOS	09-Mar-01							
	HRS	0	4800						
	AFL	0							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									

PKG:25

ATA 26 - FIRE PROTECTION

261012	NO. 1 ENGINE FIREWALL FIRE DETECTION ELEMENT						Component	ATA:26
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN	0			
SN:UNKNOWN	HRS	0		TSN	0			
	AFL	0		TSN	0			
PROC. REF: AMM 26-11-02PROC. REF: AMM 26-11-02								

261013	NO. 2 ENGINE FIREWALL FIRE DETECTION ELEMENT						Component	ATA:26
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN	0			
SN:UNKNOWN	HRS	0		TSN	0			
	AFL	0		TSN	0			
PROC. REF: AMM 26-11-02PROC. REF: AMM 26-11-02								

261014	NO. 1 ENGINE ACCESSORY GEARBOX FIRE DETECTION ELEMENT						Component	ATA:26
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN	0			
SN:UNKNOWN	HRS	0		TSN	0			
	AFL	0		TSN	0			
PROC. REF: AMM 26-11-02PROC. REF: AMM 26-11-02								

261015	NO. 2 ENGINE ACCESSORY GEARBOX FIRE DETECTION ELEMENT						Component	ATA:26
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN	0			
SN:UNKNOWN	HRS	0		TSN	0			
	AFL	0		TSN	0			

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 26 - FIRE PROTECTION

PROC. REF: AMM 26-11-02PROC. REF: AMM 26-11-02

261016 NO. 1 ENGINE HOT SECTION FIRE DETECTION ELEMENT						Component	ATA:26
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0			
SN:UNKNOWN	HRS	0		TSN 0			
	AFL	0		TSN 0			
PROC. REF: AMM 26-11-02PROC. REF: AMM 26-11-02							

261017 NO. 2 ENGINE HOT SECTION FIRE DETECTION ELEMENT						Component	ATA:26
PN:744-12135	MOS/MSC	12-Aug-15	O/C				
SN:UNKNOWN	HRS	7535.1					
	AFL	5764					
PROC. REF: AMM 26-11-02PROC. REF: AMM 26-11-02							

261057 NO. 1 FIRE DETECT CONTROL UNIT						Component	ATA:26
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0			
SN:UNKNOWN	HRS	0		TSN 0			
	AFL	0		TSN 0			
PROC. REF: AMM 26-11-01PROC. REF: AMM 26-11-01							

261058 NO. 2 FIRE DETECT CONTROL UNIT						Component	ATA:26
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0			
SN:UNKNOWN	HRS	0		TSN 0			
	AFL	0		TSN 0			
PROC. REF: AMM 26-11-01PROC. REF: AMM 26-11-01							

261069 NO. 1 BLEED AIR LEAK DETECTION UNIT						Component	ATA:26
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0			
SN:UNKNOWN	HRS	0		TSN 0			
	AFL	0		TSN 0			
PROC. REF: AMM 26-12-01PROC. REF: AMM 26-12-01							

261070 NO. 2 BLEED AIR LEAK DETECTION UNIT						Component	ATA:26
PN:6626100000-003	MOS/MSC	18-Apr-12	O/C	TSN 0			
SN:2714	HRS	6879.9		TSN 0			
	AFL	5240		TSN 0			
PROC. REF: AMM 26-12-01PROC. REF: AMM 26-12-01							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 26 - FIRE PROTECTION										
261071		ANTI-ICE BLEED AIR LEAK DETECTION UNIT						Component	ATA:26	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 26-12-01PROC. REF: AMM 26-12-01										
261075		APU FIRE/OVERHEAT DETECTOR						Component	ATA:26	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 26-13-01PROC. REF: AMM 26-13-01										
262001		NO. 1/LEFT/LOWER FIRE EXTINGUISHER BOTTLE						Component	ATA:26	
PN:33100021-1	MOS/MSC	22-Jun-23	O/C	TSO 0						
SN:59578B1	HRS	9258.5		TSO 0						
	AFL	7100		TSO 0						
PROC. REF: AMM 26-21-01PROC. REF: AMM 26-21-01										
262002		NO. 2/RIGHT/UPPER FIRE EXTINGUISHER BOTTLE						Component	ATA:26	
PN:33100021-1	MOS/MSC	21-Aug-25	O/C	TSO 0						
SN:72043B1	HRS	9809.8		TSO 0						
	AFL	7471		TSO 0						
PROC. REF: AMM 26-21-01PROC. REF: AMM 26-21-01										
262013		NO. 1/LEFT/LOWER FIRE EXTINGUISHER, LEFT SQUIB						Component	ATA:26	
PN:30903856	MOS	06-Dec-18	180	TSN 5	01-Jul-33		2696 d			
SN:02254	HRS									
	AFL									
				Manufacture Date:: 01-Jul-18						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
262014		NO. 1/LEFT/LOWER FIRE EXTINGUISHER, RIGHT SQUIB						Component	ATA:26	
PN:30903859	MOS	06-Dec-18	180	TSN 5	01-Jul-33		2696 d			
SN:01619	HRS									
	AFL									
				Manufacture Date:: 01-Jul-18						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 26 - FIRE PROTECTION										
262015		NO. 2/RIGHT/UPPER FIRE EXTINGUISHER, LEFT SQUIB						Component	ATA:26	
PN:30903856	MOS	21-Aug-25	180	TSN 5	31-Mar-40		5161 d			
SN:03401	HRS									
	AFL									
Manufacture Date:: 31-Mar-25										
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
262016		NO. 2/RIGHT/UPPER FIRE EXTINGUISHER, RIGHT SQUIB						Component	ATA:26	
PN:30903859	MOS	21-Aug-25	180	TSN 5	31-Mar-40		5161 d			
SN:02408	HRS									
	AFL									
Manufacture Date:: 31-Mar-25										
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
262040		APU FIRE WARNING HORN						Component	ATA:26	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 26-13-02PROC. REF: AMM 26-13-02										
262041		PILOT PORTABLE FIRE EXTINGUISHER						Component	ATA:26	
PN:A344T	MOS/MSC	07-Dec-12	O/C							
SN:UNKNOWN	HRS	7016.8								
	AFL	5361								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
262042		COPILOT PORTABLE FIRE EXTINGUISHER						Component	ATA:26	
PN:A344	MOS/MSC	18-May-16	O/C	TSN 0						
SN:B10813738	HRS	7623.3		TSN 0						
	AFL	5813		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
262051		CABIN PORTABLE FIRE EXTINGUISHER						Component	ATA:26	
PN:C352	MOS/MSC	28-Dec-22	O/C	TSN 0						
SN:H-20651164	HRS	9186.7		TSN 0						
	AFL	7047		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 26 - FIRE PROTECTION										
D2620007.S		NO. 1/LEFT/LOWER FIRE EXTINGUISHER, LEFT SQUIB SERVICE LIFE LIMIT						Service	ATA:26	
PN:30903856	MOS	06-Dec-18	120		06-Dec-28		1028 d	SERVICE LIFE LIMIT		
SN:02254	HRS	0								
	AFL	0								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
D2620007.S		NO. 1/LEFT/LOWER FIRE EXTINGUISHER, RIGHT SQUIB SERVICE LIFE LIMIT						Service	ATA:26	
PN:30903859	MOS	06-Dec-18	120		06-Dec-28		1028 d	SERVICE LIFE LIMIT		
SN:01619	HRS	0								
	AFL	0								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
D2620007.S		NO. 2/RIGHT/UPPER FIRE EXTINGUISHER, LEFT SQUIB SERVICE LIFE LIMIT						Service	ATA:26	
PN:30903856	MOS	21-Aug-25	120		21-Aug-35		3477 d	SERVICE LIFE LIMIT		
SN:03401	HRS	0								
	AFL	0								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
D2620007.S		NO. 2/RIGHT/UPPER FIRE EXTINGUISHER, RIGHT SQUIB SERVICE LIFE LIMIT						Service	ATA:26	
PN:30903859	MOS	21-Aug-25	120		21-Aug-35		3477 d	SERVICE LIFE LIMIT		
SN:02408	HRS	0								
	AFL	0								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
J2620000 ^S	** ENGINE FIRE EXTINGUISHING SYSTEM FIRE SWITCH - PERFORM FUNCTIONAL TEST						Service	ATA:26		
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	4800							
	AFL	0								
PROC. REF: AMM 26-21-00PROC. REF: AMM 26-21-00										
O2610001	NO. 1 ENGINE HOT SECTION FIRE DETECTOR ELEMENT - PERFORM VISUAL INSPECTION						Service	ATA:26		
	MOS	21-May-18								
	HRS	7855.7	3000		10855.7		832.6			
	AFL	6028								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 26 - FIRE PROTECTION										
Q2610001	NO. 2 ENGINE HOT SECTION FIRE DETECTOR ELEMENT - PERFORM VISUAL INSPECTION								Service	ATA:26
	MOS	12-Aug-15								
	HRS	7535.1	3000		10535.1		512			
	AFL	5764								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
Q2510003	COPILOT PORTABLE FIRE EXTINGUISHER - PERFORM ICC HYDROSTATIC TEST								Service	ATA:26
PN:A344	MOS	01-Feb-16	144		01-Feb-28		719 d			
SN:B10813738	HRS									
	AFL									
HydroCheck Date: : 01-Feb-16										
PROC. REF: AMM 26-23-00PROC. REF: AMM 26-23-00										
Q2620006	NO. 1/LEFT/LOWER FIRE EXTINGUISHER BOTTLE - PERFORM ICC HYDROSTATIC TEST								Service	ATA:26
PN:33100021-1	MOS	31-May-23	60		31-May-28		839 d			
SN:59578B1	HRS									
	AFL									
HydroCheck Date: : 31-May-23										
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
Q2620006	NO. 2/RIGHT/UPPER FIRE EXTINGUISHER BOTTLE - PERFORM ICC HYDROSTATIC TEST								Service	ATA:26
PN:33100021-1	MOS	21-Aug-25	60		30-Jun-30		1599 d			
SN:72043B1	HRS	9809.8								
	AFL	7471								
HydroCheck Date: : 30-Jun-25										
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
T2620001 ^S	** FIREWALL SHUT-OFF VALVES - PERFORM OPERATIONAL CHECK								Service	ATA:26
	MOS	09-Mar-01	48					AIRWORTHINESS		
	HRS	0	1200							
	AFL	0								
PROC. REF: AMM 26-21-00PROC. REF: AMM 26-21-00										

PKG:13

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 26 - FIRE PROTECTION										
Y2610000 ^S		FIREWALL AND ACCESSORY COMPARTMENT FIRE DETECTOR ELEMENTS - PERFORM VISUAL INSPECTION						Service	ATA:26	
	MOS	02-Aug-24	24							
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
Y2620002 ^S		ENGINE FIRE EXTINGUISHER CONTAINERS - PERFORM VISUAL INSPECTION. CHECK CONTAINERS FOR CONDITION, CARTRIDGES AND CARTRIDGE WIRING FOR SECURITY AND CONDITION, CONTAINER PRESSURE GAUGE FOR PROPER PRESSURES, AND PLUMBING FOR SECURITY AND CONDITION.						Service	ATA:26	
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
Y2620005 ^S		ENGINE FIRE EXTINGUISHING SYSTEM - PERFORM OPERATIONAL CHECK						Service	ATA:26	
	MOS	25-Nov-19	96							
	HRS	8177.7	2400							
	AFL	6303								
PROC. REF: AMM 26-21-00PROC. REF: AMM 26-21-00										
Y2620009 ^S		CABIN PORTABLE FIRE EXTINGUISHER - INSPECT PORTABLE HAND HELD FIRE EXTINGUISHERS FOR CONDITION AND DATE OF MANUFACTURE. CHECK OPERATING PRESSURE AND WEIGHT PER MAINTENANCE INSTRUCTIONS ON FIRE EXTINGUISHER BOTTLE.						Service	ATA:26	
PN:C352	MOS	05-Dec-14	12							
SN:H-20651164	HRS	7434.2	300							
	AFL	5687								
PROC. REF: AMM 26-21-00PROC. REF: AMM 26-21-00										
Y2620009 ^S		COPILOT PORTABLE FIRE EXTINGUISHER - INSPECT PORTABLE HAND HELD FIRE EXTINGUISHERS FOR CONDITION AND DATE OF MANUFACTURE. CHECK OPERATING PRESSURE AND WEIGHT PER MAINTENANCE INSTRUCTIONS ON FIRE EXTINGUISHER BOTTLE.						Service	ATA:26	
PN:A344	MOS	21-Aug-25	12							
SN:B10813738	HRS	9809.8	300							
	AFL	7471								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 26 - FIRE PROTECTION

Y2620009	S	PILOT PORTABLE FIRE EXTINGUISHER - INSPECT PORTABLE HAND HELD FIRE EXTINGUISHERS FOR CONDITION AND DATE OF MANUFACTURE. CHECK OPERATING PRESSURE AND WEIGHT PER MAINTENANCE INSTRUCTIONS ON FIRE EXTINGUISHER BOTTLE.						Service	ATA:26
PN:A344T	MOS	05-Dec-14	12						
SN:UNKNOWN	HRS	7434.2	300						
	AFL	5687							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:1

Z2620021	S	NO. 1 ENGINE FIRE EXTINGUISHER CONTAINER PLUMBING - PERFORM DETAILED INSPECTION						Service	ATA:26
	MOS	21-Aug-25	12						
	HRS	9809.8	300						
	AFL	7471							
PROC. REF: AMM 26-21-00PROC. REF: AMM 26-21-00									PKG:2

Z2620021	S	NO. 2 ENGINE FIRE EXTINGUISHER CONTAINER PLUMBING - PERFORM DETAILED INSPECTION						Service	ATA:26
	MOS	21-Aug-25	12						
	HRS	9809.8	300						
	AFL	7471							
PROC. REF: AMM 26-21-00PROC. REF: AMM 26-21-00									PKG:2

ATA 27 - FLIGHT CONTROLS

270301	TRIM SWITCH PANEL						Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN	0			
SN:UNKNOWN	HRS	0		TSN	0			
	AFL	0		TSN	0			
PROC. REF: AMM 27-00-01PROC. REF: AMM 27-00-01								

271001	LEFT AILERON CONTROL SYSTEM CROSSOVER CABLE						Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN	0			
SN:UNKNOWN	HRS	0		TSN	0			
	AFL	0		TSN	0			
PROC. REF: AMM 27-10-05PROC. REF: AMM 27-10-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
271002 RIGHT AILERON CONTROL SYSTEM CROSSOVER CABLE									Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-10-05PROC. REF: AMM 27-10-05									
271003 LEFT AILERON CONTROL SYSTEM CABLE									Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-10-05PROC. REF: AMM 27-10-05									
271004 RIGHT AILERON CONTROL SYSTEM CABLE									Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-10-05PROC. REF: AMM 27-10-05									
271005 AFT AILERON CONTROL SYSTEM CABLE									Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-10-05PROC. REF: AMM 27-10-05									
271045 LEFT INBOARD AILERON CONTROL CABLE									Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-10-05PROC. REF: AMM 27-10-05									
271046 RIGHT INBOARD AILERON CONTROL CABLE									Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-10-05PROC. REF: AMM 27-10-05									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
271051 LEFT FORWARD OUTBOARD AILERON CONTROL CABLE									Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-10-05PROC. REF: AMM 27-10-05									
271052 RIGHT FORWARD OUTBOARD AILERON CONTROL CABLE									Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-10-05PROC. REF: AMM 27-10-05									
271053 LEFT AFT OUTBOARD AILERON CONTROL CABLE									Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-10-05PROC. REF: AMM 27-10-05									
271054 RIGHT AFT OUTBOARD AILERON CONTROL CABLE									Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-10-05PROC. REF: AMM 27-10-05									
271083 AILERON TRIM TAB ACTUATOR									Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-10-09PROC. REF: AMM 27-10-09									
271088 AILERON SPINDLE									Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	H/T	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
271095 PILOT ANGLE OF ATTACK INDICATOR (AOA)									Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
271096 COPILOT ANGLE OF ATTACK INDICATOR (AOA)									Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
272001 FORWARD UPPER RUDDER CONTROL SYSTEM CABLE									Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-20-08PROC. REF: AMM 27-20-08									
272002 FORWARD LOWER RUDDER CONTROL SYSTEM CABLE									Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-20-08PROC. REF: AMM 27-20-08									
272003 LEFT AFT UPPER RUDDER CONTROL SYSTEM CABLE									Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-20-08PROC. REF: AMM 27-20-08									
272004 RIGHT AFT UPPER RUDDER CONTROL SYSTEM CABLE									Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-20-08PROC. REF: AMM 27-20-08									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
272005 LEFT AFT LOWER RUDDER CONTROL SYSTEM CABLE									Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-20-08PROC. REF: AMM 27-20-08									
272006 RIGHT AFT LOWER RUDDER CONTROL SYSTEM CABLE									Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-20-08PROC. REF: AMM 27-20-08									
272021 RUDDER TRIM TAB ACTUATOR									Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-20-03PROC. REF: AMM 27-20-03									
272031 PILOT RUDDER PEDAL ADJUST ACTUATOR									Component ATA:27
PN:6627208001-003 (4389596)	MOS/MSC	17-Feb-05	O/C						
SN:0437	HRS	3300.2							
	AFL	2515							
PROC. REF: AMM 27-20-05PROC. REF: AMM 27-20-05									
272032 COPILOT RUDDER PEDAL ADJUST ACTUATOR									Component ATA:27
PN:6627208001-003 (4389596)	MOS/MSC	17-Feb-05	O/C						
SN:0431	HRS	3300.2							
	AFL	2515							
PROC. REF: AMM 27-20-05PROC. REF: AMM 27-20-05									
273001 PILOT FORWARD ELEVATOR CONTROL SYSTEM CABLE									Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-30-05PROC. REF: AMM 27-30-05									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 27 - FLIGHT CONTROLS										
273002		COPILOT FORWARD ELEVATOR CONTROL SYSTEM CABLE						Component	ATA:27	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 27-30-05PROC. REF: AMM 27-30-05										
273003		LEFT AFT UPPER ELEVATOR CONTROL SYSTEM CABLE						Component	ATA:27	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 27-30-05PROC. REF: AMM 27-30-05										
273004		RIGHT AFT UPPER ELEVATOR CONTROL SYSTEM CABLE						Component	ATA:27	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 27-30-05PROC. REF: AMM 27-30-05										
273005		LEFT AFT LOWER ELEVATOR CONTROL SYSTEM CABLE						Component	ATA:27	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 27-30-05PROC. REF: AMM 27-30-05										
273006		RIGHT AFT LOWER ELEVATOR CONTROL SYSTEM CABLE						Component	ATA:27	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 27-30-05PROC. REF: AMM 27-30-05										
273015		LEFT ANGLE OF ATTACK VANE (AOA)						Component	ATA:27	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 27-31-04PROC. REF: AMM 27-31-04										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
273016 RIGHT ANGLE OF ATTACK VANE (AOA)									Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-31-04PROC. REF: AMM 27-31-04									
273022 LEFT ANGLE OF ATTACK TRANSMITTER (AOA)									Component ATA:27
PN:C-38817-1	MOS/MSC	11-Dec-23	O/C						
SN:1333	HRS	9373.9							
	AFL	7179							
PROC. REF: AMM 27-31-01PROC. REF: AMM 27-31-01									
273023 RIGHT ANGLE OF ATTACK TRANSMITTER (AOA)									Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-31-01PROC. REF: AMM 27-31-01									
273051 ELEVATOR DISCONNECT ACTUATOR									Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-30-09PROC. REF: AMM 27-30-09									
273063 PILOT STICK SHAKER									Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-31-03PROC. REF: AMM 27-31-03									
273064 COPILOT STICK SHAKER									Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-31-03PROC. REF: AMM 27-31-03									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 27 - FLIGHT CONTROLS										
273087		STALL WARNING COMPUTER						Component	ATA:27	
PN:C-38806-2	MOS/MSC	14-Feb-24	O/C							
SN:132	HRS	9467.2								
	AFL	7246								
PROC. REF: AMM 27-31-02PROC. REF: AMM 27-31-02										
273201		ELEVATOR DISCONNECT CURRENT LIMITER						Component	ATA:27	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-30-13PROC. REF: AMM 27-30-13										
273420		ELEVATOR OVERRIDE ACTUATOR						Component	ATA:27	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-30-14PROC. REF: AMM 27-30-14										
274011		HORIZONTAL STABILIZER ACTUATOR						Component	ATA:27	
PN:6627401000-009	MOS/MSC	22-Jun-23	O/C	TSO 10						
SN:B0581	HRS	9258.5		TSO 175.9						
	AFL	7100		TSO 106						
PROC. REF: AMM 27-40-02PROC. REF: AMM 27-40-02										
274031		TRIM-IN-MOTION DETECTOR						Component	ATA:27	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-41-01PROC. REF: AMM 27-41-01										
274041		FORWARD INTERFACE UNIT						Component	ATA:27	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-40-04PROC. REF: AMM 27-40-04										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 27 - FLIGHT CONTROLS										
274051	HORIZONTAL STABILIZER ACTUATOR CONTROL BOX								Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-40-02, AMM 27-40-03PROC. REF: AMM 27-40-02, AMM 27-40-03										
275020	LEFT OUTBOARD FLAP ACTUATOR								Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-50-06PROC. REF: AMM 27-50-06										
275021	LEFT INBOARD FLAP ACTUATOR								Component	ATA:27
PN:6627503000-009	MOS/MSC	18-Jul-07	O/C							
SN:1743	HRS	5671.55								
	AFL	4333								
PROC. REF: AMM 27-50-06PROC. REF: AMM 27-50-06										
275022	RIGHT INBOARD FLAP ACTUATOR								Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-50-06PROC. REF: AMM 27-50-06										
275023	RIGHT OUTBOARD FLAP ACTUATOR								Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-50-06PROC. REF: AMM 27-50-06										
275057	FLAP DRIVE POWER UNIT								Component	ATA:27
PN:6627503000-029	MOS/MSC	25-Feb-11	O/C							
SN:1461	HRS	6519.3								
	AFL	4991								
PROC. REF: AMM 27-50-08PROC. REF: AMM 27-50-08										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 27 - FLIGHT CONTROLS										
275058	FLAP CONTROL UNIT								Component	ATA:27
PN:C144486-3-003	MOS/MSC	05-Jan-20	O/C							
SN:1343	HRS	8209.7								
	AFL	6328								
PROC. REF: AMM 27-50-05PROC. REF: AMM 27-50-05										
<hr/>										
275069	FLAP POSITION INDICATOR								Component	ATA:27
PN:C145159-1	MOS/MSC	09-Oct-23	O/C							
SN:135	HRS	9332.6								
	AFL	7149								
PROC. REF: AMM 27-50-07PROC. REF: AMM 27-50-07										
<hr/>										
275080	FLAP CONTROL MODULE								Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-50-02PROC. REF: AMM 27-50-02										
<hr/>										
275081	LEFT FLAP DRIVE ROTARY VARIABLE DIFFERENTIAL TRANSFORMER								Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-50-03PROC. REF: AMM 27-50-03										
<hr/>										
275082	RIGHT FLAP DRIVE ROTARY VARIABLE DIFFERENTIAL TRANSFORMER								Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-50-03PROC. REF: AMM 27-50-03										
<hr/>										
276001	LEFT SPOILER ACTUATOR								Component	ATA:27
PN:6627602001-007	MOS/MSC	15-Jun-06	O/C							
SN:DWA392-00	HRS	4570.25								
	AFL	3497								
PROC. REF: AMM 27-60-04PROC. REF: AMM 27-60-04										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 27 - FLIGHT CONTROLS										
276002		RIGHT SPOILER ACTUATOR						Component	ATA:27	
PN:6627602001-007	MOS/MSC	15-Jun-06	O/C							
SN:DAW398-00	HRS	4570.25								
	AFL	3497								
PROC. REF: AMM 27-60-04PROC. REF: AMM 27-60-04										
276005		SPOILER CONTROL MODULE						Component	ATA:27	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-60-03PROC. REF: AMM 27-60-03										
276010		SPOILERON CONTROLLER RESISTOR BOX						Component	ATA:27	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-60-10PROC. REF: AMM 27-60-10										
276013		SPOILER SHUTOFF VALVE						Component	ATA:27	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-60-07PROC. REF: AMM 27-60-07										
276020		SPOILER LOW PRESSURE SWITCH						Component	ATA:27	
PN:6629101004-003	MOS/MSC	11-Jun-16	O/C							
SN:535	HRS	7630.1								
	AFL	5823								
PROC. REF: AMM 27-60-08PROC. REF: AMM 27-60-08										
276031		LEFT SPOILER ROTARY VARIABLE DIFFERENTIAL TRANSFORMER						Component	ATA:27	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-60-05PROC. REF: AMM 27-60-05										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 27 - FLIGHT CONTROLS										
276032	RIGHT SPOILER ROTARY VARIABLE DIFFERENTIAL TRANSFORMER								Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 27-60-05PROC. REF: AMM 27-60-05										
276073	SPOILERON COMPUTER								Component	ATA:27
PN:6627608500-007	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:00227	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 27-60-02PROC. REF: AMM 27-60-02										
276076	CONTROL WHEEL ROTARY VARIABLE DIFFERENTIAL TRANSFORMER								Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 27-60-06PROC. REF: AMM 27-60-06										
5-19-01-W2750055	* FLAP ACTUATOR JOINT (P/N 145673-1) (IRN W2750055) REPLACEMENT								Component	ATA:27
PN:159174-1	MOS/MSC	05-Dec-19	N/A	TSN 4372						
SN:UNKNOWN	HRS	8177.8	NOT APPLICABLE							
	AFL	6304								
A2711001 ^S	** AILERON TRIM TAB CONTROL SYSTEM - PERFORM OPERATIONAL CHECK								Service	ATA:27
	MOS	02-Aug-24	24	AIRWORTHINESS						
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 27-10-04PROC. REF: AMM 27-10-04										
A2721001 ^S	** RUDDER TRIM SYSTEM - PERFORM OPERATIONAL CHECK								Service	ATA:27
	MOS	02-Aug-24	24	AIRWORTHINESS						
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 27-20-00PROC. REF: AMM 27-20-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 27 - FLIGHT CONTROLS										
A2731002 ^S	** ELEVATOR DISCONNECT SYSTEM - PERFORM OPERATIONAL CHECK								Service	ATA:27
	MOS	02-Aug-24	24					AIRWORTHINESS		
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 27-30-00PROC. REF: AMM 27-30-00										
PKG:8										
A2760001 ^S	** SPOILER ACTUATOR CHECK VALVE - PERFORM OPERATIONAL CHECK								Service	ATA:27
	MOS	02-Aug-24	24					AIRWORTHINESS		
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 27-60-04PROC. REF: AMM 27-60-04										
PKG:10										
A2760002 ^S	** SPOILER SYSTEM - PERFORM SPOILER AUTHORITY WITH FLAPS CHECK								Service	ATA:27
	MOS	02-Aug-24	24					AIRWORTHINESS		
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 27-60-00PROC. REF: AMM 27-60-00										
PKG:10										
AA2700000 ^S	AILERON CONTROL CABLE SYSTEM - WITH COCKPIT AND CABIN FLOORBOARDS REMOVED, PERFORM VISUAL INSPECTION OF CABLES								Service	ATA:27
	MOS	02-Aug-24	24							
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00										
PKG:7										
AA2700001 ^S	RUDDER CONTROL CABLE SYSTEM - WITH COCKPIT AND CABIN FLOORBOARDS REMOVED, PERFORM VISUAL INSPECTION OF CABLES								Service	ATA:27
	MOS	02-Aug-24	24							
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00										
PKG:7										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
AA2700002 ^S	ELEVATOR CONTROL CABLE SYSTEM - WITH COCKPIT AND CABIN FLOORBOARDS REMOVED, PERFORM VISUAL INSPECTION OF CABLES							Service	ATA:27
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00									
AA2760021	LEFT SPOILER HYDRAULIC SYSTEM PRESSURE SWIVEL - REPLACE							Service	ATA:27
	MOS	22-Jun-23							
	HRS	9258.5	1200		10458.5		435.4		
	AFL	7100							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
AA2760021	LEFT SPOILER HYDRAULIC SYSTEM RETURN SWIVEL - REPLACE							Service	ATA:27
	MOS	22-Jun-23							
	HRS	9258.5	1200		10458.5		435.4		
	AFL	7100							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
AA2760021	RIGHT SPOILER HYDRAULIC SYSTEM PRESSURE SWIVEL - REPLACE							Service	ATA:27
	MOS	22-Jun-23							
	HRS	9258.5	1200		10458.5		435.4		
	AFL	7100							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
AA2760021	RIGHT SPOILER HYDRAULIC SYSTEM RETURN SWIVEL - REPLACE							Service	ATA:27
	MOS	22-Jun-23							
	HRS	9258.5	1200		10458.5		435.4		
	AFL	7100							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
AD2760085 ^S	SPOILER LEVER ARM - PERFORM DETAILED VISUAL INSPECTION TO ENSURE SPOILER LEVER ARM IS PROPERLY SEATED AND SECURED ON SPOILER RVDT SHAFT							Service	ATA:27
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							

PKG:7

PKG:10

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
PROC. REF: AMM 27-60-05PROC. REF: AMM 27-60-05									
AE2710049 * AILERON LEADING EDGE (INTERNAL) - PERFORM BORESCOPE INSPECTION Service ATA:27									
	MOS	EFF	T:6		11-Jun-26 *		119 d	AIRWORTHINESS	
	HRS								
	AFL								
PROC. REF: AMM 27-10-02PROC. REF: AMM 27-10-02									
AE2730037 ^S PERFORM DETAILED VISUAL INSPECTION OF THE ELEVATOR UP/DOWN SPRING ASSEMBLY, YOKE ASSEMBLY AND ASSOCIATED PARTS FOR FREE MOVEMENT, LOOSE FASTENERS AND SECURITY OF LOCKING DEVICES Service ATA:27									
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PKG:14									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
D2740003 ** HORIZONTAL STABILIZER ACTUATOR SECONDARY TRIM - PERFORM FUNCTIONAL TEST Service ATA:27									
PN:6627401000-009	MOS	02-Aug-24						AIRWORTHINESS	
SN:B0581	HRS	9525.7	600		10125.7		102.6		
	AFL	7276							
PROC. REF: AMM 27-40-02PROC. REF: AMM 27-40-02									
D2740004 ** HORIZONTAL STABILIZER ACTUATOR PRIMARY TRIM - PERFORM FUNCTIONAL TEST Service ATA:27									
PN:6627401000-009	MOS	02-Aug-24						AIRWORTHINESS	
SN:B0581	HRS	9525.7	600		10125.7		102.6		
	AFL	7276							
PROC. REF: AMM 27-40-02PROC. REF: AMM 27-40-02									
G2710003 ^S AILERON CONTROL SYSTEM CABLES (LOCATED IN WING) - PERFORM CABLE TENSION CHECK Service ATA:27									
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PKG:16									
PROC. REF: AMM 27-10-00PROC. REF: AMM 27-10-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
G2710004 ^S	AILERON CONTROL SYSTEM CABLES (LOCATED IN FUSELAGE) - PERFORM CABLE TENSION CHECK							Service	ATA:27
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 27-10-00PROC. REF: AMM 27-10-00									
PKG:13									
G2720003 ^S	RUDDER CONTROL CABLES - PERFORM TENSION CHECK							Service	ATA:27
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 27-20-00PROC. REF: AMM 27-20-00									
PKG:14									
G2720004 ^S	RUDDER PEDALS, PEDAL PUSHRODS, ADJUSTMENT ACTUATOR, AND SECTORS - PERFORM VISUAL INSPECTION. CHECK DURING FULL TRAVEL OF RUDDER.							Service	ATA:27
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
PKG:13									
G2730003 ^S	ELEVATOR CONTROL CABLES - PERFORM TENSION CHECK							Service	ATA:27
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 27-30-00PROC. REF: AMM 27-30-00									
PKG:14									
K2700007	* AILERON CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED VISUAL INSPECTION							Service	ATA:27
	MOS	22-Jun-23						AIRWORTHINESS	
	HRS	9258.5	4800		14058.5		4035.4		
	AFL	7100							
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 27 - FLIGHT CONTROLS										
K2700008	* ELEVATOR CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED VISUAL INSPECTION								Service	ATA:27
	MOS	22-Jun-23						AIRWORTHINESS		
	HRS	9258.5	4800		14058.5		4035.4			
	AFL	7100								
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00										
K2700009	* RUDDER CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED VISUAL INSPECTION								Service	ATA:27
	MOS	22-Jun-23						AIRWORTHINESS		
	HRS	9258.5	4800		14058.5		4035.4			
	AFL	7100								
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00										
K2700010	* ELEVATOR CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED VISUAL INSPECTION								Service	ATA:27
	MOS	22-Jun-23						AIRWORTHINESS		
	HRS	9258.5	4800		14058.5		4035.4			
	AFL	7100								
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00										
K2700012	* RUDDER CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED VISUAL INSPECTION								Service	ATA:27
	MOS	22-Jun-23						AIRWORTHINESS		
	HRS	9258.5	4800		14058.5		4035.4			
	AFL	7100								
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00										
K2700014	* AILERON CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED VISUAL INSPECTION								Service	ATA:27
	MOS	22-Jun-23						AIRWORTHINESS		
	HRS	9258.5	4800		14058.5		4035.4			
	AFL	7100								
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00										
N2720030	RUDDER TORQUE TUBE AND SPINDLE - PERFORM DETAILED VISUAL INSPECTION								Service	ATA:27
	MOS	21-Aug-25	72		21-Aug-31		2016 d	AIRWORTHINESS		
	HRS	9809.8								
	AFL	7471								
PROC. REF: AMM 27-20-01PROC. REF: AMM 27-20-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 27 - FLIGHT CONTROLS										
N2740023		* HORIZONTAL STABILIZER ACTUATOR ACME SCREW - REPLACE							Service	ATA:27
PN:6627401000-009	MOS/MSC	18-Aug-22	N/A							
SN:B0581	HRS	9082.6								
	AFL	6994								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
N2740024		* HORIZONTAL STABILIZER ACTUATOR ACME NUT - REPLACE							Service	ATA:27
PN:6627401000-009	MOS/MSC	18-Aug-22	N/A							
SN:B0581	HRS	9082.6								
	AFL	6994								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
N2740025		* HORIZONTAL STABILIZER ACTUATOR - PERFORM DETAILED STRUCTURAL INSPECTION							Service	ATA:27
	MOS/MSC	18-Aug-22	N/A							
	HRS	9082.6								
	AFL	6994								
P2740032		* HORIZONTAL STABILIZER ACTUATOR - PERFORM INSPECTION							Service	ATA:27
PN:6627401000-009	MOS	18-Aug-22						AIRWORTHINESS		
SN:B0581	HRS	9082.6	1200		10282.6		259.5			
	AFL	6994								
P2740033		* HORIZONTAL STABILIZER ACTUATOR - PERFORM DETAILED STRUCTURAL INSPECTION							Service	ATA:27
PN:6627401000-009	MOS	18-Aug-22								
SN:B0581	HRS	9082.6	2400		11482.6		1459.5			
	AFL	6994								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
R2710041		* AILERON SPINDLE - REPLACE							Service	ATA:27
	MOS	30-Mar-21	120		30-Mar-31		1872 d	LIFE LIMIT		
	HRS	8414.4								
	AFL	6463								
PROC. REF: AMM 27-10-07PROC. REF: AMM 27-10-07										

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 27 - FLIGHT CONTROLS										
S2750057	* FLAP ACTUATOR BALLNUT SLEEVE - PERFORM FLUORESCENT PENETRANT INSPECTION								Service	ATA:27
	MOS/MSC	05-Dec-19	N/A							
	HRS	8177.8								
	AFL	6304								
PROC. REF: NDT PART 8/27-50-01, NDT PART 8/27-50-02PROC. REF: NDT PART 8/27-50-01, NDT PART 8/27-50-02										
T2740002	* HORIZONTAL STABILIZER ACTUATOR - PERFORM INSPECTION								Service	ATA:27
	MOS/MSC	18-Aug-22	N/A							
	HRS	9082.6								
	AFL	6994								
V2712000 ^S	** ROLL DISCONNECT SWITCHES - PERFORM OPERATIONAL CHECK								Service	ATA:27
	MOS	02-Aug-24	24					AIRWORTHINESS		
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 27-60-09PROC. REF: AMM 27-60-09										
W2731001 ^S	** PITCH TRIM - PERFORM OPERATIONAL CHECK OF ELEVATOR OVERRIDE ACTUATOR								Service	ATA:27
	MOS	02-Aug-24	24					AIRWORTHINESS		
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 27-30-14PROC. REF: AMM 27-30-14										
W2750055	* LEFT INBOARD FLAP ACTUATOR JOINT - REPLACE								Service	ATA:27
	MOS/MSC	05-Dec-19	N/A							
	HRS	8177.8								
	AFL	6304								
W2750055	* LEFT OUTBOARD FLAP ACTUATOR JOINT - REPLACE								Service	ATA:27
	MOS/MSC	05-Dec-19	N/A							
	HRS	8177.8								
	AFL	6304								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 27 - FLIGHT CONTROLS										
W2750055	* RIGHT INBOARD FLAP ACTUATOR JOINT - REPLACE								Service	ATA:27
	MOS/MSC	05-Dec-19	N/A							
	HRS	8177.8								
	AFL	6304								
W2750055	* RIGHT OUTBOARD FLAP ACTUATOR JOINT - REPLACE								Service	ATA:27
	MOS/MSC	05-Dec-19	N/A							
	HRS	8177.8								
	AFL	6304								
W2750056	* LEFT INBOARD FLAP ACTUATOR JOINT - PERFORM DETAILED VISUAL INSPECTION. APPLY CORROSION PREVENTIVE COMPOUND (CPC) TO JOINT.								Service	ATA:27
	MOS/MSC	05-Dec-19	N/A							
	HRS	8177.8								
	AFL	6304								
PROC. REF: AMM 12-21-03, AMM 27-50-06PROC. REF: AMM 12-21-03, AMM 27-50-06										
W2750056	* LEFT OUTBOARD FLAP ACTUATOR JOINT - PERFORM DETAILED VISUAL INSPECTION. APPLY CORROSION PREVENTIVE COMPOUND (CPC) TO JOINT.								Service	ATA:27
	MOS/MSC	05-Dec-19	N/A							
	HRS	8177.8								
	AFL	6304								
PROC. REF: AMM 12-21-03, AMM 27-50-06PROC. REF: AMM 12-21-03, AMM 27-50-06										
W2750056	* RIGHT INBOARD FLAP ACTUATOR JOINT - PERFORM DETAILED VISUAL INSPECTION. APPLY CORROSION PREVENTIVE COMPOUND (CPC) TO JOINT.								Service	ATA:27
	MOS/MSC	05-Dec-19	N/A							
	HRS	8177.8								
	AFL	6304								
PROC. REF: AMM 12-21-03, AMM 27-50-06PROC. REF: AMM 12-21-03, AMM 27-50-06										
W2750056	* RIGHT OUTBOARD FLAP ACTUATOR JOINT - PERFORM DETAILED VISUAL INSPECTION. APPLY CORROSION PREVENTIVE COMPOUND (CPC) TO JOINT.								Service	ATA:27
	MOS/MSC	05-Dec-19	N/A							
	HRS	8177.8								
	AFL	6304								
PROC. REF: AMM 12-21-03, AMM 27-50-06PROC. REF: AMM 12-21-03, AMM 27-50-06										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
Y2700003 ^S	AILERON CONTROL CABLE SYSTEM - PERFORM VISUAL INSPECTION OF CABLES WITHIN WING							Service	ATA:27
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PKG:10									
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00									
Y2700004 ^S	RUDDER CONTROL CABLE SYSTEM - PERFORM VISUAL INSPECTION OF ACCESSIBLE UPPER AND LOWER CABLES							Service	ATA:27
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PKG:8									
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00									
Y2700005 ^S	ELEVATOR CONTROL CABLE SYSTEM - PERFORM VISUAL INSPECTION OF ACCESSIBLE UPPER AND LOWER CABLES							Service	ATA:27
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PKG:8									
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00									
Y2700006 ^S	RUDDER AND ELEVATOR CONTROL CABLES AND ASSOCIATED PULLEYS, LOCATED IN AFT PRESSURE BULKHEAD SUPPORT CHANNEL - PERFORM VISUAL INSPECTION							Service	ATA:27
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PKG:9									
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00									
Y2710000 ^S	AILERONS, AILERON TRIM TAB AND VISIBLE PORTION OF RODS - PERFORM VISUAL INSPECTION							Service	ATA:27
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PKG:10									
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 27 - FLIGHT CONTROLS										
Y2710001 ^S	AILERON BALANCE WEIGHT INSTALLATION AND SUPPORTING STRUCTURE - PERFORM VISUAL INSPECTION								Service	ATA:27
	MOS	09-Mar-01	48							
	HRS	0	1200							
	AFL	0								
PKG:16										
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
Y2710002 ^S	AILERON CONTROL SYSTEM - PERFORM OPERATIONAL CHECK								Service	ATA:27
	MOS	09-Mar-01	48							
	HRS	0	1200							
	AFL	0								
PKG:16										
PROC. REF: AMM 27-10-00PROC. REF: AMM 27-10-00										
Y2710048 ^S	AILERON TRIM TAB INSTALLATION - PERFORM FREE PLAY CHECK								Service	ATA:27
	MOS	09-Mar-01								
	HRS	0	T:9600							
	AFL	0								
PKG:22										
PROC. REF: AMM 27-10-04PROC. REF: AMM 27-10-04										
Y2720000 ^S	RUDDER - PERFORM VISUAL INSPECTION								Service	ATA:27
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PKG:2										
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
Y2720001 ^S	RUDDER BALANCE WEIGHT INSTALLATION AND SUPPORTING STRUCTURE - PERFORM VISUAL INSPECTION								Service	ATA:27
	MOS	09-Mar-01	48							
	HRS	0	1200							
	AFL	0								
PKG:14										
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 27 - FLIGHT CONTROLS										
Y2720002 ^S			RUDDER CONTROL SYSTEM - PERFORM OPERATIONAL CHECK						Service	ATA:27
	MOS	09-Mar-01	48							
	HRS	0	1200							
	AFL	0								
PROC. REF: AMM 27-20-00PROC. REF: AMM 27-20-00										
Y2721000 ^S			RUDDER TRIM TAB AND VISIBLE RODS - PERFORM VISUAL INSPECTION						Service	ATA:27
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
Y2730000 ^S			CONTROL COLUMNS - PERFORM VISUAL INSPECTION. PAY PARTICULAR ATTENTION TO AILERON CONTROL WHEEL CABLE DRUM AND BOTTOM CROSSOVER PULLEYS.						Service	ATA:27
	MOS	09-Mar-01	48							
	HRS	0	1200							
	AFL	0								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
Y2730001 ^S			ELEVATORS - PERFORM VISUAL INSPECTION						Service	ATA:27
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
Y2730002 ^S			ELEVATOR CONTROL SYSTEM - PERFORM OPERATIONAL CHECK						Service	ATA:27
	MOS	09-Mar-01	48							
	HRS	0	1200							
	AFL	0								
PROC. REF: AMM 27-30-00PROC. REF: AMM 27-30-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 27 - FLIGHT CONTROLS										
Y2730004	^S	CONTROL COLUMNS - PERFORM INSPECTION. INSPECT CABLE, PULLEYS, BEARINGS, AND ELECTRICAL WIRING							Service	ATA:27
	MOS	25-Nov-19	96							
	HRS	8177.7	2400							
	AFL	6303								
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00										
PKG:19										
Y2730007	^S	AFT ELEVATOR DISCONNECT - PERFORM DETAILED VISUAL INSPECTION							Service	ATA:27
	MOS	25-Nov-19	96							
	HRS	8177.7	2400							
	AFL	6303								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
PKG:20										
Y2740000	^S	PRIMARY PITCH TRIM SYSTEM - PERFORM OPERATIONAL CHECK							Service	ATA:27
	MOS	09-Mar-01	48							
	HRS	0	1200							
	AFL	0								
PROC. REF: AMM 27-40-00PROC. REF: AMM 27-40-00										
PKG:14										
Y2740001	^S	SECONDARY PITCH TRIM SYSTEM - PERFORM OPERATIONAL CHECK							Service	ATA:27
	MOS	09-Mar-01	48							
	HRS	0	1200							
	AFL	0								
PROC. REF: AMM 27-40-00PROC. REF: AMM 27-40-00										
PKG:14										
Y2750000	^S	FLAP DRIVE INSTALLATION - PERFORM VISUAL INSPECTION WITH FLAPS LOWERED							Service	ATA:27
	MOS	02-Aug-24	24							
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
PKG:10										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 27 - FLIGHT CONTROLS

Y2750001	^S	FLAPS - PERFORM VISUAL INSPECTION						Service	ATA:27
	MOS	21-Aug-25	12						
	HRS	9809.8	300						
	AFL	7471							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									

PKG:4

Y2750053	^S	FLAP DRIVE ACTUATORS - PERFORM A VISUAL INSPECTION OF THE ACTUATOR ATTACHMENT, PAYING PARTICULAR ATTENTION TO THE GIMBAL PIN RETAINING RINGS						Service	ATA:27
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									

PKG:10

Y2760000	^S	SPOILER AND SPOILER ACTUATOR - PERFORM VISUAL INSPECTION WITH FLAPS LOWERED AND ACCESS PANELS OPENED						Service	ATA:27
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									

PKG:10

ATA 28 - FUEL

281001	LEFT NO. 1 FUEL EJECTOR SCAVENGE PUMP						Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN	0			
SN:UNKNOWN	HRS	0		TSN	0			
	AFL	0		TSN	0			
PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01								

281002	RIGHT NO. 1 FUEL EJECTOR SCAVENGE PUMP						Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN	0			
SN:UNKNOWN	HRS	0		TSN	0			
	AFL	0		TSN	0			
PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
281003 LEFT NO. 2 FUEL EJECTOR SCAVENGE PUMP									Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01									
281004 RIGHT NO. 2 FUEL EJECTOR SCAVENGE PUMP									Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01									
281005 LEFT NO. 3 FUEL EJECTOR SCAVENGE PUMP									Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01									
281006 RIGHT NO. 3 FUEL EJECTOR SCAVENGE PUMP									Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01									
281007 LEFT NO. 4 FUEL EJECTOR SCAVENGE PUMP									Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01									
281008 RIGHT NO. 4 FUEL EJECTOR SCAVENGE PUMP									Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
281009 LEFT NO. 5 FUEL EJECTOR SCAVENGE PUMP									Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01									
281010 RIGHT NO. 5 FUEL EJECTOR SCAVENGE PUMP									Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01									
281031 FUSELAGE FUEL CELL									Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-10-02PROC. REF: AMM 28-10-02									
281051 FUEL CROSSFLOW SHUTOFF VALVE									Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-12-02PROC. REF: AMM 28-12-02									
281401 SURGE TANK FLOAT VALVE									Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-11-02PROC. REF: AMM 28-11-02									
281501 LEFT FLEX FUEL HOSE ASSY									Component ATA:28
PN:244224151	MOS/MSC	26-May-05	O/C						
SN:F16806-04	HRS	3623.3							
WC#: 28.015	AFL	2739							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 28 - FUEL										
281502		RIGHT FLEX FUEL HOSE ASSY						Component	ATA:28	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 28.015	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
<hr/>										
281521		LEFT FUEL TRANSFER CHECK VALVE						Component	ATA:28	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-12-03PROC. REF: AMM 28-12-03										
<hr/>										
281522		RIGHT FUEL TRANSFER CHECK VALVE						Component	ATA:28	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-12-03PROC. REF: AMM 28-12-03										
<hr/>										
282001		LEFT FUEL SHUTOFF VALVE						Component	ATA:28	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-20-06PROC. REF: AMM 28-20-06										
<hr/>										
282003		RIGHT FUEL SHUTOFF VALVE						Component	ATA:28	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-20-06PROC. REF: AMM 28-20-06										
<hr/>										
282011		SHUTOFF - REFUEL VALVE						Component	ATA:28	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-20-10PROC. REF: AMM 28-20-10										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 28 - FUEL										
282031	LEFT NO. 1 FUEL SUPPLY CHECK VALVE								Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-20-03PROC. REF: AMM 28-20-03										
282032	LEFT NO. 2 FUEL SUPPLY CHECK VALVE								Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-20-03PROC. REF: AMM 28-20-03										
282033	RIGHT NO. 1 FUEL SUPPLY CHECK VALVE								Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-20-03PROC. REF: AMM 28-20-03										
282034	RIGHT NO. 2 FUEL SUPPLY CHECK VALVE								Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-20-03PROC. REF: AMM 28-20-03										
282037	RIGHT FUEL SUPPLY SHUT-OFF VALVE ASSEMBLY								Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-20-06PROC. REF: AMM 28-20-06										
282038	LEFT FUEL SUPPLY SHUT-OFF VALVE ASSEMBLY								Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-20-06PROC. REF: AMM 28-20-06										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 28 - FUEL										
282041		REFUELING CONTROL PANEL						Component	ATA:28	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-20-14PROC. REF: AMM 28-20-14										
282051		LEFT MOTIVE FLOW CHECK VALVE						Component	ATA:28	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-20-05PROC. REF: AMM 28-20-05										
282052		RIGHT MOTIVE FLOW CHECK VALVE						Component	ATA:28	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-20-05PROC. REF: AMM 28-20-05										
282063		PRE-CHECK SINGLE POINT PRESSURE REFUELING (SPPR) VALVE						Component	ATA:28	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-20-12PROC. REF: AMM 28-20-12										
282064		PILOT OPERATED SINGLE POINT PRESSURE REFUELING (SPPR) VALVE						Component	ATA:28	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-20-11PROC. REF: AMM 28-20-11										
282075		LEFT MAIN FUEL EJECTOR PUMP ASSEMBLY						Component	ATA:28	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-20-01PROC. REF: AMM 28-20-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
282076 RIGHT MAIN FUEL EJECTOR PUMP ASSEMBLY									Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-20-01PROC. REF: AMM 28-20-01									
282087 LEFT STANDBY FUEL PUMP									Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-20-02PROC. REF: AMM 28-20-02									
282088 RIGHT STANDBY FUEL PUMP									Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-20-02PROC. REF: AMM 28-20-02									
282601 DEFUEL SHUTOFF VALVE									Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-20-07PROC. REF: AMM 28-20-07									
282602 REFUEL CHECK VALVE									Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-20-09PROC. REF: AMM 28-20-09									
282603 SINGLE POINT PRESSURE REFUELING (SPPR) ADAPTER									Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 28 - FUEL										
282815		APU FUEL SHUTOFF VALVE						Component	ATA:28	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-20-04PROC. REF: AMM 28-20-04										
282829		APU FUEL LINE						Component	ATA:28	
PN:PN	MOS/MSC	EFF	N/A	TSN 0						
SN:UNKNOWN	HRS	EFF		TSN 0						
	AFL			TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
2840001 EMP		* DUAL FUEL FLOW CONVERTER (DFFC) - PERFORM ACCEPTANCE TEST AND LOW TEMPERATURE SCREENING						Service	ATA:28	
	MOS/MSC	09-Mar-01	N/A							
	HRS	0								
	AFL	0								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
284001		C1 FUEL PROBE						Component	ATA:28	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05										
284002		C2 FUEL PROBE						Component	ATA:28	
PN:10552T03Y00	MOS/MSC	22-May-06	O/C							
SN:0117	HRS	4507.7								
	AFL	3441								
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05										
284003		C3 FUEL PROBE						Component	ATA:28	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 28 - FUEL										
284004	C4 FUEL PROBE								Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05										
284005	C5 FUEL PROBE								Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05										
284006	C6 FUEL PROBE								Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05										
284008	C7 FUEL PROBE								Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05										
284009	C8 FUEL PROBE								Component	ATA:28
PN:10552T03Y00	MOS/MSC	22-May-06	O/C							
SN:7262	HRS	4507.7								
	AFL	3441								
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05										
284010	C9 FUEL PROBE								Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 28 - FUEL										
284011	C10 FUEL PROBE								Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05										
<hr/>										
284012	C11 FUEL PROBE								Component	ATA:28
PN:6628408000-009	MOS/MSC	04-Jul-07	O/C							
SN:B408	HRS	5595.25								
	AFL	4268								
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05										
<hr/>										
284013	C12 FUEL PROBE								Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05										
<hr/>										
284014	C13 FUEL PROBE								Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05										
<hr/>										
284015	C14 FUEL PROBE								Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05										
<hr/>										
284016	C15 FUEL PROBE								Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 28 - FUEL										
284017	C16 FUEL PROBE								Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05										
<hr/>										
284033	FUSELAGE FUEL PROBE								Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05										
<hr/>										
284035	NO. 1 LOW PRESSURE FUEL SWITCH								Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-01PROC. REF: AMM 28-40-01										
<hr/>										
284036	NO. 2 LOW PRESSURE FUEL SWITCH								Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-01PROC. REF: AMM 28-40-01										
<hr/>										
284041	LEFT FUEL FLOAT SWITCH								Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-02PROC. REF: AMM 28-40-02										
<hr/>										
284042	RIGHT FUEL FLOAT SWITCH								Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-02PROC. REF: AMM 28-40-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 28 - FUEL										
284045	FUEL QUANTITY SIGNAL CONDITIONER								Component	ATA:28
PN:6628408000-023	MOS/MSC	04-Jun-05	O/C							
SN:B0672	HRS	3648.97								
	AFL	2757								
PROC. REF: AMM 28-40-04PROC. REF: AMM 28-40-04										
<hr/>										
284047	LEFT LOW LEVEL FUEL SENSOR								Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-03PROC. REF: AMM 28-40-03										
<hr/>										
284048	RIGHT LOW LEVEL FUEL SENSOR								Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-03PROC. REF: AMM 28-40-03										
<hr/>										
D2820013	PERFORM INITIAL CLEANING AND LEAK CHECK OF LOW-PRESSURE FUEL FILTERS								Service	ATA:28
	MOS/MSC	30-Apr-06	A/R							
	HRS									
	AFL									
PROC. REF: AMM 28-20-15PROC. REF: AMM 28-20-15										
<hr/>										
F2840003 ^S	** FUEL QUANTITY SIGNAL CONDITIONER - PERFORM FUNCTIONAL TEST TO VERIFY WEIGHT ON WHEELS (WOW) INPUTS								Service	ATA:28
	MOS	09-Mar-01	48					AIRWORTHINESS		
	HRS	0	1200							
	AFL	0								
PROC. REF: AMM 28-40-00PROC. REF: AMM 28-40-00										
<hr/>										
H2840001	* DUAL FUEL FLOW CONVERTER (DFFC) - PERFORM ACCEPTANCE TEST AND LOW TEMPERATURE SCREENING								Service	ATA:28
	MOS/MSC	09-Mar-01	N/A							
	HRS	0								
	AFL	0								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

PKG:14

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 28 - FUEL										
Y2810001	^S	WING TANKS - REMOVE FUEL TANK ACCESS PANELS AND PERFORM VISUAL INSPECTION						Service	ATA:28	
	MOS	02-Aug-24	24							
	HRS	9525.7	600							
	AFL	7276								
PKG:10										
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										

Y2810002	^S	WING TANKS - REMOVE FUEL TANK ACCESS PANELS AND PERFORM VISUAL INSPECTION						Service	ATA:28	
	MOS	25-Nov-19	96							
	HRS	8177.7	2400							
	AFL	6303								
PKG:22										
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										

Y2820000	^S	LOW PRESSURE FUEL FILTER - REMOVE AND INSPECT FOR CONTAMINATION. CLEAN IF NECESSARY.						Service	ATA:28	
	MOS	02-Aug-24	24							
	HRS	9525.7	600							
	AFL	7276								
PKG:10										
PROC. REF: AMM 28-20-15PROC. REF: AMM 28-20-15										

ATA 29 - HYDRAULIC POWER										
291001		HYDRAULIC RESERVOIR						Component	ATA:29	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN	0					
SN:UNKNOWN	HRS	0		TSN	0					
	AFL	0		TSN	0					
PROC. REF: AMM 29-10-02PROC. REF: AMM 29-10-02										

291012		L8 HYDRAULIC SHUTOFF VALVE						Component	ATA:29	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN	0					
SN:UNKNOWN	HRS	0		TSN	0					
	AFL	0		TSN	0					
PROC. REF: AMM 29-10-05PROC. REF: AMM 29-10-05										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 29 - HYDRAULIC POWER									
291013 L9 HYDRAULIC SHUTOFF VALVE									Component ATA:29
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 29-10-05PROC. REF: AMM 29-10-05									
291033 RESERVOIR PRESSURIZATION CONTROL MODULE									Component ATA:29
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 29-10-06PROC. REF: AMM 29-10-06									
291034 RESERVOIR FLUID LEVEL SENSOR									Component ATA:29
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 29-30-02PROC. REF: AMM 29-30-02									
291045 NO. 1 ENGINE DRIVEN HYDRAULIC PUMP									Component ATA:29
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 29-10-01PROC. REF: AMM 29-10-01									
291046 NO. 2 ENGINE DRIVEN HYDRAULIC PUMP									Component ATA:29
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 29-10-01PROC. REF: AMM 29-10-01									
291051 NO. 1 MAIN HYDRAULIC SYSTEM PRESSURE SWITCH									Component ATA:29
PN:6629101004-001	MOS/MSC	11-Jun-16	O/C	TSN 0					
SN:1452	HRS	7630.1		TSN 0					
	AFL	5823		TSN 0					
PROC. REF: AMM 29-30-03PROC. REF: AMM 29-30-03									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 29 - HYDRAULIC POWER										
291052		NO. 2 MAIN HYDRAULIC SYSTEM PRESSURE SWITCH						Component	ATA:29	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 29-30-03PROC. REF: AMM 29-30-03										
291057		MAIN HYDRAULIC SYSTEM ACCUMULATOR						Component	ATA:29	
PN:88746-1	MOS/MSC	28-Jan-07	O/C							
SN:424	HRS	5192.28								
	AFL	3977								
PROC. REF: AMM 29-10-04PROC. REF: AMM 29-10-04										
291059		MAIN HYDRAULIC FILTER MANIFOLD						Component	ATA:29	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 29-10-03PROC. REF: AMM 29-10-03										
291069		THERMAL SHUTOFF VALVE						Component	ATA:29	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 29-10-07PROC. REF: AMM 29-10-07										
292001		AUXILIARY FILTER MANIFOLD ASSEMBLY						Component	ATA:29	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 29-20-02PROC. REF: AMM 29-20-02										
292011		AUXILIARY HYDRAULIC PUMP ASSEMBLY						Component	ATA:29	
PN:48-16-1	MOS/MSC	27-Feb-23	O/C	TSO 0						
SN:ELE0600A	HRS	9186.7		TSO 0						
	AFL	7047		TSO 0						
PROC. REF: AMM 29-20-01PROC. REF: AMM 29-20-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 29 - HYDRAULIC POWER										
292012		AUXILIARY HYDRAULIC PUMP						Component	ATA:29	
PN:6629201000-015	MOS/MSC	11-Jun-16	O/C							
SN:K0153	HRS	7630.1								
	AFL	5823								
PROC. REF: AMM 29-20-01PROC. REF: AMM 29-20-01										
292013		AUXILIARY HYDRAULIC PUMP ELECTRIC MOTOR						Component	ATA:29	
PN:6629201000-011	MOS/MSC	11-Jun-16	O/C	TSR 0						
SN:ELE0/094	HRS	7630.1		TSR 0						
	AFL	5823		TSR 0						
PROC. REF: AMM 29-20-04PROC. REF: AMM 29-20-04										
292025		AUXILIARY HYDRAULIC SYSTEM PRESSURE SWITCH						Component	ATA:29	
PN:6629101004-001	MOS/MSC	11-Jun-16	O/C	TSN 0						
SN:1226	HRS	7630.1		TSN 0						
	AFL	5823		TSN 0						
PROC. REF: AMM 29-30-03PROC. REF: AMM 29-30-03										
292401		AUXILIARY HYDRAULIC PRESSURE CHECK VALVE						Component	ATA:29	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
293001		GROUND SERVICE CONTROL BOX						Component	ATA:29	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 29-30-01PROC. REF: AMM 29-30-01										
293011		HYDRAULIC PRESSURE TRANSDUCER						Component	ATA:29	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 29-30-04PROC. REF: AMM 29-30-04										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 29 - HYDRAULIC POWER										
D2910017	MAIN HYDRAULIC FILTER MANIFOLD ELEMENTS - REPLACE								Service	ATA:29
	MOS/MSC	06-Jul-21	-							
	HRS	8631.2								
	AFL	6618								
PROC. REF: AMM 29-10-03PROC. REF: AMM 29-10-03										
D2910018	MAIN HYDRAULIC FILTER MANIFOLD ELEMENTS - REPLACE								Service	ATA:29
	MOS	28-Jul-25								
	HRS	9780.4	300		10080.4		57.3			
	AFL	7454								
PROC. REF: AMM 29-10-03PROC. REF: AMM 29-10-03										
H2920002 ^S	HYDRAULIC SYSTEM GROUND SERVICE LEDS - PERFORM FUNCTIONAL TEST								Service	ATA:29
	MOS	09-Mar-01	48							
	HRS	0	1200							
	AFL	0								
PROC. REF: AMM 29-30-00PROC. REF: AMM 29-30-00										
O2910005	AUXILIARY HYDRAULIC FILTER MANIFOLD ELEMENTS - REPLACE								Service	ATA:29
	MOS	19-May-22						LIFE LIMIT		
	HRS	8995.3	2400		11395.3		1372.2			
	AFL	6902								
PROC. REF: AMM 29-20-02PROC. REF: AMM 29-20-02										
T2910026 ^S	RELIEF FUNCTION OF THE PRESSURIZATION CONTROL MODULE - PERFORM FUNCTIONAL TEST								Service	ATA:29
	MOS	09-Mar-01	48							
	HRS	0	1200							
	AFL	0								
PROC. REF: AMM 29-10-06PROC. REF: AMM 29-10-06										

PKG:13

PKG:14

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 29 - HYDRAULIC POWER

Y2910001	^S	HYDRAULIC COMPONENTS AND ASSOCIATED PLUMBING (AFT OF FUSELAGE FUEL CELL, FS 495 TO FS 512) - PERFORM VISUAL INSPECTION						Service	ATA:29
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PKG:14									
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									

Y2910002	^S	HYDRAULIC COMPONENTS AND ASSOCIATED PLUMBING (WHEEL WELL AND FORWARD AREA OF REAR SPAR) - PERFORM VISUAL INSPECTION						Service	ATA:29
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PKG:17									
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									

Y2910003	^S	HYDRAULIC COMPONENTS AND ASSOCIATED PLUMBING (AFT AREA OF REAR SPAR) - PERFORM VISUAL INSPECTION						Service	ATA:29
	MOS	25-Nov-19	96						
	HRS	8177.7	2400						
	AFL	6303							
PKG:19									
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									

Y2920001	^S	AUXILIARY HYDRAULIC SYSTEM - PERFORM OPERATIONAL CHECK						Service	ATA:29
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PKG:13									
PROC. REF: AMM 29-20-00PROC. REF: AMM 29-20-00									

ATA 30 - ICE AND RAIN PROTECTION

301006		ANTI-ICE VERTICAL STABILIZER RELAY PANEL						Component	ATA:30
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN	0				
SN:UNKNOWN	HRS	0		TSN	0				
	AFL	0		TSN	0				
PROC. REF: AMM 30-10-06PROC. REF: AMM 30-10-06									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 30 - ICE AND RAIN PROTECTION									
301010 LEFT HORIZONTAL STABILIZER CONTROL (MT47) SENSOR Component ATA:30									
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-10-05PROC. REF: AMM 30-10-05									
301011 RIGHT HORIZONTAL STABILIZER CONTROL (MT46) SENSOR Component ATA:30									
PN:662100000-059	MOS/MSC	03-Jun-06	O/C						
SN:UNKNOWN	HRS	4546.3							
	AFL	3481							
PROC. REF: AMM 30-10-05PROC. REF: AMM 30-10-05									
301051 LEFT ANTI-ICE (2.0 DIAMETER) CHECK VALVE Component ATA:30									
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-10-02PROC. REF: AMM 30-10-02									
301052 RIGHT ANTI-ICE (2.0 DIAMETER) CHECK VALVE Component ATA:30									
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-10-02PROC. REF: AMM 30-10-02									
301063 LEFT ANTI-ICE PRESSURE REGULATING SHUTOFF VALVE Component ATA:30									
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-10-01PROC. REF: AMM 30-10-01									
301064 RIGHT ANTI-ICE PRESSURE REGULATING SHUTOFF VALVE Component ATA:30									
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-10-01PROC. REF: AMM 30-10-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 30 - ICE AND RAIN PROTECTION										
301065		LEFT ANTI-ICE SHUTTLE VALVE						Component	ATA:30	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 49-70-06, AMM 30-10-08PROC. REF: AMM 49-70-06, AMM 30-10-08										
301066		RIGHT ANTI-ICE SHUTTLE VALVE						Component	ATA:30	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 30-10-08PROC. REF: AMM 30-10-08										
301240		ANTI-ICE MANIFOLD ASSEMBLY						Component	ATA:30	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 30-10-07PROC. REF: AMM 30-10-07										
302001		NO. 1 NACELLE INLET ANTI-ICE SHUTOFF VALVE						Component	ATA:30	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 30-20-01PROC. REF: AMM 30-20-01										
302002		NO. 2 NACELLE INLET ANTI-ICE SHUTOFF VALVE						Component	ATA:30	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 30-20-01PROC. REF: AMM 30-20-01										
302013		NO. 1 NACELLE ANTI-ICE PRESSURE SWITCH						Component	ATA:30	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 30-20-02PROC. REF: AMM 30-20-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 30 - ICE AND RAIN PROTECTION										
302014		NO. 2 NACELLE ANTI-ICE PRESSURE SWITCH						Component	ATA:30	
PN:7600020-1	MOS/MSC	27-Mar-23	O/C							
SN:5769TW	HRS	9209.1								
	AFL	7060								
PROC. REF: AMM 30-20-02PROC. REF: AMM 30-20-02										
303501		LEFT NOSE RELAY BOX						Component	ATA:30	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 30-30-01PROC. REF: AMM 30-30-01										
303510		RIGHT NOSE RELAY BOX						Component	ATA:30	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 30-30-01PROC. REF: AMM 30-30-01										
304021		WINDSHIELD ANTI-ICE CONTROLLER						Component	ATA:30	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 30-40-01PROC. REF: AMM 30-40-01										
304060		NO. 1 WING SURFACE TEMPERATURE SENSOR						Component	ATA:30	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 30-10-03PROC. REF: AMM 30-10-03										
304061		NO. 2 WING SURFACE TEMPERATURE SENSOR						Component	ATA:30	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 30-10-03PROC. REF: AMM 30-10-03										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 30 - ICE AND RAIN PROTECTION										
304062		NO. 3 WING SURFACE TEMPERATURE SENSOR						Component	ATA:30	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 30-10-03PROC. REF: AMM 30-10-03										
304063		NO. 4 WING SURFACE TEMPERATURE SENSOR						Component	ATA:30	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 30-10-03PROC. REF: AMM 30-10-03										
308005		ICE DETECTION PROBE						Component	ATA:30	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 30-80-01PROC. REF: AMM 30-80-01										
A3020000 ^S		** NACELLE ANTI-ICE SYSTEM - PERFORM FUNCTIONAL TEST						Service	ATA:30	
	MOS	09-Mar-01	48					AIRWORTHINESS		
	HRS	0	1200							
	AFL	0								
PROC. REF: AMM 30-20-00PROC. REF: AMM 30-20-00										
A3030000 ^S		** PITOT-STATIC HEAT SYSTEM - PERFORM OPERATIONAL CHECK						Service	ATA:30	
	MOS	25-Nov-19	96					AIRWORTHINESS		
	HRS	8177.7	2400							
	AFL	6303								
PROC. REF: AMM 30-30-00PROC. REF: AMM 30-30-00										
AC3010006		** ANTI-ICE MANIFOLD - PERFORM BORESCOPE INSPECTION						Service	ATA:30	
	MOS	21-Aug-25						AIRWORTHINESS		
	HRS	9809.8	600	10409.8			386.7			
	AFL	7471								
PROC. REF: AMM 30-10-07PROC. REF: AMM 30-10-07										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 30 - ICE AND RAIN PROTECTION										
H3010000 ^S	** WING/STAB ANTI-ICE SWITCH - PERFORM OPERATIONAL CHECK								Service	ATA:30
	MOS	02-Aug-24	24					AIRWORTHINESS		
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 30-10-00PROC. REF: AMM 30-10-00										
PKG:7										
T3040000 ^S	** WINDSHIELD ANTI-ICE - PERFORM FUNCTIONAL TEST OF THE WINDSHIELD ANTI-ICE SYSTEM								Service	ATA:30
	MOS	02-Aug-24	24					AIRWORTHINESS		
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 30-40-00PROC. REF: AMM 30-40-00										
PKG:7										
Y3010007 ^S	WING ANTI-ICE PICCOLO TUBE - PERFORM DETAILED VISUAL INSPECTION FOR CRACKS AT W.S. 43 AND W.S. 176.								Service	ATA:30
	MOS	02-Aug-24	24							
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
PKG:10										
Y3080000 ^S	ICE DETECTION SYSTEM - PERFORM FUNCTIONAL TEST								Service	ATA:30
	MOS	09-Mar-01	48							
	HRS	0	1200							
	AFL	0								
PROC. REF: AMM 30-80-00PROC. REF: AMM 30-80-00										
PKG:13										
Z3020005	* NO. 1 ENGINE INLET ANTI-ICE TUBE ASSEMBLY FROM THE AFT INLET BULKHEAD CONNECTION POINT FORWARD TO SPRAY RING CONNECTION, PERFORM DETAILED VISUAL/BORESCOPE INSPECTION OF THE WELDS INSIDE AND OUTSIDE OF THE TUBE AT BOTH FORWARD AND AFT ENDS.								Service	ATA:30
	MOS	28-Jul-25						AIRWORTHINESS		
	HRS	9780.4	250		10030.4		7.3			
	AFL	7454								
PROC. REF: AMM 30-20-00PROC. REF: AMM 30-20-00										

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 30 - ICE AND RAIN PROTECTION									
Z3020005	* NO. 2 ENGINE INLET ANTI-ICE TUBE ASSEMBLY FROM THE AFT INLET BULKHEAD CONNECTION POINT FORWARD TO SPRAY RING CONNECTION, PERFORM DETAILED VISUAL/BORESCOPE INSPECTION OF THE WELDS INSIDE AND OUTSIDE OF THE TUBE AT BOTH FORWARD AND AFT ENDS.							Service	ATA:30
	MOS	28-Jul-25						AIRWORTHINESS	
	HRS	9780.4	250		10030.4		7.3		
	AFL	7454							
PROC. REF: AMM 30-20-00PROC. REF: AMM 30-20-00									
Z3020006	NO. 1 ENGINE INLET ANTI-ICE TUBE ASSEMBLY FROM THE AFT INLET BULKHEAD CONNECTION POINT FORWARD TO SPRAY RING CONNECTION, PERFORM DETAILED VISUAL/BORESCOPE INSPECTION OF THE WELDS INSIDE AND OUTSIDE OF THE TUBE AT BOTH FORWARD AND AFT ENDS							Service	ATA:30
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
PROC. REF: AMM 30-20-00PROC. REF: AMM 30-20-00									
Z3020006	NO. 2 ENGINE INLET ANTI-ICE TUBE ASSEMBLY FROM THE AFT INLET BULKHEAD CONNECTION POINT FORWARD TO SPRAY RING CONNECTION, PERFORM DETAILED VISUAL/BORESCOPE INSPECTION OF THE WELDS INSIDE AND OUTSIDE OF THE TUBE AT BOTH FORWARD AND AFT ENDS							Service	ATA:30
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
PROC. REF: AMM 30-20-00PROC. REF: AMM 30-20-00									
ATA 31 - INDICATING/RECORDING SYSTEMS									
311001	PILOT CIRCUIT BREAKER PANEL ASSY							Component	ATA:31
PN:PN	MOS/MSC	09-Mar-01	O/C		TSN 0				
SN:UNKNOWN	HRS	0			TSN 0				
	AFL	0			TSN 0				
PROC. REF: AMM 24-60-01PROC. REF: AMM 24-60-01									
311005	COPILOT CIRCUIT BREAKER PANEL ASSY							Component	ATA:31
PN:PN	MOS/MSC	09-Mar-01	O/C		TSN 0				
SN:UNKNOWN	HRS	0			TSN 0				
	AFL	0			TSN 0				
PROC. REF: AMM 24-60-01PROC. REF: AMM 24-60-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 31 - INDICATING/RECORDING SYSTEMS										
311601		GEAR UP/DOWN SWITCH						Component		ATA:31
PN:A3-1295	MOS/MSC	12-Aug-15	O/C							
SN:UNKNOWN	HRS	7535.1								
	AFL	5764								
PROC. REF: AMM 32-30-02PROC. REF: AMM 32-30-02										
311805		ENGINE FUEL CONTROL PANEL						Component		ATA:31
PN:4576108500-023	MOS/MSC	20-Jan-05	O/C							
SN:MRP645048-01	HRS	3272.32								
	AFL	2494								
PROC. REF: AMM 31-11-05PROC. REF: AMM 31-11-05										
311806		ENGINE/FUEL CONTROL PANEL OVERLAY						Component		ATA:31
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
311906		FORWARD QUADRANT SWITCH PANEL OVERLAY						Component		ATA:31
PN:7631208500-015	MOS/MSC	12-Aug-15	O/C	TSN 173						
SN:UNKNOWN	HRS	7535.1		TSN 7535.1						
	AFL	5764		TSN 5764						
PROC. REF: AMM 31-11-04PROC. REF: AMM 31-11-04										
311907		RUDDER BOOST SWITCH						Component		ATA:31
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
312001		PILOTS DIGITAL CLOCK						Component		ATA:31
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-21-01PROC. REF: AMM 31-21-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 31 - INDICATING/RECORDING SYSTEMS									
312002 COPILOTS DIGITAL CLOCK									Component ATA:31
PN:M850-5V-LA	MOS/MSC	14-Dec-10	O/C	TSN 0					
SN:A5231	HRS	6457.2		TSN 0					
	AFL	4944		TSN 0					
PROC. REF: AMM 31-21-01PROC. REF: AMM 31-21-01									
312011 COPILOTS DAVTRON M850 DIGITAL CLOCK BATTERY									Component ATA:31
PN:E90	MOS	03-Feb-25	12	TSN 0	03-Feb-26		OVD	LIFE LIMIT	
SN:NA	HRS	9605.4		TSN 0					
	AFL	7333		TSN 0					
PROC. REF: AMM 31-21-02PROC. REF: AMM 31-21-02									
312012 PILOTS DAVTRON M850 DIGITAL CLOCK BATTERY									Component ATA:31
PN:E90	MOS	03-Feb-25	12	TSN 0	03-Feb-26		OVD	LIFE LIMIT	
SN:NA	HRS	9605.4		TSN 0					
	AFL	7333		TSN 0					
PROC. REF: AMM 31-21-02PROC. REF: AMM 31-21-02									
313001 FLIGHT DATA RECORDER									Component ATA:31
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
313001A DOWNLOAD FLIGHT DATA RECORDER									Service ATA:31
PN:PN	MOS/MSC	09-Mar-01	N/R					CUSTOMER CODE	
SN:UNKNOWN	HRS	0							
	AFL	0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
313003 FDR ACCELEROMETER									Component ATA:31
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 31 - INDICATING/RECORDING SYSTEMS										
313010		HOBBS METER						Component		ATA:31
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
313018		INERTIA, FDR SWITCH						Component		ATA:31
PN:PN	MOS/MSC	09-Mar-01	A/R	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
314001		SELCAL DECODER						Component		ATA:31
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
314011		NO. 1 DATA ACQUISITION (DAU) UNIT						Component		ATA:31
PN:7013348-931	MOS/MSC	12-Aug-15	O/C							
SN:00013220	HRS	7535.1								
	AFL	5764								
PROC. REF: AMM 31-42-01PROC. REF: AMM 31-42-01										
314012		NO. 2 DATA ACQUISITION (DAU) UNIT						Component		ATA:31
PN:7013348-931	MOS/MSC	15-Nov-05	O/C							
SN:00063567	HRS	4035.07								
	AFL	3047								
PROC. REF: AMM 31-42-01PROC. REF: AMM 31-42-01										
314023		NO. 1 INTEGRATED AVIONICS (IC-600) COMPUTER						Component		ATA:31
PN:7017000-82222	MOS/MSC	17-Dec-15	O/C							
SN:02065544	HRS	7546								
	AFL	5771								
PROC. REF: AMM 31-41-01PROC. REF: AMM 31-41-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 31 - INDICATING/RECORDING SYSTEMS										
314024		NO. 2 INTEGRATED AVIONICS (IC-600) COMPUTER						Component	ATA:31	
PN:7017000-82222	MOS/MSC	23-Nov-21	O/C							
SN:98041571	HRS	8770.6								
	AFL	6752								
PROC. REF: AMM 31-41-01PROC. REF: AMM 31-41-01										
314051		NO. 1 CENTRAL COMPUTING IM-600 MEMORY MODULE						Component	ATA:31	
PN:7025973-04214	MOS/MSC	17-Feb-05	O/C							
SN:01080971	HRS	3300.2								
	AFL	2515								
PROC. REF: AMM 31-41-02PROC. REF: AMM 31-41-02										
314052		NO. 2 CENTRAL COMPUTING IM-600 MEMORY MODULE						Component	ATA:31	
PN:7025973-04214	MOS/MSC	17-Feb-05	O/C							
SN:01080922	HRS	3300.2								
	AFL	2515								
PROC. REF: AMM 31-41-02PROC. REF: AMM 31-41-02										
315001		CREW WARNING PANEL ASSEMBLY						Component	ATA:31	
PN:6631508501-001	MOS/MSC	17-Feb-05	O/C	TSN 0						
SN:357	HRS	3300.2		TSN 0						
	AFL	2515		TSN 0						
PROC. REF: AMM 31-51-01PROC. REF: AMM 31-51-01										
316001		NO. 1 DU870 COMPUTER						Component	ATA:31	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-60-01PROC. REF: AMM 31-60-01										
316002		NO. 2 DU870 COMPUTER						Component	ATA:31	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-60-01PROC. REF: AMM 31-60-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 31 - INDICATING/RECORDING SYSTEMS										
316003		NO. 3 DU870 COMPUTER						Component	ATA:31	
PN:7014300-901	MOS/MSC	05-Jan-26	O/C							
SN:050E648	HRS	9987.5								
	AFL	7596								
PROC. REF: AMM 31-60-01PROC. REF: AMM 31-60-01										
316004		NO. 4 DU870 COMPUTER						Component	ATA:31	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-60-01PROC. REF: AMM 31-60-01										
316005		PILOT EFIS DISPLAY CONTROLLER						Component	ATA:31	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-60-02PROC. REF: AMM 31-60-02										
316006		COPILOT EFIS DISPLAY CONTROLLER						Component	ATA:31	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-60-02PROC. REF: AMM 31-60-02										
316007		PILOT NO. 1 MULTIFUNCTION DISPLAY CONTROLLER BEZEL						Component	ATA:31	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-60-01PROC. REF: AMM 31-60-01										
316008		PILOT NO. 2 MULTIFUNCTION DISPLAY CONTROLLER BEZEL						Component	ATA:31	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-60-01PROC. REF: AMM 31-60-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 31 - INDICATING/RECORDING SYSTEMS

316009		COPILOT NO. 1 MULTIFUNCTION DISPLAY CONTROLLER BEZEL						Component	ATA:31
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 31-60-01PROC. REF: AMM 31-60-01									

316010		COPILOT NO. 2 MULTIFUNCTION DISPLAY CONTROLLER BEZEL						Component	ATA:31
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 31-60-01PROC. REF: AMM 31-60-01									

316091		AFIS DATA TRANSFER UNIT						Component	ATA:31
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

B310000^S		** INDICATING/RECORDING SYSTEM - PERFORM OPERATIONAL CHECK						Service	ATA:31
	MOS	02-Aug-24	24					AIRWORTHINESS	
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 31-00-00PROC. REF: AMM 31-00-00									

PKG:7

ATA 32 - LANDING GEAR

320041		LEFT MAIN LANDING GEAR UPPER LINK PIN						Component	ATA:32
PN:PN	MOS	09-Mar-01		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0	10000	TSN 0		10000	2384		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									

320042		RIGHT MAIN LANDING GEAR UPPER LINK PIN						Component	ATA:32
PN:PN	MOS	09-Mar-01		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0	10000	TSN 0		10000	2384		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 32 - LANDING GEAR										
320043		LEFT MAIN LANDING GEAR LOWER LINK PIN						Component	ATA:32	
PN:PN	MOS	09-Mar-01		TSN 0				AIRWORTHINESS		
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0	10000	TSN 0	10000		2384			
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01										
320044		RIGHT MAIN LANDING GEAR LOWER LINK PIN						Component	ATA:32	
PN:PN	MOS	09-Mar-01		TSN 0				AIRWORTHINESS		
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0	10000	TSN 0	10000		2384			
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01										
320051		LEFT MAIN LANDING GEAR PISTON PIN						Component	ATA:32	
PN:PN	MOS	09-Mar-01		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0	10000	TSN 0	10000		2384			
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01										
320052		RIGHT MAIN LANDING GEAR PISTON PIN						Component	ATA:32	
PN:PN	MOS	09-Mar-01		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0	10000	TSN 0	10000		2384			
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01										
320061		LEFT MAIN LANDING GEAR ACTUATOR PISTON						Component	ATA:32	
PN:PN	MOS/MSC	09-Mar-01	H/T	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01										
320062		RIGHT MAIN LANDING GEAR ACTUATOR PISTON						Component	ATA:32	
PN:4532101000V72-002	MOS/MSC	09-Mar-01	H/T	TSN 0						
SN:H1153	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 32 - LANDING GEAR										
320071	LEFT MAIN LANDING GEAR ACTUATOR CYLINDER								Component	ATA:32
PN:4532101000V76-001	MOS/MSC	09-Mar-01	H/T	TSN 0						
SN:H0155	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01										
320072	RIGHT MAIN LANDING GEAR ACTUATOR CYLINDER								Component	ATA:32
PN:4532101000V72-002	MOS/MSC	09-Mar-01	H/T	TSN 0						
SN:H1153	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01										
320081	LEFT MAIN LANDING GEAR ACTUATOR END CAP								Component	ATA:32
PN:200-0303-001	MOS/MSC	02-Aug-24	H/T	TSN 0						
SN:UNKNOWN	HRS	9525.7		TSN 0						
	AFL	7276		TSN 0						
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01										
320082	RIGHT MAIN LANDING GEAR ACTUATOR END CAP								Component	ATA:32
PN:200-0303-001	MOS/MSC	02-Aug-24	H/T	TSN 0						
SN:UNKNOWN	HRS	9525.7		TSN 0						
	AFL	7276		TSN 0						
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01										
320091	LEFT MAIN LANDING GEAR ACTUATOR HOUSING								Component	ATA:32
PN:200-0304-001	MOS/MSC	19-Dec-10	H/T	TSN 0						
SN:H1704	HRS	6457.2		TSN 0						
	AFL	4944		TSN 0						
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01										
320092	RIGHT MAIN LANDING GEAR ACTUATOR HOUSING								Component	ATA:32
PN:4532101000V72-002	MOS/MSC	09-Mar-01	H/T	TSN 0						
SN:H1153	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 32 - LANDING GEAR										
321001		LEFT MAIN LANDING GEAR STRUT						Component	ATA:32	
PN:200-0200-013	MOS		30-Mar-21					LIFE LIMIT		
SN:H0584	HRS		8414.4		TSN 2110.4, TSO 0					
	AFL		6463	10000	TSN 1409, TSO 0	15054	7438			
Special Properties: RII ITEM PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01										
321002		RIGHT MAIN LANDING GEAR STRUT						Component	ATA:32	
PN:200-0200-014	MOS		30-Mar-21					LIFE LIMIT		
SN:H1593	HRS		8414.4		TSN 2110.4					
	AFL		6463	10000	TSN 1409	15054	7438			
Special Properties: RII ITEM PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01										
321011		LEFT MAIN LANDING GEAR SHOCK STRUT CYLINDER						Component	ATA:32	
PN:200-0201-009	MOS/MSC		30-Mar-21	H/T						
SN:H0727	HRS		8414.4		TSN 2110.4					
	AFL		6463		TSN 1409					
PROC. REF: NDT PART 4/32-10-01, NDT PART 4/32-10-00, AMM 32-10-01PROC. REF: NDT PART 4/32-10-01, NDT PART 4/32-10-00, AMM 32-10-01										
321012		RIGHT MAIN LANDING GEAR SHOCK STRUT CYLINDER						Component	ATA:32	
PN:200-0201-010	MOS/MSC		30-Mar-21	H/T						
SN:H0755	HRS		8414.4		TSN 2110.4					
	AFL		6463		TSN 1409					
PROC. REF: NDT PART 4/32-10-01, NDT PART 4/32-10-00, AMM 32-10-01PROC. REF: NDT PART 4/32-10-01, NDT PART 4/32-10-00, AMM 32-10-01										
321025		LEFT MAIN LANDING GEAR ACTUATOR UPPER PIN						Component	ATA:32	
PN:200-0325-101	MOS/MSC		24-Jun-19	H/T	TSN 0					
SN:H2409	HRS		8101.1		TSN 0					
	AFL		6233		TSN 0					
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01										
321026		RIGHT MAIN LANDING GEAR ACTUATOR UPPER PIN						Component	ATA:32	
PN:200-0325-101	MOS/MSC		24-Jun-19	H/T	TSN 0					
SN:HER08U/5030	HRS		8101.1		TSN 0					
	AFL		6233		TSN 0					
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
321037 LEFT MAIN LANDING GEAR ACTUATOR LOWER PIN									Component ATA:32
PN:200-0217-101	MOS/MSC	24-Jun-19	H/T	TSN 0					
SN:H5000	HRS	8101.1		TSN 0					
	AFL	6233		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
321038 RIGHT MAIN LANDING GEAR ACTUATOR LOWER PIN									Component ATA:32
PN:200-0217-101	MOS/MSC	24-Jun-19	H/T	TSN 0					
SN:HER08U5014	HRS	8101.1		TSN 0					
	AFL	6233		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
321049 LEFT MAIN LANDING GEAR AXLE BEAM									Component ATA:32
PN:200-0203-001	MOS/MSC	08-Sep-12	H/T						
SN:H0331	HRS	6989.1							
	AFL	5335		TSN 5311					
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
321050 RIGHT MAIN LANDING GEAR AXLE BEAM									Component ATA:32
PN:200-0203-001	MOS/MSC	08-Sep-12	H/T						
SN:H0334	HRS	6989.1							
	AFL	5335		TSN 5311					
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
321061 LEFT MAIN LANDING GEAR SIDE-STAY ACTUATOR PIN									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
321062 RIGHT MAIN LANDING GEAR SIDE-STAY ACTUATOR PIN									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
321073 LEFT MAIN LANDING GEAR SIDE BRACE ACTUATOR DISPLACEMENT TUBE								Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
321074 RIGHT MAIN LANDING GEAR SIDE BRACE ACTUATOR DISPLACEMENT TUBE								Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
321085 LEFT FORWARD TRUNNION ASSEMBLY								Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
321086 RIGHT FORWARD TRUNNION ASSEMBLY								Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
321087 LEFT AFT TRUNNION ASSEMBLY								Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
321088 RIGHT AFT TRUNNION ASSEMBLY								Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
321101 LEFT FORWARD MAIN LANDING GEAR TRUNNION PIN									Component ATA:32
PN:200-0212-103	MOS	24-Jul-12						LIFE LIMIT	
SN:H0501	HRS	6961.3		TSN 2110.4					
	AFL	5311	10000	TSN 1409	13902		6286		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
321102 RIGHT FORWARD MAIN LANDING GEAR TRUNNION PIN									Component ATA:32
PN:200-0212-103	MOS	24-Jul-12						LIFE LIMIT	
SN:H0473	HRS	6961.3		TSN 2110.4					
	AFL	5311	10000	TSN 1409	13902		6286		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
321103 LEFT AFT MAIN LANDING GEAR TRUNNION PIN									Component ATA:32
PN:200-0213-103	MOS	24-Jul-12						LIFE LIMIT	
SN:H0364	HRS	6961.3		TSN 2110.4					
	AFL	5311	10000	TSN 1409	13902		6286		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
321104 RIGHT AFT MAIN LANDING GEAR TRUNNION PIN									Component ATA:32
PN:200-0213-103	MOS	24-Jul-12						LIFE LIMIT	
SN:H0338	HRS	6961.3		TSN 2110.4					
	AFL	5311	10000	TSN 1409	13902		6286		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
321111 LEFT FORWARD LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN									Component ATA:32
PN:4532103201-001	MOS/MSC	15-Dec-10	H/T	TSN 0					
SN:CM1882	HRS	6457.2		TSN 0					
	AFL	4944		TSN 0					
PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05									
321112 RIGHT FORWARD LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN									Component ATA:32
PN:4532103201-001	MOS/MSC	15-Dec-10	H/T	TSN 0					
SN:CM1113	HRS	6457.2		TSN 0					
	AFL	4944		TSN 0					
PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
321113 LEFT FORWARD UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN									Component ATA:32
PN:4532103201-001	MOS/MSC	15-Dec-10	H/T	TSN 0					
SN:CMI806	HRS	6457.2		TSN 0					
	AFL	4944		TSN 0					
PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05									
321114 RIGHT FORWARD UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN									Component ATA:32
PN:4532103201-001	MOS/MSC	15-Dec-10	H/T	TSN 0					
SN:CMI710	HRS	6457.2		TSN 0					
	AFL	4944		TSN 0					
PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05									
321117 LEFT AFT UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN									Component ATA:32
PN:4532103202-001	MOS/MSC	18-Dec-10	H/T	TSN 0					
SN:CMI371	HRS	6457.2		TSN 0					
	AFL	4944		TSN 0					
PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05									
321118 RIGHT AFT UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN									Component ATA:32
PN:4532103202-001	MOS/MSC	18-Dec-10	H/T	TSN 0					
SN:CMI363	HRS	6457.2		TSN 0					
	AFL	4944		TSN 0					
PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05									
321119 LEFT AFT LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN									Component ATA:32
PN:4532103203-001	MOS/MSC	18-Dec-10	H/T	TSN 0					
SN:CMI818	HRS	6457.2		TSN 0					
	AFL	4944		TSN 0					
PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05									
321120 RIGHT AFT LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN									Component ATA:32
PN:4532103203-001	MOS/MSC	18-Dec-10	H/T	TSN 0					
SN:CMI759	HRS	6457.2		TSN 0					
	AFL	4944		TSN 0					
PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
321201 LEFT MAIN LANDING GEAR OLEO ASSEMBLY									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
321202 RIGHT MAIN LANDING GEAR OLEO ASSEMBLY									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
321215 LEFT MAIN LANDING GEAR SHOCK STRUT PISTON									Component ATA:32
PN:PN	MOS	09-Mar-01		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0	10000	TSN 0	10000		2384		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
321216 RIGHT MAIN LANDING GEAR SHOCK STRUT PISTON									Component ATA:32
PN:PN	MOS	09-Mar-01		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0	10000	TSN 0	10000		2384		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
321227 LEFT MAIN LANDING GEAR SHOCK STRUT LINK									Component ATA:32
PN:PN	MOS	09-Mar-01		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0	10000	TSN 0	10000		2384		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
321228 RIGHT MAIN LANDING GEAR SHOCK STRUT LINK									Component ATA:32
PN:PN	MOS	09-Mar-01		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0	10000	TSN 0	10000		2384		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
321301 LEFT MAIN LANDING GEAR OUTBOARD DOOR									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 52-80-01PROC. REF: AMM 52-80-01									
321302 LEFT MAIN LANDING GEAR INBOARD DOOR									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 52-80-01PROC. REF: AMM 52-80-01									
321303 RIGHT MAIN LANDING GEAR INBOARD DOOR									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 52-80-01PROC. REF: AMM 52-80-01									
321304 RIGHT MAIN LANDING GEAR OUTBOARD DOOR									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 52-80-01PROC. REF: AMM 52-80-01									
321901 LEFT MAIN LANDING GEAR INBOARD DOOR ACTUATOR CAP SCREWS									Component ATA:32
PN:6632303003-003	MOS/MSC	13-Apr-07	O/C						
SN:0779	HRS	5383.5							
	AFL	4119							
PROC. REF: AMM 32-31-02PROC. REF: AMM 32-31-02									
321903 RIGHT MAIN LANDING GEAR INBOARD DOOR ACTUATOR CAP SCREWS									Component ATA:32
PN:7469-1	MOS/MSC	25-Jul-12	O/C	TSN 136, TSR 0					
SN:0004	HRS	6961.3		TSN 6961.3, TSR 0					
	AFL	5311		TSN 5311, TSR 0					
PROC. REF: AMM 32-31-02PROC. REF: AMM 32-31-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
322001^S NOSE LANDING GEAR STRUT ASSEMBLY Component ATA:32									
PN:4532230001-814	MOS	12-Feb-08		TSR 0				LIFE LIMIT	
SN:008	HRS	5965.9		TSR 0					
	AFL	4561	20000	TSN 4561, TSR 0					
PROC. REF: AMM 32-20-01PROC. REF: AMM 32-20-01									
322002 NOSE LANDING GEAR CYLINDER Component ATA:32									
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-32-01PROC. REF: AMM 32-32-01									
322003 NOSE LANDING GEAR PISTON Component ATA:32									
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-32-01PROC. REF: AMM 32-32-01									
322004 NOSE LANDING GEAR ACTUATOR BRACKET Component ATA:32									
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-32-01PROC. REF: AMM 32-32-01									
322005 NOSE LANDING GEAR FORK Component ATA:32									
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-32-01PROC. REF: AMM 32-32-01									
322011^S NOSE LANDING GEAR ACTUATOR ASSEMBLY Component ATA:32									
PN:6632201000-001	MOS	09-Mar-01		TSN 0				LIFE LIMIT	
SN:EFS210	HRS	0		TSN 0					
	AFL	0	20000	TSN 0					
PROC. REF: AMM 32-32-01PROC. REF: AMM 32-32-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
322061^S NOSE LANDING GEAR TRUNNION AXLE Component ATA:32									
PN:2342110-003	MOS	09-Mar-01		TSN 0				LIFE LIMIT	
SN:R153	HRS	0		TSN 0					
	AFL	0	20000	TSN 0					
PROC. REF: AMM 32-20-01PROC. REF: AMM 32-20-01									
322071^S LEFT NOSE LANDING GEAR TRUNNION PIN Component ATA:32									
PN:2342108-003	MOS	09-Mar-01		TSN 0				LIFE LIMIT	
SN:L016	HRS	0		TSN 0					
	AFL	0	20000	TSN 0					
PROC. REF: AMM 32-20-01PROC. REF: AMM 32-20-01									
322072^S RIGHT NOSE LANDING GEAR TRUNNION PIN Component ATA:32									
PN:2342108-003	MOS	09-Mar-01		TSN 0				LIFE LIMIT	
SN:L012	HRS	0		TSN 0					
	AFL	0	20000	TSN 0					
PROC. REF: AMM 32-20-01PROC. REF: AMM 32-20-01									
322095 LEFT NOSE LANDING GEAR DOOR Component ATA:32									
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 52-81-01PROC. REF: AMM 52-81-01									
322096 RIGHT NOSE LANDING GEAR DOOR Component ATA:32									
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 52-81-01PROC. REF: AMM 52-81-01									
322111 NOSE LANDING GEAR CHASSIS ASSEMBLY Component ATA:32									
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
322121 NOSE LANDING GEAR UPLOCK MECHANISM									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-32-02PROC. REF: AMM 32-32-02									
323001 LEFT MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY									Component ATA:32
PN:200-0300-003	MOS/MSC	02-Aug-24	H/T						
SN:H0134	HRS	9525.7							
	AFL	7276		TSN 7276					
Special Properties: RII ITEM									
323002 RIGHT MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY									Component ATA:32
PN:200-0300-004	MOS/MSC	02-Aug-24	H/T						
SN:H1188	HRS	9525.7							
	AFL	7276		TSN 7276					
Special Properties: RII ITEM									
323037 LEFT MAIN LANDING GEAR INBOARD DOOR UPLOCK MECHANISM									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-31-04PROC. REF: AMM 32-31-04									
323038 RIGHT MAIN LANDING GEAR INBOARD DOOR UPLOCK MECHANISM									Component ATA:32
PN:6632303004-006	MOS/MSC	08-Sep-12	O/C	TSR 31					
SN:0117	HRS	6989.1		TSR 0					
	AFL	5335		TSR 0					
PROC. REF: AMM 32-31-04PROC. REF: AMM 32-31-04									
323110 NOSE LANDING GEAR DOWN-LOCK SWITCH									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-60-05PROC. REF: AMM 32-60-05									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
323220 LEFT DOWN AND LOCKED SWITCH									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-60-02PROC. REF: AMM 32-60-02									
323221 RIGHT DOWN AND LOCKED SWITCH									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-60-02PROC. REF: AMM 32-60-02									
323305 LEFT MAIN LANDING GEAR ACTUATOR GIMBAL ASSEMBLY									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-31-06PROC. REF: AMM 32-31-06									
323306 RIGHT MAIN LANDING GEAR ACTUATOR GIMBAL ASSEMBLY									Component ATA:32
PN:PN-UNKNOWN	MOS/MSC	25-Jul-10	O/C						
SN:UNKNOWN	HRS	6330.6							
	AFL	4850							
PROC. REF: AMM 32-31-06PROC. REF: AMM 32-31-06									
323307 LEFT MAIN LANDING GEAR SHAFT GIMBAL ASSEMBLY									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-31-06PROC. REF: AMM 32-31-06									
323308 RIGHT MAIN LANDING GEAR SHAFT GIMBAL ASSEMBLY									Component ATA:32
PN:PN-UNKNOWN	MOS/MSC	25-Jul-10	O/C						
SN:UNKNOWN	HRS	6330.6							
	AFL	4850							
PROC. REF: AMM 32-31-06PROC. REF: AMM 32-31-06									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
323309 LEFT MAIN LANDING GEAR INBOARD DOOR GIMBAL BRACKET ASSEMBLY									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-31-06PROC. REF: AMM 32-31-06									
323310 RIGHT MAIN LANDING GEAR INBOARD DOOR GIMBAL BRACKET ASSEMBLY									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-31-06PROC. REF: AMM 32-31-06									
323735 CONTROL VALVE									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-30-01PROC. REF: AMM 32-30-01									
324001 NO. 1 MAIN LANDING GEAR WHEEL									Component ATA:32
PN:3-1545-1	MOS/MSC	27-Oct-25	O/C						
SN:2432	HRS	9906.2							
	AFL	7538							
PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02									
324001A NON DESTRUCTIVE TEST NO. 1 MAIN LANDING GEAR WHEEL									Service ATA:32
PN:3-1545-1	MOS/MSC	27-Oct-25	A/R						
SN:2432	HRS	9906.2							
	AFL	7538							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
324002 NO. 2 MAIN LANDING GEAR WHEEL									Component ATA:32
PN:3-1545-1	MOS/MSC	27-Oct-25	O/C						
SN:2483	HRS	9906.2							
	AFL	7538							
PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
324002A NON DESTRUCTIVE TEST NO. 2 MAIN LANDING GEAR WHEEL									Service ATA:32
PN:3-1545-1	MOS/MSC	27-Oct-25	A/R						
SN:2483	HRS	9906.2							
	AFL	7538							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
324003 NO. 3 MAIN LANDING GEAR WHEEL									Component ATA:32
PN:3-1545-1	MOS/MSC	27-Oct-25	O/C						
SN:3275	HRS	9906.2							
	AFL	7538							
PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02									
324003A NON DESTRUCTIVE TEST NO. 3 MAIN LANDING GEAR WHEEL									Service ATA:32
PN:3-1545-1	MOS/MSC	27-Oct-25	A/R						
SN:3275	HRS	9906.2							
	AFL	7538							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
324004 NO. 4 MAIN LANDING GEAR WHEEL									Component ATA:32
PN:3-1545-1	MOS/MSC	27-Oct-25	O/C						
SN:0831	HRS	9906.2							
	AFL	7538							
PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02									
324004A NON DESTRUCTIVE TEST NO. 4 MAIN LANDING GEAR WHEEL									Service ATA:32
PN:3-1545-1	MOS/MSC	27-Oct-25	A/R						
SN:0831	HRS	9906.2							
	AFL	7538							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
324005 NOSE GEAR WHEEL ASSEMBLY									Component ATA:32
PN:9544207-4	MOS/MSC	13-Oct-25	O/C						
SN:OCT07-2939	HRS	9885.1							
	AFL	7524							
PROC. REF: AMM 32-40-01PROC. REF: AMM 32-40-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 32 - LANDING GEAR										
324021		NO. 1 MAIN LANDING GEAR TIRE						Component	ATA:32	
PN:226K08-4	MOS/MSC	27-Oct-25	O/C	TSN 0						
SN:50750049	HRS	9906.2		TSN 0						
	AFL	7538		TSN 0						
PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02										
324022		NO. 2 MAIN LANDING GEAR TIRE						Component	ATA:32	
PN:226K08-4	MOS/MSC	27-Oct-25	O/C	TSN 0						
SN:50780770	HRS	9906.2		TSN 0						
	AFL	7538		TSN 0						
PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02										
324023		NO. 3 MAIN LANDING GEAR TIRE						Component	ATA:32	
PN:226K08-4	MOS/MSC	27-Oct-25	O/C	TSN 0						
SN:50780755	HRS	9906.2		TSN 0						
	AFL	7538		TSN 0						
PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02										
324024		NO. 4 MAIN LANDING GEAR TIRE						Component	ATA:32	
PN:226K08-4	MOS/MSC	27-Oct-25	O/C	TSN 0						
SN:50741022	HRS	9906.2		TSN 0						
	AFL	7538		TSN 0						
PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02										
324025		NOSE LANDING GEAR TIRE						Component	ATA:32	
PN:03-613-8	MOS/MSC	13-Oct-25	O/C	TSN 0						
SN:5041T00281	HRS	9885.1		TSN 0						
	AFL	7524		TSN 0						
PROC. REF: AMM 32-40-01PROC. REF: AMM 32-40-01										
324061		LEFT ANTI-SKID CONTROL VALVE						Component	ATA:32	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-41-07PROC. REF: AMM 32-41-07										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
324062 RIGHT ANTI-SKID CONTROL VALVE									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-07PROC. REF: AMM 32-41-07									
324066 LEFT ANTI-SKID SHUTOFF VALVE									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
324067 RIGHT ANTI-SKID SHUTOFF VALVE									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
324097 BRAKE CONTROL UNIT									Component ATA:32
PN:42-933-3	MOS/MSC	03-Jan-06	O/C						
SN:150	HRS	4160.77							
	AFL	3151							
PROC. REF: AMM 32-41-02PROC. REF: AMM 32-41-02									
324108 EMERGENCY PARKING BRAKE CHECK VALVE									Component ATA:32
PN:1C4124	MOS/MSC	19-Mar-05	O/C						
SN:UNKNOWN	HRS	3391.45							
	AFL	2574							
PROC. REF: AMM 32-42-09PROC. REF: AMM 32-42-09									
324109 EMERGENCY/PARK BRAKE VALVE									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-42-01PROC. REF: AMM 32-42-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 32 - LANDING GEAR										
324110		EMERGENCY/PARK BRAKE PRESSURE TRANSDUCER						Component	ATA:32	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-42-03PROC. REF: AMM 32-42-03										
324111		NO. 1 MAIN LANDING GEAR BRAKE ASSEMBLY						Component	ATA:32	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01										
324112		NO. 2 MAIN LANDING GEAR BRAKE ASSEMBLY						Component	ATA:32	
PN:6632401000-002	MOS/MSC	27-Aug-21	O/C							
SN:2262	HRS	8708.2								
	AFL	6691								
PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01										
324113		NO. 3 MAIN LANDING GEAR BRAKE ASSEMBLY						Component	ATA:32	
PN:6632401000-002	MOS/MSC	25-Nov-19	O/C	TSO 0						
SN:1975	HRS	8177.7		TSO 0						
	AFL	6303		TSO 0						
PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01										
324114		NO. 4 MAIN LANDING GEAR BRAKE ASSEMBLY						Component	ATA:32	
PN:2-1579-2	MOS/MSC	15-Jul-11	O/C	TSO 0						
SN:0917SB	HRS	6651.4		TSO 0						
	AFL	5089		TSO 0						
PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01										
324201		NO. 1 BRAKE SHUTTLE VALVE						Component	ATA:32	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-42-04PROC. REF: AMM 32-42-04										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 32 - LANDING GEAR										
324202		NO. 2 BRAKE SHUTTLE VALVE						Component	ATA:32	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-42-04PROC. REF: AMM 32-42-04										
324203		NO. 3 BRAKE SHUTTLE VALVE						Component	ATA:32	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-42-04PROC. REF: AMM 32-42-04										
324204		NO. 4 BRAKE SHUTTLE VALVE						Component	ATA:32	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-42-04PROC. REF: AMM 32-42-04										
324205		BRAKE SHUTTLE MODULE						Component	ATA:32	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-41-04PROC. REF: AMM 32-41-04										
324305		LEFT PILOT BRAKE TRANSDUCER						Component	ATA:32	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-41-03PROC. REF: AMM 32-41-03										
324306		RIGHT PILOT BRAKE TRANSDUCER						Component	ATA:32	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-41-03PROC. REF: AMM 32-41-03										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 32 - LANDING GEAR										
324610-1		LEFT INBOARD BRAKE SWIVEL						Component	ATA:32	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01										
324610-2		LEFT OUTBOARD BRAKE SWIVEL						Component	ATA:32	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01										
324611-1		RIGHT INBOARD BRAKE SWIVEL						Component	ATA:32	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01										
324611-2		RIGHT OUTBOARD BRAKE SWIVEL						Component	ATA:32	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01										
324701		NO. 1 BRAKE HYDRAULIC FUSE						Component	ATA:32	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-41-09PROC. REF: AMM 32-41-09										
324702		NO. 2 BRAKE HYDRAULIC FUSE						Component	ATA:32	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-41-09PROC. REF: AMM 32-41-09										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 32 - LANDING GEAR										
324703		NO. 3 BRAKE HYDRAULIC FUSE						Component	ATA:32	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-41-09PROC. REF: AMM 32-41-09										
324704		NO. 4 BRAKE HYDRAULIC FUSE						Component	ATA:32	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-41-09PROC. REF: AMM 32-41-09										
324711		NO. 1 WHEEL SPEED TRANSDUCER						Component	ATA:32	
PN:140-183	MOS/MSC	17-Nov-20	O/C							
SN:3456	HRS	8301.3								
	AFL	6392								
PROC. REF: AMM 32-41-10PROC. REF: AMM 32-41-10										
324712		NO. 2 WHEEL SPEED TRANSDUCER						Component	ATA:32	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-41-10PROC. REF: AMM 32-41-10										
324713		NO. 3 WHEEL SPEED TRANSDUCER						Component	ATA:32	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-41-10PROC. REF: AMM 32-41-10										
324714		NO. 4 WHEEL SPEED TRANSDUCER						Component	ATA:32	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-41-10PROC. REF: AMM 32-41-10										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
324721 (MT56) BRAKE PRESSURE TRANSDUCER									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-08PROC. REF: AMM 32-41-08									
324722 (MT57) BRAKE PRESSURE TRANSDUCER									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-08PROC. REF: AMM 32-41-08									
324723 (MT58) BRAKE PRESSURE TRANSDUCER									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-08PROC. REF: AMM 32-41-08									
324724 (MT59) BRAKE PRESSURE TRANSDUCER									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-08PROC. REF: AMM 32-41-08									
324801 EMERGENCY/PARK BRAKE FUSE									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-42-07PROC. REF: AMM 32-42-07									
324805 EMERGENCY/PARK BRAKE ACCUMULATOR									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-42-02PROC. REF: AMM 32-42-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
325007 NOSE WHEEL STEERING FILTER BOX (P41)									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-50-06PROC. REF: AMM 32-50-06									
325011 NOSE WHEEL STEERING SERVO ACTUATOR									Component ATA:32
PN:JR5208C	MOS/MSC	13-Feb-08	O/C	TSR 4					
SN:A0437	HRS	5967.8		TSR 0					
	AFL	4562		TSR 0					
PROC. REF: AMM 32-50-02PROC. REF: AMM 32-50-02									
325021 NOSE WHEEL STEERING GEARBOX									Component ATA:32
PN:2W3201D	MOS/MSC	29-Oct-06	O/C						
SN:C0347	HRS	4933.32							
	AFL	3789							
PROC. REF: AMM 32-50-03PROC. REF: AMM 32-50-03									
325031 NOSE WHEEL STEERING COMPUTER									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-50-01PROC. REF: AMM 32-50-01									
325035 NOSE WHEEL STEERING POWER SUPPLY									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
325041 LEFT NOSE WHEEL STEERING TRANSDUCER									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-50-04PROC. REF: AMM 32-50-04									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
325042 RIGHT NOSE WHEEL STEERING TRANSDUCER									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-50-04PROC. REF: AMM 32-50-04									
325051^S NOSE LANDING GEAR ACTUATOR UPPER PIN									Component ATA:32
PN:4532302043-007	MOS	09-Mar-01		TSN 0				LIFE LIMIT	
SN:132	HRS	0		TSN 0					
	AFL	0	20000	TSN 0					
PROC. REF: AMM 32-32-01PROC. REF: AMM 32-32-01									
326000 NOSE LANDING GEAR WIRE HARNESS									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
326104 NOSE LANDING GEAR SQUAT/WOW SWITCH (S178)									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-50-09PROC. REF: AMM 32-50-09									
326105 NO. 1 MAIN GEAR SQUAT SWITCH									Component ATA:32
PN:444EN2-R	MOS/MSC	18-Oct-22	O/C	TSN 0					
SN:UNKNOWN	HRS	9133.2		TSN 0					
	AFL	7007		TSN 0					
PROC. REF: AMM 32-60-09PROC. REF: AMM 32-60-09									
326106 NO. 2 MAIN GEAR SQUAT SWITCH									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-60-09PROC. REF: AMM 32-60-09									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 32 - LANDING GEAR										
326107	NO. 3 MAIN GEAR SQUAT SWITCH								Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-60-09PROC. REF: AMM 32-60-09										
326108	NO. 4 MAIN GEAR SQUAT SWITCH								Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-60-09PROC. REF: AMM 32-60-09										
326115	SQUAT SWITCH RELAY BOX P21								Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-60-08PROC. REF: AMM 32-60-08										
A3230001 ^S	** LANDING GEAR - PERFORM EMERGENCY GEAR EXTENSION FUNCTIONAL TEST								Service	ATA:32
	MOS	02-Aug-24	24					AIRWORTHINESS		
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 32-33-00PROC. REF: AMM 32-33-00										
A3240005 ^S	** BRAKE HYDRAULIC FUSES - PERFORM FUNCTIONAL TEST								Service	ATA:32
	MOS	09-Mar-01	48					AIRWORTHINESS		
	HRS	0	1200							
	AFL	0								
PROC. REF: AMM 32-41-09PROC. REF: AMM 32-41-09										
A3240006 ^S	** BRAKE SHUTTLE MODULE - PERFORM FUNCTIONAL TEST								Service	ATA:32
	MOS	09-Mar-01	48					AIRWORTHINESS		
	HRS	0	1200							
	AFL	0								
PROC. REF: AMM 32-41-04PROC. REF: AMM 32-41-04										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 32 - LANDING GEAR

A3240007 ^S		** BRAKE SHUTTLE VALVES - PERFORM FUNCTIONAL TEST						Service	ATA:32
	MOS	25-Nov-19	96					AIRWORTHINESS	
	HRS	8177.7	2400						
	AFL	6303							
PKG:23									
PROC. REF: AMM 32-42-04PROC. REF: AMM 32-42-04									

A3240009 ^S		** BRAKE PRESSURE TRANSDUCERS - PERFORM FUNCTIONAL TEST						Service	ATA:32
	MOS	09-Mar-01						AIRWORTHINESS	
	HRS	0	4800						
	AFL	0							
PKG:25									
PROC. REF: AMM 32-41-08PROC. REF: AMM 32-41-08									

AA3220018		LEFT MAIN LANDING GEAR STRUT - PERFORM SPECIAL DETAILED INSPECTION						Service	ATA:32
PN:200-0200-013	MOS	30-Mar-21	96		30-Mar-29		1142 d		
SN:H0584	HRS	8414.4							
	AFL	6463	6600		13063		5447		
PROC. REF: NDT PART 7/32-10-01, NDT PART 7/32-10-03, NDT PART 7/32-10-04, NDT PART 8/32-10-02, NDT PART 7/32-10-05, NDT PART 7/32-10-06, NDT PART 8/32-10-01, NDT PART 8/32-10-03PROC. REF: NDT PART 7/32-10-01, NDT PART 7/32-10-03, NDT PART 7/32-10-04, NDT PART 8/32-10-02, NDT PART 7/32-10-05, NDT PART 7/32-10-06, NDT PART 8/32-10-01, NDT PART 8/32-10-03									

AA3220018		RIGHT MAIN LANDING GEAR STRUT - PERFORM SPECIAL DETAILED INSPECTION						Service	ATA:32
PN:200-0200-014	MOS	30-Mar-21	96		30-Mar-29		1142 d		
SN:H1593	HRS	8414.4							
	AFL	6463	6600		13063		5447		
PROC. REF: NDT PART 7/32-10-01, NDT PART 7/32-10-03, NDT PART 7/32-10-04, NDT PART 8/32-10-02, NDT PART 7/32-10-05, NDT PART 7/32-10-06, NDT PART 8/32-10-01, NDT PART 8/32-10-03PROC. REF: NDT PART 7/32-10-01, NDT PART 7/32-10-03, NDT PART 7/32-10-04, NDT PART 8/32-10-02, NDT PART 7/32-10-05, NDT PART 7/32-10-06, NDT PART 8/32-10-01, NDT PART 8/32-10-03									

AA3220111		LEFT MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY - DISASSEMBLE ACTUATOR AND PERFORM DETAILED VISUAL INSPECTION						Service	ATA:32
	MOS	30-Mar-21	96		30-Mar-29		1142 d		
	HRS	8414.4							
	AFL	6463	10000		16463		8847		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
AA3220111	RIGHT MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY - DISASSEMBLE ACTUATOR AND PERFORM DETAILED VISUAL INSPECTION							Service	ATA:32
	MOS	30-Mar-21	96		30-Mar-29		1142 d		
	HRS	8414.4							
	AFL	6463	10000		16463		8847		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
AE3220151	LEFT - MAIN LANDING GEAR STRUT ASSEMBLY REBOUND RING - REPLACE.							Service	ATA:32
	MOS	EFF	96		30-Mar-29 * (M)		1142 d		
	HRS								
	AFL								
PROC. REF: AMM 32-31-02PROC. REF: AMM 32-31-02									
AE3220151	RIGHT - MAIN LANDING GEAR STRUT ASSEMBLY REBOUND RING - REPLACE.							Service	ATA:32
	MOS	EFF	96		30-Mar-29 * (M)		1142 d		
	HRS								
	AFL								
PROC. REF: AMM 32-31-02PROC. REF: AMM 32-31-02									
D3260006	NOSE LANDING GEAR SQUAT SWITCH ROTATING DISK ASSEMBLY - LUBRICATE							Service	ATA:32
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01									
F3220045	NOSE LANDING GEAR ACTUATOR ATTACHMENT FITTING - REPLACE							Service	ATA:32
	MOS/MSC	09-Mar-01	N/A					NOT INSTALLED	
	HRS	0							
	AFL	0							
PROC. REF: AMM 32-32-01PROC. REF: AMM 32-32-01									
J3220120	* MAIN LANDING GEAR TRUNNION SHEAR PIN BUSHING - PERFORM DETAILED VISUAL INSPECTION FOR BUSHING MIGRATION							Service	ATA:32
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05									

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 32 - LANDING GEAR										
L3220020	* MAIN LANDING GEAR TRUNNION FITTINGS ON MID AND REAR SPAR - PERFORM EDDY CURRENT INSPECTION								Service	ATA:32
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0								
	AFL	0	T:10000		10000		2384			
PROC. REF: NDT PART 6/32-11-00PROC. REF: NDT PART 6/32-11-00										
L3220118	* RIGHT MAIN LANDING GEAR SHOCK STRUT CYLINDER - PERFORM ULTRASONIC INSPECTION OF THE LOWER SERVICE PORT AND FORGING PARTING LINE								Service	ATA:32
PN:200-0201-010	MOS	27-Nov-22						AIRWORTHINESS		
SN:H0755	HRS	9163.6								
	AFL	7031	600		7631		15			
L3220122	* RIGHT MAIN LANDING GEAR SHOCK STRUT CYLINDER - PERFORM ULTRASONIC INSPECTION OF THE LOWER SERVICE PORT AND FORGING PARTING LINE								Service	ATA:32
PN:200-0201-010	MOS/MSC	27-Nov-22	N/A							
SN:H0755	HRS	9163.6								
	AFL	7031								
PROC. REF: NDT PART 4/32-10-01, NDT PART 4/32-10-00PROC. REF: NDT PART 4/32-10-01, NDT PART 4/32-10-00										
M3220136	* RIGHT MAIN LANDING GEAR SHOCK STRUT CYLINDER - PERFORM ULTRASONIC INSPECTION OF THE LOWER SERVICE PORT AND FORGING PARTING LINE								Service	ATA:32
PN:200-0201-010	MOS/MSC	27-Nov-22	N/A							
SN:H0755	HRS	9163.6								
	AFL	7031								
N3220036	* LEFT MAIN LANDING GEAR AXLE BEAM - REPLACE								Service	ATA:32
PN:200-0203-001	MOS	08-Sep-12						LIFE LIMIT		
SN:H0331	HRS	6989.1								
	AFL	5335	10000	TAC 5311	10024		2408			
N3220036	* RIGHT MAIN LANDING GEAR AXLE BEAM - REPLACE								Service	ATA:32
PN:200-0203-001	MOS	08-Sep-12						LIFE LIMIT		
SN:H0334	HRS	6989.1								
	AFL	5335	10000	TAC 5311	10024		2408			

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
N3220041 * LEFT FORWARD LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE									Service ATA:32
PN:4532103201-001	MOS/MSC	15-Dec-10	N/A						
SN:CMI882	HRS	6457.2							
	AFL	4944							
N3220041 * LEFT FORWARD UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE									Service ATA:32
PN:4532103201-001	MOS/MSC	15-Dec-10	N/A						
SN:CMI806	HRS	6457.2							
	AFL	4944							
N3220041 * RIGHT FORWARD LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE									Service ATA:32
PN:4532103201-001	MOS/MSC	15-Dec-10	N/A						
SN:CMI1113	HRS	6457.2							
	AFL	4944							
N3220041 * RIGHT FORWARD UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE									Service ATA:32
PN:4532103201-001	MOS/MSC	15-Dec-10	N/A						
SN:CMI710	HRS	6457.2							
	AFL	4944							
N3220042 * LEFT AFT UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE									Service ATA:32
PN:4532103202-001	MOS/MSC	18-Dec-10	N/A						
SN:CMI371	HRS	6457.2							
	AFL	4944							
N3220042 * RIGHT AFT UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE									Service ATA:32
PN:4532103202-001	MOS/MSC	18-Dec-10	N/A						
SN:CMI363	HRS	6457.2							
	AFL	4944							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 32 - LANDING GEAR										
N3220043		* LEFT AFT LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE						Service	ATA:32	
PN:4532103203-001	MOS/MSC	18-Dec-10	N/A							
SN:CMI818	HRS	6457.2								
	AFL	4944								
N3220043		* RIGHT AFT LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE						Service	ATA:32	
PN:4532103203-001	MOS/MSC	18-Dec-10	N/A							
SN:CMI759	HRS	6457.2								
	AFL	4944								
N3220103		* LEFT MAIN LANDING GEAR ACTUATOR PISTON - REPLACE						Service	ATA:32	
PN:PN	MOS	09-Mar-01						LIFE LIMIT		
SN:UNKNOWN	HRS	0								
	AFL	0	17000		17000		9384			
N3220103		* RIGHT MAIN LANDING GEAR ACTUATOR PISTON - REPLACE						Service	ATA:32	
PN:4532101000V72-002	MOS	09-Mar-01						LIFE LIMIT		
SN:H1153	HRS	0								
	AFL	0	17000		17000		9384			
N3220104		* LEFT MAIN LANDING GEAR ACTUATOR CYLINDER - REPLACE						Service	ATA:32	
PN:4532101000V76-001	MOS	09-Mar-01						LIFE LIMIT		
SN:H0155	HRS	0								
	AFL	0	17000		17000		9384			
N3220104		* RIGHT MAIN LANDING GEAR ACTUATOR CYLINDER - REPLACE						Service	ATA:32	
PN:4532101000V72-002	MOS	09-Mar-01						LIFE LIMIT		
SN:H1153	HRS	0								
	AFL	0	17000		17000		9384			

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
N3220106 * LEFT MAIN LANDING GEAR ACTUATOR HOUSING - REPLACE									
PN:200-0304-001	MOS	19-Dec-10						LIFE LIMIT	Service ATA:32
SN:H1704	HRS	6457.2							
	AFL	4944	17000		21944		14328		
N3220106 * RIGHT MAIN LANDING GEAR ACTUATOR HOUSING - REPLACE									
PN:4532101000V72-002	MOS	09-Mar-01						LIFE LIMIT	Service ATA:32
SN:H1153	HRS	0							
	AFL	0	17000		17000		9384		
N3220116 * LEFT MAIN LANDING GEAR SHOCK STRUT CYLINDER - REPLACE									
PN:200-0201-009	MOS	30-Mar-21						LIFE LIMIT	Service ATA:32
SN:H0727	HRS	8414.4							
	AFL	6463	10000	TAC 1409	15054		7438		
N3220116 * RIGHT MAIN LANDING GEAR SHOCK STRUT CYLINDER - REPLACE									
PN:200-0201-010	MOS	30-Mar-21						LIFE LIMIT	Service ATA:32
SN:H0755	HRS	8414.4							
	AFL	6463	10000	TAC 1409	15054		7438		
N3220139 * LEFT FORWARD LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE									
PN:4532103201-001	MOS	15-Dec-10						LIFE LIMIT	Service ATA:32
SN:CMI882	HRS	6457.2							
	AFL	4944	5000		9944		2328		
N3220139 * LEFT FORWARD UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE									
PN:4532103201-001	MOS	15-Dec-10						LIFE LIMIT	Service ATA:32
SN:CMI806	HRS	6457.2							
	AFL	4944	5000		9944		2328		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
N3220139 * RIGHT FORWARD LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE									
PN:4532103201-001	MOS	15-Dec-10						LIFE LIMIT	Service ATA:32
SN:CMI1113	HRS	6457.2							
	AFL	4944	5000		9944		2328		
N3220139 * RIGHT FORWARD UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE									
PN:4532103201-001	MOS	15-Dec-10						LIFE LIMIT	Service ATA:32
SN:CMI710	HRS	6457.2							
	AFL	4944	5000		9944		2328		
N3220140 * LEFT AFT UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE									
PN:4532103202-001	MOS	18-Dec-10						LIFE LIMIT	Service ATA:32
SN:CMI371	HRS	6457.2							
	AFL	4944	5000		9944		2328		
N3220140 * RIGHT AFT UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE									
PN:4532103202-001	MOS	18-Dec-10						LIFE LIMIT	Service ATA:32
SN:CMI363	HRS	6457.2							
	AFL	4944	5000		9944		2328		
N3220141 * LEFT AFT LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE									
PN:4532103203-001	MOS	18-Dec-10						LIFE LIMIT	Service ATA:32
SN:CMI818	HRS	6457.2							
	AFL	4944	5000		9944		2328		
N3220141 * RIGHT AFT LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE									
PN:4532103203-001	MOS	18-Dec-10						LIFE LIMIT	Service ATA:32
SN:CMI759	HRS	6457.2							
	AFL	4944	5000		9944		2328		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
P3220146 * RIGHT MAIN LANDING GEAR SHOCK STRUT CYLINDER - PERFORM ULTRASONIC INSPECTION OF THE FORGING PARTING LINE Service ATA:32									
PN:200-0201-010	MOS/MSC	27-Nov-22	N/A						
SN:H0755	HRS	9163.6							
	AFL	7031							
PROC. REF: NDT PART 4/32-10-01, NDT PART 4/32-10-00PROC. REF: NDT PART 4/32-10-01, NDT PART 4/32-10-00									
P3231020 LEFT MAIN LANDING GEAR DOOR ACTUATOR GIMBAL ASSEMBLY - PERFORM EDDY CURRENT INSPECTION Service ATA:32									
	MOS	02-Aug-24			RTS				
	HRS	9525.7							
	AFL	7276	300						
PROC. REF: NDT PART 6/32-13-00PROC. REF: NDT PART 6/32-13-00									
P3231021 LEFT MAIN LANDING GEAR DOOR ACTUATOR GIMBAL SHAFT - PERFORM FLUORESCENT PENETRANT INSPECTION Service ATA:32									
	MOS	02-Aug-24			RTS				
	HRS	9525.7							
	AFL	7276	300						
PROC. REF: NDT PART 8/32-13-02PROC. REF: NDT PART 8/32-13-02									
Q3220065 * LEFT MAIN LANDING GEAR ACTUATOR PISTON - REPLACE Service ATA:32									
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
Q3220065 * RIGHT MAIN LANDING GEAR ACTUATOR PISTON - REPLACE Service ATA:32									
PN:4532101000V72-002	MOS/MSC	09-Mar-01	N/A						
SN:H1153	HRS	0							
	AFL	0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
Q3220066 * LEFT MAIN LANDING GEAR ACTUATOR CYLINDER - REPLACE Service ATA:32									
PN:4532101000V76-001	MOS/MSC	09-Mar-01	N/A						
SN:H0155	HRS	0							
	AFL	0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
Q3220066 * RIGHT MAIN LANDING GEAR ACTUATOR CYLINDER - REPLACE									Service ATA:32
PN:4532101000V72-002	MOS/MSC	09-Mar-01	N/A						
SN:H1153	HRS	0							
	AFL	0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
Q3220068 * LEFT MAIN LANDING GEAR ACTUATOR HOUSING - REPLACE									Service ATA:32
PN:200-0304-001	MOS/MSC	19-Dec-10	N/A						
SN:H1704	HRS	6457.2							
	AFL	4944							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
Q3220068 * RIGHT MAIN LANDING GEAR ACTUATOR HOUSING - REPLACE									Service ATA:32
PN:4532101000V72-002	MOS/MSC	09-Mar-01	N/A						
SN:H1153	HRS	0							
	AFL	0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
Q3220128 * LEFT MAIN LANDING GEAR SHOCK STRUT CYLINDER - REPLACE									Service ATA:32
PN:200-0201-009	MOS/MSC	30-Mar-21	N/A						
SN:H0727	HRS	8414.4							
	AFL	6463							
Q3220128 * RIGHT MAIN LANDING GEAR SHOCK STRUT CYLINDER - REPLACE									Service ATA:32
PN:200-0201-010	MOS/MSC	30-Mar-21	N/A						
SN:H0755	HRS	8414.4							
	AFL	6463							
Q3220137 * LEFT MAIN LANDING GEAR SHOCK STRUT CYLINDER - REPLACE									Service ATA:32
PN:200-0201-009	MOS/MSC	30-Mar-21	N/A						
SN:H0727	HRS	8414.4							
	AFL	6463							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 32 - LANDING GEAR										
Q3220137	* RIGHT MAIN LANDING GEAR SHOCK STRUT CYLINDER - REPLACE								Service	ATA:32
PN:200-0201-010	MOS/MSC		30-Mar-21	N/A						
SN:H0755	HRS		8414.4							
	AFL		6463							
Q3220142	* LEFT FORWARD LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE								Service	ATA:32
PN:4532103201-001	MOS/MSC		15-Dec-10	N/A						
SN:CMI882	HRS		6457.2							
	AFL		4944							
Q3220142	* LEFT FORWARD UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE								Service	ATA:32
PN:4532103201-001	MOS/MSC		15-Dec-10	N/A						
SN:CMI806	HRS		6457.2							
	AFL		4944							
Q3220142	* RIGHT FORWARD LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE								Service	ATA:32
PN:4532103201-001	MOS/MSC		15-Dec-10	N/A						
SN:CMI1113	HRS		6457.2							
	AFL		4944							
Q3220142	* RIGHT FORWARD UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE								Service	ATA:32
PN:4532103201-001	MOS/MSC		15-Dec-10	N/A						
SN:CMI710	HRS		6457.2							
	AFL		4944							
Q3220143	* LEFT AFT UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE								Service	ATA:32
PN:4532103202-001	MOS/MSC		18-Dec-10	N/A						
SN:CMI371	HRS		6457.2							
	AFL		4944							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
Q3220143 * RIGHT AFT UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE Service ATA:32									
PN:4532103202-001	MOS/MSC	18-Dec-10	N/A						
SN:CMI363	HRS	6457.2							
	AFL	4944							
Q3220144 * LEFT AFT LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE Service ATA:32									
PN:4532103203-001	MOS/MSC	18-Dec-10	N/A						
SN:CMI818	HRS	6457.2							
	AFL	4944							
Q3220144 * RIGHT AFT LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE Service ATA:32									
PN:4532103203-001	MOS/MSC	18-Dec-10	N/A						
SN:CMI759	HRS	6457.2							
	AFL	4944							
T3220007 * LEFT MAIN LANDING GEAR AXLE BEAM - PERFORM MAIN LANDING GEAR AXLE BEAM ASSEMBLY BORESCOPE INSPECTION Service ATA:32									
PN:200-0203-001	MOS	02-Aug-24	48		02-Aug-28		902 d	AIRWORTHINESS	
SN:H0331	HRS	9525.7							
	AFL	7276							
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
T3220007 * RIGHT MAIN LANDING GEAR AXLE BEAM - PERFORM MAIN LANDING GEAR AXLE BEAM ASSEMBLY BORESCOPE INSPECTION Service ATA:32									
PN:200-0203-001	MOS	02-Aug-24	48		02-Aug-28		902 d	AIRWORTHINESS	
SN:H0334	HRS	9525.7							
	AFL	7276							
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
T3220013 * LEFT MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY - REPLACE Service ATA:32									
PN:200-0300-003	MOS	02-Aug-24						LIFE LIMIT	
SN:H0134	HRS	9525.7							
	AFL	7276	17000	TAC 7276	17000		9384		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
T3220013 * RIGHT MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY - REPLACE									
PN:200-0300-004	MOS	02-Aug-24						LIFE LIMIT	Service ATA:32
SN:H1188	HRS	9525.7							
	AFL	7276	17000	TAC 7276	17000		9384		
T3220014 * LEFT MAIN LANDING GEAR ACTUATOR UPPER PIN - REPLACE									
PN:200-0325-101	MOS	24-Jun-19	96	TAC 0	24-Jun-27		497 d	LIFE LIMIT	Service ATA:32
SN:H2409	HRS	8101.1		TAC 0					
	AFL	6233		TAC 0					
PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01									
T3220014 * RIGHT MAIN LANDING GEAR ACTUATOR UPPER PIN - REPLACE									
PN:200-0325-101	MOS	24-Jun-19	96	TAC 0	24-Jun-27		497 d	LIFE LIMIT	Service ATA:32
SN:HER08U/5030	HRS	8101.1		TAC 0					
	AFL	6233		TAC 0					
PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01									
T3220024 * LEFT MAIN LANDING GEAR ACTUATOR LOWER PIN - PERFORM MAGNETIC PARTICLE INSPECTION									
PN:200-0217-101	MOS	22-Jun-23	48		22-Jun-27		495 d	AIRWORTHINESS	Service ATA:32
SN:H5000	HRS	9258.5							
	AFL	7100							
PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01									
T3220024 * LEFT MAIN LANDING GEAR ACTUATOR UPPER PIN - PERFORM MAGNETIC PARTICLE INSPECTION									
PN:200-0325-101	MOS	22-Jun-23	48		22-Jun-27		495 d	AIRWORTHINESS	Service ATA:32
SN:H2409	HRS	9258.5							
	AFL	7100							
PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01									
T3220024 * RIGHT MAIN LANDING GEAR ACTUATOR LOWER PIN - PERFORM MAGNETIC PARTICLE INSPECTION									
PN:200-0217-101	MOS	22-Jun-23	48		22-Jun-27		495 d	AIRWORTHINESS	Service ATA:32
SN:HER08U5014	HRS	9258.5							
	AFL	7100							
PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
T3220024 * RIGHT MAIN LANDING GEAR ACTUATOR UPPER PIN - PERFORM MAGNETIC PARTICLE INSPECTION Service ATA:32									
PN:200-0325-101	MOS	22-Jun-23	48		22-Jun-27		495 d	AIRWORTHINESS	
SN:HER08U/5030	HRS	9258.5							
	AFL	7100							
PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01									
T3220038 * LEFT MAIN LANDING GEAR ACTUATOR LOWER PIN - REPLACE Service ATA:32									
PN:200-0217-101	MOS	24-Jun-19	96	TAC 0	24-Jun-27		497 d	LIFE LIMIT	
SN:H5000	HRS	8101.1		TAC 0					
	AFL	6233		TAC 0					
PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01									
T3220038 * RIGHT MAIN LANDING GEAR ACTUATOR LOWER PIN - REPLACE Service ATA:32									
PN:200-0217-101	MOS	24-Jun-19	96	TAC 0	24-Jun-27		497 d	LIFE LIMIT	
SN:HER08U5014	HRS	8101.1		TAC 0					
	AFL	6233		TAC 0					
PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01									
T3220046 * LEFT MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY - REPLACE Service ATA:32									
PN:200-0300-003	MOS/MSC	02-Aug-24	N/A						
SN:H0134	HRS	9525.7							
	AFL	7276							
T3220046 * RIGHT MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY - REPLACE Service ATA:32									
PN:200-0300-004	MOS/MSC	02-Aug-24	N/A						
SN:H1188	HRS	9525.7							
	AFL	7276							
T3220063 * LEFT MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY - REPLACE Service ATA:32									
PN:200-0300-003	MOS/MSC	02-Aug-24	N/A						
SN:H0134	HRS	9525.7							
	AFL	7276							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
T3220063 * RIGHT MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY - REPLACE Service ATA:32									
PN:200-0300-004	MOS/MSC		02-Aug-24	N/A					
SN:H1188	HRS		9525.7						
	AFL		7276						
T3220064 * LEFT MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY - REPLACE Service ATA:32									
PN:200-0300-003	MOS/MSC		02-Aug-24	N/A					
SN:H0134	HRS		9525.7						
	AFL		7276						
T3220064 * RIGHT MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY - REPLACE Service ATA:32									
PN:200-0300-004	MOS/MSC		02-Aug-24	N/A					
SN:H1188	HRS		9525.7						
	AFL		7276						
T3220067 * LEFT MAIN LANDING GEAR ACTUATOR END CAP - REPLACE Service ATA:32									
PN:200-0303-001	MOS/MSC		02-Aug-24	N/A					
SN:UNKNOWN	HRS		9525.7						
	AFL		7276						
T3220067 * RIGHT MAIN LANDING GEAR ACTUATOR END CAP - REPLACE Service ATA:32									
PN:200-0303-001	MOS/MSC		02-Aug-24	N/A					
SN:UNKNOWN	HRS		9525.7						
	AFL		7276						
T3220105 * LEFT MAIN LANDING GEAR ACTUATOR END CAP - REPLACE Service ATA:32									
PN:200-0303-001	MOS		02-Aug-24					LIFE LIMIT	
SN:UNKNOWN	HRS		9525.7						
	AFL		7276	2387	9663		2047		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
T3220105 * RIGHT MAIN LANDING GEAR ACTUATOR END CAP - REPLACE									
PN:200-0303-001	MOS	02-Aug-24						LIFE LIMIT	Service ATA:32
SN:UNKNOWN	HRS	9525.7							
	AFL	7276	2387		9663		2047		
T3220135 * LEFT MAIN LANDING GEAR ACTUATOR LOWER PIN - PERFORM DETAILED VISUAL INSPECTION									
PN:200-0217-101	MOS	22-Jun-23	48		22-Jun-27		495 d	AIRWORTHINESS	Service ATA:32
SN:H5000	HRS	9258.5							
	AFL	7100							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
T3220135 * LEFT MAIN LANDING GEAR ACTUATOR UPPER PIN - PERFORM DETAILED VISUAL INSPECTION									
PN:200-0325-101	MOS	22-Jun-23	48		22-Jun-27		495 d	AIRWORTHINESS	Service ATA:32
SN:H2409	HRS	9258.5							
	AFL	7100							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
T3220135 * RIGHT MAIN LANDING GEAR ACTUATOR LOWER PIN - PERFORM DETAILED VISUAL INSPECTION									
PN:200-0217-101	MOS	22-Jun-23	48		22-Jun-27		495 d	AIRWORTHINESS	Service ATA:32
SN:HER08U5014	HRS	9258.5							
	AFL	7100							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
T3220135 * RIGHT MAIN LANDING GEAR ACTUATOR UPPER PIN - PERFORM DETAILED VISUAL INSPECTION									
PN:200-0325-101	MOS	22-Jun-23	48		22-Jun-27		495 d	AIRWORTHINESS	Service ATA:32
SN:HER08U/5030	HRS	9258.5							
	AFL	7100							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
T3220147 * LEFT AFT LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN - PERFORM VISUAL INSPECTION FOR PIN MIGRATION									
	MOS/MSC		N/A						Service ATA:32
	HRS								
	AFL								

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
T3220147					* LEFT AFT UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN - PERFORM VISUAL INSPECTION FOR PIN MIGRATION			Service	ATA:32
	MOS/MSC		N/A						
	HRS								
	AFL								
T3220147					* LEFT FORWARD LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN - PERFORM VISUAL INSPECTION FOR PIN MIGRATION			Service	ATA:32
	MOS/MSC		N/A						
	HRS								
	AFL								
T3220147					* LEFT FORWARD UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN - PERFORM VISUAL INSPECTION FOR PIN MIGRATION			Service	ATA:32
	MOS/MSC		N/A						
	HRS								
	AFL								
T3220147					* RIGHT AFT LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN - PERFORM VISUAL INSPECTION FOR PIN MIGRATION			Service	ATA:32
	MOS/MSC		N/A						
	HRS								
	AFL								
T3220147					* RIGHT AFT UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN - PERFORM VISUAL INSPECTION FOR PIN MIGRATION			Service	ATA:32
	MOS/MSC		N/A						
	HRS								
	AFL								
T3220147					* RIGHT FORWARD LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN - PERFORM VISUAL INSPECTION FOR PIN MIGRATION			Service	ATA:32
	MOS/MSC		N/A						
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
T3220147 * RIGHT FORWARD UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN - PERFORM VISUAL INSPECTION FOR PIN MIGRATION									
	MOS/MSC		N/A						Service ATA:32
	HRS								
	AFL								
<hr/>									
V3220022 LEFT AFT MAIN LANDING GEAR TRUNNION PIN - PERFORM MAGNETIC PARTICLE INSPECTION									
PN:200-0213-103	MOS	30-Mar-21	96		30-Mar-29		1142 d		Service ATA:32
SN:H0364	HRS	8414.4							
	AFL	6463							
PROC. REF: NDT PART 7/32-10-07, NDT PART 7/32-10-08PROC. REF: NDT PART 7/32-10-07, NDT PART 7/32-10-08									
<hr/>									
V3220022 LEFT FORWARD MAIN LANDING GEAR TRUNNION PIN - PERFORM MAGNETIC PARTICLE INSPECTION									
PN:200-0212-103	MOS	30-Mar-21	96		30-Mar-29		1142 d		Service ATA:32
SN:H0501	HRS	8414.4							
	AFL	6463							
PROC. REF: NDT PART 7/32-10-07, NDT PART 7/32-10-08PROC. REF: NDT PART 7/32-10-07, NDT PART 7/32-10-08									
<hr/>									
V3220022 RIGHT AFT MAIN LANDING GEAR TRUNNION PIN - PERFORM MAGNETIC PARTICLE INSPECTION									
PN:200-0213-103	MOS	30-Mar-21	96		30-Mar-29		1142 d		Service ATA:32
SN:H0338	HRS	8414.4							
	AFL	6463							
PROC. REF: NDT PART 7/32-10-07, NDT PART 7/32-10-08PROC. REF: NDT PART 7/32-10-07, NDT PART 7/32-10-08									
<hr/>									
V3220022 RIGHT FORWARD MAIN LANDING GEAR TRUNNION PIN - PERFORM MAGNETIC PARTICLE INSPECTION									
PN:200-0212-103	MOS	30-Mar-21	96		30-Mar-29		1142 d		Service ATA:32
SN:H0473	HRS	8414.4							
	AFL	6463							
PROC. REF: NDT PART 7/32-10-07, NDT PART 7/32-10-08PROC. REF: NDT PART 7/32-10-07, NDT PART 7/32-10-08									
<hr/>									
V3240004 ^S ** EMERGENCY/PARKING BRAKE SWITCH - VERIFY THAT "EMERGENCY/PARKING BRAKE" MESSAGE ILLUMINATES ON EICAS WHEN PARKING BRAKE IS SET AND THROTTLES ARE MOVED ABOVE MCR DETENT.									
	MOS	02-Aug-24	24					AIRWORTHINESS	Service ATA:32
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 32-42-01PROC. REF: AMM 32-42-01									
<hr/>									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 32 - LANDING GEAR										
V3240008 ^S	** EMERGENCY/PARKING BRAKE CONTROL SYSTEM - PERFORM FUNCTIONAL TEST								Service	ATA:32
	MOS	02-Aug-24	24					AIRWORTHINESS		
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 32-42-02PROC. REF: AMM 32-42-02										
<hr/>										
W3220149	* LEFT MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY - REPLACE								Service	ATA:32
PN:200-0300-003	MOS/MSC	02-Aug-24	N/A							
SN:H0134	HRS	9525.7								
	AFL	7276								
<hr/>										
W3220149	* RIGHT MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY - REPLACE								Service	ATA:32
PN:200-0300-004	MOS/MSC	02-Aug-24	N/A							
SN:H1188	HRS	9525.7								
	AFL	7276								
<hr/>										
W3220150	* LEFT MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY - REPLACE								Service	ATA:32
PN:200-0300-003	MOS/MSC	02-Aug-24	N/A							
SN:H0134	HRS	9525.7								
	AFL	7276								
<hr/>										
W3220150	* RIGHT MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY - REPLACE								Service	ATA:32
PN:200-0300-004	MOS/MSC	02-Aug-24	N/A							
SN:H1188	HRS	9525.7								
	AFL	7276								
<hr/>										
W3231022	LEFT MAIN LANDING GEAR INBOARD DOOR GIMBAL BRACKET - PERFORM EDDY CURRENT INSPECTION								Service	ATA:32
	MOS	02-Aug-24			RTS					
	HRS	9525.7								
	AFL	7276	300							
PROC. REF: NDT PART 6/32-13-01PROC. REF: NDT PART 6/32-13-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 32 - LANDING GEAR										
Y3220000	^S	NOSE LANDING GEAR ASSEMBLY - PERFORM VISUAL INSPECTION						Service	ATA:32	
	MOS	02-Aug-24	24							
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
Y3220001	^S	MAIN LANDING GEAR ASSEMBLY - PERFORM VISUAL INSPECTION. INSPECTION TO INCLUDE ACTUATOR, FASTENERS, SUPPORT STRUCTURE, AND SQUAT SWITCHES.						Service	ATA:32	
	MOS	02-Aug-24	24							
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
Y3220002	^S	NOSE LANDING GEAR ACTUATOR PRESSURE AND RETURN LINES - PERFORM VISUAL INSPECTION. LOWER ACTUATOR DUST BOOT TO INSPECT LINES.						Service	ATA:32	
	MOS	02-Aug-24	24							
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
Y3220003	^S	NOSE GEAR SHOCK STRUT - REMOVE AND REPLACE RETAINER RING LOCKSCREW						Service	ATA:32	
	MOS	02-Aug-24	24							
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
Y3220004	^S	MAIN LANDING GEAR ACTUATOR AND GEAR INBOARD DOOR ACTUATOR ATTACH POINTS - PERFORM VISUAL INSPECTION						Service	ATA:32	
	MOS	02-Aug-24	24							
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
Y3220006 ^S	LANDING GEAR ELECTRICAL WIRING - PERFORM VISUAL INSPECTION (THAT PORTION VISIBLE INSIDE WHEEL WELL)							Service	ATA:32
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PKG:11									
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
Y3220008 ^S	NOSE LANDING GEAR AXLE - REMOVE NOSE LANDING GEAR WHEEL AND PERFORM INSPECTION. INSPECT BOTH INSIDE AND OUTSIDE OF AXLE.							Service	ATA:32
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PKG:17									
PROC. REF: AMM 32-40-01PROC. REF: AMM 32-40-01									
Y3220124 ^S	NOSE LANDING GEAR - PERFORM DETAILED VISUAL INSPECTION OF THE NOSE LANDING GEAR UPLOCK ROLLER BRACKET							Service	ATA:32
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PKG:11									
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
Y3230002 ^S	MAIN LANDING GEAR FREE FALL ROLLER - PERFORM VISUAL INSPECTION. PAY PARTICULAR ATTENTION TO BINDING OF ROLLERS.							Service	ATA:32
	MOS	21-Aug-25	12						
	HRS	9809.8	300						
	AFL	7471							
PKG:5									
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
Y3231023 ^S	MAIN LANDING GEAR INBOARD DOOR ACTUATOR (PART NUMBER 7469) END CAP SCREWS - PERFORM DETAILED INSPECTION							Service	ATA:32
	MOS	09-Mar-01	12						
	HRS	0	300						
	AFL	0							
PKG:5									
PROC. REF: AMM 32-31-02PROC. REF: AMM 32-31-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 32 - LANDING GEAR										
Y3240000	^S	NOSE AND MAIN TIRES - PERFORM VISUAL INSPECTION						Service	ATA:32	
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 12-10-04PROC. REF: AMM 12-10-04										
Y3240001	^S	BRAKE LINES - PERFORM VISUAL INSPECTION. INSPECT ALL BRAKE LINES VISIBLE IN WHEEL WELLS AND ON STRUTS.						Service	ATA:32	
	MOS	02-Aug-24	24							
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
Y3240002	^S	BRAKE ASSEMBLIES - PERFORM VISUAL INSPECTION WITH PARKING BRAKE SET. WORN BRAKES ARE VISUALLY INDICATED WHEN THE WEAR INDICATOR PINS BECOME EVEN WITH THE OUTER SURFACE OF THE WEAR INDICATOR SLEEVE.						Service	ATA:32	
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01										
Y3240003	^S	BRAKE CONTROL SYSTEM LINEAR VARIABLE DIFFERENTIAL TRANSFORMER (LVDT) - PERFORM VISUAL INSPECTION						Service	ATA:32	
	MOS	09-Mar-01	48							
	HRS	0	1200							
	AFL	0								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
Y3260005	^S	NOSE LANDING GEAR SQUAT SWITCH ROTATING DISK ASSEMBLY - LUBRICATE						Service	ATA:32	
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 33 - LIGHTS									
330000 MODIFIED PULSE CONTROLLER									Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
331001 NO. 1 COCKPIT LIGHTING CONTROL UNIT									Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-10-06PROC. REF: AMM 33-10-06									
331002 NO. 2 COCKPIT LIGHTING CONTROL UNIT									Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-10-06PROC. REF: AMM 33-10-06									
331010 PILOT FORWARD SWITCH PANEL OVERLAY									Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-10-05PROC. REF: AMM 33-10-05									
331011 PILOT SWITCH PANEL									Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
331012 COPILOT FORWARD SWITCH PANEL OVERLAY									Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-10-05PROC. REF: AMM 33-10-05									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 33 - LIGHTS									
331013 COPILOT FORWARD SWITCH PANEL								Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
331015 CENTER SWITCH PANEL (P5)								Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
331016 CENTER SWITCH PANEL (P5) OVERLAY								Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-10-05PROC. REF: AMM 33-10-05									
331017 THROTTLE QUADRANT OVERLAY PANEL								Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
331018 PILOT AFT CIRCUIT BREAKER PANEL OVERLAY								Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-10-05PROC. REF: AMM 33-10-05									
331019 COPILOT AFT CIRCUIT BREAKER PANEL OVERLAY								Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-10-05PROC. REF: AMM 33-10-05									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 33 - LIGHTS										
331020		DIMMER CONTROL BOX						Component	ATA:33	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-10-10PROC. REF: AMM 33-10-10										
331023		GLARESHIELD FLOOR FLOODLIGHTS INVERTER						Component	ATA:33	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
331025		COCKPIT MISCELLANEOUS RELAY BOX						Component	ATA:33	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-10-07PROC. REF: AMM 33-10-07										
331030		CENTER SWITCH PANEL DIODE BOX (P12)						Component	ATA:33	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-10-08PROC. REF: AMM 33-10-08										
331033		GLARESHIELD FLOODLIGHT POWER SUPPLY						Component	ATA:33	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
331040		PILOT REVERSION PANEL OVERLAY (DS55)						Component	ATA:33	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 33 - LIGHTS										
331101		P35 FUSE PANEL						Component		ATA:33
PN:4533108552-007	MOS/MSC	17-Feb-05	O/C							
SN:MRP644283-001	HRS	3300.2								
	AFL	2515								
PROC. REF: AMM 33-10-09PROC. REF: AMM 33-10-09										
331401-1		NO. 1 LEFT POWER SUPPLY INVERTER (PS5009)						Component		ATA:33
PN:AL-2000	MOS/MSC	11-Apr-05	O/C							
SN:46634	HRS	3496.3								
	AFL	2649								
PROC. REF: AMM 33-20-10PROC. REF: AMM 33-20-10										
331401-10		NO. 5 RIGHT POWER SUPPLY INVERTER (PS5006)						Component		ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-20-10PROC. REF: AMM 33-20-10										
331401-11		NO. 6 LEFT POWER SUPPLY INVERTER (LAVATORY) (PS5010)						Component		ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-20-10PROC. REF: AMM 33-20-10										
331401-2		NO. 1 RIGHT POWER SUPPLY INVERTER (PS5003)						Component		ATA:33
PN:AL-2000	MOS/MSC	11-Apr-05	O/C							
SN:46632	HRS	3496.3								
	AFL	2649								
PROC. REF: AMM 33-20-10PROC. REF: AMM 33-20-10										
331401-3		NO. 2 LEFT POWER SUPPLY INVERTER (PS5008)						Component		ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-20-10PROC. REF: AMM 33-20-10										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 33 - LIGHTS										
331401-4		NO. 2 RIGHT POWER SUPPLY INVERTER (PS5004)						Component	ATA:33	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 33-20-10PROC. REF: AMM 33-20-10										
331401-5		NO. 3 LEFT POWER SUPPLY INVERTER (PS5007)						Component	ATA:33	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 33-20-10PROC. REF: AMM 33-20-10										
331401-6		NO. 3 RIGHT POWER SUPPLY INVERTER (PS5005)						Component	ATA:33	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 33-20-10PROC. REF: AMM 33-20-10										
331401-7		NO. 4 LEFT POWER SUPPLY INVERTER (PS5006)						Component	ATA:33	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 33-20-10PROC. REF: AMM 33-20-10										
331401-8		NO. 4 RIGHT POWER SUPPLY INVERTER (LAVATORY) (PS5010)						Component	ATA:33	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 33-20-10PROC. REF: AMM 33-20-10										
331401-9		NO. 5 LEFT POWER SUPPLY INVERTER (LAVATORY) (PS5011)						Component	ATA:33	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 33-20-10PROC. REF: AMM 33-20-10										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 33 - LIGHTS										
332001		RIGHT NO. 1 PASSENGER LIGHTING CONTROL UNIT						Component	ATA:33	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 33-20-05PROC. REF: AMM 33-20-05										
332002		RIGHT NO. 2 PASSENGER LIGHTING CONTROL UNIT						Component	ATA:33	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 33-20-05PROC. REF: AMM 33-20-05										
332003		RIGHT NO. 3 PASSENGER LIGHTING CONTROL UNIT						Component	ATA:33	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 33-20-05PROC. REF: AMM 33-20-05										
332004		RIGHT NO. 4 PASSENGER LIGHTING CONTROL UNIT						Component	ATA:33	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 33-20-05PROC. REF: AMM 33-20-05										
332005		LEFT NO. 1 PASSENGER LIGHTING CONTROL UNIT						Component	ATA:33	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 33-20-05PROC. REF: AMM 33-20-05										
332006		LEFT NO. 2 PASSENGER LIGHTING CONTROL UNIT						Component	ATA:33	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 33-20-05PROC. REF: AMM 33-20-05										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 33 - LIGHTS									
332007 LEFT NO. 3 PASSENGER LIGHTING CONTROL UNIT									Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-20-05PROC. REF: AMM 33-20-05									
332008 LEFT NO. 4 PASSENGER LIGHTING CONTROL UNIT									Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-20-05PROC. REF: AMM 33-20-05									
332030 LAVATORY NO SMOKING / RETURN TO SEAT SIGN CONTROL UNIT (DS138)									Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-20-11PROC. REF: AMM 33-20-11									
332068 COPILOT LIGHTING CONTROL MODULE									Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-20-02PROC. REF: AMM 33-20-02									
332404 ENTRYWAY CONTROL LIGHT PANEL									Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-20-01PROC. REF: AMM 33-20-01									
334011 LEFT LANDING AND TAXI LIGHT									Component ATA:33
PN:GE4587	MOS/MSC	17-Feb-22	O/C	TSN 0					
SN:UNKNOWN	HRS	8864.4		TSN 0					
	AFL	6822		TSN 0					
PROC. REF: AMM 33-40-04PROC. REF: AMM 33-40-04									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 33 - LIGHTS									
334012 RIGHT LANDING AND TAXI LIGHT									Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-40-04PROC. REF: AMM 33-40-04									
334021 LEFT NAVIGATION LIGHT (DS37)									Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-40-02PROC. REF: AMM 33-40-02									
334022 RIGHT NAVIGATION LIGHT (DS38)									Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-40-02PROC. REF: AMM 33-40-02									
334023 TAIL NAVIGATION LIGHT (DS39)									Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-40-02PROC. REF: AMM 33-40-02									
334041 COPILOT REVERSION PANEL OVERLAY (DS56)									Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
334175 RELAY OPTIONS PANEL									Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 33 - LIGHTS										
334332		UPPER ANTI-COLLISION LIGHT						Component	ATA:33	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-40-01PROC. REF: AMM 33-40-01										
334333		LOWER ANTI-COLLISION LIGHT						Component	ATA:33	
PN:GE-16386-12-1	MOS/MSC	22-Dec-08	O/C							
SN:AA2591	HRS	6088.7								
	AFL	4660								
PROC. REF: AMM 33-40-01PROC. REF: AMM 33-40-01										
335005		FORWARD ELS ACTIVATION MODULE (A81)						Component	ATA:33	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-50-01PROC. REF: AMM 33-50-01										
335006		AFT ELS ACTIVATION MODULE (A82)						Component	ATA:33	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-50-01PROC. REF: AMM 33-50-01										
336001		PILOT CHART HOLDER						Component	ATA:33	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
336002		COPILOT CHART HOLDER						Component	ATA:33	
PN:10-62-01	MOS/MSC	17-Feb-05	O/C							
SN:3357	HRS	3300.2								
	AFL	2515								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 33 - LIGHTS										
336003	PILOT MAP LIGHT								Component	ATA:33
PN:0204327-001	MOS/MSC	12-Dec-11	O/C	TSN 0						
SN:542319	HRS	6763.5		TSN 0						
	AFL	5158		TSN 0						
PROC. REF: AMM 33-10-01PROC. REF: AMM 33-10-01										
336004	COPILOT MAP LIGHT								Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-10-01PROC. REF: AMM 33-10-01										
Y3310000 ^S	FLIGHT COMPARTMENT LIGHTING - PERFORM OPERATIONAL CHECK OF THE FOLLOWING: A. MAP LIGHTS. B. INSTRUMENT PANEL FLUORESCENT LIGHTS. C. INSTRUMENT/INDICATOR LIGHTS. D. LIGHT DIMMING SWITCHES. E. CREW WARNING PANEL. F. PANEL OVERLAYS.								Service	ATA:33
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 33-10-00PROC. REF: AMM 33-10-00										
Y3340000 ^S	EXTERIOR LIGHTING SYSTEMS - PERFORM OPERATION CHECK OF THE FOLLOWING: A. TAXI LIGHTS. B. ANTI-COLLISION BEACONS. C. NAVIGATION LIGHTS. D. STROBE LIGHTS. E. LANDING/RECOGNITION LIGHTS. F. WING ICE INSPECTION LIGHTS. G. EMERGENCY DOOR EGRESS LIGHTS.								Service	ATA:33
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 33-40-00, AMM 33-41-00PROC. REF: AMM 33-40-00, AMM 33-41-00										
Y3350003 ^S	EMERGENCY LIGHTING SYSTEM - PERFORM OPERATIONAL CHECK								Service	ATA:33
	MOS	22-Jun-23	48							
	HRS	9258.5	1200							
	AFL	7100								
PROC. REF: AMM 33-50-00PROC. REF: AMM 33-50-00										

PKG:1

PKG:2

PKG:14

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 34 - NAVIGATION

34-00-FAR-91.171		CHECK VOR EQUIPMENT FOR IFR OPERATIONS FAR 91.171						Service	ATA:34
	MOS/MSC	09-Mar-01	O/C						
	HRS	0							
	AFL	0							
PROC. REF: GENERIC NO REF, FAR FAR 91.171PROC. REF: GENERIC NO REF, FAR FAR 91.171									

341001		NO. 1 AIR DATA COMPUTER						Component	ATA:34
PN:7014700-606	MOS/MSC	30-Apr-19	O/C						
SN:99072942	HRS	8080.6							
	AFL	6214							
PROC. REF: AMM 34-17-01PROC. REF: AMM 34-17-01									

341001A		TEST/INSPECT NO. 1 AIR DATA COMPUTER						Service	ATA:34
PN:7014700-606	MOS	10-Aug-24	24		10-Aug-26		179 d		
SN:99072942	HRS								
	AFL								
Calibration Date: : 10-Aug-24									
PROC. REF: FAR FAR 91.411, AMM 34-17-00, CFR 14 CFR PART 43 APP EPROC. REF: FAR FAR 91.411, AMM 34-17-00, CFR 14 CFR PART 43 APP E									

341002		NO. 2 AIR DATA COMPUTER						Component	ATA:34
PN:7014700-606	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:01014560	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-17-01PROC. REF: AMM 34-17-01									

341002A		TEST/INSPECT NO. 2 AIR DATA COMPUTER						Service	ATA:34
PN:7014700-606	MOS	10-Aug-24	24		10-Aug-26		179 d		
SN:01014560	HRS								
	AFL								
Calibration Date: : 10-Aug-24									
PROC. REF: FAR FAR 91.411, AMM 34-17-00, CFR 14 CFR PART 43 APP EPROC. REF: FAR FAR 91.411, AMM 34-17-00, CFR 14 CFR PART 43 APP E									

341013		STANDBY AIRSPEED INDICATOR						Component	ATA:34
PN:6634208002-003	MOS/MSC	17-Dec-05	O/C						
SN:274205	HRS	4110.78							
	AFL	3119							
PROC. REF: AMM 34-18-01PROC. REF: AMM 34-18-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 34 - NAVIGATION										
341025		STANDBY ALTIMETER						Component	ATA:34	
PN:7634208001-003	MOS/MSC	10-Aug-24	O/C							
SN:1722323	HRS									
	AFL									
PROC. REF: AMM 34-15-01PROC. REF: AMM 34-15-01										
341025A		TEST/INSPECT STANDBY ALTIMETER						Service	ATA:34	
PN:7634208001-003	MOS	10-Aug-24	24		10-Aug-26		179 d			
SN:1722323	HRS									
	AFL									
Calibration Date: : 10-Aug-24										
PROC. REF: FAR FAR 91.411, AMM 34-15-01, CFR 14 CFR PART 43 APP EPROC. REF: FAR FAR 91.411, AMM 34-15-01, CFR 14 CFR PART 43 APP E										
341037		LEFT PRIMARY PITOT/STATIC PROBE						Component	ATA:34	
PN:0856TJ1	MOS	17-Aug-18		TSN 0				LIFE LIMIT		
SN:308640	HRS	7915.5	15000	TSN 0	22915.5		12892.4			
	AFL	6079		TSN 0						
PROC. REF: AMM 34-11-01PROC. REF: AMM 34-11-01										
341037A		LEFT PRIMARY PITOT/STATIC PROBE - PERFORM NATIONALLY REQUIRED EQUIPMENT TESTS AND INSPECTIONS						Service	ATA:34	
PN:0856TJ1	MOS	10-Aug-24	24		10-Aug-26		179 d			
SN:308640	HRS									
	AFL									
PROC. REF: GENERIC NO REF, FAR FAR 91.411, CFR 14 CFR PART 43 APP EPROC. REF: GENERIC NO REF, FAR FAR 91.411, CFR 14 CFR PART 43 APP E										
341038		RIGHT PRIMARY PITOT/STATIC PROBE						Component	ATA:34	
PN:6634100000-003	MOS	09-Dec-24						LIFE LIMIT		
SN:276891	HRS	9574.3	15000	TSN 7559.6	17014.7		6991.6			
	AFL	7315		TSN 7118						
PROC. REF: AMM 34-11-01PROC. REF: AMM 34-11-01										
341038A		RIGHT PRIMARY PITOT/STATIC PROBE - PERFORM NATIONALLY REQUIRED EQUIPMENT TESTS AND INSPECTIONS						Service	ATA:34	
PN:6634100000-003	MOS	09-Dec-24	24		09-Dec-26		300 d			
SN:276891	HRS	9574.3								
	AFL	7315								
PROC. REF: FAR FAR 91.411, AMM 34-11-00, CFR 14 CFR PART 43 APP EPROC. REF: FAR FAR 91.411, AMM 34-11-00, CFR 14 CFR PART 43 APP E										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 34 - NAVIGATION										
341049	STANDBY PITOT/STATIC PROBE								Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-11-01PROC. REF: AMM 34-11-01										
341049A	TEST/INSPECT STANDBY PITOT/STATIC PROBE								Service	ATA:34
	MOS	10-Aug-24	24		10-Aug-26		179 d			
	HRS									
	AFL									
PROC. REF: FAR FAR 91.411, AMM 34-11-00, CFR 14 CFR PART 43 APP EPROC. REF: FAR FAR 91.411, AMM 34-11-00, CFR 14 CFR PART 43 APP E										
341061	RADAR ALTIMETER RECEIVER								Component	ATA:34
PN:7001840-937	MOS/MSC	18-Oct-24	O/C							
SN:99118031	HRS	9555.2								
	AFL	7301								
PROC. REF: AMM 34-14-01PROC. REF: AMM 34-14-01										
341073	FORWARD RADAR ALTIMETER ANTENNA								Component	ATA:34
PN:S67-2002-4	MOS/MSC	14-Jul-07	O/C							
SN:552-14361	HRS	5618.1								
	AFL	4293								
PROC. REF: AMM 34-14-02PROC. REF: AMM 34-14-02										
341074	AFT RADAR ALTIMETER ANTENNA								Component	ATA:34
PN:S67-2002-4	MOS/MSC	14-Jul-07	O/C							
SN:552-13054	HRS	5618.1								
	AFL	4293								
PROC. REF: AMM 34-14-02PROC. REF: AMM 34-14-02										
3413-RVSM	FLIGHT CHECK ALTITUDE ALERTER FUNCTION. RVSM COMPLIANT AIRCRAFT.								Service	ATA:34
	MOS/MSC	09-Mar-01	N/R							
	HRS	0								
	AFL	0								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
341901 TOTAL AIR TEMPERATURE PROBE (TAT)									Component ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-17-02PROC. REF: AMM 34-17-02									
342001 NO. 1 ATTITUDE HEADING REFERENCE COMPUTER (AHRS)									Component ATA:34
PN:145130-6000	MOS/MSC	21-Mar-22	O/C						
SN:5001	HRS	8909							
	AFL	6851							
PROC. REF: AMM 34-26-01PROC. REF: AMM 34-26-01									
342002 NO. 2 ATTITUDE HEADING REFERENCE COMPUTER (AHRS)									Component ATA:34
PN:HG2010AC02	MOS/MSC	10-Feb-09	O/C						
SN:99031032	HRS	6104.7							
	AFL								
PROC. REF: AMM 34-26-01PROC. REF: AMM 34-26-01									
342003 NO. 1 ATTITUDE HEADING REFERENCE COMPUTER FAN (AHRS)									Component ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-26-03PROC. REF: AMM 34-26-03									
342004 NO. 2 ATTITUDE HEADING REFERENCE COMPUTER FAN (AHRS)									Component ATA:34
PN:26012423-105	MOS/MSC	10-Aug-12	O/C						
SN:10396	HRS	6975.7							
	AFL	5322							
PROC. REF: AMM 34-26-03PROC. REF: AMM 34-26-03									
342037 LEFT FLUX VALVE									Component ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-26-02PROC. REF: AMM 34-26-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 34 - NAVIGATION										
342038		RIGHT FLUX VALVE						Component	ATA:34	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-26-02PROC. REF: AMM 34-26-02										
342101		DUAL ANGLE OF ATTACK INDICATOR						Component	ATA:34	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
342103		STANDBY COMPASS						Component	ATA:34	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-21-01PROC. REF: AMM 34-21-01										
342103A		CALIBRATION CHECK STANDBY COMPASS						Service	ATA:34	
PN:PN	MOS/MSC	09-Mar-01	A/R							
SN:UNKNOWN	HRS	0								
	AFL	0								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
342701		LEFT ATTITUDE HEADING REFERENCE SYSTEM MEMORY MODULE (AHRS)						Component	ATA:34	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-26-01PROC. REF: AMM 34-26-01										
342702		RIGHT ATTITUDE HEADING REFERENCE SYSTEM MEMORY MODULE (AHRS)						Component	ATA:34	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-26-01PROC. REF: AMM 34-26-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 34 - NAVIGATION										
342801		STANDBY ATTITUDE INDICATOR						Component	ATA:34	
PN:501-1648-02	MOS/MSC	12-Sep-22	O/C							
SN:1338	HRS	9101.8								
	AFL	6994								
PROC. REF: AMM 34-23-01PROC. REF: AMM 34-23-01										
343005		MARKER BEACON ANTENNA						Component	ATA:34	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-30-01PROC. REF: AMM 34-30-01										
343008		UPPER GLIDESCOPE ANTENNA (E11)						Component	ATA:34	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-30-02PROC. REF: AMM 34-30-02										
343009		LOWER GLIDESCOPE ANTENNA (E12)						Component	ATA:34	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-30-02PROC. REF: AMM 34-30-02										
343030		MARKER BEACON ANTENNA SPLITTER						Component	ATA:34	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-30-03PROC. REF: AMM 34-30-03										
344111		UPPER TCAS ANTENNA						Component	ATA:34	
PN:071-01548-0200	MOS/MSC	15-Oct-09	O/C							
SN:587-10110	HRS	6191.1								
	AFL									
PROC. REF: AMM 34-43-02PROC. REF: AMM 34-43-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 34 - NAVIGATION										
344112	LOWER TCAS ANTENNA								Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-43-02PROC. REF: AMM 34-43-02										
344143	TCAS PROCESSOR								Component	ATA:34
PN:066-01146-1211	MOS/MSC	06-Jan-22	O/C							
SN:41568	HRS	8821.5								
	AFL	6790								
PROC. REF: AMM 34-43-01PROC. REF: AMM 34-43-01										
344155	TCAS RELAY BOX ASSEMBLY								Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-43-03PROC. REF: AMM 34-43-03										
344167	TCAS CONFIGURATION MODULE								Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
344171	NO. 1 TCAS UPPER ANTENNA CABLE								Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
344172	NO. 2 TCAS UPPER ANTENNA CABLE								Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 34 - NAVIGATION										
344173	NO. 3 TCAS UPPER ANTENNA CABLE								Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
344174	NO. 4 TCAS UPPER ANTENNA CABLE								Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
344176	UPPER TCAS ADAPTER ASSEMBLY								Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
344177	LOWER TCAS ADAPTER ASSEMBLY								Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
344181	NO. 1 TCAS LOWER ANTENNA CABLE								Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
344182	NO. 2 TCAS LOWER ANTENNA CABLE								Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
344183 NO. 3 TCAS LOWER ANTENNA CABLE									Component ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
344184 NO. 4 TCAS LOWER ANTENNA CABLE									Component ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
344205 WEATHER RADAR RECEIVER/TRANSMITTER/ANTENNA									Component ATA:34
PN:7021450-601	MOS/MSC	11-Aug-09	O/C						
SN:07067540	HRS	6169.3							
	AFL	4725							
PROC. REF: AMM 34-42-01PROC. REF: AMM 34-42-01									
344207 WEATHER RADAR TRANSCEIVER									Component ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-42-01PROC. REF: AMM 34-42-01									
344209 WEATHER RADAR LIGHTNING SENSOR ANTENNA									Component ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
344221 WEATHER RADAR CONTROLLER									Component ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-42-02PROC. REF: AMM 34-42-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 34 - NAVIGATION										
344223	LIGHTNING DETECTION PROCESSOR								Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
<hr/>										
344513	TERRAIN AWARENESS WARNING (TAWS) COMPUTER								Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
<hr/>										
344514	TERRAIN AWARENESS WARNING (TAWS) CONFIGURATION MODULE								Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
<hr/>										
344515	TAWS RELAY BOX								Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
<hr/>										
345000A	UPDATE NAVIGATION DATA BASE								Service	ATA:34
	MOS/MSC		0 / -		?		?			
	HRS									
	AFL									
PROC. REF: GENERIC NO REF, EMP 9900052, EMP 9900053PROC. REF: GENERIC NO REF, EMP 9900052, EMP 9900053										
<hr/>										
345001	NO. 1 INTEGRATED NAVIGATION UNIT								Component	ATA:34
PN:7510100-631	MOS/MSC	17-Feb-05	O/C							
SN:01015045	HRS	3300.2								
	AFL	2515								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 34 - NAVIGATION										
345002	NO. 2 INTEGRATED NAVIGATION UNIT								Component	ATA:34
PN:7510100-633	MOS/MSC	17-Feb-05	O/C							
SN:99124053	HRS	3300.2								
	AFL	2515								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
<hr/>										
345011	NO. 1 NAVIGATION RECEIVER MODULE								Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
<hr/>										
345012	NO. 2 NAVIGATION RECEIVER MODULE								Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
<hr/>										
345013	NO. 1 ADF ANTENNA								Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-57-01PROC. REF: AMM 34-57-01										
<hr/>										
345014	NO. 2 ADF ANTENNA								Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-57-01PROC. REF: AMM 34-57-01										
<hr/>										
345024	GPWS CONTROL PANEL								Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
345025 ENHANCED GROUND PROXIMITY WARNING (EGPWS) COMPUTER									Component ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-45-01PROC. REF: AMM 34-45-01									
345037 FORWARD ATC ANTENNA									Component ATA:34
PN:DMNI50-2-2	MOS/MSC	16-Jul-19	O/C	TSN 0					
SN:143631	HRS	8109		TSN 0					
	AFL	6239		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
345038 AFT ATC ANTENNA									Component ATA:34
PN:DMNI50-2-2	MOS/MSC	16-Jul-19	O/C	TSN 0					
SN:143620	HRS	8109		TSN 0					
	AFL	6239		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
345049 AFT (NO. 1) DME ANTENNA									Component ATA:34
PN:DMNI50-2-2	MOS/MSC	16-Jul-19	O/C	TSN 0					
SN:143632	HRS	8109		TSN 0					
	AFL	6239		TSN 0					
PROC. REF: AMM 34-55-01PROC. REF: AMM 34-55-01									
345050 FORWARD (NO. 2) DME ANTENNA									Component ATA:34
PN:DMNI50-9-2	MOS/MSC	16-Jul-19	O/C	TSN 10					
SN:22086	HRS	8109		TSN 0					
	AFL	6239		TSN 0					
PROC. REF: AMM 34-55-01PROC. REF: AMM 34-55-01									
345083 LEFT VOR/LOCALIZER ANTENNA									Component ATA:34
PN:DMN4-17-1/N	MOS/MSC	25-Nov-19	O/C	TSN 0					
SN:21995	HRS	8177.7		TSN 0					
	AFL	6303		TSN 0					
PROC. REF: AMM 34-51-02PROC. REF: AMM 34-51-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
345084 RIGHT VOR/LOCALIZER ANTENNA									Component ATA:34
PN:DMN4-17-1/N	MOS/MSC	25-Nov-19	O/C	TSN 0					
SN:21818	HRS	8177.7		TSN 0					
	AFL	6303		TSN 0					
PROC. REF: AMM 34-51-02PROC. REF: AMM 34-51-02									
345201 NAV VHF (A42) DUPLEXER									Component ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-51-04PROC. REF: AMM 34-51-04									
345260 PHASING COUPLER									Component ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-51-03PROC. REF: AMM 34-51-03									
345501 DME INDICATOR									Component ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
345605 LEFT UPPER MODE S ATC ANTENNA									Component ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
345606 RIGHT UPPER MODE S ATC ANTENNA									Component ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 34 - NAVIGATION										
346001		PILOT FLIGHT MANAGEMENT CONTROL DISPLAY CDU						Component	ATA:34	
PN:3017-41-221	MOS/MSC	13-Apr-17	O/C							
SN:2081	HRS	7744.3								
	AFL	5922								
PROC. REF: AMM 34-60-01PROC. REF: AMM 34-60-01										
346002		COPILOT FLIGHT MANAGEMENT CONTROL DISPLAY CDU						Component	ATA:34	
PN:3017-41-221	MOS/MSC	13-Apr-17	O/C							
SN:2082	HRS	7744.3								
	AFL	5922								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
346021		FMS DATA (DTU) TRANSFER UNIT						Component	ATA:34	
PN:1408-00-1	MOS/MSC	13-Apr-17	O/C							
SN:3597	HRS	7744.3								
	AFL	5922								
PROC. REF: AMM 34-60-02PROC. REF: AMM 34-60-02										
346025		NO. 1 FLIGHT MANAGEMENT CONFIGURATION MODULE						Component	ATA:34	
PN:30171	MOS/MSC	13-Apr-17	O/C							
SN:2173	HRS	7744.3								
	AFL	5922								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
346026		NO. 2 FLIGHT MANAGEMENT CONFIGURATION MODULE						Component	ATA:34	
PN:30171	MOS/MSC	13-Apr-17	O/C							
SN:2174	HRS	7744.3								
	AFL	5922								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
346031		NO. 1 FMS ANTENNA						Component	ATA:34	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 34 - NAVIGATION										
346032	NO. 2 FMS ANTENNA								Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
<hr/>										
346090	AFIS DATA MANAGEMENT UNIT								Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
<hr/>										
347510	NO. 1 GPS ANTENNA								Component	ATA:34
PN:10708	MOS/MSC	13-Apr-17	O/C							
SN:9815	HRS	7744.3								
	AFL	5922								
PROC. REF: AMM 34-53-01PROC. REF: AMM 34-53-01										
<hr/>										
347511	NO. 2 GPS ANTENNA								Component	ATA:34
PN:10708	MOS/MSC	13-Apr-17	O/C							
SN:9814	HRS	7744.3								
	AFL	5922								
PROC. REF: AMM 34-53-01PROC. REF: AMM 34-53-01										
<hr/>										
A3400000 ^S	** NAVIGATION SYSTEMS - PERFORM OPERATIONAL CHECK								Service	ATA:34
	MOS	02-Aug-24	24					AIRWORTHINESS		
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 34-00-00PROC. REF: AMM 34-00-00										
<hr/>										
L3411062	LEFT PRIMARY PITOT/STATIC PROBE - PERFORM DETAILED VISUAL INSPECTION								Service	ATA:34
PN:0856TJ1	MOS	10-Aug-24	24		10-Aug-26		179 d			
SN:308640	HRS									
	AFL									
PROC. REF: AMM 34-11-01PROC. REF: AMM 34-11-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 34 - NAVIGATION										
M3411052	LEFT PRIMARY PITOT/STATIC PROBE - VERIFY PITCH, ROLL, AND YAW ALIGNMENT								Service	ATA:34
PN:0856TJ1	MOS	10-Aug-24	24		10-Aug-26		179 d			
SN:308640	HRS									
	AFL									
PROC. REF: AMM 34-11-01PROC. REF: AMM 34-11-01										
<hr/>										
U3411060	AIR DATA SYSTEM - PERFORM FUNCTIONAL TEST								Service	ATA:34
	MOS	10-Aug-24	24		10-Aug-26		179 d			
	HRS									
	AFL									
PROC. REF: AMM 34-17-00PROC. REF: AMM 34-17-00										
<hr/>										
V3420000 ^S	ATTITUDE HEADING REFERENCE UNIT (AHRU) MOUNTING TRAY FAN FILTER - PERFORM VISUAL INSPECTION. ENSURE FILTER IS FREE OF OBSTRUCTIONS.								Service	ATA:34
	MOS	02-Aug-24	24							
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
<hr/>										
Y3411000 ^S	PITOT-STATIC PROBES - PERFORM VISUAL INSPECTION. ENSURE DRAIN HOLES ARE CLEAR OF OBSTRUCTIONS								Service	ATA:34
	MOS	02-Aug-24	24							
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 34-11-01PROC. REF: AMM 34-11-01										
<hr/>										
Y3440000 ^S	RADOME STRUCTURE AND ANTENNA INSTALLATION - PERFORM VISUAL INSPECTION								Service	ATA:34
	MOS	09-Mar-01	48							
	HRS	0	1200							
	AFL	0								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
<hr/>										
ATA 35 - OXYGEN										
256032	COPILOTS PROTECTIVE BREATHING EQUIPMENT								Component	ATA:35
PN:119003	MOS/MSC	09-Mar-01	N/A					NOT INSTALLED		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 35 - OXYGEN									
SN:131371	HRS	0							
	AFL	0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
350001 OXYGEN CYLINDER Component ATA:35									
PN:806385-14	MOS/MSC	28-Aug-23	H/T	TSN 15					
SN:C10050116	HRS	9307.4							
	AFL	7125							
PROC. REF: AMM 35-00-01PROC. REF: AMM 35-00-01									
350013 OXYGEN CYLINDER LOW PRESSURE RELIEF VALVE Component ATA:35									
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
350201 TEMP/PRESSURE TRANSDUCER Component ATA:35									
PN:10008789	MOS/MSC	22-Jun-23	O/C						
SN:20201184	HRS	9258.5							
	AFL	7100							
PROC. REF: AMM 35-00-03PROC. REF: AMM 35-00-03									
350225 OXYGEN FILL VALVE (POST SB 45-12-1) Component ATA:35									
PN:P21010	MOS/MSC	16-Jul-19	O/C	TSN 51					
SN:7488	HRS	8109		TSN 0					
	AFL	6239		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
350230 REMOTE OXYGEN PRESSURE INDICATOR Component ATA:35									
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 35-00-05PROC. REF: AMM 35-00-05									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 35 - OXYGEN										
351001	PILOTS OXYGEN MASK								Component	ATA:35
PN:MC10-15-166	MOS/MSC	05-Jan-26	O/C	TSO 0						
SN:SE 18288	HRS	9987.5		TSO 0						
	AFL	7596		TSO 0						
PROC. REF: AMM 35-10-01PROC. REF: AMM 35-10-01										
351002	COPILOTS OXYGEN MASK								Component	ATA:35
PN:MC10-15-166	MOS/MSC	26-Aug-24	O/C	TSO 0						
SN:111581	HRS	9529		TSO 0						
	AFL	7280		TSO 0						
PROC. REF: AMM 35-10-01PROC. REF: AMM 35-10-01										
351003A	INSPECTION PASSENGER OXYGEN MASK (INSPECTION) - PERFORM VISUAL INSPECTION OF 289 SERIES PAX OXYGEN MASK (REFER ZODIAC / AVOX MANUAL 833-35-01).								Service	ATA:35
	MOS	21-Aug-25	36	21-Aug-28			921 d	VENDOR RECOMMENDATION		
	HRS	9809.8								
	AFL	7471								
PROC. REF: GENERIC NO REF, SI 833-35-01PROC. REF: GENERIC NO REF, SI 833-35-01										
351005	PILOT CREW OXYGEN OUTLET								Component	ATA:35
PN:DPB181-04	MOS/MSC	24-May-07	O/C							
SN:20/06	HRS	5477.2								
	AFL	4173								
PROC. REF: AMM 35-10-01PROC. REF: AMM 35-10-01										
351006	COPILOT CREW-OXYGEN OUTLET								Component	ATA:35
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 35-10-01PROC. REF: AMM 35-10-01										
352002	ALTITUDE COMPENSATING REGULATOR								Component	ATA:35
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 35-20-06PROC. REF: AMM 35-20-06										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 35 - OXYGEN										
352011	OXYGEN CONTROL VALVE								Component	ATA:35
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 35-20-01PROC. REF: AMM 35-20-01										
<hr/>										
353001	PORTABLE OXYGEN CYLINDER								Component	ATA:35
PN:PN	MOS/MSC		O/C							
SN:UNKNOWN	HRS									
	AFL									
PROC. REF: AMM 35-00-01PROC. REF: AMM 35-00-01										
<hr/>										
355111	OXYGEN PRESSURE INDICATOR								Component	ATA:35
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 35-00-05PROC. REF: AMM 35-00-05										
<hr/>										
K3500021	** OXYGEN SYSTEM LOW PRESSURE SUPPLY HOSES - PERFORM OPERATIONAL CHECK. ENSURE THAT HOSES ARE FREE OF OBSTRUCTIONS								Service	ATA:35
	MOS/MSC	09-Mar-01	N/A							
	HRS	0								
	AFL	0								
PROC. REF: AMM 35-00-00PROC. REF: AMM 35-00-00										
<hr/>										
N3510013	** OXYGEN CYLINDER AND REMOTE OXYGEN FILL VALVES - PERFORM PERIODIC CHECK								Service	ATA:35
	MOS	27-Oct-25						AIRWORTHINESS		
	HRS	9906.2	1500	Adj 8.2	11414.4		1391.3			
	AFL	7538								
PROC. REF: AMM 35-00-01PROC. REF: AMM 35-00-01										
<hr/>										
N3510019	** OXYGEN CYLINDER AND REMOTE OXYGEN FILL VALVES - PERFORM PERIODIC CHECK								Service	ATA:35
	MOS/MSC		N/A							
	HRS									
	AFL									
PROC. REF: AMM 35-00-01PROC. REF: AMM 35-00-01										

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 35 - OXYGEN									
O3510003 ^S ** CABIN LOW PRESSURE OXYGEN DISTRIBUTION FLEX HOSES - PERFORM FUNCTIONAL TEST Service ATA:35									
	MOS	02-Aug-24	24					AIRWORTHINESS	
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 35-20-00PROC. REF: AMM 35-20-00									
PKG:7									
O3510006 COPILOTS OXYGEN MASK - E.R.O.S. CREW OXYGEN MASKS - COMPLY WITH FACTORY OVERHAUL Service ATA:35									
PN:MC10-15-166	MOS	26-Aug-24	72		28-Jun-30		1597 d		
SN:111581	HRS	9529							
	AFL	7280							
OverHaul Date:: 28-Jun-24									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
O3510006 PILOTS OXYGEN MASK - E.R.O.S. CREW OXYGEN MASKS - COMPLY WITH FACTORY OVERHAUL Service ATA:35									
PN:MC10-15-166	MOS	05-Jan-26	72		08-Nov-31		2095 d		
SN:SE 18288	HRS	9987.5							
	AFL	7596							
OverHaul Date:: 08-Nov-25									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
O3510007 OXYGEN CYLINDER (COMPOSITE) - SCRAP Service ATA:35									
	MOS	09-Mar-01	180		28-May-37 (M)		4123 d	LIFE LIMIT	
	HRS	0							
	AFL	0							
O3510005 ** OXYGEN CYLINDER (COMPOSITE) AND LOW PRESSURE RELIEF VALVE - PERFORM ICC HYDROSTATIC TEST ON CYLINDER (PER DOT EXEMPTION E8162) AND FUNCTIONALLY TEST OXYGEN CYLINDER LOW PRESSURE RELIEF VALVE. Service ATA:35									
PN:806385-14	MOS	27-Jun-23	60		27-Jun-28		866 d		
SN:C10050116	HRS	9307.4	5000		14307.4		4284.3		
	AFL	7125							
HydroCheck Date: : 27-Jun-23									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 35 - OXYGEN										
Q3510018		** OXYGEN CYLINDER (COMPOSITE) AND LOW PRESSURE RELIEF VALVE - PERFORM ICC HYDROSTATIC TEST ON CYLINDER (PER DOT EXEMPTION E8162) AND FUNCTIONALLY TEST OXYGEN CYLINDER LOW PRESSURE RELIEF VALVE							Service	ATA:35
PN:806385-14	MOS	28-Aug-23	60		28-Aug-28		928 d			
SN:C10050116	HRS	9307.4	5000		14307.4		4284.3			
	AFL	7125								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
Q3510022										
Q3510022		OXYGEN CYLINDER REGULATOR - PERFORM OVERHAUL							Service	ATA:35
	MOS	22-Jun-23	60		22-Jun-28		861 d			
	HRS	9258.5	5000		14258.5		4235.4			
	AFL	7100								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
Q3510023										
Q3510023		OXYGEN CYLINDER REGULATOR - PERFORM OVERHAUL							Service	ATA:35
	MOS/MSC		N/A							
	HRS									
	AFL									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
W3510002 ^S										
W3510002 ^S		** OXYGEN SYSTEM - PERFORM OPERATIONAL CHECK							Service	ATA:35
	MOS	02-Aug-24	24					AIRWORTHINESS		
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 35-00-00PROC. REF: AMM 35-00-00										
Y3510000 ^S										
Y3510000 ^S		OXYGEN CYLINDER INSTALLATION - PERFORM VISUAL INSPECTION. CHECK PLUMBING FOR ROUTING, SECURITY, AND CONDITION.							Service	ATA:35
	MOS	09-Mar-01	48							
	HRS	0	1200							
	AFL	0								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 35 - OXYGEN

Y3510001	S		CREW SEAT OXYGEN HOSES - PERFORM VISUAL INSPECTION. PAY PARTICULAR ATTENTION TO AREA WHERE OXYGEN HOSES ENTER CREW SEATS ABOVE COCKPIT FLOOR.					Service	ATA:35
	MOS		21-Aug-25		12				
	HRS		9809.8		300				
	AFL		7471						
PKG:1									
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									

Y3510017	S		OXYGEN CYLINDER INSTALLATION - PERFORM VISUAL INSPECTION. CHECK PLUMBING FOR ROUTING, SECURITY, AND CONDITION					Service	ATA:35
	MOS		02-Aug-24		24				
	HRS		9525.7		600				
	AFL		7276						
PKG:7									
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									

ATA 36 - PNEUMATIC

212042			NO. 2 ENGINE OZONE CONVERTER					Component	ATA:36
PN:4520000100-801	MOS/MSC		01-Apr-22	O/C	TSN 0				
SN:2305	HRS		8936.8		TSN 0				
	AFL		6867		TSN 0				
PROC. REF: AMM 21-20-12PROC. REF: AMM 21-20-12									

361001			LEFT OUTBOARD HIGH PRESSURE TAILCONE MANIFOLD					Component	ATA:36
PN:PN	MOS/MSC		09-Mar-01	O/C	TSN 0				
SN:UNKNOWN	HRS		0		TSN 0				
	AFL		0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

361002			LEFT OUTBOARD ANTI-ICE MANIFOLD					Component	ATA:36
PN:PN	MOS/MSC		09-Mar-01	O/C	TSN 0				
SN:UNKNOWN	HRS		0		TSN 0				
	AFL		0		TSN 0				
PROC. REF: AMM 30-10-07PROC. REF: AMM 30-10-07									

361004			LEFT INBOARD HIGH-PRESSURE BLEED AIR MANIFOLD					Component	ATA:36
PN:PN	MOS/MSC		09-Mar-01	O/C	TSN 0				
SN:UNKNOWN	HRS		0		TSN 0				
	AFL		0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 36 - PNEUMATIC									
PROC. REF: AMM 36-10-07PROC. REF: AMM 36-10-07									
361005 RIGHT INBOARD HIGH-PRESSURE BLEED AIR MANIFOLD Component ATA:36									
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-10-07PROC. REF: AMM 36-10-07									
361016 RIGHT OUTBOARD ANTI-ICE MANIFOLD Component ATA:36									
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-10-07PROC. REF: AMM 30-10-07									
361020 LEFT HIGH PRESSURE OVER-TEMP SWITCH Component ATA:36									
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-20-03PROC. REF: AMM 36-20-03									
361021 RIGHT HIGH PRESSURE OVER-TEMP SWITCH Component ATA:36									
PN:641179-4	MOS/MSC	06-Jun-05	O/C						
SN:0766	HRS	3654.87							
	AFL	2759							
PROC. REF: AMM 36-20-03PROC. REF: AMM 36-20-03									
361031 ECS CONTROLLER Component ATA:36									
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-10-01PROC. REF: AMM 36-10-01									
361040 APU BLEED AIR CHECK VALVE Component ATA:36									
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-10-09PROC. REF: AMM 36-10-09									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 36 - PNEUMATIC									
361050 LOAD CONTROL SHUTOFF VALVE (L5003)									Component ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-10-10PROC. REF: AMM 36-10-10									
361053 NO. 1 ECS SHUTOFF (L37) VALVE									Component ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-10-03PROC. REF: AMM 36-10-03									
361054 NO. 2 ECS SHUTOFF (L38) VALVE									Component ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-10-03PROC. REF: AMM 36-10-03									
361065 LEFT TAILCONE HIGH PRESSURE SHUT-OFF VALVE (L39)									Component ATA:36
PN:3291216-2	MOS/MSC	09-Jun-05	O/C						
SN:736	HRS	3666.35							
	AFL	2768							
PROC. REF: AMM 36-10-02PROC. REF: AMM 36-10-02									
361066 RIGHT TAILCONE HIGH PRESSURE SHUT-OFF VALVE (L40)									Component ATA:36
PN:3291216-2	MOS/MSC	09-Jun-05	O/C						
SN:426	HRS	3666.35							
	AFL	2768							
PROC. REF: AMM 36-10-02PROC. REF: AMM 36-10-02									
361120 NO. 1 PRESSURE SWITCH (S79)									Component ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-10-06PROC. REF: AMM 36-10-06									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 36 - PNEUMATIC										
361121	NO. 2 PRESSURE SWITCH (S88)								Component	ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 36-10-06PROC. REF: AMM 36-10-06										
<hr/>										
361125	LEFT PYLON LOW PRESSURE TEMPERATURE SENSOR								Component	ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
<hr/>										
361126	RIGHT PYLON LOW PRESSURE TEMPERATURE SENSOR								Component	ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
<hr/>										
361127	LEFT TAILCONE LOW PRESSURE (2.0 DIAMETER) CHECK VALVE								Component	ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
<hr/>										
361128	RIGHT TAILCONE LOW PRESSURE (2.0 DIAMETER) CHECK VALVE								Component	ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
<hr/>										
361216	LEFT HIGH PRESSURE BLEED AIR MANIFOLD								Component	ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 36-10-07PROC. REF: AMM 36-10-07										

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 36 - PNEUMATIC									
361217 RIGHT HIGH PRESSURE BLEED AIR MANIFOLD									Component ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-10-07PROC. REF: AMM 36-10-07									
361301 APU SERVO AIR CHECK VALVE									Component ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-15-02PROC. REF: AMM 36-15-02									
361302 NO. 1 ENGINE SERVO AIR CHECK VALVE									Component ATA:36
PN:6608295-3	MOS/MSC	30-Apr-06	O/C						
SN:2360	HRS	4466.8							
	AFL	3408							
PROC. REF: AMM 36-15-02PROC. REF: AMM 36-15-02									
361303 NO. 2 ENGINE SERVO AIR CHECK VALVE									Component ATA:36
PN:6608295-3	MOS/MSC	30-Apr-06	O/C						
SN:2308	HRS	4466.8							
	AFL	3408							
PROC. REF: AMM 36-15-02PROC. REF: AMM 36-15-02									
362005 LEFT FORWARD TAILCONE OVERHEAT THERMOSTAT SWITCH (S145)									Component ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-20-02PROC. REF: AMM 36-20-02									
362006 RIGHT FORWARD TAILCONE OVERHEAT THERMOSTAT SWITCH (S146)									Component ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-20-02PROC. REF: AMM 36-20-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 36 - PNEUMATIC									
362007 LEFT AFT TAILCONE OVERHEAT THERMOSTAT SWITCH (S147)									Component ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-20-02PROC. REF: AMM 36-20-02									
362008 RIGHT AFT TAILCONE OVERHEAT THERMOSTAT SWITCH (S148)									Component ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-20-02PROC. REF: AMM 36-20-02									
5-19-00-D3610002 BORESCOPE INSPECTION HP BLEED AIR MANIFOLD ASSEMBLY ATTACH BRACKET ASSEMBLY FOR CRACKS AT WELD.(IRN D3610002)									Service ATA:36
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
A3610000 ^S ** BLEED AIR SYSTEM - PERFORM FUNCTIONAL TEST									Service ATA:36
	MOS	02-Aug-24	24					AIRWORTHINESS	
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 36-10-00PROC. REF: AMM 36-10-00									
A3610001 ^S ** PYLON OVERHEAT THERMOSTAT AND ELECTRICAL SYSTEM - PERFORM FUNCTIONAL TEST									Service ATA:36
	MOS	02-Aug-24	24					AIRWORTHINESS	
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 36-20-01PROC. REF: AMM 36-20-01									
D3610002 LEFT HIGH PRESSURE BLEED AIR MANIFOLD - PERFORM BORESCOPE INSPECTION OF ATTACH BRACKET ASSEMBLY FOR CRACKS AT WELD									Service ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C						
SN:UNKNOWN	HRS	0							
	AFL	0							
PROC. REF: AMM 36-10-07PROC. REF: AMM 36-10-07									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 36 - PNEUMATIC									
D3610002	RIGHT HIGH PRESSURE BLEED AIR MANIFOLD - PERFORM BORESCOPE INSPECTION OF ATTACH BRACKET ASSEMBLY FOR CRACKS AT WELD							Service	ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C						
SN:UNKNOWN	HRS	0							
	AFL	0							
PROC. REF: AMM 36-10-07PROC. REF: AMM 36-10-07									
P3610048	LEFT HIGH PRESSURE BLEED AIR MANIFOLD - PERFORM VISUAL INSPECTION							Service	ATA:36
	MOS	06-Dec-17							
	HRS	7770.3	3000		10770.3		747.2		
	AFL								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
P3610048	RIGHT HIGH PRESSURE BLEED AIR MANIFOLD - PERFORM VISUAL INSPECTION							Service	ATA:36
	MOS	20-Jul-15							
	HRS	7535.1	3000		10535.1		512		
	AFL								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
U3610075 ^S	ECS BLEED AIR "Y" MANIFOLD - PERFORM BORESCOPE INSPECTION							Service	ATA:36
	MOS	09-Mar-01							
	HRS	0	4800						
	AFL	0							
PROC. REF: AMM 36-10-00PROC. REF: AMM 36-10-00									
Y3610061 ^S	HIGH PRESSURE BLEED AIR SHUT-OFF VALVE IN-LINE FILTER - PERFORM CLEANING PROCEDURES							Service	ATA:36
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 36-10-02PROC. REF: AMM 36-10-02									
ATA 38 - WATER/WASTE									
380001	TOILET SERVICE PANEL							Component	ATA:38
PN:9600-102	MOS/MSC	09-Apr-06	O/C						
SN:SP1116	HRS								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 38 - WATER/WASTE									
AFL									
PROC. REF: AMM 38-30-05PROC. REF: AMM 38-30-05									
381009 TOILET HEATED DRAIN MAST Component ATA:38									
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
383001 TOILET -- Component ATA:38									
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 38-30-01PROC. REF: AMM 38-30-01									
383002 TOILET TIMER Component ATA:38									
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 38-30-02PROC. REF: AMM 38-30-02									
383005 TOILET WATER TANK Component ATA:38									
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
383011 LAVATORY SINK SHUT OFF VALVE Component ATA:38									
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
384025 TOILET PUMP Component ATA:38									
PN:5250-11A	MOS/MSC	12-Aug-15	O/C						
SN:P8851	HRS	7535.1							
	AFL	5764							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 38 - WATER/WASTE

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

384051 TOILET MACERATOR						Component	ATA:38
PN:5300-1	MOS/MSC	12-Aug-15	O/C	TSN 0			
SN:M5189	HRS	7535.1		TSN 0			
	AFL	5764		TSN 0			

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

389050 TOILET CLEAN WATER PUMP						Component	ATA:38
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0			
SN:UNKNOWN	HRS	0		TSN 0			
	AFL	0		TSN 0			

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

ATA 49 - AIRBORNE AUXILIARY POWER

490060 APU ELECTRONIC CONTROL UNIT (ECU)						Component	ATA:49
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0			
SN:UNKNOWN	HRS	0		TSN 0			
	AFL	0		TSN 0			

PROC. REF: AMM 49-60-04PROC. REF: AMM 49-60-04

491011 APU MAINTENANCE CONTROL PANEL						Component	ATA:49
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0			
SN:UNKNOWN	HRS	0		TSN 0			
	AFL	0		TSN 0			

PROC. REF: AMM 49-60-02PROC. REF: AMM 49-60-02

491020 APU COCKPIT CONTROL PANEL						Component	ATA:49
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0			
SN:UNKNOWN	HRS	0		TSN 0			
	AFL	0		TSN 0			

PROC. REF: AMM 49-60-01PROC. REF: AMM 49-60-01

494050 APU IGNITION UNIT						Component	ATA:49
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0			
SN:UNKNOWN	HRS	0		TSN 0			
	AFL	0		TSN 0			

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 49 - AIRBORNE AUXILIARY POWER										
PROC. REF: AMM 49-40-04PROC. REF: AMM 49-40-04										
<hr/>										
495001	TAILCONE APU COOLING FAN								Component	ATA:49
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 49-50-01PROC. REF: AMM 49-50-01										
<hr/>										
495002	TAILCONE ACCESS DOOR COOLING (B30) FAN								Component	ATA:49
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
<hr/>										
495040	APU THERMOSTAT (S175) SWITCH								Component	ATA:49
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
<hr/>										
495041	APU THERMOSTAT (S176) SWITCH								Component	ATA:49
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
<hr/>										
495201	STRUT SUPPORT ASSEMBLY								Component	ATA:49
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
<hr/>										
495202	STRUT SUPPORT ASSEMBLY								Component	ATA:49
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 49 - AIRBORNE AUXILIARY POWER										
497001	APU BITE INDICATOR								Component	ATA:49
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
<hr/>										
49APU1	APU								Component	ATA:49
PN:PN	MOS/MSC	E/C								
SN:UNKNOWN	HRS									
	AFL									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
<hr/>										
H4900011 ^S	** APU GENERATOR - PERFORM OVERVOLTAGE PROTECTION CHECK								Service	ATA:49
	MOS	09-Mar-01	48	AIRWORTHINESS						
	HRS	0	1200							
	AFL	0								
PROC. REF: AMM 49-40-01PROC. REF: AMM 49-40-01										
<hr/>										
Y4900000 ^S	AUXILIARY POWER UNIT - PERFORM VISUAL INSPECTION OF EXTERNAL FIREBOX INSTALLATION AND ATTACHING COMPONENTS								Service	ATA:49
	MOS	09-Mar-01	12							
	HRS	0	300							
	AFL	0								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
<hr/>										
Y4900010 ^S	APU ENGINE FIRE EXTINGUISHER CONTAINER - CHECK CONTAINER PRESSURE GAGE FOR PROPER PRESSURE								Service	ATA:49
	MOS	09-Mar-01	12							
	HRS	0	300							
	AFL	0								
PROC. REF: AMM 26-22-00PROC. REF: AMM 26-22-00										
<hr/>										
Y4900012 ^S	APU INLET SCREEN AND OPENING - PERFORM VISUAL INSPECTION								Service	ATA:49
	MOS	09-Mar-01	12							
	HRS	0	300							
	AFL	0								
PROC. REF: AMM 26-22-00PROC. REF: AMM 26-22-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 49 - AIRBORNE AUXILIARY POWER

PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00

Y4900013 ^S	APU EXHAUST DUCT AREA, INCLUDING FORWARD AND AFT APU EXHAUST FAIRINGS - PERFORM VISUAL INSPECTION							Service	ATA:49
	MOS	09-Mar-01	12						
	HRS	0	300						
	AFL	0							

PKG:2

PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00

ATA 52 - DOORS

521001	UPPER CABIN DOOR							Component	ATA:52
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					

PROC. REF: AMM 52-10-01PROC. REF: AMM 52-10-01

521002	LOWER CABIN DOOR							Component	ATA:52
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					

PROC. REF: AMM 52-10-01PROC. REF: AMM 52-10-01

521010	LOWER ENTRY DOOR FORWARD GAS DAMPER ASSEMBLY							Component	ATA:52
PN:SP21231-2	MOS/MSC	24-Jan-25	O/C	TSN 0					
SN:UNKNOWN	HRS	9595.4		TSN 0					
	AFL	7326		TSN 0					

PROC. REF: AMM 52-10-11PROC. REF: AMM 52-10-11

521011	LOWER ENTRY DOOR AFT GAS DAMPER ASSEMBLY							Component	ATA:52
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					

PROC. REF: AMM 52-10-11PROC. REF: AMM 52-10-11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 52 - DOORS										
522001	EMERGENCY EXIT DOOR ASSEMBLY								Component	ATA:52
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 52-20-01PROC. REF: AMM 52-20-01										
522010	EMERGENCY EXIT DOOR WINDOW								Component	ATA:52
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 52-20-06PROC. REF: AMM 52-20-06										
523001	TAILCONE BAGGAGE DOOR ASSEMBLY								Component	ATA:52
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
524001	TAILCONE ACCESS DOOR								Component	ATA:52
PN:4552405151-009	MOS/MSC	17-Feb-05	O/C	TSN 0						
SN:0316	HRS	3300.2		TSN 0						
	AFL	2515		TSN 0						
PROC. REF: AMM 52-40-02PROC. REF: AMM 52-40-02										
524010	SPPR DOOR ASSY								Component	ATA:52
PN:PN	MOS/MSC		O/C							
SN:UNKNOWN	HRS									
	AFL									
PROC. REF: AMM 52-40-03PROC. REF: AMM 52-40-03										
A5210009 ^S	* EMERGENCY EXIT DOOR RETAINERS - PERFORM VISUAL INSPECTION. INSPECT DOOR STOP FITTINGS ON EMERGENCY EXIT DOOR FRAMES IN FLANGE RADII. (F.S. 374 AND 394).								Service	ATA:52
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

PKG:26

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 52 - DOORS										
A5210012	S	* LOWER PASSENGER DOOR HINGE - PERFORM VISUAL INSPECTION. INSPECT PIANO HINGE LUGS AND FASTENERS.						Service	ATA:52	
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276							PKG:26	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
A5210014	S	* UPPER PASSENGER DOOR TENSION FITTINGS - PERFORM VISUAL INSPECTION. INSPECT THE FOLLOWING: A. TENSION STUDS AT RETAINING FLANGES. B. RADII AROUND FLANGE PERIPHERY.						Service	ATA:52	
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276							PKG:26	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
AA5210055	S	CABIN DOOR HANDLE RAMP ROLLER WHEEL - LUBRICATE						Service	ATA:52	
	MOS	22-Jun-23	48							
	HRS	9258.5	1200							
	AFL	7100							PKG:18	
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02										
D5210015	S	* EMERGENCY EXIT DOOR - PERFORM VISUAL INSPECTION. PAY PARTICULAR ATTENTION TO FLANGES AND FASTENER HOLES OF DOOR STOP FITTINGS.						Service	ATA:52	
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0							PKG:25	
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
E5210013	S	* UPPER AND LOWER PASSENGER DOOR LATCH ARMS AND DOOR ATTACHMENTS - PERFORM VISUAL INSPECTION						Service	ATA:52	
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0							PKG:25	
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 52 - DOORS										
F5210016	S	* UPPER PASSENGER DOOR HINGE - PERFORM VISUAL INSPECTION. INSPECT UPPER SURFACE OF HINGE FINGERS AT BASE OF LUG.						Service	ATA:52	
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
M5240004		AVIONIC ACCESS DOORS - PERFORM AVIONICS DOOR GAP AND MISMATCH INSPECTION						Service	ATA:52	
	MOS	10-Aug-24	24		10-Aug-26		179 d			
	HRS									
	AFL									
PROC. REF: AMM 52-40-01PROC. REF: AMM 52-40-01										
N5210010	S	* LOWER PASSENGER DOOR TENSION BOLTS, BOLT RETAINERS, TENSION FITTINGS, AND DOOR ATTACHMENTS - PERFORM VISUAL INSPECTION						Service	ATA:52	
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
N5210011	S	* UPPER AND LOWER PASSENGER DOOR LATCH PINS - PERFORM VISUAL INSPECTION. INSPECT BOLTS AND DOOR END RIB STRUCTURE AT LOCK PINS.						Service	ATA:52	
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
N5210017	S	* UPPER PASSENGER DOOR TENSION BOLTS, BOLT RETAINERS, TENSION FITTINGS, AND DOOR ATTACHMENTS - PERFORM VISUAL INSPECTION						Service	ATA:52	
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 52 - DOORS									
T5210003	S	EXTERNAL LOWER PASSENGER/CREW DOOR CABLES - PERFORM VISUAL INSPECTION OF VISIBLE PORTION OF CABLES AND HANDLE AREA.						Service	ATA:52
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							PKG:18
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
Y5210000	S	AVIONICS COMPARTMENT ACCESS DOORS AND SEALS - PERFORM VISUAL INSPECTION						Service	ATA:52
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							PKG:13
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
Y5210001	S	TAILCONE ACCESS DOOR AND SEAL - PERFORM VISUAL INSPECTION OF DOOR, SEALS, AND LATCHES						Service	ATA:52
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							PKG:12
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
Y5210002	S	BAGGAGE COMPARTMENT DOOR - PERFORM VISUAL INSPECTION OF DOORS, SEALS, AND LATCHES						Service	ATA:52
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							PKG:12
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
Y5210004	S	UPPER AND LOWER PASSENGER/CREW DOOR - PERFORM VISUAL INSPECTION OF DOOR STRUCTURE, TENSION FITTINGS, AND HINGE AREA FOR CRACKS AND CORROSION.						Service	ATA:52
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							PKG:18
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 52 - DOORS										
Y5210005	^S	INTERNAL LOWER PASSENGER/CREW DOOR CABLES - PERFORM VISUAL INSPECTION. REMOVE STEP SKIN TO GAIN ACCESS TO CABLES.						Service	ATA:52	
	MOS	09-Mar-01	48							
	HRS	0	1200							
	AFL	0								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
PKG:18										
Y5210006	^S	UPPER PASSENGER/CREW DOOR VENT DOOR SPRINGS - PERFORM VISUAL INSPECTION						Service	ATA:52	
	MOS	02-Aug-24	24							
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
PKG:12										
Y5210008	^S	EMERGENCY EXIT DOOR INTERNAL AND EXTERNAL HANDLE LATCHING MECHANISM. - PERFORM OPERATIONAL CHECK						Service	ATA:52	
	MOS	02-Aug-24	24							
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 52-20-07PROC. REF: AMM 52-20-07										
PKG:12										
Y5240000	^S	OXYGEN SYSTEM SERVICING DOOR AND LATCHES - PERFORM VISUAL INSPECTION FOR CONDITION AND SECURITY. CHECK DECAL FOR CONDITION AND LEGIBILITY.						Service	ATA:52	
	MOS	09-Mar-01	48							
	HRS	0	1200							
	AFL	0								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
PKG:13										
Y5240003	^S	SINGLE POINT REFUELING ACCESS DOOR - PERFORM VISUAL INSPECTION						Service	ATA:52	
	MOS	09-Mar-01	48							
	HRS	0	1200							
	AFL	0								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
PKG:14										

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 52 - DOORS										
Z5210053		CABIN MAIN ENTRY DOOR HANDLE - REPLACE							Service	ATA:52
	MOS	06-Jul-21	144		06-Jul-33		2701 d			
	HRS	8631.2								
	AFL	6618	6000		12618		5002			
PROC. REF: AMM 52-10-08, AMM 52-10-13PROC. REF: AMM 52-10-08, AMM 52-10-13										
ATA 53 - FUSELAGE										
530001		FUSELAGE ASSEMBLY							Component	ATA:53
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
531044		LEFT LOWER COUPE RAIL							Component	ATA:53
PN:PN	MOS/MSC		N/A	TSN 0				NOT APPLICABLE		
SN:UNKNOWN	HRS			TSN 0						
	AFL			TSN 0						
PROC. REF: AMM 53-10-04PROC. REF: AMM 53-10-04										
531045		RIGHT LOWER COUPE RAIL							Component	ATA:53
PN:PN	MOS/MSC		N/A	TSN 0				NOT APPLICABLE		
SN:UNKNOWN	HRS			TSN 0						
	AFL			TSN 0						
PROC. REF: AMM 53-10-04PROC. REF: AMM 53-10-04										
5323172 EMP		* SKIN CUT-OUT FOR IRIDIUM ANTENNAS, FS 283.88 TO FS 308.39 - PERFORM EDDY CURRENT INSPECTION							Service	ATA:53
	MOS/MSC	09-Mar-01	N/A					AIRWORTHINESS		
	HRS	0								
	AFL	0								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
535001		RADOME							Component	ATA:53
PN:6634408000-001	MOS/MSC	12-Dec-11	O/C	TSR 0						
SN:150	HRS	6763.5		TSR 0						
	AFL	5158		TSR 0						
PROC. REF: AMM 53-50-01PROC. REF: AMM 53-50-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 53 - FUSELAGE										
535601	LEFT DELTA FIN								Component	ATA:53
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 53-56-01PROC. REF: AMM 53-56-01										
535602	RIGHT DELTA FIN								Component	ATA:53
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 53-56-01PROC. REF: AMM 53-56-01										
545019	NO. 1 ENGINE AFT BEAM TO FRAME ATTACHMENT BOLT								Component	ATA:53
PN:PN	MOS/MSC	09-Mar-01	H/T	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
545020	NO. 2 ENGINE AFT BEAM TO FRAME ATTACHMENT BOLT								Component	ATA:53
PN:PN	MOS/MSC	09-Mar-01	H/T	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
A5310005 ^S	* FUSELAGE FUEL CELL CANTED BULKHEAD (F.S. 495) - PERFORM VISUAL INSPECTION, PAYING PARTICULAR ATTENTION TO MAIN CROSS MEMBER. INSPECT FLANGES AND ATTACHMENTS FOR CRACKING.								Service	ATA:53
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
A5310007 ^S	* AFT PRESSURE BULKHEAD BOTTOM SHEAR DIAPHRAGM - PERFORM DETAILED VISUAL INSPECTION. INSPECT BULKHEAD POST ATTACHMENT FASTENER HOLES AND CONTROL CABLE SLOT.								Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								
PKG:25										
PKG:26										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 53 - FUSELAGE

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

A5323022	^S	* NOSE LANDING GEAR AFT WHEELBOX CLOSING STRUCTURE (F.S. 150 TO F.S.162) - PERFORM VISUAL INSPECTION. INSPECT THE FOLLOWING: A. PANEL. B. CHANNEL STIFFENERS. C. SUPPORT ANGLE. D. ANGLE STIFFENER. E. ZEE STIFFENER						Service	ATA:53
	MOS	02-Aug-24					AIRWORTHINESS		
	HRS	9525.7	9600						
	AFL	7276							

PKG:26

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

A5323023	^S	* DRAG LINK ATTACHMENT LUG - PERFORM VISUAL INSPECTION						Service	ATA:53
	MOS	09-Mar-01					AIRWORTHINESS		
	HRS	0	T:9600						
	AFL	0							

PKG:25

PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00

A5360001	^S	DELTA FINS - WITH DELTA FINS REMOVED, VISUALLY INSPECT THE FOLLOWING: A. DELTA FIN AFT SPAR. B. DELTA FIN SUPPORT ANGLE. C. INSPECT STIFFENERS CONNECTING TO ATTACH FITTINGS.						Service	ATA:53
	MOS	02-Aug-24							
	HRS	9525.7	9600						
	AFL	7276							

PKG:26

PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00

D5323039	^S	* MACHINED FUSELAGE FRAME AT FS 466 - PERFORM DETAILED VISUAL INSPECTION BETWEEN STRINGER 13 LEFT AND RIGHT, PAYING PARTICULAR ATTENTION TO THE BL 10 SPLICES. CONFIRM ANY CRACK INDICATIONS WITH EDDY CURRENT PROCEDURES.						Service	ATA:53
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							

PKG:25

PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00

E5310001	^S	* LONGERON, INTERNAL (BETWEEN FS 384 AND FS 433) - PERFORM VISUAL INSPECTION						Service	ATA:53
	MOS	02-Aug-24					AIRWORTHINESS		
	HRS	9525.7	9600						
	AFL	7276							

PKG:26

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 53 - FUSELAGE

E5310002	S		* FLIGHT DECK LONGERON - PERFORM VISUAL INSPECTION (FS 149 - FS 196). INSPECT FLIGHT DECK LONGERON STIFFENERS, WEBS, AND CUTOUTS					Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							

PKG:26

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

E5310017	S		* AFT PRESSURE BULKHEAD BOTTOM CROSSMEMBER (FS 457) - PERFORM DETAILED VISUAL INSPECTION. INSPECT TEE-SECTION AT FS 457 FLANGE AT ATTACHMENT OF PRESSURE FLOOR.					Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							

PKG:26

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

E5310018	S		* AFT PRESSURE BULKHEAD PANEL FACING SHEETS (FS 457) - PERFORM VISUAL INSPECTION. INSPECT BOTH FRONT AND AFT OF FACING SHEETS.					Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							

PKG:26

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

E5323025	S		* FORWARD/AFT WHEELBOX JOINT (FS 150) - PERFORM VISUAL INSPECTION. INSPECT SPLICE STRAP AFT OF FORWARD PRESSURE BULKHEAD AT INTERSECTION OF ATTACHMENT ANGLE AND FLIGHT DECK LONGERON.					Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							

PKG:26

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

E5323050	S		* AFT POST/WINDSHIELD RETAINER ATTACHMENT - PERFORM EDDY CURRENT INSPECTION. INSPECT WINDSHIELD AFT POST AT WINDSHIELD RETAINER FASTENER HOLES.					Service	ATA:53
	MOS	09-Mar-01						AIRWORTHINESS	
	HRS	0	T:9600						
	AFL	0							

PKG:25

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 53 - FUSELAGE

PROC. REF: NDT PART 6/53-30-04PROC. REF: NDT PART 6/53-30-04

E5323053	^S	* FRAME ATTACHMENTS TO UPPER AND LOWER COUPE RAILS (FS 171 TO FS 204) - PERFORM VISUAL INSPECTION. INSPECT THE FOLLOWING: A. FRAME ATTACHMENTS TO LOWER COUPE RAILS AT FS 171, FS 182, FS 196, AND FS 204. B. FRAME ATTACHMENTS TO UPPER COUPE RAILS AT FS 196 AND FS 204. C. GUSSETS AT FASTENER HOLES.						Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:26

E5323054	^S	* TIE-ROD ASSEMBLY (FS 162) (ALUMINUM ENDS) - PERFORM VISUAL INSPECTION. INSPECT TIE-ROD ENDS, TIE-ROD TUBES, AND TIE-ROD BOLTS.						Service	ATA:53
	MOS	09-Mar-01						AIRWORTHINESS	
	HRS	0	4800						
	AFL	0							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:25

E5323055	^S	* TIE-ROD ASSEMBLY (FS 162) (TITANIUM ENDS) - PERFORM VISUAL INSPECTION. INSPECT TIE-ROD ENDS, TIE-ROD TUBES, AND TIE-ROD BOLTS.						Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:26

E5323068	^S	* STRINGER 1RH BETWEEN F.S. 533 AND F.S. 543 - PERFORM VISUAL INSPECTION. INSPECT STRINGER 1 FLANGE AND SKIN ALONG STRINGER 1 BETWEEN F.S. 533 AND F.S. 543.						Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:26

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 53 - FUSELAGE										
E5323073	^S	* FUSELAGE BOTTOM SKIN PANEL - PERFORM VISUAL INSPECTION. INSPECT CORNER RADIUS AT JUNCTION OF EXTERNAL LONGERON AND MID SPAR FRAME (F.S. 435).							Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								
PKG:26										
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
E5323074	^S	* AUXILIARY SKIN PANEL - PERFORM VISUAL INSPECTION. INSPECT CORNER RADIUS AT JUNCTION OF KEEL BEAM AND REAR SPAR FRAME (F.S. 466).							Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								
PKG:26										
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
E5350000	^S	* BOTTOM KEEL BEAM END PADS (F.S. 384 - F.S. 486) - PERFORM VISUAL INSPECTION. INSPECT END PADS AROUND BOLT HOLES AND IN RADII AT F.S. 433.							Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								
PKG:26										
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
F5323056	^S	* TIE-ROD FORK ENDS (ALUMINUM) - PERFORM FLUORESCENT PENETRANT INSPECTION							Service	ATA:53
	MOS/MSC	09-Mar-01	N/A					NOT APPLICABLE		
	HRS	0								
	AFL	0								
PKG:25										
PROC. REF: NDT PART 8/53-10-01PROC. REF: NDT PART 8/53-10-01										
F5323081	^S	* TIE-ROD FORK ENDS - PERFORM FLUORESCENT PENETRANT INSPECTION							Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								
PKG:26										
PROC. REF: NDT PART 8/53-10-01PROC. REF: NDT PART 8/53-10-01										

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 53 - FUSELAGE										
F5331021	S	* FORWARD CANTED BULKHEAD (F.S. 630) - PERFORM VISUAL INSPECTION. INSPECT AT FRONT SPAR UPPER ATTACHMENT FASTENERS.						Service	ATA:53	
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0							PKG:25	
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
F5331022	S	* MID CANTED BULKHEAD (F.S. 657) - PERFORM VISUAL INSPECTION AT MID SPAR UPPER ATTACHMENT FASTENERS						Service	ATA:53	
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276							PKG:26	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
F5331023	S	* AFT CANTED BULKHEAD (F.S. 682) - PERFORM VISUAL INSPECTION. INSPECT AT REAR SPAR ATTACHMENT FASTENERS.						Service	ATA:53	
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276							PKG:26	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
F5331024	S	* VERTICAL STABILIZER FRONT SPAR ROOT BULKHEAD ATTACHMENT (F.S. 630) - PERFORM VISUAL INSPECTION. INSPECT FRONT SPAR ROOT BULKHEAD ATTACHMENT AT FASTENER HOLES.						Service	ATA:53	
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276							PKG:26	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
F5331025	S	* VERTICAL STABILIZER MID SPAR ROOT BULKHEAD ATTACHMENT (F.S. 657) - PERFORM VISUAL INSPECTION. INSPECT MID SPAR ROOT BULKHEAD ATTACHMENT AT FASTENER HOLES.						Service	ATA:53	
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276							PKG:26	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 53 - FUSELAGE

F5331026 ^S			* VERTICAL STABILIZER REAR SPAR ROOT BULKHEAD ATTACHMENT (F.S. 682) - PERFORM VISUAL INSPECTION. INSPECT REAR SPAR ROOT BULKHEAD ATTACHMENT AT FASTENER HOLES.						Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								

PKG:26

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

H5323032			* EXTERIOR CABIN WINDOW COAMINGS (UNPAINTED) - PERFORM EDDY CURRENT INSPECTION						Service	ATA:53
	MOS	11-Mar-25	24		11-Mar-27		392 d	AIRWORTHINESS		
	HRS	9645.6	2400		12045.6		2022.5			
	AFL	7359								

PROC. REF: NDT PART 6/56-20-01PROC. REF: NDT PART 6/56-20-01

H5323092			* EXTERIOR CABIN WINDOW COAMINGS (PAINTED) - PERFORM EDDY CURRENT INSPECTION						Service	ATA:53
	MOS/MSC	30-Apr-06	N/A							
	HRS	4466.8								
	AFL	3408								

PROC. REF: NDT PART 6/56-20-01PROC. REF: NDT PART 6/56-20-01

M5313001			FORWARD FUSELAGE SKIN - PERFORM PITOT-STATIC PROBE ZONE SKIN CONTOUR CHECK						Service	ATA:53
	MOS	10-Aug-24	24		10-Aug-26		179 d			
	HRS									
	AFL									

PROC. REF: AMM 53-00-01PROC. REF: AMM 53-00-01

M5323021 ^S			* EXTERNAL LONGERON, FASTENER LOCATIONS, AND AREA AROUND WING ATTACHMENTS - PERFORM VISUAL INSPECTION. INSPECT LONGERON BETWEEN FS 398 AND FS 486, STRINGER 13 LEFT AND RIGHT						Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								

PKG:26

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty		
ATA 53 - FUSELAGE											
M5323034 ^S			* UPPER AND LOWER COUPE RAIL AND CENTER POST/WINDSHIELD RETAINER ATTACHMENT - PERFORM EDDY CURRENT INSPECTION							Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS			
	HRS	9525.7	9600								
	AFL	7276									
PROC. REF: NDT PART 6/53-30-03PROC. REF: NDT PART 6/53-30-03											
PKG:26											
N5314000 ^S			* EMERGENCY EXIT DOOR SKIN CUTOUT CORNERS AND DOUBLERS (F.S. 370 - F.S. 398) - PERFORM EDDY CURRENT INSPECTION							Service	ATA:53
	MOS	25-Nov-19	96					AIRWORTHINESS			
	HRS	8177.7	2400								
	AFL	6303									
PROC. REF: NDT PART 6/53-30-01PROC. REF: NDT PART 6/53-30-01											
PKG:19											
N5323026 ^S			* UPPER AND LOWER PASSENGER/CREW DOOR SKIN CUTOUT CORNERS (FS 224 - FS 256) - PERFORM EDDY CURRENT INSPECTION. INSPECT SKIN AT CORNERS OF PASSENGER/ CREW DOOR CUTOUT.							Service	ATA:53
	MOS	25-Nov-19	96					AIRWORTHINESS			
	HRS	8177.7	2400								
	AFL	6303									
PROC. REF: NDT PART 6/53-30-02PROC. REF: NDT PART 6/53-30-02											
PKG:19											
P5310003 ^S			* AFT PRESSURE BULKHEAD SUPPORT POST (FS 457) - PERFORM EDDY CURRENT INSPECTION							Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS			
	HRS	9525.7	9600								
	AFL	7276									
PROC. REF: NDT PART 6/53-30-18PROC. REF: NDT PART 6/53-30-18											
PKG:26											
P5310004 ^S			* AFT PRESSURE BULKHEAD FRAME PERIPHERY - PERFORM EDDY CURRENT INSPECTION							Service	ATA:53
	MOS	09-Mar-01						AIRWORTHINESS			
	HRS	0	T:9600								
	AFL	0									
PROC. REF: NDT PART 6/53-30-21PROC. REF: NDT PART 6/53-30-21											
PKG:25											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty		
ATA 53 - FUSELAGE											
P5310006 ^S			* FORWARD PRESSURE BULKHEAD - PERFORM EDDY CURRENT INSPECTION							Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS			
	HRS	9525.7	9600								
	AFL	7276									
PROC. REF: NDT PART 6/53-30-07PROC. REF: NDT PART 6/53-30-07											
P5320001 ^S * FUSELAGE PRESSURE FLOOR STEP (FS 433 - FS 457) - PERFORM EDDY CURRENT INSPECTION											
	MOS	02-Aug-24						AIRWORTHINESS			
	HRS	9525.7	9600								
	AFL	7276									
PROC. REF: NDT PART 6/53-20-01PROC. REF: NDT PART 6/53-20-01											
P5323024 ^S * FUSELAGE SKIN CUT-OUTS ABOVE FUEL CELL - PERFORM EDDY CURRENT INSPECTION											
	MOS	09-Mar-01						AIRWORTHINESS			
	HRS	0	T:9600								
	AFL	0									
PROC. REF: NDT PART 6/53-30-12PROC. REF: NDT PART 6/53-30-12											
P5323027 ^S * FUSELAGE FRAME AT FS 412 - PERFORM EDDY CURRENT INSPECTION											
	MOS	09-Mar-01						AIRWORTHINESS			
	HRS	0	T:9600								
	AFL	0									
PROC. REF: NDT PART 6/53-30-20PROC. REF: NDT PART 6/53-30-20											
P5323029 ^S * MACHINED SPAR FRAMES SYSTEMS CUTOUTS (FS 398, FS 412, FS 432, FS 466) - PERFORM EDDY CURRENT INSPECTION											
	MOS	09-Mar-01						AIRWORTHINESS			
	HRS	0	T:9600								
	AFL	0									
PROC. REF: NDT PART 6/53-30-15PROC. REF: NDT PART 6/53-30-15											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 53 - FUSELAGE										
P5323033 ^S			* FUSELAGE SKIN AT EMERGENCY DOOR EGRESS-LIGHT AND WING INSPECTION LIGHT - PERFORM EDDY CURRENT INSPECTION						Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								
PROC. REF: NDT PART 6/53-40-02PROC. REF: NDT PART 6/53-40-02										
PKG:26										
P5323037 ^S			* WINDSHIELD COUPE RAIL TIE ROD BRACKET - PERFORM EDDY CURRENT INSPECTION						Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								
PROC. REF: NDT PART 6/53-30-09PROC. REF: NDT PART 6/53-30-09										
PKG:26										
P5323038 ^S			* WINDSHIELD CENTER POST TO UPPER COUPE RAIL JOINT ATTACHMENT - PERFORM EDDY CURRENT INSPECTION						Service	ATA:53
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0								
PROC. REF: NDT PART 6/53-30-22PROC. REF: NDT PART 6/53-30-22										
PKG:25										
P5323047 ^S			* PRESSURE CABIN FUSELAGE CROWN SKIN - PERFORM EDDY CURRENT INSPECTION						Service	ATA:53
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0								
PROC. REF: NDT PART 6/53-10-04PROC. REF: NDT PART 6/53-10-04										
PKG:19										
P5323049 ^S			* FUSELAGE SKIN AT UPPER AND LOWER COUPE RAIL RUN-OUT JOINTS - PERFORM EDDY CURRENT INSPECTION						Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								
PROC. REF: NDT PART 6/53-30-11PROC. REF: NDT PART 6/53-30-11										
PKG:26										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 53 - FUSELAGE										
P5323057	S	* PRESSURE CABIN SKIN AT FUSELAGE STATION 451 - PERFORM EDDY CURRENT INSPECTION							Service	ATA:53
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0								
PROC. REF: NDT PART 6/53-30-06PROC. REF: NDT PART 6/53-30-06										
PKG:19										
P5323058	S	* FUSELAGE SKIN AT F.S. 504 - PERFORM EDDY CURRENT INSPECTION							Service	ATA:53
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0								
PROC. REF: NDT PART 6/53-30-13PROC. REF: NDT PART 6/53-30-13										
PKG:25										
P5323069	S	* CIRCUMFERENTIAL SKIN JOINT AT FORWARD PRESSURE BULKHEAD - PERFORM EDDY CURRENT INSPECTION							Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								
PROC. REF: NDT PART 6/53-30-08PROC. REF: NDT PART 6/53-30-08										
PKG:26										
P5323164	S	* PERFORM FUSELAGE SKIN AND DOUBLER AROUND ECS DUCT CUTOUT - EDDY CURRENT INSPECTION.							Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								
PROC. REF: NDT PART 6/53-40-01PROC. REF: NDT PART 6/53-40-01										
PKG:26										
P5323165	S	* WINDSHIELD CENTER POST TO LOWER COUPE RAIL JOINT ATTACHMENT - PERFORM EDDY CURRENT INSPECTION							Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								
PROC. REF: NDT PART 6/53-30-10PROC. REF: NDT PART 6/53-30-10										
PKG:26										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 53 - FUSELAGE										
P5360006 ^S			DELTA FIN ATTACH BOLT - PERFORM LIQUID PENETRANT INSPECTION						Service	ATA:53
	MOS		02-Aug-24							
	HRS		9525.7		9600					
	AFL		7276							
PROC. REF: NDT PART 8/53-10-02PROC. REF: NDT PART 8/53-10-02										
PKG:26										
Q5310023 ^S			FORWARD AND AFT FUEL CELL BAY STRUCTURE, ANGLE REINFORCEMENT, STRINGER 1, LEFT AND RIGHT - PERFORM DETAILED VISUAL INSPECTION OF HI-LITE COLLARS						Service	ATA:53
	MOS		02-Aug-24							
	HRS		9525.7		9600					
	AFL		7276							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
PKG:26										
Q5310025 ^S			AFT FUSELAGE KEELBEAM LONGERON (LEFT AND RIGHT, BL 5.15, FS 466.30 - 495.12) AND AFT FUSELAGE KEELBEAM LOWER FRAME (FS 466.30, BL 9.55 LEFT THROUGH BL 9.55 RIGHT) - PERFORM DETAILED VISUAL INSPECTION OF HI-LITE COLLARS.						Service	ATA:53
	MOS		02-Aug-24							
	HRS		9525.7		9600					
	AFL		7276							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
PKG:26										
Q5323048 ^S			* FUSELAGE (PRESSURE CABIN) - PERFORM EDDY CURRENT INSPECTION INSPECT PRESSURE CABIN SKIN (LONGITUDINAL SKIN CRACKING)						Service	ATA:53
	MOS		09-Mar-01					AIRWORTHINESS		
	HRS		0		T:9600					
	AFL		0							
PROC. REF: NDT PART 6/53-30-05PROC. REF: NDT PART 6/53-30-05										
PKG:25										
Q5323051 ^S			* LONGITUDINAL JOINTS INSIDE PRESSURE CABIN (FS 220 - FS 457) AND SKIN WITHIN ONE STRINGER BAY OF JOINT - PERFORM EDDY CURRENT INSPECTION. INSPECT SKIN FASTENER HOLES ALONG JOINTS AT STRINGER 10 LEFT AND RH, STRINGER 2 RIGHT, AND STRINGER 18 RIGHT						Service	ATA:53
	MOS		09-Mar-01					AIRWORTHINESS		
	HRS		0		T:9600					
	AFL		0							
PROC. REF: NDT PART 6/53-30-05PROC. REF: NDT PART 6/53-30-05										
PKG:25										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 53 - FUSELAGE										
Q5323059 ^S			* STRINGER TO FRAME JOINTS (FS 162 TO FS 213) - PERFORM EDDY CURRENT INSPECTION. INSPECT SKIN, STRINGERS, AND FRAMES AT JOINTS.						Service	ATA:53
	MOS		02-Aug-24					AIRWORTHINESS		
	HRS		9525.7	9600						
	AFL		7276							
PROC. REF: NDT PART 6/53-30-05PROC. REF: NDT PART 6/53-30-05										
PKG:26										
T5310027 ^S			* AFT PRESSURE BULKHEAD TOP MOUNTING STRUCTURE - PERFORM EDDY CURRENT INSPECTION.						Service	ATA:53
	MOS		02-Aug-24					AIRWORTHINESS		
	HRS		9525.7	9600						
	AFL		7276							
PROC. REF: NDT PART 6/53-30-17PROC. REF: NDT PART 6/53-30-17										
PKG:26										
T5321089 ^S			SEAT RAILS - PERFORM DETAILED INSPECTION OF SEAT RAIL (TRACK) SHEAR WEBS FOR CRACKING						Service	ATA:53
	MOS		02-Aug-24	24						
	HRS		9525.7	600						
	AFL		7276							
PROC. REF: AMM 53-20-01PROC. REF: AMM 53-20-01										
PKG:7										
T5323028 ^S			* FUSELAGE TO WING ATTACH FITTINGS - PERFORM EDDY CURRENT INSPECTION						Service	ATA:53
	MOS		09-Mar-01					AIRWORTHINESS		
	HRS		0	T:9600						
	AFL		0							
PROC. REF: NDT PART 6/53-30-16PROC. REF: NDT PART 6/53-30-16										
PKG:25										
T5323166			* EXTERNAL SKIN CUT-OUTS/PENETRATIONS (PRESSURE CABIN) - PERFORM DETAILED VISUAL INSPECTION. INSPECT SKIN AND DOUBLERS AT ANTENNAS, ELECTRICAL COMPONENTS, AND ACCESS PANELS (EXCLUDING PITOT/STATIC PROBES, AOA STALL VANES, AND WING INSPECTION LIGHT).						Service	ATA:53
	MOS		02-Aug-24	144	02-Aug-36		3824 d	AIRWORTHINESS		
	HRS		9525.7	9600	19125.7		9102.6			
	AFL		7276							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 53 - FUSELAGE										
V5323168	* LOWER COUPE RAIL RADIUS/WINDSCREEN RETAINER ATTACH - PERFORM EDDY CURRENT INSPECTION								Service	ATA:53
	MOS	22-Jun-23						AIRWORTHINESS		
	HRS	9258.5	5000		14258.5		4235.4			
	AFL	7100								
PROC. REF: NDT PART 6/53-30-23, NDT PART 6/53-30-24PROC. REF: NDT PART 6/53-30-23, NDT PART 6/53-30-24										
Y5311001 ^S	NOSE LANDING GEAR ACTUATOR ATTACH FITTING AND SURROUNDING STRUCTURE - PERFORM VISUAL INSPECTION								Service	ATA:53
	MOS	09-Mar-01	48							
	HRS	0	1200							
	AFL	0								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
Y5311003 ^S	NOSE LANDING GEAR TRUNNION FITTING AND SURROUNDING STRUCTURE - PERFORM VISUAL INSPECTION								Service	ATA:53
	MOS	09-Mar-01	48							
	HRS	0	1200							
	AFL	0								
PROC. REF: AMM 05-10-00PKG:17										
Y5320000 ^S	CENTER PEDESTAL - PERFORM VISUAL INSPECTION								Service	ATA:53
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 05-10-00PKG:1										
Y5321010 ^S	FLOORBOARDS AROUND GALLEY, LAVATORY, AND WATER TANK - PERFORM VISUAL INSPECTION								Service	ATA:53
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 53-20-01PKG:1										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 53 - FUSELAGE										
Y5321011 ^S	TAILCONE BAGGAGE COMPARTMENT - PERFORM VISUAL INSPECTION								Service	ATA:53
	MOS	02-Aug-24	24							
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
Y5321088 ^S	SEAT RAILS - REMOVE FLOORBOARD 230AL AND PERFORM VISUAL INSPECTION OF SEAT RAILS.								Service	ATA:53
	MOS	09-Mar-01	48							
	HRS	0	1200							
	AFL	0								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
Y5323020 ^S	EXTERNAL FUSELAGE (PRESSURE CABIN) - PERFORM VISUAL INSPECTION OF ALL CABIN SKINS FROM F.S. 100 TO F.S.458. PAY PARTICULAR ATTENTION TO ALL CUTOUTS AND SKIN JOINTS. NO FAIRING ACCESS REQUIRED.								Service	ATA:53
	MOS	09-Mar-01	48							
	HRS	0	1200							
	AFL	0								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
Y5323031 ^S	EXTERIOR CABIN WINDOW COAMINGS AND SURROUNDING FUSELAGE SKIN - PERFORM VISUAL INSPECTION USING 10X MAGNIFICATION AND ADEQUATE LIGHTING.								Service	ATA:53
	MOS	09-Mar-01	48							
	HRS	0	1200							
	AFL	0								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
Y5340007 ^S	WING ATTACH FITTINGS - PERFORM VISUAL INSPECTION								Service	ATA:53
	MOS	25-Nov-19	96							
	HRS	8177.7	2400							
	AFL	6303								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 53 - FUSELAGE										
Y5360000 ^S	DELTA FINS - PERFORM VISUAL INSPECTION								Service	ATA:53
	MOS	02-Aug-24	24							
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
ATA 54 - NACELLES/PYLONS										
A5450022	* NO. 1 ENGINE AFT MOUNT TO END FITTING ATTACH BOLT - REPLACE OR PERFORM MAGNETIC PARTICLE INSPECTION								Service	ATA:54
	MOS	26-Jul-23						LIFE LIMIT		
	HRS	9278	9600		10770.3 (M)		747.2			
	AFL	7111								
A5450022	* NO. 2 ENGINE AFT MOUNT TO END FITTING ATTACH BOLT - REPLACE OR PERFORM MAGNETIC PARTICLE INSPECTION								Service	ATA:54
	MOS	26-Jul-23						LIFE LIMIT		
	HRS	9278	9600		10535.1 (M)		512			
	AFL	7111								
A5450026 ^S	* ENGINE DRAG STRUT - PERFORM EDDY CURRENT INSPECTION								Service	ATA:54
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0								
PROC. REF: NDT PART 6/54-50-01PROC. REF: NDT PART 6/54-50-01										
A5450028	NO. 1 ENGINE AFT ENGINE BEAM END FITTING - REPLACE								Service	ATA:54
	MOS/MSC	09-Mar-01	N/A					N/A BY SERIAL NUMBER		
	HRS	0								
	AFL	0								
PROC. REF: AMM 53-40-02PROC. REF: AMM 53-40-02										

PKG:8

PKG:25

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 54 - NACELLES/PYLONS									
AB5450054	LEFT FORWARD ENGINE BEAM AND BEAM FITTING - PERFORM VISUAL INSPECTION, PAYING PARTICULAR ATTENTION OF THE FOLLOWING: A. UPPER CAPPING PLATE AT FASTENER HOLES, AND CHANNEL FLANGE AT FASTENER HOLES. B. BOLT HOLES, ESPECIALLY UPPER BOLT HOLE ON AFT FLANGE.							Service	ATA:54
	MOS	26-Jul-23							
	HRS	9278	6000		15278		5254.9		
	AFL	7111							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
AB5450054	RIGHT FORWARD ENGINE BEAM AND BEAM FITTING - PERFORM VISUAL INSPECTION, PAYING PARTICULAR ATTENTION OF THE FOLLOWING: A. UPPER CAPPING PLATE AT FASTENER HOLES, AND CHANNEL FLANGE AT FASTENER HOLES. B. BOLT HOLES, ESPECIALLY UPPER BOLT HOLE ON AFT FLANGE.							Service	ATA:54
	MOS	26-Jul-23							
	HRS	9278	6000		15278		5254.9		
	AFL	7111							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
E5450029 ^S	* AFT ENGINE BEAM - PERFORM VISUAL INSPECTION INSPECT UPPER CAPPING PLATE, AROUND FASTENER HOLES IN THE CAPPING PLATE, AND CHANNEL FLANGE.							Service	ATA:54
	MOS	09-Mar-01						AIRWORTHINESS	
	HRS	0	T:9600						
	AFL	0							PKG:25
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
F5450019 ^S	* AFT ENGINE BEAM ATTACHMENT TO FRAMES - PERFORM VISUAL INSPECTION. INSPECT AFT ENGINE BEAM ATTACHMENT TO FRAMES.							Service	ATA:54
	MOS	09-Mar-01						AIRWORTHINESS	
	HRS	0	T:9600						
	AFL	0							PKG:25
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
H5450012 ^S	* FRAMES 39/40 (F.S. 512/518) AT ENGINE BEAM ATTACHMENT - PERFORM EDDY CURRENT INSPECTION. INSPECT OUTER FLANGE AND FRAME WEB AT ENGINE BEAM ATTACHMENT.							Service	ATA:54
	MOS	09-Mar-01						AIRWORTHINESS	
	HRS	0	T:9600						
	AFL	0							PKG:25
PROC. REF: NDT PART 6/54-50-03PROC. REF: NDT PART 6/54-50-03									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty		
ATA 54 - NACELLES/PYLONS											
M5450015 ^S			* FORWARD ENGINE BEAM, SPAR CAP, AND WEB - PERFORM EDDY CURRENT INSPECTION							Service	ATA:54
	MOS	09-Mar-01						AIRWORTHINESS			
	HRS	0		T:9600							
	AFL	0									
PROC. REF: NDT PART 6/54-50-05PROC. REF: NDT PART 6/54-50-05											
PKG:25											
M5450018 ^S			* FORWARD ENGINE MOUNT ATTACHMENT BOLTS - PERFORM FLUORESCENT LIQUID PENETRANT INSPECTION							Service	ATA:54
	MOS	09-Mar-01						AIRWORTHINESS			
	HRS	0		T:9600							
	AFL	0									
PROC. REF: NDT PART 8/71-20-01PROC. REF: NDT PART 8/71-20-01											
PKG:25											
M5450027			NO. 1 ENGINE FORWARD ENGINE BEAM END FITTING - REPLACE							Service	ATA:54
	MOS/MS	09-Mar-01		N/A							
	HRS	0									
	AFL	0									
PROC. REF: AMM 53-40-02PROC. REF: AMM 53-40-02											
P5450011 ^S			* DRAG STRUT ATTACHMENT FITTINGS - PERFORM EDDY CURRENT INSPECTION							Service	ATA:54
	MOS	09-Mar-01						AIRWORTHINESS			
	HRS	0		T:9600							
	AFL	0									
PROC. REF: NDT PART 6/53-10-03PROC. REF: NDT PART 6/53-10-03											
PKG:25											
P5450016 ^S			* FORWARD ENGINE BEAM END FITTING - PERFORM EDDY CURRENT INSPECTION							Service	ATA:54
	MOS	09-Mar-01						AIRWORTHINESS			
	HRS	0		T:9600							
	AFL	0									
PROC. REF: NDT PART 6/54-50-02PROC. REF: NDT PART 6/54-50-02											
PKG:25											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty		
ATA 54 - NACELLES/PYLONS											
P5450017 ^S			* FORWARD ENGINE BEAM TO FRAME ATTACH BOLT - PERFORM LIQUID PENETRANT INSPECTION							Service	ATA:54
	MOS	09-Mar-01						AIRWORTHINESS			
	HRS	0		T:9600							
	AFL	0									
PROC. REF: NDT PART 8/53-40-01PROC. REF: NDT PART 8/53-40-01											
P5450020			* NO. 1 ENGINE AFT BEAM TO FRAME ATTACHMENT BOLT - REPLACE OR PERFORM LIQUID PENETRANT INSPECTION							Service	ATA:54
	MOS	26-Jul-23						LIFE LIMIT			
	HRS	9278	9600		10770.3 (M)		747.2				
	AFL	7111									
P5450020			* NO. 2 ENGINE AFT BEAM TO FRAME ATTACHMENT BOLT - REPLACE OR PERFORM LIQUID PENETRANT INSPECTION							Service	ATA:54
	MOS	26-Jul-23						LIFE LIMIT			
	HRS	9278	9600		10535.1 (M)		512				
	AFL	7111									
P5450021 ^S			* ENGINE AFT ISOLATOR MOUNT FITTINGS - PERFORM LIQUID PENETRANT INSPECTION							Service	ATA:54
	MOS	09-Mar-01						AIRWORTHINESS			
	HRS	0		T:9600							
	AFL	0									
PROC. REF: NDT PART 8/71-20-03PROC. REF: NDT PART 8/71-20-03											
P5450023			* NO. 1 ENGINE TO AFT ENGINE MOUNT ATTACH BOLTS - REPLACE OR PERFORM LIQUID PENETRANT INSPECTION							Service	ATA:54
	MOS	26-Jul-23						LIFE LIMIT			
	HRS	9278	9600		10770.3 (M)		747.2				
	AFL	7111									
P5450023			* NO. 2 ENGINE TO AFT ENGINE MOUNT ATTACH BOLTS - REPLACE OR PERFORM LIQUID PENETRANT INSPECTION							Service	ATA:54
	MOS	26-Jul-23						LIFE LIMIT			
	HRS	9278	9600		10535.1 (M)		512				
	AFL	7111									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 54 - NACELLES/PYLONS									
P5450024 ^S	* FUSELAGE FRAMES AT FS 543.55 AND 546.15 TO AFT ENGINE BEAM ATTACHMENT - PERFORM EDDY CURRENT INSPECTION.							Service	ATA:54
	MOS	09-Mar-01						AIRWORTHINESS	
	HRS	0	T:9600						
	AFL	0							PKG:25
PROC. REF: NDT PART 6/53-30-14PROC. REF: NDT PART 6/53-30-14									
P5450025 ^S	* FORWARD ENGINE BEAM AND FRAMES AT ATTACH HOLES - PERFORM EDDY CURRENT INSPECTION							Service	ATA:54
	MOS	09-Mar-01						AIRWORTHINESS	
	HRS	0	T:9600						
	AFL	0							PKG:25
PROC. REF: NDT PART 6/54-50-03PROC. REF: NDT PART 6/54-50-03									
P5450030 ^S	* AFT ENGINE BEAM END FITTING - PERFORM EDDY CURRENT INSPECTION							Service	ATA:54
	MOS	09-Mar-01						AIRWORTHINESS	
	HRS	0	T:9600						
	AFL	0							PKG:25
PROC. REF: NDT PART 6/54-50-04PROC. REF: NDT PART 6/54-50-04									
Y5410002 ^S	PYLONS - PERFORM VISUAL INSPECTION. INSPECT HILITE COLLARS COMMON TO MAIN ENGINE BEAM EXTERNAL TO FUSELAGE.							Service	ATA:54
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							PKG:14
PROC. REF: AMM 54-00-01PROC. REF: AMM 54-00-01									
ATA 55 - STABILIZERS									
551005	HORIZONTAL STABILIZER ASSEMBLY							Component	ATA:55
PN:PN	MOS/MSC	02-Aug-24	O/C						
SN:UNKNOWN	HRS	9525.7							
	AFL	7276							
Special Properties: RII ITEM									
PROC. REF: AMM 27-40-01PROC. REF: AMM 27-40-01									

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 55 - STABILIZERS

552031	LEFT ELEVATOR ASSEMBLY							Component	ATA:55
PN:4555201005-011	MOS/MSC	02-Aug-24	O/C						
SN:UNKNOWN	HRS	9525.7							
	AFL	7276							
Special Properties: RII ITEM									
PROC. REF: AMM 27-30-01PROC. REF: AMM 27-30-01									

552032	RIGHT ELEVATOR ASSEMBLY							Component	ATA:55
PN:4555201005-012	MOS/MSC	02-Aug-24	O/C						
SN:UNKNOWN	HRS	9525.7							
	AFL	7276							
Special Properties: RII ITEM									
PROC. REF: AMM 27-30-01PROC. REF: AMM 27-30-01									

553000	TAILCONE/VERTICAL STABILIZER ASSEMBLY							Component	ATA:55
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

554005	RUDDER ASSEMBLY							Component	ATA:55
PN:4555401000-023	MOS/MSC	02-Aug-24	O/C						
SN:UNKNOWN	HRS	9525.7							
	AFL	7276							
Special Properties: RII ITEM									
PROC. REF: AMM 27-20-01PROC. REF: AMM 27-20-01									

A5510014 ^S	* VERTICAL STABILIZER PIVOT FITTING BOTTOM PLATE - PERFORM DETAILED VISUAL INSPECTION. INSPECT AFT PORTION OF BOTTOM PLATE THROUGH LIGHTENING HOLE IN TOP PLATE, FORWARD PORTION OF BOTTOM PLATE THROUGH TOP PLATE CUTOUTS, AND BOTTOM OF OUTSIDE EXPOSED SURFACE OF PIVOT FITTING							Service	ATA:55
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

PKG:26

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 55 - STABILIZERS										
A5510021 ^S	* HORIZONTAL MID SPAR FROM CANTED RIB NUMBER 2 TO CANTED RIB NUMBER 3 - PERFORM DETAILED VISUAL INSPECTION								Service	ATA:55
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
PKG:26										
A5540000 ^S	* RUDDER RIB CAP (F.S. 698) - PERFORM VISUAL INSPECTION. INSPECT AROUND FASTENER HOLES AND LIGHTENING HOLES.								Service	ATA:55
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
PKG:26										
AA5510034	HORIZONTAL STABILIZER PRIMARY AND SECONDARY BOLTS AND BUSHINGS - PERFORM DETAILED INSPECTION								Service	ATA:55
	MOS	16-Jul-19								
	HRS	8109	4800		12909		2885.9			
	AFL	6239								
PROC. REF: AMM 05-10-00, AMM 55-10-00PROC. REF: AMM 05-10-00, AMM 55-10-00										
E5510074 ^S	* HORIZONTAL STABILIZER REAR SPAR FROM CANTED RIB NUMBER 2 TO CANTED RIB NUMBER 3 - PERFORM VISUAL INSPECTION. INSPECT REAR SPAR CAP AND FASTENERS.								Service	ATA:55
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
PKG:26										
E5510075 ^S	* HORIZONTAL STABILIZER OUTBOARD SPARS AND SKINS OUTBOARD OF CANTED RIB NUMBER 3 - PERFORM VISUAL INSPECTION. INSPECT SPAR CAPS AND FASTENERS								Service	ATA:55
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
PKG:26										

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 55 - STABILIZERS										
E5510076	S	* HORIZONTAL STABILIZER FRONT SPAR FROM CANTED RIB NO. 2 TO CANTED RIB NO. 3 - PERFORM VISUAL INSPECTION. INSPECT FRONT SPAR CAP AND FASTENERS.						Service	ATA:55	
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276							PKG:26	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
E5520003 S * ELEVATOR FRONT SPAR - PERFORM VISUAL INSPECTION. INSPECT SPAR CAP AT FASTENER HOLES										
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276							PKG:26	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
E5520004 S * ELEVATOR RIB NO. 1 CAP - PERFORM VISUAL INSPECTION OF RIB NO. 1 CAP CROSS SECTION AND RIB CAP FLANGES AT TORQUE TUBE										
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276							PKG:26	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
G5510000 S * HORIZONTAL STABILIZER ACTUATOR ATTACHMENT FITTING - PERFORM EDDY CURRENT INSPECTION										
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	4800							
	AFL	0							PKG:25	
PROC. REF: NDT PART 6/55-10-01PROC. REF: NDT PART 6/55-10-01										
G5510023 S * HORIZONTAL STABILIZER ACTUATOR VERTICAL TAIL ATTACHMENT - PERFORM EDDY CURRENT INSPECTION										
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	4800							
	AFL	0							PKG:25	
PROC. REF: NDT PART 6/55-30-01PROC. REF: NDT PART 6/55-30-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 55 - STABILIZERS										
H5510033 ^S			* HORIZONTAL STABILIZER ACTUATOR ATTACHMENT BOLTS - PERFORM LIQUID PENETRANT INSPECTION							Service ATA:55
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	4800							
	AFL	0								
PROC. REF: NDT PART 8/27-40-01PROC. REF: NDT PART 8/27-40-01										
M5510010			* HORIZONTAL STABILIZER AFT ROOT RIB - PERFORM EDDY CURRENT INSPECTION. INSPECT AFT ROOT RIB INTERNAL BETWEEN MID SPAR AND AFT SPAR AND UPPER AND LOWER SKINS EXTERNAL AT ATTACHMENT FASTENERS.							Service ATA:55
	MOS	18-Aug-22						AIRWORTHINESS		
	HRS	9082.6	1200		10282.6		259.5			
	AFL	6994								
PROC. REF: NDT PART 6/55-10-03PROC. REF: NDT PART 6/55-10-03										
M5540022			RUDDER TORQUE TUBE - PERFORM BORESCOPE INSPECTION							Service ATA:55
	MOS/MSC	09-Mar-01	N/A							
	HRS	0								
	AFL	0								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
N5510005 ^S			* HORIZONTAL STABILIZER REAR SPAR CAP - PERFORM EDDY CURRENT INSPECTION. INSPECT REAR SPAR CAP AND WEB AT CENTER SPLICE							Service ATA:55
	MOS	25-Nov-19	96					AIRWORTHINESS		
	HRS	8177.7	2400							
	AFL	6303								
PROC. REF: NDT PART 6/55-10-05PROC. REF: NDT PART 6/55-10-05										
N5510015 ^S			* VERTICAL STABILIZER PIVOT FITTING TOP PLATE - PERFORM EDDY CURRENT INSPECTION							Service ATA:55
	MOS	25-Nov-19	96					AIRWORTHINESS		
	HRS	8177.7	2400							
	AFL	6303								
PROC. REF: NDT PART 6/55-30-02PROC. REF: NDT PART 6/55-30-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 55 - STABILIZERS										
N5510016 ^S			* VERTICAL STABILIZER PIVOT FITTING TOWER SECTION FORWARD RADIUS - PERFORM EDDY CURRENT INSPECTION. INSPECT PIVOT FITTING AT TOWER SECTION RADIUS, PIVOT FITTING AND TOP PLATE AROUND ADJACENT FASTENERS, AND PIVOT FITTING SIDES AT TOWER SECTION RADIUS.						Service	ATA:55
	MOS	25-Nov-19	96					AIRWORTHINESS		
	HRS	8177.7	2400							
	AFL	6303								
PKG:20										
PROC. REF: NDT PART 6/55-30-03PROC. REF: NDT PART 6/55-30-03										
N5510069 ^S			* HORIZONTAL STABILIZER MID SPAR FLANGE ROOT RIB ATTACHMENT - PERFORM EDDY CURRENT INSPECTION						Service	ATA:55
	MOS	25-Nov-19	96					AIRWORTHINESS		
	HRS	8177.7	2400							
	AFL	6303								
PKG:20										
PROC. REF: NDT PART 6/55-10-02PROC. REF: NDT PART 6/55-10-02										
N5510082 ^S			* HORIZONTAL STABILIZER REAR SPAR FLANGE ROOT RIB ATTACHMENT - PERFORM EDDY CURRENT INSPECTION						Service	ATA:55
	MOS	25-Nov-19	96					AIRWORTHINESS		
	HRS	8177.7	2400							
	AFL	6303								
PKG:20										
PROC. REF: NDT PART 6/55-10-04PROC. REF: NDT PART 6/55-10-04										
P5510006 ^S			* VERTICAL STABILIZER FRONT SPAR AND MID SPAR - PERFORM RADIOGRAPHIC INSPECTION						Service	ATA:55
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								
PKG:26										
PROC. REF: NDT PART 2/55-30-01PROC. REF: NDT PART 2/55-30-01										
P5510008 ^S			* HORIZONTAL STABILIZER PRIMARY AND SECONDARY ATTACH BOLTS - PERFORM MAGNETIC PARTICLE INSPECTION						Service	ATA:55
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								
PKG:26										
PROC. REF: NDT PART 7/55-30-02, NDT PART 7/55-30-03PROC. REF: NDT PART 7/55-30-02, NDT PART 7/55-30-03										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty		
ATA 55 - STABILIZERS											
P5510009 ^S			* HORIZONTAL STABILIZER MID SPAR UPPER CAP BL 0.0 TO BL 4.0 - PERFORM X-RAY INSPECTION							Service	ATA:55
	MOS	09-Mar-01						AIRWORTHINESS			
	HRS	0	T:9600								
	AFL	0									
PROC. REF: NDT PART 2/55-10-03PROC. REF: NDT PART 2/55-10-03											
P5510011 ^S			* HORIZONTAL STABILIZER MID SPAR AND REAR SPAR UPPER FLANGE AT ROOT RIB - PERFORM RADIOGRAPHIC INSPECTION							Service	ATA:55
	MOS	02-Aug-24						AIRWORTHINESS			
	HRS	9525.7	9600								
	AFL	7276									
PROC. REF: NDT PART 2/55-10-01PROC. REF: NDT PART 2/55-10-01											
P5510017 ^S			* VERTICAL STABILIZER PIVOT FITTING TOWER SECTION - PERFORM EDDY CURRENT INSPECTION							Service	ATA:55
	MOS	09-Mar-01						AIRWORTHINESS			
	HRS	0	T:9600								
	AFL	0									
PROC. REF: NDT PART 6/55-30-05PROC. REF: NDT PART 6/55-30-05											
P5510018 ^S			* VERTICAL STABILIZER PIVOT FITTING LUGS - PERFORM EDDY CURRENT INSPECTION							Service	ATA:55
	MOS	02-Aug-24						AIRWORTHINESS			
	HRS	9525.7	9600								
	AFL	7276									
PROC. REF: NDT PART 6/55-30-04PROC. REF: NDT PART 6/55-30-04											
P5510019 ^S			* ELEVATOR HINGES ON HORIZONTAL STABILIZER - PERFORM EDDY CURRENT INSPECTION							Service	ATA:55
	MOS	02-Aug-24						AIRWORTHINESS			
	HRS	9525.7	9600								
	AFL	7276									
PROC. REF: NDT PART 6/55-20-02PROC. REF: NDT PART 6/55-20-02											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty		
ATA 55 - STABILIZERS											
P5510020 ^S			* HORIZONTAL MID SPAR UPPER CAP - PERFORM EDDY CURRENT INSPECTION							Service	ATA:55
	MOS	02-Aug-24						AIRWORTHINESS			
	HRS	9525.7	9600								
	AFL	7276									
PROC. REF: NDT PART 6/55-10-07PROC. REF: NDT PART 6/55-10-07											
PKG:26											
P5510024 ^S			* ELEVATOR CONTROL HORN - PERFORM EDDY CURRENT INSPECTION							Service	ATA:55
	MOS	02-Aug-24						AIRWORTHINESS			
	HRS	9525.7	9600								
	AFL	7276									
PROC. REF: NDT PART 6/55-20-01PROC. REF: NDT PART 6/55-20-01											
PKG:26											
P5510070 ^S			* HORIZONTAL STABILIZER FRONT SPAR - PERFORM RADIOGRAPHIC INSPECTION							Service	ATA:55
	MOS	02-Aug-24						AIRWORTHINESS			
	HRS	9525.7	9600								
	AFL	7276									
PROC. REF: NDT PART 2/55-10-02PROC. REF: NDT PART 2/55-10-02											
PKG:26											
P5510073 ^S			* HORIZONTAL REAR SPAR UPPER CAP - PERFORM EDDY CURRENT INSPECTION							Service	ATA:55
	MOS	02-Aug-24						AIRWORTHINESS			
	HRS	9525.7	9600								
	AFL	7276									
PROC. REF: NDT PART 6/55-10-07PROC. REF: NDT PART 6/55-10-07											
PKG:26											
P5510092 ^S			* HORIZONTAL STABILIZER UPPER SPAR SPLICE DOUBLER - PERFORM EDDY CURRENT INSPECTION							Service	ATA:55
	MOS	09-Mar-01						AIRWORTHINESS			
	HRS	0	T:9600								
	AFL	0									
PROC. REF: NDT PART 6/55-10-06PROC. REF: NDT PART 6/55-10-06											
PKG:20											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 55 - STABILIZERS										
P5520001 ^S			* ELEVATOR HINGE ATTACH BOLT - PERFORM MAGNETIC PARTICLE INSPECTION							Service ATA:55
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								
PROC. REF: NDT PART 7/27-30-01PROC. REF: NDT PART 7/27-30-01										
P5520002 ^S			* ELEVATOR HINGE PIN - PERFORM LIQUID PENETRANT INSPECTION							Service ATA:55
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								
PROC. REF: NDT PART 8/55-30-01PROC. REF: NDT PART 8/55-30-01										
P5520021 ^S			* ELEVATOR HINGE FITTINGS - PERFORM EDDY CURRENT INSPECTION							Service ATA:55
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								
PROC. REF: NDT PART 6/55-30-07PROC. REF: NDT PART 6/55-30-07										
P5520022 ^S			* ELEVATOR HINGE PRIMARY AND SECONDARY ATTACH BOLTS - PERFORM LIQUID PENETRANT INSPECTION							Service ATA:55
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								
PROC. REF: NDT PART 8/27-30-01, NDT PART 8/27-30-02PROC. REF: NDT PART 8/27-30-01, NDT PART 8/27-30-02										
P5540001 ^S			* RUDDER SPAR - PERFORM DETAILED VISUAL INSPECTION. INSPECT SPAR CAPS AND FASTENERS							Service ATA:55
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 55 - STABILIZERS									
P5540002 ^S					* RUDDER ATTACH BOLT - PERFORM LIQUID PENETRANT INSPECTION			Service	ATA:55
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							
PROC. REF: NDT PART 8/55-30-02PROC. REF: NDT PART 8/55-30-02									
PKG:26									
Q5510007 ^S					* VERTICAL STABILIZER SKIN AND LOWER AFT SPAR CAP - PERFORM EDDY CURRENT INSPECTION			Service	ATA:55
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							
PROC. REF: NDT PART 6/55-30-06PROC. REF: NDT PART 6/55-30-06									
PKG:26									
Q5530011 ^S					* VERTICAL STABILIZER SKIN AND UPPER AFT SPAR CAP - PERFORM EDDY CURRENT INSPECTION			Service	ATA:55
	MOS	09-Mar-01						AIRWORTHINESS	
	HRS	0	T:9600						
	AFL	0							
PROC. REF: NDT PART 6/55-30-06PROC. REF: NDT PART 6/55-30-06									
PKG:20									
T5510004 ^S					* RUDDER HINGE FITTINGS - PERFORM VISUAL INSPECTION. CONTROL SURFACE REMOVAL NOT REQUIRED.			Service	ATA:55
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
PKG:26									
W5510091					* HORIZONTAL STABILIZER HINGE PRIMARY AND SECONDARY PIVOT PIN INSTALLATION AND ATTACHING HARDWARE - PERFORM DETAILED VISUAL INSPECTION			Service	ATA:55
	MOS	02-Aug-24						MANDATORY	
	HRS	9525.7	625		10150.7		127.6		
	AFL	7276							
PROC. REF: AMM 05-10-00, AMM 55-10-00PROC. REF: AMM 05-10-00, AMM 55-10-00									

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 55 - STABILIZERS										
Y5510001	^S	HORIZONTAL STABILIZER - PERFORM EXTERNAL VISUAL INSPECTION						Service	ATA:55	
	MOS	09-Mar-01	48							
	HRS	0	1200							
	AFL	0								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
PKG:14										
Y5510002	^S	ELEVATOR HINGES ON HORIZONTAL STABILIZER - PERFORM VISUAL INSPECTION. INSPECT HINGE LUGS ON HORIZONTAL TAIL SIDE OF JOINT. INSPECT HILITE COLLARS AT BL 0.0 AND OUTBOARD ELEVATOR HINGE.						Service	ATA:55	
	MOS	09-Mar-01	48							
	HRS	0	1200							
	AFL	0								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
PKG:14										
Y5510003	^S	VERTICAL STABILIZER PIVOT FITTING - PERFORM VISUAL INSPECTION. INSPECT HI-LITE COLLARS COMMON TO THE PIVOT FITTING (MID SPAR, AFT SPAR, TOP PLATE, AND UP/DOWN SPRING BRACKET).						Service	ATA:55	
	MOS	09-Mar-01	48							
	HRS	0	1200							
	AFL	0								
PROC. REF: AMM 55-00-01PROC. REF: AMM 55-00-01										
PKG:14										
Y5510093	^S	HORIZONTAL STABILIZER - PERFORM VISUAL INSPECTION OF HI-LITE COLLARS IN THE FOLLOWING AREAS: - FORWARD SPAR TO BL 0.0 RIB - CENTER SPAR TO BL 0.0 RIB - CENTER SPAR SPLICE PLATE - AFT SPAR SPLICE PLATE - ROOT RIBS AT BL 3.70 (RIGHT AND LEFT) - UPPER DOUBLER SPAR SPLICE, BL 0.0 - HSTA UPPER ATTACH FITTING STRUCTURE						Service	ATA:55	
	MOS	09-Mar-01	48							
	HRS	0	1200							
	AFL	0								
PROC. REF: AMM 55-00-01PROC. REF: AMM 55-00-01										
PKG:14										
Y5510094	^S	LOWER BRACKET, HORIZONTAL STABILIZER TRIM ACTUATOR - PERFORM BORESCOPE INSPECTION OF HI-LITE COLLARS COMMON TO RIB NO. 6 AND MID SPAR.						Service	ATA:55	
	MOS	09-Mar-01	48							
	HRS	0	1200							
	AFL	0								
PROC. REF: AMM 55-10-00PROC. REF: AMM 55-10-00										
PKG:14										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 55 - STABILIZERS

Y5540012 ^S					RUDDER TORQUE TUBE - LOOSEN TORQUE TUBE BONDING CLAMP AND PERFORM DETAILED VISUAL INSPECTION OF AREA AROUND BONDING CLAMP FOR CORROSION.			Service	ATA:55
	MOS	09-Mar-01	12						
	HRS	0	300						
	AFL	0							
PROC. REF: AMM 27-20-01PROC. REF: AMM 27-20-01									PKG:2

ATA 56 - WINDOWS

561001					LEFT WINDSHIELD			Component	ATA:56
PN:6656100000-001	MOS/MSC	02-Aug-24	O/C						
SN:1121	HRS	9525.7							
	AFL	7276							
Special Properties: RII ITEM									
PROC. REF: AMM 56-10-01, AMM 56-10-01PROC. REF: AMM 56-10-01, AMM 56-10-01									

561002					RIGHT WINDSHIELD			Component	ATA:56
PN:6656100001-002	MOS/MSC	02-Aug-24	O/C	TSN 152					
SN:1222	HRS	9525.7		TSN 2762.2					
	AFL	7276		TSN 2118					
Special Properties: RII ITEM									
PROC. REF: AMM 56-10-01, AMM 56-10-01PROC. REF: AMM 56-10-01, AMM 56-10-01									

562010-1					LEFT NO.1 CABIN WINDOW			Component	ATA:56
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01									

562010-10					RIGHT NO.5 CABIN WINDOW			Component	ATA:56
PN:7656202000-015	MOS/MSC	22-Dec-08	O/C	TSN 0					
SN:4621	HRS	6088.5		TSN 0					
	AFL	4660		TSN 0					
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 56 - WINDOWS										
562010-11		LEFT NO.6 CABIN WINDOW						Component	ATA:56	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01										
562010-12		RIGHT NO.6 CABIN WINDOW						Component	ATA:56	
PN:7656202000-015	MOS/MSC	19-Dec-10	O/C							
SN:5304	HRS	6457.2								
	AFL	4944								
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01										
562010-13		LEFT NO.7 CABIN WINDOW						Component	ATA:56	
PN:7656202000-015	MOS/MSC	28-Jun-16	O/C	TSN 0						
SN:6187	HRS	7635.4		TSN 0						
	AFL	5831		TSN 0						
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01										
562010-14		RIGHT NO.7 CABIN WINDOW						Component	ATA:56	
PN:7656202000-015	MOS/MSC	17-Feb-05	O/C							
SN:0601	HRS	3300.2								
	AFL	2515								
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01										
562010-15		LEFT NO.8 CABIN WINDOW						Component	ATA:56	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01										
562010-16		EMERGENCY EXIT WINDOW						Component	ATA:56	
PN:7656202000-015	MOS/MSC	13-Dec-10	O/C	TSN 0						
SN:5304	HRS	6457.2		TSN 0						
	AFL	4944		TSN 0						
PROC. REF: AMM 52-20-06PROC. REF: AMM 52-20-06										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 56 - WINDOWS										
562010-2		RIGHT NO.1 CABIN WINDOW						Component	ATA:56	
PN:7656202000-015	MOS/MSC	21-Jun-05	O/C							
SN:1340	HRS	3694.5								
	AFL	2785								
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01										
562010-3		LEFT NO.2 CABIN WINDOW						Component	ATA:56	
PN:7656202000-015	MOS/MSC	22-Dec-08	O/C	TSN 0						
SN:4456	HRS	6088.5		TSN 0						
	AFL	4660		TSN 0						
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01										
562010-4		RIGHT NO.2 CABIN WINDOW						Component	ATA:56	
PN:7656202000-015	MOS/MSC	17-Feb-05	O/C							
SN:0847	HRS	3300.2								
	AFL	2515								
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01										
562010-5		LEFT NO.3 CABIN WINDOW						Component	ATA:56	
PN:7656202000-015	MOS/MSC	22-Dec-08	O/C	TSN 0						
SN:4505	HRS	6088.5		TSN 0						
	AFL	4660		TSN 0						
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01										
562010-6		RIGHT NO.3 CABIN WINDOW						Component	ATA:56	
PN:7656202000-015	MOS/MSC	22-Dec-08	O/C	TSN 0						
SN:4458	HRS	6088.5		TSN 0						
	AFL	4660		TSN 0						
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01										
562010-7		LEFT NO.4 CABIN WINDOW						Component	ATA:56	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 56 - WINDOWS										
562010-8		RIGHT NO.4 CABIN WINDOW						Component	ATA:56	
PN:7656202000-015	MOS/MSC	17-Dec-10	O/C	TSN 0						
SN:5310	HRS	6457.2		TSN 0						
	AFL	4944		TSN 0						
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01										
562010-9		LEFT NO.5 CABIN WINDOW						Component	ATA:56	
PN:7656202000-015	MOS/MSC	15-Dec-10	O/C	TSN 0						
SN:5307	HRS	6457.2		TSN 0						
	AFL	4944		TSN 0						
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01										
L5600010 ^S		* CABIN WINDOWS (INCLUDING THE EMERGENCY EXIT WINDOW) - PERFORM DETAILED VISUAL INSPECTION						Service	ATA:56	
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	4800							
	AFL	0								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
N5600003		* LEFT WINDSHIELD - PERFORM ULTRASONIC INSPECTION OF STRUCTURAL PLIES						Service	ATA:56	
PN:6656100000-001	MOS/MSC	02-Aug-24	N/A							
SN:1121	HRS	9525.7								
	AFL	7276								
PROC. REF: NDT PART 4/56-10-01PROC. REF: NDT PART 4/56-10-01										
N5600003		* RIGHT WINDSHIELD - PERFORM ULTRASONIC INSPECTION OF STRUCTURAL PLIES						Service	ATA:56	
PN:6656100001-002	MOS/MSC	02-Aug-24	N/A							
SN:1222	HRS	9525.7								
	AFL	7276								
PROC. REF: NDT PART 4/56-10-01PROC. REF: NDT PART 4/56-10-01										
N5600012		* LEFT WINDSHIELD - PERFORM BOLT HOLE INSPECTION						Service	ATA:56	
PN:6656100000-001	MOS	02-Aug-24						AIRWORTHINESS		
SN:1121	HRS	9525.7	4800		14325.7		4302.6			
	AFL	7276								
PROC. REF: AMM 56-10-01PROC. REF: AMM 56-10-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 56 - WINDOWS										
N5600012		* RIGHT WINDSHIELD - PERFORM BOLT HOLE INSPECTION						Service	ATA:56	
PN:6656100001-002	MOS	02-Aug-24						AIRWORTHINESS		
SN:1222	HRS	9525.7	4800		14325.7		4302.6			
	AFL	7276								
PROC. REF: AMM 56-10-01PROC. REF: AMM 56-10-01										
W5600002		** WINDSHIELD - PERFORM RAIN REMOVAL COATING EFFECTIVENESS TEST						Service	ATA:56	
	MOS	21-Feb-25	12		21-Feb-26		9 d	AIRWORTHINESS		
	HRS	9637.3								
	AFL	7352								
PROC. REF: AMM 56-10-01, AMM 56-10-01PROC. REF: AMM 56-10-01, AMM 56-10-01										
Y5600000 ^S		WINDSHIELDS - PERFORM VISUAL INSPECTION (INTERIOR AND EXTERIOR)						Service	ATA:56	
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
Y5600001 ^S		CABIN WINDOWS - PERFORM VISUAL INSPECTION						Service	ATA:56	
	MOS	02-Aug-24	24							
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
Y5600013 ^S		WINDSHIELDS - PERFORM VISUAL INSPECTION OF THE AERODYNAMIC SEAL						Service	ATA:56	
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 56-10-01, AMM 56-10-01PROC. REF: AMM 56-10-01, AMM 56-10-01										
ATA 57 - WINGS										
571001		WING ASSEMBLY						Component	ATA:57	
PN:PN	MOS/MSC	09-Mar-01	O/C		TSN 0					
SN:UNKNOWN	HRS	0			TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
	AFL	0		TSN 0					
PROC. REF: AMM 57-10-00PROC. REF: AMM 57-10-00									
571010 RIGHT MAIN LANDING GEAR ACTUATOR FITTING Component ATA:57									
PN:PN	MOS	09-Mar-01		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0	20000	TSN 0	20000		12384		
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01									
571011 LEFT MAIN LANDING GEAR ACTUATOR FITTING Component ATA:57									
PN:PN	MOS	09-Mar-01		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0	20000	TSN 0	20000		12384		
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01									
573001 LEFT WINGLET FILLER Component ATA:57									
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
573002 RIGHT WINGLET FILLER Component ATA:57									
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
573090 LEFT WING WINGLET Component ATA:57									
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 57-30-01PROC. REF: AMM 57-30-01									
573091 LEFT WINGLET LEADING EDGE ASSEMBLY Component ATA:57									
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 57 - WINGS

PROC. REF: AMM 57-30-01PROC. REF: AMM 57-30-01

573092 RIGHT WING WINGLET					Component	ATA:57
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0		
SN:UNKNOWN	HRS	0		TSN 0		
	AFL	0		TSN 0		
PROC. REF: AMM 57-30-01PROC. REF: AMM 57-30-01						

573093 RIGHT WINGLET LEADING EDGE ASSEMBLY					Component	ATA:57
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0		
SN:UNKNOWN	HRS	0		TSN 0		
	AFL	0		TSN 0		
PROC. REF: AMM 57-30-01PROC. REF: AMM 57-30-01						

574005 LEFT INBOARD LEADING EDGE					Component	ATA:57
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0		
SN:UNKNOWN	HRS	0		TSN 0		
	AFL	0		TSN 0		
PROC. REF: AMM 57-40-01PROC. REF: AMM 57-40-01						

574007 RIGHT INBOARD LEADING EDGE					Component	ATA:57
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0		
SN:UNKNOWN	HRS	0		TSN 0		
	AFL	0		TSN 0		
PROC. REF: AMM 57-40-01PROC. REF: AMM 57-40-01						

574011 LEFT INBOARD LEADING EDGE ACCESS SECTION					Component	ATA:57
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0		
SN:UNKNOWN	HRS	0		TSN 0		
	AFL	0		TSN 0		
PROC. REF: AMM 57-40-01PROC. REF: AMM 57-40-01						

574013 RIGHT INBOARD LEADING EDGE ACCESS SECTION					Component	ATA:57
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0		
SN:UNKNOWN	HRS	0		TSN 0		
	AFL	0		TSN 0		
PROC. REF: AMM 57-40-01PROC. REF: AMM 57-40-01						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
574033 LEFT CENTER LEADING EDGE								Component	ATA:57
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 57-40-01PROC. REF: AMM 57-40-01									
<hr/>									
574035 RIGHT CENTER LEADING EDGE								Component	ATA:57
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 57-40-01PROC. REF: AMM 57-40-01									
<hr/>									
574039 LEFT OUTBOARD LEADING EDGE ACCESS SECTION								Component	ATA:57
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 57-40-01PROC. REF: AMM 57-40-01									
<hr/>									
574041 RIGHT OUTBOARD LEADING EDGE ACCESS SECTION								Component	ATA:57
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 57-40-01PROC. REF: AMM 57-40-01									
<hr/>									
574050 LEFT OUTBOARD LEADING EDGE								Component	ATA:57
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 57-40-01PROC. REF: AMM 57-40-01									
<hr/>									
574051 RIGHT OUTBOARD LEADING EDGE								Component	ATA:57
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 57-40-01PROC. REF: AMM 57-40-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 57 - WINGS										
575001		LEFT FLAP ASSEMBLY						Component	ATA:57	
PN:4557500006-007	MOS/MSC	02-Aug-24	O/C							
SN:474598000144	HRS	9525.7								
	AFL	7276								
Special Properties: RII ITEM PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01										
575002		RIGHT FLAP ASSEMBLY						Component	ATA:57	
PN:4557500006-008	MOS/MSC	02-Aug-24	O/C							
SN:474600100146	HRS	9525.7								
	AFL	7276								
Special Properties: RII ITEM PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01										
576001		LEFT AILERON						Component	ATA:57	
PN:4557600003-001	MOS/MSC	02-Aug-24	O/C							
SN:UNKNOWN	HRS	9525.7								
	AFL	7276								
Special Properties: RII ITEM PROC. REF: AMM 27-10-02PROC. REF: AMM 27-10-02										
576002		RIGHT AILERON						Component	ATA:57	
PN:4557600003-002	MOS/MSC	02-Aug-24	O/C							
SN:00145	HRS	9525.7								
	AFL	7276								
Special Properties: RII ITEM PROC. REF: AMM 27-10-02PROC. REF: AMM 27-10-02										
576037		LEFT AILERON BOLTS (X3)						Component	ATA:57	
PN:PN	MOS/MSC	02-Aug-24	H/T	TSN 0						
SN:UNKNOWN	HRS	9525.7		TSN 0						
	AFL	7276		TSN 0						
PROC. REF: AMM 27-10-02PROC. REF: AMM 27-10-02										
576038		RIGHT AILERON BOLTS (X3)						Component	ATA:57	
PN:PN	MOS/MSC	02-Aug-24	H/T	TSN 0						
SN:UNKNOWN	HRS	9525.7		TSN 0						
	AFL	7276		TSN 0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 57 - WINGS

PROC. REF: AMM 27-10-02PROC. REF: AMM 27-10-02

577001	LEFT SPOILER --							Component	ATA:57
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
Special Properties: RII ITEM									
PROC. REF: AMM 27-60-01PROC. REF: AMM 27-60-01									

577002	RIGHT SPOILER --							Component	ATA:57
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
Special Properties: RII ITEM									
PROC. REF: AMM 27-60-01PROC. REF: AMM 27-60-01									

A5760004	* LEFTAILERON BOLTS (X3) - PERFORM MAGNETIC PARTICLE INSPECTION OR REPLACE							Service	ATA:57
PN:PN	MOS	02-Aug-24						AIRWORTHINESS	
SN:UNKNOWN	HRS	9525.7	9600	19125.7		9102.6			
	AFL	7276							

A5760004	* RIGHTAILERON BOLTS (X3) - PERFORM MAGNETIC PARTICLE INSPECTION OR REPLACE							Service	ATA:57
PN:PN	MOS	02-Aug-24						AIRWORTHINESS	
SN:UNKNOWN	HRS	9525.7	9600	19125.7		9102.6			
	AFL	7276							

AC5710190	* LEFT WING CENTER SECTION (PANELS 510AC, 510BC, 510BL AND 610BR REMOVED AND PANELS 510AL, 610AR, 720BL, AND 730BR LOWERED) - PERFORM VISUAL INSPECTION. INSPECT STRUCTURE FOR CORROSION OR DETERIORATION OF PROTECTIVE TREATMENT.							Service	ATA:57
	MOS	31-Mar-20	96	31-Mar-28		778 d			
	HRS	8253.8							
	AFL	6353							
PROC. REF: AMM 57-10-00PROC. REF: AMM 57-10-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
AC5710190		* RIGHT WING CENTER SECTION (PANELS 510AC, 510BC, 510BL AND 610BR REMOVED AND PANELS 510AL, 610AR, 720BL, AND 730BR LOWERED) - PERFORM VISUAL INSPECTION. INSPECT STRUCTURE FOR CORROSION OR DETERIORATION OF PROTECTIVE TREATMENT.						Service	ATA:57
	MOS	31-Mar-20	96		31-Mar-28		778 d		
	HRS	8253.8							
	AFL	6353							
PROC. REF: AMM 57-10-00PROC. REF: AMM 57-10-00									
AE5710035 ^S		* WING LOWER SKIN AT DRAIN HOLE (4 LOCATIONS) - PERFORM EDDY CURRENT INSPECTION						Service	ATA:57
	MOS	09-Mar-01						AIRWORTHINESS	
	HRS	0	T:9600						
	AFL	0							PKG:25
PROC. REF: NDT PART 6/57-30-02PROC. REF: NDT PART 6/57-30-02									
AE5710187		* LOWER WING FUEL DRAIN HOLES (4 LOCATIONS) - PERFORM EDDY CURRENT INSPECTION						Service	ATA:57
	MOS	EFF	72		11-Dec-31 *		2128 d	AIRWORTHINESS	
	HRS								
	AFL								
PROC. REF: NDT PART 6/57-30-03PROC. REF: NDT PART 6/57-30-03									
E5710005 ^S		* WING CENTER SECTION SPAR UPPER CAPS - PERFORM VISUAL INSPECTION. INSPECT FRONT, MID, AND REAR SPAR UPPER CAPS FROM CENTERLINE TO SKIN TERMINATION AT WS 33.						Service	ATA:57
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							PKG:26
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
E5710019 ^S		* WING BOX, UPPER SKIN, SKIN/STRINGER AND SPAR CAPS - PERFORM VISUAL INSPECTION. INSPECT UPPER WING SPAR CAPS, SKIN PANEL, AND STRINGERS OF OUTER WING						Service	ATA:57
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							PKG:26
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 57 - WINGS

E5710020 ^S	* WING BOX RIBS - PERFORM VISUAL INSPECTION. INSPECT ALL WING BOX RIBS EXCEPT CLOSING RIB BETWEEN FRONT AND MID SPARS AND CLOSING RIB BETWEEN MID AND REAR SPAR.							Service	ATA:57
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							

PKG:26

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

E5750051	* FLAP MAIN TRACK ROLLERS - PERFORM VISUAL INSPECTION WITH FLAPS REMOVED							Service	ATA:57
	MOS	09-Mar-01			RTS			AIRWORTHINESS	
	HRS	0	T:10000						
	AFL	0							

PROC. REF: AMM 05-10-00, AMM 27-50-01PROC. REF: AMM 05-10-00, AMM 27-50-01

E5750052	* FLAP NOSE ROLLERS - PERFORM VISUAL INSPECTION WITH FLAPS REMOVED							Service	ATA:57
	MOS	21-Aug-25						AIRWORTHINESS	
	HRS	9809.8	600		10409.8		386.7		
	AFL	7471							

Special Properties: RII ITEM

PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00

E5760006 ^S	* AILERON BASIC STRUCTURE - PERFORM VISUAL INSPECTION							Service	ATA:57
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							

PKG:26

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

L5710124 ^S	* AILERON DRIVE SUPPORT - PERFORM ULTRASONIC INSPECTION							Service	ATA:57
	MOS	09-Mar-01						AIRWORTHINESS	
	HRS	0	4800						
	AFL	0							

PKG:25

PROC. REF: NDT PART 4/27-10-01PROC. REF: NDT PART 4/27-10-01

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 57 - WINGS										
N5710002			* WING BOX MID SPAR LOWER CAP, OUTBOARD OF JOINT AT WS 137 BETWEEN RIB NO. 7 AND 8 - PERFORM DIRECTED VISUAL INSPECTION. INSPECT MID SPAR LOWER CAP AND LOWER SKIN PANELS.						Service	ATA:57
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	3580		13105.7		3082.6			
	AFL	7276								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
N5710004 ^S			* WING CENTER SECTION REAR SPAR - PERFORM EDDY CURRENT INSPECTION. INSPECT REAR SPAR LOWER CAP FROM CENTERLINE TO WS 33.						Service	ATA:57
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0							PKG:25	
PROC. REF: NDT PART 6/57-20-02PROC. REF: NDT PART 6/57-20-02										
N5710006 ^S			* WING CENTER SECTION FORWARD AND AFT RIBS AT WS 6 AND FORWARD RIBS AT WS 17 - PERFORM EDDY CURRENT INSPECTION						Service	ATA:57
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0							PKG:25	
PROC. REF: NDT PART 6/57-10-06PROC. REF: NDT PART 6/57-10-06										
N5710008			* WING BOX MID SPAR LOWER CAP - PERFORM ULTRASONIC INSPECTION. INSPECT MID SPAR LOWER CAP AND LOWER SKIN PANELS BETWEEN WS 99 AND WS 137						Service	ATA:57
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	2500		12025.7		2002.6			
	AFL	7276								
PROC. REF: NDT PART 4/57-30-03PROC. REF: NDT PART 4/57-30-03										
N5710009			* WING BOX MID SPAR LOWER CAP JOINT AT WS 137 - PERFORM X-RAY INSPECTION. INSPECT MID SPAR CENTER/OUTER JOINT						Service	ATA:57
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	4517		14042.7		4019.6			
	AFL	7276								
PROC. REF: NDT PART 2/57-10-02PROC. REF: NDT PART 2/57-10-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty		
ATA 57 - WINGS											
N5710010			* WING BOX REAR SPAR LOWER CAP INBOARD OF JOINT AT WS 81 - PERFORM ULTRASONIC INSPECTION. INSPECT REAR SPAR LOWER CAP BETWEEN SKIN TERMINATION AT WS 48 AND CLOSING RIB AT WS 60.							Service	ATA:57
	MOS	02-Aug-24						AIRWORTHINESS			
	HRS	9525.7	960		10485.7		462.6				
	AFL	7276									
PROC. REF: NDT PART 4/57-30-01PROC. REF: NDT PART 4/57-30-01											
N5710011 ^S			* WING BOX REAR SPAR LOWER CAP JOINT AT WS 81 - PERFORM X-RAY INSPECTION. INSPECT CENTER AND OUTER REAR SPARS, LOWER SPLICE PLATE, AND LOWER SKIN BETWEEN WS 60 AND WS 90.							Service	ATA:57
	MOS	09-Mar-01						AIRWORTHINESS			
	HRS	0	T:9600								
	AFL	0									
PROC. REF: NDT PART 2/57-10-03PKG:22 PROC. REF: NDT PART 2/57-10-03											
N5710012			* WING BOX REAR SPAR LOWER CAP OUTBOARD OF JOINT AT WS 81 TO RIB NUMBER 6 - PERFORM DETAILED VISUAL INSPECTION. INSPECT OUTER REAR SPAR LOWER CAP AND AFT LOWER SKIN PANEL OUTBOARD OF REAR SPLICE AT WS 90.							Service	ATA:57
	MOS	02-Aug-24						AIRWORTHINESS			
	HRS	9525.7	3443		12968.7		2945.6				
	AFL	7276									
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00											
N5710013			* WING BOX REAR SPAR LOWER CAP SKIN TERMINATION AT MS 48 - PERFORM EDDY CURRENT INSPECTION. INSPECT REAR SPAR LOWER CAP BETWEEN WS 33 AND WS 48.							Service	ATA:57
	MOS	09-Mar-01			RTS			AIRWORTHINESS			
	HRS	0	T:10000								
	AFL	0									
PROC. REF: NDT PART 6/57-20-04PROC. REF: NDT PART 6/57-20-04											
N5710014 ^S			* WING BOX REAR SPAR FLAP TRACK CUTOUTS - PERFORM EDDY CURRENT INSPECTION. INSPECT FLAP TRACK CUTOUTS AT WS 65, WS 126, AND WS 184 ON REAR SPAR.							Service	ATA:57
	MOS	09-Mar-01						AIRWORTHINESS			
	HRS	0	T:9600								
	AFL	0									
PROC. REF: NDT PART 6/57-20-01PKG:25 PROC. REF: NDT PART 6/57-20-01											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 57 - WINGS										
N5710016	S	* WING BOX BASIC SKIN/STRINGER, LOWER SKIN - PERFORM VISUAL INSPECTION. INSPECT OUTBOARD WING FORWARD AND AFT LOWER SKIN PANELS AND STRINGERS.						Service	ATA:57	
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0							PKG:25	
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
N5710017	S	* WING BOX BASIC SKIN/STRINGER AT STRINGER RUN-OUT, LOWER SKIN - PERFORM VISUAL INSPECTION. INSPECT STRINGER RUN-OUTS IN FORWARD AND AFT LOWER SKIN PANELS.						Service	ATA:57	
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276							PKG:26	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
N5710021	S	* CENTER SECTION MID SPAR LOWER CAP - PERFORM EDDY CURRENT INSPECTION. INSPECT MID SPAR FROM CENTERLINE SPLICE PLATE TO SKIN TERMINATION AT MS 33.						Service	ATA:57	
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0							PKG:22	
PROC. REF: NDT PART 6/57-10-02PROC. REF: NDT PART 6/57-10-02										
N5710022	S	* CENTER SECTION MID SPAR CENTERLINE JOINT - PERFORM EDDY CURRENT INSPECTION. INSPECT CENTER MID SPAR (CENTERLINE TO WS 17), LOWER SPLICE PLATE, AND CENTER MID SPAR JOINT FITTING LOWER CAP.						Service	ATA:57	
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0							PKG:22	
PROC. REF: NDT PART 6/57-10-08, NDT PART 6/57-10-10PROC. REF: NDT PART 6/57-10-08, NDT PART 6/57-10-10										
N5710023	S	* CENTER SECTION FRONT SPAR LOWER CAP - PERFORM EDDY CURRENT INSPECTION. INSPECT CENTER WING FRONT SPAR LOWER CAP BETWEEN SKIN TERMINATIONS (WS 31 LEFT TO WS 31 RIGHT).						Service	ATA:57	
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0							PKG:22	
PROC. REF: NDT PART 6/57-10-03PROC. REF: NDT PART 6/57-10-03										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 57 - WINGS										
N5710026			* WING BOX MID SPAR LOWER CAP - PERFORM ULTRASONIC INSPECTION. INSPECT MID SPAR LOWER CAP OUTBOARD OF ROOT RIB AT WS 33 TO WS 99.						Service	ATA:57
	MOS				RTS			AIRWORTHINESS		
	HRS	0			T:10000					
	AFL									
PROC. REF: NDT PART 4/57-30-03PROC. REF: NDT PART 4/57-30-03										
N5710028 ^S			* WING BOX MID SPAR LOWER CAP, SKIN TERMINATION AT WS 33 - PERFORM BOLT HOLE EDDY CURRENT INSPECTION. INSPECT MID SPAR LOWER CAP UNDERNEATH ROOT RIB (WS 33) AT POINT OF SKIN TERMINATION.						Service	ATA:57
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0			T:9600					
	AFL	0								
PROC. REF: NDT PART 6/57-10-11PKG:25										
N5710031 ^S			* WING BOX SKIN ACCESS COVER HOLES - PERFORM EDDY CURRENT INSPECTION. INSPECT ACCESS HOLES IN FORWARD AND AFT LOWER SKIN PANELS.						Service	ATA:57
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0			T:9600					
	AFL	0								
PROC. REF: NDT PART 6/57-30-01PKG:25										
N5710037 ^S			* WING BOX FRONT SPAR LOWER CAP - PERFORM VISUAL INSPECTION. INSPECT FRONT SPAR LOWER CAP AND LOWER FORWARD SKIN OUTBOARD OF MID-SPAR STATION (MS) 55.						Service	ATA:57
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0			T:9600					
	AFL	0								
PROC. REF: GENERIC NO REFPKG:22										
N5710084 ^S			SPOILER, CENTER HINGE SPOILER SIDE - PERFORM EDDY CURRENT INSPECTION						Service	ATA:57
	MOS	25-Nov-19	96							
	HRS	8177.7	2400							
	AFL	6303								
PROC. REF: NDT PART 6/57-40-01PKG:22										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 57 - WINGS										
N5710121 ^S			* WING BOX MID SPAR, OUTBOARD OF RIB NUMBER 8 - PERFORM VISUAL INSPECTION AT WS 156 AND OUTBOARD TO WS 260						Service	ATA:57
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0		T:9600						
	AFL	0								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
PKG:25										
N5710122 ^S			* WING BOX REAR SPAR, OUTBOARD OF RIB NUMBER 6 - PERFORM VISUAL INSPECTION AT WS 118 AND OUTBOARD TO WS 260						Service	ATA:57
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0		T:9600						
	AFL	0								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
PKG:25										
N5710123			* WING BOX MID SPAR LOWER CAP - PERFORM EDDY CURRENT INSPECTION AT TRUNNION FITTING						Service	ATA:57
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	2666		12191.7		2168.6			
	AFL	7276								
PROC. REF: NDT PART 6/57-10-01PROC. REF: NDT PART 6/57-10-01										
N5710137 ^S			* MID SPAR AT RIB NO. 2 NEAR WS 48 - PERFORM BOLT HOLE EDDY CURRENT INSPECTION						Service	ATA:57
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0		T:9600						
	AFL	0								
PROC. REF: NDT PART 6/57-10-11APROC. REF: NDT PART 6/57-10-11A										
PKG:25										
N5710138 ^S			* MID SPAR AT RIB NO. 3 NEAR WS 60 - PERFORM BOLT HOLE EDDY CURRENT INSPECTION						Service	ATA:57
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0		T:9600						
	AFL	0								
PROC. REF: NDT PART 6/57-10-11APROC. REF: NDT PART 6/57-10-11A										
PKG:25										

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 57 - WINGS										
N5710139 ^S			* FORWARD FLANGE FASTENERS AT REAR SPAR BETWEEN WS 52 AND WS 60 - PERFORM BOLT HOLE EDDY CURRENT INSPECTION						Service	ATA:57
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0		T:9600						
	AFL	0								
PROC. REF: NDT PART 6/57-20-03PROC. REF: NDT PART 6/57-20-03										
N5710148			* WING CENTER SECTION REAR SPAR - PERFORM EDDY CURRENT INSPECTION. INSPECT REAR SPAR LOWER CAP FROM CENTERLINE TO WS 33.						Service	ATA:57
	MOS/MSC	09-Mar-01		N/A						
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 6/57-20-02PROC. REF: NDT PART 6/57-20-02										
N5710149			* WING CENTER SECTION FORWARD AND AFT RIBS AT WS 6 AND FORWARD RIBS AT WS 17 - PERFORM EDDY CURRENT INSPECTION						Service	ATA:57
	MOS/MSC	09-Mar-01		N/A						
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 6/57-10-06PROC. REF: NDT PART 6/57-10-06										
N5710150			* WING BOX MID SPAR LOWER CAP - PERFORM ULTRASONIC INSPECTION. INSPECT MID SPAR LOWER CAP AND LOWER SKIN PANELS BETWEEN WS 99 AND WS 137.						Service	ATA:57
	MOS/MSC	09-Mar-01		N/A						
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 4/57-30-03PROC. REF: NDT PART 4/57-30-03										
N5710151			* WING BOX MID SPAR LOWER CAP JOINT AT WS 137 - PERFORM X-RAY INSPECTION. INSPECT MID SPAR CENTER/OUTER JOINT.						Service	ATA:57
	MOS/MSC	09-Mar-01		N/A						
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 2/57-10-02PROC. REF: NDT PART 2/57-10-02										
N5710152			* WING BOX REAR SPAR LOWER CAP INBOARD OF JOINT AT WS 81 - PERFORM ULTRASONIC INSPECTION. INSPECT REAR SPAR LOWER CAP BETWEEN SKIN TERMINATION AT WS 48 AND CLOSING RIB AT WS 60.						Service	ATA:57
	MOS/MSC	09-Mar-01		N/A						
	HRS	0								
	AFL	0								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
PROC. REF: NDT PART 4/57-30-01PROC. REF: NDT PART 4/57-30-01									
N5710153								Service	ATA:57
* WING BOX REAR SPAR LOWER CAP JOINT AT WS 81 - PERFORM X-RAY INSPECTION. INSPECT CENTER AND OUTER REAR SPARS, LOWER SPLICE PLATE, AND LOWER SKIN BETWEEN WS 60 AND WS 90.									
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
PROC. REF: NDT PART 2/57-10-03PROC. REF: NDT PART 2/57-10-03									
N5710155								Service	ATA:57
* WING BOX REAR SPAR LOWER CAP SKIN TERMINATION AT MS 48 - PERFORM EDDY CURRENT INSPECTION. INSPECT REAR SPAR LOWER CAP BETWEEN WS 33 AND WS 48.									
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
PROC. REF: NDT PART 6/57-20-04PROC. REF: NDT PART 6/57-20-04									
N5710157 ^S								Service	ATA:57
* WING BOX BASIC SKIN/STRINGER AT STRINGER RUN-OUT, LOWER SKIN - PERFORM VISUAL INSPECTION. INSPECT STRINGER RUN-OUTS IN FORWARD AND AFT LOWER SKIN PANELS.									
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
PKG:25									
N5710158								Service	ATA:57
* CENTER SECTION FRONT SPAR LOWER CAP - PERFORM EDDY CURRENT INSPECTION. INSPECT CENTER WING FRONT SPAR LOWER CAP BETWEEN SKIN TERMINATIONS (WS 31 LEFT TO WS 31 RIGHT).									
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
PROC. REF: NDT PART 6/57-10-03PROC. REF: NDT PART 6/57-10-03									
N5710159								Service	ATA:57
* WING BOX MID SPAR LOWER CAP - PERFORM ULTRASONIC INSPECTION. INSPECT MID SPAR LOWER CAP OUTBOARD OF ROOT RIB AT WS 33 TO WS 99.									
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
PROC. REF: NDT PART 4/57-30-03PROC. REF: NDT PART 4/57-30-03									

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 57 - WINGS										
N5710160			* WING BOX MID SPAR LOWER CAP, SKIN TERMINATION AT WS 33 - PERFORM BOLT HOLE EDDY CURRENT INSPECTION. INSPECT MID SPAR LOWER CAP UNDERNEATH ROOT RIB (WS 33) AT POINT OF SKIN TERMINATION.						Service	ATA:57
	MOS/MSC	09-Mar-01	N/A							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 6/57-10-11PROC. REF: NDT PART 6/57-10-11										
N5710161 ^S			* WING BOX SKIN ACCESS COVER HOLES - PERFORM EDDY CURRENT INSPECTION. INSPECT ACCESS HOLES IN FORWARD AND AFT LOWER SKIN PANELS.						Service	ATA:57
	MOS/MSC	09-Mar-01	N/A							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 6/57-30-01PKG:22 PROC. REF: NDT PART 6/57-30-01										
N5710163			* CENTER SECTION MID SPAR CENTERLINE JOINT - PERFORM EDDY CURRENT INSPECTION. INSPECT CENTER MID SPAR (CENTERLINE TO WS 17), LOWER SPLICE PLATE, AND CENTER MID SPAR JOINT FITTING LOWER CAP.						Service	ATA:57
	MOS/MSC	09-Mar-01	N/A							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 6/57-10-08, NDT PART 6/57-10-10PROC. REF: NDT PART 6/57-10-08, NDT PART 6/57-10-10										
N5710164			* CENTER SECTION MID SPAR LOWER CAP - PERFORM EDDY CURRENT INSPECTION. INSPECT MID SPAR FROM CENTERLINE SPLICE PLATE TO SKIN TERMINATION AT MS 33.						Service	ATA:57
	MOS/MSC	09-Mar-01	N/A							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 6/57-10-02PROC. REF: NDT PART 6/57-10-02										
N5710165			* WING BOX REAR SPAR FLAP TRACK CUT-OUTS - PERFORM EDDY CURRENT INSPECTION. INSPECT FLAP TRACK CUT-OUTS AT WS 65, WS 126, AND WS 184 ON REAR SPAR.						Service	ATA:57
	MOS/MSC	09-Mar-01	N/A							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 6/57-20-01PROC. REF: NDT PART 6/57-20-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 57 - WINGS										
N5710168	* WING BOX MID SPAR LOWER CAP - PERFORM EDDY CURRENT INSPECTION AT TRUNNION FITTING								Service	ATA:57
	MOS/MSC	09-Mar-01	N/A							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 6/57-10-01PROC. REF: NDT PART 6/57-10-01										
N5710169	* MID SPAR AT RIB NO. 2 NEAR WS 48 - PERFORM BOLT HOLE EDDY CURRENT INSPECTION								Service	ATA:57
	MOS/MSC	09-Mar-01	N/A							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 6/57-10-11APROC. REF: NDT PART 6/57-10-11A										
N5710170	* MID SPAR AT RIB NO. 3 NEAR WS 60 - PERFORM BOLT HOLE EDDY CURRENT INSPECTION								Service	ATA:57
	MOS/MSC	09-Mar-01	N/A							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 6/57-10-11APROC. REF: NDT PART 6/57-10-11A										
N5710171	* FORWARD FLANGE FASTENERS AT REAR SPAR BETWEEN WS 52 AND WS 60 - PERFORM BOLT HOLE EDDY CURRENT INSPECTION								Service	ATA:57
	MOS/MSC	09-Mar-01	N/A							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 6/57-20-03PROC. REF: NDT PART 6/57-20-03										
N5710172	* WING BOX MID SPAR LOWER CAP - PERFORM ULTRASONIC INSPECTION AT TRUNNION FITTING								Service	ATA:57
	MOS	02-Aug-24								
	HRS	9525.7	2666		12191.7		2168.6			
	AFL	7276								
PROC. REF: NDT PART 4/57-10-00PROC. REF: NDT PART 4/57-10-00										
N5710173	* WING BOX MID SPAR LOWER CAP - PERFORM ULTRASONIC INSPECTION AT TRUNNION FITTING								Service	ATA:57
	MOS/MSC	09-Mar-01	N/A							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 4/57-10-00PROC. REF: NDT PART 4/57-10-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
N5710174	* WING BOX REAR SPAR LOWER CAP SKIN TERMINATION AT MS 48 - PERFORM ULTRASONIC INSPECTION. INSPECT REAR SPAR LOWER CAP BETWEEN WS 33 AND WS 48.							Service	ATA:57
	MOS	09-Mar-01			RTS			AIRWORTHINESS	
	HRS	0	T:10000						
	AFL	0							
PROC. REF: NDT PART 4/57-30-04PROC. REF: NDT PART 4/57-30-04									
N5710175	* WING BOX REAR SPAR LOWER CAP SKIN TERMINATION AT WS 48 - PERFORM ULTRASONIC INSPECTION. INSPECT REAR SPAR LOWER CAP BETWEEN WS 33 AND WS 48.							Service	ATA:57
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
PROC. REF: NDT PART 4/57-30-04PROC. REF: NDT PART 4/57-30-04									
N5710176 ^S	* WING MID SPAR (CENTER SECTION) LOWER CAP AND CENTER JOINT FITTING - PERFORM ULTRASONIC INSPECTION							Service	ATA:57
	MOS	09-Mar-01						AIRWORTHINESS	
	HRS	0	T:9600						
	AFL	0							
PROC. REF: NDT PART 4/57-30-05PKG:22									
N5710177	* WING MID SPAR (CENTER SECTION) LOWER CAP AND CENTER JOINT FITTING - PERFORM ULTRASONIC INSPECTION							Service	ATA:57
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
PROC. REF: NDT PART 4/57-30-05PROC. REF: NDT PART 4/57-30-05									
N5750005 ^S	* FLAP MAIN TRACK HINGE FITTINGS, TRACK, AND FLAP BOX SIDES - PERFORM VISUAL INSPECTION. INSPECT MAIN TRACK HINGE FITTINGS ON TRACK AND FLAP BOX SIDES.							Service	ATA:57
	MOS	09-Mar-01						AIRWORTHINESS	
	HRS	0	T:9600						
	AFL	0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 57 - WINGS										
P5710001	S	* WING DRAG LINK ATTACH FITTING - PERFORM MAGNETIC PARTICLE INSPECTION						Service	ATA:57	
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0								
PROC. REF: NDT PART 7/57-30-02PROC. REF: NDT PART 7/57-30-02										
P5710007	S	* WING TO FUSELAGE ATTACH FITTINGS AND LINKS - PERFORM EDDY CURRENT INSPECTION						Service	ATA:57	
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0								
PROC. REF: NDT PART 6/57-10-12PROC. REF: NDT PART 6/57-10-12										
P5710015	S	* WING BOX REAR SPAR AT AILERON HINGE - PERFORM EDDY CURRENT INSPECTION						Service	ATA:57	
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0								
PROC. REF: NDT PART 6/57-10-20PROC. REF: NDT PART 6/57-10-20										
P5710018	S	* WING LOWER SKIN AT MID SPAR SPAN WISE JOINT - PERFORM EDDY CURRENT INSPECTION.						Service	ATA:57	
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								
PROC. REF: NDT PART 6/57-10-09PROC. REF: NDT PART 6/57-10-09										
P5710024	S	* WING REAR SPAR SIDE STAY FITTING SUPPORT STRUCTURE - PERFORM EDDY CURRENT INSPECTION.						Service	ATA:57	
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0								
PROC. REF: NDT PART 6/57-20-06PROC. REF: NDT PART 6/57-20-06										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 57 - WINGS										
P5710025 ^S			* WING FRONT SPAR LOWER CAP FROM WS 33.0 TO WS 60.0 - PERFORM RADIOGRAPHIC INSPECTION							Service ATA:57
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0								
PROC. REF: NDT PART 2/57-10-01PROC. REF: NDT PART 2/57-10-01										
P5710029 ^S			* WING MID-SPAR VERTICAL WEB - PERFORM EDDY CURRENT INSPECTION							Service ATA:57
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								
PROC. REF: NDT PART 6/57-10-07PROC. REF: NDT PART 6/57-10-07										
P5710030 ^S			* WING REAR SPAR VERTICAL WEB - PERFORM EDDY CURRENT INSPECTION							Service ATA:57
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								
PROC. REF: NDT PART 6/57-20-05PROC. REF: NDT PART 6/57-20-05										
P5710032 ^S			* WING RIB UPPER AFT FLANGE FILLET RADIUS AT WS 33.0 - PERFORM ULTRASONIC INSPECTION							Service ATA:57
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0								
PROC. REF: NDT PART 4/57-30-02PROC. REF: NDT PART 4/57-30-02										
P5710033 ^S			* WING ACCESS HOLE IN CLOSING RIB BETWEEN MID AND REAR SPAR - PERFORM EDDY CURRENT INSPECTION							Service ATA:57
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0								
PROC. REF: NDT PART 6/57-10-05PROC. REF: NDT PART 6/57-10-05										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 57 - WINGS										
P5710034	^S	* WING BOX JOINT TO WINGLET - PERFORM EDDY CURRENT INSPECTION							Service	ATA:57
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0		T:9600						
	AFL	0								
PROC. REF: NDT PART 6/57-10-13PROC. REF: NDT PART 6/57-10-13										
PKG:25										
P5710083	^S	* FLAP BOX BASIC STRUCTURE - PERFORM EDDY CURRENT INSPECTION							Service	ATA:57
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0		T:9600						
	AFL	0								
PROC. REF: NDT PART 6/57-40-02PROC. REF: NDT PART 6/57-40-02										
PKG:25										
P5710085	^S	SPOILER UPPER SKIN - PERFORM EDDY CURRENT INSPECTION							Service	ATA:57
	MOS	09-Mar-01								
	HRS	0		T:9600						
	AFL	0								
PROC. REF: NDT PART 6/57-10-16PROC. REF: NDT PART 6/57-10-16										
PKG:25										
P5710086	^S	SPOILER BOLTS AND HINGE PINS - PERFORM MAGNETIC PARTICLE INSPECTION							Service	ATA:57
	MOS	09-Mar-01								
	HRS	0		T:9600						
	AFL	0								
PROC. REF: NDT PART 7/27-10-01PROC. REF: NDT PART 7/27-10-01										
PKG:25										
P5710181	^S	* WING DRAG LINK TUBE - PERFORM MAGNETIC PARTICLE INSPECTION							Service	ATA:57
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0		T:9600						
	AFL	0								
PROC. REF: NDT PART 7/57-30-01PROC. REF: NDT PART 7/57-30-01										
PKG:22										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 57 - WINGS										
P5710182	S	* WING DRAG LINK ATTACH BOLTS - PERFORM LIQUID PENETRANT INSPECTION						Service	ATA:57	
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0								
PROC. REF: NDT PART 8/57-10-01PROC. REF: NDT PART 8/57-10-01										
PKG:22										
P5710183	S	* WING DRAG LINK ATTACH CLEVIS - PERFORM MAGNETIC PARTICLE INSPECTION						Service	ATA:57	
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0								
PROC. REF: NDT PART 7/57-10-01PROC. REF: NDT PART 7/57-10-01										
PKG:22										
P5710184	S	* WING ATTACH BOLTS - PERFORM FLUORESCENT PENETRANT INSPECTION						Service	ATA:57	
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0								
PROC. REF: NDT PART 8/57-10-02PROC. REF: NDT PART 8/57-10-02										
PKG:25										
P5710185	S	* WING ATTACH LINKS - PERFORM MAGNETIC PARTICLE INSPECTION						Service	ATA:57	
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0								
PROC. REF: NDT PART 7/57-10-03PROC. REF: NDT PART 7/57-10-03										
PKG:25										
P5710186	S	* WING ATTACH FITTINGS AT MID SPAR AND REAR SPAR - PERFORM MAGNETIC PARTICLE INSPECTION						Service	ATA:57	
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0								
PROC. REF: NDT PART 7/57-10-02PROC. REF: NDT PART 7/57-10-02										
PKG:25										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 57 - WINGS										
P5750002	^S	* FLAP FRONT SPAR CUTOUTS - PERFORM EDDY CURRENT INSPECTION							Service	ATA:57
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0								
PROC. REF: NDT PART 6/57-10-15PROC. REF: NDT PART 6/57-10-15										
PKG:22										
P5750003	^S	* FLAP NOSE ROLLER RIBS - PERFORM EDDY CURRENT INSPECTION							Service	ATA:57
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0								
PROC. REF: NDT PART 6/57-10-14PROC. REF: NDT PART 6/57-10-14										
PKG:25										
P5750004	^S	* FLAP ACTUATOR SUPPORT RIBS - PERFORM EDDY CURRENT INSPECTION							Service	ATA:57
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								
PROC. REF: NDT PART 6/57-10-21PROC. REF: NDT PART 6/57-10-21										
PKG:26										
P5750048	^S	* FLAP TRACKS - PERFORM MAGNETIC PARTICLE INSPECTION							Service	ATA:57
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								
PROC. REF: NDT PART 7/57-71-01PROC. REF: NDT PART 7/57-71-01										
PKG:26										
P5750049	^S	* FLAP NOSE ROLLER TRACKS - PERFORM MAGNETIC PARTICLE INSPECTION WITH FLAPS REMOVED							Service	ATA:57
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								
PROC. REF: NDT PART 7/57-10-04PROC. REF: NDT PART 7/57-10-04										
PKG:26										

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 57 - WINGS										
P5750053	^S	* FLAP TRACK SUPPORT RIBS - PERFORM EDDY CURRENT INSPECTION							Service	ATA:57
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								
PROC. REF: NDT PART 6/57-10-17PROC. REF: NDT PART 6/57-10-17										
PKG:26										
P5750068	^S	* FLAP FRONT-SPAR RIB SUPPORT STRUCTURE - PERFORM EDDY CURRENT INSPECTION							Service	ATA:57
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0								
PROC. REF: NDT PART 6/57-10-26PROC. REF: NDT PART 6/57-10-26										
PKG:25										
P5760000	^S	* AILERON ACTUATOR HINGE FITTING - PERFORM EDDY CURRENT INSPECTION							Service	ATA:57
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								
PROC. REF: NDT PART 6/57-10-25PROC. REF: NDT PART 6/57-10-25										
PKG:26										
P5760001	^S	* AILERON SKIN - PERFORM EDDY CURRENT INSPECTION							Service	ATA:57
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								
PROC. REF: NDT PART 6/57-10-19PROC. REF: NDT PART 6/57-10-19										
PKG:26										
P5760002	^S	* AILERON BALANCE TAB HINGE FITTINGS - PERFORM EDDY CURRENT INSPECTION							Service	ATA:57
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0								
PROC. REF: NDT PART 6/57-60-01PROC. REF: NDT PART 6/57-60-01										
PKG:22										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 57 - WINGS										
P5760003	^S	* AILERON TRIM AND BALANCE TAB FRONT SPARS - PERFORM RADIOGRAPHIC INSPECTION						Service	ATA:57	
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0								
PROC. REF: NDT PART 2/57-60-01PROC. REF: NDT PART 2/57-60-01										
P5760005	^S	* AILERON HINGE LUGS AND FITTINGS - PERFORM EDDY CURRENT INSPECTION						Service	ATA:57	
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								
PROC. REF: NDT PART 6/57-10-24PROC. REF: NDT PART 6/57-10-24										
P5760014	^S	* AILERON HINGE SUPPORT STRUCTURE - PERFORM EDDY CURRENT INSPECTION						Service	ATA:57	
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								
PROC. REF: NDT PART 6/57-10-23PROC. REF: NDT PART 6/57-10-23										
P5770000	^S	SPOILER HINGE ASSEMBLIES AND ACTUATOR FITTING - PERFORM EDDY CURRENT INSPECTION						Service	ATA:57	
	MOS	09-Mar-01								
	HRS	0	T:9600							
	AFL	0								
PROC. REF: NDT PART 6/57-10-22PROC. REF: NDT PART 6/57-10-22										
Q5710156	^S	* WING BOX BASIC SKIN/STRINGER, LOWER SKIN - PERFORM VISUAL INSPECTION. INSPECT OUTBOARD WING FORWARD AND AFT LOWER SKIN PANELS AND STRINGERS.						Service	ATA:57	
	MOS/MSC	09-Mar-01	N/A							
	HRS	0								
	AFL	0								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 57 - WINGS										
Q5710162	^S	* WING BOX FRONT SPAR LOWER CAP - PERFORM VISUAL INSPECTION. INSPECT FRONT SPAR LOWER CAP AND LOWER FORWARD SKIN OUTBOARD OF MID-SPAR STATION (MS) 55.						Service	ATA:57	
	MOS/MSC	09-Mar-01	N/A							
	HRS	0								
	AFL	0							PKG:22	
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
Q5710166	^S	* WING BOX MID SPAR, OUTBOARD OF RIB NO. 8 - PERFORM VISUAL INSPECTION AT WS 156 AND OUTBOARD TO WS 260						Service	ATA:57	
	MOS/MSC	09-Mar-01	N/A							
	HRS	0								
	AFL	0							PKG:22	
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
Q5710167	^S	* WING BOX REAR SPAR, OUTBOARD OF RIB NO. 6 - PERFORM VISUAL INSPECTION AT WS 118 AND OUTBOARD TO WS 260						Service	ATA:57	
	MOS/MSC	09-Mar-01	N/A							
	HRS	0								
	AFL	0							PKG:22	
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
U5710147	^S	* WING BOX MID SPAR LOWER CAP, OUTBOARD OF JOINT AT WS 137 BETWEEN RIB NO. 7 AND NO. 8 - PERFORM DETAILED VISUAL INSPECTION. INSPECT MID SPAR LOWER CAP AND LOWER SKIN PANELS.						Service	ATA:57	
	MOS/MSC	09-Mar-01	N/A							
	HRS	0								
	AFL	0							PKG:10	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
U5710154	^S	* WING BOX REAR SPAR LOWER CAP OUTBOARD OF JOINT AT WS 81 TO RIB NO. 6 - PERFORM DETAILED VISUAL INSPECTION. INSPECT OUTER REAR SPAR LOWER CAP AND AFT LOWER SKIN PANEL OUTBOARD OF REAR SPLICE AT WS 90.						Service	ATA:57	
	MOS/MSC	09-Mar-01	N/A							
	HRS	0								
	AFL	0							PKG:10	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
V5710039	S	WINGLET SKIN - PERFORM EDDY CURRENT INSPECTION						Service	ATA:57
	MOS	09-Mar-01							
	HRS	0	T:9600						
	AFL	0							
PROC. REF: NDT PART 6/57-10-18PROC. REF: NDT PART 6/57-10-18									
PKG:25									
Y5700001	S	WINGLET - PERFORM VISUAL INSPECTION						Service	ATA:57
	MOS	21-Aug-25	12						
	HRS	9809.8	300						
	AFL	7471							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
PKG:4									
Y5700002	S	FLUX VALVE BRACKET - VISUALLY INSPECT FOR CRACKS						Service	ATA:57
	MOS	09-Mar-01	12						
	HRS	0	300						
	AFL	0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
PKG:4									
Y5710000	S	WING - PERFORM EXTERNAL VISUAL INSPECTION FROM BL 0.00 TO WS 260						Service	ATA:57
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
PKG:16									
Y5710180	S	EXTERNAL LOWER WING SKIN - PERFORM VISUAL INSPECTION						Service	ATA:57
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
PKG:10									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 57 - WINGS										
Y5730013	S	AILERON BRUSH SEALS - PERFORM DETAILED INSPECTION						Service	ATA:57	
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 57-60-01PROC. REF: AMM 57-60-01										
PKG:4										
Y5750067	S	FLAP BRACKETS - PERFORM DETAILED VISUAL INSPECTION						Service	ATA:57	
	MOS	25-Nov-19	96							
	HRS	8177.7	2400							
	AFL	6303								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
PKG:22										
Y5750069	S	FLAPS - PERFORM VISUAL INSPECTION OF FLAP NOSE ROLLERS, FLAP TRACKS, FLAP NOSE ROLLER TRACKS, AND FLAP MAIN TRACK ROLLERS.						Service	ATA:57	
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
PKG:4										
Y5750071	S	FLAPS - WITH FLAPS REMOVED, PERFORM DETAILED VISUAL INSPECTION OF FLAP NOSE ROLLERS, FLAP TRACKS, FLAP NOSE ROLLER TRACKS, AND FLAP MAIN TRACK ROLLERS.						Service	ATA:57	
	MOS	09-Mar-01	48							
	HRS	0	1200							
	AFL	0								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
PKG:16										
ATA 71 - POWER PLANT										
545021		NO. 1 ENGINE AFT MOUNT TO END FITTING ATTACH BOLT						Component	ATA:71	
PN:PN	MOS/MSC	09-Mar-01	H/T	TSN	0					
SN:UNKNOWN	HRS	0		TSN	0					
	AFL	0		TSN	0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 71 - POWER PLANT										
545022	NO. 2 ENGINE AFT MOUNT TO END FITTING ATTACH BOLT								Component	ATA:71
PN:PN	MOS/MSC	09-Mar-01	H/T	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
545023	NO. 1 ENGINE TO AFT ENGINE MOUNT ATTACH BOLTS								Component	ATA:71
PN:PN	MOS/MSC	09-Mar-01	H/T	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
545024	NO. 2 ENGINE TO AFT ENGINE MOUNT ATTACH BOLTS								Component	ATA:71
PN:PN	MOS/MSC	09-Mar-01	H/T	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
710100	NO. 1 ENGINE - MAIN ENGINE WIRING HARNESS ASSEMBLY								Component	ATA:71
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-00-02, LMM 72-00-02PROC. REF: LMM 72-00-02, LMM 72-00-02										
710100	NO. 2 ENGINE - MAIN ENGINE WIRING HARNESS ASSEMBLY								Component	ATA:71
PN:3060757-3	MOS/MSC	06-Jul-23	O/C	TSN 0						
SN:22-129505-00163	HRS	8350.6		TSN 0						
	ENC	6943		TSN 0						
PROC. REF: LMM 72-00-02, LMM 72-00-02PROC. REF: LMM 72-00-02, LMM 72-00-02										
710130 ^S	NO. 1 ENGINE - INSPECT TAILPIPE/LPT3 ROTOR ASSEMBLY-VISUALLY INSPECT FOR FOREIGN OBJECT DAMAGE, THERMAL DISTRESS, AND LEAKS.								Service	ATA:71
	MOS	21-Aug-25								
	HRS	9735.7	800							
	ENC	7413								
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00										

PKG:0

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 71 - POWER PLANT

710130 ^S	NO. 2 ENGINE - INSPECT TAILPIPE/LPT3 ROTOR ASSEMBLY-VISUALLY INSPECT FOR FOREIGN OBJECT DAMAGE, THERMAL DISTRESS, AND LEAKS.							Service	ATA:71
	MOS		21-Aug-25						
	HRS		8897	800					
	ENC		7309						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									

PKG:0

710140 ^S	NO. 1 ENGINE - INSPECT INLET/FAN AREA - INSPECT FOR FOREIGN OBJECT DAMAGE AND LEAKAGE (REFER TO PARAGRAPH 4.B)							Service	ATA:71
	MOS		21-Aug-25						
	HRS		9735.7	800					
	ENC		7413						
PROC. REF: LMM 72-00-00, LMM 72-00-00PROC. REF: LMM 72-00-00, LMM 72-00-00									

PKG:0

710140 ^S	NO. 2 ENGINE - INSPECT INLET/FAN AREA - INSPECT FOR FOREIGN OBJECT DAMAGE AND LEAKAGE (REFER TO PARAGRAPH 4.B)							Service	ATA:71
	MOS		21-Aug-25						
	HRS		8897	800					
	ENC		7309						
PROC. REF: LMM 72-00-00, LMM 72-00-00PROC. REF: LMM 72-00-00, LMM 72-00-00									

PKG:0

711001	NO. 1 ENGINE FORWARD MOUNT							Component	ATA:71
PN:PN	MOS/MSC		09-Mar-01	O/C	TSN 0				
SN:UNKNOWN	HRS		0		TSN 0				
	AFL		0		TSN 0				
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									

711002	NO. 2 ENGINE FORWARD MOUNT							Component	ATA:71
PN:PN	MOS/MSC		09-Mar-01	O/C	TSN 0				
SN:UNKNOWN	HRS		0		TSN 0				
	AFL		0		TSN 0				
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									

7120005 ^U	CHANGE NO. 2 ALL							Service	ATA:71
	MOS/MSC		N/A						
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 71 - POWER PLANT

PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00

7120005	U	REPLACE NO. 2 ENGINE AFT ENGINE MOUNT ISOLATOR BONDED MOUNTING						Service	ATA:71
	MOS/MSC	26-Jul-23	N/A	TAC	0				
	HRS	9278		TAC	0				
	AFL	7111		TAC	0				

7120006		REPLACE NO. 1 ENGINE ALL ENGINE MOUNT ISOLATOR FORWARD BONDED MOUNTING						Service	ATA:71
	MOS/MSC	09-Mar-01	N/A	TAC	0				
	HRS	0		TAC	0				
	AFL	0		TAC	0				

PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00

7120006	U	REPLACE NO. 2 ENGINE AFT ENGINE MOUNT ISOLATOR BONDED MOUNTING						Service	ATA:71
	MOS/MSC	09-Mar-01	N/A	TAC	0				
	HRS	0		TAC	0				
	AFL	0		TAC	0				

7120006		REPLACE NO. 2 ENGINE ALL ENGINE MOUNT ISOLATOR FORWARD BONDED MOUNTING						Service	ATA:71
	MOS/MSC	09-Mar-01	N/A	TAC	0				
	HRS	0		TAC	0				
	AFL	0		TAC	0				

PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00

712005		NO. 1 ENGINE - AFT ENGINE MOUNT - ISOLATOR ASSEMBLY						Component	ATA:71
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN	0				
SN:UNKNOWN	HRS	0		TSN	0				
	AFL	0		TSN	0				

PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00

712006		NO. 2 ENGINE - AFT ENGINE MOUNT - ISOLATOR ASSEMBLY						Component	ATA:71
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN	0				
SN:UNKNOWN	HRS	0		TSN	0				
	AFL	0		TSN	0				

PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 71 - POWER PLANT										
7120069	U	NO. 1 ALL							Service	ATA:71
	MOS/MSC	26-Jul-23	N/A							
	HRS	9278								
	AFL	7111								
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00										
7120069	U	NO. 2 ALL							Service	ATA:71
	MOS/MSC	26-Jul-23	N/A							
	HRS	9278								
	AFL	7111								
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00										
712007		NO. 1 ENGINE - FORWARD ENGINE MOUNT - UPPER ISOLATOR ASSEMBLY							Component	ATA:71
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00										
7120070	U	CHANGE NO. 1 ALL							Service	ATA:71
	MOS	26-Jul-23		TAC 0				LIFE LIMIT		
	HRS	9278	6000	TAC 0	15278		5254.9			
	AFL	7111		TAC 0						
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00										
7120070	U	CHANGE NO. 2 ALL							Service	ATA:71
	MOS	26-Jul-23		TAC 0				LIFE LIMIT		
	HRS	9278	6000	TAC 0	15278		5254.9			
	AFL	7111		TAC 0						
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00										
7120070	U	REPLACE NO. 2 ENGINE AFT ENGINE MOUNT ISOLATOR BONDED MOUNTING							Service	ATA:71
	MOS/MSC	26-Jul-23	O/C	TAC 0				LIFE LIMIT		
	HRS	9278		TAC 0						
	AFL	7111		TAC 0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 71 - POWER PLANT										
7120073 ^U		NO. 1 ALL							Service	ATA:71
	MOS	26-Jul-23								
	HRS	9278	6000		15278		5254.9			
	AFL	7111								
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00										
7120073 ^U		NO. 2 ALL							Service	ATA:71
	MOS	26-Jul-23								
	HRS	9278	6000		15278		5254.9			
	AFL	7111								
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00										
712008		NO. 2 ENGINE - FORWARD ENGINE MOUNT - UPPER ISOLATOR ASSEMBLY							Component	ATA:71
PN:LM833-SA20-5	MOS/MSC	26-Sep-06	O/C							
SN:LK3128	HRS	4857.22								
	AFL	3730								
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00										
712009		NO. 2 ENGINE - FORWARD ENGINE MOUNT - LOWER ISOLATOR ASSEMBLY							Component	ATA:71
PN:KM833-SA20-5	MOS/MSC	26-Sep-06	O/C							
SN:LK3185	HRS	4857.22								
	AFL	3730								
PROC. REF: NDT PART 7/32-10-08, NDT PART 7/32-10-03, NDT PART 7/32-10-04, NDT PART 8/32-10-02, NDT PART 8/54-30-01, NDT PART 8/54-30-02, AMM 71-20-00PROC. REF: NDT PART 7/32-10-08, NDT PART 7/32-10-03, NDT PART 7/32-10-04, NDT PART 8/32-10-02, NDT PART 8/54-30-01, NDT PART 8/54-30-02, AMM 71-20-00										
712010		NO. 1 ENGINE - FORWARD ENGINE MOUNT - LOWER ISOLATOR ASSEMBLY							Component	ATA:71
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00										
712045		NO. 1 ENGINE AFT MOUNT							Component	ATA:71
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 71 - POWER PLANT										
712046	NO. 2 ENGINE AFT MOUNT								Component	ATA:71
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00										
712078	NO. 1 ENGINE AFT MOUNT BOLT								Component	ATA:71
PN:4571408525-001	MOS/MSC	26-Jul-23	E/C	TSN 0		AIRWORTHINESS				
SN:UNKNOWN	HRS	9278	TSN 0							
	AFL	7111	TSN 0							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00										
712079	NO. 2 ENGINE AFT MOUNT BOLT								Component	ATA:71
PN:4571408525-001	MOS/MSC	26-Jul-23	E/C	TSN 0		AIRWORTHINESS				
SN:UNKNOWN	HRS	9278	TSN 0							
	AFL	7111	TSN 0							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00										
714010 ^S	NO. 1 ENGINE - CHECK ELECTRICAL WIRES AND CONNECTIONS - VISUALLY INSPECT FOR SECURITY AND DAMAGE								Service	ATA:71
	MOS	21-Aug-25								
	HRS	9735.7	800							
	ENC	7413								
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00										
714010 ^S	NO. 2 ENGINE - CHECK ELECTRICAL WIRES AND CONNECTIONS - VISUALLY INSPECT FOR SECURITY AND DAMAGE								Service	ATA:71
	MOS	21-Aug-25								
	HRS	8897	800							
	ENC	7309								
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00										
715010 ^S	NO. 1 ENGINE - CHECK PLUMBING LINES AND CONNECTIONS - VISUALLY INSPECT FOR SECURITY, LOOSE OR BROKEN CLAMPS OR BRACKETS, LEAKS, CRACKS, CUTS, OR RUBBING								Service	ATA:71
	MOS	21-Aug-25								
	HRS	9735.7	800							
	ENC	7413								
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00										

PKG:0

PKG:0

PKG:0

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 71 - POWER PLANT

PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00

715010 ^S	NO. 2 ENGINE - CHECK PLUMBING LINES AND CONNECTIONS - VISUALLY INSPECT FOR SECURITY, LOOSE OR BROKEN CLAMPS OR BRACKETS, LEAKS, CRACKS, CUTS, OR RUBBING							Service	ATA:71
	MOS		21-Aug-25						
	HRS		8897		800				
	ENC		7309						

PKG:0

PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00

716005	NO. 1 ENGINE INLET NACELLE							Component	ATA:71
PN:4572290001-801	MOS/MSC		16-Jul-19		O/C				
SN:145LH	HRS		8109						
	AFL		6239						

PROC. REF: AMM 71-10-01PROC. REF: AMM 71-10-01

716006	NO. 2 ENGINE INLET NACELLE							Component	ATA:71
PN:2652000V24-003	MOS/MSC		02-Dec-09		O/C	TSR 0			
SN:114RH	HRS		6213.6			TSR 0			
	AFL		4758			TSR 0			

PROC. REF: AMM 71-10-01PROC. REF: AMM 71-10-01

71EN1	NO. 1 ENGINE							Component	ATA:71
PN:3060082-2	MOS/MSC				E/C				
SN:P-116284C	HRS								
	AFL								

Special Properties: RII ITEM

PROC. REF: SIL F731-88, AMM 71-00-01PROC. REF: SIL F731-88, AMM 71-00-01

71EN2	NO. 2 ENGINE							Component	ATA:71
PN:3060084-2	MOS/MSC		12-Aug-15		E/C				
SN:P-116285C	HRS		7535.1			TSN 6622.3			
	AFL		5764						

Special Properties: RII ITEM

PROC. REF: SIL F731-88, AMM 71-00-01PROC. REF: SIL F731-88, AMM 71-00-01

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 71 - POWER PLANT										
AA7120069	NO. 1 ENGINE - AFT ENGINE MOUNT - ISOLATOR ASSEMBLY - PERFORM VISUAL INSPECTION OF FORWARD AND AFT ISOLATORS AND ASSOCIATED PARTS								Service	ATA:71
	MOS	26-Jul-23								
	HRS	9278	3000		12278		2254.9			
	AFL	7111								
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00										
AA7120069	NO. 1 ENGINE - FORWARD ENGINE MOUNT - LOWER ISOLATOR ASSEMBLY - PERFORM VISUAL INSPECTION OF FORWARD AND AFT ISOLATORS AND ASSOCIATED PARTS								Service	ATA:71
	MOS	26-Jul-23								
	HRS	9278	3000		12278		2254.9			
	AFL	7111								
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00										
AA7120069	NO. 1 ENGINE - FORWARD ENGINE MOUNT - UPPER ISOLATOR ASSEMBLY - PERFORM VISUAL INSPECTION OF FORWARD AND AFT ISOLATORS AND ASSOCIATED PARTS								Service	ATA:71
	MOS	26-Jul-23								
	HRS	9278	3000		12278		2254.9			
	AFL	7111								
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00										
AA7120069	NO. 2 ENGINE - AFT ENGINE MOUNT - ISOLATOR ASSEMBLY - PERFORM VISUAL INSPECTION OF FORWARD AND AFT ISOLATORS AND ASSOCIATED PARTS								Service	ATA:71
	MOS	26-Jul-23								
	HRS	9278	3000		12278		2254.9			
	AFL	7111								
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00										
AA7120069	NO. 2 ENGINE - FORWARD ENGINE MOUNT - LOWER ISOLATOR ASSEMBLY - PERFORM VISUAL INSPECTION OF FORWARD AND AFT ISOLATORS AND ASSOCIATED PARTS								Service	ATA:71
PN:KM833-SA20-5	MOS	26-Jul-23								
SN:LK3185	HRS	9278	3000		12278		2254.9			
	AFL	7111								
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 71 - POWER PLANT										
AA7120069	NO. 2 ENGINE - FORWARD ENGINE MOUNT - UPPER ISOLATOR ASSEMBLY - PERFORM VISUAL INSPECTION OF FORWARD AND AFT ISOLATORS AND ASSOCIATED PARTS								Service	ATA:71
PN:LM833-SA20-5	MOS	26-Jul-23								
SN:LK3128	HRS	9278	3000		12278		2254.9			
	AFL	7111								
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00										
AD7120005	NO. 1 ENGINE - FORWARD ENGINE MOUNT - LOWER ISOLATOR ASSEMBLY - REPLACE BONDED MOUNTING								Service	ATA:71
	MOS/MSC	26-Jul-23	N/A		TAC 0					
	HRS	9278			TAC 0					
	AFL	7111			TAC 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00										
AD7120005	NO. 1 ENGINE - FORWARD ENGINE MOUNT - UPPER ISOLATOR ASSEMBLY - REPLACE BONDED MOUNTING								Service	ATA:71
	MOS/MSC	26-Jul-23	N/A		TAC 0					
	HRS	9278			TAC 0					
	AFL	7111			TAC 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00										
AD7120005	NO. 2 ENGINE - FORWARD ENGINE MOUNT - LOWER ISOLATOR ASSEMBLY - REPLACE BONDED MOUNTING								Service	ATA:71
PN:KM833-SA20-5	MOS/MSC	26-Jul-23	N/A		TAC 0					
SN:LK3185	HRS	9278			TAC 0					
	AFL	7111			TAC 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00										
AD7120005	NO. 2 ENGINE - FORWARD ENGINE MOUNT - UPPER ISOLATOR ASSEMBLY - REPLACE BONDED MOUNTING								Service	ATA:71
PN:LM833-SA20-5	MOS/MSC	26-Jul-23	N/A		TAC 0					
SN:LK3128	HRS	9278			TAC 0					
	AFL	7111			TAC 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00										
AD7120005 U	REPLACE NO. 1 ENGINE AFT ENGINE MOUNT ISOLATOR FORWARD BONDED MOUNTING								Service	ATA:71
	MOS/MSC	26-Jul-23	N/A		TAC 0					
	HRS	9278			TAC 0					
	AFL	7111			TAC 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 71 - POWER PLANT										
AD7120005	REPLACE NO. 1 ENGINE ALL ENGINE MOUNT ISOLATOR BONDED MOUNTING								Service	ATA:71
	MOS/MSC	27-Sep-06	N/A							
	HRS	4857.2								
	AFL	3730								
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00										
AD7120006	NO. 1 ENGINE - FORWARD ENGINE MOUNT - LOWER ISOLATOR ASSEMBLY - REPLACE BONDED MOUNTING								Service	ATA:71
	MOS/MSC	09-Mar-01	N/A		TAC 0					
	HRS	0			TAC 0					
	AFL	0			TAC 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00										
AD7120006	NO. 1 ENGINE - FORWARD ENGINE MOUNT - UPPER ISOLATOR ASSEMBLY - REPLACE BONDED MOUNTING								Service	ATA:71
	MOS/MSC	09-Mar-01	N/A		TAC 0					
	HRS	0			TAC 0					
	AFL	0			TAC 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00										
AD7120006	NO. 2 ENGINE - FORWARD ENGINE MOUNT - LOWER ISOLATOR ASSEMBLY - REPLACE BONDED MOUNTING								Service	ATA:71
	MOS/MSC	09-Mar-01	N/A		TAC 0					
	HRS	0			TAC 0					
	AFL	0			TAC 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00										
AD7120006	NO. 2 ENGINE - FORWARD ENGINE MOUNT - UPPER ISOLATOR ASSEMBLY - REPLACE BONDED MOUNTING								Service	ATA:71
	MOS/MSC	09-Mar-01	N/A		TAC 0					
	HRS	0			TAC 0					
	AFL	0			TAC 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00										
AD7120006 ^U	REPLACE NO. 1 ENGINE AFT ENGINE MOUNT ISOLATOR BONDED MOUNTING								Service	ATA:71
	MOS/MSC	09-Mar-01	N/A		TAC 0					
	HRS	0			TAC 0					
	AFL	0			TAC 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 71 - POWER PLANT									
AD7120070 NO. 1 ENGINE - FORWARD ENGINE MOUNT - LOWER ISOLATOR ASSEMBLY - REPLACE BONDED MOUNTING Service ATA:71									
	MOS	26-Jul-23		TAC 0				LIFE LIMIT	
	HRS	9278	6000	TAC 0	15278		5254.9		
	AFL	7111		TAC 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
AD7120070 NO. 1 ENGINE - FORWARD ENGINE MOUNT - UPPER ISOLATOR ASSEMBLY - REPLACE BONDED MOUNTING Service ATA:71									
	MOS	26-Jul-23		TAC 0				LIFE LIMIT	
	HRS	9278	6000	TAC 0	15278		5254.9		
	AFL	7111		TAC 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
AD7120070 NO. 2 ENGINE - FORWARD ENGINE MOUNT - LOWER ISOLATOR ASSEMBLY - REPLACE BONDED MOUNTING Service ATA:71									
PN:KM833-SA20-5	MOS	26-Jul-23		TAC 0				LIFE LIMIT	
SN:LK3185	HRS	9278	6000	TAC 0	15278		5254.9		
	AFL	7111		TAC 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
AD7120070 NO. 2 ENGINE - FORWARD ENGINE MOUNT - UPPER ISOLATOR ASSEMBLY - REPLACE BONDED MOUNTING Service ATA:71									
PN:LM833-SA20-5	MOS	26-Jul-23		TAC 0				LIFE LIMIT	
SN:LK3128	HRS	9278	6000	TAC 0	15278		5254.9		
	AFL	7111		TAC 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
AD7120070 ^U REPLACE NO. 1 ENGINE AFT ENGINE MOUNT ISOLATOR BONDED MOUNTING Service ATA:71									
	MOS/MSC	26-Jul-23	O/C	TAC 0				LIFE LIMIT	
	HRS	9278		TAC 0					
	AFL	7111		TAC 0					
AD7120075 NO. 1 ENGINE - AFT ENGINE MOUNT - ISOLATOR ASSEMBLY - PERFORM DETAILED INSPECTION OF AFT ISOLATOR ASSEMBLY AND ASSOCIATED PARTS Service ATA:71									
	MOS/MSC	26-Jul-23	MPI						
	HRS	9278	3600		12878		2854.9		
	AFL	7111							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 71 - POWER PLANT										
AD7120075	NO. 2 ENGINE - AFT ENGINE MOUNT - ISOLATOR ASSEMBLY - PERFORM DETAILED INSPECTION OF AFT ISOLATOR ASSEMBLY AND ASSOCIATED PARTS								Service	ATA:71
	MOS/MSC	26-Jul-23	MPI							
	HRS	9278	3600		12878		2854.9			
	AFL	7111								
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00										
K7120004	NO. 1 ENGINE - AFT ENGINE MOUNT - ISOLATOR ASSEMBLY - REPLACE HOUSING								Service	ATA:71
	MOS	09-Mar-01		TAC 0				LIFE LIMIT		
	HRS	0	15000	TAC 0	15000		4976.9			
	AFL	0		TAC 0						
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00										
K7120004	NO. 1 ENGINE - FORWARD ENGINE MOUNT - LOWER ISOLATOR ASSEMBLY - REPLACE HOUSING								Service	ATA:71
	MOS	09-Mar-01		TAC 0				LIFE LIMIT		
	HRS	0	15000	TAC 0	15000		4976.9			
	AFL	0		TAC 0						
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00										
K7120004	NO. 1 ENGINE - FORWARD ENGINE MOUNT - UPPER ISOLATOR ASSEMBLY - REPLACE HOUSING								Service	ATA:71
	MOS	09-Mar-01		TAC 0				LIFE LIMIT		
	HRS	0	15000	TAC 0	15000		4976.9			
	AFL	0		TAC 0						
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00										
K7120004	NO. 2 ENGINE - AFT ENGINE MOUNT - ISOLATOR ASSEMBLY - REPLACE HOUSING								Service	ATA:71
	MOS	09-Mar-01		TAC 0				LIFE LIMIT		
	HRS	0	15000	TAC 0	15000		4976.9			
	AFL	0		TAC 0						
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00										
K7120004	NO. 2 ENGINE - FORWARD ENGINE MOUNT - LOWER ISOLATOR ASSEMBLY - REPLACE HOUSING								Service	ATA:71
	MOS	09-Mar-01		TAC 0				LIFE LIMIT		
	HRS	0	15000	TAC 0	15000		4976.9			
	AFL	0		TAC 0						
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 71 - POWER PLANT										
K7120004	NO. 2 ENGINE - FORWARD ENGINE MOUNT - UPPER ISOLATOR ASSEMBLY - REPLACE HOUSING								Service	ATA:71
	MOS	09-Mar-01		TAC 0				LIFE LIMIT		
	HRS	0	15000	TAC 0	15000		4976.9			
	AFL	0		TAC 0						
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00										
K7120004	REPLACE ALL FORWARD AND AFT ENGINE MOUNT ISOLATOR HOUSINGS								Service	ATA:71
	MOS	09-Mar-01		TAC 0				LIFE LIMIT		
	HRS	0	15000	TAC 0	15000		4976.9			
	AFL	0		TAC 0						
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00										
P7120001 ^S	* FORWARD ENGINE MOUNT - PERFORM EDDY CURRENT INSPECTION								Service	ATA:71
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0								
PROC. REF: NDT PART 6/71-10-01PROC. REF: NDT PART 6/71-10-01										
Q7110004	NO. 1 ENGINE INLET - PERFORM TAP TEST								Service	ATA:71
	MOS	02-Nov-22								
	HRS	9151.6	3000		12151.6		2128.5			
	AFL	7021								
PROC. REF: AMM 71-10-01PROC. REF: AMM 71-10-01										
Q7110004	NO. 2 ENGINE INLET - PERFORM TAP TEST								Service	ATA:71
	MOS	12-Aug-15								
	HRS	7535.1	3000		10535.1		512			
	AFL	5764								
PROC. REF: AMM 71-10-01PROC. REF: AMM 71-10-01										
Q7120002	NO. 1 ENGINE - AFT ENGINE MOUNT - ISOLATOR ASSEMBLY - PERFORM DETAILED INSPECTION OF FORWARD AND AFT ISOLATORS AND ASSOCIATED PARTS								Service	ATA:71
	MOS/MSC	26-Jul-23	N/A							
	HRS	9278								
	AFL	7111								
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 71 - POWER PLANT									
Q7120002	NO. 1 ENGINE - FORWARD ENGINE MOUNT - LOWER ISOLATOR ASSEMBLY - PERFORM DETAILED INSPECTION OF FORWARD AND AFT ISOLATORS AND ASSOCIATED PARTS							Service	ATA:71
	MOS/MSC	26-Jul-23	N/A						
	HRS	9278							
	AFL	7111							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
Q7120002	NO. 1 ENGINE - FORWARD ENGINE MOUNT - UPPER ISOLATOR ASSEMBLY - PERFORM DETAILED INSPECTION OF FORWARD AND AFT ISOLATORS AND ASSOCIATED PARTS							Service	ATA:71
	MOS/MSC	26-Jul-23	N/A						
	HRS	9278							
	AFL	7111							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
Q7120002	NO. 1 ENGINE ALL ISOLATORS - PERFORM INSPECTION OF ISOLATORS AND ASSOCIATED PARTS							Service	ATA:71
	MOS/MSC	27-Sep-06	N/A						
	HRS	4857.2							
	AFL	3730							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
Q7120002	NO. 2 ENGINE - AFT ENGINE MOUNT - ISOLATOR ASSEMBLY - PERFORM DETAILED INSPECTION OF FORWARD AND AFT ISOLATORS AND ASSOCIATED PARTS							Service	ATA:71
	MOS/MSC	26-Jul-23	N/A						
	HRS	9278							
	AFL	7111							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
Q7120002	NO. 2 ENGINE - FORWARD ENGINE MOUNT - LOWER ISOLATOR ASSEMBLY - PERFORM DETAILED INSPECTION OF FORWARD AND AFT ISOLATORS AND ASSOCIATED PARTS							Service	ATA:71
PN:KM833-SA20-5	MOS/MSC	26-Jul-23	N/A						
SN:LK3185	HRS	9278							
	AFL	7111							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 71 - POWER PLANT									
Q7120002	NO. 2 ENGINE - FORWARD ENGINE MOUNT - UPPER ISOLATOR ASSEMBLY - PERFORM DETAILED INSPECTION OF FORWARD AND AFT ISOLATORS AND ASSOCIATED PARTS							Service	ATA:71
PN:LM833-SA20-5	MOS/MSC	26-Jul-23	N/A						
SN:LK3128	HRS	9278							
	AFL	7111							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
Q7120002	NO. 2 ENGINE ALL ISOLATORS - PERFORM INSPECTION OF ISOLATORS AND ASSOCIATED PARTS							Service	ATA:71
	MOS/MSC	27-Sep-06	N/A						
	HRS	4857.2							
	AFL	3730							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
Q7120073	NO. 1 ENGINE - AFT ENGINE MOUNT - ISOLATOR ASSEMBLY - PERFORM DETAILED INSPECTION OF FORWARD AND AFT ISOLATORS AND ASSOCIATED PARTS.							Service	ATA:71
	MOS	26-Jul-23							
	HRS	9278	6000		15278		5254.9		
	AFL	7111							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
Q7120073	NO. 1 ENGINE - FORWARD ENGINE MOUNT - LOWER ISOLATOR ASSEMBLY - PERFORM DETAILED INSPECTION OF FORWARD AND AFT ISOLATORS AND ASSOCIATED PARTS							Service	ATA:71
	MOS	26-Jul-23							
	HRS	9278	6000		15278		5254.9		
	AFL	7111							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
Q7120073	NO. 1 ENGINE - FORWARD ENGINE MOUNT - UPPER ISOLATOR ASSEMBLY - PERFORM DETAILED INSPECTION OF FORWARD AND AFT ISOLATORS AND ASSOCIATED PARTS							Service	ATA:71
	MOS	26-Jul-23							
	HRS	9278	6000		15278		5254.9		
	AFL	7111							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 71 - POWER PLANT									
Q7120073	NO. 2 ENGINE - AFT ENGINE MOUNT - ISOLATOR ASSEMBLY - PERFORM DETAILED INSPECTION OF FORWARD AND AFT ISOLATORS AND ASSOCIATED PARTS							Service	ATA:71
	MOS	26-Jul-23							
	HRS	9278	6000		15278		5254.9		
	AFL	7111							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
Q7120073	NO. 2 ENGINE - FORWARD ENGINE MOUNT - LOWER ISOLATOR ASSEMBLY - PERFORM DETAILED INSPECTION OF FORWARD AND AFT ISOLATORS AND ASSOCIATED PARTS							Service	ATA:71
PN:KM833-SA20-5	MOS	26-Jul-23							
SN:LK3185	HRS	9278	6000		15278		5254.9		
	AFL	7111							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
Q7120073	NO. 2 ENGINE - FORWARD ENGINE MOUNT - UPPER ISOLATOR ASSEMBLY - PERFORM DETAILED INSPECTION OF FORWARD AND AFT ISOLATORS AND ASSOCIATED PARTS.							Service	ATA:71
PN:LM833-SA20-5	MOS	26-Jul-23							
SN:LK3128	HRS	9278	6000		15278		5254.9		
	AFL	7111							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
R7100032	LEFT ENGINE NACELLE TUBES - PERFORM DETAILED VISUAL INSPECTION							Service	ATA:71
	MOS/MSC	10-Nov-11	N/A					NOT APPLICABLE	
	HRS	6740.8							
	AFL	5145							
PROC. REF: AMM 71-10-03PROC. REF: AMM 71-10-03									
Y7100002 ^S	LOWER ENGINE COWLING - VISUALLY INSPECT LATCH CHANNELS FOR CHAFING							Service	ATA:71
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									

PKG:9

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 71 - POWER PLANT									
Y7110000 ^S	ENGINE NACELLE - PERFORM VISUAL INSPECTION. INSPECT INLET BULKHEAD, STRUCTURE, PLUMBING, SKIN SPOT WELDS, ANTI-ICE OUTLET SCREEN, AND FASTENERS FOR SECURITY, CRACKS, AND GENERAL CONDITION.							Service	ATA:71
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PKG:9									
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
Y7110001 ^S	ENGINE INLET LIP AND DUCT - PERFORM VISUAL INSPECTION							Service	ATA:71
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PKG:9									
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
Y7110002 ^S	ENGINE STARTER/GENERATOR INLET AND EXHAUST DUCT AND SEALS - PERFORM VISUAL INSPECTION							Service	ATA:71
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PKG:9									
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
Y7110003 ^S	ENGINE ALTERNATOR EXHAUST DUCT AND SEALS - PERFORM VISUAL INSPECTION							Service	ATA:71
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PKG:9									
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
Y7120000 ^S	FORWARD ENGINE MOUNTS - PERFORM VISUAL INSPECTION							Service	ATA:71
	MOS	21-Aug-25	12						
	HRS	9809.8	300						
	AFL	7471							
PKG:3									
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty		
ATA 72 - ENGINE											
72-AS-720005		NO. 1 ENGINE - INSPECT MAJOR PERIODIC	PER MANUFACTURERS INSTRUCTIONS							Service	ATA:72
	MOS	06-Dec-17									
	HRS	7696.2	3000		(10696.2) 10770.3		747.2				
	ENC	5895									
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00											
72-AS-720005		NO. 2 ENGINE - INSPECT MAJOR PERIODIC	PER MANUFACTURERS INSTRUCTIONS							Service	ATA:72
	MOS	20-Jul-15									
	HRS	6622.3	3000		(9622.3) 10535.1		512				
	ENC	5602									
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00											
72-AS-720006 ^S		NO. 1 ENGINE - INSPECT COMB CHAMBER PLENUM CASE INSP	PER MANUFACTURERS INSTRUCTIONS							Service	ATA:72
	MOS	06-Dec-17									
	HRS	7696.2	3000								
	ENC	5895									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF											
72-AS-720006 ^S		NO. 2 ENGINE - INSPECT COMB CHAMBER PLENUM CASE INSP	PER MANUFACTURERS INSTRUCTIONS							Service	ATA:72
	MOS	20-Jul-15									
	HRS	6622.3	3000								
	ENC	5602									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF											
72-AS-720007		NO. 1 ENGINE - INSPECT COMPRESSOR ZONE	PER MANUFACTURERS INSTRUCTIONS							Service	ATA:72
	MOS	30-Oct-06									
	HRS	4857.2	6000		(10857.2) 10931.3		908.2				
	ENC	3730									
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 72 - ENGINE										
72-AS-720007		NO. 2 ENGINE - INSPECT COMPRESSOR ZONE PER MANUFACTURERS INSTRUCTIONS							Service	ATA:72
	MOS	28-Jun-06								
	HRS	3701.2	6000		(9701.2) 10614		590.9			
	ENC	2811								
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00										
<hr/>										
72-AS-720008 ^S		NO. 1 ENGINE - INSPECT AGB PER MANUFACTURERS INSTRUCTIONS							Service	ATA:72
	MOS	25-Oct-06								
	HRS	4857.2	6000							
	ENC	3730								
PROC. REF: LMM 72-60-02PROC. REF: LMM 72-60-02										
<hr/>										
72-AS-720008 ^S		NO. 2 ENGINE - INSPECT AGB PER MANUFACTURERS INSTRUCTIONS							Service	ATA:72
	MOS	05-Jun-06								
	HRS	3701.2	6000							
	ENC	3369								
PROC. REF: LMM 72-60-02PROC. REF: LMM 72-60-02										
<hr/>										
72-AS-720010		NO. 1 ENGINE - ANALYSIS OIL AND FILTER (BASELINE/SPECIAL REQUIREMENT) (SOAP)							Service	ATA:72
	MOS/MSC	05-Jan-00	A/R							
	HRS	0								
	ENC	0								
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00										
<hr/>										
72-AS-720010		NO. 2 ENGINE - ANALYSIS OIL AND FILTER (BASELINE/SPECIAL REQUIREMENT) (SOAP)							Service	ATA:72
	MOS/MSC	20-Jan-16	A/R							
	HRS	6674								
	ENC	5628								
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00										
<hr/>										
72-AS-720011		NO. 1 ENGINE - REPLACE FUEL FILTER ELEMENT (25-HR INITIAL)							Service	ATA:72
	MOS/MSC	05-Jan-00	A/R							
	HRS	0								
	ENC	0								
PROC. REF: LMM 73-21-02PROC. REF: LMM 73-21-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 72 - ENGINE										
72-AS-720011		NO. 2 ENGINE - REPLACE FUEL FILTER ELEMENT (25-HR INITIAL)						Service	ATA:72	
	MOS/MSC	15-Jan-00	A/R							
	HRS	0								
	ENC	0								
PROC. REF: LMM 73-21-02PROC. REF: LMM 73-21-02										
720110		NO. 1 ENGINE - ACCESSORY GEARBOX						Component	ATA:72	
PN:3060827-2	MOS/MSC	25-Oct-06	O/C							
SN:S986	HRS	4857.2								
	ENC	3730								
PROC. REF: LMM 72-60-02, LMM 72-60-02PROC. REF: LMM 72-60-02, LMM 72-60-02										
720110		NO. 2 ENGINE - ACCESSORY GEARBOX						Component	ATA:72	
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-60-02, LMM 72-60-02PROC. REF: LMM 72-60-02, LMM 72-60-02										
720244		NO. 1 ENGINE - NO. 6 CARBON SEAL ASSEMBLY						Component	ATA:72	
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
720244		NO. 2 ENGINE - NO. 6 CARBON SEAL ASSEMBLY						Component	ATA:72	
PN:3071383-2	MOS/MSC	20-Jul-15	O/C	TSN 0						
SN:13-150211-00260	HRS	6622.3		TSN 0						
	ENC	5602		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
720245		NO. 1 ENGINE - NO. 6 BEARING ASSEMBLY						Component	ATA:72	
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
720245 NO. 2 ENGINE - NO. 6 BEARING ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
722001 NO. 1 ENGINE - FAN INLET HOUSING ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
722001 NO. 2 ENGINE - FAN INLET HOUSING ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723002 NO. 1 ENGINE - NO. 3 CARBON SEAL ASSEMBLY									Component ATA:72
PN:3060150-3	MOS/MSC	25-Oct-06	O/C	TSN 0					
SN:061936801086	HRS	4857.2		TSN 0					
	ENC	3730		TSN 0					
PROC. REF: LMM 72-30-01, LMM 72-30-01PROC. REF: LMM 72-30-01, LMM 72-30-01									
723002 NO. 2 ENGINE - NO. 3 CARBON SEAL ASSEMBLY									Component ATA:72
PN:3060150-3	MOS/MSC	05-Jun-06	O/C	TSN 0					
SN:061936800093	HRS	3701.2		TSN 0					
	ENC	3369		TSN 0					
PROC. REF: LMM 72-30-01, LMM 72-30-01PROC. REF: LMM 72-30-01, LMM 72-30-01									
723010 ^S NO. 1 ENGINE - CHECK CARBON SEAL HEALTH									Service ATA:72
	MOS	22-Jun-23							
	HRS	9184.4	1600						
	ENC	7042							
PROC. REF: LMM 72-00-00, LMM 72-00-00PROC. REF: LMM 72-00-00, LMM 72-00-00									

PKG:0

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 72 - ENGINE

723010 ^S		NO. 2 ENGINE - CHECK CARBON SEAL HEALTH						Service	ATA:72
	MOS	18-Aug-22							
	HRS	8169.8	1600						
	ENC	6832							
PKG:0									
PROC. REF: LMM 72-00-00, LMM 72-00-00PROC. REF: LMM 72-00-00, LMM 72-00-00									

723011		NO. 1 ENGINE - NO. 4 CARBON SEAL RUNNER						Component	ATA:72
PN:3075639-2	MOS/MSC	25-Oct-06	O/C	TSN 0					
SN:062141803634	HRS	4857.2		TSN 0					
	ENC	3730		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

723011		NO. 2 ENGINE - NO. 4 CARBON SEAL RUNNER						Component	ATA:72
PN:3075639-2	MOS/MSC	05-Jun-06	O/C	TSN 0					
SN:052141802327	HRS	3701.2		TSN 0					
	ENC	3369		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

723012		NO. 1 ENGINE - NO. 4 CARBON SEAL ASSEMBLY						Component	ATA:72
PN:3074573-2	MOS/MSC	25-Oct-06	O/C	TSN 0					
SN:060515861210	HRS	4857.2		TSN 0					
	ENC	3730		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

723012		NO. 2 ENGINE - NO. 4 CARBON SEAL ASSEMBLY						Component	ATA:72
PN:3074573-2	MOS/MSC	05-Jun-06	O/C	TSN 0					
SN:060515847790	HRS	3701.2		TSN 0					
	ENC	3369		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

723013		NO. 1 ENGINE - NO. 5 CARBON SEAL RUNNER						Component	ATA:72
PN:3075633-2	MOS/MSC	25-Oct-06	O/C	TSN 0					
SN:062141802473	HRS	4857.2		TSN 0					
	ENC	3730		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 72 - ENGINE										
723013		NO. 2 ENGINE - NO. 5 CARBON SEAL RUNNER						Component	ATA:72	
PN:3075633-2	MOS/MSC	05-Jun-06	O/C	TSN 0						
SN:052141806990	HRS	3701.2		TSN 0						
	ENC	3369		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
<hr/>										
723014		NO. 1 ENGINE - NO. 5 CARBON SEAL ASSEMBLY						Component	ATA:72	
PN:3074574-2	MOS/MSC	25-Oct-06	O/C	TSN 0						
SN:060515859035	HRS	4857.2		TSN 0						
	ENC	3730		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
<hr/>										
723014		NO. 2 ENGINE - NO. 5 CARBON SEAL ASSEMBLY						Component	ATA:72	
PN:3074574-2	MOS/MSC	05-Jun-06	O/C	TSN 0						
SN:060515849488	HRS	3701.2		TSN 0						
	ENC	3369		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
<hr/>										
723081		NO. 1 ENGINE - ROTATING, AIR 2ND STAGE SEAL						Component	ATA:72	
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
<hr/>										
723081		NO. 2 ENGINE - ROTATING, AIR 2ND STAGE SEAL						Component	ATA:72	
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
<hr/>										
725007		NO. 1 ENGINE - HIGH PRESSURE TURBINE (HPT) NOZZLE ASSEMBLY						Component	ATA:72	
PN:3060840-3	MOS/MSC	25-Oct-06	A/R	TSN 0						
SN:UNKNOWN	HRS	4857.2		TSN 0						
WC#: 72.500	ENC	3730		TSN 0						
PROC. REF: LMM 72-50-07, LMM 72-50-07PROC. REF: LMM 72-50-07, LMM 72-50-07										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 72 - ENGINE										
725007		NO. 2 ENGINE - HIGH PRESSURE TURBINE (HPT) NOZZLE ASSEMBLY						Component	ATA:72	
PN:PN	MOS/MSC	15-Jan-00	A/R	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 72.500	ENC	0		TSN 0						
PROC. REF: LMM 72-50-07, LMM 72-50-07PROC. REF: LMM 72-50-07, LMM 72-50-07										
<hr/>										
725010		NO. 1 ENGINE - 1ST-STAGE LOW PRESSURE TURBINE (LPT) DISC						Component	ATA:72	
PN:3060129-7	MOS	25-Oct-06						LIFE LIMIT		
SN:00P21077	HRS	4857.2								
	ENC	3730	12000	TSN 3730	(12000) 12058		4442			
PROC. REF: LMM 72-50-04, LMM 72-50-04PROC. REF: LMM 72-50-04, LMM 72-50-04										
<hr/>										
725010		NO. 2 ENGINE - 1ST-STAGE LOW PRESSURE TURBINE (LPT) DISC						Component	ATA:72	
PN:3060625-1	MOS	15-Jan-00		TSN 0				LIFE LIMIT		
SN:990322904089	HRS	0		TSN 0						
	ENC	0	12000	TSN 0	(12000) 12162		4546			
PROC. REF: LMM 72-50-04, LMM 72-50-04PROC. REF: LMM 72-50-04, LMM 72-50-04										
<hr/>										
725020		NO. 1 ENGINE - 2ND-STAGE LOW PRESSURE TURBINE (LPT) DISC						Component	ATA:72	
PN:3060611-1	MOS	05-Jan-00		TSN 0				LIFE LIMIT		
SN:000322903502	HRS	0		TSN 0						
	ENC	0	12000	TSN 0	(12000) 12058		4442			
PROC. REF: LMM 72-50-04, LMM 72-50-04PROC. REF: LMM 72-50-04, LMM 72-50-04										
<hr/>										
725020		NO. 2 ENGINE - 2ND-STAGE LOW PRESSURE TURBINE (LPT) DISC						Component	ATA:72	
PN:3060611-1	MOS	15-Jan-00		TSN 0				LIFE LIMIT		
SN:000322903437	HRS	0		TSN 0						
	ENC	0	12000	TSN 0	(12000) 12162		4546			
PROC. REF: LMM 72-50-04, LMM 72-50-04PROC. REF: LMM 72-50-04, LMM 72-50-04										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 72 - ENGINE										
725030		NO. 1 ENGINE - 3RD-STAGE LOW PRESSURE TURBINE (LPT) DISC						Component	ATA:72	
PN:3060671-2	MOS	05-Jan-00		TSN 0				LIFE LIMIT		
SN:000322900149	HRS	0		TSN 0						
	ENC	0	12000	TSN 0	(12000) 12058		4442			
PROC. REF: LMM 72-50-04, LMM 72-50-04PROC. REF: LMM 72-50-04, LMM 72-50-04										
725030		NO. 2 ENGINE - 3RD-STAGE LOW PRESSURE TURBINE (LPT) DISC						Component	ATA:72	
PN:3060671-2	MOS	15-Jan-00		TSN 0				LIFE LIMIT		
SN:000322900152	HRS	0		TSN 0						
	ENC	0	12000	TSN 0	(12000) 12162		4546			
PROC. REF: LMM 72-50-04, LMM 72-50-04PROC. REF: LMM 72-50-04, LMM 72-50-04										
725040		NO. 1 ENGINE - HIGH PRESSURE TURBINE (HPT) DISC						Component	ATA:72	
PN:3060555-5	MOS	25-Oct-06						LIFE LIMIT		
SN:061217200024	HRS	4857.2								
	ENC	3730	10000	TSN 0	(13730) 13788		6172			
PROC. REF: LMM 72-50-07, LMM 72-50-07PROC. REF: LMM 72-50-07, LMM 72-50-07										
725040		NO. 2 ENGINE - HIGH PRESSURE TURBINE (HPT) DISC						Component	ATA:72	
PN:3060841-1	MOS	20-Jul-15						LIFE LIMIT		
SN:041217200360	HRS	6622.3		TSN 4043.4						
	ENC	5602	10000	TSN 3645	(11957) 12119		4503			
PROC. REF: LMM 72-50-07, LMM 72-50-07PROC. REF: LMM 72-50-07, LMM 72-50-07										
725045		NO. 1 ENGINE - HIGH PRESSURE TURBINE (HPT) ASSY						Component	ATA:72	
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
725045		NO. 2 ENGINE - HIGH PRESSURE TURBINE (HPT) ASSY						Component	ATA:72	
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 72 - ENGINE

725050		NO. 1 ENGINE - FAN DISC							Component	ATA:72
PN:3060287-2	MOS	05-Jan-00		TSN 0				LIFE LIMIT		
SN:030322901250	HRS	0		TSN 0						
	ENC	0	20000	TSN 0	(20000) 20058		12442			

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

725050		NO. 2 ENGINE - FAN DISC							Component	ATA:72
PN:3060287-2	MOS	15-Jan-00		TSN 0				LIFE LIMIT		
SN:010322905809	HRS	0		TSN 0						
	ENC	0	20000	TSN 0	(20000) 20162		12546			

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

725060		NO. 1 ENGINE - 1ST-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC							Component	ATA:72
PN:3060372-1	MOS	05-Jan-00		TSN 0				LIFE LIMIT		
SN:000316002316	HRS	0		TSN 0						
	ENC	0	10000	TSN 0	(10000) 10058		2442			

PROC. REF: LMM 72-30-04PROC. REF: LMM 72-30-04

725060		NO. 2 ENGINE - 1ST-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC							Component	ATA:72
PN:3060372-1	MOS	15-Jan-00		TSN 0				LIFE LIMIT		
SN:000316002319	HRS	0		TSN 0						
	ENC	0	10000	TSN 0	(10000) 10162		2546			

PROC. REF: LMM 72-30-04PROC. REF: LMM 72-30-04

725070		NO. 1 ENGINE - 2ND-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC							Component	ATA:72
PN:3060608-3	MOS	25-Oct-06						LIFE LIMIT		
SN:000322903502	HRS	4857.2								
	ENC	3730	10000	TSN 3730	(10000) 10058		2442			

PROC. REF: LMM 72-30-04PROC. REF: LMM 72-30-04

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
725070 NO. 2 ENGINE - 2ND-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC Component ATA:72									
PN:3060373-1	MOS	15-Jan-00		TSN 0				LIFE LIMIT	
SN:000316001852	HRS	0		TSN 0					
	ENC	0	10000	TSN 0	(10000) 10162		2546		
PROC. REF: LMM 72-30-04PROC. REF: LMM 72-30-04									
725071 NO. 1 ENGINE - COMBUSTION LINER Component ATA:72									
PN:3060766-1	MOS/MSC	28-Nov-17	O/C	TSO 0					
SN:08P16345	HRS	7696.2		TSO 0					
	ENC	5895		TSO 0					
PROC. REF: LMM 72-40-03, LMM 72-40-03PROC. REF: LMM 72-40-03, LMM 72-40-03									
725071 NO. 2 ENGINE - COMBUSTION LINER Component ATA:72									
PN:3060766-1	MOS/MSC	20-Jul-15	O/C	TSO 0					
SN:06P00417	HRS	6622.3		TSO 0					
	ENC	5602		TSO 0					
PROC. REF: LMM 72-40-03, LMM 72-40-03PROC. REF: LMM 72-40-03, LMM 72-40-03									
725080 NO. 1 ENGINE - 3RD-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC Component ATA:72									
PN:3060374-1	MOS	05-Jan-00		TSN 0				LIFE LIMIT	
SN:000316002539	HRS	0		TSN 0					
	ENC	0	10000	TSN 0	(10000) 10058		2442		
PROC. REF: LMM 72-30-04PROC. REF: LMM 72-30-04									
725080 NO. 2 ENGINE - 3RD-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC Component ATA:72									
PN:3072417-12	MOS	05-Jun-06		TSR 0				LIFE LIMIT	
SN:000316002937	HRS	3701.2		TSR 0					
	ENC	3369	10000	TSN 3369, TSR 0	(10000) 10162		2546		
PROC. REF: LMM 72-30-04PROC. REF: LMM 72-30-04									
725081 NO. 1 ENGINE - OUTER TRANSITION LINER Component ATA:72									
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 72 - ENGINE

PROC. REF: LMM 72-40-03, LMM 72-40-03PROC. REF: LMM 72-40-03, LMM 72-40-03

725081 NO. 2 ENGINE - OUTER TRANSITION LINER Component ATA:72									
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					

PROC. REF: LMM 72-40-03, LMM 72-40-03PROC. REF: LMM 72-40-03, LMM 72-40-03

725090 NO. 1 ENGINE - 4TH-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC Component ATA:72									
PN:3075326-5	MOS	05-Jan-00		TSN 0				LIFE LIMIT	
SN:001365107764	HRS	0		TSN 0					
	ENC	0	20000	TSN 0	(20000) 20058		12442		

PROC. REF: LMM 72-30-04PROC. REF: LMM 72-30-04

725090 NO. 2 ENGINE - 4TH-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC Component ATA:72									
PN:3075351-12	MOS	05-Jun-06						LIFE LIMIT	
SN:050350107807	HRS	3701.2							
	ENC	3369	20000	TSN 0	(23369) 23531		15915		

PROC. REF: LMM 72-30-04PROC. REF: LMM 72-30-04

725110 NO. 1 ENGINE - LOW PRESSURE COMPRESSOR TIE ROD Component ATA:72									
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					

PROC. REF: LMM 72-30-10, LMM 72-30-10PROC. REF: LMM 72-30-10, LMM 72-30-10

725110 NO. 2 ENGINE - LOW PRESSURE COMPRESSOR TIE ROD Component ATA:72									
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					

PROC. REF: LMM 72-30-10, LMM 72-30-10PROC. REF: LMM 72-30-10, LMM 72-30-10

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 72 - ENGINE										
725120		NO. 1 ENGINE - HIGH PRESSURE COMPRESSOR ROTOR IMPELLER						Component	ATA:72	
PN:3060371-1	MOS	05-Jan-00		TSN 0				LIFE LIMIT		
SN:005332200378	HRS	0		TSN 0						
	ENC	0	8000	TSN 0	(8000) 8058		442			
PROC. REF: LMM 72-50-06, LMM 72-50-06PROC. REF: LMM 72-50-06, LMM 72-50-06										
725120		NO. 2 ENGINE - HIGH PRESSURE COMPRESSOR ROTOR IMPELLER						Component	ATA:72	
PN:3060371-1	MOS	05-Jun-06						LIFE LIMIT		
SN:060322902406	HRS	3701.2								
	ENC	3369	8000	TSN 0	(11369) 11531		3915			
PROC. REF: LMM 72-50-06, LMM 72-50-06PROC. REF: LMM 72-50-06, LMM 72-50-06										
725130		NO. 1 ENGINE - FAN SPINNER						Component	ATA:72	
PN:3060156-2	MOS	05-Jan-00		TSN 0				LIFE LIMIT		
SN:002428000312	HRS	0		TSN 0						
	ENC	0	20000	TSN 0	(20000) 20058		12442			
PROC. REF: LMM 72-70-01, LMM 72-70-01PROC. REF: LMM 72-70-01, LMM 72-70-01										
725130		NO. 2 ENGINE - FAN SPINNER						Component	ATA:72	
PN:3060156-2	MOS	15-Jan-00		TSN 0				LIFE LIMIT		
SN:002428000311	HRS	0		TSN 0						
	ENC	0	20000	TSN 0	(20000) 20162		12546			
PROC. REF: LMM 72-70-01, LMM 72-70-01PROC. REF: LMM 72-70-01, LMM 72-70-01										
725140		NO. 1 ENGINE - FAN DRIVE SHAFT						Component	ATA:72	
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 72 - ENGINE										
725140		NO. 2 ENGINE - FAN DRIVE SHAFT						Component	ATA:72	
PN:3067021-1	MOS/MSC	23-May-07	O/C							
SN:970339000246	HRS	4564.4								
	ENC	4010								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
725160		NO. 1 ENGINE - FORWARD ROTOR HIGH PRESSURE SEAL						Component	ATA:72	
PN:3060698-1	MOS	28-Nov-17		TSN 0				LIFE LIMIT		
SN:16-162246-03040	HRS	7696.2		TSN 0						
	ENC	5895	7000	TSN 0	(12895) 12953		5337			
PROC. REF: LMM 72-70-03, LMM 72-70-03PROC. REF: LMM 72-70-03, LMM 72-70-03										
725160		NO. 2 ENGINE - FORWARD ROTOR HIGH PRESSURE SEAL						Component	ATA:72	
PN:3060698-1	MOS	20-Jul-15		TSN 0				LIFE LIMIT		
SN:14-162246-04706	HRS	6622.3		TSN 0						
	ENC	5602	7000	TSN 0	(12602) 12764		5148			
PROC. REF: LMM 72-70-03, LMM 72-70-03PROC. REF: LMM 72-70-03, LMM 72-70-03										
725170		NO. 1 ENGINE - HIGH PRESSURE SHOULDERED SHAFT						Component	ATA:72	
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
725170		NO. 2 ENGINE - HIGH PRESSURE SHOULDERED SHAFT						Component	ATA:72	
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
725180		NO. 1 ENGINE - COMBUSTION PLENUM CASE						Component	ATA:72	
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-40-04, LMM 72-40-04PROC. REF: LMM 72-40-04, LMM 72-40-04										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
725180 NO. 2 ENGINE - COMBUSTION PLENUM CASE									Component ATA:72
PN:3060534-4	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:00P24979	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-40-04, LMM 72-40-04PROC. REF: LMM 72-40-04, LMM 72-40-04									
725210 NO. 1 ENGINE - HIGH PRESSURE TURBINE FORWARD SEAL PLATE									Component ATA:72
PN:3060514-1	MOS	05-Jan-00		TSN 0				LIFE LIMIT	
SN:000322905164	HRS	0		TSN 0					
	ENC	0	10000	TSN 0	(10000) 10058		2442		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725210 NO. 2 ENGINE - HIGH PRESSURE TURBINE FORWARD SEAL PLATE									Component ATA:72
PN:3060514-1	MOS	15-Jan-00		TSN 0				LIFE LIMIT	
SN:000322905162	HRS	0		TSN 0					
	ENC	0	10000	TSN 0	(10000) 10162		2546		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725220 NO. 1 ENGINE - TURBINE INTERSTAGE TRANSITION DUCT									Component ATA:72
PN:3060694-6	MOS/MSC	25-Oct-06	O/C						
SN:97P23086	HRS	4857.2							
	ENC	3730							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725220 NO. 2 ENGINE - TURBINE INTERSTAGE TRANSITION DUCT									Component ATA:72
PN:3060694-6	MOS/MSC	20-Jul-15	O/C	TSO 0					
SN:02P01906	HRS	6622.3		TSO 0					
	ENC	5602		TSO 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725230 NO. 1 ENGINE - LOW PRESSURE TURBINE (LPT) 1 NOZZLE SEAL SUPPORT									Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-50-04, LMM 72-50-04PROC. REF: LMM 72-50-04, LMM 72-50-04									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
725230 NO. 2 ENGINE - LOW PRESSURE TURBINE (LPT) 1 NOZZLE SEAL SUPPORT									Component ATA:72
PN:3060693-1	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:00P28158	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-50-04, LMM 72-50-04PROC. REF: LMM 72-50-04, LMM 72-50-04									
725240 NO. 1 ENGINE - LOW PRESSURE TURBINE (LPT) 1 NOZZLE ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-50-04, LMM 72-50-04PROC. REF: LMM 72-50-04, LMM 72-50-04									
725240 NO. 2 ENGINE - LOW PRESSURE TURBINE (LPT) 1 NOZZLE ASSEMBLY									Component ATA:72
PN:3060666-7	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:00P29069	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-50-04, LMM 72-50-04PROC. REF: LMM 72-50-04, LMM 72-50-04									
725250 NO. 1 ENGINE - FORWARD SHAFT HIGH PRESSURE TURBINE (HPT) COUPLING									Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725250 NO. 2 ENGINE - FORWARD SHAFT HIGH PRESSURE TURBINE (HPT) COUPLING									Component ATA:72
PN:3060502-2	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:00P26421	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725260 NO. 1 ENGINE - AFT HIGH PRESSURE TURBINE (HPT) SHAFT COUPLING									Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 72 - ENGINE										
725260 NO. 2 ENGINE - AFT HIGH PRESSURE TURBINE (HPT) SHAFT COUPLING									Component	ATA:72
PN:3060599-2	MOS/MSC	15-Jan-00	O/C	TSN 0						
SN:00P28573	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
725270 NO. 1 ENGINE - NOZZLE LOW PRESSURE TURBINE (LPT) (A5) SEAL									Component	ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
725270 NO. 2 ENGINE - NOZZLE LOW PRESSURE TURBINE (LPT) (A5) SEAL									Component	ATA:72
PN:3073765-12	MOS/MSC	15-Jan-00	O/C	TSN 0						
SN:00P29032	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
726005 NO. 1 ENGINE - TRANSFER GEARBOX ASSEMBLY									Component	ATA:72
PN:3070093-16	MOS/MSC	25-Oct-06	O/C							
SN:P10020	HRS	4857.2								
	ENC	3730								
PROC. REF: LMM 72-60-03, LMM 72-60-03PROC. REF: LMM 72-60-03, LMM 72-60-03										
726005 NO. 2 ENGINE - TRANSFER GEARBOX ASSEMBLY									Component	ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-60-03, LMM 72-60-03PROC. REF: LMM 72-60-03, LMM 72-60-03										
726010 NO. 1 ENGINE - FORWARD OIL PUMP SPUR ANNULAR BALL BEARING									Component	ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
726010 NO. 2 ENGINE - FORWARD OIL PUMP SPUR ANNULAR BALL BEARING									Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									
726011 NO. 1 ENGINE - AFT OIL PUMP SPUR ANNULAR BALL BEARING									Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
726011 NO. 2 ENGINE - AFT OIL PUMP SPUR ANNULAR BALL BEARING									Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
726012 NO. 1 ENGINE - FORWARD ALTERNATOR SPU ANNULAR BALL BEARING									Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
726012 NO. 2 ENGINE - FORWARD ALTERNATOR SPU ANNULAR BALL BEARING									Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
726013 NO. 1 ENGINE - AFT ALTERNATOR SPU ANNULAR BEARING									Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
726013 NO. 2 ENGINE - AFT ALTERNATOR SPU ANNULAR BEARING									Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
726014 NO. 1 ENGINE - FORWARD AIR-OIL SEPARATOR ANNULAR BALL BEARING									Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
726014 NO. 2 ENGINE - FORWARD AIR-OIL SEPARATOR ANNULAR BALL BEARING									Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
726015 NO. 1 ENGINE - AFT AIR-OIL SEPARATOR ANNULAR BALL BEARING									Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
726015 NO. 2 ENGINE - AFT AIR-OIL SEPARATOR ANNULAR BALL BEARING									Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
726016 NO. 1 ENGINE - FORWARD STARTER/GENERATOR SPU ANNULAR BALL BEARING									Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
726016 NO. 2 ENGINE - FORWARD STARTER/GENERATOR SPU ANNULAR BALL BEARING									Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
726017 NO. 1 ENGINE - AFT STARTER/GENERATOR SPU ANNULAR BEARING									Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
726017 NO. 2 ENGINE - AFT STARTER/GENERATOR SPU ANNULAR BEARING									Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
727001 NO. 1 ENGINE - BYPASS FAN STATOR									Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-70-04, LMM 72-70-04PROC. REF: LMM 72-70-04, LMM 72-70-04									
727001 NO. 2 ENGINE - BYPASS FAN STATOR									Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-70-04, LMM 72-70-04PROC. REF: LMM 72-70-04, LMM 72-70-04									
727005 NO. 1 ENGINE - UPPER FAN DUCT ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-70-05, LMM 72-70-05PROC. REF: LMM 72-70-05, LMM 72-70-05									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
727005 NO. 2 ENGINE - UPPER FAN DUCT ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-70-05, LMM 72-70-05PROC. REF: LMM 72-70-05, LMM 72-70-05									
727006 NO. 1 ENGINE - LOWER FAN DUCT ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-70-05, LMM 72-70-05PROC. REF: LMM 72-70-05, LMM 72-70-05									
727006 NO. 2 ENGINE - LOWER FAN DUCT ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-70-05, LMM 72-70-05PROC. REF: LMM 72-70-05, LMM 72-70-05									
727010 ^S NO. 1 ENGINE - INSPECT BYPASS STATOR VANE ASSEMBLY.									Service ATA:72
	MOS	27-Oct-25							
	HRS	9832.1	1200						
	ENC	7480							
PROC. REF: LMM 72-70-04, LMM 72-70-04, LMM 72-70-04PKG:0									
727010 ^S NO. 2 ENGINE - INSPECT BYPASS STATOR VANE ASSEMBLY.									Service ATA:72
	MOS	27-Oct-25							
	HRS	8993.4	1200						
	ENC	7376							
PROC. REF: LMM 72-70-04, LMM 72-70-04, LMM 72-70-04PKG:0									
727101 NO. 1 ENGINE - NO. 1 CARBON SEAL ASSEMBLY									Component ATA:72
PN:3060457-1	MOS/MSC	28-Nov-17	O/C	TSN 0					
SN:17-152826-59105	HRS	7696.2		TSN 0					
	ENC	5895		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
727101 NO. 2 ENGINE - NO. 1 CARBON SEAL ASSEMBLY									Component ATA:72
PN:3060457-1	MOS/MSC	20-Jul-15	O/C	TSN 0					
SN:14-152826-73404	HRS	6622.3		TSN 0					
	ENC	5602		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
727102 NO. 1 ENGINE - NO. 1 CARBON SEAL RUNNER									Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
727102 NO. 2 ENGINE - NO. 1 CARBON SEAL RUNNER									Component ATA:72
PN:3075657-1	MOS/MSC	20-Jul-15	O/C	TSN 0					
SN:14-162397-04157	HRS	6622.3		TSN 0					
	ENC	5602		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
727103 NO. 1 ENGINE - NO. 1 BEARING ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
727103 NO. 2 ENGINE - NO. 1 BEARING ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
727105 NO. 1 ENGINE - HELICAL RING GEAR									Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
727105 NO. 2 ENGINE - HELICAL RING GEAR									Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
<hr/>									
727203 NO. 1 ENGINE - NO. 3 BALL BEARING									Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-30-01, LMM 72-30-01PROC. REF: LMM 72-30-01, LMM 72-30-01									
<hr/>									
727203 NO. 2 ENGINE - NO. 3 BALL BEARING									Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-30-01, LMM 72-30-01PROC. REF: LMM 72-30-01, LMM 72-30-01									
<hr/>									
727210 NO. 1 ENGINE - PLANET HOUSING ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-72-03, LMM 72-72-03PROC. REF: LMM 72-72-03, LMM 72-72-03									
<hr/>									
727210 NO. 2 ENGINE - PLANET HOUSING ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-72-03, LMM 72-72-03PROC. REF: LMM 72-72-03, LMM 72-72-03									
<hr/>									
727210-1 NO. 1 ENGINE - NO. 1 PLANET GEAR ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-72-03, LMM 72-72-03PROC. REF: LMM 72-72-03, LMM 72-72-03									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 72 - ENGINE										
727210-1		NO. 2 ENGINE - NO. 1 PLANET GEAR ASSEMBLY						Component	ATA:72	
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-72-03, LMM 72-72-03PROC. REF: LMM 72-72-03, LMM 72-72-03										
727210-2		NO. 1 ENGINE - NO. 2 PLANET GEAR ASSEMBLY						Component	ATA:72	
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-72-03, LMM 72-72-03PROC. REF: LMM 72-72-03, LMM 72-72-03										
727210-2		NO. 2 ENGINE - NO. 2 PLANET GEAR ASSEMBLY						Component	ATA:72	
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-72-03, LMM 72-72-03PROC. REF: LMM 72-72-03, LMM 72-72-03										
727210-3		NO. 1 ENGINE - NO. 3 PLANET GEAR ASSEMBLY						Component	ATA:72	
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-72-03, LMM 72-72-03PROC. REF: LMM 72-72-03, LMM 72-72-03										
727210-3		NO. 2 ENGINE - NO. 3 PLANET GEAR ASSEMBLY						Component	ATA:72	
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-72-03, LMM 72-72-03PROC. REF: LMM 72-72-03, LMM 72-72-03										
727210-4		NO. 1 ENGINE - NO. 4 PLANET GEAR ASSEMBLY						Component	ATA:72	
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-72-03, LMM 72-72-03PROC. REF: LMM 72-72-03, LMM 72-72-03										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 72 - ENGINE										
727210-4		NO. 2 ENGINE - NO. 4 PLANET GEAR ASSEMBLY						Component	ATA:72	
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: LMM 72-72-03, LMM 72-72-03PROC. REF: LMM 72-72-03, LMM 72-72-03										
ATA 72 - ENGINE										
727210-5		NO. 1 ENGINE - NO. 5 PLANET GEAR ASSEMBLY						Component	ATA:72	
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: LMM 72-72-03, LMM 72-72-03PROC. REF: LMM 72-72-03, LMM 72-72-03										
ATA 72 - ENGINE										
727210-5		NO. 2 ENGINE - NO. 5 PLANET GEAR ASSEMBLY						Component	ATA:72	
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: LMM 72-72-03, LMM 72-72-03PROC. REF: LMM 72-72-03, LMM 72-72-03										
ATA 73 - ENGINE FUEL AND CONTROL										
730110		NO. 1 ENGINE - FUEL CONTROL UNIT						Component	ATA:73	
PN:3070800-37	MOS/MSC	25-Oct-06	O/C	TSN 0						
SN:16529	HRS	4857.2	TSN 0							
	ENC	3730	TSN 0							
PROC. REF: LMM 73-20-01, LMM 73-20-01PROC. REF: LMM 73-20-01, LMM 73-20-01										
ATA 73 - ENGINE FUEL AND CONTROL										
730110		NO. 2 ENGINE - FUEL CONTROL UNIT						Component	ATA:73	
PN:3070800-47	MOS/MSC	27-Feb-23	O/C	TSO 0						
SN:19179	HRS	8273.9	TSO 0							
	ENC	6885	TSO 0							
PROC. REF: LMM 73-20-01, LMM 73-20-01PROC. REF: LMM 73-20-01, LMM 73-20-01										
ATA 73 - ENGINE FUEL AND CONTROL										
730120 ^S		NO. 1 ENGINE - REPLACE FUEL FILTER ELEMENT						Service	ATA:73	
	MOS	27-Oct-25	TSN 0							
	HRS	9832.1	600	TSN 0						
	ENC	7480	TSN 0							
PROC. REF: LMM 73-21-02, LMM 73-21-02PROC. REF: LMM 73-21-02, LMM 73-21-02										

PKG:0

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 73 - ENGINE FUEL AND CONTROL

730120^S		NO. 2 ENGINE - REPLACE FUEL FILTER ELEMENT						Service	ATA:73
	MOS	27-Oct-25							
	HRS	8993.4	600						
	ENC	7376							
PKG:0									
PROC. REF: LMM 73-21-02, LMM 73-21-02PROC. REF: LMM 73-21-02, LMM 73-21-02									

730130		NO. 1 ENGINE - ENGINE FUEL PUMP ASSEMBLY						Component	ATA:73
PN:3060760-3	MOS/MSC	25-Oct-06	O/C						
SN:0942	HRS	4857.2							
	ENC	3730							
PROC. REF: LMM 73-20-01, LMM 73-20-01, LMM 73-20-01, LMM 73-20-01PROC. REF: LMM 73-20-01, LMM 73-20-01, LMM 73-20-01, LMM 73-20-01									

730130		NO. 2 ENGINE - ENGINE FUEL PUMP ASSEMBLY						Component	ATA:73
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 73-20-01, LMM 73-20-01, LMM 73-20-01, LMM 73-20-01PROC. REF: LMM 73-20-01, LMM 73-20-01, LMM 73-20-01, LMM 73-20-01									

731001		NO. 1 ENGINE - MOTIVE FLOW FUEL PUMP ASSEMBLY						Component	ATA:73
PN:3060759-1	MOS/MSC	25-Oct-06	O/C						
SN:0457	HRS	4857.2							
	ENC	3730							
PROC. REF: LMM 73-21-02PROC. REF: LMM 73-21-02									

731001		NO. 2 ENGINE - MOTIVE FLOW FUEL PUMP ASSEMBLY						Component	ATA:73
PN:3060759-1	MOS/MSC	18-Dec-13	O/C	TSO 0					
SN:0671	HRS	6312.5		TSO 0					
	ENC	5360		TSO 0					
PROC. REF: LMM 73-21-02PROC. REF: LMM 73-21-02									

731005-1		NO. 1 ENGINE - NO. 1 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73
PN:3060540-2	MOS/MSC	25-Oct-06	O/C						
SN:97-01371-430	HRS	4857.2							
	ENC	3730							
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 73 - ENGINE FUEL AND CONTROL										
731005-1		NO. 2 ENGINE - NO. 1 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73	
PN:3060540-2	MOS/MSC	20-Jul-15	O/C	TSO 0						
SN:020137100424	HRS	6622.3		TSO 0						
	ENC	5602		TSO 0						
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01										
731005-10		NO. 1 ENGINE - NO. 10 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73	
PN:3060540-2	MOS/MSC	25-Oct-06	O/C							
SN:97-01371-1025	HRS	4857.2								
	ENC	3730								
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01										
731005-10		NO. 2 ENGINE - NO. 10 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73	
PN:3060540-2	MOS/MSC	20-Jul-15	O/C	TSO 0						
SN:052923401375	HRS	6622.3		TSO 0						
	ENC	5602		TSO 0						
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01										
731005-11		NO. 1 ENGINE - NO. 11 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73	
PN:3060540-2	MOS/MSC	25-Oct-06	O/C							
SN:990137101056	HRS	4857.2								
	ENC	3730								
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01										
731005-11		NO. 2 ENGINE - NO. 11 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73	
PN:3060540-2	MOS/MSC	20-Jul-15	O/C	TSO 0						
SN:010137103143	HRS	6622.3		TSO 0						
	ENC	5602		TSO 0						
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01										
731005-12		NO. 1 ENGINE - NO. 12 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73	
PN:3060540-2	MOS/MSC	25-Oct-06	O/C							
SN:97-01371-400	HRS	4857.2								
	ENC	3730								
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 73 - ENGINE FUEL AND CONTROL										
731005-12		NO. 2 ENGINE - NO. 12 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73	
PN:3060540-2	MOS/MSC	20-Jul-15	O/C	TSO 0						
SN:052923401374	HRS	6622.3		TSO 0						
	ENC	5602		TSO 0						
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01										
731005-2		NO. 1 ENGINE - NO. 2 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73	
PN:3060540-2	MOS/MSC	25-Oct-06	O/C							
SN:010137102472	HRS	4857.2								
	ENC	3730								
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01										
731005-2		NO. 2 ENGINE - NO. 2 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73	
PN:3060540-2	MOS/MSC	20-Jul-15	O/C	TSO 0						
SN:052923401378	HRS	6622.3		TSO 0						
	ENC	5602		TSO 0						
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01										
731005-3		NO. 1 ENGINE - NO. 3 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73	
PN:3060540-2	MOS/MSC	25-Oct-06	O/C							
SN:97-01371-398	HRS	4857.2								
	ENC	3730								
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01										
731005-3		NO. 2 ENGINE - NO. 3 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73	
PN:3060540-2	MOS/MSC	20-Jul-15	O/C	TSO 0						
SN:032923401169	HRS	6622.3		TSO 0						
	ENC	5602		TSO 0						
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01										
731005-4		NO. 1 ENGINE - NO. 4 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73	
PN:3060540-2	MOS/MSC	25-Oct-06	O/C							
SN:97-01371-572	HRS	4857.2								
	ENC	3730								
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 73 - ENGINE FUEL AND CONTROL										
731005-4		NO. 2 ENGINE - NO. 4 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73	
PN:3060540-2	MOS/MSC	20-Jul-15	O/C	TSO 0						
SN:032923401065	HRS	6622.3		TSO 0						
	ENC	5602		TSO 0						
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01										
731005-5		NO. 1 ENGINE - NO. 5 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73	
PN:3060540-2	MOS/MSC	25-Oct-06	O/C	TSO 0						
SN:990137101033	HRS	4857.2		TSO 0						
	ENC	3730		TSO 0						
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01										
731005-5		NO. 2 ENGINE - NO. 5 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73	
PN:3060540-2	MOS/MSC	20-Jul-15	O/C	TSO 0						
SN:072923400480	HRS	6622.3		TSO 0						
	ENC	5602		TSO 0						
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01										
731005-6		NO. 1 ENGINE - NO. 6 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73	
PN:3060540-2	MOS/MSC	25-Oct-06	O/C	TSO 0						
SN:990137101059	HRS	4857.2		TSO 0						
	ENC	3730		TSO 0						
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01										
731005-6		NO. 2 ENGINE - NO. 6 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73	
PN:3060540-2	MOS/MSC	20-Jul-15	O/C	TSO 0						
SN:052923400974	HRS	6622.3		TSO 0						
	ENC	5602		TSO 0						
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01										
731005-7		NO. 1 ENGINE - NO. 7 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73	
PN:3060540-2	MOS/MSC	25-Oct-06	O/C	TSO 0						
SN:97-01371-542	HRS	4857.2		TSO 0						
	ENC	3730		TSO 0						
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 73 - ENGINE FUEL AND CONTROL										
731005-7		NO. 2 ENGINE - NO. 7 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73	
PN:3060540-2	MOS/MSC	20-Jul-15	O/C	TSO 0						
SN:052623401379	HRS	6622.3		TSO 0						
	ENC	5602		TSO 0						
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01										
731005-8		NO. 1 ENGINE - NO. 8 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73	
PN:3060540-2	MOS/MSC	25-Oct-06	O/C							
SN:022923401439	HRS	4857.2								
	ENC	3730								
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01										
731005-8		NO. 2 ENGINE - NO. 8 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73	
PN:3060540-2	MOS/MSC	20-Jul-15	O/C	TSO 0						
SN:052923401376	HRS	6622.3		TSO 0						
	ENC	5602		TSO 0						
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01										
731005-9		NO. 1 ENGINE - NO. 9 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73	
PN:3060540-2	MOS/MSC	25-Oct-06	O/C							
SN:97-01371-562	HRS	4857.2								
	ENC	3730								
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01										
731005-9		NO. 2 ENGINE - NO. 9 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73	
PN:3060540-2	MOS/MSC	20-Jul-15	O/C	TSO 0						
SN:000137102869	HRS	6622.3		TSO 0						
	ENC	5602		TSO 0						
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01										
731015		NO. 1 ENGINE - FUEL PUMP PRESSURE DIFFERENTIAL INDICATOR						Component	ATA:73	
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 73-20-01, LMM 73-20-01PROC. REF: LMM 73-20-01, LMM 73-20-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 73 - ENGINE FUEL AND CONTROL									
731015 NO. 2 ENGINE - FUEL PUMP PRESSURE DIFFERENTIAL INDICATOR									Component ATA:73
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 73-20-01, LMM 73-20-01PROC. REF: LMM 73-20-01, LMM 73-20-01									
731110 NO. 1 ENGINE - PRESSURE LIMITER (PCD) VALVE									Component ATA:73
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 73-20-01, LMM 73-20-01PROC. REF: LMM 73-20-01, LMM 73-20-01									
731110 NO. 2 ENGINE - PRESSURE LIMITER (PCD) VALVE									Component ATA:73
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 73-20-01, LMM 73-20-01PROC. REF: LMM 73-20-01, LMM 73-20-01									
731120 NO. 1 ENGINE - FUEL FLOW DIVIDER/DRAIN VALVE									Component ATA:73
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
731120 NO. 2 ENGINE - FUEL FLOW DIVIDER/DRAIN VALVE									Component ATA:73
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
732102 NO. 1 ENGINE - RELIEF VALVE									Component ATA:73
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 73 - ENGINE FUEL AND CONTROL									
732102 NO. 2 ENGINE - RELIEF VALVE									Component ATA:73
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
732120^S NO. 1 ENGINE - INSPECT MOTIVE FLOW FUEL PUMP DRIVE SPLINE									Service ATA:73
	MOS	27-Oct-25							
	HRS	9832.1	600						
	ENC	7480							
PROC. REF: LMM 72-00-00, LMM 73-21-04PROC. REF: LMM 72-00-00, LMM 73-21-04									
732120^S NO. 2 ENGINE - INSPECT MOTIVE FLOW FUEL PUMP DRIVE SPLINE									Service ATA:73
	MOS	27-Oct-25							
	HRS	8993.4	600						
	ENC	7376							
PROC. REF: LMM 72-00-00, LMM 73-21-04PROC. REF: LMM 72-00-00, LMM 73-21-04									
733001 NO. 1 ENGINE FUEL FLOW TRANSDUCER									Component ATA:73
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 73-31-01PROC. REF: AMM 73-31-01									
733002 NO. 2 ENGINE FUEL FLOW TRANSDUCER									Component ATA:73
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 73-31-01PROC. REF: AMM 73-31-01									
733013 DUAL FUEL FLOW CONVERTER (DFFC)									Component ATA:73
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 73-31-02PROC. REF: AMM 73-31-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 73 - ENGINE FUEL AND CONTROL

733031 LEFT ENGINE FUEL TEMPERATURE BULB						Component	ATA:73
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0			
SN:UNKNOWN	HRS	0		TSN 0			
	AFL	0		TSN 0			
PROC. REF: AMM 73-31-03PROC. REF: AMM 73-31-03							

733032 RIGHT ENGINE FUEL TEMPERATURE BULB						Component	ATA:73
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0			
SN:UNKNOWN	HRS	0		TSN 0			
	AFL	0		TSN 0			
PROC. REF: AMM 73-31-03PROC. REF: AMM 73-31-03							

ATA 74 - IGNITION

740110 NO. 1 ENGINE - IGNITION UNIT						Component	ATA:74
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0			
SN:UNKNOWN	HRS	0		TSN 0			
	ENC	0		TSN 0			
PROC. REF: LMM 74-00-01, LMM 74-00-01PROC. REF: LMM 74-00-01, LMM 74-00-01							

740110 NO. 2 ENGINE - IGNITION UNIT						Component	ATA:74
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0			
SN:UNKNOWN	HRS	0		TSN 0			
	ENC	0		TSN 0			
PROC. REF: LMM 74-00-01, LMM 74-00-01PROC. REF: LMM 74-00-01, LMM 74-00-01							

740130 NO. 1 ENGINE - 5 O'CLOCK IGNITER (#1 POSITION) PLUG						Component	ATA:74
PN:3074541-4	MOS/MSC	28-Nov-17	O/C	TSN 0			
SN:UNKNOWN	HRS	7696.2		TSN 0			
	ENC	5895		TSN 0			
PROC. REF: LMM 74-00-01, LMM 74-00-01PROC. REF: LMM 74-00-01, LMM 74-00-01							

740130 NO. 2 ENGINE - 5 O'CLOCK IGNITER (#1 POSITION) PLUG						Component	ATA:74
PN:3074541-4	MOS/MSC	18-Aug-22	O/C	TSN 0			
SN:UNKNOWN	HRS	8169.8		TSN 0			
	ENC	6832		TSN 0			
PROC. REF: LMM 74-00-01, LMM 74-00-01PROC. REF: LMM 74-00-01, LMM 74-00-01							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 74 - IGNITION										
740140 ^S			NO. 1 ENGINE - REMOVE AND INSPECT 5 O'CLOCK IGNITER PLUG AND LEAD						Service	ATA:74
	MOS		22-Jun-23							
	HRS		9184.4		1600					
	ENC		7042							
PKG:0										
740140 ^S			NO. 2 ENGINE - REMOVE AND INSPECT 5 O'CLOCK IGNITER PLUG AND LEAD						Service	ATA:74
	MOS		18-Aug-22							
	HRS		8169.8		1600					
	ENC		6832							
PKG:0										
740150			NO. 1 ENGINE - 7 O'CLOCK IGNITER (#2 POSITION) PLUG						Component	ATA:74
PN:3074541-4	MOS/MSC		28-Nov-17	O/C	TSN 0					
SN:UNKNOWN	HRS		7696.2		TSN 0					
	ENC		5895		TSN 0					
PROC. REF: LMM 74-00-01, LMM 74-00-01PROC. REF: LMM 74-00-01, LMM 74-00-01										
740150			NO. 2 ENGINE - 7 O'CLOCK IGNITER (#2 POSITION) PLUG						Component	ATA:74
PN:3074541-4	MOS/MSC		18-Aug-22	O/C	TSN 0					
SN:UNKNOWN	HRS		8169.8		TSN 0					
	ENC		6832		TSN 0					
PROC. REF: LMM 74-00-01, LMM 74-00-01PROC. REF: LMM 74-00-01, LMM 74-00-01										
740160 ^S			NO. 1 ENGINE - REMOVE AND INSPECT 7 O'CLOCK IGNITER PLUG AND LEAD						Service	ATA:74
	MOS		22-Jun-23							
	HRS		9184.4		1600					
	ENC		7042							
PKG:0										
PROC. REF: LMM 74-00-01PROC. REF: LMM 74-00-01										
740160 ^S			NO. 2 ENGINE - REMOVE AND INSPECT 7 O'CLOCK IGNITER PLUG AND LEAD						Service	ATA:74
	MOS		18-Aug-22							
	HRS		8169.8		1600					
	ENC		6832							
PKG:0										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 74 - IGNITION

PROC. REF: LMM 74-00-01PROC. REF: LMM 74-00-01

742011 NO. 1 ENGINE - NO. 1 IGNITION (IPC 20 REFERENCE) LEAD						Component	ATA:74
PN:3060722-11	MOS/MSC	22-Jun-23	O/C	TSN 0			
SN:S23100003	HRS	9184.4		TSN 0			
	ENC	7042		TSN 0			
PROC. REF: LMM 74-00-01, LMM 74-00-01PROC. REF: LMM 74-00-01, LMM 74-00-01							

742011 NO. 2 ENGINE - NO. 1 IGNITION (IPC 20 REFERENCE) LEAD						Component	ATA:74
PN:9043913	MOS/MSC	20-Jul-15	O/C	TSN 0			
SN:UNKNOWN	HRS	6622.3		TSN 0			
	ENC	5602		TSN 0			
PROC. REF: LMM 74-00-01, LMM 74-00-01PROC. REF: LMM 74-00-01, LMM 74-00-01							

742012 NO. 1 ENGINE - NO. 2 IGNITION (IPC 25 REFERENCE) LEAD						Component	ATA:74
PN:3060722-12	MOS/MSC	22-Jun-23	O/C	TSN 0			
SN:S22500007	HRS	9184.4		TSN 0			
	ENC	7042		TSN 0			
PROC. REF: LMM 74-00-01, LMM 74-00-01PROC. REF: LMM 74-00-01, LMM 74-00-01							

742012 NO. 2 ENGINE - NO. 2 IGNITION (IPC 25 REFERENCE) LEAD						Component	ATA:74
PN:9043913	MOS/MSC	20-Jul-15	O/C	TSN 0			
SN:UNKNOWN	HRS	6622.3		TSN 0			
	ENC	5602		TSN 0			
PROC. REF: LMM 74-00-01, LMM 74-00-01PROC. REF: LMM 74-00-01, LMM 74-00-01							

743001 TAIL CONE RELAY (P13) PANEL						Component	ATA:74
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0			
SN:UNKNOWN	HRS	0		TSN 0			
	AFL	0		TSN 0			
PROC. REF: AMM 74-30-01PROC. REF: AMM 74-30-01							

743001-1 EMERGENCY LIGHTING (P-51) RELAY						Component	ATA:74
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0			
SN:UNKNOWN	HRS	0		TSN 0			
	AFL	0		TSN 0			
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 74 - IGNITION										
743005-1		K22 RELAY						Component		ATA:74
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
<hr/>										
743005-2		K61 RELAY						Component		ATA:74
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
<hr/>										
ATA 75 - AIR										
754210		NO. 1 ENGINE - INLET PRESSURE AND TEMPERATURE SENSOR						Component		ATA:75
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 75-40-01, LMM 75-40-01, LMM 75-40-01, LMM 75-40-01PROC. REF: LMM 75-40-01, LMM 75-40-01, LMM 75-40-01, LMM 75-40-01										
<hr/>										
754210		NO. 2 ENGINE - INLET PRESSURE AND TEMPERATURE SENSOR						Component		ATA:75
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 75-40-01, LMM 75-40-01, LMM 75-40-01, LMM 75-40-01PROC. REF: LMM 75-40-01, LMM 75-40-01, LMM 75-40-01, LMM 75-40-01										
<hr/>										
ATA 76 - ENGINE CONTROLS										
761013		THROTTLE CONTROL MODULE						Component		ATA:76
PN:69011-17	MOS/MSC	16-Jul-20	O/C							
SN:640	HRS	8284.1								
	AFL	6376								
PROC. REF: AMM 76-10-02PROC. REF: AMM 76-10-02										
<hr/>										
761201		AFT LEFT THROTTLE CABLE						Component		ATA:76
PN:71825-6	MOS/MSC	12-Oct-12	O/C							
SN:UNKNOWN	HRS	6996.3								
	AFL	5340								
PROC. REF: AMM 76-10-01PROC. REF: AMM 76-10-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 76 - ENGINE CONTROLS									
761202 AFT RIGHT THROTTLE CABLE									Component ATA:76
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 76-10-01PROC. REF: AMM 76-10-01									
761203 LEFT FORWARD THROTTLE CABLE									Component ATA:76
PN:71845-10	MOS/MSC	12-Oct-12	O/C						
SN:UNKNOWN	HRS	6996.3							
	AFL	5340							
PROC. REF: AMM 76-10-01PROC. REF: AMM 76-10-01									
761204 RIGHT FORWARD THROTTLE CABLE									Component ATA:76
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 76-10-01PROC. REF: AMM 76-10-01									
761310 NO. 1 ENGINE - SURGE BLEED VALVE									Component ATA:76
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 76-10-01, LMM 76-10-01, LMM 76-10-01, LMM 76-10-01PROC. REF: LMM 76-10-01, LMM 76-10-01, LMM 76-10-01, LMM 76-10-01									
761310 NO. 2 ENGINE - SURGE BLEED VALVE									Component ATA:76
PN:978812-6-1	MOS/MSC	20-Jul-15	O/C	TSO 0					
SN:10962	HRS	6622.3		TSO 0					
	ENC	5602		TSO 0					
PROC. REF: LMM 76-10-01, LMM 76-10-01, LMM 76-10-01, LMM 76-10-01PROC. REF: LMM 76-10-01, LMM 76-10-01, LMM 76-10-01, LMM 76-10-01									
761320 NO. 1 ENGINE - SOLENOID CONTROLLER VALVE									Component ATA:76
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 76-10-01, LMM 76-10-01, LMM 76-10-01, LMM 76-10-01PROC. REF: LMM 76-10-01, LMM 76-10-01, LMM 76-10-01, LMM 76-10-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 76 - ENGINE CONTROLS

761320		NO. 2 ENGINE - SOLENOID CONTROLLER VALVE						Component	ATA:76
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 76-10-01, LMM 76-10-01, LMM 76-10-01, LMM 76-10-01PROC. REF: LMM 76-10-01, LMM 76-10-01, LMM 76-10-01, LMM 76-10-01									

761330		NO. 1 ENGINE - ENGINE (DEEC) COMPUTER						Component	ATA:76
PN:2118882-1008	MOS/MSC	25-Oct-06	O/C						
SN:15-AW0059	HRS	4857.2							
	ENC	3730							
PROC. REF: LMM 76-10-02, LMM 76-10-02, LMM 76-10-02, LMM 76-10-02PROC. REF: LMM 76-10-02, LMM 76-10-02, LMM 76-10-02, LMM 76-10-02									

761330		NO. 2 ENGINE - ENGINE (DEEC) COMPUTER						Component	ATA:76
PN:2118882-1008	MOS/MSC	27-Jun-06	O/C						
SN:124-AW0057	HRS	4614							
	ENC	3532							
PROC. REF: LMM 76-10-02, LMM 76-10-02, LMM 76-10-02, LMM 76-10-02PROC. REF: LMM 76-10-02, LMM 76-10-02, LMM 76-10-02, LMM 76-10-02									

761330A		NO. 1 ENGINE - DOWNLOAD ENGINE (DEEC) COMPUTER ECTM						Service	ATA:76
PN:2118882-1008	MOS	21-Oct-25						CUSTOMER CODE	
SN:15-AW0059	HRS	9826.9							
	ENC	7476	40	(7516) 7574			OVD		
PROC. REF: MSC CAMP EHM ADENDUMPROC. REF: MSC CAMP EHM ADENDUM									

761330A		NO. 2 ENGINE - DOWNLOAD ENGINE (DEEC) COMPUTER ECTM						Service	ATA:76
PN:2118882-1008	MOS	21-Oct-25						CUSTOMER CODE	
SN:124-AW0057	HRS	8988.2							
	ENC	7372	40	(7412) 7574			OVD		
PROC. REF: MSC CAMP EHM ADENDUMPROC. REF: MSC CAMP EHM ADENDUM									

Y7600000 ^S		ENGINE DEEC WIRE HARNESS SHIELD OVERBRAIDS AND SHIELD TERMINATIONS - PERFORM VISUAL INSPECTION						Service	ATA:76
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							

PKG:15

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 76 - ENGINE CONTROLS

PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00

Y7600001 ^S	THRUST LEVER CONTROL MODULE - PERFORM FUNCTIONAL TEST							Service	ATA:76
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							

PKG:13

PROC. REF: AMM 76-10-02PROC. REF: AMM 76-10-02

Y7610007 ^S	ENGINE CONTROL CABLES - PERFORM VISUAL INSPECTION OF FORWARD AND AFT CABLE CONNECTIONS							Service	ATA:76
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							

PKG:14

PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00

ATA 77 - ENGINE INDICATING

770101	NO. 1 ENGINE - N1 MONOPOLE				Component	ATA:77
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0		
SN:UNKNOWN	HRS	0		TSN 0		
	ENC	0		TSN 0		

PROC. REF: LMM 77-10-02PROC. REF: LMM 77-10-02

770101	NO. 2 ENGINE - N1 MONOPOLE				Component	ATA:77
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0		
SN:UNKNOWN	HRS	0		TSN 0		
	ENC	0		TSN 0		

PROC. REF: LMM 77-10-02PROC. REF: LMM 77-10-02

771210	NO. 1 ENGINE - N1 COMPENSATOR				Component	ATA:77
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0		
SN:UNKNOWN	HRS	0		TSN 0		
	ENC	0		TSN 0		

PROC. REF: LMM 77-10-03, LMM 77-10-03, LMM 77-10-03, LMM 77-10-03PROC. REF: LMM 77-10-03, LMM 77-10-03, LMM 77-10-03, LMM 77-10-03

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 77 - ENGINE INDICATING										
771210		NO. 2 ENGINE - N1 COMPENSATOR						Component	ATA:77	
PN:3060735-7	MOS/MSC	05-Jun-06	O/C	TSN 0						
SN:011309700526	HRS	3701.2		TSN 0						
	ENC	3369		TSN 0						
PROC. REF: LMM 77-10-03, LMM 77-10-03, LMM 77-10-03, LMM 77-10-03PROC. REF: LMM 77-10-03, LMM 77-10-03, LMM 77-10-03, LMM 77-10-03										
771220		NO. 1 ENGINE - N2 MONOPOLE						Component	ATA:77	
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 77-10-05, LMM 77-10-05, LMM 77-10-05, LMM 77-10-05PROC. REF: LMM 77-10-05, LMM 77-10-05, LMM 77-10-05, LMM 77-10-05										
771220		NO. 2 ENGINE - N2 MONOPOLE						Component	ATA:77	
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 77-10-05, LMM 77-10-05, LMM 77-10-05, LMM 77-10-05PROC. REF: LMM 77-10-05, LMM 77-10-05, LMM 77-10-05, LMM 77-10-05										
772210		NO. 1 ENGINE - ITT HARNESS ASSEMBLY						Component	ATA:77	
PN:3060730-1	MOS/MSC	28-Nov-17	O/C	TSN 0						
SN:1716901702429	HRS	7696.2		TSN 0						
	ENC	5895		TSN 0						
PROC. REF: LMM 77-20-01, LMM 77-20-01, LMM 77-20-01, LMM 77-20-01PROC. REF: LMM 77-20-01, LMM 77-20-01, LMM 77-20-01, LMM 77-20-01										
772210		NO. 2 ENGINE - ITT HARNESS ASSEMBLY						Component	ATA:77	
PN:3060763-1	MOS/MSC	20-Jul-15	O/C	TSN 0						
SN:1516901702268	HRS	6622.3		TSN 0						
	ENC	5602		TSN 0						
PROC. REF: LMM 77-20-01, LMM 77-20-01, LMM 77-20-01, LMM 77-20-01PROC. REF: LMM 77-20-01, LMM 77-20-01, LMM 77-20-01, LMM 77-20-01										
774001		ENGINE VIBRATION MONITOR BOX						Component	ATA:77	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 77-41-01PROC. REF: AMM 77-41-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 77 - ENGINE INDICATING

774010		P36 RELAY BOX					Component	ATA:77
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 77-41-03PROC. REF: AMM 77-41-03								

774011		LEFT ENGINE VIBRATION ACCELEROMETER					Component	ATA:77
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 77-41-02PROC. REF: AMM 77-41-02								

774012		RIGHT ENGINE VIBRATION ACCELEROMETER					Component	ATA:77
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 77-41-02PROC. REF: AMM 77-41-02								

Y7741000 ^S		ENGINE VIBRATION MONITORING SYSTEM - PERFORM FUNCTIONAL TEST					Service	ATA:77
	MOS	25-Nov-19	96					
	HRS	8177.7	2400					
	AFL	6303						
PROC. REF: AMM 77-41-00PROC. REF: AMM 77-41-00								

PKG:21

ATA 78 - EXHAUST

783001		LEFT LOWER THRUST REVERSER					Component	ATA:78
PN:LJ7830101-5	MOS/MSC	26-Jul-23	O/C					
SN:00046	HRS	9278						
	AFL	7111						
Special Properties: RII ITEM								
PROC. REF: AMM 78-31-00PROC. REF: AMM 78-31-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 78 - EXHAUST									
783002 RIGHT LOWER THRUST REVERSER									Component ATA:78
PN:LJ7830101-6	MOS/MSC	26-Jul-23	O/C						
SN:00052	HRS	9278							
	AFL	7111							
Special Properties: RII ITEM PROC. REF: AMM 78-31-00PROC. REF: AMM 78-31-00									
783025 TRANSFORMER/RECTIFIER ELECTRONIC CONTROL UNIT									Component ATA:78
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
783037 NO. 1 GPM HYDRAULIC CONTROL VALVE									Component ATA:78
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 78-32-10PROC. REF: AMM 78-32-10									
783038 NO. 2 GPM HYDRAULIC CONTROL VALVE									Component ATA:78
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 78-32-10PROC. REF: AMM 78-32-10									
783051 LEFT OUTBOARD THRUST REVERSER ACTUATOR									Component ATA:78
PN:LJ7833100-3	MOS/MSC	26-Jan-14	O/C	TSO 0					
SN:A30040652	HRS	7249.8		TSO 0					
	AFL	5528		TSO 0					
PROC. REF: AMM 78-32-20PROC. REF: AMM 78-32-20									
783052 LEFT INBOARD THRUST REVERSER ACTUATOR									Component ATA:78
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 78-32-20PROC. REF: AMM 78-32-20									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 78 - EXHAUST									
783053 RIGHT INBOARD THRUST REVERSER ACTUATOR									Component ATA:78
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 78-32-20PROC. REF: AMM 78-32-20									
783054 RIGHT OUTBOARD THRUST REVERSER ACTUATOR									Component ATA:78
PN:LJ7833100-4	MOS/MSC	12-Dec-11	O/C	TSO 0					
SN:A30040459	HRS	6763.5		TSO 0					
	AFL	5158		TSO 0					
PROC. REF: AMM 78-32-20PROC. REF: AMM 78-32-20									
783061 NO. 1 CONTROL, THRUST REVERSER HYDRAULIC VALVE									Component ATA:78
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 78-32-10PROC. REF: AMM 78-32-10									
783062 NO. 2 CONTROL, THRUST REVERSER HYDRAULIC VALVE									Component ATA:78
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 78-32-10PROC. REF: AMM 78-32-10									
783101 LEFT THRUST REVERSER HYDRAULIC ISOLATION VALVE									Component ATA:78
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 78-30-02PROC. REF: AMM 78-30-02									
783102 RIGHT THRUST REVERSER HYDRAULIC ISOLATION VALVE									Component ATA:78
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 78-30-02PROC. REF: AMM 78-30-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 78 - EXHAUST									
783150 LEFT HAND INBOARD LATCHBOX ACTUATOR									Component ATA:78
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 78-32-30PROC. REF: AMM 78-32-30									
783151 RIGHT HAND INBOARD LATCHBOX ACTUATOR									Component ATA:78
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 78-32-30PROC. REF: AMM 78-32-30									
783210 LEFT THRUST REVERSER CONTROL VALVE									Component ATA:78
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
783211 RIGHT THRUST REVERSER CONTROL VALVE									Component ATA:78
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
783220 NO. 1 ENGINE THROTTLE RETARD ACTUATOR									Component ATA:78
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 78-32-40PROC. REF: AMM 78-32-40									
783221 NO. 2 ENGINE THROTTLE RETARD ACTUATOR									Component ATA:78
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 78-32-40PROC. REF: AMM 78-32-40									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 78 - EXHAUST										
783301 LEFT THRUST REVERSER CONTROL BOX									Component	ATA:78
PN:LJ7836706-3	MOS/MSC	23-Aug-22	O/C							
SN:00046	HRS	9089.4								
	AFL	6994								
PROC. REF: AMM 78-33-10PROC. REF: AMM 78-33-10										
783302 RIGHT THRUST REVERSER CONTROL BOX									Component	ATA:78
PN:LJ7836706-3	MOS/MSC	18-Jun-07	O/C							
SN:00059	HRS	5562.1								
	AFL	4242								
PROC. REF: AMM 78-33-10PROC. REF: AMM 78-33-10										
783320 LEFT OUTBOARD THRUST REVERSER WIRE HARNESS									Component	ATA:78
PN:PN	MOS/MSC	09-Mar-01	C/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 78-33-20PROC. REF: AMM 78-33-20										
783321 LEFT INBOARD THRUST REVERSER WIRE HARNESS									Component	ATA:78
PN:PN	MOS/MSC	09-Mar-01	C/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 78-33-20PROC. REF: AMM 78-33-20										
783322 RIGHT INBOARD THRUST REVERSER WIRE HARNESS									Component	ATA:78
PN:PN	MOS/MSC	09-Mar-01	C/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 78-33-20PROC. REF: AMM 78-33-20										
783323 RIGHT OUTBOARD THRUST REVERSER WIRE HARNESS									Component	ATA:78
PN:PN	MOS/MSC	09-Mar-01	C/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 78-33-20PROC. REF: AMM 78-33-20										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 78 - EXHAUST										
D7830078	^S	** THRUST REVERSER SYSTEM THROTTLE RETARD ACTUATOR - PERFORM OPERATIONAL CHECK							Service	ATA:78
	MOS	25-Nov-19	96					AIRWORTHINESS		
	HRS	8177.7	2400							
	AFL	6303								
PROC. REF: AMM 78-32-40PROC. REF: AMM 78-32-40										
PKG:21										
H7830081	^S	THRUST REVERSERS - REMOVE LINK ROD ASSEMBLIES AND PERFORM MAGNETIC PARTICLE INSPECTION							Service	ATA:78
	MOS	09-Mar-01	96							
	HRS	0	2400							
	AFL	0								
PROC. REF: NDT PART 7/78-30-01PROC. REF: NDT PART 7/78-30-01										
PKG:21										
H7830082	^S	THRUST REVERSERS - REMOVE THRUST REVERSER DOOR ASSEMBLIES AND PERFORM EDDY CURRENT INSPECTION OF PIVOT FITTING AND DOOR HINGES							Service	ATA:78
	MOS	09-Mar-01	96							
	HRS	0	2400							
	AFL	0								
PROC. REF: NDT PART 6/78-30-02, NDT PART 6/78-30-03PROC. REF: NDT PART 6/78-30-02, NDT PART 6/78-30-03										
PKG:21										
R7830007		THRUST REVERSER - PERFORM CONDUCTIVITY CHECK OF RIGHT THRUST REVERSER DOOR SKIN AND COWL ADJACENT TO APU EXHAUST							Service	ATA:78
	MOS/MSC	09-Mar-01	N/A							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 6/78-30-01PROC. REF: NDT PART 6/78-30-01										
Y7830000	^S	EXHAUST NOZZLE - PERFORM VISUAL INSPECTION							Service	ATA:78
	MOS	25-Nov-19	96							
	HRS	8177.7	2400							
	AFL	6303								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
PKG:21										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 78 - EXHAUST										
Y7830001	^S	THRUST REVERSER INNER FAN DUCT ASSEMBLY - PERFORM VISUAL INSPECTION. INSPECT FROM EXHAUST END ONLY.						Service	ATA:78	
	MOS	09-Mar-01	48							
	HRS	0	1200							
	AFL	0								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
PKG:15										
Y7830002	^S	THRUST REVERSER DOOR AND HINGE FITTINGS - PERFORM VISUAL INSPECTION						Service	ATA:78	
	MOS	09-Mar-01	48							
	HRS	0	1200							
	AFL	0								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
PKG:15										
Y7830003	^S	THRUST REVERSER PRIMARY ACTUATOR AND LATCH ASSEMBLY - PERFORM VISUAL INSPECTION						Service	ATA:78	
	MOS	09-Mar-01	48							
	HRS	0	1200							
	AFL	0								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
PKG:15										
Y7830004	^S	THRUST REVERSER HYDRAULIC CONTROL VALVE (HCV), THROTTLE RETARD ACTUATOR, AND ASSOCIATED PLUMBING - PERFORM VISUAL INSPECTION						Service	ATA:78	
	MOS	09-Mar-01	48							
	HRS	0	1200							
	AFL	0								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
PKG:15										
Y7830005	^S	THRUST REVERSER DOOR SEALS AND RETAINERS - PERFORM VISUAL INSPECTION						Service	ATA:78	
	MOS	09-Mar-01	48							
	HRS	0	1200							
	AFL	0								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
PKG:15										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 78 - EXHAUST

Y7830006 ^S		THRUST REVERSER WIRE HARNESS - PERFORM VISUAL INSPECTION						Service	ATA:78
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PKG:15									
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									

ATA 79 - OIL

790110		NO. 1 ENGINE - OIL PUMP						Component	ATA:79
PN:3060785-2	MOS/MSC	25-Oct-06	O/C		TSN 0				
SN:061405700614	HRS	4857.2			TSN 0				
	ENC	3730			TSN 0				
PROC. REF: LMM 79-20-03, LMM 79-20-03PROC. REF: LMM 79-20-03, LMM 79-20-03									

790110		NO. 2 ENGINE - OIL PUMP						Component	ATA:79
PN:3060785-2	MOS/MSC	05-Jun-06	O/C		TSN 0				
SN:061405700076	HRS	3701.2			TSN 0				
	ENC	3369			TSN 0				
PROC. REF: LMM 79-20-03, LMM 79-20-03PROC. REF: LMM 79-20-03, LMM 79-20-03									

790130 ^S		NO. 1 ENGINE - ANALYSIS OIL AND FILTER (SOAP)						Service	ATA:79
	MOS	02-Aug-24							
	HRS	9451.6	150						
	ENC	7218							
PKG:0									
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									

790130 ^S		NO. 2 ENGINE - ANALYSIS OIL AND FILTER (SOAP)						Service	ATA:79
	MOS	28-Jul-25							
	HRS	8867.6	150						
	ENC	7292							
PKG:0									
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 79 - OIL										
790140 ^S		NO. 1 ENGINE - PERFORM OIL CHANGE							Service	ATA:79
	MOS	27-Oct-25								
	HRS	9832.1	1200							
	ENC	7480								
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00										
PKG:0										
790140 ^S		NO. 2 ENGINE - PERFORM OIL CHANGE							Service	ATA:79
	MOS	27-Oct-25								
	HRS	8993.4	1200							
	ENC	7376								
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00										
PKG:0										
790150 ^S		NO. 1 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION AND PERFORM RESISTANCE CHECK							Service	ATA:79
	MOS	27-Oct-25								
	HRS	9832.1	600							
	ENC	7480								
PROC. REF: LMM 79-10-01PROC. REF: LMM 79-10-01										
PKG:0										
790150 ^S		NO. 2 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION AND PERFORM RESISTANCE CHECK							Service	ATA:79
	MOS	27-Oct-25								
	HRS	8993.4	600							
	ENC	7376								
PROC. REF: LMM 79-10-01PROC. REF: LMM 79-10-01										
PKG:0										
790160 ^S		NO. 1 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION							Service	ATA:79
	MOS	02-Aug-24								
	HRS	9451.6	150							
	ENC	7218								
PROC. REF: LMM 79-10-01PROC. REF: LMM 79-10-01										
PKG:0										

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 79 - OIL										
790160 ^S	NO. 2 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION								Service	ATA:79
	MOS	28-Jul-25								
	HRS	8867.6	150							
	ENC	7292								
PROC. REF: LMM 79-10-01PROC. REF: LMM 79-10-01										
791001	NO. 1 ENGINE - ENGINE OIL CHIP DETECTOR								Component	ATA:79
PN:277-5501-9002	MOS/MSC	18-May-13		O/C						
SN:N/A	HRS	7075.3								
	ENC	5383								
PROC. REF: LMM 79-10-01, LMM 79-10-01PROC. REF: LMM 79-10-01, LMM 79-10-01										
791001	NO. 2 ENGINE - ENGINE OIL CHIP DETECTOR								Component	ATA:79
PN:277-5501-9004	MOS/MSC	18-May-13		O/C						
SN:N/A	HRS	6239								
	ENC	5281								
PROC. REF: LMM 79-10-01, LMM 79-10-01PROC. REF: LMM 79-10-01, LMM 79-10-01										
792008	NO. 1 ENGINE - OIL FLOW REDUCTION VALVE								Component	ATA:79
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 79-20-08, LMM 79-20-08PROC. REF: LMM 79-20-08, LMM 79-20-08										
792008	NO. 2 ENGINE - OIL FLOW REDUCTION VALVE								Component	ATA:79
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 79-20-08, LMM 79-20-08PROC. REF: LMM 79-20-08, LMM 79-20-08										
792011	NO. 1 ENGINE - FUEL/OIL VALVE								Component	ATA:79
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 79 - OIL									
792011 NO. 2 ENGINE - FUEL/OIL VALVE									Component ATA:79
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
<hr/>									
792012 NO. 1 ENGINE - OIL TEMPERATURE REGULATOR									Component ATA:79
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 79-20-03, LMM 79-20-03PROC. REF: LMM 79-20-03, LMM 79-20-03									
<hr/>									
792012 NO. 2 ENGINE - OIL TEMPERATURE REGULATOR									Component ATA:79
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 79-20-03, LMM 79-20-03PROC. REF: LMM 79-20-03, LMM 79-20-03									
<hr/>									
792037 NO. 1 OIL PRESSURE SWITCH									Component ATA:79
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 79-30-02PROC. REF: AMM 79-30-02									
<hr/>									
792038 NO. 2 OIL PRESSURE SWITCH									Component ATA:79
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 79-30-02PROC. REF: AMM 79-30-02									
<hr/>									
792220 NO. 1 ENGINE - UPPER OIL COOLER ASSEMBLY									Component ATA:79
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 79 - OIL										
792220		NO. 2 ENGINE - UPPER OIL COOLER ASSEMBLY						Component	ATA:79	
PN:160554-5	MOS/MSC	05-Jun-06	O/C							
SN:76-247	HRS	3701.2								
	ENC	3369								
<hr/>										
792230		NO. 1 ENGINE - LOWER LEFT OIL COOLER ASSEMBLY						Component	ATA:79	
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
<hr/>										
792230		NO. 2 ENGINE - LOWER LEFT OIL COOLER ASSEMBLY						Component	ATA:79	
PN:160552-3	MOS/MSC	05-Jun-06	O/C							
SN:47-274	HRS	3701.2								
	ENC	3369								
<hr/>										
792240		NO. 1 ENGINE - LOWER RIGHT OIL COOLER ASSEMBLY						Component	ATA:79	
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
<hr/>										
792240		NO. 2 ENGINE - LOWER RIGHT OIL COOLER ASSEMBLY						Component	ATA:79	
PN:160554-6	MOS/MSC	05-Jun-06	O/C							
SN:1068	HRS	3701.2								
	ENC	3369								
<hr/>										
792250		NO. 1 ENGINE - PRESSURE BREATHER VALVE						Component	ATA:79	
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 79-20-02, LMM 79-20-02PROC. REF: LMM 79-20-02, LMM 79-20-02										

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 79 - OIL										
792250		NO. 2 ENGINE - PRESSURE BREATHER VALVE						Component	ATA:79	
PN:3075323-3	MOS/MSC	16-Feb-11	O/C							
SN:000814506520	HRS	5602								
	ENC	4823								
PROC. REF: LMM 79-20-02, LMM 79-20-02PROC. REF: LMM 79-20-02, LMM 79-20-02										
792260		NO. 1 ENGINE - OIL TEMPERATURE CONTROL VALVE						Component	ATA:79	
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
792260		NO. 2 ENGINE - OIL TEMPERATURE CONTROL VALVE						Component	ATA:79	
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
793001		NO. 1 ENGINE OIL PRESSURE TRANSDUCER						Component	ATA:79	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 79-30-01PROC. REF: AMM 79-30-01										
793002		NO. 2 ENGINE OIL PRESSURE TRANSDUCER						Component	ATA:79	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 79-30-01PROC. REF: AMM 79-30-01										
793011		LEFT TEMPERATURE OIL BULB						Component	ATA:79	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 79-30-03PROC. REF: AMM 79-30-03										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 79 - OIL									
793012 RIGHT TEMPERATURE OIL BULB									Component ATA:79
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 79-30-03PROC. REF: AMM 79-30-03									
793013 APU TEMPERATURE OIL BULB									Component ATA:79
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 79-30-03PROC. REF: AMM 79-30-03									
793064 NO. 1 ENGINE - TEMP BULB									Component ATA:79
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
793064 NO. 2 ENGINE - TEMP BULB									Component ATA:79
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
793310 NO. 1 ENGINE - OIL FILTER BYPASS VALVE									Component ATA:79
PN:3060782-2	MOS/MSC	25-Oct-06	O/C	TSN 0					
SN:060645105349	HRS	4857.2		TSN 0					
	ENC	3730		TSN 0					
793310 NO. 2 ENGINE - OIL FILTER BYPASS VALVE									Component ATA:79
PN:3060782-2	MOS/MSC	25-Nov-20	O/C	TSO 0					
SN:K15538	HRS	7388.5		TSO 0					
	ENC	6230		TSO 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 09-Feb-2026

12-Feb-2026 02:27 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 79 - OIL										
793315 ^S	NO. 1 ENGINE - CHECK OIL FILTER BYPASS VALVE CIRCUIT/THERMAL LOCKOUT SWITCH								Service	ATA:79
	MOS	27-Oct-25								
	HRS	9832.1	600							
	ENC	7480								
PKG:0										
793315 ^S	NO. 2 ENGINE - CHECK OIL FILTER BYPASS VALVE CIRCUIT/THERMAL LOCKOUT SWITCH								Service	ATA:79
	MOS	27-Oct-25								
	HRS	8993.4	600							
	ENC	7376								
PKG:0										
793320	NO. 1 ENGINE - FUEL HEATER / OIL COOLER ASSEMBLY								Component	ATA:79
PN:160506-4	MOS/MSC	30-Nov-16	O/C	TSO 4						
SN:47-486	HRS	7607.6		TSO 0						
	ENC	5820		TSO 0						
PROC. REF: LMM 79-20-07, LMM 79-20-07PROC. REF: LMM 79-20-07, LMM 79-20-07										
793320	NO. 2 ENGINE - FUEL HEATER / OIL COOLER ASSEMBLY								Component	ATA:79
PN:160506-4	MOS/MSC	21-Aug-25	O/C	TSN 0						
SN:4216	HRS	8897		TSN 0						
	ENC	7309		TSN 0						
PROC. REF: LMM 79-20-07, LMM 79-20-07PROC. REF: LMM 79-20-07, LMM 79-20-07										
ATA 85 - FUEL CELL SYSTEMS										
859000	SUBMIT LOGBOOK ENTRIES FOR ELOGBOOK								Service	ATA:85
	MOS/MSC	09-Mar-01	A/R							
	HRS	0								
	AFL	0								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										