

OWNER: PRIVATE JETS INC.
 ADDRESS: 7220 NW 63TH ST
 BETHANY OK 73008
 OFFICE:
 FAX:

OPERATOR: PRIVATE JETS INC.
 ADDRESS: 7220 NW 63TH ST
 BETHANY OK 73008
 OFFICE:
 FAX:

ANALYST: SEAN WELLS
 EMAIL: SWELLS@CAMPSYSTEMS.COM

+1-316-928-7895 (DIRECT)
 +1-631-588-3200 (MAIN)
 WWW.CAMPSYSTEMS.COM

800-787-9749 (EFAX-CARDS)
 631-980-4222 (EFAX-CARDS)

PLEASE REACH OUT TO YOUR ANALYST TO
 RECORD CHANGES TO ADDRESS, LAST ACTUALS
 (IF ANY).

AIRCRAFT SERIAL/REGNO: 45-145/N942FK MODEL: LEARJET 45XR MANUFACTURER: BOMBARDIER AVIATION

CERTIFICATION DATE: 09-MAR-2001

LAST ACTUALS:
 10023.1 A/C HRS as of 26-MAY-2026
 7616 AFL as of 26-MAY-2026
 2691.6 ACH as of 04-MAY-2026

ENGINE NO. 1 SERIAL/PART: P-116284C/3060082-2 MODEL: TFE731-20BR-1B MANUFACTURER: HONEYWELL

INSTALLED ON: 20-JAN-2000
 0 ENG. HRS 0 A/C HRS
 0 ENC

LAST ACTUALS:
 9994.8 ENG. HRS as of 26-MAY-2026
 7602 ENC as of 26-MAY-2026

ENGINE NO. 2 SERIAL/PART: P-116285C/3060084-2 MODEL: TFE731-20BR-1B MANUFACTURER: HONEYWELL

INSTALLED ON: 12-AUG-2015
 6622.3 ENG. HRS 7535.1 A/C HRS
 5602 ENC

LAST ACTUALS:
 9156.1 ENG. HRS as of 26-MAY-2026
 7498 ENC as of 26-MAY-2026

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 00 - INFORMATION

CI45-150721	REVIEW CONCORDE EMERGENCY BATTERY CMM 5-0167 REV E							Service	ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS	
	HRS								
	AFL								
PROC. REF: RCF CI45PROC. REF: RCF CI45									

CI45-160527	REVIEW LEARJET AMM REVISION 66							Service	ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS	
	HRS								
	AFL								
PROC. REF: RCF CI45PROC. REF: RCF CI45									

CI45-160603	REVIEW LEARJET 45 AMM TR 4-40							Service	ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS	
	HRS								
	AFL								
PROC. REF: RCF CI45PROC. REF: RCF CI45									

CI45-160613	REVIEW LEARJET 45 AMM TR 5-110							Service	ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS	
	HRS								
	AFL								
PROC. REF: RCF CI45PROC. REF: RCF CI45									

CI45-161207B	REVIEW LEARJET 45 AMM REVISION 67							Service	ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS	
	HRS								
	AFL								
PROC. REF: RCF CI45PROC. REF: RCF CI45									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 00 - INFORMATION										
CI45-181109B	REVIEW LEARJET 45/45XR AMM REVISION 71								Service	ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS		
	HRS									
	AFL									
PROC. REF: RCF C145PROC. REF: RCF C145										
CI45-190429A	REVIEW LEARJET 45/45XR AMM REV 72								Service	ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS		
	HRS									
	AFL									
PROC. REF: RCF C145PROC. REF: RCF C145										
CI45-200529	REVIEW AUDIT SUMMARY CHANGE FORM								Service	ATA:00
	MOS/MSC	EFF	-					AUDIT SUMMARY CHANGE FORM		
	HRS									
	AFL									
PROC. REF: RCF C145PROC. REF: RCF C145										
CI45-210120	REVIEW LEARJET 45/45XR AUDIT SUMMARY CHANGE FORM								Service	ATA:00
	MOS/MSC	30-Mar-21	-					AUDIT SUMMARY CHANGE FORM		
	HRS	8414.4								
	AFL	6463								
PROC. REF: RCF C145PROC. REF: RCF C145										
CI45-260206	REVIEW ATTACHED AUDIT SUMMARY CHANGE FORM								Service	ATA:00
	MOS/MSC	EFF	-					AUDIT SUMMARY CHANGE FORM		
	HRS									
	AFL									
PROC. REF: RCF C145PROC. REF: RCF C145										

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 00 - INFORMATION										
EC04-180802	NO. 1 ENGINE - REVIEW TFE731-20/-40/-60 (CIMMS) LMM TR 5-17								Service	ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS		
	HRS									
	ENC									
PROC. REF: RCF EC04-180802PROC. REF: RCF EC04-180802										
EC04-180802	NO. 2 ENGINE - REVIEW TFE731-20/-40/-60 (CIMMS) LMM TR 5-17								Service	ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS		
	HRS									
	ENC									
PROC. REF: RCF EC04-180802PROC. REF: RCF EC04-180802										
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS										
051101	PHASE A1-300 HOUR CHECKS								Package	ATA:05
	MOS	21-Aug-25	12		21-Aug-26		87 d			
	HRS	9809.8	300		10109.8		86.7			
WC#: 05.110	AFL	7471								
PROC. REF: AMM 05-10-00, AMM 05-11-01PROC. REF: AMM 05-10-00, AMM 05-11-01										
051102	PHASE A2-300 HOUR CHECKS								Package	ATA:05
	MOS	21-Aug-25	12		21-Aug-26		87 d			
	HRS	9809.8	300		10109.8		86.7			
	AFL	7471								
PROC. REF: AMM 05-10-00, AMM 05-11-02PROC. REF: AMM 05-10-00, AMM 05-11-02										
051103	PHASE A3-300 HOUR CHECKS								Package	ATA:05
	MOS	21-Aug-25	12		21-Aug-26		87 d			
	HRS	9809.8	300		10109.8		86.7			
	AFL	7471								
PROC. REF: AMM 05-10-00, AMM 05-11-03PROC. REF: AMM 05-10-00, AMM 05-11-03										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS										
051104	PHASE A4-300 HOUR CHECKS								Package	ATA:05
	MOS	21-Aug-25	12		21-Aug-26		87 d			
	HRS	9809.8	300		10109.8		86.7			
	AFL	7471								
PROC. REF: AMM 05-10-00, AMM 05-11-04 PROC. REF: AMM 05-10-00, AMM 05-11-04										
PKG:4										
051105	PHASE A5-300 HOUR CHECKS								Package	ATA:05
	MOS	21-Aug-25	12		21-Aug-26		87 d			
	HRS	9809.8	300		10109.8		86.7			
	AFL	7471								
PROC. REF: AMM 05-10-00, AMM 05-11-05 PROC. REF: AMM 05-10-00, AMM 05-11-05										
PKG:5										
051106	PHASE A6-300 HOUR CHECKS								Package	ATA:05
	MOS	21-Aug-25	12		21-Aug-26		87 d			
	HRS	9809.8	300		10109.8		86.7			
	AFL	7471								
PROC. REF: AMM 05-10-00, AMM 05-11-06 PROC. REF: AMM 05-10-00, AMM 05-11-06										
PKG:6										
051201	PHASE B1 600 HOUR CHECKS								Package	ATA:05
	MOS	02-Aug-24	24		02-Aug-26		68 d			
	HRS	9525.7	600		10125.7		102.6			
	AFL	7276								
PROC. REF: AMM 05-10-00, AMM 05-12-01 PROC. REF: AMM 05-10-00, AMM 05-12-01										
PKG:7										
051202	PHASE B2 600 HOUR CHECKS								Package	ATA:05
	MOS	02-Aug-24	24		02-Aug-26		68 d			
	HRS	9525.7	600		10125.7		102.6			
	AFL	7276								
PROC. REF: AMM 05-10-00, AMM 05-12-02 PROC. REF: AMM 05-10-00, AMM 05-12-02										
PKG:8										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS										
051203	PHASE B3 600 HOUR CHECKS								Package	ATA:05
	MOS	02-Aug-24	24		02-Aug-26		68 d			
	HRS	9525.7	600		10125.7		102.6			
	AFL	7276								
PROC. REF: AMM 05-10-00, AMM 05-12-03 PROC. REF: AMM 05-10-00, AMM 05-12-03										
051204	PHASE B4 600 HOUR CHECKS								Package	ATA:05
	MOS	02-Aug-24	24		02-Aug-26		68 d			
	HRS	9525.7	600		10125.7		102.6			
	AFL	7276								
PROC. REF: AMM 05-10-00, AMM 05-12-04 PROC. REF: AMM 05-10-00, AMM 05-12-04										
051205	PHASE B5 600 HOUR CHECKS								Package	ATA:05
	MOS	02-Aug-24	24		02-Aug-26		68 d			
	HRS	9525.7	600		10125.7		102.6			
	AFL	7276								
PROC. REF: AMM 05-10-00, AMM 05-12-05 PROC. REF: AMM 05-10-00, AMM 05-12-05										
051206	PHASE B6 600 HOUR CHECKS								Package	ATA:05
	MOS	02-Aug-24	24		02-Aug-26		68 d			
	HRS	9525.7	600		10125.7		102.6			
	AFL	7276								
PROC. REF: AMM 05-10-00, AMM 05-12-06 PROC. REF: AMM 05-10-00, AMM 05-12-06										
051301	PHASE C1 1200 HOUR CHECKS								Package	ATA:05
	MOS	22-Jun-23	48		22-Jun-27		392 d			
	HRS	9258.5	1200		10458.5		435.4			
	AFL	7100								
PROC. REF: AMM 05-10-00, AMM 05-13-01 PROC. REF: AMM 05-10-00, AMM 05-13-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS										
051302	PHASE C2 1200 HOUR CHECKS								Package	ATA:05
	MOS	22-Jun-23	48		22-Jun-27		392 d			
	HRS	9258.5	1200		10458.5		435.4			
	AFL	7100								
PKG:14										
PROC. REF: AMM 05-10-00, AMM 05-13-02 PROC. REF: AMM 05-10-00, AMM 05-13-02										
051303	PHASE C3 1200 HOUR CHECKS								Package	ATA:05
	MOS	22-Jun-23	48		22-Jun-27		392 d			
	HRS	9258.5	1200		10458.5		435.4			
	AFL	7100								
PKG:15										
PROC. REF: AMM 05-10-00, AMM 05-13-03 PROC. REF: AMM 05-10-00, AMM 05-13-03										
051304	PHASE C4 1200 HOUR CHECKS								Package	ATA:05
	MOS	22-Jun-23	48		22-Jun-27		392 d			
	HRS	9258.5	1200		10458.5		435.4			
	AFL	7100								
PKG:16										
PROC. REF: AMM 05-10-00, AMM 05-13-04 PROC. REF: AMM 05-10-00, AMM 05-13-04										
051305	PHASE C5 1200 HOUR CHECKS								Package	ATA:05
	MOS	22-Jun-23	48		22-Jun-27		392 d			
	HRS	9258.5	1200		10458.5		435.4			
	AFL	7100								
PKG:17										
PROC. REF: AMM 05-10-00, AMM 05-13-05 PROC. REF: AMM 05-10-00, AMM 05-13-05										
051306	PHASE C6 1200 HOUR CHECKS								Package	ATA:05
	MOS	22-Jun-23	48		22-Jun-27		392 d			
	HRS	9258.5	1200		10458.5		435.4			
	AFL	7100								
PKG:18										
PROC. REF: AMM 05-10-00, AMM 05-13-06 PROC. REF: AMM 05-10-00, AMM 05-13-06										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS										
051401	PHASE D1 2400 HOUR CHECKS								Package	ATA:05
	MOS	25-Nov-19	96		25-Nov-27		548 d			
	HRS	8177.7	2400		10577.7		554.6			
	AFL	6303								
PROC. REF: AMM 05-10-00, AMM 05-14-01 PROC. REF: AMM 05-10-00, AMM 05-14-01										
051402	PHASE D2 2400 HOUR CHECKS								Package	ATA:05
	MOS	25-Nov-19	96		25-Nov-27		548 d			
	HRS	8177.7	2400		10577.7		554.6			
	AFL	6303								
PROC. REF: AMM 05-10-00, AMM 05-14-02 PROC. REF: AMM 05-10-00, AMM 05-14-02										
051403	PHASE D3 2400 HOUR CHECKS								Package	ATA:05
	MOS	25-Nov-19	96		25-Nov-27		548 d			
	HRS	8177.7	2400		10577.7		554.6			
	AFL	6303								
PROC. REF: AMM 05-10-00, AMM 05-14-03 PROC. REF: AMM 05-10-00, AMM 05-14-03										
051404	PHASE D4 2400 HOUR CHECKS								Package	ATA:05
	MOS	25-Nov-19	96		25-Nov-27		548 d			
	HRS	8177.7	2400		10577.7		554.6			
	AFL	6303								
PROC. REF: AMM 05-10-00, AMM 05-14-04 PROC. REF: AMM 05-10-00, AMM 05-14-04										
051405	PHASE D5 2400 HOUR CHECKS								Package	ATA:05
	MOS	25-Nov-19	96		25-Nov-27		548 d			
	HRS	8177.7	2400		10577.7		554.6			
	AFL	6303								
PROC. REF: AMM 05-10-00, AMM 05-14-05 PROC. REF: AMM 05-10-00, AMM 05-14-05										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS										
051406	PHASE D6 2400 HOUR CHECKS								Package	ATA:05
	MOS	25-Nov-19	96		25-Nov-27		548 d			
	HRS	8177.7	2400		10577.7		554.6			
	AFL	6303								
PROC. REF: AMM 05-10-00, AMM 05-14-06 PROC. REF: AMM 05-10-00, AMM 05-14-06										
PKG:24										
051500	4800 HOUR CHECKS								Package	ATA:05
	MOS	22-Jun-23								
	HRS	9258.5	4800		14058.5		4035.4			
	AFL	7100								
PROC. REF: AMM 05-15-00, AMM 05-10-00 PROC. REF: AMM 05-15-00, AMM 05-10-00										
PKG:25										
051600	9600 HOUR CHECKS								Package	ATA:05
	MOS	02-Aug-24								
	HRS	9525.7	9600		19125.7		9102.6			
	AFL	7276								
PROC. REF: AMM 05-16-00, AMM 05-10-00 PROC. REF: AMM 05-16-00, AMM 05-10-00										
PKG:26										
051700	MAJOR LANDING GEAR INSPECTION								Package	ATA:05
	MOS	09-Mar-01								
	HRS	0								
	AFL	0	10000		10000		2384			
PROC. REF: AMM 05-17-00, AMM 05-10-00 PROC. REF: AMM 05-17-00, AMM 05-10-00										
PKG:27										
057110	NO. 1 ENGINE - 150 TO 250 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS								Package	ATA:05
	MOS	28-Jul-25								
	HRS	9706.3	250		(9956.3) 9984.6		OVD			
	ENC	7396								
PROC. REF: LMM 72-00-00 PROC. REF: LMM 72-00-00										

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty		
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS											
057110			NO. 2 ENGINE - 150 TO 250 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							Package	ATA:05
	MOS	28-Jul-25									
	HRS	8867.6	250		(9117.6) 9984.6		OVD				
	ENC	7292									
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00											
057120			NO. 1 ENGINE - 300 TO 440 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							Package	ATA:05
	MOS/MSC	22-Jun-23	N/A								
	HRS	9184.4									
	ENC	7042									
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00											
057120			NO. 2 ENGINE - 300 TO 440 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							Package	ATA:05
	MOS/MSC	18-Aug-22	N/A								
	HRS	8169.8									
	ENC	6832									
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00											
057130			NO. 1 ENGINE - 500 TO 650 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							Package	ATA:05
	MOS	21-Aug-25									
	HRS	9735.7	600		(10335.7) 10364		340.9				
	ENC	7413									
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00											
057130			NO. 2 ENGINE - 500 TO 650 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							Package	ATA:05
	MOS	21-Aug-25									
	HRS	8897	600		(9497) 10364		340.9				
	ENC	7309									
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS										
057140		NO. 1 ENGINE - 500 TO 850 HOUR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							Package	ATA:05
	MOS	21-Aug-25								
	HRS	9735.7	800		(10535.7) 10564		540.9			
	ENC	7413								
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00										
057140		NO. 2 ENGINE - 500 TO 850 HOUR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							Package	ATA:05
	MOS	21-Aug-25								
	HRS	8897	800		(9697) 10564		540.9			
	ENC	7309								
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00										
057150		NO. 1 ENGINE - 1000 TO 1300 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							Package	ATA:05
	MOS	27-Oct-25								
	HRS	9832.1	1200		(11032.1) 11060.4		1037.3			
	ENC	7480								
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00										
057150		NO. 2 ENGINE - 1000 TO 1300 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							Package	ATA:05
	MOS	27-Oct-25								
	HRS	8993.4	1200		(10193.4) 11060.4		1037.3			
	ENC	7376								
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00										
057160		NO. 1 ENGINE - 1500 TO 1650 HOUR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							Package	ATA:05
	MOS	22-Jun-23								
	HRS	9184.4	1600		(10784.4) 10812.7		789.6			
	ENC	7042								
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS										
057160		NO. 2 ENGINE - 1500 TO 1650 HOUR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							Package	ATA:05
	MOS	18-Aug-22								
	HRS	8169.8	1600		(9769.8) 10636.8		613.7			
	ENC	6832								
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00										
5-50-00-02		PERFORM UNSCHEDULED MAINTENANCE CHECK - OVERWEIGHT LANDING (WEIGHT IN EXCESS OF MAXIMUM LANDING WEIGHT)							Service	ATA:05
	MOS/MSC		A/R							
	HRS									
	AFL									
PROC. REF: AMM 05-50-00PROC. REF: AMM 05-50-00										
5-50-00-03		PERFORM UNSCHEDULED MAINTENANCE CHECK - HARD LANDING							Service	ATA:05
	MOS/MSC		A/R							
	HRS									
	AFL									
PROC. REF: AMM 05-50-00PROC. REF: AMM 05-50-00										
5-50-00-09		PERFORM UNSCHEDULED MAINTENANCE CHECK - LIGHTNING STRIKE INSPECTION							Service	ATA:05
	MOS/MSC	09-Mar-01	A/R							
	HRS	0								
	AFL	0								
PROC. REF: AMM 05-50-00PROC. REF: AMM 05-50-00										
5-50-00-18		PERFORM UNSCHEDULED MAINTENANCE CHECK - FOREIGN OBJECT DAMAGE							Service	ATA:05
	MOS/MSC		O/C							
	HRS									
	AFL									
PROC. REF: AMM 05-50-00PROC. REF: AMM 05-50-00										
5-50-00-18.1		PERFORM UNSCHEDULED MAINTENANCE CHECK - FOREIGN OBJECT DAMAGE (BIRD STRIKE)							Service	ATA:05
	MOS/MSC		A/R							
	HRS									
	AFL									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS										
5-50-00-19	PERFORM UNSCHEDULED MAINTENANCE CHECK - ENGINE VIBRATION INDICATION								Service	ATA:05
	MOS/MSC		A/R							
	HRS									
	AFL									
PROC. REF: AMM 05-50-00PROC. REF: AMM 05-50-00										
ATA 08 - LEVELING AND WEIGHING										
082000	WEIGH AIRCRAFT								Service	ATA:08
	MOS	30-Dec-22	36		RTS					
	HRS	9186.7								
	AFL	7047								
PROC. REF: AMM 08-10-00, FAR FAR 135.185PROC. REF: AMM 08-10-00, FAR FAR 135.185										
ATA 11 - PLACARDS AND MARKINGS										
G1130000 ^S	CHECK BRIGHTNESS LEVEL OF ALL SELF-LUMINOUS PLACARDS								Service	ATA:11
	MOS	09-Mar-01	48							
	HRS	0	1200							
	AFL	0								
PROC. REF: AMM 11-30-00PROC. REF: AMM 11-30-00										
ATA 12 - SERVICING										
AB1210060 ^S	MAIN LANDING GEAR UPLOCK ACTUATOR - LUBRICATE								Service	ATA:12
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01										
O1210002 ^S	FLAP ACTUATORS - CHECK OIL LEVEL								Service	ATA:12
	MOS	02-Aug-24	24							
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 12 - SERVICING									
Q1221064 LEFT INBOARD FLAP ACTUATOR JOINT - APPLY CORROSION PREVENTIVE COMPOUND (CPC) Service ATA:12									
	MOS/MSC	05-Dec-19	N/A						
	HRS	8177.8							
	AFL	6304							
PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03									
Q1221064 LEFT OUTBOARD FLAP ACTUATOR JOINT - APPLY CORROSION PREVENTIVE COMPOUND (CPC) Service ATA:12									
	MOS/MSC	05-Dec-19	N/A						
	HRS	8177.8							
	AFL	6304							
PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03									
Q1221064 RIGHT INBOARD FLAP ACTUATOR JOINT - APPLY CORROSION PREVENTIVE COMPOUND (CPC) Service ATA:12									
	MOS/MSC	05-Dec-19	N/A						
	HRS	8177.8							
	AFL	6304							
PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03									
Q1221064 RIGHT OUTBOARD FLAP ACTUATOR JOINT - APPLY CORROSION PREVENTIVE COMPOUND (CPC) Service ATA:12									
	MOS/MSC	05-Dec-19	N/A						
	HRS	8177.8							
	AFL	6304							
PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03									
T1222004 NO. 1 MAIN BATTERY - LEAD-ACID BATTERIES - PERFORM BATTERY CAPACITY CHECK Service ATA:12									
PN:RG-380E/40L	MOS	21-Aug-25	6		21-Feb-26		OVD		
SN:41180857	HRS	9809.8	500		10309.8		286.7		
	AFL	7471							
PROC. REF: AMM 12-22-00, CMM 24-30-71PROC. REF: AMM 12-22-00, CMM 24-30-71									
T1222004 NO. 2 MAIN BATTERY - LEAD-ACID BATTERIES - PERFORM BATTERY CAPACITY CHECK Service ATA:12									
PN:RG-380E/40L	MOS	21-Aug-25	6		21-Feb-26		OVD		
SN:41180858	HRS	9809.8	500		10309.8		286.7		
	AFL	7471							
PROC. REF: AMM 12-22-00, CMM 24-30-71PROC. REF: AMM 12-22-00, CMM 24-30-71									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 12 - SERVICING										
U1210004	FLAP FLEXIBLE TRANSMISSION SHAFTS - HAND LUBRICATE								Service	ATA:12
	MOS	12-Aug-15								
	HRS	7535.1	4800		12335.1		2312			
	AFL	5764								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
Y1210000 ^S	NOSE LANDING GEAR SHOCK STRUT - CHECK FOR PROPER FLUID LEVEL AND INFLATION PRESSURE								Service	ATA:12
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 12-10-02PROC. REF: AMM 12-10-02										
Y1210001 ^S	MAIN LANDING GEAR SHOCK STRUTS - CHECK FOR PROPER FLUID LEVEL AND INFLATION PRESSURE								Service	ATA:12
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 12-10-03PROC. REF: AMM 12-10-03										
Y1210003 ^S	FLAP ACTUATOR BALLNUT - LUBRICATE								Service	ATA:12
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03										
Y1210005 ^S	NOSE LANDING GEAR TRUNNION PIN - LUBRICATE								Service	ATA:12
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 12 - SERVICING										
Y1210006	^S	NOSE LANDING GEAR ACTUATOR ATTACH FITTING - LUBRICATE						Service	ATA:12	
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01										
Y1210007	^S	NOSE AND MAIN TIRES - CHECK FOR PROPER INFLATION						Service	ATA:12	
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 12-10-04PROC. REF: AMM 12-10-04										
Y1210009	^S	NOSE GEAR DOOR HINGE - LUBRICATE						Service	ATA:12	
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02										
Y1210011	^S	MAIN LANDING GEAR ACTUATOR JOINTS - LUBRICATE						Service	ATA:12	
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01										
Y1210012	^S	MAIN LANDING GEAR AXLE BEAM/PISTON JOINTS - LUBRICATE						Service	ATA:12	
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 12 - SERVICING										
Y1210013 ^S			MAIN LANDING GEAR TORQUE LINKS - LUBRICATE						Service	ATA:12
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01										
Y1210014 ^S			MAIN LANDING GEAR DOOR HINGE - LUBRICATE						Service	ATA:12
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02										
Y1210016 ^S			PASSENGER/CREW DOOR HINGE - LUBRICATE						Service	ATA:12
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02										
Y1210017 ^S			PASSENGER/CREW DOOR PINS - LUBRICATE						Service	ATA:12
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02										
Y1210018 ^S			PASSENGER/CREW DOOR TENSION BOLTS - LUBRICATE						Service	ATA:12
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 12 - SERVICING										
Y1210019 ^S	EMERGENCY EXIT DOOR LATCHING MECHANISM - LUBRICATE								Service	ATA:12
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02										
Y1210020 ^S	EMERGENCY EXIT DOOR PINS - LUBRICATE								Service	ATA:12
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02										
Y1210021 ^S	BAGGAGE COMPARTMENT DOOR LATCH PINS - LUBRICATE								Service	ATA:12
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02										
Y1210022 ^S	BAGGAGE COMPARTMENT DOOR HINGE - LUBRICATE								Service	ATA:12
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02										
Y1210023 ^S	OXYGEN SYSTEM SERVICING DOOR HINGE - LUBRICATE								Service	ATA:12
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 12 - SERVICING										
Y1210024	^S	TOILET SERVICING DOOR HINGE - LUBRICATE							Service	ATA:12
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02										
PKG:4										
Y1210025	^S	PRESSURE REFUELING STATION DOOR HINGE - LUBRICATE							Service	ATA:12
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02										
PKG:2										
Y1210026	^S	FUSELAGE FUEL FILLER DOOR HINGE - LUBRICATE							Service	ATA:12
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02										
PKG:2										
Y1210027	^S	TAILCONE ACCESS DOOR PINS - LUBRICATE							Service	ATA:12
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02										
PKG:6										
Y1210028	^S	TAILCONE ACCESS DOOR HINGE - LUBRICATE							Service	ATA:12
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02										
PKG:6										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 12 - SERVICING

Y1210029 ^S	MAIN LANDING GEAR TRUNNION PIN - LUBRICATE							Service	ATA:12
	MOS	21-Aug-25	12						
	HRS	9809.8	300						
	AFL	7471							
PKG:5									
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01									

Y1221037 ^S	FLAPS - LUBRICATE ROLLING SURFACES OF MAIN AND NOSE ROLLER TRACKS							Service	ATA:12
	MOS	21-Aug-25	12						
	HRS	9809.8	300						
	AFL	7471							
PKG:4									
PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03									

Y1221042 ^S	HORIZONTAL STABILIZER UPPER AND LOWER TORQUE LINKS - LUBRICATE							Service	ATA:12
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PKG:9									
PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03									

Y1227000 ^S	EMERGENCY PARK BRAKE HANDLE SHAFT - LUBRICATE							Service	ATA:12
	MOS	21-Aug-25	12						
	HRS	9809.8	300						
	AFL	7471							
PKG:1									
PROC. REF: AMM 12-27-00PROC. REF: AMM 12-27-00									

ATA 21 - AIR CONDITIONING

211001	SERVO AIR PRESSURE REGULATING VALVE							Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-15-01PROC. REF: AMM 36-15-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 21 - AIR CONDITIONING										
211011		LEFT PLENUM CHECK VALVE						Component	ATA:21	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-20-09PROC. REF: AMM 21-20-09										
211012		RIGHT PLENUM CHECK VALVE						Component	ATA:21	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-20-09PROC. REF: AMM 21-20-09										
211017		LEFT EMERGENCY PRESSURIZATION ISOLATION CHECK VALVE						Component	ATA:21	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-20-03PROC. REF: AMM 21-20-03										
211018		RIGHT EMERGENCY PRESSURIZATION ISOLATION CHECK VALVE						Component	ATA:21	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-20-03PROC. REF: AMM 21-20-03										
212001		COCKPIT AIR CHECK VALVE						Component	ATA:21	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-20-01PROC. REF: AMM 21-20-01										
212007		AFT BLOWER MOTOR						Component	ATA:21	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-51-09PROC. REF: AMM 21-51-09										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 21 - AIR CONDITIONING										
212008		FORWARD BLOWER MOTOR						Component	ATA:21	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
212011		LINEAR ELECTRO-MECHANICAL ACTUATOR						Component	ATA:21	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
212041		NO. 1 ENGINE OZONE CONVERTER						Component	ATA:21	
PN:4520000100-801	MOS/MSC	01-Apr-22	O/C	TSN 0						
SN:2298	HRS	8936.8	TSN 0							
	AFL	6867	TSN 0							
PROC. REF: AMM 21-20-12PROC. REF: AMM 21-20-12										
212042		NO. 2 ENGINE OZONE CONVERTER						Component	ATA:21	
PN:4520000100-801	MOS/MSC	01-Apr-22	O/C	TSN 0						
SN:2305	HRS	8936.8	TSN 0							
	AFL	6867	TSN 0							
PROC. REF: AMM 21-20-12PROC. REF: AMM 21-20-12										
212101		NO. 1 THERMAL CONTROL ACTUATOR						Component	ATA:21	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
212102		NO. 2 THERMAL CONTROL ACTUATOR						Component	ATA:21	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
212105 LEFT ENVIRONMENTAL CONTROL SYSTEM TRANSITION DUCT									Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
212106 RIGHT ENVIRONMENTAL CONTROL SYSTEM TRANSITION DUCT									Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
212201 LEFT GASPER AIR CHECK VALVE									Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-20-07PROC. REF: AMM 21-20-07									
212202 RIGHT GASPER AIR CHECK VALVE									Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-20-07PROC. REF: AMM 21-20-07									
212213 LEFT CABIN AIR CHECK VALVE									Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-20-02PROC. REF: AMM 21-20-02									
212214 RIGHT CABIN AIR CHECK VALVE									Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-20-02PROC. REF: AMM 21-20-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
212801 AVIONICS COOLING FAN MOUNT									Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-21-01PROC. REF: AMM 21-21-01									
213000 CABIN PRESSURE CONTROLLER									Component ATA:21
PN:6628408000-023 (10551B08Y09)	MOS/MSC	17-Feb-05	O/C	TSR 0					
SN:0716	HRS	3300.2		TSR 0					
	AFL	2515		TSR 0					
PROC. REF: AMM 21-30-03PROC. REF: AMM 21-30-03									
213001 LEFT EMERGENCY PRESSURE SHUTOFF VALVE									Component ATA:21
PN:3291224-1	MOS/MSC	03-Dec-09	O/C						
SN:133	HRS	6212.8							
	AFL	4758							
PROC. REF: AMM 21-31-01PROC. REF: AMM 21-31-01									
213002 RIGHT EMERGENCY PRESSURE SHUTOFF VALVE									Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-31-01PROC. REF: AMM 21-31-01									
213021 JET PUMP EJECTOR									Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-30-06PROC. REF: AMM 21-30-06									
213031 PRIMARY OUTFLOW VALVE									Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-30-01PROC. REF: AMM 21-30-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 21 - AIR CONDITIONING										
213032	SECONDARY OUTFLOW VALVE								Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-30-02PROC. REF: AMM 21-30-02										
<hr/>										
213055	EMERGENCY PRESSURE ANEROID SWITCH								Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
<hr/>										
213056	ABSOLUTE PRESSURE SWITCH								Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
<hr/>										
213101	TAILCONE CHECK VALVE								Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
<hr/>										
213110	CABIN PRESSURIZATION CHECK VALVE								Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-30-07PROC. REF: AMM 21-30-07										
<hr/>										
214301	FOOT WARMER THERMOSTAT (S167)								Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-41-02PROC. REF: AMM 21-41-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
215001 WATER SEPARATOR ASSEMBLY									Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-50-03PROC. REF: AMM 21-50-03									
215002 WATER SEPARATOR BYPASS VALVE									Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
215010 AIR CYCLE MACHINE PRECOOLER ASSEMBLY									Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-50-08PROC. REF: AMM 21-50-08									
215013 PACK BI-LEVEL PRESURE REGULATOR SHUTOFF VALVE									Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-50-02PROC. REF: AMM 21-50-02									
215015 AIR CYCLE MACHINE BYPASS CHECK VALVE									Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-50-07PROC. REF: AMM 21-50-07									
215019 CABIN REFRIGERATION CONDENSER									Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-51-04PROC. REF: AMM 21-51-04									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 21 - AIR CONDITIONING										
215030	ENVIRONMENTAL CONTROL UNIT								Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-50-01PROC. REF: AMM 21-50-01										
<hr/>										
215033	AIR CYCLE MACHINE								Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-50-04PROC. REF: AMM 21-50-04										
<hr/>										
215036	PRIMARY, SECONDARY HEAT EXCHANGER								Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
<hr/>										
215039	AIR CYCLE MACHINE TURBINE								Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-50-04PROC. REF: AMM 21-50-04										
<hr/>										
215043	AFT EVAPORATOR								Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-51-09PROC. REF: AMM 21-51-09										
<hr/>										
215044	FORWARD EVAPORATOR								Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-51-07PROC. REF: AMM 21-51-07										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 21 - AIR CONDITIONING										
215100 AIR CONDITIONING COMPRESSOR									Component	ATA:21
PN:JBS222-1	MOS/MSC	26-Jul-23	O/C	TSO 0						
SN:K18869	HRS	9278		TSO 0						
	AFL	7111		TSO 0						
PROC. REF: AMM 21-51-01PROC. REF: AMM 21-51-01										
215101 AIR CONDITIONING COMPRESSOR DRIVE MOTOR									Component	ATA:21
PN:MB86B-6	MOS/MSC	31-Jul-23	O/C	TSO 0						
SN:234	HRS	9282.8		TSO 0						
	AFL	7113		TSO 0						
PROC. REF: AMM 21-51-02PROC. REF: AMM 21-51-02										
216001 ENVIRONMENTAL CONTROL SYSTEM - INTEGRATED TEMPERATURE CONTROLLER									Component	ATA:21
PN:1151830-3	MOS/MSC	04-Jan-21	O/C							
SN:1151830-00815	HRS	8361.7								
	AFL	6425								
PROC. REF: AMM 21-60-10PROC. REF: AMM 21-60-10										
216014 COCKPIT TEMPERATURE CONTROL VALVE									Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-60-04, AMM 21-60-05PROC. REF: AMM 21-60-04, AMM 21-60-05										
216015 CABIN TEMPERATURE CONTROL VALVE									Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-60-04PROC. REF: AMM 21-60-04										
216025 COCKPIT TEMPERATURE CONTROL SELECTOR									Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-60-01PROC. REF: AMM 21-60-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
216026 CABIN TEMPERATURE CONTROL SELECTOR									Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-60-01PROC. REF: AMM 21-60-01									
216036 COCKPIT DUCT OVERHEAT THERMOSTAT									Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-60-09PROC. REF: AMM 21-60-09									
216037 CABIN DUCT OVERHEAT THERMOSTAT									Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-60-08PROC. REF: AMM 21-60-08									
216040 28VDC CABIN TEMPERATURE SENSOR/FAN ASSEMBLY									Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-60-03PROC. REF: AMM 21-60-03									
216049 CABIN DUCT OVERTEMP LIMITER									Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-60-06PROC. REF: AMM 21-60-06									
216071 LOW LIMIT TEMPERATURE CONTROL VALVE									Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 21 - AIR CONDITIONING										
216074	SERVO AIR PRESSURE REGULATING VALVE								Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 36-15-01PROC. REF: AMM 36-15-01										
216081	COCKPIT DUCT TEMPERATURE SENSOR								Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 21-60-07PROC. REF: AMM 21-60-07										
216083	COCKPIT TEMPERATURE SENSOR								Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 21-60-02PROC. REF: AMM 21-60-02										
216084	CABIN LOW LIMIT TEMPERATURE SENSOR								Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 21-50-09PROC. REF: AMM 21-50-09										
5-19-00-L2150054	WEAR INSPECTION - AIR CONDITIONING COMPRESSOR DRIVE MOTOR BRUSHES - PERFORM WEAR INSPECTION (RETURN DRIVE MOTOR TO AUTHORIZED SERVICE FACILITY FOR OVERHAUL)								Service	ATA:21
	MOS/MSC	31-Jul-23	N/A	NOT INSTALLED						
	HRS	9282.8								
	AFL	7113								
5-19-00-L2150055	OVERHAUL - AIR CONDITIONING COMPRESSOR MOTOR - PERFORM OVERHAUL (RETURN DRIVE MOTOR TO AUTHORIZED SERVICE FACILITY FOR OVERHAUL)								Service	ATA:21
	MOS/MSC	22-Jun-23	-	NOT INSTALLED						
	HRS	9258.5								
	AFL	7100								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
J2160007 ^S	TEMPERATURE CONTROL SYSTEM - INSPECT AND CLEAN CABIN AND COCKPIT TEMPERATURE CONTROL VALVE SERVO AIR FILTERS							Service	ATA:21
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PKG:8									
PROC. REF: AMM 21-60-11PROC. REF: AMM 21-60-11									
L2150054	AIR CONDITIONING COMPRESSOR DRIVE MOTOR BRUSHES - PERFORM WEAR INSPECTION							Service	ATA:21
PN:MB86B-6	MOS	31-Jul-23							
SN:234	HRS	9282.8							
	AFL	7113							
	ACH	2596.2	600		3196.2		504.6		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
L2150055	AIR CONDITIONING COMPRESSOR DRIVE MOTOR - PERFORM OVERHAUL							Service	ATA:21
PN:MB86B-6	MOS	31-Jul-23							
SN:234	HRS	9282.8							
	AFL	7113							
	ACH	2596.2	1200		3796.2		1104.6		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
L2150057 ^S	** AUXILIARY HEAT SYSTEM - PERFORM AUXILIARY HEATER ELECTRICAL AND TEMPERATURE SWITCH TEST							Service	ATA:21
	MOS	09-Mar-01	48					AIRWORTHINESS	
	HRS	0	1200						
	AFL	0							
PKG:14									
PROC. REF: AMM 21-51-00PROC. REF: AMM 21-51-00									
O2130000 ^S	PRIMARY AND SECONDARY OUTFLOW VALVES - PERFORM INSPECTION							Service	ATA:21
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PKG:13									
PROC. REF: AMM 21-30-01, AMM 21-30-02PROC. REF: AMM 21-30-01, AMM 21-30-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 21 - AIR CONDITIONING										
Q2130001 ^S	OUTFLOW VALVE AIR FILTER - REMOVE AND REPLACE								Service	ATA:21
	MOS	25-Nov-19	96							
	HRS	8177.7	2400							
	AFL	6303								
PROC. REF: AMM 21-30-04PROC. REF: AMM 21-30-04										
Q2130002 ^S	** PRESSURIZATION CONTROL SYSTEM - PERFORM FUNCTIONAL TEST. (AWL**)								Service	ATA:21
	MOS	09-Mar-01	48					AIRWORTHINESS		
	HRS	0	1200							
	AFL	0								
PROC. REF: AMM 21-30-00PROC. REF: AMM 21-30-00										
Y2130003 ^S	PRESSURIZATION CONTROL SYSTEM - PERFORM OPERATIONAL CHECK								Service	ATA:21
	MOS	02-Aug-24	24							
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 21-30-00PROC. REF: AMM 21-30-00										
Y2130065	CABIN PRESSURIZATION SYSTEM - PERFORM CABIN LEAKAGE TEST								Service	ATA:21
	MOS	22-Jun-23								
	HRS	9258.5	1200		10458.5		435.4			
	AFL	7100								
PROC. REF: AMM 21-30-00PROC. REF: AMM 21-30-00										
Y2140000 ^S	AIR CYCLE MACHINE HEAT EXCHANGER INLET - PERFORM VISUAL INSPECTION								Service	ATA:21
	MOS	09-Mar-01	48							
	HRS	0	1200							
	AFL	0								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 21 - AIR CONDITIONING										
Y2140001	NO. 1 ENGINE OZONE CONVERTER - PERFORM CLEANING AND EFFICIENCY TEST								Service	ATA:21
PN:4520000100-801	MOS	01-Apr-22								
SN:2298	HRS	8936.8	3600		12536.8		2513.7			
	AFL	6867								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
Y2140001	NO. 2 ENGINE OZONE CONVERTER - PERFORM CLEANING AND EFFICIENCY TEST								Service	ATA:21
PN:4520000100-801	MOS	01-Apr-22								
SN:2305	HRS	8936.8	3600		12536.8		2513.7			
	AFL	6867								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
Y2141000 ^S	ENVIRONMENTAL CONTROL UNIT - PERFORM VISUAL INSPECTION								Service	ATA:21
	MOS	09-Mar-01	48							
	HRS	0	1200							
	AFL	0								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
Y2141001 ^S	WATER SEPARATOR COALESCER BAG - PERFORM VISUAL INSPECTION. CLEAN IF NECESSARY.								Service	ATA:21
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
Y2141002	WATER SEPARATOR COALESCER BAG - REPLACE								Service	ATA:21
	MOS/MSC	09-Mar-01	O/C							
	HRS	0								
	AFL	0								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
Y2142000 ^S	BAGGAGE COMPARTMENT HEATING SYSTEM - PERFORM FUNCTIONAL TEST								Service	ATA:21
	MOS	25-Nov-19	96							
	HRS	8177.7	2400							
	AFL	6303								

PKG:14

PKG:2

PKG:20

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 21 - AIR CONDITIONING

PROC. REF: AMM 21-40-00PROC. REF: AMM 21-40-00

Y2145000 ^S	ECS PLENUM ASSEMBLY CHECK VALVES - PERFORM VISUAL INSPECTION. VERIFY FREEDOM OF MOVEMENT OF BUTTERFLY ASSEMBLY.							Service	ATA:21
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							

PKG:14

PROC. REF: AMM 21-20-03, AMM 21-20-09PROC. REF: AMM 21-20-03, AMM 21-20-09

Y2150058 ^S	PERFORM VISUAL INSPECTION OF AIR CONDITIONING SYSTEM COMPONENTS, INCLUDING COMPRESSOR MOTOR BELT FOR WEAR AND PROPER V-BELT TENSION, CONDENSER COILS FOR CLEANLINESS AND HOSES FOR CHAFING AND WEAR. IF OIL LEAKS ARE VISIBLE AND/OR REFRIGERANT DUMPED, CHECK COMPRESSOR OIL LEVEL. SOME LEAKAGE IS ALLOWABLE AROUND SHAFT.							Service	ATA:21
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							

PKG:14

PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00

Y2150059 ^S	AIR CONDITIONING SYSTEM - PERFORM LOAD SHED ASSEMBLY CHECK							Service	ATA:21
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							

PKG:14

PROC. REF: AMM 21-51-00PROC. REF: AMM 21-51-00

ATA 22 - AUTO FLIGHT

2210-RVSM	FLIGHT CHECK AUTOMATIC ALTITUDE HOLD FUNCTIONAL. RVSM COMPLIANT AIRCRAFT.							Service	ATA:22
	MOS/MSC	09-Mar-01	N/R						
	HRS	0							
	AFL	0							

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

221001	AUTOPILOT FLIGHT GUIDANCE CONTROLLER							Component	ATA:22
PN:7021170-901	MOS/MSC	25-Jan-19	O/C						
SN:05111601	HRS	8026.4							
	AFL	6168							

PROC. REF: AMM 22-10-01PROC. REF: AMM 22-10-01

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 22 - AUTO FLIGHT									
221041 AUTOPILOT ROLL SERVO									Component ATA:22
PN:PN 4006719-948	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 22-10-04PROC. REF: AMM 22-10-04									
221045 AUTOPILOT ROLL SERVO BRACKET									Component ATA:22
PN:PN 4005842	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 22-10-05PROC. REF: AMM 22-10-05									
221051 AUTOPILOT PITCH SERVO									Component ATA:22
PN:PN 4006719-908	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 22-10-02PROC. REF: AMM 22-10-02									
221055 AUTOPILOT PITCH SERVO BRACKET									Component ATA:22
PN:PN 4005842	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 22-10-03PROC. REF: AMM 22-10-03									
221061 AUTOPILOT YAW SERVO									Component ATA:22
PN:PN 7012919-903	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 22-10-06PROC. REF: AMM 22-10-06									
221065 AUTOPILOT YAW SERVO BRACKET									Component ATA:22
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 22-10-07PROC. REF: AMM 22-10-07									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 22 - AUTO FLIGHT

225001		YAW INTERFACE UNIT						Component	ATA:22
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 22-50-01PROC. REF: AMM 22-50-01									

225031		PILOT RUDDER BOOST SYSTEM YAW FORCE SENSOR						Component	ATA:22
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 22-50-02PROC. REF: AMM 22-50-02									

225032		COPILOT RUDDER BOOST SYSTEM YAW FORCE SENSOR						Component	ATA:22
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 22-50-02PROC. REF: AMM 22-50-02									

A2210033 ^S		** AUTOPILOT SYSTEM - PERFORM AUTOPILOT DISCONNECT TONE TEST						Service	ATA:22
	MOS	02-Aug-24	24				AIRWORTHINESS		
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 22-10-00PROC. REF: AMM 22-10-00									

PKG:7

G2210030 ^S		PITCH SERVO CABLES - PERFORM CABLE TENSION CHECK						Service	ATA:22
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 22-10-03PROC. REF: AMM 22-10-03									

PKG:14

G2210031 ^S		ROLL SERVO CABLES - PERFORM CABLE TENSION CHECK						Service	ATA:22
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 22-10-05PROC. REF: AMM 22-10-05									

PKG:13

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 22 - AUTO FLIGHT

G2210032 ^S		YAW SERVO CABLES - PERFORM CABLE TENSION CHECK						Service	ATA:22
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PKG:14									
PROC. REF: AMM 22-10-07PROC. REF: AMM 22-10-07									

ATA 23 - COMMUNICATIONS

230001		UNILINK PROCESSOR						Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

230002		CONFIGURATION MODULE						Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

231011		NO. 1 POWER AMPLIFIER/HF ANTENNA COUPLER						Component	ATA:23
PN:064-1017-01	MOS/MSC	12-Feb-08	O/C						
SN:17280	HRS	5965.9							
	AFL	4561							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

231012		NO. 2 POWER AMPLIFIER/HF ANTENNA COUPLER						Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

231021		NO. 1 VHF COMMUNICATIONS TRANSCEIVER UNIT						Component	ATA:23
PN:7510733-616	MOS/MSC	11-May-18	O/C						
SN:98093272	HRS	7850.8							
	AFL	6024							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 23 - COMMUNICATIONS

PROC. REF: AMM 23-11-01PROC. REF: AMM 23-11-01

231021A	TEST/INSPECT ATC TRANSPONDER							Service	ATA:23
	MOS	10-Aug-24	24		10-Aug-26		76 d		
	HRS								
	AFL								
		Calibration Date: : 10-Aug-24							
	PROC. REF: AMM 23-11-00, FAR FAR 91.413PROC. REF: AMM 23-11-00, FAR FAR 91.413								

231022	NO. 2 VHF COMMUNICATIONS TRANSCEIVER UNIT							Component	ATA:23
PN:7510733-616	MOS/MSC	13-Apr-17	O/C						
SN:99054063	HRS	7744.3							
	AFL	5922							
	PROC. REF: AMM 23-11-01, FAR FAR 91.413PROC. REF: AMM 23-11-01, FAR FAR 91.413								

231022A	TEST/INSPECT ATC TRANSPONDER							Service	ATA:23
	MOS	10-Aug-24	24		10-Aug-26		76 d		
	HRS								
	AFL								
		Calibration Date: : 10-Aug-24							
	PROC. REF: AMM 23-11-00, FAR FAR 91.413PROC. REF: AMM 23-11-00, FAR FAR 91.413								

231030	NO. 1 HF SELECTIVE CALLING (SELCAL) RECEIVER/EXCITER							Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
	PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

231031	NO. 2 HF SELECTIVE CALLING (SELCAL) RECEIVER/EXCITER							Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
	PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 23 - COMMUNICATIONS										
231032		HF SELECTIVE CALLING (SELCAL) ANTENNA						Component	ATA:23	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
231033		UPPER VHF ANTENNA						Component	ATA:23	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-11-02PROC. REF: AMM 23-11-02										
231034		LOWER VHF ANTENNA						Component	ATA:23	
PN:DMC60-17-1	MOS/MSC	16-Jul-19	O/C	TSN 0						
SN:18936	HRS	8109		TSN 0						
	AFL	6239		TSN 0						
PROC. REF: AMM 23-11-02PROC. REF: AMM 23-11-02										
231045		NO. 1 HF CONTROL (MODEL KCU-951)						Component	ATA:23	
PN:064-1016-03	MOS/MSC	25-Feb-08	O/C							
SN:11903	HRS	5974.6								
	AFL	4566								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
231046		NO. 2 HF CONTROL (MODEL KCU-951)						Component	ATA:23	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
231051		NO. 1 HF BRIDGING AMPLIFIER						Component	ATA:23	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 23 - COMMUNICATIONS										
231052		NO. 2 HF BRIDGING AMPLIFIER						Component	ATA:23	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
231090		PILOT HEADSET						Component	ATA:23	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
231091		COPILOT HEADSET						Component	ATA:23	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
231300		MAGNASTAR PHONE TRANSCEIVER						Component	ATA:23	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
231305		MAGNASTAR ANTENNA						Component	ATA:23	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
231307		COCKPIT PHONE						Component	ATA:23	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 23 - COMMUNICATIONS										
231308		CABIN PHONE						Component	ATA:23	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
231310		ARTU TRAY						Component	ATA:23	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
231313		NO. 1 CABIN DISTRIBUTION BUS REPEATER						Component	ATA:23	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
231314		NO. 2 CABIN DISTRIBUTION BUS REPEATER						Component	ATA:23	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
231315		CALL ALERTER SWITCH (CAS)						Component	ATA:23	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
231320		NO. 1 CABIN IRIDIUM SATCOM HANDSET						Component	ATA:23	
PN:P12248-003	MOS/MSC	12-Feb-08	O/C	TSN 0						
SN:UNKNOWN	HRS	5965.9		TSN 0						
	AFL	4561		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 23 - COMMUNICATIONS										
231321		NO. 2 CABIN IRIDIUM SATCOM HANDSET						Component	ATA:23	
PN:P12192-002	MOS/MSC	12-Feb-08	O/C	TSN 0						
SN:UNKNOWN	HRS	5965.9		TSN 0						
	AFL	4561		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
231322		CABIN IRIDIUM SATCOM PHONE CRADLE						Component	ATA:23	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
231323		IRIDIUM SATCOM TRANSCEIVER						Component	ATA:23	
PN:P12023	MOS/MSC	12-Feb-08	O/C							
SN:1202310876	HRS	5965.9								
	AFL	4561								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
231325		IRIDIUM SATCOM SONALERT						Component	ATA:23	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
231327		COCKPIT IRIDIUM SATCOM PHONE CRADLE						Component	ATA:23	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
231328		COCKPIT IRIDIUM SATCOM HANDSET						Component	ATA:23	
PN:P12192-002	MOS/MSC	12-Feb-08	O/C	TSN 0						
SN:UNKNOWN	HRS	5965.9		TSN 0						
	AFL	4561		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 23 - COMMUNICATIONS										
231330		FORWARD IRIDIUM SATCOM ANTENNA						Component	ATA:23	
PN:S67-1575-165	MOS/MSC	12-Feb-08	O/C							
SN:449-2303	HRS	5965.9								
	AFL	4561								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
231335		COCKPIT IRIDIUM SATCOM BASE UNIT						Component	ATA:23	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
233001		FORWARD CABIN VIDEO MONITOR						Component	ATA:23	
PN:AL-LCD104-04-1	MOS/MSC	06-Aug-06	O/C							
SN:120000638	HRS	4725.85								
	AFL	3628								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
233002		AFT CABIN VIDEO MONITOR						Component	ATA:23	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
233003		AUDIO DISTRIBUTION MODULE						Component	ATA:23	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
233005		PUBLIC ADDRESS SYSTEM AMPLIFER						Component	ATA:23	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-30-02PROC. REF: AMM 23-30-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 23 - COMMUNICATIONS										
233010		INFRARED REMOTE RECEIVER MODULE						Component	ATA:23	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
233015		AUDIO/VIDEO CONTROLLER						Component	ATA:23	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
233053		DVD PLAYER						Component	ATA:23	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
233054		CD PLAYER CHANGER						Component	ATA:23	
PN:MCD-102-RU-3	MOS/MSC	21-Jun-05	O/C	TSN 0						
SN:060101192	HRS	3694.5	TSN 0							
	AFL	2785	TSN 0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
233055		CD PLAYER CONTROL UNIT						Component	ATA:23	
PN:MCD-102-CH-1	MOS/MSC	22-May-06	O/C	TSN 0						
SN:100000353	HRS	4507.7	TSN 0							
	AFL	3441	TSN 0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
233056		CASSETTE TAPE PLAYER						Component	ATA:23	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 23 - COMMUNICATIONS										
233101		LEFT FORWARD CABIN SPEAKER						Component	ATA:23	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-30-01PROC. REF: AMM 23-30-01										
233102		RIGHT FORWARD CABIN SPEAKER						Component	ATA:23	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-30-01PROC. REF: AMM 23-30-01										
233103		LEFT AFT CABIN SPEAKER						Component	ATA:23	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-30-01PROC. REF: AMM 23-30-01										
233104		RIGHT AFT CABIN SPEAKER						Component	ATA:23	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-30-01PROC. REF: AMM 23-30-01										
233105		SUBWOOFER SPEAKER						Component	ATA:23	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
233201		PASSENGER INTERFACE UNIT						Component	ATA:23	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 23 - COMMUNICATIONS										
234000		INTERPHONE JACK BOX ASSEMBLY						Component	ATA:23	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
235001		NO. 1 AUDIO CONTROL UNIT						Component	ATA:23	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 23-50-01PROC. REF: AMM 23-50-01										
235002		NO. 2 AUDIO CONTROL UNIT						Component	ATA:23	
PN:7511001-937	MOS/MSC	12-Sep-22	O/C	TSN 0						
SN:04049325	HRS	9101.8	TSN 0							
	AFL	6994	TSN 0							
PROC. REF: AMM 23-50-01PROC. REF: AMM 23-50-01										
235013		LEFT COCKPIT SPEAKER						Component	ATA:23	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 23-50-03PROC. REF: AMM 23-50-03										
235014		RIGHT COCKPIT SPEAKER						Component	ATA:23	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 23-50-03PROC. REF: AMM 23-50-03										
236005		XM RADIO WEATHER RECEIVER						Component	ATA:23	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
236010 XM RADIO WEATHER DATA PORT									Component ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
236015 XM RADIO ANTENNA									Component ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
236096 NO. 1 NAVIGATION STRAP BOARD									Component ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-51-05PROC. REF: AMM 34-51-05									
236097 NO. 2 NAVIGATION STRAP BOARD									Component ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-51-05PROC. REF: AMM 34-51-05									
236098 NO. 1 COMMUNICATION STRAP BOARD									Component ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-11-03PROC. REF: AMM 23-11-03									
236099 NO. 2 COMMUNICATION STRAP BOARD									Component ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-11-03PROC. REF: AMM 23-11-03									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
237001 COCKPIT VOICE RECORDER (CVR)									Component ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-70-01PROC. REF: AMM 23-70-01									
237005 COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON (CVR ULB)									Component ATA:23
PN:DK120	MOS/MSC	02-Aug-24	O/C	TSN 0					
SN:NT60040	HRS	9525.7		TSN 0					
	AFL	7276		TSN 0					
PROC. REF: AMM 25-61-01PROC. REF: AMM 25-61-01									
237018 COCKPIT VOICE RECORDER (CVR) INERTIA SWITCH									Component ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-70-05PROC. REF: AMM 23-70-05									
237019 COCKPIT AREA MICROPHONE									Component ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
237030 PANEL SWITCH									Component ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
237031 COCKPIT VOICE RECORDER PRE-AMPLIFIER									Component ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-70-03PROC. REF: AMM 23-70-03									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 23 - COMMUNICATIONS										
238001	NO. 1 RADIO MANAGEMENT UNIT (RMU)								Component	ATA:23
PN:7013270-985	MOS/MSC	04-May-18	O/C							
SN:06125540	HRS	7849.4								
	AFL	6022								
PROC. REF: AMM 23-80-01PROC. REF: AMM 23-80-01										
238002	NO. 2 RADIO MANAGEMENT UNIT (RMU)								Component	ATA:23
PN:7013270-985	MOS/MSC	16-Mar-18	O/C							
SN:1248264	HRS	7800.1								
	AFL	5976								
PROC. REF: AMM 23-80-01PROC. REF: AMM 23-80-01										
238025	CLEARANCE DELIVERY UNIT								Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-82-01PROC. REF: AMM 23-82-01										
239004	MASTER CONTROL SWITCH								Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
239011	LAVATORY MASTER CONTROL SWITCH								Component	ATA:23
PN:8500-000077-6767	MOS/MSC	03-Mar-06	O/C							
SN:0123	HRS	4328.77								
	AFL	3297								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
A2300000 ^S	** COMMUNICATION SYSTEMS - PERFORM OPERATIONAL CHECK								Service	ATA:23
	MOS	02-Aug-24	24					AIRWORTHINESS		
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 23-00-00PROC. REF: AMM 23-00-00										

PKG:7

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 23 - COMMUNICATIONS

V2312003 ^S			HF ANTENNA - PERFORM VISUAL INSPECTION. CHECK FOR PROPER TENSION OF HF ANTENNA WIRE.					Service	ATA:23
	MOS	12-Aug-15	48						
	HRS	7535.1	1200						
	AFL	5764							
PKG:14									
PROC. REF: AMM 23-12-04PROC. REF: AMM 23-12-04									

Y2360020 ^S			AIRCRAFT STATIC DISCHARGERS - PERFORM FUNCTIONAL TEST					Service	ATA:23
	MOS	25-Nov-19	96						
	HRS	8177.7	2400						
	AFL	6303							
PKG:20									
PROC. REF: AMM 23-60-00PROC. REF: AMM 23-60-00									

Y2360023 ^S			AIRCRAFT STATIC DISCHARGERS - PERFORM FUNCTIONAL TEST					Service	ATA:23
	MOS	25-Nov-19	96						
	HRS	8177.7	2400						
	AFL	6303							
PKG:22									
PROC. REF: AMM 23-60-00PROC. REF: AMM 23-60-00									

ATA 24 - ELECTRICAL POWER

240109			AFT CIRCUIT BREAKER PANEL					Component	ATA:24
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN	0				
SN:UNKNOWN	HRS	0		TSN	0				
	AFL	0		TSN	0				
PROC. REF: AMM 24-60-04PROC. REF: AMM 24-60-04									

242000			NO. 1 ALTERNATOR					Component	ATA:24
PN:90278-2	MOS/MSC	14-Feb-24	O/C	TSO	0				
SN:651	HRS	9467.2		TSO	0				
	AFL	7246		TSO	0				
PROC. REF: AMM 24-20-01PROC. REF: AMM 24-20-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 24 - ELECTRICAL POWER										
242001	NO. 2 ALTERNATOR								Component	ATA:24
PN:90278-2	MOS/MSC	19-May-22	O/C	TSO 0						
SN:1488	HRS	8995.3		TSO 0						
	AFL	6902		TSO 0						
PROC. REF: AMM 24-20-01PROC. REF: AMM 24-20-01										
<hr/>										
242008	AC/DC VOLT INDICATOR								Component	ATA:24
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
<hr/>										
242050	NO. 1 REMOTE CONTROL CIRCUIT BREAKER								Component	ATA:24
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 24-60-01PROC. REF: AMM 24-60-01										
<hr/>										
242052	NO. 2 REMOTE CONTROL CIRCUIT BREAKER								Component	ATA:24
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 24-60-01PROC. REF: AMM 24-60-01										
<hr/>										
242054	NO. 3 REMOTE CONTROL CIRCUIT BREAKER								Component	ATA:24
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 24-60-01PROC. REF: AMM 24-60-01										
<hr/>										
242081	CABIN ELECTRICAL INVERTER								Component	ATA:24
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 24 - ELECTRICAL POWER										
242082	TAILCONE ELECTRICAL INVERTER								Component	ATA:24
PN:PN	MOS/MSC	09-Mar-01	A/R	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
<hr/>										
242083	ELECTRICAL INVERTER								Component	ATA:24
PN:SS120(C)	MOS/MSC	23-Jul-13	A/R	TSN 0						
SN:320	HRS	7175.4		TSN 0						
	AFL	5474		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
<hr/>										
243001	NO. 1 STARTER/GENERATOR								Component	ATA:24
PN:23280-067	MOS/MSC	27-Oct-25	O/C	TSO 0						
SN:Y01027	HRS	9906.2		TSO 0						
	AFL	7538		TSO 0						
PROC. REF: AMM 24-30-01PROC. REF: AMM 24-30-01										
<hr/>										
243002	NO. 2 STARTER/GENERATOR								Component	ATA:24
PN:23280-067	MOS/MSC	02-Aug-24	O/C	TSO 0						
SN:P1484LA	HRS	9525.7		TSO 0						
	AFL	7276		TSO 0						
<hr/>										
243003	APU STARTER/GENERATOR								Component	ATA:24
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 49-40-01PROC. REF: AMM 49-40-01										
<hr/>										
243005	LEFT GENERATOR CONTROL UNIT (GCU)								Component	ATA:24
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 24 - ELECTRICAL POWER									
243006 RIGHT GENERATOR CONTROL UNIT (GCU)									Component ATA:24
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
243019 NO. 1 MAIN BATTERY									Component ATA:24
PN:RG-380E/40L	MOS/MSC	02-Aug-24	O/C						
SN:41180857	HRS	9525.7							
	AFL	7276							
PROC. REF: AMM 24-31-01, AMM 24-31-06, CMM 24-30-71PROC. REF: AMM 24-31-01, AMM 24-31-06, CMM 24-30-71									
243020 NO. 2 MAIN BATTERY									Component ATA:24
PN:RG-380E/40L	MOS/MSC	02-Aug-24	O/C	TSN 34					
SN:41180858	HRS	9525.7		TSN 762.4					
	AFL	7276		TSN 532					
PROC. REF: CMM 24-30-71PROC. REF: CMM 24-30-71									
243037 EMERGENCY BATTERY									Component ATA:24
PN:RG-443	MOS/MSC	27-Oct-25	H/T	TSN 0					
SN:41475046	HRS	9906.2		TSN 0					
	AFL	7538		TSN 0					
PROC. REF: AMM 24-32-01, CMM 24-30-67PROC. REF: AMM 24-32-01, CMM 24-30-67									
246001 LEFT FORWARD POWER DISTRIBUTION PANEL									Component ATA:24
PN:650GC02Y03	MOS/MSC	21-Jun-18	O/C						
SN:575	HRS	7887.8							
	AFL	6051							
PROC. REF: AMM 24-60-02PROC. REF: AMM 24-60-02									
246002 RIGHT FORWARD POWER DISTRIBUTION PANEL									Component ATA:24
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 24-60-02PROC. REF: AMM 24-60-02									

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 24 - ELECTRICAL POWER										
246003		LEFT AFT POWER DISTRIBUTION PANEL						Component	ATA:24	
PN:660GC02Y07	MOS/MSC	30-Jan-11	O/C							
SN:588	HRS	6501.3								
	AFL	4977								
PROC. REF: AMM 24-60-03PROC. REF: AMM 24-60-03										
246004		RIGHT AFT POWER DISTRIBUTION PANEL						Component	ATA:24	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 24-60-03PROC. REF: AMM 24-60-03										
246101		LEFT GENERATOR CONTROL UNIT PRINTED CIRCUIT BOARD						Component	ATA:24	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
246102		LEFT LOGIC PRINTED CIRCUIT BOARD						Component	ATA:24	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
246104		RIGHT GENERATOR CONTROL UNIT PRINTED CIRCUIT BOARD						Component	ATA:24	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
246105		RIGHT LOGIC PRINTED CIRCUIT BOARD						Component	ATA:24	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 24 - ELECTRICAL POWER

246106	APU GENERATOR CONTROL UNIT PRINTED CIRCUIT BOARD							Component	ATA:24
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

AB2431062	EMERGENCY BATTERY - PERFORM CAPACITY CHECK							Service	ATA:24
PN:RG-443	MOS	27-Oct-25	12		27-Oct-26		154 d		
SN:41475046	HRS	9906.2	1000		10906.2		883.1		
	AFL	7538							

AB2431063	EMERGENCY BATTERY - REPLACE							Service	ATA:24
PN:RG-443	MOS	27-Oct-25	48		27-Oct-29		1250 d	LIFE LIMIT	
SN:41475046	HRS	9906.2							
	AFL	7538							

AC2460002 ^S	REMOVE ATTACHING PARTS SECURING CIRCUIT BREAKER PANEL TO STRUCTURE. CHECK FOR LOOSE CIRCUIT BREAKER TERMINALS, LOOSE WIRE TERMINALS, CORRODED TERMINALS OR BUS BARS, AND EVIDENCE OF WIRE INSULATION DAMAGE.							Service	ATA:24
	MOS	09-Mar-01	96						
	HRS	0	2400						
	AFL	0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

PKG:19

B2450002 ^S	** ELECTRICAL SYSTEM CONTROL - PERFORM OPERATIONAL CHECK							Service	ATA:24
	MOS	09-Mar-01	48					AIRWORTHINESS	
	HRS	0	1200						
	AFL	0							

PKG:13

PROC. REF: AMM 24-00-00PROC. REF: AMM 24-00-00

F2420000	** NO. 1 ALTERNATOR - PERFORM BEARING REPLACEMENT							Service	ATA:24
PN:90278-2	MOS	14-Feb-24						AIRWORTHINESS	
SN:651	HRS	9467.2	1200		10667.2		644.1		
	AFL	7246							

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 24 - ELECTRICAL POWER

F2420000		** NO. 2 ALTERNATOR - PERFORM BEARING REPLACEMENT						Service	ATA:24
PN:90278-2	MOS	19-May-22						AIRWORTHINESS	
SN:1488	HRS	8995.3	1200		10195.3		172.2		
	AFL	6902							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

H2450001 ^S		** AUXILIARY POWER SUPPLIES - PERFORM FUNCTIONAL TEST						Service	ATA:24
	MOS	02-Aug-24	24					AIRWORTHINESS	
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 24-00-00PROC. REF: AMM 24-00-00									
PKG:7									

H2450023 ^S		** EMER BATT LOW AND GEN AMPS HIGH INDICATION - PERFORM OPERATIONAL CHECK						Service	ATA:24
	MOS	02-Aug-24	24					AIRWORTHINESS	
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 24-00-00PROC. REF: AMM 24-00-00									
PKG:7									

O2431002		EMERGENCY BATTERY - PERFORM CAPACITY CHECK						Service	ATA:24
PN:RG-443	MOS/MSC	27-Oct-25	N/A						
SN:41475046	HRS	9906.2							
	AFL	7538							
PROC. REF: CMM 24-30-67PROC. REF: CMM 24-30-67									

P2430003		NO. 1 STARTER/GENERATOR - PERFORM OVERHAUL						Service	ATA:24
PN:23280-067	MOS	27-Oct-25							
SN:Y01027	HRS	9906.2	1200		11106.2		1083.1		
	AFL	7538							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

P2430003		NO. 2 STARTER/GENERATOR - PERFORM OVERHAUL						Service	ATA:24
PN:23280-067	MOS	02-Aug-24							
SN:P1484LA	HRS	9525.7	1200		10725.7		702.6		
	AFL	7276							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 24 - ELECTRICAL POWER

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

P2430007	NO. 1 STARTER/GENERATOR - REPLACE BEARINGS							Service	ATA:24
PN:23280-067	MOS/MSC		27-Oct-25		N/A				
SN:Y01027	HRS		9906.2						
	AFL		7538						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

P2430007	NO. 2 STARTER/GENERATOR - REPLACE BEARINGS							Service	ATA:24
PN:23280-067	MOS/MSC		02-Aug-24		N/A				
SN:P1484LA	HRS		9525.7						
	AFL		7276						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

Q2460001^S	** POWER DISTRIBUTION SYSTEM - PERFORM SQUAT SWITCH CHECK							Service	ATA:24
	MOS		09-Mar-01		48			AIRWORTHINESS	
	HRS		0		1200				
	AFL		0						
PROC. REF: AMM 24-60-00PROC. REF: AMM 24-60-00									
PKG:17									

R2431003^S	** BATTERY WARNING SYSTEM - PERFORM FUNCTIONAL TEST							Service	ATA:24
	MOS		09-Mar-01		96			AIRWORTHINESS	
	HRS		0		2400				
	AFL		0						
PROC. REF: AMM 24-31-00PROC. REF: AMM 24-31-00									
PKG:19									

W2450000^S	** GENERATOR FAIL INDICATION - PERFORM OPERATIONAL CHECK							Service	ATA:24
	MOS		02-Aug-24		24			AIRWORTHINESS	
	HRS		9525.7		600				
	AFL		7276						
PROC. REF: AMM 24-00-00PROC. REF: AMM 24-00-00									
PKG:7									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 24 - ELECTRICAL POWER										
Y2400001	^S	SWITCH AND CIRCUIT BREAKER PANELS - PERFORM VISUAL INSPECTION						Service	ATA:24	
	MOS	09-Mar-01	48							
	HRS	0	1200							
	AFL	0								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
PKG:13										
Y2400002	^S	ELECTRICAL WIRING - PERFORM VISUAL INSPECTION FOR ROUTING, SECURITY, CLEARANCES, CHAFING, AND ELECTRICAL COMPONENTS FOR SECURITY AND GENERAL CONDITION.						Service	ATA:24	
	MOS	02-Aug-24	24							
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
PKG:7										
Y2400025	^S	ELECTRICAL WIRING - PERFORM VISUAL INSPECTION FOR ROUTING, SECURITY, CLEARANCES, CHAFING, AND ELECTRICAL COMPONENTS FOR SECURITY AND GENERAL CONDITION.						Service	ATA:24	
	MOS	02-Aug-24	24							
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
PKG:8										
Y2430005	^S	STARTER/GENERATOR - PERFORM GROUNDING LUG BONDING CHECK						Service	ATA:24	
	MOS	02-Aug-24	24							
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 24-30-01PROC. REF: AMM 24-30-01										
PKG:9										
Y2430006	^S	STARTER/GENERATOR - PERFORM VISUAL INSPECTION OF GROUNDING LUGS						Service	ATA:24	
	MOS	02-Aug-24	24							
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
PKG:9										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 24 - ELECTRICAL POWER

Y2431000 ^S		BATTERY, GENERATOR, AND BUS-TIE CABLES - PERFORM VISUAL INSPECTION						Service	ATA:24
	MOS	25-Nov-19	96						
	HRS	8177.7	2400						
	AFL	6303							
PKG:20									
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									

Y2431001 ^S		EMERGENCY BATTERY CABLES - PERFORM VISUAL INSPECTION						Service	ATA:24
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PKG:7									
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									

Y2431005		BATTERY CABLES AND RECEPTACLES - PERFORM BATTERY CONNECTOR TOLERANCE CHECK						Service	ATA:24
	MOS	21-Aug-25							
	HRS	9809.8	300		10109.8		86.7		
	AFL	7471							
PROC. REF: AMM 24-31-00PROC. REF: AMM 24-31-00									

Y2460000 ^S		DC BUS ISOLATION - PERFORM OPERATIONAL CHECK						Service	ATA:24
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PKG:13									
PROC. REF: AMM 24-60-00PROC. REF: AMM 24-60-00									

ATA 25 - EQUIPMENT/FURNISHINGS

250010		RELAY MODULE						Component	ATA:25
PN:PN	MOS/MS	09-Mar-01	O/C	TSN	0				
SN:UNKNOWN	HRS	0		TSN	0				
	AFL	0		TSN	0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 25 - EQUIPMENT/FURNISHINGS

252000		JUMP SEAT					Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF, AMM 25-20-45PROC. REF: GENERIC NO REF, AMM 25-20-45								

252000		NO. 1 PASSENGER SEAT					Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45								

252000		NO. 2 PASSENGER SEAT					Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45								

252000		NO. 3 PASSENGER SEAT					Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45								

252000		NO. 4 PASSENGER SEAT					Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45								

252000		NO. 5 PASSENGER SEAT					Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 25 - EQUIPMENT/FURNISHINGS										
252000		NO. 6 PASSENGER SEAT						Component	ATA:25	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45										
252000		NO. 7 PASSENGER SEAT						Component	ATA:25	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45										
252000		NO. 8 PASSENGER SEAT						Component	ATA:25	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45										
252001		LAVATORY PCU						Component	ATA:25	
PN:PN	MOS/MSC	09-Mar-01	A/R	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF, AMM 25-20-45PROC. REF: GENERIC NO REF, AMM 25-20-45										
252001		NO. 1 PASSENGER SEAT PCU						Component	ATA:25	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45										
252001		NO. 2 PASSENGER SEAT PCU						Component	ATA:25	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 25 - EQUIPMENT/FURNISHINGS

252001		NO. 3 PASSENGER SEAT PCU							Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45										

252001		NO. 4 PASSENGER SEAT PCU							Component	ATA:25
PN:SP-45-07A	MOS/MSC	05-Apr-06	O/C							
SN:020600592	HRS	4422.47								
	AFL	3369								
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45										

252001		NO. 5 PASSENGER SEAT PCU							Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45										

252001		NO. 6 PASSENGER SEAT PCU							Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45										

252001		NO. 7 PASSENGER SEAT PCU							Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45										

252001		NO. 8 PASSENGER SEAT PCU							Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 25 - EQUIPMENT/FURNISHINGS										
252010		AIRSHOW COMPUTER						Component	ATA:25	
PN:920040	MOS/MSC	06-Mar-09	O/C							
SN:452	HRS	6115.4								
	AFL									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
252020		CLOSET SWITCH PANEL ASSEMBLY						Component	ATA:25	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
252090		NO. 1 110 VOLT POWER OUTLET						Component	ATA:25	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
252091		NO. 2 110 VOLT POWER OUTLET						Component	ATA:25	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
252092		NO. 3 110 VOLT POWER OUTLET						Component	ATA:25	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
252095		NO. 4 110 VOLT POWER OUTLET						Component	ATA:25	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 25 - EQUIPMENT/FURNISHINGS										
252097		NO. 1 AC POWER OUTLET						Component	ATA:25	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
252098		NO. 2 AC POWER OUTLET						Component	ATA:25	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
252099		NO. 3 AC POWER OUTLET						Component	ATA:25	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
253001		MICROWAVE OVEN						Component	ATA:25	
PN:255A-LH28-115	MOS/MSC	28-Jul-05	O/C	TSN 0						
SN:19976	HRS	3775.77	TSN 0							
	AFL	2849	TSN 0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
253075		NO. 1 HEATED WATER CONTAINER						Component	ATA:25	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
253076		NO. 2 HEATED WATER CONTAINER						Component	ATA:25	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 25 - EQUIPMENT/FURNISHINGS										
253077		HEATED WATER SWITCH						Component	ATA:25	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
253080		GALLEY DRAIN VALVE SOLENOID						Component	ATA:25	
PN:8210G94-24DC	MOS/MSC	03-Jan-06	O/C	TSN 0						
SN:T116684	HRS	4160.77	TSN 0							
	AFL	3151	TSN 0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
256001		PILOT CREW SEAT						Component	ATA:25	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 25-10-50PROC. REF: AMM 25-10-50										
256002		COPILOT CREW SEAT						Component	ATA:25	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 25-10-50PROC. REF: AMM 25-10-50										
256061		PILOTS LIFE VEST						Component	ATA:25	
PN:P01074-101	MOS/MSC	09-Feb-21	O/C	TSN 0						
SN:20100400026	HRS	8401.3	TSN 0							
	AFL	6458	TSN 0							
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01										
256062		COPILOTS LIFE VEST						Component	ATA:25	
PN:P01074-101	MOS/MSC	09-Feb-21	O/C	TSN 0						
SN:20100400085	HRS	8401.3	TSN 0							
	AFL	6458	TSN 0							
PROC. REF: CMM 25-60-05PROC. REF: CMM 25-60-05										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 25 - EQUIPMENT/FURNISHINGS										
256063		NO. 1 PASSENGER LIFE VEST						Component	ATA:25	
PN:P01074-101	MOS/MSC	09-Feb-21	O/C	TSN 0						
SN:20100400200	HRS	8401.3		TSN 0						
	AFL	6458		TSN 0						
PROC. REF: CMM 25-60-05PROC. REF: CMM 25-60-05										
256064		NO. 2 PASSENGER LIFE VEST						Component	ATA:25	
PN:P01074-101	MOS/MSC	09-Feb-21	O/C	TSN 0						
SN:20100400323	HRS	8401.3		TSN 0						
	AFL	6458		TSN 0						
PROC. REF: CMM 25-60-05PROC. REF: CMM 25-60-05										
256065		NO. 3 PASSENGER LIFE VEST						Component	ATA:25	
PN:P01074-101	MOS/MSC	09-Feb-21	O/C	TSN 0						
SN:20100400333	HRS	8401.3		TSN 0						
	AFL	6458		TSN 0						
PROC. REF: CMM 25-60-05PROC. REF: CMM 25-60-05										
256066		NO. 4 PASSENGER LIFE VEST						Component	ATA:25	
PN:P01074-101	MOS/MSC	09-Feb-21	O/C	TSN 0						
SN:20100400338	HRS	8401.3		TSN 0						
	AFL	6458		TSN 0						
PROC. REF: CMM 25-60-05PROC. REF: CMM 25-60-05										
256067		NO. 5 PASSENGER LIFE VEST						Component	ATA:25	
PN:P01074-101	MOS/MSC	09-Feb-21	O/C	TSN 0						
SN:20100400422	HRS	8401.3		TSN 0						
	AFL	6458		TSN 0						
PROC. REF: CMM 25-60-05PROC. REF: CMM 25-60-05										
256068		NO. 6 PASSENGER LIFE VEST						Component	ATA:25	
PN:P01074-101	MOS/MSC	09-Feb-21	O/C	TSN 0						
SN:20100400432	HRS	8401.3		TSN 0						
	AFL	6458		TSN 0						
PROC. REF: CMM 25-60-05PROC. REF: CMM 25-60-05										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 25 - EQUIPMENT/FURNISHINGS										
256069	NO. 7 PASSENGER LIFE VEST								Component	ATA:25
PN:P01074-101	MOS/MSC	09-Feb-21	O/C	TSN 0						
SN:20100400704	HRS	8401.3		TSN 0						
	AFL	6458		TSN 0						
PROC. REF: CMM 25-60-05PROC. REF: CMM 25-60-05										
256070	NO. 8 PASSENGER LIFE VEST								Component	ATA:25
PN:P01074-101	MOS/MSC	09-Feb-21	O/C	TSN 0						
SN:20100400721	HRS	8401.3		TSN 0						
	AFL	6458		TSN 0						
PROC. REF: CMM 25-60-05PROC. REF: CMM 25-60-05										
256071	LAVATORY LIFE VEST								Component	ATA:25
PN:P01074-101	MOS/MSC	09-Feb-21	O/C	TSN 0						
SN:20100400737	HRS	8401.3		TSN 0						
	AFL	6458		TSN 0						
PROC. REF: CMM 25-60-05PROC. REF: CMM 25-60-05										
256076	FIRST AID KIT								Component	ATA:25
PN:MSK70002	MOS/MSC	14-Jul-07	O/C							
SN:0602	HRS	5618.1								
	AFL	4293								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
256080	INSPECT LIFE VESTS								Service	ATA:25
	MOS/MSC	09-Mar-01	A/R							
	HRS	0								
	AFL	0								
PROC. REF: GENERIC NO REF, CMM 25-60-05PROC. REF: GENERIC NO REF, CMM 25-60-05										
256109	(ELT) EMERGENCY LOCATOR TRANSMITTER								Component	ATA:25
PN:453-5000	MOS/MSC	03-Feb-25	O/C	TSN 122						
SN:210-05727	HRS	9605.4		TSN 2171.2						
	AFL	7333		TSN 1646						
PROC. REF: AMM 25-62-01PROC. REF: AMM 25-62-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
256109A (ELT) EMERGENCY LOCATOR TRANSMITTER - PERFORM NATIONALY REQUIRED FUNCTIONAL TEST Service ATA:25									
PN:453-5000	MOS	03-Feb-25	12		03-Feb-26		OVD		
SN:210-05727	HRS	9605.4							
	AFL	7333							
PROC. REF: AMM 25-62-00, FAR FAR 91.207PROC. REF: AMM 25-62-00, FAR FAR 91.207									
256109B (ELT) EMERGENCY LOCATOR TRANSMITTER - INSPECT ELT BATTERIES Service ATA:25									
PN:453-5000	MOS	03-Feb-25	12		03-Feb-26		OVD		
SN:210-05727	HRS	9605.4							
	AFL	7333							
PROC. REF: AMM 25-62-00, FAR FAR 91.207PROC. REF: AMM 25-62-00, FAR FAR 91.207									
256109C (ELT) EMERGENCY LOCATOR TRANSMITTER BATTERY - REPLACE Service ATA:25									
PN:453-5000	MOS	03-Feb-25	72		03-Feb-31		1714 d	LIFE LIMIT	
SN:210-05727	HRS	9605.4							
	AFL	7333							
PROC. REF: AMM 25-62-01, FAR FAR 91.207PROC. REF: AMM 25-62-01, FAR FAR 91.207									
256110 EMERGENCY LOCATOR TRANSMITTER (ELT)/NAVIGATION INTERFACE UNIT (C406-2) Component ATA:25									
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
256115 EMERGENCY LOCATOR TRANSMITTER (ELT) ANTENNA Component ATA:25									
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 25-62-03PROC. REF: AMM 25-62-03									
256116 EMERGENCY LOCATOR TRANSMITTER (ELT) REMOTE SWITCH Component ATA:25									
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 25-62-04PROC. REF: AMM 25-62-04									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 25 - EQUIPMENT/FURNISHINGS										
258001	CABIN AIRSHOW DISPLAY COMPUTER UNIT								Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
259072	AUTOMATIC ELECTRONIC DEFIBRILLATOR (AED)								Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
259073	AUTOMATIC ELECTRONIC DEFIBRILLATOR (AED) BATTERIES								Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
259074	AUTOMATIC ELECTRONIC DEFIBRILLATOR (AED) ELECTRODE PADS								Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
AA2560000	COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON - CLEAN BEACON SWITCH, PERFORM FUNCTIONAL TEST OF BEACON, AND PERFORM TEST OF ULB BATTERY								Service	ATA:25
PN:DK120	MOS	02-Aug-24	24		02-Aug-26		68 d			
SN:NT60040	HRS	9525.7								
	AFL	7276								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
D2566001	COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON - REPLACE								Service	ATA:25
PN:DK120	MOS/MSC	02-Aug-24	DUE		31-Mar-29 (M)		1040 d			
SN:NT60040	HRS	9525.7								
	AFL	7276								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 25 - EQUIPMENT/FURNISHINGS										
E2561002		COPILOTS LIFE VEST - PERFORM INSPECTION OF LIFE VESTS							Service	ATA:25
PN:P01074-101	MOS	09-Feb-21	60		09-Feb-26		OVD			
SN:20100400085	HRS									
	AFL									
Inspection Date: : 09-Feb-21										
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01										
E2561002		LAVATORY LIFE VEST - PERFORM INSPECTION OF LIFE VESTS							Service	ATA:25
PN:P01074-101	MOS	09-Feb-21	60		09-Feb-26		OVD			
SN:20100400737	HRS									
	AFL									
Inspection Date: : 09-Feb-21										
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01										
E2561002		NO. 1 PASSENGER LIFE VEST - PERFORM INSPECTION OF LIFE VESTS							Service	ATA:25
PN:P01074-101	MOS	09-Feb-21	60		09-Feb-26		OVD			
SN:20100400200	HRS									
	AFL									
Inspection Date: : 09-Feb-21										
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01										
E2561002		NO. 2 PASSENGER LIFE VEST - PERFORM INSPECTION OF LIFE VESTS							Service	ATA:25
PN:P01074-101	MOS	09-Feb-21	60		09-Feb-26		OVD			
SN:20100400323	HRS									
	AFL									
Inspection Date: : 09-Feb-21										
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01										
E2561002		NO. 3 PASSENGER LIFE VEST - PERFORM INSPECTION OF LIFE VESTS							Service	ATA:25
PN:P01074-101	MOS	09-Feb-21	60		09-Feb-26		OVD			
SN:20100400333	HRS									
	AFL									
Inspection Date: : 09-Feb-21										
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 25 - EQUIPMENT/FURNISHINGS

E2561002		NO. 4 PASSENGER LIFE VEST - PERFORM INSPECTION OF LIFE VESTS						Service	ATA:25
PN:P01074-101	MOS	09-Feb-21	60		09-Feb-26		OVD		
SN:20100400338	HRS								
	AFL								
Inspection Date: : 09-Feb-21									
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01									

E2561002		NO. 5 PASSENGER LIFE VEST - PERFORM INSPECTION OF LIFE VESTS						Service	ATA:25
PN:P01074-101	MOS	09-Feb-21	60		09-Feb-26		OVD		
SN:20100400422	HRS								
	AFL								
Inspection Date: : 09-Feb-21									
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01									

E2561002		NO. 6 PASSENGER LIFE VEST - PERFORM INSPECTION OF LIFE VESTS						Service	ATA:25
PN:P01074-101	MOS	09-Feb-21	60		09-Feb-26		OVD		
SN:20100400432	HRS								
	AFL								
Inspection Date: : 09-Feb-21									
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01									

E2561002		NO. 7 PASSENGER LIFE VEST - PERFORM INSPECTION OF LIFE VESTS						Service	ATA:25
PN:P01074-101	MOS	09-Feb-21	60		09-Feb-26		OVD		
SN:20100400704	HRS								
	AFL								
Inspection Date: : 09-Feb-21									
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01									

E2561002		NO. 8 PASSENGER LIFE VEST - PERFORM INSPECTION OF LIFE VESTS						Service	ATA:25
PN:P01074-101	MOS	09-Feb-21	60		09-Feb-26		OVD		
SN:20100400721	HRS								
	AFL								
Inspection Date: : 09-Feb-21									
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 25 - EQUIPMENT/FURNISHINGS										
E2561002	PILOTS LIFE VEST - PERFORM INSPECTION OF LIFE VESTS								Service	ATA:25
PN:P01074-101	MOS	09-Feb-21	60		09-Feb-26		OVD			
SN:20100400026	HRS									
	AFL									
Inspection Date: : 09-Feb-21										
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01										
Y2510000 ^S	GLARESHIELD, HEADLINER, AND TRIM STRIPS - PERFORM VISUAL INSPECTION								Service	ATA:25
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PKG:1										
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
Y2510001 ^S	CREW SEATS AND SEAT BELTS - PERFORM VISUAL INSPECTION								Service	ATA:25
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PKG:1										
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
Y2520000 ^S	CABIN - PERFORM VISUAL INSPECTION OF THE FOLLOWING: A. CABIN SEATS AND SEAT BELTS. ENSURE THAT THE SEATS FUNCTION CORRECTLY AND LOCK IN PLACE. B. STOWAGE CABINETS. C. HEADLINER. D. SIDE PANELS. E. RUG.								Service	ATA:25
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PKG:1										
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
Y2540000 ^S	ALL LAVATORY PAPER AND LINEN WASTE RECEPTACLE ACCESS DOORS AND DISPOSAL DOORS FOR PROPER OPERATION, FIT, SEALING, LATCHING, AND LEGIBILITY OF PLACARD.								Service	ATA:25
	MOS	02-Aug-24	24							
	HRS	9525.7	600							
	AFL	7276								
PKG:7										
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 25 - EQUIPMENT/FURNISHINGS

Y2540009 ^S		AVIONICS EQUIPMENT AND WIRING LOCATED IN LAVATORY AREA - PERFORM GENERAL VISUAL INSPECTION						Service	ATA:25
	MOS	09-Mar-01							
	HRS	0	4800						
	AFL	0							
PKG:25									
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									

ATA 26 - FIRE PROTECTION

261012		NO. 1 ENGINE FIREWALL FIRE DETECTION ELEMENT						Component	ATA:26
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN	0				
SN:UNKNOWN	HRS	0		TSN	0				
	AFL	0		TSN	0				
PROC. REF: AMM 26-11-02PROC. REF: AMM 26-11-02									

261013		NO. 2 ENGINE FIREWALL FIRE DETECTION ELEMENT						Component	ATA:26
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN	0				
SN:UNKNOWN	HRS	0		TSN	0				
	AFL	0		TSN	0				
PROC. REF: AMM 26-11-02PROC. REF: AMM 26-11-02									

261014		NO. 1 ENGINE ACCESSORY GEARBOX FIRE DETECTION ELEMENT						Component	ATA:26
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN	0				
SN:UNKNOWN	HRS	0		TSN	0				
	AFL	0		TSN	0				
PROC. REF: AMM 26-11-02PROC. REF: AMM 26-11-02									

261015		NO. 2 ENGINE ACCESSORY GEARBOX FIRE DETECTION ELEMENT						Component	ATA:26
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN	0				
SN:UNKNOWN	HRS	0		TSN	0				
	AFL	0		TSN	0				
PROC. REF: AMM 26-11-02PROC. REF: AMM 26-11-02									

261016		NO. 1 ENGINE HOT SECTION FIRE DETECTION ELEMENT						Component	ATA:26
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN	0				
SN:UNKNOWN	HRS	0		TSN	0				
	AFL	0		TSN	0				
PROC. REF: AMM 26-11-02PROC. REF: AMM 26-11-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 26 - FIRE PROTECTION										
261017	NO. 2 ENGINE HOT SECTION FIRE DETECTION ELEMENT								Component	ATA:26
PN:744-12135	MOS/MSC	12-Aug-15	O/C							
SN:UNKNOWN	HRS	7535.1								
	AFL	5764								
PROC. REF: AMM 26-11-02PROC. REF: AMM 26-11-02										
<hr/>										
261057	NO. 1 FIRE DETECT CONTROL UNIT								Component	ATA:26
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 26-11-01PROC. REF: AMM 26-11-01										
<hr/>										
261058	NO. 2 FIRE DETECT CONTROL UNIT								Component	ATA:26
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 26-11-01PROC. REF: AMM 26-11-01										
<hr/>										
261069	NO. 1 BLEED AIR LEAK DETECTION UNIT								Component	ATA:26
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 26-12-01PROC. REF: AMM 26-12-01										
<hr/>										
261070	NO. 2 BLEED AIR LEAK DETECTION UNIT								Component	ATA:26
PN:6626100000-003	MOS/MSC	18-Apr-12	O/C	TSN 0						
SN:2714	HRS	6879.9		TSN 0						
	AFL	5240		TSN 0						
PROC. REF: AMM 26-12-01PROC. REF: AMM 26-12-01										
<hr/>										
261071	ANTI-ICE BLEED AIR LEAK DETECTION UNIT								Component	ATA:26
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 26-12-01PROC. REF: AMM 26-12-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 26 - FIRE PROTECTION

261075		APU FIRE/OVERHEAT DETECTOR						Component	ATA:26
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 26-13-01PROC. REF: AMM 26-13-01									

262001		NO. 1/LEFT/LOWER FIRE EXTINGUISHER BOTTLE						Component	ATA:26
PN:33100021-1	MOS/MSC	22-Jun-23	O/C	TSO 0					
SN:59578B1	HRS	9258.5		TSO 0					
	AFL	7100		TSO 0					
PROC. REF: AMM 26-21-01PROC. REF: AMM 26-21-01									

262002		NO. 2/RIGHT/UPPER FIRE EXTINGUISHER BOTTLE						Component	ATA:26
PN:33100021-1	MOS/MSC	21-Aug-25	O/C	TSO 0					
SN:72043B1	HRS	9809.8		TSO 0					
	AFL	7471		TSO 0					
PROC. REF: AMM 26-21-01PROC. REF: AMM 26-21-01									

262013		NO. 1/LEFT/LOWER FIRE EXTINGUISHER, LEFT SQUIB						Component	ATA:26
PN:30903856	MOS	06-Dec-18	180	TSN 5	01-Jul-33		2593 d		
SN:02254	HRS								
	AFL								
Manufacture Date:: 01-Jul-18									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

262014		NO. 1/LEFT/LOWER FIRE EXTINGUISHER, RIGHT SQUIB						Component	ATA:26
PN:30903859	MOS	06-Dec-18	180	TSN 5	01-Jul-33		2593 d		
SN:01619	HRS								
	AFL								
Manufacture Date:: 01-Jul-18									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

262015		NO. 2/RIGHT/UPPER FIRE EXTINGUISHER, LEFT SQUIB						Component	ATA:26
PN:30903856	MOS	21-Aug-25	180	TSN 5	31-Mar-40		5058 d		
SN:03401	HRS								
	AFL								
Manufacture Date:: 31-Mar-25									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 26 - FIRE PROTECTION

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

262016	NO. 2/RIGHT/UPPER FIRE EXTINGUISHER, RIGHT SQUIB							Component	ATA:26
---------------	---	--	--	--	--	--	--	------------------	---------------

PN:30903859	MOS	21-Aug-25	180	TSN 5	31-Mar-40		5058 d		
SN:02408	HRS								
	AFL								

Manufacture Date:: 31-Mar-25

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

262040	APU FIRE WARNING HORN							Component	ATA:26
---------------	------------------------------	--	--	--	--	--	--	------------------	---------------

PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					

PROC. REF: AMM 26-13-02PROC. REF: AMM 26-13-02

262041	PILOT PORTABLE FIRE EXTINGUISHER							Component	ATA:26
---------------	---	--	--	--	--	--	--	------------------	---------------

PN:A344T	MOS/MSC	07-Dec-12	O/C						
SN:UNKNOWN	HRS	7016.8							
	AFL	5361							

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

262042	COPILOT PORTABLE FIRE EXTINGUISHER							Component	ATA:26
---------------	---	--	--	--	--	--	--	------------------	---------------

PN:A344	MOS/MSC	18-May-16	O/C	TSN 0					
SN:B10813738	HRS	7623.3		TSN 0					
	AFL	5813		TSN 0					

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

262051	CABIN PORTABLE FIRE EXTINGUISHER							Component	ATA:26
---------------	---	--	--	--	--	--	--	------------------	---------------

PN:C352	MOS/MSC	28-Dec-22	O/C	TSN 0					
SN:H-20651164	HRS	9186.7		TSN 0					
	AFL	7047		TSN 0					

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

D2620007.S	NO. 1/LEFT/LOWER FIRE EXTINGUISHER, LEFT SQUIB SERVICE LIFE LIMIT						Service	ATA:26
-------------------	--	--	--	--	--	--	----------------	---------------

PN:30903856	MOS	06-Dec-18	120		06-Dec-28		925 d	SERVICE LIFE LIMIT	
SN:02254	HRS	0							
	AFL	0							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 26 - FIRE PROTECTION										
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
D2620007.S	NO. 1/LEFT/LOWER FIRE EXTINGUISHER, RIGHT SQUIB SERVICE LIFE LIMIT								Service	ATA:26
PN:30903859	MOS	06-Dec-18	120		06-Dec-28		925 d	SERVICE LIFE LIMIT		
SN:01619	HRS	0								
	AFL	0								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
D2620007.S	NO. 2/RIGHT/UPPER FIRE EXTINGUISHER, LEFT SQUIB SERVICE LIFE LIMIT								Service	ATA:26
PN:30903856	MOS	21-Aug-25	120		21-Aug-35		3374 d	SERVICE LIFE LIMIT		
SN:03401	HRS	0								
	AFL	0								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
D2620007.S	NO. 2/RIGHT/UPPER FIRE EXTINGUISHER, RIGHT SQUIB SERVICE LIFE LIMIT								Service	ATA:26
PN:30903859	MOS	21-Aug-25	120		21-Aug-35		3374 d	SERVICE LIFE LIMIT		
SN:02408	HRS	0								
	AFL	0								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
J2620000 S	** ENGINE FIRE EXTINGUISHING SYSTEM FIRE SWITCH - PERFORM FUNCTIONAL TEST								Service	ATA:26
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	4800							
	AFL	0								
PROC. REF: AMM 26-21-00PROC. REF: AMM 26-21-00										
O2610001	NO. 1 ENGINE HOT SECTION FIRE DETECTOR ELEMENT - PERFORM VISUAL INSPECTION								Service	ATA:26
	MOS	21-May-18								
	HRS	7855.7	3000		10855.7		832.6			
	AFL	6028								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										

PKG:25

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 26 - FIRE PROTECTION										
Q2610001		NO. 2 ENGINE HOT SECTION FIRE DETECTOR ELEMENT - PERFORM VISUAL INSPECTION							Service	ATA:26
	MOS	12-Aug-15								
	HRS	7535.1	3000		10535.1		512			
	AFL	5764								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
Q2510003		COPILOT PORTABLE FIRE EXTINGUISHER - PERFORM ICC HYDROSTATIC TEST							Service	ATA:26
PN:A344	MOS	01-Feb-16	144		01-Feb-28		616 d			
SN:B10813738	HRS									
	AFL									
HydroCheck Date: : 01-Feb-16										
PROC. REF: AMM 26-23-00PROC. REF: AMM 26-23-00										
Q2620006		NO. 1/LEFT/LOWER FIRE EXTINGUISHER BOTTLE - PERFORM ICC HYDROSTATIC TEST							Service	ATA:26
PN:33100021-1	MOS	31-May-23	60		31-May-28		736 d			
SN:59578B1	HRS									
	AFL									
HydroCheck Date: : 31-May-23										
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
Q2620006		NO. 2/RIGHT/UPPER FIRE EXTINGUISHER BOTTLE - PERFORM ICC HYDROSTATIC TEST							Service	ATA:26
PN:33100021-1	MOS	21-Aug-25	60		30-Jun-30		1496 d			
SN:72043B1	HRS	9809.8								
	AFL	7471								
HydroCheck Date: : 30-Jun-25										
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
T2620001 ^S		** FIREWALL SHUT-OFF VALVES - PERFORM OPERATIONAL CHECK							Service	ATA:26
	MOS	09-Mar-01	48					AIRWORTHINESS		
	HRS	0	1200							
	AFL	0								
PROC. REF: AMM 26-21-00PROC. REF: AMM 26-21-00										

PKG:13

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 26 - FIRE PROTECTION										
Y2610000 ^S		FIREWALL AND ACCESSORY COMPARTMENT FIRE DETECTOR ELEMENTS - PERFORM VISUAL INSPECTION						Service	ATA:26	
	MOS	02-Aug-24	24							
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
Y2620002 ^S		ENGINE FIRE EXTINGUISHER CONTAINERS - PERFORM VISUAL INSPECTION. CHECK CONTAINERS FOR CONDITION, CARTRIDGES AND CARTRIDGE WIRING FOR SECURITY AND CONDITION, CONTAINER PRESSURE GAUGE FOR PROPER PRESSURES, AND PLUMBING FOR SECURITY AND CONDITION.						Service	ATA:26	
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
Y2620005 ^S		ENGINE FIRE EXTINGUISHING SYSTEM - PERFORM OPERATIONAL CHECK						Service	ATA:26	
	MOS	25-Nov-19	96							
	HRS	8177.7	2400							
	AFL	6303								
PROC. REF: AMM 26-21-00PROC. REF: AMM 26-21-00										
Y2620009 ^S		CABIN PORTABLE FIRE EXTINGUISHER - INSPECT PORTABLE HAND HELD FIRE EXTINGUISHERS FOR CONDITION AND DATE OF MANUFACTURE. CHECK OPERATING PRESSURE AND WEIGHT PER MAINTENANCE INSTRUCTIONS ON FIRE EXTINGUISHER BOTTLE.						Service	ATA:26	
PN:C352	MOS	05-Dec-14	12							
SN:H-20651164	HRS	7434.2	300							
	AFL	5687								
PROC. REF: AMM 26-21-00PROC. REF: AMM 26-21-00										
Y2620009 ^S		COPILOT PORTABLE FIRE EXTINGUISHER - INSPECT PORTABLE HAND HELD FIRE EXTINGUISHERS FOR CONDITION AND DATE OF MANUFACTURE. CHECK OPERATING PRESSURE AND WEIGHT PER MAINTENANCE INSTRUCTIONS ON FIRE EXTINGUISHER BOTTLE.						Service	ATA:26	
PN:A344	MOS	21-Aug-25	12							
SN:B10813738	HRS	9809.8	300							
	AFL	7471								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 26 - FIRE PROTECTION

Y2620009 ^S		PILOT PORTABLE FIRE EXTINGUISHER - INSPECT PORTABLE HAND HELD FIRE EXTINGUISHERS FOR CONDITION AND DATE OF MANUFACTURE. CHECK OPERATING PRESSURE AND WEIGHT PER MAINTENANCE INSTRUCTIONS ON FIRE EXTINGUISHER BOTTLE.						Service	ATA:26
PN:A344T	MOS	05-Dec-14	12						
SN:UNKNOWN	HRS	7434.2	300						
	AFL	5687							
PKG:1									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

Z2620021 ^S		NO. 1 ENGINE FIRE EXTINGUISHER CONTAINER PLUMBING - PERFORM DETAILED INSPECTION						Service	ATA:26
	MOS	21-Aug-25	12						
	HRS	9809.8	300						
	AFL	7471							
PKG:2									
PROC. REF: AMM 26-21-00PROC. REF: AMM 26-21-00									

Z2620021 ^S		NO. 2 ENGINE FIRE EXTINGUISHER CONTAINER PLUMBING - PERFORM DETAILED INSPECTION						Service	ATA:26
	MOS	21-Aug-25	12						
	HRS	9809.8	300						
	AFL	7471							
PKG:2									
PROC. REF: AMM 26-21-00PROC. REF: AMM 26-21-00									

ATA 27 - FLIGHT CONTROLS

270301		TRIM SWITCH PANEL						Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN	0				
SN:UNKNOWN	HRS	0		TSN	0				
	AFL	0		TSN	0				
PROC. REF: AMM 27-00-01PROC. REF: AMM 27-00-01									

271001		LEFT AILERON CONTROL SYSTEM CROSSOVER CABLE						Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN	0				
SN:UNKNOWN	HRS	0		TSN	0				
	AFL	0		TSN	0				
PROC. REF: AMM 27-10-05PROC. REF: AMM 27-10-05									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
271002 RIGHT AILERON CONTROL SYSTEM CROSSOVER CABLE									Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-10-05PROC. REF: AMM 27-10-05									
271003 LEFT AILERON CONTROL SYSTEM CABLE									Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-10-05PROC. REF: AMM 27-10-05									
271004 RIGHT AILERON CONTROL SYSTEM CABLE									Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-10-05PROC. REF: AMM 27-10-05									
271005 AFT AILERON CONTROL SYSTEM CABLE									Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-10-05PROC. REF: AMM 27-10-05									
271045 LEFT INBOARD AILERON CONTROL CABLE									Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-10-05PROC. REF: AMM 27-10-05									
271046 RIGHT INBOARD AILERON CONTROL CABLE									Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-10-05PROC. REF: AMM 27-10-05									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
271051 LEFT FORWARD OUTBOARD AILERON CONTROL CABLE									Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-10-05PROC. REF: AMM 27-10-05									
271052 RIGHT FORWARD OUTBOARD AILERON CONTROL CABLE									Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-10-05PROC. REF: AMM 27-10-05									
271053 LEFT AFT OUTBOARD AILERON CONTROL CABLE									Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-10-05PROC. REF: AMM 27-10-05									
271054 RIGHT AFT OUTBOARD AILERON CONTROL CABLE									Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-10-05PROC. REF: AMM 27-10-05									
271083 AILERON TRIM TAB ACTUATOR									Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-10-09PROC. REF: AMM 27-10-09									
271088 AILERON SPINDLE									Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	H/T	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
271095 PILOT ANGLE OF ATTACK INDICATOR (AOA)									Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
271096 COPILOT ANGLE OF ATTACK INDICATOR (AOA)									Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
272001 FORWARD UPPER RUDDER CONTROL SYSTEM CABLE									Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-20-08PROC. REF: AMM 27-20-08									
272002 FORWARD LOWER RUDDER CONTROL SYSTEM CABLE									Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-20-08PROC. REF: AMM 27-20-08									
272003 LEFT AFT UPPER RUDDER CONTROL SYSTEM CABLE									Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-20-08PROC. REF: AMM 27-20-08									
272004 RIGHT AFT UPPER RUDDER CONTROL SYSTEM CABLE									Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-20-08PROC. REF: AMM 27-20-08									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
272005 LEFT AFT LOWER RUDDER CONTROL SYSTEM CABLE									Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-20-08PROC. REF: AMM 27-20-08									
272006 RIGHT AFT LOWER RUDDER CONTROL SYSTEM CABLE									Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-20-08PROC. REF: AMM 27-20-08									
272021 RUDDER TRIM TAB ACTUATOR									Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-20-03PROC. REF: AMM 27-20-03									
272031 PILOT RUDDER PEDAL ADJUST ACTUATOR									Component ATA:27
PN:6627208001-003 (4389596)	MOS/MSC	17-Feb-05	O/C						
SN:0437	HRS	3300.2							
	AFL	2515							
PROC. REF: AMM 27-20-05PROC. REF: AMM 27-20-05									
272032 COPILOT RUDDER PEDAL ADJUST ACTUATOR									Component ATA:27
PN:6627208001-003 (4389596)	MOS/MSC	17-Feb-05	O/C						
SN:0431	HRS	3300.2							
	AFL	2515							
PROC. REF: AMM 27-20-05PROC. REF: AMM 27-20-05									
273001 PILOT FORWARD ELEVATOR CONTROL SYSTEM CABLE									Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-30-05PROC. REF: AMM 27-30-05									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 27 - FLIGHT CONTROLS										
273002		COPILOT FORWARD ELEVATOR CONTROL SYSTEM CABLE						Component	ATA:27	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-30-05PROC. REF: AMM 27-30-05										
273003		LEFT AFT UPPER ELEVATOR CONTROL SYSTEM CABLE						Component	ATA:27	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-30-05PROC. REF: AMM 27-30-05										
273004		RIGHT AFT UPPER ELEVATOR CONTROL SYSTEM CABLE						Component	ATA:27	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-30-05PROC. REF: AMM 27-30-05										
273005		LEFT AFT LOWER ELEVATOR CONTROL SYSTEM CABLE						Component	ATA:27	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-30-05PROC. REF: AMM 27-30-05										
273006		RIGHT AFT LOWER ELEVATOR CONTROL SYSTEM CABLE						Component	ATA:27	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-30-05PROC. REF: AMM 27-30-05										
273015		LEFT ANGLE OF ATTACK VANE (AOA)						Component	ATA:27	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-31-04PROC. REF: AMM 27-31-04										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
273016 RIGHT ANGLE OF ATTACK VANE (AOA)									Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-31-04PROC. REF: AMM 27-31-04									
273022 LEFT ANGLE OF ATTACK TRANSMITTER (AOA)									Component ATA:27
PN:C-38817-1	MOS/MSC	11-Dec-23	O/C						
SN:1333	HRS	9373.9							
	AFL	7179							
PROC. REF: AMM 27-31-01PROC. REF: AMM 27-31-01									
273023 RIGHT ANGLE OF ATTACK TRANSMITTER (AOA)									Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-31-01PROC. REF: AMM 27-31-01									
273051 ELEVATOR DISCONNECT ACTUATOR									Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-30-09PROC. REF: AMM 27-30-09									
273063 PILOT STICK SHAKER									Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-31-03PROC. REF: AMM 27-31-03									
273064 COPILOT STICK SHAKER									Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-31-03PROC. REF: AMM 27-31-03									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 27 - FLIGHT CONTROLS										
273087		STALL WARNING COMPUTER						Component	ATA:27	
PN:C-38806-2	MOS/MSC	14-Feb-24	O/C							
SN:132	HRS	9467.2								
	AFL	7246								
PROC. REF: AMM 27-31-02PROC. REF: AMM 27-31-02										
273201		ELEVATOR DISCONNECT CURRENT LIMITER						Component	ATA:27	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-30-13PROC. REF: AMM 27-30-13										
273420		ELEVATOR OVERRIDE ACTUATOR						Component	ATA:27	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-30-14PROC. REF: AMM 27-30-14										
274011		HORIZONTAL STABILIZER ACTUATOR						Component	ATA:27	
PN:6627401000-009	MOS/MSC	22-Jun-23	O/C	TSO 10						
SN:B0581	HRS	9258.5		TSO 175.9						
	AFL	7100		TSO 106						
PROC. REF: AMM 27-40-02PROC. REF: AMM 27-40-02										
274031		TRIM-IN-MOTION DETECTOR						Component	ATA:27	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-41-01PROC. REF: AMM 27-41-01										
274041		FORWARD INTERFACE UNIT						Component	ATA:27	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-40-04PROC. REF: AMM 27-40-04										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 27 - FLIGHT CONTROLS										
274051	HORIZONTAL STABILIZER ACTUATOR CONTROL BOX								Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-40-02, AMM 27-40-03PROC. REF: AMM 27-40-02, AMM 27-40-03										
275020	LEFT OUTBOARD FLAP ACTUATOR								Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-50-06PROC. REF: AMM 27-50-06										
275021	LEFT INBOARD FLAP ACTUATOR								Component	ATA:27
PN:6627503000-009	MOS/MSC	18-Jul-07	O/C							
SN:1743	HRS	5671.55								
	AFL	4333								
PROC. REF: AMM 27-50-06PROC. REF: AMM 27-50-06										
275022	RIGHT INBOARD FLAP ACTUATOR								Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-50-06PROC. REF: AMM 27-50-06										
275023	RIGHT OUTBOARD FLAP ACTUATOR								Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-50-06PROC. REF: AMM 27-50-06										
275057	FLAP DRIVE POWER UNIT								Component	ATA:27
PN:6627503000-029	MOS/MSC	25-Feb-11	O/C							
SN:1461	HRS	6519.3								
	AFL	4991								
PROC. REF: AMM 27-50-08PROC. REF: AMM 27-50-08										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 27 - FLIGHT CONTROLS										
275058		FLAP CONTROL UNIT						Component	ATA:27	
PN:C144486-3-003	MOS/MSC	05-Jan-20	O/C							
SN:1343	HRS	8209.7								
	AFL	6328								
PROC. REF: AMM 27-50-05PROC. REF: AMM 27-50-05										
275069		FLAP POSITION INDICATOR						Component	ATA:27	
PN:C145159-1	MOS/MSC	09-Oct-23	O/C							
SN:135	HRS	9332.6								
	AFL	7149								
PROC. REF: AMM 27-50-07PROC. REF: AMM 27-50-07										
275080		FLAP CONTROL MODULE						Component	ATA:27	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-50-02PROC. REF: AMM 27-50-02										
275081		LEFT FLAP DRIVE ROTARY VARIABLE DIFFERENTIAL TRANSFORMER						Component	ATA:27	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-50-03PROC. REF: AMM 27-50-03										
275082		RIGHT FLAP DRIVE ROTARY VARIABLE DIFFERENTIAL TRANSFORMER						Component	ATA:27	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-50-03PROC. REF: AMM 27-50-03										
276001		LEFT SPOILER ACTUATOR						Component	ATA:27	
PN:6627602001-007	MOS/MSC	15-Jun-06	O/C							
SN:DWA392-00	HRS	4570.25								
	AFL	3497								
PROC. REF: AMM 27-60-04PROC. REF: AMM 27-60-04										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 27 - FLIGHT CONTROLS										
276002		RIGHT SPOILER ACTUATOR						Component	ATA:27	
PN:6627602001-007	MOS/MSC	15-Jun-06	O/C							
SN:DAW398-00	HRS	4570.25								
	AFL	3497								
PROC. REF: AMM 27-60-04PROC. REF: AMM 27-60-04										
276005		SPOILER CONTROL MODULE						Component	ATA:27	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-60-03PROC. REF: AMM 27-60-03										
276010		SPOILERON CONTROLLER RESISTOR BOX						Component	ATA:27	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-60-10PROC. REF: AMM 27-60-10										
276013		SPOILER SHUTOFF VALVE						Component	ATA:27	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-60-07PROC. REF: AMM 27-60-07										
276020		SPOILER LOW PRESSURE SWITCH						Component	ATA:27	
PN:6629101004-003	MOS/MSC	11-Jun-16	O/C							
SN:535	HRS	7630.1								
	AFL	5823								
PROC. REF: AMM 27-60-08PROC. REF: AMM 27-60-08										
276031		LEFT SPOILER ROTARY VARIABLE DIFFERENTIAL TRANSFORMER						Component	ATA:27	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-60-05PROC. REF: AMM 27-60-05										

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 27 - FLIGHT CONTROLS										
276032	RIGHT SPOILER ROTARY VARIABLE DIFFERENTIAL TRANSFORMER								Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 27-60-05PROC. REF: AMM 27-60-05										
276073	SPOILERON COMPUTER								Component	ATA:27
PN:6627608500-007	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:00227	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 27-60-02PROC. REF: AMM 27-60-02										
276076	CONTROL WHEEL ROTARY VARIABLE DIFFERENTIAL TRANSFORMER								Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 27-60-06PROC. REF: AMM 27-60-06										
5-19-01-W2750055	* FLAP ACTUATOR JOINT (P/N 145673-1) (IRN W2750055) REPLACEMENT								Component	ATA:27
PN:159174-1	MOS/MSC	05-Dec-19	N/A	TSN 4372						
SN:UNKNOWN	HRS	8177.8	NOT APPLICABLE							
	AFL	6304								
A2711001 ^S	** AILERON TRIM TAB CONTROL SYSTEM - PERFORM OPERATIONAL CHECK								Service	ATA:27
	MOS	02-Aug-24	24	AIRWORTHINESS						
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 27-10-04PROC. REF: AMM 27-10-04										
A2721001 ^S	** RUDDER TRIM SYSTEM - PERFORM OPERATIONAL CHECK								Service	ATA:27
	MOS	02-Aug-24	24	AIRWORTHINESS						
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 27-20-00PROC. REF: AMM 27-20-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 27 - FLIGHT CONTROLS										
A2731002 ^S	** ELEVATOR DISCONNECT SYSTEM - PERFORM OPERATIONAL CHECK								Service	ATA:27
	MOS	02-Aug-24	24					AIRWORTHINESS		
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 27-30-00PROC. REF: AMM 27-30-00										
PKG:8										
A2760001 ^S	** SPOILER ACTUATOR CHECK VALVE - PERFORM OPERATIONAL CHECK								Service	ATA:27
	MOS	02-Aug-24	24					AIRWORTHINESS		
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 27-60-04PROC. REF: AMM 27-60-04										
PKG:10										
A2760002 ^S	** SPOILER SYSTEM - PERFORM SPOILER AUTHORITY WITH FLAPS CHECK								Service	ATA:27
	MOS	02-Aug-24	24					AIRWORTHINESS		
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 27-60-00PROC. REF: AMM 27-60-00										
PKG:10										
AA2700000 ^S	AILERON CONTROL CABLE SYSTEM - WITH COCKPIT AND CABIN FLOORBOARDS REMOVED, PERFORM VISUAL INSPECTION OF CABLES								Service	ATA:27
	MOS	02-Aug-24	24							
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00										
PKG:7										
AA2700001 ^S	RUDDER CONTROL CABLE SYSTEM - WITH COCKPIT AND CABIN FLOORBOARDS REMOVED, PERFORM VISUAL INSPECTION OF CABLES								Service	ATA:27
	MOS	02-Aug-24	24							
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00										
PKG:7										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
AA2700002 ^S	ELEVATOR CONTROL CABLE SYSTEM - WITH COCKPIT AND CABIN FLOORBOARDS REMOVED, PERFORM VISUAL INSPECTION OF CABLES							Service	ATA:27
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00									
AA2760021	LEFT SPOILER HYDRAULIC SYSTEM PRESSURE SWIVEL - REPLACE							Service	ATA:27
	MOS	22-Jun-23							
	HRS	9258.5	1200		10458.5		435.4		
	AFL	7100							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
AA2760021	LEFT SPOILER HYDRAULIC SYSTEM RETURN SWIVEL - REPLACE							Service	ATA:27
	MOS	22-Jun-23							
	HRS	9258.5	1200		10458.5		435.4		
	AFL	7100							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
AA2760021	RIGHT SPOILER HYDRAULIC SYSTEM PRESSURE SWIVEL - REPLACE							Service	ATA:27
	MOS	22-Jun-23							
	HRS	9258.5	1200		10458.5		435.4		
	AFL	7100							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
AA2760021	RIGHT SPOILER HYDRAULIC SYSTEM RETURN SWIVEL - REPLACE							Service	ATA:27
	MOS	22-Jun-23							
	HRS	9258.5	1200		10458.5		435.4		
	AFL	7100							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
AD2760085 ^S	SPOILER LEVER ARM - PERFORM DETAILED VISUAL INSPECTION TO ENSURE SPOILER LEVER ARM IS PROPERLY SEATED AND SECURED ON SPOILER RVDT SHAFT							Service	ATA:27
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							

PKG:7

PKG:10

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 27 - FLIGHT CONTROLS

PROC. REF: AMM 27-60-05PROC. REF: AMM 27-60-05

AE2710049	* AILERON LEADING EDGE (INTERNAL) - PERFORM BORESCOPE INSPECTION							Service	ATA:27
	MOS	EFF	T:6		11-Jun-26 *		16 d	AIRWORTHINESS	
	HRS								
	AFL								
PROC. REF: AMM 27-10-02PROC. REF: AMM 27-10-02									

AE2730037 ^S	PERFORM DETAILED VISUAL INSPECTION OF THE ELEVATOR UP/DOWN SPRING ASSEMBLY, YOKE ASSEMBLY AND ASSOCIATED PARTS FOR FREE MOVEMENT, LOOSE FASTENERS AND SECURITY OF LOCKING DEVICES							Service	ATA:27
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
									PKG:14
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

D2740003	** HORIZONTAL STABILIZER ACTUATOR SECONDARY TRIM - PERFORM FUNCTIONAL TEST							Service	ATA:27
PN:6627401000-009	MOS	02-Aug-24						AIRWORTHINESS	
SN:B0581	HRS	9525.7	600		10125.7		102.6		
	AFL	7276							
PROC. REF: AMM 27-40-02PROC. REF: AMM 27-40-02									

D2740004	** HORIZONTAL STABILIZER ACTUATOR PRIMARY TRIM - PERFORM FUNCTIONAL TEST							Service	ATA:27
PN:6627401000-009	MOS	02-Aug-24						AIRWORTHINESS	
SN:B0581	HRS	9525.7	600		10125.7		102.6		
	AFL	7276							
PROC. REF: AMM 27-40-02PROC. REF: AMM 27-40-02									

G2710003 ^S	AILERON CONTROL SYSTEM CABLES (LOCATED IN WING) - PERFORM CABLE TENSION CHECK							Service	ATA:27
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
									PKG:16
PROC. REF: AMM 27-10-00PROC. REF: AMM 27-10-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
G2710004 ^S	AILERON CONTROL SYSTEM CABLES (LOCATED IN FUSELAGE) - PERFORM CABLE TENSION CHECK							Service	ATA:27
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 27-10-00PROC. REF: AMM 27-10-00									
G2720003 ^S	RUDDER CONTROL CABLES - PERFORM TENSION CHECK							Service	ATA:27
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 27-20-00PROC. REF: AMM 27-20-00									
G2720004 ^S	RUDDER PEDALS, PEDAL PUSHRODS, ADJUSTMENT ACTUATOR, AND SECTORS - PERFORM VISUAL INSPECTION. CHECK DURING FULL TRAVEL OF RUDDER.							Service	ATA:27
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
G2730003 ^S	ELEVATOR CONTROL CABLES - PERFORM TENSION CHECK							Service	ATA:27
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 27-30-00PROC. REF: AMM 27-30-00									
K2700007	* AILERON CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED VISUAL INSPECTION							Service	ATA:27
	MOS	22-Jun-23						AIRWORTHINESS	
	HRS	9258.5	4800		14058.5		4035.4		
	AFL	7100							
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 27 - FLIGHT CONTROLS										
K2700008	* ELEVATOR CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED VISUAL INSPECTION								Service	ATA:27
	MOS	22-Jun-23						AIRWORTHINESS		
	HRS	9258.5	4800		14058.5		4035.4			
	AFL	7100								
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00										
K2700009	* RUDDER CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED VISUAL INSPECTION								Service	ATA:27
	MOS	22-Jun-23						AIRWORTHINESS		
	HRS	9258.5	4800		14058.5		4035.4			
	AFL	7100								
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00										
K2700010	* ELEVATOR CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED VISUAL INSPECTION								Service	ATA:27
	MOS	22-Jun-23						AIRWORTHINESS		
	HRS	9258.5	4800		14058.5		4035.4			
	AFL	7100								
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00										
K2700012	* RUDDER CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED VISUAL INSPECTION								Service	ATA:27
	MOS	22-Jun-23						AIRWORTHINESS		
	HRS	9258.5	4800		14058.5		4035.4			
	AFL	7100								
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00										
K2700014	* AILERON CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED VISUAL INSPECTION								Service	ATA:27
	MOS	22-Jun-23						AIRWORTHINESS		
	HRS	9258.5	4800		14058.5		4035.4			
	AFL	7100								
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00										
N2720030	RUDDER TORQUE TUBE AND SPINDLE - PERFORM DETAILED VISUAL INSPECTION								Service	ATA:27
	MOS	21-Aug-25	72		21-Aug-31		1913 d	AIRWORTHINESS		
	HRS	9809.8								
	AFL	7471								
PROC. REF: AMM 27-20-01PROC. REF: AMM 27-20-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 27 - FLIGHT CONTROLS										
N2740023		* HORIZONTAL STABILIZER ACTUATOR ACME SCREW - REPLACE							Service	ATA:27
PN:6627401000-009	MOS/MSC	18-Aug-22	N/A							
SN:B0581	HRS	9082.6								
	AFL	6994								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
N2740024		* HORIZONTAL STABILIZER ACTUATOR ACME NUT - REPLACE							Service	ATA:27
PN:6627401000-009	MOS/MSC	18-Aug-22	N/A							
SN:B0581	HRS	9082.6								
	AFL	6994								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
N2740025		* HORIZONTAL STABILIZER ACTUATOR - PERFORM DETAILED STRUCTURAL INSPECTION							Service	ATA:27
	MOS/MSC	18-Aug-22	N/A							
	HRS	9082.6								
	AFL	6994								
P2740032		* HORIZONTAL STABILIZER ACTUATOR - PERFORM INSPECTION							Service	ATA:27
PN:6627401000-009	MOS	18-Aug-22						AIRWORTHINESS		
SN:B0581	HRS	9082.6	1200		10282.6		259.5			
	AFL	6994								
P2740033		* HORIZONTAL STABILIZER ACTUATOR - PERFORM DETAILED STRUCTURAL INSPECTION							Service	ATA:27
PN:6627401000-009	MOS	18-Aug-22								
SN:B0581	HRS	9082.6	2400		11482.6		1459.5			
	AFL	6994								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
R2710041		* AILERON SPINDLE - REPLACE							Service	ATA:27
	MOS	30-Mar-21	120		30-Mar-31		1769 d	LIFE LIMIT		
	HRS	8414.4								
	AFL	6463								
PROC. REF: AMM 27-10-07PROC. REF: AMM 27-10-07										

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 27 - FLIGHT CONTROLS										
S2750057	* FLAP ACTUATOR BALLNUT SLEEVE - PERFORM FLUORESCENT PENETRANT INSPECTION								Service	ATA:27
	MOS/MSC	05-Dec-19	N/A							
	HRS	8177.8								
	AFL	6304								
PROC. REF: NDT PART 8/27-50-01, NDT PART 8/27-50-02PROC. REF: NDT PART 8/27-50-01, NDT PART 8/27-50-02										
T2740002	* HORIZONTAL STABILIZER ACTUATOR - PERFORM INSPECTION								Service	ATA:27
	MOS/MSC	18-Aug-22	N/A							
	HRS	9082.6								
	AFL	6994								
V2712000 ^S	** ROLL DISCONNECT SWITCHES - PERFORM OPERATIONAL CHECK								Service	ATA:27
	MOS	02-Aug-24	24					AIRWORTHINESS		
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 27-60-09PROC. REF: AMM 27-60-09										
W2731001 ^S	** PITCH TRIM - PERFORM OPERATIONAL CHECK OF ELEVATOR OVERRIDE ACTUATOR								Service	ATA:27
	MOS	02-Aug-24	24					AIRWORTHINESS		
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 27-30-14PROC. REF: AMM 27-30-14										
W2750055	* LEFT INBOARD FLAP ACTUATOR JOINT - REPLACE								Service	ATA:27
	MOS/MSC	05-Dec-19	N/A							
	HRS	8177.8								
	AFL	6304								
W2750055	* LEFT OUTBOARD FLAP ACTUATOR JOINT - REPLACE								Service	ATA:27
	MOS/MSC	05-Dec-19	N/A							
	HRS	8177.8								
	AFL	6304								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 27 - FLIGHT CONTROLS										
W2750055	* RIGHT INBOARD FLAP ACTUATOR JOINT - REPLACE								Service	ATA:27
	MOS/MSC	05-Dec-19	N/A							
	HRS	8177.8								
	AFL	6304								
W2750055	* RIGHT OUTBOARD FLAP ACTUATOR JOINT - REPLACE								Service	ATA:27
	MOS/MSC	05-Dec-19	N/A							
	HRS	8177.8								
	AFL	6304								
W2750056	* LEFT INBOARD FLAP ACTUATOR JOINT - PERFORM DETAILED VISUAL INSPECTION. APPLY CORROSION PREVENTIVE COMPOUND (CPC) TO JOINT.								Service	ATA:27
	MOS/MSC	05-Dec-19	N/A							
	HRS	8177.8								
	AFL	6304								
PROC. REF: AMM 12-21-03, AMM 27-50-06PROC. REF: AMM 12-21-03, AMM 27-50-06										
W2750056	* LEFT OUTBOARD FLAP ACTUATOR JOINT - PERFORM DETAILED VISUAL INSPECTION. APPLY CORROSION PREVENTIVE COMPOUND (CPC) TO JOINT.								Service	ATA:27
	MOS/MSC	05-Dec-19	N/A							
	HRS	8177.8								
	AFL	6304								
PROC. REF: AMM 12-21-03, AMM 27-50-06PROC. REF: AMM 12-21-03, AMM 27-50-06										
W2750056	* RIGHT INBOARD FLAP ACTUATOR JOINT - PERFORM DETAILED VISUAL INSPECTION. APPLY CORROSION PREVENTIVE COMPOUND (CPC) TO JOINT.								Service	ATA:27
	MOS/MSC	05-Dec-19	N/A							
	HRS	8177.8								
	AFL	6304								
PROC. REF: AMM 12-21-03, AMM 27-50-06PROC. REF: AMM 12-21-03, AMM 27-50-06										
W2750056	* RIGHT OUTBOARD FLAP ACTUATOR JOINT - PERFORM DETAILED VISUAL INSPECTION. APPLY CORROSION PREVENTIVE COMPOUND (CPC) TO JOINT.								Service	ATA:27
	MOS/MSC	05-Dec-19	N/A							
	HRS	8177.8								
	AFL	6304								
PROC. REF: AMM 12-21-03, AMM 27-50-06PROC. REF: AMM 12-21-03, AMM 27-50-06										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
Y2700003 ^S	AILERON CONTROL CABLE SYSTEM - PERFORM VISUAL INSPECTION OF CABLES WITHIN WING							Service	ATA:27
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PKG:10									
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00									
Y2700004 ^S	RUDDER CONTROL CABLE SYSTEM - PERFORM VISUAL INSPECTION OF ACCESSIBLE UPPER AND LOWER CABLES							Service	ATA:27
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PKG:8									
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00									
Y2700005 ^S	ELEVATOR CONTROL CABLE SYSTEM - PERFORM VISUAL INSPECTION OF ACCESSIBLE UPPER AND LOWER CABLES							Service	ATA:27
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PKG:8									
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00									
Y2700006 ^S	RUDDER AND ELEVATOR CONTROL CABLES AND ASSOCIATED PULLEYS, LOCATED IN AFT PRESSURE BULKHEAD SUPPORT CHANNEL - PERFORM VISUAL INSPECTION							Service	ATA:27
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PKG:9									
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00									
Y2710000 ^S	AILERONS, AILERON TRIM TAB AND VISIBLE PORTION OF RODS - PERFORM VISUAL INSPECTION							Service	ATA:27
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PKG:10									
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 27 - FLIGHT CONTROLS										
Y2710001	^S	AILERON BALANCE WEIGHT INSTALLATION AND SUPPORTING STRUCTURE - PERFORM VISUAL INSPECTION						Service	ATA:27	
	MOS	09-Mar-01	48							
	HRS	0	1200							
	AFL	0								
PKG:16										
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
Y2710002	^S	AILERON CONTROL SYSTEM - PERFORM OPERATIONAL CHECK						Service	ATA:27	
	MOS	09-Mar-01	48							
	HRS	0	1200							
	AFL	0								
PKG:16										
PROC. REF: AMM 27-10-00PROC. REF: AMM 27-10-00										
Y2710048	^S	AILERON TRIM TAB INSTALLATION - PERFORM FREE PLAY CHECK						Service	ATA:27	
	MOS	09-Mar-01								
	HRS	0	T:9600							
	AFL	0								
PKG:22										
PROC. REF: AMM 27-10-04PROC. REF: AMM 27-10-04										
Y2720000	^S	RUDDER - PERFORM VISUAL INSPECTION						Service	ATA:27	
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PKG:2										
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
Y2720001	^S	RUDDER BALANCE WEIGHT INSTALLATION AND SUPPORTING STRUCTURE - PERFORM VISUAL INSPECTION						Service	ATA:27	
	MOS	09-Mar-01	48							
	HRS	0	1200							
	AFL	0								
PKG:14										
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
Y2720002 ^S	RUDDER CONTROL SYSTEM - PERFORM OPERATIONAL CHECK							Service	ATA:27
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PKG:14									
PROC. REF: AMM 27-20-00PROC. REF: AMM 27-20-00									
Y2721000 ^S	RUDDER TRIM TAB AND VISIBLE RODS - PERFORM VISUAL INSPECTION							Service	ATA:27
	MOS	21-Aug-25	12						
	HRS	9809.8	300						
	AFL	7471							
PKG:2									
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
Y2730000 ^S	CONTROL COLUMNS - PERFORM VISUAL INSPECTION. PAY PARTICULAR ATTENTION TO AILERON CONTROL WHEEL CABLE DRUM AND BOTTOM CROSSOVER PULLEYS.							Service	ATA:27
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PKG:13									
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
Y2730001 ^S	ELEVATORS - PERFORM VISUAL INSPECTION							Service	ATA:27
	MOS	21-Aug-25	12						
	HRS	9809.8	300						
	AFL	7471							
PKG:2									
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
Y2730002 ^S	ELEVATOR CONTROL SYSTEM - PERFORM OPERATIONAL CHECK							Service	ATA:27
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PKG:14									
PROC. REF: AMM 27-30-00PROC. REF: AMM 27-30-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 27 - FLIGHT CONTROLS										
Y2730004	^S	CONTROL COLUMNS - PERFORM INSPECTION. INSPECT CABLE, PULLEYS, BEARINGS, AND ELECTRICAL WIRING							Service	ATA:27
	MOS	25-Nov-19	96							
	HRS	8177.7	2400							
	AFL	6303								
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00										
PKG:19										
Y2730007	^S	AFT ELEVATOR DISCONNECT - PERFORM DETAILED VISUAL INSPECTION							Service	ATA:27
	MOS	25-Nov-19	96							
	HRS	8177.7	2400							
	AFL	6303								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
PKG:20										
Y2740000	^S	PRIMARY PITCH TRIM SYSTEM - PERFORM OPERATIONAL CHECK							Service	ATA:27
	MOS	09-Mar-01	48							
	HRS	0	1200							
	AFL	0								
PROC. REF: AMM 27-40-00PROC. REF: AMM 27-40-00										
PKG:14										
Y2740001	^S	SECONDARY PITCH TRIM SYSTEM - PERFORM OPERATIONAL CHECK							Service	ATA:27
	MOS	09-Mar-01	48							
	HRS	0	1200							
	AFL	0								
PROC. REF: AMM 27-40-00PROC. REF: AMM 27-40-00										
PKG:14										
Y2750000	^S	FLAP DRIVE INSTALLATION - PERFORM VISUAL INSPECTION WITH FLAPS LOWERED							Service	ATA:27
	MOS	02-Aug-24	24							
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
PKG:10										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 27 - FLIGHT CONTROLS

Y2750001	^S	FLAPS - PERFORM VISUAL INSPECTION						Service	ATA:27
	MOS	21-Aug-25	12						
	HRS	9809.8	300						
	AFL	7471							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									

PKG:4

Y2750053	^S	FLAP DRIVE ACTUATORS - PERFORM A VISUAL INSPECTION OF THE ACTUATOR ATTACHMENT, PAYING PARTICULAR ATTENTION TO THE GIMBAL PIN RETAINING RINGS						Service	ATA:27
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									

PKG:10

Y2760000	^S	SPOILER AND SPOILER ACTUATOR - PERFORM VISUAL INSPECTION WITH FLAPS LOWERED AND ACCESS PANELS OPENED						Service	ATA:27
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									

PKG:10

ATA 28 - FUEL

281001	LEFT NO. 1 FUEL EJECTOR SCAVENGE PUMP						Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN	0			
SN:UNKNOWN	HRS	0		TSN	0			
	AFL	0		TSN	0			
PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01								

281002	RIGHT NO. 1 FUEL EJECTOR SCAVENGE PUMP						Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN	0			
SN:UNKNOWN	HRS	0		TSN	0			
	AFL	0		TSN	0			
PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
281003 LEFT NO. 2 FUEL EJECTOR SCAVENGE PUMP									Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01									
281004 RIGHT NO. 2 FUEL EJECTOR SCAVENGE PUMP									Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01									
281005 LEFT NO. 3 FUEL EJECTOR SCAVENGE PUMP									Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01									
281006 RIGHT NO. 3 FUEL EJECTOR SCAVENGE PUMP									Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01									
281007 LEFT NO. 4 FUEL EJECTOR SCAVENGE PUMP									Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01									
281008 RIGHT NO. 4 FUEL EJECTOR SCAVENGE PUMP									Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
281009 LEFT NO. 5 FUEL EJECTOR SCAVENGE PUMP									Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01									
281010 RIGHT NO. 5 FUEL EJECTOR SCAVENGE PUMP									Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01									
281031 FUSELAGE FUEL CELL									Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-10-02PROC. REF: AMM 28-10-02									
281051 FUEL CROSSFLOW SHUTOFF VALVE									Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-12-02PROC. REF: AMM 28-12-02									
281401 SURGE TANK FLOAT VALVE									Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-11-02PROC. REF: AMM 28-11-02									
281501 LEFT FLEX FUEL HOSE ASSY									Component ATA:28
PN:244224151	MOS/MSC	26-May-05	O/C						
SN:F16806-04	HRS	3623.3							
WC#: 28.015	AFL	2739							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 28 - FUEL										
281502		RIGHT FLEX FUEL HOSE ASSY						Component	ATA:28	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
WC#: 28.015	AFL	0	TSN 0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
<hr/>										
281521		LEFT FUEL TRANSFER CHECK VALVE						Component	ATA:28	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 28-12-03PROC. REF: AMM 28-12-03										
<hr/>										
281522		RIGHT FUEL TRANSFER CHECK VALVE						Component	ATA:28	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 28-12-03PROC. REF: AMM 28-12-03										
<hr/>										
282001		LEFT FUEL SHUTOFF VALVE						Component	ATA:28	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 28-20-06PROC. REF: AMM 28-20-06										
<hr/>										
282003		RIGHT FUEL SHUTOFF VALVE						Component	ATA:28	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 28-20-06PROC. REF: AMM 28-20-06										
<hr/>										
282011		SHUTOFF - REFUEL VALVE						Component	ATA:28	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 28-20-10PROC. REF: AMM 28-20-10										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 28 - FUEL										
282031		LEFT NO. 1 FUEL SUPPLY CHECK VALVE						Component	ATA:28	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 28-20-03PROC. REF: AMM 28-20-03										
282032		LEFT NO. 2 FUEL SUPPLY CHECK VALVE						Component	ATA:28	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 28-20-03PROC. REF: AMM 28-20-03										
282033		RIGHT NO. 1 FUEL SUPPLY CHECK VALVE						Component	ATA:28	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 28-20-03PROC. REF: AMM 28-20-03										
282034		RIGHT NO. 2 FUEL SUPPLY CHECK VALVE						Component	ATA:28	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 28-20-03PROC. REF: AMM 28-20-03										
282037		RIGHT FUEL SUPPLY SHUT-OFF VALVE ASSEMBLY						Component	ATA:28	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 28-20-06PROC. REF: AMM 28-20-06										
282038		LEFT FUEL SUPPLY SHUT-OFF VALVE ASSEMBLY						Component	ATA:28	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 28-20-06PROC. REF: AMM 28-20-06										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 28 - FUEL										
282041 REFUELING CONTROL PANEL									Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-20-14PROC. REF: AMM 28-20-14										
282051 LEFT MOTIVE FLOW CHECK VALVE									Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-20-05PROC. REF: AMM 28-20-05										
282052 RIGHT MOTIVE FLOW CHECK VALVE									Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-20-05PROC. REF: AMM 28-20-05										
282063 PRE-CHECK SINGLE POINT PRESSURE REFUELING (SPPR) VALVE									Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-20-12PROC. REF: AMM 28-20-12										
282064 PILOT OPERATED SINGLE POINT PRESSURE REFUELING (SPPR) VALVE									Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-20-11PROC. REF: AMM 28-20-11										
282075 LEFT MAIN FUEL EJECTOR PUMP ASSEMBLY									Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-20-01PROC. REF: AMM 28-20-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
282076 RIGHT MAIN FUEL EJECTOR PUMP ASSEMBLY									Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-20-01PROC. REF: AMM 28-20-01									
282087 LEFT STANDBY FUEL PUMP									Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-20-02PROC. REF: AMM 28-20-02									
282088 RIGHT STANDBY FUEL PUMP									Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-20-02PROC. REF: AMM 28-20-02									
282601 DEFUEL SHUTOFF VALVE									Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-20-07PROC. REF: AMM 28-20-07									
282602 REFUEL CHECK VALVE									Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-20-09PROC. REF: AMM 28-20-09									
282603 SINGLE POINT PRESSURE REFUELING (SPPR) ADAPTER									Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
282815 APU FUEL SHUTOFF VALVE									Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-20-04PROC. REF: AMM 28-20-04									
282829 APU FUEL LINE									Component ATA:28
PN:PN	MOS/MSC	EFF	N/A	TSN 0					
SN:UNKNOWN	HRS	EFF		TSN 0					
	AFL			TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
2840001 EMP * DUAL FUEL FLOW CONVERTER (DFFC) - PERFORM ACCEPTANCE TEST AND LOW TEMPERATURE SCREENING									Service ATA:28
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
284001 C1 FUEL PROBE									Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05									
284002 C2 FUEL PROBE									Component ATA:28
PN:10552T03Y00	MOS/MSC	22-May-06	O/C						
SN:0117	HRS	4507.7							
	AFL	3441							
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05									
284003 C3 FUEL PROBE									Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 28 - FUEL										
284004	C4 FUEL PROBE								Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05										
<hr/>										
284005	C5 FUEL PROBE								Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05										
<hr/>										
284006	C6 FUEL PROBE								Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05										
<hr/>										
284008	C7 FUEL PROBE								Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05										
<hr/>										
284009	C8 FUEL PROBE								Component	ATA:28
PN:10552T03Y00	MOS/MSC	22-May-06	O/C							
SN:7262	HRS	4507.7								
	AFL	3441								
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05										
<hr/>										
284010	C9 FUEL PROBE								Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 28 - FUEL										
284011	C10 FUEL PROBE								Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05										
<hr/>										
284012	C11 FUEL PROBE								Component	ATA:28
PN:6628408000-009	MOS/MSC	04-Jul-07	O/C							
SN:B408	HRS	5595.25								
	AFL	4268								
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05										
<hr/>										
284013	C12 FUEL PROBE								Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05										
<hr/>										
284014	C13 FUEL PROBE								Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05										
<hr/>										
284015	C14 FUEL PROBE								Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05										
<hr/>										
284016	C15 FUEL PROBE								Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 28 - FUEL										
284017	C16 FUEL PROBE								Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05										
<hr/>										
284033	FUSELAGE FUEL PROBE								Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05										
<hr/>										
284035	NO. 1 LOW PRESSURE FUEL SWITCH								Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-01PROC. REF: AMM 28-40-01										
<hr/>										
284036	NO. 2 LOW PRESSURE FUEL SWITCH								Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-01PROC. REF: AMM 28-40-01										
<hr/>										
284041	LEFT FUEL FLOAT SWITCH								Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-02PROC. REF: AMM 28-40-02										
<hr/>										
284042	RIGHT FUEL FLOAT SWITCH								Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-02PROC. REF: AMM 28-40-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 28 - FUEL										
284045	FUEL QUANTITY SIGNAL CONDITIONER								Component	ATA:28
PN:6628408000-023	MOS/MSC	04-Jun-05	O/C							
SN:B0672	HRS	3648.97								
	AFL	2757								
PROC. REF: AMM 28-40-04PROC. REF: AMM 28-40-04										
<hr/>										
284047	LEFT LOW LEVEL FUEL SENSOR								Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-03PROC. REF: AMM 28-40-03										
<hr/>										
284048	RIGHT LOW LEVEL FUEL SENSOR								Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-03PROC. REF: AMM 28-40-03										
<hr/>										
D2820013	PERFORM INITIAL CLEANING AND LEAK CHECK OF LOW-PRESSURE FUEL FILTERS								Service	ATA:28
	MOS/MSC	30-Apr-06	A/R							
	HRS									
	AFL									
PROC. REF: AMM 28-20-15PROC. REF: AMM 28-20-15										
<hr/>										
F2840003 ^S	** FUEL QUANTITY SIGNAL CONDITIONER - PERFORM FUNCTIONAL TEST TO VERIFY WEIGHT ON WHEELS (WOW) INPUTS								Service	ATA:28
	MOS	09-Mar-01	48					AIRWORTHINESS		
	HRS	0	1200							
	AFL	0								
PROC. REF: AMM 28-40-00PROC. REF: AMM 28-40-00										
<hr/>										
H2840001	* DUAL FUEL FLOW CONVERTER (DFFC) - PERFORM ACCEPTANCE TEST AND LOW TEMPERATURE SCREENING								Service	ATA:28
	MOS/MSC	09-Mar-01	N/A							
	HRS	0								
	AFL	0								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 28 - FUEL										
Y2810001	^S	WING TANKS - REMOVE FUEL TANK ACCESS PANELS AND PERFORM VISUAL INSPECTION						Service	ATA:28	
	MOS	02-Aug-24	24							
	HRS	9525.7	600							
	AFL	7276								
PKG:10										
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										

Y2810002	^S	WING TANKS - REMOVE FUEL TANK ACCESS PANELS AND PERFORM VISUAL INSPECTION						Service	ATA:28	
	MOS	25-Nov-19	96							
	HRS	8177.7	2400							
	AFL	6303								
PKG:22										
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										

Y2820000	^S	LOW PRESSURE FUEL FILTER - REMOVE AND INSPECT FOR CONTAMINATION. CLEAN IF NECESSARY.						Service	ATA:28	
	MOS	02-Aug-24	24							
	HRS	9525.7	600							
	AFL	7276								
PKG:10										
PROC. REF: AMM 28-20-15PROC. REF: AMM 28-20-15										

ATA 29 - HYDRAULIC POWER										
291001		HYDRAULIC RESERVOIR						Component	ATA:29	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN	0					
SN:UNKNOWN	HRS	0		TSN	0					
	AFL	0		TSN	0					
PROC. REF: AMM 29-10-02PROC. REF: AMM 29-10-02										

291012		L8 HYDRAULIC SHUTOFF VALVE						Component	ATA:29	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN	0					
SN:UNKNOWN	HRS	0		TSN	0					
	AFL	0		TSN	0					
PROC. REF: AMM 29-10-05PROC. REF: AMM 29-10-05										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 29 - HYDRAULIC POWER									
291013 L9 HYDRAULIC SHUTOFF VALVE									Component ATA:29
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 29-10-05PROC. REF: AMM 29-10-05									
291033 RESERVOIR PRESSURIZATION CONTROL MODULE									Component ATA:29
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 29-10-06PROC. REF: AMM 29-10-06									
291034 RESERVOIR FLUID LEVEL SENSOR									Component ATA:29
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 29-30-02PROC. REF: AMM 29-30-02									
291045 NO. 1 ENGINE DRIVEN HYDRAULIC PUMP									Component ATA:29
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 29-10-01PROC. REF: AMM 29-10-01									
291046 NO. 2 ENGINE DRIVEN HYDRAULIC PUMP									Component ATA:29
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 29-10-01PROC. REF: AMM 29-10-01									
291051 NO. 1 MAIN HYDRAULIC SYSTEM PRESSURE SWITCH									Component ATA:29
PN:6629101004-001	MOS/MSC	11-Jun-16	O/C	TSN 0					
SN:1452	HRS	7630.1		TSN 0					
	AFL	5823		TSN 0					
PROC. REF: AMM 29-30-03PROC. REF: AMM 29-30-03									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 29 - HYDRAULIC POWER										
291052		NO. 2 MAIN HYDRAULIC SYSTEM PRESSURE SWITCH						Component	ATA:29	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 29-30-03PROC. REF: AMM 29-30-03										
291057		MAIN HYDRAULIC SYSTEM ACCUMULATOR						Component	ATA:29	
PN:88746-1	MOS/MSC	28-Jan-07	O/C							
SN:424	HRS	5192.28								
	AFL	3977								
PROC. REF: AMM 29-10-04PROC. REF: AMM 29-10-04										
291059		MAIN HYDRAULIC FILTER MANIFOLD						Component	ATA:29	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 29-10-03PROC. REF: AMM 29-10-03										
291069		THERMAL SHUTOFF VALVE						Component	ATA:29	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 29-10-07PROC. REF: AMM 29-10-07										
292001		AUXILIARY FILTER MANIFOLD ASSEMBLY						Component	ATA:29	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 29-20-02PROC. REF: AMM 29-20-02										
292011		AUXILIARY HYDRAULIC PUMP ASSEMBLY						Component	ATA:29	
PN:48-16-1	MOS/MSC	27-Feb-23	O/C	TSO 0						
SN:ELE0600A	HRS	9186.7		TSO 0						
	AFL	7047		TSO 0						
PROC. REF: AMM 29-20-01PROC. REF: AMM 29-20-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 29 - HYDRAULIC POWER										
292012		AUXILIARY HYDRAULIC PUMP						Component	ATA:29	
PN:6629201000-015	MOS/MSC	11-Jun-16	O/C							
SN:K0153	HRS	7630.1								
	AFL	5823								
PROC. REF: AMM 29-20-01PROC. REF: AMM 29-20-01										
292013		AUXILIARY HYDRAULIC PUMP ELECTRIC MOTOR						Component	ATA:29	
PN:6629201000-011	MOS/MSC	11-Jun-16	O/C	TSR 0						
SN:ELE0/094	HRS	7630.1		TSR 0						
	AFL	5823		TSR 0						
PROC. REF: AMM 29-20-04PROC. REF: AMM 29-20-04										
292025		AUXILIARY HYDRAULIC SYSTEM PRESSURE SWITCH						Component	ATA:29	
PN:6629101004-001	MOS/MSC	11-Jun-16	O/C	TSN 0						
SN:1226	HRS	7630.1		TSN 0						
	AFL	5823		TSN 0						
PROC. REF: AMM 29-30-03PROC. REF: AMM 29-30-03										
292401		AUXILIARY HYDRAULIC PRESSURE CHECK VALVE						Component	ATA:29	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
293001		GROUND SERVICE CONTROL BOX						Component	ATA:29	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 29-30-01PROC. REF: AMM 29-30-01										
293011		HYDRAULIC PRESSURE TRANSDUCER						Component	ATA:29	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 29-30-04PROC. REF: AMM 29-30-04										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 29 - HYDRAULIC POWER										
D2910017	MAIN HYDRAULIC FILTER MANIFOLD ELEMENTS - REPLACE								Service	ATA:29
	MOS/MSC	06-Jul-21	-							
	HRS	8631.2								
	AFL	6618								
PROC. REF: AMM 29-10-03PROC. REF: AMM 29-10-03										
D2910018	MAIN HYDRAULIC FILTER MANIFOLD ELEMENTS - REPLACE								Service	ATA:29
	MOS	28-Jul-25								
	HRS	9780.4	300		10080.4		57.3			
	AFL	7454								
PROC. REF: AMM 29-10-03PROC. REF: AMM 29-10-03										
H2920002 ^S	HYDRAULIC SYSTEM GROUND SERVICE LEDS - PERFORM FUNCTIONAL TEST								Service	ATA:29
	MOS	09-Mar-01	48							
	HRS	0	1200							
	AFL	0								
PROC. REF: AMM 29-30-00PROC. REF: AMM 29-30-00										
O2910005	AUXILIARY HYDRAULIC FILTER MANIFOLD ELEMENTS - REPLACE								Service	ATA:29
	MOS	19-May-22						LIFE LIMIT		
	HRS	8995.3	2400		11395.3		1372.2			
	AFL	6902								
PROC. REF: AMM 29-20-02PROC. REF: AMM 29-20-02										
T2910026 ^S	RELIEF FUNCTION OF THE PRESSURIZATION CONTROL MODULE - PERFORM FUNCTIONAL TEST								Service	ATA:29
	MOS	09-Mar-01	48							
	HRS	0	1200							
	AFL	0								
PROC. REF: AMM 29-10-06PROC. REF: AMM 29-10-06										

PKG:13

PKG:14

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 29 - HYDRAULIC POWER

Y2910001	^S	HYDRAULIC COMPONENTS AND ASSOCIATED PLUMBING (AFT OF FUSELAGE FUEL CELL, FS 495 TO FS 512) - PERFORM VISUAL INSPECTION						Service	ATA:29
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									

PKG:14

Y2910002	^S	HYDRAULIC COMPONENTS AND ASSOCIATED PLUMBING (WHEEL WELL AND FORWARD AREA OF REAR SPAR) - PERFORM VISUAL INSPECTION						Service	ATA:29
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									

PKG:17

Y2910003	^S	HYDRAULIC COMPONENTS AND ASSOCIATED PLUMBING (AFT AREA OF REAR SPAR) - PERFORM VISUAL INSPECTION						Service	ATA:29
	MOS	25-Nov-19	96						
	HRS	8177.7	2400						
	AFL	6303							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									

PKG:19

Y2920001	^S	AUXILIARY HYDRAULIC SYSTEM - PERFORM OPERATIONAL CHECK						Service	ATA:29
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 29-20-00PROC. REF: AMM 29-20-00									

PKG:13

ATA 30 - ICE AND RAIN PROTECTION

301006		ANTI-ICE VERTICAL STABILIZER RELAY PANEL (P40)						Component	ATA:30
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN	0				
SN:UNKNOWN	HRS	0		TSN	0				
	AFL	0		TSN	0				
PROC. REF: AMM 30-10-06PROC. REF: AMM 30-10-06									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 30 - ICE AND RAIN PROTECTION									
301010 LEFT HORIZONTAL STABILIZER CONTROL SENSOR (MT47)									Component ATA:30
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-10-05PROC. REF: AMM 30-10-05									
301011 RIGHT HORIZONTAL STABILIZER CONTROL SENSOR (MT46)									Component ATA:30
PN:662100000-059	MOS/MSC	03-Jun-06	O/C						
SN:UNKNOWN	HRS	4546.3							
	AFL	3481							
PROC. REF: AMM 30-10-05PROC. REF: AMM 30-10-05									
301051 LEFT ANTI-ICE 2.0 DIAMETER CHECK VALVE									Component ATA:30
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-10-02PROC. REF: AMM 30-10-02									
301052 RIGHT ANTI-ICE 2.0 DIAMETER CHECK VALVE									Component ATA:30
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-10-02PROC. REF: AMM 30-10-02									
301063 LEFT ANTI-ICE PRESSURE REGULATING SHUTOFF VALVE									Component ATA:30
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-10-01PROC. REF: AMM 30-10-01									
301064 RIGHT ANTI-ICE PRESSURE REGULATING SHUTOFF VALVE									Component ATA:30
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-10-01PROC. REF: AMM 30-10-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 30 - ICE AND RAIN PROTECTION										
301065		LEFT ANTI-ICE SHUTTLE VALVE						Component	ATA:30	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 49-70-06, AMM 30-10-08PROC. REF: AMM 49-70-06, AMM 30-10-08										
301066		RIGHT ANTI-ICE SHUTTLE VALVE						Component	ATA:30	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 30-10-08PROC. REF: AMM 30-10-08										
301240		ANTI-ICE MANIFOLD ASSEMBLY						Component	ATA:30	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 30-10-07PROC. REF: AMM 30-10-07										
302001		NO. 1 NACELLE INLET ANTI-ICE SHUTOFF VALVE						Component	ATA:30	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 30-20-01PROC. REF: AMM 30-20-01										
302002		NO. 2 NACELLE INLET ANTI-ICE SHUTOFF VALVE						Component	ATA:30	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 30-20-01PROC. REF: AMM 30-20-01										
302013		NO. 1 NACELLE ANTI-ICE PRESSURE SWITCH						Component	ATA:30	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 30-20-02PROC. REF: AMM 30-20-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 30 - ICE AND RAIN PROTECTION										
302014		NO. 2 NACELLE ANTI-ICE PRESSURE SWITCH						Component	ATA:30	
PN:7600020-1	MOS/MSC	27-Mar-23	O/C							
SN:5769TW	HRS	9209.1								
	AFL	7060								
PROC. REF: AMM 30-20-02PROC. REF: AMM 30-20-02										
<hr/>										
303501		LEFT NOSE RELAY BOX						Component	ATA:30	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 30-30-01PROC. REF: AMM 30-30-01										
<hr/>										
303510		RIGHT NOSE RELAY BOX						Component	ATA:30	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 30-30-01PROC. REF: AMM 30-30-01										
<hr/>										
304021		WINDSHIELD ANTI-ICE CONTROLLER						Component	ATA:30	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 30-40-01PROC. REF: AMM 30-40-01										
<hr/>										
304060		NO. 1 WING SURFACE TEMPERATURE SENSOR						Component	ATA:30	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 30-10-03PROC. REF: AMM 30-10-03										
<hr/>										
304061		NO. 2 WING SURFACE TEMPERATURE SENSOR						Component	ATA:30	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 30-10-03PROC. REF: AMM 30-10-03										

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 30 - ICE AND RAIN PROTECTION									
304062 NO. 3 WING SURFACE TEMPERATURE SENSOR									Component ATA:30
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-10-03PROC. REF: AMM 30-10-03									
304063 NO. 4 WING SURFACE TEMPERATURE SENSOR									Component ATA:30
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-10-03PROC. REF: AMM 30-10-03									
308005 ICE DETECTION PROBE									Component ATA:30
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-80-01PROC. REF: AMM 30-80-01									
A3020000 ^S ** NACELLE ANTI-ICE SYSTEM - PERFORM FUNCTIONAL TEST									Service ATA:30
	MOS	09-Mar-01	48					AIRWORTHINESS	
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 30-20-00PROC. REF: AMM 30-20-00									
A3030000 ^S ** PITOT-STATIC HEAT SYSTEM - PERFORM OPERATIONAL CHECK									Service ATA:30
	MOS	25-Nov-19	96					AIRWORTHINESS	
	HRS	8177.7	2400						
	AFL	6303							
PROC. REF: AMM 30-30-00PROC. REF: AMM 30-30-00									
AC3010006 ** ANTI-ICE MANIFOLD - PERFORM BORESCOPE INSPECTION									Service ATA:30
	MOS	21-Aug-25						AIRWORTHINESS	
	HRS	9809.8	600		10409.8		386.7		
	AFL	7471							
PROC. REF: AMM 30-10-07PROC. REF: AMM 30-10-07									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 30 - ICE AND RAIN PROTECTION										
H3010000 ^S	** WING/STAB ANTI-ICE SWITCH - PERFORM OPERATIONAL CHECK								Service	ATA:30
	MOS	02-Aug-24	24					AIRWORTHINESS		
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 30-10-00PROC. REF: AMM 30-10-00										
PKG:7										
T3040000 ^S	** WINDSHIELD ANTI-ICE - PERFORM FUNCTIONAL TEST OF THE WINDSHIELD ANTI-ICE SYSTEM								Service	ATA:30
	MOS	02-Aug-24	24					AIRWORTHINESS		
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 30-40-00PROC. REF: AMM 30-40-00										
PKG:7										
Y3010007 ^S	WING ANTI-ICE PICCOLO TUBE - PERFORM DETAILED VISUAL INSPECTION FOR CRACKS AT W.S. 43 AND W.S. 176.								Service	ATA:30
	MOS	02-Aug-24	24							
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
PKG:10										
Y3080000 ^S	ICE DETECTION SYSTEM - PERFORM FUNCTIONAL TEST								Service	ATA:30
	MOS	09-Mar-01	48							
	HRS	0	1200							
	AFL	0								
PROC. REF: AMM 30-80-00PROC. REF: AMM 30-80-00										
PKG:13										
Z3020005	* NO. 1 ENGINE INLET ANTI-ICE TUBE ASSEMBLY FROM THE AFT INLET BULKHEAD CONNECTION POINT FORWARD TO SPRAY RING CONNECTION, PERFORM DETAILED VISUAL/BORESCOPE INSPECTION OF THE WELDS INSIDE AND OUTSIDE OF THE TUBE AT BOTH FORWARD AND AFT ENDS.								Service	ATA:30
	MOS	28-Jul-25						AIRWORTHINESS		
	HRS	9780.4	250		10030.4		7.3			
	AFL	7454								
PROC. REF: AMM 30-20-00PROC. REF: AMM 30-20-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 30 - ICE AND RAIN PROTECTION

Z3020005	* NO. 2 ENGINE INLET ANTI-ICE TUBE ASSEMBLY FROM THE AFT INLET BULKHEAD CONNECTION POINT FORWARD TO SPRAY RING CONNECTION, PERFORM DETAILED VISUAL/BOREScope INSPECTION OF THE WELDS INSIDE AND OUTSIDE OF THE TUBE AT BOTH FORWARD AND AFT ENDS.							Service	ATA:30
	MOS	28-Jul-25						AIRWORTHINESS	
	HRS	9780.4	250		10030.4		7.3		
	AFL	7454							
PROC. REF: AMM 30-20-00PROC. REF: AMM 30-20-00									

Z3020006	NO. 1 ENGINE INLET ANTI-ICE TUBE ASSEMBLY FROM THE AFT INLET BULKHEAD CONNECTION POINT FORWARD TO SPRAY RING CONNECTION, PERFORM DETAILED VISUAL/BOREScope INSPECTION OF THE WELDS INSIDE AND OUTSIDE OF THE TUBE AT BOTH FORWARD AND AFT ENDS							Service	ATA:30
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
PROC. REF: AMM 30-20-00PROC. REF: AMM 30-20-00									

Z3020006	NO. 2 ENGINE INLET ANTI-ICE TUBE ASSEMBLY FROM THE AFT INLET BULKHEAD CONNECTION POINT FORWARD TO SPRAY RING CONNECTION, PERFORM DETAILED VISUAL/BOREScope INSPECTION OF THE WELDS INSIDE AND OUTSIDE OF THE TUBE AT BOTH FORWARD AND AFT ENDS							Service	ATA:30
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
PROC. REF: AMM 30-20-00PROC. REF: AMM 30-20-00									

ATA 31 - INDICATING/RECORDING SYSTEMS

311001	PILOT CIRCUIT BREAKER PANEL							Component	ATA:31
PN:PN	MOS/MSC	09-Mar-01	O/C		TSN 0				
SN:UNKNOWN	HRS	0			TSN 0				
	AFL	0			TSN 0				
PROC. REF: AMM 24-60-01PROC. REF: AMM 24-60-01									

311005	COPILOT CIRCUIT BREAKER PANEL							Component	ATA:31
PN:PN	MOS/MSC	09-Mar-01	O/C		TSN 0				
SN:UNKNOWN	HRS	0			TSN 0				
	AFL	0			TSN 0				
PROC. REF: AMM 24-60-01PROC. REF: AMM 24-60-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 31 - INDICATING/RECORDING SYSTEMS										
311601		GEAR UP/DOWN SWITCH						Component	ATA:31	
PN:A3-1295	MOS/MSC	12-Aug-15	O/C							
SN:UNKNOWN	HRS	7535.1								
	AFL	5764								
PROC. REF: AMM 32-30-02PROC. REF: AMM 32-30-02										
311805		ENGINE FUEL CONTROL PANEL						Component	ATA:31	
PN:4576108500-023	MOS/MSC	20-Jan-05	O/C							
SN:MRP645048-01	HRS	3272.32								
	AFL	2494								
PROC. REF: AMM 31-11-05PROC. REF: AMM 31-11-05										
311806		ENGINE/FUEL CONTROL PANEL OVERLAY						Component	ATA:31	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
311906		FORWARD QUADRANT SWITCH PANEL OVERLAY						Component	ATA:31	
PN:7631208500-015	MOS/MSC	12-Aug-15	O/C	TSN 173						
SN:UNKNOWN	HRS	7535.1		TSN 7535.1						
	AFL	5764		TSN 5764						
PROC. REF: AMM 31-11-04PROC. REF: AMM 31-11-04										
311907		RUDDER BOOST SWITCH (DS48)						Component	ATA:31	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
312001		PILOTS DIGITAL CLOCK						Component	ATA:31	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-21-01PROC. REF: AMM 31-21-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 31 - INDICATING/RECORDING SYSTEMS									
312002 COPILOTS DIGITAL CLOCK									Component ATA:31
PN:M850-5V-LA	MOS/MSC	14-Dec-10	O/C	TSN 0					
SN:A5231	HRS	6457.2		TSN 0					
	AFL	4944		TSN 0					
PROC. REF: AMM 31-21-01PROC. REF: AMM 31-21-01									
312011 PILOTS DAVTRON M850 DIGITAL CLOCK BATTERY									Component ATA:31
PN:E90	MOS	03-Feb-25	12	TSN 0	03-Feb-26		OVD	LIFE LIMIT	
SN:NA	HRS	9605.4		TSN 0					
	AFL	7333		TSN 0					
PROC. REF: AMM 31-21-02PROC. REF: AMM 31-21-02									
312012 COPILOTS DAVTRON M850 DIGITAL CLOCK BATTERY									Component ATA:31
PN:E90	MOS	03-Feb-25	12	TSN 0	03-Feb-26		OVD	LIFE LIMIT	
SN:NA	HRS	9605.4		TSN 0					
	AFL	7333		TSN 0					
PROC. REF: AMM 31-21-02PROC. REF: AMM 31-21-02									
313001 FLIGHT DATA RECORDER									Component ATA:31
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
313001A DOWNLOAD									Service ATA:31
PN:PN	MOS/MSC	09-Mar-01	N/R					CUSTOMER CODE	
SN:UNKNOWN	HRS	0							
	AFL	0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
313003 FLIGHT DATA RECORDER (FDR) ACCELEROMETER									Component ATA:31
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 31 - INDICATING/RECORDING SYSTEMS										
313010		HOBBS METER						Component		ATA:31
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
313018		FLIGHT DATA RECORDER INERTIA SWITCH						Component		ATA:31
PN:PN	MOS/MSC	09-Mar-01	A/R	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
314001		SELCAL DECODER						Component		ATA:31
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
314011		NO. 1 DATA ACQUISITION (DAU) UNIT						Component		ATA:31
PN:7013348-931	MOS/MSC	12-Aug-15	O/C							
SN:00013220	HRS	7535.1								
	AFL	5764								
PROC. REF: AMM 31-42-01PROC. REF: AMM 31-42-01										
314012		NO. 2 DATA ACQUISITION (DAU) UNIT						Component		ATA:31
PN:7013348-931	MOS/MSC	15-Nov-05	O/C							
SN:00063567	HRS	4035.07								
	AFL	3047								
PROC. REF: AMM 31-42-01PROC. REF: AMM 31-42-01										
314023		NO. 1 INTEGRATED AVIONICS COMPUTER (IC-600)						Component		ATA:31
PN:7017000-82222	MOS/MSC	17-Dec-15	O/C							
SN:02065544	HRS	7546								
	AFL	5771								
PROC. REF: AMM 31-41-01PROC. REF: AMM 31-41-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 31 - INDICATING/RECORDING SYSTEMS										
314024		NO. 2 INTEGRATED AVIONICS COMPUTER (IC-600)						Component	ATA:31	
PN:7017000-82222	MOS/MSC	23-Nov-21	O/C							
SN:98041571	HRS	8770.6								
	AFL	6752								
PROC. REF: AMM 31-41-01PROC. REF: AMM 31-41-01										
314051		NO. 1 CENTRAL COMPUTING MEMORY MODULE IM-600						Component	ATA:31	
PN:7025973-04214	MOS/MSC	17-Feb-05	O/C							
SN:01080971	HRS	3300.2								
	AFL	2515								
PROC. REF: AMM 31-41-02PROC. REF: AMM 31-41-02										
314052		NO. 2 CENTRAL COMPUTING MEMORY MODULE IM-600						Component	ATA:31	
PN:7025973-04214	MOS/MSC	17-Feb-05	O/C							
SN:01080922	HRS	3300.2								
	AFL	2515								
PROC. REF: AMM 31-41-02PROC. REF: AMM 31-41-02										
315001		CREW WARNING PANEL						Component	ATA:31	
PN:6631508501-001	MOS/MSC	17-Feb-05	O/C	TSN 0						
SN:357	HRS	3300.2		TSN 0						
	AFL	2515		TSN 0						
PROC. REF: AMM 31-51-01PROC. REF: AMM 31-51-01										
316001		NO. 1 DU870 COMPUTER						Component	ATA:31	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-60-01PROC. REF: AMM 31-60-01										
316002		NO. 2 DU870 COMPUTER						Component	ATA:31	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-60-01PROC. REF: AMM 31-60-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 31 - INDICATING/RECORDING SYSTEMS										
316003		NO. 3 DU870 COMPUTER						Component	ATA:31	
PN:7014300-901	MOS/MSC	05-Jan-26	O/C							
SN:050E648	HRS	9987.5								
	AFL	7596								
PROC. REF: AMM 31-60-01PROC. REF: AMM 31-60-01										
316004		NO. 4 DU870 COMPUTER						Component	ATA:31	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-60-01PROC. REF: AMM 31-60-01										
316005		PILOT EFIS DISPLAY CONTROLLER						Component	ATA:31	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-60-02PROC. REF: AMM 31-60-02										
316006		COPILOT EFIS DISPLAY CONTROLLER						Component	ATA:31	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-60-02PROC. REF: AMM 31-60-02										
316007		PILOT NO. 1 MULTIFUNCTION DISPLAY CONTROLLER BEZEL						Component	ATA:31	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-60-01PROC. REF: AMM 31-60-01										
316008		PILOT NO. 2 MULTIFUNCTION DISPLAY CONTROLLER BEZEL						Component	ATA:31	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-60-01PROC. REF: AMM 31-60-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 31 - INDICATING/RECORDING SYSTEMS

316009 COPILOT NO. 1 MULTIFUNCTION DISPLAY CONTROLLER BEZEL								Component	ATA:31
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 31-60-01PROC. REF: AMM 31-60-01									

316010 COPILOT NO. 2 MULTIFUNCTION DISPLAY CONTROLLER BEZEL								Component	ATA:31
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 31-60-01PROC. REF: AMM 31-60-01									

316091 AFIS DATA TRANSFER UNIT								Component	ATA:31
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

B310000 ^S ** INDICATING/RECORDING SYSTEM - PERFORM OPERATIONAL CHECK								Service	ATA:31
	MOS	02-Aug-24	24					AIRWORTHINESS	
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 31-00-00PROC. REF: AMM 31-00-00									

PKG:7

ATA 32 - LANDING GEAR

320041 LEFT MAIN LANDING GEAR UPPER LINK PIN								Component	ATA:32
PN:PN	MOS	09-Mar-01		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0	10000	TSN 0	10000		2384		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									

320042 RIGHT MAIN LANDING GEAR UPPER LINK PIN								Component	ATA:32
PN:PN	MOS	09-Mar-01		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0	10000	TSN 0	10000		2384		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 32 - LANDING GEAR										
320043		LEFT MAIN LANDING GEAR LOWER LINK PIN						Component	ATA:32	
PN:PN	MOS	09-Mar-01		TSN 0				AIRWORTHINESS		
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0	10000	TSN 0	10000		2384			
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01										
320044		RIGHT MAIN LANDING GEAR LOWER LINK PIN						Component	ATA:32	
PN:PN	MOS	09-Mar-01		TSN 0				AIRWORTHINESS		
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0	10000	TSN 0	10000		2384			
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01										
320051		LEFT MAIN LANDING GEAR PISTON PIN						Component	ATA:32	
PN:PN	MOS	09-Mar-01		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0	10000	TSN 0	10000		2384			
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01										
320052		RIGHT MAIN LANDING GEAR PISTON PIN						Component	ATA:32	
PN:PN	MOS	09-Mar-01		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0	10000	TSN 0	10000		2384			
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01										
320061		LEFT MAIN LANDING GEAR ACTUATOR PISTON						Component	ATA:32	
PN:PN	MOS/MSC	09-Mar-01	H/T	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01										
320062		RIGHT MAIN LANDING GEAR ACTUATOR PISTON						Component	ATA:32	
PN:4532101000V72-002	MOS/MSC	09-Mar-01	H/T	TSN 0						
SN:H1153	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 32 - LANDING GEAR										
320071		LEFT MAIN LANDING GEAR ACTUATOR CYLINDER						Component	ATA:32	
PN:4532101000V76-001	MOS/MSC	09-Mar-01	H/T	TSN 0						
SN:H0155	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01										
320072		RIGHT MAIN LANDING GEAR ACTUATOR CYLINDER						Component	ATA:32	
PN:4532101000V72-002	MOS/MSC	09-Mar-01	H/T	TSN 0						
SN:H1153	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01										
320081		LEFT MAIN LANDING GEAR ACTUATOR END CAP						Component	ATA:32	
PN:200-0303-001	MOS/MSC	02-Aug-24	H/T	TSN 0						
SN:UNKNOWN	HRS	9525.7		TSN 0						
	AFL	7276		TSN 0						
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01										
320082		RIGHT MAIN LANDING GEAR ACTUATOR END CAP						Component	ATA:32	
PN:200-0303-001	MOS/MSC	02-Aug-24	H/T	TSN 0						
SN:UNKNOWN	HRS	9525.7		TSN 0						
	AFL	7276		TSN 0						
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01										
320091		LEFT MAIN LANDING GEAR ACTUATOR HOUSING						Component	ATA:32	
PN:200-0304-001	MOS/MSC	19-Dec-10	H/T	TSN 0						
SN:H1704	HRS	6457.2		TSN 0						
	AFL	4944		TSN 0						
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01										
320092		RIGHT MAIN LANDING GEAR ACTUATOR HOUSING						Component	ATA:32	
PN:4532101000V72-002	MOS/MSC	09-Mar-01	H/T	TSN 0						
SN:H1153	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 32 - LANDING GEAR										
321001		LEFT MAIN LANDING GEAR STRUT						Component	ATA:32	
PN:200-0200-013	MOS		30-Mar-21					LIFE LIMIT		
SN:H0584	HRS		8414.4		TSN 2110.4, TSO 0					
	AFL		6463	10000	TSN 1409, TSO 0	15054	7438			
Special Properties: RII ITEM PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01										
321002		RIGHT MAIN LANDING GEAR STRUT						Component	ATA:32	
PN:200-0200-014	MOS		30-Mar-21					LIFE LIMIT		
SN:H1593	HRS		8414.4		TSN 2110.4					
	AFL		6463	10000	TSN 1409	15054	7438			
Special Properties: RII ITEM PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01										
321011		LEFT MAIN LANDING GEAR SHOCK STRUT CYLINDER						Component	ATA:32	
PN:200-0201-009	MOS/MSC		30-Mar-21	H/T						
SN:H0727	HRS		8414.4		TSN 2110.4					
	AFL		6463		TSN 1409					
PROC. REF: NDT PART 4/32-10-01, NDT PART 4/32-10-00, AMM 32-10-01PROC. REF: NDT PART 4/32-10-01, NDT PART 4/32-10-00, AMM 32-10-01										
321012		RIGHT MAIN LANDING GEAR SHOCK STRUT CYLINDER						Component	ATA:32	
PN:200-0201-010	MOS/MSC		30-Mar-21	H/T						
SN:H0755	HRS		8414.4		TSN 2110.4					
	AFL		6463		TSN 1409					
PROC. REF: NDT PART 4/32-10-01, NDT PART 4/32-10-00PROC. REF: NDT PART 4/32-10-01, NDT PART 4/32-10-00										
321025		LEFT MAIN LANDING GEAR ACTUATOR UPPER PIN						Component	ATA:32	
PN:200-0325-101	MOS/MSC		24-Jun-19	H/T	TSN 0					
SN:H2409	HRS		8101.1		TSN 0					
	AFL		6233		TSN 0					
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01										
321026		RIGHT MAIN LANDING GEAR ACTUATOR UPPER PIN						Component	ATA:32	
PN:200-0325-101	MOS/MSC		24-Jun-19	H/T	TSN 0					
SN:HER08U/5030	HRS		8101.1		TSN 0					
	AFL		6233		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
321037 LEFT MAIN LANDING GEAR ACTUATOR LOWER PIN									Component ATA:32
PN:200-0217-101	MOS/MSC	24-Jun-19	H/T	TSN 0					
SN:H5000	HRS	8101.1		TSN 0					
	AFL	6233		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
321038 RIGHT MAIN LANDING GEAR ACTUATOR LOWER PIN									Component ATA:32
PN:200-0217-101	MOS/MSC	24-Jun-19	H/T	TSN 0					
SN:HER08U5014	HRS	8101.1		TSN 0					
	AFL	6233		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
321049 LEFT MAIN LANDING GEAR AXLE BEAM									Component ATA:32
PN:200-0203-001	MOS/MSC	08-Sep-12	H/T						
SN:H0331	HRS	6989.1							
	AFL	5335		TSN 5311					
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
321050 RIGHT MAIN LANDING GEAR AXLE BEAM									Component ATA:32
PN:200-0203-001	MOS/MSC	08-Sep-12	H/T						
SN:H0334	HRS	6989.1							
	AFL	5335		TSN 5311					
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
321061 LEFT MAIN LANDING GEAR SIDE-STAY ACTUATOR PIN									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
321062 RIGHT MAIN LANDING GEAR SIDE-STAY ACTUATOR PIN									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
321073 LEFT MAIN LANDING GEAR SIDE BRACE ACTUATOR DISPLACEMENT TUBE									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
321074 RIGHT MAIN LANDING GEAR SIDE BRACE ACTUATOR DISPLACEMENT TUBE									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
321085 LEFT FORWARD TRUNNION ASSEMBLY									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
321086 RIGHT FORWARD TRUNNION ASSEMBLY									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
321087 LEFT AFT TRUNNION ASSEMBLY									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
321088 RIGHT AFT TRUNNION ASSEMBLY									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
321101 LEFT FORWARD MAIN LANDING GEAR TRUNNION PIN									Component ATA:32
PN:200-0212-103	MOS	24-Jul-12						LIFE LIMIT	
SN:H0501	HRS	6961.3		TSN 2110.4					
	AFL	5311	10000	TSN 1409	13902		6286		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
321102 RIGHT FORWARD MAIN LANDING GEAR TRUNNION PIN									Component ATA:32
PN:200-0212-103	MOS	24-Jul-12						LIFE LIMIT	
SN:H0473	HRS	6961.3		TSN 2110.4					
	AFL	5311	10000	TSN 1409	13902		6286		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
321103 LEFT AFT MAIN LANDING GEAR TRUNNION PIN									Component ATA:32
PN:200-0213-103	MOS	24-Jul-12						LIFE LIMIT	
SN:H0364	HRS	6961.3		TSN 2110.4					
	AFL	5311	10000	TSN 1409	13902		6286		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
321104 RIGHT AFT MAIN LANDING GEAR TRUNNION PIN									Component ATA:32
PN:200-0213-103	MOS	24-Jul-12						LIFE LIMIT	
SN:H0338	HRS	6961.3		TSN 2110.4					
	AFL	5311	10000	TSN 1409	13902		6286		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
321111 LEFT FORWARD LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN									Component ATA:32
PN:4532103201-001	MOS/MSC	15-Dec-10	H/T	TSN 0					
SN:CM1882	HRS	6457.2		TSN 0					
	AFL	4944		TSN 0					
PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05									
321112 RIGHT FORWARD LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN									Component ATA:32
PN:4532103201-001	MOS/MSC	15-Dec-10	H/T	TSN 0					
SN:CM1113	HRS	6457.2		TSN 0					
	AFL	4944		TSN 0					
PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
321113 LEFT FORWARD UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN									Component ATA:32
PN:4532103201-001	MOS/MSC	15-Dec-10	H/T	TSN 0					
SN:CMI806	HRS	6457.2		TSN 0					
	AFL	4944		TSN 0					
PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05									
321114 RIGHT FORWARD UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN									Component ATA:32
PN:4532103201-001	MOS/MSC	15-Dec-10	H/T	TSN 0					
SN:CMI710	HRS	6457.2		TSN 0					
	AFL	4944		TSN 0					
PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05									
321117 LEFT AFT UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN									Component ATA:32
PN:4532103202-001	MOS/MSC	18-Dec-10	H/T	TSN 0					
SN:CMI371	HRS	6457.2		TSN 0					
	AFL	4944		TSN 0					
PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05									
321118 RIGHT AFT UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN									Component ATA:32
PN:4532103202-001	MOS/MSC	18-Dec-10	H/T	TSN 0					
SN:CMI363	HRS	6457.2		TSN 0					
	AFL	4944		TSN 0					
PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05									
321119 LEFT AFT LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN									Component ATA:32
PN:4532103203-001	MOS/MSC	18-Dec-10	H/T	TSN 0					
SN:CMI818	HRS	6457.2		TSN 0					
	AFL	4944		TSN 0					
PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05									
321120 RIGHT AFT LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN									Component ATA:32
PN:4532103203-001	MOS/MSC	18-Dec-10	H/T	TSN 0					
SN:CMI759	HRS	6457.2		TSN 0					
	AFL	4944		TSN 0					
PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
321201 LEFT MAIN LANDING GEAR OLEO ASSEMBLY									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
321202 RIGHT MAIN LANDING GEAR OLEO ASSEMBLY									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
321215 LEFT MAIN LANDING GEAR SHOCK STRUT PISTON									Component ATA:32
PN:PN	MOS	09-Mar-01		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0	10000	TSN 0	10000		2384		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
321216 RIGHT MAIN LANDING GEAR SHOCK STRUT PISTON									Component ATA:32
PN:PN	MOS	09-Mar-01		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0	10000	TSN 0	10000		2384		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
321227 LEFT MAIN LANDING GEAR SHOCK STRUT LINK									Component ATA:32
PN:PN	MOS	09-Mar-01		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0	10000	TSN 0	10000		2384		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
321228 RIGHT MAIN LANDING GEAR SHOCK STRUT LINK									Component ATA:32
PN:PN	MOS	09-Mar-01		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0	10000	TSN 0	10000		2384		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
321301 LEFT MAIN LANDING GEAR OUTBOARD DOOR									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 52-80-01PROC. REF: AMM 52-80-01									
321302 LEFT MAIN LANDING GEAR INBOARD DOOR									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 52-80-01PROC. REF: AMM 52-80-01									
321303 RIGHT MAIN LANDING GEAR INBOARD DOOR									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 52-80-01PROC. REF: AMM 52-80-01									
321304 RIGHT MAIN LANDING GEAR OUTBOARD DOOR									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 52-80-01PROC. REF: AMM 52-80-01									
322001^S NOSE LANDING GEAR STRUT ASSEMBLY									Component ATA:32
PN:4532230001-814	MOS	12-Feb-08		TSR 0				LIFE LIMIT	
SN:008	HRS	5965.9		TSR 0					
	AFL	4561	20000	TSN 4561, TSR 0					
PROC. REF: AMM 32-20-01PROC. REF: AMM 32-20-01									
322002 NOSE LANDING GEAR CYLINDER									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-32-01PROC. REF: AMM 32-32-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
322003 NOSE LANDING GEAR PISTON									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-32-01PROC. REF: AMM 32-32-01									
322004 NOSE LANDING GEAR ACTUATOR BRACKET									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-32-01PROC. REF: AMM 32-32-01									
322005 NOSE LANDING GEAR FORK									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-32-01PROC. REF: AMM 32-32-01									
322011 ^S NOSE LANDING GEAR ACTUATOR ASSEMBLY									Component ATA:32
PN:6632201000-001	MOS	09-Mar-01		TSN 0				LIFE LIMIT	
SN:EFS210	HRS	0		TSN 0					
	AFL	0	20000	TSN 0					
PROC. REF: AMM 32-32-01PROC. REF: AMM 32-32-01									
322061 ^S NOSE LANDING GEAR TRUNNION AXLE									Component ATA:32
PN:2342110-003	MOS	09-Mar-01		TSN 0				LIFE LIMIT	
SN:R153	HRS	0		TSN 0					
	AFL	0	20000	TSN 0					
PROC. REF: AMM 32-20-01PROC. REF: AMM 32-20-01									
322071 ^S LEFT NOSE LANDING GEAR TRUNNION PIN									Component ATA:32
PN:2342108-003	MOS	09-Mar-01		TSN 0				LIFE LIMIT	
SN:L016	HRS	0		TSN 0					
	AFL	0	20000	TSN 0					
PROC. REF: AMM 32-20-01PROC. REF: AMM 32-20-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
322072^S RIGHT NOSE LANDING GEAR TRUNNION PIN Component ATA:32									
PN:2342108-003	MOS	09-Mar-01		TSN 0				LIFE LIMIT	
SN:L012	HRS	0		TSN 0					
	AFL	0	20000	TSN 0					
PROC. REF: AMM 32-20-01PROC. REF: AMM 32-20-01									
322095 LEFT NOSE LANDING GEAR DOOR Component ATA:32									
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 52-81-01PROC. REF: AMM 52-81-01									
322096 RIGHT NOSE LANDING GEAR DOOR Component ATA:32									
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 52-81-01PROC. REF: AMM 52-81-01									
322111 NOSE LANDING GEAR CHASSIS ASSEMBLY Component ATA:32									
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
322121 NOSE LANDING GEAR UPLOCK MECHANISM Component ATA:32									
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-32-02PROC. REF: AMM 32-32-02									
323001 LEFT MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY Component ATA:32									
PN:200-0300-003	MOS/MSC	02-Aug-24	H/T						
SN:H0134	HRS	9525.7							
	AFL	7276		TSN 7276					
Special Properties: RII ITEM									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
323002 RIGHT MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY									Component ATA:32
PN:200-0300-004	MOS/MSC	02-Aug-24	H/T						
SN:H1188	HRS	9525.7							
	AFL	7276		TSN 7276					
Special Properties: RII ITEM									
<hr/>									
323037 LEFT MAIN LANDING GEAR INBOARD DOOR UPLOCK MECHANISM									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-31-04PROC. REF: AMM 32-31-04									
<hr/>									
323038 RIGHT MAIN LANDING GEAR INBOARD DOOR UPLOCK MECHANISM									Component ATA:32
PN:6632303004-006	MOS/MSC	08-Sep-12	O/C	TSR 31					
SN:0117	HRS	6989.1		TSR 0					
	AFL	5335		TSR 0					
PROC. REF: AMM 32-31-04PROC. REF: AMM 32-31-04									
<hr/>									
323110 NOSE LANDING GEAR DOWN-LOCK SWITCH									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-60-05PROC. REF: AMM 32-60-05									
<hr/>									
323220 LEFT DOWN AND LOCKED SWITCH									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-60-02PROC. REF: AMM 32-60-02									
<hr/>									
323221 RIGHT DOWN AND LOCKED SWITCH									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-60-02PROC. REF: AMM 32-60-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
323301 LEFT MAIN LANDING GEAR INBOARD DOOR ACTUATOR CAP SCREWS									Component ATA:32
PN:6632303003-003	MOS/MSC	13-Apr-07	O/C						
SN:0779	HRS	5383.5							
	AFL	4119							
PROC. REF: AMM 32-31-02PROC. REF: AMM 32-31-02									
323302 RIGHT MAIN LANDING GEAR INBOARD DOOR ACTUATOR CAP SCREWS									Component ATA:32
PN:7469-1	MOS/MSC	25-Jul-12	O/C		TSN 136, TSR 0				
SN:0004	HRS	6961.3			TSN 6961.3, TSR 0				
	AFL	5311			TSN 5311, TSR 0				
PROC. REF: AMM 32-31-02PROC. REF: AMM 32-31-02									
323305 LEFT MAIN LANDING GEAR ACTUATOR GIMBAL ASSEMBLY									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C		TSN 0				
SN:UNKNOWN	HRS	0			TSN 0				
	AFL	0			TSN 0				
PROC. REF: AMM 32-31-06PROC. REF: AMM 32-31-06									
323306 RIGHT MAIN LANDING GEAR ACTUATOR GIMBAL ASSEMBLY									Component ATA:32
PN:PN-UNKNOWN	MOS/MSC	25-Jul-10	O/C						
SN:UNKNOWN	HRS	6330.6							
	AFL	4850							
PROC. REF: AMM 32-31-06PROC. REF: AMM 32-31-06									
323307 LEFT MAIN LANDING GEAR SHAFT GIMBAL ASSEMBLY									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C		TSN 0				
SN:UNKNOWN	HRS	0			TSN 0				
	AFL	0			TSN 0				
PROC. REF: AMM 32-31-06PROC. REF: AMM 32-31-06									
323308 RIGHT MAIN LANDING GEAR SHAFT GIMBAL ASSEMBLY									Component ATA:32
PN:PN-UNKNOWN	MOS/MSC	25-Jul-10	O/C						
SN:UNKNOWN	HRS	6330.6							
	AFL	4850							
PROC. REF: AMM 32-31-06PROC. REF: AMM 32-31-06									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
323309 LEFT MAIN LANDING GEAR INBOARD DOOR GIMBAL BRACKET ASSEMBLY									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-31-06PROC. REF: AMM 32-31-06									
323310 RIGHT MAIN LANDING GEAR INBOARD DOOR GIMBAL BRACKET ASSEMBLY									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-31-06PROC. REF: AMM 32-31-06									
323735 CONTROL VALVE									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-30-01PROC. REF: AMM 32-30-01									
324001 NO. 1 MAIN LANDING GEAR WHEEL									Component ATA:32
PN:3-1545-1	MOS/MSC	27-Oct-25	O/C						
SN:2432	HRS	9906.2							
	AFL	7538							
PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02									
324001A NON DESTRUCTIVE TEST NO. 1 MAIN LANDING GEAR WHEEL									Service ATA:32
PN:3-1545-1	MOS/MSC	27-Oct-25	A/R						
SN:2432	HRS	9906.2							
	AFL	7538							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
324002 NO. 2 MAIN LANDING GEAR WHEEL									Component ATA:32
PN:3-1545-1	MOS/MSC	27-Oct-25	O/C						
SN:2483	HRS	9906.2							
	AFL	7538							
PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
324002A NON DESTRUCTIVE TEST NO. 2 MAIN LANDING GEAR WHEEL									Service ATA:32
PN:3-1545-1	MOS/MSC		27-Oct-25	A/R					
SN:2483	HRS		9906.2						
	AFL		7538						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
324003 NO. 3 MAIN LANDING GEAR WHEEL									Component ATA:32
PN:3-1545-1	MOS/MSC		27-Oct-25	O/C					
SN:3275	HRS		9906.2						
	AFL		7538						
PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02									
324003A NON DESTRUCTIVE TEST NO. 3 MAIN LANDING GEAR WHEEL									Service ATA:32
PN:3-1545-1	MOS/MSC		27-Oct-25	A/R					
SN:3275	HRS		9906.2						
	AFL		7538						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
324004 NO. 4 MAIN LANDING GEAR WHEEL									Component ATA:32
PN:3-1545-1	MOS/MSC		27-Oct-25	O/C					
SN:0831	HRS		9906.2						
	AFL		7538						
PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02									
324004A NON DESTRUCTIVE TEST NO. 4 MAIN LANDING GEAR WHEEL									Service ATA:32
PN:3-1545-1	MOS/MSC		27-Oct-25	A/R					
SN:0831	HRS		9906.2						
	AFL		7538						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
324005 NOSE GEAR WHEEL ASSEMBLY									Component ATA:32
PN:9544207-4	MOS/MSC		13-Oct-25	O/C					
SN:OCT07-2939	HRS		9885.1						
	AFL		7524						
PROC. REF: AMM 32-40-01PROC. REF: AMM 32-40-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 32 - LANDING GEAR										
324021	NO. 1 MAIN LANDING GEAR TIRE								Component	ATA:32
PN:226K08-4	MOS/MSC	27-Oct-25	O/C	TSN 0						
SN:50750049	HRS	9906.2		TSN 0						
	AFL	7538		TSN 0						
PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02										
324022	NO. 2 MAIN LANDING GEAR TIRE								Component	ATA:32
PN:226K08-4	MOS/MSC	27-Oct-25	O/C	TSN 0						
SN:50780770	HRS	9906.2		TSN 0						
	AFL	7538		TSN 0						
PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02										
324023	NO. 3 MAIN LANDING GEAR TIRE								Component	ATA:32
PN:226K08-4	MOS/MSC	27-Oct-25	O/C	TSN 0						
SN:50780755	HRS	9906.2		TSN 0						
	AFL	7538		TSN 0						
PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02										
324024	NO. 4 MAIN LANDING GEAR TIRE								Component	ATA:32
PN:226K08-4	MOS/MSC	27-Oct-25	O/C	TSN 0						
SN:50741022	HRS	9906.2		TSN 0						
	AFL	7538		TSN 0						
PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02										
324025	NOSE LANDING GEAR TIRE								Component	ATA:32
PN:03-613-8	MOS/MSC	13-Oct-25	O/C	TSN 0						
SN:5041T00281	HRS	9885.1		TSN 0						
	AFL	7524		TSN 0						
PROC. REF: AMM 32-40-01PROC. REF: AMM 32-40-01										
324061	LEFT ANTI-SKID CONTROL VALVE								Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-41-07PROC. REF: AMM 32-41-07										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
324062 RIGHT ANTI-SKID CONTROL VALVE									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-07PROC. REF: AMM 32-41-07									
324066 LEFT ANTI-SKID SHUTOFF VALVE									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
324067 RIGHT ANTI-SKID SHUTOFF VALVE									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
324097 BRAKE CONTROL UNIT									Component ATA:32
PN:42-933-3	MOS/MSC	03-Jan-06	O/C						
SN:150	HRS	4160.77							
	AFL	3151							
PROC. REF: AMM 32-41-02PROC. REF: AMM 32-41-02									
324108 EMERGENCY PARKING BRAKE CHECK VALVE									Component ATA:32
PN:1C4124	MOS/MSC	19-Mar-05	O/C						
SN:UNKNOWN	HRS	3391.45							
	AFL	2574							
PROC. REF: AMM 32-42-09PROC. REF: AMM 32-42-09									
324109 EMERGENCY/PARK BRAKE VALVE									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-42-01PROC. REF: AMM 32-42-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 32 - LANDING GEAR										
324110		EMERGENCY/PARK BRAKE PRESSURE TRANSDUCER						Component	ATA:32	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-42-03PROC. REF: AMM 32-42-03										
324111		NO. 1 MAIN LANDING GEAR BRAKE ASSEMBLY						Component	ATA:32	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01										
324112		NO. 2 MAIN LANDING GEAR BRAKE ASSEMBLY						Component	ATA:32	
PN:6632401000-002	MOS/MSC	27-Aug-21	O/C							
SN:2262	HRS	8708.2								
	AFL	6691								
PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01										
324113		NO. 3 MAIN LANDING GEAR BRAKE ASSEMBLY						Component	ATA:32	
PN:6632401000-002	MOS/MSC	25-Nov-19	O/C	TSO 0						
SN:1975	HRS	8177.7		TSO 0						
	AFL	6303		TSO 0						
PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01										
324114		NO. 4 MAIN LANDING GEAR BRAKE ASSEMBLY						Component	ATA:32	
PN:2-1579-2	MOS/MSC	15-Jul-11	O/C	TSO 0						
SN:0917SB	HRS	6651.4		TSO 0						
	AFL	5089		TSO 0						
PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01										
324201		NO. 1 BRAKE SHUTTLE VALVE						Component	ATA:32	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-42-04PROC. REF: AMM 32-42-04										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 32 - LANDING GEAR										
324202		NO. 2 BRAKE SHUTTLE VALVE						Component		ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-42-04PROC. REF: AMM 32-42-04										
324203		NO. 3 BRAKE SHUTTLE VALVE						Component		ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-42-04PROC. REF: AMM 32-42-04										
324204		NO. 4 BRAKE SHUTTLE VALVE						Component		ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-42-04PROC. REF: AMM 32-42-04										
324205		BRAKE SHUTTLE MODULE						Component		ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-41-04PROC. REF: AMM 32-41-04										
324305		LEFT PILOT BRAKE TRANSDUCER						Component		ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-41-03PROC. REF: AMM 32-41-03										
324306		RIGHT PILOT BRAKE TRANSDUCER						Component		ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-41-03PROC. REF: AMM 32-41-03										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 32 - LANDING GEAR										
324610-1		LEFT INBOARD BRAKE SWIVEL						Component	ATA:32	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01										
324610-2		LEFT OUTBOARD BRAKE SWIVEL						Component	ATA:32	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01										
324611-1		RIGHT INBOARD BRAKE SWIVEL						Component	ATA:32	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01										
324611-2		RIGHT OUTBOARD BRAKE SWIVEL						Component	ATA:32	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01										
324701		NO. 1 BRAKE HYDRAULIC FUSE						Component	ATA:32	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-41-09PROC. REF: AMM 32-41-09										
324702		NO. 2 BRAKE HYDRAULIC FUSE						Component	ATA:32	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-41-09PROC. REF: AMM 32-41-09										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 32 - LANDING GEAR										
324703		NO. 3 BRAKE HYDRAULIC FUSE						Component	ATA:32	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-41-09PROC. REF: AMM 32-41-09										
324704		NO. 4 BRAKE HYDRAULIC FUSE						Component	ATA:32	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-41-09PROC. REF: AMM 32-41-09										
324711		NO. 1 WHEEL SPEED TRANSDUCER						Component	ATA:32	
PN:140-183	MOS/MSC	17-Nov-20	O/C							
SN:3456	HRS	8301.3								
	AFL	6392								
PROC. REF: AMM 32-41-10PROC. REF: AMM 32-41-10										
324712		NO. 2 WHEEL SPEED TRANSDUCER						Component	ATA:32	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-41-10PROC. REF: AMM 32-41-10										
324713		NO. 3 WHEEL SPEED TRANSDUCER						Component	ATA:32	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-41-10PROC. REF: AMM 32-41-10										
324714		NO. 4 WHEEL SPEED TRANSDUCER						Component	ATA:32	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-41-10PROC. REF: AMM 32-41-10										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
324721 (MT56) BRAKE PRESSURE TRANSDUCER									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-08PROC. REF: AMM 32-41-08									
324722 (MT57) BRAKE PRESSURE TRANSDUCER									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-08PROC. REF: AMM 32-41-08									
324723 (MT58) BRAKE PRESSURE TRANSDUCER									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-08PROC. REF: AMM 32-41-08									
324724 (MT59) BRAKE PRESSURE TRANSDUCER									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-08PROC. REF: AMM 32-41-08									
324801 EMERGENCY/PARK BRAKE FUSE									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-42-07PROC. REF: AMM 32-42-07									
324805 EMERGENCY/PARK BRAKE ACCUMULATOR									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-42-02PROC. REF: AMM 32-42-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
325007 NOSE WHEEL STEERING FILTER BOX (P41)									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-50-06PROC. REF: AMM 32-50-06									
325011 NOSE WHEEL STEERING SERVO ACTUATOR									Component ATA:32
PN:JR5208C	MOS/MSC	13-Feb-08	O/C	TSR 4					
SN:A0437	HRS	5967.8		TSR 0					
	AFL	4562		TSR 0					
PROC. REF: AMM 32-50-02PROC. REF: AMM 32-50-02									
325021 NOSE WHEEL STEERING GEARBOX									Component ATA:32
PN:2W3201D	MOS/MSC	29-Oct-06	O/C						
SN:C0347	HRS	4933.32							
	AFL	3789							
PROC. REF: AMM 32-50-03PROC. REF: AMM 32-50-03									
325031 NOSE WHEEL STEERING COMPUTER									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-50-01PROC. REF: AMM 32-50-01									
325035 NOSE WHEEL STEERING POWER SUPPLY									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
325041 LEFT NOSE WHEEL STEERING TRANSDUCER									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-50-04PROC. REF: AMM 32-50-04									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
325042 RIGHT NOSE WHEEL STEERING TRANSDUCER									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-50-04PROC. REF: AMM 32-50-04									
325051 ^S NOSE LANDING GEAR ACTUATOR UPPER PIN									Component ATA:32
PN:4532302043-007	MOS	09-Mar-01		TSN 0				LIFE LIMIT	
SN:132	HRS	0		TSN 0					
	AFL	0	20000	TSN 0					
PROC. REF: AMM 32-32-01PROC. REF: AMM 32-32-01									
326000 NOSE LANDING GEAR WIRE HARNESS									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
326104 NOSE LANDING GEAR SQUAT/WOW SWITCH (S178)									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-50-09PROC. REF: AMM 32-50-09									
326105 NO. 1 MAIN GEAR SQUAT SWITCH									Component ATA:32
PN:444EN2-R	MOS/MSC	18-Oct-22	O/C	TSN 0					
SN:UNKNOWN	HRS	9133.2		TSN 0					
	AFL	7007		TSN 0					
PROC. REF: AMM 32-60-09PROC. REF: AMM 32-60-09									
326106 NO. 2 MAIN GEAR SQUAT SWITCH									Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-60-09PROC. REF: AMM 32-60-09									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 32 - LANDING GEAR										
326107	NO. 3 MAIN GEAR SQUAT SWITCH								Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-60-09PROC. REF: AMM 32-60-09										
326108	NO. 4 MAIN GEAR SQUAT SWITCH								Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-60-09PROC. REF: AMM 32-60-09										
326115	SQUAT SWITCH RELAY BOX P21								Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-60-08PROC. REF: AMM 32-60-08										
A3230001 ^S	** LANDING GEAR - PERFORM EMERGENCY GEAR EXTENSION FUNCTIONAL TEST								Service	ATA:32
	MOS	02-Aug-24	24					AIRWORTHINESS		
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 32-33-00PROC. REF: AMM 32-33-00										
A3240005 ^S	** BRAKE HYDRAULIC FUSES - PERFORM FUNCTIONAL TEST								Service	ATA:32
	MOS	09-Mar-01	48					AIRWORTHINESS		
	HRS	0	1200							
	AFL	0								
PROC. REF: AMM 32-41-09PROC. REF: AMM 32-41-09										
A3240006 ^S	** BRAKE SHUTTLE MODULE - PERFORM FUNCTIONAL TEST								Service	ATA:32
	MOS	09-Mar-01	48					AIRWORTHINESS		
	HRS	0	1200							
	AFL	0								
PROC. REF: AMM 32-41-04PROC. REF: AMM 32-41-04										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 32 - LANDING GEAR

A3240007 ^S		** BRAKE SHUTTLE VALVES - PERFORM FUNCTIONAL TEST						Service	ATA:32
	MOS	25-Nov-19	96					AIRWORTHINESS	
	HRS	8177.7	2400						
	AFL	6303							
PKG:23									
PROC. REF: AMM 32-42-04PROC. REF: AMM 32-42-04									

A3240009 ^S		** BRAKE PRESSURE TRANSDUCERS - PERFORM FUNCTIONAL TEST						Service	ATA:32
	MOS	09-Mar-01						AIRWORTHINESS	
	HRS	0	4800						
	AFL	0							
PKG:25									
PROC. REF: AMM 32-41-08PROC. REF: AMM 32-41-08									

AA3220018		LEFT MAIN LANDING GEAR STRUT - PERFORM SPECIAL DETAILED INSPECTION						Service	ATA:32
PN:200-0200-013	MOS	30-Mar-21	96		30-Mar-29		1039 d		
SN:H0584	HRS	8414.4							
	AFL	6463	6600		13063		5447		
PROC. REF: NDT PART 7/32-10-01, NDT PART 7/32-10-03, NDT PART 7/32-10-04, NDT PART 8/32-10-02, NDT PART 7/32-10-05, NDT PART 7/32-10-06, NDT PART 8/32-10-01, NDT PART 8/32-10-03PROC. REF: NDT PART 7/32-10-01, NDT PART 7/32-10-03, NDT PART 7/32-10-04, NDT PART 8/32-10-02, NDT PART 7/32-10-05, NDT PART 7/32-10-06, NDT PART 8/32-10-01, NDT PART 8/32-10-03									

AA3220018		RIGHT MAIN LANDING GEAR STRUT - PERFORM SPECIAL DETAILED INSPECTION						Service	ATA:32
PN:200-0200-014	MOS	30-Mar-21	96		30-Mar-29		1039 d		
SN:H1593	HRS	8414.4							
	AFL	6463	6600		13063		5447		
PROC. REF: NDT PART 7/32-10-01, NDT PART 7/32-10-03, NDT PART 7/32-10-04, NDT PART 8/32-10-02, NDT PART 7/32-10-05, NDT PART 7/32-10-06, NDT PART 8/32-10-01, NDT PART 8/32-10-03PROC. REF: NDT PART 7/32-10-01, NDT PART 7/32-10-03, NDT PART 7/32-10-04, NDT PART 8/32-10-02, NDT PART 7/32-10-05, NDT PART 7/32-10-06, NDT PART 8/32-10-01, NDT PART 8/32-10-03									

AA3220111		LEFT MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY - DISASSEMBLE ACTUATOR AND PERFORM DETAILED VISUAL INSPECTION						Service	ATA:32
	MOS	30-Mar-21	96		30-Mar-29		1039 d		
	HRS	8414.4							
	AFL	6463	10000		16463		8847		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
AA3220111	RIGHT MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY - DISASSEMBLE ACTUATOR AND PERFORM DETAILED VISUAL INSPECTION							Service	ATA:32
	MOS	30-Mar-21	96		30-Mar-29		1039 d		
	HRS	8414.4							
	AFL	6463	10000		16463		8847		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
AE3220151	LEFT - MAIN LANDING GEAR STRUT ASSEMBLY REBOUND RING - REPLACE.							Service	ATA:32
	MOS	EFF	96		30-Mar-29 * (M)		1039 d		
	HRS								
	AFL								
PROC. REF: AMM 32-31-02PROC. REF: AMM 32-31-02									
AE3220151	RIGHT - MAIN LANDING GEAR STRUT ASSEMBLY REBOUND RING - REPLACE.							Service	ATA:32
	MOS	EFF	96		30-Mar-29 * (M)		1039 d		
	HRS								
	AFL								
PROC. REF: AMM 32-31-02PROC. REF: AMM 32-31-02									
D3260006	NOSE LANDING GEAR SQUAT SWITCH ROTATING DISK ASSEMBLY - LUBRICATE							Service	ATA:32
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01									
F3220045	NOSE LANDING GEAR ACTUATOR ATTACHMENT FITTING - REPLACE							Service	ATA:32
	MOS/MSC	09-Mar-01	N/A					NOT INSTALLED	
	HRS	0							
	AFL	0							
PROC. REF: AMM 32-32-01PROC. REF: AMM 32-32-01									
J3220120	* MAIN LANDING GEAR TRUNNION SHEAR PIN BUSHING - PERFORM DETAILED VISUAL INSPECTION FOR BUSHING MIGRATION							Service	ATA:32
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 32 - LANDING GEAR										
L3220020	* MAIN LANDING GEAR TRUNNION FITTINGS ON MID AND REAR SPAR - PERFORM EDDY CURRENT INSPECTION								Service	ATA:32
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0								
	AFL	0	T:10000		10000		2384			
PROC. REF: NDT PART 6/32-11-00PROC. REF: NDT PART 6/32-11-00										
L3220118	* RIGHT MAIN LANDING GEAR SHOCK STRUT CYLINDER - PERFORM ULTRASONIC INSPECTION OF THE LOWER SERVICE PORT AND FORGING PARTING LINE								Service	ATA:32
PN:200-0201-010	MOS	27-Nov-22						AIRWORTHINESS		
SN:H0755	HRS	9163.6								
	AFL	7031	600		7631		15			
L3220122	* RIGHT MAIN LANDING GEAR SHOCK STRUT CYLINDER - PERFORM ULTRASONIC INSPECTION OF THE LOWER SERVICE PORT AND FORGING PARTING LINE								Service	ATA:32
PN:200-0201-010	MOS/MSC	27-Nov-22	N/A							
SN:H0755	HRS	9163.6								
	AFL	7031								
PROC. REF: NDT PART 4/32-10-01, NDT PART 4/32-10-00PROC. REF: NDT PART 4/32-10-01, NDT PART 4/32-10-00										
M3220136	* RIGHT MAIN LANDING GEAR SHOCK STRUT CYLINDER - PERFORM ULTRASONIC INSPECTION OF THE LOWER SERVICE PORT AND FORGING PARTING LINE								Service	ATA:32
PN:200-0201-010	MOS/MSC	27-Nov-22	N/A							
SN:H0755	HRS	9163.6								
	AFL	7031								
N3220036	* LEFT MAIN LANDING GEAR AXLE BEAM - REPLACE								Service	ATA:32
PN:200-0203-001	MOS	08-Sep-12						LIFE LIMIT		
SN:H0331	HRS	6989.1								
	AFL	5335	10000	TAC 5311	10024		2408			
N3220036	* RIGHT MAIN LANDING GEAR AXLE BEAM - REPLACE								Service	ATA:32
PN:200-0203-001	MOS	08-Sep-12						LIFE LIMIT		
SN:H0334	HRS	6989.1								
	AFL	5335	10000	TAC 5311	10024		2408			

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
N3220041 * LEFT FORWARD LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE									Service ATA:32
PN:4532103201-001	MOS/MSC	15-Dec-10	N/A						
SN:CMI882	HRS	6457.2							
	AFL	4944							
<hr/>									
N3220041 * LEFT FORWARD UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE									Service ATA:32
PN:4532103201-001	MOS/MSC	15-Dec-10	N/A						
SN:CMI806	HRS	6457.2							
	AFL	4944							
<hr/>									
N3220041 * RIGHT FORWARD LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE									Service ATA:32
PN:4532103201-001	MOS/MSC	15-Dec-10	N/A						
SN:CMI1113	HRS	6457.2							
	AFL	4944							
<hr/>									
N3220041 * RIGHT FORWARD UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE									Service ATA:32
PN:4532103201-001	MOS/MSC	15-Dec-10	N/A						
SN:CMI710	HRS	6457.2							
	AFL	4944							
<hr/>									
N3220042 * LEFT AFT UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE									Service ATA:32
PN:4532103202-001	MOS/MSC	18-Dec-10	N/A						
SN:CMI371	HRS	6457.2							
	AFL	4944							
<hr/>									
N3220042 * RIGHT AFT UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE									Service ATA:32
PN:4532103202-001	MOS/MSC	18-Dec-10	N/A						
SN:CMI363	HRS	6457.2							
	AFL	4944							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
N3220043 * LEFT AFT LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE									Service ATA:32
PN:4532103203-001	MOS/MSC	18-Dec-10	N/A						
SN:CMI818	HRS	6457.2							
	AFL	4944							
<hr/>									
N3220043 * RIGHT AFT LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE									Service ATA:32
PN:4532103203-001	MOS/MSC	18-Dec-10	N/A						
SN:CMI759	HRS	6457.2							
	AFL	4944							
<hr/>									
N3220103 * LEFT MAIN LANDING GEAR ACTUATOR PISTON - REPLACE									Service ATA:32
PN:PN	MOS	09-Mar-01						LIFE LIMIT	
SN:UNKNOWN	HRS	0							
	AFL	0	17000		17000		9384		
<hr/>									
N3220103 * RIGHT MAIN LANDING GEAR ACTUATOR PISTON - REPLACE									Service ATA:32
PN:4532101000V72-002	MOS	09-Mar-01						LIFE LIMIT	
SN:H1153	HRS	0							
	AFL	0	17000		17000		9384		
<hr/>									
N3220104 * LEFT MAIN LANDING GEAR ACTUATOR CYLINDER - REPLACE									Service ATA:32
PN:4532101000V76-001	MOS	09-Mar-01						LIFE LIMIT	
SN:H0155	HRS	0							
	AFL	0	17000		17000		9384		
<hr/>									
N3220104 * RIGHT MAIN LANDING GEAR ACTUATOR CYLINDER - REPLACE									Service ATA:32
PN:4532101000V72-002	MOS	09-Mar-01						LIFE LIMIT	
SN:H1153	HRS	0							
	AFL	0	17000		17000		9384		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
N3220106 * LEFT MAIN LANDING GEAR ACTUATOR HOUSING - REPLACE									
PN:200-0304-001	MOS		19-Dec-10					LIFE LIMIT	Service ATA:32
SN:H1704	HRS		6457.2						
	AFL		4944		17000	21944	14328		
N3220106 * RIGHT MAIN LANDING GEAR ACTUATOR HOUSING - REPLACE									
PN:4532101000V72-002	MOS		09-Mar-01					LIFE LIMIT	Service ATA:32
SN:H1153	HRS		0						
	AFL		0		17000	17000	9384		
N3220116 * LEFT MAIN LANDING GEAR SHOCK STRUT CYLINDER - REPLACE									
PN:200-0201-009	MOS		30-Mar-21					LIFE LIMIT	Service ATA:32
SN:H0727	HRS		8414.4						
	AFL		6463		10000 TAC 1409	15054	7438		
N3220116 * RIGHT MAIN LANDING GEAR SHOCK STRUT CYLINDER - REPLACE									
PN:200-0201-010	MOS		30-Mar-21					LIFE LIMIT	Service ATA:32
SN:H0755	HRS		8414.4						
	AFL		6463		10000 TAC 1409	15054	7438		
N3220139 * LEFT FORWARD LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE									
PN:4532103201-001	MOS		15-Dec-10					LIFE LIMIT	Service ATA:32
SN:CMI882	HRS		6457.2						
	AFL		4944		5000	9944	2328		
N3220139 * LEFT FORWARD UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE									
PN:4532103201-001	MOS		15-Dec-10					LIFE LIMIT	Service ATA:32
SN:CMI806	HRS		6457.2						
	AFL		4944		5000	9944	2328		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 32 - LANDING GEAR										
N3220139		* RIGHT FORWARD LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE							Service	ATA:32
PN:4532103201-001	MOS	15-Dec-10						LIFE LIMIT		
SN:CMI1113	HRS	6457.2								
	AFL	4944	5000		9944		2328			
N3220139		* RIGHT FORWARD UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE							Service	ATA:32
PN:4532103201-001	MOS	15-Dec-10						LIFE LIMIT		
SN:CMI710	HRS	6457.2								
	AFL	4944	5000		9944		2328			
N3220140		* LEFT AFT UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE							Service	ATA:32
PN:4532103202-001	MOS	18-Dec-10						LIFE LIMIT		
SN:CMI371	HRS	6457.2								
	AFL	4944	5000		9944		2328			
N3220140		* RIGHT AFT UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE							Service	ATA:32
PN:4532103202-001	MOS	18-Dec-10						LIFE LIMIT		
SN:CMI363	HRS	6457.2								
	AFL	4944	5000		9944		2328			
N3220141		* LEFT AFT LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE							Service	ATA:32
PN:4532103203-001	MOS	18-Dec-10						LIFE LIMIT		
SN:CMI818	HRS	6457.2								
	AFL	4944	5000		9944		2328			
N3220141		* RIGHT AFT LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE							Service	ATA:32
PN:4532103203-001	MOS	18-Dec-10						LIFE LIMIT		
SN:CMI759	HRS	6457.2								
	AFL	4944	5000		9944		2328			

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
P3220146 * RIGHT MAIN LANDING GEAR SHOCK STRUT CYLINDER - PERFORM ULTRASONIC INSPECTION OF THE FORGING PARTING LINE Service ATA:32									
PN:200-0201-010	MOS/MSC	27-Nov-22	N/A						
SN:H0755	HRS	9163.6							
	AFL	7031							
PROC. REF: NDT PART 4/32-10-01, NDT PART 4/32-10-00PROC. REF: NDT PART 4/32-10-01, NDT PART 4/32-10-00									
P3231020 LEFT MAIN LANDING GEAR DOOR ACTUATOR GIMBAL ASSEMBLY - PERFORM EDDY CURRENT INSPECTION Service ATA:32									
	MOS	02-Aug-24			RTS				
	HRS	9525.7							
	AFL	7276	300						
PROC. REF: NDT PART 6/32-13-00PROC. REF: NDT PART 6/32-13-00									
P3231021 LEFT MAIN LANDING GEAR DOOR ACTUATOR GIMBAL SHAFT - PERFORM FLUORESCENT PENETRANT INSPECTION Service ATA:32									
	MOS	02-Aug-24			RTS				
	HRS	9525.7							
	AFL	7276	300						
PROC. REF: NDT PART 8/32-13-02PROC. REF: NDT PART 8/32-13-02									
Q3220065 * LEFT MAIN LANDING GEAR ACTUATOR PISTON - REPLACE Service ATA:32									
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
Q3220065 * RIGHT MAIN LANDING GEAR ACTUATOR PISTON - REPLACE Service ATA:32									
PN:4532101000V72-002	MOS/MSC	09-Mar-01	N/A						
SN:H1153	HRS	0							
	AFL	0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
Q3220066 * LEFT MAIN LANDING GEAR ACTUATOR CYLINDER - REPLACE Service ATA:32									
PN:4532101000V76-001	MOS/MSC	09-Mar-01	N/A						
SN:H0155	HRS	0							
	AFL	0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
Q3220066 * RIGHT MAIN LANDING GEAR ACTUATOR CYLINDER - REPLACE Service ATA:32									
PN:4532101000V72-002	MOS/MSC	09-Mar-01	N/A						
SN:H1153	HRS	0							
	AFL	0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
Q3220068 * LEFT MAIN LANDING GEAR ACTUATOR HOUSING - REPLACE Service ATA:32									
PN:200-0304-001	MOS/MSC	19-Dec-10	N/A						
SN:H1704	HRS	6457.2							
	AFL	4944							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
Q3220068 * RIGHT MAIN LANDING GEAR ACTUATOR HOUSING - REPLACE Service ATA:32									
PN:4532101000V72-002	MOS/MSC	09-Mar-01	N/A						
SN:H1153	HRS	0							
	AFL	0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
Q3220128 * LEFT MAIN LANDING GEAR SHOCK STRUT CYLINDER - REPLACE Service ATA:32									
PN:200-0201-009	MOS/MSC	30-Mar-21	N/A						
SN:H0727	HRS	8414.4							
	AFL	6463							
Q3220128 * RIGHT MAIN LANDING GEAR SHOCK STRUT CYLINDER - REPLACE Service ATA:32									
PN:200-0201-010	MOS/MSC	30-Mar-21	N/A						
SN:H0755	HRS	8414.4							
	AFL	6463							
Q3220137 * LEFT MAIN LANDING GEAR SHOCK STRUT CYLINDER - REPLACE Service ATA:32									
PN:200-0201-009	MOS/MSC	30-Mar-21	N/A						
SN:H0727	HRS	8414.4							
	AFL	6463							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 32 - LANDING GEAR										
Q3220137	* RIGHT MAIN LANDING GEAR SHOCK STRUT CYLINDER - REPLACE								Service	ATA:32
PN:200-0201-010	MOS/MSC		30-Mar-21	N/A						
SN:H0755	HRS		8414.4							
	AFL		6463							
Q3220142	* LEFT FORWARD LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE								Service	ATA:32
PN:4532103201-001	MOS/MSC		15-Dec-10	N/A						
SN:CMI882	HRS		6457.2							
	AFL		4944							
Q3220142	* LEFT FORWARD UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE								Service	ATA:32
PN:4532103201-001	MOS/MSC		15-Dec-10	N/A						
SN:CMI806	HRS		6457.2							
	AFL		4944							
Q3220142	* RIGHT FORWARD LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE								Service	ATA:32
PN:4532103201-001	MOS/MSC		15-Dec-10	N/A						
SN:CMI1113	HRS		6457.2							
	AFL		4944							
Q3220142	* RIGHT FORWARD UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE								Service	ATA:32
PN:4532103201-001	MOS/MSC		15-Dec-10	N/A						
SN:CMI710	HRS		6457.2							
	AFL		4944							
Q3220143	* LEFT AFT UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE								Service	ATA:32
PN:4532103202-001	MOS/MSC		18-Dec-10	N/A						
SN:CMI371	HRS		6457.2							
	AFL		4944							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
Q3220143 * RIGHT AFT UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE Service ATA:32									
PN:4532103202-001	MOS/MSC	18-Dec-10	N/A						
SN:CMI363	HRS	6457.2							
	AFL	4944							
Q3220144 * LEFT AFT LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE Service ATA:32									
PN:4532103203-001	MOS/MSC	18-Dec-10	N/A						
SN:CMI818	HRS	6457.2							
	AFL	4944							
Q3220144 * RIGHT AFT LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE Service ATA:32									
PN:4532103203-001	MOS/MSC	18-Dec-10	N/A						
SN:CMI759	HRS	6457.2							
	AFL	4944							
T3220007 * LEFT MAIN LANDING GEAR AXLE BEAM - PERFORM MAIN LANDING GEAR AXLE BEAM ASSEMBLY BORESCOPE INSPECTION Service ATA:32									
PN:200-0203-001	MOS	02-Aug-24	48		02-Aug-28		799 d	AIRWORTHINESS	
SN:H0331	HRS	9525.7							
	AFL	7276							
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
T3220007 * RIGHT MAIN LANDING GEAR AXLE BEAM - PERFORM MAIN LANDING GEAR AXLE BEAM ASSEMBLY BORESCOPE INSPECTION Service ATA:32									
PN:200-0203-001	MOS	02-Aug-24	48		02-Aug-28		799 d	AIRWORTHINESS	
SN:H0334	HRS	9525.7							
	AFL	7276							
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
T3220013 * LEFT MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY - REPLACE Service ATA:32									
PN:200-0300-003	MOS	02-Aug-24						LIFE LIMIT	
SN:H0134	HRS	9525.7							
	AFL	7276	17000	TAC 7276	17000		9384		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
T3220013 * RIGHT MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY - REPLACE									
PN:200-0300-004	MOS	02-Aug-24						LIFE LIMIT	Service ATA:32
SN:H1188	HRS	9525.7							
	AFL	7276	17000	TAC 7276	17000		9384		
T3220014 * LEFT MAIN LANDING GEAR ACTUATOR UPPER PIN - REPLACE									
PN:200-0325-101	MOS	24-Jun-19	96	TAC 0	24-Jun-27		394 d	LIFE LIMIT	Service ATA:32
SN:H2409	HRS	8101.1		TAC 0					
	AFL	6233		TAC 0					
PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01									
T3220014 * RIGHT MAIN LANDING GEAR ACTUATOR UPPER PIN - REPLACE									
PN:200-0325-101	MOS	24-Jun-19	96	TAC 0	24-Jun-27		394 d	LIFE LIMIT	Service ATA:32
SN:HER08U/5030	HRS	8101.1		TAC 0					
	AFL	6233		TAC 0					
PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01									
T3220024 * LEFT MAIN LANDING GEAR ACTUATOR LOWER PIN - PERFORM MAGNETIC PARTICLE INSPECTION									
PN:200-0217-101	MOS	22-Jun-23	48		22-Jun-27		392 d	AIRWORTHINESS	Service ATA:32
SN:H5000	HRS	9258.5							
	AFL	7100							
PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01									
T3220024 * LEFT MAIN LANDING GEAR ACTUATOR UPPER PIN - PERFORM MAGNETIC PARTICLE INSPECTION									
PN:200-0325-101	MOS	22-Jun-23	48		22-Jun-27		392 d	AIRWORTHINESS	Service ATA:32
SN:H2409	HRS	9258.5							
	AFL	7100							
PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01									
T3220024 * RIGHT MAIN LANDING GEAR ACTUATOR LOWER PIN - PERFORM MAGNETIC PARTICLE INSPECTION									
PN:200-0217-101	MOS	22-Jun-23	48		22-Jun-27		392 d	AIRWORTHINESS	Service ATA:32
SN:HER08U5014	HRS	9258.5							
	AFL	7100							
PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
T3220024 * RIGHT MAIN LANDING GEAR ACTUATOR UPPER PIN - PERFORM MAGNETIC PARTICLE INSPECTION Service ATA:32									
PN:200-0325-101	MOS	22-Jun-23	48		22-Jun-27		392 d	AIRWORTHINESS	
SN:HER08U/5030	HRS	9258.5							
	AFL	7100							
PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01									
T3220038 * LEFT MAIN LANDING GEAR ACTUATOR LOWER PIN - REPLACE Service ATA:32									
PN:200-0217-101	MOS	24-Jun-19	96	TAC 0	24-Jun-27		394 d	LIFE LIMIT	
SN:H5000	HRS	8101.1		TAC 0					
	AFL	6233		TAC 0					
PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01									
T3220038 * RIGHT MAIN LANDING GEAR ACTUATOR LOWER PIN - REPLACE Service ATA:32									
PN:200-0217-101	MOS	24-Jun-19	96	TAC 0	24-Jun-27		394 d	LIFE LIMIT	
SN:HER08U5014	HRS	8101.1		TAC 0					
	AFL	6233		TAC 0					
PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01									
T3220046 * LEFT MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY - REPLACE Service ATA:32									
PN:200-0300-003	MOS/MSC	02-Aug-24	N/A						
SN:H0134	HRS	9525.7							
	AFL	7276							
T3220046 * RIGHT MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY - REPLACE Service ATA:32									
PN:200-0300-004	MOS/MSC	02-Aug-24	N/A						
SN:H1188	HRS	9525.7							
	AFL	7276							
T3220063 * LEFT MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY - REPLACE Service ATA:32									
PN:200-0300-003	MOS/MSC	02-Aug-24	N/A						
SN:H0134	HRS	9525.7							
	AFL	7276							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
T3220063 * RIGHT MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY - REPLACE Service ATA:32									
PN:200-0300-004	MOS/MSC	02-Aug-24	N/A						
SN:H1188	HRS	9525.7							
	AFL	7276							
T3220064 * LEFT MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY - REPLACE Service ATA:32									
PN:200-0300-003	MOS/MSC	02-Aug-24	N/A						
SN:H0134	HRS	9525.7							
	AFL	7276							
T3220064 * RIGHT MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY - REPLACE Service ATA:32									
PN:200-0300-004	MOS/MSC	02-Aug-24	N/A						
SN:H1188	HRS	9525.7							
	AFL	7276							
T3220067 * LEFT MAIN LANDING GEAR ACTUATOR END CAP - REPLACE Service ATA:32									
PN:200-0303-001	MOS/MSC	02-Aug-24	N/A						
SN:UNKNOWN	HRS	9525.7							
	AFL	7276							
T3220067 * RIGHT MAIN LANDING GEAR ACTUATOR END CAP - REPLACE Service ATA:32									
PN:200-0303-001	MOS/MSC	02-Aug-24	N/A						
SN:UNKNOWN	HRS	9525.7							
	AFL	7276							
T3220105 * LEFT MAIN LANDING GEAR ACTUATOR END CAP - REPLACE Service ATA:32									
PN:200-0303-001	MOS	02-Aug-24						LIFE LIMIT	
SN:UNKNOWN	HRS	9525.7							
	AFL	7276	2387		9663		2047		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
T3220105 * RIGHT MAIN LANDING GEAR ACTUATOR END CAP - REPLACE Service ATA:32									
PN:200-0303-001	MOS	02-Aug-24						LIFE LIMIT	
SN:UNKNOWN	HRS	9525.7							
	AFL	7276	2387		9663		2047		
T3220135 * LEFT MAIN LANDING GEAR ACTUATOR LOWER PIN - PERFORM DETAILED VISUAL INSPECTION Service ATA:32									
PN:200-0217-101	MOS	22-Jun-23	48		22-Jun-27		392 d	AIRWORTHINESS	
SN:H5000	HRS	9258.5							
	AFL	7100							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
T3220135 * LEFT MAIN LANDING GEAR ACTUATOR UPPER PIN - PERFORM DETAILED VISUAL INSPECTION Service ATA:32									
PN:200-0325-101	MOS	22-Jun-23	48		22-Jun-27		392 d	AIRWORTHINESS	
SN:H2409	HRS	9258.5							
	AFL	7100							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
T3220135 * RIGHT MAIN LANDING GEAR ACTUATOR LOWER PIN - PERFORM DETAILED VISUAL INSPECTION Service ATA:32									
PN:200-0217-101	MOS	22-Jun-23	48		22-Jun-27		392 d	AIRWORTHINESS	
SN:HER08U5014	HRS	9258.5							
	AFL	7100							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
T3220135 * RIGHT MAIN LANDING GEAR ACTUATOR UPPER PIN - PERFORM DETAILED VISUAL INSPECTION Service ATA:32									
PN:200-0325-101	MOS	22-Jun-23	48		22-Jun-27		392 d	AIRWORTHINESS	
SN:HER08U/5030	HRS	9258.5							
	AFL	7100							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
T3220147 * LEFT AFT LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN - PERFORM VISUAL INSPECTION FOR PIN MIGRATION Service ATA:32									
	MOS/MSC		N/A						
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
T3220147					* LEFT AFT UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN - PERFORM VISUAL INSPECTION FOR PIN MIGRATION			Service	ATA:32
	MOS/MSC		N/A						
	HRS								
	AFL								
T3220147					* LEFT FORWARD LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN - PERFORM VISUAL INSPECTION FOR PIN MIGRATION			Service	ATA:32
	MOS/MSC		N/A						
	HRS								
	AFL								
T3220147					* LEFT FORWARD UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN - PERFORM VISUAL INSPECTION FOR PIN MIGRATION			Service	ATA:32
	MOS/MSC		N/A						
	HRS								
	AFL								
T3220147					* RIGHT AFT LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN - PERFORM VISUAL INSPECTION FOR PIN MIGRATION			Service	ATA:32
	MOS/MSC		N/A						
	HRS								
	AFL								
T3220147					* RIGHT AFT UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN - PERFORM VISUAL INSPECTION FOR PIN MIGRATION			Service	ATA:32
	MOS/MSC		N/A						
	HRS								
	AFL								
T3220147					* RIGHT FORWARD LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN - PERFORM VISUAL INSPECTION FOR PIN MIGRATION			Service	ATA:32
	MOS/MSC		N/A						
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
T3220147 * RIGHT FORWARD UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN - PERFORM VISUAL INSPECTION FOR PIN MIGRATION									
	MOS/MSC		N/A						Service ATA:32
	HRS								
	AFL								
V3220022 LEFT AFT MAIN LANDING GEAR TRUNNION PIN - PERFORM MAGNETIC PARTICLE INSPECTION									
PN:200-0213-103	MOS	30-Mar-21	96		30-Mar-29		1039 d		Service ATA:32
SN:H0364	HRS	8414.4							
	AFL	6463							
PROC. REF: NDT PART 7/32-10-07, NDT PART 7/32-10-08PROC. REF: NDT PART 7/32-10-07, NDT PART 7/32-10-08									
V3220022 LEFT FORWARD MAIN LANDING GEAR TRUNNION PIN - PERFORM MAGNETIC PARTICLE INSPECTION									
PN:200-0212-103	MOS	30-Mar-21	96		30-Mar-29		1039 d		Service ATA:32
SN:H0501	HRS	8414.4							
	AFL	6463							
PROC. REF: NDT PART 7/32-10-07, NDT PART 7/32-10-08PROC. REF: NDT PART 7/32-10-07, NDT PART 7/32-10-08									
V3220022 RIGHT AFT MAIN LANDING GEAR TRUNNION PIN - PERFORM MAGNETIC PARTICLE INSPECTION									
PN:200-0213-103	MOS	30-Mar-21	96		30-Mar-29		1039 d		Service ATA:32
SN:H0338	HRS	8414.4							
	AFL	6463							
PROC. REF: NDT PART 7/32-10-07, NDT PART 7/32-10-08PROC. REF: NDT PART 7/32-10-07, NDT PART 7/32-10-08									
V3220022 RIGHT FORWARD MAIN LANDING GEAR TRUNNION PIN - PERFORM MAGNETIC PARTICLE INSPECTION									
PN:200-0212-103	MOS	30-Mar-21	96		30-Mar-29		1039 d		Service ATA:32
SN:H0473	HRS	8414.4							
	AFL	6463							
PROC. REF: NDT PART 7/32-10-07, NDT PART 7/32-10-08PROC. REF: NDT PART 7/32-10-07, NDT PART 7/32-10-08									
V3240004 ^S ** EMERGENCY/PARKING BRAKE SWITCH - VERIFY THAT "EMERGENCY/PARKING BRAKE" MESSAGE ILLUMINATES ON EICAS WHEN PARKING BRAKE IS SET AND THROTTLES ARE MOVED ABOVE MCR DETENT.									
	MOS	02-Aug-24	24					AIRWORTHINESS	Service ATA:32
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 32-42-01PROC. REF: AMM 32-42-01									

PKG:11

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 32 - LANDING GEAR										
V3240008	^S	** EMERGENCY/PARKING BRAKE CONTROL SYSTEM - PERFORM FUNCTIONAL TEST							Service	ATA:32
	MOS	02-Aug-24	24					AIRWORTHINESS		
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 32-42-02PROC. REF: AMM 32-42-02										
W3220149 * LEFT MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY - REPLACE										
PN:200-0300-003	MOS/MSC	02-Aug-24	N/A						Service ATA:32	
SN:H0134	HRS	9525.7								
	AFL	7276								
W3220149 * RIGHT MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY - REPLACE										
PN:200-0300-004	MOS/MSC	02-Aug-24	N/A						Service ATA:32	
SN:H1188	HRS	9525.7								
	AFL	7276								
W3220150 * LEFT MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY - REPLACE										
PN:200-0300-003	MOS/MSC	02-Aug-24	N/A						Service ATA:32	
SN:H0134	HRS	9525.7								
	AFL	7276								
W3220150 * RIGHT MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY - REPLACE										
PN:200-0300-004	MOS/MSC	02-Aug-24	N/A						Service ATA:32	
SN:H1188	HRS	9525.7								
	AFL	7276								
W3231022 LEFT MAIN LANDING GEAR INBOARD DOOR GIMBAL BRACKET - PERFORM EDDY CURRENT INSPECTION										
	MOS	02-Aug-24			RTS				Service ATA:32	
	HRS	9525.7								
	AFL	7276	300							
PROC. REF: NDT PART 6/32-13-01PROC. REF: NDT PART 6/32-13-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 32 - LANDING GEAR										
Y3220000	^S	NOSE LANDING GEAR ASSEMBLY - PERFORM VISUAL INSPECTION						Service	ATA:32	
	MOS	02-Aug-24	24							
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
Y3220001	^S	MAIN LANDING GEAR ASSEMBLY - PERFORM VISUAL INSPECTION. INSPECTION TO INCLUDE ACTUATOR, FASTENERS, SUPPORT STRUCTURE, AND SQUAT SWITCHES.						Service	ATA:32	
	MOS	02-Aug-24	24							
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
Y3220002	^S	NOSE LANDING GEAR ACTUATOR PRESSURE AND RETURN LINES - PERFORM VISUAL INSPECTION. LOWER ACTUATOR DUST BOOT TO INSPECT LINES.						Service	ATA:32	
	MOS	02-Aug-24	24							
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
Y3220003	^S	NOSE GEAR SHOCK STRUT - REMOVE AND REPLACE RETAINER RING LOCKSCREW						Service	ATA:32	
	MOS	02-Aug-24	24							
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
Y3220004	^S	MAIN LANDING GEAR ACTUATOR AND GEAR INBOARD DOOR ACTUATOR ATTACH POINTS - PERFORM VISUAL INSPECTION						Service	ATA:32	
	MOS	02-Aug-24	24							
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
Y3220006 ^S	LANDING GEAR ELECTRICAL WIRING - PERFORM VISUAL INSPECTION (THAT PORTION VISIBLE INSIDE WHEEL WELL)							Service	ATA:32
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PKG:11									
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
Y3220008 ^S	NOSE LANDING GEAR AXLE - REMOVE NOSE LANDING GEAR WHEEL AND PERFORM INSPECTION. INSPECT BOTH INSIDE AND OUTSIDE OF AXLE.							Service	ATA:32
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PKG:17									
PROC. REF: AMM 32-40-01PROC. REF: AMM 32-40-01									
Y3220124 ^S	NOSE LANDING GEAR - PERFORM DETAILED VISUAL INSPECTION OF THE NOSE LANDING GEAR UPLOCK ROLLER BRACKET							Service	ATA:32
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PKG:11									
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
Y3230002 ^S	MAIN LANDING GEAR FREE FALL ROLLER - PERFORM VISUAL INSPECTION. PAY PARTICULAR ATTENTION TO BINDING OF ROLLERS.							Service	ATA:32
	MOS	21-Aug-25	12						
	HRS	9809.8	300						
	AFL	7471							
PKG:5									
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
Y3231023 ^S	MAIN LANDING GEAR INBOARD DOOR ACTUATOR (PART NUMBER 7469) END CAP SCREWS - PERFORM DETAILED INSPECTION							Service	ATA:32
	MOS	09-Mar-01	12						
	HRS	0	300						
	AFL	0							
PKG:5									
PROC. REF: AMM 32-31-02PROC. REF: AMM 32-31-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 32 - LANDING GEAR										
Y3240000	^S	NOSE AND MAIN TIRES - PERFORM VISUAL INSPECTION						Service	ATA:32	
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 12-10-04PROC. REF: AMM 12-10-04										
Y3240001	^S	BRAKE LINES - PERFORM VISUAL INSPECTION. INSPECT ALL BRAKE LINES VISIBLE IN WHEEL WELLS AND ON STRUTS.						Service	ATA:32	
	MOS	02-Aug-24	24							
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
Y3240002	^S	BRAKE ASSEMBLIES - PERFORM VISUAL INSPECTION WITH PARKING BRAKE SET. WORN BRAKES ARE VISUALLY INDICATED WHEN THE WEAR INDICATOR PINS BECOME EVEN WITH THE OUTER SURFACE OF THE WEAR INDICATOR SLEEVE.						Service	ATA:32	
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01										
Y3240003	^S	BRAKE CONTROL SYSTEM LINEAR VARIABLE DIFFERENTIAL TRANSFORMER (LVDT) - PERFORM VISUAL INSPECTION						Service	ATA:32	
	MOS	09-Mar-01	48							
	HRS	0	1200							
	AFL	0								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
Y3260005	^S	NOSE LANDING GEAR SQUAT SWITCH ROTATING DISK ASSEMBLY - LUBRICATE						Service	ATA:32	
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 33 - LIGHTS										
330000		MODIFIED PULSE CONTROLLER						Component	ATA:33	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
<hr/>										
331001		NO. 1 COCKPIT LIGHTING CONTROL UNIT						Component	ATA:33	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 33-10-06PROC. REF: AMM 33-10-06										
<hr/>										
331002		NO. 2 COCKPIT LIGHTING CONTROL UNIT						Component	ATA:33	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 33-10-06PROC. REF: AMM 33-10-06										
<hr/>										
331010		PILOT FORWARD SWITCH PANEL OVERLAY						Component	ATA:33	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 33-10-05PROC. REF: AMM 33-10-05										
<hr/>										
331011		PILOT SWITCH PANEL						Component	ATA:33	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
<hr/>										
331012		COPILOT FORWARD SWITCH PANEL OVERLAY						Component	ATA:33	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 33-10-05PROC. REF: AMM 33-10-05										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 33 - LIGHTS									
331013 COPILOT FORWARD SWITCH PANEL									Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
331015 CENTER SWITCH PANEL (P5)									Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
331016 CENTER SWITCH PANEL (P5) OVERLAY									Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-10-05PROC. REF: AMM 33-10-05									
331017 THROTTLE QUADRANT OVERLAY PANEL									Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
331018 PILOT AFT CIRCUIT BREAKER PANEL OVERLAY									Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-10-05PROC. REF: AMM 33-10-05									
331019 COPILOT AFT CIRCUIT BREAKER PANEL OVERLAY									Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-10-05PROC. REF: AMM 33-10-05									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 33 - LIGHTS									
331020 DIMMER CONTROL BOX									Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-10-10PROC. REF: AMM 33-10-10									
331023 GLARESHIELD FLOOR FLOODLIGHTS INVERTER									Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
331025 COCKPIT MISCELLANEOUS RELAY BOX									Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-10-07PROC. REF: AMM 33-10-07									
331030 CENTER SWITCH PANEL DIODE BOX (P12)									Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-10-08PROC. REF: AMM 33-10-08									
331033 GLARESHIELD FLOODLIGHT POWER SUPPLY									Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
331040 PILOT REVERSION PANEL OVERLAY (DS55)									Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 33 - LIGHTS										
331101		P35 FUSE PANEL						Component		ATA:33
PN:4533108552-007	MOS/MSC	17-Feb-05	O/C							
SN:MRP644283-001	HRS	3300.2								
	AFL	2515								
PROC. REF: AMM 33-10-09PROC. REF: AMM 33-10-09										
331401-1		NO. 1 LEFT POWER SUPPLY INVERTER (PS5009)						Component		ATA:33
PN:AL-2000	MOS/MSC	11-Apr-05	O/C							
SN:46634	HRS	3496.3								
	AFL	2649								
PROC. REF: AMM 33-20-10PROC. REF: AMM 33-20-10										
331401-10		NO. 5 RIGHT POWER SUPPLY INVERTER (PS5006)						Component		ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-20-10PROC. REF: AMM 33-20-10										
331401-11		NO. 6 LEFT POWER SUPPLY INVERTER (LAVATORY) (PS5010)						Component		ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-20-10PROC. REF: AMM 33-20-10										
331401-2		NO. 1 RIGHT POWER SUPPLY INVERTER (PS5003)						Component		ATA:33
PN:AL-2000	MOS/MSC	11-Apr-05	O/C							
SN:46632	HRS	3496.3								
	AFL	2649								
PROC. REF: AMM 33-20-10PROC. REF: AMM 33-20-10										
331401-3		NO. 2 LEFT POWER SUPPLY INVERTER (PS5008)						Component		ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-20-10PROC. REF: AMM 33-20-10										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 33 - LIGHTS										
331401-4		NO. 2 RIGHT POWER SUPPLY INVERTER (PS5004)						Component	ATA:33	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 33-20-10PROC. REF: AMM 33-20-10										
331401-5		NO. 3 LEFT POWER SUPPLY INVERTER (PS5007)						Component	ATA:33	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 33-20-10PROC. REF: AMM 33-20-10										
331401-6		NO. 3 RIGHT POWER SUPPLY INVERTER (PS5005)						Component	ATA:33	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 33-20-10PROC. REF: AMM 33-20-10										
331401-7		NO. 4 LEFT POWER SUPPLY INVERTER (PS5006)						Component	ATA:33	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 33-20-10PROC. REF: AMM 33-20-10										
331401-8		NO. 4 RIGHT POWER SUPPLY INVERTER (LAVATORY) (PS5010)						Component	ATA:33	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 33-20-10PROC. REF: AMM 33-20-10										
331401-9		NO. 5 LEFT POWER SUPPLY INVERTER (LAVATORY) (PS5011)						Component	ATA:33	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 33-20-10PROC. REF: AMM 33-20-10										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 33 - LIGHTS										
332001		RIGHT NO. 1 PASSENGER LIGHTING CONTROL UNIT						Component	ATA:33	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 33-20-05PROC. REF: AMM 33-20-05										
332002		RIGHT NO. 2 PASSENGER LIGHTING CONTROL UNIT						Component	ATA:33	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 33-20-05PROC. REF: AMM 33-20-05										
332003		RIGHT NO. 3 PASSENGER LIGHTING CONTROL UNIT						Component	ATA:33	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 33-20-05PROC. REF: AMM 33-20-05										
332004		RIGHT NO. 4 PASSENGER LIGHTING CONTROL UNIT						Component	ATA:33	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 33-20-05PROC. REF: AMM 33-20-05										
332005		LEFT NO. 1 PASSENGER LIGHTING CONTROL UNIT						Component	ATA:33	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 33-20-05PROC. REF: AMM 33-20-05										
332006		LEFT NO. 2 PASSENGER LIGHTING CONTROL UNIT						Component	ATA:33	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 33-20-05PROC. REF: AMM 33-20-05										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 33 - LIGHTS									
332007 LEFT NO. 3 PASSENGER LIGHTING CONTROL UNIT									Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-20-05PROC. REF: AMM 33-20-05									
332008 LEFT NO. 4 PASSENGER LIGHTING CONTROL UNIT									Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-20-05PROC. REF: AMM 33-20-05									
332030 LAVATORY NO SMOKING / RETURN TO SEAT SIGN CONTROL UNIT (DS138)									Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-20-11PROC. REF: AMM 33-20-11									
332068 COPILOT LIGHTING CONTROL MODULE									Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-20-02PROC. REF: AMM 33-20-02									
332404 ENTRYWAY CONTROL LIGHT PANEL									Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-20-01PROC. REF: AMM 33-20-01									
334011 LEFT LANDING AND TAXI LIGHT									Component ATA:33
PN:GE4587	MOS/MSC	17-Feb-22	O/C	TSN 0					
SN:UNKNOWN	HRS	8864.4		TSN 0					
	AFL	6822		TSN 0					
PROC. REF: AMM 33-40-04PROC. REF: AMM 33-40-04									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 33 - LIGHTS									
334012 RIGHT LANDING AND TAXI LIGHT									Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-40-04PROC. REF: AMM 33-40-04									
334021 LEFT NAVIGATION LIGHT (DS37)									Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-40-02PROC. REF: AMM 33-40-02									
334022 RIGHT NAVIGATION LIGHT (DS38)									Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-40-02PROC. REF: AMM 33-40-02									
334023 TAIL NAVIGATION LIGHT (DS39)									Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-40-02PROC. REF: AMM 33-40-02									
334041 COPILOT REVERSION PANEL OVERLAY (DS56)									Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
334175 RELAY OPTIONS PANEL									Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 33 - LIGHTS										
334332 UPPER ANTI-COLLISION LIGHT									Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-40-01PROC. REF: AMM 33-40-01										
334333 LOWER ANTI-COLLISION LIGHT									Component	ATA:33
PN:GE-16386-12-1	MOS/MSC	22-Dec-08	O/C							
SN:AA2591	HRS	6088.7								
	AFL	4660								
PROC. REF: AMM 33-40-01PROC. REF: AMM 33-40-01										
335005 FORWARD ELS ACTIVATION MODULE (A81)									Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-50-01PROC. REF: AMM 33-50-01										
335006 AFT ELS ACTIVATION MODULE (A82)									Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-50-01PROC. REF: AMM 33-50-01										
336001 PILOT CHART HOLDER									Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
336002 COPILOT CHART HOLDER									Component	ATA:33
PN:10-62-01	MOS/MSC	17-Feb-05	O/C							
SN:3357	HRS	3300.2								
	AFL	2515								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 33 - LIGHTS										
336003	PILOT MAP LIGHT								Component	ATA:33
PN:0204327-001	MOS/MSC	12-Dec-11	O/C	TSN 0						
SN:542319	HRS	6763.5		TSN 0						
	AFL	5158		TSN 0						
PROC. REF: AMM 33-10-01PROC. REF: AMM 33-10-01										
336004	COPILOT MAP LIGHT								Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-10-01PROC. REF: AMM 33-10-01										
Y3310000 ^S	FLIGHT COMPARTMENT LIGHTING - PERFORM OPERATIONAL CHECK OF THE FOLLOWING: A. MAP LIGHTS. B. INSTRUMENT PANEL FLUORESCENT LIGHTS. C. INSTRUMENT/INDICATOR LIGHTS. D. LIGHT DIMMING SWITCHES. E. CREW WARNING PANEL. F. PANEL OVERLAYS.								Service	ATA:33
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 33-10-00PROC. REF: AMM 33-10-00										
Y3340000 ^S	EXTERIOR LIGHTING SYSTEMS - PERFORM OPERATION CHECK OF THE FOLLOWING: A. TAXI LIGHTS. B. ANTI-COLLISION BEACONS. C. NAVIGATION LIGHTS. D. STROBE LIGHTS. E. LANDING/RECOGNITION LIGHTS. F. WING ICE INSPECTION LIGHTS. G. EMERGENCY DOOR EGRESS LIGHTS.								Service	ATA:33
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 33-40-00, AMM 33-41-00PROC. REF: AMM 33-40-00, AMM 33-41-00										
Y3350003 ^S	EMERGENCY LIGHTING SYSTEM - PERFORM OPERATIONAL CHECK								Service	ATA:33
	MOS	22-Jun-23	48							
	HRS	9258.5	1200							
	AFL	7100								
PROC. REF: AMM 33-50-00PROC. REF: AMM 33-50-00										

PKG:1

PKG:2

PKG:14

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 34 - NAVIGATION										
34-00-FAR-91.171		CHECK VOR EQUIPMENT FOR IFR OPERATIONS FAR 91.171						Service	ATA:34	
	MOS/MSC	09-Mar-01	O/C							
	HRS	0								
	AFL	0								
PROC. REF: GENERIC NO REF, FAR FAR 91.171PROC. REF: GENERIC NO REF, FAR FAR 91.171										
341001		NO. 1 AIR DATA COMPUTER						Component	ATA:34	
PN:7014700-606	MOS/MSC	30-Apr-19	O/C							
SN:99072942	HRS	8080.6								
	AFL	6214								
PROC. REF: AMM 34-17-01PROC. REF: AMM 34-17-01										
341001A		TEST/INSPECT NO. 1 AIR DATA COMPUTER						Service	ATA:34	
PN:7014700-606	MOS	10-Aug-24	24		10-Aug-26		76 d			
SN:99072942	HRS									
	AFL									
Calibration Date: : 10-Aug-24										
PROC. REF: FAR FAR 91.411, AMM 34-17-00, CFR 14 CFR PART 43 APP EPROC. REF: FAR FAR 91.411, AMM 34-17-00, CFR 14 CFR PART 43 APP E										
341002		NO. 2 AIR DATA COMPUTER						Component	ATA:34	
PN:7014700-606	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:01014560	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-17-01PROC. REF: AMM 34-17-01										
341002A		TEST/INSPECT NO. 2 AIR DATA COMPUTER						Service	ATA:34	
PN:7014700-606	MOS	10-Aug-24	24		10-Aug-26		76 d			
SN:01014560	HRS									
	AFL									
Calibration Date: : 10-Aug-24										
PROC. REF: FAR FAR 91.411, AMM 34-17-00, CFR 14 CFR PART 43 APP EPROC. REF: FAR FAR 91.411, AMM 34-17-00, CFR 14 CFR PART 43 APP E										
341013		STANDBY AIRSPEED INDICATOR						Component	ATA:34	
PN:6634208002-003	MOS/MSC	17-Dec-05	O/C							
SN:274205	HRS	4110.78								
	AFL	3119								
PROC. REF: AMM 34-18-01PROC. REF: AMM 34-18-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 34 - NAVIGATION										
341025		STANDBY ALTIMETER						Component	ATA:34	
PN:7634208001-003	MOS/MSC	10-Aug-24	O/C							
SN:1722323	HRS									
	AFL									
PROC. REF: AMM 34-15-01PROC. REF: AMM 34-15-01										
341025A		TEST/INSPECT STANDBY ALTIMETER						Service	ATA:34	
PN:7634208001-003	MOS	10-Aug-24	24		10-Aug-26		76 d			
SN:1722323	HRS									
	AFL									
Calibration Date: : 10-Aug-24										
PROC. REF: FAR FAR 91.411, AMM 34-15-01, CFR 14 CFR PART 43 APP EPROC. REF: FAR FAR 91.411, AMM 34-15-01, CFR 14 CFR PART 43 APP E										
341037		LEFT PRIMARY PITOT/STATIC PROBE						Component	ATA:34	
PN:0856TJ1	MOS	17-Aug-18		TSN 0				LIFE LIMIT		
SN:308640	HRS	7915.5	15000	TSN 0	22915.5		12892.4			
	AFL	6079		TSN 0						
PROC. REF: AMM 34-11-01PROC. REF: AMM 34-11-01										
341037A		LEFT PRIMARY PITOT/STATIC PROBE - PERFORM NATIONALLY REQUIRED EQUIPMENT TESTS AND INSPECTIONS						Service	ATA:34	
PN:0856TJ1	MOS	10-Aug-24	24		10-Aug-26		76 d			
SN:308640	HRS									
	AFL									
PROC. REF: GENERIC NO REF, FAR FAR 91.411, CFR 14 CFR PART 43 APP EPROC. REF: GENERIC NO REF, FAR FAR 91.411, CFR 14 CFR PART 43 APP E										
341038		RIGHT PRIMARY PITOT/STATIC PROBE						Component	ATA:34	
PN:6634100000-003	MOS	09-Dec-24						LIFE LIMIT		
SN:276891	HRS	9574.3	15000	TSN 7559.6	17014.7		6991.6			
	AFL	7315		TSN 7118						
PROC. REF: AMM 34-11-01PROC. REF: AMM 34-11-01										
341038A		RIGHT PRIMARY PITOT/STATIC PROBE - PERFORM NATIONALLY REQUIRED EQUIPMENT TESTS AND INSPECTIONS						Service	ATA:34	
PN:6634100000-003	MOS	09-Dec-24	24		09-Dec-26		197 d			
SN:276891	HRS	9574.3								
	AFL	7315								
PROC. REF: FAR FAR 91.411, AMM 34-11-00, CFR 14 CFR PART 43 APP EPROC. REF: FAR FAR 91.411, AMM 34-11-00, CFR 14 CFR PART 43 APP E										

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 34 - NAVIGATION										
341049	STANDBY PITOT/STATIC PROBE								Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-11-01PROC. REF: AMM 34-11-01										
341049A	TEST/INSPECT STANDBY PITOT/STATIC PROBE								Service	ATA:34
	MOS	10-Aug-24	24		10-Aug-26		76 d			
	HRS									
	AFL									
PROC. REF: FAR FAR 91.411, AMM 34-11-00, CFR 14 CFR PART 43 APP EPROC. REF: FAR FAR 91.411, AMM 34-11-00, CFR 14 CFR PART 43 APP E										
341061	RADAR ALTIMETER RECEIVER								Component	ATA:34
PN:7001840-937	MOS/MSC	18-Oct-24	O/C							
SN:99118031	HRS	9555.2								
	AFL	7301								
PROC. REF: AMM 34-14-01PROC. REF: AMM 34-14-01										
341073	FORWARD RADAR ALTIMETER ANTENNA								Component	ATA:34
PN:S67-2002-4	MOS/MSC	14-Jul-07	O/C							
SN:552-14361	HRS	5618.1								
	AFL	4293								
PROC. REF: AMM 34-14-02PROC. REF: AMM 34-14-02										
341074	AFT RADAR ALTIMETER ANTENNA								Component	ATA:34
PN:S67-2002-4	MOS/MSC	14-Jul-07	O/C							
SN:552-13054	HRS	5618.1								
	AFL	4293								
PROC. REF: AMM 34-14-02PROC. REF: AMM 34-14-02										
3413-RVSM	FLIGHT CHECK ALTITUDE ALERTER FUNCTION. RVSM COMPLIANT AIRCRAFT.								Service	ATA:34
	MOS/MSC	09-Mar-01	N/R							
	HRS	0								
	AFL	0								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 34 - NAVIGATION										
341901	TOTAL AIR TEMPERATURE PROBE (TAT)								Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-17-02PROC. REF: AMM 34-17-02										
342001	NO. 1 ATTITUDE HEADING REFERENCE COMPUTER (AHRS)								Component	ATA:34
PN:145130-6000	MOS/MSC	21-Mar-22	O/C							
SN:5001	HRS	8909								
	AFL	6851								
PROC. REF: AMM 34-26-01PROC. REF: AMM 34-26-01										
342002	NO. 2 ATTITUDE HEADING REFERENCE COMPUTER (AHRS)								Component	ATA:34
PN:HG2010AC02	MOS/MSC	10-Feb-09	O/C							
SN:99031032	HRS	6104.7								
	AFL									
PROC. REF: AMM 34-26-01PROC. REF: AMM 34-26-01										
342003	NO. 1 ATTITUDE HEADING REFERENCE COMPUTER FAN (AHRS)								Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-26-03PROC. REF: AMM 34-26-03										
342004	NO. 2 ATTITUDE HEADING REFERENCE COMPUTER FAN (AHRS)								Component	ATA:34
PN:26012423-105	MOS/MSC	10-Aug-12	O/C							
SN:10396	HRS	6975.7								
	AFL	5322								
PROC. REF: AMM 34-26-03PROC. REF: AMM 34-26-03										
342037	LEFT FLUX VALVE								Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-26-02PROC. REF: AMM 34-26-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 34 - NAVIGATION										
342038		RIGHT FLUX VALVE						Component	ATA:34	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-26-02PROC. REF: AMM 34-26-02										
342101		DUAL ANGLE OF ATTACK INDICATOR						Component	ATA:34	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
342103		STANDBY COMPASS						Component	ATA:34	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-21-01PROC. REF: AMM 34-21-01										
342103A		CALIBRATION CHECK STANDBY COMPASS						Service	ATA:34	
PN:PN	MOS/MSC	09-Mar-01	A/R							
SN:UNKNOWN	HRS	0								
	AFL	0								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
342701		LEFT ATTITUDE HEADING REFERENCE SYSTEM MEMORY MODULE (AHRS)						Component	ATA:34	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-26-01PROC. REF: AMM 34-26-01										
342702		RIGHT ATTITUDE HEADING REFERENCE SYSTEM MEMORY MODULE (AHRS)						Component	ATA:34	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-26-01PROC. REF: AMM 34-26-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
342801 STANDBY ATTITUDE INDICATOR									Component ATA:34
PN:501-1648-02	MOS/MSC	12-Sep-22	O/C						
SN:1338	HRS	9101.8							
	AFL	6994							
PROC. REF: AMM 34-23-01PROC. REF: AMM 34-23-01									
343005 MARKER BEACON ANTENNA									Component ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-30-01PROC. REF: AMM 34-30-01									
343008 UPPER GLIDESCOPE ANTENNA (E11)									Component ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-30-02PROC. REF: AMM 34-30-02									
343009 LOWER GLIDESCOPE ANTENNA (E12)									Component ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-30-02PROC. REF: AMM 34-30-02									
343030 MARKER BEACON ANTENNA SPLITTER									Component ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-30-03PROC. REF: AMM 34-30-03									
344111 UPPER TCAS ANTENNA									Component ATA:34
PN:071-01548-0200	MOS/MSC	15-Oct-09	O/C						
SN:587-10110	HRS	6191.1							
	AFL								
PROC. REF: AMM 34-43-02PROC. REF: AMM 34-43-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 34 - NAVIGATION										
344112	LOWER TCAS ANTENNA								Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-43-02PROC. REF: AMM 34-43-02										
344143	TCAS PROCESSOR								Component	ATA:34
PN:066-01146-1211	MOS/MSC	06-Jan-22	O/C							
SN:41568	HRS	8821.5								
	AFL	6790								
PROC. REF: AMM 34-43-01PROC. REF: AMM 34-43-01										
344155	TCAS RELAY BOX ASSEMBLY								Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-43-03PROC. REF: AMM 34-43-03										
344167	TCAS CONFIGURATION MODULE								Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
344171	NO. 1 TCAS UPPER ANTENNA CABLE								Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
344172	NO. 2 TCAS UPPER ANTENNA CABLE								Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 34 - NAVIGATION										
344173	NO. 3 TCAS UPPER ANTENNA CABLE								Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
344174	NO. 4 TCAS UPPER ANTENNA CABLE								Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
344176	UPPER TCAS ADAPTER ASSEMBLY								Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
344177	LOWER TCAS ADAPTER ASSEMBLY								Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
344181	NO. 1 TCAS LOWER ANTENNA CABLE								Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
344182	NO. 2 TCAS LOWER ANTENNA CABLE								Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
344183 NO. 3 TCAS LOWER ANTENNA CABLE									Component ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
344184 NO. 4 TCAS LOWER ANTENNA CABLE									Component ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
344205 WEATHER RADAR RECEIVER/TRANSMITTER/ANTENNA									Component ATA:34
PN:7021450-601	MOS/MSC	11-Aug-09	O/C						
SN:07067540	HRS	6169.3							
	AFL	4725							
PROC. REF: AMM 34-42-01PROC. REF: AMM 34-42-01									
344207 WEATHER RADAR TRANSCEIVER									Component ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-42-01PROC. REF: AMM 34-42-01									
344209 WEATHER RADAR LIGHTNING SENSOR ANTENNA									Component ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
344221 WEATHER RADAR CONTROLLER									Component ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-42-02PROC. REF: AMM 34-42-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 34 - NAVIGATION										
344223	LIGHTNING DETECTION PROCESSOR								Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
344513	TERRAIN AWARENESS WARNING (TAWS) COMPUTER								Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
344514	TERRAIN AWARENESS WARNING (TAWS) CONFIGURATION MODULE								Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
344515	TAWS RELAY BOX								Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
345000A	UPDATE NAVIGATION DATA BASE								Service	ATA:34
	MOS/MSC		0 / -		?		?			
	HRS									
	AFL									
PROC. REF: GENERIC NO REF, EMP 9900052, EMP 9900053PROC. REF: GENERIC NO REF, EMP 9900052, EMP 9900053										
345001	NO. 1 INTEGRATED NAVIGATION UNIT								Component	ATA:34
PN:7510100-631	MOS/MSC	17-Feb-05	O/C							
SN:01015045	HRS	3300.2								
	AFL	2515								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 34 - NAVIGATION										
345002		NO. 2 INTEGRATED NAVIGATION UNIT						Component	ATA:34	
PN:7510100-633	MOS/MSC	17-Feb-05	O/C							
SN:99124053	HRS	3300.2								
	AFL	2515								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
<hr/>										
345011		NO. 1 NAVIGATION RECEIVER MODULE						Component	ATA:34	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
<hr/>										
345012		NO. 2 NAVIGATION RECEIVER MODULE						Component	ATA:34	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
<hr/>										
345013		NO. 1 ADF ANTENNA						Component	ATA:34	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-57-01PROC. REF: AMM 34-57-01										
<hr/>										
345014		NO. 2 ADF ANTENNA						Component	ATA:34	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-57-01PROC. REF: AMM 34-57-01										
<hr/>										
345024		GPWS CONTROL PANEL						Component	ATA:34	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
345025 ENHANCED GROUND PROXIMITY WARNING (EGPWS) COMPUTER									Component ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-45-01PROC. REF: AMM 34-45-01									
345037 FORWARD ATC ANTENNA									Component ATA:34
PN:DMNI50-2-2	MOS/MSC	16-Jul-19	O/C	TSN 0					
SN:143631	HRS	8109		TSN 0					
	AFL	6239		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
345038 AFT ATC ANTENNA									Component ATA:34
PN:DMNI50-2-2	MOS/MSC	16-Jul-19	O/C	TSN 0					
SN:143620	HRS	8109		TSN 0					
	AFL	6239		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
345049 AFT (NO. 1) DME ANTENNA									Component ATA:34
PN:DMNI50-2-2	MOS/MSC	16-Jul-19	O/C	TSN 0					
SN:143632	HRS	8109		TSN 0					
	AFL	6239		TSN 0					
PROC. REF: AMM 34-55-01PROC. REF: AMM 34-55-01									
345050 FORWARD (NO. 2) DME ANTENNA									Component ATA:34
PN:DMNI50-9-2	MOS/MSC	16-Jul-19	O/C	TSN 10					
SN:22086	HRS	8109		TSN 0					
	AFL	6239		TSN 0					
PROC. REF: AMM 34-55-01PROC. REF: AMM 34-55-01									
345083 LEFT VOR/LOCALIZER ANTENNA									Component ATA:34
PN:DMN4-17-1/N	MOS/MSC	25-Nov-19	O/C	TSN 0					
SN:21995	HRS	8177.7		TSN 0					
	AFL	6303		TSN 0					
PROC. REF: AMM 34-51-02PROC. REF: AMM 34-51-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
345084 RIGHT VOR/LOCALIZER ANTENNA									Component ATA:34
PN:DMN4-17-1/N	MOS/MSC	25-Nov-19	O/C	TSN 0					
SN:21818	HRS	8177.7		TSN 0					
	AFL	6303		TSN 0					
PROC. REF: AMM 34-51-02PROC. REF: AMM 34-51-02									
345201 NAV VHF (A42) DUPLEXER									Component ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-51-04PROC. REF: AMM 34-51-04									
345260 PHASING COUPLER									Component ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-51-03PROC. REF: AMM 34-51-03									
345501 DME INDICATOR									Component ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
345605 LEFT UPPER MODE S ATC ANTENNA									Component ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
345606 RIGHT UPPER MODE S ATC ANTENNA									Component ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 34 - NAVIGATION										
346001		PILOT FLIGHT MANAGEMENT CONTROL DISPLAY CDU						Component	ATA:34	
PN:3017-41-221	MOS/MSC	13-Apr-17	O/C							
SN:2081	HRS	7744.3								
	AFL	5922								
PROC. REF: AMM 34-60-01PROC. REF: AMM 34-60-01										
346002		COPILOT FLIGHT MANAGEMENT CONTROL DISPLAY CDU						Component	ATA:34	
PN:3017-41-221	MOS/MSC	13-Apr-17	O/C							
SN:2082	HRS	7744.3								
	AFL	5922								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
346021		FMS DATA (DTU) TRANSFER UNIT						Component	ATA:34	
PN:1408-00-1	MOS/MSC	13-Apr-17	O/C							
SN:3597	HRS	7744.3								
	AFL	5922								
PROC. REF: AMM 34-60-02PROC. REF: AMM 34-60-02										
346025		NO. 1 FLIGHT MANAGEMENT CONFIGURATION MODULE						Component	ATA:34	
PN:30171	MOS/MSC	13-Apr-17	O/C							
SN:2173	HRS	7744.3								
	AFL	5922								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
346026		NO. 2 FLIGHT MANAGEMENT CONFIGURATION MODULE						Component	ATA:34	
PN:30171	MOS/MSC	13-Apr-17	O/C							
SN:2174	HRS	7744.3								
	AFL	5922								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
346031		NO. 1 FMS ANTENNA						Component	ATA:34	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 34 - NAVIGATION										
346032	NO. 2 FMS ANTENNA								Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
<hr/>										
346090	AFIS DATA MANAGEMENT UNIT								Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
<hr/>										
347510	NO. 1 GPS ANTENNA								Component	ATA:34
PN:10708	MOS/MSC	13-Apr-17	O/C							
SN:9815	HRS	7744.3								
	AFL	5922								
PROC. REF: AMM 34-53-01PROC. REF: AMM 34-53-01										
<hr/>										
347511	NO. 2 GPS ANTENNA								Component	ATA:34
PN:10708	MOS/MSC	13-Apr-17	O/C							
SN:9814	HRS	7744.3								
	AFL	5922								
PROC. REF: AMM 34-53-01PROC. REF: AMM 34-53-01										
<hr/>										
A3400000 ^S	** NAVIGATION SYSTEMS - PERFORM OPERATIONAL CHECK								Service	ATA:34
	MOS	02-Aug-24	24					AIRWORTHINESS		
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 34-00-00PROC. REF: AMM 34-00-00										
<hr/>										
L3411062	LEFT PRIMARY PITOT/STATIC PROBE - PERFORM DETAILED VISUAL INSPECTION								Service	ATA:34
PN:0856TJ1	MOS	10-Aug-24	24		10-Aug-26		76 d			
SN:308640	HRS									
	AFL									
PROC. REF: AMM 34-11-01PROC. REF: AMM 34-11-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 34 - NAVIGATION										
M3411052	LEFT PRIMARY PITOT/STATIC PROBE - VERIFY PITCH, ROLL, AND YAW ALIGNMENT								Service	ATA:34
PN:0856TJ1	MOS	10-Aug-24	24		10-Aug-26		76 d			
SN:308640	HRS									
	AFL									
PROC. REF: AMM 34-11-01PROC. REF: AMM 34-11-01										
<hr/>										
U3411060	AIR DATA SYSTEM - PERFORM FUNCTIONAL TEST								Service	ATA:34
	MOS	10-Aug-24	24		10-Aug-26		76 d			
	HRS									
	AFL									
PROC. REF: AMM 34-17-00PROC. REF: AMM 34-17-00										
<hr/>										
V3420000 ^S	ATTITUDE HEADING REFERENCE UNIT (AHRU) MOUNTING TRAY FAN FILTER - PERFORM VISUAL INSPECTION. ENSURE FILTER IS FREE OF OBSTRUCTIONS.								Service	ATA:34
	MOS	02-Aug-24	24							
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
<hr/>										
Y3411000 ^S	PITOT-STATIC PROBES - PERFORM VISUAL INSPECTION. ENSURE DRAIN HOLES ARE CLEAR OF OBSTRUCTIONS								Service	ATA:34
	MOS	02-Aug-24	24							
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 34-11-01PROC. REF: AMM 34-11-01										
<hr/>										
Y3440000 ^S	RADOME STRUCTURE AND ANTENNA INSTALLATION - PERFORM VISUAL INSPECTION								Service	ATA:34
	MOS	09-Mar-01	48							
	HRS	0	1200							
	AFL	0								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
<hr/>										
ATA 35 - OXYGEN										
256032	COPILOTS PROTECTIVE BREATHING EQUIPMENT								Component	ATA:35
PN:119003	MOS/MSC	09-Mar-01	N/A					NOT INSTALLED		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 35 - OXYGEN									
SN:131371	HRS	0							
	AFL	0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
350001 OXYGEN CYLINDER Component ATA:35									
PN:806385-14	MOS/MSC	28-Aug-23	H/T	TSN 15					
SN:C10050116	HRS	9307.4							
	AFL	7125							
PROC. REF: AMM 35-00-01PROC. REF: AMM 35-00-01									
350013 OXYGEN CYLINDER LOW PRESSURE RELIEF VALVE Component ATA:35									
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
350201 TEMP/PRESSURE TRANSDUCER Component ATA:35									
PN:10008789	MOS/MSC	22-Jun-23	O/C						
SN:20201184	HRS	9258.5							
	AFL	7100							
PROC. REF: AMM 35-00-03PROC. REF: AMM 35-00-03									
350225 OXYGEN FILL VALVE (POST SB 45-12-1) Component ATA:35									
PN:P21010	MOS/MSC	16-Jul-19	O/C	TSN 51					
SN:7488	HRS	8109		TSN 0					
	AFL	6239		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
350230 REMOTE OXYGEN PRESSURE INDICATOR Component ATA:35									
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 35-00-05PROC. REF: AMM 35-00-05									

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 35 - OXYGEN										
351001	PILOTS OXYGEN MASK								Component	ATA:35
PN:MC10-15-166	MOS/MSC	05-Jan-26	O/C	TSO 0						
SN:SE 18288	HRS	9987.5		TSO 0						
	AFL	7596		TSO 0						
PROC. REF: AMM 35-10-01PROC. REF: AMM 35-10-01										
351002	COPILOTS OXYGEN MASK								Component	ATA:35
PN:MC10-15-166	MOS/MSC	26-Aug-24	O/C	TSO 0						
SN:111581	HRS	9529		TSO 0						
	AFL	7280		TSO 0						
351003A	INSPECTION PASSENGER OXYGEN MASK (INSPECTION) - PERFORM VISUAL INSPECTION OF 289 SERIES PAX OXYGEN MASK (REFER ZODIAC / AVOX MANUAL 833-35-01).								Service	ATA:35
	MOS	21-Aug-25	36	21-Aug-28		818 d		VENDOR RECOMMENDATION		
	HRS	9809.8								
	AFL	7471								
PROC. REF: GENERIC NO REF, SI 833-35-01PROC. REF: GENERIC NO REF, SI 833-35-01										
351005	PILOT CREW OXYGEN OUTLET								Component	ATA:35
PN:DPB181-04	MOS/MSC	24-May-07	O/C							
SN:20/06	HRS	5477.2								
	AFL	4173								
PROC. REF: AMM 35-10-01PROC. REF: AMM 35-10-01										
351006	COPILOT CREW-OXYGEN OUTLET								Component	ATA:35
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 35-10-01PROC. REF: AMM 35-10-01										
352002	ALTITUDE COMPENSATING REGULATOR								Component	ATA:35
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 35-20-06PROC. REF: AMM 35-20-06										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 35 - OXYGEN										
352011	OXYGEN CONTROL VALVE								Component	ATA:35
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 35-20-01PROC. REF: AMM 35-20-01										
<hr/>										
353001	PORTABLE OXYGEN CYLINDER								Component	ATA:35
PN:PN	MOS/MSC		O/C							
SN:UNKNOWN	HRS									
	AFL									
PROC. REF: AMM 35-00-01PROC. REF: AMM 35-00-01										
<hr/>										
355111	OXYGEN PRESSURE INDICATOR								Component	ATA:35
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 35-00-05PROC. REF: AMM 35-00-05										
<hr/>										
K3500021	** OXYGEN SYSTEM LOW PRESSURE SUPPLY HOSES - PERFORM OPERATIONAL CHECK. ENSURE THAT HOSES ARE FREE OF OBSTRUCTIONS								Service	ATA:35
	MOS/MSC	09-Mar-01	N/A							
	HRS	0								
	AFL	0								
PROC. REF: AMM 35-00-00PROC. REF: AMM 35-00-00										
<hr/>										
N3510013	** OXYGEN CYLINDER AND REMOTE OXYGEN FILL VALVES - PERFORM PERIODIC CHECK								Service	ATA:35
	MOS	27-Oct-25						AIRWORTHINESS		
	HRS	9906.2	1500	Adj 8.2	11414.4		1391.3			
	AFL	7538								
PROC. REF: AMM 35-00-01PROC. REF: AMM 35-00-01										
<hr/>										
N3510019	** OXYGEN CYLINDER AND REMOTE OXYGEN FILL VALVES - PERFORM PERIODIC CHECK								Service	ATA:35
	MOS/MSC		N/A							
	HRS									
	AFL									
PROC. REF: AMM 35-00-01PROC. REF: AMM 35-00-01										

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 35 - OXYGEN									
Q3510003^S ** CABIN LOW PRESSURE OXYGEN DISTRIBUTION FLEX HOSES - PERFORM FUNCTIONAL TEST									
	MOS	02-Aug-24	24					AIRWORTHINESS	Service ATA:35
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 35-20-00PROC. REF: AMM 35-20-00									
PKG:7									
Q3510006 COPILOTS OXYGEN MASK - E.R.O.S. CREW OXYGEN MASKS - COMPLY WITH FACTORY OVERHAUL									
PN:MC10-15-166	MOS	26-Aug-24	72		28-Jun-30		1494 d		Service ATA:35
SN:111581	HRS	9529							
	AFL	7280							
OverHaul Date:: 28-Jun-24									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
Q3510006 PILOTS OXYGEN MASK - E.R.O.S. CREW OXYGEN MASKS - COMPLY WITH FACTORY OVERHAUL									
PN:MC10-15-166	MOS	05-Jan-26	72		08-Nov-31		1992 d		Service ATA:35
SN:SE 18288	HRS	9987.5							
	AFL	7596							
OverHaul Date:: 08-Nov-25									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
Q3510007 OXYGEN CYLINDER (COMPOSITE) - SCRAP									
	MOS	09-Mar-01	180		28-May-37 (M)		4020 d	LIFE LIMIT	Service ATA:35
	HRS	0							
	AFL	0							
Q3510005 ** OXYGEN CYLINDER (COMPOSITE) AND LOW PRESSURE RELIEF VALVE - PERFORM ICC HYDROSTATIC TEST ON CYLINDER (PER DOT EXEMPTION E8162) AND FUNCTIONALLY TEST OXYGEN CYLINDER LOW PRESSURE RELIEF VALVE.									
PN:806385-14	MOS	27-Jun-23	60		27-Jun-28		763 d		Service ATA:35
SN:C10050116	HRS	9307.4	5000		14307.4		4284.3		
	AFL	7125							
HydroCheck Date: : 27-Jun-23									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 35 - OXYGEN										
Q3510018		** OXYGEN CYLINDER (COMPOSITE) AND LOW PRESSURE RELIEF VALVE - PERFORM ICC HYDROSTATIC TEST ON CYLINDER (PER DOT EXEMPTION E8162) AND FUNCTIONALLY TEST OXYGEN CYLINDER LOW PRESSURE RELIEF VALVE							Service	ATA:35
PN:806385-14	MOS	28-Aug-23	60		28-Aug-28		825 d			
SN:C10050116	HRS	9307.4	5000		14307.4		4284.3			
	AFL	7125								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
Q3510022										
Q3510022		OXYGEN CYLINDER REGULATOR - PERFORM OVERHAUL							Service	ATA:35
	MOS	22-Jun-23	60		22-Jun-28		758 d			
	HRS	9258.5	5000		14258.5		4235.4			
	AFL	7100								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
Q3510023										
Q3510023		OXYGEN CYLINDER REGULATOR - PERFORM OVERHAUL							Service	ATA:35
	MOS/MSC		N/A							
	HRS									
	AFL									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
W3510002 ^S										
W3510002 ^S		** OXYGEN SYSTEM - PERFORM OPERATIONAL CHECK							Service	ATA:35
	MOS	02-Aug-24	24					AIRWORTHINESS		
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 35-00-00PROC. REF: AMM 35-00-00										
Y3510000 ^S										
Y3510000 ^S		OXYGEN CYLINDER INSTALLATION - PERFORM VISUAL INSPECTION. CHECK PLUMBING FOR ROUTING, SECURITY, AND CONDITION.							Service	ATA:35
	MOS	09-Mar-01	48							
	HRS	0	1200							
	AFL	0								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 35 - OXYGEN

Y3510001	^S		CREW SEAT OXYGEN HOSES - PERFORM VISUAL INSPECTION. PAY PARTICULAR ATTENTION TO AREA WHERE OXYGEN HOSES ENTER CREW SEATS ABOVE COCKPIT FLOOR.					Service	ATA:35
		MOS	21-Aug-25		12				
		HRS	9809.8		300				
		AFL	7471						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:1

Y3510017	^S		OXYGEN CYLINDER INSTALLATION - PERFORM VISUAL INSPECTION. CHECK PLUMBING FOR ROUTING, SECURITY, AND CONDITION					Service	ATA:35
		MOS	02-Aug-24		24				
		HRS	9525.7		600				
		AFL	7276						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:7

ATA 36 - PNEUMATIC

361001			LEFT OUTBOARD HIGH PRESSURE TAILCONE MANIFOLD					Component	ATA:36
PN:PN		MOS/MSC	09-Mar-01	O/C	TSN 0				
SN:UNKNOWN		HRS	0		TSN 0				
		AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

361002			LEFT OUTBOARD ANTI-ICE MANIFOLD					Component	ATA:36
PN:PN		MOS/MSC	09-Mar-01	O/C	TSN 0				
SN:UNKNOWN		HRS	0		TSN 0				
		AFL	0		TSN 0				
PROC. REF: AMM 30-10-07PROC. REF: AMM 30-10-07									

361004			LEFT INBOARD HIGH-PRESSURE BLEED AIR MANIFOLD					Component	ATA:36
PN:PN		MOS/MSC	09-Mar-01	O/C	TSN 0				
SN:UNKNOWN		HRS	0		TSN 0				
		AFL	0		TSN 0				
PROC. REF: AMM 36-10-07PROC. REF: AMM 36-10-07									

361005			RIGHT INBOARD HIGH-PRESSURE BLEED AIR MANIFOLD					Component	ATA:36
PN:PN		MOS/MSC	09-Mar-01	O/C	TSN 0				
SN:UNKNOWN		HRS	0		TSN 0				
		AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 36 - PNEUMATIC

PROC. REF: AMM 36-10-07PROC. REF: AMM 36-10-07

361016 RIGHT OUTBOARD ANTI-ICE MANIFOLD						Component	ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0			
SN:UNKNOWN	HRS	0		TSN 0			
	AFL	0		TSN 0			
PROC. REF: AMM 30-10-07PROC. REF: AMM 30-10-07							

361020 LEFT HIGH PRESSURE OVER-TEMP SWITCH						Component	ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0			
SN:UNKNOWN	HRS	0		TSN 0			
	AFL	0		TSN 0			
PROC. REF: AMM 36-20-03PROC. REF: AMM 36-20-03							

361021 RIGHT HIGH PRESSURE OVER-TEMP SWITCH						Component	ATA:36
PN:641179-4	MOS/MSC	06-Jun-05	O/C				
SN:0766	HRS	3654.87					
	AFL	2759					
PROC. REF: AMM 36-20-03PROC. REF: AMM 36-20-03							

361031 ECS CONTROLLER						Component	ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0			
SN:UNKNOWN	HRS	0		TSN 0			
	AFL	0		TSN 0			
PROC. REF: AMM 36-10-01PROC. REF: AMM 36-10-01							

361040 APU BLEED AIR CHECK VALVE						Component	ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0			
SN:UNKNOWN	HRS	0		TSN 0			
	AFL	0		TSN 0			
PROC. REF: AMM 36-10-09PROC. REF: AMM 36-10-09							

361050 LOAD CONTROL SHUTOFF VALVE (L5003)						Component	ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0			
SN:UNKNOWN	HRS	0		TSN 0			
	AFL	0		TSN 0			
PROC. REF: AMM 36-10-10PROC. REF: AMM 36-10-10							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 36 - PNEUMATIC										
361053		NO. 1 ECS SHUTOFF (L37) VALVE						Component	ATA:36	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 36-10-03PROC. REF: AMM 36-10-03										
361054		NO. 2 ECS SHUTOFF (L38) VALVE						Component	ATA:36	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 36-10-03PROC. REF: AMM 36-10-03										
361065		LEFT TAILCONE HIGH PRESSURE SHUT-OFF VALVE (L39)						Component	ATA:36	
PN:3291216-2	MOS/MSC	09-Jun-05	O/C							
SN:736	HRS	3666.35								
	AFL	2768								
PROC. REF: AMM 36-10-02PROC. REF: AMM 36-10-02										
361066		RIGHT TAILCONE HIGH PRESSURE SHUT-OFF VALVE (L40)						Component	ATA:36	
PN:3291216-2	MOS/MSC	09-Jun-05	O/C							
SN:426	HRS	3666.35								
	AFL	2768								
PROC. REF: AMM 36-10-02PROC. REF: AMM 36-10-02										
361120		NO. 1 PRESSURE SWITCH (S79)						Component	ATA:36	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 36-10-06PROC. REF: AMM 36-10-06										
361121		NO. 2 PRESSURE SWITCH (S88)						Component	ATA:36	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 36-10-06PROC. REF: AMM 36-10-06										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 36 - PNEUMATIC									
361125 LEFT PYLON LOW PRESSURE TEMPERATURE SENSOR									Component ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
361126 RIGHT PYLON LOW PRESSURE TEMPERATURE SENSOR									Component ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
361127 LEFT TAILCONE LOW PRESSURE (2.0 DIAMETER) CHECK VALVE									Component ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
361128 RIGHT TAILCONE LOW PRESSURE (2.0 DIAMETER) CHECK VALVE									Component ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
361215 LEFT HIGH PRESSURE BLEED AIR MANIFOLD									Component ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
361216 RIGHT HIGH PRESSURE BLEED AIR MANIFOLD									Component ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-10-07PROC. REF: AMM 36-10-07									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 36 - PNEUMATIC									
361301 APU SERVO AIR CHECK VALVE									Component ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-15-02PROC. REF: AMM 36-15-02									
361302 NO. 1 ENGINE SERVO AIR CHECK VALVE									Component ATA:36
PN:6608295-3	MOS/MSC	30-Apr-06	O/C						
SN:2360	HRS	4466.8							
	AFL	3408							
PROC. REF: AMM 36-15-02PROC. REF: AMM 36-15-02									
361303 NO. 2 ENGINE SERVO AIR CHECK VALVE									Component ATA:36
PN:6608295-3	MOS/MSC	30-Apr-06	O/C						
SN:2308	HRS	4466.8							
	AFL	3408							
PROC. REF: AMM 36-15-02PROC. REF: AMM 36-15-02									
362005 LEFT FORWARD TAILCONE OVERHEAT THERMOSTAT SWITCH (S145)									Component ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-20-02PROC. REF: AMM 36-20-02									
362006 RIGHT FORWARD TAILCONE OVERHEAT THERMOSTAT SWITCH (S146)									Component ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-20-02PROC. REF: AMM 36-20-02									
362007 LEFT AFT TAILCONE OVERHEAT THERMOSTAT SWITCH (S147)									Component ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-20-02PROC. REF: AMM 36-20-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 36 - PNEUMATIC										
362008	RIGHT AFT TAILCONE OVERHEAT THERMOSTAT SWITCH (S148)								Component	ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 36-20-02PROC. REF: AMM 36-20-02										
364925	LEFT ECS CHECK VALVE								Component	ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 36-10-04PROC. REF: AMM 36-10-04										
364926	RIGHT ECS CHECK VALVE								Component	ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 36-10-04PROC. REF: AMM 36-10-04										
5-19-00-D3610002	BORESCOPE INSPECTION HP BLEED AIR MANIFOLD ASSEMBLY ATTACH BRACKET ASSEMBLY FOR CRACKS AT WELD.(IRN D3610002)								Service	ATA:36
	MOS/MSC	09-Mar-01	N/A							
	HRS	0								
	AFL	0								
A3610000 ^S	** BLEED AIR SYSTEM - PERFORM FUNCTIONAL TEST								Service	ATA:36
	MOS	02-Aug-24	24					AIRWORTHINESS		
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 36-10-00PROC. REF: AMM 36-10-00										
A3610001 ^S	** PYLON OVERHEAT THERMOSTAT AND ELECTRICAL SYSTEM - PERFORM FUNCTIONAL TEST								Service	ATA:36
	MOS	02-Aug-24	24					AIRWORTHINESS		
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 36-20-01PROC. REF: AMM 36-20-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 36 - PNEUMATIC									
D3610002	LEFT HIGH PRESSURE BLEED AIR MANIFOLD - PERFORM BORESCOPE INSPECTION OF ATTACH BRACKET ASSEMBLY FOR CRACKS AT WELD							Service	ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C						
SN:UNKNOWN	HRS	0							
	AFL	0							
PROC. REF: AMM 36-10-07PROC. REF: AMM 36-10-07									
D3610002	RIGHT HIGH PRESSURE BLEED AIR MANIFOLD - PERFORM BORESCOPE INSPECTION OF ATTACH BRACKET ASSEMBLY FOR CRACKS AT WELD							Service	ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C						
SN:UNKNOWN	HRS	0							
	AFL	0							
PROC. REF: AMM 36-10-07PROC. REF: AMM 36-10-07									
P3610048	LEFT HIGH PRESSURE BLEED AIR MANIFOLD - PERFORM VISUAL INSPECTION							Service	ATA:36
	MOS	06-Dec-17							
	HRS	7770.3	3000		10770.3		747.2		
	AFL								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
P3610048	RIGHT HIGH PRESSURE BLEED AIR MANIFOLD - PERFORM VISUAL INSPECTION							Service	ATA:36
	MOS	20-Jul-15							
	HRS	7535.1	3000		10535.1		512		
	AFL								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
U3610075 ^S	ECS BLEED AIR "Y" MANIFOLD - PERFORM BORESCOPE INSPECTION							Service	ATA:36
	MOS	09-Mar-01							
	HRS	0	4800						
	AFL	0							
PROC. REF: AMM 36-10-00PROC. REF: AMM 36-10-00									
Y3610061 ^S	HIGH PRESSURE BLEED AIR SHUT-OFF VALVE IN-LINE FILTER - PERFORM CLEANING PROCEDURES							Service	ATA:36
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							

PKG:25

PKG:8

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 36 - PNEUMATIC

PROC. REF: AMM 36-10-02PROC. REF: AMM 36-10-02

ATA 38 - WATER/WASTE

380001 TOILET SERVICE PANEL						Component	ATA:38
PN:9600-102	MOS/MSC	09-Apr-06	O/C				
SN:SP1116	HRS						
	AFL						
PROC. REF: AMM 38-30-05PROC. REF: AMM 38-30-05							

381009 TOILET HEATED DRAIN MAST						Component	ATA:38
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0			
SN:UNKNOWN	HRS	0		TSN 0			
	AFL	0		TSN 0			
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF							

383001 TOILET --						Component	ATA:38
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0			
SN:UNKNOWN	HRS	0		TSN 0			
	AFL	0		TSN 0			
PROC. REF: AMM 38-30-01PROC. REF: AMM 38-30-01							

383002 TOILET TIMER						Component	ATA:38
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0			
SN:UNKNOWN	HRS	0		TSN 0			
	AFL	0		TSN 0			
PROC. REF: AMM 38-30-02PROC. REF: AMM 38-30-02							

383005 TOILET WATER TANK						Component	ATA:38
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0			
SN:UNKNOWN	HRS	0		TSN 0			
	AFL	0		TSN 0			
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF							

383011 LAVATORY SINK SHUT OFF VALVE						Component	ATA:38
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0			
SN:UNKNOWN	HRS	0		TSN 0			
	AFL	0		TSN 0			

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 38 - WATER/WASTE

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

384025	TOILET PUMP								Component	ATA:38
--------	-------------	--	--	--	--	--	--	--	-----------	--------

PN:5250-11A	MOS/MSC	12-Aug-15	O/C						
SN:P8851	HRS	7535.1							
	AFL	5764							

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

384051	TOILET MACERATOR								Component	ATA:38
--------	------------------	--	--	--	--	--	--	--	-----------	--------

PN:5300-1	MOS/MSC	12-Aug-15	O/C	TSN 0					
SN:M5189	HRS	7535.1		TSN 0					
	AFL	5764		TSN 0					

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

389050	TOILET CLEAN WATER PUMP								Component	ATA:38
--------	-------------------------	--	--	--	--	--	--	--	-----------	--------

PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

ATA 49 - AIRBORNE AUXILIARY POWER

490060	APU ELECTRONIC CONTROL UNIT (ECU)								Component	ATA:49
--------	-----------------------------------	--	--	--	--	--	--	--	-----------	--------

PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					

PROC. REF: AMM 49-60-04PROC. REF: AMM 49-60-04

491011	APU MAINTENANCE CONTROL PANEL								Component	ATA:49
--------	-------------------------------	--	--	--	--	--	--	--	-----------	--------

PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					

PROC. REF: AMM 49-60-02PROC. REF: AMM 49-60-02

491020	APU COCKPIT CONTROL PANEL								Component	ATA:49
--------	---------------------------	--	--	--	--	--	--	--	-----------	--------

PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 49 - AIRBORNE AUXILIARY POWER

PROC. REF: AMM 49-60-01PROC. REF: AMM 49-60-01

494050 APU IGNITION UNIT						Component	ATA:49
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0			
SN:UNKNOWN	HRS	0		TSN 0			
	AFL	0		TSN 0			
PROC. REF: AMM 49-40-04PROC. REF: AMM 49-40-04							

495001 TAILCONE APU COOLING FAN						Component	ATA:49
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0			
SN:UNKNOWN	HRS	0		TSN 0			
	AFL	0		TSN 0			
PROC. REF: AMM 49-50-01PROC. REF: AMM 49-50-01							

495002 TAILCONE ACCESS DOOR COOLING (B30) FAN						Component	ATA:49
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0			
SN:UNKNOWN	HRS	0		TSN 0			
	AFL	0		TSN 0			
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF							

495040 APU THERMOSTAT (S175) SWITCH						Component	ATA:49
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0			
SN:UNKNOWN	HRS	0		TSN 0			
	AFL	0		TSN 0			
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF							

495041 APU THERMOSTAT (S176) SWITCH						Component	ATA:49
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0			
SN:UNKNOWN	HRS	0		TSN 0			
	AFL	0		TSN 0			
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF							

495201 STRUT SUPPORT ASSEMBLY						Component	ATA:49
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0			
SN:UNKNOWN	HRS	0		TSN 0			
	AFL	0		TSN 0			
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 49 - AIRBORNE AUXILIARY POWER										
495202	STRUT SUPPORT ASSEMBLY								Component	ATA:49
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
<hr/>										
497001	APU BITE INDICATOR								Component	ATA:49
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: GENERIC NO REF, AMM 49-70-04PROC. REF: GENERIC NO REF, AMM 49-70-04										
<hr/>										
49APU1	APU								Component	ATA:49
PN:PN	MOS/MSC	E/C								
SN:UNKNOWN	HRS									
	AFL									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
<hr/>										
H4900011 ^S	** APU GENERATOR - PERFORM OVERVOLTAGE PROTECTION CHECK								Service	ATA:49
	MOS	09-Mar-01	48			AIRWORTHINESS				
	HRS	0	1200							
	AFL	0								
PROC. REF: AMM 49-40-01PROC. REF: AMM 49-40-01										
<hr/>										
Y4900000 ^S	AUXILIARY POWER UNIT - PERFORM VISUAL INSPECTION OF EXTERNAL FIREBOX INSTALLATION AND ATTACHING COMPONENTS								Service	ATA:49
	MOS	09-Mar-01	12							
	HRS	0	300							
	AFL	0								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
<hr/>										
Y4900010 ^S	APU ENGINE FIRE EXTINGUISHER CONTAINER - CHECK CONTAINER PRESSURE GAGE FOR PROPER PRESSURE								Service	ATA:49
	MOS	09-Mar-01	12							
	HRS	0	300							
	AFL	0								
PROC. REF: AMM 26-22-00PROC. REF: AMM 26-22-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 49 - AIRBORNE AUXILIARY POWER

Y4900012 ^S		APU INLET SCREEN AND OPENING - PERFORM VISUAL INSPECTION						Service	ATA:49
	MOS	09-Mar-01	12						
	HRS	0	300						
	AFL	0							
PKG:2									
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									

Y4900013 ^S		APU EXHAUST DUCT AREA, INCLUDING FORWARD AND AFT APU EXHAUST FAIRINGS - PERFORM VISUAL INSPECTION						Service	ATA:49
	MOS	09-Mar-01	12						
	HRS	0	300						
	AFL	0							
PKG:2									
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									

ATA 52 - DOORS

521001		UPPER CABIN DOOR						Component	ATA:52
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 52-10-01PROC. REF: AMM 52-10-01									

521002		LOWER CABIN DOOR						Component	ATA:52
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 52-10-01PROC. REF: AMM 52-10-01									

521010		LOWER ENTRY DOOR FORWARD GAS DAMPER ASSEMBLY						Component	ATA:52
PN:SP21231-2	MOS/MSC	24-Jan-25	O/C	TSN 0					
SN:UNKNOWN	HRS	9595.4		TSN 0					
	AFL	7326		TSN 0					
PROC. REF: AMM 52-10-11PROC. REF: AMM 52-10-11									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 52 - DOORS										
521011	LOWER ENTRY DOOR AFT GAS DAMPER ASSEMBLY								Component	ATA:52
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 52-10-11PROC. REF: AMM 52-10-11										
522001	EMERGENCY EXIT DOOR ASSEMBLY								Component	ATA:52
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 52-20-01PROC. REF: AMM 52-20-01										
522010	EMERGENCY EXIT DOOR WINDOW								Component	ATA:52
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 52-20-06PROC. REF: AMM 52-20-06										
523001	TAILCONE BAGGAGE DOOR ASSEMBLY								Component	ATA:52
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
524001	TAILCONE ACCESS DOOR								Component	ATA:52
PN:4552405151-009	MOS/MSC	17-Feb-05	O/C	TSN 0						
SN:0316	HRS	3300.2		TSN 0						
	AFL	2515		TSN 0						
PROC. REF: AMM 52-40-02PROC. REF: AMM 52-40-02										
524010	SPPR DOOR ASSY								Component	ATA:52
PN:PN	MOS/MSC		O/C							
SN:UNKNOWN	HRS									
	AFL									
PROC. REF: AMM 52-40-03PROC. REF: AMM 52-40-03										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 52 - DOORS										
A5210009	S	* EMERGENCY EXIT DOOR RETAINERS - PERFORM VISUAL INSPECTION. INSPECT DOOR STOP FITTINGS ON EMERGENCY EXIT DOOR FRAMES IN FLANGE RADII. (F.S. 374 AND 394).							Service	ATA:52
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276							PKG:26	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
A5210012	S	* LOWER PASSENGER DOOR HINGE - PERFORM VISUAL INSPECTION. INSPECT PIANO HINGE LUGS AND FASTENERS.							Service	ATA:52
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276							PKG:26	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
A5210014	S	* UPPER PASSENGER DOOR TENSION FITTINGS - PERFORM VISUAL INSPECTION. INSPECT THE FOLLOWING: A. TENSION STUDS AT RETAINING FLANGES. B. RADII AROUND FLANGE PERIPHERY.							Service	ATA:52
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276							PKG:26	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
AA5210055	S	CABIN DOOR HANDLE RAMP ROLLER WHEEL - LUBRICATE							Service	ATA:52
	MOS	22-Jun-23	48							
	HRS	9258.5	1200							
	AFL	7100							PKG:18	
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02										
D5210015	S	* EMERGENCY EXIT DOOR - PERFORM VISUAL INSPECTION. PAY PARTICULAR ATTENTION TO FLANGES AND FASTENER HOLES OF DOOR STOP FITTINGS.							Service	ATA:52
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0							PKG:25	
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 52 - DOORS										
E5210013	^S	* UPPER AND LOWER PASSENGER DOOR LATCH ARMS AND DOOR ATTACHMENTS - PERFORM VISUAL INSPECTION							Service	ATA:52
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0		T:9600						
	AFL	0								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
PKG:25										
F5210016	^S	* UPPER PASSENGER DOOR HINGE - PERFORM VISUAL INSPECTION. INSPECT UPPER SURFACE OF HINGE FINGERS AT BASE OF LUG.							Service	ATA:52
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7		9600						
	AFL	7276								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
PKG:26										
M5240004		AVIONIC ACCESS DOORS - PERFORM AVIONICS DOOR GAP AND MISMATCH INSPECTION							Service	ATA:52
	MOS	10-Aug-24		24		10-Aug-26		76 d		
	HRS									
	AFL									
PROC. REF: AMM 52-40-01PROC. REF: AMM 52-40-01										
N5210010	^S	* LOWER PASSENGER DOOR TENSION BOLTS, BOLT RETAINERS, TENSION FITTINGS, AND DOOR ATTACHMENTS - PERFORM VISUAL INSPECTION							Service	ATA:52
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0		T:9600						
	AFL	0								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
PKG:24										
N5210011	^S	* UPPER AND LOWER PASSENGER DOOR LATCH PINS - PERFORM VISUAL INSPECTION. INSPECT BOLTS AND DOOR END RIB STRUCTURE AT LOCK PINS.							Service	ATA:52
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0		T:9600						
	AFL	0								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
PKG:24										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 52 - DOORS									
N5210017	S	* UPPER PASSENGER DOOR TENSION BOLTS, BOLT RETAINERS, TENSION FITTINGS, AND DOOR ATTACHMENTS - PERFORM VISUAL INSPECTION						Service	ATA:52
	MOS	09-Mar-01						AIRWORTHINESS	
	HRS	0	T:9600						
	AFL	0							PKG:24
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
T5210003	S	EXTERNAL LOWER PASSENGER/CREW DOOR CABLES - PERFORM VISUAL INSPECTION OF VISIBLE PORTION OF CABLES AND HANDLE AREA.						Service	ATA:52
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							PKG:18
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
Y5210000	S	AVIONICS COMPARTMENT ACCESS DOORS AND SEALS - PERFORM VISUAL INSPECTION						Service	ATA:52
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							PKG:13
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
Y5210001	S	TAILCONE ACCESS DOOR AND SEAL - PERFORM VISUAL INSPECTION OF DOOR, SEALS, AND LATCHES						Service	ATA:52
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							PKG:12
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
Y5210002	S	BAGGAGE COMPARTMENT DOOR - PERFORM VISUAL INSPECTION OF DOORS, SEALS, AND LATCHES						Service	ATA:52
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							PKG:12
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 52 - DOORS										
Y5210004	^S	UPPER AND LOWER PASSENGER/CREW DOOR - PERFORM VISUAL INSPECTION OF DOOR STRUCTURE, TENSION FITTINGS, AND HINGE AREA FOR CRACKS AND CORROSION.						Service	ATA:52	
	MOS	09-Mar-01	48							
	HRS	0	1200							
	AFL	0								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
PKG:18										
Y5210005	^S	INTERNAL LOWER PASSENGER/CREW DOOR CABLES - PERFORM VISUAL INSPECTION. REMOVE STEP SKIN TO GAIN ACCESS TO CABLES.						Service	ATA:52	
	MOS	09-Mar-01	48							
	HRS	0	1200							
	AFL	0								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
PKG:18										
Y5210006	^S	UPPER PASSENGER/CREW DOOR VENT DOOR SPRINGS - PERFORM VISUAL INSPECTION						Service	ATA:52	
	MOS	02-Aug-24	24							
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
PKG:12										
Y5210008	^S	EMERGENCY EXIT DOOR INTERNAL AND EXTERNAL HANDLE LATCHING MECHANISM. - PERFORM OPERATIONAL CHECK						Service	ATA:52	
	MOS	02-Aug-24	24							
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 52-20-07PROC. REF: AMM 52-20-07										
PKG:12										
Y5240000	^S	OXYGEN SYSTEM SERVICING DOOR AND LATCHES - PERFORM VISUAL INSPECTION FOR CONDITION AND SECURITY. CHECK DECAL FOR CONDITION AND LEGIBILITY.						Service	ATA:52	
	MOS	09-Mar-01	48							
	HRS	0	1200							
	AFL	0								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
PKG:13										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 52 - DOORS										
Y5240003 ^S	SINGLE POINT REFUELING ACCESS DOOR - PERFORM VISUAL INSPECTION								Service	ATA:52
	MOS	09-Mar-01	48							
	HRS	0	1200							
	AFL	0								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
PKG:14										
Z5210053	CABIN MAIN ENTRY DOOR HANDLE - REPLACE								Service	ATA:52
	MOS	06-Jul-21	144		06-Jul-33		2598 d			
	HRS	8631.2								
	AFL	6618	6000		12618		5002			
PROC. REF: AMM 52-10-08, AMM 52-10-13PROC. REF: AMM 52-10-08, AMM 52-10-13										
ATA 53 - FUSELAGE										
530001	FUSELAGE ASSEMBLY								Component	ATA:53
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
531044	LEFT LOWER COUPE RAIL								Component	ATA:53
PN:PN	MOS/MSC		N/A	TSN 0				NOT APPLICABLE		
SN:UNKNOWN	HRS			TSN 0						
	AFL			TSN 0						
PROC. REF: AMM 53-10-04PROC. REF: AMM 53-10-04										
531045	RIGHT LOWER COUPE RAIL								Component	ATA:53
PN:PN	MOS/MSC		N/A	TSN 0				NOT APPLICABLE		
SN:UNKNOWN	HRS			TSN 0						
	AFL			TSN 0						
5323172 EMP	* SKIN CUT-OUT FOR IRIDIUM ANTENNAS, FS 283.88 TO FS 308.39 - PERFORM EDDY CURRENT INSPECTION								Service	ATA:53
	MOS/MSC	09-Mar-01	N/A					AIRWORTHINESS		
	HRS	0								
	AFL	0								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 53 - FUSELAGE

535001	RADOME							Component	ATA:53
PN:6634408000-001	MOS/MSC	12-Dec-11	O/C	TSR 0					
SN:150	HRS	6763.5		TSR 0					
	AFL	5158		TSR 0					
PROC. REF: AMM 53-50-01PROC. REF: AMM 53-50-01									

535601	LEFT DELTA FIN							Component	ATA:53
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 53-56-01PROC. REF: AMM 53-56-01									

535602	RIGHT DELTA FIN							Component	ATA:53
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 53-56-01PROC. REF: AMM 53-56-01									

545019	NO. 1 ENGINE AFT BEAM TO FRAME ATTACHMENT BOLT							Component	ATA:53
PN:PN	MOS/MSC	09-Mar-01	H/T	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

A5310005 ^S	* FUSELAGE FUEL CELL CANTED BULKHEAD (F.S. 495) - PERFORM VISUAL INSPECTION, PAYING PARTICULAR ATTENTION TO MAIN CROSS MEMBER. INSPECT FLANGES AND ATTACHMENTS FOR CRACKING.							Service	ATA:53
	MOS	09-Mar-01					AIRWORTHINESS		
	HRS	0	T:9600						
	AFL	0							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									

PKG:25

A5310007 ^S	* AFT PRESSURE BULKHEAD BOTTOM SHEAR DIAPHRAGM - PERFORM DETAILED VISUAL INSPECTION. INSPECT BULKHEAD POST ATTACHMENT FASTENER HOLES AND CONTROL CABLE SLOT.							Service	ATA:53
	MOS	02-Aug-24					AIRWORTHINESS		
	HRS	9525.7	9600						
	AFL	7276							

PKG:26

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 53 - FUSELAGE

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

A5323022	^S	* NOSE LANDING GEAR AFT WHEELBOX CLOSING STRUCTURE (F.S. 150 TO F.S.162) - PERFORM VISUAL INSPECTION. INSPECT THE FOLLOWING: A. PANEL. B. CHANNEL STIFFENERS. C. SUPPORT ANGLE. D. ANGLE STIFFENER. E. ZEE STIFFENER						Service	ATA:53
	MOS	02-Aug-24					AIRWORTHINESS		
	HRS	9525.7	9600						
	AFL	7276							

PKG:26

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

A5323023	^S	* DRAG LINK ATTACHMENT LUG - PERFORM VISUAL INSPECTION						Service	ATA:53
	MOS	09-Mar-01					AIRWORTHINESS		
	HRS	0	T:9600						
	AFL	0							

PKG:25

PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00

A5360001	^S	DELTA FINS - WITH DELTA FINS REMOVED, VISUALLY INSPECT THE FOLLOWING: A. DELTA FIN AFT SPAR. B. DELTA FIN SUPPORT ANGLE. C. INSPECT STIFFENERS CONNECTING TO ATTACH FITTINGS.						Service	ATA:53
	MOS	02-Aug-24							
	HRS	9525.7	9600						
	AFL	7276							

PKG:26

PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00

D5323039	^S	* MACHINED FUSELAGE FRAME AT FS 466 - PERFORM DETAILED VISUAL INSPECTION BETWEEN STRINGER 13 LEFT AND RIGHT, PAYING PARTICULAR ATTENTION TO THE BL 10 SPLICES. CONFIRM ANY CRACK INDICATIONS WITH EDDY CURRENT PROCEDURES.						Service	ATA:53
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							

PKG:25

PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00

E5310001	^S	* LONGERON, INTERNAL (BETWEEN FS 384 AND FS 433) - PERFORM VISUAL INSPECTION						Service	ATA:53
	MOS	02-Aug-24					AIRWORTHINESS		
	HRS	9525.7	9600						
	AFL	7276							

PKG:26

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 53 - FUSELAGE

E5310002	S		* FLIGHT DECK LONGERON - PERFORM VISUAL INSPECTION (FS 149 - FS 196). INSPECT FLIGHT DECK LONGERON STIFFENERS, WEBS, AND CUTOUTS					Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							

PKG:26

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

E5310017	S		* AFT PRESSURE BULKHEAD BOTTOM CROSSMEMBER (FS 457) - PERFORM DETAILED VISUAL INSPECTION. INSPECT TEE-SECTION AT FS 457 FLANGE AT ATTACHMENT OF PRESSURE FLOOR.					Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							

PKG:26

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

E5310018	S		* AFT PRESSURE BULKHEAD PANEL FACING SHEETS (FS 457) - PERFORM VISUAL INSPECTION. INSPECT BOTH FRONT AND AFT OF FACING SHEETS.					Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							

PKG:26

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

E5323025	S		* FORWARD/AFT WHEELBOX JOINT (FS 150) - PERFORM VISUAL INSPECTION. INSPECT SPLICE STRAP AFT OF FORWARD PRESSURE BULKHEAD AT INTERSECTION OF ATTACHMENT ANGLE AND FLIGHT DECK LONGERON.					Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							

PKG:26

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

E5323050	S		* AFT POST/WINDSHIELD RETAINER ATTACHMENT - PERFORM EDDY CURRENT INSPECTION. INSPECT WINDSHIELD AFT POST AT WINDSHIELD RETAINER FASTENER HOLES.					Service	ATA:53
	MOS	09-Mar-01						AIRWORTHINESS	
	HRS	0	T:9600						
	AFL	0							

PKG:25

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 53 - FUSELAGE

PROC. REF: NDT PART 6/53-30-04PROC. REF: NDT PART 6/53-30-04

E5323053	^S	* FRAME ATTACHMENTS TO UPPER AND LOWER COUPE RAILS (FS 171 TO FS 204) - PERFORM VISUAL INSPECTION. INSPECT THE FOLLOWING: A. FRAME ATTACHMENTS TO LOWER COUPE RAILS AT FS 171, FS 182, FS 196, AND FS 204. B. FRAME ATTACHMENTS TO UPPER COUPE RAILS AT FS 196 AND FS 204. C. GUSSETS AT FASTENER HOLES.						Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:26

E5323054	^S	* TIE-ROD ASSEMBLY (FS 162) (ALUMINUM ENDS) - PERFORM VISUAL INSPECTION. INSPECT TIE-ROD ENDS, TIE-ROD TUBES, AND TIE-ROD BOLTS.						Service	ATA:53
	MOS	09-Mar-01						AIRWORTHINESS	
	HRS	0	4800						
	AFL	0							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:25

E5323055	^S	* TIE-ROD ASSEMBLY (FS 162) (TITANIUM ENDS) - PERFORM VISUAL INSPECTION. INSPECT TIE-ROD ENDS, TIE-ROD TUBES, AND TIE-ROD BOLTS.						Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:26

E5323068	^S	* STRINGER 1RH BETWEEN F.S. 533 AND F.S. 543 - PERFORM VISUAL INSPECTION. INSPECT STRINGER 1 FLANGE AND SKIN ALONG STRINGER 1 BETWEEN F.S. 533 AND F.S. 543.						Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:26

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 53 - FUSELAGE										
E5323073 ^S		* FUSELAGE BOTTOM SKIN PANEL - PERFORM VISUAL INSPECTION. INSPECT CORNER RADIUS AT JUNCTION OF EXTERNAL LONGERON AND MID SPAR FRAME (F.S. 435).							Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								
PKG:26										
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
<hr/>										
E5323074 ^S		* AUXILIARY SKIN PANEL - PERFORM VISUAL INSPECTION. INSPECT CORNER RADIUS AT JUNCTION OF KEEL BEAM AND REAR SPAR FRAME (F.S. 466).							Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								
PKG:26										
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
<hr/>										
E5350000 ^S		* BOTTOM KEEL BEAM END PADS (F.S. 384 - F.S. 486) - PERFORM VISUAL INSPECTION. INSPECT END PADS AROUND BOLT HOLES AND IN RADII AT F.S. 433.							Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								
PKG:26										
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
<hr/>										
F5323056 ^S		* TIE-ROD FORK ENDS (ALUMINUM) - PERFORM FLUORESCENT PENETRANT INSPECTION							Service	ATA:53
	MOS/MSC	09-Mar-01	N/A					NOT APPLICABLE		
	HRS	0								
	AFL	0								
PKG:25										
PROC. REF: NDT PART 8/53-10-01PROC. REF: NDT PART 8/53-10-01										
<hr/>										
F5323081 ^S		* TIE-ROD FORK ENDS - PERFORM FLUORESCENT PENETRANT INSPECTION							Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								
PKG:26										
PROC. REF: NDT PART 8/53-10-01PROC. REF: NDT PART 8/53-10-01										

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 53 - FUSELAGE										
F5331021	S	* FORWARD CANTED BULKHEAD (F.S. 630) - PERFORM VISUAL INSPECTION. INSPECT AT FRONT SPAR UPPER ATTACHMENT FASTENERS.						Service	ATA:53	
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0							PKG:25	
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
F5331022	S	* MID CANTED BULKHEAD (F.S. 657) - PERFORM VISUAL INSPECTION AT MID SPAR UPPER ATTACHMENT FASTENERS						Service	ATA:53	
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276							PKG:26	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
F5331023	S	* AFT CANTED BULKHEAD (F.S. 682) - PERFORM VISUAL INSPECTION. INSPECT AT REAR SPAR ATTACHMENT FASTENERS.						Service	ATA:53	
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276							PKG:26	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
F5331024	S	* VERTICAL STABILIZER FRONT SPAR ROOT BULKHEAD ATTACHMENT (F.S. 630) - PERFORM VISUAL INSPECTION. INSPECT FRONT SPAR ROOT BULKHEAD ATTACHMENT AT FASTENER HOLES.						Service	ATA:53	
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276							PKG:26	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
F5331025	S	* VERTICAL STABILIZER MID SPAR ROOT BULKHEAD ATTACHMENT (F.S. 657) - PERFORM VISUAL INSPECTION. INSPECT MID SPAR ROOT BULKHEAD ATTACHMENT AT FASTENER HOLES.						Service	ATA:53	
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276							PKG:26	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 53 - FUSELAGE

F5331026 ^S			* VERTICAL STABILIZER REAR SPAR ROOT BULKHEAD ATTACHMENT (F.S. 682) - PERFORM VISUAL INSPECTION. INSPECT REAR SPAR ROOT BULKHEAD ATTACHMENT AT FASTENER HOLES.					Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							

PKG:26

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

H5323032			* EXTERIOR CABIN WINDOW COAMINGS (UNPAINTED) - PERFORM EDDY CURRENT INSPECTION					Service	ATA:53
	MOS	11-Mar-25	24		11-Mar-27		289 d	AIRWORTHINESS	
	HRS	9645.6	2400		12045.6		2022.5		
	AFL	7359							

PROC. REF: NDT PART 6/56-20-01PROC. REF: NDT PART 6/56-20-01

H5323092			* EXTERIOR CABIN WINDOW COAMINGS (PAINTED) - PERFORM EDDY CURRENT INSPECTION					Service	ATA:53
	MOS/MSC	30-Apr-06	N/A						
	HRS	4466.8							
	AFL	3408							

PROC. REF: NDT PART 6/56-20-01PROC. REF: NDT PART 6/56-20-01

M5313001			FORWARD FUSELAGE SKIN - PERFORM PITOT-STATIC PROBE ZONE SKIN CONTOUR CHECK					Service	ATA:53
	MOS	10-Aug-24	24		10-Aug-26		76 d		
	HRS								
	AFL								

PROC. REF: AMM 53-00-01PROC. REF: AMM 53-00-01

M5323021 ^S			* EXTERNAL LONGERON, FASTENER LOCATIONS, AND AREA AROUND WING ATTACHMENTS - PERFORM VISUAL INSPECTION. INSPECT LONGERON BETWEEN FS 398 AND FS 486, STRINGER 13 LEFT AND RIGHT					Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							

PKG:26

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 53 - FUSELAGE										
M5323034 ^S			* UPPER AND LOWER COUPE RAIL AND CENTER POST/WINDSHIELD RETAINER ATTACHMENT - PERFORM EDDY CURRENT INSPECTION						Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								
PROC. REF: NDT PART 6/53-30-03PROC. REF: NDT PART 6/53-30-03										
PKG:26										
N5314000 ^S			* EMERGENCY EXIT DOOR SKIN CUTOUT CORNERS AND DOUBLERS (F.S. 370 - F.S. 398) - PERFORM EDDY CURRENT INSPECTION						Service	ATA:53
	MOS	25-Nov-19	96					AIRWORTHINESS		
	HRS	8177.7	2400							
	AFL	6303								
PROC. REF: NDT PART 6/53-30-01PROC. REF: NDT PART 6/53-30-01										
PKG:19										
N5323026 ^S			* UPPER AND LOWER PASSENGER/CREW DOOR SKIN CUTOUT CORNERS (FS 224 - FS 256) - PERFORM EDDY CURRENT INSPECTION. INSPECT SKIN AT CORNERS OF PASSENGER/ CREW DOOR CUTOUT.						Service	ATA:53
	MOS	25-Nov-19	96					AIRWORTHINESS		
	HRS	8177.7	2400							
	AFL	6303								
PROC. REF: NDT PART 6/53-30-02PROC. REF: NDT PART 6/53-30-02										
PKG:19										
P5310003 ^S			* AFT PRESSURE BULKHEAD SUPPORT POST (FS 457) - PERFORM EDDY CURRENT INSPECTION						Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								
PROC. REF: NDT PART 6/53-30-18PROC. REF: NDT PART 6/53-30-18										
PKG:26										
P5310004 ^S			* AFT PRESSURE BULKHEAD FRAME PERIPHERY - PERFORM EDDY CURRENT INSPECTION						Service	ATA:53
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0								
PROC. REF: NDT PART 6/53-30-21PROC. REF: NDT PART 6/53-30-21										
PKG:25										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 53 - FUSELAGE										
P5310006	^S	* FORWARD PRESSURE BULKHEAD - PERFORM EDDY CURRENT INSPECTION							Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								
PROC. REF: NDT PART 6/53-30-07PROC. REF: NDT PART 6/53-30-07										
ATA 53 - FUSELAGE										
P5320001	^S	* FUSELAGE PRESSURE FLOOR STEP (FS 433 - FS 457) - PERFORM EDDY CURRENT INSPECTION							Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								
PROC. REF: NDT PART 6/53-20-01PROC. REF: NDT PART 6/53-20-01										
ATA 53 - FUSELAGE										
P5323024	^S	* FUSELAGE SKIN CUT-OUTS ABOVE FUEL CELL - PERFORM EDDY CURRENT INSPECTION							Service	ATA:53
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0								
PROC. REF: NDT PART 6/53-30-12PROC. REF: NDT PART 6/53-30-12										
ATA 53 - FUSELAGE										
P5323027	^S	* FUSELAGE FRAME AT FS 412 - PERFORM EDDY CURRENT INSPECTION							Service	ATA:53
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0								
PROC. REF: NDT PART 6/53-30-20PROC. REF: NDT PART 6/53-30-20										
ATA 53 - FUSELAGE										
P5323029	^S	* MACHINED SPAR FRAMES SYSTEMS CUTOUTS (FS 398, FS 412, FS 432, FS 466) - PERFORM EDDY CURRENT INSPECTION							Service	ATA:53
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0								
PROC. REF: NDT PART 6/53-30-15PROC. REF: NDT PART 6/53-30-15										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 53 - FUSELAGE										
P5323033 ^S			* FUSELAGE SKIN AT EMERGENCY DOOR EGRESS-LIGHT AND WING INSPECTION LIGHT - PERFORM EDDY CURRENT INSPECTION						Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								
PROC. REF: NDT PART 6/53-40-02PROC. REF: NDT PART 6/53-40-02										
P5323037 ^S										
			* WINDSHIELD COUPE RAIL TIE ROD BRACKET - PERFORM EDDY CURRENT INSPECTION						Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								
PROC. REF: NDT PART 6/53-30-09PROC. REF: NDT PART 6/53-30-09										
P5323038 ^S										
			* WINDSHIELD CENTER POST TO UPPER COUPE RAIL JOINT ATTACHMENT - PERFORM EDDY CURRENT INSPECTION						Service	ATA:53
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0								
PROC. REF: NDT PART 6/53-30-22PROC. REF: NDT PART 6/53-30-22										
P5323047 ^S										
			* PRESSURE CABIN FUSELAGE CROWN SKIN - PERFORM EDDY CURRENT INSPECTION						Service	ATA:53
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0								
PROC. REF: NDT PART 6/53-10-04PROC. REF: NDT PART 6/53-10-04										
P5323049 ^S										
			* FUSELAGE SKIN AT UPPER AND LOWER COUPE RAIL RUN-OUT JOINTS - PERFORM EDDY CURRENT INSPECTION						Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								
PROC. REF: NDT PART 6/53-30-11PROC. REF: NDT PART 6/53-30-11										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty		
ATA 53 - FUSELAGE											
P5323057 ^S			* PRESSURE CABIN SKIN AT FUSELAGE STATION 451 - PERFORM EDDY CURRENT INSPECTION							Service	ATA:53
	MOS	09-Mar-01						AIRWORTHINESS			
	HRS	0		T:9600							
	AFL	0									
PROC. REF: NDT PART 6/53-30-06PROC. REF: NDT PART 6/53-30-06											
PKG:19											
P5323058 ^S			* FUSELAGE SKIN AT F.S. 504 - PERFORM EDDY CURRENT INSPECTION							Service	ATA:53
	MOS	09-Mar-01						AIRWORTHINESS			
	HRS	0		T:9600							
	AFL	0									
PROC. REF: NDT PART 6/53-30-13PROC. REF: NDT PART 6/53-30-13											
PKG:25											
P5323069 ^S			* CIRCUMFERENTIAL SKIN JOINT AT FORWARD PRESSURE BULKHEAD - PERFORM EDDY CURRENT INSPECTION							Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS			
	HRS	9525.7		9600							
	AFL	7276									
PROC. REF: NDT PART 6/53-30-08PROC. REF: NDT PART 6/53-30-08											
PKG:26											
P5323164 ^S			* PERFORM FUSELAGE SKIN AND DOUBLER AROUND ECS DUCT CUTOUT - EDDY CURRENT INSPECTION.							Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS			
	HRS	9525.7		9600							
	AFL	7276									
PROC. REF: NDT PART 6/53-40-01PROC. REF: NDT PART 6/53-40-01											
PKG:26											
P5323165 ^S			* WINDSHIELD CENTER POST TO LOWER COUPE RAIL JOINT ATTACHMENT - PERFORM EDDY CURRENT INSPECTION							Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS			
	HRS	9525.7		9600							
	AFL	7276									
PROC. REF: NDT PART 6/53-30-10PROC. REF: NDT PART 6/53-30-10											
PKG:26											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 53 - FUSELAGE										
P5360006 ^S			DELTA FIN ATTACH BOLT - PERFORM LIQUID PENETRANT INSPECTION						Service	ATA:53
	MOS	02-Aug-24								
	HRS	9525.7	9600							
	AFL	7276								
PROC. REF: NDT PART 8/53-10-02PROC. REF: NDT PART 8/53-10-02										
PKG:26										
Q5310023 ^S			FORWARD AND AFT FUEL CELL BAY STRUCTURE, ANGLE REINFORCEMENT, STRINGER 1, LEFT AND RIGHT - PERFORM DETAILED VISUAL INSPECTION OF HI-LITE COLLARS						Service	ATA:53
	MOS	02-Aug-24								
	HRS	9525.7	9600							
	AFL	7276								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
PKG:26										
Q5310025 ^S			AFT FUSELAGE KEELBEAM LONGERON (LEFT AND RIGHT, BL 5.15, FS 466.30 - 495.12) AND AFT FUSELAGE KEELBEAM LOWER FRAME (FS 466.30, BL 9.55 LEFT THROUGH BL 9.55 RIGHT) - PERFORM DETAILED VISUAL INSPECTION OF HI-LITE COLLARS.						Service	ATA:53
	MOS	02-Aug-24								
	HRS	9525.7	9600							
	AFL	7276								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
PKG:26										
Q5323048 ^S			* FUSELAGE (PRESSURE CABIN) - PERFORM EDDY CURRENT INSPECTION INSPECT PRESSURE CABIN SKIN (LONGITUDINAL SKIN CRACKING)						Service	ATA:53
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0								
PROC. REF: NDT PART 6/53-30-05PROC. REF: NDT PART 6/53-30-05										
PKG:25										
Q5323051 ^S			* LONGITUDINAL JOINTS INSIDE PRESSURE CABIN (FS 220 - FS 457) AND SKIN WITHIN ONE STRINGER BAY OF JOINT - PERFORM EDDY CURRENT INSPECTION. INSPECT SKIN FASTENER HOLES ALONG JOINTS AT STRINGER 10 LEFT AND RH, STRINGER 2 RIGHT, AND STRINGER 18 RIGHT						Service	ATA:53
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0								
PROC. REF: NDT PART 6/53-30-05PROC. REF: NDT PART 6/53-30-05										
PKG:25										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 53 - FUSELAGE										
Q5323059 ^S			* STRINGER TO FRAME JOINTS (FS 162 TO FS 213) - PERFORM EDDY CURRENT INSPECTION. INSPECT SKIN, STRINGERS, AND FRAMES AT JOINTS.						Service	ATA:53
	MOS		02-Aug-24					AIRWORTHINESS		
	HRS		9525.7	9600						
	AFL		7276							
PROC. REF: NDT PART 6/53-30-05PROC. REF: NDT PART 6/53-30-05										
PKG:26										
T5310027 ^S			* AFT PRESSURE BULKHEAD TOP MOUNTING STRUCTURE - PERFORM EDDY CURRENT INSPECTION.						Service	ATA:53
	MOS		02-Aug-24					AIRWORTHINESS		
	HRS		9525.7	9600						
	AFL		7276							
PROC. REF: NDT PART 6/53-30-17PROC. REF: NDT PART 6/53-30-17										
PKG:26										
T5321089 ^S			SEAT RAILS - PERFORM DETAILED INSPECTION OF SEAT RAIL (TRACK) SHEAR WEBS FOR CRACKING						Service	ATA:53
	MOS		02-Aug-24	24						
	HRS		9525.7	600						
	AFL		7276							
PROC. REF: AMM 53-20-01PROC. REF: AMM 53-20-01										
PKG:7										
T5323028 ^S			* FUSELAGE TO WING ATTACH FITTINGS - PERFORM EDDY CURRENT INSPECTION						Service	ATA:53
	MOS		09-Mar-01					AIRWORTHINESS		
	HRS		0	T:9600						
	AFL		0							
PROC. REF: NDT PART 6/53-30-16PROC. REF: NDT PART 6/53-30-16										
PKG:25										
T5323166			* EXTERNAL SKIN CUT-OUTS/PENETRATIONS (PRESSURE CABIN) - PERFORM DETAILED VISUAL INSPECTION. INSPECT SKIN AND DOUBLERS AT ANTENNAS, ELECTRICAL COMPONENTS, AND ACCESS PANELS (EXCLUDING PITOT/STATIC PROBES, AOA STALL VANES, AND WING INSPECTION LIGHT).						Service	ATA:53
	MOS		02-Aug-24	144	02-Aug-36		3721 d	AIRWORTHINESS		
	HRS		9525.7	9600	19125.7		9102.6			
	AFL		7276							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
V5323168	* LOWER COUPE RAIL RADIUS/WINDSCREEN RETAINER ATTACH - PERFORM EDDY CURRENT INSPECTION							Service	ATA:53
	MOS	22-Jun-23						AIRWORTHINESS	
	HRS	9258.5	5000		14258.5		4235.4		
	AFL	7100							
PROC. REF: NDT PART 6/53-30-23, NDT PART 6/53-30-24PROC. REF: NDT PART 6/53-30-23, NDT PART 6/53-30-24									
Y5311001 ^S	NOSE LANDING GEAR ACTUATOR ATTACH FITTING AND SURROUNDING STRUCTURE - PERFORM VISUAL INSPECTION							Service	ATA:53
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
Y5311003 ^S	NOSE LANDING GEAR TRUNNION FITTING AND SURROUNDING STRUCTURE - PERFORM VISUAL INSPECTION							Service	ATA:53
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 05-10-00PKG:17									
Y5320000 ^S	CENTER PEDESTAL - PERFORM VISUAL INSPECTION							Service	ATA:53
	MOS	21-Aug-25	12						
	HRS	9809.8	300						
	AFL	7471							
PROC. REF: AMM 05-10-00PKG:1									
Y5321010 ^S	FLOORBOARDS AROUND GALLEY, LAVATORY, AND WATER TANK - PERFORM VISUAL INSPECTION							Service	ATA:53
	MOS	21-Aug-25	12						
	HRS	9809.8	300						
	AFL	7471							
PROC. REF: AMM 53-20-01PKG:1									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 53 - FUSELAGE										
Y5321011	S	TAILCONE BAGGAGE COMPARTMENT - PERFORM VISUAL INSPECTION						Service	ATA:53	
	MOS	02-Aug-24	24							
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
PKG:8										
Y5321088	S	SEAT RAILS - REMOVE FLOORBOARD 230AL AND PERFORM VISUAL INSPECTION OF SEAT RAILS.						Service	ATA:53	
	MOS	09-Mar-01	48							
	HRS	0	1200							
	AFL	0								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
PKG:13										
Y5323020	S	EXTERNAL FUSELAGE (PRESSURE CABIN) - PERFORM VISUAL INSPECTION OF ALL CABIN SKINS FROM F.S. 100 TO F.S.458. PAY PARTICULAR ATTENTION TO ALL CUTOUTS AND SKIN JOINTS. NO FAIRING ACCESS REQUIRED.						Service	ATA:53	
	MOS	09-Mar-01	48							
	HRS	0	1200							
	AFL	0								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
PKG:13										
Y5323031	S	EXTERIOR CABIN WINDOW COAMINGS AND SURROUNDING FUSELAGE SKIN - PERFORM VISUAL INSPECTION USING 10X MAGNIFICATION AND ADEQUATE LIGHTING.						Service	ATA:53	
	MOS	09-Mar-01	48							
	HRS	0	1200							
	AFL	0								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
PKG:13										
Y5340007	S	WING ATTACH FITTINGS - PERFORM VISUAL INSPECTION						Service	ATA:53	
	MOS	25-Nov-19	96							
	HRS	8177.7	2400							
	AFL	6303								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
PKG:19										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 53 - FUSELAGE

Y5360000 ^S		DELTA FINS - PERFORM VISUAL INSPECTION						Service	ATA:53
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PKG:8									
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									

ATA 54 - NACELLES/PYLONS

545020		NO. 2 ENGINE AFT BEAM TO FRAME ATTACHMENT BOLT						Component	ATA:54
PN:PN	MOS/MSC	09-Mar-01	H/T	TSN	0				
SN:UNKNOWN	HRS	0		TSN	0				
	AFL	0		TSN	0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

545021		NO. 1 ENGINE AFT MOUNT TO END FITTING ATTACH BOLT						Component	ATA:54
PN:PN	MOS/MSC	09-Mar-01	H/T	TSN	0				
SN:UNKNOWN	HRS	0		TSN	0				
	AFL	0		TSN	0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

545022		NO. 2 ENGINE AFT MOUNT TO END FITTING ATTACH BOLT						Component	ATA:54
PN:PN	MOS/MSC	09-Mar-01	H/T	TSN	0				
SN:UNKNOWN	HRS	0		TSN	0				
	AFL	0		TSN	0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

545023		NO. 1 ENGINE TO AFT ENGINE MOUNT ATTACH BOLTS						Component	ATA:54
PN:PN	MOS/MSC	09-Mar-01	H/T	TSN	0				
SN:UNKNOWN	HRS	0		TSN	0				
	AFL	0		TSN	0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

545024		NO. 2 ENGINE TO AFT ENGINE MOUNT ATTACH BOLTS						Component	ATA:54
PN:PN	MOS/MSC	09-Mar-01	H/T	TSN	0				
SN:UNKNOWN	HRS	0		TSN	0				
	AFL	0		TSN	0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 54 - NACELLES/PYLONS										
A5450022	* NO. 1 ENGINE AFT MOUNT TO END FITTING ATTACH BOLT - REPLACE OR PERFORM MAGNETIC PARTICLE INSPECTION								Service	ATA:54
	MOS	26-Jul-23						LIFE LIMIT		
	HRS	9278	9600		10770.3 (M)		747.2			
	AFL	7111								
A5450022	* NO. 2 ENGINE AFT MOUNT TO END FITTING ATTACH BOLT - REPLACE OR PERFORM MAGNETIC PARTICLE INSPECTION								Service	ATA:54
	MOS	26-Jul-23						LIFE LIMIT		
	HRS	9278	9600		10535.1 (M)		512			
	AFL	7111								
A5450026 ^S	* ENGINE DRAG STRUT - PERFORM EDDY CURRENT INSPECTION								Service	ATA:54
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0								
PROC. REF: NDT PART 6/54-50-01PROC. REF: NDT PART 6/54-50-01										
A5450028	NO. 1 ENGINE AFT ENGINE BEAM END FITTING - REPLACE								Service	ATA:54
	MOS/MSC	09-Mar-01	N/A					N/A BY SERIAL NUMBER		
	HRS	0								
	AFL	0								
PROC. REF: AMM 53-40-02PROC. REF: AMM 53-40-02										
AB5450054	LEFT FORWARD ENGINE BEAM AND BEAM FITTING - PERFORM VISUAL INSPECTION, PAYING PARTICULAR ATTENTION OF THE FOLLOWING: A. UPPER CAPPING PLATE AT FASTENER HOLES, AND CHANNEL FLANGE AT FASTENER HOLES. B. BOLT HOLES, ESPECIALLY UPPER BOLT HOLE ON AFT FLANGE.								Service	ATA:54
	MOS	26-Jul-23								
	HRS	9278	6000		15278		5254.9			
	AFL	7111								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 54 - NACELLES/PYLONS										
AB5450054			RIGHT FORWARD ENGINE BEAM AND BEAM FITTING - PERFORM VISUAL INSPECTION, PAYING PARTICULAR ATTENTION OF THE FOLLOWING: A. UPPER CAPPING PLATE AT FASTENER HOLES, AND CHANNEL FLANGE AT FASTENER HOLES. B. BOLT HOLES, ESPECIALLY UPPER BOLT HOLE ON AFT FLANGE.						Service	ATA:54
	MOS	26-Jul-23								
	HRS	9278	6000		15278		5254.9			
	AFL	7111								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
E5450029 ^S			* AFT ENGINE BEAM - PERFORM VISUAL INSPECTION INSPECT UPPER CAPPING PLATE, AROUND FASTENER HOLES IN THE CAPPING PLATE, AND CHANNEL FLANGE.						Service	ATA:54
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0							PKG:25	
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
F5450019 ^S			* AFT ENGINE BEAM ATTACHMENT TO FRAMES - PERFORM VISUAL INSPECTION. INSPECT AFT ENGINE BEAM ATTACHMENT TO FRAMES.						Service	ATA:54
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0							PKG:25	
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
H5450012 ^S			* FRAMES 39/40 (F.S. 512/518) AT ENGINE BEAM ATTACHMENT - PERFORM EDDY CURRENT INSPECTION. INSPECT OUTER FLANGE AND FRAME WEB AT ENGINE BEAM ATTACHMENT.						Service	ATA:54
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0							PKG:25	
PROC. REF: NDT PART 6/54-50-03PROC. REF: NDT PART 6/54-50-03										
M5450015 ^S			* FORWARD ENGINE BEAM, SPAR CAP, AND WEB - PERFORM EDDY CURRENT INSPECTION						Service	ATA:54
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0							PKG:25	
PROC. REF: NDT PART 6/54-50-05PROC. REF: NDT PART 6/54-50-05										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 54 - NACELLES/PYLONS										
M5450018 ^S	* FORWARD ENGINE MOUNT ATTACHMENT BOLTS - PERFORM FLUORESCENT LIQUID PENETRANT INSPECTION								Service	ATA:54
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0								
PROC. REF: NDT PART 8/71-20-01PROC. REF: NDT PART 8/71-20-01										
M5450027	NO. 1 ENGINE FORWARD ENGINE BEAM END FITTING - REPLACE								Service	ATA:54
	MOS/MSC	09-Mar-01	N/A							
	HRS	0								
	AFL	0								
P5450011 ^S	* DRAG STRUT ATTACHMENT FITTINGS - PERFORM EDDY CURRENT INSPECTION								Service	ATA:54
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0								
PROC. REF: NDT PART 6/53-10-03PROC. REF: NDT PART 6/53-10-03										
P5450016 ^S	* FORWARD ENGINE BEAM END FITTING - PERFORM EDDY CURRENT INSPECTION								Service	ATA:54
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0								
PROC. REF: NDT PART 6/54-50-02PROC. REF: NDT PART 6/54-50-02										
P5450017 ^S	* FORWARD ENGINE BEAM TO FRAME ATTACH BOLT - PERFORM LIQUID PENETRANT INSPECTION								Service	ATA:54
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0								
PROC. REF: NDT PART 8/53-40-01PROC. REF: NDT PART 8/53-40-01										
P5450020	* NO. 1 ENGINE AFT BEAM TO FRAME ATTACHMENT BOLT - REPLACE OR PERFORM LIQUID PENETRANT INSPECTION								Service	ATA:54
	MOS	26-Jul-23						LIFE LIMIT		
	HRS	9278	9600		10770.3 (M)		747.2			
	AFL	7111								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 54 - NACELLES/PYLONS

P5450020	* NO. 2 ENGINE AFT BEAM TO FRAME ATTACHMENT BOLT - REPLACE OR PERFORM LIQUID PENETRANT INSPECTION								Service	ATA:54
	MOS	26-Jul-23						LIFE LIMIT		
	HRS	9278	9600		10535.1 (M)		512			
	AFL	7111								

P5450021 ^S	* ENGINE AFT ISOLATOR MOUNT FITTINGS - PERFORM LIQUID PENETRANT INSPECTION								Service	ATA:54
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0								

PKG:25

PROC. REF: NDT PART 8/71-20-03PROC. REF: NDT PART 8/71-20-03

P5450023	* NO. 1 ENGINE TO AFT ENGINE MOUNT ATTACH BOLTS - REPLACE OR PERFORM LIQUID PENETRANT INSPECTION								Service	ATA:54
	MOS	26-Jul-23						LIFE LIMIT		
	HRS	9278	9600		10770.3 (M)		747.2			
	AFL	7111								

P5450023	* NO. 2 ENGINE TO AFT ENGINE MOUNT ATTACH BOLTS - REPLACE OR PERFORM LIQUID PENETRANT INSPECTION								Service	ATA:54
	MOS	26-Jul-23						LIFE LIMIT		
	HRS	9278	9600		10535.1 (M)		512			
	AFL	7111								

P5450024 ^S	* FUSELAGE FRAMES AT FS 543.55 AND 546.15 TO AFT ENGINE BEAM ATTACHMENT - PERFORM EDDY CURRENT INSPECTION.								Service	ATA:54
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0								

PKG:25

PROC. REF: NDT PART 6/53-30-14PROC. REF: NDT PART 6/53-30-14

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 54 - NACELLES/PYLONS

P5450025	S		* FORWARD ENGINE BEAM AND FRAMES AT ATTACH HOLES - PERFORM EDDY CURRENT INSPECTION					Service	ATA:54
	MOS	09-Mar-01						AIRWORTHINESS	
	HRS	0	T:9600						
	AFL	0							
PROC. REF: NDT PART 6/54-50-03PROC. REF: NDT PART 6/54-50-03									

PKG:25

P5450030	S		* AFT ENGINE BEAM END FITTING - PERFORM EDDY CURRENT INSPECTION					Service	ATA:54
	MOS	09-Mar-01						AIRWORTHINESS	
	HRS	0	T:9600						
	AFL	0							
PROC. REF: NDT PART 6/54-50-04PROC. REF: NDT PART 6/54-50-04									

PKG:25

Y5410002	S		PYLONS - PERFORM VISUAL INSPECTION. INSPECT HILITE COLLARS COMMON TO MAIN ENGINE BEAM EXTERNAL TO FUSELAGE.					Service	ATA:54
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 54-00-01PROC. REF: AMM 54-00-01									

PKG:14

ATA 55 - STABILIZERS

551005			HORIZONTAL STABILIZER ASSEMBLY					Component	ATA:55
PN:PN	MOS/MSC	02-Aug-24	O/C						
SN:UNKNOWN	HRS	9525.7							
	AFL	7276							
Special Properties: RII ITEM PROC. REF: AMM 27-40-01PROC. REF: AMM 27-40-01									

552031			LEFT ELEVATOR ASSEMBLY					Component	ATA:55
PN:4555201005-011	MOS/MSC	02-Aug-24	O/C						
SN:UNKNOWN	HRS	9525.7							
	AFL	7276							
Special Properties: RII ITEM PROC. REF: AMM 27-30-01PROC. REF: AMM 27-30-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 55 - STABILIZERS

552032	RIGHT ELEVATOR ASSEMBLY							Component	ATA:55
PN:4555201005-012	MOS/MSC	02-Aug-24	O/C						
SN:UNKNOWN	HRS	9525.7							
	AFL	7276							
Special Properties: RII ITEM									
PROC. REF: AMM 27-30-01PROC. REF: AMM 27-30-01									

553000	TAILCONE/VERTICAL STABILIZER ASSEMBLY							Component	ATA:55
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

554005	RUDDER ASSEMBLY							Component	ATA:55
PN:4555401000-023	MOS/MSC	02-Aug-24	O/C						
SN:UNKNOWN	HRS	9525.7							
	AFL	7276							
Special Properties: RII ITEM									
PROC. REF: AMM 27-20-01PROC. REF: AMM 27-20-01									

A5510014 ^S	* VERTICAL STABILIZER PIVOT FITTING BOTTOM PLATE - PERFORM DETAILED VISUAL INSPECTION. INSPECT AFT PORTION OF BOTTOM PLATE THROUGH LIGHTENING HOLE IN TOP PLATE, FORWARD PORTION OF BOTTOM PLATE THROUGH TOP PLATE CUTOUTS, AND BOTTOM OF OUTSIDE EXPOSED SURFACE OF PIVOT FITTING							Service	ATA:55
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
PKG:26									

A5510021 ^S	* HORIZONTAL MID SPAR FROM CANTED RIB NUMBER 2 TO CANTED RIB NUMBER 3 - PERFORM DETAILED VISUAL INSPECTION							Service	ATA:55
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
PKG:26									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 55 - STABILIZERS										
A5540000	^S	* RUDDER RIB CAP (F.S. 698) - PERFORM VISUAL INSPECTION. INSPECT AROUND FASTENER HOLES AND LIGHTENING HOLES.							Service	ATA:55
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
AA5510034		HORIZONTAL STABILIZER PRIMARY AND SECONDARY BOLTS AND BUSHINGS - PERFORM DETAILED INSPECTION							Service	ATA:55
	MOS	16-Jul-19								
	HRS	8109	4800		12909		2885.9			
	AFL	6239								
PROC. REF: AMM 05-10-00, AMM 55-10-00PROC. REF: AMM 05-10-00, AMM 55-10-00										
E5510074	^S	* HORIZONTAL STABILIZER REAR SPAR FROM CANTED RIB NUMBER 2 TO CANTED RIB NUMBER 3 - PERFORM VISUAL INSPECTION. INSPECT REAR SPAR CAP AND FASTENERS.							Service	ATA:55
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
E5510075	^S	* HORIZONTAL STABILIZER OUTBOARD SPARS AND SKINS OUTBOARD OF CANTED RIB NUMBER 3 - PERFORM VISUAL INSPECTION. INSPECT SPAR CAPS AND FASTENERS							Service	ATA:55
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
E5510076	^S	* HORIZONTAL STABILIZER FRONT SPAR FROM CANTED RIB NO. 2 TO CANTED RIB NO. 3 - PERFORM VISUAL INSPECTION. INSPECT FRONT SPAR CAP AND FASTENERS.							Service	ATA:55
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 55 - STABILIZERS										
E5520003 ^S			* ELEVATOR FRONT SPAR - PERFORM VISUAL INSPECTION. INSPECT SPAR CAP AT FASTENER HOLES						Service	ATA:55
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								
PROC. REF: GENERIC NO REF PROC. REF: GENERIC NO REF										
PKG:26										
E5520004 ^S			* ELEVATOR RIB NO. 1 CAP - PERFORM VISUAL INSPECTION OF RIB NO. 1 CAP CROSS SECTION AND RIB CAP FLANGES AT TORQUE TUBE						Service	ATA:55
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								
PROC. REF: GENERIC NO REF PROC. REF: GENERIC NO REF										
PKG:26										
G5510000 ^S			* HORIZONTAL STABILIZER ACTUATOR ATTACHMENT FITTING - PERFORM EDDY CURRENT INSPECTION						Service	ATA:55
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	4800							
	AFL	0								
PROC. REF: NDT PART 6/55-10-01 PROC. REF: NDT PART 6/55-10-01										
PKG:25										
G5510023 ^S			* HORIZONTAL STABILIZER ACTUATOR VERTICAL TAIL ATTACHMENT - PERFORM EDDY CURRENT INSPECTION						Service	ATA:55
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	4800							
	AFL	0								
PROC. REF: NDT PART 6/55-30-01 PROC. REF: NDT PART 6/55-30-01										
PKG:25										
H5510033 ^S			* HORIZONTAL STABILIZER ACTUATOR ATTACHMENT BOLTS - PERFORM LIQUID PENETRANT INSPECTION						Service	ATA:55
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	4800							
	AFL	0								
PROC. REF: NDT PART 8/27-40-01 PROC. REF: NDT PART 8/27-40-01										
PKG:25										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 55 - STABILIZERS										
M5510010			* HORIZONTAL STABILIZER AFT ROOT RIB - PERFORM EDDY CURRENT INSPECTION. INSPECT AFT ROOT RIB INTERNAL BETWEEN MID SPAR AND AFT SPAR AND UPPER AND LOWER SKINS EXTERNAL AT ATTACHMENT FASTENERS.						Service	ATA:55
	MOS	18-Aug-22						AIRWORTHINESS		
	HRS	9082.6	1200		10282.6		259.5			
	AFL	6994								
PROC. REF: NDT PART 6/55-10-03PROC. REF: NDT PART 6/55-10-03										
M5540022			RUDDER TORQUE TUBE - PERFORM BORESCOPE INSPECTION						Service	ATA:55
	MOS/MSC	09-Mar-01	N/A							
	HRS	0								
	AFL	0								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
N5510005 ^S			* HORIZONTAL STABILIZER REAR SPAR CAP - PERFORM EDDY CURRENT INSPECTION. INSPECT REAR SPAR CAP AND WEB AT CENTER SPLICE						Service	ATA:55
	MOS	25-Nov-19	96					AIRWORTHINESS		
	HRS	8177.7	2400							
	AFL	6303								
PROC. REF: NDT PART 6/55-10-05PROC. REF: NDT PART 6/55-10-05										
N5510015 ^S			* VERTICAL STABILIZER PIVOT FITTING TOP PLATE - PERFORM EDDY CURRENT INSPECTION						Service	ATA:55
	MOS	25-Nov-19	96					AIRWORTHINESS		
	HRS	8177.7	2400							
	AFL	6303								
PROC. REF: NDT PART 6/55-30-02PROC. REF: NDT PART 6/55-30-02										
N5510016 ^S			* VERTICAL STABILIZER PIVOT FITTING TOWER SECTION FORWARD RADIUS - PERFORM EDDY CURRENT INSPECTION. INSPECT PIVOT FITTING AT TOWER SECTION RADIUS, PIVOT FITTING AND TOP PLATE AROUND ADJACENT FASTENERS, AND PIVOT FITTING SIDES AT TOWER SECTION RADIUS.						Service	ATA:55
	MOS	25-Nov-19	96					AIRWORTHINESS		
	HRS	8177.7	2400							
	AFL	6303								
PROC. REF: NDT PART 6/55-30-03PROC. REF: NDT PART 6/55-30-03										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty		
ATA 55 - STABILIZERS											
N5510069 ^S			* HORIZONTAL STABILIZER MID SPAR FLANGE ROOT RIB ATTACHMENT - PERFORM EDDY CURRENT INSPECTION							Service	ATA:55
	MOS	25-Nov-19	96					AIRWORTHINESS			
	HRS	8177.7	2400								
	AFL	6303									
PROC. REF: NDT PART 6/55-10-02PROC. REF: NDT PART 6/55-10-02											
PKG:20											
N5510082 ^S			* HORIZONTAL STABILIZER REAR SPAR FLANGE ROOT RIB ATTACHMENT - PERFORM EDDY CURRENT INSPECTION							Service	ATA:55
	MOS	25-Nov-19	96					AIRWORTHINESS			
	HRS	8177.7	2400								
	AFL	6303									
PROC. REF: NDT PART 6/55-10-04PROC. REF: NDT PART 6/55-10-04											
PKG:20											
P5510006 ^S			* VERTICAL STABILIZER FRONT SPAR AND MID SPAR - PERFORM RADIOGRAPHIC INSPECTION							Service	ATA:55
	MOS	02-Aug-24						AIRWORTHINESS			
	HRS	9525.7	9600								
	AFL	7276									
PROC. REF: NDT PART 2/55-30-01PROC. REF: NDT PART 2/55-30-01											
PKG:26											
P5510008 ^S			* HORIZONTAL STABILIZER PRIMARY AND SECONDARY ATTACH BOLTS - PERFORM MAGNETIC PARTICLE INSPECTION							Service	ATA:55
	MOS	02-Aug-24						AIRWORTHINESS			
	HRS	9525.7	9600								
	AFL	7276									
PROC. REF: NDT PART 7/55-30-02, NDT PART 7/55-30-03PROC. REF: NDT PART 7/55-30-02, NDT PART 7/55-30-03											
PKG:26											
P5510009 ^S			* HORIZONTAL STABILIZER MID SPAR UPPER CAP BL 0.0 TO BL 4.0 - PERFORM X-RAY INSPECTION							Service	ATA:55
	MOS	09-Mar-01						AIRWORTHINESS			
	HRS	0	T:9600								
	AFL	0									
PROC. REF: NDT PART 2/55-10-03PROC. REF: NDT PART 2/55-10-03											
PKG:20											

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 55 - STABILIZERS										
P5510011	^S	* HORIZONTAL STABILIZER MID SPAR AND REAR SPAR UPPER FLANGE AT ROOT RIB - PERFORM RADIOGRAPHIC INSPECTION						Service	ATA:55	
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								
PROC. REF: NDT PART 2/55-10-01PROC. REF: NDT PART 2/55-10-01										
PKG:26										
P5510017	^S	* VERTICAL STABILIZER PIVOT FITTING TOWER SECTION - PERFORM EDDY CURRENT INSPECTION						Service	ATA:55	
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0								
PROC. REF: NDT PART 6/55-30-05PROC. REF: NDT PART 6/55-30-05										
PKG:20										
P5510018	^S	* VERTICAL STABILIZER PIVOT FITTING LUGS - PERFORM EDDY CURRENT INSPECTION						Service	ATA:55	
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								
PROC. REF: NDT PART 6/55-30-04PROC. REF: NDT PART 6/55-30-04										
PKG:26										
P5510019	^S	* ELEVATOR HINGES ON HORIZONTAL STABILIZER - PERFORM EDDY CURRENT INSPECTION						Service	ATA:55	
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								
PROC. REF: NDT PART 6/55-20-02PROC. REF: NDT PART 6/55-20-02										
PKG:26										
P5510020	^S	* HORIZONTAL MID SPAR UPPER CAP - PERFORM EDDY CURRENT INSPECTION						Service	ATA:55	
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								
PROC. REF: NDT PART 6/55-10-07PROC. REF: NDT PART 6/55-10-07										
PKG:26										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty		
ATA 55 - STABILIZERS											
P5510024 ^S			* ELEVATOR CONTROL HORN - PERFORM EDDY CURRENT INSPECTION							Service	ATA:55
	MOS	02-Aug-24						AIRWORTHINESS			
	HRS	9525.7	9600								
	AFL	7276									
PROC. REF: NDT PART 6/55-20-01PROC. REF: NDT PART 6/55-20-01											
PKG:26											
P5510070 ^S			* HORIZONTAL STABILIZER FRONT SPAR - PERFORM RADIOGRAPHIC INSPECTION							Service	ATA:55
	MOS	02-Aug-24						AIRWORTHINESS			
	HRS	9525.7	9600								
	AFL	7276									
PROC. REF: NDT PART 2/55-10-02PROC. REF: NDT PART 2/55-10-02											
PKG:26											
P5510073 ^S			* HORIZONTAL REAR SPAR UPPER CAP - PERFORM EDDY CURRENT INSPECTION							Service	ATA:55
	MOS	02-Aug-24						AIRWORTHINESS			
	HRS	9525.7	9600								
	AFL	7276									
PROC. REF: NDT PART 6/55-10-07PROC. REF: NDT PART 6/55-10-07											
PKG:26											
P5510092 ^S			* HORIZONTAL STABILIZER UPPER SPAR SPLICE DOUBLER - PERFORM EDDY CURRENT INSPECTION							Service	ATA:55
	MOS	09-Mar-01						AIRWORTHINESS			
	HRS	0	T:9600								
	AFL	0									
PROC. REF: NDT PART 6/55-10-06PROC. REF: NDT PART 6/55-10-06											
PKG:20											
P5520001 ^S			* ELEVATOR HINGE ATTACH BOLT - PERFORM MAGNETIC PARTICLE INSPECTION							Service	ATA:55
	MOS	02-Aug-24						AIRWORTHINESS			
	HRS	9525.7	9600								
	AFL	7276									
PROC. REF: NDT PART 7/27-30-01PROC. REF: NDT PART 7/27-30-01											
PKG:26											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 55 - STABILIZERS										
P5520002	^S	* ELEVATOR HINGE PIN - PERFORM LIQUID PENETRANT INSPECTION						Service	ATA:55	
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								
PROC. REF: NDT PART 8/55-30-01PROC. REF: NDT PART 8/55-30-01										
PKG:26										
P5520021	^S	* ELEVATOR HINGE FITTINGS - PERFORM EDDY CURRENT INSPECTION						Service	ATA:55	
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								
PROC. REF: NDT PART 6/55-30-07PROC. REF: NDT PART 6/55-30-07										
PKG:26										
P5520022	^S	* ELEVATOR HINGE PRIMARY AND SECONDARY ATTACH BOLTS - PERFORM LIQUID PENETRANT INSPECTION						Service	ATA:55	
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								
PROC. REF: NDT PART 8/27-30-01, NDT PART 8/27-30-02PROC. REF: NDT PART 8/27-30-01, NDT PART 8/27-30-02										
PKG:26										
P5540001	^S	* RUDDER SPAR - PERFORM DETAILED VISUAL INSPECTION. INSPECT SPAR CAPS AND FASTENERS						Service	ATA:55	
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
PKG:26										
P5540002	^S	* RUDDER ATTACH BOLT - PERFORM LIQUID PENETRANT INSPECTION						Service	ATA:55	
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								
PROC. REF: NDT PART 8/55-30-02PROC. REF: NDT PART 8/55-30-02										
PKG:26										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 55 - STABILIZERS										
Q5510007 ^S	* VERTICAL STABILIZER SKIN AND LOWER AFT SPAR CAP - PERFORM EDDY CURRENT INSPECTION								Service	ATA:55
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								
PROC. REF: NDT PART 6/55-30-06PROC. REF: NDT PART 6/55-30-06										
PKG:26										
Q5530011 ^S	* VERTICAL STABILIZER SKIN AND UPPER AFT SPAR CAP - PERFORM EDDY CURRENT INSPECTION								Service	ATA:55
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0								
PROC. REF: NDT PART 6/55-30-06PROC. REF: NDT PART 6/55-30-06										
PKG:20										
T5510004 ^S	* RUDDER HINGE FITTINGS - PERFORM VISUAL INSPECTION. CONTROL SURFACE REMOVAL NOT REQUIRED.								Service	ATA:55
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
PKG:26										
W5510091	* HORIZONTAL STABILIZER HINGE PRIMARY AND SECONDARY PIVOT PIN INSTALLATION AND ATTACHING HARDWARE - PERFORM DETAILED VISUAL INSPECTION								Service	ATA:55
	MOS	02-Aug-24						MANDATORY		
	HRS	9525.7	625		10150.7		127.6			
	AFL	7276								
PROC. REF: AMM 05-10-00, AMM 55-10-00PROC. REF: AMM 05-10-00, AMM 55-10-00										
Y5510001 ^S	HORIZONTAL STABILIZER - PERFORM EXTERNAL VISUAL INSPECTION								Service	ATA:55
	MOS	09-Mar-01	48							
	HRS	0	1200							
	AFL	0								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
PKG:14										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 55 - STABILIZERS

Y5510002 ^S	ELEVATOR HINGES ON HORIZONTAL STABILIZER - PERFORM VISUAL INSPECTION. INSPECT HINGE LUGS ON HORIZONTAL TAIL SIDE OF JOINT. INSPECT HILITE COLLARS AT BL 0.0 AND OUTBOARD ELEVATOR HINGE.							Service	ATA:55
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							

PKG:14

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

Y5510003 ^S	VERTICAL STABILIZER PIVOT FITTING - PERFORM VISUAL INSPECTION. INSPECT HI-LITE COLLARS COMMON TO THE PIVOT FITTING (MID SPAR, AFT SPAR, TOP PLATE, AND UP/DOWN SPRING BRACKET).							Service	ATA:55
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							

PKG:14

PROC. REF: AMM 55-00-01PROC. REF: AMM 55-00-01

Y5510093 ^S	HORIZONTAL STABILIZER - PERFORM VISUAL INSPECTION OF HI-LITE COLLARS IN THE FOLLOWING AREAS: - FORWARD SPAR TO BL 0.0 RIB - CENTER SPAR TO BL 0.0 RIB - CENTER SPAR SPLICE PLATE - AFT SPAR SPLICE PLATE - ROOT RIBS AT BL 3.70 (RIGHT AND LEFT) - UPPER DOUBLER SPAR SPLICE, BL 0.0 - HSTA UPPER ATTACH FITTING STRUCTURE							Service	ATA:55
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							

PKG:14

PROC. REF: AMM 55-00-01PROC. REF: AMM 55-00-01

Y5510094 ^S	LOWER BRACKET, HORIZONTAL STABILIZER TRIM ACTUATOR - PERFORM BORESCOPE INSPECTION OF HI-LITE COLLARS COMMON TO RIB NO. 6 AND MID SPAR.							Service	ATA:55
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							

PKG:14

PROC. REF: AMM 55-10-00PROC. REF: AMM 55-10-00

Y5540012 ^S	RUDDER TORQUE TUBE - LOOSEN TORQUE TUBE BONDING CLAMP AND PERFORM DETAILED VISUAL INSPECTION OF AREA AROUND BONDING CLAMP FOR CORROSION.							Service	ATA:55
	MOS	09-Mar-01	12						
	HRS	0	300						
	AFL	0							

PKG:2

PROC. REF: AMM 27-20-01PROC. REF: AMM 27-20-01

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 55 - STABILIZERS

ATA 56 - WINDOWS

561001		LEFT WINDSHIELD				Component	ATA:56
PN:6656100000-001	MOS/MSC	02-Aug-24	O/C				
SN:1121	HRS	9525.7					
	AFL	7276					
Special Properties: RII ITEM							
PROC. REF: AMM 56-10-01, AMM 56-10-01PROC. REF: AMM 56-10-01, AMM 56-10-01							

561002		RIGHT WINDSHIELD				Component	ATA:56
PN:6656100001-002	MOS/MSC	02-Aug-24	O/C	TSN 152			
SN:1222	HRS	9525.7		TSN 2762.2			
	AFL	7276		TSN 2118			
Special Properties: RII ITEM							
PROC. REF: AMM 56-10-01, AMM 56-10-01PROC. REF: AMM 56-10-01, AMM 56-10-01							

562010-1		LEFT NO.1 CABIN WINDOW				Component	ATA:56
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0			
SN:UNKNOWN	HRS	0		TSN 0			
	AFL	0		TSN 0			
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01							

562010-10		RIGHT NO.5 CABIN WINDOW				Component	ATA:56
PN:7656202000-015	MOS/MSC	22-Dec-08	O/C	TSN 0			
SN:4621	HRS	6088.5		TSN 0			
	AFL	4660		TSN 0			
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01							

562010-11		LEFT NO.6 CABIN WINDOW				Component	ATA:56
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0			
SN:UNKNOWN	HRS	0		TSN 0			
	AFL	0		TSN 0			
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 56 - WINDOWS										
562010-12		RIGHT NO.6 CABIN WINDOW						Component	ATA:56	
PN:7656202000-015	MOS/MSC	19-Dec-10	O/C							
SN:5304	HRS	6457.2								
	AFL	4944								
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01										
562010-13		LEFT NO.7 CABIN WINDOW						Component	ATA:56	
PN:7656202000-015	MOS/MSC	28-Jun-16	O/C	TSN 0						
SN:6187	HRS	7635.4		TSN 0						
	AFL	5831		TSN 0						
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01										
562010-14		RIGHT NO.7 CABIN WINDOW						Component	ATA:56	
PN:7656202000-015	MOS/MSC	17-Feb-05	O/C							
SN:0601	HRS	3300.2								
	AFL	2515								
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01										
562010-15		LEFT NO.8 CABIN WINDOW						Component	ATA:56	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01										
562010-16		EMERGENCY EXIT WINDOW						Component	ATA:56	
PN:7656202000-015	MOS/MSC	13-Dec-10	O/C	TSN 0						
SN:5304	HRS	6457.2		TSN 0						
	AFL	4944		TSN 0						
PROC. REF: AMM 52-20-06PROC. REF: AMM 52-20-06										
562010-2		RIGHT NO.1 CABIN WINDOW						Component	ATA:56	
PN:7656202000-015	MOS/MSC	21-Jun-05	O/C							
SN:1340	HRS	3694.5								
	AFL	2785								
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 56 - WINDOWS										
562010-3		LEFT NO.2 CABIN WINDOW						Component	ATA:56	
PN:7656202000-015	MOS/MSC	22-Dec-08	O/C	TSN 0						
SN:4456	HRS	6088.5		TSN 0						
	AFL	4660		TSN 0						
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01										
562010-4		RIGHT NO.2 CABIN WINDOW						Component	ATA:56	
PN:7656202000-015	MOS/MSC	17-Feb-05	O/C							
SN:0847	HRS	3300.2								
	AFL	2515								
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01										
562010-5		LEFT NO.3 CABIN WINDOW						Component	ATA:56	
PN:7656202000-015	MOS/MSC	22-Dec-08	O/C	TSN 0						
SN:4505	HRS	6088.5		TSN 0						
	AFL	4660		TSN 0						
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01										
562010-6		RIGHT NO.3 CABIN WINDOW						Component	ATA:56	
PN:7656202000-015	MOS/MSC	22-Dec-08	O/C	TSN 0						
SN:4458	HRS	6088.5		TSN 0						
	AFL	4660		TSN 0						
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01										
562010-7		LEFT NO.4 CABIN WINDOW						Component	ATA:56	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01										
562010-8		RIGHT NO.4 CABIN WINDOW						Component	ATA:56	
PN:7656202000-015	MOS/MSC	17-Dec-10	O/C	TSN 0						
SN:5310	HRS	6457.2		TSN 0						
	AFL	4944		TSN 0						
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 56 - WINDOWS										
562010-9	LEFT NO.5 CABIN WINDOW								Component	ATA:56
PN:7656202000-015	MOS/MSC	15-Dec-10	O/C	TSN 0						
SN:5307	HRS	6457.2		TSN 0						
	AFL	4944		TSN 0						
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01										
L5600010 ^S	* CABIN WINDOWS (INCLUDING THE EMERGENCY EXIT WINDOW) - PERFORM DETAILED VISUAL INSPECTION								Service	ATA:56
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	4800							
	AFL	0								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
N5600003	* LEFT WINDSHIELD - PERFORM ULTRASONIC INSPECTION OF STRUCTURAL PLIES								Service	ATA:56
PN:6656100000-001	MOS/MSC	02-Aug-24	N/A							
SN:1121	HRS	9525.7								
	AFL	7276								
PROC. REF: NDT PART 4/56-10-01PROC. REF: NDT PART 4/56-10-01										
N5600003	* RIGHT WINDSHIELD - PERFORM ULTRASONIC INSPECTION OF STRUCTURAL PLIES								Service	ATA:56
PN:6656100001-002	MOS/MSC	02-Aug-24	N/A							
SN:1222	HRS	9525.7								
	AFL	7276								
PROC. REF: NDT PART 4/56-10-01PROC. REF: NDT PART 4/56-10-01										
N5600012	* LEFT WINDSHIELD - PERFORM BOLT HOLE INSPECTION								Service	ATA:56
PN:6656100000-001	MOS	02-Aug-24						AIRWORTHINESS		
SN:1121	HRS	9525.7	4800		14325.7		4302.6			
	AFL	7276								
PROC. REF: AMM 56-10-01PROC. REF: AMM 56-10-01										
N5600012	* RIGHT WINDSHIELD - PERFORM BOLT HOLE INSPECTION								Service	ATA:56
PN:6656100001-002	MOS	02-Aug-24						AIRWORTHINESS		
SN:1222	HRS	9525.7	4800		14325.7		4302.6			
	AFL	7276								
PROC. REF: AMM 56-10-01PROC. REF: AMM 56-10-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 56 - WINDOWS

W5600002		** WINDSHIELD - PERFORM RAIN REMOVAL COATING EFFECTIVENESS TEST						Service	ATA:56
	MOS	21-Feb-25	12		21-Feb-26		OVD	AIRWORTHINESS	
	HRS	9637.3							
	AFL	7352							
PROC. REF: AMM 56-10-01, AMM 56-10-01PROC. REF: AMM 56-10-01, AMM 56-10-01									

Y5600000^S		WINDSHIELDS - PERFORM VISUAL INSPECTION (INTERIOR AND EXTERIOR)						Service	ATA:56
	MOS	21-Aug-25	12						
	HRS	9809.8	300						
	AFL	7471							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									

PKG:1

Y5600001^S		CABIN WINDOWS - PERFORM VISUAL INSPECTION						Service	ATA:56
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									

PKG:7

Y5600013^S		WINDSHIELDS - PERFORM VISUAL INSPECTION OF THE AERODYNAMIC SEAL						Service	ATA:56
	MOS	21-Aug-25	12						
	HRS	9809.8	300						
	AFL	7471							
PROC. REF: AMM 56-10-01, AMM 56-10-01PROC. REF: AMM 56-10-01, AMM 56-10-01									

PKG:1

ATA 57 - WINGS

571001		WING ASSEMBLY						Component	ATA:57
PN:PN	MOS/MSC	09-Mar-01	O/C		TSN 0				
SN:UNKNOWN	HRS	0			TSN 0				
	AFL	0			TSN 0				
PROC. REF: AMM 57-10-00PROC. REF: AMM 57-10-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 57 - WINGS										
571010		LEFT MAIN LANDING GEAR ACTUATOR FITTING						Component	ATA:57	
PN:PN	MOS	09-Mar-01		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0	20000	TSN 0	20000		12384			
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01										
571011		RIGHT MAIN LANDING GEAR ACTUATOR FITTING						Component	ATA:57	
PN:PN	MOS	09-Mar-01		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0	20000	TSN 0	20000		12384			
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01										
573001		LEFT WINGLET FILLER						Component	ATA:57	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
573002		RIGHT WINGLET FILLER						Component	ATA:57	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
573090		LEFT WING WINGLET						Component	ATA:57	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 57-30-01PROC. REF: AMM 57-30-01										
573091		LEFT WINGLET LEADING EDGE ASSEMBLY						Component	ATA:57	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 57-30-01PROC. REF: AMM 57-30-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 57 - WINGS										
573092		RIGHT WING WINGLET						Component	ATA:57	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 57-30-01PROC. REF: AMM 57-30-01										
573093		RIGHT WINGLET LEADING EDGE ASSEMBLY						Component	ATA:57	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 57-30-01PROC. REF: AMM 57-30-01										
574005		LEFT INBOARD LEADING EDGE						Component	ATA:57	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 57-40-01PROC. REF: AMM 57-40-01										
574007		RIGHT INBOARD LEADING EDGE						Component	ATA:57	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 57-40-01PROC. REF: AMM 57-40-01										
574011		LEFT INBOARD LEADING EDGE ACCESS SECTION						Component	ATA:57	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 57-40-01PROC. REF: AMM 57-40-01										
574013		RIGHT INBOARD LEADING EDGE ACCESS SECTION						Component	ATA:57	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 57-40-01PROC. REF: AMM 57-40-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
574033 LEFT CENTER LEADING EDGE									Component ATA:57
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 57-40-01PROC. REF: AMM 57-40-01									
574035 RIGHT CENTER LEADING EDGE									Component ATA:57
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 57-40-01PROC. REF: AMM 57-40-01									
574039 LEFT OUTBOARD LEADING EDGE ACCESS SECTION									Component ATA:57
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 57-40-01PROC. REF: AMM 57-40-01									
574041 RIGHT OUTBOARD LEADING EDGE ACCESS SECTION									Component ATA:57
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 57-40-01PROC. REF: AMM 57-40-01									
574050 LEFT OUTBOARD LEADING EDGE									Component ATA:57
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 57-40-01PROC. REF: AMM 57-40-01									
574051 RIGHT OUTBOARD LEADING EDGE									Component ATA:57
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 57-40-01PROC. REF: AMM 57-40-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 57 - WINGS

575001 LEFT FLAP ASSEMBLY Component ATA:57									
PN:4557500006-007	MOS/MSC	02-Aug-24	O/C						
SN:474598000144	HRS	9525.7							
	AFL	7276							
Special Properties: RII ITEM									
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01									

575002 RIGHT FLAP ASSEMBLY Component ATA:57									
PN:4557500006-008	MOS/MSC	02-Aug-24	O/C						
SN:474600100146	HRS	9525.7							
	AFL	7276							
Special Properties: RII ITEM									
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01									

576001 LEFT AILERON Component ATA:57									
PN:4557600003-001	MOS/MSC	02-Aug-24	O/C						
SN:UNKNOWN	HRS	9525.7							
	AFL	7276							
Special Properties: RII ITEM									
PROC. REF: AMM 27-10-02PROC. REF: AMM 27-10-02									

576002 RIGHT AILERON Component ATA:57									
PN:4557600003-002	MOS/MSC	02-Aug-24	O/C						
SN:00145	HRS	9525.7							
	AFL	7276							
Special Properties: RII ITEM									
PROC. REF: AMM 27-10-02PROC. REF: AMM 27-10-02									

576037 LEFT AILERON BOLTS (X3) Component ATA:57									
PN:PN	MOS/MSC	02-Aug-24	H/T	TSN 0					
SN:UNKNOWN	HRS	9525.7		TSN 0					
	AFL	7276		TSN 0					
PROC. REF: AMM 27-10-02PROC. REF: AMM 27-10-02									

576038 RIGHT AILERON BOLTS (X3) Component ATA:57									
PN:PN	MOS/MSC	02-Aug-24	H/T	TSN 0					
SN:UNKNOWN	HRS	9525.7		TSN 0					
	AFL	7276		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 57 - WINGS

PROC. REF: AMM 27-10-02PROC. REF: AMM 27-10-02

577001		LEFT SPOILER --						Component	ATA:57
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
Special Properties: RII ITEM									
PROC. REF: AMM 27-60-01PROC. REF: AMM 27-60-01									

577002		RIGHT SPOILER --						Component	ATA:57
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
Special Properties: RII ITEM									
PROC. REF: AMM 27-60-01PROC. REF: AMM 27-60-01									

A5760004		* LEFT AILERON BOLTS (X3) - PERFORM MAGNETIC PARTICLE INSPECTION OR REPLACE						Service	ATA:57
PN:PN	MOS	02-Aug-24						AIRWORTHINESS	
SN:UNKNOWN	HRS	9525.7	9600	19125.7			9102.6		
	AFL	7276							

A5760004		* RIGHT AILERON BOLTS (X3) - PERFORM MAGNETIC PARTICLE INSPECTION OR REPLACE						Service	ATA:57
PN:PN	MOS	02-Aug-24						AIRWORTHINESS	
SN:UNKNOWN	HRS	9525.7	9600	19125.7			9102.6		
	AFL	7276							

AC5710190		* LEFT WING CENTER SECTION (PANELS 510AC, 510BC, 510BL AND 610BR REMOVED AND PANELS 510AL, 610AR, 720BL, AND 730BR LOWERED) - PERFORM VISUAL INSPECTION. INSPECT STRUCTURE FOR CORROSION OR DETERIORATION OF PROTECTIVE TREATMENT.						Service	ATA:57
	MOS	31-Mar-20	96	31-Mar-28			675 d		
	HRS	8253.8							
	AFL	6353							
PROC. REF: AMM 57-10-00PROC. REF: AMM 57-10-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
AC5710190		* RIGHT WING CENTER SECTION (PANELS 510AC, 510BC, 510BL AND 610BR REMOVED AND PANELS 510AL, 610AR, 720BL, AND 730BR LOWERED) - PERFORM VISUAL INSPECTION. INSPECT STRUCTURE FOR CORROSION OR DETERIORATION OF PROTECTIVE TREATMENT.						Service	ATA:57
	MOS	31-Mar-20	96		31-Mar-28		675 d		
	HRS	8253.8							
	AFL	6353							
PROC. REF: AMM 57-10-00PROC. REF: AMM 57-10-00									
AE5710035 ^S		* WING LOWER SKIN AT DRAIN HOLE (4 LOCATIONS) - PERFORM EDDY CURRENT INSPECTION						Service	ATA:57
	MOS	09-Mar-01						AIRWORTHINESS	
	HRS	0	T:9600						
	AFL	0							PKG:25
PROC. REF: NDT PART 6/57-30-02PROC. REF: NDT PART 6/57-30-02									
AE5710187		* LOWER WING FUEL DRAIN HOLES (4 LOCATIONS) - PERFORM EDDY CURRENT INSPECTION						Service	ATA:57
	MOS	EFF	72		11-Dec-31 *		2025 d	AIRWORTHINESS	
	HRS								
	AFL								
PROC. REF: NDT PART 6/57-30-03PROC. REF: NDT PART 6/57-30-03									
E5710005 ^S		* WING CENTER SECTION SPAR UPPER CAPS - PERFORM VISUAL INSPECTION. INSPECT FRONT, MID, AND REAR SPAR UPPER CAPS FROM CENTERLINE TO SKIN TERMINATION AT WS 33.						Service	ATA:57
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							PKG:26
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
E5710019 ^S		* WING BOX, UPPER SKIN, SKIN/STRINGER AND SPAR CAPS - PERFORM VISUAL INSPECTION. INSPECT UPPER WING SPAR CAPS, SKIN PANEL, AND STRINGERS OF OUTER WING						Service	ATA:57
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							PKG:26
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
E5710020 ^S	* WING BOX RIBS - PERFORM VISUAL INSPECTION. INSPECT ALL WING BOX RIBS EXCEPT CLOSING RIB BETWEEN FRONT AND MID SPARS AND CLOSING RIB BETWEEN MID AND REAR SPAR.							Service	ATA:57
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
PKG:26									
E5750051	* FLAP MAIN TRACK ROLLERS - PERFORM VISUAL INSPECTION WITH FLAPS REMOVED							Service	ATA:57
	MOS	09-Mar-01			RTS			AIRWORTHINESS	
	HRS	0	T:10000						
	AFL	0							
PROC. REF: AMM 05-10-00, AMM 27-50-01PROC. REF: AMM 05-10-00, AMM 27-50-01									
E5750052	* FLAP NOSE ROLLERS - PERFORM VISUAL INSPECTION WITH FLAPS REMOVED							Service	ATA:57
	MOS	21-Aug-25						AIRWORTHINESS	
	HRS	9809.8	600		10409.8		386.7		
	AFL	7471							
Special Properties: RII ITEM PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
E5760006 ^S	* AILERON BASIC STRUCTURE - PERFORM VISUAL INSPECTION							Service	ATA:57
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
PKG:26									
L5710124 ^S	* AILERON DRIVE SUPPORT - PERFORM ULTRASONIC INSPECTION							Service	ATA:57
	MOS	09-Mar-01						AIRWORTHINESS	
	HRS	0	4800						
	AFL	0							
PROC. REF: NDT PART 4/27-10-01PROC. REF: NDT PART 4/27-10-01									
PKG:25									

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 57 - WINGS										
N5710002		* WING BOX MID SPAR LOWER CAP, OUTBOARD OF JOINT AT WS 137 BETWEEN RIB NO. 7 AND 8 - PERFORM DIRECTED VISUAL INSPECTION. INSPECT MID SPAR LOWER CAP AND LOWER SKIN PANELS.							Service	ATA:57
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	3580		13105.7		3082.6			
	AFL	7276								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
N5710004 ^S		* WING CENTER SECTION REAR SPAR - PERFORM EDDY CURRENT INSPECTION. INSPECT REAR SPAR LOWER CAP FROM CENTERLINE TO WS 33.							Service	ATA:57
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0							PKG:25	
PROC. REF: NDT PART 6/57-20-02PROC. REF: NDT PART 6/57-20-02										
N5710006 ^S		* WING CENTER SECTION FORWARD AND AFT RIBS AT WS 6 AND FORWARD RIBS AT WS 17 - PERFORM EDDY CURRENT INSPECTION							Service	ATA:57
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0							PKG:25	
PROC. REF: NDT PART 6/57-10-06PROC. REF: NDT PART 6/57-10-06										
N5710008		* WING BOX MID SPAR LOWER CAP - PERFORM ULTRASONIC INSPECTION. INSPECT MID SPAR LOWER CAP AND LOWER SKIN PANELS BETWEEN WS 99 AND WS 137							Service	ATA:57
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	2500		12025.7		2002.6			
	AFL	7276								
PROC. REF: NDT PART 4/57-30-03PROC. REF: NDT PART 4/57-30-03										
N5710009		* WING BOX MID SPAR LOWER CAP JOINT AT WS 137 - PERFORM X-RAY INSPECTION. INSPECT MID SPAR CENTER/OUTER JOINT							Service	ATA:57
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	4517		14042.7		4019.6			
	AFL	7276								
PROC. REF: NDT PART 2/57-10-02PROC. REF: NDT PART 2/57-10-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 57 - WINGS										
N5710010		* WING BOX REAR SPAR LOWER CAP INBOARD OF JOINT AT WS 81 - PERFORM ULTRASONIC INSPECTION. INSPECT REAR SPAR LOWER CAP BETWEEN SKIN TERMINATION AT WS 48 AND CLOSING RIB AT WS 60.							Service	ATA:57
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	960		10485.7		462.6			
	AFL	7276								
PROC. REF: NDT PART 4/57-30-01PROC. REF: NDT PART 4/57-30-01										
N5710011 ^S		* WING BOX REAR SPAR LOWER CAP JOINT AT WS 81 - PERFORM X-RAY INSPECTION. INSPECT CENTER AND OUTER REAR SPARS, LOWER SPLICE PLATE, AND LOWER SKIN BETWEEN WS 60 AND WS 90.							Service	ATA:57
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0								
PROC. REF: NDT PART 2/57-10-03PKG:22 PROC. REF: NDT PART 2/57-10-03										
N5710012		* WING BOX REAR SPAR LOWER CAP OUTBOARD OF JOINT AT WS 81 TO RIB NUMBER 6 - PERFORM DETAILED VISUAL INSPECTION. INSPECT OUTER REAR SPAR LOWER CAP AND AFT LOWER SKIN PANEL OUTBOARD OF REAR SPLICE AT WS 90.							Service	ATA:57
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	3443		12968.7		2945.6			
	AFL	7276								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
N5710013		* WING BOX REAR SPAR LOWER CAP SKIN TERMINATION AT MS 48 - PERFORM EDDY CURRENT INSPECTION. INSPECT REAR SPAR LOWER CAP BETWEEN WS 33 AND WS 48.							Service	ATA:57
	MOS	09-Mar-01			RTS			AIRWORTHINESS		
	HRS	0	T:10000							
	AFL	0								
PROC. REF: NDT PART 6/57-20-04PROC. REF: NDT PART 6/57-20-04										
N5710014 ^S		* WING BOX REAR SPAR FLAP TRACK CUTOUTS - PERFORM EDDY CURRENT INSPECTION. INSPECT FLAP TRACK CUTOUTS AT WS 65, WS 126, AND WS 184 ON REAR SPAR.							Service	ATA:57
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0								
PROC. REF: NDT PART 6/57-20-01PKG:25 PROC. REF: NDT PART 6/57-20-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 57 - WINGS										
N5710016	S	* WING BOX BASIC SKIN/STRINGER, LOWER SKIN - PERFORM VISUAL INSPECTION. INSPECT OUTBOARD WING FORWARD AND AFT LOWER SKIN PANELS AND STRINGERS.						Service	ATA:57	
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0							PKG:25	
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
N5710017	S	* WING BOX BASIC SKIN/STRINGER AT STRINGER RUN-OUT, LOWER SKIN - PERFORM VISUAL INSPECTION. INSPECT STRINGER RUN-OUTS IN FORWARD AND AFT LOWER SKIN PANELS.						Service	ATA:57	
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276							PKG:26	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
N5710021	S	* CENTER SECTION MID SPAR LOWER CAP - PERFORM EDDY CURRENT INSPECTION. INSPECT MID SPAR FROM CENTERLINE SPLICE PLATE TO SKIN TERMINATION AT MS 33.						Service	ATA:57	
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0							PKG:22	
PROC. REF: NDT PART 6/57-10-02PROC. REF: NDT PART 6/57-10-02										
N5710022	S	* CENTER SECTION MID SPAR CENTERLINE JOINT - PERFORM EDDY CURRENT INSPECTION. INSPECT CENTER MID SPAR (CENTERLINE TO WS 17), LOWER SPLICE PLATE, AND CENTER MID SPAR JOINT FITTING LOWER CAP.						Service	ATA:57	
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0							PKG:22	
PROC. REF: NDT PART 6/57-10-08, NDT PART 6/57-10-10PROC. REF: NDT PART 6/57-10-08, NDT PART 6/57-10-10										
N5710023	S	* CENTER SECTION FRONT SPAR LOWER CAP - PERFORM EDDY CURRENT INSPECTION. INSPECT CENTER WING FRONT SPAR LOWER CAP BETWEEN SKIN TERMINATIONS (WS 31 LEFT TO WS 31 RIGHT).						Service	ATA:57	
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0							PKG:22	
PROC. REF: NDT PART 6/57-10-03PROC. REF: NDT PART 6/57-10-03										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
N5710026			* WING BOX MID SPAR LOWER CAP - PERFORM ULTRASONIC INSPECTION. INSPECT MID SPAR LOWER CAP OUTBOARD OF ROOT RIB AT WS 33 TO WS 99.					Service	ATA:57
	MOS				RTS			AIRWORTHINESS	
	HRS	0			T:10000				
	AFL								
PROC. REF: NDT PART 4/57-30-03PROC. REF: NDT PART 4/57-30-03									
N5710028 ^S			* WING BOX MID SPAR LOWER CAP, SKIN TERMINATION AT WS 33 - PERFORM BOLT HOLE EDDY CURRENT INSPECTION. INSPECT MID SPAR LOWER CAP UNDERNEATH ROOT RIB (WS 33) AT POINT OF SKIN TERMINATION.					Service	ATA:57
	MOS	09-Mar-01						AIRWORTHINESS	
	HRS	0			T:9600				
	AFL	0							
PROC. REF: NDT PART 6/57-10-11PKG:25									
N5710031 ^S			* WING BOX SKIN ACCESS COVER HOLES - PERFORM EDDY CURRENT INSPECTION. INSPECT ACCESS HOLES IN FORWARD AND AFT LOWER SKIN PANELS.					Service	ATA:57
	MOS	09-Mar-01						AIRWORTHINESS	
	HRS	0			T:9600				
	AFL	0							
PROC. REF: NDT PART 6/57-30-01PKG:25									
N5710037 ^S			* WING BOX FRONT SPAR LOWER CAP - PERFORM VISUAL INSPECTION. INSPECT FRONT SPAR LOWER CAP AND LOWER FORWARD SKIN OUTBOARD OF MID-SPAR STATION (MS) 55.					Service	ATA:57
	MOS	09-Mar-01						AIRWORTHINESS	
	HRS	0			T:9600				
	AFL	0							
PROC. REF: GENERIC NO REFPKG:22									
N5710084 ^S			SPOILER, CENTER HINGE SPOILER SIDE - PERFORM EDDY CURRENT INSPECTION					Service	ATA:57
	MOS	25-Nov-19	96						
	HRS	8177.7	2400						
	AFL	6303							
PROC. REF: NDT PART 6/57-40-01PKG:22									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 57 - WINGS										
N5710121 ^S			* WING BOX MID SPAR, OUTBOARD OF RIB NUMBER 8 - PERFORM VISUAL INSPECTION AT WS 156 AND OUTBOARD TO WS 260						Service	ATA:57
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0		T:9600						
	AFL	0								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
PKG:25										
N5710122 ^S			* WING BOX REAR SPAR, OUTBOARD OF RIB NUMBER 6 - PERFORM VISUAL INSPECTION AT WS 118 AND OUTBOARD TO WS 260						Service	ATA:57
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0		T:9600						
	AFL	0								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
PKG:25										
N5710123			* WING BOX MID SPAR LOWER CAP - PERFORM EDDY CURRENT INSPECTION AT TRUNNION FITTING						Service	ATA:57
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	2666		12191.7		2168.6			
	AFL	7276								
PROC. REF: NDT PART 6/57-10-01PROC. REF: NDT PART 6/57-10-01										
N5710137 ^S			* MID SPAR AT RIB NO. 2 NEAR WS 48 - PERFORM BOLT HOLE EDDY CURRENT INSPECTION						Service	ATA:57
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0		T:9600						
	AFL	0								
PROC. REF: NDT PART 6/57-10-11APROC. REF: NDT PART 6/57-10-11A										
PKG:25										
N5710138 ^S			* MID SPAR AT RIB NO. 3 NEAR WS 60 - PERFORM BOLT HOLE EDDY CURRENT INSPECTION						Service	ATA:57
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0		T:9600						
	AFL	0								
PROC. REF: NDT PART 6/57-10-11APROC. REF: NDT PART 6/57-10-11A										
PKG:25										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 57 - WINGS										
N5710139 ^S			* FORWARD FLANGE FASTENERS AT REAR SPAR BETWEEN WS 52 AND WS 60 - PERFORM BOLT HOLE EDDY CURRENT INSPECTION						Service	ATA:57
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0		T:9600						
	AFL	0								
PROC. REF: NDT PART 6/57-20-03PROC. REF: NDT PART 6/57-20-03										
N5710148			* WING CENTER SECTION REAR SPAR - PERFORM EDDY CURRENT INSPECTION. INSPECT REAR SPAR LOWER CAP FROM CENTERLINE TO WS 33.						Service	ATA:57
	MOS/MSC	09-Mar-01		N/A						
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 6/57-20-02PROC. REF: NDT PART 6/57-20-02										
N5710149			* WING CENTER SECTION FORWARD AND AFT RIBS AT WS 6 AND FORWARD RIBS AT WS 17 - PERFORM EDDY CURRENT INSPECTION						Service	ATA:57
	MOS/MSC	09-Mar-01		N/A						
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 6/57-10-06PROC. REF: NDT PART 6/57-10-06										
N5710150			* WING BOX MID SPAR LOWER CAP - PERFORM ULTRASONIC INSPECTION. INSPECT MID SPAR LOWER CAP AND LOWER SKIN PANELS BETWEEN WS 99 AND WS 137.						Service	ATA:57
	MOS/MSC	09-Mar-01		N/A						
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 4/57-30-03PROC. REF: NDT PART 4/57-30-03										
N5710151			* WING BOX MID SPAR LOWER CAP JOINT AT WS 137 - PERFORM X-RAY INSPECTION. INSPECT MID SPAR CENTER/OUTER JOINT.						Service	ATA:57
	MOS/MSC	09-Mar-01		N/A						
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 2/57-10-02PROC. REF: NDT PART 2/57-10-02										
N5710152			* WING BOX REAR SPAR LOWER CAP INBOARD OF JOINT AT WS 81 - PERFORM ULTRASONIC INSPECTION. INSPECT REAR SPAR LOWER CAP BETWEEN SKIN TERMINATION AT WS 48 AND CLOSING RIB AT WS 60.						Service	ATA:57
	MOS/MSC	09-Mar-01		N/A						
	HRS	0								
	AFL	0								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 57 - WINGS

PROC. REF: NDT PART 4/57-30-01PROC. REF: NDT PART 4/57-30-01

N5710153								* WING BOX REAR SPAR LOWER CAP JOINT AT WS 81 - PERFORM X-RAY INSPECTION. INSPECT CENTER AND OUTER REAR SPARS, LOWER SPLICE PLATE, AND LOWER SKIN BETWEEN WS 60 AND WS 90.	Service ATA:57
----------	--	--	--	--	--	--	--	--	----------------

MOS/MSC	09-Mar-01	N/A
HRS	0	
AFL	0	

PROC. REF: NDT PART 2/57-10-03PROC. REF: NDT PART 2/57-10-03

N5710155								* WING BOX REAR SPAR LOWER CAP SKIN TERMINATION AT MS 48 - PERFORM EDDY CURRENT INSPECTION. INSPECT REAR SPAR LOWER CAP BETWEEN WS 33 AND WS 48.	Service ATA:57
----------	--	--	--	--	--	--	--	--	----------------

MOS/MSC	09-Mar-01	N/A
HRS	0	
AFL	0	

PROC. REF: NDT PART 6/57-20-04PROC. REF: NDT PART 6/57-20-04

N5710157 ^S								* WING BOX BASIC SKIN/STRINGER AT STRINGER RUN-OUT, LOWER SKIN - PERFORM VISUAL INSPECTION. INSPECT STRINGER RUN-OUTS IN FORWARD AND AFT LOWER SKIN PANELS.	Service ATA:57
-----------------------	--	--	--	--	--	--	--	---	----------------

MOS/MSC	09-Mar-01	N/A
HRS	0	
AFL	0	

PKG:25

PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00

N5710158								* CENTER SECTION FRONT SPAR LOWER CAP - PERFORM EDDY CURRENT INSPECTION. INSPECT CENTER WING FRONT SPAR LOWER CAP BETWEEN SKIN TERMINATIONS (WS 31 LEFT TO WS 31 RIGHT).	Service ATA:57
----------	--	--	--	--	--	--	--	--	----------------

MOS/MSC	09-Mar-01	N/A
HRS	0	
AFL	0	

PROC. REF: NDT PART 6/57-10-03PROC. REF: NDT PART 6/57-10-03

N5710159								* WING BOX MID SPAR LOWER CAP - PERFORM ULTRASONIC INSPECTION. INSPECT MID SPAR LOWER CAP OUTBOARD OF ROOT RIB AT WS 33 TO WS 99.	Service ATA:57
----------	--	--	--	--	--	--	--	---	----------------

MOS/MSC	09-Mar-01	N/A
HRS	0	
AFL	0	

PROC. REF: NDT PART 4/57-30-03PROC. REF: NDT PART 4/57-30-03

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 57 - WINGS										
N5710160			* WING BOX MID SPAR LOWER CAP, SKIN TERMINATION AT WS 33 - PERFORM BOLT HOLE EDDY CURRENT INSPECTION. INSPECT MID SPAR LOWER CAP UNDERNEATH ROOT RIB (WS 33) AT POINT OF SKIN TERMINATION.						Service	ATA:57
	MOS/MSC	09-Mar-01	N/A							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 6/57-10-11PROC. REF: NDT PART 6/57-10-11										
N5710161 ^S			* WING BOX SKIN ACCESS COVER HOLES - PERFORM EDDY CURRENT INSPECTION. INSPECT ACCESS HOLES IN FORWARD AND AFT LOWER SKIN PANELS.						Service	ATA:57
	MOS/MSC	09-Mar-01	N/A							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 6/57-30-01PKG:22 PROC. REF: NDT PART 6/57-30-01										
N5710163			* CENTER SECTION MID SPAR CENTERLINE JOINT - PERFORM EDDY CURRENT INSPECTION. INSPECT CENTER MID SPAR (CENTERLINE TO WS 17), LOWER SPLICE PLATE, AND CENTER MID SPAR JOINT FITTING LOWER CAP.						Service	ATA:57
	MOS/MSC	09-Mar-01	N/A							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 6/57-10-08, NDT PART 6/57-10-10PROC. REF: NDT PART 6/57-10-08, NDT PART 6/57-10-10										
N5710164			* CENTER SECTION MID SPAR LOWER CAP - PERFORM EDDY CURRENT INSPECTION. INSPECT MID SPAR FROM CENTERLINE SPLICE PLATE TO SKIN TERMINATION AT MS 33.						Service	ATA:57
	MOS/MSC	09-Mar-01	N/A							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 6/57-10-02PROC. REF: NDT PART 6/57-10-02										
N5710165			* WING BOX REAR SPAR FLAP TRACK CUT-OUTS - PERFORM EDDY CURRENT INSPECTION. INSPECT FLAP TRACK CUT-OUTS AT WS 65, WS 126, AND WS 184 ON REAR SPAR.						Service	ATA:57
	MOS/MSC	09-Mar-01	N/A							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 6/57-20-01PROC. REF: NDT PART 6/57-20-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 57 - WINGS										
N5710168	* WING BOX MID SPAR LOWER CAP - PERFORM EDDY CURRENT INSPECTION AT TRUNNION FITTING								Service	ATA:57
	MOS/MSC	09-Mar-01	N/A							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 6/57-10-01PROC. REF: NDT PART 6/57-10-01										
N5710169	* MID SPAR AT RIB NO. 2 NEAR WS 48 - PERFORM BOLT HOLE EDDY CURRENT INSPECTION								Service	ATA:57
	MOS/MSC	09-Mar-01	N/A							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 6/57-10-11APROC. REF: NDT PART 6/57-10-11A										
N5710170	* MID SPAR AT RIB NO. 3 NEAR WS 60 - PERFORM BOLT HOLE EDDY CURRENT INSPECTION								Service	ATA:57
	MOS/MSC	09-Mar-01	N/A							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 6/57-10-11APROC. REF: NDT PART 6/57-10-11A										
N5710171	* FORWARD FLANGE FASTENERS AT REAR SPAR BETWEEN WS 52 AND WS 60 - PERFORM BOLT HOLE EDDY CURRENT INSPECTION								Service	ATA:57
	MOS/MSC	09-Mar-01	N/A							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 6/57-20-03PROC. REF: NDT PART 6/57-20-03										
N5710172	* WING BOX MID SPAR LOWER CAP - PERFORM ULTRASONIC INSPECTION AT TRUNNION FITTING								Service	ATA:57
	MOS	02-Aug-24								
	HRS	9525.7	2666		12191.7		2168.6			
	AFL	7276								
PROC. REF: NDT PART 4/57-10-00PROC. REF: NDT PART 4/57-10-00										
N5710173	* WING BOX MID SPAR LOWER CAP - PERFORM ULTRASONIC INSPECTION AT TRUNNION FITTING								Service	ATA:57
	MOS/MSC	09-Mar-01	N/A							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 4/57-10-00PROC. REF: NDT PART 4/57-10-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 57 - WINGS										
N5710174		* WING BOX REAR SPAR LOWER CAP SKIN TERMINATION AT MS 48 - PERFORM ULTRASONIC INSPECTION. INSPECT REAR SPAR LOWER CAP BETWEEN WS 33 AND WS 48.							Service	ATA:57
	MOS	09-Mar-01			RTS			AIRWORTHINESS		
	HRS	0	T:10000							
	AFL	0								
PROC. REF: NDT PART 4/57-30-04PROC. REF: NDT PART 4/57-30-04										
N5710175		* WING BOX REAR SPAR LOWER CAP SKIN TERMINATION AT WS 48 - PERFORM ULTRASONIC INSPECTION. INSPECT REAR SPAR LOWER CAP BETWEEN WS 33 AND WS 48.							Service	ATA:57
	MOS/MSC	09-Mar-01	N/A							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 4/57-30-04PROC. REF: NDT PART 4/57-30-04										
N5710176 ^S		* WING MID SPAR (CENTER SECTION) LOWER CAP AND CENTER JOINT FITTING - PERFORM ULTRASONIC INSPECTION							Service	ATA:57
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0								
PROC. REF: NDT PART 4/57-30-05PROC. REF: NDT PART 4/57-30-05										
N5710177		* WING MID SPAR (CENTER SECTION) LOWER CAP AND CENTER JOINT FITTING - PERFORM ULTRASONIC INSPECTION							Service	ATA:57
	MOS/MSC	09-Mar-01	N/A							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 4/57-30-05PROC. REF: NDT PART 4/57-30-05										
N5750005 ^S		* FLAP MAIN TRACK HINGE FITTINGS, TRACK, AND FLAP BOX SIDES - PERFORM VISUAL INSPECTION. INSPECT MAIN TRACK HINGE FITTINGS ON TRACK AND FLAP BOX SIDES.							Service	ATA:57
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 57 - WINGS										
P5710001	^S	* WING DRAG LINK ATTACH FITTING - PERFORM MAGNETIC PARTICLE INSPECTION							Service	ATA:57
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0								
PROC. REF: NDT PART 7/57-30-02PROC. REF: NDT PART 7/57-30-02										
PKG:22										
P5710007	^S	* WING TO FUSELAGE ATTACH FITTINGS AND LINKS - PERFORM EDDY CURRENT INSPECTION							Service	ATA:57
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0								
PROC. REF: NDT PART 6/57-10-12PROC. REF: NDT PART 6/57-10-12										
PKG:25										
P5710015	^S	* WING BOX REAR SPAR AT AILERON HINGE - PERFORM EDDY CURRENT INSPECTION							Service	ATA:57
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0								
PROC. REF: NDT PART 6/57-10-20PROC. REF: NDT PART 6/57-10-20										
PKG:25										
P5710018	^S	* WING LOWER SKIN AT MID SPAR SPAN WISE JOINT - PERFORM EDDY CURRENT INSPECTION.							Service	ATA:57
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								
PROC. REF: NDT PART 6/57-10-09PROC. REF: NDT PART 6/57-10-09										
PKG:26										
P5710024	^S	* WING REAR SPAR SIDE STAY FITTING SUPPORT STRUCTURE - PERFORM EDDY CURRENT INSPECTION.							Service	ATA:57
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0								
PROC. REF: NDT PART 6/57-20-06PROC. REF: NDT PART 6/57-20-06										
PKG:25										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 57 - WINGS										
P5710025	S	* WING FRONT SPAR LOWER CAP FROM WS 33.0 TO WS 60.0 - PERFORM RADIOGRAPHIC INSPECTION						Service	ATA:57	
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0							PKG:22	
PROC. REF: NDT PART 2/57-10-01PROC. REF: NDT PART 2/57-10-01										
P5710029	S	* WING MID-SPAR VERTICAL WEB - PERFORM EDDY CURRENT INSPECTION						Service	ATA:57	
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276							PKG:26	
PROC. REF: NDT PART 6/57-10-07PROC. REF: NDT PART 6/57-10-07										
P5710030	S	* WING REAR SPAR VERTICAL WEB - PERFORM EDDY CURRENT INSPECTION						Service	ATA:57	
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276							PKG:26	
PROC. REF: NDT PART 6/57-20-05PROC. REF: NDT PART 6/57-20-05										
P5710032	S	* WING RIB UPPER AFT FLANGE FILLET RADIUS AT WS 33.0 - PERFORM ULTRASONIC INSPECTION						Service	ATA:57	
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0							PKG:25	
PROC. REF: NDT PART 4/57-30-02PROC. REF: NDT PART 4/57-30-02										
P5710033	S	* WING ACCESS HOLE IN CLOSING RIB BETWEEN MID AND REAR SPAR - PERFORM EDDY CURRENT INSPECTION						Service	ATA:57	
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0							PKG:25	
PROC. REF: NDT PART 6/57-10-05PROC. REF: NDT PART 6/57-10-05										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 57 - WINGS										
P5710034	^S	* WING BOX JOINT TO WINGLET - PERFORM EDDY CURRENT INSPECTION							Service	ATA:57
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0		T:9600						
	AFL	0								
PROC. REF: NDT PART 6/57-10-13PROC. REF: NDT PART 6/57-10-13										
PKG:25										
P5710083	^S	* FLAP BOX BASIC STRUCTURE - PERFORM EDDY CURRENT INSPECTION							Service	ATA:57
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0		T:9600						
	AFL	0								
PROC. REF: NDT PART 6/57-40-02PROC. REF: NDT PART 6/57-40-02										
PKG:25										
P5710085	^S	SPOILER UPPER SKIN - PERFORM EDDY CURRENT INSPECTION							Service	ATA:57
	MOS	09-Mar-01								
	HRS	0		T:9600						
	AFL	0								
PROC. REF: NDT PART 6/57-10-16PROC. REF: NDT PART 6/57-10-16										
PKG:25										
P5710086	^S	SPOILER BOLTS AND HINGE PINS - PERFORM MAGNETIC PARTICLE INSPECTION							Service	ATA:57
	MOS	09-Mar-01								
	HRS	0		T:9600						
	AFL	0								
PROC. REF: NDT PART 7/27-10-01PROC. REF: NDT PART 7/27-10-01										
PKG:25										
P5710181	^S	* WING DRAG LINK TUBE - PERFORM MAGNETIC PARTICLE INSPECTION							Service	ATA:57
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0		T:9600						
	AFL	0								
PROC. REF: NDT PART 7/57-30-01PROC. REF: NDT PART 7/57-30-01										
PKG:22										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 57 - WINGS										
P5710182 ^S			* WING DRAG LINK ATTACH BOLTS - PERFORM LIQUID PENETRANT INSPECTION							Service ATA:57
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0		T:9600						
	AFL	0								
PROC. REF: NDT PART 8/57-10-01PROC. REF: NDT PART 8/57-10-01										
PKG:22										
P5710183 ^S			* WING DRAG LINK ATTACH CLEVIS - PERFORM MAGNETIC PARTICLE INSPECTION							Service ATA:57
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0		T:9600						
	AFL	0								
PROC. REF: NDT PART 7/57-10-01PROC. REF: NDT PART 7/57-10-01										
PKG:22										
P5710184 ^S			* WING ATTACH BOLTS - PERFORM FLUORESCENT PENETRANT INSPECTION							Service ATA:57
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0		T:9600						
	AFL	0								
PROC. REF: NDT PART 8/57-10-02PROC. REF: NDT PART 8/57-10-02										
PKG:25										
P5710185 ^S			* WING ATTACH LINKS - PERFORM MAGNETIC PARTICLE INSPECTION							Service ATA:57
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0		T:9600						
	AFL	0								
PROC. REF: NDT PART 7/57-10-03PROC. REF: NDT PART 7/57-10-03										
PKG:25										
P5710186 ^S			* WING ATTACH FITTINGS AT MID SPAR AND REAR SPAR - PERFORM MAGNETIC PARTICLE INSPECTION							Service ATA:57
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0		T:9600						
	AFL	0								
PROC. REF: NDT PART 7/57-10-02PROC. REF: NDT PART 7/57-10-02										
PKG:25										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 57 - WINGS										
P5750002	^S	* FLAP FRONT SPAR CUTOUTS - PERFORM EDDY CURRENT INSPECTION							Service	ATA:57
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0								
PROC. REF: NDT PART 6/57-10-15PROC. REF: NDT PART 6/57-10-15										
P5750003	^S	* FLAP NOSE ROLLER RIBS - PERFORM EDDY CURRENT INSPECTION							Service	ATA:57
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0								
PROC. REF: NDT PART 6/57-10-14PROC. REF: NDT PART 6/57-10-14										
P5750004	^S	* FLAP ACTUATOR SUPPORT RIBS - PERFORM EDDY CURRENT INSPECTION							Service	ATA:57
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								
PROC. REF: NDT PART 6/57-10-21PROC. REF: NDT PART 6/57-10-21										
P5750048	^S	* FLAP TRACKS - PERFORM MAGNETIC PARTICLE INSPECTION							Service	ATA:57
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								
PROC. REF: NDT PART 7/57-71-01PROC. REF: NDT PART 7/57-71-01										
P5750049	^S	* FLAP NOSE ROLLER TRACKS - PERFORM MAGNETIC PARTICLE INSPECTION WITH FLAPS REMOVED							Service	ATA:57
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								
PROC. REF: NDT PART 7/57-10-04PROC. REF: NDT PART 7/57-10-04										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 57 - WINGS										
P5750053	^S	* FLAP TRACK SUPPORT RIBS - PERFORM EDDY CURRENT INSPECTION							Service	ATA:57
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								
PROC. REF: NDT PART 6/57-10-17PROC. REF: NDT PART 6/57-10-17										
PKG:26										
P5750068	^S	* FLAP FRONT-SPAR RIB SUPPORT STRUCTURE - PERFORM EDDY CURRENT INSPECTION							Service	ATA:57
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0								
PROC. REF: NDT PART 6/57-10-26PROC. REF: NDT PART 6/57-10-26										
PKG:25										
P5760000	^S	* AILERON ACTUATOR HINGE FITTING - PERFORM EDDY CURRENT INSPECTION							Service	ATA:57
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								
PROC. REF: NDT PART 6/57-10-25PROC. REF: NDT PART 6/57-10-25										
PKG:26										
P5760001	^S	* AILERON SKIN - PERFORM EDDY CURRENT INSPECTION							Service	ATA:57
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								
PROC. REF: NDT PART 6/57-10-19PROC. REF: NDT PART 6/57-10-19										
PKG:26										
P5760002	^S	* AILERON BALANCE TAB HINGE FITTINGS - PERFORM EDDY CURRENT INSPECTION							Service	ATA:57
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0								
PROC. REF: NDT PART 6/57-60-01PROC. REF: NDT PART 6/57-60-01										
PKG:22										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 57 - WINGS										
P5760003	^S	* AILERON TRIM AND BALANCE TAB FRONT SPARS - PERFORM RADIOGRAPHIC INSPECTION						Service	ATA:57	
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0								
PROC. REF: NDT PART 2/57-60-01PROC. REF: NDT PART 2/57-60-01										
P5760005	^S	* AILERON HINGE LUGS AND FITTINGS - PERFORM EDDY CURRENT INSPECTION						Service	ATA:57	
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								
PROC. REF: NDT PART 6/57-10-24PROC. REF: NDT PART 6/57-10-24										
P5760014	^S	* AILERON HINGE SUPPORT STRUCTURE - PERFORM EDDY CURRENT INSPECTION						Service	ATA:57	
	MOS	02-Aug-24						AIRWORTHINESS		
	HRS	9525.7	9600							
	AFL	7276								
PROC. REF: NDT PART 6/57-10-23PROC. REF: NDT PART 6/57-10-23										
P5770000	^S	SPOILER HINGE ASSEMBLIES AND ACTUATOR FITTING - PERFORM EDDY CURRENT INSPECTION						Service	ATA:57	
	MOS	09-Mar-01								
	HRS	0	T:9600							
	AFL	0								
PROC. REF: NDT PART 6/57-10-22PROC. REF: NDT PART 6/57-10-22										
Q5710156	^S	* WING BOX BASIC SKIN/STRINGER, LOWER SKIN - PERFORM VISUAL INSPECTION. INSPECT OUTBOARD WING FORWARD AND AFT LOWER SKIN PANELS AND STRINGERS.						Service	ATA:57	
	MOS/MSC	09-Mar-01	N/A							
	HRS	0								
	AFL	0								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
Q5710162	S	* WING BOX FRONT SPAR LOWER CAP - PERFORM VISUAL INSPECTION. INSPECT FRONT SPAR LOWER CAP AND LOWER FORWARD SKIN OUTBOARD OF MID-SPAR STATION (MS) 55.						Service	ATA:57
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							PKG:22
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
Q5710166	S	* WING BOX MID SPAR, OUTBOARD OF RIB NO. 8 - PERFORM VISUAL INSPECTION AT WS 156 AND OUTBOARD TO WS 260						Service	ATA:57
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							PKG:22
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
Q5710167	S	* WING BOX REAR SPAR, OUTBOARD OF RIB NO. 6 - PERFORM VISUAL INSPECTION AT WS 118 AND OUTBOARD TO WS 260						Service	ATA:57
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							PKG:22
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
U5710147	S	* WING BOX MID SPAR LOWER CAP, OUTBOARD OF JOINT AT WS 137 BETWEEN RIB NO. 7 AND NO. 8 - PERFORM DETAILED VISUAL INSPECTION. INSPECT MID SPAR LOWER CAP AND LOWER SKIN PANELS.						Service	ATA:57
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							PKG:10
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
U5710154	S	* WING BOX REAR SPAR LOWER CAP OUTBOARD OF JOINT AT WS 81 TO RIB NO. 6 - PERFORM DETAILED VISUAL INSPECTION. INSPECT OUTER REAR SPAR LOWER CAP AND AFT LOWER SKIN PANEL OUTBOARD OF REAR SPLICE AT WS 90.						Service	ATA:57
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							PKG:10
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 57 - WINGS										
V5710039 ^S	WINGLET SKIN - PERFORM EDDY CURRENT INSPECTION								Service	ATA:57
	MOS	09-Mar-01								
	HRS	0	T:9600							
	AFL	0								
PROC. REF: NDT PART 6/57-10-18PROC. REF: NDT PART 6/57-10-18										
PKG:25										
Y5700001 ^S	WINGLET - PERFORM VISUAL INSPECTION								Service	ATA:57
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
PKG:4										
Y5700002 ^S	FLUX VALVE BRACKET - VISUALLY INSPECT FOR CRACKS								Service	ATA:57
	MOS	09-Mar-01	12							
	HRS	0	300							
	AFL	0								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
PKG:4										
Y5710000 ^S	WING - PERFORM EXTERNAL VISUAL INSPECTION FROM BL 0.00 TO WS 260								Service	ATA:57
	MOS	09-Mar-01	48							
	HRS	0	1200							
	AFL	0								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
PKG:16										
Y5710180 ^S	EXTERNAL LOWER WING SKIN - PERFORM VISUAL INSPECTION								Service	ATA:57
	MOS	02-Aug-24	24							
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
PKG:10										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 57 - WINGS										
Y5730013 ^S	AILERON BRUSH SEALS - PERFORM DETAILED INSPECTION								Service	ATA:57
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 57-60-01PROC. REF: AMM 57-60-01										
Y5750067 ^S	FLAP BRACKETS - PERFORM DETAILED VISUAL INSPECTION								Service	ATA:57
	MOS	25-Nov-19	96							
	HRS	8177.7	2400							
	AFL	6303								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
Y5750069 ^S	FLAPS - PERFORM VISUAL INSPECTION OF FLAP NOSE ROLLERS, FLAP TRACKS, FLAP NOSE ROLLER TRACKS, AND FLAP MAIN TRACK ROLLERS.								Service	ATA:57
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
Y5750071 ^S	FLAPS - WITH FLAPS REMOVED, PERFORM DETAILED VISUAL INSPECTION OF FLAP NOSE ROLLERS, FLAP TRACKS, FLAP NOSE ROLLER TRACKS, AND FLAP MAIN TRACK ROLLERS.								Service	ATA:57
	MOS	09-Mar-01	48							
	HRS	0	1200							
	AFL	0								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
ATA 71 - POWER PLANT										
710100	NO. 1 ENGINE - MAIN ENGINE WIRING HARNESS ASSEMBLY								Component	ATA:71
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-00-02, LMM 72-00-02PROC. REF: LMM 72-00-02, LMM 72-00-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 71 - POWER PLANT										
710100	NO. 2 ENGINE - MAIN ENGINE WIRING HARNESS ASSEMBLY								Component	ATA:71
PN:3060757-3	MOS/MSC	06-Jul-23	O/C	TSN 0						
SN:22-129505-00163	HRS	8350.6		TSN 0						
	ENC	6943		TSN 0						
PROC. REF: LMM 72-00-02, LMM 72-00-02PROC. REF: LMM 72-00-02, LMM 72-00-02										
710130 ^S	NO. 1 ENGINE - INSPECT TAILPIPE/LPT3 ROTOR ASSEMBLY-VISUALLY INSPECT FOR FOREIGN OBJECT DAMAGE, THERMAL DISTRESS, AND LEAKS.								Service	ATA:71
	MOS	21-Aug-25								
	HRS	9735.7	800							
	ENC	7413								
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00										
710130 ^S	NO. 2 ENGINE - INSPECT TAILPIPE/LPT3 ROTOR ASSEMBLY-VISUALLY INSPECT FOR FOREIGN OBJECT DAMAGE, THERMAL DISTRESS, AND LEAKS.								Service	ATA:71
	MOS	21-Aug-25								
	HRS	8897	800							
	ENC	7309								
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00										
710140 ^S	NO. 1 ENGINE - INSPECT INLET/FAN AREA - INSPECT FOR FOREIGN OBJECT DAMAGE AND LEAKAGE (REFER TO PARAGRAPH 4.B)								Service	ATA:71
	MOS	21-Aug-25								
	HRS	9735.7	800							
	ENC	7413								
PROC. REF: LMM 72-00-00, LMM 72-00-00PROC. REF: LMM 72-00-00, LMM 72-00-00										
710140 ^S	NO. 2 ENGINE - INSPECT INLET/FAN AREA - INSPECT FOR FOREIGN OBJECT DAMAGE AND LEAKAGE (REFER TO PARAGRAPH 4.B)								Service	ATA:71
	MOS	21-Aug-25								
	HRS	8897	800							
	ENC	7309								
PROC. REF: LMM 72-00-00, LMM 72-00-00PROC. REF: LMM 72-00-00, LMM 72-00-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 71 - POWER PLANT										
711001	NO. 1 ENGINE FORWARD MOUNT								Component	ATA:71
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00										
711002	NO. 2 ENGINE FORWARD MOUNT								Component	ATA:71
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00										
7120005 ^U	CHANGE NO. 2 ALL								Service	ATA:71
	MOS/MSC		N/A							
	HRS									
	AFL									
7120005 ^U	REPLACE NO. 2 ENGINE AFT ENGINE MOUNT ISOLATOR BONDED MOUNTING								Service	ATA:71
	MOS/MSC	26-Jul-23	N/A	TAC 0						
	HRS	9278		TAC 0						
	AFL	7111		TAC 0						
7120006	REPLACE NO. 1 ENGINE ALL ENGINE MOUNT ISOLATOR FORWARD BONDED MOUNTING								Service	ATA:71
	MOS/MSC	09-Mar-01	N/A	TAC 0						
	HRS	0		TAC 0						
	AFL	0		TAC 0						
7120006 ^U	REPLACE NO. 2 ENGINE AFT ENGINE MOUNT ISOLATOR BONDED MOUNTING								Service	ATA:71
	MOS/MSC	09-Mar-01	N/A	TAC 0						
	HRS	0		TAC 0						
	AFL	0		TAC 0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 71 - POWER PLANT									
7120006	U	REPLACE NO. 2 ENGINE ALL ENGINE MOUNT ISOLATOR FORWARD BONDED MOUNTING						Service	ATA:71
	MOS/MSC	09-Mar-01	N/A	TAC	0				
	HRS	0		TAC	0				
	AFL	0		TAC	0				
<hr/>									
712005		NO. 1 ENGINE - AFT ENGINE MOUNT - ISOLATOR ASSEMBLY						Component	ATA:71
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN	0				
SN:UNKNOWN	HRS	0		TSN	0				
	AFL	0		TSN	0				
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
<hr/>									
712006		NO. 2 ENGINE - AFT ENGINE MOUNT - ISOLATOR ASSEMBLY						Component	ATA:71
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN	0				
SN:UNKNOWN	HRS	0		TSN	0				
	AFL	0		TSN	0				
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
<hr/>									
7120069	U	NO. 1 ALL						Service	ATA:71
	MOS/MSC	26-Jul-23	N/A						
	HRS	9278							
	AFL	7111							
<hr/>									
7120069	U	NO. 2 ALL						Service	ATA:71
	MOS/MSC	26-Jul-23	N/A						
	HRS	9278							
	AFL	7111							
<hr/>									
712007		NO. 1 ENGINE - FORWARD ENGINE MOUNT - UPPER ISOLATOR ASSEMBLY						Component	ATA:71
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN	0				
SN:UNKNOWN	HRS	0		TSN	0				
	AFL	0		TSN	0				
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 71 - POWER PLANT									
7120070 ^U CHANGE NO. 1 ALL Service ATA:71									
	MOS	26-Jul-23		TAC 0				LIFE LIMIT	
	HRS	9278	6000	TAC 0	15278		5254.9		
	AFL	7111		TAC 0					
7120070 ^U CHANGE NO. 2 ALL Service ATA:71									
	MOS	26-Jul-23		TAC 0				LIFE LIMIT	
	HRS	9278	6000	TAC 0	15278		5254.9		
	AFL	7111		TAC 0					
7120070 ^U REPLACE NO. 2 ENGINE AFT ENGINE MOUNT ISOLATOR BONDED MOUNTING Service ATA:71									
	MOS/MSC	26-Jul-23	O/C	TAC 0				LIFE LIMIT	
	HRS	9278		TAC 0					
	AFL	7111		TAC 0					
7120073 ^U NO. 1 ALL Service ATA:71									
	MOS	26-Jul-23							
	HRS	9278	6000		15278		5254.9		
	AFL	7111							
7120073 ^U NO. 2 ALL Service ATA:71									
	MOS	26-Jul-23							
	HRS	9278	6000		15278		5254.9		
	AFL	7111							
712008 NO. 2 ENGINE - FORWARD ENGINE MOUNT - UPPER ISOLATOR ASSEMBLY Component ATA:71									
PN:LM833-SA20-5	MOS/MSC	26-Sep-06	O/C						
SN:LK3128	HRS	4857.22							
	AFL	3730							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 71 - POWER PLANT										
712009		NO. 1 ENGINE - FORWARD ENGINE MOUNT - LOWER ISOLATOR ASSEMBLY						Component	ATA:71	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00										
712010		NO. 2 ENGINE - FORWARD ENGINE MOUNT - LOWER ISOLATOR ASSEMBLY						Component	ATA:71	
PN:KM833-SA20-5	MOS/MSC	26-Sep-06	O/C	TSN 0						
SN:LK3185	HRS	4857.22		TSN 0						
	AFL	3730		TSN 0						
PROC. REF: NDT PART 7/32-10-08, NDT PART 7/32-10-03, NDT PART 7/32-10-04, NDT PART 8/32-10-02, NDT PART 8/54-30-01, NDT PART 8/54-30-02, AMM 71-20-00PROC. REF: NDT PART 7/32-10-08, NDT PART 7/32-10-03, NDT PART 7/32-10-04, NDT PART 8/32-10-02, NDT PART 8/54-30-01, NDT PART 8/54-30-02, AMM 71-20-00										
712045		NO. 1 ENGINE AFT MOUNT						Component	ATA:71	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00										
712046		NO. 2 ENGINE AFT MOUNT						Component	ATA:71	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00										
712078		NO. 1 ENGINE AFT MOUNT BOLT						Component	ATA:71	
PN:4571408525-001	MOS/MSC	26-Jul-23	E/C	TSN 0				AIRWORTHINESS		
SN:UNKNOWN	HRS	9278		TSN 0						
	AFL	7111		TSN 0						
712079		NO. 2 ENGINE AFT MOUNT BOLT						Component	ATA:71	
PN:4571408525-001	MOS/MSC	26-Jul-23	E/C	TSN 0				AIRWORTHINESS		
SN:UNKNOWN	HRS	9278		TSN 0						
	AFL	7111		TSN 0						
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 71 - POWER PLANT										
714010 ^S			NO. 1 ENGINE - CHECK ELECTRICAL WIRES AND CONNECTIONS - VISUALLY INSPECT FOR SECURITY AND DAMAGE						Service	ATA:71
	MOS		21-Aug-25							
	HRS		9735.7		800					
	ENC		7413							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00										
714010 ^S			NO. 2 ENGINE - CHECK ELECTRICAL WIRES AND CONNECTIONS - VISUALLY INSPECT FOR SECURITY AND DAMAGE						Service	ATA:71
	MOS		21-Aug-25							
	HRS		8897		800					
	ENC		7309							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00										
715010 ^S			NO. 1 ENGINE - CHECK PLUMBING LINES AND CONNECTIONS - VISUALLY INSPECT FOR SECURITY, LOOSE OR BROKEN CLAMPS OR BRACKETS, LEAKS, CRACKS, CUTS, OR RUBBING						Service	ATA:71
	MOS		21-Aug-25							
	HRS		9735.7		800					
	ENC		7413							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00										
715010 ^S			NO. 2 ENGINE - CHECK PLUMBING LINES AND CONNECTIONS - VISUALLY INSPECT FOR SECURITY, LOOSE OR BROKEN CLAMPS OR BRACKETS, LEAKS, CRACKS, CUTS, OR RUBBING						Service	ATA:71
	MOS		21-Aug-25							
	HRS		8897		800					
	ENC		7309							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00										
716005			NO. 1 ENGINE INLET NACELLE						Component	ATA:71
PN:4572290001-801	MOS/MSC		16-Jul-19		O/C					
SN:145LH	HRS		8109							
	AFL		6239							
PROC. REF: AMM 71-10-01PROC. REF: AMM 71-10-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 71 - POWER PLANT

716006	NO. 2 ENGINE INLET NACELLE							Component	ATA:71
PN:2652000V24-003	MOS/MSC	02-Dec-09	O/C		TSR 0				
SN:114RH	HRS	6213.6			TSR 0				
	AFL	4758			TSR 0				
PROC. REF: AMM 71-10-01PROC. REF: AMM 71-10-01									

71EN1	NO. 1 ENGINE							Component	ATA:71
PN:3060082-2	MOS/MSC		E/C						
SN:P-116284C	HRS								
	AFL								
Special Properties: RII ITEM									
PROC. REF: SIL F731-88, AMM 71-00-01PROC. REF: SIL F731-88, AMM 71-00-01									

71EN2	NO. 2 ENGINE							Component	ATA:71
PN:3060084-2	MOS/MSC	12-Aug-15	E/C						
SN:P-116285C	HRS	7535.1			TSN 6622.3				
	AFL	5764							
Special Properties: RII ITEM									
PROC. REF: SIL F731-88, AMM 71-00-01PROC. REF: SIL F731-88, AMM 71-00-01									

AA7120069	NO. 1 ENGINE - AFT ENGINE MOUNT - ISOLATOR ASSEMBLY - PERFORM VISUAL INSPECTION OF FORWARD AND AFT ISOLATORS AND ASSOCIATED PARTS							Service	ATA:71
	MOS	26-Jul-23							
	HRS	9278	3000		12278		2254.9		
	AFL	7111							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									

AA7120069	NO. 1 ENGINE - FORWARD ENGINE MOUNT - LOWER ISOLATOR ASSEMBLY - PERFORM VISUAL INSPECTION OF FORWARD AND AFT ISOLATORS AND ASSOCIATED PARTS							Service	ATA:71
	MOS	26-Jul-23							
	HRS	9278	3000		12278		2254.9		
	AFL	7111							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 71 - POWER PLANT										
AA7120069	NO. 1 ENGINE - FORWARD ENGINE MOUNT - UPPER ISOLATOR ASSEMBLY - PERFORM VISUAL INSPECTION OF FORWARD AND AFT ISOLATORS AND ASSOCIATED PARTS								Service	ATA:71
	MOS	26-Jul-23								
	HRS	9278	3000		12278		2254.9			
	AFL	7111								
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00										
AA7120069	NO. 2 ENGINE - AFT ENGINE MOUNT - ISOLATOR ASSEMBLY - PERFORM VISUAL INSPECTION OF FORWARD AND AFT ISOLATORS AND ASSOCIATED PARTS								Service	ATA:71
	MOS	26-Jul-23								
	HRS	9278	3000		12278		2254.9			
	AFL	7111								
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00										
AA7120069	NO. 2 ENGINE - FORWARD ENGINE MOUNT - LOWER ISOLATOR ASSEMBLY - PERFORM VISUAL INSPECTION OF FORWARD AND AFT ISOLATORS AND ASSOCIATED PARTS								Service	ATA:71
PN:KM833-SA20-5	MOS	26-Jul-23								
SN:LK3185	HRS	9278	3000		12278		2254.9			
	AFL	7111								
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00										
AA7120069	NO. 2 ENGINE - FORWARD ENGINE MOUNT - UPPER ISOLATOR ASSEMBLY - PERFORM VISUAL INSPECTION OF FORWARD AND AFT ISOLATORS AND ASSOCIATED PARTS								Service	ATA:71
PN:LM833-SA20-5	MOS	26-Jul-23								
SN:LK3128	HRS	9278	3000		12278		2254.9			
	AFL	7111								
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00										
AD7120005	NO. 1 ENGINE - FORWARD ENGINE MOUNT - LOWER ISOLATOR ASSEMBLY - REPLACE BONDED MOUNTING								Service	ATA:71
	MOS/MSC	26-Jul-23	N/A	TAC 0						
	HRS	9278		TAC 0						
	AFL	7111		TAC 0						
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00										
AD7120005	NO. 1 ENGINE - FORWARD ENGINE MOUNT - UPPER ISOLATOR ASSEMBLY - REPLACE BONDED MOUNTING								Service	ATA:71
	MOS/MSC	26-Jul-23	N/A	TAC 0						
	HRS	9278		TAC 0						
	AFL	7111		TAC 0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 71 - POWER PLANT

PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00

AD7120005 NO. 2 ENGINE - FORWARD ENGINE MOUNT - LOWER ISOLATOR ASSEMBLY - REPLACE BONDED MOUNTING Service ATA:71									
PN:KM833-SA20-5	MOS/MSC	26-Jul-23	N/A	TAC 0					
SN:LK3185	HRS	9278		TAC 0					
	AFL	7111		TAC 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									

AD7120005 NO. 2 ENGINE - FORWARD ENGINE MOUNT - UPPER ISOLATOR ASSEMBLY - REPLACE BONDED MOUNTING Service ATA:71									
PN:LM833-SA20-5	MOS/MSC	26-Jul-23	N/A	TAC 0					
SN:LK3128	HRS	9278		TAC 0					
	AFL	7111		TAC 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									

AD7120005 ^U REPLACE NO. 1 ENGINE AFT ENGINE MOUNT ISOLATOR FORWARD BONDED MOUNTING Service ATA:71									
	MOS/MSC	26-Jul-23	N/A	TAC 0					
	HRS	9278		TAC 0					
	AFL	7111		TAC 0					

AD7120005 REPLACE NO. 1 ENGINE ALL ENGINE MOUNT ISOLATOR BONDED MOUNTING Service ATA:71									
	MOS/MSC	27-Sep-06	N/A						
	HRS	4857.2							
	AFL	3730							

AD7120006 NO. 1 ENGINE - FORWARD ENGINE MOUNT - LOWER ISOLATOR ASSEMBLY - REPLACE BONDED MOUNTING Service ATA:71									
	MOS/MSC	09-Mar-01	N/A	TAC 0					
	HRS	0		TAC 0					
	AFL	0		TAC 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									

AD7120006 NO. 1 ENGINE - FORWARD ENGINE MOUNT - UPPER ISOLATOR ASSEMBLY - REPLACE BONDED MOUNTING Service ATA:71									
	MOS/MSC	09-Mar-01	N/A	TAC 0					
	HRS	0		TAC 0					
	AFL	0		TAC 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 71 - POWER PLANT									
AD7120006 NO. 2 ENGINE - FORWARD ENGINE MOUNT - LOWER ISOLATOR ASSEMBLY - REPLACE BONDED MOUNTING Service ATA:71									
	MOS/MSC	09-Mar-01	N/A	TAC 0					
	HRS	0		TAC 0					
	AFL	0		TAC 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
AD7120006 NO. 2 ENGINE - FORWARD ENGINE MOUNT - UPPER ISOLATOR ASSEMBLY - REPLACE BONDED MOUNTING Service ATA:71									
	MOS/MSC	09-Mar-01	N/A	TAC 0					
	HRS	0		TAC 0					
	AFL	0		TAC 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
AD7120006 ^U REPLACE NO. 1 ENGINE AFT ENGINE MOUNT ISOLATOR BONDED MOUNTING Service ATA:71									
	MOS/MSC	09-Mar-01	N/A	TAC 0					
	HRS	0		TAC 0					
	AFL	0		TAC 0					
AD7120070 NO. 1 ENGINE - FORWARD ENGINE MOUNT - LOWER ISOLATOR ASSEMBLY - REPLACE BONDED MOUNTING Service ATA:71									
	MOS	26-Jul-23		TAC 0				LIFE LIMIT	
	HRS	9278	6000	TAC 0	15278		5254.9		
	AFL	7111		TAC 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
AD7120070 NO. 1 ENGINE - FORWARD ENGINE MOUNT - UPPER ISOLATOR ASSEMBLY - REPLACE BONDED MOUNTING Service ATA:71									
	MOS	26-Jul-23		TAC 0				LIFE LIMIT	
	HRS	9278	6000	TAC 0	15278		5254.9		
	AFL	7111		TAC 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
AD7120070 NO. 2 ENGINE - FORWARD ENGINE MOUNT - LOWER ISOLATOR ASSEMBLY - REPLACE BONDED MOUNTING Service ATA:71									
PN:KM833-SA20-5	MOS	26-Jul-23		TAC 0				LIFE LIMIT	
SN:LK3185	HRS	9278	6000	TAC 0	15278		5254.9		
	AFL	7111		TAC 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 71 - POWER PLANT									
AD7120070 NO. 2 ENGINE - FORWARD ENGINE MOUNT - UPPER ISOLATOR ASSEMBLY - REPLACE BONDED MOUNTING									
PN:LM833-SA20-5	MOS	26-Jul-23		TAC 0				LIFE LIMIT	Service ATA:71
SN:LK3128	HRS	9278	6000	TAC 0	15278		5254.9		
	AFL	7111		TAC 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
AD7120070 ^U REPLACE NO. 1 ENGINE AFT ENGINE MOUNT ISOLATOR BONDED MOUNTING									
	MOS/MSC	26-Jul-23	O/C	TAC 0				LIFE LIMIT	Service ATA:71
	HRS	9278		TAC 0					
	AFL	7111		TAC 0					
AD7120075 NO. 1 ENGINE - AFT ENGINE MOUNT - ISOLATOR ASSEMBLY - PERFORM DETAILED INSPECTION OF AFT ISOLATOR ASSEMBLY AND ASSOCIATED PARTS									
	MOS/MSC	26-Jul-23	MPI						Service ATA:71
	HRS	9278	3600		12878		2854.9		
	AFL	7111							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
AD7120075 NO. 2 ENGINE - AFT ENGINE MOUNT - ISOLATOR ASSEMBLY - PERFORM DETAILED INSPECTION OF AFT ISOLATOR ASSEMBLY AND ASSOCIATED PARTS									
	MOS/MSC	26-Jul-23	MPI						Service ATA:71
	HRS	9278	3600		12878		2854.9		
	AFL	7111							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
K7120004 NO. 1 ENGINE - AFT ENGINE MOUNT - ISOLATOR ASSEMBLY - REPLACE HOUSING									
	MOS	09-Mar-01		TAC 0				LIFE LIMIT	Service ATA:71
	HRS	0	15000	TAC 0	15000		4976.9		
	AFL	0		TAC 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
K7120004 NO. 1 ENGINE - FORWARD ENGINE MOUNT - LOWER ISOLATOR ASSEMBLY - REPLACE HOUSING									
	MOS	09-Mar-01		TAC 0				LIFE LIMIT	Service ATA:71
	HRS	0	15000	TAC 0	15000		4976.9		
	AFL	0		TAC 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 71 - POWER PLANT										
K7120004	NO. 1 ENGINE - FORWARD ENGINE MOUNT - UPPER ISOLATOR ASSEMBLY - REPLACE HOUSING								Service	ATA:71
	MOS	09-Mar-01		TAC 0				LIFE LIMIT		
	HRS	0	15000	TAC 0	15000		4976.9			
	AFL	0		TAC 0						
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00										
K7120004	NO. 2 ENGINE - AFT ENGINE MOUNT - ISOLATOR ASSEMBLY - REPLACE HOUSING								Service	ATA:71
	MOS	09-Mar-01		TAC 0				LIFE LIMIT		
	HRS	0	15000	TAC 0	15000		4976.9			
	AFL	0		TAC 0						
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00										
K7120004	NO. 2 ENGINE - FORWARD ENGINE MOUNT - LOWER ISOLATOR ASSEMBLY - REPLACE HOUSING								Service	ATA:71
	MOS	09-Mar-01		TAC 0				LIFE LIMIT		
	HRS	0	15000	TAC 0	15000		4976.9			
	AFL	0		TAC 0						
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00										
K7120004	NO. 2 ENGINE - FORWARD ENGINE MOUNT - UPPER ISOLATOR ASSEMBLY - REPLACE HOUSING								Service	ATA:71
	MOS	09-Mar-01		TAC 0				LIFE LIMIT		
	HRS	0	15000	TAC 0	15000		4976.9			
	AFL	0		TAC 0						
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00										
K7120004 ^U	REPLACE ALL FORWARD AND AFT ENGINE MOUNT ISOLATOR HOUSINGS								Service	ATA:71
	MOS	09-Mar-01		TAC 0				LIFE LIMIT		
	HRS	0	15000	TAC 0	15000		4976.9			
	AFL	0		TAC 0						
P7120001 ^S	* FORWARD ENGINE MOUNT - PERFORM EDDY CURRENT INSPECTION								Service	ATA:71
	MOS	09-Mar-01						AIRWORTHINESS		
	HRS	0	T:9600							
	AFL	0								
PROC. REF: NDT PART 6/71-10-01PROC. REF: NDT PART 6/71-10-01										

PKG:25

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 71 - POWER PLANT										
Q7110004	NO. 1 ENGINE INLET - PERFORM TAP TEST								Service	ATA:71
	MOS	02-Nov-22								
	HRS	9151.6	3000		12151.6		2128.5			
	AFL	7021								
PROC. REF: AMM 71-10-01PROC. REF: AMM 71-10-01										
Q7110004	NO. 2 ENGINE INLET - PERFORM TAP TEST								Service	ATA:71
	MOS	12-Aug-15								
	HRS	7535.1	3000		10535.1		512			
	AFL	5764								
PROC. REF: AMM 71-10-01PROC. REF: AMM 71-10-01										
Q7120002	NO. 1 ENGINE - AFT ENGINE MOUNT - ISOLATOR ASSEMBLY - PERFORM DETAILED INSPECTION OF FORWARD AND AFT ISOLATORS AND ASSOCIATED PARTS								Service	ATA:71
	MOS/MSC	26-Jul-23	N/A							
	HRS	9278								
	AFL	7111								
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00										
Q7120002	NO. 1 ENGINE - FORWARD ENGINE MOUNT - LOWER ISOLATOR ASSEMBLY - PERFORM DETAILED INSPECTION OF FORWARD AND AFT ISOLATORS AND ASSOCIATED PARTS								Service	ATA:71
	MOS/MSC	26-Jul-23	N/A							
	HRS	9278								
	AFL	7111								
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00										
Q7120002	NO. 1 ENGINE - FORWARD ENGINE MOUNT - UPPER ISOLATOR ASSEMBLY - PERFORM DETAILED INSPECTION OF FORWARD AND AFT ISOLATORS AND ASSOCIATED PARTS								Service	ATA:71
	MOS/MSC	26-Jul-23	N/A							
	HRS	9278								
	AFL	7111								
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00										
Q7120002	NO. 1 ENGINE ALL ISOLATORS - PERFORM INSPECTION OF ISOLATORS AND ASSOCIATED PARTS								Service	ATA:71
	MOS/MSC	27-Sep-06	N/A							
	HRS	4857.2								
	AFL	3730								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 71 - POWER PLANT									
Q7120002	NO. 2 ENGINE - AFT ENGINE MOUNT - ISOLATOR ASSEMBLY - PERFORM DETAILED INSPECTION OF FORWARD AND AFT ISOLATORS AND ASSOCIATED PARTS							Service	ATA:71
	MOS/MSC	26-Jul-23	N/A						
	HRS	9278							
	AFL	7111							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
Q7120002	NO. 2 ENGINE - FORWARD ENGINE MOUNT - LOWER ISOLATOR ASSEMBLY - PERFORM DETAILED INSPECTION OF FORWARD AND AFT ISOLATORS AND ASSOCIATED PARTS							Service	ATA:71
PN:KM833-SA20-5	MOS/MSC	26-Jul-23	N/A						
SN:LK3185	HRS	9278							
	AFL	7111							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
Q7120002	NO. 2 ENGINE - FORWARD ENGINE MOUNT - UPPER ISOLATOR ASSEMBLY - PERFORM DETAILED INSPECTION OF FORWARD AND AFT ISOLATORS AND ASSOCIATED PARTS							Service	ATA:71
PN:LM833-SA20-5	MOS/MSC	26-Jul-23	N/A						
SN:LK3128	HRS	9278							
	AFL	7111							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
Q7120002	NO. 2 ENGINE ALL ISOLATORS - PERFORM INSPECTION OF ISOLATORS AND ASSOCIATED PARTS							Service	ATA:71
	MOS/MSC	27-Sep-06	N/A						
	HRS	4857.2							
	AFL	3730							
Q7120073	NO. 1 ENGINE - AFT ENGINE MOUNT - ISOLATOR ASSEMBLY - PERFORM DETAILED INSPECTION OF FORWARD AND AFT ISOLATORS AND ASSOCIATED PARTS.							Service	ATA:71
	MOS	26-Jul-23							
	HRS	9278	6000		15278		5254.9		
	AFL	7111							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 71 - POWER PLANT										
Q7120073	NO. 1 ENGINE - FORWARD ENGINE MOUNT - LOWER ISOLATOR ASSEMBLY - PERFORM DETAILED INSPECTION OF FORWARD AND AFT ISOLATORS AND ASSOCIATED PARTS								Service	ATA:71
	MOS	26-Jul-23								
	HRS	9278	6000		15278		5254.9			
	AFL	7111								
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00										
Q7120073	NO. 1 ENGINE - FORWARD ENGINE MOUNT - UPPER ISOLATOR ASSEMBLY - PERFORM DETAILED INSPECTION OF FORWARD AND AFT ISOLATORS AND ASSOCIATED PARTS								Service	ATA:71
	MOS	26-Jul-23								
	HRS	9278	6000		15278		5254.9			
	AFL	7111								
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00										
Q7120073	NO. 2 ENGINE - AFT ENGINE MOUNT - ISOLATOR ASSEMBLY - PERFORM DETAILED INSPECTION OF FORWARD AND AFT ISOLATORS AND ASSOCIATED PARTS								Service	ATA:71
	MOS	26-Jul-23								
	HRS	9278	6000		15278		5254.9			
	AFL	7111								
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00										
Q7120073	NO. 2 ENGINE - FORWARD ENGINE MOUNT - LOWER ISOLATOR ASSEMBLY - PERFORM DETAILED INSPECTION OF FORWARD AND AFT ISOLATORS AND ASSOCIATED PARTS								Service	ATA:71
PN:KM833-SA20-5	MOS	26-Jul-23								
SN:LK3185	HRS	9278	6000		15278		5254.9			
	AFL	7111								
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00										
Q7120073	NO. 2 ENGINE - FORWARD ENGINE MOUNT - UPPER ISOLATOR ASSEMBLY - PERFORM DETAILED INSPECTION OF FORWARD AND AFT ISOLATORS AND ASSOCIATED PARTS.								Service	ATA:71
PN:LM833-SA20-5	MOS	26-Jul-23								
SN:LK3128	HRS	9278	6000		15278		5254.9			
	AFL	7111								
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 71 - POWER PLANT										
R7100032	LEFT ENGINE NACELLE TUBES - PERFORM DETAILED VISUAL INSPECTION								Service	ATA:71
	MOS/MSC	10-Nov-11	N/A					NOT APPLICABLE		
	HRS	6740.8								
	AFL	5145								
PROC. REF: AMM 71-10-03PROC. REF: AMM 71-10-03										
Y7100002 ^S	LOWER ENGINE COWLING - VISUALLY INSPECT LATCH CHANNELS FOR CHAFING								Service	ATA:71
	MOS	02-Aug-24	24							
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
Y7110000 ^S	ENGINE NACELLE - PERFORM VISUAL INSPECTION. INSPECT INLET BULKHEAD, STRUCTURE, PLUMBING, SKIN SPOT WELDS, ANTI-ICE OUTLET SCREEN, AND FASTENERS FOR SECURITY, CRACKS, AND GENERAL CONDITION.								Service	ATA:71
	MOS	02-Aug-24	24							
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
Y7110001 ^S	ENGINE INLET LIP AND DUCT - PERFORM VISUAL INSPECTION								Service	ATA:71
	MOS	02-Aug-24	24							
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
Y7110002 ^S	ENGINE STARTER/GENERATOR INLET AND EXHAUST DUCT AND SEALS - PERFORM VISUAL INSPECTION								Service	ATA:71
	MOS	02-Aug-24	24							
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 71 - POWER PLANT										
Y7110003 ^S	ENGINE ALTERNATOR EXHAUST DUCT AND SEALS - PERFORM VISUAL INSPECTION								Service	ATA:71
	MOS	02-Aug-24	24							
	HRS	9525.7	600							
	AFL	7276								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
Y7120000 ^S	FORWARD ENGINE MOUNTS - PERFORM VISUAL INSPECTION								Service	ATA:71
	MOS	21-Aug-25	12							
	HRS	9809.8	300							
	AFL	7471								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
ATA 72 - ENGINE										
72-AS-720005	NO. 1 ENGINE - INSPECT MAJOR PERIODIC PER MANUFACTURERS INSTRUCTIONS								Service	ATA:72
	MOS	06-Dec-17								
	HRS	7696.2	3000		(10696.2) 10724.5		701.4			
	ENC	5895								
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00										
72-AS-720005	NO. 2 ENGINE - INSPECT MAJOR PERIODIC PER MANUFACTURERS INSTRUCTIONS								Service	ATA:72
	MOS	20-Jul-15								
	HRS	6622.3	3000		(9622.3) 10489.3		466.2			
	ENC	5602								
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00										
72-AS-720006 ^S	NO. 1 ENGINE - INSPECT COMB CHAMBER PLENUM CASE INSP PER MANUFACTURERS INSTRUCTIONS								Service	ATA:72
	MOS	06-Dec-17								
	HRS	7696.2	3000							
	ENC	5895								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 72 - ENGINE										
72-AS-720006 ^S	NO. 2 ENGINE - INSPECT COMB CHAMBER PLENUM CASE INSP PER MANUFACTURERS INSTRUCTIONS								Service	ATA:72
	MOS	20-Jul-15								
	HRS	6622.3	3000							
	ENC	5602								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
72-AS-720007	NO. 1 ENGINE - INSPECT COMPRESSOR ZONE PER MANUFACTURERS INSTRUCTIONS								Service	ATA:72
	MOS	30-Oct-06								
	HRS	4857.2	6000		(10857.2) 10885.5		862.4			
	ENC	3730								
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00										
72-AS-720007	NO. 2 ENGINE - INSPECT COMPRESSOR ZONE PER MANUFACTURERS INSTRUCTIONS								Service	ATA:72
	MOS	28-Jun-06								
	HRS	3701.2	6000		(9701.2) 10568.2		545.1			
	ENC	2811								
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00										
72-AS-720008 ^S	NO. 1 ENGINE - INSPECT AGB PER MANUFACTURERS INSTRUCTIONS								Service	ATA:72
	MOS	25-Oct-06								
	HRS	4857.2	6000							
	ENC	3730								
PROC. REF: LMM 72-60-02PROC. REF: LMM 72-60-02										
72-AS-720008 ^S	NO. 2 ENGINE - INSPECT AGB PER MANUFACTURERS INSTRUCTIONS								Service	ATA:72
	MOS	05-Jun-06								
	HRS	3701.2	6000							
	ENC	3369								
PROC. REF: LMM 72-60-02PROC. REF: LMM 72-60-02										
72-AS-720010	NO. 1 ENGINE - ANALYSIS OIL AND FILTER (BASELINE/SPECIAL REQUIREMENT) (SOAP)								Service	ATA:72
	MOS/MSC	05-Jan-00	A/R							
	HRS	0								
	ENC	0								
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 72 - ENGINE										
72-AS-720010		NO. 2 ENGINE - ANALYSIS OIL AND FILTER (BASELINE/SPECIAL REQUIREMENT) (SOAP)						Service	ATA:72	
	MOS/MSC	20-Jan-16	A/R							
	HRS	6674								
	ENC	5628								
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00										
72-AS-720011		NO. 1 ENGINE - REPLACE FUEL FILTER ELEMENT (25-HR INITIAL)						Service	ATA:72	
	MOS/MSC	05-Jan-00	A/R							
	HRS	0								
	ENC	0								
PROC. REF: LMM 73-21-02PROC. REF: LMM 73-21-02										
72-AS-720011		NO. 2 ENGINE - REPLACE FUEL FILTER ELEMENT (25-HR INITIAL)						Service	ATA:72	
	MOS/MSC	15-Jan-00	A/R							
	HRS	0								
	ENC	0								
PROC. REF: LMM 73-21-02PROC. REF: LMM 73-21-02										
720110		NO. 1 ENGINE - ACCESSORY GEARBOX						Component	ATA:72	
PN:3060827-2	MOS/MSC	25-Oct-06	O/C							
SN:S986	HRS	4857.2								
	ENC	3730								
PROC. REF: LMM 72-60-02, LMM 72-60-02PROC. REF: LMM 72-60-02, LMM 72-60-02										
720110		NO. 2 ENGINE - ACCESSORY GEARBOX						Component	ATA:72	
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-60-02, LMM 72-60-02PROC. REF: LMM 72-60-02, LMM 72-60-02										
720244		NO. 1 ENGINE - NO. 6 CARBON SEAL ASSEMBLY						Component	ATA:72	
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 72 - ENGINE										
720244		NO. 2 ENGINE - NO. 6 CARBON SEAL ASSEMBLY						Component	ATA:72	
PN:3071383-2	MOS/MSC	20-Jul-15	O/C	TSN 0						
SN:13-1502111-00260	HRS	6622.3	TSN 0							
	ENC	5602	TSN 0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
<hr/>										
720245		NO. 1 ENGINE - NO. 6 BEARING ASSEMBLY						Component	ATA:72	
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
<hr/>										
720245		NO. 2 ENGINE - NO. 6 BEARING ASSEMBLY						Component	ATA:72	
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
<hr/>										
722001		NO. 1 ENGINE - FAN INLET HOUSING ASSEMBLY						Component	ATA:72	
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
<hr/>										
722001		NO. 2 ENGINE - FAN INLET HOUSING ASSEMBLY						Component	ATA:72	
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
<hr/>										
723002		NO. 1 ENGINE - NO. 3 CARBON SEAL ASSEMBLY						Component	ATA:72	
PN:3060150-3	MOS/MSC	25-Oct-06	O/C	TSN 0						
SN:061936801086	HRS	4857.2	TSN 0							
	ENC	3730	TSN 0							
PROC. REF: LMM 72-30-01, LMM 72-30-01PROC. REF: LMM 72-30-01, LMM 72-30-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 72 - ENGINE										
723002	NO. 2 ENGINE - NO. 3 CARBON SEAL ASSEMBLY								Component	ATA:72
PN:3060150-3	MOS/MSC	05-Jun-06	O/C	TSN 0						
SN:061936800093	HRS	3701.2		TSN 0						
	ENC	3369		TSN 0						
PROC. REF: LMM 72-30-01, LMM 72-30-01PROC. REF: LMM 72-30-01, LMM 72-30-01										
723010 ^S	NO. 1 ENGINE - CHECK CARBON SEAL HEALTH								Service	ATA:72
	MOS	22-Jun-23								
	HRS	9184.4	1600							
	ENC	7042								
PROC. REF: LMM 72-00-00, LMM 72-00-00PKG:0										
723010 ^S	NO. 2 ENGINE - CHECK CARBON SEAL HEALTH								Service	ATA:72
	MOS	18-Aug-22								
	HRS	8169.8	1600							
	ENC	6832								
PROC. REF: LMM 72-00-00, LMM 72-00-00PKG:0										
723011	NO. 1 ENGINE - NO. 4 CARBON SEAL RUNNER								Component	ATA:72
PN:3075639-2	MOS/MSC	25-Oct-06	O/C	TSN 0						
SN:062141803634	HRS	4857.2		TSN 0						
	ENC	3730		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
723011	NO. 2 ENGINE - NO. 4 CARBON SEAL RUNNER								Component	ATA:72
PN:3075639-2	MOS/MSC	05-Jun-06	O/C	TSN 0						
SN:052141802327	HRS	3701.2		TSN 0						
	ENC	3369		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
723012	NO. 1 ENGINE - NO. 4 CARBON SEAL ASSEMBLY								Component	ATA:72
PN:3074573-2	MOS/MSC	25-Oct-06	O/C	TSN 0						
SN:060515861210	HRS	4857.2		TSN 0						
	ENC	3730		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 72 - ENGINE										
723012		NO. 2 ENGINE - NO. 4 CARBON SEAL ASSEMBLY						Component	ATA:72	
PN:3074573-2	MOS/MSC	05-Jun-06	O/C	TSN 0						
SN:060515847790	HRS	3701.2		TSN 0						
	ENC	3369		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
<hr/>										
723013		NO. 1 ENGINE - NO. 5 CARBON SEAL RUNNER						Component	ATA:72	
PN:3075633-2	MOS/MSC	25-Oct-06	O/C	TSN 0						
SN:062141802473	HRS	4857.2		TSN 0						
	ENC	3730		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
<hr/>										
723013		NO. 2 ENGINE - NO. 5 CARBON SEAL RUNNER						Component	ATA:72	
PN:3075633-2	MOS/MSC	05-Jun-06	O/C	TSN 0						
SN:052141806990	HRS	3701.2		TSN 0						
	ENC	3369		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
<hr/>										
723014		NO. 1 ENGINE - NO. 5 CARBON SEAL ASSEMBLY						Component	ATA:72	
PN:3074574-2	MOS/MSC	25-Oct-06	O/C	TSN 0						
SN:060515859035	HRS	4857.2		TSN 0						
	ENC	3730		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
<hr/>										
723014		NO. 2 ENGINE - NO. 5 CARBON SEAL ASSEMBLY						Component	ATA:72	
PN:3074574-2	MOS/MSC	05-Jun-06	O/C	TSN 0						
SN:060515849488	HRS	3701.2		TSN 0						
	ENC	3369		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
<hr/>										
723081		NO. 1 ENGINE - ROTATING, AIR 2ND STAGE SEAL						Component	ATA:72	
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 72 - ENGINE										
723081	NO. 2 ENGINE - ROTATING, AIR 2ND STAGE SEAL								Component	ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
<hr/>										
725007	NO. 1 ENGINE - HIGH PRESSURE TURBINE (HPT) NOZZLE ASSEMBLY								Component	ATA:72
PN:3060840-3	MOS/MSC	25-Oct-06	A/R	TSN 0						
SN:UNKNOWN	HRS	4857.2		TSN 0						
WC#: 72.500	ENC	3730		TSN 0						
PROC. REF: LMM 72-50-07, LMM 72-50-07PROC. REF: LMM 72-50-07, LMM 72-50-07										
<hr/>										
725007	NO. 2 ENGINE - HIGH PRESSURE TURBINE (HPT) NOZZLE ASSEMBLY								Component	ATA:72
PN:PN	MOS/MSC	15-Jan-00	A/R	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 72.500	ENC	0		TSN 0						
PROC. REF: LMM 72-50-07, LMM 72-50-07PROC. REF: LMM 72-50-07, LMM 72-50-07										
<hr/>										
725010	NO. 1 ENGINE - 1ST-STAGE LOW PRESSURE TURBINE (LPT) DISC								Component	ATA:72
PN:3060129-7	MOS	25-Oct-06						LIFE LIMIT		
SN:00P21077	HRS	4857.2								
	ENC	3730	12000	TSN 3730	(12000) 12014		4398			
PROC. REF: LMM 72-50-04, LMM 72-50-04PROC. REF: LMM 72-50-04, LMM 72-50-04										
<hr/>										
725010	NO. 2 ENGINE - 1ST-STAGE LOW PRESSURE TURBINE (LPT) DISC								Component	ATA:72
PN:3060625-1	MOS	15-Jan-00		TSN 0				LIFE LIMIT		
SN:990322904089	HRS	0		TSN 0						
	ENC	0	12000	TSN 0	(12000) 12118		4502			
PROC. REF: LMM 72-50-04, LMM 72-50-04PROC. REF: LMM 72-50-04, LMM 72-50-04										
<hr/>										
725020	NO. 1 ENGINE - 2ND-STAGE LOW PRESSURE TURBINE (LPT) DISC								Component	ATA:72
PN:3060611-1	MOS	05-Jan-00		TSN 0				LIFE LIMIT		
SN:000322903502	HRS	0		TSN 0						
	ENC	0	12000	TSN 0	(12000) 12014		4398			

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 72 - ENGINE

PROC. REF: LMM 72-50-04, LMM 72-50-04PROC. REF: LMM 72-50-04, LMM 72-50-04

725020		NO. 2 ENGINE - 2ND-STAGE LOW PRESSURE TURBINE (LPT) DISC						Component	ATA:72
PN:3060611-1	MOS	15-Jan-00		TSN 0				LIFE LIMIT	
SN:000322903437	HRS	0		TSN 0					
	ENC	0	12000	TSN 0	(12000) 12118		4502		

PROC. REF: LMM 72-50-04, LMM 72-50-04PROC. REF: LMM 72-50-04, LMM 72-50-04

725030		NO. 1 ENGINE - 3RD-STAGE LOW PRESSURE TURBINE (LPT) DISC						Component	ATA:72
PN:3060671-2	MOS	05-Jan-00		TSN 0				LIFE LIMIT	
SN:000322900149	HRS	0		TSN 0					
	ENC	0	12000	TSN 0	(12000) 12014		4398		

PROC. REF: LMM 72-50-04, LMM 72-50-04PROC. REF: LMM 72-50-04, LMM 72-50-04

725030		NO. 2 ENGINE - 3RD-STAGE LOW PRESSURE TURBINE (LPT) DISC						Component	ATA:72
PN:3060671-2	MOS	15-Jan-00		TSN 0				LIFE LIMIT	
SN:000322900152	HRS	0		TSN 0					
	ENC	0	12000	TSN 0	(12000) 12118		4502		

PROC. REF: LMM 72-50-04, LMM 72-50-04PROC. REF: LMM 72-50-04, LMM 72-50-04

725040		NO. 1 ENGINE - HIGH PRESSURE TURBINE (HPT) DISC						Component	ATA:72
PN:3060555-5	MOS	25-Oct-06						LIFE LIMIT	
SN:061217200024	HRS	4857.2							
	ENC	3730	10000	TSN 0	(13730) 13744		6128		

PROC. REF: LMM 72-50-07, LMM 72-50-07PROC. REF: LMM 72-50-07, LMM 72-50-07

725040		NO. 2 ENGINE - HIGH PRESSURE TURBINE (HPT) DISC						Component	ATA:72
PN:3060841-1	MOS	20-Jul-15						LIFE LIMIT	
SN:041217200360	HRS	6622.3		TSN 4043.4					
	ENC	5602	10000	TSN 3645	(11957) 12075		4459		

PROC. REF: LMM 72-50-07, LMM 72-50-07PROC. REF: LMM 72-50-07, LMM 72-50-07

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 72 - ENGINE

725045		NO. 1 ENGINE - HIGH PRESSURE TURBINE (HPT) ASSY						Component	ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					

725045		NO. 2 ENGINE - HIGH PRESSURE TURBINE (HPT) ASSY						Component	ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					

725050		NO. 1 ENGINE - FAN DISC						Component	ATA:72
PN:3060287-2	MOS	05-Jan-00		TSN 0				LIFE LIMIT	
SN:030322901250	HRS	0		TSN 0					
	ENC	0	20000	TSN 0	(20000) 20014		12398		

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

725050		NO. 2 ENGINE - FAN DISC						Component	ATA:72
PN:3060287-2	MOS	15-Jan-00		TSN 0				LIFE LIMIT	
SN:010322905809	HRS	0		TSN 0					
	ENC	0	20000	TSN 0	(20000) 20118		12502		

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

725060		NO. 1 ENGINE - 1ST-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC						Component	ATA:72
PN:3060372-1	MOS	05-Jan-00		TSN 0				LIFE LIMIT	
SN:000316002316	HRS	0		TSN 0					
	ENC	0	10000	TSN 0	(10000) 10014		2398		

PROC. REF: LMM 72-30-04PROC. REF: LMM 72-30-04

725060		NO. 2 ENGINE - 1ST-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC						Component	ATA:72
PN:3060372-1	MOS	15-Jan-00		TSN 0				LIFE LIMIT	
SN:000316002319	HRS	0		TSN 0					
	ENC	0	10000	TSN 0	(10000) 10118		2502		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 72 - ENGINE

PROC. REF: LMM 72-30-04PROC. REF: LMM 72-30-04

725070		NO. 1 ENGINE - 2ND-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC						Component	ATA:72
PN:3060608-3	MOS	25-Oct-06						LIFE LIMIT	
SN:000322903502	HRS	4857.2							
	ENC	3730	10000	TSN 3730	(10000) 10014		2398		

PROC. REF: LMM 72-30-04PROC. REF: LMM 72-30-04

725070		NO. 2 ENGINE - 2ND-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC						Component	ATA:72
PN:3060373-1	MOS	15-Jan-00		TSN 0				LIFE LIMIT	
SN:000316001852	HRS	0		TSN 0					
	ENC	0	10000	TSN 0	(10000) 10118		2502		

PROC. REF: LMM 72-30-04PROC. REF: LMM 72-30-04

725071		NO. 1 ENGINE - COMBUSTION LINER						Component	ATA:72
PN:3060766-1	MOS/MSC	28-Nov-17	O/C	TSO 0					
SN:08P16345	HRS	7696.2		TSO 0					
	ENC	5895		TSO 0					

PROC. REF: LMM 72-40-03, LMM 72-40-03PROC. REF: LMM 72-40-03, LMM 72-40-03

725071		NO. 2 ENGINE - COMBUSTION LINER						Component	ATA:72
PN:3060766-1	MOS/MSC	20-Jul-15	O/C	TSO 0					
SN:06P00417	HRS	6622.3		TSO 0					
	ENC	5602		TSO 0					

PROC. REF: LMM 72-40-03, LMM 72-40-03PROC. REF: LMM 72-40-03, LMM 72-40-03

725080		NO. 1 ENGINE - 3RD-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC						Component	ATA:72
PN:3060374-1	MOS	05-Jan-00		TSN 0				LIFE LIMIT	
SN:000316002539	HRS	0		TSN 0					
	ENC	0	10000	TSN 0	(10000) 10014		2398		

PROC. REF: LMM 72-30-04PROC. REF: LMM 72-30-04

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 72 - ENGINE										
725080		NO. 2 ENGINE - 3RD-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC						Component	ATA:72	
PN:3072417-12	MOS	05-Jun-06		TSR 0				LIFE LIMIT		
SN:000316002937	HRS	3701.2		TSR 0						
	ENC	3369	10000	TSN 3369, TSR 0	(10000) 10118		2502			
PROC. REF: LMM 72-30-04PROC. REF: LMM 72-30-04										
725081		NO. 1 ENGINE - OUTER TRANSITION LINER						Component	ATA:72	
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-40-03, LMM 72-40-03PROC. REF: LMM 72-40-03, LMM 72-40-03										
725081		NO. 2 ENGINE - OUTER TRANSITION LINER						Component	ATA:72	
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-40-03, LMM 72-40-03PROC. REF: LMM 72-40-03, LMM 72-40-03										
725090		NO. 1 ENGINE - 4TH-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC						Component	ATA:72	
PN:3075326-5	MOS	05-Jan-00		TSN 0				LIFE LIMIT		
SN:001365107764	HRS	0		TSN 0						
	ENC	0	20000	TSN 0	(20000) 20014		12398			
PROC. REF: LMM 72-30-04PROC. REF: LMM 72-30-04										
725090		NO. 2 ENGINE - 4TH-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC						Component	ATA:72	
PN:3075351-12	MOS	05-Jun-06						LIFE LIMIT		
SN:050350107807	HRS	3701.2								
	ENC	3369	20000	TSN 0	(23369) 23487		15871			
PROC. REF: LMM 72-30-04PROC. REF: LMM 72-30-04										
725110		NO. 1 ENGINE - LOW PRESSURE COMPRESSOR TIE ROD						Component	ATA:72	
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 72 - ENGINE

PROC. REF: LMM 72-30-10, LMM 72-30-10PROC. REF: LMM 72-30-10, LMM 72-30-10

725110		NO. 2 ENGINE - LOW PRESSURE COMPRESSOR TIE ROD						Component	ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					

PROC. REF: LMM 72-30-10, LMM 72-30-10PROC. REF: LMM 72-30-10, LMM 72-30-10

725120		NO. 1 ENGINE - HIGH PRESSURE COMPRESSOR ROTOR IMPELLER						Component	ATA:72
PN:3060371-1	MOS	05-Jan-00		TSN 0				LIFE LIMIT	
SN:005332200378	HRS	0		TSN 0					
	ENC	0	8000	TSN 0	(8000) 8014		398		

PROC. REF: LMM 72-50-06, LMM 72-50-06PROC. REF: LMM 72-50-06, LMM 72-50-06

725120		NO. 2 ENGINE - HIGH PRESSURE COMPRESSOR ROTOR IMPELLER						Component	ATA:72
PN:3060371-1	MOS	05-Jun-06						LIFE LIMIT	
SN:060322902406	HRS	3701.2							
	ENC	3369	8000	TSN 0	(11369) 11487		3871		

PROC. REF: LMM 72-50-06, LMM 72-50-06PROC. REF: LMM 72-50-06, LMM 72-50-06

725130		NO. 1 ENGINE - FAN SPINNER						Component	ATA:72
PN:3060156-2	MOS	05-Jan-00		TSN 0				LIFE LIMIT	
SN:002428000312	HRS	0		TSN 0					
	ENC	0	20000	TSN 0	(20000) 20014		12398		

PROC. REF: LMM 72-70-01, LMM 72-70-01PROC. REF: LMM 72-70-01, LMM 72-70-01

725130		NO. 2 ENGINE - FAN SPINNER						Component	ATA:72
PN:3060156-2	MOS	15-Jan-00		TSN 0				LIFE LIMIT	
SN:002428000311	HRS	0		TSN 0					
	ENC	0	20000	TSN 0	(20000) 20118		12502		

PROC. REF: LMM 72-70-01, LMM 72-70-01PROC. REF: LMM 72-70-01, LMM 72-70-01

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 72 - ENGINE										
725140		NO. 1 ENGINE - FAN DRIVE SHAFT						Component	ATA:72	
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
725140		NO. 2 ENGINE - FAN DRIVE SHAFT						Component	ATA:72	
PN:3067021-1	MOS/MSC	23-May-07	O/C	TSN 0						
SN:970339000246	HRS	4564.4		TSN 0						
	ENC	4010		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
725160		NO. 1 ENGINE - FORWARD ROTOR HIGH PRESSURE SEAL						Component	ATA:72	
PN:3060698-1	MOS	28-Nov-17		TSN 0				LIFE LIMIT		
SN:16-162246-03040	HRS	7696.2		TSN 0						
	ENC	5895	7000	TSN 0		(12895) 12909	5293			
PROC. REF: LMM 72-70-03, LMM 72-70-03PROC. REF: LMM 72-70-03, LMM 72-70-03										
725160		NO. 2 ENGINE - FORWARD ROTOR HIGH PRESSURE SEAL						Component	ATA:72	
PN:3060698-1	MOS	20-Jul-15		TSN 0				LIFE LIMIT		
SN:14-162246-04706	HRS	6622.3		TSN 0						
	ENC	5602	7000	TSN 0		(12602) 12720	5104			
PROC. REF: LMM 72-70-03, LMM 72-70-03PROC. REF: LMM 72-70-03, LMM 72-70-03										
725170		NO. 1 ENGINE - HIGH PRESSURE SHOULDERED SHAFT						Component	ATA:72	
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
725170		NO. 2 ENGINE - HIGH PRESSURE SHOULDERED SHAFT						Component	ATA:72	
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 72 - ENGINE

725180		NO. 1 ENGINE - COMBUSTION PLENUM CASE						Component	ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-40-04, LMM 72-40-04PROC. REF: LMM 72-40-04, LMM 72-40-04									

725180		NO. 2 ENGINE - COMBUSTION PLENUM CASE						Component	ATA:72
PN:3060534-4	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:00P24979	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-40-04, LMM 72-40-04PROC. REF: LMM 72-40-04, LMM 72-40-04									

725210		NO. 1 ENGINE - HIGH PRESSURE TURBINE FORWARD SEAL PLATE						Component	ATA:72
PN:3060514-1	MOS	05-Jan-00		TSN 0				LIFE LIMIT	
SN:000322905164	HRS	0		TSN 0					
	ENC	0	10000	TSN 0	(10000) 10014		2398		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

725210		NO. 2 ENGINE - HIGH PRESSURE TURBINE FORWARD SEAL PLATE						Component	ATA:72
PN:3060514-1	MOS	15-Jan-00		TSN 0				LIFE LIMIT	
SN:000322905162	HRS	0		TSN 0					
	ENC	0	10000	TSN 0	(10000) 10118		2502		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

725220		NO. 1 ENGINE - TURBINE INTERSTAGE TRANSITION DUCT						Component	ATA:72
PN:3060694-6	MOS/MSC	25-Oct-06	O/C						
SN:97P23086	HRS	4857.2							
	ENC	3730							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

725220		NO. 2 ENGINE - TURBINE INTERSTAGE TRANSITION DUCT						Component	ATA:72
PN:3060694-6	MOS/MSC	20-Jul-15	O/C	TSO 0					
SN:02P01906	HRS	6622.3		TSO 0					
	ENC	5602		TSO 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
725230 NO. 1 ENGINE - LOW PRESSURE TURBINE (LPT) 1 NOZZLE SEAL SUPPORT									Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-50-04, LMM 72-50-04PROC. REF: LMM 72-50-04, LMM 72-50-04									
725230 NO. 2 ENGINE - LOW PRESSURE TURBINE (LPT) 1 NOZZLE SEAL SUPPORT									Component ATA:72
PN:3060693-1	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:00P28158	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-50-04, LMM 72-50-04PROC. REF: LMM 72-50-04, LMM 72-50-04									
725240 NO. 1 ENGINE - LOW PRESSURE TURBINE (LPT) 1 NOZZLE ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-50-04, LMM 72-50-04PROC. REF: LMM 72-50-04, LMM 72-50-04									
725240 NO. 2 ENGINE - LOW PRESSURE TURBINE (LPT) 1 NOZZLE ASSEMBLY									Component ATA:72
PN:3060666-7	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:00P29069	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-50-04, LMM 72-50-04PROC. REF: LMM 72-50-04, LMM 72-50-04									
725250 NO. 1 ENGINE - FORWARD SHAFT HIGH PRESSURE TURBINE (HPT) COUPLING									Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725250 NO. 2 ENGINE - FORWARD SHAFT HIGH PRESSURE TURBINE (HPT) COUPLING									Component ATA:72
PN:3060502-2	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:00P26421	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
725260 NO. 1 ENGINE - AFT HIGH PRESSURE TURBINE (HPT) SHAFT COUPLING									Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725260 NO. 2 ENGINE - AFT HIGH PRESSURE TURBINE (HPT) SHAFT COUPLING									Component ATA:72
PN:3060599-2	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:00P28573	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725270 NO. 1 ENGINE - NOZZLE LOW PRESSURE TURBINE (LPT) (A5) SEAL									Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725270 NO. 2 ENGINE - NOZZLE LOW PRESSURE TURBINE (LPT) (A5) SEAL									Component ATA:72
PN:3073765-12	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:00P29032	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
726005 NO. 1 ENGINE - TRANSFER GEARBOX ASSEMBLY									Component ATA:72
PN:3070093-16	MOS/MSC	25-Oct-06	O/C						
SN:P10020	HRS	4857.2							
	ENC	3730							
PROC. REF: LMM 72-60-03, LMM 72-60-03PROC. REF: LMM 72-60-03, LMM 72-60-03									
726005 NO. 2 ENGINE - TRANSFER GEARBOX ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-60-03, LMM 72-60-03PROC. REF: LMM 72-60-03, LMM 72-60-03									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 72 - ENGINE										
726010		NO. 1 ENGINE - FORWARD OIL PUMP SPUR ANNULAR BALL BEARING						Component	ATA:72	
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00										
726010		NO. 2 ENGINE - FORWARD OIL PUMP SPUR ANNULAR BALL BEARING						Component	ATA:72	
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00										
726011		NO. 1 ENGINE - AFT OIL PUMP SPUR ANNULAR BALL BEARING						Component	ATA:72	
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
726011		NO. 2 ENGINE - AFT OIL PUMP SPUR ANNULAR BALL BEARING						Component	ATA:72	
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
726012		NO. 1 ENGINE - FORWARD ALTERNATOR SPU ANNULAR BALL BEARING						Component	ATA:72	
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
726012		NO. 2 ENGINE - FORWARD ALTERNATOR SPU ANNULAR BALL BEARING						Component	ATA:72	
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 72 - ENGINE										
726013		NO. 1 ENGINE - AFT ALTERNATOR SPU ANNULAR BEARING						Component	ATA:72	
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
726013		NO. 2 ENGINE - AFT ALTERNATOR SPU ANNULAR BEARING						Component	ATA:72	
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
726014		NO. 1 ENGINE - FORWARD AIR-OIL SEPARATOR ANNULAR BALL BEARING						Component	ATA:72	
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
726014		NO. 2 ENGINE - FORWARD AIR-OIL SEPARATOR ANNULAR BALL BEARING						Component	ATA:72	
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
726015		NO. 1 ENGINE - AFT AIR-OIL SEPARATOR ANNULAR BALL BEARING						Component	ATA:72	
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
726015		NO. 2 ENGINE - AFT AIR-OIL SEPARATOR ANNULAR BALL BEARING						Component	ATA:72	
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 72 - ENGINE										
726016		NO. 1 ENGINE - FORWARD STARTER/GENERATOR SPU ANNULAR BALL BEARING						Component	ATA:72	
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
726016		NO. 2 ENGINE - FORWARD STARTER/GENERATOR SPU ANNULAR BALL BEARING						Component	ATA:72	
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
726017		NO. 1 ENGINE - AFT STARTER/GENERATOR SPU ANNULAR BEARING						Component	ATA:72	
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
726017		NO. 2 ENGINE - AFT STARTER/GENERATOR SPU ANNULAR BEARING						Component	ATA:72	
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
727001		NO. 1 ENGINE - BYPASS FAN STATOR						Component	ATA:72	
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: LMM 72-70-04, LMM 72-70-04PROC. REF: LMM 72-70-04, LMM 72-70-04										
727001		NO. 2 ENGINE - BYPASS FAN STATOR						Component	ATA:72	
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: LMM 72-70-04, LMM 72-70-04PROC. REF: LMM 72-70-04, LMM 72-70-04										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
727005 NO. 1 ENGINE - UPPER FAN DUCT ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-70-05, LMM 72-70-05PROC. REF: LMM 72-70-05, LMM 72-70-05									
727005 NO. 2 ENGINE - UPPER FAN DUCT ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-70-05, LMM 72-70-05PROC. REF: LMM 72-70-05, LMM 72-70-05									
727006 NO. 1 ENGINE - LOWER FAN DUCT ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-70-05, LMM 72-70-05PROC. REF: LMM 72-70-05, LMM 72-70-05									
727006 NO. 2 ENGINE - LOWER FAN DUCT ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-70-05, LMM 72-70-05PROC. REF: LMM 72-70-05, LMM 72-70-05									
727010 ^S NO. 1 ENGINE - INSPECT BYPASS STATOR VANE ASSEMBLY.									Service ATA:72
	MOS	27-Oct-25							
	HRS	9832.1	1200						
	ENC	7480							
PROC. REF: LMM 72-70-04, LMM 72-70-04, LMM 72-70-04PROC. REF: LMM 72-70-04, LMM 72-70-04, LMM 72-70-04									
727010 ^S NO. 2 ENGINE - INSPECT BYPASS STATOR VANE ASSEMBLY.									Service ATA:72
	MOS	27-Oct-25							
	HRS	8993.4	1200						
	ENC	7376							
PROC. REF: LMM 72-70-04, LMM 72-70-04, LMM 72-70-04PROC. REF: LMM 72-70-04, LMM 72-70-04, LMM 72-70-04									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
727101 NO. 1 ENGINE - NO. 1 CARBON SEAL ASSEMBLY									Component ATA:72
PN:3060457-1	MOS/MSC	28-Nov-17	O/C	TSN 0					
SN:17-152826-59105	HRS	7696.2		TSN 0					
	ENC	5895		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
727101 NO. 2 ENGINE - NO. 1 CARBON SEAL ASSEMBLY									Component ATA:72
PN:3060457-1	MOS/MSC	20-Jul-15	O/C	TSN 0					
SN:14-152826-73404	HRS	6622.3		TSN 0					
	ENC	5602		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
727102 NO. 1 ENGINE - NO. 1 CARBON SEAL RUNNER									Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
727102 NO. 2 ENGINE - NO. 1 CARBON SEAL RUNNER									Component ATA:72
PN:3075657-1	MOS/MSC	20-Jul-15	O/C	TSN 0					
SN:14-162397-04157	HRS	6622.3		TSN 0					
	ENC	5602		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
727103 NO. 1 ENGINE - NO. 1 BEARING ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
727103 NO. 2 ENGINE - NO. 1 BEARING ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
727105 NO. 1 ENGINE - HELICAL RING GEAR									Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
727105 NO. 2 ENGINE - HELICAL RING GEAR									Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
727203 NO. 1 ENGINE - NO. 3 BALL BEARING									Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-30-01, LMM 72-30-01PROC. REF: LMM 72-30-01, LMM 72-30-01									
727203 NO. 2 ENGINE - NO. 3 BALL BEARING									Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-30-01, LMM 72-30-01PROC. REF: LMM 72-30-01, LMM 72-30-01									
727210 NO. 1 ENGINE - PLANET HOUSING ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-72-03, LMM 72-72-03PROC. REF: LMM 72-72-03, LMM 72-72-03									
727210 NO. 2 ENGINE - PLANET HOUSING ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-72-03, LMM 72-72-03PROC. REF: LMM 72-72-03, LMM 72-72-03									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 72 - ENGINE										
727210-1		NO. 1 ENGINE - NO. 1 PLANET GEAR ASSEMBLY						Component	ATA:72	
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: LMM 72-72-03, LMM 72-72-03PROC. REF: LMM 72-72-03, LMM 72-72-03										
727210-1		NO. 2 ENGINE - NO. 1 PLANET GEAR ASSEMBLY						Component	ATA:72	
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: LMM 72-72-03, LMM 72-72-03PROC. REF: LMM 72-72-03, LMM 72-72-03										
727210-2		NO. 1 ENGINE - NO. 2 PLANET GEAR ASSEMBLY						Component	ATA:72	
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: LMM 72-72-03, LMM 72-72-03PROC. REF: LMM 72-72-03, LMM 72-72-03										
727210-2		NO. 2 ENGINE - NO. 2 PLANET GEAR ASSEMBLY						Component	ATA:72	
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: LMM 72-72-03, LMM 72-72-03PROC. REF: LMM 72-72-03, LMM 72-72-03										
727210-3		NO. 1 ENGINE - NO. 3 PLANET GEAR ASSEMBLY						Component	ATA:72	
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: LMM 72-72-03, LMM 72-72-03PROC. REF: LMM 72-72-03, LMM 72-72-03										
727210-3		NO. 2 ENGINE - NO. 3 PLANET GEAR ASSEMBLY						Component	ATA:72	
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: LMM 72-72-03, LMM 72-72-03PROC. REF: LMM 72-72-03, LMM 72-72-03										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 72 - ENGINE

727210-4		NO. 1 ENGINE - NO. 4 PLANET GEAR ASSEMBLY					Component	ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: LMM 72-72-03, LMM 72-72-03PROC. REF: LMM 72-72-03, LMM 72-72-03								

727210-4		NO. 2 ENGINE - NO. 4 PLANET GEAR ASSEMBLY					Component	ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: LMM 72-72-03, LMM 72-72-03PROC. REF: LMM 72-72-03, LMM 72-72-03								

727210-5		NO. 1 ENGINE - NO. 5 PLANET GEAR ASSEMBLY					Component	ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: LMM 72-72-03, LMM 72-72-03PROC. REF: LMM 72-72-03, LMM 72-72-03								

727210-5		NO. 2 ENGINE - NO. 5 PLANET GEAR ASSEMBLY					Component	ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: LMM 72-72-03, LMM 72-72-03PROC. REF: LMM 72-72-03, LMM 72-72-03								

ATA 73 - ENGINE FUEL AND CONTROL

730110		NO. 1 ENGINE - FUEL CONTROL UNIT					Component	ATA:73
PN:3070800-37	MOS/MSC	25-Oct-06	O/C					
SN:16529	HRS	4857.2						
	ENC	3730						
PROC. REF: LMM 73-20-01, LMM 73-20-01PROC. REF: LMM 73-20-01, LMM 73-20-01								

730110		NO. 2 ENGINE - FUEL CONTROL UNIT					Component	ATA:73
PN:3070800-47	MOS/MSC	27-Feb-23	O/C	TSO 0				
SN:19179	HRS	8273.9		TSO 0				
	ENC	6885		TSO 0				
PROC. REF: LMM 73-20-01, LMM 73-20-01PROC. REF: LMM 73-20-01, LMM 73-20-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 73 - ENGINE FUEL AND CONTROL									
730120^S NO. 1 ENGINE - REPLACE FUEL FILTER ELEMENT Service ATA:73									
	MOS		27-Oct-25						
	HRS		9832.1	600					
	ENC		7480						
PROC. REF: LMM 73-21-02, LMM 73-21-02PROC. REF: LMM 73-21-02, LMM 73-21-02									
730120^S NO. 2 ENGINE - REPLACE FUEL FILTER ELEMENT Service ATA:73									
	MOS		27-Oct-25						
	HRS		8993.4	600					
	ENC		7376						
PROC. REF: LMM 73-21-02, LMM 73-21-02PROC. REF: LMM 73-21-02, LMM 73-21-02									
730130 NO. 1 ENGINE - ENGINE FUEL PUMP ASSEMBLY Component ATA:73									
PN:3060760-3	MOS/MSC		25-Oct-06	O/C					
SN:0942	HRS		4857.2						
	ENC		3730						
PROC. REF: LMM 73-20-01, LMM 73-20-01, LMM 73-20-01, LMM 73-20-01PROC. REF: LMM 73-20-01, LMM 73-20-01, LMM 73-20-01, LMM 73-20-01									
730130 NO. 2 ENGINE - ENGINE FUEL PUMP ASSEMBLY Component ATA:73									
PN:PN	MOS/MSC		15-Jan-00	O/C	TSN 0				
SN:UNKNOWN	HRS		0		TSN 0				
	ENC		0		TSN 0				
PROC. REF: LMM 73-20-01, LMM 73-20-01, LMM 73-20-01, LMM 73-20-01PROC. REF: LMM 73-20-01, LMM 73-20-01, LMM 73-20-01, LMM 73-20-01									
731001 NO. 1 ENGINE - MOTIVE FLOW FUEL PUMP ASSEMBLY Component ATA:73									
PN:3060759-1	MOS/MSC		25-Oct-06	O/C					
SN:0457	HRS		4857.2						
	ENC		3730						
PROC. REF: LMM 73-21-02PROC. REF: LMM 73-21-02									
731001 NO. 2 ENGINE - MOTIVE FLOW FUEL PUMP ASSEMBLY Component ATA:73									
PN:3060759-1	MOS/MSC		18-Dec-13	O/C	TSO 0				
SN:0671	HRS		6312.5		TSO 0				
	ENC		5360		TSO 0				
PROC. REF: LMM 73-21-02PROC. REF: LMM 73-21-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 73 - ENGINE FUEL AND CONTROL									
731005-1 NO. 1 ENGINE - NO. 1 FUEL MANIFOLD NOZZLE ASSEMBLY Component ATA:73									
PN:3060540-2	MOS/MSC	25-Oct-06	O/C						
SN:97-01371-430	HRS	4857.2							
	ENC	3730							
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01									
731005-1 NO. 2 ENGINE - NO. 1 FUEL MANIFOLD NOZZLE ASSEMBLY Component ATA:73									
PN:3060540-2	MOS/MSC	20-Jul-15	O/C	TSO 0					
SN:020137100424	HRS	6622.3		TSO 0					
	ENC	5602		TSO 0					
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01									
731005-10 NO. 1 ENGINE - NO. 10 FUEL MANIFOLD NOZZLE ASSEMBLY Component ATA:73									
PN:3060540-2	MOS/MSC	25-Oct-06	O/C						
SN:97-01371-1025	HRS	4857.2							
	ENC	3730							
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01									
731005-10 NO. 2 ENGINE - NO. 10 FUEL MANIFOLD NOZZLE ASSEMBLY Component ATA:73									
PN:3060540-2	MOS/MSC	20-Jul-15	O/C	TSO 0					
SN:052923401375	HRS	6622.3		TSO 0					
	ENC	5602		TSO 0					
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01									
731005-11 NO. 1 ENGINE - NO. 11 FUEL MANIFOLD NOZZLE ASSEMBLY Component ATA:73									
PN:3060540-2	MOS/MSC	25-Oct-06	O/C						
SN:990137101056	HRS	4857.2							
	ENC	3730							
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01									
731005-11 NO. 2 ENGINE - NO. 11 FUEL MANIFOLD NOZZLE ASSEMBLY Component ATA:73									
PN:3060540-2	MOS/MSC	20-Jul-15	O/C	TSO 0					
SN:010137103143	HRS	6622.3		TSO 0					
	ENC	5602		TSO 0					
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 73 - ENGINE FUEL AND CONTROL										
731005-12		NO. 1 ENGINE - NO. 12 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73	
PN:3060540-2	MOS/MSC	25-Oct-06	O/C							
SN:97-01371-400	HRS	4857.2								
	ENC	3730								
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01										
731005-12		NO. 2 ENGINE - NO. 12 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73	
PN:3060540-2	MOS/MSC	20-Jul-15	O/C	TSO 0						
SN:052923401374	HRS	6622.3		TSO 0						
	ENC	5602		TSO 0						
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01										
731005-2		NO. 1 ENGINE - NO. 2 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73	
PN:3060540-2	MOS/MSC	25-Oct-06	O/C							
SN:010137102472	HRS	4857.2								
	ENC	3730								
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01										
731005-2		NO. 2 ENGINE - NO. 2 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73	
PN:3060540-2	MOS/MSC	20-Jul-15	O/C	TSO 0						
SN:052923401378	HRS	6622.3		TSO 0						
	ENC	5602		TSO 0						
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01										
731005-3		NO. 1 ENGINE - NO. 3 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73	
PN:3060540-2	MOS/MSC	25-Oct-06	O/C							
SN:97-01371-398	HRS	4857.2								
	ENC	3730								
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01										
731005-3		NO. 2 ENGINE - NO. 3 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73	
PN:3060540-2	MOS/MSC	20-Jul-15	O/C	TSO 0						
SN:032923401169	HRS	6622.3		TSO 0						
	ENC	5602		TSO 0						
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 73 - ENGINE FUEL AND CONTROL										
731005-4		NO. 1 ENGINE - NO. 4 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73	
PN:3060540-2	MOS/MSC	25-Oct-06	O/C							
SN:97-01371-572	HRS	4857.2								
	ENC	3730								
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01										
731005-4		NO. 2 ENGINE - NO. 4 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73	
PN:3060540-2	MOS/MSC	20-Jul-15	O/C	TSO 0						
SN:032923401065	HRS	6622.3		TSO 0						
	ENC	5602		TSO 0						
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01										
731005-5		NO. 1 ENGINE - NO. 5 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73	
PN:3060540-2	MOS/MSC	25-Oct-06	O/C							
SN:990137101033	HRS	4857.2								
	ENC	3730								
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01										
731005-5		NO. 2 ENGINE - NO. 5 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73	
PN:3060540-2	MOS/MSC	20-Jul-15	O/C	TSO 0						
SN:072923400480	HRS	6622.3		TSO 0						
	ENC	5602		TSO 0						
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01										
731005-6		NO. 1 ENGINE - NO. 6 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73	
PN:3060540-2	MOS/MSC	25-Oct-06	O/C							
SN:990137101059	HRS	4857.2								
	ENC	3730								
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01										
731005-6		NO. 2 ENGINE - NO. 6 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73	
PN:3060540-2	MOS/MSC	20-Jul-15	O/C	TSO 0						
SN:052923400974	HRS	6622.3		TSO 0						
	ENC	5602		TSO 0						
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 73 - ENGINE FUEL AND CONTROL										
731005-7		NO. 1 ENGINE - NO. 7 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73	
PN:3060540-2	MOS/MSC	25-Oct-06	O/C							
SN:97-01371-542	HRS	4857.2								
	ENC	3730								
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01										
731005-7		NO. 2 ENGINE - NO. 7 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73	
PN:3060540-2	MOS/MSC	20-Jul-15	O/C	TSO 0						
SN:052623401379	HRS	6622.3		TSO 0						
	ENC	5602		TSO 0						
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01										
731005-8		NO. 1 ENGINE - NO. 8 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73	
PN:3060540-2	MOS/MSC	25-Oct-06	O/C							
SN:022923401439	HRS	4857.2								
	ENC	3730								
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01										
731005-8		NO. 2 ENGINE - NO. 8 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73	
PN:3060540-2	MOS/MSC	20-Jul-15	O/C	TSO 0						
SN:052923401376	HRS	6622.3		TSO 0						
	ENC	5602		TSO 0						
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01										
731005-9		NO. 1 ENGINE - NO. 9 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73	
PN:3060540-2	MOS/MSC	25-Oct-06	O/C							
SN:97-01371-562	HRS	4857.2								
	ENC	3730								
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01										
731005-9		NO. 2 ENGINE - NO. 9 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73	
PN:3060540-2	MOS/MSC	20-Jul-15	O/C	TSO 0						
SN:000137102869	HRS	6622.3		TSO 0						
	ENC	5602		TSO 0						
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 73 - ENGINE FUEL AND CONTROL

731015 NO. 1 ENGINE - FUEL PUMP PRESSURE DIFFERENTIAL INDICATOR						Component	ATA:73
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0			
SN:UNKNOWN	HRS	0		TSN 0			
	ENC	0		TSN 0			
PROC. REF: LMM 73-20-01, LMM 73-20-01PROC. REF: LMM 73-20-01, LMM 73-20-01							

731015 NO. 2 ENGINE - FUEL PUMP PRESSURE DIFFERENTIAL INDICATOR						Component	ATA:73
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0			
SN:UNKNOWN	HRS	0		TSN 0			
	ENC	0		TSN 0			
PROC. REF: LMM 73-20-01, LMM 73-20-01PROC. REF: LMM 73-20-01, LMM 73-20-01							

731110 NO. 1 ENGINE - PRESSURE LIMITER (PCD) VALVE						Component	ATA:73
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0			
SN:UNKNOWN	HRS	0		TSN 0			
	ENC	0		TSN 0			
PROC. REF: LMM 73-20-01, LMM 73-20-01PROC. REF: LMM 73-20-01, LMM 73-20-01							

731110 NO. 2 ENGINE - PRESSURE LIMITER (PCD) VALVE						Component	ATA:73
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0			
SN:UNKNOWN	HRS	0		TSN 0			
	ENC	0		TSN 0			
PROC. REF: LMM 73-20-01, LMM 73-20-01PROC. REF: LMM 73-20-01, LMM 73-20-01							

731120 NO. 1 ENGINE - FUEL FLOW DIVIDER/DRAIN VALVE						Component	ATA:73
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0			
SN:UNKNOWN	HRS	0		TSN 0			
	ENC	0		TSN 0			
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF							

731120 NO. 2 ENGINE - FUEL FLOW DIVIDER/DRAIN VALVE						Component	ATA:73
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0			
SN:UNKNOWN	HRS	0		TSN 0			
	ENC	0		TSN 0			
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 73 - ENGINE FUEL AND CONTROL										
732102		NO. 1 ENGINE - RELIEF VALVE						Component	ATA:73	
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
732102		NO. 2 ENGINE - RELIEF VALVE						Component	ATA:73	
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
732120^S		NO. 1 ENGINE - INSPECT MOTIVE FLOW FUEL PUMP DRIVE SPLINE						Service	ATA:73	
	MOS	27-Oct-25								
	HRS	9832.1	600							
	ENC	7480								
PROC. REF: LMM 72-00-00, LMM 73-21-04PROC. REF: LMM 72-00-00, LMM 73-21-04										
732120^S		NO. 2 ENGINE - INSPECT MOTIVE FLOW FUEL PUMP DRIVE SPLINE						Service	ATA:73	
	MOS	27-Oct-25								
	HRS	8993.4	600							
	ENC	7376								
PROC. REF: LMM 72-00-00, LMM 73-21-04PROC. REF: LMM 72-00-00, LMM 73-21-04										
733001		NO. 1 ENGINE FUEL FLOW TRANSDUCER						Component	ATA:73	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 73-31-01PROC. REF: AMM 73-31-01										
733002		NO. 2 ENGINE FUEL FLOW TRANSDUCER						Component	ATA:73	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 73-31-01PROC. REF: AMM 73-31-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 73 - ENGINE FUEL AND CONTROL

733013		DUAL FUEL FLOW CONVERTER (DFFC)					Component	ATA:73
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 73-31-02PROC. REF: AMM 73-31-02								

733031		LEFT ENGINE FUEL TEMPERATURE BULB					Component	ATA:73
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 73-31-03PROC. REF: AMM 73-31-03								

733032		RIGHT ENGINE FUEL TEMPERATURE BULB					Component	ATA:73
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 73-31-03PROC. REF: AMM 73-31-03								

ATA 74 - IGNITION

740110		NO. 1 ENGINE - IGNITION UNIT					Component	ATA:74
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: LMM 74-00-01, LMM 74-00-01PROC. REF: LMM 74-00-01, LMM 74-00-01								

740110		NO. 2 ENGINE - IGNITION UNIT					Component	ATA:74
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: LMM 74-00-01, LMM 74-00-01PROC. REF: LMM 74-00-01, LMM 74-00-01								

740130		NO. 1 ENGINE - 5 O'CLOCK IGNITER (#1 POSITION) PLUG					Component	ATA:74
PN:3074541-4	MOS/MSC	28-Nov-17	O/C	TSN 0				
SN:UNKNOWN	HRS	7696.2		TSN 0				
	ENC	5895		TSN 0				
PROC. REF: LMM 74-00-01, LMM 74-00-01PROC. REF: LMM 74-00-01, LMM 74-00-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 74 - IGNITION									
740130 NO. 2 ENGINE - 5 O'CLOCK IGNITER (#1 POSITION) PLUG									Component ATA:74
PN:3074541-4	MOS/MSC	18-Aug-22	O/C	TSN 0					
SN:UNKNOWN	HRS	8169.8		TSN 0					
	ENC	6832		TSN 0					
PROC. REF: LMM 74-00-01, LMM 74-00-01PROC. REF: LMM 74-00-01, LMM 74-00-01									
740140 ^S NO. 1 ENGINE - REMOVE AND INSPECT 5 O'CLOCK IGNITER PLUG AND LEAD									Service ATA:74
	MOS	22-Jun-23							
	HRS	9184.4	1600						
	ENC	7042							
PKG:0									
740140 ^S NO. 2 ENGINE - REMOVE AND INSPECT 5 O'CLOCK IGNITER PLUG AND LEAD									Service ATA:74
	MOS	18-Aug-22							
	HRS	8169.8	1600						
	ENC	6832							
PKG:0									
740150 NO. 1 ENGINE - 7 O'CLOCK IGNITER (#2 POSITION) PLUG									Component ATA:74
PN:3074541-4	MOS/MSC	28-Nov-17	O/C	TSN 0					
SN:UNKNOWN	HRS	7696.2		TSN 0					
	ENC	5895		TSN 0					
PROC. REF: LMM 74-00-01, LMM 74-00-01PROC. REF: LMM 74-00-01, LMM 74-00-01									
740150 NO. 2 ENGINE - 7 O'CLOCK IGNITER (#2 POSITION) PLUG									Component ATA:74
PN:3074541-4	MOS/MSC	18-Aug-22	O/C	TSN 0					
SN:UNKNOWN	HRS	8169.8		TSN 0					
	ENC	6832		TSN 0					
PROC. REF: LMM 74-00-01, LMM 74-00-01PROC. REF: LMM 74-00-01, LMM 74-00-01									
740160 ^S NO. 1 ENGINE - REMOVE AND INSPECT 7 O'CLOCK IGNITER PLUG AND LEAD									Service ATA:74
	MOS	22-Jun-23							
	HRS	9184.4	1600						
	ENC	7042							
PKG:0									
PROC. REF: LMM 74-00-01PROC. REF: LMM 74-00-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 74 - IGNITION

740160^S		NO. 2 ENGINE - REMOVE AND INSPECT 7 O'CLOCK IGNITER PLUG AND LEAD						Service	ATA:74
	MOS	18-Aug-22							
	HRS	8169.8	1600						
	ENC	6832							
PKG:0									
PROC. REF: LMM 74-00-01PROC. REF: LMM 74-00-01									

742011		NO. 1 ENGINE - NO. 1 IGNITION (IPC 20 REFERENCE) LEAD						Component	ATA:74
PN:3060722-11	MOS/MSC	22-Jun-23	O/C	TSN 0					
SN:S23100003	HRS	9184.4		TSN 0					
	ENC	7042		TSN 0					
PROC. REF: LMM 74-00-01, LMM 74-00-01PROC. REF: LMM 74-00-01, LMM 74-00-01									

742011		NO. 2 ENGINE - NO. 1 IGNITION (IPC 20 REFERENCE) LEAD						Component	ATA:74
PN:9043913	MOS/MSC	20-Jul-15	O/C	TSN 0					
SN:UNKNOWN	HRS	6622.3		TSN 0					
	ENC	5602		TSN 0					
PROC. REF: LMM 74-00-01, LMM 74-00-01PROC. REF: LMM 74-00-01, LMM 74-00-01									

742012		NO. 1 ENGINE - NO. 2 IGNITION (IPC 25 REFERENCE) LEAD						Component	ATA:74
PN:3060722-12	MOS/MSC	22-Jun-23	O/C	TSN 0					
SN:S22500007	HRS	9184.4		TSN 0					
	ENC	7042		TSN 0					
PROC. REF: LMM 74-00-01, LMM 74-00-01PROC. REF: LMM 74-00-01, LMM 74-00-01									

742012		NO. 2 ENGINE - NO. 2 IGNITION (IPC 25 REFERENCE) LEAD						Component	ATA:74
PN:9043913	MOS/MSC	20-Jul-15	O/C	TSN 0					
SN:UNKNOWN	HRS	6622.3		TSN 0					
	ENC	5602		TSN 0					
PROC. REF: LMM 74-00-01, LMM 74-00-01PROC. REF: LMM 74-00-01, LMM 74-00-01									

743001		TAIL CONE RELAY (P13) PANEL						Component	ATA:74
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 74-30-01PROC. REF: AMM 74-30-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 74 - IGNITION

743001-1		EMERGENCY LIGHTING (P-51) RELAY					Component	ATA:74
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

743005-1		K22 RELAY					Component	ATA:74
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

743005-2		K61 RELAY					Component	ATA:74
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

ATA 75 - AIR

754210		NO. 1 ENGINE - INLET PRESSURE AND TEMPERATURE SENSOR					Component	ATA:75
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: LMM 75-40-01, LMM 75-40-01, LMM 75-40-01, LMM 75-40-01PROC. REF: LMM 75-40-01, LMM 75-40-01, LMM 75-40-01, LMM 75-40-01								

754210		NO. 2 ENGINE - INLET PRESSURE AND TEMPERATURE SENSOR					Component	ATA:75
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: LMM 75-40-01, LMM 75-40-01, LMM 75-40-01, LMM 75-40-01PROC. REF: LMM 75-40-01, LMM 75-40-01, LMM 75-40-01, LMM 75-40-01								

ATA 76 - ENGINE CONTROLS

761013		THROTTLE CONTROL MODULE					Component	ATA:76
PN:69011-17	MOS/MSC	16-Jul-20	O/C					
SN:640	HRS	8284.1						
	AFL	6376						
PROC. REF: AMM 76-10-02PROC. REF: AMM 76-10-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 76 - ENGINE CONTROLS										
761201		AFT LEFT THROTTLE CABLE						Component	ATA:76	
PN:71825-6	MOS/MSC	12-Oct-12	O/C							
SN:UNKNOWN	HRS	6996.3								
	AFL	5340								
PROC. REF: AMM 76-10-01PROC. REF: AMM 76-10-01										
761202		AFT RIGHT THROTTLE CABLE						Component	ATA:76	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 76-10-01PROC. REF: AMM 76-10-01										
761203		LEFT FORWARD THROTTLE CABLE						Component	ATA:76	
PN:71845-10	MOS/MSC	12-Oct-12	O/C							
SN:UNKNOWN	HRS	6996.3								
	AFL	5340								
PROC. REF: AMM 76-10-01PROC. REF: AMM 76-10-01										
761204		RIGHT FORWARD THROTTLE CABLE						Component	ATA:76	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 76-10-01PROC. REF: AMM 76-10-01										
761310		NO. 1 ENGINE - SURGE BLEED VALVE						Component	ATA:76	
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 76-10-01, LMM 76-10-01, LMM 76-10-01, LMM 76-10-01PROC. REF: LMM 76-10-01, LMM 76-10-01, LMM 76-10-01, LMM 76-10-01										
761310		NO. 2 ENGINE - SURGE BLEED VALVE						Component	ATA:76	
PN:978812-6-1	MOS/MSC	20-Jul-15	O/C	TSO 0						
SN:10962	HRS	6622.3		TSO 0						
	ENC	5602		TSO 0						
PROC. REF: LMM 76-10-01, LMM 76-10-01, LMM 76-10-01, LMM 76-10-01PROC. REF: LMM 76-10-01, LMM 76-10-01, LMM 76-10-01, LMM 76-10-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 76 - ENGINE CONTROLS										
761320		NO. 1 ENGINE - SOLENOID CONTROLLER VALVE						Component		ATA:76
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 76-10-01, LMM 76-10-01, LMM 76-10-01, LMM 76-10-01PROC. REF: LMM 76-10-01, LMM 76-10-01, LMM 76-10-01, LMM 76-10-01										
761320		NO. 2 ENGINE - SOLENOID CONTROLLER VALVE						Component		ATA:76
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 76-10-01, LMM 76-10-01, LMM 76-10-01, LMM 76-10-01PROC. REF: LMM 76-10-01, LMM 76-10-01, LMM 76-10-01, LMM 76-10-01										
761330		NO. 1 ENGINE - ENGINE (DEEC) COMPUTER						Component		ATA:76
PN:2118882-1008	MOS/MSC	25-Oct-06	O/C							
SN:15-AW0059	HRS	4857.2								
	ENC	3730								
PROC. REF: LMM 76-10-02, LMM 76-10-02, LMM 76-10-02, LMM 76-10-02PROC. REF: LMM 76-10-02, LMM 76-10-02, LMM 76-10-02, LMM 76-10-02										
761330		NO. 2 ENGINE - ENGINE (DEEC) COMPUTER						Component		ATA:76
PN:2118882-1008	MOS/MSC	27-Jun-06	O/C							
SN:124-AW0057	HRS	4614								
	ENC	3532								
PROC. REF: LMM 76-10-02, LMM 76-10-02, LMM 76-10-02, LMM 76-10-02PROC. REF: LMM 76-10-02, LMM 76-10-02, LMM 76-10-02, LMM 76-10-02										
761330A		NO. 1 ENGINE - DOWNLOAD ENGINE (DEEC) COMPUTER ECTM						Service		ATA:76
PN:2118882-1008	MOS	21-Oct-25						CUSTOMER CODE		
SN:15-AW0059	HRS	9826.9								
	ENC	7476	40		(7516) 7530		OVD			
PROC. REF: MSC CAMP EHM ADENDUMPROC. REF: MSC CAMP EHM ADENDUM										
761330A		NO. 2 ENGINE - DOWNLOAD ENGINE (DEEC) COMPUTER ECTM						Service		ATA:76
PN:2118882-1008	MOS	21-Oct-25						CUSTOMER CODE		
SN:124-AW0057	HRS	8988.2								
	ENC	7372	40		(7412) 7530		OVD			
PROC. REF: MSC CAMP EHM ADENDUMPROC. REF: MSC CAMP EHM ADENDUM										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 76 - ENGINE CONTROLS

Y7600000 ^S	ENGINE DEEC WIRE HARNESS SHIELD OVERBRAIDS AND SHIELD TERMINATIONS - PERFORM VISUAL INSPECTION							Service	ATA:76
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PKG:15									
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									

Y7600001 ^S	THRUST LEVER CONTROL MODULE - PERFORM FUNCTIONAL TEST							Service	ATA:76
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PKG:13									
PROC. REF: AMM 76-10-02PROC. REF: AMM 76-10-02									

Y7610007 ^S	ENGINE CONTROL CABLES - PERFORM VISUAL INSPECTION OF FORWARD AND AFT CABLE CONNECTIONS							Service	ATA:76
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PKG:14									
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									

ATA 77 - ENGINE INDICATING

770101	NO. 1 ENGINE - N1 MONOPOLE							Component	ATA:77
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN	0				
SN:UNKNOWN	HRS	0		TSN	0				
	ENC	0		TSN	0				
PROC. REF: LMM 77-10-02PROC. REF: LMM 77-10-02									

770101	NO. 2 ENGINE - N1 MONOPOLE							Component	ATA:77
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN	0				
SN:UNKNOWN	HRS	0		TSN	0				
	ENC	0		TSN	0				
PROC. REF: LMM 77-10-02PROC. REF: LMM 77-10-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 77 - ENGINE INDICATING

771210		NO. 1 ENGINE - N1 COMPENSATOR					Component	ATA:77
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: LMM 77-10-03, LMM 77-10-03, LMM 77-10-03, LMM 77-10-03PROC. REF: LMM 77-10-03, LMM 77-10-03, LMM 77-10-03, LMM 77-10-03								

771210		NO. 2 ENGINE - N1 COMPENSATOR					Component	ATA:77
PN:3060735-7	MOS/MSC	05-Jun-06	O/C	TSN 0				
SN:011309700526	HRS	3701.2		TSN 0				
	ENC	3369		TSN 0				
PROC. REF: LMM 77-10-03, LMM 77-10-03, LMM 77-10-03, LMM 77-10-03PROC. REF: LMM 77-10-03, LMM 77-10-03, LMM 77-10-03, LMM 77-10-03								

771220		NO. 1 ENGINE - N2 MONOPOLE					Component	ATA:77
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: LMM 77-10-05, LMM 77-10-05, LMM 77-10-05, LMM 77-10-05PROC. REF: LMM 77-10-05, LMM 77-10-05, LMM 77-10-05, LMM 77-10-05								

771220		NO. 2 ENGINE - N2 MONOPOLE					Component	ATA:77
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: LMM 77-10-05, LMM 77-10-05, LMM 77-10-05, LMM 77-10-05PROC. REF: LMM 77-10-05, LMM 77-10-05, LMM 77-10-05, LMM 77-10-05								

772210		NO. 1 ENGINE - ITT HARNESS ASSEMBLY					Component	ATA:77
PN:3060730-1	MOS/MSC	28-Nov-17	O/C	TSN 0				
SN:1716901702429	HRS	7696.2		TSN 0				
	ENC	5895		TSN 0				
PROC. REF: LMM 77-20-01, LMM 77-20-01, LMM 77-20-01, LMM 77-20-01PROC. REF: LMM 77-20-01, LMM 77-20-01, LMM 77-20-01, LMM 77-20-01								

772210		NO. 2 ENGINE - ITT HARNESS ASSEMBLY					Component	ATA:77
PN:3060763-1	MOS/MSC	20-Jul-15	O/C	TSN 0				
SN:1516901702268	HRS	6622.3		TSN 0				
	ENC	5602		TSN 0				
PROC. REF: LMM 77-20-01, LMM 77-20-01, LMM 77-20-01, LMM 77-20-01PROC. REF: LMM 77-20-01, LMM 77-20-01, LMM 77-20-01, LMM 77-20-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 77 - ENGINE INDICATING

774001		ENGINE VIBRATION MONITOR BOX					Component	ATA:77
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 77-41-01PROC. REF: AMM 77-41-01								

774010		P36 RELAY BOX					Component	ATA:77
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 77-41-03PROC. REF: AMM 77-41-03								

774011		LEFT ENGINE VIBRATION ACCELEROMETER					Component	ATA:77
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 77-41-02PROC. REF: AMM 77-41-02								

774012		RIGHT ENGINE VIBRATION ACCELEROMETER					Component	ATA:77
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 77-41-02PROC. REF: AMM 77-41-02								

Y7741000 ^S		ENGINE VIBRATION MONITORING SYSTEM - PERFORM FUNCTIONAL TEST					Service	ATA:77
	MOS	25-Nov-19	96					
	HRS	8177.7	2400					
	AFL	6303						
PROC. REF: AMM 77-41-00PROC. REF: AMM 77-41-00								
PKG:21								

ATA 78 - EXHAUST

783001		LEFT LOWER THRUST REVERSER					Component	ATA:78
PN:LJ7830101-5	MOS/MSC	26-Jul-23	O/C					
SN:00046	HRS	9278						
	AFL	7111						
Special Properties: RII ITEM								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 78 - EXHAUST

PROC. REF: AMM 78-31-00PROC. REF: AMM 78-31-00

783002 RIGHT LOWER THRUST REVERSER						Component	ATA:78
PN:LJ7830101-6	MOS/MSC	26-Jul-23	O/C				
SN:00052	HRS	9278					
	AFL	7111					
Special Properties: RII ITEM							
PROC. REF: AMM 78-31-00PROC. REF: AMM 78-31-00							

783025 TRANSFORMER/RECTIFIER ELECTRONIC CONTROL UNIT						Component	ATA:78
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0			
SN:UNKNOWN	HRS	0		TSN 0			
	AFL	0		TSN 0			
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF							

783037 NO. 1 GPM HYDRAULIC CONTROL VALVE						Component	ATA:78
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0			
SN:UNKNOWN	HRS	0		TSN 0			
	AFL	0		TSN 0			
PROC. REF: AMM 78-32-10PROC. REF: AMM 78-32-10							

783038 NO. 2 GPM HYDRAULIC CONTROL VALVE						Component	ATA:78
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0			
SN:UNKNOWN	HRS	0		TSN 0			
	AFL	0		TSN 0			
PROC. REF: AMM 78-32-10PROC. REF: AMM 78-32-10							

783051 LEFT OUTBOARD THRUST REVERSER ACTUATOR						Component	ATA:78
PN:LJ7833100-3	MOS/MSC	26-Jan-14	O/C	TSO 0			
SN:A30040652	HRS	7249.8		TSO 0			
	AFL	5528		TSO 0			
PROC. REF: AMM 78-32-20PROC. REF: AMM 78-32-20							

783052 LEFT INBOARD THRUST REVERSER ACTUATOR						Component	ATA:78
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0			
SN:UNKNOWN	HRS	0		TSN 0			
	AFL	0		TSN 0			

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 78 - EXHAUST

PROC. REF: AMM 78-32-20PROC. REF: AMM 78-32-20

783053 RIGHT INBOARD THRUST REVERSER ACTUATOR						Component	ATA:78
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0			
SN:UNKNOWN	HRS	0		TSN 0			
	AFL	0		TSN 0			
PROC. REF: AMM 78-32-20PROC. REF: AMM 78-32-20							

783054 RIGHT OUTBOARD THRUST REVERSER ACTUATOR						Component	ATA:78
PN:LJ7833100-4	MOS/MSC	12-Dec-11	O/C	TSO 0			
SN:A30040459	HRS	6763.5		TSO 0			
	AFL	5158		TSO 0			
PROC. REF: AMM 78-32-20PROC. REF: AMM 78-32-20							

783061 NO. 1 CONTROL, THRUST REVERSER HYDRAULIC VALVE						Component	ATA:78
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0			
SN:UNKNOWN	HRS	0		TSN 0			
	AFL	0		TSN 0			
PROC. REF: AMM 78-32-10PROC. REF: AMM 78-32-10							

783062 NO. 2 CONTROL, THRUST REVERSER HYDRAULIC VALVE						Component	ATA:78
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0			
SN:UNKNOWN	HRS	0		TSN 0			
	AFL	0		TSN 0			
PROC. REF: AMM 78-32-10PROC. REF: AMM 78-32-10							

783101 LEFT THRUST REVERSER HYDRAULIC ISOLATION VALVE						Component	ATA:78
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0			
SN:UNKNOWN	HRS	0		TSN 0			
	AFL	0		TSN 0			
PROC. REF: AMM 78-30-02PROC. REF: AMM 78-30-02							

783102 RIGHT THRUST REVERSER HYDRAULIC ISOLATION VALVE						Component	ATA:78
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0			
SN:UNKNOWN	HRS	0		TSN 0			
	AFL	0		TSN 0			
PROC. REF: AMM 78-30-02PROC. REF: AMM 78-30-02							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 78 - EXHAUST									
783150 LEFT HAND INBOARD LATCHBOX ACTUATOR									Component ATA:78
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 78-32-30PROC. REF: AMM 78-32-30									
783151 RIGHT HAND INBOARD LATCHBOX ACTUATOR									Component ATA:78
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 78-32-30PROC. REF: AMM 78-32-30									
783210 LEFT THRUST REVERSER CONTROL VALVE									Component ATA:78
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
783211 RIGHT THRUST REVERSER CONTROL VALVE									Component ATA:78
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
783220 NO. 1 ENGINE THROTTLE RETARD ACTUATOR									Component ATA:78
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 78-32-40PROC. REF: AMM 78-32-40									
783221 NO. 2 ENGINE THROTTLE RETARD ACTUATOR									Component ATA:78
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 78-32-40PROC. REF: AMM 78-32-40									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 78 - EXHAUST										
783301		LEFT THRUST REVERSER CONTROL BOX						Component		ATA:78
PN:LJ7836706-3	MOS/MSC	23-Aug-22	O/C							
SN:00046	HRS	9089.4								
	AFL	6994								
PROC. REF: AMM 78-33-10PROC. REF: AMM 78-33-10										
783302		RIGHT THRUST REVERSER CONTROL BOX						Component		ATA:78
PN:LJ7836706-3	MOS/MSC	18-Jun-07	O/C							
SN:00059	HRS	5562.1								
	AFL	4242								
PROC. REF: AMM 78-33-10PROC. REF: AMM 78-33-10										
783320		LEFT OUTBOARD THRUST REVERSER WIRE HARNESS						Component		ATA:78
PN:PN	MOS/MSC	09-Mar-01	C/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 78-33-20PROC. REF: AMM 78-33-20										
783321		LEFT INBOARD THRUST REVERSER WIRE HARNESS						Component		ATA:78
PN:PN	MOS/MSC	09-Mar-01	C/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 78-33-20PROC. REF: AMM 78-33-20										
783322		RIGHT INBOARD THRUST REVERSER WIRE HARNESS						Component		ATA:78
PN:PN	MOS/MSC	09-Mar-01	C/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 78-33-20PROC. REF: AMM 78-33-20										
783323		RIGHT OUTBOARD THRUST REVERSER WIRE HARNESS						Component		ATA:78
PN:PN	MOS/MSC	09-Mar-01	C/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 78-33-20PROC. REF: AMM 78-33-20										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 78 - EXHAUST										
D7830078	^S	** THRUST REVERSER SYSTEM THROTTLE RETARD ACTUATOR - PERFORM OPERATIONAL CHECK						Service	ATA:78	
	MOS	25-Nov-19	96					AIRWORTHINESS		
	HRS	8177.7	2400							
	AFL	6303								
PROC. REF: AMM 78-32-40PROC. REF: AMM 78-32-40										
PKG:21										
H7830081	^S	THRUST REVERSERS - REMOVE LINK ROD ASSEMBLIES AND PERFORM MAGNETIC PARTICLE INSPECTION						Service	ATA:78	
	MOS	09-Mar-01	96							
	HRS	0	2400							
	AFL	0								
PROC. REF: NDT PART 7/78-30-01PROC. REF: NDT PART 7/78-30-01										
PKG:21										
H7830082	^S	THRUST REVERSERS - REMOVE THRUST REVERSER DOOR ASSEMBLIES AND PERFORM EDDY CURRENT INSPECTION OF PIVOT FITTING AND DOOR HINGES						Service	ATA:78	
	MOS	09-Mar-01	96							
	HRS	0	2400							
	AFL	0								
PROC. REF: NDT PART 6/78-30-02, NDT PART 6/78-30-03PROC. REF: NDT PART 6/78-30-02, NDT PART 6/78-30-03										
PKG:21										
R7830007		THRUST REVERSER - PERFORM CONDUCTIVITY CHECK OF RIGHT THRUST REVERSER DOOR SKIN AND COWL ADJACENT TO APU EXHAUST						Service	ATA:78	
	MOS/MSC	09-Mar-01	N/A							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 6/78-30-01PROC. REF: NDT PART 6/78-30-01										
Y7830000	^S	EXHAUST NOZZLE - PERFORM VISUAL INSPECTION						Service	ATA:78	
	MOS	25-Nov-19	96							
	HRS	8177.7	2400							
	AFL	6303								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
PKG:21										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 78 - EXHAUST										
Y7830001	^S	THRUST REVERSER INNER FAN DUCT ASSEMBLY - PERFORM VISUAL INSPECTION. INSPECT FROM EXHAUST END ONLY.						Service	ATA:78	
	MOS	09-Mar-01	48							
	HRS	0	1200							
	AFL	0								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
PKG:15										
Y7830002	^S	THRUST REVERSER DOOR AND HINGE FITTINGS - PERFORM VISUAL INSPECTION						Service	ATA:78	
	MOS	09-Mar-01	48							
	HRS	0	1200							
	AFL	0								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
PKG:15										
Y7830003	^S	THRUST REVERSER PRIMARY ACTUATOR AND LATCH ASSEMBLY - PERFORM VISUAL INSPECTION						Service	ATA:78	
	MOS	09-Mar-01	48							
	HRS	0	1200							
	AFL	0								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
PKG:15										
Y7830004	^S	THRUST REVERSER HYDRAULIC CONTROL VALVE (HCV), THROTTLE RETARD ACTUATOR, AND ASSOCIATED PLUMBING - PERFORM VISUAL INSPECTION						Service	ATA:78	
	MOS	09-Mar-01	48							
	HRS	0	1200							
	AFL	0								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
PKG:15										
Y7830005	^S	THRUST REVERSER DOOR SEALS AND RETAINERS - PERFORM VISUAL INSPECTION						Service	ATA:78	
	MOS	09-Mar-01	48							
	HRS	0	1200							
	AFL	0								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
PKG:15										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 78 - EXHAUST

Y7830006 ^S		THRUST REVERSER WIRE HARNESS - PERFORM VISUAL INSPECTION						Service	ATA:78
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PKG:15									
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									

ATA 79 - OIL

790110		NO. 1 ENGINE - OIL PUMP						Component	ATA:79
PN:3060785-2	MOS/MSC	25-Oct-06	O/C		TSN 0				
SN:061405700614	HRS	4857.2			TSN 0				
	ENC	3730			TSN 0				
PROC. REF: LMM 79-20-03, LMM 79-20-03PROC. REF: LMM 79-20-03, LMM 79-20-03									

790110		NO. 2 ENGINE - OIL PUMP						Component	ATA:79
PN:3060785-2	MOS/MSC	05-Jun-06	O/C		TSN 0				
SN:061405700076	HRS	3701.2			TSN 0				
	ENC	3369			TSN 0				
PROC. REF: LMM 79-20-03, LMM 79-20-03PROC. REF: LMM 79-20-03, LMM 79-20-03									

790130 ^S		NO. 1 ENGINE - ANALYSIS OIL AND FILTER (SOAP)						Service	ATA:79
	MOS	02-Aug-24							
	HRS	9451.6	150						
	ENC	7218							
PKG:0									
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									

790130 ^S		NO. 2 ENGINE - ANALYSIS OIL AND FILTER (SOAP)						Service	ATA:79
	MOS	28-Jul-25							
	HRS	8867.6	150						
	ENC	7292							
PKG:0									
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 79 - OIL										
790140 ^S	NO. 1 ENGINE - PERFORM OIL CHANGE								Service	ATA:79
	MOS	27-Oct-25								
	HRS	9832.1	1200							
	ENC	7480								
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00										
PKG:0										
790140 ^S	NO. 2 ENGINE - PERFORM OIL CHANGE								Service	ATA:79
	MOS	27-Oct-25								
	HRS	8993.4	1200							
	ENC	7376								
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00										
PKG:0										
790150 ^S	NO. 1 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION AND PERFORM RESISTANCE CHECK								Service	ATA:79
	MOS	27-Oct-25								
	HRS	9832.1	600							
	ENC	7480								
PROC. REF: LMM 79-10-01PROC. REF: LMM 79-10-01										
PKG:0										
790150 ^S	NO. 2 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION AND PERFORM RESISTANCE CHECK								Service	ATA:79
	MOS	27-Oct-25								
	HRS	8993.4	600							
	ENC	7376								
PROC. REF: LMM 79-10-01PROC. REF: LMM 79-10-01										
PKG:0										
790160 ^S	NO. 1 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION								Service	ATA:79
	MOS	02-Aug-24								
	HRS	9451.6	150							
	ENC	7218								
PROC. REF: LMM 79-10-01PROC. REF: LMM 79-10-01										
PKG:0										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 79 - OIL										
790160 ^S	NO. 2 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION								Service	ATA:79
	MOS	28-Jul-25								
	HRS	8867.6	150							
	ENC	7292								
PROC. REF: LMM 79-10-01PROC. REF: LMM 79-10-01										
791001	NO. 1 ENGINE - ENGINE OIL CHIP DETECTOR								Component	ATA:79
PN:277-5501-9002	MOS/MSC	18-May-13	O/C							
SN:N/A	HRS	7075.3								
	ENC	5383								
PROC. REF: LMM 79-10-01, LMM 79-10-01PROC. REF: LMM 79-10-01, LMM 79-10-01										
791001	NO. 2 ENGINE - ENGINE OIL CHIP DETECTOR								Component	ATA:79
PN:277-5501-9004	MOS/MSC	18-May-13	O/C							
SN:N/A	HRS	6239								
	ENC	5281								
PROC. REF: LMM 79-10-01, LMM 79-10-01PROC. REF: LMM 79-10-01, LMM 79-10-01										
792008	NO. 1 ENGINE - OIL FLOW REDUCTION VALVE								Component	ATA:79
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 79-20-08, LMM 79-20-08PROC. REF: LMM 79-20-08, LMM 79-20-08										
792008	NO. 2 ENGINE - OIL FLOW REDUCTION VALVE								Component	ATA:79
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 79-20-08, LMM 79-20-08PROC. REF: LMM 79-20-08, LMM 79-20-08										
792011	NO. 1 ENGINE - FUEL/OIL VALVE								Component	ATA:79
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 79 - OIL									
792011 NO. 2 ENGINE - FUEL/OIL VALVE									Component ATA:79
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
<hr/>									
792012 NO. 1 ENGINE - OIL TEMPERATURE REGULATOR									Component ATA:79
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 79-20-03, LMM 79-20-03PROC. REF: LMM 79-20-03, LMM 79-20-03									
<hr/>									
792012 NO. 2 ENGINE - OIL TEMPERATURE REGULATOR									Component ATA:79
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 79-20-03, LMM 79-20-03PROC. REF: LMM 79-20-03, LMM 79-20-03									
<hr/>									
792037 NO. 1 OIL PRESSURE SWITCH									Component ATA:79
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 79-30-02PROC. REF: AMM 79-30-02									
<hr/>									
792038 NO. 2 OIL PRESSURE SWITCH									Component ATA:79
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 79-30-02PROC. REF: AMM 79-30-02									
<hr/>									
792220 NO. 1 ENGINE - UPPER OIL COOLER ASSEMBLY									Component ATA:79
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 79 - OIL										
792220	NO. 2 ENGINE - UPPER OIL COOLER ASSEMBLY								Component	ATA:79
PN:160554-5	MOS/MSC	05-Jun-06	O/C							
SN:76-247	HRS	3701.2								
	ENC	3369								
792230	NO. 1 ENGINE - LOWER LEFT OIL COOLER ASSEMBLY								Component	ATA:79
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
792230	NO. 2 ENGINE - LOWER LEFT OIL COOLER ASSEMBLY								Component	ATA:79
PN:160552-3	MOS/MSC	05-Jun-06	O/C							
SN:47-274	HRS	3701.2								
	ENC	3369								
792240	NO. 1 ENGINE - LOWER RIGHT OIL COOLER ASSEMBLY								Component	ATA:79
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
792240	NO. 2 ENGINE - LOWER RIGHT OIL COOLER ASSEMBLY								Component	ATA:79
PN:160554-6	MOS/MSC	05-Jun-06	O/C							
SN:1068	HRS	3701.2								
	ENC	3369								
792250	NO. 1 ENGINE - PRESSURE BREATHER VALVE								Component	ATA:79
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 79-20-02, LMM 79-20-02PROC. REF: LMM 79-20-02, LMM 79-20-02										

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 79 - OIL										
792250		NO. 2 ENGINE - PRESSURE BREATHER VALVE						Component	ATA:79	
PN:3075323-3	MOS/MSC	16-Feb-11	O/C							
SN:000814506520	HRS	5602								
	ENC	4823								
PROC. REF: LMM 79-20-02, LMM 79-20-02PROC. REF: LMM 79-20-02, LMM 79-20-02										
792260		NO. 1 ENGINE - OIL TEMPERATURE CONTROL VALVE						Component	ATA:79	
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
792260		NO. 2 ENGINE - OIL TEMPERATURE CONTROL VALVE						Component	ATA:79	
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
793001		NO. 1 ENGINE OIL PRESSURE TRANSDUCER						Component	ATA:79	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 79-30-01PROC. REF: AMM 79-30-01										
793002		NO. 2 ENGINE OIL PRESSURE TRANSDUCER						Component	ATA:79	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 79-30-01PROC. REF: AMM 79-30-01										
793011		LEFT TEMPERATURE OIL BULB						Component	ATA:79	
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 79-30-03PROC. REF: AMM 79-30-03										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 79 - OIL										
793012	RIGHT TEMPERATURE OIL BULB								Component	ATA:79
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 79-30-03PROC. REF: AMM 79-30-03										
793013	APU TEMPERATURE OIL BULB								Component	ATA:79
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 79-30-03PROC. REF: AMM 79-30-03										
793064	NO. 1 ENGINE - TEMP BULB								Component	ATA:79
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
793064	NO. 2 ENGINE - TEMP BULB								Component	ATA:79
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
793310	NO. 1 ENGINE - OIL FILTER BYPASS VALVE								Component	ATA:79
PN:3060782-2	MOS/MSC	25-Oct-06	O/C	TSN 0						
SN:060645105349	HRS	4857.2		TSN 0						
	ENC	3730		TSN 0						
793310	NO. 2 ENGINE - OIL FILTER BYPASS VALVE								Component	ATA:79
PN:3060782-2	MOS/MSC	25-Nov-20	O/C	TSO 0						
SN:K15538	HRS	7388.5		TSO 0						
	ENC	6230		TSO 0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10023.1 AFL: 7616 As Of: 26-May-2026

26-May-2026 01:43 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 79 - OIL

793315 ^S			NO. 1 ENGINE - CHECK OIL FILTER BYPASS VALVE CIRCUIT/THERMAL LOCKOUT SWITCH					Service	ATA:79
	MOS	27-Oct-25							
	HRS	9832.1	600						
	ENC	7480							

PKG:0

793315 ^S			NO. 2 ENGINE - CHECK OIL FILTER BYPASS VALVE CIRCUIT/THERMAL LOCKOUT SWITCH					Service	ATA:79
	MOS	27-Oct-25							
	HRS	8993.4	600						
	ENC	7376							

PKG:0

793320			NO. 1 ENGINE - FUEL HEATER / OIL COOLER ASSEMBLY					Component	ATA:79
PN:160506-4	MOS/MSC	30-Nov-16	O/C		TSO 4				
SN:47-486	HRS	7607.6			TSO 0				
	ENC	5820			TSO 0				

PROC. REF: LMM 79-20-07, LMM 79-20-07PROC. REF: LMM 79-20-07, LMM 79-20-07

793320			NO. 2 ENGINE - FUEL HEATER / OIL COOLER ASSEMBLY					Component	ATA:79
PN:160506-4	MOS/MSC	21-Aug-25	O/C		TSN 0				
SN:4216	HRS	8897			TSN 0				
	ENC	7309			TSN 0				

PROC. REF: LMM 79-20-07, LMM 79-20-07PROC. REF: LMM 79-20-07, LMM 79-20-07

ATA 85 - FUEL CELL SYSTEMS

859000			SUBMIT LOGBOOK ENTRIES FOR ELOGBOOK					Service	ATA:85
	MOS/MSC	09-Mar-01	A/R						
	HRS	0							
	AFL	0							

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task