

OWNER: FIRE ROCK LLC		OPERATOR: PRIVATE JETS INC.		
ADDRESS: 7200 NW 63RD STREET BETHANY OK 73008		ADDRESS: 7200 NW 63RD STREET BETHANY OK 73008		
OFFICE:		OFFICE: 405-681-4466		
FAX:		FAX: 405-681-1661		
ANALYST:	CHRISTOPHER CUTLER	+1-316-462-2451 (DIRECT)	800-787-9749 (EFAX-CARDS)	PLEASE REACH OUT TO YOUR ANALYST TO RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY).
EMAIL:	CCUTLER@CAMPSYSTEMS.COM	+1-631-588-3200 (MAIN)	631-980-4222 (EFAX-CARDS)	
		WWW.CAMPSYSTEMS.COM		

AIRCRAFT	SERIAL/REGNO: 45-2027/N116PJ	MODEL:	LEARJET 40XR	MANUFACTURER: BOMBARDIER AVIATION
CERTIFICATION DATE: 10-MAY-2005		LAST ACTUALS:		
		9841.3	A/C HRS	as of 14-SEP-2026
		7790	AFL	as of 14-SEP-2026
		3133.9	ACH	as of 31-AUG-2026

ENGINE NO. 1	SERIAL / PART: P-116596C/3060084-1	MODEL:	TFE731-20BR-1B	MANUFACTURER: HONEYWELL		
INSTALLED ON: 13-MAR-2026		LAST ACTUALS:				
0	ENG. HRS	9596.2	A/C HRS	9757.3	ENG. HRS	as of 14-SEP-2026
	ENC			7752	ENC	as of 14-SEP-2026

ENGINE NO. 2	SERIAL / PART: P-116597C/3060084-1	MODEL:	TFE731-20BR-1B	MANUFACTURER: HONEYWELL		
INSTALLED ON: 13-MAR-2026		LAST ACTUALS:				
0	ENG. HRS	9596.2	A/C HRS	9757.3	ENG. HRS	as of 14-SEP-2026
	ENC			7752	ENC	as of 14-SEP-2026

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 00 - INFORMATION									
CI40-150721		REVIEW CONCORDE EMERGENCY BATTERY CMM 5-0167 REVISION E						Service	ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS	
	HRS								
	AFL								
PROC. REF: RCF CI40		PROC. REF: RCF CI40							
CI40-160527		REVIEW LEARJET 40 AMM REVISION 34						Service	ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS	
	HRS								
	AFL								
PROC. REF: RCF CI40		PROC. REF: RCF CI40							
CI40-160603		REVIEW LEARJET 40 AMM TR 4-28						Service	ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS	
	HRS								
	AFL								
PROC. REF: RCF CI40		PROC. REF: RCF CI40							
CI40-160613		REVIEW LEARJET 40 AMM TR 5-77						Service	ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS	
	HRS								
	AFL								
PROC. REF: RCF CI40		PROC. REF: RCF CI40							
CI40-161207B		REVIEW LEARJET 40 AMM REVISION 35						Service	ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS	
	HRS								
	AFL								
PROC. REF: RCF CI40		PROC. REF: RCF CI40							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR
Serial: 45-2027
RegNo: N116PJ
HRS: 9841.3
AFL: 7790
As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 00 - INFORMATION									
CI40-181109B	REVIEW LEARJET 40/40XR AMM REVISION 39								Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS	
	HRS								
	AFL								
PROC. REF: RCF CI40PROC. REF: RCF CI40									
CI40-190429A	REVIEW LEARJET 40/40XR AMM REV 40								Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS	
	HRS								
	AFL								
PROC. REF: RCF CI40PROC. REF: RCF CI40									
CI40-200529	REVIEW AUDIT SUMMARY CHANGE FORM								Service ATA:00
	MOS/MSC	EFF	-					AUDIT SUMMARY CHANGE FORM	
	HRS								
	AFL								
PROC. REF: RCF CI40PROC. REF: RCF CI40									
CI40-210120	REVIEW LEARJET 40/40XR AUDIT SUMMARY CHANGE FORM								Service ATA:00
	MOS/MSC	EFF	-					AUDIT SUMMARY CHANGE FORM	
	HRS								
	AFL								
PROC. REF: RCF CI40PROC. REF: RCF CI40									
EC04-180802	NO. 1 ENGINE - REVIEW TFE731-20/-40/-60 (CIMMS) LMM TR 5-17								Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS	
	HRS								
	ENC								
PROC. REF: RCF EC04-180802PROC. REF: RCF EC04-180802									

? - Insufficient Information
S - Suppressed Requirement
* - Estimated Due(New Requirement)
(EFF) - Effective C / W
(M) - Manual Due
U - User Task
Ex - Excluded Task

Status Report

Model: LEARJET 40XR
 Serial: 45-2027
 RegNo: N116PJ
 HRS: 9841.3
 AFL: 7790
 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 00 - INFORMATION									
EC04-180802	NO. 2 ENGINE - REVIEW TFE731-20/-40/-60 (CIMMS) LMM TR 5-17								Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS	
	HRS								
	ENC								
PROC. REF: RCF EC04-180802PROC. REF: RCF EC04-180802									
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
051101	PERFORM PHASE A1-300 HOUR CHECKS								Package ATA:05
	MOS	13-Mar-26	12 (+14d/-14d)		13-Mar-27	27-Mar-27	179 d (+14)		
	HRS	9596.2	300 (+25/-25)		9896.2	9921.2	54.9 (+25)		
	AFL	7624							
PROC. REF: AMM 05-11-01PROC. REF: AMM 05-11-01									
051102	PERFORM PHASE A2-300 HOUR CHECKS								Package ATA:05
	MOS	13-Mar-26	12 (+14d/-14d)		13-Mar-27	27-Mar-27	179 d (+14)		
	HRS	9596.2	300 (+25/-25)		9896.2	9921.2	54.9 (+25)		
	AFL	7624							
PROC. REF: AMM 05-11-02PROC. REF: AMM 05-11-02									
051103	PERFORM PHASE A3-300 HOUR CHECKS								Package ATA:05
	MOS	13-Mar-26	12 (+14d/-14d)		13-Mar-27	27-Mar-27	179 d (+14)		
	HRS	9596.2	300 (+25/-25)		9896.2	9921.2	54.9 (+25)		
	AFL	7624							
PROC. REF: AMM 05-11-03PROC. REF: AMM 05-11-03									
051104	PERFORM PHASE A4-300 HOUR CHECKS								Package ATA:05
	MOS	13-Mar-26	12 (+14d/-14d)		13-Mar-27	27-Mar-27	179 d (+14)		
	HRS	9596.2	300 (+25/-25)		9896.2	9921.2	54.9 (+25)		
	AFL	7624							
PROC. REF: AMM 05-11-04PROC. REF: AMM 05-11-04									

?-Insufficient Information
 S-Suppressed Requirement
 *-Estimated Due(New Requirement)
 (EFF)-Effective C/W
 (M)-Manual Due
 U-User Task
 Ex-Excluded Task

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
051105	PERFORM PHASE A5-300 HOUR CHECKS							Package	ATA:05
	MOS	13-Mar-26	12 (+14d/-14d)		13-Mar-27	27-Mar-27	179 d (+14)		
	HRS	9596.2	300 (+25/-25)		9896.2	9921.2	54.9 (+25)		
	AFL	7624							
PROC. REF: AMM 05-11-05PROC. REF: AMM 05-11-05									PKG:5
051106	PERFORM PHASE A6-300 HOUR CHECKS							Package	ATA:05
	MOS	13-Mar-26	12 (+14d/-14d)		13-Mar-27	27-Mar-27	179 d (+14)		
	HRS	9596.2	300 (+25/-25)		9896.2	9921.2	54.9 (+25)		
	AFL	7624							
PROC. REF: AMM 05-11-06PROC. REF: AMM 05-11-06									PKG:6
051201	PERFORM PHASE B1-600 HOUR CHECKS							Package	ATA:05
	MOS	13-Mar-26	24 (+14d/-14d)		13-Mar-28	27-Mar-28	545 d (+14)		
	HRS	9596.2	600 (+25/-25)		10196.2	10221.2	354.9 (+25)		
	AFL	7624							
PROC. REF: AMM 05-12-01PROC. REF: AMM 05-12-01									PKG:7
051202	PERFORM PHASE B2-600 HOUR CHECKS							Package	ATA:05
	MOS	13-Mar-26	24 (+14d/-14d)		13-Mar-28	27-Mar-28	545 d (+14)		
	HRS	9596.2	600 (+25/-25)		10196.2	10221.2	354.9 (+25)		
	AFL	7624							
PROC. REF: AMM 05-12-02PROC. REF: AMM 05-12-02									PKG:8
051203	PERFORM PHASE B3-600 HOUR CHECKS							Package	ATA:05
	MOS	13-Mar-26	24 (+14d/-14d)		13-Mar-28	27-Mar-28	545 d (+14)		
	HRS	9596.2	600 (+25/-25)		10196.2	10221.2	354.9 (+25)		
	AFL	7624							
PROC. REF: AMM 05-12-03PROC. REF: AMM 05-12-03									PKG:9

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
051204	PERFORM PHASE B4-600 HOUR CHECKS							Package	ATA:05
	MOS	13-Mar-26	24 (+14d/-14d)		13-Mar-28	27-Mar-28	545 d (+14)		
	HRS	9596.2	600 (+25/-25)		10196.2	10221.2	354.9 (+25)		
	AFL	7624							
PROC. REF: AMM 05-12-04PROC. REF: AMM 05-12-04									PKG:10
051205	PERFORM PHASE B5-600 HOUR CHECKS							Package	ATA:05
	MOS	13-Mar-26	24 (+14d/-14d)		13-Mar-28	27-Mar-28	545 d (+14)		
	HRS	9596.2	600 (+25/-25)		10196.2	10221.2	354.9 (+25)		
	AFL	7624							
PROC. REF: AMM 05-12-05PROC. REF: AMM 05-12-05									PKG:11
051206	PERFORM PHASE B6-600 HOUR CHECKS							Package	ATA:05
	MOS	13-Mar-26	24 (+14d/-14d)		13-Mar-28	27-Mar-28	545 d (+14)		
	HRS	9596.2	600 (+25/-25)		10196.2	10221.2	354.9 (+25)		
	AFL	7624							
PROC. REF: AMM 05-12-06PROC. REF: AMM 05-12-06									PKG:12
051301	PERFORM PHASE C1-1200 HOUR CHECKS							Package	ATA:05
	MOS	13-Mar-26	48 (+14d/-14d)		13-Mar-30	27-Mar-30	1275 d (+14)		
	HRS	9596.2	1200 (+25/-25)		10796.2	10821.2	954.9 (+25)		
	AFL	7624							
PROC. REF: AMM 05-13-01PROC. REF: AMM 05-13-01									PKG:13
051302	PERFORM PHASE C2-1200 HOUR CHECKS							Package	ATA:05
	MOS	13-Mar-26	48 (+14d/-14d)		13-Mar-30	27-Mar-30	1275 d (+14)		
	HRS	9596.2	1200 (+25/-25)		10796.2	10821.2	954.9 (+25)		
	AFL	7624							
PROC. REF: AMM 05-13-02PROC. REF: AMM 05-13-02									PKG:14

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR
Serial: 45-2027
RegNo: N116PJ
HRS: 9841.3
AFL: 7790
As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
051303	PERFORM PHASE C3-1200 HOUR CHECKS							Package	ATA:05
	MOS	13-Mar-26	48 (+14d/-14d)		13-Mar-30	27-Mar-30	1275 d (+14)		
	HRS	9596.2	1200 (+25/-25)		10796.2	10821.2	954.9 (+25)		
	AFL	7624							
PROC. REF: AMM 05-13-03PROC. REF: AMM 05-13-03									PKG:15
051304	PERFORM PHASE C4-1200 HOUR CHECKS							Package	ATA:05
	MOS	13-Mar-26	48 (+14d/-14d)		13-Mar-30	27-Mar-30	1275 d (+14)		
	HRS	9596.2	1200 (+25/-25)		10796.2	10821.2	954.9 (+25)		
	AFL	7624							
PROC. REF: AMM 05-13-04PROC. REF: AMM 05-13-04									PKG:16
051305	PERFORM PHASE C5-1200 HOUR CHECKS							Package	ATA:05
	MOS	13-Mar-26	48 (+14d/-14d)		13-Mar-30	27-Mar-30	1275 d (+14)		
	HRS	9596.2	1200 (+25/-25)		10796.2	10821.2	954.9 (+25)		
	AFL	7624							
PROC. REF: AMM 05-13-05PROC. REF: AMM 05-13-05									PKG:17
051306	PERFORM PHASE C6-1200 HOUR CHECKS							Package	ATA:05
	MOS	13-Mar-26	48 (+14d/-14d)		13-Mar-30	27-Mar-30	1275 d (+14)		
	HRS	9596.2	1200 (+25/-25)		10796.2	10821.2	954.9 (+25)		
	AFL	7624							
PROC. REF: AMM 05-13-06PROC. REF: AMM 05-13-06									PKG:18
051401	PERFORM PHASE D1-2400 HOUR CHECKS							Package	ATA:05
	MOS	13-Mar-26	96 (+14d/-14d)		13-Mar-34	27-Mar-34	2736 d (+14)		
	HRS	9596.2	2400 (+25/-25)		11996.2	12021.2	2154.9 (+25)		
	AFL	7624							
PROC. REF: AMM 05-14-01PROC. REF: AMM 05-14-01									PKG:19

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C/W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
051402	PERFORM PHASE D2-2400 HOUR CHECKS							Package	ATA:05
	MOS	13-Mar-26	96 (+14d/-14d)		13-Mar-34	27-Mar-34	2736 d (+14)		
	HRS	9596.2	2400 (+25/-25)		11996.2	12021.2	2154.9 (+25)		
	AFL	7624							
PROC. REF: AMM 05-14-02PROC. REF: AMM 05-14-02									PKG:20
051403	PERFORM PHASE D3-2400 HOUR CHECKS							Package	ATA:05
	MOS	13-Mar-26	96 (+14d/-14d)		13-Mar-34	27-Mar-34	2736 d (+14)		
	HRS	9596.2	2400 (+25/-25)		11996.2	12021.2	2154.9 (+25)		
	AFL	7624							
PROC. REF: AMM 05-14-03PROC. REF: AMM 05-14-03									PKG:21
051404	PERFORM PHASE D4-2400 HOUR CHECKS							Package	ATA:05
	MOS	13-Mar-26	96 (+14d/-14d)		13-Mar-34	27-Mar-34	2736 d (+14)		
	HRS	9596.2	2400 (+25/-25)		11996.2	12021.2	2154.9 (+25)		
	AFL	7624							
PROC. REF: AMM 05-14-04PROC. REF: AMM 05-14-04									PKG:22
051405	PERFORM PHASE D5-2400 HOUR CHECKS							Package	ATA:05
	MOS	13-Mar-26	96 (+14d/-14d)		13-Mar-34	27-Mar-34	2736 d (+14)		
	HRS	9596.2	2400 (+25/-25)		11996.2	12021.2	2154.9 (+25)		
	AFL	7624							
PROC. REF: AMM 05-14-05PROC. REF: AMM 05-14-05									PKG:23
051406	PERFORM PHASE D6-2400 HOUR CHECKS							Package	ATA:05
	MOS	13-Mar-26	96 (+14d/-14d)		13-Mar-34	27-Mar-34	2736 d (+14)		
	HRS	9596.2	2400 (+25/-25)		11996.2	12021.2	2154.9 (+25)		
	AFL	7624							
PROC. REF: AMM 05-14-06PROC. REF: AMM 05-14-06									PKG:24

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS / MAINTENANCE CHECKS									
051500	PERFORM 4800 HOUR CHECKS							Package	ATA:05
	MOS	13-Mar-26							
	HRS	9596.2	4800		14396.2		4554.9		
	AFL	7624							
PROC. REF: AMM 05-15-00PROC. REF: AMM 05-15-00									PKG:25
051600	PERFORM 9600 HOUR CHECKS							Package	ATA:05
	MOS	13-Mar-26							
	HRS	9596.2	9600		19196.2		9354.9		
	AFL	7624							
PROC. REF: AMM 05-16-00PROC. REF: AMM 05-16-00									PKG:26
051700	PERFORM MAJOR LANDING GEAR INSPECTION							Package	ATA:05
	MOS	10-May-05							
	HRS	0							
	AFL	0	10000		10000		2210		
PROC. REF: AMM 05-17-00PROC. REF: AMM 05-17-00									PKG:27
057110	NO. 1 ENGINE - 150 TO 250 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							Package	ATA:05
	MOS	17-Aug-26							
	HRS	9734.6	250 (-100)		(9984.6) 10068.6		227.3		
	ENC	7734							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									
057110	NO. 2 ENGINE - 150 TO 250 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							Package	ATA:05
	MOS	17-Aug-26							
	HRS	9734.6	250 (-100)		(9984.6) 10068.6		227.3		
	ENC	7734							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C / W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
057120	NO. 1 ENGINE - 300 TO 440 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS								Package ATA:05
	MOS/MSC	25-Jan-05	N/A						
	HRS	0							
	ENC	0							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									
057120	NO. 2 ENGINE - 300 TO 440 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS								Package ATA:05
	MOS/MSC	26-Jan-05	N/A						
	HRS	0							
	ENC	0							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									
057130	NO. 1 ENGINE - 500 TO 650 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS								Package ATA:05
	MOS	21-Aug-25							
	HRS	9510	600 (+50/-100)		(10110) 10194	10160	352.7 (+50)		
	ENC	7585							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									
057130	NO. 2 ENGINE - 500 TO 650 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS								Package ATA:05
	MOS	25-Aug-25							
	HRS	9510	600 (+50/-100)		(10110) 10194	10160	352.7 (+50)		
	ENC	7585							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									
057140	NO. 1 ENGINE - 500 TO 850 HOUR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS								Package ATA:05
	MOS	21-Aug-25							
	HRS	9510	850 (-350)		(10360) 10444		602.7		
	ENC	7585							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									

?-Insufficient Information

S-Suppressed Requirement

*-Estimated Due(New Requirement)

(EFF)-Effective C/W

(M)-Manual Due

U-User Task

Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
057140	NO. 2 ENGINE - 500 TO 850 HOUR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS								Package ATA:05
	MOS	25-Aug-25							
	HRS	9510	850 (-350)		(10360) 10444		602.7		
	ENC	7585							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									
057150	NO. 1 ENGINE - 1000 TO 1300 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS								Package ATA:05
	MOS	21-Aug-25							
	HRS	9510	1200 (+100/-200)		(10710) 10794	10810	952.7 (+100)		
	ENC	7585							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									
057150	NO. 2 ENGINE - 1000 TO 1300 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS								Package ATA:05
	MOS	25-Aug-25							
	HRS	9510	1200 (+100/-200)		(10710) 10794	10810	952.7 (+100)		
	ENC	7585							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									
057160	NO. 1 ENGINE - 1500 TO 1650 HOUR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS								Package ATA:05
	MOS	21-Aug-25							
	HRS	9510	1600 (+50/-100)		(11110) 11194	11160	1352.7 (+50)		
	ENC	7585							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									
057160	NO. 2 ENGINE - 1500 TO 1650 HOUR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS								Package ATA:05
	MOS	25-Aug-25							
	HRS	9510	1600 (+50/-100)		(11110) 11194	11160	1352.7 (+50)		
	ENC	7585							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR
Serial: 45-2027
RegNo: N116PJ
HRS: 9841.3
AFL: 7790
As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
05	REGISTRATION ^U	RENEW AIRCRAFT REGISTRATION							Service ATA:05
	MOS/MSC	13-Aug-16	A/R					CUSTOMER OPERATIONS REQUIREMENT	
	HRS	6857.7							
	AFL	5573							
PROC. REF: AMM 05-50-00PROC. REF: AMM 05-50-00									
5-50-00-EV	PERFORM ENGINE VIBRATION TEST AND INSPECTION							Service	ATA:05
	MOS/MSC		A/R						
	HRS								
	AFL								
PROC. REF: AMM 05-50-00PROC. REF: AMM 05-50-00									
5-50-00-FD	INSPECTION FOREIGN OBJECT DAMAGE							Service	ATA:05
	MOS/MSC		O/C					O/C - ON CONDITION	
	HRS								
	AFL								
PROC. REF: AMM 05-50-00PROC. REF: AMM 05-50-00									
ATA 08 - LEVELING AND WEIGHING									
080000	WEIGHT AND BALANCE							Service	ATA:08
	MOS	16-Oct-24	36 (+14d/-14d)	Adj -16d	30-Sep-27	14-Oct-27	380 d (+14)		
	HRS	9492.6							
	AFL	7560							
PROC. REF: AMM 08-10-00, FAR 135.185PROC. REF: AMM 08-10-00, FAR 135.185									
ATA 11 - PLACARDS AND MARKINGS									
G1130000 ^S	CHECK BRIGHTNESS LEVEL OF ALL SELF-LUMINOUS PLACARDS							Service	ATA:11
	MOS	13-Mar-26	48 (+14d/-14d)						
	HRS	9596.2	1200 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 11-30-00PROC. REF: AMM 11-30-00									
PKG:13									

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C/W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 12 - SERVICING									
5-19-00-Q1221064	FLAP ACTUATOR JOINT (P/N 145673-1) - APPLY CORROSION PREVENTIVE COMPOUND (CPC)								Service ATA:12
	MOS/MSC	25-Jan-15	-					N/A BY PART NUMBER	
	HRS								
	AFL								
PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03									
5-19-00-U1210004	FLAP FLEXIBLE TRANSMISSION SHAFTS - HAND LUBRICATE								Service ATA:12
	MOS	25-Jan-15							
	HRS	6669.27	4800 (+25/-25)		11469.27	11494.27	1628 (+25)		
	AFL	5419							
PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03									
AB1210060 ^S	MAIN LANDING GEAR UP-LOCK ACTUATOR - LUBRICATE								Service ATA:12
	MOS	13-Mar-26	12						
	HRS	9596.2	300						
	AFL	7624							
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01									
O1210002 ^S	FLAP ACTUATORS - CHECK OIL LEVEL.								Service ATA:12
	MOS	13-Mar-26	24 (+14d/-14d)						
	HRS	9596.2	600 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03									
Y1210000 ^S	NOSE LANDING GEAR SHOCK STRUT - CHECK FOR PROPER FLUID LEVEL AND INFLATION PRESSURE.								Service ATA:12
	MOS	13-Mar-26	12 (+14d/-14d)						
	HRS	9596.2	300 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 12-10-02PROC. REF: AMM 12-10-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR
Serial: 45-2027
RegNo: N116PJ
HRS: 9841.3
AFL: 7790
As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 12 - SERVICING									
Y1210001	^S	MAIN LANDING GEAR SHOCK STRUTS - CHECK FOR PROPER FLUID LEVEL AND INFLATION PRESSURE						Service	ATA:12
	MOS	13-Mar-26	12	(+14d/-14d)					
	HRS	9596.2	300	(+25/-25)					
	AFL	7624							
PROC. REF: AMM 12-10-03PROC. REF: AMM 12-10-03									PKG:5
Y1210003	^S	LUBRICATE FLAP ACTUATOR BALLNUT						Service	ATA:12
	MOS	13-Mar-26	12	(+14d/-14d)					
	HRS	9596.2	300	(+25/-25)					
	AFL	7624							
PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03									PKG:4
Y1210005	^S	LUBRICATE NOSE LANDING GEAR TRUNNION PIN						Service	ATA:12
	MOS	13-Mar-26	12	(+14d/-14d)					
	HRS	9596.2	300	(+25/-25)					
	AFL	7624							
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01									PKG:5
Y1210006	^S	LUBRICATE NOSE LANDING GEAR ACTUATOR ATTACH FITTING						Service	ATA:12
	MOS	13-Mar-26	12	(+14d/-14d)					
	HRS	9596.2	300	(+25/-25)					
	AFL	7624							
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01									PKG:5
Y1210007	^S	CHECK NOSE AND MAIN TIRES FOR PROPER INFLATION.						Service	ATA:12
	MOS	13-Mar-26	12	(+14d/-14d)					
	HRS	9596.2	300	(+25/-25)					
	AFL	7624							
PROC. REF: AMM 12-10-04PROC. REF: AMM 12-10-04									PKG:5

? - Insufficient Information
S - Suppressed Requirement
* - Estimated Due(New Requirement)
(EFF) - Effective C / W
(M) - Manual Due
U - User Task
Ex - Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 12 - SERVICING										
Y1210009 ^S		LUBRICATE NOSE GEAR DOOR HINGE							Service	ATA:12
	MOS	13-Mar-26	12	(+14d/-14d)						
	HRS	9596.2	300	(+25/-25)						
	AFL	7624								
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02									PKG:1	
Y1210011 ^S		LUBRICATE MAIN LANDING GEAR ACTUATOR JOINTS							Service	ATA:12
	MOS	13-Mar-26	12	(+14d/-14d)						
	HRS	9596.2	300	(+25/-25)						
	AFL	7624								
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01									PKG:5	
Y1210012 ^S		LUBRICATE MAIN LANDING GEAR AXLE BEAM/PISTON JOINTS							Service	ATA:12
	MOS	13-Mar-26	12	(+14d/-14d)						
	HRS	9596.2	300	(+25/-25)						
	AFL	7624								
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01									PKG:5	
Y1210013 ^S		LUBRICATE MAIN LANDING GEAR TORQUE LINKS							Service	ATA:12
	MOS	13-Mar-26	12	(+14d/-14d)						
	HRS	9596.2	300	(+25/-25)						
	AFL	7624								
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01									PKG:5	
Y1210014 ^S		LUBRICATE MAIN GEAR DOOR HINGE							Service	ATA:12
	MOS	13-Mar-26	12	(+14d/-14d)						
	HRS	9596.2	300	(+25/-25)						
	AFL	7624								
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02									PKG:5	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR
Serial: 45-2027
RegNo: N116PJ
HRS: 9841.3
AFL: 7790
As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 12 - SERVICING									
Y1210016 ^S		LUBRICATE PASSENGER/CREW DOOR HINGE						Service	ATA:12
	MOS	13-Mar-26	12 (+14d/-14d)						
	HRS	9596.2	300 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02									PKG:6
Y1210017 ^S		LUBRICATE PASSENGER/CREW DOOR PINS						Service	ATA:12
	MOS	13-Mar-26	12 (+14d/-14d)						
	HRS	9596.2	300 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02									PKG:6
Y1210018 ^S		LUBRICATE PASSENGER/CREW DOOR TENSION BOLTS						Service	ATA:12
	MOS	13-Mar-26	12 (+14d/-14d)						
	HRS	9596.2	300 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02									PKG:6
Y1210019 ^S		LUBRICATE EMERGENCY EXIT DOOR LATCHING MECHANISM						Service	ATA:12
	MOS	13-Mar-26	12 (+14d/-14d)						
	HRS	9596.2	300 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02									PKG:6
Y1210020 ^S		LUBRICATE EMERGENCY EXIT DOOR PINS						Service	ATA:12
	MOS	13-Mar-26	12 (+14d/-14d)						
	HRS	9596.2	300 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02									PKG:6

? - Insufficient Information
S - Suppressed Requirement
* - Estimated Due(New Requirement)
(EFF) - Effective C / W
(M) - Manual Due
U - User Task
Ex - Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 12 - SERVICING									
Y1210021 ^S	LUBRICATE BAGGAGE COMPARTMENT DOOR LATCH PINS								Service ATA:12
	MOS	13-Mar-26	12 (+14d/-14d)						
	HRS	9596.2	300 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02									PKG:6
Y1210022 ^S	LUBRICATE BAGGAGE COMPARTMENT DOOR HINGE								Service ATA:12
	MOS	13-Mar-26	12 (+14d/-14d)						
	HRS	9596.2	300 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02									PKG:6
Y1210023 ^S	LUBRICATE OXYGEN SYSTEM SERVICING DOOR HINGE								Service ATA:12
	MOS	13-Mar-26	12 (+14d/-14d)						
	HRS	9596.2	300 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02									PKG:1
Y1210024 ^S	LUBRICATE TOILET SERVICING DOOR HINGE								Service ATA:12
	MOS	13-Mar-26	12 (+14d/-14d)						
	HRS	9596.2	300 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02									PKG:4
Y1210025 ^S	LUBRICATE PRESSURE REFUELING DOOR HINGE								Service ATA:12
	MOS	13-Mar-26	12 (+14d/-14d)						
	HRS	9596.2	300 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02									PKG:2

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR
Serial: 45-2027
RegNo: N116PJ
HRS: 9841.3
AFL: 7790
As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 12 - SERVICING									
Y1210026 ^S	LUBRICATE FUSELAGE FUEL FILLER DOOR HINGE								Service ATA:12
	MOS	13-Mar-26	12 (+14d/-14d)						
	HRS	9596.2	300 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02									
PKG:2									
Y1210027 ^S	LUBRICATE TAILCONE ACCESS DOOR PINS								Service ATA:12
	MOS	13-Mar-26	12 (+14d/-14d)						
	HRS	9596.2	300 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02									
PKG:6									
Y1210028 ^S	LUBRICATE TAILCONE ACCESS DOOR HINGE								Service ATA:12
	MOS	13-Mar-26	12 (+14d/-14d)						
	HRS	9596.2	300 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02									
PKG:6									
Y1210029 ^S	LUBRICATE MAIN LANDING GEAR TRUNNION PIN								Service ATA:12
	MOS	13-Mar-26	12 (+14d/-14d)						
	HRS	9596.2	300 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01									
PKG:5									
Y1221037 ^S	FLAPS - LUBRICATE ROLLING SURFACES OF MAIN AND NOSE ROLLER TRACKS.								Service ATA:12
	MOS	13-Mar-26	12 (+14d/-14d)						
	HRS	9596.2	300 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03									
PKG:4									

? - Insufficient Information
S - Suppressed Requirement
* - Estimated Due(New Requirement)
(EFF) - Effective C / W
(M) - Manual Due
U - User Task
Ex - Excluded Task

Status Report

Model: LEARJET 40XR
 Serial: 45-2027
 RegNo: N116PJ
 HRS: 9841.3
 AFL: 7790
 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 12 - SERVICING									
Y1221042 ^S		LUBRICATE HORIZONTAL STABILIZER UPPER AND LOWER TORQUE LINKS						Service	ATA:12
	MOS	13-Mar-26	24 (+14d/-14d)						
	HRS	9596.2	600 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03									
PKG:9									
Y1227000 ^S		LUBRICATE EMERGENCY PARK BRAKE HANDLE SHAFT						Service	ATA:12
	MOS	13-Mar-26	12 (+14d/-14d)						
	HRS	9596.2	300 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 12-27-00PROC. REF: AMM 12-27-00									
PKG:1									
ATA 21 - AIR CONDITIONING									
212011		NO. 1 EMERGENCY PRESSURIZATION CHECK VALVE						Component	ATA:21
PN:6621000000-043	MOS/MSC	10-May-05	O/C	TSN 0					
SN:2581	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-20-03PROC. REF: AMM 21-20-03									
212012		NO.2 EMERGENCY PRESSURIZATION CHECK VALVE						Component	ATA:21
PN:6621000000-043	MOS/MSC	10-May-05	O/C	TSN 0					
SN:2588	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-20-03PROC. REF: AMM 21-20-03									
212810		ASSY, AVIONICS COOLING FAN MOUNT						Component	ATA:21
PN:4521208521-009	MOS/MSC	10-May-05	O/C	TSN 0					
SN:A00318352C	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-21-01PROC. REF: AMM 21-21-01									
213000		CABIN PRESSURE CONTROLLER						Component	ATA:21
PN:6621300000-029	MOS/MSC	10-May-05	O/C	TSN 0					
SN:50-H0130	HRS	0		TSN 0					
	AFL	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR

Serial: 45-2027

RegNo: N116PJ

HRS: 9841.3

AFL: 7790

As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
PROC. REF: AMM 21-30-03PROC. REF: AMM 21-30-03									
213001	LEFT EMERGENCY PRESSURE SHUTOFF VALVE								Component ATA:21
PN:3291224-1	MOS/MSC	08-Apr-22	O/C						
SN:710	HRS	8768							
	AFL	7041							
PROC. REF: AMM 21-31-01PROC. REF: AMM 21-31-01									
213002	RIGHT EMERGENCY PRESSURE SHUTOFF VALVE								Component ATA:21
PN:3291224-1	MOS/MSC	08-Apr-22	O/C						
SN:717	HRS	8768							
	AFL	7041							
PROC. REF: AMM 21-31-01PROC. REF: AMM 21-31-01									
213031	PRIMARY OUTFLOW VALVE								Component ATA:21
PN:103858-1	MOS/MSC	10-May-05	O/C	TSN 0					
SN:104-A0334	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-30-01PROC. REF: AMM 21-30-01									
213032	SECONDARY OUTFLOW VALVE								Component ATA:21
PN:103858-2	MOS/MSC	03-Jun-13	O/C						
SN:86-B0004	HRS	5513.02							
	AFL	4486							
PROC. REF: AMM 21-30-02PROC. REF: AMM 21-30-02									
213055	EMERGENCY PRESSURE ANEROID SWITCH								Component ATA:21
PN:E45C-47	MOS/MSC	10-May-05	O/C	TSN 0					
SN:4978	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
213105	TAILCONE CHECK CABIN PRESS VALVE								Component ATA:21
PN:130158-3-1	MOS/MSC	10-May-05	O/C	TSN 0					
SN:94-A0631	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information

S-Suppressed Requirement

*-Estimated Due(New Requirement)

(EFF)-Effective C / W

(M)-Manual Due

U-User Task

Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
215004	WATER SEPARATOR ASSEMBLY							Component	ATA:21
PN:2341168-1	MOS/MSC	10-May-05	O/C	TSN 0					
SN:408	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-50-03PROC. REF: AMM 21-50-03									
215005	(KEITH PRODUCTS) PALLET AIR CONDITIONING COMPRESSOR ASSEMBLY							Component	ATA:21
PN:JBS222-1	MOS/MSC	16-Mar-26	O/C	TSO 0					
SN:K55753	HRS	9596.2		TSO 0					
	AFL	7624		TSO 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
215007	(R-134) AIR CONDITIONING COMPRESSOR DRIVE MOTOR							Component	ATA:21
PN:ES61110-4	MOS	16-Mar-26							
SN:0189	HRS	9596.2							
	AFL	7624							
	ACH	3089.7	1200 (+25/-25)	TSN 482.3	3807.4	3832.4	673.5 (+25)		
PROC. REF: AMM 21-51-02PROC. REF: AMM 21-51-02									
215007A	(R-134) AIR CONDITIONING COMPRESSOR DRIVE MOTOR BRUSHES - PERFORM WEAR INSPECTION (IRN L2150054)							Service	ATA:21
PN:ES61110-4	MOS	16-Mar-26							
SN:0189	HRS	9596.2							
	AFL	7624							
	ACH	3089.7	600 (+25/-25)		3689.7	3714.7	555.8 (+25)		
PROC. REF: AMM 21-51-00PROC. REF: AMM 21-51-00									
215019	(KEITH PRODUCTS) AIR CONDITIONING CONDENSOR ASSEMBLY							Component	ATA:21
PN:45-0350-1	MOS/MSC	10-May-05	O/C	TSN 0					
SN:K11695	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-51-04PROC. REF: AMM 21-51-04									
215024	(KEITH PRODUCTS) AIR CONDITIONING MAINTENANCE PANEL							Component	ATA:21
PN:45-1756-1	MOS/MSC	10-May-05	O/C	TSN 0					
SN:L11366	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
215030	ENVIRONMENTAL CONTROL UNIT							Component	ATA:21
PN:6621000000-081	MOS/MSC	10-May-05	O/C	TSN 0					
SN:075C-0108	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-50-01PROC. REF: AMM 21-50-01									
215051	(KEITH PRODUCTS) AIR CONDITIONER ASSEMBLY LOAD SHED							Component	ATA:21
PN:45-0755-1	MOS/MSC	10-May-05	O/C	TSN 0					
SN:K11240	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-51-12PROC. REF: AMM 21-51-12									
215052	FWD (KEITH PRODUCTS) AIR CONDITIONING ASSEMBLY EVAPORATOR							Component	ATA:21
PN:45-0250-2	MOS/MSC	10-May-05	O/C	TSN 0					
SN:K11474	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
215053	AFT AIR CONDITIONING ASSEMBLY(KEITH PRODUCTS) EVAPORATOR							Component	ATA:21
PN:45-0263-1	MOS/MSC	10-May-05	O/C	TSN 0					
SN:K11450	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
215054	AUX (KEITH PRODUCTS) HEATER ASSEMBLY							Component	ATA:21
PN:45-0264-1	MOS/MSC	10-May-05	O/C	TSN 0					
SN:K11500	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-51-13PROC. REF: AMM 21-51-13									
215055	FWD EVAPORATOR ASSEMBLY MOTOR							Component	ATA:21
PN:ES61136-2	MOS/MSC	10-May-05	O/C	TSN 0					
SN:0920	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR
Serial: 45-2027
RegNo: N116PJ
HRS: 9841.3
AFL: 7790
As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
215056	AFT EVAPORATOR ASSEMBLY MOTOR							Component	ATA:21
PN:ES61136-2	MOS/MSC	10-May-05	O/C	TSN 0					
SN:0908	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
216001	INTEGRATED ECS TEMP CONTROLLER							Component	ATA:21
PN:1151830-3	MOS/MSC	10-May-05	O/C	TSN 0					
SN:1151830-00681	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-60-10PROC. REF: AMM 21-60-10									
216013	COCKPIT TEMPERATURE CONTROL VALVE							Component	ATA:21
PN:6621000000-047	MOS/MSC	10-May-05	O/C	TSN 0					
SN:735	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-60-05PROC. REF: AMM 21-60-05									
216014	CABIN TEMPERATURE CONTROL VALVE							Component	ATA:21
PN:3291222-1	MOS/MSC	31-Dec-19	O/C						
SN:964	HRS	7795							
	AFL	6296							
PROC. REF: AMM 21-60-04PROC. REF: AMM 21-60-04									
5-19-00-Y2130065	LEAKAGE TEST CABIN PRESSURIZATION SYSTEM (IRN W2130065)							Service	ATA:21
	MOS	13-Mar-26							
	HRS	9596.2	1200 (+25/-25)		10796.2	10821.2	954.9 (+25)		
	AFL	7624							
PROC. REF: AMM 21-30-00PROC. REF: AMM 21-30-00									
5-19-01-Y2141002	REPLACE WATER SEPARATOR COALESCER BAG (IRN Y2141002)							Service	ATA:21
	MOS/MSC	04-Aug-05	-						
	HRS	31.7							
	AFL	22							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C/W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
J2160008	^S	TEMPERATURE CONTROL SYSTEM - INSPECT AND CLEAN CABIN AND COCKPIT TEMPERATURE CONTROL VALVE SERVO AIR FILTERS.						Service	ATA:21
	MOS	13-Mar-26	24 (+14d/-14d)						
	HRS	9596.2	600 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 21-60-11PROC. REF: AMM 21-60-11									PKG:8
L2150056	^S	** AUXILIARY HEAT SYSTEM - PERFORM FUNCTIONAL TEST. (AWL**)						Service	ATA:21
	MOS	13-Mar-26	24 (+14d/-14d)					AIRWORTHINESS	
	HRS	9596.2	600 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 21-51-00PROC. REF: AMM 21-51-00									PKG:8
L2150057	^S	** AUXILIARY HEAT SYSTEM - PERFORM AUXILIARY HEATER ELECTRICAL AND TEMPERATURE TEST (AWL**)						Service	ATA:21
	MOS	13-Mar-26	48 (+14d/-14d)					AIRWORTHINESS	
	HRS	9596.2	1200 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 21-51-00PROC. REF: AMM 21-51-00									PKG:14
O2130000	^S	PRIMARY AND SECONDARY OUTFLOW VALVES - PERFORM INSPECTION.						Service	ATA:21
	MOS	13-Mar-26	48 (+14d/-14d)						
	HRS	9596.2	1200 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 21-30-01, AMM 21-30-02PROC. REF: AMM 21-30-01, AMM 21-30-02									PKG:13
O2130001	^S	REPLACE OUTFLOW VALVE AIR FILTER - REMOVE AND REPLACE.						Service	ATA:21
	MOS	13-Mar-26	96 (+14d/-14d)						
	HRS	9596.2	2400 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 21-30-04PROC. REF: AMM 21-30-04									PKG:19

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
O2130002	^S	** PRESSURIZATION CONTROL SYSTEM - PERFORM FUNCTIONAL TEST. (AWL**)						Service	ATA:21
	MOS	13-Mar-26	48 (+14d/-14d)					AIRWORTHINESS	
	HRS	9596.2	1200 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 21-30-00PROC. REF: AMM 21-30-00									PKG:13
Y2130003	^S	PRESSURIZATION CONTROL SYSTEM - PERFORM OPERATIONAL CHECK						Service	ATA:21
	MOS	13-Mar-26	24 (+14d/-14d)						
	HRS	9596.2	600 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 21-30-00PROC. REF: AMM 21-30-00									PKG:7
Y2140000	^S	AIR CYCLE MACHINE HEAT EXCHANGER INLET - PERFORM VISUAL INSPECTION						Service	ATA:21
	MOS	13-Mar-26	48 (+14d/-14d)						
	HRS	9596.2	1200 (+25/-25)						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:14
Y2141000	^S	ENVIRONMENTAL CONTROL UNIT - PERFORM VISUAL INSPECTION						Service	ATA:21
	MOS	13-Mar-26	48 (+14d/-14d)						
	HRS	9596.2	1200 (+25/-25)						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:14
Y2141001	^S	WATER SEPARATOR COALESCER BAG - PERFORM VISUAL INSPECTION. CLEAN IF NECESSARY.						Service	ATA:21
	MOS	13-Mar-26	12 (+14d/-14d)						
	HRS	9596.2	300 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 21-50-03PROC. REF: AMM 21-50-03									PKG:2

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR
Serial: 45-2027
RegNo: N116PJ
HRS: 9841.3
AFL: 7790
As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
Y2142000 ^S		PERFORM BAGGAGE COMPARTMENT HEATING SYSTEM - FUNCTIONAL TEST						Service	ATA:21
	MOS	13-Mar-26	96 (+14d/-14d)						
	HRS	9596.2	2400 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 21-40-00PROC. REF: AMM 21-40-00									PKG:20
Y2145000 ^S		ECS PLENUM ASSEMBLY CHECK VALVES - PERFORM VISUAL INSPECTION. VERIFY FREEDOM OF MOVEMENT OF BUTTERFLY ASSEMBLY.						Service	ATA:21
	MOS	13-Mar-26	48 (+14d/-14d)						
	HRS	9596.2	1200 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 21-20-09PROC. REF: AMM 21-20-09									PKG:14
Y2150058 ^S		PERFORM VISUAL INSPECTION OF THE AIR CONDITIONING SYSTEM COMPONENTS, INCLUDING COMPRESSOR MOTOR BELT FOR WEAR AND PROPER V-BELT TENSION, CONDENSER COILS FOR CLEANLINESS AND HOSES FOR CHAFING AND WEAR. IF OIL LEAKS ARE VISIBLE AND/OR REFRIGERANT DUMPED, CHECK COMPRESSOR OIL LEVEL (SOME LEAKAGE IS ALLOWABLE AROUND THE SHAFT.)						Service	ATA:21
	MOS	13-Mar-26	48 (+14d/-14d)						
	HRS	9596.2	1200 (+25/-25)						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:14
Y2150059 ^S		AIR CONDITIONING SYSTEM - PERFORM LOAD SHED ASSEMBLY CHECK						Service	ATA:21
	MOS	13-Mar-26	48 (+14d/-14d)						
	HRS	9596.2	1200 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 21-51-00PROC. REF: AMM 21-51-00									PKG:14
ATA 22 - AUTO FLIGHT									
221001		AUTOPILOT FLIGHT GUIDANCE CONTROLLER						Component	ATA:22
PN:7021170-901	MOS/MSC	06-Apr-11	O/C						
SN:97100248	HRS	4134.42							
	AFL	3382							
PROC. REF: AMM 22-10-01PROC. REF: AMM 22-10-01									

? - Insufficient Information
S - Suppressed Requirement
* - Estimated Due(New Requirement)
(EFF) - Effective C / W
(M) - Manual Due
U - User Task
Ex - Excluded Task

Status Report

Model: LEARJET 40XR
 Serial: 45-2027
 RegNo: N116PJ
 HRS: 9841.3
 AFL: 7790
 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 22 - AUTO FLIGHT									
221041	AUTOPILOT ROLL SERVO								Component ATA:22
PN:4006719-948	MOS/MSC	13-Dec-21	O/C						
SN:97019207	HRS	8647.8							
	AFL	6960							
PROC. REF: AMM 22-10-04PROC. REF: AMM 22-10-04									
221045	AILERON SERVO BRACKET								Component ATA:22
PN:4005842	MOS/MSC	10-May-05	O/C	TSN 0					
SN:04107574	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 22-10-05PROC. REF: AMM 22-10-05									
221051	AUTOPILOT PITCH SERVO								Component ATA:22
PN:4006719-908	MOS/MSC	10-May-05	O/C	TSN 0					
SN:04078769	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 22-10-02PROC. REF: AMM 22-10-02									
221055	PITCH SERVO BRACKET								Component ATA:22
PN:4005842	MOS/MSC	10-May-05	O/C	TSN 0					
SN:04067332	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 22-10-03PROC. REF: AMM 22-10-03									
221061	AUTOPILOT YAW SERVO								Component ATA:22
PN:7012919-904	MOS/MSC	10-May-05	O/C	TSN 0					
SN:01100509	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 22-10-06PROC. REF: AMM 22-10-06									
221065	SERVO, YAW BRACKET								Component ATA:22
PN:7012098-902	MOS/MSC	10-May-05	O/C	TSN 0					
SN:04080540	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 22-10-07PROC. REF: AMM 22-10-07									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-------	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 22 - AUTO FLIGHT

225001	YAW INTERFACE UNIT							Component	ATA:22
PN:4522108501-011	MOS/MSC	10-May-05	O/C	TSN 0					
SN:MRP306891-01	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 22-50-01PROC. REF: AMM 22-50-01									

A2210033	^S	** AUTOPILOT SYSTEM - PERFORM AUTOPILOT DISCONNECT TONE TEST. (AWL**)							Service ATA:22
	MOS	13-Mar-26	24 (+14d/-14d)					AIRWORTHINESS	
	HRS	9596.2	600 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 22-10-00PROC. REF: AMM 22-10-00									
									PKG:7

G2210030	^S	PITCH SERVO CABLES - PERFORM CABLE TENSION CHECK							Service ATA:22
	MOS	13-Mar-26	48 (+14d/-14d)						
	HRS	9596.2	1200 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 22-10-03PROC. REF: AMM 22-10-03									
									PKG:14

G2210031	^S	ROLL SERVO CABLES - PERFORM CABLE TENSION CHECK							Service ATA:22
	MOS	13-Mar-26	48 (+14d/-14d)						
	HRS	9596.2	1200 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 22-10-05PROC. REF: AMM 22-10-05									
									PKG:13

G2210032	^S	YAW SERVO CABLES - PERFORM CABLE TENSION CHECK							Service ATA:22
	MOS	13-Mar-26	48 (+14d/-14d)						
	HRS	9596.2	1200 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 22-10-07PROC. REF: AMM 22-10-07									
									PKG:14

ATA 23 - COMMUNICATIONS

230013	ANTENNA SPLITTER							Component	ATA:23
PN:DMH21-1	MOS/MSC	10-May-05	O/C	TSN 0					
SN:30072	HRS	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
	AFL	0		TSN 0					
PROC. REF: AMM 34-30-03PROC. REF: AMM 34-30-03									
231011	NO. 1 POWER AMPLIFIER/HF ANTENNA COUPLER							Component	ATA:23
PN:064-1017-01	MOS/MSC	08-Apr-13	O/C						
SN:16738	HRS	5470.47							
	AFL	4452							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
231021	NO. 1 INTEGRATED COMM/ATC UNIT							Component	ATA:23
PN:7510733-666	MOS/MSC	13-Jan-26	O/C						
SN:98113427	HRS	9594.9							
	AFL								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
231021A	RECERTIFY NO. 1 INTEGRATED COMM/ATC UNIT TRANSPONDER - FAR 91.413							Service	ATA:23
	MOS	13-Jan-26	24		13-Jan-28		485 d		
	HRS	9594.9							
	AFL								
PROC. REF: GENERIC NO REF, FAR SUBPART EPROC. REF: GENERIC NO REF, FAR SUBPART E									
231022	NO. 2 INTEGRATED COMM/ATC UNIT							Component	ATA:23
PN:7510733-666	MOS/MSC	13-Jan-26	O/C						
SN:05029146	HRS	9594.9							
	AFL								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
231022A	RECERTIFY NO. 2 INTEGRATED COMM/ATC UNIT TRANSPONDER - FAR 91.413							Service	ATA:23
	MOS	13-Jan-26	24		13-Jan-28		485 d		
	HRS	9594.9							
	AFL								
PROC. REF: GENERIC NO REF, FAR SUBPART EPROC. REF: GENERIC NO REF, FAR SUBPART E									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR
Serial: 45-2027
RegNo: N116PJ
HRS: 9841.3
AFL: 7790
As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
231023	NO.1 STRAP BOARD NAV							Component	ATA:23
PN:4523180820-2027-001	MOS/MSC	10-May-05	O/C	TSN 0					
SN:A00587725-01	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-11-03PROC. REF: AMM 23-11-03									
231024	NO.2 STRAP BOARD NAV							Component	ATA:23
PN:4523180820-2017-005	MOS/MSC	10-May-05	O/C	TSN 0					
SN:A00587764-1	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-11-03PROC. REF: AMM 23-11-03									
231029	HF RECEIVER/EXCITER							Component	ATA:23
PN:064-1015-01	MOS/MSC	01-Feb-15	O/C						
SN:32609	HRS	6678.12							
	AFL	5426							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
231033	UPPER VHF ANTENNA							Component	ATA:23
PN:DMC60-17-1	MOS/MSC	27-Oct-11	O/C						
SN:16307	HRS	4469.73							
	AFL	3671							
PROC. REF: AMM 23-11-02PROC. REF: AMM 23-11-02									
231034	LOWER VHF ANTENNA							Component	ATA:23
PN:DMC60-17-1	MOS/MSC	27-Oct-11	O/C						
SN:16308	HRS	4469.73							
	AFL	3671							
PROC. REF: AMM 23-11-02PROC. REF: AMM 23-11-02									
231035	NO.1 STRAP BOARD COMM							Component	ATA:23
PN:4523180820-2017-003	MOS/MSC	10-May-05	O/C	TSN 0					
SN:A00587707-01	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-11-03PROC. REF: AMM 23-11-03									

? - Insufficient Information
S - Suppressed Requirement
* - Estimated Due(New Requirement)
(EFF) - Effective C / W
(M) - Manual Due
U - User Task
Ex - Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
231036	NO.2 STRAP BOARD COMM							Component	ATA:23
PN:4523180820-2017-007	MOS/MSC	10-May-05	O/C	TSN 0					
SN:A00587782-01	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-11-03PROC. REF: AMM 23-11-03									
231045	NO. 1 HF CONTROL							Component	ATA:23
PN:064-1016-03	MOS/MSC	25-Jan-12	O/C						
SN:11177	HRS	4667.67							
	AFL	3815							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
231505 ^U	IRIDIUM SATCOM PHONE BASE UNIT CORDLESS							Component	ATA:23
PN:9L8810A-B	MOS/MSC	03-Apr-11	O/C						
SN:250211	HRS	4129.55							
	AFL	3376							
231510 ^U	IRIDIUM SATCOM TRANSCEIVER							Component	ATA:23
PN:500617-2	MOS/MSC	18-Jul-05	O/C	TSN 0					
SN:5231	HRS	18.9		TSN 0					
	AFL	15		TSN 0					
231510A ^U	GENERAL VISUAL INSPECTION MOUNTING AND RETAINING HARDWARE. CHECK FOR SECURITY OF ATTACHMENT AND OTHER DEFECTS							Service	ATA:23
PN:500617-2	MOS	16-Mar-26	48		16-Mar-30		1278 d		
SN:5231	HRS	9596.2	1200		10796.2		954.9		
	AFL	7624							
231515 ^U	IRIDIUM SATCOM ANTENNA							Component	ATA:23
PN:C1490-1	MOS/MSC	18-Jul-05	O/C	TSN 0					
SN:5033798	HRS	18.9		TSN 0					
	AFL	15		TSN 0					

?-Insufficient Information

S-Suppressed Requirement

*-Estimated Due(New Requirement)

(EFF)-Effective C / W

(M)-Manual Due

U-User Task

Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
231515A ^U		GENERAL VISUAL INSPECTION IRIDIUM SATCOM ANTENNA MOUNTAINING AND RETAINING HARDWARE. CHECK FOR SECURITY OF ATTACHMENT AND OTHER DEFECTS						Service	ATA:23
PN:CI490-1	MOS	16-Mar-26	48		16-Mar-30		1278 d		
SN:5033798	HRS	9596.2	1200		10796.2		954.9		
	AFL	7624							
233014		1-R CABIN STEREO SPEAKER						Component	ATA:23
PN:6623308507-001	MOS/MSC	18-Jul-05	O/C	TSN 0					
SN:040500488	HRS	18.9		TSN 0					
	AFL	15		TSN 0					
PROC. REF: AMM 23-30-01PROC. REF: AMM 23-30-01									
233015		2-R CABIN STEREO SPEAKER						Component	ATA:23
PN:6623308507-001	MOS/MSC	18-Jul-05	O/C	TSN 0					
SN:040500589	HRS	18.9		TSN 0					
	AFL	15		TSN 0					
PROC. REF: AMM 23-30-01PROC. REF: AMM 23-30-01									
233016		2-L CABIN STEREO SPEAKER						Component	ATA:23
PN:6623308507-001	MOS/MSC	18-Jul-05	O/C	TSN 0					
SN:040500490	HRS	18.9		TSN 0					
	AFL	15		TSN 0					
PROC. REF: AMM 23-30-01PROC. REF: AMM 23-30-01									
233017		1-L CABIN STEREO SPEAKER						Component	ATA:23
PN:6623308507-001	MOS/MSC	18-Jul-05	O/C	TSN 0					
SN:040500481	HRS	18.9		TSN 0					
	AFL	15		TSN 0					
PROC. REF: AMM 23-30-01PROC. REF: AMM 23-30-01									
233025		SUB WOOFER SPEAKER						Component	ATA:23
PN:EN-646-W	MOS/MSC	10-May-05	O/C	TSN 0					
SN:040500044	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-30-01PROC. REF: AMM 23-30-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
233043	PA AMPLIFIER							Component	ATA:23
PN:PA-7501-01-1	MOS/MSC	10-May-05	O/C	TSN 0					
SN:060400501	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-30-02PROC. REF: AMM 23-30-02									
235001	PILOT AUDIO CONTROL UNIT							Component	ATA:23
PN:7511001-937	MOS/MSC	03-Sep-14	O/C						
SN:05019873	HRS	6427.53							
	AFL	5233							
PROC. REF: AMM 23-50-01PROC. REF: AMM 23-50-01									
235002	COPILOT AUDIO CONTROL UNIT							Component	ATA:23
PN:4523558501-003	MOS/MSC	03-Sep-14	O/C						
SN:05064203	HRS	6427.53							
	AFL	5233							
PROC. REF: AMM 23-50-01PROC. REF: AMM 23-50-01									
237001	COCKPIT VOICE RECORDER							Component	ATA:23
PN:980-6020-011	MOS/MSC	10-May-05	O/C	TSN 0					
SN:CVR30-04088	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-70-01PROC. REF: AMM 23-70-01									
237002	CD CHANGER							Component	ATA:23
PN:MCD-102-RU-3	MOS/MSC	18-Jul-05	O/C	TSN 0					
SN:030500239	HRS	18.9		TSN 0					
	AFL	15		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
237005	CVR UNDERWATER LOCATOR BEACON							Component	ATA:23
PN:DK120	MOS/MSC	13-Mar-26	O/C	TSN 48					
SN:AT169093	HRS	9596.2		TSN 875					
	AFL	7624		TSN 618					
PROC. REF: AMM 25-61-01PROC. REF: AMM 25-61-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
237005A		CLEAN CVR UNDERWATER LOCATOR BEACON SWITCH, AND PERFORM OPERATIONAL CHECK AND TEST OF ULB BATTERY (AA2560000)						Service	ATA:23
PN:DK120	MOS	13-Mar-26	24 (+14d/-14d)	Adj -2d	11-Mar-28	25-Mar-28	543 d (+14)		
SN:AT169093	HRS	9596.2							
	AFL	7624							
PROC. REF: AMM 25-61-01PROC. REF: AMM 25-61-01									
237005B		REPLACE CVR UNDERWATER LOCATOR BEACON BATTERY (D2566001)						Service	ATA:23
PN:DK120	MOS/MSC	11-Mar-22	DUE		30-Jun-28 (M)		654 d	LIFE LIMIT	
SN:AT169093	HRS	8721.2							
	AFL	7006							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
237005C		RECERTIFY CVR UNDERWATER LOCATOR BEACON						Service	ATA:23
PN:DK120	MOS	13-Mar-26	216 (+14d/-14d)		13-Mar-44	27-Mar-44	6389 d (+14)		
SN:AT169093	HRS	9596.2							
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
237019		COCKPIT AREA MICROPHONE						Component	ATA:23
PN:980-6113-001	MOS/MSC	10-May-05	O/C	TSN 0					
SN:03374	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
237034		CVR PRE-AMPLIFIER						Component	ATA:23
PN:980-6118-001	MOS/MSC	10-May-05	O/C	TSN 0					
SN:CAMP-00554	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-70-03PROC. REF: AMM 23-70-03									
238001		NO. 1 RADIO MANAGEMENT UNIT						Component	ATA:23
PN:7013270-985	MOS/MSC	04-Dec-19	O/C						
SN:01130471	HRS	7762.1							
	AFL	6271							
PROC. REF: AMM 23-80-01PROC. REF: AMM 23-80-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
238002	NO. 2 RADIO MANAGEMENT UNIT							Component	ATA:23
PN:7013270-965	MOS/MSC	04-Dec-19	O/C						
SN:04124627	HRS	7762.1							
	AFL	6271							
PROC. REF: AMM 23-80-01PROC. REF: AMM 23-80-01									
238025	CLEARANCE DELIVERY UNIT							Component	ATA:23
PN:7513000-835	MOS/MSC	10-May-05	O/C	TSN 0					
SN:04112863	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-82-01PROC. REF: AMM 23-82-01									
A2300000 ^S	** COMMUNICATIONS SYSTEMS - PERFORM OPERATIONAL CHECK. (AWL**)							Service	ATA:23
	MOS	13-Mar-26	24 (+14d/-14d)					AIRWORTHINESS	
	HRS	9596.2	600 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 23-00-00PROC. REF: AMM 23-00-00									
NC23155001-SMM ^U	DETAILED VISUAL INSPECTION IRIDIUM SATCOM ANTENNA SKIN CUTOUT AND DOUBLER							Service	ATA:23
	MOS	10-May-05							
	HRS	0							
	AFL	0	T:10000		10000		2210		
NC23155001-SMM-A ^U	FUNCTIONAL TEST IRIDIUM SATELITE COMMUNICATIONS PHONE SYSTEM							Service	ATA:23
	MOS	13-Mar-26	24		13-Mar-28		545 d		
	HRS	9596.2	600		10196.2		354.9		
	AFL	7624							
NC23155001-SMM-B ^U	PERFORM A GENERAL VISUAL INSPECTION OF THE TRANSCEIVER MOUNTINGAND RETAINING HARDWARE. CHECK FOR SECURITY OF ATTACHMENT ANDOTHER DEFECTS							Service	ATA:23
	MOS	22-Apr-24	48		22-Apr-28		585 d		
	HRS	9368.9	1200		10568.9		727.6		
	AFL	7476							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
NC23155001-SMM-C ^U		PERFORM A GENERAL VISUAL INSPECTION OF THE COCKPIT PHONEMOUNTING AND RETAINING HARDWARE. CHECK FOR SECURITY OFATTACHMENT AND OTHER DEFECTS.						Service	ATA:23
	MOS	22-Apr-24	48		22-Apr-28		585 d		
	HRS	9368.9	1200		10568.9		727.6		
	AFL	7476							
NC23155001-SMM-D ^U		PERFORM A GENERAL VISUAL INSPECTION OF THE CABIN HANDSET ANDBASE UNIT, AND RETAINING HARDWARE. CHECK FOR SECURITY OFATTACHMENT AND OTHER DEFECTS.						Service	ATA:23
	MOS	22-Apr-24	48		22-Apr-28		585 d		
	HRS	9368.9	1200		10568.9		727.6		
	AFL	7476							
NC23155001-SMM-E ^U		PERFORM A GENERAL VISUAL INSPECTION OF THE ANTENNA ANDRETAINING HARDWARE. CHECK FOR SECURITY OF ATTACHMENT AND OTHERDEFECTS.						Service	ATA:23
	MOS	22-Apr-24	48		22-Apr-28		585 d		
	HRS	9368.9	1200		10568.9		727.6		
	AFL	7476							
NC23155001-SMM-F ^U		GENERAL VISUAL INSPECTION IRIDIUM SATELITE COMMUNICATIONS PHONE SYSTEM CONNECTORS AND WIRING FOR CHAFING, DAMAGE, SECURITY OF ATTACHMENT, AND OTHER DEFECTS						Service	ATA:23
	MOS	22-Apr-24	48		22-Apr-28		585 d		
	HRS	9368.9	1200		10568.9		727.6		
	AFL	7476							
V2312003 ^S		HF ANTENNA- PERFORM VISUAL INSPECTION. CHECK FOR PROPER TENSION ON HF ANTENNA WIRE						Service	ATA:23
	MOS	13-Mar-26	48 (+14d/-14d)						
	HRS	9596.2	1200 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 23-12-04PROC. REF: AMM 23-12-04									PKG:14

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 23 - COMMUNICATIONS										
Y2360020 ^S		AIRCRAFT STATIC DISCHARGERS - PERFORM FUNCTIONAL TEST							Service	ATA:23
	MOS	13-Mar-26	96 (+14d/-14d)							
	HRS	9596.2	2400 (+25/-25)							
	AFL	7624								
PROC. REF: AMM 23-60-00PROC. REF: AMM 23-60-00										
PKG:20										
Y2360023 ^S		AIRCRAFT STATIC DISCHARGERS - PERFORM FUNCTIONAL TEST							Service	ATA:23
	MOS	13-Mar-26	96 (+14d/-14d)							
	HRS	9596.2	2400 (+25/-25)							
	AFL	7624								
PROC. REF: AMM 23-60-00PROC. REF: AMM 23-60-00										
PKG:22										
ATA 24 - ELECTRICAL POWER										
240101		PILOT CIRCUIT BREAKER PANEL							Component	ATA:24
PN:4531180817-2027-001	MOS/MSC	10-May-05	O/C	TSN 0						
SN:A00587710-01	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 24-60-01PROC. REF: AMM 24-60-01										
240102		COPILOT CIRCUIT BREAKER PANEL							Component	ATA:24
PN:4531180818-2027-001	MOS/MSC	10-May-05	O/C	TSN 0						
SN:A0058776-01	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 24-60-01PROC. REF: AMM 24-60-01										
242001		NO. 1 AC 5KVA ALTERNATOR							Component	ATA:24
PN:90278-2	MOS/MSC	27-May-24	O/C	TSO 0						
SN:1185	HRS	9381.4	TSO 0							
	AFL	7483	TSO 0							
PROC. REF: AMM 24-20-01PROC. REF: AMM 24-20-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 24 - ELECTRICAL POWER									
242001A	NO. 1 AC 5KVA ALTERNATOR ** REPLACE BEARINGS (IRN F2420000) (AWL**)								Service ATA:24
PN:90278-2	MOS	27-May-24						LIFE LIMIT	
SN:1185	HRS	9381.4	1200 (+25/-25)		10581.4	10606.4	740.1 (+25)		
	AFL	7483							
PROC. REF: AMM 24-20-01PROC. REF: AMM 24-20-01									
242002	NO. 2 AC 5KVA ALTERNATOR								Component ATA:24
PN:90278-2	MOS/MSC	06-May-24	O/C						
SN:1293	HRS	9381.4							
	AFL	7483							
PROC. REF: AMM 24-20-01PROC. REF: AMM 24-20-01									
242002A	NO. 2 AC 5KVA ALTERNATOR ** REPLACE BEARINGS (IRN F2420000) (AWL**)								Service ATA:24
PN:90278-2	MOS	06-May-24		TAC 13				LIFE LIMIT	
SN:1293	HRS	9381.4	1200 (+25/-25)	TAC 310.1	10271.3	10296.3	430 (+25)		
	AFL	7483		TAC 231					
PROC. REF: AMM 24-20-01PROC. REF: AMM 24-20-01									
242050	BREAKER, REMOTE CIRCUIT								Component ATA:24
PN:SM600BA25N1	MOS/MSC	18-Jul-05	O/C	TSN 0					
SN:91298	HRS	18.9		TSN 0					
	AFL	15		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
242054	AFT BREAKER, OPTIONAL CIRCUIT								Component ATA:24
PN:4533488524-017	MOS/MSC	10-May-05	O/C	TSN 0					
SN:A00588396	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
242055	OPTIONAL BREAKER PANEL CIRCUIT								Component ATA:24
PN:4524088502-029	MOS/MSC	18-Jul-05	O/C	TSN 0					
SN:A00612021	HRS	18.9		TSN 0					
	AFL	15		TSN 0					
PROC. REF: AMM 24-60-01PROC. REF: AMM 24-60-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 24 - ELECTRICAL POWER									
242081	1200 VA, 115VAC , 60HZ INVERTER								Component ATA:24
PN:2D1200-1A-1011	MOS/MSC	17-Aug-26	O/C						
SN:GB001506	HRS	9818.6							
	AFL	7772							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
243001	NO. 1 STARTER/GENERATOR (IRN P2430003)								Component ATA:24
PN:23280-067	MOS	09-Jan-23		TSO 0				OVERHAUL	
SN:P1263/CA	HRS	9039.2	1200 (+25/-25)	TSO 0, Adj -14.3	10224.9	10249.9	383.6 (+25)		
	AFL	7232		TSO 0					
PROC. REF: AMM 24-30-01PROC. REF: AMM 24-30-01									
243001A	REPLACE NO. 1 STARTER/GENERATOR (IRN P2430003) BEARING (IRN P2430007)								Service ATA:24
PN:23280-067	MOS/MSC	09-Jan-23	N/A						
SN:P1263/CA	HRS	9039.2							
	AFL	7232							
PROC. REF: AMM 24-30-01PROC. REF: AMM 24-30-01									
243002	NO. 2 STARTER/GENERATOR (IRN P2430003)								Component ATA:24
PN:23280-067	MOS	10-May-23		TSO 0				OVERHAUL	
SN:P1391/CA	HRS	9071.3	1200 (+25/-25)	TSO 0, Adj -2.03	10269.27	10294.27	428 (+25)		
	AFL	7252		TSO 0					
PROC. REF: AMM 24-30-01PROC. REF: AMM 24-30-01									
243002A	REPLACE NO. 2 STARTER/GENERATOR (IRN P2430003) BEARING (IRN P2430007)								Service ATA:24
PN:23280-067	MOS/MSC	10-May-23	N/A						
SN:P1391/CA	HRS	9071.3							
	AFL	7252							
PROC. REF: AMM 24-30-01PROC. REF: AMM 24-30-01									
243037	EMERGENCY BATTERY (P/N RG-443), (IF INSTALLED) -REPLACE (IRN AB2431063).								Component ATA:24
PN:RG-443	MOS	13-Mar-26	60 (+14d/-14d)	TSN 0	13-Mar-31	27-Mar-31	1640 d (+14)	REPLACE	
SN:41334010	HRS	9596.2	5000 (+25/-25)	TSN 0	14596.2	14621.2	4754.9 (+25)		
	AFL	7624		TSN 0					
PROC. REF: AMM 24-32-01, CMM 24-30-67PROC. REF: AMM 24-32-01, CMM 24-30-67									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 24 - ELECTRICAL POWER										
243037A		CAPACITY CHECK EMERGENCY BATTERY (IRN O2431002, IRN AB2431062)							Service	ATA:24
PN:RG-443	MOS	13-Mar-26	12 (+14d/-14d)		13-Mar-27	27-Mar-27	179 d (+14)			
SN:41334010	HRS	9596.2	1000 (+25/-25)		10596.2	10621.2	754.9 (+25)			
	AFL	7624								
PROC. REF: GENERIC NO REF, CMM 24-30-67PROC. REF: GENERIC NO REF, CMM 24-30-67										
243043		NO. 1 MAIN AIRCRAFT BATTERY							Component	ATA:24
PN:RG-380E/40L	MOS	13-Mar-26	48 (+1m/-1m)	TSN 0, Adj 3d	16-Mar-30	16-Apr-30	1278 d (+31)			
SN:41390824	HRS	9596.2		TSN 0						
	AFL	7624		TSN 0						
PROC. REF: AMM 24-31-01, AMM 24-31-06, CMM 24-30-71PROC. REF: AMM 24-31-01, AMM 24-31-06, CMM 24-30-71										
243043B		CAPACITY CHECK NO. 1 MAIN AIRCRAFT BATTERY (IRN O1222000 NI-CAD/IRN T1222004 38 AMP HOUR LEAD-ACID/T1222007 28 AMP HOUR LEAD ACID)							Service	ATA:24
PN:RG-380E/40L	MOS	13-Mar-26	6 (+1m/-1m)		13-Sep-26	13-Oct-26	TOL (+28 d)			
SN:41390824	HRS	9596.2								
	AFL	7624								
PROC. REF: AMM 12-22-00, CMM 24-30-71PROC. REF: AMM 12-22-00, CMM 24-30-71										
243044		NO. 2 MAIN AIRCRAFT BATTERY							Component	ATA:24
PN:RG-380E/44L	MOS	06-Apr-26	48 (+1m/-1m)	TSN 0	06-Apr-30	06-May-30	1299 d (+30)			
SN:41390824	HRS	9633.1		TSN 0						
	AFL	7650		TSN 0						
PROC. REF: AMM 24-31-01, AMM 24-31-06, CMM 24-30-71PROC. REF: AMM 24-31-01, AMM 24-31-06, CMM 24-30-71										
243044B		CAPACITY CHECK NO. 2 MAIN AIRCRAFT BATTERY (IRN O1222000 NI-CAD/IRN T1222004 38 AMP HOUR LEAD-ACID/T1222007 28 AMP HOUR LEAD ACID)							Service	ATA:24
PN:RG-380E/44L	MOS	06-Apr-26	6 (+1m/-1m)		06-Oct-26	06-Nov-26	21 d (+31)			
SN:41390824	HRS	9633.1								
	AFL	7650								
PROC. REF: AMM 12-22-00, CMM 24-30-71PROC. REF: AMM 12-22-00, CMM 24-30-71										
246001		LH FWD PWR DISTRIBUTION PANEL							Component	ATA:24
PN:650GC02Y03	MOS/MSC	10-May-05	O/C	TSN 0						
SN:364	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 24-60-02PROC. REF: AMM 24-60-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 24 - ELECTRICAL POWER									
246002	RH FWD PWR DISTRIBUTION PANEL							Component	ATA:24
PN:655GC02Y03	MOS/MSC	10-May-05	O/C	TSN 0					
SN:358	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 24-60-02PROC. REF: AMM 24-60-02									
246003	LH AFT PWR DISTRIBUTION PANEL							Component	ATA:24
PN:660GC02Y07	MOS/MSC	03-Jun-13	O/C						
SN:211	HRS	5513.02							
	AFL	4486							
PROC. REF: AMM 24-60-03PROC. REF: AMM 24-60-03									
246004	RIGHT AFT PWR DISTRIBUTION PANEL							Component	ATA:24
PN:700GC02Y07	MOS/MSC	14-Nov-09	O/C						
SN:142	HRS	3056.47							
	AFL	2526							
PROC. REF: AMM 24-60-03PROC. REF: AMM 24-60-03									
5-19-00-Y2431005	PERFORM BATTERY CONNECTOR TOLERANCE CHECK.							Service	ATA:24
	MOS	13-Mar-26							
	HRS	9596.2	300 (+25/-25)		9896.2	9921.2	54.9 (+25)		
	AFL	7624							
PROC. REF: AMM 24-31-00PROC. REF: AMM 24-31-00									
AC2460002 ^S	REMOVE ATTACHING PARTS SECURING CIRCUIT BREAKER PANEL TO STRUCTURE. CHECK FOR LOOSE CIRCUIT BREAKER TERMINALS, LOOSE WIRE TERMINALS, CORRODED TERMINALS OR BUSS BARS, AND EVIDENCE OF WIRE INSULATION DAMAGE.							Service	ATA:24
	MOS	13-Mar-26	96 (+14d/-14d)						
	HRS	9596.2	2400 (+25/-25)						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
B2450002 ^S	** ELECTRICAL SYSTEM CONTROL - PERFORM OPERATIONAL CHECK (AWL**)							Service	ATA:24
	MOS	13-Mar-26	48 (+14d/-14d)					AIRWORTHINESS	
	HRS	9596.2	1200 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 24-00-00PROC. REF: AMM 24-00-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 24 - ELECTRICAL POWER									
H2450001	^S	** AUXILIARY POWER SUPPLIES - PERFORM FUNCTIONAL TEST (AWL**)						Service	ATA:24
	MOS	13-Mar-26	24 (+14d/-14d)					AIRWORTHINESS	
	HRS	9596.2	600 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 24-00-00PROC. REF: AMM 24-00-00									PKG:7
H2450023	^S	** EMER BATT LOW AND GEN AMPS HIGH INDICATION - PERFORM OPERATIONAL CHECK (AWL**)						Service	ATA:24
	MOS	13-Mar-26	24 (+14d/-14d)					AIRWORTHINESS	
	HRS	9596.2	600 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 24-00-00PROC. REF: AMM 24-00-00									PKG:7
Q2460001	^S	** POWER DISTRIBUTION SYSTEM - PERFORM SQUAT SWITCH CHECK (AWL**)						Service	ATA:24
	MOS	13-Mar-26	48 (+14d/-14d)					AIRWORTHINESS	
	HRS	9596.2	1200 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 24-60-00PROC. REF: AMM 24-60-00									PKG:17
R2431003	^S	** BATTERY WARNING SYSTEM - PERFORM FUNCTIONAL TEST. (EFFECTIVE ON AIRCRAFT WITH NI-CAD BATTERIES INSTALLED.) (AWL**)						Service	ATA:24
	MOS	13-Mar-26	96 (+14d/-14d)					AIRWORTHINESS	
	HRS	9596.2	2400 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 24-31-00PROC. REF: AMM 24-31-00									PKG:19
W2450000	^S	** GENERATOR FAIL INDICATION - PERFORM OPERATIONALCHECK. (AWL**)						Service	ATA:24
	MOS	13-Mar-26	24 (+14d/-14d)					AIRWORTHINESS	
	HRS	9596.2	600 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 24-00-00PROC. REF: AMM 24-00-00									PKG:7

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR
Serial: 45-2027
RegNo: N116PJ
HRS: 9841.3
AFL: 7790
As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 24 - ELECTRICAL POWER										
Y2400001 ^S		SWITCH AND CIRCUIT BREAKER PANELS - PERFORM VISUAL INSPECTION							Service	ATA:24
	MOS	13-Mar-26	48 (+14d/-14d)							
	HRS	9596.2	1200 (+25/-25)							
	AFL	7624								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
PKG:13										
Y2400002 ^S		ELECTRICAL WIRING - PERFORM VISUAL INSPECTION FOR ROUTING, SECURITY, CLEARANCES, CHAFING, AND ELECTRICAL COMPONENTS FOR SECURITY AND GENERAL CONDITION.							Service	ATA:24
	MOS	13-Mar-26	24 (+14d/-14d)							
	HRS	9596.2	600 (+25/-25)							
	AFL	7624								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
PKG:7										
Y2400025 ^S		ELECTRICAL WIRING - PERFORM VISUAL INSPECTION FOR ROUTING, SECURITY, CLEARANCES, CHAFING, AND ELECTRICAL COMPONENTS FOR SECURITY AND GENERAL CONDITION							Service	ATA:24
	MOS	13-Mar-26	24 (+14d/-14d)							
	HRS	9596.2	600 (+25/-25)							
	AFL	7624								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
PKG:8										
Y2430005 ^S		STARTER/GENERATOR - PERFORM GROUNDING LUG BONDING CHECK							Service	ATA:24
	MOS	13-Mar-26	24 (+14d/-14d)							
	HRS	9596.2	600 (+25/-25)							
	AFL	7624								
PROC. REF: AMM 24-30-01PROC. REF: AMM 24-30-01										
PKG:9										
Y2430006 ^S		STARTER/GENERATOR - PERFORM VISUAL INSPECTION OF GROUNDING LUGS.							Service	ATA:24
	MOS	13-Mar-26	24 (+14d/-14d)							
	HRS	9596.2	600 (+25/-25)							
	AFL	7624								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
PKG:9										

? - Insufficient Information
S - Suppressed Requirement
* - Estimated Due(New Requirement)
(EFF) - Effective C / W
(M) - Manual Due
U - User Task
Ex - Excluded Task

Status Report

Model: LEARJET 40XR

Serial: 45-2027

RegNo: N116PJ

HRS: 9841.3

AFL: 7790

As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 24 - ELECTRICAL POWER									
Y2431000	^S	BATTERY, GENERATOR, AND BUS-TIE CABLES - PERFORM VISUAL INSPECTION.						Service	ATA:24
	MOS	13-Mar-26	96 (+14d/-14d)						
	HRS	9596.2	2400 (+25/-25)						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
PKG:20									
Y2431001	^S	EMERGENCY BATTERY CABLES - PERFORM VISUAL INSPECTION.						Service	ATA:24
	MOS	13-Mar-26	24 (+14d/-14d)						
	HRS	9596.2	600 (+25/-25)						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
PKG:7									
Y2460000	^S	DC BUS ISOLATION - PERFORM OPERATIONAL CHECK						Service	ATA:24
	MOS	13-Mar-26	48 (+14d/-14d)						
	HRS	9596.2	1200 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 24-60-00PROC. REF: AMM 24-60-00									
PKG:13									
ATA 25 - EQUIPMENT/FURNISHINGS									
251001		PILOT CREW SEAT						Component	ATA:25
PN:4525103038-007	MOS/MSC	10-May-05	O/C	TSN 0					
SN:654	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 25-10-50PROC. REF: AMM 25-10-50									
251002		COPILOT CREW SEAT						Component	ATA:25
PN:4525103038-008	MOS/MSC	10-May-05	O/C	TSN 0					
SN:635	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 25-10-50PROC. REF: AMM 25-10-50									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
256061	PILOT LIFE VEST							Component	ATA:25
PN:63600-101	MOS/MSC	13-Mar-26	O/C	TSN 72					
SN:L4686058	HRS	9596.2		TSN 1699.6					
	AFL	7624		TSN 1253					
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01									
256061A	INSPECT PILOT LIFE VEST (E2561002)							Service	ATA:25
PN:63600-101	MOS	13-Mar-26	60		13-Mar-31		1640 d		
SN:L4686058	HRS	9596.2							
	AFL	7624							
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01									
256062	COPILOT LIFE VEST							Component	ATA:25
PN:63600-101	MOS/MSC	16-Mar-26	O/C	TSN 72					
SN:L4686058	HRS	9596.2		TSN 1699.6					
	AFL	7624		TSN 1253					
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01									
256062A	INSPECT COPILOT LIFE VEST (E2561002)							Service	ATA:25
PN:63600-101	MOS	16-Mar-26	60		16-Mar-31		1643 d		
SN:L4686058	HRS	9596.2							
	AFL	7624							
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01									
256063	NO. 1 LIFE VEST							Component	ATA:25
PN:63600-101	MOS/MSC	16-Mar-26	O/C	TSN 72					
SN:L4686059	HRS	9596.2		TSN 1699.6					
	AFL	7624		TSN 1253					
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01									
256063A	INSPECT NO. 1 LIFE VEST (E2561002)							Service	ATA:25
PN:63600-101	MOS	16-Mar-26	60		16-Mar-31		1643 d		
SN:L4686059	HRS	9596.2							
	AFL	7624							
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
256064	NO. 2 LIFE VEST							Component	ATA:25
PN:636300-101	MOS/MSC	13-Mar-26	O/C	TSN 72					
SN:L4686056	HRS	9596.2		TSN 1699.6					
	AFL	7624		TSN 1253					
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01									
256064A	INSPECT NO. 2 LIFE VEST (E2561002)							Service	ATA:25
PN:636300-101	MOS	13-Mar-26	60		13-Mar-31		1640 d		
SN:L4686056	HRS	9596.2							
	AFL	7624							
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01									
256065	NO. 3 LIFE VEST							Component	ATA:25
PN:63600-101	MOS/MSC	13-Mar-26	O/C	TSN 72					
SN:L4586052	HRS	9596.2		TSN 1699.6					
	AFL	7624		TSN 1253					
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01									
256065A	INSPECT NO. 3 LIFE VEST (E2561002)							Service	ATA:25
PN:63600-101	MOS	13-Mar-26	60		13-Mar-31		1640 d		
SN:L4586052	HRS	9596.2							
	AFL	7624							
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01									
256066	NO. 4 LIFE VEST							Component	ATA:25
PN:63600-101	MOS/MSC	13-Mar-26	O/C	TSN 72					
SN:L4686051	HRS	9596.2		TSN 1699.6					
	AFL	7624		TSN 1253					
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01									
256066A	INSPECT NO. 4 LIFE VEST (E2561002)							Service	ATA:25
PN:63600-101	MOS	13-Mar-26	60		13-Mar-31		1640 d		
SN:L4686051	HRS	9596.2							
	AFL	7624							
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR
Serial: 45-2027
RegNo: N116PJ
HRS: 9841.3
AFL: 7790
As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
256067	NO. 5 LIFE VEST							Component	ATA:25
PN:63600-105	MOS/MSC	13-Mar-26	O/C	TSO 0					
SN:L2741193	HRS	9596.2		TSO 0					
	AFL	7624		TSO 0					
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01									
256067A	INSPECT NO. 5 LIFE VEST (E2561002)							Service	ATA:25
PN:63600-105	MOS	13-Mar-26	60		13-Mar-31		1640 d		
SN:L2741193	HRS	9596.2							
	AFL	7624							
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01									
256068	NO. 6 LIFE VEST							Component	ATA:25
PN:63600-101	MOS/MSC	13-Mar-26	O/C	TSN 72					
SN:L4686053	HRS	9596.2		TSN 1699.6					
	AFL	7624		TSN 1253					
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01									
256068A	INSPECT NO. 6 LIFE VEST (E2561002)							Service	ATA:25
PN:63600-101	MOS	13-Mar-26	60		13-Mar-31		1640 d		
SN:L4686053	HRS	9596.2							
	AFL	7624							
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01									
256071	LAVATORY LIFE VEST							Component	ATA:25
PN:63600-101	MOS/MSC	03-Mar-20	O/C	TSN 0	03-Mar-30 (M)		1265 d		
SN:L4686050	HRS	7896.6		TSN 0					
	AFL	6371		TSN 0					
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01									
256071A	INSPECT LAVATORY LIFE VEST (E2561002)							Service	ATA:25
PN:63600-101	MOS	16-Mar-26	60 (+14d/-14d)		16-Mar-31	30-Mar-31	1643 d (+14)		
SN:L4686050	HRS	9596.2							
	AFL	7624							
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01									

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C/W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
256076	FIRST AID KIT							Component	ATA:25
PN:PN	MOS/MSC	13-Oct-17	O/C	TSN 0					
SN:UNKNOWN	HRS	7059.3		TSN 0					
	AFL	5738		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
256076A	VISUAL INSPECTION FIRST AID KIT PER MANUFACTURERS INSTRUCTIONS							Service	ATA:25
PN:PN	MOS	13-Mar-26	12 (+14d/-14d)		13-Mar-27	27-Mar-27	179 d (+14)		
SN:UNKNOWN	HRS	9596.2							
	AFL	7624							
PROC. REF: GENERIC CUSTOMPROC. REF: GENERIC CUSTOM									
256109	EMERGENCY LOCATOR TRANSMITTER BEACON							Component	ATA:25
PN:453-5000-366	MOS/MSC	16-Mar-26	O/C						
SN:10213	HRS	9596.2							
	AFL	7624							
PROC. REF: AMM 25-62-01PROC. REF: AMM 25-62-01									
256109A	FUNCTIONAL TEST EMERGENCY LOCATOR TRANSMITTER BEACON SYSTEM							Service	ATA:25
PN:453-5000-366	MOS	16-Mar-26	12 (+14d/-14d)		16-Mar-27	30-Mar-27	182 d (+14)		
SN:10213	HRS	9596.2							
	AFL	7624							
PROC. REF: AMM 25-62-00, FAR FAR 91.207PROC. REF: AMM 25-62-00, FAR FAR 91.207									
256109B	INSPECT EMERGENCY LOCATOR TRANSMITTER (ELT) BATTERY							Service	ATA:25
PN:552-0133	MOS	13-Mar-26	12 (+14d/-14d)		13-Mar-27	27-Mar-27	179 d (+14)		
SN:1005120-024	HRS	9596.2							
	AFL	7624							
PROC. REF: AMM 25-62-00PROC. REF: AMM 25-62-00									
256109C	REPLACE EMERGENCY LOCATOR TRANSMITTER (ELT) BATTERY							Service	ATA:25
PN:552-0133	MOS/MSC	13-Mar-26	DUE		28-Feb-29 (M)		897 d		
SN:1005120-024	HRS	9596.2							
	AFL	7624							
Expiry Date: : 28-Feb-29									
PROC. REF: AMM 25-62-01, FAR FAR 91.207PROC. REF: AMM 25-62-01, FAR FAR 91.207									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
256109D	REPLACE EMERGENCY LOCATOR TRANSMITTER BEACON REMOTE SWITCH BATTERY (IF INSTALLED)							Service	ATA:25
PN:453-5000-366	MOS/MSC	16-Mar-26	A/R						
SN:10213	HRS	9596.2							
	AFL	7624							
PROC. REF: GENERIC NO REF, FAR FAR 91.207PROC. REF: GENERIC NO REF, FAR FAR 91.207									
256111	EMERGENCY LOCATOR TRANSMITTER (ELT) BATTERY							Component	ATA:25
PN:552-0133	MOS/MSC	13-Mar-26	O/C	TSN 0					
SN:1005120-024	HRS	9596.2		TSN 0					
	AFL	7624		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
256115	ELT ANTENNA							Component	ATA:25
PN:110-337	MOS/MSC	10-May-05	O/C	TSN 0					
SN:4030477	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 25-62-03PROC. REF: AMM 25-62-03									
258010	AIRSHOW FLT DECK CONTROLLER							Component	ATA:25
PN:922000-2	MOS/MSC	04-Jan-15	O/C						
SN:G02041804	HRS	6640							
	AFL	5400							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
5-19-01-N2561004	DORNE AND MARGOLIN ELT REMOTE CONTROL BATTERY P/N U264-1 (IRN N2561004)							Service	ATA:25
	MOS/MSC	10-May-05	N/A						
	HRS	0							
	AFL	0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
T2550000 ^S	AVIONICS EQUIPMENT AND WIRING LOCATED IN FORWARD RH AVIONICS CABINET - PERFORM GENERAL VISUAL INSPECTION.							Service	ATA:25
	MOS	13-Mar-26							
	HRS	9596.2	4800 (+25/-25)						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
									PKG:25

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 25 - EQUIPMENT/FURNISHINGS

Y2510000 ^S	GLARESHIELD, HEADLINER, AND TRIM STRIPS - PERFORM VISUAL INSPECTION			Service	ATA:25
MOS	13-Mar-26	12	(+14d/-14d)		
HRS	9596.2	300	(+25/-25)		
AFL	7624				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF					PKG:1

Y2510001	^S	CREW SEATS AND SEAT BELTS - PERFORM VISUAL INSPECTION						Service	ATA:25
	MOS	13-Mar-26	12	(+14d/-14d)					
	HRS	9596.2	300	(+25/-25)					
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:1

Y2520000	^S	CABIN - PERFORM VISUAL INSPECTION OF THE FOLLOWING:A. CABIN SEATS AND SEAT BELTS. ENSURE THAT THE SEATS FUNCTION CORRECTLY AND LOCK IN PLACE.B. STOWAGE CABINETSC. HEADLINERD. SIDE PANELSE. RUG						Service	ATA:25
	MOS	13-Mar-26	12	(+14d/-14d)					
	HRS	9596.2	300	(+25/-25)					
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:1

Y2540000	^S	PERFORM ALL LAVATORY PAPER AND LINEN WASTE RECEPTACLE ACCESS DOORS AND DISPOSAL DOORS FOR PROPER OPERATION, FIT, SEALING, LATCHING, AND LEGIBILITY OF PLACARD.						Service	ATA:25	
	MOS	13-Mar-26	24	(+14d/-14d)						
	HRS	9596.2	600	(+25/-25)						
	AFL	7624								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										PKG:7

ATA 26 - FIRE PROTECTION

261057	NO. 1 FIRE DETECT CONTROL UNIT			Component	ATA:26
PN:877-01032	MOS/MSC	19-Apr-11	O/C		
SN:0403-208	HRS	4171.45			
	AFL	3411			
PROC. REF: AMM 26-11-01PROC. REF: AMM 26-11-01					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR
 Serial: 45-2027
 RegNo: N116PJ
 HRS: 9841.3
 AFL: 7790
 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 26 - FIRE PROTECTION									
261058	NO. 2 FIRE DETECT CONTROL UNIT							Component	ATA:26
PN:35009-39	MOS/MSC	04-Mar-08	O/C						
SN:1763	HRS	1982.37							
	AFL	1615							
PROC. REF: AMM 26-11-01PROC. REF: AMM 26-11-01									
261521	LH LEAK DETECTION UNIT							Component	ATA:26
PN:6626100000-003	MOS/MSC	10-May-05	O/C	TSN 0					
SN:1029	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 26-12-01PROC. REF: AMM 26-12-01									
261522	RH LEAK DETECTION UNIT							Component	ATA:26
PN:6626100000-003	MOS/MSC	10-May-05	O/C	TSN 0					
SN:1035	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 26-12-01PROC. REF: AMM 26-12-01									
261570	ANTI-ICE LEAK DETECTION UNIT							Component	ATA:26
PN:6626100000-003	MOS/MSC	19-Apr-11	O/C						
SN:1706	HRS	4171.45							
	AFL	3411							
PROC. REF: AMM 26-12-01PROC. REF: AMM 26-12-01									
262001	NO. 1/LEFT/LOWER FIRE EXTINGUISHER BOTTLE							Component	ATA:26
PN:33100021-1	MOS/MSC	16-Oct-24	O/C	TSO 0					
SN:51536B1	HRS	9492.6		TSO 0					
	AFL	7560		TSO 0					
PROC. REF: AMM 26-21-01PROC. REF: AMM 26-21-01									
262001A	NO. 1/LEFT/LOWER FIRE EXTINGUISHER BOTTLE - HYDROSTATIC TEST (Q2620006)							Service	ATA:26
PN:33100021-1	MOS	16-Oct-24	60 (+14d/-14d)	16-Oct-29	30-Oct-29	1127 d (+14)			
SN:51536B1	HRS	9492.6							
	AFL	7560							
PROC. REF: AMM 26-21-01PROC. REF: AMM 26-21-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 26 - FIRE PROTECTION									
262002	NO. 2/RIGHT/UPPER FIRE EXTINGUISHER BOTTLE							Component	ATA:26
PN:33100021-1	MOS/MSC	16-Oct-24	O/C	TSO 0					
SN:50847B1	HRS	9492.6		TSO 0					
	AFL	7560		TSO 0					
PROC. REF: AMM 26-21-01PROC. REF: AMM 26-21-01									
262002A	NO. 2/RIGHT/UPPER FIRE EXTINGUISHER BOTTLE - HYDROSTATIC TEST (Q2620006)							Service	ATA:26
PN:33100021-1	MOS	16-Oct-24	60 (+14d/-14d)		16-Oct-29	30-Oct-29	1127 d (+14)		
SN:50847B1	HRS	9492.6							
	AFL	7560							
PROC. REF: AMM 26-21-01PROC. REF: AMM 26-21-01									
262013	NO. 1/LEFT/LOWER FIRE EXTINGUISHER, LEFT SQUIB							Component	ATA:26
PN:30903856	MOS	16-Oct-24	180 (+14d/-14d)	TSN 0	16-Oct-39	30-Oct-39	4779 d (+14)	LIFE LIMIT	
SN:03212	HRS	9492.6		TSN 0					
	AFL	7560		TSN 0					
PROC. REF: AMM 26-21-02PROC. REF: AMM 26-21-02									
262013A	NO. 1/LEFT/LOWER FIRE EXTINGUISHER, LEFT SQUIB SERVICE LIFE LIMIT							Service	ATA:26
PN:30903856	MOS	16-Oct-24	120 (+14d/-14d)		16-Oct-34	30-Oct-34	2953 d (+14)	SERVICE LIFE LIMIT	
SN:03212	HRS	9492.6							
	AFL	7560							
PROC. REF: AMM 26-21-02PROC. REF: AMM 26-21-02									
262014	NO. 1/LEFT/LOWER FIRE EXTINGUISHER, RIGHT SQUIB							Component	ATA:26
PN:30903859	MOS	16-Oct-24	180 (+14d/-14d)	TSN 0	16-Oct-39	30-Oct-39	4779 d (+14)		
SN:02315	HRS	9492.6		TSN 0					
	AFL	7560		TSN 0					
PROC. REF: AMM 26-21-02PROC. REF: AMM 26-21-02									
262014A	NO. 1/LEFT/LOWER FIRE EXTINGUISHER, RIGHT SQUIB SERVICE LIFE LIMIT							Service	ATA:26
PN:30903859	MOS	16-Oct-24	120 (+14d/-14d)		16-Oct-34	30-Oct-34	2953 d (+14)	SERVICE LIFE LIMIT	
SN:02315	HRS	9492.6							
	AFL	7560							
PROC. REF: AMM 26-21-02PROC. REF: AMM 26-21-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 26 - FIRE PROTECTION									
262015	NO. 2 / RIGHT / UPPER FIRE EXTINGUISHER, LEFT SQUIB							Component	ATA:26
PN:30903856	MOS	16-Oct-24	180 (+14d/-14d)	TSN 0	16-Oct-39	30-Oct-39	4779 d (+14)		
SN:03214	HRS	9492.6		TSN 0					
	AFL	7560		TSN 0					
PROC. REF: AMM 26-21-02PROC. REF: AMM 26-21-02									
262015A	NO. 2 / RIGHT / UPPER FIRE EXTINGUISHER, LEFT SQUIB SERVICE LIFE LIMIT (D2620007)							Service	ATA:26
PN:30903856	MOS	16-Oct-24	120 (+14d/-14d)		16-Oct-34	30-Oct-34	2953 d (+14)	SERVICE LIFE LIMIT	
SN:03214	HRS	9492.6							
	AFL	7560							
PROC. REF: AMM 26-21-02PROC. REF: AMM 26-21-02									
262016	NO. 2 / RIGHT / UPPER FIRE EXTINGUISHER, RIGHT SQUIB							Component	ATA:26
PN:30903859	MOS	16-Oct-24	180 (+14d/-14d)	TSN 0	16-Oct-39	30-Oct-39	4779 d (+14)	LIFE LIMIT	
SN:02286	HRS	9492.6		TSN 0					
	AFL	7560		TSN 0					
PROC. REF: AMM 26-21-02PROC. REF: AMM 26-21-02									
262016A	NO. 2 / RIGHT / UPPER FIRE EXTINGUISHER, RIGHT SQUIB SERVICE LIFE LIMIT							Service	ATA:26
PN:30903859	MOS	16-Oct-24	120 (+14d/-14d)		16-Oct-34	30-Oct-34	2953 d (+14)		
SN:02286	HRS	9492.6							
	AFL	7560							
PROC. REF: AMM 26-21-02PROC. REF: AMM 26-21-02									
262041	PILOT PORTABLE FIRE EXTINGUISHER							Component	ATA:26
PN:A344	MOS/MSC	13-Oct-17	O/C	TSN 0					
SN:D-00364181	HRS	7059.3		TSN 0					
	AFL	5738		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
262041B	HYDROSTATIC TEST PILOT PORTABLE FIRE EXTINGUISHER (Q2510003)							Service	ATA:26
PN:A344	MOS	13-Oct-17	144 (+14d/-14d)		13-Oct-29	27-Oct-29	1124 d (+14)		
SN:D-00364181	HRS	7059.3							
	AFL	5738							
PROC. REF: AMM 26-23-00PROC. REF: AMM 26-23-00									

?-Insufficient Information

S-Suppressed Requirement

*-Estimated Due(New Requirement)

(EFF)-Effective C / W

(M)-Manual Due

U-User Task

Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 26 - FIRE PROTECTION									
262042	COPILOT PORTABLE FIRE EXTINGUISHER							Component	ATA:26
PN:A344	MOS/MSC	13-Oct-17	O/C	TSN 0					
SN:D-00363453	HRS	7059.3		TSN 0					
	AFL	5738		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
262042B	HYDROSTATIC TEST COPILOT PORTABLE FIRE EXTINGUISHER (Q2510003)							Service	ATA:26
PN:A344	MOS	13-Oct-17	144 (+14d/-14d)		13-Oct-29	27-Oct-29	1124 d (+14)		
SN:D-00363453	HRS	7059.3							
	AFL	5738							
PROC. REF: AMM 26-23-00PROC. REF: AMM 26-23-00									
262051	CABIN PORTABLE FIRE EXTINGUISHER							Component	ATA:26
PN:C352	MOS/MSC	13-Oct-17	O/C	TSN 0					
SN:E-09392938	HRS	7059.3		TSN 0					
	AFL	5738		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
262051B	HYDROSTATIC TEST CABIN PORTABLE FIRE EXTINGUISHER (Q2510003)							Service	ATA:26
PN:C352	MOS	13-Oct-17	144 (+14d/-14d)		13-Oct-29	27-Oct-29	1124 d (+14)		
SN:E-09392938	HRS	7059.3							
	AFL	5738							
PROC. REF: AMM 26-23-00PROC. REF: AMM 26-23-00									
5-19-00-O2610001-LEFT	NO. 1 ENGINE HOT SECTION FIRE DETECTOR ELEMENT - PERFORM VISUAL INSPECTION (IRN O2610001)							Service	ATA:26
	MOS	16-Mar-26							
	HRS	9596.2	3500 (+100/-100)		13096.2	13196.2	3254.9 (+100)		
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
5-19-00-O2610001-RIGHT	NO. 2 ENGINE HOT SECTION FIRE DETECTOR ELEMENT - PERFORM VISUAL INSPECTION (IRN O2610001)							Service	ATA:26
	MOS	16-Mar-26							
	HRS	9596.2	3500 (+100/-100)		13096.2	13196.2	3254.9 (+100)		
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 26 - FIRE PROTECTION									
J2620000	^S	** ENGINE FIRE EXTINGUISHING SYSTEM FIRE SWITCH - PERFORM FUNCTIONAL TEST (AWL**)						Service	ATA:26
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	4800 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 26-21-00PROC. REF: AMM 26-21-00									PKG:25
T2620001	^S	** FIREWALL SHUTOFF VALVES - PERFORM OPERATIONAL CHECK (AWL**)						Service	ATA:26
	MOS	13-Mar-26	48 (+14d/-14d)					AIRWORTHINESS	
	HRS	9596.2	1200 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 26-21-00PROC. REF: AMM 26-21-00									PKG:13
Y2610000	^S	FIREWALL AND ACCESSORY COMPARTMENT FIRE DETECTOR ELEMENTS - PERFORM VISUAL INSPECTION.						Service	ATA:26
	MOS	13-Mar-26	24 (+14d/-14d)						
	HRS	9596.2	600 (+25/-25)						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:9
Y2620002	^S	ENGINE FIRE EXTINGUISHER CONTAINERS - PERFORM VISUAL INSPECTION. CHECK CONTAINERS FOR CONDITION, CARTRIDGES AND CARTRIDGE WIRING FOR SECURITY AND CONDITION, CONTAINER PRESSURE GAGES FOR PROPER PRESSURES, AND PLUMBING FOR SECURITY AND CONDITION.						Service	ATA:26
	MOS	13-Mar-26	12 (+14d/-14d)						
	HRS	9596.2	300 (+25/-25)						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:2
Y2620005	^S	ENGINE FIRE EXTINGUISHING SYSTEM - PERFORM OPERATIONAL CHECK						Service	ATA:26
	MOS	13-Mar-26	96 (+14d/-14d)						
	HRS	9596.2	2400 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 26-21-00PROC. REF: AMM 26-21-00									PKG:19

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
---------	------	-------	----------	------------	----------------------------	-----------	-----------	-------------	----------

ATA 26 - FIRE PROTECTION

Y2620009	^S	INSPECT PORTABLE HAND HELD FIRE EXTINGUISHERS FOR CONDITION AND DATE OF MANUFACTURE. CHECK OPERATING PRESSURE AND WEIGHT PER MAINTENANCE INSTRUCTIONS ON FIRE EXTINGUISHER BOTTLE.						Service	ATA:26
	MOS	13-Mar-26	12	(+14d/-14d)					
	HRS	9596.2	300	(+25/-25)					
	AFL	7624							
PROC. REF: AMM 26-23-00PROC. REF: AMM 26-23-00									PKG:1

Z2620021	^S	NO. 1 ENGINE FIRE EXTINGUISHER CONTAINER PLUMBING - PERFORM DETAILED INSPECTION						Service	ATA:26
	MOS	13-Mar-26	12						
	HRS	9596.2	300						
	AFL	7624							
PROC. REF: AMM 26-21-00PROC. REF: AMM 26-21-00									PKG:2

Z2620021	^S	NO. 2 ENGINE FIRE EXTINGUISHER CONTAINER PLUMBING - PERFORM DETAILED INSPECTION						Service	ATA:26
	MOS	13-Mar-26	12						
	HRS	9596.2	300						
	AFL	7624							
PROC. REF: AMM 26-21-00PROC. REF: AMM 26-21-00									PKG:2

ATA 27 - FLIGHT CONTROLS

270308	^U	TRIM SWITCH PANEL						Component	ATA:27
PN:4522208501-018	MOS/MSC	10-May-05	O/C	TSN 0					
SN:A00346119-01	HRS	0		TSN 0					
	AFL	0		TSN 0					

271095		PILOT ANGLE OF ATTACK INDICATOR						Component	ATA:27
PN:C-38805-1	MOS/MSC	10-May-05	O/C	TSN 0					
SN:83042	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
271096	COPILOT ANGLE OF ATTACK INDICATOR							Component	ATA:27
PN:C-38805-1	MOS/MSC	10-May-05	O/C	TSN 0					
SN:83044	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
271560	AILERON TRIM ACTUATOR							Component	ATA:27
PN:6627108000-001	MOS/MSC	10-May-05	O/C	TSN 0					
SN:0363	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-10-09PROC. REF: AMM 27-10-09									
272031	PILOT RUDDER PEDAL ADJUST ACTUATOR							Component	ATA:27
PN:6627208001-001	MOS/MSC	10-May-05	O/C	TSN 0					
SN:0783	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-20-05PROC. REF: AMM 27-20-05									
272032	COPILOT RUDDER PEDAL ADJUST ACTUATOR							Component	ATA:27
PN:6627208001-001	MOS/MSC	10-May-05	O/C	TSN 0					
SN:0785	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-20-05PROC. REF: AMM 27-20-05									
272550	RUDDER TRIM ACTUATOR							Component	ATA:27
PN:4323322	MOS/MSC	10-May-05	O/C	TSN 0					
SN:0310	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-20-03PROC. REF: AMM 27-20-03									
273063	PILOT STICK SHAKER							Component	ATA:27
PN:6627308500-009	MOS/MSC	10-May-05	O/C	TSN 0					
SN:1423	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-31-03PROC. REF: AMM 27-31-03									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR
Serial: 45-2027
RegNo: N116PJ
HRS: 9841.3
AFL: 7790
As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
273064	COPILOT STICK SHAKER							Component	ATA:27
PN:6627308500-009	MOS/MSC	10-May-05	O/C	TSN 0					
SN:1412	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-31-03PROC. REF: AMM 27-31-03									
273075	LH ANGLE OF ATTACK TRANSMITTER							Component	ATA:27
PN:6627308500-001	MOS/MSC	26-Oct-06	O/C						
SN:860	HRS	945.68							
	AFL	753							
PROC. REF: AMM 27-31-01PROC. REF: AMM 27-31-01									
273076	RH ANGLE OF ATTACK TRANSMITTER							Component	ATA:27
PN:6627308500-001	MOS/MSC	10-May-05	O/C	TSN 0					
SN:895	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-31-01PROC. REF: AMM 27-31-01									
273087	STALL WARNING COMPUTER							Component	ATA:27
PN:6627308500-013	MOS/MSC	16-Mar-26	O/C						
SN:122	HRS	9596.2							
	AFL	7624							
PROC. REF: AMM 27-31-02PROC. REF: AMM 27-31-02									
274011	HORIZONTAL STABILIZER ACTUATOR							Component	ATA:27
PN:6627401000-009	MOS/MSC	13-Mar-26	O/C						
SN:B0581	HRS	9596.2		TSO 175.9					
	AFL	7624		TSO 106					
PROC. REF: AMM 27-40-02PROC. REF: AMM 27-40-02									
274011A	HORIZONTAL STABILIZER ACTUATOR * PERFORM INSPECTION (IRN T2740002 FOR P/N 6627401000-007 OR IRN P2740032 FOR P/N 6627401000-009)							Service	ATA:27
PN:6627401000-009	MOS	13-Mar-26							
SN:B0581	HRS	9596.2	1200	TAC 940.5	9855.7		14.4		
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C / W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
274011B	HORIZONTAL STABILIZER ACTUATOR * PERFORM DETAILED STRUCTURAL INSPECTION (IRN N2740025 FOR P/N 6627401000-007 OR IRN P2740033 FOR P/N 6627401000-009) (AWL*)							Service	ATA:27
PN:6627401000-009	MOS	13-Mar-26						AIRWORTHINESS	
SN:B0581	HRS	9596.2	2400	TAC 940.5	11055.7		1214.4		
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
274041	FWD INTERFACE UNIT							Component	ATA:27
PN:4527408503-027	MOS/MSC	03-Jun-13	O/C						
SN:MRP642750	HRS	5513.02							
	AFL	4486							
PROC. REF: AMM 27-40-04PROC. REF: AMM 27-40-04									
274051	HORIZONTAL STAB ACTUATOR CONTROL UNIT							Component	ATA:27
PN:6627401000-003	MOS/MSC	11-Mar-22	O/C						
SN:D0581	HRS	8721.2							
	AFL	7006							
PROC. REF: AMM 27-40-03PROC. REF: AMM 27-40-03									
274164	TRIM-IN-MOTION DETECTOR							Component	ATA:27
PN:1625-1-1	MOS/MSC	10-May-05	O/C	TSN 0					
SN:205050274	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-41-01PROC. REF: AMM 27-41-01									
275014	LH FLAP DRIVE RVDT							Component	ATA:27
PN:C144489-2	MOS/MSC	10-May-05	O/C	TSN 0					
SN:A0654	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-50-03PROC. REF: AMM 27-50-03									
275015	RH FLAP DRIVE RVDT							Component	ATA:27
PN:C144489-2	MOS/MSC	10-May-05	O/C	TSN 0					
SN:A0659	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-50-03PROC. REF: AMM 27-50-03									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR
Serial: 45-2027
RegNo: N116PJ
HRS: 9841.3
AFL: 7790
As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
275021	LH IB FLAP ACTUATOR							Component	ATA:27
PN:C144487-4	MOS/MSC	14-Mar-19	O/C						
SN:1935	HRS	7551							
	AFL								
PROC. REF: AMM 27-50-06PROC. REF: AMM 27-50-06									
275022	RH IB FLAP ACTUATOR							Component	ATA:27
PN:C144487-4	MOS/MSC	25-Jan-15	O/C						
SN:1204	HRS	6669.27							
	AFL	5419							
PROC. REF: AMM 27-50-06PROC. REF: AMM 27-50-06									
275023	LH OB FLAP ACTUATOR							Component	ATA:27
PN:6627503000-033	MOS/MSC	25-Jan-15	O/C						
SN:1229	HRS	6669.27							
	AFL	5419							
PROC. REF: AMM 27-50-06PROC. REF: AMM 27-50-06									
275024	RH OB FLAP ACTUATOR							Component	ATA:27
PN:C144488-4	MOS/MSC	25-Jan-15	O/C						
SN:2059	HRS	6669.27							
	AFL	5419							
PROC. REF: AMM 27-50-06PROC. REF: AMM 27-50-06									
275040	FLAP CONTROL UNIT							Component	ATA:27
PN:C144486-3-003	MOS/MSC	02-Oct-23	O/C						
SN:1663	HRS	9194.3							
	AFL	7332							
PROC. REF: AMM 27-50-05PROC. REF: AMM 27-50-05									
275055	FLAP LEVER MODULE ASSY							Component	ATA:27
PN:69013-15	MOS/MSC	02-Aug-05	O/C						
SN:029	HRS	31.7							
	AFL	22							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

? - Insufficient Information
S - Suppressed Requirement
* - Estimated Due(New Requirement)
(EFF) - Effective C / W
(M) - Manual Due
U - User Task
Ex - Excluded Task

Status Report

Model: LEARJET 40XR
Serial: 45-2027
RegNo: N116PJ
HRS: 9841.3
AFL: 7790
As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
275057	FLAP DRIVE POWER UNIT							Component	ATA:27
PN:6627503000-001	MOS/MSC	13-Mar-26	O/C						
SN:1358	HRS	9596.2		TSN 2338.3					
	AFL	7624		TSN 1611					
Special Properties: RII ITEM									
PROC. REF: AMM 27-50-08PROC. REF: AMM 27-50-08									
275069	FLAP POSITION INDICATOR							Component	ATA:27
PN:C145159-1	MOS/MSC	10-May-05	O/C	TSN 0					
SN:1429	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-50-07PROC. REF: AMM 27-50-07									
276001	LH SPOILER ACTUATOR							Component	ATA:27
PN:6627602001-007	MOS/MSC	25-May-06	O/C						
SN:DAW521-01	HRS	578.27							
	AFL	440							
PROC. REF: AMM 27-60-04PROC. REF: AMM 27-60-04									
276002	RH SPOILER ACTUATOR							Component	ATA:27
PN:P455A0001-03	MOS/MSC	25-May-06	O/C						
SN:DAW022-95	HRS	578.27							
	AFL	440							
PROC. REF: AMM 27-60-04PROC. REF: AMM 27-60-04									
2760085 ^S	SPOILER LEVER ARM - PERFORM DETAILED VISUAL INSPECTION TO ENSURE SPOILER LEVER ARM IS PROPERLY SEATED AND SECURED ON SPOILER RVDT SHAFT							Service	ATA:27
	MOS	13-Mar-26	36 (+14d/-14d)						
	HRS	9596.2	600 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 27-60-05PROC. REF: AMM 27-60-05									
276013	SPOILER SHUTOFF VALVE							Component	ATA:27
PN:6627602002-005	MOS/MSC	10-May-05	O/C	TSN 0					
SN:0052T	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-60-07PROC. REF: AMM 27-60-07									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
276014	SPOILER CONTROL LEVER MODULE								Component ATA:27
PN:69014-7	MOS/MSC	10-May-05	O/C	TSN 0					
SN:339	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-60-03PROC. REF: AMM 27-60-03									
276049	LH SPOILER RVDT								Component ATA:27
PN:4527603007-001	MOS/MSC	01-Dec-05	O/C						
SN:A0650	HRS								
	AFL								
PROC. REF: AMM 27-60-05PROC. REF: AMM 27-60-05									
276050	RH SPOILER RVDT								Component ATA:27
PN:4527603007-001	MOS/MSC	01-Dec-05	O/C						
SN:A0651	HRS								
	AFL								
PROC. REF: AMM 27-60-05PROC. REF: AMM 27-60-05									
276073	SPOILERON COMPUTER								Component ATA:27
PN:402800-07-01	MOS/MSC	10-May-23	O/C						
SN:00823	HRS	9071.3							
	AFL	7252							
PROC. REF: AMM 27-60-02PROC. REF: AMM 27-60-02									
276076	CONTROL WHEEL RVDT								Component ATA:27
PN:3G4-211A	MOS/MSC	16-Mar-26	O/C						
SN:UNKNOWN	HRS	9596.2		TSN 4553.6					
	AFL	7624		TSN 4512					
PROC. REF: AMM 27-60-06PROC. REF: AMM 27-60-06									
5-19-00-D2740003	** HORIZONTAL STABILIZER ACTUATOR SECONDARY TRIM - PERFORM FUNCTIONAL TEST (IRN D2740003) (AWL**)								Service ATA:27
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	600 (+25/-25)	10196.2	10221.2	354.9 (+25)			
	AFL	7624							
PROC. REF: AMM 27-40-02PROC. REF: AMM 27-40-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
5-19-00-D2740004	** HORIZONTAL STABILIZER ACTUATOR PRIMARY TRIM - PERFORM FUNCTIONAL TEST (IRN D2740004) (AWL**)							Service	ATA:27
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	600 (+25/-25)		10196.2	10221.2	354.9 (+25)		
	AFL	7624							
PROC. REF: AMM 27-40-02PROC. REF: AMM 27-40-02									
5-19-00-K2700007	* AILERON CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED VISUAL INSPECTION (IRN K2700007) (AWL*)							Service	ATA:27
	MOS	10-May-23						AIRWORTHINESS	
	HRS	9071.3	4800		13871.3		4030		
	AFL	7252							
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00									
5-19-00-K2700007-LEFT	U S DETAILED VISUAL INSPECTION LEFT * AILERON CONTROL SYSTEM PRIMARY CABLES (K2700007)							Service	ATA:27
	MOS	27-Oct-11						AIRWORTHINESS	
	HRS	4469.73	4800						
	AFL	3671							
5-19-00-K2700007-RIGHT	U S DETAILED VISUAL INSPECTION RIGHT * AILERON CONTROL SYSTEM PRIMARY CABLES (K2700007)							Service	ATA:27
	MOS	27-Oct-11						AIRWORTHINESS	
	HRS	4469.73	4800						
	AFL	3671							
5-19-00-K2700008	* ELEVATOR CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED VISUAL INSPECTION (IRN K2700008) (AWL*)							Service	ATA:27
	MOS	10-May-23						AIRWORTHINESS	
	HRS	9071.3	4800		13871.3		4030		
	AFL	7252							
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00									
5-19-00-K2700009	* RUDDER CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED VISUAL INSPECTION (IRN K2700009) (AWL*)							Service	ATA:27
	MOS	10-May-23						AIRWORTHINESS	
	HRS	9071.3	4800		13871.3		4030		
	AFL	7252							
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
5-19-00-K2700010	* ELEVATOR CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED INSPECTION (IRN K2700010) (AWL*)							Service	ATA:27
	MOS	10-May-23						AIRWORTHINESS	
	HRS	9071.3	4800		13871.3		4030		
	AFL	7252							
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00									
5-19-00-K2700012	* RUDDER CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED VISUAL INSPECTION (IRN K2700012) (AWL*)							Service	ATA:27
	MOS	10-May-23						AIRWORTHINESS	
	HRS	9071.3	4800		13871.3		4030		
	AFL	7252							
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00									
5-19-00-K2700014	* AILERON CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED VISUAL INSPECTION (IRN K2700014) (AWL*)							Service	ATA:27
	MOS	10-May-23						AIRWORTHINESS	
	HRS	9071.3	4800		13871.3		4030		
	AFL	7252							
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00									
5-19-00-N2720030	RUDDER TORQUE TUBE AND SPINDLE - PERFORM DETAILED VISUAL INSPECTION (IRN N2720030)							Service	ATA:27
	MOS	22-Apr-24	72 (+14d/-14d)	Adj -9d	13-Apr-30	27-Apr-30	1306 d (+14)		
	HRS	9368.9							
	AFL	7476							
PROC. REF: AMM 27-20-01PROC. REF: AMM 27-20-01									
5-19-00-S2750057	* FLAP ACTUATOR BALLNUT SLEEVE - PERFORM FLOURESCENT PENETRANT INSPECTION (FLAP ACTUATOR ASSEMBLY LEARJET P/N 6627503000-009, 6627503000-011, 6627503000-021, 6627503000-023, 6627503000-025 AND 6627503000-027, MICROTECNICA P/N C144487-1, C144488-1, C144487-2, C144488-2, C144487-3 AND C144488-3) (AWL*)							Service	ATA:27
	MOS/MS	-						N/A BY PART NUMBER	
	HRS								
	AFL								
PROC. REF: NDT PART 8/27-50-01, NDT PART 8/27-50-02PROC. REF: NDT PART 8/27-50-01, NDT PART 8/27-50-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
5-19-00-W2750056	* FLAP ACTUATOR JOINT (P/N 145673-1) - PERFORM DETAILED VISUAL INSPECTION. APPLY CORROSION PREVENTIVE COMPOUND (CPC) TO JOINT. (AWL*)							Service	ATA:27
	MOS/MSC	25-Jan-15	N/A					N/A BY PART NUMBER	
	HRS								
	AFL								
PROC. REF: AMM 27-50-06PROC. REF: AMM 27-50-06									
5-19-01-AA2760021-LEFT	LEFT SPOILER HYDRAULIC PRESSURE SWIVEL - REPLACE							Service	ATA:27
	MOS	13-Mar-26							
	HRS	9596.2	1200 (+25/-25)		10796.2	10821.2	954.9 (+25)		
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
5-19-01-AA2760021-LEFT	LEFT SPOILER HYDRAULIC RETURN SWIVEL - REPLACE							Service	ATA:27
	MOS	13-Mar-26							
	HRS	9596.2	1200 (+25/-25)		10796.2	10821.2	954.9 (+25)		
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
5-19-01-AA2760021-RIGHT	RIGHT SPOILER HYDRAULIC PRESSURE SWIVEL - REPLACE							Service	ATA:27
	MOS	13-Mar-26							
	HRS	9596.2	1200 (+25/-25)		10796.2	10821.2	954.9 (+25)		
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
5-19-01-AA2760021-RIGHT	RIGHT SPOILER HYDRAULIC RETURN SWIVEL - REPLACE							Service	ATA:27
	MOS	13-Mar-26							
	HRS	9596.2	1200 (+25/-25)		10796.2	10821.2	954.9 (+25)		
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
5-19-01-R2710041	REPLACE * AILERON SPINDLE (4527102103-001) (AWL*)								Service ATA:27
	MOS/MSC	10-May-05	N/A					N/A EQUIPMENT NOT INSTALLED	
	HRS	0							
	AFL	0							
PROC. REF: AMM 27-10-07PROC. REF: AMM 27-10-07									
5-19-01-W2750055	* REPLACE FLAP ACTUATOR JOINT (P/N 145673-1) (Q2750055) (AWL*)								Component ATA:27
PN:PN	MOS/MSC	25-Jan-15	N/A	TSN 0				NOT APPLICABLE	
SN:UNKNOWN	HRS			TSN 0					
	AFL			TSN 0					
PROC. REF: AMM 27-50-06PROC. REF: AMM 27-50-06									
A2711001 ^S	** AILERON TRIM TAB CONTROL SYSTEM - PERFORM OPERATIONAL CHECK. (AWL**)								Service ATA:27
	MOS	13-Mar-26	24 (+14d/-14d)					AIRWORTHINESS	
	HRS	9596.2	600 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 27-10-04PROC. REF: AMM 27-10-04									
A2721001 ^S	** RUDDER TRIM SYSTEM - PERFORM OPERATIONAL CHECK. (AWL**)								Service ATA:27
	MOS	13-Mar-26	24 (+14d/-14d)					AIRWORTHINESS	
	HRS	9596.2	600 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 27-20-00PROC. REF: AMM 27-20-00									
A2731002 ^S	** ELEVATOR DISCONNECT SYSTEM - PERFORM OPERATIONAL CHECK. (AWL**)								Service ATA:27
	MOS	13-Mar-26	24 (+14d/-14d)					AIRWORTHINESS	
	HRS	9596.2	600 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 27-30-00PROC. REF: AMM 27-30-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
A2760001	^S	** SPOILER ACTUATOR CHECK VALVE - PERFORM OPERATIONAL CHECK (AWL**)						Service	ATA:27
	MOS	13-Mar-26	24 (+14d/-14d)					AIRWORTHINESS	
	HRS	9596.2	600 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 27-60-04PROC. REF: AMM 27-60-04									PKG:10
A2760002	^S	** SPOILER SYSTEM - PERFORM SPOILER AUTHORITY WITH FLAPS CHECK (AWL**)						Service	ATA:27
	MOS	13-Mar-26	24 (+14d/-14d)					AIRWORTHINESS	
	HRS	9596.2	600 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 27-60-00PROC. REF: AMM 27-60-00									PKG:10
AA2700000	^S	AILERON CONTROL CABLE SYSTEM - WITH COCKPIT AND CABIN FLOORBOARDS REMOVED, PERFORM VISUAL INSPECTION OF ACCESSIBLE CABLES						Service	ATA:27
	MOS	13-Mar-26	24 (+14d/-14d)						
	HRS	9596.2	600 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00									PKG:7
AA2700001	^S	RUDDER CONTROL CABLE SYSTEM - WITH COCKPIT AND CABIN FLOORBOARDS REMOVED, PERFORM VISUAL INSPECTION OF ACCESSIBLE CABLES						Service	ATA:27
	MOS	13-Mar-26	24 (+14d/-14d)						
	HRS	9596.2	600 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00									PKG:7
AA2700002	^S	ELEVATOR CONTROL CABLE SYSTEM - WITH COCKPIT AND CABIN FLOORBOARDS REMOVED, PERFORM VISUAL INSPECTION OF ACCESSIBLE CABLES						Service	ATA:27
	MOS	13-Mar-26	24 (+14d/-14d)						
	HRS	9596.2	600 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00									PKG:7

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
AE2710049		* AILERON LEADING EDGE (INTERNAL) - PERFORM BORESCOPE INSPECTION						Service	ATA:27
	MOS	EFF	T:6		RTS			AIRWORTHINESS	
	HRS								
	AFL								
PROC. REF: AMM 27-10-02PROC. REF: AMM 27-10-02									
AE2730037 ^S		PERFORM DETAILED VISUAL INSPECTION OF THE ELEVATOR UP/DOWN SPRING ASSEMBLY, YOKE ASSEMBLY AND ASSOCIATED PARTS FOR FREE MOVEMENT, LOOSE FASTENERS AND SECURITY OF LOCKING DEVICES.						Service	ATA:27
	MOS	13-Mar-26	48						
	HRS	9596.2	1200						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
PKG:14									
AF2710051		* AILERON BALANCE WEIGHT SUPPORT BRACKETS - PERFORM EDDY CURRENT INSPECTION						Service	ATA:27
	MOS	EFF	T:6		28-Oct-26 *		43 d	AIRWORTHINESS	
	HRS								
	AFL								
G2710003 ^S		AILERON CONTROL SYSTEM CABLES (LOCATED IN WING AREA) - PERFORM CABLE TENSION CHECK						Service	ATA:27
	MOS	13-Mar-26	48 (+14d/-14d)						
	HRS	9596.2	1200 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 27-10-00PROC. REF: AMM 27-10-00									
PKG:16									
G2710004 ^S		AILERON CONTROL SYSTEM CABLES (LOCATED IN FUSELAGE AREA) - PERFORM CABLE TENSION CHECK						Service	ATA:27
	MOS	13-Mar-26	48 (+14d/-14d)						
	HRS	9596.2	1200 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 27-10-00PROC. REF: AMM 27-10-00									
PKG:13									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR
Serial: 45-2027
RegNo: N116PJ
HRS: 9841.3
AFL: 7790
As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
G2720003 ^S		RUDDER CONTROL CABLES - PERFORM TENSION CHECK						Service	ATA:27
	MOS	13-Mar-26	48 (+14d/-14d)						
	HRS	9596.2	1200 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 27-20-00PROC. REF: AMM 27-20-00									PKG:14
G2720004 ^S		RUDDER PEDALS, PEDAL PUSHRODS, ADJUSTMENT ACTUATOR, AND SECTORS - PERFORM VISUAL INSPECTION. CHECK DURING FULL TRAVEL OF RUDDER						Service	ATA:27
	MOS	13-Mar-26	48 (+14d/-14d)						
	HRS	9596.2	1200 (+25/-25)						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:13
G2730003 ^S		ELEVATOR CONTROL CABLES - PERFORM TENSION CHECK						Service	ATA:27
	MOS	13-Mar-26	48 (+14d/-14d)						
	HRS	9596.2	1200 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 27-30-00PROC. REF: AMM 27-30-00									PKG:14
V2712000 ^S		** ROLL DISCONNECT SWITCHES - PERFORM OPERATIONAL CHECK (AWL**)						Service	ATA:27
	MOS	13-Mar-26	24 (+14d/-14d)					AIRWORTHINESS	
	HRS	9596.2	600 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 27-60-09PROC. REF: AMM 27-60-09									PKG:7
W2731001 ^S		** PITCH TRIM - PERFORM OPERATIONAL CHECK OF ELEVATOR OVERRIDE ACTUATOR (AWL**)						Service	ATA:27
	MOS	13-Mar-26	24 (+14d/-14d)					AIRWORTHINESS	
	HRS	9596.2	600 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 27-30-14PROC. REF: AMM 27-30-14									PKG:8

? - Insufficient Information
S - Suppressed Requirement
* - Estimated Due(New Requirement)
(EFF) - Effective C / W
(M) - Manual Due
U - User Task
Ex - Excluded Task

Status Report

Model: LEARJET 40XR
Serial: 45-2027
RegNo: N116PJ
HRS: 9841.3
AFL: 7790
As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty	
ATA 27 - FLIGHT CONTROLS										
Y2700003 ^S		AILERON CONTROL CABLE SYSTEM - PERFORM VISUAL INSPECTION OF CABLES WITHIN WING							Service	ATA:27
	MOS	13-Mar-26	24 (+14d/-14d)							
	HRS	9596.2	600 (+25/-25)							
	AFL	7624								
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00										
PKG:10										
Y2700004 ^S		RUDDER CONTROL CABLE SYSTEM - PERFORM VISUAL INSPECTION OF ACCESSIBLE UPPER AND LOWER CABLES							Service	ATA:27
	MOS	13-Mar-26	24 (+14d/-14d)							
	HRS	9596.2	600 (+25/-25)							
	AFL	7624								
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00										
PKG:8										
Y2700005 ^S		ELEVATOR CONTROL CABLE SYSTEM - PERFORM VISUAL INSPECTION OF ACCESSIBLE UPPER AND LOWER CABLES							Service	ATA:27
	MOS	13-Mar-26	24 (+14d/-14d)							
	HRS	9596.2	600 (+25/-25)							
	AFL	7624								
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00										
PKG:8										
Y2700006 ^S		RUDDER AND ELEVATOR CONTROL CABLES AND ASSOCIATED PULLEYS, LOCATED IN AFT PRESSURE BULKHEAD SUPPORT CHANNEL - PERFORM VISUAL INSPECTION							Service	ATA:27
	MOS	13-Mar-26	24 (+14d/-14d)							
	HRS	9596.2	600 (+25/-25)							
	AFL	7624								
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00										
PKG:9										
Y2710000 ^S		AILERONS, AILERON TRIM TAB AND VISIBLE PORTION OF RODS - PERFORM VISUAL INSPECTION.							Service	ATA:27
	MOS	13-Mar-26	24 (+14d/-14d)							
	HRS	9596.2	600 (+25/-25)							
	AFL	7624								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
PKG:10										

? - Insufficient Information
S - Suppressed Requirement
* - Estimated Due(New Requirement)
(EFF) - Effective C / W
(M) - Manual Due
U - User Task
Ex - Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
Y2710001	^S	AILERON BALANCE WEIGHT INSTALLATION AND SUPPORTING STRUCTURE - PERFORM VISUAL INSPECTION.						Service	ATA:27
	MOS	13-Mar-26	48 (+14d/-14d)						
	HRS	9596.2	1200 (+25/-25)						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:16
Y2710002	^S	AILERON CONTROL SYSTEM - PERFORM OPERATIONAL CHECK						Service	ATA:27
	MOS	13-Mar-26	48 (+14d/-14d)						
	HRS	9596.2	1200 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 27-10-00PROC. REF: AMM 27-10-00									PKG:16
Y2710048	^S	AILERON TRIM TAB INSTALLATION - PERFORM FREE PLAY CHECK						Service	ATA:27
	MOS	13-Mar-26	96 (+14d/-14d)						
	HRS	9596.2	2400 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 27-10-04PROC. REF: AMM 27-10-04									PKG:22
Y2720000	^S	RUDDER - PERFORM VISUAL INSPECTION.						Service	ATA:27
	MOS	13-Mar-26	12 (+14d/-14d)						
	HRS	9596.2	300 (+25/-25)						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:2
Y2720001	^S	RUDDER BALANCE WEIGHT INSTALLATION AND SUPPORTING STRUCTURE - PERFORM VISUAL INSPECTION						Service	ATA:27
	MOS	13-Mar-26	48 (+14d/-14d)						
	HRS	9596.2	1200 (+28/-28)						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:14

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR
Serial: 45-2027
RegNo: N116PJ
HRS: 9841.3
AFL: 7790
As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
Y2720002 ^S	RUDDER CONTROL SYSTEM - PERFORM OPERATIONAL CHECK								Service ATA:27
	MOS	13-Mar-26	48 (+14d/-14d)						
	HRS	9596.2	1200 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 27-20-00PROC. REF: AMM 27-20-00									
PKG:14									
Y2721000 ^S	RUDDER TRIM TAB AND VISIBLE RODS - PERFORM VISUAL INSPECTION.								Service ATA:27
	MOS	13-Mar-26	12 (+14d/-14d)						
	HRS	9596.2	300 (+25/-25)						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
PKG:2									
Y2730000 ^S	CONTROL COLUMNS - PERFORM VISUAL INSPECTION. PAY PARTICULAR ATTENTION TO AILERON CONTROL WHEEL CABLE DRUM AND BOTTOM CROSSOVER PULLEYS								Service ATA:27
	MOS	13-Mar-26	48 (+14d/-14d)						
	HRS	9596.2	1200 (+25/-25)						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
PKG:13									
Y2730001 ^S	ELEVATORS - PERFORM VISUAL INSPECTION								Service ATA:27
	MOS	13-Mar-26	12 (+14d/-14d)						
	HRS	9596.2	300 (+25/-25)						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
PKG:2									
Y2730002 ^S	ELEVATOR CONTROL SYSTEM - PERFORM OPERATIONAL CHECK								Service ATA:27
	MOS	13-Mar-26	48 (+14d/-14d)						
	HRS	9596.2	1200 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 27-30-00PROC. REF: AMM 27-30-00									
PKG:14									

? - Insufficient Information
S - Suppressed Requirement
* - Estimated Due(New Requirement)
(EFF) - Effective C / W
(M) - Manual Due
U - User Task
Ex - Excluded Task

Status Report

Model: LEARJET 40XR
Serial: 45-2027
RegNo: N116PJ
HRS: 9841.3
AFL: 7790
As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
Y2730004 ^S		CONTROL COLUMNS - PERFORM INSPECTION. INSPECT CABLE, PULLEYS, BEARINGS, AND ELECTRICAL WIRING						Service	ATA:27
	MOS	13-Mar-26	96 (+14d/-14d)						
	HRS	9596.2	2400 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00									PKG:19
Y2730007 ^S		AFT ELEVATOR DISCONNECT - PERFORM DETAILED VISUAL INSPECTION.						Service	ATA:27
	MOS	13-Mar-26	96 (+14d/-14d)						
	HRS	9596.2	2400 (+25/-25)						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:20
Y2740000 ^S		PRIMARY PITCH TRIM SYSTEM - PERFORM OPERATIONAL CHECK						Service	ATA:27
	MOS	13-Mar-26	48 (+14d/-14d)						
	HRS	9596.2	1200 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 27-40-00PROC. REF: AMM 27-40-00									PKG:14
Y2740001 ^S		SECONDARY PITCH TRIM SYSTEM - PERFORM OPERATIONAL CHECK						Service	ATA:27
	MOS	13-Mar-26	48 (+14d/-14d)						
	HRS	9596.2	1200 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 27-40-00PROC. REF: AMM 27-40-00									PKG:14
Y2750000 ^S		FLAP DRIVE INSTALLATION - PERFORM VISUAL INSPECTION WITH FLAPS LOWERED.						Service	ATA:27
	MOS	13-Mar-26	24 (+14d/-14d)						
	HRS	9596.2	600 (+25/-25)						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:10

? - Insufficient Information
S - Suppressed Requirement
* - Estimated Due(New Requirement)
(EFF) - Effective C / W
(M) - Manual Due
U - User Task
Ex - Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty	
ATA 27 - FLIGHT CONTROLS										
Y2750001	^S	FLAPS - PERFORM VISUAL INSPECTION							Service	ATA:27
	MOS	13-Mar-26	12	(+14d/-14d)						
	HRS	9596.2	300	(+25/-25)						
	AFL	7624								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
PKG:4										

Y2750053	^S	FLAP DRIVE ACTUATORS - PERFORM A VISUAL INSPECTION OF THE ACTUATOR ATTACHMENT, PAYING PARTICULAR ATTENTION TO THE GIMBAL PIN RETAINING RINGS.							Service	ATA:27	
	MOS	13-Mar-26	24	(+14d/-14d)							
	HRS	9596.2	600	(+25/-25)							
	AFL	7624									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF											PKG:10

Y2760000	^S	SPOILER AND SPOILER ACTUATOR - PERFORM VISUAL INSPECTION WITH FLAPS LOWERED AND ACCESS PANELS OPENED.						Service	ATA:27	
	MOS	13-Mar-26	24	(+14d/-14d)						
	HRS	9596.2	600	(+25/-25)						
	AFL	7624								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										PKG:10

ATA 28 - FUEL

281001	L/H BAY 1 FUEL, EJECTOR SCAVENGE PUMP				Component	ATA:28
PN:6628200302-001V0685	MOS/MSC	10-May-05	O/C	TSN 0		
SN:44040004	HRS	0		TSN 0		
	AFL	0		TSN 0		
PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01						

281002	R/H BAY 1 FUEL, EJECTOR SCAVENGE PUMP				Component	ATA:28
PN:6628200302-001V0685	MOS/MSC	10-May-05	O/C	TSN 0		
SN:44040012	HRS	0		TSN 0		
	AFL	0		TSN 0		
PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
281003	L/H BAY 3 FUEL, EJECTOR SCAVENGE PUMP							Component	ATA:28
PN:6628200302-001V0685	MOS/MSC	10-May-05	O/C	TSN 0					
SN:44040026	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01									
281004	R/H BAY 3 FUEL, EJECTOR SCAVENGE PUMP							Component	ATA:28
PN:6628200302-001V0685	MOS/MSC	10-May-05	O/C	TSN 0					
SN:44040011	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01									
281005	L/H BAY 2 FWD FUEL, EJECTOR SCAVENGE PUMP							Component	ATA:28
PN:6628200302-001V0685	MOS/MSC	10-May-05	O/C	TSN 0					
SN:44040008	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01									
281006	R/H BAY 2 FWD FUEL, EJECTOR SCAVENGE PUMP							Component	ATA:28
PN:6628200302-001V0685	MOS/MSC	10-May-05	O/C	TSN 0					
SN:44040010	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01									
281007	L/H BAY 2 AFT FUEL, EJECTOR SCAVENGE PUMP							Component	ATA:28
PN:6628200302-001V0685	MOS/MSC	10-May-05	O/C	TSN 0					
SN:44040025	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
281008	R/H BAY 2 AFT FUEL, EJECTOR SCAVENGE PUMP							Component	ATA:28
PN:6628200302-001V0685	MOS/MSC	10-May-05	O/C	TSN 0					
SN:44040020	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01									
281009	L/H BAY 9 FUEL, EJECTOR SCAVENGE PUMP							Component	ATA:28
PN:6628200302-001V0685	MOS/MSC	10-May-05	O/C	TSN 0					
SN:44040005	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01									
281010	R/H BAY 9 FUEL, EJECTOR SCAVENGE PUMP							Component	ATA:28
PN:6628200302-001V0685	MOS/MSC	10-May-05	O/C	TSN 0					
SN:44040003	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01									
281031	FUSELAGE FUEL CELL							Component	ATA:28
PN:6628100103-003	MOS/MSC	10-May-05	O/C	TSN 0					
SN:332	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-10-02PROC. REF: AMM 28-10-02									
281512	RH MOTORIZED SHUT OFF VALVE							Component	ATA:28
PN:6628200101-003	MOS/MSC	10-May-05	O/C	TSN 0					
SN:1102	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
282001	L/H NO. 1 MOTORIZED SHUT OFF VALVE							Component	ATA:28
PN:6628200101-003	MOS/MSC	10-May-05	O/C	TSN 0					
SN:1097	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR
 Serial: 45-2027
 RegNo: N116PJ
 HRS: 9841.3
 AFL: 7790
 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
282003	L/H NO. 2 MOTORIZED SHUT OFF VALVE							Component	ATA:28
PN:6628200101-003	MOS/MSC	10-May-05	O/C	TSN 0					
SN:1099	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
282011	SHUTOFF - REFUEL VALVE							Component	ATA:28
PN:6628200102-003	MOS/MSC	10-May-05	O/C	TSN 0					
SN:46041020	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-20-10PROC. REF: AMM 28-20-10									
282013	CENTER DEFUEL SHUT OFF VALVE							Component	ATA:28
PN:91816-EM9102-2	MOS/MSC	10-May-05	O/C	TSN 0					
SN:1074	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-20-07PROC. REF: AMM 28-20-07									
282033	RH MAIN EJECTOR PUMP							Component	ATA:28
PN:6628200301-001	MOS/MSC	10-May-05	O/C	TSN 0					
SN:36040168	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-20-01PROC. REF: AMM 28-20-01									
282041	CONTROL - REFUELING PANEL							Component	ATA:28
PN:452840800V5-001	MOS/MSC	10-May-05	O/C	TSN 0					
SN:04120826BA	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-20-14PROC. REF: AMM 28-20-14									
282043	L-1 FUEL SUPPLY CHECK VALVE							Component	ATA:28
PN:7628200101-001	MOS/MSC	10-May-05	O/C	TSN 0					
SN:M0146CV1104	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-20-03PROC. REF: AMM 28-20-03									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
282044	R-2 FUEL SUPPLY CHECK VALVE							Component	ATA:28
PN:7628200101-001	MOS/MSC	10-May-05	O/C	TSN 0					
SN:M0189CV0904	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-20-03PROC. REF: AMM 28-20-03									
282045	R-1 FUEL SUPPLY CHECK VALVE							Component	ATA:28
PN:7628200101-001	MOS/MSC	10-May-05	O/C	TSN 0					
SN:M0158CV1084	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-20-03PROC. REF: AMM 28-20-03									
282046	L-2 FUEL SUPPLY CHECK VALVE							Component	ATA:28
PN:7628200101-001	MOS/MSC	10-May-05	O/C	TSN 0					
SN:M0148CV1104	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-20-03PROC. REF: AMM 28-20-03									
282051	LH MOTIVE FLOW CHECK VALVE							Component	ATA:28
PN:6628200106-003	MOS/MSC	10-May-05	O/C	TSN 0					
SN:38040216	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-20-05PROC. REF: AMM 28-20-05									
282052	RH MOTIVE FLOW CHECK VALVE							Component	ATA:28
PN:6628200106-003	MOS/MSC	10-May-05	O/C	TSN 0					
SN:31040894	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-20-05PROC. REF: AMM 28-20-05									
282063	PRE-CHECK SPPR VALVE							Component	ATA:28
PN:6628200116-001	MOS/MSC	14-May-15	O/C	TSN 0					
SN:44120253	HRS	6708.1		TSN 0					
	AFL	5450		TSN 0					
PROC. REF: AMM 28-20-12PROC. REF: AMM 28-20-12									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
282064	PILOT SPPR VALVE							Component	ATA:28
PN:61087-2	MOS/MSC	10-May-05	O/C	TSN 0					
SN:320	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-20-11PROC. REF: AMM 28-20-11									
282087	LH STANDBY FUEL PUMP							Component	ATA:28
PN:6628200303-003	MOS/MSC	10-May-05	O/C	TSN 0					
SN:12AV74	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-20-02PROC. REF: AMM 28-20-02									
282088	RH STANDBY FUEL PUMP							Component	ATA:28
PN:6628200303-003	MOS/MSC	10-May-05	O/C	TSN 0					
SN:12AV75	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-20-02PROC. REF: AMM 28-20-02									
282113	LH FUEL TRANSFER VALVE							Component	ATA:28
PN:7628200104-001	MOS/MSC	10-May-05	O/C	TSN 0					
SN:M0144CV1104	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-12-03PROC. REF: AMM 28-12-03									
282114	RH FUEL TRANSFER VALVE							Component	ATA:28
PN:7628200104-001	MOS/MSC	10-May-05	O/C	TSN 0					
SN:M0145CV1104	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-12-03PROC. REF: AMM 28-12-03									
284001	C1 FUEL PROBE ASSEMBLY							Component	ATA:28
PN:6628408000-001	MOS/MSC	10-May-05	O/C	TSN 0					
SN:0709	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
284002	C2 FUEL PROBE ASSEMBLY							Component	ATA:28
PN:6628408000-027	MOS/MSC	22-Feb-06	O/C						
SN:0663	HRS	386.77							
	AFL	298							
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05									
284003	C3 FUEL PROBE ASSEMBLY							Component	ATA:28
PN:6628408000-005	MOS/MSC	10-May-05	O/C	TSN 0					
SN:0688	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05									
284004	C4 FUEL PROBE ASSEMBLY							Component	ATA:28
PN:6628408000-007	MOS/MSC	10-May-05	O/C	TSN 0					
SN:0796	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05									
284005	C5 FUEL PROBE ASSEMBLY							Component	ATA:28
PN:6628408000-009	MOS/MSC	10-May-05	O/C	TSN 0					
SN:1041	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05									
284006	C6 FUEL PROBE ASSEMBLY							Component	ATA:28
PN:6628408000-011	MOS/MSC	10-May-05	O/C	TSN 0					
SN:1349	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05									
284008	C8 FUEL PROBE ASSEMBLY							Component	ATA:28
PN:6628408000-001	MOS/MSC	10-May-05	O/C	TSN 0					
SN:0727	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
284009	C9 FUEL PROBE ASSEMBLY							Component	ATA:28
PN:6628408000-027	MOS/MSC	22-Feb-06	O/C						
SN:7240	HRS	386.77							
	AFL	298							
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05									
284010	C10 FUEL PROBE ASSEMBLY							Component	ATA:28
PN:6628408000-005	MOS/MSC	10-May-05	O/C	TSN 0					
SN:0710	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05									
284011	C11 FUEL PROBE ASSEMBLY							Component	ATA:28
PN:6628408000-019	MOS/MSC	10-May-05	O/C	TSN 0					
SN:811	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05									
284012	C12 FUEL PROBE ASSEMBLY							Component	ATA:28
PN:6628408000-009	MOS/MSC	10-May-05	O/C	TSN 0					
SN:1039	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05									
284013	C13 FUEL PROBE ASSEMBLY							Component	ATA:28
PN:6628408000-011	MOS/MSC	10-May-05	O/C	TSN 0					
SN:1352	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05									
284014	C14 FUEL PROBE ASSEMBLY							Component	ATA:28
PN:6628408000-011	MOS/MSC	10-May-05	O/C	TSN 0					
SN:1351	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05									

?-Insufficient Information
 S-Suppressed Requirement
 *-Estimated Due(New Requirement)
 (EFF)-Effective C / W
 (M)-Manual Due
 U-User Task
 Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
284015	C15 FUEL PROBE ASSEMBLY							Component	ATA:28
PN:6628408000-021	MOS/MSC	10-May-05	O/C	TSN 0					
SN:0677	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05									
284016	C16 FUEL PROBE ASSEMBLY							Component	ATA:28
PN:6628408000-011	MOS/MSC	10-May-05	O/C	TSN 0					
SN:1356	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05									
284017	C17 FUEL PROBE ASSEMBLY							Component	ATA:28
PN:6628408000-021	MOS/MSC	10-May-05	O/C	TSN 0					
SN:0676	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05									
284033	FUSELAGE FUEL PROBE							Component	ATA:28
PN:6628408000-019	MOS/MSC	10-May-05	O/C	TSN 0					
SN:811	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05									
284045	FUEL QUANTITY SIGNAL CONDITIONER							Component	ATA:28
PN:10551B08Y09	MOS/MSC	07-Dec-13	O/C						
SN:B0676	HRS	5894.57							
	AFL	4812							
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05									
5-19-00-D2820013	PERFORM INITIAL CLEANING AND LEAK CHECK OF LOW PRESSURE FUEL FILTERS (IRN D2820013)							Service	ATA:28
	MOS/MSC	04-Aug-05	-						
	HRS	31.7							
	AFL	22							
PROC. REF: AMM 28-20-15PROC. REF: AMM 28-20-15									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
F2840003	^S	** FUEL QUANTITY SIGNAL CONDITIONER - PERFORM FUNCTIONAL TEST TO VERIFY WEIGHT-ON-WHEELS (WOW) INPUTS (AWL**)						Service	ATA:28
	MOS	13-Mar-26	48 (+14d/-14d)					AIRWORTHINESS	
	HRS	9596.2	1200 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 28-40-00PROC. REF: AMM 28-40-00									
Y2810001	^S	WING TANKS - REMOVE FUEL TANK ACCESS PANELS AND PERFORM VISUAL INSPECTION						Service	ATA:28
	MOS	13-Mar-26	24 (+14d/-14d)						
	HRS	9596.2	600 (+25/-25)						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
Y2810002	^S	WING TANKS - REMOVE FUEL TANK ACCESS PANELS AND PERFORM VISUAL INSPECTION.						Service	ATA:28
	MOS	13-Mar-26	96 (+14d/-14d)						
	HRS	9596.2	2400 (+25/-25)						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
Y2820000	^S	LOW PRESSURE FUEL FILTER - REMOVE AND INSPECT FOR CONTAMINATION. CLEAN IF NECESSARY						Service	ATA:28
	MOS	13-Mar-26	24 (+14d/-14d)						
	HRS	9596.2	600 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 28-20-15PROC. REF: AMM 28-20-15									
ATA 29 - HYDRAULIC POWER									
291013		HYDRAULIC FUEL SHUTOFF VALVE						Component	ATA:29
PN:6600355-2	MOS/MSC	10-May-05	O/C	TSN 0					
SN:04-1019160	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 29-10-05PROC. REF: AMM 29-10-05									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR
Serial: 45-2027
RegNo: N116PJ
HRS: 9841.3
AFL: 7790
As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 29 - HYDRAULIC POWER									
291033	PRESSURE CONTROL MODULE BOX							Component	ATA:29
PN:ZVM11-2	MOS/MSC	10-May-05	O/C	TSN 0					
SN:04-101135	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 29-10-06PROC. REF: AMM 29-10-06									
291034	RESERVOIR FLOAT SENSOR							Component	ATA:29
PN:3L14F-17	MOS/MSC	10-May-05	O/C	TSN 0					
SN:497	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 29-30-02PROC. REF: AMM 29-30-02									
291045	LH ENGINE DRIVEN HYDRAULIC PUMP							Component	ATA:29
PN:6629101000-001	MOS/MSC	10-May-05	O/C	TSN 0					
SN:MX683284A	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 29-10-01PROC. REF: AMM 29-10-01									
291046	RH ENGINE DRIVEN HYDRAULIC PUMP							Component	ATA:29
PN:6629101000-001	MOS/MSC	10-May-05	O/C	TSN 0					
SN:MX683286A	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 29-10-01PROC. REF: AMM 29-10-01									
291057	MAIN HYDRAULIC SYSTEM ACCUMULATOR							Component	ATA:29
PN:88746-1	MOS/MSC	10-May-05	O/C	TSN 0					
SN:313	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 29-10-04PROC. REF: AMM 29-10-04									
291059	MAIN HYDRAULIC FILTER MANIFOLD ASSEMBLY							Component	ATA:29
PN:2247H000-004	MOS/MSC	27-Mar-15	O/C	TSR 0					
SN:1583	HRS	6705.27		TSR 0					
	AFL	5447		TSR 0					
PROC. REF: AMM 29-10-03PROC. REF: AMM 29-10-03									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 29 - HYDRAULIC POWER									
291069	THERMAL SHUTOFF VALVE							Component	ATA:29
PN:98050	MOS/MSC	10-May-05	O/C	TSN 0					
SN:0513	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 29-10-07PROC. REF: AMM 29-10-07									
292010 ^U	PUMP DC MOTOR							Component	ATA:29
PN:24470	MOS/MSC	21-Jul-26	O/C	TSN 0					
SN:ELE0518A	HRS	9794.8		TSN 0					
	AFL	7756		TSN 0					
292011	AUXILIARY HYDRAULIC PUMP ASSEMBLY							Component	ATA:29
PN:6629201000-013	MOS/MSC	29-May-14	O/C						
SN:K0304	HRS								
	AFL								
PROC. REF: AMM 29-20-01PROC. REF: AMM 29-20-01									
293011	HYDRAULIC PRESSURE TRANSDUCER							Component	ATA:29
PN:7629301001-001	MOS/MSC	10-May-05	O/C	TSN 0					
SN:7052-2-50	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 29-30-04PROC. REF: AMM 29-30-04									
293012	PRESSURE TRANSDUCER							Component	ATA:29
PN:7629301001-001	MOS/MSC	10-May-05	O/C	TSN 0					
SN:7052-2-48	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 29-30-04PROC. REF: AMM 29-30-04									
293021	HYDRAULIC GROUND SERVICE CONTROL BOX							Component	ATA:29
PN:4529308000V9-001	MOS/MSC	10-May-05	O/C	TSN 0					
SN:A5050	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 29-30-01PROC. REF: AMM 29-30-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR
Serial: 45-2027
RegNo: N116PJ
HRS: 9841.3
AFL: 7790
As Of: 14-Sep-2026
15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 29 - HYDRAULIC POWER									
5-19-01-D2910017	REPLACE MAIN HYDRAULIC FILTER MANIFOLD ELEMENTS (IRN D2910017)								Service ATA:29
	MOS/MSC	04-Aug-05	-						
	HRS	31.7							
	AFL	22							
PROC. REF: AMM 29-10-03PROC. REF: AMM 29-10-03									
5-19-01-D2910018	REPLACE MAIN HYDRAULIC FILTER MANIFOLD ELEMENTS (IRN D2910018)								Service ATA:29
	MOS	13-Mar-26							
	HRS	9596.2	300 (+25/-25)		9896.2	9921.2	54.9 (+25)		
	AFL	7624							
PROC. REF: AMM 29-10-03PROC. REF: AMM 29-10-03									
5-19-01-O2910005	REPLACE AUXILIARY HYDRAULIC FILTER MANIFOLD ELEMENTS (IRN O2910005)								Service ATA:29
	MOS	10-May-23							
	HRS	9071.3	2400 (+25/-25)	Adj -2.03	11469.27	11494.27	1628 (+25)		
	AFL	7252							
PROC. REF: AMM 29-20-02PROC. REF: AMM 29-20-02									
T2910026 ^S	RELIEF FUNCTION OF THE HYDRAULIC RESERVOIR PRESSURIZATION CONTROL MODULE - PERFORM FUNCTIONALTEST								Service ATA:29
	MOS	13-Mar-26	48 (+14d/-14d)						
	HRS	9596.2	1200 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 29-10-06PROC. REF: AMM 29-10-06									PKG:14
Y2910001 ^S	HYDRAULIC COMPONENTS AND ASSOCIATED PLUMBING (AFT OF FUSELAGE FUEL CELL, FS 495 TO FS 512) - PERFORM VISUAL INSPECTION								Service ATA:29
	MOS	13-Mar-26	48 (+14d/-14d)						
	HRS	9596.2	1200 (+25/-25)						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:14

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C / W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 40XR
Serial: 45-2027
RegNo: N116PJ
HRS: 9841.3
AFL: 7790
As Of: 14-Sep-2026
15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 29 - HYDRAULIC POWER									
Y2910002	^S	HYDRAULIC COMPONENTS AND ASSOCIATED PLUMBING (WHEEL WELL AND FORWARD AREA OF REAR SPAR) - PERFORM VISUAL INSPECTION.						Service	ATA:29
	MOS	13-Mar-26	48 (+14d/-14d)						
	HRS	9596.2	1200 (+25/-25)						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:17
Y2910003	^S	HYDRAULIC COMPONENTS AND ASSOCIATED PLUMBING (AFT AREA OF REAR SPAR) - PERFORM VISUAL INSPECTION						Service	ATA:29
	MOS	13-Mar-26	96 (+14d/-14d)						
	HRS	9596.2	2400 (+25/-25)						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:19
Y2920001	^S	AUXILIARY HYDRAULIC SYSTEM - PERFORM OPERATIONAL CHECK						Service	ATA:29
	MOS	13-Mar-26	48 (+14d/-14d)						
	HRS	9596.2	1200 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 29-20-00PROC. REF: AMM 29-20-00									PKG:13
ATA 30 - ICE AND RAIN PROTECTION									
301063		LH PRESS REG/MOD SHUTOFF VALVE						Component	ATA:30
PN:6621000000-087	MOS/MSC	10-May-05	O/C	TSN 0					
SN:839	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-10-01PROC. REF: AMM 30-10-01									
301064		RH PRESS REG/MOD SHUTOFF VALVE						Component	ATA:30
PN:6621000000-087	MOS/MSC	10-May-05	O/C	TSN 0					
SN:845	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-10-01PROC. REF: AMM 30-10-01									

? - Insufficient Information
S - Suppressed Requirement
* - Estimated Due(New Requirement)
(EFF) - Effective C / W
(M) - Manual Due
U - User Task
Ex - Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 30 - ICE AND RAIN PROTECTION									
304021	WINDSHIELD ANTI-ICE CONTROLLER							Component	ATA:30
PN:90825-9	MOS/MSC	30-Jun-17	O/C						
SN:267	HRS	7012.8							
	AFL	5698							
PROC. REF: AMM 30-40-01PROC. REF: AMM 30-40-01									
308006	ICE DETECT PROBE							Component	ATA:30
PN:0871HN2	MOS/MSC	10-May-05	O/C	TSN 0					
SN:0329	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-80-01PROC. REF: AMM 30-80-01									
5-19-00-AC3010006	** ANTI-ICE MANIFOLD ASSEMBLY - PERFORM BORESCOPE INSPECTION (AWL**)							Service	ATA:30
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	600 (+25/-25)		10196.2	10221.2	354.9 (+25)		
	AFL	7624							
PROC. REF: AMM 30-10-07PROC. REF: AMM 30-10-07									
5-19-00-Z3020005-LEFT	LEFT * ENGINE INLET ANTI-ICE TUBE ASSEMBLY FROM THE AFT INLET BULKHEAD CONNECTION POINT FORWARD TO SPRAY RING CONNECTION, PERFORM DETAILED VISUAL/BORESCOPE INSPECTION OF THE WELDS INSIDE AND OUTSIDE OF THE TUBE AT BOTH FORWARD AND AFT ENDS. (AWL*)							Service	ATA:30
	MOS	17-Aug-26						AIRWORTHINESS	
	HRS	9818.6	250		10068.6		227.3		
	AFL	7772							
PROC. REF: AMM 30-20-00PROC. REF: AMM 30-20-00									
5-19-00-Z3020005-RIGHT	RIGHT * ENGINE INLET ANTI-ICE TUBE ASSEMBLY FROM THE AFT INLET BULKHEAD CONNECTION POINT FORWARD TO SPRAY RING CONNECTION, PERFORM DETAILED VISUAL/BORESCOPE INSPECTION OF THE WELDS INSIDE AND OUTSIDE OF THE TUBE AT BOTH FORWARD AND AFT ENDS. (AWL*)							Service	ATA:30
	MOS	17-Aug-26						AIRWORTHINESS	
	HRS	9818.6	250		10068.6		227.3		
	AFL	7772							
PROC. REF: AMM 30-20-00PROC. REF: AMM 30-20-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR
Serial: 45-2027
RegNo: N116PJ
HRS: 9841.3
AFL: 7790
As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 30 - ICE AND RAIN PROTECTION									
5-19-00-Z3020006-LEFT	LEFT ENGINE INLET ANTI-ICE TUBE ASSEMBLY FROM THE AFT INLET BULKHEAD CONNECTION POINT FORWARD TO SPRAY RING CONNECTION, PERFORM DETAILED VISUAL/BORESCOPE INSPECTION OF THE WELDS INSIDE AND OUTSIDE OF THE TUBE AT BOTH FORWARD AND AFT ENDS.							Service	ATA:30
	MOS/MSC	10-May-05	N/A						
	HRS	0							
	AFL	0							
	PROC. REF: AMM 30-20-00PROC. REF: AMM 30-20-00								
5-19-00-Z3020006-RIGHT	RIGHT ENGINE INLET ANTI-ICE TUBE ASSEMBLY FROM THE AFT INLET BULKHEAD CONNECTION POINT FORWARD TO SPRAY RING CONNECTION, PERFORM DETAILED VISUAL/BORESCOPE INSPECTION OF THE WELDS INSIDE AND OUTSIDE OF THE TUBE AT BOTH FORWARD AND AFT ENDS							Service	ATA:30
	MOS/MSC	10-May-05	N/A						
	HRS	0							
	AFL	0							
	PROC. REF: AMM 30-20-00PROC. REF: AMM 30-20-00								
A3020000 ^S	** NACELLE ANTI-ICE SYSTEM - PERFORM FUNCTIONAL TEST (AWL**)							Service	ATA:30
	MOS	13-Mar-26	48 (+14d/-14d)					AIRWORTHINESS	
	HRS	9596.2	1200 (+25/-25)						
	AFL	7624							
	PROC. REF: AMM 30-20-00PROC. REF: AMM 30-20-00								
A3030000 ^S	** PITOT-STATIC HEAT SYSTEM - PERFORM OPERATIONAL CHECK (AWL**)							Service	ATA:30
	MOS	13-Mar-26	96 (+14d/-14d)					AIRWORTHINESS	
	HRS	9596.2	2400 (+25/-25)						
	AFL	7624							
	PROC. REF: AMM 30-30-00PROC. REF: AMM 30-30-00								
H3010000 ^S	** WING/STAB ANTI-ICE SWITCH - PERFORM OPERATIONAL CHECK (AWL**)							Service	ATA:30
	MOS	13-Mar-26	24 (+14d/-14d)					AIRWORTHINESS	
	HRS	9596.2	600 (+25/-25)						
	AFL	7624							
	PROC. REF: AMM 30-10-00PROC. REF: AMM 30-10-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 30 - ICE AND RAIN PROTECTION									
T3040000	S	** PERFORM FUNCTIONAL TEST OF THE WINDSHIELD ANTI-ICE SYSTEM. (AWL**)						Service	ATA:30
	MOS	13-Mar-26	24 (+14d/-14d)					AIRWORTHINESS	
	HRS	9596.2	600 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 30-40-00PROC. REF: AMM 30-40-00									PKG:7
Y3010007	S	WING ANTI-ICE PICCOLO TUBE - PERFORM DETAILED VISUAL INSPECTION FOR CRACKS AT W.S. 43 AND W.S. 176.						Service	ATA:30
	MOS	13-Mar-26	24 (+14d/-14d)						
	HRS	9596.2	600 (+25/-25)						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:10
Y3080000	S	ICE DETECTION SYSTEM - PERFORM FUNCTIONAL TEST						Service	ATA:30
	MOS	13-Mar-26	48 (+14d/-14d)						
	HRS	9596.2	1200 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 30-80-00PROC. REF: AMM 30-80-00									PKG:13
ATA 31 - INDICATING/RECORDING SYSTEMS									
311607	CENTER SWITCH PANEL							Component	ATA:31
PN:M4525188576-041-641	MOS/MSC	10-May-05	O/C	TSN 0					
SN:MAN147556	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 31-11-03PROC. REF: AMM 31-11-03									
311805	ENGINE FUEL CONTROL PANEL							Component	ATA:31
PN:4576108500-025	MOS/MSC	16-May-22	O/C						
SN:A00381795-01	HRS	8777.4							
	AFL	7052							
PROC. REF: AMM 31-11-05PROC. REF: AMM 31-11-05									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 31 - INDICATING/RECORDING SYSTEMS									
312001	PILOT CLOCK								Component ATA:31
PN:M850	MOS/MSC	24-Sep-21	O/C	TSN 0					
SN:A8274	HRS	8457.7		TSN 0					
	AFL	6804		TSN 0					
PROC. REF: AMM 31-21-01PROC. REF: AMM 31-21-01									
312002	COPILOT CLOCK								Component ATA:31
PN:M850-5V-LA	MOS/MSC	29-Nov-14	O/C						
SN:A3472	HRS	6566.75							
	AFL	5343							
PROC. REF: AMM 31-21-01PROC. REF: AMM 31-21-01									
312011	REPLACE PILOT DIGITAL CLOCK BATTERY								Component ATA:31
PN:DURACELL N	MOS	13-Mar-26	12 (+14d/-14d)	TSN 0	13-Mar-27	27-Mar-27	179 d (+14)		
SN:N/A	HRS	9596.2		TSN 0					
	AFL	7624		TSN 0					
PROC. REF: AMM 31-21-02PROC. REF: AMM 31-21-02									
312012	REPLACE COPILOT DIGITAL CLOCK BATTERY								Component ATA:31
PN:DURACELL N	MOS	13-Mar-26	12 (+14d/-14d)	TSN 0	13-Mar-27	27-Mar-27	179 d (+14)		
SN:N/A	HRS	9596.2		TSN 0					
	AFL	7624		TSN 0					
PROC. REF: AMM 31-21-02PROC. REF: AMM 31-21-02									
314001	SELCAL DECODER								Component ATA:31
PN:1200006-102	MOS/MSC	18-Jul-05	O/C	TSN 0					
SN:1675	HRS	18.9		TSN 0					
	AFL	15		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
314011	NO. 1 DATA ACQUISITION UNIT								Component ATA:31
PN:7013348-938	MOS/MSC	26-Jul-24	O/C						
SN:01084576	HRS	9450.9							
	AFL	7531							
PROC. REF: AMM 31-42-01PROC. REF: AMM 31-42-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR
 Serial: 45-2027
 RegNo: N116PJ
 HRS: 9841.3
 AFL: 7790
 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 31 - INDICATING/RECORDING SYSTEMS									
314012	NO. 2 DATA ACQUISITION UNIT							Component	ATA:31
PN:7013348-938	MOS/MSC	26-Jul-24	O/C						
SN:06056251	HRS	9450.9							
	AFL	7531							
PROC. REF: AMM 31-42-01PROC. REF: AMM 31-42-01									
314023	NO. 1 IC-600 INTEGRATED AVIONICS COMPUTER							Component	ATA:31
PN:7017000-82222	MOS/MSC	30-Mar-22	O/C						
SN:06077657	HRS	8750.5							
	AFL	7031							
PROC. REF: AMM 31-41-01PROC. REF: AMM 31-41-01									
314024	NO. 2 IC-600 INTEGRATED AVIONICS COMPUTER							Component	ATA:31
PN:7017000-82222	MOS/MSC	10-May-05	O/C	TSN 0					
SN:00012987	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 31-41-01PROC. REF: AMM 31-41-01									
314051	LH IM-600 MEMORY MODULE							Component	ATA:31
PN:7025973-04214	MOS/MSC	01-Dec-05	O/C	TSN 0					
SN:05013483	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 31-41-02PROC. REF: AMM 31-41-02									
314052	RH IM-600 MEMORY MODULE							Component	ATA:31
PN:7025973-04214	MOS/MSC	01-Dec-05	O/C	TSN 0					
SN:05013484	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 31-41-02PROC. REF: AMM 31-41-02									
315001	CREW WARNING PANEL							Component	ATA:31
PN:90-42801-8	MOS/MSC	10-May-05	O/C	TSN 0					
SN:387	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 31-51-01PROC. REF: AMM 31-51-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 31 - INDICATING/RECORDING SYSTEMS									
316025	PILOT EFIS DISPLAY CONTROLLER							Component	ATA:31
PN:7016986-733	MOS/MSC	10-May-05	O/C	TSN 0					
SN:05015778	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 31-60-02PROC. REF: AMM 31-60-02									
316026	COPILOT EFIS DISPLAY CONTROLLER							Component	ATA:31
PN:7016986-733	MOS/MSC	10-May-05	O/C	TSN 0					
SN:05015779	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 31-60-02PROC. REF: AMM 31-60-02									
B3100000 ^S	** INDICATING/RECORDING SYSTEM - PERFORM OPERATIONAL CHECK (AWL**)							Service	ATA:31
	MOS	13-Mar-26	24 (+14d/-14d)					AIRWORTHINESS	
	HRS	9596.2	600 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 31-00-00PROC. REF: AMM 31-00-00									
PKG:7									
ATA 32 - LANDING GEAR									
320041	* LEFT UPPER MAIN LANDING GEAR LINK PIN (IRN N3220101) (AWL*)							Component	ATA:32
PN:200-0214-101	MOS	14-Dec-05		TSN 0				LIFE LIMIT	
SN:NSN	HRS	2600.03		TSN 0					
	AFL	2143	10000	TSN 2143	10000		2210		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
320042	* RIGHT UPPER MAIN LANDING GEAR LINK PIN (IRN N3220101) (AWL*)							Component	ATA:32
PN:200-0214-101	MOS	14-Dec-05		TSN 0				LIFE LIMIT	
SN:NSN	HRS	2600.03		TSN 0					
	AFL	2143	10000	TSN 2143	10000		2210		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
320043	* LEFT LOWER MAIN LANDING GEAR LINK PIN (IRN N3220101) (AWL*)							Component	ATA:32
PN:200-0204-001	MOS	14-Dec-05		TSN 0				LIFE LIMIT	
SN:NSN	HRS	2600.03		TSN 0					
	AFL	2143	10000	TSN 2143	10000		2210		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR
Serial: 45-2027
RegNo: N116PJ
HRS: 9841.3
AFL: 7790
As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
320044	* RIGHT LOWER MAIN LANDING GEAR LINK PIN (IRN N3220101) (AWL*)							Component	ATA:32
PN:200-0204-001	MOS	14-Dec-05		TSN 0				LIFE LIMIT	
SN:NSN	HRS	2600.03		TSN 0					
	AFL	2143	10000	TSN 2143	10000		2210		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
320051	LEFT * MAIN LANDING GEAR PISTON PIN (IRN N3220102) (AWL*)							Component	ATA:32
PN:200-0215-101	MOS	14-Dec-05		TSN 0				LIFE LIMIT	
SN:NSN	HRS	2600.03		TSN 0					
	AFL	2143	10000	TSN 2143	10000		2210		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
320052	RIGHT * MAIN LANDING GEAR PISTON PIN (IRN N3220102) (AWL*)							Component	ATA:32
PN:200-0215-101	MOS	14-Dec-05		TSN 0				LIFE LIMIT	
SN:NSN	HRS	2600.03		TSN 0					
	AFL	2143	10000	TSN 2143	10000		2210		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
320061	* LEFT MAIN LANDING GEAR ACTUATOR PISTON (IRN N3220103). (AWL*)							Component	ATA:32
PN:200-0301-103	MOS	15-Nov-10		TSN 0				LIFE LIMIT	
SN:NSN	HRS	0		TSN 0					
	AFL	0	17000	TSN 0	17000		9210		
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01									
320062	* RIGHT MAIN LANDING GEAR ACTUATOR PISTON (IRN N3220103). (AWL*)							Component	ATA:32
PN:200-0301-103	MOS	15-Nov-10		TSN 0				LIFE LIMIT	
SN:NSN	HRS	0		TSN 0					
	AFL	0	17000	TSN 0	17000		9210		
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01									
320071	* LEFT MAIN LANDING GEAR ACTUATOR CYLINDER (IRN N3220104) (AWL*)							Component	ATA:32
PN:200-0302-101	MOS	15-Nov-10		TSN 0				LIFE LIMIT	
SN:NSN	HRS	0		TSN 0					
	AFL	0	17000	TSN 0	17000		9210		
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01									

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C / W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
320072	* RIGHT MAIN LANDING GEAR ACTUATOR CYLINDER (IRN N3220104) (AWL*)							Component	ATA:32
PN:200-0302-101	MOS	15-Nov-10		TSN 0				LIFE LIMIT	
SN:NSN	HRS	0		TSN 0					
	AFL	0	17000	TSN 0	17000		9210		
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01									
320081	* LEFT MAIN LANDING GEAR ACTUATOR END CAP (IRN T3220105) (AWL*)							Component	ATA:32
PN:200-0072-001	MOS	13-Mar-26		TSN 0				LIFE LIMIT	
SN:N/A	HRS	9596.2		TSN 0					
	AFL	7624	2387	TSN 0	10011		2221		
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01									
320082	* RIGHT MAIN LANDING GEAR ACTUATOR END CAP (IRN T3220105) (AWL*)							Component	ATA:32
PN:200-0303-001	MOS	25-Jan-15						LIFE LIMIT	
SN:H2458	HRS	6669.27							
	AFL	5419	2387	TSN 0	7806		16		
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01									
320091	* LEFT MAIN LANDING GEAR ACTUATOR HOUSING (IRN N3220106) (AWL*)							Component	ATA:32
PN:200-0304-001	MOS	15-Nov-10		TSN 0				LIFE LIMIT	
SN:NSN	HRS	0		TSN 0					
	AFL	0	17000	TSN 0	17000		9210		
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01									
320092	* RIGHT MAIN LANDING GEAR ACTUATOR HOUSING (IRN N3220106) (AWL*)							Component	ATA:32
PN:200-0304-001	MOS	15-Nov-10		TSN 0				LIFE LIMIT	
SN:NSN	HRS	0		TSN 0					
	AFL	0	17000	TSN 0	17000		9210		
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01									
321001	* LEFT MAIN LANDING GEAR STRUT ASSEMBLY (IRN N3220012) (AWL*)							Component	ATA:32
PN:200-0200-011	MOS	10-May-23		TSN 216				LIFE LIMIT	
SN:H0319	HRS	9071.3		TSN 9071.3					
	AFL	7252	10000	TSN 7252	10000		2210		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
321001A	LEFT MAIN LANDING GEAR STRUT ASSEMBLY - SPECIAL DETAILED INSPECTION (IRN AA3220018)								Service ATA:32
PN:200-0200-011	MOS	10-May-23	96 (+14d/-14d)		10-May-31	24-May-31	1698 d (+14)		
SN:H0319	HRS	9071.3							
	AFL	7252	6600 (+25/-25)		13852	13877	6062 (+25)		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
321002	* RIGHT MAIN LANDING GEAR STRUT ASSEMBLY (IRN N3220012) (AWL*)								Component ATA:32
PN:200-0200-012	MOS	10-May-23		TSN 216				LIFE LIMIT	
SN:H1323	HRS	9071.3		TSN 9071.3					
	AFL	7252	10000	TSN 7252	10000		2210		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
321002A	RIGHT MAIN LANDING GEAR STRUT ASSEMBLY - SPECIAL DETAILED INSPECTION (IRN AA3220018)								Service ATA:32
PN:200-0200-012	MOS	10-May-23	96 (+14d/-14d)		10-May-31	24-May-31	1698 d (+14)		
SN:H1323	HRS	9071.3							
	AFL	7252	6600 (+25/-25)		13852	13877	6062 (+25)		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
321011	* REPLACE LEFT MAIN LANDING GEAR SHOCK STRUT CYLINDER (IRN N3220116) (AWL*)								Component ATA:32
PN:200-0201-005	MOS	14-Dec-05		TSN 0				LIFE LIMIT	
SN:NSN	HRS	0		TSN 0					
	AFL	0	10000	TSN 0	10000		2210		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
321012	* REPLACE RIGHT MAIN LANDING GEAR SHOCK STRUT CYLINDER (IRN N3220116) (AWL*)								Component ATA:32
PN:200-0201-006	MOS	14-Dec-05		TSN 0				LIFE LIMIT	
SN:NSN	HRS	0		TSN 0					
	AFL	0	10000	TSN 0	10000		2210		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
321025	LEFT * MAIN LANDING GEAR SIDE STAY ACTUATOR UPPER PIN (P/N 200-0325). (IRN T3220014). (AWL*)								Component ATA:32
PN:200-0235-101	MOS	21-Apr-26	96	TSN 48	21-Apr-30		1314 d	LIFE LIMIT	
SN:TUR16718	HRS	9655							
	AFL	7666							
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
321025A		* LEFT UPPER MAIN LANDING GEAR SIDE-STAY ACTUATOR PINS - PERFORM MAGNETIC PARTICLE INSPECTION (IRN T3220024) (AWL*)						Service	ATA:32
PN:200-0235-101	MOS	21-Apr-26	48		21-Apr-30		1314 d	AIRWORTHINESS	
SN:TUR16718	HRS	9655							
	AFL	7666							
PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01									
321025B		* LEFT UPPER MAIN LANDING GEAR SIDE-STAY ACTUATOR PINS - PERFORM DETAILED VISUAL INSPECTION (IRN T3220135) (AWL*)						Service	ATA:32
PN:200-0235-101	MOS	21-Apr-26	48		21-Apr-30		1314 d	AIRWORTHINESS	
SN:TUR16718	HRS	9655							
	AFL	7666							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
321026		RIGHT * MAIN LANDING GEAR SIDE STAY ACTUATOR UPPER PIN (P/N 200-0325). (IRN T3220014) (AWL*)						Component	ATA:32
PN:200-0235-101	MOS	21-Apr-26	96	TSN 48	21-Apr-30		1314 d	LIFE LIMIT	
SN:TUR16713	HRS	9655							
	AFL	7666							
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01									
321026A		* RIGHT UPPER MAIN LANDING GEAR SIDE-STAY ACTUATOR PINS - PERFORM MAGNETIC PARTICLE INSPECTION (IRN T3220024) (AWL*)						Service	ATA:32
PN:200-0235-101	MOS	21-Apr-26	48		21-Apr-30		1314 d	AIRWORTHINESS	
SN:TUR16713	HRS	9655							
	AFL	7666							
PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01									
321026B		* RIGHT UPPER MAIN LANDING GEAR SIDE-STAY ACTUATOR PINS - PERFORM DETAILED VISUAL INSPECTION (IRN T3220135) (AWL*)						Service	ATA:32
PN:200-0235-101	MOS	21-Apr-26	48		21-Apr-30		1314 d	AIRWORTHINESS	
SN:TUR16713	HRS	9655							
	AFL	7666							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
321037		LEFT * MAIN LANDING GEAR SIDE STAY ACTUATOR LOWER PIN (P/N 200-0217). (IRN T3220038) (AWL*)						Component	ATA:32
PN:200-0217-101	MOS	21-Apr-26	96	TSN 48	21-Apr-30		1314 d	LIFE LIMIT	
SN:CPS01C-4066	HRS	9655							
	AFL	7666							
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
321037A		* LEFT LOWER MAIN LANDING GEAR SIDE-STAY ACTUATOR PINS - PERFORM MAGNETIC PARTICLE INSPECTION (IRN T3220024) (AWL*)						Service	ATA:32
PN:200-0217-101	MOS	21-Apr-26	48		21-Apr-30		1314 d	AIRWORTHINESS	
SN:CPS01C-4066	HRS	9655							
	AFL	7666							
PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01									
321037B		* LEFT LOWER MAIN LANDING GEAR SIDE-STAY ACTUATOR PINS - PERFORM DETAILED VISUAL INSPECTION (IRN T3220135) (AWL*)						Service	ATA:32
PN:200-0217-101	MOS	21-Apr-26	48		21-Apr-30		1314 d	AIRWORTHINESS	
SN:CPS01C-4066	HRS	9655							
	AFL	7666							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
321038		RIGHT * MAIN LANDING GEAR SIDE STAY ACTUATOR LOWER PIN (P/N 200-0217). (IRN T3220038) (AWL*)						Component	ATA:32
PN:200-0217-101	MOS	21-Apr-26	96	TSN 48	21-Apr-30		1314 d	LIFE LIMIT	
SN:CPS01C-4068	HRS	9655							
	AFL	7666							
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01									
321038A		* RIGHT LOWER MAIN LANDING GEAR SIDE-STAY ACTUATOR PINS - PERFORM MAGNETIC PARTICLE INSPECTION (IRN T3220024) (AWL*)						Service	ATA:32
PN:200-0217-101	MOS	21-Apr-26	48		21-Apr-30		1314 d	AIRWORTHINESS	
SN:CPS01C-4068	HRS	9655							
	AFL	7666							
PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01									
321038B		* RIGHT LOWER MAIN LANDING GEAR SIDE-STAY ACTUATOR PINS - PERFORM DETAILED VISUAL INSPECTION (IRN T3220135) (AWL*)						Service	ATA:32
PN:200-0217-101	MOS	21-Apr-26	48		21-Apr-30		1314 d	AIRWORTHINESS	
SN:CPS01C-4068	HRS	9655							
	AFL	7666							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
321049		LEFT * MAIN LANDING GEAR AXLE BEAM (IRN N3220036) (AWL*)						Component	ATA:32
PN:200-0203-001	MOS	14-Dec-05						LIFE LIMIT	
SN:H0726	HRS	2600.03							
	AFL	2143	10000	TSN 2143	10000		2210		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
321050	RIGHT * MAIN LANDING GEAR AXLE BEAM (IRN N3220036) (AWL*)							Component	ATA:32
PN:200-0203-001	MOS	14-Dec-05						LIFE LIMIT	
SN:H0722	HRS	2600.03							
	AFL	2143	10000	TSN 2143	10000		2210		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
321085	L/H FWD MAIN LANDING GEAR TRUNNION BREAKOUT BLK ASSEMBLY							Component	ATA:32
PN:4532103011-009	MOS/MSC	10-May-05	O/C	TSN 0					
SN:CYC064	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
321086	R/H FWD MAIN LANDING GEAR TRUNNION BREAKOUT BLK ASSEMBLY							Component	ATA:32
PN:4532103011-010	MOS/MSC	10-May-05	O/C	TSN 0					
SN:CYC061	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
321087	LH AFT MAIN LANDING GEAR TRUNNION BREAKOUT BLK ASSEMBLY							Component	ATA:32
PN:4532103021-007	MOS/MSC	10-May-05	O/C	TSN 0					
SN:CYC053	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
321088	RIGHT AFT MAIN LANDING GEAR TRUNNION BREAKOUT BLK ASSEMBLY							Component	ATA:32
PN:4532103021-008	MOS/MSC	10-May-05	O/C	TSN 0					
SN:CYC049	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
321101	LEFT FORWARD * MAIN LANDING GEAR TRUNNION PIN (IRN N3220023) (AWL*)							Component	ATA:32
PN:200-0212-103	MOS	10-May-05		TSN 0				LIFE LIMIT	
SN:H0895	HRS	0		TSN 0					
	AFL	0	10000	TSN 0	10000		2210		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									

?-Insufficient Information

S-Suppressed Requirement

*-Estimated Due(New Requirement)

(EFF)-Effective C / W

(M)-Manual Due

U-User Task

Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
321102	RIGHT FORWARD * MAIN LANDING GEAR TRUNNION PIN (IRN N3220023) (AWL*)							Component	ATA:32
PN:200-0212-103	MOS	10-May-05		TSN 0				LIFE LIMIT	
SN:H0894	HRS	0		TSN 0					
	AFL	0	10000	TSN 0	10000		2210		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
321103	LEFT AFT * MAIN LANDING GEAR TRUNNION PIN (IRN N3220023) (AWL*)							Component	ATA:32
PN:200-0213-103	MOS	10-May-05		TSN 0				LIFE LIMIT	
SN:H0676	HRS	0		TSN 0					
	AFL	0	10000	TSN 0	10000		2210		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
321104	RIGHT AFT * MAIN LANDING GEAR TRUNNION PIN (IRN N3220023) (AWL*)							Component	ATA:32
PN:200-0213-103	MOS	10-May-05		TSN 0				LIFE LIMIT	
SN:H0684	HRS	0		TSN 0					
	AFL	0	10000	TSN 0	10000		2210		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
321111	LEFT FORWARD LOWER * MAIN LANDING GEAR TRUNNION SHEAR PIN (AWL*)							Component	ATA:32
PN:4532103201-001	MOS	26-Oct-14						LIFE LIMIT	
SN:1174	HRS	6496.17							
	AFL	5289	5000	TSN 0	10289		2499		
PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05									
321112	RIGHT FORWARD LOWER * MAIN LANDING GEAR TRUNNION SHEAR PIN (AWL*)							Component	ATA:32
PN:4532103201-001	MOS	26-Oct-14						LIFE LIMIT	
SN:CM11418	HRS	6496.17							
	AFL	5289	5000	TSN 0	10289		2499		
PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05									
321113	LEFT FORWARD UPPER * MAIN LANDING GEAR TRUNNION SHEAR PIN (AWL*)							Component	ATA:32
PN:4532103201-001	MOS	26-Oct-14						LIFE LIMIT	
SN:CM11440	HRS	6496.17							
	AFL	5289	5000	TSN 0	10289		2499		
PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
321114	RIGHT FORWARD UPPER * MAIN LANDING GEAR TRUNNION SHEAR PIN (AWL*)							Component	ATA:32
PN:4532103201-001	MOS	26-Oct-14						LIFE LIMIT	
SN:CM11433	HRS	6496.17							
	AFL	5289	5000	TSN 0	10289		2499		
PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05									
321117	LEFT AFT UPPER * MAIN LANDING GEAR TRUNNION SHEAR PIN (AWL*)							Component	ATA:32
PN:4532103202-001	MOS	11-Mar-22		TSN 0				LIFE LIMIT	
SN:CM11350	HRS	8721.2		TSN 0					
	AFL	7006	1800	TSN 0	8806		1016		
PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05									
321118	RIGHT AFT UPPER * MAIN LANDING GEAR TRUNNION SHEAR PIN (AWL*)							Component	ATA:32
PN:4532103202-001	MOS	11-Mar-22		TSN 0				LIFE LIMIT	
SN:CM11263	HRS	8721.2		TSN 0					
	AFL	7006	1800	TSN 0	8806		1016		
PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05									
321119	LEFT AFT LOWER * MAIN LANDING GEAR TRUNNION SHEAR PIN (AWL*)							Component	ATA:32
PN:4532103203-001	MOS	11-Mar-22		TSN 0				LIFE LIMIT	
SN:CM11501	HRS	8721.2		TSN 0					
	AFL	7006	1800	TSN 0	8806		1016		
PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05									
321120	RIGHT AFT LOWER * MAIN LANDING GEAR TRUNNION SHEAR PIN (AWL*)							Component	ATA:32
PN:4532103203-001	MOS	11-Mar-22		TSN 0				LIFE LIMIT	
SN:CM11509	HRS	8721.2		TSN 0					
	AFL	7006	1800	TSN 0	8806		1016		
PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05									
321215	LEFT * MAIN LANDING GEAR SHOCK STRUT PISTON (IRN N3220035) (AWL*)							Component	ATA:32
PN:200-0202-101	MOS	10-May-05		TSN 0				LIFE LIMIT	
SN:H0236	HRS	0		TSN 0					
	AFL	0	10000	TSN 0	10000		2210		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
321216	RIGHT * MAIN LANDING GEAR SHOCK STRUT PISTON (IRN N3220035) (AWL*)							Component	ATA:32
PN:200-0202-101	MOS	10-May-05		TSN 0				LIFE LIMIT	
SN:H0819	HRS	0		TSN 0					
	AFL	0	10000	TSN 0	10000		2210		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
321227	* LEFT MAIN LANDING GEAR SHOCK STRUT LINK (IRN N3220037) (AWL*)							Component	ATA:32
PN:200-0204-101	MOS	10-May-05		TSN 0				LIFE LIMIT	
SN:H0705	HRS	0		TSN 0					
	AFL	0	10000	TSN 0	10000		2210		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
321228	* RIGHT MAIN LANDING GEAR SHOCK STRUT LINK (IRN N3220037) (AWL*)							Component	ATA:32
PN:200-0204-101	MOS	10-May-05		TSN 0				LIFE LIMIT	
SN:H0671	HRS	0		TSN 0					
	AFL	0	10000	TSN 0	10000		2210		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
322001	* NOSE LANDING GEAR STRUT ASSEMBLY (IRN O3220009) (AWL*)							Component	ATA:32
PN:4532240001-817	MOS	27-May-24						LIFE LIMIT	
SN:398	HRS	9381.4		TSN 9381.4					
	AFL	7483	20000	TSN 7483	20000		12210		
PROC. REF: AMM 32-20-01PROC. REF: AMM 32-20-01									
322002	NOSE LANDING GEAR CYLINDER							Component	ATA:32
PN:2342102	MOS/MSC	10-May-05	O/C	TSN 0					
SN:T363	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
322003	NOSE LANDING GEAR PISTON							Component	ATA:32
PN:2342104	MOS/MSC	10-May-05	O/C	TSN 0					
SN:F042	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
322004	NOSE LANDING GEAR ASSEMBLY BRACKET							Component	ATA:32
PN:2342111	MOS/MSC	10-May-05	O/C	TSN 0					
SN:R224	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
322005	NOSE LANDING GEAR FORK							Component	ATA:32
PN:2342116	MOS/MSC	10-May-05	O/C	TSN 0					
SN:R378	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
322011	* NOSE LANDING GEAR ACTUATOR (P/N 6632201000) (IRN O3220010) (AWL*)							Component	ATA:32
PN:6632201000-005	MOS	10-May-05		TSN 0				LIFE LIMIT	
SN:EFS378	HRS	0		TSN 0					
	AFL	0	20000	TSN 0	20000		12210		
PROC. REF: AMM 32-32-01PROC. REF: AMM 32-32-01									
3220147	LEFT FORWARD LOWER * MAIN LANDING GEAR TRUNNION SHEAR PINS - PERFORM VISUAL INPECTION FOR PIN MIGRATION (AWL*)							Service	ATA:32
	MOS	13-Mar-26							
	HRS	9596.2							
	AFL	7624	600		8224		434		
PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05									
322061	* NOSE LANDING GEAR TRUNNION AXLE (IRN O3220029) (AWL*)							Component	ATA:32
PN:2342110-003	MOS	10-May-05		TSN 0				LIFE LIMIT	
SN:384	HRS	0		TSN 0					
	AFL	0	20000	TSN 0	20000		12210		
PROC. REF: AMM 32-20-01PROC. REF: AMM 32-20-01									
322071	LEFT * NOSE LANDING GEAR TRUNNION PIN (IRN O3220028) (AWL*)							Component	ATA:32
PN:2342108-003	MOS	10-May-05		TSN 0				LIFE LIMIT	
SN:E020	HRS	0		TSN 0					
	AFL	0	20000	TSN 0	20000		12210		
PROC. REF: AMM 32-20-01PROC. REF: AMM 32-20-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
322072	RIGHT * NOSE LANDING GEAR TRUNNION PIN (IRN O3220028) (AWL*)							Component	ATA:32
PN:2342108-003	MOS	10-May-05		TSN 0				LIFE LIMIT	
SN:E005	HRS	0		TSN 0					
	AFL	0	20000	TSN 0	20000		12210		
PROC. REF: AMM 32-20-01PROC. REF: AMM 32-20-01									
322095	LEFT NOSE LANDING GEAR DOOR							Component	ATA:32
PN:4552800001-007	MOS/MSC	10-May-05	O/C	TSN 0					
SN:0315	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 52-81-01PROC. REF: AMM 52-81-01									
322096	RIGHT NOSE LANDING GEAR DOOR							Component	ATA:32
PN:4552800002-007	MOS/MSC	10-May-05	O/C	TSN 0					
SN:0311	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 52-81-01PROC. REF: AMM 52-81-01									
322121	NOSE LANDING GEAR UPLOCK MECHANISM							Component	ATA:32
PN:2269H000-003	MOS/MSC	01-Dec-06	O/C						
SN:0064	HRS	1017.73							
	AFL	815							
PROC. REF: AMM 32-32-02PROC. REF: AMM 32-32-02									
323001	LEFT * MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY (AWL*)							Component	ATA:32
PN:200-0300-005	MOS	13-Mar-26						LIFE LIMIT	
SN:H0361	HRS	9596.2		TSN 9594.9					
	AFL	7624	17000	TSN 7619	17005		9215		
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01									
323002	RIGHT * MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY (AWL*)							Component	ATA:32
PN:200-0300-006	MOS	16-Oct-24		TSN 64				LIFE LIMIT	
SN:H1714	HRS	9492.6		TSN 3148.6					
	AFL	7560	17000	TSN 2384	22176		14386		
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR
 Serial: 45-2027
 RegNo: N116PJ
 HRS: 9841.3
 AFL: 7790
 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
323013	LEFT INBOARD MAIN LANDING GEAR DOOR ACTUATOR							Component	ATA:32
PN:7469-1	MOS/MSC	13-Mar-14	O/C						
SN:0194	HRS	6040.72							
	AFL	4913							
PROC. REF: AMM 32-31-02PROC. REF: AMM 32-31-02									
323014	RIGHT INBOARD MAIN LANDING GEAR DOOR ACTUATOR							Component	ATA:32
PN:7469-1	MOS/MSC	27-May-24	O/C	TSO 0					
SN:0673	HRS	9381.4		TSO 0					
	AFL	7483		TSO 0					
PROC. REF: AMM 32-31-02PROC. REF: AMM 32-31-02									
323110	* NOSE LANDING GEAR ACTUATOR UPPER PIN (AWL*)							Component	ATA:32
PN:4532302043-007	MOS	18-Jul-05		TSN 0				LIFE LIMIT	
SN:251	HRS	18.9		TSN 0					
	AFL	15	20000	TSN 0	20015		12225		
PROC. REF: AMM 32-32-01PROC. REF: AMM 32-32-01									
323206	LEFT UPLOCK ACTUATOR ASSEMBLY							Component	ATA:32
PN:3000H000-005	MOS/MSC		O/C						
SN:0248	HRS								
	AFL	0							
PROC. REF: AMM 32-31-04PROC. REF: AMM 32-31-04									
323240	RIGHT UPLOCK ACTUATOR ASSEMBLY							Component	ATA:32
PN:6632303004-006	MOS/MSC	10-May-05	O/C	TSN 0					
SN:1654	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-31-04PROC. REF: AMM 32-31-04									
323735	MAIN LANDING GEAR VALVE							Component	ATA:32
PN:6632302001-003	MOS/MSC	10-May-05	O/C	TSN 0					
SN:1343	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
324001	LEFT INBOARD MAIN LANDING GEAR WHEEL							Component	ATA:32
PN:3-1545-1	MOS/MSC	19-May-26	O/C						
SN:0612	HRS	9709.5							
	AFL	7701							
PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02									
324002	LEFT OUTBOARD MAIN LANDING GEAR WHEEL							Component	ATA:32
PN:3-1545-1	MOS/MSC	19-May-26	O/C						
SN:2694	HRS	9709.5							
	AFL	7701							
PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02									
324003	RIGHT INBOARD MAIN LANDING GEAR WHEEL							Component	ATA:32
PN:3-1545-1	MOS/MSC	21-Apr-26	O/C						
SN:1984	HRS	9655							
	AFL	7666							
PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02									
324004	RIGHT OUTBOARD MAIN LANDING GEAR WHEEL							Component	ATA:32
PN:3-1545-1	MOS/MSC	21-Apr-26	O/C						
SN:2846	HRS	9655							
	AFL	7666							
PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02									
324005	NOSE GEAR ASSEMBLY WHEEL							Component	ATA:32
PN:5010694	MOS/MSC	19-May-26	O/C						
SN:00-9103	HRS	9709.5							
	AFL	7701							
PROC. REF: AMM 32-40-01PROC. REF: AMM 32-40-01									
324021	LEFT INBOARD MAIN LANDING GEAR TIRE							Component	ATA:32
PN:226K08-4	MOS/MSC	19-May-26	O/C	TSN 0					
SN:52270710	HRS	9709.5		TSN 0					
	AFL	7701		TSN 0					
PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02									

?-Insufficient Information

S-Suppressed Requirement

*-Estimated Due(New Requirement)

(EFF)-Effective C / W

(M)-Manual Due

U-User Task

Ex-Excluded Task

Status Report

Model: LEARJET 40XR
 Serial: 45-2027
 RegNo: N116PJ
 HRS: 9841.3
 AFL: 7790
 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
324022	LEFT OUTBOARD MAIN LANDING GEAR TIRE							Component	ATA:32
PN:226K08-4	MOS/MSC	19-May-26	O/C	TSN 0					
SN:51980697	HRS	9709.5		TSN 0					
	AFL	7701		TSN 0					
PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02									
324023	RIGHT INBOARD MAIN LANDING GEAR TIRE							Component	ATA:32
PN:226K08-4	MOS/MSC	21-Apr-26	O/C	TSN 0					
SN:51960780	HRS	9655		TSN 0					
	AFL	7666		TSN 0					
PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02									
324024	RIGHT OUTBOARD MAIN LANDING GEAR TIRE							Component	ATA:32
PN:226K08-4	MOS/MSC	21-Apr-26	O/C	TSN 0					
SN:51970705	HRS	9655		TSN 0					
	AFL	7666		TSN 0					
PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02									
324025	NOSE TIRE							Component	ATA:32
PN:031-613-8	MOS/MSC	19-May-26	O/C	TSN 0					
SN:5098T00347	HRS	9709.5		TSN 0					
	AFL	7701		TSN 0					
PROC. REF: AMM 32-40-01PROC. REF: AMM 32-40-01									
324041	LEFT OUTBOARD MAIN LANDING GEAR BRAKE							Component	ATA:32
PN:2-1579-2	MOS/MSC	22-Sep-16	O/C	TSO 0					
SN:0131	HRS	6857.7		TSO 0					
	AFL	553		TSO 0					
PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01									
324042	LEFT INBOARD MAIN LANDING GEAR BRAKE							Component	ATA:32
PN:2-1579-2	MOS/MSC	22-Sep-16	O/C	TSO 0					
SN:1999	HRS	6857.7		TSO 0					
	AFL	5573		TSO 0					
PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
324043	RIGHT INBOARD MAIN LANDING GEAR BRAKE							Component	ATA:32
PN:2-1579-2	MOS/MSC	22-Sep-16	O/C	TSO 0					
SN:1221	HRS	6857.7		TSO 0					
	AFL	5573		TSO 0					
PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01									
324044	RIGHT OUTBOARD MAIN LANDING GEAR BRAKE							Component	ATA:32
PN:2-1579-2	MOS/MSC	10-May-23	O/C	TSO 0					
SN:0825	HRS	9071.3		TSO 0					
	AFL	7252		TSO 0					
PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01									
324061	LEFT ANTI-SKID CONTROL VALVE							Component	ATA:32
PN:39-787	MOS/MSC	29-Jul-22	O/C						
SN:1257	HRS	8833.8							
	AFL	7089							
PROC. REF: AMM 32-41-07PROC. REF: AMM 32-41-07									
324062	RIGHT ANTI-SKID CONTROL VALVE							Component	ATA:32
PN:39-787	MOS/MSC	25-Jan-22	O/C						
SN:802	HRS	8706.9							
	AFL	6996							
PROC. REF: AMM 32-41-07PROC. REF: AMM 32-41-07									
324201	LEFT INBOARD BRAKE SHUTTLE VALVE							Component	ATA:32
PN:7632401002-003	MOS/MSC	10-May-05	O/C	TSN 0					
SN:1288	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-42-04PROC. REF: AMM 32-42-04									
324202	LEFT OUTBOARD BRAKE SHUTTLE VALVE							Component	ATA:32
PN:7632401002-003	MOS/MSC	10-May-05	O/C	TSN 0					
SN:1285	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-42-04PROC. REF: AMM 32-42-04									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
324203	RIGHT INBOARD BRAKE SHUTTLE VALVE							Component	ATA:32
PN:7632401002-003	MOS/MSC	10-May-05	O/C	TSN 0					
SN:1284	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-42-04PROC. REF: AMM 32-42-04									
324204	RIGHT OUTBOARD BRAKE SHUTTLE VALVE							Component	ATA:32
PN:7632401002-003	MOS/MSC	10-May-05	O/C	TSN 0					
SN:1289	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-42-04PROC. REF: AMM 32-42-04									
324205 ^U	BRAKE SHUTTLE MODULE							Component	ATA:32
PN:6632401003-001	MOS/MSC	09-Jan-23	O/C	TSO 0					
SN:040	HRS	9039.2		TSO 0					
	AFL	7232		TSO 0					
324305	BRAKE CONTROL UNIT							Component	ATA:32
PN:42-933-3	MOS/MSC	16-Mar-26	O/C						
SN:440A	HRS	9596.2							
	AFL	7624							
PROC. REF: AMM 32-41-02PROC. REF: AMM 32-41-02									
324805	BRAKE ACCUMULATOR							Component	ATA:32
PN:4532403040-005	MOS/MSC	10-May-05	O/C	TSN 0					
SN:353	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-42-02PROC. REF: AMM 32-42-02									
324868 ^U	EMERGENCY PARK BRAKE VALVE							Component	ATA:32
PN:6632401002-011	MOS/MSC	02-Aug-09	O/C						
SN:025	HRS	2839.98							
	AFL	2341							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
325011	NOSE STEERING WHEEL ACTUATOR							Component	ATA:32
PN:JR5208C	MOS/MSC	10-May-05	O/C	TSN 0					
SN:A0343	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-50-02PROC. REF: AMM 32-50-02									
325021	NOSE STEERING WHEEL GEARBOX							Component	ATA:32
PN:2W3201D	MOS/MSC	10-May-05	O/C	TSN 0					
SN:C0336	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-50-03PROC. REF: AMM 32-50-03									
325031	NOSE STEERING WHEEL COMPUTER							Component	ATA:32
PN:498000-03-01	MOS/MSC	10-May-05	O/C	TSN 0					
SN:00336	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-50-01PROC. REF: AMM 32-50-01									
325041	RIGHT NWS RVDT							Component	ATA:32
PN:19710/3A1279A	MOS/MSC	10-May-05	O/C	TSN 0					
SN:0681	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
325042	LEFT NWS RVDT							Component	ATA:32
PN:19710/3A1279A	MOS/MSC	10-May-05	O/C	TSN 0					
SN:0643	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
5-19-00-AA3220111-LEFT	LEFT MAIN LANDING GEAR SIDE-STAY ACTUATOR - DISASSEMBLE ACTUATOR AND PERFORM DETAILED VISUAL INSPECTION. (IRN AA3220111)							Service	ATA:32
	MOS	03-Sep-21	96 (+14d/-14d)	Adj -92d	03-Jun-29	17-Jun-29	992 d (+14)		
	HRS	8435.1							
	AFL	6787	10000 (+25/-25)		16787	16812	8997 (+25)		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
5-19-00-AA3220111-RIGHT	RIGHT MAIN LANDING GEAR SIDE-STAY ACTUATOR - DISASSEMBLE ACTUATOR AND PERFORM DETAILED VISUAL INSPECTION. (IRN AA3220111)							Service	ATA:32
	MOS	03-Sep-21	96 (+14d/-14d)	Adj -92d	03-Jun-29	17-Jun-29	992 d (+14)		
	HRS	8435.1							
	AFL	6787	10000 (+25/-25)		16787	16812	8997 (+25)		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
5-19-00-L3220020-LEFT	* MAIN LANDING GEAR TRUNNION FITTINGS ON MID AND REAR SPAR - PERFORM EDDY CURRENT INSPECTION (IRN L3220020) (AWL*)							Service	ATA:32
	MOS	10-May-05						AIRWORTHINESS	
	HRS	0							
	AFL	0	T:10000		10000		2210		
PROC. REF: NDT PART 6/32-11-00PROC. REF: NDT PART 6/32-11-00									
5-19-00-L3220020-RIGHT	* MAIN LANDING GEAR TRUNNION FITTINGS ON MID AND REAR SPAR - PERFORM EDDY CURRENT INSPECTION (IRN L3220020) (AWL*)							Service	ATA:32
	MOS	10-May-05						AIRWORTHINESS	
	HRS	0							
	AFL	0	T:10000		10000		2210		
PROC. REF: NDT PART 6/32-11-00PROC. REF: NDT PART 6/32-11-00									
5-19-00-P3220146	MAIN LANDING GEAR * SHOCK STRUT CYLINDER (P/N 200-0201-109 AND 200-0201-110) PERFORM ULTRASONIC INSPECTION OF THE FORGING PARTING LINE							Service	ATA:32
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2							
	AFL	7624	600		8224		434		
PROC. REF: NDT PART 4/32-10-01PROC. REF: NDT PART 4/32-10-01									
5-19-00-P3231020-LEFT	MAIN LANDING GEAR DOOR ACTUATOR GIMBAL ASSEMBLY - PERFORM EDDY CURRENT INSPECTION (IRN P3231020)							Service	ATA:32
	MOS/MSC	10-May-05	N/A						
	HRS	0							
	AFL	0							
PROC. REF: NDT PART 6/32-13-00PROC. REF: NDT PART 6/32-13-00									
5-19-00-P3231020-RIGHT	MAIN LANDING GEAR DOOR ACTUATOR GIMBAL ASSEMBLY - PERFORM EDDY CURRENT INSPECTION (IRN P3231020)							Service	ATA:32
	MOS/MSC	10-May-05	N/A						
	HRS	0							
	AFL	0							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
PROC. REF: NDT PART 6/32-13-00PROC. REF: NDT PART 6/32-13-00									
5-19-00-P3231021-LEFT	MAIN LANDING GEAR DOOR ACTUATOR GIMBAL SHAFT - PERFORM FLUORESCENT PENETRANT INSPECTION - (IRN P3231021)							Service	ATA:32
	MOS/MSC	10-May-05	N/A						
	HRS	0							
	AFL	0							
PROC. REF: NDT PART 8/32-13-02PROC. REF: NDT PART 8/32-13-02									
5-19-00-P3231021-RIGHT	MAIN LANDING GEAR DOOR ACTUATOR GIMBAL SHAFT - PERFORM FLUORESCENT PENETRANT INSPECTION - (IRN P3231021)							Service	ATA:32
	MOS/MSC	10-May-05	N/A						
	HRS	0							
	AFL	0							
PROC. REF: NDT PART 8/32-13-02PROC. REF: NDT PART 8/32-13-02									
5-19-00-T3220007	* MAIN LANDING GEAR AXLES - PERFORM MAIN LANDING GEAR AXLE BEAM ASSEMBLY (P/N 200-203-001) BORESCOPE INSPECTION (IRN T3220007) (AWL*)							Service	ATA:32
	MOS	13-Mar-26	48		13-Mar-30		1275 d		
	HRS	9596.2							
	AFL	7624							
PROC. REF: NDT PART 8/32-10-03, AMM 32-10-01PROC. REF: NDT PART 8/32-10-03, AMM 32-10-01									
5-19-00-V3220022-LEFT	MAIN LANDING GEAR TRUNNION PINS - PERFORM MAGNETIC PARTICLE INSPECTION.							Service	ATA:32
	MOS	03-Sep-21	96 (+14d/-14d)	Adj -92d	03-Jun-29	17-Jun-29	992 d (+14)		
	HRS	8435.1							
	AFL	6787							
PROC. REF: NDT PART 7/32-10-07, NDT PART 7/32-10-08PROC. REF: NDT PART 7/32-10-07, NDT PART 7/32-10-08									
5-19-00-V3220022-RIGHT	MAIN LANDING GEAR TRUNNION PINS - PERFORM MAGNETIC PARTICLE INSPECTION.							Service	ATA:32
	MOS	03-Sep-21	96 (+25d/-25d)	Adj -92d	03-Jun-29	28-Jun-29	992 d (+25)		
	HRS	8435.1							
	AFL	6787							
PROC. REF: NDT PART 7/32-10-07, NDT PART 7/32-10-08PROC. REF: NDT PART 7/32-10-07, NDT PART 7/32-10-08									
5-19-00-W3231022-LEFT	LEFT MAIN LANDING GEAR INBOARD DOOR GIMBAL BRACKET (P/N 4532103150-001) - PERFORM EDDY CURRENT INSPECTION.							Service	ATA:32
	MOS/MSC	10-May-05	N/A						
	HRS	0							
	AFL	0							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
PROC. REF: NDT PART 6/32-13-01PROC. REF: NDT PART 6/32-13-01									
5-19-00-W3231022-RIGHT RIGHT MAIN LANDING GEAR INBOARD DOOR GIMBAL BRACKET (P/N 4532103150-001) - PERFORM EDDY CURRENT INSPECTION. Service ATA:32									
	MOS/MSC	10-May-05	N/A						
	HRS	0							
	AFL	0							
PROC. REF: NDT PART 6/32-13-01PROC. REF: NDT PART 6/32-13-01									
5-19-01-L3231024 * REPLACE MAIN LANDING GEAR INBOARD DOOR ACTUATOR CAP SCREWS (P/N 7469-1) (AWL*) Service ATA:32									
	MOS	03-Sep-21						LIFE LIMIT	
	HRS	8435.1	2400		10835.1		993.8		
	AFL	6787							
PROC. REF: AMM 32-31-02PROC. REF: AMM 32-31-02									
5-19-01-N3220012-L REPLACE * MAIN LANDING GEAR STRUT ASSEMBLY (P/N 6632101000) (N3220012) (AWL*) Service ATA:32									
	MOS	10-May-05						LIFE LIMIT	
	HRS	0							
	AFL	0	10000		10000		2210		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
5-19-01-N3220012-R REPLACE * MAIN LANDING GEAR STRUT ASSEMBLY (P/N 6632101000) (N3220012) (AWL*) Service ATA:32									
	MOS	10-May-05						LIFE LIMIT	
	HRS	0							
	AFL	0	10000		10000		2210		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
5-19-01-N3220023 REPLACE * MAIN LANDING GEAR TRUNNION PINS (P/N 200-0212, 200-0213) (N3220023) (AWL*) Service ATA:32									
	MOS	10-May-05						LIFE LIMIT	
	HRS	0							
	AFL	0	10000		10000		2210		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
5-19-01-N3220035-L REPLACE * MAIN LANDING GEAR SHOCK STRUT PISTON (N3220035) (AWL*) Service ATA:32									
	MOS	14-Dec-05						LIFE LIMIT	
	HRS	0							
	AFL	0	10000		10000		2210		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
PROC. REF: NDT PART 7/32-10-03, AMM 32-10-01PROC. REF: NDT PART 7/32-10-03, AMM 32-10-01									
5-19-01-N3220035-R	REPLACE * MAIN LANDING GEAR SHOCK STRUT PISTON (N3220035) (AWL*)							Service	ATA:32
	MOS	14-Dec-05						LIFE LIMIT	
	HRS	0							
	AFL	0	10000		10000		2210		
PROC. REF: NDT PART 7/32-10-03, AMM 32-10-01PROC. REF: NDT PART 7/32-10-03, AMM 32-10-01									
5-19-01-N3220036-L	* REPLACE LEFT MAIN LANDING GEAR AXLE BEAM (IRN N3220036) (AWL*)							Service	ATA:32
	MOS	14-Dec-05						LIFE LIMIT	
	HRS	0							
	AFL	0	10000		10000		2210		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
5-19-01-N3220036-R	* REPLACE RIGHT MAIN LANDING GEAR AXLE BEAM (IRN N3220036) (AWL*)							Service	ATA:32
	MOS	14-Dec-05						LIFE LIMIT	
	HRS	0							
	AFL	0	10000		10000		2210		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
5-19-01-N3220037-L	* REPLACE LEFT MAIN LANDING GEAR SHOCK STRUT LINK (IRN N3220037) (AWL*)							Service	ATA:32
	MOS	14-Dec-05						LIFE LIMIT	
	HRS	0							
	AFL	0	10000		10000		2210		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
5-19-01-N3220037-R	* REPLACE RIGHT MAIN LANDING GEAR SHOCK STRUT LINK (IRN N3220037) (AWL*)							Service	ATA:32
	MOS	14-Dec-05						LIFE LIMIT	
	HRS	0							
	AFL	0	10000		10000		2210		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
5-19-01-N3220041	REPLACE * MAIN LANDING GEAR FORWARD TRUNNION SHEAR PINS (P/N 4532103015, 4532103132) (IRN N3220041) (AWL*)							Service	ATA:32
	MOS/MSC	10-May-05	N/A						
	HRS	0							
	AFL	0							
PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR
Serial: 45-2027
RegNo: N116PJ
HRS: 9841.3
AFL: 7790
As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
5-19-01-N3220042	REPLACE * MAIN LANDING GEAR AFT TRUNNION UPPER SHEAR PIN (P/N 4532103025, 4532103133) (IRN N3220042) (AWL*)							Service	ATA:32
	MOS/MSC	26-Oct-14	N/A						
	HRS	6496.17							
	AFL	5289							
PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05									
5-19-01-N3220043	REPLACE * MAIN LANDING GEAR AFT TRUNNION LOWER SHEAR PIN (P/N 4532103026, 4532103134) (IRN N3220043) (AWL*)							Service	ATA:32
	MOS/MSC	26-Oct-14	N/A						
	HRS	6496.17							
	AFL	5289							
PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05									
5-19-01-N3220101	REPLACE * MAIN LANDING GEAR LINK PIN (P/N 200-0214) (IRN N3220101) (AWL*)							Service	ATA:32
	MOS	14-Dec-05						LIFE LIMIT	
	HRS	0							
	AFL	0	10000		10000		2210		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
5-19-01-N3220102	* REPLACE MAIN LANDING GEAR PISTON PIN (IRN N3220102) (AWL*)							Service	ATA:32
	MOS	14-Dec-05						LIFE LIMIT	
	HRS	0							
	AFL	0	10000		10000		2210		
PROC. REF: NDT PART 7/32-10-04, AMM 32-10-01PROC. REF: NDT PART 7/32-10-04, AMM 32-10-01									
5-19-01-N3220116	REPLACE * MAIN LANDING GEAR SHOCK STRUT CYLINDER (P/N 200-0201-109, -110) (N3220116) (AWL*)							Service	ATA:32
	MOS	14-Dec-05						LIFE LIMIT	
	HRS	0							
	AFL	0	10000		10000		2210		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
5-19-01-N3220126	REPLACE * MAIN LANDING GEAR SIDE-STAY ACTUATOR FITTING (N3220126) (AWL*)							Service	ATA:32
	MOS	10-May-05						LIFE LIMIT	
	HRS	0							
	AFL	0	20000		20000		12210		
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01									

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C / W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
5-19-01-N3220139	REPLACE * MAIN LANDING GEAR FORWARD TRUNNION SHEAR PIN (P/N 4532103201) (N3220139) (AWL*)							Service	ATA:32
	MOS							LIFE LIMIT	
	HRS								
	AFL	0	5000		10289 (M)		2499		
PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05									
5-19-01-N3220140	REPLACE * MAIN LANDING GEAR AFT TRUNNION UPPER SHEAR PIN (P/N 4532103202) (N3220140) (AWL*)							Service	ATA:32
	MOS/MSC	10-May-05	N/A						
	HRS	0							
	AFL	0							
PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05									
5-19-01-N3220141	REPLACE * MAIN LANDING GEAR AFT TRUNNION LOWER SHEAR PIN (P/N 4532103203) (N3220141) (AWL*)							Service	ATA:32
	MOS/MSC	10-May-05	N/A						
	HRS	0							
	AFL	0							
PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05									
A3230001 S	** LANDING GEAR - PERFORM EMERGENCY GEAR EXTENSIONFUNCTIONAL TEST (AWL**)							Service	ATA:32
	MOS	13-Mar-26	24 (+14d/-14d)					AIRWORTHINESS	
	HRS	9596.2	600 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 32-33-00PROC. REF: AMM 32-33-00									
A3240005 S	** BRAKE HYDRAULIC FUSES - PERFORM FUNCTIONAL TEST (AWL**)							Service	ATA:32
	MOS	13-Mar-26	48 (+14d/-14d)					AIRWORTHINESS	
	HRS	9596.2	1200 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 32-41-09PROC. REF: AMM 32-41-09									
A3240006 S	** BRAKE SHUTTLE MODULE - PERFORM FUNCTIONAL TEST (AWL**)							Service	ATA:32
	MOS	13-Mar-26	48 (+14d/-14d)					AIRWORTHINESS	
	HRS	9596.2	1200 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 32-41-04PROC. REF: AMM 32-41-04									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
---------	------	-------	----------	------------	----------------------------	-----------	-----------	-------------	----------

ATA 32 - LANDING GEAR

A3240007	^S	**BRAKE SHUTTLE VALVES - PERFORM FUNCTIONAL TEST (AWL**)						Service	ATA:32
	MOS	13-Mar-26	96 (+14d/-14d)					AIRWORTHINESS	
	HRS	9596.2	2400 (+25/-25)						
	AFL	7624							
									PKG:23
PROC. REF: AMM 32-42-04PROC. REF: AMM 32-42-04									

A3240009	^S	** BRAKE PRESSURE TRANSDUCERS - PERFORM FUNCTIONAL TEST (AWL**)						Service	ATA:32
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	4800 (+25/-25)						
	AFL	7624							
									PKG:25
PROC. REF: AMM 32-41-08PROC. REF: AMM 32-41-08									

AB3220016	^S	NOSE LANDING GEAR STRUT ASSEMBLY - PERFORM SPECIAL DETAILED INSPECTION.						Service	ATA:32
	MOS	10-May-05							
	HRS	0							
	AFL	0	10000 (+25/-25)						
									PKG:27
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

AE3220151		LEFT - MAIN LANDING GEAR STRUT ASSEMBLY REBOUND RING - REPLACE.						Service	ATA:32
	MOS	EFF	96		10-May-31 * (M)		1698 d		
	HRS								
	AFL								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

AE3220151		RIGHT - MAIN LANDING GEAR STRUT ASSEMBLY REBOUND RING - REPLACE.						Service	ATA:32
	MOS	EFF	96		10-May-31 * (M)		1698 d		
	HRS								
	AFL								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
H3220017	^S	NOSE LANDING GEAR TRUNNION AXLE - PERFORM VISUAL INSPECTION. IF CORROSION IS FOUND, REMOVE AXLE FROM CYLINDER AND PERFORM FLUORESCENT PENETRANT INSPECTION OF LUG AREA AND MAGNETIC PARTICLE INSPECTION OF AXLE. IF CORROSION IS NOT FOUND, CONDUCT FLUORESCENT PENETRANT INSPECTION OF AXLE PORTION THAT IS EXPOSED FROM CYLINDER						Service	ATA:32
	MOS	10-May-05							
	HRS	0							
	AFL	0	10000 (+25/-25)						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:27
L3220019	^S	NOSE LANDING GEAR ACTUATOR ATTACHMENT PIN - REMOVE PIN AND PERFORM MAGNETIC PARTICLE INSPECTION.						Service	ATA:32
	MOS	10-May-05							
	HRS	0							
	AFL	0	10000 (+25/-25)						
PROC. REF: NDT PART 7/32-30-02PROC. REF: NDT PART 7/32-30-02									PKG:27
L3220109	^S	NOSE LANDING GEAR ACTUATOR ASSEMBLY - DISASSEMBLE ACTUATOR AND PERFORM DETAILED VISUAL INSPECTION						Service	ATA:32
	MOS	10-May-05							
	HRS	0							
	AFL	0	10000 (+25/-25)						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:27
V3240004	^S	** EMERGENCY/PARKING BRAKE SWITCH - VERIFY THAT "EMERGENCY/PARKING BRAKE" MESSAGE ILLUMINATESON EICAS WHEN PARKING BRAKE IS SET AND THROTTLESARE MOVED ABOVE MCR DETENT (AWL**)						Service	ATA:32
	MOS	13-Mar-26	24 (+14d/-14d)					AIRWORTHINESS	
	HRS	9596.2	600 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 32-42-01PROC. REF: AMM 32-42-01									PKG:11
V3240008	^S	** EMERGENCY/PARKING BRAKE CONTROL SYSTEM - PERFORM FUNCTIONAL TEST (AWL**)						Service	ATA:32
	MOS	13-Mar-26	24 (+14d/-14d)					AIRWORTHINESS	
	HRS	9596.2	600 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 32-42-02PROC. REF: AMM 32-42-02									PKG:11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
Y3220000	^S	NOSE LANDING GEAR ASSEMBLY - PERFORM VISUAL INSPECTION.						Service	ATA:32
	MOS	13-Mar-26	24	(+14d/-14d)					
	HRS	9596.2	600	(+25/-25)					
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
PKG:11									
Y3220001	^S	MAIN LANDING GEAR ASSEMBLY - PERFORM VISUAL INSPECTION. INSPECTION TO INCLUDE ACTUATOR, FASTENERS,SUPPORT STRUCTURE, AND SQUAT SWITCHES.						Service	ATA:32
	MOS	13-Mar-26	24	(+14d/-14d)					
	HRS	9596.2	600	(+25/-25)					
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
PKG:11									
Y3220002	^S	NOSE LANDING GEAR ACTUATOR PRESSURE AND RETURN LINES - PERFORM VISUAL INSPECTION. LOWER ACTUATOR DUST BOOT TO INSPECT LINES.						Service	ATA:32
	MOS	13-Mar-26	24	(+14d/-14d)					
	HRS	9596.2	600	(+25/-25)					
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
PKG:11									
Y3220003	^S	NOSE GEAR SHOCK STRUT - REMOVE AND REPLACE RETAINERRING LOCKSCREW						Service	ATA:32
	MOS	13-Mar-26	24	(+14d/-14d)					
	HRS	9596.2	600	(+25/-25)					
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
PKG:11									
Y3220004	^S	MAIN LANDING GEAR ACTUATOR AND GEAR INBOARD DOOR ACTUATOR ATTACH POINTS - PERFORM VISUAL INSPECTION.						Service	ATA:32
	MOS	13-Mar-26	24	(+14d/-14d)					
	HRS	9596.2	600	(+25/-25)					
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
PKG:11									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
Y3220006 ^S		LANDING GEAR ELECTRICAL WIRING - PERFORM VISUAL INSPECTION (THAT PORTION VISIBLE INSIDE WHEEL/WELL).						Service	ATA:32
	MOS	13-Mar-26	24 (+14d/-14d)						
	HRS	9596.2	600 (+25/-25)						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:11
Y3220008 ^S		NOSE LANDING GEAR AXLE - REMOVE NOSE LANDING GEAR WHEEL AND PERFORM INSPECTION. INSPECT BOTHINSIDE AND OUTSIDE OF AXLE						Service	ATA:32
	MOS	13-Mar-26	48 (+14d/-14d)						
	HRS	9596.2	1200 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 32-40-01PROC. REF: AMM 32-40-01									PKG:17
Y3220124 ^S		NOSE LANDING GEAR - PERFORM DETAILED VISUAL INSPECTION OF THE NOSE LANDING GEAR UPLOCK ROLLER BRACKET						Service	ATA:32
	MOS	13-Mar-26	24 (+14d/-14d)						
	HRS	9596.2	600 (+25/-25)						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:11
Y3230002 ^S		MAIN LANDING GEAR FREE FALL ROLLER - PERFORM VISUAL INSPECTION. PAY PARTICULAR ATTENTION TO BINDING OF ROLLERS.						Service	ATA:32
	MOS	13-Mar-26	12 (+14d/-14d)						
	HRS	9596.2	300 (+25/-25)						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:5
Y3231023 ^S		PERFORM MAIN LANDING GEAR INBOARD DOOR ACTUATOR (P/N 7469) END CAP SCREWS - DETAILED INSPECTION						Service	ATA:32
	MOS	13-Mar-26	12 (+14d/-14d)						
	HRS	9596.2	300 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 32-31-02PROC. REF: AMM 32-31-02									PKG:5

Status Report

Model: LEARJET 40XR
Serial: 45-2027
RegNo: N116PJ
HRS: 9841.3
AFL: 7790
As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
Y3240000	^S	NOSE AND MAIN TIRES - PERFORM VISUAL INSPECTION						Service	ATA:32
	MOS	13-Mar-26	12	(+14d/-14d)					
	HRS	9596.2	300	(+25/-25)					
	AFL	7624							
PROC. REF: AMM 12-10-04PROC. REF: AMM 12-10-04									PKG:5
Y3240001	^S	BRAKE LINES - PERFORM VISUAL INSPECTION. INSPECT ALL BRAKE LINES VISIBLE IN WHEEL WELLS AND ON STRUTS.						Service	ATA:32
	MOS	13-Mar-26	24	(+14d/-14d)					
	HRS	9596.2	600	(+25/-25)					
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:11
Y3240002	^S	BRAKE ASSEMBLIES - PERFORM VISUAL INSPECTION WITH PARKING BRAKE SET. WORN BRAKES ARE VISUALLY INDICATED WHEN THE WEAR INDICATOR PINS BECOME EVEN WITH THE OUTER SURFACE OF THE WEAR INDICATOR SLEEVE						Service	ATA:32
	MOS	13-Mar-26	12	(+14d/-14d)					
	HRS	9596.2	300	(+25/-25)					
	AFL	7624							
PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01									PKG:5
Y3240003	^S	BRAKE CONTROL SYSTEM LINEAR VARIABLE DIFFERENTIAL TRANSFORMER (LVDT) - PERFORM VISUAL INSPECTION.						Service	ATA:32
	MOS	13-Mar-26	48	(+14d/-14d)					
	HRS	9596.2	1200	(+25/-25)					
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:13
Y3260005	^S	LUBRICATE NOSE LANDING GEAR SQUAT SWITCH ROTATING DISK ASSEMBLY						Service	ATA:32
	MOS	13-Mar-26	12	(+14d/-14d)					
	HRS	9596.2	300	(+25/-25)					
	AFL	7624							
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01									PKG:5

? - Insufficient Information
S - Suppressed Requirement
* - Estimated Due(New Requirement)
(EFF) - Effective C / W
(M) - Manual Due
U - User Task
Ex - Excluded Task

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 33 - LIGHTS									
330000	MODIFIED PULSE CONTROLLER								Component ATA:33
PN:2401S	MOS/MSC	18-Jul-05	O/C	TSN 0					
SN:AR00716	HRS	18.9		TSN 0					
	AFL	15		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
331001	NO. 1 LIGHTING CONTROL UNIT								Component ATA:33
PN:RDC4-1	MOS/MSC	10-May-05	O/C	TSN 0					
SN:0642	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-10-06PROC. REF: AMM 33-10-06									
331002	NO.2 LIGHTING CONTROL UNIT								Component ATA:33
PN:RDC4-1	MOS/MSC	10-May-05	O/C	TSN 0					
SN:0643	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-10-06PROC. REF: AMM 33-10-06									
331005	CENTER DIODE SWITCH RELAY BOX ASSEMBLY								Component ATA:33
PN:4533108520-005	MOS/MSC	10-May-05	O/C	TSN 0					
SN:A00319688-01	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-10-08PROC. REF: AMM 33-10-08									
331010	DIMMER CONTROL BOX								Component ATA:33
PN:LT-48(G)	MOS/MSC	10-May-05	O/C	TSN 0					
SN:1679	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-10-10PROC. REF: AMM 33-10-10									
331020	LIGHTING INVERTER SUPPLY								Component ATA:33
PN:6900135-001	MOS/MSC	10-May-05	O/C	TSN 0					
SN:467	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-10-04PROC. REF: AMM 33-10-04									

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C / W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 33 - LIGHTS									
331029	CENTER PANEL OVERLAY ASSEMBLY SWITCH							Component	ATA:33
PN:7676108500-007	MOS/MSC	01-Sep-13	O/C						
SN:854/L16683	HRS	5692.87							
	AFL	4644							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
331030	COCKPIT LIGHTING CONTROL MODULE							Component	ATA:33
PN:SP-45-54	MOS/MSC	16-Feb-09	O/C						
SN:110600688	HRS	2629.47							
	AFL	2166							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
332006	NO.4 LIGHT CONTROL UNIT SWITCH							Component	ATA:33
PN:SP-45-33	MOS/MSC	10-May-05	O/C	TSN 0					
SN:060500543	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
332404	ENTRY WAY SWITCH PANEL							Component	ATA:33
PN:SP-45-32	MOS/MSC	18-Jul-05	O/C	TSN 0					
SN:050500814	HRS	18.9		TSN 0					
	AFL	15		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
334332	UPPER ANTI-COLLISION LIGHT							Component	ATA:33
PN:GE16386-12-1	MOS/MSC	18-Jul-05	O/C	TSN 0					
SN:AF2952	HRS	18.9		TSN 0					
	AFL	15		TSN 0					
PROC. REF: AMM 33-40-01PROC. REF: AMM 33-40-01									
334333	LOWER ANTI-COLLISION LIGHT							Component	ATA:33
PN:GE-16386-12-1	MOS/MSC	04-May-26	O/C						
SN:AA2591	HRS	9684.8							
	AFL	7685							
PROC. REF: AMM 33-40-01PROC. REF: AMM 33-40-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 33 - LIGHTS									
335020	ELS ACTIVATION MODULE							Component	ATA:33
PN:4533508501V5-001	MOS/MSC	18-Jul-05	O/C	TSN 0					
SN:A00440271-01	HRS	18.9		TSN 0					
	AFL	15		TSN 0					
PROC. REF: AMM 33-50-01PROC. REF: AMM 33-50-01									
336001	PILOT LIGHTED CHART HOLDER							Component	ATA:33
PN:10-62-01	MOS/MSC	13-Nov-13	O/C						
SN:6751	HRS	5854.77							
	AFL	4776							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
336002	COPILOT LIGHTED CHART HOLDER							Component	ATA:33
PN:10-62-01	MOS/MSC	13-Nov-13	O/C						
SN:6714	HRS	5854.77							
	AFL	4776							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
Y3310000 ^S	PERFORM FLIGHT COMPARTMENT LIGHTING - OPERATION OF THE FOLLOWING: A. MAP LIGHTS. B. INSTRUMENT PANEL FLUORESCENT LIGHTS. C. INSTRUMENT/INDICATOR LIGHTS. D. LIGHT DIMMING SWITCHES. E. CREW WARNING PANEL. F. PANEL OVERLAYS.							Service	ATA:33
	MOS	13-Mar-26	12 (+14d/-14d)						
	HRS	9596.2	300 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 33-10-00PROC. REF: AMM 33-10-00									PKG:1
Y3340000 ^S	EXTERIOR LIGHTING SYSTEMS - PERFORM OPERATION OF THE FOLLOWING: A. TAXI LIGHTS.B. ANTI-COLLISION BEACONS.C. NAVIGATION LIGHTS.D. STROBE LIGHTS.E. LANDING/RECOGNITION LIGHTS.F. WING ICE INSPECTION LIGHTS.G. EMERGENCY DOOR EGRESS LIGHTS.							Service	ATA:33
	MOS	13-Mar-26	12 (+14d/-14d)						
	HRS	9596.2	300 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 33-40-00, AMM 33-41-00PROC. REF: AMM 33-40-00, AMM 33-41-00									PKG:2

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 33 - LIGHTS									
Y3350003	^S	EMERGENCY LIGHTING SYSTEM - PERFORM OPERATIONAL CHECK							Service ATA:33
	MOS	13-Mar-26	48 (+14d/-14d)						
	HRS	9596.2	1200 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 33-50-00PROC. REF: AMM 33-50-00									
ATA 34 - NAVIGATION									
340001		RECERTIFY LEFT PITOT STATIC SYSTEM							Service ATA:34
	MOS	13-Jan-26	24		13-Jan-28		485 d		
	HRS	9594.9							
	AFL								
PROC. REF: AMM 34-11-00, FAR SUBPART EPROC. REF: AMM 34-11-00, FAR SUBPART E									
340005		RECERTIFY RIGHT PITOT STATIC SYSTEM							Service ATA:34
	MOS	13-Jan-26	24		13-Jan-28		485 d		
	HRS	9594.9							
	AFL								
PROC. REF: AMM 34-11-00, FAR SUBPART EPROC. REF: AMM 34-11-00, FAR SUBPART E									
341001		NO. 1 AIR DATA COMPUTER							Component ATA:34
PN:7030700-71704	MOS/MSC	13-Jan-26	O/C						
SN:05010297	HRS	9594.9							
	AFL								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
341001A		RECERTIFY NO. 1 AIR DATA COMPUTER							Service ATA:34
PN:7030700-71704	MOS	13-Jan-26	24		13-Jan-28		485 d		
SN:05010297	HRS	9594.9							
	AFL								
PROC. REF: GENERIC NO REF, FAR SUBPART EPROC. REF: GENERIC NO REF, FAR SUBPART E									
341002		NO. 2 AIR DATA COMPUTER							Component ATA:34
PN:7030700-71704	MOS/MSC	13-Jan-26	O/C						
SN:06111242	HRS	9594.9							
	AFL								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
341002A	RECERTIFY NO. 2 AIR DATA COMPUTER								Service ATA:34
PN:7030700-71704	MOS	13-Jan-26	24		13-Jan-28		485 d		
SN:06111242	HRS	9594.9							
	AFL								
PROC. REF: GENERIC NO REF, FAR SUBPART EPROC. REF: GENERIC NO REF, FAR SUBPART E									
341013	STANDBY AIRSPEED INDICATOR								Component ATA:34
PN:6634208002-003	MOS/MSC	08-Dec-21	O/C	TSO 5					
SN:271917	HRS	8647.8		TSO 0					
	AFL	6960		TSO 0					
PROC. REF: AMM 34-18-01PROC. REF: AMM 34-18-01									
341025	STANDBY ALTIMETER								Component ATA:34
PN:3A43.42.51F.05.1.GM	MOS/MSC	27-Mar-15	O/C						
SN:1049907	HRS	6705.27							
	AFL	5447							
PROC. REF: AMM 34-15-01PROC. REF: AMM 34-15-01									
341025A	RECERTIFY STANDBY ALTIMETER								Service ATA:34
PN:3A43.42.51F.05.1.GM	MOS	13-Jan-26	24		13-Jan-28		485 d		
SN:1049907	HRS	9594.9							
	AFL								
PROC. REF: GENERIC NO REF, FAR SUBPART EPROC. REF: GENERIC NO REF, FAR SUBPART E									
341037	LEFT PRIMARY PITOT/STATIC PROBE (P/N 0856TJ1 OR 6634100000-001)								Component ATA:34
PN:6634100000-001	MOS	13-Mar-26						LIFE LIMIT	
SN:282155	HRS	9596.2	15000 (+25/-25)	TSN 2685.2	21911	21936	12069.7 (+25)		
	AFL	7624							
PROC. REF: AMM 34-11-01PROC. REF: AMM 34-11-01									
341038	RIGHT PRIMARY PITOT/STATIC PROBE (P/N 0856TJ2 OR 6634100000-003)								Component ATA:34
PN:6634100000-003	MOS	10-May-05		TSN 0				LIFE LIMIT	
SN:228303	HRS	0	15000 (+25/-25)	TSN 0	15000	15025	5158.7 (+25)		
	AFL	0		TSN 0					
PROC. REF: AMM 34-11-01PROC. REF: AMM 34-11-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
341049	STANDBY PITOT/STATIC PROBE							Component	ATA:34
PN:6634100000-005	MOS/MSC	15-Jul-19	O/C						
SN:255416	HRS	7629.8							
	AFL	6170							
PROC. REF: AMM 34-11-01PROC. REF: AMM 34-11-01									
341061	RADAR ALTIMETER RECEIVER							Component	ATA:34
PN:7001840-936	MOS/MSC	10-May-05	O/C	TSN 0					
SN:05018748	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
341073	FWD RADAR ALTIMETER ANTENNA							Component	ATA:34
PN:S67-2002-4	MOS/MSC	10-May-05	O/C	TSN 0					
SN:11976	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
341074	AFT RADAR ALTIMETER ANTENNA							Component	ATA:34
PN:S67-2002-4	MOS/MSC	10-May-05	O/C	TSN 0					
SN:552-12301	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
341085	TAT SENSOR PROBE							Component	ATA:34
PN:102AU1AG	MOS/MSC	10-May-05	O/C	TSN 0					
SN:A56616	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-17-02PROC. REF: AMM 34-17-02									
342001	NO. 1 ATTITUDE HEADING REFERENCE COMPUTER							Component	ATA:34
PN:142185-1102	MOS/MSC	05-Jul-23	O/C						
SN:1298	HRS	9121.8							
	AFL	7284							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
342002	NO. 2 ATTITUDE HEADING REFERENCE COMPUTER							Component	ATA:34
PN:142185-1102	MOS/MSC	07-Jul-23	O/C						
SN:1219	HRS	9121.8							
	AFL	7284							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
342003	LEFT AHRS FAN							Component	ATA:34
PN:26012423-105	MOS/MSC	22-Feb-14	O/C						
SN:NSN	HRS	6022.57							
	AFL	4903							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
342004	RIGHT AHRS FAN							Component	ATA:34
PN:140691-0000	MOS/MSC	10-May-05	O/C	TSN 0					
SN:2732	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
342037	LEFT FLUX VALVE							Component	ATA:34
PN:7010133	MOS/MSC	22-Feb-14	O/C						
SN:85074657	HRS	6022.57							
	AFL	4903							
PROC. REF: AMM 34-26-02PROC. REF: AMM 34-26-02									
342038	RIGHT FLUX VALVE							Component	ATA:34
PN:7010133	MOS/MSC	10-May-05	O/C	TSN 0					
SN:01025838	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-26-02PROC. REF: AMM 34-26-02									
342049	NO. 1 DISPLAY, DU870 UNIT							Component	ATA:34
PN:7014300-901	MOS/MSC	16-Feb-18	O/C						
SN:0201A982	HRS	7180.4							
	AFL	5824							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
342050	NO. 2 DISPLAY, DU870 UNIT							Component	ATA:34
PN:7014300-901	MOS/MSC	05-Nov-19	O/C	TSO 0					
SN:98113978	HRS	7762.1		TSO 0					
	AFL	6271		TSO 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
342051	NO. 3 DISPLAY, DU870 UNIT							Component	ATA:34
PN:7014300-901	MOS/MSC	18-Jul-05	O/C	TSN 0					
SN:0505E648	HRS	18.9		TSN 0					
	AFL	15		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
342052	NO. 4 DISPLAY, DU870 UNIT							Component	ATA:34
PN:7014300-901	MOS/MSC	29-Aug-14	O/C						
SN:0608F718	HRS	6419.93							
	AFL	5227							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
342075	STANDBY ATTITUDE INDICATOR							Component	ATA:34
PN:501-1648-02	MOS/MSC	16-Mar-26	O/C	TSO 0					
SN:1340	HRS	9596.2		TSO 0					
	AFL	7624		TSO 0					
PROC. REF: AMM 34-23-01PROC. REF: AMM 34-23-01									
342087	STANDBY COMPASS							Component	ATA:34
PN:PAI-700-5V	MOS/MSC	10-May-05	O/C	TSN 0					
SN:54257	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-21-01PROC. REF: AMM 34-21-01									
344011	WEATHER RADAR ANTENNA							Component	ATA:34
PN:7021450-601	MOS/MSC	15-Jul-11	O/C						
SN:08038292	HRS	4321.27							
	AFL	3541							
PROC. REF: AMM 34-42-01PROC. REF: AMM 34-42-01									

?-Insufficient Information

S-Suppressed Requirement

*-Estimated Due(New Requirement)

(EFF)-Effective C / W

(M)-Manual Due

U-User Task

Ex-Excluded Task

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
344012	WEATHER RADAR CONTROLLER							Component	ATA:34
PN:7008471-667	MOS/MSC	10-May-05	O/C	TSN 0					
SN:04128107	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-42-02PROC. REF: AMM 34-42-02									
344111	UPPER TCAS ANTENNA							Component	ATA:34
PN:7514081-913	MOS/MSC	13-Nov-08	O/C						
SN:ANE21122	HRS	2476.37							
	AFL	2046							
PROC. REF: AMM 34-43-02PROC. REF: AMM 34-43-02									
344112	LOWER TCAS ANTENNA							Component	ATA:34
PN:7514081-913	MOS/MSC	09-Jul-11	O/C						
SN:ANE34705	HRS	4311.47							
	AFL	3530							
PROC. REF: AMM 34-43-02PROC. REF: AMM 34-43-02									
344143	TCAS PROCESSOR							Component	ATA:34
PN:7517900-55012	MOS/MSC	27-Mar-15	O/C						
SN:20008090	HRS	6705.27							
	AFL	5447							
PROC. REF: AMM 34-43-01PROC. REF: AMM 34-43-01									
345001	NO. 1 INTEGRATED NAVIGATION UNIT							Component	ATA:34
PN:7510100-633	MOS/MSC	24-Sep-21	O/C						
SN:01035165	HRS	8457.7							
	AFL	6804							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
345002	NO. 2 INTEGRATED NAVIGATION UNIT							Component	ATA:34
PN:7510100-633	MOS/MSC	04-Nov-21	O/C	TSR 21					
SN:02086727	HRS	8563.6		TSR 0					
	AFL	6885		TSR 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C / W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 40XR
 Serial: 45-2027
 RegNo: N116PJ
 HRS: 9841.3
 AFL: 7790
 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
345013	NO. 1 ADF ANTENNA							Component	ATA:34
PN:7510300-901	MOS/MSC	22-Jul-11	O/C						
SN:1101H620	HRS	4335.18							
	AFL	3554							
PROC. REF: AMM 34-57-01PROC. REF: AMM 34-57-01									
345014	NO. 2 ADF ANTENNA							Component	ATA:34
PN:7510300-901	MOS/MSC	10-May-05	O/C	TSN 0					
SN:04118782	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-57-01PROC. REF: AMM 34-57-01									
345025	ENHANCED GROUND PROXIMITY WARNING COMPUTER							Component	ATA:34
PN:965-0976-040-208-208	MOS/MSC	10-May-05	O/C	TSN 0					
SN:20041	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-45-01PROC. REF: AMM 34-45-01									
345037	UPPER ATC ANTENNA							Component	ATA:34
PN:DMN150-2-2	MOS/MSC	18-Jul-05	O/C	TSN 0					
SN:102434	HRS	18.9		TSN 0					
	AFL	15		TSN 0					
PROC. REF: AMM 34-56-01PROC. REF: AMM 34-56-01									
345038	LOWER ATC ANTENNA							Component	ATA:34
PN:DMN150-2-2	MOS/MSC	10-May-05	O/C	TSN 0					
SN:88828	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-56-01PROC. REF: AMM 34-56-01									
345049	NO. 1 DME ANTENNA							Component	ATA:34
PN:DMN150-2-2	MOS/MSC	10-May-05	O/C	TSN 0					
SN:88829	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-55-01PROC. REF: AMM 34-55-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR
Serial: 45-2027
RegNo: N116PJ
HRS: 9841.3
AFL: 7790
As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
345050	NO. 2 DME ANTENNA							Component	ATA:34
PN:DMN150-9-2	MOS/MSC	10-May-05	O/C	TSN 0					
SN:7063	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-55-01PROC. REF: AMM 34-55-01									
345061	MARKER BEACON ANTENNA							Component	ATA:34
PN:DMN27-3	MOS/MSC	10-May-05	O/C	TSN 0					
SN:14914	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-30-01PROC. REF: AMM 34-30-01									
345083	LEFT VOR/LOCALIZER ANTENNA							Component	ATA:34
PN:DMN4-17-1/N	MOS/MSC	10-May-05	O/C	TSN 0					
SN:20783	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
345084	RIGHT VOR/LOCALIZER ANTENNA							Component	ATA:34
PN:DMN4-17-1/N	MOS/MSC	10-May-05	O/C	TSN 0					
SN:20784	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
345085	PHASING, VHF/NAV COUPLER							Component	ATA:34
PN:DMN4-17-2	MOS/MSC	10-May-05	O/C	TSN 0					
SN:19012	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-51-03PROC. REF: AMM 34-51-03									
345605	NO.1 ATC ANTENNA							Component	ATA:34
PN:DMN150-2-2	MOS/MSC	10-May-05	O/C	TSN 0					
SN:89515	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-56-01PROC. REF: AMM 34-56-01									

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C / W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 40XR
 Serial: 45-2027
 RegNo: N116PJ
 HRS: 9841.3
 AFL: 7790
 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
345606	NO.2 ATC ANTENNA							Component	ATA:34
PN:DMN150-2-2	MOS/MSC	10-May-05	O/C	TSN 0					
SN:88839	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-56-01PROC. REF: AMM 34-56-01									
346001	PILOT CONTROL DISPLAY, FLIGHT MANAGEMENT CDU							Component	ATA:34
PN:2017-41-201	MOS/MSC	27-Jul-23	O/C						
SN:1506	HRS	9146.9							
	AFL	7300							
PROC. REF: AMM 34-60-01PROC. REF: AMM 34-60-01									
346021	FMS DATA TRANSFER UNIT							Component	ATA:34
PN:1406-01-1	MOS/MSC	10-May-05	O/C	TSN 0					
SN:3285	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-60-02PROC. REF: AMM 34-60-02									
346025	NO.1 FMS CONFIG MODULE							Component	ATA:34
PN:10171	MOS/MSC	10-May-05	O/C	TSN 0					
SN:4112	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
347510	NO. 1 GPS ANTENNA							Component	ATA:34
PN:10706	MOS/MSC	10-May-05	O/C	TSN 0					
SN:9447	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-53-01PROC. REF: AMM 34-53-01									
347511	NO. 2 GPS ANTENNA							Component	ATA:34
PN:10706	MOS/MSC	18-Jul-05	O/C	TSN 0					
SN:9934	HRS	18.9		TSN 0					
	AFL	15		TSN 0					
PROC. REF: AMM 34-53-01PROC. REF: AMM 34-53-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
5-19-02-RVSM-L3411062	PERFORM PITOT/STATIC PROBE - DETAILED VISUAL INSPECTION. (IRN L3411062)								Service ATA:34
	MOS	09-Mar-26	24 (+14d/-14d)		09-Mar-28	23-Mar-28	541 d (+14)		
	HRS	9596.1							
	AFL	7623							
PROC. REF: AMM 34-11-01PROC. REF: AMM 34-11-01									
5-19-02-RVSM-M3411052	VERIFY PITCH, ROLL, AND YAW ALIGNMENT ON PRIMARY PITOT-STATIC PROBES (IRN M3411052)								Service ATA:34
	MOS	09-Mar-26	24 (+14d/-14d)		09-Mar-28	23-Mar-28	541 d (+14)		
	HRS	9596.1							
	AFL	7623							
PROC. REF: AMM 34-11-01PROC. REF: AMM 34-11-01									
5-19-02-RVSM-U3411060	FUNCTIONAL TEST AIR DATA SYSTEM								Service ATA:34
	MOS	13-Jan-26	24 (+14d/-14d)		13-Jan-28	27-Jan-28	485 d (+14)		
	HRS	9594.9							
	AFL								
PROC. REF: AMM 34-17-00PROC. REF: AMM 34-17-00									
A3400000 ^S	** NAVIGATION SYSTEMS - PERFORM OPERATIONAL CHECK (AWL**)								Service ATA:34
	MOS	13-Mar-26	24 (+14d/-14d)					AIRWORTHINESS	
	HRS	9596.2	600 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 34-00-00PROC. REF: AMM 34-00-00									PKG:7
Y3411000 ^S	PITOT-STATIC PROBE - PERFORM VISUAL INSPECTION. ENSURE DRAIN HOLES ARE CLEAR OF OBSTRUCTIONS								Service ATA:34
	MOS	13-Mar-26	24 (+14d/-14d)						
	HRS	9596.2	600 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 34-11-01PROC. REF: AMM 34-11-01									PKG:7
Y3440000 ^S	RADOME STRUCTURE AND ANTENNA INSTALLATION - PERFORM VISUAL INSPECTION.								Service ATA:34
	MOS	13-Mar-26	48 (+14d/-14d)						
	HRS	9596.2	1200 (+25/-25)						
	AFL	7624							
									PKG:13

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
---------	------	-------	----------	------------	----------------------------	-----------	-----------	-------------	----------

ATA 34 - NAVIGATION

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

ATA 35 - OXYGEN

350001	OXYGEN REGULATOR & CYLINDER (IRN O3510007)							Component	ATA:35
PN:806385-13	MOS	13-Mar-26	180 (+14d/-14d)	TSN 70	13-May-35	27-May-35	3162 d (+14)	LIFE LIMIT	
SN:ALT372-8282	HRS	9596.2		TSN 1673.9					
	AFL	7624		TSN 1239					
PROC. REF: AMM 35-00-01PROC. REF: AMM 35-00-01									

350001A	** PERFORM ICC HYDROSTATIC TEST ON CYLINDER (PER DOT EXEMPTION E8162) AND FUNCTIONALLY TEST OXYGEN CYLINDER LOW PRESSURE RELIEF VALVE. (IRN Q3510005 OR Q3510018) (AWL**)							Service	ATA:35
PN:806385-13	MOS	13-Mar-26	60 (+14d/-14d)		13-Mar-31	27-Mar-31	1640 d (+14)		
SN:ALT372-8282	HRS	9596.2	5000 (+25/-25)		14596.2	14621.2	4754.9 (+25)		
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

350001B	** OXYGEN CYLINDER AND REMOTE OXYGEN FILL VALVES - PERFORM PERIODIC CHECK. (IRN N3510013) (AWL**)							Service	ATA:35
	MOS	27-May-24							
	HRS	9381.4	1500 (+25/-25)		10881.4	10906.4	1040.1 (+25)		
	AFL	7483							
PROC. REF: AMM 35-00-01PROC. REF: AMM 35-00-01									

350230	OXYGEN INDICATOR							Component	ATA:35
PN:P24090	MOS/MSC	18-Jul-05	O/C	TSN 0					
SN:017	HRS	18.9		TSN 0					
	AFL	15		TSN 0					
PROC. REF: AMM 35-00-05PROC. REF: AMM 35-00-05									

351001	PILOT OXYGEN MASK							Component	ATA:35
PN:MC10-15-166	MOS/MSC	21-Jul-26	O/C						
SN:S095950	HRS	9794.8							
	AFL	7756							
PROC. REF: AMM 35-10-01PROC. REF: AMM 35-10-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 35 - OXYGEN									
351001A		OVERHAUL PILOT OXYGEN MASK (IRN 5-19-00-O3510006)						Service	ATA:35
PN:MC10-15-166	MOS	21-Jul-26	72 (+14d/-14d)		21-Jul-32	04-Aug-32	2136 d (+14)		
SN:S095950	HRS								
	AFL								
			OverHaul Date:: 21-Jul-26						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
351002		COPILOT OXYGEN MASK						Component	ATA:35
PN:MC10-15-166	MOS/MSC	21-Jul-26	O/C						
SN:SE55958	HRS	9794.8							
	AFL	7756							
PROC. REF: AMM 35-10-01PROC. REF: AMM 35-10-01									
351002A		OVERHAUL COPILOT OXYGEN MASK (IRN 5-19-00-O3510006)						Service	ATA:35
PN:MC10-15-166	MOS	21-Jul-26	72 (+14d/-14d)		21-Jul-32	04-Aug-32	2136 d (+14)		
SN:SE55958	HRS								
	AFL								
			OverHaul Date:: 21-Jul-26						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
352002		ALTITUDE COMPENSATING REGULATOR						Component	ATA:35
PN:PN	MOS/MSC	10-May-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 35-20-06PROC. REF: AMM 35-20-06									
352015		OXYGEN CONTROL VALVE						Component	ATA:35
PN:P21081	MOS/MSC	10-May-05	O/C	TSN 0					
SN:0358	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 35-20-01PROC. REF: AMM 35-20-01									
5-19-00-N3510019		** PERFORM PERIODIC CHECK OF THE OXYGEN CYLINDER AND REMOTE FILL VALVES (IRN N3510019) (AWL**)						Service	ATA:35
	MOS	13-Mar-26							
	HRS	9596.2	1500 (+25/-25)		11096.2	11121.2	1254.9 (+25)		
	AFL	7624							
PROC. REF: AMM 35-00-01PROC. REF: AMM 35-00-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 35 - OXYGEN									
5-19-00-Q3510018	PERFORM ** ICC HYDROSTATIC TEST ON CYLINDER (PER DOT EXEMPTION E8162) AND FUNCTIONALLY TEST OXYGEN CYLINDER LOW PRESSURE RELIEF VALVE. (EFFECTIVE ON AIRCRAFT EQUIPPED WITH INCREASED CAPACITY OXYGEN SYSTEM.) (AWL**)							Service	ATA:35
	MOS	13-Mar-26	60 (+14d/-14d)		13-Mar-31	27-Mar-31	1640 d (+14)		
	HRS	9596.2	5000 (+25/-25)		14596.2	14621.2	4754.9 (+25)		
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
5-19-00-Q3510023	OXYGEN CYLINDER REGULATOR - PERFORM OVERHAUL.							Service	ATA:35
	MOS	13-Mar-26	60 (+14d/-14d)		13-Mar-31	27-Mar-31	1640 d (+14)		
	HRS	9596.2	5000 (+25/-25)		14596.2	14621.2	4754.9 (+25)		
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
O3510003 ^S	** CABIN LOW PRESSURE OXYGEN DISTRIBUTION FLEX HOSES - PERFORM FUNCTIONAL TEST. (AWL**)							Service	ATA:35
	MOS	13-Mar-26	24 (+14d/-14d)					AIRWORTHINESS	
	HRS	9596.2	600 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 35-20-00PROC. REF: AMM 35-20-00									
S3510014 ^S	** OXYGEN SYSTEM ALTITUDE COMPENSATING REGULATOR - PERFORM FUNCTIONAL TEST. (AWL**)							Service	ATA:35
	MOS	13-Mar-26	24 (+14d/-14d)					AIRWORTHINESS	
	HRS	9596.2	600 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 35-20-00PROC. REF: AMM 35-20-00									
W3510002 ^S	** OXYGEN SYSTEM - PERFORM OPERATIONAL CHECK (AWL**)							Service	ATA:35
	MOS	13-Mar-26	24 (+14d/-14d)					AIRWORTHINESS	
	HRS	9596.2	600 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 35-00-00PROC. REF: AMM 35-00-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 35 - OXYGEN									
Y3510000	^S	OXYGEN CYLINDER INSTALLATION - PERFORM VISUAL INSPECTION. CHECK PLUMBING FOR ROUTING, SECURITY, AND CONDITION.						Service	ATA:35
	MOS	13-Mar-26	48 (+14d/-14d)						
	HRS	9596.2	1200 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 35-00-01PROC. REF: AMM 35-00-01									PKG:13
Y3510001	^S	CREW SEAT OXYGEN HOSES - PERFORM VISUAL INSPECTION. PAY PARTICULAR ATTENTION TO AREA WHERE OXYGEN HOSES ENTER CREW SEATS ABOVE COCKPIT FLOOR						Service	ATA:35
	MOS	13-Mar-26	12 (+14d/-14d)						
	HRS	9596.2	300 (+25/-25)						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:1
Y3510017	^S	OXYGEN CYLINDER INSTALLATION - PERFORM VISUAL INSPECTION. CHECK PLUMBING FOR ROUTING, SECURITY, AND CONDITION.						Service	ATA:35
	MOS	13-Mar-26	24 (+14d/-14d)						
	HRS	9596.2	600 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 35-00-01PROC. REF: AMM 35-00-01									PKG:7
ATA 36 - PNEUMATIC									
361031		ECS CONTROLLER						Component	ATA:36
PN:6636108500-003	MOS/MSC	13-Sep-22	O/C						
SN:366MF	HRS	8895.7							
	AFL	7135							
PROC. REF: AMM 36-10-01PROC. REF: AMM 36-10-01									
361041		NO. 1 HIGH PRESSURE SWITCH						Component	ATA:36
PN:642019-3	MOS/MSC	10-May-05	O/C	TSN 0					
SN:0765	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-10-06PROC. REF: AMM 36-10-06									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 36 - PNEUMATIC									
361042	NO. 2 HIGH PRESSURE SWITCH							Component	ATA:36
PN:642019-3	MOS/MSC	10-May-05	O/C	TSN 0					
SN:0750	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-10-06PROC. REF: AMM 36-10-06									
361053	NO. 1 ECS SHUT-OFF (L37) VALVE							Component	ATA:36
PN:6621000000-061	MOS/MSC	10-May-05	O/C	TSN 0					
SN:729	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-10-03PROC. REF: AMM 36-10-03									
361054	NO. 2 ECS SHUT-OFF (L38) VALVE							Component	ATA:36
PN:6621000000-061	MOS/MSC	10-May-05	O/C	TSN 0					
SN:731	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-10-03PROC. REF: AMM 36-10-03									
361065	LEFT TAILCONE HIGH PRESSURE SHUT-OFF VALVE							Component	ATA:36
PN:6621000000-092	MOS/MSC	30-Aug-13	O/C						
SN:771	HRS	5687.42							
	AFL	4640							
PROC. REF: AMM 36-10-02PROC. REF: AMM 36-10-02									
361066	RIGHT TAILCONE HIGH PRESSURE SHUT-OFF VALVE							Component	ATA:36
PN:3291216-2	MOS/MSC	26-May-22	O/C						
SN:1274C	HRS	8787.3							
	AFL	7061							
PROC. REF: AMM 36-10-02PROC. REF: AMM 36-10-02									
361160	LEFT OZONE CONVERTER							Component	ATA:36
PN:53A405-4	MOS/MSC	15-Mar-18	O/C	TSO 0					
SN:0497-1008	HRS	7205.4		TSO 0					
	AFL	5847		TSO 0					
PROC. REF: AMM 21-20-12PROC. REF: AMM 21-20-12									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 36 - PNEUMATIC									
361160A	TEST LEFT OZONE CONVERTER EFFICIENCY (Y2140001)								Service ATA:36
PN:53A405-4	MOS	15-Mar-18							
SN:0497-1008	HRS	7205.4	3600 (+25/-25)		10805.4	10830.4	964.1 (+25)		
	AFL	5847							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
361161	RIGHT OZONE CONVERTER								Component ATA:36
PN:53A405-4	MOS/MSC	15-Mar-18	O/C	TSO 0					
SN:0504-1015	HRS	7205.4		TSO 0					
	AFL	5847		TSO 0					
PROC. REF: AMM 21-20-12PROC. REF: AMM 21-20-12									
361161A	TEST RIGHT OZONE CONVERTER EFFICIENCY (Y2140001)								Service ATA:36
PN:53A405-4	MOS	15-Mar-18							
SN:0504-1015	HRS	7205.4	3600 (+25/-25)		10805.4	10830.4	964.1 (+25)		
	AFL	5847							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
361215	LEFT HIGH PRESSURE BLEED AIR MANIFOLD ASSEMBLY								Component ATA:36
PN:LJ01212-001	MOS/MSC	10-May-05	O/C	TSN 0					
SN:281204-002	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-10-07PROC. REF: AMM 36-10-07									
361216	RIGHT HIGH PRESSURE BLEED AIR MANIFOLD ASSEMBLY								Component ATA:36
PN:LJ01317-002	MOS/MSC	16-Mar-26	O/C						
SN:UNKNOWN	HRS	9596.2		TSN 11421.6					
	AFL	7624		TSN 7965					
PROC. REF: AMM 36-10-07PROC. REF: AMM 36-10-07									
361337	LEFT SERVO AIR CHECK VALVE								Component ATA:36
PN:6608295-3	MOS/MSC	11-Jun-08	O/C						
SN:2677	HRS	2192.67							
	AFL	1781							
PROC. REF: AMM 36-15-02PROC. REF: AMM 36-15-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR
Serial: 45-2027
RegNo: N116PJ
HRS: 9841.3
AFL: 7790
As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 36 - PNEUMATIC									
361337A	REPLACE LEFT SERVO AIR CHECK VALVE (K3610012)								Service ATA:36
PN:6608295-3	MOS/MSC	11-Jun-08	O/C						
SN:2677	HRS	2192.67							
	AFL	1781							
PROC. REF: AMM 36-15-02PROC. REF: AMM 36-15-02									
361357	RIGHT SERVO AIR CHECK VALVE								Component ATA:36
PN:6608295-3	MOS/MSC	11-Jun-08	O/C						
SN:2194	HRS	2192.67							
	AFL	1781							
PROC. REF: AMM 36-15-02PROC. REF: AMM 36-15-02									
361357A	REPLACE RIGHT SERVO AIR CHECK VALVE (K3610012)								Service ATA:36
PN:6608295-3	MOS/MSC	11-Jun-08	O/C						
SN:2194	HRS	2192.67							
	AFL	1781							
PROC. REF: AMM 36-15-02PROC. REF: AMM 36-15-02									
5-19-00-P3610048	PERFORM VISUAL INSPECTION HIGH PRESSURE BLEED AIR MANIFOLD ASSEMBLY								Service ATA:36
	MOS	13-Mar-26							
	HRS	9596.2	3500 (+100/-100)		13096.2	13196.2	3254.9 (+100)		
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
A3610000 ^S	** BLEED AIR SYSTEM - PERFORM FUNCTIONAL TEST (AWL**)								Service ATA:36
	MOS	13-Mar-26	24 (+14d/-14d)					AIRWORTHINESS	
	HRS	9596.2	600 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 36-10-00PROC. REF: AMM 36-10-00									
A3610001 ^S	** PYLON OVERHEAT THERMOSTAT AND ELECTRICAL SYSTEM - PERFORM FUNCTIONAL TEST (AWL**)								Service ATA:36
	MOS	13-Mar-26	24 (+14d/-14d)					AIRWORTHINESS	
	HRS	9596.2	600 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 36-20-01PROC. REF: AMM 36-20-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 36 - PNEUMATIC									
U3610075	^S	BORESCOPE INSPECTION ECS BLEED AIR "Y" MANIFOLD (P/N 12945-054-019, 12945-054-025, 12945-054-031, 129-054-037, 12945-054V1-001, 12945-054V2-001, 12945-054V6-001, 4536102027-001)						Service	ATA:36
	MOS	13-Mar-26							
	HRS	9596.2	4800 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 36-10-00PROC. REF: AMM 36-10-00									PKG:25

Y3610061	^S	HIGH PRESSURE BLEED AIR SHUT-OFF VALVE IN-LINE FILTER - PERFORM CLEANING PROCEDURES						Service	ATA:36
	MOS	13-Mar-26	24 (+14d/-14d)						
	HRS	9596.2	600 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 36-10-02PROC. REF: AMM 36-10-02									PKG:8

ATA 38 - WATER/WASTE

382016	LAVATORY HOT WATER TANK							Component	ATA:38
PN:AR9061-1	MOS/MSC	02-Aug-05	O/C						
SN:0028	HRS	31.7		TSR 0					
	AFL	22		TSR 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

383001	TOILET ASSEMBLY							Component	ATA:38
PN:663830300-005	MOS/MSC	05-Jul-18	O/C						
SN:U2395	HRS	7338.4							
	AFL	5941							
PROC. REF: AMM 38-30-01PROC. REF: AMM 38-30-01									

383014	TOILET TIMER							Component	ATA:38
PN:7638303002-009	MOS/MSC	18-Jul-05	O/C	TSN 0					
SN:T3891	HRS	18.9		TSN 0					
	AFL	15		TSN 0					
PROC. REF: AMM 38-30-02PROC. REF: AMM 38-30-02									

ATA 52 - DOORS

5-19-02-RVSM-M5240004	INSPECT AVIONIC ACCESS DOOR GAP AND MISMATCH (IRN M5240004)							Service	ATA:52
	MOS	09-Mar-26	24 (+14d/-14d)	09-Mar-28	23-Mar-28	541 d (+14)			

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 52 - DOORS									
	HRS	9596.1							
	AFL	7623							
PROC. REF: AMM 52-40-01PROC. REF: AMM 52-40-01									
521001	UPPER CABIN ASSEMBLY DOOR								Component ATA:52
PN:4552101000-003	MOS/MSC	10-May-05	O/C	TSN 0					
SN:W295	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
521002	LOWER CABIN ASSEMBLY DOOR								Component ATA:52
PN:4552100300-001	MOS/MSC	10-May-05	O/C	TSN 0					
SN:W281	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
5210053	CABIN DOOR HANDLE - REPLACE								Service ATA:52
	MOS	03-Sep-21	144 (+14d/-14d)	Adj -126d	30-Apr-33	14-May-33	2419 d (+14)		
	HRS	8435.1							
	AFL	6787	6000 (+25/-25)		12787	12812	4997 (+25)		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
521301	LEFT INBOARD MAIN GEAR DOOR								Component ATA:52
PN:4552803004-003	MOS/MSC	10-May-05	O/C	TSN 0					
SN:665478900295	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 52-80-01PROC. REF: AMM 52-80-01									
521302	RIGHT INBOARD MAIN GEAR DOOR								Component ATA:52
PN:4552803004-004	MOS/MSC	10-May-05	O/C	TSN 0					
SN:665480800295	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 52-80-01PROC. REF: AMM 52-80-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 52 - DOORS									
521303	LEFT OUTBOARD MAIN GEAR DOOR							Component	ATA:52
PN:4552803003-003	MOS/MSC	10-May-05	O/C	TSN 0					
SN:223824400295	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 52-80-01PROC. REF: AMM 52-80-01									
521304	RIGHT OUTBOARD MAIN GEAR DOOR							Component	ATA:52
PN:4552803003-004	MOS/MSC	27-Mar-15	O/C						
SN:939663300517	HRS	6705.27							
	AFL	5447							
PROC. REF: AMM 52-80-01PROC. REF: AMM 52-80-01									
522001	EMERGENCY EXIT ASSEMBLY DOOR							Component	ATA:52
PN:4552200076V36-001	MOS/MSC	10-May-05	O/C	TSN 0					
SN:L2027	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 52-20-01PROC. REF: AMM 52-20-01									
523001	ASSEMBLY, TAILCONE BAGGAGE DOOR							Component	ATA:52
PN:12045-557V1-001X01	MOS/MSC	10-May-05	O/C	TSN 0					
SN:0315	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
524001	TAILCONE ACCESS DOOR							Component	ATA:52
PN:4552405151-009	MOS/MSC	10-May-05	O/C	TSN 0					
SN:0315	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 52-40-02PROC. REF: AMM 52-40-02									
A5210009 ^S	* EMERGENCY EXIT DOOR RETAINERS - PERFORM VISUAL INSPECTION. INSPECT DOOR STOP FITTINGS ON EMERGENCY EXIT DOOR FRAMES IN FLANGE RADII. (FS 374 AND 394) (AWL*)							Service	ATA:52
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR
Serial: 45-2027
RegNo: N116PJ
HRS: 9841.3
AFL: 7790
As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 52 - DOORS									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
A5210012 ^S	* LOWER PASSENGER DOOR HINGE - PERFORM VISUAL INSPECTION. INSPECT PIANO HINGE LUGS AND FASTENERS (AWL*)							Service	ATA:52
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:26
A5210014 ^S	* UPPER PASSENGER DOOR TENSION FITTINGS - VISUAL INSPECTION. INSPECT THE FOLLOWING:A. TENSION STUDS AT RETAINING FLANGES.B. RADII AROUND FLANGE PERIPHERY (AWL*)							Service	ATA:52
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:26
AA5210055 ^S	CABIN DOOR HANDLE RAMP ROLLER WHEEL - LUBRICATION							Service	ATA:52
	MOS	13-Mar-26	48						
	HRS	9596.2	1200						
	AFL	7624							
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02									PKG:18
D5210015 ^S	* EMERGENCY EXIT DOOR - PERFORM VISUAL INSPECTION. PAY PARTICULAR ATTENTION TO FLANGES AND FASTENER HOLES OF DOOR STOP FITTINGS (AWL*)							Service	ATA:52
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	4800						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:25
E5210013 ^S	* UPPER AND LOWER PASSENGER DOOR LATCH ARMS AND DOOR ATTACHMENTS - PERFORM VISUAL INSPECTION (AWL*)							Service	ATA:52
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	4800						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:25

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 52 - DOORS									
F5210016	^S	* UPPER PASSENGER DOOR HINGE - PERFORM VISUAL INSPECTION. INSPECT UPPER SURFACE OF HINGE FINGERSAT BASE OF LUG (AWL*)						Service	ATA:52
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:26
N5210010	^S	* LOWER PASSENGER DOOR TENSION BOLTS, BOLT RETAINERS, TENSION FITTINGS, AND DOOR ATTACHMENTS - PERFORM VISUAL INSPECTION (AWL*)						Service	ATA:52
	MOS	13-Mar-26	96					AIRWORTHINESS	
	HRS	9596.2	2400						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:24
N5210011	^S	* UPPER AND LOWER PASSENGER DOOR LATCH PINS - PERFORM VISUAL INSPECTION. INSPECT BOLTS AND DOOR END RIB STRUCTURE AT LOCK PINS. (AWL*)						Service	ATA:52
	MOS	13-Mar-26	96					AIRWORTHINESS	
	HRS	9596.2	2400						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:24
N5210017	^S	* UPPER PASSENGER DOOR TENSION BOLTS, BOLT RETAINERS, TENSION FITTINGS, AND DOOR ATTACHMENTS - PERFORM VISUAL INSPECTION. (AWL*)						Service	ATA:52
	MOS	13-Mar-26	96					AIRWORTHINESS	
	HRS	9596.2	2400						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:24
T5210003	^S	EXTERNAL LOWER PASSENGER/CREW DOOR CABLES - PERFORM VISUAL INSPECTION OF VISIBLE PORTION OF CABLES AND HANDLE AREA.						Service	ATA:52
	MOS	13-Mar-26	48 (+14d/-14d)						
	HRS	9596.2	1200 (+25/-25)						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:18

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 52 - DOORS									
Y5210000 ^S	AVIONICS COMPARTMENT ACCESS DOORS AND SEALS - PERFORM VISUAL INSPECTION.								Service ATA:52
	MOS	13-Mar-26	48 (+14d/-14d)						
	HRS	9596.2	1200 (+25/-25)						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
PKG:13									
Y5210001 ^S	TAILCONE ACCESS DOOR AND SEAL - PERFORM VISUAL INSPECTION OF DOOR, SEALS, AND LATCHES.								Service ATA:52
	MOS	13-Mar-26	24 (+14d/-14d)						
	HRS	9596.2	600 (+25/-25)						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
PKG:12									
Y5210002 ^S	BAGGAGE COMPARTMENT DOOR - PERFORM VISUAL INSPECTION OF DOORS, SEALS, AND LATCHES.								Service ATA:52
	MOS	13-Mar-26	24 (+14d/-14d)						
	HRS	9596.2	600 (+25/-25)						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
PKG:12									
Y5210004 ^S	UPPER AND LOWER PASSENGER/CREW DOOR - PERFORM VISUAL INSPECTION OF DOOR STRUCTURE, TENSION FITTINGS, AND HINGE AREA FOR CRACKS AND CORROSION.								Service ATA:52
	MOS	13-Mar-26	48 (+14d/-14d)						
	HRS	9596.2	1200 (+25/-25)						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
PKG:18									
Y5210005 ^S	INTERNAL LOWER PASSENGER/CREW DOOR CABLES - PERFORM VISUAL INSPECTION. REMOVE STEP SKIN TO GAIN ACCESS TO CABLES.								Service ATA:52
	MOS	13-Mar-26	48 (+14d/-14d)						
	HRS	9596.2	1200 (+25/-25)						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
PKG:18									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 52 - DOORS									
Y5210006	^S	UPPER PASSENGER/CREW DOOR VENT DOOR SPRINGS - PERFORM VISUAL INSPECTION.						Service	ATA:52
	MOS	13-Mar-26	24	(+14d/-14d)					
	HRS	9596.2	600	(+25/-25)					
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:12
Y5210008	^S	PERFORM EMERGENCY EXIT DOOR INTERNAL AND EXTERNAL HANDLE LATCHING MECHANISM - PERFORM OPERATIONAL CHECK						Service	ATA:52
	MOS	13-Mar-26	24	(+14d/-14d)					
	HRS	9596.2	600	(+25/-25)					
	AFL	7624							
PROC. REF: AMM 52-20-07PROC. REF: AMM 52-20-07									PKG:12
Y5240000	^S	OXYGEN SYSTEM SERVICING DOOR AND LATCHES - PERFORM VISUAL INSPECTION FOR CONDITION AND SECURITY. CHECK DECAL FOR CONDITION AND LEGIBILITY.						Service	ATA:52
	MOS	13-Mar-26	48	(+14d/-14d)					
	HRS	9596.2	1200	(+25/-25)					
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:13
Y5240003	^S	SINGLE POINT REFUELING ACCESS DOOR - PERFORM VISUAL INSPECTION.						Service	ATA:52
	MOS	13-Mar-26	48	(+14d/-14d)					
	HRS	9596.2	1200	(+25/-25)					
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:14
ATA 53 - FUSELAGE									
5-19-00-H5323032		* EXTERIOR CABIN WINDOW COAMING (UNPAINTED) - PERFORM EDDY CURRENT INSPECTION (H5323032) (AWL*)						Service	ATA:53
	MOS	13-Mar-26	24		13-Mar-28		545 d	AIRWORTHINESS	
	HRS	9596.2	2400		11996.2		2154.9		
	AFL	7624							
PROC. REF: NDT PART 6/56-20-01PROC. REF: NDT PART 6/56-20-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR
Serial: 45-2027
RegNo: N116PJ
HRS: 9841.3
AFL: 7790
As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
5-19-00-H5323092		*EXTERIOR CABIN WINDOW COAMING (PAINTED) - PERFORM EDDY CURRENT INSPECTION (IRN H5323092) (AWL*)						Service	ATA:53
	MOS/MSC	10-May-05	N/A						
	HRS	0							
	AFL	0							
PROC. REF: NDT PART 6/56-20-01PROC. REF: NDT PART 6/56-20-01									
5-19-00-T5323166		* EXTERNAL SKIN CUT-OUTS/PENETRATIONS (PRESSURE CABIN) - PERFORM DETAILED VISUAL INSPECTION. INSPECT SKIN AND DOUBLERS AT ANTENNAS, ELECTRICAL COMPONENTS, AND ACCESS PANELS. (EXCLUDING PITOT/ STATIC PROBES, AOA STALL VANES, AND WING INSPECTION LIGHT) (AWL*)						Service	ATA:53
	MOS	01-May-17	144		01-May-29		959 d	MANDATORY	
	HRS	6994.7	9600		16594.7		6753.4		
	AFL	5681							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
5-19-00-V5323168		* LOWER COUPE RAIL RADIUS/WINDSCREEN RETAINER ATTACH - PERFORM EDDY CURRENT INSPECTION (P/N 4553130001-802 THRU 4553130001-809) (AWL*)						Service	ATA:53
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	5000		14596.2		4754.9		
	AFL	7624							
PROC. REF: NDT PART 6/53-30-23, NDT PART 6/53-30-24PROC. REF: NDT PART 6/53-30-23, NDT PART 6/53-30-24									
5-19-01-U5323167-LEFT		* LEFT COUPE RAIL (4553002003V7000-001). REPLACE (AWL*)						Component	ATA:53
PN:PN	MOS/MSC	10-May-05	N/A	TSN 0				NOT APPLICABLE	
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
5-19-01-U5323167-RIGHT		*RIGHT COUPE RAIL (4553002003V7001-002). REPLACE (AWL*)						Component	ATA:53
PN:PN	MOS/MSC	10-May-05	N/A	TSN 0				NOT APPLICABLE	
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
5-19-02-RVSM-M5313001		PERFORM PITOT-STATIC PROBE ZONE SKIN CONTOUR CHECK (IRN M5313001)						Service	ATA:53
	MOS	13-Jan-26	24 (+14d/-14d)		13-Jan-28	27-Jan-28	485 d (+14)		
	HRS	9594.9							
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
PROC. REF: AMM 53-00-01PROC. REF: AMM 53-00-01									
530001	ASSEMBLY FUSELAGE							Component	ATA:53
PN:4553000010-001	MOS/MSC	10-May-05	O/C	TSN 0					
SN:L2027	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
535001	RADOME							Component	ATA:53
PN:6634408000-005	MOS/MSC	30-Jul-13	O/C						
SN:0254	HRS	5607.75							
	AFL	4568							
PROC. REF: AMM 53-50-01PROC. REF: AMM 53-50-01									
535601	LEFT DELTA FIN							Component	ATA:53
PN:4555501000-015	MOS/MSC	10-May-05	O/C	TSN 0					
SN:S7549/A0070	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 53-56-01PROC. REF: AMM 53-56-01									
535602	RIGHT DELTA FIN							Component	ATA:53
PN:4555501000-016	MOS/MSC	10-May-05	O/C	TSN 0					
SN:S7549/A0070	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 53-56-01PROC. REF: AMM 53-56-01									
A5310005 ^S	* FUSELAGE FUEL CELL CANTED BULKHEAD (FS 495) - PERFORM VISUAL INSPECTION, PAYING PARTICULAR ATTENTION TO MAIN CROSSMEMBER. INSPECT FLANGES AND ATTACHMENTSFOR CRACKING (AWL*)							Service	ATA:53
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	4800						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
PKG:25									

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
A5310007	^S	* AFT PRESSURE BULKHEAD BOTTOM SHEAR DIAPHRAGM - PERFORM DETAILED VISUAL INSPECTION. INSPECT BULKHEAD POST ATTACHMENT FASTENER HOLES AND CONTROL CABLE SLOT (AWL *)						Service	ATA:53
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:26
A5323023	^S	* DRAG LINK ATTACHMENT LUG - PERFORM VISUAL INSPECTION (AWL *)						Service	ATA:53
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	4800						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:25
A5360001	^S	WITH DELTA FINS REMOVED, VISUALLY INSPECT THE FOLLOWING:A. DELTA FIN AFT SPAR.B. DELTA FIN SUPPORT ANGLE.C. INSPECT STIFFENERS CONNECTING TO ATTACH FITTINGS						Service	ATA:53
	MOS	13-Mar-26							
	HRS	9596.2	9600 (+25/-25)						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:26
E5310001	^S	* LONGERON, INTERNAL (BETWEEN FS 384 AND FS 433) - PERFORM VISUAL INSPECTION (AWL *)						Service	ATA:53
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:26
E5310017	^S	* AFT PRESSURE BULKHEAD BOTTOM CROSSMEMBER (FS 457) - PERFORM DETAILED VISUAL INSPECTION. INSPECT TEE-SECTION AT FS 457 FLANGE AT ATTACHMENT TO PRESSURE FLOOR. (AWL *)						Service	ATA:53
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:26

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR
Serial: 45-2027
RegNo: N116PJ
HRS: 9841.3
AFL: 7790
As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
E5310018	^S	* AFT PRESSURE BULKHEAD PANEL FACING SHEETS (FS 457) - PERFORM VISUAL INSPECTION. INSPECT BOTH FRONT AND AFT OF FACING SHEETS (AWL*)						Service	ATA:53
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:26
E5323050	^S	* AFT POST/WINDSHIELD RETAINER ATTACHMENT - WITH HEADLINER REMOVED, PERFORM EDDY CURRENT INSPECTION (AWL*)						Service	ATA:53
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	4800						
	AFL	7624							
PROC. REF: NDT PART 6/53-30-04PROC. REF: NDT PART 6/53-30-04									PKG:25
E5323068	^S	* STRINGER 1 RH BETWEEN FS 533 AND FS 543 - PERFORM VISUAL INSPECTION. INSPECT STRINGER 1 FLANGE AND SKIN ALONG STRINGER 1 BETWEEN FS 533 AND FS 543 (AWL*)						Service	ATA:53
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:26
E5323073	^S	* FUSELAGE BOTTOM SKIN PANEL - PERFORM VISUAL INSPECTION. INSPECT CORNER RADIUS AT JUNCTION OF EXTERNAL LONGERON AND MID SPAR FRAME (FS 435) (AWL*)						Service	ATA:53
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:26
E5323074	^S	* AUXILIARY SKIN PANEL - PERFORM VISUAL INSPECTION. INSPECT CORNER RADIUS AT JUNCTION OF KEEL BEAM AND REAR SPAR FRAME (FS 466) (AWL*)						Service	ATA:53
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:26

? - Insufficient Information
S - Suppressed Requirement
* - Estimated Due(New Requirement)
(EFF) - Effective C / W
(M) - Manual Due
U - User Task
Ex - Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
E5350000	^S	* BOTTOM KEELBEAM END PADS (FS 384 - FS 486) - PERFORM VISUAL INSPECTION. INSPECT END PADS AROUND BOLT HOLES AND IN RADII AT FS 433. (AWL*)						Service	ATA:53
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:26
F5323081	^S	* TIE-ROD FORK ENDS (TITANIUM, P/N R24889) - PERFORM FLUORESCENT PENETRANT INSPECTION (AWL*)						Service	ATA:53
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: NDT PART 8/53-10-01PROC. REF: NDT PART 8/53-10-01									PKG:26
F5331021	^S	* FORWARD CANTED BULKHEAD (FS 630) - PERFORM VISUAL INSPECTION. INSPECT AT FRONT SPAR ATTACHMENT FASTENERS (AWL*)						Service	ATA:53
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	4800						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:25
F5331022	^S	* MID CANTED BULKHEAD (FS 657) - PERFORM VISUAL INSPECTION AT MID SPAR UPPER ATTACHMENT FASTENERS (AWL*)						Service	ATA:53
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:26
F5331023	^S	* AFT CANTED BULKHEAD (FS 682) - PERFORM VISUAL INSPECTION. INSPECT AT REAR SPAR ATTACHMENT FASTENERS (AWL*)						Service	ATA:53
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:26

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
F5331024	^S	* VERTICAL STABILIZER FRONT ROOT BULKHEAD ATTACHMENT (FS 630) - PERFORM VISUAL INSPECTION. INSPECT FRONT SPAR ROOT BULKHEAD ATTACHMENT AT FASTENER HOLES (AWL*)						Service	ATA:53
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:26
F5331025	^S	* VERTICAL STABILIZER MID SPAR ROOT BULKHEAD ATTACHMENT (FS 657) - PERFORM VISUAL INSPECTION. INSPECT MID SPAR ROOT BULKHEAD ATTACHMENT AT FASTENER HOLES (AWL*)						Service	ATA:53
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:26
F5331026	^S	* VERTICAL STABILIZER REAR SPAR ROOT BULKHEAD ATTACHMENT (FS 682) - PERFORM VISUAL INSPECTION.INSPECT REAR SPAR ROOT BULKHEAD ATTACHMENT ATFASTENER HOLES (AWL*)						Service	ATA:53
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:26
J5310019	^S	* FLIGHT DECK LONGERON (FS 174 - FS 220.51) - PERFORM VISUAL INSPECTION. INSPECT FLIGHT DECK LONGERON STIFFENERS, WEBS, AND CUTOUTS (AWL*)						Service	ATA:53
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:26
J5323093	^S	* NOSE LANDING GEAR AFT WHEELBOX CLOSING STRUCTURE (FS 174 TO FS 186) - PERFORM VISUAL INSPECTION. INSPECT THE FOLLOWING:A. PANEL.B. CHANNEL STIFFENERS.C. SUPPORT ANGLE.D. ANGLE STIFFENER.E. ZEE STIFFENER. (AWL*)						Service	ATA:53
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:26

?-Insufficient Information

S-Suppressed Requirement

*-Estimated Due(New Requirement)

(EFF)-Effective C / W

(M)-Manual Due

U-User Task

Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
J5323094	^S	* FORWARD/AFT WHEELBOX JOINT (FS 174) - PERFORM VISUAL INSPECTION. INSPECT SPLICE STRAP AFT OF FORWARD PRESSURE BULKHEAD AT INTERSECTION OF ATTACHMENT ANGLE AND FLIGHT DECK LONGERON (AWL*)						Service	ATA:53
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:26
J5323095	^S	* UPPER AND LOWER PASSENGER/CREW DOOR SKIN CUTOUT CORNERS (F.S. 249 - F.S. 281) - PERFORM EDDY CURRENT INSPECTION. INSPECT SKIN AT CORNERS OF PASSENGER/CREW DOOR CUTOUT (AWL*)						Service	ATA:53
	MOS	13-Mar-26	96					AIRWORTHINESS	
	HRS	9596.2	2400						
	AFL	7624							
PROC. REF: NDT PART 6/53-30-02PROC. REF: NDT PART 6/53-30-02									PKG:19
J5323101	^S	* FRAME ATTACHMENTS TO UPPER AND LOWER COUPE RAILS (FS 195 TO FS 228) - PERFORM VISUAL INSPECTION. INSPECT THE FOLLOWING:A. FRAME ATTACHMENTS TO LOWER COUPE RAILS AT FS 195, FS 206, FS 221, AND FS 229.B. FRAME ATTACHMENTS TO UPPER COUPE RAILS AT FS 221 AND FS 229.C. GUSSETS AT FASTENER HOLES. (AWL*)						Service	ATA:53
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: NDT PART 6/53-30-03PROC. REF: NDT PART 6/53-30-03									PKG:26
J5323102	^S	* TIE-ROD ASSEMBLY (FS 186) (TITANIUM ENDS) - PERFORM VISUAL INSPECTION. INSPECT TIE-ROD ENDS, TIE-ROD TUBES, AND TIE-ROD BOLTS. (AWL*)						Service	ATA:53
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:26
L5311002	^S	* NOSE LANDING GEAR ACTUATOR ATTACHMENT ON FORWARD PRESSURE BULKHEAD - PERFORM EDDY CURRENT INSPECTION. INSPECT ACTUATOR ATTACHMENT BRACKET LUGS, RADII, AND FASTENER HOLES (AWL*)						Service	ATA:53
	MOS	10-May-05						AIRWORTHINESS	
	HRS	0							
	AFL	0	10000						
PROC. REF: NDT PART 6/32-12-00PROC. REF: NDT PART 6/32-12-00									PKG:27

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
---------	------	-------	----------	------------	----------------------------	-----------	-----------	-------------	----------

ATA 53 - FUSELAGE

L5311004	^S	* NOSE LANDING GEAR TRUNNION FITTINGS - PERFORM VISUAL INSPECTION OF THE TRUNNION FITTINGS AND ATTACHMENT BOLTS (AWL*)						Service	ATA:53
	MOS	10-May-05						AIRWORTHINESS	
	HRS	0							
	AFL	0	10000						

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

PKG:27

L5311005	^S	PERFORM * NOSE LANDING GEAR TRUNNION FITTINGS AND SUPPORT STRUCTURE - PERFORM EDDY CURRENT INSPECTION OF THE TRUNNION SUPPORT STRUCTURE AT THE FORWARD PRESSURE BULKHEAD FLANGE (AWL*)						Service	ATA:53
	MOS	10-May-05						AIRWORTHINESS	
	HRS	0							
	AFL	0	10000						

PROC. REF: NDT PART 6/32-12-05PROC. REF: NDT PART 6/32-12-05

PKG:27

M5323021	^S	* EXTERNAL LONGERON, FASTENER LOCATIONS, AND AREA AROUND WING ATTACHMENTS - PERFORM VISUAL INSPECTION. INSPECT LONGERON BETWEEN FS 398 AND FS 486, STRINGER 13 LHS & RHS (AWL*)						Service	ATA:53
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

PKG:26

M5323034	^S	* UPPER AND LOWER COUPE RAIL AND CENTER POST/WINDSHIELD RETAINER ATTACHMENT - PERFORM EDDY CURRENT INSPECTION. (AWL*)						Service	ATA:53
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							

PROC. REF: NDT PART 6/53-30-03PROC. REF: NDT PART 6/53-30-03

PKG:26

N5314000	^S	* EMERGENCY EXIT DOOR SKIN CUTOUT CORNERS AND DOUBLERS (FS 370 TO FS 398) - PERFORM EDDY CURRENTINSPECTION. (AWL*)						Service	ATA:53
	MOS	13-Mar-26	96					AIRWORTHINESS	
	HRS	9596.2	2400						
	AFL	7624							

PKG:19

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
PROC. REF: NDT PART 6/53-30-01PROC. REF: NDT PART 6/53-30-01									
P5310003	^S	* AFT PRESSURE BULKHEAD SUPPORT POST (FS 457) - PERFORM EDDY CURRENT INSPECTION (AWL*)						Service	ATA:53
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: NDT PART 6/53-30-18PROC. REF: NDT PART 6/53-30-18									
P5310004	^S	* AFT PRESSURE BULKHEAD FRAME PERIPHERY - PERFORM EDDY CURRENT INSPECTION. (AWL*)						Service	ATA:53
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	4800						
	AFL	7624							
PROC. REF: NDT PART 6/53-30-21PROC. REF: NDT PART 6/53-30-21									
P5310006	^S	* FORWARD PRESSURE BULKHEAD - PERFORM EDDY CURRENT INSPECTION. (AWL*)						Service	ATA:53
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: NDT PART 6/53-30-07PROC. REF: NDT PART 6/53-30-07									
P5320001	^S	* FUSELAGE PRESSURE FLOOR STEP (FS 433 - FS 457) - PERFORM EDDY CURRENT INSPECTION. (AWL*)						Service	ATA:53
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: NDT PART 6/53-20-01PROC. REF: NDT PART 6/53-20-01									
P5323024	^S	* FUSELAGE SKIN CUT-OUTS ABOVE FUEL CELL - PERFORM EDDY CURRENT INSPECTION. (AWL*)						Service	ATA:53
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	4800						
	AFL	7624							
PROC. REF: NDT PART 6/53-30-12PROC. REF: NDT PART 6/53-30-12									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR
Serial: 45-2027
RegNo: N116PJ
HRS: 9841.3
AFL: 7790
As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
P5323027	^S	* FUSELAGE FRAME AT FS 412 - PERFORM EDDY CURRENT INSPECTION. (AWL*)						Service	ATA:53
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	4800						
	AFL	7624							
PROC. REF: NDT PART 6/53-30-20PROC. REF: NDT PART 6/53-30-20									PKG:25
P5323029	^S	* MACHINED SPAR FRAMES SYSTEMS CUTOUTS (FS 398, FS 412, FS 432, FS 466) - PERFORM EDDY CURRENT INSPECTION. (AWL*)						Service	ATA:53
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	4800						
	AFL	7624							
PROC. REF: NDT PART 6/53-30-15PROC. REF: NDT PART 6/53-30-15									PKG:25
P5323033	^S	* FUSELAGE SKIN AT EMERGENCY DOOR EGRESS-LIGHT AND WING INSPECTION LIGHT - PERFORM EDDY CURRENTINSPECTION. (AWL*)						Service	ATA:53
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: NDT PART 6/53-40-02PROC. REF: NDT PART 6/53-40-02									PKG:26
P5323037	^S	* WINDSHIELD COUPE RAIL TIE ROD BRACKET - PERFORM EDDY CURRENT INSPECTION. (AWL*)						Service	ATA:53
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: NDT PART 6/53-30-09PROC. REF: NDT PART 6/53-30-09									PKG:26
P5323038	^S	* WINDSHIELD CENTERPOST TO UPPER COUPE RAIL JOINT ATTACHMENT - PERFORM EDDY CURRENT INSPECTION (AWL*)						Service	ATA:53
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	4800						
	AFL	7624							
PROC. REF: NDT PART 6/53-30-22PROC. REF: NDT PART 6/53-30-22									PKG:25

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C / W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
P5323047	^S	* PRESSURE CABIN FUSELAGE CROWN SKIN - PERFORM EDDY CURRENT INSPECTION (AWL*)						Service	ATA:53
	MOS	13-Mar-26	96					AIRWORTHINESS	
	HRS	9596.2	2400						
	AFL	7624							
PROC. REF: NDT PART 6/53-10-04PROC. REF: NDT PART 6/53-10-04									PKG:19
P5323049	^S	* FUSELAGE SKIN AT UPPER AND LOWER COUPE RAIL RUN-OUT JOINTS - PERFORM EDDY CURRENT INSPECTION. (AWL*)						Service	ATA:53
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: NDT PART 6/53-30-11PROC. REF: NDT PART 6/53-30-11									PKG:26
P5323057	^S	* PRESSURE CABIN SKIN AT FUSELAGE STATION 451 - PERFORM EDDY CURRENT INSPECTION (AWL*)						Service	ATA:53
	MOS	13-Mar-26	96					AIRWORTHINESS	
	HRS	9596.2	2400						
	AFL	7624							
PROC. REF: NDT PART 6/53-30-06PROC. REF: NDT PART 6/53-30-06									PKG:19
P5323058	^S	* FUSELAGE SKIN AT F.S. 504 - PERFORM EDDY CURRENT INSPECTION. (AWL*)						Service	ATA:53
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	4800						
	AFL	7624							
PROC. REF: NDT PART 6/53-30-13PROC. REF: NDT PART 6/53-30-13									PKG:25
P5323069	^S	* CIRCUMFERENTIAL SKIN JOINT AT FORWARD PRESSURE BULKHEAD - PERFORM EDDY CURRENT INSPECTION. (AWL*)						Service	ATA:53
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: NDT PART 6/53-30-08PROC. REF: NDT PART 6/53-30-08									PKG:26

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR
Serial: 45-2027
RegNo: N116PJ
HRS: 9841.3
AFL: 7790
As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
P5323164	^S	* FUSELAGE SKIN AND DOUBLER AROUND ECS DUCT CUTOUT - PERFORM EDDY CURRENT INSPECTION. (AWL*)						Service	ATA:53
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: NDT PART 6/53-40-01PROC. REF: NDT PART 6/53-40-01									
P5323165	^S	* WINDSHIELD CENTER POST TO LOWER COUPE RAIL JOINT ATTACHMENT - PERFORM EDDY CURRENT INSPECTION (AWL*)						Service	ATA:53
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: NDT PART 6/53-30-10PROC. REF: NDT PART 6/53-30-10									
P5360006	^S	DELTA FIN ATTACH BOLT - PERFORM LIQUID PENETRANT INSPECTION.						Service	ATA:53
	MOS	13-Mar-26							
	HRS	9596.2	9600 (+25/-25)						
	AFL	7624							
PROC. REF: NDT PART 8/53-10-02PROC. REF: NDT PART 8/53-10-02									
Q5310023	^S	FORWARD AND AFT FUEL CELL BAY STRUCTURE, ANGLE REINFORCEMENT, STRINGER 1, LH & RH - PERFORM DETAILED VISUAL INSPECTION OF HI-LITE COLLARS.						Service	ATA:53
	MOS	13-Mar-26							
	HRS	9596.2	9600 (+25/-25)						
	AFL	7624							
PROC. REF: AMM RSIP-HST79-104-2PROC. REF: AMM RSIP-HST79-104-2									
Q5310025	^S	AFT FUSELAGE KEELBEAM LONGERON (LH & RH, BL 5.15, FS 466.30 - 495.12) AND AFT FUSELAGE KEELBEAM LOWER FRAME (FS 466.30, BL 9.55 LH THRU BL 9.55 RH) - PERFORM DETAILED VISUAL INSPECTION OF HI-LITE COLLARS.						Service	ATA:53
	MOS	13-Mar-26							
	HRS	9596.2	9600 (+25/-25)						
	AFL	7624							
PROC. REF: AMM RSIP-HST79-104-3PROC. REF: AMM RSIP-HST79-104-3									

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C / W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
Q5323048	^S	* FUSELAGE (PRESSURE CABIN) - PERFORM EDDY CURRENT INSPECTION. INSPECT PRESSURE CABIN SKIN (LONGITUDINAL SKIN CRACKING). (AWL*)						Service	ATA:53
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	4800						
	AFL	7624							
PROC. REF: NDT PART 6/53-30-05PROC. REF: NDT PART 6/53-30-05									PKG:25
Q5323099	^S	* LONGITUDINAL JOINTS INSIDE PRESSURE CABIN (FS 244 - FS 457) AND SKIN WITHIN ONE STRINGER BAY OF JOINT - PERFORM EDDY CURRENT INSPECTION. INSPECT SKIN FASTENER HOLES ALONG JOINTS AT STRINGER 10 LH AND RH AND STRINGER 2 RH AND STRINGER 18 RH (AWL*)						Service	ATA:53
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	4800						
	AFL	7624							
PROC. REF: NDT PART 6/53-30-05PROC. REF: NDT PART 6/53-30-05									PKG:25
Q5323103	^S	* STRINGER TO FRAME JOINTS (FS 186 TO FS 237) - PERFORM EDDY CURRENT INSPECTION. INSPECT SKIN, STRINGERS, AND FRAMES AT JOINTS. (AWL*)						Service	ATA:53
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: NDT PART 6/53-30-05PROC. REF: NDT PART 6/53-30-05									PKG:26
T5310027	^S	* AFT PRESSURE BULKHEAD TOP MOUNTING STRUCTURE - PERFORM EDDY CURRENT INSPECTION (AWL*)						Service	ATA:53
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: NDT PART 6/53-30-17PROC. REF: NDT PART 6/53-30-17									PKG:26
T5321089	^S	SEAT RAILS - PERFORM DETAILED INSPECTION OF SEAT RAIL (TRACK) SHEAR WEBS FOR CRACKING.						Service	ATA:53
	MOS	13-Mar-26	24 (+14d/-14d)						
	HRS	9596.2	600 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 53-20-01PROC. REF: AMM 53-20-01									PKG:7

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR
Serial: 45-2027
RegNo: N116PJ
HRS: 9841.3
AFL: 7790
As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
T5323028 ^S		* FUSELAGE TO WING ATTACH FITTINGS - PERFORM EDDY CURRENT INSPECTION. (AWL*)						Service	ATA:53
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	4800						
	AFL	7624							
PROC. REF: NDT PART 6/53-30-16PROC. REF: NDT PART 6/53-30-16									PKG:25
V5323169 ^S		*FUSELAGE SKIN AT STRINGER AND FRAME LOCATIONS FS230.84 TO FS244.00 - PERFORM EDDY CURRENT INSPECTION. (EFFECTIVE ON AIRCRAFT 45-2006 ONLY) (AWL*)						Service	ATA:53
	MOS/MSC	13-Mar-26	N/A					AIRWORTHINESS	
	HRS	9596.2							
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:25
V5323170 ^S		*FUSELAGE SKIN AT STRINGER AND FRAME LOCATIONS FS349.12 TO FS377.54 - PERFORM EDDY CURRENT INSPECTION. (EFFECTIVE ON AIRCRAFT 45-2006 ONLY) (AWL*)						Service	ATA:53
	MOS/MSC	13-Mar-26	N/A					AIRWORTHINESS	
	HRS	9596.2							
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:25
V5323171 ^S		*STRINGER 10 AT FUSELAGE STATION FS345.39 TO 378.38 - PERFORM X-RAY INSPECTION. (EFFECTIVE ON AIRCRAFT 45-2006 ONLY) (AWL*)						Service	ATA:53
	MOS/MSC	13-Mar-26	N/A					AIRWORTHINESS	
	HRS	9596.2							
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:25
Y5311001 ^S		NOSE LANDING GEAR ACTUATOR ATTACH FITTING AND SURROUNDING STRUCTURE - PERFORM VISUAL INSPECTION.						Service	ATA:53
	MOS	13-Mar-26	48 (+14d/-14d)						
	HRS	9596.2	1200 (+25/-25)						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:17

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C / W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 40XR
Serial: 45-2027
RegNo: N116PJ
HRS: 9841.3
AFL: 7790
As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
Y5311003 ^S	NOSE LANDING GEAR TRUNNION FITTING AND SURROUNDING STRUCTURE - PERFORM VISUAL INSPECTION.								Service ATA:53
	MOS	13-Mar-26	48 (+14d/-14d)						
	HRS	9596.2	1200 (+25/-25)						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
Y5320000 ^S	CENTER PEDESTAL - PERFORM VISUAL INSPECTION								Service ATA:53
	MOS	13-Mar-26	12 (+14d/-14d)						
	HRS	9596.2	300 (+25/-25)						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
Y5321010 ^S	PERFORM FLOORBOARDS AROUND GALLEY, LAVATORY, AND WATER TANK - PERFORM VISUAL INSPECTION. NOTE: IF EVIDENCE OF SPILLAGE IS VISIBLE, PERFORM INSPECTION ON THE GALLEY AND LAVATORY AREAS FOR SPILLS AND CORROSION.								Service ATA:53
	MOS	13-Mar-26	12 (+14d/-14d)						
	HRS	9596.2	300 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 53-20-01PROC. REF: AMM 53-20-01									
Y5321011 ^S	TAILCONE BAGGAGE COMPARTMENT - PERFORM VISUAL INSPECTION.								Service ATA:53
	MOS	13-Mar-26	24 (+14d/-14d)						
	HRS	9596.2	600 (+25/-25)						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
Y5321088 ^S	SEAT RAILS - REMOVE FLOORBOARD 230AL AND PERFORM VISUAL INSPECTION OF SEAT RAILS. NOTE: IF CORROSION IS DETECTED, REMOVE ALL FLOORBOARDS AND INSPECT ALL SEAT RAILS.								Service ATA:53
	MOS	13-Mar-26	48 (+14d/-14d)						
	HRS	9596.2	1200 (+25/-25)						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?

Insufficient Information

S

Suppressed Requirement

*

Estimated Due(New Requirement)

(EFF)

Effective C / W

(M)

Manual Due

U

User Task

Ex

Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
Y5323031	^S	EXTERIOR CABIN WINDOW COAMINGS AND SURROUNDING FUSELAGE SKIN - PERFORM VISUAL INSPECTION USING 10X MAGNIFICATION AND ADEQUATE LIGHTING.						Service	ATA:53
	MOS	13-Mar-26	48 (+14d/-14d)						
	HRS	9596.2	1200 (+25/-25)						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:13
Y5323105	^S	EXTERNAL FUSELAGE (PRESSURE CABIN) - PERFORM VISUAL INSPECTION OF ALL CABIN SKINS FROM F.S. 124 TO F.S.458. PAY PARTICULAR ATTENTION TO ALL CUTOUTS AND SKIN JOINTS. NO FAIRING ACCESS REQUIRED.						Service	ATA:53
	MOS	13-Mar-26	48 (+14d/-14d)						
	HRS	9596.2	1200 (+25/-25)						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:13
Y5340007	^S	WING ATTACH FITTINGS - PERFORM VISUAL INSPECTION.						Service	ATA:53
	MOS	13-Mar-26	96 (+14d/-14d)						
	HRS	9596.2	2400 (+25/-25)						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:19
Y5360000	^S	DELTA FINS - PERFORM VISUAL INSPECTION.						Service	ATA:53
	MOS	13-Mar-26	24 (+14d/-14d)						
	HRS	9596.2	600 (+25/-25)						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:8
ATA 54 - NACELLES/PYLONS									
5-19-00-Q5450013-LEFT	^U	LEFT FORWARD ENGINE BEAM AND BEAM FITTING - PERFORM VISUAL INSPECTION, PAYING PARTICULAR ATTENTION TO THE FOLLOWING:A. UPPER CAPPING PLATE AT FASTENER HOLES, AND CHANNEL FLANGE AT FASTENER HOLESB. BOLT HOLES, ESPECIALLY UPPER BOLT HOLE ON AFT FLANGE(IRN Q5450013)						Service	ATA:54
	MOS/MSC	10-May-05	N/A						
	HRS	0							
	AFL	0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR
Serial: 45-2027
RegNo: N116PJ
HRS: 9841.3
AFL: 7790
As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 54 - NACELLES / PYLONS									
5-19-00-Q5450013-RIGHT	RIGHT FORWARD ENGINE BEAM AND BEAM FITTING - PERFORM VISUAL INSPECTION, PAYING PARTICULAR ATTENTION TO THE FOLLOWING:A. UPPER CAPPING PLATE AT FASTENER HOLES, AND CHANNEL FLANGE AT FASTENER HOLESB. BOLT HOLES, ESPECIALLY UPPER BOLT HOLE ON AFT FLANGE(IRN Q5450013)							Service	ATA:54
	MOS/MSC	10-May-05	N/A						
	HRS	0							
	AFL	0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
5-19-01-A5450022-LEFT	REPLACE * AFT ENGINE MOUNT TO END FITTING ATTACH BOLT (IRN A5450022) (AWL*)							Service	ATA:54
	MOS	13-Mar-26						LIFE LIMIT	
	HRS	9596.2	9600		19196.2		9354.9		
	AFL	7624							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
5-19-01-A5450022-RIGHT	REPLACE * AFT ENGINE MOUNT TO END FITTING ATTACH BOLT (IRN A5450022) (AWL*)							Service	ATA:54
	MOS	13-Mar-26						LIFE LIMIT	
	HRS	9596.2	9600		19196.2		9354.9		
	AFL	7624							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
5-19-01-P5450020-LEFT	REPLACE * AFT ENGINE BEAM TO FRAME ATTACHMENT BOLT (P5450020) (AWL*)							Service	ATA:54
	MOS	13-Mar-26						LIFE LIMIT	
	HRS	9596.2	9600		19196.2		9354.9		
	AFL	7624							
PROC. REF: NDT PART 8/54-30-01PROC. REF: NDT PART 8/54-30-01									
5-19-01-P5450020-RIGHT	REPLACE * AFT ENGINE BEAM TO FRAME ATTACHMENT BOLT (P5450020) (AWL*)							Service	ATA:54
	MOS	13-Mar-26						LIFE LIMIT	
	HRS	9596.2	9600		19196.2		9354.9		
	AFL	7624							
PROC. REF: NDT PART 8/54-30-01PROC. REF: NDT PART 8/54-30-01									
5-19-01-P5450023-LEFT	REPLACE * ENGINE TO AFT ENGINE MOUNT ATTACH BOLT (IRN P5450023) (AWL*)							Service	ATA:54
	MOS	13-Mar-26						LIFE LIMIT	
	HRS	9596.2	9600		19196.2		9354.9		
	AFL	7624							
PROC. REF: NDT PART 8/54-30-02PROC. REF: NDT PART 8/54-30-02									

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C / W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 54 - NACELLES/PYLONS									
5-19-01-P5450023-RIGHT	REPLACE * ENGINE TO AFT ENGINE MOUNT ATTACH BOLT (IRN P5450023) (AWL*)							Service	ATA:54
	MOS	13-Mar-26						LIFE LIMIT	
	HRS	9596.2	9600		19196.2		9354.9		
	AFL	7624							
PROC. REF: NDT PART 8/54-30-02PROC. REF: NDT PART 8/54-30-02									
5450054	LEFT FORWARD ENGINE BEAM AND BEAM FITTING - PERFORM VISUAL INSPECTION, PAYING PARTICULAR ATTENTION TO THE FOLLOWING: A. UPPER CAPPING PLATE AT FASTENER HOLES, AND CHANNEL FLANGE AT FASTENER HOLES B. BOLT HOLES, ESPECIALLY UPPER BOLT HOLE ON AFT FLANGE							Service	ATA:54
	MOS	07-Feb-14							
	HRS	5991.87	7000 (+100/-100)		12991.87	13091.87	3150.6 (+100)		
	AFL	4884							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
5450054	RIGHT FORWARD ENGINE BEAM AND BEAM FITTING - PERFORM VISUAL INSPECTION, PAYING PARTICULAR ATTENTION TO THE FOLLOWING:A. UPPER CAPPING PLATE AT FASTENER HOLES, AND CHANNEL FLANGE AT FASTENER HOLESB. BOLT HOLES, ESPECIALLY UPPER BOLT HOLE ON AFT FLANGE							Service	ATA:54
	MOS	07-Feb-14							
	HRS	5991.87	7000 (+100/-100)		12991.87	13091.87	3150.6 (+100)		
	AFL	4884							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
A5450026 ^S	* ENGINE DRAG STRUT - PERFORM EDDY CURRENT INSPECTION (AWL*)							Service	ATA:54
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	4800						
	AFL	7624							
PROC. REF: NDT PART 6/54-50-01PROC. REF: NDT PART 6/54-50-01									
E5450029 ^S	* AFT ENGINE BEAM - PERFORM VISUAL INSPECTION. INSPECT UPPER CAPPING PLATE, AROUND FASTENER HOLES IN THE CAPPING PLATE, AND CHANNEL FLANGE (AWL*)							Service	ATA:54
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	4800						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 54 - NACELLES / PYLONS									
F5450019	^S	* AFT ENGINE BEAM ATTACHMENT TO FRAMES - PERFORM VISUAL INSPECTION. INSPECT AFT ENGINE BEAM ATTACHMENT TO FRAMES (AWL*)						Service	ATA:54
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	4800						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:25
H5450012	^S	* FRAMES 39/40 (FS 512/518) AT ENGINE BEAM ATTACHMENT - PERFORM EDDY CURRENT INSPECTION. INSPECT OUTER FLANGE AND FRAME WEB AT ENGINE BEAM ATTACHMENT (AWL*)						Service	ATA:54
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	4800						
	AFL	7624							
PROC. REF: NDT PART 6/54-50-03PROC. REF: NDT PART 6/54-50-03									PKG:25
M5450015	^S	* FORWARD ENGINE BEAM, SPAR CAP, AND WEB - PERFORM EDDY CURRENT INSPECTION. (AWL*)						Service	ATA:54
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	4800						
	AFL	7624							
PROC. REF: NDT PART 6/54-50-05PROC. REF: NDT PART 6/54-50-05									PKG:25
M5450018	^S	*FORWARD ENGINE MOUNT ATTACHMENT BOLTS - PERFORM FLUORESCENT LIQUID PENETRANT INSPECTION (AWL*)						Service	ATA:54
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	4800						
	AFL	7624							
PROC. REF: NDT PART 8/71-20-01PROC. REF: NDT PART 8/71-20-01									PKG:25
P5450011	^S	* DRAG STRUT ATTACHMENT FITTINGS - PERFORM EDDY CURRENT INSPECTION. (AWL*)						Service	ATA:54
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	4800						
	AFL	7624							
PROC. REF: NDT PART 6/53-10-03PROC. REF: NDT PART 6/53-10-03									PKG:25

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR
Serial: 45-2027
RegNo: N116PJ
HRS: 9841.3
AFL: 7790
As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 54 - NACELLES / PYLONS									
P5450016	^S	*FORWARD ENGINE BEAM END FITTING - PERFORM EDDY CURRENT INSPECTION. (AWL*)						Service	ATA:54
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	4800						
	AFL	7624							
PROC. REF: NDT PART 6/54-50-02PROC. REF: NDT PART 6/54-50-02									PKG:25
P5450017	^S	* FORWARD ENGINE BEAM TO FRAME ATTACH BOLTS - PERFORM LIQUID PENETRANT INSPECTION (AWL*)						Service	ATA:54
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	4800						
	AFL	7624							
PROC. REF: NDT PART 8/53-40-01PROC. REF: NDT PART 8/53-40-01									PKG:25
P5450021	^S	* ENGINE AFT ISOLATOR MOUNT FITTINGS - PERFORM LIQUID PENETRANT INSPECTION. (AWL*)						Service	ATA:54
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	4800						
	AFL	7624							
PROC. REF: NDT PART 8/71-20-03PROC. REF: NDT PART 8/71-20-03									PKG:25
P5450024	^S	* FUSELAGE FRAMES AT FS 543.55 AND 546.15 TO AFT BEAM ATTACHMENT - PERFORM EDDY CURRENT INSPECTION (AWL*)						Service	ATA:54
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	4800						
	AFL	7624							
PROC. REF: NDT PART 6/53-30-14PROC. REF: NDT PART 6/53-30-14									PKG:25
P5450025	^S	* FORWARD ENGINE BEAM AND FRAMES AT ATTACH HOLES - PERFORM EDDY CURRENT INSPECTION (AWL*)						Service	ATA:54
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	4800						
	AFL	7624							
PROC. REF: NDT PART 6/54-50-03PROC. REF: NDT PART 6/54-50-03									PKG:25

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 54 - NACELLES / PYLONS									
P5450030	^S	* AFT ENGINE BEAM END FITTING - PERFORM EDDY CURRENT INSPECTION (AWL*)						Service	ATA:54
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	4800						
	AFL	7624							
PROC. REF: NDT PART 6/54-50-04PROC. REF: NDT PART 6/54-50-04									
PKG:25									
Y5410002	^S	PYLONS - PERFORM VISUAL INSPECTION. INSPECT HILITE COLLARS COMMON TO MAIN ENGINE BEAM EXTERNAL TO FUSELAGE						Service	ATA:54
	MOS	13-Mar-26	48 (+14d/-14d)						
	HRS	9596.2	1200 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 54-00-01PROC. REF: AMM 54-00-01									
PKG:14									
ATA 55 - STABILIZERS									
5-19-00-M5510010		* HORIZONTAL STABILIZER AFT ROOT RIB - PERFORM EDDY CURRENT INSPECTION. INSPECT AFT ROOT RIB INTERNAL BETWEEN MID SPAR AND AFT SPAR AND UPPER AND LOWER SKINS EXTERNAL AT ATTACHMENT FASTNERS. (IRN M5510010) (AWL*)						Service	ATA:55
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	1200		10796.2		954.9		
	AFL	7624							
PROC. REF: NDT PART 6/55-10-03PROC. REF: NDT PART 6/55-10-03									
5-19-00-M5540022		RUDDER TORQUE TUBE - PERFORM BORESCOPE INSPECTION						Service	ATA:55
	MOS/MSC	11-May-05	N/A						
	HRS	4185.15							
	AFL	3428							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
5-19-00-W5510091		* HORIZONTAL STABILIZER HINGE PRIMARY AND SECONDARY PIVOT PIN INSTALLATION AND ATTACHING HARDWARE - PERFORM DETAILED VISUAL INSPECTION (IRN W5510091) (AWL*)						Service	ATA:55
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	625		10221.2		379.9		
	AFL	7624							
PROC. REF: AMM 55-10-00PROC. REF: AMM 55-10-00									

?-Insufficient Information

S-Suppressed Requirement

*-Estimated Due(New Requirement)

(EFF)-Effective C / W

(M)-Manual Due

U-User Task

Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 55 - STABILIZERS									
5510034	HORIZONTAL STABILIZER PRIMARY AND SECONDARY BOLTS AND BUSHINGS - PERFORM DETAILED INSPECTION								Service ATA:55
	MOS	14-Mar-19							
	HRS	7551	4800 (+25/-25)		12351	12376	2509.7 (+25)		
	AFL								
PROC. REF: AMM 55-10-00PROC. REF: AMM 55-10-00									
551200	HORIZONTAL STABILIZER								Component ATA:55
PN:4555101002-027	MOS/MSC	10-May-23	O/C	TSN 216					
SN:S7549A0056	HRS	9071.3		TSN 9071.3					
	AFL	7252		TSN 7252					
PROC. REF: AMM 27-40-01PROC. REF: AMM 27-40-01									
552031	LEFT ELEVATOR								Component ATA:55
PN:4555201001V7003-001	MOS/MSC	10-May-23	O/C	TSN 216					
SN:S7549A0059	HRS	9071.3		TSN 9071.3					
	AFL	7252		TSN 7252					
PROC. REF: AMM 55-20-00PROC. REF: AMM 55-20-00									
552032	RIGHT ELEVATOR								Component ATA:55
PN:4555201001V7003-002	MOS/MSC	10-May-23	O/C	TSN 216					
SN:S7549A0059	HRS	9071.3		TSN 9071.3					
	AFL	7252		TSN 7252					
PROC. REF: AMM 55-20-00PROC. REF: AMM 55-20-00									
553001	VERTICAL ASSEMBLY, TAILCONE STABILIZER								Component ATA:55
PN:4555301001-001	MOS/MSC	10-May-05	O/C	TSN 0					
SN:A0055	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
554005	ASSEMBLY RUDDER								Component ATA:55
PN:4555401000-017	MOS/MSC	10-May-23	O/C	TSN 216					
SN:S7549A0063	HRS	9071.3		TSN 9071.3					
	AFL	7252		TSN 7252					
PROC. REF: AMM 27-20-01PROC. REF: AMM 27-20-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 55 - STABILIZERS									
A5510014	^S	* VERTICAL STABILIZER PIVOT FITTING BOTTOM PLATE - PERFORM DETAILED VISUAL INSPECTION. INSPECT AFT PORTION OF BOTTOM PLATE THROUGH LIGHTENING HOLE IN TOP PLATE, FORWARD PORTION OF BOTTOM PLATE THROUGH TOP PLATE CUTOUTS, AND BOTTOM OF OUTSIDE EXPOSED SURFACE OF PIVOT FITTING (AWL*)						Service	ATA:55
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:26
A5510021	^S	* HORIZONTAL MID SPAR FROM CANTED RIB #2 TO CANTED RIB #3 - PERFORM DETAILED VISUAL INSPECTION (AWL*)						Service	ATA:55
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:26
A5540000	^S	* RUDDER ROOT RIB CAP (FS 698) - PERFORM VISUAL INSPECTION. INSPECT AROUND FASTENER HOLES AND LIGHTENING HOLES (AWL*)						Service	ATA:55
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:26
E5510074	^S	* HORIZONTAL STABILIZER REAR SPAR FROM CANTED RIB #2 TO CANTED RIB #3 - PERFORM VISUAL INSPECTION. INSPECT REAR SPAR CAP AND FASTENERS (AWL*)						Service	ATA:55
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:26
E5510075	^S	* HORIZONTAL STABILIZER OUTBOARD SPARS AND SKINS OUTBOARD OF CANTED RIB #3 - PERFORM VISUAL INSPECTION. INSPECT SPAR CAPS AND FASTENERS. (AWL*)						Service	ATA:55
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:26

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 55 - STABILIZERS									
E5510076	^S	* HORIZONTAL STABILIZER FRONT SPAR FROM CANTED RIB #2 TO CANTED RIB #3 - PERFORM VISUAL INSPECTION. INSPECT FRONT SPAR CAP AND FASTENERS (AWL*)						Service	ATA:55
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:26
E5520003	^S	* ELEVATOR FRONT SPAR - PERFORM VISUAL INSPECTION. INSPECT SPAR CAP AT FASTENER HOLES (AWL*)						Service	ATA:55
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:26
E5520004	^S	* ELEVATOR RIB #1 CAP - PERFORM VISUAL INSPECTION OF RIB #1 CAP CROSS SECTION AND RIB CAP FLANGES AT TORQUE TUBE. (AWL*)						Service	ATA:55
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:26
G5510000	^S	* HORIZONTAL STABILIZER ACTUATOR ATTACHMENT FITTINGS - PERFORM EDDY CURRENT INSPECTION (AWL*)						Service	ATA:55
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	4800						
	AFL	7624							
PROC. REF: NDT PART 6/55-10-01PROC. REF: NDT PART 6/55-10-01									PKG:25
G5510023	^S	* HORIZONTAL STABILIZER ACTUATOR VERTICAL TAIL ATTACHMENT - PERFORM EDDY CURRENT INSPECTION (AWL*)						Service	ATA:55
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	4800						
	AFL	7624							
PROC. REF: NDT PART 6/55-30-01PROC. REF: NDT PART 6/55-30-01									PKG:25

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR
Serial: 45-2027
RegNo: N116PJ
HRS: 9841.3
AFL: 7790
As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 55 - STABILIZERS									
H5510033	^S	* HORIZONTAL STABILIZER ACTUATOR ATTACHMENT BOLTS - PERFORM LIQUID PENETRANT INSPECTION (AWL*)						Service	ATA:55
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	4800						
	AFL	7624							
PROC. REF: NDT PART 8/27-40-01PROC. REF: NDT PART 8/27-40-01									
N5510005	^S	* HORIZONTAL STABILIZER REAR SPAR CAP - PERFORM EDDY CURRENT INSPECTION. INSPECT REAR SPAR CAP AND WEB AT CENTER SPLICE. (AWL*)						Service	ATA:55
	MOS	13-Mar-26	96					AIRWORTHINESS	
	HRS	9596.2	2400						
	AFL	7624							
PROC. REF: NDT PART 6/55-10-05PROC. REF: NDT PART 6/55-10-05									
N5510015	^S	* VERTICAL STABILIZER PIVOT FITTING TOP PLATE - PERFORM EDDY CURRENT INSPECTION. (AWL*)						Service	ATA:55
	MOS	13-Mar-26	96					AIRWORTHINESS	
	HRS	9596.2	2400						
	AFL	7624							
PROC. REF: NDT PART 6/55-30-02PROC. REF: NDT PART 6/55-30-02									
N5510016	^S	* VERTICAL STABILIZER PIVOT FITTING TOWER SECTION FORWARD RADIUS - PERFORM EDDY CURRENT INSPECTION.INSPECT PIVOT FITTING AT TOWER SECTION RADIUS,PIVOT FITTING AND TOP PLATE AROUND ADJACENT FASTENERS,AND PIVOT FITTING SIDES AT TOWER SECTION RADIUS. (AWL*)						Service	ATA:55
	MOS	13-Mar-26	96					AIRWORTHINESS	
	HRS	9596.2	2400						
	AFL	7624							
PROC. REF: NDT PART 6/55-30-03PROC. REF: NDT PART 6/55-30-03									
N5510069	^S	* HORIZONTAL STABILIZER MID SPAR FLANGE ROOT RIB ATTACHMENT - PERFORM EDDY CURRENT INSPECTION. (AWL*)						Service	ATA:55
	MOS	13-Mar-26	96					AIRWORTHINESS	
	HRS	9596.2	2400						
	AFL	7624							
PROC. REF: NDT PART 6/55-10-02PROC. REF: NDT PART 6/55-10-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 55 - STABILIZERS									
N5510082 ^S		* HORIZONTAL STABILIZER REAR SPAR FLANGE ROOT RIB ATTACHMENT -PERFORM EDDY CURRENT INSPECTION. (AWL*)						Service	ATA:55
	MOS	13-Mar-26	96					AIRWORTHINESS	
	HRS	9596.2	2400						
	AFL	7624							
PROC. REF: NDT PART 6/55-10-04PROC. REF: NDT PART 6/55-10-04									PKG:20
P5510006 ^S		* VERTICAL STABILIZER FRONT SPAR AND MID SPAR - PERFORM RADIOGRAPHIC INSPECTION (AWL*)						Service	ATA:55
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: NDT PART 2/55-30-01PROC. REF: NDT PART 2/55-30-01									PKG:26
P5510008 ^S		* HORIZONTAL STABILIZER PRIMARY AND SECONDARY ATTACH BOLTS - PERFORM MAGNETIC PARTICLE INSPECTION (AWL*)						Service	ATA:55
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: NDT PART 7/55-30-02, NDT PART 7/55-30-03PROC. REF: NDT PART 7/55-30-02, NDT PART 7/55-30-03									PKG:26
P5510009 ^S		* HORIZONTAL STABILIZER MID SPAR CAP B.L. 0.0 TO B.L. 4.0 - PERFORM X-RAY INSPECTION (AWL*)						Service	ATA:55
	MOS	13-Mar-26	96					AIRWORTHINESS	
	HRS	9596.2	2400						
	AFL	7624							
PROC. REF: NDT PART 2/55-10-03PROC. REF: NDT PART 2/55-10-03									PKG:20
P5510011 ^S		* HORIZONTAL STABILIZER MID-SPAR AND REAR-SPAR UPPER FLANGE AT ROOT RIB - PERFORM RADIOGRAPHIC INSPECTION (AWL*)						Service	ATA:55
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: NDT PART 2/55-10-01PROC. REF: NDT PART 2/55-10-01									PKG:26

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 55 - STABILIZERS									
P5510017	^S	* VERTICAL STABILIZER PIVOT FITTING TOWER SECTION - PERFORM EDDY CURRENT INSPECTION (AWL*)						Service	ATA:55
	MOS	13-Mar-26	96					AIRWORTHINESS	
	HRS	9596.2	2400						
	AFL	7624							
PROC. REF: NDT PART 6/55-30-05PROC. REF: NDT PART 6/55-30-05									PKG:20
P5510018	^S	* VERTICAL STABILIZER PIVOT FITTING LUGS - PERFORM EDDY CURRENT INSPECTION (AWL*)						Service	ATA:55
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: NDT PART 6/55-30-04PROC. REF: NDT PART 6/55-30-04									PKG:26
P5510019	^S	* ELEVATOR HINGES ON HORIZONTAL STABILIZER - PERFORM EDDY CURRENT INSPECTION (AWL*)						Service	ATA:55
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: NDT PART 6/55-20-02PROC. REF: NDT PART 6/55-20-02									PKG:26
P5510020	^S	* HORIZONTAL MID-SPAR UPPER CAP - PERFORM EDDY CURRENT INSPECTION (AWL*)						Service	ATA:55
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: NDT PART 6/55-10-07PROC. REF: NDT PART 6/55-10-07									PKG:26
P5510024	^S	* ELEVATOR CONTROL HORN - PERFORM EDDY CURRENT INSPECTION (AWL*)						Service	ATA:55
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: NDT PART 6/55-20-01PROC. REF: NDT PART 6/55-20-01									PKG:26

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR
Serial: 45-2027
RegNo: N116PJ
HRS: 9841.3
AFL: 7790
As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 55 - STABILIZERS									
P5510070	^S	* HORIZONTAL STABILIZER FRONT SPAR - PERFORM RADIOGRAPHIC INSPECTION (AWL*)						Service	ATA:55
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: NDT PART 2/55-10-02PROC. REF: NDT PART 2/55-10-02									PKG:26
P5510073	^S	* HORIZONTAL REAR SPAR UPPER CAP - PERFORM EDDY CURRENT INSPECTION (AWL*)						Service	ATA:55
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: NDT PART 6/55-10-07PROC. REF: NDT PART 6/55-10-07									PKG:26
P5510092	^S	* HORIZONTAL STABILIZER UPPER-SPAR-SPLICE DOUBLER - PERFORM EDDY CURRENT INSPECTION (AWL*)						Service	ATA:55
	MOS	13-Mar-26	96					AIRWORTHINESS	
	HRS	9596.2	2400						
	AFL	7624							
PROC. REF: NDT PART 6/55-10-06PROC. REF: NDT PART 6/55-10-06									PKG:20
P5520001	^S	* ELEVATOR HINGE ATTACH BOLT - PERFORM MAGNETIC PARTICLE INSPECTION (AWL*)						Service	ATA:55
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: NDT PART 7/27-30-01PROC. REF: NDT PART 7/27-30-01									PKG:26
P5520021	^S	* ELEVATOR HINGE FITTINGS - PERFORM EDDY CURRENT INSPECTION (AWL*)						Service	ATA:55
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: NDT PART 6/55-30-07PROC. REF: NDT PART 6/55-30-07									PKG:26

? - Insufficient Information
S - Suppressed Requirement
* - Estimated Due(New Requirement)
(EFF) - Effective C / W
(M) - Manual Due
U - User Task
Ex - Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 55 - STABILIZERS									
P5520022	^S	* ELEVATOR HINGE PRIMARY AND SECONDARY ATTACH BOLTS - PERFORM LIQUID PENETRANT INSPECTION (AWL*)						Service	ATA:55
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: NDT PART 8/27-30-01, NDT PART 8/27-30-02PROC. REF: NDT PART 8/27-30-01, NDT PART 8/27-30-02									PKG:26
P5540001	^S	* RUDDER SPAR - PERFORM DETAILED VISUAL INSPECTION. INSPECT SPAR CAPS AND FASTENERS (AWL*)						Service	ATA:55
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:26
P5540002	^S	* RUDDER ATTACH BOLT - PERFORM LIQUID PENETRANT INSPECTION (AWL*)						Service	ATA:55
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: NDT PART 8/55-30-02PROC. REF: NDT PART 8/55-30-02									PKG:26
Q5510007	^S	* VERTICAL STABILIZER SKIN AND AFT LOWER SPAR CAP - PERFORM EDDY CURRENT INSPECTION (AWL*)						Service	ATA:55
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: NDT PART 6/55-30-06PROC. REF: NDT PART 6/55-30-06									PKG:26
Q5530011	^S	* VERTICAL STABILIZER SKIN AND UPPER AFT SPAR CAP - PERFORM EDDY CURRENT INSPECTION (AWL*)						Service	ATA:55
	MOS	13-Mar-26	96					AIRWORTHINESS	
	HRS	9596.2	2400						
	AFL	7624							
PROC. REF: NDT PART 6/55-30-06PROC. REF: NDT PART 6/55-30-06									PKG:20

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 55 - STABILIZERS									
T5510004 ^S		* RUDDER HINGE FITTINGS - PERFORM VISUAL INSPECTION. CONTROL SURFACE REMOVAL NOT REQUIRED. (AWL*)						Service	ATA:55
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:26
Y5510001 ^S		HORIZONTAL STABILIZER - PERFORM EXTERNAL VISUAL INSPECTION.						Service	ATA:55
	MOS	13-Mar-26	48 (+14d/-14d)						
	HRS	9596.2	1200 (+25/-25)						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:14
Y5510002 ^S		ELEVATOR HINGES ON HORIZONTAL STABILIZER - PERFORM VISUAL INSPECTION. INSPECT HINGE LUGS ON HORIZONTAL TAIL SIDE OF JOINT. INSPECT HILITE COLLARS AT BL 0.0 AND OUTBOARD ELEVATOR HINGE						Service	ATA:55
	MOS	13-Mar-26	48 (+14d/-14d)						
	HRS	9596.2	1200 (+25/-25)						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:14
Y5510003 ^S		VERTICAL STABILIZER PIVOT FITTING - PERFORM VISUAL INSPECTION. INSPECT HILITE COLLARS COMMON TO THE PIVOT FITTING (MID SPAR, AFT SPAR, TOP PLATE, AND UP/DOWN SPRING BRACKET).						Service	ATA:55
	MOS	13-Mar-26	48 (+14d/-14d)						
	HRS	9596.2	1200 (+25/-25)						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:14
Y5510093 ^S		HORIZONTAL STABILIZER - PERFORM VISUAL INSPECTION OF HILITE COLLARS IN THE FOLLOWING AREAS: - FORWARD SPAR TO BL 0.0 RIB.- CENTER SPAR TO BL 0.0 RIB.- CENTER SPAR SPLICE PLATE.- AFT SPAR SPLICE PLATE.- ROOT RIBS AT BL 3.70 (RIGHT AND LEFT).- UPPER DOUBLER SPAR SPLICE, BL 0.0.- HSTA UPPER ATTACH FITTING STRUCTURE.						Service	ATA:55
	MOS	13-Mar-26	48 (+14d/-14d)						
	HRS	9596.2	1200 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 55-00-01PROC. REF: AMM 55-00-01									PKG:14

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 55 - STABILIZERS									
Y5510094	^S	LOWER BRACKET, HORIZONTAL STABILIZER TRIM ACTUATOR - PERFORM BORESCOPE INSPECTION OF HILITE COLLARS COMMON TO RIB # 6 AND MID SPAR						Service	ATA:55
	MOS	13-Mar-26	48 (+14d/-14d)						
	HRS	9596.2	1200 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 55-10-00PROC. REF: AMM 55-10-00									PKG:14
Y5540012	^S	RUDDER TORQUE TUBE - LOOSEN TORQUE TUBE BONDING CLAMP AND PERFORM DETAILED VISUAL INSPECTION OF AREA AROUND BONDING CLAMP FOR CORROSION. NOTE: PERFORM BONDING CHECK OF CLAMP AND BONDING JUMPERS AFTER REINSTALLATION OF CLAMP.						Service	ATA:55
	MOS	13-Mar-26	12 (+14d/-14d)						
	HRS	9596.2	300 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 27-20-01PROC. REF: AMM 27-20-01									PKG:2
ATA 56 - WINDOWS									
5-19-00-W5600002		** WINDSHIELD - PERFORM RAIN REMOVAL COATING EFFECTIVENESS TEST (AWL**)						Service	ATA:56
	MOS	13-Mar-26	12 (+14d/-14d)		13-Mar-27	27-Mar-27	179 d (+14)	AIRWORTHINESS	
	HRS	9596.2							
	AFL	7624							
PROC. REF: AMM 56-10-01, AMM 56-10-01PROC. REF: AMM 56-10-01, AMM 56-10-01									
561001		LEFT WINDSHIELD						Component	ATA:56
PN:665610000-003	MOS/MSC	21-Jul-26	O/C						
SN:3737	HRS	9794.8							
	AFL	7756							
PROC. REF: AMM 56-10-01, AMM 56-10-01PROC. REF: AMM 56-10-01, AMM 56-10-01									
561001A		* LEFT WINDSHIELD - PERFORM ULTRASONIC INSPECTION OF THE STRUCTURAL PLIES (IRN N5600003) (AWL*)						Service	ATA:56
	MOS	11-Aug-22							
	HRS	8836.8	4800		13636.8		3795.5		
	AFL	7093							
PROC. REF: NDT PART 4/56-10-01PROC. REF: NDT PART 4/56-10-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR
Serial: 45-2027
RegNo: N116PJ
HRS: 9841.3
AFL: 7790
As Of: 14-Sep-2026
15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 56 - WINDOWS									
561001B	* LEFT WINDSHIELD - PERFORM BOLT HOLE INSPECTION (IRN N5600012) (AWL*)							Service	ATA:56
	MOS/MSC	28-Aug-23	N/A						
	HRS	9158.1							
	AFL	7309							
PROC. REF: AMM 56-10-01PROC. REF: AMM 56-10-01									
561002	RIGHT WINDSHIELD							Component	ATA:56
PN:173600-24	MOS/MSC	13-Jul-26	O/C						
SN:2512	HRS	9780.7							
	AFL	7747							
PROC. REF: AMM 56-10-01, AMM 56-10-01PROC. REF: AMM 56-10-01, AMM 56-10-01									
561002A	* RIGHT WINDSHIELD - PERFORM ULTRASONIC INSPECTION OF THE STRUCTURAL PLIES (IRN N5600003) (AWL*)							Service	ATA:56
	MOS/MSC	11-Aug-22	N/A						
	HRS	8836.8							
	AFL	7093							
PROC. REF: NDT PART 4/56-10-01PROC. REF: NDT PART 4/56-10-01									
561002B	* RIGHT WINDSHIELD - PERFORM BOLT HOLE INSPECTION (IRN N5600012) (AWL*)							Service	ATA:56
	MOS	11-Aug-22							
	HRS	8836.8	4800		13636.8		3795.5		
	AFL	7093							
PROC. REF: AMM 56-10-01PROC. REF: AMM 56-10-01									
L5600010 ^S	* CABIN WINDOWS (INCLUDING THE EMERGENCY EXIT WINDOW) - PERFORM DETAILED VISUAL INSPECTION (AWL*)							Service	ATA:56
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	4800						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
Y5600000 ^S	WINDSHIELDS - PERFORM VISUAL INSPECTION (INTERIOR AND EXTERIOR).							Service	ATA:56
	MOS	13-Mar-26	12 (+14d/-14d)						
	HRS	9596.2	300 (+25/-25)						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C / W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 56 - WINDOWS									
Y5600001 ^S	CABIN WINDOWS - PERFORM VISUAL INSPECTION.								Service ATA:56
	MOS	13-Mar-26	24 (+14d/-14d)						
	HRS	9596.2	600 (+25/-25)						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
PKG:7									
Y5600013 ^S	WINDSHIELDS - PERFORM VISUAL INSPECTION OF THE AERODYNAMIC SEAL. NOTE: IF REPAIRS TO THE SEAL ARE NEEDED, REFER TO 56-10-01								Service ATA:56
	MOS	13-Mar-26	12 (+14d/-14d)						
	HRS	9596.2	300 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 56-10-01, AMM 56-10-01PROC. REF: AMM 56-10-01, AMM 56-10-01									
PKG:1									
ATA 57 - WINGS									
5-19-00-E5750051	* FLAP MAIN TRACK ROLLERS - PERFORM VISUAL INSPECTION WITH FLAPS REMOVED (IRN E5750051) (AWL*)								Service ATA:57
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	600		10196.2		354.9		
	AFL	7624							
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01									
5-19-00-E5750052	* FLAP NOSE ROLLERS - PERFORM VISUAL INSPECTION WITH THE FLAPS REMOVED (IRN E5750052) (AWL*)								Service ATA:57
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	600		10196.2		354.9		
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
5-19-00-N5710002	* WING BOX MID SPAR LOWER CAP, OUTBOARD OF JOINT AT WS 137 BETWEEN RIBS 7 AND 8 - PERFORM DIRECTED VISUAL INSPECTION. INSPECT MID SPAR LOWER CAP AND LOWER SKIN PANELS. (IRN N5710002) (AWL*)								Service ATA:57
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	3580		13176.2		3334.9		
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
5-19-00-N5710008	* WING BOX MID SPAR LOWER CAP - PERFORM ULTRASONIC INSPECTION. INSPECT MID SPAR LOWER CAP AND LOWER SKIN PANELS BETWEEN WS 99 & WS 137 (IRN N5710008) (AWL*)								Service ATA:57
	MOS	16-Mar-26						AIRWORTHINESS	
	HRS	9596.2	2500		12096.2		2254.9		
	AFL	7624							
PROC. REF: NDT PART 4/57-30-03PROC. REF: NDT PART 4/57-30-03									
5-19-00-N5710009	* WING BOX MID SPAR LOWER CAP JOINT AT WS 137 - PERFORM XRAY INSPECTION. INSPECT MID SPAR CENTER/OUTER JOINT (IRN N5710009) (AWL*)								Service ATA:57
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	4517		14113.2		4271.9		
	AFL	7624							
PROC. REF: NDT PART 2/57-10-02PROC. REF: NDT PART 2/57-10-02									
5-19-00-N5710010	* WING BOX REAR SPAR LOWER CAP INBOARD OF JOINT AT WS 81 - PERFORM ULTRASONIC INSPECTION. INSPECT REAR SPAR LOWER CAP BETWEEN SKIN TERMINATION AT WS 48 AND CLOSING RIB AT WS 60 (IRN N5710010) (AWL*)								Service ATA:57
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	960		10556.2		714.9		
	AFL	7624							
PROC. REF: NDT PART 4/57-30-01PROC. REF: NDT PART 4/57-30-01									
5-19-00-N5710012	* WING BOX REAR SPAR LOWER CAP OUTBOARD OF JOINT AT WS 81 TO RIB 6 - PERFORM DETAILED VISUAL INSPECTION. INSPECT OUTER REAR SPAR LOWER CAP AND AFT LOWER SKIN PANEL OUTBOARD OF REAR SPLICE AT WS 90. (IRN N5710012) (AWL*)								Service ATA:57
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	3443		13039.2		3197.9		
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
5-19-00-N5710013	* WING BOX REAR SPAR LOWER CAP SKIN TERMINATION AT MS 48 - PERFORM EDDY CURRENT INSPECTION. INSPECT REAR SPAR LOWER CAP BETWEEN WS33 AND WS48. (AWL*)								Service ATA:57
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	1077		10673.2		831.9		
	AFL	7624							
PROC. REF: NDT PART 6/57-20-04PROC. REF: NDT PART 6/57-20-04									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
5-19-00-N5710026	* WING BOX MID SPAR LOWER CAP - PERFORM NDI INSPECTION. INSPECT MID SPAR LOWER CAP OUTBOARD OF ROOT RIB AT WS 33 TO WS 99. (IRN N5710026) (AWL*)							Service	ATA:57
	MOS	16-Mar-26						AIRWORTHINESS	
	HRS	9596.2	2278		11874.2		2032.9		
	AFL	7624							
PROC. REF: NDT PART 4/57-30-03PROC. REF: NDT PART 4/57-30-03									
5-19-00-N5710123	* WING BOX MID SPAR LOWER CAP - PERFORM EDDY CURRENT INSPECTION AT TRUNNION FITTING (IRN N5710123) (AWL*)							Service	ATA:57
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	2666		12262.2		2420.9		
	AFL	7624							
PROC. REF: NDT PART 6/57-10-01PROC. REF: NDT PART 6/57-10-01									
5-19-00-N5710174	* WING BOX REAR SPAR LOWER CAP SKIN TERMINATION AT MS 48 - PERFORM ULTRASONIC INSPECTION. INSPECT REAR SPAR LOWER CAP BETWEEN WS 33 AND WS 48 (AWL*)							Service	ATA:57
	MOS	13-Mar-26							
	HRS	9596.2	1077		10673.2		831.9		
	AFL	7624							
PROC. REF: NDT PART 4/57-30-04PROC. REF: NDT PART 4/57-30-04									
5-19-00-P5710172	* WING BOX MID SPAR LOWER CAP - PERFORM ULTRASONIC INSPECTION AT TRUNNION FITTING (AWL*)							Service	ATA:57
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	2666		12262.2		2420.9		
	AFL	7624							
PROC. REF: NDT PART 4/57-10-00PROC. REF: NDT PART 4/57-10-00									
5-19-01-A5760004-LEFT	LEFT * AILERON BOLTS * REPLACE LEFT AILERON BOLTS (IRN A5760004) (AWL*)							Service	ATA:57
	MOS	13-Mar-26							
	HRS	9596.2	9600		19196.2		9354.9		
	AFL	7624							
PROC. REF: AMM 27-10-02PROC. REF: AMM 27-10-02									
5-19-01-A5760004-RIGHT	RIGHT * AILERON BOLTS * REPLACE RIGHT AILERON BOLTS (IRN A5760004) (AWL*)							Service	ATA:57
	MOS	13-Mar-26							
	HRS	9596.2	9600		19196.2		9354.9		
	AFL	7624							
PROC. REF: AMM 27-10-02PROC. REF: AMM 27-10-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
570001	WING ASSEMBLY							Component	ATA:57
PN:4557000004-001	MOS/MSC	10-May-05	O/C	TSN 0					
SN:144043600295	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 57-10-00PROC. REF: AMM 57-10-00									
571010	* REPLACE LEFT MAIN LANDING GEAR SIDE-STAY ACTUATOR FITTING (IRN N3220126) (AWL*)							Component	ATA:57
PN:4532103041-009	MOS	22-Apr-08		TSN 0					
SN:NSN	HRS	2112.67		TSN 0					
	AFL	1713	20000	TSN 0	21713		13923		
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01									
571011	* REPLACE RIGHT MAIN LANDING GEAR SIDE-STAY ACTUATOR FITTING (IRN N3220126) (AWL*)							Component	ATA:57
PN:4532103041-009	MOS	22-Apr-08		TSN 0					
SN:NSN	HRS	2112.67		TSN 0					
	AFL	1713	20000	TSN 0	21713		13923		
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01									
5710190	* LEFT WING CENTER SECTION (PANELS 510AC, 510BC, 510BL AND 610BR REMOVED AND PANELS 510AL, 610AR, 720BL, AND 730BR LOWERED) - PERFORM VISUAL INSPECTION. INSPECT STRUCTURE FOR CORROSION OR DETERIORATION OF PROTECTIVE TREATMENT.							Service	ATA:57
	MOS	19-Feb-20	96	Adj 6d	25-Feb-28		528 d		
	HRS	7875.4							
	AFL	6355							
PROC. REF: AMM 57-10-00PROC. REF: AMM 57-10-00									
5710190	* RIGHT WING CENTER SECTION (PANELS 510AC, 510BC, 510BL AND 610BR REMOVED AND PANELS 510AL, 610AR, 720BL, AND 730BR LOWERED) - PERFORM VISUAL INSPECTION. INSPECT STRUCTURE FOR CORROSION OR DETERIORATION OF PROTECTIVE TREATMENT.							Service	ATA:57
	MOS	19-Feb-20	96	Adj 6d	25-Feb-28		528 d		
	HRS	7875.4							
	AFL	6355							
PROC. REF: AMM 57-10-00PROC. REF: AMM 57-10-00									
573001	LEFT WINGLET ASSEMBLY							Component	ATA:57
PN:4557300006-001/00	MOS/MSC	10-May-05	O/C	TSN 0					
SN:675845000295	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 57-30-01PROC. REF: AMM 57-30-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR
 Serial: 45-2027
 RegNo: N116PJ
 HRS: 9841.3
 AFL: 7790
 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
573002	RIGHT WINGLET ASSEMBLY							Component	ATA:57
PN:4557300006-002/00	MOS/MSC	10-May-05	O/C	TSN 0					
SN:675547300295	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 57-30-01PROC. REF: AMM 57-30-01									
574011	LEFT INBOARD LEADING EDGE ACCESS SECTION							Component	ATA:57
PN:4557400005-037	MOS/MSC	10-May-05	O/C	TSN 0					
SN:675656500295	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 57-40-01PROC. REF: AMM 57-40-01									
574013	RIGHT INBOARD LEADING EDGE ACCESS SECTION							Component	ATA:57
PN:4557400005-038	MOS/MSC	10-May-05	O/C	TSN 0					
SN:277549200295	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 57-40-01PROC. REF: AMM 57-40-01									
574039	LEFT OUTBOARD LEADING EDGE ACCESS SECTION							Component	ATA:57
PN:4557400005-045	MOS/MSC	10-May-05	O/C	TSN 0					
SN:675673200295	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 57-40-01PROC. REF: AMM 57-40-01									
574041	RIGHT OUTBOARD LEADING EDGE ACCESS SECTION							Component	ATA:57
PN:4557400005-044	MOS/MSC	10-May-05	O/C	TSN 0					
SN:220291600295	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 57-40-01PROC. REF: AMM 57-40-01									
574042	LEFT INBOARD LEADING EDGE							Component	ATA:57
PN:4557400005-039	MOS/MSC	10-May-05	O/C	TSN 0					
SN:675658100295	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 57-40-01PROC. REF: AMM 57-40-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
574043	RIGHT INBOARD LEADING EDGE							Component	ATA:57
PN:4557400005-040	MOS/MSC	10-May-05	O/C	TSN 0					
SN:675660000295	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 57-40-01PROC. REF: AMM 57-40-01									
574044	LEFT CENTER LEADING EDGE							Component	ATA:57
PN:4557400005-041	MOS/MSC	10-May-05	O/C	TSN 0					
SN:675664700295	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 57-40-01PROC. REF: AMM 57-40-01									
574045	RIGHT CENTER LEADING EDGE							Component	ATA:57
PN:4557400005-042	MOS/MSC	10-May-05	O/C	TSN 0					
SN:418499400295	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 57-40-01PROC. REF: AMM 57-40-01									
574046	LEFT OUTBOARD LEADING EDGE							Component	ATA:57
PN:4557400005-043	MOS/MSC	10-May-05	O/C	TSN 0					
SN:473401600295	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 57-40-01PROC. REF: AMM 57-40-01									
574047	RIGHT OUTBOARD LEADING EDGE							Component	ATA:57
PN:4557400005-046	MOS/MSC	10-May-05	O/C	TSN 0					
SN:219958200295	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 57-40-01PROC. REF: AMM 57-40-01									
575002	RIGHT FLAP ASSEMBLY							Component	ATA:57
PN:4557500006-008	MOS/MSC	10-May-23	O/C	TSN 216					
SN:676081600295	HRS	9071.3		TSN 9071.3					
	AFL	7252		TSN 7252					
PROC. REF: AMM 57-50-01PROC. REF: AMM 57-50-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR
Serial: 45-2027
RegNo: N116PJ
HRS: 9841.3
AFL: 7790
As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-------	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 57 - WINGS									
576001	LEFT AILERON ASSEMBLY							Component	ATA:57
PN:4557600003-001	MOS/MSC	10-May-23	O/C	TSN 216					
SN:698914500299	HRS	9071.3		TSN 9071.3					
	AFL	7252		TSN 7252					
Special Properties: RII ITEM									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

576002	RIGHT AILERON ASSEMBLY							Component	ATA:57
PN:4557600003-002	MOS/MSC	10-May-23	O/C	TSN 216					
SN:701682900299	HRS	9071.3		TSN 9071.3					
	AFL	7252		TSN 7252					
Special Properties: RII ITEM									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

577001	LEFT SPOILER ASSEMBLY							Component	ATA:57
PN:4557700003-021	MOS/MSC	10-May-23	O/C	TSN 216					
SN:0342	HRS	9071.3		TSN 9071.3					
	AFL	7252		TSN 7252					
PROC. REF: AMM 57-70-01PROC. REF: AMM 57-70-01									

577002	RIGHT SPOILER ASSEMBLY							Component	ATA:57
PN:4557700003-022	MOS/MSC	10-May-23	O/C	TSN 216					
SN:0349	HRS	9071.3		TSN 9071.3					
	AFL	7252		TSN 7252					
PROC. REF: AMM 57-70-01PROC. REF: AMM 57-70-01									

AE5710035 ^S	* WING LOWER SKIN AT DRAIN HOLE (4 LOCATIONS) - PERFORM EDDY CURRENT INSPECTION (AWL*)							Service	ATA:57
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	4800						
	AFL	7624							
PROC. REF: NDT PART 6/57-30-02PROC. REF: NDT PART 6/57-30-02									

AE5710187	* LOWER WING FUEL DRAIN HOLES (4 LOCATIONS) - PERFORM EDDY CURRENT INSPECTION							Service	ATA:57
	MOS	EFF	72		11-Dec-31 *		1913 d	AIRWORTHINESS	
	HRS								
	AFL								
PROC. REF: NDT PART 6/57-30-03PROC. REF: NDT PART 6/57-30-03									

? - Insufficient Information
S - Suppressed Requirement
* - Estimated Due(New Requirement)
(EFF) - Effective C / W
(M) - Manual Due
U - User Task
Ex - Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
E5710005	^S	* WING CENTER SECTION SPAR UPPER CAPS - PERFORM VISUAL INSPECTION. INSPECT FRONT, MID, AND REAR SPARUPPER CAPS FROM CENTERLINE TO SKIN TERMINATION ATWS 33 (AWL*)						Service	ATA:57
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:26
E5710019	^S	* WING BOX, UPPER SKIN, SKIN/STRINGER AND SPAR CAPS - PERFORM VISUAL INSPECTION. INSPECT UPPER WING SPAR CAPS, SKIN PANEL, AND STRINGERS OF OUTER WING. (AWL*)						Service	ATA:57
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:26
E5710020	^S	* WING BOX RIBS - PERFORM VISUAL INSPECTION. INSPECT ALL WING BOX RIBS EXCEPT CLOSING RIB BETWEEN FRONT AND MID SPARS AND CLOSING RIB BETWEEN MID AND REAR SPAR (AWL*)						Service	ATA:57
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:26
E5760006	^S	* AILERON BASIC STRUCTURE - PERFORM VISUAL INSPECTION. (AWL*)						Service	ATA:57
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:26
L5710124	^S	* AILERON DRIVE SUPPORT - PERFORM ULTRASONIC INSPECTION. (AWL*)						Service	ATA:57
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	4800						
	AFL	7624							
PROC. REF: NDT PART 4/27-10-01PROC. REF: NDT PART 4/27-10-01									PKG:25

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR
Serial: 45-2027
RegNo: N116PJ
HRS: 9841.3
AFL: 7790
As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
N5710004	^S	* WING CENTER SECTION REAR SPAR - PERFORM EDDY CURRENT INSPECTION. INSPECT REAR SPAR LOWER CAP FROM CENTERLINE TO WS 33. (AWL *)						Service	ATA:57
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	4800						
	AFL	7624							
PROC. REF: NDT PART 6/57-20-02PROC. REF: NDT PART 6/57-20-02									PKG:25
N5710006	^S	* WING CENTER SECTION FORWARD AND AFT RIBS AT WS 6 AND FORWARD RIBS AT WS 17 - PERFORM EDDY CURRENT INSPECTION. (AWL *)						Service	ATA:57
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	4800						
	AFL	7624							
PROC. REF: NDT PART 6/57-10-06PROC. REF: NDT PART 6/57-10-06									PKG:25
N5710011	^S	* WING BOX REAR SPAR LOWER CAP JOINT AT WS 81 - PERFORM X-RAY INSPECTION. (AWL *)						Service	ATA:57
	MOS	13-Mar-26	96					AIRWORTHINESS	
	HRS	9596.2	2400						
	AFL	7624							
PROC. REF: NDT PART 2/57-10-03PROC. REF: NDT PART 2/57-10-03									PKG:22
N5710014	^S	* WING BOX REAR SPAR FLAP TRACK CUTOUTS - PERFORM EDDY CURRENT INSPECTION. INSPECT FLAP TRACK CUTOUTS AT WS 65, WS 126, AND WS 184 ON REAR SPAR. (AWL *)						Service	ATA:57
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	4800						
	AFL	7624							
PROC. REF: NDT PART 6/57-20-01PROC. REF: NDT PART 6/57-20-01									PKG:25
N5710016	^S	* WING BOX BASIC SKIN/STRINGER, LOWER SKIN - PERFORM VISUAL INSPECTION. INSPECT OUTBOARD WING FORWARD AND AFT LOWER SKIN PANELS AND STRINGERS (AWL *)						Service	ATA:57
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	4800						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:25

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C / W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 40XR
Serial: 45-2027
RegNo: N116PJ
HRS: 9841.3
AFL: 7790
As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
N5710017	^S	* WING BOX BASIC SKIN/STRINGER AT STRINGER RUN-OUT, LOWER SKIN - PERFORM VISUAL INSPECTION. INSPECT STRINGER RUN-OUTS IN FORWARD AND AFT LOWER SKIN PANELS. (AWL*)						Service	ATA:57
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:26
N5710021	^S	* CENTER SECTION MID SPAR LOWER CAP - PERFORM EDDY CURRENT INSPECTION. (AWL*)						Service	ATA:57
	MOS	13-Mar-26	96					AIRWORTHINESS	
	HRS	9596.2	2400						
	AFL	7624							
PROC. REF: NDT PART 6/57-10-02PROC. REF: NDT PART 6/57-10-02									PKG:22
N5710022	^S	* CENTER SECTION MID SPAR CENTERLINE JOINT - PERFORM EDDY CURRENT INSPECTION. (AWL*)						Service	ATA:57
	MOS	13-Mar-26	96					AIRWORTHINESS	
	HRS	9596.2	2400						
	AFL	7624							
PROC. REF: NDT PART 6/57-10-08, NDT PART 6/57-10-10PROC. REF: NDT PART 6/57-10-08, NDT PART 6/57-10-10									PKG:22
N5710023	^S	* CENTER SECTION FRONT SPAR LOWER CAP - PERFORM EDDY CURRENT INSPECTION. (AWL*)						Service	ATA:57
	MOS	13-Mar-26	96					AIRWORTHINESS	
	HRS	9596.2	2400						
	AFL	7624							
PROC. REF: NDT PART 6/57-10-03PROC. REF: NDT PART 6/57-10-03									PKG:22
N5710028	^S	* WING BOX MID SPAR LOWER CAP, SKIN TERMINATION AT WS 33 - BOLT HOLE - PERFORM EDDY CURRENT INSPECTION. INSPECT MID SPAR LOWER CAP UNDERNEATH ROOT RIB (WS 33) AT POINT OF SKIN TERMINATION. (AWL*)						Service	ATA:57
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	4800						
	AFL	7624							
PROC. REF: NDT PART 6/57-10-11PROC. REF: NDT PART 6/57-10-11									PKG:25

? - Insufficient Information
S - Suppressed Requirement
* - Estimated Due(New Requirement)
(EFF) - Effective C / W
(M) - Manual Due
U - User Task
Ex - Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
N5710031	^S	PERFORM * WING BOX SKIN ACCESS COVER HOLES - EDDY CURRENT INSPECTION. INSPECT ACCESS HOLES IN FORWARD AND AFT LOWER SKIN PANELS. (AWL*)						Service	ATA:57
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	4800						
	AFL	7624							
PROC. REF: NDT PART 6/57-30-01PROC. REF: NDT PART 6/57-30-01									PKG:25
N5710037	^S	* WING BOX FRONT SPAR LOWER CAP - PERFORM VISUAL INSPECTION. INSPECT FRONT SPAR LOWER CAP AND LOWER FORWARD SKIN OUTBOARD OF MID-SPAR STATION (MS) 55. (AWL*)						Service	ATA:57
	MOS	13-Mar-26	96					AIRWORTHINESS	
	HRS	9596.2	2400						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:22
N5710084	^S	SPOILER, CENTER HINGE SPOILER SIDE - PERFORM NDI INSPECTION						Service	ATA:57
	MOS	13-Mar-26	96 (+14d/-14d)						
	HRS	9596.2	2400 (+25/-25)						
	AFL	7624							
PROC. REF: NDT PART 6/57-40-01PROC. REF: NDT PART 6/57-40-01									PKG:22
N5710121	^S	* WING BOX MID SPAR, OUTBOARD OF RIB 8 - PERFORM VISUAL INSPECTION AT WS 156 AND OUTBOARD TO WS 260 (AWL*)						Service	ATA:57
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	4800						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:25
N5710122	^S	* WING BOX REAR SPAR, OUTBOARD OF RIB 6 - PERFORM VISUAL INSPECTION AT WS 118 AND OUTBOARD TO WS 260. (AWL*)						Service	ATA:57
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	4800						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:25

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
N5710137 ^S	* MID SPAR AT RIB 2 NEAR WS 48 - PERFORM BOLT HOLE EDDY CURRENT INSPECTION. (AWL*)							Service	ATA:57
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	4800						
	AFL	7624							
PROC. REF: NDT PART 6/57-10-11APROC. REF: NDT PART 6/57-10-11A									
N5710138 ^S	* MID SPAR AT RIB 3 NEAR WS 60 - PERFORM BOLT HOLE EDDY CURRENT INSPECTION. (AWL*)							Service	ATA:57
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	4800						
	AFL	7624							
PROC. REF: NDT PART 6/57-10-11APROC. REF: NDT PART 6/57-10-11A									
N5710139 ^S	* FORWARD FLANGE FASTENERS AT REAR SPAR BETWEEN WS 52 AND WS 60 - PERFORM BOLT HOLE EDDY CURRENT INSPECTION. (AWL*)							Service	ATA:57
	MOS	13-Mar-26	96					AIRWORTHINESS	
	HRS	9596.2	2400						
	AFL	7624							
PROC. REF: NDT PART 6/57-20-03PROC. REF: NDT PART 6/57-20-03									
N5710176 ^S	* WING MID-SPAR (CENTER SECTION) LOWER CAP AND CENTER-JOINT FITTING - PERFORM ULTRASONIC INSPECTION. (AWL*)							Service	ATA:57
	MOS	13-Mar-26	96					AIRWORTHINESS	
	HRS	9596.2	2400						
	AFL	7624							
PROC. REF: NDT PART 4/57-30-05PROC. REF: NDT PART 4/57-30-05									
N5750005 ^S	* FLAP MAIN TRACK HINGE FITTINGS, TRACK, AND FLAP BOX SIDES - PERFORM VISUAL INSPECTION. INSPECT MAIN TRACK HINGE FITTINGS ON TRACK AND FLAP BOX SIDES. (AWL*)							Service	ATA:57
	MOS	13-Mar-26	96					AIRWORTHINESS	
	HRS	9596.2	2400						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR
Serial: 45-2027
RegNo: N116PJ
HRS: 9841.3
AFL: 7790
As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
P5710001	^S	* WING DRAG LINK ATTACH FITTING - PERFORM MAGNETIC PARTICLE INSPECTION (AWL*)						Service	ATA:57
	MOS	13-Mar-26	96					AIRWORTHINESS	
	HRS	9596.2	2400						
	AFL	7624							
PROC. REF: NDT PART 7/57-30-02PROC. REF: NDT PART 7/57-30-02									PKG:22
P5710007	^S	* WING TO FUSELAGE ATTACH FITTINGS AND LINKS - PERFORM EDDY CURRENT INSPECTION (AWL*)						Service	ATA:57
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	4800						
	AFL	7624							
PROC. REF: NDT PART 6/57-10-12PROC. REF: NDT PART 6/57-10-12									PKG:25
P5710015	^S	* WING REAR SPAR AT AILERON HINGE - PERFORM EDDY CURRENT INSPECTION (AWL*)						Service	ATA:57
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	4800						
	AFL	7624							
PROC. REF: NDT PART 6/57-10-20PROC. REF: NDT PART 6/57-10-20									PKG:25
P5710018	^S	* WING LOWER SKIN AT MID-SPAR SPAN-WISE JOINT - PERFORM EDDY CURRENT INSPECTION (AWL*)						Service	ATA:57
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: NDT PART 6/57-10-09PROC. REF: NDT PART 6/57-10-09									PKG:26
P5710024	^S	* WING REAR-SPAR SIDE-STAY-FITTING SUPPORT STRUCTURE - PERFORM EDDY CURRENT INSPECTION (AWL*)						Service	ATA:57
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	4800						
	AFL	7624							
PROC. REF: NDT PART 6/57-20-06PROC. REF: NDT PART 6/57-20-06									PKG:25

? - Insufficient Information
S - Suppressed Requirement
* - Estimated Due(New Requirement)
(EFF) - Effective C / W
(M) - Manual Due
U - User Task
Ex - Excluded Task

Status Report

Model: LEARJET 40XR
Serial: 45-2027
RegNo: N116PJ
HRS: 9841.3
AFL: 7790
As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
P5710025	^S	* WING FRONT SPAR LOWER CAP FROM WS 33.0 TO WS 60.0 - PERFORM RADIOGRAPHIC INSPECTION (AWL*)						Service	ATA:57
	MOS	13-Mar-26	96					AIRWORTHINESS	
	HRS	9596.2	2400						
	AFL	7624							
PROC. REF: NDT PART 2/57-10-01PROC. REF: NDT PART 2/57-10-01									PKG:22
P5710029	^S	* WING MID-SPAR VERTICAL WEB - PERFORM EDDY CURRENT INSPECTION (AWL*)						Service	ATA:57
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: NDT PART 6/57-10-07PROC. REF: NDT PART 6/57-10-07									PKG:26
P5710030	^S	* WING REAR SPAR VERTICAL WEB - PERFORM EDDY CURRENT INSPECTION (AWL*)						Service	ATA:57
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: NDT PART 6/57-20-05PROC. REF: NDT PART 6/57-20-05									PKG:26
P5710032	^S	* WING RIB UPPER-AFT-FLANGE FILLET RADIUS AT WS 33.0 - PERFORM ULTRASONIC INSPECTION (AWL*)						Service	ATA:57
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	4800						
	AFL	7624							
PROC. REF: NDT PART 4/57-30-02PROC. REF: NDT PART 4/57-30-02									PKG:25
P5710033	^S	* WING ACCESS HOLE IN CLOSING RIB BETWEEN MID SPAR AND REAR SPAR - PERFORM EDDY CURRENT INSPECTION (AWL*)						Service	ATA:57
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	4800						
	AFL	7624							
PROC. REF: NDT PART 6/57-10-05PROC. REF: NDT PART 6/57-10-05									PKG:25

? - Insufficient Information
S - Suppressed Requirement
* - Estimated Due(New Requirement)
(EFF) - Effective C / W
(M) - Manual Due
U - User Task
Ex - Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
P5710034 ^S	* WING BOX JOINT TO WINGLET - PERFORM EDDY CURRENT INSPECTION (AWL*)							Service	ATA:57
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	4800						
	AFL	7624							
PROC. REF: NDT PART 6/57-10-13PROC. REF: NDT PART 6/57-10-13									
PKG:25									
P5710083 ^S	* FLAP BOX BASIC STRUCTURE - PERFORM EDDY CURRENT INSPECTION (AWL*)							Service	ATA:57
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	4800						
	AFL	7624							
PROC. REF: NDT PART 6/57-40-02PROC. REF: NDT PART 6/57-40-02									
PKG:25									
P5710085 ^S	SPOILER UPPER SKIN - PERFORM EDDY CURRENT INSPECTION							Service	ATA:57
	MOS	13-Mar-26							
	HRS	9596.2	4800 (+25/-25)						
	AFL	7624							
PROC. REF: NDT PART 6/57-10-16PROC. REF: NDT PART 6/57-10-16									
PKG:25									
P5710086 ^S	SPOILER BOLTS AND HINGE PINS - PERFORM MAGNETIC PARTICLE INSPECTION							Service	ATA:57
	MOS	13-Mar-26							
	HRS	9596.2	4800 (+25/-25)						
	AFL	7624							
PROC. REF: NDT PART 7/27-10-01PROC. REF: NDT PART 7/27-10-01									
PKG:25									
P5710181 ^S	* WING DRAG LINK TUBE - PERFORM MAGNETIC PARTICLE INSPECTION (AWL*)							Service	ATA:57
	MOS	13-Mar-26	96					AIRWORTHINESS	
	HRS	9596.2	2400						
	AFL	7624							
PROC. REF: NDT PART 7/57-30-01PROC. REF: NDT PART 7/57-30-01									
PKG:22									

Status Report

Model: LEARJET 40XR
Serial: 45-2027
RegNo: N116PJ
HRS: 9841.3
AFL: 7790
As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
P5710182	^S	* WING DRAG LINK ATTACH BOLTS - PERFORM LIQUID PENETRANT INSPECTION (AWL*)						Service	ATA:57
	MOS	13-Mar-26	96					AIRWORTHINESS	
	HRS	9596.2	2400						
	AFL	7624							
PROC. REF: NDT PART 8/57-10-01PROC. REF: NDT PART 8/57-10-01									PKG:22
P5710183	^S	* WING DRAG-LINK CLEVIS - PERFORM MAGNETIC PARTICLE INSPECTION (AWL*)						Service	ATA:57
	MOS	13-Mar-26	96					AIRWORTHINESS	
	HRS	9596.2	2400						
	AFL	7624							
PROC. REF: NDT PART 7/57-10-01PROC. REF: NDT PART 7/57-10-01									PKG:22
P5710184	^S	* WING ATTACH BOLTS - PERFORM FLUORESCENT PENETRANT INSPECTION (AWL*)						Service	ATA:57
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	4800						
	AFL	7624							
PROC. REF: NDT PART 8/57-10-02PROC. REF: NDT PART 8/57-10-02									PKG:25
P5710185	^S	* WING ATTACH LINKS - PERFORM MAGNETIC PARTICLE INSPECTION (AWL*)						Service	ATA:57
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	4800						
	AFL	7624							
PROC. REF: NDT PART 7/57-10-03PROC. REF: NDT PART 7/57-10-03									PKG:25
P5710186	^S	* WING ATTACH FITTINGS AT MID SPAR AND REAR SPAR - PERFORM MAGNETIC PARTICLE INSPECTION (AWL*)						Service	ATA:57
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	4800						
	AFL	7624							
PROC. REF: NDT PART 7/57-10-02PROC. REF: NDT PART 7/57-10-02									PKG:25

? - Insufficient Information
S - Suppressed Requirement
* - Estimated Due(New Requirement)
(EFF) - Effective C / W
(M) - Manual Due
U - User Task
Ex - Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
P5750002	^S	* FLAP FRONT-SPAR CUTOUTS - PERFORM EDDY CURRENT INSPECTION (AWL*)						Service	ATA:57
	MOS	13-Mar-26	96					AIRWORTHINESS	
	HRS	9596.2	2400						
	AFL	7624							
PROC. REF: NDT PART 6/57-10-15PROC. REF: NDT PART 6/57-10-15									PKG:22
P5750003	^S	* FLAP NOSE-ROLLER RIBS - PERFORM EDDY CURRENT INSPECTION (AWL*)						Service	ATA:57
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	4800						
	AFL	7624							
PROC. REF: NDT PART 6/57-10-14PROC. REF: NDT PART 6/57-10-14									PKG:25
P5750004	^S	* FLAP ACTUATOR SUPPORT RIBS - PERFORM EDDY CURRENT INSPECTION (AWL*)						Service	ATA:57
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: NDT PART 6/57-10-21PROC. REF: NDT PART 6/57-10-21									PKG:26
P5750048	^S	* FLAP TRACKS - PERFORM MAGNETIC PARTICLE INSPECTION (AWL*)						Service	ATA:57
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: NDT PART 7/57-71-01PROC. REF: NDT PART 7/57-71-01									PKG:26
P5750049	^S	* FLAP NOSE ROLLER TRACKS - PERFORM MAGNETIC PARTICLE INSPECTION WITH FLAPS REMOVED (AWL*)						Service	ATA:57
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: NDT PART 7/57-10-04PROC. REF: NDT PART 7/57-10-04									PKG:26

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR
 Serial: 45-2027
 RegNo: N116PJ
 HRS: 9841.3
 AFL: 7790
 As Of: 14-Sep-2026
 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
P5750053	^S	* FLAP TRACK SUPPORT RIBS - PERFORM EDDY CURRENT INSPECTION (AWL*)						Service	ATA:57
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: NDT PART 6/57-10-17PROC. REF: NDT PART 6/57-10-17									PKG:26
P5750068	^S	* FLAP FRONT-SPAR RIB SUPPORT STRUCTURE - PERFORM EDDY CURRENT INSPECTION (AWL*)						Service	ATA:57
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	4800						
	AFL	7624							
PROC. REF: NDT PART 6/57-10-26PROC. REF: NDT PART 6/57-10-26									PKG:25
P5760000	^S	* AILERON ACTUATOR HINGE FITTING - PERFORM EDDY CURRENT INSPECTION (AWL*)						Service	ATA:57
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: NDT PART 6/57-10-25PROC. REF: NDT PART 6/57-10-25									PKG:26
P5760001	^S	* AILERON SKIN -PERFORM EDDY CURRENT INSPECTION (AWL*)						Service	ATA:57
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: NDT PART 6/57-10-19PROC. REF: NDT PART 6/57-10-19									PKG:26
P5760002	^S	* AILERON BALANCE TAB HINGE FITTINGS - PERFORM EDDY CURRENT INSPECTION (AWL*)						Service	ATA:57
	MOS	13-Mar-26	96					AIRWORTHINESS	
	HRS	9596.2	2400						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:22

?-Insufficient Information
 S-Suppressed Requirement
 *-Estimated Due(New Requirement)
 (EFF)-Effective C / W
 (M)-Manual Due
 U-User Task
 Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
P5760003	^S	* AILERON TRIM AND BALANCE TAB FRONT SPARS - PERFORM RADIOGRAPHIC INSPECTION (AWL*)						Service	ATA:57
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	4800						
	AFL	7624							
PROC. REF: NDT PART 2/57-60-01PROC. REF: NDT PART 2/57-60-01									PKG:25
P5760005	^S	* AILERON HINGE LUGS AND FITTINGS - PERFORM EDDY CURRENT INSPECTION (AWL*)						Service	ATA:57
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: NDT PART 6/57-10-24PROC. REF: NDT PART 6/57-10-24									PKG:26
P5760014	^S	* AILERON HINGE SUPPORT STRUCTURE - PERFORM EDDY CURRENT INSPECTION (AWL*)						Service	ATA:57
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	9600						
	AFL	7624							
PROC. REF: NDT PART 6/57-10-23PROC. REF: NDT PART 6/57-10-23									PKG:26
P5770000	^S	SPOILER HINGE ASSEMBLIES AND ACTUATOR FITTING - PERFORM EDDY CURRENT INSPECTION						Service	ATA:57
	MOS	13-Mar-26							
	HRS	9596.2	4800 (+25/-25)						
	AFL	7624							
PROC. REF: NDT PART 6/57-10-22PROC. REF: NDT PART 6/57-10-22									PKG:25
V5710039	^S	WINGLET SKIN - PERFORM EDDY CURRENT INSPECTION.						Service	ATA:57
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	4800 (+25/-25)						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:25

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
Y5700001 ^S	WINGLET - PERFORM VISUAL INSPECTION								Service ATA:57
	MOS	13-Mar-26	12 (+14d/-14d)						
	HRS	9596.2	300 (+25/-25)						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:4
Y5710000 ^S	WING - PERFORM EXTERNAL VISUAL INSPECTION FROM BL 0.00 TO WS 260.								Service ATA:57
	MOS	13-Mar-26	48 (+14d/-14d)						
	HRS	9596.2	1200 (+25/-25)						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:16
Y5710180 ^S	EXTERNAL LOWER WING SKIN - PERFORM VISUAL INSPECTION.								Service ATA:57
	MOS	13-Mar-26	24 (+14d/-14d)						
	HRS	9596.2	600 (+25/-25)						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:10
Y5730013 ^S	AILERON BRUSH SEALS - PERFORM DETAILED INSPECTION								Service ATA:57
	MOS	13-Mar-26	12 (+14d/-14d)						
	HRS	9596.2	300 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 57-60-01PROC. REF: AMM 57-60-01									PKG:4
Y5750067 ^S	FLAP BRACKETS (P/N A159019-1 AND A159022-1) - PERFORM DETAILED VISUAL INSPECTION.								Service ATA:57
	MOS	13-Mar-26	96 (+14d/-14d)						
	HRS	9596.2	2400 (+25/-25)						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:22

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR
Serial: 45-2027
RegNo: N116PJ
HRS: 9841.3
AFL: 7790
As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
Y5750069	^S	FLAPS - PERFORM VISUAL INSPECTION OF FLAP NOSE ROLLERS, FLAP TRACKS, FLAP NOSE ROLLER TRACKS, AND FLAP MAIN TRACK ROLLERS						Service	ATA:57
	MOS	13-Mar-26	12 (+14d/-14d)						
	HRS	9596.2	300 (+25/-25)						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:4
Y5750071	^S	FLAPS - WITH FLAPS REMOVED, PERFORM DETAILED VISUAL INSPECTION OF FLAP NOSE ROLLERS, FLAP TRACKS, FLAP NOSE ROLLER TRACKS, AND FLAP MAIN TRACK ROLLERS.						Service	ATA:57
	MOS	13-Mar-26	48 (+14d/-14d)						
	HRS	9596.2	1200 (+25/-25)						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:16
ATA 71 - POWER PLANT									
5-19-00-Q7110004-LEFT	NO. 1 ENGINE INLET - PERFORM TAP TEST							Service	ATA:71
	MOS	10-May-23							
	HRS	9071.3	3500 (+100/-100)		12571.3	12671.3	2730 (+100)		
	AFL	7252							
PROC. REF: AMM 71-10-01PROC. REF: AMM 71-10-01									
5-19-00-Q7110004-RIGHT	NO. 2 ENGINE INLET - PERFORM TAP TEST							Service	ATA:71
	MOS	10-May-23							
	HRS	9071.3	3500 (+100/-100)		12571.3	12671.3	2730 (+100)		
	AFL	7252							
PROC. REF: AMM 71-10-01PROC. REF: AMM 71-10-01									
5-19-00-R7100032	LEFT ENGINE NACELLE TUBES - PERFORM DETAILED VISUAL INSPECTION							Service	ATA:71
	MOS/MSC	-						NOT APPLICABLE	
	HRS								
	AFL								
PROC. REF: AMM 71-10-03PROC. REF: AMM 71-10-03									

? - Insufficient Information
S - Suppressed Requirement
* - Estimated Due(New Requirement)
(EFF) - Effective C / W
(M) - Manual Due
U - User Task
Ex - Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 71 - POWER PLANT									
5-19-01-V7120074L	*REPLACE LEFT AFT ENGINE MOUNT BOLT (P/N 4571408525-001) (IRN V7120074) (AWL*)							Service	ATA:71
	MOS/MSC	10-May-05	E/C					AIRWORTHINESS	
	HRS	0							
	AFL	0							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
5-19-01-V7120074R	*REPLACE RIGHT AFT ENGINE MOUNT BOLT (P/N 4571408525-001) (IRN V7120074) (AWL*)							Service	ATA:71
	MOS/MSC	10-May-05	E/C					AIRWORTHINESS	
	HRS	0							
	AFL	0							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
710100	NO. 1 ENGINE - MAIN ENGINE WIRING HARNESS ASSEMBLY							Component	ATA:71
PN:PN	MOS/MSC	25-Jan-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-00-02, LMM 72-00-02PROC. REF: LMM 72-00-02, LMM 72-00-02									
710100	NO. 2 ENGINE - MAIN ENGINE WIRING HARNESS ASSEMBLY							Component	ATA:71
PN:PN	MOS/MSC	26-Jan-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-00-02, LMM 72-00-02PROC. REF: LMM 72-00-02, LMM 72-00-02									
710130 ^S	NO. 1 ENGINE - INSPECT TAILPIPE/LPT3 ROTOR ASSEMBLY-VISUALLY INSPECT FOR FOREIGN OBJECT DAMAGE, THERMAL DISTRESS, AND LEAKS.							Service	ATA:71
	MOS	21-Aug-25							
	HRS	9510	850 (-350)						
	ENC	7585							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									
710130 ^S	NO. 2 ENGINE - INSPECT TAILPIPE/LPT3 ROTOR ASSEMBLY-VISUALLY INSPECT FOR FOREIGN OBJECT DAMAGE, THERMAL DISTRESS, AND LEAKS.							Service	ATA:71
	MOS	25-Aug-25							
	HRS	9510	850 (-350)						
	ENC	7585							
PKG:0									
PKG:0									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
---------	------	-------	----------	------------	----------------------------	-----------	-----------	-------------	----------

ATA 71 - POWER PLANT

PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00

710140	^S	NO. 1 ENGINE - INSPECT INLET/FAN AREA - INSPECT FOR FOREIGN OBJECT DAMAGE AND LEAKAGE (REFER TO PARAGRAPH 4.B)						Service	ATA:71
	MOS	21-Aug-25							
	HRS	9510	850 (-350)						
	ENC	7585							

PROC. REF: LMM 72-00-00, LMM 72-00-00PROC. REF: LMM 72-00-00, LMM 72-00-00

PKG:0

710140	^S	NO. 2 ENGINE - INSPECT INLET/FAN AREA - INSPECT FOR FOREIGN OBJECT DAMAGE AND LEAKAGE (REFER TO PARAGRAPH 4.B)						Service	ATA:71
	MOS	25-Aug-25							
	HRS	9510	850 (-350)						
	ENC	7585							

PROC. REF: LMM 72-00-00, LMM 72-00-00PROC. REF: LMM 72-00-00, LMM 72-00-00

PKG:0

711001		NO. 1 ENGINE FORWARD MOUNT						Component	ATA:71
PN:4571200011-003	MOS/MSC	07-Dec-09	O/C						
SN:CDF1248	HRS	3096.38							
	AFL	2562							

PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00

711002		NO. 2 ENGINE FORWARD MOUNT						Component	ATA:71
PN:4571200011-003	MOS/MSC	10-May-05	O/C	TSN 0					
SN:CDF660	HRS	0		TSN 0					
	AFL	0		TSN 0					

PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00

7120004	^S	REPLACE NO. 1 ENGINE AFT ENGINE MOUNT ISOLATOR HOUSING						Component	ATA:71
PN:PN	MOS	10-May-05		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	0	15000 (+25/-25)	TSN 0					
	AFL	0		TSN 0					

PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 71 - POWER PLANT									
7120004	REPLACE NO. 1 ENGINE ALL ENGINE MOUNT ISOLATOR HOUSINGS							Component	ATA:71
	MOS	10-May-05						LIFE LIMIT	
	HRS	0	15000 (+25/-25)		15000	15025	5158.7 (+25)		
	AFL	0							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120004 ^S	REPLACE NO. 1 ENGINE FORWARD LOWER ENGINE MOUNT ISOLATOR HOUSING							Component	ATA:71
PN:PN	MOS	10-May-05		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	0	15000 (+25/-25)	TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120004 ^S	REPLACE NO. 1 ENGINE FORWARD UPPER ENGINE MOUNT ISOLATOR HOUSING							Component	ATA:71
PN:PN	MOS	10-May-05		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	0	15000 (+25/-25)	TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120004 ^S	REPLACE NO. 2 ENGINE AFT ENGINE MOUNT ISOLATOR HOUSING							Component	ATA:71
PN:PN	MOS	10-May-05		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	0	15000 (+25/-25)	TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120004	REPLACE NO. 2 ENGINE ALL ENGINE MOUNT ISOLATOR HOUSINGS							Component	ATA:71
	MOS	10-May-05						LIFE LIMIT	
	HRS	0	15000 (+25/-25)		15000	15025	5158.7 (+25)		
	AFL	0							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120004 ^S	REPLACE NO. 2 ENGINE FORWARD LOWER ENGINE MOUNT ISOLATOR HOUSING							Component	ATA:71
PN:PN	MOS	10-May-05		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	0	15000 (+25/-25)	TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 71 - POWER PLANT									
7120004	^S	REPLACE NO. 2 ENGINE FORWARD UPPER ENGINE MOUNT ISOLATOR HOUSING						Component	ATA:71
PN:PN	MOS	10-May-05		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	0	15000 (+25/-25)	TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120005	^S	REPLACE NO. 1 ENGINE AFT ENGINE MOUNT ISOLATOR FORWARD BONDED MOUNTING						Component	ATA:71
PN:PN	MOS	10-May-05		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	0	5000 (+100/-100)	TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120005		REPLACE NO. 1 ENGINE ALL ENGINE MOUNT ISOLATOR BONDED MOUNTING						Component	ATA:71
	MOS/MSC	10-May-05	N/A						
	HRS	0							
	AFL	0							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120005	^S	REPLACE NO. 1 ENGINE FORWARD LOWER ENGINE MOUNT ISOLATOR BONDED MOUNTING						Component	ATA:71
PN:PN	MOS	10-May-05		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	0	5000 (+100/-100)	TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120005	^S	REPLACE NO. 1 ENGINE FORWARD UPPER ENGINE MOUNT ISOLATOR BONDED MOUNTING						Component	ATA:71
PN:PN	MOS	10-May-05		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	0	5000 (+100/-100)	TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120005	^S	REPLACE NO. 2 ENGINE AFT ENGINE MOUNT ISOLATOR BONDED MOUNTING						Component	ATA:71
PN:PN	MOS	10-May-05		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	0	5000 (+100/-100)	TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 71 - POWER PLANT									
7120005	REPLACE NO. 2 ENGINE ALL ENGINE MOUNT ISOLATOR BONDED MOUNTING							Component	ATA:71
	MOS/MSC	10-May-05	N/A						
	HRS	0							
	AFL	0							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120005 ^S	REPLACE NO. 2 ENGINE FORWARD LOWER ENGINE MOUNT ISOLATOR BONDED MOUNTING							Component	ATA:71
PN:PN	MOS	10-May-05		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	0	5000 (+100/-100)	TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120005 ^S	REPLACE NO. 2 ENGINE FORWARD UPPER ENGINE MOUNT ISOLATOR BONDED MOUNTING							Component	ATA:71
PN:PN	MOS	10-May-05		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	0	5000 (+100/-100)	TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120006 ^S	REPLACE NO. 1 ENGINE AFT ENGINE MOUNT ISOLATOR FORWARD BONDED MOUNTING							Component	ATA:71
PN:PN	MOS	10-May-05		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	0	3500 (+100/-100)	TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120006	REPLACE NO. 1 ENGINE ALL ENGINE MOUNT ISOLATOR FORWARD BONDED MOUNTING							Component	ATA:71
PN:LM833-48	MOS	13-Mar-26		TSN 0				LIFE LIMIT	
SN:N/A	HRS	9596.2	3500 (+100/-100)	TSN 0	13096.2	13196.2	3254.9 (+100)		
	AFL	7624		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120006 ^S	REPLACE NO. 1 ENGINE FORWARD LOWER ENGINE MOUNT ISOLATOR BONDED MOUNTING							Component	ATA:71
PN:PN	MOS	10-May-05		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	0	3500 (+100/-100)	TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 71 - POWER PLANT									
7120006 ^S	REPLACE NO. 1 ENGINE FORWARD UPPER ENGINE MOUNT ISOLATOR BONDED MOUNTING								Component ATA:71
PN:PN	MOS	10-May-05		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	0	3500 (+100/-100)	TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120006 ^S	REPLACE NO. 2 ENGINE AFT ENGINE MOUNT ISOLATOR BONDED MOUNTING								Component ATA:71
PN:PN	MOS	10-May-05		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	0	3500 (+100/-100)	TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120006	REPLACE NO. 2 ENGINE ALL ENGINE MOUNT ISOLATOR FORWARD BONDED MOUNTING								Component ATA:71
PN:LM833-48	MOS	13-Mar-26		TSN 0				LIFE LIMIT	
SN:N/A	HRS	9596.2	3500 (+100/-100)	TSN 0	13096.2	13196.2	3254.9 (+100)		
	AFL	7624		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120006 ^S	REPLACE NO. 2 ENGINE FORWARD LOWER ENGINE MOUNT ISOLATOR BONDED MOUNTING								Component ATA:71
PN:PN	MOS	10-May-05		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	0	3500 (+100/-100)	TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120006 ^S	REPLACE NO. 2 ENGINE FORWARD UPPER ENGINE MOUNT ISOLATOR BONDED MOUNTING								Component ATA:71
PN:PN	MOS	10-May-05		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	0	3500 (+100/-100)	TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
712005	NO. 1 ENGINE AFT MOUNT ISOLATOR ASSEMBLY								Component ATA:71
PN:LM-833-SA18	MOS/MSC	07-Feb-14	O/C						
SN:LK2048	HRS	5991.87							
	AFL	4884							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C / W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 71 - POWER PLANT									
712006	NO. 2 ENGINE AFT MOUNT ISOLATOR ASSEMBLY							Component	ATA:71
PN:LM-833-SA18	MOS/MSC	07-Feb-14	O/C						
SN:LK2064	HRS	5991.87							
	AFL	4884							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120069 ^S	NO. 1 ENGINE AFT ISOLATOR - PERFORM VISUAL INSPECTION OF ISOLATOR AND ASSOCIATED PARTS							Service	ATA:71
	MOS/MSC	10-May-05	N/A						
	HRS	0							
	AFL	0							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120069	NO. 1 ENGINE ALL ISOLATORS - PERFORM VISUAL INSPECTION OF ISOLATORS AND ASSOCIATED PARTS							Service	ATA:71
	MOS/MSC	14-Mar-14	N/A						
	HRS	5991.87							
	AFL	4884							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120069 ^S	NO. 1 ENGINE FORWARD UPPER ISOLATOR - PERFORM VISUAL INSPECTION OF ISOLATOR AND ASSOCIATED PARTS							Service	ATA:71
	MOS/MSC	10-May-05	N/A						
	HRS	0							
	AFL	0							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120069 ^S	NO. 2 ENGINE AFT ISOLATOR - PERFORM VISUAL INSPECTION OF ISOLATOR AND ASSOCIATED PARTS							Service	ATA:71
	MOS/MSC	10-May-05	N/A						
	HRS	0							
	AFL	0							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120069	NO. 2 ENGINE ALL ISOLATORS - PERFORM VISUAL INSPECTION OF ISOLATORS AND ASSOCIATED PARTS							Service	ATA:71
	MOS/MSC	12-Mar-14	N/A						
	HRS	5991.87							
	AFL	4884							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 71 - POWER PLANT									
7120069	^S	NO. 2 ENGINE FORWARD LOWER ISOLATOR - PERFORM VISUAL INSPECTION OF ISOLATOR AND ASSOCIATED PARTS						Service	ATA:71
	MOS/MSC	10-May-05	N/A						
	HRS	0							
	AFL	0							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120069	^S	NO. 2 ENGINE FORWARD UPPER ISOLATOR - PERFORM VISUAL INSPECTION OF ISOLATOR AND ASSOCIATED PARTS						Service	ATA:71
	MOS/MSC	10-May-05	N/A						
	HRS	0							
	AFL	0							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120070	^S	REPLACE NO. 1 ENGINE AFT ENGINE MOUNT ISOLATOR BONDED MOUNTING						Component	ATA:71
PN:PN	MOS/MSC	10-May-05	N/A	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120070		REPLACE NO. 1 ENGINE ALL ENGINE MOUNT ISOLATOR BONDED MOUNTING						Component	ATA:71
PN:PN	MOS/MSC		N/A						
SN:UNKNOWN	HRS								
	AFL	0							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120070	^S	REPLACE NO. 1 ENGINE FORWARD LOWER ENGINE MOUNT ISOLATOR BONDED MOUNTING						Component	ATA:71
PN:PN	MOS/MSC	10-May-05	N/A	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120070	^S	REPLACE NO. 1 ENGINE FORWARD UPPER ENGINE MOUNT ISOLATOR BONDED MOUNTING						Component	ATA:71
PN:PN	MOS/MSC	10-May-05	N/A	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C/W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 71 - POWER PLANT									
7120070 ^S	REPLACE NO. 2 ENGINE AFT ENGINE MOUNT ISOLATOR BONDED MOUNTING							Component	ATA:71
PN:PN	MOS/MSC	10-May-05	N/A	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120070	REPLACE NO. 2 ENGINE ALL ENGINE MOUNT ISOLATOR BONDED MOUNTING							Component	ATA:71
PN:PN	MOS/MSC		N/A						
SN:UNKNOWN	HRS								
	AFL	0							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120070 ^S	REPLACE NO. 2 ENGINE FORWARD LOWER ENGINE MOUNT ISOLATOR BONDED MOUNTING							Component	ATA:71
PN:PN	MOS/MSC	10-May-05	N/A	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120070 ^S	REPLACE NO. 2 ENGINE FORWARD UPPER ENGINE MOUNT ISOLATOR BONDED MOUNTING							Component	ATA:71
PN:PN	MOS/MSC	10-May-05	N/A	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120073 ^S	NO. 1 ENGINE AFT ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS							Service	ATA:71
	MOS/MSC	10-May-05	N/A						
	HRS	0							
	AFL	0							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120073	NO. 1 ENGINE ALL ISOLATORS - PERFORM INSPECTION OF ISOLATORS AND ASSOCIATED PARTS							Service	ATA:71
	MOS/MSC	07-Feb-14	N/A						
	HRS	5991.87							
	AFL	4884							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									

?-Insufficient Information

S-Suppressed Requirement

*-Estimated Due(New Requirement)

(EFF)-Effective C / W

(M)-Manual Due

U-User Task

Ex-Excluded Task

Status Report

Model: LEARJET 40XR
Serial: 45-2027
RegNo: N116PJ
HRS: 9841.3
AFL: 7790
As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 71 - POWER PLANT									
7120073	^S	NO. 1 ENGINE FORWARD LOWER ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS							Service ATA:71
	MOS / MSC	10-May-05	N/A						
	HRS	0							
	AFL	0							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120073	^S	NO. 1 ENGINE FORWARD UPPER ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS							Service ATA:71
	MOS / MSC	10-May-05	N/A						
	HRS	0							
	AFL	0							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120073	^S	NO. 2 ENGINE AFT ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS							Service ATA:71
	MOS / MSC	10-May-05	N/A						
	HRS	0							
	AFL	0							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120073		NO. 2 ENGINE ALL ISOLATORS - PERFORM INSPECTION OF ISOLATORS AND ASSOCIATED PARTS							Service ATA:71
	MOS / MSC	07-Feb-14	N/A						
	HRS	5991.87							
	AFL	4884							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120073	^S	NO. 2 ENGINE FORWARD LOWER ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS							Service ATA:71
	MOS / MSC	10-May-05	N/A						
	HRS	0							
	AFL	0							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120073	^S	NO. 2 ENGINE FORWARD UPPER ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS							Service ATA:71
	MOS / MSC	10-May-05	N/A						
	HRS	0							
	AFL	0							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									

? - Insufficient Information
S - Suppressed Requirement
* - Estimated Due (New Requirement)
(EFF) - Effective C / W
(M) - Manual Due
U - User Task
Ex - Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 71 - POWER PLANT									
714010 ^S		NO. 1 ENGINE - CHECK ELECTRICAL WIRES AND CONNECTIONS - VISUALLY INSPECT FOR SECURITY AND DAMAGE						Service	ATA:71
	MOS	21-Aug-25							
	HRS	9510	850 (-350)						
	ENC	7585							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									PKG:0
714010 ^S		NO. 2 ENGINE - CHECK ELECTRICAL WIRES AND CONNECTIONS - VISUALLY INSPECT FOR SECURITY AND DAMAGE						Service	ATA:71
	MOS	25-Aug-25							
	HRS	9510	850 (-350)						
	ENC	7585							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									PKG:0
715010 ^S		NO. 1 ENGINE - CHECK PLUMBING LINES AND CONNECTIONS - VISUALLY INSPECT FOR SECURITY, LOOSE OR BROKEN CLAMPS OR BRACKETS, LEAKS, CRACKS, CUTS, OR RUBBING						Service	ATA:71
	MOS	21-Aug-25							
	HRS	9510	850 (-350)						
	ENC	7585							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									PKG:0
715010 ^S		NO. 2 ENGINE - CHECK PLUMBING LINES AND CONNECTIONS - VISUALLY INSPECT FOR SECURITY, LOOSE OR BROKEN CLAMPS OR BRACKETS, LEAKS, CRACKS, CUTS, OR RUBBING						Service	ATA:71
	MOS	25-Aug-25							
	HRS	9510	850 (-350)						
	ENC	7585							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									PKG:0
71EN1		NO. 1 ENGINE						Component	ATA:71
PN:3060084-1	MOS/MSC	13-Mar-26	E/C						
SN:P-116596C	HRS	9596.2							
WC#: 71.EN1	AFL	7624							
PROC. REF: SIL F731-88, AMM 71-00-01PROC. REF: SIL F731-88, AMM 71-00-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR
Serial: 45-2027
RegNo: N116PJ
HRS: 9841.3
AFL: 7790
As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 71 - POWER PLANT									
71EN2	NO. 2 ENGINE								Component ATA:71
PN:3060084-1	MOS/MSC	13-Mar-26	E/C						
SN:P-116597C	HRS	9596.2							
WC#: 71.EN2	AFL	7624							
PROC. REF: SIL F731-88, AMM 71-00-01PROC. REF: SIL F731-88, AMM 71-00-01									
P7120001 ^S	* FORWARD ENGINE MOUNT - PERFORM EDDY CURRENT INSPECTION (AWL*)								Service ATA:71
	MOS	13-Mar-26						AIRWORTHINESS	
	HRS	9596.2	4800						
	AFL	7624							
PROC. REF: NDT PART 6/71-10-01PROC. REF: NDT PART 6/71-10-01									
Y7100002 ^S	LOWER ENGINE COWLING - VISUALLY INSPECT LATCH CHANNELS FOR CHAFING.								Service ATA:71
	MOS	13-Mar-26	24 (+14d/-14d)						
	HRS	9596.2	600 (+25/-25)						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
Y7110000 ^S	ENGINE NACELLE - PERFORM VISUAL INSPECTION. INSPECT INLET BULKHEAD, STRUCTURE, PLUMBING, SKIN SPOT WELDS, ANTI-ICE OUTLET SCREEN, AND FASTENERS FOR SECURITY, CRACKS, AND GENERAL CONDITION.								Service ATA:71
	MOS	13-Mar-26	24 (+14d/-14d)						
	HRS	9596.2	600 (+25/-25)						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
Y7110001 ^S	ENGINE INLET LIP AND DUCT - PERFORM VISUAL INSPECTION.								Service ATA:71
	MOS	13-Mar-26	24 (+14d/-14d)						
	HRS	9596.2	600 (+25/-25)						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

? - Insufficient Information
S - Suppressed Requirement
* - Estimated Due(New Requirement)
(EFF) - Effective C / W
(M) - Manual Due
U - User Task
Ex - Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 71 - POWER PLANT									
Y7110002	^S	ENGINE STARTER/GENERATOR INLET AND EXHAUST DUCT AND SEALS - PERFORM VISUAL INSPECTION.							Service ATA:71
	MOS	13-Mar-26	24 (+14d/-14d)						
	HRS	9596.2	600 (+25/-25)						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:9
Y7110003	^S	ENGINE ALTERNATOR EXHAUST DUCT AND SEALS - PERFORM VISUAL INSPECTION.							Service ATA:71
	MOS	13-Mar-26	24 (+14d/-14d)						
	HRS	9596.2	600 (+25/-25)						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:9
Y7120000	^S	FORWARD ENGINE MOUNTS - PERFORM VISUAL INSPECTION							Service ATA:71
	MOS	13-Mar-26	12 (+14d/-14d)						
	HRS	9596.2	300 (+25/-25)						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:3
ATA 72 - ENGINE									
72-AS-720005		NO. 1 ENGINE - INSPECT MAJOR PERIODIC PER MANUFACTURERS INSTRUCTIONS							Service ATA:72
	MOS	21-Aug-25							
	HRS	9510	3500 (+100)		(13010) 13094	13110	3252.7 (+100)		
	ENC	7585							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									
72-AS-720005		NO. 2 ENGINE - INSPECT MAJOR PERIODIC PER MANUFACTURERS INSTRUCTIONS							Service ATA:72
	MOS	25-Aug-25							
	HRS	9510	3500 (+100)		(13010) 13094	13110	3252.7 (+100)		
	ENC	7585							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR
Serial: 45-2027
RegNo: N116PJ
HRS: 9841.3
AFL: 7790
As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
72-AS-720006	^S	NO. 1 ENGINE - INSPECT COMB CHAMBER PLENUM CASE INSP PER MANUFACTURERS INSTRUCTIONS							Service ATA:72
	MOS	25-Jan-05							
	HRS	0	3500 (+100/-100)						
	ENC	0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
72-AS-720006	^S	NO. 2 ENGINE - INSPECT COMB CHAMBER PLENUM CASE INSP PER MANUFACTURERS INSTRUCTIONS							Service ATA:72
	MOS	26-Jan-05							
	HRS	0	3500 (+100/-100)						
	ENC	0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
72-AS-720007		NO. 1 ENGINE - INSPECT COMPRESSOR ZONE PER MANUFACTURERS INSTRUCTIONS							Service ATA:72
	MOS	14-Mar-14							
	HRS	5991.87	7000 (+200)		(12991.87) 13075.87	13191.87	3234.6 (+200)		
	ENC	4884							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									
72-AS-720007		NO. 2 ENGINE - INSPECT COMPRESSOR ZONE PER MANUFACTURERS INSTRUCTIONS							Service ATA:72
	MOS	12-Mar-14							
	HRS	5991.87	7000 (+200)		(12991.87) 13075.87	13191.87	3234.6 (+200)		
	ENC	4884							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									
72-AS-720008	^S	NO. 1 ENGINE - INSPECT AGB PER MANUFACTURERS INSTRUCTIONS							Service ATA:72
	MOS	25-Jan-05							
	HRS	0	7000 (+200/-200)						
	ENC	0							
PROC. REF: LMM 72-60-02PROC. REF: LMM 72-60-02									
72-AS-720008	^S	NO. 2 ENGINE - INSPECT AGB PER MANUFACTURERS INSTRUCTIONS							Service ATA:72
	MOS	26-Jan-05							
	HRS	0	7000 (+200/-200)						
	ENC	0							
PROC. REF: LMM 72-60-02PROC. REF: LMM 72-60-02									

? - Insufficient Information
S - Suppressed Requirement
* - Estimated Due(New Requirement)
(EFF) - Effective C / W
(M) - Manual Due
U - User Task
Ex - Excluded Task

Status Report

Model: LEARJET 40XR
Serial: 45-2027
RegNo: N116PJ
HRS: 9841.3
AFL: 7790
As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
72-AS-720010		NO. 1 ENGINE - ANALYSIS OIL AND FILTER (BASELINE/SPECIAL REQUIREMENT) (SOAP)						Service	ATA:72
	MOS/MSC	18-Jul-05	A/R						
	HRS	13.7							
	ENC	11							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									
72-AS-720010		NO. 2 ENGINE - ANALYSIS OIL AND FILTER (BASELINE/SPECIAL REQUIREMENT) (SOAP)						Service	ATA:72
	MOS/MSC	18-Jul-05	A/R						
	HRS	13.7							
	ENC	11							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									
72-AS-720011		NO. 1 ENGINE - REPLACE FUEL FILTER ELEMENT (25-HR INITIAL)						Service	ATA:72
	MOS/MSC	18-Jul-05	A/R						
	HRS	13.7							
	ENC	11							
PROC. REF: LMM 73-21-02PROC. REF: LMM 73-21-02									
72-AS-720011		NO. 2 ENGINE - REPLACE FUEL FILTER ELEMENT (25-HR INITIAL)						Service	ATA:72
	MOS/MSC	18-Jul-05	A/R						
	HRS	13.7							
	ENC	11							
PROC. REF: LMM 73-21-02PROC. REF: LMM 73-21-02									
720110		NO. 1 ENGINE - ACCESSORY GEARBOX						Component	ATA:72
PN:3060827-2	MOS/MSC	25-Jan-05	O/C	TSN 0					
SN:S-2066	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-60-02, LMM 72-60-02PROC. REF: LMM 72-60-02, LMM 72-60-02									
720110		NO. 2 ENGINE - ACCESSORY GEARBOX						Component	ATA:72
PN:3060827-2	MOS/MSC	26-Jan-05	O/C	TSN 0					
SN:S-2062	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-60-02, LMM 72-60-02PROC. REF: LMM 72-60-02, LMM 72-60-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
723010 ^S		NO. 1 ENGINE - CHECK CARBON SEAL HEALTH						Service	ATA:72
	MOS	21-Aug-25							
	HRS	9510	1600 (+50/-100)						
	ENC	7585							
PROC. REF: LMM 72-00-00, LMM 72-00-00PROC. REF: LMM 72-00-00, LMM 72-00-00									
PKG:0									
723010 ^S		NO. 2 ENGINE - CHECK CARBON SEAL HEALTH						Service	ATA:72
	MOS	25-Aug-25							
	HRS	9510	1600 (+50/-100)						
	ENC	7585							
PROC. REF: LMM 72-00-00, LMM 72-00-00PROC. REF: LMM 72-00-00, LMM 72-00-00									
PKG:0									
725007		NO. 1 ENGINE - HIGH PRESSURE TURBINE (HPT) NOZZLE ASSEMBLY						Component	ATA:72
PN:PN	MOS/MSC	25-Jan-05	A/R	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 72.500	ENC	0		TSN 0					
PROC. REF: LMM 72-50-07, LMM 72-50-07PROC. REF: LMM 72-50-07, LMM 72-50-07									
725007		NO. 2 ENGINE - HIGH PRESSURE TURBINE (HPT) NOZZLE ASSEMBLY						Component	ATA:72
PN:PN	MOS/MSC	26-Jan-05	A/R	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 72.500	ENC	0		TSN 0					
PROC. REF: LMM 72-50-07, LMM 72-50-07PROC. REF: LMM 72-50-07, LMM 72-50-07									
725010		NO. 1 ENGINE - 1ST-STAGE LOW PRESSURE TURBINE (LPT) DISC						Component	ATA:72
PN:3060625-1	MOS	25-Jan-05		TSN 0				LIFE LIMIT	
SN:040322901930	HRS	0		TSN 0					
	ENC	0	12000	TSN 0	(12000) 12038		4248		
PROC. REF: LMM 72-50-04, LMM 72-50-04PROC. REF: LMM 72-50-04, LMM 72-50-04									

?-Insufficient Information

S-Suppressed Requirement

*-Estimated Due(New Requirement)

(EFF)-Effective C / W

(M)-Manual Due

U-User Task

Ex-Excluded Task

Status Report

Model: LEARJET 40XR
Serial: 45-2027
RegNo: N116PJ
HRS: 9841.3
AFL: 7790
As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
725010	NO. 2 ENGINE - 1ST-STAGE LOW PRESSURE TURBINE (LPT) DISC								Component ATA:72
PN:3060625-1	MOS	26-Jan-05		TSN 0				LIFE LIMIT	
SN:040322901934	HRS	0		TSN 0					
	ENC	0	12000	TSN 0	(12000) 12038		4248		
PROC. REF: LMM 72-50-04, LMM 72-50-04PROC. REF: LMM 72-50-04, LMM 72-50-04									
725020	NO. 1 ENGINE - 2ND-STAGE LOW PRESSURE TURBINE (LPT) DISC								Component ATA:72
PN:3060611-1	MOS	25-Jan-05		TSN 0				LIFE LIMIT	
SN:040322901467	HRS	0		TSN 0					
	ENC	0	12000	TSN 0	(12000) 12038		4248		
PROC. REF: LMM 72-50-04, LMM 72-50-04PROC. REF: LMM 72-50-04, LMM 72-50-04									
725020	NO. 2 ENGINE - 2ND-STAGE LOW PRESSURE TURBINE (LPT) DISC								Component ATA:72
PN:3060611-1	MOS	26-Jan-05		TSN 0				LIFE LIMIT	
SN:040322900200	HRS	0		TSN 0					
	ENC	0	12000	TSN 0	(12000) 12038		4248		
PROC. REF: LMM 72-50-04, LMM 72-50-04PROC. REF: LMM 72-50-04, LMM 72-50-04									
725030	NO. 1 ENGINE - 3RD-STAGE LOW PRESSURE TURBINE (LPT) DISC								Component ATA:72
PN:3060671-2	MOS	25-Jan-05		TSN 0				LIFE LIMIT	
SN:040322902116	HRS	0		TSN 0					
	ENC	0	12000	TSN 0	(12000) 12038		4248		
PROC. REF: LMM 72-50-04, LMM 72-50-04PROC. REF: LMM 72-50-04, LMM 72-50-04									
725030	NO. 2 ENGINE - 3RD-STAGE LOW PRESSURE TURBINE (LPT) DISC								Component ATA:72
PN:3060671-2	MOS	26-Jan-05		TSN 0				LIFE LIMIT	
SN:040322902117	HRS	0		TSN 0					
	ENC	0	12000	TSN 0	(12000) 12038		4248		
PROC. REF: LMM 72-50-04, LMM 72-50-04PROC. REF: LMM 72-50-04, LMM 72-50-04									

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C / W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
725040	NO. 1 ENGINE - HIGH PRESSURE TURBINE (HPT) DISC								Component ATA:72
PN:3060841-1	MOS	21-Aug-25		TSN 0				LIFE LIMIT	
SN:24-162246-04265	HRS	9510		TSN 0					
	ENC	7585	10000	TSN 0	(17585) 17623		9833		
PROC. REF: LMM 72-50-07, LMM 72-50-07PROC. REF: LMM 72-50-07, LMM 72-50-07									
725040	NO. 2 ENGINE - HIGH PRESSURE TURBINE (HPT) DISC								Component ATA:72
PN:3060841-1	MOS	25-Aug-25		TSN 0				LIFE LIMIT	
SN:24-162246-04263	HRS	9510		TSN 0					
	ENC	7585	10000	TSN 0	(17585) 17623		9833		
PROC. REF: LMM 72-50-07, LMM 72-50-07PROC. REF: LMM 72-50-07, LMM 72-50-07									
725045	NO. 1 ENGINE - HIGH PRESSURE TURBINE (HPT) ASSY								Component ATA:72
PN:PN	MOS/MSC	25-Jan-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
725045	NO. 2 ENGINE - HIGH PRESSURE TURBINE (HPT) ASSY								Component ATA:72
PN:PN	MOS/MSC	26-Jan-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
725050	NO. 1 ENGINE - FAN DISC								Component ATA:72
PN:3060287-2	MOS	25-Jan-05		TSN 0				LIFE LIMIT	
SN:030322902310	HRS	0		TSN 0					
	ENC	0	20000	TSN 0	(20000) 20038		12248		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725050	NO. 2 ENGINE - FAN DISC								Component ATA:72
PN:3060287-2	MOS	26-Jan-05		TSN 0				LIFE LIMIT	
SN:040322900791	HRS	0		TSN 0					
	ENC	0	20000	TSN 0	(20000) 20038		12248		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725060	NO. 1 ENGINE - 1ST-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC								Component ATA:72
PN:3060372-1	MOS	25-Jan-05		TSN 0				LIFE LIMIT	
SN:040306003327	HRS	0		TSN 0					
	ENC	0	10000	TSN 0	(10000) 10038		2248		
PROC. REF: LMM 72-30-04PROC. REF: LMM 72-30-04									
725060	NO. 2 ENGINE - 1ST-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC								Component ATA:72
PN:3060372-1	MOS	26-Jan-05		TSN 0				LIFE LIMIT	
SN:040316003325	HRS	0		TSN 0					
	ENC	0	10000	TSN 0	(10000) 10038		2248		
PROC. REF: LMM 72-30-04PROC. REF: LMM 72-30-04									
725070	NO. 1 ENGINE - 2ND-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC								Component ATA:72
PN:3060373-1	MOS	25-Jan-05		TSN 0				LIFE LIMIT	
SN:040316002582	HRS	0		TSN 0					
	ENC	0	10000	TSN 0	(10000) 10038		2248		
PROC. REF: LMM 72-30-04PROC. REF: LMM 72-30-04									
725070	NO. 2 ENGINE - 2ND-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC								Component ATA:72
PN:3060373-1	MOS	26-Jan-05		TSN 0				LIFE LIMIT	
SN:040316002571	HRS	0		TSN 0					
	ENC	0	10000	TSN 0	(10000) 10038		2248		
PROC. REF: LMM 72-30-04PROC. REF: LMM 72-30-04									
725080	NO. 1 ENGINE - 3RD-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC								Component ATA:72
PN:3060374-1	MOS	25-Jan-05		TSN 0				LIFE LIMIT	
SN:040316002226	HRS	0		TSN 0					
	ENC	0	20000	TSN 0	(20000) 20038		12248		
PROC. REF: LMM 72-30-04PROC. REF: LMM 72-30-04									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
725080	NO. 2 ENGINE - 3RD-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC								Component ATA:72
PN:3060374-1	MOS	26-Jan-05		TSN 0				LIFE LIMIT	
SN:040316002225	HRS	0		TSN 0					
	ENC	0	20000	TSN 0	(20000) 20038		12248		
PROC. REF: LMM 72-30-04PROC. REF: LMM 72-30-04									
725090	NO. 1 ENGINE - 4TH-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC								Component ATA:72
PN:3075326-5	MOS	25-Jan-05		TSN 0				LIFE LIMIT	
SN:040350107662	HRS	0		TSN 0					
	ENC	0	20000	TSN 0	(20000) 20038		12248		
PROC. REF: LMM 72-30-04PROC. REF: LMM 72-30-04									
725090	NO. 2 ENGINE - 4TH-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC								Component ATA:72
PN:3075326-5	MOS	26-Jan-05		TSN 0				LIFE LIMIT	
SN:040350107603	HRS	0		TSN 0					
	ENC	0	20000	TSN 0	(20000) 20038		12248		
PROC. REF: LMM 72-30-04PROC. REF: LMM 72-30-04									
725110	NO. 1 ENGINE - LOW PRESSURE COMPRESSOR TIE ROD								Component ATA:72
PN:3074744-1	MOS/MSC	25-Jan-05	O / C	TSN 0					
SN:04P22935	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-30-10, LMM 72-30-10PROC. REF: LMM 72-30-10, LMM 72-30-10									
725110	NO. 2 ENGINE - LOW PRESSURE COMPRESSOR TIE ROD								Component ATA:72
PN:3074744-1	MOS/MSC	26-Jan-05	O / C	TSN 0					
SN:04P22921	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-30-10, LMM 72-30-10PROC. REF: LMM 72-30-10, LMM 72-30-10									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
725120	NO. 1 ENGINE - HIGH PRESSURE COMPRESSOR ROTOR IMPELLER								Component ATA:72
PN:3060371-1	MOS			TSN 0				LIFE LIMIT	
SN:13-182449-10175	HRS			TSN 0					
	ENC	0	8000	TSN 0	(12884) 12922 (M)		5132		
PROC. REF: LMM 72-50-06, LMM 72-50-06PROC. REF: LMM 72-50-06, LMM 72-50-06									
725120	NO. 2 ENGINE - HIGH PRESSURE COMPRESSOR ROTOR IMPELLER								Component ATA:72
PN:3060371-1	MOS			TSN 0				LIFE LIMIT	
SN:13-182449-09492	HRS			TSN 0					
	ENC	0	8000	TSN 0	(12884) 12922 (M)		5132		
PROC. REF: LMM 72-50-06, LMM 72-50-06PROC. REF: LMM 72-50-06, LMM 72-50-06									
725130	NO. 1 ENGINE - FAN SPINNER								Component ATA:72
PN:3060156-2	MOS	25-Jan-05		TSN 0				LIFE LIMIT	
SN:042784300293	HRS	0		TSN 0					
	ENC	0	20000	TSN 0	(20000) 20038		12248		
PROC. REF: LMM 72-70-01, LMM 72-70-01PROC. REF: LMM 72-70-01, LMM 72-70-01									
725130	NO. 2 ENGINE - FAN SPINNER								Component ATA:72
PN:3060156-2	MOS	26-Jan-05		TSN 0				LIFE LIMIT	
SN:042784300283	HRS	0		TSN 0					
	ENC	0	20000	TSN 0	(20000) 20038		12248		
PROC. REF: LMM 72-70-01, LMM 72-70-01PROC. REF: LMM 72-70-01, LMM 72-70-01									
725140	NO. 1 ENGINE - FAN DRIVE SHAFT								Component ATA:72
PN:3060180-2	MOS/MSC	25-Jan-05	O/C	TSN 0					
SN:041366303699	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
725140	NO. 2 ENGINE - FAN DRIVE SHAFT								Component ATA:72
PN:3067021-1	MOS/MSC	26-Jan-05	O/C	TSN 0					
SN:010339000673	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725160	NO. 1 ENGINE - FORWARD ROTOR HIGH PRESSURE SEAL								Component ATA:72
PN:3060698-1	MOS			TSN 0				LIFE LIMIT	
SN:13-162246-00058	HRS			TSN 0					
	ENC	0	7000	TSN 0	(11884) 11922 (M)		4132		
PROC. REF: LMM 72-70-03, LMM 72-70-03PROC. REF: LMM 72-70-03, LMM 72-70-03									
725160	NO. 2 ENGINE - FORWARD ROTOR HIGH PRESSURE SEAL								Component ATA:72
PN:3060698-1	MOS			TSN 0				LIFE LIMIT	
SN:12-162053-47102	HRS			TSN 0					
	ENC	0	7000	TSN 0	(11884) 11922 (M)		4132		
PROC. REF: LMM 72-70-03, LMM 72-70-03PROC. REF: LMM 72-70-03, LMM 72-70-03									
725170	NO. 1 ENGINE - HIGH PRESSURE SHOULDERED SHAFT								Component ATA:72
PN:3060366-3	MOS/MSC	25-Jan-05	O/C	TSN 0					
SN:04P26318	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725170	NO. 2 ENGINE - HIGH PRESSURE SHOULDERED SHAFT								Component ATA:72
PN:3060366-3	MOS/MSC	26-Jan-05	O/C	TSN 0					
SN:04P25139	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725180	NO. 1 ENGINE - COMBUSTION PLENUM CASE								Component ATA:72
PN:3060534-4	MOS/MSC	25-Jan-05	O/C	TSN 0					
SN:04P23220	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-40-04, LMM 72-40-04PROC. REF: LMM 72-40-04, LMM 72-40-04									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
725180	NO. 2 ENGINE - COMBUSTION PLENUM CASE								Component ATA:72
PN:3060534-4	MOS/MSC	26-Jan-05	O/C	TSN 0					
SN:04P24170	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-40-04, LMM 72-40-04PROC. REF: LMM 72-40-04, LMM 72-40-04									
725210	NO. 1 ENGINE - HIGH PRESSURE TURBINE FORWARD SEAL PLATE								Component ATA:72
PN:3060514-1	MOS	21-Aug-25		TSN 0				LIFE LIMIT	
SN:2318244945089	HRS	9510		TSN 0					
	ENC	7585	10000	TSN 0	(17585) 17623		9833		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725210	NO. 2 ENGINE - HIGH PRESSURE TURBINE FORWARD SEAL PLATE								Component ATA:72
PN:3060514-1	MOS	25-Aug-25		TSN 0				LIFE LIMIT	
SN:1518244919022	HRS	9510		TSN 0					
	ENC	7585	10000	TSN 0	(17585) 17623		9833		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725220	NO. 1 ENGINE - TURBINE INTERSTAGE TRANSITION DUCT								Component ATA:72
PN:3060694-6	MOS/MSC	21-Aug-25	O/C	TSN 247, TSO 0					
SN:02P01802	HRS	9510		TSN 9510, TSO 0					
	ENC	7585		TSN 7585, TSO 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725220	NO. 2 ENGINE - TURBINE INTERSTAGE TRANSITION DUCT								Component ATA:72
PN:3060694-6	MOS/MSC	26-Jan-05	O/C	TSN 0					
SN:00P27570	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725230	NO. 1 ENGINE - LOW PRESSURE TURBINE (LPT) 1 NOZZLE SEAL SUPPORT								Component ATA:72
PN:3060693-1	MOS/MSC	25-Jan-05	O/C	TSN 0					
SN:01P15821	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-50-04, LMM 72-50-04PROC. REF: LMM 72-50-04, LMM 72-50-04									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
725230	NO. 2 ENGINE - LOW PRESSURE TURBINE (LPT) 1 NOZZLE SEAL SUPPORT							Component	ATA:72
PN:3060693-1	MOS/MSC	26-Jan-05	O/C	TSN 0					
SN:950740420408	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-50-04, LMM 72-50-04PROC. REF: LMM 72-50-04, LMM 72-50-04									
725240	NO. 1 ENGINE - LOW PRESSURE TURBINE (LPT) 1 NOZZLE ASSEMBLY							Component	ATA:72
PN:3060666-7	MOS/MSC	25-Jan-05	O/C	TSN 0					
SN:08P11075	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-50-04, LMM 72-50-04PROC. REF: LMM 72-50-04, LMM 72-50-04									
725240	NO. 2 ENGINE - LOW PRESSURE TURBINE (LPT) 1 NOZZLE ASSEMBLY							Component	ATA:72
PN:3060666-7	MOS/MSC	26-Jan-05	O/C	TSN 0					
SN:950740418475	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-50-04, LMM 72-50-04PROC. REF: LMM 72-50-04, LMM 72-50-04									
725250	NO. 1 ENGINE - FORWARD SHAFT HIGH PRESSURE TURBINE (HPT) COUPLING							Component	ATA:72
PN:3060502-2	MOS/MSC	25-Jan-05	O/C	TSN 0					
SN:05P00427	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725250	NO. 2 ENGINE - FORWARD SHAFT HIGH PRESSURE TURBINE (HPT) COUPLING							Component	ATA:72
PN:3060502-2	MOS/MSC	26-Jan-05	O/C	TSN 0					
SN:04P25580	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725260	NO. 1 ENGINE - AFT HIGH PRESSURE TURBINE (HPT) SHAFT COUPLING							Component	ATA:72
PN:3060599-2	MOS/MSC	25-Jan-05	O/C	TSN 0					
SN:04P26086	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR
 Serial: 45-2027
 RegNo: N116PJ
 HRS: 9841.3
 AFL: 7790
 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
725260	NO. 2 ENGINE - AFT HIGH PRESSURE TURBINE (HPT) SHAFT COUPLING							Component	ATA:72
PN:3060599-2	MOS/MSC	26-Jan-05	O/C	TSN 0					
SN:04P25408	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725270	NO. 1 ENGINE - NOZZLE LOW PRESSURE TURBINE (LPT) (A5) SEAL							Component	ATA:72
PN:3073765-12	MOS/MSC	25-Jan-05	O/C	TSN 0					
SN:01P15394	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725270	NO. 2 ENGINE - NOZZLE LOW PRESSURE TURBINE (LPT) (A5) SEAL							Component	ATA:72
PN:3073765-12	MOS/MSC	26-Jan-05	O/C	TSN 0					
SN:95074042151	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
726005	NO. 1 ENGINE - TRANSFER GEARBOX ASSEMBLY							Component	ATA:72
PN:3070093-16	MOS/MSC	25-Jan-05	O/C	TSN 0					
SN:04P11300	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-60-03, LMM 72-60-03PROC. REF: LMM 72-60-03, LMM 72-60-03									
726005	NO. 2 ENGINE - TRANSFER GEARBOX ASSEMBLY							Component	ATA:72
PN:3070093-16	MOS/MSC	26-Jan-05	O/C	TSN 0					
SN:04P11302	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-60-03, LMM 72-60-03PROC. REF: LMM 72-60-03, LMM 72-60-03									
727006	NO. 1 ENGINE - LOWER FAN DUCT ASSEMBLY							Component	ATA:72
PN:PN	MOS/MSC	25-Jan-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-70-05, LMM 72-70-05PROC. REF: LMM 72-70-05, LMM 72-70-05									

?-Insufficient Information
 S-Suppressed Requirement
 *-Estimated Due(New Requirement)
 (EFF)-Effective C / W
 (M)-Manual Due
 U-User Task
 Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
727006	NO. 2 ENGINE - LOWER FAN DUCT ASSEMBLY								Component ATA:72
PN:PN	MOS/MSC	26-Jan-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-70-05, LMM 72-70-05PROC. REF: LMM 72-70-05, LMM 72-70-05									
727010 ^S	NO. 1 ENGINE - INSPECT BYPASS STATOR VANE ASSEMBLY.								Service ATA:72
	MOS	21-Aug-25							
	HRS	9510	1200 (+100/-200)						
	ENC	7585							
PROC. REF: LMM 72-70-04, LMM 72-70-04, LMM 72-70-04PROC. REF: LMM 72-70-04, LMM 72-70-04, LMM 72-70-04									
727010 ^S	NO. 2 ENGINE - INSPECT BYPASS STATOR VANE ASSEMBLY.								Service ATA:72
	MOS	25-Aug-25							
	HRS	9510	1200 (+100/-200)						
	ENC	7585							
PROC. REF: LMM 72-70-04, LMM 72-70-04, LMM 72-70-04PROC. REF: LMM 72-70-04, LMM 72-70-04, LMM 72-70-04									
ATA 73 - ENGINE FUEL AND CONTROL									
730110	NO. 1 ENGINE - FUEL CONTROL UNIT								Component ATA:73
PN:3070800-47	MOS/MSC	06-Oct-20	O/C	TSR 0					
SN:16117	HRS	7987.5		TSR 0					
	ENC	6473		TSR 0					
PROC. REF: LMM 73-20-01, LMM 73-20-01PROC. REF: LMM 73-20-01, LMM 73-20-01									
730110	NO. 2 ENGINE - FUEL CONTROL UNIT								Component ATA:73
PN:3070800-37	MOS/MSC	26-Jan-05	O/C	TSN 0					
SN:16768	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 73-20-01, LMM 73-20-01PROC. REF: LMM 73-20-01, LMM 73-20-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 73 - ENGINE FUEL AND CONTROL									
730120		NO. 1 ENGINE - REPLACE FUEL FILTER ELEMENT							Service ATA:73
	MOS	21-Apr-26							
	HRS	9571	600		(10171) 10255	10176	413.7 (+5)		
	ENC	7628							
PROC. REF: LMM 73-21-02, LMM 73-21-02PROC. REF: LMM 73-21-02, LMM 73-21-02									
PKG:0									
730120		NO. 2 ENGINE - REPLACE FUEL FILTER ELEMENT							Service ATA:73
	MOS	21-Apr-26							
	HRS	9571	600		(10171) 10255	10176	413.7 (+5)		
	ENC	7628							
PROC. REF: LMM 73-21-02, LMM 73-21-02PROC. REF: LMM 73-21-02, LMM 73-21-02									
PKG:0									
730130		NO. 1 ENGINE - ENGINE FUEL PUMP ASSEMBLY							Component ATA:73
PN:3060760-4	MOS/MSC	25-Jan-05	O/C	TSN 0					
SN:1682	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 73-20-01, LMM 73-20-01, LMM 73-20-01, LMM 73-20-01PROC. REF: LMM 73-20-01, LMM 73-20-01, LMM 73-20-01, LMM 73-20-01									
730130		NO. 2 ENGINE - ENGINE FUEL PUMP ASSEMBLY							Component ATA:73
PN:3060760-4	MOS/MSC	26-Jan-05	O/C	TSN 0					
SN:1660	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 73-20-01, LMM 73-20-01, LMM 73-20-01, LMM 73-20-01PROC. REF: LMM 73-20-01, LMM 73-20-01, LMM 73-20-01, LMM 73-20-01									
731001		NO. 1 ENGINE - MOTIVE FLOW FUEL PUMP ASSEMBLY							Component ATA:73
PN:3060759-1	MOS/MSC	25-Jan-05	O/C	TSN 0					
SN:0985	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 73-21-02PROC. REF: LMM 73-21-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 73 - ENGINE FUEL AND CONTROL									
731001	NO. 2 ENGINE - MOTIVE FLOW FUEL PUMP ASSEMBLY							Component	ATA:73
PN:3060759-1	MOS/MSC	26-Jan-05	O/C	TSN 0					
SN:1658	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 73-21-02PROC. REF: LMM 73-21-02									
731110	NO. 1 ENGINE - PRESSURE LIMITER (PCD) VALVE							Component	ATA:73
PN:3070685-11	MOS/MSC	25-Jan-05	O/C	TSN 0					
SN:16227	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 73-20-01, LMM 73-20-01PROC. REF: LMM 73-20-01, LMM 73-20-01									
731110	NO. 2 ENGINE - PRESSURE LIMITER (PCD) VALVE							Component	ATA:73
PN:3070685-11	MOS/MSC	26-Jan-05	O/C	TSN 0					
SN:16255	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 73-20-01, LMM 73-20-01PROC. REF: LMM 73-20-01, LMM 73-20-01									
731120	NO. 1 ENGINE - FUEL FLOW DIVIDER/DRAIN VALVE							Component	ATA:73
PN:394476-2	MOS/MSC	25-Jan-05	O/C	TSN 0					
SN:1819	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
731120	NO. 2 ENGINE - FUEL FLOW DIVIDER/DRAIN VALVE							Component	ATA:73
PN:394476-2	MOS/MSC	26-Jan-05	O/C	TSN 0					
SN:1181	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
732120 ^S	NO. 1 ENGINE - INSPECT MOTIVE FLOW FUEL PUMP DRIVE SPLINE							Service	ATA:73
	MOS	21-Aug-25							
	HRS	9510	600 (+50/-100)						
	ENC	7585							
PROC. REF: LMM 72-00-00, LMM 73-21-04PROC. REF: LMM 72-00-00, LMM 73-21-04									
PKG:0									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 73 - ENGINE FUEL AND CONTROL

732120	^S	NO. 2 ENGINE - INSPECT MOTIVE FLOW FUEL PUMP DRIVE SPLINE						Service	ATA:73
	MOS	25-Aug-25							
	HRS	9510	600	(+50/-100)					
	ENC	7585							
PROC. REF: LMM 72-00-00, LMM 73-21-04PROC. REF: LMM 72-00-00, LMM 73-21-04									

PKG:0

733013		DUAL FUEL FLOW (DFFC) CONVERTER						Component	ATA:73
PN:6673308500-003	MOS/MSC	13-Dec-09	O/C						
SN:V01030738BA	HRS	3104.17							
	AFL	2569							
PROC. REF: AMM 73-31-02PROC. REF: AMM 73-31-02									

734012		RIGHT FUEL TEMPERATURE BULB						Component	ATA:73
PN:MS28034-3	MOS/MSC	01-Dec-06	O/C						
SN:133624	HRS	1017.73							
	AFL	815							
PROC. REF: AMM 73-31-03PROC. REF: AMM 73-31-03									

ATA 74 - IGNITION

740130		NO. 1 ENGINE - 5 O'CLOCK IGNITER (#1 POSITION) PLUG						Component	ATA:74
PN:3074541-4	MOS/MSC	21-Aug-25	O/C	TSN 0					
SN:N/A	HRS	9510		TSN 0					
	ENC	7585		TSN 0					
PROC. REF: LMM 74-00-01, LMM 74-00-01PROC. REF: LMM 74-00-01, LMM 74-00-01									

740140	^S	NO. 1 ENGINE - REMOVE AND INSPECT 5 O'CLOCK IGNITER PLUG AND LEAD						Service	ATA:74
	MOS	21-Aug-25							
	HRS	9510	1600	(+50/-100)					
	ENC	7585							
PKG:0									

740140	^S	NO. 2 ENGINE - REMOVE AND INSPECT 5 O'CLOCK IGNITER PLUG AND LEAD						Service	ATA:74
	MOS	25-Aug-25							
	HRS	9510	1600	(+50/-100)					
	ENC	7585							

PKG:0

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 74 - IGNITION

740150	NO. 1 ENGINE - 7 O'CLOCK IGNITER (#2 POSITION) PLUG							Component	ATA:74
PN:3074541-4	MOS/MSC	21-Aug-25	O/C	TSN 0					
SN:N/A	HRS	9510		TSN 0					
	ENC	7585		TSN 0					
PROC. REF: LMM 74-00-01, LMM 74-00-01PROC. REF: LMM 74-00-01, LMM 74-00-01									

740160 ^S	NO. 1 ENGINE - REMOVE AND INSPECT 7 O'CLOCK IGNITER PLUG AND LEAD							Service	ATA:74
	MOS	21-Aug-25							
	HRS	9510	1600 (+50/-100)						
	ENC	7585							
									PKG:0
PROC. REF: LMM 74-00-01PROC. REF: LMM 74-00-01									

740160 ^S	NO. 2 ENGINE - REMOVE AND INSPECT 7 O'CLOCK IGNITER PLUG AND LEAD							Service	ATA:74
	MOS	25-Aug-25							
	HRS	9510	1600 (+50/-100)						
	ENC	7585							
									PKG:0
PROC. REF: LMM 74-00-01PROC. REF: LMM 74-00-01									

ATA 76 - ENGINE CONTROLS

761210	THROTTLE CONTROL MODULE							Component	ATA:76
PN:69011-17	MOS/MSC	24-Sep-21	O/C						
SN:607	HRS	8457.7							
	AFL	6804							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

761320	NO. 1 ENGINE - SOLENOID CONTROLLER VALVE							Component	ATA:76
PN:10696-6-1	MOS/MSC	25-Jan-05	O/C	TSN 0					
SN:11660	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 76-10-01, LMM 76-10-01, LMM 76-10-01, LMM 76-10-01PROC. REF: LMM 76-10-01, LMM 76-10-01, LMM 76-10-01, LMM 76-10-01									

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 76 - ENGINE CONTROLS									
761320	NO. 2 ENGINE - SOLENOID CONTROLLER VALVE							Component	ATA:76
PN:10969-6-1	MOS/MSC	26-Jan-05	O/C	TSN 0					
SN:11657	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 76-10-01, LMM 76-10-01, LMM 76-10-01, LMM 76-10-01PROC. REF: LMM 76-10-01, LMM 76-10-01, LMM 76-10-01, LMM 76-10-01									
761330	NO. 1 ENGINE - ENGINE (DEEC) COMPUTER							Component	ATA:76
PN:2118882-1008	MOS/MSC	25-Jan-05	O/C	TSN 0					
SN:124-AW0049	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 76-10-02, LMM 76-10-02, LMM 76-10-02, LMM 76-10-02PROC. REF: LMM 76-10-02, LMM 76-10-02, LMM 76-10-02, LMM 76-10-02									
761330	NO. 2 ENGINE - ENGINE (DEEC) COMPUTER							Component	ATA:76
PN:2118882-1008	MOS/MSC	26-Jan-05	O/C	TSN 0					
SN:124-AW0054	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 76-10-02, LMM 76-10-02, LMM 76-10-02, LMM 76-10-02PROC. REF: LMM 76-10-02, LMM 76-10-02, LMM 76-10-02, LMM 76-10-02									
761330A	NO. 1 ENGINE - DOWNLOAD ENGINE (DEEC) COMPUTER ECTM							Service	ATA:76
PN:2118882-1008	MOS/MSC	03-Oct-19	A/R						
SN:124-AW0049	HRS	7680.1							
	ENC	6230							
PROC. REF: MSC CAMP EHM ADENDUMPROC. REF: MSC CAMP EHM ADENDUM									
761330A	NO. 2 ENGINE - DOWNLOAD ENGINE (DEEC) COMPUTER ECTM							Service	ATA:76
PN:2118882-1008	MOS/MSC	03-Oct-19	A/R						
SN:124-AW0054	HRS	7680.1							
	ENC	6230							
PROC. REF: MSC CAMP EHM ADENDUMPROC. REF: MSC CAMP EHM ADENDUM									
Y7600000 ^S	ENGINE DEEC WIRE HARNESS SHIELD OVERBRAIDS AND SHIELD TERMINATIONS - PERFORM VISUAL INSPECTION.							Service	ATA:76
	MOS	13-Mar-26	48 (+14d/-14d)						
	HRS	9596.2	1200 (+25/-25)						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
---------	------	-------	----------	------------	----------------------------	-----------	-----------	-------------	----------

ATA 76 - ENGINE CONTROLS

Y7600001	^S	THRUST LEVER CONTROL MODULE - PERFORM FUNCTIONAL TEST						Service	ATA:76
	MOS	13-Mar-26	48 (+14d/-14d)						
	HRS	9596.2	1200 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 76-10-02PROC. REF: AMM 76-10-02									

PKG:13

Y7610007	^S	ENGINE CONTROL CABLES - PERFORM VISUAL INSPECTION OF FORWARD AND AFT CABLE CONNECTION.						Service	ATA:76
	MOS	13-Mar-26	48 (+14d/-14d)						
	HRS	9596.2	1200 (+25/-25)						
	AFL	7624							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

PKG:14

ATA 77 - ENGINE INDICATING

772210	NO. 1 ENGINE - ITT HARNESS ASSEMBLY							Component	ATA:77
PN:3060763-1	MOS/MSC	21-Aug-25	O/C	TSO 0					
SN:2516901702500	HRS	9510		TSO 0					
	ENC	7585		TSO 0					
PROC. REF: LMM 77-20-01, LMM 77-20-01, LMM 77-20-01, LMM 77-20-01PROC. REF: LMM 77-20-01, LMM 77-20-01, LMM 77-20-01, LMM 77-20-01									

774001	ENGINE VIBRATION MONITOR BOX							Component	ATA:77
PN:241-241-000-501	MOS/MSC	25-Jan-15	O/C						
SN:0173	HRS	6669.27							
	AFL	5419							
PROC. REF: AMM 77-41-01PROC. REF: AMM 77-41-01									

Y7741000	^S	ENGINE VIBRATION MONITORING SYSTEM - PERFORM FUNCTIONAL TEST.						Service	ATA:77
	MOS	13-Mar-26	96 (+14d/-14d)						
	HRS	9596.2	2400 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 77-41-00PROC. REF: AMM 77-41-00									

PKG:21

ATA 78 - EXHAUST

783001	LEFT LOWER THRUST REVERSER							Component	ATA:78
PN:PN	MOS/MSC	10-May-05	O/C	TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 78 - EXHAUST									
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 78-31-00PROC. REF: AMM 78-31-00									
783001	LEFT UPPER THRUST REVERSER								Component ATA:78
PN:LJ7830101-5	MOS/MSC	10-May-05	O/C	TSN 0					
SN:A30040305	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 78-31-00PROC. REF: AMM 78-31-00									
783002	RIGHT LOWER THRUST REVERSER								Component ATA:78
PN:PN	MOS/MSC	10-May-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 78-31-00PROC. REF: AMM 78-31-00									
783002	RIGHT UPPER THRUST REVERSER								Component ATA:78
PN:LJ7830101-6	MOS/MSC	10-May-23	O/C						
SN:A30040305	HRS	9071.3							
	AFL	7252							
PROC. REF: AMM 78-31-00PROC. REF: AMM 78-31-00									
783031	NO. 1 ASSEMBLY, THRUST REVERSER CONTROL BOX								Component ATA:78
PN:LJ7836704-17	MOS/MSC	26-Jul-24	O/C						
SN:OBTE30584	HRS	9450.9							
	AFL	7531							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
783032	NO. 2 ASSEMBLY, THRUST REVERSER CONTROL BOX								Component ATA:78
PN:6678300000-003	MOS/MSC	28-Mar-11	O/C						
SN:OBTE30547	HRS	4114.93							
	AFL	3365							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 78 - EXHAUST									
783101	LEFT THRUST REVERSER ISOLATION VALVE							Component	ATA:78
PN:LJ7835200-5	MOS/MSC	25-Jan-22	O/C	TSO 0					
SN:0590	HRS	8706.9		TSO 0					
	AFL	6996		TSO 0					
PROC. REF: AMM 78-30-02PROC. REF: AMM 78-30-02									
783102	RIGHT THRUST REVERSER ISOLATION VALVE							Component	ATA:78
PN:71556-8	MOS/MSC	15-Dec-09	O/C						
SN:0814	HRS	3106.15							
	AFL	2571							
PROC. REF: AMM 78-30-02PROC. REF: AMM 78-30-02									
D7830078 ^S	** THRUST REVERSER SYSTEM THROTTLE RETARD ACTUATOR - PERFORM OPERATIONAL CHECK (AWL**)							Service	ATA:78
	MOS	13-Mar-26	96 (+14d/-14d)					AIRWORTHINESS	
	HRS	9596.2	2400 (+25/-25)						
	AFL	7624							
PROC. REF: AMM 78-32-40PROC. REF: AMM 78-32-40									
H7830081 ^S	THRUST REVERSERS - REMOVE LINK ROD ASSEMBLIES AND PERFORM MAGNETIC PARTICLE INSPECTION							Service	ATA:78
	MOS	13-Mar-26	96 (+14d/-14d)						
	HRS	9596.2	2400 (+25/-25)						
	AFL	7624							
PROC. REF: NDT PART 7/78-30-01PROC. REF: NDT PART 7/78-30-01									
H7830082 ^S	THRUST REVERSERS - REMOVE THRUST REVERSER DOOR ASSEMBLIES AND PERFORM EDDY CURRENT INSPECTIONOF PIVOT FITTING AND DOOR HINGES							Service	ATA:78
	MOS	13-Mar-26	96 (+14d/-14d)						
	HRS	9596.2	2400 (+25/-25)						
	AFL	7624							
PROC. REF: NDT PART 6/78-30-02, NDT PART 6/78-30-03PROC. REF: NDT PART 6/78-30-02, NDT PART 6/78-30-03									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR
Serial: 45-2027
RegNo: N116PJ
HRS: 9841.3
AFL: 7790
As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 78 - EXHAUST										
Y7830000 ^S		EXHAUST NOZZLE - PERFORM VISUAL INSPECTION.							Service	ATA:78
	MOS	13-Mar-26	96 (+14d/-14d)							
	HRS	9596.2	2400 (+25/-25)							
	AFL	7624								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
PKG:21										
Y7830001 ^S		THRUST REVERSER INNER FAN DUCT ASSEMBLY -PERFORM VISUAL INSPECTION. INSPECT FROM EXHAUST END ONLY.							Service	ATA:78
	MOS	13-Mar-26	48 (+14d/-14d)							
	HRS	9596.2	1200 (+25/-25)							
	AFL	7624								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
PKG:15										
Y7830002 ^S		THRUST REVERSER DOOR AND HINGE FITTINGS - PERFORM VISUAL INSPECTION.							Service	ATA:78
	MOS	13-Mar-26	48 (+14d/-14d)							
	HRS	9596.2	1200 (+25/-25)							
	AFL	7624								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
PKG:15										
Y7830003 ^S		THRUST REVERSER PRIMARY ACTUATOR AND LATCH ASSEMBLY - PERFORM VISUAL INSPECTION.							Service	ATA:78
	MOS	13-Mar-26	48 (+14d/-14d)							
	HRS	9596.2	1200 (+25/-25)							
	AFL	7624								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
PKG:15										
Y7830004 ^S		THRUST REVERSER HYDRAULIC CONTROL VALVE (HCV), THROTTLE RETARD ACTUATOR, AND ASSOCIATEDPLUMBING - PERFORM VISUAL INSPECTION.							Service	ATA:78
	MOS	13-Mar-26	48 (+14d/-14d)							
	HRS	9596.2	1200 (+25/-25)							
	AFL	7624								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
PKG:15										

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C / W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026 15-Sep-2026 01:15 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 78 - EXHAUST										
Y7830005 ^S		THRUST REVERSER DOOR SEALS AND RETAINERS - PERFORM VISUAL INSPECTION.							Service	ATA:78
	MOS	13-Mar-26	48 (+14d/-14d)							
	HRS	9596.2	1200 (+25/-25)							
	AFL	7624								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
PKG:15										
Y7830006 ^S		THRUST REVERSER WIRE HARNESS - PERFORM VISUAL INSPECTION.							Service	ATA:78
	MOS	13-Mar-26	48 (+14d/-14d)							
	HRS	9596.2	1200 (+25/-25)							
	AFL	7624								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
PKG:15										
ATA 79 - OIL										
790110		NO. 1 ENGINE - OIL PUMP							Component	ATA:79
PN:3060785-3	MOS/MSC	25-Jan-05	O/C	TSN 0						
SN:061405700706	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: LMM 79-20-03, LMM 79-20-03PROC. REF: LMM 79-20-03, LMM 79-20-03										
790110		NO. 2 ENGINE - OIL PUMP							Component	ATA:79
PN:3060785-3	MOS/MSC	26-Jan-05	O/C	TSN 0						
SN:081405700019	HRS	0	TSN 0							
	ENC	0	TSN 0							
PROC. REF: LMM 79-20-03, LMM 79-20-03PROC. REF: LMM 79-20-03, LMM 79-20-03										
790130		NO. 1 ENGINE - ANALYSIS OIL AND FILTER (SOAP)							Service	ATA:79
	MOS	17-Aug-26								
	HRS	9734.6	150 (+100)		(9884.6) 9968.6	9984.6	127.3 (+100)			
	ENC	7734								
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00										
PKG:0										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 40XR
Serial: 45-2027
RegNo: N116PJ
HRS: 9841.3
AFL: 7790
As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 79 - OIL									
790130		NO. 2 ENGINE - ANALYSIS OIL AND FILTER (SOAP)							Service ATA:79
	MOS	17-Aug-26							
	HRS	9734.6	150 (+100)		(9884.6) 9968.6	9984.6	127.3 (+100)		
	ENC	7734							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									PKG:0
790140 ^S		NO. 1 ENGINE - PERFORM OIL CHANGE							Service ATA:79
	MOS	21-Aug-25							
	HRS	9510	1200 (+100/-200)						
	ENC	7585							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									PKG:0
790140 ^S		NO. 2 ENGINE - PERFORM OIL CHANGE							Service ATA:79
	MOS	25-Aug-25							
	HRS	9510	1200 (+100/-200)						
	ENC	7585							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									PKG:0
790150 ^S		NO. 1 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION AND PERFORM RESISTANCE CHECK							Service ATA:79
	MOS	21-Aug-25							
	HRS	9510	600 (+50/-100)						
	ENC	7585							
PROC. REF: LMM 79-10-01PROC. REF: LMM 79-10-01									PKG:0
790150 ^S		NO. 2 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION AND PERFORM RESISTANCE CHECK							Service ATA:79
	MOS	25-Aug-25							
	HRS	9510	600 (+50/-100)						
	ENC	7585							
PROC. REF: LMM 79-10-01PROC. REF: LMM 79-10-01									PKG:0

? - Insufficient Information
S - Suppressed Requirement
* - Estimated Due(New Requirement)
(EFF) - Effective C / W
(M) - Manual Due
U - User Task
Ex - Excluded Task

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 79 - OIL									
790160 ^S		NO. 1 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION						Service	ATA:79
	MOS	17-Aug-26							
	HRS	9734.6	150 (+100)						
	ENC	7734							
PROC. REF: LMM 79-10-01PROC. REF: LMM 79-10-01									PKG:0
790160 ^S		NO. 2 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION						Service	ATA:79
	MOS	17-Aug-26							
	HRS	9734.6	150 (+100)						
	ENC	7734							
PROC. REF: LMM 79-10-01PROC. REF: LMM 79-10-01									PKG:0
792008		NO. 1 ENGINE - OIL FLOW REDUCTION VALVE						Component	ATA:79
PN:3060769-1	MOS/MSC	25-Jan-05	O/C	TSN 0					
SN:040645103627	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 79-20-08, LMM 79-20-08PROC. REF: LMM 79-20-08, LMM 79-20-08									
792008		NO. 2 ENGINE - OIL FLOW REDUCTION VALVE						Component	ATA:79
PN:3060769-1	MOS/MSC	26-Jan-05	O/C	TSN 0					
SN:040645103617	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 79-20-08, LMM 79-20-08PROC. REF: LMM 79-20-08, LMM 79-20-08									
792260		NO. 1 ENGINE - OIL TEMPERATURE CONTROL VALVE						Component	ATA:79
PN:158465-6	MOS/MSC	25-Jan-05	O/C	TSN 0					
SN:11615	HRS	0		TSN 0					
	ENC	0		TSN 0					
792260		NO. 2 ENGINE - OIL TEMPERATURE CONTROL VALVE						Component	ATA:79
PN:158465-6	MOS/MSC	26-Jan-05	O/C	TSN 0					
SN:11614	HRS	0		TSN 0					
	ENC	0		TSN 0					

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C / W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 40XR Serial: 45-2027 RegNo: N116PJ HRS: 9841.3 AFL: 7790 As Of: 14-Sep-2026

15-Sep-2026 01:15 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 79 - OIL									
793064	NO. 1 ENGINE - TEMP BULB								Component ATA:79
PN:MS28034-3	MOS/MSC	25-Jan-05	O/C	TSN 0					
SN:H8987	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
793064	NO. 2 ENGINE - TEMP BULB								Component ATA:79
PN:MS28034-3	MOS/MSC	26-Jan-05	O/C	TSN 0					
SN:J5959	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
793315 ^S	NO. 1 ENGINE - CHECK OIL FILTER BYPASS VALVE CIRCUIT/THERMAL LOCKOUT SWITCH								Service ATA:79
	MOS	21-Aug-25							
	HRS	9510	1200 (+100/-200)						
	ENC	7585							
PKG:0									
793315 ^S	NO. 2 ENGINE - CHECK OIL FILTER BYPASS VALVE CIRCUIT/THERMAL LOCKOUT SWITCH								Service ATA:79
	MOS	25-Aug-25							
	HRS	9510	1200 (+100/-200)						
	ENC	7585							
PKG:0									
793320	NO. 1 ENGINE - FUEL HEATER / OIL COOLER ASSEMBLY								Component ATA:79
PN:3060709-4	MOS/MSC	25-Jan-05	O/C	TSN 0					
SN:1897	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 79-20-07, LMM 79-20-07PROC. REF: LMM 79-20-07, LMM 79-20-07									
793320	NO. 2 ENGINE - FUEL HEATER / OIL COOLER ASSEMBLY								Component ATA:79
PN:3060709-4	MOS/MSC	26-Jan-05	O/C	TSN 0					
SN:1895	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 79-20-07, LMM 79-20-07PROC. REF: LMM 79-20-07, LMM 79-20-07									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task