

OWNER: PRIVATE JETS INC.		OPERATOR: PRIVATE JETS INC.		
ADDRESS: 7220 NW 63TH ST BETHANY OK 73008		ADDRESS: 7220 NW 63TH ST BETHANY OK 73008		
OFFICE:		OFFICE:		
FAX:		FAX:		
ANALYST: SEAN WELLS		+1-316-928-7895 (DIRECT)	800-787-9749 (EFAX-CARDS)	PLEASE REACH OUT TO YOUR ANALYST TO RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY).
EMAIL: SWELLS@CAMPSYSTEMS.COM		+1-631-588-3200 (MAIN)	631-980-4222 (EFAX-CARDS)	
		WWW.CAMPSYSTEMS.COM		

AIRCRAFT	SERIAL/REGNO: 45-145/N942FK	MODEL: LEARJET 45XR	MANUFACTURER: BOMBARDIER AVIATION
CERTIFICATION DATE: 09-MAR-2001		LAST ACTUALS:	
		10101.4 A/C HRS	as of 14-SEP-2026
		7674 AFL	as of 14-SEP-2026
		2695.6 ACH	as of 29-JUL-2026

ENGINE NO. 1	SERIAL/PART: P-116284C/3060082-2	MODEL: TFE731-20BR-1B	MANUFACTURER: HONEYWELL
INSTALLED ON: 25-JUN-2026		LAST ACTUALS:	
0	ENG. HRS 10023.1 A/C HRS	10073.1 ENG. HRS	as of 14-SEP-2026
	ENC	7660 ENC	as of 14-SEP-2026

ENGINE NO. 2	SERIAL/PART: P-116285C/3060084-2	MODEL: TFE731-20BR-1B	MANUFACTURER: HONEYWELL
INSTALLED ON: 25-JUN-2026		LAST ACTUALS:	
0	ENG. HRS 10023.1 A/C HRS	9234.4 ENG. HRS	as of 14-SEP-2026
	ENC	7556 ENC	as of 14-SEP-2026

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 00 - INFORMATION									
CI45-150721	REVIEW CONCORDE EMERGENCY BATTERY CMM 5-0167 REV E								Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS	
	HRS								
	AFL								
PROC. REF: RCF CI45PROC. REF: RCF CI45									
CI45-160527	REVIEW LEARJET AMM REVISION 66								Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS	
	HRS								
	AFL								
PROC. REF: RCF CI45PROC. REF: RCF CI45									
CI45-160603	REVIEW LEARJET 45 AMM TR 4-40								Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS	
	HRS								
	AFL								
PROC. REF: RCF CI45PROC. REF: RCF CI45									
CI45-160613	REVIEW LEARJET 45 AMM TR 5-110								Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS	
	HRS								
	AFL								
PROC. REF: RCF CI45PROC. REF: RCF CI45									
CI45-161207B	REVIEW LEARJET 45 AMM REVISION 67								Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS	
	HRS								
	AFL								
PROC. REF: RCF CI45PROC. REF: RCF CI45									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 00 - INFORMATION									
CI45-181109B	REVIEW LEARJET 45/45XR AMM REVISION 71								Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS	
	HRS								
	AFL								
PROC. REF: RCF CI45PROC. REF: RCF CI45									
CI45-190429A	REVIEW LEARJET 45/45XR AMM REV 72								Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS	
	HRS								
	AFL								
PROC. REF: RCF CI45PROC. REF: RCF CI45									
CI45-200529	REVIEW AUDIT SUMMARY CHANGE FORM								Service ATA:00
	MOS/MSC	EFF	-					AUDIT SUMMARY CHANGE FORM	
	HRS								
	AFL								
PROC. REF: RCF CI45PROC. REF: RCF CI45									
CI45-210120	REVIEW LEARJET 45/45XR AUDIT SUMMARY CHANGE FORM								Service ATA:00
	MOS/MSC	30-Mar-21	-					AUDIT SUMMARY CHANGE FORM	
	HRS	8414.4							
	AFL	6463							
PROC. REF: RCF CI45PROC. REF: RCF CI45									
CI45-260206	REVIEW ATTACHED AUDIT SUMMARY CHANGE FORM								Service ATA:00
	MOS/MSC	EFF	-					AUDIT SUMMARY CHANGE FORM	
	HRS								
	AFL								
PROC. REF: RCF CI45PROC. REF: RCF CI45									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 00 - INFORMATION									
EC04-180802	NO. 1 ENGINE - REVIEW TFE731-20/-40/-60 (CIMMS) LMM TR 5-17								Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS	
	HRS								
	ENC								
PROC. REF: RCF EC04-180802PROC. REF: RCF EC04-180802									
EC04-180802	NO. 2 ENGINE - REVIEW TFE731-20/-40/-60 (CIMMS) LMM TR 5-17								Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS	
	HRS								
	ENC								
PROC. REF: RCF EC04-180802PROC. REF: RCF EC04-180802									
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
051101	PHASE A1-300 HOUR CHECKS								Package ATA:05
	MOS	25-Jun-26	12		25-Jun-27		283 d		
	HRS	10023.1	300		10323.1		221.7		
WC#: 05.110	AFL	7616							
PROC. REF: AMM 05-10-00, AMM 05-11-01PROC. REF: AMM 05-10-00, AMM 05-11-01									
051102	PHASE A2-300 HOUR CHECKS								Package ATA:05
	MOS	25-Jun-26	12		25-Jun-27		283 d		
	HRS	10023.1	300		10323.1		221.7		
	AFL	7616							
PROC. REF: AMM 05-10-00, AMM 05-11-02PROC. REF: AMM 05-10-00, AMM 05-11-02									
051103	PHASE A3-300 HOUR CHECKS								Package ATA:05
	MOS	25-Jun-26	12		25-Jun-27		283 d		
	HRS	10023.1	300		10323.1		221.7		
	AFL	7616							
PROC. REF: AMM 05-10-00, AMM 05-11-03PROC. REF: AMM 05-10-00, AMM 05-11-03									

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C / W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
051104	PHASE A4-300 HOUR CHECKS							Package	ATA:05
	MOS	25-Jun-26	12		25-Jun-27		283 d		
	HRS	10023.1	300		10323.1		221.7		
	AFL	7616							
PROC. REF: AMM 05-10-00, AMM 05-11-04PROC. REF: AMM 05-10-00, AMM 05-11-04									PKG:4
051105	PHASE A5-300 HOUR CHECKS							Package	ATA:05
	MOS	25-Jun-26	12		25-Jun-27		283 d		
	HRS	10023.1	300		10323.1		221.7		
	AFL	7616							
PROC. REF: AMM 05-10-00, AMM 05-11-05PROC. REF: AMM 05-10-00, AMM 05-11-05									PKG:5
051106	PHASE A6-300 HOUR CHECKS							Package	ATA:05
	MOS	25-Jun-26	12		25-Jun-27		283 d		
	HRS	10023.1	300		10323.1		221.7		
	AFL	7616							
PROC. REF: AMM 05-10-00, AMM 05-11-06PROC. REF: AMM 05-10-00, AMM 05-11-06									PKG:6
051201	PHASE B1 600 HOUR CHECKS							Package	ATA:05
	MOS	25-Jun-26	24		25-Jun-28		649 d		
	HRS	10023.1	600		10623.1		521.7		
	AFL	7616							
PROC. REF: AMM 05-10-00, AMM 05-12-01PROC. REF: AMM 05-10-00, AMM 05-12-01									PKG:7
051202	PHASE B2 600 HOUR CHECKS							Package	ATA:05
	MOS	25-Jun-26	24		25-Jun-28		649 d		
	HRS	10023.1	600		10623.1		521.7		
	AFL	7616							
PROC. REF: AMM 05-10-00, AMM 05-12-02PROC. REF: AMM 05-10-00, AMM 05-12-02									PKG:8

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS / MAINTENANCE CHECKS									
051203	PHASE B3 600 HOUR CHECKS							Package	ATA:05
	MOS	25-Jun-26	24		25-Jun-28		649 d		
	HRS	10023.1	600		10623.1		521.7		
	AFL	7616							
PROC. REF: AMM 05-10-00, AMM 05-12-03PROC. REF: AMM 05-10-00, AMM 05-12-03									PKG:9
051204	PHASE B4 600 HOUR CHECKS							Package	ATA:05
	MOS	25-Jun-26	24		25-Jun-28		649 d		
	HRS	10023.1	600		10623.1		521.7		
	AFL	7616							
PROC. REF: AMM 05-10-00, AMM 05-12-04PROC. REF: AMM 05-10-00, AMM 05-12-04									PKG:10
051205	PHASE B5 600 HOUR CHECKS							Package	ATA:05
	MOS	25-Jun-26	24		25-Jun-28		649 d		
	HRS	10023.1	600		10623.1		521.7		
	AFL	7616							
PROC. REF: AMM 05-10-00, AMM 05-12-05PROC. REF: AMM 05-10-00, AMM 05-12-05									PKG:11
051206	PHASE B6 600 HOUR CHECKS							Package	ATA:05
	MOS	25-Jun-26	24		25-Jun-28		649 d		
	HRS	10023.1	600		10623.1		521.7		
	AFL	7616							
PROC. REF: AMM 05-10-00, AMM 05-12-06PROC. REF: AMM 05-10-00, AMM 05-12-06									PKG:12
051301	PHASE C1 1200 HOUR CHECKS							Package	ATA:05
	MOS	22-Jun-23	48		22-Jun-27		280 d		
	HRS	9258.5	1200		10458.5		357.1		
	AFL	7100							
PROC. REF: AMM 05-10-00, AMM 05-13-01PROC. REF: AMM 05-10-00, AMM 05-13-01									PKG:13

?-Insufficient Information

S-Suppressed Requirement

*-Estimated Due(New Requirement)

(EFF)-Effective C / W

(M)-Manual Due

U-User Task

Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
051302	PHASE C2 1200 HOUR CHECKS							Package	ATA:05
	MOS	22-Jun-23	48		22-Jun-27		280 d		
	HRS	9258.5	1200		10458.5		357.1		
	AFL	7100							
PROC. REF: AMM 05-10-00, AMM 05-13-02PROC. REF: AMM 05-10-00, AMM 05-13-02									PKG:14
051303	PHASE C3 1200 HOUR CHECKS							Package	ATA:05
	MOS	22-Jun-23	48		22-Jun-27		280 d		
	HRS	9258.5	1200		10458.5		357.1		
	AFL	7100							
PROC. REF: AMM 05-10-00, AMM 05-13-03PROC. REF: AMM 05-10-00, AMM 05-13-03									PKG:15
051304	PHASE C4 1200 HOUR CHECKS							Package	ATA:05
	MOS	22-Jun-23	48		22-Jun-27		280 d		
	HRS	9258.5	1200		10458.5		357.1		
	AFL	7100							
PROC. REF: AMM 05-10-00, AMM 05-13-04PROC. REF: AMM 05-10-00, AMM 05-13-04									PKG:16
051305	PHASE C5 1200 HOUR CHECKS							Package	ATA:05
	MOS	22-Jun-23	48		22-Jun-27		280 d		
	HRS	9258.5	1200		10458.5		357.1		
	AFL	7100							
PROC. REF: AMM 05-10-00, AMM 05-13-05PROC. REF: AMM 05-10-00, AMM 05-13-05									PKG:17
051306	PHASE C6 1200 HOUR CHECKS							Package	ATA:05
	MOS	22-Jun-23	48		22-Jun-27		280 d		
	HRS	9258.5	1200		10458.5		357.1		
	AFL	7100							
PROC. REF: AMM 05-10-00, AMM 05-13-06PROC. REF: AMM 05-10-00, AMM 05-13-06									PKG:18

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS / MAINTENANCE CHECKS									
051401	PHASE D1 2400 HOUR CHECKS								Package ATA:05
	MOS	25-Jun-26	96		25-Jun-34		2840 d		
	HRS	10023.1	2400		12423.1		2321.7		
	AFL	7616							
PROC. REF: AMM 05-10-00, AMM 05-14-01PROC. REF: AMM 05-10-00, AMM 05-14-01									PKG:19
051402	PHASE D2 2400 HOUR CHECKS								Package ATA:05
	MOS	25-Jun-26	96		25-Jun-34		2840 d		
	HRS	10023.1	2400		12423.1		2321.7		
	AFL	7616							
PROC. REF: AMM 05-10-00, AMM 05-14-02PROC. REF: AMM 05-10-00, AMM 05-14-02									PKG:20
051403	PHASE D3 2400 HOUR CHECKS								Package ATA:05
	MOS	25-Jun-26	96		25-Jun-34		2840 d		
	HRS	10023.1	2400		12423.1		2321.7		
	AFL	7616							
PROC. REF: AMM 05-10-00, AMM 05-14-03PROC. REF: AMM 05-10-00, AMM 05-14-03									PKG:21
051404	PHASE D4 2400 HOUR CHECKS								Package ATA:05
	MOS	25-Jun-26	96		25-Jun-34		2840 d		
	HRS	10023.1	2400		12423.1		2321.7		
	AFL	7616							
PROC. REF: AMM 05-10-00, AMM 05-14-04PROC. REF: AMM 05-10-00, AMM 05-14-04									PKG:22
051405	PHASE D5 2400 HOUR CHECKS								Package ATA:05
	MOS	25-Jun-26	96		25-Jun-34		2840 d		
	HRS	10023.1	2400		12423.1		2321.7		
	AFL	7616							
PROC. REF: AMM 05-10-00, AMM 05-14-05PROC. REF: AMM 05-10-00, AMM 05-14-05									PKG:23

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS / MAINTENANCE CHECKS									
051406	PHASE D6 2400 HOUR CHECKS							Package	ATA:05
	MOS	25-Jun-26	96		25-Jun-34		2840 d		
	HRS	10023.1	2400		12423.1		2321.7		
	AFL	7616							
PROC. REF: AMM 05-10-00, AMM 05-14-06PROC. REF: AMM 05-10-00, AMM 05-14-06									PKG:24
051500	4800 HOUR CHECKS							Package	ATA:05
	MOS	22-Jun-23							
	HRS	9258.5	4800		14058.5		3957.1		
	AFL	7100							
PROC. REF: AMM 05-15-00, AMM 05-10-00PROC. REF: AMM 05-15-00, AMM 05-10-00									PKG:25
051600	9600 HOUR CHECKS							Package	ATA:05
	MOS	02-Aug-24							
	HRS	9525.7	9600		19125.7		9024.3		
	AFL	7276							
PROC. REF: AMM 05-16-00, AMM 05-10-00PROC. REF: AMM 05-16-00, AMM 05-10-00									PKG:26
051700	MAJOR LANDING GEAR INSPECTION							Package	ATA:05
	MOS	09-Mar-01							
	HRS	0							
	AFL	0	10000		10000		2326		
PROC. REF: AMM 05-17-00, AMM 05-10-00PROC. REF: AMM 05-17-00, AMM 05-10-00									PKG:27
057110	NO. 1 ENGINE - 150 TO 250 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							Package	ATA:05
	MOS	25-Jun-26							
	HRS	9994.8	250		(10244.8) 10273.1		171.7		
	ENC	7602							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
057110	NO. 2 ENGINE - 150 TO 250 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS								Package ATA:05
	MOS	25-Jun-26							
	HRS	9156.1	250		(9406.1) 10273.1		171.7		
	ENC	7498							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									
057120	NO. 1 ENGINE - 300 TO 440 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS								Package ATA:05
	MOS/MSC	22-Jun-23	N/A						
	HRS	9184.4							
	ENC	7042							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									
057120	NO. 2 ENGINE - 300 TO 440 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS								Package ATA:05
	MOS/MSC	18-Aug-22	N/A						
	HRS	8169.8							
	ENC	6832							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									
057130	NO. 1 ENGINE - 500 TO 650 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS								Package ATA:05
	MOS	21-Aug-25							
	HRS	9735.7	600		(10335.7) 10364		262.6		
	ENC	7413							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									
057130	NO. 2 ENGINE - 500 TO 650 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS								Package ATA:05
	MOS	21-Aug-25							
	HRS	8897	600		(9497) 10364		262.6		
	ENC	7309							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
057140	NO. 1 ENGINE - 500 TO 850 HOUR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS								Package ATA:05
	MOS	21-Aug-25							
	HRS	9735.7	800		(10535.7) 10564		462.6		
	ENC	7413							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									
057140	NO. 2 ENGINE - 500 TO 850 HOUR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS								Package ATA:05
	MOS	21-Aug-25							
	HRS	8897	800		(9697) 10564		462.6		
	ENC	7309							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									
057150	NO. 1 ENGINE - 1000 TO 1300 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS								Package ATA:05
	MOS	27-Oct-25							
	HRS	9832.1	1200		(11032.1) 11060.4		959		
	ENC	7480							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									
057150	NO. 2 ENGINE - 1000 TO 1300 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS								Package ATA:05
	MOS	27-Oct-25							
	HRS	8993.4	1200		(10193.4) 11060.4		959		
	ENC	7376							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									
057160	NO. 1 ENGINE - 1500 TO 1650 HOUR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS								Package ATA:05
	MOS	22-Jun-23							
	HRS	9184.4	1600		(10784.4) 10812.7		711.3		
	ENC	7042							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
057160	NO. 2 ENGINE - 1500 TO 1650 HOUR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							Package	ATA:05
	MOS	18-Aug-22							
	HRS	8169.8	1600		(9769.8) 10636.8		535.4		
	ENC	6832							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									
5-50-00-02	PERFORM UNSCHEDULED MAINTENANCE CHECK - OVERWEIGHT LANDING (WEIGHT IN EXCESS OF MAXIMUM LANDING WEIGHT)							Service	ATA:05
	MOS/MSC		A/R						
	HRS								
	AFL								
PROC. REF: AMM 05-50-00PROC. REF: AMM 05-50-00									
5-50-00-03	PERFORM UNSCHEDULED MAINTENANCE CHECK - HARD LANDING							Service	ATA:05
	MOS/MSC		A/R						
	HRS								
	AFL								
PROC. REF: AMM 05-50-00PROC. REF: AMM 05-50-00									
5-50-00-09	PERFORM UNSCHEDULED MAINTENANCE CHECK - LIGHTNING STRIKE INSPECTION							Service	ATA:05
	MOS/MSC	09-Mar-01	A/R						
	HRS	0							
	AFL	0							
PROC. REF: AMM 05-50-00PROC. REF: AMM 05-50-00									
5-50-00-18	PERFORM UNSCHEDULED MAINTENANCE CHECK - FOREIGN OBJECT DAMAGE							Service	ATA:05
	MOS/MSC		O/C						
	HRS								
	AFL								
PROC. REF: AMM 05-50-00PROC. REF: AMM 05-50-00									
5-50-00-18.1	PERFORM UNSCHEDULED MAINTENANCE CHECK - FOREIGN OBJECT DAMAGE (BIRD STRIKE)							Service	ATA:05
	MOS/MSC		A/R						
	HRS								
	AFL								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
5-50-00-19	PERFORM UNSCHEDULED MAINTENANCE CHECK - ENGINE VIBRATION INDICATION							Service	ATA:05
	MOS/MSC		A/R						
	HRS								
	AFL								
PROC. REF: AMM 05-50-00PROC. REF: AMM 05-50-00									
ATA 08 - LEVELING AND WEIGHING									
082000	WEIGH AIRCRAFT							Service	ATA:08
	MOS	16-Jun-26	36		16-Jun-29		1005 d		
	HRS	10023.1							
	AFL	7616							
PROC. REF: AMM 08-10-00, FAR FAR 135.185PROC. REF: AMM 08-10-00, FAR FAR 135.185									
ATA 11 - PLACARDS AND MARKINGS									
G1130000 ^S	CHECK BRIGHTNESS LEVEL OF ALL SELF-LUMINOUS PLACARDS							Service	ATA:11
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 11-30-00PROC. REF: AMM 11-30-00									
ATA 12 - SERVICING									
AB1210060 ^S	MAIN LANDING GEAR UPLOCK ACTUATOR - LUBRICATE							Service	ATA:12
	MOS	25-Jun-26	12						
	HRS	10023.1	300						
	AFL	7616							
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01									
O1210002 ^S	FLAP ACTUATORS - CHECK OIL LEVEL							Service	ATA:12
	MOS	25-Jun-26	24						
	HRS	10023.1	600						
	AFL	7616							
PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 12 - SERVICING									
Q1221064	LEFT INBOARD FLAP ACTUATOR JOINT - APPLY CORROSION PREVENTIVE COMPOUND (CPC)							Service	ATA:12
	MOS/MSC	05-Dec-19	N/A						
	HRS	8177.8							
	AFL	6304							
PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03									
Q1221064	LEFT OUTBOARD FLAP ACTUATOR JOINT - APPLY CORROSION PREVENTIVE COMPOUND (CPC)							Service	ATA:12
	MOS/MSC	05-Dec-19	N/A						
	HRS	8177.8							
	AFL	6304							
PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03									
Q1221064	RIGHT INBOARD FLAP ACTUATOR JOINT - APPLY CORROSION PREVENTIVE COMPOUND (CPC)							Service	ATA:12
	MOS/MSC	05-Dec-19	N/A						
	HRS	8177.8							
	AFL	6304							
PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03									
Q1221064	RIGHT OUTBOARD FLAP ACTUATOR JOINT - APPLY CORROSION PREVENTIVE COMPOUND (CPC)							Service	ATA:12
	MOS/MSC	05-Dec-19	N/A						
	HRS	8177.8							
	AFL	6304							
PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03									
T1222004	NO. 1 MAIN BATTERY - LEAD-ACID BATTERIES - PERFORM BATTERY CAPACITY CHECK							Service	ATA:12
PN:RG-380E/40L	MOS	24-Aug-26	6	Adj -3d	21-Feb-27		159 d		
SN:41180857	HRS	10074	500		10574		472.6		
	AFL	7658							
PROC. REF: AMM 12-22-00, CMM 24-30-71PROC. REF: AMM 12-22-00, CMM 24-30-71									
T1222004	NO. 2 MAIN BATTERY - LEAD-ACID BATTERIES - PERFORM BATTERY CAPACITY CHECK							Service	ATA:12
PN:RG-380E/40L	MOS	24-Aug-26	6	Adj -3d	21-Feb-27		159 d		
SN:41180858	HRS	10074	500		10574		472.6		
	AFL	7658							
PROC. REF: AMM 12-22-00, CMM 24-30-71PROC. REF: AMM 12-22-00, CMM 24-30-71									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 12 - SERVICING									
U1210004	FLAP FLEXIBLE TRANSMISSION SHAFTS - HAND LUBRICATE							Service	ATA:12
	MOS	12-Aug-15							
	HRS	7535.1	4800		12335.1		2233.7		
	AFL	5764							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
Y1210000 ^S	NOSE LANDING GEAR SHOCK STRUT - CHECK FOR PROPER FLUID LEVEL AND INFLATION PRESSURE							Service	ATA:12
	MOS	25-Jun-26	12						
	HRS	10023.1	300						
	AFL	7616							
PROC. REF: AMM 12-10-02PROC. REF: AMM 12-10-02									
Y1210001 ^S	MAIN LANDING GEAR SHOCK STRUTS - CHECK FOR PROPER FLUID LEVEL AND INFLATION PRESSURE							Service	ATA:12
	MOS	25-Jun-26	12						
	HRS	10023.1	300						
	AFL	7616							
PROC. REF: AMM 12-10-03PROC. REF: AMM 12-10-03									
Y1210003 ^S	FLAP ACTUATOR BALLNUT - LUBRICATE							Service	ATA:12
	MOS	25-Jun-26	12						
	HRS	10023.1	300						
	AFL	7616							
PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03									
Y1210005 ^S	NOSE LANDING GEAR TRUNNION PIN - LUBRICATE							Service	ATA:12
	MOS	25-Jun-26	12						
	HRS	10023.1	300						
	AFL	7616							
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01									

? - Insufficient Information
S - Suppressed Requirement
* - Estimated Due(New Requirement)
(EFF) - Effective C / W
(M) - Manual Due
U - User Task
Ex - Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 12 - SERVICING									
Y1210006 ^S		NOSE LANDING GEAR ACTUATOR ATTACH FITTING - LUBRICATE						Service	ATA:12
	MOS	25-Jun-26	12						
	HRS	10023.1	300						
	AFL	7616							
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01									PKG:5
Y1210007 ^S		NOSE AND MAIN TIRES - CHECK FOR PROPER INFLATION						Service	ATA:12
	MOS	25-Jun-26	12						
	HRS	10023.1	300						
	AFL	7616							
PROC. REF: AMM 12-10-04PROC. REF: AMM 12-10-04									PKG:5
Y1210009 ^S		NOSE GEAR DOOR HINGE - LUBRICATE						Service	ATA:12
	MOS	25-Jun-26	12						
	HRS	10023.1	300						
	AFL	7616							
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02									PKG:1
Y1210011 ^S		MAIN LANDING GEAR ACTUATOR JOINTS - LUBRICATE						Service	ATA:12
	MOS	25-Jun-26	12						
	HRS	10023.1	300						
	AFL	7616							
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01									PKG:5
Y1210012 ^S		MAIN LANDING GEAR AXLE BEAM/PISTON JOINTS - LUBRICATE						Service	ATA:12
	MOS	25-Jun-26	12						
	HRS	10023.1	300						
	AFL	7616							
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01									PKG:5

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 12 - SERVICING									
Y1210013 ^S	MAIN LANDING GEAR TORQUE LINKS - LUBRICATE								Service ATA:12
	MOS	25-Jun-26	12						
	HRS	10023.1	300						
	AFL	7616							
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01									
PKG:5									
Y1210014 ^S	MAIN LANDING GEAR DOOR HINGE - LUBRICATE								Service ATA:12
	MOS	25-Jun-26	12						
	HRS	10023.1	300						
	AFL	7616							
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02									
PKG:5									
Y1210016 ^S	PASSENGER/CREW DOOR HINGE - LUBRICATE								Service ATA:12
	MOS	25-Jun-26	12						
	HRS	10023.1	300						
	AFL	7616							
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02									
PKG:6									
Y1210017 ^S	PASSENGER/CREW DOOR PINS - LUBRICATE								Service ATA:12
	MOS	25-Jun-26	12						
	HRS	10023.1	300						
	AFL	7616							
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02									
PKG:6									
Y1210018 ^S	PASSENGER/CREW DOOR TENSION BOLTS - LUBRICATE								Service ATA:12
	MOS	25-Jun-26	12						
	HRS	10023.1	300						
	AFL	7616							
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02									
PKG:6									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 12 - SERVICING									
Y1210019	^S	EMERGENCY EXIT DOOR LATCHING MECHANISM - LUBRICATE						Service	ATA:12
	MOS	25-Jun-26	12						
	HRS	10023.1	300						
	AFL	7616							
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02									PKG:6
Y1210020	^S	EMERGENCY EXIT DOOR PINS - LUBRICATE						Service	ATA:12
	MOS	25-Jun-26	12						
	HRS	10023.1	300						
	AFL	7616							
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02									PKG:6
Y1210021	^S	BAGGAGE COMPARTMENT DOOR LATCH PINS - LUBRICATE						Service	ATA:12
	MOS	25-Jun-26	12						
	HRS	10023.1	300						
	AFL	7616							
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02									PKG:6
Y1210022	^S	BAGGAGE COMPARTMENT DOOR HINGE - LUBRICATE						Service	ATA:12
	MOS	25-Jun-26	12						
	HRS	10023.1	300						
	AFL	7616							
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02									PKG:6
Y1210023	^S	OXYGEN SYSTEM SERVICING DOOR HINGE - LUBRICATE						Service	ATA:12
	MOS	25-Jun-26	12						
	HRS	10023.1	300						
	AFL	7616							
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02									PKG:1

? - Insufficient Information
S - Suppressed Requirement
* - Estimated Due(New Requirement)
(EFF) - Effective C / W
(M) - Manual Due
U - User Task
Ex - Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 12 - SERVICING									
Y1210024	^S	TOILET SERVICING DOOR HINGE - LUBRICATE						Service	ATA:12
	MOS	25-Jun-26	12						
	HRS	10023.1	300						
	AFL	7616							
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02									PKG:4
Y1210025	^S	PRESSURE REFUELING STATION DOOR HINGE - LUBRICATE						Service	ATA:12
	MOS	25-Jun-26	12						
	HRS	10023.1	300						
	AFL	7616							
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02									PKG:2
Y1210026	^S	FUSELAGE FUEL FILLER DOOR HINGE - LUBRICATE						Service	ATA:12
	MOS	25-Jun-26	12						
	HRS	10023.1	300						
	AFL	7616							
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02									PKG:2
Y1210027	^S	TAILCONE ACCESS DOOR PINS - LUBRICATE						Service	ATA:12
	MOS	25-Jun-26	12						
	HRS	10023.1	300						
	AFL	7616							
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02									PKG:6
Y1210028	^S	TAILCONE ACCESS DOOR HINGE - LUBRICATE						Service	ATA:12
	MOS	25-Jun-26	12						
	HRS	10023.1	300						
	AFL	7616							
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02									PKG:6

? - Insufficient Information
S - Suppressed Requirement
* - Estimated Due(New Requirement)
(EFF) - Effective C / W
(M) - Manual Due
U - User Task
Ex - Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 12 - SERVICING									
Y1210029 ^S		MAIN LANDING GEAR TRUNNION PIN - LUBRICATE						Service	ATA:12
	MOS	25-Jun-26	12						
	HRS	10023.1	300						
	AFL	7616							
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01									PKG:5
Y1221037 ^S		FLAPS - LUBRICATE ROLLING SURFACES OF MAIN AND NOSE ROLLER TRACKS						Service	ATA:12
	MOS	25-Jun-26	12						
	HRS	10023.1	300						
	AFL	7616							
PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03									PKG:4
Y1221042 ^S		HORIZONTAL STABILIZER UPPER AND LOWER TORQUE LINKS - LUBRICATE						Service	ATA:12
	MOS	25-Jun-26	24						
	HRS	10023.1	600						
	AFL	7616							
PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03									PKG:9
Y1227000 ^S		EMERGENCY PARK BRAKE HANDLE SHAFT - LUBRICATE						Service	ATA:12
	MOS	25-Jun-26	12						
	HRS	10023.1	300						
	AFL	7616							
PROC. REF: AMM 12-27-00PROC. REF: AMM 12-27-00									PKG:1
ATA 21 - AIR CONDITIONING									
211001		SERVO AIR PRESSURE REGULATING VALVE						Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-15-01PROC. REF: AMM 36-15-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
211011	LEFT PLENUM CHECK VALVE								Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-20-09PROC. REF: AMM 21-20-09									
211012	RIGHT PLENUM CHECK VALVE								Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-20-09PROC. REF: AMM 21-20-09									
211017	LEFT EMERGENCY PRESSURIZATION ISOLATION CHECK VALVE								Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-20-03PROC. REF: AMM 21-20-03									
211018	RIGHT EMERGENCY PRESSURIZATION ISOLATION CHECK VALVE								Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-20-03PROC. REF: AMM 21-20-03									
212001	COCKPIT AIR CHECK VALVE								Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-20-01PROC. REF: AMM 21-20-01									
212007	AFT BLOWER MOTOR								Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-51-09PROC. REF: AMM 21-51-09									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
212008	FORWARD BLOWER MOTOR							Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
212011	LINEAR ELECTRO-MECHANICAL ACTUATOR							Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
212041	NO. 1 ENGINE OZONE CONVERTER							Component	ATA:21
PN:4520000100-801	MOS/MSC	01-Apr-22	O/C	TSN 0					
SN:2298	HRS	8936.8		TSN 0					
	AFL	6867		TSN 0					
PROC. REF: AMM 21-20-12PROC. REF: AMM 21-20-12									
212042	NO. 2 ENGINE OZONE CONVERTER							Component	ATA:21
PN:4520000100-801	MOS/MSC	01-Apr-22	O/C	TSN 0					
SN:2305	HRS	8936.8		TSN 0					
	AFL	6867		TSN 0					
PROC. REF: AMM 21-20-12PROC. REF: AMM 21-20-12									
212101	NO. 1 THERMAL CONTROL ACTUATOR							Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
212102	NO. 2 THERMAL CONTROL ACTUATOR							Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C / W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
212105	LEFT ENVIRONMENTAL CONTROL SYSTEM TRANSITION DUCT							Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
212106	RIGHT ENVIRONMENTAL CONTROL SYSTEM TRANSITION DUCT							Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
212201	LEFT GASPER AIR CHECK VALVE							Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-20-07PROC. REF: AMM 21-20-07									
212202	RIGHT GASPER AIR CHECK VALVE							Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-20-07PROC. REF: AMM 21-20-07									
212213	LEFT CABIN AIR CHECK VALVE							Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-20-02PROC. REF: AMM 21-20-02									
212214	RIGHT CABIN AIR CHECK VALVE							Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-20-02PROC. REF: AMM 21-20-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
212801	AVIONICS COOLING FAN MOUNT								Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-21-01PROC. REF: AMM 21-21-01									
213000	CABIN PRESSURE CONTROLLER								Component ATA:21
PN:6628408000-023 (10551B08Y09)	MOS/MSC	17-Feb-05	O/C	TSR 0					
SN:0716	HRS	3300.2		TSR 0					
	AFL	2515		TSR 0					
PROC. REF: AMM 21-30-03PROC. REF: AMM 21-30-03									
213001	LEFT EMERGENCY PRESSURE SHUTOFF VALVE								Component ATA:21
PN:3291224-1	MOS/MSC	03-Dec-09	O/C						
SN:133	HRS	6212.8							
	AFL	4758							
PROC. REF: AMM 21-31-01PROC. REF: AMM 21-31-01									
213002	RIGHT EMERGENCY PRESSURE SHUTOFF VALVE								Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-31-01PROC. REF: AMM 21-31-01									
213021	JET PUMP EJECTOR								Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-30-06PROC. REF: AMM 21-30-06									
213031	PRIMARY OUTFLOW VALVE								Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-30-01PROC. REF: AMM 21-30-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
213032	SECONDARY OUTFLOW VALVE							Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-30-02PROC. REF: AMM 21-30-02									
213055	EMERGENCY PRESSURE ANEROID SWITCH							Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
213056	ABSOLUTE PRESSURE SWITCH							Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
213101	TAILCONE CHECK VALVE							Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
213110	CABIN PRESSURIZATION CHECK VALVE							Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-30-07PROC. REF: AMM 21-30-07									
214301	FOOT WARMER THERMOSTAT (S167)							Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-41-02PROC. REF: AMM 21-41-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
215001	WATER SEPARATOR ASSEMBLY							Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-50-03PROC. REF: AMM 21-50-03									
215002	WATER SEPARATOR BYPASS VALVE							Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
215010	AIR CYCLE MACHINE PRECOOLER ASSEMBLY							Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-50-08PROC. REF: AMM 21-50-08									
215013	PACK BI-LEVEL PRESURE REGULATOR SHUTOFF VALVE							Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-50-02PROC. REF: AMM 21-50-02									
215015	AIR CYCLE MACHINE BYPASS CHECK VALVE							Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-50-07PROC. REF: AMM 21-50-07									
215019	CABIN REFRIGERATION CONDENSER							Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-51-04PROC. REF: AMM 21-51-04									

?-Insufficient Information
 S-Suppressed Requirement
 *-Estimated Due(New Requirement)
 (EFF)-Effective C / W
 (M)-Manual Due
 U-User Task
 Ex-Excluded Task

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
215030	ENVIRONMENTAL CONTROL UNIT							Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-50-01PROC. REF: AMM 21-50-01									
215033	AIR CYCLE MACHINE							Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-50-04PROC. REF: AMM 21-50-04									
215036	PRIMARY, SECONDARY HEAT EXCHANGER							Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
215039	AIR CYCLE MACHINE TURBINE							Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-50-04PROC. REF: AMM 21-50-04									
215043	AFT EVAPORATOR							Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-51-09PROC. REF: AMM 21-51-09									
215044	FORWARD EVAPORATOR							Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-51-07PROC. REF: AMM 21-51-07									

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C/W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
215100	AIR CONDITIONING COMPRESSOR							Component	ATA:21
PN:JBS222-1	MOS/MSC	26-Jul-23	O/C	TSO 0					
SN:K18869	HRS	9278		TSO 0					
	AFL	7111		TSO 0					
PROC. REF: AMM 21-51-01PROC. REF: AMM 21-51-01									
215101	AIR CONDITIONING COMPRESSOR DRIVE MOTOR							Component	ATA:21
PN:MB86B-6	MOS/MSC	31-Jul-23	O/C	TSO 0					
SN:234	HRS	9282.8		TSO 0					
	AFL	7113		TSO 0					
PROC. REF: AMM 21-51-02PROC. REF: AMM 21-51-02									
216001	ENVIRONMENTAL CONTROL SYSTEM - INTEGRATED TEMPERATURE CONTROLLER							Component	ATA:21
PN:1151830-3	MOS/MSC	04-Jan-21	O/C						
SN:1151830-00815	HRS	8361.7							
	AFL	6425							
PROC. REF: AMM 21-60-10PROC. REF: AMM 21-60-10									
216014	COCKPIT TEMPERATURE CONTROL VALVE							Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-60-04, AMM 21-60-05PROC. REF: AMM 21-60-04, AMM 21-60-05									
216015	CABIN TEMPERATURE CONTROL VALVE							Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-60-04PROC. REF: AMM 21-60-04									
216025	COCKPIT TEMPERATURE CONTROL SELECTOR							Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-60-01PROC. REF: AMM 21-60-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
216026	CABIN TEMPERATURE CONTROL SELECTOR							Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-60-01PROC. REF: AMM 21-60-01									
216036	COCKPIT DUCT OVERHEAT THERMOSTAT							Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-60-09PROC. REF: AMM 21-60-09									
216037	CABIN DUCT OVERHEAT THERMOSTAT							Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-60-08PROC. REF: AMM 21-60-08									
216040	28VDC CABIN TEMPERATURE SENSOR/FAN ASSEMBLY							Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-60-03PROC. REF: AMM 21-60-03									
216049	CABIN DUCT OVERTEMP LIMITER							Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-60-06PROC. REF: AMM 21-60-06									
216071	LOW LIMIT TEMPERATURE CONTROL VALVE							Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
216074	SERVO AIR PRESSURE REGULATING VALVE							Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-15-01PROC. REF: AMM 36-15-01									
216081	COCKPIT DUCT TEMPERATURE SENSOR							Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-60-07PROC. REF: AMM 21-60-07									
216083	COCKPIT TEMPERATURE SENSOR							Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-60-02PROC. REF: AMM 21-60-02									
216084	CABIN LOW LIMIT TEMPERATURE SENSOR							Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-50-09PROC. REF: AMM 21-50-09									
5-19-00-L2150054	WEAR INSPECTION - AIR CONDITIONING COMPRESSOR DRIVE MOTOR BRUSHES - PERFORM WEAR INSPECTION (RETURN DRIVE MOTOR TO AUTHORIZED SERVICE FACILITY FOR OVERHAUL)							Service	ATA:21
	MOS/MSC	31-Jul-23	N/A					NOT INSTALLED	
	HRS	9282.8							
	AFL	7113							
5-19-00-L2150055	OVERHAUL - AIR CONDITIONING COMPRESSOR MOTOR - PERFORM OVERHAUL (RETURN DRIVE MOTOR TO AUTHORIZED SERVICE FACILITY FOR OVERHAUL)							Service	ATA:21
	MOS/MSC	22-Jun-23	-					NOT INSTALLED	
	HRS	9258.5							
	AFL	7100							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
J2160007	^S	TEMPERATURE CONTROL SYSTEM - INSPECT AND CLEAN CABIN AND COCKPIT TEMPERATURE CONTROL VALVE SERVO AIR FILTERS						Service	ATA:21
	MOS	25-Jun-26	24						
	HRS	10023.1	600						
	AFL	7616							
PROC. REF: AMM 21-60-11PROC. REF: AMM 21-60-11									PKG:8
L2150054		AIR CONDITIONING COMPRESSOR DRIVE MOTOR BRUSHES - PERFORM WEAR INSPECTION						Service	ATA:21
PN:MB86B-6	MOS	31-Jul-23							
SN:234	HRS	9282.8							
	AFL	7113							
	ACH	2596.2	600		3196.2		500.6		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
L2150055		AIR CONDITIONING COMPRESSOR DRIVE MOTOR - PERFORM OVERHAUL						Service	ATA:21
PN:MB86B-6	MOS	31-Jul-23							
SN:234	HRS	9282.8							
	AFL	7113							
	ACH	2596.2	1200		3796.2		1100.6		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
L2150057	^S	** AUXILIARY HEAT SYSTEM - PERFORM AUXILIARY HEATER ELECTRICAL AND TEMPERATURE SWITCH TEST						Service	ATA:21
	MOS	09-Mar-01	48					AIRWORTHINESS	
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 21-51-00PROC. REF: AMM 21-51-00									PKG:14
O2130000	^S	PRIMARY AND SECONDARY OUTFLOW VALVES - PERFORM INSPECTION						Service	ATA:21
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 21-30-01, AMM 21-30-02PROC. REF: AMM 21-30-01, AMM 21-30-02									PKG:13

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
O2130001 ^S	OUTFLOW VALVE AIR FILTER - REMOVE AND REPLACE								Service ATA:21
	MOS	25-Jun-26	96						
	HRS	10023.1	2400						
	AFL	7616							
PROC. REF: AMM 21-30-04PROC. REF: AMM 21-30-04									
PKG:19									
O2130002 ^S	** PRESSURIZATION CONTROL SYSTEM - PERFORM FUNCTIONAL TEST. (AWL **)								Service ATA:21
	MOS	09-Mar-01	48					AIRWORTHINESS	
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 21-30-00PROC. REF: AMM 21-30-00									
PKG:13									
Y2130003 ^S	PRESSURIZATION CONTROL SYSTEM - PERFORM OPERATIONAL CHECK								Service ATA:21
	MOS	25-Jun-26	24						
	HRS	10023.1	600						
	AFL	7616							
PROC. REF: AMM 21-30-00PROC. REF: AMM 21-30-00									
PKG:7									
Y2130065	CABIN PRESSURIZATION SYSTEM - PERFORM CABIN LEAKAGE TEST								Service ATA:21
	MOS	22-Jun-23							
	HRS	9258.5	1200		10458.5		357.1		
	AFL	7100							
PROC. REF: AMM 21-30-00PROC. REF: AMM 21-30-00									
Y2140000 ^S	AIR CYCLE MACHINE HEAT EXCHANGER INLET - PERFORM VISUAL INSPECTION								Service ATA:21
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
PKG:14									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
Y2140001	NO. 1 ENGINE OZONE CONVERTER - PERFORM CLEANING AND EFFICIENCY TEST								Service ATA:21
PN:4520000100-801	MOS	01-Apr-22							
SN:2298	HRS	8936.8	3600		12536.8		2435.4		
	AFL	6867							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
Y2140001	NO. 2 ENGINE OZONE CONVERTER - PERFORM CLEANING AND EFFICIENCY TEST								Service ATA:21
PN:4520000100-801	MOS	01-Apr-22							
SN:2305	HRS	8936.8	3600		12536.8		2435.4		
	AFL	6867							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
Y2141000 ^S	ENVIRONMENTAL CONTROL UNIT - PERFORM VISUAL INSPECTION								Service ATA:21
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:14
Y2141001 ^S	WATER SEPARATOR COALESCER BAG - PERFORM VISUAL INSPECTION. CLEAN IF NECESSARY.								Service ATA:21
	MOS	25-Jun-26	12						
	HRS	10023.1	300						
	AFL	7616							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:2
Y2141002	WATER SEPARATOR COALESCER BAG - REPLACE								Service ATA:21
	MOS/MSC	09-Mar-01	O/C						
	HRS	0							
	AFL	0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
Y2142000 ^S	BAGGAGE COMPARTMENT HEATING SYSTEM - PERFORM FUNCTIONAL TEST								Service ATA:21
	MOS	25-Jun-26	96						
	HRS	10023.1	2400						
	AFL	7616							
									PKG:20

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
---------	------	-------	----------	------------	----------------------------	-----------	-----------	-------------	----------

ATA 21 - AIR CONDITIONING

PROC. REF: AMM 21-40-00PROC. REF: AMM 21-40-00

Y2145000	^S	ECS PLENUM ASSEMBLY CHECK VALVES - PERFORM VISUAL INSPECTION. VERIFY FREEDOM OF MOVEMENT OF BUTTERFLY ASSEMBLY.						Service	ATA:21
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							

PKG:14

PROC. REF: AMM 21-20-03, AMM 21-20-09PROC. REF: AMM 21-20-03, AMM 21-20-09

Y2150058	^S	PERFORM VISUAL INSPECTION OF AIR CONDITIONING SYSTEM COMPONENTS, INCLUDING COMPRESSOR MOTOR BELT FOR WEAR AND PROPER V-BELT TENSION, CONDENSER COILS FOR CLEANLINESS AND HOSES FOR CHAFING AND WEAR. IF OIL LEAKS ARE VISIBLE AND/OR REFRIGERANT DUMPED, CHECK COMPRESSOR OIL LEVEL. SOME LEAKAGE IS ALLOWABLE AROUND SHAFT.						Service	ATA:21
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							

PKG:14

PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00

Y2150059	^S	AIR CONDITIONING SYSTEM - PERFORM LOAD SHED ASSEMBLY CHECK						Service	ATA:21
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							

PKG:14

PROC. REF: AMM 21-51-00PROC. REF: AMM 21-51-00

ATA 22 - AUTO FLIGHT

2210-RVSM		FLIGHT CHECK AUTOMATIC ALTITUDE HOLD FUNCTIONAL. RVSM COMPLIANT AIRCRAFT.						Service	ATA:22
	MOS/MSC	09-Mar-01	N/R						
	HRS	0							
	AFL	0							

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

221001		AUTOPILOT FLIGHT GUIDANCE CONTROLLER						Component	ATA:22
PN:7021170-901	MOS/MSC	25-Jan-19	O/C						
SN:05111601	HRS	8026.4							
	AFL	6168							

PROC. REF: AMM 22-10-01PROC. REF: AMM 22-10-01

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 22 - AUTO FLIGHT									
221041	AUTOPILOT ROLL SERVO								Component ATA:22
PN:PN 4006719-948	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 22-10-04PROC. REF: AMM 22-10-04									
221045	AUTOPILOT ROLL SERVO BRACKET								Component ATA:22
PN:PN 4005842	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 22-10-05PROC. REF: AMM 22-10-05									
221051	AUTOPILOT PITCH SERVO								Component ATA:22
PN:PN 4006719-908	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 22-10-02PROC. REF: AMM 22-10-02									
221055	AUTOPILOT PITCH SERVO BRACKET								Component ATA:22
PN:PN 4005842	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 22-10-03PROC. REF: AMM 22-10-03									
221061	AUTOPILOT YAW SERVO								Component ATA:22
PN:PN 7012919-903	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 22-10-06PROC. REF: AMM 22-10-06									
221065	AUTOPILOT YAW SERVO BRACKET								Component ATA:22
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 22-10-07PROC. REF: AMM 22-10-07									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 22 - AUTO FLIGHT									
225001	YAW INTERFACE UNIT							Component	ATA:22
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 22-50-01PROC. REF: AMM 22-50-01									
225031	PILOT RUDDER BOOST SYSTEM YAW FORCE SENSOR							Component	ATA:22
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 22-50-02PROC. REF: AMM 22-50-02									
225032	COPILOT RUDDER BOOST SYSTEM YAW FORCE SENSOR							Component	ATA:22
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 22-50-02PROC. REF: AMM 22-50-02									
A2210033 ^S	** AUTOPILOT SYSTEM - PERFORM AUTOPILOT DISCONNECT TONE TEST							Service	ATA:22
	MOS	25-Jun-26	24					AIRWORTHINESS	
	HRS	10023.1	600						
	AFL	7616							
PROC. REF: AMM 22-10-00PROC. REF: AMM 22-10-00									
G2210030 ^S	PITCH SERVO CABLES - PERFORM CABLE TENSION CHECK							Service	ATA:22
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 22-10-03PROC. REF: AMM 22-10-03									
G2210031 ^S	ROLL SERVO CABLES - PERFORM CABLE TENSION CHECK							Service	ATA:22
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 22-10-05PROC. REF: AMM 22-10-05									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
---------	------	-------	----------	------------	----------------------------	-----------	-----------	-------------	----------

ATA 22 - AUTO FLIGHT

G2210032	^S	YAW SERVO CABLES - PERFORM CABLE TENSION CHECK						Service	ATA:22
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 22-10-07PROC. REF: AMM 22-10-07									PKG:14

ATA 23 - COMMUNICATIONS

230001		UNILINK PROCESSOR						Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

230002		CONFIGURATION MODULE						Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

231011		NO. 1 POWER AMPLIFIER/HF ANTENNA COUPLER						Component	ATA:23
PN:064-1017-01	MOS/MSC	12-Feb-08	O/C						
SN:17280	HRS	5965.9							
	AFL	4561							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

231012		NO. 2 POWER AMPLIFIER/HF ANTENNA COUPLER						Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

231021		NO. 1 VHF COMMUNICATIONS TRANSCEIVER UNIT						Component	ATA:23
PN:7510733-616	MOS/MSC	11-May-18	O/C						
SN:98093272	HRS	7850.8							
	AFL	6024							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
---------	------	-------	----------	------------	----------------------------	-----------	-----------	-------------	----------

ATA 23 - COMMUNICATIONS

PROC. REF: AMM 23-11-01PROC. REF: AMM 23-11-01

231021A	TEST/INSPECT ATC TRANSPONDER							Service	ATA:23
	MOS	24-Aug-26	24		16-Aug-28		701 d		
	HRS	10074							
	AFL	7658							
Calibration Date: : 16-Aug-26									
PROC. REF: AMM 23-11-00, FAR FAR 91.413PROC. REF: AMM 23-11-00, FAR FAR 91.413									

231022	NO. 2 VHF COMMUNICATIONS TRANSCEIVER UNIT							Component	ATA:23
PN:7510733-616	MOS/MSC	13-Apr-17	O/C						
SN:99054063	HRS	7744.3							
	AFL	5922							
PROC. REF: AMM 23-11-01, FAR FAR 91.413PROC. REF: AMM 23-11-01, FAR FAR 91.413									

231022A	TEST/INSPECT ATC TRANSPONDER							Service	ATA:23
	MOS	24-Aug-26	24		16-Aug-28		701 d		
	HRS	10074							
	AFL	7658							
Calibration Date: : 16-Aug-26									
PROC. REF: AMM 23-11-00, FAR FAR 91.413PROC. REF: AMM 23-11-00, FAR FAR 91.413									

231030	NO. 1 HF SELECTIVE CALLING (SELCAL) RECEIVER/EXCITER							Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

231031	NO. 2 HF SELECTIVE CALLING (SELCAL) RECEIVER/EXCITER							Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 10101.4
 AFL: 7674
 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
231032	HF SELECTIVE CALLING (SELCAL) ANTENNA							Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
231033	UPPER VHF ANTENNA							Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-11-02PROC. REF: AMM 23-11-02									
231034	LOWER VHF ANTENNA							Component	ATA:23
PN:DMC60-17-1	MOS/MSC	16-Jul-19	O/C	TSN 0					
SN:18936	HRS	8109		TSN 0					
	AFL	6239		TSN 0					
PROC. REF: AMM 23-11-02PROC. REF: AMM 23-11-02									
231045	NO. 1 HF CONTROL (MODEL KCU-951)							Component	ATA:23
PN:064-1016-03	MOS/MSC	25-Feb-08	O/C						
SN:11903	HRS	5974.6							
	AFL	4566							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
231046	NO. 2 HF CONTROL (MODEL KCU-951)							Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
231051	NO. 1 HF BRIDGING AMPLIFIER							Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
231052	NO. 2 HF BRIDGING AMPLIFIER							Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
231090	PILOT HEADSET							Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
231091	COPILOT HEADSET							Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
231300	MAGNASTAR PHONE TRANSCEIVER							Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
231305	MAGNASTAR ANTENNA							Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
231307	COCKPIT PHONE							Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
231308	CABIN PHONE							Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
231310	ARTU TRAY							Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
231313	NO. 1 CABIN DISTRIBUTION BUS REPEATER							Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
231314	NO. 2 CABIN DISTRIBUTION BUS REPEATER							Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
231315	CALL ALERTER SWITCH (CAS)							Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
231320	NO. 1 CABIN IRIDIUM SATCOM HANDSET							Component	ATA:23
PN:P12248-003	MOS/MSC	12-Feb-08	O/C	TSN 0					
SN:UNKNOWN	HRS	5965.9		TSN 0					
	AFL	4561		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 10101.4
 AFL: 7674
 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
231321	NO. 2 CABIN IRIDIUM SATCOM HANDSET							Component	ATA:23
PN:P12192-002	MOS/MSC	12-Feb-08	O/C	TSN 0					
SN:UNKNOWN	HRS	5965.9		TSN 0					
	AFL	4561		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
231322	CABIN IRIDIUM SATCOM PHONE CRADLE							Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
231323	IRIDIUM SATCOM TRANSCEIVER							Component	ATA:23
PN:P12023	MOS/MSC	12-Feb-08	O/C						
SN:1202310876	HRS	5965.9							
	AFL	4561							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
231325	IRIDIUM SATCOM SONALERT							Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
231327	COCKPIT IRIDIUM SATCOM PHONE CRADLE							Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
231328	COCKPIT IRIDIUM SATCOM HANDSET							Component	ATA:23
PN:P12192-002	MOS/MSC	12-Feb-08	O/C	TSN 0					
SN:UNKNOWN	HRS	5965.9		TSN 0					
	AFL	4561		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information
 S-Suppressed Requirement
 *-Estimated Due(New Requirement)
 (EFF)-Effective C / W
 (M)-Manual Due
 U-User Task
 Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 10101.4
 AFL: 7674
 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
231330	FORWARD IRIDIUM SATCOM ANTENNA							Component	ATA:23
PN:S67-1575-165	MOS/MSC	12-Feb-08	O/C						
SN:449-2303	HRS	5965.9							
	AFL	4561							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
231335	COCKPIT IRIDIUM SATCOM BASE UNIT							Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
233001	FORWARD CABIN VIDEO MONITOR							Component	ATA:23
PN:AL-LCD104-04-1	MOS/MSC	06-Aug-06	O/C						
SN:120000638	HRS	4725.85							
	AFL	3628							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
233002	AFT CABIN VIDEO MONITOR							Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
233003	AUDIO DISTRIBUTION MODULE							Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
233005	PUBLIC ADDRESS SYSTEM AMPLIFER							Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-30-02PROC. REF: AMM 23-30-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
233010	INFRARED REMOTE RECEIVER MODULE							Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
233015	AUDIO/VIDEO CONTROLLER							Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
233053	DVD PLAYER							Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
233054	CD PLAYER CHANGER							Component	ATA:23
PN:MCD-102-RU-3	MOS/MSC	21-Jun-05	O/C						
SN:060101192	HRS	3694.5							
	AFL	2785							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
233055	CD PLAYER CONTROL UNIT							Component	ATA:23
PN:MCD-102-CH-1	MOS/MSC	22-May-06	O/C						
SN:100000353	HRS	4507.7							
	AFL	3441							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
233056	CASSETTE TAPE PLAYER							Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
233101	LEFT FORWARD CABIN SPEAKER							Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-30-01PROC. REF: AMM 23-30-01									
233102	RIGHT FORWARD CABIN SPEAKER							Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-30-01PROC. REF: AMM 23-30-01									
233103	LEFT AFT CABIN SPEAKER							Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-30-01PROC. REF: AMM 23-30-01									
233104	RIGHT AFT CABIN SPEAKER							Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-30-01PROC. REF: AMM 23-30-01									
233105	SUBWOOFER SPEAKER							Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
233201	PASSENGER INTERFACE UNIT							Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C / W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
234000	INTERPHONE JACK BOX ASSEMBLY							Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
235001	NO. 1 AUDIO CONTROL UNIT							Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-50-01PROC. REF: AMM 23-50-01									
235002	NO. 2 AUDIO CONTROL UNIT							Component	ATA:23
PN:7511001-937	MOS/MSC	12-Sep-22	O/C						
SN:04049325	HRS	9101.8							
	AFL	6994							
PROC. REF: AMM 23-50-01PROC. REF: AMM 23-50-01									
235013	LEFT COCKPIT SPEAKER							Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-50-03PROC. REF: AMM 23-50-03									
235014	RIGHT COCKPIT SPEAKER							Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-50-03PROC. REF: AMM 23-50-03									
236005	XM RADIO WEATHER RECEIVER							Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C / W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
236010	XM RADIO WEATHER DATA PORT							Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
236015	XM RADIO ANTENNA							Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
236096	NO. 1 NAVIGATION STRAP BOARD							Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-51-05PROC. REF: AMM 34-51-05									
236097	NO. 2 NAVIGATION STRAP BOARD							Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-51-05PROC. REF: AMM 34-51-05									
236098	NO. 1 COMMUNICATION STRAP BOARD							Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-11-03PROC. REF: AMM 23-11-03									
236099	NO. 2 COMMUNICATION STRAP BOARD							Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-11-03PROC. REF: AMM 23-11-03									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
237001	COCKPIT VOICE RECORDER (CVR)							Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-70-01PROC. REF: AMM 23-70-01									
237005	COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON (CVR ULB)							Component	ATA:23
PN:DK120	MOS/MSC	25-Jun-26	O/C	TSN 22					
SN:NT60040	HRS	10023.1		TSN 497.4					
	AFL	7616		TSN 340					
PROC. REF: AMM 25-61-01PROC. REF: AMM 25-61-01									
237018	COCKPIT VOICE RECORDER (CVR) INERTIA SWITCH							Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-70-05PROC. REF: AMM 23-70-05									
237019	COCKPIT AREA MICROPHONE							Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
237030	PANEL SWITCH							Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
237031	COCKPIT VOICE RECORDER PRE-AMPLIFIER							Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-70-03PROC. REF: AMM 23-70-03									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
238001	NO. 1 RADIO MANAGEMENT UNIT (RMU)							Component	ATA:23
PN:7013270-985	MOS/MSC	04-May-18	O/C						
SN:06125540	HRS	7849.4							
	AFL	6022							
PROC. REF: AMM 23-80-01PROC. REF: AMM 23-80-01									
238002	NO. 2 RADIO MANAGEMENT UNIT (RMU)							Component	ATA:23
PN:7013270-985	MOS/MSC	16-Mar-18	O/C						
SN:1248264	HRS	7800.1							
	AFL	5976							
PROC. REF: AMM 23-80-01PROC. REF: AMM 23-80-01									
238025	CLEARANCE DELIVERY UNIT							Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-82-01PROC. REF: AMM 23-82-01									
239004	MASTER CONTROL SWITCH							Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
239011	LAVATORY MASTER CONTROL SWITCH							Component	ATA:23
PN:8500-000077-6767	MOS/MSC	03-Mar-06	O/C						
SN:0123	HRS	4328.77							
	AFL	3297							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
A2300000 ^S	** COMMUNICATION SYSTEMS - PERFORM OPERATIONAL CHECK							Service	ATA:23
	MOS	25-Jun-26	24					AIRWORTHINESS	
	HRS	10023.1	600						
	AFL	7616							
PROC. REF: AMM 23-00-00PROC. REF: AMM 23-00-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
V2312003	^S	HF ANTENNA - PERFORM VISUAL INSPECTION. CHECK FOR PROPER TENSION OF HF ANTENNA WIRE.						Service	ATA:23
	MOS	12-Aug-15	48						
	HRS	7535.1	1200						
	AFL	5764							
PROC. REF: AMM 23-12-04PROC. REF: AMM 23-12-04									PKG:14
Y2360020	^S	AIRCRAFT STATIC DISCHARGERS - PERFORM FUNCTIONAL TEST						Service	ATA:23
	MOS	25-Jun-26	96						
	HRS	10023.1	2400						
	AFL	7616							
PROC. REF: AMM 23-60-00PROC. REF: AMM 23-60-00									PKG:20
Y2360023	^S	AIRCRAFT STATIC DISCHARGERS - PERFORM FUNCTIONAL TEST						Service	ATA:23
	MOS	25-Jun-26	96						
	HRS	10023.1	2400						
	AFL	7616							
PROC. REF: AMM 23-60-00PROC. REF: AMM 23-60-00									PKG:22
ATA 24 - ELECTRICAL POWER									
240109		AFT CIRCUIT BREAKER PANEL						Component	ATA:24
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 24-60-04PROC. REF: AMM 24-60-04									
242000		NO. 1 ALTERNATOR						Component	ATA:24
PN:90278-2	MOS/MSC	14-Feb-24	O/C	TSO 0					
SN:651	HRS	9467.2		TSO 0					
	AFL	7246		TSO 0					
PROC. REF: AMM 24-20-01PROC. REF: AMM 24-20-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 24 - ELECTRICAL POWER									
242001	NO. 2 ALTERNATOR							Component	ATA:24
PN:90278-2	MOS/MSC	19-May-22	O/C	TSO	0				
SN:1488	HRS	8995.3		TSO	0				
	AFL	6902		TSO	0				
PROC. REF: AMM 24-20-01PROC. REF: AMM 24-20-01									
242008	AC/DC VOLT INDICATOR							Component	ATA:24
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN	0				
SN:UNKNOWN	HRS	0		TSN	0				
	AFL	0		TSN	0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
242050	NO. 1 REMOTE CONTROL CIRCUIT BREAKER							Component	ATA:24
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN	0				
SN:UNKNOWN	HRS	0		TSN	0				
	AFL	0		TSN	0				
PROC. REF: AMM 24-60-01PROC. REF: AMM 24-60-01									
242052	NO. 2 REMOTE CONTROL CIRCUIT BREAKER							Component	ATA:24
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN	0				
SN:UNKNOWN	HRS	0		TSN	0				
	AFL	0		TSN	0				
PROC. REF: AMM 24-60-01PROC. REF: AMM 24-60-01									
242054	NO. 3 REMOTE CONTROL CIRCUIT BREAKER							Component	ATA:24
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN	0				
SN:UNKNOWN	HRS	0		TSN	0				
	AFL	0		TSN	0				
PROC. REF: AMM 24-60-01PROC. REF: AMM 24-60-01									
242081	CABIN ELECTRICAL INVERTER							Component	ATA:24
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN	0				
SN:UNKNOWN	HRS	0		TSN	0				
	AFL	0		TSN	0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 24 - ELECTRICAL POWER									
242082	TAILCONE ELECTRICAL INVERTER							Component	ATA:24
PN:PN	MOS/MSC	09-Mar-01	A/R	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
242083	ELECTRICAL INVERTER							Component	ATA:24
PN:SS120(C)	MOS/MSC	23-Jul-13	A/R						
SN:320	HRS	7175.4							
	AFL	5474							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
243001	NO. 1 STARTER/GENERATOR							Component	ATA:24
PN:23280-067	MOS/MSC	27-Oct-25	O/C	TSO 0					
SN:Y01027	HRS	9906.2		TSO 0					
	AFL	7538		TSO 0					
PROC. REF: AMM 24-30-01PROC. REF: AMM 24-30-01									
243002	NO. 2 STARTER/GENERATOR							Component	ATA:24
PN:23280-067	MOS/MSC	02-Aug-24	O/C	TSO 0					
SN:P1484LA	HRS	9525.7		TSO 0					
	AFL	7276		TSO 0					
PROC. REF: AMM 24-30-01PROC. REF: AMM 24-30-01									
243003	APU STARTER/GENERATOR							Component	ATA:24
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 49-40-01PROC. REF: AMM 49-40-01									
243005	LEFT GENERATOR CONTROL UNIT (GCU)							Component	ATA:24
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 24 - ELECTRICAL POWER									
243006	RIGHT GENERATOR CONTROL UNIT (GCU)							Component	ATA:24
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
243019	NO. 1 MAIN BATTERY							Component	ATA:24
PN:RG-380E/40L	MOS/MSC	02-Aug-24	O/C						
SN:41180857	HRS	9525.7							
	AFL	7276							
PROC. REF: AMM 24-31-01, AMM 24-31-06, CMM 24-30-71PROC. REF: AMM 24-31-01, AMM 24-31-06, CMM 24-30-71									
243020	NO. 2 MAIN BATTERY							Component	ATA:24
PN:RG-380E/40L	MOS/MSC	02-Aug-24	O/C	TSN 34					
SN:41180858	HRS	9525.7		TSN 762.4					
	AFL	7276		TSN 532					
PROC. REF: CMM 24-30-71PROC. REF: CMM 24-30-71									
243037	EMERGENCY BATTERY							Component	ATA:24
PN:RG-443	MOS/MSC	27-Oct-25	H/T	TSN 0					
SN:41475046	HRS	9906.2		TSN 0					
	AFL	7538		TSN 0					
PROC. REF: AMM 24-32-01, CMM 24-30-67PROC. REF: AMM 24-32-01, CMM 24-30-67									
246001	LEFT FORWARD POWER DISTRIBUTION PANEL							Component	ATA:24
PN:650GC02Y03	MOS/MSC	21-Jun-18	O/C						
SN:575	HRS	7887.8							
	AFL	6051							
PROC. REF: AMM 24-60-02PROC. REF: AMM 24-60-02									
246002	RIGHT FORWARD POWER DISTRIBUTION PANEL							Component	ATA:24
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 24-60-02PROC. REF: AMM 24-60-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 24 - ELECTRICAL POWER									
246003	LEFT AFT POWER DISTRIBUTION PANEL								Component ATA:24
PN:660GC02Y07	MOS/MSC	30-Jan-11	O/C						
SN:588	HRS	6501.3							
	AFL	4977							
PROC. REF: AMM 24-60-03PROC. REF: AMM 24-60-03									
246004	RIGHT AFT POWER DISTRIBUTION PANEL								Component ATA:24
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 24-60-03PROC. REF: AMM 24-60-03									
246101	LEFT GENERATOR CONTROL UNIT PRINTED CIRCUIT BOARD								Component ATA:24
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
246102	LEFT LOGIC PRINTED CIRCUIT BOARD								Component ATA:24
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
246104	RIGHT GENERATOR CONTROL UNIT PRINTED CIRCUIT BOARD								Component ATA:24
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
246105	RIGHT LOGIC PRINTED CIRCUIT BOARD								Component ATA:24
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
---------	------	-------	----------	------------	----------------------------	-----------	-----------	-------------	----------

ATA 24 - ELECTRICAL POWER

246106	APU GENERATOR CONTROL UNIT PRINTED CIRCUIT BOARD							Component	ATA:24
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

AB2431062	EMERGENCY BATTERY - PERFORM CAPACITY CHECK							Service	ATA:24
PN:RG-443	MOS	27-Oct-25	12		27-Oct-26		42 d		
SN:41475046	HRS	9906.2	1000		10906.2		804.8		
	AFL	7538							

AB2431063	EMERGENCY BATTERY - REPLACE							Service	ATA:24
PN:RG-443	MOS	27-Oct-25	48		27-Oct-29		1138 d	LIFE LIMIT	
SN:41475046	HRS	9906.2							
	AFL	7538							

AC2460002 ^S	REMOVE ATTACHING PARTS SECURING CIRCUIT BREAKER PANEL TO STRUCTURE. CHECK FOR LOOSE CIRCUIT BREAKER TERMINALS, LOOSE WIRE TERMINALS, CORRODED TERMINALS OR BUS BARS, AND EVIDENCE OF WIRE INSULATION DAMAGE.							Service	ATA:24
	MOS	25-Jun-26	96						
	HRS	10023.1	2400						
	AFL	7616							
									PKG:19
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

B2450002 ^S	** ELECTRICAL SYSTEM CONTROL - PERFORM OPERATIONAL CHECK							Service	ATA:24
	MOS	09-Mar-01	48					AIRWORTHINESS	
	HRS	0	1200						
	AFL	0							
									PKG:13
PROC. REF: AMM 24-00-00PROC. REF: AMM 24-00-00									

F2420000	** NO. 1 ALTERNATOR - PERFORM BEARING REPLACEMENT							Service	ATA:24
PN:90278-2	MOS	14-Feb-24						AIRWORTHINESS	
SN:651	HRS	9467.2	1200		10667.2		565.8		
	AFL	7246							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 24 - ELECTRICAL POWER									
F2420000	** NO. 2 ALTERNATOR - PERFORM BEARING REPLACEMENT								Service ATA:24
PN:90278-2	MOS	19-May-22						AIRWORTHINESS	
SN:1488	HRS	8995.3	1200		10195.3		93.9		
	AFL	6902							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
H2450001 ^S	** AUXILIARY POWER SUPPLIES - PERFORM FUNCTIONAL TEST								Service ATA:24
	MOS	25-Jun-26	24					AIRWORTHINESS	
	HRS	10023.1	600						
	AFL	7616							
PROC. REF: AMM 24-00-00PROC. REF: AMM 24-00-00									
H2450023 ^S	** EMER BATT LOW AND GEN AMPS HIGH INDICATION - PERFORM OPERATIONAL CHECK								Service ATA:24
	MOS	25-Jun-26	24					AIRWORTHINESS	
	HRS	10023.1	600						
	AFL	7616							
PROC. REF: AMM 24-00-00PROC. REF: AMM 24-00-00									
O2431002	EMERGENCY BATTERY - PERFORM CAPACITY CHECK								Service ATA:24
PN:RG-443	MOS/MSC	27-Oct-25	N/A						
SN:41475046	HRS	9906.2							
	AFL	7538							
PROC. REF: CMM 24-30-67PROC. REF: CMM 24-30-67									
P2430003	NO. 1 STARTER/GENERATOR - PERFORM OVERHAUL								Service ATA:24
PN:23280-067	MOS	27-Oct-25							
SN:Y01027	HRS	9906.2	1200		11106.2		1004.8		
	AFL	7538							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
P2430003	NO. 2 STARTER/GENERATOR - PERFORM OVERHAUL								Service ATA:24
PN:23280-067	MOS	02-Aug-24							
SN:P1484LA	HRS	9525.7	1200		10725.7		624.3		
	AFL	7276							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
---------	------	-------	----------	------------	----------------------------	-----------	-----------	-------------	----------

ATA 24 - ELECTRICAL POWER

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

P2430007	NO. 1 STARTER/GENERATOR - REPLACE BEARINGS							Service	ATA:24
PN:23280-067	MOS/MSC	27-Oct-25	N/A						
SN:Y01027	HRS	9906.2							
	AFL	7538							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

P2430007	NO. 2 STARTER/GENERATOR - REPLACE BEARINGS							Service	ATA:24
PN:23280-067	MOS/MSC	02-Aug-24	N/A						
SN:P1484LA	HRS	9525.7							
	AFL	7276							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

Q2460001 ^S	** POWER DISTRIBUTION SYSTEM - PERFORM SQUAT SWITCH CHECK							Service	ATA:24
	MOS	09-Mar-01	48					AIRWORTHINESS	
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 24-60-00PROC. REF: AMM 24-60-00									
									PKG:17

R2431003 ^S	** BATTERY WARNING SYSTEM - PERFORM FUNCTIONAL TEST							Service	ATA:24
	MOS	25-Jun-26	96					AIRWORTHINESS	
	HRS	10023.1	2400						
	AFL	7616							
PROC. REF: AMM 24-31-00PROC. REF: AMM 24-31-00									
									PKG:19

W2450000 ^S	** GENERATOR FAIL INDICATION - PERFORM OPERATIONAL CHECK							Service	ATA:24
	MOS	25-Jun-26	24					AIRWORTHINESS	
	HRS	10023.1	600						
	AFL	7616							
PROC. REF: AMM 24-00-00PROC. REF: AMM 24-00-00									
									PKG:7

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 24 - ELECTRICAL POWER									
Y2400001	^S	SWITCH AND CIRCUIT BREAKER PANELS - PERFORM VISUAL INSPECTION						Service	ATA:24
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:13
Y2400002	^S	ELECTRICAL WIRING - PERFORM VISUAL INSPECTION FOR ROUTING, SECURITY, CLEARANCES, CHAFING, AND ELECTRICAL COMPONENTS FOR SECURITY AND GENERAL CONDITION.						Service	ATA:24
	MOS	25-Jun-26	24						
	HRS	10023.1	600						
	AFL	7616							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:7
Y2400025	^S	ELECTRICAL WIRING - PERFORM VISUAL INSPECTION FOR ROUTING, SECURITY, CLEARANCES, CHAFING, AND ELECTRICAL COMPONENTS FOR SECURITY AND GENERAL CONDITION.						Service	ATA:24
	MOS	25-Jun-26	24						
	HRS	10023.1	600						
	AFL	7616							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:8
Y2430005	^S	STARTER/GENERATOR - PERFORM GROUNDING LUG BONDING CHECK						Service	ATA:24
	MOS	25-Jun-26	24						
	HRS	10023.1	600						
	AFL	7616							
PROC. REF: AMM 24-30-01PROC. REF: AMM 24-30-01									PKG:9
Y2430006	^S	STARTER/GENERATOR - PERFORM VISUAL INSPECTION OF GROUNDING LUGS						Service	ATA:24
	MOS	25-Jun-26	24						
	HRS	10023.1	600						
	AFL	7616							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:9

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 24 - ELECTRICAL POWER									
Y2431000	^S	BATTERY, GENERATOR, AND BUS-TIE CABLES - PERFORM VISUAL INSPECTION						Service	ATA:24
	MOS	25-Jun-26	96						
	HRS	10023.1	2400						
	AFL	7616							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:20
Y2431001	^S	EMERGENCY BATTERY CABLES - PERFORM VISUAL INSPECTION						Service	ATA:24
	MOS	25-Jun-26	24						
	HRS	10023.1	600						
	AFL	7616							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:7
Y2431005		BATTERY CABLES AND RECEPTACLES - PERFORM BATTERY CONNECTOR TOLERANCE CHECK						Service	ATA:24
	MOS	25-Jun-26							
	HRS	10023.1	300		10323.1		221.7		
	AFL	7616							
PROC. REF: AMM 24-31-00PROC. REF: AMM 24-31-00									
Y2460000	^S	DC BUS ISOLATION - PERFORM OPERATIONAL CHECK						Service	ATA:24
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 24-60-00PROC. REF: AMM 24-60-00									PKG:13
ATA 25 - EQUIPMENT/FURNISHINGS									
250010		RELAY MODULE						Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

? - Insufficient Information
S - Suppressed Requirement
* - Estimated Due(New Requirement)
(EFF) - Effective C / W
(M) - Manual Due
U - User Task
Ex - Excluded Task

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
252000	JUMP SEAT							Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45									
252000	NO. 1 PASSENGER SEAT							Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45									
252000	NO. 2 PASSENGER SEAT							Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45									
252000	NO. 3 PASSENGER SEAT							Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45									
252000	NO. 4 PASSENGER SEAT							Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45									
252000	NO. 5 PASSENGER SEAT							Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45									

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C / W
(M)-Manual Due
U-User Task
Ex-Excluded Task

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT / FURNISHINGS									
252000	NO. 6 PASSENGER SEAT							Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45									
252000	NO. 7 PASSENGER SEAT							Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45									
252000	NO. 8 PASSENGER SEAT							Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45									
252001	LAVATORY PCU							Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	A/R	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45									
252001	NO. 1 PASSENGER SEAT PCU							Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45									
252001	NO. 2 PASSENGER SEAT PCU							Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45									

?-Insufficient Information
 S-Suppressed Requirement
 *-Estimated Due(New Requirement)
 (EFF)-Effective C / W
 (M)-Manual Due
 U-User Task
 Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT / FURNISHINGS									
252001	NO. 3 PASSENGER SEAT PCU							Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45									
252001	NO. 4 PASSENGER SEAT PCU							Component	ATA:25
PN:SP-45-07A	MOS/MSC	05-Apr-06	O/C						
SN:020600592	HRS	4422.47							
	AFL	3369							
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45									
252001	NO. 5 PASSENGER SEAT PCU							Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45									
252001	NO. 6 PASSENGER SEAT PCU							Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45									
252001	NO. 7 PASSENGER SEAT PCU							Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45									
252001	NO. 8 PASSENGER SEAT PCU							Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45									

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C / W
(M)-Manual Due
U-User Task
Ex-Excluded Task

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
252010	AIRSHOW COMPUTER							Component	ATA:25
PN:920040	MOS/MSC	06-Mar-09	O/C						
SN:452	HRS	6115.4							
	AFL								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
252020	CLOSET SWITCH PANEL ASSEMBLY							Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
252090	NO. 1 110 VOLT POWER OUTLET							Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
252091	NO. 2 110 VOLT POWER OUTLET							Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
252092	NO. 3 110 VOLT POWER OUTLET							Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
252095	NO. 4 110 VOLT POWER OUTLET							Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information
 S-Suppressed Requirement
 *-Estimated Due(New Requirement)
 (EFF)-Effective C / W
 (M)-Manual Due
 U-User Task
 Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT / FURNISHINGS									
252097	NO. 1 AC POWER OUTLET							Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
252098	NO. 2 AC POWER OUTLET							Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
252099	NO. 3 AC POWER OUTLET							Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
253001	MICROWAVE OVEN							Component	ATA:25
PN:255A-LH28-115	MOS/MSC	28-Jul-05	O/C						
SN:19976	HRS	3775.77							
	AFL	2849							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
253075	NO. 1 HEATED WATER CONTAINER							Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
253076	NO. 2 HEATED WATER CONTAINER							Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT / FURNISHINGS									
253077	HEATED WATER SWITCH							Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
253080	GALLEY DRAIN VALVE SOLENOID							Component	ATA:25
PN:8210G94-24DC	MOS/MSC	03-Jan-06	O/C						
SN:T116684	HRS	4160.77							
	AFL	3151							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
256001	PILOT CREW SEAT							Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 25-10-50PROC. REF: AMM 25-10-50									
256002	COPILOT CREW SEAT							Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 25-10-50PROC. REF: AMM 25-10-50									
256061	PILOTS LIFE VEST							Component	ATA:25
PN:P01074-201	MOS/MSC	25-Jun-26	O/C	TSO 0					
SN:359865	HRS	10023.1		TSO 0					
	AFL	7616		TSO 0					
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01									
256062	COPILOTS LIFE VEST							Component	ATA:25
PN:P01074-201	MOS/MSC	25-Jun-26	O/C	TSO 0					
SN:35861	HRS	10023.1		TSO 0					
	AFL	7616		TSO 0					
PROC. REF: CMM 25-60-05PROC. REF: CMM 25-60-05									

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C / W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT / FURNISHINGS									
256063	NO. 1 PASSENGER LIFE VEST							Component	ATA:25
PN:P01074-201	MOS/MSC	25-Jun-26	O/C	TSO 0					
SN:359856	HRS	10023.1		TSO 0					
	AFL	7616		TSO 0					
PROC. REF: CMM 25-60-05PROC. REF: CMM 25-60-05									
256064	NO. 2 PASSENGER LIFE VEST							Component	ATA:25
PN:P01074-201	MOS/MSC	25-Jun-26	O/C	TSO 0					
SN:359869	HRS	10023.1		TSO 0					
	AFL	7616		TSO 0					
PROC. REF: CMM 25-60-05PROC. REF: CMM 25-60-05									
256065	NO. 3 PASSENGER LIFE VEST							Component	ATA:25
PN:P01074-201	MOS/MSC	25-Jun-26	O/C	TSO 0					
SN:359864	HRS	10023.1		TSO 0					
	AFL	7616		TSO 0					
PROC. REF: CMM 25-60-05PROC. REF: CMM 25-60-05									
256066	NO. 4 PASSENGER LIFE VEST							Component	ATA:25
PN:P01074-201	MOS/MSC	25-Jun-26	O/C	TSO 0					
SN:359868	HRS	10023.1		TSO 0					
	AFL	7616		TSO 0					
PROC. REF: CMM 25-60-05PROC. REF: CMM 25-60-05									
256067	NO. 5 PASSENGER LIFE VEST							Component	ATA:25
PN:P01074-201	MOS/MSC	25-Jun-26	O/C	TSO 0					
SN:359873	HRS	10023.1		TSO 0					
	AFL	7616		TSO 0					
PROC. REF: CMM 25-60-05PROC. REF: CMM 25-60-05									
256068	NO. 6 PASSENGER LIFE VEST							Component	ATA:25
PN:P01074-201	MOS/MSC	25-Jun-26	O/C	TSO 0					
SN:359852	HRS	10023.1		TSO 0					
	AFL	7616		TSO 0					
PROC. REF: CMM 25-60-05PROC. REF: CMM 25-60-05									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
256069	NO. 7 PASSENGER LIFE VEST							Component	ATA:25
PN:P01074-201	MOS/MSC	25-Jun-26	O/C	TSO 0					
SN:359849	HRS	10023.1		TSO 0					
	AFL	7616		TSO 0					
PROC. REF: CMM 25-60-05PROC. REF: CMM 25-60-05									
256070	NO. 8 PASSENGER LIFE VEST							Component	ATA:25
PN:P01074-201	MOS/MSC	25-Jun-26	O/C	TSO 0					
SN:359866	HRS	10023.1		TSO 0					
	AFL	7616		TSO 0					
PROC. REF: CMM 25-60-05PROC. REF: CMM 25-60-05									
256071	LAVATORY LIFE VEST							Component	ATA:25
PN:P01074-201	MOS/MSC	25-Jun-26	O/C	TSO 0					
SN:359863	HRS	10023.1		TSO 0					
	AFL	7616		TSO 0					
PROC. REF: CMM 25-60-05PROC. REF: CMM 25-60-05									
256076	FIRST AID KIT							Component	ATA:25
PN:MSK70002	MOS/MSC	14-Jul-07	O/C						
SN:0602	HRS	5618.1							
	AFL	4293							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
256080	INSPECT LIFE VESTS							Service	ATA:25
	MOS/MSC	09-Mar-01	A/R						
	HRS	0							
	AFL	0							
PROC. REF: GENERIC NO REF, CMM 25-60-05PROC. REF: GENERIC NO REF, CMM 25-60-05									
256109	(ELT) EMERGENCY LOCATOR TRANSMITTER							Component	ATA:25
PN:453-5000	MOS/MSC	25-Jun-26	O/C	TSN 138					
SN:210-05727	HRS	10023.1		TSN 2588.9					
	AFL	7616		TSN 1929					
PROC. REF: AMM 25-62-01PROC. REF: AMM 25-62-01									

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C/W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
256109A	(ELT) EMERGENCY LOCATOR TRANSMITTER - PERFORM NATIONALY REQUIRED FUNCTIONAL TEST								Service ATA:25
PN:453-5000	MOS	25-Jun-26	12	Adj -142d	03-Feb-27		141 d		
SN:210-05727	HRS	10023.1							
	AFL	7616							
PROC. REF: AMM 25-62-00, FAR FAR 91.207PROC. REF: AMM 25-62-00, FAR FAR 91.207									
256109B	(ELT) EMERGENCY LOCATOR TRANSMITTER - INSPECT ELT BATTERIES								Service ATA:25
PN:453-5000	MOS	25-Jun-26	12		25-Jun-27		283 d		
SN:210-05727	HRS	10023.1							
	AFL	7616							
PROC. REF: AMM 25-62-00, FAR FAR 91.207PROC. REF: AMM 25-62-00, FAR FAR 91.207									
256109C	(ELT) EMERGENCY LOCATOR TRANSMITTER BATTERY - REPLACE								Service ATA:25
PN:453-5000	MOS	03-Feb-25	72		03-Feb-31		1602 d	LIFE LIMIT	
SN:210-05727	HRS	9605.4							
	AFL	7333							
PROC. REF: AMM 25-62-01, FAR FAR 91.207PROC. REF: AMM 25-62-01, FAR FAR 91.207									
256110	EMERGENCY LOCATOR TRANSMITTER (ELT)/NAVIGATION INTERFACE UNIT (C406-2)								Component ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
256115	EMERGENCY LOCATOR TRANSMITTER (ELT) ANTENNA								Component ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 25-62-03PROC. REF: AMM 25-62-03									
256116	EMERGENCY LOCATOR TRANSMITTER (ELT) REMOTE SWITCH								Component ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 25-62-04PROC. REF: AMM 25-62-04									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
258001	CABIN AIRSHOW DISPLAY COMPUTER UNIT							Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
259072	AUTOMATIC ELECTRONIC DEFIBRILLATOR (AED)							Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
259073	AUTOMATIC ELECTRONIC DEFIBRILLATOR (AED) BATTERIES							Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
259074	AUTOMATIC ELECTRONIC DEFIBRILLATOR (AED) ELECTRODE PADS							Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
AA2560000	COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON - CLEAN BEACON SWITCH, PERFORM FUNCTIONAL TEST OF BEACON, AND PERFORM TEST OF ULB BATTERY							Service	ATA:25
PN:DK120	MOS	25-Jun-26	24		25-Jun-28		649 d		
SN:NT60040	HRS	10023.1							
	AFL	7616							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
D2566001	COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON - REPLACE							Service	ATA:25
PN:DK120	MOS/MSC	02-Aug-24	DUE		31-Mar-29 (M)		928 d		
SN:NT60040	HRS	9525.7							
	AFL	7276							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT / FURNISHINGS									
E2561002	COPILOTS LIFE VEST - PERFORM INSPECTION OF LIFE VESTS								Service ATA:25
PN:P01074-201	MOS	25-Jun-26	60		21-Nov-29		1163 d		
SN:35861	HRS	10023.1							
	AFL	7616							
Inspection Date: : 21-Nov-24									
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01									
E2561002	LAVATORY LIFE VEST - PERFORM INSPECTION OF LIFE VESTS								Service ATA:25
PN:P01074-201	MOS	25-Jun-26	60		21-Nov-29		1163 d		
SN:359863	HRS	10023.1							
	AFL	7616							
Inspection Date: : 21-Nov-24									
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01									
E2561002	NO. 1 PASSENGER LIFE VEST - PERFORM INSPECTION OF LIFE VESTS								Service ATA:25
PN:P01074-201	MOS	25-Jun-26	60		21-Nov-29		1163 d		
SN:359856	HRS	10023.1							
	AFL	7616							
Inspection Date: : 21-Nov-24									
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01									
E2561002	NO. 2 PASSENGER LIFE VEST - PERFORM INSPECTION OF LIFE VESTS								Service ATA:25
PN:P01074-201	MOS	25-Jun-26	60		21-Nov-29		1163 d		
SN:359869	HRS	10023.1							
	AFL	7616							
Inspection Date: : 21-Nov-24									
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01									
E2561002	NO. 3 PASSENGER LIFE VEST - PERFORM INSPECTION OF LIFE VESTS								Service ATA:25
PN:P01074-201	MOS	25-Jun-26	60		21-Nov-29		1163 d		
SN:359864	HRS	10023.1							
	AFL	7616							
Inspection Date: : 21-Nov-24									
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01									

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C / W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT / FURNISHINGS									
E2561002	NO. 4 PASSENGER LIFE VEST - PERFORM INSPECTION OF LIFE VESTS								Service ATA:25
PN:P01074-201	MOS	25-Jun-26	60		21-Nov-29		1163 d		
SN:359868	HRS	10023.1							
	AFL	7616							
Inspection Date: : 21-Nov-24									
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01									
E2561002	NO. 5 PASSENGER LIFE VEST - PERFORM INSPECTION OF LIFE VESTS								Service ATA:25
PN:P01074-201	MOS	25-Jun-26	60		21-Nov-29		1163 d		
SN:359873	HRS	10023.1							
	AFL	7616							
Inspection Date: : 21-Nov-24									
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01									
E2561002	NO. 6 PASSENGER LIFE VEST - PERFORM INSPECTION OF LIFE VESTS								Service ATA:25
PN:P01074-201	MOS	25-Jun-26	60		21-Nov-29		1163 d		
SN:359852	HRS	10023.1							
	AFL	7616							
Inspection Date: : 21-Nov-24									
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01									
E2561002	NO. 7 PASSENGER LIFE VEST - PERFORM INSPECTION OF LIFE VESTS								Service ATA:25
PN:P01074-201	MOS	25-Jun-26	60		21-Nov-29		1163 d		
SN:359849	HRS	10023.1							
	AFL	7616							
Inspection Date: : 21-Nov-24									
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01									
E2561002	NO. 8 PASSENGER LIFE VEST - PERFORM INSPECTION OF LIFE VESTS								Service ATA:25
PN:P01074-201	MOS	25-Jun-26	60		21-Nov-29		1163 d		
SN:359866	HRS	10023.1							
	AFL	7616							
Inspection Date: : 21-Nov-24									
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01									

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C / W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT / FURNISHINGS									
E2561002	PILOTS LIFE VEST - PERFORM INSPECTION OF LIFE VESTS							Service	ATA:25
PN:P01074-201	MOS	25-Jun-26	60		21-Nov-29		1163 d		
SN:359865	HRS	10023.1							
	AFL	7616							
Inspection Date: : 21-Nov-24									
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01									
Y2510000 ^S	GLARESHIELD, HEADLINER, AND TRIM STRIPS - PERFORM VISUAL INSPECTION							Service	ATA:25
	MOS	25-Jun-26	12						
	HRS	10023.1	300						
	AFL	7616							
PKG:1									
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
Y2510001 ^S	CREW SEATS AND SEAT BELTS - PERFORM VISUAL INSPECTION							Service	ATA:25
	MOS	25-Jun-26	12						
	HRS	10023.1	300						
	AFL	7616							
PKG:1									
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
Y2520000 ^S	CABIN - PERFORM VISUAL INSPECTION OF THE FOLLOWING: A. CABIN SEATS AND SEAT BELTS. ENSURE THAT THE SEATS FUNCTION CORRECTLY AND LOCK IN PLACE. B. STOWAGE CABINETS. C. HEADLINER. D. SIDE PANELS. E. RUG.							Service	ATA:25
	MOS	25-Jun-26	12						
	HRS	10023.1	300						
	AFL	7616							
PKG:1									
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
Y2540000 ^S	ALL LAVATORY PAPER AND LINEN WASTE RECEPTACLE ACCESS DOORS AND DISPOSAL DOORS FOR PROPER OPERATION, FIT, SEALING, LATCHING, AND LEGIBILITY OF PLACARD.							Service	ATA:25
	MOS	25-Jun-26	24						
	HRS	10023.1	600						
	AFL	7616							
PKG:7									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
Y2540009	^S	AVIONICS EQUIPMENT AND WIRING LOCATED IN LAVATORY AREA - PERFORM GENERAL VISUAL INSPECTION							Service ATA:25
	MOS	09-Mar-01							
	HRS	0	4800						
	AFL	0							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
ATA 26 - FIRE PROTECTION									
261012		NO. 1 ENGINE FIREWALL FIRE DETECTION ELEMENT							Component ATA:26
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 26-11-02PROC. REF: AMM 26-11-02									
261013		NO. 2 ENGINE FIREWALL FIRE DETECTION ELEMENT							Component ATA:26
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 26-11-02PROC. REF: AMM 26-11-02									
261014		NO. 1 ENGINE ACCESSORY GEARBOX FIRE DETECTION ELEMENT							Component ATA:26
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 26-11-02PROC. REF: AMM 26-11-02									
261015		NO. 2 ENGINE ACCESSORY GEARBOX FIRE DETECTION ELEMENT							Component ATA:26
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 26-11-02PROC. REF: AMM 26-11-02									
261016		NO. 1 ENGINE HOT SECTION FIRE DETECTION ELEMENT							Component ATA:26
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 26-11-02PROC. REF: AMM 26-11-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 26 - FIRE PROTECTION									
261017	NO. 2 ENGINE HOT SECTION FIRE DETECTION ELEMENT							Component	ATA:26
PN:744-12135	MOS/MSC	12-Aug-15	O/C						
SN:UNKNOWN	HRS	7535.1							
	AFL	5764							
PROC. REF: AMM 26-11-02PROC. REF: AMM 26-11-02									
261057	NO. 1 FIRE DETECT CONTROL UNIT							Component	ATA:26
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 26-11-01PROC. REF: AMM 26-11-01									
261058	NO. 2 FIRE DETECT CONTROL UNIT							Component	ATA:26
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 26-11-01PROC. REF: AMM 26-11-01									
261069	NO. 1 BLEED AIR LEAK DETECTION UNIT							Component	ATA:26
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 26-12-01PROC. REF: AMM 26-12-01									
261070	NO. 2 BLEED AIR LEAK DETECTION UNIT							Component	ATA:26
PN:6626100000-003	MOS/MSC	18-Apr-12	O/C	TSN 0					
SN:2714	HRS	6879.9		TSN 0					
	AFL	5240		TSN 0					
PROC. REF: AMM 26-12-01PROC. REF: AMM 26-12-01									
261071	ANTI-ICE BLEED AIR LEAK DETECTION UNIT							Component	ATA:26
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 26-12-01PROC. REF: AMM 26-12-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 26 - FIRE PROTECTION									
261075	APU FIRE/OVERHEAT DETECTOR							Component	ATA:26
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 26-13-01PROC. REF: AMM 26-13-01									
262001	NO. 1/LEFT/LOWER FIRE EXTINGUISHER BOTTLE							Component	ATA:26
PN:33100021-1	MOS/MSC	22-Jun-23	O/C	TSO 0					
SN:59578B1	HRS	9258.5		TSO 0					
	AFL	7100		TSO 0					
PROC. REF: AMM 26-21-01PROC. REF: AMM 26-21-01									
262002	NO. 2/RIGHT/UPPER FIRE EXTINGUISHER BOTTLE							Component	ATA:26
PN:33100021-1	MOS/MSC	21-Aug-25	O/C	TSO 0					
SN:72043B1	HRS	9809.8		TSO 0					
	AFL	7471		TSO 0					
PROC. REF: AMM 26-21-01PROC. REF: AMM 26-21-01									
262013	NO. 1/LEFT/LOWER FIRE EXTINGUISHER, LEFT SQUIB							Component	ATA:26
PN:M30903856	MOS/MSC	06-Dec-18	H/T						
SN:02254	HRS	7976.3		TSN 0					
	AFL	6133		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
262014	NO. 1/LEFT/LOWER FIRE EXTINGUISHER, RIGHT SQUIB							Component	ATA:26
PN:M30903859	MOS/MSC	06-Dec-18	H/T						
SN:01619	HRS	7976.3		TSN 0					
	AFL	6133		TSN 0					
262015	NO. 2/RIGHT/UPPER FIRE EXTINGUISHER, LEFT SQUIB							Component	ATA:26
PN:30903856	MOS/MSC	21-Aug-25	H/T	TSN 5					
SN:03401	HRS	9809.8		TSN 0					
	AFL	7471		TSN 0					

?-Insufficient Information
 S-Suppressed Requirement
 *-Estimated Due(New Requirement)
 (EFF)-Effective C / W
 (M)-Manual Due
 U-User Task
 Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 26 - FIRE PROTECTION									
262016	NO. 2/RIGHT/UPPER FIRE EXTINGUISHER, RIGHT SQUIB							Component	ATA:26
PN:30903859	MOS/MSC	21-Aug-25	H/T	TSN 3					
SN:02408	HRS	9809.8		TSN 0					
	AFL	7471		TSN 0					
262040	APU FIRE WARNING HORN							Component	ATA:26
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 26-13-02PROC. REF: AMM 26-13-02									
262041	PILOT PORTABLE FIRE EXTINGUISHER							Component	ATA:26
PN:A344T	MOS/MSC	07-Dec-12	O/C						
SN:UNKNOWN	HRS	7016.8							
	AFL	5361							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
262042	COPILOT PORTABLE FIRE EXTINGUISHER							Component	ATA:26
PN:A344	MOS/MSC	18-May-16	O/C	TSN 0					
SN:B10813738	HRS	7623.3		TSN 0					
	AFL	5813		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
262051	CABIN PORTABLE FIRE EXTINGUISHER							Component	ATA:26
PN:C352	MOS/MSC	28-Dec-22	O/C	TSN 0					
SN:H-20651164	HRS	9186.7		TSN 0					
	AFL	7047		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
D2620007.S	NO. 1/LEFT/LOWER FIRE EXTINGUISHER, LEFT SQUIB - SERVICE LIFE LIMIT							Service	ATA:26
PN:M30903856	MOS	06-Dec-18	120		06-Dec-28		813 d	SERVICE LIFE LIMIT	
SN:02254	HRS	7976.3							
	AFL	6133							

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C / W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 26 - FIRE PROTECTION										
D2620007.S		NO. 1/LEFT/LOWER FIRE EXTINGUISHER, RIGHT SQUIB - SERVICE LIFE LIMIT							Service	ATA:26
PN:M30903859	MOS	06-Dec-18	120		06-Dec-28		813 d	SERVICE LIFE LIMIT		
SN:01619	HRS	7976.3								
	AFL	6133								
D2620007.S		NO. 2/RIGHT/UPPER FIRE EXTINGUISHER, LEFT SQUIB - SERVICE LIFE LIMIT							Service	ATA:26
PN:30903856	MOS	21-Aug-25	120		21-Aug-35		3262 d	SERVICE LIFE LIMIT		
SN:03401	HRS	9809.8								
	AFL	7471								
D2620007.S		NO. 2/RIGHT/UPPER FIRE EXTINGUISHER, RIGHT SQUIB - SERVICE LIFE LIMIT							Service	ATA:26
PN:30903859	MOS	21-Aug-25	120		21-Aug-35		3262 d	SERVICE LIFE LIMIT		
SN:02408	HRS	9809.8								
	AFL	7471								
D2620007.T		NO. 1/LEFT/LOWER FIRE EXTINGUISHER, LEFT SQUIB - TOTAL LIFE LIMIT							Service	ATA:26
	MOS	06-Dec-18	180		01-Jul-33		2481 d	LIFE LIMIT		
	HRS	7976.3								
	AFL	6133								
			Manufacture Date:: 01-Jul-18							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
D2620007.T		NO. 1/LEFT/LOWER FIRE EXTINGUISHER, RIGHT SQUIB - TOTAL LIFE LIMIT							Service	ATA:26
	MOS	06-Dec-18	180		01-Jul-33		2481 d	LIFE LIMIT		
	HRS	7976.3								
	AFL	6133								
			Manufacture Date:: 01-Jul-18							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
D2620007.T		NO. 2/RIGHT/UPPER FIRE EXTINGUISHER, LEFT SQUIB - TOTAL LIFE LIMIT							Service	ATA:26
	MOS	21-Aug-25	180		31-Mar-40		4946 d	LIFE LIMIT		
	HRS	9809.8								
	AFL	7471								
			Manufacture Date:: 31-Mar-25							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
---------	------	-------	----------	------------	----------------------------	-----------	-----------	-------------	----------

ATA 26 - FIRE PROTECTION

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

D2620007.T	NO. 2/RIGHT/UPPER FIRE EXTINGUISHER, RIGHT SQUIB - TOTAL LIFE LIMIT							Service	ATA:26
	MOS	21-Aug-25	180		31-May-40		5007 d	LIFE LIMIT	
	HRS	9809.8							
	AFL	7471							

Manufacture Date:: 31-May-25

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

J2620000 S	** ENGINE FIRE EXTINGUISHING SYSTEM FIRE SWITCH - PERFORM FUNCTIONAL TEST							Service	ATA:26
	MOS	09-Mar-01						AIRWORTHINESS	
	HRS	0	4800						
	AFL	0							

PKG:25

PROC. REF: AMM 26-21-00PROC. REF: AMM 26-21-00

O2610001	NO. 1 ENGINE HOT SECTION FIRE DETECTOR ELEMENT - PERFORM VISUAL INSPECTION							Service	ATA:26
	MOS	21-May-18							
	HRS	7855.7	3000		10855.7		754.3		
	AFL	6028							

PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00

O2610001	NO. 2 ENGINE HOT SECTION FIRE DETECTOR ELEMENT - PERFORM VISUAL INSPECTION							Service	ATA:26
	MOS	12-Aug-15							
	HRS	7535.1	3000		10535.1		433.7		
	AFL	5764							

PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00

Q2510003	COPILOT PORTABLE FIRE EXTINGUISHER - PERFORM ICC HYDROSTATIC TEST							Service	ATA:26
PN:A344	MOS	01-Feb-16	144		01-Feb-28		504 d		
SN:B10813738	HRS								
	AFL								

HydroCheck Date: : 01-Feb-16

PROC. REF: AMM 26-23-00PROC. REF: AMM 26-23-00

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 26 - FIRE PROTECTION									
Q2620006		NO. 1/LEFT/LOWER FIRE EXTINGUISHER BOTTLE - PERFORM ICC HYDROSTATIC TEST						Service	ATA:26
PN:33100021-1	MOS	31-May-23	60		31-May-28		624 d		
SN:59578B1	HRS								
	AFL								
			HydroCheck Date: : 31-May-23						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
Q2620006		NO. 2/RIGHT/UPPER FIRE EXTINGUISHER BOTTLE - PERFORM ICC HYDROSTATIC TEST						Service	ATA:26
PN:33100021-1	MOS	21-Aug-25	60		30-Jun-30		1384 d		
SN:72043B1	HRS	9809.8							
	AFL	7471							
			HydroCheck Date: : 30-Jun-25						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
T2620001 ^S		** FIREWALL SHUT-OFF VALVES - PERFORM OPERATIONAL CHECK						Service	ATA:26
	MOS	09-Mar-01	48					AIRWORTHINESS	
	HRS	0	1200						
	AFL	0							
									PKG:13
PROC. REF: AMM 26-21-00PROC. REF: AMM 26-21-00									
Y2610000 ^S		FIREWALL AND ACCESSORY COMPARTMENT FIRE DETECTOR ELEMENTS - PERFORM VISUAL INSPECTION						Service	ATA:26
	MOS	25-Jun-26	24						
	HRS	10023.1	600						
	AFL	7616							
									PKG:9
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
Y2620002 ^S		ENGINE FIRE EXTINGUISHER CONTAINERS - PERFORM VISUAL INSPECTION. CHECK CONTAINERS FOR CONDITION, CARTRIDGES AND CARTRIDGE WIRING FOR SECURITY AND CONDITION, CONTAINER PRESSURE GAUGE FOR PROPER PRESSURES, AND PLUMBING FOR SECURITY AND CONDITION.						Service	ATA:26
	MOS	25-Jun-26	12						
	HRS	10023.1	300						
	AFL	7616							
									PKG:2
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 26 - FIRE PROTECTION									
Y2620005 ^S		ENGINE FIRE EXTINGUISHING SYSTEM - PERFORM OPERATIONAL CHECK						Service	ATA:26
	MOS	25-Jun-26	96						
	HRS	10023.1	2400						
	AFL	7616							
PROC. REF: AMM 26-21-00PROC. REF: AMM 26-21-00									PKG:19
Y2620009 ^S		CABIN PORTABLE FIRE EXTINGUISHER - INSPECT PORTABLE HAND HELD FIRE EXTINGUISHERS FOR CONDITION AND DATE OF MANUFACTURE. CHECK OPERATING PRESSURE AND WEIGHT PER MAINTENANCE INSTRUCTIONS ON FIRE EXTINGUISHER BOTTLE.						Service	ATA:26
PN:C352	MOS	25-Jun-26	12						
SN:H-20651164	HRS	10023.1	300						
	AFL	7616							
									PKG:1
Y2620009 ^S		COPILOT PORTABLE FIRE EXTINGUISHER - INSPECT PORTABLE HAND HELD FIRE EXTINGUISHERS FOR CONDITION AND DATE OF MANUFACTURE. CHECK OPERATING PRESSURE AND WEIGHT PER MAINTENANCE INSTRUCTIONS ON FIRE EXTINGUISHER BOTTLE.						Service	ATA:26
PN:A344	MOS	25-Jun-26	12						
SN:B10813738	HRS	10023.1	300						
	AFL	7616							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:1
Y2620009 ^S		PILOT PORTABLE FIRE EXTINGUISHER - INSPECT PORTABLE HAND HELD FIRE EXTINGUISHERS FOR CONDITION AND DATE OF MANUFACTURE. CHECK OPERATING PRESSURE AND WEIGHT PER MAINTENANCE INSTRUCTIONS ON FIRE EXTINGUISHER BOTTLE.						Service	ATA:26
PN:A344T	MOS	25-Jun-26	12						
SN:UNKNOWN	HRS	10023.1	300						
	AFL	7616							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:1
Z2620021 ^S		NO. 1 ENGINE FIRE EXTINGUISHER CONTAINER PLUMBING - PERFORM DETAILED INSPECTION						Service	ATA:26
	MOS	25-Jun-26	12						
	HRS	10023.1	300						
	AFL	7616							
PROC. REF: AMM 26-21-00PROC. REF: AMM 26-21-00									PKG:2

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C / W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 26 - FIRE PROTECTION									
Z2620021	^S	NO. 2 ENGINE FIRE EXTINGUISHER CONTAINER PLUMBING - PERFORM DETAILED INSPECTION							Service ATA:26
	MOS	25-Jun-26	12						
	HRS	10023.1	300						
	AFL	7616							
PROC. REF: AMM 26-21-00PROC. REF: AMM 26-21-00									
									PKG:2

ATA 27 - FLIGHT CONTROLS

270301	TRIM SWITCH PANEL							Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-00-01PROC. REF: AMM 27-00-01									
271001	LEFT AILERON CONTROL SYSTEM CROSSOVER CABLE							Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-10-05PROC. REF: AMM 27-10-05									

271002	RIGHT AILERON CONTROL SYSTEM CROSSOVER CABLE							Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-10-05PROC. REF: AMM 27-10-05									

271003	LEFT AILERON CONTROL SYSTEM CABLE							Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-10-05PROC. REF: AMM 27-10-05									

271004	RIGHT AILERON CONTROL SYSTEM CABLE							Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-10-05PROC. REF: AMM 27-10-05									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
271005	AFT AILERON CONTROL SYSTEM CABLE							Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-10-05PROC. REF: AMM 27-10-05									
271045	LEFT INBOARD AILERON CONTROL CABLE							Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-10-05PROC. REF: AMM 27-10-05									
271046	RIGHT INBOARD AILERON CONTROL CABLE							Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-10-05PROC. REF: AMM 27-10-05									
271051	LEFT FORWARD OUTBOARD AILERON CONTROL CABLE							Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-10-05PROC. REF: AMM 27-10-05									
271052	RIGHT FORWARD OUTBOARD AILERON CONTROL CABLE							Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-10-05PROC. REF: AMM 27-10-05									
271053	LEFT AFT OUTBOARD AILERON CONTROL CABLE							Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-10-05PROC. REF: AMM 27-10-05									

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C / W
(M)-Manual Due
U-User Task
Ex-Excluded Task

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
271054	RIGHT AFT OUTBOARD AILERON CONTROL CABLE							Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-10-05PROC. REF: AMM 27-10-05									
271083	AILERON TRIM TAB ACTUATOR							Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-10-09PROC. REF: AMM 27-10-09									
271088	AILERON SPINDLE							Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	H/T	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-10-07PROC. REF: AMM 27-10-07									
271095	PILOT ANGLE OF ATTACK INDICATOR (AOA)							Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
271096	COPILOT ANGLE OF ATTACK INDICATOR (AOA)							Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
272001	FORWARD UPPER RUDDER CONTROL SYSTEM CABLE							Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-20-08PROC. REF: AMM 27-20-08									

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C / W
(M)-Manual Due
U-User Task
Ex-Excluded Task

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
272002	FORWARD LOWER RUDDER CONTROL SYSTEM CABLE							Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-20-08PROC. REF: AMM 27-20-08									
272003	LEFT AFT UPPER RUDDER CONTROL SYSTEM CABLE							Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-20-08PROC. REF: AMM 27-20-08									
272004	RIGHT AFT UPPER RUDDER CONTROL SYSTEM CABLE							Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-20-08PROC. REF: AMM 27-20-08									
272005	LEFT AFT LOWER RUDDER CONTROL SYSTEM CABLE							Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-20-08PROC. REF: AMM 27-20-08									
272006	RIGHT AFT LOWER RUDDER CONTROL SYSTEM CABLE							Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-20-08PROC. REF: AMM 27-20-08									
272021	RUDDER TRIM TAB ACTUATOR							Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-20-03PROC. REF: AMM 27-20-03									

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C / W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
272031	PILOT RUDDER PEDAL ADJUST ACTUATOR							Component	ATA:27
PN:6627208001-003 (4389596)	MOS/MSC	17-Feb-05	O/C						
SN:0437	HRS	3300.2							
	AFL	2515							
PROC. REF: AMM 27-20-05PROC. REF: AMM 27-20-05									
272032	COPILOT RUDDER PEDAL ADJUST ACTUATOR							Component	ATA:27
PN:6627208001-003 (4389596)	MOS/MSC	17-Feb-05	O/C						
SN:0431	HRS	3300.2							
	AFL	2515							
PROC. REF: AMM 27-20-05PROC. REF: AMM 27-20-05									
273001	PILOT FORWARD ELEVATOR CONTROL SYSTEM CABLE							Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-30-05PROC. REF: AMM 27-30-05									
273002	COPILOT FORWARD ELEVATOR CONTROL SYSTEM CABLE							Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-30-05PROC. REF: AMM 27-30-05									
273003	LEFT AFT UPPER ELEVATOR CONTROL SYSTEM CABLE							Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-30-05PROC. REF: AMM 27-30-05									
273004	RIGHT AFT UPPER ELEVATOR CONTROL SYSTEM CABLE							Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-30-05PROC. REF: AMM 27-30-05									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 10101.4
 AFL: 7674
 As Of: 14-Sep-2026
 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
273005	LEFT AFT LOWER ELEVATOR CONTROL SYSTEM CABLE							Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-30-05PROC. REF: AMM 27-30-05									
273006	RIGHT AFT LOWER ELEVATOR CONTROL SYSTEM CABLE							Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-30-05PROC. REF: AMM 27-30-05									
273015	LEFT ANGLE OF ATTACK VANE (AOA)							Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-31-04PROC. REF: AMM 27-31-04									
273016	RIGHT ANGLE OF ATTACK VANE (AOA)							Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-31-04PROC. REF: AMM 27-31-04									
273022	LEFT ANGLE OF ATTACK TRANSMITTER (AOA)							Component	ATA:27
PN:C-38817-1	MOS/MSC	11-Dec-23	O/C						
SN:1333	HRS	9373.9							
	AFL	7179							
PROC. REF: AMM 27-31-01PROC. REF: AMM 27-31-01									
273023	RIGHT ANGLE OF ATTACK TRANSMITTER (AOA)							Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-31-01PROC. REF: AMM 27-31-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 10101.4
 AFL: 7674
 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
273051	ELEVATOR DISCONNECT ACTUATOR							Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-30-09PROC. REF: AMM 27-30-09									
273063	PILOT STICK SHAKER							Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-31-03PROC. REF: AMM 27-31-03									
273064	COPILOT STICK SHAKER							Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-31-03PROC. REF: AMM 27-31-03									
273087	STALL WARNING COMPUTER							Component	ATA:27
PN:C-38806-2	MOS/MSC	14-Feb-24	O/C						
SN:132	HRS	9467.2							
	AFL	7246							
PROC. REF: AMM 27-31-02PROC. REF: AMM 27-31-02									
273201	ELEVATOR DISCONNECT CURRENT LIMITER							Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-30-13PROC. REF: AMM 27-30-13									
273420	ELEVATOR OVERRIDE ACTUATOR							Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-30-14PROC. REF: AMM 27-30-14									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
274011	HORIZONTAL STABILIZER ACTUATOR							Component	ATA:27
PN:6627401000-009	MOS/MSC	25-Jun-26	O/C						
SN:B851	HRS	10023.1		TSO 993.7					
	AFL	7616							
PROC. REF: AMM 27-40-02PROC. REF: AMM 27-40-02									
274031	TRIM-IN-MOTION DETECTOR							Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-41-01PROC. REF: AMM 27-41-01									
274041	FORWARD INTERFACE UNIT							Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-40-04PROC. REF: AMM 27-40-04									
274051	HORIZONTAL STABILIZER ACTUATOR CONTROL BOX							Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-40-02, AMM 27-40-03PROC. REF: AMM 27-40-02, AMM 27-40-03									
275020	LEFT OUTOBARD FLAP ACTUATOR							Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-50-06PROC. REF: AMM 27-50-06									
275021	LEFT INBOARD FLAP ACTUATOR							Component	ATA:27
PN:6627503000-009	MOS/MSC	18-Jul-07	O/C						
SN:1743	HRS	5671.55							
	AFL	4333							
PROC. REF: AMM 27-50-06PROC. REF: AMM 27-50-06									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
275022	RIGHT INBOARD FLAP ACTUATOR							Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-50-06PROC. REF: AMM 27-50-06									
275023	RIGHT OUTBOARD FLAP ACTUATOR							Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-50-06PROC. REF: AMM 27-50-06									
275057	FLAP DRIVE POWER UNIT							Component	ATA:27
PN:6627503000-029	MOS/MSC	25-Feb-11	O/C						
SN:1461	HRS	6519.3							
	AFL	4991							
PROC. REF: AMM 27-50-08PROC. REF: AMM 27-50-08									
275058	FLAP CONTROL UNIT							Component	ATA:27
PN:C144486-3-003	MOS/MSC	05-Jan-20	O/C						
SN:1343	HRS	8209.7							
	AFL	6328							
PROC. REF: AMM 27-50-05PROC. REF: AMM 27-50-05									
275069	FLAP POSITION INDICATOR							Component	ATA:27
PN:C145159-1	MOS/MSC	09-Oct-23	O/C						
SN:135	HRS	9332.6							
	AFL	7149							
PROC. REF: AMM 27-50-07PROC. REF: AMM 27-50-07									
275080	FLAP CONTROL MODULE							Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-50-02PROC. REF: AMM 27-50-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
275081	LEFT FLAP DRIVE ROTARY VARIABLE DIFFERENTIAL TRANSFORMER							Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-50-03PROC. REF: AMM 27-50-03									
275082	RIGHT FLAP DRIVE ROTARY VARIABLE DIFFERENTIAL TRANSFORMER							Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-50-03PROC. REF: AMM 27-50-03									
276001	LEFT SPOILER ACTUATOR							Component	ATA:27
PN:6627602001-007	MOS/MSC	15-Jun-06	O/C						
SN:DWA392-00	HRS	4570.25							
	AFL	3497							
PROC. REF: AMM 27-60-04PROC. REF: AMM 27-60-04									
276002	RIGHT SPOILER ACTUATOR							Component	ATA:27
PN:6627602001-007	MOS/MSC	15-Jun-06	O/C						
SN:DAW398-00	HRS	4570.25							
	AFL	3497							
PROC. REF: AMM 27-60-04PROC. REF: AMM 27-60-04									
276005	SPOILER CONTROL MODULE							Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-60-03PROC. REF: AMM 27-60-03									
276010	SPOILERON CONTROLLER RESISTOR BOX							Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-60-10PROC. REF: AMM 27-60-10									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
276013	SPOILER SHUTOFF VALVE							Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-60-07PROC. REF: AMM 27-60-07									
276020	SPOILER LOW PRESSURE SWITCH							Component	ATA:27
PN:6629101004-003	MOS/MSC	11-Jun-16	O/C						
SN:535	HRS	7630.1							
	AFL	5823							
PROC. REF: AMM 27-60-08PROC. REF: AMM 27-60-08									
276031	LEFT SPOILER ROTARY VARIABLE DIFFERENTIAL TRANSFORMER							Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-60-05PROC. REF: AMM 27-60-05									
276032	RIGHT SPOILER ROTARY VARIABLE DIFFERENTIAL TRANSFORMER							Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-60-05PROC. REF: AMM 27-60-05									
276073	SPOILERON COMPUTER							Component	ATA:27
PN:6627608500-007	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:00227	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-60-02PROC. REF: AMM 27-60-02									
276076	CONTROL WHEEL ROTARY VARIABLE DIFFERENTIAL TRANSFORMER							Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-60-06PROC. REF: AMM 27-60-06									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
5-19-01-W2750055	* FLAP ACTUATOR JOINT (P/N 145673-1) (IRN W2750055) REPLACEMENT							Component	ATA:27
PN:159174-1	MOS/MSC	05-Dec-19	N/A	TSN 4372				NOT APPLICABLE	
SN:UNKNOWN	HRS	8177.8							
	AFL	6304							
A2711001 ^S	** AILERON TRIM TAB CONTROL SYSTEM - PERFORM OPERATIONAL CHECK							Service	ATA:27
	MOS	25-Jun-26	24					AIRWORTHINESS	
	HRS	10023.1	600						
	AFL	7616							
PROC. REF: AMM 27-10-04PROC. REF: AMM 27-10-04									PKG:7
A2721001 ^S	** RUDDER TRIM SYSTEM - PERFORM OPERATIONAL CHECK							Service	ATA:27
	MOS	25-Jun-26	24					AIRWORTHINESS	
	HRS	10023.1	600						
	AFL	7616							
PROC. REF: AMM 27-20-00PROC. REF: AMM 27-20-00									PKG:7
A2731002 ^S	** ELEVATOR DISCONNECT SYSTEM - PERFORM OPERATIONAL CHECK							Service	ATA:27
	MOS	25-Jun-26	24					AIRWORTHINESS	
	HRS	10023.1	600						
	AFL	7616							
PROC. REF: AMM 27-30-00PROC. REF: AMM 27-30-00									PKG:8
A2760001 ^S	** SPOILER ACTUATOR CHECK VALVE - PERFORM OPERATIONAL CHECK							Service	ATA:27
	MOS	25-Jun-26	24					AIRWORTHINESS	
	HRS	10023.1	600						
	AFL	7616							
PROC. REF: AMM 27-60-04PROC. REF: AMM 27-60-04									PKG:10

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
A2760002	^S	** SPOILER SYSTEM - PERFORM SPOILER AUTHORITY WITH FLAPS CHECK						Service	ATA:27
	MOS	25-Jun-26	24					AIRWORTHINESS	
	HRS	10023.1	600						
	AFL	7616							
PROC. REF: AMM 27-60-00PROC. REF: AMM 27-60-00									
PKG:10									
AA2700000	^S	AILERON CONTROL CABLE SYSTEM - WITH COCKPIT AND CABIN FLOORBOARDS REMOVED, PERFORM VISUAL INSPECTION OF CABLES						Service	ATA:27
	MOS	25-Jun-26	24						
	HRS	10023.1	600						
	AFL	7616							
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00									
PKG:7									
AA2700001	^S	RUDDER CONTROL CABLE SYSTEM - WITH COCKPIT AND CABIN FLOORBOARDS REMOVED, PERFORM VISUAL INSPECTION OF CABLES						Service	ATA:27
	MOS	25-Jun-26	24						
	HRS	10023.1	600						
	AFL	7616							
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00									
PKG:7									
AA2700002	^S	ELEVATOR CONTROL CABLE SYSTEM - WITH COCKPIT AND CABIN FLOORBOARDS REMOVED, PERFORM VISUAL INSPECTION OF CABLES						Service	ATA:27
	MOS	25-Jun-26	24						
	HRS	10023.1	600						
	AFL	7616							
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00									
PKG:7									
AA2760021		LEFT SPOILER HYDRAULIC SYSTEM PRESSURE SWIVEL - REPLACE						Service	ATA:27
	MOS	22-Jun-23							
	HRS	9258.5	1200		10458.5		357.1		
	AFL	7100							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
AA2760021		LEFT SPOILER HYDRAULIC SYSTEM RETURN SWIVEL - REPLACE						Service	ATA:27
	MOS	22-Jun-23							
	HRS	9258.5	1200		10458.5		357.1		
	AFL	7100							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
AA2760021		RIGHT SPOILER HYDRAULIC SYSTEM PRESSURE SWIVEL - REPLACE						Service	ATA:27
	MOS	22-Jun-23							
	HRS	9258.5	1200		10458.5		357.1		
	AFL	7100							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
AA2760021		RIGHT SPOILER HYDRAULIC SYSTEM RETURN SWIVEL - REPLACE						Service	ATA:27
	MOS	22-Jun-23							
	HRS	9258.5	1200		10458.5		357.1		
	AFL	7100							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
AD2760085 ^S		SPOILER LEVER ARM - PERFORM DETAILED VISUAL INSPECTION TO ENSURE SPOILER LEVER ARM IS PROPERLY SEATED AND SECURED ON SPOILER RVDT SHAFT						Service	ATA:27
	MOS	25-Jun-26	24						
	HRS	10023.1	600						
	AFL	7616							
PROC. REF: AMM 27-60-05PROC. REF: AMM 27-60-05									
AE2710049		* AILERON LEADING EDGE (INTERNAL) - PERFORM BORESCOPE INSPECTION						Service	ATA:27
	MOS	25-Jun-26	72		25-Jun-32		2110 d	AIRWORTHINESS	
	HRS	10023.1							
	AFL	7616							
PROC. REF: AMM 27-10-02PROC. REF: AMM 27-10-02									

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C / W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
AE2730037 ^S		PERFORM DETAILED VISUAL INSPECTION OF THE ELEVATOR UP/DOWN SPRING ASSEMBLY, YOKE ASSEMBLY AND ASSOCIATED PARTS FOR FREE MOVEMENT, LOOSE FASTENERS AND SECURITY OF LOCKING DEVICES						Service	ATA:27
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:14
D2740003		** HORIZONTAL STABILIZER ACTUATOR SECONDARY TRIM - PERFORM FUNCTIONAL TEST						Service	ATA:27
PN:6627401000-009	MOS	25-Jun-26						AIRWORTHINESS	
SN:B851	HRS	10023.1	600		10623.1		521.7		
	AFL	7616							
PROC. REF: AMM 27-40-02PROC. REF: AMM 27-40-02									
D2740004		** HORIZONTAL STABILIZER ACTUATOR PRIMARY TRIM - PERFORM FUNCTIONAL TEST						Service	ATA:27
PN:6627401000-009	MOS	25-Jun-26						AIRWORTHINESS	
SN:B851	HRS	10023.1	600		10623.1		521.7		
	AFL	7616							
PROC. REF: AMM 27-40-02PROC. REF: AMM 27-40-02									
G2710003 ^S		AILERON CONTROL SYSTEM CABLES (LOCATED IN WING) - PERFORM CABLE TENSION CHECK						Service	ATA:27
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 27-10-00PROC. REF: AMM 27-10-00									PKG:16
G2710004 ^S		AILERON CONTROL SYSTEM CABLES (LOCATED IN FUSELAGE) - PERFORM CABLE TENSION CHECK						Service	ATA:27
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 27-10-00PROC. REF: AMM 27-10-00									PKG:13

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
G2720003 ^S		RUDDER CONTROL CABLES - PERFORM TENSION CHECK						Service	ATA:27
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 27-20-00PROC. REF: AMM 27-20-00									PKG:14
G2720004 ^S		RUDDER PEDALS, PEDAL PUSHRODS, ADJUSTMENT ACTUATOR, AND SECTORS - PERFORM VISUAL INSPECTION. CHECK DURING FULL TRAVEL OF RUDDER.						Service	ATA:27
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:13
G2730003 ^S		ELEVATOR CONTROL CABLES - PERFORM TENSION CHECK						Service	ATA:27
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 27-30-00PROC. REF: AMM 27-30-00									PKG:14
K2700007		* AILERON CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED VISUAL INSPECTION						Service	ATA:27
	MOS	22-Jun-23						AIRWORTHINESS	
	HRS	9258.5	4800		14058.5		3957.1		
	AFL	7100							
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00									
K2700008		* ELEVATOR CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED VISUAL INSPECTION						Service	ATA:27
	MOS	22-Jun-23						AIRWORTHINESS	
	HRS	9258.5	4800		14058.5		3957.1		
	AFL	7100							
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
K2700009	* RUDDER CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED VISUAL INSPECTION							Service	ATA:27
	MOS	22-Jun-23						AIRWORTHINESS	
	HRS	9258.5	4800		14058.5		3957.1		
	AFL	7100							
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00									
K2700010	* ELEVATOR CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED VISUAL INSPECTION							Service	ATA:27
	MOS	22-Jun-23						AIRWORTHINESS	
	HRS	9258.5	4800		14058.5		3957.1		
	AFL	7100							
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00									
K2700012	* RUDDER CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED VISUAL INSPECTION							Service	ATA:27
	MOS	22-Jun-23						AIRWORTHINESS	
	HRS	9258.5	4800		14058.5		3957.1		
	AFL	7100							
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00									
K2700014	* AILERON CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED VISUAL INSPECTION							Service	ATA:27
	MOS	22-Jun-23						AIRWORTHINESS	
	HRS	9258.5	4800		14058.5		3957.1		
	AFL	7100							
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00									
N2720030	RUDDER TORQUE TUBE AND SPINDLE - PERFORM DETAILED VISUAL INSPECTION							Service	ATA:27
	MOS	21-Aug-25	72		21-Aug-31		1801 d	AIRWORTHINESS	
	HRS	9809.8							
	AFL	7471							
PROC. REF: AMM 27-20-01PROC. REF: AMM 27-20-01									
N2740023	* HORIZONTAL STABILIZER ACTUATOR ACME SCREW - REPLACE							Service	ATA:27
PN:6627401000-009	MOS/MS	25-Jun-26	N/A						
SN:B851	HRS	10023.1							
	AFL	7616							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
N2740024	* HORIZONTAL STABILIZER ACTUATOR ACME NUT - REPLACE								Service ATA:27
PN:6627401000-009	MOS/MSC	25-Jun-26	N/A						
SN:B851	HRS	10023.1							
	AFL	7616							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
N2740025	* HORIZONTAL STABILIZER ACTUATOR - PERFORM DETAILED STRUCTURAL INSPECTION								Service ATA:27
PN:6627401000-009	MOS/MSC	25-Jun-26	N/A						
SN:B851	HRS	10023.1							
	AFL	7616							
P2740032	* HORIZONTAL STABILIZER ACTUATOR - PERFORM INSPECTION								Service ATA:27
PN:6627401000-009	MOS	25-Jun-26						AIRWORTHINESS	
SN:B851	HRS	10023.1	1200		11223.1		1121.7		
	AFL	7616							
P2740033	* HORIZONTAL STABILIZER ACTUATOR - PERFORM DETAILED STRUCTURAL INSPECTION								Service ATA:27
PN:6627401000-009	MOS	25-Jun-26							
SN:B851	HRS	10023.1	2400		12423.1		2321.7		
	AFL	7616							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
R2710041	* AILERON SPINDLE - REPLACE								Service ATA:27
	MOS	30-Mar-21	120		30-Mar-31		1657 d	LIFE LIMIT	
	HRS	8414.4							
	AFL	6463							
PROC. REF: AMM 27-10-07PROC. REF: AMM 27-10-07									
S2750057	* FLAP ACTUATOR BALLNUT SLEEVE - PERFORM FLUORESCENT PENETRANT INSPECTION								Service ATA:27
	MOS/MSC	05-Dec-19	N/A						
	HRS	8177.8							
	AFL	6304							
PROC. REF: NDT PART 8/27-50-01, NDT PART 8/27-50-02PROC. REF: NDT PART 8/27-50-01, NDT PART 8/27-50-02									

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
T2740002	* HORIZONTAL STABILIZER ACTUATOR - PERFORM INSPECTION								Service ATA:27
PN:6627401000-009	MOS/MSC	25-Jun-26	N/A						
SN:B851	HRS	10023.1							
	AFL	7616							
PROC. REF: AMM 27-40-02PROC. REF: AMM 27-40-02									
V2712000 ^S	** ROLL DISCONNECT SWITCHES - PERFORM OPERATIONAL CHECK								Service ATA:27
	MOS	25-Jun-26	24					AIRWORTHINESS	
	HRS	10023.1	600						
	AFL	7616							
PROC. REF: AMM 27-60-09PROC. REF: AMM 27-60-09									
W2731001 ^S	** PITCH TRIM - PERFORM OPERATIONAL CHECK OF ELEVATOR OVERRIDE ACTUATOR								Service ATA:27
	MOS	25-Jun-26	24					AIRWORTHINESS	
	HRS	10023.1	600						
	AFL	7616							
PROC. REF: AMM 27-30-14PROC. REF: AMM 27-30-14									
W2750055	* LEFT INBOARD FLAP ACTUATOR JOINT - REPLACE								Service ATA:27
	MOS/MSC	05-Dec-19	N/A						
	HRS	8177.8							
	AFL	6304							
W2750055	* LEFT OUTBOARD FLAP ACTUATOR JOINT - REPLACE								Service ATA:27
	MOS/MSC	05-Dec-19	N/A						
	HRS	8177.8							
	AFL	6304							
W2750055	* RIGHT INBOARD FLAP ACTUATOR JOINT - REPLACE								Service ATA:27
	MOS/MSC	05-Dec-19	N/A						
	HRS	8177.8							
	AFL	6304							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
W2750055	* RIGHT OUTBOARD FLAP ACTUATOR JOINT - REPLACE							Service	ATA:27
	MOS/MSC	05-Dec-19	N/A						
	HRS	8177.8							
	AFL	6304							
W2750056	* LEFT INBOARD FLAP ACTUATOR JOINT - PERFORM DETAILED VISUAL INSPECTION. APPLY CORROSION PREVENTIVE COMPOUND (CPC) TO JOINT.							Service	ATA:27
	MOS/MSC	05-Dec-19	N/A						
	HRS	8177.8							
	AFL	6304							
PROC. REF: AMM 12-21-03, AMM 27-50-06PROC. REF: AMM 12-21-03, AMM 27-50-06									
W2750056	* LEFT OUTBOARD FLAP ACTUATOR JOINT - PERFORM DETAILED VISUAL INSPECTION. APPLY CORROSION PREVENTIVE COMPOUND (CPC) TO JOINT.							Service	ATA:27
	MOS/MSC	05-Dec-19	N/A						
	HRS	8177.8							
	AFL	6304							
PROC. REF: AMM 12-21-03, AMM 27-50-06PROC. REF: AMM 12-21-03, AMM 27-50-06									
W2750056	* RIGHT INBOARD FLAP ACTUATOR JOINT - PERFORM DETAILED VISUAL INSPECTION. APPLY CORROSION PREVENTIVE COMPOUND (CPC) TO JOINT.							Service	ATA:27
	MOS/MSC	05-Dec-19	N/A						
	HRS	8177.8							
	AFL	6304							
PROC. REF: AMM 12-21-03, AMM 27-50-06PROC. REF: AMM 12-21-03, AMM 27-50-06									
W2750056	* RIGHT OUTBOARD FLAP ACTUATOR JOINT - PERFORM DETAILED VISUAL INSPECTION. APPLY CORROSION PREVENTIVE COMPOUND (CPC) TO JOINT.							Service	ATA:27
	MOS/MSC	05-Dec-19	N/A						
	HRS	8177.8							
	AFL	6304							
PROC. REF: AMM 12-21-03, AMM 27-50-06PROC. REF: AMM 12-21-03, AMM 27-50-06									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
Y2700003	^S	AILERON CONTROL CABLE SYSTEM - PERFORM VISUAL INSPECTION OF CABLES WITHIN WING						Service	ATA:27
	MOS	25-Jun-26	24						
	HRS	10023.1	600						
	AFL	7616							
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00									PKG:10
Y2700004	^S	RUDDER CONTROL CABLE SYSTEM - PERFORM VISUAL INSPECTION OF ACCESSIBLE UPPER AND LOWER CABLES						Service	ATA:27
	MOS	25-Jun-26	24						
	HRS	10023.1	600						
	AFL	7616							
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00									PKG:8
Y2700005	^S	ELEVATOR CONTROL CABLE SYSTEM - PERFORM VISUAL INSPECTION OF ACCESSIBLE UPPER AND LOWER CABLES						Service	ATA:27
	MOS	25-Jun-26	24						
	HRS	10023.1	600						
	AFL	7616							
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00									PKG:8
Y2700006	^S	RUDDER AND ELEVATOR CONTROL CABLES AND ASSOCIATED PULLEYS, LOCATED IN AFT PRESSURE BULKHEAD SUPPORT CHANNEL - PERFORM VISUAL INSPECTION						Service	ATA:27
	MOS	25-Jun-26	24						
	HRS	10023.1	600						
	AFL	7616							
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00									PKG:9
Y2710000	^S	AILERONS, AILERON TRIM TAB AND VISIBLE PORTION OF RODS - PERFORM VISUAL INSPECTION						Service	ATA:27
	MOS	25-Jun-26	24						
	HRS	10023.1	600						
	AFL	7616							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:10

? - Insufficient Information
S - Suppressed Requirement
* - Estimated Due(New Requirement)
(EFF) - Effective C / W
(M) - Manual Due
U - User Task
Ex - Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
Y2710001	^S	AILERON BALANCE WEIGHT INSTALLATION AND SUPPORTING STRUCTURE - PERFORM VISUAL INSPECTION						Service	ATA:27
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:16
Y2710002	^S	AILERON CONTROL SYSTEM - PERFORM OPERATIONAL CHECK						Service	ATA:27
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 27-10-00PROC. REF: AMM 27-10-00									PKG:16
Y2710048	^S	AILERON TRIM TAB INSTALLATION - PERFORM FREE PLAY CHECK						Service	ATA:27
	MOS	25-Jun-26	96						
	HRS	10023.1	2400						
	AFL	7616							
PROC. REF: AMM 27-10-04PROC. REF: AMM 27-10-04									PKG:22
Y2720000	^S	RUDDER - PERFORM VISUAL INSPECTION						Service	ATA:27
	MOS	25-Jun-26	12						
	HRS	10023.1	300						
	AFL	7616							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:2
Y2720001	^S	RUDDER BALANCE WEIGHT INSTALLATION AND SUPPORTING STRUCTURE - PERFORM VISUAL INSPECTION						Service	ATA:27
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:14

? - Insufficient Information
S - Suppressed Requirement
* - Estimated Due(New Requirement)
(EFF) - Effective C / W
(M) - Manual Due
U - User Task
Ex - Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
Y2720002	^S	RUDDER CONTROL SYSTEM - PERFORM OPERATIONAL CHECK							Service ATA:27
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 27-20-00PROC. REF: AMM 27-20-00									PKG:14
Y2721000	^S	RUDDER TRIM TAB AND VISIBLE RODS - PERFORM VISUAL INSPECTION							Service ATA:27
	MOS	25-Jun-26	12						
	HRS	10023.1	300						
	AFL	7616							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:2
Y2730000	^S	CONTROL COLUMNS - PERFORM VISUAL INSPECTION. PAY PARTICULAR ATTENTION TO AILERON CONTROL WHEEL CABLE DRUM AND BOTTOM CROSSOVER PULLEYS.							Service ATA:27
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:13
Y2730001	^S	ELEVATORS - PERFORM VISUAL INSPECTION							Service ATA:27
	MOS	25-Jun-26	12						
	HRS	10023.1	300						
	AFL	7616							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:2
Y2730002	^S	ELEVATOR CONTROL SYSTEM - PERFORM OPERATIONAL CHECK							Service ATA:27
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 27-30-00PROC. REF: AMM 27-30-00									PKG:14

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C / W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
Y2730004	^S	CONTROL COLUMNS - PERFORM INSPECTION. INSPECT CABLE, PULLEYS, BEARINGS, AND ELECTRICAL WIRING						Service	ATA:27
	MOS	25-Jun-26	96						
	HRS	10023.1	2400						
	AFL	7616							
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00									PKG:19
Y2730007	^S	AFT ELEVATOR DISCONNECT - PERFORM DETAILED VISUAL INSPECTION						Service	ATA:27
	MOS	25-Jun-26	96						
	HRS	10023.1	2400						
	AFL	7616							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:20
Y2740000	^S	PRIMARY PITCH TRIM SYSTEM - PERFORM OPERATIONAL CHECK						Service	ATA:27
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 27-40-00PROC. REF: AMM 27-40-00									PKG:14
Y2740001	^S	SECONDARY PITCH TRIM SYSTEM - PERFORM OPERATIONAL CHECK						Service	ATA:27
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 27-40-00PROC. REF: AMM 27-40-00									PKG:14
Y2750000	^S	FLAP DRIVE INSTALLATION - PERFORM VISUAL INSPECTION WITH FLAPS LOWERED						Service	ATA:27
	MOS	25-Jun-26	24						
	HRS	10023.1	600						
	AFL	7616							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:10

? - Insufficient Information
S - Suppressed Requirement
* - Estimated Due(New Requirement)
(EFF) - Effective C / W
(M) - Manual Due
U - User Task
Ex - Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
Y2750001 ^S		FLAPS - PERFORM VISUAL INSPECTION						Service	ATA:27
	MOS	25-Jun-26	12						
	HRS	10023.1	300						
	AFL	7616							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
Y2750053 ^S		FLAP DRIVE ACTUATORS - PERFORM A VISUAL INSPECTION OF THE ACTUATOR ATTACHMENT, PAYING PARTICULAR ATTENTION TO THE GIMBAL PIN RETAINING RINGS						Service	ATA:27
	MOS	25-Jun-26	24						
	HRS	10023.1	600						
	AFL	7616							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
Y2760000 ^S		SPOILER AND SPOILER ACTUATOR - PERFORM VISUAL INSPECTION WITH FLAPS LOWERED AND ACCESS PANELS OPENED						Service	ATA:27
	MOS	25-Jun-26	24						
	HRS	10023.1	600						
	AFL	7616							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
ATA 28 - FUEL									
281001		LEFT NO. 1 FUEL EJECTOR SCAVENGE PUMP						Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01									
281002		RIGHT NO. 1 FUEL EJECTOR SCAVENGE PUMP						Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01									

? - Insufficient Information
S - Suppressed Requirement
* - Estimated Due(New Requirement)
(EFF) - Effective C / W
(M) - Manual Due
U - User Task
Ex - Excluded Task

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
281003	LEFT NO. 2 FUEL EJECTOR SCAVENGE PUMP							Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01									
281004	RIGHT NO. 2 FUEL EJECTOR SCAVENGE PUMP							Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01									
281005	LEFT NO. 3 FUEL EJECTOR SCAVENGE PUMP							Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01									
281006	RIGHT NO. 3 FUEL EJECTOR SCAVENGE PUMP							Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01									
281007	LEFT NO. 4 FUEL EJECTOR SCAVENGE PUMP							Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01									
281008	RIGHT NO. 4 FUEL EJECTOR SCAVENGE PUMP							Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01									

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C / W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 10101.4
 AFL: 7674
 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
281009	LEFT NO. 5 FUEL EJECTOR SCAVENGE PUMP							Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01									
281010	RIGHT NO. 5 FUEL EJECTOR SCAVENGE PUMP							Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01									
281031	FUSELAGE FUEL CELL							Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-10-02PROC. REF: AMM 28-10-02									
281051	FUEL CROSSFLOW SHUTOFF VALVE							Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-12-02PROC. REF: AMM 28-12-02									
281401	SURGE TANK FLOAT VALVE							Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-11-02PROC. REF: AMM 28-11-02									
281501	LEFT FLEX FUEL HOSE ASSY							Component	ATA:28
PN:244224151	MOS/MSC	26-May-05	O/C						
SN:F16806-04	HRS	3623.3							
WC#: 28.015	AFL	2739							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
281502	RIGHT FLEX FUEL HOSE ASSY							Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.015	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
281521	LEFT FUEL TRANSFER CHECK VALVE							Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-12-03PROC. REF: AMM 28-12-03									
281522	RIGHT FUEL TRANSFER CHECK VALVE							Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-12-03PROC. REF: AMM 28-12-03									
282001	LEFT FUEL SHUTOFF VALVE							Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-20-06PROC. REF: AMM 28-20-06									
282003	RIGHT FUEL SHUTOFF VALVE							Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-20-06PROC. REF: AMM 28-20-06									
282011	SHUTOFF - REFUEL VALVE							Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-20-10PROC. REF: AMM 28-20-10									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 10101.4
 AFL: 7674
 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
282031	LEFT NO. 1 FUEL SUPPLY CHECK VALVE							Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-20-03PROC. REF: AMM 28-20-03									
282032	LEFT NO. 2 FUEL SUPPLY CHECK VALVE							Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-20-03PROC. REF: AMM 28-20-03									
282033	RIGHT NO. 1 FUEL SUPPLY CHECK VALVE							Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-20-03PROC. REF: AMM 28-20-03									
282034	RIGHT NO. 2 FUEL SUPPLY CHECK VALVE							Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-20-03PROC. REF: AMM 28-20-03									
282037	RIGHT FUEL SUPPLY SHUT-OFF VALVE ASSEMBLY							Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-20-06PROC. REF: AMM 28-20-06									
282038	LEFT FUEL SUPPLY SHUT-OFF VALVE ASSEMBLY							Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-20-06PROC. REF: AMM 28-20-06									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
282041	REFUELING CONTROL PANEL							Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-20-14PROC. REF: AMM 28-20-14									
282051	LEFT MOTIVE FLOW CHECK VALVE							Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-20-05PROC. REF: AMM 28-20-05									
282052	RIGHT MOTIVE FLOW CHECK VALVE							Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-20-05PROC. REF: AMM 28-20-05									
282063	PRE-CHECK SINGLE POINT PRESSURE REFUELING (SPPR) VALVE							Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-20-12PROC. REF: AMM 28-20-12									
282064	PILOT OPERATED SINGLE POINT PRESSURE REFUELING (SPPR) VALVE							Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-20-11PROC. REF: AMM 28-20-11									
282075	LEFT MAIN FUEL EJECTOR PUMP ASSEMBLY							Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-20-01PROC. REF: AMM 28-20-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
282076	RIGHT MAIN FUEL EJECTOR PUMP ASSEMBLY							Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-20-01PROC. REF: AMM 28-20-01									
282087	LEFT STANDBY FUEL PUMP							Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-20-02PROC. REF: AMM 28-20-02									
282088	RIGHT STANDBY FUEL PUMP							Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-20-02PROC. REF: AMM 28-20-02									
282601	DEFUEL SHUTOFF VALVE							Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-20-07PROC. REF: AMM 28-20-07									
282602	REFUEL CHECK VALVE							Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-20-09PROC. REF: AMM 28-20-09									
282603	SINGLE POINT PRESSURE REFUELING (SPPR) ADAPTER							Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
282815	APU FUEL SHUTOFF VALVE							Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-20-04PROC. REF: AMM 28-20-04									
282829	APU FUEL LINE							Component	ATA:28
PN:PN	MOS/MSC	EFF	N/A	TSN 0					
SN:UNKNOWN	HRS	EFF		TSN 0					
	AFL			TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
2840001 EMP	* DUAL FUEL FLOW CONVERTER (DFFC) - PERFORM ACCEPTANCE TEST AND LOW TEMPERATURE SCREENING							Service	ATA:28
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
284001	C1 FUEL PROBE							Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05									
284002	C2 FUEL PROBE							Component	ATA:28
PN:10552T03Y00	MOS/MSC	22-May-06	O/C						
SN:0117	HRS	4507.7							
	AFL	3441							
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05									
284003	C3 FUEL PROBE							Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05									

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C / W
(M)-Manual Due
U-User Task
Ex-Excluded Task

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
284004	C4 FUEL PROBE							Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05									
284005	C5 FUEL PROBE							Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05									
284006	C6 FUEL PROBE							Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05									
284008	C7 FUEL PROBE							Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05									
284009	C8 FUEL PROBE							Component	ATA:28
PN:10552T03Y00	MOS/MSC	22-May-06	O/C						
SN:7262	HRS	4507.7							
	AFL	3441							
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05									
284010	C9 FUEL PROBE							Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
284011	C10 FUEL PROBE							Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05									
284012	C11 FUEL PROBE							Component	ATA:28
PN:6628408000-009	MOS/MSC	04-Jul-07	O/C						
SN:B408	HRS	5595.25							
	AFL	4268							
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05									
284013	C12 FUEL PROBE							Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05									
284014	C13 FUEL PROBE							Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05									
284015	C14 FUEL PROBE							Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05									
284016	C15 FUEL PROBE							Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05									

? - Insufficient Information
S - Suppressed Requirement
* - Estimated Due(New Requirement)
(EFF) - Effective C / W
(M) - Manual Due
U - User Task
Ex - Excluded Task

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
284017	C16 FUEL PROBE							Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05									
284033	FUSELAGE FUEL PROBE							Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05									
284035	NO. 1 LOW PRESSURE FUEL SWITCH							Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-40-01PROC. REF: AMM 28-40-01									
284036	NO. 2 LOW PRESSURE FUEL SWITCH							Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-40-01PROC. REF: AMM 28-40-01									
284041	LEFT FUEL FLOAT SWITCH							Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-40-02PROC. REF: AMM 28-40-02									
284042	RIGHT FUEL FLOAT SWITCH							Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-40-02PROC. REF: AMM 28-40-02									

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C / W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
284045	FUEL QUANTITY SIGNAL CONDITIONER							Component	ATA:28
PN:6628408000-023	MOS/MSC	04-Jun-05	O/C						
SN:B0672	HRS	3648.97							
	AFL	2757							
PROC. REF: AMM 28-40-04PROC. REF: AMM 28-40-04									
284047	LEFT LOW LEVEL FUEL SENSOR							Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-40-03PROC. REF: AMM 28-40-03									
284048	RIGHT LOW LEVEL FUEL SENSOR							Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-40-03PROC. REF: AMM 28-40-03									
D2820013	PERFORM INITIAL CLEANING AND LEAK CHECK OF LOW-PRESSURE FUEL FILTERS							Service	ATA:28
	MOS/MSC	30-Apr-06	A/R						
	HRS								
	AFL								
PROC. REF: AMM 28-20-15PROC. REF: AMM 28-20-15									
F2840003 ^S	** FUEL QUANTITY SIGNAL CONDITIONER - PERFORM FUNCTIONAL TEST TO VERIFY WEIGHT ON WHEELS (WOW) INPUTS							Service	ATA:28
	MOS	09-Mar-01	48					AIRWORTHINESS	
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 28-40-00PROC. REF: AMM 28-40-00									
H2840001	* DUAL FUEL FLOW CONVERTER (DFFC) - PERFORM ACCEPTANCE TEST AND LOW TEMPERATURE SCREENING							Service	ATA:28
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
Y2810001	^S	WING TANKS - REMOVE FUEL TANK ACCESS PANELS AND PERFORM VISUAL INSPECTION						Service	ATA:28
	MOS	25-Jun-26	24						
	HRS	10023.1	600						
	AFL	7616							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:10
Y2810002	^S	WING TANKS - REMOVE FUEL TANK ACCESS PANELS AND PERFORM VISUAL INSPECTION						Service	ATA:28
	MOS	25-Jun-26	96						
	HRS	10023.1	2400						
	AFL	7616							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:22
Y2820000	^S	LOW PRESSURE FUEL FILTER - REMOVE AND INSPECT FOR CONTAMINATION. CLEAN IF NECESSARY.						Service	ATA:28
	MOS	25-Jun-26	24						
	HRS	10023.1	600						
	AFL	7616							
PROC. REF: AMM 28-20-15PROC. REF: AMM 28-20-15									PKG:10
ATA 29 - HYDRAULIC POWER									
291001		HYDRAULIC RESERVOIR						Component	ATA:29
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 29-10-02PROC. REF: AMM 29-10-02									
291012		L8 HYDRAULIC SHUTOFF VALVE						Component	ATA:29
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 29-10-05PROC. REF: AMM 29-10-05									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 29 - HYDRAULIC POWER									
291013	L9 HYDRAULIC SHUTOFF VALVE							Component	ATA:29
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 29-10-05PROC. REF: AMM 29-10-05									
291033	RESERVOIR PRESSURIZATION CONTROL MODULE							Component	ATA:29
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 29-10-06PROC. REF: AMM 29-10-06									
291034	RESERVOIR FLUID LEVEL SENSOR							Component	ATA:29
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 29-30-02PROC. REF: AMM 29-30-02									
291045	NO. 1 ENGINE DRIVEN HYDRAULIC PUMP							Component	ATA:29
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 29-10-01PROC. REF: AMM 29-10-01									
291046	NO. 2 ENGINE DRIVEN HYDRAULIC PUMP							Component	ATA:29
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 29-10-01PROC. REF: AMM 29-10-01									
291051	NO. 1 MAIN HYDRAULIC SYSTEM PRESSURE SWITCH							Component	ATA:29
PN:6629101004-001	MOS/MSC	11-Jun-16	O/C	TSN 0					
SN:1452	HRS	7630.1		TSN 0					
	AFL	5823		TSN 0					
PROC. REF: AMM 29-30-03PROC. REF: AMM 29-30-03									

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C / W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 29 - HYDRAULIC POWER									
291052	NO. 2 MAIN HYDRAULIC SYSTEM PRESSURE SWITCH							Component	ATA:29
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 29-30-03PROC. REF: AMM 29-30-03									
291057	MAIN HYDRAULIC SYSTEM ACCUMULATOR							Component	ATA:29
PN:88746-1	MOS/MSC	28-Jan-07	O/C						
SN:424	HRS	5192.28							
	AFL	3977							
PROC. REF: AMM 29-10-04PROC. REF: AMM 29-10-04									
291059	MAIN HYDRAULIC FILTER MANIFOLD							Component	ATA:29
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 29-10-03PROC. REF: AMM 29-10-03									
291069	THERMAL SHUTOFF VALVE							Component	ATA:29
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 29-10-07PROC. REF: AMM 29-10-07									
292001	AUXILIARY FILTER MANIFOLD ASSEMBLY							Component	ATA:29
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 29-20-02PROC. REF: AMM 29-20-02									
292011	AUXILIARY HYDRAULIC PUMP ASSEMBLY							Component	ATA:29
PN:48-16-1	MOS/MSC	27-Feb-23	O/C	TSO 0					
SN:ELE0600A	HRS	9186.7		TSO 0					
	AFL	7047		TSO 0					
PROC. REF: AMM 29-20-01PROC. REF: AMM 29-20-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 29 - HYDRAULIC POWER									
292012	AUXILIARY HYDRAULIC PUMP							Component	ATA:29
PN:6629201000-015	MOS/MSC	11-Jun-16	O/C						
SN:K0153	HRS	7630.1							
	AFL	5823							
PROC. REF: AMM 29-20-01PROC. REF: AMM 29-20-01									
292013	AUXILIARY HYDRAULIC PUMP ELECTRIC MOTOR							Component	ATA:29
PN:6629201000-011	MOS/MSC	11-Jun-16	O/C	TSR 0					
SN:ELE0/094	HRS	7630.1		TSR 0					
	AFL	5823		TSR 0					
PROC. REF: AMM 29-20-04PROC. REF: AMM 29-20-04									
292025	AUXILIARY HYDRAULIC SYSTEM PRESSURE SWITCH							Component	ATA:29
PN:6629101004-001	MOS/MSC	11-Jun-16	O/C	TSN 0					
SN:1226	HRS	7630.1		TSN 0					
	AFL	5823		TSN 0					
PROC. REF: AMM 29-30-03PROC. REF: AMM 29-30-03									
292401	AUXILIARY HYDRAULIC PRESSURE CHECK VALVE							Component	ATA:29
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
293001	GROUND SERVICE CONTROL BOX							Component	ATA:29
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 29-30-01PROC. REF: AMM 29-30-01									
293011	HYDRAULIC PRESSURE TRANSDUCER							Component	ATA:29
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 29-30-04PROC. REF: AMM 29-30-04									

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C / W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 29 - HYDRAULIC POWER									
D2910017	MAIN HYDRAULIC FILTER MANIFOLD ELEMENTS - REPLACE								Service ATA:29
	MOS/MSC	06-Jul-21	-						
	HRS	8631.2							
	AFL	6618							
PROC. REF: AMM 29-10-03PROC. REF: AMM 29-10-03									
D2910018	MAIN HYDRAULIC FILTER MANIFOLD ELEMENTS - REPLACE								Service ATA:29
	MOS	25-Jun-26							
	HRS	10023.1	300		10323.1		221.7		
	AFL	7616							
PROC. REF: AMM 29-10-03PROC. REF: AMM 29-10-03									
H2920002 ^S	HYDRAULIC SYSTEM GROUND SERVICE LEDS - PERFORM FUNCTIONAL TEST								Service ATA:29
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 29-30-00PROC. REF: AMM 29-30-00									
O2910005	AUXILIARY HYDRAULIC FILTER MANIFOLD ELEMENTS - REPLACE								Service ATA:29
	MOS	19-May-22						LIFE LIMIT	
	HRS	8995.3	2400		11395.3		1293.9		
	AFL	6902							
PROC. REF: AMM 29-20-02PROC. REF: AMM 29-20-02									
T2910026 ^S	RELIEF FUNCTION OF THE PRESSURIZATION CONTROL MODULE - PERFORM FUNCTIONAL TEST								Service ATA:29
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 29-10-06PROC. REF: AMM 29-10-06									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
---------	------	-------	----------	------------	----------------------------	-----------	-----------	-------------	----------

ATA 29 - HYDRAULIC POWER

Y2910001	^S	HYDRAULIC COMPONENTS AND ASSOCIATED PLUMBING (AFT OF FUSELAGE FUEL CELL, FS 495 TO FS 512) - PERFORM VISUAL INSPECTION						Service	ATA:29
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:14

Y2910002	^S	HYDRAULIC COMPONENTS AND ASSOCIATED PLUMBING (WHEEL WELL AND FORWARD AREA OF REAR SPAR) - PERFORM VISUAL INSPECTION						Service	ATA:29
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:17

Y2910003	^S	HYDRAULIC COMPONENTS AND ASSOCIATED PLUMBING (AFT AREA OF REAR SPAR) - PERFORM VISUAL INSPECTION						Service	ATA:29
	MOS	25-Jun-26	96						
	HRS	10023.1	2400						
	AFL	7616							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:19

Y2920001	^S	AUXILIARY HYDRAULIC SYSTEM - PERFORM OPERATIONAL CHECK						Service	ATA:29
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 29-20-00PROC. REF: AMM 29-20-00									PKG:13

ATA 30 - ICE AND RAIN PROTECTION

301006		ANTI-ICE VERTICAL STABILIZER RELAY PANEL (P40)						Component	ATA:30
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-10-06PROC. REF: AMM 30-10-06									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 30 - ICE AND RAIN PROTECTION									
301010	LEFT HORIZONTAL STABILIZER CONTROL SENSOR (MT47)							Component	ATA:30
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-10-05PROC. REF: AMM 30-10-05									
301011	RIGHT HORIZONTAL STABILIZER CONTROL SENSOR (MT46)							Component	ATA:30
PN:6621000000-059	MOS/MSC	03-Jun-06	O/C						
SN:UNKNOWN	HRS	4546.3							
	AFL	3481							
PROC. REF: AMM 30-10-05PROC. REF: AMM 30-10-05									
301051	LEFT ANTI-ICE 2.0 DIAMETER CHECK VALVE							Component	ATA:30
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-10-02PROC. REF: AMM 30-10-02									
301052	RIGHT ANTI-ICE 2.0 DIAMETER CHECK VALVE							Component	ATA:30
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-10-02PROC. REF: AMM 30-10-02									
301063	LEFT ANTI-ICE PRESSURE REGULATING SHUTOFF VALVE							Component	ATA:30
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-10-01PROC. REF: AMM 30-10-01									
301064	RIGHT ANTI-ICE PRESSURE REGULATING SHUTOFF VALVE							Component	ATA:30
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-10-01PROC. REF: AMM 30-10-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 30 - ICE AND RAIN PROTECTION									
301065	LEFT ANTI-ICE SHUTTLE VALVE							Component	ATA:30
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 49-70-06, AMM 30-10-08PROC. REF: AMM 49-70-06, AMM 30-10-08									
301066	RIGHT ANTI-ICE SHUTTLE VALVE							Component	ATA:30
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-10-08PROC. REF: AMM 30-10-08									
301240	ANTI-ICE MANIFOLD ASSEMBLY							Component	ATA:30
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-10-07PROC. REF: AMM 30-10-07									
302001	NO. 1 NACELLE INLET ANTI-ICE SHUTOFF VALVE							Component	ATA:30
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-20-01PROC. REF: AMM 30-20-01									
302002	NO. 2 NACELLE INLET ANTI-ICE SHUTOFF VALVE							Component	ATA:30
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-20-01PROC. REF: AMM 30-20-01									
302013	NO. 1 NACELLE ANTI-ICE PRESSURE SWITCH							Component	ATA:30
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-20-02PROC. REF: AMM 30-20-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 30 - ICE AND RAIN PROTECTION									
302014	NO. 2 NACELLE ANTI-ICE PRESSURE SWITCH							Component	ATA:30
PN:7600020-1	MOS/MSC	27-Mar-23	O/C						
SN:5769TW	HRS	9209.1							
	AFL	7060							
PROC. REF: AMM 30-20-02PROC. REF: AMM 30-20-02									
303501	LEFT NOSE RELAY BOX							Component	ATA:30
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-30-01PROC. REF: AMM 30-30-01									
303510	RIGHT NOSE RELAY BOX							Component	ATA:30
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-30-01PROC. REF: AMM 30-30-01									
304021	WINDSHIELD ANTI-ICE CONTROLLER							Component	ATA:30
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-40-01PROC. REF: AMM 30-40-01									
304060	NO. 1 WING SURFACE TEMPERATURE SENSOR							Component	ATA:30
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-10-03PROC. REF: AMM 30-10-03									
304061	NO. 2 WING SURFACE TEMPERATURE SENSOR							Component	ATA:30
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-10-03PROC. REF: AMM 30-10-03									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 30 - ICE AND RAIN PROTECTION									
304062	NO. 3 WING SURFACE TEMPERATURE SENSOR							Component	ATA:30
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-10-03PROC. REF: AMM 30-10-03									
304063	NO. 4 WING SURFACE TEMPERATURE SENSOR							Component	ATA:30
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-10-03PROC. REF: AMM 30-10-03									
308005	ICE DETECTION PROBE							Component	ATA:30
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-80-01PROC. REF: AMM 30-80-01									
A3020000 ^S	** NACELLE ANTI-ICE SYSTEM - PERFORM FUNCTIONAL TEST							Service	ATA:30
	MOS	09-Mar-01	48					AIRWORTHINESS	
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 30-20-00PROC. REF: AMM 30-20-00									
A3030000 ^S	** PITOT-STATIC HEAT SYSTEM - PERFORM OPERATIONAL CHECK							Service	ATA:30
	MOS	25-Jun-26	96					AIRWORTHINESS	
	HRS	10023.1	2400						
	AFL	7616							
PROC. REF: AMM 30-30-00PROC. REF: AMM 30-30-00									
AC3010006	** ANTI-ICE MANIFOLD - PERFORM BORESCOPE INSPECTION							Service	ATA:30
	MOS	21-Aug-25						AIRWORTHINESS	
	HRS	9809.8	600		10409.8		308.4		
	AFL	7471							
PROC. REF: AMM 30-10-07PROC. REF: AMM 30-10-07									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 30 - ICE AND RAIN PROTECTION									
H3010000	^S	** WING/STAB ANTI-ICE SWITCH - PERFORM OPERATIONAL CHECK						Service	ATA:30
	MOS	25-Jun-26	24					AIRWORTHINESS	
	HRS	10023.1	600						
	AFL	7616							
PROC. REF: AMM 30-10-00PROC. REF: AMM 30-10-00									PKG:7
T3040000	^S	** WINDSHIELD ANTI-ICE - PERFORM FUNCTIONAL TEST OF THE WINDSHIELD ANTI-ICE SYSTEM						Service	ATA:30
	MOS	25-Jun-26	24					AIRWORTHINESS	
	HRS	10023.1	600						
	AFL	7616							
PROC. REF: AMM 30-40-00PROC. REF: AMM 30-40-00									PKG:7
Y3010007	^S	WING ANTI-ICE PICCOLO TUBE - PERFORM DETAILED VISUAL INSPECTION FOR CRACKS AT W.S. 43 AND W.S. 176.						Service	ATA:30
	MOS	25-Jun-26	24						
	HRS	10023.1	600						
	AFL	7616							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:10
Y3080000	^S	ICE DETECTION SYSTEM - PERFORM FUNCTIONAL TEST						Service	ATA:30
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 30-80-00PROC. REF: AMM 30-80-00									PKG:13
Z3020005		* NO. 1 ENGINE INLET ANTI-ICE TUBE ASSEMBLY FROM THE AFT INLET BULKHEAD CONNECTION POINT FORWARD TO SPRAY RING CONNECTION, PERFORM DETAILED VISUAL/BORESCOPE INSPECTION OF THE WELDS INSIDE AND OUTSIDE OF THE TUBE AT BOTH FORWARD AND AFT ENDS.						Service	ATA:30
	MOS	25-Jun-26						AIRWORTHINESS	
	HRS	10023.1	250		10273.1		171.7		
	AFL	7616							
PROC. REF: AMM 30-20-00PROC. REF: AMM 30-20-00									

? - Insufficient Information
S - Suppressed Requirement
* - Estimated Due(New Requirement)
(EFF) - Effective C / W
(M) - Manual Due
U - User Task
Ex - Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 30 - ICE AND RAIN PROTECTION									
Z3020005	* NO. 2 ENGINE INLET ANTI-ICE TUBE ASSEMBLY FROM THE AFT INLET BULKHEAD CONNECTION POINT FORWARD TO SPRAY RING CONNECTION, PERFORM DETAILED VISUAL/BORESCOPE INSPECTION OF THE WELDS INSIDE AND OUTSIDE OF THE TUBE AT BOTH FORWARD AND AFT ENDS.							Service	ATA:30
	MOS	25-Jun-26						AIRWORTHINESS	
	HRS	10023.1	250		10273.1		171.7		
	AFL	7616							
PROC. REF: AMM 30-20-00PROC. REF: AMM 30-20-00									
Z3020006	NO. 1 ENGINE INLET ANTI-ICE TUBE ASSEMBLY FROM THE AFT INLET BULKHEAD CONNECTION POINT FORWARD TO SPRAY RING CONNECTION, PERFORM DETAILED VISUAL/BORESCOPE INSPECTION OF THE WELDS INSIDE AND OUTSIDE OF THE TUBE AT BOTH FORWARD AND AFT ENDS							Service	ATA:30
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
PROC. REF: AMM 30-20-00PROC. REF: AMM 30-20-00									
Z3020006	NO. 2 ENGINE INLET ANTI-ICE TUBE ASSEMBLY FROM THE AFT INLET BULKHEAD CONNECTION POINT FORWARD TO SPRAY RING CONNECTION, PERFORM DETAILED VISUAL/BORESCOPE INSPECTION OF THE WELDS INSIDE AND OUTSIDE OF THE TUBE AT BOTH FORWARD AND AFT ENDS							Service	ATA:30
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
PROC. REF: AMM 30-20-00PROC. REF: AMM 30-20-00									
ATA 31 - INDICATING/RECORDING SYSTEMS									
311001	PILOT CIRCUIT BREAKER PANEL							Component	ATA:31
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 24-60-01PROC. REF: AMM 24-60-01									
311005	COPILOT CIRCUIT BREAKER PANEL							Component	ATA:31
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 24-60-01PROC. REF: AMM 24-60-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 31 - INDICATING/RECORDING SYSTEMS									
311601	GEAR UP/DOWN SWITCH							Component	ATA:31
PN:A3-1295	MOS/MSC	12-Aug-15	O/C						
SN:UNKNOWN	HRS	7535.1							
	AFL	5764							
PROC. REF: AMM 32-30-02PROC. REF: AMM 32-30-02									
311805	ENGINE FUEL CONTROL PANEL							Component	ATA:31
PN:4576108500-023	MOS/MSC	20-Jan-05	O/C						
SN:MRP645048-01	HRS	3272.32							
	AFL	2494							
PROC. REF: AMM 31-11-05PROC. REF: AMM 31-11-05									
311806	ENGINE/FUEL CONTROL PANEL OVERLAY							Component	ATA:31
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
311906	FORWARD QUADRANT SWITCH PANEL OVERLAY							Component	ATA:31
PN:7631208500-015	MOS/MSC	12-Aug-15	O/C	TSN 173					
SN:UNKNOWN	HRS	7535.1		TSN 7535.1					
	AFL	5764		TSN 5764					
PROC. REF: AMM 31-11-04PROC. REF: AMM 31-11-04									
311907	RUDDER BOOST SWITCH (DS48)							Component	ATA:31
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
312001	PILOTS DIGITAL CLOCK							Component	ATA:31
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 31-21-01PROC. REF: AMM 31-21-01									

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C/W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 31 - INDICATING/RECORDING SYSTEMS									
312002	COPILOTS DIGITAL CLOCK								Component ATA:31
PN:M850-5V-LA	MOS/MSC	14-Dec-10	O/C	TSN 0					
SN:A5231	HRS	6457.2		TSN 0					
	AFL	4944		TSN 0					
PROC. REF: AMM 31-21-01PROC. REF: AMM 31-21-01									
312011	PILOTS DAVTRON M850 DIGITAL CLOCK BATTERY								Component ATA:31
PN:NBATTERYE90	MOS	25-Jun-26	12	TSN 0, Adj -142d	03-Feb-27		141 d	LIFE LIMIT	
SN:UNKNOWN	HRS	10023.1		TSN 0					
	AFL	7616		TSN 0					
PROC. REF: AMM 31-21-02PROC. REF: AMM 31-21-02									
312012	COPILOTS DAVTRON M850 DIGITAL CLOCK BATTERY								Component ATA:31
PN:NBATTERYE90	MOS	25-Jun-26	12	TSN 0, Adj -142d	03-Feb-27		141 d	LIFE LIMIT	
SN:UNKNOWN	HRS	10023.1		TSN 0					
	AFL	7616		TSN 0					
PROC. REF: AMM 31-21-02PROC. REF: AMM 31-21-02									
313001	FLIGHT DATA RECORDER								Component ATA:31
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
313001A	DOWNLOAD								Service ATA:31
PN:PN	MOS/MSC	09-Mar-01	N/R					CUSTOMER CODE	
SN:UNKNOWN	HRS	0							
	AFL	0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
313003	FLIGHT DATA RECORDER (FDR) ACCELEROMETER								Component ATA:31
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 31 - INDICATING/RECORDING SYSTEMS									
313010	HOBBS METER							Component	ATA:31
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
313018	FLIGHT DATA RECORDER INERTIA SWITCH							Component	ATA:31
PN:PN	MOS/MSC	09-Mar-01	A/R	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
314001	SELCAL DECODER							Component	ATA:31
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
314011	NO. 1 DATA ACQUISITION (DAU) UNIT							Component	ATA:31
PN:7013348-931	MOS/MSC	12-Aug-15	O/C						
SN:00013220	HRS	7535.1							
	AFL	5764							
PROC. REF: AMM 31-42-01PROC. REF: AMM 31-42-01									
314012	NO. 2 DATA ACQUISITION (DAU) UNIT							Component	ATA:31
PN:7013348-931	MOS/MSC	15-Nov-05	O/C						
SN:00063567	HRS	4035.07							
	AFL	3047							
PROC. REF: AMM 31-42-01PROC. REF: AMM 31-42-01									
314023	NO. 1 INTEGRATED AVIONICS COMPUTER (IC-600)							Component	ATA:31
PN:7017000-82222	MOS/MSC	17-Dec-15	O/C						
SN:02065544	HRS	7546							
	AFL	5771							
PROC. REF: AMM 31-41-01PROC. REF: AMM 31-41-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 31 - INDICATING/RECORDING SYSTEMS									
314024	NO. 2 INTEGRATED AVIONICS COMPUTER (IC-600)							Component	ATA:31
PN:7017000-82222	MOS/MSC	23-Nov-21	O/C						
SN:98041571	HRS	8770.6							
	AFL	6752							
PROC. REF: AMM 31-41-01PROC. REF: AMM 31-41-01									
314051	NO. 1 CENTRAL COMPUTING MEMORY MODULE IM-600							Component	ATA:31
PN:7025973-04214	MOS/MSC	17-Feb-05	O/C						
SN:01080971	HRS	3300.2							
	AFL	2515							
PROC. REF: AMM 31-41-02PROC. REF: AMM 31-41-02									
314052	NO. 2 CENTRAL COMPUTING MEMORY MODULE IM-600							Component	ATA:31
PN:7025973-04214	MOS/MSC	17-Feb-05	O/C						
SN:01080922	HRS	3300.2							
	AFL	2515							
PROC. REF: AMM 31-41-02PROC. REF: AMM 31-41-02									
315001	CREW WARNING PANEL							Component	ATA:31
PN:6631508501-001	MOS/MSC	17-Feb-05	O/C	TSN 0					
SN:357	HRS	3300.2		TSN 0					
	AFL	2515		TSN 0					
PROC. REF: AMM 31-51-01PROC. REF: AMM 31-51-01									
316001	NO. 1 DU870 COMPUTER							Component	ATA:31
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 31-60-01PROC. REF: AMM 31-60-01									
316002	NO. 2 DU870 COMPUTER							Component	ATA:31
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 31-60-01PROC. REF: AMM 31-60-01									

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C/W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 31 - INDICATING/RECORDING SYSTEMS									
316003	NO. 3 DU870 COMPUTER							Component	ATA:31
PN:7014300-901	MOS/MSC	05-Jan-26	O/C						
SN:050E648	HRS	9987.5							
	AFL	7596							
PROC. REF: AMM 31-60-01PROC. REF: AMM 31-60-01									
316004	NO. 4 DU870 COMPUTER							Component	ATA:31
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 31-60-01PROC. REF: AMM 31-60-01									
316005	PILOT EFIS DISPLAY CONTROLLER							Component	ATA:31
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 31-60-02PROC. REF: AMM 31-60-02									
316006	COPILOT EFIS DISPLAY CONTROLLER							Component	ATA:31
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 31-60-02PROC. REF: AMM 31-60-02									
316007	PILOT NO. 1 MULTIFUNCTION DISPLAY CONTROLLER BEZEL							Component	ATA:31
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 31-60-01PROC. REF: AMM 31-60-01									
316008	PILOT NO. 2 MULTIFUNCTION DISPLAY CONTROLLER BEZEL							Component	ATA:31
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 31-60-01PROC. REF: AMM 31-60-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
---------	------	-------	----------	------------	----------------------------	-----------	-----------	-------------	----------

ATA 31 - INDICATING/RECORDING SYSTEMS

316009	COPILOT NO. 1 MULTIFUNCTION DISPLAY CONTROLLER BEZEL							Component	ATA:31
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 31-60-01PROC. REF: AMM 31-60-01									

316010	COPILOT NO. 2 MULTIFUNCTION DISPLAY CONTROLLER BEZEL							Component	ATA:31
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 31-60-01PROC. REF: AMM 31-60-01									

316091	AFIS DATA TRANSFER UNIT							Component	ATA:31
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

B3100000 ^S	** INDICATING/RECORDING SYSTEM - PERFORM OPERATIONAL CHECK							Service	ATA:31
	MOS	25-Jun-26	24					AIRWORTHINESS	
	HRS	10023.1	600						
	AFL	7616							
PROC. REF: AMM 31-00-00PROC. REF: AMM 31-00-00									
									PKG:7

ATA 32 - LANDING GEAR

320041	LEFT MAIN LANDING GEAR UPPER LINK PIN							Component	ATA:32
PN:PN	MOS	09-Mar-01		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0	10000	TSN 0	10000		2326		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									

320042	RIGHT MAIN LANDING GEAR UPPER LINK PIN							Component	ATA:32
PN:PN	MOS	09-Mar-01		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0	10000	TSN 0	10000		2326		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
320043	LEFT MAIN LANDING GEAR LOWER LINK PIN							Component	ATA:32
PN:PN	MOS	09-Mar-01		TSN 0				AIRWORTHINESS	
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0	10000	TSN 0	10000		2326		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
320044	RIGHT MAIN LANDING GEAR LOWER LINK PIN							Component	ATA:32
PN:PN	MOS	09-Mar-01		TSN 0				AIRWORTHINESS	
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0	10000	TSN 0	10000		2326		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
320051	LEFT MAIN LANDING GEAR PISTON PIN							Component	ATA:32
PN:PN	MOS	09-Mar-01		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0	10000	TSN 0	10000		2326		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
320052	RIGHT MAIN LANDING GEAR PISTON PIN							Component	ATA:32
PN:PN	MOS	09-Mar-01		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0	10000	TSN 0	10000		2326		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
320061	LEFT MAIN LANDING GEAR ACTUATOR PISTON							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	H/T	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01									
320062	RIGHT MAIN LANDING GEAR ACTUATOR PISTON							Component	ATA:32
PN:4532101000V72-002	MOS/MSC	09-Mar-01	H/T	TSN 0					
SN:H1153	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
320071	LEFT MAIN LANDING GEAR ACTUATOR CYLINDER							Component	ATA:32
PN:4532101000V76-001	MOS/MSC	09-Mar-01	H/T	TSN 0					
SN:H0155	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01									
320072	RIGHT MAIN LANDING GEAR ACTUATOR CYLINDER							Component	ATA:32
PN:4532101000V72-002	MOS/MSC	09-Mar-01	H/T	TSN 0					
SN:H1153	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01									
320081	LEFT MAIN LANDING GEAR ACTUATOR END CAP							Component	ATA:32
PN:200-0303-001	MOS/MSC	02-Aug-24	H/T	TSN 0					
SN:UNKNOWN	HRS	9525.7		TSN 0					
	AFL	7276		TSN 0					
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01									
320082	RIGHT MAIN LANDING GEAR ACTUATOR END CAP							Component	ATA:32
PN:200-0303-001	MOS/MSC	02-Aug-24	H/T	TSN 0					
SN:UNKNOWN	HRS	9525.7		TSN 0					
	AFL	7276		TSN 0					
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01									
320091	LEFT MAIN LANDING GEAR ACTUATOR HOUSING							Component	ATA:32
PN:200-0304-001	MOS/MSC	19-Dec-10	H/T	TSN 0					
SN:H1704	HRS	6457.2		TSN 0					
	AFL	4944		TSN 0					
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01									
320092	RIGHT MAIN LANDING GEAR ACTUATOR HOUSING							Component	ATA:32
PN:4532101000V72-002	MOS/MSC	09-Mar-01	H/T	TSN 0					
SN:H1153	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
321001	LEFT MAIN LANDING GEAR STRUT								Component ATA:32
PN:200-0200-013	MOS/MSC	25-Jun-26	H/T						
SN:H0584	HRS	10023.1			TSN 3719.1, TSO 1608.7				
	AFL	7616			TSN 2562, TSO 1153				
Special Properties: RII ITEM PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
321002	RIGHT MAIN LANDING GEAR STRUT								Component ATA:32
PN:200-0200-014	MOS/MSC	25-Jun-26	H/T						
SN:H1593	HRS	10023.1			TSN 3719.1				
	AFL	7616			TSN 2562				
Special Properties: RII ITEM PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
321011	LEFT MAIN LANDING GEAR SHOCK STRUT CYLINDER								Component ATA:32
PN:200-0201-009	MOS/MSC	30-Mar-21	H/T						
SN:H0727	HRS	8414.4			TSN 2110.4				
	AFL	6463			TSN 1409				
PROC. REF: NDT PART 4/32-10-01, NDT PART 4/32-10-00, AMM 32-10-01PROC. REF: NDT PART 4/32-10-01, NDT PART 4/32-10-00, AMM 32-10-01									
321012	RIGHT MAIN LANDING GEAR SHOCK STRUT CYLINDER								Component ATA:32
PN:200-0201-010	MOS/MSC	30-Mar-21	H/T						
SN:H0755	HRS	8414.4			TSN 2110.4				
	AFL	6463			TSN 1409				
PROC. REF: NDT PART 4/32-10-01, NDT PART 4/32-10-00PROC. REF: NDT PART 4/32-10-01, NDT PART 4/32-10-00									
321025	LEFT MAIN LANDING GEAR ACTUATOR UPPER PIN								Component ATA:32
PN:200-0325-101	MOS/MSC	24-Jun-19	H/T		TSN 0				
SN:H2409	HRS	8101.1			TSN 0				
	AFL	6233			TSN 0				
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01									
321026	RIGHT MAIN LANDING GEAR ACTUATOR UPPER PIN								Component ATA:32
PN:200-0325-101	MOS/MSC	24-Jun-19	H/T		TSN 0				
SN:HER08U/5030	HRS	8101.1			TSN 0				
	AFL	6233			TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
321037	LEFT MAIN LANDING GEAR ACTUATOR LOWER PIN							Component	ATA:32
PN:200-0217-101	MOS/MSC	24-Jun-19	H/T	TSN 0					
SN:H5000	HRS	8101.1		TSN 0					
	AFL	6233		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
321038	RIGHT MAIN LANDING GEAR ACTUATOR LOWER PIN							Component	ATA:32
PN:200-0217-101	MOS/MSC	24-Jun-19	H/T	TSN 0					
SN:HER08U5014	HRS	8101.1		TSN 0					
	AFL	6233		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
321049	LEFT MAIN LANDING GEAR AXLE BEAM							Component	ATA:32
PN:200-0203-001	MOS/MSC	08-Sep-12	H/T						
SN:H0331	HRS	6989.1							
	AFL	5335		TSN 5311					
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
321050	RIGHT MAIN LANDING GEAR AXLE BEAM							Component	ATA:32
PN:200-0203-001	MOS/MSC	08-Sep-12	H/T						
SN:H0334	HRS	6989.1							
	AFL	5335		TSN 5311					
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
321061	LEFT MAIN LANDING GEAR SIDE-STAY ACTUATOR PIN							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
321062	RIGHT MAIN LANDING GEAR SIDE-STAY ACTUATOR PIN							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
321073	LEFT MAIN LANDING GEAR SIDE BRACE ACTUATOR DISPLACEMENT TUBE							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
321074	RIGHT MAIN LANDING GEAR SIDE BRACE ACTUATOR DISPLACEMENT TUBE							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
321085	LEFT FORWARD TRUNNION ASSEMBLY							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
321086	RIGHT FORWARD TRUNNION ASSEMBLY							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
321087	LEFT AFT TRUNNION ASSEMBLY							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
321088	RIGHT AFT TRUNNION ASSEMBLY							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
321101	LEFT FORWARD MAIN LANDING GEAR TRUNNION PIN								Component ATA:32
PN:200-0212-103	MOS	24-Jul-12						LIFE LIMIT	
SN:H0501	HRS	6961.3		TSN 2110.4					
	AFL	5311	10000	TSN 1409	13902		6228		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
321102	RIGHT FORWARD MAIN LANDING GEAR TRUNNION PIN								Component ATA:32
PN:200-0212-103	MOS	24-Jul-12						LIFE LIMIT	
SN:H0473	HRS	6961.3		TSN 2110.4					
	AFL	5311	10000	TSN 1409	13902		6228		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
321103	LEFT AFT MAIN LANDING GEAR TRUNNION PIN								Component ATA:32
PN:200-0213-103	MOS	24-Jul-12						LIFE LIMIT	
SN:H0364	HRS	6961.3		TSN 2110.4					
	AFL	5311	10000	TSN 1409	13902		6228		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
321104	RIGHT AFT MAIN LANDING GEAR TRUNNION PIN								Component ATA:32
PN:200-0213-103	MOS	24-Jul-12						LIFE LIMIT	
SN:H0338	HRS	6961.3		TSN 2110.4					
	AFL	5311	10000	TSN 1409	13902		6228		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
321111	LEFT FORWARD LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN								Component ATA:32
PN:4532103201-001	MOS/MSC	15-Dec-10	H/T	TSN 0					
SN:CM1882	HRS	6457.2		TSN 0					
	AFL	4944		TSN 0					
PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05									
321112	RIGHT FORWARD LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN								Component ATA:32
PN:4532103201-001	MOS/MSC	15-Dec-10	H/T	TSN 0					
SN:CM11113	HRS	6457.2		TSN 0					
	AFL	4944		TSN 0					
PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 10101.4
 AFL: 7674
 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
321113	LEFT FORWARD UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN							Component	ATA:32
PN:4532103201-001	MOS/MSC	15-Dec-10	H/T	TSN 0					
SN:CM1806	HRS	6457.2		TSN 0					
	AFL	4944		TSN 0					
PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05									
321114	RIGHT FORWARD UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN							Component	ATA:32
PN:4532103201-001	MOS/MSC	15-Dec-10	H/T	TSN 0					
SN:CM1710	HRS	6457.2		TSN 0					
	AFL	4944		TSN 0					
PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05									
321117	LEFT AFT UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN							Component	ATA:32
PN:4532103202-001	MOS/MSC	18-Dec-10	H/T	TSN 0					
SN:CM1371	HRS	6457.2		TSN 0					
	AFL	4944		TSN 0					
PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05									
321118	RIGHT AFT UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN							Component	ATA:32
PN:4532103202-001	MOS/MSC	18-Dec-10	H/T	TSN 0					
SN:CM1363	HRS	6457.2		TSN 0					
	AFL	4944		TSN 0					
PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05									
321119	LEFT AFT LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN							Component	ATA:32
PN:4532103203-001	MOS/MSC	18-Dec-10	H/T	TSN 0					
SN:CM1818	HRS	6457.2		TSN 0					
	AFL	4944		TSN 0					
PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05									
321120	RIGHT AFT LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN							Component	ATA:32
PN:4532103203-001	MOS/MSC	18-Dec-10	H/T	TSN 0					
SN:CM1759	HRS	6457.2		TSN 0					
	AFL	4944		TSN 0					
PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
321201	LEFT MAIN LANDING GEAR OLEO ASSEMBLY							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
321202	RIGHT MAIN LANDING GEAR OLEO ASSEMBLY							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
321215	LEFT MAIN LANDING GEAR SHOCK STRUT PISTON							Component	ATA:32
PN:PN	MOS	09-Mar-01		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0	10000	TSN 0	10000		2326		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
321216	RIGHT MAIN LANDING GEAR SHOCK STRUT PISTON							Component	ATA:32
PN:PN	MOS	09-Mar-01		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0	10000	TSN 0	10000		2326		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
321227	LEFT MAIN LANDING GEAR SHOCK STRUT LINK							Component	ATA:32
PN:PN	MOS	09-Mar-01		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0	10000	TSN 0	10000		2326		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
321228	RIGHT MAIN LANDING GEAR SHOCK STRUT LINK							Component	ATA:32
PN:PN	MOS	09-Mar-01		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0	10000	TSN 0	10000		2326		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 10101.4
 AFL: 7674
 As Of: 14-Sep-2026
 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
321301	LEFT MAIN LANDING GEAR OUTBOARD DOOR							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 52-80-01PROC. REF: AMM 52-80-01									
321302	LEFT MAIN LANDING GEAR INBOARD DOOR							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 52-80-01PROC. REF: AMM 52-80-01									
321303	RIGHT MAIN LANDING GEAR INBOARD DOOR							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 52-80-01PROC. REF: AMM 52-80-01									
321304	RIGHT MAIN LANDING GEAR OUTBOARD DOOR							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 52-80-01PROC. REF: AMM 52-80-01									
322001 ^S	NOSE LANDING GEAR STRUT ASSEMBLY							Component	ATA:32
PN:4532230001-814	MOS	12-Feb-08		TSR 0				LIFE LIMIT	
SN:008	HRS	5965.9		TSR 0					
	AFL	4561	20000	TSN 4561, TSR 0					
PROC. REF: AMM 32-20-01PROC. REF: AMM 32-20-01									
322002	NOSE LANDING GEAR CYLINDER							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-32-01PROC. REF: AMM 32-32-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
322003	NOSE LANDING GEAR PISTON							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-32-01PROC. REF: AMM 32-32-01									
322004	NOSE LANDING GEAR ACTUATOR BRACKET							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-32-01PROC. REF: AMM 32-32-01									
322005	NOSE LANDING GEAR FORK							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-32-01PROC. REF: AMM 32-32-01									
322011 ^S	NOSE LANDING GEAR ACTUATOR ASSEMBLY							Component	ATA:32
PN:6632201000-001	MOS	09-Mar-01		TSN 0				LIFE LIMIT	
SN:EFS210	HRS	0		TSN 0					
	AFL	0	20000	TSN 0					
PROC. REF: AMM 32-32-01PROC. REF: AMM 32-32-01									
322061 ^S	NOSE LANDING GEAR TRUNNION AXLE							Component	ATA:32
PN:2342110-003	MOS	09-Mar-01		TSN 0				LIFE LIMIT	
SN:R153	HRS	0		TSN 0					
	AFL	0	20000	TSN 0					
PROC. REF: AMM 32-20-01PROC. REF: AMM 32-20-01									
322071 ^S	LEFT NOSE LANDING GEAR TRUNNION PIN							Component	ATA:32
PN:2342108-003	MOS	09-Mar-01		TSN 0				LIFE LIMIT	
SN:L016	HRS	0		TSN 0					
	AFL	0	20000	TSN 0					
PROC. REF: AMM 32-20-01PROC. REF: AMM 32-20-01									

? - Insufficient Information
S - Suppressed Requirement
* - Estimated Due(New Requirement)
(EFF) - Effective C / W
(M) - Manual Due
U - User Task
Ex - Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
322072 ^S	RIGHT NOSE LANDING GEAR TRUNNION PIN							Component	ATA:32
PN:2342108-003	MOS	09-Mar-01		TSN 0				LIFE LIMIT	
SN:L012	HRS	0		TSN 0					
	AFL	0	20000	TSN 0					
PROC. REF: AMM 32-20-01PROC. REF: AMM 32-20-01									
322095	LEFT NOSE LANDING GEAR DOOR							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 52-81-01PROC. REF: AMM 52-81-01									
322096	RIGHT NOSE LANDING GEAR DOOR							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 52-81-01PROC. REF: AMM 52-81-01									
322111	NOSE LANDING GEAR CHASSIS ASSEMBLY							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
322121	NOSE LANDING GEAR UPLOCK MECHANISM							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-32-02PROC. REF: AMM 32-32-02									
323001	LEFT MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY							Component	ATA:32
PN:200-0300-003	MOS/MSC	02-Aug-24	H/T						
SN:H0134	HRS	9525.7							
	AFL	7276		TSN 7276					
Special Properties: RII ITEM									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
323002	RIGHT MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY							Component	ATA:32
PN:200-0300-004	MOS/MSC	02-Aug-24	H/T						
SN:H1188	HRS	9525.7							
	AFL	7276		TSN 7276					
Special Properties: RII ITEM									
323037	LEFT MAIN LANDING GEAR INBOARD DOOR UPLOCK MECHANISM							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-31-04PROC. REF: AMM 32-31-04									
323038	RIGHT MAIN LANDING GEAR INBOARD DOOR UPLOCK MECHANISM							Component	ATA:32
PN:6632303004-006	MOS/MSC	08-Sep-12	O/C	TSR 31					
SN:0117	HRS	6989.1		TSR 0					
	AFL	5335		TSR 0					
PROC. REF: AMM 32-31-04PROC. REF: AMM 32-31-04									
323110	NOSE LANDING GEAR DOWN-LOCK SWITCH							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-60-05PROC. REF: AMM 32-60-05									
323220	LEFT DOWN AND LOCKED SWITCH							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-60-02PROC. REF: AMM 32-60-02									
323221	RIGHT DOWN AND LOCKED SWITCH							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-60-02PROC. REF: AMM 32-60-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
323301	LEFT MAIN LANDING GEAR INBOARD DOOR ACTUATOR CAP SCREWS							Component	ATA:32
PN:6632303003-003	MOS/MSC	13-Apr-07	O/C						
SN:0779	HRS	5383.5							
	AFL	4119							
PROC. REF: AMM 32-31-02PROC. REF: AMM 32-31-02									
323302	RIGHT MAIN LANDING GEAR INBOARD DOOR ACTUATOR CAP SCREWS							Component	ATA:32
PN:6632303003-001	MOS/MSC	25-Jun-26	O/C						
SN:0012	HRS	10023.1							
	AFL	7616							
PROC. REF: AMM 32-31-02PROC. REF: AMM 32-31-02									
323305	LEFT MAIN LANDING GEAR ACTUATOR GIMBAL ASSEMBLY							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-31-06PROC. REF: AMM 32-31-06									
323306	RIGHT MAIN LANDING GEAR ACTUATOR GIMBAL ASSEMBLY							Component	ATA:32
PN:PN-UNKNOWN	MOS/MSC	25-Jul-10	O/C						
SN:UNKNOWN	HRS	6330.6							
	AFL	4850							
PROC. REF: AMM 32-31-06PROC. REF: AMM 32-31-06									
323307	LEFT MAIN LANDING GEAR SHAFT GIMBAL ASSEMBLY							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-31-06PROC. REF: AMM 32-31-06									
323308	RIGHT MAIN LANDING GEAR SHAFT GIMBAL ASSEMBLY							Component	ATA:32
PN:PN-UNKNOWN	MOS/MSC	25-Jul-10	O/C						
SN:UNKNOWN	HRS	6330.6							
	AFL	4850							
PROC. REF: AMM 32-31-06PROC. REF: AMM 32-31-06									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
323309	LEFT MAIN LANDING GEAR INBOARD DOOR GIMBAL BRACKET ASSEMBLY							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-31-06PROC. REF: AMM 32-31-06									
323310	RIGHT MAIN LANDING GEAR INBOARD DOOR GIMBAL BRACKET ASSEMBLY							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-31-06PROC. REF: AMM 32-31-06									
323735	CONTROL VALVE							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-30-01PROC. REF: AMM 32-30-01									
324001	NO. 1 MAIN LANDING GEAR WHEEL							Component	ATA:32
PN:3-1545-1	MOS/MSC	25-Jun-26	O/C						
SN:1194	HRS	10023.1							
	AFL	7616							
PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02									
324001A	NON DESTRUCTIVE TEST NO. 1 MAIN LANDING GEAR WHEEL							Service	ATA:32
PN:3-1545-1	MOS/MSC	25-Jun-26	A/R						
SN:1194	HRS	10023.1							
	AFL	7616							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
324002	NO. 2 MAIN LANDING GEAR WHEEL							Component	ATA:32
PN:3-1545-1	MOS/MSC	25-Jun-26	O/C						
SN:1222	HRS	10023.1							
	AFL	7616							
PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
324002A	NON DESTRUCTIVE TEST NO. 2 MAIN LANDING GEAR WHEEL								Service ATA:32
PN:3-1545-1	MOS/MSC	25-Jun-26	A/R						
SN:1222	HRS	10023.1							
	AFL	7616							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
324003	NO. 3 MAIN LANDING GEAR WHEEL								Component ATA:32
PN:3-1545-1	MOS/MSC	27-Oct-25	O/C						
SN:3275	HRS	9906.2							
	AFL	7538							
PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02									
324003A	NON DESTRUCTIVE TEST NO. 3 MAIN LANDING GEAR WHEEL								Service ATA:32
PN:3-1545-1	MOS/MSC	27-Oct-25	A/R						
SN:3275	HRS	9906.2							
	AFL	7538							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
324004	NO. 4 MAIN LANDING GEAR WHEEL								Component ATA:32
PN:3-1545-1	MOS/MSC	27-Oct-25	O/C						
SN:0831	HRS	9906.2							
	AFL	7538							
PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02									
324004A	NON DESTRUCTIVE TEST NO. 4 MAIN LANDING GEAR WHEEL								Service ATA:32
PN:3-1545-1	MOS/MSC	27-Oct-25	A/R						
SN:0831	HRS	9906.2							
	AFL	7538							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
324005	NOSE GEAR WHEEL ASSEMBLY								Component ATA:32
PN:9544207-4	MOS/MSC	13-Oct-25	O/C						
SN:OCT07-2939	HRS	9885.1							
	AFL	7524							
PROC. REF: AMM 32-40-01PROC. REF: AMM 32-40-01									

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C / W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
324021	NO. 1 MAIN LANDING GEAR TIRE							Component	ATA:32
PN:226K08-4	MOS/MSC	25-Jun-26	O/C	TSN 0					
SN:50740670	HRS	10023.1		TSN 0					
	AFL	7616		TSN 0					
PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02									
324022	NO. 2 MAIN LANDING GEAR TIRE							Component	ATA:32
PN:226K08-4	MOS/MSC	25-Jun-26	O/C	TSN 0					
SN:50730754	HRS	10023.1		TSN 0					
	AFL	7616		TSN 0					
PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02									
324023	NO. 3 MAIN LANDING GEAR TIRE							Component	ATA:32
PN:226K08-4	MOS/MSC	27-Oct-25	O/C	TSN 0					
SN:50780755	HRS	9906.2		TSN 0					
	AFL	7538		TSN 0					
PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02									
324024	NO. 4 MAIN LANDING GEAR TIRE							Component	ATA:32
PN:226K08-4	MOS/MSC	27-Oct-25	O/C	TSN 0					
SN:50741022	HRS	9906.2		TSN 0					
	AFL	7538		TSN 0					
PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02									
324025	NOSE LANDING GEAR TIRE							Component	ATA:32
PN:03-613-8	MOS/MSC	13-Oct-25	O/C	TSN 0					
SN:5041T00281	HRS	9885.1		TSN 0					
	AFL	7524		TSN 0					
PROC. REF: AMM 32-40-01PROC. REF: AMM 32-40-01									
324061	LEFT ANTI-SKID CONTROL VALVE							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-07PROC. REF: AMM 32-41-07									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
324062	RIGHT ANTI-SKID CONTROL VALVE							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-07PROC. REF: AMM 32-41-07									
324066	LEFT ANTI-SKID SHUTOFF VALVE							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
324067	RIGHT ANTI-SKID SHUTOFF VALVE							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
324097	BRAKE CONTROL UNIT							Component	ATA:32
PN:42-933-3	MOS/MSC	03-Jan-06	O/C						
SN:150	HRS	4160.77							
	AFL	3151							
PROC. REF: AMM 32-41-02PROC. REF: AMM 32-41-02									
324108	EMERGENCY PARKING BRAKE CHECK VALVE							Component	ATA:32
PN:1C4124	MOS/MSC	19-Mar-05	O/C						
SN:UNKNOWN	HRS	3391.45							
	AFL	2574							
PROC. REF: AMM 32-42-09PROC. REF: AMM 32-42-09									
324109	EMERGENCY/PARK BRAKE VALVE							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-42-01PROC. REF: AMM 32-42-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
324110	EMERGENCY/PARK BRAKE PRESSURE TRANSDUCER							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-42-03PROC. REF: AMM 32-42-03									
324111	NO. 1 MAIN LANDING GEAR BRAKE ASSEMBLY							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01									
324112	NO. 2 MAIN LANDING GEAR BRAKE ASSEMBLY							Component	ATA:32
PN:6632401000-002	MOS/MSC	27-Aug-21	O/C						
SN:2262	HRS	8708.2							
	AFL	6691							
PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01									
324113	NO. 3 MAIN LANDING GEAR BRAKE ASSEMBLY							Component	ATA:32
PN:6632401000-002	MOS/MSC	25-Nov-19	O/C	TSO 0					
SN:1975	HRS	8177.7		TSO 0					
	AFL	6303		TSO 0					
PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01									
324114	NO. 4 MAIN LANDING GEAR BRAKE ASSEMBLY							Component	ATA:32
PN:2-1579-2	MOS/MSC	15-Jul-11	O/C	TSO 0					
SN:0917SB	HRS	6651.4		TSO 0					
	AFL	5089		TSO 0					
PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01									
324201	NO. 1 BRAKE SHUTTLE VALVE							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-42-04PROC. REF: AMM 32-42-04									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
324202	NO. 2 BRAKE SHUTTLE VALVE							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-42-04PROC. REF: AMM 32-42-04									
324203	NO. 3 BRAKE SHUTTLE VALVE							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-42-04PROC. REF: AMM 32-42-04									
324204	NO. 4 BRAKE SHUTTLE VALVE							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-42-04PROC. REF: AMM 32-42-04									
324205	BRAKE SHUTTLE MODULE							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-04PROC. REF: AMM 32-41-04									
324305	LEFT PILOT BRAKE TRANSDUCER							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-03PROC. REF: AMM 32-41-03									
324306	RIGHT PILOT BRAKE TRANSDUCER							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-03PROC. REF: AMM 32-41-03									

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C / W
(M)-Manual Due
U-User Task
Ex-Excluded Task

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
324610-1	LEFT INBOARD BRAKE SWIVEL							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01									
324610-2	LEFT OUTBOARD BRAKE SWIVEL							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01									
324611-1	RIGHT INBOARD BRAKE SWIVEL							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01									
324611-2	RIGHT OUTBOARD BRAKE SWIVEL							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01									
324701	NO. 1 BRAKE HYDRAULIC FUSE							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-09PROC. REF: AMM 32-41-09									
324702	NO. 2 BRAKE HYDRAULIC FUSE							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-09PROC. REF: AMM 32-41-09									

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C / W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
324703	NO. 3 BRAKE HYDRAULIC FUSE							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-09PROC. REF: AMM 32-41-09									
324704	NO. 4 BRAKE HYDRAULIC FUSE							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-09PROC. REF: AMM 32-41-09									
324711	NO. 1 WHEEL SPEED TRANSDUCER							Component	ATA:32
PN:140-183	MOS/MSC	17-Nov-20	O/C						
SN:3456	HRS	8301.3							
	AFL	6392							
PROC. REF: AMM 32-41-10PROC. REF: AMM 32-41-10									
324712	NO. 2 WHEEL SPEED TRANSDUCER							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-10PROC. REF: AMM 32-41-10									
324713	NO. 3 WHEEL SPEED TRANSDUCER							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-10PROC. REF: AMM 32-41-10									
324714	NO. 4 WHEEL SPEED TRANSDUCER							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-10PROC. REF: AMM 32-41-10									

?-Insufficient Information

S-Suppressed Requirement

*-Estimated Due(New Requirement)

(EFF)-Effective C / W

(M)-Manual Due

U-User Task

Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
324721	(MT56) BRAKE PRESSURE TRANSDUCER							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-08PROC. REF: AMM 32-41-08									
324722	(MT57) BRAKE PRESSURE TRANSDUCER							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-08PROC. REF: AMM 32-41-08									
324723	(MT58) BRAKE PRESSURE TRANSDUCER							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-08PROC. REF: AMM 32-41-08									
324724	(MT59) BRAKE PRESSURE TRANSDUCER							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-08PROC. REF: AMM 32-41-08									
324801	EMERGENCY/PARK BRAKE FUSE							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-42-07PROC. REF: AMM 32-42-07									
324805	EMERGENCY/PARK BRAKE ACCUMULATOR							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-42-02PROC. REF: AMM 32-42-02									

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C / W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 10101.4
 AFL: 7674
 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
325007	NOSE WHEEL STEERING FILTER BOX (P41)							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-50-06PROC. REF: AMM 32-50-06									
325011	NOSE WHEEL STEERING SERVO ACTUATOR							Component	ATA:32
PN:JR5208C	MOS/MSC	13-Feb-08	O/C	TSR 4					
SN:A0437	HRS	5967.8		TSR 0					
	AFL	4562		TSR 0					
PROC. REF: AMM 32-50-02PROC. REF: AMM 32-50-02									
325021	NOSE WHEEL STEERING GEARBOX							Component	ATA:32
PN:2W3201D	MOS/MSC	29-Oct-06	O/C						
SN:C0347	HRS	4933.32							
	AFL	3789							
PROC. REF: AMM 32-50-03PROC. REF: AMM 32-50-03									
325031	NOSE WHEEL STEERING COMPUTER							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-50-01PROC. REF: AMM 32-50-01									
325035	NOSE WHEEL STEERING POWER SUPPLY							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
325041	LEFT NOSE WHEEL STEERING TRANSDUCER							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-50-04PROC. REF: AMM 32-50-04									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
325042	RIGHT NOSE WHEEL STEERING TRANSDUCER							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-50-04PROC. REF: AMM 32-50-04									
325051 ^S	NOSE LANDING GEAR ACTUATOR UPPER PIN							Component	ATA:32
PN:4532302043-007	MOS	09-Mar-01		TSN 0				LIFE LIMIT	
SN:132	HRS	0		TSN 0					
	AFL	0	20000	TSN 0					
PROC. REF: AMM 32-32-01PROC. REF: AMM 32-32-01									
326000	NOSE LANDING GEAR WIRE HARNESS							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
326104	NOSE LANDING GEAR SQUAT/WOW SWITCH (S178)							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-50-09PROC. REF: AMM 32-50-09									
326105	NO. 1 MAIN GEAR SQUAT SWITCH							Component	ATA:32
PN:444EN2-R	MOS/MSC	18-Oct-22	O/C	TSN 0					
SN:UNKNOWN	HRS	9133.2		TSN 0					
	AFL	7007		TSN 0					
PROC. REF: AMM 32-60-09PROC. REF: AMM 32-60-09									
326106	NO. 2 MAIN GEAR SQUAT SWITCH							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-60-09PROC. REF: AMM 32-60-09									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
326107	NO. 3 MAIN GEAR SQUAT SWITCH							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-60-09PROC. REF: AMM 32-60-09									
326108	NO. 4 MAIN GEAR SQUAT SWITCH							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-60-09PROC. REF: AMM 32-60-09									
326115	SQUAT SWITCH RELAY BOX P21							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-60-08PROC. REF: AMM 32-60-08									
A3230001 ^S	** LANDING GEAR - PERFORM EMERGENCY GEAR EXTENSION FUNCTIONAL TEST							Service	ATA:32
	MOS	25-Jun-26	24					AIRWORTHINESS	
	HRS	10023.1	600						
	AFL	7616							
PROC. REF: AMM 32-33-00PROC. REF: AMM 32-33-00									
A3240005 ^S	** BRAKE HYDRAULIC FUSES - PERFORM FUNCTIONAL TEST							Service	ATA:32
	MOS	09-Mar-01	48					AIRWORTHINESS	
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 32-41-09PROC. REF: AMM 32-41-09									
A3240006 ^S	** BRAKE SHUTTLE MODULE - PERFORM FUNCTIONAL TEST							Service	ATA:32
	MOS	09-Mar-01	48					AIRWORTHINESS	
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 32-41-04PROC. REF: AMM 32-41-04									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
A3240007 ^S ** BRAKE SHUTTLE VALVES - PERFORM FUNCTIONAL TEST									
	MOS	25-Jun-26	96					AIRWORTHINESS	Service ATA:32
	HRS	10023.1	2400						
	AFL	7616							
PROC. REF: AMM 32-42-04PROC. REF: AMM 32-42-04									
A3240009 ^S ** BRAKE PRESSURE TRANSDUCERS - PERFORM FUNCTIONAL TEST									
	MOS	09-Mar-01						AIRWORTHINESS	Service ATA:32
	HRS	0	4800						
	AFL	0							
PROC. REF: AMM 32-41-08PROC. REF: AMM 32-41-08									
AA3220018 LEFT MAIN LANDING GEAR STRUT - PERFORM SPECIAL DETAILED INSPECTION									
PN:200-0200-013	MOS	30-Mar-21	96		30-Mar-29		927 d		Service ATA:32
SN:H0584	HRS	8414.4							
	AFL	6463	6600		13063		5389		
PROC. REF: NDT PART 7/32-10-01, NDT PART 7/32-10-03, NDT PART 7/32-10-04, NDT PART 8/32-10-02, NDT PART 7/32-10-05, NDT PART 7/32-10-06, NDT PART 8/32-10-01, NDT PART 8/32-10-03PROC. REF: NDT PART 7/32-10-01, NDT PART 7/32-10-03, NDT PART 7/32-10-04, NDT PART 8/32-10-02, NDT PART 7/32-10-05, NDT PART 7/32-10-06, NDT PART 8/32-10-01, NDT PART 8/32-10-03									
AA3220018 RIGHT MAIN LANDING GEAR STRUT - PERFORM SPECIAL DETAILED INSPECTION									
PN:200-0200-014	MOS	30-Mar-21	96		30-Mar-29		927 d		Service ATA:32
SN:H1593	HRS	8414.4							
	AFL	6463	6600		13063		5389		
PROC. REF: NDT PART 7/32-10-01, NDT PART 7/32-10-03, NDT PART 7/32-10-04, NDT PART 8/32-10-02, NDT PART 7/32-10-05, NDT PART 7/32-10-06, NDT PART 8/32-10-01, NDT PART 8/32-10-03PROC. REF: NDT PART 7/32-10-01, NDT PART 7/32-10-03, NDT PART 7/32-10-04, NDT PART 8/32-10-02, NDT PART 7/32-10-05, NDT PART 7/32-10-06, NDT PART 8/32-10-01, NDT PART 8/32-10-03									
AA3220111 LEFT MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY - DISASSEMBLE ACTUATOR AND PERFORM DETAILED VISUAL INSPECTION									
	MOS	30-Mar-21	96		30-Mar-29		927 d		Service ATA:32
	HRS	8414.4							
	AFL	6463	10000		16463		8789		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
AA3220111		RIGHT MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY - DISASSEMBLE ACTUATOR AND PERFORM DETAILED VISUAL INSPECTION						Service	ATA:32
	MOS	30-Mar-21	96		30-Mar-29		927 d		
	HRS	8414.4							
	AFL	6463	10000		16463		8789		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
AE3220151		LEFT - MAIN LANDING GEAR STRUT ASSEMBLY REBOUND RING - REPLACE.						Service	ATA:32
	MOS	EFF	96		30-Mar-29 * (M)		927 d		
	HRS								
	AFL								
PROC. REF: AMM 32-31-02PROC. REF: AMM 32-31-02									
AE3220151		RIGHT - MAIN LANDING GEAR STRUT ASSEMBLY REBOUND RING - REPLACE.						Service	ATA:32
	MOS	EFF	96		30-Mar-29 * (M)		927 d		
	HRS								
	AFL								
PROC. REF: AMM 32-31-02PROC. REF: AMM 32-31-02									
D3260006		NOSE LANDING GEAR SQUAT SWITCH ROTATING DISK ASSEMBLY - LUBRICATE						Service	ATA:32
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01									
F3220045		NOSE LANDING GEAR ACTUATOR ATTACHMENT FITTING - REPLACE						Service	ATA:32
	MOS/MSC	09-Mar-01	N/A					NOT INSTALLED	
	HRS	0							
	AFL	0							
PROC. REF: AMM 32-32-01PROC. REF: AMM 32-32-01									
J3220120		* MAIN LANDING GEAR TRUNNION SHEAR PIN BUSHING - PERFORM DETAILED VISUAL INSPECTION FOR BUSHING MIGRATION						Service	ATA:32
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
L3220020	* MAIN LANDING GEAR TRUNNION FITTINGS ON MID AND REAR SPAR - PERFORM EDDY CURRENT INSPECTION								Service ATA:32
	MOS	09-Mar-01						AIRWORTHINESS	
	HRS	0							
	AFL	0	T:10000		10000		2326		
PROC. REF: NDT PART 6/32-11-00PROC. REF: NDT PART 6/32-11-00									
L3220118	* RIGHT MAIN LANDING GEAR SHOCK STRUT CYLINDER - PERFORM ULTRASONIC INSPECTION OF THE LOWER SERVICE PORT AND FORGING PARTING LINE								Service ATA:32
PN:200-0201-010	MOS	25-Jun-26						AIRWORTHINESS	
SN:H0755	HRS	10023.1							
	AFL	7616	600		8216		542		
L3220122	* RIGHT MAIN LANDING GEAR SHOCK STRUT CYLINDER - PERFORM ULTRASONIC INSPECTION OF THE LOWER SERVICE PORT AND FORGING PARTING LINE								Service ATA:32
PN:200-0201-010	MOS/MSC	27-Nov-22	N/A						
SN:H0755	HRS	9163.6							
	AFL	7031							
PROC. REF: NDT PART 4/32-10-01, NDT PART 4/32-10-00PROC. REF: NDT PART 4/32-10-01, NDT PART 4/32-10-00									
M3220136	* RIGHT MAIN LANDING GEAR SHOCK STRUT CYLINDER - PERFORM ULTRASONIC INSPECTION OF THE LOWER SERVICE PORT AND FORGING PARTING LINE								Service ATA:32
PN:200-0201-010	MOS/MSC	27-Nov-22	N/A						
SN:H0755	HRS	9163.6							
	AFL	7031							
N3220036	* LEFT MAIN LANDING GEAR AXLE BEAM - REPLACE								Service ATA:32
PN:200-0203-001	MOS	08-Sep-12						LIFE LIMIT	
SN:H0331	HRS	6989.1							
	AFL	5335	10000	TAC 5311	10024		2350		
N3220036	* RIGHT MAIN LANDING GEAR AXLE BEAM - REPLACE								Service ATA:32
PN:200-0203-001	MOS	08-Sep-12						LIFE LIMIT	
SN:H0334	HRS	6989.1							
	AFL	5335	10000	TAC 5311	10024		2350		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
N3220041	* LEFT FORWARD LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE								Service ATA:32
PN:4532103201-001	MOS/MSC	15-Dec-10	N/A						
SN:CMI882	HRS	6457.2							
	AFL	4944							
N3220041	* LEFT FORWARD UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE								Service ATA:32
PN:4532103201-001	MOS/MSC	15-Dec-10	N/A						
SN:CMI806	HRS	6457.2							
	AFL	4944							
N3220041	* RIGHT FORWARD LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE								Service ATA:32
PN:4532103201-001	MOS/MSC	15-Dec-10	N/A						
SN:CMI1113	HRS	6457.2							
	AFL	4944							
N3220041	* RIGHT FORWARD UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE								Service ATA:32
PN:4532103201-001	MOS/MSC	15-Dec-10	N/A						
SN:CMI710	HRS	6457.2							
	AFL	4944							
N3220042	* LEFT AFT UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE								Service ATA:32
PN:4532103202-001	MOS/MSC	18-Dec-10	N/A						
SN:CMI371	HRS	6457.2							
	AFL	4944							
N3220042	* RIGHT AFT UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE								Service ATA:32
PN:4532103202-001	MOS/MSC	18-Dec-10	N/A						
SN:CMI363	HRS	6457.2							
	AFL	4944							

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
N3220043	* LEFT AFT LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE								Service ATA:32
PN:4532103203-001	MOS/MSC	18-Dec-10	N/A						
SN:CM1818	HRS	6457.2							
	AFL	4944							
N3220043	* RIGHT AFT LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE								Service ATA:32
PN:4532103203-001	MOS/MSC	18-Dec-10	N/A						
SN:CM1759	HRS	6457.2							
	AFL	4944							
N3220103	* LEFT MAIN LANDING GEAR ACTUATOR PISTON - REPLACE								Service ATA:32
PN:PN	MOS	09-Mar-01						LIFE LIMIT	
SN:UNKNOWN	HRS	0							
	AFL	0	17000		17000		9326		
N3220103	* RIGHT MAIN LANDING GEAR ACTUATOR PISTON - REPLACE								Service ATA:32
PN:4532101000V72-002	MOS	09-Mar-01						LIFE LIMIT	
SN:H1153	HRS	0							
	AFL	0	17000		17000		9326		
N3220104	* LEFT MAIN LANDING GEAR ACTUATOR CYLINDER - REPLACE								Service ATA:32
PN:4532101000V76-001	MOS	09-Mar-01						LIFE LIMIT	
SN:H0155	HRS	0							
	AFL	0	17000		17000		9326		
N3220104	* RIGHT MAIN LANDING GEAR ACTUATOR CYLINDER - REPLACE								Service ATA:32
PN:4532101000V72-002	MOS	09-Mar-01						LIFE LIMIT	
SN:H1153	HRS	0							
	AFL	0	17000		17000		9326		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 10101.4
 AFL: 7674
 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
N3220106	* LEFT MAIN LANDING GEAR ACTUATOR HOUSING - REPLACE								Service ATA:32
PN:200-0304-001	MOS	19-Dec-10						LIFE LIMIT	
SN:H1704	HRS	6457.2							
	AFL	4944	17000		21944		14270		
N3220106	* RIGHT MAIN LANDING GEAR ACTUATOR HOUSING - REPLACE								Service ATA:32
PN:4532101000V72-002	MOS	09-Mar-01						LIFE LIMIT	
SN:H1153	HRS	0							
	AFL	0	17000		17000		9326		
N3220116	* LEFT MAIN LANDING GEAR SHOCK STRUT CYLINDER - REPLACE								Service ATA:32
PN:200-0201-009	MOS	30-Mar-21						LIFE LIMIT	
SN:H0727	HRS	8414.4							
	AFL	6463	10000	TAC 1409	15054		7380		
N3220116	* RIGHT MAIN LANDING GEAR SHOCK STRUT CYLINDER - REPLACE								Service ATA:32
PN:200-0201-010	MOS	30-Mar-21						LIFE LIMIT	
SN:H0755	HRS	8414.4							
	AFL	6463	10000	TAC 1409	15054		7380		
N3220139	* LEFT FORWARD LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE								Service ATA:32
PN:4532103201-001	MOS	15-Dec-10						LIFE LIMIT	
SN:CM1882	HRS	6457.2							
	AFL	4944	5000		9944		2270		
N3220139	* LEFT FORWARD UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE								Service ATA:32
PN:4532103201-001	MOS	15-Dec-10						LIFE LIMIT	
SN:CM1806	HRS	6457.2							
	AFL	4944	5000		9944		2270		

?-Insufficient Information
 S-Suppressed Requirement
 *-Estimated Due(New Requirement)
 (EFF)-Effective C / W
 (M)-Manual Due
 U-User Task
 Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
N3220139	* RIGHT FORWARD LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE								Service ATA:32
PN:4532103201-001	MOS	15-Dec-10						LIFE LIMIT	
SN:CMI1113	HRS	6457.2							
	AFL	4944	5000		9944		2270		
N3220139	* RIGHT FORWARD UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE								Service ATA:32
PN:4532103201-001	MOS	15-Dec-10						LIFE LIMIT	
SN:CMI710	HRS	6457.2							
	AFL	4944	5000		9944		2270		
N3220140	* LEFT AFT UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE								Service ATA:32
PN:4532103202-001	MOS	18-Dec-10						LIFE LIMIT	
SN:CMI371	HRS	6457.2							
	AFL	4944	5000		9944		2270		
N3220140	* RIGHT AFT UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE								Service ATA:32
PN:4532103202-001	MOS	18-Dec-10						LIFE LIMIT	
SN:CMI363	HRS	6457.2							
	AFL	4944	5000		9944		2270		
N3220141	* LEFT AFT LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE								Service ATA:32
PN:4532103203-001	MOS	18-Dec-10						LIFE LIMIT	
SN:CMI818	HRS	6457.2							
	AFL	4944	5000		9944		2270		
N3220141	* RIGHT AFT LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE								Service ATA:32
PN:4532103203-001	MOS	18-Dec-10						LIFE LIMIT	
SN:CMI759	HRS	6457.2							
	AFL	4944	5000		9944		2270		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
P3220146	* RIGHT MAIN LANDING GEAR SHOCK STRUT CYLINDER - PERFORM ULTRASONIC INSPECTION OF THE FORGING PARTING LINE							Service	ATA:32
PN:200-0201-010	MOS/MSC	27-Nov-22	N/A						
SN:H0755	HRS	9163.6							
	AFL	7031							
PROC. REF: NDT PART 4/32-10-01, NDT PART 4/32-10-00PROC. REF: NDT PART 4/32-10-01, NDT PART 4/32-10-00									
P3231020	LEFT MAIN LANDING GEAR DOOR ACTUATOR GIMBAL ASSEMBLY - PERFORM EDDY CURRENT INSPECTION							Service	ATA:32
	MOS	25-Jun-26							
	HRS	10023.1							
	AFL	7616	300	Adj -40	7876		202		
PROC. REF: NDT PART 6/32-13-00PROC. REF: NDT PART 6/32-13-00									
P3231021	LEFT MAIN LANDING GEAR DOOR ACTUATOR GIMBAL SHAFT - PERFORM FLUORESCENT PENETRANT INSPECTION							Service	ATA:32
	MOS	25-Jun-26							
	HRS	10023.1							
	AFL	7616	300	Adj -40	7876		202		
PROC. REF: NDT PART 8/32-13-02PROC. REF: NDT PART 8/32-13-02									
Q3220065	* LEFT MAIN LANDING GEAR ACTUATOR PISTON - REPLACE							Service	ATA:32
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
Q3220065	* RIGHT MAIN LANDING GEAR ACTUATOR PISTON - REPLACE							Service	ATA:32
PN:4532101000V72-002	MOS/MSC	09-Mar-01	N/A						
SN:H1153	HRS	0							
	AFL	0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
Q3220066	* LEFT MAIN LANDING GEAR ACTUATOR CYLINDER - REPLACE							Service	ATA:32
PN:4532101000V76-001	MOS/MSC	09-Mar-01	N/A						
SN:H0155	HRS	0							
	AFL	0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
Q3220066	* RIGHT MAIN LANDING GEAR ACTUATOR CYLINDER - REPLACE								Service ATA:32
PN:4532101000V72-002	MOS/MSC	09-Mar-01	N/A						
SN:H1153	HRS	0							
	AFL	0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
Q3220068	* LEFT MAIN LANDING GEAR ACTUATOR HOUSING - REPLACE								Service ATA:32
PN:200-0304-001	MOS/MSC	19-Dec-10	N/A						
SN:H1704	HRS	6457.2							
	AFL	4944							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
Q3220068	* RIGHT MAIN LANDING GEAR ACTUATOR HOUSING - REPLACE								Service ATA:32
PN:4532101000V72-002	MOS/MSC	09-Mar-01	N/A						
SN:H1153	HRS	0							
	AFL	0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
Q3220128	* LEFT MAIN LANDING GEAR SHOCK STRUT CYLINDER - REPLACE								Service ATA:32
PN:200-0201-009	MOS/MSC	30-Mar-21	N/A						
SN:H0727	HRS	8414.4							
	AFL	6463							
Q3220128	* RIGHT MAIN LANDING GEAR SHOCK STRUT CYLINDER - REPLACE								Service ATA:32
PN:200-0201-010	MOS/MSC	30-Mar-21	N/A						
SN:H0755	HRS	8414.4							
	AFL	6463							
Q3220137	* LEFT MAIN LANDING GEAR SHOCK STRUT CYLINDER - REPLACE								Service ATA:32
PN:200-0201-009	MOS/MSC	30-Mar-21	N/A						
SN:H0727	HRS	8414.4							
	AFL	6463							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
Q3220137	* RIGHT MAIN LANDING GEAR SHOCK STRUT CYLINDER - REPLACE								Service ATA:32
PN:200-0201-010	MOS/MSC	30-Mar-21	N/A						
SN:H0755	HRS	8414.4							
	AFL	6463							
Q3220142	* LEFT FORWARD LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE								Service ATA:32
PN:4532103201-001	MOS/MSC	15-Dec-10	N/A						
SN:CMI882	HRS	6457.2							
	AFL	4944							
Q3220142	* LEFT FORWARD UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE								Service ATA:32
PN:4532103201-001	MOS/MSC	15-Dec-10	N/A						
SN:CMI806	HRS	6457.2							
	AFL	4944							
Q3220142	* RIGHT FORWARD LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE								Service ATA:32
PN:4532103201-001	MOS/MSC	15-Dec-10	N/A						
SN:CMI1113	HRS	6457.2							
	AFL	4944							
Q3220142	* RIGHT FORWARD UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE								Service ATA:32
PN:4532103201-001	MOS/MSC	15-Dec-10	N/A						
SN:CMI710	HRS	6457.2							
	AFL	4944							
Q3220143	* LEFT AFT UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE								Service ATA:32
PN:4532103202-001	MOS/MSC	18-Dec-10	N/A						
SN:CMI371	HRS	6457.2							
	AFL	4944							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
Q3220143	* RIGHT AFT UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE								Service ATA:32
PN:4532103202-001	MOS/MSC	18-Dec-10	N/A						
SN:CM1363	HRS	6457.2							
	AFL	4944							
Q3220144	* LEFT AFT LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE								Service ATA:32
PN:4532103203-001	MOS/MSC	18-Dec-10	N/A						
SN:CM1818	HRS	6457.2							
	AFL	4944							
Q3220144	* RIGHT AFT LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE								Service ATA:32
PN:4532103203-001	MOS/MSC	18-Dec-10	N/A						
SN:CM1759	HRS	6457.2							
	AFL	4944							
T3220007	* LEFT MAIN LANDING GEAR AXLE BEAM - PERFORM MAIN LANDING GEAR AXLE BEAM ASSEMBLY BORESCOPE INSPECTION								Service ATA:32
PN:200-0203-001	MOS	02-Aug-24	48		02-Aug-28		687 d	AIRWORTHINESS	
SN:H0331	HRS	9525.7							
	AFL	7276							
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
T3220007	* RIGHT MAIN LANDING GEAR AXLE BEAM - PERFORM MAIN LANDING GEAR AXLE BEAM ASSEMBLY BORESCOPE INSPECTION								Service ATA:32
PN:200-0203-001	MOS	02-Aug-24	48		02-Aug-28		687 d	AIRWORTHINESS	
SN:H0334	HRS	9525.7							
	AFL	7276							
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
T3220013	* LEFT MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY - REPLACE								Service ATA:32
PN:200-0300-003	MOS	02-Aug-24						LIFE LIMIT	
SN:H0134	HRS	9525.7							
	AFL	7276	17000	TAC 7276	17000		9326		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
T3220013	* RIGHT MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY - REPLACE								Service ATA:32
PN:200-0300-004	MOS	02-Aug-24						LIFE LIMIT	
SN:H1188	HRS	9525.7							
	AFL	7276	17000	TAC 7276	17000		9326		
T3220014	* LEFT MAIN LANDING GEAR ACTUATOR UPPER PIN - REPLACE								Service ATA:32
PN:200-0325-101	MOS	24-Jun-19	96	TAC 0	24-Jun-27		282 d	LIFE LIMIT	
SN:H2409	HRS	8101.1		TAC 0					
	AFL	6233		TAC 0					
PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01									
T3220014	* RIGHT MAIN LANDING GEAR ACTUATOR UPPER PIN - REPLACE								Service ATA:32
PN:200-0325-101	MOS	24-Jun-19	96	TAC 0	24-Jun-27		282 d	LIFE LIMIT	
SN:HER08U/5030	HRS	8101.1		TAC 0					
	AFL	6233		TAC 0					
PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01									
T3220024	* LEFT MAIN LANDING GEAR ACTUATOR LOWER PIN - PERFORM MAGNETIC PARTICLE INSPECTION								Service ATA:32
PN:200-0217-101	MOS	22-Jun-23	48		22-Jun-27		280 d	AIRWORTHINESS	
SN:H5000	HRS	9258.5							
	AFL	7100							
PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01									
T3220024	* LEFT MAIN LANDING GEAR ACTUATOR UPPER PIN - PERFORM MAGNETIC PARTICLE INSPECTION								Service ATA:32
PN:200-0325-101	MOS	22-Jun-23	48		22-Jun-27		280 d	AIRWORTHINESS	
SN:H2409	HRS	9258.5							
	AFL	7100							
PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01									
T3220024	* RIGHT MAIN LANDING GEAR ACTUATOR LOWER PIN - PERFORM MAGNETIC PARTICLE INSPECTION								Service ATA:32
PN:200-0217-101	MOS	22-Jun-23	48		22-Jun-27		280 d	AIRWORTHINESS	
SN:HER08U5014	HRS	9258.5							
	AFL	7100							
PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
T3220024	* RIGHT MAIN LANDING GEAR ACTUATOR UPPER PIN - PERFORM MAGNETIC PARTICLE INSPECTION								Service ATA:32
PN:200-0325-101	MOS	22-Jun-23	48		22-Jun-27		280 d	AIRWORTHINESS	
SN:HER08U/5030	HRS	9258.5							
	AFL	7100							
PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01									
T3220038	* LEFT MAIN LANDING GEAR ACTUATOR LOWER PIN - REPLACE								Service ATA:32
PN:200-0217-101	MOS	24-Jun-19	96	TAC 0	24-Jun-27		282 d	LIFE LIMIT	
SN:H5000	HRS	8101.1		TAC 0					
	AFL	6233		TAC 0					
PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01									
T3220038	* RIGHT MAIN LANDING GEAR ACTUATOR LOWER PIN - REPLACE								Service ATA:32
PN:200-0217-101	MOS	24-Jun-19	96	TAC 0	24-Jun-27		282 d	LIFE LIMIT	
SN:HER08U5014	HRS	8101.1		TAC 0					
	AFL	6233		TAC 0					
PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01									
T3220046	* LEFT MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY - REPLACE								Service ATA:32
PN:200-0300-003	MOS/MSC	02-Aug-24	N/A						
SN:H0134	HRS	9525.7							
	AFL	7276							
T3220046	* RIGHT MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY - REPLACE								Service ATA:32
PN:200-0300-004	MOS/MSC	02-Aug-24	N/A						
SN:H1188	HRS	9525.7							
	AFL	7276							
T3220063	* LEFT MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY, EXCLUDING THE END CAP - REPLACE								Service ATA:32
PN:200-0300-003	MOS/MSC	02-Aug-24	N/A						
SN:H0134	HRS	9525.7							
	AFL	7276							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
T3220063	* RIGHT MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY, EXCLUDING THE END CAP - REPLACE								Service ATA:32
PN:200-0300-004	MOS/MSC	02-Aug-24	N/A						
SN:H1188	HRS	9525.7							
	AFL	7276							
T3220064	* LEFT MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY, EXCLUDING THE END CAP - REPLACE								Service ATA:32
PN:200-0300-003	MOS/MSC	02-Aug-24	N/A						
SN:H0134	HRS	9525.7							
	AFL	7276							
T3220064	* LEFT MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY, EXCLUDING THE END CAP - REPLACE								Service ATA:32
PN:200-0300-004	MOS/MSC	02-Aug-24	N/A						
SN:H1188	HRS	9525.7							
	AFL	7276							
T3220067	* LEFT MAIN LANDING GEAR ACTUATOR END CAP - REPLACE								Service ATA:32
PN:200-0303-001	MOS/MSC	02-Aug-24	N/A						
SN:UNKNOWN	HRS	9525.7							
	AFL	7276							
T3220067	* RIGHT MAIN LANDING GEAR ACTUATOR END CAP - REPLACE								Service ATA:32
PN:200-0303-001	MOS/MSC	02-Aug-24	N/A						
SN:UNKNOWN	HRS	9525.7							
	AFL	7276							
T3220105	* LEFT MAIN LANDING GEAR ACTUATOR END CAP - REPLACE								Service ATA:32
PN:200-0303-001	MOS	02-Aug-24						LIFE LIMIT	
SN:UNKNOWN	HRS	9525.7							
	AFL	7276	2387		9663		1989		
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01									

? - Insufficient Information
S - Suppressed Requirement
* - Estimated Due(New Requirement)
(EFF) - Effective C / W
(M) - Manual Due
U - User Task
Ex - Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
T3220105	* RIGHT MAIN LANDING GEAR ACTUATOR END CAP - REPLACE								Service ATA:32
PN:200-0303-001	MOS	02-Aug-24						LIFE LIMIT	
SN:UNKNOWN	HRS	9525.7							
	AFL	7276	2387		9663		1989		
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01									
T3220135	* LEFT MAIN LANDING GEAR ACTUATOR LOWER PIN - PERFORM DETAILED VISUAL INSPECTION								Service ATA:32
PN:200-0217-101	MOS	22-Jun-23	48		22-Jun-27		280 d	AIRWORTHINESS	
SN:H5000	HRS	9258.5							
	AFL	7100							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
T3220135	* LEFT MAIN LANDING GEAR ACTUATOR UPPER PIN - PERFORM DETAILED VISUAL INSPECTION								Service ATA:32
PN:200-0325-101	MOS	22-Jun-23	48		22-Jun-27		280 d	AIRWORTHINESS	
SN:H2409	HRS	9258.5							
	AFL	7100							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
T3220135	* RIGHT MAIN LANDING GEAR ACTUATOR LOWER PIN - PERFORM DETAILED VISUAL INSPECTION								Service ATA:32
PN:200-0217-101	MOS	22-Jun-23	48		22-Jun-27		280 d	AIRWORTHINESS	
SN:HER08U5014	HRS	9258.5							
	AFL	7100							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
T3220135	* RIGHT MAIN LANDING GEAR ACTUATOR UPPER PIN - PERFORM DETAILED VISUAL INSPECTION								Service ATA:32
PN:200-0325-101	MOS	22-Jun-23	48		22-Jun-27		280 d	AIRWORTHINESS	
SN:HER08U/5030	HRS	9258.5							
	AFL	7100							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
T3220147	* LEFT AFT LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN - PERFORM VISUAL INSPECTION FOR PIN MIGRATION								Service ATA:32
	MOS/MSC		N/A						
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
T3220147	* LEFT AFT UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN - PERFORM VISUAL INSPECTION FOR PIN MIGRATION							Service	ATA:32
	MOS/MSC		N/A						
	HRS								
	AFL								
T3220147	* LEFT FORWARD LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN - PERFORM VISUAL INSPECTION FOR PIN MIGRATION							Service	ATA:32
	MOS/MSC		N/A						
	HRS								
	AFL								
T3220147	* LEFT FORWARD UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN - PERFORM VISUAL INSPECTION FOR PIN MIGRATION							Service	ATA:32
	MOS/MSC		N/A						
	HRS								
	AFL								
T3220147	* RIGHT AFT LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN - PERFORM VISUAL INSPECTION FOR PIN MIGRATION							Service	ATA:32
	MOS/MSC		N/A						
	HRS								
	AFL								
T3220147	* RIGHT AFT UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN - PERFORM VISUAL INSPECTION FOR PIN MIGRATION							Service	ATA:32
	MOS/MSC		N/A						
	HRS								
	AFL								
T3220147	* RIGHT FORWARD LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN - PERFORM VISUAL INSPECTION FOR PIN MIGRATION							Service	ATA:32
	MOS/MSC		N/A						
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
T3220147	* RIGHT FORWARD UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN - PERFORM VISUAL INSPECTION FOR PIN MIGRATION							Service	ATA:32
	MOS/MSC		N/A						
	HRS								
	AFL								
V3220022	LEFT AFT MAIN LANDING GEAR TRUNNION PIN - PERFORM MAGNETIC PARTICLE INSPECTION							Service	ATA:32
PN:200-0213-103	MOS	30-Mar-21	96		30-Mar-29		927 d		
SN:H0364	HRS	8414.4							
	AFL	6463							
PROC. REF: NDT PART 7/32-10-07, NDT PART 7/32-10-08PROC. REF: NDT PART 7/32-10-07, NDT PART 7/32-10-08									
V3220022	LEFT FORWARD MAIN LANDING GEAR TRUNNION PIN - PERFORM MAGNETIC PARTICLE INSPECTION							Service	ATA:32
PN:200-0212-103	MOS	30-Mar-21	96		30-Mar-29		927 d		
SN:H0501	HRS	8414.4							
	AFL	6463							
PROC. REF: NDT PART 7/32-10-07, NDT PART 7/32-10-08PROC. REF: NDT PART 7/32-10-07, NDT PART 7/32-10-08									
V3220022	RIGHT AFT MAIN LANDING GEAR TRUNNION PIN - PERFORM MAGNETIC PARTICLE INSPECTION							Service	ATA:32
PN:200-0213-103	MOS	30-Mar-21	96		30-Mar-29		927 d		
SN:H0338	HRS	8414.4							
	AFL	6463							
PROC. REF: NDT PART 7/32-10-07, NDT PART 7/32-10-08PROC. REF: NDT PART 7/32-10-07, NDT PART 7/32-10-08									
V3220022	RIGHT FORWARD MAIN LANDING GEAR TRUNNION PIN - PERFORM MAGNETIC PARTICLE INSPECTION							Service	ATA:32
PN:200-0212-103	MOS	30-Mar-21	96		30-Mar-29		927 d		
SN:H0473	HRS	8414.4							
	AFL	6463							
PROC. REF: NDT PART 7/32-10-07, NDT PART 7/32-10-08PROC. REF: NDT PART 7/32-10-07, NDT PART 7/32-10-08									
V3240004 ^S	** EMERGENCY/PARKING BRAKE SWITCH - VERIFY THAT "EMERGENCY/PARKING BRAKE" MESSAGE ILLUMINATES ON EICAS WHEN PARKING BRAKE IS SET AND THROTTLES ARE MOVED ABOVE MCR DETENT.							Service	ATA:32
	MOS	25-Jun-26	24					AIRWORTHINESS	
	HRS	10023.1	600						
	AFL	7616							
PROC. REF: AMM 32-42-01PROC. REF: AMM 32-42-01									
PKG:11									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 10101.4
 AFL: 7674
 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
V3240008	^S	** EMERGENCY/PARKING BRAKE CONTROL SYSTEM - PERFORM FUNCTIONAL TEST						Service	ATA:32
	MOS	25-Jun-26	24					AIRWORTHINESS	
	HRS	10023.1	600						
	AFL	7616							
PROC. REF: AMM 32-42-02PROC. REF: AMM 32-42-02									
W3220149		* LEFT MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY - REPLACE						Service	ATA:32
PN:200-0300-003	MOS/MSC	02-Aug-24	N/A						
SN:H0134	HRS	9525.7							
	AFL	7276							
W3220149		* RIGHT MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY - REPLACE						Service	ATA:32
PN:200-0300-004	MOS/MSC	02-Aug-24	N/A						
SN:H1188	HRS	9525.7							
	AFL	7276							
W3220150		* LEFT MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY - REPLACE						Service	ATA:32
PN:200-0300-003	MOS/MSC	02-Aug-24	N/A						
SN:H0134	HRS	9525.7							
	AFL	7276							
W3220150		* RIGHT MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY - REPLACE						Service	ATA:32
PN:200-0300-004	MOS/MSC	02-Aug-24	N/A						
SN:H1188	HRS	9525.7							
	AFL	7276							
W3231022		LEFT MAIN LANDING GEAR INBOARD DOOR GIMBAL BRACKET - PERFORM EDDY CURRENT INSPECTION						Service	ATA:32
	MOS	25-Jun-26							
	HRS	10023.1							
	AFL	7616	300	Adj -40	7876		202		
PROC. REF: NDT PART 6/32-13-01PROC. REF: NDT PART 6/32-13-01									

?-Insufficient Information
 S-Suppressed Requirement
 *-Estimated Due(New Requirement)
 (EFF)-Effective C / W
 (M)-Manual Due
 U-User Task
 Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
Y3220000	^S	NOSE LANDING GEAR ASSEMBLY - PERFORM VISUAL INSPECTION						Service	ATA:32
	MOS	25-Jun-26	24						
	HRS	10023.1	600						
	AFL	7616							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:11
Y3220001	^S	MAIN LANDING GEAR ASSEMBLY - PERFORM VISUAL INSPECTION. INSPECTION TO INCLUDE ACTUATOR, FASTENERS, SUPPORT STRUCTURE, AND SQUAT SWITCHES.						Service	ATA:32
	MOS	25-Jun-26	24						
	HRS	10023.1	600						
	AFL	7616							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:11
Y3220002	^S	NOSE LANDING GEAR ACTUATOR PRESSURE AND RETURN LINES - PERFORM VISUAL INSPECTION. LOWER ACTUATOR DUST BOOT TO INSPECT LINES.						Service	ATA:32
	MOS	25-Jun-26	24						
	HRS	10023.1	600						
	AFL	7616							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:11
Y3220003	^S	NOSE GEAR SHOCK STRUT - REMOVE AND REPLACE RETAINER RING LOCKSCREW						Service	ATA:32
	MOS	25-Jun-26	24						
	HRS	10023.1	600						
	AFL	7616							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:11
Y3220004	^S	MAIN LANDING GEAR ACTUATOR AND GEAR INBOARD DOOR ACTUATOR ATTACH POINTS - PERFORM VISUAL INSPECTION						Service	ATA:32
	MOS	25-Jun-26	24						
	HRS	10023.1	600						
	AFL	7616							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:11

? - Insufficient Information
S - Suppressed Requirement
* - Estimated Due (New Requirement)
(EFF) - Effective C / W
(M) - Manual Due
U - User Task
Ex - Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
Y3220006 ^S		LANDING GEAR ELECTRICAL WIRING - PERFORM VISUAL INSPECTION (THAT PORTION VISIBLE INSIDE WHEEL WELL)						Service	ATA:32
	MOS	25-Jun-26	24						
	HRS	10023.1	600						
	AFL	7616							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:11
Y3220008 ^S		NOSE LANDING GEAR AXLE - REMOVE NOSE LANDING GEAR WHEEL AND PERFORM INSPECTION. INSPECT BOTH INSIDE AND OUTSIDE OF AXLE.						Service	ATA:32
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 32-40-01PROC. REF: AMM 32-40-01									PKG:17
Y3220124 ^S		NOSE LANDING GEAR - PERFORM DETAILED VISUAL INSPECTION OF THE NOSE LANDING GEAR UPLOCK ROLLER BRACKET						Service	ATA:32
	MOS	25-Jun-26	24						
	HRS	10023.1	600						
	AFL	7616							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:11
Y3230002 ^S		MAIN LANDING GEAR FREE FALL ROLLER - PERFORM VISUAL INSPECTION. PAY PARTICULAR ATTENTION TO BINDING OF ROLLERS.						Service	ATA:32
	MOS	25-Jun-26	12						
	HRS	10023.1	300						
	AFL	7616							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:5
Y3231023 ^S		MAIN LANDING GEAR INBOARD DOOR ACTUATOR (PART NUMBER 7469) END CAP SCREWS - PERFORM DETAILED INSPECTION						Service	ATA:32
	MOS	25-Jun-26	12						
	HRS	10023.1	300						
	AFL	7616							
PROC. REF: AMM 32-31-02PROC. REF: AMM 32-31-02									PKG:5

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
Y3240000	^S	NOSE AND MAIN TIRES - PERFORM VISUAL INSPECTION						Service	ATA:32
	MOS	25-Jun-26	12						
	HRS	10023.1	300						
	AFL	7616							
PROC. REF: AMM 12-10-04PROC. REF: AMM 12-10-04									PKG:5
Y3240001	^S	BRAKE LINES - PERFORM VISUAL INSPECTION. INSPECT ALL BRAKE LINES VISIBLE IN WHEEL WELLS AND ON STRUTS.						Service	ATA:32
	MOS	25-Jun-26	24						
	HRS	10023.1	600						
	AFL	7616							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:11
Y3240002	^S	BRAKE ASSEMBLIES - PERFORM VISUAL INSPECTION WITH PARKING BRAKE SET. WORN BRAKES ARE VISUALLY INDICATED WHEN THE WEAR INDICATOR PINS BECOME EVEN WITH THE OUTER SURFACE OF THE WEAR INDICATOR SLEEVE.						Service	ATA:32
	MOS	25-Jun-26	12						
	HRS	10023.1	300						
	AFL	7616							
PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01									PKG:5
Y3240003	^S	BRAKE CONTROL SYSTEM LINEAR VARIABLE DIFFERENTIAL TRANSFORMER (LVDT) - PERFORM VISUAL INSPECTION						Service	ATA:32
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:13
Y3260005	^S	NOSE LANDING GEAR SQUAT SWITCH ROTATING DISK ASSEMBLY - LUBRICATE						Service	ATA:32
	MOS	25-Jun-26	12						
	HRS	10023.1	300						
	AFL	7616							
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01									PKG:5

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C / W
(M)-Manual Due
U-User Task
Ex-Excluded Task

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 33 - LIGHTS									
330000	MODIFIED PULSE CONTROLLER							Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
331001	NO. 1 COCKPIT LIGHTING CONTROL UNIT							Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-10-06PROC. REF: AMM 33-10-06									
331002	NO. 2 COCKPIT LIGHTING CONTROL UNIT							Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-10-06PROC. REF: AMM 33-10-06									
331010	PILOT FORWARD SWITCH PANEL OVERLAY							Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-10-05PROC. REF: AMM 33-10-05									
331011	PILOT SWITCH PANEL							Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
331012	COPILOT FORWARD SWITCH PANEL OVERLAY							Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-10-05PROC. REF: AMM 33-10-05									

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C / W
(M)-Manual Due
U-User Task
Ex-Excluded Task

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 33 - LIGHTS									
331013	COPILOT FORWARD SWITCH PANEL							Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
331015	CENTER SWITCH PANEL (P5)							Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
331016	CENTER SWITCH PANEL (P5) OVERLAY							Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-10-05PROC. REF: AMM 33-10-05									
331017	THROTTLE QUADRANT OVERLAY PANEL							Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
331018	PILOT AFT CIRCUIT BREAKER PANEL OVERLAY							Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-10-05PROC. REF: AMM 33-10-05									
331019	COPILOT AFT CIRCUIT BREAKER PANEL OVERLAY							Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-10-05PROC. REF: AMM 33-10-05									

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 33 - LIGHTS									
331020	DIMMER CONTROL BOX							Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-10-10PROC. REF: AMM 33-10-10									
331023	GLARESHIELD FLOOR FLOODLIGHTS INVERTER							Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
331025	COCKPIT MISCELLANEOUS RELAY BOX							Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-10-07PROC. REF: AMM 33-10-07									
331030	CENTER SWITCH PANEL DIODE BOX (P12)							Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-10-08PROC. REF: AMM 33-10-08									
331033	GLARESHIELD FLOODLIGHT POWER SUPPLY							Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
331040	PILOT REVERSION PANEL OVERLAY (DS55)							Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 10101.4
 AFL: 7674
 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 33 - LIGHTS									
331101	P35 FUSE PANEL							Component	ATA:33
PN:4533108552-007	MOS/MSC	17-Feb-05	O/C						
SN:MRP644283-001	HRS	3300.2							
	AFL	2515							
PROC. REF: AMM 33-10-09PROC. REF: AMM 33-10-09									
331401-1	NO. 1 LEFT POWER SUPPLY INVERTER (PS5009)							Component	ATA:33
PN:AL-2000	MOS/MSC	11-Apr-05	O/C						
SN:46634	HRS	3496.3							
	AFL	2649							
PROC. REF: AMM 33-20-10PROC. REF: AMM 33-20-10									
331401-10	NO. 5 RIGHT POWER SUPPLY INVERTER (PS5006)							Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-20-10PROC. REF: AMM 33-20-10									
331401-11	NO. 6 LEFT POWER SUPPLY INVERTER (LAVATORY) (PS5010)							Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-20-10PROC. REF: AMM 33-20-10									
331401-2	NO. 1 RIGHT POWER SUPPLY INVERTER (PS5003)							Component	ATA:33
PN:AL-2000	MOS/MSC	11-Apr-05	O/C						
SN:46632	HRS	3496.3							
	AFL	2649							
PROC. REF: AMM 33-20-10PROC. REF: AMM 33-20-10									
331401-3	NO. 2 LEFT POWER SUPPLY INVERTER (PS5008)							Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-20-10PROC. REF: AMM 33-20-10									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 33 - LIGHTS									
331401-4	NO. 2 RIGHT POWER SUPPLY INVERTER (PS5004)							Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-20-10PROC. REF: AMM 33-20-10									
331401-5	NO. 3 LEFT POWER SUPPLY INVERTER (PS5007)							Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-20-10PROC. REF: AMM 33-20-10									
331401-6	NO. 3 RIGHT POWER SUPPLY INVERTER (PS5005)							Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-20-10PROC. REF: AMM 33-20-10									
331401-7	NO. 4 LEFT POWER SUPPLY INVERTER (PS5006)							Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-20-10PROC. REF: AMM 33-20-10									
331401-8	NO. 4 RIGHT POWER SUPPLY INVERTER (LAVATORY) (PS5010)							Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-20-10PROC. REF: AMM 33-20-10									
331401-9	NO. 5 LEFT POWER SUPPLY INVERTER (LAVATORY) (PS5011)							Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-20-10PROC. REF: AMM 33-20-10									

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C / W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 10101.4
 AFL: 7674
 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 33 - LIGHTS									
332001	RIGHT NO. 1 PASSENGER LIGHTING CONTROL UNIT								Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-20-05PROC. REF: AMM 33-20-05									
332002	RIGHT NO. 2 PASSENGER LIGHTING CONTROL UNIT								Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-20-05PROC. REF: AMM 33-20-05									
332003	RIGHT NO. 3 PASSENGER LIGHTING CONTROL UNIT								Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-20-05PROC. REF: AMM 33-20-05									
332004	RIGHT NO. 4 PASSENGER LIGHTING CONTROL UNIT								Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-20-05PROC. REF: AMM 33-20-05									
332005	LEFT NO. 1 PASSENGER LIGHTING CONTROL UNIT								Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-20-05PROC. REF: AMM 33-20-05									
332006	LEFT NO. 2 PASSENGER LIGHTING CONTROL UNIT								Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-20-05PROC. REF: AMM 33-20-05									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 33 - LIGHTS									
332007	LEFT NO. 3 PASSENGER LIGHTING CONTROL UNIT							Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-20-05PROC. REF: AMM 33-20-05									
332008	LEFT NO. 4 PASSENGER LIGHTING CONTROL UNIT							Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-20-05PROC. REF: AMM 33-20-05									
332030	LAVATORY NO SMOKING / RETURN TO SEAT SIGN CONTROL UNIT (DS138)							Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-20-11PROC. REF: AMM 33-20-11									
332068	COPILOT LIGHTING CONTROL MODULE							Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-20-02PROC. REF: AMM 33-20-02									
332404	ENTRYWAY CONTROL LIGHT PANEL							Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-20-01PROC. REF: AMM 33-20-01									
334011	LEFT LANDING AND TAXI LIGHT							Component	ATA:33
PN:GE4587	MOS/MSC	17-Feb-22	O/C	TSN 0					
SN:UNKNOWN	HRS	8864.4		TSN 0					
	AFL	6822		TSN 0					
PROC. REF: AMM 33-40-04PROC. REF: AMM 33-40-04									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 33 - LIGHTS									
334012	RIGHT LANDING AND TAXI LIGHT							Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-40-04PROC. REF: AMM 33-40-04									
334021	LEFT NAVIGATION LIGHT (DS37)							Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-40-02PROC. REF: AMM 33-40-02									
334022	RIGHT NAVIGATION LIGHT (DS38)							Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-40-02PROC. REF: AMM 33-40-02									
334023	TAIL NAVIGATION LIGHT (DS39)							Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-40-02PROC. REF: AMM 33-40-02									
334041	COPILOT REVERSION PANEL OVERLAY (DS56)							Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
334175	RELAY OPTIONS PANEL							Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 33 - LIGHTS									
334332	UPPER ANTI-COLLISION LIGHT							Component	ATA:33
PN:GE16386-12-1	MOS/MSC	25-Jun-26	O/C	TSO 0					
SN:AF3036	HRS	10023.1		TSO 0					
	AFL	7616		TSO 0					
PROC. REF: AMM 33-40-01PROC. REF: AMM 33-40-01									
334333	LOWER ANTI-COLLISION LIGHT							Component	ATA:33
PN:GE-16386-12-1	MOS/MSC	22-Dec-08	O/C						
SN:AA2591	HRS	6088.7							
	AFL	4660							
PROC. REF: AMM 33-40-01PROC. REF: AMM 33-40-01									
335005	FORWARD ELS ACTIVATION MODULE (A81)							Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-50-01PROC. REF: AMM 33-50-01									
335006	AFT ELS ACTIVATION MODULE (A82)							Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-50-01PROC. REF: AMM 33-50-01									
336001	PILOT CHART HOLDER							Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
336002	COPILOT CHART HOLDER							Component	ATA:33
PN:10-62-01	MOS/MSC	17-Feb-05	O/C						
SN:3357	HRS	3300.2							
	AFL	2515							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C / W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 33 - LIGHTS									
336003	PILOT MAP LIGHT							Component	ATA:33
PN:0204327-001	MOS/MSC	12-Dec-11	O/C	TSN 0					
SN:542319	HRS	6763.5		TSN 0					
	AFL	5158		TSN 0					
PROC. REF: AMM 33-10-01PROC. REF: AMM 33-10-01									
336004	COPILOT MAP LIGHT							Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-10-01PROC. REF: AMM 33-10-01									
Y3310000 ^S	FLIGHT COMPARTMENT LIGHTING - PERFORM OPERATIONAL CHECK OF THE FOLLOWING: A. MAP LIGHTS. B. INSTRUMENT PANEL FLUORESCENT LIGHTS. C. INSTRUMENT/INDICATOR LIGHTS. D. LIGHT DIMMING SWITCHES. E. CREW WARNING PANEL. F. PANEL OVERLAYS.							Service	ATA:33
	MOS	25-Jun-26	12						
	HRS	10023.1	300						
	AFL	7616							
PROC. REF: AMM 33-10-00PROC. REF: AMM 33-10-00									
Y3340000 ^S	EXTERIOR LIGHTING SYSTEMS - PERFORM OPERATION CHECK OF THE FOLLOWING: A. TAXI LIGHTS. B. ANTI-COLLISION BEACONS. C. NAVIGATION LIGHTS. D. STROBE LIGHTS. E. LANDING/RECOGNITION LIGHTS. F. WING ICE INSPECTION LIGHTS. G. EMERGENCY DOOR EGRESS LIGHTS.							Service	ATA:33
	MOS	25-Jun-26	12						
	HRS	10023.1	300						
	AFL	7616							
PROC. REF: AMM 33-40-00, AMM 33-41-00PROC. REF: AMM 33-40-00, AMM 33-41-00									
Y3350003 ^S	EMERGENCY LIGHTING SYSTEM - PERFORM OPERATIONAL CHECK							Service	ATA:33
	MOS	22-Jun-23	48						
	HRS	9258.5	1200						
	AFL	7100							
PROC. REF: AMM 33-50-00PROC. REF: AMM 33-50-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
34-00-FAR-91.171	CHECK VOR EQUIPMENT FOR IFR OPERATIONS FAR 91.171								Service ATA:34
	MOS/MSC	09-Mar-01	O/C						
	HRS	0							
	AFL	0							
PROC. REF: GENERIC NO REF, FAR FAR 91.171PROC. REF: GENERIC NO REF, FAR FAR 91.171									
341001	NO. 1 AIR DATA COMPUTER								Component ATA:34
PN:7014700-606	MOS/MSC	30-Apr-19	O/C						
SN:99072942	HRS	8080.6							
	AFL	6214							
PROC. REF: AMM 34-17-01PROC. REF: AMM 34-17-01									
341001A	TEST/INSPECT NO. 1 AIR DATA COMPUTER								Service ATA:34
PN:7014700-606	MOS	24-Aug-26	24		16-Aug-28		701 d		
SN:99072942	HRS	10074							
	AFL	7658							
Calibration Date: : 16-Aug-26									
PROC. REF: FAR FAR 91.411, AMM 34-17-00, CFR 14 CFR PART 43 APP EPROC. REF: FAR FAR 91.411, AMM 34-17-00, CFR 14 CFR PART 43 APP E									
341002	NO. 2 AIR DATA COMPUTER								Component ATA:34
PN:7014700-606	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:01014560	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-17-01PROC. REF: AMM 34-17-01									
341002A	TEST/INSPECT NO. 2 AIR DATA COMPUTER								Service ATA:34
PN:7014700-606	MOS	24-Aug-26	24		16-Aug-28		701 d		
SN:01014560	HRS	10074							
	AFL	7658							
Calibration Date: : 16-Aug-26									
PROC. REF: FAR FAR 91.411, AMM 34-17-00, CFR 14 CFR PART 43 APP EPROC. REF: FAR FAR 91.411, AMM 34-17-00, CFR 14 CFR PART 43 APP E									
341013	STANDBY AIRSPEED INDICATOR								Component ATA:34
PN:6634208002-003	MOS/MSC	17-Dec-05	O/C						
SN:274205	HRS	4110.78							
	AFL	3119							
PROC. REF: AMM 34-18-01PROC. REF: AMM 34-18-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
341025	STANDBY ALTIMETER							Component	ATA:34
PN:7634208001-003	MOS/MSC	10-Aug-24	O/C						
SN:1722323	HRS								
	AFL								
PROC. REF: AMM 34-15-01PROC. REF: AMM 34-15-01									
341025A	TEST/INSPECT STANDBY ALTIMETER							Service	ATA:34
PN:7634208001-003	MOS	24-Aug-26	24		16-Aug-28		701 d		
SN:1722323	HRS	10074							
	AFL	7658							
Calibration Date: : 16-Aug-26									
PROC. REF: FAR FAR 91.411, AMM 34-15-01, CFR 14 CFR PART 43 APP EPROC. REF: FAR FAR 91.411, AMM 34-15-01, CFR 14 CFR PART 43 APP E									
341037	LEFT PRIMARY PITOT/STATIC PROBE							Component	ATA:34
PN:0856TJ1	MOS	17-Aug-18		TSN 0				LIFE LIMIT	
SN:308640	HRS	7915.5	15000	TSN 0	22915.5		12814.1		
	AFL	6079		TSN 0					
PROC. REF: AMM 34-11-01PROC. REF: AMM 34-11-01									
341037A	LEFT PRIMARY PITOT/STATIC PROBE - PERFORM NATIONALLY REQUIRED EQUIPMENT TESTS AND INSPECTIONS							Service	ATA:34
PN:0856TJ1	MOS	24-Aug-26	24		24-Aug-28		709 d		
SN:308640	HRS	10074							
	AFL	7658							
PROC. REF: GENERIC NO REF, FAR FAR 91.411, CFR 14 CFR PART 43 APP EPROC. REF: GENERIC NO REF, FAR FAR 91.411, CFR 14 CFR PART 43 APP E									
341038	RIGHT PRIMARY PITOT/STATIC PROBE							Component	ATA:34
PN:6634100000-003	MOS	09-Dec-24						LIFE LIMIT	
SN:276891	HRS	9574.3	15000	TSN 7559.6	17014.7		6913.3		
	AFL	7315		TSN 7118					
PROC. REF: AMM 34-11-01PROC. REF: AMM 34-11-01									
341038A	RIGHT PRIMARY PITOT/STATIC PROBE - PERFORM NATIONALLY REQUIRED EQUIPMENT TESTS AND INSPECTIONS							Service	ATA:34
PN:6634100000-003	MOS	09-Dec-24	24		09-Dec-26		85 d		
SN:276891	HRS	9574.3							
	AFL	7315							
PROC. REF: FAR FAR 91.411, AMM 34-11-00, CFR 14 CFR PART 43 APP EPROC. REF: FAR FAR 91.411, AMM 34-11-00, CFR 14 CFR PART 43 APP E									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
341049	STANDBY PITOT/STATIC PROBE							Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-11-01PROC. REF: AMM 34-11-01									
341049A	TEST/INSPECT STANDBY PITOT/STATIC PROBE							Service	ATA:34
	MOS	24-Aug-26	24		24-Aug-28		709 d		
	HRS	10074							
	AFL	7658							
PROC. REF: FAR FAR 91.411, AMM 34-11-00, CFR 14 CFR PART 43 APP EPROC. REF: FAR FAR 91.411, AMM 34-11-00, CFR 14 CFR PART 43 APP E									
341061	RADAR ALTIMETER RECEIVER							Component	ATA:34
PN:7001840-937	MOS/MSC	18-Oct-24	O/C						
SN:99118031	HRS	9555.2							
	AFL	7301							
PROC. REF: AMM 34-14-01PROC. REF: AMM 34-14-01									
341073	FORWARD RADAR ALTIMETER ANTENNA							Component	ATA:34
PN:S67-2002-4	MOS/MSC	14-Jul-07	O/C						
SN:552-14361	HRS	5618.1							
	AFL	4293							
PROC. REF: AMM 34-14-02PROC. REF: AMM 34-14-02									
341074	AFT RADAR ALTIMETER ANTENNA							Component	ATA:34
PN:S67-2002-4	MOS/MSC	14-Jul-07	O/C						
SN:552-13054	HRS	5618.1							
	AFL	4293							
PROC. REF: AMM 34-14-02PROC. REF: AMM 34-14-02									
3413-RVSM	FLIGHT CHECK ALTITUDE ALERTER FUNCTION. RVSM COMPLIANT AIRCRAFT.							Service	ATA:34
	MOS/MSC	09-Mar-01	N/R						
	HRS	0							
	AFL	0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
341901	TOTAL AIR TEMPERATURE PROBE (TAT)							Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-17-02PROC. REF: AMM 34-17-02									
342001	NO. 1 ATTITUDE HEADING REFERENCE COMPUTER (AHRS)							Component	ATA:34
PN:145130-6000	MOS/MSC	21-Mar-22	O/C						
SN:5001	HRS	8909							
	AFL	6851							
PROC. REF: AMM 34-26-01PROC. REF: AMM 34-26-01									
342002	NO. 2 ATTITUDE HEADING REFERENCE COMPUTER (AHRS)							Component	ATA:34
PN:HG2010AC02	MOS/MSC	10-Feb-09	O/C						
SN:99031032	HRS	6104.7							
	AFL								
PROC. REF: AMM 34-26-01PROC. REF: AMM 34-26-01									
342003	NO. 1 ATTITUDE HEADING REFERENCE COMPUTER FAN (AHRS)							Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-26-03PROC. REF: AMM 34-26-03									
342004	NO. 2 ATTITUDE HEADING REFERENCE COMPUTER FAN (AHRS)							Component	ATA:34
PN:26012423-105	MOS/MSC	10-Aug-12	O/C						
SN:10396	HRS	6975.7							
	AFL	5322							
PROC. REF: AMM 34-26-03PROC. REF: AMM 34-26-03									
342037	LEFT FLUX VALVE							Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-26-02PROC. REF: AMM 34-26-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
342038	RIGHT FLUX VALVE							Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-26-02PROC. REF: AMM 34-26-02									
342101	DUAL ANGLE OF ATTACK INDICATOR							Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
342103	STANDBY COMPASS							Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-21-01PROC. REF: AMM 34-21-01									
342103A	CALIBRATION CHECK STANDBY COMPASS							Service	ATA:34
PN:PN	MOS/MSC	09-Mar-01	A/R						
SN:UNKNOWN	HRS	0							
	AFL	0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
342701	LEFT ATTITUDE HEADING REFERENCE SYSTEM MEMORY MODULE (AHRS)							Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-26-01PROC. REF: AMM 34-26-01									
342702	RIGHT ATTITUDE HEADING REFERENCE SYSTEM MEMORY MODULE (AHRS)							Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-26-01PROC. REF: AMM 34-26-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 10101.4
 AFL: 7674
 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
342801	STANDBY ATTITUDE INDICATOR							Component	ATA:34
PN:501-1648-02	MOS/MSC	12-Sep-22	O/C						
SN:1338	HRS	9101.8							
	AFL	6994							
PROC. REF: AMM 34-23-01PROC. REF: AMM 34-23-01									
343005	MARKER BEACON ANTENNA							Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-30-01PROC. REF: AMM 34-30-01									
343008	UPPER GLIDESCOPE ANTENNA (E11)							Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-30-02PROC. REF: AMM 34-30-02									
343009	LOWER GLIDESCOPE ANTENNA (E12)							Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-30-02PROC. REF: AMM 34-30-02									
343030	MARKER BEACON ANTENNA SPLITTER							Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-30-03PROC. REF: AMM 34-30-03									
344111	UPPER TCAS ANTENNA							Component	ATA:34
PN:071-01548-0100	MOS/MSC	29-Jul-26	O/C						
SN:8976	HRS	10054.4							
	AFL	7641							
PROC. REF: AMM 34-43-02PROC. REF: AMM 34-43-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 10101.4
 AFL: 7674
 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
344112	LOWER TCAS ANTENNA							Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-43-02PROC. REF: AMM 34-43-02									
344143	TCAS PROCESSOR							Component	ATA:34
PN:066-01146-1211	MOS/MSC	13-Jul-26	O/C						
SN:10934	HRS	10035.6							
	AFL	7624							
PROC. REF: AMM 34-43-01PROC. REF: AMM 34-43-01									
344155	TCAS RELAY BOX ASSEMBLY							Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-43-03PROC. REF: AMM 34-43-03									
344167	TCAS CONFIGURATION MODULE							Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
344171	NO. 1 TCAS UPPER ANTENNA CABLE							Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
344172	NO. 2 TCAS UPPER ANTENNA CABLE							Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
344173	NO. 3 TCAS UPPER ANTENNA CABLE							Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
344174	NO. 4 TCAS UPPER ANTENNA CABLE							Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
344176	UPPER TCAS ADAPTER ASSEMBLY							Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
344177	LOWER TCAS ADAPTER ASSEMBLY							Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
344181	NO. 1 TCAS LOWER ANTENNA CABLE							Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
344182	NO. 2 TCAS LOWER ANTENNA CABLE							Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information
 S-Suppressed Requirement
 *-Estimated Due(New Requirement)
 (EFF)-Effective C / W
 (M)-Manual Due
 U-User Task
 Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
344183	NO. 3 TCAS LOWER ANTENNA CABLE							Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
344184	NO. 4 TCAS LOWER ANTENNA CABLE							Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
344205	WEATHER RADAR RECEIVER/TRANSMITTER/ANTENNA							Component	ATA:34
PN:7021450-601	MOS/MSC	11-Aug-09	O/C						
SN:07067540	HRS	6169.3							
	AFL	4725							
PROC. REF: AMM 34-42-01PROC. REF: AMM 34-42-01									
344207	WEATHER RADAR TRANSCEIVER							Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-42-01PROC. REF: AMM 34-42-01									
344209	WEATHER RADAR LIGHTNING SENSOR ANTENNA							Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
344221	WEATHER RADAR CONTROLLER							Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-42-02PROC. REF: AMM 34-42-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
344223	LIGHTNING DETECTION PROCESSOR							Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
344513	TERRAIN AWARENESS WARNING (TAWS) COMPUTER							Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
344514	TERRAIN AWARENESS WARNING (TAWS) CONFIGURATION MODULE							Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
344515	TAWS RELAY BOX							Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
345000A	UPDATE NAVIGATION DATA BASE							Service	ATA:34
	MOS/MSC	24-Aug-26	0 / -		21-Sep-26 (M)		6 d		
	HRS	10074							
	AFL	7658							
Expiry Date: : 21-Sep-26									
PROC. REF: GENERIC NO REF, EMP 9900052, EMP 9900053PROC. REF: GENERIC NO REF, EMP 9900052, EMP 9900053									
345001	NO. 1 INTEGRATED NAVIGATION UNIT							Component	ATA:34
PN:7510100-631	MOS/MSC	17-Feb-05	O/C						
SN:01015045	HRS	3300.2							
	AFL	2515							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
345002	NO. 2 INTEGRATED NAVIGATION UNIT							Component	ATA:34
PN:7510100-633	MOS/MSC	17-Feb-05	O/C						
SN:99124053	HRS	3300.2							
	AFL	2515							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
345011	NO. 1 NAVIGATION RECEIVER MODULE							Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
345012	NO. 2 NAVIGATION RECEIVER MODULE							Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
345013	NO. 1 ADF ANTENNA							Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-57-01PROC. REF: AMM 34-57-01									
345014	NO. 2 ADF ANTENNA							Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-57-01PROC. REF: AMM 34-57-01									
345024	GPWS CONTROL PANEL							Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
345025	ENHANCED GROUND PROXIMITY WARNING (EGPWS) COMPUTER							Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-45-01PROC. REF: AMM 34-45-01									
345037	FORWARD ATC ANTENNA							Component	ATA:34
PN:DMNI50-2-2	MOS/MSC	16-Jul-19	O/C	TSN 0					
SN:143631	HRS	8109		TSN 0					
	AFL	6239		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
345038	AFT ATC ANTENNA							Component	ATA:34
PN:DMNI50-2-2	MOS/MSC	16-Jul-19	O/C	TSN 0					
SN:143620	HRS	8109		TSN 0					
	AFL	6239		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
345049	AFT (NO. 1) DME ANTENNA							Component	ATA:34
PN:DMNI50-2-2	MOS/MSC	16-Jul-19	O/C	TSN 0					
SN:143632	HRS	8109		TSN 0					
	AFL	6239		TSN 0					
PROC. REF: AMM 34-55-01PROC. REF: AMM 34-55-01									
345050	FORWARD (NO. 2) DME ANTENNA							Component	ATA:34
PN:DMNI50-9-2	MOS/MSC	16-Jul-19	O/C	TSN 10					
SN:22086	HRS	8109		TSN 0					
	AFL	6239		TSN 0					
PROC. REF: AMM 34-55-01PROC. REF: AMM 34-55-01									
345083	LEFT VOR/LOCALIZER ANTENNA							Component	ATA:34
PN:DMN4-17-1/N	MOS/MSC	25-Nov-19	O/C	TSN 0					
SN:21995	HRS	8177.7		TSN 0					
	AFL	6303		TSN 0					
PROC. REF: AMM 34-51-02PROC. REF: AMM 34-51-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
345084	RIGHT VOR/LOCALIZER ANTENNA							Component	ATA:34
PN:DMN4-17-1/N	MOS/MSC	25-Nov-19	O/C	TSN 0					
SN:21818	HRS	8177.7		TSN 0					
	AFL	6303		TSN 0					
PROC. REF: AMM 34-51-02PROC. REF: AMM 34-51-02									
345201	NAV VHF (A42) DUPLEXER							Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-51-04PROC. REF: AMM 34-51-04									
345260	PHASING COUPLER							Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-51-03PROC. REF: AMM 34-51-03									
345501	DME INDICATOR							Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
345605	LEFT UPPER MODE S ATC ANTENNA							Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
345606	RIGHT UPPER MODE S ATC ANTENNA							Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 10101.4
 AFL: 7674
 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
346001	PILOT FLIGHT MANAGEMENT CONTROL DISPLAY CDU							Component	ATA:34
PN:3017-41-221	MOS/MSC	13-Apr-17	O/C						
SN:2081	HRS	7744.3							
	AFL	5922							
PROC. REF: AMM 34-60-01PROC. REF: AMM 34-60-01									
346002	COPILOT FLIGHT MANAGEMENT CONTROL DISPLAY CDU							Component	ATA:34
PN:3017-41-221	MOS/MSC	13-Apr-17	O/C						
SN:2082	HRS	7744.3							
	AFL	5922							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
346021	FMS DATA (DTU) TRANSFER UNIT							Component	ATA:34
PN:1408-00-1	MOS/MSC	13-Apr-17	O/C						
SN:3597	HRS	7744.3							
	AFL	5922							
PROC. REF: AMM 34-60-02PROC. REF: AMM 34-60-02									
346025	NO. 1 FLIGHT MANAGEMENT CONFIGURATION MODULE							Component	ATA:34
PN:30171	MOS/MSC	13-Apr-17	O/C						
SN:2173	HRS	7744.3							
	AFL	5922							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
346026	NO. 2 FLIGHT MANAGEMENT CONFIGURATION MODULE							Component	ATA:34
PN:30171	MOS/MSC	13-Apr-17	O/C						
SN:2174	HRS	7744.3							
	AFL	5922							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
346031	NO. 1 FMS ANTENNA							Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
346032	NO. 2 FMS ANTENNA							Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
346090	AFIS DATA MANAGEMENT UNIT							Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
347510	NO. 1 GPS ANTENNA							Component	ATA:34
PN:10708	MOS/MSC	13-Apr-17	O/C						
SN:9815	HRS	7744.3							
	AFL	5922							
PROC. REF: AMM 34-53-01PROC. REF: AMM 34-53-01									
347511	NO. 2 GPS ANTENNA							Component	ATA:34
PN:10708	MOS/MSC	13-Apr-17	O/C						
SN:9814	HRS	7744.3							
	AFL	5922							
PROC. REF: AMM 34-53-01PROC. REF: AMM 34-53-01									
A3400000 ^S	** NAVIGATION SYSTEMS - PERFORM OPERATIONAL CHECK							Service	ATA:34
	MOS	25-Jun-26	24					AIRWORTHINESS	
	HRS	10023.1	600						
	AFL	7616							
PROC. REF: AMM 34-00-00PROC. REF: AMM 34-00-00									
L3411062	LEFT PRIMARY PITOT/STATIC PROBE - PERFORM DETAILED VISUAL INSPECTION							Service	ATA:34
PN:0856TJ1	MOS	24-Aug-26	24	Adj -14d	10-Aug-28		695 d		
SN:308640	HRS	10074							
	AFL	7658							
PROC. REF: AMM 34-11-01PROC. REF: AMM 34-11-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
M3411052	LEFT PRIMARY PITOT/STATIC PROBE - VERIFY PITCH, ROLL, AND YAW ALIGNMENT							Service	ATA:34
PN:0856TJ1	MOS	24-Aug-26	24	Adj -14d	10-Aug-28		695 d		
SN:308640	HRS	10074							
	AFL	7658							
PROC. REF: AMM 34-11-01PROC. REF: AMM 34-11-01									
U3411060	AIR DATA SYSTEM - PERFORM FUNCTIONAL TEST							Service	ATA:34
	MOS	24-Aug-26	24	Adj -14d	10-Aug-28		695 d		
	HRS	10074							
	AFL	7658							
PROC. REF: AMM 34-17-00PROC. REF: AMM 34-17-00									
V3420000 ^S	ATTITUDE HEADING REFERENCE UNIT (AHRU) MOUNTING TRAY FAN FILTER - PERFORM VISUAL INSPECTION. ENSURE FILTER IS FREE OF OBSTRUCTIONS.							Service	ATA:34
	MOS	25-Jun-26	24						
	HRS	10023.1	600						
	AFL	7616							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
Y3411000 ^S	PITOT-STATIC PROBES - PERFORM VISUAL INSPECTION. ENSURE DRAIN HOLES ARE CLEAR OF OBSTRUCTIONS							Service	ATA:34
	MOS	25-Jun-26	24						
	HRS	10023.1	600						
	AFL	7616							
PROC. REF: AMM 34-11-01PROC. REF: AMM 34-11-01									
Y3440000 ^S	RADOME STRUCTURE AND ANTENNA INSTALLATION - PERFORM VISUAL INSPECTION							Service	ATA:34
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
ATA 35 - OXYGEN									
256032	COPILOTS PROTECTIVE BREATHING EQUIPMENT							Component	ATA:35
PN:119003	MOS/MSC	09-Mar-01	N/A					NOT INSTALLED	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 35 - OXYGEN									
SN:131371	HRS	0							
	AFL	0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
350001	OXYGEN CYLINDER								Component ATA:35
PN:806385-14	MOS/MSC	28-Aug-23	H/T	TSN 15					
SN:C10050116	HRS	9307.4							
	AFL	7125							
PROC. REF: AMM 35-00-01PROC. REF: AMM 35-00-01									
350013	OXYGEN CYLINDER LOW PRESSURE RELIEF VALVE								Component ATA:35
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
350201	TEMP/PRESSURE TRANSDUCER								Component ATA:35
PN:10008789	MOS/MSC	22-Jun-23	O/C						
SN:20201184	HRS	9258.5							
	AFL	7100							
PROC. REF: AMM 35-00-03PROC. REF: AMM 35-00-03									
350225	OXYGEN FILL VALVE (POST SB 45-12-1)								Component ATA:35
PN:P21010	MOS/MSC	16-Jul-19	O/C	TSN 51					
SN:7488	HRS	8109		TSN 0					
	AFL	6239		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
350230	REMOTE OXYGEN PRESSURE INDICATOR								Component ATA:35
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 35-00-05PROC. REF: AMM 35-00-05									

? - Insufficient Information
S - Suppressed Requirement
* - Estimated Due(New Requirement)
(EFF) - Effective C / W
(M) - Manual Due
U - User Task
Ex - Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 35 - OXYGEN									
351001	PILOTS OXYGEN MASK							Component	ATA:35
PN:MC10-15-166	MOS/MSC	05-Jan-26	O/C	TSO 0					
SN:SE 18288	HRS	9987.5		TSO 0					
	AFL	7596		TSO 0					
PROC. REF: AMM 35-10-01PROC. REF: AMM 35-10-01									
351002	COPILOTS OXYGEN MASK							Component	ATA:35
PN:MC10-15-166	MOS/MSC	26-Aug-24	O/C	TSO 0					
SN:111581	HRS	9529		TSO 0					
	AFL	7280		TSO 0					
PROC. REF: AMM 35-10-01PROC. REF: AMM 35-10-01									
351003A	INSPECTION PASSENGER OXYGEN MASK (INSPECTION) - PERFORM VISUAL INSPECTION OF 289 SERIES PAX OXYGEN MASK (REFER ZODIAC / AVOX MANUAL 833-35-01).							Service	ATA:35
	MOS	21-Aug-25	36		21-Aug-28		706 d	VENDOR RECOMMENDATION	
	HRS	9809.8							
	AFL	7471							
PROC. REF: GENERIC NO REF, SI 833-35-01PROC. REF: GENERIC NO REF, SI 833-35-01									
351005	PILOT CREW OXYGEN OUTLET							Component	ATA:35
PN:DPB181-04	MOS/MSC	24-May-07	O/C						
SN:20/06	HRS	5477.2							
	AFL	4173							
PROC. REF: AMM 35-10-01PROC. REF: AMM 35-10-01									
351006	COPILOT CREW-OXYGEN OUTLET							Component	ATA:35
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 35-10-01PROC. REF: AMM 35-10-01									
352002	ALTITUDE COMPENSATING REGULATOR							Component	ATA:35
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 35-20-06PROC. REF: AMM 35-20-06									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 35 - OXYGEN									
352011	OXYGEN CONTROL VALVE							Component	ATA:35
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 35-20-01PROC. REF: AMM 35-20-01									
353001	PORTABLE OXYGEN CYLINDER							Component	ATA:35
PN:PN	MOS/MSC		O/C						
SN:UNKNOWN	HRS								
	AFL								
PROC. REF: AMM 35-00-01PROC. REF: AMM 35-00-01									
355111	OXYGEN PRESSURE INDICATOR							Component	ATA:35
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 35-00-05PROC. REF: AMM 35-00-05									
K3500021	** OXYGEN SYSTEM LOW PRESSURE SUPPLY HOSES - PERFORM OPERATIONAL CHECK. ENSURE THAT HOSES ARE FREE OF OBSTRUCTIONS							Service	ATA:35
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
PROC. REF: AMM 35-00-00PROC. REF: AMM 35-00-00									
N3510013	** OXYGEN CYLINDER AND REMOTE OXYGEN FILL VALVES - PERFORM PERIODIC CHECK							Service	ATA:35
	MOS	27-Oct-25						AIRWORTHINESS	
	HRS	9906.2	1500	Adj 8.2	11414.4		1313		
	AFL	7538							
PROC. REF: AMM 35-00-01PROC. REF: AMM 35-00-01									
N3510019	** OXYGEN CYLINDER AND REMOTE OXYGEN FILL VALVES - PERFORM PERIODIC CHECK							Service	ATA:35
	MOS/MSC		N/A						
	HRS								
	AFL								
PROC. REF: AMM 35-00-01PROC. REF: AMM 35-00-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 35 - OXYGEN									
O3510003 ^S		** CABIN LOW PRESSURE OXYGEN DISTRIBUTION FLEX HOSES - PERFORM FUNCTIONAL TEST						Service	ATA:35
	MOS	25-Jun-26	24					AIRWORTHINESS	
	HRS	10023.1	600						
	AFL	7616							
PROC. REF: AMM 35-20-00PROC. REF: AMM 35-20-00									
O3510006		COPILOTS OXYGEN MASK - E.R.O.S. CREW OXYGEN MASKS - COMPLY WITH FACTORY OVERHAUL						Service	ATA:35
PN:MC10-15-166	MOS	26-Aug-24	72		28-Jun-30		1382 d		
SN:111581	HRS	9529							
	AFL	7280							
OverHaul Date:: 28-Jun-24									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
O3510006		PILOTS OXYGEN MASK - E.R.O.S. CREW OXYGEN MASKS - COMPLY WITH FACTORY OVERHAUL						Service	ATA:35
PN:MC10-15-166	MOS	05-Jan-26	72		08-Nov-31		1880 d		
SN:SE 18288	HRS	9987.5							
	AFL	7596							
OverHaul Date:: 08-Nov-25									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
O3510007		OXYGEN CYLINDER (COMPOSITE) - SCRAP						Service	ATA:35
	MOS	09-Mar-01	180		28-May-37 (M)		3908 d	LIFE LIMIT	
	HRS	0							
	AFL	0							
Q3510005		** OXYGEN CYLINDER (COMPOSITE) AND LOW PRESSURE RELIEF VALVE - PERFORM ICC HYDROSTATIC TEST ON CYLINDER (PER DOT EXEMPTION E8162) AND FUNCTIONALLY TEST OXYGEN CYLINDER LOW PRESSURE RELIEF VALVE.						Service	ATA:35
PN:806385-14	MOS	27-Jun-23	60		27-Jun-28		651 d		
SN:C10050116	HRS	9307.4	5000		14307.4		4206		
	AFL	7125							
HydroCheck Date: : 27-Jun-23									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information

S-Suppressed Requirement

*-Estimated Due(New Requirement)

(EFF)-Effective C / W

(M)-Manual Due

U-User Task

Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 35 - OXYGEN									
Q3510018	** OXYGEN CYLINDER (COMPOSITE) AND LOW PRESSURE RELIEF VALVE - PERFORM ICC HYDROSTATIC TEST ON CYLINDER (PER DOT EXEMPTION E8162) AND FUNCTIONALLY TEST OXYGEN CYLINDER LOW PRESSURE RELIEF VALVE							Service	ATA:35
PN:806385-14	MOS	28-Aug-23	60		28-Aug-28		713 d		
SN:C10050116	HRS	9307.4	5000		14307.4		4206		
	AFL	7125							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
Q3510022	OXYGEN CYLINDER REGULATOR - PERFORM OVERHAUL							Service	ATA:35
	MOS	22-Jun-23	60		22-Jun-28		646 d		
	HRS	9258.5	5000		14258.5		4157.1		
	AFL	7100							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
Q3510023	OXYGEN CYLINDER REGULATOR - PERFORM OVERHAUL							Service	ATA:35
	MOS/MSC		N/A						
	HRS								
	AFL								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
W3510002 ^S	** OXYGEN SYSTEM - PERFORM OPERATIONAL CHECK							Service	ATA:35
	MOS	25-Jun-26	24					AIRWORTHINESS	
	HRS	10023.1	600						
	AFL	7616							
PROC. REF: AMM 35-00-00PROC. REF: AMM 35-00-00									PKG:7
Y3510000 ^S	OXYGEN CYLINDER INSTALLATION - PERFORM VISUAL INSPECTION. CHECK PLUMBING FOR ROUTING, SECURITY, AND CONDITION.							Service	ATA:35
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:13

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 35 - OXYGEN									
Y3510001 ^S		CREW SEAT OXYGEN HOSES - PERFORM VISUAL INSPECTION. PAY PARTICULAR ATTENTION TO AREA WHERE OXYGEN HOSES ENTER CREW SEATS ABOVE COCKPIT FLOOR.						Service	ATA:35
	MOS	25-Jun-26	12						
	HRS	10023.1	300						
	AFL	7616							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:1

Y3510017 ^S		OXYGEN CYLINDER INSTALLATION - PERFORM VISUAL INSPECTION. CHECK PLUMBING FOR ROUTING, SECURITY, AND CONDITION						Service	ATA:35
	MOS	25-Jun-26	24						
	HRS	10023.1	600						
	AFL	7616							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:7

ATA 36 - PNEUMATIC

361001		LEFT OUTBOARD HIGH PRESSURE TAILCONE MANIFOLD						Component	ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

361002		LEFT OUTBOARD ANTI-ICE MANIFOLD						Component	ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-10-07PROC. REF: AMM 30-10-07									

361004		LEFT INBOARD HIGH-PRESSURE BLEED AIR MANIFOLD						Component	ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-10-07PROC. REF: AMM 36-10-07									

361005		RIGHT INBOARD HIGH-PRESSURE BLEED AIR MANIFOLD						Component	ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 36 - PNEUMATIC									
PROC. REF: AMM 36-10-07PROC. REF: AMM 36-10-07									
361016	RIGHT OUTBOARD ANTI-ICE MANIFOLD							Component	ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-10-07PROC. REF: AMM 30-10-07									
361020	LEFT HIGH PRESSURE OVER-TEMP SWITCH							Component	ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-20-03PROC. REF: AMM 36-20-03									
361021	RIGHT HIGH PRESSURE OVER-TEMP SWITCH							Component	ATA:36
PN:641179-4	MOS/MSC	06-Jun-05	O/C						
SN:0766	HRS	3654.87							
	AFL	2759							
PROC. REF: AMM 36-20-03PROC. REF: AMM 36-20-03									
361031	ECS CONTROLLER							Component	ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-10-01PROC. REF: AMM 36-10-01									
361040	APU BLEED AIR CHECK VALVE							Component	ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-10-09PROC. REF: AMM 36-10-09									
361050	LOAD CONTROL SHUTOFF VALVE (L5003)							Component	ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-10-10PROC. REF: AMM 36-10-10									

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C / W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 36 - PNEUMATIC									
361053	NO. 1 ECS SHUTOFF (L37) VALVE							Component	ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-10-03PROC. REF: AMM 36-10-03									
361054	NO. 2 ECS SHUTOFF (L38) VALVE							Component	ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-10-03PROC. REF: AMM 36-10-03									
361065	LEFT TAILCONE HIGH PRESSURE SHUT-OFF VALVE (L39)							Component	ATA:36
PN:3291216-2	MOS/MSC	09-Jun-05	O/C						
SN:736	HRS	3666.35							
	AFL	2768							
PROC. REF: AMM 36-10-02PROC. REF: AMM 36-10-02									
361066	RIGHT TAILCONE HIGH PRESSURE SHUT-OFF VALVE (L40)							Component	ATA:36
PN:3291216-2	MOS/MSC	09-Jun-05	O/C						
SN:426	HRS	3666.35							
	AFL	2768							
PROC. REF: AMM 36-10-02PROC. REF: AMM 36-10-02									
361120	NO. 1 PRESSURE SWITCH (S79)							Component	ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-10-06PROC. REF: AMM 36-10-06									
361121	NO. 2 PRESSURE SWITCH (S88)							Component	ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-10-06PROC. REF: AMM 36-10-06									

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C / W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 36 - PNEUMATIC									
361125	LEFT PYLON LOW PRESSURE TEMPERATURE SENSOR							Component	ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
361126	RIGHT PYLON LOW PRESSURE TEMPERATURE SENSOR							Component	ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
361127	LEFT TAILCONE LOW PRESSURE (2.0 DIAMETER) CHECK VALVE							Component	ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
361128	RIGHT TAILCONE LOW PRESSURE (2.0 DIAMETER) CHECK VALVE							Component	ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
361215	LEFT HIGH PRESSURE BLEED AIR MANIFOLD							Component	ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-10-07PROC. REF: AMM 36-10-07									
361216	RIGHT HIGH PRESSURE BLEED AIR MANIFOLD							Component	ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-10-07PROC. REF: AMM 36-10-07									

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C / W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 36 - PNEUMATIC									
361301	APU SERVO AIR CHECK VALVE							Component	ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-15-02PROC. REF: AMM 36-15-02									
361302	NO. 1 ENGINE SERVO AIR CHECK VALVE							Component	ATA:36
PN:6608295-3	MOS/MSC	30-Apr-06	O/C						
SN:2360	HRS	4466.8							
	AFL	3408							
PROC. REF: AMM 36-15-02PROC. REF: AMM 36-15-02									
361303	NO. 2 ENGINE SERVO AIR CHECK VALVE							Component	ATA:36
PN:6608295-3	MOS/MSC	30-Apr-06	O/C						
SN:2308	HRS	4466.8							
	AFL	3408							
PROC. REF: AMM 36-15-02PROC. REF: AMM 36-15-02									
362005	LEFT FORWARD TAILCONE OVERHEAT THERMOSTAT SWITCH (S145)							Component	ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-20-02PROC. REF: AMM 36-20-02									
362006	RIGHT FORWARD TAILCONE OVERHEAT THERMOSTAT SWITCH (S146)							Component	ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-20-02PROC. REF: AMM 36-20-02									
362007	LEFT AFT TAILCONE OVERHEAT THERMOSTAT SWITCH (S147)							Component	ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-20-02PROC. REF: AMM 36-20-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 36 - PNEUMATIC									
362008	RIGHT AFT TAILCONE OVERHEAT THERMOSTAT SWITCH (S148)							Component	ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-20-02PROC. REF: AMM 36-20-02									
364925	LEFT ECS CHECK VALVE							Component	ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-10-04PROC. REF: AMM 36-10-04									
364926	RIGHT ECS CHECK VALVE							Component	ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-10-04PROC. REF: AMM 36-10-04									
5-19-00-D3610002	BORESCOPE INSPECTION HP BLEED AIR MANIFOLD ASSEMBLY ATTACH BRACKET ASSEMBLY FOR CRACKS AT WELD.(IRN D3610002)							Service	ATA:36
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
A3610000 ^S	** BLEED AIR SYSTEM - PERFORM FUNCTIONAL TEST							Service	ATA:36
	MOS	25-Jun-26	24					AIRWORTHINESS	
	HRS	10023.1	600						
	AFL	7616							
PROC. REF: AMM 36-10-00PROC. REF: AMM 36-10-00									
A3610001 ^S	** PYLON OVERHEAT THERMOSTAT AND ELECTRICAL SYSTEM - PERFORM FUNCTIONAL TEST							Service	ATA:36
	MOS	25-Jun-26	24					AIRWORTHINESS	
	HRS	10023.1	600						
	AFL	7616							
PROC. REF: AMM 36-20-01PROC. REF: AMM 36-20-01									

?-Insufficient Information

S-Suppressed Requirement

*-Estimated Due(New Requirement)

(EFF)-Effective C / W

(M)-Manual Due

U-User Task

Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 36 - PNEUMATIC									
D3610002	LEFT HIGH PRESSURE BLEED AIR MANIFOLD - PERFORM BORESCOPE INSPECTION OF ATTACH BRACKET ASSEMBLY FOR CRACKS AT WELD							Service	ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C						
SN:UNKNOWN	HRS	0							
	AFL	0							
PROC. REF: AMM 36-10-07PROC. REF: AMM 36-10-07									
D3610002	RIGHT HIGH PRESSURE BLEED AIR MANIFOLD - PERFORM BORESCOPE INSPECTION OF ATTACH BRACKET ASSEMBLY FOR CRACKS AT WELD							Service	ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C						
SN:UNKNOWN	HRS	0							
	AFL	0							
PROC. REF: AMM 36-10-07PROC. REF: AMM 36-10-07									
P3610048	LEFT HIGH PRESSURE BLEED AIR MANIFOLD - PERFORM VISUAL INSPECTION							Service	ATA:36
	MOS	06-Dec-17							
	HRS	7770.3	3000		10770.3		668.9		
	AFL								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
P3610048	RIGHT HIGH PRESSURE BLEED AIR MANIFOLD - PERFORM VISUAL INSPECTION							Service	ATA:36
	MOS	20-Jul-15							
	HRS	7535.1	3000		10535.1		433.7		
	AFL								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
U3610075 ^S	ECS BLEED AIR "Y" MANIFOLD - PERFORM BORESCOPE INSPECTION							Service	ATA:36
	MOS	09-Mar-01							
	HRS	0	4800						
	AFL	0							
									PKG:25
PROC. REF: AMM 36-10-00PROC. REF: AMM 36-10-00									
Y3610061 ^S	HIGH PRESSURE BLEED AIR SHUT-OFF VALVE IN-LINE FILTER - PERFORM CLEANING PROCEDURES							Service	ATA:36
	MOS	25-Jun-26	24						
	HRS	10023.1	600						
	AFL	7616							
									PKG:8

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C / W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
---------	------	-------	----------	------------	----------------------------	-----------	-----------	-------------	----------

ATA 36 - PNEUMATIC

PROC. REF: AMM 36-10-02PROC. REF: AMM 36-10-02

ATA 38 - WATER/WASTE

380001	TOILET SERVICE PANEL							Component	ATA:38
PN:9600-102	MOS/MSC	09-Apr-06	O/C						
SN:SP1116	HRS								
	AFL								
PROC. REF: AMM 38-30-05PROC. REF: AMM 38-30-05									

381009	TOILET HEATED DRAIN MAST							Component	ATA:38
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

383001	TOILET --							Component	ATA:38
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 38-30-01PROC. REF: AMM 38-30-01									

383002	TOILET TIMER							Component	ATA:38
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 38-30-02PROC. REF: AMM 38-30-02									

383005	TOILET WATER TANK							Component	ATA:38
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

383011	LAVATORY SINK SHUT OFF VALVE							Component	ATA:38
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
---------	------	-------	----------	------------	----------------------------	-----------	-----------	-------------	----------

ATA 38 - WATER / WASTE

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

384025	TOILET PUMP							Component	ATA:38
PN:5250-11A	MOS/MSC	12-Aug-15	O/C						
SN:P8851	HRS	7535.1							
	AFL	5764							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

384051	TOILET MACERATOR							Component	ATA:38
PN:5300-1	MOS/MSC	12-Aug-15	O/C	TSN 0					
SN:M5189	HRS	7535.1		TSN 0					
	AFL	5764		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

389050	TOILET CLEAN WATER PUMP							Component	ATA:38
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

ATA 49 - AIRBORNE AUXILIARY POWER

490060	APU ELECTRONIC CONTROL UNIT (ECU)							Component	ATA:49
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 49-60-04PROC. REF: AMM 49-60-04									

491011	APU MAINTENANCE CONTROL PANEL							Component	ATA:49
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 49-60-02PROC. REF: AMM 49-60-02									

491020	APU COCKPIT CONTROL PANEL							Component	ATA:49
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 49 - AIRBORNE AUXILIARY POWER										
PROC. REF: AMM 49-60-01PROC. REF: AMM 49-60-01										
494050		APU IGNITION UNIT							Component	ATA:49
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 49-40-04PROC. REF: AMM 49-40-04										
495001		TAILCONE APU COOLING FAN							Component	ATA:49
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 49-50-01PROC. REF: AMM 49-50-01										
495002		TAILCONE ACCESS DOOR COOLING (B30) FAN							Component	ATA:49
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
495040		APU THERMOSTAT (S175) SWITCH							Component	ATA:49
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
495041		APU THERMOSTAT (S176) SWITCH							Component	ATA:49
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
495201		STRUT SUPPORT ASSEMBLY							Component	ATA:49
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

? - Insufficient Information
S - Suppressed Requirement
* - Estimated Due(New Requirement)
(EFF) - Effective C/W
(M) - Manual Due
U - User Task
Ex - Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 49 - AIRBORNE AUXILIARY POWER									
495202	STRUT SUPPORT ASSEMBLY							Component	ATA:49
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
497001	APU BITE INDICATOR							Component	ATA:49
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 49-70-04PROC. REF: AMM 49-70-04									
49APU1	APU							Component	ATA:49
PN:PN	MOS/MSC		E/C						
SN:UNKNOWN	HRS								
	AFL								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
H4900011 ^S	** APU GENERATOR - PERFORM OVERVOLTAGE PROTECTION CHECK							Service	ATA:49
	MOS	09-Mar-01	48					AIRWORTHINESS	
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 49-40-01PROC. REF: AMM 49-40-01									
Y4900000 ^S	AUXILIARY POWER UNIT - PERFORM VISUAL INSPECTION OF EXTERNAL FIREBOX INSTALLATION AND ATTACHING COMPONENTS							Service	ATA:49
	MOS	25-Jun-26	12						
	HRS	10023.1	300						
	AFL	7616							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
Y4900010 ^S	APU ENGINE FIRE EXTINGUISHER CONTAINER - CHECK CONTAINER PRESSURE GAGE FOR PROPER PRESSURE							Service	ATA:49
	MOS	25-Jun-26	12						
	HRS	10023.1	300						
	AFL	7616							
PROC. REF: AMM 26-22-00PROC. REF: AMM 26-22-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
---------	------	-------	----------	------------	----------------------------	-----------	-----------	-------------	----------

ATA 49 - AIRBORNE AUXILIARY POWER

Y4900012	^S	APU INLET SCREEN AND OPENING - PERFORM VISUAL INSPECTION						Service	ATA:49
	MOS	25-Jun-26	12						
	HRS	10023.1	300						
	AFL	7616							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:2

Y4900013	^S	APU EXHAUST DUCT AREA, INCLUDING FORWARD AND AFT APU EXHAUST FAIRINGS - PERFORM VISUAL INSPECTION						Service	ATA:49
	MOS	25-Jun-26	12						
	HRS	10023.1	300						
	AFL	7616							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:2

ATA 52 - DOORS

521001		UPPER CABIN DOOR						Component	ATA:52
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 52-10-01PROC. REF: AMM 52-10-01									

521002		LOWER CABIN DOOR						Component	ATA:52
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 52-10-01PROC. REF: AMM 52-10-01									

521010		LOWER ENTRY DOOR FORWARD GAS DAMPER ASSEMBLY						Component	ATA:52
PN:SP21231-2	MOS/MSC	24-Jan-25	O/C	TSN 0					
SN:UNKNOWN	HRS	9595.4		TSN 0					
	AFL	7326		TSN 0					
PROC. REF: AMM 52-10-11PROC. REF: AMM 52-10-11									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 10101.4
 AFL: 7674
 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 52 - DOORS									
521011	LOWER ENTRY DOOR AFT GAS DAMPER ASSEMBLY								Component ATA:52
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 52-10-11PROC. REF: AMM 52-10-11									
522001	EMERGENCY EXIT DOOR ASSEMBLY								Component ATA:52
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 52-20-01PROC. REF: AMM 52-20-01									
522010	EMERGENCY EXIT DOOR WINDOW								Component ATA:52
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 52-20-06PROC. REF: AMM 52-20-06									
523001	TAILCONE BAGGAGE DOOR ASSEMBLY								Component ATA:52
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
524001	TAILCONE ACCESS DOOR								Component ATA:52
PN:4552405151-009	MOS/MSC	17-Feb-05	O/C	TSN 0					
SN:0316	HRS	3300.2		TSN 0					
	AFL	2515		TSN 0					
PROC. REF: AMM 52-40-02PROC. REF: AMM 52-40-02									
524010	SPPR DOOR ASSY								Component ATA:52
PN:PN	MOS/MSC		O/C						
SN:UNKNOWN	HRS								
	AFL								
PROC. REF: AMM 52-40-03PROC. REF: AMM 52-40-03									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 52 - DOORS									
A5210009	^S	* EMERGENCY EXIT DOOR RETAINERS - PERFORM VISUAL INSPECTION. INSPECT DOOR STOP FITTINGS ON EMERGENCY EXIT DOOR FRAMES IN FLANGE RADII. (F.S. 374 AND 394).						Service	ATA:52
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:26
A5210012	^S	* LOWER PASSENGER DOOR HINGE - PERFORM VISUAL INSPECTION. INSPECT PIANO HINGE LUGS AND FASTENERS.						Service	ATA:52
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:26
A5210014	^S	* UPPER PASSENGER DOOR TENSION FITTINGS - PERFORM VISUAL INSPECTION. INSPECT THE FOLLOWING: A. TENSION STUDS AT RETAINING FLANGES. B. RADII AROUND FLANGE PERIPHERY.						Service	ATA:52
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:26
AA5210055	^S	CABIN DOOR HANDLE RAMP ROLLER WHEEL - LUBRICATE						Service	ATA:52
	MOS	22-Jun-23	48						
	HRS	9258.5	1200						
	AFL	7100							
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02									PKG:18
D5210015	^S	* EMERGENCY EXIT DOOR - PERFORM VISUAL INSPECTION. PAY PARTICULAR ATTENTION TO FLANGES AND FASTENER HOLES OF DOOR STOP FITTINGS.						Service	ATA:52
	MOS	09-Mar-01						AIRWORTHINESS	
	HRS	0	T:9600						
	AFL	0							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:25

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 10101.4
 AFL: 7674
 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 52 - DOORS									
E5210013	^S	* UPPER AND LOWER PASSENGER DOOR LATCH ARMS AND DOOR ATTACHMENTS - PERFORM VISUAL INSPECTION						Service	ATA:52
	MOS	09-Mar-01						AIRWORTHINESS	
	HRS	0	T:9600						
	AFL	0							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:25
F5210016	^S	* UPPER PASSENGER DOOR HINGE - PERFORM VISUAL INSPECTION. INSPECT UPPER SURFACE OF HINGE FINGERS AT BASE OF LUG.						Service	ATA:52
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:26
M5240004		AVIONIC ACCESS DOORS - PERFORM AVIONICS DOOR GAP AND MISMATCH INSPECTION						Service	ATA:52
	MOS	24-Aug-26	24	Adj -14d	10-Aug-28		695 d		
	HRS	10074							
	AFL	7658							
PROC. REF: AMM 52-40-01PROC. REF: AMM 52-40-01									
N5210010	^S	* LOWER PASSENGER DOOR TENSION BOLTS, BOLT RETAINERS, TENSION FITTINGS, AND DOOR ATTACHMENTS - PERFORM VISUAL INSPECTION						Service	ATA:52
	MOS	25-Jun-26	96					AIRWORTHINESS	
	HRS	10023.1	2400						
	AFL	7616							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:24
N5210011	^S	* UPPER AND LOWER PASSENGER DOOR LATCH PINS - PERFORM VISUAL INSPECTION. INSPECT BOLTS AND DOOR END RIB STRUCTURE AT LOCK PINS.						Service	ATA:52
	MOS	25-Jun-26	96					AIRWORTHINESS	
	HRS	10023.1	2400						
	AFL	7616							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:24

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 52 - DOORS									
N5210017	^S	* UPPER PASSENGER DOOR TENSION BOLTS, BOLT RETAINERS, TENSION FITTINGS, AND DOOR ATTACHMENTS - PERFORM VISUAL INSPECTION						Service	ATA:52
	MOS	25-Jun-26	96					AIRWORTHINESS	
	HRS	10023.1	2400						
	AFL	7616							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:24
T5210003	^S	EXTERNAL LOWER PASSENGER/CREW DOOR CABLES - PERFORM VISUAL INSPECTION OF VISIBLE PORTION OF CABLES AND HANDLE AREA.						Service	ATA:52
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:18
Y5210000	^S	AVIONICS COMPARTMENT ACCESS DOORS AND SEALS - PERFORM VISUAL INSPECTION						Service	ATA:52
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:13
Y5210001	^S	TAILCONE ACCESS DOOR AND SEAL - PERFORM VISUAL INSPECTION OF DOOR, SEALS, AND LATCHES						Service	ATA:52
	MOS	25-Jun-26	24						
	HRS	10023.1	600						
	AFL	7616							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:12
Y5210002	^S	BAGGAGE COMPARTMENT DOOR - PERFORM VISUAL INSPECTION OF DOORS, SEALS, AND LATCHES						Service	ATA:52
	MOS	25-Jun-26	24						
	HRS	10023.1	600						
	AFL	7616							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:12

? - Insufficient Information
S - Suppressed Requirement
* - Estimated Due(New Requirement)
(EFF) - Effective C / W
(M) - Manual Due
U - User Task
Ex - Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 52 - DOORS									
Y5210004	^S	UPPER AND LOWER PASSENGER/CREW DOOR - PERFORM VISUAL INSPECTION OF DOOR STRUCTURE, TENSION FITTINGS, AND HINGE AREA FOR CRACKS AND CORROSION.						Service	ATA:52
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:18
Y5210005	^S	INTERNAL LOWER PASSENGER/CREW DOOR CABLES - PERFORM VISUAL INSPECTION. REMOVE STEP SKIN TO GAIN ACCESS TO CABLES.						Service	ATA:52
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:18
Y5210006	^S	UPPER PASSENGER/CREW DOOR VENT DOOR SPRINGS - PERFORM VISUAL INSPECTION						Service	ATA:52
	MOS	25-Jun-26	24						
	HRS	10023.1	600						
	AFL	7616							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:12
Y5210008	^S	EMERGENCY EXIT DOOR INTERNAL AND EXTERNAL HANDLE LATCHING MECHANISM. - PERFORM OPERATIONAL CHECK						Service	ATA:52
	MOS	25-Jun-26	24						
	HRS	10023.1	600						
	AFL	7616							
PROC. REF: AMM 52-20-07PROC. REF: AMM 52-20-07									PKG:12
Y5240000	^S	OXYGEN SYSTEM SERVICING DOOR AND LATCHES - PERFORM VISUAL INSPECTION FOR CONDITION AND SECURITY. CHECK DECAL FOR CONDITION AND LEGIBILITY.						Service	ATA:52
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:13

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 52 - DOORS									
Y5240003	S	SINGLE POINT REFUELING ACCESS DOOR - PERFORM VISUAL INSPECTION							Service ATA:52
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
Z5210053		CABIN MAIN ENTRY DOOR HANDLE - REPLACE							Service ATA:52
	MOS	06-Jul-21	144		06-Jul-33		2486 d		
	HRS	8631.2							
	AFL	6618	6000		12618		4944		
PROC. REF: AMM 52-10-08, AMM 52-10-13PROC. REF: AMM 52-10-08, AMM 52-10-13									
ATA 53 - FUSELAGE									
530001		FUSELAGE ASSEMBLY							Component ATA:53
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
531044		LEFT LOWER COUPE RAIL							Component ATA:53
PN:PN	MOS/MSC		N/A	TSN 0				NOT APPLICABLE	
SN:UNKNOWN	HRS			TSN 0					
	AFL			TSN 0					
PROC. REF: AMM 53-10-04PROC. REF: AMM 53-10-04									
531045		RIGHT LOWER COUPE RAIL							Component ATA:53
PN:PN	MOS/MSC		N/A	TSN 0				NOT APPLICABLE	
SN:UNKNOWN	HRS			TSN 0					
	AFL			TSN 0					
PROC. REF: AMM 53-10-04PROC. REF: AMM 53-10-04									
5323172 EMP		* SKIN CUT-OUT FOR Iridium ANTENNAS, FS 283.88 TO FS 308.39 - PERFORM EDDY CURRENT INSPECTION							Service ATA:53
	MOS/MSC	09-Mar-01	N/A					AIRWORTHINESS	
	HRS	0							
	AFL	0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
535001	RADOME							Component	ATA:53
PN:6634408000-001	MOS/MSC	12-Dec-11	O/C	TSR 0					
SN:150	HRS	6763.5		TSR 0					
	AFL	5158		TSR 0					
PROC. REF: AMM 53-50-01PROC. REF: AMM 53-50-01									
535601	LEFT DELTA FIN							Component	ATA:53
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 53-56-01PROC. REF: AMM 53-56-01									
535602	RIGHT DELTA FIN							Component	ATA:53
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 53-56-01PROC. REF: AMM 53-56-01									
545019	NO. 1 ENGINE AFT BEAM TO FRAME ATTACHMENT BOLT							Component	ATA:53
PN:NAS6706DU50	MOS/MSC	25-Jun-26	H/T	TSN 0					
SN:UNKNOWN	HRS	10023.1		TSN 0					
	AFL	7616		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
A5310005 ^S	* FUSELAGE FUEL CELL CANTED BULKHEAD (F.S. 495) - PERFORM VISUAL INSPECTION, PAYING PARTICULAR ATTENTION TO MAIN CROSS MEMBER. INSPECT FLANGES AND ATTACHMENTS FOR CRACKING.							Service	ATA:53
	MOS	09-Mar-01						AIRWORTHINESS	
	HRS	0	T:9600						
	AFL	0							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
A5310007 ^S	* AFT PRESSURE BULKHEAD BOTTOM SHEAR DIAPHRAGM - PERFORM DETAILED VISUAL INSPECTION. INSPECT BULKHEAD POST ATTACHMENT FASTENER HOLES AND CONTROL CABLE SLOT.							Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							
PKG:26									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
A5323022	^S	* NOSE LANDING GEAR AFT WHEELBOX CLOSING STRUCTURE (F.S. 150 TO F.S.162) - PERFORM VISUAL INSPECTION. INSPECT THE FOLLOWING: A. PANEL. B. CHANNEL STIFFENERS. C. SUPPORT ANGLE. D. ANGLE STIFFENER. E. ZEE STIFFENER						Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							
									PKG:26
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
A5323023	^S	* DRAG LINK ATTACHMENT LUG - PERFORM VISUAL INSPECTION						Service	ATA:53
	MOS	09-Mar-01						AIRWORTHINESS	
	HRS	0	T:9600						
	AFL	0							
									PKG:25
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
A5360001	^S	DELTA FINS - WITH DELTA FINS REMOVED, VISUALLY INSPECT THE FOLLOWING: A. DELTA FIN AFT SPAR. B. DELTA FIN SUPPORT ANGLE. C. INSPECT STIFFENERS CONNECTING TO ATTACH FITTINGS.						Service	ATA:53
	MOS	02-Aug-24							
	HRS	9525.7	9600						
	AFL	7276							
									PKG:26
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
D5323039	^S	* MACHINED FUSELAGE FRAME AT FS 466 - PERFORM DETAILED VISUAL INSPECTION BETWEEN STRINGER 13 LEFT AND RIGHT, PAYING PARTICULAR ATTENTION TO THE BL 10 SPLICES. CONFIRM ANY CRACK INDICATIONS WITH EDDY CURRENT PROCEDURES.						Service	ATA:53
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
									PKG:25
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
E5310001	^S	* LONGERON, INTERNAL (BETWEEN FS 384 AND FS 433) - PERFORM VISUAL INSPECTION						Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							
									PKG:26
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
E5310002	^S	* FLIGHT DECK LONGERON - PERFORM VISUAL INSPECTION (FS 149 - FS 196). INSPECT FLIGHT DECK LONGERON STIFFENERS, WEBS, AND CUTOUTS						Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:26
E5310017	^S	* AFT PRESSURE BULKHEAD BOTTOM CROSSMEMBER (FS 457) - PERFORM DETAILED VISUAL INSPECTION. INSPECT TEE-SECTION AT FS 457 FLANGE AT ATTACHMENT OF PRESSURE FLOOR.						Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:26
E5310018	^S	* AFT PRESSURE BULKHEAD PANEL FACING SHEETS (FS 457) - PERFORM VISUAL INSPECTION. INSPECT BOTH FRONT AND AFT OF FACING SHEETS.						Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:26
E5323025	^S	* FORWARD/AFT WHEELBOX JOINT (FS 150) - PERFORM VISUAL INSPECTION. INSPECT SPLICE STRAP AFT OF FORWARD PRESSURE BULKHEAD AT INTERSECTION OF ATTACHMENT ANGLE AND FLIGHT DECK LONGERON.						Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:26
E5323050	^S	* AFT POST/WINDSHIELD RETAINER ATTACHMENT - PERFORM EDDY CURRENT INSPECTION. INSPECT WINDSHIELD AFT POST AT WINDSHIELD RETAINER FASTENER HOLES.						Service	ATA:53
	MOS	09-Mar-01						AIRWORTHINESS	
	HRS	0	T:9600						
	AFL	0							
									PKG:25

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
---------	------	-------	----------	------------	----------------------------	-----------	-----------	-------------	----------

ATA 53 - FUSELAGE

PROC. REF: NDT PART 6/53-30-04PROC. REF: NDT PART 6/53-30-04

E5323053	^S	* FRAME ATTACHMENTS TO UPPER AND LOWER COUPE RAILS (FS 171 TO FS 204) - PERFORM VISUAL INSPECTION. INSPECT THE FOLLOWING: A. FRAME ATTACHMENTS TO LOWER COUPE RAILS AT FS 171, FS 182, FS 196, AND FS 204. B. FRAME ATTACHMENTS TO UPPER COUPE RAILS AT FS 196 AND FS 204. C. GUSSETS AT FASTENER HOLES.						Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							
									PKG:26
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

E5323054	^S	* TIE-ROD ASSEMBLY (FS 162) (ALUMINUM ENDS) - PERFORM VISUAL INSPECTION. INSPECT TIE-ROD ENDS, TIE-ROD TUBES, AND TIE-ROD BOLTS.						Service	ATA:53
	MOS	09-Mar-01						AIRWORTHINESS	
	HRS	0	4800						
	AFL	0							
									PKG:25
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									

E5323055	^S	* TIE-ROD ASSEMBLY (FS 162) (TITANIUM ENDS) - PERFORM VISUAL INSPECTION. INSPECT TIE-ROD ENDS, TIE-ROD TUBES, AND TIE-ROD BOLTS.						Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							
									PKG:26
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

E5323068	^S	* STRINGER 1RH BETWEEN F.S. 533 AND F.S. 543 - PERFORM VISUAL INSPECTION. INSPECT STRINGER 1 FLANGE AND SKIN ALONG STRINGER 1 BETWEEN F.S. 533 AND F.S. 543.						Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							
									PKG:26
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
E5323073	^S	* FUSELAGE BOTTOM SKIN PANEL - PERFORM VISUAL INSPECTION. INSPECT CORNER RADIUS AT JUNCTION OF EXTERNAL LONGERON AND MID SPAR FRAME (F.S. 435).						Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:26
E5323074	^S	* AUXILIARY SKIN PANEL - PERFORM VISUAL INSPECTION. INSPECT CORNER RADIUS AT JUNCTION OF KEEL BEAM AND REAR SPAR FRAME (F.S. 466).						Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:26
E5350000	^S	* BOTTOM KEEL BEAM END PADS (F.S. 384 - F.S. 486) - PERFORM VISUAL INSPECTION. INSPECT END PADS AROUND BOLT HOLES AND IN RADII AT F.S. 433.						Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:26
F5323056	^S	* TIE-ROD FORK ENDS (ALUMINUM) - PERFORM FLUORESCENT PENETRANT INSPECTION						Service	ATA:53
	MOS/MSC	09-Mar-01	N/A					NOT APPLICABLE	
	HRS	0							
	AFL	0							
PROC. REF: NDT PART 8/53-10-01PROC. REF: NDT PART 8/53-10-01									PKG:25
F5323081	^S	* TIE-ROD FORK ENDS - PERFORM FLUORESCENT PENETRANT INSPECTION						Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							
PROC. REF: NDT PART 8/53-10-01PROC. REF: NDT PART 8/53-10-01									PKG:26

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
F5331021	^S	* FORWARD CANTED BULKHEAD (F.S. 630) - PERFORM VISUAL INSPECTION. INSPECT AT FRONT SPAR UPPER ATTACHMENT FASTENERS.						Service	ATA:53
	MOS	09-Mar-01						AIRWORTHINESS	
	HRS	0		T:9600					
	AFL	0							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:25
F5331022	^S	* MID CANTED BULKHEAD (F.S. 657) - PERFORM VISUAL INSPECTION AT MID SPAR UPPER ATTACHMENT FASTENERS						Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7		9600					
	AFL	7276							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:26
F5331023	^S	* AFT CANTED BULKHEAD (F.S. 682) - PERFORM VISUAL INSPECTION. INSPECT AT REAR SPAR ATTACHMENT FASTENERS.						Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7		9600					
	AFL	7276							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:26
F5331024	^S	* VERTICAL STABILIZER FRONT SPAR ROOT BULKHEAD ATTACHMENT (F.S. 630) - PERFORM VISUAL INSPECTION. INSPECT FRONT SPAR ROOT BULKHEAD ATTACHMENT AT FASTENER HOLES.						Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7		9600					
	AFL	7276							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:26
F5331025	^S	* VERTICAL STABILIZER MID SPAR ROOT BULKHEAD ATTACHMENT (F.S. 657) - PERFORM VISUAL INSPECTION. INSPECT MID SPAR ROOT BULKHEAD ATTACHMENT AT FASTENER HOLES.						Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7		9600					
	AFL	7276							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:26

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
F5331026	^S	* VERTICAL STABILIZER REAR SPAR ROOT BULKHEAD ATTACHMENT (F.S. 682) - PERFORM VISUAL INSPECTION. INSPECT REAR SPAR ROOT BULKHEAD ATTACHMENT AT FASTENER HOLES.						Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:26
H5323032		* EXTERIOR CABIN WINDOW COAMINGS (UNPAINTED) - PERFORM EDDY CURRENT INSPECTION						Service	ATA:53
	MOS	11-Mar-25	24		11-Mar-27		177 d	AIRWORTHINESS	
	HRS	9645.6	2400		12045.6		1944.2		
	AFL	7359							
PROC. REF: NDT PART 6/56-20-01PROC. REF: NDT PART 6/56-20-01									
H5323092		* EXTERIOR CABIN WINDOW COAMINGS (PAINTED) - PERFORM EDDY CURRENT INSPECTION						Service	ATA:53
	MOS/MSC	30-Apr-06	N/A						
	HRS	4466.8							
	AFL	3408							
PROC. REF: NDT PART 6/56-20-01PROC. REF: NDT PART 6/56-20-01									
M5313001		FORWARD FUSELAGE SKIN - PERFORM PITOT-STATIC PROBE ZONE SKIN CONTOUR CHECK						Service	ATA:53
	MOS	24-Aug-26	24	Adj -14d	10-Aug-28		695 d		
	HRS	10074							
	AFL	7658							
PROC. REF: AMM 53-00-01PROC. REF: AMM 53-00-01									
M5323021	^S	* EXTERNAL LONGERON, FASTENER LOCATIONS, AND AREA AROUND WING ATTACHMENTS - PERFORM VISUAL INSPECTION. INSPECT LONGERON BETWEEN FS 398 AND FS 486, STRINGER 13 LEFT AND RIGHT						Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:26

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
M5323034	^S	* UPPER AND LOWER COUPE RAIL AND CENTER POST/WINDSHIELD RETAINER ATTACHMENT - PERFORM EDDY CURRENT INSPECTION						Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							
PROC. REF: NDT PART 6/53-30-03PROC. REF: NDT PART 6/53-30-03									PKG:26
N5314000	^S	* EMERGENCY EXIT DOOR SKIN CUTOUT CORNERS AND DOUBLERS (F.S. 370 - F.S. 398) - PERFORM EDDY CURRENT INSPECTION						Service	ATA:53
	MOS	25-Jun-26	96					AIRWORTHINESS	
	HRS	10023.1	2400						
	AFL	7616							
PROC. REF: NDT PART 6/53-30-01PROC. REF: NDT PART 6/53-30-01									PKG:19
N5323026	^S	* UPPER AND LOWER PASSENGER/CREW DOOR SKIN CUTOUT CORNERS (FS 224 - FS 256) - PERFORM EDDY CURRENT INSPECTION. INSPECT SKIN AT CORNERS OF PASSENGER/ CREW DOOR CUTOUT.						Service	ATA:53
	MOS	25-Jun-26	96					AIRWORTHINESS	
	HRS	10023.1	2400						
	AFL	7616							
PROC. REF: NDT PART 6/53-30-02PROC. REF: NDT PART 6/53-30-02									PKG:19
P5310003	^S	* AFT PRESSURE BULKHEAD SUPPORT POST (FS 457) - PERFORM EDDY CURRENT INSPECTION						Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							
PROC. REF: NDT PART 6/53-30-18PROC. REF: NDT PART 6/53-30-18									PKG:26
P5310004	^S	* AFT PRESSURE BULKHEAD FRAME PERIPHERY - PERFORM EDDY CURRENT INSPECTION						Service	ATA:53
	MOS	09-Mar-01						AIRWORTHINESS	
	HRS	0	T:9600						
	AFL	0							
PROC. REF: NDT PART 6/53-30-21PROC. REF: NDT PART 6/53-30-21									PKG:25

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C / W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
P5310006	^S	* FORWARD PRESSURE BULKHEAD - PERFORM EDDY CURRENT INSPECTION						Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							
PROC. REF: NDT PART 6/53-30-07PROC. REF: NDT PART 6/53-30-07									PKG:26
P5320001	^S	* FUSELAGE PRESSURE FLOOR STEP (FS 433 - FS 457) - PERFORM EDDY CURRENT INSPECTION						Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							
PROC. REF: NDT PART 6/53-20-01PROC. REF: NDT PART 6/53-20-01									PKG:26
P5323024	^S	* FUSELAGE SKIN CUT-OUTS ABOVE FUEL CELL - PERFORM EDDY CURRENT INSPECTION						Service	ATA:53
	MOS	09-Mar-01						AIRWORTHINESS	
	HRS	0	T:9600						
	AFL	0							
PROC. REF: NDT PART 6/53-30-12PROC. REF: NDT PART 6/53-30-12									PKG:25
P5323027	^S	* FUSELAGE FRAME AT FS 412 - PERFORM EDDY CURRENT INSPECTION						Service	ATA:53
	MOS	09-Mar-01						AIRWORTHINESS	
	HRS	0	T:9600						
	AFL	0							
PROC. REF: NDT PART 6/53-30-20PROC. REF: NDT PART 6/53-30-20									PKG:25
P5323029	^S	* MACHINED SPAR FRAMES SYSTEMS CUTOUTS (FS 398, FS 412, FS 432, FS 466) - PERFORM EDDY CURRENT INSPECTION						Service	ATA:53
	MOS	09-Mar-01						AIRWORTHINESS	
	HRS	0	T:9600						
	AFL	0							
PROC. REF: NDT PART 6/53-30-15PROC. REF: NDT PART 6/53-30-15									PKG:25

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
P5323033	^S	* FUSELAGE SKIN AT EMERGENCY DOOR EGRESS-LIGHT AND WING INSPECTION LIGHT - PERFORM EDDY CURRENT INSPECTION						Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							
PROC. REF: NDT PART 6/53-40-02PROC. REF: NDT PART 6/53-40-02									
P5323037	^S	* WINDSHIELD COUPE RAIL TIE ROD BRACKET - PERFORM EDDY CURRENT INSPECTION						Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							
PROC. REF: NDT PART 6/53-30-09PROC. REF: NDT PART 6/53-30-09									
P5323038	^S	* WINDSHIELD CENTER POST TO UPPER COUPE RAIL JOINT ATTACHMENT - PERFORM EDDY CURRENT INSPECTION						Service	ATA:53
	MOS	09-Mar-01						AIRWORTHINESS	
	HRS	0	T:9600						
	AFL	0							
PROC. REF: NDT PART 6/53-30-22PROC. REF: NDT PART 6/53-30-22									
P5323047	^S	* PRESSURE CABIN FUSELAGE CROWN SKIN - PERFORM EDDY CURRENT INSPECTION						Service	ATA:53
	MOS	25-Jun-26	96					AIRWORTHINESS	
	HRS	10023.1	2400						
	AFL	7616							
PROC. REF: NDT PART 6/53-10-04PROC. REF: NDT PART 6/53-10-04									
P5323049	^S	* FUSELAGE SKIN AT UPPER AND LOWER COUPE RAIL RUN-OUT JOINTS - PERFORM EDDY CURRENT INSPECTION						Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							
PROC. REF: NDT PART 6/53-30-11PROC. REF: NDT PART 6/53-30-11									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
P5323057	^S	* PRESSURE CABIN SKIN AT FUSELAGE STATION 451 - PERFORM EDDY CURRENT INSPECTION						Service	ATA:53
	MOS	25-Jun-26	96					AIRWORTHINESS	
	HRS	10023.1	2400						
	AFL	7616							
PROC. REF: NDT PART 6/53-30-06PROC. REF: NDT PART 6/53-30-06									PKG:19
P5323058	^S	* FUSELAGE SKIN AT F.S. 504 - PERFORM EDDY CURRENT INSPECTION						Service	ATA:53
	MOS	09-Mar-01						AIRWORTHINESS	
	HRS	0	T:9600						
	AFL	0							
PROC. REF: NDT PART 6/53-30-13PROC. REF: NDT PART 6/53-30-13									PKG:25
P5323069	^S	* CIRCUMFERENTIAL SKIN JOINT AT FORWARD PRESSURE BULKHEAD - PERFORM EDDY CURRENT INSPECTION						Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							
PROC. REF: NDT PART 6/53-30-08PROC. REF: NDT PART 6/53-30-08									PKG:26
P5323164	^S	* PERFORM FUSELAGE SKIN AND DOUBLER AROUND ECS DUCT CUTOUT - EDDY CURRENT INSPECTION.						Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							
PROC. REF: NDT PART 6/53-40-01PROC. REF: NDT PART 6/53-40-01									PKG:26
P5323165	^S	* WINDSHIELD CENTER POST TO LOWER COUPE RAIL JOINT ATTACHMENT - PERFORM EDDY CURRENT INSPECTION						Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							
PROC. REF: NDT PART 6/53-30-10PROC. REF: NDT PART 6/53-30-10									PKG:26

?-Insufficient Information

S-Suppressed Requirement

*-Estimated Due(New Requirement)

(EFF)-Effective C / W

(M)-Manual Due

U-User Task

Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
P5360006	^S	DELTA FIN ATTACH BOLT - PERFORM LIQUID PENETRANT INSPECTION						Service	ATA:53
	MOS	02-Aug-24							
	HRS	9525.7	9600						
	AFL	7276							
PROC. REF: NDT PART 8/53-10-02PROC. REF: NDT PART 8/53-10-02									PKG:26
Q5310023	^S	FORWARD AND AFT FUEL CELL BAY STRUCTURE, ANGLE REINFORCEMENT, STRINGER 1, LEFT AND RIGHT - PERFORM DETAILED VISUAL INSPECTION OF HI-LITE COLLARS						Service	ATA:53
	MOS	02-Aug-24							
	HRS	9525.7	9600						
	AFL	7276							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:26
Q5310025	^S	AFT FUSELAGE KEELBEAM LONGERON (LEFT AND RIGHT, BL 5.15, FS 466.30 - 495.12) AND AFT FUSELAGE KEELBEAM LOWER FRAME (FS 466.30, BL 9.55 LEFT THROUGH BL 9.55 RIGHT) - PERFORM DETAILED VISUAL INSPECTION OF HI-LITE COLLARS.						Service	ATA:53
	MOS	02-Aug-24							
	HRS	9525.7	9600						
	AFL	7276							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:26
Q5323048	^S	* FUSELAGE (PRESSURE CABIN) - PERFORM EDDY CURRENT INSPECTION INSPECT PRESSURE CABIN SKIN (LONGITUDINAL SKIN CRACKING)						Service	ATA:53
	MOS	09-Mar-01						AIRWORTHINESS	
	HRS	0	T:9600						
	AFL	0							
PROC. REF: NDT PART 6/53-30-05PROC. REF: NDT PART 6/53-30-05									PKG:25
Q5323051	^S	* LONGITUDINAL JOINTS INSIDE PRESSURE CABIN (FS 220 - FS 457) AND SKIN WITHIN ONE STRINGER BAY OF JOINT - PERFORM EDDY CURRENT INSPECTION. INSPECT SKIN FASTENER HOLES ALONG JOINTS AT STRINGER 10 LEFT AND RH, STRINGER 2 RIGHT, AND STRINGER 18 RIGHT						Service	ATA:53
	MOS	09-Mar-01						AIRWORTHINESS	
	HRS	0	T:9600						
	AFL	0							
PROC. REF: NDT PART 6/53-30-05PROC. REF: NDT PART 6/53-30-05									PKG:25

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
Q5323059	^S	* STRINGER TO FRAME JOINTS (FS 162 TO FS 213) - PERFORM EDDY CURRENT INSPECTION. INSPECT SKIN, STRINGERS, AND FRAMES AT JOINTS.						Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							
PROC. REF: NDT PART 6/53-30-05PROC. REF: NDT PART 6/53-30-05									PKG:26
T5310027	^S	* AFT PRESSURE BULKHEAD TOP MOUNTING STRUCTURE - PERFORM EDDY CURRENT INSPECTION.						Service	ATA:53
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							
PROC. REF: NDT PART 6/53-30-17PROC. REF: NDT PART 6/53-30-17									PKG:26
T5321089	^S	SEAT RAILS - PERFORM DETAILED INSPECTION OF SEAT RAIL (TRACK) SHEAR WEBS FOR CRACKING						Service	ATA:53
	MOS	25-Jun-26	24						
	HRS	10023.1	600						
	AFL	7616							
PROC. REF: AMM 53-20-01PROC. REF: AMM 53-20-01									PKG:7
T5323028	^S	* FUSELAGE TO WING ATTACH FITTINGS - PERFORM EDDY CURRENT INSPECTION						Service	ATA:53
	MOS	09-Mar-01						AIRWORTHINESS	
	HRS	0	T:9600						
	AFL	0							
PROC. REF: NDT PART 6/53-30-16PROC. REF: NDT PART 6/53-30-16									PKG:25
T5323166		* EXTERNAL SKIN CUT-OUTS/PENETRATIONS (PRESSURE CABIN) - PERFORM DETAILED VISUAL INSPECTION. INSPECT SKIN AND DOUBLERS AT ANTENNAS, ELECTRICAL COMPONENTS, AND ACCESS PANELS (EXCLUDING PITOT/STATIC PROBES, AOA STALL VANES, AND WING INSPECTION LIGHT).						Service	ATA:53
	MOS	02-Aug-24	144		02-Aug-36		3609 d	AIRWORTHINESS	
	HRS	9525.7	9600		19125.7		9024.3		
	AFL	7276							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
V5323168	* LOWER COUPE RAIL RADIUS/WINDSCREEN RETAINER ATTACH - PERFORM EDDY CURRENT INSPECTION							Service	ATA:53
	MOS	22-Jun-23						AIRWORTHINESS	
	HRS	9258.5	5000		14258.5		4157.1		
	AFL	7100							
PROC. REF: NDT PART 6/53-30-23, NDT PART 6/53-30-24PROC. REF: NDT PART 6/53-30-23, NDT PART 6/53-30-24									
Y5311001 ^S	NOSE LANDING GEAR ACTUATOR ATTACH FITTING AND SURROUNDING STRUCTURE - PERFORM VISUAL INSPECTION							Service	ATA:53
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
Y5311003 ^S	NOSE LANDING GEAR TRUNNION FITTING AND SURROUNDING STRUCTURE - PERFORM VISUAL INSPECTION							Service	ATA:53
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
Y5320000 ^S	CENTER PEDESTAL - PERFORM VISUAL INSPECTION							Service	ATA:53
	MOS	25-Jun-26	12						
	HRS	10023.1	300						
	AFL	7616							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
Y5321010 ^S	FLOORBOARDS AROUND GALLEY, LAVATORY, AND WATER TANK - PERFORM VISUAL INSPECTION							Service	ATA:53
	MOS	25-Jun-26	12						
	HRS	10023.1	300						
	AFL	7616							
PROC. REF: AMM 53-20-01PROC. REF: AMM 53-20-01									

? - Insufficient Information
S - Suppressed Requirement
* - Estimated Due(New Requirement)
(EFF) - Effective C / W
(M) - Manual Due
U - User Task
Ex - Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
Y5321011	^S	TAILCONE BAGGAGE COMPARTMENT - PERFORM VISUAL INSPECTION						Service	ATA:53
	MOS	25-Jun-26	24						
	HRS	10023.1	600						
	AFL	7616							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:8
Y5321088	^S	SEAT RAILS - REMOVE FLOORBOARD 230AL AND PERFORM VISUAL INSPECTION OF SEAT RAILS.						Service	ATA:53
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:13
Y5323020	^S	EXTERNAL FUSELAGE (PRESSURE CABIN) - PERFORM VISUAL INSPECTION OF ALL CABIN SKINS FROM F.S. 100 TO F.S.458. PAY PARTICULAR ATTENTION TO ALL CUTOUTS AND SKIN JOINTS. NO FAIRING ACCESS REQUIRED.						Service	ATA:53
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:13
Y5323031	^S	EXTERIOR CABIN WINDOW COAMINGS AND SURROUNDING FUSELAGE SKIN - PERFORM VISUAL INSPECTION USING 10X MAGNIFICATION AND ADEQUATE LIGHTING.						Service	ATA:53
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:13
Y5340007	^S	WING ATTACH FITTINGS - PERFORM VISUAL INSPECTION						Service	ATA:53
	MOS	25-Jun-26	96						
	HRS	10023.1	2400						
	AFL	7616							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:19

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 10101.4
 AFL: 7674
 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
Y5360000	^S	DELTA FINS - PERFORM VISUAL INSPECTION							Service ATA:53
	MOS	25-Jun-26	24						
	HRS	10023.1	600						
	AFL	7616							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
ATA 54 - NACELLES/PYLONS									
545020		NO. 2 ENGINE AFT BEAM TO FRAME ATTACHMENT BOLT							Component ATA:54
PN:NAS6706U52D	MOS/MSC	25-Jun-26	H/T	TSN 0					
SN:UNKNOWN	HRS	10023.1		TSN 0					
	AFL	7616		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
545021		NO. 1 ENGINE AFT MOUNT TO END FITTING ATTACH BOLT							Component ATA:54
PN:NAS8705D30	MOS/MSC	25-Jun-26	H/T	TSN 0					
SN:UNKNOWN	HRS	10023.1		TSN 0					
	AFL	7616		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
545022		NO. 2 ENGINE AFT MOUNT TO END FITTING ATTACH BOLT							Component ATA:54
PN:NAS8705D30	MOS/MSC	25-Jun-26	H/T	TSN 0					
SN:UNKNOWN	HRS	10023.1		TSN 0					
	AFL	7616		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
545023		NO. 1 ENGINE TO AFT ENGINE MOUNT ATTACH BOLTS							Component ATA:54
PN:NAS8705D30	MOS/MSC	25-Jun-26	H/T	TSN 0					
SN:UNKNOWN	HRS	10023.1		TSN 0					
	AFL	7616		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
545024		NO. 2 ENGINE TO AFT ENGINE MOUNT ATTACH BOLTS							Component ATA:54
PN:NAS8705D30	MOS/MSC	25-Jun-26	H/T	TSN 0					
SN:UNKNOWN	HRS	10023.1		TSN 0					
	AFL	7616		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 54 - NACELLES / PYLONS									
A5450022	* NO. 1 ENGINE AFT MOUNT TO END FITTING ATTACH BOLT - REPLACE OR PERFORM MAGNETIC PARTICLE INSPECTION								Service ATA:54
PN:NAS8705D30	MOS	25-Jun-26						LIFE LIMIT	
SN:UNKNOWN	HRS	10023.1	9600		19623.1		9521.7		
	AFL	7616							
A5450022	* NO. 2 ENGINE AFT MOUNT TO END FITTING ATTACH BOLT - REPLACE OR PERFORM MAGNETIC PARTICLE INSPECTION								Service ATA:54
PN:NAS8705D30	MOS	25-Jun-26						LIFE LIMIT	
SN:UNKNOWN	HRS	10023.1	9600		19623.1		9521.7		
	AFL	7616							
A5450026 ^S	* ENGINE DRAG STRUT - PERFORM EDDY CURRENT INSPECTION								Service ATA:54
	MOS	16-Jun-26						AIRWORTHINESS	
	HRS	10023.1	4800						
	AFL	7616							
PROC. REF: NDT PART 6/54-50-01PROC. REF: NDT PART 6/54-50-01									PKG:25
A5450028	NO. 1 ENGINE AFT ENGINE BEAM END FITTING - REPLACE								Service ATA:54
	MOS/MSC	09-Mar-01	N/A					N/A BY SERIAL NUMBER	
	HRS	0							
	AFL	0							
PROC. REF: AMM 53-40-02PROC. REF: AMM 53-40-02									
AB5450054	LEFT FORWARD ENGINE BEAM AND BEAM FITTING - PERFORM VISUAL INSPECTION, PAYING PARTICULAR ATTENTION OF THE FOLLOWING: A. UPPER CAPPING PLATE AT FASTENER HOLES, AND CHANNEL FLANGE AT FASTENER HOLES. B. BOLT HOLES, ESPECIALLY UPPER BOLT HOLE ON AFT FLANGE.								Service ATA:54
	MOS	26-Jul-23							
	HRS	9278	6000		15278		5176.6		
	AFL	7111							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 54 - NACELLES/PYLONS									
AB5450054	RIGHT FORWARD ENGINE BEAM AND BEAM FITTING - PERFORM VISUAL INSPECTION, PAYING PARTICULAR ATTENTION OF THE FOLLOWING: A. UPPER CAPPING PLATE AT FASTENER HOLES, AND CHANNEL FLANGE AT FASTENER HOLES. B. BOLT HOLES, ESPECIALLY UPPER BOLT HOLE ON AFT FLANGE.							Service	ATA:54
	MOS	26-Jul-23							
	HRS	9278	6000		15278		5176.6		
	AFL	7111							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
E5450029 ^S	* AFT ENGINE BEAM - PERFORM VISUAL INSPECTION INSPECT UPPER CAPPING PLATE, AROUND FASTENER HOLES IN THE CAPPING PLATE, AND CHANNEL FLANGE.							Service	ATA:54
	MOS	16-Jun-26						AIRWORTHINESS	
	HRS	10023.1	4800						
	AFL	7616							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
F5450019 ^S	* AFT ENGINE BEAM ATTACHMENT TO FRAMES - PERFORM VISUAL INSPECTION. INSPECT AFT ENGINE BEAM ATTACHMENT TO FRAMES.							Service	ATA:54
	MOS	16-Jun-26						AIRWORTHINESS	
	HRS	10023.1	4800						
	AFL	7616							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
H5450012 ^S	* FRAMES 39/40 (F.S. 512/518) AT ENGINE BEAM ATTACHMENT - PERFORM EDDY CURRENT INSPECTION. INSPECT OUTER FLANGE AND FRAME WEB AT ENGINE BEAM ATTACHMENT.							Service	ATA:54
	MOS	16-Jun-26						AIRWORTHINESS	
	HRS	10023.1	4800						
	AFL	7616							
PROC. REF: NDT PART 6/54-50-03PROC. REF: NDT PART 6/54-50-03									
M5450015 ^S	* FORWARD ENGINE BEAM, SPAR CAP, AND WEB - PERFORM EDDY CURRENT INSPECTION							Service	ATA:54
	MOS	16-Jun-26						AIRWORTHINESS	
	HRS	10023.1	4800						
	AFL	7616							
PROC. REF: NDT PART 6/54-50-05PROC. REF: NDT PART 6/54-50-05									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 54 - NACELLES / PYLONS									
M5450018	^S	* FORWARD ENGINE MOUNT ATTACHMENT BOLTS - PERFORM FLUORESCENT LIQUID PENETRANT INSPECTION						Service	ATA:54
	MOS	16-Jun-26						AIRWORTHINESS	
	HRS	10023.1	4800						
	AFL	7616							
PROC. REF: NDT PART 8/71-20-01PROC. REF: NDT PART 8/71-20-01									
M5450027		NO. 1 ENGINE FORWARD ENGINE BEAM END FITTING - REPLACE						Service	ATA:54
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
PROC. REF: AMM 53-40-02, AMM 53-40-02PROC. REF: AMM 53-40-02, AMM 53-40-02									
P5450011	^S	* DRAG STRUT ATTACHMENT FITTINGS - PERFORM EDDY CURRENT INSPECTION						Service	ATA:54
	MOS	16-Jun-26						AIRWORTHINESS	
	HRS	10023.1	4800						
	AFL	7616							
PROC. REF: NDT PART 6/53-10-03PROC. REF: NDT PART 6/53-10-03									
P5450016	^S	* FORWARD ENGINE BEAM END FITTING - PERFORM EDDY CURRENT INSPECTION						Service	ATA:54
	MOS	16-Jun-26						AIRWORTHINESS	
	HRS	10023.1	4800						
	AFL	7616							
PROC. REF: NDT PART 6/54-50-02PROC. REF: NDT PART 6/54-50-02									
P5450017	^S	* FORWARD ENGINE BEAM TO FRAME ATTACH BOLT - PERFORM LIQUID PENETRANT INSPECTION						Service	ATA:54
	MOS	16-Jun-26						AIRWORTHINESS	
	HRS	10023.1	4800						
	AFL	7616							
PROC. REF: NDT PART 8/53-40-01PROC. REF: NDT PART 8/53-40-01									
P5450020		* NO. 1 ENGINE AFT BEAM TO FRAME ATTACHMENT BOLT - REPLACE OR PERFORM LIQUID PENETRANT INSPECTION						Service	ATA:54
PN:NAS6706DU50	MOS	25-Jun-26						LIFE LIMIT	
SN:UNKNOWN	HRS	10023.1	9600		19623.1		9521.7		
	AFL	7616							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 54 - NACELLES / PYLONS									
P5450020	* NO. 2 ENGINE AFT BEAM TO FRAME ATTACHMENT BOLT - REPLACE OR PERFORM LIQUID PENETRANT INSPECTION							Service	ATA:54
PN:NAS6706U52D	MOS	25-Jun-26						LIFE LIMIT	
SN:UNKNOWN	HRS	10023.1	9600		19623.1		9521.7		
	AFL	7616							
P5450021 ^S	* ENGINE AFT ISOLATOR MOUNT FITTINGS - PERFORM LIQUID PENETRANT INSPECTION							Service	ATA:54
	MOS	16-Jun-26						AIRWORTHINESS	
	HRS	10023.1	4800						
	AFL	7616							
PROC. REF: NDT PART 8/71-20-03PROC. REF: NDT PART 8/71-20-03									
P5450023	* NO. 1 ENGINE TO AFT ENGINE MOUNT ATTACH BOLTS - REPLACE OR PERFORM LIQUID PENETRANT INSPECTION							Service	ATA:54
PN:NAS8705D30	MOS	25-Jun-26						LIFE LIMIT	
SN:UNKNOWN	HRS	10023.1	9600		19623.1		9521.7		
	AFL	7616							
P5450023	* NO. 2 ENGINE TO AFT ENGINE MOUNT ATTACH BOLTS - REPLACE OR PERFORM LIQUID PENETRANT INSPECTION							Service	ATA:54
PN:NAS8705D30	MOS	25-Jun-26						LIFE LIMIT	
SN:UNKNOWN	HRS	10023.1	9600		19623.1		9521.7		
	AFL	7616							
P5450024 ^S	* FUSELAGE FRAMES AT FS 543.55 AND 546.15 TO AFT ENGINE BEAM ATTACHMENT - PERFORM EDDY CURRENT INSPECTION.							Service	ATA:54
	MOS	16-Jun-26						AIRWORTHINESS	
	HRS	10023.1	4800						
	AFL	7616							
PROC. REF: NDT PART 6/53-30-14PROC. REF: NDT PART 6/53-30-14									

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C / W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 54 - NACELLES / PYLONS									
P5450025	^S	* FORWARD ENGINE BEAM AND FRAMES AT ATTACH HOLES - PERFORM EDDY CURRENT INSPECTION						Service	ATA:54
	MOS	16-Jun-26						AIRWORTHINESS	
	HRS	10023.1	4800						
	AFL	7616							
PROC. REF: NDT PART 6/54-50-03PROC. REF: NDT PART 6/54-50-03									
P5450030	^S	* AFT ENGINE BEAM END FITTING - PERFORM EDDY CURRENT INSPECTION						Service	ATA:54
	MOS	16-Jun-26						AIRWORTHINESS	
	HRS	10023.1	4800						
	AFL	7616							
PROC. REF: NDT PART 6/54-50-04PROC. REF: NDT PART 6/54-50-04									
Y5410002	^S	PYLONS - PERFORM VISUAL INSPECTION. INSPECT HILITE COLLARS COMMON TO MAIN ENGINE BEAM EXTERNAL TO FUSELAGE.						Service	ATA:54
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 54-00-01PROC. REF: AMM 54-00-01									
ATA 55 - STABILIZERS									
551005	HORIZONTAL STABILIZER ASSEMBLY							Component	ATA:55
PN:PN	MOS/MSC	02-Aug-24	O/C						
SN:UNKNOWN	HRS	9525.7							
	AFL	7276							
Special Properties: RII ITEM									
PROC. REF: AMM 27-40-01PROC. REF: AMM 27-40-01									
552031	LEFT ELEVATOR ASSEMBLY							Component	ATA:55
PN:4555201005-011	MOS/MSC	02-Aug-24	O/C						
SN:UNKNOWN	HRS	9525.7							
	AFL	7276							
Special Properties: RII ITEM									
PROC. REF: AMM 27-30-01PROC. REF: AMM 27-30-01									

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C / W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 55 - STABILIZERS									
552032	RIGHT ELEVATOR ASSEMBLY							Component	ATA:55
PN:4555201005-012	MOS/MSC	02-Aug-24	O/C						
SN:UNKNOWN	HRS	9525.7							
	AFL	7276							
Special Properties: RII ITEM									
PROC. REF: AMM 27-30-01PROC. REF: AMM 27-30-01									
553000	TAILCONE/VERTICAL STABILIZER ASSEMBLY							Component	ATA:55
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
554005	RUDDER ASSEMBLY							Component	ATA:55
PN:4555401000-023	MOS/MSC	02-Aug-24	O/C						
SN:UNKNOWN	HRS	9525.7							
	AFL	7276							
Special Properties: RII ITEM									
PROC. REF: AMM 27-20-01PROC. REF: AMM 27-20-01									
A5510014 ^S	* VERTICAL STABILIZER PIVOT FITTING BOTTOM PLATE - PERFORM DETAILED VISUAL INSPECTION. INSPECT AFT PORTION OF BOTTOM PLATE THROUGH LIGHTENING HOLE IN TOP PLATE, FORWARD PORTION OF BOTTOM PLATE THROUGH TOP PLATE CUTOUTS, AND BOTTOM OF OUTSIDE EXPOSED SURFACE OF PIVOT FITTING							Service	ATA:55
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
A5510021 ^S	* HORIZONTAL MID SPAR FROM CANTED RIB NUMBER 2 TO CANTED RIB NUMBER 3 - PERFORM DETAILED VISUAL INSPECTION							Service	ATA:55
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 55 - STABILIZERS									
A5540000	^S	* RUDDER RIB CAP (F.S. 698) - PERFORM VISUAL INSPECTION. INSPECT AROUND FASTENER HOLES AND LIGHTENING HOLES.						Service	ATA:55
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:26
AA5510034		HORIZONTAL STABILIZER PRIMARY AND SECONDARY BOLTS AND BUSHINGS - PERFORM DETAILED INSPECTION						Service	ATA:55
	MOS	16-Jul-19							
	HRS	8109	4800		12909		2807.6		
	AFL	6239							
PROC. REF: AMM 05-10-00, AMM 55-10-00PROC. REF: AMM 05-10-00, AMM 55-10-00									
E5510074	^S	* HORIZONTAL STABILIZER REAR SPAR FROM CANTED RIB NUMBER 2 TO CANTED RIB NUMBER 3 - PERFORM VISUAL INSPECTION. INSPECT REAR SPAR CAP AND FASTENERS.						Service	ATA:55
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:26
E5510075	^S	* HORIZONTAL STABILIZER OUTBOARD SPARS AND SKINS OUTBOARD OF CANTED RIB NUMBER 3 - PERFORM VISUAL INSPECTION. INSPECT SPAR CAPS AND FASTENERS						Service	ATA:55
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:26
E5510076	^S	* HORIZONTAL STABILIZER FRONT SPAR FROM CANTED RIB NO. 2 TO CANTED RIB NO. 3 - PERFORM VISUAL INSPECTION. INSPECT FRONT SPAR CAP AND FASTENERS.						Service	ATA:55
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:26

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 55 - STABILIZERS									
E5520003	^S	* ELEVATOR FRONT SPAR - PERFORM VISUAL INSPECTION. INSPECT SPAR CAP AT FASTENER HOLES						Service	ATA:55
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:26
E5520004	^S	* ELEVATOR RIB NO. 1 CAP - PERFORM VISUAL INSPECTION OF RIB NO. 1 CAP CROSS SECTION AND RIB CAP FLANGES AT TORQUE TUBE						Service	ATA:55
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:26
G5510000	^S	* HORIZONTAL STABILIZER ACTUATOR ATTACHMENT FITTING - PERFORM EDDY CURRENT INSPECTION						Service	ATA:55
	MOS	09-Mar-01						AIRWORTHINESS	
	HRS	0	4800						
	AFL	0							
PROC. REF: NDT PART 6/55-10-01PROC. REF: NDT PART 6/55-10-01									PKG:25
G5510023	^S	* HORIZONTAL STABILIZER ACTUATOR VERTICAL TAIL ATTACHMENT - PERFORM EDDY CURRENT INSPECTION						Service	ATA:55
	MOS	09-Mar-01						AIRWORTHINESS	
	HRS	0	4800						
	AFL	0							
PROC. REF: NDT PART 6/55-30-01PROC. REF: NDT PART 6/55-30-01									PKG:25
H5510033	^S	* HORIZONTAL STABILIZER ACTUATOR ATTACHMENT BOLTS - PERFORM LIQUID PENETRANT INSPECTION						Service	ATA:55
	MOS	09-Mar-01						AIRWORTHINESS	
	HRS	0	4800						
	AFL	0							
PROC. REF: NDT PART 8/27-40-01PROC. REF: NDT PART 8/27-40-01									PKG:25

? - Insufficient Information
S - Suppressed Requirement
* - Estimated Due(New Requirement)
(EFF) - Effective C / W
(M) - Manual Due
U - User Task
Ex - Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 55 - STABILIZERS									
M5510010	* HORIZONTAL STABILIZER AFT ROOT RIB - PERFORM EDDY CURRENT INSPECTION. INSPECT AFT ROOT RIB INTERNAL BETWEEN MID SPAR AND AFT SPAR AND UPPER AND LOWER SKINS EXTERNAL AT ATTACHMENT FASTENERS.							Service	ATA:55
	MOS	18-Aug-22						AIRWORTHINESS	
	HRS	9082.6	1200		10282.6		181.2		
	AFL	6994							
PROC. REF: NDT PART 6/55-10-03PROC. REF: NDT PART 6/55-10-03									
M5540022	RUDDER TORQUE TUBE - PERFORM BORESCOPE INSPECTION							Service	ATA:55
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
N5510005 ^S	* HORIZONTAL STABILIZER REAR SPAR CAP - PERFORM EDDY CURRENT INSPECTION. INSPECT REAR SPAR CAP AND WEB AT CENTER SPLICE							Service	ATA:55
	MOS	25-Jun-26	96					AIRWORTHINESS	
	HRS	10023.1	2400						
	AFL	7616							
PROC. REF: NDT PART 6/55-10-05PROC. REF: NDT PART 6/55-10-05									
N5510015 ^S	* VERTICAL STABILIZER PIVOT FITTING TOP PLATE - PERFORM EDDY CURRENT INSPECTION							Service	ATA:55
	MOS	25-Jun-26	96					AIRWORTHINESS	
	HRS	10023.1	2400						
	AFL	7616							
PROC. REF: NDT PART 6/55-30-02PROC. REF: NDT PART 6/55-30-02									
N5510016 ^S	* VERTICAL STABILIZER PIVOT FITTING TOWER SECTION FORWARD RADIUS - PERFORM EDDY CURRENT INSPECTION. INSPECT PIVOT FITTING AT TOWER SECTION RADIUS, PIVOT FITTING AND TOP PLATE AROUND ADJACENT FASTENERS, AND PIVOT FITTING SIDES AT TOWER SECTION RADIUS.							Service	ATA:55
	MOS	25-Jun-26	96					AIRWORTHINESS	
	HRS	10023.1	2400						
	AFL	7616							
PROC. REF: NDT PART 6/55-30-03PROC. REF: NDT PART 6/55-30-03									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 55 - STABILIZERS									
N5510069 ^S	* HORIZONTAL STABILIZER MID SPAR FLANGE ROOT RIB ATTACHMENT - PERFORM EDDY CURRENT INSPECTION							Service	ATA:55
	MOS	25-Jun-26	96					AIRWORTHINESS	
	HRS	10023.1	2400						
	AFL	7616							
PROC. REF: NDT PART 6/55-10-02PROC. REF: NDT PART 6/55-10-02									PKG:20
N5510082 ^S	* HORIZONTAL STABILIZER REAR SPAR FLANGE ROOT RIB ATTACHMENT - PERFORM EDDY CURRENT INSPECTION							Service	ATA:55
	MOS	25-Jun-26	96					AIRWORTHINESS	
	HRS	10023.1	2400						
	AFL	7616							
PROC. REF: NDT PART 6/55-10-04PROC. REF: NDT PART 6/55-10-04									PKG:20
P5510006 ^S	* VERTICAL STABILIZER FRONT SPAR AND MID SPAR - PERFORM RADIOGRAPHIC INSPECTION							Service	ATA:55
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							
PROC. REF: NDT PART 2/55-30-01PROC. REF: NDT PART 2/55-30-01									PKG:26
P5510008 ^S	* HORIZONTAL STABILIZER PRIMARY AND SECONDARY ATTACH BOLTS - PERFORM MAGNETIC PARTICLE INSPECTION							Service	ATA:55
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							
PROC. REF: NDT PART 7/55-30-02, NDT PART 7/55-30-03PROC. REF: NDT PART 7/55-30-02, NDT PART 7/55-30-03									PKG:26
P5510009 ^S	* HORIZONTAL STABILIZER MID SPAR UPPER CAP BL 0.0 TO BL 4.0 - PERFORM X-RAY INSPECTION							Service	ATA:55
	MOS	25-Jun-26	96					AIRWORTHINESS	
	HRS	10023.1	2400						
	AFL	7616							
PROC. REF: NDT PART 2/55-10-03PROC. REF: NDT PART 2/55-10-03									PKG:20

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 55 - STABILIZERS									
P5510011	^S	* HORIZONTAL STABILIZER MID SPAR AND REAR SPAR UPPER FLANGE AT ROOT RIB - PERFORM RADIOGRAPHIC INSPECTION						Service	ATA:55
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							
PROC. REF: NDT PART 2/55-10-01PROC. REF: NDT PART 2/55-10-01									PKG:26
P5510017	^S	* VERTICAL STABILIZER PIVOT FITTING TOWER SECTION - PERFORM EDDY CURRENT INSPECTION						Service	ATA:55
	MOS	25-Jun-26	96					AIRWORTHINESS	
	HRS	10023.1	2400						
	AFL	7616							
PROC. REF: NDT PART 6/55-30-05PROC. REF: NDT PART 6/55-30-05									PKG:20
P5510018	^S	* VERTICAL STABILIZER PIVOT FITTING LUGS - PERFORM EDDY CURRENT INSPECTION						Service	ATA:55
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							
PROC. REF: NDT PART 6/55-30-04PROC. REF: NDT PART 6/55-30-04									PKG:26
P5510019	^S	* ELEVATOR HINGES ON HORIZONTAL STABILIZER - PERFORM EDDY CURRENT INSPECTION						Service	ATA:55
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							
PROC. REF: NDT PART 6/55-20-02PROC. REF: NDT PART 6/55-20-02									PKG:26
P5510020	^S	* HORIZONTAL MID SPAR UPPER CAP - PERFORM EDDY CURRENT INSPECTION						Service	ATA:55
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							
PROC. REF: NDT PART 6/55-10-07PROC. REF: NDT PART 6/55-10-07									PKG:26

? - Insufficient Information
S - Suppressed Requirement
* - Estimated Due(New Requirement)
(EFF) - Effective C / W
(M) - Manual Due
U - User Task
Ex - Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 55 - STABILIZERS									
P5510024	^S	* ELEVATOR CONTROL HORN - PERFORM EDDY CURRENT INSPECTION						Service	ATA:55
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							
PROC. REF: NDT PART 6/55-20-01PROC. REF: NDT PART 6/55-20-01									PKG:26
P5510070	^S	* HORIZONTAL STABILIZER FRONT SPAR - PERFORM RADIOGRAPHIC INSPECTION						Service	ATA:55
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							
PROC. REF: NDT PART 2/55-10-02PROC. REF: NDT PART 2/55-10-02									PKG:26
P5510073	^S	* HORIZONTAL REAR SPAR UPPER CAP - PERFORM EDDY CURRENT INSPECTION						Service	ATA:55
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							
PROC. REF: NDT PART 6/55-10-07PROC. REF: NDT PART 6/55-10-07									PKG:26
P5510092	^S	* HORIZONTAL STABILIZER UPPER SPAR SPLICE DOUBLER - PERFORM EDDY CURRENT INSPECTION						Service	ATA:55
	MOS	25-Jun-26	96					AIRWORTHINESS	
	HRS	10023.1	2400						
	AFL	7616							
PROC. REF: NDT PART 6/55-10-06PROC. REF: NDT PART 6/55-10-06									PKG:20
P5520001	^S	* ELEVATOR HINGE ATTACH BOLT - PERFORM MAGNETIC PARTICLE INSPECTION						Service	ATA:55
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							
PROC. REF: NDT PART 7/27-30-01PROC. REF: NDT PART 7/27-30-01									PKG:26

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 55 - STABILIZERS									
P5520002	^S	* ELEVATOR HINGE PIN - PERFORM LIQUID PENETRANT INSPECTION						Service	ATA:55
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							
PROC. REF: NDT PART 8/55-30-01PROC. REF: NDT PART 8/55-30-01									PKG:26
P5520021	^S	* ELEVATOR HINGE FITTINGS - PERFORM EDDY CURRENT INSPECTION						Service	ATA:55
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							
PROC. REF: NDT PART 6/55-30-07PROC. REF: NDT PART 6/55-30-07									PKG:26
P5520022	^S	* ELEVATOR HINGE PRIMARY AND SECONDARY ATTACH BOLTS - PERFORM LIQUID PENETRANT INSPECTION						Service	ATA:55
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							
PROC. REF: NDT PART 8/27-30-01, NDT PART 8/27-30-02PROC. REF: NDT PART 8/27-30-01, NDT PART 8/27-30-02									PKG:26
P5540001	^S	* RUDDER SPAR - PERFORM DETAILED VISUAL INSPECTION. INSPECT SPAR CAPS AND FASTENERS						Service	ATA:55
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:26
P5540002	^S	* RUDDER ATTACH BOLT - PERFORM LIQUID PENETRANT INSPECTION						Service	ATA:55
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							
PROC. REF: NDT PART 8/55-30-02PROC. REF: NDT PART 8/55-30-02									PKG:26

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 55 - STABILIZERS									
Q5510007 ^S	* VERTICAL STABILIZER SKIN AND LOWER AFT SPAR CAP - PERFORM EDDY CURRENT INSPECTION								Service ATA:55
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							
PROC. REF: NDT PART 6/55-30-06PROC. REF: NDT PART 6/55-30-06									
PKG:26									
Q5530011 ^S	* VERTICAL STABILIZER SKIN AND UPPER AFT SPAR CAP - PERFORM EDDY CURRENT INSPECTION								Service ATA:55
	MOS	25-Jun-26	96					AIRWORTHINESS	
	HRS	10023.1	2400						
	AFL	7616							
PROC. REF: NDT PART 6/55-30-06PROC. REF: NDT PART 6/55-30-06									
PKG:20									
T5510004 ^S	* RUDDER HINGE FITTINGS - PERFORM VISUAL INSPECTION. CONTROL SURFACE REMOVAL NOT REQUIRED.								Service ATA:55
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	9600						
	AFL	7276							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
PKG:26									
W5510091	* HORIZONTAL STABILIZER HINGE PRIMARY AND SECONDARY PIVOT PIN INSTALLATION AND ATTACHING HARDWARE - PERFORM DETAILED VISUAL INSPECTION								Service ATA:55
	MOS	25-Jun-26						MANDATORY	
	HRS	10023.1	625		10648.1		546.7		
	AFL	7616							
PROC. REF: AMM 05-10-00, AMM 55-10-00PROC. REF: AMM 05-10-00, AMM 55-10-00									
Y5510001 ^S	HORIZONTAL STABILIZER - PERFORM EXTERNAL VISUAL INSPECTION								Service ATA:55
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
PKG:14									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 55 - STABILIZERS									
Y5510002 ^S		ELEVATOR HINGES ON HORIZONTAL STABILIZER - PERFORM VISUAL INSPECTION. INSPECT HINGE LUGS ON HORIZONTAL TAIL SIDE OF JOINT. INSPECT HILITE COLLARS AT BL 0.0 AND OUTBOARD ELEVATOR HINGE.						Service	ATA:55
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:14
Y5510003 ^S		VERTICAL STABILIZER PIVOT FITTING - PERFORM VISUAL INSPECTION. INSPECT HI-LITE COLLARS COMMON TO THE PIVOT FITTING (MID SPAR, AFT SPAR, TOP PLATE, AND UP/DOWN SPRING BRACKET).						Service	ATA:55
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 55-00-01PROC. REF: AMM 55-00-01									PKG:14
Y5510093 ^S		HORIZONTAL STABILIZER - PERFORM VISUAL INSPECTION OF HI-LITE COLLARS IN THE FOLLOWING AREAS: - FORWARD SPAR TO BL 0.0 RIB - CENTER SPAR TO BL 0.0 RIB - CENTER SPAR SPLICE PLATE - AFT SPAR SPLICE PLATE - ROOT RIBS AT BL 3.70 (RIGHT AND LEFT) - UPPER DOUBLER SPAR SPLICE, BL 0.0 - HSTA UPPER ATTACH FITTING STRUCTURE						Service	ATA:55
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 55-00-01PROC. REF: AMM 55-00-01									PKG:14
Y5510094 ^S		LOWER BRACKET, HORIZONTAL STABILIZER TRIM ACTUATOR - PERFORM BORESCOPE INSPECTION OF HI-LITE COLLARS COMMON TO RIB NO. 6 AND MID SPAR.						Service	ATA:55
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 55-10-00PROC. REF: AMM 55-10-00									PKG:14
Y5540012 ^S		RUDDER TORQUE TUBE - LOOSEN TORQUE TUBE BONDING CLAMP AND PERFORM DETAILED VISUAL INSPECTION OF AREA AROUND BONDING CLAMP FOR CORROSION.						Service	ATA:55
	MOS	25-Jun-26	12						
	HRS	10023.1	300						
	AFL	7616							
PROC. REF: AMM 27-20-01PROC. REF: AMM 27-20-01									PKG:2

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
---------	------	-------	----------	------------	----------------------------	-----------	-----------	-------------	----------

ATA 55 - STABILIZERS

ATA 56 - WINDOWS

561001	LEFT WINDSHIELD							Component	ATA:56
PN:6656100000-001	MOS/MSC	02-Aug-24	O/C						
SN:1121	HRS	9525.7							
	AFL	7276							
Special Properties: RII ITEM									
PROC. REF: AMM 56-10-01, AMM 56-10-01PROC. REF: AMM 56-10-01, AMM 56-10-01									

561002	RIGHT WINDSHIELD							Component	ATA:56
PN:6656100001-002	MOS/MSC	25-Jun-26	O/C						
SN:1918	HRS	10023.1							
	AFL	7616							
Special Properties: RII ITEM									
PROC. REF: AMM 56-10-01, AMM 56-10-01PROC. REF: AMM 56-10-01, AMM 56-10-01									

562010-1	LEFT NO.1 CABIN WINDOW							Component	ATA:56
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01									

562010-10	RIGHT NO.5 CABIN WINDOW							Component	ATA:56
PN:7656202000-015	MOS/MSC	22-Dec-08	O/C	TSN 0					
SN:4621	HRS	6088.5		TSN 0					
	AFL	4660		TSN 0					
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01									

562010-11	LEFT NO.6 CABIN WINDOW							Component	ATA:56
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 56 - WINDOWS									
562010-12	RIGHT NO.6 CABIN WINDOW							Component	ATA:56
PN:7656202000-015	MOS/MSC	19-Dec-10	O/C						
SN:5304	HRS	6457.2							
	AFL	4944							
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01									
562010-13	LEFT NO.7 CABIN WINDOW							Component	ATA:56
PN:7656202000-015	MOS/MSC	28-Jun-16	O/C	TSN 0					
SN:6187	HRS	7635.4		TSN 0					
	AFL	5831		TSN 0					
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01									
562010-14	RIGHT NO.7 CABIN WINDOW							Component	ATA:56
PN:7656202000-015	MOS/MSC	17-Feb-05	O/C						
SN:0601	HRS	3300.2							
	AFL	2515							
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01									
562010-15	LEFT NO.8 CABIN WINDOW							Component	ATA:56
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01									
562010-16	EMERGENCY EXIT WINDOW							Component	ATA:56
PN:7656202000-015	MOS/MSC	13-Dec-10	O/C	TSN 0					
SN:5304	HRS	6457.2		TSN 0					
	AFL	4944		TSN 0					
PROC. REF: AMM 52-20-06PROC. REF: AMM 52-20-06									
562010-2	RIGHT NO.1 CABIN WINDOW							Component	ATA:56
PN:7656202000-015	MOS/MSC	21-Jun-05	O/C						
SN:1340	HRS	3694.5							
	AFL	2785							
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 56 - WINDOWS									
562010-3	LEFT NO.2 CABIN WINDOW							Component	ATA:56
PN:7656202000-015	MOS/MSC	22-Dec-08	O/C	TSN 0					
SN:4456	HRS	6088.5		TSN 0					
	AFL	4660		TSN 0					
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01									
562010-4	RIGHT NO.2 CABIN WINDOW							Component	ATA:56
PN:7656202000-015	MOS/MSC	17-Feb-05	O/C						
SN:0847	HRS	3300.2							
	AFL	2515							
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01									
562010-5	LEFT NO.3 CABIN WINDOW							Component	ATA:56
PN:7656202000-015	MOS/MSC	22-Dec-08	O/C	TSN 0					
SN:4505	HRS	6088.5		TSN 0					
	AFL	4660		TSN 0					
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01									
562010-6	RIGHT NO.3 CABIN WINDOW							Component	ATA:56
PN:7656202000-015	MOS/MSC	22-Dec-08	O/C	TSN 0					
SN:4458	HRS	6088.5		TSN 0					
	AFL	4660		TSN 0					
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01									
562010-7	LEFT NO.4 CABIN WINDOW							Component	ATA:56
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01									
562010-8	RIGHT NO.4 CABIN WINDOW							Component	ATA:56
PN:7656202000-015	MOS/MSC	17-Dec-10	O/C	TSN 0					
SN:5310	HRS	6457.2		TSN 0					
	AFL	4944		TSN 0					
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01									

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C / W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 56 - WINDOWS									
562010-9	LEFT NO.5 CABIN WINDOW							Component	ATA:56
PN:7656202000-015	MOS/MSC	15-Dec-10	O/C	TSN 0					
SN:5307	HRS	6457.2		TSN 0					
	AFL	4944		TSN 0					
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01									
L5600010 S	* CABIN WINDOWS (INCLUDING THE EMERGENCY EXIT WINDOW) - PERFORM DETAILED VISUAL INSPECTION							Service	ATA:56
	MOS	09-Mar-01						AIRWORTHINESS	
	HRS	0	4800						
	AFL	0							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
N5600003	* LEFT WINDSHIELD - PERFORM ULTRASONIC INSPECTION OF STRUCTURAL PLIES							Service	ATA:56
PN:6656100000-001	MOS/MSC	02-Aug-24	N/A						
SN:1121	HRS	9525.7							
	AFL	7276							
PROC. REF: NDT PART 4/56-10-01PROC. REF: NDT PART 4/56-10-01									
N5600003	* RIGHT WINDSHIELD - PERFORM ULTRASONIC INSPECTION OF STRUCTURAL PLIES							Service	ATA:56
PN:6656100001-002	MOS/MSC	25-Jun-26	N/A						
SN:1918	HRS	10023.1							
	AFL	7616							
PROC. REF: NDT PART 4/56-10-01PROC. REF: NDT PART 4/56-10-01									
N5600012	* LEFT WINDSHIELD - PERFORM BOLT HOLE INSPECTION							Service	ATA:56
PN:6656100000-001	MOS	02-Aug-24						AIRWORTHINESS	
SN:1121	HRS	9525.7	4800		14325.7		4224.3		
	AFL	7276							
PROC. REF: AMM 56-10-01PROC. REF: AMM 56-10-01									
N5600012	* RIGHT WINDSHIELD - PERFORM BOLT HOLE INSPECTION							Service	ATA:56
PN:6656100001-002	MOS	25-Jun-26						AIRWORTHINESS	
SN:1918	HRS	10023.1	4800		14823.1		4721.7		
	AFL	7616							
PROC. REF: AMM 56-10-01PROC. REF: AMM 56-10-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 56 - WINDOWS									
W5600002		** WINDSHIELD - PERFORM RAIN REMOVAL COATING EFFECTIVENESS TEST						Service	ATA:56
	MOS	25-Jun-26	12	Adj -124d	21-Feb-27		159 d	AIRWORTHINESS	
	HRS	10023.1							
	AFL	7616							
PROC. REF: AMM 56-10-01, AMM 56-10-01PROC. REF: AMM 56-10-01, AMM 56-10-01									
Y5600000 ^S		WINDSHIELDS - PERFORM VISUAL INSPECTION (INTERIOR AND EXTERIOR)						Service	ATA:56
	MOS	25-Jun-26	12						
	HRS	10023.1	300						
	AFL	7616							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
Y5600001 ^S		CABIN WINDOWS - PERFORM VISUAL INSPECTION						Service	ATA:56
	MOS	25-Jun-26	24						
	HRS	10023.1	600						
	AFL	7616							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
Y5600013 ^S		WINDSHIELDS - PERFORM VISUAL INSPECTION OF THE AERODYNAMIC SEAL						Service	ATA:56
	MOS	25-Jun-26	12						
	HRS	10023.1	300						
	AFL	7616							
PROC. REF: AMM 56-10-01, AMM 56-10-01PROC. REF: AMM 56-10-01, AMM 56-10-01									
ATA 57 - WINGS									
571001		WING ASSEMBLY						Component	ATA:57
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 57-10-00PROC. REF: AMM 57-10-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
571010	LEFT MAIN LANDING GEAR ACTUATOR FITTING								Component ATA:57
PN:PN	MOS	09-Mar-01		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0	20000	TSN 0	20000		12326		
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01									
571011	RIGHT MAIN LANDING GEAR ACTUATOR FITTING								Component ATA:57
PN:PN	MOS	09-Mar-01		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0	20000	TSN 0	20000		12326		
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01									
573001	LEFT WINGLET FILLER								Component ATA:57
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
573002	RIGHT WINGLET FILLER								Component ATA:57
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
573090	LEFT WING WINGLET								Component ATA:57
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 57-30-01PROC. REF: AMM 57-30-01									
573091	LEFT WINGLET LEADING EDGE ASSEMBLY								Component ATA:57
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 57-30-01PROC. REF: AMM 57-30-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
573092	RIGHT WING WINGLET							Component	ATA:57
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 57-30-01PROC. REF: AMM 57-30-01									
573093	RIGHT WINGLET LEADING EDGE ASSEMBLY							Component	ATA:57
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 57-30-01PROC. REF: AMM 57-30-01									
574005	LEFT INBOARD LEADING EDGE							Component	ATA:57
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 57-40-01PROC. REF: AMM 57-40-01									
574007	RIGHT INBOARD LEADING EDGE							Component	ATA:57
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 57-40-01PROC. REF: AMM 57-40-01									
574011	LEFT INBOARD LEADING EDGE ACCESS SECTION							Component	ATA:57
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 57-40-01PROC. REF: AMM 57-40-01									
574013	RIGHT INBOARD LEADING EDGE ACCESS SECTION							Component	ATA:57
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 57-40-01PROC. REF: AMM 57-40-01									

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C / W
(M)-Manual Due
U-User Task
Ex-Excluded Task

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
574033	LEFT CENTER LEADING EDGE							Component	ATA:57
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 57-40-01PROC. REF: AMM 57-40-01									
574035	RIGHT CENTER LEADING EDGE							Component	ATA:57
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 57-40-01PROC. REF: AMM 57-40-01									
574039	LEFT OUTBOARD LEADING EDGE ACCESS SECTION							Component	ATA:57
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 57-40-01PROC. REF: AMM 57-40-01									
574041	RIGHT OUTBOARD LEADING EDGE ACCESS SECTION							Component	ATA:57
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 57-40-01PROC. REF: AMM 57-40-01									
574050	LEFT OUTBOARD LEADING EDGE							Component	ATA:57
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 57-40-01PROC. REF: AMM 57-40-01									
574051	RIGHT OUTBOARD LEADING EDGE							Component	ATA:57
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 57-40-01PROC. REF: AMM 57-40-01									

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C / W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 10101.4
 AFL: 7674
 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
575001	LEFT FLAP ASSEMBLY							Component	ATA:57
PN:4557500006-007	MOS/MSC	25-Jun-26	O/C						
SN:474598000144	HRS	10023.1							
	AFL	7616							
Special Properties: RII ITEM									
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01									
575002	RIGHT FLAP ASSEMBLY							Component	ATA:57
PN:4557500006-008	MOS/MSC	25-Jun-26	O/C						
SN:474600100146	HRS	10023.1							
	AFL	7616							
Special Properties: RII ITEM									
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01									
576001	LEFT AILERON							Component	ATA:57
PN:4557600003-001	MOS/MSC	25-Jun-26	O/C						
SN:474607700145	HRS	10023.1							
	AFL	7616							
Special Properties: RII ITEM									
PROC. REF: AMM 27-10-02PROC. REF: AMM 27-10-02									
576002	RIGHT AILERON							Component	ATA:57
PN:4557600003-002	MOS/MSC	25-Jun-26	O/C						
SN:474609600145	HRS	10023.1							
	AFL	7616							
Special Properties: RII ITEM									
PROC. REF: AMM 27-10-02PROC. REF: AMM 27-10-02									
576037	LEFT AILERON BOLTS (X3)							Component	ATA:57
PN:NAS6204-16H	MOS/MSC	25-Jun-26	H/T	TSN 0					
SN:UNKNOWN	HRS	10023.1		TSN 0					
	AFL	7616		TSN 0					
PROC. REF: AMM 27-10-02PROC. REF: AMM 27-10-02									
576038	RIGHT AILERON BOLTS (X3)							Component	ATA:57
PN:NAS6204-16H	MOS/MSC	25-Jun-26	H/T	TSN 0					
SN:UNKNOWN	HRS	10023.1		TSN 0					
	AFL	7616		TSN 0					

?-Insufficient Information
 S-Suppressed Requirement
 *-Estimated Due(New Requirement)
 (EFF)-Effective C / W
 (M)-Manual Due
 U-User Task
 Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
PROC. REF: AMM 27-10-02PROC. REF: AMM 27-10-02									
577001	LEFT SPOILER --							Component	ATA:57
PN:4557700003-023	MOS/MSC	25-Jun-26	O/C						
SN:0175	HRS	10023.1							
	AFL	7616							
Special Properties: RII ITEM									
PROC. REF: AMM 27-60-01PROC. REF: AMM 27-60-01									
577002	RIGHT SPOILER --							Component	ATA:57
PN:4557700003-022	MOS/MSC	25-Jun-26	O/C						
SN:0186	HRS	10023.1							
	AFL	7616							
Special Properties: RII ITEM									
PROC. REF: AMM 27-60-01PROC. REF: AMM 27-60-01									
A5760004	* LEFT AILERON BOLTS (X3) - PERFORM MAGNETIC PARTICLE INSPECTION OR REPLACE							Service	ATA:57
PN:NAS6204-16H	MOS	25-Jun-26						AIRWORTHINESS	
SN:UNKNOWN	HRS	10023.1	9600		19623.1		9521.7		
	AFL	7616							
A5760004	* RIGHT AILERON BOLTS (X3) - PERFORM MAGNETIC PARTICLE INSPECTION OR REPLACE							Service	ATA:57
PN:NAS6204-16H	MOS	25-Jun-26						AIRWORTHINESS	
SN:UNKNOWN	HRS	10023.1	9600		19623.1		9521.7		
	AFL	7616							
AC5710190	* LEFT WING CENTER SECTION (PANELS 510AC, 510BC, 510BL AND 610BR REMOVED AND PANELS 510AL, 610AR, 720BL, AND 730BR LOWERED) - PERFORM VISUAL INSPECTION. INSPECT STRUCTURE FOR CORROSION OR DETERIORATION OF PROTECTIVE TREATMENT.							Service	ATA:57
	MOS	31-Mar-20	96		31-Mar-28		563 d		
	HRS	8253.8							
	AFL	6353							
PROC. REF: AMM 57-10-00PROC. REF: AMM 57-10-00									

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C / W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
AC5710190	* RIGHT WING CENTER SECTION (PANELS 510AC, 510BC, 510BL AND 610BR REMOVED AND PANELS 510AL, 610AR, 720BL, AND 730BR LOWERED) - PERFORM VISUAL INSPECTION. INSPECT STRUCTURE FOR CORROSION OR DETERIORATION OF PROTECTIVE TREATMENT.							Service	ATA:57
	MOS	31-Mar-20	96		31-Mar-28		563 d		
	HRS	8253.8							
	AFL	6353							
PROC. REF: AMM 57-10-00PROC. REF: AMM 57-10-00									
AE5710035 ^S	* WING LOWER SKIN AT DRAIN HOLE (4 LOCATIONS) - PERFORM EDDY CURRENT INSPECTION							Service	ATA:57
	MOS	25-Jun-26						AIRWORTHINESS	
	HRS	10023.1	4800						
	AFL	7616							
PROC. REF: NDT PART 6/57-30-02PROC. REF: NDT PART 6/57-30-02									
AE5710187	* LOWER WING FUEL DRAIN HOLES (4 LOCATIONS) - PERFORM EDDY CURRENT INSPECTION							Service	ATA:57
	MOS	EFF	72		11-Dec-31 *		1913 d	AIRWORTHINESS	
	HRS								
	AFL								
PROC. REF: NDT PART 6/57-30-03PROC. REF: NDT PART 6/57-30-03									
E5710005 ^S	* WING CENTER SECTION SPAR UPPER CAPS - PERFORM VISUAL INSPECTION. INSPECT FRONT, MID, AND REAR SPAR UPPER CAPS FROM CENTERLINE TO SKIN TERMINATION AT WS 33.							Service	ATA:57
	MOS	25-Jun-26						AIRWORTHINESS	
	HRS	10023.1	9600						
	AFL	7616							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
E5710019 ^S	* WING BOX, UPPER SKIN, SKIN/STRINGER AND SPAR CAPS - PERFORM VISUAL INSPECTION. INSPECT UPPER WING SPAR CAPS, SKIN PANEL, AND STRINGERS OF OUTER WING							Service	ATA:57
	MOS	25-Jun-26						AIRWORTHINESS	
	HRS	10023.1	9600						
	AFL	7616							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
E5710020	^S	* WING BOX RIBS - PERFORM VISUAL INSPECTION. INSPECT ALL WING BOX RIBS EXCEPT CLOSING RIB BETWEEN FRONT AND MID SPARS AND CLOSING RIB BETWEEN MID AND REAR SPAR.						Service	ATA:57
	MOS	25-Jun-26						AIRWORTHINESS	
	HRS	10023.1	9600						
	AFL	7616							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:26
E5750051		* FLAP MAIN TRACK ROLLERS - PERFORM VISUAL INSPECTION WITH FLAPS REMOVED						Service	ATA:57
	MOS	25-Jun-26						AIRWORTHINESS	
	HRS	10023.1	600		10623.1		521.7		
	AFL	7616							
PROC. REF: AMM 05-10-00, AMM 27-50-01PROC. REF: AMM 05-10-00, AMM 27-50-01									
E5750052		* FLAP NOSE ROLLERS - PERFORM VISUAL INSPECTION WITH FLAPS REMOVED						Service	ATA:57
	MOS	21-Aug-25						AIRWORTHINESS	
	HRS	9809.8	600		10409.8		308.4		
	AFL	7471							
Special Properties: RII ITEM PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
E5760006	^S	* AILERON BASIC STRUCTURE - PERFORM VISUAL INSPECTION						Service	ATA:57
	MOS	25-Jun-26						AIRWORTHINESS	
	HRS	10023.1	9600						
	AFL	7616							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:26
L5710124	^S	* AILERON DRIVE SUPPORT - PERFORM ULTRASONIC INSPECTION						Service	ATA:57
	MOS	09-Mar-01						AIRWORTHINESS	
	HRS	0	4800						
	AFL	0							
PROC. REF: NDT PART 4/27-10-01PROC. REF: NDT PART 4/27-10-01									PKG:25

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
N5710002	* WING BOX MID SPAR LOWER CAP, OUTBOARD OF JOINT AT WS 137 BETWEEN RIB NO. 7 AND 8 - PERFORM DIRECTED VISUAL INSPECTION. INSPECT MID SPAR LOWER CAP AND LOWER SKIN PANELS.							Service	ATA:57
	MOS	25-Jun-26						AIRWORTHINESS	
	HRS	10023.1	3580		13603.1		3501.7		
	AFL	7616							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
N5710004 ^S	* WING CENTER SECTION REAR SPAR - PERFORM EDDY CURRENT INSPECTION. INSPECT REAR SPAR LOWER CAP FROM CENTERLINE TO WS 33.							Service	ATA:57
	MOS	25-Jun-26						AIRWORTHINESS	
	HRS	10023.1	4800						
	AFL	7616							
PROC. REF: NDT PART 6/57-20-02PROC. REF: NDT PART 6/57-20-02									PKG:25
N5710006 ^S	* WING CENTER SECTION FORWARD AND AFT RIBS AT WS 6 AND FORWARD RIBS AT WS 17 - PERFORM EDDY CURRENT INSPECTION							Service	ATA:57
	MOS	25-Jun-26						AIRWORTHINESS	
	HRS	10023.1	4800						
	AFL	7616							
PROC. REF: NDT PART 6/57-10-06PROC. REF: NDT PART 6/57-10-06									PKG:25
N5710008	* WING BOX MID SPAR LOWER CAP - PERFORM ULTRASONIC INSPECTION. INSPECT MID SPAR LOWER CAP AND LOWER SKIN PANELS BETWEEN WS 99 AND WS 137							Service	ATA:57
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	2500		12025.7		1924.3		
	AFL	7276							
PROC. REF: NDT PART 4/57-30-03PROC. REF: NDT PART 4/57-30-03									
N5710009	* WING BOX MID SPAR LOWER CAP JOINT AT WS 137 - PERFORM X-RAY INSPECTION. INSPECT MID SPAR CENTER/OUTER JOINT							Service	ATA:57
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	4517		14042.7		3941.3		
	AFL	7276							
PROC. REF: NDT PART 2/57-10-02PROC. REF: NDT PART 2/57-10-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
N5710010	* WING BOX REAR SPAR LOWER CAP INBOARD OF JOINT AT WS 81 - PERFORM ULTRASONIC INSPECTION. INSPECT REAR SPAR LOWER CAP BETWEEN SKIN TERMINATION AT WS 48 AND CLOSING RIB AT WS 60.							Service	ATA:57
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	960		10485.7		384.3		
	AFL	7276							
PROC. REF: NDT PART 4/57-30-01PROC. REF: NDT PART 4/57-30-01									
N5710011 ^S	* WING BOX REAR SPAR LOWER CAP JOINT AT WS 81 - PERFORM X-RAY INSPECTION. INSPECT CENTER AND OUTER REAR SPARS, LOWER SPLICE PLATE, AND LOWER SKIN BETWEEN WS 60 AND WS 90.							Service	ATA:57
	MOS	25-Jun-26	96					AIRWORTHINESS	
	HRS	10023.1	2400						
	AFL	7616							
PROC. REF: NDT PART 2/57-10-03PROC. REF: NDT PART 2/57-10-03									
N5710012	* WING BOX REAR SPAR LOWER CAP OUTBOARD OF JOINT AT WS 81 TO RIB NUMBER 6 - PERFORM DETAILED VISUAL INSPECTION. INSPECT OUTER REAR SPAR LOWER CAP AND AFT LOWER SKIN PANEL OUTBOARD OF REAR SPLICE AT WS 90.							Service	ATA:57
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	3443		12968.7		2867.3		
	AFL	7276							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
N5710013	* WING BOX REAR SPAR LOWER CAP SKIN TERMINATION AT MS 48 - PERFORM EDDY CURRENT INSPECTION. INSPECT REAR SPAR LOWER CAP BETWEEN WS 33 AND WS 48.							Service	ATA:57
	MOS	25-Jun-26						AIRWORTHINESS	
	HRS	10023.1	1077		11100.1		998.7		
	AFL	7616							
PROC. REF: NDT PART 6/57-20-04PROC. REF: NDT PART 6/57-20-04									
N5710014 ^S	* WING BOX REAR SPAR FLAP TRACK CUTOUTS - PERFORM EDDY CURRENT INSPECTION. INSPECT FLAP TRACK CUTOUTS AT WS 65, WS 126, AND WS 184 ON REAR SPAR.							Service	ATA:57
	MOS	25-Jun-26						AIRWORTHINESS	
	HRS	10023.1	4800						
	AFL	7616							
PROC. REF: NDT PART 6/57-20-01PROC. REF: NDT PART 6/57-20-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
N5710016 ^S		* WING BOX BASIC SKIN/STRINGER, LOWER SKIN - PERFORM VISUAL INSPECTION. INSPECT OUTBOARD WING FORWARD AND AFT LOWER SKIN PANELS AND STRINGERS.						Service	ATA:57
	MOS	25-Jun-26						AIRWORTHINESS	
	HRS	10023.1	4800						
	AFL	7616							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:25
N5710017 ^S		* WING BOX BASIC SKIN/STRINGER AT STRINGER RUN-OUT, LOWER SKIN - PERFORM VISUAL INSPECTION. INSPECT STRINGER RUN-OUTS IN FORWARD AND AFT LOWER SKIN PANELS.						Service	ATA:57
	MOS	25-Jun-26						AIRWORTHINESS	
	HRS	10023.1	9600						
	AFL	7616							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:26
N5710021 ^S		* CENTER SECTION MID SPAR LOWER CAP - PERFORM EDDY CURRENT INSPECTION. INSPECT MID SPAR FROM CENTERLINE SPLICE PLATE TO SKIN TERMINATION AT MS 33.						Service	ATA:57
	MOS	25-Jun-26	96					AIRWORTHINESS	
	HRS	10023.1	2400						
	AFL	7616							
PROC. REF: NDT PART 6/57-10-02PROC. REF: NDT PART 6/57-10-02									PKG:22
N5710022 ^S		* CENTER SECTION MID SPAR CENTERLINE JOINT - PERFORM EDDY CURRENT INSPECTION. INSPECT CENTER MID SPAR (CENTERLINE TO WS 17), LOWER SPLICE PLATE, AND CENTER MID SPAR JOINT FITTING LOWER CAP.						Service	ATA:57
	MOS	25-Jun-26	96					AIRWORTHINESS	
	HRS	10023.1	2400						
	AFL	7616							
PROC. REF: NDT PART 6/57-10-08, NDT PART 6/57-10-10PROC. REF: NDT PART 6/57-10-08, NDT PART 6/57-10-10									PKG:22
N5710023 ^S		* CENTER SECTION FRONT SPAR LOWER CAP - PERFORM EDDY CURRENT INSPECTION. INSPECT CENTER WING FRONT SPAR LOWER CAP BETWEEN SKIN TERMINATIONS (WS 31 LEFT TO WS 31 RIGHT).						Service	ATA:57
	MOS	25-Jun-26	96					AIRWORTHINESS	
	HRS	10023.1	2400						
	AFL	7616							
PROC. REF: NDT PART 6/57-10-03PROC. REF: NDT PART 6/57-10-03									PKG:22

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
N5710026		* WING BOX MID SPAR LOWER CAP - PERFORM ULTRASONIC INSPECTION. INSPECT MID SPAR LOWER CAP OUTBOARD OF ROOT RIB AT WS 33 TO WS 99.						Service	ATA:57
	MOS	25-Jun-26						AIRWORTHINESS	
	HRS	10023.1	2278		12301.1		2199.7		
	AFL	7616							
PROC. REF: NDT PART 4/57-30-03PROC. REF: NDT PART 4/57-30-03									
N5710028 ^S		* WING BOX MID SPAR LOWER CAP, SKIN TERMINATION AT WS 33 - PERFORM BOLT HOLE EDDY CURRENT INSPECTION. INSPECT MID SPAR LOWER CAP UNDERNEATH ROOT RIB (WS 33) AT POINT OF SKIN TERMINATION.						Service	ATA:57
	MOS	25-Jun-26						AIRWORTHINESS	
	HRS	10023.1	4800						
	AFL	7616							
PROC. REF: NDT PART 6/57-10-11PROC. REF: NDT PART 6/57-10-11									
N5710031 ^S		* WING BOX SKIN ACCESS COVER HOLES - PERFORM EDDY CURRENT INSPECTION. INSPECT ACCESS HOLES IN FORWARD AND AFT LOWER SKIN PANELS.						Service	ATA:57
	MOS	25-Jun-26						AIRWORTHINESS	
	HRS	10023.1	4800						
	AFL	7616							
PROC. REF: NDT PART 6/57-30-01PROC. REF: NDT PART 6/57-30-01									
N5710037 ^S		* WING BOX FRONT SPAR LOWER CAP - PERFORM VISUAL INSPECTION. INSPECT FRONT SPAR LOWER CAP AND LOWER FORWARD SKIN OUTBOARD OF MID-SPAR STATION (MS) 55.						Service	ATA:57
	MOS	25-Jun-26	96					AIRWORTHINESS	
	HRS	10023.1	2400						
	AFL	7616							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
N5710084 ^S		SPOILER, CENTER HINGE SPOILER SIDE - PERFORM EDDY CURRENT INSPECTION						Service	ATA:57
	MOS	25-Jun-26	96						
	HRS	10023.1	2400						
	AFL	7616							
PROC. REF: NDT PART 6/57-40-01PROC. REF: NDT PART 6/57-40-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
N5710121	^S	* WING BOX MID SPAR, OUTBOARD OF RIB NUMBER 8 - PERFORM VISUAL INSPECTION AT WS 156 AND OUTBOARD TO WS 260						Service	ATA:57
	MOS	25-Jun-26						AIRWORTHINESS	
	HRS	10023.1	4800						
	AFL	7616							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:25
N5710122	^S	* WING BOX REAR SPAR, OUTBOARD OF RIB NUMBER 6 - PERFORM VISUAL INSPECTION AT WS 118 AND OUTBOARD TO WS 260						Service	ATA:57
	MOS	25-Jun-26						AIRWORTHINESS	
	HRS	10023.1	4800						
	AFL	7616							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:25
N5710123		* WING BOX MID SPAR LOWER CAP - PERFORM EDDY CURRENT INSPECTION AT TRUNNION FITTING						Service	ATA:57
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	2666		12191.7		2090.3		
	AFL	7276							
PROC. REF: NDT PART 6/57-10-01PROC. REF: NDT PART 6/57-10-01									
N5710137	^S	* MID SPAR AT RIB NO. 2 NEAR WS 48 - PERFORM BOLT HOLE EDDY CURRENT INSPECTION						Service	ATA:57
	MOS	25-Jun-26						AIRWORTHINESS	
	HRS	10023.1	4800						
	AFL	7616							
PROC. REF: NDT PART 6/57-10-11APROC. REF: NDT PART 6/57-10-11A									PKG:25
N5710138	^S	* MID SPAR AT RIB NO. 3 NEAR WS 60 - PERFORM BOLT HOLE EDDY CURRENT INSPECTION						Service	ATA:57
	MOS	25-Jun-26						AIRWORTHINESS	
	HRS	10023.1	4800						
	AFL	7616							
PROC. REF: NDT PART 6/57-10-11APROC. REF: NDT PART 6/57-10-11A									PKG:25

? - Insufficient Information
S - Suppressed Requirement
* - Estimated Due(New Requirement)
(EFF) - Effective C / W
(M) - Manual Due
U - User Task
Ex - Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
N5710139	^S	* FORWARD FLANGE FASTENERS AT REAR SPAR BETWEEN WS 52 AND WS 60 - PERFORM BOLT HOLE EDDY CURRENT INSPECTION						Service	ATA:57
	MOS	25-Jun-26	96					AIRWORTHINESS	
	HRS	10023.1	2400						
	AFL	7616							
PROC. REF: NDT PART 6/57-20-03PROC. REF: NDT PART 6/57-20-03									
N5710148		* WING CENTER SECTION REAR SPAR - PERFORM EDDY CURRENT INSPECTION. INSPECT REAR SPAR LOWER CAP FROM CENTERLINE TO WS 33.						Service	ATA:57
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
PROC. REF: NDT PART 6/57-20-02PROC. REF: NDT PART 6/57-20-02									
N5710149		* WING CENTER SECTION FORWARD AND AFT RIBS AT WS 6 AND FORWARD RIBS AT WS 17 - PERFORM EDDY CURRENT INSPECTION						Service	ATA:57
	MOS/MSC	25-Jun-26	N/A						
	HRS	10023.1							
	AFL	7616							
PROC. REF: NDT PART 6/57-10-06PROC. REF: NDT PART 6/57-10-06									
N5710150		* WING BOX MID SPAR LOWER CAP - PERFORM ULTRASONIC INSPECTION. INSPECT MID SPAR LOWER CAP AND LOWER SKIN PANELS BETWEEN WS 99 AND WS 137.						Service	ATA:57
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
PROC. REF: NDT PART 4/57-30-03PROC. REF: NDT PART 4/57-30-03									
N5710151		* WING BOX MID SPAR LOWER CAP JOINT AT WS 137 - PERFORM X-RAY INSPECTION. INSPECT MID SPAR CENTER/OUTER JOINT.						Service	ATA:57
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
PROC. REF: NDT PART 2/57-10-02PROC. REF: NDT PART 2/57-10-02									
N5710152		* WING BOX REAR SPAR LOWER CAP INBOARD OF JOINT AT WS 81 - PERFORM ULTRASONIC INSPECTION. INSPECT REAR SPAR LOWER CAP BETWEEN SKIN TERMINATION AT WS 48 AND CLOSING RIB AT WS 60.						Service	ATA:57
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
PROC. REF: NDT PART 4/57-30-01PROC. REF: NDT PART 4/57-30-01									
N5710153	* WING BOX REAR SPAR LOWER CAP JOINT AT WS 81 - PERFORM X-RAY INSPECTION. INSPECT CENTER AND OUTER REAR SPARS, LOWER SPLICE PLATE, AND LOWER SKIN BETWEEN WS 60 AND WS 90.							Service	ATA:57
	MOS/MSC	25-Jun-26	N/A						
	HRS	10023.1							
	AFL	7616							
PROC. REF: NDT PART 2/57-10-03PROC. REF: NDT PART 2/57-10-03									
N5710155	* WING BOX REAR SPAR LOWER CAP SKIN TERMINATION AT MS 48 - PERFORM EDDY CURRENT INSPECTION. INSPECT REAR SPAR LOWER CAP BETWEEN WS 33 AND WS 48.							Service	ATA:57
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
PROC. REF: NDT PART 6/57-20-04PROC. REF: NDT PART 6/57-20-04									
N5710157 ^S	* WING BOX BASIC SKIN/STRINGER AT STRINGER RUN-OUT, LOWER SKIN - PERFORM VISUAL INSPECTION. INSPECT STRINGER RUN-OUTS IN FORWARD AND AFT LOWER SKIN PANELS.							Service	ATA:57
	MOS/MSC	25-Jun-26	N/A						
	HRS	10023.1							
	AFL	7616							
									PKG:25
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
N5710158	* CENTER SECTION FRONT SPAR LOWER CAP - PERFORM EDDY CURRENT INSPECTION. INSPECT CENTER WING FRONT SPAR LOWER CAP BETWEEN SKIN TERMINATIONS (WS 31 LEFT TO WS 31 RIGHT).							Service	ATA:57
	MOS/MSC	25-Jun-26	N/A						
	HRS	10023.1							
	AFL	7616							
PROC. REF: NDT PART 6/57-10-03PROC. REF: NDT PART 6/57-10-03									
N5710159	* WING BOX MID SPAR LOWER CAP - PERFORM ULTRASONIC INSPECTION. INSPECT MID SPAR LOWER CAP OUTBOARD OF ROOT RIB AT WS 33 TO WS 99.							Service	ATA:57
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
PROC. REF: NDT PART 4/57-30-03PROC. REF: NDT PART 4/57-30-03									

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C/W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
N5710160		* WING BOX MID SPAR LOWER CAP, SKIN TERMINATION AT WS 33 - PERFORM BOLT HOLE EDDY CURRENT INSPECTION. INSPECT MID SPAR LOWER CAP UNDERNEATH ROOT RIB (WS 33) AT POINT OF SKIN TERMINATION.						Service	ATA:57
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
PROC. REF: NDT PART 6/57-10-11PROC. REF: NDT PART 6/57-10-11									
N5710161 ^S		* WING BOX SKIN ACCESS COVER HOLES - PERFORM EDDY CURRENT INSPECTION. INSPECT ACCESS HOLES IN FORWARD AND AFT LOWER SKIN PANELS.						Service	ATA:57
	MOS/MSC	25-Jun-26	N/A						
	HRS	10023.1							
	AFL	7616							
PROC. REF: NDT PART 6/57-30-01PROC. REF: NDT PART 6/57-30-01									
N5710163		* CENTER SECTION MID SPAR CENTERLINE JOINT - PERFORM EDDY CURRENT INSPECTION. INSPECT CENTER MID SPAR (CENTERLINE TO WS 17), LOWER SPLICE PLATE, AND CENTER MID SPAR JOINT FITTING LOWER CAP.						Service	ATA:57
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
PROC. REF: NDT PART 6/57-10-08, NDT PART 6/57-10-10PROC. REF: NDT PART 6/57-10-08, NDT PART 6/57-10-10									
N5710164		* CENTER SECTION MID SPAR LOWER CAP - PERFORM EDDY CURRENT INSPECTION. INSPECT MID SPAR FROM CENTERLINE SPLICE PLATE TO SKIN TERMINATION AT MS 33.						Service	ATA:57
	MOS/MSC	25-Jun-26	N/A						
	HRS	10023.1							
	AFL	7616							
PROC. REF: NDT PART 6/57-10-02PROC. REF: NDT PART 6/57-10-02									
N5710165		* WING BOX REAR SPAR FLAP TRACK CUT-OUTS - PERFORM EDDY CURRENT INSPECTION. INSPECT FLAP TRACK CUT-OUTS AT WS 65, WS 126, AND WS 184 ON REAR SPAR.						Service	ATA:57
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
PROC. REF: NDT PART 6/57-20-01PROC. REF: NDT PART 6/57-20-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
N5710168	* WING BOX MID SPAR LOWER CAP - PERFORM EDDY CURRENT INSPECTION AT TRUNNION FITTING							Service	ATA:57
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
PROC. REF: NDT PART 6/57-10-01PROC. REF: NDT PART 6/57-10-01									
N5710169	* MID SPAR AT RIB NO. 2 NEAR WS 48 - PERFORM BOLT HOLE EDDY CURRENT INSPECTION							Service	ATA:57
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
PROC. REF: NDT PART 6/57-10-11APROC. REF: NDT PART 6/57-10-11A									
N5710170	* MID SPAR AT RIB NO. 3 NEAR WS 60 - PERFORM BOLT HOLE EDDY CURRENT INSPECTION							Service	ATA:57
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
PROC. REF: NDT PART 6/57-10-11APROC. REF: NDT PART 6/57-10-11A									
N5710171	* FORWARD FLANGE FASTENERS AT REAR SPAR BETWEEN WS 52 AND WS 60 - PERFORM BOLT HOLE EDDY CURRENT INSPECTION							Service	ATA:57
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
PROC. REF: NDT PART 6/57-20-03PROC. REF: NDT PART 6/57-20-03									
N5710172	* WING BOX MID SPAR LOWER CAP - PERFORM ULTRASONIC INSPECTION AT TRUNNION FITTING							Service	ATA:57
	MOS	02-Aug-24							
	HRS	9525.7	2666		12191.7		2090.3		
	AFL	7276							
PROC. REF: NDT PART 4/57-10-00PROC. REF: NDT PART 4/57-10-00									
N5710173	* WING BOX MID SPAR LOWER CAP - PERFORM ULTRASONIC INSPECTION AT TRUNNION FITTING							Service	ATA:57
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
PROC. REF: NDT PART 4/57-10-00PROC. REF: NDT PART 4/57-10-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
N5710174	* WING BOX REAR SPAR LOWER CAP SKIN TERMINATION AT MS 48 - PERFORM ULTRASONIC INSPECTION. INSPECT REAR SPAR LOWER CAP BETWEEN WS 33 AND WS 48.							Service	ATA:57
	MOS	25-Jun-26						AIRWORTHINESS	
	HRS	10023.1	1077		11100.1		998.7		
	AFL	7616							
PROC. REF: NDT PART 4/57-30-04PROC. REF: NDT PART 4/57-30-04									
N5710175	* WING BOX REAR SPAR LOWER CAP SKIN TERMINATION AT WS 48 - PERFORM ULTRASONIC INSPECTION. INSPECT REAR SPAR LOWER CAP BETWEEN WS 33 AND WS 48.							Service	ATA:57
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
PROC. REF: NDT PART 4/57-30-04PROC. REF: NDT PART 4/57-30-04									
N5710176 ^S	* WING MID SPAR (CENTER SECTION) LOWER CAP AND CENTER JOINT FITTING - PERFORM ULTRASONIC INSPECTION							Service	ATA:57
	MOS	25-Jun-26	96					AIRWORTHINESS	
	HRS	10023.1	2400						
	AFL	7616							
PROC. REF: NDT PART 4/57-30-05PROC. REF: NDT PART 4/57-30-05									
N5710177	* WING MID SPAR (CENTER SECTION) LOWER CAP AND CENTER JOINT FITTING - PERFORM ULTRASONIC INSPECTION							Service	ATA:57
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
PROC. REF: NDT PART 4/57-30-05PROC. REF: NDT PART 4/57-30-05									
N5750005 ^S	* FLAP MAIN TRACK HINGE FITTINGS, TRACK, AND FLAP BOX SIDES - PERFORM VISUAL INSPECTION. INSPECT MAIN TRACK HINGE FITTINGS ON TRACK AND FLAP BOX SIDES.							Service	ATA:57
	MOS	25-Jun-26	96					AIRWORTHINESS	
	HRS	10023.1	2400						
	AFL	7616							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
P5710001	^S	* WING DRAG LINK ATTACH FITTING - PERFORM MAGNETIC PARTICLE INSPECTION						Service	ATA:57
	MOS	25-Jun-26	96					AIRWORTHINESS	
	HRS	10023.1	2400						
	AFL	7616							
PROC. REF: NDT PART 7/57-30-02PROC. REF: NDT PART 7/57-30-02									PKG:22
P5710007	^S	* WING TO FUSELAGE ATTACH FITTINGS AND LINKS - PERFORM EDDY CURRENT INSPECTION						Service	ATA:57
	MOS	25-Jun-26						AIRWORTHINESS	
	HRS	10023.1	4800						
	AFL	7616							
PROC. REF: NDT PART 6/57-10-12PROC. REF: NDT PART 6/57-10-12									PKG:25
P5710015	^S	* WING BOX REAR SPAR AT AILERON HINGE - PERFORM EDDY CURRENT INSPECTION						Service	ATA:57
	MOS	25-Jun-26						AIRWORTHINESS	
	HRS	10023.1	4800						
	AFL	7616							
PROC. REF: NDT PART 6/57-10-20PROC. REF: NDT PART 6/57-10-20									PKG:25
P5710018	^S	* WING LOWER SKIN AT MID SPAR SPAN WISE JOINT - PERFORM EDDY CURRENT INSPECTION.						Service	ATA:57
	MOS	25-Jun-26						AIRWORTHINESS	
	HRS	10023.1	9600						
	AFL	7616							
PROC. REF: NDT PART 6/57-10-09PROC. REF: NDT PART 6/57-10-09									PKG:26
P5710024	^S	* WING REAR SPAR SIDE STAY FITTING SUPPORT STRUCTURE - PERFORM EDDY CURRENT INSPECTION.						Service	ATA:57
	MOS	25-Jun-26						AIRWORTHINESS	
	HRS	10023.1	4800						
	AFL	7616							
PROC. REF: NDT PART 6/57-20-06PROC. REF: NDT PART 6/57-20-06									PKG:25

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C / W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
P5710025	^S	* WING FRONT SPAR LOWER CAP FROM WS 33.0 TO WS 60.0 - PERFORM RADIOGRAPHIC INSPECTION						Service	ATA:57
	MOS	25-Jun-26	96					AIRWORTHINESS	
	HRS	10023.1	2400						
	AFL	7616							
PROC. REF: NDT PART 2/57-10-01PROC. REF: NDT PART 2/57-10-01									PKG:22
P5710029	^S	* WING MID-SPAR VERTICAL WEB - PERFORM EDDY CURRENT INSPECTION						Service	ATA:57
	MOS	25-Jun-26						AIRWORTHINESS	
	HRS	10023.1	9600						
	AFL	7616							
PROC. REF: NDT PART 6/57-10-07PROC. REF: NDT PART 6/57-10-07									PKG:26
P5710030	^S	* WING REAR SPAR VERTICAL WEB - PERFORM EDDY CURRENT INSPECTION						Service	ATA:57
	MOS	25-Jun-26						AIRWORTHINESS	
	HRS	10023.1	9600						
	AFL	7616							
PROC. REF: NDT PART 6/57-20-05PROC. REF: NDT PART 6/57-20-05									PKG:26
P5710032	^S	* WING RIB UPPER AFT FLANGE FILLET RADIUS AT WS 33.0 - PERFORM ULTRASONIC INSPECTION						Service	ATA:57
	MOS	25-Jun-26						AIRWORTHINESS	
	HRS	10023.1	4800						
	AFL	7616							
PROC. REF: NDT PART 4/57-30-02PROC. REF: NDT PART 4/57-30-02									PKG:25
P5710033	^S	* WING ACCESS HOLE IN CLOSING RIB BETWEEN MID AND REAR SPAR - PERFORM EDDY CURRENT INSPECTION						Service	ATA:57
	MOS	25-Jun-26						AIRWORTHINESS	
	HRS	10023.1	4800						
	AFL	7616							
PROC. REF: NDT PART 6/57-10-05PROC. REF: NDT PART 6/57-10-05									PKG:25

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
P5710034	^S	* WING BOX JOINT TO WINGLET - PERFORM EDDY CURRENT INSPECTION						Service	ATA:57
	MOS	09-Mar-01						AIRWORTHINESS	
	HRS	0		T:9600					
	AFL	0							
PROC. REF: NDT PART 6/57-10-13PROC. REF: NDT PART 6/57-10-13									PKG:25
P5710083	^S	* FLAP BOX BASIC STRUCTURE - PERFORM EDDY CURRENT INSPECTION						Service	ATA:57
	MOS	25-Jun-26						AIRWORTHINESS	
	HRS	10023.1		4800					
	AFL	7616							
PROC. REF: NDT PART 6/57-40-02PROC. REF: NDT PART 6/57-40-02									PKG:25
P5710085	^S	SPOILER UPPER SKIN - PERFORM EDDY CURRENT INSPECTION						Service	ATA:57
	MOS	09-Mar-01							
	HRS	0		T:9600					
	AFL	0							
PROC. REF: NDT PART 6/57-10-16PROC. REF: NDT PART 6/57-10-16									PKG:25
P5710086	^S	SPOILER BOLTS AND HINGE PINS - PERFORM MAGNETIC PARTICLE INSPECTION						Service	ATA:57
	MOS	09-Mar-01							
	HRS	0		T:9600					
	AFL	0							
PROC. REF: NDT PART 7/27-10-01PROC. REF: NDT PART 7/27-10-01									PKG:25
P5710181	^S	* WING DRAG LINK TUBE - PERFORM MAGNETIC PARTICLE INSPECTION						Service	ATA:57
	MOS	25-Jun-26	96					AIRWORTHINESS	
	HRS	10023.1	2400						
	AFL	7616							
PROC. REF: NDT PART 7/57-30-01PROC. REF: NDT PART 7/57-30-01									PKG:22

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
P5710182	^S	* WING DRAG LINK ATTACH BOLTS - PERFORM LIQUID PENETRANT INSPECTION						Service	ATA:57
	MOS	25-Jun-26	96					AIRWORTHINESS	
	HRS	10023.1	2400						
	AFL	7616							
PROC. REF: NDT PART 8/57-10-01PROC. REF: NDT PART 8/57-10-01									PKG:22
P5710183	^S	* WING DRAG LINK ATTACH CLEVIS - PERFORM MAGNETIC PARTICLE INSPECTION						Service	ATA:57
	MOS	25-Jun-26	96					AIRWORTHINESS	
	HRS	10023.1	2400						
	AFL	7616							
PROC. REF: NDT PART 7/57-10-01PROC. REF: NDT PART 7/57-10-01									PKG:22
P5710184	^S	* WING ATTACH BOLTS - PERFORM FLUORESCENT PENETRANT INSPECTION						Service	ATA:57
	MOS	25-Jun-26						AIRWORTHINESS	
	HRS	10023.1	4800						
	AFL	7616							
PROC. REF: NDT PART 8/57-10-02PROC. REF: NDT PART 8/57-10-02									PKG:25
P5710185	^S	* WING ATTACH LINKS - PERFORM MAGNETIC PARTICLE INSPECTION						Service	ATA:57
	MOS	25-Jun-26						AIRWORTHINESS	
	HRS	10023.1	4800						
	AFL	7616							
PROC. REF: NDT PART 7/57-10-03PROC. REF: NDT PART 7/57-10-03									PKG:25
P5710186	^S	* WING ATTACH FITTINGS AT MID SPAR AND REAR SPAR - PERFORM MAGNETIC PARTICLE INSPECTION						Service	ATA:57
	MOS	25-Jun-26						AIRWORTHINESS	
	HRS	10023.1	4800						
	AFL	7616							
PROC. REF: NDT PART 7/57-10-02PROC. REF: NDT PART 7/57-10-02									PKG:25

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
P5750002 ^S	* FLAP FRONT SPAR CUTOUTS - PERFORM EDDY CURRENT INSPECTION								Service ATA:57
	MOS	25-Jun-26	96					AIRWORTHINESS	
	HRS	10023.1	2400						
	AFL	7616							
PROC. REF: NDT PART 6/57-10-15PROC. REF: NDT PART 6/57-10-15									PKG:22
P5750003 ^S	* FLAP NOSE ROLLER RIBS - PERFORM EDDY CURRENT INSPECTION								Service ATA:57
	MOS	25-Jun-26						AIRWORTHINESS	
	HRS	10023.1	4800						
	AFL	7616							
PROC. REF: NDT PART 6/57-10-14PROC. REF: NDT PART 6/57-10-14									PKG:25
P5750004 ^S	* FLAP ACTUATOR SUPPORT RIBS - PERFORM EDDY CURRENT INSPECTION								Service ATA:57
	MOS	25-Jun-26						AIRWORTHINESS	
	HRS	10023.1	9600						
	AFL	7616							
PROC. REF: NDT PART 6/57-10-21PROC. REF: NDT PART 6/57-10-21									PKG:26
P5750048 ^S	* FLAP TRACKS - PERFORM MAGNETIC PARTICLE INSPECTION								Service ATA:57
	MOS	25-Jun-26						AIRWORTHINESS	
	HRS	10023.1	9600						
	AFL	7616							
PROC. REF: NDT PART 7/57-71-01PROC. REF: NDT PART 7/57-71-01									PKG:26
P5750049 ^S	* FLAP NOSE ROLLER TRACKS - PERFORM MAGNETIC PARTICLE INSPECTION WITH FLAPS REMOVED								Service ATA:57
	MOS	25-Jun-26						AIRWORTHINESS	
	HRS	10023.1	9600						
	AFL	7616							
PROC. REF: NDT PART 7/57-10-04PROC. REF: NDT PART 7/57-10-04									PKG:26

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
P5750053	^S	* FLAP TRACK SUPPORT RIBS - PERFORM EDDY CURRENT INSPECTION						Service	ATA:57
	MOS	25-Jun-26						AIRWORTHINESS	
	HRS	10023.1	9600						
	AFL	7616							
PROC. REF: NDT PART 6/57-10-17PROC. REF: NDT PART 6/57-10-17									PKG:26
P5750068	^S	* FLAP FRONT-SPAR RIB SUPPORT STRUCTURE - PERFORM EDDY CURRENT INSPECTION						Service	ATA:57
	MOS	25-Jun-26						AIRWORTHINESS	
	HRS	10023.1	4800						
	AFL	7616							
PROC. REF: NDT PART 6/57-10-26PROC. REF: NDT PART 6/57-10-26									PKG:25
P5760000	^S	* AILERON ACTUATOR HINGE FITTING - PERFORM EDDY CURRENT INSPECTION						Service	ATA:57
	MOS	25-Jun-26						AIRWORTHINESS	
	HRS	10023.1	9600						
	AFL	7616							
PROC. REF: NDT PART 6/57-10-25PROC. REF: NDT PART 6/57-10-25									PKG:26
P5760001	^S	* AILERON SKIN - PERFORM EDDY CURRENT INSPECTION						Service	ATA:57
	MOS	25-Jun-26						AIRWORTHINESS	
	HRS	10023.1	9600						
	AFL	7616							
PROC. REF: NDT PART 6/57-10-19PROC. REF: NDT PART 6/57-10-19									PKG:26
P5760002	^S	* AILERON BALANCE TAB HINGE FITTINGS - PERFORM EDDY CURRENT INSPECTION						Service	ATA:57
	MOS	25-Jun-26	96					AIRWORTHINESS	
	HRS	10023.1	2400						
	AFL	7616							
PROC. REF: NDT PART 6/57-60-01PROC. REF: NDT PART 6/57-60-01									PKG:22

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
P5760003	^S	* AILERON TRIM AND BALANCE TAB FRONT SPARS - PERFORM RADIOGRAPHIC INSPECTION						Service	ATA:57
	MOS	25-Jun-26						AIRWORTHINESS	
	HRS	10023.1	4800						
	AFL	7616							
PROC. REF: NDT PART 2/57-60-01PROC. REF: NDT PART 2/57-60-01									PKG:25
P5760005	^S	* AILERON HINGE LUGS AND FITTINGS - PERFORM EDDY CURRENT INSPECTION						Service	ATA:57
	MOS	25-Jun-26						AIRWORTHINESS	
	HRS	10023.1	9600						
	AFL	7616							
PROC. REF: NDT PART 6/57-10-24PROC. REF: NDT PART 6/57-10-24									PKG:26
P5760014	^S	* AILERON HINGE SUPPORT STRUCTURE - PERFORM EDDY CURRENT INSPECTION						Service	ATA:57
	MOS	25-Jun-26						AIRWORTHINESS	
	HRS	10023.1	9600						
	AFL	7616							
PROC. REF: NDT PART 6/57-10-23PROC. REF: NDT PART 6/57-10-23									PKG:26
P5770000	^S	SPOILER HINGE ASSEMBLIES AND ACTUATOR FITTING - PERFORM EDDY CURRENT INSPECTION						Service	ATA:57
	MOS	09-Mar-01							
	HRS	0	T:9600						
	AFL	0							
PROC. REF: NDT PART 6/57-10-22PROC. REF: NDT PART 6/57-10-22									PKG:25
Q5710156	^S	* WING BOX BASIC SKIN/STRINGER, LOWER SKIN - PERFORM VISUAL INSPECTION. INSPECT OUTBOARD WING FORWARD AND AFT LOWER SKIN PANELS AND STRINGERS.						Service	ATA:57
	MOS/MSC	25-Jun-26	N/A						
	HRS	10023.1							
	AFL	7616							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:22

? - Insufficient Information
S - Suppressed Requirement
* - Estimated Due(New Requirement)
(EFF) - Effective C / W
(M) - Manual Due
U - User Task
Ex - Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
Q5710162 ^S	* WING BOX FRONT SPAR LOWER CAP - PERFORM VISUAL INSPECTION. INSPECT FRONT SPAR LOWER CAP AND LOWER FORWARD SKIN OUTBOARD OF MID-SPAR STATION (MS) 55.							Service	ATA:57
	MOS/MSC	25-Jun-26	N/A						
	HRS	10023.1							
	AFL	7616							
									PKG:22
Q5710166 ^S	* WING BOX MID SPAR, OUTBOARD OF RIB NO. 8 - PERFORM VISUAL INSPECTION AT WS 156 AND OUTBOARD TO WS 260							Service	ATA:57
	MOS/MSC	25-Jun-26	N/A						
	HRS	10023.1							
	AFL	7616							
									PKG:22
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
Q5710167 ^S	* WING BOX REAR SPAR, OUTBOARD OF RIB NO. 6 - PERFORM VISUAL INSPECTION AT WS 118 AND OUTBOARD TO WS 260							Service	ATA:57
	MOS/MSC	25-Jun-26	N/A						
	HRS	10023.1							
	AFL	7616							
									PKG:22
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
U5710147 ^S	* WING BOX MID SPAR LOWER CAP, OUTBOARD OF JOINT AT WS 137 BETWEEN RIB NO. 7 AND NO. 8 - PERFORM DETAILED VISUAL INSPECTION. INSPECT MID SPAR LOWER CAP AND LOWER SKIN PANELS.							Service	ATA:57
	MOS/MSC	25-Jun-26	N/A						
	HRS	10023.1							
	AFL	7616							
									PKG:10
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
U5710154 ^S	* WING BOX REAR SPAR LOWER CAP OUTBOARD OF JOINT AT WS 81 TO RIB NO. 6 - PERFORM DETAILED VISUAL INSPECTION. INSPECT OUTER REAR SPAR LOWER CAP AND AFT LOWER SKIN PANEL OUTBOARD OF REAR SPLICE AT WS 90.							Service	ATA:57
	MOS/MSC	25-Jun-26	N/A						
	HRS	10023.1							
	AFL	7616							
									PKG:10
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
V5710039	^S	WINGLET SKIN - PERFORM EDDY CURRENT INSPECTION						Service	ATA:57
	MOS	09-Mar-01							
	HRS	0	T:9600						
	AFL	0							
PROC. REF: NDT PART 6/57-10-18PROC. REF: NDT PART 6/57-10-18									PKG:25
Y5700001	^S	WINGLET - PERFORM VISUAL INSPECTION						Service	ATA:57
	MOS	25-Jun-26	12						
	HRS	10023.1	300						
	AFL	7616							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:4
Y5700002	^S	FLUX VALVE BRACKET - VISUALLY INSPECT FOR CRACKS						Service	ATA:57
	MOS	25-Jun-26	12						
	HRS	10023.1	300						
	AFL	7616							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:4
Y5710000	^S	WING - PERFORM EXTERNAL VISUAL INSPECTION FROM BL 0.00 TO WS 260						Service	ATA:57
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:16
Y5710180	^S	EXTERNAL LOWER WING SKIN - PERFORM VISUAL INSPECTION						Service	ATA:57
	MOS	25-Jun-26	24						
	HRS	10023.1	600						
	AFL	7616							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:10

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
Y5730013 ^S		AILERON BRUSH SEALS - PERFORM DETAILED INSPECTION						Service	ATA:57
	MOS	25-Jun-26	12						
	HRS	10023.1	300						
	AFL	7616							
PROC. REF: AMM 57-60-01PROC. REF: AMM 57-60-01									
Y5750067 ^S		FLAP BRACKETS - PERFORM DETAILED VISUAL INSPECTION						Service	ATA:57
	MOS	25-Jun-26	96						
	HRS	10023.1	2400						
	AFL	7616							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
Y5750069 ^S		FLAPS - PERFORM VISUAL INSPECTION OF FLAP NOSE ROLLERS, FLAP TRACKS, FLAP NOSE ROLLER TRACKS, AND FLAP MAIN TRACK ROLLERS.						Service	ATA:57
	MOS	25-Jun-26	12						
	HRS	10023.1	300						
	AFL	7616							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
Y5750071 ^S		FLAPS - WITH FLAPS REMOVED, PERFORM DETAILED VISUAL INSPECTION OF FLAP NOSE ROLLERS, FLAP TRACKS, FLAP NOSE ROLLER TRACKS, AND FLAP MAIN TRACK ROLLERS.						Service	ATA:57
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
ATA 71 - POWER PLANT									
710100		NO. 1 ENGINE - MAIN ENGINE WIRING HARNESS ASSEMBLY						Component	ATA:71
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-00-02, LMM 72-00-02PROC. REF: LMM 72-00-02, LMM 72-00-02									

? - Insufficient Information
S - Suppressed Requirement
* - Estimated Due(New Requirement)
(EFF) - Effective C / W
(M) - Manual Due
U - User Task
Ex - Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 71 - POWER PLANT									
710100	NO. 2 ENGINE - MAIN ENGINE WIRING HARNESS ASSEMBLY							Component	ATA:71
PN:3060757-3	MOS/MSC	06-Jul-23	O/C	TSN 0					
SN:22-129505-00163	HRS	8350.6		TSN 0					
	ENC	6943		TSN 0					
PROC. REF: LMM 72-00-02, LMM 72-00-02PROC. REF: LMM 72-00-02, LMM 72-00-02									
710130 ^S	NO. 1 ENGINE - INSPECT TAILPIPE/LPT3 ROTOR ASSEMBLY-VISUALLY INSPECT FOR FOREIGN OBJECT DAMAGE, THERMAL DISTRESS, AND LEAKS.							Service	ATA:71
	MOS	21-Aug-25							
	HRS	9735.7	800						
	ENC	7413							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									
710130 ^S	NO. 2 ENGINE - INSPECT TAILPIPE/LPT3 ROTOR ASSEMBLY-VISUALLY INSPECT FOR FOREIGN OBJECT DAMAGE, THERMAL DISTRESS, AND LEAKS.							Service	ATA:71
	MOS	21-Aug-25							
	HRS	8897	800						
	ENC	7309							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									
710140 ^S	NO. 1 ENGINE - INSPECT INLET/FAN AREA - INSPECT FOR FOREIGN OBJECT DAMAGE AND LEAKAGE (REFER TO PARAGRAPH 4.B)							Service	ATA:71
	MOS	21-Aug-25							
	HRS	9735.7	800						
	ENC	7413							
PROC. REF: LMM 72-00-00, LMM 72-00-00PROC. REF: LMM 72-00-00, LMM 72-00-00									
710140 ^S	NO. 2 ENGINE - INSPECT INLET/FAN AREA - INSPECT FOR FOREIGN OBJECT DAMAGE AND LEAKAGE (REFER TO PARAGRAPH 4.B)							Service	ATA:71
	MOS	21-Aug-25							
	HRS	8897	800						
	ENC	7309							
PROC. REF: LMM 72-00-00, LMM 72-00-00PROC. REF: LMM 72-00-00, LMM 72-00-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 71 - POWER PLANT									
711001	NO. 1 ENGINE FORWARD MOUNT							Component	ATA:71
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
711002	NO. 2 ENGINE FORWARD MOUNT							Component	ATA:71
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120005 ^U	CHANGE NO. 2 ALL							Service	ATA:71
	MOS/MSC		N/A						
	HRS								
	AFL								
7120005 ^U	REPLACE NO. 2 ENGINE AFT ENGINE MOUNT ISOLATOR BONDED MOUNTING							Service	ATA:71
	MOS/MSC	26-Jul-23	N/A	TAC 0					
	HRS	9278		TAC 0					
	AFL	7111		TAC 0					
7120006	REPLACE NO. 1 ENGINE ALL ENGINE MOUNT ISOLATOR FORWARD BONDED MOUNTING							Service	ATA:71
	MOS/MSC	09-Mar-01	N/A	TAC 0					
	HRS	0		TAC 0					
	AFL	0		TAC 0					
7120006 ^U	REPLACE NO. 2 ENGINE AFT ENGINE MOUNT ISOLATOR BONDED MOUNTING							Service	ATA:71
	MOS/MSC	09-Mar-01	N/A	TAC 0					
	HRS	0		TAC 0					
	AFL	0		TAC 0					

? - Insufficient Information
S - Suppressed Requirement
* - Estimated Due(New Requirement)
(EFF) - Effective C / W
(M) - Manual Due
U - User Task
Ex - Excluded Task

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 71 - POWER PLANT									
7120006 ^U		REPLACE NO. 2 ENGINE ALL ENGINE MOUNT ISOLATOR FORWARD BONDED MOUNTING						Service	ATA:71
	MOS/MSC	09-Mar-01	N/A	TAC	0				
	HRS	0		TAC	0				
	AFL	0		TAC	0				
712005		NO. 1 ENGINE - AFT ENGINE MOUNT - ISOLATOR ASSEMBLY						Component	ATA:71
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN	0				
SN:UNKNOWN	HRS	0		TSN	0				
	AFL	0		TSN	0				
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
712006		NO. 2 ENGINE - AFT ENGINE MOUNT - ISOLATOR ASSEMBLY						Component	ATA:71
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN	0				
SN:UNKNOWN	HRS	0		TSN	0				
	AFL	0		TSN	0				
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120069 ^U		NO. 1 ALL						Service	ATA:71
	MOS/MSC	26-Jul-23	N/A						
	HRS	9278							
	AFL	7111							
7120069 ^U		NO. 2 ALL						Service	ATA:71
	MOS/MSC	26-Jul-23	N/A						
	HRS	9278							
	AFL	7111							
712007		NO. 1 ENGINE - FORWARD ENGINE MOUNT - UPPER ISOLATOR ASSEMBLY						Component	ATA:71
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN	0				
SN:UNKNOWN	HRS	0		TSN	0				
	AFL	0		TSN	0				
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									

? - Insufficient Information
S - Suppressed Requirement
* - Estimated Due(New Requirement)
(EFF) - Effective C / W
(M) - Manual Due
U - User Task
Ex - Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 71 - POWER PLANT									
7120070 ^U		CHANGE NO. 1 ALL						Service	ATA:71
	MOS	26-Jul-23		TAC 0				LIFE LIMIT	
	HRS	9278	6000	TAC 0	15278		5176.6		
	AFL	7111		TAC 0					
7120070 ^U		CHANGE NO. 2 ALL						Service	ATA:71
	MOS	26-Jul-23		TAC 0				LIFE LIMIT	
	HRS	9278	6000	TAC 0	15278		5176.6		
	AFL	7111		TAC 0					
7120070 ^U		REPLACE NO. 2 ENGINE AFT ENGINE MOUNT ISOLATOR BONDED MOUNTING						Service	ATA:71
	MOS/MSC	26-Jul-23	O/C	TAC 0				LIFE LIMIT	
	HRS	9278		TAC 0					
	AFL	7111		TAC 0					
7120073 ^U		NO. 1 ALL						Service	ATA:71
	MOS	26-Jul-23							
	HRS	9278	6000		15278		5176.6		
	AFL	7111							
7120073 ^U		NO. 2 ALL						Service	ATA:71
	MOS	26-Jul-23							
	HRS	9278	6000		15278		5176.6		
	AFL	7111							
712008		NO. 2 ENGINE - FORWARD ENGINE MOUNT - UPPER ISOLATOR ASSEMBLY						Component	ATA:71
PN:LM833-SA20-5	MOS/MSC	26-Sep-06	O/C						
SN:LK3128	HRS	4857.22							
	AFL	3730							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									

? - Insufficient Information
S - Suppressed Requirement
* - Estimated Due(New Requirement)
(EFF) - Effective C / W
(M) - Manual Due
U - User Task
Ex - Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 71 - POWER PLANT									
712009	NO. 1 ENGINE - FORWARD ENGINE MOUNT - LOWER ISOLATOR ASSEMBLY								Component ATA:71
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
712010	NO. 2 ENGINE - FORWARD ENGINE MOUNT - LOWER ISOLATOR ASSEMBLY								Component ATA:71
PN:KM833-SA20-5	MOS/MSC	26-Sep-06	O/C						
SN:LK3185	HRS	4857.22							
	AFL	3730							
PROC. REF: NDT PART 7/32-10-08, NDT PART 7/32-10-03, NDT PART 7/32-10-04, NDT PART 8/32-10-02, NDT PART 8/54-30-01, NDT PART 8/54-30-02, AMM 71-20-00PROC. REF: NDT PART 7/32-10-08, NDT PART 7/32-10-03, NDT PART 7/32-10-04, NDT PART 8/32-10-02, NDT PART 8/54-30-01, NDT PART 8/54-30-02, AMM 71-20-00									
712045	NO. 1 ENGINE AFT MOUNT								Component ATA:71
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
712046	NO. 2 ENGINE AFT MOUNT								Component ATA:71
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
712078	NO. 1 ENGINE AFT MOUNT BOLT								Component ATA:71
PN:4571408525-001	MOS/MSC	26-Jul-23	E/C	TSN 0				AIRWORTHINESS	
SN:UNKNOWN	HRS	9278		TSN 0					
	AFL	7111		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
712079	NO. 2 ENGINE AFT MOUNT BOLT								Component ATA:71
PN:4571408525-001	MOS/MSC	26-Jul-23	E/C	TSN 0				AIRWORTHINESS	
SN:UNKNOWN	HRS	9278		TSN 0					
	AFL	7111		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 71 - POWER PLANT									
714010 ^S	NO. 1 ENGINE - CHECK ELECTRICAL WIRES AND CONNECTIONS - VISUALLY INSPECT FOR SECURITY AND DAMAGE							Service	ATA:71
	MOS	21-Aug-25							
	HRS	9735.7	800						
	ENC	7413							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									
714010 ^S	NO. 2 ENGINE - CHECK ELECTRICAL WIRES AND CONNECTIONS - VISUALLY INSPECT FOR SECURITY AND DAMAGE							Service	ATA:71
	MOS	21-Aug-25							
	HRS	8897	800						
	ENC	7309							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									
715010 ^S	NO. 1 ENGINE - CHECK PLUMBING LINES AND CONNECTIONS - VISUALLY INSPECT FOR SECURITY, LOOSE OR BROKEN CLAMPS OR BRACKETS, LEAKS, CRACKS, CUTS, OR RUBBING							Service	ATA:71
	MOS	21-Aug-25							
	HRS	9735.7	800						
	ENC	7413							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									
715010 ^S	NO. 2 ENGINE - CHECK PLUMBING LINES AND CONNECTIONS - VISUALLY INSPECT FOR SECURITY, LOOSE OR BROKEN CLAMPS OR BRACKETS, LEAKS, CRACKS, CUTS, OR RUBBING							Service	ATA:71
	MOS	21-Aug-25							
	HRS	8897	800						
	ENC	7309							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									
716005	NO. 1 ENGINE INLET NACELLE							Component	ATA:71
PN:4572290001-801	MOS/MSC	16-Jul-19	O/C						
SN:145LH	HRS	8109							
	AFL	6239							
PROC. REF: AMM 71-10-01PROC. REF: AMM 71-10-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 71 - POWER PLANT									
716006	NO. 2 ENGINE INLET NACELLE							Component	ATA:71
PN:2652000V24-003	MOS/MSC	02-Dec-09	O/C	TSR 0					
SN:114RH	HRS	6213.6		TSR 0					
	AFL	4758		TSR 0					
PROC. REF: AMM 71-10-01PROC. REF: AMM 71-10-01									
71EN1	NO. 1 ENGINE							Component	ATA:71
PN:3060082-2	MOS/MSC	25-Jun-26	E/C						
SN:P-116284C	HRS	10023.1							
	AFL	7616							
Special Properties: RII ITEM									
PROC. REF: SIL F731-88, AMM 71-00-01PROC. REF: SIL F731-88, AMM 71-00-01									
71EN2	NO. 2 ENGINE							Component	ATA:71
PN:3060084-2	MOS/MSC	25-Jun-26	E/C						
SN:P-116285C	HRS	10023.1							
	AFL	7616							
Special Properties: RII ITEM									
PROC. REF: SIL F731-88, AMM 71-00-01PROC. REF: SIL F731-88, AMM 71-00-01									
AA7120069	NO. 1 ENGINE - AFT ENGINE MOUNT - ISOLATOR ASSEMBLY - PERFORM VISUAL INSPECTION OF FORWARD AND AFT ISOLATORS AND ASSOCIATED PARTS							Service	ATA:71
	MOS	26-Jul-23							
	HRS	9278	3000		12278		2176.6		
	AFL	7111							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
AA7120069	NO. 1 ENGINE - FORWARD ENGINE MOUNT - LOWER ISOLATOR ASSEMBLY - PERFORM VISUAL INSPECTION OF FORWARD AND AFT ISOLATORS AND ASSOCIATED PARTS							Service	ATA:71
	MOS	26-Jul-23							
	HRS	9278	3000		12278		2176.6		
	AFL	7111							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 71 - POWER PLANT									
AA7120069		NO. 1 ENGINE - FORWARD ENGINE MOUNT - UPPER ISOLATOR ASSEMBLY - PERFORM VISUAL INSPECTION OF FORWARD AND AFT ISOLATORS AND ASSOCIATED PARTS						Service	ATA:71
	MOS	26-Jul-23							
	HRS	9278	3000		12278		2176.6		
	AFL	7111							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
AA7120069		NO. 2 ENGINE - AFT ENGINE MOUNT - ISOLATOR ASSEMBLY - PERFORM VISUAL INSPECTION OF FORWARD AND AFT ISOLATORS AND ASSOCIATED PARTS						Service	ATA:71
	MOS	26-Jul-23							
	HRS	9278	3000		12278		2176.6		
	AFL	7111							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
AA7120069		NO. 2 ENGINE - FORWARD ENGINE MOUNT - LOWER ISOLATOR ASSEMBLY - PERFORM VISUAL INSPECTION OF FORWARD AND AFT ISOLATORS AND ASSOCIATED PARTS						Service	ATA:71
PN:KM833-SA20-5	MOS	26-Jul-23							
SN:LK3185	HRS	9278	3000		12278		2176.6		
	AFL	7111							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
AA7120069		NO. 2 ENGINE - FORWARD ENGINE MOUNT - UPPER ISOLATOR ASSEMBLY - PERFORM VISUAL INSPECTION OF FORWARD AND AFT ISOLATORS AND ASSOCIATED PARTS						Service	ATA:71
PN:LM833-SA20-5	MOS	26-Jul-23							
SN:LK3128	HRS	9278	3000		12278		2176.6		
	AFL	7111							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
AD7120005		NO. 1 ENGINE - FORWARD ENGINE MOUNT - LOWER ISOLATOR ASSEMBLY - REPLACE BONDED MOUNTING						Service	ATA:71
	MOS/MSC	26-Jul-23	N/A	TAC 0					
	HRS	9278		TAC 0					
	AFL	7111		TAC 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
AD7120005		NO. 1 ENGINE - FORWARD ENGINE MOUNT - UPPER ISOLATOR ASSEMBLY - REPLACE BONDED MOUNTING						Service	ATA:71
	MOS/MSC	26-Jul-23	N/A	TAC 0					
	HRS	9278		TAC 0					
	AFL	7111		TAC 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 71 - POWER PLANT									
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
AD7120005	NO. 2 ENGINE - FORWARD ENGINE MOUNT - LOWER ISOLATOR ASSEMBLY - REPLACE BONDED MOUNTING								Service ATA:71
PN:KM833-SA20-5	MOS/MSC	26-Jul-23	N/A	TAC 0					
SN:LK3185	HRS	9278		TAC 0					
	AFL	7111		TAC 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
AD7120005	NO. 2 ENGINE - FORWARD ENGINE MOUNT - UPPER ISOLATOR ASSEMBLY - REPLACE BONDED MOUNTING								Service ATA:71
PN:LM833-SA20-5	MOS/MSC	26-Jul-23	N/A	TAC 0					
SN:LK3128	HRS	9278		TAC 0					
	AFL	7111		TAC 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
AD7120005 ^U	REPLACE NO. 1 ENGINE AFT ENGINE MOUNT ISOLATOR FORWARD BONDED MOUNTING								Service ATA:71
	MOS/MSC	26-Jul-23	N/A	TAC 0					
	HRS	9278		TAC 0					
	AFL	7111		TAC 0					
AD7120005	REPLACE NO. 1 ENGINE ALL ENGINE MOUNT ISOLATOR BONDED MOUNTING								Service ATA:71
	MOS/MSC	27-Sep-06	N/A						
	HRS	4857.2							
	AFL	3730							
AD7120006	NO. 1 ENGINE - FORWARD ENGINE MOUNT - LOWER ISOLATOR ASSEMBLY - REPLACE BONDED MOUNTING								Service ATA:71
	MOS/MSC	09-Mar-01	N/A	TAC 0					
	HRS	0		TAC 0					
	AFL	0		TAC 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
AD7120006	NO. 1 ENGINE - FORWARD ENGINE MOUNT - UPPER ISOLATOR ASSEMBLY - REPLACE BONDED MOUNTING								Service ATA:71
	MOS/MSC	09-Mar-01	N/A	TAC 0					
	HRS	0		TAC 0					
	AFL	0		TAC 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 71 - POWER PLANT									
AD7120006	NO. 2 ENGINE - FORWARD ENGINE MOUNT - LOWER ISOLATOR ASSEMBLY - REPLACE BONDED MOUNTING							Service	ATA:71
	MOS/MSC	09-Mar-01	N/A	TAC 0					
	HRS	0		TAC 0					
	AFL	0		TAC 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
AD7120006	NO. 2 ENGINE - FORWARD ENGINE MOUNT - UPPER ISOLATOR ASSEMBLY - REPLACE BONDED MOUNTING							Service	ATA:71
	MOS/MSC	09-Mar-01	N/A	TAC 0					
	HRS	0		TAC 0					
	AFL	0		TAC 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
AD7120006 ^U	REPLACE NO. 1 ENGINE AFT ENGINE MOUNT ISOLATOR BONDED MOUNTING							Service	ATA:71
	MOS/MSC	09-Mar-01	N/A	TAC 0					
	HRS	0		TAC 0					
	AFL	0		TAC 0					
AD7120070	NO. 1 ENGINE - FORWARD ENGINE MOUNT - LOWER ISOLATOR ASSEMBLY - REPLACE BONDED MOUNTING							Service	ATA:71
	MOS	26-Jul-23		TAC 0				LIFE LIMIT	
	HRS	9278	6000	TAC 0	15278		5176.6		
	AFL	7111		TAC 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
AD7120070	NO. 1 ENGINE - FORWARD ENGINE MOUNT - UPPER ISOLATOR ASSEMBLY - REPLACE BONDED MOUNTING							Service	ATA:71
	MOS	26-Jul-23		TAC 0				LIFE LIMIT	
	HRS	9278	6000	TAC 0	15278		5176.6		
	AFL	7111		TAC 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
AD7120070	NO. 2 ENGINE - FORWARD ENGINE MOUNT - LOWER ISOLATOR ASSEMBLY - REPLACE BONDED MOUNTING							Service	ATA:71
PN:KM833-SA20-5	MOS	26-Jul-23		TAC 0				LIFE LIMIT	
SN:LK3185	HRS	9278	6000	TAC 0	15278		5176.6		
	AFL	7111		TAC 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 71 - POWER PLANT									
AD7120070	NO. 2 ENGINE - FORWARD ENGINE MOUNT - UPPER ISOLATOR ASSEMBLY - REPLACE BONDED MOUNTING								Service ATA:71
PN:LM833-SA20-5	MOS	26-Jul-23		TAC 0				LIFE LIMIT	
SN:LK3128	HRS	9278	6000	TAC 0	15278		5176.6		
	AFL	7111		TAC 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
AD7120070 ^U	REPLACE NO. 1 ENGINE AFT ENGINE MOUNT ISOLATOR BONDED MOUNTING								Service ATA:71
	MOS/MSC	26-Jul-23	O/C	TAC 0				LIFE LIMIT	
	HRS	9278		TAC 0					
	AFL	7111		TAC 0					
AD7120075	NO. 1 ENGINE - AFT ENGINE MOUNT - ISOLATOR ASSEMBLY - PERFORM DETAILED INSPECTION OF AFT ISOLATOR ASSEMBLY AND ASSOCIATED PARTS								Service ATA:71
	MOS/MSC	26-Jul-23	MPI						
	HRS	9278	3600		12878		2776.6		
	AFL	7111							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
AD7120075	NO. 2 ENGINE - AFT ENGINE MOUNT - ISOLATOR ASSEMBLY - PERFORM DETAILED INSPECTION OF AFT ISOLATOR ASSEMBLY AND ASSOCIATED PARTS								Service ATA:71
	MOS/MSC	26-Jul-23	MPI						
	HRS	9278	3600		12878		2776.6		
	AFL	7111							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
K7120004	NO. 1 ENGINE - AFT ENGINE MOUNT - ISOLATOR ASSEMBLY - REPLACE HOUSING								Service ATA:71
	MOS	09-Mar-01		TAC 0				LIFE LIMIT	
	HRS	0	15000	TAC 0	15000		4898.6		
	AFL	0		TAC 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
K7120004	NO. 1 ENGINE - FORWARD ENGINE MOUNT - LOWER ISOLATOR ASSEMBLY - REPLACE HOUSING								Service ATA:71
	MOS	09-Mar-01		TAC 0				LIFE LIMIT	
	HRS	0	15000	TAC 0	15000		4898.6		
	AFL	0		TAC 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 71 - POWER PLANT									
K7120004	NO. 1 ENGINE - FORWARD ENGINE MOUNT - UPPER ISOLATOR ASSEMBLY - REPLACE HOUSING							Service	ATA:71
	MOS	09-Mar-01		TAC 0				LIFE LIMIT	
	HRS	0	15000	TAC 0	15000		4898.6		
	AFL	0		TAC 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
K7120004	NO. 2 ENGINE - AFT ENGINE MOUNT - ISOLATOR ASSEMBLY - REPLACE HOUSING							Service	ATA:71
	MOS	09-Mar-01		TAC 0				LIFE LIMIT	
	HRS	0	15000	TAC 0	15000		4898.6		
	AFL	0		TAC 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
K7120004	NO. 2 ENGINE - FORWARD ENGINE MOUNT - LOWER ISOLATOR ASSEMBLY - REPLACE HOUSING							Service	ATA:71
	MOS	09-Mar-01		TAC 0				LIFE LIMIT	
	HRS	0	15000	TAC 0	15000		4898.6		
	AFL	0		TAC 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
K7120004	NO. 2 ENGINE - FORWARD ENGINE MOUNT - UPPER ISOLATOR ASSEMBLY - REPLACE HOUSING							Service	ATA:71
	MOS	09-Mar-01		TAC 0				LIFE LIMIT	
	HRS	0	15000	TAC 0	15000		4898.6		
	AFL	0		TAC 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
K7120004 ^U	REPLACE ALL FORWARD AND AFT ENGINE MOUNT ISOLATOR HOUSINGS							Service	ATA:71
	MOS	09-Mar-01		TAC 0				LIFE LIMIT	
	HRS	0	15000	TAC 0	15000		4898.6		
	AFL	0		TAC 0					
P7120001 ^S	* FORWARD ENGINE MOUNT - PERFORM EDDY CURRENT INSPECTION							Service	ATA:71
	MOS	16-Jun-26						AIRWORTHINESS	
	HRS	10023.1	4800						
	AFL	7616							
PROC. REF: NDT PART 6/71-10-01PROC. REF: NDT PART 6/71-10-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 71 - POWER PLANT									
Q7110004	NO. 1 ENGINE INLET - PERFORM TAP TEST								Service ATA:71
	MOS	02-Nov-22							
	HRS	9151.6	3000		12151.6		2050.2		
	AFL	7021							
PROC. REF: AMM 71-10-01PROC. REF: AMM 71-10-01									
Q7110004	NO. 2 ENGINE INLET - PERFORM TAP TEST								Service ATA:71
	MOS	12-Aug-15							
	HRS	7535.1	3000		10535.1		433.7		
	AFL	5764							
PROC. REF: AMM 71-10-01PROC. REF: AMM 71-10-01									
Q7120002	NO. 1 ENGINE - AFT ENGINE MOUNT - ISOLATOR ASSEMBLY - PERFORM DETAILED INSPECTION OF FORWARD AND AFT ISOLATORS AND ASSOCIATED PARTS								Service ATA:71
	MOS/MSC	26-Jul-23	N/A						
	HRS	9278							
	AFL	7111							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
Q7120002	NO. 1 ENGINE - FORWARD ENGINE MOUNT - LOWER ISOLATOR ASSEMBLY - PERFORM DETAILED INSPECTION OF FORWARD AND AFT ISOLATORS AND ASSOCIATED PARTS								Service ATA:71
	MOS/MSC	26-Jul-23	N/A						
	HRS	9278							
	AFL	7111							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
Q7120002	NO. 1 ENGINE - FORWARD ENGINE MOUNT - UPPER ISOLATOR ASSEMBLY - PERFORM DETAILED INSPECTION OF FORWARD AND AFT ISOLATORS AND ASSOCIATED PARTS								Service ATA:71
	MOS/MSC	26-Jul-23	N/A						
	HRS	9278							
	AFL	7111							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
Q7120002	NO. 1 ENGINE ALL ISOLATORS - PERFORM INSPECTION OF ISOLATORS AND ASSOCIATED PARTS								Service ATA:71
	MOS/MSC	27-Sep-06	N/A						
	HRS	4857.2							
	AFL	3730							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 71 - POWER PLANT									
Q7120002	NO. 2 ENGINE - AFT ENGINE MOUNT - ISOLATOR ASSEMBLY - PERFORM DETAILED INSPECTION OF FORWARD AND AFT ISOLATORS AND ASSOCIATED PARTS							Service	ATA:71
	MOS/MSC	26-Jul-23	N/A						
	HRS	9278							
	AFL	7111							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
Q7120002	NO. 2 ENGINE - FORWARD ENGINE MOUNT - LOWER ISOLATOR ASSEMBLY - PERFORM DETAILED INSPECTION OF FORWARD AND AFT ISOLATORS AND ASSOCIATED PARTS							Service	ATA:71
PN:KM833-SA20-5	MOS/MSC	26-Jul-23	N/A						
SN:LK3185	HRS	9278							
	AFL	7111							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
Q7120002	NO. 2 ENGINE - FORWARD ENGINE MOUNT - UPPER ISOLATOR ASSEMBLY - PERFORM DETAILED INSPECTION OF FORWARD AND AFT ISOLATORS AND ASSOCIATED PARTS							Service	ATA:71
PN:LM833-SA20-5	MOS/MSC	26-Jul-23	N/A						
SN:LK3128	HRS	9278							
	AFL	7111							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
Q7120002	NO. 2 ENGINE ALL ISOLATORS - PERFORM INSPECTION OF ISOLATORS AND ASSOCIATED PARTS							Service	ATA:71
	MOS/MSC	27-Sep-06	N/A						
	HRS	4857.2							
	AFL	3730							
Q7120073	NO. 1 ENGINE - AFT ENGINE MOUNT - ISOLATOR ASSEMBLY - PERFORM DETAILED INSPECTION OF FORWARD AND AFT ISOLATORS AND ASSOCIATED PARTS.							Service	ATA:71
	MOS	26-Jul-23							
	HRS	9278	6000		15278		5176.6		
	AFL	7111							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 71 - POWER PLANT									
Q7120073	NO. 1 ENGINE - FORWARD ENGINE MOUNT - LOWER ISOLATOR ASSEMBLY - PERFORM DETAILED INSPECTION OF FORWARD AND AFT ISOLATORS AND ASSOCIATED PARTS							Service	ATA:71
	MOS	26-Jul-23							
	HRS	9278	6000		15278		5176.6		
	AFL	7111							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
Q7120073	NO. 1 ENGINE - FORWARD ENGINE MOUNT - UPPER ISOLATOR ASSEMBLY - PERFORM DETAILED INSPECTION OF FORWARD AND AFT ISOLATORS AND ASSOCIATED PARTS							Service	ATA:71
	MOS	26-Jul-23							
	HRS	9278	6000		15278		5176.6		
	AFL	7111							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
Q7120073	NO. 2 ENGINE - AFT ENGINE MOUNT - ISOLATOR ASSEMBLY - PERFORM DETAILED INSPECTION OF FORWARD AND AFT ISOLATORS AND ASSOCIATED PARTS							Service	ATA:71
	MOS	26-Jul-23							
	HRS	9278	6000		15278		5176.6		
	AFL	7111							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
Q7120073	NO. 2 ENGINE - FORWARD ENGINE MOUNT - LOWER ISOLATOR ASSEMBLY - PERFORM DETAILED INSPECTION OF FORWARD AND AFT ISOLATORS AND ASSOCIATED PARTS							Service	ATA:71
PN:KM833-SA20-5	MOS	26-Jul-23							
SN:LK3185	HRS	9278	6000		15278		5176.6		
	AFL	7111							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
Q7120073	NO. 2 ENGINE - FORWARD ENGINE MOUNT - UPPER ISOLATOR ASSEMBLY - PERFORM DETAILED INSPECTION OF FORWARD AND AFT ISOLATORS AND ASSOCIATED PARTS.							Service	ATA:71
PN:LM833-SA20-5	MOS	26-Jul-23							
SN:LK3128	HRS	9278	6000		15278		5176.6		
	AFL	7111							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 71 - POWER PLANT									
R7100032	LEFT ENGINE NACELLE TUBES - PERFORM DETAILED VISUAL INSPECTION							Service	ATA:71
	MOS/MSC	10-Nov-11	N/A					NOT APPLICABLE	
	HRS	6740.8							
	AFL	5145							
PROC. REF: AMM 71-10-03PROC. REF: AMM 71-10-03									
Y7100002 ^S	LOWER ENGINE COWLING - VISUALLY INSPECT LATCH CHANNELS FOR CHAFING							Service	ATA:71
	MOS	25-Jun-26	24						
	HRS	10023.1	600						
	AFL	7616							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
Y7110000 ^S	ENGINE NACELLE - PERFORM VISUAL INSPECTION. INSPECT INLET BULKHEAD, STRUCTURE, PLUMBING, SKIN SPOT WELDS, ANTI-ICE OUTLET SCREEN, AND FASTENERS FOR SECURITY, CRACKS, AND GENERAL CONDITION.							Service	ATA:71
	MOS	25-Jun-26	24						
	HRS	10023.1	600						
	AFL	7616							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
Y7110001 ^S	ENGINE INLET LIP AND DUCT - PERFORM VISUAL INSPECTION							Service	ATA:71
	MOS	25-Jun-26	24						
	HRS	10023.1	600						
	AFL	7616							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
Y7110002 ^S	ENGINE STARTER/GENERATOR INLET AND EXHAUST DUCT AND SEALS - PERFORM VISUAL INSPECTION							Service	ATA:71
	MOS	25-Jun-26	24						
	HRS	10023.1	600						
	AFL	7616							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 71 - POWER PLANT									
Y7110003	^S	ENGINE ALTERNATOR EXHAUST DUCT AND SEALS - PERFORM VISUAL INSPECTION							Service ATA:71
	MOS	25-Jun-26	24						
	HRS	10023.1	600						
	AFL	7616							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:9
Y7120000	^S	FORWARD ENGINE MOUNTS - PERFORM VISUAL INSPECTION							Service ATA:71
	MOS	25-Jun-26	12						
	HRS	10023.1	300						
	AFL	7616							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:3
ATA 72 - ENGINE									
72-AS-720005		NO. 1 ENGINE - INSPECT MAJOR PERIODIC PER MANUFACTURERS INSTRUCTIONS							Service ATA:72
	MOS	06-Dec-17							
	HRS	7696.2	3000		(10696.2) 10724.5		623.1		
	ENC	5895							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									
72-AS-720005		NO. 2 ENGINE - INSPECT MAJOR PERIODIC PER MANUFACTURERS INSTRUCTIONS							Service ATA:72
	MOS	20-Jul-15							
	HRS	6622.3	3000		(9622.3) 10489.3		387.9		
	ENC	5602							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									
72-AS-720006	^S	NO. 1 ENGINE - INSPECT COMB CHAMBER PLENUM CASE INSP PER MANUFACTURERS INSTRUCTIONS							Service ATA:72
	MOS	06-Dec-17							
	HRS	7696.2	3000						
	ENC	5895							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C / W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
72-AS-720006	^S	NO. 2 ENGINE - INSPECT COMB CHAMBER PLENUM CASE INSP PER MANUFACTURERS INSTRUCTIONS						Service	ATA:72
	MOS	20-Jul-15							
	HRS	6622.3	3000						
	ENC	5602							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
72-AS-720007		NO. 1 ENGINE - INSPECT COMPRESSOR ZONE PER MANUFACTURERS INSTRUCTIONS						Service	ATA:72
	MOS	30-Oct-06							
	HRS	4857.2	6000		(10857.2) 10885.5		784.1		
	ENC	3730							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									
72-AS-720007		NO. 2 ENGINE - INSPECT COMPRESSOR ZONE PER MANUFACTURERS INSTRUCTIONS						Service	ATA:72
	MOS	28-Jun-06							
	HRS	3701.2	6000		(9701.2) 10568.2		466.8		
	ENC	2811							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									
72-AS-720008	^S	NO. 1 ENGINE - INSPECT AGB PER MANUFACTURERS INSTRUCTIONS						Service	ATA:72
	MOS	25-Oct-06							
	HRS	4857.2	6000						
	ENC	3730							
PROC. REF: LMM 72-60-02PROC. REF: LMM 72-60-02									
72-AS-720008	^S	NO. 2 ENGINE - INSPECT AGB PER MANUFACTURERS INSTRUCTIONS						Service	ATA:72
	MOS	05-Jun-06							
	HRS	3701.2	6000						
	ENC	3369							
PROC. REF: LMM 72-60-02PROC. REF: LMM 72-60-02									
72-AS-720010		NO. 1 ENGINE - ANALYSIS OIL AND FILTER (BASELINE/SPECIAL REQUIREMENT) (SOAP)						Service	ATA:72
	MOS/MSC	05-Jan-00	A/R						
	HRS	0							
	ENC	0							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
72-AS-720010		NO. 2 ENGINE - ANALYSIS OIL AND FILTER (BASELINE/SPECIAL REQUIREMENT) (SOAP)						Service	ATA:72
	MOS/MSC	20-Jan-16	A/R						
	HRS	6674							
	ENC	5628							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									
72-AS-720011		NO. 1 ENGINE - REPLACE FUEL FILTER ELEMENT (25-HR INITIAL)						Service	ATA:72
	MOS/MSC	05-Jan-00	A/R						
	HRS	0							
	ENC	0							
PROC. REF: LMM 73-21-02PROC. REF: LMM 73-21-02									
72-AS-720011		NO. 2 ENGINE - REPLACE FUEL FILTER ELEMENT (25-HR INITIAL)						Service	ATA:72
	MOS/MSC	15-Jan-00	A/R						
	HRS	0							
	ENC	0							
PROC. REF: LMM 73-21-02PROC. REF: LMM 73-21-02									
720110		NO. 1 ENGINE - ACCESSORY GEARBOX						Component	ATA:72
PN:3060827-2	MOS/MSC	25-Oct-06	O/C						
SN:S986	HRS	4857.2							
	ENC	3730							
PROC. REF: LMM 72-60-02, LMM 72-60-02PROC. REF: LMM 72-60-02, LMM 72-60-02									
720110		NO. 2 ENGINE - ACCESSORY GEARBOX						Component	ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-60-02, LMM 72-60-02PROC. REF: LMM 72-60-02, LMM 72-60-02									
720244		NO. 1 ENGINE - NO. 6 CARBON SEAL ASSEMBLY						Component	ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
720244	NO. 2 ENGINE - NO. 6 CARBON SEAL ASSEMBLY								Component ATA:72
PN:3071383-2	MOS/MSC	20-Jul-15	O/C	TSN 0					
SN:13-150211-00260	HRS	6622.3		TSN 0					
	ENC	5602		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
720245	NO. 1 ENGINE - NO. 6 BEARING ASSEMBLY								Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
720245	NO. 2 ENGINE - NO. 6 BEARING ASSEMBLY								Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
722001	NO. 1 ENGINE - FAN INLET HOUSING ASSEMBLY								Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
722001	NO. 2 ENGINE - FAN INLET HOUSING ASSEMBLY								Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723002	NO. 1 ENGINE - NO. 3 CARBON SEAL ASSEMBLY								Component ATA:72
PN:3060150-3	MOS/MSC	25-Oct-06	O/C	TSN 0					
SN:061936801086	HRS	4857.2		TSN 0					
	ENC	3730		TSN 0					
PROC. REF: LMM 72-30-01, LMM 72-30-01PROC. REF: LMM 72-30-01, LMM 72-30-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
723002	NO. 2 ENGINE - NO. 3 CARBON SEAL ASSEMBLY								Component ATA:72
PN:3060150-3	MOS/MSC	05-Jun-06	O/C	TSN 0					
SN:061936800093	HRS	3701.2		TSN 0					
	ENC	3369		TSN 0					
PROC. REF: LMM 72-30-01, LMM 72-30-01PROC. REF: LMM 72-30-01, LMM 72-30-01									
723010 ^S	NO. 1 ENGINE - CHECK CARBON SEAL HEALTH								Service ATA:72
	MOS	22-Jun-23							
	HRS	9184.4	1600						
	ENC	7042							
PROC. REF: LMM 72-00-00, LMM 72-00-00PROC. REF: LMM 72-00-00, LMM 72-00-00									
723010 ^S	NO. 2 ENGINE - CHECK CARBON SEAL HEALTH								Service ATA:72
	MOS	18-Aug-22							
	HRS	8169.8	1600						
	ENC	6832							
PROC. REF: LMM 72-00-00, LMM 72-00-00PROC. REF: LMM 72-00-00, LMM 72-00-00									
723011	NO. 1 ENGINE - NO. 4 CARBON SEAL RUNNER								Component ATA:72
PN:3075639-2	MOS/MSC	25-Oct-06	O/C	TSN 0					
SN:062141803634	HRS	4857.2		TSN 0					
	ENC	3730		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723011	NO. 2 ENGINE - NO. 4 CARBON SEAL RUNNER								Component ATA:72
PN:3075639-2	MOS/MSC	05-Jun-06	O/C	TSN 0					
SN:052141802327	HRS	3701.2		TSN 0					
	ENC	3369		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723012	NO. 1 ENGINE - NO. 4 CARBON SEAL ASSEMBLY								Component ATA:72
PN:3074573-2	MOS/MSC	25-Oct-06	O/C	TSN 0					
SN:060515861210	HRS	4857.2		TSN 0					
	ENC	3730		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
723012	NO. 2 ENGINE - NO. 4 CARBON SEAL ASSEMBLY								Component ATA:72
PN:3074573-2	MOS/MSC	05-Jun-06	O/C	TSN 0					
SN:060515847790	HRS	3701.2		TSN 0					
	ENC	3369		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723013	NO. 1 ENGINE - NO. 5 CARBON SEAL RUNNER								Component ATA:72
PN:3075633-2	MOS/MSC	25-Oct-06	O/C	TSN 0					
SN:062141802473	HRS	4857.2		TSN 0					
	ENC	3730		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723013	NO. 2 ENGINE - NO. 5 CARBON SEAL RUNNER								Component ATA:72
PN:3075633-2	MOS/MSC	05-Jun-06	O/C	TSN 0					
SN:052141806990	HRS	3701.2		TSN 0					
	ENC	3369		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723014	NO. 1 ENGINE - NO. 5 CARBON SEAL ASSEMBLY								Component ATA:72
PN:3074574-2	MOS/MSC	25-Oct-06	O/C	TSN 0					
SN:060515859035	HRS	4857.2		TSN 0					
	ENC	3730		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723014	NO. 2 ENGINE - NO. 5 CARBON SEAL ASSEMBLY								Component ATA:72
PN:3074574-2	MOS/MSC	05-Jun-06	O/C	TSN 0					
SN:060515849488	HRS	3701.2		TSN 0					
	ENC	3369		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723081	NO. 1 ENGINE - ROTATING, AIR 2ND STAGE SEAL								Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
723081	NO. 2 ENGINE - ROTATING, AIR 2ND STAGE SEAL							Component	ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725007	NO. 1 ENGINE - HIGH PRESSURE TURBINE (HPT) NOZZLE ASSEMBLY							Component	ATA:72
PN:3060840-3	MOS/MSC	25-Oct-06	A/R	TSN 0					
SN:UNKNOWN	HRS	4857.2		TSN 0					
WC#: 72.500	ENC	3730		TSN 0					
PROC. REF: LMM 72-50-07, LMM 72-50-07PROC. REF: LMM 72-50-07, LMM 72-50-07									
725007	NO. 2 ENGINE - HIGH PRESSURE TURBINE (HPT) NOZZLE ASSEMBLY							Component	ATA:72
PN:PN	MOS/MSC	15-Jan-00	A/R	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 72.500	ENC	0		TSN 0					
PROC. REF: LMM 72-50-07, LMM 72-50-07PROC. REF: LMM 72-50-07, LMM 72-50-07									
725010	NO. 1 ENGINE - 1ST-STAGE LOW PRESSURE TURBINE (LPT) DISC							Component	ATA:72
PN:3060129-7	MOS	25-Oct-06						LIFE LIMIT	
SN:00P21077	HRS	4857.2							
	ENC	3730	12000	TSN 3730	(12000) 12014		4340		
PROC. REF: LMM 72-50-04, LMM 72-50-04PROC. REF: LMM 72-50-04, LMM 72-50-04									
725010	NO. 2 ENGINE - 1ST-STAGE LOW PRESSURE TURBINE (LPT) DISC							Component	ATA:72
PN:3060625-1	MOS	15-Jan-00		TSN 0				LIFE LIMIT	
SN:990322904089	HRS	0		TSN 0					
	ENC	0	12000	TSN 0	(12000) 12118		4444		
PROC. REF: LMM 72-50-04, LMM 72-50-04PROC. REF: LMM 72-50-04, LMM 72-50-04									
725020	NO. 1 ENGINE - 2ND-STAGE LOW PRESSURE TURBINE (LPT) DISC							Component	ATA:72
PN:3060611-1	MOS	05-Jan-00		TSN 0				LIFE LIMIT	
SN:000322903502	HRS	0		TSN 0					
	ENC	0	12000	TSN 0	(12000) 12014		4340		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
PROC. REF: LMM 72-50-04, LMM 72-50-04PROC. REF: LMM 72-50-04, LMM 72-50-04									
725020	NO. 2 ENGINE - 2ND-STAGE LOW PRESSURE TURBINE (LPT) DISC								Component ATA:72
PN:3060611-1	MOS	15-Jan-00		TSN 0				LIFE LIMIT	
SN:000322903437	HRS	0		TSN 0					
	ENC	0	12000	TSN 0	(12000) 12118		4444		
PROC. REF: LMM 72-50-04, LMM 72-50-04PROC. REF: LMM 72-50-04, LMM 72-50-04									
725030	NO. 1 ENGINE - 3RD-STAGE LOW PRESSURE TURBINE (LPT) DISC								Component ATA:72
PN:3060671-2	MOS	05-Jan-00		TSN 0				LIFE LIMIT	
SN:000322900149	HRS	0		TSN 0					
	ENC	0	12000	TSN 0	(12000) 12014		4340		
PROC. REF: LMM 72-50-04, LMM 72-50-04PROC. REF: LMM 72-50-04, LMM 72-50-04									
725030	NO. 2 ENGINE - 3RD-STAGE LOW PRESSURE TURBINE (LPT) DISC								Component ATA:72
PN:3060671-2	MOS	15-Jan-00		TSN 0				LIFE LIMIT	
SN:000322900152	HRS	0		TSN 0					
	ENC	0	12000	TSN 0	(12000) 12118		4444		
PROC. REF: LMM 72-50-04, LMM 72-50-04PROC. REF: LMM 72-50-04, LMM 72-50-04									
725040	NO. 1 ENGINE - HIGH PRESSURE TURBINE (HPT) DISC								Component ATA:72
PN:3060555-5	MOS	25-Oct-06						LIFE LIMIT	
SN:061217200024	HRS	4857.2							
	ENC	3730	10000	TSN 0	(13730) 13744		6070		
PROC. REF: LMM 72-50-07, LMM 72-50-07PROC. REF: LMM 72-50-07, LMM 72-50-07									
725040	NO. 2 ENGINE - HIGH PRESSURE TURBINE (HPT) DISC								Component ATA:72
PN:3060841-1	MOS	20-Jul-15						LIFE LIMIT	
SN:041217200360	HRS	6622.3		TSN 4043.4					
	ENC	5602	10000	TSN 3645	(11957) 12075		4401		
PROC. REF: LMM 72-50-07, LMM 72-50-07PROC. REF: LMM 72-50-07, LMM 72-50-07									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
725045	NO. 1 ENGINE - HIGH PRESSURE TURBINE (HPT) ASSY								Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
725045	NO. 2 ENGINE - HIGH PRESSURE TURBINE (HPT) ASSY								Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
725050	NO. 1 ENGINE - FAN DISC								Component ATA:72
PN:3060287-2	MOS	05-Jan-00		TSN 0				LIFE LIMIT	
SN:030322901250	HRS	0		TSN 0					
	ENC	0	20000	TSN 0	(20000) 20014		12340		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725050	NO. 2 ENGINE - FAN DISC								Component ATA:72
PN:3060287-2	MOS	15-Jan-00		TSN 0				LIFE LIMIT	
SN:010322905809	HRS	0		TSN 0					
	ENC	0	20000	TSN 0	(20000) 20118		12444		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725060	NO. 1 ENGINE - 1ST-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC								Component ATA:72
PN:3060372-1	MOS	05-Jan-00		TSN 0				LIFE LIMIT	
SN:000316002316	HRS	0		TSN 0					
	ENC	0	10000	TSN 0	(10000) 10014		2340		
PROC. REF: LMM 72-30-04PROC. REF: LMM 72-30-04									
725060	NO. 2 ENGINE - 1ST-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC								Component ATA:72
PN:3060372-1	MOS	15-Jan-00		TSN 0				LIFE LIMIT	
SN:000316002319	HRS	0		TSN 0					
	ENC	0	10000	TSN 0	(10000) 10118		2444		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
PROC. REF: LMM 72-30-04PROC. REF: LMM 72-30-04									
725070	NO. 1 ENGINE - 2ND-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC							Component	ATA:72
PN:3060608-3	MOS	25-Oct-06						LIFE LIMIT	
SN:000322903502	HRS	4857.2							
	ENC	3730	10000	TSN 3730	(10000) 10014		2340		
PROC. REF: LMM 72-30-04PROC. REF: LMM 72-30-04									
725070	NO. 2 ENGINE - 2ND-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC							Component	ATA:72
PN:3060373-1	MOS	15-Jan-00		TSN 0				LIFE LIMIT	
SN:000316001852	HRS	0		TSN 0					
	ENC	0	10000	TSN 0	(10000) 10118		2444		
PROC. REF: LMM 72-30-04PROC. REF: LMM 72-30-04									
725071	NO. 1 ENGINE - COMBUSTION LINER							Component	ATA:72
PN:3060766-1	MOS/MSC	28-Nov-17	O/C	TSO 0					
SN:08P16345	HRS	7696.2		TSO 0					
	ENC	5895		TSO 0					
PROC. REF: LMM 72-40-03, LMM 72-40-03PROC. REF: LMM 72-40-03, LMM 72-40-03									
725071	NO. 2 ENGINE - COMBUSTION LINER							Component	ATA:72
PN:3060766-1	MOS/MSC	20-Jul-15	O/C	TSO 0					
SN:06P00417	HRS	6622.3		TSO 0					
	ENC	5602		TSO 0					
PROC. REF: LMM 72-40-03, LMM 72-40-03PROC. REF: LMM 72-40-03, LMM 72-40-03									
725080	NO. 1 ENGINE - 3RD-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC							Component	ATA:72
PN:3060374-1	MOS	05-Jan-00		TSN 0				LIFE LIMIT	
SN:000316002539	HRS	0		TSN 0					
	ENC	0	10000	TSN 0	(10000) 10014		2340		
PROC. REF: LMM 72-30-04PROC. REF: LMM 72-30-04									

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
725080	NO. 2 ENGINE - 3RD-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC								Component ATA:72
PN:3072417-12	MOS	05-Jun-06		TSR 0				LIFE LIMIT	
SN:000316002937	HRS	3701.2		TSR 0					
	ENC	3369	10000	TSN 3369, TSR 0	(10000) 10118		2444		
PROC. REF: LMM 72-30-04PROC. REF: LMM 72-30-04									
725081	NO. 1 ENGINE - OUTER TRANSITION LINER								Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-40-03, LMM 72-40-03PROC. REF: LMM 72-40-03, LMM 72-40-03									
725081	NO. 2 ENGINE - OUTER TRANSITION LINER								Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-40-03, LMM 72-40-03PROC. REF: LMM 72-40-03, LMM 72-40-03									
725090	NO. 1 ENGINE - 4TH-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC								Component ATA:72
PN:3075326-5	MOS	05-Jan-00		TSN 0				LIFE LIMIT	
SN:001365107764	HRS	0		TSN 0					
	ENC	0	20000	TSN 0	(20000) 20014		12340		
PROC. REF: LMM 72-30-04PROC. REF: LMM 72-30-04									
725090	NO. 2 ENGINE - 4TH-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC								Component ATA:72
PN:3075351-12	MOS	05-Jun-06						LIFE LIMIT	
SN:050350107807	HRS	3701.2							
	ENC	3369	20000	TSN 0	(23369) 23487		15813		
PROC. REF: LMM 72-30-04PROC. REF: LMM 72-30-04									
725110	NO. 1 ENGINE - LOW PRESSURE COMPRESSOR TIE ROD								Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C / W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
PROC. REF: LMM 72-30-10, LMM 72-30-10PROC. REF: LMM 72-30-10, LMM 72-30-10									
725110	NO. 2 ENGINE - LOW PRESSURE COMPRESSOR TIE ROD							Component	ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-30-10, LMM 72-30-10PROC. REF: LMM 72-30-10, LMM 72-30-10									
725120	NO. 1 ENGINE - HIGH PRESSURE COMPRESSOR ROTOR IMPELLER							Component	ATA:72
PN:3060371-1	MOS	05-Jan-00		TSN 0				LIFE LIMIT	
SN:005332200378	HRS	0		TSN 0					
	ENC	0	8000	TSN 0	(8000) 8014		340		
PROC. REF: LMM 72-50-06, LMM 72-50-06PROC. REF: LMM 72-50-06, LMM 72-50-06									
725120	NO. 2 ENGINE - HIGH PRESSURE COMPRESSOR ROTOR IMPELLER							Component	ATA:72
PN:3060371-1	MOS	05-Jun-06						LIFE LIMIT	
SN:060322902406	HRS	3701.2							
	ENC	3369	8000	TSN 0	(11369) 11487		3813		
PROC. REF: LMM 72-50-06, LMM 72-50-06PROC. REF: LMM 72-50-06, LMM 72-50-06									
725130	NO. 1 ENGINE - FAN SPINNER							Component	ATA:72
PN:3060156-2	MOS	05-Jan-00		TSN 0				LIFE LIMIT	
SN:002428000312	HRS	0		TSN 0					
	ENC	0	20000	TSN 0	(20000) 20014		12340		
PROC. REF: LMM 72-70-01, LMM 72-70-01PROC. REF: LMM 72-70-01, LMM 72-70-01									
725130	NO. 2 ENGINE - FAN SPINNER							Component	ATA:72
PN:3060156-2	MOS	15-Jan-00		TSN 0				LIFE LIMIT	
SN:002428000311	HRS	0		TSN 0					
	ENC	0	20000	TSN 0	(20000) 20118		12444		
PROC. REF: LMM 72-70-01, LMM 72-70-01PROC. REF: LMM 72-70-01, LMM 72-70-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
725140	NO. 1 ENGINE - FAN DRIVE SHAFT								Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725140	NO. 2 ENGINE - FAN DRIVE SHAFT								Component ATA:72
PN:3067021-1	MOS/MSC	23-May-07	O/C						
SN:970339000246	HRS	4564.4							
	ENC	4010							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725160	NO. 1 ENGINE - FORWARD ROTOR HIGH PRESSURE SEAL								Component ATA:72
PN:3060698-1	MOS	28-Nov-17		TSN 0				LIFE LIMIT	
SN:16-162246-03040	HRS	7696.2		TSN 0					
	ENC	5895	7000	TSN 0	(12895) 12909		5235		
PROC. REF: LMM 72-70-03, LMM 72-70-03PROC. REF: LMM 72-70-03, LMM 72-70-03									
725160	NO. 2 ENGINE - FORWARD ROTOR HIGH PRESSURE SEAL								Component ATA:72
PN:3060698-1	MOS	20-Jul-15		TSN 0				LIFE LIMIT	
SN:14-162246-04706	HRS	6622.3		TSN 0					
	ENC	5602	7000	TSN 0	(12602) 12720		5046		
PROC. REF: LMM 72-70-03, LMM 72-70-03PROC. REF: LMM 72-70-03, LMM 72-70-03									
725170	NO. 1 ENGINE - HIGH PRESSURE SHOULDERED SHAFT								Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725170	NO. 2 ENGINE - HIGH PRESSURE SHOULDERED SHAFT								Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C / W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
725180	NO. 1 ENGINE - COMBUSTION PLENUM CASE								Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-40-04, LMM 72-40-04PROC. REF: LMM 72-40-04, LMM 72-40-04									
725180	NO. 2 ENGINE - COMBUSTION PLENUM CASE								Component ATA:72
PN:3060534-4	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:00P24979	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-40-04, LMM 72-40-04PROC. REF: LMM 72-40-04, LMM 72-40-04									
725210	NO. 1 ENGINE - HIGH PRESSURE TURBINE FORWARD SEAL PLATE								Component ATA:72
PN:3060514-1	MOS	05-Jan-00		TSN 0				LIFE LIMIT	
SN:000322905164	HRS	0		TSN 0					
	ENC	0	10000	TSN 0	(10000) 10014		2340		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725210	NO. 2 ENGINE - HIGH PRESSURE TURBINE FORWARD SEAL PLATE								Component ATA:72
PN:3060514-1	MOS	15-Jan-00		TSN 0				LIFE LIMIT	
SN:000322905162	HRS	0		TSN 0					
	ENC	0	10000	TSN 0	(10000) 10118		2444		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725220	NO. 1 ENGINE - TURBINE INTERSTAGE TRANSITION DUCT								Component ATA:72
PN:3060694-6	MOS/MSC	25-Oct-06	O/C						
SN:97P23086	HRS	4857.2							
	ENC	3730							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725220	NO. 2 ENGINE - TURBINE INTERSTAGE TRANSITION DUCT								Component ATA:72
PN:3060694-6	MOS/MSC	20-Jul-15	O/C	TSO 0					
SN:02P01906	HRS	6622.3		TSO 0					
	ENC	5602		TSO 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
725230	NO. 1 ENGINE - LOW PRESSURE TURBINE (LPT) 1 NOZZLE SEAL SUPPORT							Component	ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-50-04, LMM 72-50-04PROC. REF: LMM 72-50-04, LMM 72-50-04									
725230	NO. 2 ENGINE - LOW PRESSURE TURBINE (LPT) 1 NOZZLE SEAL SUPPORT							Component	ATA:72
PN:3060693-1	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:00P28158	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-50-04, LMM 72-50-04PROC. REF: LMM 72-50-04, LMM 72-50-04									
725240	NO. 1 ENGINE - LOW PRESSURE TURBINE (LPT) 1 NOZZLE ASSEMBLY							Component	ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-50-04, LMM 72-50-04PROC. REF: LMM 72-50-04, LMM 72-50-04									
725240	NO. 2 ENGINE - LOW PRESSURE TURBINE (LPT) 1 NOZZLE ASSEMBLY							Component	ATA:72
PN:3060666-7	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:00P29069	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-50-04, LMM 72-50-04PROC. REF: LMM 72-50-04, LMM 72-50-04									
725250	NO. 1 ENGINE - FORWARD SHAFT HIGH PRESSURE TURBINE (HPT) COUPLING							Component	ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725250	NO. 2 ENGINE - FORWARD SHAFT HIGH PRESSURE TURBINE (HPT) COUPLING							Component	ATA:72
PN:3060502-2	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:00P26421	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C / W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
725260	NO. 1 ENGINE - AFT HIGH PRESSURE TURBINE (HPT) SHAFT COUPLING							Component	ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725260	NO. 2 ENGINE - AFT HIGH PRESSURE TURBINE (HPT) SHAFT COUPLING							Component	ATA:72
PN:3060599-2	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:00P28573	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725270	NO. 1 ENGINE - NOZZLE LOW PRESSURE TURBINE (LPT) (A5) SEAL							Component	ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725270	NO. 2 ENGINE - NOZZLE LOW PRESSURE TURBINE (LPT) (A5) SEAL							Component	ATA:72
PN:3073765-12	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:00P29032	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
726005	NO. 1 ENGINE - TRANSFER GEARBOX ASSEMBLY							Component	ATA:72
PN:3070093-16	MOS/MSC	25-Oct-06	O/C						
SN:P10020	HRS	4857.2							
	ENC	3730							
PROC. REF: LMM 72-60-03, LMM 72-60-03PROC. REF: LMM 72-60-03, LMM 72-60-03									
726005	NO. 2 ENGINE - TRANSFER GEARBOX ASSEMBLY							Component	ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-60-03, LMM 72-60-03PROC. REF: LMM 72-60-03, LMM 72-60-03									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
726010	NO. 1 ENGINE - FORWARD OIL PUMP SPUR ANNULAR BALL BEARING								Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									
726010	NO. 2 ENGINE - FORWARD OIL PUMP SPUR ANNULAR BALL BEARING								Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									
726011	NO. 1 ENGINE - AFT OIL PUMP SPUR ANNULAR BALL BEARING								Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
726011	NO. 2 ENGINE - AFT OIL PUMP SPUR ANNULAR BALL BEARING								Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
726012	NO. 1 ENGINE - FORWARD ALTERNATOR SPU ANNULAR BALL BEARING								Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
726012	NO. 2 ENGINE - FORWARD ALTERNATOR SPU ANNULAR BALL BEARING								Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C / W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
726013	NO. 1 ENGINE - AFT ALTERNATOR SPU ANNULAR BEARING								Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
726013	NO. 2 ENGINE - AFT ALTERNATOR SPU ANNULAR BEARING								Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
726014	NO. 1 ENGINE - FORWARD AIR-OIL SEPARATOR ANNULAR BALL BEARING								Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
726014	NO. 2 ENGINE - FORWARD AIR-OIL SEPARATOR ANNULAR BALL BEARING								Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
726015	NO. 1 ENGINE - AFT AIR-OIL SEPARATOR ANNULAR BALL BEARING								Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
726015	NO. 2 ENGINE - AFT AIR-OIL SEPARATOR ANNULAR BALL BEARING								Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
726016	NO. 1 ENGINE - FORWARD STARTER/GENERATOR SPU ANNULAR BALL BEARING							Component	ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
726016	NO. 2 ENGINE - FORWARD STARTER/GENERATOR SPU ANNULAR BALL BEARING							Component	ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
726017	NO. 1 ENGINE - AFT STARTER/GENERATOR SPU ANNULAR BEARING							Component	ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
726017	NO. 2 ENGINE - AFT STARTER/GENERATOR SPU ANNULAR BEARING							Component	ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
727001	NO. 1 ENGINE - BYPASS FAN STATOR							Component	ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-70-04, LMM 72-70-04PROC. REF: LMM 72-70-04, LMM 72-70-04									
727001	NO. 2 ENGINE - BYPASS FAN STATOR							Component	ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-70-04, LMM 72-70-04PROC. REF: LMM 72-70-04, LMM 72-70-04									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
727005	NO. 1 ENGINE - UPPER FAN DUCT ASSEMBLY								Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-70-05, LMM 72-70-05PROC. REF: LMM 72-70-05, LMM 72-70-05									
727005	NO. 2 ENGINE - UPPER FAN DUCT ASSEMBLY								Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-70-05, LMM 72-70-05PROC. REF: LMM 72-70-05, LMM 72-70-05									
727006	NO. 1 ENGINE - LOWER FAN DUCT ASSEMBLY								Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-70-05, LMM 72-70-05PROC. REF: LMM 72-70-05, LMM 72-70-05									
727006	NO. 2 ENGINE - LOWER FAN DUCT ASSEMBLY								Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-70-05, LMM 72-70-05PROC. REF: LMM 72-70-05, LMM 72-70-05									
727010 ^S	NO. 1 ENGINE - INSPECT BYPASS STATOR VANE ASSEMBLY.								Service ATA:72
	MOS	27-Oct-25							
	HRS	9832.1	1200						
	ENC	7480							
PROC. REF: LMM 72-70-04, LMM 72-70-04, LMM 72-70-04PROC. REF: LMM 72-70-04, LMM 72-70-04, LMM 72-70-04									
727010 ^S	NO. 2 ENGINE - INSPECT BYPASS STATOR VANE ASSEMBLY.								Service ATA:72
	MOS	27-Oct-25							
	HRS	8993.4	1200						
	ENC	7376							
PROC. REF: LMM 72-70-04, LMM 72-70-04, LMM 72-70-04PROC. REF: LMM 72-70-04, LMM 72-70-04, LMM 72-70-04									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 10101.4
 AFL: 7674
 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
727101	NO. 1 ENGINE - NO. 1 CARBON SEAL ASSEMBLY								Component ATA:72
PN:3060457-1	MOS/MSC	28-Nov-17	O/C	TSN 0					
SN:17-152826-59105	HRS	7696.2		TSN 0					
	ENC	5895		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
727101	NO. 2 ENGINE - NO. 1 CARBON SEAL ASSEMBLY								Component ATA:72
PN:3060457-1	MOS/MSC	20-Jul-15	O/C	TSN 0					
SN:14-152826-73404	HRS	6622.3		TSN 0					
	ENC	5602		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
727102	NO. 1 ENGINE - NO. 1 CARBON SEAL RUNNER								Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
727102	NO. 2 ENGINE - NO. 1 CARBON SEAL RUNNER								Component ATA:72
PN:3075657-1	MOS/MSC	20-Jul-15	O/C	TSN 0					
SN:14-162397-04157	HRS	6622.3		TSN 0					
	ENC	5602		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
727103	NO. 1 ENGINE - NO. 1 BEARING ASSEMBLY								Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
727103	NO. 2 ENGINE - NO. 1 BEARING ASSEMBLY								Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
727105	NO. 1 ENGINE - HELICAL RING GEAR								Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
727105	NO. 2 ENGINE - HELICAL RING GEAR								Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
727203	NO. 1 ENGINE - NO. 3 BALL BEARING								Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-30-01, LMM 72-30-01PROC. REF: LMM 72-30-01, LMM 72-30-01									
727203	NO. 2 ENGINE - NO. 3 BALL BEARING								Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-30-01, LMM 72-30-01PROC. REF: LMM 72-30-01, LMM 72-30-01									
727210	NO. 1 ENGINE - PLANET HOUSING ASSEMBLY								Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-72-03, LMM 72-72-03PROC. REF: LMM 72-72-03, LMM 72-72-03									
727210	NO. 2 ENGINE - PLANET HOUSING ASSEMBLY								Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-72-03, LMM 72-72-03PROC. REF: LMM 72-72-03, LMM 72-72-03									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 10101.4
 AFL: 7674
 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
727210-1	NO. 1 ENGINE - NO. 1 PLANET GEAR ASSEMBLY								Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-72-03, LMM 72-72-03PROC. REF: LMM 72-72-03, LMM 72-72-03									
727210-1	NO. 2 ENGINE - NO. 1 PLANET GEAR ASSEMBLY								Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-72-03, LMM 72-72-03PROC. REF: LMM 72-72-03, LMM 72-72-03									
727210-2	NO. 1 ENGINE - NO. 2 PLANET GEAR ASSEMBLY								Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-72-03, LMM 72-72-03PROC. REF: LMM 72-72-03, LMM 72-72-03									
727210-2	NO. 2 ENGINE - NO. 2 PLANET GEAR ASSEMBLY								Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-72-03, LMM 72-72-03PROC. REF: LMM 72-72-03, LMM 72-72-03									
727210-3	NO. 1 ENGINE - NO. 3 PLANET GEAR ASSEMBLY								Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-72-03, LMM 72-72-03PROC. REF: LMM 72-72-03, LMM 72-72-03									
727210-3	NO. 2 ENGINE - NO. 3 PLANET GEAR ASSEMBLY								Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-72-03, LMM 72-72-03PROC. REF: LMM 72-72-03, LMM 72-72-03									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
727210-4	NO. 1 ENGINE - NO. 4 PLANET GEAR ASSEMBLY								Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-72-03, LMM 72-72-03PROC. REF: LMM 72-72-03, LMM 72-72-03									
727210-4	NO. 2 ENGINE - NO. 4 PLANET GEAR ASSEMBLY								Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-72-03, LMM 72-72-03PROC. REF: LMM 72-72-03, LMM 72-72-03									
727210-5	NO. 1 ENGINE - NO. 5 PLANET GEAR ASSEMBLY								Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-72-03, LMM 72-72-03PROC. REF: LMM 72-72-03, LMM 72-72-03									
727210-5	NO. 2 ENGINE - NO. 5 PLANET GEAR ASSEMBLY								Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-72-03, LMM 72-72-03PROC. REF: LMM 72-72-03, LMM 72-72-03									
ATA 73 - ENGINE FUEL AND CONTROL									
730110	NO. 1 ENGINE - FUEL CONTROL UNIT								Component ATA:73
PN:3070800-37	MOS/MSC	25-Oct-06	O/C						
SN:16529	HRS	4857.2							
	ENC	3730							
PROC. REF: LMM 73-20-01, LMM 73-20-01PROC. REF: LMM 73-20-01, LMM 73-20-01									
730110	NO. 2 ENGINE - FUEL CONTROL UNIT								Component ATA:73
PN:3070800-47	MOS/MSC	27-Feb-23	O/C	TSO 0					
SN:19179	HRS	8273.9		TSO 0					
	ENC	6885		TSO 0					
PROC. REF: LMM 73-20-01, LMM 73-20-01PROC. REF: LMM 73-20-01, LMM 73-20-01									

?-Insufficient Information

S-Suppressed Requirement

*-Estimated Due(New Requirement)

(EFF)-Effective C / W

(M)-Manual Due

U-User Task

Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 73 - ENGINE FUEL AND CONTROL									
730120 ^S		NO. 1 ENGINE - REPLACE FUEL FILTER ELEMENT						Service	ATA:73
	MOS	27-Oct-25							
	HRS	9832.1	600						
	ENC	7480							
PROC. REF: LMM 73-21-02, LMM 73-21-02PROC. REF: LMM 73-21-02, LMM 73-21-02									
PKG:0									
730120 ^S		NO. 2 ENGINE - REPLACE FUEL FILTER ELEMENT						Service	ATA:73
	MOS	27-Oct-25							
	HRS	8993.4	600						
	ENC	7376							
PROC. REF: LMM 73-21-02, LMM 73-21-02PROC. REF: LMM 73-21-02, LMM 73-21-02									
PKG:0									
730130		NO. 1 ENGINE - ENGINE FUEL PUMP ASSEMBLY						Component	ATA:73
PN:3060760-3	MOS/MSC	25-Oct-06	O/C						
SN:0942	HRS	4857.2							
	ENC	3730							
PROC. REF: LMM 73-20-01, LMM 73-20-01, LMM 73-20-01, LMM 73-20-01PROC. REF: LMM 73-20-01, LMM 73-20-01, LMM 73-20-01, LMM 73-20-01									
730130		NO. 2 ENGINE - ENGINE FUEL PUMP ASSEMBLY						Component	ATA:73
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 73-20-01, LMM 73-20-01, LMM 73-20-01, LMM 73-20-01PROC. REF: LMM 73-20-01, LMM 73-20-01, LMM 73-20-01, LMM 73-20-01									
731001		NO. 1 ENGINE - MOTIVE FLOW FUEL PUMP ASSEMBLY						Component	ATA:73
PN:3060759-1	MOS/MSC	25-Oct-06	O/C						
SN:0457	HRS	4857.2							
	ENC	3730							
PROC. REF: LMM 73-21-02PROC. REF: LMM 73-21-02									
731001		NO. 2 ENGINE - MOTIVE FLOW FUEL PUMP ASSEMBLY						Component	ATA:73
PN:3060759-1	MOS/MSC	18-Dec-13	O/C	TSO 0					
SN:0671	HRS	6312.5		TSO 0					
	ENC	5360		TSO 0					
PROC. REF: LMM 73-21-02PROC. REF: LMM 73-21-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 73 - ENGINE FUEL AND CONTROL									
731005-1	NO. 1 ENGINE - NO. 1 FUEL MANIFOLD NOZZLE ASSEMBLY								Component ATA:73
PN:3060540-2	MOS/MSC	25-Oct-06	O/C						
SN:97-01371-430	HRS	4857.2							
	ENC	3730							
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01									
731005-1	NO. 2 ENGINE - NO. 1 FUEL MANIFOLD NOZZLE ASSEMBLY								Component ATA:73
PN:3060540-2	MOS/MSC	20-Jul-15	O/C	TSO 0					
SN:020137100424	HRS	6622.3		TSO 0					
	ENC	5602		TSO 0					
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01									
731005-10	NO. 1 ENGINE - NO. 10 FUEL MANIFOLD NOZZLE ASSEMBLY								Component ATA:73
PN:3060540-2	MOS/MSC	25-Oct-06	O/C						
SN:97-01371-1025	HRS	4857.2							
	ENC	3730							
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01									
731005-10	NO. 2 ENGINE - NO. 10 FUEL MANIFOLD NOZZLE ASSEMBLY								Component ATA:73
PN:3060540-2	MOS/MSC	20-Jul-15	O/C	TSO 0					
SN:052923401375	HRS	6622.3		TSO 0					
	ENC	5602		TSO 0					
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01									
731005-11	NO. 1 ENGINE - NO. 11 FUEL MANIFOLD NOZZLE ASSEMBLY								Component ATA:73
PN:3060540-2	MOS/MSC	25-Oct-06	O/C						
SN:990137101056	HRS	4857.2							
	ENC	3730							
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01									
731005-11	NO. 2 ENGINE - NO. 11 FUEL MANIFOLD NOZZLE ASSEMBLY								Component ATA:73
PN:3060540-2	MOS/MSC	20-Jul-15	O/C	TSO 0					
SN:010137103143	HRS	6622.3		TSO 0					
	ENC	5602		TSO 0					
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 73 - ENGINE FUEL AND CONTROL									
731005-12		NO. 1 ENGINE - NO. 12 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73
PN:3060540-2	MOS/MSC	25-Oct-06	O/C						
SN:97-01371-400	HRS	4857.2							
	ENC	3730							
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01									
731005-12		NO. 2 ENGINE - NO. 12 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73
PN:3060540-2	MOS/MSC	20-Jul-15	O/C	TSO 0					
SN:052923401374	HRS	6622.3		TSO 0					
	ENC	5602		TSO 0					
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01									
731005-2		NO. 1 ENGINE - NO. 2 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73
PN:3060540-2	MOS/MSC	25-Oct-06	O/C						
SN:010137102472	HRS	4857.2							
	ENC	3730							
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01									
731005-2		NO. 2 ENGINE - NO. 2 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73
PN:3060540-2	MOS/MSC	20-Jul-15	O/C	TSO 0					
SN:052923401378	HRS	6622.3		TSO 0					
	ENC	5602		TSO 0					
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01									
731005-3		NO. 1 ENGINE - NO. 3 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73
PN:3060540-2	MOS/MSC	25-Oct-06	O/C						
SN:97-01371-398	HRS	4857.2							
	ENC	3730							
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01									
731005-3		NO. 2 ENGINE - NO. 3 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73
PN:3060540-2	MOS/MSC	20-Jul-15	O/C	TSO 0					
SN:032923401169	HRS	6622.3		TSO 0					
	ENC	5602		TSO 0					
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 73 - ENGINE FUEL AND CONTROL									
731005-4	NO. 1 ENGINE - NO. 4 FUEL MANIFOLD NOZZLE ASSEMBLY							Component	ATA:73
PN:3060540-2	MOS/MSC	25-Oct-06	O/C						
SN:97-01371-572	HRS	4857.2							
	ENC	3730							
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01									
731005-4	NO. 2 ENGINE - NO. 4 FUEL MANIFOLD NOZZLE ASSEMBLY							Component	ATA:73
PN:3060540-2	MOS/MSC	20-Jul-15	O/C	TSO 0					
SN:032923401065	HRS	6622.3		TSO 0					
	ENC	5602		TSO 0					
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01									
731005-5	NO. 1 ENGINE - NO. 5 FUEL MANIFOLD NOZZLE ASSEMBLY							Component	ATA:73
PN:3060540-2	MOS/MSC	25-Oct-06	O/C						
SN:990137101033	HRS	4857.2							
	ENC	3730							
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01									
731005-5	NO. 2 ENGINE - NO. 5 FUEL MANIFOLD NOZZLE ASSEMBLY							Component	ATA:73
PN:3060540-2	MOS/MSC	20-Jul-15	O/C	TSO 0					
SN:072923400480	HRS	6622.3		TSO 0					
	ENC	5602		TSO 0					
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01									
731005-6	NO. 1 ENGINE - NO. 6 FUEL MANIFOLD NOZZLE ASSEMBLY							Component	ATA:73
PN:3060540-2	MOS/MSC	25-Oct-06	O/C						
SN:990137101059	HRS	4857.2							
	ENC	3730							
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01									
731005-6	NO. 2 ENGINE - NO. 6 FUEL MANIFOLD NOZZLE ASSEMBLY							Component	ATA:73
PN:3060540-2	MOS/MSC	20-Jul-15	O/C	TSO 0					
SN:052923400974	HRS	6622.3		TSO 0					
	ENC	5602		TSO 0					
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 73 - ENGINE FUEL AND CONTROL									
731005-7	NO. 1 ENGINE - NO. 7 FUEL MANIFOLD NOZZLE ASSEMBLY							Component	ATA:73
PN:3060540-2	MOS/MSC	25-Oct-06	O/C						
SN:97-01371-542	HRS	4857.2							
	ENC	3730							
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01									
731005-7	NO. 2 ENGINE - NO. 7 FUEL MANIFOLD NOZZLE ASSEMBLY							Component	ATA:73
PN:3060540-2	MOS/MSC	20-Jul-15	O/C	TSO 0					
SN:052623401379	HRS	6622.3		TSO 0					
	ENC	5602		TSO 0					
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01									
731005-8	NO. 1 ENGINE - NO. 8 FUEL MANIFOLD NOZZLE ASSEMBLY							Component	ATA:73
PN:3060540-2	MOS/MSC	25-Oct-06	O/C						
SN:022923401439	HRS	4857.2							
	ENC	3730							
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01									
731005-8	NO. 2 ENGINE - NO. 8 FUEL MANIFOLD NOZZLE ASSEMBLY							Component	ATA:73
PN:3060540-2	MOS/MSC	20-Jul-15	O/C	TSO 0					
SN:052923401376	HRS	6622.3		TSO 0					
	ENC	5602		TSO 0					
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01									
731005-9	NO. 1 ENGINE - NO. 9 FUEL MANIFOLD NOZZLE ASSEMBLY							Component	ATA:73
PN:3060540-2	MOS/MSC	25-Oct-06	O/C						
SN:97-01371-562	HRS	4857.2							
	ENC	3730							
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01									
731005-9	NO. 2 ENGINE - NO. 9 FUEL MANIFOLD NOZZLE ASSEMBLY							Component	ATA:73
PN:3060540-2	MOS/MSC	20-Jul-15	O/C	TSO 0					
SN:000137102869	HRS	6622.3		TSO 0					
	ENC	5602		TSO 0					
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 73 - ENGINE FUEL AND CONTROL									
731015	NO. 1 ENGINE - FUEL PUMP PRESSURE DIFFERENTIAL INDICATOR							Component	ATA:73
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 73-20-01, LMM 73-20-01PROC. REF: LMM 73-20-01, LMM 73-20-01									
731015	NO. 2 ENGINE - FUEL PUMP PRESSURE DIFFERENTIAL INDICATOR							Component	ATA:73
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 73-20-01, LMM 73-20-01PROC. REF: LMM 73-20-01, LMM 73-20-01									
731110	NO. 1 ENGINE - PRESSURE LIMITER (PCD) VALVE							Component	ATA:73
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 73-20-01, LMM 73-20-01PROC. REF: LMM 73-20-01, LMM 73-20-01									
731110	NO. 2 ENGINE - PRESSURE LIMITER (PCD) VALVE							Component	ATA:73
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 73-20-01, LMM 73-20-01PROC. REF: LMM 73-20-01, LMM 73-20-01									
731120	NO. 1 ENGINE - FUEL FLOW DIVIDER/DRAIN VALVE							Component	ATA:73
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
731120	NO. 2 ENGINE - FUEL FLOW DIVIDER/DRAIN VALVE							Component	ATA:73
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information

S-Suppressed Requirement

*-Estimated Due(New Requirement)

(EFF)-Effective C/W

(M)-Manual Due

U-User Task

Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 73 - ENGINE FUEL AND CONTROL									
732102	NO. 1 ENGINE - RELIEF VALVE							Component	ATA:73
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
732102	NO. 2 ENGINE - RELIEF VALVE							Component	ATA:73
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
732120 ^S	NO. 1 ENGINE - INSPECT MOTIVE FLOW FUEL PUMP DRIVE SPLINE							Service	ATA:73
	MOS	27-Oct-25							
	HRS	9832.1	600						
	ENC	7480							
PROC. REF: LMM 72-00-00, LMM 73-21-04PROC. REF: LMM 72-00-00, LMM 73-21-04									
732120 ^S	NO. 2 ENGINE - INSPECT MOTIVE FLOW FUEL PUMP DRIVE SPLINE							Service	ATA:73
	MOS	27-Oct-25							
	HRS	8993.4	600						
	ENC	7376							
PROC. REF: LMM 72-00-00, LMM 73-21-04PROC. REF: LMM 72-00-00, LMM 73-21-04									
733001	NO. 1 ENGINE FUEL FLOW TRANSDUCER							Component	ATA:73
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 73-31-01PROC. REF: AMM 73-31-01									
733002	NO. 2 ENGINE FUEL FLOW TRANSDUCER							Component	ATA:73
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 73-31-01PROC. REF: AMM 73-31-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 73 - ENGINE FUEL AND CONTROL									
733013	DUAL FUEL FLOW CONVERTER (DFFC)							Component	ATA:73
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 73-31-02PROC. REF: AMM 73-31-02									
733031	LEFT ENGINE FUEL TEMPERATURE BULB							Component	ATA:73
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 73-31-03PROC. REF: AMM 73-31-03									
733032	RIGHT ENGINE FUEL TEMPERATURE BULB							Component	ATA:73
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 73-31-03PROC. REF: AMM 73-31-03									
ATA 74 - IGNITION									
740110	NO. 1 ENGINE - IGNITION UNIT							Component	ATA:74
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 74-00-01, LMM 74-00-01PROC. REF: LMM 74-00-01, LMM 74-00-01									
740110	NO. 2 ENGINE - IGNITION UNIT							Component	ATA:74
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 74-00-01, LMM 74-00-01PROC. REF: LMM 74-00-01, LMM 74-00-01									
740130	NO. 1 ENGINE - 5 O'CLOCK IGNITER (#1 POSITION) PLUG							Component	ATA:74
PN:3074541-4	MOS/MSC	28-Nov-17	O/C	TSN 0					
SN:UNKNOWN	HRS	7696.2		TSN 0					
	ENC	5895		TSN 0					
PROC. REF: LMM 74-00-01, LMM 74-00-01PROC. REF: LMM 74-00-01, LMM 74-00-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 74 - IGNITION									
740130	NO. 2 ENGINE - 5 O'CLOCK IGNITER (#1 POSITION) PLUG							Component	ATA:74
PN:3074541-4	MOS/MSC	18-Aug-22	O/C	TSN 0					
SN:UNKNOWN	HRS	8169.8		TSN 0					
	ENC	6832		TSN 0					
PROC. REF: LMM 74-00-01, LMM 74-00-01PROC. REF: LMM 74-00-01, LMM 74-00-01									
740140 ^S	NO. 1 ENGINE - REMOVE AND INSPECT 5 O'CLOCK IGNITER PLUG AND LEAD							Service	ATA:74
	MOS	22-Jun-23							
	HRS	9184.4	1600						
	ENC	7042							
PKG:0									
740140 ^S	NO. 2 ENGINE - REMOVE AND INSPECT 5 O'CLOCK IGNITER PLUG AND LEAD							Service	ATA:74
	MOS	18-Aug-22							
	HRS	8169.8	1600						
	ENC	6832							
PKG:0									
740150	NO. 1 ENGINE - 7 O'CLOCK IGNITER (#2 POSITION) PLUG							Component	ATA:74
PN:3074541-4	MOS/MSC	28-Nov-17	O/C	TSN 0					
SN:UNKNOWN	HRS	7696.2		TSN 0					
	ENC	5895		TSN 0					
PROC. REF: LMM 74-00-01, LMM 74-00-01PROC. REF: LMM 74-00-01, LMM 74-00-01									
740150	NO. 2 ENGINE - 7 O'CLOCK IGNITER (#2 POSITION) PLUG							Component	ATA:74
PN:3074541-4	MOS/MSC	18-Aug-22	O/C	TSN 0					
SN:UNKNOWN	HRS	8169.8		TSN 0					
	ENC	6832		TSN 0					
PROC. REF: LMM 74-00-01, LMM 74-00-01PROC. REF: LMM 74-00-01, LMM 74-00-01									
740160 ^S	NO. 1 ENGINE - REMOVE AND INSPECT 7 O'CLOCK IGNITER PLUG AND LEAD							Service	ATA:74
	MOS	22-Jun-23							
	HRS	9184.4	1600						
	ENC	7042							
PKG:0									
PROC. REF: LMM 74-00-01PROC. REF: LMM 74-00-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 74 - IGNITION									
740160 ^S		NO. 2 ENGINE - REMOVE AND INSPECT 7 O'CLOCK IGNITER PLUG AND LEAD						Service	ATA:74
	MOS	18-Aug-22							
	HRS	8169.8	1600						
	ENC	6832							
PROC. REF: LMM 74-00-01PROC. REF: LMM 74-00-01									
742011		NO. 1 ENGINE - NO. 1 IGNITION (IPC 20 REFERENCE) LEAD						Component	ATA:74
PN:3060722-11	MOS/MSC	22-Jun-23	O/C	TSN 0					
SN:S23100003	HRS	9184.4		TSN 0					
	ENC	7042		TSN 0					
PROC. REF: LMM 74-00-01, LMM 74-00-01PROC. REF: LMM 74-00-01, LMM 74-00-01									
742011		NO. 2 ENGINE - NO. 1 IGNITION (IPC 20 REFERENCE) LEAD						Component	ATA:74
PN:9043913	MOS/MSC	20-Jul-15	O/C	TSN 0					
SN:UNKNOWN	HRS	6622.3		TSN 0					
	ENC	5602		TSN 0					
PROC. REF: LMM 74-00-01, LMM 74-00-01PROC. REF: LMM 74-00-01, LMM 74-00-01									
742012		NO. 1 ENGINE - NO. 2 IGNITION (IPC 25 REFERENCE) LEAD						Component	ATA:74
PN:3060722-12	MOS/MSC	22-Jun-23	O/C	TSN 0					
SN:S22500007	HRS	9184.4		TSN 0					
	ENC	7042		TSN 0					
PROC. REF: LMM 74-00-01, LMM 74-00-01PROC. REF: LMM 74-00-01, LMM 74-00-01									
742012		NO. 2 ENGINE - NO. 2 IGNITION (IPC 25 REFERENCE) LEAD						Component	ATA:74
PN:9043913	MOS/MSC	20-Jul-15	O/C	TSN 0					
SN:UNKNOWN	HRS	6622.3		TSN 0					
	ENC	5602		TSN 0					
PROC. REF: LMM 74-00-01, LMM 74-00-01PROC. REF: LMM 74-00-01, LMM 74-00-01									
743001		TAIL CONE RELAY (P13) PANEL						Component	ATA:74
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 74-30-01PROC. REF: AMM 74-30-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 74 - IGNITION									
743001-1	EMERGENCY LIGHTING (P-51) RELAY							Component	ATA:74
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
743005-1	K22 RELAY							Component	ATA:74
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
743005-2	K61 RELAY							Component	ATA:74
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
ATA 75 - AIR									
754210	NO. 1 ENGINE - INLET PRESSURE AND TEMPERATURE SENSOR							Component	ATA:75
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 75-40-01, LMM 75-40-01, LMM 75-40-01, LMM 75-40-01PROC. REF: LMM 75-40-01, LMM 75-40-01, LMM 75-40-01, LMM 75-40-01									
754210	NO. 2 ENGINE - INLET PRESSURE AND TEMPERATURE SENSOR							Component	ATA:75
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 75-40-01, LMM 75-40-01, LMM 75-40-01, LMM 75-40-01PROC. REF: LMM 75-40-01, LMM 75-40-01, LMM 75-40-01, LMM 75-40-01									
ATA 76 - ENGINE CONTROLS									
761013	THROTTLE CONTROL MODULE							Component	ATA:76
PN:69011-17	MOS/MSC	16-Jul-20	O/C						
SN:640	HRS	8284.1							
	AFL	6376							
PROC. REF: AMM 76-10-02PROC. REF: AMM 76-10-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 76 - ENGINE CONTROLS									
761201	AFT LEFT THROTTLE CABLE							Component	ATA:76
PN:71825-6	MOS/MSC	12-Oct-12	O/C						
SN:UNKNOWN	HRS	6996.3							
	AFL	5340							
PROC. REF: AMM 76-10-01PROC. REF: AMM 76-10-01									
761202	AFT RIGHT THROTTLE CABLE							Component	ATA:76
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 76-10-01PROC. REF: AMM 76-10-01									
761203	LEFT FORWARD THROTTLE CABLE							Component	ATA:76
PN:71845-10	MOS/MSC	12-Oct-12	O/C						
SN:UNKNOWN	HRS	6996.3							
	AFL	5340							
PROC. REF: AMM 76-10-01PROC. REF: AMM 76-10-01									
761204	RIGHT FORWARD THROTTLE CABLE							Component	ATA:76
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 76-10-01PROC. REF: AMM 76-10-01									
761310	NO. 1 ENGINE - SURGE BLEED VALVE							Component	ATA:76
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 76-10-01, LMM 76-10-01, LMM 76-10-01, LMM 76-10-01PROC. REF: LMM 76-10-01, LMM 76-10-01, LMM 76-10-01, LMM 76-10-01									
761310	NO. 2 ENGINE - SURGE BLEED VALVE							Component	ATA:76
PN:978812-6-1	MOS/MSC	20-Jul-15	O/C	TSO 0					
SN:10962	HRS	6622.3		TSO 0					
	ENC	5602		TSO 0					
PROC. REF: LMM 76-10-01, LMM 76-10-01, LMM 76-10-01, LMM 76-10-01PROC. REF: LMM 76-10-01, LMM 76-10-01, LMM 76-10-01, LMM 76-10-01									

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C / W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 76 - ENGINE CONTROLS									
761320	NO. 1 ENGINE - SOLENOID CONTROLLER VALVE							Component	ATA:76
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 76-10-01, LMM 76-10-01, LMM 76-10-01, LMM 76-10-01PROC. REF: LMM 76-10-01, LMM 76-10-01, LMM 76-10-01, LMM 76-10-01									
761320	NO. 2 ENGINE - SOLENOID CONTROLLER VALVE							Component	ATA:76
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 76-10-01, LMM 76-10-01, LMM 76-10-01, LMM 76-10-01PROC. REF: LMM 76-10-01, LMM 76-10-01, LMM 76-10-01, LMM 76-10-01									
761330	NO. 1 ENGINE - ENGINE (DEEC) COMPUTER							Component	ATA:76
PN:2118882-1008	MOS/MSC	25-Oct-06	O/C						
SN:15-AW0059	HRS	4857.2							
	ENC	3730							
PROC. REF: LMM 76-10-02, LMM 76-10-02, LMM 76-10-02, LMM 76-10-02PROC. REF: LMM 76-10-02, LMM 76-10-02, LMM 76-10-02, LMM 76-10-02									
761330	NO. 2 ENGINE - ENGINE (DEEC) COMPUTER							Component	ATA:76
PN:2118882-1008	MOS/MSC	27-Jun-06	O/C						
SN:124-AW0057	HRS	4614							
	ENC	3532							
PROC. REF: LMM 76-10-02, LMM 76-10-02, LMM 76-10-02, LMM 76-10-02PROC. REF: LMM 76-10-02, LMM 76-10-02, LMM 76-10-02, LMM 76-10-02									
761330A	NO. 1 ENGINE - DOWNLOAD ENGINE (DEEC) COMPUTER ECTM							Service	ATA:76
PN:2118882-1008	MOS	24-Aug-26						CUSTOMER CODE	
SN:15-AW0059	HRS	10045.7							
	ENC	7644	40	Adj -1	(7683) 7697		23		
PROC. REF: MSC CAMP EHM ADENDUMPROC. REF: MSC CAMP EHM ADENDUM									
761330A	NO. 2 ENGINE - DOWNLOAD ENGINE (DEEC) COMPUTER ECTM							Service	ATA:76
PN:2118882-1008	MOS	24-Aug-26						CUSTOMER CODE	
SN:124-AW0057	HRS	9207							
	ENC	7540	40		(7580) 7698		24		
PROC. REF: MSC CAMP EHM ADENDUMPROC. REF: MSC CAMP EHM ADENDUM									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-------	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 76 - ENGINE CONTROLS

Y7600000	^S	ENGINE DEEC WIRE HARNESS SHIELD OVERBRAIDS AND SHIELD TERMINATIONS - PERFORM VISUAL INSPECTION						Service	ATA:76
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:15

Y7600001	^S	THRUST LEVER CONTROL MODULE - PERFORM FUNCTIONAL TEST						Service	ATA:76
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 76-10-02PROC. REF: AMM 76-10-02									PKG:13

Y7610007	^S	ENGINE CONTROL CABLES - PERFORM VISUAL INSPECTION OF FORWARD AND AFT CABLE CONNECTIONS						Service	ATA:76
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:14

ATA 77 - ENGINE INDICATING

770101	NO. 1 ENGINE - N1 MONOPOLE							Component	ATA:77
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 77-10-02PROC. REF: LMM 77-10-02									

770101	NO. 2 ENGINE - N1 MONOPOLE							Component	ATA:77
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 77-10-02PROC. REF: LMM 77-10-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 77 - ENGINE INDICATING									
771210	NO. 1 ENGINE - N1 COMPENSATOR								Component ATA:77
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 77-10-03, LMM 77-10-03, LMM 77-10-03, LMM 77-10-03PROC. REF: LMM 77-10-03, LMM 77-10-03, LMM 77-10-03, LMM 77-10-03									
771210	NO. 2 ENGINE - N1 COMPENSATOR								Component ATA:77
PN:3060735-7	MOS/MSC	05-Jun-06	O/C	TSN 0					
SN:011309700526	HRS	3701.2		TSN 0					
	ENC	3369		TSN 0					
PROC. REF: LMM 77-10-03, LMM 77-10-03, LMM 77-10-03, LMM 77-10-03PROC. REF: LMM 77-10-03, LMM 77-10-03, LMM 77-10-03, LMM 77-10-03									
771220	NO. 1 ENGINE - N2 MONOPOLE								Component ATA:77
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 77-10-05, LMM 77-10-05, LMM 77-10-05, LMM 77-10-05PROC. REF: LMM 77-10-05, LMM 77-10-05, LMM 77-10-05, LMM 77-10-05									
771220	NO. 2 ENGINE - N2 MONOPOLE								Component ATA:77
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 77-10-05, LMM 77-10-05, LMM 77-10-05, LMM 77-10-05PROC. REF: LMM 77-10-05, LMM 77-10-05, LMM 77-10-05, LMM 77-10-05									
772210	NO. 1 ENGINE - ITT HARNESS ASSEMBLY								Component ATA:77
PN:3060730-1	MOS/MSC	28-Nov-17	O/C	TSN 0					
SN:1716901702429	HRS	7696.2		TSN 0					
	ENC	5895		TSN 0					
PROC. REF: LMM 77-20-01, LMM 77-20-01, LMM 77-20-01, LMM 77-20-01PROC. REF: LMM 77-20-01, LMM 77-20-01, LMM 77-20-01, LMM 77-20-01									
772210	NO. 2 ENGINE - ITT HARNESS ASSEMBLY								Component ATA:77
PN:3060763-1	MOS/MSC	20-Jul-15	O/C	TSN 0					
SN:1516901702268	HRS	6622.3		TSN 0					
	ENC	5602		TSN 0					
PROC. REF: LMM 77-20-01, LMM 77-20-01, LMM 77-20-01, LMM 77-20-01PROC. REF: LMM 77-20-01, LMM 77-20-01, LMM 77-20-01, LMM 77-20-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
---------	------	-------	----------	------------	----------------------------	-----------	-----------	-------------	----------

ATA 77 - ENGINE INDICATING

774001	ENGINE VIBRATION MONITOR BOX							Component	ATA:77
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 77-41-01PROC. REF: AMM 77-41-01									

774010	P36 RELAY BOX							Component	ATA:77
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 77-41-03PROC. REF: AMM 77-41-03									

774011	LEFT ENGINE VIBRATION ACCELEROMETER							Component	ATA:77
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 77-41-02PROC. REF: AMM 77-41-02									

774012	RIGHT ENGINE VIBRATION ACCELEROMETER							Component	ATA:77
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 77-41-02PROC. REF: AMM 77-41-02									

Y7741000 ^S	ENGINE VIBRATION MONITORING SYSTEM - PERFORM FUNCTIONAL TEST							Service	ATA:77
	MOS	25-Jun-26	96						
	HRS	10023.1	2400						
	AFL	7616							
PROC. REF: AMM 77-41-00PROC. REF: AMM 77-41-00									
									PKG:21

ATA 78 - EXHAUST

783001	LEFT LOWER THRUST REVERSER							Component	ATA:78
PN:LJ7830101-5	MOS/MSC	26-Jul-23	O/C						
SN:00046	HRS	9278							
	AFL	7111							
Special Properties: RII ITEM									

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C / W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
---------	------	-------	----------	------------	----------------------------	-----------	-----------	-------------	----------

ATA 78 - EXHAUST

PROC. REF: AMM 78-31-00PROC. REF: AMM 78-31-00

783002	RIGHT LOWER THRUST REVERSER							Component	ATA:78
PN:LJ7830101-6	MOS/MSC	26-Jul-23	O/C						
SN:00052	HRS	9278							
	AFL	7111							
Special Properties: RII ITEM									
PROC. REF: AMM 78-31-00PROC. REF: AMM 78-31-00									

783025	TRANSFORMER/RECTIFIER ELECTRONIC CONTROL UNIT							Component	ATA:78
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

783037	NO. 1 GPM HYDRAULIC CONTROL VALVE							Component	ATA:78
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 78-32-10PROC. REF: AMM 78-32-10									

783038	NO. 2 GPM HYDRAULIC CONTROL VALVE							Component	ATA:78
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 78-32-10PROC. REF: AMM 78-32-10									

783051	LEFT OUTBOARD THRUST REVERSER ACTUATOR							Component	ATA:78
PN:LJ7833100-3	MOS/MSC	26-Jan-14	O/C	TSO 0					
SN:A30040652	HRS	7249.8		TSO 0					
	AFL	5528		TSO 0					
PROC. REF: AMM 78-32-20PROC. REF: AMM 78-32-20									

783052	LEFT INBOARD THRUST REVERSER ACTUATOR							Component	ATA:78
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 78 - EXHAUST									
PROC. REF: AMM 78-32-20PROC. REF: AMM 78-32-20									
783053	RIGHT INBOARD THRUST REVERSER ACTUATOR								Component ATA:78
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 78-32-20PROC. REF: AMM 78-32-20									
783054	RIGHT OUTBOARD THRUST REVERSER ACTUATOR								Component ATA:78
PN:LJ7833100-4	MOS/MSC	12-Dec-11	O/C	TSO 0					
SN:A30040459	HRS	6763.5		TSO 0					
	AFL	5158		TSO 0					
PROC. REF: AMM 78-32-20PROC. REF: AMM 78-32-20									
783061	NO. 1 CONTROL, THRUST REVERSER HYDRAULIC VALVE								Component ATA:78
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 78-32-10PROC. REF: AMM 78-32-10									
783062	NO. 2 CONTROL, THRUST REVERSER HYDRAULIC VALVE								Component ATA:78
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 78-32-10PROC. REF: AMM 78-32-10									
783101	LEFT THRUST REVERSER HYDRAULIC ISOLATION VALVE								Component ATA:78
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 78-30-02PROC. REF: AMM 78-30-02									
783102	RIGHT THRUST REVERSER HYDRAULIC ISOLATION VALVE								Component ATA:78
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 78-30-02PROC. REF: AMM 78-30-02									

? - Insufficient Information
S - Suppressed Requirement
* - Estimated Due(New Requirement)
(EFF) - Effective C / W
(M) - Manual Due
U - User Task
Ex - Excluded Task

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 78 - EXHAUST									
783150	LEFT HAND INBOARD LATCHBOX ACTUATOR							Component	ATA:78
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 78-32-30PROC. REF: AMM 78-32-30									
783151	RIGHT HAND INBOARD LATCHBOX ACTUATOR							Component	ATA:78
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 78-32-30PROC. REF: AMM 78-32-30									
783210	LEFT THRUST REVERSER CONTROL VALVE							Component	ATA:78
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
783211	RIGHT THRUST REVERSER CONTROL VALVE							Component	ATA:78
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
783220	NO. 1 ENGINE THROTTLE RETARD ACTUATOR							Component	ATA:78
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 78-32-40PROC. REF: AMM 78-32-40									
783221	NO. 2 ENGINE THROTTLE RETARD ACTUATOR							Component	ATA:78
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 78-32-40PROC. REF: AMM 78-32-40									

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C / W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 78 - EXHAUST									
783301	LEFT THRUST REVERSER CONTROL BOX							Component	ATA:78
PN:LJ7836704-17	MOS/MSC	25-Jun-26	O/C						
SN:OBTE30526	HRS	10023.1							
	AFL	7616							
PROC. REF: AMM 78-33-10PROC. REF: AMM 78-33-10									
783302	RIGHT THRUST REVERSER CONTROL BOX							Component	ATA:78
PN:LJ7836706-3	MOS/MSC	18-Jun-07	O/C						
SN:00059	HRS	5562.1							
	AFL	4242							
PROC. REF: AMM 78-33-10PROC. REF: AMM 78-33-10									
783320	LEFT OUTBOARD THRUST REVERSER WIRE HARNESS							Component	ATA:78
PN:PN	MOS/MSC	09-Mar-01	C/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 78-33-20PROC. REF: AMM 78-33-20									
783321	LEFT INBOARD THRUST REVERSER WIRE HARNESS							Component	ATA:78
PN:PN	MOS/MSC	09-Mar-01	C/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 78-33-20PROC. REF: AMM 78-33-20									
783322	RIGHT INBOARD THRUST REVERSER WIRE HARNESS							Component	ATA:78
PN:PN	MOS/MSC	09-Mar-01	C/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 78-33-20PROC. REF: AMM 78-33-20									
783323	RIGHT OUTBOARD THRUST REVERSER WIRE HARNESS							Component	ATA:78
PN:PN	MOS/MSC	09-Mar-01	C/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 78-33-20PROC. REF: AMM 78-33-20									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 78 - EXHAUST									
D7830078	^S	** THRUST REVERSER SYSTEM THROTTLE RETARD ACTUATOR - PERFORM OPERATIONAL CHECK						Service	ATA:78
	MOS	25-Jun-26	96					AIRWORTHINESS	
	HRS	10023.1	2400						
	AFL	7616							
PROC. REF: AMM 78-32-40PROC. REF: AMM 78-32-40									PKG:21
H7830081	^S	THRUST REVERSERS - REMOVE LINK ROD ASSEMBLIES AND PERFORM MAGNETIC PARTICLE INSPECTION						Service	ATA:78
	MOS	25-Jun-26	96						
	HRS	10023.1	2400						
	AFL	7616							
PROC. REF: NDT PART 7/78-30-01PROC. REF: NDT PART 7/78-30-01									PKG:21
H7830082	^S	THRUST REVERSERS - REMOVE THRUST REVERSER DOOR ASSEMBLIES AND PERFORM EDDY CURRENT INSPECTION OF PIVOT FITTING AND DOOR HINGES						Service	ATA:78
	MOS	25-Jun-26	96						
	HRS	10023.1	2400						
	AFL	7616							
PROC. REF: NDT PART 6/78-30-02, NDT PART 6/78-30-03PROC. REF: NDT PART 6/78-30-02, NDT PART 6/78-30-03									PKG:21
R7830007		THRUST REVERSER - PERFORM CONDUCTIVITY CHECK OF RIGHT THRUST REVERSER DOOR SKIN AND COWL ADJACENT TO APU EXHAUST						Service	ATA:78
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
PROC. REF: NDT PART 6/78-30-01PROC. REF: NDT PART 6/78-30-01									
Y7830000	^S	EXHAUST NOZZLE - PERFORM VISUAL INSPECTION						Service	ATA:78
	MOS	25-Jun-26	96						
	HRS	10023.1	2400						
	AFL	7616							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:21

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 78 - EXHAUST									
Y7830001	^S	THRUST REVERSER INNER FAN DUCT ASSEMBLY - PERFORM VISUAL INSPECTION. INSPECT FROM EXHAUST END ONLY.						Service	ATA:78
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:15
Y7830002	^S	THRUST REVERSER DOOR AND HINGE FITTINGS - PERFORM VISUAL INSPECTION						Service	ATA:78
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:15
Y7830003	^S	THRUST REVERSER PRIMARY ACTUATOR AND LATCH ASSEMBLY - PERFORM VISUAL INSPECTION						Service	ATA:78
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:15
Y7830004	^S	THRUST REVERSER HYDRAULIC CONTROL VALVE (HCV), THROTTLE RETARD ACTUATOR, AND ASSOCIATED PLUMBING - PERFORM VISUAL INSPECTION						Service	ATA:78
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:15
Y7830005	^S	THRUST REVERSER DOOR SEALS AND RETAINERS - PERFORM VISUAL INSPECTION						Service	ATA:78
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:15

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 78 - EXHAUST									
Y7830006 ^S		THRUST REVERSER WIRE HARNESS - PERFORM VISUAL INSPECTION						Service	ATA:78
	MOS	09-Mar-01	48						
	HRS	0	1200						
	AFL	0							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:15
ATA 79 - OIL									
790110		NO. 1 ENGINE - OIL PUMP						Component	ATA:79
PN:3060785-2	MOS/MSC	25-Oct-06	O/C	TSN 0					
SN:061405700614	HRS	4857.2		TSN 0					
	ENC	3730		TSN 0					
PROC. REF: LMM 79-20-03, LMM 79-20-03PROC. REF: LMM 79-20-03, LMM 79-20-03									
790110		NO. 2 ENGINE - OIL PUMP						Component	ATA:79
PN:3060785-2	MOS/MSC	05-Jun-06	O/C	TSN 0					
SN:061405700076	HRS	3701.2		TSN 0					
	ENC	3369		TSN 0					
PROC. REF: LMM 79-20-03, LMM 79-20-03PROC. REF: LMM 79-20-03, LMM 79-20-03									
790130 ^S		NO. 1 ENGINE - ANALYSIS OIL AND FILTER (SOAP)						Service	ATA:79
	MOS	25-Jun-26							
	HRS	9994.8	150						
	ENC	7602							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									PKG:0
790130 ^S		NO. 2 ENGINE - ANALYSIS OIL AND FILTER (SOAP)						Service	ATA:79
	MOS	25-Jun-26							
	HRS	9156.1	150						
	ENC	7498							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									PKG:0

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 79 - OIL									
790140 ^S	NO. 1 ENGINE - PERFORM OIL CHANGE								Service ATA:79
	MOS	27-Oct-25							
	HRS	9832.1	1200						
	ENC	7480							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									
790140 ^S	NO. 2 ENGINE - PERFORM OIL CHANGE								Service ATA:79
	MOS	27-Oct-25							
	HRS	8993.4	1200						
	ENC	7376							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									
790150 ^S	NO. 1 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION AND PERFORM RESISTANCE CHECK								Service ATA:79
	MOS	27-Oct-25							
	HRS	9832.1	600						
	ENC	7480							
PROC. REF: LMM 79-10-01PROC. REF: LMM 79-10-01									
790150 ^S	NO. 2 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION AND PERFORM RESISTANCE CHECK								Service ATA:79
	MOS	27-Oct-25							
	HRS	8993.4	600						
	ENC	7376							
PROC. REF: LMM 79-10-01PROC. REF: LMM 79-10-01									
790160 ^S	NO. 1 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION								Service ATA:79
	MOS	25-Jun-26							
	HRS	9994.8	150						
	ENC	7602							
PROC. REF: LMM 79-10-01PROC. REF: LMM 79-10-01									

? - Insufficient Information
S - Suppressed Requirement
* - Estimated Due(New Requirement)
(EFF) - Effective C / W
(M) - Manual Due
U - User Task
Ex - Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 79 - OIL									
790160 ^S	NO. 2 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION								Service ATA:79
	MOS	25-Jun-26							
	HRS	9156.1	150						
	ENC	7498							
PROC. REF: LMM 79-10-01PROC. REF: LMM 79-10-01									
791001	NO. 1 ENGINE - ENGINE OIL CHIP DETECTOR								Component ATA:79
PN:277-5501-9002	MOS/MSC	18-May-13	O/C						
SN:N/A	HRS	7075.3							
	ENC	5383							
PROC. REF: LMM 79-10-01, LMM 79-10-01PROC. REF: LMM 79-10-01, LMM 79-10-01									
791001	NO. 2 ENGINE - ENGINE OIL CHIP DETECTOR								Component ATA:79
PN:277-5501-9004	MOS/MSC	18-May-13	O/C						
SN:N/A	HRS	6239							
	ENC	5281							
PROC. REF: LMM 79-10-01, LMM 79-10-01PROC. REF: LMM 79-10-01, LMM 79-10-01									
792008	NO. 1 ENGINE - OIL FLOW REDUCTION VALVE								Component ATA:79
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 79-20-08, LMM 79-20-08PROC. REF: LMM 79-20-08, LMM 79-20-08									
792008	NO. 2 ENGINE - OIL FLOW REDUCTION VALVE								Component ATA:79
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 79-20-08, LMM 79-20-08PROC. REF: LMM 79-20-08, LMM 79-20-08									
792011	NO. 1 ENGINE - FUEL/OIL VALVE								Component ATA:79
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 79 - OIL									
792011	NO. 2 ENGINE - FUEL/OIL VALVE								Component ATA:79
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
792012	NO. 1 ENGINE - OIL TEMPERATURE REGULATOR								Component ATA:79
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 79-20-03, LMM 79-20-03PROC. REF: LMM 79-20-03, LMM 79-20-03									
792012	NO. 2 ENGINE - OIL TEMPERATURE REGULATOR								Component ATA:79
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 79-20-03, LMM 79-20-03PROC. REF: LMM 79-20-03, LMM 79-20-03									
792037	NO. 1 OIL PRESSURE SWITCH								Component ATA:79
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 79-30-02PROC. REF: AMM 79-30-02									
792038	NO. 2 OIL PRESSURE SWITCH								Component ATA:79
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 79-30-02PROC. REF: AMM 79-30-02									
792220	NO. 1 ENGINE - UPPER OIL COOLER ASSEMBLY								Component ATA:79
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 79 - OIL									
792220	NO. 2 ENGINE - UPPER OIL COOLER ASSEMBLY							Component	ATA:79
PN:160554-5	MOS/MSC	05-Jun-06	O/C						
SN:76-247	HRS	3701.2							
	ENC	3369							
792230	NO. 1 ENGINE - LOWER LEFT OIL COOLER ASSEMBLY							Component	ATA:79
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
792230	NO. 2 ENGINE - LOWER LEFT OIL COOLER ASSEMBLY							Component	ATA:79
PN:160552-3	MOS/MSC	05-Jun-06	O/C						
SN:47-274	HRS	3701.2							
	ENC	3369							
792240	NO. 1 ENGINE - LOWER RIGHT OIL COOLER ASSEMBLY							Component	ATA:79
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
792240	NO. 2 ENGINE - LOWER RIGHT OIL COOLER ASSEMBLY							Component	ATA:79
PN:160554-6	MOS/MSC	05-Jun-06	O/C						
SN:1068	HRS	3701.2							
	ENC	3369							
792250	NO. 1 ENGINE - PRESSURE BREATHER VALVE							Component	ATA:79
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 79-20-02, LMM 79-20-02PROC. REF: LMM 79-20-02, LMM 79-20-02									

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 79 - OIL									
792250	NO. 2 ENGINE - PRESSURE BREATHER VALVE							Component	ATA:79
PN:3075323-3	MOS/MSC	16-Feb-11	O/C						
SN:000814506520	HRS	5602							
	ENC	4823							
PROC. REF: LMM 79-20-02, LMM 79-20-02PROC. REF: LMM 79-20-02, LMM 79-20-02									
792260	NO. 1 ENGINE - OIL TEMPERATURE CONTROL VALVE							Component	ATA:79
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
792260	NO. 2 ENGINE - OIL TEMPERATURE CONTROL VALVE							Component	ATA:79
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
793001	NO. 1 ENGINE OIL PRESSURE TRANSDUCER							Component	ATA:79
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 79-30-01PROC. REF: AMM 79-30-01									
793002	NO. 2 ENGINE OIL PRESSURE TRANSDUCER							Component	ATA:79
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 79-30-01PROC. REF: AMM 79-30-01									
793011	LEFT TEMPERATURE OIL BULB							Component	ATA:79
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 79-30-03PROC. REF: AMM 79-30-03									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 10101.4 AFL: 7674 As Of: 14-Sep-2026 15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 79 - OIL									
793012	RIGHT TEMPERATURE OIL BULB							Component	ATA:79
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 79-30-03PROC. REF: AMM 79-30-03									
793013	APU TEMPERATURE OIL BULB							Component	ATA:79
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 79-30-03PROC. REF: AMM 79-30-03									
793064	NO. 1 ENGINE - TEMP BULB							Component	ATA:79
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
793064	NO. 2 ENGINE - TEMP BULB							Component	ATA:79
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
793310	NO. 1 ENGINE - OIL FILTER BYPASS VALVE							Component	ATA:79
PN:3060782-2	MOS/MSC	25-Oct-06	O/C	TSN 0					
SN:060645105349	HRS	4857.2		TSN 0					
	ENC	3730		TSN 0					
793310	NO. 2 ENGINE - OIL FILTER BYPASS VALVE							Component	ATA:79
PN:3060782-2	MOS/MSC	25-Nov-20	O/C	TSO 0					
SN:K15538	HRS	7388.5		TSO 0					
	ENC	6230		TSO 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 10101.4
AFL: 7674
As Of: 14-Sep-2026

15-Sep-2026 01:18 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 79 - OIL									
793315 ^S	NO. 1 ENGINE - CHECK OIL FILTER BYPASS VALVE CIRCUIT/THERMAL LOCKOUT SWITCH							Service	ATA:79
	MOS	27-Oct-25							
	HRS	9832.1	600						
	ENC	7480							
PKG:0									
793315 ^S	NO. 2 ENGINE - CHECK OIL FILTER BYPASS VALVE CIRCUIT/THERMAL LOCKOUT SWITCH							Service	ATA:79
	MOS	27-Oct-25							
	HRS	8993.4	600						
	ENC	7376							
PKG:0									
793320	NO. 1 ENGINE - FUEL HEATER / OIL COOLER ASSEMBLY							Component	ATA:79
PN:160506-4	MOS/MSC	30-Nov-16	O/C	TSO 4					
SN:47-486	HRS	7607.6		TSO 0					
	ENC	5820		TSO 0					
PROC. REF: LMM 79-20-07, LMM 79-20-07PROC. REF: LMM 79-20-07, LMM 79-20-07									
793320	NO. 2 ENGINE - FUEL HEATER / OIL COOLER ASSEMBLY							Component	ATA:79
PN:160506-4	MOS/MSC	21-Aug-25	O/C	TSN 0					
SN:4216	HRS	8897		TSN 0					
	ENC	7309		TSN 0					
PROC. REF: LMM 79-20-07, LMM 79-20-07PROC. REF: LMM 79-20-07, LMM 79-20-07									
ATA 85 - FUEL CELL SYSTEMS									
859000	SUBMIT LOGBOOK ENTRIES FOR ELOGBOOK							Service	ATA:85
	MOS/MSC	09-Mar-01	A/R						
	HRS	0							
	AFL	0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

? - Insufficient Information
S - Suppressed Requirement
* - Estimated Due(New Requirement)
(EFF) - Effective C / W
(M) - Manual Due
U - User Task
Ex - Excluded Task