



THUNDER WINGS
AIRCRAFT SALES LLC

Ph: 405-570-0891

2005 Lear 40 (w) BR Engines and ER
(extra range) tank mod

S/N: 45-2027, N116PJ



ASKING PRICE..... MAKE OFFER

Will consider all trades

HIGHLIGHTS

- Part 135 Certificate, Nation-wide Customer Base
- Professional Management and Crew can remain in place
- Fantastic revenue stream in place
- Enrolled on Honeywell MSP Gold Program
- Interior/Exterior refreshed in 2018
- No known damage history

AIRFRAME

9271.4 Total Hours
7401 Landings

ENGINES

Honeywell TFE 731-20BR-1B
Left Engine SNP-116596C – 9187.4 Hours/7367 Cycles
Right Engine SNP-11597C – 9187.4 Hours/7367 Cycles

EXTERIOR

Recent Paint Touch-Up 2018
Top Fuselage is Matterhorn White with
Bottom Fuselage in Royal Blue
Accent Stripes are Red and Blue

INTERIOR

Seven Passengers
Executive Standard Configuration (6 cabin seats plus 1 belted lavatory seat)
Executive Club Seats with 4 fold-out tables
Forward Galley
Aft Lavatory (belted)
External Baggage Compartment
2018 Partial Interior Refurb

LEARJET 40XR PERFORMANCE

Max Range (NM):	1,960
Seating:	2/7
Cabin Volume (CuFt):	369
Cruise Speed (Kts):	432
Rate of climb (f/s):	2,820
Balanced field length (feet):	4,680
Payload (Maximum)	2,051
Baggage (CuFt Int/Ext):	15/50
Ceiling (feet):	51,000
Direct Operating Cost (per hour)	\$1,775
Direct Op	\$4.20

AVIONICS

Dual AZ-850 Air Data Computers
Dual AHZ-800 AHRS Computers
Dual IC-600 Auto Pilot Computers
Dual Honeywell RNZ-851 Nav Units
Dual Honeywell RCZ-833 Comm Units
Dual Honeywell 800 Digital Acquisition Units
Four Tube DU-870 EFIS/MFS with 7" X 8" Displays
Engine Instrument/Crew Alerting System (EICAS)
Honeywell Primus WU-660 Color Radar
RT-300 Radio Altimeter
Universal UNS-1C Flight Management System
ELT Artex C406-2 MHz w/ Nav Interface

ADDITIONAL EQUIPMENT

RVSM
Pulselights
Extended Range
Modification Iridium ICS-
100 SATCOM Phone 115
VAC Outlets
Fwd & Aft 10.4" Monitors (LCD)
Airshow 4000
Cabin Entertainment System (10-disc CD Changer, DVD
Player)





