



THUNDER WINGS
AIRCRAFT SALES LLC

Ph: 405-570-0891

2001 Learjet 45
S/N: 45-145, N942FK



ASKING PRICE.....MAKE OFFER

Will consider all trades

HIGHLIGHTS

- Part 135 Certificate, Nation-wide Customer Base
- Professional Management and Crew can remain in place
- Fantastic revenue stream in place
- Enrolled on Honeywell MSP Gold Program
- Interior/Exterior refreshed in 2016
- No known damage history

AIRFRAME

10,023.1 Total Time
7616 Total Landings

ENGINES

Honeywell TFE 731-20BR-1B
Left Engine SN: P-116284C
9994.8 Hours / 7602 Cycles
Right Engine SN: P-116285C
9156.1 Hours / 7498 Cycles

ADDITIONAL FEATURES

- Airshow 400
- Cabin entertainment system
(10 Disc CD changer & DVD Player)
- 115 Volt AC outlets
- Fwd and Aft Monitors (L.C.D.)
- RS Refreshment Center
- 9 Passengers

AVIONICS

Honeywell Primus 1000 Suite Flt Dir/AP
Dual Honeywell IC-600 EFIS
Honeywell DU-870 4-tube AFIS
Honeywell DTU Triple data port transfer Comm
Dual Honeywell RCS-851M w/8.33 kHz Nav
Dual Honeywell RNZ-851 w/FM immun DME
Dual Honeywell AHRS
Dual Honeywell LCR-93 Altimeter
Thommen standby CVR
Honeywell SSCVR (30-minute) Beacon
Dukane 120/90 underwater RMU
Dual Honeywell RMU855 Flt Dir
Honeywell F/Phone
AirCell Access EZ Airborne FMS
Universal UNS-1C Hi Freq
Honeywell KHF 950 EGPWS
Honeywell Mark V EGPWS Rad Alt
Honeywell RT-300 SATCOM
AirCell Axxess ST-4200 TAWS
Honeywell EGPWS w/windshear TCAS
Honeywell TPU-67A TCAS-II Transp
Dual Honeywell w/Mode S diversity Radar
Honeywell Primus 660
Dual Honeywell w/Mode S diversity Radar
Honeywell Primus 660

INTERIOR

- Executive Tan leather Double Club seating (2016)
- Executive Fold-Out Tables
- High Gloss Veneer Woodwork
- Wool accent carpeting
- Tan Sheepskin covered Crew seats
- Dropped aisle accent lighting
- Pleated Fabric window shades
- Tapis off-white Ultraleather headliner

EXTERIOR

- Recent Paint Touch-Up 2016









